

**EA02-025**

**FORD**

**10/27/03**

**BOOK 27 OF 61**

**PART 3 OF 5**

**BOX 23 OF 28**

971007

## Improved Methods for Testing the Durability of Corrosion Protection in Brake Fluids

Fresh Brake Fluids will not simulate corrosion of brake systems, because their corrosion inhibitor additions prevent it. Copper in long-field usage vehicles is the highest ion concentration.

Garry L. Jackson  
Delphi Chassis Systems

Pierre Lévesque  
Union Carbide Corp.

Frederick T. Wagner  
General Motors Research & Development Center

*How does the high copper ion contribute to the corrosion of other metals when under a B+ field? Do experiments need aged fluids?*

### ABSTRACT

Present corrosion testing procedures for brake fluids assess the properties of fresh fluids under some forms of environmental stress (e.g., water content, elevated temperature). These tests may not accurately predict corrosion protection properties of fluid after the years of continuous service typical of North American practice. This paper describes the development of laboratory accelerated aging procedures which reproduce the chemical changes occurring in brake fluids during long-term service. Short-duration vehicular tests with these lab-aged fluids have reproduced specific modes of corrosion previously observed only after long-term customer use.

### INTRODUCTION

Brake fluid reliably transmits full boosted pedal pressure throughout the braking system. Brake fluid also serves to protect against corrosion the brake system materials it contacts. While in Europe the brake fluid in a vehicle is typically changed every few years, in North America brake fluids are not routinely changed. Therefore, it is important to assess the long-term corrosion protection of brake fluid used in cars and trucks sold in North America.

The minimum levels of corrosion protection required for brake fluids are set by laboratory test procedures embodied in FMVSS 116<sup>1</sup>, a regulation based on the primary brake fluid standard for the automotive industry, SAE J1703<sup>2</sup>. The corrosion tests required by these standards are performed on fresh samples of brake fluid and may not be a reliable


indicator of the level of corrosion protection afforded by the fluid after several years in a vehicle. A fluid compounded from high-quality base materials, but containing no corrosion inhibitors whatsoever, can pass the weight change requirements (see Table 1). Corrosion is on occasion still observed within brake systems filled with fluids which were fully compliant with SAE J1703 and FMVSS 116 when fresh. Chemical analysis of used brake fluids suggests reasons why corrosion could occur in these circumstances.

Table 1: J1703 corrosion test (section 4.6) weight changes for an uninhibited brake fluid base.

metal	J1703 max. wt. change ( $\mu\text{g}/\text{cm}^2$ )	measured wt. change ( $\mu\text{g}/\text{cm}^2$ )
Timed iron	±0.2	-0.04
Steel	±0.2	-0.04
Aluminum	±0.1	+0.01
Cast iron	±0.2	+0.00
Braze	±0.4	-0.02
Copper	±0.4	+0.00
Zinc	±0.4	+0.06


*Note: J1703 4.6 requirements on coupon and fluid appearance, sediment, and rubber interaction also passed*

This paper first characterizes, through chemical analysis, the changes which can occur in brake fluids during vehicular use. Then, building upon this database, we develop new aging and testing procedures which can measure the durability of the corrosion protection provided by a fully-formulated fluid. The primary corrosion inhibitors used in most brake fluids are amines, organic bases which both provide general buffering




pH measurements?

### Aged fluids.



Data from 1996 Brake Key Life Test Customer Data Acquisition Study  
TO: Q20001

**Brake Key Life Test - 1995 C.V., G.M. & T.C.**



Data from 29 customers total, in cities of Boston, Atlanta Tampa

3713 7618

capacity against the deleterious effects of acidic breakdown products and provide specific protection of particular metals, presumably through adsorption. Amines both work well as inhibitors and fulfill the extended solubility constraints imposed by the need for the brake fluid to remain a single phase system over wide ranges of temperature and water content. This paper will therefore concentrate upon the amine components of the total inhibitor package.

**SPECIAL STRESSES AND REQUIREMENTS OF ANTILOCK BRAKE SYSTEMS** - Modern antilock brake systems pose new challenges to the proper integration of formulated brake fluids into total brake system design for durable performance. The increased circulation of brake fluid associated with ABS (e.g., through low-pressure return lines to the master cylinder reservoir) may increase the chances of loss of brake fluid components from the fluid, either by direct evaporation, permeation through polymers, or sorption into polymers. The forced circulation can also facilitate the transport of corrosion products and/or thermal degradation products, if they are present, from one point in the brake system to another.

#### CHANGES IN BRAKE FLUID CHEMISTRY DURING VEHICULAR SERVICE

**DROP IN RESERVE ALKALINITY** - The amine inhibitors which provide the primary corrosion protection in most brake fluids are organic bases. A simple approximate measurement of their total concentration (and the stability thereof) in a formulated brake fluid can be obtained by acid-base titrations similar to those called out for engine coolants by ASTM standard D 1121<sup>3</sup>. The Reserve Alkalinity (RA) of a brake fluid is defined as the number of milliliters of 0.100 M hydrochloric acid needed to titrate 50 ml of brake fluid down to a pH of 5.5<sup>4</sup> (in contrast, the D 1121 definition of RA for engine coolant is ml HCl / 10 ml coolant concentrate). In an attempt to keep all brake fluid components in solution during the titration, the brake fluid is prediluted with a solution of 80% denatured alcohol and 20% deionized water (in this work, ~2ml of brake fluid [quantified by weight] was diluted to 60 ml total volume before starting titration with 0.100 M HCl). RA's of fresh brake fluids in recent commercial production range from about 3 to about 120.

Figure 1 shows the residual RA (as % of initial value) of a brake fluid in matched vehicles 0-3.5 years old, plotted as a function of the age of the fluid. By 30 months (about 50,000 km) the RA has dropped to as low as 9% of its initial value, and about half of this small residual RA arises from components other than the amine. The titration data therefore suggest a 20-fold reduction in primary inhibitor concentration over 2-3 years of service.



Figure 1 : Decrease in reserve alkalinity of a brake fluid during vehicular use.

Table 2 shows %RA (vs. fresh values for appropriate OEM brake fluids) for a number of fluid samples taken from randomly-selected vehicles produced by a range of manufacturers. Some loss of RA during vehicular service is universally observed, but the % retained varies widely for different fluids. In the absence of further data, no conclusions about the quality of corrosion protection afforded by a fluid should be drawn from absolute RA values, since it may be possible to formulate effective fluids with a wide range of initial RA's. However, the evolution of the RA over time of use gives a general picture of the stability of the inhibitor package. If the material retains a smaller percentage of its initial RA over time, one can have less confidence that the initial level of corrosion protection implied by J1703 compliance will be confirmed through the service life of the vehicle.

Table 2: Retained reserve alkalinity for a number of OEM fluids after vehicular use.

OEM fluid	Kilometers (approx.)	Months (approx.)	% initial RA retained
I	73430	36	9%
ii	71657	36	21%
iii	47674	ns	33%
iv	117762	36	49%
v	60780	ns	53%

**DROP IN AMINE INHIBITOR CONCENTRATIONS, BUILDUP OF INHIBITOR REACTION PRODUCTS, AND LOSS OF TOTAL NITROGEN** - Decarboxylation of RA, while simple, actually measures only general buffering capacity, not the concentrations of particular inhibitors. To properly characterize the chemical evolution of brake fluids in use and to prevent misinterpretation of RA data, it is necessary to be able to quantify the concentrations of individual inhibitors. The capillary gas chromatographic (GC) techniques employing flame ionization detectors (FID's) commonly used in quality control of the glycol ether and polyglycol components of brake fluid base oils, if carried out with unusually high resolution, quantify the presence of at least some of the common amine inhibitors. However, since the

amines constitute only a small fraction of the total fluid and the chromatographic properties of some important amines are less than optimal for clean separation, full characterization of amines content requires methods which are more selective for nitrogen compounds.

One successful approach has been to use capillary GC with a thermal ionization detector (or nitrogen-phosphorus detector [NPD]) which has a sensitivity for nitrogen atoms in molecules which is over 5000-fold greater than its sensitivity for carbon atoms<sup>14</sup>. This high selectivity for N allows not only ready identification of the chromatographic peaks due to the original amines but also allows one to determine the fate of nitrogen atoms as the original amines react to form new nitrogen-containing compounds during vehicular use. This ability to monitor nitrogen in the fluid even after it has been incorporated into reaction products which may no longer provide buffering capacity has proven particularly useful in tuning laboratory aging procedures to accurately reproduce the effects of extended vehicular use.

Total nitrogen in the brake fluid was also measured with a standard N/S elemental analyzer. Since this technique is sensitive to nitrogen in any relevant form, the drop of total nitrogen as seen by this method allows determination of what fraction of initial nitrogen completely left the fluid. In the primary fluids under study here, the overwhelming preponderance of original nitrogen in the fluid was in the form of the amine inhibitor(s).

Capillary electrophoresis was found to be another successful analytical approach for the amines in most of the inhibitor packages<sup>15</sup>. The technique relies on the fact that ions move with different velocities through a capillary tube filled with buffer solution when an electric field is applied across the length of the tube. Amines in aqueous solutions of brake fluid were separated and detected as their ammonium cations in a pyridinium sulfate buffer at pH 4.4. When they passed through the UV absorbance detector on the Capillary Ion Analysis (CIA) instrument, amine cations were detected as a decrease in absorbance at 254 nm because they displaced some of the pyridinium cations which absorb light at that wavelength<sup>16</sup>. For many fluids, this procedure detects all of the original amines and any reaction products thereof which retain basicity. However, it will not detect other nitrogen-containing reaction products which do not still contribute to the buffering capacity of the used fluid. The limited aqueous solubilities of the ammonium ions derived from the inhibitors in some fluids can lead to irreproducible CIA results. Consequently, the NPD GC and CIA methods were used together to generate corroborative and complementary data.

The mechanisms by which the amines content decreases over time can be inferred by comparison of several metrics of a fluid after vehicular use: the % RA retained, the % retained of total original amine species (by NPD GC), the % of total nitrogen retained (by N/S), and the % buildup of known N-containing reaction products which do not provide buffering capacity (by NPD GC). While the RA and the concentrations of the original amines drop away after approximately 75000 km to <10% of their initial values, more than a third of the original total nitrogen remains in the fluid. Essentially all of this residual N is in a form other than the original amines, and most of the residual N is in a form which does not provide

significant buffering against addition of acid. Of this inactivated but still-present portion of the N, approximately half can be identified as a particular reaction product, the formamide of an inhibitor originally present in the fluid. Cast iron readily rusted when placed in contact with uninhibited brake fluid base to which an appropriate level of this formamide, 5% water, and 50 ppm chloride were added. When the original amines replaced the formamide in control experiments, no rusting was observed at all. The formamide reaction product thus serves neither as a buffer nor as a corrosion inhibitor. However, it does provide a readily-analyzed signature for the severity of thermal oxidation to which a fluid has been subjected while being used in a vehicle.

**INCREASE IN DISSOLVED METALS** - Measurements of dissolved metals in brake fluid (here, done by inductively-coupled plasma atomic emission spectroscopy) provides an indirect indicator of corrosion activity within the brake system. If such measurements are to be a useful guide to the functional durability of the fluid, they must both be interpreted with some care and be accompanied by detailed inspection of brake system components to establish whether the presence of the dissolved metals in the fluid is in fact indicative of a condition which could eventually decrease brake system performance. A low rate of general corrosion over a large surface area of a metal may lead to apparently significant levels of that metal dissolved in the fluid but may pose no threat to system performance. Conversely, a very high rate of localized corrosion of a metal could produce only a small dissolved metal content in the fluid but eventually lead to significant loss of brake system function. A case of correlation between metals spikes in the fluid and component corrosion with a potential for functional significance over an extended service life will be given in later sections of this paper.

Figure 2 shows the pickup of metals by a fluid in vehicular service as a function of fluid age, corresponding to distances traveled of 0-100,000 km. In all vehicles in this figure and for all fluid ages, the metal at highest concentration in solution is copper. This is in part due to the (perhaps surprisingly) large preponderance of the system surface area exposed to the brake fluid which is copper. The interior of typical 2-layer steel brake pipe is completely covered by the copper bearing alloy. A typical light-duty vehicle uses 14 m of such pipe, with an internal diameter of ~2.5 mm, giving an internal geometric surface area of 1200 cm<sup>2</sup>. Atomic force microscopy scans of the interior copper surface of the pipe yield a roughness factor of 1.5, so that the ~900 ml of brake fluid in a vehicle (including that in the master cylinder reservoir) is exposed to 1800 cm<sup>2</sup> of copper. The approximately 300 ppm of Cu seen in the brake fluid after ~36 months corresponds to dissolution of ~0.1 mg/cm<sup>2</sup> copper in 3 years of service, compared with the 0.4 mg/cm<sup>2</sup> copper allowed in a 5 day laboratory test to comply with J1703. The copper corrosion, which appears to be general (rather than localized) in morphology, poses no direct threat to system integrity.

The significance of Figure 2 lies not in the relatively large dissolved copper levels but in the more subtle levels of dissolved iron. No dissolved iron shall be seen until around 30 months, after which 50-100 ppm of dissolved iron becomes typical. Cast iron components removed from some vehicles after such times show some level of pitting of the iron, with pits typically surrounded by metallic copper.

Dissolved iron appears in the brake fluid after the initial anti-corrosion inhibitor are significantly depleted and dissolved copper levels rise to around 200 ppm. The apparent induction period for iron corrosion has presented difficulties in testing technological changes designed to minimize this effect; no test protocol employing fresh brake fluid had succeeded in reproducing the iron corrosion observed at times in vehicles after several years' service. Later sections of this paper will show that attention to the chemical changes in brake fluid during use has led to test procedures which reproduce the field vehicular effects within 6 months.

The dissolved zinc levels in Figure 2 show no evidence of the induction time seen for iron. Since testing for corrosion protection of zinc in brake fluid is known to be problematic even in fresh brake fluids<sup>20</sup> (it is not yet a requirement of FMVSS116), it would not be entirely surprising if some Zn corrosion is occurring even after relatively short service. Another possible source of the observed zinc is extraction of Zn compounds from hoses.

Table 3 shows dissolved metal data for different fluids after extended use in vehicles built by a number of manufacturers. Analytically significant levels of dissolved metals are a common, but not completely universal, characteristic of brake fluids in vehicular service. Between different vehicles, the metals dissolved in brake fluid can be expected to vary with the metals exposed to brake fluid and the service conditions, as well as with the properties of the brake fluids used.

Table 3: Dissolved metals for a number of OEM fluids after use in vehicles.

Fluid	Lot	months (approx)	Cu (ppm)	Fe (ppm)	Zn (ppm)
a	4591	28	30	<10	10
a	57785	28	150	10	0
a	77371	40	220	110	50
b	6154	12	30	<10	10
b	60717	na	300	<10	130
b	na	60	550	30	200
c	47619	na	260	30	140
c	71004	36	15	2	49
c	106612	24	16	3	33




Figure 2: Dissolved metals in a fluid as function of time of use.

## LABORATORY AGING PROCEDURES

Analysis of changes in reserve alkalinity, concentrations of initial amines, concentrations of identifiable nitrogen-containing reaction products, and total nitrogen with vehicular use point to at least two pathways for loss of buffering capacity and amine inhibitor action in brake fluids over time. Under conditions where the buffering capacity is almost completely lost, total nitrogen measurements show retention of 35-45% of the original nitrogen in the fluid (in a formulation for which the vast majority of initial nitrogen is in the amine inhibitors). Thus 1/3-1/2 of the initial nitrogen remains in the fluid but has been converted to non-buffering compounds which are also not good inhibitors. About half of this now-inactive nitrogen can be accounted for by the growth of the formamide derived from an initial amine inhibitor. The chemical path to a formamide is reasonably clear. One end of a glycol ether base fluid molecule can dissociatively oxidize, breaking off one carbon atom to yield formate, a common oxidation product of glycols and glycol ethers. The formate can then react with amine molecules to form inactive formamide molecules. The large concentrations of formamide products which develop during vehicular service thus point to thermal oxidation as one significant cause of the changes of brake fluid chemistry seen in vehicles.

The other significant change in fluid amine chemistry involved not conversion of nitrogen to an inactive form, but loss of nitrogen (in any form) from the brake fluid. The selective loss of various amines from brake systems suggested that volatility, either directly from the fluid surface in the master cylinder reservoir or indirectly via permeation through hoses, could be the second major pathway to the loss of amine inhibitor activity in vehicles. These two pathways to amine loss were incorporated into a laboratory aging procedure designed to mimic vehicular behavior.

**THERMAL OXIDATION** - The thermal oxidation aspect of brake fluid aging was emulated in the laboratory by an 18 hour air-sparged reflux of the fluid at 132° C in the presence of copper powder. To gain maximum acceleration of the aging process, it was desirable to run at the highest temperature which fluid was likely to see anywhere in vehicular brake systems under conditions occurring during normal driving. The chosen 132° C is the highest temperature allowed for fluid during a standard vehicular service test. Copper powder (at >2 cm<sup>2</sup> Cu per ml brake fluid) was incorporated into the procedure because of the similarly high Cu surface / brake fluid volume ratio in real brake systems, the observed dissolution of Cu into fluids during use, and the known behavior of Cu as a catalyst for the oxidation of organic compounds<sup>11</sup>. The duration of the laboratory oxidation treatment was sufficient to approximate the levels of formamide reaction products seen in vehicular brake fluid samples after 3 years' service.

Refluxing of 2 liter quantities of fluid was carried out in a 5000 ml round-bottomed flask with three 24/40 tapered glass joints (two fixed and one adapted), warmed with a heating mantle. A water-cooled 300 ml - long Graham (coil) condenser in series with a 300 mm - long Allihn (bulb)

condenser (the latter on top) proved adequate to keep total weight losses for the fluids below 0.5% during this procedure. Air (free of carbon dioxide and hydrocarbons) was sparged through the fluid at 10 ml/s through a fluorinated ethylene-propylene (FEP) tube drawn out in the hot air of a heat gun to give a ca. 1 mm opening. Temperature was measured by a 0.15 mm thermocouple within the fluid and was controlled with an Omega BSS501 temperature controller switching the power to a variable transformer set at 70 V (for steady-state operation) which in turn supplied power to the heating mantle. The fluid and 80 g of copper powder (Bakelite 1728-61) were continuously stirred with a magnetic stirrer directly below the heating mantle. A 10-20 cm<sup>2</sup> piece of cast iron brake cylinder was used as a stir bar and provided a quick visual check of any corrosive effects generated during the thermal oxidation; a second standard polytetrafluoroethylene-coated stir bar was also put in the flask to improve stirring. The fluid was refluxed in the flow of air for 18 hr at 132° C in this apparatus. Then the fluid was decanted from above the copper powder and transferred to a 4 liter borosilicate glass beaker for the next step of the laboratory aging process.

The white columns of Figure 3 show the % RA retained after SAE compatibility fluid RM-66-04 and a number of commercially available brake fluids were subjected to this thermal oxidation procedure. Results range from >90% retention of buffering capacity to complete destruction of buffering capacity (pH below 5.5 after thermal oxidation [not shown]). While DOT 4 fluids taken as a class were more resistant to loss of amine and buffering capacity by thermal oxidation, some DOT 4 fluids showed some of the lowest levels of thermal stability seen in my fluids.

Significantly smaller RA losses were observed when argon was substituted for air in this procedure or when fluid was simply sealed into brake pipe and heated. Nitrogen analysis of fluids subjected to this air-sparged reflux procedure showed very little loss of total nitrogen. The primary mechanism of loss of buffering capacity tested by this procedure therefore appears to in fact be thermal oxidation.

**VOLATILIZATION** - The simplest process which could explain the observed 55-65% loss of total nitrogen from some brake fluids during vehicular service is volatilization of amines either from the free surface in the master cylinder reservoir or after permeation through hoses. Another possibility is simple absorption into hose materials without evaporation off of the hose outer surface. Since simple vaporization of the amines off of the free fluid surface can be performed more reproducibly in the laboratory, direct evaporation was chosen as the initial laboratory procedure to emulate the observed vehicular loss of total nitrogen from the fluid.

The tendency of fresh fluids towards loss of amine inhibitors through volatilization can be quickly measured largely in isolation of other effects by placing 100 ml of fluid into a standard SAE corrosion test jar which is then placed, uncovered, in an oven at 100° C for 16 hours (temperature chosen for convenience to a lab running standard corrosion tests). Figure 4 shows how the RA drops for various fluids as a function of time under these conditions. However, this simple volatilization experiment alone does not accurately




Figure 3: % Reserve alkalinity retained after thermal oxidation and after complete lab-aging procedure were applied to SAE compatibility fluid RM-44-04 and commercially available fluids (\* indicates DOT 4 fluid).




Figure 4: Reserve alkalinity retention as function of heating time (covered) at 100°C for SAE compatibility fluid RM-44-04 and various commercially available fluids (\* indicates DOT 4 fluid).

reproduce the chemical changes observed during vehicle use, particularly the production of formamide oxidation products.

**OVERALL AGING: COMBINED PROCESSES** - The best fit of lab-aged fluid composition to vehicle-aged fluids has been obtained if the volatilization step is performed after the air-sparged refluxing procedure previously described. A lower temperature is used for volatilization in this combined procedure because (1) fluid temperatures at the location of volatilization (reservoir or hose) will be lower than the maximum system temperature used for the thermal oxidation step and (2) volatilization at higher temperatures could cause changes in the relative concentrations of base fluid components which have not been observed in vehicles.

The 2 liters of previously refluxed fluid are decanted into a 4 liter beaker, which is then held, uncovered, at 30° C (thermocouple in the fluid 2.5 cm above the bottom) for 64 hours on a hotplate regulated by a temperature controller. The fluid is then cooled and filtered through 2.5 µm paper (Whatman 42) to remove suspended copper powder, taking care in pouring to capture any condensate on the sides of the beaker along with the liquid. Weight losses from the fluid during this volatilization step range from about 2 to 5%.

The black columns of Figure 3 show the %RA (vs. fresh fluid) retained after both the thermal oxidation and volatilization step for a number of fluids. For most, but not all, fluids, almost all of the loss of buffering capacity occurs during the thermal oxidation step of the laboratory aging procedure.

Table 4 compares chemical parameters for fresh, laboratory-aged and vehicle-aged fluids. By design, the dissolved metals contents of lab-aged fluids are significantly lower than those of fluids used in vehicular service. The low metal contents in the lab-aged fluids simplify detection of corrosion when lab-aged fluid is put into the brake systems of new vehicles.

Table 4 : Comparison of chemical properties of a fluid in vehicular-aged and laboratory-aged forms.

Item	% RA	% aged	formamide % of surface	Cu ppm	Fe ppm	Zn ppm
77371	17%	5%	17%	220	110	50
85245	9%	3%	17%	210	60	60
77160	12%	<3%	20%	320	160	120
lab-aged	13%	8%	10%	82	3	<5

## BEHAVIOR OF LABORATORY-AGED FLUIDS IN VEHICLES

**DISSOLVED METALS** - To test the correlation of expectations from laboratory work with true vehicular behavior, an experiment was run in matched new vehicles using two brake fluid formulations (I and II), each in both fresh and lab-aged conditions. Table 5 shows dissolved metals content after 6 months fluid use for the individual vehicles, grouped by fluid type. The clear difference between the four groups is that the lab-aged fluid I led to significantly higher dissolved iron levels than seen in the other three groups. Since repeat analysis confirmed an essentially null iron content for the lab-aged fluids at the time they were put into vehicles, it was clear that the laboratory-aged form of fluid I had initiated some form of iron corrosion during 6 months vehicular exposure. No iron corrosion was detected during this brief vehicular exposure for the non-aged form of I or for either the fresh or lab-aged forms of II. Comparison of the results of Table 5 with the new-fluid dissolved metals timeline of Figure 2 suggests that the laboratory aging procedure appears to have accelerated the relevant fluid about 30 months down the timeline. In contrast, Fluid II showed no increase in 6 month vehicular dissolved iron after the same laboratory stress prior to installation in new matched vehicles, suggesting improved durability of iron corrosion protection.

**CORROSION OF COMPONENTS** - Figure 5 compares the interior surfaces of cast iron wheel cylinders which ran 6 months (top) and 12 months (bottom) with lab-aged fluids I (left) and II (right) in the vehicular experiment. The non-corroded appearance on the right duplicates all previous testing experience with fresh brake fluids - no corrosion of cast iron components occurs before several years of vehicular exposure. The rusting seen on the left with lab-aged I is similar to corrosion sometimes seen in wheel cylinders of vehicles after several years in the field - a patch of rust builds at the bottom of the cylinder. Electron microscopy of the rust patch shows, again in agreement with long-term vehicular experience, deposition of significant levels of copper in the corroded region. The appearance of this corrosion correlates with the elevated dissolved iron levels seen in laboratory-aged fluid I within 6 months of the start of service. No corrosion was seen in wheel cylinders running fresh fluids I or II or lab-aged fluid II, again in agreement with the dissolved iron data. It should be noted that the difference in dissolved Fe and observed cylinder corrosion was observed despite the similar levels of dissolved copper in all four groups of vehicles. While copper is implicated in the iron corrosion by its deposition in the rusted areas, the data suggest that it is necessary to have severely depleted the iron corrosion inhibitors (amines) before the dissolved copper can accelerate the corrosion of iron.

Table 5: Dissolved metals for fresh and lab-aged fluids I and II, before and after 6 months service in matched vehicles.

Fluid	fresh / lab-aged	Iron	Cu ppm	Fe ppm	Zn ppm
I	fresh	0	0	0	0
II	fresh	0	0	0	0
I	aged	0	82	3	<3
II	aged	0	69	3	<3
I	fresh	16261	130	<2	11
I	fresh	30910	320	<3	17
I	fresh	18465	460	3	26
I	fresh	9745	150	<3	16
I	aged	35385	210	50	20
I	aged	11350	240	33	49
I	aged	24975	260	57	61
I	aged	20089	270	50	23
II	fresh	13384	110	2	12
II	fresh	26333	180	<3	16
II	fresh	7501	54	<3	5
II	fresh	34128	160	11	13
II	aged	17260	240	5	64
II	aged	19742	250	5	74
II	aged	12613	230	3	42
II	aged	11779	360	3	81

#### BEHAVIOR OF LAB-AGED COMMERCIAL BRAKE FLUIDS IN SAE J1703 LABORATORY CORROSION TESTS

Internal corrosion of brake system components has been observed in some vehicles after several years' service in brake fluids which easily pass the corrosion tests in the J1703 standard. One cannot, therefore, have confidence that the standard corrosion tests performed on fresh fluids adequately predict the durability of corrosion protection for the life of the vehicle. Laboratory-aging of fluids prior to vehicle fill has reproduced long-term vehicular effects after much shorter vehicular exposure. In an attempt to develop a laboratory corrosion test which does have predictive power for the durability of corrosion protection, standard corrosion tests were run on a number of commercial brake fluids in both fresh and laboratory-aged (thermal oxidation + volatilization) conditions. In this application, the ca. 100 ppm copper level in some lab-aged fluids complicates the interpretation of weight-loss measurements. Copper deposition can accompany corrosion, (most noticeably on zinc, iron, and aluminum coupons) and decrease the magnitude (or even invert the apparent sign) of real corrosive weight losses. Lab-aged fluids were therefore analyzed for metals after being used in the corrosion test, and the dissolved metals contents were cross-checked against the measured weight losses to ensure that the latter were not grossly misleading.

Table 6 shows standard J1703 corrosion test weight changes for SAE compatibility fluid RM-66-04 and for 9 commercially available fluids tested both in fresh and laboratory-aged conditions. A number of fluids showed significant zinc weight losses and/or etching when tested in lab-aged form. Otherwise no weight losses or gains outside the SAE limits were induced by lab-aging prior to the standard J1703 corrosion test. It should be noted that used fluid from vehicles can also show no objectionable weight losses in the standard J1703 corrosion tests, even when the used fluid is drawn from vehicles after service intervals which sometimes produce visible corrosion of components. It appears that the conditions of the corrosion test in J1703 are not severe enough to produce visible corrosion even from aged fluids which do allow visible internal brake system corrosion in severe vehicular service.

Table 7 shows preliminary results on weight changes for metals tested in lab-aged fluids by the J1703 method modified by addition of 50 ppm chloride to the test fluid. With the addition of chloride, not only zinc but also cleaned iron, steel and/or aluminum showed pitting or etching with some lab-aged fluids.

Modifying the J1703 corrosion test both by lab-aged fluid and by addition of 50 ppm chloride clearly increases its severity and its ability to distinguish between fluids, at least in regards to coupon appearance. However, even this doubly-modified version of the SAE corrosion test does not reproduce the effect on cast iron observed in vehicles.

To minimize the future necessity of vehicular testing, even with lab-aged fluids, more stringent laboratory corrosion tests must be developed. Additional factors which may contribute to the more aggressive corrosion environment in vehicles compared to the standard J1703 corrosion test include details of the time/temperature history of the fluid and further changes in brake fluid chemistry induced by interactions with consumers in the system (particularly loose materials). Further modifications to the standard J1703 corrosion test procedures, as applied to lab-aged fluids, are being investigated to determine the simplest possible laboratory corrosion test conditions which better reproduce the worst-case behavior of fluids in severe vehicular service.

#### SUMMARY AND CONCLUSIONS

Constantly increasing expectations for durability of automotive components on the part of both consumers and manufacturers suggest the desirability of improved methods to ensure the durability of corrosion protection in brake fluids. Chemical analysis of used brake fluids has shown that the species which are often the primary corrosion inhibitor can be lost over time both through thermal oxidation and by another process which completely removes nitrogen from the fluid. A two-step laboratory aging procedure was developed to reproduce these vehicular changes in brake fluid chemistry. Fluids subjected to this laboratory aging process typically still passed all of the corrosion weight change requirements of the standard SAE J1703 corrosion test (except, in some cases, that

for zinc). However, when lab-aged fluid was used in controlled vehicular tests of less than one year's duration, increased levels of dissolved iron appeared in the fluid and inspection of cast iron wheel cylinders showed visible internal corrosion. Such corrosion, with a morphology never before reproduced in laboratory or vehicular testing but seen in some vehicles after multiple years' actual service, suggests that the lab-aging procedure does reproduce corrosion properties representative of old fluid in severe service. Short-term vehicular testing with lab-aged fluids therefore provides the first feasible accelerated means of determining the long-term durability of both fluids and brake system components against internal corrosion.

J1703 corrosion test results with fresh, vehicle-aged, and laboratory-aged fluids show that the standard laboratory corrosion test procedures do not reproduce winter-time conditions, after long term vehicle use, even when the appropriate aged fluid chemistry is used. Appropriate additions of chloride increase the severity of the lab test conducted with lab aged fluids, but the fit to extreme vehicular conditions remains incomplete. Further development of laboratory corrosion tests, in conjunction with fluid-aging procedures, is needed if facile, as well as reliable, prediction of the long-term corrosion durability of brake fluids and system components is to become possible.

#### ACKNOWLEDGMENTS

The authors owe thanks to many people for essential collaboration: W.A. Noll of Delphi Chassis contributed essential insight and support. M.S. Harrington, V. Gilliam, J. Leonard, D. Lantz, and D. Park of UCC performed analytical work and/or testing. T.E. Moylan of GM R&D performed much of the laboratory-aging work. K. L. Olson of GM R&D developed and ran the new NPD gas chromatographic and capillary electrophoresis techniques for analyzing brake fluid. T.J. Chapman, D.F. Eash, P.M. Hanley, and N.M. Potter of GM R&D provided metals analysis and other analytical effort.

#### REFERENCES

1. NHTSA Standard No. 116, "Motor Vehicle Brake Fluids", 49 CFR 371-116, October 1, 1993.
2. SAE Standard, "Motor Vehicle Brake Fluid" - SAE J1703, SAE Handbook, SAE, New York, New York, January, 1995.
3. "Standard Test Method for Reserve Alkalinity of Engine Coolants and Antifrosts", 1996 Annual Book of ASTM Standards, V. 15.05, D 1121-93, pp. 10-12, ASTM, West Conshohocken, PA.
4. The 50 ml comparison volume is set by no standard but mimic from common practice of titrating pH test fluid defined by section 4.3 of SAE J1703 prepared with 50 ml of brake fluid.
5. H.H. Willard, L.L. Merritt, Jr., J.A. Dent, and F.A. Sestic, Jr., Instrumental Methods of Analysis, 6th edition, Van Nostrand, New York, New York, 1981, p. 472.
6. P.L. Peterson, "Recent Advances in Thermionic Detection for Gas Chromatography", *J. Chromatographic Science*, 24, 41-52 (1986).
7. R. Kuhn and S. Horchinske-Kuhn, Capillary Electrophoresis: Principles and Practice, Springer Verlag, Berlin, Germany, 1993.
8. J.P. Leaders, ed., Handbook of Capillary Electrophoresis, CRC Press, Boca Raton, FL, 1993.
9. W. Bock and H. Engelhardt, "Capillary Electrophoresis of Organic and Inorganic Cations with Indirect UV Detection", *Chromatographia*, 33, 313-316 (1992).
10. Meyer, P.W., "Brake Fluids and Brake Fluid Specifications in Europe", *Society of Automotive Engineers*, 710232, 1971.
11. Cotton, P.A. and Wilkinson, G., Advanced Inorganic Chemistry: A Comprehensive Text, 3rd ed., John Wiley & Sons, New York, New York, 1972, pp. 320-321.

Figure 5: Cast iron wheel cylinders after 6 (top) and 12 (bottom) months vehicular service in lab-aged fluids I (left) and II (right).



Table 6: J1703 weight changes for metals ( $\text{mg/cm}^2$ ) in fresh and lab-aged fluids (reported fresh/lab-aged). Results outside J1703 requirements established for fresh fluids printed in boldface (\* indicates DOT 4 fluid).

Fluid	cold-iron	steel	aluminum	cast iron	brass	copper	zinc
SAE max. allowed	+0.2	+0.2	+0.1	+0.2	+0.4	+0.4	+0.4
SAE RM-66-04	<b>-0.07 /</b> <b>+0.04</b>	<b>-0.01 /</b> <b>+0.04</b>	<b>-0.00 /</b> <b>+0.04</b>	<b>+0.06 /</b> <b>+0.03</b>	<b>-0.02 /</b> <b>+0.02</b>	<b>-0.01 /</b> <b>+0.07</b>	<b>-0.02 /</b> <b>+0.32</b>
a	-0.01 / +0.02	+0.01 / -0.00	-0.00 / -0.02	+0.04 / +0.00	-0.07 / -0.01	-0.06 / +0.02	-0.00 / -1.32
b	-0.01 / +0.04	-0.00 / +0.06	+0.03 / +0.02	+0.10 / +0.07	-0.02 / +0.24	+0.02 / +0.23	-0.35 / -3.84
c	+0.02 / +0.01	-0.01 / +0.00	+0.03 / +0.04	+0.00 / +0.03	-0.02 / +0.07	-0.04 / +0.09	-0.12 et / -3.04
d	+0.03 / +0.01	+0.03 / +0.02	+0.02 / +0.05	+0.03 / +0.06	-0.02 / -0.02	+0.01 / +0.01	+0.02 / +0.02
e	-0.00 / -0.01	-0.00 / +0.04	-0.01 / +0.03	-0.00 / +0.12	-0.07 / +0.09	-0.10 / +0.25	+0.02 / -1.01
f	+0.00 / +0.00	+0.03 / +0.04	+0.03 / +0.02	+0.08 / +0.03	-0.08 / -0.10	-0.06 / -0.00	+0.02 / -0.73 et
g	-0.01 / +0.03	+0.03 / +0.02	-0.00 / +0.02	+0.06 / +0.05	-0.05 / +0.05	-0.06 / +0.08	+0.01 / -0.32 et
h*	-0.00 / +0.03	-0.00 / +0.03	-0.00 / +0.01	+0.04 / +0.08	-0.00 / -0.03	+0.01 / +0.03	+0.02 / +0.04
j*	+0.06 / +0.01	+0.05 / +0.02	+0.03 / +0.01	+0.10 / +0.03	+0.02 / -0.14	+0.04 / -0.17	+0.12 / +0.07

et = etching (failure according to SAE J1703 requirement 4.6)

Table 7: Weight changes for metals (mg/cm<sup>2</sup>) in lab-aged fluids subjected to J1703 corrosion test procedures modified by addition of 50 ppm chloride to the test fluid. Results outside J1703 requirements (established for fresh fluids without chloride) printed in boldface (\* indicates DOT 4 fluid).

Fluid	tinplate iron	steel	aluminum	cast iron	brass	copper	nickel
SAE max. allowed	+0.2	+0.2	+0.1	+0.2	+0.4	+0.4	+0.4
SAE RM-44-84	-0.06	+0.02	-0.00 et	+0.03	-0.04	+0.01	-0.04
a	+0.01	+0.02	+0.13 et	+0.08	-0.17	+0.21	-1.34
b	-0.01 pt	-0.04	-0.00	-0.00	+0.17	+0.23	-4.51 et
c	+0.03	+0.03	+0.02	+0.05	-0.02	+0.08	-1.34
d	-0.01	-0.00	+0.06 pt	-0.00	-0.13	-0.05	-0.61
e	-0.00	-0.03	+0.02 et	+0.04	-0.10	-0.02	-3.03 et
f	+0.03 pt	-0.00 pt	-0.02	+0.02	-0.01	+0.04	-1.42 et
g	+0.02	+0.03	-0.00 et	+0.10	-0.07	-0.00	-0.36 et
h*	-0.04 et	-0.01	-0.02	+0.04	-0.23	-0.15	+0.03
j*	-0.00 et	-0.00	+0.08 et	+0.08	-0.24	-0.20	+0.06

et = etching perplis (failure according to SAE J1703 requirement 4.6)

## FACSIMILE COVER SHEET

**TO:**

Name:

Greg Stevens / Norman LaPointe

Company:

Ford Motor

Phone No.:

Fax: 313 323-6686 / 313 337 8256

Routine:

Rush: X

Comments:

SAG paper we discussed during  
Meeting on 2/24/99**FROM:**

Name:

M.K. KTT

Phone No.:

225 355-6343

Fax No.:

Date:

2/25/99

Time:

TOTAL NUMBER OF PAGES

11

(including this cover page)

YOU ARE NOTIFIED THAT THE INFORMATION CONTAINED IN THIS FACSIMILE TRANSMISSION IS COMMUNICATION INTENDED FOR THE USE OF THE INDIVIDUAL WHO IS NAMED ABOVE. IF YOU ARE NOT THE INTENDED RECIPIENT, OR AN EMPLOYEE OR AGENT RESPONSIBLE FOR DELIVERY TO THE INTENDED RECIPIENT, YOU ARE PROHIBITED FROM DISSEMINATING, DISTRIBUTING, OR COPYING THIS INFORMATION. IF YOU HAVE RECEIVED THIS COMMUNICATION IN ERROR, PLEASE NOTIFY US IMMEDIATELY BY TELEPHONE AND RETURN THE ORIGINAL MESSAGE TO US AT THE ADDRESS SHOWN ABOVE BY THE U.S. MAIL AT OUR EXPENSE. THANK YOU.

TEXAS INSTRUMENTS INC.				MATERIALS & CONTROLS GROUP	SITE
PARTS LIST	PROJECT			PART NUMBER: 77PSL2-1	REV LTR: L CLS: 650
EXPLOSION	NUM: 3423			DWG PFX: NUM: 77PSL2-1	ECN INC DT: 98/02/24
TITLE: PRESSURE SWITCH				(CUST P/N F2VC-9F924-AB)	
LV/CNT	QTY/UM	ITEM	PART/DRAWING NUMBER	REV	NOMENCLATURE/PARM DATA
01	1	REF	36952-1 36952-1		FINAL ASSEMBLY
01	2	1	271 27759-10 27759SH1	A1	BASE ASSEMBLY
02	3	1	2 46515-2 46515	L1	BASE (BROWN)
02	4	1	3 36888-1 36888	N1	STATIONARY TERMINAL
02	5	1	4 36897-2 36897SH1	D1	MOVABLE TERMINAL ASM
03	6	1	21 36887-1 36887	H1	MOVABLE TERMINAL
03	7	1	3 74916-1 74916	D1	RIVET
03	8	1	4 36889-1 36889	G1	SPRING ARM
04	9	AN	21 27716-1 27716SH1	B1	SPR MAT'L STR SPEC (.216 LB/K)
03	10	1	5 28744-1 28744	D1	MOVABLE CONTACT
01	11	1	24 27293-13 27293SH2	H1	SENSOR ASSEMBLY
02	12	1	21 36980-1 36980	H1	MOD SAE J512 HEXPORT
02	13	1	3 74353-1 74353	H1	GASKET
02	14	1	4 27713-1 27713	F1	CUP
02	15	3	5 74176-1 74176	F1	SEAL
03	16	AN	27225-1 27225	C1	KAPTON STRIP SPEC (.175 LB/K)
02	17	1	6 27639-1 27639	AB1	WASHER
02	18	1	7 27406-1 27406	F1	CONVERTER
02	19	1	8 73958-2 73958	F1	SPACER
02	20	OR	8 73958-3 73958	J1	SPACER
03	21	AN	74224-1 74224	F1	KAPTON TAPE (.100 LB/K)
02	22	1	9 36656-27 36656SH1	BM1	3/4" FORMED DISC Amts on DMS reference 15135
02	23	OR	9 36656-28 36656SH1	BM1	3/4" FORMED DISC
04	041	1	141 74797-1	BM1	CHTMD RTNR

3719 7830

01	25	1	18	74078-143 74078	! B! ! TRANSFER PIN
01	26	1	21	74247-4 74247	! G! ! ENVIRONMENTAL SEAL
01	27	1	22	74888-1 74888	! L! ! THREAD CAP ! A!
01	28	AR		27318-1 27318	! CARTON ASM. ! D!
02	29	1	23	74219-1 74219	! CARTON
02	30	3	33	74218-1 74218	! D! ! ROW SEPARATOR
02	31	2	41	27317-1 27317	! D! ! DEVICE SEPARATOR
02	32	AR	51	13688-4 13688-4	! E! ! CLOSURE TAPE

! NOTES, REV, DATA, DISTRIBUTION, OPERATING CHARACTERISTICS, SPECIAL REQUIREMENTS !

REV DESC: CHG 74488-1 TO 28744-1 ! CCB APPROVAL DATE: 98/02/24

DFTG WORK GROUP: PRECISION CONTROLS ! ECN ORIGINATOR: DI T HA

NOTES:

- 1 - ACTUATION PRESSURE ----- 90 -160 PSIG
- 2 - RELEASE PRESSURE----- 20 PSIG MIN.
- 3 - DEVICE TO BE MARKED PER CODING SPECIFICATION 75871-1

DETAILED REVISION DESCRIPTION:

99 CR M39209, 28744-1 CONTACT (MOV) WAS 74488-1  
STOCK DISPOSITION  
FINISHED DEVICES - USE  
PARTS & SUB ASMS - USE SUBS, HOLD PARTS

75525 SH.1 NOTE 5: "NECESSARY" WAS IN A RANGE OF .35 TO .60... THICKNESS - 2; NOTE 6: .35/4" WAS .11/2"	DEVICE # 55PS PROJ. # 3371	TITLE MATERIAL SPECIFICATION AISI #301 STAINLESS STEEL	REV G	75525 SH.1														
<p>1. MATERIAL TEST REPORTS AND THICKNESS TRACE MUST BE SUPPLIED WITH EACH LOT OF MATERIAL.</p> <p>2. CHEMICAL COMPOSITION OF MATERIAL:</p> <table> <tr> <td>C</td> <td>Mn</td> <td>P</td> <td>S</td> <td>Si</td> <td>Cr</td> <td>Ni</td> </tr> <tr> <td>.09/.12</td> <td>.90/1.30</td> <td>.04 MAX.</td> <td>.010 MAX.</td> <td>.35/.75</td> <td>17/17.5</td> <td>7/7.5</td> </tr> </table> <p>3. MATERIAL: THE MATERIAL SHALL BE VACUUM MELTED. INCLUSION DETERMINATION SHALL BE MADE ON STARTING STOCK FOLLOWING THE RATING PROCEDURES OF ASTM E-45. INCLUSIONS SHALL BE 2 MAXIMUM PER METHOD A.</p> <p>6 Ra MAX. SURFACE FINISH (TARGET 4 Ra)</p> <p>MAX. ALLOWABLE BURR .0008"</p> <p>4. MECHANICAL PROPERTIES: (SEE TABLE SHEET 3)</p> <p>AS A REFERENCE TENSILE STRENGTH - NOMINALLY 7 KSI GREATER THAN THE YIELD STRENGTH.</p> <p>5. STRIP STRESS RELIEF: STRIP STRESS RELIEVE AT A TEMPERATURE IN THE RANGE OF 1000°/1200°F. AND AT A SPEED NECESSARY TO ACHIEVE SPECIFIED MECHANICAL PROPERTIES. NO PASSIVATION PERMITTED. APPLY GULF STAINLESS METAL 13 OR EQUIVALENT AFTER STRESS RELIEF.</p> <p>6. STOCK CURVATURE: NATURAL STOCK CURVATURE OF THE STRIP SHALL NOT EXCEED 3/4 INCH PER FT. OF LENGTH PER FIG. 3 AND SHALL BE MEASURED WITH A 12 INCH LENGTH OF STRIP LAID UNRESTRAINED, ON EDGE, ON A SMOOTH SURFACE.</p> <p>7. CUT SIZE: 18" I.D. 25° MAX. O.D. MAX. CUT WEIGHT 60#</p> <p>8. PROCESS CHANGES: THE SUPPLIER SHALL IDENTIFY THE DISCRETE, STEP-BY-STEP PROCESS TO MAKE EACH TEXAS INSTRUMENTS PART NUMBER ORDERED. THESE PROCESSES SHALL BE DOCUMENTED, REVISION CONTROLLED, AND MAINTAINED BY THE SUPPLIER. ALL PROCESSING MUST BE ACCOMPLISHED IN ACCORDANCE WITH THE APPROVED DOCUMENTATION. DOCUMENTATION SHOULD INCLUDE BUT NOT BE LIMITED TO:</p> <ul style="list-style-type: none"> <li>A. ALL MAJOR EQUIPMENT TO BE USED DURING MATERIAL PROCESSING. THIS SHOULD INCLUDE ANY ALTERNATE EQUIPMENT THAT IS USED.</li> <li>B. THE CRITICAL OPERATING PARAMETERS TO BE SET ON EACH MACHINE.</li> <li>C. THE QUALITY AND LAB CHECKS TO ENSURE DUALITY COMPLIANCE.</li> </ul> <p>COMPLETED PROCESS TRAVELERS MUST BE MAINTAINED ON FILE AT THE SUPPLIER'S LOCATION FOR A PERIOD NOT LESS THAN 3 YEARS AFTER MATERIAL SHIPMENT AND MUST INCLUDE INFORMATION TO ENABLE TRACEABILITY FROM ANY MATERIAL LOT BACK TO THE CORRESPONDING COMPLETED TRAVELER. WHERE ALTERNATE EQUIPMENT IS PERMITTED, THE COMPLETED PROCESS TRAVELERS MUST INDICATE WHICH SPECIFIC EQUIPMENT WAS USED.</p> <p>ANY CHANGES TO THE PROCESS DOCUMENTATION AFTER QUALIFICATION MAY NOT BE MADE WITHOUT THE WRITTEN APPROVAL OF T.I. AND MAY REQUIRE RE-DUALIFICATION.</p> <p>9. PACKAGING: SHALL INCLUDE VAPOR BARRIER RUST INHIBITOR EQUIVALENT TO CORTEC VCI 132.</p>					C	Mn	P	S	Si	Cr	Ni	.09/.12	.90/1.30	.04 MAX.	.010 MAX.	.35/.75	17/17.5	7/7.5
C	Mn	P	S	Si	Cr	Ni												
.09/.12	.90/1.30	.04 MAX.	.010 MAX.	.35/.75	17/17.5	7/7.5												
SUPERSEDES DWG. 75525 SH.1 REV."F", DATED 10-29-96																		
00W>				H4-24 038E 027-4 01 013														
CHAS. PLEURANT 2-5-98 SL FEB 24 '99 12:22		TEXAS INSTRUMENTS ATTLEBORO, MASSACHUSETTS 02703	RILSON CORPORATION 	75525 SH.1 PAGE. 05 3713 7632														

75525#2

## COIL IDENTIFICATION



REV. A

75525#2 SH.

LOT CONTROL CODING FOR FINAL SLIT COIL (MARK CLEARLY ON INNER SURFACE OF EACH COIL)

IDENTIFICATION OF COIL NO. OF THE  
MASTER COIL (IF THE MASTER COIL  
CONSISTS OF MORE THAN 1 COIL.)  
EXAMPLE:

- A - 1<sup>ST</sup> COIL (OR ONLY COIL)
- B - 2<sup>ND</sup> COIL
- C - 3<sup>RD</sup> COIL

BREAKDOWN OF 24.5" WIDTH.  
SLIT & IDENTIFY 3 CUTSBREAKDOWN CUTS TO MEET  
FINAL INDIVIDUAL COIL SIZEFINAL SLIT TO  
ORDERED WIDTHMASTER COIL 54.5" WIDE  
(5 DIGIT NO.)FIG. # 1MATERIAL EXITING  
FROM TOP OF COILFIG. # 2

REVISION	0.375	01-1	1442	144-27011	P3P	P37
BY	J. Dail 3/14/95					
CR	D. Hult 3/25/95					
REW	C. Sampio 3/16/95					



TEXAS INSTRUMENTS  
INCORPORATED  
ATTLEBORO, MASS., U.S.A.

KIDRON  
CONTROL PRESSURE  
REGULATOR

5082363153

PAGE 08

FEB 24 '99 12:22

3713 7633

DEVICE # 55PS PROJ.# 3371	TITLE MATERIAL SPECIFICATION	REV V	75525 SH.3
------------------------------	---------------------------------	----------	------------

400-13 IDENTICAL TO -3 except  
SLIT width will be .673-.676 A.  
04/27/98 DONNAHOO329 MF

MAX. COIL WIDTH 1.54" TO 1.50" G.O.  
1.51"-.12" 1.53"-1.57" O.T.H.  
1.52"-.10" 1.51"-.08" O.T.H.  
1.53"-.06" 1.52"-.04" O.T.H.  
1.54"-.04" 1.53"-.02" O.T.H.




FIG. 3

MAX. VARIATION WITHIN ANY FINISHED CUT.  
TOTAL COIL VARIATION SHALL NOT EXCEED  
.0003".

75525-13	.873 - .877	.0105 ± .00015"	50-80	200/230	5/32	2.2
75525-12	.498 - .502	.0085 ± .00015	50-80	200/230	5/32	.53
75525-11	.498 - .502	.007 ± .00015	50-80	200/230	5/32	.44
75525-10	.498 - .502	.0055 ± .00015	50-80	200/230	5/32	.34
75525-9	24° REF.	.072 REF.	N/A	N/A	N/A	N/A
75525-8	.873 - .877	.014 ± .00015"	50-80	200/230	5/32	2.38
75525-7	.648 - .652	.007 ± .00015"	50-80	200/230	5/32	.79
75525-8	.848 - .852	.0055 ± .00015"	50-80	200/230	5/32	.80
75525-5	.873 - .877	.013 ± .00015"	50-80	200/230	5/32	2.7
75525-4	.648 - .652	.005 ± .00015	50-80	200/230	5/32	.54
75525-3	.748 - .752	.0105 ± .00015"	50-80	200/230	5/32	1.8
75525-2	.873 - .877	.0122 ± .00015"	50-80	200/230	5/32	2.5
OBSOLETE PER CR155360 8-14-90						

PART NO.	SLIT WIDTH	THICKNESS	COLD WORK %	0.2% OFFSET YIELD STRENGTH (KSI)	MAX. EDGE CAMBER FOR 3 FT OF LENGTH	LBS /K

QTY	Q1	M4-1	M4-2	Q13
CHAS. PLEURANT B-2-B2				
O.C WAGNER B-2-B2				



TEXAS INSTRUMENTS  
ATLANTA, GEORGIA 30339


KLIXON  
GENERAL PRODUCTS DIVISION

5082363153

A 75525 SH.3


**Figure 1.**

## 2 and 3 parameter WEIBULL FAILURE ANALYSIS



NOTES: TTPB 720K cyclic data point included in analysis


### Hydraulic Pressure Switch Cross Section



3713 7636

## Brake Pressure Switch Function-

- Provide power to Speed Control Clutch circuit.  
Clutch engages servo-motor to pull throttle cable.
- Provide redundant sensing of brake application independent of the primary system deactivation mode by disconnecting power to clutch circuit causing servo-motor to release throttle cable.
  - Under Hard Braking only
  - Stop lamp signal is primary (normal braking)



Brake Pressure Switch  
P2VC-5F924-AB  
Material List for MY 92/93

2nd Q 92  
quiet disc  
introduced  
+ just snap  
less in deflection

Material List for MY 92/93		
Gasket	Elastomer Ethylene Propylene	JBL Compound # E-7104-70
Diaphragm	Kapton, Polyimide	Dupont 500 FN131L, 3 Diaphragms per switch
Base	PBT, Plastic	Grade Celanex 4300
Crimp Ring	Aluminum	Grade # 5052
Spacer	Kapton, Polyimide	Dupont #200H, Friction Reducer on Disc
Rivet	Brass	CDA 260
Transfer Pin	Ceramic	Sinterite , L-3 Grade
Environmental Seal	Silicone	JBL Compound # S7519
Converter	Cold Rolled Steel	Grade # 1008
Washer	Cold Rolled Steel, Zinc Plated	Grade # 1050
Cup	Cold Rolled Steel	Grade 1010
Spring Arm	Beryllium Copper	Grade # C17200
Movable Contact	Silver Plated Copper	Oxygen Free Cu, Fine Silver
Stationary Terminal	Brass + Silver Inlay	CDA 260
Movable Terminal	Brass	CDA 260
Disc	Stainless Steel	Grade 302 ?? former disc matl.
Hexport	Cold Rolled Steel, Zinc Plated	C10L10
Thread Cap	LDPE, Plastic	

\*\*\*\*\*  
\* Note printed by NLAPPOINT on 17 Feb 1999 at 16:14:08 \*  
\*\*\*\*\*

From: FPORTER --DRBN007  
To: NLAPPOINT--DRBN005

Date and time 01/26/99 17:25:48  
SLAROUCH--FORDNAI

FROM: F. J. Porter  
Subject: (U) Brake Pressure Switch Material

USAET(UTC -08:00)

The following is from TI drawings

Part	Material	Comments
Modified SAE J512 Hexport	C10L10 Steel	Zinc Plating .0003 min thk w/yellow dichromate
Converter	1068 or 1010 C.R. Steel	Zinc Plating .0002-.0004 thk may have rust inhibitor
Washer	1050 CRS	Zinc Plate .0002-.0006 thk Heat treat austemper Rockwell 40-60
Cup	1010 or 1006 C.R.S.	Zinc Plating w/yellow chromate .0002-.0004 thk
Spring	Beryllium copper C17200	Mill hardened (Brush Wellman alloy 190 nm)
Kapton	Dupont 500 PN1313L	1 mil Teflon PTFE 3 mil Kapton Type H 1 mil teflon PTFE
Moveable Contact	Copper	Finish: DMC-133 OFHC Silver DMC-10 fine silver

Environmental Seal Silicon JBL S7519

Transfer Pin	L-3 Grade Steatite (DC-15ES) or L-3 Grade Steatite (DC-144H)
Switch Rivet	CDA 260 Brass
Gasket	Ethylene Propylene JBL Compound E-7104-70 JBL Part No. 61978
Spacer	Dupont Kapton 200H .0017-.0023 thk
Crimping Ring	Aluminum 5052
Thread Cap	LOPE

Regards,  
Fred Porter CV - fporter  
Chassis E/E Systems Applications (313)845-3722  
Bldg 5 - Mail Drop 5030 - Cubicle 3B004 fax: 390-4145


*D/S* *302 S.S.*

74797

## CRIMP RING

REV.  
B

74797



## NOTES:

1. PINCH OFF RADIUS ALLOWED.
2. .002 MAX. BURR ALLOWED.
3. PARTS TO BE SHIPPED ISSUED AND STORED IN SEALED PLASTIC BAGS.
4. MATERIAL CERTIFICATION REQUIRED WITH EACH SHIPMENT.

FOR REFERENCE ONLY  
CHECK LATEST REVISION  
BEFORE USE  
Parts Made To This Print Must Conform To  
ENGL. STD. E9898 REV. E

Date JAN 7 1999

NOTWITHSTANDING THE INFORMATION CONTAINED  
HEREIN IS TO BE USED AGAINST THE  
SAVED DRAWINGS AS THE INCORPORATED  
PROPERTY OF TEXAS INSTRUMENTS INC., ANY USE APPLICABLE  
OR OTHERWISE THEREOF OR ANY OF ITS APPLICATIONS  
COMPLIANCE OR VIOLATION THEREOF.

SUPERSEDES DWG. 74797 REV. A DATED 11-2-90

74797-1	ALUMINUM 6062	
PART NO.	MATERIAL	FINISH
REV. B		
BY CHIEF FABRICANT 11-2-90 CH. <i>[Signature]</i> 1-30-91 ENG. <i>[Signature]</i> 90128	TEXAS INSTRUMENTS ATTLEBORO, MASSACHUSETTS 02703	NIXON CONTROL PRODUCTS DIVISION
		DWG. NO. A
		74797

CODE IDENT NO. 82647

3713 7640

DEVICE # 51PS  
PROJ. # 3355


TITLE

SPACER

REV  
J

73958

73958



NOTES:

- ◆ 1. .001 MAX. BURR ALLOWABLE.  
2. PARTS TO BE SHIPPED, ISSUED, AND STORED IN SEALED PLASTIC BAGS.  
3. ALL CONTAINERS OF PARTS MUST BE DATE CODED, DATE CODE IS TO REFLECT  
ANY MATERIAL LOT, TOOL OR PROCESS CHANGE.  
4. MATERIAL CERTIFICATION REQUIRED WITH EACH LOT.

CHANGED THE SECOND NOTE THREE TO NOTE FOUR.  
S/N 30-03  
S/N 12782, D.P.

73958-4	KAPTON .0017 - .0023 THICK (FORD RCS)	.260/.270
73958-3	MADE FROM 74224-1 (KAPTON TAPE)	NO HOLE
73958-2	DUPONT'S KAPTON 200H, .0017 - .0023 THICK	NO HOLE
73958-1	KAPTON .0017 - .0023 THICK	.260/.270
PART NO.	MATERIAL	DIM 'A'

THIS DWG. SUPERSEDES 73958 REV. "H" DATED 3-02-93.

REWD:

BY TOM DAIL 10-10-88

CH.

7-7-93



TEXAS INSTRUMENTS  
ATTLEBORO, MASSACHUSETTS 02703

KLIXON  
CONTROL PRODUCTS  
DIVISION

REV. B  
A

73958

PRINT NUMBER 73958

3713 7641

74224

TITLE

KAPTON TAPE


REV.

F

74224

## NOTES:

1. ROLLS SLITTED FROM ENDS OF MASTER COIL NOT ACCEPTABLE.
2. BUCKLING OF THE CORE ALLOWED UP TO  $1/4"$  MEASURED RADIALLY AWAY FROM THE CORE.
3. DENTS, RIPS, OR JAGGED EDGES ON MATERIAL NOT ALLOWED.
4. ROLLS ARE TO BE SHIPPED WITH PROTECTIVE INSERT CORES IN THE PACKING BOX.



FOR REFERENCE ONLY  
CHECK LATEST REVISION  
BEFORE USE  
Parts Made To This Print Must Conform To  
ENG. STD. E9898 REV. E  
Dated JAN 7 1999

NOTICE: THIS DRAWING CONTAINS INFORMATION CONTROLLED BY THE UNITED STATES GOVERNMENT. IT IS FOR OFFICIAL USE ONLY AND IS NOT TO BE USED AGAINST THE INTEREST OF THE UNITED STATES. APPROVAL OR RELEASE OF ANY COPY OR PART THEREOF IS SUBJECT TO THE RESTRICTIONS OF THE CONTRACT WHICH AUTHORIZED ITS PREPARATION OR THE SPONTANEOUS DISCHARGE OF THE CONTRACTOR OR SPONSOR.

APPROVED MATERIAL: KAPTON 200H  
DATE: 10-14-90 BY: CH:

PART NUMBER	DUPONTS, KAPTON 200H	.0017/.0023	
	MATERIAL	THICKNESS	

THIS DWG. SUPERSEDES 74224 REV. "E" DATED 10-14-88

BY: TOM DAIL 10-14-90	TEXAS INSTRUMENTS ATTLEBORO, MASSACHUSETTS 02703	NIXON OFFICIAL PRODUCTS DIVISION	RS-A 187-3013 Q394M211235 DWG. NO. REV. A DATE: 10-14-90
CH:  EXCL: <i>John Hough 10-14-90</i> MAKPEACE			74224

3713 7642

	DEV. # 52PSL PROJ. # 3355	TITLE SEAL	REV C	74176
74176	<p>FOR REFERENCE ONLY CHECK LATEST REVISION BEFORE USE Parts Made To This Print Meet Customer To ENG. STD. E9898 REV. E Date JAN 7 1999</p> <p>NOTES: THIS PRINT IS FOR THE FURNISHING OF THE PART NUMBERED AS TO BE USED DURING THE MANUFACTURE OF TEXAS INSTRUMENTS INC. PRODUCTS OR ASSEMBLY TIME REQUIREMENTS OF 50% OF ITS APPROXIMATE CONTAINERS OR VOLUME SHOWN ON THIS DRAWING.</p>			
15ST ISSUE 52PSL-1 02/01/84 H.H. 02/22/84 D.G. 02/27/84 D.G.	ADD SAME NOTE AS ON 74075 03/17/98 HF ECHAN39730 D.H.	C	27225 MAS 27227 04/24/85 H.H. 02/22/82 S.L.	
74176-1	MAKE FROM 27225-1 (STRIP)			
PART NO.	MATERIAL			
A	SIGNATURES ON FILE. REFER TO ELECTRONIC CHANGE NOTICE.	THIS IS A CAD DRAWING. THE GEOMETRY IN THE ASSOCIATED CAD COMPUTER FILE IS DIMENSIONALLY ACCURATE. WHEN DRAWING IS BEING REVISED, THE GEOMETRY MUST BE UPDATED IN ALL VIEWS AND ON ALL SHEETS.		
REV>				
ISSUED H.H. 02/01/84 REVIEWED D.ETRAT 02/13/84 APPROVED C.H. WERNER 02/13/84 PUBLISHED				734 03 01 M21P25 RSX REV. NO. A 74176
<b>TEXAS INSTRUMENTS</b> ATLANTA, MASSACHUSETTS 02101		KUKON CONTROL PRODUCTS DIVISION		

3713 7643

74353

TITLE

GASKET


REV.  
H

74353

FOR REFERENCE ONLY  
CHECK LATEST REVISION  
BEFORE USE  
Part Made To This Print Must Conform To  
ENG. STD. E9998 REV. E

Bob JAN 7 1999

NOTES: THIS DRAWING IS FOR INFORMATION ONLY.  
DRAWN DRAWINGS TO BE USED AS PICTURES.  
INTERFERE ON THESE DRAWINGS ARE NOT ALLOWED.  
DO NOT MAKE ANY CHANGES OR ADJUSTMENTS  
UNLESS APPROVED BY THE ENGINEER OR MANAGER  
COMPANIES OR INDIVIDUALS OWNED BY THE COMPANY.



## NOTES:

1. PARTS MUST BE PURCHASED FROM TI ENGINEERING APPROVED VENDORS, LISTED BELOW.
2. MATERIAL CERTIFICATION REQUIRED WITH EACH SHIPMENT.
3. MATERIAL TO BE COMPATIBLE WITH FREON-1R & REFRIGERANT ONE.
4. PARTS TO BE SHIPPED, ISSUED, AND STORED ON 1 FOOT  $\frac{1}{2}$  INCH MANDRELS, SEALED IN PLASTIC BAGS AND SHIPPED IN CARDBOARD TUBES.
5. ALL CONTAINERS OF PARTS MUST BE MARKED TO REFLECT ANY MATERIAL LOT, TOOL OR PROCESS CHANGE.
6. DASH 1(-1) AND DASH 4(-4) GASKET MUST HAVE FOUR(4) WHITE STRIPING INK MARKS, EQUALLY SPACED AROUND THE CIRCUMFERENCE, AND NOT LESS THAN  $\frac{1}{8}$  INCH WIDE. NO INK IS ALLOWED ON ANY OTHER SURFACE.



PART NO.	MATERIAL	DIAMETER	COLOR	A	B	C
				(M)	(M)	(M)
74353-4	ETHYLENE PROPYLENE JBL COMPOUND E-7104-70 JBL PART NO. G1978	70	BLACK	.670-.662	.030-.036	.063
74353-3	ETHYLENE PROPYLENE JBL COMPOUND E-7054	70	WHITE	.670-.662	.030-.036	.063
74353-2	ETHYLENE PROPYLENE JBL COMPOUND E-7054	70	WHITE	.599-.591	.030-.036	.063
74353-1	ETHYLENE PROPYLENE JBL COMPOUND E-7104-70 JBL PART NO. G1978	70	BLACK	.599-.591	.030-.036	.063
REV. H		0.75	0.131	0.1-1	MUH	T35 P327 P35-1 09338
BY T. Dail 3-18-85	TEXAS INSTRUMENTS INCORPORATED ATTLEBORO, MASS., U.S.A.	KODAK	CONTROLS PROPERTIES DIVISION	A	74353	
CH. C. Jan 3-10-85						
ENCL. J. Jan 3-11-85						

3713 7644

DEVICE # 77PSL  
PROJ. # 3355

TITLE


THREAD CAP

REV  
A

74888

74888

FOR REFERENCE ONLY  
CHECK LATEST REVISION  
BEFORE USE  
Part Made To This Print Must Conform To  
ENG. STD. E9X98 REV. E  
Date JAN 7 1999  
  
NOTICE THIS PRINT IS FOR INFORMATION ONLY.  
THE TAILED DESIGN IS TO BE USED PRACTICALLY.  
INTERIOR OF THREAD UNLISTED BECAUSE INAPPLICABLE  
OR AMOUNT THE EXTENTS OF ANY OF ITS APPLICABILITY  
CANNOT BE DETERMINED OR WHAT IT COULD REQUIRE.



NOTE:

1. GATE MARK AND MANUFACTURER IDENTIFICATION IN RAISED LETTERS ON THIS SURFACE.

1ST ISSUE  
1-30-82, OF 30  
CRW07857

A	74888-1	CAPPLUGS	EC-6	LOPE	RED	
	PART NO.	VENDOR	STOCK NO.	MATERIAL	COLOR	
REV>					RS# 013	038 M21 P37-3035
CHAS. FLEURANT 1-30-82		TEXAS INSTRUMENTS	ATTLEBORO, MASSACHUSETTS 02703	KELIXON CONTROL PRODUCTS DIVISION	REV. A	74888
2.	3-1-93					CONFIDENTIAL NO 82847
3.	920206					

8713 7645

PROJ. # 3500	TITLE	REV	75755 SH.1				
			A	P31	Q3	Q4	M&I
INITIAL SYSTEM LOGON:		FOR REFERENCE ONLY CHECK LATEST REVISION BEFORE USE Parts Made To This Print Must Conform To ENG. STD. E9898 REV. E DIB JAN 7 1999					
FROM A BLANK IMS SCREEN TYPE IN  TSSON ATPSDA <USERID> <PASSWORD> WHERE <USERID> IS YOUR IMS USERID AND <PASSWORD> IS YOUR IMS PASSWORD.  EX. TSSON ATPSDA A98898 PPPP  THEN PRESS THE ENTER KEY		NOTWITHSTANDING THE INFORMATION CONTAINED HEREIN IS TO BE USED AGAINST THE INTERESTS OF TEAM MEMBER NATIONS WHICH ARE LOCATED IN AGAINST THE INTERESTS OF ANY OF THE AFFILIATED COMPANIES OR FINALLY OWNED SUBSIDIARIES.					
THE RETURN SCREEN SHOULD BE THE ROUTE CARD SYSTEM MENU  AFTER INITIAL LOGON, YOU MAY ACCESS THE MENU FROM A BLANK IMS SCREEN BY TYPING IN  ATPS000  THEN HIT ENTER							
OPTION 20: OPTION 20 OF THE MENU (OR ATPS020 FROM A BLANK SCREEN) WILL ALLOW YOU TO DISPLAY A LIST OF DISC PARTS FOR A GIVEN DRAWING NUMBER.  FOR QUICK ACCESS TO THIS INFORMATION YOU MAY ENTER THE FOLLOWING ON A BLANK IMS SCREEN:  ATPS020 <DRAWING_NUMBER> WHERE <DRAWING_NUMBER> IS THE PART II DRAWING THAT YOU WANT TO DISPLAY.  EX. ATPS020 9769SH245  THEN HIT ENTER							
OPTION 30: OPTION 30 OF THE MENU (OR ATP030 FROM A BLANK SCREEN) WILL ALLOW YOU TO ACCESS CHARACTERISTIC DATA FOR A SPECIFIED DISC PART NUMBER.  FOR QUICK ACCESS TO THIS INFORMATION YOU MAY ENTER THE FOLLOWING ON A BLANK IMS SCREEN:  ATPS030 <PART_Number> WHERE <PART_Number> IS THE DISC PART THAT YOU WANT TO DISPLAY  EX. ATPS030 9769-6-800  THEN HIT ENTER  IF YOU HAVE ANY QUESTIONS OR PROBLEMS, PLEASE CONTACT DRAFTING  A LISTING OF PEOPLE TO CONTACT FOR HELP OR INFORMATION ON THIS SYSTEM WILL BE MAINTAINED ON TIOLR AND CAN BE ACCESSED AS FOLLOWS:  T DA:RCS.USERDOC.CONTACTS							
1ST ISSUE 9-13-93, OFF K.H.G. 9-13-93, J.H.G. GCRN14288.	CHAS. FLUORANT 9-13-93 JH-G 9-14-93 GCRN14288 9-13-93	TEXAS INSTRUMENTS ATTLEBORO, MASSACHUSETTS 02703	KLIXON CONTROL PRODUCTS DIVISION	Q3 REV. E	Q4	M&I	P1
A			A	75755 SH.1	CODE IDENT NO. 82647		

3713 7646

DEVICE # 77/87PS  
PROJ. # 3423


TITLE

SWITCH RIVET

REV  
G

74916

74916



NOTES:

1. MATERIAL CERTIFICATION REQUIRED, TO BE KEPT BY SUPPLIER AND PROVIDED UPON TI'S REQUEST.
2. TAPERED HOLE IS ALLOWED.
3. PARTS MUST BE PACKAGED CLEAN AND DRY.

MARK UP FOR CHG.  
L.B.G.  
EACH 1/8 INCH  
S18/21/93  
CR442181

FOR REFERENCE ONLY  
CHECK LATEST REVISION  
BEFORE USE  
Parts Made To This Print Must Conform To  
ENG. STD. E9898 REV. E

Date JAN 7 1999

NOTICE: THIS PRINT SHOWS THE INFORMATION CONTAINED HEREIN IS TO BE USED AGAINST THE  
EXTERIOR OF TEXAS INSTRUMENTS INCORPORATED  
OR AGAINST THE INTERIOR OF ANY OF ITS AFFILIATED  
COMPANIES OR DIVISIONS OR SUBDIVISIONS.

74916-2	OBSOLETE PER CRM15079	
74916-1	CDA 280 BRASS	NONE
PART NO.	MATERIAL	FINISH

SUPERSEDES DWG. 74916 REV. "F", DATED 9-30-93

(U)	STRUCTURES ON FILE, REFER TO ELECTRONIC CHANGE NOTICE.	THIS IS A CAD DRAWING. THE GEOMETRY IN THE ASSOCIATED CAT COMPUTER FILE IS dimensionally ACCURATE. WHEN DRAWING IS BEING REVISED, THE GEOMETRY MUST BE UPDATED IN ALL VIEWS AND ON ALL SHEETS.	02-3 M5-3 013 D38# M21 P37 P35
DWY>	DRWY CHG. PLURANT 9-30-93 REVIEW JOHNNIE KNAK 9-30-93 APPROVED MATT SELLERS 9-30-93 APPROVED	TEXAS INSTRUMENTS ATTLEBORO, MASSACHUSETTS 02703	KELIXON CONTROL PRODUCTS DIVISION REV. NO. A DATE 1/93 74916


3713 7647

## TRANSFER PIN

REV.  
G

74078

74078



\*L\* LENGTH IS DETERMINED BY THE SUFFIX OF THE PART NUMBER IN THOUSANDS OF AN INCH. I.E.: PART NO. \*L\*  
 74078-155 .155  
 74078-210 .210

VENDOR WILL BE PREPARED TO FURNISH PINS .130 - .250 LONG.

## NOTES:

1. FINISHED PARTS TO BE SHIPPED, ISSUED AND STORED IN SEALED PLASTIC BAGS. SEALED PLASTIC BAGS TO CONTAIN 20,000 PINS (OR LESS FOR PARTIAL BAGS). BAGS MUST BE CLEARLY LABELED WITH THE PART NO. AND THE QUANTITY OF PARTS IDENTIFIED ON THE OUTSIDE OF EACH BAG.
2. MATERIAL CERTIFICATION REQUIRED WITH EACH SHIPMENT.

MATERIAL: L-3 GRADE STEATITE (DC-18E5) OR  
 L-3 GRADE STEATITE (DC-144E)

CURE PER SPEC. —— 50502-2

SHRINKAGE SPEC. —— 50501-1

FOR REFERENCE ONLY  
 CHECK LATEST REVISION  
 BEFORE USE  
 Parts Made To This Print Must Conform To  
 ENG. STD. E9898 REV. E

Date JAN 7 1999

NOTWITHSTANDING THE INFORMATION CONTAINED HEREIN IS TO BE USED AGAINST THE INTEREST OF SEVEN INSTRUMENTS Incorporated OR ANYONE ELSE SUBJECT TO ANY OF THE APPLICABLE COMMERCIAL OR MILITARY TRADE RESTRICTIONS.

THIS DWG. SUPERSIDES 74078 REV. "E" DATED 8-4-88

BY TOM DAIL 10-17-98

CH.

ENG. [Signature] H. H. H. 10-20-98

MAKEPEACE



TEXAS INSTRUMENTS  
 ATTLEBORO, MASSACHUSETTS 02703

KODAK  
 CONTROL PRODUCTS  
 DIVISION

DWG.  
 REV.

A

DWG. NO.

74078

CODE IDENT NO. 82647

3713 7648

13608-4

CLOSURE TAPE

REV. 13608-4

3" 60# TAPE  
COLOR NATURAL  
WATER ACTIVATED ADHESIVE  
NON-ASPHALTIC

FOR REFERENCE ONLY  
CHECK LATEST REVISION  
BEFORE USE  
Parts Made To This Print Must Conform To  
ENG. STD. E9898 REV. E

Date JAN 7 1999

NOTICE: THIS PRINT AND THE INFORMATION AND  
DRAWING CONTAINED IN IT ARE THE PROPERTY OF  
TEXAS INSTRUMENTS INCORPORATED. NO PART  
OF THIS DRAWING MAY BE COPIED OR REPRODUCED  
IN WHOLE OR IN PART, OR USED TO MAKE ANOTHER  
DRAWING OR WORK, WITHOUT THE WRITTEN CONSENT  
OF TEXAS INSTRUMENTS INCORPORATED.

PRINTED APR 27 1972

1

REV: DFTI	45° TS-1 W1-S172-1 VS W1-S V5-1 1241 Y-1	DATE 1999-01-07	P-1 P-1 P-1 P-1
BY BOARDMAN Z-15-72	TEXAS INSTRUMENTS INCORPORATED ATTLEBORO, MASS. U.S.A.	NIXON CONTROL PRODUCTS DIVISION	DATE 1999-01-07
CH:	A 2-2172	CODE IDENT NO.	A 13608-4
K&E	MADE IN U.S.A.	CODE IDENT NO.	B2647

3713 7649


DEV. # 52/57PS  
EROL # 3355

ROW SEPARATOR

D

74218

74218



44

3-10-90

MATERIAL: 200 LB. CORRUGATED CARDBOARD

FOR REFERENCE ONLY  
CHECK LATEST REVISION  
BEFORE USE  
Parts Made To This Print Must Conform To  
ENG. STD. E9898 REV. E  
Date JAN 7 1999  
  
NOTICE: THIS PRINT AND THE INFORMATION CONTAINED HEREIN IS TO BE USED AGAINST THE INTEREST OF TRADE INDIVIDUALS OR ORGANIZATIONS  
DETERMINE THE INTEGRITY OF ANY OF ITS AFFILIATES  
COMPANIES OR RELATED OWNERS OR SUBSIDIARIES.

THIS DWG. SUPERSEDES 74218 REV. "C" DATED 10-16-90

REV:					03	P1	P37-P12
BT	TOP DATE	10-16-90					
CH							
EXC.	4/1/91		TEXAS INSTRUMENTS		KLIXON		74218
MAKERSPACE			ATTLEBORO, MASSACHUSETTS 02703		GENERAL PRODUCTION		CORP. IDENT. NO. R2847

3713 7650

DEV. # 52/57PS  
PROJ. # 3365

TITLE

CARTON

REV.

D

74219

74219

CONSTRUCTION TO BE RSC FROM 275 LB. CORRUGATED CARDBOARD  
WITH TAPE CLOSURE, TAPE OTHER THAN ASPHALTIC TYPE.

INSIDE DIMENSIONS

LENGTH 22 9/16" MIN.  
WIDTH 10 9/16" MIN.  
HEIGHT 6 5/16" MIN.

OUTSIDE DIMENSIONS

LENGTH 23" MAX.  
WIDTH 11" MAX.  
HEIGHT 7 1/2" MAX.

FOR REFERENCE ONLY  
CHECK LATEST REVISION  
BEFORE USE  
Parts Made To This Print Must Conform To  
ENG. STD. E9898 REV. E

Date JAN 7 1999

NOTES: THIS PRINT CONTAINS INFORMATION CON-  
CERNING SPACERS TO BE USED ALONG WITH THE  
STRUCTURE OF THESE INSTRUMENTS WHICH APPLICATES  
TO DESIGN TIME REQUIREMENTS OF ASME B8.1 APPENDIX  
D. THIS PRINT IS NOT APPLICABLE FOR SPACERS WHICH  
DO NOT MEET THE REQUIREMENTS OF ASME B8.1 APPENDIX  
D.

THIS DMO. SUPERSEDES 74219 REV. "C" DATED 10-16-90

REVIS

03/01

1997-31P/2

BY

TECH-SHRL 10-14-90

CH.

RHS, w/lin. Hmml 4/2/91

RELEASER:



TEXAS INSTRUMENTS  
ATTLEBORO, MASSACHUSETTS 02700

KODAK  
PRINTING PRODUCTS  
DIVISION

DMO  
REV.  
A

74219

PRINTED IN U.S.A. 8/94

3713 7651

**EA02-025**

**FORD**

**10/27/03**


**BOOK 27**

**DRAWING**

## REVISIONS


ZONE	LTR	52/57PS	DESCRIPTION	PROJ. #	DATE	A
D			REDRAWN WITH GENERAL REVISIONS CR. 155858, CF	3355	3-19-91	X

10 7/16



SEPARATOR "A"


22 7/16



SEPARATOR "B"

FOR REFERENCE ONLY  
CHECK LATEST REVISION  
BEFORE USE  
Parts Made To This Print Must Conform To  
ENG. STD. E9898 REV. E  
Date JAN 7 1999

## SEPARATOR ASSEMBLY DESCRIPTION


7 x 17 CELLS WITH AIR SPACE  
(171 PARTITIONS)

27317-1	18 SEPARATOR A'S & B'S SEPARATOR B'S	.031 CHIPBOARD
PART NO	DESCRIPTION	MATERIAL

UNLESS OTHERWISE SPECIFIED DIMENSIONS ARE IN INCHES	BY CHAS FLEURANT	DATE 3-19-91	101301 P37
TOLERANCE ON FRACTIONS DECIMALS ANGLES	CH.		
ENG.	1	46/61	TITLE

TEXAS INSTRUMENTS  
ATTLEBORO, MASSACHUSETTS 02703KLD  
6  
CONTROL F  
DIVIS

B-3	D	DELETED ITEM 6 27317-2 DEVICE SEPARATOR DELETED BALLOON #4 BALLOON #4 WAS #6 CR.153858, CF	3-19-91	J.R.
-----	---	---	---------	------



FOR REFERENCE ONLY  
CHECK LATEST REVISION  
BEFORE USE  
Parts Made To This Print Must Conform To  
ENG. STD. E9898 REV. E

Date JAN 7 1999

NOTICE: THIS PRINT NOR THE INFORMATION CONTAINED HEREIN IS TO BE USED AGAINST THE INTEREST OF TEXAS INSTRUMENTS INCORPORATED OR QUANTITY THE INTERESTS OF ANY OF ITS AFFILIATED COMPANIES OR WHOLLY OWNED SUBSIDIARIES.

AS REFD	5	13608-4	TAPE
2	4	27317-1	DEVICE SEPARATOR
3	3	74218-1	ROW SEPARATOR
	1	74219-1	CARTON
		1	ASSEMBLY
QUANTITY		ITEM NO	DESCRIPTION
	-1		
		DASH NO	

UNLESS OTHERWISE SPECIFIED DIMENSIONS ARE IN INCHES	BY DATE CH.	11-2-98	TEXAS INSTRUMENTS ATTLEBORO, MASSACHUSETTS 02703	TITLE CARTON ASSEMBLY
TOLERANCE ON FRACTIONS DECIMALS ANGLES	ENG. Stan Homo)			
MATERIAL			KLIXON © CONTROL PRODUCTS DIVISION	

SPEED Control De-Aer Switch

8713 7691

\*\*\*\*\*  
\* Note printed by TBAZIL on 8 Mar 1999 at 08:53:19 \*  
\*\*\*\*\*

From: MREESSE --DRBN005  
To: SREIMERS--DRBN007  
cc: TBAZIL --DRBN005  
DSYLVEST--DRBN006

Date and time 03/05/99 14:27:15  
LSMITH9 --DRBN005  
WLIVINGS--DRBN005

FROM: M. P. REESE USAET(UTC -05:00)  
Subject: Brake Dead Switch Re-location - DESIGN ORDER RESULTS

STEVE, THERE IS A PLACE FOR A SWITCH TO BE LOCATED ON THE 1992/1993/1994 TOWN CAR BRAKE PEDAL ASSEMBLY. IT IS THE "KEYHOLE" IN THE PEDAL ASSEMBLY'S BRACKET, WORKING WITH THE FLAT SURFACE ON THE PLASTIC ADAPTER (ON THE PEDAL ASSEMBLY'S ARM). THESE FEATURES WERE USED TO MOUNT THE VALVE ASSEMBLY - SPEED CONTROL (-9C717-) AND THE CLIP - SPEED CONTROL VACUUM VALVE (-9C966-) ON OTHER MODEL YEAR/CARLINE PANTHER CARS. SWITCH AND WIRING CLEARANCE TO STEERING COLUMN CRUSH ZONE WILL DEPEND ON DIMENSIONS OF SWITCH TO BE USED, AND WIRING ROUTING. (THE 1999 MODEL SWITCH, AT THIS LOCATION, DOES INTERFERE WITH THE CRUSH ZONE.) A DIFFERENT/NEW SWITCH WILL BE NEEDED.

IT IS TIME FOR THE CHECK TO VERIFY THESE RESULTS, THAT I REQUESTED DURING THE 1999 MAR 03 MEETING. THE CHECK IS NEEDED, BECAUSE REFERENCES (DESIGN LAYOUTS, WERS, DOCHMAN, ETC.) THAT WE HAVE AVAILABLE (AND RECOVERED FROM ARCHIVES) ARE NOT PERFECT. I REQUEST REVIEW BY THE APPROPRIATE DESIGN AND RELEASE (SWITCH AND WIRING) ENGINEER. PLEASE RELAY THIS REQUEST.

IF THIS SOLUTION DOES NOT HOLD UP TO THE CHECK, THEN WE WILL NOT BE ABLE TO ADD A SWITCH ON THE BRAKE PEDAL AND BRACKET ASSEMBLY.

Regards,

M. P. Reese 313-317-7142 (313-621-6675 FAX)  
OPD LVC - Brakes Mail Drop 1229 BUILDING 2 24M31  
\*\*\* Forwarding note from MREESSE --DRBN005 03/01/99 12:24 \*\*\*  
To: SREIMERS--DRBN007 FPORTER --DRBN007  
cc: TBAZIL --DRBN005 JNEME --DRBN005

FROM: M. P. REESE USAET(UTC -05:00)  
Subject: Brake Dead Switch Re-location - DESIGN ORDER

STEVE, THE RESULT OF THE MEETING THIS MORNING IS THAT WE WILL HAVE A FEASIBLE, CLEAR SOLUTION (FOR SWITCH MOUNTED TO BRAKE PEDAL ASSEMBLY, ON 1992/1993/1994 TOWN CAR) BY NOON FRIDAY 1999 MAR 05.

IN MAKING THIS SOLUTION, WE ARE BEING VERY CAREFUL SO THAT WE DO NOT MAKE SOMETHING ELSE WORSE. THE HISTORY IS VAGUE.  
ANY GOOD NEWS, ABOUT OTHER SOLUTIONS?

Regards,

M. P. Reese 313-317-7142 (313-621-6675 FAX)  
OPD LVC - Brakes Mail Drop 1229 BUILDING 2 24M31  
\*\*\* Forwarding note from SREIMERS--DRBN007 02/27/99 16:19 \*\*\*  
To: MREESSE --DRBN005 FPORTER --DRBN007 Porter, F.J.  
cc:

FROM: Steve Reimers USAET(UTC -05:00)  
Subject: Brake Dead Switch Re-location  
Marty, Please call Fred Porter with the update from your meeting. I will be at MPG most of the day.

Steve Reimers  
AVT Chassis E/E System Applications  
39-03286 SREIMERS sreimers@ford.com  
\*\*\* Forwarding note from MREESSE --DRBN005 02/27/99 16:13 \*\*\*  
To: SREIMERS--DRBN007  
CC: TBAZIL --DRBN005  
LSMITH9 --DRBN005

FROM: M. P. REESE USAET(UTC -05:00)  
Subject: Brake Deac Switch Re-location

I AM OPTIMISTIC ABOUT ABILITY TO PACKAGE THE CURRENT PRODUCTION SWITCH ON THE BRAKE PEDAL AND BRACKET ASSEMBLY IN 1992/1993/1994 TOWN CARS. I WILL KNOW MORE (BUT NOT EVERYTHING) ABOUT TIMING AT THE CONCLUSION OF A 9:00 AM MEETING WITH CHASSIS DESIGNERS. GENERAL OPTIMISM COMES FROM THE BRAKE PEDAL AND BRACKET ASSEMBLY DRAWINGS; THEY (SO FAR) SHOW EVOLUTION OVER THE MODEL YEARS, AND INVOLVE ONLY ONE SUPPLIER.

WERS AND DOCMAN ARE NOT IN GOOD SHAPE FOR THIS 1992/1993/1994 MODEL TASK. THAT SLOWS THE ADVANCE. FACILITATES AMBUSH.

ALWAYS, I MUST CONSIDER EFFECTS ON FMVSS 105. VEHICLE TEST, BRAKE SYSTEM.

I INTEND TO CALL YOU, ABOUT NOON ON MONDAY 1999 MAR 01.

Regards,  
M. P. Reese 313-317-7142 (313-621-6673 FAX)  
OPD LVC - Brakes Mail Drop 1229 BUILDING 2 24M31  
\*\*\* Forwarding note from SREIMERS--DRBN007 02/25/99 15:39 \*\*\*  
To: MREESSE --DRBN005

FROM: Steve Reimers USAET(UTC -05:00)

Subject: Brake Deac Switch Re-location  
Marty, I was asked what the status of this design work. Have you got any good words I can pass on to my manager? I would like to give Jack Paskus a sense of where we are on this task, what the next step(s) are and when they are targeted to complete. My meeting with Paskus is Monday at 3:30.  
thanks,

Steve Reimers building 5 3C043  
AVT Chassis E/E System Applications mail drop 5011  
39-03286 SREIMERS sreimers@ford.com fax 39-03286 ;>

3713 7693

\*\*\*\*\*  
\* Note printed by MREHSE on 3 May 1999 at 15:07:49 \*  
\*\*\*\*\*

From: MREHSE --DRBN005  
To: SREIMERS--DRBN007  
cc: TBAZIL --DRBN005

Date and time 05/03/99 13:18:30

JNEME --DRBN005

FROM: M. P. REESE  
Subject: Prop Valve Service Part

USAET(UTC -04:00)

STEVE, FCSD DAVE SMITH HAS REPLIED. (I WILL BUY SERVICE PARTS, ANYWAY; ONE PRESSURE SWITCH, AND ONE PROPORTIONING VALVE.)

Regards,

M. P. Reese 313-317-7142 (313-621-6675 FAX)  
ODD LVC - Brakes Mail Drop 1229 BUILDING 2 24M31  
\*\*\* Forwarding note from DSMITH22--DRBN006 05/03/99 12:12 \*\*\*  
To: MREHSE --DRBN005  
cc: TBAZIL --DRBN006

FROM: Dave Smith

USAET(UTC -04:00)

Subject: Prop Valve Service Part

Marty, the prop valves I looked at all come with the brake pressure switch. Brake pressure switch is available separately but prop valve cannot be purchased without the brake pressure switch.  
I am concurring with Tom.

Best Regards,

Dave Smith - FCSD North American Parts Analysis - Car Brakes  
Room 1103B NPDC- Livonia, MI.  
Ph. 734-523-5471 Fax 458-0059 - email: dsmith22@ford.com  
\*\*\* Forwarding note from MREHSE --DRBN005 05/03/99 10:41 \*\*\*  
To: DSMITH22--DRBN006 SREIMERS--DRBN007  
cc: TBAZIL --DRBN005 JNEME --DRBN005

FROM: M. P. REESE

USAET(UTC -04:00)

Subject: Prop Valve Service Part

DAVE, HELP, PLEASE. I ASK THAT YOU CHECK SERVICE INFORMATION, AND CONFIRM THE REPLY THAT TOM BAZIL FORWARDED TO STEVE REIMERS.  
(I THINK THAT A SERVICE USAGE CHART (FOR PROPORTIONING VALVE -2B091-, AND FOR BRAKE PRESSURE SWITCH -9F924-; FOR 1992 THROUGH 1994 MODEL TOWN CAR/CROWN VICTORIA/GRAND MARQUIS) WOULD BE A HELPFUL PART OF THE ANSWER.)  
STEVE REIMERS' MAIN QUESTION IS CONTAINED IN HIS NOTE, FORWARDED HERE.

STEVE, I AM BUYING A BRAKE PRESSURE SWITCH FOR A 1992 TOWN CAR AT VILLAGE FORD. VILLAGE FORD ADVISES THAT A F2VY-9F924-A WILL BE AVAILABLE FOR PICKUP TUESDAY. PRICE IS ABOUT \$13.00. I THINK THAT THIS ANSWERS PART OF YOUR QUESTION. IF MORE PARTS ACQUIRED FROM SERVICE WILL HELP US, LET ME KNOW WHAT YOU WOULD LIKE TO SEE AND I WILL TRY.

Regards,

M. P. Reese 313-317-7142 (313-621-6675 FAX)  
ODD LVC - Brakes Mail Drop 1229 BUILDING 2 24M31  
\*\*\* Forwarding note from TBAZIL --DRBN005 04/30/99 18:40 \*\*\*  
To: SREIMERS--DRBN007  
cc: MREHSE --DRBN005 TBAZIL --DRBN005

FROM: Tom Bazil

USAET(UTC -04:00)

3713 7694

**Subject:** Prop Valve Service Part  
Prop valves F2VC-2B091-BA and F2AZ-2B091-BA include the switch and indicate service parts F2VY-2B091-B and F2AZ-2B091-BA as respective service numbers.

F2VC-2B091-BA shows component switch F2VC-9F924-BA which has its own service number F2VY-9F924-B. The valve block F2VC-2B382-AA/AB does not show that it is serviceable separately in the WERS screens.

Does this answer? If not, Marty Reese has volunteered to try to buy parts at a dealer? Please respond to Marty.

Have a good day!


---

Thomas E. Basil (313) 59-47547 Lrg & Lux Car OPO Brake/Veh Supv  
Drop 1229-LVC, Cuba 24-H36, fax 52-16675, pager (888) 375-6449  
\*\*\* Forwarding note from SREIMERS--DRBN007 04/29/99 10:09 \*\*\*  
To: TBASIL --DRBN005

**FROM:** Steve Reimers **TO:** USADET(UTC -04:00)  
**Subject:** Prop Valve Service Part  
Tom, Does the Prop valve service part include the Brake pressure switch for the 1992 and 1993 Town Car and Crown Vic and Grand Marquis?


Steve Reimers building 5 3E008  
RVT Chassis E/E System Applications mail drop 5011  
39-03186 SREIMERS sreimers@ford.com fax 39-04145 r>

3713 7695




3713 7896

3719 7697



8719 7898



**1992 BRAKE CONTROL VALVES**

CARLINE	BRAKE SYSTEM	PROPORTIONING VALVE -2B891-	PERFORMANCE	JUNCTION BLOCK -2C320-	IN	OUT
Crown Victoria/ Grand Marquis	ABS/TC	F1VC-AD	500/.43		M10 M12	M10 M12
	w/o ABS/TC			F2AC-BA	M10	M10 M10
Town Car	ABS ABS/TC	F2VC-BA F2VY-2A01-B	500/.43		M10 M12	M10 M12
	Limo w/o ABS/TC	F2VC-CB	500/.43		M10 M12	M10 M10 M12 M12


F2W-2B382-44  
 P2VC-11 - AD  
 P2VC-7F2A-88 — F2VY-9F924-B

8713789

**1993 BRAKE CONTROL VALVES**

CARLINE	Brake System	PROPORTIONING VALVE -2B681-	PERFORMANCE	JUNCTION BLOCK -2C520-	IN	OUT
Crown Victoria/ Grand Marquis	ABS/TC w/o SPD CNTRL	F2AC-AA	500/43		M10 M12	M10 M12
	ABS/TC w/SPD CNTNL	F2AC-BA <del>F2AC-2B681-B</del>	500/43		M10 M12	M10 M12
	w/o SPD CNTRL			F2AC-BB	M10	M10 M10
	w/o ABS/TC w/SPD CNTNL			F2AC-CG	M10	M10 M10
Town Car	ABS ABS/TC		500/43		M10 M12	M10 M12
	Limo w/o ABS/TC	F1VC-AA	300/27		M10 M12	M10 M10 M12 M12

F2AC-95924-AA F2AC-2C520-CC




**1993 ANTHLOCK/TC FRAME CARS**

CARLINE	HYDRAULIC CONTROL UNIT	ECU BRACKET	ECU BRACKET ATTACHMENT SCREW	ELECTRONIC CONTROL UNIT	ECU BRACKET	ECU ATTACHMENT SCREWS	POWER RELAY	ECU BRACKET TO FRAME TIE-BOLTS
Town Car	F1VC-2C204-AB	F1VC-2C204-AB	M00101-500	F1VC-2C204-AB	F1VC-2C204-AB	M00101-500	F002-2C204-AD	M00203-5104

**1993 ANTH-LOCK SENSORS**


CARLINE	FRONT			REAR		
	SENSOR ASSEMBLY (NO COLOR CODE)	ATTACHMENT SCREW/CLIP	ATTACHMENT SCREW/NUT/SCREW	SENSOR ASSEMBLY (NO COLOR CODE)	ATTACHMENT SCREW/CLIP	ATTACHMENT SCREW/NUT/SCREW
Town Car	F1VC-2C204-AB	CB60-2C204-AB M00101-500 M00101-500 CB6401	M00203-5104 M00101-500	F1VC-2C204-AB	ELC-2C210-AB R004725-5100	M00203-5104 M002101-500
Crown Victoria/ Grand Marquis	F1VC-2C204-AB	CB60-2C204-AB M00101-500 M00101-500 CB6401	M00203-5104 M00101-500	F1VC-2C204-AB	ELC-2C210-AB R004725-5100	M00203-5104 M00203-5104

3713 7700




3713 7701

Town Car, Crown Victoria, and Grand Marquis  
Days from Sale to Engine off or Unknown




3713 7702

Town Car, Crown Vic, and Grand Marquis  
Underhood or Unknown Only



3713 7703

# Contributing Factors



3719704

1. Connector Seal
2. Kapton Life
3. Continuous Power
4. Switch Orientation
5. Current Capability
6. Grounded Hex-Port
7. Plastic Parameters

# Potential Actions

	Improve connector seal	Re-align connector	Re-locate switch to brake pedal	Improve Kapton diaphragm	Insert in-line fuse with switch	Add power off switch	Re-locate switch to ground side	Re-locate switch to RUN circuit	Insulate switch from prop valve	Use flame retardant plastic
Connector Seal	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>							
Kapton Lite			<input checked="" type="checkbox"/>	<input type="checkbox"/>						
Continuous Power					<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Switch Orientation		<input type="checkbox"/>	<input checked="" type="checkbox"/>						<input type="checkbox"/>	
Current Capability					<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>	
Grounded Hex-port			<input checked="" type="checkbox"/>				<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>	
Plastic Parameters										<input type="checkbox"/>

■ = fixed  
 = improved



US Department  
of Transportation

National Highway  
Traffic Safety  
Administration

DEC 1 1998

P. J. BOHANNON

11/17/98

U.S.D.O.T.

400 Seventh Street, S.W.  
Washington, D.C. 20590

DISPOSE of Copies (Black Stamped) by:	2018
RETAIN Record Copy (Red Stamped) Thru:	
Schedule Number:	

**CERTIFIED MAIL**  
**RETURN RECEIPT REQUESTED**

L.W. Camp, Director  
Automotive Safety and Engineering Standards Office  
Ford Motor Company  
330 Town Center Drive  
Dearborn, MI 48126

NSA-12jfa  
PE98-055

Dear Mr. Camp:

This letter is to revise the due date for the November 24, 1998 information request letter  
regarding investigation PE98-055. The correct due date is January 15, 1999.

Sincerely,

Thomas Z. Cooper, Chief  
Vehicle Integrity Division  
Office of Defects Investigation



AUTO SAFETY HOTLINE  
800/424-9393  
Wash. D.C. Area (202) 366-0123

3719 7706



U.S. Department  
of Transportation  
National Highway  
Traffic Safety  
Administration

F. J. BOHAN--

NJV 24 IS98

1 NOV 03 5:10 PM

**CERTIFIED MAIL**  
**RETURN RECEIPT REQUESTED**

1100  
U.S.  
GOVERNMENT  
PRINTING  
OFFICE  
1998

400 Seventh Street, S.W.  
Washington, D.C. 20590

DISPOSE of Copies (Black Stamped) by:	2018
RETAIN Record Copy (Red Stamped) Thru:	
Schedule Number:	27.03

L.W. Camp, Director  
Automotive Safety and Engineering Standards Office  
Ford Motor Company  
330 Town Center Drive  
Dearborn, MI 48126

NSA-12jfa  
PE98-055

Dear Mr. Camp:

This letter is to advise you that the Office of Defects Investigation (ODI) of the National Highway Traffic Safety Administration (NHTSA) is conducting a Preliminary Evaluation concerning engine compartment fires in certain Lincoln Town Car vehicles manufactured by the Ford Motor Company.

This office has received 21 reports of engine compartment fires in 1992 and 1993 Lincoln Town Cars. The fires in these vehicles are reported to have started while the vehicles were parked and the engines not running. Ten of the reports indicate a fire at the left front fender wheel well area (see photograph, page 6), two indicate a fire at the master cylinder, which is adjacent to the left front fender wheel well area, and the remaining nine reports indicate a fire in the engine compartment. Additionally, five of the reports indicate the vehicle owner's carport, garage, or home, was also damage as a result of the fire.

A copy of each of the reports is enclosed for your information.

Unless otherwise stated in the text, the following definitions apply to this information request:

- **Subject vehicles:** all 1992 and 1993 Lincoln Town Car vehicles.
- **Ford:** Ford Motor Company, all of its past and present officers, employees, whether assigned to its principal offices or to any of its field or other locations, including all of its divisions, subsidiaries (whether or not incorporated) and affiliated enterprises and all of their headquarters, regional, zone and other offices and their employees, and all agents, contractors, consultants, attorneys and law firms and other persons engaged by or under the control of Ford Motor Company (including all business units and persons previously referred to) who are or were involved in any way with (a) design, analysis, modification or production; (b) testing, assessment or evaluation; or (c) record-keeping, claims, or lawsuits relating to the alleged defect in the subject vehicles.



AUTO SAFETY HOTLINE  
(800) 424-8383  
Wash. D.C. Area (202) 368-0123

3713 7707

- Alleged defect: all under hood fires, or other thermal anomalies, from any source or origin, of any description, level, degree, or magnitude, occurring in the left, or drivers side, of the engine compartment. This would include fires in the area of the left front wheel, or left front fender.
- Documents: in the broadest sense of the word, shall mean all written, printed, typed, recorded or graphic matter whatsoever, however produced or reproduced, of every kind, nature, and description, including but not limited to, papers, records, letters, correspondence, memoranda, communications, electronic mail messages (existing in hard copy and/or in electronic storage), faxes, notes, annotations, working papers, drafts, minutes, records, resolutions, books, pleadings, response to discovery, administrative and judicial filings, all transcripts and other recordings of any kind, affidavits, materials and things produced in discovery, statements, summaries, interviews, opinions, reports, newspaper articles, studies, analysis, evaluations, interpretations, applications, agreements, jottings, agendas, bulletins, notices, announcements, instructions, designs, specifications, blueprints, as-builts, manuals, brochures, publications, schedules, journals, statistical data, lists, tabulations, computer printouts, data processing input, data in storage, and data output, microfilm, microfiche, data from optical scanning or recording, photographs, tangible things, and all records kept by electronic, photographic, or mechanical means, any drafts or revisions pertaining to any of the foregoing, and all other things similar to any of the foregoing however denominated and any other data compilations from which information can be obtained, translated if necessary, into reasonably usable form and any other documents.

In order for my staff to evaluate the alleged defect, certain information is required. Pursuant to 49 U.S.C. § 30166, please provide numbered responses to the following questions. Please repeat each question verbatim before the response. If you have previously furnished ODI with information that is responsive to any item(s) in this request, you need not resubmit that information, but your response must cross-reference (by date of response and question number) the earlier submission. If Ford cannot answer any specific question, please state the reason why it is unable to do so. If you claim that any information or material responsive to the following items need not be divulged to the NHTSA because it is privileged, or the work product of an attorney, state the nature of that information or material and identify any document in which it is found by, date, subject or title, name and position of person from and person to whom it was sent, and name and position of any other recipient. You must also describe any privilege that you claim, and explain why you believe it applies.

1. State the total number of subject vehicles sold in the United States by model year.
2. State the number incidents, known to Ford, in which the alleged defect has been reported to have occurred in the subject vehicles. Furnish copies of all documents, from any and all sources, including documents which may not originally have been submitted to Ford, which

are in Ford's possession or control, or of which it is otherwise aware, that pertain, in any way, to any of these incidents. This should include, but is not limited to, all documents possessed by Ford, or of which it is otherwise aware, pertaining to the reports included with this letter. Furnish all documents whether or not Ford has verified the validity of each document. For each incident in this response please provide the vehicle owner's name, address, and telephone number; and identify all vehicles by vehicle identification number, model year, date of manufacture, date of retail sale, date of incident, mileage at the time of the incident, and problem description. For all incidents involving lawsuits please identify the caption, court, docket number, and filing date of each lawsuit and a copy of the complaint document initiating the lawsuit. Sort all incidents by cause and area or component of origin.

- ③ State the total number vehicles sold in the United States by model name and model year that have engine compartment configurations (i.e., components and component location, wiring harnesses and harness location) the same as the subject vehicles. Provide a response to question number two for all vehicles identified in your answer to this question.
4. State the number of all warranty claims, including extended warranty claims, and "goodwill," field or zone adjustments received by Ford that relate to the alleged defect in the subject vehicles by calendar year, calendar month, and problem identification. Identify all owners by name, address, and telephone number, and all vehicles by vehicle identification number, model name, model year, date of manufacture, date of retail sale, date of incident, mileage at the time of the incident, and problem description.
5. Identify all electrical circuits by name, number, and wire color, located in the left side of the engine compartment that are, or remain, energized by the battery when the ignition key is in the off position. For all circuits identified, provide a schematic drawing which identifies the harness(es) in which they reside, the harness location(s), and the components to which power is supplied.
- ⑥ Identify and describe all inspections, tests or other analyses conducted by Ford, its contractors, suppliers, or by any other entities, regarding the inspection of any subject vehicles that relate to the alleged defect, to date. Identify, by name and address, the entity that conducted each such test or analysis. Furnish copies of all reports, surveys, notes, tables, graphs or other documents that pertain to each such test or analysis. State when each test or analysis was initiated and concluded, or whether it is still in progress. Include in your response a description of a worst case scenario.
7. If Ford has issued any bulletins, advisories, or other communications to distributors, retailers, consumers, or any other entity pertaining to the alleged defect in the subject vehicles, provide a copy of each such document. If no such documents have been issued, so state.

8. Identify and describe all significant modifications or changes made by or on behalf of Ford in the manufacture, design, or material composition of all components in the subject vehicles that may relate to the alleged defect. The following information must be included for each such modification or change:
  - a. the approximate date on which the modification or change was incorporated into production;
  - b. a description of the modification or change;
  - c. the reason for the modification or change; and
  - d. whether the modified or changed components can be interchanged with earlier production components.
9. Provide Ford's assessment of the alleged defect in the subject vehicles, including:
  - a. all causal or contributory factors;
  - b. the failure mode;
  - c. the risk to occupant safety it poses; and
  - d. whether there are any circumstances that would provide the vehicle owner or others with warning of its existence.


Your response to this letter, in duplicate, must be submitted to this office by January 6, 1999. Please include in your response the identification codes referenced on page 1 of this letter. If you find that you are unable to provide all of the information requested within the time allotted, you must request an extension from Mr. Thomas Z. Cooper not later than five days from the due date. If you are unable to provide all of the information requested by the original deadline, you must submit a partial response by that date with whatever information you have available, even if you have received an extension.

This letter is being sent to your company pursuant to 49 U.S.C. § 30166, which authorizes NHTSA to conduct any investigation that may be necessary to enforce Chapter 301 of Title 49, U.S. Code. Your failure to respond promptly and fully to this letter could subject Ford to civil penalties pursuant to 49 U.S.C. § 30163 or lead to an action for injunctive relief pursuant to 49 U.S.C. § 30163.

If you consider any portion of your response to be confidential information, include that material in a separate enclosure marked "CONFIDENTIAL." In addition, you must submit a copy of all such material to the Office of Chief Counsel (NCC-30), National Highway Traffic Safety Administration, 400 Seventh Street, SW, Washington, DC 20590, and comply with all other requirements for the submission of confidential business information stated in 49 CFR Part 512.

If you have any technical questions concerning this matter, please contact Mr. John Abbott or my staff at (202) 366-5221.

Sincerely,



Thomas Z. Cooper

Thomas Z. Cooper, Chief  
Vehicle Integrity Division  
Office of Defects Investigation

Enclosures: 12 VOQ's: 813241, 824016, 808265, 821667, 979634, 521137, 804418, 541041  
820316, 536206, 819621, 823462; 5 fire department reports; 2 internet reports; and  
2 fire investigator reports

NHTSA:NSA:ODI  
NSA-12:JABBOTT:drd:6-5221:11/17/98  
cc:  
NSA-01  
NSA-12/Subj/Chron/  
Document: I:/ABBOTT/Towncar.IR

3713 7711

PE98-055  
page 6

1992 Lincoln Town Car (1LNLM81W2NY [REDACTED])



8713 7712

11/24/98

PE Opening Reports (PE98-055)  
1992 Lincoln Town Car Engine Fires

NO.	Source	ST	VIN	M/Y
1	813241	FL	1LNLM82W5NY	92
2	B24018	TX	1LNLM81W2NY	92
3	BD8265	FL	1LNLM82W7NY	92
4	821687	LA	1LNLM81W9NY	92
5	979634	TX	1LNLM82W5NY	92
6	521137	OK	1LNLM81W2NY	92
7	F.D.R.	GA	1LNLM82W3NY	92
8	804418	OH	1LNLM81W8NY	92
9	541041	FL	1LNLM81W3NY	92
10	F.D.R.	FL	1LNLM81W2NY	92
11	F.D.R.	FL	1LNLM82W7NY	92
12	A805260	FL	1LNLM81W0NY	92
13	820318	FL	1LNLM81W3NY	92
14	IVNet	FL	1LNLM81W8NY	92
15	536206	MS	1LNLM83W9NY	92
16	819621	LA	1LNLM82W5NY	92
17	IVNet	FL	1LNLM82W4NY	92
18	F.D.R.	GA	1LNLM82W1NY	92
19	A804221	FL	1LNLM81WP2Y	93
20	823462	MS	1LNLM81W5PY	93
21	F.D.R.	FL	1LNLM81WXPY	93

3719 7718

DEC 10 1998 RECD BY MSSP 1000 AM 212... 212 BLD 4459 10 VEH/4

Tony, Jr.

Page: 01

CGIS DETAIL REPORT

12/07/98 18:14:14

CGIS Report Number: WJIAAR135 Program Type: 0  
Report Source: MSS - PCSO - QSPS

Orig Rpt #: 225951-98  
Report Date: 10/09/1998

JOC

----- REPORT SUMMARY -----

VEHICLE: 1993 TOWN CAR, SIGN , SEDAN  
Engine: 4.6L ROMEO BASE EFT  
Operating Enviro: Vehicle Use:

VIN : 1LWLM82WDPT  
Odometer: 51,500 MILES  
WCC : SD03  
Rsp. Act:

Symptom: 3 01 0 00 CHASSIS  
OTHER (CODE NOT AVAILABLE)

SERVICE BRAKE SYSTEM  
OTHER (CODE NOT AVAILABLE)

Additional Symptom:

Other Veh: With Concern: Severity Rating - Customer: Engineering:

Causal Component: 28264

Feature:

SWITCH BRAKES WRN L

Causal Factor:

Loc:

Causal Condition:

Photo:

Images: 0

Component Test Status:

Return Loc:

Vehicle Fixed?: YES Customer satisfied?: Repair Effectiveness (%): 100

----- COMBINE IT'S -----

---TYPE--- COMMENT TEXT

CONCER INITIALLY THE CUSTOMERS CONCERN WAS THAT THE VEHICLE WOULD NOT COME OUT OF PARK. WHILE IN THE DEALERSHIP, AN UNDERHOOD FIRE STARTED, CAUSED BY A LEAKING BRAKE FLUID THROUGH THE SWITCH INTO THE CONNECTOR. REPLACED THE SPEED CONTROL SWITCH AND CONNECTOR. REPLACED THE STOP LAMP SWITCH FOR THE ORIGINAL CUSTOMERS CONCERN. PER TECHNICIAN, THIS IS THE THIRD UNIT THAT HAD AN UNDERHOOD FIRE THAT APPEARED TO ORIGINATE FROM THIS AREA. THE OTHER TWO WERE TOO DAMAGED TO DETERMINE THE SPECIFIC LOCATION OF THE POINT OF THE ORIGIN. THE SWITCH AND CONNECTOR ARE PRESENTLY IN MY POSSESSION IN THE MEMPHIS REGIONAL OFFICE.

AUDIT 10/14/1998 09:56AM BRENDA WENDEL MSS - PCSO - QSPS

DEALER ID 68523 CHANGED TO 12096 BY BWENDEL

----- CONCERN DETAILS -----

----- DIAGNOSTIC INFORMATION -----  
Symp. Verif?: Ease of Diagnosis: Level of Assistance:  
Comp. Timing: Base Timing MIL light on? :  
Test Stand: Road Test ID Number:  
Prior Repair Attempts: Repair Prior to Call: NO  
DNICs USED: KOREC: CB:  
KORE: CB:  
Equipment/Procedure Used Effective? Equipment/Procedure Used Effective?

----- SERVICE ACTIONS -----

Repair Type	Component Number	Number Type	Description	Causal Comp.
RPT	28264	SERVICE	SWITCH BRAKES WRN L	YES

----- VEHICLE DETAILS -----

Vehicle Build Date: 09/10/1992 Warranty Start Date: 02/08/1993  
Date of Sale: 02/08/1993 Selling Dir. (Met, Dlr, Sub): 12096  
Dealer Special Order: Gross Vehicle Weight:  
LH/RH Drive:

----- ENGINE -----  
Engine: 4.6L ROMEO BASE EFT Tag: 3G 812 AA  
Bld Dt: Calib: 318JR10 A Serial #: W

REDACTED

3713 7714M

DEC 10 '98 15:21 FR HESCU (MMW BHD) 310 004 4450 TO USWU 5:02 00

Page: 02

CQIS DETAIL REPORT

12/07/98 18:14:14

CQIS Report Number: WJIAAL35 Program Type: Q Orig Rpt #: 225951-98  
Report Source: MSS - FCSD - QSES Report Date: 10/09/1998

--- TRANSMISSION ---  
Trans: ADD-S 4SP ELEC O/D Part #: \_\_\_\_\_  
Bld Dt: \_\_\_\_\_ Serial #: \_\_\_\_\_  
Model: \_\_\_\_\_ Plt: \_\_\_\_\_ Shift: \_\_\_\_\_

Axle: 8.8 3.08 CONVENTIONAL Id Tag Code: \_\_\_\_\_ Bld Dt: \_\_\_\_\_  
Serial #: \_\_\_\_\_ Plt: \_\_\_\_\_

Tire : P215/70R15 95H Brand: \_\_\_\_\_  
Radio : ELITE PREMIUM AM/FM STRO/CSTZ A/C : ATC AIR CONDITIONER  
Paint : BLUE EXTERIOR PAINT FAMILY \_\_\_\_\_ AQUAMARINE FROST C/C

----- AFTER MARKET MODIFICATIONS -----

NO AFTER MARKET MODIFICATIONS DATA AVAILABLE FOR THIS VEHICLE

----- REPORT ORIGINATOR - REPAIR FACILITY - CUSTOMER INFORMATION -----  
Orig/Caller: \_\_\_\_\_ Title: OTHER

Repair Dir: 12098 - SCHILLING L-W/MENDENHALL INC Ph#: (901) 794-4000  
City: Memphis State: Tennessee  
Country: UNITED STATES Region: Memphis - 23

Claim #:/Date: \_\_\_\_\_ /19/1998

Customer Name: \_\_\_\_\_ City: \_\_\_\_\_

----- CQIS VIN HISTORY -----

NO CQIS VIN HISTORY AVAILABLE FOR THIS VEHICLE

----- SUPPLEMENTAL SURVEY: NONE -----

----- VEHICLE'S WARRANTY HISTORY (365 days only) -----

NO VEHICLE WARRANTY HISTORY AVAILABLE FOR THIS VEHICLE

3713 7715

DEC 10 '98 15:21 FR AS650 (300 EAST) 313 594 2268 TO 00004

P.04 US

Page: 01

CGIS DETAIL REPORT

12/07/98 18:14:12

CGIS Report Number: VDUMA322 Program Type: Q Orig Rpt #: 134596-97  
Report Source: MSS - PCSD - QSF5 Report Date: 04/21/1997**R E P O R T   S U M M A R Y**

**VEHICLE:** 1992 TOON CAR, STAND, SEDAN      **VIN:** 1LNLM81W8NT  
**Engine:** 4.6L ROMEO BASE EFI      **Odometer:** 36,802 MILES  
**Operating Enviro:**      **WCC:** SF07  
**Vehicle Use:**      **Rsp. Act:**  
**SYMP/ICM:** 7 04 2 45 UNKNOWN SOURCE CONCERNS      **FIRE/SHOICE**  
**SMOKE**      **UNDERHOOD**  
**Additional Symptom:**  
**Other Veh. With Concern:**      **Severity Rating - Customer:** Engineering  
**Causal Component:** 2AS74      **SWITCH ASY LOW AIR P**  
**Causal Factor:** Feature: Loc:  
**Causal Condition:** Photo: Images: 0  
**Component Test Status:** Return Loc:  
**Vehicle Fixed?:** YES      **Customer satisfied?:** Repair Effectiveness (%): 100

**C O M M E N T S**

**TYPE**      **COMMENT TEXT**  
**CONCER** THERE WAS SMOKE FROM UNDER THE HOOD.  
**REPAIR** THE BRAKE PRESSURE SWITCH CAUGHT ON FIRE AND BURNED THE WIRING WITH THE KEY ON. PREVIOUS VEHICLES WITH FIRES STARTING IN THIS AREA WERE BURNED TO THE DEGREE THAT WE COULD ONLY GUESS WHAT CAUSED THE FIRE. THIS VEHICLE FIRE STOPPED SOON ENOUGH. WE REPLACED THE BRAKE PRESSURE SWITCH.  
**AUDIT** 04/23/1997 10:25AM DATA ENTRY'S      MSS - PCSD - QSF5  
**SYMP/ICM** 3 01 0 00      CHANGED TO 7 04 2 45      BY MEAKER6

**C O N C E R N   D E T A I L S**

**D I A G N O S T I C   I N F O R M A T I O N**  
**Symp. Verif?:** Ease of Diagnosis:      **Level of Assistance:**  
**Comp. Timing:** Base Timing :      **MIL light on? :**  
**Test Stand :** Road Test :      **SD Number:**  
**Prior Repair Attempts:**      **Repair Prior to Call:** NO  
**DTCS Codes:** K0EC:      **CH:**  
**KOER:**      **Equipment/Procedure Used**      **Effective?**      **Equipment/Procedure Used**      **Effective?**

**S E R V I C E   A C T I O N S**

Repair Type	Component Number	Number	Description	Causal Comp.
RPL	2AS74	SERVICE	SWITCH ASY LOW AIR P	YES

**V E H I C L E   D E T A I L S**

Vehicle Build Date:	04/07/1992	Warranty Start Date:	10/02/1992
Date of Sale:	10/02/1992	Selling Dlr (Mkt,Dlr,Sub):	11627
Dealer Special Order:		Gross Vehicle Weight:	
UH/RH Drive:			

**--- E N G I N E ---**

Engine: 4.6L ROMEO BASE EFI	Tag: 2G	812 MA
Bld Dt:	Calib: 21B1005 A	Serial #: N

**--- T R A N S M I S S I O N ---**

Trans: MOD-E 4SP ELEC O/D	Part #:	
Bld Dt:	Serial #:	
Model:	Flt:	Shift:

3713 7718

DEC 10 '98 15:22 FR ASSES (300 EAST)

313 554 2266 TO 68864

FWD-CC

Page: 02

CQIS DETAIL REPORT

12/07/98 18:14:12

CQIS Report Number: [REDACTED] Program Type: Q  
Report Source: NSN - FCSD - QSPS Orig Rpt #: 134396-97  
Report Date: 04/21/1997Axle: 8.8 3.08 CONVENTIONAL 16 Tag Code: Blk Br:  
Serial #: Flt:Tire : P215/70R15 WSW Brand :  
Radio : ELETR PREMIUM AM/FM STRO/CSTR A/C : ATC AIR CONDITIONER  
Paint : BLUE EXTERIOR PAINT FAMILY CLEAR CRYSTAL BLUE FROST C/C

## ----- AFTER MARKET MODIFICATIONS -----

NO AFTER MARKET MODIFICATIONS DATA AVAILABLE FOR THIS VEHICLE

----- REPORT ORIGINATOR - REPAIR FACILITY - CUSTOMER INFORMATION -----  
Orig/Caller : GEORGE TAYLOR Title: OTHERRepair Dlr: 11627 Ft Lauderdale L-M Inc Ph#: (354) 779-2060  
City: Ft Lauderdale State : Florida  
Country: UNITED STATES Region : Orlando - 24

Claim #:Date : 129844

Customer Name [REDACTED] City :

## ----- CQIS VIN HISTORY -----

CQIS Prog  
Date Report # Type Sync Cat Causal Part Description Dealer Id  
04/22/1997 9DVAH14 EDR ELECT. VALVE-FRT DISC BRAKE P 11627

## ----- SUPPLEMENTAL SURVEY: NONE -----

## ----- VEHICLE'S WARRANTY HISTORY (363 days only) -----

Repair Repair Odometer Mfr Causal Service Part Number Labor  
Dealer ID Date Order (Miles) Mfr Cond. Pfx Base Sfx Operation  
11627 04/21/1997 38862

3713 7717

\*\* TOTAL PAGE.04 \*\*

\*\* TOTAL PAGE.05 \*\*

**BRAKE QUALITY IMPROVEMENT TASK FORCE**  
**Meeting #164 - Monday, 09 February 1998**

**AGENDA**

<u>Discussion Item</u>	<u>Lead</u>	<u>Time</u>
1. Brake Hose Material Change (EPDM)	Ken Stransky (Dana)	10 min DELETED
2. Test Plan Status	Mike Beccaccio	5 min
3. Vehicle Operations Update	Calvin Skeen	10 min
4. FCSD Issues	Eric Alcock / John Coleman	10 min
5. RCD Update	George Thornton	10 min
6. Notes: Subjective vs. Objective Correlation	Greg Vytetel	10 min
7. Brake Pedal Feel: Metrics and Test Methods	Bruce Pease	10 min
8. Walk-Ins	All	5 min

**Upcoming Agenda Items:**

<u>Discussion Item</u>	<u>Lead</u>	<u>Assigned Date</u>	<u>Report Out</u>
1. Notes: Subjective vs. Objective Correlation	Greg Vytetel	10/28/98	02/08/99
2. Brake Hose Material Change (EPDM)	Ken Stransky (Dana)	1/26/99	02/08/99
3. Brake Pedal Feel: Metrics and Test Methods	Bruce Pease	N/A	02/08/99
4. Improved Brake Fluid Fill Process	Mike Vittek	N/A	02/08/99
5. DOT3 vs. DOT4 Water Absorption	Paul Hurley	N/A	02/15/99
6. Yaw Rate Sensor Lessons Learned	Gerry Davis	02/01/99	02/15/99
7. Proposed Heath Chart Revisions from PHN131 Roughness Lessons Learned	TBD	N/A	02/15/99
8. On-Vehicle LRO Data from Pilot Plant	Dave Mann	02/01/99	02/15/99
9. Brake Pad/Lining Replacement Policy	John Coleman	12/14/98	02/15/99
10. LRO Robustness to Wheel Bolt-up	Kelly Trout	01/11/99	02/15/99
11. Evac and Fill Modeling	George Vilic	08/03/98	02/22/99
12. Chassis Rotts Testing	John Coleman	08/10/98	03/01/99
13. Brake Design Cookbook	Bill Cowell	12/07/98	03/08/99
14. AMS Test Correlation	Peter Livingstone	12/07/98	03/15/99
15. Brake Pad - Adequacy of High Mileage Requirements in the Ford Reliability Disciplines	Bill Cowell / Joe Schramek	02/01/99	03/26/99
16. DTV Generation: DST vs. Autobahn Comparison on Transit	Bob Knepper	12/07/98	3/29/99
17. Park Brake and Wheel Bearing Supplier Strategies	Monika Gablowski / Paraj Bajaj	08/17/98	04/12/99
18. AMS Correlation (APG vs. Lommel) and Tire Study	Bill Faulk	12/07/98	04/12/99
19. Rotor Core Shifting Spec Analysis	Bill Cowell / J. Fash	12/14/98	04/19/99
20. Different Wheel Torque Specifications between Europe and N.A.	Steve Marulis	N/A	12/31/99

3713-7718

**Other Discussion Items**

Originator: John R. Coleman  
Distributed by: John Silvertz  
File name: 020899.doc

Page 4 of 6

Created on: 3-Feb-99  
Revised on: 5-Feb-99  
Printed on: 5-Feb-99

\*\*\*\*\*  
\* Note printed by TBAZIL on 1 Mar 1999 at 14:52:35 \*  
\*\*\*\*\*

From: MREESSE --DRBN005  
To: SREIMERS--DRBN007  
cc: TBAZIL --DRBN005

Date and time 03/01/99 12:24:34  
FPORTER --DRBN007  
JNSEME --DRBN005

FROM: M. P. REESE USAET(UTC -05:00)  
Subject: Brake Dvac Switch Re-location - DESIGN ORDER

STEVE, THE RESULT OF THE MEETING THIS MORNING IS THAT WE WILL HAVE A FEASIBLE, CLEAR SOLUTION (FOR SWITCH MOUNTED TO BRAKE PEDAL ASSEMBLY, ON 1992/1993/1994 TOWN CAR) BY NOON FRIDAY 1999 MAR 05.  
IN MAKING THIS SOLUTION, WE ARE BEING VERY CAREFUL SO THAT WE DO NOT MAKE SOMETHING ELSE WORSE. THE HISTORY IS VAGUE.  
ANY GOOD NEWS, ABOUT OTHER SOLUTIONS?

Regards,  
M. P. Reese 313-317-7142 (313-621-6675 FAX)  
OPD LVC - Brakes Mail Drop 1229 BUILDING 2 24M31  
\*\*\* Forwarding note from SREIMERS--DRBN007 02/27/99 16:19 \*\*\*  
To: MREESSE --DRBN005  
cc: FPORTER --DRBN007 Porter, F.J.

FROM: Steve Reimers USAET(UTC -05:00)  
Subject: Brake Dvac Switch Re-location  
Marty, Please call Fred Porter with the update from your meeting. I will be at MPG most of the day.

Steve Reimers building 5 3E008  
AVT Chassis E/E System Applications mail drop 5011  
39-03286 SREIMERS steiners@ford.com fax 39-03286 />  
\*\*\* Forwarding note from MREESSE --DRBN005 02/27/99 16:13 \*\*\*  
To: SREIMERS--DRBN007  
cc: TBAZIL --DRBN005 LSMITH9 --DRBN005

FROM: M. P. REESE USAET(UTC -05:00)  
Subject: Brake Dvac Switch Re-location

I AM OPTIMISTIC ABOUT ABILITY TO PACKAGE THE CURRENT PRODUCTION SWITCH ON THE BRAKE PEDAL AND BRACKET ASSEMBLY IN 1992/1993/1994 TOWN CARS. I WILL KNOW MORE (BUT NOT EVERYTHING) ABOUT TIMING AT THE CONCLUSION OF A 9:00 AM MEETING WITH CHASSIS DESIGNERS. GENERAL OPTIMISM COMES FROM THE BRAKE PEDAL AND BRACKET ASSEMBLY DRAWINGS; THEY (SO FAR) SHOW EVOLUTION OVER THE MODEL YEARS, AND INVOLVE ONLY ONE SUPPLIER.

WERS AND DOCMAN ARE NOT IN GOOD SHAPE FOR THIS 1992/1993/1994 MODEL TASK. THAT SLOWS THE ADVANCE. FACILITATES AMBUSE.

ALWAYS, I MUST CONSIDER EFFECTS ON FMVSS 105. VEHICLE TEST, BRAKE SYSTEM.

I INTEND TO CALL YOU, ABOUT NOON ON MONDAY 1999 MAR 01.

Regards,  
M. P. Reese 313-317-7142 (313-621-6675 FAX)  
OPD LVC - Brakes Mail Drop 1229 BUILDING 2 24M31  
\*\*\* Forwarding note from SREIMERS--DRBN007 02/25/99 15:39 \*\*\*  
To: MREESSE --DRBN005

3713 7719

FROM: Steve Reimers

USAET(UTC -05:00)

Subject: Brake Dead Switch Re-location

Marty, I was asked what the status of this design work. Have you got any good words I can pass on to my manager? I would like to give Jack Paskus a sense of where we are on this task, what the next step(s) are and when they are targeted to complete. My meeting with Paskus is Monday at 3:30. thanks,

Steve Reimers

AVT Chassis E/M System Applications  
39-03286 SREIMERS sreimers@ford.com


building 5 3C043

mail drop 5011

fax 39-03286 >

3713 7720


1992 and 1993 Town Car underhood fires  
engine off or engine unknown



37187721

H298-055  
99/Mar-01  
map engine-off-unknown.ppt

1992 and 1993 Town Car underhood fires  
one can not rule out the 9F924 switch



126 Town Cars  
3 Grand Marquis  
1 Crown Victoria  
Note: Data has not been  
fully updated for CV/CIM

PEM-033  
99-Feb-09  
nwq fires possible sw.ppt

## SUMMARY

### 1) Reviewed 158 92/93 Town Car reports which included:

Owner Reports (MORS)

Field Reports (CQIS)

Lawsuits and Claims Litigation Prevention Files

NHTSA Reports

There were 47 reports categorized engine off/unknown and underhood based on the information available.

30 out of 47 are reported engine off.

17 out of 47 are reported unknown.

Of the 30 vehicles reported with the engine off:

15 are reported to be unknown probable cause.

7 are reported to be electrical as a probable cause.

4 are reported as having started in the left front wheel area.

4 are reported as the brake pressure switch probable cause.

Of the 17 vehicles reported with the engine unknown:

11 are reported to be unknown probable cause.

3 are reported to be electrical as a probable cause.

1 is reported as the brake pressure switch as a probable cause.

1 is reported as spark plug wires as a probable cause.

1 is reported as the solenoid pressure sensor as a probable cause.

Specific cause reports were ruled out other than the four components as defined by NHTSA, including the brake pressure switch.

### 2) The file of the 47 vehicles were sent to FCSD for review of option content.

### 3) Provided the list of the 47 vehicles to Vehicle Safety Office for further investigation of these vehicles.

## NEXT STEPS:

Review CV/GM CQIS reports for the same criteria as Town Car.

Reviewing Town Car underhood hot circuits, engine off with UTA on 3/2/99.

3713 7723

-DRAFT-

Chassis Brake Response to Investigation PE98-055 -1992 and 1993 Model Town Car Vehicles

- 8a) The approximate date on which the modification or change was incorporated into production...  
AC-00-E-1012 2004-007
- At the beginning of the 1992 model year (approximately August 1991) through the 1994 model year (approximately July 1994)
- 8b) A description of the modification or change...  
BA, CA
- The brake pressure switch was packaged on the brake proportioning-valve block F2VC-2B091-AB.
- BB; C.B.
- 8c) The reason for the modification or change...  
AC-00-E
- The switch was new for 1992. The package was changed for the 1995 model year with the introduction of front-rear versus diagonal brake circuit splitting.
- 8d) Whether the modified or changed components can be interchanged with earlier production components...  
AC-00-E
- The 1992-1994 packages are not interchangeable with prior or later models.

LVC OPD Brake Engineering Section  
January 27, 1998

3713 7726



U.S. Department  
of Transportation

National Highway  
Traffic Safety  
Administration

DEC 1 1998

**CERTIFIED MAIL**  
**RETURN RECEIPT REQUESTED**

L.W. Camp, Director  
Automotive Safety and Engineering Standards Office  
Ford Motor Company  
330 Town Center Drive  
Dearborn, MI 48126

400 Seventh Street, S.W.  
Washington, D.C. 20590

DISPOSE of Copies (Black Stamped) by:	2018
RETAIN Record Copy (Red Stamped) Thru:	
Schedule Number:	

NSA-12jfa  
PE98-055

Dear Mr. Camp:

This letter is to revise the due date for the November 24, 1998 information request letter regarding Investigation PE98-055. The correct due date is January 15, 1999.

Sincerely,

Thomas Z. Cooper, Chief  
Vehicle Integrity Division  
Office of Defects Investigation



AUTO SAFETY HOTLINE  
1800 424-9393  
Wash. D.C. Area (202) 356-5123

3713 7727



U.S. Department  
of Transportation

National Highway  
Traffic Safety  
Administration

T. J. BOHAN --

NOV 24 1998

10 NOV 98 E.S.

**CERTIFIED MAIL**  
**RETURN RECEIPT REQUESTED**

400 Seventh Street, S.W.  
Washington, D.C. 20590

DISPOSE of Copies (Black Stamped) by:	
RETAIN Record Copy (Red Stamped) thru:	07018
Schedule Number:	27.03

L.W. Camp, Director  
Automotive Safety and Engineering Standards Office  
Ford Motor Company  
330 Town Center Drive  
Dearborn, MI 48126

NSA-12jfa  
PE98-055

Dear Mr. Camp:

This letter is to advise you that the Office of Defects Investigation (ODI) of the National Highway Traffic Safety Administration (NHTSA) is conducting a Preliminary Evaluation concerning engine compartment fires in certain Lincoln Town Car vehicles manufactured by the Ford Motor Company.

This office has received 21 reports of engine compartment fires in 1992 and 1993 Lincoln Town Cars. The fires in these vehicles are reported to have started while the vehicles were parked and the engines not running. Ten of the reports indicate a fire at the left front fender wheel well area (see photograph, page 6), two indicate a fire at the master cylinder, which is adjacent to the left front fender wheel well area, and the remaining nine reports indicate a fire in the engine compartment. Additionally, five of the reports indicate the vehicle owner's carport, garage, or home, was also damaged as a result of the fire.

A copy of each of the reports is enclosed for your information.

Unless otherwise stated in the text, the following definitions apply to this information request:

- Subject vehicles: all 1992 and 1993 Lincoln Town Car vehicles.
- Ford: Ford Motor Company, all of its past and present officers, employees, whether assigned to its principal offices or to any of its field or other locations, including all of its divisions, subsidiaries (whether or not incorporated) and affiliated enterprises and all of their headquarters, regional, zone and other offices and their employees, and all agents, contractors, consultants, attorneys and law firms and other persons engaged by or under the control of Ford Motor Company (including all business units and persons previously referred to) who are or were involved in any way with (a) design, analysis, modification or production; (b) testing, assessment or evaluation; or (c) record-keeping, claims, or lawsuits relating to the alleged defect in the subject vehicles.



AUTO SAFETY HOTLINE  
(800) 424-9393  
Wash. D.C. Area (202) 366-0123

3713 7728

- Alleged defect: all under hood fires, or other thermal anomalies, from any source or origin, of any description, level, degree, or magnitude, occurring in the left, or drivers side, of the engine compartment. This would include fires in the area of the left front wheel, or left front fender.
- Documents: in the broadest sense of the word, shall mean all written, printed, typed, recorded or graphic matter whatsoever, however produced or reproduced, of every kind, nature, and description, including but not limited to, papers, records, letters, correspondence, memoranda, communications, electronic mail messages (existing in hard copy and/or in electronic storage), faxes, notes, annotations, working papers, drafts, minutes, records, resolutions, books, pleadings, response to discovery, administrative and judicial filings, all transcripts and other recordings of any kind, affidavits, materials and things produced in discovery, statements, summaries, interviews, opinions, reports, newspaper articles, studies, analysis, evaluations, interpretations, applications, agreements, jottings, agendas, bulletins, notices, announcements, instructions, designs, specifications, blueprints, as-builts, manuals, brochures, publications, schedules, journals, statistical data, lists, tabulations, computer printouts, data processing input, data in storage, and data output, microfilm, microfiche, data from optical scanning or recording, photographs, tangible things, and all records kept by electronic, photographic, or mechanical means, any drafts or revisions pertaining to any of the foregoing, and all other things similar to any of the foregoing however denominated and any other data compilations from which information can be obtained, translated if necessary, into reasonably usable form and any other documents.

In order for my staff to evaluate the alleged defect, certain information is required. Pursuant to 49 U.S.C. § 30156, please provide numbered responses to the following questions. Please repeat each question verbatim before the response. If you have previously furnished ODI with information that is responsive to any item(s) in this request, you need not resubmit that information, but your response must cross-reference (by date of response and question number) the earlier submission. If Ford cannot answer any specific question, please state the reason why it is unable to do so. If you claim that any information or material responsive to the following items need not be divulged to the NHTSA because it is privileged, or the work product of an attorney, state the nature of that information or material and identify any document in which it is found by, date, subject or title, name and position of person from and person to whom it was sent, and name and position of any other recipient. You must also describe any privilege that you claim, and explain why you believe it applies.

1. State the total number of subject vehicles sold in the United States by model year.
2. State the number incidents, known to Ford, in which the alleged defect has been reported to have occurred in the subject vehicles. Furnish copies of all documents, from any and all sources, including documents which may not originally have been submitted to Ford, which

are in Ford's possession or control, or of which it is otherwise aware, that pertain, in any way, to any of these incidents. This should include, but is not limited to, all documents possessed by Ford, or of which it is otherwise aware, pertaining to the reports included with this letter. Furnish all documents whether or not Ford has verified the validity of each document. For each incident in this response please provide the vehicle owner's name, address, and telephone number; and identify all vehicles by vehicle identification number, model year, date of manufacture, date of retail sale, date of incident, mileage at the time of the incident, and problem description. For all incidents involving lawsuits please identify the caption, court, docket number, and filing date of each lawsuit and a copy of the complaint document initiating the lawsuit. Sort all incidents by cause and area or component of origin.

- ③ State the total number vehicles sold in the United States by model name and model year that have engine compartment configurations (i.e., components and component location, wiring harnesses and harness location) the same as the subject vehicles. Provide a response to question number two for all vehicles identified in your answer to this question.
4. State the number of all warranty claims, including extended warranty claims, and "goodwill," field or zone adjustments received by Ford that relate to the alleged defect in the subject vehicles by calendar year, calendar month, and problem identification. Identify all owners by name, address, and telephone number, and all vehicles by vehicle identification number, model name, model year, date of manufacture, date of retail sale, date of incident, mileage at the time of the incident, and problem description.
5. Identify all electrical circuits by name, number, and wire color, located in the left side of the engine compartment that are, or remain, energized by the battery when the ignition key is in the off position. For all circuits identified, provide a schematic drawing which identifies the harness(es) in which they reside, the harness location(s), and the components to which power is supplied.
- ⑥ Identify and describe all inspections, tests or other analyses conducted by Ford, its contractors, suppliers, or by any other entities, regarding the inspection of any subject vehicles that relate to the alleged defect, to date. Identify, by name and address, the entity that conducted each such test or analysis. Furnish copies of all reports, surveys, notes, tables, graphs or other documents that pertain to each such test or analysis. State when each test or analysis was initiated and concluded, or whether it is still in progress. Include in your response a description of a worst case scenario.
7. If Ford has issued any bulletins, advisories, or other communications to distributors, retailers, consumers, or any other entity pertaining to the alleged defect in the subject vehicles, provide a copy of each such document. If no such documents have been issued, so state.

8. Identify and describe all significant modifications or changes made by or on behalf of Ford in the manufacture, design, or material composition of all components in the subject vehicles that may relate to the alleged defect. The following information must be included for each such modification or change:
  - a. the approximate date on which the modification or change was incorporated into production;
  - b. a description of the modification or change;
  - c. the reason for the modification or change; and
  - d. whether the modified or changed components can be interchanged with earlier production components.
9. Provide Ford's assessment of the alleged defect in the subject vehicles, including:
  - a. all causal or contributory factors;
  - b. the failure mode;
  - c. the risk to occupant safety it poses; and
  - d. whether there are any circumstances that would provide the vehicle owner or others with warning of its existence.


Your response to this letter, in duplicate, must be submitted to this office by January 6, 1999. Please include in your response the identification codes referenced on page 1 of this letter. If you find that you are unable to provide all of the information requested within the time allotted, you must request an extension from Mr. Thomas Z. Cooper not later than five days from the due date. If you are unable to provide all of the information requested by the original deadline, you must submit a partial response by that date with whatever information you have available, even if you have received an extension.

This letter is being sent to your company pursuant to 49 U.S.C. § 30166, which authorizes NHTSA to conduct any investigation that may be necessary to enforce Chapter 301 of Title 49, U.S. Code. Your failure to respond promptly and fully to this letter could subject Ford to civil penalties pursuant to 49 U.S.C. § 30165 or lead to an action for injunctive relief pursuant to 49 U.S.C. § 30163.

If you consider any portion of your response to be confidential information, include that material in a separate enclosure marked "CONFIDENTIAL." In addition, you must submit a copy of all such material to the Office of Chief Counsel (NCC-30), National Highway Traffic Safety Administration, 400 Seventh Street, SW, Washington, DC 20590, and comply with all other requirements for the submission of confidential business information stated in 49 CFR Part 512.

If you have any technical questions concerning this matter, please contact Mr. John Abbott of my staff at (202) 366-5221.

Sincerely,



Thomas Z. Cooper, Chief  
Vehicle Integrity Division  
Office of Defects Investigation

Enclosures: 12 VOQ's: 813241, 824016, 808265, 821667, 979634, 521137, 804418, 541041  
820316, 536206, 819621, 823462; 5 fire department reports; 2 internet reports; and  
2 fire investigator reports

NHTSA:NSA:ODI  
NSA-12:JABBOTT:drd:6-5221:11/17/98  
cc:  
NSA-01  
NSA-12/Subj/Chron/  
Document: I:/ABBOTT/Towncar.IR

PE98-055  
page 6

1992 Lincoln Town Car (1LNLM81W2NY [REDACTED]



3713 7733

11/24/98

PE Opening Reports (PE98-055)  
1992 Lincoln Town Car Engine Fires

NO.	Source	ST	VIN	M/Y
1	813241	FL	1LNLM82W5NY	92
2	824016	TX	1LNLM81W2NY	92
3	808285	FL	1LNLM82W7NY	92
4	821867	LA	1LNLM81W9NY	92
5	979634	TX	1LNLM82W5NY	92
6	521137	OK	1LNLM81W2NY	92
7	F.D.R.	GA	1LNLM82W3NY	92
8	804418	OH	1LNLM81W8NY	92
9	541041	FL	1LNLM81W3NY	92
10	F.D.R.	FL	1LNLM81W2NY	92
11	F.D.R.	FL	1LNLM82W7NY	92
12	A805260	FL	1LNLM81W0NY	92
13	820316	FL	1LNLM81W3NY	92
14	I/Net	FL	1LNLM81W8NY	92
15	536206	MS	1LNLM83W9NY	92
16	819621	LA	1LNLM82W5NY	92
17	I/Net	FL	1LNLM82W4NY	92
18	F.D.R.	GA	1LNLM82W1NY	92
19	A804221	FL	1LNLM81WP2Y	93
20	823462	MS	1LNLM81W5PY	93
21	F.D.R.	FL	1LNLM81WXPY	93

373 7724

- DRAFT -

To: Zandra Deering

From: Tom Bezl

Date: January 15, 1999

Subject: Significant Foundation Brake Design Changes under PE98-055

The basic package of the brake pressure switch as located with the proportioning valve block (F2VC-2B091-AA, BA, CA) continued with minor changes through the 1994 model year. No other apparently significant design changes have been identified at this time.

3719 7785

1995

① ABS w/o TC

Now ABS

-2B195-

AOP PIA

② ABS/TC

REMOTE VALUE

PIA SPOT RL

③ 1 1/2 version for Lima / Paracae

1A

1990 diagonal split

1994 Under Booster 1/2

1pm LCR #1, Block #5

Tevos M/C Noxx -10

Prog value same split w/ d into 7G

Hot - normally closed

Tc '91 on FN

1991 Vacuum switch?

Tc '92 on EN153



Central Laboratory  
15000 Century Drive  
Dearborn, MI 48120-1287

January 15, 1999

Preliminary Findings:

(A)

The cup is partially covered with a greenish residue. Residue appears to be primarily an oxide of the brass contact material with possibly a sulfur compound. This suggests transfer of oxide or corrosion product from the brass contacts to the cup.

(B)

The stationary contact exhibits intergranular cracks which indicate stress corrosion cracking (SCC). SCC is caused by combination of a specific corrosive environment and a sustained tensile stress (can be localized). Ammonia, ammonia compounds, sulfur compounds, and moisture are known to cause SCC in brass. The contact material has been reported to be 360 brass, which is highly susceptible to SCC.

(C)

The presence of brake fluid on the switch side of the diaphragm has been determined. Black residues in the hex port and on the cup, converter, and disc appear to be compounds which may have formed from a reaction between decomposition products (acids) of the polyester base, the brake fluid, and metals in the switch. This suggests that the brake fluid was present on both sides of the diaphragm during the thermal event.

All three diaphragms exhibit what appears to be mechanical damage. The damage does not match up with any mating parts of the switch. This suggests that damage may have occurred prior to assembly. The diaphragm has become brittle and cracked in the vicinity of the damage. Brake fluid has become entrained between the layers (Teflon and capton) of the diaphragms.

The post of the movable contact melted back into the bulkhead between the switch and terminal cavities of the base. There is also arc damage (localized melting) to one corner of the bridge of the stationary contact. This damage appears fresh (surfaces bright and shiny) which suggests that it may have occurred in the later stages of the thermal event.

The terminals exhibit deposits which appear to be primarily sulfur compounds of the terminal material (tin plated brass). Although these deposits appear visually similar to the deposit found on the cup, they appear to be of different composition.

The white residue found in the connector cavity contains elements found in dry chemical fire extinguishers (Muscovite and phosphorus).

Steve LaRouche


Integrating 606°F

Flash 312°F

Fused @ 15A ~ 180W

3719 7737

Hydraulic Pressure Switch Cross Section



3713 7738

in connection with the brake pressure switch.  
WJIAA135 occurred at 51,500 miles.  
VDUAA322 occurred at 56,802 miles.

**Supplier:** The pressure switch was manufactured by Texas Instruments. The switch was purchased in assembly with the brake proportioning valve bought from Surfaces.

**Contacts:** Surfaces - Mike Thomas (248)543-6520 MILITE Industries  
TI - Rob Sharp (248)305-5729  
TI - Russ Beumann (508)236-3314  
TI - Charlie Douglas (800)236-3657

**Function:** The brake pressure switch is a redundant switch for turning off the speed control function.

**X-Rays:** Taken by Steve LaRouche, Norm LaPointe & Clark Thomas on 12/17/1998. Original photographs and part are in Steve LaRouche's possession.

**ON-GOING ACTIVITY:**

2 service parts have been ordered from Fairlane Ford for X-ray and other testing by Central Lab Services.

Meeting with representatives of TI is planned for 12/22/1998 to discuss intended operation of the switch. The meeting will be at the Central Laboratory Conference room off of the lobby.

**QUESTIONS:** (in no particular order)

- 1) What is the normal current in the brake pressure switch?
- 2) Was cruise control standard on Town Car in 1992 and 1993?
- 3) Under what circumstances is brake fluid flammable?



According to Clark Thomas & Mary Haga, brake fluid is flammable at approximately 300 degrees F.

- 4) What is the repair history for vehicles that have exhibited a problem? Repair history for the two CQIS vehicles are being gathered by Fred Porter.
- 5) What other vehicles use this brake pressure switch? What are their electrical configurations?

MODEL YEAR	92	93	94	95	96	97	98
Town Car	[xxxx]	[xxxx]	[xxxx]	[xxxx]	[xxxx]	[xxxx]	
Crown Vic	[xxxx]	[xxxx]	[xxxx]	[xxxx]	[xxxx]	[xxxx]	
Grand Marquis	[xxxx]	[xxxx]	[xxxx]	[xxxx]	[xxxx]	[xxxx]	
Econoline	[xxxx]	[xxxx]	[xxxx]	[xxxx]	[xxxx]	[xxxx]	
Club Wagon	[xxxx]	[xxxx]	[xxxx]	[xxxx]	[xxxx]	[xxxx]	
F-Series		[xxxx]	[xxxx]	[xxxx]	[xxxx]	[xxxx]	
Bronco		[xxxx]	[xxxx]	[xxxx]	[xxxx]	[xxxx]	
Taurus SHO		[xxxx]	[xxxx]	[----]			
Capri			[xxxx]	[xxxx]	[----]		
Windstar			[xxxx]	[xxxx]	[xxxx]	[xxxx]	

2000

8713 7740



ILNLM92WXNY749071 1992 Lincoln Town Car - Dallas, TX, 99-Jan-13

1E98-055


9713 7741

1LNLM92WXNY

1992 Lincoln Town Car - Dallas, TX, 99-Jan-13

PE 98-655

3718 7742



1LNLM92WXNY [REDACTED] 992 Lincoln Town Car - Dallas, TX, 99-Jan-13

PE 98-055

3713 743





Switch A

ILNLM92W1PY

1993 Lincoln Town Car - Houston, Tx 99-Jan-14 PE98-055

3719 774



1LNLM92W1PY


1993 Lincoln Town Car - Houston, Tx 99-Jan-14 PE98-055

8713 7745



1LNLM92W1P


1993 Lincoln Town Car - Houston, TX 99-Jan-14 PE98-055




Switch A

F2VC-9F924-AB 2281

3719 7746




Switch B



1LNLM83WSNY


1992 Lincoln Town Car - Houston, TX 99-Jan-14 PE98-055

3713 747



ILNLM83WSNY [REDACTED] 992 Lincoln Town Car - Houston, TX 99-Jan-14 PE98-055


3713 7746



1LNLM83W5NY

992 Lincoln Town Car - Houston, TX 99-Jan-14 PE98-055

3713 7749



Switch B

F2VC-9F924-AB 2114

1LNLM83WSNY

1992 Lincoln Town Car - Houston, TX 99-Jan-14 PE98-055

37187760




1LNLM83W5NY [REDACTED] 1992 Lincoln Town Car - Houston, TX 99-Jan-14 PE98-055



Switch B

F2VC-9F924-AB 2114





Switch C

3713 7751

1LNLM81W2NY [REDACTED] 1992 Lincoln Town Car - Houston, TX 99-Jan-14 PE98-055

87137752




Switch C

F2VC-9F924-AB 2003

1LNLM81W2NY [REDACTED] 1992 Lincoln Town Car - Houston, TX 99-Jan-14 PE98-055

3713 7763



1LNLM82W7NY [REDACTED]

1992 Lincoln Town Car - Houston, TX 99-Jan-14

TE98-055

**1992-93 LINCOLN TOWN CAR  
UNDERHOOD FIRES**

PE98-056

NO.	OWNER NAME	ADDRESS	CITY	STATE	ZIP	TELEPHONE	VIN	MODEL	YEAR	BUILD	SALE	REPORT DATE	REPORT TYPE	MILEAGE	ISSUE	REPORTED	POSSIBLE PROBLEM DESCRIPTION	
																	DATE	CORSV
1	NA	Hage	OK	NA	NA	NA	1U1LM81W4NT	Town Car	1992	0312462	0340242	08/7/98	CORSV	84,682	Fires		Lincoln leather on exhaust manifold and carried in fire.	
2	NA	Evergreen Park	IL	NA	NA	NA	1U1LM82W4NT	Town Car	1992	1000881	0227482	08/26/98	CORSV	220,240	Fires		Brahes.	
3	NA	Sacramento	CA	NA	NA	NA	1U1LM83W4NT	Town Car	1992	0312462	0340242	09/20/98	CORSV	21,280	Melted		Brake lines.	
4	NA	Los Angeles	CA	NA	NA	NA	1U1LM84W4NT	Town Car	1992	0312462	0340242	09/20/98	CORSV	37,442	Fires		Brake lines.	
5	NA	Oscarn	MI	NA	NA	NA	1U1LM85W4NT	Town Car	1992	0312462	0340242	09/23/98	CORSV	217,800	Fires		Alternator melt-down issue.	
6	NA	Gainesville	FL	NA	NA	NA	1U1LM86W4NT	Town Car	1992	1271891	0131482	08/26/98	CORSV	40,772	Heated/Burned		Overheated, drive belt brake, A/C heated, burned.	
7	NA	Memphis	TN	NA	NA	NA	1U1LM87W4PT	Town Car	1992	0312462	0340242	10/08/98	CORSV	61,022	Fires		Brake lines.	
8	NA	FL Lauderdale	FL	NA	NA	NA	1U1LM88W4NT	Town Car	1992	0407482	1002482	04/21/98	CORSV	88,202	Grease		Brake pressure switch caught on fire and burned the wiring.	
9	NA	Santa Monica	CA	NA	NA	NA	1U1LM89W4NT	Town Car	1992	0312462	0340242	12/27/98	CORSV	34,837	Melted wires		Overheated, melted wires.	
10	NA	Poughkeepsie	NY	NA	NA	NA	1U1LM90W4NT	Town Car	1992	0312462	0340242	01/08/99	CORSV	49,118	Overheated		Spark plug wires melted.	
11	NA	Troy	NY	NA	NA	NA	1U1LM91W4PT	Town Car	1992	0312462	0340242	08/23/98	CORSV	14,922	Fires		Brakes.	
12		Northbrook	IL				1U1LM92W4PT	Town Car	1992	0305462	1120548	07/22/98	MORS	40,000	Burned		Shorted wiring.	
13		Kingsville	IL				1U1LM93W4PT	Town Car	1992	0312462	0811542	08/14/98	MORS	83,200	Fires		Unknown.	
14		Englewood	NJ				1U1LM94W4PT	Town Car	1992	0312462	1271894	07/23/98	MORS	12,000	Fires		Unknown.	
15		New Orleans	LA				1U1LM95W4PT	Town Car	1992	0312462	0771482	08/23/98	MORS	8,500	Fires		Unknown.	
16		Brownsville	NC				1U1LM96W4PT	Town Car	1992	0401482	0419482	08/24/98	MORS	25,911	Fires		Unknown.	
17		Pittsburgh	PA				1U1LM97W4PT	Town Car	1992	1204462	0130482	03/23/98	MORS	12,900	Fires		Wiring harness.	
18		Rochester	NY				1U1LM98W4NT	Town Car	1992	0312462	0802482	08/30/98	MORS	26,000	Fires		Unknown.	
19		Macomb Island	FL				1U1LM99W4NT	Town Car	1992	1125481	1221481	02/27/98	MORS	48,000	Fires		Unknown.	
20		Melbourne	FL				1U1LM100W4NT	Town Car	1992	0305462	0916482	01/28/99	MORS/VOC	40,000	Fires		Unknown.	
21		Baton Rouge	LA				NA	Town Car	1992	0312462	0811482	08/18/98	MORS	84,000	Fires		Unknown.	
22		Indianapolis	IN				1U1LM101W4NT	Town Car	1992	0312462	0730482	09/23/98	MORS	85,000	Fires		Unknown.	
23		Jackson	MS				1U1LM102W4NT	Town Car	1992	0312462	0821482	07/31/98	MORS	88,000	Fires		Unknown.	
24		St. Matthews	LA				1U1LM103W4NT	Town Car	1992	0312462	0513482	01/21/99	MORS	88,000	Fires		Unknown.	
25		Port St. Lucie	FL				1U1LM104W4NT	Town Car	1992	0312462	0800482	01/02/99	MORS/VOC	61,000	Fires		Unknown.	
26		Orlando	FL				1U1LM105W4NT	Town Car	1992	0312462	0416482	04/17/98	MORS	1	Fires		Unknown.	

**1992-93 LINCOLN TOWN CAR  
UNDERHOOD FIRES**

PE98-055

NO.	OWNER NAME	ADDRESS	CITY	ZIP	TELEPHONE	STATE	CODE	NUMBER	VIN	MODEL	YEAR	MODEL	BUILD	SALE	REPORT	REPORT	ISSUE	REPORTED	Possible Problem Description
27	Bayliss		TX			ILNLMB2W2NY			1LNLMB2W2NY	Town Car	1992	Town Car	1000841	03/03/92	04/17/94	MORS	37,000	FIRE	Unknown.
28	Beverly Hills		CA			ILNLMB2W2NY			1LNLMB2W2NY	Town Car	1992	Town Car	0241883	09/12/92	08/14/93	MORS	125	FIRE	Unknown.
29	New Iberia		LA			ILNLMB2W2NY			1LNLMB2W2NY	Town Car	1992	Town Car	1011461	11/14/91	01/12/93	MORS	18,000	FIRE	Unknown.
30	Brownsville		TX			ILNLMB2W2NY			1LNLMB2W2NY	Town Car	1992	Town Car	0316552	07/24/92	04/04/97	MORS	64,000	FIRE	Unknown.
31	Rapids		FL			ILNLMB2W2NY			1LNLMB2W2NY	Town Car	1992	Town Car	0520293	08/10/92	12/23/96	MORS	53,000	FIRE	Engine compartment, gas lines.
32	Reynold		GA			ILNLMB2W2NY			1LNLMB2W2NY	Town Car	1992	Town Car	0326503	04/10/92	09/26/93	MORS	28,000	FIRE	Unknown.
33	Minot		IL			ILNLMB2W2NY			1LNLMB2W2NY	Town Car	1992	Town Car	0722882	05/17/92	10/12/95	MORS	58,212	FIRE	Brakes.
34	Spokane		NY			ILNLMB2W2NY			1LNLMB2W2NY	Town Car	1992	Town Car	0320592	04/10/92	07/08/93	MORS	11,000	FIRE	Brakes.
35	Creston		TX			ILNLMB2W2NY			1LNLMB2W2NY	Town Car	1992	Town Car	0504880	03/20/92	11/23/97	MORS	72,000	FIRE	Unknown.
36	Vicksburg		TX			ILNLMB2W2NY			1LNLMB2W2NY	Town Car	1992	Town Car	0500982	08/22/92	08/01/97	MORS	84,000	FIRE	Fire started above the air intake.
37	Sonoma		KY			ILNLMB2W2NY			1LNLMB2W2NY	Town Car	1992	Town Car	0718882	07/14/92	08/26/98	MORS	1	FIRE	Engine compartment.
38	Orchardwood		MS			ILNLMB2W2NY			1LNLMB2W2NY	Town Car	1992	Town Car	0522882	05/14/92	05/04/98	MORS/VOO	67,884	FIRE	Wiring harness to engine compartment.
39	Holiday		FL			ILNLMB2W2NY			1LNLMB2W2NY	Town Car	1992	Town Car	0722782	12/30/92	07/29/98	MORS	47,500	FIRE	Motor.
40	Baldwin		TX			ILNLMB2W2NY			1LNLMB2W2NY	Town Car	1992	Town Car	1020882	08/21/92	12/07/98	MORS	120,000	FIRE	Under the hood - cold cold, pressure sensor for the ABS.
41	Fernandina		FL			ILNLMB2W2NY			1LNLMB2W2NY	Town Car	1992	Town Car	0718882	04/10/92	05/05/98	MORS	1	FIRE	Unknown.
42	E. Amherst		NY			ILNLMB2W2NY			1LNLMB2W2NY	Town Car	1992	Town Car	1021882	08/17/92	05/21/97	MORS	90,000	FIRE	Under the hood.
43	Washington		NC			ILNLMB2W2NY			ILNLMB2W2NY	Unknown	1992	Unknown	Unknown	12/08/97	MORS	56,000	FIRE	Under the hood.	
44	Metz		FL			ILNLMB2W2NY			ILNLMB2W2NY	Town Car	1992	Town Car	1111882	12/05/92	01/03/97	MORS	46,000	FIRE	Under the car.
45	Boca Raton		FL			ILNLMB2W2NY			ILNLMB2W2NY	Town Car	1992	Town Car	0722882	08/14/92	12/03/97	MORS	47,000	FIRE	Under the engine.
46	Forest Hills		NY			ILNLMB2W2NY			ILNLMB2W2NY	Town Car	1992	Town Car	1204881	12/04/91	03/13/98	MORS	1	FIRE	Electrical short.
47	Glendale		KS			ILNLMB2W2NY			ILNLMB2W2NY	Town Car	1992	Town Car	0827881	09/18/91	02/20/97	MORS	88,000	FIRE	Frost suspension.
48	Eden		OH			ILNLMB2W2NY			ILNLMB2W2NY	Town Car	1992	Town Car	0414882	08/18/92	11/01/98	MORS/VOO	120,000	FIRE	Ignition or electrical system.
49	Edens		GA			ILNLMB2W2NY			ILNLMB2W2NY	Town Car	1992	Town Car	0221882	03/10/92	04/26/98	MORS	43,007	FIRE	Unknown.
50	Kansas City		MO			ILNLMB2W2NY			ILNLMB2W2NY	Town Car	1992	Town Car	0803881	08/18/92	10/06/98	MORS	73,000	FIRE	Electrical system.
51	Houston		TX			ILNLMB2W2NY			ILNLMB2W2NY	Town Car	1992	Town Car	0527881	11/02/91	04/26/98	MORS	68,000	FIRE	Electrical.
52	Lev's Garage		MD			ILNLMB2W2NY			ILNLMB2W2NY	Town Car	1992	Town Car	1022881	11/14/91	05/06/98	MORS	71,000	FIRE	Brake system sensor.

8713 7765

**1992-93 LINCOLN TOWN CAR  
UNDERHOOD FIRES**

PE98-055

NO.	OWNER NAME	ADDRESS	CITY	STATE	ZIP CODE	TELEPHONE NUMBER	VIN	MODEL	BUILD	SALE	REPORT DATE	REPORT TYPE	ISSUE	REPORTED	Possible Problem Description	
53	Jensen Beach		FL				1LNLM61WVNY	1992	Town Car	12/11/91	01/14/92	03/19/98	MORS/ VOO	70,000	Fire	Electrical.
54	Neodesha		KS				1LNLM61WVNY	1992	Town Car	04/25/92	07/11/92	01/19/98	MORS/ VOO	88,700	Fire	Unknown.
55	Stiles		LA				1LNLM61WVNY	1992	Town Car	04/18/92	05/02/92	12/09/97	MORS/ VOO	80,000	Fire	Electrical short.
56	West Palm Beach		FL				1LNLM61WVNY	1992	Town Car	01/22/92	02/11/92	10/14/97	MORS	75,000	Fire	Scratches.
57	Baytown		TX				1LNLM61WVNY	1992	Town Car	08/16/92	04/01/93	06/09/97	MORS/ VOO	87,000	Fire	Electrical problem.
58	Austin		TX				1LNLM61WVNY	1992	Town Car	05/05/92	08/01/92	08/28/97	MORS	53,000	Fire	Scratches.
59	Ledyard		TX				1LNLM61WVNY	1992	Town Car	12/17/91	04/23/92	04/18/97	MORS	105,000	Fire	Unknown.
60	Van Pelt		IL				1LNLM61WVNY	1992	Town Car	12/05/91	01/20/92	06/25/97	MORS	95,000	Fire	Left front tire.
61	Houston		TX				1LNLM61WVNY	1992	Town Car	06/05/92	11/02/92	07/09/97	MORS	80,000	Fire	Unknown.
62	Coldwater		FL				1LNLM61WVNY	1992	Town Car	05/20/92	08/29/92	06/23/97	MORS	38,000	Fire	Unknown.
63	Cocoa Beach		FL				1LNLM61WVNY	1992	Town Car	08/19/91	02/04/91	06/18/97	MORS/ VOO	70,000	Fire	Left front wheel area.
64	Dallas		TX				1LNLM61WVNY	1992	Town Car	04/03/92	04/21/92	05/03/97	MORS	95,000	Fire	Engine.
65	Lewisburg		VA				1LNLM61WVNY	1992	Town Car	04/27/92	05/13/92	04/30/97	MORS	111,000	Fire	Unknown.
66	Houston		TX				1LNLM61WVNY	1992	Town Car	04/16/92	05/01/92	03/07/97	MORS	100,000	Fire	Under the hood.
67	Leeds		VA				1LNLM61WVNY	1992	Town Car	08/03/91	11/05/91	08/18/95	MORS	70,000	Fire	Unknown.
68	Memphis		TN				Unknown	1992	Unknown	Unknown	Unknown	02/03/97	MORS	1	Fire	Under the hood.
69	Unknown		WA				1LNLM61WVNY	1992	Town Car	05/04/92	08/20/92	04/21/97	MORS	87,000	Fire	Electrical short.
70	Massapequa		LA				1LNLM61WVNY	1992	Town Car	07/01/92	08/01/92	10/24/97	MORS	80,000	Fire	Electrical.
71	Mount Holly		NJ				1LNLM61WVNY	1992	Town Car	10/13/92	12/20/92	04/08/97	MORS	85,000	Fire	Electrical.
72	West Columbia		SC				Unknown	1992	Unknown	Unknown	Unknown	03/03/94	MORS	8,000	Burned	Brakes.
73	Canton		GA				1LNLM61WVNY	1992	Town Car	08/23/92	09/11/92	04/21/97	MORS	84,000	Fire	Catalytic converter.
74	Quinton		DK				1LNLM61WVNY	1992	Town Car	03/10/92	03/28/92	07/02/97	MORS/ VOO	118,000	Fire	Spark plug wires.
75	West Beach		FL				1LNLM61WVNY	1992	Gr. Mar.	04/25/92	05/08/92	05/11/98	COIS	80,000	Fire	Decelerator pedal.
76	Unknown		WA				1LNLM61WVNY	1992	Town Car	11/25/91	12/27/91	Unknown	VOO	Unknown	Fire	Unknown.
77	Unknown		WA				1LNLM61WVNY	1992	Town Car	05/20/92	08/20/92	Unknown	VOO	Unknown	Fire	Unknown.
78	Unknown		WA				1LNLM61WVNY	1992	Town Car	07/16/92	08/21/92	Unknown	VOO	Unknown	Fire	Unknown.

3713 7756

1992-93 LINCOLN TOWN CAR  
UNDERHOOD FIRES

PES9-056

NO.	OWNER NAME	ADDRESS	CITY	STATE	ZIP CODE	TELEPHONE NUMBER	VIN	MODEL	YEAR	BUILD DATE	SALE DATE	REPORT DATE	REPORT TYPE	MILEAGE	REPORTED BY	FIRE	POSSIBLE PROBLEM DESCRIPTION
1	Unknown	MA	MA	MA	Unknown	1UMLM81W2NT		1992	Town Car	04/07/92	06/29/92	Unknown	VOC	Unknown	Fire	Unknown.	
2	Unknown	MA	MA	MA	Unknown	1UMLM81W2NY		1992	Town Car	08/05/92	08/18/92	Unknown	VOC	Unknown	Fire	Unknown.	
3	Unknown	MA	MA	MA	Unknown	1UMLM81W2NT		1992	Town Car	08/17/92	08/21/92	Unknown	VOC	Unknown	Fire	Unknown.	
4	Unknown	MA	MA	MA	Unknown	1UMLM81W2NY		1992	Town Car	04/27/92	05/13/92	Unknown	VOC	Unknown	Fire	Unknown.	
5	Unknown	MA	MA	MA	Unknown	1UMLM81W2PVY		1992	Town Car	08/05/92	08/22/92	Unknown	VOC	Unknown	Fire	Unknown.	
6	Unknown	MA	MA	MA	Unknown	1UMLM81W2PVY		1992	Town Car	08/18/92	07/19/92	Unknown	VOC	Unknown	Fire	Unknown.	
7	Unknown	MA	MA	MA	Unknown	1UMLM81W2PY		1992	Town Car	08/26/92	08/29/92	Unknown	VOC	Unknown	Fire	Unknown.	
8	Unknown	MA	MA	MA	Unknown	1UMLM81W2PY		1992	Town Car	04/06/92	05/04/92	Unknown	VOC	Unknown	Fire	Unknown.	
9	Unknown	MA	MA	MA	Unknown	1UMLM81W2PY		1992	Town Car	10/26/92	11/04/92	Unknown	VOC	Unknown	Fire	Unknown.	
10	Unknown	FL	MA	MA	Unknown	1UMLM81W2PY		1992	Town Car	02/22/92	05/17/92	08/01/92	VOC	Unknown	Fire	Engine.	
11	Unknown	MA	MA	MA	Unknown	1UMLM81W2PY		1992	Town Car	05/15/92	06/03/92	10/01/92	VOC	Unknown	Fire	Underhood.	
12	Unknown	TX	MA	MA	Unknown	1UMLM81W2WVY		1992	Town Car	08/26/92	08/21/92	Unknown	VOC	Unknown	Fire	Engine compartment.	
13	Unknown	TX	MA	MA	Unknown	1UMLM81W2PVY		1992	Town Car	08/18/92	08/14/92	11/04/92	VOC	Unknown	Fire	Engine compartment.	
14	Unknown	TX	MA	MA	Unknown	1UMLM81W2PY		1992	Town Car	11/24/92	12/01/92	11/04/92	VOC	Unknown	Fire	Engine compartment.	
15	Unknown	NY	MA	MA	Unknown	1UMLM81W2PY		1993	Town Car	11/03/92	11/30/92	08/01/92	VOC	Unknown	Fire	Engine compartment.	
16	Unknown	CA	MA	MA	Unknown	1UMLM81W2PY		1993	Town Car	10/13/92	10/23/92	02/01/92	VOC	Unknown	Fire	Underhood.	
17	Unknown	FL	MA	MA	Unknown	1UMLM81W2NT		1992	Town Car	07/15/92	11/26/92	11/04/92	VOC	Unknown	Fire	Underhood.	
18	Unknown	MA	MA	MA	Unknown	1UMLM81W2WVY		1992	Town Car	08/24/92	08/03/92	10/01/92	VOC	Unknown	Fire	Underhood.	
19	Unknown	TX	MA	MA	Unknown	1UMLM81W2PY		1992	Town Car	08/24/92	07/13/92	10/01/92	VOC	Unknown	Fire	Engine compartment.	
20	Unknown	MA	MA	MA	Unknown	1UMLM81W2PY		1992	Town Car	09/16/92	03/22/92	08/01/92	VOC	Unknown	Fire	Engine.	
21	Unknown	MA	MA	MA	Unknown	1UMLM81W2PY		1993	Town Car	08/03/92	10/08/92	08/01/92	VOC	Unknown	Fire	Engine.	
22	Unknown	MA	MA	MA	Unknown	1UMLM81W2WVY		1992	Town Car	08/13/92	07/24/92	01/01/92	VOC	Unknown	Fire	Engine compartment.	
23	Unknown	MA	MA	MA	Unknown	1UMLM81W2NT		1992	Town Car	08/24/92	08/13/92	05/01/92	VOC	Unknown	Fire	Leak fuel sender tank.	
24	Unknown	TX	MA	MA	Unknown	1UMLM81W2PY		1992	Town Car	11/21/91	02/03/92	05/01/92	VOC	Unknown	Fire	Engine compartment.	
25	Unknown	FL	MA	MA	Unknown	1UMLM81W2PY		1992	Town Car	04/05/92	05/07/92	10/01/92	VOC	Unknown	Fire	Engine compartment.	
26	Unknown	MA	MA	MA	Unknown	1UMLM81W2WVY		1992	Gr. Vans	08/27/91	08/18/91	08/01/92	VOC	Unknown	Fire	Brake booster.	

3713 7757

1992-93 LINCOLN TOWN CAR  
UNDERHOOD FIRES

PEM-055

NO.	OWNER NAME	ADDRESS	CITY	STATE	ZIP	TELEPHONE	NUMBER	VIN	MODEL	BUILD	SALE	REPORT	REPORT	ISSUE	Possible	PROBLEM DESCRIPTION	
101	Unknown	Unknown	Unknown	FL	N/A	Unknown	2MECMWYHNC	[REDACTED]	1992	Grand Marquis	030382	05/29/92	06/01/93	VOD	Unknown	Fires	Under hood.
102	Unknown	Unknown	Unknown	FL	N/A	Unknown	UHLMB2WNY	[REDACTED]	1992	Town Car	05/04/92	18/03/92	08/01/93	VOD	Unknown	Fires	Engine compartment.
103	Unknown	Unknown	Unknown	FL	N/A	Unknown	UHLMB2WNY	[REDACTED]	1993	Town Car	04/03/92	05/12/92	07/01/93	VOD	Unknown	Fires	Engine compartment.
104	Unknown	Unknown	Unknown	FL	N/A	Unknown	UHLMB2WNY	[REDACTED]	1992	Town Car	03/20/92	04/16/92	12/01/93	VOD	Unknown	Fires	Left edge of hood and fender
105	Unknown	Unknown	Unknown	NC	N/A	Unknown	1LNLLB2WNY	[REDACTED]	1992	Town Car	05/04/92	08/03/92	08/01/93	VOD	Unknown	Fires	Under hood.
110	Unknown	Unknown	Unknown	FL	N/A	Unknown	1LNLLB2WNY	[REDACTED]	1993	Town Car	08/19/92	07/02/92	11/01/93	VOD	Unknown	Fires	Under hood.
111	Unknown	Unknown	Unknown	FL	N/A	Unknown	SLHLBBWNY	[REDACTED]	1992	Town Car	04/15/92	04/28/92	08/01/93	VOD	Unknown	Fires	Under hood.

3713 7768

1992/93 Lincoln Town Car Parts Lists - NHTSA Inquiry PE98-055

To Concern: \_\_\_\_\_ Alert: \_\_\_\_\_ [FuncRelease]

Sel C/F Part: \_\_\_\_\_ Actv CPSC= Seq Release: \_\_\_\_\_ IS CUS Date: \_\_\_\_\_

Brake Booster/Master Cylinder Assy.

X - F F1VC 2B195 AE NC00 060701 000 NC00E10391062000R P IR 94/03/29  
<BSTR.&MSTR.CYL.ASY.BRK...> <.....>

- CR Description: notice issued to identify Mexican grand mequin chassis parts as balance out, since NAAO is responsible for this vehicle for the 1995 model year.

O - F F1VC 2B195 BA NC00 060701 000 NC00E10041053000R P IR 89/11/11  
<BSTR.&MSTR.CYL.ASY.BRK...> <.....>  
• CR Description: release 200 tandem booster with passenger compartment air intake (pcai).

- F F1VC 2B195 B2 NC00 060701 000 NC00I10010977026IR P IR 89/05/22  
<BSTR.&MSTR.CYL.ASY.BRK...> <.....>  
• CR Description: initial release-abs booster & master cylinder

- F F1VC 2B195 B2 NC00 060701 001 NC00E00444499092IR P IR 89/09/22  
<BSTR.&MSTR.CYL.ASY.BRK...> <.....>  
• CR Description: Usage Change

O - F F1VC 2B195 CA NC00 060701 000 NC00E10048319001IR P IR 90/02/14  
<BSTR.&MSTR.CYL.ASY.BRK...> <.....>

- CR Description: Release a booster and master cyl assy for abs vehicles with a bracket for attaching the 42 pin electrical connector fln. This change was requested by b & a to eliminate one in place part and save the labor for assembling the bracket to the Booster. Release the bracket for service.

X - F F1VC 2B195 CB NC00 060701 000 NC00E10057809001IR P IR 90/03/28  
<BSTR.&MSTR.CYL.ASY.BRK...> <.....>

- CR Description: Revise The Hole Pattern In Bracket f1vc-14536-Ba To Be - Compatible With Wiring Connector Changes. Revise The Abs Booster & Master Cylinder Assy. F1vc-2b195-Cb To Show The New Bracket. Revise The Bracket Attaching Point So That It Is Secured Under The Inboard Master Cylinder Attachment Nut.

X - F F1VC 2B195 CC NC00 060701 000 NC00E10070190000R P IR 90/05/04  
<BSTR.&MSTR.CYL.ASY.BRK...> <.....>

- CR Description: Complaints of vehicle pull while braking exist for town car, em53, taurus/sable and continental. This is due to a master cylinder induced pressure differential in the two circuits of the brake system. This pressure difference can be made nearly zero by using a "linked piston" master cylinder design. This change is only applicable to cars with abs and is a \$1.08 piece cost increase. This change will reduce town car and em53 warranty by 4c/1000 (\$1.05/veh) and continental by 8c/1000 (\$1.23/veh). Taurus/sable (12% abs) warranty will not be measurably affected. Release the following booster and master cylinder assys. Which all use the same master cylinder f1vc-2afl32-aa. Town car and em53 use f1vc-2b195-cc, taurus/sable and continental use f1dc-2b195-ab, taurus ab uses f1dc-2b195- bb.

X - F F1VC 2B195 CD NC00 060701 000 NC00E10092919000IR P IR 90/10/03  
<BSTR.&MSTR.CYL.ASY.BRK...> <.....>

- CR Description: The low pressure brake fluid hose connecting the antilock brake master cylinder reservoir to the hydraulic control unit reservoir is too long. The routing of the hose will be improved by reducing the length from 500+/-5 to 475+/-5.

O - F F1VC 2B195 CE NC00 060701 000 NC00E10084260000R P IR 90/10/24  
<BSTR.&MSTR.CYL.ASY.BRK...> <.....>

- CR Description: modify connector terminals on brake fluid reservoir cap. The modifications are reduce the gage thickness and increase The lead-in chamber of the subject terminals. Previous not affected. The part which is being modified is a common part used on Both the dn-5 and fn-9 cartines also. There are no problems in changing these cartines as well. They get the improved Connector free.

X - F F1VC 2B195 CP NC00 060701 000 NC00E10104848000R P IR 90/11/28  
<BSTR.&MSTR.CYL.ASY.BRK...> <.....>

- CR Description: In ABS brake booster and master cylinder assembly, revise low pressure hose storage position for shipping. Also delete the shipping cap from the check valve located in the booster to ease assembly operation and reduce cost. PMVSS is not affected.

62-83  
SUMMARIES BY

FRIDAY-NON draft

ANT LEADING ELECTRICAL  
80 spd abs master diag  
78 thermal

Part Name & Number  
Description of change

To Concern: \_\_\_\_\_ Alert: \_\_\_\_\_ If UncnclReleasw

Sel C/P Part: \_\_\_\_\_ Acty CPSC: Seq Release: \_\_\_\_\_ IS CUS Date: \_\_\_\_\_

F F1VC 2B195 CG NC00 060701 000 NC00E10300678000IR P IR 93/05/20

&lt;BSTR.&amp;MSTR.CYL.ASY.BRK...&gt;&lt;.....&gt;

- CR Description: incorporate new bracket (f3ac 14536 aa) into booster master cylinder.

F F1VC 2B195 DA NC00 060701 000 NC00E10070190000IR P IR 90/06/04

&lt;BSTR.&amp;MSTR.CYL.ASY-BRK...&gt;&lt;.....&gt;

- CR Description: Complaints of vehicle pull while braking exist for town car, en53, taurus/sable and continental. This is due to a master cylinder induced pressure differential in the two circuits of the brake system. This pressure difference can be made nearly zero by using a "linked piston" master cylinder design. This change is only applicable to cars with abs and is a \$1.08 piece cost increase. This change will reduce town car and en53 warranty by 4c/1000 (\$1.05/veh) and continental by 8c/1000 (\$1.23/veh). Taurus/sable (12% abs) warranty will not be measurably affected. Release the following booster and master cylinder asy's. Which all use the same master cylinder f1vc-2a032-aa. Town car and en53 use f1vc-2b195-cd, taurus/sable and continental use f1dc-2b195-ab, taurus sho uses f1dc-2b195- bb.

F F1VC 2B195 DB NC00 060701 000 NC00E10084269000IR P IR 90/10/24

&lt;BSTR.&amp;MSTR.CYL.ASY-BRK...&gt;&lt;.....&gt;

- CR Description: modify connector terminals on brake fluid reservoir cap. The modifications are reduce the gage thickness and increase the lead-in chamfer of the subject terminals. FMVSS not affected. The part which is being modified is a common part used on Both the do-5 and fh-9 carlines also. There are no problems in changing these carlines as well. They get the improved Connector free.

F F1VC 2B195 DC NC00 060701 000 NC00E10104848000IR P IR 90/11/28

&lt;BSTR.&amp;MSTR.CYL.ASY-BRK...&gt;&lt;.....&gt;

- CR Description: In ABS brake booster and master cylinder assembly, revise low pressure hose storage position for shipping. Also delete the shipping cap from the check valve located in the booster to ease assembly operation and reduce cost. FMVSS is not affected.

F F1VC 2B195 DD NC00 060701 000 NC00E10079779020IR P IR 92/08/27

&lt;BSTR.&amp;MSTR.CYL.ASY-BRK...&gt;&lt;.....&gt;

- CR Description: 1992 April record change for brakes. 1. En-f3ic-2b109-aa -- completed ea-brake tube - initially released incomplete. 2. F3ac-90433-ab -- tolerances revised as manufactured,i.e. +/- 0.03 to +/- 0.3; Id. 0.05 to +/- 0.12. 3. Remove item #3, revisions done on other notice 4. F1vc-2b195-cg/f1vc-2b195-dd/f1vc-2a032-aa/f3dc-2a032-aa: release supplier drawing showing master cylinder reduction-control valve. 5. F3dc-2780-be -- revised drawing reflecting change in main rivet on parking brake control assembly. 6. F3ac-2c026-aa -- replace rear rotor file drawing with update (no change). 7. F3lc-2c287-cb -- brake fluid tube assembly - incorrect flare is shown at pt c20. Revise drawing to show the flare for pt c20. 8. Remove items #8 & #9. These revisions were completed on other notice. 9. 10. F3lc-2c334-aa & f3lc-2c333-aa -- change coul mounting torque from 7 - 9 nm to 2.5 +/- 0.4 nm. 11. F3lc-2c296-be & f3lc-2c296-aa -- add 3.6mm dimension to last change: anti-rotation clip & revise wrench block stud hole hex dimensions to prevent plastic build up in stud threads. 12. F3ac-2c026-ab -- change in location of the part number stamp. 13. F3dc-2c299-ab & f3dc-2b664-ab -- added specification for vibration and a not specifying that certain dimensions are before coating.

C F1VC 2005 AA NC00 060701 000 NC00E10042672000IR P IR 89/11/17

&lt;BSTR.ASY-BRK...&gt;&lt;.....&gt;

- CR Description: Revise booster check valve location from the 2:00 position to the 11:00 position. New part number for the booster and master cylinder assy. Will be f1vc-2b195-ab and the booster alone will be f1vc-2005-ab. These parts will also be used on en53 non-abs cars. Tooling cost is \$1700, piece cost change is zero and there is no affect on r1000 or lgw/1000. Parts will be available for en53 vp build in jan. 1990. does not affect compliance with regulations --brake dept.

C F1VC 2005 AB NC00 060701 000 NC00E10107234042IR P IR 93/05/20

&lt;BSTR.ASY-BRK...&gt;&lt;.....&gt;

- CR Description: Initial release of brk rotors,shield & calipers

C F1VC 2005 AC NC00 060701 000 NC00E10079779040IR P IR 94/01/03

&lt;BSTR.ASY-BRK...&gt;&lt;NON.ABS...&gt;

- CR Description: Initial release of brk rotors,shield & calipers. 1. If4zc-060600-04: add unique torque for colnt fit brk hs 2. F3dc-2c189-aa; add supplier info 3. B5dc-9a474-ba; redraw 4. F3oc-2078/2b557-ab; redraw 5. F6cc-2530/2531-ab; drawing revision 6. F4ec-2003-ac; drawing revisions 7. F4dc-2c204-bb; redraw to final level of release 8. F2oc-2c205-ab:f3lc-2c190-ac:f4lc-2c190-aa: revise to facilitate manufacturing 9. F4ac-1125-aa; drawing revision 10. F2ac-2005/2b195-ha:f1vc-2005-ac; redraw,revise labels 11. F1ac-1107-aa: show optional design 12. F4ec-2267/2268-aa:f4ac-2267/2268-bb; add wax to tube nut 13. F6xc-2c360-aa; revise drwg to facilitate manufacturing

C F1VC 2005 BA NC00 060701 001 NC00E10640585005IR P IR 98/09/03

- CR Description: Blanket concern to support wets clean-up actions.

## 1992/93 Lincoln Town Car Parts Lists - NHTSA Inquiry PE98-055

draft

To Concur: \_\_\_\_\_ Alert: \_\_\_\_\_ IfunelRelease  
 Sel C/F Part: \_\_\_\_\_ Acty CPSC Seq Release: \_\_\_\_\_ IS CIS Date: \_\_\_\_\_

- F F0VC 2005 AA NC00 060701 000 NC00E10032035000IR P IR 89/09/08  
 <BSTR.ASY-BRK> <SERVICE ONLY>

- CR Description: Release booster & master ass'y using teves grease spec. # 446 06 acu n 10636. Booster & master cyl. Ass'y's built with new grease to be identified with blue dab of paint in the 12:00 position on the booster front shell. For a min. of 60 days from start of production. 1st requirement-- material test of new grease only.

## Master Cylinder &amp; Pressure Control Valve Assy -

- C F1VC 2C156 AA NC00 060701 000 NC00E10348036000IR P IR 93/11/18  
 <CYL.&PRESS.CONTR.VLV.ASY-BR> <NON.ABS>

- CR Description: replace the Fmc-2b195-bb booster master cylinder ass'y with the Fmc-2b195-ba starting job #1 94. ending with job #1 95 also replace the fmc-2a040-ba tube with fmc-2a040-aa for job #1 94 ending with job #1 95. This will be the same as the 93 model year booster, master cylinder, brake tubes.

## TUBE.ASY-FUEL.RETURN.&amp; BRAKE

- F F1VC 9L291 AA NC00 100103 000 NC00E10019802000IR P IR 89/06/26  
 <TUBE.ASY-FUEL.RETURN.& BRAKE> <.....>

- CR Description: the fuel and brake line headers must be revised to acc utomodate the new rear brake tube (-2367-). The action required includes revising the rear end of the vapor tube 1/2 inch and shortening the inboard brake tube. Sys gen components removed.... 10/25/89 sys gen components removed.... 01/04/90

- F F1VC 9L291 AB NC00 100103 000 NC00E100277030000IR P IR 89/09/06  
 <TUBE.ASY-FUEL.RETURN.& BRAKE> <.....>

- CR Description: Hole location for the rear fuel line clip in the kick-up area is not feasible for the frame processing. Revise the design of the subject clip and relocate the frame hole location as required. The new location of the fuel line hole is as follows: x - 4382.0 y - z - 630.0 sys gen components removed.... 12/15/89 sys gen components removed.... 03/04/90 sys gen components removed.... 01/26/90

- F F1VC 9L291 AC NC00 100103 000 NC00E10037380000IR P IR 89/11/27  
 <TUBE.ASY-FUEL.RETURN.& BRAKE> <.....>

- CR Description: (1) the fuel line bundle clip in the rear kick-up area can contact the vehicle body on the 1991 fn-36 due to minimal clearance to the body flange. The subject hole should be moved to 4432.0 - x; 690.0 - z from 4382.5 - x; 630.0 - z on the f1vc-3085-dj frame ass'y. (2) add an additional nylon clip to the fuel line bundle (-91291-) in order to hold the lines clear during body decking. A new hole is required at 4895.0 - x and 548.0 - z. Sys gen components removed.... 90/03/30 sys gen components removed.... 90/05/15 (3) revise the rear routing of the fuel bundle to provide adequate clearance to the body and the fuel tank flange. (4) shorten the steel braided teflon tubing on supply and return lines by 20 mm. (5) revise routing to provide clearance to the (a) seat belt bolt, (b) rear engine mount, (c) front and rear torque box. (6) revise the -9e294-fuel vapor crossover & front brake tube to avoid contact with the knee brace (ref. Concern # c10023180). (7) design and release a new fuel vapor c/o and front brake bundle (-9e294) for the the non-abs 1991 fn-36. (8) release the f0vc-5a297-ab air line in the -91291-fuel line bundle. Sys gen components removed.... 90/05/17

- F F1VC 9L291 AD NC00 100103 000 NC00E10048573000IR P IR 90/01/30  
 <TUBE.ASY-FUEL.RETURN.& BRAKE> <.....>

- CR Description: Last Change: The following action is required for the -91291- and -9e294- fuel bundles to resolve clearance issues: 1. Review fuel (ret & supp. -91291-) line and brake line routing in order to : a) Improve clearance along center rail, torque box, and rear suspension (abs and non-abs). B) provide an adequate clearance window between the fuel lines and brake lines for installation of the shift cable and bracket assembly (abs and non-abs). C) eliminate contact and inadequate clearance between the brake lines from the master cylinder and the fuel lines (non-abs only). 2. Revise the -9e294 crossover vapor line routing to eliminate contact to the shift cable frame attachment clip (abs and non-abs). Sys gen components removed.... 90/07/10 also, to facilitate bba assembly process, change the rear hole of the fuel filter bracket (-9b072-) to a slot at a \$3200 tooling cost and no piece cost increase. Sys gen components removed.... 90/08/21 the clip f0vc-9a317-aa has been carried over and released for all 1991 fn-36 vehicles. The clip is no longer necessary for 1991 and should be deleted for a \$26 piece cost and bba labor save on two clips per vehicle.

- F F1VC 9L291 AE NC00 100103 000 NC00E10048573002IR P IR 90/02/21  
 <TUBE.ASY-FUEL.RETURN.& BRAKE> <.....>

- CR Description: the -91291- and -9e294- fuel bundles released with the previous notice supplement #10048573-000 were reviewed on an updated vehicle by fuel system engineering and it was discovered that additional clearance issues must be resolved. Therefore the following action is required: revise -91291- and -9e294- abs and non-abs fuel bundles to provide adequate clearance to rear seat belt bracket, the floor pan, center rail, and the rear frame. The 20k us tooling is for the addition of a new flat clip for the -91291- bundle. Sys gen components removed.... 90/07/10 sys gen components removed.... 90/08/21

To Concern: \_\_\_\_\_ Alert: \_\_\_\_\_ [Func|Release]

Sel C/F Part: \_\_\_\_\_ Acty CPSC= Seq Release= IS CIS Date=

- F F1VC 9L291 AF NC00 100103 000 NC00E10048573007IR P IR 90/03/20

&lt;TUBE.ASY-FUEL.RETURN.&amp; BRAKE&gt; &lt;.....&gt;

- CR Description: The following action is required for the -9L291- air line assembly. F1vc-5a897-aa will replace f1vc-5a897-ab which is p/n to the fuel/brake tube bundle -9L291-. This change will result in a \$ 0.30 per piece cost increase and a tooling charge of \$ 13,000.00. This change is a result of the new lh fender apron requiring re-routing of the air suspension air line along the frame rail requiring the following changes: \* add 76 mm's of air line tubing. \* add 100 mm's of cvt protection tubing under the brake distribution valve, located on the lh frame side rail. \* add (1) f1vc-9279-aa clip and reposition two existing clips to accommodate new routing along the frame rail. Sys gen components removed.... 90/08/21 notice resolution \* release new air line routing along lh frame rail and revise retension of the air line assembly. \* delete air line assembly (f1vc-5a897-ab from -9L291- \* add new air line assembly f1vc-5a897-aa to -9L291-. \* -9L291- becomes f1vc-9L291-ag

- F F1VC 9L291 AG NC00 100103 000 NC00E10066976000IR P IR 90/03/30

&lt;TUBE.ASY-FUEL.RETURN.&amp; BRAKE&gt; &lt;.....&gt;

- CR Description: Re-routing of the fn-36 -9L291- fuel/brake bundle will be accomplished as a cx change. The marked up parts list and prints show the changes; which are as follows: 1) F1vc-9L291-ab will replace f1vc-9L291-ag ; which involves re-routing of the fuel and brake lines to provide improved clearance to the steering shaft coupling. 2) deletion of one of the f1vc-9f276-aa. Note: one of the f1vc-9f276-aa is still required p/n to the fuel/brake bundle at the rear. 3) a new metal clip is to be added p/n to the -9L291 toward the front of the bundle to electrically ground and provide support in the fuel supply and return lines. A m8 bolt will be used to secure the clip.

- F F1VC 9L291 AH NC00 100103 000 NC00E10066976000IR P IR 90/04/10

&lt;TUBE.ASY-FUEL.RETURN.&amp; BRAKE&gt; &lt;.....&gt;

- CR Description: 1991 fn-36 phase ii functional build revealed the following concerns with the fuel/brake bundle and the crossover tubes; sys gen components removed.... 90/08/21 -9L291- fuel/brake bundle 1) vapor tube/hose connection assembly problem. 2) clip location problem (bundle quality problem) 3) air line location problem (bundle qty probm) 4) air line clip insertion problem (bundle design) -9a294- vapor/brake crossover assy 1) vapor tube interferes with brake line connection on abs equipped car. 2) vapor tube to shifter cable clip close (3.2mm as designed). 3) frame change necessitates line change at clip b 4) push pin difficult to install. corrective action on the afore mentioned concerns will be: -9L291- \* cx change to produce a f1vc-9L291-aj bundle to replace the f1vc-9L291-ab bundle. This bundle will have a rerouted fuel vapor tube and the details will call out the location of bundle straps to ensure air line location. \* bundy has been informed of the clip location quality problem. \* bundy has been informed of the air line insertion concern and has been given direction to modify the clip design to produce similar insertion loads for the 91 fn36 and en33 clips as on current fn36. -9a294- cx change to produce a f1vc-9a294-af and a f1vc-9a294-bd in place of the current f1vc-9a294-ac and f1vc-9a294-bc. The following actions are needed on the new assembly: \* reroute vapor tube to provide improved access to the abs brake line connection (-9L291- to -9a294-) \* reroute vapor and brake tubes to accomodate frame change. \* investigate vapor tube to shifter cable clip clearance; a shorter vapor hose used to connect the -9L291- to the -9a294- appears to be needed to avoid having the vapor hose from pushing the tubes into the shifter clip clearance zone. \* release push pin 388577-s in place of the currently released push pin n805635-a to attach the center of the -9a294- to the #2 crossmember.

- F F1VC 9L291 AJ NC00 100103 000 NC00E10069882000IR P IR 90/04/23

&lt;TUBE.ASY-FUEL.RETURN.&amp; BRAKE&gt; &lt;.....&gt;

- CR Description: Add single tube retaining clip, f1vc-9279-aa, to suspension airline stay at 605-mm from end of airline. Move existing clip from 400 mm to 365 mm, from end of airline. 91 fn36 frame drawing to be revised to represent current frame production, including 7.0-7.25 mm dia. Hole which is on the top of the forward lh roll aft of the abs hydraulic unit. Revision to be accomplished on latest chassis monthly record change. Sys gen components removed.... 90/08/21

- F F1VC 9L291 AK NC00 100103 000 NC00E10080356000IR P IR 90/07/03

&lt;TUBE.ASY-FUEL.RETURN.&amp; BRAKE&gt; &lt;.....&gt;

- CR Description: 1991 fn-36 town car : -9L291- fuel/brake bundle revisions concerns raised on the Sp2 build resulted in the following changes to the -9L291- for job #1: 1) redesign of the fuel supply and return line routing at #4 crossmember to improve clearance to the shock absorber mounting washer. 2) redesign of the fuel supply, return, and vapor line routing at the firewall to provide improved clearance to the body. 3) addition of a tube retaining clip to the fuel supply and return lines near the fuel rail to prevent possible nvh concern. 4) adjustment of the number and placement of tie straps for the air suspension air line to insure proper routing and prevent pinching of the air line on frame,body,or tubes.

- F F1VC 9L291 AL NC00 100103 000 NC00E10080356000IR P IR 90/07/03

&lt;TUBE.ASY-FUEL.RETURN.&amp; BRAKE&gt; &lt;.....&gt;

- CR Description: 1991 fn-36 town car : -9L291- fuel/brake bundle revisions concerns raised on the Sp2 build resulted in the following changes to the -9L291- for job #1: 1) redesign of the fuel supply and return line routing at #4 crossmember to improve clearance to the shock absorber mounting washer. 2) redesign of the fuel supply, return, and vapor line routing at the firewall to provide improved clearance to the body. 3) addition of a tube retaining clip to the fuel supply and return lines near the fuel rail to prevent possible nvh concern. 4) adjustment of the number and placement of tie straps for the air suspension air line to insure proper routing and prevent pinching of the air line on frame,body,or tubes.

To Concern: \_\_\_\_\_ Alert: \_\_\_\_\_ [Func1Release]  
 Sel C/F Part: \_\_\_\_\_ Acty CPSC: Seq Release: \_\_\_\_\_ S CIS Date: \_\_\_\_\_  
 - F FIVC 9L291 AM NC00 100103 000 NC00E10086498000IR P IR 90/08/02  
 <TUBELASY-FUEL.RETURN.& BRAKE> <.....>

- CR Description: revise fuel/brake bundle (9L291) as follows: 1) replace air suspension air line f1vc-5a897-ab with f1vc-5a897-ac. The new air line changes the location of retaining clips and installation tape marks. 2) revise bundle strapping of air line (5a897) to fuel/brake bundle (9L291) by adding bundle strap and modifying the location of existing bundle straps. 3) revise fuel/brake bundle drawing to show air line routing around filter area and provide sections and notes as to specific strapping of air line to bundle. 4) revise location of fuel line clip on #4 crossmember in the p2-f1vc-9L291-al. 5) add engineering spec delta ex-flar-9327-as to complete drawing.

- F FIVC 9L291 AN NC00 100103 000 NC00E10086523000IR P IR 90/08/10  
 <TUBELASY-FUEL.RETURN.& BRAKE> <.....>

- CR Description: the following action necessary to correct air swap air line to frame noise: for fn36: air line assembly f1vc-5a897-ad will replace f1vc-5a897-ac which is pl to fuel/brake tube bundle -9L291- for en53: end item air line assembly f2ac-5a897-ab will replace f2ac-5a897-ac. This change is a result of relocating the suspension air line and revising its retention along the side of the #4 c/member, requiring the following changes: delete tape wrap above "y" connector and replace with double tubing clip with optional construction, to accommodate the new retention along the #4 c/member. B & A processing: fn36 & en53. Revise process sheets to reflect new air line routing and retention along the lh side of the #4 c/member. Fuel/brake bundle: delete air line assy f1vc-5a897-ac from 9L291. Add new air line assy f1vc-5a897-ad to new fuel/brake bundle f1vc-9L291-ac. Sys gen components removed... 90/11/28 \*\*\* this change must be coordinated with frame change supplement.

- F FIVC 9L291 AR NC00 100103 000 NC00E10078761000IR P IR 90/09/17  
 <TUBELASY-FUEL.RETURN.& BRAKE> <.....>

- CR Description: increase in fuel supply and return line length at fuel sender to accommodate modified fuel sender. The increase in line length is to be achieved by increasing the length of tieflex hose. Part numbers will have the suffix bumped from a? To c? And b? To d? For en-53 and a? To b? For fn-36; as follows: f2ac-9L291-ac fuel/brake bundle non-abs en-53 f2ac-9L291-ad fuel/brake bundle abs en-53 ----- f1vc-9L291-ba fuel/brake bundle fn-36. Layouts and detail drawings are required. Note this notice must be processed before notice nc00-e-10072777-000.

- F FIVC 9L291 A3 NC00 100103 000 NC00I10010977019IR P IR 89/05/05  
 <TUBELASY-FUEL.RETURN.& BRAKE> <.....>

- CR Description: initial release-fuel lines & fuel filter assy sys gen components removed.... 10/25/89

- F FIVC 9L291 BA NC00 100103 000 NC00E10091352000IR P IR 90/10/10  
 <TUBELASY-FUEL.RETURN.& BRAKE> <.....>

- CR Description: revise air line to add forth tape mark for installation. Revisions to drawing and layout pending new air line - drawing (air line - 5a897-). Detailed drawings and layouts required. 90/09/28 drawing of air line in air suspension drafting; package issued. \*\*\*\*\* the new -5a897- is to be added to the f1vc-9L291-ba (not hb) and the suffix should be bumped to ca (ie f1vc-9L291-ca is a f1vc-9L291-ac).sys gen components removed... 91/01/29

- F FIVC 9L291 CA NC00 100103 000 NC00E10095356000IR P IR 90/10/19  
 <TUBELASY-FUEL.RETURN.& BRAKE> <.....>

- CR Description: vehicle tryouts with a 4 inch protective sleeve added to the inboard air line routed along the #4 crossmember, proved positive in that the squeak noise previously heard on 4-p vehicles was eliminated. This tryout accepted as resolution from a. Ferguson w/mon q-press sq/fil. Sys gen components removed... 91/03/07 approval is requested to incorporate the following part changes. 1991 fn36 - delete air line assembly f1vc-5a897-ac and advance/release the new part number. - fuel/brake bundle: delete air line assembly f1vc-5a897-ac from -9L291+ bundle assembly. Add new air line assembly to -9L291+ assembly. - air line piece cost \$ 0.06 tooling \$ 3600.00 1992 en53 - delete end item air line assembly f2ac-5a897-ab and advance/release the new part number. - air line piece cost \$ 0.06 tooling \$ 3600.00 timing to incorporate running change at wilson is projected to be week of 901105. Fn36/en53 service not affected. Use/exhaust existing stock.

- F FIVC 9L291 CB NC00 100103 000 NC00E10102784000IR P IR 90/11/16  
 <TUBELASY-FUEL.RETURN.& BRAKE> <.....>

- CR Description: revise -9L291- as follows: for cr c10102784: add a nylon 12 sleeve to the fuel return line between bonds fr10 and fr11; the slit in the sleeve is to POINT upward. (5k tooling ; \$0.40 piece cost c10102784) the above occurs on fn-36 and en-53 for cr c10100320: add a bundle strap to the brake lines, fuel vapor, and fuel supply lines. (0 tooling ; \$0.10 piece cost c10100320) the above occurs on en-53 only.

To Customer: \_\_\_\_\_ Alert: \_\_\_\_\_ [Func/Release]

Sel C/F Part: \_\_\_\_\_ Acty CPSC: Seq Release: \_\_\_\_\_ IS CIS Date: \_\_\_\_\_

- F F1VC 9L291 CC NC00 100103 000 NC00E1012226000IR P IR 91/01/16

&lt;TUBE.ASY-FUEL.RETURN.&amp; BRAKE&gt; &lt;.....&gt;

- CR Description: add the previously deleted rubber protective cover on the fuel lines at the fire wall. This cover consists of 4 inch slit rubber hose secured with two tie straps. The slit is to point to the side of the vehicle as installed. The rubber cover is to extend approx. 0.5 inches below bend number #s ft 3 & ft 5 and 3.5 inches above these bends. Note: hose used for cover to be hypalon hose ese-n2d158-a (same covering used on the flex tube at fuel sender)

- F F1VC 9L291 CD NC00 100103 000 NC00E10124098000IR P IR 91/03/20

&lt;TUBE.ASY-FUEL.RETURN.&amp; BRAKE&gt; &lt;.....&gt;

- CR Description: add a rubber isolator sleeve to the fuel lines at the #4 crossmember and the body reinforcement. The sleeve is to be a slit rubber hose tie strapped to the fuel lines. \*\*\*\* ex drawings released for review by supplier the following fuel/brake bundles are affected: (991 fn-36 F1vc-9l291-cd to become f1vc-9l291-cc 1992 en-53 f2ac-9l291-cr to become f2ac-9l291-cf f2ac-9l291-dd to become f2ac-9l291-d)

- F F1VC 9L291 CE NC00 100103 000 NC00E10124098002IR P IR 91/05/31

&lt;TUBE.ASY-FUEL.RETURN.&amp; BRAKE&gt; &lt;.....&gt;

- CR Description: revise the "T" shaped clip to lower the fuel lines by 5.76 mm. Initial drawing has been completed by wright plastics. \*\*\* the "T" shaped clip is to be added to details without modifying the line location; however the layout should reflect the line movement caused by the clip and line location (see pcd for direction) 91-05-20 \*\*\*\* bundy tubing was kicked off on clip 91-05-13 wixom tryout has shown the "T" shaped clip should be implemented as soon as feasible (manufacturing date of 91-07-29 has been give by the supplier for the clip completion) this notice must follow the ex notice for en-53nc00-e-10139122 ex'd 91-05-21. \*\*\* the parts affected are as follows: fn-36 1991 and 1992 with current fuel rail: f1vc-9l291-ce will advance to f1vc-9l291-cf fn-36 1992 with new fuel rail due fall 91: F2vc-9l291-cc will advance to f2vc-9l291-ab \*\*\*\*\*This notice is to follow nc00-e-10139122-000.

- F F1VC 9L291 CF NC00 100103 000 NC00E10128004005IR P IR 91/07/26

&lt;TUBE.ASY-FUEL.RETURN.&amp; BRAKE&gt; &lt;.....&gt;

- CR Description: replace screw n800369-456 with screw n610857-456. Screw attaches clip-fuel line & brake (9f276) to valve say-brake brake press control (2b091). Torque on the joint is to be 6.8-9.2 nm.

- F F2VC 9L291 AA NC00 100103 000 NC00E10124098002IR P IR 91/05/31

&lt;TUBE.ASY-FUEL.RETURN.&amp; BRAKE&gt; &lt;.....&gt;

- CR Description: CR Description: revise the "T" shaped clip to lower the fuel lines by 5.76 mm. Initial drawing has been completed by wright plastics. \*\*\* the "T" shaped clip is to be added to details without modifying the line location; however the layout should reflect the line movement caused by the clip and line location (see pcd for direction) 91-05-20 \*\*\*\* bundy tubing was kicked off on clip 91-05-13 wixom tryout has shown the "T" shaped clip should be implemented as soon as feasible (manufacturing date of 91-07-29 has been give by the supplier for the clip completion) this notice must follow the ex notice for en-53nc00-e-10139122 ex'd 91-05-21. \*\*\* the parts affected are as follows: fn-36 1991 and 1992 with current fuel rail: f1vc-9l291-ce will advance to f1vc-9l291-cf fn-36 1992 with new fuel rail due fall 91: F2vc-9l291-cc will advance to f2vc-9l291-ab \*\*\*\*\*This notice is to follow nc00-e-10139122-000.

- F P2VC 9L291 AB NC00 100103 000 NC00E10128004000IR P IR 91/07/15

&lt;TUBE.ASY-FUEL.RETURN.&amp; BRAKE&gt; &lt;.....&gt;

- CR Description: release a randified brake prop valve bracket and a clip pls to the fuel tubes. The clip attaches to the bracket with a m-6 self tapping bolt. The clip and bracket are to prevent bending of the fuel lines during assembly. \*\*\*91-06-25 reviewed bracket with brake valve supplier; they are working on both a temporary and permanent change. \* 91-06-26 reviewed clip with fuel line supplier. Bundy is proceeding with tooling for the clip. Clip to be pls to fuel lines. Assembly drawings will be crd'd up.

- F F2VC 9L291 AC NC00 100103 000 NC00E10165200000IR P IR 91/11/16

&lt;TUBE.ASY-FUEL.RETURN.&amp; BRAKE&gt; &lt;.....&gt;

- CR Description: delete f1vc-9f276-ha and (1) n802791-456 due to f2ac-9f276-452 acting as a ground for the fuel portion of the 9f291- bundle. F1vc-9f276-ha was incorporated to create a ground for the lo fuel lines.

- F F2VC 9L291 AD NC00 100103 000 NC00E101806780000IR P IR 92/01/09

&lt;TUBE.ASY-FUEL.RETURN.&amp; BRAKE&gt; &lt;.....&gt;

- CR Description: incorporate the following design changes to improve air line retention to the # 4 crossmember. - Revise double clip above "y" to insure positive retention - add protective tubing to the air line loop above "y" conn fn36 air line; delete f1vc-5a897-af add f2vc-5a897-aa en53 air line; delete f2ac-5a897-ac add f2ac-5a897-ad. clip-double tube delete f1vc-9279-ha add f2ac-9279-aa \*\* fuel portion: 920106 For 1992 - replace f1vc-5a897-af with f2vc-5a897-aa in the f2vc-9l291-ad (fuel return and brake line bundle) For 1993 - replace f1vc-5a897-af with f2vc-5a897-aa in f3vc-9l291-ab (fuel return and brake line bundle)

To Concern: \_\_\_\_\_ Alert: \_\_\_\_\_ IPublicRelease

Sel C/F Part: \_\_\_\_\_ Acty CPSC: Seq Release: \_\_\_\_\_ IS CRIS Date: \_\_\_\_\_

F F2VC 9L291 AE NC00 100103 000 NC00E10180678001R P IR 92/01/21

&lt;TUBE.ASY-FUEL.RETURN.&amp; BRAKE&gt; &lt;.....&gt;

- CR Description: this notice is to support 10180678 (add sheathing or convoluting to the airline (f1vc 5a97 af) just above the "y" connector for protection. Airline is pin to fuel & brake line bundle (9l291). Also, revise clips on #4 cross member to provide better retention. The part number on the first line should be (f1vc 5a897 not (f1vc 5a97 af).

F F3VC 9L291 AA NC00 100103 000 NC00E10165200000IR P IR 91/11/16

&lt;TUBE.ASY-FUEL.RETURN.&amp; BRAKE&gt; &lt;.....&gt;

- CR Description: delete f1vc-9l276-ha and (1) a803191-a56 due to f2ac-9l276-as acting as a ground for the fuel portion of the -9l291- bundle. F1vc-9l276-ha was incorporated to create a ground for the to fuel lines.

F F3VC 9L291 AB NC00 100103 000 NC00B10180678000IR P IR 92/01/09

&lt;TUBE.ASY-FUEL.RETURN.&amp; BRAKE&gt; &lt;.....&gt;

- CR Description: incorporate the following design changes to improve air line retention to the #4 crossmember. - revise double clip above "y" to insure positive retention - add protective tubing to the air line loop above "y" conn. fn36 air line: delete f1vc-5a897-af add f2vc-5a897-an en33 air line: delete f2ac-5a897-ac add f2ac-5a897-ad clip-double tube: delete f2ac-9279-be add f2ac-9279-as \*\*\*\* for 1992 - replace f1vc-5a897-af with f2vc-5a897-as in the f2vc-9l291-ad (fuel return and brake line bundle) for 1993 - replace f1vc-5a897-af with f2vc-5a897-as in (3vc-9l291-ab (fuel return and brake line bundle

F F3VC 9L291 AC NC00 100103 000 NC00B10236663000IR P IR 92/09/04

&lt;TUBE.ASY-FUEL.RETURN.&amp; BRAKE&gt; &lt;.....&gt;

- CR Description: \$\$\$\$ must be coordinated with nc00 e 10221001 002, replaces part released by nc00 e 10221001 003 \$\$\$\$ - to reduce likelihood of misbuilds, release new adaptor block which has two m12 outlet ports instead of one m10 and one m12. Additionally, release new fuel-brake line bundle for non-limo which has two m12 tube nuts to mate to adaptor (3vc-9l291-be). - change to adaptor block (3vc-2e320-ha) is a no cost change. Change to fuel-brake line bundle (3vc-9l291-ha) costs are: piece cost \$0.01; tooling cost \$10,000. - current brake-fuel line bundle (3vc-9l291-ac) will continue to be used on the limo. The current prop valve (2b091) will continue to be used on the en33.

F F3VC 9L291 BA NC00 100103 000 NC00E10236663000IR P IR 92/09/04

&lt;TUBE.ASY-FUEL.&amp; BRAKE.(LH)&gt; &lt;.....&gt;

- CR Description: \$\$\$\$ must be coordinated with nc00 e 10221001 002, replaces part released by nc00 e 10221001 003 \$\$\$\$ - to reduce likelihood of misbuilds, release new adaptor block which has two m12 outlet ports instead of one m10 and one m12. Additionally, release new fuel-brake line bundle for non-limo which has two m12 tube nuts to mate to adaptor (3vc-9l291-be). - change to adaptor block (3vc-2e320-ha) is a no cost change. Change to fuel-brake line bundle (3vc-9l291-ha) costs are: piece cost \$0.01; tooling cost \$10,000. - current brake-fuel line bundle (3vc-9l291-ac) will continue to be used on the limo. The current prop valve (2b091) will continue to be used on the en33.

**TUBE.ASY-P/S.RETURN**

C F1VC 3A563 EA NC00 110203 000 NC00E10108505001R P IR 91/01/29

&lt;TUBE.ASY-P/S.RETURN&gt; &lt;.....&gt;

- CR Description: design activity: redesign p/s cooler package similar to 92 en-53 (fm pack type mounted to the lower r.h. corner of the radiator support assembly. Also, please update p/t and illustration sheets as req'd. \*\*\*\*\* testing: new cooler passed spm req'mts./vco 910108 (a). \*\*\*\*\*stator: cost, weight, & timing tbd. "detail drawings req'd". \*\*\*\*\*sys gen components removed.... 91/06/26

C F1VC 3A563 FA NC00 110203 000 NC00E10074000000IR P IR 90/05/10

&lt;TUBE.ASY-P/S.RETURN&gt; &lt;.....&gt;

- CR Description: subject: 91 fn-36 4.6l efi all except trailer tow c/o item 92 en-53 all except trailer tow. Break down: job #1 req'd. - express chg. (ex) p/t dear action suffice comments f1vc-3a563-aa t&h say new ab new 3a563+o/o hose f1vc-3a563-fa tube say new fb revise/modify f1vc-3a274-ha hose c/o ha carryover component piece cost: no change weight : no change tooling : \$24,800 (e) (tbd) figure could be significantly less if tooling can be modified. Supplier : form ric

C F1VC 3A563 FB NC00 110203 000 NC00E10145560002R P IR 93/07/17

&lt;TUBE.ASY-P/S.RETURN&gt; &lt;.....&gt;

- CR Description: revise the finish on the en114/fa116 p/s return hose assembly and gear end of the pressure hose to aluminized rich paint over galvan and the pump end of the pressure hose to thick wall (.042" versus current .035") tubing. development of .042" wall is still ongoing. System pressure, temperature and noise effects are being studied. Steering engineering approves for use in the fa116/fa114 pending that .035" wall tube remains a fall back option.

To Concern: \_\_\_\_\_ Alert: \_\_\_\_\_ IFunc/Release

Sel C/F Part: \_\_\_\_\_ Actv CPSC= Seq Release= 15 CMS Date=

- F F3VC 3A563 A1 NC00 110203 000 NC00E10145560002IR P IR 93/07/17

&lt;TUBE.ASY-P/S.RETURN...&gt; &lt;.....&gt;

- CR Description: revise the finish on the en114/p116 p/s return hose assemblies and gear end of the pressure hose to aluminum rich paint over galvan and the pump end of the pressure hose to thick wall (.042" versus current .035") tubing. development of .042" wall is still ongoing. System pressure temperature and noise effects are being studied. Steering engineering approves for use in the fn116/en114 pending that .035" wall tube remains a fall back option.

- F F0VC 3A563 JA NC00 110203 000 NC00E10057562000IR P IR 90/06/20

&lt;TUBE.ASY-P/S.PUMP.RETURN...&gt; &lt;PCN=9BVA1104025...&gt;

- CR Description: new p/s line package req'd for trailer tow & police vehicles. In order to route around the abs anti-lock relay module and module bracket. \*\*\* memo: 92 base vehicle is ab1 1991 fn-36. Break down: refs d.o. Dated 891106 - see attachment p/n desc action cost / wt tooling comments f2ac-3a274-ca rm line delete \$ 0.30/20 S 2.200 spent f2ac-3493-al rm line new \$ 1.18/.50 @S 2.500e +\$ 0.88 e f2ac-3a274-da rm line delete \$ 0.19/.13 S 1,800 spent f2ac-3493-b1 rm line new \$ 0.34/nc #@S 1,800 +\$ 0.23 e Important: tooling & pc cost \$ 4,300 +\$ 1.11 e # memo: phase 1 builds used (f2ac-3493-al) base assy @ memo: new lines/routing require shielding for protection design Activity: please design & rel. components stated above also, please update p/f & illustration sheets as required. Break down: standard parts p/n desc action comments u605917-e56 bok info only deleted on a 10057561/rwj 97242-a101 clamp info only deleted on a 10057561/rwj a8da-8227-as clamp info only released on a 10057561/rwj e8a-3c510-aa clamp-rel. 91 fn-36 on a 10047814/tha 95873-a101 strap rel. Positive retention 3493 \*\*\* memo: 92 base vehicle is ab1 1991 fn-36. Break down: refs d.o. Dated 891106 - see attachment p/n desc action cost / wt tooling comments f2ac-3a274-ca rm line delete \$ 0.30/20 S 2.200 spent f2ac-3493-al rm line new \$ 1.18/.50 @S 2.500e +\$ 0.88 e f2ac-3a274-da rm line delete \$ 0.19/.13 S 1,800 spent f2ac-3493-b1 rm line new \$ 0.34/nc #@S 1,800 +\$ 0.23 e Important: tooling & pc cost \$ 4,300 +\$ 1.11 e # memo: phase 1 builds used (f2ac-3493-al) base assy @ memo: new lines/routing require shielding for protection design sys gen components removed.... 91/01/29

- F F0VC 3A563 JA NOSE 110203 000 NOSEE10065839000IR P IR 90/04/18

&lt;TUBE.ASY-P/S.PUMP.RETURN...&gt; &lt;.....&gt;

CR Description:

- F F1VC 3A563 A1 NC00 110203 000 NC00E10011356002IR P IR 89/06/23

&lt;TUBE.ASY-P/S.PUMP.RETURN...&gt; &lt;.....&gt;

- CR Description: 1991 fn36-requires all new p/s hydraulic distribution system for packaging & b&a dfa reasons. The p/s pressure line contacts front end stabilizer bar. Design activity: please design and release all new p/s hydraulic distribution systems to avoid contact with the front end stabilizer bar, plus accommodate bulk dfa concerns. Also, please review p/f & illustration sheets and update accordingly. See marked up copies attached. Processing activity: please update process sheets as req'd.

- F F1VC 3A563 BA NC00 110203 000 NC00E10057561002IR P IR 90/03/28

&lt;TUBE.ASY-P/S.PUMP.RETURN...&gt; &lt;.....&gt;

- CR Description: supplement required to delete p/s return tube assy omitted on Supplement 000.

- F F1VC 3A563 B1 NC00 110203 000 NC00E10010977020IR P IR 89/07/07

&lt;TUBE.ASY-P/S.PUMP.RETURN...&gt; &lt;.....&gt;

- CR Description: initial release of p/s hoses, cooler & mtr. Parts. Sys gen components removed.... 01/04/90 sys gen components removed.... 01/26/90 sys gen components removed.... 90/03/30

## PROP Valves:

- C F2VC 2B091 CC NC00 060202 000 NC00E10129983000IR P IR 92/04/02  
<VALVE.ASY.BRK.PRESS.CONTROL> <LIMO...>

- CR Description: adding ab1 to limo must be coordinated change between ab00 (body), nd0w (axle), and no00. Chassis cannot support job #1, 1993 timing, and requests affected parts be returned for 14p93a. This notice releases ab1 brakes as standard on limo & body must modify usage to include f0vb-2c309-ad, f0vb-2u312-ac, and n801164-s43 for limo application. (these parts are currently released for non-limo only). The axle assy f3vc-4001-a1 (025-d tag #) must be coordinated with ab1 brakes parts. Chassis fuel systems must add limo usage to f3vc-9x294-aa and delete f3vc-9x294-ba. I will include an add/delete parts list for all brake parts with the notice package. The only new brake subsystem parts are for the 11" brake assy and prop valves. All other parts are usage changes or resurrections of 1990 parts. The total chassis costs are \$293 v/c and \$160000 tooling to add ab1 to the limousine package. \*\*\* as in today's non-ab1 limo, two prop valves will be released the first, which will be installed by wixons will look identical to the ab1 valve used on the base car although it will have a different performance. It will have a black sticker to identify it from production valves. The second will GO INTO A KIT FOR USE when/if the vehicle is modified. This will continue to have a green sticker for identification. ----- fmxas should be tested. B&A, schmanski & genikas, insist on not changing tube nut to prevent mis-build. Brakes requests b&a concurrence they will process to prevent any mis build, i.e. black sticker valve on non limo, or unstickered valve on limo.

To Concern: \_\_\_\_\_ Alert: \_\_\_\_\_ IP Panel Release

Sel C/S Part: \_\_\_\_\_ Acty CPSC = Seq Release = IS C/S Determination

F F2VC 2B091 AA NC00 060605 000 NC00E10128004001IR PIR 91/07/11

&lt;VALVE ASY.BRK.PRESS.CONTROL&gt; &lt;ANTI-SPIN.BRAKES.WITH.SPEED.CONTROL.FB/PP..&gt;

- CR Description: for fn36 and en33 - with abs; release new prop valves(2b091) with modified bracket - extended for attachment of fuel line clip. For non-abs en33, release new adapter assys (2c320) With similarly modified bracket.

New part replaces usage

F2vc-2b091-aa f2vc-2b091-ad abs w/o new speed control

F2vc-2b091-be f2vc-2b091-aa abs w/o new speed control

F2ac-2c320-bb f2ac-2c320-be non-abs w/o new spd ctrl

F2ac-2c320-cb f2ac-2c320-ca non-abs w/ new spd ctrl

- until production tooling, listed parts are available, alert a10128004 authorizes use of pm parts.

- Summary

(incremental) piece cost tooling weight

Non abs (with &amp; w/o spd ctrl) \$1.00 \$50,000 0.20 #

Abs (with &amp; w/o spd ctrl) \$0.35 \$100,000 0.16 #

F F2VC 2B091 A1 NC00 060605 000 NC00E10014063008IR PIR 90/05/24

&lt;VALVE ASY.BRK.PRESS.CONTROL&gt; &lt;.....&gt;

- CR Description: initial release fn36 frames syn gen components removed... 10/25/89

F F2VC 2B091 BA NC00 060605 000 NC00E00444499336IR PIR 91/01/18

&lt;VALVE ASY.BRK.PRESS.CONTROL&gt; &lt;.....&gt;

- CR Description: Initial release of proportioning valve & junction block with p.i.a. speed control deactivation switch

Q F F2VC 2B091 CA NC00 060605 000 NC00E10117988001IR PIR 91/02/28

&lt;VALVE ASY.BRK.PRESS.CONTROL&gt; &lt;LIMO.....&gt;

- CR Description: USAGE CHANGE

X F F2VC 2B091 CB NC00 060605 000 NC00E10128004004IR PIR 91/07/25

&lt;VALVE ASY.BRK.PRESS.CONTROL&gt; &lt;LIMO.....&gt;

- CR Description: f2vc-2b382-ab released in error. Delete and cancel f2vc- 2b382-ab. Non-limousine--relistate f2vc-2b382-aa as a component of f2vc-2b091-aa and f2vc-2b091-ba. Limousine--release f2vc-2b091-cb with f2vc-2b382-be as a component. F2vc-2b091-cb replaces f2vc-2b091-ca.

F F2VC 2B091 CC NC00 060605 000 NC00E101843380001IR PIR 92/02/11

&lt;VALVE ASY.BRK.PRESS.CONTROL&gt; &lt;LIMO.....&gt;

- CR Description: until production tooling,listed parts are available use pm's

C F3VC 2B091 BA NC00 060202 000 NC00E10129983005IR PIR 92/08/21

&lt;VALVE ASY.BRK.PRESS.CONTROL&gt; &lt;LIMO.....&gt;

- CR Description: adding abs to limo must be coordinated change between ab00 (body), ad0w (axle), and ac00. Chassis cannot support job #1, 1993 timing, and requests affected parts be retained for j4p93a. This notice releases abs brakes as standard on limousine body must modify usage to include f0vb-2c309-ad, f0vb-2c312-ac, and n801164-a43 for limo application. (these parts are currently released for non-limo only). The axle assy f3vc-4001-a1 (025-d tag #) must be coordinated with abs brakes parts. Chassis fuel systems must add limo usage to f3vc-9a294-aa and delete f3vc-9a294-ha. It will include an add/delete parts list for all brake parts with the notice package. The only new brake subsystem parts are for the 11"brake assy and prop valves. All other parts are usage changes or restatements of 1990 parts. The total chassis costs are \$293 v/c and \$160000 tooling to add abs to the limousine package. \*\*\*\*as in today's non-abs limo, two prop valves will be released the first, which will be installed by wixom will look identical to the abs valve used on the base car although it will have a different Performance. It will have a black sticker to identify it from production valves. The second will go into a kit for use when/if the vehicle is modified. This will continue to have a green sticker for identification. --- fmvsas should be tested. B&a, schmieski & genkka, bnat, on not changing tube air to prevent mis-build. Brakes requests b&a concurrence they wil l process to prevent any mis build, i.e. black sticker valve on non limo, or unstickered valve on limo. \*\*\*\*\*clarify usage and effective points for the limo w/out abs and limo w/abs in 93 on the prop valve (2b091) and the limo brk conv kit (2a201).

To Concern: \_\_\_\_\_ Alert: \_\_\_\_\_ IfanicRelease

Sel C/P Part: \_\_\_\_\_ Acty CPSC= Seq Release= IS CDS Date=

- F P3VC 2B091 AA NC00 060605 000 NC00E1012998300S/R P IR 92/08/21  
 <VALVE.ASY.BRK.PRESS.CONTROL.> <LIMO.....>

- CR Description: adding abs to limo must be coordinated change between nb00 (body), na0w (axle), and nc00. Chassis cannot support job #1, 1993 timing, and requests affected parts be retimed for j4p93a. This notice releases abs brakes as standard on limousine body must modify usage to include f0vb-2c309-ad, f0vb-2c312-ac, and n801164-s43 for limo application. (these parts are currently released for non-limo only). The axle assy f3vw-4001-a1 (025-d tag #) must be coordinated with abs brakes parts. Chassis fuel systems must add limo usage to f3vc-9a294-aa and delete f3vc-9a294-ba. I will include an add/delete parts list for all brake parts with the notice package. The only new brake subsystem parts are for the 11"brake assy and prop valves. All other parts are usage changes or restatements of 1990 parts. The total chassis costs are \$293 v/o and \$160000 tooling to add abs to the limousine package. \*\*\*\*as in today's non-abs limo, two prop valves will be released the first, which will be installed by wixom will look identical to the abs valve used on the base car although it will have a different performance. It will have a black sticker to identify it from production valves. The second will go into a kit for use when/if the vehicle is modified. This will continue to have a green sticker for identification. --- fmvws should be tested. B&a, schumanakl & genikes, insist on not changing tube nut so prevent mis-build. Brakes requests b&a concurrence they will process to prevent any mis-build, i.e. black sticker valve on non limo, or unstickered valve on limo. \*\*\*\*clarify usage and effective points for the limo w/out abs and limo w/abs in 93 on the prop valve (2b091) and the limo brk conv kits (2a201).

- F P3VC 2B091 BA NC00 060605 000 NC00E00444499662/R P IR 92/09/16  
 <VALVE.ASY.BRK.PRESS.CONTROL.> <LIMO.....>

- CR Description: delete the abs info from the limo usage

## Air Suspension:

- F P2VC 3B484 AA NC00 040501 000 NC00E10126577000R P IR 91/05/28  
 <COMPR.&DRYER.ASY-SUSP.AIR.S> <.....>

- CR Description: to eliminate compressor noise, the current mounting washer is to be replaced with a thicker (1.5mm vs 1.0mm), harder (38rc vs. 34 rc) washer. Part numbers are affected as follows:

CAR LINE	PART NAME	CURRENT NUMBER	REVISED NUMBER
1992 FN36	COMP/DRYER ASSY	P2VC-3B484-AA	P2VC-3B484-AB
1992 FN36	COMPRESSOR ASSY	P2VC-2875-AA	P2VC-2875-AB
1992 EN53	COMP/DRYER ASSY	P2AC-3B484-AD	P2AC-3B484-AB
1992 EN53	COMPRESSOR ASSY	P2AC-2875-AD	P2AC-2875-AB

- F P2VC 3B484 AB DE00 040501 000 DE00I10267019004R P IR 93/09/24  
 <COMPR.&DRYER.ASY-SUSP.AIR.S> <.....>

- CR Description: supplement to effect out pn96 air suspension parts

- F P2VC 3B484 AB NC00 040501 000 NC00E1017D180000R P IR 91/12/02  
 <COMPR.&DRYER.ASY-SUSP.AIR.S> <.....>

- CR Description: Implement a redesigned compressor yoke gasket. The new gasket, which is 50% wider and 100% thicker, is more substantial and, therefore, easier to positively locate in the gasket retaining groove. The retaining groove on the compressor crank case will be enlarged to accommodate the revised gasket. Tokico has agreed to subversion test 15,000 fn36, and 15,000 en53 compressors with revised gaskets to verify the effectiveness of this corrective action.

- F P2VC 3B484 AC NC00 040501 000 NC00E10221208000R P IR 92/08/05  
 <COMPR.&DRYER.ASY-SUSP.AIR.S> <.....>

- CR Description: revise compressor mounting bracket to provide sufficient clearance to the flywheel sprocket. Supplier has provided a proposal which increases clearance from zero to five mm. Timing - assuming \$5,000 obsolescence cost for en53 brackets Wixom - to receive parts by sept 15, 1992 SL Thomas - to receive parts by jan 1993 part numbers will be affected as follows:

COMPONENT	CURRENT P/N	NEW P/N
FN36 COMPRESSOR & DRYER ASSY	P2VC-3B484-AC	P3VC-3B484-AA
FN36 COMPRESSOR ASSY SVC. ONLY	P2VC-2875-AC	P3VC-2875-AA
EN53 COMPRESSOR & DRYER ASSY.	P2AC-3B484-AA	P3AC-3B484-AA
EN53 COMPRESSOR ASSY SVC. ONLY	P2AC-2875-AD	P3AC-2875-AA

To Concern: \_\_\_\_\_ Alert: \_\_\_\_\_ [FuncRelease]  
 Sel C/F Part: \_\_\_\_\_ Artv CPSCom Seq Release: \_\_\_\_\_ S CMS Date: \_\_\_\_\_  
 - F P3VC 3B484 AA NC00 040501 000 NC00E00444499915IR P IR 93/09/24  
 <COMPR.&DRYER.ASY-SUSP.AIRS><.....>  
 • CR Description: this notice supplement supports alert #10336934 which releases air suspension air compressors minus the rubber air intake hose & mounting clip. Parts to be identified by a "pm" prefix. See referenced alert for further description.

ABS HCU: note in 1993... Towncar adopted Mark VIII ABS HCU as a complexity reduction (ABS or ABS/TC7).

X F P1VC 2C286 AA NC00 060903 000 NC00E10098043000IR P IR 90/10/11  
 <CONTROL.ASY-BRK.ANTI/LK.HYD><.....>

- CR Description: use 1991 fn36 abs without traction assist. Label the hydraulic control units and the shipping boxes that the unit arrive in for both fn36 & fn9. The labels should read "towncar" for the fn36 and "continental" for the fn9. The labels on the boxes should be large so that a hi-to driver can read them from the operators chair. This should continue until the fool-proof connectors become available as per components with fool-proof connectors release on c10053836 not c10090911 which was rejected in favor of this alert. Also, labels should continue to be used even after fool-proof connectors are available. It should be noted that body electrical still has not released the wiring harness change to incorporate the fool-proof connector.

F P3VC 2C286 AA NC00 060903 000 NC00E10185750000IR P IR 92/04/29  
 <CONTR.ASY-BRK.ANTI/LOCK.HYD><.....>

- CR Description: the unused christmas tree retainer on the 19-pin connector will be removed and 4 tie straps (one at each end of the 19-pin and 4-pin connector) will be added to keep the wires within the convolute. Cost is \$0.41 piece cost, \$0 tooling. This is a 1992 running change for em3/fn36. \*\*\* In addition, this notice will release a different reservoir cap and replace the current rubber plugs in the tube ports with a single tape strip covering the ports. These are for contamination prevention during shipping, and are removed before assembly. This is a no cost change, and is being released on the dn5 and fn9 drawings as well as the em3/fn36. The dn5 and fn9 part numbers will not change. \*\*\* this notice also releases f2vc-2c266-as for service only. F2vc-2c266-as is an abs valve block that will service 1991 and part of the 1992 model year fn36 abs-only vehicles. This part has the disc/disc calibration and a black connector. F2vc-2c266-as (already released) will continue to service the latter part of the 1992 model year built with the grey connector. The release of f2vc-2c266-as is done at no cost, no tooling.

O F P3VC 2C286 AB NC00 060903 000 NC00E10249956000IR P IR 92/12/03  
 <CONTR.ASY-BRK.ANTI/LOCK.HYD><.....>

- CR Description: modify 19-way canon connector with internal key-way to prevent 180 degree rotation by mistake. testing tbd. this is a one model year change, however, it involves safety concerns and should be incorporated.

O F P3VC 2C286 AC NC00 060903 000 NC00E10249956000IR P IR 92/12/03  
 <CONTR.ASY-BRK.ANTI/LOCK.HYD><.....>

- CR Description: modify 19-way canon connector with internal key-way to prevent 180 degree rotation by mistake. testing tbd. this is a one model year change, however, it involves safety concerns and should be incorporated.

X C P1VC 2C285 BB NC00 060903 001 NC00E10068739002IR P IR 90/04/18  
 <CONTR.ASY-BRK.A/LK.TRCTION.H><.....>

- CR Description: to provide power tool access at the rear of the hcu/cfc the inboard tube nut, revise the tube nut extension for the secondary circuit in the hcu/cfc to be the same as the primary circuit tube nut extension to conform with changes made on the tube bundle f2c296.

X C P1VC 2C285 BC NC00 060903 001 NC00E10068739002IR P IR 90/04/18  
 <CONTR.ASY-BRK.A/LK.TRCTION.H><.....>

- CR Description: to provide power tool access at the rear of the hcu/cfc the inboard tube nut, revise the tube nut extension for the secondary circuit in the hcu/cfc to be the same as the primary circuit tube nut extension to conform with changes made on the tube bundle f2c296.

X F P1VC 2C285 A1 NC00 060903 000 NC00E10018851001IR P IR 89/05/22  
 <CONTR.ASY-BRK.ANTI/LK.HYD><.....>

- CR Description: revise outlet porting of hydraulic control unit for manufacturing feasibility.

F P1VC 2C285 A1 NC00 060903 001 NC00E10018851001IR P IR 89/05/22  
 <CONTR.ASY-BRK.ANTI/LK.HYD><REMOVAL.RSULTING.FROM.DUAL.RELEASE.RECORDS>

- CR Description: revise outlet porting of hydraulic control unit for manufacturing feasibility.

To Customer: \_\_\_\_\_ Alert: \_\_\_\_\_ IFuseOrRelease

Sel C/F Partnum: \_\_\_\_\_ Acty CPSC= Seq Release: \_\_\_\_\_ S CIS Date: \_\_\_\_\_

 F F1VC 2C285 BA NC00 060903 000 NC00E10668739002/R P IR 90/04/18

&lt;CONTRASY-BRK.ANTI/LK.HYD..&gt; &lt;.....&gt;

- CR Description: to provide power tool access at the rear of the hew/hc the inboard tube nut, revise the tube nut extension for the secondary circuit in the hewto y2c285 to be the same as the primary circuit tube nut extension to conform with changes made on the tube bundle y2c296.

 F F1VC 2C285 BB NC00 060903 000 NC00E0444499323/R P IR 90/12/17

&lt;CONTRASY-BRK.A/LK.TRCTION.H&gt; &lt;.....&gt;

- CR Description: usage change: effective point revision to brake anti-lock hydraulic controls due to part availability.

 F F1VC 2C285 BC NC00 060903 000 NC00E10068739003/R P IR 90/06/24

&lt;CONTRASY-BRK.A/LK.TRCTION.H&gt; &lt;.....&gt;

- CR Description: to provide power tool access at the rear of the hew/hc to the inboard tube nut: 1. Revert the abe hex common extensions, for attaching of the brake tubes from the master cylinder , to one long and one short extention. This is a \$0.48 piece cost save at \$0.00 tool cost. 2. Increase the length of the secondary circuit brake tube 10.0, increase the length of the tube nut to compensate for the short extention at the hew, and revise the tube nut to m12 from m10. This is a piece cost increase of \$0.08 and a tool cost of \$10000.00. These changes will maintain the tube nut hex in the current location, continuing to provide power tool access, at a net piece cost save of \$0.40 and \$10000.00 tool cost. Sys gen components removed.... 90/06/21

 F F1VC 2C285 CA NC00 060903 000 NC00E1011734100/R P IR 91/02/28

&lt;CONTRASY-BRK.A/LK.TRCTION.H&gt; &lt;.....&gt;

- CR Description: release f1vc-2c296-cb in place of f1vc-2b296-cm and/or pm-f1vc-2b296-ac. F1vc-2c296-cb has two m10 tube nuts to mate with the m10 fittings on the revised traction control hew. F1vc-2b296-ac is not affected. --- incorporation in production of the brake tube bundle f1vc-2c296-cb must be coordinated with incorporation in production of the hew-2c285- released on nc00-e10117341 000.

 F F1VC 2C285 CB NC00 060903 000 NC00E10145327000/R P IR 91/09/22

&lt;CONTRASY-BRK.A/LK.TRCTION.H&gt; &lt;.....&gt;

- CR Description: change from spiral wrap to convolute tubing, add a "christmas tree" to the 19-pin connector pigtail, and add a hole to the 2c303 bracket to retain the pigtail for both en53 and fn36.

\*\*\*\*\*  
\* Note printed by TBAZIL on 15 Jan 1999 at 09:12:36 \*  
\*\*\*\*\*

From: JEVANSE --DRBN005  
To: FCONDON --DRBN005

Date and time 01/15/99 09:11:33  
TBAZIL --DRBN005

FROM: Joe Evans  
Subject: 9F924 Update (19981218)

USAET(UTC -05:00)

Regards, Joe Evans  
Brakes, Vacuum Distribution and Chassis Control Systems  
Core Brake Control Systems Engineering  
Phone 32-23832 Fax 32-31947

\*\*\* Forwarding note from FPORTER --DRBN007 12/18/98 17:04 \*\*\*

To: WABRAMCZ --DRBN005  
RENGLISI --DRBN005  
DGOBL --DRBN005  
KGRIBBLE --DRBN005  
SLAROUCH --FORDNA1  
JNAME --DRBN005  
GSTRAVENI --DRBN005  
BWEILFER3 --DRBN006

BEGEN --DRBN007  
JEVANSE --DRBN005  
JGREGOIR --DRBN005  
NLAPOINT --DRBN005  
JMCINERN --DRBN005  
RNEVI --DRBN005  
CTHOMASS --DRBN005

FROM: F. J. Porter

USAET(UTC -05:00)

Subject: 9F924 Update (19981218)

1992-1993-Town Car F2VC-9F924-A Brake Pressure Switch Investigation

TEAM:

AVT ESSS Chassis Electronics: Fred Porter x84-53722 fporter  
AVT Chassis Engineering: Joe Evans x32-23832 jevans8  
Barry Egan x32-39512 began  
AVT ESSS EDS: Rob English x33-73225 renglisi  
AVT Design Analysis: Norm LaPointe x59-42686 nlapoint  
AVT ESSS OPE: Jim Gregoire x33-79962 jgregoirz  
E&SE Prod. Veh. Safety: William Abramczyk x32-23244 wabramcz  
Ray Nevi x59-47688 rnevi  
Large Luxury VC Safety: John McInerney x32-20276 jmcinern  
Joe Name x39-09133 jname  
AVT Materials Engineering: Greg Stevens x32-36686 gsteven1  
Ken Gribble x32-38658 kgribble  
Clark Thomas x59-41313 cthomas5  
Central Lab Services: Steve LaRouche x84-54876 slarouch

INFORMATION:

NHTSA letter: PE98-055

Vehicles Identified: 21 initially identified.  
20 additional vehicles reported since publication of  
the investigation.

Warranty: A total of 89 warranty claims are identified in AWS on the  
F2VV-9F924-A for 1992 and 1993 Town Cars.

Two CQIS reports (WJIAA135 & VDUAA322) mention underhood fire

3713 7771

WWRS5A6A R1264222 List Part Function Replacement History 99/01/15 09:54:53

REPLACES - REPLACED BY

Part: F1VC 2B091 PT-VL:  EffPnt/Date:   
Func Acty:  CPSC:  C/F:  Class:   
History: - Prel:  Reg:  Organizatn:   
Engineer:  Color: E Print:

Part=====	Acty	CPSC==	Seq	Release=====	C/F	S	CL	S	Date====
- F1VC 2B091 AA	NC00 060605 000	NC00E10036524000	F	R P	R	89/11/10			
<VALVE.ASY.BRK.PRESS.CONTROL.><.....>									
R F1VC 2B091 A1	NC00 060605 000	NC00I10010977022	F						
B F1VC 2B091 AB	NC00 060605 000	NC00E10036524000	F						
- F1VC 2B091 AB	NC00 060605 000	NC00E10061037001	F	R P	R	90/05/25			
<VALVE.ASY.BRK.PRESS.CONTROL.><.....>									
R F2AC 2B091 A1	NC00 060605 000	NC00I10043767000	F						
B F1VC 2B091 AC	NC00 060605 000	NC00E10051375000	F						
B F1VC 2B091 AD	NC00 060605 000	NC00E10061037001	F						
- F1VC 2B091 AC	NC00 060605 000	NC00E10061037000	F	R P	R	90/04/04			
<VALVE.ASY.BRK.PRESS.CONTROL.><ANTI/LK.....>									
R F1VC 2B091 AB	NC00 060605 000	NC00E10051375000	F						
B F1VC 2B091 AD	NC00 060605 000	NC00E10061037000	F						

SELECT>> F=Function U=Usage N=Notice 4=UCC/Proc 5=DES/Funct 6=Service  
MORE

3713 7772

WWRSS5A6A R1264222 List Part Function Replacement History 99/01/15 09:54:59

REPLACES - REPLACED BY

Part: F1VC 2B091 PT-VL:  EffPnt/Date:   
Func Acty:  CPSC:  C/F:  Class:   
History: - Prel:  Reg:  Organiztn:   
Engineer:  Color: E Print: -

Part	Acty	CPSC	Seq	Release	C/F	S CL	S Date		
<u>F1VC</u>	<u>2B091</u>	<u>AD</u>	<u>NC00</u>	<u>060605</u>	<u>000</u>	<u>NC00E10128004001</u>	<u>F</u>	<u>R P</u>	<u>R 91/07/11</u>

<VALVE.ASY.BRK.PRESS.CONTROL.><ANTI/LX.....>

R	<u>F1VC</u>	<u>2B091</u>	<u>AB</u>	<u>NC00</u>	<u>060605</u>	<u>000</u>	<u>NC00E10061037001</u>	<u>F</u>
B	<u>F2AC</u>	<u>2B091</u>	<u>AA</u>	<u>NC00</u>	<u>060605</u>	<u>000</u>	<u>NC00E10128004001</u>	<u>F</u>
B	<u>F2VC</u>	<u>2B091</u>	<u>AA</u>	<u>NC00</u>	<u>060605</u>	<u>000</u>	<u>NC00I10014063008</u>	<u>F</u>
B	<u>F5AC</u>	<u>2B091</u>	<u>AA0</u>	<u>NC00</u>	<u>060605</u>	<u>000</u>	<u>NC00I10107232002</u>	<u>F</u>
R	<u>F1VC</u>	<u>2B091</u>	<u>A1</u>	<u>NC00</u>	<u>060605</u>	<u>000</u>	<u>NC00I10010977022</u>	<u>F   R P   R 89/05/18</u>

<VALVE.ASY.BRK.PRESS.CONTROL.><.....>

R	<u>F0VC</u>	<u>2B091</u>	<u>AB</u>	<u>NC00</u>	<u>060605</u>	<u>000</u>	<u>NC00I10010977014</u>	<u>F</u>
B	<u>F1VC</u>	<u>2B091</u>	<u>AA</u>	<u>NC00</u>	<u>060605</u>	<u>000</u>	<u>NC00I10010977022</u>	<u>F</u>
B	<u>F2AC</u>	<u>2B091</u>	<u>A1</u>	<u>NC00</u>	<u>060605</u>	<u>000</u>	<u>NC00I10010977014</u>	<u>F</u>
R	<u>F1VC</u>	<u>2B091</u>	<u>BA</u>	<u>NC00</u>	<u>060605</u>	<u>000</u>	<u>NC00I10010977048</u>	<u>F   R P   R 90/01/12</u>

<VALVE.ASY.BRK.PRESS.CONTROL.><.....>

R	<u>F1VC</u>	<u>2B091</u>	<u>BA</u>	<u>NC00</u>	<u>060701</u>	<u>000</u>	<u>NC00I10010977047</u>	<u>F</u>
---	-------------	--------------	-----------	-------------	---------------	------------	-------------------------	----------

SELECT=>> F=Function U=Usage N=Notice 4=UCC/Proc 5=DES/Funct 6=Service

MORE

3713 7773

WWRS5A6A R1264222 List Part Function Replacement History 99/01/15 09:55:05

REPLACES - REPLACED BY

Part: F1VC 2B091 PT-VL: \_\_\_\_\_ EffPnt/Date: \_\_\_\_\_  
Func Acty: \_\_\_\_\_ CPSC: \_\_\_\_\_ C/F: \_\_\_\_\_ Class: \_\_\_\_\_  
History: \_\_\_\_\_ Prel: \_\_\_\_\_ Reg: \_\_\_\_\_ Organizatn: \_\_\_\_\_  
Engineer: \_\_\_\_\_ Color: B Print: \_\_\_\_\_

Part	Acty	CPSC	Seq	Release	C/F	S	CL	S	Date		
F1VC	2B091	BA	NC00	060701	000	NC00E00444499103	F	R	P	R	89/10/30
<VALVE.ASY.BRK.PRESS.CONTROL.><.....>											
F1VC	2B091	BA	NC00	060701	001	NC00E10640585004	F	R	S	R	98/08/03
<VALVE.ASY.BRK.PRESS.CONTROL.><SERVICE.ONLY.....>											
R	None					NC00E10640585004	F				
B	None					NC00E10640585004	F				
F1VC	2B091	CA	NC00	060605	000	NC00E10128004004	F	R	P	R	91/07/25
<VALVE.ASY.BRK.PRESS.CONTROL.><.....>											
R	F0VC	2B091	BA	NC00	060605	000	NC00E10111036000	F			
B	F2VC	2B091	CA	NC00	060605	000	NC00E10117988000	F			
B	P1F1VC	2B091	CA	NC00	060605	000	NC00E10128004004	F			

SELECT=>> F=Function U=Usage N=Notice 4=UCC/Proc 5=DES/Funct 6=Service  
LAST

WWRS5A6A R1264222 List Part Function Replacement History 99/01/15 09:55:19  
 REPLACES - REPLACED BY

Part: F2AC 2B091 PT-VL: \_\_\_\_\_ EffPnt/Date: \_\_\_\_\_  
 Func Acty: CPSC C/F: \_\_\_\_\_ Class: \_\_\_\_\_  
 History: - Frel: \_\_\_\_\_ Reg: \_\_\_\_\_ Organizatn: \_\_\_\_\_  
 Engineer: - Color: ■ Print: \_\_\_\_\_

Func | Release

S | S CL | S Date====

C | R P | R 92/08/31

<VALVE.ASY.BRK.PRESS.CONTROL.><ANTI/LK.....>

F2AC 2B091 AA NC00 060202 000 NC00E10129983006 C | R P | R 94/02/15

<VALVE.ASY.BRK.PRESS.CONTROL.><ANTI/LK.....>

R NONE NC00E10129983006 C

B NONE NC00E10129983006 C

H F5VC 2B091 AA NC00 060202 000 NC00E10357590000 C

F2AC 2B091 AA NC00 060605 000 NC00E10128004004 F | R P | R 91/07/25

<VALVE.ASY.BRK.PRESS.CONTROL.><ANTI/LK.....>

R F1VC 2B091 AD NC00 060605 000 NC00E10128004001 F

B PMF2AC 2B091 AA NC00 060605 000 NC00E10128004004 F

F2AC 2B091 A1 NC00 060605 000 NC00I10043767000 F | R P | R 89/12/13

<VALVE.ASY.BRK.PRESS.CONTROL.><.....>

R F1VC 2B091 A1 NC00 060605 000 NC00I10010977014 F

SELECT=>> F=Function U=Usage N=Notice 4=UCC/Proc 5=DES/Funct 6=Service

MORE

WWRSSA6A R1264222 List Part Function Replacement History 99/01/15 09:55:28

REPLACES - REPLACED BY

Part: F2AC 2B091 PT-VL:  EffPnt/Date:   
Func Acty:  CPSC:  C/F:  Class:   
History: - Prel:  Reg:  Organiztn:   
Engineer:  Color: E Print: -

Part	Acty	CPSC	Seq	Release	C/F	S	CL	S	Date
F2AC	2B091 A1	NC00	060605	000 NC00I10043767000	F	R	P	R	89/12/13
<VALVE.ASY.BRK.PRESS.CONTROL.><.....>									
B	F1VC	2B091 AB	NC00	060605	000 NC00I10043767000	F			
B	F2VC	2B091 A1	NC00	060605	000 NC00I10014063001	F			
-	F2AC	2B091 BA	NC00	060605	000 NC00E10221001004	F	R	P	R 92/08/21
<VALVE.ASY.BRK.PRESS.CONTROL.><ANTI-SPIN.BRAKES.WITH.SPEED.CONTROL.FB/FP...>									
R	NONE				NC00E00444499552	F			
R	F2VC	2B091 AA	NC00	060605	000 NC00E10128004001	F			
B	NONE				NC00E00444499552	F			
B	PMF2AC	2B091 BA	NC00	060605	000 NC00E10128004008	F			

SELECT=>> F=Function U=Usage N=Notice 4=UCC/Proc 5=DES/Funct 6=Service  
LAST

3713 7776

WWRSSA6A R1264222 List Part Function Replacement History 99/01/15 09:55:38

REPLACES - REPLACED BY

Part: F2VC 2B091 PT-VL:  EffPnt/Date:   
Func Acty:  CPSC:  C/F: - Class:   
History: - Prel: - Reg: - Organizatn: -  
Engineer:  Color: E Print: -

Part	Acty	CPSC	Seq	Release	C/F	S	CL	S	Date		
<u>F2VC</u>	<u>2B091</u>	<u>CC</u>	<u>NC00</u>	<u>060202</u>	<u>000</u>	<u>NC00E10129983000</u>	<u>C</u>	<u>R</u>	<u>P</u>	<u>R</u>	<u>92/04/02</u>
<VALVE.ASY.BRK.PRESS.CONTROL.><LIMO.....>											
R	NONE				NC00E10184338001		C				
B	NONE				NC00E10129983000		C				
<u>F2VC</u>	<u>2B091</u>	<u>AA</u>	<u>NC00</u>	<u>060605</u>	<u>000</u>	<u>NC00I100128004001</u>	<u>F</u>	<u> R</u>	<u>P</u>	<u> R</u>	<u>91/07/11</u>
<VALVE.ASY.BRK.PRESS.CONTROL.><ANTI-SPIN.BRAKES.WITH.SPEED.CONTROL.FB/FP...>											
R	<u>F2VC</u>	<u>2B091</u>	<u>A1</u>	<u>NC00</u>	<u>060605</u>	<u>000</u>	<u>NC00I10014063008</u>	<u>F</u>			
B	<u>F2AC</u>	<u>2B091</u>	<u>BA</u>	<u>NC00</u>	<u>060605</u>	<u>000</u>	<u>NC00E10128004001</u>	<u>F</u>			
B	<u>F2VC</u>	<u>2B091</u>	<u>BA</u>	<u>NC00</u>	<u>060605</u>	<u>000</u>	<u>NC00E10079844001</u>	<u>F</u>			
B	<u>F5AC</u>	<u>2B091</u>	<u>BA0</u>	<u>NC00</u>	<u>060605</u>	<u>000</u>	<u>NC00I10107232002</u>	<u>F</u>			
<u>F2VC</u>	<u>2B091</u>	<u>A1</u>	<u>NC00</u>	<u>060605</u>	<u>000</u>	<u>NC00I10014063008</u>	<u>F</u>	<u> R</u>	<u>P</u>	<u> R</u>	<u>90/05/24</u>
<VALVE.ASY.BRK.PRESS.CONTROL.><.....>											
R	<u>F2AC</u>	<u>2B091</u>	<u>A1</u>	<u>NC00</u>	<u>060605</u>	<u>000</u>	<u>NC00I10014063001</u>	<u>F</u>			
B	<u>F2VC</u>	<u>2B091</u>	<u>AA</u>	<u>NC00</u>	<u>060605</u>	<u>000</u>	<u>NC00I10014063008</u>	<u>F</u>			

SELECT=>> F=Function U=Usage N=Notice 4=UCC/Proc 5=DES/Funct 6=Service

MORE

3713 7777

WWRS5A6A R1264222 List Part Function Replacement History 99/01/15 09:55:43

REPLACES - REPLACED BY

Part: F2VC 2B091 PT-VL: EffPnt/Date:  
Func Acty: CPSC C/F: Class:  
History: Prel: Reg: Organizatn:  
Engineer: Color: E Print: \_

Part	Acty	CPSC	Seq	Release	C/F	S	CL	S	Date
- F2VC	2B091 BA	NC00	060605	000 NC00E00444499336	F	R	P	R	91/01/18
<VALVE.ASY.BRK.PRESS.CONTROL.><.....>									
R	F2VC	2B091 AA	NC00	060605	000 NC00E10079844001	F			
-	F2VC	2B091 CA	NC00	060605	000 NC00E10117988001	F	R	P	R 91/02/28
<VALVE.ASY.BRK.PRESS.CONTROL.><LIMO.....>									
R	F1VC	2B091 CA	NC00	060605	000 NC00E10117988000	F			
B	F2VC	2B091 CB	NC00	060605	000 NC00E10117988001	F			
-	F2VC	2B091 CB	NC00	060605	000 NC00E10128004004	F	R	P	R 91/07/25
<VALVE.ASY.BRK.PRESS.CONTROL.><LIMO.....>									
R	F2VC	2B091 CA	NC00	060605	000 NC00E10117988001	F			
B	F2VC	2B091 CC	NC00	060605	000 NC00E10128004003	F			
B	F5VC	2B091 AAO	NC00	060605	000 NC00I10107232002	F			

SELECT=>> F=Function U=Usage N=Notice 4=UCC/Proc 5=DES/Funct 6=Service  
MORE

3713 7778

WWRS5A6A R1264222 List Part Function Replacement History 99/01/15 09:55:50

REPLACES - REPLACED BY

Part: F2VC 2B091 PT-VL: EffPnt/Date:  
Func Acty: CPSC: C/F: Class:  
History: Prel: Reg: Organizatn:  
Engineer: Color: Print:

Func | Release

S CL S Date====

R P R 92/02/11

Part===== Acty CPSC== Seq Release===== C/F  
F2VC 2B091 CC NC00 060605 000 NC00E10184338000 F

<VALVE.ASY.BRK.PRESS.CONTROL.><LTMO.....>

R F2VC 2B091 CB NC00 060605 000 NC00E10128004002 F  
B F3VC 2B091 AA NC00 060605 000 NC00E10184338000 F  
B PMF2VC 2B091 CC NC00 060605 000 NC00E10128004008 F

SELECT=>> F=Function U=Usage N=Notice 4=UCC/Proc 5=DES/Funct 6=Service  
LAST

3713 7779

WWR55A6A R1264222 List Part Function Replacement History 99/01/15 09:56:01

REPLACES - REPLACED BY

Part: F3VC 2B091 PT-VL:  EffPnt/Date:   
Func Acty:  CPSC:  C/F:  Class:   
History: - Prel:  Reg:  Organizata: -  
Engineer:  Color: E Print: -

			Func	Release
Part	=====	Acty	CPSC== Seq	Release===== C/F S CL   S Date====
-	F3VC	2B091 BA	NC00 060202 000	NC00E10129983005 C   R P   R 92/08/21
<VALVE.ASY.BRK.PRESS.CONTROL.><LIMO.....>				
B	NONE		NC00E10129983000	C
-	F3VC	2B091 AA	NC00 060605 000	NC00E10129983005 F   R P   R 92/08/21
<VALVE.ASY.BRK.PRESS.CONTROL.><LIMO.....>				
R	NONE		NC00E10129983001	F
,R	F2VC	2B091 CC	NC00 060605 000	NC00E10184338000 F
B	NONE		NC00E10129983001	F
B	NONE		NC00E10184338000	F
-	F3VC	2B091 BA	NC00 060605 000	NC00E00444499662 F   R P   R 92/09/16
<VALVE.ASY.BRK.PRESS.CONTROL.><LIMO.....>				
R	NONE		NC00E00444499662	F
R	NONE		NC00E10129983005	F
B	NONE		NC00E00444499662	F

SELECT=>> F=Function U=Usage N=Notice 4=UCC/Proc 5=DES/Funct 6=Service  
MORE

WWRS5A6A R1264222 List Part Function Replacement History 99/01/15 09:56:07

REPLACES - REPLACED BY

Part: F3VC 2B091 PT-VL:   EffPnt/Date:    
Func Acty:   CPSC:   C/P:   Class:    
History:   Prel:   Reg:   Organizatn:    
Engineer:   Color: E Print:  

Func Release

Part===== Acty CPSC== Seq Release===== C/F S CL S Date=====  
F3VC 2B091 ER NC00 060605 000 NC00E0044499662 F R P R 92/09/16

<VALVE.ASY.BRK.PRESS.CONTROL.><LIMO.....>

B NONE NC00E10129983005 F

SELECT=>> F=Function U=Usage N=Notice 4=UCC/Proc S=DES/Funct 6=Service  
LAST

3719 7781

WWRS5A6A R136694C List Part Function Replacement History 99/01/14 19:53:04

REPLACES - REPLACED BY

Part: F3AC 2C219 PT-VL:  EffPnt/Date:   
Func Acty:  CPSC:  C/F:  Class:   
History:  Prel:  Reg:  Organizatn:   
Engineer:  Color: E Print:

Part	Acty	CPSC	Seq	Release	C/F	S	CL	S	Date
- F3AC 2C219 BA	NOSE	060903 000	NOSEE10384500000	F	R	P	R	94/03/10	
<MODULE.ASY-BRK.A/LK.CNTRL.HL><.....>									
B	NONE		NOSEE10333831000	F					
- F3AC 2C219 CA	NC00	060903 000	NC00E10384500000	F	R	P	R	94/03/09	
<MODULE.ASY-BRK.A/LK.CNTRL.HL><.....>									
R	NONE		NC00E00444499936	F					
R	NONE		NC00E10278548000	F					
R	NONE		NC00E10384500000	F					
B	NONE		NC00E10278548000	F					
B	NONE		NC00E10384500000	F					

SELECT=>> F=Function U=Usage N=Notice 4=UCC/Proc 5=DES/Funct 6=Service  
LAST

3713 7782

WWRSS5A6A R136694C List Part Function Replacement History 99/01/14 19:53:22

REPLACES - REPLACED BY

Part: F3AC 2C219 PT-VL: EffPnt/Date:  
Func Acty: CPSC C/F: - Class: -  
History: Pral: Reg: - Organizatn: -  
Engineer: Color: E Print: -

Part	Acty	CPSC	Seq	Release	C/P	S	CL	S	Date
<u>F3AC</u>	<u>2C219 AA</u>	<u>NC00</u>	<u>060903</u>	<u>000</u>	<u>NC00E10278548000</u>	<u>F</u>	<u>R</u>	<u>P</u>	<u>R 93/06/25</u>
<MODULE.ASY-BRK.A/LK.CNTRL.EL><.....>									
R	<u>F1VC</u>	<u>2C219 AB</u>	<u>NC00</u>	<u>060903</u>	<u>000</u>	<u>NC00E10240197000</u>	<u>F</u>		
B		<u>NONE</u>				<u>NC00E10240197000</u>	<u>F</u>		
B	<u>F3AC</u>	<u>2C219 BA</u>	<u>NC00</u>	<u>060903</u>	<u>000</u>	<u>NC00E10257885000</u>	<u>F</u>		
B	<u>F3AC</u>	<u>2C219 BA</u>	<u>NC00</u>	<u>060903</u>	<u>000</u>	<u>NC00E10348673000</u>	<u>F</u>	<u> R</u>	<u>P  R 93/11/19</u>
<MODULE.ASY-BRK.A/LK.CNTRL.EL><.....>									
R	<u>F3AC</u>	<u>2C219 AA</u>	<u>NC00</u>	<u>060903</u>	<u>000</u>	<u>NC00E10257885000</u>	<u>F</u>		
R	<u>F3AC</u>	<u>2C219 CA</u>	<u>NC00</u>	<u>060903</u>	<u>000</u>	<u>NC00E10348673000</u>	<u>F</u>		
B		<u>NONE</u>				<u>NC00E10257885000</u>	<u>F</u>		
B		<u>NONE</u>				<u>NC00E10348673000</u>	<u>F</u>		
B	<u>F3AC</u>	<u>2C219 BA</u>	<u>NOSE</u>	<u>060903</u>	<u>000</u>	<u>NOSEE10384500000</u>	<u>F</u>	<u> R</u>	<u>P  R 94/03/10</u>
<MODULE.ASY-BRK.A/LK.CNTRL.EL><.....>									
R		<u>NONE</u>				<u>NOSEE10333831000</u>	<u>F</u>		

SELECT=>> F=Function U=Usage N=Notice 4=UCC/Proc 5=DES/Funct 6=Service

MORE

3713 7783

WWRSSA6A R136694C List Part Function Replacement History 99/01/14 19:54:12

REPLACES - REPLACED BY

Part: F1VC 2C219 PT-VL:  EffPnt/Date:   
Func Acty:  CPSC:  C/F:  Class:   
History:  Prel:  Reg:  Organizatn:   
Engineer:  Color: E Print:

Part=====	Acty	CPSC==	Seq	Release=====	C/F	S	CL	S	Date=====
- F1VC 2C219 AA	NC00 060903 000	NC00E10257885000	F	R P	R	92/12/14			
<MODULE.ASY-BRK.A/LK.CNTRL.HL><.....>									
R	NONE		NC00E10257885000	F					
B	NONE		NC00E10257885000	F					
-	F1VC 2C219 AB	NC00 060903 000	NC00E10240197000	F   R P   R	92/09/30				
<MODULE.ASY-BRK.A/LK.CNTRL.HL><.....>									
R	NONE		NC00I10107213008	F					
R	F1VC 2C219 AA	NC00 060903 000	NC00E10050056000	F					
B	F3AC 2C219 AA	NC00 060903 000	NC00E10240197000	F					
-	F1VC 2C219 A1	NC00 060903 000	NC00I10010977024	F   R P   R	89/06/08				
<MODULE.ASY-BRK.A/LOCK.CONTRO><.....>									
R	F0VC 2C219 AC	NC00 060903 000	NC00I10010977014	F					
B	F1VC 2C219 AA	NC00 060903 000	NC00I10010977024	F					

SELECT=>> F=Function U=Usage N=Notice 4=UCC/Proc 5=DES/Funct 6=Service  
MORE

3713 7784

WWRSS5A6A R136694C List Part Function Replacement History 99/01/14 19:54:23

REPLACES - REPLACED BY

Part: F1VC 2C219 PT-VL:  EffPnt/Date:   
Func Acty:  CPSC:  C/F:  Class:   
History: - Prel:  Reg:  Organiztn: -  
Engineer:  Color: ■ Print:

Part=====	Acty	CPSC==	Seq	Release=====	C/F	S	CL	S	Date====	
<u>F1VC</u>	<u>2C219</u>	<u>BA</u>	<u>NC00</u>	<u>060903</u>	<u>000</u>	<u>NC00E10250073000</u>	<u>F</u>	<u>R</u>	<u>P</u>	<u>R 92/10/16</u>
<MOD.AST-BRK.ANTI/LK.CONTRL.E><NON.T/C.....>										
R	NONE					NC00E10129983001		F		
R	NONE					NC00E10129983004		F		
B	NONE					NC00E10129983001		F		
B	NONE					NC00E10129983004		F		

SELECT=>> F=Function U=Usage N=Notice 4=UCC/Proc 5=DES/Funct 6=Service  
LAST

3713 7786

WWRS5A6A R136694C List Part Function Replacement History 99/01/14 18:36:27

REPLACES - REPLACED BY

Part: F1VC 2B195 CG PT-VL: EffPnt/Date: \_\_\_\_\_  
Func Acty:    CPSC:    C/F:    Class:     
History:    Prel:    Reg:    Organizatn:     
Engineer:    Color:    Print:   

Part===== Acty CPSC== Seq Release===== C/F S CL S Date=====  
F1VC 2B195 CG NC00 060701 000 NC00E10300678000 F R P R 93/05/20  
<ESTR.&.MSTR.CYL.AST.BRK....><.....>

			Func	Release
R		NONE	NC00E00444499608	F
R		NONE	NC00E00444499705	F
R		NONE	NC00E00444499718	F
R		NONE	NC00E10129983001	F
R	F1VC	2B195 CF	NC00 060701 000	NC00E10104848000 F
B	F2AC	2B195 BA	NC00 060701 000	NC00E10171561008 F
B	F3AC	2B195 CA	NC00 060701 000	NC00E10300678000 F
B	F5AC	2B195 AA0	NC00 060701 000	NC00I10107232032 F

SELECT=>> F=Function U=Usage N=Notice 4=UCC/Proc 5=DES/Punct 6=Service  
LAST

3713 7786

WWRS5A6A R136694C List Part Function Replacement History 99/01/14 19:35:43

REPLACES - REPLACED BY

Part: F1VC 2B195 CG PT-VL:  EffPnt/Date: \_\_\_\_\_  
Func Acty:  CPSC:  C/F:  Class:   
History:  Prel:  Reg:  Organiztn:   
Engineer:  Color: E Print:

Part=====	Acty	CPSC==	Seq	Release=====	C/F	S	CL	S	Date====
- F1VC	2B195 CG	NC00	060701	000 NC00E10300678000	F	R	P	R	93/05/20
<ESTR.& MSTR.CYL.ASY.BRK.....><.....>									
R	NONE			NC00E00444499608		F			
R	NONE			NC00E00444499705		F			
R	NONE			NC00E00444499718		F			
R	NONE			NC00E10129983001		F			
R	F1VC	2B195 CF	NC00	060701	000 NC00E10104848000		F		
B	F2AC	2B195 BA	NC00	060701	000 NC00E10171551000		F		
B	F3AC	2B195 CA	NC00	060701	000 NC00E10300678000		F		
B	F5AC	2B195 AA0	NC00	060701	000 NC00I10107232032		F		

SELECT=>> F=Function U=Usage N=Notice 4=UCC/Proc 5=DES/Funct 6=Service  
LAST

3713 7787

WWR8744A R136694C Next Assembly Reference Maintenance 99/01/14 19:24:57  
 Function : F Last Change: 94/02/15 MMH9217  
 Part Number : F2AC 2B091 BA  
 Function====> Acty: MC00 CPSC: 060202 . Seq: 000 C/FA: C Status: R  
 Release=====> Acty: MC00 Type: E Base: 10357590 Supp: 000 Status: R  
 S Next Assembly Part No. Quantity UM A Effective In Effective Out Act  
 - F3VC 2A201 BA 1 EA P XS4P93A XS4P94A  
 - MC00E10218420001 MC00E10218420002  
 - F4VC 2A201 AA 1 EA P XS4P94A S4P95A R  
 - MC00E10218420002 MC00E10357590000

Select: D=Delete W=Wght P=Procure F=Fa/Derived Usage L=Loc Codes G=Pgm Id  
F1=Updt F3=Part Verify F3=Proc F4=CofA F5=Prev Page F6=Rebuild N/A  
Function status is invalid for update.

LAST

3713 7788

(BA) <sup>1000/6</sup>  
F2VC-2B091-CC PASS  
F3VC-2B091-(<sup>pass</sup>) SWITC<sup>H</sup>  
                  (A) <sup>insert all</sup>

-2C320- JEW Block

-2B264-


ECU F3A-2C219-PA

HCU FAAC-2C185-PA

PT-SWIRL-FAAC-2C204-PA

N/C F3A-2C356-PA  
                  F3A-2C357-PA  
                  F3A-2C358-PA

3713 7789



3713 7790

Falcon				xxxxx xxxxx xxxxx xxxxx
Explorer				---- xxxxx xxxxx
Ranger				---- xxxxx xxxxx
Expedition				---- xxxxx xxxxx
Navigator				---- xxxxx xxxxx

xxxxx = used in model year

---- = may have been used in model year

- 6) Is this switch still in use? If not, why not? If so, what design changes have been implemented since 1992/1993?

Charlie Douglas of TI is investigating the design changes that may have been implemented on the brake pressure switch beginning in 1992.

- 7) What fault codes are stored if the brake pressure switch fails?

Regards,

Fred Porter            OV - fporter            fporter@ford.com  
Chassis E/E Systems Applications            (313)845-3722  
Bldg 5 - Mail Drop 5030 - Cubicle 3E004    Fax: 390-4145

<u>MODEL YEAR</u>	<u>VEHICLE</u>	<u>APPLICATION</u>	<u>SPEED CONTROL</u>
1992	Town Car Crown Vic Grand Marquis	Non ABS	PIA to Junction block -2.c.32.0- on frame rail (T.L.)
1992	Town Car Crown Vic Grand Marquis	ABS A&S/TC	PIA TO PROP VALVE MOUNTED ON FRAME RAIL (T.L.)
1993	Town Car Crown Vic Grand Marquis	Non ABS	PIA to Junction block on frame rail (T.L.)
1993	Town Car Crown Vic Grand Marquis	ABS A-BS/TC	SAME AS 92
1994	Town Car Crown Vic Grand Marquis	Non ABS/ABS	PIA to Junction block on frame rail (T.L.)
1994	Town Car Crown Vic Grand Marquis	ABS/TC	SAME AS 92,93
1995	Town Car Crown Vic Grand Marquis	Non ABS/ABS	PIA to Junction block on frame rail (T.L.)
1995	Town Car Crown Vic Grand Marquis	ABS/TC	PIA to prop valve mounted to bracket w/s to master cylinder (T.L.)
1996	Town Car Crown Vic Grand Marquis	Non ABS/ABS	PIA to Junction block on frame rail (T.L.)
1996	Town Car Crown Vic Grand Marquis	ABS/TC	PIA to master cylinder (T.L.)
1997	Town Car Crown Vic Grand Marquis	Non ABS/ABS	PIA to Junction block on frame rail (T.L.)
1997	Town Car Crown Vic Grand Marquis	ABS/TC	PIA to master cylinder (T.L.)
1998	Town Car Crown Vic Grand Marquis	All	Plunger type in pedal box

3713 7732



## Vehicle Owner's Questionnaire

1-888-424-9311

Office of Defects Investigation

Please provide your name, address, and phone number, as well as specific details about your vehicle and the problems you encountered with it. You may want to have your owner's manual handy as you proceed through the several screens of the questionnaire. Required information is marked with \*.

## Owner Information

\* First Name:  MI: \* Last Name: Organization: \* Address 1: Address 2: \* City:  \* State:  AK  \* Zip: *Action Code*PE98055*slightly less  
'93 cars than**'92*\* Home Phone: Work Phone:  Ext: Fax Number: Email Address: 

The Privacy Act prevents release of owner information without prior authorization.

Do you wish to request a mailed signature form, which will authorize NHTSA to provide a copy of the owner information along with the vehicle information contained in this report to the manufacturer of your vehicle?

 Yes 

## Vehicle Information

17 digit Vehicle Identification Number (VIN):   
(Located under windshield on driver's side dashboard)[Send mail to the Web Master](#)

3713 7788

FOR A COPY.

MPR  
1998 DEC 11

3713 7794

Page: 01

## CGIS DETAIL REPORT

12/07/98 15:14:14

CGIS Report Number: WJZAA135 Program Type: Q  
Report Source: MSS - FCSD - QSPSOrig Rpt #: 225951-98  
Report Date: 10/09/1998

JUC

## ----- REPORT SUMMARY -----

VEHICLE: 1993 TOWN CAR, SIGN SEDAN  
Engine: 4.6L ROMEO BASE EFI  
Operating Enviro: Vehicle Use:VIN: 1LMLM462WGPY [REDACTED]  
Odometer: 51,500 MILES  
WCC: 5D05  
Rep. Act:SYMPTOM: 3 01 0 00 CHASSIS OTHER (CODE NOT AVAILABLE) SERVICE BRAKE SYSTEM  
Additional Symptom: Other (Code Not Available)

Other Veh. With Concern: Severity Rating - Customer: Engineering:

Causal Component: 2B264 Feature: SWITCH BRK PRS WRN L  
Causal Factor: Loc: Photo: Images: 0  
Causal Condition: Component Test Status: RECALL LOC: Repair Effectiveness (%): 100  
Vehicle Fixed?: YES Customer satisfied?:

## ----- COMMENTS -----

--TYPE-- CONCERN: INITIALLY THE CUSTOMERS CONCERN WAS THAT THE VEHICLE WOULD NOT COME OUT OF PARK. WHILE IN THE DEALERSHIP, AN UNDERHOOD FIRE STARTED, CAUSED BY A LEAKING BRAKE FLUID THROUGH THE SWITCH INTO THE CONNECTOR. REPAIR: REPLACED THE SPEED CONTROL SWITCH AND CONNECTOR. REPLACED THE STOP LAMP SWITCH FOR THE ORIGINAL CUSTOMERS CONCERN. PER TECHNICIAN, THIS IS THE THIRD UNIT THAT HAD AN UNDERHOOD FIRE THAT APPEARED TO ORIGINATE FROM THIS AREA. THE OTHER TWO WERE TOO DAMAGED TO DETERMINE THE SPECIFIC LOCATION OF THE POINT OF THE ORIGIN. THE SWITCH AND CONNECTOR ARE PRESENTLY IN MY POSSESSION IN THE MEMPHIS REGIONAL OFFICE.

AUDIT -- 10/14/1998 09:56AM BRENDAN WENDEL MSS - FCSD - QSPS  
DEALER ID 68323 CHANGED TO 12098 BY SWENDEL

## ----- CONCERN DETAILS -----

----- DIAGNOSTIC INFORMATION -----  
 Symp. Verif?: Ease of Diagnosis: Level of Assistance:  
 Comp. Timing: Ease Timing: MIL light on?:  
 Test Stand: Road Test: SD Number:  
 Prior Repair Attempts: KOBC: Repair Prior to Call: NO  
 DTCS KODES: CS:  
 KOER: Equipment/Procedure Used effective? Equipment/Procedure Used effective?

## ----- SERVICE ACTIONS -----

Repair Type	Component Number	Number Type	Description	Causal Comp.
RPL	2B264	SERVICE	SWITCH BRK PRS WRN L	YES

## ----- VEHICLE DETAILS -----

Vehicle Build Date:	09/10/1992	Warranty Start Date:	02/08/1993
Date of Sale:	02/08/1993	Selling Dlr (Mkt,Dlr,Sub):	12098
Dealer Special Order:		Gross Vehicle Weight:	
LH/RH Drive:			

## ----- ENGINE -----

Engine: 4.6L ROMEO BASE EFI	Tag: 3G	812 AA
Bld Pt: Calb: 31&JR10 A		Serial #: W

REDACTED

3713 7795M

Page: 02

CQIS DETAIL REPORT

12/07/98 16:14:14

CQIS Report Number: NJ10A135 Program Type: Q Orig Rpt #: 225951-98  
Report Source: HSS - FCSD - QSPS Report Date: 10/09/1998

--- TRANSMISSION ---  
Trans: ADD-E 4SP ELEC O/D Part #: \_\_\_\_\_  
Bld Dt: \_\_\_\_\_ Serial #: \_\_\_\_\_  
Model: \_\_\_\_\_ Plt: \_\_\_\_\_ Shift: \_\_\_\_\_  
Axle: 8.8 3.08 CONVENTIONAL Ed Tag Code: \_\_\_\_\_ Bld Dt: \_\_\_\_\_  
Serial #: \_\_\_\_\_ Plt: \_\_\_\_\_  
--- ADDITIONAL ---  
Tire : P215/70R15 RSP Brand : \_\_\_\_\_  
Radio : ELECTR PREMIUM AM/FM STRO/CSTZ A/C : REC AIR CONDITIONER  
Paint : BLUE EXTERIOR PAINT FAMILY \_\_\_\_\_ AQUAMARINE FROST C/C

----- AFTER MARKET MODIFICATIONS -----

NO AFTER MARKET MODIFICATIONS DATA AVAILABLE FOR THIS VEHICLE

----- REPORT ORIGINATOR - REPAIR FACILITY - CUSTOMER INFORMATION -----  
Orig/Caller : KENNETH DYTRE Title: OTHER

Repair Dlr: 12098 - SCHILLING L-H/MENDENHALL INC Ph#: (901) 794-4000  
City: Memphis State : Tennessee  
Country: UNITED STATES Region : Memphis - 23

Claim #/Date : LIC#777 07/19/1998

Customer Name: \_\_\_\_\_

NO CQIS-VIN HISTORY AVAILABLE FOR THIS VEHICLE

--- SUPPLEMENTAL SURVEY: NONE

----- VEHICLE'S WARRANTY HISTORY (365 days only) -----

NO VEHICLE WARRANTY HISTORY AVAILABLE FOR THIS VEHICLE

Page: 01

## CQIS DETAIL REPORT

12/07/98 18:14:12

CQIS Report Number: VDQAAA322 Program Type: Q Orig Rpt #: 134596-97  
 Report Source: MSS - FCSD - QSF5 Report Date: 04/21/1997

## REPORT SUMMARY

VEHICLE: 1992 TOWN CAR,STAND,SEDAN VIN: 1LMLM81W6BT714787  
 Engine: 4.6L ROMEO BASE EFI Odometer: 56,502 MILES  
 Operating Environ: NCC: 5P07  
 Vehicle Use: Rep. Act:

SYMPTOM: 7 04 2 45 UNKNOWN SOURCE CONCERNS FIRE/SMOKE  
 SMOKE UNDERHOOD

Additional Symptom:  
 Other Veh. With Concern: Severity Rating - Customer: Engineering:  
 Causal Component: 2A574 Feature: SWITCH ASY LOW AIR P  
 Causal Factor: Loc:  
 Causal Condition: Photo: Images: 0  
 Component Test Status: Return Loc:  
 Vehicle Fixed?: YES Customer satisfied?: Repair Effectiveness (%): 100

## COMMENTS

TYPE COMMENT TEXT  
 CONCER THERE WAS SMOKE FROM UNDER THE HOOD.  
 REPAIR THE BRAKE PRESSURE SWITCH CAUGHT ON FIRE AND BURNED THE WIRING WITH THE KEY OFF. PREVIOUS VEHICLES WITH FIRES STARTING IN THIS AREA WERE SUMPT TO THE DEGREE THAT WE COULD ONLY GUESS WHAT CAUSED THE FIRE. THIS VEHICLE'S FIRE STOPPED SOON ENOUGH. WE REPLACED THE BRAKE PRESSURE SWITCH.  
 AUDIT 04/23/1998 10:18AM DATA ENTRY'S MSS - FCSD - QSF5  
 SYMPTOM 3 01 0 00 CHANGED TO 7 04 2 45 BY MEAKERS

## CONCERN DETAILS

## DIAGNOSTIC INFORMATION

Syng. Verif?:	Base of Diagnosis:	Level of Assistance:	
Comp. Timing:	Base Timing	MIL light on?	
Test Stand:	Road Test	AD Number:	
Prior Repair Attempts:		Repair Prior to Call: NO	
DTCs Known:	KOEC:		
KOER:	CB:		
Equipment/Procedure Used	Effective?	Equipment/Procedure Used	Effective?

## SERVICE ACTIONS

Repair Type	Component Number	Number	Description	Causal Comp.
RPL	2A574	TYPE SERVICE	SWITCH ASY LOW AIR P	YES

## VEHICLE DETAILS

Vehicle Build Date:	04/07/1992	Warranty Start Date:	10/02/1992
Date of Sale:	10/02/1992	Selling Dlr (Mkt,Dlr,Sub):	11627
Dealer Special Order:		Gross Vehicle Weight:	
LM/RH Drive:			

## --- ENGINE ---

Engine: 4.6L ROMEO BASE EFI	Tag: 2G	812 MA
Bld Dt:	Calb: 218JR05 A	Serial #: N

## --- TRANSMISSION ---

Trans: AOD-E 4SP ELEC O/D	Part #:	
Bld Dt:	Serial #:	
Model:	Plt:	Shift:

Page: 02

CQIS DETAIL REPORT

12/07/98 18:14:12

CQIS Report Number: VDVAAL1322 Program Type: Q  
Report Source: MSS - PCED - QSPS

Orig Rpt #: 134596-97  
Report Date: 04/21/1997

A N K L E ---  
Axle: 8.8 3.08 CONVENTIONAL ID Tag Code: Bid Dt:  
Serial #: ----- Flt:  
--- ADDITIONAL ---  
Tire : P215/70R15 NEW Brand :  
Radio : ELECTR PREMIUM AM/FM STRO/CSDR A/C : ATC AIR CONDITIONER  
Paint : BLUE EXTERIOR PAINT FAMILY ----- CLEAR CRYSTAL BLUE FROST C/C

----- AFTER MARKET MODIFICATIONS -----

NO AFTER MARKET MODIFICATIONS DATA AVAILABLE FOR THIS VEHICLE

----- REPORT ORIGINATOR - REPAIR FACILITY - CUSTOMER INFORMATION -----  
Orig/Caller : GEORGE TAYLOR Title: OTHER

Repair Dlr: 11627 - Ft Lauderdale L-M Inc Ph#: (954) 779-2060  
City: Ft Lauderdale State : Florida  
Country: UNITED STATES Region : Orlando - 24

Claim #:Date : 129844

Customer name : City :

----- C Q I S V I H S I S T O R Y -----

Date	CQIS Prog	Report #	Type	Symp Cat	Causal Part Description	Dealer Id
04/22/1997	VDVAAL13	EDSR	ELECT.	VALVE-FRT DISC BRK P		11627

----- S U P P L E M E N T A L S U R V E Y : NONE -----

----- VEHICLE'S WARRANTY HISTORY (365 days only) -----

Dealer ID	Date	Repair Order	Odometer	Per Causi	Service Part Number	Labor
			(Miles)	Wkr Cond.	Pfx Base	fix Operation
11627	04/21/1997		56802			

3713 7798

\*\* TOTAL PAGE.04 \*\*

\*\* TOTAL PAGE.05 \*\*



Central Laboratory  
16000 Century Drive  
Dearborn, MI 48120-1267  
FAX (313) 222-1614  
FAX (313) 322-1614

Report 9901571  
9900607  
9900226  
Multiple  
December 22, 1999

---

To: G. Stevens (313) 32-36886 (313) 39-0724 FAX

From: S. LaRouche (313) 84-54878

Subject: Speed Control Cut-off Switch  
Part Number: F2VY-9F924-A  
Specification: See Engineering Drawing  
Supplier: Texas Instruments

Received: Forty nine switches, identified in Appendix A, were received during the period of January, 1999 through May 1999. The switches were received from dealership, storage yard, and field surveys. The switches were received under three Central Laboratory work requests: 9900226, 9900607, and 9901571. The results from a previous investigation (Central Laboratory Report 9804105) will be included in this report for comparison. The components of the switches are identified in Appendix B.

---

Object: Evaluate the switches to assist in determining the cause of underhood fires.

Conclusion: See Table 1.

---

**Data and Analysis:**

**Test Protocol**

The switches received under laboratory work request 9900226 (identified as A, B, C, D, E(#1-1), and F), were disassembled and documented (Figures 1 through 81) in the presence of personnel from Texas Instruments. Any fluid, deposits, or residues found in the switches were analyzed using Fourier Transform Infrared Analysis (FTIR) and Scanning Electron Microscopy (SEM) with Energy Dispersive X-ray Spectroscopy (EDS). The Kapton seals were examined for cracks and leak paths, visually and with SEM. The results are summarized in Table 1. Results from the previous investigation (9804105, Reddick) are included in this table for comparison.

The switches received under laboratory work requests 9900607 and 9901571 were documented as-received, functionally tested (if applicable), and evaluated using the test protocol<sup>1</sup> listed in Appendix C. Switches were selected for disassembly and evaluation based on their performance during the functional tests. The interior components, fluids, deposits, and residues of the selected switches were analyzed using the same techniques used for laboratory work requests 9804105 and 9900226. The results are summarized in Table 1. The switches are documented in Figures 82 through 219.

---

<sup>1</sup> The test protocol was developed by S. Reimers and N. LePointe of Ford Motor Company, and Aziz Rahman of Texas Instruments. The protocol is based on the tests and results from laboratory work requests 9804105 and 9900226.

---

Concur: David Bell Jr.  
P. Klaas, Supervisor  
Metallurgy Section

By: J. L. R.  
Steven LaRouche (SLAROUCH)

Note: Table 1, Figures 1 through 219, and Appendices A through C were delivered to G. Stevens and S. Reimers on December 22, 1999.

SL/sl

# 8628

## Request for Central Laboratory Service

15000 Concourse Dr., Dearborn MI 48120-1267 Phone [313] 32-21676 FAX [313] 32-21614

All shaded areas must be filled in to process your request.

*(Administrative Use Only)*

Your Name (Send report to)		Telephone	Phone ID	FAX
<i>G. Stevens Sensitivity Control N. LaPointe</i>		<i>313 323 6682 313 594 7480</i>	<i>G. STEVENS N. LAPONTE</i>	<i>313 320 7774 313 337 8256</i>
Specimen To				
Room No./Mail Drop/PO Box	Department/Activity	Building	Location Code	Dept. #
<i>MN SIDE/26063 BVT MATS</i>	<i>5A-45</i>	<i>5A</i>	<i>T13</i>	<i>X06644</i>

Total # of Samples	Sample Handling	TOXIC/CAW	Source	Supplier Code
<i>17</i>	<input checked="" type="checkbox"/> Return after test <input type="checkbox"/> Dispose after test <input type="checkbox"/> Dispose after 30 days			
Part/Material Name	Sample Identification (Contingent below if needed)	Part Number (If any)	Material Specification (If any)	CPCS Code
<i>Sensit. Control</i>	<i>SEE ATTACHED</i>	<i>E2VY-9P94A</i>	<i>NA</i>	<i>TEXAS INSTRUMENTS</i>
<i>Current Status</i>	<i>SUSP</i>			

Name of Investigation/Specific Test Required (Check all that apply)	Request Info. Box (For requester use)	
<input type="checkbox"/> Production/Test problem	<input checked="" type="checkbox"/> Perform Test as in Lab No. <i>549432617</i>	
<input checked="" type="checkbox"/> Failure Analysis	<input type="checkbox"/> Photographs (Describe below)	
<input type="checkbox"/> Legal	<input type="checkbox"/> Use Specification _____ as a guide	
<input type="checkbox"/> Specification Compliance	<input type="checkbox"/> Other (Describe below)	
Stop testing upon failure?	Does this appear CAB testing? (If "Yes", what is the expected outcome?)	Do you need to know your CL contact and phone?
<input type="checkbox"/> No <input checked="" type="checkbox"/> Yes	<input checked="" type="checkbox"/> No <input type="checkbox"/> Yes	<input type="checkbox"/> Yes

### Additional Sample Information/Testing Requirements

*PERFORM TESTS AS IN 99061 TO ASSIST IN DETERMINING  
CAUSE OF POSSIBLE LEAKAGE/FIRE. ADDITIONAL SWATCHES  
MAY FOLLOW.*

*CC: Steve Stevens  
Power Supply & Enviro. Tech  
3E 008/5081  
Bldg #5*

Format (Check all that apply)			
Date you would like report	<i>7-1-97</i>	<input checked="" type="checkbox"/> FAX preliminary results <input type="checkbox"/> FAX hand written	<input checked="" type="checkbox"/> Mail typed report
Date you must have report	<i>7-1-97</i>	<input type="checkbox"/> FAX typed report <input checked="" type="checkbox"/> Mail hand written	<input type="checkbox"/> Electronically transfer report
<small>For information about services or assistance in completing this form please refer to the Central Laboratory WEB page. Laboratory number and date cannot be assigned without receipt of samples. Samples will be disposed of after 30 days unless otherwise indicated above.</small>			
<small>[www.gvsu.edu/central/forms.htm]</small>			

# 8514 5L

## Request for Central Laboratory Service

13000 Century Dr., Dearborn MI 48120-1247 Phone [313] 22-31674 FAX [313] 22-31614

All stated areas must be filled in to process your request Informational Use Only					
		Laboratory Number	Date		
		49002607	2-12-99 5L		
Your Name (Send report to)		Telephone	PROFS ID	FAX	
STEVEN S. STEVENS		313 323 6685	STEVEN1	313 390 7722	
Secondary Contact:		Telephone	PROFS ID	FAX	
NURSE IN PRACTICE		313 944 2186	NURSE1	313 337 8256	
Spec Request To:					
Room No/Mail Drop/PO Box	Department/Activity	Billing	Location Code	Dept. #	Work Task # (For 3100 Use Only)
MHSXN 260X5 AYT MATERIALS		#5	5100	T13	XQ604
Total # of Samples	Sample Handling		TON/CASE	SOURCE	Supplier Code
21	<input checked="" type="checkbox"/> Return after test <input type="checkbox"/> Dispose after test <input type="checkbox"/> Dispose after 30 days				
Test/Material Name	Sample Identification (Continue below if needed)	Part Number (if any)	Material Specification (if any)	CPSC Code	Supplier
SWEEPS CIRCUIT	SEE ATTACH-3	F2VY 919121A	NA		INTER'S
CUT-OUT SWITCH					

Investigation		Request Info. Box (For requester use)	
Name of investigation/Specific Test Required (Check all that apply) <input checked="" type="checkbox"/> Production/test problem <input type="checkbox"/> Perform Test as in Lab No. _____ <input checked="" type="checkbox"/> Failure Analysis <input type="checkbox"/> Photograph (Describe below) <input checked="" type="checkbox"/> Legal <input type="checkbox"/> Use Specification _____ as a guide <input type="checkbox"/> Specification Compliance <input type="checkbox"/> Other (Describe below)			
Stop testing upon failure?	<input type="checkbox"/> No <input checked="" type="checkbox"/> Yes	Does this report CAE testing? (If "Yes", what is the expected outcome?) <input type="checkbox"/> No <input checked="" type="checkbox"/> Yes	Do you need to know your CL contact and phone? <input checked="" type="checkbox"/> Yes

Additional Sample Information/Testing Requirements					
EX: ---, DUE TO ---, NEED ANALYZE SWITCHING TO --- FOR TEST ESTABLISHES THAT N-LIN POWER TO METER IN DETERMINED CORRECT BUT PUSHER SWITCH FINS ON 1 SAMPLE.					
SWITCHES ARE FINES, FIXES, SWINGS, MILES, SWIVELS, ETC. PULLS					
Report					

Format (Check all that apply)	
Does you would like report <input checked="" type="checkbox"/> 4-1-59	<input type="checkbox"/> FAX preliminary results <input type="checkbox"/> FAX hand written
Does you want report <input checked="" type="checkbox"/> 4-1-59	<input type="checkbox"/> FAX typed report <input type="checkbox"/> Mail hand written

- Mail typed report
- Electronically transfer report
- Phone preliminary results

For information about services or assistance in completing this form please refer to the Central Laboratory Web page. Laboratory number and date cannot be assigned without receipt of sample. Samples will be disposed of after 30 days unless otherwise indicated above.

# Request for Central Laboratory Service

19000 Conroy Dr., Dearborn, MI 48120-1267 Phone [313] 32-21676 FAX [313] 32-21614

All shaded areas must be filled in to process your request Laboratory Use Only					
Your Name [Send report to]		Telephone	PROPS ID	FAX	
<i>G. Stevens</i>		<i>366-810</i>	<i>GSTEVEN1</i>	<i>366-810</i>	
Secondary Contact		Telephone	PROPS ID	FAX	
<i>N. L. P.</i>		<i>426-810</i>	<i>NL.P.</i>	<i>426-810</i>	
Send Report To:		N/A			
Box No/Mail Drop/PO Box	Department/Activity	Billing	Location Code	Dept. #	Work Task # (For 5400 Loc. Only)
<i>MD 5016</i>	<i>MATERIALS MGT</i>	<i>BLOCK 7</i>	<i>S100</i>	<i>T13</i>	<i>X005401</i>
Total # of Samples:	Sample Handling		TO/RCA/SH	Source	Supplier Code
<input checked="" type="checkbox"/> Return after test <input type="checkbox"/> Dispose after test <input type="checkbox"/> Dispose after 30 days					
Part/Material Name	Sample Identification [Continue below if needed]	Part Number [If any]	Material Specification [If any]	CPRC Code	Supplier
<i>SPECIAL CIRCUITS</i> <i>EXTERNAL SWITCH</i>	<i>A, B, C, D, E/E), A/W</i>	<i>F304 S4701A MA</i>			<i>TEAMS</i>
	<i>E</i>				
Instructions					
Nature of Investigation/Specific Tests Required [Check all that apply]				Requester Info. Box [For requestor use]	
<input type="checkbox"/> Production/Process problem <input type="checkbox"/> Perform Test w/ Lab No. _____ <input checked="" type="checkbox"/> Failure Analysis <input type="checkbox"/> Photograph [Describe below] <input checked="" type="checkbox"/> Legal <input type="checkbox"/> Use Specification _____ as a guide <input type="checkbox"/> Specification Compliance <input type="checkbox"/> Other [Describe below]					
Do you want upon follow?	Does this support CAE testing? <input type="checkbox"/> Yes, what brief expected outcome?			Do you want to know your CL contact and name? <input type="checkbox"/> Yes	
<input type="checkbox"/> No <input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No <input checked="" type="checkbox"/> Yes				
Additional Sample Information/Testing Requirements					
<i>Dissassemble samples for inspection and determine failure Test insulation</i>					
<i>Perform analysis to assess jet determined cause as possible Supply fine wire insulation</i>					
Report					
Format [Check all that apply]					
<input checked="" type="checkbox"/> Mail typed report <input type="checkbox"/> FAX preliminary results <input type="checkbox"/> FAX hand written <input type="checkbox"/> FAX typed report <input type="checkbox"/> Mail hand written <input type="checkbox"/> Electronically transfer report <input type="checkbox"/> Phone preliminary results					

For information about services or assistance in completing this form please refer to the Central Laboratory WEB page.  
 Laboratory number and date cannot be assigned without receipt of samples.  
 Samples will be disposed of after 30 days unless otherwise indicated above.



Central Laboratory

Reports 9900226

9900607

9901571

---

Table 1  
Appendices A, B, and C