

EA02-025

FORD 10/27/03

APPENDIX N

BOOK 31 OF 61

PART 1 OF 4

Expected

Date of Inspection: 9/22/00

Inspected by: BK

Data Form for Examination and Disassembly of Brake Switch

GENERAL INFORMATION

Long Tag Number: 0070863490

VIN: 1LNEM82W5N [REDACTED] Date: 07/28/92

Vehicle Location - City: DETROIT

Vehicle Location - State: MICHIGAN

Vehicle Model: TOWN CAR

Vehicle Model - Year: 1992

Part Prefix Number: F2VC

Part Base Number: 9F924

Part Suffix Number: AB

Date Code: 2052

Base Physical Condition Notes: SIGNIFICANT DEBRIS ON EXTERIOR SURFACE HEX PORT SURFACES RUSTED, RESIDUE ON TERMINAL CONTACTS.

Overall External Beginning Photo Number: 7501

Overall External Ending Photo Number: 7514

Resistance: Terminal-to-Terminal: 12 Ω

Resistance: Stationary Terminal to Hex Port: 65.1 k Ω

Resistance: Moveable Terminal to Hex Port: 440 M Ω

CONNECTOR INFORMATION

Connector Present (y/n): No

Res: Terminal-to-Terminal w/ Connector: _____

Res: Stationary Term to Hex Port w/ Connector: _____

Res: Moveable Term to Hex Port w/ Connector: _____

Connector/Seal Start Photo No: _____

Connector/Seal End Photo No: _____

Connector Seal Notes: _____

Connector Engagement Notes: _____

Exponent

INFORMATION AFTER REMOVAL OF ALUMINUM

CRIMP RING

Loose Liquid or material Collected from Inside the Base:

Liquid Contaminant.

Aluminum Crimp Ring Condition Notes: Loose

Distorted Contaminant. Minor Contaminant

Interior of Base Condition Notes: Liquid In Base.

Residue on Terminal. Spring Arm

Partially Broken In Center of Arm.

INFO AFTER OPENING CUP

Interior Hexport Condition Notes: White Marks on

Gasket.

Cup-Washer-Kapton Condition Notes: White Marks

on Surface of Kapton Layer 1.

KAPTON LAYERS

LAYER 1

Kapton Layer 1 Brake Fluid Side Condition: Distorted

Appearance. White Marks on Surface.

Tear from 0 to 4 O'clock. Tear At 8

O'clock. Tear from 9 to 12 O'clock.

Kapton Layer 1 Brake Fluid Side Start Photo #: 7512

Kapton Layer 1 Brake Fluid Side end Photo #: 7517

Hexport-Cup Condition Notes: Cup Expansive

Fluid Contaminant, Distorted Arm

Residue Present

Al Crimp-Base-Hex Port Start Photo No: 7515

Al Crimp-Base-Hex Port End Photo No: 7523

Interior Hexport Photo Start No: 7524

Interior Hexport Photo End No: 7527

Cup-Washer-Kapton Photo Start No: 7528

Cup-Washer-Kapton Photo End No: 7531

Kapton Layer 1 Switch Side Condition: Residue Evidence

of Degradation. Multiple Tears

from 12 to 3 O'clock. Tear from

7 to 9 O'clock.

Kapton Layer 1 Switch Side Start Photo #: 7601

Kapton Layer 1 Switch Side end Photo #: 7604

Expend

LAYER 2

Kapton Layer 1 Brake Fluid Side Condition: BUSE
EVIDENCE OF DECONTAMINATION TEAR AT 2
0'clock. TEAR AT 3 O'clock MULTIPLE
CIRCUMFERENTIAL TEARS FROM 3 to
12 O'clock. CIRCUMFERENTIAL BUCK LINE
FROM 6 to 11 O'clock
 Kapton Layer 2 Brake Fluid Side Start Photo #: 7605
 Kapton Layer 2 Brake Fluid Side end Photo #: 7607

Kapton Layer 2 Switch Side Condition: _____

 Kapton Layer 2 Switch Side Start Photo #: 7608
 Kapton Layer 2 Switch Side end Photo #: 7610

LAYER 3

Kapton Layer 3 Brake Fluid Side Condition: BUSE
EVIDENCE OF DECONTAMINATION DARKENED
APPEARANCE. TEAR AT 7 O'clock

 Kapton Layer 3 Brake Fluid Side Start Photo #: 7611
 Kapton Layer 3 Brake Fluid Side end Photo #: 7612

Kapton Layer 3 Switch Side Condition: PMK
RESIDUE ON SURFACE

 Kapton Layer 3 Switch Side Start Photo #: 7614
 Kapton Layer 3 Switch Side end Photo #: 7616

WASHER-CUP-BUTTON ASSEMBLY

Washer-Cup-Button Assembly Condition: PARTE FINE
COVER. NASTH BEVER AND BOTTOM
SURFACES DISCOURSED

 Washer-Cup-Button Photo Start Number: 7617
 Washer-Cup-Button Photo End Number: 7626

Exponent
Date of Inspection: 9/24/00

Inspected by: BK

Data Form for Examination and Disassembly of Brake Switch

GENERAL INFORMATION

Log Tag Number: 0070376840
VIN: 2MECM74WXXNA BUCK DATA: AS/07/92
Vehicle Location - City: PRO GRANDE CITY
Vehicle Location - State: TEXAS
Vehicle Model: GRAND MARQUIS
Vehicle Model - Year: 1992
Part Prefix Number: F2VC
Part Base Number: 9F924
Part Suffix Number: AB
Date Code: 4138A

Resistance: Terminal-to-Terminal: 284.5 k Ω
Resistance: Stationary Terminal to Hex Port: 18.12 M Ω
Resistance: Movable Terminal to Hex Port: 19.20 M Ω

CONNECTOR INFORMATION

Connector Present (y/n): YES
Res: Terminal-to-Terminal w/ Connector: _____
Res: Stationary Term to Hex Port w/ Connector: _____
Res: Movable Term to Hex Port w/ Connector: _____
Connector/Seal Start Photo No: 7715
Connector/Seal End Photo No: 7718
Connector Seal Notes: _____

Base Physical Condition Notes: DISASSEMBLED
EXTERNAL SURFACE - RESIDUAL OIL
INTERIOR OF BASE AND TERMINAL
CONTACTS.

Overall External Beginning Photo Number: 7701
Overall External Ending Photo Number: 7714

Connector Engagement Notes: Electrical Parts
NO RESISTANCE NO RESISTANCE
MEASUREMENTS TAKEN.

Exponent

INFORMATION AFTER REMOVAL OF ALUMINUM CRIMP RING

Loose Liquid or material Collected from Inside the Base:

Aluminum Crimp Ring Condition Notes: Clean & dry

Interior of Base Condition Notes: Residue on

Base And CONTACTS

Hexport-Cup Condition Notes: Residue on External Surface of Cup.

Al Crimp-Base-Hex Port Start Photo No: 7719

Al Crimp-Base-Hex Port End Photo No: 7725

INFO AFTER OPENING CUP

Interior Hexport Condition Notes: _____

Interior Hexport Photo Start No: 7726

Interior Hexport Photo End No: 7728

Cup-Washer-Kapton Condition Notes: _____

Cup-Washer-Kapton Photo Start No: 7730

Cup-Washer-Kapton Photo End No: 7732

KAPTON LAYERS

LAYER 1

Kapton Layer 1 Brake Fluid Side Condition: Buzz

Evidence of Deformation. Torn from

7 to 8 o'clock. Silver-colored

Debris on Surface

Kapton Layer 1 Switch Side Condition: _____

Kapton Layer 1 Brake Fluid Side Start Photo #: 7733

Kapton Layer 1 Brake Fluid Side end Photo #: 7735

Kapton Layer 1 Switch Side Start Photo #: 7801

Kapton Layer 1 Switch Side end Photo #: 7804

Exponcat

LAYER 2

Kapton Layer 1 Brake Fluid Side Condition: _____

Kapton Layer 2 Brake Fluid Side Start Photo #: 7805

Kapton Layer 2 Brake Fluid Side end Photo #: 7807

Kapton Layer 2 Switch Side Condition: _____

Kapton Layer 2 Switch Side Start Photo #: 7808

Kapton Layer 2 Switch Side end Photo #: 7810

LAYER 3

Kapton Layer 3 Brake Fluid Side Condition: Good

Excess of Determination.

Kapton Layer 3 Brake Fluid Side Start Photo #: 7811 if not

Kapton Layer 3 Brake Fluid Side end Photo #: 7813

Kapton Layer 3 Switch Side Condition: _____

Kapton Layer 3 Switch Side Start Photo #: 7814

Kapton Layer 3 Switch Side end Photo #: 7816

WASHER-CUP-BUTTON ASSEMBLY

Washer-Cup-Button Assembly Condition: Good

Good And Dry

Washer-Cup-Button Photo Start Number: 7817

Washer-Cup-Button Photo End Number: 7831

Exponent

Date of Inspection: 9/25

Inspected by: BK

Data Form for Examination and Disassembly of Brake Switch

GENERAL INFORMATION

Long Tag Number: 0070907663

VIN: 2FACP74W1N2 Build Date: 06/15/92

Vehicle Location - City: GAOSEN

Vehicle Location - State: ALABAMA

Vehicle Model: CROWN VICTORIA

Vehicle Model - Year: 1992

Part Prefix Number: FZVC

Part Base Number: 9F924

Part Suffix Number: AB

Date Code: 201B

Base Physical Condition Notes: Diagram on

EXTERIOR SURFACE - BASE INTERNAL

SURFACE MOUNT.

Overall External Beginning Photo Number: 7901

Overall External Ending Photo Number: 7914

Resistance: Terminal-to-Terminal: 1.1 Ω

Resistance: Stationary Terminal to Hex Port: 7.11 M Ω

Resistance: Movable Terminal to Hex Port: 7.72 M Ω

CONNECTOR INFORMATION

Connector Present (y/n): NO

Res: Terminal-to-Terminal w/ Connector: _____

Res: Stationary Term to Hex Port w/ Connector: _____

Res: Movable Term to Hex Port w/ Connector: _____

Connector/Seal Start Photo No: _____

Connector/Seal End Photo No: _____

Connector Seal Notes: _____

Connector Engagement Notes: _____

Exponent

INFORMATION AFTER REMOVAL OF ALUMINUM CRIMP RING

Loose Liquid or material Collected from Inside the Base:

Aluminum Crimp Ring Condition Notes:

Interior of Base Condition Notes: INTERIOR BASE
Moist with fluid. PORTING SCARS
Area TERMINAL COVERED WITH RESIDUE.

INFO AFTER OPENING CUP

Interior Hexport Condition Notes WHITE MARRAS
OR GREY

Cup-Washer-Kapton Condition Notes: WHITE MARRAS
OR KAPTON LAYER 1.

KAPTON LAYERS

LAYER 1

Kapton Layer 1 Brake Fluid Side Condition: BROWN
EVIDENCE OF DEGRADATION. TEAR FROM
7 to 2 O'clock. TEAR FROM 8 to 1
O'clock. DARK MARRAS AND RESIDUE
PRESENT

Kapton Layer 1 Brake Fluid Side Start Photo #: 7929
Kapton Layer 1 Brake Fluid Side end Photo #: 7931

Hexport-Cup Condition Notes:

AI Crimp-Base-Hex Port Start Photo No: 7915
AI Crimp-Base-Hex Port End Photo No: 7921

Interior Hexport Photo Start No: 7922
Interior Hexport Photo End No: 7925

Cup-Washer-Kapton Photo Start No: 7926
Cup-Washer-Kapton Photo End No: 7928

Kapton Layer 1 Switch Side Condition: BROWN SURFACE
OF DEGRADATION. TEAR FROM 11
to 4 O'clock. TEAR FROM

Kapton Layer 1 Switch Side Start Photo #: 7932
Kapton Layer 1 Switch Side end Photo #: 7934

Exponent

LAYER 2

Kapton Layer 1 Brake Fluid Side Condition: Damage
Evidence of DECONTAMINATION TEAR FROM
7 to 10'clock.

Kapton Layer 2 Brake Fluid Side Start Photo #: 8001

Kapton Layer 2 Brake Fluid Side end Photo #: 8004

LAYER 3

Kapton Layer 3 Brake Fluid Side Condition: Damage
Evidence of DECONTAMINATION

Kapton Layer 3 Brake Fluid Side Start Photo #: 8008

Kapton Layer 3 Brake Fluid Side end Photo #: 8010

WASHER-CUP-BUTTON ASSEMBLY

Washer-Cup-Button Assembly Condition: Parts Missing
With Fluid

Washer-Cup-Button Photo Start Number: 8014

Washer-Cup-Button Photo End Number: 8032

Kapton Layer 2 Switch Side Condition: Damage
Evidence of DECONTAMINATION TEAR
FROM

Kapton Layer 2 Switch Side Start Photo #: 8005

Kapton Layer 2 Switch Side end Photo #: 8007

Kapton Layer 3 Switch Side Condition: Damage
REPAIR IN CONTACT.

Kapton Layer 3 Switch Side Start Photo #: 8011

Kapton Layer 3 Switch Side end Photo #: 8013

Expend

Date of Inspection: 9/25/00

Inspected by: BK

Data Form for Examination and Disassembly of Brake Switch

GENERAL INFORMATION

Log Tag Number: 0071184661

VIN: 1LNLM81W3PY Build Date: 10/02/92

Vehicle Location - City: TUCSON

Vehicle Location - State: ARIZONA

Vehicle Model: TOWN CAR

Vehicle Model - Year: 1993

Part Prefix Number: F2VC

Part Base Number: 9F924

Part Suffix Number: AB

Date Code: 2036

Base Physical Condition Notes: DEBRIS on

EXTERNAL SURFACE, INTERIOR OF BASE

AND TERMINAL CONTACTS ARE CLEAN

AND DRY.

Overall External Beginning Photo Number: 8101

Overall External Ending Photo Number: 8114

Resistance: Terminal-to-Terminal: .1 Ω

Resistance: Stationary Terminal to Hex Port: OPEN

Resistance: Moveable Terminal to Hex Port: OPEN

CONNECTOR INFORMATION

Connector Present (y/n): No

Res: Terminal-to-Terminal w/ Connector: _____

Res: Stationary Term to Hex Port w/ Connector: _____

Res: Moveable Term to Hex Port w/ Connector: _____

Connector/Seal Start Photo No: _____

Connector/Seal End Photo No: _____

Connector Seal Notes: _____

Connector Engagement Notes: _____

Exponent

INFORMATION AFTER REMOVAL OF ALUMINUM CRIMP RING

Loose Liquid or material Collected from Inside the Base:

Alumina Crimp Ring Condition Notes: Clear & Dry.

Interior of Base Condition Notes: Clear & Dry

Trace of Pin Groove on Spring Arm After Disassembly -

Hexport-Cup Condition Notes: Clear & Dry

AI Crimp-Base-Hex Port Start Photo No: 8115

AI Crimp-Base-Hex Port End Photo No: 8122

INFO AFTER OPENING CUP

Interior Hexport Condition Notes: WHITE MARKS

on left

Interior Hexport Photo Start No: 8123

Interior Hexport Photo End No: 8126

Cup-Washer-Kapton Condition Notes: WHITE MARKS

on Kapton Layer 1. Kapton Layer 1 & 2 raised from Cup during disassembly. Layer 1 & 2 were marked for removal from Cup prior to marking Layer 3.

Cup-Washer-Kapton Photo Start No: 8127

Cup-Washer-Kapton Photo End No: 8130

KAPTON LAYERS

LAYER 1

Kapton Layer 1 Brake Fluid Side Condition: WHITE MARKS ON SURFACE. BEGINS EVIDENCE OF DEGRADATION FROM 4 to 11 O'clock. Multiple Tears In Center, From 8 to 9 O'clock. Patch Marked At 6 O'clock.

Kapton Layer 1 Brake Fluid Side Start Photo #: 8131

Kapton Layer 1 Brake Fluid Side end Photo #: 8133

Kapton Layer 1 Switch Side Condition: Visible Evidence of Degradation. Tear From 7 to 2 O'clock. One Tear.

Kapton Layer 1 Switch Side Start Photo #: 8134

Kapton Layer 1 Switch Side end Photo #: 8136

Exponent

LAYER 2

Kapton Layer 1 Brake Fluid Side Condition: 7091E
EVIDENCE OF DISINTEGRATION. TRIM AT
11 O'CLOCK. TRIM AT 11 O'CLOCK.

Kapton Layer 2 Brake Fluid Side Start Photo #: 8201

Kapton Layer 2 Brake Fluid Side end Photo #: 8204

Kapton Layer 2 Switch Side Condition: _____

Kapton Layer 2 Switch Side Start Photo #: 8205

Kapton Layer 2 Switch Side end Photo #: 8207

LAYER 3

Kapton Layer 3 Brake Fluid Side Condition: _____

Kapton Layer 3 Brake Fluid Side Start Photo #: 8208

Kapton Layer 3 Brake Fluid Side end Photo #: 8210

Kapton Layer 3 Switch Side Condition: DRY

PERIOD ON SURFACES.

Kapton Layer 3 Switch Side Start Photo #: 8211

Kapton Layer 3 Switch Side end Photo #: 8213

WASHER-CUP-BUTTON ASSEMBLY

Washer-Cup-Button Assembly Condition: FRAY DRY

DISINTEGRATION ON WASHER BUSH.

Washer-Cup-Button Photo Start Number: 8214

Washer-Cup-Button Photo End Number: 8234

Exponent

Date of Inspection: 9/25/00

Inspected by: Bk

Data Form for Examination and Disassembly of Brake Switch

GENERAL INFORMATION

Long Tag Number: 0071389672
 VIN: 2MECM79W7NA Build Date: 02/26/92
 Vehicle Location - City: HAOUY
 Vehicle Location - State: LOUISIANA
 Vehicle Model: GRAND MARQUIS
 Vehicle Model - Year: 1992

Part Prefix Number: F2VC
 Part Base Number: 9F924
 Part Suffix Number: A8
 Date Code: 2015

Resistance: Terminal-to-Terminal: 71.1 k Ω
 Resistance: Stationary Terminal to Hex Port: 128.9 k Ω
 Resistance: Movable Terminal to Hex Port: 4.6 Ω

CONNECTOR INFORMATION

Connector Present (y/n): No
 Res: Terminal-to-Terminal w/ Connector: _____
 Res: Stationary Term to Hex Port w/ Connector: _____
 Res: Movable Term to Hex Port w/ Connector: _____
 Connector/Seal Start Photo No: _____
 Connector/Seal End Photo No: _____
 Connector Seal Notes: _____

Base Physical Condition Notes: DEBRIS ON
EXTERNAL SURFACE. INTERNAL OF
BASE MOIST. DEBRIS PASSING.

Overall External Beginning Photo Number: 8301
 Overall External Ending Photo Number: 8314

Connector Engagement Notes: _____

Exponent

INFORMATION AFTER REMOVAL OF ALUMINUM CRIMP RING

Loose Liquid or material Collected from Inside the Base:
Liquid + Material Collected From Base.

Aluminum Crimp Ring Condition Notes: Liquid And
Material Collected From Crimp Ring.

Interior of Base Condition Notes: Liquid In Base.
Spring And Detached At Bottom. Transferred
Pin And Remnant Of Spring And Lead In
Base.

INFO AFTER OPENING CUP

Interior Hexport Condition Notes White Material
Found.

Cup-Washer-Kapton Condition Notes: White Material
At Kapton Layers.

KAPTON LAYERS

LAYER 1

Kapton Layer 1 Brake Fluid Side Condition: Visible Evidence
of Penetration. White Material and Springs.
From Fan 9 to 12 O'clock. Better
Material At 4 And 7 O'clock.

Kapton Layer 1 Brake Fluid Side Start Photo #: 8331

Kapton Layer 1 Brake Fluid Side end Photo #: 8333

Hexport-Cup Condition Notes: Cup Evidence
Disclosed And Residual Cup

At Crimp-Base-Hex Port Start Photo No: 8315

At Crimp-Base-Hex Port End Photo No: 8323

Interior Hexport Photo Start No: 8324

Interior Hexport Photo End No: 8327

Cup-Washer-Kapton Photo Start No: 8328

Cup-Washer-Kapton Photo End No: 8330

Kapton Layer 1 Switch Side Condition: Visible Evidence
of Penetration. From At 4 And
10 O'clock. Cup End.

Kapton Layer 1 Switch Side Start Photo #: 8334

Kapton Layer 1 Switch Side end Photo #: 8336

Exposure

LAYER 2

Kapton Layer 1 Brake Fluid Side Condition: Trace
Surface of Determination, Term From
4 to 5 O'clock And AT 7:00 AM.
Circumferential Black Mark From 2 to 4
O'clock. Circumferential Ann Radial Burr
Mark at 7:00 O'clock.
Kapton Layer 2 Brake Fluid Side Start Photo #: 8401
Kapton Layer 2 Brake Fluid Side end Photo #: 8404

Kapton Layer 2 Switch Side Condition: Trace Surface
of Determination, Term At 5:10 And
11 O'clock, Term From 7 to 8 O'clock
One End.
Kapton Layer 2 Switch Side Start Photo #: 8405
Kapton Layer 2 Switch Side end Photo #: 8407

LAYER 3

Kapton Layer 3 Brake Fluid Side Condition: Trace Surface
of Determination, Term At 2 And 6 O'clock.
Trace Term From 3 to 5 O'clock.
Kapton Layer 3 Brake Fluid Side Start Photo #: 8408
Kapton Layer 3 Brake Fluid Side end Photo #: 8410

Kapton Layer 3 Switch Side Condition: Trace Surface
of Determination, Radial and Surface
Kapton Layer 3 Switch Side Start Photo #: 8411
Kapton Layer 3 Switch Side end Photo #: 8413

WASHER-CUP-BUTTON ASSEMBLY

Washer-Cup-Button Assembly Condition: Trace From
Center. Radial Phase Discoloration Ann
Radius Covered.

Washer-Cup-Button Photo Start Number: 8414
Washer-Cup-Button Photo End Number: 8434

Exponent

Date of Inspection: 9/26/00

Inspected by: BK

Data Form for Examination and Disassembly of Brake Switch

GENERAL INFORMATION

Long Tag Number: 007112.1973
 VIN: 2MELM7SN0X Build Date: 05/04/92
 Vehicle Location - City: HEIDELBERG
 Vehicle Location - State: PENNSYLVANIA
 Vehicle Model: JAWA MARGUIS
 Vehicle Model - Year: 1992

Part Prefix Number: FZVC
 Part Base Number: 9F924
 Part Suffix Number: AB
 Date Code: 2031

Resistance: Terminal-to-Terminal: 92.8 Ω
 Resistance: Stationary Terminal to Hex Port: 3.371 MΩ
 Resistance: Moveable Terminal to Hex Port: 3.470 MΩ

CONNECTOR INFORMATION

Connector Present (y/n): - No
 Res: Terminal-to-Terminal w/ Connector: _____
 Res: Stationary Term to Hex Port w/ Connector: _____
 Res: Moveable Term to Hex Port w/ Connector: _____
 Connector/Seal Start Photo No: _____
 Connector/Seal End Photo No: _____
 Connector Seal Notes: _____

Base Physical Condition Notes: DECALS ON EXTERIOR
SURFACE HARD-PAINT SURFACE RAISED
INTEGRAL OF BASE MOUNT WITH
FLUID.

Overall External Beginning Photo Number: 8501
 Overall External Ending Photo Number: 8514

Connector Engagement Notes: _____

Experiment

INFORMATION AFTER REMOVAL OF ALUMINUM CRIMP RING

Loose Liquid or material Collected from Inside the Base:

Aluminum Crimp Ring Condition Notes: LOOSE MATERIAL
COLLECTED FROM CRIMP RING. CONCENTRATED
PARTICULATE ON INTERIOR SURFACE.

Interior of Base Condition Notes: INFORMATION OF BASE
MOIST AND RESIDUAL CORROSION SPRING ARM
DAMAGE AT EQUATOR.

INFO AFTER OPENING CUP

Interior Hexport Condition Notes: WHITE MARKS ON
COCKET.

Cup-Washer-Kapton Condition Notes: WHITE MARKS
ON KAPTON LAYER 1.

KAPTON LAYERS

LAYER 1

Kapton Layer 1 Brake Fluid Side Condition: DONOR EVIDENCE
OF DETERIORATION. TEAR FROM 11 to 4 O'clock
TO TEAR IN CENTER. TEAR FROM 10 to 5
O'clock. BRUISE REMAINS AROUND CIRCUMFERENCE
MARKS AT 10 O'clock. WHITE MARKS ON
SURFACE. ONE TEAR
Kapton Layer 1 Brake Fluid Side Start Photo #: 8511
Kapton Layer 1 Brake Fluid Side end Photo #: 8513

Hexport-Cup Condition Notes: CUP SURFACE
DISCOLORED AND RESIDUAL CORROSION

AI Crimp-Base-Hex Port Start Photo No: 8515
AI Crimp-Base-Hex Port End Photo No: 8522

Interior Hexport Photo Start No: 8523
Interior Hexport Photo End No: 8526

Cup-Washer-Kapton Photo Start No: 8527
Cup-Washer-Kapton Photo End No: 8530

Kapton Layer 1 Switch Side Condition: DONOR EVIDENCE
OF DETERIORATION. TEAR AT 1 O'clock
ONE TEAR

Kapton Layer 1 Switch Side Start Photo #: 8534
Kapton Layer 1 Switch Side end Photo #: 8536

Expend

LAYER 2

Kapton Layer 1 Brake Fluid Side Condition: Trace Evidence
OF DEGRADATION. TRACES AT 5, 9 AND
11 O'Clock. ONE EYE

Kapton Layer 2 Brake Fluid Side Start Photo #: 8601
Kapton Layer 2 Brake Fluid Side end Photo #: 8604

Kapton Layer 2 Switch Side Condition: Trace
EVIDENCE OF DEGRADATION. TRACES
AT 3 O'Clock. ONE EYE

Kapton Layer 2 Switch Side Start Photo #: 8605
Kapton Layer 2 Switch Side end Photo #: 8607

LAYER 3

Kapton Layer 3 Brake Fluid Side Condition: Trace
EVIDENCE OF DEGRADATION. TRACES AT
8 O'Clock

Kapton Layer 3 Brake Fluid Side Start Photo #: 8608
Kapton Layer 3 Brake Fluid Side end Photo #: 8610

Kapton Layer 3 Switch Side Condition: Discoloration
APPEARANCES. RESIDUE ON SURFACES.

Kapton Layer 3 Switch Side Start Photo #: 8611
Kapton Layer 3 Switch Side end Photo #: 8613

WASHER-CUP-BUTTON ASSEMBLY

Washer-Cup-Button Assembly Condition: Trace
WITH FEW. CONVERSION, DISC, AND
WASHER BOWL SURFACES DISCOLORED.

Washer-Cup-Button Photo Start Number: 8614
Washer-Cup-Button Photo End Number: 8634

Exponent

Date of Inspection: 9/27/00

Inspected by: BK

Data Form for Examination and Disassembly of Brake Switch

GENERAL INFORMATION

Long Tag Number: 0070725317
 VIN: 2MFLM75W3P M Date: 10/16/92
 Vehicle Location - City: Fort Lauderdale
 Vehicle Location - State: FLORIDA
 Vehicle Model: GRAND MARQUIS
 Vehicle Model - Year: 1993

Part Prefix Number: F2VC
 Part Base Number: 9F924
 Part Suffix Number: AB
 Date Code: 2030

Resistance: Terminal-to-Terminal: OL
 Resistance: Stationary Terminal to Hex Port: 8.90 M Ω
 Resistance: Moveable Terminal to Hex Port: 9.32 M Ω

CONNECTOR INFORMATION

Connector Present (y/n): N
 Res: Terminal-to-Terminal w/ Connector: _____
 Res: Stationary Term to Hex Port w/ Connector: _____
 Res: Moveable Term to Hex Port w/ Connector: _____
 Connector/Seal Start Photo No: _____
 Connector/Seal End Photo No: _____
 Connector Seal Notes: _____

Base Physical Condition Notes: Misc. Damage
External Surface. Reason on
Intention of Part

Overall External Beginning Photo Number: 8701
 Overall External Ending Photo Number: 8714

Connector Engagement Notes: _____

Exponent

INFORMATION AFTER REMOVAL OF ALUMINUM CRIMP RING

Loose Liquid or material Collected from Inside the Base:

Aluminum Crimp Ring Condition Notes: CRIMP RING

Interior of Base Condition Notes: RESIDUE ON BASE
FROM TERMINAL CONTACTS.

INFO AFTER OPENING CUP

Interior Hexport Condition Notes

Cup-Washer-Kapton Condition Notes: GRASSY PORTAGE
TO KAPTON LAYERS. DURING DISASSEMBLY
WHITE MARKS ON GRASSY AND KAPTON
LAYER 1.

KAPTON LAYERS

LAYER 1

Kapton Layer 1 Brake Fluid Side Condition: RESIDUE EVIDENCE
OF DECONTAMINATION. WHITE MARKS ON SURFACE.
EVIDENCE ON SURFACE. CIRCUMFERENTIAL WHITE MARKS
AT 6 AND 12 O'clock. ONE EVIDENCE

Kapton Layer 1 Brake Fluid Side Start Photo #: 8730
Kapton Layer 1 Brake Fluid Side end Photo #: 8731

Hexport-Cup Condition Notes: CUP SEPARATE
DISASSEMBLED. RESIDUE ON PORTION.

AI Crimp-Base-Hex Port Start Photo No: 8715
AI Crimp-Base-Hex Port End Photo No: 8721

Interior Hexport Photo Start No: 8722
Interior Hexport Photo End No: 8723

Cup-Washer-Kapton Photo Start No: 8724
Cup-Washer-Kapton Photo End No: 8729

Kapton Layer 1 Switch Side Condition: RESIDUE EVIDENCE
OF DECONTAMINATION. EVIDENCE AT 12 O'clock
ONE EVIDENCE

Kapton Layer 1 Switch Side Start Photo #: 8732
Kapton Layer 1 Switch Side end Photo #: 8735

Exponent

LAYER 2

Kapton Layer 1 Brake Fluid Side Condition: Dark
EVIDENCE OF DECONTAMINATION, CARBONIZATION
BLACK LINE AT 10 O'clock ONE END

Kapton Layer 2 Brake Fluid Side Start Photo #: 8801

Kapton Layer 2 Brake Fluid Side end Photo #: 8804

Kapton Layer 2 Switch Side Condition: Dark Evidence
of DECONTAMINATION TEAR AT 1 AND
2 O'clock ONE END

Kapton Layer 2 Switch Side Start Photo #: 8805

Kapton Layer 2 Switch Side end Photo #: 8807

LAYER 3

Kapton Layer 3 Brake Fluid Side Condition: Dark Evidence
of DECONTAMINATION TEAR AT 12 O'clock
ONE END

Kapton Layer 3 Brake Fluid Side Start Photo #: 8808

Kapton Layer 3 Brake Fluid Side end Photo #: 8810

Kapton Layer 3 Switch Side Condition: Darkened
Appearance, RESIDUE ON SURFACE
ONE END

Kapton Layer 3 Switch Side Start Photo #: 8811

Kapton Layer 3 Switch Side end Photo #: 8813

WASHER-CUP-BUTTON ASSEMBLY

Washer-Cup-Button Assembly Condition: Dark
MOIST WITH FINE DECONTAMINATION
REVER OF WRITER

Washer-Cup-Button Photo Start Number: 8814

Washer-Cup-Button Photo End Number: 8834

Exponent

Date of Inspection: 9/27

Inspected by: BK

Data Form for Examination and Disassembly of Brake Switch

GENERAL INFORMATION

Long Tag Number: 2071228706

VIN: 2FACP13WIN Build Date: 08/01/92

Vehicle Location - City: HIWASSEE

Vehicle Location - State: FLORIDA

Vehicle Model: CROWN VICTORIA

Vehicle Model - Year: 1992

Part Prefix Number: F2AC

Part Base Number: 9F924

Part Suffix Number: AA

Date Code: 2127

Resistance: Terminal-to-Terminal: 4.40 MΩ

Resistance: Stationary Terminal to Hex Port: OPEN

Resistance: Moveable Terminal to Hex Port: OPEN

CONNECTOR INFORMATION

Connector Present (y/n): No

Res: Terminal-to-Terminal w/ Connector: _____

Res: Stationary Term to Hex Port w/ Connector: _____

Res: Moveable Term to Hex Port w/ Connector: _____

Connector/Seal Start Photo No: _____

Connector/Seal End Photo No: _____

Connector Seal Notes: _____

Base Physical Condition Notes: DISASSEMBLED EXHAUST SURFACE. BASE TERMINAL CLEAN AND DRY.

Overall External Beginning Photo Number: 8901

Overall External Ending Photo Number: 8914

Connector Engagement Notes: _____

Exponent

INFORMATION AFTER REMOVAL OF ALUMINUM CRIMP RING

Loose Liquid or material Collected from Inside the Base:

Aluminum Crimp Ring Condition Notes: Clean & Dry.

Interior of Base Condition Notes: Clean & Dry

Environment Seal: Attached To Base
On Disassembly. Transfer Pd Of Sealing
Area Any Debris From Into Base Prior
To Photo.

INFO AFTER OPENING CUP

Interior Hexport Condition Notes Moist Areas on Gaskets

Cup-Washer-Kapton Condition Notes: ---

KAPTON LAYERS

LAYER 1

Kapton Layer 1 Brake Fluid Side Condition: Moist Surface
of Kaptonized. Two Concentric Rings
From 2 to 5 O'clock. Concentric
Rings From 9 to 12 O'clock. Ring
Regions on Surface.

Kapton Layer 1 Brake Fluid Side Start Photo #: 8930

Kapton Layer 1 Brake Fluid Side end Photo #: 8932

Hexport-Cup Condition Notes: Clean & Dry

Al Crimp-Base-Hex Port Start Photo No: 8915

Al Crimp-Base-Hex Port End Photo No: 8921

Interior Hexport Photo Start No: 8922

Interior Hexport Photo End No: 8925

Cup-Washer-Kapton Photo Start No: 8926

Cup-Washer-Kapton Photo End No: 8929

Kapton Layer 1 Switch Side Condition: ---

Kapton Layer 1 Switch Side Start Photo #: 8933

Kapton Layer 1 Switch Side end Photo #: 8935

Exponent

LAYER 2

Kapton Layer 1 Brake Fluid Side Condition: _____

Kapton Layer 2 Brake Fluid Side Start Photo #: 9001

Kapton Layer 2 Brake Fluid Side end Photo #: 9004

Kapton Layer 2 Switch Side Condition: _____

Kapton Layer 2 Switch Side Start Photo #: 9005

Kapton Layer 2 Switch Side end Photo #: 9007

LAYER 3

Kapton Layer 3 Brake Fluid Side Condition: _____

Kapton Layer 3 Brake Fluid Side Start Photo #: 9008

Kapton Layer 3 Brake Fluid Side end Photo #: 9010

Kapton Layer 3 Switch Side Condition: Residual and

See Photos

Kapton Layer 3 Switch Side Start Photo #: 9011

Kapton Layer 3 Switch Side end Photo #: 9013

WASHER-CUP-BUTTON ASSEMBLY

Washer-Cup-Button Assembly Condition: As is, Perme

As is, Perme

Washer-Cup-Button Photo Start Number: 9014

Washer-Cup-Button Photo End Number: 9034

Request

Date of Inspection: 9/27/00

Inspected by: BK

Data Form for Examination and Disassembly of Brake Switch

GENERAL INFORMATION

Long Tag Number: 0071566478

VIN: 2MEFM75W2AM Date: 06/26/92

Vehicle Location - City: Kenner

Vehicle Location - State: LOUISIANA

Vehicle Model: TRUCK MARQUIS

Vehicle Model - Year: 1992

Part Prefix Number: F2VC

Part Base Number: 9F924

Part Suffix Number: AB

Data Code: 2114

Resistance: Terminal-to-Terminal: .1 Ω

Resistance: Stationary Terminal to Hex Port: 6.30 M Ω

Resistance: Moveable Terminal to Hex Port: 6.48 M Ω

CONNECTOR INFORMATION

Connector Present (y/n): No

Res: Terminal-to-Terminal w/ Connector: _____

Res: Stationary Term to Hex Port w/ Connector: _____

Res: Moveable Term to Hex Port w/ Connector: _____

Connector/Seal Start Photo No: _____

Connector/Seal End Photo No: _____

Connector Seal Notes: _____

Base Physical Condition Notes: DIRTY ON EXTERNAL SURFACE. TERMINAL OF BASE MOUNT WITH FLUX.

Overall External Beginning Photo Number: 9101

Overall External Ending Photo Number: 9114

Connector Engagement Notes: _____

Exponent

INFORMATION AFTER REMOVAL OF ALUMINUM CRIMP RING

Loose Liquid or material Collected from Inside the Base:

Aluminum Crimp Ring Condition Notes: CLEAN AND DRY

Interior of Base Condition Notes: INTERNAL MARKS, RESIDUE ON PORTION OF SPRING ARM & TERMINALS CONTACTS

INFO AFTER OPENING CUP

Interior Hexport Condition Notes: WHITE MARKS ON FACE

Cup-Washer-Kapton Condition Notes: WHITE MARKS ON SURFACES OF KAPTON LAYERS

KAPTON LAYERS

LAYER 1

Kapton Layer 1 Brake Fluid Side Condition: WHITE MARKS ON SURFACES, POSITIVE EVIDENCE OF DELAMINATION TERN AT 9 O'clock.

Kapton Layer 1 Brake Fluid Side Start Photo #: 9120
Kapton Layer 1 Brake Fluid Side end Photo #: 9122

Hexport-Cup Condition Notes: PORTION OF SURFACE DISCOLORED AND RESIDUE PRESENT.

Al Crimp-Base-Hex Port Start Photo No: 9115
Al Crimp-Base-Hex Port End Photo No: 9121

Interior Hexport Photo Start No: 9122
Interior Hexport Photo End No: 9123

Cup-Washer-Kapton Photo Start No: 9124
Cup-Washer-Kapton Photo End No: 9127

Kapton Layer 1 Switch Side Condition: POSITIVE EVIDENCE OF DELAMINATION, TERN AT 4 O'clock. POSITIVE BRACE LINE AT 2 O'clock, ONE ETC.

Kapton Layer 1 Switch Side Start Photo #: 9123
Kapton Layer 1 Switch Side end Photo #: 9125

Equipment

LAYER 2

Kapton Layer 1 Brake Fluid Side Condition: Small EVIDENCE
of DECONTAMINATION. TEST AT 9 O'clock

Kapton Layer 2 Switch Side Condition: TEST AT
3 O'clock. ONE EVIDENCE

Kapton Layer 2 Brake Fluid Side Start Photo #: 9204

Kapton Layer 2 Brake Fluid Side end Photo #: 9207

Kapton Layer 2 Switch Side Start Photo #: 9205

Kapton Layer 2 Switch Side end Photo #: 9207

LAYER 3

Kapton Layer 3 Brake Fluid Side Condition: ---

Kapton Layer 3 Switch Side Condition: DATA
APPEARANCE. RESIDUE ON SURFACE

Kapton Layer 3 Brake Fluid Side Start Photo #: 9208

Kapton Layer 3 Brake Fluid Side end Photo #: 9210

Kapton Layer 3 Switch Side Start Photo #: 9211

Kapton Layer 3 Switch Side end Photo #: 9213

WASHER-CUP-BUTTON ASSEMBLY

Washer-Cup-Button Assembly Condition: Part M17
WITH FLUID. REVER OF WASHER PARTIALLY
DISCOLORED. SURFACE OF CONTACT DISCOLORED

Washer-Cup-Button Photo Start Number: 9214

Washer-Cup-Button Photo End Number: 9233

Inspector:

Date of Inspection: 9/28/00

Inspected by: BK

Data Form for Examination and Disassembly of Brake Switch

GENERAL INFORMATION

Long Tag Number: 0069624471

VIN ZFALP74W3PK Build Date: 11/12/92

Vehicle Location - City: BEVERLY

Vehicle Location - State: MASSACHUSETTS

Vehicle Model: CROWN VICTORIA

Vehicle Model - Year: 1993

Part Prefix Number: F2VC

Part Base Number: 9F924

Part Suffix Number: AB

Date Code: 2030

Resistance: Terminal-to-Terminal: 1.455 kΩ

Resistance: Stationary Terminal to Hex Port: 2.619 MΩ

Resistance: Moveable Terminal to Hex Port: 8.7 Ω

CONNECTOR INFORMATION

Connector Present (y/n): Y

Res: Terminal-to-Terminal w/ Connector: _____

Res: Stationary Term to Hex Port w/ Connector: _____

Res: Moveable Term to Hex Port w/ Connector: _____

Connector/Seal Start Photo No: 9315

Connector/Seal End Photo No: 9316

Connector Seal Notes: _____

Base Physical Condition Notes: Disassembled

EXTERNAL SURFACE PAINT ON

HEX-PORT, INTERNAL OF BASE HAS

MUST. DISASSEMBLE SURFACE AND

TERMINAL CONTACTS

Overall External Beginning Photo Number: 9301

Overall External Ending Photo Number: 9314

Connector Engagement Notes: NO EXTERNAL

COMPONENTS RETAINED WITH CONNECTOR.

NO RESISTANCE MEASUREMENTS TAKEN.

Experiment

INFORMATION AFTER REMOVAL OF ALUMINUM CRIMP RING

Loose Liquid or material Collected from Inside the Base:

Liquid Collected from Base

Aluminum Crimp Ring Condition Notes: Markings

Scraped from Crimp Ring, Corrosion Present.

Interior of Base Condition Notes: Liquid In Base.

Spilling from Deposits at Flow.

Remnants in Base. Intense Surface and Thermal Corrosion Observed in Residue.

Hexport-Cup Condition Notes: Surface Mark

with Fine Discoloration Residue on Surface.

Al Crimp-Base-Hex Port Start Photo No: 9317

Al Crimp-Base-Hex Port End Photo No: 9324

INFO AFTER OPENING CUP

Interior Hexport Condition Notes: White Marks in

Cap.

Interior Hexport Photo Start No: 9325

Interior Hexport Photo End No: 9328

Cup-Washer-Kapton Condition Notes: White Marks

in Kapton Layer 1.

Cup-Washer-Kapton Photo Start No: 9329

Cup-Washer-Kapton Photo End No: 9332

KAPTON LAYERS

LAYER 1

Kapton Layer 1 Brake Fluid Side Condition: White Marks

on Surfaces. BRACE EVIDENCE OF DEFORMATION.

TEARS FROM 3 TO 5 O'CLOCK. TWO TEARS IN

CENTER. RADIAL BURST MARK AT 2 O'CLOCK.

4 O'CLOCK CIRCUMFERENTIAL BURST MARK

FROM 12 TO 5 O'CLOCK. RESIDUE ON SURFACE. TWO ENDS

Kapton Layer 1 Brake Fluid Side Start Photo #: 9333

Kapton Layer 1 Brake Fluid Side end Photo #: 9335

Kapton Layer 1 Switch Side Condition: BRACE EVIDENCE

OF DEFORMATION. TEARS AT 5, 8 AND

11 O'CLOCK. RESIDUE ON SURFACE. TWO ENDS

Kapton Layer 1 Switch Side Start Photo #: 9401

Kapton Layer 1 Switch Side end Photo #: 9405

Expend

LAYER 2

Kapton Layer 1 Brake Fluid Side Condition: BASE ENGINE
OF DETERMINATION. THREE TEARS BEYOND 1 AND
0'clock. Two TEARS IN CENTER TEAR AT
7 P.M. 0'clock. RESIDUE ON SURFACES. RESIDUE
BASE CALORIMETRIC DATA LINES AT 9 0'clock.

^{TWO ENDS}
Kapton Layer 2 Brake Fluid Side Start Photo #: 9406

Kapton Layer 2 Brake Fluid Side end Photo #: 9408

Kapton Layer 2 Switch Side Condition: BASE ENGINE
OF DETERMINATION. TEAR AT 12:00 0'clock
TWO ENDS.

Kapton Layer 2 Switch Side Start Photo #: 9409

Kapton Layer 2 Switch Side end Photo #: 9411

LAYER 3

Kapton Layer 3 Brake Fluid Side Condition: MARKING
APPROXIMATE. BASES SURFACE OF
DETERMINATION. TEAR AT 6 0'clock
ONE END.

Kapton Layer 3 Brake Fluid Side Start Photo #: 9412

Kapton Layer 3 Brake Fluid Side end Photo #: 9414

Kapton Layer 3 Switch Side Condition: MARK
RESIDUE ON SURFACES.

Kapton Layer 3 Switch Side Start Photo #: 9415

Kapton Layer 3 Switch Side end Photo #: 9417

WASHER-CUP-BUTTON ASSEMBLY

Washer-Cup-Button Assembly Condition: PARTS FREE
CORROSION. COMPLETE, DISC BEYOND AREA
OF WASHING AND REVERSE SIDE DISMANTLED.

Washer-Cup-Button Photo Start Number: 9418

Washer-Cup-Button Photo End Number: 9436

Exponent

Date of Inspection: 9/29/00

Inspected by: PK

Data Form for Examination and Disassembly of Brake Switch

GENERAL INFORMATION

Long Tag Number: 0071001852

VIN: 2MELM75W9P Build Date: 08/11/92

Vehicle Location - City: SALINA

Vehicle Location - State: KS

Vehicle Model: Home Motors

Vehicle Model - Year: 1993

Part Prefix Number: F2VC

Part Base Number: 9F924

Part Suffix Number: A0

Date Code: 2014

Resistance: Terminal-to-Terminal: 5.8 Ω

Resistance: Stationary Terminal to Hex Port: OPEN

Resistance: Moveable Terminal to Hex Port: OPEN

CONNECTOR INFORMATION

Connector Present (y/n): No

Res: Terminal-to-Terminal w/ Connector: _____

Res: Stationary Term to Hex Port w/ Connector: _____

Res: Moveable Term to Hex Port w/ Connector: _____

Connector/Seal Start Photo No: _____

Connector/Seal End Photo No: _____

Connector Seal Notes: _____

Base Physical Condition Notes: Damage on EXTERIOR

SURFACE. DIRTY AND RUSTY

ON INTERIOR SURFACE OF BASE

AND CONNECTOR.

Overall External Beginning Photo Number: 9501

Overall External Ending Photo Number: 9519

Connector Engagement Notes: _____

Experiment

INFORMATION AFTER REMOVAL OF ALUMINUM CRIMP RING

Loose Liquid or material Collected from Inside the Base:

None.

Aluminum Crimp Ring Condition Notes: Clean & Dry.

Interior of Base Condition Notes: DIAM IN BASE,

TRAMING CORRUDED. SPINA ARM

DAMAGED NEAR FLOW.

INFO AFTER OPENING CUP

Interior Hexport Condition Notes

Hexport-Cup Condition Notes: SURFACE CORRODED

AND DISCOLORING.

AI Crimp-Base-Hex Port Start Photo No: 9515

AI Crimp-Base-Hex Port End Photo No: 9522

Interior Hexport Photo Start No: 9523

Interior Hexport Photo End No: 9524

Cup-Washer-Kapton Condition Notes: GRINDY ADHESION

TO KAPTON LAYER DURING DISASSEMBLY.

WHITE MARKS ON GASKET

Cup-Washer-Kapton Photo Start No: 9525

Cup-Washer-Kapton Photo End No: 9530

KAPTON LAYERS

LAYER 1

Kapton Layer 1 Brake Fluid Side Condition: ROUGH EVIDENCE

OF DEGRADATION. MULTIPLE TEARS

AROUND CIRCUMFERENCE. WHITE MARKS

ON SURFACE. BEING REVISION ON

SURFACE.

Kapton Layer 1 Switch Side Condition: _____

Kapton Layer 1 Brake Fluid Side Start Photo #: 9531

Kapton Layer 1 Brake Fluid Side end Photo #: 9533

Kapton Layer 1 Switch Side Start Photo #: 9534

Kapton Layer 1 Switch Side end Photo #: 9536

Inspection

LAYER 2

Kapton Layer 1 Brake Fluid Side Condition: _____

Kapton Layer 2 Switch Side Condition: _____

Kapton Layer 2 Brake Fluid Side Start Photo #: 9601

Kapton Layer 2 Switch Side Start Photo #: 9605

Kapton Layer 2 Brake Fluid Side end Photo #: 9604

Kapton Layer 2 Switch Side end Photo #: 9607

LAYER 3

Kapton Layer 3 Brake Fluid Side Condition: _____

Kapton Layer 3 Switch Side Condition: RESIN ON SURFACE

Kapton Layer 3 Brake Fluid Side Start Photo #: 9608

Kapton Layer 3 Switch Side Start Photo #: 9611

Kapton Layer 3 Brake Fluid Side end Photo #: 9610

Kapton Layer 3 Switch Side end Photo #: 9612

WASHER-CUP-BUTTON ASSEMBLY

Washer-Cup-Button Assembly Condition: Parts Dry.

WHITE RESIN ON PARTS PRESENT
ON METALLIC PARTS.

Washer-Cup-Button Photo Start Number: 9614

Washer-Cup-Button Photo End Number: 9634

Examiner

Date of Inspection: 9/29/00

Inspected by: BK

Data Form for Examination and Disassembly of Brake Switch

GENERAL INFORMATION

Long Tag Number: 0069094524

VIN: 1LNMB82W5N4 Build Date: 03/06/92

Vehicle Location - City: INDIANAPOLIS

Vehicle Location - State: OH

Vehicle Model: Town Car

Vehicle Model - Year: 1992

Part Prefix Number: F2AC

Part Base Number: 9F924

Part Suffix Number: AA

Date Code: 3280

Resistance: Terminal-to-Terminal: 2.25Ω

Resistance: Stationary Terminal to Hex Port: 28.52 MΩ

Resistance: Moveable Terminal to Hex Port: 29.11 MΩ

CONNECTOR INFORMATION

Connector Present (y/n): Y

Res: Terminal-to-Terminal w/ Connector: _____

Res: Stationary Term to Hex Port w/ Connector: _____

Res: Moveable Term to Hex Port w/ Connector: _____

Connector/Seal Start Photo No: 97.23

Connector/Seal End Photo No: 97.24

Connector Seal Notes: _____

Base Physical Condition Notes: Damage on

EXTENSION SURFACE. Damage on

INTERNAL SURFACE OF BASE.

Hex Port Ruptured.

Overall External Beginning Photo Number: 9701

Overall External Ending Photo Number: 9714

Connector Engagement Notes: ELECTRICAL COMPONENT

NOT REMOVED. NO RESISTANCE

MEASUREMENTS TAKEN.

Exponent

INFORMATION AFTER REMOVAL OF ALUMINUM CRIMP RING

Loose Liquid or material Collected from Inside the Base:

NONE

Aluminum Crimp Ring Condition Notes:

LOOSE MATERIAL
COLLECTED FROM CRIMP RING. SOME
CORROSION ON CRIMP RING.

Interior of Base Condition Notes:

RESIDUE IN BASE
AND ON TERMINAL CONTACTS.

INFO AFTER OPENING CUP

Interior Hexport Condition Notes:

WATER MARKS ON
SCREWS.

Cup-Washer-Kapton Condition Notes:

KAPTON LAYERS
PARTIALLY RAISED DURING DISASSEMBLY

KAPTON LAYERS

LAYER 1

Kapton Layer 1 Brake Fluid Side Condition:

SMALL
EVIDENCE OF DISCONTINUOUS MULTIPLE
TEARS IN CENTER AND AROUND
CIRCUMFERENCES. DARK SPOTS AND
PORTIONS OF SURFACE.

Kapton Layer 1 Brake Fluid Side Start Photo #: 9733

Kapton Layer 1 Brake Fluid Side end Photo #: 9735

Hexport-Cup Condition Notes:

RESIDUE AND
DISCONTINUOUS ON PORTION OF CUP
SURFACE. CORROSION ON CUP
EDGE.

AI Crimp-Base-Hex Port Start Photo No: 9715

AI Crimp-Base-Hex Port End Photo No: 9722

Interior Hexport Photo Start No: 9725

Interior Hexport Photo End No: 9728

Cup-Washer-Kapton Photo Start No: 9729

Cup-Washer-Kapton Photo End No: 9732

Kapton Layer 1 Switch Side Condition: _____

Kapton Layer 1 Switch Side Start Photo #: 9801

Kapton Layer 1 Switch Side end Photo #: 9804

3713 9523

Exposure

LAYER 2

Kapton Layer 1 Brake Fluid Side Condition: _____

Kapton Layer 2 Switch Side Condition: _____

Kapton Layer 2 Brake Fluid Side Start Photo #: 9805

Kapton Layer 2 Switch Side Start Photo #: 9808

Kapton Layer 2 Brake Fluid Side end Photo #: 9807

Kapton Layer 2 Switch Side end Photo #: 9810

LAYER 3

Kapton Layer 3 Brake Fluid Side Condition: _____

Kapton Layer 3 Switch Side Condition: _____

Kapton Layer 3 Brake Fluid Side Start Photo #: 9811

Kapton Layer 3 Switch Side Start Photo #: 9814

Kapton Layer 3 Brake Fluid Side end Photo #: 9813

Kapton Layer 3 Switch Side end Photo #: 9816

WASHER-CUP-BUTTON ASSEMBLY

Washer-Cup-Button Assembly Condition: Clear

And Dry.

Washer-Cup-Button Photo Start Number: 9817

Washer-Cup-Button Photo End Number: 9836

Report

Date of Inspection: 10/2/00

Inspected by: BK

Data Form for Examination and Disassembly of Brake Switch

GENERAL INFORMATION

Long Tag Number: 0071057870

VIN: 2ME1M75W3N Build Date: 00/11/92

Vehicle Location - City: HARVILLE

Vehicle Location - State: OH

Vehicle Model: Ford MAZDA

Vehicle Model - Year: 1992

Part Prefix Number: F2VC

Part Base Number: 9F924

Part Suffix Number: AB

Date Code: 1364

Base Physical Condition Notes: Degraded and Exposed

SUSPECT TAP FROM OF BRKE ARM

CONDUCTORS MOVE WITH FLUID ARM

RESISTANCE - COVERED

Overall External Beginning Photo Number: 9901

Overall External Ending Photo Number: 9914

Resistance: Terminal-to-Terminal: 340.9 k Ω

Resistance: Stationary Terminal to Hex Port: 3.82 M Ω

Resistance: Movable Terminal to Hex Port: 1.91 M Ω

CONNECTOR INFORMATION

Connector Present (y/n): No

Res: Terminal-to-Terminal w/ Connector: _____

Res: Stationary Term to Hex Port w/ Connector: _____

Res: Movable Term to Hex Port w/ Connector: _____

Connector/Seal Start Photo No: _____

Connector/Seal End Photo No: _____

Connector Seal Notes: _____

Connector Engagement Notes: _____

Hexport

INFORMATION AFTER REMOVAL OF ALUMINUM CRIMP RING

Loose Liquid or material Collected from Inside the Base:

None

Aluminum Crimp Ring Condition Notes: Liquor Collected from Crimp Ring.

Interior of Base Condition Notes: Tarnish Surface. Moist. Spans Area Between In Middle of Arm. Residue in Base. Contains Residue.

INFO AFTER OPENING CUP

Interior Hexport Condition Notes: White Marks on Gasket.

Cup-Washer-Kapton Condition Notes: White Marks on Kapton Layer 1.

KAPTON LAYERS

LAYER 1

Kapton Layer 1 Brake Fluid Side Condition: White Marks on Surface. Residue and Surface. Rubber Evidence of Delamination. Taken from 7 to 7 O'clock. One End.

Kapton Layer 1 Brake Fluid Side Start Photo #: 9911
Kapton Layer 1 Brake Fluid Side end Photo #: 9933

Hexport-Cup Condition Notes: Surface of Cup Moist. Discolored Area Around Cavities.

Al Crimp-Base-Hex Port Start Photo No: 9915
Al Crimp-Base-Hex Port End Photo No: 9923

Interior Hexport Photo Start No: 9923
Interior Hexport Photo End No: 9926

Cup-Washer-Kapton Photo Start No: 9927
Cup-Washer-Kapton Photo End No: 9930

Kapton Layer 1 Switch Side Condition: Bugle Surface of Delamination. Taken At 1 Am. 8 O'clock Area from 10 to 11 o'clock One End.

Kapton Layer 1 Switch Side Start Photo #: 9934
Kapton Layer 1 Switch Side end Photo #: 9936

Expend

LAYER 2

Kapton Layer 1 Brake Fluid Side Condition: RUSSLE
EVAPORATED DECONTAMINATION. TENS FAN
1 to 2 O'clock AND NEAR CENTER.
ONE FAN

Kapton Layer 2 Brake Fluid Side Start Photo #: 10001
Kapton Layer 2 Brake Fluid Side end Photo #: 10014

Kapton Layer 2 Switch Side Condition: RUSSLE EVAPORATED
DECONTAMINATION. TENS AT 1 AND
8 O'clock AND FAN 10 TO 11
O'clock. ONE FAN

Kapton Layer 2 Switch Side Start Photo #: 10005
Kapton Layer 2 Switch Side end Photo #: 10007

LAYER 3

Kapton Layer 3 Brake Fluid Side Condition: RUSSLE
EVAPORATED DECONTAMINATION. TENS FAN
11 TO 1 O'clock. ONE FAN.

Kapton Layer 3 Brake Fluid Side Start Photo #: 10008
Kapton Layer 3 Brake Fluid Side end Photo #: 10010

Kapton Layer 3 Switch Side Condition: RESIDUAL
SUBSTANCE.

Kapton Layer 3 Switch Side Start Photo #: 10011
Kapton Layer 3 Switch Side end Photo #: 10013

WASHER-CUP-BUTTON ASSEMBLY

Washer-Cup-Button Assembly Condition: WHITE
MOIST WITH FLUID. WHITE BEVEL AREA
AND RESIDUAL SIG. CONTACT AND
DISC DISCOLORED.

Washer-Cup-Button Photo Start Number: 10014
Washer-Cup-Button Photo End Number: 10034

Exponent

Date of Inspection: 10/22/02

Inspected by: BK

Data Form for Examination and Disassembly of Brake Switch

GENERAL INFORMATION

Long Tag Number: 0071139606

VIN: 2FACP74W8P2 Build Date: 09/08/92

Vehicle Location - City: St CHARLES

Vehicle Location - State: MO

Vehicle Model: Crown Victoria

Vehicle Model - Year: 1993

Part Prefix Number: F2VC

Part Base Number: 9F924

Part Suffix Number: AB

Date Code: 1347

Resistance: Terminal-to-Terminal: 1.5 Ω

Resistance: Stationary Terminal to Hex Port: 10.65 M Ω

Resistance: Movable Terminal to Hex Port: 13.07 M Ω

CONNECTOR INFORMATION

Connector Present (y/n): No

Res: Terminal-to-Terminal w/ Connector: _____

Res: Stationary Term to Hex Port w/ Connector: _____

Res: Movable Term to Hex Port w/ Connector: _____

Connector/Seal Start Photo No: _____

Connector/Seal End Photo No: _____

Connector Seal Notes: _____

Base Physical Condition Notes: Damage on EXTERIOR SURFACE. Damage on INTERIOR OF BASE AND CONTACTS.

Overall External Beginning Photo Number: 10101

Overall External Ending Photo Number: 1114

Connector Engagement Notes: _____

Experiment

INFORMATION AFTER REMOVAL OF ALUMINUM CRIMP RING

Loose Liquid or material Collected from Inside the Base:

None.

Aluminum Crimp Ring Condition Notes: Clean & Dry.

Interior of Base Condition Notes: Clean & Moist.

Hexport-Cup Condition Notes: Clean & Moist.

Al Crimp-Base-Hex Port Start Photo No: 10115

Al Crimp-Base-Hex Port End Photo No: 10122

INFO AFTER OPENING CUP

Interior Hexport Condition Notes

Interior Hexport Photo Start No: 10123

Interior Hexport Photo End No: 10124

Cup-Washer-Kapton Condition Notes: WHITE MARKS

ON SURFACES OF KAPTON LAYER 1. MARKS

PROCESSED TO KAPTON LAYER DISASSEMBLY

DISASSEMBLY

Cup-Washer-Kapton Photos Start No: 10125

Cup-Washer-Kapton Photo End No: 10130

KAPTON LAYERS

LAYER 1

Kapton Layer 1 Brake Fluid Side Condition: WHITE MARKS

ON SURFACES. RESIDUE ON SURFACES. TONERS

FROM 4 TO 5 AND 10 TO 11 O'CLOCK.

RESIDUE EVIDENCE OF DECONTAMINATION

Kapton Layer 1 Switch Side Condition: ---

Kapton Layer 1 Brake Fluid Side Start Photo #: 10131

Kapton Layer 1 Brake Fluid Side end Photo #: 10133

Kapton Layer 1 Switch Side Start Photo #: 10134

Kapton Layer 1 Switch Side end Photo #: 10136

Equipment

LAYER 2

Kapton Layer 1 Brake Fluid Side Condition: _____

Kapton Layer 2 Brake Fluid Side Start Photo #: 10201

Kapton Layer 2 Brake Fluid Side end Photo #: 10204

Kapton Layer 2 Switch Side Condition: _____

Kapton Layer 2 Switch Side Start Photo #: 10205

Kapton Layer 2 Switch Side end Photo #: 10207

LAYER 3

Kapton Layer 3 Brake Fluid Side Condition: _____

Kapton Layer 3 Brake Fluid Side Start Photo #: 10208

Kapton Layer 3 Brake Fluid Side end Photo #: 10210

Kapton Layer 3 Switch Side Condition: Pressure
Swapped

Kapton Layer 3 Switch Side Start Photo #: 10211

Kapton Layer 3 Switch Side end Photo #: 10213

WASHER-CUP-BUTTON ASSEMBLY

Washer-Cup-Button Assembly Condition: Pressure
Done

Washer-Cup-Button Photo Start Number: 10214

Washer-Cup-Button Photo End Number: 10234

Exponent

Date of Inspection: 10/02/07

Inspected by: BK

Data Form for Examination and Disassembly of Brake Switch

GENERAL INFORMATION

Long Tag Number: 0070081194

VIN: 1LNLM91W14N4 Mfg Date: 02/18/97

Vehicle Location - City: Alcoa

Vehicle Location - State: TN

Vehicle Model: Truck Cab

Vehicle Model - Year: 1992

Part Prefix Number: 2FV

Part Base Number: 9F924

Part Suffix Number: A8

Date Code: 2045

Base Physical Condition Notes: None Discovered
GREEN SURFACES BASE TERMINAL
PLATE

Overall External Beginning Photo Number: 10301
Overall External Ending Photo Number: 10314

Resistance: Terminal-to-Terminal: 1 Ω

Resistance: Stationary Terminal to Hex Port: 4.78M Ω

Resistance: Moveable Terminal to Hex Port: 4.92M Ω

CONNECTOR INFORMATION

Connector Present (y/n): No

Res: Terminal-to-Terminal w/ Connector: _____

Res: Stationary Term to Hex Port w/ Connector: _____

Res: Moveable Term to Hex Port w/ Connector: _____

Connector/Seal Start Photo No: _____

Connector/Seal End Photo No: _____

Connector Seal Notes: _____

Connector Engagement Notes: _____

Expend

INFORMATION AFTER REMOVAL OF ALUMINUM CRIMP RING

Loose Liquid or material Collected from Inside the Base:
None
Aluminum Crimp Ring Condition Notes: Comp & Dry.

Interior of Base Condition Notes: Insured
Surface Moist. Patches of Spots
from Pencil-Exposure

INFO AFTER OPENING CUP

Interior Hexport Condition Notes: White Material
(Gross)

Cup-Washer-Kapton Condition Notes: White Marks
on Kapton Layer 1.

KAPTON LAYERS

LAYER 1

Kapton Layer 1 Brake Fluid Side Condition: White Marks
on Surface. Resins on Surface. Patches
Surface of Determination. Total from
10 to 11 O'clock.

Kapton Layer 1 Brake Fluid Side Start Photo #: 10330
Kapton Layer 1 Brake Fluid Side end Photo #: 10332

Hexport-Cup Condition Notes: Portion of
Cup Surface Disclosed And
Residual-Exposure.

AI Crimp-Base-Hex Port Start Photo No: 10315
AI Crimp-Base-Hex Port End Photo No: 10321

Interior Hexport Photo Start No: 10322
Interior Hexport Photo End No: 10325

Cup-Washer-Kapton Photo Start No: 10326
Cup-Washer-Kapton Photo End No: 10329

Kapton Layer 1 Switch Side Condition: Resins Surface
of Determination. Total At 11 O'clock
Two Tests from 7 to 8 O'clock.
One Test

Kapton Layer 1 Switch Side Start Photo #: 10333
Kapton Layer 1 Switch Side end Photo #: 10335

Expend

LAYER 2

Kapton Layer 1 Brake Fluid Side Condition: Broken
EVIDENCE OF DEFORMATION. TORN AT
L.S. Area 7 O'clock.

Kapton Layer 2 Brake Fluid Side Start Photo #: 10401
Kapton Layer 2 Brake Fluid Side end Photo #: 10404

Kapton Layer 2 Switch Side Condition: Broken
EVIDENCE OF DEFORMATION. TORN
AT 10 O'clock. Out Edge.

Kapton Layer 2 Switch Side Start Photo #: 10405
Kapton Layer 2 Switch Side end Photo #: 10407

LAYER 3

Kapton Layer 3 Brake Fluid Side Condition: Broken
EVIDENCE OF DEFORMATION.

Kapton Layer 3 Brake Fluid Side Start Photo #: 10408
Kapton Layer 3 Brake Fluid Side end Photo #: 10410

Kapton Layer 3 Switch Side Condition: Broken
RESIDUE ON SURFACE.

Kapton Layer 3 Switch Side Start Photo #: 10411
Kapton Layer 3 Switch Side end Photo #: 10413

WASHER-CUP-BUTTON ASSEMBLY

Washer-Cup-Button Assembly Condition: From Mount
area found Below of Washer Area
Portion of: Converter Area Disc
Area Discard.

Washer-Cup-Button Photo Start Number: 10414
Washer-Cup-Button Photo End Number: 10434

LOGGING AND BOXING task.

Collect parts (RAC code FED S1) from Ford Warranty Return Parts Center.

Important....DO NOT SEPARATE YELLOW TAG FROM PARTS!!!
If yellow tag is missing, then add a tag with VIN, ODOM, and State from worksheet packaged with parts.

For each brake pressure switch record the following in an Excel spreadsheet file-

- (Part # *RO #*)
1. 10 digit Yellow Tag number (or enter VIN and Odom miles and State)
 2. 11 digit Part Number stamped on brake pressure switch.
 3. 4 digit Date Code stamped on brake pressure switch following after part number
 4. YES or NO, Resistance between terminals is less than 1 ohm. *-ed 3*

Box parts in the following Date Code groups:

1. less than 1200.
2. 1201 to 1228.
3. 1229 to 1257.
4. 1258 to 1285.
5. 1286 to 1313.
6. 1314 to 1341.
7. 1342 to 2000.
8. 2001 to 2028.
9. 2029 to 2057.
10. 2058 to 2085.
11. 2086 to 2113.
12. 2114 to 2141.
13. 2142 to 2169.
14. 2170 to 2197.
15. 2198 to 2225.
16. 2226 to 2253.
17. 2254 to 2281.
18. 2282 to 2309.
19. 2310 to 2337.
20. 2338 to 3000.
21. 3001 to 4000.
22. 4001 to 9000.
23. 9001 to 9365.
24. unreadable.

SAMPLE SELECTION task

Select a sample group of 432 parts with the following criteria from the above boxed parts:

1. All samples must have part number F2VC-9F924- AB-or-BB.
2. Vehicle line, odometer mileage, date code, region, and vehicle build date as shown below.

Town Car

High Mileage VINs (> 100K)

parts date coded < 2000

6 Southern Coastal states build date < Feb 1 1992

6 Other states build date < Feb 1 1992

parts date coded 2001 thru 2184 (Jan 1 1992 - June 30 1992)

Southern Coastal states

2 build date < Feb 1 1992

2 Feb 1 1992 < build date < Nov 30 1992

2 build date > Nov 30 1992

Other states

2 build date < Feb 1 1992

2 Feb 1 1992 < build date < Nov 30 1992

2 build date > Nov 30 1992

parts date coded 2185 thru 2304 (July 1 1992 - Oct 31 1992)

Southern Coastal states

3 Feb 1 1992 < build date < Nov 30 1992

3 build date > Nov 30 1992

Other states

3 Feb 1 1992 < build date < Nov 30 1992

3 build date > Nov 30 1992

parts date coded 2305 thru xxxxx (Nov 1 1992 - xxxxx)

Southern Coastal states

3 Feb 1 1992 < build date < Nov 30 1992

3 build date > Nov 30 1992

Other states

3 Feb 1 1992 < build date < Nov 30 1992

3 build date > Nov 30 1992

Median Mileage (40K to 100K)

48 same criteria as High Mileage

Low Mileage (< 40K)

48 same criteria as High Mileage

Crown Victoria

144 same criteria as Town Car above



Grand Marquis

144 same criteria as Town Car above

total = 432 parts

3713 9566

ANALYSIS task

For 432 brake pressure switches record the following in an excel spreadsheet file.

External

1. 10 digit Yellow Tag number (if none, then enter VIN)
 2. YES or NO, Condition of plastic base shows heat damage or melting.
 3. YES or NO, Condition of electrical connector shows leakage.
 4. YES or NO or missing, Mating connector shows signs of fluid leakage.
 5. Foam or Silicone or missing, Mating connector seal.
 6. YES or NO or missing, Mating seal shows compression mark.
 7. YES or NO, Kapton shows delamination bubbles.
 8. YES or NO, Kapton shows non-symmetric deformation. *See Scope*
 9. Brake pressure switch height inches +/- 0.01
 10. Crimp ring o.d. inches +/- 0.01 *how many pieces*
 11. Crimp ring height inches +/- 0.01
 12. Actuation pressure psi +/- 2
 13. Reset pressure psi +/- 2 *DAQ*
 14. Leakage rate pass/fail psi / minute (<62 psi / 30 seconds at 3000 psi) *DAQ*
 15. Resistance between terminals ohms +/-0.1 ohm, @ 0 psi
 16. Resistance between terminals ohms +/-0.1 ohm, @ 200 psi.
 17. YES or NO, Resistance from terminals to hex-port less than 10,000 ohm @ 0 psi *DAQ*
 18. YES or NO, Resistance from terminals to hex-port less than 10,000 ohm @ 200 psi
- Fluoroscopic examination (photograph items logged "Yes")
18. Yes or No, loose metal parts are present in base assembly
 19. Yes or No, Spring arm is touching sensor cup
 20. Yes or No, Spring arm shows cracks or material loss
 21. Yes or No, Moveable terminal shows cracks or material loss
 22. Yes or No, Stationary terminal shows cracks or material loss *Pics*

ANALYSIS task (continued)

Internal

Carefully separate the base from the sensor by removing crimp ring, preserving the part number and date code. Bag each loose part individually and keep with Yellow Tag.

23. Connector Leak? No Yes
24. Component wear? None Light Medium Heavy
25. Brake Fluid leak? No Yes
26. Environment seal condition? Good Bad
27. If seal bad, describe condition.
28. Sensor Cup Corrosion? Yes No (if YES, provide photo and chemical composition)
29. Sensor cup crimp o.d.
30. Sensor cup crimp height
31. Force (apply at bump) to deflect spring arm to close contacts. - DAD
32. Transfer Pin stroke from 0 to 200 psi and from 200 to 1400 psi. } LUST
33. Transfer pin height above cup (0, 200, and 1400 psi)
34. Stationary/ Moveable terminal retention Loose Firm
35. Stationary/ Moveable terminal condition OK Discolored
Corroded (if corroded, provide photo and chemical composition)

Carefully separate the hex-part from the sensor cup by opening the sensor cup crimp. Bag each loose part individually and keep with Yellow Tag.

36. Diaphragm Inspection - indicate presence of listed conditions for each side of each layer of Kapton.

Condition	Nearest Fluid		Middle		Nearest Converter	
	Fluid #1	Converter	Fluid #2	Converter	Fluid #3	Converter
Teflon stretch	Teflon	Kapton	Teflon	Kapton	Teflon	Kapton
Teflon cracks	Teflon	Kapton	Teflon	Kapton	Teflon	Kapton
Teflon delamination	Teflon	Kapton	Teflon	Kapton	Teflon	Kapton
Kapton cracks	Teflon	Kapton	Teflon	Kapton	Teflon	Kapton
Strain pattern	Teflon	Kapton	Teflon	Kapton	Teflon	Kapton
Wear particals/discoloration	Teflon	Kapton	Teflon	Kapton	Teflon	Kapton

37. Gasket Inspection

	Present	Yes	No
Nibbles/missing material		Yes	No

Comparative Analysis task

Quantify differences between three groups: 1. 10 Parts from peak of claims reports population; 2. 10 Parts from end of recall population; 3. 10 New/ unused current production parts.



Forces applied (insitu) to
stationary terminal at contact
moving terminal at spring arm bump (0, 200, and 1400 psi)
ceramic pin at snap disk
snap disk at converter
converter at Kapton
terminal retaining forces

Dimensional Analysis

assembly height (0, 200, and 1400 psi)
spring arm to cup clearance (0, 200, and 1400 psi)
crimp ring o.d and height (0, 200, and 1400 psi)
stationary contact to cup clearance (0, 200, and 1400 psi)
Transfer pin height above opening (0, 200, and 1400 psi)
base height
base crimp flange o.d., thickness
enviro seal flange o.d., thickness
sensor cup crimp o.d. and height (0, 200, and 1400 psi)
converter button profile
converter button outside diameter
converter button clearance from top of washer (0, 200, 1400 psi)
washer hole profile
washer hole inside diameter (bottom of taper)
washer hole taper outside diameter
washer thickness
washer outside diameter
hex-port gasket groove i.d., o.d., depth
hex-port i.d. at Kapton interface
hex-port o.d., thickness at crimp flange
stationary terminal minimum cross-section
moving terminal minimum cross-section
Kapton profile (0, 200, and 1400 psi)
Transfer pin length, o.d.
Sensor cup transfer pin opening i.d.


Purpose: Determine Root Cause of Town Underhood Fire Allegations

Work plan	Target completion
Receive parts, prelim exam, sort and store.	9/30/99
Draft analysis scope of work .	9/15/99
Distribute draft for adds/deletes.	9/15/99
Review and update draft.	9/17/99
Meet with Central Lab to discuss sow	9/20/99
Finalize analysis scope of work	9/21/99
Select samples for analysis.	10/1/99
Contract with outside agency if necessary	10/1/99
Deliver samples to tester	10/1/99
Monitor test analysis progress	10/25/99
Receive final test report	10/27/99
Review and publish conclusion	10/31/99



3713 9591


AB



AB

3713 9592

ATTACHMENT 6
Hydraulic Pressure Switch Cross Section



To: Jay Logel ~~talk to~~

Quote

From: Steve Reimers

Re: Recall 99S15 Returned Parts Analysis

I have spoken with Central lab and they are not equipped to perform the analysis shown below. I need your help to get an outside agency going on these tasks. There are three main tasks. Logging and boxing parts, selecting part sample group, analysis of sample group, and comparative analysis. The details of the tasks are shown in the following pages. Preferably these tasks would all be done by the same agency to avoid delivery delays, but could be split up if necessary.

I am available to discuss these tasks with whomever you recommend.

I have also included the work plan for this effort.

Steve Reimers,
sreimers, 39-03286

SREIMERS@Ford.com

313 - 390 - 3286

Bldg 5

► Potomac & Oakwood

3713 9594

MRI

LOGGING AND BOXING task.

Collect parts (RAC code FED S1) from Ford Warranty Return Parts Center.

Important....DO NOT SEPARATE YELLOW TAG FROM PARTS!!!

If yellow tag is missing, then add a tag with VIN, ODOM, and State from worksheet packaged with parts.

For each brake pressure switch record the following in an Excel spreadsheet file (Part_

1. 10 digit Yellow Tag number (or enter VIN and Odom miles and State)
2. 11 digit Part Number stamped on brake pressure switch.
3. 4 digit Date Code stamped on brake pressure switch following after part number
4. YES or NO, Resistance between terminals is less than 1 ohm.

Box parts in the following Date Code groups:

1. less than 1200.
2. 1201 to 1228.
3. 1229 to 1257.
4. 1258 to 1285.
5. 1286 to 1313.
6. 1314 to 1341.
7. 1342 to 2000.
8. 2001 to 2028.
9. 2029 to 2057.
10. 2058 to 2085.
11. 2086 to 2113.
12. 2114 to 2141.
13. 2142 to 2169.
14. 2170 to 2197.
15. 2198 to 2225.
16. 2226 to 2253.
17. 2254 to 2281.
18. 2282 to 2309.
19. 2310 to 2337.
20. 2338 to 3000.
21. 3001 to 4000.
22. 4001 to 9000.
23. 9001 to 9365.
24. unreadable.

~~3000 - 7000~~

Change
all cataloged
later.

ANALYSIS task

1998 every 400 miles

1400 in vehicle parts 665-700

For 432 brake pressure switches record the following in an excel spreadsheet file.

External

1. 10 digit Yellow Tag number (if none, then enter VIN)
2. YES or NO, Condition of plastic base shows heat damage or melting.
3. YES or NO, Condition of electrical connector shows leakage.
4. YES or NO or missing, Mating connector shows signs of fluid leakage.
5. Foam or Silicone or missing, Mating connector seal.
6. YES or NO or missing, Mating seal shows compression mark.
7. YES or NO, Kapton shows delamination bubbles.
8. YES or NO, Kapton shows non-symmetric deformation.
9. Brake pressure switch height inches +/- 0.01
10. Crimp ring o.d. inches +/- 0.01
11. Crimp ring height inches +/- 0.01
12. Actuation pressure psi +/- 2
13. Reset pressure psi +/- 2
14. Leakage rate psi / minute (<62 psi / 30 seconds at 3000 psi)
15. Resistance between terminals ohms +/- 0.1 ohm, @ 0 psi.
16. Resistance between terminals ohms +/- 0.1 ohm, @ 200 psi.
17. YES or NO, Resistance from terminals to hex-port less than 10,000 ohm @ 0 psi
18. YES or NO, Resistance from terminals to hex-port less than 10,000 ohm @ 200 psi

Y/N

at ϕ closed

Air Pressure ok

spec req. Air

Body not grounded

Fluorescopic examination (photograph items logged "Yes")

18. Yes or No, loose metal parts are present in base assembly
19. Yes or No, Spring arm is touching sensor cup
20. Yes or No, Spring arm shows cracks or material loss
21. Yes or No, Moveable terminal shows cracks or material loss
22. Yes or No, Stationary terminal shows cracks or material loss

2.5 in 1 in OD

- Rear brake after APCV

ANALYSIS task (continued)

Internal

Carefully separate the base from the sensor by removing crimp ring, preserving the part number and date code. Bag each loose part individually and keep with Yellow Tag.

- 23. Connector Leak? No Yes
- 24. Component wear? None Light Medium Heavy
- 25. Brake Fluid leak? No Yes
- 26. Environment seal condition? Good Bad
- 27. If seal bad, describe condition.
- 28. Sensor Cup Corrosion? Yes No (if YES, provide photo and chemical composition)
- 29. Sensor cup crimp o.d.
- 30. Sensor cup crimp height
- 31. Force (apply at bump) to deflect spring arm to close contacts.
- 32. Transfer Pin stroke from 0 to 200 psi and from 200 to 1400 psi.
- 33. Transfer pin height above cup (0, 200, and 1400 psi)
- 34. Stationary/ Moveable terminal retention Loose Firm
- 35. Stationary/ Moveable terminal condition OK Discolored
Corroded (if corroded, provide photo and chemical composition)

Carefully separate the hex-port from the sensor cup by opening the sensor cup crimp. Bag each loose part individually and keep with Yellow Tag.

36. Diaphragm Inspection - indicate presence of listed conditions for each side of each layer of Kapton.

Condition	Nearest Fluid		Middle		Nearest Converter	
	Fluid #1	Converter	Fluid #2	Converter	Fluid #3	Converter
	Teflon	Kapton	Teflon	Kapton	Teflon	Kapton
Teflon stretch						
Teflon cracks						
Teflon delamination						
Kapton cracks						
Strain pattern						
Wear particals/discoloration						
	37. Gasket Inspection					
	Present		Yes		No	
	Nibbles/missing material		Yes	No		

SAMPLE SELECTION task

Select a sample group of 432 parts with the following criteria from the above boxed parts:

1. All samples must have part number F2VC-9F924- AB or BB.
2. Vehicle line, odometer mileage, date code, region, and vehicle build date as shown below.

Town Car

High Mileage VINs (> 100K)

parts date coded < 2000

6 Southern Coastal states build date < Feb 1 1992

6 Other states build date < Feb 1 1992

parts date coded 2001 thru 2184 (Jan 1 1992 - June 30 1992)

Southern Coastal states

2 build date < Feb 1 1992

2 Feb 1 1992 < build date < Nov 30 1992

2 build date > Nov 30 1992

Other states

2 build date < Feb 1 1992

2 Feb 1 1992 < build date < Nov 30 1992

2 build date > Nov 30 1992

parts date coded 2185 thru 2304 (July 1 1992 - Oct 31 1992)

Southern Coastal states

3 Feb 1 1992 < build date < Nov 30 1992

3 build date > Nov 30 1992

Other states

3 Feb 1 1992 < build date < Nov 30 1992

3 build date > Nov 30 1992

parts date coded 2305 thru xxxx (Nov 1 1992 - xxxx)

Southern Coastal states

3 Feb 1 1992 < build date < Nov 30 1992

3 build date > Nov 30 1992

Other states

3 Feb 1 1992 < build date < Nov 30 1992

3 build date > Nov 30 1992

Median Mileage (40K to 100K)

48 same criteria as High Mileage

Low Mileage (< 40K)

48 same criteria as High Mileage

Crown Victoria

144 same criteria as Town Car above

Grand Marquis

144 same criteria as Town Car above

total = 432 parts

Comparative Analysis task

Quantify differences between three groups: 1. 10 Parts from peak of claims reports population; 2. 10 Parts from end of recall population; 3. 10 New/ unused current production parts.

Forces applied (insitu) to
stationary terminal at contact
moving terminal at spring arm bump (0, 200, and 1400 psi)
ceramic pin at snap disk
snap disk at converter
converter at Kapton
terminal retaining forces

Dimensional Analysis
assembly height (0, 200, and 1400 psi)
spring arm to cup clearance (0, 200, and 1400 psi)
crimp ring o.d and height (0, 200, and 1400 psi)
stationary contact to cup clearance (0, 200, and 1400 psi)
Transfer pin height above opening (0, 200, and 1400 psi)
base height
base crimp flange o.d., thickness
enviro seal flange o.d., thickness
sensor cup crimp o.d. and height (0, 200, and 1400 psi)
converter button profile
converter button outside diameter
converter button clearance from top of washer (0, 200, 1400 psi)
washer hole profile
washer hole inside diameter (bottom of taper)
washer hole taper outside diameter
washer thickness
washer outside diameter
hex-port gasket groove i.d., o.d., depth
hex-port i.d. at Kapton interface
hex-port o.d., thickness at crimp flange
stationary terminal minimum cross-section
moving terminal minimum cross-section
Kapton profile (0, 200, and 1400 psi)
Transfer pin length, o.d.
Sensor cup transfer pin opening i.d.

TI

Purpose: Determine Root Cause of Town Underhood Fire Allegations

Work plan	Target completion
Receive parts, prelim exam, sort and store.	9/30/99
Draft analysis scope of work .	9/15/99
Distribute draft for adds/deletes.	9/15/99
Review and update draft.	9/17/99
Meet with Central Lab to discuss sow	9/20/99
Finalize analysis scope of work	9/21/99
Select samples for analysis.	10/1/99
Contract with outside agency if necessary	10/1/99
Deliver samples to tester	10/1/99
Monitor test analysis progress	10/25/99
Receive final test report	10/27/99
Review and publish conclusion	10/31/99

SAMPLE SELECTION task

Select a sample group of 432 parts with the following criteria from the above boxed parts:

1. All samples must have part number F2VC-9F924- AB-or-BB.
2. Vehicle line, odometer mileage, date code, region, and vehicle build date as shown below.

Town Car

High Mileage VINs (> 100K)

parts date coded < 2000

6 Southern Coastal states build date < Feb 1 1992

6 Other states build date < Feb 1 1992

parts date coded 2001 thru 2184 (Jan 1 1992 - June 30 1992)

Southern Coastal states

2 build date < Feb 1 1992

2 Feb 1 1992 < build date < Nov 30 1992

2 build date > Nov 30 1992

Other states

2 build date < Feb 1 1992

2 Feb 1 1992 < build date < Nov 30 1992

2 build date > Nov 30 1992

parts date coded 2185 thru 2304 (July 1 1992 - Oct 31 1992)

Southern Coastal states

3 Feb 1 1992 < build date < Nov 30 1992

3 build date > Nov 30 1992

Other states

3 Feb 1 1992 < build date < Nov 30 1992

3 build date > Nov 30 1992

parts date coded 2305 thru xxxx (Nov 1 1992 - xxxx)

Southern Coastal states

3 Feb 1 1992 < build date < Nov 30 1992

3 build date > Nov 30 1992

Other states

3 Feb 1 1992 < build date < Nov 30 1992

3 build date > Nov 30 1992

Median Mileage (40K to 100K)

48 same criteria as High Mileage

Low Mileage (< 40K)

48 same criteria as High Mileage

Crown Victoria

144 same criteria as Town Car above

Grand Marquis

144 same criteria as Town Car above

total = 432 parts

3713 9601

ANALYSIS task

For 432 brake pressure switches record the following in an excel spreadsheet file.

External

- Need Def.*
Need Def.
Mating Conn. Supplied?
Seal Between Conn.
Need Def.
Kapton is GE material - which part?
Height Relative to what?
1. 10 digit Yellow Tag number (if none, then enter VIN)
 - 2. YES or NO, Condition of plastic base shows heat damage or melting.
 - 3. YES or NO, Condition of electrical connector shows leakage.
 - 4. YES or NO or missing, Mating connector shows signs of fluid leakage.
 - 5. Foam or Silicone or missing, Mating connector seal.
 - 6. YES or NO or missing, Mating seal shows compression mark.
 - 7. YES or NO, Kapton shows delamination bubbles.
 - 8. YES or NO, Kapton shows non-symmetric deformation. *Need f. bore scope?*
 - 9. Brake pressure switch height inches +/- 0.01 *- whole switch*
 10. Crimp ring o.d. inches +/- 0.01 *- g*
 11. Crimp ring height inches +/- 0.01 *- how many places*
 12. Actuation pressure psi +/- 2
 13. Reset pressure psi +/- 2
 14. Leakage rate pass/fail psi / minute (62 psi / 30 seconds at 3000 |)
 15. Resistance between terminals ohms +/- 0.1 ohm, @ 0 psi.
 16. Resistance between terminals ohms +/- 0.1 ohm, @ 200 psi.
 17. YES or NO, Resistance from terminals to hex-port less than 10,000 ohm @ 0 psi
 18. YES or NO, Resistance from terminals to hex-port less than 10,000 ohm @ 200 psi

Fluoroscopic examination (photograph items logged "Yes")

18. Yes or No, loose metal parts are present in base assembly
19. Yes or No, Spring arm is touching sensor cup
20. Yes or No, Spring arm shows cracks or material loss
21. Yes or No, Moveable terminal shows cracks or material loss
22. Yes or No, Stationary terminal shows cracks or material loss

look at after opening?

#

ANALYSIS task (continued)

Internal

Carefully separate the base from the sensor by removing crimp ring, preserving the part number and date code. Bag each loose part individually and keep with Yellow Tag.

- 23. Connector Leak? No Yes
- 24. Component wear? None Light Medium Heavy
- 25. Brake Fluid leak? No Yes
- 26. Environment seal condition? Good Bad
- 27. If seal bad, describe condition.
- 28. Sensor Cup Corrosion? Yes No (if YES, provide photo and chemical composition)
- 29. Sensor cup crimp o.d.
- 30. Sensor cup crimp height
- 31. Force (apply at bump) to deflect spring arm to close contacts. *hand held ? -> DAG*
- 32. Transfer Pin stroke from 0 to 200 psi and from 200 to 1400 psi.
- 33. Transfer pin height above cup (0, 200, and 1400 psi)
- 34. Stationary/ Moveable terminal retention Loose Firm
- 35. Stationary/ Moveable terminal condition OK Discolored Corroded (if corroded, provide photo and chemical composition)

Need to use LVDT / Dial indicator

Carefully separate the hex-port from the sensor cup by opening the sensor cup crimp. Bag each loose part individually and keep with Yellow Tag.

36. Diaphragm Inspection - indicate presence of listed conditions for each side of each layer of Kapton.

Nearest Fluid		Middle		Nearest Converter	
Fluid #1	Converter	Fluid #2	Converter	Fluid #3	Converter
Teflon	Kapton	Teflon	Kapton	Teflon	Kapton
Teflon		Teflon		Teflon	

- examples*
- Condition
 - Teflon stretch
 - Teflon cracks
 - Teflon delamination
 - Kapton cracks
 - Strain pattern
 - Wear particals/discoloration

37. Gasket Inspection

Present	Yes	No
Nibbles/missing material	Yes	No

LOGGING AND BOXING task.

Collect parts (RAC code FED S1) from Ford Warranty Return Parts Center.

Important....DO NOT SEPARATE YELLOW TAG FROM PARTS!!!
If yellow tag is missing, then add a tag with VIN, ODOM, and State from worksheet packaged with parts.

For each brake pressure switch record the following in an Excel spreadsheet file-
(Part-)

1. 10 digit Yellow Tag number (or enter VIN and Odom miles and State)
2. 11 digit Part Number stamped on brake pressure switch.
3. 4 digit Date Code stamped on brake pressure switch following after part number
4. YES or NO, Resistance between terminals is less than 1 ohm.

Box parts in the following Date Code groups:

1. less than 1200.
2. 1201 to 1228.
3. 1229 to 1257.
4. 1258 to 1285.
5. 1286 to 1313.
6. 1314 to 1341.
7. 1342 to 2000.
8. 2001 to 2028.
9. 2029 to 2057.
10. 2058 to 2085.
11. 2086 to 2113.
12. 2114 to 2141.
13. 2142 to 2169.
14. 2170 to 2197.
15. 2198 to 2225.
16. 2226 to 2253.
17. 2254 to 2281.
18. 2282 to 2309.
19. 2310 to 2337.
20. 2338 to 3000.
21. 3001 to 4000.
22. 4001 to 9000.
23. 9001 to 9365.
24. unreadable.

3-7 K

Comparative Analysis task

Quantify differences between three groups: 1. 10 Parts from peak of claims reports population; 2. 10 Parts from end of recall population; 3. 10 New/ unused current production parts.

Forces applied (insitu) to

stationary terminal at contact
moving terminal at spring arm bump (0, 200, and 1400 psi)
ceramic pin at snap disk
snap disk at converter
converter at Kapton
terminal retaining forces

Dimensional Analysis

assembly height (0, 200, and 1400 psi)
spring arm to cup clearance (0, 200, and 1400 psi)
crimp ring o.d and height (0, 200, and 1400 psi)
stationary contact to cup clearance (0, 200, and 1400 psi)
Transfer pin height above opening (0, 200, and 1400 psi)
base height
base crimp flange o.d., thickness
enviro seal flange o.d., thickness
sensor cup crimp o.d. and height (0, 200, and 1400 psi)
converter button profile
converter button outside diameter
converter button clearance from top of washer (0, 200, 1400 psi)
washer hole profile
washer hole inside diameter (bottom of taper)
washer hole taper outside diameter
washer thickness
washer outside diameter
hex-port gasket groove i.d., o.d., depth
hex-port i.d. at Kapton interface
hex-port o.d., thickness at crimp flange
stationary terminal minimum cross-section
moving terminal minimum cross-section
Kapton profile (0, 200, and 1400 psi)
Transfer pin length, o.d.
Sensor cup transfer pin opening i.d.

Purpose: Determine Root Cause of Town Underhood Fire Allegations

Work plan	Target completion
Receive parts, prelim exam, sort and store.	9/30/99
Draft analysis scope of work .	9/15/99
Distribute draft for adds/deletes.	9/15/99
Review and update draft.	9/17/99
Meet with Central Lab to discuss sow	9/20/99
Finalize analysis scope of work	9/21/99
Select samples for analysis.	10/1/99
Contract with outside agency if necessary	10/1/99
Deliver samples to tester	10/1/99
Monitor test analysis progress	10/25/99
Receive final test report	10/27/99
Review and publish conclusion	10/31/99

Ford Pressure Switch Study | "To Do List"

• Logging & Boxing Task

- ▶ Create Database Access 3-7k parts
- ▶ Obtain Box's

• Analysis External

▶ Need Def.

- plastic base heat damage
- connector leakage
- mating connector leakage

▶ Measurements

#9 } How many places & how
10 }
11 }

▶ Kapton - which component?

▶ Activation Pressure / Leakage Rate ...

- Get DAQ System
- Write DAQ Prog
- Write Analysis Prog

▶ Setup to Measure Term Resistance under pressure < need some enclosure > 15 - 18a

▶ Find Fluoroscope with photographic capability

50 SHEETS
100 SHEETS
22-141
22-142
22-144
200 SHEETS



Internal

► Need LVDY
32 & 33

Set up & Pressure & Fixture

20-141 40 SHEETS
20-142 100 SHEETS
20-144 200 SHEETS





Service Recall Bulletin

May, 1999

TO: All Ford and Lincoln Mercury Dealers

SUBJECT: Safety Recall 99S15: Certain 1992 and 1993 Crown Victoria, Grand Marquis, and Lincoln Town Cars with Speed Control - Speed Control Deactivation Switch

AFFECTED VEHICLES

Certain 1992 and 1993 Crown Victoria and Grand Marquis with Speed Control built at the St. Thomas assembly plant from February 5, 1992 through November 30, 1992. Also, certain 1992 and 1993 Town Cars built at the Wixom Assembly plant from November 4, 1991 through November 30, 1992.

REASON FOR RECALL

Some Speed Control Deactivation Switches on the affected vehicles may develop a resistive short in the electrical circuit that may potentially result in an underhood fire. A fire is possible both when the vehicle is running and when the vehicle engine is off. Also, the short may disable the speed control system or cause a fuse to open.

SERVICE ACTION

Repair parts will not be available until mid-June, 1999. Until parts are available, the interim repair described in Attachment III should be used. When parts are available the permanent repair must be completed to close this recall.

Interim Repair: This repair should be performed immediately to eliminate the possibility of a fire. This interim repair involves disconnecting the electrical connector from the Speed Control Deactivation Switch, taping the connector end to protect it from contamination and securing the connector with a tie-strap. The speed control system will be inoperative until the permanent repair is performed.

Permanent Repair: The parts for this repair are expected to become available the middle of June, 1999. This repair will involve the replacement of the Speed Control Deactivation Switch with a new switch. In addition, the switch hard-shell connector will be replaced to eliminate the possibility of undetected heat damage to the connector.

Safety Recall 99S15
Certain 1992 and 1993 Crown Victoria, Grand Marquis, and Lincoln Town Cars
with Speed Control - Speed Control Deactivation Switch

OASIS

You must use OASIS to determine if a vehicle is eligible for this recall.

Please note that the Interim Repair will not remove the VIN from OASIS.

PLEASE NOTE

Correct all vehicles in stock before delivery. Federal law requires dealers to complete any outstanding safety recall service before a new vehicle is delivered to the buyer or lessee. Violation of this requirement by a dealer could result in a civil penalty of up to \$1,100 per vehicle.

PROMPTLY CORRECT

Promptly correct affected vehicles on the enclosed list and other eligible vehicles which are brought to your dealership.

DEALER-OWNER CONTACT

Immediately contact any affected owner whose name is not on the list. Give the owner a copy of the Owner Letter and schedule a service date.

REGIONAL CONTACT

Advise regional office if an owner:

- cannot be contacted.
- does not make a service date.

CLAIMS PREPARATION AND SUBMISSION

- Enter claims using DWE.
- Refer to ACESII Manual for claims preparation and submission information.
- After performing the Permanent Repair, the replaced parts must be returned to the Warranty Parts Return Center for inspection (See Attachment II page 2). FCS 700 tags will be sent as soon as the claim for the Permanent Repair is submitted.

OWNER REFUNDS

Ford Motor will only refund for owner-paid repairs made before the date of the Owner Letter (or after the date of the Owner Letter if an emergency repair was made away from the servicing dealer.) Refer to ACESII Manual for Refund Information.

Safety Recall 99S15
Certain 1992 and 1993 Crown Victoria, Grand Marquis, and Lincoln Town Cars with
Speed Control - Speed Control Deactivation Switch

LABOR ALLOWANCES**Interim Repair**

Description	Labor Operation	Labor Time
Remove, Tape and Secure the Speed Control Deactivation Switch *	99S15E*	0.3 Hour
Administrative Allowance	Misc. Expense Code "ADMIN"	0.1 Hour

* Labor Operation 99S15E will NOT close the Recall.

Permanent Repair

Description	Labor Operation	Labor Time
Replace Speed Control Deactivation Switch and Hard-shell Connector	99S15B	0.5 Hour
Administrative Allowance	Misc. Expense Code "ADMIN"	0.1 Hour

PARTS REQUIREMENTS**Parts Ordering Information**

Parts will not be direct shipped for this recall. Order your parts requirement through normal order processing channels as noted below.

Stock Orders
 Interim Orders
 Emergency Orders
 Emergency Orders

Effective immediately
 Effective immediately
 after July 1, 1999
 before July 1, 1999

Normal order process -
 Normal order process
 Normal order process
 Call 1-800-325-5621

Part Number

XW7Z-9G652-AA

Description

Speed Control Deactivation Switch Kit

Quantity

1

Safety Recall 99S15
Certain 1992 and 1993 Crown Victoria, Grand Marquis, and Lincoln Town Cars with
Speed Control - Speed Control Deactivation Switch

DEALER PRICE

For latest prices, check or call your:

- Order Processing Center
- DOES II
- Updated Price Book

EXCESS STOCK RETURN

Excess stock returned for credit ~~must have been purchased from Ford Customer Service Division in accordance with Policy Procedure Bulletin 4000.~~

DISPOSITION OF REMOVED PARTS

Parts Return Requested (after completion of Permanent Repair):

We are requesting that the removed parts be returned to Ford Motor Company:

- Speed Control Deactivation Switch
- Switch Hardshell Connector

Packaging and Shipping:

- Speed Control Deactivation Switch
 - Do not drain the brake fluid from inside the Speed Control Deactivation Switch.
 - Use the plastic cap from the new switch to trap and seal as much oil inside the switch as possible.
- Switch Hardshell Connector
 - Connect the hardshell connector to the Speed Control Deactivation Switch.
 - Attach the FCS 700 tag to the part
 - Place the part in a plastic bag and secure with twist-tie.
- Shipping Instructions
 - Follow direction on FCS 700 tag
 - See Section 3 of the ACES II manual for more details

INTERIM REPAIR

DISABLE SPEED CONTROL DEACTIVATION SWITCH

SERVICE PROCEDURE

1. Disconnect the electrical connector from the speed control deactivation switch. See Figure 1.




FIGURE 1

2. Tape the end of the connector to prevent contamination from entering the end of the connector.
3. Tie strap the connector to the wiring harness located on the left splash shield.

PERMANENT REPAIR

SPEED CONTROL DEACTIVATION SWITCH AND CONNECTOR REPLACEMENT

AFFECTED VEHICLES: CERTAIN 1992 AND 1993 CROWN VICTORIA, GRAND MARQUIS
AND TOWN CAR WITH SPEED CONTROL

OVERVIEW

This repair involves replacement of the speed control deactivation switch and the hard shell of the switch electrical connector. The connector terminals will be removed from the old connector hard shell and inserted into the *new* connector hard shell.

PROCEDURE

1. Install a memory saver and disconnect the negative battery terminal.
2. Disconnect the electrical connector from the speed control deactivation switch. See Figure 2.




FIGURE 2

3. Remove the locking wedge from the end of the connector. Then, disengage the locking tabs and remove the wire terminals from the connector. See Figure 3.




FIGURE 3

4. Obtain the *new* connector from the kit. Insert both wire terminal ends through the connector seal and into the connector hard shell. (The wire terminal ends may be installed into either of the connector cavities).
5. Check the connector to make sure the locking tabs have engaged both terminal ends. Also, make sure the seal is fully seated in the back of the connector. Then, install the red locking wedge to secure the terminals in the connector.
6. Obtain the speed control deactivation switch from the parts kit.
7. Remove the old speed control deactivation switch.
8. Fill the *new* speed control deactivation switch with High Performance DOT 3 Brake Fluid and install the speed control deactivation switch. Tighten the switch to 18 Nm (13 lb-ft).
9. Attach the electrical connector to the speed control deactivation switch.
10. Connect the battery negative cable and remove the memory saver.
11. Raise the vehicle on a hoist.
12. Connect a clear drain tube to the RH rear bleeder screw and the other end in a container partially filled with the recommended brake fluid.
13. Have an assistant pump the brake pedal and then hold firm pressure on the brake pedal.
14. Loosen the RH rear bleeder screw until a stream of brake fluid comes out. While the assistant maintains pressure on the brake pedal, tighten the bleeder screw.
 - Repeat until clear, bubble-free fluid comes out.
 - Refill the brake master cylinder reservoir as necessary.
15. Repeat Steps 12-14 for the LH rear bleeder screw.
16. Lower the vehicle.

A. R. O'Neil
Director
Vehicle Service and Programs
Ford Customer Service Division



Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121

May, 1999

Safety Recall 99S15

Mr. John Sample
123 Main Street
Anywhere, USA 12345

Your Vehicle Identification Number: 12345678901234567

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Ford Motor Company has decided that a defect which relates to motor vehicle safety exists in certain 1992 and 1993 Crown Victoria, Grand Marquis, and Lincoln Town Cars with Speed Control.

SAFETY DEFECT

Some Speed Control Deactivation Switches on the affected vehicles may develop a resistive short in the electrical circuit that may potentially result in an underhood fire. A fire is possible both when the vehicle is running and when the vehicle engine is off. Also, the short may disable the speed control system or cause the brake light fuse to open.

REPAIRS

Repair parts may not be available until mid-June, 1999. If your dealer is not able to obtain the parts needed for this recall, an Interim Repair can be performed at no charge to you. However a second visit to your dealer will be required at a later date to have the permanent repair performed. We regret this inconvenience, but your safety is our primary concern.

Interim Repair: If parts are not available, the Interim Repair should be performed immediately. This repair involves disconnecting the electrical connector from the Speed Control Deactivation Switch and protecting the connector end from contamination. The Speed Control System will be inoperative until the Permanent Repair is performed; normal vehicle operation without Speed Control is not affected.

Permanent Repair: Parts for this repair are expected to become available the middle of June, 1999. This repair will involve the replacement of the Speed Control Deactivation Switch with a new switch. In addition, the switch hard-shell connector will be replaced to eliminate the possibility of undetected heat damage to the connector.

3713 9616

HOW LONG WILL IT TAKE?

The time needed for either of the repairs is less than one-half day. However, due to service scheduling issues, your dealer may need your vehicle for a longer period of time. Please call your dealer for a service date.

Call your dealer without delay. Ask for a service date and whether parts are in stock for Safety Recall 99S15.

If your dealer does not have the parts in stock, they can be ordered before scheduling your service date. If available, parts would be expected to arrive within a week after ordering. If parts are not available, your dealer can perform the Interim Repair free of charge. When parts are available, your dealer will perform the Permanent Repair free of charge.

When you bring your vehicle in, show the dealer this letter. If you misplace this letter, your dealer will still do the work, free of charge.

REFUNDS

If you paid to have this service done before the date of this letter, Ford is offering a full refund. For the refund, please give your paid original receipt to your Ford or Lincoln Mercury dealer. To avoid delays, do not send receipts to Ford Motor Company.

CHANGED ADDRESS OR SOLD THE VEHICLE?

Please fill out the enclosed prepaid postcard and mail it to us if you have changed your address or sold the vehicle.

If the dealer doesn't make the repair promptly and without charge, you may contact the Ford Customer Assistance Center, P. O. Box 6248, Dearborn, Michigan 48121. You also may send a complaint to the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street, S. W., Washington, D. C. 20590 or call the toll free Auto Safety Hotline 1-800-424-9393 (Washington, D. C. area residents may call 366-0123).

We regret the inconvenience this service may cause you, but we want you to have the work done for your safety and satisfaction with your Ford or Lincoln-built vehicle.

Sincerely,



A. R. O'Neill

Director

Vehicle Service and Programs