


EA02-025

FORD 10/27/03

APPENDIX N

BOOK 31 OF 61

PART 2 OF 4




3713 9616


Draft of 6/10/99

1992 & 1993 Town Car, Crown Victoria and Grand Marquis Speed Control Deactivation Switch


ATTACHMENT 5

Hydrolic Steering Gearbox Cross Section





1713 5620



AB

3713 . 9621

11/1/99

10:00 AM

Steve R.

2000 All Done Now ok resistance

Meas.

Term to Term $> 5 \Omega$

2 Terms to Hes $< 100 K\Omega$

3000

10K pts

1500 lined

200 Unrested

(130) in Excel

1000/wk

4000 current

① Log Root & ② Build each R. No. ③ ④

sep. 4 digit Prefix
6-7 digit base
3 digit suff. (1.5e-)

⑤ Resis between terms

⑥ Resis. Hes to Str

⑦ Resis. Hes to Hes

⑧ Signs of Hes R.

Easy way to see RD & Dots added

3713 9622

Part Separated from Tag - just R.O. #
Parts Binned in same bag.

Can't
be used

Warranty Center

► Chris Wash -
(313) 324-488281

Warranty Return Center

Post Bldg park back door

► Harry Desimone

(313) 348-2044

* FEDS)
RAC Code)

(5070 Commerce Dr. N.
Dearborn, MI 48120

200 Tags a Day

Pts. Coming In

3713 9623

Notes

10/27/99

Central Lab

- Post Notes C.L.
- Steve K.
- Tim L. C.L.
- ?

- Cracks in Stationary Terminal



3713 9624

► Microfocal X Ray

Fractional Focus System

Images Quickly - 2 views

- 2-3 days 432

3500 for 3 full days

► No Real time (MOS) Inspection

- 150 KV

- Gamma Radiograph several inches

Ron Scott

- Large Films Here

160 KV

50 microns

Tube to Image Disk

Tube to Subject

- Small Films

320 KV

Focal Spot 3.5 μm

10ma.

Not Here

- 1st Half \rightarrow (no mask) (5 min)

Hanauatsu X-Ray Tube

130 KV


current 300μA
100μA

Focal 10 μ

- 2nd Half

Same

Under 160 KV micro focus



GM/C.V.

92

AB
F2VC

C 93

AA
F2AC

94

QUIET SW

T C (BB) / AB
F2VS & F2VC

ECON AA / CA

F3TA

FSERIES

CA

Engineering Specification

PART NAME MOTOR ASSEMBLY - SPEED CONTROL DEACTIVATE						PART NUMBER △ ES-F270-99924-A1	
LIT	REV	DATE	REV	REVISIONS	DR	OK	REFERENCE
APPROVED DATA TO COMPLETE SPEC. IS RATED/PLD Rev. A/2 NCXCE10079779C02						PREPARATION/PROMPTED BY R.S. Peo-Jo 9-07-16 CHECKED BY DETAILED BY CONCURRENT APPROVAL SIGNATURES DESIGN ENGINEERING SUPERVISOR R.L. Tamm 10-05-16 DESIGN ENGINEERING MGR. MANUFACTURING SUPERVISOR J. H. [Signature] QUALITY CONTROL C.P. Kinnar 10-05-16 ELECTROSTATIC DIVISION M. N. [Signature]	
						CONTROL ITEM - THE △ SIGN ALSO IDENTIFIES PRODUCT ENGINEERING DESIGNED, MANUFACTURED, CRITICAL CHARACTERISTICS WHICH ARE ADDITIONAL, CRITICAL, OR CHARACTERISTICS IDENTIFIED BY PROCESS PATENTS. NO APPROVAL ON THE Q-MONITOR CONTROL PLANS WHICH REQUIRE PRODUCT ENGINEERING APPROVAL.	
FRAME 1 OF 18			REV			△ ES-F270-99924-A1	

PD 3947-A1, previous edition may NOT be used

Engineering Specification

SWITCH ASSEMBLY - SPEED CONTROL DEACTIVATE

I. General

This specification covers the test requirements for the speed control deactivate switch -9F924- used in the electronic speed control system. Design changes on the switch assembly or its components shall not be made without compliance to Section V of this specification and written approval from the releasing Production Engineering Office.

This engineering specification is a supplement to the released drawing on the above part, and all requirements herein must be met in addition to all other requirements of the part drawing. Minimum measures necessary for demonstrating compliance to these requirements are given in each section.

The engineering tests, sample sizes, and test frequencies contained within this engineering specification reflect the minimum requirements established to provide a regular evaluation of conformance to design intent. The engineering test program is intended as a supplement to normal material inspections, dimensional checking and in-process controls, and should in no way adversely influence other inspection operations.

QI suppliers may implement different test sample sizes and frequencies providing these changes have been included in an alternate Control Plan approved by the design responsible Product Engineering Office and concurred in by SQA.

II. PRODUCTION VALIDATION AND IN-PROCESS TESTS

- Production Validation (PV) Tests must be completed satisfactorily with parts from production tooling (and processes where possible) before ISIR approval and authorization for shipment of production parts can be effected. Parts must be revalidated completely, or per Section V whenever any change is made which could possibly affect part function or performance;
- In-Process Test Phase 1 (IP-1) - IP-1 tests are used to demonstrate process capability and must be completed using initial production parts from production tooling and processes prior to first production shipment approval. IP-1 tests are to continue in effect until process capability is demonstrated.
- In-Process Tests Phase 2 (IP-2) - IP-2 test programs may be implemented only after process capability has been established. Tests must be completed with production parts on a continuing basis. Samples for these tests must be selected on a random basis to represent the entire production population as much as possible. In the event that any of the requirements in these tests is not met, the reaction plan specified in Ford Q101 Sect. 3.5, "Engineering Specification (ES) Test Performance Requirements" shall be invoked.

2	18	REVISED		V ES-P2VC-9F924-AA
FRAME	OF	REVISED		NUMBER

NA PD 3947-82 Revision C dated May 1982


SECTION III. TABLE OF TESTS

Engineering Specification

ITEM	TEST NAME FUNCTIONAL TESTS	PRODUCTION VALIDATION			IN-CIRCUIT IR-1			IN-CIRCUIT IR-2		
		MINIMUM SAMPLE SIZE	STATISTICAL ACCEPTANCE CRITERIA	TEST	MINIMUM SAMPLE SIZE	STATISTICAL ACCEPTANCE CRITERIA	TEST	MINIMUM SAMPLE SIZE	STATISTICAL ACCEPTANCE CRITERIA	
III.										
A	Calibration	72	P90-.96	100%	All Must Pass	100%	All Must Pass	-	-	-
B	Voltage Drop	72	P90-.96	12/lot	P90-.96	4/lot	-	-	-	-
C	Current Leakage	72	P90-.96	3/lot	P90-.96	4/lot	-	-	-	-
D	Proof Test	72	P90-.96	12/lot	P90-.96	4/lot	-	-	-	-
F	Burst	6	P90-.72	3/lot	P90-.72	4/lot	-	-	-	-
I	Vibration	6	P90-.72	3/lot	P90-.72	6/6 lot	P90-.72	-	-	-
J	Terminal Strength	12	P90-.96	6/lot	P90-.72	4/lot	All Must Pass	-	-	-
K	Vacuum	6	P90-.72	3/lot	P90-.72	6/6 lot	P90-.72	-	-	-
L	Temperature Cycle	6	P90-.72	3/lot	P90-.72	6/6 lot	P90-.72	-	-	-
M	Fluid Resistance	36	P90-.96	36/12lots	P90-.94	36/12lots	P90-.96	-	-	-
IV.										
Reliability Tests										
G	Impulse	24	P90-.90	12/lot	P90-.96	3/3 lot	P90-.96	-	-	-
H	Humidity	6	P90-.72	3/lot	P90-.72	6/6 lot	P90-.72	-	-	-
I	Salt Spray	6	P90-.72	3/lot	P90-.72	6/6 lot	P90-.72	-	-	-

Engineering Specification

INSPECTION VALIDATION FLOW CHART



TM PD 3947-02 (earlier editions may not be used)

3713 9652

Engineering Specification

III. TEST PROGRAMS AND REQUIREMENTS

▽ A. Calibration

1. Test Requirements

- a. Switch calibration is to be checked at room temperature (16°C - 35°C) using ambient air or equivalent.
- b. Calibration settings shall be specified on the part drawing with the settings checked after 2 or more pressure cycles with ambient air, or equivalent. Pressure cycle range is to be determined by the manufacturer to insure switch calibration stability. The cut-in and differential set points are to be measured while conducting 750 ± 50 millamps while 19.0 ± 1.0 volts D.C. is applied. The cut-in point is to be checked with increasing pressure.
- c. The cut-out point is to be checked with decreasing pressure, and the differential set point is to be calculated using the cut-in pressure minus the cut-out pressure.

2. Acceptance Requirements

- a. Nonconformance is defined as any switch point which falls outside the tolerance band specified on the part drawing.

B. Voltage Drop

1. Test Requirements

- a. Voltage drop is to be measured after 2 or more cycles with ambient air or equivalent from 0 to $10,000 \pm 172$ KPa (1450 ± 25 PSI) while conducting 750 ± 50 millamps and 19.0 ± 1.0 volts D.C. is applied to the switch. Under these conditions with the switch closed the voltage drop is to be measured. Millivolt connection interface at terminals to be less than 10 millivolts.

2. Acceptance Requirements

- a. Nonconformance is defined as a voltage drop in excess of 200 millivolts.

5	18	REVISED	NUMBER
---	----	---------	--------

NAF PD 3947-02 (Previous editions may not be used)

3713 9653

Engineering Specification

II. TEST PROCEDURES AND REQUIREMENTS (cont'd)

C. Current Leakage

1. Test Requirements

- a. Current leakage is to be checked with 500 volts, 60 Hz alternating current.
- b. Current leakage is to be checked:
 - (1) Between the switch leads with the contacts open.
 - (2) Between the lead and the switch housing with contacts closed.
 - (3) Between either lead and switch housing with the contacts open.

2. Acceptance Requirements

- a. Nonconformance is defined as any leakage current in excess of one hundred (100) microampere.

D. Proof Test

1. Test Requirements

- a. Subject sample switches to Section A to establish their initial switching pressures.
- b. Proof test is to be conducted using brake fluid or equivalent as the pressure medium. Test pressure shall be as specified on the part drawing. Test pressure shall be isolated from pressure source and held for not less than 30 seconds.
- c. Recheck the switches to Section A.

2. Acceptance Requirements

- a. No evidence of fluid leakage, seepage, or drop in test pressure greater than 430 KPa.(62 PSI) is permitted.
- b. A change in cut-in and cut-out pressures greater than $\pm 5\%$ from the initial value is not permitted.
- c. The test samples must be destroyed after testing.

II. TEST PROCEDURES AND REQUIREMENTS (cont'd)

Impulse

1. Test Requirements

- a. Test the switch for a total of 500,000 cycles. Cycle pressure between (low) 0-276 KPa (0-40 psi) and (high) 10,000 \pm 345 KPa (1450 \pm 50 psi).
 - 1) 0 - 475,000 cycles: 13 \pm 1 volts, trace current to monitor function.
 - 2) 475,001 - 500,000 cycles: 13 \pm 1 volts D.C., 750 \pm 50 ma., per figure 4.
- b. Brake fluid temperature to be 135 \pm 14°C and ambient temperature to be 107°C min.
- c. Cycle rate is to be 110-130 cycles per minute.
- d. Switch must open and close each cycle.

2. Acceptance Requirements

- a. After impulse test check to sections A, B, C, & D using the procedure established in each section.
- b. Nonconformance is defined as any switch not meeting the criteria in sections A, B, C, & D.
- c. Samples used for this test must be destroyed after all testing is completed.

F. Burst

1. Test Requirement

- a. Burst strength is to be checked using brake fluid or equivalent as the pressure medium.
- b. Pressurize the switch to 48.3 MPa (7000 PSI) minimum and hold for 30 seconds minimum.

2. Acceptance Requirements

- a. Nonconformance is defined as any evidence of fluid leakage or seepage from the switch or threads. Samples used for this test must be destroyed after testing is completed.

S7
5596

7	18	REVISED	NUMBER
OF			▼ ES-F2VC-9F924-AA

Engineering Specification

III. TEST PROGRAMS AND REQUIREMENTS (CONT'D)

C. Humidity

1. Test Requirements

- a. Mount the switch in the test port in a humidity chamber. Currently released mating electrical connector must be installed before start of test.
- b. Subject the switch to ten (10) continuous humidity cycles as follows:
 - (1) Raise temperature to 65 +10/-2 °C over 2.5 hours; at 90-98% relative humidity.
 - (2) Hold 3 hours at 65 +10/-2 °C at 90-98% relative humidity.
 - (3) Lower temperature to 23 +10/-2 °C over 2.5 hours; at 80-98% relative humidity.

2. Acceptance Requirements

- a. Within 15 minutes after completion of the tenth humidity cycle check the switch to sections A, B, C, D, using the procedure established in each section.
- b. Nonconformance is defined as any switch not meeting the criteria in sections A, B, C, or D.

D. Salt Spray

1. Test Requirements

- a. Mount the switch in the test port in a salt spray chamber. The currently released mating electrical connector and wiring must be installed prior to start of test.
- b. Expose the switch assembly to 72 hours of salt spray per ASTM B-117.

2. Acceptance Requirements

- a. After exposure, check the switch to sections A, B, C, D, using the procedure established in each section.
- b. Nonconformance is defined as any switch not meeting the criteria in sections A, B, C, or D. Samples used for this test must be destroyed after all testing is completed.

8	18	REVISED	NUMBER
FRAME	OF		▽ ES-F2VC-9F924-AA

999
E111

Engineering Specification

III. TEST PROCEDURES AND REQUIREMENTS (cont'd)

I. Vibration

1. Test Requirements

- a. Mount the switch in the test port and attach the currently released mating electrical connector before start of test.
- b. Switches are to be vibrated in all 3 planes with electrical continuity being monitored during the entire test. See Figure 1 for switch orientation in the 3 planes. Vibration tests are to be conducted at room temperature using brake fluid, ambient air, or equivalent as the pressure medium.
- c. Internal pressure shall be maintained at 0 KPa G. when the switch is in the closed position and 1.1 times max actuation pressure shown on print when the switch is in the open position.
- d. Vibrate the switch at 1.5 mm displacement (peak-to-peak) while varying the frequency uniformly from 5 to 50 Hz over a 3 minute period.
- e. Vibrate the switch in alternate one-hour periods in the open and closed positions for a total of 8 hours in each plane. (Total test time is 24 hours).

2. Acceptance Requirements

- a. After the entire vibration sequence check the switches to sections A, B, C, or D using the procedures established in each section.
- b. Nonconformance is defined as any evidence of leakage or any change in electrical continuity/discontinuity during the vibration cycles, or any switch not meeting the criteria in sections A, B, C, or D. Samples used for this test must be destroyed after all testing is completed.

18	REVISED	NUMBER	▽ ES-F2VC-9F024-AA
OF			

Engineering Specification

III. TEST PROCEDURES AND REQUIREMENTS (cont'd)

J. Terminal Strength

1. Test Requirements

- a. Mount the switch in the test port.
 - (1) Apply a 89 ± 9 N axial force to each terminal.
 - (2) With a pendulum apply a 45 ± 5 N impact force to the switch housing at the connector end, perpendicular to the centerline axis of the switch. See Figure 2 for force application point and direction.

2. Acceptance Requirements

- a. Check the switch to sections A, B, C, and D using the procedures established in each section.
- b. Nonconformance is defined as any terminal or housing fracture, or any switch not meeting the criteria in sections A, B, C, or D.

K. Vacuum

1. Test Requirements

- a. Mount the switch in the test port. Vacuum tests are to be conducted at room temperature using ambient air as the pressure medium.
- b. Subject the switch to 5 cycles of vacuum from atmospheric pressure (760 mm Hg) to an absolute pressure of 3-6 mm Hg. Maintain the vacuum for a minimum of 60 seconds.

2. Acceptance Requirements

- a. Check the switch to sections A, B, C, and D using the procedure established in each section.
- b. Nonconformance is defined as any switch not meeting the criteria in sections A, B, C, and D.

10	10			▼ ES-P2VC-9F924-AA
REVISED			NUMBER	

Engineering Specification

III. TEST PROCEDURES AND REQUIREMENTS (cont'd)

L. Temperature Cycle

1. Test Requirements

- a. Mount switches in test ports; test to be run using currently released brake fluid.
- b. Repeat the following procedure 25 times.
 - (1) Lower the switch and fluid temperature to at least -40°C.
 - (2) Cycle the switches ten times at 10 seconds/cycles. One cycle consists of a pressure variation from 0 - 276 KPa.G (0-40 psi) to 10,000 \pm 345 KPa.G (1450 \pm 50 PSI).
Note: Switch must open and close each cycle.
 - (3) Raise switch and fluid temperature to 38°C minimum.
 - (4) Repeat Step 2.
- c. At completion of Step b, check switches per sections A, B, C, and D.

2. Acceptance Requirements

- a. Nonconformance is defined as any evidence of switch fluid leakage, sapage, or not meeting the criteria of sections A, B, C, and D.

M. Fluid Resistance

1. Test Requirements

- a. Mount the switch in the test port and orient as installed in the vehicle.
- b. Install the currently released mating electrical connector (with wire leads) to the switch.
- c. Sequentially, immerse the switch into each of the specified fluids, at a temperature of 23 \pm 2 °C, for 5 \pm 1 second. Remove the switch and drain and store the switch for the specified time at room temperature, prior to immersing into the next fluid.

11	18			✓ ES-F2VC-9F924-AA
FRAME	OF	REVISED		NUMBER
FD 3947-B2 (Previous editions may NOT be used)				3713 9669

Spring Specification

TEST PROCEDURES AND REQUIREMENTS (cont'd)

<u>Fluid</u>	<u>Brain Time</u>	<u>Storage Time</u>
Reference Fuel C ASTM D471	60 \pm 5 min.	none
10W40 Engine Oil	24 \pm 1 hour	14 days
Ethylene Glycol/ Water 50/50 by Volume	24 \pm 1 hour	24 \pm 1 hour
Brake Fluid DOT 3	24 \pm 1 hour	48 \pm 1 hour
Automatic Transmission/ Power Steering Fluid (same) ESP-M2G138-GJ	24 \pm 1 hour	14 days
Isopropyl Alcohol/ Water 50/50 by Volume	24 \pm 1 hour	none
Reference Fuel C, ASTM D471 with Methyl Alcohol 85/15 by Volume	24 \pm 1 hour	none

d. Per the Flow Chart, subject the prescribed number of immersed switches to the post immersion tests specified below:

- III. E. Impulse
- III. G. Humidity
- III. H. Salt Spray
- III. J. Terminal Strength

Acceptance Requirements

- a. switches must fully meet the requirements of the specified post immersion test.
- b. Nonconformance is defined as any switch not meeting the criteria in sections A, B, C, or D. Samples used for this test must be destroyed after all testing is completed.

12	18			▼ ES-F2VG-9F924-AA
FRAME	OF	REVISED		NUMBER

Engineering Specification

V. STATISTICAL ANALYSIS METHODS

- A. For PV, IP-1 and IP-2 tests, all samples tested must pass. Having all the required sample size pass will provide data to support the conclusion that the switch has a minimum reliability R, at a given confidence of C. The notation P_c-R is interpreted as minimum reliability equal to R, at a confidence C; thus P90-.80 means a minimum reliability of 80% at 90% confidence.
- B. All samples must pass is the statistical test acceptance criteria stated for tests with 100% frequency; or samples from lots, which could have a variable size.

REVALIDATION REQUIREMENTS

- A. No change in design, material, process or component supplier shall be made without prior approval from the releasing Product Engineering Office. As part of approving a change, the releasing Product Engineering Office will establish the portion of the Product Validation tests required to be run to revalidate the switch. The following table is to be used as a guide in determining the type of tests required for revalidation requirements.

RUNNING CHANGE REVALIDATION

<u>Component</u>	<u>Process or Material Change or New Supplier</u>
1. Terminals, Contacts, or Connector	III, B, C, E, G, H,I, J, L, M.
2. Case or Housing	All Tests
3. Disc or Diaphragm	III, A,D,E,F,I,K,L
4. Fitting or Fluid Connection	III, D, E, F, H, I, M,
B. Annual revalidation is not required on carryover switches.	

VI. LOT DEFINITION

A lot is defined as no more than eight (8) hours of production up to 4,000 pieces. If shifts extend beyond eight (8) hours, or more than 4,000 pieces are produced in a shift, the product must be separated into at least two lots.

713
561

13	18			✓ ES-F2VC-9F924-AA
NAME	OF	REVISED		NUMBER

Engineering Specification

VII. RECORD RETENTION

- A. Recording and record retention shall conform with Ford Q-101.
- B. Production Validation test results and analysis are to be forwarded to the releasing Product Engineering Office before approval for shipment of production parts can be granted.
- C. In-Process test results shall be available at the supplier's manufacturing facility for the releasing Product Engineering Office and Ford SQA or its representatives to review on request.

VIII. INSTRUCTIONS AND NOTES

All switches are to be identified with the Ford part number, supplier identification, and a date code indicating final assembly.

All test equipment and test procedures for testing to this specification must be approved by the releasing Product Engineering Office and no change in equipment or procedure may be made without their written concurrence.

Test port configuration is shown in Figure 3.

O-rings, if used in the design, shall be free from cuts, nicks, abrasions or any other damage which would result in a fluid leak.

All switches must have a shipping cap installed over the port threads to prevent contamination. All shipping caps must be approved by the releasing Product Engineering Office prior to production incorporation.

All switches that do not pass the calibration test are to either be readjusted and rechecked, or scrapped. (Salvage of component parts permitted with 100% reinspection).

If product nonconformance occurs for test Sections III. B, C, D, E, F, and J, production shall be stopped and the problems corrected. All production lots shall be sorted 100% prior to shipment. Suspected nonconformance of any shipped parts shall be reported immediately to the releasing Product Engineering Office.

If nonconformance of the statistical acceptance criteria occurs for test Sections III. G, H, I, K, L and M, a cause to recall the subject weeks production and to stop production may result.

7000
7000
7000

14	18	REVISED		▼ ES-F2VC-9F924-AA
NAME	OF		NUMBER	

Engineering Specification

IX. COMPILED OF REFERENCE DOCUMENTS

ASTM B-117, Salt Spray Testing

Ford Q-101, Quality System Standard - 1990 Edition


ES-PUEB-1AAA64-AA, Specification - SLV Assy - Wire Connector

ES-F2VF-9C735-AA, Specification - Servo Assembly Speed Control

15	OF	18	REVISED	NUMBER
----	----	----	---------	--------



▽ ES-F2VC-9F924-AA

Engineering Specification



VIBRATION TEST - SWITCH ORIENTATION

FIGURE 1.



TERMINAL STRENGTH - LOAD ORIENTATION

FIGURE 2.

16 18


REVISED

▽ BS-F2VC-9F924-AA

NUMBER

3713 9664

Engineering Specification




TEST FIXTURE PORT CONFIGURATION
FIGURE 3

17	18	REVISED		▼ ES-7270-97924-MA
FRAME	OF			NUMBER
MAY PD 3947-52 Previous editions may NOT be used				

3713 9665

Engineering Specification



**DEACTIVATE SWITCH
TEST SET UP**

FIGURE 4

FRAME	18	18	REVISED		NUMBER
-------	----	----	---------	--	--------

TM PD 3947-a2 Previous editions are NOT to be used

3713 9666

378 COLD WORKING OF METAL




Figure 13.16 Die hob producing a mold cavity by pressing into soft steel.

sary hardness and strength to withstand the tremendous pressures involved. Pressing the hob into the blank requires much care, and frequently several alternate pressings and annealings are necessary before the job is complete. During the hobbing operation the flow of metal in the blank is restrained from any appreciable lateral movement by a heavy retainer ring placed around it. The actual pressing is done in hydraulic presses having capacities ranging from 250 to 8000 tons (2 to 70 MN).

The advantage of hobbing is that multiple, identical cavities can be produced economically. The surfaces of the cavities have a highly polished finish, and no machine work is necessary other than to remove surplus metal from the top and sides of the blank. This process is used in producing molds for the plastic and die-casting industries.

Coining and Embossing

The operation of coining, shown in Figure 13.17, is performed in dies which confine the metal and restrict its flow in a lateral direction. Shallow configurations on the surfaces of flat objects, such as coins, are produced in this manner. Because special-type presses developing high pressures are required in this operation, its use is limited to fairly soft alloys.

Embossing is more of a drawing or stretching operation and does not require the high pressures necessary for coining. The punch is usually relieved so that it touches only the part of the blank that is being em-





Figure 13.17 Illustrating the difference between coining and embossing.

y by pressing into soft
y
e tremendous pressures in-
quires much care, and frequent
adjustments are necessary before
controlling the flow of metal.
able lateral movement by
tional pressing is done in h-
to 250 to 8000 tons (2 to
1000 kg/cm²).
ile, identical cavities can
cavities have a highly
ary other than to rem-
blank. This process is
casting industries.

13.17, is performed in
low in a lateral direc-
it objects, such as coins
pe presses developing
use is limited to func-

ing operation and de-
molding. The punch is
the blank that is be-

Figure 13.18 Rotary embossing.



Review of Crimp Marks

1975/76

1335 12/1/91

1338 - 2

1331 - 2

2032 2/1/92

2031 3 0071453817

2039 2 0071207545

2029 2-3 0071247026

2036 3 0070809793

2038 2 0070277916

2122 - 5/1/92

2119 8 0069637210

2119 8 0071138055

2119 8 0070750725

2126 5 0071849397

2127 8 0071611873

2126 8 0071461942

2119 7 0071138055

2214 8/1/92

2224 7 0069543732

2209 7 0070388015

2209 8 0071609108

2205 8 0071051227

2235 8 0069327915

2238 8 0071467428

3713 9669

Review of Climp Marks

1993

None to review

1994

40 SHTS 100 SHTS 200 SHTS	40142 22-142	4054	4	0069622917	<Large Lettering>	AA
		4144	34	0071188125	"	AB
		4154	3	0070603030	"	AA
		5278	2	0070609743	"	AA

1995

1996

6095	8	0069386444	"	AA
6300	7	0070677645	"	AB
6131	7	0070683189	"	AB

1997

817	8	0071249515	"	AB
-----	---	------------	---	----

(All Same)

1998	8	0070667366	"	AB
------	---	------------	---	----

Review of Crop Marks

12/16/86

3

2068 - 2071 Container

2069 - 2 0070783457

AB

2069 - 3 0071080302

AB

2105 to 2106 Container

2104 2 0070558590

AB

2104 2 0070694119

AB

④ 2107 & 2113 Container

2108 2 0071250724

AA

2112 3 0070839517

AA

2113 3 0071092729

AA


2112 3 0070839517

AA

2113 3 0071093883

AA

Picture



3713 9671

Review of Crimp Dates 1/16/00

2117 - 2120 Container

2119 - 8 - 0070750728 AA
2120 - 8 - 0069403715 AA
2119 - 8 - 0069637210 AA
2120 - 8 - 0071303819 AA

2128 - 2130 Container

2128 - 8 - 0070863477 AB
2128 - 7 - 0070139003 AB
2128 - 8 - 0069327348 AB
2128 - 8 - 0071324112 AB

2135 - 2137 Container

2137 - 7 - 0070335588 AA
2137 - 8 - 0071287875 AA
2137 - 8 - 007128951 AA
2135 - 8 - 0070915519 AA

2149 - 2155 Container

2150 - 7 - 00711581247 AA
2153 - 8 - 0070855626 AA
2155 - 8 - 0070855626 AA

Review at Camp

1/10/00

2198 - 2211 Container

2209 - 8 - 0071850624 AA

2209 - 7 - 0071396342 AA

2205 - 7 - 0070775203 AA

2205 - 7 - 0070436563 AA

2240 - 2253 Container

2248 - 7 - 0070338358 AA

2240 - 8 - 0071470980 AA

2248 - 8 - 0070663762 AA

2240 - 8 - 0070141411 AA

2261 - 2267 Container

2262 - 7 - 0069320998 AB

2262 - 8 - 0071547691 AA

2266 - 8 - 0071504333 AB

2262 - 6 - 0071123349 AA ("Rusted")

2275 - 2281 Container

2281 - 8 - 0071139424 AB

2278 - 8 - 0071646899 AB

2278 - 8 - 0071200824 AB

2281 - 8 - 0070910807 AB

2281 - 8 - 0071430039 AB

3713 9673

Review of Camps

1/10/08

3

2282 - 2309 Container

2287 - 7 - 007063/761 AB

2287 - 7 - 0071813214 AB

2338 - 2366 Container

2352 - 8 - 007142 6395 AB

22-141
22-152
22-153

3713 9674

Robert Panek

From: Reimers, Steve (S.J.) [sreimers@ford.com]
Sent: Tuesday, December 14, 1999 12:01 PM
To: Robert Panek (E-mail)
Subject: Pre-Crimp Inspection

Rob,

I would like Exponent to do a non-destructive examination of the pre-crimp

witness marks on one Brake Pressure switch from each of the following dates (as close as possible):

12/1/91 - 1335

2/1/92 - 2052

5/1/92 - 3132

8/1/92 - 3214

1993

1994

1995

1996

1997

1998.

As you may recall when we were disassembling parts we noticed a difference

in the pre-crimp witness marks.

We would like to find out when these marks appear or disappear.
The pre-crimp marks are visible from the hexport and just inside the aluminum cup edge.

thanks,

Steve Reimers
VAT EMEC Chassis E/E Systems
313 39 03286, fax 313 39 04145

3713 9675

BROWN McCARROL & OAKS HARTLINE, L.L.P.

**111 Congress Avenue, Suite 1400
Austin, Texas 78701-4043
(512) 472-5456
(512) 479-1101 - Facsimile**

1300 Wortham Tower
2727 Allen Parkway
Houston, Texas 77019-2180
(713) 529-3110
(713) 529-6195 - Facsimile

220 Energy Center
1127 Julian Road
Longview, Texas 75606-3999
(903) 236-9999
(903) 236-8787 - Facsimile

340 Crescent Court
Suite 1400
Dallas, Texas 75201-4929
(214) 939-6100
(214) 939-6179 - Facsimile

July 14, 2000

(512) 479-9761

FAX COVER SHEET

TO:	NAME: COMPANY: PHONE: FAX NO.:	Doug Lampe FORD MOTOR COMPANY (313) 844-4111 (313) 845-3486
TO:	NAME: COMPANY: PHONE: FAX NO.:	Robert Panek Exponent - Failure Analysis (248) 324-8100 (248) 324-9199
TO:	NAME: COMPANY: PHONE: FAX NO.:	Fred Porter FORD MOTOR COMPANY (313) 845-3722 (313) 390-4145
FROM:	NAME: USER ID: TOTAL NO. OF PAGES: CLIENT/MATTER NO.:	Jeffrey C. Maniske 6587 3 13486.94658

THIS FACSIMILE MESSAGE IS PRIVILEGED AND CONFIDENTIAL COMMUNICATION AND IS TRANSMITTED FOR THE EXCLUSIVE INFORMATION AND USE OF THE ADDRESSEES. PERSONS RESPONSIBLE FOR DELIVERING THIS COMMUNICATION TO THE INTENDED RECIPIENT ARE ADVISED THAT THIS COMMUNICATION MAY NOT BE COPIED OR DISSEMINATED EXCEPT AS DIRECTED BY THE ADDRESSEES. IF YOU RECEIVE THIS COMMUNICATION IN ERROR, PLEASE NOTIFY US IMMEDIATELY BY TELEPHONE AT 512-472-5456, EXT. 2613.

Completed By: _____

Date: _____

Time: _____

Brown McCarroll & Oaks Hartline, L.L.P.

ATTORNEYS AT LAW

111 Congress Avenue, Suite 1400, Austin, TX 78701-4043

Phone 512-472-5436 • Fax 512-479-1101

July 14, 2000

Writer's Direct Number:
(512) 479-9761**VIA FACSIMILE**

Mr. Johnny W. Carter
Swanson, Godfrey, L.L.P.
1000 Louisiana, Suite 5100
Houston, TX 77002

Re: Cause No. 35650-S; [REDACTED] vs. Ford Motor Company, et al.; In
the 329th Judicial Court of Wharton County, Texas

Dear Johnny:

This letter is to confirm Texas Instrument's inspection of field returned brake pressure switch components on Monday, July 17, and Tuesday, July 18, 2000, beginning at 9:00 a.m. and concluding at 5:00 p.m. each day. The inspection will take place at the following facility:

Exponent
39100 Country Club Drive
Farmington, MI 48331

For your convenience, I am enclosing written directions from Detroit Metro Airport to Exponent in an attachment to this correspondence.

Ford has informed me that arrangements are being made to have a microscope available. Additionally, I have also been informed that the documents you have requested in earlier correspondence, as well as the computer disc previously discussed, will all be available to you at the inspection.

Upon arriving at Exponent, please ask for Mr. Robert Pausk.

If you have any questions regarding the above or the enclosed, please do not hesitate to contact me. I look forward to seeing you on Monday.

Until our next communication, I remain,

Very truly yours,


Jeffrey C. Manske

JCM:rlm
Enclosure
A28:HHR2001
1348.94681

3713 9677

Exponent
Failure Analysis Associates

Exponent
149 Commonwealth Dr.
Menlo Park, CA 94025

telephone 650-326-9400
facsimile 650-326-8073
www.exponent.com

F A X C O V E R S H E E T

To:	<u>Sarah A. McLaren, Esquire</u>	<u>248-258-0421</u>
	Name	Fax
	<u>Feeaney, Kellett, Wiener & Bush</u>	<u>10-27-00</u>
	Company	Date
From:	<u>Bruce Ketcham</u>	<u>248-324-9118</u>
	Name	Telephone
	<u>Managing Engineer</u>	<u>248-324-9199</u>
	Title	Fax
Draft Supplemental Protocol & Data Form		
Subject:		
3	<u>bketcham@exponent.com</u>	
Total pages including this page.	<u>E-mail</u>	
If you do not receive all of the pages indicated, please call _____		
at () _____ as soon as possible.		

PLEASE NOTE: The information contained in this facsimile transmission is intended to be sent only to the stated recipient of the transmission. If the reader of this message is not the intended recipient's agent, you are hereby notified that any dissemination, distribution or copying of the information contained in this facsimile transmission is prohibited. You are further asked to notify us of the error as soon as possible at the telephone number shown above and to return the facsimile documents to us immediately by mail at the address shown above. Thank you.

SPECIAL INSTRUCTIONS:

Sarah:

As discussed.

Bruce

Exponent

DRAFT

October 27, 2000

Brake Pressure Switch Disassembly Protocol – Supplement

For each previously disassembled brake switch:

1. Remove the three plastic bags containing the three kapton diaphragms from the plastic bag that contains the disassembled switch components. Remove each bag and open the petri dish that contains the kapton diaphragm. Remove the kapton layer from the petri dish. Use a micrometer¹ to measure the thickness of the kapton diaphragm at the three unmarked diaphragm corners. Record the measured thickness and the measurement location relative to the marked corner with the mark facing outward and positioned at 12 o'clock. Return each kapton diaphragm to its respective petri dish, recover the dish and place in its plastic bag and return to the plastic bag for the respective switch.

¹ Mitutoyo 0-1" Micrometer, No 293-765-10, Serial Number 2392940, Calibration date 07/28/2000.

DRAFTExponent
Date of Inspection: _____

Inspected by: _____

Data Form for Examination and Disassembly of Brake Switch - Supplement

Long Tag Number: _____

Measurement Position	Measurement (in)
----------------------	------------------

3:00 o'clock	_____
6:00 o'clock	_____
9:00 o'clock	_____



Attorneys At Law

Austin • Dallas • Houston • Longview • Round Rock • The Woodlands

FAX COVER SHEET

AUSTIN OFFICE

111 Congress Avenue

Suite 1400

Austin, Texas 78701-4043

(512) 479-1101 (FAX)

(512) 479-8781

TO: Fred Porter
Company: Ford Motor Company
Phone No.:
FAX No.: 313/390-4146

FROM: Jeff Mankos
User ID: 8698
Client/Matter No.: 13486.94858
Total Pages: 35

DATE: December 15, 1999

Confirmation Receipt Required Yes No

MESSAGE: Please review the attached and contact me.

This facsimile message is PRIVILEGED and CONFIDENTIAL attorney-client communication and is transmitted for the exclusive information and use of the addressee. Persons responsible for delivering this communication to the intended recipient are admonished that this communication may not be copied or disseminated except as directed by the addressee. If you receive this communication in error, please notify us immediately by telephone at (512) 479-8486, ext. 2813.

Compiled By: _____ Date: _____ Time: _____

39100 Centri Club 298-329-7112

FH 48337

 Bob some water went down
 and mine. *[Signature]*

HIGHLIGHTS
 Stephen B. Offner
 Week Ending 91-08-16



FORD MY'92 ELECTRONIC SPEED CONTROL DEACTIVATE PS.

VALIDATION:

The Thermal Cycle test was successfully expedited in order to begin the important Impulse test as soon as possible. Half of the Impulse test is run on virgin devices, and the other half is to be run on parts which have completed the Fluid Resistance test. We are now running the virgin Pass Car and Light Truck parts simultaneously. A significant problem is occurring on the PC devices. We have had three failures to date (325K of 500K) due to fluid leakage. Autopsy of two (thus far) shows fatigued Kapton; no real evidence of foreign matter nor damage to the Kapton during assembly. Stan Hospol is providing valuable assistance in failure analysis. Note that we are running AMI-built PC and LT side-by-side, with no failures of the LT parts, which is directing F/A toward the cap. We are continuing to run the test for two reasons: one, to attempt to complete the LT parts successfully; and two, to continue to fail PC parts to provide additional F/A clues. Hypotheses include: increased connector travel in the robust design; extraordinarily tight sensor crimp as evidenced by the deformations where the Kapton layers overlap; very flat washers (unlike the norm, which is slightly cup-shaped) which may also contribute to tight crimp. We are giving this crimp top priority. At this point, it is safe to assume that the PC parts presently undergoing Fluid Resistance will also fail on Impulse. This means that after the problem is corrected, at the very least the Fluid Resistance test will need to be re-run, or at worst the entire validation will have to be rerun from scratch, which is about a nine-week process either way. We are now trying to determine how to best approach Ford with this news.

MECHANIZATION:

Mechanization has performed repeated measurements on the three AMI gage blocks and three switch assemblies, and Jeff has performed exactly the same measurements manually. The AMI calibrator (measure-only mode) and the check station produced commendable sigma's, although lack of agreement between the two requires more effort to understand. Jeff's measurements produced sigma's slightly worse than the automatic equipment. The good news is that it appears that a very good correlation exists between Jeff's manual measurements and the check station. We are planning a "pre-effectivity run" (a.k.a. "final debug run") of a few hundred switch assemblies, collecting all data on each piece and identifying each individually for later analysis. This will provide a statistically significant number of parts for check station vs. Jeff correlations, as well as allow Pareto analysis of problems which occur during the run.

Dave Paxpoll has spent quite a bit of time working on the riveter on the Eastern Automation equipment. At present, we've got a hybrid of Milford and Thompson riveter parts, which seem to be running fairly well. However, for the long-term Mechanization is looking into elimination of the rivet. We are working with an ultrasonic welding firm, Supla, who has provided very impressive samples. I am meeting with them today to provide actual springs and movable terminals, so we can do actual in-process performance and life tests.

Progress on the above items is presently impacted by lack of materials. We have 27K moveables and 45K stationaries from Basler which were rejected for encapsulation. The sticky green substance has been identified as the environmentally-friendly cleaner/waxproofing product (Imron 119) that Basler used to remove the EF stamping late (Imron 185).

919000 - New Number

OXYLIC ACID? —
CONTENT?

NOT LIKELY per
TI-003600

CSL

SR

IRMCO MSDS MATERIAL SAFETY DATA SHEETS

HIGHLIGHTS 910816**Page 2**

Apparently he is not drying and/or removing this product correctly. Rick B. has determined that a phosphoric-acid tumbling product he uses regularly In-house will remove the green stains. We are having him expedite this cleaning process so we may continue with riveter work and the pre-effectivity run.

MISCELLANEOUS:

We have finally received the correct mating-connector terminals and wedges from UTA. The confusion was caused in part because this is a brand-new design and is not properly documented yet; additionally the correct individual who has knowledge of this product was out sick..

The hexport samples in 10B21 material have arrived. One has been sent to TSL for analysis of hardness, in the same fashion as done previously for a 10C10 part. This will allow direct comparison, in order to determine if the 10B21 is actually significantly harder. These parts, without re-toll, gaged very well - however, they were not plated in a 5K batch size, and they were packed individually for shipment. The hardness results, along with the quote, will help determine whether we will proceed with a full plating lot (5K).

TI-003601

MILITARY
SPECIFICATIONS

HIGHLIGHTS
Stephen B. Offiler
Week Ending 91-08-23

FORD MY'92 ELECTRONIC SPEED CONTROL DEACTIVATE PS

Factor 1
Factor 2
control
series 1 2
3 4

VALIDATION:

Light Truck 77PS devices have successfully completed the first phase of Impulse testing, including 475K mechanical cycles and 25K powered cycles.

The AMI-built Pass Car devices on this same test were aborted at 389K cycles, with 8 of 12 failed due to ruptured Kapton. One hypothesis explored was that the Pass Car converters travel farther than the standard design (due to different disc support bump location in the cup), which results in additional strain on the Kapton. This was substantiated with converter force/deflection measurements done on Pete Sampson's equipment. We calculated that the standard design travels .017" at 1450 psi, while both the model shop and production rebump design travels .023". However, previous validation work on 57PS using the model shop rebump cup on the hand-line did not show any Kapton problems. We are now running a matrix test, with two variables: rebump cup, model shop or production; and crimp technique, AMI or hand-line. The control lot, hand-line model shop rebumps, was taken from the original 57PS CCPS validation, and therefore should pass 500K as before. The test lot, AMI built production rebumps, is taken from the present 77PS validation lot and is expected to turn up failures beginning around 270K. The opposite diagonal of the matrix, AMI-built model shop rebumps and hand-line production rebumps, have never been run before and will help identify which test variable is the major contributor to failure. The plan is to run the test until sufficient failures have occurred in all four lots. Weibull and autopsy will be used to analyze the failures. Due to the extreme priority given to this test, plans are being made to have the test monitored throughout the weekend. I will come in early Sat. AM and noon Sat. Jeff will come in Sunday AM, and I will come in again Sun. PM. When failures are found, they will be removed, the manifold plugged, and the test restarted. Weekend monitoring should allow completion of about 400K cycles by Monday morning, and should turn up significant failures of the test groups which may allow initial conclusions well before all devices ultimately fail.

As yet, we have not decided how to approach the customer with this issue. Kelsey-Hayes is somewhat aware that we are having a problem, because they have requested a quantity of 150 77PSL2-1's by 91-08-30 for DVP&R testing, we have been forced to inform them that these may be delayed. If we miss the given date, they will bring this issue to Ford. The plan is to develop a strategy on Monday once we have initial information from the failure test.

MECHANIZATION:

Eastern Automation spent two days here this week, working on the contact feed/kinetic system. Apparently this design is very flimsy, but does work okay when dialed in. The riveter has been acting up again; it seems that every time one problem is fixed another one occurs. This equipment is causing significant delays to the planned effectiveness runs and the pre-effectiveness run. The pre-effectiveness run of about 250 ps is very important from a design standpoint, since we plan to collect all calibration and check-station data for every single part, as well as every machine malfunction, and use this to Paretoize problems; establish check/cal/manual correlations, etc. It is unclear at this point when we will be able to perform the pre-effectiveness run, although we are now several weeks late and the priority is very high.

3713 9684

T1-003602

HIGHLIGHTS - 910823 - PAGE 2

HEXPORT:

We had a conference call this morning with Elco specifically relating to one of the points raised in Steve Fulton's letter, regarding thread condition and reroll. Steve points out that ANSI B1.1 allows a plus 2A thread additional allowance in pitch and major diameter, such that the no-go gage used is still 2A but the go gage is 1A. The difference here is an additional 1.1 mils on the high end. Also, SAE JS12 specifically states that the additional allowance applies, and invokes ANSI B1.1. This fact should significantly help in our negotiations with the customers to approve this change. Also per ANSI, if this additional allowance is unacceptable for various reasons (lubricant or sealant clearance required in threads, or very high temperature service where expansion is an issue) then the thread designation on the print must include a "G", for example: 3/8-24-UNF-2AG. Of course, our print does not have the "G" which basically means we are at liberty to inspect per the relaxed ANSI spec. I checked 10 parts which were unacceptable on the 2A go gage, and found 8 of them to be okay on the 3A gage, the other two being marginal and requiring use of the 4.5 in-lb torque technique for arbitration. I believe that this additional tolerance, combined with one of the other ideas presented in Steve's letter (harder material and/or slightly reduced plating thickness) will be sufficient to eliminate the thread reroll and reduce thread rejections to near zero.

E74
5985

TI-003603

HIGHLIGHTS

Stephen R. Oliver
Week Ending 91-08-29

9/10/91




FORD MY'92 ELECTRONIC SPEED CONTROL DEACTIVATE PS

VALIDATION:

The matrix test designed to help identify the cause of early Kapton failures in Pass Car devices is well underway. This includes production caps built on AMI and hand-line, and model shop rebooms built on AMI and hand-line. All AMI-built parts are dead, with production caps ranging from 307K to 504K, and model shop caps ranging from 541K to 861K. Half of each of the hand-line lots are also dead, with production caps beginning to fail at 830K, and model-shop caps at 790K. The test is presently a few hours shy of one week in length, with about 1.1KK cycles to date made possible by significant efforts during and after regular work hours. These results are definitely pointing to the crimp method as the primary contributor to failure, with the cap style a secondary factor.

A second matrix has been placed on this test in parallel, although these are 790K behind the first matrix. This is testing the influence of pre-crimp, since the AMI uses pre-crimp and the hand-line does not. Devices with (control) and without pre-crimp were built on AMI, and a lot with pre-crimp was built on the hand-line. No failures yet.



Devices using pressure-sensitive paper between the Kapton and the washer were built both on the hand-line and the AMI, with and without pre-crimp. Definite differences are apparent between AMI and hand-line, but no difference attributable to pre-crimp. The AMI parts show generally less pressure applied, while the hand-line parts show higher peak pressures in the Kapton area and, significantly, evidence of washer/hexport touching which is absent on AMI. This is further supporting evidence that the hand-line crimp is deforming (plastically) the washer and/or hexport such that the effective Kapton clamp diameter is moved outward, allowing more effective Kapton area to react to the strain of converter motion. Planned cross-sections will help to justify this hypothesis.

MECHANIZATION:

We were able to complete our first pre-effectivity runs yesterday. Small lots were run to develop a correlation between the manual measurement and the check station, which proved to be quite good, with an offset of only about 0.6 mils. Next, a quantity of 57 devices were built, individually serialized, and manually measured for comparison with printed calibration and check station data. 42.1% were good based on manual measurements, and were called good by the machine. 21.8% were junk for various reasons such as stripped or missing components. 15.8% were good but called bad by the machine. Most of these fell outside the correct calibration window, yet manual and check station measurements found them to be good. Given the excellent correlation of the check station, I have proposed that the software be modified so that anything found good by the check station will be considered good. This will alleviate most of the subtle "good parts called bad" and significantly increase yield. Another 15.8% of the parts were bad and were called bad. Most of the problems here are related to abnormal spring geometries which cause erratic correlation between the calibrator and check station, resulting in a part calibrated correctly but failing check. Finally, 3.5% of the parts were found to be bad, but called good by the machine. These are mechanical issues which can be corrected easily with addition of sensors, etc. It is very important that this be accomplished, given the severe consequences of a bad part which is allowed to be built into a finished device. Next, we plan to run the AMI's to build 150 customer samples urgently needed by Kelsey-Hayes. We are in a good position to accomplish this.

TI-003604

- results - + H + testing?

HIGHLIGHTS
 Stephen B. Offiler
 Week Ending 91-09-06

FORD MY'92 ELECTRONIC SPEED CONTROL DEACTIVATE PS

VALIDATION:

Results of Kapton lifecycling to date are as follows. Given the Weibull beta's and theta's for each test lot, reliabilities have been calculated for 500K cycles.

<u>Rel @ 500K</u>	<u>Configuration</u>
99.85%	Prod. cup, Hand line crimp, with AMI precrimp
99.77	Prod. cup, AMI crimp (built 910828)
99.26	Prod. cup, Hand line crimp
97.63	Model shop cup, Hand line crimp (9010xx validation)
96.75	Prod. cup, AMI crimp without precrimp (910828)
94.81	Model shop cup, AMI crimp
14.69	Prod. cup, AMI crimp (built 9107xx for PC Val.)

Notably, the lot of standard PC production parts recently built on AMI as a control lot (#2 above) turned out to be very significantly different than the failed validation parts. The hand line crimp displays some slight advantage over the AMI crimp, and the presence of precrimp also displays an advantage.

We plan to get Light Track parts, built in July along with the failed PC parts above, on test ASAP. The reason for this is because these parts are now also suspected to have reduced life. One of the LT parts which recently passed Impulse testing was found to be wet inside; it was very close to failure which would have stalled current LT validation progress. Understanding the characteristic life of these LT parts built in this timeframe may shift the focus away from the increased PC converter travel, and towards either component parts or a production problem, which has since been corrected.

We are also testing new lots of PC parts which are designed to modify converter travel. One lot actually decreases travel by preloading the slide, hence shortening its throw. The other lot raises the converter relative to the washer, such that the total travel is the same, but is shifted up so at maximum travel the flexure of the Kapton is similar to a LT part. Yet another control lot is included with these parts.

It has been decided to go ahead and rebuild PC validation parts now, even though the cause of the early failures has not been identified and corrected yet. PC control lots built recently are displaying very good life. We plan to get these parts onto the cycler by the end of the day today, which will allow them to reach 500K roughly mid-day Tuesday if all goes well. During build of these sensors on AMI, we also ran a couple of parts with pressure-sensitive film. The pressure traces on these looked essentially identical to the ones that were taken during the previous AMI build (the one that produced excellent life). We hope that a similar crimp pressure will mean a similar life expectancy.

Another significant tool for solution of this problem is the cross-sections of the original failed parts and controls. However, we have not received the parts from TSL yet, and Paul Sherman has not returned my calls.

doctor - ? station enabled ? station enabled

TI-023605

Robotrand - 14443 chassis returning in July

DEC 15 '99 10:15 AMI chassis return in July 231 292 7423

PAGE.87

HIGHLIGHTS - 910906 - Page 2

S.W.
Chav**MECHANIZATION:**

We have proposed that the control software on the switch AMI be changed such that the check station is the final arbitrator of a "good" part. This is because we have demonstrated excellent correlation between the check station and the real world. Presently, a part bad on either cal or check will be called bad, decreasing yields if cal is bad but check is good. Before Mech. will make this fundamental software change, they'd like to see effort placed on understanding the differences between the calibrator and the check station.

Russo H

We have begun to experiment with the system of weights on the calibrator in order to try to close the gap in correlation between it and the check station. A quick-and-dirty experiment was conducted, using a limited selection of poorly-fitting weights. We did discover that additional weight over the transfer-pins area seems to close the correlation gap slightly. We also noted that the check station itself is running commendably well, with sigma's on repeated measurements of the same part running in the range of 0.06 - 0.14 mils. See MSG #182281 for a complete discussion.

W.L.A.
461.Page
Sequence
Error
this
part

TI-003606

*This P-1C
out-of-sequence!*

HIGHLIGHTS
Stephen B. Offner
Week Ending 91-09-27

*9/17/91
9-09-27*



FORD MY'92 ELECTRONIC SPEED CONTROL DEACTIVATE PS

VALIDATION, PASS CAR:

Test reports were finalized late last Friday, and fax'd to Joe Schuck in preparation for a call first thing Monday morning to Bruce Pease to solicit his support for a conditional ISR. Because he was about to leave on business for several days, he asked us to approach his supervisor, Bruce Maeroff, with a concise explanation of the situation. Apparently Mr. Pease did not prepare Mr. Maeroff, because the deviation from procedure, using head-line bulk parts without Fluid Resistance testing to pass Impulse, has caused quite a commotion. Joe is very critical of our reluctance to approach Ford up-front when the problems began. At this point, SQA Mark Scholler has asked for Bruce P. to write an "alert" at which point Mark will enter a 90-day extension. We'd like to understand Ford's position relative to holding us to only 90 days, because this simply might not be enough time to get the Kapton rupture issues cleaned up to Ford's liking, which includes at least a re-run of Fluid Resistance and Impulse. A complete explanation of the Kapton issue has been forwarded to Joe, to arm him with more facts for use in dealing with Ford.

VALIDATION, LIGHT TRUCK:

A different set of problems to deal with in Light Truck. Here, salt-spray failures occurred which were attributed to the existing connector. Our validation was run with EPC connectors, which are an older design and not very robust. This has raised questions such as which connector LT actually plans to use, which we do not know. They may in fact choose (-or have chosen) the UTAG connector, which we used successfully on Pass Car. We have tried to claim similarity in the ISR wrinkle, which at this point has not been well received. There has been talk of re-running the whole thing with UTAG connectors, which is ridiculous.

KAPTON LIFE:

Cycling of the various test lots continues. At this point, we have, generally, 4 or more failures of 6 in each lot, enabling decent Weibulls to be calculated. For the modified-converter-travel lots, we have learned that there is no difference between the control lot, the lot with .006" reduced washer to raise the converter bump, and the lot with .005" stepped washer to pre-deflect the disc and limit travel. All three have Beta's between 4.4 and 5.1, and Theta's between 1073 and 1142. Note that these AMI-built parts actually performed atypically well in terms of characteristic life (Theta), although Beta's are typical. For the lot with the stepped bi-point to "raise the Kapton clamp diameter outward", we found the test lot significantly worse than the control lot. The Beta & Theta for the control lot was 4.0 & 711, versus 2.8 & 573 for the test lot. Maybe we actually need to bring the clamp diameter inward, as Stan Hoorn has suggested. We're also analyzing the head-line bulk Pass Car validation parts, and have found a Beta of 7.2 and Theta of 1080, very typical numbers for head-line product (compares with 4.0 and 1133 previously).

Presently, we have on test the AMI-built validation attempt which was run in Stan's cycler at reduced pressure (different parts from same lot), and two lots of parts being run to support production. These two lots are part of a 1300-pc Pass Car lot accidentally built on the AMI, and we are now cycling them to determine if they are, by chance, actually good. We have six straight off the AMI, and another 6 which were crimped on AMI then crimped again on the blind-line, which may expose a potential salvage technique.

71-003610

HIGHLIGHTS

Stephen B. Offiler
Week Ending 91-09-20

FORD MY'92 ELECTRONIC SPEED CONTROL DEACTIVATE PS**VALIDATION:**

Rough drafts of both the Pass Car and Light Truck ISR reports are complete; final reports are being slightly delayed by the Humidity test. This should have completed yesterday (Thurs.), however, the chamber in ETL was hit by an electrical disturbance during a thunderstorm Tuesday night and shut down. We had completed three full cycles at this point, so another seven were required after re-start. This will complete this afternoon at 4:30pm. Jeff has been scheduled to work until 6:30 tonight to finish final characterization on these devices so the reports can be finalized.

Unfortunately, problems occurred in both the Car and Truck devices during the testing; the ES states "all devices must pass." Car is worse, due to the significant difficulties encountered with Kapton life, and the reaction plan which finally led to running 24 manual-build devices on an emergency test without any initial characterizations and without subjecting 12 to Field Resistance. It is likely that Pass Car will grant conditional approval at best, or no approval at all, until we straighten out the Kapton problems and re-run the test "by the book". Problems encountered with Truck are much less severe, and hopefully will not prevent approval. The difficulty we had was salt spray failures, where 4 of 6 devices filled with salt solution which caused extremely high current leakage. However, careful scrutiny of these devices showed the leak path was via the mating connector, and we have blamed the design of this connector in the writeup.

We plan to fax the final versions of the reports to Joe Schuck so he may prepare for telecon's with Bruce Pease and John Pelkey on Monday morning. The aerosol finished product will be bound in TI Test Report standard format for inclusion with the rest of the ISR package, and shipped early next week.

KAPTON LIFE:

Now that the CCP3 cycler has been freed up by completion of validation, we plan to conduct with the various test-loops for Kapton failures. Testing includes devices with limited converter travel (via modified washers); devices with modified exports to control Kapton glumping and move it outward; and devices with switches versus without switches, which the data strongly suggests as a variable.

NOTE: *...NET*
...ADDITIONAL PARTS
...*...NET*

SPRING AND STATIONARY TERMINAL BREAKAGE:

When Q.C. ran their QAS pilot test procedure on LT 77's off of the effectiveness runs, spring breakage was noted on parts cycled at 640/min on the production cycler. This had never previously been an issue, although until this time all parts have typically been run only in the CCP3 cycler at under 130/min. A comparison test was started, using parts picked at random from the effectiveness runs, running on the production cycler and the CCP3 cycler in parallel. This time, the production cycler turned up not only broken springs, but also broken stationary terminals. Parts on the CCP3 cycler have not been completely analyzed, but we do not suspect any problems with these parts. We've cut windows in a couple of devices and took high-speed video of the spring action on both cyclers. This footage will be analyzed as soon as possible to attempt to determine the differences between the cyclers. As far as stationary

TI-003608

HIGHLIGHTS - 910920 - Page 2

A inspect J-4
that may not
be present in
it?
or S?

Control plan?

SAMPLES:

We had an order for 12 parts for Ford Australia which was due to ship on 910917. However, correspondence via fax with the brake engineer, Brent Franks, made it clear that an M10 x 1.0 thread is required. Previous samples used M10 x 1.25, and we have no hexports with the correct thread. I sent a lengthy memo to Brent, copying TI Australia Field Sales and Engineering, explaining the confusion over the thread spec and the schedule slip it has caused. At this point, we need to have hexports made on CNC lache in order to complete the order.

We have received an urgent request from Hillie Industries / Pitts' head of purchasing for 300 Pass-Car 77's for their validation. They want these devices next Friday. We should be able to meet this need if we crimp sensors on the manual line and correct the problems with the springs and stationary terminals.

Result

111-674
1656

TI-003609

HIGHLIGHTS - 910927 - Page 2

Mfg. Eng. has exposed a key piece of information in the crimp puzzle. Actual pressure-transducer measurements of the crimp cylinder pressures has shown that the AMI was running significantly lower in pressure on both stages of crimp. This data was collected before some maintenance (cleaning filters, etc) was done on AMI, so the plan is to repeat the measurements to obtain the present status. Furthermore, a test is planned by Mfg. Eng. with our support where devices will be built with pressures on AMI at lower values, and at values matching the hand-line. Controls will be built on the hand-line as well. These will be cycled to failure in our cycler for direct comparison with all previous data, as soon as manifold positions begin to open up early next week. We also plan to build a couple from each lot with Fuji pressure-sensitive film.

MECHANIZATION:

Mfg. Eng. and Mechanization have spent significant efforts to correct the problems noted with the EA and the AMI. This includes the spring-bending tool, which was leaving score marks, bending to an insufficient angle, and the bottom die was found to be chipped. On AMI, the cutoff stations for both terminals have been upgraded to ensure that asymmetric cutoff cannot occur, which combined with a new, lower calibrator target should help avoid broken stationary terminals. We plan to begin testing with devices calibrated .005 lower and using the corresponding pin (.146 -.005 = .141).

The Final Arm Machine and the pressure tesser have been moved from B20 to B12, and are presently being set-up and connected to utilities. The Base Arm Machine and the EA machine are in the process of being moved. It will be several days before we can even power-up the machines, at which point several more days will be needed to get them back to their status before the move.

SAMPLES:

The schedule for the 300-pc lot of 77PS's requested by Plus for ISR work has been successfully moved forward by Marketing, pending the correction to the base mold, which also co-incides with the completion of the machine move. They are expecting parts around 911007.

For the Ford Australia samples, I have updated the metric hexport dwg EX3423-61 to include the correct thread, M10 x 1.0 - 6g. I have also reviewed the ISO tolerancing technique and calculated the correct pre-plans major and pitch diameters for the thread, which have been placed on the print. The specified 6H (internal) and 6g (external) thread tolerances correspond with our 2B and 2A respectively; while the metric standard actually provides about 13% more tolerance. The EK has been forwarded to Mike McHugh for creation on the CNC lathe.

771
962

TI-003611

HIGHLIGHTS

Stephen B. Offiler
Week Ending 91-10-04

✓
10/14/99



FORD MY'92 ELECTRONIC SPEED CONTROL DEACTIVATE PS

INITIAL SAMPLE REPORT (ISR):

Conditional approval has been granted at Pass Car; Bruce Pease has written a 90-day "alert" which means we must complete full ISR in this timeframe. Basically this means correction of the problems which led to early Kapton failures, and a re-run of some (or all) of the ES tests. If the correction is simple and straightforward, then it is likely we'll only need to submit Fluid Resistance and Impulse; whereas if significant process or design changes are made, we'll need to do the whole thing. Timing, of course, is absolutely critical, since our 90-day period (911002 thru 911231) is effectively shortened because it encompasses both holidays. Bruce has asked for a detailed action plan ASAP, which is in the works. Before submission to Bruce we will review this plan formally with Design, Mfg. Eng., Mfg., Quality, and MCL. The rough outline shows that regardless of which tests we run, we must have the final parts built on Wed. 911030, three and a half weeks from today.

The Design FMEA was completed on a very high priority basis last weekend for review with Mark Scholler (SQA) during Dave's trip last Tuesday 911001. Apparently our DFMEA technique/approach on this program (and others) is not pure Design; we seem to have a tendency to mix too much process in with it. Mark is being very helpful on this. We need to revamp the DFMEA and resubmit. Weekly FMEA meetings will recommence.

We are now expediting arrival of new, blue-colored environmental seals for Pass Car to replace the current ones, which have only a hard-to-find stripe mark for differentiation. We plan to file an SREA for these, and if all goes well, we'll build the above re-validation parts with these.

KAPTON LIFE:

Diaphragm life-testing of various experimental lots was suspended last Sat. 910928 due to hydraulic pump failure. The pump was removed from the cycler and hand-carried to an authorized service center in Warwick, RI. Repair was turned around in two days, and we are in the process of re-installing it in the cycler. Excellent job by Jeff D., Natalia in Purchasing, and Tri-Power Sales & Service. Since a failure of this nature can set critical testing back by a week minimum, we have decided it is wise to purchase a spare Enerpac unit which will be available for any of the cyclers (not just CCPS) in the event of failure.

We plan to run an experiment to test the hypothesis that air pressure in the AMI crimp heads was insufficient during the original (failed) validation build. We've taken a sample of pre-crimp-only devices directly off the AMI during a production run. The pressures will be ramped down to the lower level discovered recently to crimp one test lot; they will be turned up to match the hand-line to crimp the other lot. These will be cycled to failure and analyzed with Weibull techniques for comparison with other test-lots.

EXPORT:

Thread rejections continue to waste everyone's time. Most are written in-process, and end up being a gaging-technique issue rather than a true rejection. We are attempting to streamline the process by instituting a reaction plan whenever a potential rejection is discovered. Use of the 4.5 in-lb gage torque is the arbitrator if rejected on the GO gage.

TI-009612

HIGHLIGHTS - 911004 - Page 1

We are creating an evaluation plan for the 10B21 hexport samples. These have the potential to solve the thread problem because the thread is significantly harder (per actual DPH measurement) than current 10L10, hence damage during plating should theoretically be lessened. We will look at undergoing tests of strength (burst, stripping torque) and environmental resistance. We'll need to approach Ford with an SREA if all evaluations are positive. Also, we are expecting soon the full-plating-lot of reduced zinc parts (.00015 vs current .0003 min) which have olive-drab chromate to help regain some lost corrosion resistance. These spend significantly less time in the plating bath, and hence they theoretically are damaged less.

At some point, it is conceivable that we'll combine all of our thread efforts to produce a higher quality part. This includes the above 10B21 harder material, with thinner plating and olive-drab chromate, using the ANSI B1.1 gaging technique which allows 3A GO / 2A NOGO on plated parts.

SAMPLES:

Due to the move of the Mechanization equipment, we are presently unable to produce any parts. Efforts have been prioritized by Mfg. Eng. to correct issues with the Eastern Automation movable terminal equipment, then get the base asm. machine up, then last-but-not-least the final asm. This is likely to take about another week, including in-depth evaluations of the EA progress, cycled on the severe production cycles. This will put us behind schedule in shipping the 300-pc run for Pita.

I've discovered that the paperwork for the Ford Australia metric hexport samples was lost somewhere between the Model Shop and the CNC Lathe in Bld. 20. We are still a couple of weeks from shipping these samples.

TI-003619

15
1656
ET/MS

HIGHLIGHTS

Stephen B. Offler
Week Ending 91-10-11

FORD MYC92 ELECTRONIC SPEED CONTROL DEACTIVATE PS

INITIAL SAMPLE REPORT (ISR):

We have completed the detailed action plan for correction of outstanding ISR issues, and sent it via MSG (#165560) to Joe Schuck for relay to Bruce Pease. We have good confidence that the Kapton life can be improved via minor process upgrades/controls, since over the course of Kapton life testing we have seen numerous "control" lots which have demonstrated excellent life. The challenge remains to isolate the cause and eliminate/control it, and progress is being made.

KAPTON DIAPHRAGM LIFE:

Crimp pressures (i.e. the air pressure in each of the two crimp stages) remain the suspected primary cause of poor Kapton life. We are running a test of six lots of devices, built on AMI with known, consistent components, and crimped over a range of pressures from about 45/40 to 70/60. These will be cycled to failure beginning today and analyzed with Weibull techniques for comparison with previous test lots. This test should identify the correct crimp pressures to use.

We are also investigating secondary influences, specifically the washer. Of all internal components directly or indirectly affecting the Kapton, the washer is the only one which is built on several different tools and is therefore known to have the potential for geometric differences. Furthermore, we have learned from production operators that significant shifts in device characteristics can be obtained by changing washer lots. They sometimes use this fact to help control piloting. Parts hand-built by Jeff typically have no control over washer lot, so we plan to go back through our past experimental lots to check washers. Pending results of this investigation, we'll likely produce another set of test lots, varying only washer lot, with the inclusion of a Ni-plated lot. These will be crimped at a pressure which produces poor life, in the interest of obtaining comparative results more quickly.

Given our experiences with cyclic failures during the course of this investigation, we are looking into spare parts to allow rapid repair in the future. Jeff has discovered that the Baerpak hydraulic pump unit is around \$2300, and the Moog servovalve is around \$2500. The alternative to purchase of spare parts is to comprehend potential downtime delays. Failure of either causes a minimum delay of 4-5 days, potentially longer.

CUSTOMER ISSUES:

Tim Andreessen (Pass Car Brake Eng.) has requested a couple of silent 77's. We happen to have a couple of spare switches of this configuration already built. These will be shipped N/C to Joe for hand delivery to Tim.

We had a brief meeting with Dave Pollock of GM Powertrain Eng. They were here on a pitch capability business, but during the course of the meeting Dave learned of our switch capabilities and realized he had a potential application. Cadillac (Northstar) is working on an engine torque management safety system (an offshoot of traction control), which will reduce engine power if sensors determine the driver is on the brake and gas simultaneously. They are still trying to fix the pressure range, but Dave's gut feel is that a typical cruise-control-decelerate level is appropriate. During the informal 77PS line tour, he was particularly impressed by our base calibration technique requiring only one pin length.

3713 9695 TI-003614

52 7483

HIGHLIGHTS

STATION A: OFFICER
W/E 91-10-25

Jeff D.
91-10-25

KAPTON DIAPHRAGM LIFE:

As Jeff D. reported last week, the results of the aging pressure showed absolutely no influence on diaphragm life. We are now in the middle of the washer test, using O-cut Ni plate, O-cut Zn plate, and Z-cut Zn plate. The O-cut Zn seems worse than the other two, which are about equal, preliminarily. Failures in the latter lots began around 800K, so the washer is nearly a secondary variable.

Based on Carl Sanford's inputs, we tried lubricating gaskets (using silicone DOT-C brake fluid) to see if this would have any effect on the "tearoff" shape observed in the Kapton surface when the bearing is cut off a crimped device. Dry and lubed parts were crimped on H-L and Arms. Tearoffs were observed in most devices on dry Arms part and on lubed H-L part had no tearoff. Since essentially no difference was observed in any of the lots, we have no confidence that the tearoff phenomenon has any influence on Kapton life. We plan to go back to previous failed devices and cut off bearings to see if any further clues can be obtained using this analysis technique.

We have elevated the priority on the H-L vs Arms discussion, so we can get the parts cycling over the weekend. Jeff, Dave, Matt, and I will work together to get these test lots built today. A full matrix will be built: Arms built on both crimped and H-L tools on both crimpers. Jeff is hard cutting parts, using O-cut Zn washers. Matt need to bring Jeff in a couple times over the weekend to keep the test running.

SAMPLES:

I think we're finally straight on the Ford Australia samples, after a flurry of correspondence between Charlie and John Butler @ TI Australia. Well ship #2 TPS-1 will receive connectors and insulation kit for US\$25 each. Mike McHugh reported that a flight will be launched Oct 29. Flying should be completed by Nov 2, returning to ship Nov 4 if all goes well.

TI-003615

Jeffrey DiDominico
Weekly Highlights for Steve Offiler
10/18/91

FORD MY'92 ELECTRONIC SPEED CONTROL DEACTIVATE PS

RAPTOR DIAPHRAGM LIFE:

Impulse of test lots crimped at different pressures is nearly complete. Weibull analysis of the data has revealed a general downward trend in reliability at 500K as crimp pressure is increased, however, we have not seen the drastic differences or trend we expected.

Crimp Pressures	Data	Theta	Reliability at 500K
45/40	4.6	677	78%
50/44	3.4	672	81%
55/44	3.9	669	73%
60/50	2.8	764	74%
65/55	4.9	632	73%
70/60	3.6	643	67%

A new matrix of test lots are scheduled to go on impulse by the end of today. This matrix will target differences in washer as a cause of diaphragm failure. The matrix will include 0-out washers (control lot) which have more of a chamfer on the inner edge than a radius, 2-out washers which have the best radius we have seen, and the old-style nickel plated washers which are more slippery. A fourth group will be added to the matrix early next week which will be crimped on the AMI with the tools from the hand-line crimper substituted.

CUSTOMER ISSUES/SAMPLES:

It is still unclear which thread is required to fulfill the 12-piece sample order for Ford of Australia. Charlie Douglas hopes to have confirmation one way or the other by Monday. If the M10 x 1.25 thread is correct, we can ship samples next week. However, if the M10 x 1.0 is required, we will not be ready to ship until early November due to back log in the CNC lathe department and the necessity of plating.

CRUISE CONTROL AUTOMATION EQUIPMENT:

Manufacturing engineering and mechanization continue to iron out problems with the switch assembly AMI (6NAMI) and the Eastern Automation machine. Production has an order of 3,570 parts to be shipped on Monday which has put this debug on emergency status. 100% of Dave Peripoli's time will be dedicated to this effort until resolved. This accounts for the delay in the above test lot being delayed until next week.

TI-003616

CFC

L696

HIGHLIGHTS

Steel Officer
W/E 91-11-01

DIAPHRAGM LIFE:

Results of washer test (using 0 wt Zn plate; 2 wt Zn plate; and 0 wt Ni plate) all runnings at Amst & "normal" pressure:

	<u>LOT</u>	<u>β</u>	<u>θ</u>	
a)	0 wt Ni	2.4	1630	{ first fail @ 63E}
b)	2 wt Zn	2.4	1472	{ first fail @ 67E}
c)	0 wt Zn	3.3	960	{ first fail @ 100E}

Mixed failure angles were apparent from the Weibull graphs; the first failures seemed to be on a different curve than the latter ones. The above β and θ therefore actually represent averages of the mixed modes combined.

Results of crimp tool swap:

	<u>LOT</u>	<u>β</u>	<u>θ</u>	
a)	Hand die tools on Amst	10.4	705	out of spec
b)	Hand die tools on HL	5.3	670	
c)	Amst tools on Amst	6.6	660	
d)	Amst tools on HL	7.9	540	

Contrary to washer test, mixed modes did not appear to be a factor. It seems that the handdie tools produce a higher θ , while the Amst produces a higher β . All above used 0 wt washers based on results of washer test. However, sort of washer test should be identical to sort of crimp tool swap.

Based on a combination of the above, it would appear that hand-die tools on the Amst dies with 2-wt washers will produce our best shot at good devices. Of course, we still have no concrete idea, yet.

Jeff DiDonato has developed a very good hypothesis which explains bonding formation. He suggests that the nature of laport bonding is quite possibly asymmetric, leading to greater damping in some areas and less in others. Those areas damped less would allow the Kapton to pull out, producing the "print" of the laport. We're experimenting with this hypothesis using stepped reliefs in the laport combined w/ full-round Kapton.

TI-003617

Using the relatively new technique of cutting away the top part to observe the top Kapton layer while the device is still fully crimped, we have opened up the worst and best devices from the three weather lots. This was done to attempt to understand the apparent differences in failure mode. Evidence of bonding shape was fairly subtle, but nonetheless the three low-life parts had a fairly narrow area of perforation, apparently at the peak of the bonding (but this is questionable, since the bonding could be a result of the perforation rather than the cause.) In contrast, the high-life parts showed the top layer to be failing uniformly all the way around.

It is unfortunate that we are at our drop-dead point to build ISIR parts, because all indications seem to be pointing to the bonding as the fundamental problem, and we are only just beginning to understand the cause and remedy to this phenomena. With Joe Schuck's departure, it might be wise for Marketing to place a call to Bruce Penn to update him on our status and request an extension to our 90-day deadline.

TL-003618

CIVIC
6598

HIGHLIGHTS

Stephen B. Offiler
Week Ending 91-11-08



FORD MY'92 ELECTRONIC SPEED CONTROL DEACTIVATE PS

PASS-CAR REVALIDATION:

Two lots of parts were constructed to undergo the combined Fluid Resistance and Impulse testing, which was compromised in the original validation attempt. One lot uses the desired production technique (AMI) whereas the other uses the technique we were forced into as a fallback during the original validation (S7PS Hand Line). Based on results of failure testing over the last several weeks, the best-performing crimp dies and washers were used. Half of each lot was precharacterized and delivered to the Chem Lab on time to begin the Fluid Resistance test on schedule Tuesday. The other half, which undergo only Impulse, started cycling on Wednesday. These will complete their 475K mechanical cycles early Saturday, and Jeff will come in to set up and run the 25K powered cycles. Post-characterizations will be done early next week, then all parts will be run to failure in order for the sake of information. An interesting observation was made regarding act/rel pressures. Parts crimped on the hand-line were lower on average than the AMI parts, by about 3 psi on act and 11 psi on release. We plan to take a closer look at this phenomena to see if it provides any clues to the diaphragm life issue.

KAPTON DIAPHRAGM LIFE:

We're continuing to work on the teardrop shape in the Kapton surface as a contributor to early life failures. We've seen the perforation in the diaphragm to generally coincide with the apex of the teardrop if present; if absent the diaphragm wear is well distributed around the perimeter. We're looking into the possible mechanisms that promote teardrop formation, including pre-crimp, gasket friction, and ultrasonic clamping. We're also looking into whether teardrop formation is an issue with Light Truck parts.

CUSTOMER ISSUES, SAMPLES:

For the Ford of Australia samples, the M10 x 1.0 hexports were completed by an outside house, plated in B11, and have been built into devices. We planned to test these on the production tester, but apparently it would not seal properly. We're making an adapter so we can manually test these on our Life Test check station. They will ship today, on-time per the revised schedule. They were originally promised for 91-09-17 until confusion over thread spec's arose.

Charlie Douglas met with Bruce Peace earlier this week to discuss the Kapton life / revalidation issue. Charlie reports that the meeting went well, and Bruce is convinced we're making good progress on the solution to this problem. It looks like an extension to the 90-day alert is possible, if required. On another subject, Charlie hand-delivered the SREIA for the change to blue-colored environmental seals for PC devices.

MACHINIZATION:

John Kourtsos and crew are presently working on eliminating the rivet from the Eastern Automation movable-terminal assembly machine. The two options being considered are ultrasonic welding and resistance welding. I'm working on a quick sketch of the terminal/spring redesign for presentation at a meeting John will hold early next week. Of course, this change will require re-validation. I propose that we use our P & DFMEA's to drive the justification for this change, possibly rethinking the PRN's associated with the rivet and riveting process relative to a welding process.

TI-009619

08/09/00

HIGHLIGHTS

Stephen B. Offiler
Week Ending 91-11-15



FORD MY'92 ELECTRONIC SPEED CONTROL DEACTIVATE PS

PASS-CAR REVALIDATION:

Twelve parts from each lot (AMI crimp and HL crimp) successfully passed the Impulse test. Twelve more of each will undergo this test when they complete the Fluid Resistance test in December. They have been characterized post-test, and are now running to failure for information. They are at 950K cycles with no significant number of failures to report yet. As previously reported, the pre-test characterization showed significant differences in release pressure between the two lots. This difference disappeared during cycling; it is possible that it is attributable to a Kapton-wetting phenomenon. We're looking into linking this with observed differences in the crimp techniques which are suspected to lead to diaphragm life problems. Also, Jeff has noticed crimp dimension differences between the two lots, even though the same crimp dies were used for both. We're looking into this with Mfg. Eng. help.

HEXPORT:

We have completed an initial evaluation of the mechanical strength of the 10B21 hexports. Two tests were used: burst, and torque-to-breakage. Results of both tests indicate that the 10B21 hexports have better strength. The average burst strength of 10B21 was 7983 psi versus 7630 psi for 10L10. The average torque of 10B21 was 51.8 ft-lb versus 41.3 for 10L10. Also, we previously cross-sectioned samples of each material and measured the hardness in the thread area. Results of 6 measurements at the crests of the threads show the 10B21 averaging 244 DPH (200 gram Diamond Pyramid Hardness), with the 10L10 averaging 194 DPH. If no cost differences exist (as Elco has led us to believe) then we should seriously consider a move to 10B21 material. Final decision on this is pending environmental analysis of the reduced plating thickness (to reduce thread damage in plating barrel) as well as final decision on the ANSI-specified gaging technique, using 2A LO and 3A GO gages. I'm confident that the combination of the above will finally eliminate the chronic thread problems we've been experiencing on this and all other Elco hexports.


SAMPLES / CUSTOMER ISSUES:

We've begun to receive sample requests for silent devices from Ford for WIN18 (Truck style centered connector with Pass Car style pressure) and from Bendix for Truck. We're establishing new part numbers, envelope drawings, and parts lists for these products. Samples are due in early December, which doesn't seem to be a problem since we already have small quantities of silent discs. Base colors have not been firmly established, hence for samples we'll use standard black for truck and brown for car.

The Ford Australia samples with metric M10 x 1.0 o-ring hexports shipped last week. We received a fax from Brent Franks, the F of A engineer on this program, which indicates he's experiencing audible noise difficulties. I have responded to this, indicating that this is an established concern and we are working to minimize it. Brent also alluded to a possible change in pressure spec's, downward. I am trying to steer him away from this, since the Pass Car disc already has reduced throw (relative to Truck and other 57PS's) and making it silent will only worsen this; compounded with even lower pressure spec's may reduce throw to an unacceptable level.

TI-003620

HIGHLIGHTS
 Stephen B. Officer
 Week Ending 91-11-22




FORD MY'92 ELECTRONIC SPEED CONTROL DEACTIVATE PS

PASS-CAR REVALIDATION:

Eight of ten parts crimped on the hand line, cycling to failure for information, have died between 853K and 1336K. The remaining two have been removed from test for diaphragm analysis. In contrast, only one of the eight parts crimped on AMI (using HL crimp dies) has failed thus far, at 1361K cycles. Two of these have also been removed for analysis. The remaining five will continue to run to failure. This lot is of particular interest, because this is the first time since we began diaphragm life testing in August that the AMI has produced parts superior to the hand line.

DIAPHRAGM LIFE:

The planned analysis of the four long-life parts from the above validation consists of F/d characterization, to observe if differences in converter travel (pre-deflection caused by crimp differences?) account for the drastic life differences, plus opening for observation of diaphragm condition/teardrop. F/d curves have been obtained on virgin sensors from this test to explore the observed differences in release pressures between AMI crimp and HL crimp. It was learned that the effective area on actuation is comparable for all, whereas the effective area on release is much larger for the HL crimp parts, which accounts for their much lower release values. No good hypothesis has been generated to explain this large shift, however.

The model shop has built a set of test hexports which have a step to clamp the Kapton at the outer circumference. This was tried previously, however this time we're using three different step heights, and full-round Kapton. We're using this to explore teardrop formation/wetting, to understand whether the Kapton primarily stretches (deforms plastically) to wet, or whether it primarily pulls out from under the clamped area. We've opened two samples from each of the test lots for diaphragm observation. The control lot (square Kapton, no step) has one textbook teardrop, and one which is wetted ideally. The round Kapton test lots show generally poor wetting with no actual teardrop but some looseness and upward bulging. The fact that we're observing poor wetting in the test lots seems to suggest that the square Kapton promotes some pulling out from the clamp area in order to wet, and the teardrops form if the Kapton pulls out asymmetrically. We are also characterizing samples from these lots, which should show the differences in wetting as smaller effective area hence higher actuation and release values relative to the control group. Finally, these parts will be cycled to failure.

Another extensive part of the theory of teardrop formation is getting underway now. We're marking all caps, so that orientation in the dies during crimp can be controlled. Thus, if the bending of the "C" frames of the crimp tools (radially outward) is a factor, there should be some correlation between teardrop and position. Some parts are being run with Fuji pressure-sensitive paper, while others are "normal" construction. We'll be performing extensive measurements of the crimp height/diameter of these parts (relative to position), as well as opening them for observation of teardrop. A few will be removed from the table before the air-blast station, to help determine if the teardrop forms before or during wetting.

TI-003621

1713
5782

HIGHLIGHTS 911122 Page 2

MECHANIZATION/MANUFACTURING:

A problem with staking the stationary terminal on the base atm machine has been observed. Various efforts to correct this, including comparison with staking on the 57PS-style stakes, has led to the conclusion that a small amount of lubrication is required in order to fold the stake tab correctly. In fact, simply touching the stake tool with a finger has been shown to produce good stakes for several parts. A short-term lubrication procedure, swabbing the tool with Vanishing Oil, has been implemented. Longer term, Mechanization is working on staking tools with various surface treatments (chrome, nitriding) which do not require lubrication. It is generally assumed that the movable terminal does not exhibit this problem due to trace amounts of lubricant picked up from the exhaust of the air cylinders in the movable terminal assembly machine, and the 57PS does not exhibit this problem because all terminals are handled by operators during assembly.


A meeting was held with Staples, a manufacturer of ultrasonic welding equipment, to explore the possibility of replacing the troublesome spring arm rivet with a weld. They showed extensive literature and examples of ultrasonic welds of copper to brass, as well as many other material combinations. They claim to have excellent acceptance with the US automotive companies and their electrical suppliers. Mechanization has contracted them to produce prototypes for us, which we will initially evaluate with various cycling and pull/pull tests.

TI-003622

1075 2145

HIGHLIGHTS

Stephen B. Offiler
Week Ending 91-11-27



FORD MY'92 ELECTRONIC SPEED CONTROL DEACTIVATE PS.

DIAPHRAGM LIFE:

All of the Pass Car Revalidation parts have been cycled to failure. The AML-crimped parts (hand-line crimp tools) exhibited by far the best diaphragm performance to date, with a Beta of 15.3 and a Theta of 1579; versus the hand-line crimped parts with 7.2 and 1207 respectively. We have held aside several sensors from each lot for analysis of this large difference, including virgins, 500K cycles, and long-life parts which hadn't failed at 1350K cycles.

We are now cycling the experimental lots with full-round Kapton, built with stepped hexports in order to concentrate the clamping force at the outer circumference. Control lots with round Kapton/no step, and normal square Kapton are also included. Initial characterization showed the full-round lots actuated and released at higher values than the square control lot, which was expected because the Kapton is not wetted very well hence a smaller effective area and larger pressures needed to develop equivalent disc force. A quick interim characterization of a few of the parts at 450K cycles shows that the pressures have dropped, again as expected, since cycling has completed the wetting. The only failures have been in the lots with the largest step (.007" norm.) and based on the very slow progression of the leakage I expect we'll find extruded gaskets, not diaphragm problems.

We have completed the build of all test parts for the analysis of the asymmetric-crimp study, to help determine if crimp tool "C" frame flexing contributes to teardrop formation. We're checking two parts from each next with Fuji pressure-sensitive paper, to look for next-to-next variations, as well as analyzing crimp height and diameter and teardrop formation relative to the next and the direction of the "C" frame flex. This test is delayed slightly by the fact that the decrimer is down for repairs, as well as lack of tech support while Jeff is attending Hydraulic Training.

57PS TO 77PS CONVERSION:

The initial phase of this testing program has gotten underway. 57PS sensors with the highest actuation and the widest release (1.8-1) were chosen as representative of the larger pin travel and the highest snap energy. Sensors were pre-characterized and the pin window analyzed, then built onto 77PS switches using a pin length skewed long (towards creep-release) to obtain the largest spring deflections. Devices were given an initial characterization and returned to Man to be cycled on production cycling equipment. They will be checked for continuity every 50K cycles, and failures will be opened for analysis as they occur. Weibull techniques will be employed as well after all have failed.

MISCELLANEOUS:

We have received word from Ford SQA Mark Scholler that the revamped partial DFMEA has been corrected consistent with Ford philosophy. We must now continue to revamp the rest of the document in the same fashion.

It has come to my attention that the on-line 57PS inspection equipment for contact leakage has not been upgraded yet to comprehend the 77PS. They are therefore relying on us to supply lab equipment for this test, which is unacceptable for several reasons: equipment availability; setup time; and especially safety concerns, since our 500VAC sources are not protected and guarded appropriately for use by non-electrically-astute production personnel.

T1-003623

HIGHLIGHTS

Stephen B. Offner
Week Ending 91-12-06

W.B.O.
12/22



FORD MY'92 ELECTRONIC SPEED CONTROL DEACTIVATE PS

DIAPHRAGM LIFE:

The test of round diaphragms continues. Five of six controls (standard, square Kapton) have failed with a beta of 7.5 and then of 1245, which is quite good. However, only two of the twenty test devices (round Kapton with various hexport steps) have failed, beginning at nearly 1700K. We are presently working on a new set of controls, which use square Kapton cut from the exact same material as the round parts. A "standard" control lot will again be included.

We have expanded the plans for the determination of the mechanism of teardrop formation. We are now looking at process and design contributors. Test lots are being built using all standard parts, as well as lots without gaskets, and lots with modified converters to produce a zero-height bump. These will be crimped to various stages of completion, including removal prior to air-blast, prior to final (stage II) crimp, and prior to stage I crimp. In order to examine the diaphragm in the pre-crimp condition (prior to stage I), we plan to have the model shop modify hexports to make them into 2-piece units which match a standard hexport when assembled but allow easy removal of the hex portion from the flange.

The test of possible asymmetry in the crimp procedure has been partially completed. We have observed no real correlation between the location of the teardrop and the orientation of the device relative to the nest. Based on this, we've decided to abort the rest of this test in order to place emphasis on the above test of teardrop mechanism.

57 TO 77 CONVERSION:

To date, using 77 switches calibrated to .089" and 57PSL8-1 sensors, pinned high, we have had one spring break (in the expected location, at the top of the rivet head) at 900K cycles. The remaining 9 have passed 1250K cycles, and the test continues.

We are formulating a game plan to begin a detailed test, based on tentatively positive results from the above. This will include a study at tolerance extremes, using high- and low-calibrated switches, pinned at each extreme of the pin window. The test will use the actual Sensor assembly in question rather than the worst-case as above. Cycling will be done on the CCP3 cycler rather than the production equipment, at the ES specified temperatures and pressures.

Co-operation with Marketing is planned, to ensure that our testing program is aimed at the high-volume 57PSL product(s), and to decide on the correct approach for customer approval and validation of the new product. At some point a decision will be reached on a TI part number designation for these; it is inappropriate to call them 57's, and it may be risky to call them 77's due to the price difference between these and cruise control 77's. It has been suggested to use the next available series number, probably 78PS.

DFMEA:

We plan to get work underway again on the Design FMEA. Given the number of parts and an estimate of the time required to complete each part, based on recent hexport work, it looks like the completion date will be mid-February, if all goes well.

TI-003624


470.1 4 revision

172.1 - 172.2 000 000

NE AM

470

176 2001/01/01 AM

HIGHLIGHTSStephen B. Offiler
Week Ending 91-12-13


12/13/91
**FORD MY'92 ELECTRONIC SPEED CONTROL DEACTIVATE PS**

VALIDATION: The two lots of PC revalidation parts (AMI built and HL built) have completed the Fluid Resistance test, and are presently undergoing the Impulse test. This test will be completed by Tuesday morning, with final characterization to commence immediately, and final test report writeup to take place Wednesday in order to prepare the ISR package addendum by Friday. The plan is to report results from both lots, hopefully to gain approval from Ford for both processes.

DIAPHRAGM LIFE: The test of round diaphragms is nearing completion. Approx. nine survivors from the various test lots are presently at 2250K cycles, running in parallel with the above reval test. The control lot, with all standard components, is complete with Beta=3.3, Theta=1369, and Rel @ 500K=99.52%. The lot with round Kapton and all other components standard has only 3 failures (beginning at 1933K) and no stat's calculated yet. The lot with round Kapton and .003" step in the hexport to control Kapton clamp has 5/6 dead, Beta=10.2, Theta=2090, and Rel @ 500K=99.9999%. The other two experimental lots, with various size steps in the hexport, also do not have enough failures to allow stat's. These results certainly suggest that the round Kapton has much better life expectancy relative to square, but other significant problems exist, specifically device calibration drift and manufacturing concerns.

The test to determine the mechanism of teardrop formation is partially complete, and some initial conclusions can be made. Standard parts, parts without gaskets, and parts modified to produce zero-height converter buttons are being crimped to various stages of completion, in order to track the progress of teardrop formation. We've seen parts with the familiar teardrop after final crimp and air blast having a twin-apex teardrop (Mickey Mouse) pre-air blast, and a somewhat fuzzy suggestion of the Mickey shape pre-final crimp (post 45° crimp). The next significant milestone in this experiment is to check the condition of the diaphragm pre-45° crimp (post precrimp). The only way to do this is to use 2-piece hexports, which allow normal precrimp assembly action and also allow inspection of the diaphragm without needing to lathe-cut the hexport. The mold shop is presently working on these. The parts without gaskets are also very interesting. Pre-air blast (post final crimp) there is significant excess material which has been moved radially inward; although there is no suggestion of a teardrop shape. At the previous process step, pre-final crimp (post 45° crimp) the same sort of condition is apparent, but less material has been moved inward at this point. The 2-piece hexports will be used to complete this sequence as well. At this point, we are definitely seeing a progressive action taking place, which is tending to move material radially inward as the crimps are made. Without gaskets, much more material seems to be allowed to move.

57 TO 77 CONVERSION: Using 77PS switches calibrated to .069" and 57PSL2-1 sensors pinned high, we have seen 7/10 devices fail on the production cycler due to fractured springs. All are breaking in the expected location, at the top of the rivet head where the spring is effectively constrained and the bending stresses are concentrated per cantilever beam theory. Weibull analysis shows Beta=2.1 and Theta=3230 with Rel @ 225K=99.63% and Rel @ 1000K=91.83%. *NEED SCHENKLE FOR LS-2*

Charlie Douglas hand-carried 6 samples of the 57PSL2-2 conversion to Tom Sizemore at Ford Power Steering. These were well-received. Charlie discussed revalidation requirements, and also found out that they're planning to switch to the more robust UTA mating connector.

TI-009625

371
6786

HIGHLIGHTS
 Stephen B. Offier
 Week Ending 91-12-20

12/12/91



FORD MY'92 ELECTRONIC SPEED CONTROL DEACTIVATE PS

DIAPHRAGM LIFE:

All devices from the round Kapton test have finally failed (except one, expected to go any second now). Results are as follows:

Control lot, square Kapton	Beta=5.3	Theta=1369K Rel @ 500K=99.52%
All round Kapton lots	Beta=9.2	Theta=2350K Rel @ 500K=99.9999%

The only questionable aspect of the above test is that the round Kapton came from a different lot of material, possibly produced in a lab process, and therefore it possibly has greater mechanical properties which help account for the increased life. We plan a test using square versus round Kapton from the same material lot.

2nd
plan
 We plan to consolidate all recent knowledge gained from various design and process testing, and hold a meeting in early January.

VALIDATION:

The Pass Car revalidation has been completed successfully, and the addendum to the original test report has been written, bound in TI test report format, and delivered to QRA for submission to Ford. The 90-day slot expires on 91-12-31. We ran two test lots in parallel: crimped on Hand Line, and crimped on AMI using NL tools. All of these devices passed 500K cycles with flying colors. The writeup includes both test lots, such that we will be approved for both processes using HL crimp dies.

57 TO 77 CONVERSION:

cycle point
 The lifetest of 10 devices (1.8-1 sensors, 77 switches) has been aborted at 6KK cycles, with 2 devices remaining. A rough draft development schedule has been assembled, which shows that we can begin shipping new devices as early as 03/92 if all goes well, and high priority is placed on completion of all internal and customer validation testing. This also assumes red-type (customer envelope prints into Ford's system, TI parts lists, all ISR paperwork, etc. etc.) is handled efficiently.

DFMEA:

Work is progressing fairly smoothly. Since we recently began the serious attempt at completing this task, we've experienced only minor scheduling snags. Additional meetings have been scheduled in order to continue on a path to intercept mid-February completion. At this point, this effort is occupying significantly more than the 8-10 hours/week I previously estimated, and this is likely to continue.

TI-003626

HIGHLIGHTS
Stephen B. Offiler
Week Ending 92-01-10

FORD MY92 ELECTRONIC SPEED CONTROL DEACTIVATE PS.

57-to-77 CONVERSION: I have officially reserved the number 87PS (project #3472) for the new devices. For the sake of continuity and easy simplicity, we plan to retain the same suffix, for example 57PSL11-2 becomes 87PSL11-2. It is important that we agree upon a strategy soon, since we are beginning to fall behind the aggressive schedule drafted in December and there remains some question whether we work exclusively on L2-2 or simultaneously work on all candidates, i.e. L2-2, L8-1, L11-2, and L11-3 as well as 57PS devices which need validation of AI crisp ring and line-move.

SILENT DEVICE FOR MY93 SHO TAURUS: We have received a M/C, with our silent 77PS switch installed, from Tim Andriksen at Ford. They claim that the supposedly silent switch makes audible noise in the passenger compartment, and request an evaluation and test report. We plan to fixture the M/C on benchtop, confirm that the switch is the culprit, and next obtain an ABS Taurus to install this M/C and quantify the audible noise. Other experimentation, such as use of a snubber, can be executed at the same time.

DIAPHRAGM LIFE: We are presently running a test which is comparing square and round Kapton which is taken from the exact same material lot. This is because the exemplary life performance of the round Kapton witnessed previously was compared to production square Kapton from a different lot and different mfg. process. We've included a control group using standard production parts, and another test group using Ube polyimide material obtained from Gary Baker.


We have completed all testing designed to expose the formation process of the teardrop. Results will be presented and discussed at a meeting with Mfg. Eng. early next week.

DFMEA: Significant efforts are being expended in order to remain on track for completion in early February. While this is requiring more time commitment than originally planned, the team is very pleased thus far with the results. This should become a benchmark document for future DFMEA's.

TI-003627

HIGHLIGHTS

Stephen B. Gitter
Week Ending 92-01-17



FORD MY'92 ELECTRONIC SPEED CONTROL DEACTIVATION

87PS: Charlie Douglas has begun to hold startup meetings, and we are proceeding with required planning to co-ordinate internal design validation plus customer production validation of 87PSL2-2, L5-1, and L11-3. Also included are re-validation of 87PSF3-3, and 87PSF9-1 which are running in parallel with 87PS testing. Certain devices already have ISR dates prescribed to Ford (92-04-15), which will serve to direct priorities. We are working on several items to streamline this process, including approval from Ford to consolidate specifications.

Since a fairly large number of devices will ultimately need to undergo Impulse and Thermal Cycle (using similarity as much as possible for all other tests) we are beginning to plan for cycle capacity. Jeff has devised a scheme to set up the new cycler to run the complex TC test unattended. He will place an order for an Omega dual-setpoint temperature controller needed to accomplish this, as well as a spare brake-fluid-compatible hydraulic cylinder.

SILENT DEVICE FOR MY'93 SHO TAURUS: Benchtop testing of the M/C with our silent 77 installed showed extremely little audible noise, requiring amplification to hear at all. This suggests that the noise problem is emanating from elsewhere in the system, but of course it could still be stimulated by our switch. Ford has requested we perform an evaluation and respond with a formal test report. This will require that we obtain an ABS-equipped vehicle in order to isolate the source of noise. Any ABS Taurus, or any Continental (ABS standard) will fit this Taurus M/C. We prefer a Taurus if possible, since Ford reports the problem manifests itself here, but we are having significant trouble locating a rental ABS Taurus. We may have to try the Continental, which is based on the Taurus platform but probably includes more sound-deadening materials which will make the audible noise situation different.

DIAPHRAGM LIFE: The ongoing square vs. round Kapton test has begun to produce interesting results. (Recall that round Kapton from a previous test, from an 8.5 x 11 sample sheet, produced exemplary results.) This test compares round and square cut from the same sample sheet. The test also includes a Japanese polyimide film from Ube, square, and a control lot. As the test nears 1KK cycles, 3 of 6 Ube parts are dead beginning at 414K; 4 of 6 controls are dead beginning at 545K; and NO failures from either square or round lot from sample sheet material. It seems obvious that the sample material has much greater resistance to rupture, and it remains to be seen whether round vs. square makes a significant difference in these parts. Upon completion of this test, we should involve Dupont to explain the material differences (production vs. sample sheet) and possibly upgrade the production material.

A synopsis of developments in diaphragm life testing was presented this week. As a result, several good ideas were generated. The general attitude is that a snap-mate design is required, which is not sensitive to production line variables such as crimp tool geometries, crimp forces, etc. We will proceed with testing and development work, including the following experimentation: reduce/lift Kapton clamping by machining a step on the outer portion of the hexport flange to provide metal-to-metal contact to washer and using a small-diameter round diaphragm; try self-cured diaphragms with only 2 layers; try Kapton without Teflon; addition of a "bump" male feature on the hexport with corresponding female in the washer in order to stretch the Kapton during assembly; and use of pre-bent, concave hexports (silicone parts, for example) to see if this eliminates the tendency of the diaphragm to move radially toward which is thought to happen as the hexport and washer bond at crimp.

TOKICO: Info coming from Charlie in Dearborn via Dave indicates we've bid our hands on a Tokico M/C with Hy-Serv switch installed. Apparently the switch mounts at an angle in order to clear the reservoir. We plan to completely characterize the switch, take photos and X-rays, thin cross-sections, etc.

SNP# 0166, 12/15/98 9:55 AM

209-144

TI-003628

HIGHLIGHTS

Stephen B. Offler
Week Ending 92-01-24

FORD MY'92 ELECTRONIC SPEED CONTROL DEACTIVATE PS

87PS: Planning for the various validations and all attendant documentation continues. We are presently working with Tom Strauss (PC Steering) and John Kalppel (LT Steering) to consolidate the two separate ES's (ES3C for front applications, and ES7A for LT). We've been able to steer LT away from the temperature characterizations required during their Thermal Cycle test. The Impulse test, previously 225K to 1450 psi and 775K to 600 psi was tentatively changed to 250K at 1450 psi, but John dug up a hose assembly ES which calls out 400K to 1600 psi. Before we settle on anything, I've requested that John forward a copy of that spec. It is possible that other parameters (such as temperature) are also different. Regardless, any changes apply to Validation testing, not to In-Process testing which will remain the same.

CUSTOMER ISSUES: Marketing has come up with a plan to borrow a car from Tasea Lincoln-Mercury in order to install the Teves M/C and conduct experiments on switch noise. We will visit Tasea today to finalize details. I have roughed out a test plan which will be presented to Tasea management. We have five switches that we'd like to experiment with: 1) the low-differential "silent" switch returned with the M/C; 2) a squibber device with snap disc; 3) a squibber device with low-diff disc; 4) a device using a custom diaphragm composed of layers of Kapton and EPDM rubber; 5) the Hi-Sat switch. We hope to be able to determine where the noise is coming from, and under what conditions, so that we may recommend possible solutions to Ford.

We've learned that our delay in producing an envelope drawing for WIN88 has upset a certain individual on that program, who has now threatened to go ahead with Hi-Sat. In order to placate this individual, we will place high priority on producing this print, although his reaction is somewhat childish and underscores a seemingly fundamental problem with the TV/Ford working relationship.

DIAPHRAGM LIFE: The present test of round vs. square diaphragms is nearing completion. The round test parts are again showing the best life, with only 3 of 6 dead and no Weibull stat's calculated yet. The square test parts (some sample-sheet material as well) have 5 of 6 dead, with a rel. at 500K = 99.91%. The controls (production material) have all 6 dead, with rel. at 500K = 95.76%. Finally, the Japanese polyimide material shows the worst life with all 6 dead and a rel. at 500K = 83.39%.

We have an outline, but still need to finalized plans to continue with diaphragm life experiments as discussed at last week's meeting. This is complicated somewhat by the need for cyclo resources to conduct the battery of validation tests for 57PS and 87PS.

PRODUCTION ISSUES: Mfg. Eng. is interested in redefining the 77PS switch calibration scheme, by running the calibrono/check station at a fixed valve and selecting pins as appropriate for different sensor lots. A meeting will need to be organized in the near future to explore ramifications of this.

71-003029

HIGHLIGHTS

Stephen B. Offner
Week Ending 92-01-31

J.B.O.
1-2-92

FORD MY'92 ELECTRONIC SPEED CONTROL DEACTIVATE PS

87PS: We've received information from John Kalpel (LT Steering) which shows the requirement for the hoses used in PS assemblies is 400K cycles at 150 C fluid / 135 C ambient to 1600 psi. John has asked us to increase our requirement (for Validation only) to this, with the exception that he hasn't asked for any change in our present test temperature, which is 135 C fluid / 107 C ambient. We are generally in agreement that we can meet the higher number of cycles and higher pressure without any problem, and furthermore it appears to be a large negotiation concession on our part. We now owe John a marked-up spec. for finalization, and concurrence with other PS engineers (Pass Car. Europe, etc.).

SHO TAURUS NOISE ISSUE: We have obtained a brand-new '92 Mercury Sable as a test vehicle from Tasca Lincoln-Mercury in Seckonk, MA. Their co-operation in this matter has been exemplary. The car is to be returned the morning of Feb. 6. We have installed the master cylinder that was sent to us by Tim Andresen, along with the prototype "silent" 77PS device which they found to make noise on a '93 SHO Taurus evaluation prototype. We have installed this M/C, and discovered a very minor noise in the system, and tactile feel in the pedal. With engine off or on, the noise is not as noticeable as the sound made by the brake light switch. Subjectively, the noise/feel are generally not considered annoying in any way by several individuals who have experienced it. We have noted at least three points in the pedal travel which produce some noise and/or tactile-feel: the BLS, our switch, and the third is suspected to be the ABS pedal-travel sensor. The Ford memo from Tim Andresen which accompanied the M/C states: "Based on the number of cars we have built with the switch, I don't think this is a 100% problem. However, some of the switches make significant noise which may be intermittent." This seems to suggest that the noise we are experiencing is not necessarily as acute as it might be under different conditions. We plan to continue evaluations, including: installation of a normal snap device for comparison sake; isolation of the "silent" switch with rubber hose; a custom device with rubber diaphragm; and we are considering the logistics required in order to use the prototype rubber devices we've prepared with silent and snap discs.

DIAPHRAGM LIFE: The most recent test of square vs. round Kapton has been completed. The round Kapton from the sample sheet fared best, with rel. at 500K = 99.71%; next is square Kapton from the same sample sheet at 99.53%; then production square Kapton at 93.76%; finally the Japanese polyimide at 83.29%. (all values at 50% confidence).

TI-003630

HIGHLIGHTS

Stephen B. Offiler
Week Ending 92-02-07

FORD MY'92 ELECTRONIC SPEED CONTROL DEACTIVATE PS

SWITCH NOISE ISSUE: We have completed testing on the borrowed '92 Sable w/ Teves ABS, and the car has been restored to original equipment condition and returned on schedule to Texas Lincoln Mercury. We had the opportunity to explore a number of different switch configurations, including: discs at various differentials; snubbers vs. standard 1512 ports; remote mounting with rubber hose; and the Hi-Star device. We confirmed the noise issue reported by Ford, as well as a tactile feel, although the so-named "low-differential" (4 psi) device implicated by Ford was not considered significantly obtrusive. Subsequent testing showed absolutely no noise or feel using discs with "ultra-low differential" up to 2.6 psi, while a 3.6 psi device was marginal. It is generally felt that 3.0 psi max differential would be sufficient to completely eliminate this customer concern. We'll need to explore the disc-processing ramifications of such a spec. Experimentation conducted with snubber hexports showed 4.0 psi diff. was undetectable, while 5.6 psi was marginal, suggesting a spec of about 5.0 max. However, concerns with the snubber include the fact that snubber plus 1512 will be quite expensive, standard o-ring snubber may be suitable to Pass Car but won't help this issue when it arises at Light Truck, and finally air entrainment. We found no difference in noise and feel when the switches were remotely mounted with about 42" of 1/4" I.D. hydraulic hose. Finally, running the Hi-Star switch for information showed that even with its snubber it has significant noise and feel, to a somewhat greater extent than our low-diff device and somewhat less than one of our production snap devices.

PRODUCTION ISSUES: Production impulse testing turned up spring arms cracking at the bump. Analysis by Mfg. Eng. and Mech. showed that the bump was not being formed correctly, with a fairly sharp crease in one area where the bump comes out of the plane of the spring. This corresponded with the location of the crack. The tool was disassembled and it was learned that the die was formed asymmetrically, causing this sharp crease. Since this feature has not been machined since day 1, there is some cause for concern that all product shipped has this potential to crack. However, the production cycle is known to be unrealistically severe. We have had no problems to date with any spring arms that in our cycle. We are presently running a sampling of recent production devices in our cycle to ensure that there truly isn't any cause for concern. The feature in the die which caused this condition was expertly re-worked by hand, and the bumps now look exemplary.

CUSTOMER ISSUES: We were forced to rush to get a print out to WINSS, and as such did not have the opportunity to reduce the number of dimensions as we intended to do on all future envelope prints. This print was turned around by drafting in one day. Our "lateness" perceived by Ford is a black eye for TI, although the real reason the print was "late" is that we don't seem to have a good ability to anticipate the requirements of Ford's system, thus we're caught unprepared and forced to rush which causes negative feelings and greatly increases the chances for error.

TI-003631

HIGHLIGHTS

Stephen B. Offiler
Week Ending 92-02-14



FORD MY'92 ELECTRONIC SPEED CONTROL DEACTIVATE PS

SWITCH NOISE ISSUE: We've begun to work with the disc department to arrive upon a production-viable method to produce ultra-low-differential discs. We've returned the original Disc Dept. prototype lot of 1.3 psi diff. to Ted for further analysis, including Force-Deflection work. The goal is to develop a means of producing and checking these discs in production. Additionally, Ted has provided a bit of disturbing news: the disc used in the actual device which caused the customer noise complaint has a differential of 2.5 psi (all quoted measurements using Disc Dept equipment) while our experimentation showed a 3 psi device to be undetectable. Does this mean that diff. is not necessarily correlatable to sound? Mfg. Eng. and Mechanization are becoming involved at this point. A meeting will be held next Monday to discuss how to pilot, build, and test a device which is silent.

HI-STAT DEVICE: We've completed a competitive evaluation of this device. This includes X-rays, characterizations, cycle testing to failure, and disassembly. We discovered quite a bit of drift in characterization, with initial readings of 289/144, 10K readings of 279/129, and 50K readings of 265/134. The mV drop looked okay. The device was a release-creep. The device developed a leak at about 100K cycles. Upon opening, we discovered the internal seal (composed of a round-section O-ring, colored purple) had extruded. Design features include an insert-voided base, with very beefy sections to support the crimp operation which must withstand the entire burst pressure. No transfer pin is used, rather the discs (2 stacked) sit directly on the spring arm with a Kapton insulator. Overall the device appears very prototype in nature, with no plating of any kind on any steel internal components. Additionally, the device is quite poor in terms of Design For Assembly, with the diaphragm, the pressure/force converter pin, and the discs poorly located and easy to misplace.

DIAPHRAGM LIFE: We've received test parts from the model shop, and evaluations have begun. Configurations include:

- stepped hexports to accomodate small-diameter round diaphragms which are constrained primarily by the gasket rather than clamped between hex flange and washer
- hexports and washers with features to stretch the diaphragm during assembly
- two vs. three pieces of full-round Kapton to explore drift and life
- concave features cut into washer and hex flange to mimic the "bead" geometry which occurs during crimp

HEXPORT: As a result of the Elco meeting, we are planning to do a combined Impulse and Thermal-Cycle test of the 10821 hexports in order to have this information available if the customer request it when we inform them of the material change. This is likely to be combined with the evaluation of the Staples ultrasonic welded movable terminals, and one of the higher-pressure disc lots for 87PS conversion.

T1-003632

HIGHLIGHTS

Stephen B. Officer
Week Ending 92-02-21




FORD MTC'92 ELECTRONIC SPEED CONTROL DEACTIVATE PS

57 AND 87 VALIDATIONS: The decision has been made to significantly elevate the priority on these programs. All six are planned to progress more or less in parallel, but rearrangements can and will be made in order to finish 57PSL11-3 and 57PSFJ-3 to avoid jeopardizing the 920415 date promised to Ford. The internal motivation for completing the other four ASAP is to expedite the changeover of 57Lx-x business to 87Lx-x, which improves company profits. We are presently working on the detailed timing, and in parallel Jeff has begun to co-ordinate device builds and equipment requirements. Additional resources required will be determined by the timing charts. The elevated priority of these six programs tends to place everything else on the back burner.

SILENT DEVICE: Initial meetings have been held with Mechanization to begin to explore production techniques for piloting/pinning (calibration) silent devices. Pending test results on the first lot of silent ultra-low-differential discs from the disc dept., we'll begin looking at force- and pressure-deflection curves to determine characteristics that would be correlatable to pinning technique, such as inflection points in the hatched curves and determination of slope changes that define these points, etc. etc. Additionally, we'll be doing more work with the numerical approach originally proposed, where the ratio's of device differential vs. act. sigma across a range of calibration settings produce a local peak at the center of the pinning window. Mechanization has taken a first-pass look at an automatic machine to collect hatched-curve data on sensors to find the center of the pin window. The cost is very roughly \$88K.


DIAPHRAGM LIFE / MISC TESTING: Progress on the current lots of diaphragm-life experiments has been halted by the validations. Some progress has been made: we have discovered that features which stretch the Kapton during crimp leave asymmetric strain patterns in the diaphragm (not bad/better, but actually worse); the lots using small round diaphragms constrained by the gasket (rather than clamped by the hex flange/washer) look quite good, and we plan to eventually cycle a lot of these; and the two-vs-three full round Kaptons running to determine drift performance has produced a leaker in the two-pc lot.

Stan Horod has provided a bagful of miscellaneous 52PS and 57PS devices built in 1986. We plan to choose a few 32's from the bag (built on AMI) and open them up to look for landdrops.

Devices using ultrasonic-welded movable terminal assemblies and 10821 hexports have been built to undergo a hybrid Impulse and Thermal Cycle test. This is designed to provide data on the life of these components at temperature, pressure, and cycling extremes. The hybrid test was originally conceived to expedite individual Impulse and TC tests and distribute the temperature cycling throughout life cycling. This was abandoned.

While cycling production devices recently (looking for spring arm cracks at the bump) we had one PC device that went open-circuit at high temperature. It actually displayed continuity very briefly during release, which we attributed to bounce. The switching action seems to suggest the device was pinned very short. We opened the device, and discovered the base was calibrated to .092" (outside the .089" +/- .002 machine setting) and the T-pin was .142". Our calculations show this is at least .003" too short. We need to understand if thermal expansion is causing a pin-shift at high temp, and/or if temperature causes characteristic changes to the hatched curve. This may lead to revised room-temp pinning to compensate; shooting for the high end of the window instead of the center.

T1-003638


Engineering Specification

PART NAME

PART NUMBER

LET

PR

LET

PR

DATE

LET

PR

REVISIONS

DR

CR

REFERENCE

APPROVED DATA TO COMPLETE
SPEC. & RATE/TD
NECOKA/0079779002

PART NUMBER APPROVED BY
D.J. Pachal, 900916
CHECKED BY DETAILED BY

CONTRACTOR APPROVAL
SIGNATURE

CONTRACTOR APPROVAL SIGNATURE
4.7.1000 "P" 010
CONTRACTOR MFG.

MANUFACTURING MODEL

QUALITY CONTROL
D.J. Pachal, 900916
Signature

SUPPLY QUALITY INSPECTION
D.J. Pachal, 900916

MANUFACTURE APPROVAL
D.J. Pachal, 900916

▼ Control Test - Test Product And
Parties Product Engineering And
Tested Critical Characteristics
And Additional Checks, Dimensions
Or Function Or Function
After Determination Product
Product Specified Methods

FRAME 1.1 REV-A1

▼ MS-2370-97004-1A


PD 3947-a1

TI-009634


Sample #: _____

Layer Position: _____

Brake Fluid Side



Connector Side



3713 9716

Checklist:

[Redacted] 11/12/14 A270309W 11/12/14 A270309W 11/12/14 A270309W												8	9	10	11
F2V69	F2V69	F2V69	F2V69	F2V69	F2V69	F2V69	F2V69	F2V69	F2V69	F2V69	F2V69	F2V69	F2V69	F2V69	
F2H4AB	F2H4AB	F2H4AB	F2H4AB	F2H4AB	F2H4AB	F2H4AB	F2H4AB	F2H4AB	F2H4AB	F2H4AB	F2H4AB	F2H4AB	F2H4AB	F2H4AB	
9	13381	2059	2063	2083	2094	2094	2094	2094	2094	2094	2094	2094	2094	2094	
72°TC	93°TC	92°CV	92°TC												
103.939	178.045	107.627	109.341	103.652	103.217	105.832	105.7832	105.7832	105.7832	105.7832	105.7832	105.7832	105.7832	105.7832	
18.692-4	04.14.10.8	181.000-4	070.000-4	058.000-6	038.737-4	057.837-4	057.837-4	057.837-4	057.837-4	057.837-4	057.837-4	057.837-4	057.837-4	057.837-4	
New connection on existing hardware															
None	None	None	None	None	None	None	None	None	None	None	None	None	None	None	
9:30	10:30	11:00	4:00	1:00	2:00	3:00	4:00	5:00	6:00	7:00	8:00	9:00	10:00	11:00	
ising Seal	Marking	No Connector	No Connector	OK	No Connector										
ising Seal	Marking	No Connector	No Connector	OK	No Connector										
Minia	A	↑	OK	↑	OK	OK	↑	OK	↑	OK	↑	OK	↑	OK	
00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	
00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	
NJ	NJ	NJ	NJ	NJ	NJ	NJ	NJ	NJ	NJ	NJ	NJ	NJ	NJ	NJ	
↑	↑	↑	↑	↑	↑	↑	↑	↑	↑	↑	↑	↑	↑	↑	
NJ	NJ	NJ	NJ	NJ	NJ	NJ	NJ	NJ	NJ	NJ	NJ	NJ	NJ	NJ	
↑	↑	↑	↑	↑	↑	↑	↑	↑	↑	↑	↑	↑	↑	↑	
Blue Seal	Blue Seal	Blue Seal	Blue Seal	Blue Seal	Blue Seal	Blue Seal	Blue Seal	Blue Seal	Blue Seal	Blue Seal	Blue Seal	Blue Seal	Blue Seal	Blue Seal	
John Paul McLaughlin	John Paul McLaughlin	John Paul McLaughlin	John Paul McLaughlin	John Paul McLaughlin	John Paul McLaughlin	John Paul McLaughlin	John Paul McLaughlin	John Paul McLaughlin	John Paul McLaughlin	John Paul McLaughlin	John Paul McLaughlin	John Paul McLaughlin	John Paul McLaughlin	John Paul McLaughlin	
Positions relative to start of thread @ 12:00 viewed from connector end.															