

**EA02-025**

**FORD 10/27/03**

**APPENDIX N**

**BOOK 31 OF 61**

**PART 4 OF 4**

 Facsimile Transmittal

Date **14 AUG 00** No. of Pages **13**  
(Including this Transmittal)

To: **MATT BRACH**

From: **FRED PORTER**

Location \_\_\_\_\_ Room \_\_\_\_\_

Location \_\_\_\_\_ Room \_\_\_\_\_

**EXHIBENT**  
FAX No. **(248) 324-9199**

FAX No. **(313) 390-4145**

Telephone No. **(248) 324-9112**

Telephone No. **(313) 845-3722**

Comments:

**MATT For My Phone MESSAGE,  
PLEASE REVIEW AND COMMENT ON  
THIS PROCEDURE**

**THANKS  
FW**

Gen. Adv. 1552

**SCHIRMEISTER AJAMIE**

A REGISTERED LIMITED LIABILITY PARTNERSHIP  
PENNZON PLACE - SOUTH TOWER  
711 LOUISIANA, SUITE 2100  
HOUSTON, TEXAS 77002  
(713) 860-1600  
FAX (713) 860-1609  
www.schir-aj.com

DAVID J. RYER  
djr@schir-aj.com

015.12  
015.13

August 10, 2000

BY FACSIMILE

Mr. Eric Mayer  
Susan Godfrey, L.L.P.  
1000 Louisiana, Suite 5100  
Houston, Texas 77002

Mr. Jeff Mancke  
Brown McCarroll & Oaks Hartline, L.L.P.  
111 Congress Avenue, Suite 1400  
Austin, Texas 78701

Re: Cause No. 35650-S; [REDACTED] v. Ford Motor Company, et al.; In the  
329<sup>th</sup> Judicial District Court of Wharton County, Texas

Cause No. 9905441; [REDACTED] v. Ford Motor Company, et al.; In the  
68<sup>th</sup> Judicial District Court of Dallas County, Texas

Gentlemen:

Enclosed is a copy of the protocol submitted with the agreement of all defendants in the *Gacron* case. I propose that we use this protocol as the basis of the protocol for the massive switch disassembly to take place in Exponent in Farmington Hills beginning on August 21, 2000. I am unclear as to whether there is any intent to x-ray these switches. If so, the enclosed protocol begins with an x-ray segment, followed by the disassembly segment.

In addition, I believe we need to add two steps to the disassembly segment, which were included in the actual disassembly protocol employed in our recent disassembly of the Krupp, Raska and Payne switches:

- (8a) To preserve the orientation of the Kapton diaphragm and of each layer within the Kapton diaphragm, mark the same successive corner of each layer of the Kapton diaphragm, using colored marking or paint pins, beginning with a yellow dot on the

SCHIRMEISTER AJAMIE L.L.P.


August 10, 2000

corner of the first Kapton layer next to the hex port side, followed by a pink/red dot on the same successive corner of the center layer closest to the hex port side, and ending with a green dot on the same successive corner of the third layer on the side closest to the hex port side;

- (8b) Then with a razor blade, if possible, carefully separate the three layers of the Kapton diaphragm into its three separate layers. Lay each layer on a clean, dry photographic background and photograph each side of each layer. Then inspect each side of each layer through a binocular electronic microscope with digital imaging capability and record the images.

Please let me have your thoughts on this proposed as soon as possible as to whether we can agree to this format as the basic initial protocol. Should you have any questions, please do not hesitate to contact me at (713) 860-1600.

Sincerely,



Dana S. Spect

cc: Andrew Schirmeister

Sent by: SCHIRRMESTER ALANIE LLP

7138801688

08/11/00 10:05AM; JUDGE #348; Page 4/13

Received: 8/11/00 2:10PM

7138801688 - SCHIRRMESTER ALANIE LLP; Page 9

88/10/2000 14:16 7137818225

INMETECH INC

PAGE 82

Sent by: SCHIRRMESTER ALANIE LLP

7138801688

08/02/00 2:00PM; JUDGE #408; Page 8/9

NY. 8-8888

JORDAN GRAYSON PNEY LLP RITY

10.100 P.04

**CAUSE NO. DC-98-160**

**OSIEL GONZALEZ**

**IN THE DISTRICT COURT**

**vs.**

**OF STARR COUNTY, TEXAS**

**M & T MOTORS, INC. and/or  
M & T MOTORS; FORD MOTOR  
COMPANY and  
UNITED TECHNOLOGIES  
AUTOMOTIVE, INC.**

**220th JUDICIAL DISTRICT**

**ORDER GRANTING FORD MOTOR COMPANY'S MOTION FOR  
FURTHER ORDERS REGARDING INSPECTION OF EVIDENCE AND  
FOR REPEATED INSPECTION OF EVIDENCE FOR REPEATED  
INSPECTIONS IN ORDER TO CONDUCT SAME AFTER SUCH  
INSPECTION**

**CAME ON TO BE HEARD, Ford Motor Company's Motion for Further  
Orders Regarding Inspection of Evidence and For Relief Extension of Deadline  
For Experts' Depositions In Order to Conduct Same After Such Inspections, and  
The Court, having read the Motion, finds that the Motion is meritorious as stated below  
and should be GRANTED;**

**IT IS, THEREFORE, ORDERED** that within three days of this hearing,  
Plaintiff's counsel shall provide at least three dates prior to trial on which the  
inspection of the component parts removed from vehicles in this case can take  
place at Plaintiff's expert's facility, and dates on which Plaintiff's experts will be  
available for deposition.

**IT IS FURTHER ORDERED** that within three days of being provided such  
dates, all parties shall promptly inform all other parties of their representatives'  
availability on those dates, and the inspections shall promptly be scheduled in  
writing for the first of those dates on which all of those representatives can be  
present;

**IT IS FURTHER ORDERED** that the inspections shall take place at Plaintiff's experts' laboratory on the date scheduled and under the following conditions:

First, Plaintiff's experts shall provide an x-ray machine in which x-rays of the part using the following protocol:

- (1) Work with X-Ray Technician to carefully remove damaged component from evidence packaging and place it on the X-Ray machine staging platform.
- (2) Activate X-Ray machine and obtain initial image of component.
- (3) Carefully reposition damaged component on the X-Ray machine's staging platform to achieve a view of the part which is rotated 90 degrees from its original position in the horizontal plane.
- (4) Repeat Step (2), above, for this positioning of the damaged component.
- (5) Carefully reposition damaged component on the X-Ray machine's staging platform to achieve a view of the part which is 90 degrees from its position in Step (3), above, in the vertical plane (i.e. set the part on its side).
- (6) Repeat Step (2), above, for this positioning of the damaged component.
- (7) Based on observations made up to this point, carefully reposition damaged component to other positions in order to obtain as complete and accurate rendering of the internal structure of the damaged component as possible.
- (8) Repeat Step (2), above for all other positions viewed in Step (7), above.

08/11/00 10:08AM; Infor\_4040; Page 8/12  
 Sent by: SCHINWEISTER AJAMIE LLP 7188801889;  
 Received: 08/11/00 2:11PM;  
 08/18/2000 14:18 7137018228  
 Sent by: SCHINWEISTER AJAMIE LLP 7188801889;  
 08/02/00 2:11PM; Infor\_4040; Page 8/9  
 08/11/00 9:28AM; RESQUE COLVIN CHEVET LLP ATTY NO.100 P.8/8

- (9) Carefully remove damaged component from the X-Ray machine staging platform and place it back in the evidence package.
- (10) Confirm that x-rays as developed provide satisfactory image of internal components of part before any disassembly begins

**IT IS FURTHER ORDERED** that thereafter, Plaintiff's experts conduct disassembly of the parts using the following protocol:

- (1) Several steps will be taken before disassembling the switch. First, electrical resistance measurements will be taken from terminal to terminal and each terminal to the hot post. In addition, the base and part being will be visually inspected for contamination. If there is any contamination present, samples will be taken and preserved for testing. At all points throughout the process described herein, samples will be taken of any observed contamination, to be preserved for later testing.
- (2) Remove component from evidence packaging and use a knife with paring tool or high speed grinder to carefully remove outer retaining ring material to a sufficient extent to allow the internal parts of the component to be removed.
- (3) Remove switch body half of part with knife or use disassembler of switch contact pieces.
- (4) Remove coil.
- (5) If it is agreed to by all parties, the procedure for assembly can also be disassembled by the same procedure described in Section III-1 above. Separate and photograph pieces as described above.
- (6) Separate outer retaining ring from hot post.

Sent by: SCHIRMHEISTER AJAMIS LLP

7188801889;

08/11/00 10:08AM; JAMES 4048; Page 7/13

Received: 8/10/00 2:17PM;

7187618888 - SCHIRMHEISTER AJAMIS LLP; Page 8

08/10/2000 14:16 7137618888

INMETECH INC

PAGE 08

Sent by: SCHIRMHEISTER AJAMIS LLP

7138801889;

08/08/00 2:10PM; JAMES 4008; Page 0/0

FRV 2.0000 0.0000

SHREVE CALVIN B REY LLP ATTY

Page 0  
P.0-0

- (7) Separate screws disc assembly from hex part.
- (8) Separate Kapton seals from hex part or procedure disc assembly (whichever places they are adhering to at this point).
- (9) Place all pieces removed on a clean, dry photographic background space for the purpose of still photography. Try to leave all pieces in their original orientation.
- (10) Perform any visual inspection required by any of the parties present. Trucon/Or microscope with photographic capabilities will be available.
- (11) Clearly package and identify each part with an evidence tag and return them to the original container of this evidence.

IT IS FURTHER SPECIFICALLY ORDERED that no disassembly may take place until and unless a readable x-ray image of the interior of each part has been obtained, or by unanimous agreement of the parties;

IT IS FURTHER ORDERED that an extension of the discovery period in this case will take place as to the depositions of the parties' experts, in order that they may take place after the inspections and when the experts are available.

SIGNED FOR ENTRY this \_\_\_\_\_ day of \_\_\_\_\_ 2000.

JUDGE FREDERICK

P.003/1

**COMPONENT INSPECTION PROTOCOL USING X-RAY MACHINE**  
**In the Matter of Governor v. Ford Motor Co. (Part of LAMS 940-9843)**

The following steps describe the equipment and procedure to collect internal structural information from damaged component parts removed from the vehicle in this matter in an attempt to verify the identity and condition of the internal pieces of the component.

**X-RAY TESTING PROCEDURE**

1. Work with X-ray Technician to carefully remove damaged component from evidence packaging and place it on the X-ray machine staging platform.
2. Activate X-ray machine and obtain initial image of component.
3. Carefully reposition damaged component on the X-ray machine's staging platform to achieve a view of the part which is rotated 90° from its original position in the horizontal plane.
4. Repeat Step 2 above for this positioning of the damaged component.
5. Carefully reposition damaged component on the X-ray machine's staging platform to achieve a view of the part which is 90° from its position in Step 3 above in the vertical plane (i.e., not the part on its side).
6. Repeat Step 2 above for this positioning of the damaged component.
7. Based on observations made up to this point, carefully reposition damaged component to other positions in order to obtain as complete and accurate rendering of its internal structure of the damaged component as possible.
8. Repeat Step 2 above for all other positions viewed in Step 7 above.
9. Carefully remove damaged component from the X-ray machine staging platform and place it back in the evidence package.
10. Confirm that x-rays as developed provide satisfactory image of internal component of part before any discussion begins.

XXXXXXXXXXXX

3713 9805

**DISASSEMBLY AND VISUAL INSPECTION PROCEDURE**

After all X-ray inspection is complete, several steps will be taken before disassembling the switch. First, electrical resistance measurements should be taken from terminal to terminal and each terminal to the hex part. In addition, the base and part flange will be visually inspected for contamination. If there is any communication present, samples will be taken and preserved for testing. At all points throughout the process described herein, samples will be taken of any observed contamination, to be preserved for later testing.

Next, the component parts can be disassembled using a procedure similar to the following or one determined agreeable to all parties present at the time of inspection:

1. Remove component from evidence packaging, secure the switch in a vice, and use a high speed grinder to carefully remove outer retaining ring material to a sufficient extent to allow the internal parts of the component to be removed. Two vertical slices across the outer edge ring, 180° apart will allow the outer ring to be removed.
2. Remove switch body half of part with little or no disturbance of switch contact pieces.
3. Remove seal.
4. If it is agreed to by all parties, the pressure disc assembly can also be disassembled by using a knife. Separate and photograph pieces as described above.
5. Separate pressure disc assembly from hex part.
6. Separate Kapton seals from hex part or pressure disc assembly (whichever pieces they are adhering to at this point).
7. Place all pieces removed on a clean, dry photographic background space for the purpose of cell photography. Try to locate all pieces in their original orientation.
8. Perform any visual inspection required by any of the parties present. Tricocular microscopes with photographic capabilities will be available.
9. Clearly package and identify each part with an evidence tag and return them to the original container of this evidence.

SENT BY: SCHIRMEISTER AJAMIE LLP

710001000;

08/11/00 10:07AM; 0348; Page 10/19

Received: 8/10/00 2:16PM

710001000 - SCHIRMEISTER AJAMIE LLP; Page 8

08/10/2000 14:16 7107010236

INTECH INC

PAGE 00

SENT BY: SCHIRMEISTER AJAMIE LLP

710001000;

04/07/00 11:01AM; 0010; Page 4/10

08/10/2000 07:47 7107010236

1 000 041 2170 - SCHIRMEISTER AJAMIE LLP; Page 8

08/10/2000 11:07AM

SCHIRMEISTER AJAMIE LLP

08/10/2000 11:07AM

**COMPARISON INSPECTION PROCEDURE USING X-RAY MACHINE**  
**IN THE MATTER OF CHRYSLER CREDIT CORPORATION (PART OF LITIGATION 04-0004)**

The following steps describe the equipment and procedure to collect internal structural information from damaged component parts recovered from the vehicles in this matter in an attempt to verify the identity and condition of the internal pieces of the components.

**(1) NEED FOR CARE**

Need believes that X-rays are needed to document, as well as possible the location of the parts at issue prior to disassembly of the recovered parts, since in their fragile condition, disassembly may result in loss of evidence on the interior of the switches, no matter how carefully disassembly is attempted.

**(2) X-RAY TESTING PROCEDURE**

- (1) Work with X-Ray Technician to carefully remove damaged component from evidence packaging and place it on the X-Ray machine cradling platform.
- (2) Activate X-Ray machine and obtain initial image of component.
- (3) Carefully position damaged component on the X-Ray machine's cradling platform to achieve a view of the part which is rotated 90 degrees from its original position in the horizontal plane.
- (4) Repeat Step (2), above, for this positioning of the damaged component.
- (5) Carefully position damaged component on the X-Ray machine's cradling platform to achieve a view of the part which is 90 degrees from its position in Step (3), above, in the vertical plane (i.e. let the part rest on its side).
- (6) Repeat Step (2), above, for this positioning of the damaged component.
- (7) Based on observations made up to this point, carefully reposition damaged component to other positions in order to obtain as complete and accurate rendering of the internal structure of the damaged component as possible.

08/11/88 FRI 11:30 FAX 512 518 1101  
 7128001000;  
 08/11/88 10:07AM; JAMES 8348; Page 11/13

7128001000 - SCHIRMWEISTER AJAMIK LLP; Page 0  
 INATECH INC PAGE 09  
 08/07/88 11:58AM; JAMES 8348; Page 8/13

7128001000;  
 1 888 841 8178 - SCHIRMWEISTER AJAMIK LLP; Page 7  
 JORDAN COLVEN O'NEIL LLP NY NY NO. 002 P.7/7

- (8) Repeat Step (2), above for all other positions viewed in Step (7), above.
- (9) Carefully remove damaged components from the X-Ray machine staging platform and place it back in the evidence packaging.
- (10) Confirm that views as developed provide satisfactory image of internal components of part before any disassembly begins.

**(11) DISASSEMBLY AND VISUAL INSPECTION PROCEDURE**

After all X-Ray inspection is complete, the component parts can be disassembled using a procedure similar to the following or one determined agreeable to all parties present at the time of inspection:

- (1) Remove components from evidence packaging and use a lathe with parting tool or high speed grinder to carefully remove outer retaining ring mounted to a sufficient extent to allow the internal parts of the component to be removed.
- (2) Remove switch body half of part with care to avoid disturbance of switch contact plates.
- (3) Remove seal.
- (4) Separate outer retaining ring from hat part.
- (5) Separate pressure disc assembly from hat part.
- (6) Separate Kipon seals from hat part or pressure disc assembly (whichever plates they are adhering to at this point).
- (7) Place all plates removed on a clean, dry photographic background paper for the purpose of all photography. Try to locate all plates in their original orientation.
- (8) If it is agreed to by all parties, the pressure disc assembly can also be disassembled by the same procedure described in Section 11-1 above. Separate and photograph plates as described above.
- (9) Perform any visual inspection required by any of the parties, present. Microscopes will be available.
- (10) Cleanly package and identify each part with an evidence tag and return them to the original container of this evidence.

AUG 14 '08 12:25 FR CHASSIS ELECTRONICS 313 398 4145 TO 92483249199 P.12/13  
 08/11/00 FAX 11:30 FAX 512 478 1101 Brown McCarroll 412  
 Sent by: SCHIRMWEISTER AJAMER LLP 7137818386; 08/11/00 10:05AM; #348; Page 12/13  
 Received: 8/10/0 8:28PM 7137818386 -> SCHIRMWEISTER AJAMER LLP; Page 10  
 08/18/2008 14:16 7137818386 INMTECH INC PAGE 18  
 with cc: SCHIRMWEISTER AJAMER LLP (7137818386); 08/07/00 11:26AM; #318; Page 8/12

3/14

**CAUSE NO. C-4178-98-P**

<b>PAILINE G. GONZALEZ and JOSE NOE GONZALEZ, SR.</b>	•	<b>IN THE DISTRICT COURT</b>
<b>vs.</b>	•	
<b>VAN BURELLO MOTORS, INC.; FORD MOTOR COMPANY; and UNITED TECHNOLOGIES AUTOMOTIVE, INC.</b>	•	<b>OF HIDALGO COUNTY, TEXAS</b>
	•	
	•	<b>332nd JUDICIAL DISTRICT</b>

**AGREED ORDER FOR PROTECTION AND  
PRESERVATION OF EVIDENCE**

COME NOW the Parties to this matter and have agreed as to the following conditions for protection and for preservation of evidence.

**IT IS THEREFORE ORDERED: THE FOLLOWING PROVISIONS APPLY TO THIS VENUE AS OF TODAY'S DATE.**

1. The vehicle at issue in this lawsuit, a 1993 Lincoln Town Car, VIN #1LNLM81WXPY645376. ("the Ford vehicle") is currently located in the warehouse owned by Plaintiff's counsel Ramon Garcia at 3801 North Business 281, Edinburg, Texas. Each party agrees not to engage in any activities or to give consent for any activities which would result in the loss of any part of the vehicle, specifically including but not limited any destructive inspections and/or testing, except as set out in the terms of this Agreed Order.

2. All removed parts will remain at the warehouse location set out above absent written notice to all parties. No parts will be removed from the vehicle in a way that damages the vehicle's overall integrity (i.e., by cutting, tearing, etc.) without notice to all parties as stated in paragraph 4 below. **ANY PART WHICH HAS BEEN REMOVED BY ANY PARTY SHALL BE MADE AVAILABLE AND PROTECTED IN ACCORDANCE WITH THE TERMS OF THIS ORDER.**

3. If expert witnesses are retained by any party in the litigation, they shall be allowed reasonable access to any parts removed from the vehicle for non-destructive

sent by: SCHIRMEISTER AJAMIE LLP

7138801899;

08/11/00 10:08AM; JUDGE #348; Page 13/13

Received: 8/10/00 14:15

7137818235

7138801899; SCHIRMEISTER AJAMIE LLP; Page 11

DMETECH INC

Page 11

04/07/00 11:27AM; JUDGE #318; Page 10/13

inspections and testing upon reasonable notice. The parties shall agree as to the location/method of delivery to that location, and any other terms of the inspection and/or testing.

4.

If any party desires to perform any testing or destructive handling of any part of or of the overall vehicle, such testing or destructive handling will take place upon a reasonable date and time after sufficient time to allow the filing and hearing of any motions to postpone or modify the parameters for such activities. All other parties will be given notice of the date of the testing and/or destructive handling and will receive a reasonably timed invitation to have a representative present. At least seven (7) days prior to the activity, the party performing same will produce in writing a description of the activities to be performed, and the equipment to be used. The testing or destructive handling will take place at a place and time that will permit documentation by photographs and/or video recording. No party shall use audio recording devices, separately or as a part of video recording, absent court order.

5.

If the parties cannot agree upon circumstances under which the vehicle should be tested or destructively handled, the parties must seek a clarifying Order before any unilateral attempt test or destructively handle the vehicle.

SIGNED this the 14 day of Feb, 2000.

  
JUDGE PRESSING

NOTICE TO THE PUBLIC AND FOR DISTRIBUTION OF COPIES

Page 1

3713 9818

**Matthew Brach**

---

**From:** Reimers, Steve (S.J.) [sreimers@ford.com]  
**Sent:** Wednesday, September 13, 2000 1:17 PM  
**To:** 'Matthew Brach'  
**Subject:** FW: Sample Vials

fyi

> -----Original Message-----

> **From:** LaRouche, Steve (S.)  
> **Sent:** Wednesday, September 13, 2000 12:37 PM  
> **To:** Reimers, Steve (S.J.)  
> **Subject:** Sample Vials

> Steve: I got your phone message about a source for sample vials. We  
buy  
> them from Fisher Scientific (order line: 1-800-766-7000).  
> We use 20 ml borosilicate scintillation vials with urea caps that have  
> cone shaped plastic liners (these cap liners won't react with brake  
> fluid). The Fisher catalog number is 03<sup>2</sup>337-7. They cost  
approximately  
> \$150 for a case of 500.

>  
>  
> Steve LaRouche  
> North American Materials Engineering and Testing  
> Metallurgy Section, Central Laboratory, Room N410  
> Phone: (313) 845-4876 FAX: (313) 322-1614  
> Internet: mailto:slarouch@ford.com  
> Central Lab Web Page: <http://www.dearborn3.ford.com/met/north.htm>

# Exponent

Failure Analysis Associates

Exponent  
39100 Country Club Drive  
Farmington Hills, MI 48331

Telephone 248-324-9100  
Facsimile 248-324-9199  
www.exponent.com

## F A X C O V E R S H E E T

To: Steve Reimers 313 390 4145  
Name Fax  
Ford Motor Co. 3/7/00  
Company Date  
From: Rob Panek 248 324 9112  
Name Telephone  
Title Fax  
Olympus Quote - F/T  
Subject

Total pages including this page.

E-mail

If you do not receive all of the pages indicated, please call \_\_\_\_\_  
at ( ) \_\_\_\_\_ as soon as possible.

**PLEASE NOTE:** The information contained in this facsimile transmission is intended to be sent only to the stated recipient of the transmission. If the reader of this message is not the intended recipient's agent, you are hereby notified that any dissemination, distribution or copying of the information contained in this facsimile transmission is prohibited. You are further asked to notify us of the error as soon as possible at the telephone number shown above and to return the facsimile documents to us immediately by mail at the address shown above. Thank you.

**SPECIAL INSTRUCTIONS:**

3713 9012

**OLYMPUS AMERICA INC.  
INDUSTRIAL PRODUCTS GROUP**2 Corporate Center Drive  
Melville, NY 11747

1-800-798-5782 Fax: 1-516-844-5626

**Quotation**

ROB PANECK

EXONENT FAILURE ANALYSIS INC

39108 COUNTRY CLUB DR

FARMINGTON HILL, MI 48331

Phone: [1] 248-324-9112

Fax: [1] 248-324-9199

Questions? Please call Andy Kopec, Sales Rep (248) 698-8070

Quotation Number: 541030011

Date 03/02/2000

Quote Expires on: 03/31/00

Model	Item #	Description	Price	Qty	Extend
K27-16-16-80	2917D	Mini Borescope 2.7mm diameter (.106"), working length 7.32", DOV 60 degrees, Fore-oblique	\$3,451.00	1	\$3,451.00
MC-R45F	8315C	C-mount adapter for K27, K17, SES-1711S-2, K12 Miniboscopes (focusing).	\$659.00	1	\$659.00
SONY PVM-97	459H	9" Diagonal, High Resolution Black & White Monitor; 600 TVL (H) Resolution; audio line in/out; size: 8.8"x9"x9.5"; wgt: 12.1 lbs; power: 120VAC, 50/60 Hz.	\$464.00	1	\$464.00

Please fax and mail your Purchase Order to:

Olympus America Inc. - IPE

1 Corporate Center Drive

Melville, NY 11747

(916) 798-6392

(800) 844-5782 F.S.

After Hours Call K

Not 24 Hours

24-Hour Fax ADP

Origin. We will ship via Federal Express Day 3 unless you

specify at time of order. Federal Express Priority 1 and UPS Ground are also available.

**TOTAL \$4,574.00**

Terms:

Net 30 Days

FOB

Melville

NY

All prices quoted are U.S. list price and pertain to equipment intended for use in the U.S. and warranty support from Olympus America Inc. Prices are not valid for overseas support. Please notify your Olympus representative should this

3713 9813

\* \* \* COMMUNICATION RESULT REPORT ( MAR. 7.2000 4:42PM ) \* \* \*

FILE MODE	OPTION	ADDRESS (GROUP)	TTI RESULT	EXONENT PAGE
852 MEMORY TX		13133904145-9858	OK	P. 2/2

REASON FOR ERROR

E-1) HANG UP OR LINE FAIL  
 E-3) NO ANSWER  
 03/02/00 THU 15:24 FAX 818 844 8628

E-2) BUSY  
 E-4) NO FACSIMILE CONNECTION  
 OLYMPUS REGION #

002

**OLYMPUS AMERICA INC.**  
**INDUSTRIAL PRODUCTS GROUP**  
 2 Corporate Center Drive  
 Melville, NY 11747  
 1-800-798-5782 Fax: 1-516-844-5828



**Quotation**

ROB PANBECK  
 EXPONENT FAILURE ANALYSIS INC  
 39100 COUNTRY CLUB ER.  
 FARMINGTON HILL, MI 48331  
 Phone: (1) 248-324-9112  
 Fax: (1) 248-324-9199

Questions? Please call Andy Kopsco, Sales Rep (248) 888-8070

Quotation Number: 541030011

Date 03/02/2000

Quote Expires on: 03/31/00

Model	Qty	Description	Price	Unit	Extnd
K27-18-18-80	28770	Mini Binoculars 2.7mm diameter (.105"), working length 7.32", DOV 80 degrees, Fore-oblique	\$3,481.00	1	\$3,481.00
MC-R48F	83110	C mount adapter for K27, K17, 855-17-118-2, K12 Minibinoculars (focusing).	\$869.00	1	\$869.00
SONY PVM-87	44810	8" Diagonal, High Resolution Black & White Monitor, 800 TVL (H) Resolution; audio: line input; size: 8.0" x 6.6"; wgt: 12.1 lb; power: 120VAC, 60/50 Hz.	\$484.00	1	\$484.00
					3713 9814

# OLYMPUS

OLYMPUS AMERICA INC.  
ENDSCOPE DIVISION  
INDUSTRIAL PRODUCTS GROUP

TWO CORPORATE CENTER DRIVE  
MELVILLE, NEW YORK  
11747-8187

TEL. (516) 844 8000  
FAX (516) 844 8626

03/02/2000

ROB PANECK  
EXPONENT FAILURE ANALYSIS INC  
39100 COUNTRY CLUB DR  
FARMINGTON HILL, MI 48331  
Phone: (1) 248-324-9112  
Fax: (1) 248-324-9199

Quotation # 541030011

Dear Mr. Paneck:

Thank you for providing Olympus with the opportunity to quote our Industrial Imaging products as listed on the enclosed quotation.

As a service to our customers, we provide set-up, maintenance and training at no additional cost. To request this service, please call when all your equipment has been received.

We look forward to having you as a valued customer. Please feel free to contact me if you have any questions.

Sincerely,

*Andy Kypiec*  
Andy Kypiec  
Olympus America Inc.

# OLYMPUS

OLYMPUS AMERICA INC.  
ENDSCOPE DIVISION  
INDUSTRIAL PRODUCTS GROUP

TWO CORPORATE CENTER DRIVE  
MELVILLE NEW YORK  
11747-2157

TEL (516) 844 8626  
FAX (516) 844 8620

01/14/2000

MR. ROB PANECK  
EXPONENT FAILURE ANALYSIS  
9100 COUNTRY CLUB DR  
FARMINGTON HILL, MI 48331  
Phone: 248-324-9112  
Fax: 248-324-9199

Quotation # 541010047


Dear Mr. Panack:

Thank you for providing Olympus with the opportunity to quote our Industrial Imaging products as listed on the enclosed quote.

As a service to our customers, we provide set-up, maintenance and training at no additional cost. To request this service, please call when all your equipment has been received.

We look forward to having you as a valued customer. Please feel free to contact me if you have any questions.

Sincerely,

  
Andy Kopec  
Olympus America Inc.

**OLYMPUS AMERICA INC.  
INDUSTRIAL PRODUCTS GROUP**2 Corporate Center Drive  
Meville, NY 11747

1-800-798-5782 Fax: 1-516-844-5828

**Quotation**MR. ROB PANECK  
EXPONENT FAILURE ANALYSIS  
39180 COUNTRY CLUB DR  
FARMINGTON HILL, MI 48331  
Phone: 248-324-9112  
Fax: 248-324-9199

Questions? Please call Andy Kopeck, Sales Rep (248) 898-8070

Quotation Number: 641010047

Date 01/14/2000

Quote Expires on: 03/14/2000

Item #	Model	Description	Price	Qty	Extend
K12-09-15-53	2917G	Mini Borescope 1.2mm diameter (.47"), working length 3.78", DOV 53 degrees, Fore-Oblique	\$3,626.00	1	\$3,626.00
MC-R45F	6315C	C mount adapter for K27, K17, SES-1711S-2, K12 Miniborescopes (focusing).	\$659.00	1	\$659.00
SONY PVM-97	4595	9" Diagonal, High Resolution Black & White Monitor; 900 TVL (H) Resolution; audio: line in/out; size: 8.6"x9"x9.8"; wgt: 12.1 lbs; power: 120VAC, 50/60 Hz.	\$464.00	1	\$464.00
KC-75	4593CA	KC-75 Low-light B&W camera body set; 1/2" CCD; C-mount; 570 TVL (H) X 485 TVL (V) resolution; Size: 1.8" X 1.2" X 3.6", Wt: 5 oz; Power: 12VDC	\$1,324.00	1	\$1,324.00

Please fill and mail your Purchase Order to:

Olympus America Inc.  
2 Corporate Center Drive  
Meville, NY 11747(800) 798-5782  
(516) 844-5828 Fax  
Attention: DetailPd. 28 Days  
30-60 Days ARO

Origin: We will ship via Federal Express Day 2 unless you

otherwise or direct order. Federal Express Priority 1 and UPS  
Ground are also available.


TOTAL \$6,073.00

*All prices quoted are U.S. list price and pertain to equipment intended for use in the U.S. and warranty support from Olympus America Inc. Prices are not valid for overseas support. Please notify your Olympus representative should this*

3713 9817

# OLYMPUS INDUSTRIAL

## Small-diameter fiberscopes and borescopes



**Need access ports as small as these...**

*Actual diameter*

0.84 mm

1.2 mm

1.75 mm

2.4 mm

2.7 mm

3.6 mm

4.1 mm

A wide range of Olympus flexible fiberscopes and borescopes are available in small diameters — 4 mm and under — as small as 0.84 mm for Ultra Thin fiberscopes and 1.2 mm for Miniborescopes. Their availability in many different sizes, working lengths, directions of view, fields of view, and magnification offer a flexibility to inspect the tightest, most cramped and difficult work sites.

**Ultra Thin fiberscopes.** These compact, high-resolution instruments range in diameters from

0.84 mm to 4.1 mm, with working lengths from 254 mm (10 in.) to 1280 mm (50.4 in.). Flexibility and two-way articulation (in all but the 0.84 mm diameter model)

make it easy to snake the insertion tube around obstacles. Unlike larger fiberscopes, Ultra Thin fiberscopes have a moisture-proof outer covering of PVC instead of a metallic sheath, for smooth access and flexibility in these small diameters.



*Ultra Thin fiberscope and R.K.-3 light source.*

*Creating the Vision*

Olympus line of small-diameter rigid borescopes consists of 4 mm diameter borescopes and 2.7 mm, 1.75 mm, 1.2 mm diameter Miniborescopes.

Small-diameter 4 mm borescopes have hybrid rod and convex lens systems for the brightest possible images, with a decided spatial effect that approaches "3-D."

New, Improved light guide bundles bathe the subject in a brilliant flood of light despite the compact size. Directions of view are forward and side. Side-viewing scopes have an orbital scan of 260 degrees, which gives the inspector quick access to a large area at the turn of a control.

Miniborescopes have a patented single-fiber Selfoc® rod lens. They produce brilliant, highly magnified images. They have an excellent depth of field with good focus from 1 mm to 40 mm. Working lengths for Miniborescopes range from 96 to 188 mm (3.8 to 7.4 in.).



Miniborescope K27-18-90-82 used with a video system.

### SPECIFICATIONS - Ultra Thin Fiberscopes

Model	Max. outer diam.	Working length	Direction of view DOV	Field of view FOV	Depth of field DOF	Articulation: up, down/right, left
IF4D4-15	4.1mm (0.161in)	1270mm (49.9in)	Direct	65°	5-80mm	120°/NA
IF4S4-16	4.1mm (0.161in)	1280mm (50.4in)	Side	65°	4-40mm	120°/NA
EMF-P3	3.8mm (0.149in)	255mm (10.0in)	Direct	65°	5-50mm	130°/NA
IF2D4-8	2.4mm (0.094in)	510mm (24.0in)	Direct	76°	2-50mm	120°/NA
IF2D4-14	2.4mm (0.094in)	1178mm (46.0in)	Direct	76°	2-50mm	120°/NA
IF8PD4-6	0.84mm (0.025in)	480mm (18.9in)	Direct	62°	1-50mm	NA
IF8PD4-11	0.84mm (0.025in)	960mm (38.0in)	Direct	58°	1-50mm	NA
Insertion tube	Stainless steel braid; PVC outer cover, waterproof					
Focus	Fixed					

IF8PD4: PTFE outer cover, waterproof

### SPECIFICATIONS - 2.7 mm Miniborescopes

Model	Working length	Direction of view DOV	Field of view FOV	Depth of field DOF
K27-18-00-82	188mm (7.32in)	Direct	62°	1-40mm
K27-18-15-80	188mm (7.32in)	Fore-obl. (15°)	60°	1-40mm
K27-18-90-82	188mm (7.40in)	Side	62°	1-40mm
Maximum outer diameter	2.70mm (0.106in)			
Insertion tube	Stainless steel, waterproof			
Light guide	Integral light guide			

### SPECIFICATIONS - 1.75 mm Miniborescopes

Model	Working length	Direction of view DOV	Field of view FOV	Depth of field DOF
K17-18-00-82	188mm (7.32in)	Direct	62°	1-40mm
K17-18-15-80	188mm (7.32in)	Fore-obl. (15°)	60°	1-40mm
K17-18-90-82	188mm (7.40in)	Side	62°	1-40mm
SE8-1711S-2*	105mm (4.13in)	Side	55°	1-40mm
Maximum outer diameter	1.75mm (0.069in)			
Insertion tube	Stainless steel, waterproof			
Light guide	Integral light guide			

\* Special application scope—For applications that require minimum parallel between the objective lens window and the illuminator window

### SPECIFICATIONS - 4 mm Borescopes

Model	Working length	Direction of view DOV	Field of view FOV*	Depth of field DOF
D840-087-000-80	70mm (2.8in)	Direct	80°	4mm→
D840-016-000-80	150mm (5.9in)	Direct	80°	4mm→
D840-024-000-80	240mm (9.4in)	Direct	80°	4mm→
D840-032-000-80	320mm (12.6in)	Direct	80°	4mm→
G040-011-090-50	110mm (4.3in)	Side	50°	2mm→
G040-020-090-50	200mm (7.9in)	Side	50°	2mm→
G040-028-090-50	280mm (11.0in)	Side	50°	2mm→
G040-037-090-50	370mm (14.6in)	Side	50°	2mm→
Maximum outer diameter	4.10mm (0.161in)			
Orbital scan	260°, not available on direct models			
Insertion tube	Stainless steel, waterproof			
Light guide	Separate light guide is required			
* FOV	80° (direct only) and 30° FOV optionally available			

### SPECIFICATIONS - 1.2 mm Miniborescopes

Model	Working length	Direction of view DOV	Field of view FOV	Depth of field DOF
K12-08-00-45	96mm (3.78in)	Direct	45°	1-40mm
K12-08-15-63	96mm (3.78in)	Fore-obl. (15°)	62°	1-40mm
Maximum outer diameter	1.20mm (0.047in)			
Insertion tube	Stainless steel, waterproof			
Light guide	Integral light guide			


# OLYMPUS INDUSTRIAL

Olympus Corporation, Industrial Fiberoptics Division  
4 Nevada Drive, Lake Success, N.Y. 11042-1178  
Tel: 516-488-8888, 800-448-6280 FAX: 516-488-9879

#### Regional Offices:

Los Angeles, Tel. 714-670-8500 • Cleveland, Tel. 216-779-9955  
Atlanta, Tel. 404-428-1678 • Dallas, Tel. 214-588-9987  
Canadian Dist: Cassen Industrial, Toronto, Tel. 416-479-4100

Printed in USA, SM 702. Specifications subject to change without notice.




**Material Move Request** FOR INTRA-COMPANY MOTOR VEHICLE SHIPMENTS ONLY  
(Not to Be Used by Common Carrier)

0549503

FROM: <b>BLDG 5</b>		TO: <b>EXPORT FAILURE ANALYSIS</b>	
Department	Department No.	Department	Department No.
	<b>7402</b>		
Building: <b>AVT5</b>		Building	
Check One: <input type="checkbox"/> Floor <input type="checkbox"/> Bay <input type="checkbox"/> Crb		For information, Contact	Phone
Number		Check One: <input type="checkbox"/> Floor <input type="checkbox"/> Bay <input type="checkbox"/> Crb	Date
		<b>11/10/99</b>	
Part Number	Description	Purpose (E.I.A., Test, Build, Job, Etc.)	
<b>50 411W7E</b>	<b>DRAC. SWITCH &amp; CONNECTOR</b>	<b>FAILURE ANALYSIS</b>	
<b>11 96652-AA</b>	<b>FROM RECALL 99S15</b>		
<b>5JR BOXES</b>	<b>Box #9179488 8 Boxes</b>		
	<b>9181375 9176873 5 Boxes</b>		
	<b>91812089 9182127</b>		
NOTE: * An "X" MUST be placed in this column when shipping hazardous materials. ** List all hazardous materials first - do not abbreviate.			
Signature of Requestor		M.V.T.C.R. Department	
<b>Steve Reinert</b>		<b>John P. L.</b>	

3713 9628

MAY 1993 3258



# Material Move Request

FOR INTRA-COMPANY MOTOR VEHICLE SHIPMENTS ONLY  
(Not to Be Used by Common Carrier)

0549514

FROM: <b>Stone River</b>		TO: <b>EXPERIMENT FAILURE ANALYSIS</b>	
Department <b>TR402</b>	Department No.	Department	Department No.
Building <b>AVT5</b>		Building <b>FARMINGTON HILLS</b>	
Classification <input type="checkbox"/> Parts <input checked="" type="checkbox"/> Qty <input type="checkbox"/> Ord	For Information, Contact Phone	Check One: <input type="checkbox"/> Floor <input type="checkbox"/> Bay <input type="checkbox"/> Ord	Date <b>11/18/99</b>
Number		Number	

Qty.	Part Number	Description ** (For Hazardous Materials: Description and Classification)	Purpose (E.I.A., Test, Build, Job, Etc.)
24	BOXES	KW7E 96652 AA	FAILURE ANALYSIS
		9181448 (14 BOXES)	

Any hazardous materials listed above must be properly described, classified, packaged and labeled in accordance with the requirements of Title 49, Code of Federal Regulations.

NOTE: To be filled by shipper in this column when shipping hazardous materials. Attach all hazard labels available. Do not abbreviate.

Signature of Requester


*SJ Raines*

H.M.T.C.F. Approval

*SJR*

MAY 1992 3268

3713 9821



**Steve Reimers**

Product Design Engineer  
Core Suspension and Steering  
Chassis Electronic Systems  
Advanced Vehicle Technology  
PROFS: SREIMERS  
Email: SREIMERS@ford.com

20000 Robin's Drive  
Dearborn, MI 48121  
Bldg. #5, 3C005, MD #6020  
Telephone: 313/590-3288  
Fax: 313/390-4145







PLANT/PROCESSOR CODE : AGO C29  
 NAME : BRENDTKE, C.  
 PHONE : 3133375885

KEY PROCESS :  
 KEY ELEMENT : -  
 KEY TOOL : -  
 REQUEST LANG : E  
 STANDARD LANG : -

REPEAT OPPOSITE SIDE:  
 PSO/ADI  
 LINE/SUB-ASSEMBLY :  
 CER NUMBER :

HEADER CHANGE : AGO  
 DATE : 05/22/1992

EFFECTIVE DATE PLANT: AGO

IN DATE/POINT : 05/22/1992

ISSUE DATE ORIGINAL: 11/13/1991

ELEMENT CHANGE : Y  
 PART CHANGE : N  
 TOOL CHANGE : N  
 USAGE CHANGE : N

OUT DATE/POINT :

LATEST : 05/22/1992

REPLACES PROCESS : CJ7010 00101 AGO ILLUSTRATION DATE : \*\* N/A \*\*

EMPLAGED BY PROCESS : NO. OF ILLUSTRATIONS : 00  
 CPSCS ----- VEHICLES ----- PLANTS -----  
 080600 080000 080608 CVB WIX

INSTALLATION MANUAL REFERENCES

IL-F3LC-080000-01

REVISIONS

REVISION-DATE	REVISION-ID	REVISION-CER NUMBER	REVISION DESCRIPTION
05/22/1992	C29		REPLACES CVB CJ7010 00101 AGO
05/22/1992	C29		ELEMENT 110 REVISED
05/22/1992	C29		ELEMENT 110 MAND ITEM CHANGED FROM Y TO N
05/22/1992	C29		ELEMENT 100 REVISED
05/22/1992	C29		ELEMENT 100 MAND ITEM CHANGED FROM Y TO N
05/22/1992	C29		ELEMENT 070 REVISED
05/22/1992	C29		ELEMENT 070 MAND ITEM CHANGED FROM Y TO N
05/22/1992	C29		ELEMENT 080 REVISED
05/22/1992	C29		ELEMENT 080 MAND ITEM CHANGED FROM Y TO N
05/22/1992	C29		ELEMENT 030 REVISED
05/22/1992	C29		ELEMENT 030 MAND ITEM CHANGED FROM Y TO N
05/22/1992	C29		ELEMENT 010 REVISED
05/22/1992	C29		ELEMENT 010 MAND ITEM CHANGED FROM Y TO N
05/22/1992	C29		UPDATE
05/22/1992	C29		COPY - CVB CJ7010-00101-AGO

3713 9925

\*\*\*\*\* MANDATORY COMPLIANCE \*\*\*\*\* MANDATORY COMPLIANCE \*\*\*\*\* MANDATORY COMPLIANCE \*\*\*\*\* MANDATORY COMPLIANCE \*\*\*\*\*  
 PROCESS TITLE : EVACUATE AND FILL BRAKE SYSTEM  
 MAND \* FAM PROCESS ELVL/SFK PLT CPY -- STUDY -- ALT C/N  
 \* CVB CJ7010 001 02 AGO

\*\* Initial

ELEMENTS

ELEMENT: 010 PART REFS: CHG 06/22/1992  
 TEXT====> REMOVE MASTER CYLINDER CAP. E01 STANDARD LANGUAGE: VALIDATED

CONTROL USAGE==> LINCOLN TOWN CAR 05/22/1992

ELEMENT: 020 PART REFS: 08/22/1992  
 TEXT====> CONNECT (BRAKE CONSOLE) (TOW) ROPE TO VEHICLE E01 STANDARD LANGUAGE: VALIDATED

CONTROL USAGE==> LINCOLN TOWN CAR 06/22/1992

ELEMENT: 030 PART REFS: CHG 06/22/1992  
 TEXT====> PLACE MASTER CYLINDER CAP (TOPSIDE DOWN) ON CONVL. E01 STANDARD LANGUAGE: VALIDATED

CONTROL USAGE==> LINCOLN TOWN CAR 05/22/1992

ELEMENT: 040 \*MANDATORY \* PART REFS: 06/22/1992  
 TEXT====> CONNECT ABS POWER SUPPLY ADAPTER TO ABS HYDRAULIC CONTROL UNIT PIGTAIL. E01 STANDARD LANGUAGE: VALIDATED  
 E02

TOOLS==> CTL: DESC: ADAPTER - 18-PIN ANTI-LOCK TYP: Z 05/22/1992  
 TOOL NUMBER: 56ZF 28372 QTY: 001

CONTROL USAGE==> LINCOLN TOWN CAR 06/22/1992

ELEMENT: 060 PART REFS: A CHG 06/22/1992  
 TEXT====> ALIGN AND SEAT FILL HEAD ADAPTOR TO MASTER CYLINDER. E01 STANDARD LANGUAGE: VALIDATED

TOOLS==> CTL: DESC: BRAKE EVAC & FILL EQUIPMENT (DEB-315) TYP: C 05/22/1992  
 TOOL NUMBER: COMM QTY: 001

TOOLS==> CTL: DESC: BRAKE FILL ADAPTOR TYP: Z 06/22/1992  
 TOOL NUMBER: 56ZF 26896 QTY: 001

CONTROL USAGE==> LINCOLN TOWN CAR 06/22/1992

ELEMENT: 080 \*MANDATORY \* PART REFS: 05/22/1992  
 TEXT====> DEPRESS CYCLE START BUTTON. E01 STANDARD LANGUAGE: VALIDATED

ADAPTER WILL CLAMP AND EVAC/FILL CYCLE WILL START.  
 IF A LARGE OR SMALL LEAK IS DETECTED DURING THE CYCLE, THE EQUIPMENT WILL ABORT THE CYCLE. IF TIME PERMITS, THE CYCLE CAN BE RESTARTED BY DEPRESSING THE START BUTTON AGAIN.

RECOMMENDED MACHINE SETTINGS:  
 TOTAL VACUUM 35 SEC  
 VACUUM I 20 SEC

R01  
 R02  
 R03  
 R04  
 R05  
 R06  
 R07  
 R08  
 R09

3713 9826

\*\*\*\*\* MANDATORY COMPLIANCE \*\*\*\*\* MANDATORY COMPLIANCE \*\*\*\*\* MANDATORY COMPLIANCE \*\*\*\*\* MANDATORY COMPLIANCE \*\*\*\*\*  
 PROCESS TITLE ----- MAND \* FAN PROCESS ELVL/SFA PLT CPY -- STUDY -- ALT C/N  
 EVACUATE AND FILL BRAKE SYSTEM \* CYB CJ7D10 001 02 AGD

ELEMENTS

SMALL LEAK DECAY	5 SEC	R10
(VACUUM DECAY NOT TO EXCEED 3MBAR DROP-OFF)		R11
VACUUM #2	10 SEC MINIMUM	R12
FILL	INITIAL PRESSURE - 150 PSI	R13
	FINAL FILL PRESSURE - 135 PSI	R14
UNCLAMP DELAY	1.8 SEC	R15
TOP-OFF (HIGH SCAV.)	5 SEC	R16
HIGH VACUUM PURGE	8 SEC	R17
LARGE LEAK CHECK @ MBAR ABSOLUTE IN 15 SEC.		R18
SMALL LEAK CHECK @ MBAR ABSOLUTE IN 5 SEC.		R19
CLAMP PRESSURE 900-1000 PSI		R20

TOOLS==> CTL: DESC: BRAKE EVAC & FILL EQUIPMENT (DEB-315) TYP: C QTY: 001 05/22/1992  
 TOOL NUMBER: COMB

TOOLS==> CTL: DESC: BRAKE FILL ADAPTOR TYP: Z QTY: 001 05/22/1992  
 TOOL NUMBER: 56ZF 28996

CONTROL USAGE==> LINCOLN TOWN CAR 05/22/1992

ELEMENT: 070 PART REFS: CHG 06/22/1992  
 TEXT==> REMOVE FILL HEAD ADAPTER FROM MASTER CYLINDER RESERVOIR ED1 STANDARD LANGUAGE: VALIDATED  
 AT THE CONCLUSION OF THE CYCLE. R01

TOOLS==> CTL: DESC: BRAKE EVAC & FILL EQUIPMENT (DEB-315) TYP: C QTY: 001 05/22/1992  
 TOOL NUMBER: COMB

TOOLS==> CTL: DESC: BRAKE FILL ADAPTOR TYP: Z QTY: 001 05/22/1992  
 TOOL NUMBER: 56ZF 28996

CONTROL USAGE==> LINCOLN TOWN CAR 05/22/1992

ELEMENT: 080 \*MANDATORY \* PART REFS: 06/22/1992  
 TEXT==> DISCONNECT ABS POWER SUPPLY ADAPTER FROM HCU PIGTAIL. ED1 STANDARD LANGUAGE: VALIDATED

TOOLS==> CTL: DESC: ADAPTER - 19-PIN ANTI-LOCK TYP: Z QTY: 001 05/22/1992  
 TOOL NUMBER: 56ZF 28272

CONTROL USAGE==> LINCOLN TOWN CAR 05/22/1992

ELEMENT: 090 \*MANDATORY \* PART REFS: 06/22/1992  
 TEXT==> OBTAIN RESERVOIR CAP FROM COML TOP ED1 STANDARD LANGUAGE: VALIDATED

NOTE: FLUID LEVEL IN RESERVOIR MUST BE 0-4MM BELOW R02  
 MAX FILL LINE ON SIDE OF RESERVOIR. R03

CONTROL USAGE==> LINCOLN TOWN CAR 05/22/1992

\*\*\*\*\* MANDATORY COMPLIANCE \*\*\*\*\* MANDATORY COMPLIANCE \*\*\*\*\* MANDATORY COMPLIANCE \*\*\*\*\* MANDATORY COMPLIANCE \*\*\*\*\*  
 PROCESS TITLE MAND \* FAM PROCESS ELVL/SFX PLY COPY -- STUDY -- ALT C/N  
 EVACUATE AND FILL BRAKE SYSTEM \* CV8 Cj7010 001 02 A00

ELEMENTS

ELEMENT: 100	PART REFS:	CHG 05/22/1992
TEXT--> POSITION CAP TO BRAKE RESERVOIR	EO1 STANDARD LANGUAGE: VALIDATED	
CONTROL USAGE--> LINCOLN TOWN CAR		05/22/1992

ELEMENT: 110	PART REFS:	CHG 05/22/1992
TEXT--> SEAT CAP TO RESERVOIR	EO1 STANDARD LANGUAGE: VALIDATED	
CONTROL USAGE--> LINCOLN TOWN CAR		05/22/1992

ELEMENT: 120	PART REFS:	CHG 05/22/1992
TEXT--> REMOVE TOW ROPE FROM VEHICLE	EO1 STANDARD LANGUAGE: VALIDATED	
CONTROL USAGE--> LINCOLN TOWN CAR		05/22/1992

\*\*\*\*\* MANDATORY COMPLIANCE \*\*\*\*\* MANDATORY COMPLIANCE \*\*\*\*\* MANDATORY COMPLIANCE \*\*\*\*\* MANDATORY COMPLIANCE \*\*\*\*\*

PROCESS TITLE ----- \* MAND \* FAN PROCESS ELVL/SFX PLT CPT -- STUDY -- ALT C/N

EVACUATE AND FILL BRAKE SYSTEM \* \* CVR C/JTQ10 001 02 480

\*\*

PLANT/PROCESSOR CODE : AGO C29  
 NAME : BRENDTKE, C.  
 PHONE : 3133779885  
 KEY PROCESS :  
 KEY ELEMENT :  
 KEY TOOL :  
 REQUEST LANG : E  
 STANDARD LANG :  
 REPEAT OPPOSITE SIDE:  
 PSD/AOI  
 LINE/SUB-ASSEMBLY :  
 CER NUMBER :

EFFECTIVE DATE PLANT: AGO  
 IN DATE/POINT : 05/09/1992  
 OUT DATE/POINT :  
 ISSUE DATE ORIGINAL: 11/13/1991  
 LATEST : 05/09/1992  
 HEADER CHANGE : AGO  
 DATE : 05/02/1992  
 ELEMENT CHANGE : Y  
 PART CHANGE : N  
 TOOL CHANGE : Y  
 USAGE CHANGE : Y

REPLACES PROCESS : NONE  
 ILLUSTRATION DATE : \*\* N/A \*\*  
 REPLACED BY PROCESS :  
 NO. OF ILLUSTRATIONS : 00  
 CPSCS :  
 080800 080000 080808  
 VEHICLES : CFB  
 PLANTS : STM

INSTALLATION MANUAL REFERENCES

IL-F2LC-060000-01

REVISIONS

REVISION-DATE	REVISION-ID	REVISION-CER-NUMBER	REVISION DESCRIPTION
05/05/1992	C29		REPLACES CFBNONE
05/09/1992	C29		ELEMENT 030 UCC HAS BEEN PHYSICALLY DELETED
05/09/1992	C29		ELEMENT 030 UCC ADDED
05/09/1992	C29		ELEMENT 070 UCC HAS BEEN PHYSICALLY DELETED
05/09/1992	C29		ELEMENT 070 UCC ADDED
05/09/1992	C29		ELEMENT 030 UCC HAS BEEN PHYSICALLY DELETED
05/09/1992	C29		ELEMENT 030 UCC ADDED
05/09/1992	C29		ELEMENT 080 UCC ADDED
05/09/1992	C29		ELEMENT 080 UCC ADDED
05/02/1992	C29		ELEMENT ALL UCC ADDED
05/02/1992	C29		PROCESS WAS PREVIOUSLY CJ3100
05/02/1992	C29		COPY -CFB-CJ7010-00000-AGO-1
05/02/1992	C29		UPDATE
05/02/1992	C29		COPY -CLB-CJ7010-00108-AGO-

\*\*\*\*\* MANDATORY COMPLIANCE \*\*\*\*\* MANDATORY COMPLIANCE \*\*\*\*\* MANDATORY COMPLIANCE \*\*\*\*\* MANDATORY COMPLIANCE \*\*\*\*\*  
 PROCESS TITLE : EVACUATE AND FILL BRAKE SYSTEM  
 \* MAND \* FAM PROCESS ELVL/SFX PLY CPY -- STUDY -- ALT C/N  
 \* \* CFB CJ7010 001 00 AGO

*Find/Measure*

ELEMENTS

ELEMENT: 010 \*MANDATORY \*

TEXT====> REMOVE MASTER CYLINDER CAP

PART REFS:  
E01 STANDARD LANGUAGE: VALIDATED

ADD 05/02/1992

CONTROL USAGE====> CROWN VICTORIA

ELEMENT: 020 \*MANDATORY \*

TEXT====> PLACE MASTER CYLINDER CAP ( TOPSIDE DOWN) ON COWL

PART REFS:  
E01 STANDARD LANGUAGE: VALIDATED

ADD 05/02/1992

ADD 05/02/1992

CONTROL USAGE====> CROWN VICTORIA

ELEMENT: 030 \*MANDATORY \*

TEXT====> CONNECT ABS POWER SUPPLY ADAPTER TO ABS HYDRAULIC CONTROL UNIT PIGTAIL (ABS UNITS ONLY)

PART REFS:  
E01 STANDARD LANGUAGE: VALIDATED  
E02

ADD 05/02/1992

ADD 05/02/1992

TOOLS====> CTL: DESC: ADAPTER - 10-PIN ANTI-LOCK  
TOOL NUMBER: 582F 28372

TYP: 2  
QTY: 001

ADD 06/02/1992

CONTROL USAGE====> CROWN VICTORIA ANTI-SPIN TRACTION BRAKES

ADD 05/09/1992

ELEMENT: 040 \*MANDATORY \*

TEXT====> ALIGN-AND-SEAT FILL HEAD ADAPTOR TO MASTER CYLINDER

PART REFS:  
E01 STANDARD LANGUAGE: VALIDATED

ADD 05/02/1992

TOOLS====> CTL: DESC: BRAKE EVAC & FILL EQUIPMENT (DEN-315)  
TOOL NUMBER: COMM

TYP: C  
QTY: 001

ADD 06/02/1992

TOOLS====> CTL: DESC: BRAKE FILL ADAPTOR  
TOOL NUMBER: 882F 28888

TYP: 2  
QTY: 001

ADD 05/02/1992

CONTROL USAGE====> CROWN VICTORIA

ADD 05/02/1992

ELEMENT: 050 \*MANDATORY \*

TEXT====> DEPRESS CYCLE START BUTTON  
ADAPTOR WILL CLAMP AND EVAC/FILL CYCLE WILL START

PART REFS:  
E01 STANDARD LANGUAGE: VALIDATED

ADD 05/02/1992

IF A LARGE OR SMALL LEAK IS DETECTED DURING THE CYCLE, THE EQUIPMENT WILL ABORT THE CYCLE. IF TIME PERMITS, THE CYCLE CAN BE RESTARTED BY DEPRESSING THE START BUTTON AGAIN

RECOMMENDED MACHINE SETTINGS:

TOTAL VACUUM 40 SEC

VACUUM 1 25 SEC

SMALL LEAK DECAY 5 SEC

(VACUUM DECAY NOT TO EXCEED 3MBAR DROP-OFF)

VACUUM #2 15 SEC MINIMUM

FINAL FILL PRESSURE - 145 PSI

UNCLAMP DELAY 1.5 SEC

R01  
R02  
R03  
R04  
R05  
R06  
R07  
R08  
R09  
R10  
R11  
R12  
R13  
R14

\*\*\*\*\* MANDATORY COMPLIANCE \*\*\*\*\* MANDATORY COMPLIANCE \*\*\*\*\* MANDATORY COMPLIANCE \*\*\*\*\* MANDATORY COMPLIANCE \*\*\*\*\*  
PROCESS TITLE EVACUATE AND FILL BRAKE SYSTEM \* MAND \* FAM PROCESS ELVL/SFX PLT CPV -- STUDY -- ALT C/N \* \* CFB C37010 001 00 ADD

ELEMENTS

TOP-OFF (HIGH SCAV.) 3 SEC  
 HIGH VACUUM PURGE 10 SEC R15  
 LARGE LEAK CHECK @ MBAR ABSOLUTE IN 15 SEC. R16  
 SMALL LEAK CHECK @ MBAR ABSOLUTE IN 5 SEC. R17  
 CLAMP PRESSURE @10-1000 PSI R18  
 R19

TOOLS==> CTL: DESC: BRAKE EVAC & FILL EQUIPMENT (DEB-316) TYP: C ADD 06/02/1992  
 TOOL NUMBER: COMM QTY: 001

TOOLS==> CTL: DESC: BRAKE FILL ADAPTOR TYP: Z ADD 05/02/1992  
 TOOL NUMBER: 50ZF 26696 QTY: 001

CONTROL USAGE==> CROWN VICTORIA ADD 05/02/1992

ELEMENT: 060 \*MANDATORY \* PART REFS:  
 TEXT==> REMOVE FILL HEAD ADAPTER FROM MASTER CYLINDER RESERVOIR E01 STANDARD LANGUAGE: VALIDATED ADD 06/02/1992  
 AT THE CONCLUSION OF THE CYCLE. R01

TOOLS==> CTL: DESC: BRAKE EVAC & FILL EQUIPMENT (DEB-316) TYP: C ADD 06/02/1992  
 TOOL NUMBER: COMM QTY: 001

TOOLS==> CTL: DESC: BRAKE FILL ADAPTOR TYP: Z ADD 06/02/1992  
 TOOL NUMBER: 50ZF 26696 QTY: 001

CONTROL USAGE==> CROWN VICTORIA ADD 06/02/1992

ELEMENT: 070 \*MANDATORY \* PART REFS:  
 TEXT==> DISCONNECT ABS POWER SUPPLY ADAPTER FROM HCU PIGTAIL E01 STANDARD LANGUAGE: VALIDATED ADD 06/02/1992  
 ANTI-LOCK UNITS ONLY. R01

TOOLS==> CTL: DESC: ADAPTER - 19-PIN ANTI-LOCK TYP: Z ADD 05/02/1992  
 TOOL NUMBER: 50ZF 28372 QTY: 001

CONTROL USAGE==> CROWN VICTORIA ANTI-SPIN TRACTION BRAKES ADD 05/09/1992

ELEMENT: 080 \*MANDATORY \* PART REFS:  
 TEXT==> OBTAIN RESERVOIR CAP FROM CONVL TOP E01 STANDARD LANGUAGE: VALIDATED ADD 06/02/1992  
 R01

NOTE: FLUID LEVEL IN RESERVOIR MUST BE 0-4MM BELOW  
 MAX FILL LINE ON SIDE OF RESERVOIR. R02  
 R03

CONTROL USAGE==> CROWN VICTORIA ADD 06/02/1992

ELEMENT: 090 \*MANDATORY \* PART REFS:  
 TEXT==> POSITION CAP TO BRAKE RESERVOIR E01 STANDARD LANGUAGE: VALIDATED ADD 05/03/1992

CONTROL USAGE==> CROWN VICTORIA ADD 05/02/1992

\*\*\*\*\* MANDATORY COMPLIANCE \*\*\*\*\* MANDATORY COMPLIANCE \*\*\*\*\* MANDATORY COMPLIANCE \*\*\*\*\* MANDATORY COMPLIANCE \*\*\*\*\*  
 PROCESS TITLE EVACUATE AND FILL BRAKE SYSTEM \* MAND \* FAN PROCESS ELVL/SFX PLT CPY -- STUDY -- ALT C/N  
 \* \* CFB 01/7010 001 00 AGO





Central Laboratory  
16000 Century Drive  
Dearborn, MI 48120-1287  
FAX (313) 322-1614

Report 03023

November 8, 2000

**To:** S. Reimers (313) 39-03286 (313) 39-04146 FAX  
**From:** S. LaRouche (313) 84-54876  
**Subject:** Brake Pressure Switch  
Part Number: F2VC-9F924-AB  
Specification: Not Provided  
Supplier: Texas Instruments

**Received:** One brake pressure switch, identified as #2, was received on September 12, 2000. The switch developed a short circuit during electrical testing with brake fluid injected into the switch cavity.

**Object:** Determine the cause of the short-circuit.

**Conclusion:** The short-circuit was caused by a buildup of copper-rich material on the face of the cup, which formed a bridge between the cup and movable contact. The buildup of copper-rich material most likely resulted from electrolytic deposition of movable contact material on the cup. A cell was probably set up in which the contact acted as the anode, the cup acted as the cathode, and the brake fluid served as the electrolyte.


**Data and Analysis:**


**Surface Analysis**

(Visual Examination, Scanning Electron Microscopy (SEM), and Energy Dispersive X-ray Spectroscopy (EDS))



The switch cavity was opened by removing the aluminum crimp ring and separating the base from the cup (Figure 1). This revealed a buildup of material that bridged the gap between the movable contact (Figure 2) and the face of the cup (Figures 3 and 4). The movable contact is made of brass, while the cup is made of zinc-plated steel. The buildup consisted of a dark greenish sludge (assumed to be brake fluid) and hard deposits that formed a bridge between the contact and cup. This bridge appears to have been the cause of the short-circuit in the switch. Two samples of the hard deposits were scraped away from the face of the cup and analyzed with SEM/EDS. The deposits were found to contain copper (Figures 5 and 6). The surface of the movable contact shows evidence of pitting attack (Figure 7). The presence of copper in the deposits, and evidence of attack in the surface of the contact, indicate that the deposits are most likely contact material that was transferred on the face of the cup. This suggests that an electrolytic cell was set up in the switch, in which the movable contact acted as the anode, the cup acted as the cathode, and the brake fluid served as the electrolyte.

**Contributor:** C. Stevenson

**Concur:**   
P. Klass, Supervisor  
Metallurgy Section


**By:**   
Steven LaRouche (SLAROUCH)

**Enclosures:** Figures 1 through 7



~2X

Figure 1: Digital photograph showing switch cavity after cup and base were separated.




~7.5X

Figure 2: Digital photograph showing buildup of material on movable contact.



-6.4X

Figure 3: Digital photograph showing buildup on face of cup.



-7.1X

Figure 4: Digital photograph showing side view of buildup of material on face of cup where it would have formed bridge between cup and contact.

09029





Figure 5: SEM photomicrograph and EDS spectrum of deposit removed from face of cup.

03023







Figure 6: SEM photomicrograph and EDS spectra of deposit removed from face of cup.




54.6X

*Figure 7: SEM photomicrograph showing pitting attack in surface of movable contact.*

wiring: switches w/connector



WET / POWERED  
 DRY / POWERED  
 WET / NO POWER  
 ? DRY / NO POWER



Set voltage at  $14 \pm 0.1$  volt  
 Set current limit to  $100 \pm 10$  milliamps  
 while ~~switch~~ + & - is connected together.

Close only for current limit check.

ExperimentData

Date & Time	supply volts	supply current	supply current limit	switch number	Leak microAmps Moving Terminal	Leak microAmps Stat Terminal	Open Circuit volts	Switch Resistance mov to stat	Resistance mov to hex	Resistance stat to hex	Switch mAmps	Connector voltage yellow wire	Connector voltage purple wire	Fluid added milli Liters	comments
8/1/00 2:54 PM	13.97	31.00	101	1				0.1	>40M	>40M	6.2	14	14		cal resistance = 0.1 ohms
8/1/00 3:30 PM	13.97			3				0.2	>40M	>40M	6.2	14	14		elbow @ 6 o'clock
8/1/00 3:30 PM	13.97			3					10M						Elbow at 6 o'clock
8/1/00 3:33 PM	13.97			4					22M						1.5 flooded til came out of terminals
8/1/00 3:35 PM	13.97			4				0.2	>40M	>40M	6.2	14	14		0.8 added DOT3 to dry switch.
8/1/00 3:35 PM	13.97			5					27M						Elbow at 6 o'clock
8/1/00 3:35 PM	13.97			5				0.2	>40M	>40M	6.2	14	14		0.7 added DOT3 to dry switch.
8/1/00 5:05 PM	13.97			2				0.2	>40M	>40M	6.2	14	14		Elbow at 4 o'clock
8/1/00 5:05 PM	13.97			2					30M						Elbow at 8 o'clock
8/2/00 7:50 AM	13.96			1				0.1	>40M	>40M	6.2	13.96	13.96		0.5 added DOT3 to dry switch
8/2/00 7:50 AM	13.96			2				0.2	>40M	>40M	6.3	13.96	13.96		cal resistance = 0.1
8/2/00 7:50 AM	13.96			2					>20M						0.1
8/2/00 7:50 AM	13.96			3				0.2	>40M	>40M	6.3	13.96	13.96		
8/2/00 7:50 AM	13.96			3					>40M						0.5 reflooded
8/2/00 7:50 AM	13.96			4				0.2	>40M	>40M	6.3	13.96	13.96		
8/2/00 7:50 AM	13.96			4					>20M						0.1
8/2/00 7:50 AM	13.96			5				0.2	>40M	>40M	6.3	13.96	13.96		
8/2/00 7:50 AM	13.96			5					>20M						0
8/3/00 8:47 AM	13.96			1	0.1			0.2	>40M	>40M	6.2	13.96	13.96		
8/3/00 8:47 AM	13.96			2	32			0.2	>40M	>40M	6.3	13.96	13.96		
8/3/00 8:47 AM	13.96			3	30			0.2	>40M	>40M	6.3	13.96	13.96		
8/3/00 8:47 AM	13.96			4	31			0.2	>40M	>40M	6.2	13.96	13.96		
8/3/00 8:47 AM	13.96			5	40			0.2	>40M	>40M	6.3	13.96	13.96		
8/4/00 9:09 AM	13.93			1	0.1	0.1	.0	0.2	>40M	>40M	6.2	13.96	13.96		
8/4/00 9:09 AM	13.93			2	25	25	1.174	0.2	>40M	>40M	6.3	13.96	13.96		
8/4/00 9:09 AM	13.93			3	31	31	1.2	0.2	>40M	>40M	6.3	13.96	13.96		
8/4/00 9:09 AM	13.93			4	32	32	1.117	0.2	>40M	>40M	6.2	13.96	13.96		
8/4/00 9:09 AM	13.93			5	28	28	1.083	0.2	>40M	>40M	6.3	13.96	13.96		
8/7/00 8:41 AM	13.95			1	0.1	0.1	0	0.2	>40M	>40M	6.2	13.95	13.95		
8/7/00 8:41 AM	13.95			2	14	14	1.04				6.3	13.95	13.95		
8/7/00 8:41 AM	13.95			3	22	22	1.17	0.2	>40M	>40M	6.3	13.95	13.95		
8/7/00 8:41 AM	13.95			4	24	24	1.08	0.2	>40M	>40M	6.2	13.95	13.95		
8/7/00 8:41 AM	13.95			5	176	176	0.33	0.2	>10M	>10M	6.4	13.95	13.95		
8/7/00 8:41 AM	13.95			2	50	50		0.2	>20M	>20M					0.1
8/8/00 8:46 AM	13.95			1	0.2	0.2	0	0.2	>40M	>40M	6.2	13.95	13.95		
8/8/00 8:46 AM	13.95			2	23	27	0.82	0.2	>20M	>20M	6.3	13.95	13.95		
8/8/00 8:46 AM	13.95			3	27	22	1.19	0.2	>40M	>40M	6.2	13.95	13.95		
8/8/00 8:46 AM	13.95			4	28	28	1	0.2	>40M	>40M	6.3	13.95	13.95		
8/8/00 8:46 AM	13.95			5	3400	3400	0.007	0.2	9300	9300	9.9	13.95	13.95		

ExperimentData

8/9/00 9:43 AM	13.95			1	0.1	0	0	0.2 >40M	>40M	6.2	13.95	13.95	
8/9/00 9:43 AM	13.95			2	1560	1560	0.15	0.2 >2M	>2M	7.3	13.95	13.95	
8/9/00 9:43 AM	13.95			3	11.7	11.7	1.2	0.2 >40M	>40M	6.3	13.95	13.95	
8/9/00 9:43 AM	13.95			3	57	57							0.1
8/9/00 9:43 AM	13.95			4	17	17	1	0.2 >40M	>40M	6.3	13.95	13.95	
8/9/00 9:43 AM	13.95			5	3083	3083	0.007	0.2 >7000	>7000	9	13.95	13.95	
8/9/00 9:43 AM	13.95			4	48	48							0.1
8/10/00 8:24 AM	14.00			1	0.1	0	0	0.2 >40M	>40M	6.3	14	14	
8/10/00 8:24 AM	14.00			2	585	585	0.15	0.2 >10M	>10M	6.6	14	14	
8/10/00 8:24 AM	14.00			3	640	640	1.2	0.2 >40M	>40M	6.7	14	14	
8/10/00 8:24 AM	14.00			4	85	85	1	0.2 >40M	>40M	6.4	14	14	
8/10/00 8:24 AM	14.00			5	1759	1759	0.008	0.2 >10M	>10M	8.1	14	14	
8/11/00 10:06 AM	13.99			1	0.2	0.2	0	0.2 >40M	>40M	6.4	13.99	13.99	
8/11/00 10:06 AM	13.99			2	1990	1990	0.02	0.2 1642	1500	21.4			
8/11/00 10:06 AM	13.99			3	3000	3000	0.5	0.2 >2.4M	>2.4M	6.5			max = 8040, min = 1440 uAmp
8/11/00 10:06 AM	13.99			4	966	966	0.2	0.2 >0.7M	>0.7M	7.1			max = 28890, min = 240 uAmp
8/11/00 10:06 AM	13.99			5	2790	2790	0	0.2 5620	5620	9.2			max = 2076, min = 904 uAmp
8/11/00 10:06 AM	13.99			5	2790	2790	0	0.2 5620	5620	9.2			max = 2816, min = 2740 uAmp
8/12/00 1:40 PM	3.08			1	0.1	0.1	0.001	0.2 >40M	>40M	6.3	13.99	13.99	
8/12/00 1:40 PM	3.08			2	360	360	0.5	0.2 1400	1400	6.8	13.99	13.99	
8/12/00 1:40 PM	3.08			3	2840	2840	0.3	0.2 >1M	>1M	6.9	13.99	13.99	leak mAmps max = 14.08, min = 0.28, avg 0.36.
8/12/00 1:40 PM	3.08			4	3350	3350	0.03	0.2 26000	26000	8.6	13.99	13.99	mA max 9.64, min 2.24.
8/12/00 1:40 PM	3.08			5	510	510	0.01	0.2 27000	27000	6.8	13.99	13.99	mA max 18.0, min 3.2
8/12/00 1:40 PM	3.08			5	510	510	0.01	0.2 27000	27000	6.8	13.99	13.99	mA are stable
8/13/00 8:56 AM	14.00			1	0.1	0.1	0.01	0.2 >12M	>12M	6.4	13.99	13.99	0
8/13/00 8:56 AM	14.00			2	30420	30420	0.001	0.2 >2.5M	>2.5M	6.5	13.99	13.99	0 33.2 to 29.0 m Amp leak
8/13/00 8:56 AM	14.00			3	3900	3900	0.004	0.2 2900	2900	10.8	13.99	13.99	0 1.16 to 29.08 mA leak
8/13/00 8:56 AM	14.00			4	9760	9760	0.004	0.2 5400	5400	13.3	13.99	13.99	0 8.0 to 14.84 mA leak
8/13/00 8:56 AM	14.00			5	420	420	0.014	0.2 52000	52000	6.8	13.99	13.99	0
8/14/00 8:00 AM	8.95	197.00	200	1	0.2	0.2	0.103	0.1 >40M	>40M				0 supply still in current limit mode
8/14/00 8:00 AM	8.95	197.00	200	2	145000	145000	0.087	0.2 >0.6M	>0.6M	7	14.03	14.03	supply still in current limit mode
													This happened at 315 mAmp. The current then dropped to 88 mAmp. The drop in current may have occurred because the conducting path was destroyed by the extra
8/14/00 8:05 AM	14.00	88.00	315	2	2870	2870	0.12	0.1 3030	3170	11	14.03	14.03	0 current.
													leak max 7.92 mA
													min 2.68 mA
8/14/00 8:05 AM	14.00			3	6320	7340				12	14.03	14.03	0 avg 6.32 mA
													leak max = 17.64 mA
													min = 15.84 mA
8/14/00 8:05 AM	14.00			4	16770	16770	0.002	0.2 2230	2330	25	14.03	14.03	0 avg = 16.77 mA
8/14/00 8:05 AM	14.00			5	314	314	0.021	0.2 81100	95700	6	14.03	14.03	0 stable leak current
8/14/00 9:20 AM	14.00	55.00	100	2									0 Add second power supply for switch number 2.
8/15/00 9:01 AM	1.00			1	0.2	0.2	0.015	0.2 >40M	>40M	6	14.09	14.09	0
8/15/00 9:01 AM	1.00			2	6770	6780	0.002	0.2 3780	3800	6.2			0
8/15/00 9:01 AM	14.00			3	17620	15980	0.006	0.2 1540	1690	21	14.09	14.09	0 leak mAmp range 35.44 to 10.48 m.h, 26.2 to 12.72 s.h.

ExperimentData

8/15/00 9:01 AM	14.00		4	1410	1380	0.018	0.2 41100	13690	8	14.09	14.09	0
8/15/00 9:01 AM	14.00		5	286	287	0.032	0.2 92800	414000	8	14.09	14.09	0
8/16/00 10:30 AM	14.00		1	0.2	0.2	0.201	0.2 >40M	>40M	6	14.06	14.06	0
8/16/00 10:30 AM	14.00		2	4590	4280	0.011	0.2 3590	3292	8	13.98	13.97	0
												leak mAmps range m:h 30.4 to 44.8
8/16/00 10:30 AM	14.00		3	35700	44700	0.006	0.2 845	10470000	7	11.46	11.22	0 s:h 38 to 50.8
8/16/00 10:30 AM	14.00		4	4100	4100	0.013	0.2 2523	2140	14	9.15	9.23	0
8/16/00 10:30 AM	14.00		5	300	300	0.051	0.2 422000	88900	7	8.39	8.44	0
8/17/00 12:00 PM	1.50		1	0.3	0.3	0.045	0.2 >40M	>40M	6	14.08	14.08	0
8/17/00 12:00 PM	1.50		2	2300	2140	0.025	0.1 1580	910		14.08	14.08	0
												leak mA range m:h 31.16 to 37.44
8/17/00 12:00 PM	1.50		3	35370	36880	0.011	0.1 4670	4590	24	14.08	14.08	0 s:h 37.92 to 36.68
8/17/00 12:00 PM	1.50		4	47800	47700	0.039	0.1 19720	19580		14.08	14.08	0
8/17/00 12:00 PM	1.50		5	100	90	0.13	0.1 23560	24100	7	14.08	14.08	0
8/18/00 12:30 PM	14.00		1	0.3	0.3	0.032	0.1 >40M	>40M	6	14.01	14.01	0
												leak mAmps range m:h 1.36 to 5.36
8/18/00 12:30 PM	14.00		2	2820	4300	0.04	0.1 10320	10500	11	14.01	14.01	0 s:h 2.32 to 5.80
												leak mAmps range m:h 31.24 to >1000
8/18/00 12:30 PM	14.00		3	1000000	33120	0.003	0.1 1066	1066	36	14.01	14.01	0 s:h 31.16 to 39.48
8/18/00 12:30 PM	14.00		4	2280	1530	0.011	0.1 8770	1005	8	14.01	14.01	0
8/18/00 12:30 PM	14.00		5	624	627	0.017	0.1 50800	52100	7	14.01	14.01	0
8/21/00 9:00 AM	1.90		1	0.5	0.5	0.068	0.2 >40M	>40M	6	14.15	14.15	0
8/21/00 9:00 AM	1.90		2	0.2	0.2	0.08	0.2 3.4	3.3	3.245	14	14	0 sep. power supply leak mAmps range m:h 1.88 to 11.84
												leak mAmps range m:h 2.0 to 6.6
8/21/00 9:00 AM	1.90		3	2850	2780	0.009	0.2 51600	51500	12	14.15	14.15	0 s:h 8.24 to 16.88
												leak mAmps range m:h 8.24 to 16.88 s:h 8.68 to 15.72
8/21/00 9:00 AM	1.90		4	11670	12860	0.004	0.2 3987	4250	13	14.15	14.15	0
8/21/00 9:00 AM	1.90		5	250	250	0.089	0.1 476000	582000	6	14.15	14.15	0
8/22/00 7:30 AM	14.00		1	0.2	0.2	0.035	0.2 >40M	>40M	6	14.01	14.01	0
												leak mAmps range m:h 2.03 to 4.98
8/22/00 7:30 AM	14.00	6.24	2	3500	4110	0.042	0.1 10530	10610	6.242	14	14	0 s:h 2.59 to 5.63
												leak mAmps range m:h 9.32 to 14.52
8/22/00 7:30 AM	14.00		3	10470	10560	0.016	0.2 1140	1130	16	14.01	14.01	0 s:h 9.2 to 13.16
												leak mAmps range m:h 9.32 to 11.28
8/22/00 7:30 AM	14.00		4	9730	9220	0.002	0.2 9010	9840	23	14.01	14.01	0 s:h 8.64 to 11.84

ExperimentData

8/22/00 7:30 AM	14.00			5	280	270	0.026	0.2 53700	52900	7	14.01	14.01	0
8/23/00 7:00 AM	4.80			1	0.2	0.2	0.031	0.2 >40M	>40M		14	14	0
8/23/00 7:00 AM	4.80			2	112200	112100		0.2 4.8	4.7		14	14	0
8/23/00 7:00 AM	4.80			3	255900	256900	0.0002	0.1 5.8	5.8		14	14	0.1 switch is slightly warm to the touch
8/23/00 7:00 AM	4.80			4	634000	630000	0.0001	0.2 3.3	3.5		14	14	0.1
8/23/00 7:00 AM	4.80			5	2.7	2.6	0.134	0.1 2650000	2540000		14	14	0
8/24/00 12:00 AM	4.20			3									0 white vapor seen rising through ontry hole when syringe 1 was removed.
8/24/00 2:30 PM	12.00	8000.00		4									0 stopped conducting after approximately 10minutes at 8 maps and 12 volts.
8/25/00 12:00 AM	14.00	6.25	100	1	0.5	0.5	0.46	0.2 >40M	>40M		14.05	14.05	0 Switch is now disconnected.
													0 open circuit > 40Meg
													leak mAmps range
													m:h 3.16 to 6.04
													s:h 3.36 to 15.96
8/25/00 12:00 AM	0.50	100.00	100	2	4570	5150	0.12	0.2 173000	151000		0.511	0.516	0 set power supply to 14.0v
8/25/00 12:00 AM	0.20	100.00	100	3	208	216	0	0.2 3.7	3.7		0.258	0.257	0 set supply to 14.0v
8/25/00 12:00 AM	14.00	6.22	100	5	0.1	0.1	0.042	0.2 179000	178000		14.03	14.03	0
													cal = 0.1
8/28/00 10:00 AM	14.00		100	1	0.2	0.2	0.0221	0.1 >40M	>40M	6.24	14.05	14.05	0 open circuit >40M
8/28/00 10:00 AM	1.00		100	2	108100	108100	0	0.3 13.9	13.9	0.66	1.039	0.995	0 o.l. condition
8/28/00 10:00 AM	0.40		100	3	108500	108700	0	0.1 4	4	0.1314	0.41	0.41	0
													switch resistance range
													m:h 146k to 217 k
8/28/00 10:00 AM	14.00		100	5	180	180	0.033	0.2 186900	268500	6.23	14.03	14.03	0 s:h 230k to 302k
													open circuit >40M
8/29/00 10:00 AM	14.00	6.24	100	1	0.2	0.2	0.0153	0.2 >40M	>40M		14.05	14.05	0 cal = 0.1
													over oad condition. Actual voltage set to 14.0 vdc when
8/29/00 10:00 AM	0.30	0.17	100	2	112400	112300	0	0.2 11.2	11.2		0.82	0.82	0 not current limited.
													overload condition. Actual voltage is 14v when not
8/29/00 10:00 AM	0.20	0.13	100	3	100900	100900	0	0.2 3.2	3.2		0.3	0.3	0 current limited.
													switch resistance range
													m:h 156k to 224k
8/29/00 10:00 AM	14.00	6.25	100	5	180	180	0.031	0.2 183100	265900		14.03	14.03	0 s:h 244k to 282k
8/30/00 10:00 AM	14.00	6.24	100	1	0.2	0.2	0.018	0.2 >40M	>40M		14.05	14.05	0
8/30/00 10:00 AM	0.50	0.34	100	2	114600	114600	0	0.2 8.4	8.4		0.666	0.666	0
8/30/00 10:00 AM	0.00	0.02	100	3	100800	100800	0	0.2 .6	.6		0.043	0.043	0
8/30/00 10:00 AM	14.00	6.25	100	5	17.8	17.8	0.377	0.2 >6M	>6M		14.07	14.07	0
8/30/00 2:20 PM				3				0.2 .7	.7				0 before moving to hi current fixture.

ExperimentData

8/30/00 2:20 PM	13.50	0.00	14500	3				0.2 0.6	0.7			
8/30/00 2:21 PM		15100.00	14500	3	15100000						2.38	
8/30/00 2:21 PM				3				0.2 .6	.7			
8/30/00 2:22 PM		14500.00	14500	3	14500000						1.77	
8/30/00 2:26 PM		14500.00	14500	3	14500000						1.48	
8/30/00 2:31 PM		14500.00	14500	3	14500000						1.37	
8/30/00 2:36 PM		14500.00	14500	3	14500000						1.27	
8/30/00 2:41 PM		14500.00	14500	3	14500000						1.18	
8/30/00 2:46 PM		14500.00	14500	3	14500000						1.19	
8/30/00 2:51 PM		14500.00	14500	3	14500000						1.28	
8/30/00 2:56 PM		14500.00	14500	3	14500000						1.63	
8/30/00 2:57 PM		14500.00	14500	3	14500000						1.92	
8/30/00 2:58 PM		14500.00	14500	3	14500000						2.16	
8/30/00 2:58 PM		14500.00	14500	3	14500000						2.22	
8/30/00 2:58 PM		14500.00	14500	3	14500000						2.22	
8/30/00 2:58 PM		14500.00	14500	3	14500000						2.52	
8/30/00 2:58 PM		14500.00	14500	3	14500000						2.52	
8/30/00 2:58 PM		2400.00	14500	3	2400000						6.96	
8/30/00 2:58 PM		200.00	14500	3	200000						11.63	
8/30/00 3:03 PM		1000.00	14500	3	1000000						12.29	
8/30/00 3:04 PM		900.00	14500	3	900000						12.24	
8/30/00 3:05 PM		100.00	14500	3	100000						9.44	
8/30/00 3:05 PM		0.00	14500	3	0.1						4.24	
8/31/00 9:00 AM	14.00	6.24	100	1	0.1	0.1	0.016	0.2 >40M	>40M		13.96	13.96
8/31/00 9:00 AM	0.60	0.30	100	2	114600	114600	0	0.2 6.4	6.4		0.694	0.697
8/31/00 9:00 AM	2.70	1.22	2120	4	2108000	2109000	0.067	0.2 2.0	2.0		2.793	2.793
8/31/00 9:00 AM		6.23	100	5	31.5	31.5	0.203	0.2 >2M	>2M		13.99	13.99
9/1/00 9:03 AM	14.00		105	1	0.5	0.5	0.13	0.2 >21M	>21M	6	14.04	14.04
9/1/00 9:19 AM	0.51		104	2	104	104	0	2 5	4.9	0.23	0.443	0.444
9/1/00 9:28 AM	0.28		109	4	109	109	0	0.2 2.4	2.4	0.13	0.208	0.208
9/1/00 9:37 AM	14.03		102	5	0.6	0.6	0.09	0.2 1.5M	1.5M	6.23	14.03	14.03
9/1/00 9:45 AM	14.03			5	168	168	0.55					
9/1/00 10:30 AM				2								

This switch was removed from the fixture and mounted on a bracket for video taping.  
 The supply was adjusted to 13.5 volts and the current limit set to 14.5 amps.  
 A thermo couple was externally mounted on the base near the moving terminal.  
 Dense white smoke issuing from hole in base.  
 Now on hi current fixture.  
 very bright glow inside switch cavity.  
 Flame begins  
 Flame has gone out.  
 Switch removed from fixture.  
 back on test after disconnected on 8/24/2000.  
 Thermo couple on base  
 @ 9:15 AM 91.6 F  
 @ 10:30 AM 149 F  
 cal + 0.1 ohm  
 open ckt > 40M  
 Removed from test fixture and moved to Hi current supply fixture.

ExperimentData

9/1/00 12:15 PM			2	0	0.1 5.7	5.7								0 On Hi current fixture. Set current limit to 18 amps. The plug for the hole in the base has fallen inside the 0 switch cavity. The leakage current indicates that the 5.7 ohm short to ground has changed to 0 27000 ohms.
9/1/00 12:24 PM	13.53		18000	2										0
9/1/00 12:31 PM	13.52	6.54	18000	2	500									0
9/1/00 12:56 PM	13.52	6.91	18000	2	850									0
9/1/00 1:15 PM	13.52	6.45	18000	2	460									0
9/1/00 1:43 PM	13.53	6.45		2										0
9/1/00 1:54 PM	13.52	6.64	18000	2	700									0 Switch is being returned to test fixture.
9/1/00 2:05 PM	0.19		109	4	109100	109100	0	0.2 2	1.9	0.08	0.183	0.183		0 Switch is being moved to hi current fixture.
9/1/00 2:16 PM	13.50	6.24	18000	4	220									0 Short to ground has changed from 2 ohms to 61,000.
9/1/00 2:20 PM	14.02		109	2	800	800	0	0.2 1975	1975	6.24	14.02	14.02		0 Switch is now back on low current fixture.
9/1/00 2:35 PM	13.53	6.11		4										0
9/1/00 3:20 PM	13.53	6.07		4	70									0
9/1/00 4:00 PM	13.53	6.07		4	70									0
9/1/00 4:24 PM	13.53	6.06	210	4	70									current limit reduced to 100 mA for overnight 0 unsupervised exposure.
9/5/00 2:00 PM	14.00	6.25	100	1	0.2	0.2	0.041	0.2 >40M	>40M		14.06	14.06		0
9/5/00 2:00 PM	0.80	16.83	100	2	108600	108600	0	0.2 50000	50000		14.02	14.02		0 contaminated with plug
9/5/00 2:00 PM	13.51	6.14	100	4	13530	13530	0.401	0.4 3.1M	3.1M		13.5	13.5		0
9/5/00 2:00 PM	8.70	15.89	100	5	98000	98000	0.0001	0.2 87.5	87.4		5.15	5.15		0
9/6/00 12:05 AM	13.50	6.30	14000	4	300									0
9/6/00 8:41 AM	14.00		104	1	0.2	0.2	0.029	0.2 >40M	>40M	6.23	14.05	14.05		0
9/6/00 8:41 AM	1.36		109	2	109000									0 current limit condition ended before measurement.
9/6/00 8:41 AM	14.02		109	2	1760	1760	0.06	0.2 15000	15000	6.23	14.02	14.02		0 leak current range 1.40 to 6.28.
9/6/00 8:59 AM	7.23		99	5	98000	98000	0	0.2 236	236	3.25	7.23	7.23		0
9/6/00 9:40 AM	13.53	6.51	206	4	415	394		0.1 1.4M	1.4M		13.53	13.53		0
9/6/00 9:50 AM	13.53		14000	4										0 increased current limit to 14 amps
9/6/00 10:15 AM	13.50	6.30	14000	4	300									0
9/6/00 2:12 PM	13.50	6.30	200	4	300									0 set current limit back to 200 mA for unsupervised
9/7/00 12:45 AM	13.50	6.26	200	4	260									0
9/7/00 10:00 AM	14.00	6.24	100	1	0.09	0.09	11.5	0.3 >40M	>40M		14.06	14.06		0
9/7/00 10:00 AM	0.90	9.86	100	2	7430	7430	0.0431	0.2 108700	106400		14.03	14.03		0
9/7/00 10:00 AM	13.51	6.34	100	4	114800	114800	0.1641	0.3 1530000	1530000		13.5	13.5		0
9/7/00 10:00 AM	14.00	2.55	100	5	99000	99000	0.0112	0.2 4530	4580		14.11	14.11		0
9/8/00 1:00 PM	14.00	6.23	1	1	0.15	0.15	0.0101	0.3 >40M	>40M		14.06	14.06		0
9/8/00 1:00 PM	2.00	104.40	100	2	3370	3370	0.0011	0.3 128200	128200		14.08	14.08		0
9/8/00 1:00 PM	13.50	6.01	100	4	550	550	0.11	0.3 990000	990000		13.5	13.5		0
9/8/00 1:00 PM	1.80	12.52	100	5	99250	99250	0.00001	0.3 12.5	12.5		1.61	1.61		0
9/8/00 4:49 PM	14.00			5	8400									0 leakage current range 3 to 12.1 mAmp
9/8/00 4:54 PM	14.00			5	128000									0 leakage current range 7.2 to 74.4 mAmps.
9/8/00 5:00 PM	13.50	7.60	200	4	1640									0





ExperimentData

9/29/00 4:50 PM	0.00	0.00	0	1	0
10/2/00 8:53 AM	14.00	0.00	100	1	0
10/2/00 4:56 PM	0.00	0.00	0	1	0

Reimers, Steve (S.J.)

Hi-Stat Test Supervision

From: Reimers, Steve (S.J.)  
Sent: Friday, October 13, 2000 11:30 AM  
To: Bob Melenovalky (B.) (E-mail)  
Cc: Porter, Fred (F.J.); LaPointe, Norman (N.R.)  
Subject: Test Detail Questions

Bob,

Here are some questions for the teleconference on 10/16/2000 at 10 AM.

- ① How was the switch contact function monitored? counter } differences records available.
- ② How were pressure cycle counts recorded? cycle box - no }
- ③ How was pressure applied? 1450 } could spikes occur
- ④ Where was pressure measured? at MC & at Manifold (temporarily) frequency? 1/11
- ⑤ Was pressure recorded? how? review? - between correlated pulse set-ups (only @ set-up)

What switch connector part number was used? no connectors

Did all connectors have red face seal and wire grommet (gray seal)?

Did leaking fluid appear at the top of the connector wire grommet (gray seal)?

Was the wire grommet forced out by the leaking fluid?

What wire part number and manufacturer was used to make electrical connection to switch?

What brake fluid was used? DOT 3 NAPA-brand (new).

Was air purged from switches? Yes, hypo injected

What was orientation of switch (vertical with base on top, ...)? connector up

Was the temp of the fluid recorded? Monitor by controller  $\pm 0.5^\circ\text{C}$  (no record)

Where was fluid temp measured? In Manifold (no circulation), cartridge heaters heats manifold to 135C

Was the temp of the switch ambient recorded? Yes, circular chart

Where was ambient temp measured? in chamber 1 foot in air stream (16 ft<sup>3</sup> chamber)

Did the cycling run continuously without interruption? to failure (yes) (New parts from Service)

How much current was going through the switch? - must check 7.42mA @ 14V

Was the current level recorded? - no

Was the applied voltage recorded? - must check

regards,  
Steve Reimers  
RV&T EESE Chassis E/E Systems  
313 39 03286, fax 313 39 04145

Photos of failed seals.

Risetime

Fall time


- 3 - master cylinder (Chrysler Neon) 50 cc/chamber  
1.5M cycle capable  
(pneumatically driven)
- 3/16" brake line (auto) to manifold
  - @ 1.5 Hz (2 Hz, could not get cycle below 40 psi).
  - Manifold had x150 cc include air bleed.
  - Injected hypo to bleed air from switch.
- 4 - 3000 psi range Xducer  
Signal Bandwidth to be checked.
- 

Manifold Sketch -

Pressure Rise Time  $\frac{1}{10}$  ~~second~~ Second

0.7 seconds dwell

Profile of a cycle



**Reimers, Steve (S.J.)**

---

**From:** Porter, Fred (F.J.)  
**Sent:** Wednesday, March 01, 2000 5:18 PM  
**To:** Reimers, Steve (S.J.)  
**Subject:** FW: Speed Control Deactivation Switch

—Original Message—

**From:** Sheffield, Drew (D.L.)  
**Sent:** Wednesday, March 01, 2000 3:29 PM  
**To:** Porter, Fred (F.J.)  
**Subject:** RE: Speed Control Deactivation Switch

Fred,

MI spoke with Bob of HI-Stat and gave him the name and numbers for our M/C suppliers – Bosch, Tokico, TRW, and Conti.

Sincerely,

*Drew Sheffield*

Purchasing Specialist, Front and Rear Suspension Modules  
Chassis & Electrical Commodity Management  
(313)337-8408, fax (313)317-4260, OMP MD 005

—Original Message—

**From:** Porter, Fred (F.J.)  
**Sent:** Thursday, February 24, 2000 4:47 PM  
**To:** Suter, Lawrence (L.D.); Sheffield, Drew (D.L.)  
**Cc:** Melnovsky, Bob (B.); Reimers, Steve (S.J.)  
**Subject:** Speed Control Deactivation Switch

Need your help to identify vehicle volumes.

We are moving forward with developing a new source for the switch. We have been working with Bob Melnovsky of HIStat as an alternative.

HIStat has provided an engineering estimate as follows:

Piece Price	\$2.29 @ 2M/year
	\$2.43 @ 1M/year
	\$2.59 @ 500k/year
Tooling	\$302,000
Capital	\$1,100,000

For our next steps, we need to accurately identify which vehicle lines are using this part and the volumes. This will help HIStat develop a more accurate business plan.

Then we need to identify the timing for implementing the new brake pedal clevis design so that we can coordinate a change to a brake pedal travel switch for this function. I understand the first implementation is scheduled for the '03 Windstar.

Do you know who we can contact for this information?

Regards,

Fred Porter  
Supervisor, Chassis E/E Systems Applications Engineering  
Phone: (313)84-53722 Fax: (313)39-04146  
E-mail: fporter@ford.com

**Reimers, Steve (S.J.)**

---

**From:** Porter, Fred (F.J.)  
**Sent:** Tuesday, June 06, 2000 5:10 PM  
**To:** Reimers, Steve (S.J.)  
**Subject:** FW: RPS Form from sreimers

FYI.

Regards,

Fred Porter  
Supervisor, Chassis E/E Systems Applications Engineering  
Phone: (313)84-53722 Fax: (313)39-04145  
E-mail: fporter@ford.com

-----Original Message-----  
**From:** Thomas, Sharon (S.C.)  
**Sent:** Tuesday, June 06, 2000 5:10 PM  
**To:** Porter, Fred (F.J.)  
**Subject:** RE: RPS Form from sreimers

This note is sufficient.

-----Original Message-----  
**From:** Porter, Fred (F.J.)  
**Sent:** Tuesday, June 06, 2000 4:49 PM  
**To:** Thomas, Sharon (S.C.)  
**Subject:** RE: RPS Form from sreimers

I approve this order. Do I need to enter this somewhere or is this note sufficient?

Regards,

Fred Porter  
Supervisor, Chassis E/E Systems Applications Engineering  
Phone: (313)84-53722 Fax: (313)39-04145  
E-mail: fporter@ford.com

-----Original Message-----  
**From:** Thomas, Sharon (S.C.)  
**Sent:** Saturday, June 03, 2000 12:40 PM  
**To:** Porter, Fred (F.J.)  
**Subject:** FW: RPS Form from sreimers

Fred, please approve.

-----Original Message-----  
**From:** wwadm@sstore.pds.ford.com [mailto:wwadm@sstore.pds.ford.com]  
**Sent:** Thursday, June 01, 2000 3:26 PM  
**To:** sthoma38@ford.com  
**Subject:** RPS Form from sreimers

**New Order**

Requested by: sreimers  
Telephone: 1-313-3903286  
Building: 402834, ou  
Room Number: 3E008

Ship to:  
345 S MILL ST  
LEXINGTON, Ohio  
44904

Attn: David Schaefer,  
phone 419-884-4156  
Total Part Cost: 40,000  
Total Service Cost: 0  
Total Tooling Cost: 0  
Combined Cost: 40,000

Buyer: Trueblowski, Dan  
Supplier Code: F903  
Supplier Name: HI-Stat  
Supplier Address:  
2350 Franklin Road  
Suite 200  
Bloomfield Hills, Michigan 48302  
Supplier Contact: Bob Melanovsky  
Supplier Phone: 248-332-2280  
Supplier Fax: 248-332-2296  
Required Date: 6/30/2000  
Worktask/Project: J00  
Department Code: T402


**Purpose:**

We are working with HI-Stat to develop them as a Brake Pressure switch supplier.

Base part number is 9F924.

50 proto-type BrakePressure Switch  
40000

800



**Request for Central Laboratory Service**  
 15000 Country Dr., Dearborn, MI 48120-1267 FAX (313) 32-21614

All shaded areas must be filled in to process your request.

Administrative Use Only	
Laboratory Number <b>03072</b>	Date <b>9-12-00aj</b>

Secondary Contact <b>FRED Porter</b>	Telephone	CDS ID	FAX
---	-----------	--------	-----

Requester's Name/Dept./PO Box	Send Report To	SHIP To
-------------------------------	----------------	---------

Part # (Continued)	Sample Handling <input checked="" type="checkbox"/> Return after test <input type="checkbox"/> Dispose after test	Source	TOXCAS #	Supplier
-----------------------	--	--------	----------	----------

<b>F2UC-9F924-AB</b>	<b>#2, #5, 5XEMPAR</b>	<b>N/A</b>	<b>N/A</b>	<b>TI</b>
<b>Brake Pressure Switch</b>				

Requester Info. Box (Requester Use)
Stop testing upon failure? <input type="checkbox"/> No <input type="checkbox"/> Yes

**Specific Testing Requirements/Additional Sample Information**

**X RAY (PHOTOS) of Samples.**  
**Completed and Samples returned.**  
**Photos taken with Samples.**  
**Samples in Lab**

Report [A signed hard copy final report will be mailed.]	
[Check any others that apply.]	
Date you would like report: <b>9-12-00</b>	<input type="checkbox"/> Transmit preliminary results <input type="checkbox"/> FAX final report <input checked="" type="checkbox"/> Send photographs only
Date you must have report: <b>9-13-00</b>	<input type="checkbox"/> Phone preliminary results <input type="checkbox"/> No typed report (results/data)

Administrative Use Only		
Initial Reading		
<input type="checkbox"/> Chemistry (313) 32-7877	<input checked="" type="checkbox"/> Metallurgy & Mechanical (313) 32-21613	<input type="checkbox"/> Polymers, Coatings & Corrosion (313) 99-46694

For information about services or assistance in completing this form, refer to the Central Laboratory WEB page. ([www.dearborn3.ford.com/central/central.htm](http://www.dearborn3.ford.com/central/central.htm))  
 Laboratory number and date cannot be assigned without receipt of samples.  
 Samples will be disposed of 30 days after report completion, unless otherwise requested.



Central Laboratory  
 15000 Century Drive  
 Dearborn, MI 48120-1297  
 FAX (313) 322-1614

Report 03022

September 13, 2000

To: S. Reimers (313) 3-03286 (313) 39-04146 FAX

From: A. Zinkosky (313) 59-41444

Subject: Brake Pressure Switch  
 Part Number: F2VC-8F924-AB  
 Specification: Not provided  
 Supplier: Texas Instruments

Received: The brake pressure switch assemblies were received on September 12, 2000 and were identified as: Exemplar; #2 and #5

Object: Provided radiographic service per request.

**Data and Analysis:**

The sample and documentary photographs were taken by the requester upon completion of the radiographic examination.

X-ray Film \_\_\_\_\_  
 X-ray Video Tapes \_\_\_\_\_  
 X-ray Photographs   x   were provided to the requester for his/her interpretation.<sup>1</sup>

<sup>1</sup> Corporate records retention policy requires that all negatives, tapes, and photographs be retained for three years from date of issue and then be properly disposed of. If your office does not wish to maintain the records as required, please return the radiographs for our file.

Concur: *P. F. Klass*  
 P. F. Klass, Supervisor  
 Metallurgy & Mechanical Section

By: *Alex Zinkosky*  
 Alex Zinkosky (AZINKOSK)  
 Laboratory Specialist

AZ/fej



Central Laboratory  
 15000 Century Drive  
 Dearborn, MI 48120-1287  
 FAX (313) 322-1814

Report 03022

September 13, 2000

To: S. Reimers (313) 3-03286 (313) 39-04145 FAX

From: A. Zinkosky (313) 59-41444

Subject: Brake Pressure Switch  
 Part Number: F2VC-9F824-AB  
 Specification: Not provided  
 Supplier: Texas Instruments

Received: The brake pressure switch assemblies were received on September 12, 2000 and were identified as: Exemplar #2 and #5

Object: Provided radiographic service per request.

**Data and Analysis:**

The sample and documentary photographs were taken by the requester upon completion of the radiographic examination.


X-ray Film \_\_\_\_\_  
 X-ray Video Tapes \_\_\_\_\_  
 X-ray Photographs   x   were provided to the requester for his/her interpretation.<sup>1</sup>

<sup>1</sup> Corporate records retention policy requires that all negatives, tapes, and photographs be retained for three years from date of issue and then be properly disposed of. If your office does not wish to maintain the records as required, please return the radiographs for our file.

Concur: P. F. Klaas  
 P. F. Klaas, Supervisor  
 Metallurgy & Mechanical Section

By: Alex Zinkosky  
 Alex Zinkosky (AZINKOSK)  
 Laboratory Specialist

AZ/acj



3713 9858

PRODUCED BY FORD


15



3713 9859

PRODUCED BY FORD

15



3713 9968

PRODUCED BY FORD

#2



3713 9861

PRODUCED BY FORD


#2



3713 9862

PRODUCED BY FORD

E2



3713 9863

PRODUCED BY FORD


#5




3713 9864

PRODUCED BY FORD

115



115



3713 9965

PRODUCED BY FORD

**Number of 1992 and 1993 Lincoln Town Car vehicles  
sold with Traction Control**

	1992 Lincoln Town Car vehicles sold with traction control	1993 Lincoln Town Car vehicles sold with traction control
Alabama	95	80
Alaska	13	11
Arizona	152	74
Arkansas	70	129
California	1581	1820
Colorado	231	330
Connecticut	348	434
District of Columbia	85	92
Delaware	43	41
Florida	358	417
Georgia	154	255
Hawaii	52	7
Idaho	51	39
Illinois	1914	2058
Indiana	392	620
Iowa	144	187
Kansas	253	394
Kentucky	122	160
Louisiana	156	230
Maine	32	42
Maryland	638	709
Massachusetts	486	681
Michigan	1360	2606
Minnesota	203	316

Number of 1992 and 1993 Lincoln Town Car vehicles  
sold with Traction Control

	1992 Lincoln Town Car vehicles sold with traction control	1993 Lincoln Town Car vehicles sold with traction control
Mississippi	14	6
Missouri	765	830
Montana	33	32
Nebraska	111	120
Nevada	76	80
New Hampshire	67	63
New Jersey	1895	2709
New Mexico	60	53
New York	2599	3301
North Carolina	168	202
North Dakota	41	51
Ohio	817	1156
Oklahoma	344	1248
Oregon	98	121
Pennsylvania	1430	1704
Rhode Island	11	3
South Carolina	84	85
South Dakota	28	44
Tennessee	204	341
Texas	527	807
Utah	63	105
Vermont	19	26
Virginia	654	728
Washington	180	219

Number of 1992 and 1993 Lincoln Town Car vehicles  
sold with Traction Control

	1992 Lincoln Town Car vehicles sold with traction control	1993 Lincoln Town Car vehicles sold with traction control
West Virginia	68	102
Wisconsin	310	407
Wyoming	27	27

- All 1992 and 1993 Lincoln Town Car vehicles are equipped with speed control and anti-lock brakes

Number of 1992 and 1993 Grand Marquis  
vehicles sold with Speed Control, Anti-Lock Brakes  
and Traction Control

	1992 Mercury Grand Marquis vehicles sold with anti-lock brakes and traction control	1992 Mercury Grand Marquis vehicles sold with speed control	1993 Mercury Grand Marquis vehicles sold with anti-lock brakes and traction control	1993 Mercury Grand Marquis vehicles sold with speed control
Alabama	400	426	548	260
Alaska	29	7	9	1
Arizona	463	211	355	138
Arkansas	122	189	210	110
California	2822	751	1860	372
Colorado	379	122	226	50
Connecticut	438	258	464	172
District of Columbia	292	0	282	0
Delaware	157	114	133	100
Florida	4298	5925	5804	3401
Georgia	1079	814	920	512
Hawaii	25	5	19	5
Idaho	67	79	45	46
Illinois	3330	2308	2161	1181
Indiana	686	616	508	287
Iowa	242	245	216	88
Kansas	363	151	269	65
Kentucky	319	294	293	150
Louisiana	410	580	488	282
Maine	75	214	94	89
Maryland	1155	515	963	316
Massachusetts	1128	1717	1370	1130
Michigan	3037	2310	1960	973

Number of 1992 and 1993 Grand Marquis  
vehicles sold with Speed Control, Anti-Lock Brakes  
and Traction Control

	1992 Mercury Grand Marquis vehicles sold with anti-lock brakes and traction control	1992 Mercury Grand Marquis vehicles sold with speed control	1993 Mercury Grand Marquis vehicles sold with anti-lock brakes and traction control	1993 Mercury Grand Marquis vehicles sold with speed control
Minnesota	512	523	555	314
Mississippi	157	207	226	139
Missouri	812	1137	648	605
Montana	89	9	73	3
Nebraska	151	137	121	57
Nevada	85	130	137	81
New Hampshire	120	281	186	165
New Jersey	2845	2330	3106	1339
New Mexico	148	57	150	59
New York	3331	2169	3223	1331
North Carolina	644	638	659	391
North Dakota	78	15	84	24
Ohio	1324	1613	1301	839
Oklahoma	265	283	3018	180
Oregon	152	23	140	7
Pennsylvania	2300	1529	2003	687
Rhode Island	10	24	23	14
South Carolina	382	336	412	207
South Dakota	62	8	52	1
Tennessee	421	473	446	272
Texas	1991	2071	1727	1111
Utah	102	23	107	37
Vermont	13	33	41	20
Virginia	994	500	969	333

Number of 1992 and 1993 Grand Marquis  
vehicles sold with Speed Control, Anti-Lock Brakes  
and Traction Control

	1992 Mercury Grand Marquis vehicles sold with anti-lock brakes and traction control	1992 Mercury Grand Marquis vehicles sold with speed control	1993 Mercury Grand Marquis vehicles sold with anti-lock brakes and traction control	1993 Mercury Grand Marquis vehicles sold with speed control
Washington	282	32	253	26
West Virginia	192	126	132	91
Wisconsin	639	571	552	205
Wyoming	74	39	54	18

- anti-lock brakes and traction control were sold as a package