

EA02-025

FORD 10/27/03

APPENDIX N

BOOK 37

PART 2 OF 3

What is SDS requirement number?

Visteon Speed Control by completed
SDS (SC-0068) states: The stop lamp switch and redundant deactivator
switch must be on the same fused circuit.

Is it feasible to disconnect the switch as immediate containment?

Yes. The customer will not have use of the speed control.

Is it acceptable to Jumper out the switch as immediate containment?

Visteon Speed Control by completed
NO... Would eliminate an important safety feature of the speed control
system. The Brake Pressure Switch provides the redundant method for
sensing brake application independent of the primary system deactivation
mode. This is an SDS (SC-0005) requirement.

Elimination of this feature requires the concurrence of the OGC.

Other recommendations for immediate containment?

All by on-going
Add fuse between the stop lamp fuse and the brake pressure switch?

Recommendations for increased Life of switch.

TI by 3/5/99
TI suggested looking at an Automotive ceramic diaphragm pressure
transducer (not a switch) that is used for ABS.

Brake Pressure Switch Test Log
Updated 2/16/99

Category	Test	Location	Test Parameters	Results Update
Lab Simulation of Potential Location in Switch	1	TI	Various Levels of Brake Fluid, Water, Deionized 14Vdc to one terminal, Newport grounded	100+ hours into test, max current 5mA No significant change with time
	2	TI	Various Levels of Brake Fluid, Water, Deionized 1 Amp through switch terminals	100+ hours into test No significant temperature rise with time
	3	AVT	Brake Fluid in Switch, 24 VDC to one terminal Newport Grounded	> 200 hours into test, max current 7mA No significant change with time
	4	AVT	Brake Fluid in Switch, 24 VDC to one terminal Newport Grounded, Ambient at 100 C	16 hours into test max current 5mA No significant temperature rise with time
	5	AVT	Brake Fluid in Switch, 18 Amps Through switch terminals	Temperature rise of 20 C above room temp Delta T reached steady state at 20 C
	6	TI	Build heater element into Switch Heat III failure	Expected update 2/19
Life Cycle Reliability of Pressure Switch	7	TI	0-1400 psi pressure pulses at 135C ambient per ES	Parts at 600k cycles, no leaks. Will continue to failure
Diaphragm Wear Field vs Lab Correlation	8	TI	0-1400 psi pressure pulses at 135C ambient	Parts withdrawn every 200k cycles, characterized for wear
	9	Central Labs	Various Field returns, from dealer lots, junkyards	Parts in Central Labs, being processed
Design Of Experiments Evaluating Factors Effecting Diaphragm Wear	10	TI	Various Levels of Brake Fluid, Water, Under ES conditions, in failure	Test being structured. Expected Phase One to begin 2/19
On-Vehicle Characterization of Pressure & Temperature Profile in Town Car	11	AVT	Monitor Pressure and Temperature at Switch Location for ABS and non-ABS braking events.	Logistics being worked out.

3719 4337

PRODUCED BY FORD


ES92-925-A 0899

Telecom

2/16/99

FROM: Norm LaPointe

Re: GTO Correlation Data for Brake Application
vs 99% Reliability of Switch



95 Percent
 Driver 16 sec car mile
 x Hours = Car miles

Need new Energy for B if A
 moves to right because of ABS
 modulation.

3713 1730

PRODUCED BY FORD

ERR2-B25-R 9891

* Note printed by FPORTER on 22 Feb 1999 at 16:45:00 *

From: I2060825--EXTERNAL Date and time 02/16/99 17:09:05
To: FPORTER --FORDMAIL 'Fred Porter (For NLAPPOINT--FORDMAIL 'Norm LaPointe | F
SLAROUCH--FORDMAIL 'Steve LaRouche (SREIMERS--FORDMAIL 'Steve Reimers | F
cc: PHEKSL2--EXTERNAL Beringhouse, Steve OTFWOGYK--EXTERNAL Sharpe, Robert

From: Rahman, Asiz
Subject: Brake Pressure Switch Test Log.xls

cc: "Beringhouse, Steven"<sherlinghouse@mail.mc.ti.com>,
"Dague, Bryan"<bdague@mail.mc.ti.com>,
"McGuirk, Andy"<a-mcguirk@mail.mc.ti.com>,
"Baumann, Russ"<rbaumann@mail.mc.ti.com>,
"Sharpe, Robert"<rsharpe@mail.mc.ti.com>

<<Brake Pressure Switch Test Log.xls>>

Team,

This is a first pass at the test log we can use to track our tests and to
update the core team on Wednesday meetings. Please review/add/edit/comment.

Thanks
Asiz.

Attachments sent separately:

Data Type	File Name
-----	-----
BINARY	BRAKEPR.XLS_PC

3713 1391

PRODUCED BY FORD

EAR2-825-A 9892

.....
* Note printed by FPORTER on 22 Feb 1999 at 16:43:06 *
.....

From: I2060625--EXTERNAL Date and time 02/17/99 01:48:48
To: FPORTER --FORDMAIL 'Fred Porter ; For NLAPOINT--FORDMAIL 'Norm LaPointe (F
SLAROUCK--FORDMAIL 'Steve LaRouche ; BREIMERS--FORDMAIL 'Steve Reimers (F

From: Rahman, Aziz
Subject: Brake Pressure Switch Evaluation Plan.xls

<<Brake Pressure Switch Evaluation Plan.xls>>

Team, please review evaluation plan. It is basically a collation of Steve R. and Norm's inputs. I will add the switch dissection section tomorrow. The pressure calibration station from TI is expected to arrive on Thursday and will probably reside at Central Labs due to availability of high pressure air.

Steve R, will Allan be available to perform the electrical characterizations data collection? I can definitely help with data analysis and maintenance of the database.

Please review the attachment and let's discuss tomorrow.

Thanks
Aziz.

Attachments sent separately:

Data Type	File Name
.....
BINARY	BRAKEPRE.XLS_PC

3713 1382

PRODUCED BY FORD

ED82-025-A 0003

* Note printed by FORTER on 12 Feb 1999 at 17:02:20 *

From: I2060025--EXTERNAL Date and time 02/18/99 12:49:21
To: FPORTER --FORDMAIL 'Fred Porter (For NLAPOINT--FORDMAIL 'Norm LaPointe (F
SLAROUCH--FORDMAIL 'Steve LaRouche (BREIMERS--FORDMAIL 'Steve Reimers (F
cc: PMS4K5L3--EXTERNAL Beringhouse, Steve OTWOGYK--EXTERNAL Sharpe, Robert

From: Rahman, Aziz
Subject: Switch Log and Eval. Procedure

cc: 'Beringhouse, Steven' <sbearinghouse@email.mt.ti.com>,
'Dague, Bryan' <bdague@email.mt.ti.com>,
'Baumann, Russ' <rbaumann@email.mt.ti.com>,
'McQuirk, Andy' <a-mcquirk@email.mt.ti.com>,
'Sharpe, Robert' <rsharpe@email.mt.ti.com>

Updated as of 2/18/99. There were some switches from the initial 24 switch survey that were opened up at AVT and the tag and switch parts were not kept together. I have noted this in the log.

Since the tag numbers for every incoming shipment start from 1, I suggest we use VIN numbers to track the database. This will uniquely identify the switch.

I suggest that the switch analysis priority be as follows:

- Switches from underhood fires, which have not been severely damaged
- Switches from Town Cars, starting by highest mileage and descending
- Switches from CV and GW, starting by highest mileage and descending
- Severely damaged switches from underhood fires
- Disassembled switches, with suspect paperwork trail

<<SwitchLog>>
Evaluation Procedure updated as of 2/18/99. Note identification of harness wires by color.

<<EVALPROC>>
I think we are closing in on finalizing the log format and the evaluation procedures. I believe that these are good enough for us to start using them for data entry.

In order to reduce confusion, I will plan on updating the log once a week. Please delete the earlier versions, so that you have only one latest copy.

Please comment..

Thanks
Aziz

Attachments sent separately:

Data Type	File Name
BINARY	SWITCHLO.XLS_PC
BINARY	EVALPROC.XLS_PC

3713 1387

PRODUCED BY FORD

EA82-825-A 9884

9900607
Raw DATA

NO FINAL REPORT
YET

3713 3008

PRODUCED BY FORD

ENG2-025-A 0005

TLE


SPRING CONTROL CIRCUIT SWITCH

Project No. 2-3267
Book No. 2097

am Page No. _____

2/7

PK



(19) STILL ATTACHED TO PUMP VALVE

DC 3098

CONNECTION BETWEEN FULL DISCLOSED

NOE APPEARANCE TO WIRE INSUL. (EXPOSED FLAME - FLAME TO WIRE
IMPRESSION IN PUMP VALVE IS EXHIBIT, BUT IS NOT DEEP OR
SHARP - SEEN FIRST APPEAR AS COMPRESSED AS OTHER
APPEARANCES

CAVITY 3 WIRE CLEAN FROM PUMP VALVE
INTERIOR OF OIL BURNER

SLIGHT IMPRESSION IN WIRE FROM PUMP
TERMINALS EXHIBIT SOME CORROSION

PK

TOWEL CASE (18) STILL ATTACHED TO PUMP VALVE

SWITCH BURNER

MOST OF BASE MISSING, CONTACTS, TERMINALS, TRANSFER
PIN MISSING

CUP EXPOSED - BASE COVERED WITH PAINT & GREEN DEPOSITS

PK

93 C.V. (110) DC 2772

STILL ATTACHED TO PUMP VALVE

CONNECTION APPEARS BARE EXPOSED

NO DAMAGE TO WIRE

IMPRESSION IN PUMP VALVE EXHIBIT & DEEP

CAVITY 3 WIRE CLEAN FROM PUMP VALVE
INTERIOR OF OIL BURNER

SLIGHT IMPRESSION IN WIRE FROM PUMP
TERMINALS EXHIBIT

PK

IC S-93 (113) DC 3089

CONNECTION PART EXPOSED

NO DAMAGE TO WIRE

SLIGHT IMPRESSION IN WIRE

IMPRESSION IN PUMP VALVE EXHIBIT & DEEP (ALL 3 WIRE)

WIRE & CAVITY CLEAN FROM PUMP VALVE
INTERIOR OF OIL BURNER

SLIGHT IMPRESSION IN WIRE FROM PUMP
TERMINALS EXHIBIT

To Page No. _____

Inspected & Understood by me.

Date

Invented by

Date

Observed by

3713 3008

From Page No. ...

Rx



J.S. (4) DC 2028

CAMERA ONE ENCLAVE
NO DEBRIS TO WIRE
BLACK BARRAGE IN HORIZONTAL
IMPRESSION IN SOIL FROM SOIL & DEBRIS
WIRE 1 ON WIRE CLEAN BELOW SOIL
TERRAIN CLEAN
IMPRESSIONS LEFT IN WIRE FROM SOIL
TERRAIN CLEAN

Rx

GRN. MAR (43) DC 3295

CAMERA FIVE ENCLAVE
SOIL DEBRIS TO WIRE (BRUSH, DEBRIS?)
CAMERA ON LEFT CAMERA TOWARD WIRE
IMPRESSION IN SOIL FROM SOIL
CAMERA 1 WIRE CLEAN BELOW SOIL
TERRAIN CLEAN
IMPRESSIONS IN WIRE FROM SOIL
TERRAIN CLEAN

Rx

6-92 J.S. (4) DC 2115

CAMERA NOT FULL ENCLAVE (OR WIRE NOT FULL
SECTION)
NO DEBRIS TO WIRE
BLACK BARRAGE IN HORIZONTAL
IMPRESSION IN SOIL FROM SOIL - OFF CENTER
CAMERA 1 WIRE CLEAN BELOW SOIL
IMPRESSIONS IN WIRE FROM SOIL
TERRAIN CLEAN

one
off
one

To Page N

Witnessed & Understood by me,

Date

Invented by

Date

Reported by

From Page No. _____

PX 2 C. Vic (44) DC 3025A

OF WIDE SIDE OF CONNECTION NOT FULL ENGAGED
WIDEN THROTTLE, BUT NO APPARENT DAMAGE
BLACK RESIDUE WITH GREEN ON JUST CORNER ANGLE
IN HORIZONTAL
UNRECOGNIZED IN 200 JPM 504, 504, 504, 504, 504
CAVITY 4 WIDE CORNER BELOW 504, 504
IN 504, 504, 504, 504, 504
100% RESIDUE ON 504 IN WIDE
TREATMENT ABOVE:

NY 2 BURRO (46) DC 2031

MOST OF BASE MISSING
CONTACTS, TERMINALS, TRANSFORMER PIN MISSING
NO CONTACTS
PART OF FACE OF C-15 ENVELOPE A LITTLE
WITH JUST 3 GREEN IN CENTER
BROWN RESIDUE IN HORIZONTAL

PX 7 T.C. #7 DC 30B1A

EXTRA PART WITH OFF WHITE DISC TO
ON 200 JPM 504
CONNECTED PART MISSING
THE ADDITION TO WIDE (HORIZONTAL?)
BLACK RESIDUE WITH GREEN ON JUST CORNER
ANGLE IN HORIZONTAL
UNRECOGNIZED IN 200 JPM 504, 504, 504
CAVITY 4 WIDE CORNER BELOW 504, 504
IN 504, 504, 504, 504, 504
100% RESIDUE ON 504 IN WIDE
TREATMENT ABOVE

To Page No. _____

Inspected & Understood by me.	Date	Invented by	Date
		Recorded by	

3713 3010

From Page No. _

PX

T.C (#5) DC 2043A

EVIDENCE OF HEAVY METAL (DRUMMA BRASS
PLUG?)

CONNECTOR WAS FOUND

NO REMAINS TO WIRE.

BRASS BRASS DEPOSIT IN HEAVY

IMPRESSION IN RED GUN CASE 4 DEPT - 608 0000

ONE CONNECTOR WAS WITHIN BRASS BRASS

DURING TO EDGE OF SWITCH

Cavity 2 wires shown below 4000 5000

Some all brass gun

IMPRESSION IN WIRE BRASS 5000

TERMINAL CLEAN

IN BOX - NO CONNECTORS

NY

4-92 86922 (#7TX) DC 2059

TERMINAL CLEAN

TERMINAL CAVITY DR

BLACK RESIDUE IN HEAVY

PY

3-93 91358 (#11TX) DC 3028

TERMINAL & CAVITY CLEAN & DR

BLACK RESIDUE IN HEAVY

PY

12-92 87224 (#10TX) DC 2331

TERMINAL & CAVITY CLEAN & DR

BRASS BRASS CLEANED IN HEAVY

PY

9-92 88087 (#4TX) DC 204E

Cavity Clean & DR

ONE TERMINAL - BRASS CLEANED

IN AREA SURROUNDING BY CONNECTOR.

OTHER TERMINAL CLEAN

BLACK RESIDUE WITH BRASS BRASS

CLEANED IN HEAVY

To Page No.

Witnessed & Understood by me.

Date

Invented by

Date

Examined by

3713 3011

1st Page No. _____

4/8

PX [REDACTED] 3-93 71337 (#3TX) DC 3015

TERMINALS AND CAVITY CLEAN & DRY
BLACK RESIDUE & BROWN BRONN RESIDUE
IN HOLEPOT.

NX [REDACTED] 2-92 73164 (#4TX) DC 2006

TERMINALS & CAVITY CLEAN & DRY
BLACK RESIDUE IN HOLEPOT.

PX [REDACTED] 3-73 63614 (#8TX) DC 3025A

TERMINALS & CAVITY CLEAN & DRY
BLACK RESIDUE IN HOLEPOT

PX [REDACTED] 12-92 GUN MAG (#9TX) DC 2260

TERMINALS & CAVITY CLEAN & DRY
BLACK RESIDUE IN HOLEPOT

DISASSEMBLY OF ^{3025A} SWITCHES

PX [REDACTED] TERMINALS & CAVITY CLEAN & DRY

TERMINALS CLEAN FOR
CUP CONTACTS WHICH COORDINATION BELOW CONTACT PINS

REMOVE SW. HOLEPOT, IN PLACE, AND REMOVE
TO INSIDE PLATING

APPROX. TO BE WASHED (ELECTROLYTIC WASHING)
IN SWITCH CAVITY

WASH OF OLD CONTACTS WITH JUST CONTACT
RESIDUE

TRANSFER TO BENCH IN PLACE BY GENTLY POUNDING

INDIVIDUAL CONTACT THE CONTACTS NEAR THE

BASE OF CONTACTS & INSIDE CLEAN

GREEN OIL

WASH OUT CONTACT INTERF. - APPROX. TO 50% ON

#1 KNOCK SW. TERMINAL END SIDE TRAY

NEED TO NO APPEARANCE DAMAGE TO KNOCK
BELOW TRAY

KAYTON DEFENSE TO CONFIDENTIAL To Page No. _____

Read & Understood by me,

Date

Invented by

TELETYPE PLANT

Date

From Page No. _____

PX



#2 KAPTON - DEFORMED - NO APPARENT DAMAGE NOT BROADCAST

#3 KAPTON DEFORMED TO CONFORM TO WASHO BLOCK BELONGS WHERE IS CONTACTED CONVENTION & WASHO NO APPARENT THERMAL CHANGE NOT BROADCAST

SPRING BROWN / OLIVE APPEAR ON SEAL SIDE OF WASHO & CONVENTION INTERIOR OF THE BATTERY JUST DURING AN WASHO, CONVENTION, & AIR BLACK REGIONS IN NEGATIVE CAPSULE

PX

CONVENTION DEL - THERMAL CHANGE RECORDING CAPSULE PAPER - NO CHANGE UNDER BATTERY

ENV. SEAL INTACT, MELANGE APPEARS TO BE NORMAL

FOOTER OF THE CAPSULE WITH BUST & WHITE CALIBER DOTS - WASHO - WASHO (SUBSEQUENT QUALITY OF BATTERY) XRAY PX APPEARS IN PLACE OF CONVENTION RECORDS

NUMERICAL CONTROL DISCOVERED UNDER THE CAPSULE & LABELS FROM OTHER SOURCE. OTHER PX

HEAVY GROUND SEAL OK

#1 KAPTON - ONE AREA ON BLUE SIDE DEFORMED WASHO - APPEARS TO BE IN THERMAL ZONE DOES NOT SEEM TO HAVE BEEN AFFECTED

To Page 8

Witnessed & Understood by me,

Date

Invented by

Date

Recorded by

3713 3013

From Page No. _____

To Page No. _____

PX [REDACTED] Carbure

#2 KARTON - DOES NOT APPEAR TO HAVE BEEN BRANCHED

#3 KARTON - SAME

KARTON SIDE OF WASHING & CONDITIONING - LOCATIONS BLACK DISCOLORATION

INSIDE OF CURTAIN HOOKS FROM OF CURTAINS, WASHED, COVERED WITH WHITE RUST COLORED DEPOSITS.

BLACK DEPOSITS IN HOLLOW OF CURTAIN

LaRue
3-4-93

To Page No. _____

read & Understood by me.

Date

Invented by

Date

3713 3014

ERG-825-A 9883

PRODUCED BY FORD

From Page No. 8514 Steve

Continuation: See Page 78

The SWITZERS FEEL FROM OASIS

[REDACTED] 92 TC E2VC DC 2062
LEADS

VIA SEM

BLACK REGION WITH SECTION OF EAST COAST
AND IN HOUSE
PROBABLY BRASS FIVE IN TERMINALS
BLACK REGION ON TERMINALS & AT INTER
TERMINALS WHERE THEY COME THROUGH BRASS
CUT GRIND AREA
ENV SEM INTER, NPLMS, JOHN ADN TO FROM
GRAND
FACE OF CUT CENTER WITH BLACK JUDGE
AND FOR FOR CLIMATE ANALYSIS
NEEDING MORE NEEDS TO HAVE BEEN
CHARGE OF
SHOULD HAVE BEEN WHERE ACCESS TO
BE BEEN FIVE IN TERMINALS & CUT
CHARGE AREA

NY [REDACTED] 92 TC E2VC 2128
LEADS

VIA SEM

BLACK REGION WITH SECTION OF EAST COAST
AND IN HOUSE
PROBABLY BRASS FIVE WITH BLACK REGION
IN TERMINALS AREA - BRASS (BLACK) IN TERMINALS
TERMINALS FROM BRASS AREA
CUT AREA

To Page

Witnessed & Understood by me.	Date	Invented by	Date
		Recorded by	

3713 3015

TITLE Spaced Letter Copying Sheet

Project No. 7-13-57

Book No. 3697

From Page No. 5514

2
12

ONE TOP INTEREST, IN PLACE. ~~TOP~~ ADD. TO INTEREST JOURNAL.
BLACK SLIDES WITH CURVED SURFACES. SLIDES IN
FACE OF CAR.

MAKING CONTACT BETWEEN SLIDES
PROVIDES BACKLASH TO BLACK SLIDES AND ADD IN
JOURNAL DRIVE.
BASE OF TERMINAL FLANGE.

Lip Review
3-17-59

To Page No. _____

Witnessed & Understood by me,

Date

Invented by

Date

Recorded by

3713 3016

EA92-625-A 9888

PRODUCED BY FORD

TITLE Switch - Speed Control Cutoff

Project No. 3000107
Book No. 2771

(5)

From Page No. -

Re: G. Stevens / S. LaRoche (313) 32-10816 (313) 39-C7224

Subject: Switch - Speed Control Cutoff
Part Number: F2VY-9F924-A
Specification: Not Provided
Supplier: Texas Instruments

Received: Nine samples identified as follows:
PU614995 - cup face & hexport
NY736847 - cup face & hexport
PY605826 - cup face; hexport & cup interior
NY54410 - hexport & cup interior

Object: Determine the elemental composition of the particles

Surface Analysis

Five of the nine particles were moist. They needed to be cleaned in the ultrasonic in freon, then filtered, with vacuum.
The elements detected are listed in decreasing order of intensity.
The number of particles is listed in parentheses.

<u>PY614995 cup face (5)</u>			<u>NY736847 cup face (2)</u>	
<u>Particle 1 & 2</u>	<u>Particle 3</u>	<u>Particles 4 & 5</u>	<u>All Particles</u>	
<u>Zinc</u>	<u>Iron</u>	<u>Zinc</u>	<u>Zinc</u>	
<u>Iron</u>		<u>Iron</u>	<u>Copper</u>	
<u>Copper</u>		<u>Copper</u>	<u>Silver</u>	
<u>Silicon</u>		<u>Sulfur</u>	<u>Iron</u>	
<u>Calcium</u>		<u>Silicon</u>	<u>Potassium</u>	
		<u>Calcium</u>	<u>Silicon</u>	
			<u>Sulfur</u>	
			<u>Calcium</u>	

* Spikes saved on ISE system show No peak labeled. NDS analysis
(confirmed this peak is actually Zn. The peak is mislabeled in file:
10 cup part 5, 3, 2, 1 4 hexport 4, 3, 2
Zn cup part 3, 1 4 hexport 6, 5, 4, 3, 2, 1
95 hexport 5, 4, 3, 2, 1

To Page No. 20

Witnessed & Understood by me,	Date	Invented by	Date
		Recorded by	

3713 3017

PRODUCED BY FORD

ENG-825-A 9808

3514

Project No. 9AC667
Book No. 2771

TITLE

Switch-Speed Control "dotoff"

From Page No. B

F [redacted] hexpart (5)

Particle 1	Particle 2	Particle 3	Particle 4	Particle 5
Iron	Iron	Iron	Iron	Zinc
Copper	Copper	Manganese		Iron
Manganese	Chromium	Aluminum		Copper
Sulfur	Potassium	Sulfur		Sulfur
	Sulfur	Silicon		Silicon
	Aluminum			Calcium
	Manganese			
	Silicon			
	Calcium			

N [redacted] hexpart (5)

Particle 1	Particle 2	Particle 3
Iron	Zinc	Iron
Potassium	Copper	Potassium
Sulfur	Iron	Sulfur
	Chromium	Copper
	Silicon	
	Sulfur	

P [redacted] cupface (3)

All Particles
Copper
Silver
Zinc
Iron
Potassium

E [redacted] hexpart (4)

Particles 1&4	Particles 2&3
Copper	Copper
Zinc	Zinc
Potassium	Potassium
Sulfur	Sulfur
Chromium	Silicon

P [redacted] cupface (4)

All Particles
Copper
Zinc
Chromium
Iron
Potassium
Sulfur

NP [redacted] cupface (4)

All Particles
Copper
Zinc
Sulfur
Potassium
Silicon
Chromium
Iron

M [redacted] cupface (3)

All Particles
Zinc
Copper
Silver
Potassium
Sulfur

All Spectra saved on IES system.
All remnants of copy of results
to Steve, L. Huber.

5/1/69

CD

To Page No.

Witnessed & Understood by me,

Date

Invited by

Date


Recorded by

3713 3018

PRODUCED BY FORD

ERR2-825-A 9987

Operator: Chantal Stevenson
Client: [REDACTED]
Job: 9800607
28hexpart4 (5/7/99 16:34)



3713 3019

PRODUCED BY FORD

ENG2-625-A 9806


Operator : Chantal Stevenson

Client : ██████████

Job : 9900807

28hexpart3 (5/7/99 16:31)

cpa



3713 3020

PRODUCED BY FORD


EA82-025-A 9999

Operator : Chantell Stevenson

Client : ██████████

Job : 9900607

26hexp12 (5/7/99 16:27)




Operator: Chantal Stevenson

Client: [REDACTED]

Job: 6900607

26hecpart1 (5/7/99 18:24)

cps



3713 3022

PRODUCED BY FORD

ERR2-025-A 0911


Operator: Chantell Stevenson

Client: [REDACTED]

Job: 9900807

25cupfacepart3 (5/7/99 16:18)

cps




3713 3023

PRODUCED BY FORD

EA82-825-R 9812

Operator : Chantell Stevenson
Client : ██████████
Job : 9900807
28cupfacepan2 (5/7/99 16:14)




3713 3024

PRODUCED BY FORD

ERR2-825-A 9913

Operator: Chantal Stevenson
Client: [REDACTED]
Job: 000007
26cup/acapart1 (5/7/99 16:11)



3713 3025

PRODUCED BY FORD

E982-025-A 0014


Operator: Chantell Stevenson

Client: [REDACTED]

Job: 9900007

10ciper5 (5/7/99 18:02)

cps



3713 3026

PRODUCED BY FORD

EA82-825-A 8915


Operator: Chantell Stevenson

Client: [REDACTED]

Job: 9900607

10cipart4 (5/7/99 15:26)

cps




3713 3027

PRODUCED BY FORD

EAD2-825-A 0018

Operator : Charrell Stevenson
Client : ██████████
Job : 9900607
10cipart3 (5/7/98 15:26)




3713 3028

PRODUCED BY FORD

ERR2-825-A 8017

Operator : Chantell Stevenson
Client : ██████████
Job : 9900607
10cipart2 (5/7/99 15:23)



3713 3029

PRODUCED BY FORD

ER62-625-A 9918


Operator: Chestall, Stevenson

Client: [REDACTED]

Job: 9900607

10cpart1 (5/7/99 15:18)

cps



3713 3030

PRODUCED BY FORD


ER62-025-A 8818

Operator: Chantell Stevenson

Client: [REDACTED]

Job: 9900807

25cipar4 (5/7/99 15:15)




3713 3031

PRODUCED BY FORD

EDS2-825-A 9928

Operator : Chantal Stevenson
Client : XXXXXXXXXX
Job : 9900607
26cipart3 (5/7/99 15:11)



3713 3032

PRODUCED BY FORD

ER02-025-A 0921


Operator : Chantell Stevenson

Client : ██████████

Job : 9900607

28clpart2 (5/7/99 15:08)

cps



3713 3033

PRODUCED BY FORD

EA82-025-A 0822


Operator : Chantell Stevenson

Client [REDACTED]

Job : 9900807

ztcipar1 (5/7/99 15:05)

cps



3713 3034

PRODUCED BY FORD

ERS2-825-A 8923


Operator: Chantell Stevenson

Client: [REDACTED]

Job: 9800607

25carbontape (5/7/99 15:02)

cps



3713 3036

PRODUCED BY FORD

ER82-825-A 9824


Operator : Chantell Stevenson

Client : ██████████

Job : 9900607

10hexpan4 (5/7/99 14:53)

cps




Operator : Chantel Stevenson

Client : [REDACTED]

Job : 990607

10hexpart3 (5/7/99 14:49)

cps



3713 3037

PRODUCED BY FORD

ER02-025-A 0026


Operator : Chantall Stevenson

Client : ██████████

Job : 9900607

10hexpart2 (5/7/99 14:45)

cps



3713 3038

PRODUCED BY FORD


ER62-825-A 8927

Operator: Chantell Stevenson

Client: [REDACTED]

Job: 9900807

10hexpart1 (5/6/99 11:34)




3713 3039

PRODUCED BY FORD

ER02-025-A 0028

Operator : Chantell Stevenson
Client : ██████████
Job : 9900807
47facepartB (5/8/99 11:07)



3713 3040

PRODUCED BY FORD

ER02-025-A 9929


Operator : Chantell Stevenson

Client : ██████████

Job : 9900807

47facepart5 (5/5/99 11:04)

cps




3713 3041

PRODUCED BY FORD

ER02-825-A 8938

Operator: Chantal Stevenson
Client: [REDACTED]
Job: 9900907
47facepart4 (5/6/99 11:00)



3713 3042
PRODUCED BY POND

ER82-825-A 9931


Operator: Chantal Stevenson

Client: [REDACTED]

Job: 9900607

477acpart3 (5/5/99 10:57)

cps



3713 3043

PRODUCED BY FORD

ER92-625-A 8932


Operator : Chantell Stevenson

Client [REDACTED]

Job : 9900607

47facepart2 (5/6/99 10:54)

cps




3713 3044

PRODUCED BY FORD

ER92-825-A 9933

Operator: Chantal Stevenson
Client: [REDACTED]
Job: 990007
47facepart1 (5/5/99 10:51)




3713 3045

PRODUCED BY FORD

ER02-625-A 9934

Operator: Chantell Stevenson
Client: [REDACTED]
Job: 9900607
95facepart5 (5/6/99 10:49)



3713 3046

PRODUCED BY FORD

ER62-825-A 9835


Operator : Charrel Stevenson

Client : ██████████

Job : 9900907

85facepart4 (5/8/99 10:45)

cps



3713 3047

PRODUCED BY FORD

ER82-825-R 9838


Operator : Chantell Stevenson

Client : [REDACTED]

Job : 9900607

95facepart3 (5/8/99 10:41)

cps



3713 3048

PRODUCED BY FORD


E982-025-A 9837

Operator : Chantell Stevenson

Client : [REDACTED]

Job : 9600607

95facapert2 (5/6/99 10:38)



3713 3048

PRODUCED BY FOR


EA82-825-A 9836

Operator : Chantell Stevenson

Client : ██████████

Job : 9900607

95facepart1 (5/6/99 10:35)



3713 3050

PRODUCED BY FORD

EA02-025-A 9938


Operator: Chantell Stevenson

Client: [REDACTED]

Job: 9900807

95hexpart5 (5/6/99 10:26)

cps



3713 3051

PRODUCED BY FORD

ERR2-825-A 9848


Operator: Chantell Stevenson

Client: ██████████

Job: 9000807

95hexpart4 (5/6/99 10:23)

cps



3713 3052

PRODUCED BY FORD

ER02-025-A 9941


Operator: Chantal Stevenson

Client: [REDACTED]

Job: 8900607

95haupart3 (5/8/98 10:21)

cps



3713 3053

PRODUCED BY PC

ER62-625-A 9942


Operator: Chetall Stevenson

Client: ██████████

Job: 9600607

95hexpart2 (5/5/99 10:18)

cps



3713 3054

PRODUCED BY FORD

ERG2-825-R 9943


Operator : Chantall Stevenson

Client [REDACTED]

Job : 9900507

95hexpart1 (5/6/99 10:16)

cps



3713 3055

PRODUCED BY FORD

ER02-825-A 9944


Operator: Chantell Stevenson

Client: [REDACTED]

Job: 9900607

carbon tape (5/6/99 10:12)

cps




3713 3056

PRODUCED BY FORD

ER02-025-A 9845

Operator: Chantel Stevenson
Client: [REDACTED]
Job: 9800907
47haxpart5 (5/5/99 10:07)



3713 3057

PRODUCED BY FORD

ER02-025-A 0946


Operator : Charrell Stevenson

Client [REDACTED]

Job : 9900607

47hexpart4 (5/8/99 10:05)

cps




3713 3058

PRODUCED BY FORD

ER82-825-A 9847

Operator: Chantel Stevenson
Client: [REDACTED]
Job: 9900807
47haexpert3 (5/6/99 10:02)




3713 3059

PRODUCED BY

EDS-225-A 884

Operator: Chantal Stevenson
Client: [REDACTED]
Job: 9900607
47hexpart2 (5/5/99 16:10)



3713 3080

PRODUCED BY FORD


ERR2-825-A 9849

Operator: Chantel Stevenson

Client: [REDACTED]

Job: 8900607

47hexpart1 (5/5/09 16:07)



3713 3061

PRODUCED BY FORD

ERR2-825-A 8858



Central Laboratory
15000 Century Drive
Dearborn, MI 48120-1257
FAX (313) 322-1614

Report 9900907

April 13, 1999

To: G. Stevens/S[redacted] (313) 32-38698 (313) 39-07224 FAX

From: Gayle D. Gulten (313) 32-27322

Subject: Deposits - Speed Control Switch

Source: N[redacted] and PY[redacted]

Received: The following items were received on March 25, 1999, from S. LaFouche:

- NY66003, Top, -4mL green fluid labeled- "Brake fluid reservoir top, 3/1/99, NY[redacted] 92TC"
- NY[redacted] Master Cylinder, -5mL green fluid labeled - "Master cylinder front port, 3/1/99, NY[redacted]"
- PY[redacted] Cup
- PY[redacted] Hexport
- NY[redacted] Cup
- NY[redacted] Hexport

Object: Determine if oxalate and/or brake fluid is present in the cup and hexports and what the nature of the black residue is in the fluids.

Conclusion: Brake fluid was found in all the samples tested. Oxalate-type materials were found in both the N[redacted] hexport (hydrocarbon may also be present in both this hexport and cup sample) and the PY[redacted] hexport samples. Both of the N[redacted] brake fluid samples showed evidence of nitrogenous and/or carboxylic acid salt material as well as possibly some hydrocarbon. The darker residue in these fluids could not be separated, however, these fluids contain elevated levels of zinc and copper as well as probably sulfur (which may account for the darker color). The zinc and copper may have been absorbed from the metallic constituents and be present as the metallic portions of the carboxylic acid salt while the sulfur may indicate the presence of a sulfur-based material (possibly such as a mineral oil-based (hydrocarbon) material, i.e. lubricating oil). Based on the boron levels and the infrared, neither of these two brake fluids appears to be factory fill Dow HD 50-4.

Data and Analysis:

Molecular Characterization

(FTIR, Qualitative)

PY605828 Deposit

Spectra of the cup are characteristic of essentially a glycol ether-based material.

Spectra of the hexport are characteristic of essentially a glycol ether-based material and an oxalate.

NY734410 Deposit

Spectra of the cup are characteristic of essentially a glycol ether-based material (some hydrocarbon may also be possible).

Spectra of the hexport are characteristic of essentially a glycol ether-based material, an oxalate, and other material (possibly including a hydrocarbon).

NY66003 Fluids

Spectra of the reservoir top brake fluid are characteristic of a glycol ether based material and other material (possibly including nitrogenous and/or carboxylic acid salt and hydrocarbon).

Spectra of the master cylinder brake fluid are characteristic of a glycol ether-based material and other (possibly including nitrogenous and/or carboxylic acid salt and possibly hydrocarbon).

Elemental Analysis, mg/kg
(ASTM D 5185-93)¹

	<u>Top</u>	<u>Master Cylinder</u>	<u>Unused Dow HD 50-4</u>
Aluminum	1	2	<1
Boron	22	12	138
Barium	<1	<1	<1
Calcium	1	2	<1
Cadmium	1	1	<1
Chromium	1	1	<1
Copper	486	500	<1
Iron	4	8	1
Magnesium	2	3	<1
Manganese	1	1	<1
Molybdenum	1	1	<1
Sodium	392	393	588
Nickel	<1	<1	<1
Phosphorus	11	11	6
Lead	22	25	1
Sulfur	183	184	<1
Silicon	4	4	<1
Tin	9	9	5
Titanium	<1	<1	<1
Zinc	501	552	<1

Water Content of Fluids, % by weight
(ASTM E 203)NY [redacted] - Reservoir Top
1.4NY [redacted] - Master Cylinder
1.4Particulates

Both the NY [redacted] reservoir top and master cylinder fluids were filtered through an 8µm nylon filter over a 40 Whatman filter. No particulates were gathered.

The precision and accuracy of results obtained by this method are within ±3% at 95% confidence level.

Contributor:

Contact:

Mary Hage
Organic Section

By:


Gayle D. Gulen (GGULEN)
Product Materials Engineer

Request for Central Laboratory Service

Receipt - Copy

Lab Request Number: 009900607

Date of Request: 02/22/1999 08:17:31 AM

Print Date: 03/25/1999 02:43:49 PM

Request Description: SPEED CONTROL CUTOFF SWITCH

Requester Information:

Primary Contact: STEVENS, GREG - 10006

Phone: (313) 323-8896

PROFS ID: GSTEVEN1

Fax: (313) 380-7224

Secondary Contact: LA POINTE, NORM - 18076

Phone: (313) 604-2686

PROFS ID: NLAPON1

Fax: (313) 337-8266

Send Report to:

MD 68040000, AVT MATERIALS, BLDG. #5

Bill to:

Acqg.Location: 5100

Dept: T113

Work Task: X0G04

Sample Information:

Total Number of Containers: 21

Sample Handling: Risked after test

Source: Not specified

Supplier Code: Not specified

Additional Name

SPEED CONTROL

CUTOFF SWITCH

Qty: 21

Sample Identification

SEE ATTACHED SH

EET

Part Number

F2VY-8F824-A

Material Spec

NA

CPSC Code

00.00.00

Supplier

TEXAS

INST

NUMEN

TS

Investigation Information:

Name of Investigator/Requester Info. Box: Mail typed report

Additional Sample Information/Testing Requirements:

EXAMINE, DOCUMENT, AND ANALYZE SWITCHES PER PROTOCOL ESTABLISHED BY N. LAPONTE TO ASSIST IN DETERMINING CAUSE OF POSSIBLE SWITCH FIRE OR LEAKAGE. SWITCHES ARE FROM FIELD SURVEYS. MORE SWITCHES MAY FOLLOW.

Reporting Directions:

Date customer would like report: 04/01/1999

Date customer must have report: 04/01/1999

Report Format(s):

Log-In Information:

Initial Request: Metaburg

Accepted for Central Laboratory by: Lafouche, Steve

Phone: 64-54876

View your lab status at: [HTTP://bd4web.pd7.ford.com/kalis](http://bd4web.pd7.ford.com/kalis)

Program Name: KALISLab Engr Module

Program Version: Version: 2.0.6

PLEASE DETERMINE THE FOLLOWING:

Oil & Hexameth Samples
Presence of Brake Fluid
Presence of Oxylates, etc.

Brake Fluid Samples
Presence of Oxylates, etc.
Water Content if possible

Thomas

Steve Lafouche



Central Laboratory
15000 Century Drive
Dearborn, MI 48120-1257
FAX (313) 322-1614

Report 9900607

April 13, 1999

To: G. Stevens/S. LaRouche (313) 32-3668 (313) 38-07224 FAX

From: Gayle D. Gullen (313) 32-27322

Subject: Deposits - Speed Control Switch
Source: NY [redacted] and PY [redacted]

Received: The following items were received on March 25, 1999, from S. LaRouche:

- NY [redacted] Top, -4mL green fluid labeled- "Brake fluid reservoir top, 3/1/99, NY [redacted] 92TC"
- NY [redacted] Master Cylinder, -5mL green fluid labeled - "Master cylinder front port, 3/1/99, NY [redacted]"
- P [redacted] Cup
- P [redacted] Hexport
- N [redacted] Cup
- N [redacted] Hexport

Object: Determine if oxalate and/or brake fluid is present in the cup and hexports and what the nature of the black residue is in the fluids.

Conclusion: Brake fluid was found in all the samples tested. Oxalate-type materials were found in both the NY [redacted] hexport (hydrocarbon may also be present in both this hexport and cup sample) and the P [redacted] hexport samples. Both of the NY [redacted] brake fluid samples showed evidence of nitrogenous and/or carboxylic acid salt material as well as possibly some hydrocarbon. The darker residue in these fluids could not be separated, however, these fluids contain elevated levels of zinc and copper as well as probably sulfur (which may account for the darker color). The zinc and copper may have been absorbed from the metallic constituents and be present as the metallic portions of the carboxylic acid salt while the sulfur may indicate the presence of a sulfur-based material (possibly such as a mineral oil-based (hydrocarbon) material, i.e. lubricating oil). Based on the boron levels and the infrared, neither of these two brake fluids appears to be factory fill Dow HD 50-4.

Data and Analysis:

Molecular Characterization
(FTIR, Qualitative)

PY [redacted] Deposit

Spectra of the cup are characteristic of essentially a glycol ether-based material.

Spectra of the hexport are characteristic of essentially a glycol ether-based material and an oxalate.

NY [redacted] Deposit

Spectra of the cup are characteristic of essentially a glycol ether-based material [some hydrocarbon may also be possible].

Spectra of the hexport are characteristic of essentially a glycol ether-based material, an oxalate, and other material [possibly including a hydrocarbon].

NY [redacted] Fluids

Spectra of the reservoir top brake fluid are characteristic of a glycol ether based material and other material [possibly including nitrogenous and/or carboxylic acid salt and hydrocarbon].

Spectra of the master cylinder brake fluid are characteristic of a glycol ether-based material and other [possibly including nitrogenous and/or carboxylic acid salt and possibly hydrocarbon].

**Elemental Analysis, mg/kg**
(ASTM D 5185-93)¹

	<u>Top</u>	<u>Master Cylinder</u>	<u>Unused Dow HD 50-4</u>
Aluminum	1	2	<1
Boron	22	12	138
Barium	<1	<1	<1
Calcium	1	2	<1
Cadmium	1	1	<1
Chromium	1	1	<1
Copper	496	500	<1
Iron	4	8	1
Magnesium	2	3	<1
Manganese	1	1	<1
Molybdenum	1	1	<1
Sodium	382	383	569
Nickel	<1	<1	<1
Phosphorus	11	11	8
Lead	22	25	1
Sulfur	163	164	<1
Silicon	4	4	<1
Tin	9	9	5
Titanium	<1	<1	<1
Zinc	501	582	<1

Water Content of Fluids, % by weight
(ASTM E 203)N[REDACTED] - Reservoir Top
1.4N[REDACTED] - Master Cylinder
1.3**Particulates**

Both the N[REDACTED] reservoir top and master cylinder fluids were filtered through an Eum nylon filter over a 40 Whatman filter. No particulates were gathered.

The precision and accuracy of results obtained by this method are within ±5% at 95% confidence level.

Contributor:**Concur:**Mary Hagan
Organic Section**By:**Gayle D. Gullen (GGULLEN)
Product Materials Engineer



Central Laboratory
 15000 Century Drive
 Dearborn, MI 48120-1287
 FAX (313) 323-1814

Report 9900807

April 9, 1999

To: M. Haga
 From: D. Schumacher 313 845 5039
 Subject: Brake Fluid
 Part Number: Not Provided
 Specification: Not Provided
 Supplier: Not Provided

Received: On February 22, 1999, two brake fluid aliquots were received.

Object: Determine the elemental concentration of the elements listed below in each aliquot.

Data and Analysis:

Elemental Analysis, mg/kg
 (ASTM D 5185-93)¹

	<i>Tip</i> 9900807-1	<i>M. Haga</i> 9900807-2
Aluminum	1	2
Boron	22	12
Barium	<1	<1
Calcium	1	2
Cadmium	1	1
Chromium	1	1
Copper	498	500
Iron	4	8
Magnesium	2	3
Manganese	1	1
Molybdenum	1	1
Sodium	302	393
Nickel	<1	<1
Phosphorus	11	11
Lead	22	25
Sulfur	153	154
Silicon	4	4
Tin	9	9
Titanium	<1	<1
Zinc	501	582

The precision and accuracy of results obtained by this method are within ±5% at 95% confidence level.

Concur: _____
 James R. Manor, Supervisor
 Analytical Chemistry Section

By: _____
 Daniel E. Schumacher
 Laboratory Engineer



Central Laboratory
 15000 Century Drive
 Dearborn, MI 48120-1267
 FAX (313) 322-1514

Report 9900513

March 2, 1999

To: M. Hagar/Greg Stevens
 From: D. Schumacher 313.845.5038
 Subject: Brake fluid
 Part number: N.A.
 Source: N.A.

Received: Two brake fluid samples were received on February 22, 1999.

Object: Determine the elemental concentration of the elements listed below in the samples.

Data and Analysis:

Concentration, weight percent¹
 (ARL 3580B ICP-AES)

	<u>New</u>	<u>Used</u>
Aluminum	<1	<1
Boron	138	150
Barium	<1	<1
Calcium	<1	18
Cadmium	<1	<1
Chromium	<1	3
Copper	<1	316
Iron	1	10
Magnesium	<1	1
Manganese	<1	1
Molybdenum	<1	5
Sodium	589	570
Nickel	<1	<1
Phosphorus	6	13
Lead	1	4
Sulfur	<1	19
Silicon	<1	31
Tin	6	9
Titanium	<1	<1
Zinc	<1	287

¹ The precision of this technique for this matrix is estimated to be a 5% at a 95% confidence level.

Concur: _____
 James P. Manor, Supervisor
 Analytical Chemistry Section

By: _____
 Daniel E. Schumacher
 Laboratory Engineer

From Page No. _____

~~Reservoir~~ ~~Aluminum nitrate hydrate~~

~~Reservoir~~ ~~Aluminum nitrate hydrate~~

~~Reservoir~~ ~~Aluminum nitrate hydrate~~

~~Reservoir~~ ~~Aluminum nitrate hydrate~~

~~Reservoir~~ ~~Aluminum nitrate hydrate~~

~~Reservoir~~ ~~Aluminum nitrate hydrate~~

~~Reservoir~~ ~~Aluminum nitrate hydrate~~

~~Reservoir~~ ~~Aluminum nitrate hydrate~~

~~NY~~

Reservoir - glycol ether based material + oxalate + possibly other hydrocarbon
 especially glycol ether based material = hydrocarbon

~~NY~~

Reservoir - glycol ether based material = volatile
 especially glycol ether based material

Reservoir NY

Reservoir - glycol ether based material +
 other (possibly including nitrogenous
 hydrocarbon salt + hydrocarbon)

Reservoir - glycol ether based material +
 other (possibly including nitrogenous
 hydrocarbon salt + hydrocarbon)

No apparent precipitates were present in the
 practice fluid (collected from the eye + 4/25/69)
 - Send for ICP - 4/28/69
 Mr. C. Rev

To Page No. _____

Witnessed & Understood by me.	Date	Invented by	Date
		Recorded by	

Request for Central Laboratory Service

Receipt - Copy

Lab Request Number: 009900602

Date of Request: 02/22/1999 08:17:31 AM

Print Date: 03/25/1999 02:43:49 PM

Request Description: SPEED CONTROL CUTOFF SWITCH

Requester Information:

Primary Contact: STEVENS, GREG - 10006

Phone: (313) 323-8580

PROFS ID: GSTEVEN1

Fax: (313) 390-7224

Secondary Contact: LA POINTE, NORM - 10076

Phone: (313) 584-2680

PROFS ID: NLAPON1

Fax: (313) 337-8256

Send Report to:

MD 5006/25005, AVT MATERIALS, BLDG. #5

Bill to:

Acctg. Location: 8100

Dept: T113

Work Task: X0304

Sample Information:

Total Number of Containers: 21

Sample Handling: Return after test

Source: Not specified

Supplier Code: Not specified

Part Material Name
SPEED CONTROL
CUTOFF SWITCH

Qty
21

Sample Identification
SEE ATTACHED RH-
EET

Part Number
F3VY-8F324-A

Material Spec
NA

CPSC Code
80.00.00

Supplier
TEXAS
INST
RUMENTS

Investigation Information:

Nature of Investigation/Requester Info. Desc: Not typed report

Additional Sample Information/Testing Requirements:

EXAMINE, DOCUMENT, AND ANALYZE SWITCHES PER PROTOCOL ESTABLISHED BY M. LAPONTE TO ASSIST IN DETERMINING CAUSE OF POSSIBLE SWITCH FIRE OR LEAKAGE. SWITCHES ARE FROM FIELD SURVEYS. MORE SWITCHES MAY FOLLOW.

Executive Directions:

Date customer would like report: 04/01/1999

Date customer must have report: 04/01/1999

Report Format(s):

Fee-in Information:

Initial Routing: Mansburg

Accepted for Central Laboratory by: LaFouche, Steve

Phone: 81-54876

View your test status at: [HTTP://tdc4web.pdf.twd.com/kals](http://tdc4web.pdf.twd.com/kals)

Program Name: KALISLab Eng Module
Program Version: Version: 2.0.0

PLEASE DETERMINE THE FOLLOWING:

Cap & Hardware Samples
Presence of Brake Fluid
Presence of OXYLITES, ETC.

Brake Fluid Samples
Presence of OXYLITES, ETC.
Water Content if possible

Thanks

Steve LaFouche

Request for Central Laboratory Service

Receipt - Copy

Lab Request Number: 009900007
Date of Request: 02/22/1999 08:17:31 AM
Print Date: 03/25/1999 02:43:49 PM

General Description: SPEED CONTROL CUTOFF SWITCH

Requester Information:

Primary Contact: STEVENS, OREG - 10006 Phone: (313) 323-8688 PROFS ID: GSTEVENI Fax: (313) 390-7224
Secondary Contact: LA PONTE, NORM - 10076 Phone: (313) 594-2986 PROFS ID: NLAPONTE Fax: (313) 337-8256

Send Report to: MD 6000/20065, AVT MATERIALS, BLDG. #5
Bill to: Acctg. Location: 5100
Dept: T113
Work Task: XOGM

Sample Information:

Total Number of Containers: 21 Sample Handling: Return sites lost
Source: Not specified Supplier Code: Not specified

Part/Item Name	Qty	Sample Identification	Part Number	Material Strip	CHSC Code	Supplier
SPEED CONTROL CUTOFF SWITCH	21	SEE ATTACHED SH EET	F2VY-9F924-A	NA	00.00.00	TEXAS INST FLUORIN IS

Investigation Information:

Nature of Investigation: Requester Info. Box: Mail typed report

Additional Sample Information/Testing Requirements:

EXAMINE, DOCUMENT, AND ANALYZE SWITCHES PER PROTOCOL ESTABLISHED BY N. LAPONTE TO ASSIST IN DETERMINING CAUSE OF POSSIBLE SWITCH FINE OR LEAKAGE. SWITCHES ARE FROM FIELD SURVEYS. MORE SWITCHES MAY FOLLOW.

Reporting Directions:

Date customer would like report: 04/01/1999
Date customer must have report: 04/01/1999

Report Format(s):

Log-in Information:

Initial Reading: Motorology
Accepted for Central Laboratory by: LaFleurde, Steve (Phone: 81-54876)

View your test status at: <http://statewulpsd7.tord.com/kids/>

Program Name: KALISLab Envy Module
Program Version: Version: 2.0.6

PLEASE DETERMINE THE FOLLOWING:
 Cur & Hgurat Samples NY 734410 PY605826
 PRESENCE OF BRAKE FLUID
 PRESENCE OF OXYLITES, ETC.
 BRAKE FLUID SAMPLING
 PRESENCE OF OXYLITES, ETC.
 WATER CONTENT IF POSSIBLE
 After for ID of yellow particles
 If no red - if sufficient
 send for ICP
 Steve LaFleurde

Project No. _____

Book No. _____

TITLE _____

No. _____

990657 *Greg Stevens* / *J. LaVad.* 3/15

- 4m. Logos - find *Bradybird* *Wasson* *Log*
3/1/59 NY [redacted] "9.2 TC"

- 5m. Logos - find *Wasson* *Wasson* *Log*
3/1/59 NY [redacted]

Wasson *Wasson* *Log* removed from PY [redacted]
Face Log
report

Wasson *Wasson* *Log* NY [redacted] *Wasson* *Wasson* *Log*
NY [redacted] *Wasson* *Wasson* *Log*

To Page No. _____

Understood by me.

J. LaVad.

Date

4/3 00

Invented by

Date

3713 3072

PRODUCED BY FORD

ER82-825-A 8861

Project No. 22-22-285

14

Book No. TITLE gunn interior window

From Page No. _____

Reservoir No.	Material	Analysis
NY 1-1	3/14	3/14
NY 1-2	3/14	3/14
NY 1-3	3/14	3/14
NY 1-4	3/14	3/14
NY 1-5	3/14	3/14

File:

NY [redacted]
 report - glycol ether based material + oxalate +
 possibly other hydrocarbons
 esp. essentially glycol ether based material

NY [redacted]
 report - glycol ether based material + oxalate
 esp. essentially glycol ether based material

B. by Fluid N [redacted]
 Reservoir 1-1 - glycol ether based material +
 other possibly including nitrogenous +
 carboxylic acid salt + hydrocarbon
 Fracture cylinder - report: glycol ether based
 material + other possibly including
 nitrogenous + carboxylic acid salt


no apparent insolubles were present in the
 bulk material (to test then you right + 40 S/1000
 - send for ICP - 4/8/55
 M. C. Her

Inspected & Understood by me. | Date | Invented by | Date | To Page No. _____

3713 3073
 PRODUCED BY FORD

9900607

Wed Apr 07 12:06:08 1989



Collection Date: Wed Apr 07 12:55:08 1989

9900607b
MCH

SPEED CONTROL CUT OFF SWITCH
NY 734410 HEXPORT
AS RECEIVED
BETWEEN PLATES

Handwritten notes:
Should call head
number for analysis
quantity of plates
by [unclear]

Number of sample scans: 12
Number of background scans: 1
Resolution: 4 000
Sample gas: 20
Motor velocity: 0.0125
Aperture: 75 00


ENR2-025-A 8883

PRODUCED BY FORD

3719 3074

9900607

Wed Apr 07 13:30:41 1960



Collection time: Wed Apr 07 13:27:46 1960

9900607a

rich

speed control cut off switch
cup NY734410
is received
between plates

Handwritten notes:
2.1 x 10⁶ ...
1.2 x 10⁶ ...

Number of sample scans: 1
Number of background scans: 1
Resolution: 4000
Sample gas: 20
Carrier velocity: 462.74
Aperture: 75.00


3713.9075

PRODUCED BY FORD

FORM-675-R 5084

9900607

Wed Apr 07 13:27:17 1969



Collection time: Wed Apr 07 13:25:25 1969

9900607c

rich

speed control cut off switch
report by 805828
as received
between plates

5.1 ml. 1 lb. and 100 ml. 100 ml.

Number of sample scans: 127
Number of background scans: 12
Resolution: 4000
Sample gain: 2.0
Motor velocity: 0.625
Aperture: 75 μ


ENG-025-A 8905

PRODUCED BY FORD

3713 3078

9900607

Wed Apr 07 13:44:24 1999



Collection time: Wed Apr 07 13:44:24 1999

9900607a

100

speed control cut off switch
cup by 605826
as received
between plates

Handwritten notes:
100 to 1000
1000 to 10000

Number of sample scans: 32
Number of background scans: 32
Resolution: 4.0001
Sample gain: 2.0
Mirror velocity: 0.625
Aperture: 15.00


5082-625-9 8908

PRODUCED BY FOND

3713 3077

9900607

Thu Apr 08 09 27 05 1999



Collection info: Thu Apr 08 09:25:40 1999
 9900607a
 1ack

Brake Fluid, ny 669063
 reservoir, 3/1/99
 as received
 between plates


*3400 cm-1 band is due to H-bonding
 with primary amine by
 adjacent molecules*

Number of sample scans: 12
 Number of background scans: 12
 Resolution: 4.000
 Sample gain: 2.0
 Mirror velocity: 0.6125
 Aperture: 75.00

3713 3078
 PRODUCED BY FORD
 E082-828-A 9987

9900607

Thu Apr 06 09:25:27 1989



Collection Date: Thu Apr 06 09:24:17 1989

9900607

10

Drake fluid, ny 668063
master cylinder, front port
as received
between plates

*gly. & other fluid coming to
with 1 possible in tank
along with the rest of the
... 118 g/mL ...*

Number of sample scans: 32
Number of background scans: 32
Resolution: 4.000
Sample gain: 1.0
Motor velocity: 0.6329
Aperture: 75.00

2002-02-01

PRODUCED

3713



Central Laboratory
15000 Century Drive
Dearborn, MI 48120-1287
FAX (313) 322-1814

Report 9900607

March 10, 1999

To: Greg Stevens / Steve LaFouche

From: A. Wedepohl (313) 84-54240

Subject: Speed Control Cutoff Switch

Received: Six samples on white filter paper were submitted for SEM/EDS on March 9, 1999.

Object: Provide elemental composition for each of the six samples by EDS.

Data and Analysis:

Surface Analysis


(Visual Examination, Scanning Electron Microscopy (SEM),
Energy Dispersive X-ray Spectroscopy (EDS))

	Appearance	EDS Spectra
Sample 1	White Particles/Powder	Zn
Sample 2	Orange Particles. Fuzzy	Fe, trace Zn
Sample 3	Brown, crystalline Fragments	Fe, Zn
Sample 4	Black smudge	Mostly organic with isolated regions of Cu, Zn or Cu, Zn, S, K
Sample 5	Black smudge with chunks	same as 4
Sample 6	Gray particles	a. Cu, Cl, Zn b. Cu, Zn, Cl, Ag c. Cu, Zn, Cl d. Cu, Zn, Cl, Fe


By:

Andrew Wedepohl (AWEDEPOH)
Laboratory Engineer


Operator : Andrew Wedepohl
Client : ██████████
Job : 9900807
Sample 1 Zn (3/9/99 15:35)




Operator : Andrew Wedepohl
Client : ██████████
Job : 9900807
Sample 2 Fe (3/9/99 15:48)



Operator : Andrew Wedepohl
Client : ██████████
Job : 9900807
Sample 3 Fe-Zn (3/9/99 15:55)



Operator : Andrew Wedepohl
Client : ██████████
Job : 9900807
Spectrum 2 Fe (3/9/99 15:58)




3713 3081


PRODUCED BY FORD

ER82-625-A 9878


Operator : Andrew Wedepohl
Client : ██████████
Job : 9900807
Sample 4 Cu-K-Zn (3/9/99 16:08)




Operator : Andrew Wedepohl
Client : ██████████
Job : 9900807
Sample 4 K-S-Cu-Zn (3/9/99 16:11)



Operator : Andrew Wedepohl
Client : ██████████
Job : 9900807
Sample 5 Cu-Zn-S-K (3/9/99 16:21)



Operator : Andrew Wedepohl
Client : ██████████
Job : 9900807
Sample 6 Cu-Zn-Cl (3/9/99 16:32)




3713 3082


PRODUCED BY FORD

ENG2-825-A 8871


Operator : Andrew Wiedepohl
Client : ██████████
Job : 9900507
Sample 6 Cu-Zn-CI (3/9/99 16:51)



Operator : Andrew Wiedepohl
Client : ██████████
Job : 9900507
Sample 6 (3/9/99 16:52)



Operator : Andrew Wiedepohl
Client : ██████████
Job : 9900507
Sample 6 (3/9/99 16:54)



3713 3083

PRODUCED BY FORD

ER82-825-A 8972

TITLE _____

From Page No. _____

TO: [REDACTED]
SUBJECT: SPEED CONTROL CUTOFF SWITCH
PART NUMBER: E2VY-9F924-A
SPECIFICATIONS: NOT PROVIDED

SUPPLIER: TEXAS INSTRUMENTS

RECEIVED: TWENTY-ONE SAMPLES WERE RECEIVED ON FEB 22, 1999

OBJECT: TEST SWITCH PER MATRIX PROCEDURE AND
EVALUATION PROCESS INSTRUCTIONS THAT WERE PROVIDED

TEST DATA: SEE MATRIX CHARTS ATTACHED TO THE
FIELD REPORT

To Page No. _____

Witnessed & Understood by me

[Signature]

Date

4/15/99

Entered by

[Signature]

Recorded by

Date

4-15-99

3713 3084

PRODUCED BY FORD

ERB2-625-A 9973

Request for Central Laboratory Service

Revised - Copy

Lab Request Number: 26990697
Date of Request: 02/22/99 09:17:31 AM
Print Date: 02/22/99 09:31:41 AM

Request Description: SPEED CONTROL CUTOFF SWITCH

Requester Information:

Primary Contact: [Redacted] 10006 [Redacted]
Secondary Contact: LA POINTE, NORM - 10079 Phone: (313) 594-2988 PROPSID: NLAPoint Fax: (313) 337-8258

Send Report to: MD 5008/2G085, AVT MATERIALS, BLDG. #6
Bill to: Acctg. Location: 5100
Dept: T113
Work Task: XQG04

Sample Information:

Total Number of Containers: 21 Sample Handling: Return after test
Source: Not specified Supplier Code: Not specified

Part/Material Name	Qty	Sample Identification	Part Number	Material Spec	CPSC Code	Supplier
SPEED CONTROL CUTOFF SWITCH	21	SEE ATTACHED SR BET	F2YY-87924-A	NA	00.00.00	EXAS NST RLMEN TS

Investigation Information:

Nature of Investigation: Requestor Info. Box: Mail typed report

Additional Sample Information/Testing Requirements:

EXAMINE, DOCUMENT, AND ANALYZE SWITCHES PER PROTOCOL ESTABLISHED BY N. LAPOINTE TO ASSIST IN DETERMINING CAUSE OF POSSIBLE SWITCH FIRE OR LEAKAGE. SWITCHES ARE FROM FIELD SURVEYS. MORE SWITCHES MAY FOLLOW.

Reporting Directions:

Date customer would like report: 04/01/1999
Date customer must have report: 04/01/1999

Report Format(s):

Lead-In Information:

From: Rousing: Metallurgy
Accepted for Central Laboratory by: LaRouche, Steve Phone: 84-54878

View your test status at: [HTTP://rd4web.pdf.ford.com/test/](http://rd4web.pdf.ford.com/test/)

Program Name: KALISLab Engr Module
Program Version: Version: 2.0.6

*Rouman
Pressure & Resistance*

3713 3085

PRODUCED BY FORD

ERR2-025-A 0974

Brake Switch * Checklist *Res 11-1-65*

		Memphis	A	B	C	D	E	F	
		PP	PP	NY	NY	W	NX	NY	NX
Field Info	1 Copy field into Brake Switch Log etc	C	C	C	C	C	C	C	C
	2 Photograph Switch	C	C	C	C	C	C	C	C
	3 Record any unusual adjustment observations	C	C	C	C	C	C	C	C
	4 Check to Converter engagement	C	C	C	C	C	C	C	C
Switch & Converter Assembly	5 Wire 15.00V to 15.00V (15.00V) Resistance								
	6 Wire 15.00V to 15.00V Resistance								
	7 Wire 20.00V to 20.00V Resistance								
Converter & Study	8 Separate Straps from Switch								
	9 Study Converter Box								
	10 Wire 15.00V to 15.00V (15.00V) Resistance								
	12 Check for full engagement of converter								
	13 Check wire insulation								
Switch & Converter Assembly	14 Check wire grey pads								
	15 Cut wire insulation to check for corrosion								
	16 Separate Switch to Converter Stud								
	17 Spring Spacing to Stationary Terminal Resistance								
	18 Spring Contact to Spring Resistance								
Switch & Converter Assembly	19 Stationary Terminal to Spring Resistance								
	20 Wire to Spring Resistance								
									3.28 15
Switch & Converter Assembly	24 Switch Opening Pressure								
	25 Switch Closing Pressure								
	26 Post Test for Leakage								
	27 Repeat Steps 17 through 20 at 100 psi								
Switch & Converter Assembly	28 Remove electrical striping								
	29 All electrical conductors, Photograph								
	30 Remove cap								
	31 Examine removed conductors, Photograph								
Field Info	32 BE IN CHG of 1000 hrs, contacts, conductors								
	33 CAP-CHK of 1000 hrs, 1000 hrs, conductors, etc								
	34 Photographs; samples of contacts								
	35 Call for address of conductors or spring								

123
59
NO BREAK
8888

GM-625-A 8875

PRODUCED BY FORD

		↓	↓	↓	↓	↓	↓	↓	↓
		PY	P	P	PY	N	PK	PK	TO
Add Info	1 Key Field Selection Switch Log in	C	C	C	C	C	C	C	C
	2 Photograph Switch								
	3 Record any unusual observed visual observations	C	C	C	C	C	C	C	C
	4 Check for Connector engagement 5 Key if appropriate								
Status - Connector Activated	6 Verify all lights are illuminated								
	7 Verify all lights are illuminated								
	8 Verify all lights are illuminated								
Connector Cable	9 Verify Connector Seal								
	10 Verify all wires are properly connected								
	11 Check for full engagement of connector								
	12 Check wire lengths								
Switch External Unenclosed	13 Check wire girth								
	14 Check wire insulation for cracks								
	15 Check for proper operation of switch								
	16 Turn switch to Off position								
	17 Verify Terminal in External Terminal Block	0.2	0.3			0.2	0.2	0.2	0.2
	18 Verify Terminal in Internal Terminal Block	0.2	0.3			0.2	0.2	0.2	0.2
Switch External Enclosed	19 Verify Terminal in External Terminal Block	0.2	0.3			0.2	0.2	0.2	0.2
	20 Verify Terminal in Internal Terminal Block	0.2	0.3			0.2	0.2	0.2	0.2
	21 Switch Operating Pressure	137	160			147	132	140	137
	22 Switch Charging Pressure	59	80			70	66	112	66
Switch	23 Fuel Valve for Leakage	NO LEAK	NO LEAK			NO LEAK	NO LEAK	NO LEAK	NO LEAK
	24 Verify Steps 17 through 20 of 8894g	8888	8888			8888	8888	8888	8888
	25 Verify Step 17 through 20 of 8894g	8888	8888			8888	8888	8888	8888
Switch	26 Verify Step 17 through 20 of 8894g	8888	8888			8888	8888	8888	8888
	27 Verify Step 17 through 20 of 8894g	8888	8888			8888	8888	8888	8888
	28 Verify Step 17 through 20 of 8894g	8888	8888			8888	8888	8888	8888
	29 Verify Step 17 through 20 of 8894g	8888	8888			8888	8888	8888	8888
Termination	30 Verify Step 17 through 20 of 8894g	8888	8888			8888	8888	8888	8888
	31 Verify Step 17 through 20 of 8894g	8888	8888			8888	8888	8888	8888
	32 Verify Step 17 through 20 of 8894g	8888	8888			8888	8888	8888	8888
Termination	33 Verify Step 17 through 20 of 8894g	8888	8888			8888	8888	8888	8888
	34 Verify Step 17 through 20 of 8894g	8888	8888			8888	8888	8888	8888
	35 Verify Step 17 through 20 of 8894g	8888	8888			8888	8888	8888	8888

Brake Switch T g Checklist

		11	12	13	14	15	16	17	18
		PY	PY	NY	PX	PY	BY	PY	PY
Final Ins	1 Key Field into Test Station Log etc	C							
	2 Photograph Switch	C							
	3 Record any unusual observed wheel observations	C							
	4 Check for Connector engagement								
	5 Key if appropriate								
Switch + Connector Assembly	6 Wire 18 GPH to Wheel Hub Resistance								
	7 Wire 18 GPH to Magnet Resistance								
	8 Wire 20 GPH to Magnet Resistance								
Connector Only	9 Remove Wires from Pinout								
	10 Wire 18 GPH to Wheel Hub Resistance								
	11 Wire 18 GPH to Wheel Hub Resistance								
	12 Check for full engagement of connector								
	13 Check wire insulation								
Switch + Internal Inspected	14 Check wire gage ends								
	15 Cut wire leads to check for corrosion								
	16 Assembly Switch to Collector Head								
	17 Spring Mounted to Battery Terminal Resistance	0.2							
	18 Spring Mounted to Magnet Resistance	0.2							
Switch + Internal Inspected	19 Battery Terminal to Magnet Resistance	0.2							
	20 Wire to Magnet Resistance	0.2							
	24 Switch Operating Pressure	1.34							
	25 Switch Closing Pressure	71							
Switch + Internal Inspected	26 Final Test for Leakage	NO LEAK							
	27 Repeat Steps W through 24 at 100 psi								
Switch	28 Remove obstructing ring								
	29 Examine contact surfaces, Photograph								
	30 Remove cap								
	31 Examine contact surfaces, Photograph								
Inspection	32 Micro-Exam of SW face, contacts, inserts								
	33 Micro-Exam of SW cap, magnet, contact pins, etc.								
	34 Photographic Analysis of contacts								
	35 Seal the system at completion of testing								

Brake Switch 1 ~~of Chassis~~

		19	20	21	22	23			
		PV	PV	PV	??	PV	PRT	PRT	RM
1. Inlet Side	1. Key 2 into hole near Switch 1 up side								
	2. Photograph Switch								
	3. Record any unusual signal signal photographs								
	4. Check for Corrosion/engraving								
	5. Key #18 appropriate								
2. Switch + 3. Visual for Advisability	6. Key 18 Range into 20 (MAGNET) Resistance								
	7. Key 18 20 to 21 (WIPER) Resistance								
	8. Key 18 21 to 22 (WIPER) Resistance								
	9. Key 18 22 to 23 (WIPER) Resistance								
4. Cap or Cle Study	10. Key 18 23 to 24 (WIPER) Resistance								
	11. Key 18 24 to 25 (WIPER) Resistance								
	12. Check for full engagement at all points								
	13. Check wire insulation								
	14. Check wire gage size								
5. Switch Exhaust Inspection	15. Key 18 25 to 26 (WIPER) Resistance								
	16. Key 18 26 to 27 (WIPER) Resistance								
	17. Key 18 27 to 28 (WIPER) Resistance								
	18. Key 18 28 to 29 (WIPER) Resistance								
	19. Key 18 29 to 30 (WIPER) Resistance								
	20. Key 18 30 to 31 (WIPER) Resistance								
6. Switch External Pressure/Leak	24. Switch Opening Pressure						158	127	126
	25. Switch Closing Pressure						68	62	64
	26. Fuel Test for Leakage						NO LEAK	NO LEAK	NO LEAK
	27. Repeat Steps 17 through 20 at 100 psi								
7. Switch	28. Key 18 31 to 32 (WIPER) Resistance								
	29. Key 18 32 to 33 (WIPER) Resistance								
	30. Key 18 33 to 34 (WIPER) Resistance								
	31. Key 18 34 to 35 (WIPER) Resistance								
8. Inlet Side	32. Key 18 35 to 36 (WIPER) Resistance								
	33. Key 18 36 to 37 (WIPER) Resistance								
	34. Key 18 37 to 38 (WIPER) Resistance								

LOGS
DID NOT
DIA

EM-2-22-1 2878

PRODUCED BY FORD

3713 3089

(3) Brake Switch To Checklist ↓ ↓ ↓ ↓ ↓ (2)

		PX	PY	NY	PY	NY	PY	PX	NY
Initial Tests	1 Plug Field into Brake Lamp Kit	U	U	U	U	U	U	U	U
	2 Plug Lamp Switch	U	U	U	U	U	U	U	U
	3 Connect any ground control cable assemblies	U	U	U	U	U	U	U	U
	4 Check for Connector engagement If any EIS applicable	U	U	U	U	U	U	U	U
Switch + Connector Assembly	5 Move to Check Valve (Operating Resistance)		0.2		0.8		6.0 M	0.1	U
	6 Move to COV to Magnet Resistance		0.8		0.8		6.0 M	0.1	U
	7 Move to COV to Magnet Resistance		0.8		0.8		6.0 M	0.1	U
	8 Operate Master Line Switch								
Intermittent Test	9 Verify Connector Area								
	10 Move to COV to Wire (WOMAN) Resistance		0		0			0	
	11								
	12 Check for full engagement of connector								
	13 Check wire condition	C	C		C			C	C
Switch Electrical Requirements	14 Check wire girth seals								
	15 Get wire headless to check for condition								
	16 Reversible Switch in Collection Stand								
	17 Spring Tension to Primary Neutral Resistance	0.1	0.2		0.3		1.5	0.1	0.1
	18 Spring Tension to Magnet Resistance	0.8	0.8		0.8		6.25 M	0.8	0.8
Switch Electrical Parameters	19 Spring Tension to Magnet Resistance	0.8	0.8		0.8		6.36 M	0.8	0.8
	20 Force to Magnet Resistance	0.8	160 K		0.46 M		0.9	0.8	0.8
	24 Contact Opening Pressure	133	151		136		164	136	135
	25 Switch Closing Pressure	63	82		66		66	108	74
Switch Electrical Parameters	26 Pull Test for Leakage	NO LEAK	NR LEAK		NO LEAK		NO LEAK	NO LEAK	NR LEAK
	27 Contact Shape 17 through 20 at 100 gms								
	28	0.8	0.8		0.8		0.1	0.8	0.8
Switch	29	0.8	0.8		0.8		0.1	0.8	0.8
	30	0.8	0.8		0.8		0.1	0.8	0.8
	31	0.8	0.8		0.8		0.1	0.8	0.8
	32	0.8	0.8		0.8		0.1	0.8	0.8
Inspection	33								
	34								
	35								

CONTACTS DID NOT OPEN

Request for Central Laboratory Service

Receipt - Copy

Lab Request Number: D090000000

Date of Request: 02/22/1998 08:17:31 AM

Print Date: 02/22/1998 09:31:41 AM

Request Description: SPEED CONTROL CLITOFF SWITCH

Requester Information:

Primary Contact: [REDACTED]
Secondary Contact: LA POINTE, NORM - 10075 Phone: (313) 594-2686 PROFS ID: NLAPOINT Fax: (313) 337-8256

Send Report to: MD 5006/2G056, AVT MATERIALS, BLDG. #8
Bill to: Acctg. Location: 5100
Dept: T113
Work Task: XQ034

Sample Information:

Total Number of Containers: 21 Sample Handling: Return after test
Source: Not specified Supplier Code: Not specified

Part/Material Name	Qty	Sample Identification	Part Number	Material Spec	CPSC Code	Supplier
SPEED CONTROL CUTOFF SWITCH	21	SEE ATTACHED SR EET	P2VY-3P24-A	NA	00.00.00	TEXAS INST RUMEN TS

Investigation Information:

Nature of Investigation: Requester Info. Box: Mail typed report

Additional Sample Information/Testing Requirements:

EXAMINE, DOCUMENT, AND ANALYZE SWITCHES PER PROTOCOL ESTABLISHED BY N. LAPOINTE TO ASSIST IN DETERMINING CAUSE OF POSSIBLE SWITCH FIRE OR LEAKAGE. SWITCHES ARE FROM FIELD SURVEYS. MORE SWITCHES MAY FOLLOW.

Reporting Directions:

Date customer would like report: 04/01/1998
Date customer must have report: 04/01/1998

Report Format(s):

Log-in Information:

Initial Routing: Metallurgy
Accepted for Central Laboratory by: LaRouche, Steve Phone: 84-54878

View your test request at: [HTTP://td4web1.pc7.ford.com/taier](http://td4web1.pc7.ford.com/taier)

Program Name: KALISLab Engr Module
Program Version: Version: 2.0.6

ALEX
FLUORO SCOP.

3713 3092

PRODUCED BY FORD

E082-025-R 9981

TITLE Spacer Control Valve Switch

Project No. 99020-3

Book No. 2572

From Page No. Object: Fluoroscopically analyze the supplied switch and connector assemblies.

Received: Three spaced (series) control cutoff switches were received on February 22, 1999 and were identified as:

PX [redacted], PX [redacted] and NY [redacted]

Part# F2VY29F924-A

Specification: not stated

Supplier: Texas Instruments

Test Date: Fluoroscopic Examination

Sample PX [redacted] switch shows a mis-assembled integral an-hermetic double seal. This mis-assembly would allow leakage past the double seal.

The remaining two samples (switches) show the internal an-hermetic double seal with less than optimum compression.

All three switches are similar in appearance. One of the side connection looks (looking down) like mis-shaped. Instead of being square shouldered the shoulder exhibits an approx. 30° angle. This allows one side of the connection to distort. This prevents the sealing gasket from being properly compressed and would allow leakage past the seal.

In addition the switches knife edges that compress the compression sealing gasket is mis-shaped and would potentially allow leakage.

The fluoroscopic image shows the connector sealing gasket containing large gaps. These gaps appear interconnected. This suggests that the gasket is an open cell foam. To properly seal this connector the gasket should be a closed cell foam. Investigation of this gasket is highly recommended.

Attached are 6 pages of photographs.

Witnessed & Understood by me,

Date

Invented by

Date

23 Feb 99

Recorded by

3713 3093

PRODUCED BY FORD

ENG-825-A 8982

V_{in}

P_y [redacted]

- 5) 2 Ω
- 6) 6.01 M Ω
- 7) 6.08 M Ω
- 10) open circ.
- 11) waiting

- 17) 1.5 Ω
- 18) 6.25 M Ω
- 19) 6.36 M Ω
- 20) 0.4 Ω
- 21) waiting

V_{in}

P_x [redacted]

- 5) 0.4 Ω
- 6) ∞ Ω
- 7) ∞ Ω
- 10) ∞ Ω
- 11) ∞ Ω
- waiting
- 17) ∞ Ω 0.4 Ω
- 18) ∞ Ω
- 19) ∞ Ω
- 20) 6.5 Ω

(stationary closest to Fext)

P_x [redacted]

- 5) 0.4 Ω
- 6) ∞ Ω
- 7) ∞ Ω
- 10) }
- 11) }

P_y [redacted]

- 5) ∞ Ω
- 6) ∞ Ω
- 7) ∞ Ω
- 10) ∞ Ω
- 11) }
- 17) 0.3 Ω
- 18) ∞ Ω
- 19) ∞ Ω
- 20) 0.463 M Ω

Vin

Y

- 5) 0.2 Ω
- 6) $\infty \Omega$
- 7) $\infty \Omega$
- 10) $\infty \Omega$
- ~~16)~~
- 17) 0.2 Ω
- 18) $\infty \Omega$
- 19) $\infty \Omega$
- 20) 160 K Ω

Vin R_X

- 5) 0.2 Ω
- 6) $\infty \Omega$
- 7) $\infty \Omega$
- 10) $\infty \Omega$
- 17) 0.2 Ω
- 18) $\infty \Omega$
- 19) $\infty \Omega$
- 20) 17.65 K Ω

J Vin PY

- 5) 0.3 Ω
- 6) 20.22 m Ω
- 7) 21.45 m Ω
- 10) $\infty \Omega$
- 17) 0.2 Ω
- 18) 34 m Ω
- 19) 39 m Ω
- 20) 63.4 K Ω

PY

- 5) 0.3 Ω
- 6) $\infty \Omega$
- 7) $\infty \Omega$
- 10) $\infty \Omega$
- 17) 0.3 Ω
- 18) $\infty \Omega$
- 19) $\infty \Omega$
- 20) 55 Ω

V_{in} P_Y [REDACTED]

17) 2.2 Ω
18) ∞ Ω
19) ∞ Ω
20) 1.437 m Ω

V_{in} P_Y [REDACTED]

17) 0.3 Ω
18) ∞ Ω
19) ∞ Ω
20) 1.6 m Ω

V_{in} P_X [REDACTED]

17) 0.2 Ω
18) ∞
19) ∞
20) 7.5 m Ω