


EA02-025

FORD 10/27/03

APPENDIX N

BOOK 37


PART 3 OF 3



3713 3105

PRODUCED BY FORD


E962-625-A 3867



3713 3106

PRODUCED BY FORD



EA62-925-A 8888



3713 3107

PRODUCED BY FORD


EA62-625-A 9808



3713 3108

PRODUCED BY FORD



ER02-025-A 9900



3713 3109

PRODUCED BY FORD


EP82-825-A 9991



3713 3110

PRODUCED BY F

2002-025-A 20



3713 3111

PRODUCED BY FORD

5902-025-A 0003

Request for Central Laboratory Service

Receipt - Copy

Lab Request Number: 0502011900
Date of Request: 05/02/1998 08:17:31 AM
Print Date: 05/02/1998 08:48:35 PM

Item Description: SPEED CONTROL CUTOFF SWITCH

Customer Information:

Primary Contact: [REDACTED] 18694
Secondary Contact: LA POINTE, NORM - 18675

Phone: (312) 594-2300 PROPS DE LA POINTE Fax: (312) 594-2300

Send Report to:
EMI to:
Dept:
Work Test:

MD 500003005, FMT MATERIALS, BLDG. #5
Analyst Location: 5100
T113
XQ304

Sample Information:

Total Number of Containers: 21
Source: Not specified

Sample Handling: Return after test
Supplier Code: Not specified

Part Material Name	Cty	Sample Identification	Part Number	Material Spec	CPAC Code	Supplier
SPEED CONTROL CUTOFF SWITCH	21	SEE ATTACHED BY ECT	PZVY-9F204-A	NA	00.00.00	TEXAS INST ALMEN TS

Investigation Information:

Name of Investigator: Follow Analysis
Long Term Project:
Requester Info. Doc: Modified report

Additional Sample Information/Testing Requirements:

EXAMINE, DOCUMENT, AND ANALYZE SWITCHES PER PROTOCOL ESTABLISHED BY N. LAPOINTE
TO ARRIVE AT DETERMINING CAUSE OF POSSIBLE SWITCH FIRE OR LEAKAGE. SWITCHES
ARE FROM FIELD SURVEYS. MORE SWITCHES MAY FOLLOW.

Specifying Deadlines:

Date customer would like report: 04/01/1999
Date customer must have report: 04/01/1999

Report Format(s):

Lead-In Information:
Initial Routing: Metallurgy
Accepted for Central Laboratory by: LaRouche, Steve

Phone: 84-54876

View your test status at: [HTTP://wwwlab.pvt.com/test/](http://wwwlab.pvt.com/test/)

Program Name: KALIBLab Engg Module
Program Version: 3.0.0

3713 2517

Request for Central Laboratory Services

Receipt - Copy

Lab Request Number: 0000000226
Date of Request: 06/29/1999 10:16:23 AM
Print Date: 06/29/1999 09:48:02 PM

Request Description: SPEED CONTROL CUTOFF SWITCH

Customer Information:

Primary Contact: 10005

Secondary Contact: LA PONTE, NORM - 10075

Phone: (313) 384-3980 PROFS ID: NLAPONT Fax: (313) 387-6256

Send Report to: MD EQUIPMENT, RVT MATERIALS, BLDG. #6
Bill to:
Autolocator: 6160
Dept: T113
Work Task: X0004

Sample Information:

Total Number of Containers: 8
Source: Not specified

Sample Handling: Dispose after 20 days
Supplier Code: Not specified

Container Name:
SPEED CONTROL
CUTOFF SWITCH

QTY: 8
Sample Identification:
A,B,C,D,E,H,G,
AND F

Part Number:
F2V9-Y000-A

Material Name:
NA

CPRC Date: 06/30/00
Supplier:
TEXAS
INST
RUMEN
TS

Investigation Information:

Name of Investigation:

Failure Analysis
Long Term Project

Requester Info. (Name:

Mail typed report

Additional Sample Information/Testing Requirements:

DISASSEMBLE SWITCHES IN PRESENCE OF PERSONNEL FROM TEXAS INSTRUMENTS. PERFORM
ANALYSES TO DETERMINE CAUSE OF POSSIBLE SWITCH FIRE OR LEAKAGE.

Reporting Directions:

Date customer would like report: 07/11/1999

Date customer must have report: 06/31/1999

Report Format(s):

Label Information:

Initial Reading: Metallurgy

Accepted for Central Laboratory by: LaRouche, Steve

Phone: 84-54878

Program Name: KALRELIS Eng Module
Program Version: 3.0.0

View your full status at: [HTTP://MetMetals.pdf.fax.com/0004](http://MetMetals.pdf.fax.com/0004)

0713-2616

Request for Central Laboratory Services

Receipt - Copy

Lab Request Number: 00001571
Date of Request: 06/12/2000 03:32:46 PM
Print Date: 05/26/2000 05:40:22 PM

Sample Description: SPEED CONTROL CUTOFF SWITCH

Investigator Information:

Primary Contact: [REDACTED] 10000
Secondary Contact: LA POINTE, NORM - 10075

Phone: (313) 594-2866 PROJ ID: LAPOINTE Fax: (313) 537-4204

Send Report to:
Bill to:
Spec Report to:
Acctg Location: 5100
Dept: T113
Work Task: 200004

Sample Information:

Total Number of Containers: 17
Source: Not specified

Sample Handling: Return after test
Supply Code: Not specified

Part/Material Name	Qty	Sample Identification	Part Number	Material Size	CPTC Code	Shipping
SPEED CONTROL CUTOFF SWITCH	17	SEE ATTACHED SH GET	P2VY-0F004-A	NA	00.00.00	TEXAS INST PACIFIC TB

Investigation Information:

Nature of Investigation/Requestor Info: Doc: Mail typed report

Additional Sample Information/Test/Spec Requirements:

Perform Tests as in Lab Number: 0000007

PERFORM TESTS AS IN REQUEST TO ASSIST IN DETERMINING CAUSE OF POSSIBLE
LEAKAGE/FRICTION. ADDITIONAL SWITCHES MAY FOLLOW.

Customer Discrepancy:

Date customer would file report: 07/01/1999
Date customer must have report: 07/01/1999

Report Format(s):

Label Information:

Initial Review: Metallurgy
Accepted for Central Laboratory by: LaPointe, Norm

Phone: 31-54876

View your test platform at: <HTTP://labweb.pdf.lord.com/labs/>

Program Name: KALISLab Engr Module
Program Version: 3.0.0

Note printed by FPORTER on 23 Feb 1999 at 16:26:19

From: I2060625--EXTERNAL Date and time 02/23/99 16:13:50
To: FPORTER --FORDMAIL 'Fred Porter' | For NEAPOLITAN--FORDMAIL 'Nolan LaPointe' |
From: Rahman, Aziz
Subject: FW: (U)Pressure Tests

You may have received this from Steve R. Interesting info on pressure profiles at various nodes. we will try to factor this into our vehicle test.

Regards
Aziz.

From: Steve Reimers SMTD:sreimers@ford.com
Sent: Friday, February 19, 1999 4:13 AM
To: Aziz Rahman, Texas
Subject: (U) Pressure Tests

fyi... I gave him a copy of your test plan and asked what pressure range and frequency we should instrument for.

Steve Reimers building 5 3C043
AVT Chassis E/E System Applications mail drop 5011
39-03286 SREIMERS sreimers@ford.com fax 39-03286
*** Forwarding note from JJOYCE1 --DRBN007 02/18/99 19:40 ***
To: SREIMERS--DRBN007
cc: FPORTER --DRBN007

FROM: John Joyce USAST(UTC -05:00)
Subject: (U) Pressure Tests

Steve,

I got your note and will be on vacation tomorrow through Wednesday. Here's the info.

The more I think about this, the more I think TC activation may be the mechanism.

I am not sure of the order of the things connected and that can influence the low frequency amplitude of the signals. But the short answer is to instrument for 0-250 Bar and sample at 1 kHz or more.

Since I'm not sure of where the pressure switch is hydraulically connected I'll give you pressures at nodes and states I do know. The worst case for the switch would be to be connected between the HCU and the prop valve, which is where I think it is.

This is the low frequency component of the signal. I'll talk about the high-frequency component further down.

HCU - HCU NODE
Maximum Pressure - 175 Bar

3719 1222

PRODUCED BY FORD

E902-025-A 2007

Achieved by getting maximum vacuum (high revving engine and suddenly close throttle) than standing on the pedal as hard as you can. I don't remember this number very well it might be as low as 130 or as high as 220. It also depends on your leg strength. This type of pressure is VERY RARE at this node. For this car, the driver will typically apply <20 bar and very rarely exceed 50 bar.

HCU - PROP VALVE MODE

Standing Still - Same as MC pressure - see above.

ABS Maximum - ~110 Bar

This is achieved by loading to GVW and performing an ABS stop. You may find that you are pedal effort limited, not limited by ABS control. It's pretty rare to get this high of pressure in this mode.

TCS Maximum - ~180 Bar

This is a good candidate. On this vehicle because the HCU had to pump through the prop valve to do the brakes-only traction control, the pressures coming out of the HCU got very high. The pressure relief valve on the pump VERY OFTEN dictated the peak pressure which could be developed - not the control - put another way, because the pressure at the rear brake had to restrain the entire powertrain (no engine intervention) and push through a prop valve, it was often possible to drive through the TC - the engine could overpower the brakes, even though very high pressures were being generated at the HCU. The noise during TC activation in these applications was very dependent upon the pressure relief valve opening point. So the pressure relief valve value got changed a few times over the years as performance was sacrificed for NVH. Also the tolerance on the pressure relief valves was fairly large - a total of 40 bar, at that time I believe. The pressure relief valve pressure might be anywhere from 30 to 180 bar depending on part-to-part variation and the design generation that was agreed upon.

You can achieve this easiest by getting the rear wheels off the ground and putting the car in drive. Get into the throttle hard, but not so hard that you drive out of first gear or faster than 15 mph. If you maintain this for a while, the thermal modal to protect the rear linings will disable the Traction Control. You will then need to wait for them to cool, before the function will be reenabled. You can dramatically accelerate the cooling time by cruising (without braking) at about 40 mph.

Typical drivers can regularly get high pressures in this mode.

PROP VALVE - REAR BRAKE MODE

ABS Maximum Pressure ~70 Bar

Load to GVW and perform an ABS stop at maximum pedal effort.

TCS Maximum Pressure ~100 Bar

This pressure level is strongly dependent upon the pressure relief valve level - see above.

Standing Still

Same as ABS Maximum Pressure

High Frequency Content

The high frequency content has two parts. If you are not in ABS or Traction Control there is practically no high frequency content - the pressure is modulated at <10 Hz. This is basically limited by Booster response times

3713 1223

PRODUCED BY FORD

ER02-025-A 0000

and hydraulic dampening in the ABS orifices.

High Frequency Content Due To Control

During ABS/TC events the pressure is changed in quick steps. Typically it will increase by 10 Bar in a few milliseconds, and this type of change occurs about every 100ms. The pressure will decrease by about 20 Bar every 100 ms. There can be quite a bit of variation in these numbers, but those are pretty typical. (Actually the numbers I assigned were for ABS, swap "increase" and "decrease" for TC activation.)

High Frequency Content Due to Shock Waves

This is a secondary effect from the control. Generally it is worst right at the outlet of the MCV. It is damped and dissipated the further you get from the MCV. The shock wave is generated from the cyclical pulsing of the pump as well as the sudden changes in pressure when a solenoid valve is snapped open or shut.

The amplitude of this can be really big - I haven't looked at it in this generation unit for a few years, but I think it's about 50 Bar peak-peak right at the MCV. It will fall off as you move further away from the MCV.

The frequency is pretty high and I think some components are above the 1 kHz level, but you can get a very good idea of the disturbances by sampling at 1kHz.

Regards,
John Joyce

3713 1224

PRODUCED BY FORD

DR02-025-A 5500

* Note printed by FPORTER on 23 Feb 1999 at 11:18:50 *

From: 12060625--EXTERNAL Date and time 03/22/99 10:19:17
To: SREIMERS--FORDMAIL 'Steve Reimers (F SLAROCHE--FORDMAIL 'Steve LaRouche (
WLAPOINT--FORDMAIL 'Norm LaPointe (F FPORTER --FORDMAIL 'Fred Porter (For

From: Rahman, Aziz
Subject: TI Durability

Norm,

I just confirmed. The durability tests were run at 135 C.

Regards
Aziz.

3713 1226

PRODUCED BY FORD

ENR2-825-A 10000

* Note printed by FPORTER on 23 Feb 1993 at 11:16:59 *

From: 12050425--EXTERNAL Date and time 02/23/93 10:16:59
To: SLAROUCHE--FORDMAIL 'Steve LaRouche' ; SREIMERS--FORDMAIL 'Steve Reimers' ; S
NLAPPOINT--FORDMAIL 'Nora LaPointe' ; F FPORTER --FORDMAIL 'Fred Porter' ; F
cc: OTFWUGYK--EXTERNAL Sharpe, Robert

From: Rahman, Aziz
Subject: TI Durability Samples

cc: "Sharpe, Robert" <rsharp@mail.mot.ti.com>

I have the following disassembled samples with me and I will forward them to Steve L. today pm.

200k Cycles	3 samples
400k Cycles	2 samples
600k Cycles	2 samples
728k Cycles	1 sample (observed leakage)
800k Cycles	2 samples

This will be part of the library to establish lab tests vs field data.

Regards
Aziz.

3713 1226

PRODUCED BY FORD

BB62-026-A 19881

113

2/24/79

Final Notes

What fluid residue?

DC leakage 5 mA

What caused carbonization?

What caused insulation breakdown?

What is the relative current ratio?

What is the product resistance vs.

What is the effect of temperature?

What is the dielectric strength?

What is the inhibitor in
Infrared Emissivity
Evacue Fluid (ZnS² Deltapl)

What is the absorption coefficient?

What is the absorption coefficient for ZnS?

92-94

3713 1795

PRODUCED BY FORD

ER02-025-A 18682

2/2

2/24/72

M-1. Hopkins & Alzabard
- samples off Memphis Switch

Are these standard fuses? No ATO
Does trailer fuse increase fuses?

Picture of switch as built?

3rd Feb - 1972. Carter & Day 5-
- not from Brake Fluid Co.
Memphis process uses sulfur.
on switch - Carter what
topping - insulation resistance.

3713 1789

PRODUCED BY FORD

BB02-025-A 18863

2/24/69
2/2

Lock into fire retardant cage
w/t?

plus tests

Test Jack
Chlorine as corrosive

S. late as corrosive

Continue 300 hour Test

1. 2. 3.
4. 5. 6.
7. 8. 9.

37131800

PRODUCED BY FORD

0002-025-A 10004

Action(s)

2/24/88

- f Go look at cars
- o) Prepare to do combustion test on
g) base w/harness attached sheet w/
- f Request Battery drain warranty
with BR SW replacement
- Get effective date for Quiet SW
F2AC
- f - - - monitor with optics 1/25
- ~~start~~ loose metal in switch cavity
- Check APG for 74/75 Town car
- Look into Fisher Switch usage at 70's
- - - - -
- - - - -
- v Team meeting w/Doc
- Call in Tom & Tim

37131801

PRODUCED BY FORD

EMB2-028-A 10005

C = COMPLETE
NA = NOT APPLICABLE
TIP = TO BE PERFORMED

Brake Switch Testing/Checking

INF = INFINITY (OPEN)
NP = NOT PERFORMED
NRCLS = NOT RECD AT GEN. LAB

C = COMPLETE
NA = NOT APPLICABLE
TBP = TO BE PERFORMED

Brake Switch Testing Checklist

INF = INFINITY (OPEN)
NP = NOT PERFORMED
NRCLS = NOT RECD AT GEN. LAB.

Test Item	1. No Pedal Free Brake Lag off	2. Emergency Brake	3. Normal Stop Acceleration	4. Normal Stop Deceleration	5. Normal Stop Acceleration	6. Normal Stop Deceleration	7. Normal Stop Acceleration	8. Normal Stop Deceleration	9. Normal Stop Acceleration	10. Normal Stop Deceleration	11. Normal Stop Acceleration	12. Normal Stop Deceleration	13. Normal Stop Acceleration	14. Normal Stop Deceleration	15. Cut value detection or attack for emergency
Switch - External	1.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
Switch - Internal	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
Switch - Unspecified	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
Switch - External	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
Switch - Internal	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
Switch - Unspecified	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
Switch - External	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
Switch - Internal	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
Switch - Unspecified	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
Technique	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0

From Page No. _____

TG:

SUBJECT: SPEED CONTROL CANCEL SWITCH

PART NUMBER: F2VY-9F924-A

SPECIFICATION: NOT PROVIDED

SUPPLIER: TEXAS INSTRUMENTS

RECEIVED: SEVENTEEN SPECIMENS WERE RECEIVED
ON MAY 12, 1991.OBJECT: TEST SWITCH FOR MATRIX PROCEDURE AND
EVALUATION PROCESS INSTRUCTIONS THAT WERE
PROVIDED.

TEST DATA:

SEE MATRIX CHARTS ATTACHED TO THE
FIELD REPORT.

To Page No. _____

Witnessed & Understood by me,

[Signature]

Date

Initiated by

[Signature]

Date

5-25-91

3713 3291

PRODUCED BY FORD

ER02-025-A 10003

STA Mfg

BPS

5/2/97

John Rant's away, FRED, Steve,

Team meeting - "Prevent action" chart
plans

- Recall parts examine
plan

XRAY

TEST TO FAILURE
REGIONAL SAMPLING

- Invite John Rant's
grantis

JUNE 17-18 TRIP TO ATTLEBORO

- Line visit John / ME
- Understand 92 Process Joe K?
- " 99 Process Tom M?
- Norm LaPointe ?

3713 1788

PRODUCED BY FORD

BB62-025-A 10004

SMMPSXEA
==>

Service to Engineering Cross Reference

09/01/00 14:52:57

SERVICE PART: 1W1Z- 2140-AA CYLINDER ASY - MASTER
HISTORY: N

A	C	ENGINEERING PART	ENG. INFO	EFFECTIVE	Effective
			ORIGIN	IN DATE	Out Date
		1W13 2C156 AA	WERS	12/14/99	

F1=Help F2=ServPartDisp F5=EngPartDisp F6=EngServXref
NO MORE RECORDS AVAILABLE

EFT54AM

ES F17A- 2L118-A4

ES 1374

ES 2669-1

ES 2922

M982-020-R 10666

SMMPSXEA

Service to Engineering Cross Reference

09/01/00 14:53:10

==> _____

SERVICE PART: 1W1Z- 2140-BA CYLINDER ASY - MASTER
HISTORY: N

A	C	ENGINEERING PART	ENG. INFO ORIGIN	EFFECTIVE IN DATE	Effective Out Date
-	-	1W13 2C156 BA	WERS	12/14/99	-----

F1=Help F2=ServPartDisp F5=EngPartDisp F6=EngServXref
NO MORE RECORDS AVAILABLE

EFT54AM

EM02-025-A 10007

09/01/00

MATTER CHANGE REPORT for NLAPOINT
(for past 2 months)

C = Matter Change; * = Changed field; N = New Matter

LOG DATE	NUMBER	MATTER NAME	STATUS	OGC ATTY	TRIAL DATE	OC FIRM
08/01/00	C 966611	SOUTH DAKOTA FLEE	OPEN	*DLAMPE		
08/01/00	C 402108	SOUTH DAKOTA STAT	OPEN	*DLAMPE		
08/01/00	C 402107	SOUTH DAKOTA STAT	OPEN	*DLAMPE		
07/06/00	N 410536	HUBBARD TROY	OPEN	DLAMPE		AZ36
07/05/00	C 403443	MYERS JEFFREY L	*CLSD	NGRABOWS		

Susan to call me back!

- FMEA for shorted switch.
- FMEA for failed BOS function
- What does competition do? SALTER
- Why a P switch? VISCON
- Immediate action (Containment)
 - Disconnect Switch (Remove & Replace)
 - Re-wire to low-side
 - ~~short out~~ Jumper out switch
 -
- 1/4 D
- Competitive Analysis.
 - of redundant sw.
 - Does current one fit?
 - Is it a redundant sw?
- OTHER TEAM MEMBERS - TOWNSEND
- FNAs require hot all time except
- Cut away of system
- Team Review

37131818

PRODUCED BY JORD

3713-026-A 10078

INTERIM REPAIR

DISABLE SPEED CONTROL DEACTIVATION SWITCH

SERVICE PROCEDURE

1. Disconnect the electrical connector from the speed control deactivation switch. See Figure 1.




FIGURE 1

2. Tape the end of the connector to prevent contamination from entering the end of the connector.
3. Tie strap the connector to the wiring harness located on the left splash shield.

PERMANENT REPAIR

SPEED CONTROL DEACTIVATION SWITCH AND CONNECTOR REPLACEMENT

AFFECTED VEHICLES: CERTAIN 1992 AND 1993 CROWN VICTORIA, GRAND MARQUIS AND TOWN CAR WITH SPEED CONTROL

OVERVIEW

This repair involves replacement of the speed control deactivation switch and the hard shell of the switch electrical connector. The connector terminals will be removed from the old connector hard shell and inserted into the new connector hard shell.

PROCEDURE

1. Install a memory saver and disconnect the negative battery terminal.
2. Disconnect the electrical connector from the speed control deactivation switch. See Figure 2.





FIGURE 2

3. Remove the locking wedge from the end of the connector. Then, disengage the locking tabs and remove the wire terminals from the connector. See Figure 3.



IR99815C

FIGURE 3

4. Obtain the new connector from the kit. Insert both wire terminal ends through the connector seal and into the connector hard shell. (The wire terminal ends may be installed into either of the connector cavities).
5. Check the connector to make sure the locking tabs have engaged both terminal ends. Also, make sure the seal is fully seated in the back of the connector. Then, install the red locking wedge to secure the terminals in the connector.
6. Obtain the speed control deactivation switch from the parts kit.
7. Remove the old speed control deactivation switch.
8. Fill the new speed control deactivation switch with High Performance DOT 3 Brake Fluid and install the speed control deactivation switch. Tighten the switch to 18 Nm (13 lb-ft).
9. Attach the electrical connector to the speed control deactivation switch.
10. Connect the battery negative cable and remove the memory saver.
11. Raise the vehicle on a hoist.
12. Connect a clear drain tube to the RH rear bleeder screw and the other end in a container partially filled with the recommended brake fluid.
13. Have an assistant pump the brake pedal and then hold firm pressure on the brake pedal.
14. Loosen the RH rear bleeder screw until a stream of brake fluid comes out. While the assistant maintains pressure on the brake pedal, tighten the bleeder screw.
 - Repeat until clear, bubble-free fluid comes out.
 - Refill the brake master cylinder reservoir as necessary.
15. Repeat Steps 12-14 for the LH rear bleeder screw.
16. Lower the vehicle.

[redacted]
From: Irving Salmeen
Sent: Wednesday, February 24, 1999 8:15 AM
To: salmeen@po.box.rl.ford.com
Subject: DOW Rep Meeting

Regards,
IRVING SALMEEN

*** Forwarding note from SREIMERS-DRBN007 02/23/99 11:09 ***
To: PKILLGOA-DRBN006 ISALMEEN-DRBN005
cc: JNEME -DRBN005 FPORTER -DRBN007 Porter, F.J.

FROM: Steve Reimers USAET(UTC -06:00)

Subject: DOW Rep Meeting

Meeting has been changed to Wednesday 2/24/99, 2pm in bldg 6 rm 3403B.
This is supporting a NHTSA investigation of underhood fires. We really need the
right people on this team. Please call me if you have any questions or if you
need further justification to support this effort.
thanks,

Steve Reimers building 6 3C043
AVT Chassis E/E System Applications mail drop 5011
39-03266 SREIMERS sreimers@ford.com fax 39-03266 >
*** Forwarding note from SREIMERS-DRBN007 02/22/99 15:32 ***
To: PKILLGOA-DRBN006 ISALMEEN-DRBN005

FROM: Steve Reimers USAET(UTC -06:00)

Subject: DOW Rep Meeting

Need a Chemistry or Materials expert to help sort out what is or maybe potential
reactions leading to brake fluid ignition inside the switch cavity of the Bra
ke Pressure switch. The main question is given the constraints of battery volt
age, 15 amps maximum current, and the combination of brake fluid, copper, zinc,
silver, sulfur, and an inductive load induced arc can there be combustion? Also
o, where does the sulfur come from?

Steve Reimers building 6 3C043
AVT Chassis E/E System Applications mail drop 5011
39-03266 SREIMERS sreimers@ford.com fax 39-03266 >
*** Forwarding note from SREIMERS-DRBN007 02/19/99 12:37 ***
To: JNEME -DRBN005 FPORTER -DRBN007 Frederick J. Porter
RENGUSI -DRBN006 SSALTER -DRBN005
NLAPOINT -DRBN006 TMASTER -DRBN006
JKAFATI -DRBN004 SREIMERS -DRBN007 Steve Reimers
FKOHL -DRBN007 Fred Kohn TBrazil -DRBN005
JMCINERN -DRBN005 DOBEL -DRBN005
LBROWN -DRBN005 SCOLEI -DRBN006
HWELFERD -DRBN005 GSTEVEN1 -DRBN005
WAERAMICZ -DRBN005 MREESSE -DRBN005
GLAROUCH -FORDNA1 TSCHRODY -VISTECN
DBUDZYNS -VISTECN PBTOKE8 -VISTECN
12060625 -EXTERNAL OTPWIDGYK -EXTERNAL

FROM: Steve Reimers USAET(UTC -06:00)

3713 5062

E982-625-A 18866

PRODUCED BY FORD

Requester: Steve Reimers
Date to be scheduled: 02/23/99
Starting time: 09:00 AM
Ending time: 11:00 AM

Location: bldg 5 3A01T

Subject: DOW Rep Meeting

Purpose: Discuss with DOW the brake pressure switch.
Attend Only if interested in materials questions?

0
A A _0 of GM

Steve Reimers building 5 3C043
AVT Chassis E/E System Applications mail drop 6011
39-03288 5REIMERS reimers@ford.com fax 39-03286 >

3713 5063

PRODUCED BY FORD

2002-025-A 10007

Irving Salmeen
From: Irving Salmeen
Sent: Wednesday, February 24, 1999 8:15 AM
To: isalmeen@pobox.srl.ford.com
Subject: DOW Rep Meeting

Regards,

IRVING SALMEEN

*** Forwarding note from SREIMERS-DRBN007 02/22/99 18:32 ***
To: PKILLGOA-DRBN005 ISALMEEN-DRBN008

FROM: Steve Reimers USAET(UTC -05:00)
Subject: DOW Rep Meeting

Need a Chemistry or Materials expert to help sort out what is or maybe potential reactions leading to brake fluid ignition inside the switch cavity of the Brake Pressure switch. The main question is given the constraints of battery voltage, 15 amps maximum current, and the combination of brake fluid, copper, zinc, silver, sulfur, and an inductive load induced arc can there be combustion? Also, where does the sulfur come from?

Steve Reimers building 5 3C043
AVT Chassis E/E System Applications mail drop 5011
39-03296 SREIMERS sreimers@ford.com fax 39-03296 >
--- Forwarding note from SREIMERS-DRBN007 02/15/99 12:37 ---
To: JNEME -DRBN005 FPORTER -DRBN007 Frederick J. Porter
RENGLUS1 -DRBN005 SEALTER -DRBN005
NLAPPOINT -DRBN005 TMASTER2 -DRBN005
JKAFATI -DRBN004 SREIMERS -DRBN007 Steve Reimers
FKOHL -DRBN007 Fred Kohl TBAZIL -DRBN005
JMCINERN -DRBN006 OGIOEL -DRBN006
LBROWN -DRBN005 SCOLE1 -DRBN006
HWELFERT3 -DRBN006 GSTEVEN1 -DRBN006
WABRAMC2 -DRBN006 MREEMB -DRBN006
SLAROUCH -FORDNA1 TACHRODY -VISTEON
DBUDZYNS -VISTEON PETOKES -VISTEON
I2080635 -EXTERNAL OTIPWOGYK -EXTERNAL

FROM: Steve Reimers USAET(UTC -05:00)

Requester: Steve Reimers
Date to be scheduled: 02/23/99
Starting time: 09:00 AM
Ending time: 11:00 AM

Location: bldg 5 3A017

Subject: DOW Rep Meeting

Purpose: Discuss with DOW the brake pressure switch.
Attend Only if Interested in materials questions?

Ü
A A _o q ÜM

3713 5050

PRODUCED BY FORD

5902-825-A 10000

Steve Reimers building 5 3C043
AVT Chassis E/E System Applications mail drop 5011
39-03286 SREIMERS sreimers@ford.com fax 39-03286 >

3713 5051

PRODUCED BY FORD

E982-825-A 10866

[REDACTED]

From: Irving Salmeen
Sent: Wednesday, February 24, 1999 8:15 AM
To: isalmeen@pobox.eri.ford.com
Subject: DOW Rep Meeting

Regards,
IRVING SALMEEN

*** Forwarding note from BREIMERS-DRBN007 02/23/99 11:09 ***
To: PKILLGOA-DRBN005 ISALMEEN-DRBN005
cc: JNEME -DRBN008 FPORTER -DRBN007 Porter, F.J.

FROM: Steve Reimers **USAET(UTC -06:00)**

Subject: DOW Rep Meeting

Meeting has been changed to Wednesday 2/24/99, 2pm in bldg 8 rm 3A038.
This is supporting a NHTSA investigation of underhood fires. We really need the
right people on this team. Please call me if you have any questions or if you
need further justification to support this effort.
thanks,

Steve Reimers building 8 3C043
AVT Chassis E/E System Applications mail drop 5011
39-03286 BREIMERS sreimers@ford.com fax 39-03286 >
--- Forwarding note from BREIMERS-DRBN007 02/22/99 15:32 ---
To: PKILLGOA-DRBN005 ISALMEEN-DRBN008

FROM: Steve Reimers **USAET(UTC -06:00)**

Subject: DOW Rep Meeting

Need a Chemistry or Materials expert to help sort out what is or maybe potential
I reactions leading to brake fluid ignition inside the switch cavity of the Bra
ke Pressure switch. The main question is given the constraints of battery volt
age, 15 amps maximum current, and the combination of brake fluid, copper, zinc,
silver, sulfur, and an inductive load induced arc can there be combustion? Als
o, where does the sulfur come from?

Steve Reimers building 8 3C043
AVT Chassis E/E System Applications mail drop 5011
39-03286 BREIMERS sreimers@ford.com fax 39-03286 >
*** Forwarding note from BREIMERS-DRBN007 02/19/99 12:37 ***
To: JNEME -DRBN008 FPORTER -DRBN007 Frederick J. Porter
PKILLGOA-DRBN005 SALTIER -DRBN008
MLAPOINT-DRBN005 TMASTERS-DRBN006
JKAFATI -DRBN004 BREIMERS-DRBN007 Steve Reimers
FKOHL -DRBN007 Fred Kohl TBAZIL -DRBN006
JMCINNIS-DRBN006 OGCEL -DRBN005
LBROWN -DRBN006 SCOLE1 -DRBN006
HWE_PERS-DRBN006 GSTEVENH-DRBN006
WABRAMCZ-DRBN006 MREESE -DRBN004
SLAROUCH-FORDNA1 TECHROOY-VISTECN
DBUDZYNS-VISTECN PSTOKES -VISTECN
12080626-EXTERNAL OTPWOGYK-EXTERNAL

FROM: Steve Reimers **USAET(UTC -06:00)**

3713 6052

PRODUCED BY FORD

ER02-025-A 16616

Requester: Steve Reimers
Date to be scheduled: 02/23/98
Starting time: 09:00 AM
Ending time: 11:00 AM

Location: bldg 5 3A017

Subject: DOW Rep Meeting

Purpose: Discuss with DOW the brake pressure switch.
Attend Only if interested in materials questions?

U
A A U of UM

Steve Reimers building 5 3C043
AVT Chassis E/E System Applications mail drop 5011
39-03289 SREIMERS3 sreimers@ford.com fax 39-03285 >

3713 5053

PRODUCED BY FORD

2002-025-A 10011

Toronto Pressure Switch Mfg 7/24/7

Steve Reimers	SREIMERS	X0328G	AVT/EECF
Shawn McCarthy	SHMCARTY	X-21355	FRL
Eve Carter	ECARTER	X31733	FRL
Dave Bauer	DBAUER	X41756	FRL
Ton Stevens	TON STEVENS	X-37395	1.2500000000000001
Greg Stevens	GSTEVEN	X3668L	RVT MAT
Norm Lafontaine	NLAPOINT	X9268L	AVT-DES. Aire
Steve LaRouche	SLAROUCHE	S487G	Central Ln
ETIS KLAAS	PKLAAS	21613	central 48
M.K. KITT (DOW)	M.K. KITT@DOW.COM	223 553 6343	111-2000
Kay Grubbs	KGrubbs	38658	RVT Mfg
P.Z. (Unknown)	PZESTI.CD		T-
Rob English	ROBENGL	73225	AVT-SEE
John P. Dowell CD	JOHNDOW	X-33384	111
John P. Dowell CD			
<i>Scott Urquiza</i>	SURQUIZA	200-0007	Dow Parameter
<i>Paul Portnoy</i>	PAULPORTNOY	(33)521-53722	AVT-SEE

3713 1787

PRODUCED BY FORD

EM2-025-A 10012

* Note printed by FPORTER on 6 Mar 1999 at 11:09:53 *

From: SLAROUCH--FORDMAIL Date and time 03/02/99 11:56:23
To: FPORTER --FORDMAIL Porter, Fred (F.J. NLAPOLST--FORDMAIL LaPointe, Norman (SREIMERS--FORDMAIL Reimers, Steve (S. I2060628--EXTERNAL 'A. Rahman' SMCCARTY--FORDMAIL McCarthy, Shaun (S SLAROUCH--FORDMAIL LaRouche, Steve (S
From: LaRouche, Steve (S.)
Subject:

We have found three switches so far (including the one to be analyzed by the Sci Lab), that will not open electrically when disc is heard to snap under application of air pressure. I sectioned one of these switches and found what appears to be water (it evaporated rather quickly at room temp) and corrosion product. I found that the transfer pin has been stuck in place by the corrosion products. What this means, is that even if the disc snaps, the pin will not pull back, and the contacts will not open. None of these switches showed evidence of diaphragm leakage on the test stand.

Steve LaRouche (SLAROUCH)
Metallurgy Section, Central Laboratory, Room W410
(313) 845-4876 (313) 322-1614 FAX

3713 1371

PRODUCED BY FORD

E882-826-A 10013

Shaun McCarthy
From: Shaun McCarthy
Sent: Tuesday, March 02, 1999 2:50 PM
To: smccart3@gw.ford.com
Subject: NO SUBJECT

Regards,
SHAUN McCarthy _ SRL Room 1339 Mail Stop 1170
32-21365 FAX 32-31129
** Forwarding note from SLAROUCH-FORDMAIL 03/02/99 11:56 --
To: FPORTER -FORDMAIL Porter, Fred (F.J. NLAPOINT-FORDMAIL LePoints, Norman (S)
SRIMERS-FORDMAIL Reimers, Steve (S. I2080625-EXTERNAL 'A. Rahman'
SMCCART3-FORDMAIL McCarthy, Shaun (S SLAROUCH-FORDMAIL LaRouche, Steve (S

From: LaRouche, Steve (S.)
Subject:

We have found three switches so far (including the one to be analyzed by the Sci Lab), that will not open electrically when disc is heard to snap under application of air pressure. I sectioned one of these switches and found what appears to be water (it evaporated rather quickly at room temp) and corrosion product. I found that the transfer pin has been stuck in place by the corrosion products. What this means, is that even if the disc snaps, the pin will not pull back, and the contacts will not open. None of these switches showed evidence of diaphragm leakage on the test stand.

Steve LaRouche (SLAROUCH)
Metallurgy Section, Central Laboratory, Room N410
(313) 848-4876 (313) 322-1614 FAX

3713 5026

PRODUCED BY FORD

2002-025-A 10014

Brooks Pressure-Switch Meeting 1/3

	EMAIL	3/3/99
Steve Rainiers	SRAINERS	X03286 AUT/EES
Fred Portee	FPORTEE	X53722 AUT/EES
M. P. REESE	MREESE	X77142 OPD LVC
Rob Sharpe	rsharpe@tri.com	(416) 362-8747 Tens Instruments
EMIL STEVENS	GSTEVENS	X36686 AUT MATL
Noem LaPointe	NLAPOINT	X42686 AUT/DES. Inv.
Steve Le-Rewent	SLAROUCHE	54876 CENTRAL LAB
Judy M. Young	J-MYOUNG@tri.com	5062343000 TE QRA
WILLIAM M. ABRAMOWICZ	WABRAMOW	313 32 23284 ASO
* Steve Boringhouse / Bryan Dugay from TS on conference call speaker phone.		

3713 1794

PRODUCED BY FORD

ER02-020-A 10015

RVT - ESE WORKPLAN FOR 92-93MY TOWN CAR UNDERHOOD FIRES

TOWNS CAR UNDERHOOD FIRES		
	Target Complete	Date
Read, assess, and categorize CQIS verbatims:	Champion	
(A). Town Car, CV/GM.	RVT-Elect	A - 3/8/99
(B). Econoline and F-Series.	RVT-Elect	S - 3/12/99
(2). Identify underhood hot at all times wiring circuits and electrical components.	RVT-Elect	S - 3/9/99
(A). Draw possible conclusions relative to CQIS verbatims.	RVT-Elect	S - 3/10/99
(3). Review previous repair info on 47 Town Cars identified with underhood fires:	RVT-Elect	A - 3/5/99
(A). Draw possible conclusions relative CQIS verbatims.	RVT-Elect	S - 3/9/99
(4). Correlate 47 Town Cars against orderable options - traction assist and trailer tow.	FCSD	A - 3/1/99
(A). First 31 out of 47 Town Cars.	FCSD	S - 3/10/99
(B). Last 16 out of 47 Town Cars.	RVT-Elect	S - 3/11/99
(C). Draw possible conclusions relative to CQIS verbatims.	RVT-Elect	S - 3/11/99
(5). Perform field inspections of the 47 Town Cars:	LVC-Safety	S - 3/15/99
(A). Perform phone survey using questionnaires by RVT-EESE and Design Analysis.	LVC-Safety	S - 3/15/99
(B). Litigation Prevention Team follows up with selected field reviews of vehicles.	LVC-Safety	S - 4/5/99
(6). Brake Pressure Switch:	RVT-Chassis	
(A). Determine root cause.	RVT-Chassis	
(B). Brainstorm and identify possible resolution proposals.	RVT-Chassis	S - 3/10/99
* Recommend resolution proposal along with supporting rationale.	RVT-Chassis	S - 3/22/99
(C). Identify required DVP&R testing: CAE and/or Bench and/or In-Vehicle, etc.	RVT-Chassis	
* Complete DVP&R testing.	RVT-Chassis	
(D). Determine manufacturing feasibility with affected suppliers.	RVT-Chassis	S - 3/17/99
* Obtain supplier costing/info/tools to support resolution proposal.	RVT-Chassis	
(E). Determine Assy Fees for proposal - review installation procedure with FCSD.	RVT-Chassis	S - 3/17/99
(F). Complete 14D white paper.	RVT-Chassis	

Information contained herein is CONFIDENTIAL and is the sole property of [REDACTED]. It is to be kept secret and not disclosed to anyone outside of [REDACTED] without prior written consent of [REDACTED].

3719 1732

PRODUCED BY FORD

1982-125-A 10014

* Note printed by FPORTER on 5 Mar 1999 at 17:40:04 *

From: TRABIL --DRBN005 Date and time 03/05/99 08:12:05
To: BREIMERS--DRBN007 Reimers, Steve
cc: BECHEN --DRBN007 REVERSE --DRBN005
BFRAME --DRBN005 LIMITER --DRBN005
WLAPOINT--DRBN005 FPORTER --DRBN007

FROM: Tom Basil USAPT(UTC -05:00)
Subject: Brake pressure switch
I don't think so without greater risk than existing ideas, but I welcome ideas
from cos.

Have a good day!

Thomas S. Basil (313) 59-47547 Lrg & Lnx Car CPO Brakes/Veh Supv
Drop 1223-LVC, Cuba 24-H36, fax 51-36678, pager (888) 375-6649
*** Forwarding note from BREIMERS--DRBN007 03/04/99 11:15 ***

To: TRABIL --DRBN005 Basil, Tom FPORTER --DRBN007 Porter, F.J.

From: Steve Reimers USAPT(UTC -05:00)
Subject: Brake pressure switch
Tom, Another potential solution... Isolate the pressure switch hydraulic port f
rom the vehicle ground. Is there a way to connect the brake pressure switch to
the prop-valve hydraulic port with a non-conductive tubing or spacer or someth
ing else????

Steve Reimers building 5 3ED08
AVT Chassis E/E System Applications mail drop 5011
19-C1286 BREIMERS fax 39-03386 ,>

3713 1370

PRODUCED BY FORD

5982-625-A 10017

Note printed by FPORTER on 18 Mar 1989 at 17:27:35

From: SLAROUCHE--FORDMAIL Date and time 03/12/99 13:03:30
To: WLAPPOINT--FORDMAIL LaPointe, Norman SLAROUCHE--FORDMAIL LaRouche, Steve
FPORTER --FORDMAIL Porter, Fred BREIMERS--FORDMAIL Reimers, Steve
GSTEVEN1--FORDMAILP Stevens, Gregory

From: LaRouche, Steve (S.)
Subject: CASIS

I received another switch from the oasis. '93 Town Car, '83k miles. Dealer: Robinson Brothers, Baton Rouge, LA. Complaint was that ABS light stays on, brakes grab when vehicle is coasting as though brakes had been applied. Replaced switch because it was found to be leaking.

Steve LaRouche (SLAROUCHE)
Metallurgy Section, Central Laboratory, Room #410
(313) 545-4874 (313) 322-1814 FAX

3713 1356

PRODUCED BY

EP82-825-A 10

Schrody, Thomas (T.P.)

From: Fred Kohl [mailto:fkohl@gw.ford.com]
Sent: Monday, March 22, 1999 3:41 PM
To: dbudzyns@visteon.com; ghuberts@visteon.com
Cc: techrody@visteon.com
Subject: RE: Brake Pressure Switch In Ground Return Circuit

Dan and Garland: I have scheduled tomorrow morning Tues at 8am to 8:30 to review Brake Pressure Switch in Grd Circuit status with Scott in his office. Please attend if you want.

Note: Tom Schrody is coming.

Regards, Fred Kohl, Precision Speed Control (Panther)
PROFS ID: FKOHL Phone (313) 32-21801 Pager (868) 377-6280
IBM Mail(USFMCSJZ)
Mailing Address: EVB, 1WE06
*** Forwarding note from SSIMPS03-VISTEON 03/21/99 14:44 ***
To: FKOHL -FORDMAIL Kohl, Fred (F.H.)
cc: DBUOZYNS-VISTEON Budzynski, Dan (D.)

From: Simpson, Scott (S.L.)
Subject: RE: Brake Pressure Switch In Ground Return Circuit

Please set up a meeting to brief me on this. We don't need more than 30 minutes.

Scott Simpson
Manager, Powertrain Electronic Systems and Applications
Powertrain Control Systems/Visteon
Phone: (313) 621-7959 Fax: (313) 322-1830

—Original Message—

From: Fred Kohl [mailto:fkohl@gw.ford.com]
Sent: Thursday, March 18, 1999 11:53 AM
To: dbudzyns@visteon.com; fporter@gw.ford.com; ghuberts@visteon.com; sreimers@gw.ford.com; ssimpec3@visteon.com; techrody@visteon.com
Cc: fkohl@gw.ford.com
Subject: Brake Pressure Switch In Ground Return Circuit

Fred Porter and Steve Reimers:

Attached file (GrdReturn.doc) details what it would take at a minimum to place the brake pressure switch (deactivation switch) in the ground return circuit.

Please note a complete design analysis would be needed to determine if other changes are required.

Visteon does not feel this change is a viable solution for fixing the issue. We will continue to support you and the teams efforts to resolve the issue.

A reply on Visteon letterhead will come next week.

Regards, Fred Kohl, Precision Speed Control (Panther)
PROFS ID: FKOHL Phone (313) 32-21801 Pager (868) 377-6280
IBM Mail(USFMCSJZ)
Mailing Address: EVB, 1WE06

Schrody, Thomas (T.P.)

From: Fred Kohl (fkohl@gw.ford.com)
Sent: Thursday, March 18, 1999 11:53 AM
To: dbudzyns@visteon.com; fporter@gw.ford.com; ghuberts@visteon.com;
sreimers@gw.ford.com; salmpac3@visteon.com; tschrody@visteon.com
Cc: fkohl@gw.ford.com
Subject: Brake Pressure Switch in Ground Return Circuit

Fred Porter and Steve Reimers:

Attached file (GrdReturn.doc) details what it would take at a minimum to place the brake pressure switch (deactivation switch) in the ground return circuit.

Please note a complete design analysis would be needed to determine if other changes are required.

Visteon does not feel this change is a viable solution for fixing the issue. We will continue to support you and the teams efforts to resolve the issue.

A reply on Visteon letterhead will come next week.

Regards,... Fred Kohl, Precision Speed Control (Panther)
PROPS ID: FKOHL Phone (313) 32-21801 Pager (888) 377-0200
IBM Mail(USFMCBJZ)
Mailing Address: EV9, 1WE08



Schrody, Thomas (T.P.)

From: Steve Reimers (sreimers@gw.ford.com)
Sent: Thursday, February 25, 1999 4:15 PM
To: wboyer1@visteon.com
Cc: fkohl@gw.ford.com; tschrody@visteon.com; gdwygart@visteon.com; ghuberts@visteon.com;
Porter, F.J.
Subject: RE: Speed control servo

Thanks for the technical info. Did the bad R44 NGSC batch include any MY98 or MY 99 Town cars built after 11/1/98? If so, was there any corrective action for the vehicles already delivered? Also, are there other failure modes internal to the NGSC which result in the clutch coil being energized when it should be off?

Steve Reimers building 5 3C043
AVT Chassis E/E System Applications mail drop 5011
39-03286 SREIMERS sreimers@ford.com fax 39-03286 >
--- Forwarding note from WBOYER1 -VISTEON 02/25/99 15:51 ---
To: SREIMERS-FORMAIL Reimers, Steve (S.
cc: FKOHL -FORMAIL Kohl, Fred (F.H.) TSCHRODY-VISTEON Schrody, Thomas (T.
GDYGERT-VISTEON Dygart, Greg (G.J. DBUDZYNS-VISTEON Budzynski, Dan (D.
GHUBERTS-VISTEON Huberts, Garlan (G

From: Boyer, Wee (W.D.)
Subject: RE: Speed control servo

9bvrq

Greg Dygart helped me with this. He ran a dynamic transient response analysis on the flyback voltage appearing at the EPS - Dead node (our J1-4 terminal) when the clutch is engaged and switched off by the external EPS. With the flyback clamping resistor in place, the transient is limited to a relatively clean, exponentially decaying impulse peaking at about -50 volts, with or without the 22 nF capacitor in our module, confirming my description of 2/22/1999.

Without the 82 ohm resistor and diode across the clutch winding, the voltage is an underdamped oscillation that theoretically peaks at +/- 1000 volts and whose envelope decays exponentially. It is very likely that the switch and/or capacitor (rated at 100 volts dc, 200 v pk) would break down at a much lower voltage. The energy stored in the clutch winding could cause the switch to arc. For this to occur the ignition must be ON and speed control must have been "SET" (or #1 fault = shorted MOSFET driver) AND the flyback resistor, R44, is open (fault #2) AND the brake pressure builds up to open the switch. If fault #1 occurs without the switch opening, a continuous current of about 0.5 amp drains the battery rather rapidly (overnight) and the driver will be aware that something is wrong. Fault #2 is known to have caused fault #1 and the drained battery on a small population of vehicles built with Thin FR4 (non-ceramic) circuits and a bad batch of R44 resistors from the supplier! I do not believe these are in the same generation of NGSC modules as the present concern.

Please copy Huberta, Garlan (G.J.) and/or Dygert, Greg (G.J.) with any reply or response to this message.

Regards,
Wes (W. D.) Boyer Phone: (313) 249-9417
Visteon Automotive Systems Fax: (313) 322-3829
Precision Speed Control - Electronic Design E-mail: WBoyer1@visteon.com
(Usually at work, Wednesday + Thursday, only; Personal e-mail:
w.d.boyer@leesa.org)

> —Original Message—
> From: Steve Reimers [SMTP:sreimers@gw.ford.com]
> Sent: Monday, February 22, 1999 12:16 PM
> To: wboyer1@visteon.com
> Cc: lkohl@gw.ford.com
> Subject: RE: Speed control servo
>
> Can you model this with the flyback resistor disconnected?
>
> Steve Reimers building 5 SC045
> AVT Chassis E/E System Applications mail drop 8011
> 39-03260 BREIMERS-POFOMAIL sreimers@ford.com fax 39-03265 >
> *** Forwarding note from BREIMERS-POFOMAIL 02/22/99 10:00 ***
> To: BREIMERS-POFOMAIL Reimers, Steve (S. WBOYER1-VISTEON Boyer, Wes
> (W.D.)
> cc: PKOHL --POFOMAIL Kohl, Fried (F.H.) TSCHIRODY-VISTEON Schrödy,
> Thomas (T
>
> From: Boyer, Wes (W.D.)
> Subject: RE: Speed control servo
>
> The transient pulse will be an identical mirror image of the one shown in
> the previous traces. That is, instead of floating at the Vbias level,
> "charging" the inductance at zero [the Vds(on) of the MOSFET] and flying
> back to a positive voltage, the pulse on the BPS side (referenced to
> ground)
> will fly back to a negative voltage limited by the IR drop across the
> clamping resistor. There will be a small difference in the dynamics due

> to
> a capacitor at the BPS-Dead node that doesn't enter the picture when the
> FET
> is switched. I will look into that on Wednesday.
>
> Wes
> w.d.boyer@leee.org
>
> -----Original Message-----
> From: Steve Reimers
> To: wboyer1@visteon.com
> Cc: fkohl@gw.ford.com; tschrody@visteon.com
> Sent: 2/18/99 5:46 PM
> Subject: RE: Speed control servo
>
> Please re-run this model with the following condition: No Fly-back and
> FET alive
> ys on and use the Brake Pressure switch to create the switching
> transient.
> What is the voltage at the brake pressure switch?
>
> Steve Reimers building 5 3C043
> AVT Chassis E/E System Applications mail drop 5011
> 3B-03286 BREIMERS reimers@ford.com fax 3B-03286 >
> *** Forwarding note from WBOYER1 -VISTEON 02/17/99 10:58 ---
> To: DPORTER1-VISTEON Porter, David (D.L.) BREIMERS-FORMAIL Reimers,
> Steve (S.
> cc: FKOHLL --FORMAIL Kohl, Fred (F.H.) TSCHRODY-VISTEON Schrody,
> Thomas (T
> DBUDZYNS-VISTEON Budzynski, Dan (D.
>
> From: Boyer, Wes (W.D.)
> Subject: RE: Speed control servo
>
> Attached is an analysis of the idealized flyback pulse of the turn-off
> transient on the clutch winding:
> <<C1_8244.pdf>>
>
> Regards,
> Wes (W. D.) Boyer Phone: (313) 248-8417
> Visteon Automotive Systems Fax: (313)
> 322-3529
> Precision Speed Control - Electronic Design E-mail:
> WBoyer1@visteon.com
> (Usually at work, Wednesday + Thursday, only; Personal e-mail:
> w.d.boyer@leee.org)
>
> -----Original Message-----
> > From: Porter, David (D.L.)
> > Sent: Wednesday, February 17, 1999 10:29 AM
> > To: Steve Reimers
> > Cc: Fred Kohl (E-mail); Tom Schrody (E-mail); Wes Boyer (E-mail)
> > Subject: RE: Speed control servo
> >
> > Steve, the inductance of the clutch was at one time called out as
> 53-112
> > MH. This is measured at 1 KHz and in parallel.
> >
> > Dave Porter dporter1@Visteon.net Phone: 313-390-6574
> > Fax
> > 313-322-3529
> >
> > -----Original Message-----
> > From: Steve Reimers (SMTP:reimers@gw.ford.com)

>> Sent: Wednesday, February 17, 1999 9:53 AM
>> To: dporter1@visteon.com; fkohl@gw.ford.com
>> Subject: FW: Speed control servo

>>
>> Fred Kohl will bring the parts to Visteon. These were retrieved
>> from junkyards
>> as part of a sampling process related to Brake Pressure switch
>> function. The
>> Brake Pressure switch ES spec defines 300 milli-Henry as the
> minimum
>> test induc
>> tance for life testing. Is this a good number? Can you measure
> the
>> Inductance
>> to establish a minimum and maximum?

>>
>> Steve Reimers building 5 3C043
>> AVT Chassis E/E System Applications mail drop 5011
>> 39-03266 SREIMERS sreimers@ford.com fax 39-03266 >
>> *** Forwarding note from DPORTER1--VISTEON 02/17/99 08:16 ***
>> To: SREIMERS--FORDMAIL Reimers, Steve (S.
>> cc: FKohl --FORDMAIL Fred Kohl (E-mail) WBOYER1 --VISTEON Wes
>> Boyer (E-mail)
>>
>> From: Porter, David (D.L.)
>> Subject: FW: Speed control servo
>>
>> Steve, the clutch resistance should be in the neighborhood of 24
>> Ohms. If
>> the clutch winding is intact, and nothing is mechanically
> damaged,
>> etc. I
>> would assume the parts are functional. There is no specified
>> inductance on
>> the clutch, because it varies with gear position (open or
> closed).
>> If it
>> is important to check functionality of these parts, bring them
> to
>> curtab,
>> and I can bench test them for you. Are these parts off vehicles,
> or
>> just
>> unused parts that have been lying in a corner for a few years?
> You
>> did not
>> mention motor phase inductance or resistance. Generally, the
> motors
>> are OK
>> If they rotate freely, and the three phases all have a
> resistance of
>> about
>> 2.5 Ohms.
>>
>> Dave Porter dporter1@Visteon.com Phone:
> 313-390-6674
>> Fax
>> 313-322-3829
>>
>> > ---Original Message---
>> > From: Boyer, Wes (W.D.)
>> > Sent: Wednesday, February 17, 1999 8:05 AM
>> > To: Porter, David (D.L.)
>> > Subject: FW: Speed control servo

>> >
>> >
>> > I.y.
>> > Regards,
>> > Wes (W. D.) Boyer Phone: (313)
>> 248-3417
>> > Viateon Automotive Systems Fax: (313)
>> 322-3529
>> > Precision Speed Control - Electronic Design E-mail:
>> WBoyer1@viateon.com
>> > (Usually at work, Wednesday + Thursday, only; Personal e-mail:
>> > w.d.boyer@iesa.org)
>> >
>> > -----Original Message-----
>> > From: Fred Kohl [SMTP:fkohl@gw.ford.com]
>> > Sent: Tuesday, February 16, 1999 3:48 PM
>> > To: wboyer1@viateon.com; techrody@viateon.com
>> > Subject: RE: Speed control servo
>> >
>> > fyi
>> >
>> > Regards,... Fred Kohl, Precision Speed Control (Panther)
>> > PROFB ID: FKOHL Phone TBD Pager (888) 377-6280
>> > IBM Mail(USPMCCB1Z)
>> > Mailing Address: ETC C378
>> > *** Forwarding note from BREIMERS--DRBN007 02/16/99 12:36 ***
>> > To: FKOHL --DRBN007
>> >
>> > FROM: Steve Reimers USAET(UTC
>> > -06:00)
>> > Subject: RE: Speed control servo
>> > These are from MY92 and 93. No known failures. Just want to
> know
>> > If
>> > there
>> > clutch control function has degraded.
>> >
>> > Steve Reimers building 5 SC043
>> > AVT Chassis E/E System Applications mail drop 5011
>> > 39-03286 BREIMERS reimers@ford.com fax 39-03286 >
>> > *** Forwarding note from FKOHL --FORDMAIL 02/16/99 10:33 ***
>> > To: TECHRODY-VISTEON Schrody, Thomas (T
>> > cc: DBUDZYNS-VISTEON Budzynski, Dan (D. FKOHL --FORDMAIL
> Kohl,
>> > Fred
>> > (F.H.)
>> > BREIMERS--FORDMAIL Reimers, Steve (S.
>> >
>> > From: Boyer, Wes (W.D.)
>> > Subject: RE: Speed control servo
>> >
>> > I'll send a copy of the complete clutch-dump analysis when I
> get
>> > in on
>> > Wednesday.
>> >
>> > What model year clutches are we talking about? And, Why from
> the
>> > "junkyard?"
>> >
>> > Wes
>> > w.d.boyer@iesa.org
>> > -----Original Message-----
>> > From: Schrody, Thomas (T.P.)

>> > To: Boyer, Wes (W.D.)
>> > Sent: 2/16/98 10:19 AM
>> > Subject: FW: Speed control servo
>> >
>> > Wes,
>> >
>> > I don't think you're in today, but if you are... Could you
> respond
>> to
>> > Steve Reimers? I'm busy at NPEF and will return tomorrow.
>> >
>> > -----Original Message-----
>> > From: Fred Kohl
>> > To: techrooty@visi.com
>> > Cc: cbudzyn@visi.com; fkohl@gw.ford.com;
>> > sreimers@gw.ford.com
>> > Sent: 2/16/98 7:58 AM
>> > Subject: Speed control servo
>> >
>> > Can you answer Steve questions?
>> >
>> > Regards,... Fred Kohl, Predelion Speed Control (Panther)
>> > PROFS ID: FKOHL Phone TBD Pager (888) 377-6200
>> > IBM Mail(USFMCSJZ)
>> > Mailing Address: ETC C375
>> > *** Forwarding note from SREIMERS--DRBN007 02/16/98 15:14 ***
>> > To: FKOHL --DRBN007
>> >
>> > FROM: Steve Reimers USAET(UTC)
>> > -0500
>> > Subject: Speed control servo
>> > What is the inductance and resistance of the clutch? What is
> used
>> > to
>> > clamp the
>> > flyback voltage? What is the magnitude of the flyback
> voltage?
>> > I have collected at least ten speed servos from junk yards.
> Can
>> > you test
>> > them?
>> > or function?
>> >
>> > Steve Reimers building 5 3C048
>> > AVT chassis E/E System Applications mail drop 5011
>> > 39-03298 SREIMERS sreimers@gw.ford.com fax 39-03298 >
>
>
> Attachments sent separately.
>
> Data Type File Name
> -----
> BINARY CL_82R44.PDF_PC

3713 4955

Schrody, Thomas (T.P.)

From: Steve Reimers [sreimers@gw.ford.com]
Sent: Wednesday, February 24, 1999 8:49 AM
To: tschrody@vistacon.com
CC: fkohl@gw.ford.com
Subject: RE: Speed Control Output

I agree a stuck on condition would drain the battery. The other thing it does is provide a potential for arcing at the brake pressure switch contacts every time the switch actuates.

I am interested in ANY failure mode where the clutch output circuit provides a ground path when it should not. Does your DFMEA address this mode of failure?

One possible cause could be a FET latching fault (something I came across years ago). This fault results in the FET being turned on by some internal parasitic mechanism (usually triggered by an over-voltage).
thanks,

Steve Reimers building 5 3C043
AVT Chassis E/E System Applications mail drop 5011
39-03266 SREIMERS sreimers@ford.com fax 39-03266 >
*** Forwarding note from TSCHRODY--VISTEON 02/24/99 07:24 ***
To: SREIMERS-FORDMAIL, Reimers, Steve (S.
cc: FKOHLE --FORDMAIL Kohl, Fred (F.H.)

From: Schrody, Thomas (T.P.)
Subject: RE: Speed Control Output

I'm not sure I understand your question. A continuously energized clutch circuit is not considered a failure mode. The FET is in the "latched" on state whenever the speed control is engaged. When the brake pressure switch disconnects the power from the clutch, the microprocessor will detect it and turn the FET off. When power is re-applied to the clutch, it would be off.

A shorted clutch driver is a potential failure mode (however, I did not see this failure mode on the one badly burned unit I examined). If the FET were shorted, the clutch would be on whenever the brake pressure switch was closed. Aside from draining the battery when the ignition is off, this would pose no problem. The amount of current drawn by the circuit would be no greater than when the speed control was engaged.

From a safety standpoint, our system will still disengage because the amplifier will see the BCC switch and cancel. In addition, the removal of power by the brake pressure switch will also cancel the system. In both cases, the servo is spooled to the zero (throttle released) position and the clutch is released.

I'll try to make it to your 2:00 meeting this afternoon. I don't have badge access to Building 5. Do you know who I can contact to gain access?

Regards,

Thomas Schrody
Product Design Engineer ETC, C-365
Precision Speed Control Tel: (313) 323-9696
Visteon Automotive Systems Fax: (313) 322-3629

> -----Original Message-----

> From: Steve Reimers [SMTP:sreimers@gw.ford.com]
> Sent: Tuesday, February 23, 1999 5:25 PM
> To: fkohl@gw.ford.com
> Cc: techrody@visteon.com
> Subject: Speed Control Output
>
> Does your FMEA include a condition where the clutch is continuously
> energized b
> because the FET output driver is latched in the ON-state? Is this a
> failure mode?
> e for the output FET circuit? When the Brake pressure switch disconnects
> the p
> power to the clutch would that cause the FET to unlatch? When the
> Brake pressure switch re-applies power to the clutch would the FET
> re-latch or
> stay OFF?
>
> Steve Reimers building 5 3C043
> AVT Chassis E/E System Applications mail drop 8011
> 39-03286 SREIMERS sreimers@ford.com fax 39-03286 >

Schrody, Thomas (T.P.)

From: Boyer, Wes (W.D.)
Sent: Monday, February 22, 1999 10:00 AM
To: Reimers, Steve (S.J.); Boyer, Wes (W.D.)
Cc: Kohl, Fred (F.H.); Schrody, Thomas (T.P.)
Subject: RE: Speed control servo

The transient pulse will be an identical mirror image of the one shown in the previous traces. That is, instead of floating at the V_{BATT} level, "charging" the inductance at zero (the V_{Ds(on)} of the MOSFET) and flying back to a positive voltage, the pulse on the BPS side (referenced to ground) will fly back to a negative voltage limited by the I_R drop across the clamping resistor. There will be a small difference in the dynamics due to a capacitor at the BPS-Dsac node that doesn't enter the picture when the FET is switched. I will look into that on Wednesday.

Wes
w.d.boyer@isaaa.org

---Original Message---

From: Steve Reimers
To: wboyer1@visteon.com
Cc: fkohl@gw.ford.com; techrody@visteon.com
Sent: 2/18/99 5:46 PM
Subject: RE: Speed control servo

Please re-run this model with the following condition: No Fly-back and
FET alive.
yes on and use the Brake Pressure switch to create the switching
transient.
What is the voltage at the brake pressure switch?

Steve Reimers building 5 3C043
AVT Chassis E/E System Applications mail drop 8011
39-03286 SREIMERS sreimers@ford.com fax 39-03286 >
*** Forwarding note from WBOYER1 -VISTEON 02/17/99 10:00 ***
To: DPORTER1-VISTEON Porter, David (D.L.SPREMERS-FORDMAIL Reimers,
Steve (S.
cc: FKohl -FORDMAIL Kohl, Fred (F.H.) TECHRODY--VISTEON Schrody,
Thomas (T
DBUDZYNS-VISTEON Budzynski, Dan (D.

From: Boyer, Wes (W.D.)

Subject: RE: Speed control servo

Attached is an analysis of the idealized flyback pulse of the turn-off transient on the clutch winding:
[**<<CI_8244.pdf>>**](#)

Research,

Wee (W. D.) Boyer
Visteon Automotive Systems
Phone: (313) 249-9417
Fax: (313)

Precision Speed Control - Electronic Design E-mail:
WBoyer1@visi.com
(Usually at work, Wednesday + Thursday, only; Personal e-mail:
w.d.boyer@lisa.org)

> ---Original Message---
> From: Porter, David (D.L.)
> Sent: Wednesday, February 17, 1999 10:29 AM
> To: Steve Reimers
> Cc: Fred Kohl (E-mail); Tom Schroyd (E-mail); Wes Boyer (E-mail)
> Subject: RE: Speed control servo
>
> Steve, the inductance of the clutch was at one time called out as
53-112
> M-H. This is measured at 1 KHz and in parallel.
>
> Dave Porter dporter1@Visteon.com Phone: 313-380-8674
Fax
> 313-322-3529
>
> ---Original Message---
> From: Steve Reimers [SMTP:sreimers@gw.ford.com]
> Sent: Wednesday, February 17, 1999 9:53 AM
> To: dporter1@visteon.com; fkohl@gw.ford.com
> Subject: FW: Speed control servo
>
> Fred Kohl will bring the parts to Visteon. These were retrieved
from junkyards
> as part of a sampling process related to Brake Pressure switch
function. The
> Brake Pressure switch ES spec defines 300 milli-Newton as the
minimum
> test induc
> tance for life testing. Is this a good number? Can you measure
the
> inductances
> to establish a minimum and maximum?
>
> Steve Reimers building 5 3C043
AVT Chassis E/E System Applications mail drop 5011
39-03229 BREIMERS reimers@ford.com fax 39-03229 >
*** Forwarding note from DPORTER1-VISTEON 02/17/99 08:18
> To: BREIMERS-FORDMAIL Reimers, Steve (B.
> cc: PKOHL --FORDMAIL Fred Kohl (E-mail) WBOYER1-VISTEON
> Boyer (E-mail)
>
> From: Porter, David (D.L.)
> Subject: FW: Speed control servo
>
> Steve, the clutch resistance should be in the neighborhood of 24
Ohms. If
> the clutch winding is intact, and nothing is mechanically
damaged.
> etc.

> would assume the parts are functional. There is no specified
> inductance on
> the clutch, because it varies with gear position (open or
closed).
> If it
> is important to check functionality of these parts, bring them
to
> our lab,
> and I can bench test them for you. Are these parts off vehicles,
or
> just
> unused parts that have been lying in a corner for a few years?
You
> did not
> mention motor phase inductance or resistance. Generally, the
motors
> are OK
> if they rotate freely, and the three phases all have a
resistance of
> about
> 2.6 Ohms.
>
> Dave Porter dporter1@Viateon.com Phone:
313-390-8874
> Fax
> 313-322-3629
>
> > ---Original Message---
> > From: Boyer, Wes (W.D.)
> > Sent: Wednesday, February 17, 1999 8:05 AM
> > To: Porter, David (D.L.)
> > Subject: FW: Speed control servo
>
>
> f.y.i.
> Regards,
> Wes (W. D.) Boyer Phone: (313)
248-9417
> > Viateon Automotive Systems Fax: (313)
322-3629
> > Precision Speed Control - Electronic Design: E-mail:
WBoyer1@viateon.com
> > (Usually at work, Wednesday + Thursday, only; Personal e-mail:
> > w.d.boyer@isae.org)
>
> > ---Original Message---
> > From: Fred Kohl [BMTP:kohl@gw.lord.com]
> > Sent: Tuesday, February 16, 1999 3:48 PM
> > To: wboyer1@viateon.com; leichrody@viateon.com
> > Subject: RE: Speed control servo
>
> > fyi
>
> > Regards... Fred Kohl, Precision Speed Control (Panther)
> > PROFS ID: FKOHLL Phone TBD Pager (586) 377-6280
> > IBM Mail(USPMCBJZ)
> > Mailing Address: ETC C376
> > *** Forwarding note from BREIMERS-DRBN007 02/16/99 12:36 ***
> > To: FKOHLL -DRBN007
>
> > FROM: Steve Reimers USAET(UTC
-05:00)
> > Subject: RE: Speed control servo
> > These are from MY92 and 93. No known failures. Just want to

know
> If
> > there
> > clutch control function has degraded.
>
> > Steve Reimers building 5 3C043
> > AVT Chassis S/E System Applications mail drop 5011
> > 39-03286 SREIMERS reimers@ford.com fax 39-03288 >
> > *** Forwarding note from FKOHLL -FORDMAIL 02/16/99 10:33 ***
> > To: TSCHRODY-VISTEON Schrödy, Thomas (T
> > cc: DBUDZYNS-VISTEON Budzynski, Dan (D. FKOHLL -FORDMAIL
Kohl,
> Fred
> > (F.H.)
> > SREIMERS-FORDMAIL Reimers, Steve (S.
>
> > From: Boyer, Wes (W.D.)
> > Subject: RE: Speed control servo
>
> > I'll send a copy of the complete clutch-dump analysis when I
get
> In on
> > Wednesday.
>
> > What model year clutches are we talking about? And, Why from
the
> > "junkyard?"
>
> > Wes
> > w.d.boyer@isca.org
> > -----Original Message-----
> > From: Schrödy, Thomas (T.P.)
> > To: Boyer, Wes (W.D.)
> > Sent: 2/16/99 10:13 AM
> > Subject: FW: Speed control servo
>
> > Wes,
>
> > I don't think you're in today, but if you are... Could you
respond
> to
> > Steve Reimers? I'm busy at NPEF and will return tomorrow.
>
> > -----Original Message-----
> > From: Fred Kohl
> > To: tschrody@visteon.com
> > Cc: dbudzyns@visteon.com; fkohl@gw.ford.com;
reimers@gw.ford.com
> > Sent: 2/16/99 7:00 AM
> > Subject: Speed control servo
>
> > Can you answer Steve questions?
>
> > Regards, ... Fred Kohl, Precision Speed Control (Panther)
> > PROPS ID: FKOHLL Phone TBD Pager (800) 377-6280
> > IBM Mail(USFMCSJZ)
> > Mailing Address: ETC C375
> > *** Forwarding note from SREIMERS-ORBN007 02/16/99 10:14 ***
> > To: FKOHLL -ORBN007
>
> > FROM: Steve Reimers USAET(UTC
-05:00)
> > Subject: Speed control servo
> > What is the inductance and resistance of the clutch? What is

used
> to
> > clamp the
> > flyback voltage? What is the magnitude of the flyback
voltage?
> > I have collected at least ten speed servos from junk yards.
Can
> you test
> > them f
> > or function?
>
> > Steve Reimers building 5 3C043
> > AVT Chassis E/E System Applications mail drop 5011
> > 39-03286 SREIMERS sreimers@ford.com fax 39-03286 ;>

Attachments sent separately:

Data Type	File Name
BINARY	CL_B2R44.PDF_PC

Schrody, Thomas (T.P.)

From: Porter, David (D.L.)
Sent: Friday, February 19, 1999 2:50 PM
To: Fred Kohl (E-mail)
Cc: Tom Schrody (E-mail)
Subject: Vehicle Teardown Data

Here is revised matrix with data on clutch flyback circuit added.

Yeh matcha.doc

Schrody, Thomas (T.P.)

From: Steve Reimers [SREIMERS.DRBH007@ovm.gw.ford.com]
Sent: Friday, February 19, 1999 7:38 AM
To: JHEMC.DP@omc008@ovm.gw.ford.com; elerouch@mail.ford.com; FPORTERL.DRBH007
@ovm.gw.ford.com; FRENGLIS1.DRBH005@ovm.gw.ford.com; SSALTERL.DRBH006
@ovm.gw.ford.com; NIAPONT.DRBH005@ovm.gw.ford.com; TMASTERB.DRBH006
@ovm.gw.ford.com; JKAFATL.DRBH004@ovm.gw.ford.com; SREIMERS.DRBH007
@ovm.gw.ford.com; tschrody@viscon.com; FKOHIL.DRBH007@ovm.gw.ford.com;
TBAZIL.DRBH008@ovm.gw.ford.com; JMCINERIN.DRBH008@ovm.gw.ford.com;
davidzyn@viscon.com; petokes@viscon.com; DGCEL.DRBH005@ovm.gw.ford.com;
LBROWNL.DRBH005@ovm.gw.ford.com; SCOLE1.DRBH005@ovm.gw.ford.com;
HWELPERL.DRBH005@ovm.gw.ford.com; GSTEVEN1.DRBH005@ovm.gw.ford.com;
WABRAMC2.DRBH005@ovm.gw.ford.com; MREESEL.DRBH005@ovm.gw.ford.com;
ashman@email.mci.ti.com; rsharpe@email.mci.ti.com
Subject: DOW Rep Meeting

02-12-99.vcs

Requester: Steve Reimers
Date to be scheduled: 02/23/00

Starting time: 09:00 AM
Ending time: 11:00 AM
Recurrence: Single event

Location: bldg 5 3A017

Subject: DOW Rep Meeting

Purpose: Discuss with DOW the brake pressure switch.
Attend Only if interested in materials questions?

Recurrence: Single event

Schrody, Thomas (T.P.)

From: Fred Kohl (fkohl@gw.ford.com)
Sent: Friday, February 19, 1999 10:40 AM
To: dporter1@visteon.com; tschrody@visteon.com
Cc: dbudzyns@visteon.com; fkohl@gw.ford.com
Subject: Speed control clutches

Can you get parts for TI testing of the brake pressure switch?
Five clutches

Regards, Fred Kohl, Precision Speed Control (Panther)
PROFS ID: FKOHL Phone TBD Pager (866) 377-8280
IBM Mail(USFMCBJZ)
Mailing Address: ETC C375
*** Forwarding note from SREIMERS-DRBN007 02/18/99 17:38 ***
To: FKOHL -DRBN007

FROM: Steve Reimers USAET(UTC -06:00)
Subject: Speed control clutches
I need 5 clutches to send to TI so they have the correct load for there testing.
Of course I really needed them yesterday.

Steve Reimers building 5 3C049
AVT Chassis E/E System Applications mail drop 5011
39-03286 SREIMERS sreimers@ford.com fax 39-03286 >

Schrody, Thomas (T.P.)

From: Fred Kohl (fkohl@gw.ford.com)
Sent: Friday, February 19, 1999 10:38 AM
To: dporter1@visteon.com; tschrody@visteon.com
Cc: dbudzyns@visteon.com; fkohl@gw.ford.com
Subject: Speed control report

Info needed in report for Brake Pressure Investigation.

Regards, Fred Kohl, Precision Speed Control (Panther)
PROFS ID: FKOHL Phone TBD Pager (866) 377-8280
IBM Mail(USFMCBJZ)
Mailing Address: ETC C375
*** Forwarding note from SREIMERS-DRBN007 02/18/99 17:48 ***
To: FKOHL -DRBN007

FROM: Steve Reimers USAET(UTC -06:00)
Subject: Speed control report
Please include the functional status of the fly-back circuit in the report of t

he feel returned units. ALSO...any FRACAS activity to report?

Steve Reimers building 5 3C043
AVT Chassis E/E System Applications mail drop 5011
39-03286 SREIMERS reimers@ford.com fax 39-03286

Schrody, Thomas (T.P.)

From: Steve Reimers [sreimers@gw.ford.com]
Bcc: Thursday, February 18, 1999 5:46 PM
To: wboyer1@visi.com
Cc: fkoehl@gw.ford.com; technodr@visi.com
Subject: RE: Speed control servo

Please re-run this model with the following condition: No Fly-back and FET always on and use the Brake Pressure switch to create the switching transient. What is the voltage at the brake pressure switch?

Steve Reimers building 5 3C043
AVT Chassis E/E System Applications mail drop 5011
39-03286 BREIMERS sreimers@ford.com fax 39-03286 ;>
-- Working notes from WBOYER1 --VISTEON 02/17/00 10:58 ---
To: DPORTER1--VISTEON; Power, David (DL BREIMERS--FORDMAIL); Reimers, Steve (S.
cc: KOHL, --FORDMAIL; Kohl, Fred (F.H.) TSCHRODY--VISTEON; Schrody, Thomas (T
DBUDZYMIS--VISTEON; Budzynski, Dan (D.

From: Boyer, Wm (W.D.)
Subject: RE: Speed control servo

Attached is an analysis of the idealized flyback pulse of the turn-off transient on the clutch winding:

Regards,
Wes (W. D.) Boyer Phone: (313) 248-9417
Visteon Automotive Systems Fax: (313) 322-3629
Precision Speed Control - Electronic Design E-mail: WBoyer1@visteon.com
(Usually at work, Wednesday + Thursday, only; Personal e-mail:
w.d.boyer@msn.com)

2—Original Message—

> Original Message
> From: Porter, David (D.L.)
> Sent: Wednesday, February 17, 1999 10:29 AM
> To: Steve Reimers
> Cc: Fred Kohl (E-mail); Tom Schroyd (E-mail); Wes Boyer (E-mail)
> Subject: RE: Speed control servo
>

- > Steve, the inductance of the clutch was at one time called out as 53-112
- > MH. This is measured at 1 KHz and in parallel.

> -----Original Message-----
> From: Steve Palmers (SMTP:salmers@gw.ford.com)
> Sent: Wednesday, February 17, 1999 9:53 AM
> To: dporter1@visteon.com; fkohl@gw.ford.com
> Subject: PW: Speed control serve
>
> Fred Kohn will bring the parts to Visteon. These were retrieved
> from junkyards
> as part of a scrapping process related to Brake Pressure switch

> function. The
> Brake Pressure switch ES spec defines 300 mill-Henry as the minimum
> test induc-
> tance for life testing. Is this a good number? Can you measure the
> inductance
> to establish a minimum and maximum?
>
> Steve Reimers building 5 3C043
> AVT Chassis E/E System Applications mail drop 5011
> 39-03286 BREIMERS sreimers@ford.com fax 39-03286 ;>
> *** Forwarding note from DPORTER1--VISTEON 02/17/99 08:18 ***
> To: BREIMERS--FORDMAIL Reimers, Steve (S.
> cc: FKohl --FORDMAIL Fred Kohl (E-mail) WBOYER1 --VISTEON Wes
> Boyer (E-mail)
>
> From: Porter, David (D.L.)
> Subject: FW: Speed control servo
>
> Steve, the clutch resistance should be in the neighborhood of 24
> Ohms. If
> the clutch winding is intact, and nothing is mechanically damaged,
> etc. I
> would assume the parts are functional. There is no specified
> inductance on
> the clutch, because it varies with gear position (open or closed).
> If it
> is important to check functionality of these parts, bring them to
> our lab,
> and I can bench test them for you. Are these parts off vehicles, or
> just
> unused parts that have been lying in a corner for a few years? You
> did not
> mention motor phase inductance or resistance. Generally, the motors
> are OK
> If they rotate freely, and the three phases all have a resistance of
> about
> 2.5 Ohms.
>
> Dave Porter dporter1@visteon.net Phone: 313-322-3574
> Fax:
> 313-322-3529
>
> > -----Original Message-----
> > From: Boyer, Wes (W.D.)
> > Sent: Wednesday, February 17, 1999 8:05 AM
> > To: Porter, David (D.L.)
> > Subject: FW: Speed control servo
>
>
> > I.y.l.
> > Regards,
> > Wes (W. D.) Boyer Phone: (313)
> 248-9417
> > Visteon Automotive Systems Fax: (313)
> 322-3529
> > Precision Speed Control - Electronic Design E-mail:
> WBoyer1@visteon.com
> > (Usually at work, Wednesday + Thursday, only; Personal e-mail:
> > w.d.boyer@leas.org)
>
> > -----Original Message-----
> > From: Fred Kohl [SMTP:fkohl@gw.ford.com]
> > Sent: Tuesday, February 16, 1999 3:48 PM
> > To: wboyer1@visteon.com; techrody@visteon.com

> > Subject: RE: Speed control servo
>
> > fyl
>
> Regards,___ Fred Kohl, Precision Speed Control (Panther)
> PROFS ID: FKOHLL Phone TBD Pager (866) 377-6280
> IBM Mail(USPMCSJZ)
> Mailing Address: ETC C375
> *** Forwarding note from SREIMERS--DRBN007 02/16/99 12:38 ***
> To: FKOHLL --DRBN007
>
> FROM: Steve Reimers USAET(UTC -05:00)
> Subject: RE: Speed control servo
> These are from MY92 and 93. No known failures. Just want to know
> if
> there
> clutch control function has degraded.
>
> Steve Reimers building 5 3C043
> AVT Chassis/E/E System Applications mail drop 5011
> 39-03288 SREIMERS erimers@ford.com fax 39-03288 >
> *** Forwarding note from FKOHLL --FORDMAIL 02/16/99 10:33 ***
> To: TSCHRODY-VISTEON Schrödy, Thomas (T
> cc: DBUDZYNE-VISTEON Budzynski, Dan (D. FKOHLL --FORDMAIL Kohl,
> Fred
> (F.H.)
> SREIMERS-FORDMAIL Reimers, Steve (S.
>
> From: Boyer, Wes (W.D.)
> Subject: RE: Speed control servo
>
> I'll send a copy of the complete clutch-dump analysis when I get
in on
> Wednesday.
>
> What model year clutches are we talking about? And, Why from the
> "junkyard?"
>
> Wes
> w.d.boyer@isca.org
> ---Original Message---
> From: Schrödy, Thomas (T.P.)
> To: Boyer, Wes (W.D.)
> Sent: 2/16/99 10:19 AM
> Subject: FW: Speed control servo
>
> Wes,
>
> I don't think you're in today, but if you are... Could you respond
to
> Steve Reimers? I'm busy at NPEF and will return tomorrow.
>
> ---Original Message---
> From: Fred Kohl
> To: tschrody@visteon.com
> Cc: dbudzyn@visteon.com; fkohl@gw.ford.com; erimers@gw.ford.com
> Sent: 2/16/99 7:59 AM
> Subject: Speed control servo
>
> Can you answer Steve questions?
>
> Regards,___ Fred Kohl, Precision Speed Control (Panther)
> PROFS ID: FKOHLL Phone TBD Pager (866) 377-6280
> IBM Mail(USPMCSJZ)

> > Mailing Address: ETC C375
> > *** Forwarding note from SREIMERS-DRBN007 02/15/98 18:14 ***
> > To: FKOHL -DRBN007
>
> > FROM: Steve Reimers USAET(UTC -05:00)
> > Subject: Speed control servo
> > What is the inductance and resistance of the clutch? What is used
> to
> > clamp the
> > flyback voltage? What is the magnitude of the flyback voltage?
> > I have collected at least ten speed servos from junk yards. Can
> you test
> them?
> or function?
>
> > Steve Reimers building 5 3C043
> > AVT Chassis E/E System Applications mail drop 6011
> > 39-03286 SREIMERS sreimers@ford.com fax 39-03286 ;>

Attachments sent separately:

Data Type	File Name
BINARY	CL_B2R44.PDF,_PC

Schrody, Thomas (T.P.)

From: Boyer, Wes (W.O.)
Sent: Wednesday, February 17, 1998 10:57 AM
To: Porter, David (D.L.); Reimers, Steve (S.J.)
Cc: Kohl, Fred (F.H.); Schrody, Thomas (T.P.); Budzynski, Dan (D.J.)
Subject: RE: Speed control servo

Attached is an analysis of the idealized flyback pulse of the turn-off transient on the clutch winding:

cl_b2r44.pdf

Regards,
Wes (W.D.) Boyer Phone: (313) 248-9417
Visteon Automotive Systems Fax: (313) 322-3529
Precision Speed Control - Electronic Design E-mail: WBoyer1@visteon.com
(Usually at work, Wednesday + Thursday, only; Personal e-mail: w.d.boyer@usa.org)

—Original Message—

From: Porter, David (D.L.)
Sent: Wednesday, February 17, 1998 10:39 AM
To: Steve Reimers
Cc: Fred Kohl (E-mail); Tom Schrody (E-mail); Wes Boyer (E-mail)
Subject: RE: Speed control servo

Steve, the inductance of the clutch was at one time called out as 63-112 MH. This is measured at 1 KHz and in parallel.

Dave Porter dporter1@visteon.com Phone: 313-360-8674 Fax 313-322-3529

—Original Message—

From: Steve Reimers [SMTP:sreimers@gw.ford.com]
Sent: Wednesday, February 17, 1998 9:53 AM
To: dporter1@visteon.com; fcoh@gw.ford.com
Subject: FW: Speed control servo

Fred Kohl will bring the parts to Visteon. These were retrieved from junkyards as part of a sampling process related to Brake Pressure switch function. The Brake Pressure switch ES spec defines 300 milli-Henry as the minimum test inductance for the testing. Is this a good number? Can you measure the inductance to establish a minimum and maximum?

Steve Reimers building 5 3C043
AVT Chassis E/E System Applications mail drop 5011
39-03286 SREIMERS sreimers@ford.com fax 39-03286 >
*** Forwarding note from DPORTER1-VISTEON 02/17/99 08:16 ***
To: SREIMERS-FORDMAIL Reimers, Steve (S.
cc: FKOH1 -FORDMAIL Fred Kohl (E-mail) WBOYER1 -VISTEON Wes Boyer (E-mail)

From: Porter, David (D.L.)
Subject: FW: Speed control servo

Steve, the clutch resistance should be in the neighborhood of 24 Ohms. If the clutch winding is intact, and nothing is mechanically damaged, etc. I would assume the parts are functional. There is no specified inductance on the clutch, because it varies with gear position (open or closed). It is important to check functionality of these parts, bring them to our lab, and I can bench test them for you. Are these parts off vehicles, or just unused parts that have been lying in a corner for a few years? You did not mention motor phase inductance or resistance. Generally, the motors are OK if they rotate freely, and the three phases all have a resistance of about 2.5 Ohms.

Dave Porter dporter1@Viasatnet.com Phone: 313-390-6674 Fax:

> -----Original Message-----
> From: Boyer, Wes (W.D.)
> Sent: Wednesday, February 17, 1999 8:05 AM
> To: Porter, David (D.L.)
> Subject: FW: Speed control servo
>
>
> f.y.i.
> Regards,
> Wes (W. D.) Boyer Phone: (313) 248-9417
> Visteon Automotive Systems Fax: (313) 322-3529
> Precision Speed Control - Electronic Design E-mail: WBoyer1@visteon.com
> (Usually at work, Wednesday + Thursday, only. Personal e-mail:
> w.d.boyer@juno.com)

> -----Original Message-----
> From: Fred Kohl [SMTP:kohlN@gw.ford.com]
> Sent: Tuesday, February 16, 1999 3:48 PM
> To: wboyer1@visiocon.com; tachrody@visiocon.com
> Subject: RE: Board control servo

> Regards, Fred Kohl, Precision Speed Control (Panther)
> PROFS ID: FKOHL Phone TBD Pager (800) 377-6260
> IBM Mail(USFMCSJXZ)
> Mailing Address: ETC C376
> *** Forwarding note from SPREMMERS-DRBN007 02/16/99 12:31
> To: FKOHL -DRBN007
>
> FROM: Steve Reimers USAET(UTC -05:00)
> Subject: RE: Speed control servo
> These are from MY92 and 93. No known failures. Just went to
> them

> clutch control function has degraded.
>
> Steve Reimers building 5 3C043
> AVT Chassis E/E System Applications mail drop 5011
> 39-03286 SREIMERS sreimers@ford.com fax 39-03286 >
> *** Forwarding note from FKOHL --FORDMAIL 02/16/99 10:33 ***
> To: TSCHRODY--VISTEON Schrödy, Thomas (T
> cc: DBUDZYNS--VISTEON Budzynski, Dan (D. FKOHL --FORDMAIL Kohl, Fred
> (F.H.)
> SREIMERS--FORDMAIL Reimers, Steve (S.
>
> From: Boyer, Wes (W.D.)
> Subject: RE: Speed control servo
>
> I'll send a copy of the complete clutch-dump analysis when I get in on
> Wednesday.
>
> What model year clutches are we talking about? And, Why from the
> "junkyard?"
>
> Wes
> w.d.boyer@leee.org
> -----Original Message-----
> From: Schrödy, Thomas (T.P.)
> To: Boyer, Wes (W.D.)
> Sent: 2/16/99 10:13 AM
> Subject: FW: Speed control servo
>
> Wes,
>
> I don't think you're in today, but if you are... Could you respond to
> Steve Reimers? I'm busy at NPEF and will return tomorrow.
>
> -----Original Message-----
> From: Fred Kohl
> To: tschrody@visteon.com
> Cc: dbudzyns@visteon.com; fkohl@gw.ford.com; sreimers@gw.ford.com
> Sent: 2/16/99 7:58 AM
> Subject: Speed control servo
>
> Can you answer Steve questions?
>
> Regards, ... Fred Kohl, Precision Speed Control (Panther)
> PROFS ID: FKOHL Phone TSD Pager (800) 377-8220
> IBM Mail(USPMCGJZ)
> Mailing Address: ETC C375
> *** Forwarding note from SREIMERS--DRBN007 02/16/99 18:14 ***
> To: FKOHL --DRBN007
>
> FROM: Steve Reimers USAET(UTC -06:00)
> Subject: Speed control servo
> What is the inductance and resistance of the clutch? What is used to
> clamp the
> flyback voltage? What is the magnitude of the flyback voltage?
> I have collected at least ten speed servos from junk yards. Can you test
> them f
> or function?
>
> Steve Reimers building 5 3C043
> AVT Chassis E/E System Applications mail drop 5011
> 39-03286 SREIMERS sreimers@ford.com fax 39-03286 >

Schrody, Thomas (T.P.)

From: Fred Kohl (fkohl@gw.ford.com)
Sent: Wednesday, February 17, 1999 9:56 AM
To: dporter1@visteon.com
Cc: fkohl@gw.ford.com; dbudzyns@visteon.com; techrody@visteon.com; wboyer1@visteon.com;
sreimers@gw.ford.com
Subject: FW: Speed control servo

I will pick up the 10 servos from Steve Reimers late today (2/17). I will put them on your desk for analysis. Steve needs your analysis by vehicle number. Each servo is in a bag with vehicle ID.

If I get a chance I will put the vehicle number on the part...

Regards, Fred Kohl, Precision Speed Control (Panther)
PROFS ID: FKOHL Phone TBD Pager (868) 377-6260
IBM Mail(USFMCBLZ)
Mailing Address: ETC C375
*** Forwarding note from DPORTER1-VISTEON 02/17/99 08:18 ***
To: SREIMERS-FORDMAIL Reimers, Steve (S.
cc: FKOHL --FORDMAIL Fred Kohl (E-mail) WBOYER1 --VISTEON Wes Boyer (E-mail)

From: Porter, David (D.L.)
Subject: FW: Speed control servo

Steve, the clutch resistance should be in the neighborhood of 24 Ohms. If the clutch winding is intact, and nothing is mechanically damaged, etc. I would assume the parts are functional. There is no specified inductance on the clutch, because it varies with gear position (open or closed). If it is important to check functionality of these parts, bring them to our lab, and I can bench test them for you. Are these parts off vehicles, or just unused parts that have been lying in a corner for a few years? You did not mention motor phase inductance or resistance. Generally, the motors are OK if they rotate freely, and the three phases all have a resistance of about 2.5 Ohms.

Dave Porter dporter1@Visteon.net.com Phone: 313-390-6674 Fax:
313-322-3529

> -----Original Message-----
> From: Boyer, Wes (W.D.)
> Sent: Wednesday, February 17, 1999 8:05 AM
> To: Porter, David (D.L.)
> Subject: FW: Speed control servo
>
>
> f.y.i.
> Regards,
> Wes (W. D.) Boyer Phone: (313) 248-9417
> Visteon Automotive Systems Fax: (313) 322-3529
> Precision Speed Control - Electronic Design E-mail: WBoyer1@visteon.com
> (Usually at work, Wednesday + Thursday, only; Personal e-mail:
> w.d.boyer@iesee.org)
>
> -----Original Message-----
> From: Fred Kohl [SMTP:fkohl@gw.ford.com]
> Sent: Tuesday, February 16, 1999 3:46 PM
> To: wboyer1@visteon.com; techrody@visteon.com

> Subject: RE: Speed control servo
>
> fyi
>
> Regards,___ Fred Kohl, Precision Speed Control (Panther)
> PROFS ID: FKOHL Phone TBD Pager (800) 377-6280
> IBM Mail(USFMCBJZ)
> Mailing Address: ETC C375
> *** Forwarding note from SREIMERS--DRBN007 02/16/99 12:38 ***
> To: FKOHL --DRBN007
>
> FROM: Steve Reimers USAET(UTC -06:00)
> Subject: RE: Speed control servo
> These are from MY92 and 93. No known failures. Just want to know if
> there
> clutch control function has degraded.
>
> Steve Reimers building 6 3C043
> AVT Chassis E/E System Applications mail drop 6011
> 39-03288 BREIMERS sreimers@ford.com fax 39-03288 >
> *** Forwarding note from FKOHL --FORDMAIL 02/16/99 10:33 ***
> To: TSCHRODY-VISTEON Schrody, Thomas (T.
> cc: DBUDZYNS-VISTEON Budzynski, Dan (D. FKOHL --FORDMAIL Kohl, Fred
> (F.H.)
> SREIMERS--FORDMAIL Reimers, Steve (S.
>
> From: Boyer, Wes (W.D.)
> Subject: RE: Speed control servo
>
> I'll send a copy of the complete clutch-dump analysis when I get in on
> Wednesday.
>
> What model year clutches are we talking about? And, Why from the
> 'junkyard'?
>
> Wes
> w.d.boyer@leee.org
> -----Original Message-----
> From: Schrody, Thomas (T.P.)
> To: Boyer, Wes (W.D.)
> Sent: 2/16/99 10:13 AM
> Subject: FW: Speed control servo
>
> Wes,
>
> I don't think you're in today, but if you are... Could you respond to
> Steve Reimers? I'm busy at NPEF and will return tomorrow.
>
> -----Original Message-----
> From: Fred Kohl
> To: tschrody@visteon.com
> Cc: dbudzyns@visteon.com; fkohl@gw.ford.com; sreimers@gw.ford.com
> Sent: 2/16/99 7:59 AM
> Subject: Speed control servo
>
> Can you answer Steve questions?
>
> Regards,___ Fred Kohl, Precision Speed Control (Panther)
> PROFS ID: FKOHL Phone TBD Pager (800) 377-6280
> IBM Mail(USFMCBJZ)
> Mailing Address: ETC C375
> *** Forwarding note from SREIMERS--DRBN007 02/16/99 10:14 ***
> To: FKOHL --DRBN007
>

> FROM: Steve Reimers USAET(UTC -05:00)
> Subject: Speed control servo
> What is the inductance and resistance of the clutch? What is used to
> clamp the
> flyback voltage? What is the magnitude of the flyback voltage?
> I have collected at least ten speed servos from junk yards. Can you test
> them f
> or function?
>
> Steve Reimers building 5 3C043
> AVT Chassis E/E System Applications mail drop 5011
> 39-03286 SREIMERS sreimers@ford.com fax 39-03286 >

Part 2

MIME-version: 1.0
Content-Type: application/ma-tnef
Content-Transfer-Encoding: base64

b3J+IJANAGcCCAAEAAAAAABAAEAQgIAAAAABQAQAAAAAAAdoAAEigAcAGAAAAEIQTSSN-WNy
b3jNvZnCqgTWPbCSb3RIADEIAQWAwAOAAAACcSEACAAAC4AAwAzAOEIAAUABAAAAAAA
AAEJAACAAcAAAAAAAABIADAA4AAADPwIAEQIABEALQADADIB4QmIAQAHAAAOCJPNOMMUMz
NEM2RDIxMTHEmIewMEMwNEY4CjEwOUIAKwcbBIABBqAAABGVzogJ3B2WQqY29udH.MbCBzXj2
bwBYCAEnpAQAAgAAAAAaApBA5AGAAwOAAAACwACAAEAAAADAC4AAAAAAEAQODwC82od1q+
AQMAXUAAAAAAhBwAAAEEAAAUAAl3BzWQqY29udH.bnBzXj2wACAXEAQAAACA AAAABvint
smoTGxKdxAR0orHAKD.JnDOPACHpYAAZJIAwAPwAAAAl3BzWQqY29udH.bnBzXj2wACAXEAQAAACA AAAABvint
AAAAAwAeQAAAAAeADSAQAAAAl3BzWQqY29udH.bnBzXj2wACAXEAQAAACA AAAABvint
AABDEwAATFpGdFRWk1o8DAa0ActInWzEwNdyAPzsnNgIAKRA+LJAgBjwA+w2vIMD4gbMCzwBQ
AvQuVRN-HmgDoQKDDIAQVnBycUoyEVzgEE8gVg8QZNwAcBnIwNAPGEWVwBcIyGwgDwDIA1GSo
ID/CkQZkayCokbMRwG8EYQH0MIGMAUAIADYwBzCwBzUo4QMDMVUHVlsbgjgBmUgYdgV2ZsxA
HPo2B8JCh20LJDcB1QAJBzAZBwY4Ch4MHTMC4QZC8wZBHC4AhyYBQwDwBwByAwdwBwBHAy2Yg
MOAIEkRkXMuR5tnJMAheOPwbtmCl.jgqjYQcEwAUAZBjgCFOAHAIJLw4MCFwJpJhgBDRAwBjB0DY
bhkgFrAawGcJpCFQXR EgYyVRJkA8EEEHV3B4AHYwxdaxAcgCsAMg32ydsKQd3rcIAdA/JVBUsyGA
KaEm0BwIwBwBZAGlP8MwCMgJmEeeCJOAlAhwSFQwYNAKOB1ERAJYAVAdprAbwQ8CAD8CFwICmA
CsPw6m8AkOwyICgkhoC2AA8DyBbEhxDGALsEpJwMwMsB83m0xAcAgAHAFQH0IwBQwCwQwQwypMDA
IC8xIXEwAdswUy+FBRAmoSFzbTRICGH8IAsgYidkKAo4AOxwBwIwAACEQImA3NAQ8cB5/whg
JVAHECrzNKYko5TAITDlJwAhsAeQIVAFwWovsAVAzynALwGICUIXBwBUAC4H8wMCwMwpeEAMA
JrEDoGG/laAfEcBQ8cA58JwZgJFwntoxDMXwIFkIYClwImnoyhtIAJxwrgjNHAxJb8Q40ACLUF
wCjoJVSHCfCfBJAc8FUQhMhIE8LJ2DJY1MplAn9ZAhIEvglCdfE4vBngIfpJXAJQJUJhK8pAd3o
Pz8wtkdQGpCGAFQDwIwJUJ8UwAcqjwAqz8HytTwepdEO+EAJEDSC12hZC8w4w0uBt0zKME
kCpxQFYIUWUqQXQUNwWgnSSbJqFATMC200IAAmzEzLTM5wC0YODY3JPB0qj2hewIRJDIwUwACQDIM
GhOzyDIE2s72GwQwCQBLA1wWJtJwUQ2wAB0AF0A+wCz3pcVVJwBQwzEPVQCAgwnwLT0wNAFAN2BZ
AwzQrVxDY1hwA2E80IN1wEBUQmDwAYThJUFchksjVw5EJLJlwowmDxw/Bw1uQZC8QwamPH0
RmlU24HKwCkgTrmANUQzCw8wDg3meQ5EPN0KedJb1qzT2QhUGhNQUEh1KPhATPwQXeh1TGJqVSFa
kIZXURBTy2AlaEPwAhuA2AD0B80mz2b1qPWEo4Qwz38m4C55Lmtw87VOavBwJwUmVnCxE2
wEuW5VwTTBwEvDwIw8FC284Ach1ExxCAM4DgjOTROYLD1E/FEVwQGANwJ88pPIH/BwBP4Bw
bG1SCW2CTwJbwP18zFAdJUC2pAjAuwWQwCPDw2L0NEwE8CjAA2AwzZNMClzBwQbPJFLCIDA+wMq
bYFXWwNPoGHAT+HQUyVpbaMwPUpjCjzPwEwQHwxyFQIAFdmCAF84AhywCHBd5AigKRAAdMGzz
BJAOeywBk82sDxwzCw8w65QwIAwAqJwz29UE4C88wRC1Vwv/nw71m1nwY4yduSSBb2gD
IAbbyJ01ULDpmw3tmGwJwBwAsBwX3qJGfJw1sPwHwNUC1Bjz2BTPwCm4w/TYB31rk34d1wOyFg
BPPBQARwzXdwYwJw/F3RNwQZB+C7pxQAcHPHzwExQPrwC28ZmwQcjs8m4z2D4Yw/VSOnXNykaUc
KFA0M8zBYTVQwkw8RqXw-GURRIE2L.TxwTFCwewBCRIwJUJz2XEPwCp4nhwBywTcaJc02G0Bn1UIC
TQXOAswPwNBTRk1DGkzQWmJwVw4mtwzZC1horNqUVUQw0wQw55gwVLCqj0FwBw83CwEwJpw
wJcsUHFTkTBjTQwPwQAcErB0kdeMdB0wTayL1RQwNtQ04gOKQwLkLRs7RgcwipwSts7pgMyBN
kVEhEr9qQdxFeGqX08hN88BwDbeNCh831MF+AMGJyVY/k3+8OyywMAEw8Q1TvvwDwPQwJ45
M0bxT1QwmgHHDcGZ2kQhws8D643FKPKK1QDpewJGwP1Qw0hBwupw2PwEEIAEAc8+YQEA
feBLwqmpwPwQwHwtdQMOJwJNLEPEwQzA4wVQwBwVwBwHwz2PAwRxAwEBwC1Ac0wvBwMw1
dolpMANocEwANwvMwT7TCwzPwKwJwBwPwvkwVwzJwz1QwHwA16Z0p4w+MFJwzZDjwzvOn+HAGn
WEZPUkPwNQKw7mCjwDCwCHwPwJwUyRDwJwqgRfwmAcFZjwFNUwJwB0s4BTjwBwVwAaAnw7FUwV
URCAREJwPwKw2TqTRjckwQmVwkvwzJwz2wv+eWQwCmlePwAmwWPwpxGx1YwzCwHgLiJwzBwCwG3Gw+e4V8FQ
wQwU7wvBwHw+eDw4wvQm0wvSPwEREPwkwTbwCwXGPwE24DwCwHwBwBwQwLJwz4CwBwBwvQwB
/mchAGoqKIAwDwBwEwLkPwtrV3PwtxPwIwYwMwQwLJwz1wV0wBwymBwDwEcwBwQwTQwLJwz2w
w3FwCwPwJwEwJwBwGwvQwPw+/wvwszJwz2wAH4Ew04wvQwUwBwPwz1wVwBwz4TQwz1wA

QF+31Zd5/9c/32aCaqWa5SkwAIArOYILgPs04DoxJyzj4EEoF4S4oDvM4EkwDoxK8lu9DB0USMC
//PCHExoEfCkpW3++FR2GALN3C&g/HN5Q08QPUtvJ3MD8EkrHVB0CHDwgRphIDYOSQS7mH+cv
0+KGN9emul5vd/dDy0FkuoDMw3+Njlcfk08F4zZ849QTe80/VNUO0v7n/XEM4wd/zwn3A4FAK
0L0cYnBvdP/4zu/W3B4mP+d5efnC+dP/+eT89fo3+hfBOx5+k6Ww7W419wh8Cm168PqJ-4
H/8az6vPrh8GP5Jc3oO8g8WI/4ZJ4JuC744VEJ0D9ZZdLzBh2wEu8dAVZkdWYv2HNNGBgGxa
e8HgJuFT/8R0HVw+NC2oNlmKW7x8J4D/z9QPNBVIT0h9e815EKQNFH/MMH1MCJCdNI4Bgz4rJ
IP9qYvRRFCU5UuAUOuTQFD/P/7XW4zsdrxXuh+7L7wvU+v+o85/wY/CnBAuNuOAgB8IAAL
AAOACCAGAAAAAADAAAAAAAARgAAAAADhQAAAAAAAABYAIAYAAAAAMAAAAAAAABGAAAAABC
AAAAAAAAnAqAgpBgAAAAAAwAAAAAAAEYAAAAAUoUAABUSAAGAACGACAGAAAAADAAAAAAA
RgAAAABUhQAAAQAAAUAUAAA4QazAAAAAMAAoiAYAAAAAMAAAAAAAABQAAAAAGFAAAAAAA
CwAEgAgpBgAAAAAAwAAAAAAAEYAAAAAdoUAAAAAAAADAACCAGAAAAADAAAAAAAARgAAAAAR
HQAAAAAAAAB4AIIAYAAAAAMAAAAAAAABGAAAAABfAAAAAAAAbgAgpBgAAAAAAwAAAAAAA
AEYAAAAAAAnUAAAABAAAAB4ACYAnAYAAAAAMAAAAAAAABGAAAAADeFAAAABAAAAAQAA
AAAAAAAAnAqACCAGAAAAADAAAAAAAAPgAAAA4HQAQAAAEEAAAAAAAAnOePwIEAAAADAPo
5AGAAAAMAgAAAAAAwA2AAAAAAADAIQ///wIBPwABAAAAAAAAGM//VM7YT0gO3ABZm8yZDt
PVZJU1RFWDAtL7icMDIxXnzEzMTc0Nl0iMTiENDk4AB4AOEABAAAQCQAAERQT1JURV1xAAAAB4A
OUABAAAACQAAAERQT1JURV1xAAAAB4ABzAbk2zd1q+AUAAACDdcX+mtd1q+AP4APoABAABOAA
AEZXOIAAAAAAHgAdDgEAAAAUAAAUSBIZWQgY29udHJvbCBzZ6J2bwAeADUGAcQAAAEEYAAAAM0C4
MDk1NjkwMDg0RDlxmtk4PK0wMEEwQzDQ0VGMRAmMUZEQgyMUBmbWmboEDm8kZWFyYmByb6m
b3JkLmNvbT4AAAALACKAAAAAAwA4wAAAAAAwA4GE00wIYEDAcQYAAAAAABEAAAAMAEBAAAAAAAwA4EAE
AAAABgQAcQAAAAGUAAAABTVEVWRSxUSEVDTFVUQ0h6RVNUJU1RBThnfNU0nPVLxEGKVJTRIRU6F8Ud
Qk888EPTE9GM|RPSE1TSUZUSEVDTFVUQ0h6RVNUJU1RBThnfNU0nPVLxEGKVJTRIRU6F8Ud
AAAAAAIBwABAAAARgAADwzFDgwOTU2OTAwODREMEExOThGRDAwQTBDOUNDRUYyMzAxRkRCODtx
QGZYy2BuMTQyLmRYXJb3JLmZycmQuY2RPgAAAFPG

Schrody, Thomas (T.P.)

From: Fred.Kohl [mailto:fkohl@gw.ford.com]
Sent: Monday, February 15, 1999 9:29 AM
To: tschrody@visatcom.com
Cc: fkohl@gw.ford.com
Subject: RE: More Questions

Tom, I told Steve that the customer would not know if an internal driver for the clutch output was stuck on. The BOO signal would cause the motor to be driven back to idle. Also, the brake pressure switch when activated would open the feed to the clutch circuit.

I told him that there is NO warning light for faults.

Another question Steve had: does the speed control module check to see if the driver circuit for the clutch is turned on when it should not be. Does it set an internal code or make the system inop?

Steve mentioned that ABS units check the output state and sets codes if there are faults detected.

Regards,___ Fred.Kohl, Precision Speed Control (Panther)
PROFS ID: FKOHL Phone TBD Pager (800) 377-6280
IBM Mail(USPMCBJZ)
Mailing Address: ETC C375
*** Forwarding note from SREIMERS-DRBN007 02/15/99 08:57 ***
To: FKOHL --DRBN007

*** Reply to note of 02/15/99 08:21
FROM: Steve Reimers USAET(UTC -05:00)
Subject: RE: More Questions
If the clutch output driver gets stuck "ON" would the customer be aware of it?
Would the speed control detect this fault? ...light a warning lamp? ...log a fault code? Any action on FRACAS?

Steve Reimers building 5 3C043

AVT Chassis E/E System Applications mail drop 5011
39-03288 SREIMERS sreimers@ford.com fax 39-03288 >

Schrody, Thomas (T.P.)

From: Fred Kohl (fkohl@gw.ford.com)
Sent: Monday, February 15, 1999 8:13 AM
To: sreimers@gw.ford.com
Cc: dbudzyna@visteon.com; tschrody@visteon.com; fkohl@gw.ford.com
Subject: Alternate Deac Switch

Yes, the pedal mounted switch currently used is compatible electrically with the 92 and 93 Town Car.

I do not know if mounting in the vehicle and wiring harness requirements can easily be met. Chassis would have to answer the mounting / packaging questions and EEE would have to address the wiring harness issues.

The current Town Car deact switch engineer is Mike Salanta (MBALANTA) 84-54007. .

Regards, Fred Kohl, Precision Speed Control (Panther)
PROPS ID: FKOHL Phone TBD Pager (888) 377-6280
IBM Mail(USFMCBJZ)
Mailing Address: ETC C375
*** Forwarding note from SREIMERS--DRBN007 02/13/99 10:43 ***
To: FKOHL --DRBN007

FROM: Steve Reimers USAET(UTC -06:00)
Subject: Alternate Deac Switch
Is the brake pedal mounted switch a viable replacement for the Pressure switch as far as the speed control electronics is concerned? Is this switch input compatible with the speed controls in 92 and 93 Town cars?

Steve Reimers building 5 3C043
AVT Chassis E/E System Applications mail drop 5011
39-03288 SREIMERS sreimers@ford.com fax 39-03288 >

Schrody, Thomas (T.P.)

From: Fred Kohl (fkohl@gw.ford.com)
Sent: Friday, February 12, 1999 3:39 PM
To: tschrody@visteon.com
Cc: fkohl@gw.ford.com
Subject: More Questions

Answers to the questions:

Do not understand first question as stated. If he means brake pressure switch stuck closed all of the time, customer would not know as long as there not any other failures.

A relay between the fuse and the switch is OK.

Tom, need your help with the time between BOO signal and when software turns off (de-energize) the clutch circuit. What does the software say?
Also, is the timing different if we get a De-ac switch signal?

Regards, Fred Kohl, Precision Speed Control (Panther)
PROPS ID: FKOHL Phone TBD Pager (888) 377-6280
IBM Mail(USFMCBJZ)
Mailing Address: ETC C375
*** Forwarding note from SREIMERS--DRBN007 02/09/99 10:08 ***

To: FKOHLL -DRBN007

FROM: Steve Reimers USAET(UTC -06:00)

Subject: More Questions

Would a customer know if the speed control clutch drive output was stuck on?

Is a relay between the the Brake P switch and fuse an feasible fix?

What kind of timing is expected between when the BOO turns off the clutch drive output and when the Brake P switch opens?

thanks,

Steve Reimers building B 3C043
AVT Chassis E/E System Applications mail drop 5011
39-03288 SREIMERS sreimers@ford.com fax 39-03288 >

Schrady, Thomas (T.P.)

From: Steve Reimers (SREIMERS.DRBN007@ovm.gw.ford.com)
Sent: Thursday, February 11, 1999 10:00 AM
To: JNEHIE.DRBN005@ovm.gw.ford.com; FPORTER.DRBN007
@ovm.gw.ford.com; RENGLISI.DRBN005@ovm.gw.ford.com; SSALTER.DRBN006
@ovm.gw.ford.com; NLAPPOINT.DRBN005@ovm.gw.ford.com; TMASTER8.DRBN005
@ovm.gw.ford.com; JKAFATTI.DRBN004@ovm.gw.ford.com; SREIMERS.DRBN007
@ovm.gw.ford.com; tschrady@viscon.com; FKOHLL.DRBN007@ovm.gw.ford.com;
TBAZIL.DRBN005@ovm.gw.ford.com; JMCINERIN.DRBN005@ovm.gw.ford.com;
doudzyna@viscon.com; petokas@viscon.com; DGOGL.DRBN005@ovm.gw.ford.com;
LBROWN.DRBN005@ovm.gw.ford.com; SCOLE1.DRBN008@ovm.gw.ford.com;
HWELFERS.DRBN006@ovm.gw.ford.com; GSTEVENH.DRBN006@ovm.gw.ford.com;
WABRAMCZ.DRBN005@ovm.gw.ford.com

Subject: Brake Pressure Switch

43-17-09.VCM

Requester: Steve Reimers
Date to be scheduled: 02/17/99
Starting time: 02:00 PM
Ending time: 04:00 PM
Recurrence: Single event

Location: building B 3A039

Subject: Brake Pressure Switch

Purpose: Weekly team meeting.

Recurrence: Single event

Schrody, Thomas (T.P.)

From: Steve Reimers [SREIMERS.DRBN007@ovvm.gw.ford.com]
Sent: Tuesday, February 09, 1999 7:14 AM
To: JNEME.DRBN006@ovvm.gw.ford.com; elarouch@mail.ford.com; FPORTER.DRBN007@ovvm.gw.ford.com; RENGLI81.DRBN005@ovvm.gw.ford.com; SSALTER.DRBN006@ovvm.gw.ford.com; NLAPPOINT.DRBN005@ovvm.gw.ford.com; TMASTER.DRBN005@ovvm.gw.ford.com; JKAFATI.DRBN004@ovvm.gw.ford.com; SREIMERS.DRBN007@ovvm.gw.ford.com; technodv@viscon.com; FKOHL.DRBN007@ovvm.gw.ford.com; TBAZIL.DRBN005@ovvm.gw.ford.com; JMCINERN.DRBN005@ovvm.gw.ford.com; cbudzyna@viscon.com; patokas@viscon.com; DGOEL.DRBN005@ovvm.gw.ford.com; LBROWN.DRBN005@ovvm.gw.ford.com; SCOLE1.DRBN008@ovvm.gw.ford.com; HWELFER3.DRBN008@ovvm.gw.ford.com; GSTEVEN1.DRBN005@ovvm.gw.ford.com; WABRAMCZ.DRBN005@ovvm.gw.ford.com
Subject: Brake Pressure Switch

12-18-99.VCS

Requester: Steve Reimers
Date to be scheduled: 02/10/99
Starting time: 02:00 PM
Ending time: 03:00 PM
Recurrence: Single event

Location: bldg 5 3A017

Subject: Brake Pressure Switch

Purpose: Review work plan status.
Plan for Tech. Review on Thursday 2/11/99.

Recurrence: Single event

Schrody, Thomas (T.P.)

From: Steve Reimers [sreimers@gw.ford.com]
Sent: Friday, February 12, 1999 4:53 PM
To: jneme@gw.ford.com; elarouch@mail.ford.com; fporter@gw.ford.com; rengli1@gw.ford.com; ssalter@gw.ford.com; nlapoint@gw.ford.com; tmaster@gw.ford.com; jkafati@gw.ford.com; technodv@viscon.com; fkohl@gw.ford.com; tbazial@gw.ford.com; jmcinern@gw.ford.com; cbudzyna@viscon.com; patokas@viscon.com; dgoel@gw.ford.com; lbrown@gw.ford.com; scole1@gw.ford.com; hwelfer3@eccma1.dearborn.ford.com; gsteven1@gw.ford.com
Subject: PC File(s) sent to you...

This file lists the actions, champion and target date for the Brake Pressure Switch investigation. The next meeting is tentatively set for 2/16/99 afternoon.
A meeting notice will be sent if there is going to be a meeting.

Steve Reimers building 5 3C043
AVT Chassis E/E System Applications mail drop 5011
39-03286 SREIMERS sreimers@ford.com fax 39-03286 >

Schrody, Thomas (T.P.)

From: smimers@gw.ford.com
Sent: Friday, February 05, 1999 4:48 PM
To: tschrody@visetron.com
Subject: File BRKPSW.DOC_PC



Schrody, Thomas (T.P.)

From: Stokes, Paul (P.D.)
Sent: Thursday, February 04, 1999 5:00 PM
To: Schrody, Thomas (T.P.)
Cc: Huberts, Gunter (G.J.)
Subject: FW: Brake Pressure Switch

Tom: The reason this meeting notice was sent to you is because at a meeting today (2/4) same subject which Dan Budzyneld and I attended, we were asked to volunteer some people from speed control to help with this investigation. You (for module) and Fred (for system) were nominated.

AVT, chassis electronics is leading this effort. I think they will be doing most of the work but they may need some help with some speed control specific items. Note that the speed control is NOT suspected as the root cause of this investigation. However, the brake pressure switch is and we are the sole user of the brake pressure switch.

Yes, I intentionally left out what the investigation is all about. See me for details.

—Original Message—

From: Steve Reimers (SMRTP;SPREMMER@DRBN007@www.gw.ford.com)
Sent: Thursday, February 04, 1999 11:44 AM
To: CSTEVEN7.DRBN005@www.gw.ford.com; slatouch@mail.ford.com;
FPORTER.DRBN007@www.gw.ford.com; RBN9LH01.DRBN005@www.gw.ford.com; \$BALTER.DRBN004@www.gw.ford.com;
NLAPORT.DRBN005@www.gw.ford.com; TMATSTER.DRBN006@www.gw.ford.com; JKAPATI.DRBN004@www.gw.ford.com;
SRBIMBER.DRBN007@www.gw.ford.com; tschrody@visetron.com; FKQHL.DRBN007@www.gw.ford.com; TBAZIL.DRBN005
@www.gw.ford.com; JMKINGSL.DRBN008@www.gw.ford.com; dbudzynel@verizon.com; pdobbs@verizon.com;
DSCRL.DRBN005@www.gw.ford.com; LEROWND.DRBN006@www.gw.ford.com; SCOLE1.DRBN005@www.gw.ford.com;
HWELPERA.DRBN008@www.gw.ford.com

Subject: Brake Pressure Switch

Requester: Steve Reimers
Date to be scheduled: 02/05/99
Starting time: 02:00 PM
Ending time: 03:00 PM
Recurrence: Single event

Location: building 6 54039

Subject: Brake Pressure Switch

Purpose: Develop Work Plan.



Recurrence: Single event

Note printed by SMIIMERS on 24 Mar 1999 at 14:03:55

From: SLAROUCHE--FORDMAIL Date and time 03/24/99 13:30:55
To: KEEPOINT--FORDMAIL LaPointe, Norman SLAROUCHE--FORDMAIL LaBoucha, Steve
FPORTER --FORDMAIL Porter, Fred SMIIMERS--FORDMAIL Reimers, Steve
GATEVERI--FORDMAIL Stevans, Gregory

From: LaBoucha, Steve (S.)
Subject: switches from EAA

I have received two switches with filled out questionnaires from EAA. One is from a '93 Town Car (Davenport, FL), and the other is from a Town Car with no model year listed (Insurance Auto Auction in Aurora, IL). One vehicle caught fire while it was left idling (IL vehicle), the other caught fire "15-20 minutes after it was parked. Owner couldn't get it out of park previous evening. Police changed fuse for her. Both switches badly burned. Probably won't be able to tell much from them. A 15A fuse was included with one of the switches. No other parts or brake fluid received with switches. Will not be able to make today's meeting.

Steve LaBoucha (SLAROUCHE)
Metallurgy Section, Central Laboratory, Room 8410
(313) 845-4878 (313) 322-1814 FAX

Team meeting notes

93 CV Non/ABS w/SPEED CONTROL
WANT AIR SUSPENSION

3/24/99

Bring BACK 92 Town

Jon Watson - Contain fire to switch
with Jacket/Shell

70/900 Report Leads From ANS ABRANECYK

Fseries PN 96 - 2 Mel/teal Connectors. Noryl?

OVER

3713 1777

PRODUCED BY FORD

EAE2-025-A 18047

CAN A REPLACEMENT CONNECTOR
BE CAUSING EXCESS LEAKAGE?

~~RE~~

- Take inventory data for?
Line Bill

Tankyard connector evaluation

E-mail WARRANTY DATA TO ANCY.

3713 1778

PRODUCED BY FORD

BA02-025-A 10048

Note printed by FPORTER on 25 Mar 1999 at 15:01:00

From: SLAROUCH--FORDMAIL Date and time 03/24/99 13:20:55
To: MIAPPOINT--FORDMAIL; LaPointe, Norman SLAROUCH--FORDMAIL; LaRouche, Steve
FPORTER --FORDMAIL; Porter, Fred REIMERS--FORDMAIL; Reimers, Steve
GSTEVEM1--FORDMAIL; Stevens, Gregory

From: LaRouche, Steve (S.)
Subject: Switches from AAA

I have received two switches with filled out questionnaires from AAA. One is from a 92 Town Car (Davenport, FL), and the other is from a Town Car with no model year listed (Insurance Auto Auction in Aurora, IL). One vehicle caught fire while it was left idling (FL vehicle), the other caught fire ~15-20 minutes after it was parked. Owner couldn't get it out of park previous evening. Police changed fuse for her. Both switches badly burned. Probably won't be able to tell much from them. A 15A fuse was included with one of the switches. No other parts or brake fluid received with switches. Will not be able to make today's meeting.

Steve LaRouche (SLAROUCH)
Metallurgy Section, Central Laboratory, Room W410
(313) 843-4876 (313) 322-1614 FAX

3713 1351

PRODUCED BY FORD

EAG2-826-A 15849

4/4

Brake Pressure Switch Team Mtg 3/31/99

Steve Reimers	RVT/EE32	REIMERS	X03286
Fred Paole	RVT/EE32	FREDER	X53722
Fred Korn	Known	FKOHL	21801
Greg Stevens	RVT MAT'L	GSTEVEN	36686
Joe Kafati	EE32	JKAFATI	05389
Noem Lepointe	DESIGN ANAL	NLEPOINT	42676
Andy M. Yannas	PE QRA	A.yannas@ti.com	5088363086

3713 1776

PRODUCED BY FORD

ENR2-025-A 10000

BP Team Mtg

4/7/99

MARTY REESE, BILL ABRAMCZYK, ANDY McGUIRK,
FRED PORTER, JOE KAFATI, TOM MASTERS,
PETER JOH, NORM LAPoint, S Rainiers

- Bill Read report from Myrtle Beach, SC
-- home destroyed.
- Joe - selecting Waterproof relay

- UTA
- Need UTA to explain work plan timing
Why 8 weeks turn-around?
 - Validate Pilot Relay fix
 - Splash, Vibration
 - Does Speed control still work.
 - Need DV work plan developed.
 - Will the BP Switch be replaced as part of recall?
- Are we going to take interim action of disconnecting Brake Pressure Switch?
This disables Speed Control.

A - For Monday Meeting, should have
FMEA Issues & Process, Timing for Kits, Timing for Validation

- Econoline 8D similarities & uniqueness

TI - Testing Vertical (Plus-up) function

- ? - Does SYMPTOM MOVE ACROSS PLATFORMS
BLown FUSE, STUCK-IN-PARK, CRUISE MAP,

① TI needs to look at capacity to provide kits

3713 1772

PRODUCED BY FORD

ER02-025-A 18851

Steve LaRouche (SLAROUCH)
Metallurgy Section, Central Laboratory, Room N410
(313) 949-4876 (313) 322-1614 FAX

-----Original Message-----
From: Frederick J. Porter mailto:fporter@gw.ford.com
Sent: Friday, April 16, 1999 8:15 PM
To: slarouch@mail.ford.com
Cc: slapoint@gw.ford.com; arainer@gw.ford.com; phlans@mail.ford.com
Subject: Brake Switches

For clarification:

When you are done with the testing, do the switches from KAA show signs of a cell being formed?

Is there, or could there be, evidence of corrosion occurring on the KAA switches similar to the junkyard switches.

Regards,

Fred Porter OV - fporter fporter@ford.com
Chassis S/S Systems Applications (313) 949-3723
Bldg 5 - Mail Drop 5030 - Cubicle 3B004 FAX: 390-4145
*** Forwarding note from SLAROUCH--FORDMAIL 04/16/99 17:14 ***
To: FPORTER --FORMAIL Porter, Fred (F.J.)
cc: MLAPONT--FORMAIL Lapointe, Norman (MLAPONT) --FORMAIL Klans, Pete
(P.K.)
SLAROUCH--FORMAIL LaRouche, Steve (S.)

From: LaRouche, Steve (S.)
Subject: Brake Switches

Fred: I had a meeting this afternoon with two gentlemen (one was Roc Carter) from Scientific Research Laboratories to discuss brake switches. I showed them the results I have so far, and they felt that our testing was pretty comprehensive and that there was really not any more that they could contribute in terms of testing. We tried to come up with possible scenarios that would tie our findings to a cause of fire, but couldn't come up with anything. Here is a quick summary of our findings at Central Lab:

There appear to be two modes of failure occurring: One involving leakage of brake fluid through the O-ring seal and an apparent cell being set up between the contacts and steel cup. The other involving ingress of water into the switch cavity, with no brake fluid leakage, and no evidence of a cell:

The Memphis switch and all of the leakers analyzed so far show a leak path through the O-ring seals. The cup faces show transfer of the brass contact material to them which suggests that a cell has occurred between the hot contacts and the grounded cup. In addition to brake fluid, the Memphis switch shows evidence (dezincification of the brass contact) that some moisture may have also been present. We found no evidence that road salt had entered the switches.

3713 1624

PRODUCED BY FORD

2002-025-A 10052

The completely burned switches also show probable transfer of contact material to the cups, indicating a possible cell. No evidence of road salt detected. Could not determine if brake fluid leakage occurred.

Three of the junk yard switches (including the one analyzed by SRL) showed corrosion of the cups suggesting ingress of water into the switch cavities. This appears to be a different mode of failure in that there was no evidence of a cell occurring between the contacts and cup. Again, there was no evidence of road salt in the switch cavities. Although there is some damage to the Kapton seals, there appears to have been no leak path or leakage of brake fluid.

I have received two switches from the OASIS which were both leakers. Testing is pretty much complete on these switches and so far we have found nothing different from the other leakers we analyzed.

I have also received three switches from EPA which were completely burned. These switches are in various stages of analysis, but so far do not appear to be different from the completely burned switches we analyzed previously.

The brake fluids in the Memphis switch and all the leakers (including those from the OASIS) contain oxalates. The brake fluid from the car you have out at MPG does not. The guys from SRL suggested that we analyze brake fluids from old vehicles for oxalates and other contaminants, as well as measure conductivity. So far, we have received no brake fluid samples for this.

This is what we have so far: We have found several conditions which may have contributed to a fire, but have not been able to link any of them to a definite cause. I don't think that additional testing on switches is going to be beneficial. I would like to complete the testing that is in progress and wrap this up. Let me know how you want us to proceed.

Steve LeRoux
(SLAROUC)
Metallurgy Section, Central Laboratory, Room N410
(313) 445-4876 (313) 122-1414 FAX

3713 1625

PRODUCED BY FORD

5002-025-A 10053

* Note printed by FPORTER on 26 May 1999 at 16:49:49 *

From: SLAROUCH--FORDMAIL Date and time 04/16/99 17:14:42
To: FPORTER --FORDMAIL Porter, Fred (F.J.)
cc: MLAPPOINT--FORDMAIL LaPointe, Norman (PKLAMS --FORDMAIL Kleam, Pete (P.F.)
SLAROUCH--FORDMAIL LaRouche, Steve (S.)

From: LaRouche, Steve (S.)

Subject: Brake Switches

Fred: I had a meeting this afternoon with two gentlemen (one was Roc Carter) from Scientific Research Laboratories to discuss brake switches. I showed them the results I have so far, and they felt that our testing was pretty comprehensive and that there was really not any more that they could contribute in terms of testing. We tried to come up with possible scenarios that would tie our findings to a cause of fire, but couldn't come up with anything. Here is a quick summary of our findings at Central Lab:

There appear to be two modes of failure occurring: One involving leakage of brake fluid through the Kapton seal and an apparent cell being set up between the contacts and steel cup; The other involving ingressation of water into the switch cavity, with no brake fluid leakage, and no evidence of a cell:

The Memphis switch and all of the leakers analysed so far show a leak path through the Kapton seals. The cup faces show transfer of the brass contact material to them which suggests that a cell has occurred between the hot contacts and the grounded cup. In addition to brake fluid, the Memphis switch shows evidence (desiccification of the brass contact) that some moisture may have also been present. We found no evidence that road salt had entered the switchage.

The completely burned switches also show probable transfer of contact material to the cups, indicating a possible cell. No evidence of road salt detected. Could not determine if brake fluid leakage occurred.

Three of the junk yard switches (including the one analysed by SRL) showed corrosion of the cups suggesting ingressation of water into the switch cavities. This appears to be a different mode of failure in that there was no evidence of a cell occurring between the contacts and cup. Again, there was no evidence of road salt in the switch cavities. Although there is some damage to the Kapton seals, there appears to have been no leak path or leakages of brake fluid.

I have received two switches from the OASIS which were both leakers. Testing is pretty much complete on these switches and so far we have found nothing different from the other leakers we analysed.

I have also received three switches from EPA which were completely burned. These switches are in various stages of analysis, but so far do not appear to be different from the completely burned switches we analysed previously.

The brake fluids in the Memphis switch and all the leakers (including those from the OASIS) contain oxalates. The brake fluid from the car you have out at MPG does not. The guys from SRL suggested that we analyse brake fluids from old vehicles for oxalates and other contaminants, as well as measure conductivity. So far, we have received no brake fluid samples for this.

3713 5252

PRODUCED BY FOI

E982-025-A 10054

This is what we have so far: We have found several conditions which may have contributed to a fire, but have not been able to link any of them to a definite cause. I don't think that additional testing on switches is going to be beneficial. I would like to complete the testing that is in progress and wrap this up. Let me know how you want us to proceed.

Steve LaRouche (SLAROUCH)
Metallurgy Section, Central Laboratory, Room B410
(313) 343-4876 (313) 321-1614 FAX

3713 5253

PRODUCED BY FORM

ENR2-825-A 19688

Note printed by FFPORTER on 20 Apr 1999 at 09:59:33

From: SLAROUCH--FORDMAIL Date and time 04/20/99 09:05:14
To: FFPORTER --FORDMAIL Porter, Fred (F.J.
cc: SLAROUCH--FORDMAIL LaRouche, Steve (S.)

From: LaRouche, Steve (S.)
Subject: RE: Brake Switches

Fred: You are correct for the Reddick switch. The damage was most severe on the washer side of the seal pack, which indicated that was where the cracking initiated. I don't think we can make a general statement about where the cracking/damage initiated for all the samples as it appears to have initiated at different locations in different samples (The cracking appears to have initiated on the fluid side of the seals in the two oasis samples; the initiation point could not be determined in the other samples).

Steve LaRouche (SLAROUCH)
Metallurgy Section, Central Laboratory, Room M410
(313) 845-4876 (313) 322-1814 FAX

-----Original Message-----

From: Frederick J. Porter mailto:fporter@fw.ford.com
Sent: Monday, April 19, 1999 5:17 PM
To: slarouch@mail.ford.com
Cc: steimer@fw.ford.com
Subject: RE: Brake Switches

At today's Technical Review Committee meeting, the question was asked "Can we tell which direction the brittleness and cracking is happening on the kapton switches?" We noted that in your chart the Reddick vehicle said that it started on washer side. I think this means that the cracking started on the electrical side and progressed to the hydraulic side of the kapton.

1) Please confirm that I am correct.

2) Can we make a statement in regards to which kapton layer started to crack first on the other leaky switches?

Regards,

Fred Porter CV - Fporter fporter@fw.ford.com
Chassis E/E Systems Applications (313) 845-3722
Bldg 8 - Mail Drop 5030 - Cubicle 3E004 fax: 320-4145
*** Forwarding note from SLAROUCH--FORDMAIL 04/19/99 07:57 ***
To: FFPORTER --FORDMAIL Porter, Fred (F.J.)

From: LaRouche, Steve (S.)
Subject: RE: Brake Switches

Fred: We are currently investigating this. I hope to have an answer this week.

3713 1623

PRODUCED BY FORD

EAD2-925-A 100058

8628

Request for Central Laboratory Service

15006 Country Dr., Dearborn MI 48130-1357 Phone (313) 323-2676 FAX (313) 323-3614

For information about services or assistance in completing this form please refer to the Council Laboratory Work page. Laboratory number and date cannot be omitted without prior notice of acceptance.

For information about services or assistance in completing this form please contact your local office of the Minnesota Department of Health.

Home | About the City

Does your spouse work? 7-1-93

FAX preliminary results FAX final version
 FAX final report Mail final version

Mail typed report
 Electronically transfer report
 Provide preliminary results

For information about services or assistance in completing this form please refer to the Central Laboratory Web page. Laboratory number and date cannot be changed without receipt of samples. Samples will be discarded after 30 days unless otherwise specified above.

3713 3281

PRODUCED BY FORD

5002-925-A 10057

Request for Central Laboratory Service

Request - Copy

Lab Request Number: 00000137
Date of Request: 05/12/1999 03:37:40 PM
Print Date: 05/12/1999 04:54:42 PM

Request Description: SPEED CONTROL CUTOFF SWITCH

Customer Information:

Primary Contact: S

Secondary Contact: EXP-CARVE, NC1405 - 10073

PHONE: (313) 337-5256

FAX: (313) 337-5256

PROPS TO: NAPPOINT

Send Report to:	MD 3005/2G085, PVT MATERIALS, BLDG. #5
BILL to:	Acctg. Location: 5100
	Dept: T113
	Work Task: XQ394

Sample Information:

Total Number of Containers: 17

Sample Handling: Return after test

Source: Not specified

Supplier Code: Not specified

Part/Material Name	Ctn	Sample Identification	Part Number	Material Spec.	CPSC Code	Supplier
SPEED CONTROL CUTOFF SWITCH	17	SET ATTACHED SH SET	P2VY-3F924-A	NA	00.00.00	TEXAS INST RUMEN T3

Investigation Information:

Nature of Investigation: Requester info. Box: Mail typed report

Additional Sample Information/Testing Requirements:

Perform Tests as in Lab Number: 9000007

PERFORM TESTS AS IN 9000007 TO ASSIST IN DETERMINING CAUSE OF POSSIBLE
LEAKAGE/FIRES. ADDITIONAL SWITCHES MAY FOLLOW.

Customer Instructions:

Date customer would like report: 07/01/1999

Date customer must have report: 07/01/1999

Report Format(s):

Login Information:

Initial Routing: Metallurgy

Accepted for Central Laboratory by: LaRouche, Steve

Phone: 64-34876

Program Name: KALUSLab Engg Module
Program Version: 3.0.0

View your test status at: <HTTP://bd4web.pvt.ford.com/test>

Roman: Please perform test. i pressurize
this as before.

Jim needs to log this
in to you.
Thanks,
Steve

3713 3286

PRODUCED BY FORD

ENR2-025-A 10856

From Page No. _____

TO: _____

SUBJECT: SPREAD COTTON COTTEE SWITCH
PART NUMBER: F1VY-9F914-A
SPECIFICATION: NOT PROVIDED

SUPPLIER: TEXAS INSTRUMENTS

RECEIVED: SEVENTEEN SPECIMENS WERE RECEIVED
ON MAY 12, 1999.

TEST: TEST SWITCH PER MATRIX PROCEDURE AND
EVALUATION PROCESS INSTRUCTIONS THAT WERE
PROVIDED

TEST DATA:

SEE MATRIX CHARTS ATTACHED TO THE
FILED REPORT

To Page No. _____

Witnessed & Understood by me,
J. L. Munro, S.A.

Date

Submitted by

R. M. Yingst, S.A.

Date

5-25-99

3713 3287

PRODUCED BY FORD

EAB2-625-A 16099

C = COMPLETE
NA = NOT APPLICABLE
TOB = TO BE PERFORMED

Brake Switch Testing Checklist

INF = INFINITY (OPEN)
NP = NOT PERFORMED
NACLS = NOT NEEDED AT CEM. LAB.

	Jan-95	Apr-95	Jun-95	Aug-95	May-95	Jun-96	Nov-96	Open
Field Info	X	X	X	X	X	X	C	
1. Using Field Intercept Vehicle Log #s	C	C	C	C	C	C	C	C
2. Passenger Seats	C	C	C	C	C	C	C	C
3. Forward Day Instrument Panel Visual Inspection	C	C	C	C	C	C	C	C
4. Check for Converter bypasses	NP	NP	C	NP	NP	NP	NP	NP
5. Check SRS components								
Switch + Connector Assembly	6. Check for GM 1000 Volt bypasses	NP	NP		NP	NP	NP	NP
7. Check GM 1000 Volt Harness Resistance	NP	NP		NP	NP	NP	NP	NP
8. Check Harness from GM	NP	NP		NP	NP	NP	NP	NP
9. Check GM 1000 Volt Harness Resistance	NP	NP		NP	NP	NP	NP	NP
10. Check GM 1000 Volt Bypasses	NP	NP		NP	NP	NP	NP	NP
11. Check GM 1000 Volt Bypasses	NP	NP		NP	NP	NP	NP	NP
12. Check resistance for left side application of connector	NP	NP		NP	NP	NP	NP	NP
13. Check side connectors	NP	NP		NP	NP	NP	NP	NP
14. Check side gray wires	NP	NP		NP	NP	NP	NP	NP
15. Check side resistance to check for connection	NP	NP		NP	NP	NP	NP	NP
Switch External Unconnected	16. Ground Bridge to Common Ground	—	—	—	—	—	—	NP
	17. Spring Terminal to Battery Terminal Resistance	0.04 ohm	0.03 ohm	0.01 ohm	0.01 ohm	0.03 ohm	0.01 ohm	0.05 ohm
	18. Spring Terminal to Harness Resistance	0.02 ohm						
	19. Harness Terminal to Harness Resistance	0.02 ohm						
	20. Harness to Harness Resistance	0.02 ohm						
Switch External Connected	21. Ground Opening Pressure	0.04 ohm	0.55	260	0.04 ohm	275	176	0.04 ohm
	22. Ground Closing Pressure	0.04 ohm	2.00	140	0.04 ohm	170	160	0.04 ohm
	23. Power Test Ice Loadings	NO LEAK						
	24. Power Wires at Strength 200 at 1000vdc	—	—	—	—	—	—	—
	25. Power Terminal to Battery Terminal Resistance	0.04 ohm	0.04 ohm	0.02	0.02 ohm	0.02 ohm	0.05 ohm	0.02
	26. Ground Terminal Harness Resistance - GM 1000 Volt	0.02	0.02	0.02	0.02	0.02	0.02	0.02
	27. Harness Terminal to Harness Resistance - GM 1000 Volt	0.02	0.02	0.02	0.02	0.02	0.02	0.02
	28. Harness to Harness Resistance - GM 1000 Volt	0.02	0.02	0.02	0.02	0.02	0.02	0.02
Switch	29. Harness resistance							
	30. Harness electrical surface Photography							
	31. Harness heat							
	32. Harness electrical surface Photography							
Techniques	33. Visual inspection of contacts							
	34. Visual inspection of contacts							
	35. Visual inspection of connectors							
	36. Visual inspection of connectors							
	37. Visual inspection of connectors							
	38. Visual inspection of connectors							
	39. Visual inspection of connectors							
	40. Visual inspection of connectors							
	41. Visual inspection of connectors							
	42. Visual inspection of connectors							
	43. Visual inspection of connectors							
	44. Visual inspection of connectors							
	45. Visual inspection of connectors							
	46. Visual inspection of connectors							
	47. Visual inspection of connectors							
	48. Visual inspection of connectors							
	49. Visual inspection of connectors							
	50. Visual inspection of connectors							
	51. Visual inspection of connectors							
	52. Visual inspection of connectors							
	53. Visual inspection of connectors							
	54. Visual inspection of connectors							
	55. Visual inspection of connectors							
	56. Visual inspection of connectors							
	57. Visual inspection of connectors							
	58. Visual inspection of connectors							
	59. Visual inspection of connectors							
	60. Visual inspection of connectors							
	61. Visual inspection of connectors							
	62. Visual inspection of connectors							
	63. Visual inspection of connectors							
	64. Visual inspection of connectors							
	65. Visual inspection of connectors							
	66. Visual inspection of connectors							
	67. Visual inspection of connectors							
	68. Visual inspection of connectors							
	69. Visual inspection of connectors							
	70. Visual inspection of connectors							
	71. Visual inspection of connectors							
	72. Visual inspection of connectors							
	73. Visual inspection of connectors							
	74. Visual inspection of connectors							
	75. Visual inspection of connectors							
	76. Visual inspection of connectors							
	77. Visual inspection of connectors							
	78. Visual inspection of connectors							
	79. Visual inspection of connectors							
	80. Visual inspection of connectors							
	81. Visual inspection of connectors							
	82. Visual inspection of connectors							
	83. Visual inspection of connectors							
	84. Visual inspection of connectors							
	85. Visual inspection of connectors							
	86. Visual inspection of connectors							
	87. Visual inspection of connectors							
	88. Visual inspection of connectors							
	89. Visual inspection of connectors							
	90. Visual inspection of connectors							
	91. Visual inspection of connectors							
	92. Visual inspection of connectors							
	93. Visual inspection of connectors							
	94. Visual inspection of connectors							
	95. Visual inspection of connectors							
	96. Visual inspection of connectors							
	97. Visual inspection of connectors							
	98. Visual inspection of connectors							
	99. Visual inspection of connectors							
	100. Visual inspection of connectors							
	101. Visual inspection of connectors							
	102. Visual inspection of connectors							
	103. Visual inspection of connectors							
	104. Visual inspection of connectors							
	105. Visual inspection of connectors							
	106. Visual inspection of connectors							
	107. Visual inspection of connectors							
	108. Visual inspection of connectors							
	109. Visual inspection of connectors							
	110. Visual inspection of connectors							
	111. Visual inspection of connectors							
	112. Visual inspection of connectors							
	113. Visual inspection of connectors							
	114. Visual inspection of connectors							
	115. Visual inspection of connectors							
	116. Visual inspection of connectors							
	117. Visual inspection of connectors							
	118. Visual inspection of connectors							
	119. Visual inspection of connectors							
	120. Visual inspection of connectors							
	121. Visual inspection of connectors							
	122. Visual inspection of connectors							
	123. Visual inspection of connectors							
	124. Visual inspection of connectors							
	125. Visual inspection of connectors							
	126. Visual inspection of connectors							
	127. Visual inspection of connectors							
	128. Visual inspection of connectors							
	129. Visual inspection of connectors							
	130. Visual inspection of connectors							
	131. Visual inspection of connectors							
	132. Visual inspection of connectors							
	133. Visual inspection of connectors							
	134. Visual inspection of connectors							
	135. Visual inspection of connectors							
	136. Visual inspection of connectors							
	137. Visual inspection of connectors							
	138. Visual inspection of connectors							
	139. Visual inspection of connectors							
	140. Visual inspection of connectors							
	141. Visual inspection of connectors							
	142. Visual inspection of connectors							
	143. Visual inspection of connectors							
	144. Visual inspection of connectors							
	145. Visual inspection of connectors							
	146. Visual inspection of connectors							
	147. Visual inspection of connectors							
	148. Visual inspection of connectors							
	149. Visual inspection of connectors							
	150. Visual inspection of connectors							
	151. Visual inspection of connectors							
	152. Visual inspection of connectors							
	153. Visual inspection of connectors							
	154. Visual inspection of connectors							
	155. Visual inspection of connectors							
	156. Visual inspection of connectors							
	157. Visual inspection of connectors							
	158. Visual inspection of connectors							
	159. Visual inspection of connectors							
	160. Visual inspection of connectors							
	161. Visual inspection of connectors							
	162. Visual inspection of connectors							
	163. Visual inspection of connectors							
	164. Visual inspection of connectors							
	165. Visual inspection of connectors							
	166. Visual inspection of connectors							
	167. Visual inspection of connectors							
	168. Visual inspection of connectors							
	169. Visual inspection of connectors							
	170. Visual inspection of connectors							
	171. Visual inspection of connectors							
	172. Visual inspection of connectors							
	173. Visual inspection of connectors							
	174. Visual inspection of connectors							
	175. Visual inspection of connectors							
	176. Visual inspection of connectors							
	177. Visual inspection of connectors							
	178. Visual inspection of connectors							
	179. Visual inspection of connectors							
	180. Visual inspection of connectors							
	181. Visual inspection of connectors							
	182. Visual inspection of connectors							
	183. Visual inspection of connectors							
	184. Visual inspection of connectors							
	185. Visual inspection of connectors							
	186. Visual inspection of connectors							
	187. Visual inspection of connectors							
	188. Visual inspection of connectors							
	189. Visual inspection of connectors							
	190. Visual inspection of connectors							
	191. Visual inspection of connectors							
	192. Visual inspection of connectors							
	193. Visual inspection of connectors							
	194. Visual inspection of connectors							
	195. Visual inspection of connectors							
	196. Visual inspection of connectors							
	197. Visual inspection of connectors							
	198. Visual inspection of connectors							
	199. Visual inspection of connectors							
	200. Visual inspection of connectors							
	201. Visual inspection of connectors							
	202. Visual inspection of connectors							
	203. Visual inspection of connectors							
	204. Visual inspection of connectors							
	205. Visual inspection of connectors							
	206. Visual inspection of connectors							
	207. Visual inspection of connectors							

C - COMPLETE
NA - NOT APPLICABLE
TBD - TO BE DETERMINED

Brake Switch Testing Checklist

INF = INFINITY (OPEN)

MP = NOT PERFORMED

NACLS • NOT RECENTLY CEN (10)

C - COMPLETE
NA - NOT APPLICABLE
TBD - TO BE DETERMINED

Brake Switch Testing Checklist

INF = INFINITY (OPENED)
NP = NOT PENDING
NACLS = NOT HECDAT CEN. LAD.

From Page No. _____

TGI

SUBJECT: SPEED CONTROL CUTOFF SWITCH
PART NUMBER: F1VY-9F934-A
SPECIFICATION: NOT PROVIDED

SUPPLIER: TEXAS INSTRUMENTS

RECEIVED: SEVENTEEN SPECIMENS WERE RECEIVED
ON MAY 12, 1999.

OBJECT: TEST SWITCH THE MATRIX PROCEDURE AND
EVALUATION PROCESSES INSTRUCTIONS THAT WERE
PROVIDED

TEST DATA:


SEE MATRIX CHARTS ATTACHED TO THE
FIELD REPORT

To Page No. _____

Witnessed & Understood by me,

John J. Murphy, Jr.

Date

Date
5-25-99

3713 3291

PRODUCED BY FORD

E982-825-A 18863

STA Mfg | BPS

5/21/77

John Rantis, Away, FRED, Store.

- Team meeting - "Prevent action" chart
plans development

- Recall parts examine
plan

XRAY
TEST TO FAILURE
REGIONAL SAMPLING

- Invite John Rantis
jrantis

JUNE 17-18 TRIP TO ATTLEBORO

- Line visit John / ME
- Understand 92 Process Joe K?
- " 99 Process Tom M?
Norm LaPointe ?

3713 1766

PRODUCED BY FORD

EAB2-825-A 18084

SMMPSXEA

Service to Engineering Cross Reference

09/01/00 14:52:57

==> SERVICE PART: 1W1Z- 2140-AA CYLINDER ASY - MASTER
HISTORY: N

A	C	ENGINEERING PART	ENG. INFO ORIGIN	EFFECTIVE IN DATE	Effective Out Date
		1W13 2C156 AA	WERS	12/14/99	

F1=Help F2=ServPartDisp F5=EngPartDisp F6=EngServXref
NO MORE RECORDS AVAILABLE

EFT54AM

ES F17A-2L118-A4

ES 1374

ES 2669-1

ES 2922

SMMPSXEA

Service to Engineering Cross Reference

09/01/00 14:53:10

==> SERVICE PART: 1W1Z- 2140-BA CYLINDER ASY - MASTER
HISTORY: N

A	C	ENG. INFO	EFFECTIVE	Effective
ENGINEERING PART		ORIGIN	IN DATE	Out Date
-----		-----	-----	-----
	1W13 2C156 BA	WERS	12/14/99	

F1=Help F2=ServPartDisp F5=EngPartDisp F6=EngServXref
NO MORE RECORDS AVAILABLE

EPT54AM

09/01/00

MATTER CHANGE REPORT for NLAPOINT
(for past 2 months)

C = Matter Change; * = Changed field; N = New Matter

LOG DATE	NUMBER	MATTER NAME	STATUS	OGC ATTY	TRIAL DATE	OC FIRM
08/01/00	C 966611	SOUTH DAKOTA FLEE	OPEN	*DLAMPE		
08/01/00	C 402108	SOUTH DAKOTA STAT	OPEN	*DLAMPE		
08/01/00	C 402107	SOUTH DAKOTA STAT	OPEN	*DLAMPE		
07/06/00	N 410536	HUBBARD TROY	OPEN	DLAMPE		AZ36
07/05/00	C 403443	MYERS JEFFREY L	*CLSD	NGRABOWS		

Susan to call me back!

- FMEA for shorted switch.
 - FMEA for failed B00 function
 - What does competition do? SALTER
 - Why a P switch? VISTECN
 - Immediate action (Containment)
 - Disconnect Switch (Remove & Replace)
 - Re-wire to low-side
 - ~~short out~~ Jumper out switch
 - /4 D
 - OTHER TEAM MEA
 - VO - TOWNC
 - Competitive Analysis.
 - of Redundant SW.
 - does current work?
 - Is it a Redundant SW?
 - FAULTS REQUIRE HOT
 - ALL TIME FAULTS
 - Cut away of switch
- TOM RAY

3713 181B

PRODUCED BY

Q.E.D.


2002-025-A 18870

INTERIM REPAIR

DISABLE SPEED CONTROL DEACTIVATION SWITCH

SERVICE PROCEDURE

1. Disconnect the electrical connector from the speed control deactivation switch. See Figure 1.



IR96615A

FIGURE 1

2. Tape the end of the connector to prevent contamination from entering the end of the connector.
3. Tie strap the connector to the wiring harness located on the left splash shield.

PERMANENT REPAIR

SPEED CONTROL DEACTIVATION SWITCH AND CONNECTOR REPLACEMENT

AFFECTED VEHICLES: CERTAIN 1992 AND 1993 CROWN VICTORIA, GRAND MARQUIS
AND TOWN CAR WITH SPEED CONTROL

OVERVIEW

This repair involves replacement of the speed control deactivation switch and the hard shell of the switch electrical connector. The connector terminals will be removed from the old connector hard shell and inserted into the new connector hard shell.

PROCEDURE

1. Install a memory saver and disconnect the negative battery terminal.
2. Disconnect the electrical connector from the speed control deactivation switch. See Figure 2.





FIGURE 2

3. Remove the locking wedge from the end of the connector. Then, disengage the locking tabs and remove the wire terminals from the connector. See Figure 3.



IP99815C

FIGURE 3

4. Obtain the new connector from the kit. Insert both wire terminal ends through the connector seal and into the connector hard shell. (The wire terminal ends may be installed into either of the connector cavities).
5. Check the connector to make sure the locking tabs have engaged both terminal ends. Also, make sure the seal is fully seated in the back of the connector. Then, install the red locking wedge to secure the terminals in the connector.
6. Obtain the speed control deactivation switch from the parts kit.
7. Remove the old speed control deactivation switch.
8. Fill the new speed control deactivation switch with High Performance DOT 3 Brake Fluid and install the speed control deactivation switch. Tighten the switch to 16 Nm (13 lb-ft).
9. Attach the electrical connector to the speed control deactivation switch.
10. Connect the battery negative cable and remove the memory saver.
11. Raise the vehicle on a hoist.
12. Connect a clear drain tube to the RH rear bleeder screw and the other end in a container partially filled with the recommended brake fluid.
13. Have an assistant pump the brake pedal and then hold firm pressure on the brake pedal.
14. Loosen the RH rear bleeder screw until a stream of brake fluid comes out. While the assistant maintains pressure on the brake pedal, tighten the bleeder screw.
 - Repeat until clear, bubble-free fluid comes out.
 - Refill the brake master cylinder reservoir as necessary.
15. Repeat Steps 12-14 for the LH rear bleeder screw.
16. Lower the vehicle.