

**[CONFIDENTIAL MATERIAL
REDACTED]**

10. Provide a description of each of the following conditions as it applies to the alleged defect in the subject vehicle and a chronological summary of the actions Honeywell has taken to rectify this condition in the subject component:
- a. A misformed condition in the actuator die which can lead to a rebound of the lock bolt causing a potential for failure of the ECL to unlock during the vehicle start up;
 - b. A bowing condition on the ECL hardware cover which can lead to binding of the ECL gears;
 - c. Improper heat treatment of the casting, crimp nest resulting in a potential for improper seating, which lead to either the binding of the ECL gears or the rebound of the ECL lock bolt; and
 - d. Any other condition in the subject component that relates to the alleged defect in the subject vehicle.

SAGINAW TESTER SEQUENCE OF OPERATION

SCAN TIME 3.1ms.

1. Extend Guard Rung 10
2. Retract Nest Rung 27
3. Check for shorted wire for 500 ms. Rung 37
3A) if good, continue test
3B) if bad, stop test & reject part
4. Clamp part & check resistance at the same time. Rung 62
4A) if good, continue test
4B) if bad, stop test & reject
5. Check for no crimp, missing screw, & try to retract part to start position. Rung 91
5A) if good, continue test
5B) if bad, stop test & reject part
6. Extend Linear Encoder & close relay G [G transfers contact signal to PLC] Rung 101
7. Delay 500 ms.
- ✓ 8. Turn on "6 volts" & check part for 11.25mm Rung 118
8A) if over 11.25mm, reject
8B) if under 11.25mm, continue test
- ✓ 9. Delay 1.0 second & do a shorted test
- ✓ 10. Delay 900ms
- ✓ 11. Check part to see if contacts are closed.
11A) if open, reject part
11B) if closed, extend plunger
- ✓ 12. Delay 500 ms. Rung 35-3
- ✓ 13. Retract plunger (turn on read retract) Rung 36
During movement :
- ✓ 14. Part must "open at high set point",
"close before Schaevitz reaches low set point".
14A) If part is bad, stop test & reject
14B) if good, continue test
- ✓ 15. Retract Linear Encoder
- ✓ 16. Delay 200 ms. Rung 410 Tim 4
- ✓ 17. "Turn on 9v"
- ✓ 18. Delay 500ms Rung 419 Tim 5
- ✓ 19. Extend plunger for 500 ms.
- ✓ 20. Check part. contacts must be open.
(if not, reject)
- ✓ 21. Extend Electric side load cycle.

Rung 478

484

Change 1714 to

2015

(3 places)

- ✓ 22. Start 3.0 sec timer, Lebow set point has to be made before 3.0 sec. Timer times out.
22A) if not, reject part $T_{1-2} \approx R_{avg} 444$

NOTE: Lebow is force gage.

- ✓ 23. Delay 500 ms after Lebow set point is made. $T_{1-2} \approx R_{avg} 444$

- ✓ 24 Retract plunger, 2.0 sec. with side load

25. after 1.2 sec., pulse to check part. $R_{avg} 166$
24A) If part is closed, continue test
24B) If part is open, stop test & reject part

26. Retract side load $R_{avg} 444$

27. Delay 200 ms. $T_{1-2} \approx R_{avg} 444$

NOTE: All tests for shorts test are 500 ms. long

28. Check for shorted part for 500 ms. $R_{avg} 507$
28A) If shorted, stop test & reject

29. "Turn on 14.2V" $R_{avg} 527$

- ✓ 30. Delay 500 ms. $T_{1-2} \approx R_{avg} 517$

31. Extend plunger for 500 ms. $R_{avg} 532$

32. Check part
32A) If part is not open, stop test & reject part
32B) If part is good, continue test

33. Check for shorted part for 500 ms. $R_{avg} 528$
33A) If part is bad, stop test & reject part
33B) If part is good, continue test

34. "Turn on 8.5V" $R_{avg} 551$

35. Delay 500 ms. $T_{1-2} \approx R_{avg} 541$

- ✓ 36. Retract plunger for 1.2 sec. $R_{avg} 547$

37. Check part $R_{avg} 572$
37A) If open, stop test & reject part
37B) If closed, continue test

38. Delay 500 ms. $T_{1-2} \approx R_{avg} 579$

39. Extend Plunger for 500 ms. $R_{avg} 584$

40. Check part $R_{avg} 542$
40A) If closed, stop test & reject part
40B) If open, continue test

41. Check for shorted part for 500 ms. $R_{avg} 590$
41A) If shorted, stop test & reject
41B) If good, continue test

42. "Turn on 14.2V" $R_{avg} 427$

- 43 Delay 500 ms. Rung 615
- 44 Retract plunger Rung 649 & 655
 > 14.2 v test, once the contacts close, we look for any open longer than 3.1 ms.,
 if so we reject as intermittent.
- 45 Check part Rung 626
 45A) If open, stop test & reject part
 45B) If good, continue test
- 46 Do a shorted test Rung 621
- 47 "Turn on 8.5v" Rung 639
- 48 Delay 500 ms. Rung 662
- 49 Extend plunger Rung 668
- 50 Check part Rung 674
 50A) If part is closed, stop test & reject
 50B) If open, continue test
- 51 Delay 500 ms. Rung 681
- 52 Retract plunger for 1.2 sec. Rung 687
- 53 Check part Rung 692
 53A) If open, stop test & reject part
 53B) If closed, continue test
- 54 Turn off 8.5V Rung 704
- ✓ 55 Turn on 14.2V & extend plunger Rung 707
- ✓ 56 Delay 1.5 sec Rung 714
- 57 Retract plunger Rung 721
- 58 Open relay H while under power Rung 725
- REGRIND TEST
- 59 Delay 1 sec. Rung 725
- 60 Check part. Rung 733
 60A) If closed, part passed
 60B) If open, Reject part
- 61 If all conditions have been met for a good part, turn on good light & add 1 to counter Rung 750
- 62 Extend stamp pad for 300 ms. Rung 810
- 63 Unclamp part Rung 825
- 64 Extend nest Rung 829
- 65 Reinacigane Rung 845

(NOTE*) On a reject part:
1.) test is stopped
2.) a red light will come on
3.) 1 of 5 counters will count the reject
4.) part is not given back to the operator until a red button is pushed


(NOTE)

On all extend
plungers the timer is
set for 500ms.

REJECT CODES

1. 1mm reject (Inactive)
2. Intermittent (Inactive)
3. Reject 6V ↑
4. Reject not open 9V ↑
5. 9V side load
6. 14.2V ↑
7. 8.5 V ↓
8. 8.5 V ↑
9. 14.2 V ↓
10. 8.5V ↑
11. 8.5V ↓
12. Not close initially
13. 6vun
14. No screw or bad crimp
15. Intermittent
16. Intermittent
17. Shorted Reject

Column Lock Warranty Returns with Switch Point Initiatives




11. Produce each of the following:

- a. One exemplar sample of each design version of the subject component; and,
- b. Field return samples of the subject component exhibiting each of the following conditions:
 - i. A misformed condition in the actuator die, which can lead to a rebound of the lock bolt causing a potential for failure of the ECL to unlock during the vehicle start-up;
 - ii. A bowing condition on the ECL hardware cover, which can lead to binding of the ECL gears;
 - iii. Improper heat treatment of the casting crimp nest resulting in a potential for improper seating, which can lead to either the binding of the ECL gears or the rebound of the ECL lock bolt; and
 - iv. Any other condition in the subject component that relates to the alleged defect in the subject vehicle.

Tek Stop 300 S/s

109 Acqs



CH1--5.00 V--CH2--5.00 V--M 1.00 s--CH1--2.4 V 9 Apr 2003
D 100ms Runs After 09:10:29


Attachment 11A

(Oscilloscope Graph of
Returned Unit)

Tek Stop: 500 S/s

109 Acqs

[T]




Part # 23
Date Code
9028
14.2Volts

9 Apr 2003
09:10:29

12. Furnish Honeywell's assessment of the alleged defect in the subject vehicle, including:
 - a. The causal or contributory factor(s);
 - b. The failure mechanism(s);
 - c. The failure mode(s);
 - d. The risk to motor vehicle safety that it poses; and
 - e. What warnings, if any, the operator and the other person both inside and outside the vehicle would have that the alleged defect was occurring or subject component was malfunctioning.

Column Lock Warranty Returns



PARETO OF DEFECTS

