

**EA03-004**

**FORD 8/27/03**

**ATTACHMENT J**

**BOOK 1 OF 3**

**PART 4 OF 4**

**From:** Sesshore, Patricia (P.J.)  
**Sent:** Tuesday, September 19, 2000 6:49 PM  
**To:** Hyde, Mary Ellen (M.E.)  
**Subject:** FW: CCRG - Wheel concern

Per my earlier e-mail, here is a copy of the actual paper reviewed and approved at the CCRG last week.

-----Original Message-----

**From:** Sennett, Syed (S.H.)  
**Sent:** Friday, September 15, 2000 2:36 PM  
**To:** Nease, Joseph (J.S.)  
**Cc:** Loop, James (J.L.); McNamee, John (J.T.); Dearing-Thornton, Zandra (Z.F.); Sesshore, Patricia (P.J.); Sennett, Syed (S.H.)  
**Subject:** CCRG - Wheel concern

Attached is the final version of the CCRG concern paper. I have included changes made by you to the earlier version. This paper was reviewed with Pat Sesshore. Please forward this to The CCRG committee for closure. Please call me regarding any questions you may

 WH\_CCRG.doc

have.

MODEL YEAR 1995-2000 WINDSTAR WHEEL CONCERN

To: CCRG Chairman  
Subject: 1995-2000 Windstar Wheel Concern

**CONCERN DESCRIPTION:** Allegations of wheel nuts with insufficient torque and loose wheel studs/bolts on 1995-2000 Windstar vehicles were reported to the CCRG by Ford of Canada - FCSD.

**CONCERN INVESTIGATION:** The following data was investigated to assess this concern:  
**Field Data:** (Approximately 1.5 Million vehicles were sold during 1995-2000)

(1) CQIS claims:

The indicator summary for 1995-2000 model years is as follows:

HDSR 11 wheel separated

CAC 33 wheel separated

NHL 6 wheel separated

Note: 21 out of 50 Le 42% vehicles had wheels repaired under warranty per AWS prior to incident

(2) AWS claims:

19 total claims of wheel separation were reported in AWS (cut-off date 6/30/00). Twelve (12) out of Nineteen (19) i.e. 63% confirmed instances where wheels were removed and reinstalled prior to separation.

(3) Accidents and injuries: Total Four (4) were reported, three (3) claims and 1 lawsuit which were closed.

(4) No assembly issues: The nut runner torque capability (CPK) was 1.4 – 1.5 (Acceptable 3 Sigma is 1.33) between Jan.95 and Jan.00 using a pneumatic nut runner. A D.C. nut runner has since been installed at Oakville Assembly Plant which increased the torque capability to 5-11.

(5) No design or material defect issues: Review of Durability vehicle concerns for Model Years 1995-2001 conducted with all past wheel Design and Release Engineers on durability vehicles indicates that no wheel separation concerns were ever reported during testing. Also, material analysis of parts returned from two vehicles in the field performed by Ford Central Laboratories indicates that the studs met all material specifications.

(6) Mileage study: The average mileage of all claims for wheel separation is 26,000 which is high enough to reasonably assume that tires were likely removed for tire rotation as part of routine maintenance.

**ASSESSMENT OF EFFECT ON VEHICLE OPERATION:**

The customer will notice vibration and/or steering wheel rattle if lug nuts are loosening. This condition would gradually increase as wheel lug-nuts went elongated. If left unchecked, it may lead to breaking of wheel studs and possibly the wheel separating from the wheel.

**RECOMMENDATION:**

No field action required since engineering analysis indicates that the wheel design is robust and since the majority of the incidents of wheels separating occurred after the wheel were removed when servicing the vehicle the condition may be related to improper service and/or maintenance. Also, this investigation does not indicate a defect trend in the field. Based upon this information, Windstar OPD Chassis Engineering and NAC Safety/Recall Engineering recommends closure of this concern.

\_\_\_\_\_  
Syed Hasan Sarmast (signed)  
(Syed Sarmast)  
Windstar OPD - Chassis

9/15/00  
Date

**From:** Seashore, Patricia (P.J.)  
**Sent:** Monday, September 18, 2000 2:01 AM  
**To:** Heyda, Mary Ellen (M.E.)  
**Cc:** Sims, Michael (M.A.)  
**Subject:** FW: CCRG - Wheel concern

 [WHL\\_CCRG2.doc](#)

I will forward a copy of the 1-pager (I don't believe the attachment will come through). The recommendation is as follows:

No field action required since engineering analysis indicates that the wheel design is robust and since the majority of the incidents of wheels separating occurred after the wheels were removed when servicing the vehicle the condition may be related to improper service and/or maintenance. Also, this investigation does not indicate a defect trend in the field. Based upon this information, Windstar OPD Chassis Engineering and MAC Safety/Recall Engineering recommends closure of this concern..

This recommendation was reviewed and agreed to in CCRG last week,

-----Original Message-----

**From:** Sarmast, Syed (S.H.)  
**To:** Name, Joseph (J.S.)  
**Cc:** Loop, James (J.R.); McInernay, John (J.T.); Dearing-Thornton, Sandra (Z.F.); Seashore, Patricia (P.J.); Sarmast, Syed (S.H.)  
**Sent:** 9/15/00 2:35 PM  
**Subject:** CCRG - Wheel concern

Attached is the final version of the CCRG concern paper. I have included and changes made by you to the earlier version. This paper was reviewed with Pat Seashore. Please forward this to The CCRG committee for closure. Please call me regarding any questions you may have. <[WHL\\_CCRG2.doc](#)>

**MODEL YEAR 1995-2000 WINDSTAR WHEEL CONCERN**

To: CCRG Chairman  
Subject: 1995-2000 Windstar Wheel Concerns

**CONCERN DESCRIPTION:** Allegations of wheel nuts with insufficient torque and loose wheel studs/bolts on 1995-2000 Windstar vehicles were reported to the CCRG by Ford of Canada - PCSD.

**CONCERN INVESTIGATION:** The following data was investigated to assess this concern:  
**Field Data:** (Approximately 1.5 Million vehicles were sold during 1995-2000)

(1) CQIS claims:

The indicator summary for 1995-2000 model years is as follows:

EDSR 11 wheel separated

CAC 33 wheel separated

NHL 6 wheel separated

Note: 21 out of 30 i.e. 42% vehicles had wheels removed under warranty per AWS prior to incident

(2) AWS claims:

19 total claims of wheel separation were reported in AWS (cut-off date 6/30/00). Twelve (12) out of Nineteen (19) i.e. 63% confirmed instances where wheels were removed and reinstalled prior to separation.

(3) Accidents and Injuries: Total Four (4) were reported, three (3) claims and 1 lawsuit which were closed.

(4) No assembly issues: The nut runout torque capability (CPR) was 1.4 -1.5 (Acceptable 3 Sigma is 1.33) between Jan. 95 and Jan. 00 using a pneumatic nut runner. A D.C nut runner has since been installed at Oakville Assembly Plant which increased the torque capability to 3 -11.

(5) No design or material defect issues: Review of Durability vehicle concerns for Model Years 1995-2001 conducted with all past wheels Design and Release Engineers on durability vehicles indicate that no wheel separation concerns were ever reported during testing. Also, material analysis of parts returned from two vehicles in the field performed by Ford Central Laboratories indicates that the studs met all material specifications.

(6) Mileage study: The average mileage of all claims for wheel separation is 26,000 which is high enough to reasonably assume that tires were likely removed for tire rotation as part of routine maintenance.

**ASSESSMENT OF EFFECT ON VEHICLE OPERATION:**

The customer will notice vibration and/or steering wheel rattle if lug nuts are loosening. This condition would gradually increase as wheel lug-nuts seat elongates. If left unchecked, it may lead to breaking of wheel studs and possibly the wheel separating from the wheel.

**RECOMMENDATION:**

No field action required since engineering analysis indicates that the wheel design is robust and since the majority of the incidents of wheels separating occurred after the wheels were removed when servicing the vehicle the condition may be related to improper service and/or maintenance. Also, this investigation does not indicate a defect trend in the field. Based upon this information, Windstar OPD Chassis Engineering and NAC Safety/Recall Engineering recommends closure of this concern.

Syed Hassan Samast (signed)  
(Syed Samast)  
Windstar OPD - Chassis

9/15/00  
Date

---

**From:** Sammet, Syed (S.H.)  
**Sent:** Friday, September 15, 2000 2:36 PM  
**To:** Name, Joseph (J.S.)  
**Cc:** Loop, James (J.R.); Molnemey, John (J.T.); Dearing-Thomton, Zandr (Z.F.); Seashore, Patricia (P.J.); Sammet, Syed (S.H.)  
**Subject:** CCRG - Wheel concern

Attached is the final version of the CCRG concern paper. I have included and changes made by you to the earlier version. This paper was reviewed with Pat Seashore. Please forward this to The CCRG committee for closure. Please call me regarding any questions you may



WHL\_CCRG2.doc

have.

1 REDACTED

ENR-004 03421

MODEL YEAR 1995-2000 WINDSTAR WHEEL CONCERN

To: CCRG Chairman  
Subject: 1995-2000 Windstar Wheel Concern

**CONCERN DESCRIPTION:** Allegations of wheel nuts with insufficient torque and loose wheel studs/bags on 1995-2000 Windstar vehicles were reported to the CCRG by Ford of Canada - FCSD.

**CONCERN INVESTIGATION:** The following data was investigated to assess this concern:  
**Field Data:** (Approximately 1.5 Million vehicles were sold during 1995-2000)

(1) CQIS claims:

The indicator summary for 1995-2000 model years is as follows:

HDSR 11 wheel separated

CAC 33 wheel separated

NHL 6 wheel separated

Note: 21 out of 30 i.e. 42% vehicles had wheels removed under warranty per AWS prior to incident

(2) AWS claims:

19 total claims of wheel separation were reported in AWS (cut-off date 6/30/00). Twelve (12) out of Nineteen (19) i.e. 63% confirmed instances where wheels were removed and reinstalled prior to separation.

(3) Accidents and injuries: Total Four (4) were reported, three (3) claims and 1 lawsuit which were closed.

(4) No assembly issues: The net nut/runner torque capability (CPK) was 1.4 - 1.5 (Acceptable 3 Sigma is 1.33) between Jan. 95 and Jan. 00 using a pneumatic nut runner. A D.C. nut runner has since been installed at Oakville Assembly Plant which increased the torque capability to 5 - 11.

(5) No design or material defect issues: Review of Durability vehicle concerns for Model Years 1995-2001 conducted with all past wheel Design and Release Engineers on durability vehicles indicates that no wheels separation concerns were ever reported during testing. Also, material analysis of parts returned from two vehicles in the field performed by Ford Central Laboratories indicates that the studs met all material specifications.

(6) Mileage study: The average mileage of all claims for wheel separation is 26,000 which is high enough to reasonably assume that tires were likely removed for the rotation as part of routine maintenance.

**ASSESSMENT OF EFFECT ON VEHICLE OPERATION:**

The customer will notice vibration and/or steering wheel nibble if lug nuts are loosening. This condition would gradually increase as wheel lug-nuts seat elongates. If left unchecked, it may lead to breaking of wheel studs and possibly the wheel separating from the wheel.

**RECOMMENDATION:**

No field action required since engineering analysis indicates that the wheel design is robust and since the majority of the incidents of wheels separating occurred after the wheels were removed when servicing the vehicle the condition may be related to improper service and/or maintenance. Also, this investigation does not indicate a defect trend in the field. Based upon this information, Windstar OPD Chassis Engineering and NAC Safety/Recall Engineering recommends closure of this concern.

\_\_\_\_\_  
Syed Hasan Sarmast (signed)  
(Syed Sarmast)  
Windstar OPD - Chassis

9/15/00

Date

---

**From:** Name, Joseph (J.S.)  
**Sent:** Tuesday, September 05, 2000 6:26 PM  
**To:** Seashore, Patricia (P.J.)  
**Subject:** Windsor Wheel CCRG Item

Pat... If we are closing this item, we need to do so at next Tuesday's CCRG meeting to avoid the lateness of the 90 day metric from going to Chris T and RPJ. Syed completed his warranty search and there appears to be no trend but we need him to check repair history on the vehicles to see if the wheels were removed prior to the incidents. I talked with Syed earlier today and we plan to sit down with you on Friday.

**Joe Name**  
NAC - SafetyRecalls  
Phone: 39-08133; Fax: 39-06002; Cube; Bldg #1, 1GB25

WINDSTAR  
ONLY

**ECI Tracker Reports Referencing Wheel Lug Nut and/or Studs**  
**Brake Wear, Wheel, Lug, Nut and Studs**

Page 10 of 12 pages

~~needed~~  
there are  
~~so many~~ search  
~~for~~ ~~which~~ the  
shell "in fact!"

**ECI Tracker Reports Referencing Wheel Lug Nuts and/or Brake  
Search Words: Wheel, lug, nut and Brake**

**ECI Tracker Imports Referencing Wheel, Lug Nut and/or Stock  
Screws, Washers, Wheel, Lug, Nut and Stock**

**SCI Teacher Reports Referencing Wheel/Lug Nut and/or Stack**  
**Stack: Wheel; Wheel, Lug, Nut and Stack**

ODI No	Model Yr	Wh	Mile	Summary	Failure Date	Date of Letter
781573	1998			MISSING OR IMPROPERLY ADJUSTED LUG NUTS ARE A FACTORY PROBLEM ON 1998 UNITS MANUFACTURED IN CANADA.		8-Jun-00
844810	1998 2FMDA514W0886463			VIBRATION FROM REAR DRIVERS SIDE WHEEL DUE TO 4 LUG NUTS FALLING OFF WHEEL, 52000 WHEEL WAS BEING SECURED BY 1 LOOSE LUG NUT.	5-Mar-00	5-Apr-00
888658	1998 2FMDA514W0886463			WHILE DRIVING AT 70 MPH 2 LUGS: NUTS CAME OFF, AND THE CONSUMER HAD TO PULL OVER TO THE SIDE OF THE ROAD. CONSUMER TOOK OFF THE HUB CAP AND NOTICED THAT TWO OF THE LUGS: NUTS CAME OFF, AND THE OTHER THREE WERE COMING OFF. THE STUDS 52000 SHEARED OFF INSIDE THE LUG NUTS. *AK	27-Mar-00	5-Apr-00
545765	1998			LUG NUTS BROKE OFF OF RIGHT FRONT TIRE AND HUB OF WHEEL/Brake DRUM, RESULTING IN TIRE FALLING OFF OF VEHICLE AND CAUSING DAMAGE TO VEHICLE. (OHIO TRAFFIC CRASH 8 REPORT). MJS	5-Apr-00	25-May-00
715402	1998 2FMDA514W0886463			1) ALL 5 LUGS: NUTS SHEARED OFF FROM THE RIGHT FRONT PASSENGER HUB, CAUSING THE WHEEL TO LEAVE THE VEHICLE. THE BODY OF THE VEHICLE TRAVELED APPROXIMATELY 300 FEET UNTIL IT STOPPED. 2) THE REAR BRAKES HAD TO BE REPLACED WITH NEW PADS AND ROTORS. DEALER COULDNT EXPLAIN WHY THIS WAS A PROBLEM. 3) THE NEXT DAY THE RIGHT PASSENGER MIRROR ELECTRICAL SYSTEM NO LONGER WORKED. 4) THE PARKING BRAKE CONSISTENTLY DOES NOT URN/ENGAGE AFTER USE. WE NO LONGER USE IT, POSSIBLY CREATING A SAFETY HAZARD. 5) THE VEHICLE INTERMITTENTLY STALLS OUT AT LOW SPEEDS OR UPON STOPPING. ADDITIONALLY THE INITIAL GEARS SHIFT HARD AND LOUD. 6) THE REAR 44000 SEAT WILL NOT MOVE ON THE TRACK. *AK	28-Nov-00	28-Nov-00
262365	1998 2FMDA514W0886463			THE LEFT WHEEL LUGS: NUTS BROKE OFF OR SHEARED OFF WHICH MAY CAUSE THE WHEEL TO FALL OFF. OCCURRED TWICE. PLEASE PROVIDE FURTHER INFORMATION. *AK	1-Apr-00	21-Jan-00
717738	1998 2FMDA514W0886463			MY WIFE WAS TURNING LEFT AT A RED LIGHT AND WAS WAITING FOR PEDESTRIANS TO CROSS THE STREET. AS SHE TURNED THE CORNER THE RIGHT FRONT TIRE SNAPPED OFF OF THE HUB AND ALMOST HIT A LAWYER! ALL FIVE OF THE STUDS BROKE OFF, THE METAL INDICATED THEY WERE FRESH BREAKS. THERE WAS NOT ANY INDICATION OF THE NUTS BEING LOOSE. THE NUTS WERE STILL SCREWED ON THE STUDS. THE WHEEL AND NUTS DID NOT LOOK SCARRED AS IF THEY HAD BEEN LOOSE. PRIOR TO THE WHEEL COMING OFF THERE HAD BEEN NO SHIMMY OR VIBRATION AT ALL. I HAD DRIVEN THE VEHICLE THE PREVIOUS NIGHT AND HAD NOT FELT ANYTHING OUT OF THE ORDINARY. SHE HAD ONLY ACCELERATED FROM THE LEFT TURN POSITION ABOUT 15FT AND COULD NOT HAVE BEEN GOING FASTER THAN 5 MPH. THE VEHICLE HAD NOT BEEN SERVICED AFTER WE PURCHASED IT. THANK GOD SHE WAS NOT ON THE	21-Jun-00	28-Jan-00

857486	1998	PASSENGER'S SIDE FRONT TIRE BOLTS SHEARED OFF AND WHEEL ROLLED DOWN THE HIGHWAY. CAR RESTED ON FRONT DISC BRAKE, THEN IT CAME TO A STOP. MECHANIC SAID 10700 THE BOLTS BROKE OFF, AND NUTS WERE STILL ON THEM. "AK" WAS MAKING A LEFT TURN, RIGHT FRONT PASSENGER'S WHEEL FLEW OFF, THIS WAS CAUSED BY 5 OF THE WHEEL BOLTS BREAKING OFF IN HALF. IT MADE A LOUD BOOM & THEN A RANG TYPE OF NOISE. CONTACTED FORD & INFORMED NOT THEIR FAULT & WILL NOT PAY FOR 14 REPAIRS. "AK"	6-Jun-00	24-Feb-00
✓ 858005	1998 2FMZA514703	WHILE DRIVING WHEELS ON RIGHT FRONT PASSENGER'S SIDE CAME COMPLETELY OFF. ALL LUGBOLTS WERE BROKEN WITH NO SIGN OF WEAR AND TEAR. VAN WAS TOWED TO A DEALERSHIP. PLEASE PROVIDE ANY FURTHER INFORMATION."AK"	9-Mar-00	19-Apr-00
→ 858080	2000	CONSUMER WAS AT THE STOP LIGHT AND WHILE TURNING RIGHT FRONT PASSENGER'S WHEEL FELL OFF. VEHICLE WAS TOWED TO THE DEALERSHIP. MECHANIC TOLD CONSUMER THAT 10700 WHEEL LUGS: NUTS WERE TOO TIGHT, AND ALL FIVE WERE SEVERED."AK" WHILE DRIVING AT 70 MPH FRONT RIGHT WHEEL LUGS SHEARED OFF CAUSING WHEEL TO 30400 COME OFF."AK" *SLC 22800 FRONT WHEEL BOLTS FELL OFF, AND TIRE CAME OFF. "AK"	16-Jun-00	14-Jun-00
✓ 858088	1998 2FMZA514008	LEFT FRONT WHEEL LUG BOLTS SHEARED OFF CAUSING THE TIRE AND WHEEL TO COME OFF 32800 AND HIT ANOTHER VEHICLE. CONSUMER REQUESTS REIMBURSEMENT. "SLC"	2-Jun-00	23-Jun-00
873132	1998 2FMZA514008	LEFT FRONT WHEEL LUG BOLTS SHEARED OFF CAUSING THE TIRE AND WHEEL TO COME OFF 32800 AND HIT ANOTHER VEHICLE. CONSUMER REQUESTS REIMBURSEMENT. "SLC"	8-Nov-00	17-Oct-00
873723	1998 2FMZA514008	MY CONCERN IS WHY ALL FIVE STUDS THAT HOLD THE WHEEL ON BROKE AT ONCE, RESULTING IN LOSS OF STEERING. THE BODY SHOP AND THE INSURANCE AGENT COULD OFFER NO GOOD REASON FOR THIS FAILURE, THEY SAID MAYBE THE LUG NUTS WERE OVER TIGHT. NOW I'M CONCERN ABOUT IT HAPPENING AGAIN TO ANOTHER WHEEL IF SOMETHING IS DEFECTIVE. "AK"	5-Dec-00	19-Dec-00
740848	1998 2FMZA514008		7-Feb-01	18-Feb-01



2003-004 0002

~~SECRET~~

~~SECRET~~

---

**From:** Marin, Nick (N.)  
**Sent:** Tuesday, November 07, 2000 7:29 AM  
**To:** Sammut, Syed (S.H.)  
**Cc:** Molnemay, John (J.T.); Neme, Joseph (J.S.)  
**Subject:** MY '99 WINDSTAR KEEPS BREAKING FRONT WHEEL STUDS

IT SEEMS THAT YOU ARE AWARE OF MY PROBLEMS. BACK IN JULY/2000 I ALLEGEDLY FORD IN TILBURY REPAIRED MY VAN WHEN ALL 5 STUDS ON THE RH FRONT WHEEL WERE TORN OFF. THEY SENT YOU A COPY OF THE REPAIR BILL OR AT LEAST THEY INFORMED YOU ABOUT THE PROBLEM. SOON AFTER THE REPAIR WAS DONE I GAVE ALL THE REMAINERS OF THE STUDS AND THE RIM TO JOE NEME FOR TESTING. HAVE YOU DONE ANY TEST ON THEM? WHAT DO YOU THINK WOULD BE THE PROBLEM?  
AN ANSWER FROM YOU WOULD BE GREATLY APPRECIATED. THANK YOU.

[REDACTED]

---

**From:** [REDACTED]  
**Sent:** Friday, October 27, 2000 8:54 AM  
**To:** Name, Joseph (J.S.)  
**Subject:** Windsor Broken Studs Test

Hi Joe,  
I hope you remember me. Early last August I came to your office and gave you the remainders of the 5 studs and the rim from my '99 WINSTAR. They broke while I was driving and the wheel fell off. Would you, please tell me if you did any test on those studs and what was the result of the test?

Thank you  
[REDACTED]

**From:** [REDACTED]  
**Sent:** Thursday, November 23, 2000 7:31 AM  
**To:** Name, Joseph (J.S.)  
**Cc:** McNamey, John (J.T.)  
**Subject:** RE: this is second time the wheel fell off.

Thank you for the note, Joe.

As you know it's been two weeks since the van was fixed and so far no problems. Next week I will go to Moe Campbell for a check up on that wheel. Hope everything will be fine. I am, still, very eager to find out the results of the lab test.

Once again, Thank you.

[REDACTED]

[REDACTED]

---Original Message---

**From:** Name, Joseph (J.S.)  
**Sent:** Wednesday, November 22, 2000 4:49 PM  
**To:** [REDACTED]  
**Cc:** McNamey, John (J.T.); Seashore, Patricia (P.J.); Samast, Syed (S.H.); Kurnow, Carl (C.N.); Goring, Kimberly (K.L.)  
**Subject:** FW: this is second time the wheel fell off.

Engineering is concerned when they hear of a condition like the one you originally expressed last summer when the wheel came off your vehicle. Unfortunately, you did not get timely response back on what all happened after your initial contact. Hopefully this note will help you understand some other items that were done regarding your concern.

As you recall, immediately after you notified the PVT manager I sent you an e-mail to get specific information on your vehicle so that I can present your concern to the Critical Concern Review Group (CCRG). This group was established to review potentially critical customer concerns and is chaired by the Automotive Safety Office and includes personnel from Engineering, Vehicle Operations, Research, Legal, and Customer Service. I presented your concern to the committee on the Tuesday following your original notification and you were contacted by my engineer John who made arrangements to meet with you to get the parts off your vehicle. This group takes all concerns very seriously!

Based on the data you provided, you were also informed of the proper torque specification for lug nuts on your vehicle.

All corporate data bases were searched for other similar concerns on all 1995-2001 Windstars not just the model year of your vehicle. Based on a thorough review of all the data bases, it was determined by the committee that there is not a trend of wheel separation on Windstar vehicles.

Parts from your vehicle were also sent to the materials lab for analysis and as you know, engineering has not received a report out from the lab yet. As John told you, results from this analysis will be provided to you when available.

Your second incident was a concern to us as it was to you and that is why I sent John and Syed to look at your vehicle to see if there is something uniquely different with your vehicle compared to others. At the review, it was discovered that the wheel on your vehicle that was repaired and replaced by a Ford Dealership had witness marks on the back side that may indicate that it was not sitting properly on the rotor/hub. We removed the parts and are bring them back to see if the same witness marks exist on your original wheel to help determine where they may of come from. John may be contacting you to look at your vehicle again if that

wouldn't be too much of an imposition.

May I suggest that you use John and me as your contacts on this item. I understand that notes and requests for information have gone to many different areas. Unfortunately instead of helping to get you a good response, this has added confusion.

—Original Message—

From: [REDACTED] Seashore, Patricia (P.J.)  
Sent: Wednesday, November 15, 2000 1:00 PM  
To: [REDACTED]  
Cc: [REDACTED]  
Subject: RE: this is second time the wheel fell off.

Am I satisfied how the whole problem was handle ? Definitely NOT. Why ?

1. First time it happened, NOBODY paid any attention to me. Wasn't it a serious enough safety incident to have somebody looking into it ? Nobody did not even bother answering my E mail. After they repaired the minivan and I paid for it Joe Name ask me for the parts to do some tests on them. Results... Nobody knows, yet !!!

2. Second time , after two weeks of silence John McInerney was the only person to answer my calls and he actually did something for me. Syed Samast did come with John to see the problem, but the way he tried to solve the problem was not appropriate at all. Oh, you've got a broken stud ? We give some new parts and we get rid of you. You are not the only problem we have. I showed him what I think was the problem and he blamed Lally Ford for not fixing it right the first time. Any tests done on the parts ? Who knows ! When I finally talked to Keri Kumrow he said , "yes, I got your E mail and this may be your priority but I got 1000 of other priorities." What should I say to such an answer?

Patricia, I am a Ford Motor Company employee and I hoped that with the way we can communicate would be easy for me to explain to the right people what happened. But it looks like just about everybody chooses to "click DELETE," and ignore me.

How about the rest of the people who buy Ford vehicles ? Do you choose to ignore them, as well ?

I was LUCKY TWICE. If that wheel would fall off on the highway me and my family would be history now. Do you need to have some DEAD people in order to look at this kind of problems ? Isn't this a serious enough safety issue worth of looking into ?

Windstar minivan is supposed to be one of the safestest FAMILY vehicle on the road. Is this how you show you concern for the customer SAFETY and SATISFACTION ? Should I recommend this vehicle to somebody else ?

To answer your last question . Yes, at 1000Km after repair I will go to the dealer for a check up.

[REDACTED]

—Original Message—

From: Seashore, Patricia (P.J.)  
Sent: Wednesday, November 15, 2000 6:35 AM  
To: [REDACTED]  
Subject: PW: this is second time the wheel fell off.

I was obviously not aware of all the background on your vehicle; that it had happened previously and that you had been doing work on the vehicle. Safety is my top concern, as well as reassuring you that we are concerned about customer satisfaction for all. One of the engineers in my group met with you last week; Syed Samast. Are you pleased with the assistance you received from Syed? Do we have some follow up steps in place with you or do we need to add some?

Patricia J. Seashore  
Bldg. 1 11F021 Phone: 313-32-36585  
Windstar/Villager Chassis Manager  
Lifestyle Vehicles Brakes/Tires/Wheels/Steering Chassis Manager

—Original Message—

From: [REDACTED]  
Sent: Wednesday, November 01, 2000 7:30 AM

To: Sesthers, Patrick (P.J.)  
Cc: Kunzow, Carl (C.H.)  
Subject: RE: this is second time the wheel fell off.

Pat, this is not the first time the RH side front wheel tear down the stud. First time it happened in JULY/2000. At that time I was comming from work and the wheel came off **COMPLETELY TEARING OFF ALL 5 STUDS**. I had about 28000Km on board at that time. I sent notes to CARL K. and some other people but nobody paid any attention to me. Everybody blamed me FOR ROTATING THE TIRE MYSELF AT 34000Km. So, after driving the vehicle for another 20000Km- the wheel fell off because of me. **Lally Ford Inc., Timmins** (Ford dealer where I bought the vehicle) REPAIRED THE MINIVAN WITH THEIR CERTIFIED TECHNICIANS and I paid for it (\$1778). Here we go again, 108000KM AND THREE MONTH LATER THE EXACTLY SAME WHEEL DOES THE SAME THING AGAIN. Within these three month I did not do anything to the vehicle. Am I the SCAPE GOAT again? This would be an easy way out. Pat, **WOULD YOU DARE TO TAKE YOUR FAMILY FOR A DRIVE ON THE HIGHWAY IN THIS VEHICLE ?**

Thank you for paying attention.  
[REDACTED]

—Original Message—

From: Sesthers, Patrick (P.J.)  
Sent: Tuesday, October 31, 2000 2:45 PM  
To: [REDACTED] Kunzow, Carl (C.H.)  
Cc: Jashurun, David (D.R.)  
Subject: FW:

[REDACTED] - I asked Carl Kunzow to follow up and obtain additional information from you regarding the service that had been done to your Windstar. Have you ever had the wheels removed for any kind of service? If so, when?

—Original Message—

From: Sesthers, Patrick (P.J.)  
Sent: Friday, October 27, 2000 11:41 AM  
To: Kunzow, Carl (C.H.)  
Cc: Samast, Syed (S.H.); Loop, James (J.R.); Merkley, Sherif (S.); Jashurun, David (D.R.); Maitte, Bill (B.)  
Subject: RE:

Carl: please have the OAP FCSD PVT rep research this vehicle and determine what service has been done to it – specifically if the wheels have ever been removed. If the answer is yes, then we can only assume it was improperly serviced (under or over torqued).

—Original Message—

From: Kunzow, Carl (C.H.)  
Sent: Friday, October 27, 2000 11:36 AM  
To: Sesthers, Patrick (P.J.)  
Cc: Samast, Syed (S.H.); Loop, James (J.R.); Merkley, Sherif (S.); Jashurun, David (D.R.); Maitte, Bill (B.)  
Subject: FW:

I think that someone should look at this specific vehicle.

—Original Message—

From: Marin, Nick (N.)  
Sent: Friday, October 27, 2000 11:16 AM  
To: Jashurun, David (D.R.)  
Cc: Kunzow, Carl (C.H.); Lang Dr., Jeorgen (J.K.); Plascencia, Stanislav (S.I.); Porter, Dave (D.); Traynor, Greg (G.P.); Zibat, Mark (M.)  
Subject:

GENTLEMEN, I NEED YOUR HELP. PLEASE, READ MY ATTACHMENT.

THANK YOU  
[REDACTED]

<< File: '99 WINDSTAR.doc >>

---

**From:** Molnarney, John (J.T.)  
**Sent:** Tuesday, November 14, 2000 7:34 AM  
**To:** [REDACTED]  
**Cc:** Neme, Joseph (J.S.); Sammest, Syed (S.H.); Molnarney, John (J.T.)  
**Subject:** RE: broken stud test

'morning Nick, I dropped your firewheel off at noon on thurs, came back to drive to Chicago area on other company stuff. Back at 2AM Saturday morn, off to Phoenix Sunday at 7PM, just got off the "red eye" at 6:45AM this morning! Haven't had time to check ANYTHING. How bout you Syed?

-----Original Message-----

**From:** [REDACTED]  
**Sent:** Monday, November 13, 2000 9:33 AM  
**To:** Neme, Joseph (J.S.); Molnarney, John (J.T.)  
**Subject:** broken stud test

Good morning gentlemen,

Any news on the test of the broken stud from my '99 WINDSTAR ?

**From:** [REDACTED]  
**Sent:** Friday, November 03, 2000 11:20 AM  
**To:** Name, Joseph (J.S.)  
**Cc:** McInerney, John (J.T.)  
**Subject:** RE: '99 windstar broken stud test

Joe,

Thank you very much for answering. I am on light duty right now (broken leg in august) so I am steady days for another 4 weeks. Whenever your engineer is available I will be there to show him the van.

John,

I hope you receive this message as well, please let me know when you or your man is available. E-mail me, or call me at [REDACTED]. Page me at [REDACTED]

Thanks to both of you,  
[REDACTED]

—Original Message—

**From:** Name, Joseph (J.S.)  
**Sent:** Friday, November 03, 2000 10:03 AM  
**To:** [REDACTED]  
**Cc:** McInerney, John (J.T.)  
**Subject:** PW: '99 windstar broken stud test  
[REDACTED]

I was out of the office when you sent the letter and my e-mail should of notified you. I spoke with one of our engineers this morning and just learned that you had another incident with your wheel at the same vehicle position. I want to have the engineers look at your vehicle at the dealership. They may want to take back some parts for analysis. Do you still work the midnight shift? What dealership/time works best for you next week? Please let John McInerney know so he can work out the details with the dealership and the wheel engineer... thanks

—Original Message—

**From:** [REDACTED]  
**Sent:** Tuesday, October 31, 2000 6:57 AM  
**To:** Name, Joseph (J.S.)  
**Subject:** '99 windstar broken stud test

Joe, I did sent you a message last week regarding the result of the broken stud from my '99WINDSTAR.

DID YOU RECEIVE IT? AN ANSWER WOULD BE VERY MUCH APPRECIATED.

Thank you  
[REDACTED]

Article No.  
98-5A-4

- BRAKES—PREVENTING BRAKE VIBRATION—  
SERVICE TIP
- WHEELS—PROPER LUG TORQUE PROCEDURES—  
SERVICE TIP

FORD: 1972-97 THUNDERBIRD  
1978-86 LTD  
1976-97 MUSTANG  
1981-97 CROWN VICTORIA  
1982-88 EXP  
1982-98 ESCORT  
1984-94 TEMPO  
1986-97 TAURUS  
1986-93 FESTIVA  
1989-97 PROBE  
1994-97 ASPIRE  
1995-98 CONTOUR

LINCOLN-MERCURY: 1979-83 MONARCH, ZEPHYR  
1979-97 COUGAR  
1980-83 MARK VI  
1980-98 CONTINENTAL, TOWN CAR  
1981-86 LYNX  
1983-86 MARQUIS  
1984-92 MARK VII  
1984-94 TOPAZ  
1986-97 SABLE  
1987-89 TRACER  
1987-97 GRAND MARQUIS  
1991-94 CAPRI  
1991-97 TRACER  
1993-98 MARK VIII  
1995-98 MYSTIQUE

LIGHT TRUCK: 1979-86 BRONCO  
1979-87 ECONOLINE, F-150-350 SERIES  
1984-90 BRONCO II  
1984-97 RANGER  
1986-97 AEROSTAR  
1986-97 F SUPER DUTY  
1991-97 EXPLORER  
1993-97 VILLAGER  
1995-98 WINDSTAR

- BRAKES—PREVENTING BRAKE VIBRATION—  
SERVICE TIP
- WHEELS—PROPER LUG TORQUE PROCEDURES—  
SERVICE TIP

Article No.  
98-5A-4  
Cont'd.

## 1997 EXPEDITION 1998 NAVIGATOR

**ISSUE:** The use of air impact tools to tighten wheel lug nuts can lead to overtightened and/or unevenly tightened wheel lug nuts. Air Impact tools typically used for wheel lug nut removal and installation can generate up to 475 N·m (350 lb·ft) of torque. Overtightened and/or unevenly torqued wheel lug nuts may cause:
 

- Brake vibration
- Distortion of the wheel hub
- Distortion of the brake rotor
- Brake rotor runout
- Damage to the wheel
- Damage to the wheel nuts and studs

**ACTION:** All wheel lug nuts should only be tightened to specification using a torque wrench or by using the Rotunda ACCUTORQ 184-R0314 or equivalent on a 1/2" drive air impact tool. The "ACCUTORQ" lug nut sockets limit the torque of the air impact tool, preventing overtightening or uneven tightening of the wheel lug nuts. The torque limiting devices (regulators) on air impact tools will not reduce the output torque enough to prevent overtightening of the wheel lug nuts.

**NOTE:** REFER TO THE APPROPRIATE SERVICE MANUAL OR THE CHART IN FIGURE 1 FOR THE CORRECT WHEEL LUG NUT TORQUE SPECIFICATION. THE CHART IN FIGURE 1 ALSO PROVIDES THE CORRECT "ACCUTORQ" LUG NUT SOCKET TO USE.

The "ACCUTORQ" socket is intended for lug nut installation, not removal. When using the "ACCUTORQ" socket, the output torque of the air impact tool must be set to 217-339 N·m (160-250 lb·ft), usually this will be the lowest setting on the air impact tool.

The "ACCUTORQ" lug nut sockets are available through Rotunda Equipment. The four-piece set (184-R0314) fits most Ford Motor Company cars and light trucks. The tool set consists of four (4) lug nut sockets and a storage case. The set can be ordered by calling Rotunda Equipment at 1-800-ROT-UNDA (768-8632).

**CAUTION: AIR IMPACT TOOLS SHOULD NOT BE USED TO TIGHTEN WHEEL LUG NUTS UNLESS THE "ACCUTORQ" LUG NUT SOCKET OF THE CORRECT SPECIFICATION IS USED.**

**NOTE: DO NOT USE AIR IMPACT TOOLS ON LOCKING WHEEL LUG NUTS. THEY ARE TO BE HAND-TORQUED ONLY.**

**OTHER APPLICABLE ARTICLES: NONE**

**SUPERSEDES: 97-17-6**

**WARRANTY STATUS: INFORMATION ONLY**

**CASIS CODES: 301000, 303000, 306000**

## ADDITIONAL SOCKETS

VEHICLE	YEAR	MM	INCH	SOCKET COLOR
<b>FORD</b>				
Aerostar	1984-87	21mm	5/8"	Light Brown
Cougar	1990-93	19mm-24"	10mm	Gray
Crown Victoria	1991-97	13/16"	10mm	Dark Brown
E-Series	1990	21mm	5/8"	Light Brown
Escort	1991-95	21mm	5/8"	Light Brown
Expert	1992-95	19mm-24"	10mm	Gray
EXP	1992-95	19mm-24"	10mm	Gray
Focus	1998-99	21mm	5/8"	Light Brown
Girod	1976-82	13/16"	10mm	Dark Brown
LTD	1976-82	13/16"	10mm	Dark Brown
Mustang	1976-87	13/16"	10mm	Dark Brown
Pinto	1971-82	21mm	5/8"	Light Brown
Taurus	1985-97	19mm-24"	10mm	Gray
Taurus	1994-94	19mm-24"	10mm	Gray
Thunderbird	1987-97	19mm-24"	10mm	Gray
Thunderbird	1979-89	13/16"	10mm	Dark Brown
<b>MERCURY</b>				
All Models	1990-91	13/16"	10mm	Dark Brown
<b>MITSUBISHI</b>				
Carisma	1991-94	21mm	5/8"	Light Brown
Colt	1978-95	13/16"	10mm	Dark Brown
Cougar	1992-97	19mm-24"	10mm	Gray
Cougar	1973-88	13/16"	10mm	Dark Brown
Lancer	1991-92	19mm-24"	10mm	Gray
Magnum	1990-93	13/16"	10mm	Dark Brown
Mystique	1995-95	19mm-24"	10mm	Gray
Naperville, Zephyr	1979-81	13/16"	10mm	Dark Brown
Sabre	1988-97	19mm-24"	10mm	Gray
Tempo	1984-94	19mm-24"	10mm	Gray
Tribeca	1991-97	21mm	5/8"	Light Brown
Topper	1997-98	21mm	5/8"	Light Brown
Grand Marquis	1991-97	19mm-24"	10mm	Gray
<b>LIGHT TURBO</b>				
E-150/E-150	1978-97	13/16"	10mm	Dark Brown
EF-250/350	1980-97	7/8"	14mm	Turquoise
EF-350/450 (Dual Power)	1984-97	7/8"	14mm	Turquoise
F-Super Duty	1988-97		14mm	NA
Aspen	1990-97	19mm-24"	10mm	Gray
Bronco	1979-90	13/16"	10mm	Dark Brown
Bronco II	1984-93	19mm-24"	10mm	Gray
Cougar	1973-82	21mm	5/8"	Black
Diplomat	1991-97	13/16"	10mm	Dark Brown
Ranger	1994-97	19mm-24"	10mm	Gray
Windstar	1993-95	13/16"	10mm	Dark Brown
Villager	1990-97	21mm	5/8"	Light Brown
Expedition	1997	19mm-24"	10mm	Gray
Navigator	1998	19mm-24"	10mm	Gray

TB-4198-2

Figure 1 - Article 69-5A-4

---

## **TSB Article Number: 97-17-6**

---

**Brakes - Preventing Brake Vibration - Service Tip**

**Wheels - Proper Lug Torque Procedures - Service Tip**

---

**FORD:** 1972-1997 THUNDERBIRD  
1976-1997 CROWN VICTORIA, MUSTANG  
1982-1998 ESCORT  
1984-1994 TEMPO  
1986-1997 TAURUS  
1988-1993 FESTIVA  
1989-1997 PROBE  
1994-1997 ASPIRE  
1995-1998 CONTOUR

**LINCOLN-MERCURY:** 1979-1997 COUGAR  
1980-1998 CONTINENTAL, TOWN CAR  
1981-1986 LYNX  
1983-1986 MARQUIS  
1984-1992 MARK VII  
1984-1994 TOPAZ  
1986-1997 SABLE  
1987-1989 TRACER  
1987-1997 GRAND MARQUIS  
1991-1994 CAPRI[SPC]  
1991-1997 TRACER  
1993-1998 MARK VIII  
1995-1998 MYSTIQUE

**LIGHT TRUCK:** 1979-1996 BRONCO  
1979-1997 ECONOLINE, F-150-350 SERIES  
1984-1990 BRONCO II  
1984-1997 RANGER  
1986-1997 AEROSTAR  
1988-1997 F SUPER DUTY  
1991-1997 EXPLORER  
1993-1997 VILLAGER  
1995-1998 WINDSTAR  
1997-1997 EXPEDITION  
1998-1998 NAVIGATOR

---

This TSB article is being republished in its entirety to update the applicable models and years, and also expand the issue.

**ISSUE:** The use of air impact tools to tighten wheel lug nuts can lead to overtightened and/or unevenly tightened wheel lug nuts. Air impact tools typically used for wheel lug nut removal and installation can generate up to 475 N·m (350 lb·ft) of torque. Overtightened and/or unevenly torqued wheel lug nuts may

cause:

- Brake vibration
- Distortion of the wheel hub
- Distortion of the brake rotor
- Brake rotor runout
- Damage to the wheel
- Damage to the wheel nuts and studs

**ACTION:** All wheel lug nuts should only be tightened to specification using a torque wrench or by using the Rotunda ACCUTORQ 164-R0314 or equivalent on a 1/2" drive air impact tool. The "ACCUTORQ" lug nut sockets limit the torque of the air impact tool, preventing overtightening or uneven tightening of the wheel lug nuts. The torque limiting devices (regulators) on air impact tools will not reduce the output torque enough to prevent overtightening of the wheel lug nuts.

**NOTE: REFER TO THE APPROPRIATE SERVICE MANUAL OR THE CHART IN FIGURE 1 FOR THE CORRECT WHEEL LUG NUT TORQUE SPECIFICATION. THE CHART IN FIGURE 1 ALSO PROVIDES THE CORRECT "ACCUTORQ" LUG NUT SOCKET TO USE.**

The "ACCUTORQ" socket is intended for lug nut installation, not removal. When using the "ACCUTORQ" socket, the output torque of the air impact tool must be set to 217-339 N.m (160-250 lb-ft), usually this will be the lowest setting on the air impact tool.

The "ACCUTORQ" lug nut sockets are available through Rotunda Equipment. The four-piece set (164-R0314) fits 95% of all Ford Motor Company cars and light trucks. The tool set consists of four (4) lug nut sockets and a storage case. The set can be ordered by calling Rotunda Equipment at 1-800-ROT-UNDA (768-8632).

**CAUTION: AIR IMPACT TOOLS SHOULD NOT BE USED TO TIGHTEN WHEEL LUG NUTS UNLESS THE "ACCUTORQ" LUG NUT SOCKET OF THE CORRECT SPECIFICATION IS USED.**

**NOTE: DO NOT USE AIR IMPACT TOOLS ON LOCKING WHEEL LUG NUTS. THEY ARE TO BE HAND-TORQUED ONLY.**

**Other Applicable Articles: NONE**

**Supersedes: 95-6-4**

**Warranty Status: Information Only**

**OASIS CODES: 301000, 303000, 306000**

Figure 1 - Article 97-17-6

**FCSD Field Quality Engineer (FQE) Request**

Complete the FQE Support Request section of the form below (green borders).

If you have questions, contact Maria Lovelace (Milwaukee: 323-6561)

After the form is completed, save it on your hard drive and send via E-mail to: [Maria.Lovelace@ford.com](mailto:Maria.Lovelace@ford.com)

FCSD PQEs are trained engineers, familiar with all subsystems and vehicles. They visit dealership Service Departments and other Ford and Lincoln-Mercury service locations and fleets daily. PQEs can provide the following support services: Inspect vehicles for specific conditions; take photographs; recover and return failed components; locate vehicles for testing and/or inspection by other engineering personnel; perform test drives and record results.

NHTSA Investigation into Wiederter wheel lug nut breakage	
Model Year(s) 1998/1999/2000	Requestor's Name N. Villarruel
Vehicle Line(s) Windstar	Phone Number 313-322-7986
Mileage range All	E-mail Address NVILLARR
Part number(s)	Pictures/CQIB Reports? NR
Date Issued May 21, 2003	Due Date ASAP
Geographic or Climatic Concern?	
All geographic areas	
What specific information do you want recorded (measurements, etc.)?	Record Mileage and VIN Use LQ-4 to cover dealer cost of replacement.

NHTSA is conducting an investigation into Wiederter wheel lug nut breakage. To assist in Ford Engineering investigation, please obtain the following components from the field.  
Place priority on vehicles built in May/June of 1997.

Obtain five (5) sets of the following parts from each of the model year (97-99) listed above:

- 1) Wheel assemblies - 15 inch aluminum. Fronts only  
-1998 F7BA-1007-BD (15x6.0 Aluminum wheel)  
-1999/2000 XF2A-1007-CC (15 x 6.5 Aluminum Wheel)
- 2) Front rotors - (base part 1125)
- 3) Front hub and bearing assy (1104)
- 4) Lug nuts

Tag all parts with side removed (LH, RH) and with corresponding VIN.

Ship parts to attention:

Six Sigma Center  
15080 Commerce Drive North  
Dearborn, MI 48129

Attn: N. Villarruel 322-7986 or Syed Sarmat 390-1949

Send Maria a note when one is located and I will keep track of total.

**Assignment Allocation Do Not Fill In - FQE Office Use Only**

Assigned	FQE	Location	Assigned	FQE	Location
N/A	Don Christoff	Florida		Tom Hecker	Minnesota
	Tony Celarano	Co. Garage		Brian Hawn	Nevada
	Dave Cox	Texas		Gordie Kalitz	California
	Tony Diolisi	Colorado		Don Myers	Iowa
	John Demos	Michigan		Tom Peeler	Georgia
	Don Hammock	Texas		Dave Pilgrim	Pennsylvania
	Mack Haydik	Pennsylvania		Lynn Sonnen	Texas
	All	X		Ron Tower	Florida

**ASSIGNMENT NO. 98**

**FCSD Field Quality Engineer (FQE) Request**

Complete the PQB Support Request section of the form below (green headers).

If you have questions, contact Maria Lovelace (Mlovelac 323-6561)

After the form is completed, save it on your hard drive and send via E-mail to: Maria.Lovelace

FCSD PQEs are trained engineers, familiar with all subsystems and vehicles. They visit dealership Service Departments and other Ford and Lincoln-Mercury service locations and fleets daily. PQEs can provide the following support services: Inspect vehicles for specific conditions; take photographs; recover and return failed components; locate vehicles for testing and/or inspection by other engineering personnel; perform test drives and record results.

<b>Assignment Specifics</b>	
Model Year(s) 1998/1999/2000	Requestor's Name N. Villareal
Vehicle Line(s) Windsor	Phone Number 313-322-7986
Mileage range All	Email Address NVILLARR
Part number(s)	Pictures/CQIS Reports? NR
Date Issued 16 May 2003	Due Date ASAP
<b>What specific information and/or service are you requesting?</b>	
<b>Inspect vehicles and record information</b>	
Geographic or Climatic Context?	All geographic areas
What specific information do you want recorded (measurements, etc.)?	Record Mileage and VIN Use L04 to cover dealer cost of replacement.

**Describe below the concern you are investigating – Include information about the nature and severity of the concern.**

NHTSA is conducting an investigation into Windsor wheel lug nut breakage. To assist in Ford Engineering investigation, please obtain the following components from the field.

Place priority on vehicles built in May/June of 1997

Obtain five (5) sets of the following parts from each of the model year (97-99) listed above:

- 1) Non-failed wheel assemblies - 15 inch aluminum. Fronts only
  - 1998 F76A-1007-BD (15x6.0 Aluminum wheel)
  - 1999/2000 XF2A-1007-CC (15 x 6.5 Aluminum Wheel)
- 2) Front rotors - (base part 1125)
- 3) Front hub and bearing assy (1104)
- 4) Lug nuts

Tag all parts with side removed (LH, RH) and with corresponding VIN.

Ship parts to attention:

Six Sigma Center  
13000 Commerce Drive North  
Dearborn, MI 48129

Attn: N. Villareal 322-7986 or Syed Samiul 390-1949

Send Maria a note when one is found.

5/18/03 NY R6-A  
98 99 00  
11 11 11  
111 11 111 111

Assignment Allocation: Do Not Fill In - FOM Office Use Only					
Assigned	FQE	Location	Assigned	FQE	Location
X	Don Christoff	Florida	X	Tom Harlow	Minnesota
NA	Tony Colarossi	Co. Centers	X	Brian Howe	Nevada
X	Dave Cox	Texas	X	Gloria Kelly	California
X	Tony Dennis	Colorado	X	Don Myers	Iowa
X	John Donkin	Michigan	X	Tom Peeler	Georgia
X	Don Homanick	Texas	X	Dave Higgins	Pennsylvania
X	Mark Huyck	Pennsylvania	X	Lynn Johnson	Texas
				Ron Trower	Florida
ASSIGNMENT NO. 58					

WEBS HARDCOPY PARAMETERS REPORT

BASIC PARAMETERS

REQUESTOR: NORMAN HALL  
REQUEST DATE/TIME: 96/06/11 12:45:03  
REPORTS REQUESTED FOR: NORMAN HALL  
DESTINATION DEVICE: E3100005  
PRINT DATE/TIME: 96/06/11 12:45:03  
PAGE RETRIEVE DATE/TIME: 96/06/11 12:45:03

REPORT OPTIONS

HARD-COPY REQUEST-TYPE: ON-LINE REQUEST (LASTEST DATA)

LANGUAGE: ENGLISH

PART DATA RESTRICTIONS:  
NONE

SELECTION CRITERIA

NOTICE NUMBER:

PART NUMBER:

PART FUNCTION:

SEARCH NUMBER: A10633103

REPORTS REQUESTED

RELEASE / CONCISE COVER	DETAILED INFORMATION REQUEST
42 RELEASE SUMMARY CONTENTS OF ASSEMBLY	BAR ONLY
43 RELEASE CONCISE SUMMARY CONCISE DETAIL	
45 PART FUNCTION RELEASE X	ALERT DETAIL
MULTI-FUNCTION RELEASE	

ALERT NUMBER: A10603103 PAGE: 1 ALERT NUMBER: 1 PRINT DATE/TIME: 06/06/11 13:45  
 CRSC: TYPE: (U) ONE PPM  
 ORIGIN ACTIVITY: A NAD0 ORVILLE ASY  
 GENERATOR: NICHIBA WHEEL PHONE: 89-33320 DATE: 06/06/06 LOCATION: ORVILLE ASY. PLT 94  
 CRSC: 040401 NOTICE NO: RESOLVING NOTICE:  
 ALERT DESC: SECURE TIRE AND WHEEL ASY. TO VEHICLE (ALUMINUM WHEEL) ONLY  
 PROCEDURE #: CLY900 E1, 060  
 PRODUCTS AFFECTED: WINDSTAR  
 MODEL, COLOR: TW23 MODEL YEAR: 96  
 PLATES AFFECTED: NAD0  
 MFG CONCERN CODE: ING CONCERN CODE: INVALID: EFFECTIVE IN: OUT:  
 PROGRAM: DATE: INGRESION CODE: 000 DILP:  
 NET INGR. VAR. COST: NET INGR. TOOL COST: NET INGR. LBR COST:  
 NET INGR. MATER. COST: WT EFFECT:  
 UNIT MEASURE: APPENDIX:  
 SUPP DOC#: PROC. #CLY900 E1&90  
 INT'L. MANUAL REV: CR-PGA-413-EA

AFFECTED PARTS  
 AFFECTED PART NO.: F2DC 1013 AR APP PART DESC: NUT-WHEEL BOLT-L/3-25-IMP STD REC'D: Y  
 CRSC: / 040401 NOTICE: INTR: SUPPLY/LOCAL: AVAIL: FUNC REQD:  
 / SUPPLIER:

----- FURTHER DESCRIPTION/ALERT RESOLUTION/REASON FOR REJECTION ETC.

----- FURTHER DESCRIPTION/ALERT RESOLUTION/REASON FOR REJECTION ETC.

UNRCD: ACTIVITY: ENGINEERING DATE: 06/06/11  
 ALERT DESC:  
 A TORQUE PROCESS POTENTIAL STUDY WAS CONDUCTED ON THIS  
 OPERATION. IN INDICATES THAT THE PROCESS VALIDATION IS WELL  
 WITHIN THE DYNAMIC TORQUE SPECIFICATION, BUT THE MAXIMUM  
 NOMINAL TORQUE IS EXCEEDING THE SPECIFICATION.  
 ENGINEERING SPECIFICATION: 133.0 NM +/- 20.0 NM  
 DYNAMIC CAPABILITY: 1.42 PP. 1.35 FPA.  
 RESIDUAL INSPECTION LIMITS: 92.0 NM TO 183.6 NM  
 MINIMUM ENGINEERED TORQUE: 92.0 NM  
 THIS ALERT HAS BEEN ISSUED TO NOTIFY WHO OF THE MEDIUM  
 TORQUE VALUE THAT IS THE MEASURED OUTCOME OF THE PROCESS.  
 THE STUDY DATA IS AVAILABLE UPON REQUEST.  
 THE STUDY FOR THE STEEL RIMS FELL WITHIN THE ENGINEERING  
 SPECIFICATION. NO RESIDUAL Specs REQUIRED.

• -MORE-

-----  
-----  
-----

TYPE: (U) USE PWD -----468  
SUBJECT ACTIVITY: M229 CAVILLE RST DATE: 26/04/06  
ORIGINATOR:333320 REFERENCED: CAVILLE ASBY. WEST PHONE: C4  
SPEC: 844601 NOTICE NO: RECEIVING NOTICE:

DISCRETE APPROXIMATIONS

ITEMNO	DEPARTMENT	ITEMID	ACTIVITY	APPROVING MAN'S NAME	DATE APPROVED	APPROVAL
					-000	
0000	AR2062	AR2062	MEAD	MICHAL EARL	96/06/06	
X		MEAD		MEAD		
0000	Y702	TYP6677	MEAD	SCHMIDT, TOM J.	96/06/06	TRACIE, T.H.-SOUT RUE
X	AR2062	AR2062	MEAD	MEAD, D.	96/06/06	
X	AR2062	AR2062	MEAD	MICHAL EARL	96/06/11	

- 10 -

7300-204 0463

Concurrent # A10633103

Appendix B

Torque Process Potential Study Worksheet

Plant: O.A.P

Coring: WINDSTAR

Date: May 19, 96

## PROCESS INFORMATION:


Process No: CL7900 Element No: QBD DateMyte file name: Dyna 20 Resid: 20

Study By: Jerry C. Jack

Control: M101WIN

Description: Secure Tire Wheel Assy To Car L/S STEEL

## Torque Specifications (Nm):

Dynamic Mean: 132.0 Variance: ±20.0 Minimum (Static) \_\_\_\_\_ NmTool Codes: Processor: CAN 16 Actual: CAN 16 Plant #: \_\_\_\_\_Tool Manufacturer: CJP MULTI Model Number: \_\_\_\_\_Type: Air Shut-Off Clutch / Shaft / Transducer Reaction Absorbed: Y / NSocket Condition: Good Length of Extension: 3" Driver: Bolt / HammerSocket or Bit Size: 19 N-N Transducer: 371-2-NH Bay Location: \_\_\_\_\_Bolt #: \_\_\_\_\_ Nut #: ENAC 10.900 Part #: \_\_\_\_\_FULL STUDY  
SPOOL

## SKETCH OF OPERATION

On Test: None Trace Excessive Green Bands Y/NTorque Mean before adjustments: 132.6Remarks: STEEL RING EAST SIDE L/S

## Study Recap

POS #	SAMPLE SIZE	MEAN DYN	MEAN RESID	MEAN SHIFT	+3 SIGMA DYN	+3 SIGMA RESID	-3 SIGMA DYN	-3 SIGMA RESID	6 SIG RANG DYN	6 SIG RANG RESID	DYNAMIC Pp	DYNAMIC Ppk	RESIDUAL LOW	RESIDUAL HIGH
1	66	135.2	134.7	0.5	146.0	156.7	124.4	112.8	31.6	43.9	1.85	1.65	116.9	151.1
2	66	133.9	131.8	-2.6	146.9	147.4	121.0	113.2	26.0	36.2	1.57	1.47	113.0	145.1
3	66	134.5	137.5	3.0	147.7	157.7	121.3	117.4	26.4	46.3	1.51	1.40	124.0	158.7
4	66	133.0	143.8	10.8	147.1	167.0	120.5	120.7	26.6	46.3	1.38	1.47	139.1	137.5
5	66	133.1	134.4	1.3	145.9	155.5	120.2	113.3	26.7	42.2	1.56	1.35	121.2	155.4
(12194)														
2N9330 3.30 134.1 129.9 5.8 147.7 167.0 120.2 112.8 25.7 42.2 1.51 1.40 113 157.5														


TORSIONAL STUDY REPORT FORM

Plant: O.A.P.Outline: WINDSTARDate: 5-29-96

## PROCESS INFORMATION:

081Process No: Ch 7900 Element No:            Date/Shift No: None Run #: 29Study By: Laurie L. JackCorporation: W.I.B.I.W.I.NDescription: Assy Torque Stud Assembly To Vehicle "Steel Rins" R/5


## Torque Specifications (Nm):

Dynamic Mean: 133.0 Variance: ±32.9 Minimum (Static):        NmTool Codes: Processed: Lat 165 Adjust: Lat 165 Plant #:       Tool Manufacturer: C/P Quality Model Number:       Type: Air Shut-Off / Clutch / Stop / Transducer Reaction Absorbent: Y / NSocket Condition:        Length of Extension: 3" Driven: Bolt / NutSocket or Bit Size: 19 M.M. Transducer: 271-244-N Bay Location:       Bolt #:        Nut #: ER3C101200 Part #:       SKETCH OF OPERATIONOI Test: None / Trace / Excessive Green Bands  NTorque Mean before adjustments: 138.5Remarks: Mini Study "Steel Rins" west side" R/5Study Recap

NO	SAMPLE SIZE	MEAN DYN	MEAN RESID	MEAN SHIFT	+3 SIGMA DYN	RESID	-3 SIGMA DYN	RESID	6 SIGMA RANGE DYN	RESID	DYNAMIC Pp	Ppk	RESIDUAL LOW	HIGH
1	22	22	138.1	148.6	155.4	146.1	168.1	120.0	129.1	24.2	38.0	1.53	153.8	157.0
2	22	22	135.8	139.1	13.9	147.6	103.9	124.1	118.4	28.5	41.4	1.70	146	129.3 153.6
3	22	22	132.6	135.4	2.8	148.4	150.4	121.7	112.7	31.7	45.1	1.85	131	126.8 134.6
4	22	22	133.5	139.8	6.3	146.9	160.9	121.1	117.7	24.8	44.2	1.61	157	129.6 160.0
5	22	22	133.3	146.3	7.0	146.5	167.0	131.0	113.6	34.5	62.4	1.63	167.3	155.7
6/10	110	110	139.7	140.5	6.9	147.6	168.1	120.0	112.9	27.4	55.2	1.53	146	125.8 160.0

Plant: O.A.P.Casing: WINDSTARDate: May 17, 1986**PROCESS INFORMATION:**Process No: CL7800 Element No: 282 Date Mynt Mfr mkt Dyn: 21 Resid: 21Study By: John F. Jack Control: DISWINDescription: Secure tree & shield base to case L12 ALUMINUM

Torque Specification (N.m):

Dynamic Mean: 133.0 Variance: ±30.0 Minimum (N.m): 80Tool Codes: Program: Cav 167 Actual: Cav 167 Part #: \_\_\_\_\_Tool Manufacturer: C/P MULTI Model Number: \_\_\_\_\_Type: As Shut Off / Clutch / Gear / Transducer Reaction Absorbed: Y / NSocket Condition: Good Length of Extension: 3" Driver: Bolt / NutSocket or Bit Size: 19 M.M. Transducer: 271-2-N-N Bay Location: \_\_\_\_\_Bolt #: \_\_\_\_\_ Nut #: 5300101300 Part #: \_\_\_\_\_Part: 5300101300  
Alt#: 1**SKETCH OF OPERATION**Off Test: None / None Executive Green Band: Y / NTorque Mean before adjustments: 125.6Remarks: All mounting pins East Side L15

Study Recap EXP LIMITS: 92.0 NM to 159.0 NM



OS #	SAMPLE SIZE	MEAN DYN	MEAN RESID	MEAN SHIFT	+3 SIGMA DYN	+3 SIGMA RESID	-3 SIGMA DYN	-3 SIGMA RESID	6 SIGMA RANGE DYN	6 SIGMA RANGE RESID	DYNAMIC P.D.	RESIDUAL P.D.	RESIDUAL LOW/HIGH	
1	66	66	133.5	120.0	135	146.1	145.5	121.0	94.5	25.1	61.0	1.60	1.55	10.4 143.2
2	66	66	136.4	118.9	145.5	147.0	146.8	121.9	93.0	25.9	53.7	1.60	1.98	101.7 143.7
3	66	66	133.1	123.5	9.6	147.3	132.6	119.0	94.4	28.3	52.3	1.42	1.41	101.2 143.2
4	66	66	133.4	121.7	6.7	147.5	131.9	119.3	93.4	28.1	50.5	1.42	1.39	10.4 145.6
5	66	66	133.0	123.5	9.3	145.0	143.7	120.5	103.2	34.7	70.4	1.64	1.63	106.6 140.5
1/194)	330	330	133.4	122.3	11.1	147.5	132.6	119.0	92.0	24.4	49.5	1.43	1.39	101.2 145.6
					1.1M, 1.5	160.2	160.2	92.0	71.0	68.0	88.0			

Plant: O.A.PCarline: WINDSTARDate: 5-20-96

## PROCESS INFORMATION:

083Process No: CAN 7900 Element No: 083 Datafile Name: DYN 2.5 Read: 30Study By: Spence & AbbottCovered: M 181 W 1 NDescription: 1534 TIRE & Axle Bay T. Verdict "Aluminum Lugs" R/S

## Torque Specifications (Nm):

Dynamic Mean: 188.2 Variance: ± 20.0 Minimum (Static) \_\_\_\_\_ NmTool Codes: Process: CAN 167 Actual: CAN 167 Part #: \_\_\_\_\_Tool Manufacturer: GTC Model Number: \_\_\_\_\_Type: Air Shu-On Clutch / Bell / Transducer Reaction Absorbed: Y / NSocket Condition: \_\_\_\_\_ Length of Extension: 3" Driver: Bolt / NutSocket or Bit Size: 19 M.M. Transducer: 271-2 Bay Location: \_\_\_\_\_Bolt #: \_\_\_\_\_ Nut #: 530-1013-00 Part #: \_\_\_\_\_

## SKETCH OF OPERATION

On Test: None / Trace / Excessive Green Band: Y/NTorque Mean before adjustments: 188.5Remarks: HMM Study "Aluminum" WEST SIDE R/S

## Study Recap EXP LIMITS 92.0 Nm To 159.0 Nm

POS #	SAMPLE SIZE	MEAN DYN	MEAN RESID	MEAN SHIFT	+3 SIGMA DYN	-3 SIGMA DYN	+3 SIGMA RESID	-3 SIGMA RESID	5 SIGMA RANGE DYN	DYNAMIC Pp	RESIDUAL Ppk	RESIDUAL LOW	RESIDUAL HIGH	
1	22	131.8	132.9	7.1	143.6	129.0	121.1	101.8	21.5	92.2	1.66	1.75	13.6	145.6
2	22	131.9	112.5	14.5	144.1	142.9	123.8	92.1	50.3	54.8	1.97	1.87	98.2	149.7
3	22	133.0	117.8	13.2	145.9	138.8	124.6	100.7	25.9	32.9	1.55	1.54	10.9	134.5
4	22	132.0	127.9	4.1	143.7	148.1	120.4	107.7	28.3	46.5	1.71	1.63	41.3	148.7
5	22	138.1	128.8	7.3	145.2	156.7	121.1	100.8	24.1	65.9	1.61	1.65	99.8	142.4
(12/34)														
Pp: 110.110 110.132.8 125.6 7.2 146.9 157.0 130.2 92.1 25.9 66.9 1.66 1.54 98.2 145.6														
Ppk: 100.140 100.131.1 117.7 0.7 147.1 158.1 131.1 97.1 25.7 66.7 1.61 1.54 97.1 145.1														


## Torque Probes Potential Study Worksheet

Place: OAKVILLE Carbox: WINDSTAR Date: OCT. 1- 97

## PROCEDURE INFORMATION

Procedure No: CL 7900 Element No: 080 Data Matrix ID: 107 Run #: 99Study By: Terry & Jack Control: M 1 S 1 WDescription: 1334 Tires & wheel assembly to car 45 Street

## Torque Specifications (Nm)

Dynamic Mean: 132.0 Variation: +2.0, -2.0 Residual Mean: \_\_\_\_\_ Variation: +2.0Tool Order: Planning Class 167 Actual: \_\_\_\_\_ Part #: \_\_\_\_\_Tool Manufacturer: J.P. Naylor Model Number: \_\_\_\_\_Type: Air Blow-Off / Click / Self / Induction Retention Absorbent: Y / NSocket Condition: Good Length of Extension: 9" Drive Bits: 1/2"Socket or Bit Size: 19 M.M. Transition: 21/2 N.H. Bay Location: \_\_\_\_\_Box #: \_\_\_\_\_ Net wt: E9.00 (14.12) Part #: \_\_\_\_\_5 NUTS

## TESTING OR ADJUSTMENT

On Test: None None Residual: None Green Book: Y/N

Torque Mean before adjustment: \_\_\_\_\_

Remarks: \_\_\_\_\_

## Study Name:

POS #	SAMPLE SIZE	MEAN	STDEV	+3 SIGMA		-3 SIGMA		6 SIGMA RANGE		DYNAMIC Fp	RESIDUAL Fp	RESIDUAL LOW HIGH			
				DYN	RESID	DYN	RESID	DYN	RESID						
1	22	22	133.0	131.4	1.6	144.7	156.1	121.3	102.7	28.4	49.4	1.71	1.71	117.4	144.0
2	22	22	130.9	128.9	2.0	138.8	145.5	122.9	112.1	15.9	33.2	2.52	2.25	120.4	141.51
3	22	22	131.3	133.0	0.7	144.8	151.5	120.3	114.5	28.8	37.0	1.67	1.61	129.0	143.7
4	22	22	132.9	132.0	0.9	145.1	146.5	120.8	115.7	24.3	30.8	1.72	1.71	119.6	139.1
5	22	22	133.2	127.6	5.6	143.9	150.3	122.6	105.0	21.3	46.3	1.88	1.86	118.5	144.9
6	178	110	132.5	131.4	1.1	145.1	156.1	120.3	106.7	24.8	49.4	1.67	1.61	117.4	140.9

EXP LIMITS 106.7 ~ 156.1 NM


## Torsion Probes - Potential Study Worksheet

Place: OAKVILLE can WINDSTARDate: January 2/97

## PROCEDURE INFORMATION:

Process No: CL 7700 Bureau No: 081 Date Mfg Sh No: DTE 109 Date In: 101Study By: TOM A. JACK Control: M S I WDescription: Pass/Fail straight Acqy Takeoff 1/8 37666

## Torque Specifications (Nm):

Dynamic Max: 189.0 Volume sh. Pa. Q Dynamic Min: \_\_\_\_\_ Volume sh. \_\_\_\_\_Tool Color: Yellow Green-Red Anode: CAN 16 T Tool ID: \_\_\_\_\_Tool Manufacturer: G/P MULTI Model Number: \_\_\_\_\_Type: AC Break Off / Check / Hold / Transistor Detection Method: Y / NSolder Condition: Good Length of Extension: 3" Depth Inv: 1/4"Solder or Bit Size: 19 MM Temperature: 271.2 MH4 Bay Location: \_\_\_\_\_Part #: E3361011 Part #: 6 NUTS

## METHOD OF OPERATION:

On Time: None None Reverse: None Green Back: Y / N

Torque Max before adjustment: \_\_\_\_\_

Remarks: \_\_\_\_\_

## Study Setup:

POS #	SAMPLE SIZE	MEAN	STDDEV	+3 SIGMA	-3 SIGMA	6 SIGMA RANGE	DYNAMIC		RESIDUAL						
							DYN	RESTD	DYN	RESTD					
1	22	22	789.3	104.9	11.5	143.6	163.6	121.3	144.8	22.3	38.8	1.79	1.74	118.5	145.4
2	22	22	133.7	180.0	2.3	144.3	153.6	123.1	118.4	21.3	33.2	1.88	1.87	131.3	143.1
3	22	22	133.1	139.4	6.7	143.4	161.6	123.8	118.1	20.6	43.5	1.95	1.94	129.3	145.6
4	22	22	133.6	140.9	5.1	143.4	163.3	123.8	118.0	19.6	46.3	2.04	1.98	122.4	148.9
5	22	22	163.2	163.5	0.3	144.8	155.2	121.7	111.2	23.1	43.4	1.93	1.71	119.3	143.2
6	110	110	488.2	107.6	42.4	440.8	449.3	391.3	311.8	39.3	51.5	1.79	1.71	118.5	145.9

A-10 - 100-100-100-100-100-100

880-004 0400

Plant: OAKVILLE CAR WINDSTAR Date: Oct 1-82

## PROCESS INFORMATION

Process No: Clp 7900 Revision No: 002 Dynamic Run No: 10X Run 100

Study By: Robert J. Cook

Control D S/W

Description: Test Torque Nut Run Test

Torque Specification: 100 ft-lbs

Dynamic Mean: 133.0 Volume: 16.0 Standard Mean: \_\_\_\_\_ Volume: 16

Tool Counter: None None None Model: CAN 16T Run #: 1

Tool Maintenance: Off Quality Model Number: \_\_\_\_\_


Type: Air Run-Off / Comp / Elec   Reaction Attenuate:  Y / N

System Orientation: Down Length of Extension: 3" Drive Run / Min

Bottom or End Run: 19.000 Torque: 271.2 N-m Avg Length: \_\_\_\_\_

Date of: \_\_\_\_\_ Net #: EARL 1013 Part #: \_\_\_\_\_

NOTES: 016



## TESTING INFORMATION

On Tool:  Type:  Parallel:  Cross Run: Y/N

Torque Mode before adjustment: \_\_\_\_\_

Remarks: \_\_\_\_\_

## Study Setup

SEQ #	SAMPLE SIZE	MEAN	STDDEV	+3 SIGMA	-3 SIGMA	6 SIGMA RANGE	DYNAMIC Freq	Repetitive Low	Repetitive High						
	TYPE	UNITS	UNITS	TYPE	TYPE	TYPE	TYPE	TYPE	TYPE						
1	22	22	100.0	102.2	97.8	146.5	197.2	123.2	89.4	24.8	40.8	7.45	1.54	100.1	192.0
2	22	22	101.6	102.3	99.3	109.7	139.0	101.6	95.2	11.1	31.4	2.49	2.32	100.9	192.1
3	22	22	101.6	102.1	99.2	104.8	109.2	101.4	99.4	32.1	1.79	1.66	100.0	190.7	
4	22	22	100.9	101.5	98.6	102.2	104.6	100.1	95.9	17.2	63.1	0.35	0.15	101.7	192.7
5	22	22	104.5	105.1	97.1	106.6	138.0	101.8	91.3	24.2	47.7	16.1	1.51	100.4	191.5
R	110	110	103.1	108.4	95.1	116.6	147.6	101.4	89.4	36.1	49.2	3.64	1.51	100.1	199.7

## Initial Product Potential Study Worksheet

Part: OAKVILLECarton: WINDSTARDate: Oct-8-91

## PROCESS INFORMATION

Phone No: CL7800 Device No: 083 Date/Model Number: 1984/10/24Study By: John P. Jack Control: W-E-WDescription: Very Tight J-weld Ready To Go Pt. 2

## Torque Specifications (Nm)

Dynamic Mean: 10.0 Variation: ±0.0 Standard Deviation: 0.0 Variance: 0.0Tool Color: Black Part No: CAB 16T Date: Tool Manufacturer: C/P WELDER Model Number: Type: Air Gun-OK / Chuck: 1 Drill: 1 Transformer: 0 Revision Number: 0 / NSocket Condition: Good Length of Extension: 3" Driver Box / Nut: Socket or Bit Size: 19 N.M. Transformer: 271-2.40N Key Length: Box #:  Nut #: F3.DG.10.18 Part #: 11**5 NOTES:****METHOD OF OPERATION**On Test: No / Yes / None / None Green Box: Y/NTorque Mean before adjustment: 10.0

Remarks: \_\_\_\_\_

**Study Report**

POS #	HANDLE SIZE	MEAN DYN	MEAN RESID	+3 SIGMA DYN		-3 SIGMA DYN		6 SIGMA RANGE DYN		DYNAMIC Fp	RESIDUAL Fp	RESIDUAL LOW HIGH
				DYN	RESID	DYN	RESID	DYN	RESID			
1	22	144.1	144.9	145.5	144.1	133.7	95.0	29.0	49.2	1.75	1.66	MIN 144.099
2	22	145.1	145.1	146.8	154.1	133.5	90.1	23.1	44.0	1.74	1.53	101.3 145.5
3	22	146.0	143.3	145.8	144.5	146.1	146.1	31.7	55.4	1.95	1.66	141.6 146.8
4	22	146.0	141.1	145.1	145.1	123.9	126.0	94.1	14.0	1.97	1.78	141.2 146.8
5	22	141.7	145.8	144.9	154.6	123.7	94.0	14.0	14.6	1.97	1.90	101.7 142.2
X <sup>1</sup>	110	110	110	114.4	114.4	102.0	112.9	110.7	116.1	115.8	112.8	112.2 116.8
R												

Plant: OAKVILLE

Process: TIRE & WHEEL ASSEMBLY

Date: APP 19/000

**PROCESS INFORMATION:**

Process No: 19.00 Element No: 080 DataMite File No: Dyn: \_\_\_\_\_ Read: \_\_\_\_\_  
Study By: JAN + GARY Contact: M/S / WIN  
Description: TIRE AND WHEEL ASG TO VEHICLE

**Torque Specifications (Nm):**

Dynamic Mean: 133.0 Variance: 7.0.0 Minimum (Static): \_\_\_\_\_  
Tool Codes: Processed: AAC 1811-1412 Actual: \_\_\_\_\_ Plant #: \_\_\_\_\_  
Tool Manufacturer: ATLAS COPCO Model Number: \_\_\_\_\_  
Type: Air Shut-Off / Clutch / Stall / Transducer Reaction Approved: Y / N  
Socket Condition: GOOD Length of Extension: SIX IN. Driver: Ball Nut  
Socket or Bit Size: 19 MM Transducer: 271.2 NM Bay Location: \_\_\_\_\_  
Ball #: 158 DC1012-1A Part #: 158 DC1012-1A



Sketch of Operation

5 FAST

LSS

Oil Test: None / Trace / Explosive Green Band: Y / N  
Torque Mean Prior To Adjustment was: \_\_\_\_\_ Nm  
Remarks: \_\_\_\_\_

**Spec Sheet**

	DYN	INCH	DYN	INCH	DYN	INCH	DYN	INCH	DYN	INCH	DYN	INCH	DYN	INCH	DYN	INCH	
1	16.6	134.0	145.5	9.1	133.0	116.5	132.0	125.4	115.7	39.8	10.55	10.21	131.0	132.7			
2	16.6	134.0	146.5	6.3	134.0	161.2	132.0	111.9	KW	41.3	10.45	10.04	131.5	133.1			
3	16.6	134.0	146.5	6.3	134.0	162.8	132.0	118.8	117.6	41.8	11.25	10.84	132.2	133.7			
4	16.6	134.0	146.5	12.7	134.0	171.4	132.0	104.0	3.5	50.3	10.10	11.90	133.7	134.7			
5	16.6	134.0	146.5	10.7	134.0	166.9	132.0	126.1	3.1	40.1	9.60	11.63	130.7	132.3			
	123.0	33.0	137.0	105.2	117.0	134.0	171.0	131.0	125.1	3.6	43.1	10.55	10.21	130.7	131.3		

Exp Limits 118.8 - 171.9

Plant: OAKVILLE

Vehicle Process Potential Study Worksheet

Carline: MONDEO STAGE

Date: MAR 14 1999

**PROCESS INFORMATION:**

Process No: CL7800 Element No: 081 Data/Mys Name: Dyn: \_\_\_\_\_ Result: \_\_\_\_\_  
Study By: DAL → DAVY Control: (M) S/W/N  
Description: TIRE AND WHEEL. AGS TO INFLATE.

**Torque Specifications (Nm):**

Dynamic Mean: 133.0 Variance: ± 20.0 Minimum (Static): \_\_\_\_\_  
Tool Code: Processor: 6111 PLANNER Actual: \_\_\_\_\_ Plant #: \_\_\_\_\_  
Tool Manufacturer: ATLAS COPCO Model Number: \_\_\_\_\_  
Type: Air Shut-Off / Clutch / Bell / Transducer Reaction Absorbed: Y / N  
Socket Condition: GOOD Length of Extension: 6 1/2 IN Driver: Bolt Nut \_\_\_\_\_  
Socket or Bit Size: 12MM Transducer: 271-2 Bay Location: \_\_\_\_\_  
Bolt #: \_\_\_\_\_ Nut #: EBDC1012-AA Part #: EB DC1012-AA



Sketch of Operation

5 FAST

RSS

Oil Test: None / Trace / Excessive Green Band: Y / N  
Torque Mean Prior To Adjustments was: \_\_\_\_\_ Nm  
Remarks: \_\_\_\_\_

**Study Results**

No.	DYN		MEMO		DYN		MEMO		DYN		MEMO		DYN		MEMO		DYN		MEMO	
	LOW	HIGH	LOW	HIGH	LOW	HIGH	LOW	HIGH	LOW	HIGH	LOW	HIGH	LOW	HIGH	LOW	HIGH	LOW	HIGH	LOW	HIGH
1	66	66	134.0	144.0	122.0	145.0	177.0	177.0	132.0	117.0	147.0	155.0	118.0	118.0	123.0	123.0	167.0	167.0	167.0	167.0
2	66	66	134.0	144.0	126.0	134.0	179.0	179.0	112.0	117.0	147.0	155.0	118.0	118.0	123.0	123.0	173.0	173.0	167.0	167.0
3	66	66	134.0	144.0	126.0	135.0	182.0	182.0	132.0	107.0	147.0	147.0	118.0	118.0	149.0	149.0	167.0	167.0	167.0	167.0
4	66	66	134.0	144.0	126.0	136.0	172.0	172.0	132.0	115.0	147.0	150.0	118.0	118.0	149.0	149.0	173.0	173.0	167.0	167.0
5	66	66	134.0	144.0	126.0	135.0	182.0	182.0	132.0	109.0	147.0	147.0	118.0	118.0	149.0	149.0	167.0	167.0	167.0	167.0
Range	66.0	66.0	134.0	144.0	126.0	135.0	182.0	182.0	132.0	109.0	147.0	147.0	118.0	118.0	149.0	149.0	167.0	167.0	167.0	167.0

Exp Limits 117.5 - 182.6

## CHANGES OR REVIEW DATA

Command word = FORWARD

	1	(2)	(3)	(4)	(5)	(22)	(27)	(28)	(29)	(30)	(37)	(38)
C	LIMIT	LIMIT	MIN	MAX	SHIFT	MIN	MAX	SHIFT	MIN	MAX	MIN	MAX
M	TORQ	TORQ	TORQ	TORQ	+	0	+	0	0	0	HIGH	LOW
PROC.	2	MIN	VAR	SHFT	MIN	MAX	SHFT	MIN	MAX	ALERT	MIN	MAX
NUMBER	Z	+/-	+/-	MIN	RANGE	RANGE	MIN	RANGE	RANGE	ALERT	HIGH	LOW
CL7900	M	123.0	20.0	.0	5.8	62.2	44.5	100	80	167.0	112.0	
CL7900	M	123.0	20.0	.0	6.8	55.2	40.5	100	80	168.1	112.0	
CL7900	M	123.0	20.0	.0	11.1	45.5	40.5	100	80	158.6	92.0	
CL7900	M	123.0	20.0	.0	7.2	66.9	40.5	100	80	159.0	92.1	
CM1000	M	40.0	6.0	.0	2.3	15.1	12.0	100	80	45.8	36.7	
CM2000	M	40.0	6.0	.0	2.7	16.3	12.4	100	80	50.6	36.3	
CM2100	M	40.0	6.0	.0	1.4	20.0	12.8	100	80	51.4	31.4	
CM3000	M	40.0	6.0	.0	0.8	3.7	12.6	100	80	.0	.0	
CM3000	M	47.2	7.2	.0	-4.3	13.1	14.3	100	80	50.3	38.9	
CV0500	S	30.0	4.5	.0	1.3	6.1	5.9	100	80	.0	.0	
CV0550	S	62.5	9.4	.0	1.2	13.0	10.8	100	80	.0	.0	
CV5000	S	12.0	1.5	.0	0.8	4.7	3.6	100	80	.0	.0	

PF 1-Help 2-Top 3-End 4-Opt 5-Del 6-Copy 7-Eject 8-Fwd 9-Ins 10-L 11-R 12-Bot

100-1000-0000

\*\*\*\*\*  
\* Note printed by GCARLOZZ on 4 Mar 1997 at 06:56:29 \*  
\*\*\*\*\*

From: RWOODY1 --DRBN004  
To: GCARLOZZ--DRBN004

Date and time 03/04/97 06:45:48

FROM: Ronald Woody CANET(UTC -05:00)  
Subject: Urgent!! --- Wheel Lugnut Torque  
GET DAN TO ANS. THIS. I WOULD LIKE TO SEE THE ANSWER BEFORE IT LEAVES THE PLANT

Regards,  
Ronald Moody

\*\*\* Forwarding note from JBIENIEK--DRBN004 03/03/97 12:41 \*\*\*  
To: JPRYDE --DRBN004 PROVACEV--DRBN004  
SHENDER2--DRBN004 AWELLS2 --DRBN004  
JRODRI25--DRBN007 JFOWLER1--DRBN004  
MMARTIN8--DRBN004 GBAKER2 --DRBN004  
PVANDERG--DRBN005 MWASCHAK--DRBN004  
SHOLLOW1--DRBN004 AJEMISON--DRBN004  
DAULDI --DRBN004 DMILASKY--DRBN004  
ESCHACK1--DRBN004 CMCKEACH--DRBN004  
TLER2 --DRBN004 TJOYCE --DRBN004  
DLAMERAT--DRBN004 PLEE2 --DRBN004  
RMORGAN --DRBN005 SZONCA --DRBN004  
GWILLI28--DRBN004 CDOWD --DRBN004  
MGONZA10--DRBN004  
  
cc: EVANBERG--DRBN004 RVARTO --DRBN004  
HJACKSON--DRBN004 KWARD2 --DRBN004  
RMONGEON--DRBN005 SRYAN --DRBN004  
SABBOTT1--DRBN004 DMILLMAN--DRBN004  
JVANNOOR--DRBN004 JGROW --DRBN004  
RELLIS3 --DRBN004 GSTEWAR4--DRBN004  
RMONTANO--DRBN004 CMOYNIHA--DRBN004  
GCANO --DRBN004 JWOOD4 --DRBN005  
RSEWELL --DRBN005 RWODY1 --DRBN004  
PSPANN --DRBN004 RPAPULSON--DRBN004  
JSCHNIE4--DRBN004 SBASKA1 --DRBN004

FROM: Joe Bieniek USAEST(UTC -05:00)  
Subject: Urgent!! --- Wheel Lugnut Torque

There has been some concerns raised by the Dealer Counsel in regards to the correct torque being applied to lugnuts by wheel multiples. In efforts to prove our capability, the Fastening Systems section is requesting the following from each plant.

- 1) One year of inspection data (TISS). We feel a good summary of this is the Process Ranking Summary Report. Please send the pages of this report that contain lugnut data for each month starting January 1996.  
*12 Pgs\**
- 2) A copy of the latest TPPS study done on the wheel multiples.  
*4 Pgs\**
- 3) Provide the current dynamic specifications set in the multiples. And provide the current specification (range) that the inspectors are using for residual readings.
- 4) Provide the lowest residual reading the inspectors are encountering.

MARCH 5, 1997

TO: JOE BIENIEK


FROM: DAN AULD (DAULD1)

CC: RON WOODY (RWOODY1)  
DAVID LEECH (DLIECH)

I am faxing you the information you requested on the Wheel Nut Torques. You will notice that the first four sheets are the Torque Process Potential Studies (TPPS) for steel (LS & RS) and for aluminum (LS & RS). The next 12 sheets are the Process Ranking Summary Sheets (PRSS) by month for a year with July's data combined with June's data due to the 3 week layoff. The data for the Wheel Nut Torques are highlighted as well as the lowest residual readings for the month in the 10th column. The dynamic specification of 113.0 Nm to 153.0 Nm is located on the 4 TPPS sheets as well as the 11th and 12th columns on the PRSS sheets.

Could you send me a profs acknowledging that you have received this information and that the data satisfies your request.

Regards,



Dan Auld  
Fastening Systems Co-ordinator  
Oakville Assembly Plant

## Torque Studies - Potential Study Workbooks

Plant: O.A.P.Captive: WINDSTARDate: 5-29-96

## PROCESS INFORMATION:

083Process No: Lab 7900 Element No: 083 DataMyte file name: Dyno 2.5 Part #: 30Study By: James C. LefebvreControl: M161WINDescription: Easy Tite & Wheel Easy T. Nutricle Alumina 1.05" R/S

## Torque Specifications (N-m)

Dynamic Mean: 133.0Variance: .20.0

Minimum (Static) \_\_\_\_\_ Nm

Tool Order: Procurement: Cognex 165Actual: Cognex 165

Part #: \_\_\_\_\_

Tool Manufacturer: Cognex

Model Number: \_\_\_\_\_

Type: Air Chuck-Cap

Clutch / Cap / Transducer

Reaction Absorbed: Y / N

Socket Condition: \_\_\_\_\_



Length of Extension: 2"

Driven: Bolt / Nut

Socket or Bit Size: 19 M.14Transducer: 271-2

Bay Locations: \_\_\_\_\_

Bolt #: \_\_\_\_\_



Nut #: 5/16-18-12-06 Part #: \_\_\_\_\_

## SKETCH OF OPERATION

On Test: None / Trace / Escalope Green Band Y/NTorque Mean before adjustments: 138.8Remarks: Easy Study "Alumina 1.05" WEST SIDE R/S

## Study Recap EXP LIMITS 92.0 NM TO 159.0 NM

TOB #	SAMPLE SIZE	MEAN DYN	MEAN RESID	MEAN SHIFT	+3 SIGMA DYN		-3 SIGMA DYN		6 SIGMA RANGE DYN		DYNAMIC Pp	Ppk	RESIDUAL LOW	HIGH	
					DYN	RESID	DYN	RESID	DYN	RESID					
1	22	131.8	132.9	1.1	142.6	139.0	121.1	146.8	21.5	52.2	1.86	1.75	134.4	146.6	
2	22	134.0	117.5	16.5	144.1	148.9	122.5	92.1	20.3	56.8	1.97	1.87	98.2	146.7	
3	22	133.0	119.2	13.2	145.9	138.8	120.2	100.9	25.9	37.9	1.55	1.54	103.9	134.5	
4	22	132.0	127.9	4.1	143.7	148.1	120.4	107.7	23.3	46.5	1.71	1.63	114.3	143.7	
5	22	133.1	128.8	4.3	145.6	133.7	121.1	108.8	34.1	55.9	1.66	1.45	97.8	142.4	
2/941															
6	110	110	132.8	125.6	7.2	145.9	107.0	120.0	92.1	25.9	66.9	1.66	1.54	98.2	145.6
					1mm/s	1mm/s	1mm/s	1mm/s	Q+	Q+					

Part: O.A.P.Cerline: WINDSTARDate: May 18, 96PROCESS INFORMATION:Process No: CL2000 Element No: 087 Date/Myte File No: Dyn 21 Rev: 21Study By: John G. CookControl: MISWINDescription: Secure Torque & extend base to cap L18 ALUMINUMTorque Specifications (Nm):Dynamic Mean: 133.0 Variance: 4.20 Minimum (Stddev): \_\_\_\_\_ NmTool Codes: Process: Cav 167 Adjust: Cav 167 Part #: \_\_\_\_\_Tool Manufacturer: CIP MULTI Model Number: \_\_\_\_\_Type: Air Shut-Off / Clutch / Bell / Transducer Reaction Absorbed: Y / NSocket Condition: Good Length of Extension: 3" Driver: Bolt / NutSocket or Bit Size: 19.14-19 Transducer: 211-2-N-14 Bay Location: \_\_\_\_\_Bolt #: \_\_\_\_\_ Nut #: 630C101200 Part #: \_\_\_\_\_SECTION OF OPERATION:Oil Test: None / Trace? Excessive Green Band: Y / NTorque Mean before adjustments: 135.6Remarks: All four outer pins fast side 2/5

Study Range EXP LIMITS: 92.0 Nm to 159.0 Nm.

N	SAMPLE SIZE	MEAN DYN	MEAN RESID	MEAN SHIFT		+3 SIGMA DYN		-3 SIGMA DYN		6 SIGMA RANGE DYN		DYNAMIC Pp	Ppk	RESIDUAL LOW	HIGH
				DYN	RESID	DYN	RESID	DYN	RESID	DYN	RESID				
1	66	133.5	133.0	-3.5	146.1	146.6	131.0	94.5	25.1	51.0	160	1.65	101.4	148.7	
2	66	134.4	110.7	-16.5	147.0	145.8	121.9	92.0	25.0	53.9	162	1.48	101.7	148.7	
3	66	133.1	123.5	9.6	147.2	152.6	119.0	94.4	28.2	57.3	142	1.41	101.3	143.7	
4	66	133.4	126.7	6.7	147.5	151.9	119.3	101.4	28.1	56.5	142	1.39	101.4	145.6	
5	66	132.7	123.5	9.3	145.0	149.7	130.6	103.2	24.4	46.4	144	1.63	101.6	149.5	
6	330	133.4	122.3	11.1	147.5	152.6	117.0	97.0	24.4	40.5	143	1.39	101.2	145.6	


Torque Survey Test Data Sheet

Date 5-28-96Name D.A.P.Online WINDSTARDate 5-28-96

## Process Information

081Process No: 647900 Element No: 300000 Date/Myo file no: Dyn 26 Run: 29Study By: Jerry E. Jack Contact: N.I.B.I.W.I.NDescription: Aug. Test Subject Aug. To Max Torque "Street Rats" R/S

## Torque Specifications (Nm)

Dynamic Mean: 133.0Variation: ± 80.0Minimum (Nm): 0Tool Class: Process: Cav 165 Actual: Cav 165 Part #: Tool Manufacturer: C/P Hub 31 Model Number: Type: Air Gun-Off / Clutch / Gear / Transducer Reaction Absorber: Y / NSocket Condition:  Length of Extension: 3" Driver: Bolt ✓ NutSocket or Bit Size: 1/2 N.H. Transducer: 271-24-N Bay Location: Bolt #:  Nut #: 623C101200 Part #: HAN Stryoy  
STRELL

## SKETCH OF OPERATION

On Tool: None / Trace / Executive Green Band:  NTorque Mean before adjustment: 138.8Remarks: Han Stryoy "Street Rats" WEST 2026" R/S

## Study Recap

SAMPLE SIZE	MEAN DYN	MEAN TORQ	MEAN STDDEV	+3 SIGMA DYN	+3 SIGMA TORQ	-3 SIGMA DYN	-3 SIGMA TORQ	6 SIG RANGE DYN	6 SIG RANGE TORQ	DYNAMIC FDP	RESIDENTIAL LOW HIGH	
22 22	133.1	148.6	17.5	146.1	160.7	120.0	128.1	26.2	38.0	1.53	153 157.0	
22 22	136.8	139.1	13.3	147.6	159.3	124.1	138.4	28.5	41.9	1.70	146 168.0	
22 22	132.4	105.4	13.3	148.4	158.0	121.7	118.2	31.7	45.1	1.85	126.8 156.6	
22 22	133.5	139.8	17.3	145.9	164.2	121.1	117.7	24.8	44.8	1.61	157 160.0	
22 22	133.3	176.3	9.0	143.5	167.0	121.0	113.6	24.5	52.4	1.62	127.2 155.7	
110	110	133.7	140.5	16.3	147.6	160.1	120.0	112.9	27.4	55.2	1.53	126.9 160.0

Xerox, Business, Industrial, Manufacturing

Plant: O.A.P.Cordless: WINDSTARDate: MAY 13, 96**PROCESS INFORMATION:**Process No: CL7900 Element No: Q80 Dynamic file no: Dyn.80 Ratio: .80Study By: Jeanne E. Jack Control: W181W1NDescription: Screws Torque Wrench Assembly L/S**Torque Specifications (N.m)**Dynamic Mean: 133.0 Variation: ± 8.0 Minimum (Static): N/ATool Cordless: Precison CAN 16 Actual: CAN 16 Part #: Tool Manufacturer: CIP MULT Model Number: Type: Air Shut-Off Clutch / Stall / Transducer Reaction Absorbed: Y/NSocket Condition: Good Length of Extension: 2" Driver: Sok / NutSocket or Nut Size: 1/4 N.O. Transducer: 271-2 MM Bay Location: Bolt #: Nut # G3821-10400 Part #FULL STUDY  
SPOOL**SECTION OF OPERATION**On Test: None Trans Executive Green Band (Y/N)Torque Mean before adjustments: 135.6Remarks: Steel nuts fast size L/S**Study Recap**

OB	SAMPLE	SIZE	MEAN		MIN/MAX		+3 SIGMA		-3 SIGMA		6 SIG SIGMA		DYNAMIC ID	ID PPM	PERIODIC LOW/HIGH		
			DYN	RSSID	DYN	RESTD	DYN	RSSID	DYN	RSSID	DYN	RSSID			DYN	RSSID	
1	66	66	135.2	134.7	135.5	146.0	146.7	124.4	118.8	21.6	48.9	48.5	145	145	146.9	147.4	
2	66	66	132.9	131.8	132.6	146.9	147.4	121.0	118.2	26.0	36.3	35.4	147	147	147.0	146.1	
3	66	66	130.8	137.5	130.0	147.7	157.7	121.3	117.4	21.4	46.3	45.1	140	140	124.3	135.7	
4	66	66	133.0	143.8	134.0	147.1	167.0	120.5	110.7	26.6	46.3	45.4	147	147	130.1	137.5	
5	66	66	133.1	134.4	133.3	145.7	155.5	120.3	118.3	20.7	40.2	43.6	135	135	131.2	135.4	
13	330	330	134.1	134.1	133.9	15.8	147.7	167.0	120.2	110.8	25.7	42.2	41.1	140	140	116.9	137.5

**OAKVILLE ASSEMBLY PLANT**  
**Torque Inspection Report**  
**Process Ranking Summary Report**

Date: 01/01/97 - 01/31/97	Dept: All	Start: All Shifts	End: All	Printed on:
Class: All	Time: All	Shift: All	Ends: All	02/03/97, 1:13 PM
Type: All	Super: All	Lifts: All		TSM v 6.71

**MANDATORY Processes**

Process Part Number	Process Description	Data Points						Value	High Limit	Low Limit
		Total	High	Low	Slow	Stop/Slow	Checkout			
59 CJ4601021	REAR WHEEL ASSEMBLY TO REAR AXLE BACKUP	0	0	0	0.00%	0.00%	0		30.5	39.5
60 CA4620094	ADS. REAR BRAKE LINE END. TO BACKING PL.	440	0	0	0.00%	31.14%	0	7.6	10.4	7.6
61 CJ4620091	ADS. REAR BRAKE LINE END. TO BACKING PL	440	0	0	0.00%	35.41%	0	7.6	10.4	7.6
62 CJ4620104	REAR BRAKE TUBE TO BACKING PLATE L/S	440	0	0	0.00%	32.95%	0	14.6	20.2	14.6
63 CJ4620101	REAR BRAKE TUBE TO BACKING PLATE R/H BACKUP	440	0	0	0.00%	30.41%	0	14.6	20.2	14.6
64 CJ4620090	ADS/ADS & SEC REAR BRAKE TUBES TO HOSES -	440	0	0	0.00%	13.64%	0	13.3	17.7	13.3
65 CJ4620091	ADS/ADS & SEC REAR BRAKE TUBES TO HOSES -	440	0	0	0.00%	20.41%	0	13.4	17.7	13.3
66 CJ2300078	SUB-ASSEMBLY BRAKE TUBES TO ABS ECU MODU	440	0	0	0.00%	5.49%	0	11.4	20.9	11.3
67 CJ2310140	SECURE ABS HTD VALVE TO STEER KIT	440	0	0	0.00%	12.30%	0	23.7	34.5	23.7
68 CJ2330140	ADS. RH RTT BRAKE TUBE TO TUBE BUNDLE INCLUDES CJ2300140	0	0	0	0.00%	0.00%	0		18.6	21.6
69 CJ2330140	ADS. RD RTT BRAKE TUBE TO TUBE BUNDLE	440	0	0	0.00%	25.00%	0	14.8	20.2	14.8
70 CJ2340090	SEC FRONT BRAKE TUBES TO MASTER CYLINDER	440	0	0	0.00%	23.20%	0	9.2	15.9	8.9
71 CJ2340090	SEC FRONT BRAKE TUBES TO JUNCTION BLOCK INCLUDES CJ2300140	0	0	0	0.00%	0.00%	0		20.2	14.8
72 CJ2580100	ASSEMBLE FRONT CALIPER TO FRONT KNUCKLE	440	0	0	0.00%	3.41%	0	98.5	148.2	94.1
73 CJ2580101	ASSEMBLE FRONT CALIPER TO FRONT KNUCKLE	440	0	0	0.00%	4.59%	0	94.2	148.2	94.1
74 CJ2582100	ASSEMBLE FRONT CALIPER TO FRONT KNUCKLE BACKUP	0	0	0	0.00%	0.00%	0		152.3	97.7
75 CJ2640070	SEC FRONT BRAKE ROD TO CALIPER - L/S	440	0	0	0.00%	9.07%	0	44.8	63.3	44.7
76 CJ2640071	SEC FRONT BRAKE ROD TO CALIPER - R/S	440	0	0	0.00%	10.23%	0	44.7	63.3	44.7
77 CJ2640100	SEC FRONT BRAKE ROD TO BRAKE TUBE - L/S	440	0	0	0.00%	19.32%	0	9.9	16.3	9.9
78 CJ2640101	SEC FRONT BRAKE ROD TO BRAKE TUBE - R/S	440	0	0	0.00%	43.18%	0	10.3	16.6	9.5
79 CJ0100060	SECURE FUEL FILLER PIPE TO BODY	440	0	0	0.00%	25.00%	0	3.6	9.1	3.0
80 CJ0200250	ARM FUEL TANK TO UNDERKIT (20 GALLON)	440	0	0	0.00%	14.77%	0	40.6	54.7	40.3
81 CJ0200260	ARM FUEL TANK TO UNDERKIT (25 GALLON)	440	0	0	0.00%	25.00%	0	40.3	54.7	40.3
82 CR0500070	INSTALL RETURN HOSE CLAMP	440	0	0	0.00%	4.88%	0	2.0	5.2	2.0
83 CJ0500230	INSTALL FUEL FILLER CLAMP	440	0	0	0.00%	12.50%	0	1.1	4.8	1.1
84 CK1400064	ACCEL BKT & RET SPRING TO ENG. 3.0L	440	0	0	0.00%	25.46%	0	12.7	17.3	12.7
85 CL7900000	TIRE AND WHEEL ASSY. TO VEHICLE L/S	440	0	0	0.00%	9.07%	0	113.4	159.0	113.4
86 CL7900001	TIRE AND WHEEL ASSY. TO VEHICLE R/S MULTI-SPINDEL	440	0	0	0.00%	21.50%	0	113.4	159.0	113.0
87 CL7900002	TIRE & WHEEL ASSY. TO VEH. L/S (ALUM.) MULTI-SPINDEL	440	0	0	0.00%	0.00%	0	108.7	159.0	98.0
88 CL7900003	TIRE & WHEEL ASSY. TO VEH. R/S (ALUM.) MULTI-SPINDEL	440	0	0	0.00%	1.14%	0	102.8	159.0	98.0

**OAKVILLE ASSEMBLY PLANT**  
**Torque Inspection Report**  
**Process Ranking Summary Report**

Date: 02/01/97 - 02/28/97 Dept: All  
 Shifts: All Shifts Clean: All  
 Types: All Zoner: All Supers: All Car: All  
 Xbar: All List: All Printed on  
 03/03/97, 1:36 PM TISE v 6.71

**MANDATORY Processes**

Process ID Number	Process Description	Data Points								
		Total	High	Low	Slow	Matches	Creaks	Worst	High Limit	Low Limit
59 CJ0401021	SEC REAR WHEEL ASSEMBLY TO REAR AXLE BACKUP	0	0	0	0.00%	0.00%	0	00.5	99.5	
60 CJ0523098	ABR. REAR JOUNCE BONE ABR. TO SACKING PL	395	0	0	0.00%	54.43%	0	7.6	10.4	7.6
61 CJ0523091	ABR. REAR JOUNCE BONE BCK. TO SACKING PL	395	0	0	0.00%	63.29%	0	7.6	10.4	7.6
62 CJ0623100	REAR BRAKE TUBE TO SACKING PLATE L/R	395	0	0	0.00%	84.05%	0	14.8	20.2	14.8
63 CJ0623101	REAR BRAKE TUBE TO SACKING PLATE R/H SHUTO	395	0	0	0.00%	27.05%	0	14.8	20.2	14.8
64 CJ0623096	ABR. & SEC REAR BRAKE TUBES TO HORN -	395	0	0	0.00%	32.91%	0	12.3	17.7	12.3
65 CJ0623031	ABR. & SEC REAR BRAKE TUBES TO HORN -	395	0	0	0.00%	35.38%	0	12.3	17.7	12.3
66 CJ2504070	RHS-ARMED BRAKE TUBES TO ABS HYD. HORN	390	0	0	0.00%	3.05%	0	11.3	20.9	11.3
67 CJ2519100	SECURE ABS HYD VALVE TO SIGHTS	390	0	0	0.00%	8.97%	0	26.3	34.3	25.3
68 CJ2504040	ABR. RH FRT BRAKE TUBE TO TUBE BUNDLE INCLUDES CJ2501040	0	0	0	0.00%	0.00%	0	10.6	11.6	
69 CJ2501040	ABR. RH FRT BRAKE TUBE TO TUBE BUNDLE	390	0	0	0.00%	38.09%	0	14.9	20.2	14.8
70 CJ2430098	SEC FRONT BRAKE TUBES TO MASTER CYLINDER	390	0	0	0.00%	30.77%	0	9.3	15.9	8.9
71 CJ2430070	SEC FRONT BRAKE TUBES TO JUNCTION BLOCK INCLUDES CJ2530140	0	0	0	0.00%	0.00%	0	20.2	14.8	
72 CJ2520190	ASSEMBLE FRONT CALIPER TO FRONT KNUCKLE	395	0	0	0.00%	2.33%	0	94.4	148.2	94.1
73 CJ2520161	ASSEMBLE FRONT CALIPER TO FRONT KNUCKLE	395	0	0	0.00%	6.33%	0	95.7	148.2	94.1
74 CJ2520190	ASSEMBLE FRONT CALIPER TO FRONT KNUCKLE SHUTO	0	0	0	0.00%	9.06%	0	132.3	97.7	
75 CJ2640090	SEC FRONT BRAKE BONE TO CALIPER - L/S	395	0	0	0.00%	12.66%	0	46.8	63.3	46.7
76 CJ2640091	SEC FRONT BRAKE BONE TO CALIPER - R/S	395	0	0	0.00%	7.59%	0	46.7	63.3	46.7
77 CJ2640100	SEC FRONT BRAKE BONE TO BRAKE TUBE - L/S	390	0	0	0.00%	29.49%	0	9.6	16.3	9.5
78 CJ2640101	SEC FRONT BRAKE BONE TO BRAKE TUBE - R/S MULTI-SPINDLE	390	0	0	0.00%	33.90%	0	9.7	16.6	9.5
79 CJ0200040	SECURE FUEL FILLER PIPE TO BODY	385	0	0	0.00%	10.39%	0	3.3	5.1	3.0
80 CJ0200050	ARM FUEL TANK TO UNDERBODY (20 GALLON)	395	0	0	0.00%	29.11%	0	46.3	54.7	40.3
81 CJ0220040	ARM FUEL TANK TO UNDERBODY (25 GALLON)	395	0	0	0.00%	29.32%	0	40.3	54.7	40.3
82 CJ0500070	INSTALL MASTIC HOSE CLAMP	395	0	0	0.00%	12.44%	0	2.6	5.2	2.0
83 CJ0500280	INSTALL FUEL FILLER CLAMP	395	0	0	0.00%	13.92%	0	1.2	4.5	1.1
84 CK1400040	ACCEL BRKT & RET SPRING TO ENG. 3.0L	395	0	0	0.00%	41.77%	0	12.7	17.3	12.7
85 CJ7900080	TIRE AND WHEEL ASSY. TO VEHICLE L/S MULTI-SPINDLE	385	0	0	0.00%	19.46%	0	113.0	193.0	113.0
86 CJ7900081	TIRE AND WHEEL ASSY. TO VEHICLE R/S MULTI-SPINDLE	385	0	0	0.00%	15.56%	0	113.0	193.0	113.0
87 CJ7900082	TIRE & WHEEL ASSY. TO VEH. L/S (ALUM.) MULTI-SPINDLE	385	0	0	0.00%	1.30%	0	97.7	159.0	92.0
88 CJ7900083	TIRE & WHEEL ASSY. TO VEH. R/S (ALUM.) MULTI-SPINDLE	385	0	0	0.00%	0.00%	0	99.8	159.0	92.0

**OAKVILLE ASSEMBLY PLANT**  
**Torque Inspection Report**  
**Process Ranking Summary Report**

Date: 12/01/96 - 12/31/96 Dept: All	Date: All	Car: All	Printed on:
Shift: All Shifts Class: All	Super: All	Model: All	01/15/97, 11:21 AM
Type: All		List: All	T100 v 6.71

**MANDATORY Processes**  
Process Rank Summary

Process Cat Number	Process Description	Data Points							High Limit	Low Limit	Shift
		Total	High	Low	100%	Wastage	Checkout	Worst			
39 C00423095	ASSE. REAR JOUNCE BONE BOX. TO BACKING PL.	300	0	0	0.00%	31.30%	0	7.4	10.4	7.4	
40 C00423097	ASSE. REAR JOUNCE BONE BOX. TO BACKING PL.	295	0	0	0.00%	39.70%	0	7.6	10.4	7.6	
41 C00423100	REAR BRAKE TUBE TO BACKING PLATE L/S	295	0	0	0.00%	48.37%	0	14.8	20.3	14.8	
42 C00423101	REAR BRAKE TUBE TO BACKING PLATE R/H	295	0	0	0.00%	35.59%	0	14.8	20.3	14.8	
43 C00423036	ASSEMBLE 2 SEC REAR BRAKE TUBES TO HOSES -	300	0	0	0.00%	36.67%	0	18.3	17.7	12.3	
44 C00423037	ASSEMBLE 2 SEC REAR BRAKE TUBES TO HOSES -	305	0	0	0.00%	37.70%	0	12.4	17.7	12.3	
45 C00423074	SUB-ASSEMBLE BRAKE TUBES TO ABS FWD MODU	295	0	0	0.00%	4.99%	0	11.5	20.9	11.3	
46 C00423088	INSTALL ABS FWD VALVE TO SIDEBRAIL	295	0	0	0.00%	20.49%	0	25.6	34.3	25.3	
47 C004230140	ASSE. RH FRT BRAKE TUBE TO TUBE MODULE INCLUDES C004230140	0	0	0	0.00%	0.00%	0	10.6	11.4		
48 C00423080	ASSE. RH FRT BRAKE TUBE TO TUBE MODULE	295	0	0	0.00%	27.39%	0	14.6	20.2	14.6	
49 C00423090	SEC FRONT BRAKE TUBES TO MASTER CYL,MODULE	295	0	0	0.00%	24.46%	0	8.9	15.9	8.9	
50 C00423070	SEC FRONT BRAKE TUBES TO JUNCTION BLOCK INCLUDES C004230140	0	0	0	0.00%	0.00%	0	20.2	14.6		
51 C004230100	ASSEMBLE FRONT CALIPER TO FRONT BRACKET	305	0	0	0.00%	9.84%	0	90.1	165.2	90.1	
52 C004230101	ASSEMBLE FRONT CALIPER TO FRONT BRACKET	305	0	0	0.00%	9.84%	0	90.3	165.2	90.1	
53 C004230100	ASSEMBLE FRONT CALIPER TO FRONT BRACKET BACKUP	0	0	0	0.00%	0.00%	0	132.3	197.7		
54 C00420010	SEC FRONT BRAKE LINE TO CALIPER - L/S	310	0	0	0.00%	20.97%	0	48.7	63.3	48.7	
55 C00420011	SEC FRONT BRAKE LINE TO CALIPER - R/S	305	0	0	0.00%	13.11%	0	48.9	48.3	48.7	
56 C00420010	SEC FRONT BRAKE LINE TO BRAKE TUBE - L/S	300	0	0	0.00%	24.16%	0	9.5	16.5	9.5	
57 C00420011	SEC FRONT BRAKE LINE TO BRAKE TUBE - R/S	295	0	0	0.00%	34.46%	0	9.5	16.4	9.5	
58 C00420040	SECURE FUEL FILLER PIPE TO BODY	300	0	0	0.00%	35.00%	0	3.0	5.1	3.0	
59 C00420030	ASSEMBLE FUEL TANK TO UNDERBODY (20 GALLONS)	305	0	0	0.00%	32.79%	0	48.4	54.7	48.3	
60 C00420040	ASSEMBLE FUEL TANK TO UNDERBODY (25 GALLONS)	305	0	0	0.00%	21.31%	0	49.3	54.7	48.3	
61 C00420070	INSTALL RETURN LINE CLAMP	305	0	0	0.00%	13.11%	0	2.9	5.2	2.0	
62 C00420220	INSTALL FUEL FILLER CLAMP	295	0	0	0.00%	14.75%	0	1.7	4.5	1.1	
63 C01420040	ASSEMBLE BRAKE & RET SPRING TO BRAKE, S.OL	80	0	0	0.00%	38.60%	0	12.7	17.3	12.7	
64 C07900080	TIRE AND WHEEL ASY. TO VEHICLE L/S	295	0	0	0.00%	13.50%	0	113.7	193.0	113.0	
65 C07900081	TIRE AND WHEEL ASY. TO VEHICLE R/S MULTI-SPINDEL	295	0	0	0.00%	14.29%	0	113.8	193.0	113.0	
66 C07900082	TIRE & WHEEL ASY. TO VEH. L/S (CALIN.) MULTI-SPINDEL	295	0	0	0.00%	0.80%	0	107.1	159.0	92.0	
67 C07900083	TIRE & WHEEL ASY. TO VEH. R/S (CALIN.) MULTI-SPINDEL	295	0	0	0.00%	3.57%	0	108.9	159.0	92.0	
68 C02800100	ASSEMBLE CAT. COV/INLET PIPE TO MANIFOL Spec changes: 12/10/96	40	0	0	0.00%	37.50%	0	28.1	45.0	27.0	

**OAKVILLE ASSEMBLY PLANT**  
**Torque Inspection Report**  
**Process Ranking Summary Report**

Date: 11/01/96 - 11/30/96    Pages: All  
 Shifts: All Shifts    Classes: All  
 Types: All    Zones: All  
 Super: All    Cars: All  
 Rows: All    Lists: All    Printed on  
 12/12/96, 10:17 AM  
 TBS v 4.71

**MANDATORY Processes**

Process Task Number	Process Description	Data Points							High Time	Low Time	Limit
		Total	High	Low	Max	Min	Average	Checksum			
30 CJ0423090	ASSEMBLE REAR JOUNCE BONE MNT. TO BACKING PL.	330	0	0	0.003	50.00%	0	7.6	10.4	7.6	
31 CJ0423091	ASSEMBLE REAR JOUNCE MNT. MNT. TO BACKING PL.	330	0	0	0.003	53.00%	0	7.6	10.4	7.6	
37 CJ0423100	REAR BRAKE TUBE TO BACKING PLATE L/H	330	0	0	0.003	42.42%	0	14.8	20.2	14.8	
42 CJ0423101	REAR BRAKE TUBE TO BACKING PLATE R/H	330	0	0	0.003	31.92%	0	14.8	20.2	14.8	
	SHUTOFF										
43 CJ0430026	ASSEMBLE & SEC BRAKE BRAKE TUBES TO HOSES -	330	0	0	0.003	38.79%	0	12.3	17.7	12.3	
45 CJ0430027	ASSEMBLE & SEC BRAKE BRAKE TUBES TO HOSES -	330	0	0	0.003	36.99%	0	12.3	17.7	12.3	
46 CJ0430028	SEC-BRAKE BRAKE BRAKE TUBES TO AIR FWD HUB	320	0	0	0.003	7.91%	0	11.7	20.9	11.3	
46 CJ0430029	SECURE AIR FWD VALVE TO GENERATOR	320	0	0	0.003	21.00%	0	29.6	34.5	29.5	
47 CJ0430048	ASSEMBLE AIR FWD BRAKE TUBE TO TUBE BUNDLE	0	0	0	0.003	0.00%	0		10.6	11.6	
	INCLUDES CJ0430148										
48 CJ0430100	ASSEMBLE AIR FWD BRAKE TUBE TO TUBE BUNDLE	320	0	0	0.003	27.80%	0	14.9	20.2	14.8	
49 CJ0430098	SEC FRONT BRAKE TUBES TO MASTER CYLINDER	320	0	0	0.003	39.10%	0	8.9	15.9	8.9	
50 CJ0430070	SEC FRONT BRAKE TUBES TO JUNCTION BLOCK	0	0	0	0.003	0.00%	0		20.2	14.8	
	INCLUDES CJ0430148										
71 CJ0520100	ASSEMBLE FRONT CALIPER TO FRONT KNUCKLE	330	0	0	0.003	15.19%	0	94.4	146.2	94.1	
72 CJ0520101	ASSEMBLE FRONT CALIPER TO FRONT KNUCKLE	330	0	0	0.003	4.59%	0	94.4	146.2	94.1	
73 CJ0521100	ASSEMBLE FRONT CALIPER TO FRONT KNUCKLE	0	0	0	0.003	0.00%	0		138.3	177.7	
	BRAKES										
74 CJ0640096	SEC FRONT BRAKE HOSE TO CALIPER - L/H	330	0	0	0.003	19.70%	0	46.7	63.3	46.7	
75 CJ0640097	SEC FRONT BRAKE HOSE TO CALIPER - R/H	330	0	0	0.003	27.27%	0	46.7	63.3	46.7	
76 CJ0640100	SEC FRONT BRAKE HOSE TO BRAKE TUBE - L/H	330	0	0	0.003	20.31%	0	9.7	16.3	9.5	
77 CJ0640101	SEC FRONT BRAKE HOSE TO BRAKE TUBE - R/H	330	0	0	0.003	37.50%	0	9.6	16.6	9.5	
	MULTI-SPINDEL										
78 CR0100040	SECURE FUEL FILLER PIPE TO BOOT	340	0	0	0.003	22.04%	0		3.0	5.1	3.0
79 CR0200229	ARM FUEL TANK TO UNDERBODY (20 GALLON)	330	0	0	0.003	25.76%	0	40.3	54.7	40.3	
80 CR0200240	ARM FUEL TANK TO UNDERBODY (25 GALLON)	330	0	0	0.003	13.64%	0	40.3	54.7	40.3	
81 CR0200270	INSTALL RETURN HOSE CLAMP	330	0	0	0.003	12.12%	0	2.0	5.3	2.0	
82 CR0200270	INSTALL PARK FILLER CLAMP	330	0	0	0.003	9.09%	0	1.8	4.5	1.1	
83 CL1400040	ACCEL BKT & BKT SPRING TO ENG. 3.0L	330	0	0	0.003	60.91%	0	12.7	17.3	12.7	
84 CL7900036	TIRE AND WHEEL ASSY. TO VEHICLE L/H	320	0	0	0.003	7.81%	0	113.0	153.0	113.0	
	MULTI-SPINDEL										
85 CL7900061	TIRE AND WHEEL ASSY. TO VEHICLE R/H	320	0	0	0.003	75.63%	0	114.6	153.0	113.0	
	MULTI-SPINDEL										
86 CL7900082	TIRE & WHEEL ASSY. TO VEH. L/H (ALUM.)	320	0	0	0.003	0.00%	0	103.2	159.0	92.0	
	MULTI-SPINDEL										
87 CL7900083	TIRE & WHEEL ASSY. TO VEH. R/H (ALUM.)	320	0	0	0.003	0.00%	0	97.5	159.0	92.0	
	MULTI-SPINDEL										
88 CR0200160	ASSEMBLE CAT. CONV/INLET PIPE TO MANIFOL	330	0	0	0.003	22.73%	0	34.4	50.6	34.3	

**OAKVILLE ASSEMBLY PLANT**  
**Torque Inspection Report**  
**Process Ranking Summary Report**

Dates: 10/01/96 - 10/31/96    Super All  
 Shifts: All Shifts    Class: All    Zoner: All    Ops: All    Printed on  
 Types: All    Status: All    10/12/96, 10:12 AM  
 Lists: All    TIBS v 6.71

**MANDATORY Processes**

Process Task Number	Process Description	Data Points								
		Total	High	Low	Slow	Mistakes	Checkouts	Varat	High Limit	Low Limit
59 CJ0401021	RTG REAR WHEEL ASSEMBLY TO REAR AXLE BACKUP	0	0	0	0.00%	0.00%	0		60.5	59.5
60 CJ0420090	ASB. REAR SOURCE HOSE BK. TO BACKING PL.	370	0	0	0.00%	54.00%	0	7.6	10.4	7.6
61 CJ0420091	ASB. REAR SOURCE HOSE BK. TO BACKING PL.	370	0	0	0.00%	47.37%	0	7.6	10.4	7.6
62 CJ0423908	REAR BRAKE TUBE TO BACKING PLATE L/S	370	0	0	0.00%	58.11%	0	14.8	20.2	14.8
63 CJ0423901	REAR BRAKE TUBE TO BACKING PLATE R/R	370	0	0	0.00%	52.70%	0	14.8	20.2	14.8
64 CJ0450030	ASSEMBLE SEC REAR BRAKE TUBES TO HOSES -	370	0	0	0.00%	29.48%	0	12.3	17.7	12.3
65 CJ0450031	ASSEMBLE SEC REAR BRAKE TUBES TO HOSES -	370	0	0	0.00%	29.39%	0	12.4	17.7	12.3
66 CJ2300070	SUB-ASSEMBLE BRAKE TUBES TO ABS EWD HOSE	360	0	0	0.00%	4.17%	0	11.3	20.9	11.3
67 CJ2310100	SECURE ABS RTB VALVE TO SIDERRAIL	360	0	0	0.00%	5.00%	0	25.9	34.5	25.3
68 CJ2300140	ASB. RT PNT BRAKE TUBE TO TUBE BUNDLE	0	0	0	0.00%	0.00%	0		18.6	11.6
	INCLUDES CJ2300140									
69 CJ2301000	ASB. RH PNT BRAKE TUBE TO TUBE BUNDLE	360	0	0	0.00%	27.70%	0	14.5	20.2	14.8
70 CJ2430090	SEC FRONT BRAKE TUBES TO MASTER CYLINDER	360	0	0	0.00%	19.10%	1	9.0	15.9	8.9
71 CJ2450070	SEC FRONT BRAKE TUBES TO JUNCTION BLOCK	0	0	0	0.00%	0.00%	0		20.2	14.8
	INCLUDES CJ2300140									
72 CJ2520100	ASSEMBLE FRONT CALIPER TO FRONT WHEEL	370	0	0	0.00%	9.44%	0	94.9	168.2	94.1
73 CJ2520101	ASSEMBLE FRONT CALIPER TO FRONT WHEEL	370	0	0	0.00%	18.92%	0	95.5	168.2	94.1
74 CJ2521100	ASSEMBLE FRONT CALIPER TO FRONT WHEEL	0	0	0	0.00%	0.00%	0		132.3	97.7
	BACKUP									
75 CJ2640070	SEC FRONT BRAKE HOSE TO CALIPER - L/S	370	0	0	0.00%	28.10%	0	46.7	63.3	46.7
76 CJ2640071	SEC FRONT BRAKE HOSE TO CALIPER - R/S	370	0	0	0.00%	28.30%	0	46.7	63.3	46.7
77 CJ2640100	SEC FRONT BRAKE HOSE TO BRAKE TUBE - L/S	360	0	0	0.00%	12.50%	0	10.0	16.3	9.5
78 CJ2640101	SEC FRONT BRAKE HOSE TO BRAKE TUBE - R/S	360	0	0	0.00%	34.77%	0	10.0	16.4	9.5
	MULTI-SPINDLE									
79 CJ0190040	SECURE FUEL FILLER PIPE TO BODY	360	0	0	0.00%	19.30%	0	3.0	5.1	3.0
80 CJ0200050	ARM FUEL TANK TO UNDERBODY (20 GALLON)	370	0	0	0.00%	44.50%	0	40.3	54.7	40.3
81 CJ0200060	ARM FUEL TANK TO UNDERBODY (25 GALLON)	370	0	0	0.00%	31.00%	0	40.4	54.7	40.3
82 CJ0200070	INSTALL RETURN HOSE CLAMP	370	0	0	0.00%	29.73%	0	2.0	5.3	2.0
83 CJ0200210	INSTALL FUEL FILLER CLAMP	370	0	0	0.00%	22.97%	0	1.2	4.3	1.1
84 CJ1400060	ACCEL BRKT & KEY SPRING TO BEGL. 3.0L	370	0	0	0.00%	43.95%	0	12.7	17.3	12.7
85 CL7900080	TIRE AND WHEEL ASY. TO VEHICLE L/S	360	0	0	0.00%	9.72%	0	114.0	153.0	113.0
	MULTI-SPINDLE									
86 CL7900081	TIRE AND WHEEL ASY. TO VEHICLE R/S	360	0	0	0.00%	20.63%	0	113.7	153.0	113.0
	MULTI-SPINDLE									
87 CL7900082	TIRE & WHEEL ASY. TO VEH. L/S (ALUM.)	360	0	0	0.00%	1.30%	0	102.7	159.0	98.0
	MULTI-SPINDLE									
88 CL7900085	TIRE & WHEEL ASY. TO VEH. R/S (ALUM.)	360	0	0	0.00%	1.30%	0	109.1	159.0	98.0
	MULTI-SPINDLE									

**OAKVILLE ASSEMBLY PLANT**  
**Torque Inspection Report**  
**Process Ranking Summary Report**

Dates: 09/01/96 - 09/30/96 Dept: All  
 Shifts: All Shifts Class: All  
 Types: All Zoner: All Report: All  
 Cars: All Where: All Listr: All  
 Printed on 10/02/96, 12:04 PM  
 File# v.6.71

**MANDATORY Processes**

Process Task Number	Process Description	Data Points							High Limit	Low Limit
		Total	High	Low	Slow	Shutoffs	Checkouts	Worst		
38 CJ0681021	REC REAR WHEEL ASSEMBLY TO REAR AXLE BACKUP	0	0	0	0.00%	0.00%	0		59.5	59.5
39 CJ0682090	ADM. REAR SOURCE HOSE BK. TO BACKING PL.	395	0	0	0.00%	36.94%	0	7.6	10.4	7.6
40 CJ0682091	ADM. REAR SOURCE HOSE BK. TO BACKING PL.	395	0	0	0.00%	39.49%	0	7.6	10.4	7.6
61 CJ0682100	REAR BRAKE TUBE TO BACKING PLATE L/S	395	0	0	0.00%	49.37%	0	14.8	20.2	14.8
62 CJ0682101	REAR BRAKE TUBE TO BACKING PLATE R/R	395	0	0	0.00%	39.04%	0	14.8	20.2	14.8
63 CJ0682102	ADM & REC REAR BRAKE TUBES TO HOSES -	395	0	0	0.00%	13.42%	0	12.3	17.7	12.3
64 CJ0682103	ADM & REC REAR BRAKE TUBES TO HOSES -	395	0	0	0.00%	75.92%	0	12.3	17.7	12.3
65 CJ0682104	SUB-ASSEMBLY BRAKE TUBES TO ADM KITS MODU	410	0	0	0.00%	25.61%	0	11.3	20.9	11.3
66 CJ0682105	SECURE ADM KIT VALVE TO SIDEWALL	410	0	0	0.00%	14.63%	0	26.4	34.5	26.4
67 CJ0682106	ADM. RH PT BRAKE TUBE TO TUBE BUNDLE	0	0	0	0.00%	0.00%	0		18.6	17.6
INCLUDES CJ0681140										
70 CJ0682110	ADM. RH PT BRAKE TUBE TO TUBE BUNDLE	405	0	0	0.00%	27.14%	0	14.8	20.2	14.8
69 CJ0683040	REC FRONT BRAKE TUBES TO MASTER CYLINDER	410	0	0	0.00%	35.37%	0	9.4	19.4	8.9
70 CJ0683070	REC FRONT BRAKE TUBES TO JUNCTION BLOCK	0	0	0	0.00%	0.00%	0		20.2	14.8
INCLUDES CJ0682140										
71 CJ0684100	ASSEMBLE FRONT CALIPER TO FRONT KNUCKLE	395	0	0	0.00%	6.35%	0	95.3	148.2	95.3
72 CJ0684101	ASSEMBLE FRONT CALIPER TO FRONT KNUCKLE	395	0	0	0.00%	2.35%	0	95.4	148.2	95.1
73 CJ0684102	ASSEMBLE FRONT CALIPER TO FRONT KNUCKLE	0	0	0	0.00%	0.00%	0		132.3	97.7
BACKUP										
74 CJ0684090	REC FRONT BRAKE HOSE TO CALIPER - L/S	395	0	0	0.00%	31.45%	0	46.7	63.3	46.7
75 CJ0684091	REC FRONT BRAKE HOSE TO CALIPER - R/S	395	0	0	0.00%	30.38%	0	46.7	63.3	46.7
76 CJ0684092	REC FRONT BRAKE HOSE TO BRAKE TUBE - L/S	405	0	0	0.00%	26.46%	0	9.7	16.5	9.3
77 CJ0684093	REC FRONT BRAKE HOSE TO BRAKE TUBE - R/S	405	0	0	0.00%	29.40%	0	9.7	16.6	9.3
MULTI-SPINNABLE										
78 CJ0700060	SECURE FUEL FILLER PIPE TO BODY	395	0	0	0.00%	0.00%	0	3.0	5.1	3.0
79 CJ0700250	ADM FUEL TANK TO UNDERBODY (20 GALLON)	395	0	0	0.00%	38.38%	0	44.3	54.7	44.3
80 CJ0700260	ADM FUEL TANK TO UNDERBODY (25 GALLON)	395	0	0	0.00%	29.11%	0	44.4	54.7	44.3
81 CJ0700070	INSTALL RETURN HOSE CLAMP	395	0	0	0.00%	22.70%	0	2.0	5.2	2.0
82 CJ0700220	INSTALL FUEL FILLER CLAMP	395	0	0	0.00%	18.99%	0	1.2	4.3	1.1
83 CJ1400060	ACCEL. BREST & KEY SPRING TO ABS. 3.0L	395	0	0	0.00%	35.44%	0	18.7	27.3	18.7
84 CL7900080	TIRE AND WHEEL ASY. TO VEHICLE L/S	405	0	0	0.00%	4.94%	0	113.0	153.0	113.0
MULTI-SPINNABLE										
85 CL7900081	TIRE AND WHEEL ASY. TO VEHICLE R/S	405	0	0	0.00%	9.86%	0	113.6	153.0	113.0
MULTI-SPINNABLE										
86 CL7900082	TIRE & WHEEL ASY. TO VEH. L/S (ALUM.)	405	0	0	0.00%	0.00%	0	105.1	159.0	92.0
MULTI-SPINNABLE										
87 CL7900083	TIRE & WHEEL ASY. TO VEH. R/S (ALUM.)	405	0	0	0.00%	1.22%	0	102.2	159.0	92.0
MULTI-SPINNABLE										

SAPT

96

**OAKVILLE ASSEMBLY PLANT**  
**Torque Inspection Report**  
**Process Ranking Summary Report**

Dates: 02/01/96 - 02/27/96 Dept: All  
 Shifts: All Shifts Classes: All Types: All Zones: All Super: All Car: All Xders: All Lists: All Printed on 02/05/96, 10:08 AM  
 T188 v 6.71

Process Rank Number	Process Description	Data Points									
		Total	High	Low	Slow	Mistakes	Checkouts	Worst	High Limit	Low Limit	
19 C40623100	ASSEMBLE REAR JOURNEY HOSE BHK. TO BACKING PL.	400	0	0	0.00%	42.75%	0	7.6	18.4	7.4	
40 C40623091	ASSEMBLE REAR JOURNEY HOSE BHK. TO BACKING PL.	400	0	0	0.00%	41.25%	0	7.4	18.4	7.4	
61 C40623100	REAR BRAKE TUBE TO BACKING PLATE L/S	400	0	0	0.00%	33.75%	0	16.8	20.2	16.8	
62 C40623101	REAR BRAKE TUBE TO BACKING PLATE R/H	400	0	0	0.00%	32.75%	0	14.8	20.2	14.8	
<b>CABIN</b>											
45 C42330090	ASSEMBLE SEC REAR BRAKE TUBES TO HOSES -	400	0	0	0.00%	19.50%	0	12.4	17.7	12.3	
46 C42330091	ASSEMBLE SEC REAR BRAKE TUBES TO HOSES -	400	0	0	0.00%	23.75%	0	12.3	17.7	12.3	
48 C42330070	SUB-ASSEMBLE BRAKE TUBES TO ABS KITS HOSE	390	0	0	0.00%	26.51%	0	11.6	20.9	11.3	
49 C42330100	SECURE ABS KIT VALVE TO SUBASBL	390	0	0	0.00%	19.25%	0	26.2	34.3	25.5	
57 C42330040	ASSEMBLE SEC BRAKE TUBE TO TUBE SANGLE	0	0	0	0.00%	0.00%	0	18.6	17.6		
INCLUDES C42330140											
48 C42330100	ASSEMBLE SEC BRAKE TUBE TO TUBE SANGLE	390	0	0	0.00%	44.87%	0	14.8	20.2	14.8	
49 C42330070	SEC FRONT BRAKE TUBES TO MASTER CYLINDER	390	0	0	0.00%	47.44%	0	9.1	15.9	8.9	
70 C42330070	SEC FRONT BRAKE TUBES TO JUNCTION BLOCK	0	0	0	0.00%	0.00%	0	26.2	16.8		
INCLUDES C42330140											
71 C40620100	ASSEMBLE FRONT CALIPER TO FRONT KNUCKLE	400	0	0	0.00%	3.75%	0	93.1	168.2	94.1	
72 C40620101	ASSEMBLE FRONT CALIPER TO FRONT KNUCKLE	400	0	0	0.00%	3.00%	0	95.6	168.2	94.1	
73 C40621100	ASSEMBLE FRONT CALIPER TO FRONT KNUCKLE	0	0	0	0.00%	0.00%	0	132.3	177.7		
<b>BACKUP</b>											
74 C42440090	SEC FRONT BRAKE HOSE TO CALIPER - L/R	400	0	0	0.00%	41.25%	0	46.7	49.3	46.7	
75 C42440091	SEC FRONT BRAKE HOSE TO CALIPER - R/R	400	0	0	0.00%	36.25%	0	46.7	49.3	46.7	
76 C42440100	SEC FRONT BRAKE HOSE TO BRAKE TUBE - L/R	390	0	0	0.00%	28.21%	0	9.7	16.5	9.5	
77 C42440101	SEC FRONT BRAKE HOSE TO BRAKE TUBE - R/R	390	0	0	0.00%	26.92%	0	10.3	16.6	9.5	
<b>MULTI-SPINDLE</b>											
78 C40700040	ASSEMBLE FUEL FILLER PIPE TO BODY	420	0	0	0.00%	0.00%	0	3.0	5.1	3.0	
79 C40600040	ASSEMBLE FUEL TANK TO BODY (20 GALLONS)	400	0	0	0.00%	30.00%	0	40.3	54.7	40.3	
80 C40600040	ASSEMBLE FUEL TANK TO BODY (15 GALLONS)	400	0	0	0.00%	30.00%	0	40.3	54.7	40.3	
81 C40600070	INSTALL RETURN HOSE CLAMP	400	0	0	0.00%	18.75%	0	2.0	5.2	2.0	
82 C40600070	INSTALL FUEL FILLER CLAMP	400	0	0	0.00%	20.00%	0	1.2	4.3	1.1	
83 C41400040	ADJUST BRAKE & SET SPRINGS TO ENCL. S.01	400	0	0	0.00%	47.50%	0	12.7	17.3	12.7	
84 C47900080	TIRE AND WHEEL ASSY. TO VEHICLE L/R	390	0	0	0.00%	16.67%	0	115.1	153.0	113.0	
<b>MULTI-SPINDLE</b>											
85 C47900081	TIRE AND WHEEL ASSY. TO VEHICLE R/R	390	0	0	0.00%	14.16%	0	114.5	155.0	113.0	
<b>MULTI-SPINDLE</b>											
86 C47900082	TIRE & WHEEL ASSY. TO VEH. L/R (ALUM.)	390	0	0	0.00%	2.50%	0	107.5	159.0	92.0	
<b>MULTI-SPINDLE</b>											
87 C47900083	TIRE & WHEEL ASSY. TO VEH. R/R (ALUM.)	390	0	0	0.00%	2.50%	0	109.2	159.0	92.0	
<b>MULTI-SPINDLE</b>											
88 C40600100	ASSEMBLE CAT. CONV/INLET PIPE TO MANIFOLD	400	0	0	0.00%	53.75%	0	34.3	50.6	34.3	

**OAKVILLE ASSEMBLY PLANT**  
**Torque Inspection Report**  
**Process Ranking Summary Report**

Total: 04/01/94 - 04/30/94 Dept: All  
 Shifts: All Shifts Closest: All Zone: All Cars: All Printed on  
 Type: All Super: All Drivers: All 07/17/94, 7:53 AM  
 List: All Time v 6.71

**MANDATORY Processes**

Process Part Number	Process Description	Data Points						High	Low	High Limit	Low Limit
		Total	High	Low	100%	Statutes	Checkouts				
199 CJ0681027	SEC REAR BRAKE ASSEMBLY TO REAR AXLE SHCOP	0	0	0	0.00%	0.00%	0	80.5	89.5	80.5	89.5
40 CJ0682094	ASB. REAR BRAKE HOSE END. TO BACKING PL.	400	0	0	0.00%	68.75%	0	7.4	10.4	7.4	10.4
64 CJ0682095	ASB. REAR BRAKE HOSE END. TO BACKING PL.	400	0	0	0.00%	58.75%	0	7.6	10.4	7.6	10.4
62 CJ0682100	REAR BRAKE TUBE TO BACKING PLATE L/S	400	0	0	0.00%	22.50%	0	15.1	20.2	14.8	14.8
63 CJ0682101	REAR BRAKE TUBE TO BACKING PLATE R/H	400	0	0	0.00%	28.00%	0	14.8	20.2	14.8	14.8
64 CJ0682090	ASBBS & SEC REAR BRAKE TUBES TO HOSES -	400	0	0	0.00%	18.50%	0	12.3	17.7	12.3	17.7
65 CJ0682091	ASBBS & SEC REAR BRAKE TUBES TO HOSES -	400	0	0	0.00%	18.75%	0	12.3	17.7	12.3	17.7
66 CJ0680070	SLD-ASSEMBLY BRAKE TUBES TO ABS EVO HOSE	400	0	0	0.00%	15.00%	0	11.4	20.9	11.3	20.9
67 CJ0681010	SECURE ABS EVO VALVE TO SIDECASTL	400	0	0	0.00%	15.75%	0	26.5	34.5	25.5	34.5
68 CJ0680040	ASB. OR ABS BRAKE TUBE TO TUBE BUNDLE	0	0	0	0.00%	0.00%	0	18.6	21.4	18.6	21.4
69 CJ0680100	ASB. OR ABS BRAKE TUBE TO TUBE BUNDLE	400	0	0	0.00%	37.50%	0	14.8	20.2	14.8	20.2
70 CJ0680090	SEC FRONT BRAKE TUBES TO MASTER CYLINDER	400	0	0	0.00%	32.50%	0	9.2	15.9	8.9	15.9
71 CJ0680070	SEC FRONT BRAKE TUBES TO JUNCTION BLOCK	0	0	0	0.00%	0.00%	0	20.2	24.8	20.2	24.8
72 CJ0680070	ASSEMBLE FRONT CALIPER TO FRONT BRACKET	400	0	0	0.00%	3.00%	0	95.1	100.2	94.1	100.2
73 CJ0680101	ASSEMBLE FRONT CALIPER TO FRONT BRACKET	400	0	0	0.00%	1.25%	0	95.2	100.2	94.1	100.2
74 CJ0681100	ASSEMBLE FRONT CALIPER TO FRONT BRACKET	0	0	0	0.00%	0.00%	0	132.3	137.7	132.3	137.7
75 CJ0640090	SEC FRONT BRAKE HOSE TO CALIPER - L/S	400	0	0	0.00%	38.75%	0	46.7	65.3	46.7	65.3
76 CJ0640091	SEC FRONT BRAKE HOSE TO CALIPER - R/S	400	0	0	0.00%	35.00%	0	46.7	65.3	46.7	65.3
77 CJ0640100	SEC FRONT BRAKE HOSE TO BRAKE TUBE - L/S	400	0	0	0.00%	27.50%	0	9.5	16.5	9.5	16.5
78 CJ0640101	SEC FRONT BRAKE HOSE TO BRAKE TUBE - R/S	400	0	0	0.00%	12.50%	0	9.5	16.5	9.5	16.5
<b>MULTI-SPINDLE</b>											
79 CJ0100040	SECURE FUEL FILLER PIPE TO BODY	400	0	0	0.00%	13.75%	0	3.0	5.1	3.0	5.1
80 CJ0600050	ARM FUEL TANK TO BODY/C20 GALLON	400	0	0	0.00%	55.00%	0	40.9	54.7	40.3	54.3
81 CJ0600040	ARM FUEL TANK TO UNDERKIT/C23 GALLON	400	0	0	0.00%	27.50%	0	40.3	54.7	40.3	54.3
82 CJ0600070	INSTALL RETURN HOSE CLAMP	400	0	0	0.00%	20.00%	0	2.0	5.2	2.0	5.2
83 CJ0600020	INSTALL FUEL FILLER CLAMP	400	0	0	0.00%	21.25%	0	1.4	4.5	1.1	4.5
84 CJ0640060	ADJUST BODY & ACT SWING TO ENG. 3.0L	400	0	0	0.00%	37.50%	0	12.7	17.3	12.7	17.3
85 CJ7900000	TIRE AND WHEEL ASY. TO VEHICLE L/S	350	0	0	0.00%	16.67%	0	113.3	153.0	113.0	153.0
<b>MULTI-SPINDLE</b>											
86 CJ7900001	TIRE AND WHEEL ASY. TO VEHICLE R/S	350	0	0	0.00%	10.61%	0	113.4	153.0	113.0	153.0
<b>MULTI-SPINDLE</b>											
87 CJ7900002	TIRE & WHEEL ASY. TO VEH. L/S (ALUM.)	350	0	0	0.00%	0.00%	0	107.3	139.0	98.0	139.0
88 CJ7900003	TIRE & WHEEL ASY. TO VEH. R/S (ALUM.)	350	0	0	0.00%	1.32%	0	111.1	139.0	98.0	139.0
<b>MULTI-SPINDLE</b>											
Spec change: 06/06/96											

--- Page #3 ---

**OAKVILLE ASSEMBLY PLANT**  
**Torque Inspection Report**  
**Process Ranking Summary Report**

Date: 05/01/96 - 05/31/96	Dept: All	Dept: All	Dept: All	Printed on
Shifts: All Shifts	Class: All	Zone: All	Shift: All	06/05/96, 11:05 AM
	Type: All	Report: All	List: All	Torque v 6.71

**MANDATORY Processes**

Process Task Number	Process Description	Data Points						High Limit		
		Total	High	Low	Max	Min	Checkups	Worst	Limit	Unit
58 CJ0401009	RSC REAR WHEEL ASSEMBLY TO REAR AXLE BACKUP	0	0	0	0.000	0.000%	0		80.5	99.5
59 CJ0401021	RSC REAR WHEEL ASSEMBLY TO REAR AXLE BACKUP	0	0	0	0.000	0.000%	0		80.5	99.5
60 CJ0423006	ADS. REAR JOUNCE BONE R/R. TO BACKING PL.	420	0	0	0.000	39.525	0	7.6	10.4	7.6
61 CJ0423007	ADS. REAR JOUNCE BONE R/R. TO BACKING PL.	420	0	0	0.000	34.705	0	7.6	10.4	7.6
62 CJ0423106	REAR BRAKE TUBE TO BACKING PLATE L/S	420	0	0	0.000	39.925	0	14.8	20.2	14.8
63 CJ0423107	REAR BRAKE TUBE TO BACKING PLATE R/R	420	0	0	0.000	29.810	0	14.8	20.2	14.8
64 CJ0440020	ASSEMBLE REAR BRAKE TUBES TO HOMER -	420	0	0	0.000	29.340	0	12.6	17.7	12.6
65 CJ0450031	ASSEMBLE REAR BRAKE TUBES TO HOMER -	420	0	0	0.000	16.475	0	12.3	17.7	12.3
66 CJ0460076	ASSEMBLE BRAKE TUBES TO ABS AND HOMER	420	0	0	0.000	12.785	0	11.4	20.9	11.3
67 CJ0461040	SECURE ABS AND HOMER VALVE TO BACKPLATE	420	0	0	0.000	9.300	0	26.6	34.5	26.5
68 CJ0460140	ASSEMBLE ABS PRT BRAKE TUBE TO TUBE HANDLE INCLUDES CA2650140	250	0	0	0.000	22.000	0	11.6	18.6	11.6
69 CJ0430100	ASSEMBLE ABS PRT BRAKE TUBE TO TUBE HANDLE	100	0	0	0.000	39.540	0	14.8	20.2	14.8
70 CJ0430076	RSC FRONT BRAKE TUBES TO MASTER CYLINDER	420	0	0	0.000	34.805	0	9.5	15.9	8.9
71 CJ0430100	ASSEMBLE FRONT CALIPER TO FRONT KNUCKLE	420	0	0	0.000	4.700	0	94.9	100.2	94.1
72 CJ0430101	ASSEMBLE FRONT CALIPER TO FRONT KNUCKLE	420	0	0	0.000	7.145	0	97.4	100.3	94.1
73 CJ0431100	ASSEMBLE FRONT CALIPER TO FRONT KNUCKLE BACKUP	0	0	0	0.000	8.000	0	132.3	97.7	
74 CJ0440070	RSC FRONT BRAKE BONE TO CALIPER - L/S	420	0	0	0.000	39.295	0	46.7	63.8	46.7
75 CJ0440071	RSC FRONT BRAKE BONE TO CALIPER - R/R	420	0	0	0.000	36.325	0	46.7	63.8	46.7
76 CJ0440076	RSC FRONT BRAKE BONE TO BRAKE TUBE - L/S	420	0	0	0.000	16.400	0	9.5	16.5	9.5
77 CJ0440101	RSC FRONT BRAKE BONE TO BRAKE TUBE - R/R	420	0	0	0.000	16.825	0	9.5	16.6	9.5
78 CJ0490040	SECURE FUEL FILLER PIPE TO BODY	420	0	0	0.000	15.405	0	8.0	9.1	3.0
79 CJ0490050	ASSEMBLE FUEL TANK TO UNDERBODY (20 GALLONS)	420	0	0	0.000	20.995	0	40.5	54.7	40.5
80 CJ0490055	ASSEMBLE FUEL TANK TO UNDERBODY (25 GALLONS)	420	0	0	0.000	20.795	0	40.4	54.7	40.5
81 CJ0490070	INSTALL RETAIN BOLT CLAMP	420	0	0	0.000	26.900	0	8.0	9.2	2.0
82 CJ0490080	INSTALL FUEL FILLER CLAMP	420	0	0	0.000	17.600	0	1.1	4.5	1.1
83 CJ1400040	ASSEMBLE JACKET & RIV SPRING TO AXLE. 3.0L	420	0	0	0.000	34.700	0	12.7	17.3	12.7
84 CJ7900050	TIRE AND WHEEL ASSEMBLY TO VEHICLE L/R	420	0	0	0.000	12.795	0	113.7	123.0	113.0
85 CJ7900051	TIRE AND WHEEL ASSEMBLY TO VEHICLE R/R	420	0	0	0.000	24.425	0	113.4	123.0	113.0
86 CJ9000100	ASSEMBLE CAT. CONV/INLET PIPE TO MANIFOL	420	0	0	0.000	35.715	0	34.4	50.6	34.3
87 CJ9100140	ASSEMBLE INLET PIPE/REGULATOR TO MANIFOL	420	0	0	0.000	17.600	0	31.5	51.4	31.4
88 CJ9000090	ASSEMBLE GASKET AND FLEX COUPLING TO F-P	420	0	0	0.000	19.775	0	34.0	46.0	34.0
89 CJ9000110	ASSEMBLE GASKET AND FLEX COUPLING TO NUT	420	0	0	0.000	4.655	0	34.5	50.3	35.0

AMERICAN JLG  
PROPORTIONAL  
Y2K Audit Findings

**DAVILLE ASSEMBLY PLANT**  
Torque Inspection Report  
Process Ranking Summary Report  
01/01/98 - 07/31/98, both shifts

**ROUTINE Processes**

Process Number	Process Description	Data Sets					Data Points					Hi Value	Lo Value	Hi-Low Limit
		Total	H1	Lo	Hs	Total	H1	Lo	Hs	Total	H1			
38 CJ0021046	ABG/ABG. BOOSTER TO MASTER CYL. (MANUAL)	44	0	0	0	0.00	220	0	0	0.00	23.3	35.4	33.7	
39 CJ0021050	MANUAL OPERATION	44	0	0	0	0.00	220	0	0	0.00	14.1	29.7	15.8	
40 CJ0021052	BOOSTER & BRAKE SUPP. TO BRAKE PANEL. C4 BUT	44	0	0	0	0.00	220	0	0	0.00	24.3	31.9	26.3	
41 CJ0021056	BOOSTER & BRAKE SUPP. TO BRAKE PANEL. C2 BUT	44	0	0	0	0.00	220	0	0	0.00	11.3	18.8	11.3	
42 CJ0021060	ABG. BRAKE TUBE TO PROPORTIONING VALVE	49	0	0	0	0.00	245	0	0	0.00	11.3	18.5	11.3	
43 CJ0021070	ABG. LE. REAR BRAKE TUBE TO TUBE BUNDLE	49	0	0	0	0.00	245	0	0	0.00	12.4	18.5	11.5	
44 CJ0021074	ABG. REAR BRAKE LINE BKT. TO BACKING PLATE	46	0	0	0	0.00	220	0	0	0.00	7.6	18.6	7.6	
45 CJ0021091	ABG. REAR BRAKE LINE BKT. TO BACKING PLATE	46	0	0	0	0.00	220	0	0	0.00	7.6	18.6	7.6	
46 CJ0021095	REAR BRAKE TUBE TO BACKING PLATE L/S	44	0	0	0	0.00	220	0	0	0.00	14.8	20.2	14.8	
47 CJ0021071	REAR BRAKE TUBE TO BACKING PLATE R/H	46	0	0	0	0.00	220	0	0	0.00	14.8	20.2	14.8	
48 CJ0021079	ABG. & H/C REAR BRAKE TUBES TO HOSES - L/S	47	0	0	0	0.00	225	0	0	0.00	13.0	17.7	12.3	
49 CJ0021081	ABG. & H/C REAR BRAKE TUBES TO HOSES - R/H	47	0	0	0	0.00	225	0	0	0.00	12.4	17.7	12.3	
50 CJ0021079	H/C-ABG BRAKE TUBES TO ABS H/C MODULE	56	0	0	0	0.00	255	0	0	0.00	12.8	20.9	11.5	
51 CJ0021049	SWING AND HYD VALVE TO STEERING	49	0	0	0	0.00	245	0	0	0.00	25.8	34.5	25.3	
52 CJ0021040	ASSEMBLE REAR BRAKE TUBE TO JUNCTION BLOCK (EXCLUDES CJ002140)	49	0	0	0	0.00	245	0	0	0.00	12.2	18.6	11.6	
53 CJ0021090	REAR BRAKE TUBE TO MASTER CYLINDER	49	0	0	0	0.00	220	0	0	0.00	8.7	18.7	8.7	
54 CJ0021070	REAR BRAKE TUBE TO JUNCTION BLOCK. EXCLUDES CJ002140	49	0	0	0	0.00	220	0	0	0.00	11.7	18.6	11.6	
55 CJ0021046	ASSEMBLE FRONT CALIPER TO FRONT BRAKE L/S	44	0	0	0	0.00	220	0	0	0.00	98.3	168.2	96.1	
56 CJ0021041	ASSEMBLE FRONT CALIPER TO FRONT BRAKE R/H	46	0	0	0	0.00	220	0	0	0.00	98.4	168.2	96.1	
57 CJ0021095	REC FRONT BRAKE HOSE TO CALIPER - L/S	48	0	0	0	0.00	240	0	0	0.00	46.7	62.3	46.7	
58 CJ0021097	REC FRONT BRAKE HOSE TO CALIPER - R/H	48	0	0	0	0.00	240	0	0	0.00	46.7	62.3	46.7	
59 CJ0021090	REC FRONT BRAKE HOSE TO BRAKE TUBE - L/S	49	0	0	0	0.00	245	0	0	0.00	9.3	16.6	9.3	
60 CJ0021091	REC FRONT BRAKE HOSE TO BRAKE TUBE - R/H	49	0	0	0	0.00	245	0	0	0.00	10.5	16.6	9.8	
61 CJ0100040	ASSEMBLE FUEL FILLER PIPE TO BODY	44	0	0	0	0.00	220	0	0	0.00	3.8	5.1	3.0	
62 CJ0021046	ASSEMBLE FUEL TANK TO UNDERBODY C25 BALLOON	47	0	0	0	0.00	225	0	0	0.00	48.3	54.7	40.3	
63 CJ0021040	ASSEMBLE FUEL TANK TO UNDERBODY C25 BALLOON	47	0	0	0	0.00	225	0	0	0.00	48.3	54.7	40.3	
64 CJ0021078	UNIFALL RETURN HOSE CLAMP	47	0	0	0	0.00	225	0	0	0.00	2.1	3.3	2.0	
65 CJ0021026	UNIFALL FUEL FILLER CLAMP	47	0	0	0	0.00	225	0	0	0.00	1.7	4.5	1.1	
66 CL7900068	TIRE AND WHEEL ASY. TO VEHICLE L/S	44	0	0	0	0.00	220	0	0	0.00	119.3	193.0	119.0	340
67 CL7900061	TIRE AND WHEEL ASY. TO VEHICLE R/S	44	0	0	0	0.00	220	0	0	0.00	115.4	193.0	113.0	340
68 CJ0021040	ASSEMBLE CAT. DOW/VULTE PIPE TO MANIFOLD	46	0	0	0	0.00	226	0	0	0.00	34.3	50.6	34.3	
69 CJ0100140	ASSEMBLE INLET PIPE/REGULATOR TO MANIFOLD	46	0	0	0	0.00	226	0	0	0.00	31.3	51.4	31.4	
70 DN0021090	ASSEMBLE GASKET AND FLUID COUPLING TO T-PIPE	46	0	0	0	0.00	226	0	0	0.00	34.3	46.6	34.0	
71 DM9000110	ASSEMBLE GASKET AND FLUID COUPLING TO RUFFLE	46	0	0	0	0.00	226	0	0	0.00	36.6	58.3	36.9	
72 CJ0021026	DOOR LATCH ASSEMBLY TO CENTER DOOR MFT	46	0	0	0	0.00	220	0	0	0.00	10.2	15.6	10.2	
73 BT1100050	TRIMABLE OUTER CONTROL LEVER TO AXLES/HAMS	46	0	0	0	0.00	220	0	0	0.00	10.3	14.7	10.3	
74 BT1400100	WIRING CABLE BRKT TO AXLES TURNS	46	0	0	0	0.00	220	0	0	0.00	19.8	32.6	19.2	
75 ED2500100	14305 TO ALTERNATOR CONNECTIONS (3.6L)	46	0	0	0	0.00	220	0	0	0.00	4.8	9.2	4.8	

ABOM0401001  
ABOP0100000  
Y2Subd040101

**OMVILLE ASBESTOS PLANT**  
**Torque Inspection Report**  
**Process Banking Summary Report**  
**02/01/96 - 02/29/96, Both Shifts**

**PREDATORY Processes**

Work	Process Number	Process Description	Data Sets						Data Points						Hf	Ls
			Total	Hf	Ls	Rlo	Total	Hf	Ls	Rlo	Upper Limit	Lower Limit				
38	CJ4021040	SLV/ABR. BOOSTER TO MASTER CYL. (CHANNEL)	64	0	0	0.00	320	0	0	0.00	25.7	25.4	25.7			
39	CJ4020100	MANUAL OPERATION	64	0	0	0.00	320	0	0	0.00	19.9	20.7	19.9			
40	CJ4020000	BOOSTER & BRAKE SUPP. TO BRAKE PANEL. (4 SET)	64	0	0	0.00	320	0	0	0.00	34.3	31.9	34.3			
41	CJ4020000	BOOSTER & BRAKE SUPP. TO BRAKE PANEL. (2 SET)	64	0	0	0.00	320	0	0	0.00	11.5	10.5	11.5			
42	CJ4020000	ABR. BRAKE TUBE TO PROPORTIONING VALVE	64	0	0	0.00	320	0	0	0.00	11.7	10.5	11.5			
43	CJ4020000	ABR. LH REAR BRAKE TUBE TO TUBE BUNDLE	64	0	0	0.00	320	0	0	0.00	11.9	10.5	11.5			
44	CJ4020000	ABR. RH REAR BRAKE TUBE TO TUBE BUNDLE	64	0	0	0.00	320	0	0	0.00	11.9	10.5	11.5			
45	CJ4020000	34070 - AIRPLANE GUN	64	0	0	0.00	320	0	0	0.00	7.6	10.4	7.6			
46	CJ4020000	ABR. REAR SOURCE HOSE END. TO BACKING PLATE	64	0	0	0.00	320	0	0	0.00	7.6	10.4	7.6			
47	CJ4020001	ABR. REAR SOURCE HOSE END. TO BACKING PLATE	64	0	0	0.00	320	0	0	0.00	14.6	20.2	14.6			
48	CJ4020100	REAR BRAKE TUBE TO BACKING PLATE L/R	64	0	0	0.00	320	0	0	0.00	14.8	20.2	14.8			
49	CJ4020101	REAR BRAKE TUBE TO BACKING PLATE R/H	64	0	0	0.00	320	0	0	0.00	14.8	20.2	14.8			
50	CJ4020000	BRKT	64	0	0	0.00	320	0	0	0.00	12.3	17.7	12.3			
51	CJ4020030	ASSEMBLE & SEC REAR BRAKE TUBES TO SORBS - L/R	64	0	0	0.00	320	0	0	0.00	12.3	17.7	12.3			
52	CJ4020031	ASSEMBLE & SEC REAR BRAKE TUBES TO SORBS - R/R	64	0	0	0.00	320	0	0	0.00	11.5	20.5	11.5			
53	CJ4020070	SECURE BRAKE TUBES TO ABS STO MODULE	64	0	0	0.00	320	0	0	0.00	22.7	34.5	22.7			
54	CJ4020100	ASSEMBLE ABS HYD VALVE TO SHOCKBALL	64	0	0	0.00	320	0	0	0.00	12.1	18.6	11.6			
55	CJ4020140	INCLUDE CJ4020140	64	0	0	0.00	320	0	0	0.00	4.9	15.9	4.9			
56	CJ4020000	SECURE BRAKE TUBES TO JUNCTION BLOCK	64	0	0	0.00	320	0	0	0.00	12.5	18.6	11.6			
57	CJ4020070	INCLUDE CJ4020140	64	0	0	0.00	320	0	0	0.00	26.2	168.2	26.1			
58	CJ4020100	ASSEMBLE FRONT CALIPER TO FRONT KNUCKLE L/R	64	0	0	0.00	320	0	0	0.00	56.7	168.2	56.7			
59	CJ4020101	ASSEMBLE FRONT CALIPER TO FRONT KNUCKLE R/R	64	0	0	0.00	320	0	0	0.00	44.9	168.2	44.7			
60	CJ4020090	SEC FRONT BRAKE HOLE TO CALIPER - L/R	64	0	0	0.00	320	0	0	0.00	44.7	168.2	44.7			
61	CJ4020091	SEC FRONT BRAKE HOLE TO BRAKE TUBE - L/R	64	0	0	0.00	320	0	0	0.00	5.5	16.5	5.5			
62	CJ4020100	SEC FRONT BRAKE HOLE TO BRAKE TUBE - R/R	64	0	0	0.00	320	0	0	0.00	9.3	16.6	9.3			
63	CJ4020000	MULTI-SPINNLE	64	0	0	0.00	320	0	0	0.00	3.0	5.1	3.0			
64	CJ4020040	INCLUDE FUEL PELLIC PIPE TO BODY	64	0	0	0.00	320	0	0	0.00	44.4	94.7	44.3			
65	CJ4020050	ASSEM FUEL TANK TO UNDERBT (20 GALLON)	64	0	0	0.00	320	0	0	0.00	41.0	94.7	40.3			
66	CJ4020040	ASSEM FUEL TANK TO UNDERBT (25 GALLON)	64	0	0	0.00	320	0	0	0.00	2.0	5.2	2.0			
67	CJ4020070	INSTALL RETURN HOSE CLAMP	64	0	0	0.00	320	0	0	0.00	1.8	4.5	1.1			
68	CJ4020020	INSTALL FUEL FILLING CLAMP	64	0	0	0.00	320	0	0	0.00	133.1	193.8	173.0	FAS	%	
69	CJ4020060	TIRES AND WHEEL ASM. TO VEHICLE L/R	64	0	0	0.00	320	0	0	0.00	193.0	193.0	193.0			
70	CJ4020061	TIRES AND WHEEL ASM. TO VEHICLE R/R	64	0	0	0.00	320	0	0	0.00	24.3	30.6	24.3			
71	CJ4020100	ASSEMBLE CAT. CORN/VALVE PIPE TO MANIFOLD	64	0	0	0.00	320	0	0	0.00	31.4	31.4	31.4			
72	CJ4020100	ASSEMBLE INLET PIPE/REDUCER TO MANIFOLD	64	0	0	0.00	320	0	0	0.00	35.0	44.8	34.6			
73	CJ4020090	ASSEMBLE BANJOE AND FLEX COUPLING TO Y-PIPE	64	0	0	0.00	320	0	0	0.00	35.9	56.3	35.9			
74	CJ4020010	ASSEMBLE BANJOE AND FLEX COUPLING TO Y-PIPE	64	0	0	0.00	320	0	0	0.00	19.2	15.8	10.2			
75	CJ4020010	SEC LATER AMMENDMENT TO CENTER RAD SUPT	64	0	0	0.00	320	0	0	0.00	10.5	14.7	10.5			
76	CJ4020010	TRANSMISSION OUTER CONTROL LEVER TO AXLES TRANS	64	0	0	0.00	320	0	0	0.00	19.3	32.3	19.2			
77	CJ4020010	SHFT CABLE JACKET TO AXLES TRANS.	64	0	0	0.00	320	0	0	0.00	4.8	9.2	4.8			
78	CJ4020010	14303 TO ALTERNATOR CONNECTIONS (3.6L)	64	0	0	0.00	320	0	0	0.00						

ASSEMBLY JNL  
PROPORTIONAL  
T260001[glitch]

**CLEVELAND ASSEMBLY PLANT**  
**Torque Inspection Report**  
**Process Ranking Summary Report**  
03/01/96 - 03/31/96, Both Shifts

**MANUFACTORY Processes**

Process Task Number	Process Description	Data Sets			Data Points			St Worst Limit	Lo Best Limit	
		Total	Ht	Lo	Total	Ht	Lo			
37	CJ0100100	HOOTER & BRAKE SUPP. TO DASH PANEL. 14 NUT	81	0	0	0.00	405	0	0.00	16.4
48	CJ0100090	HOOTER & BRAKE SUPP. TO DASH PANEL. 17 NUT	81	0	0	0.00	405	0	0.00	24.3
41	CJ0100090	AIR. BRAKE TUBE TO PROPORTIONING VALVE	82	0	0	0.00	410	0	0.00	11.5
42	CJ0100090	AIR/WL BRAKE BRAKE TUBE TO TUBE BUNDLE	82	0	0	0.00	410	0	0.00	11.5
43	CJ0100090	AIR/WL BRAKE BRAKE TUBE TO TUBE BUNDLE SWING - AIRPLANE GUN	82	0	0	0.00	410	0	0.00	11.5
44	CJ0420094	AIR. BRAKE BRAKE BRAKE MM. TO BACKING PLATE	79	0	0	0.00	395	0	0.00	7.6
45	CJ04200971	AIR. BRAKE BRAKE BRAKE MM. TO BACKING PLATE	79	0	0	0.00	395	0	0.00	7.6
46	CJ0420100	REAR BRAKE TUBE TO BACKING PLATE L/R	79	0	0	0.00	395	0	0.00	14.8
47	CJ0420101	REAR BRAKE TUBE TO BACKING PLATE R/R	79	0	0	0.00	395	0	0.00	14.8
		MATERIAL								
48	CJ0450090	AIR/WL REAR BRAKE TUBES TO HORN - L/R	82	0	0	0.00	410	0	0.00	12.3
49	CJ0450091	AIR/WL REAR BRAKE TUBES TO HORN - R/R	82	0	0	0.00	410	0	0.00	12.3
50	CJ0450070	BLK-ASSEMBLY BRAKE TUBES TO AIR. HYD. MODULE	82	0	0	0.00	410	0	0.00	11.5
51	CJ0310000	SECURE AIR. HYD. VALVE TO SIDE RAIL	82	0	0	0.00	410	0	0.00	25.3
52	CJ0330010	ASSEMBLE IN FIT BRAKE TUBE TO JUNCTION BLOCK EXCLUDING CJ0430010	82	0	0	0.00	410	0	0.00	12.7
53	CJ0430090	REAR FRONT BRAKE TUBES TO MASTER CYLINDER	82	0	0	0.00	410	0	0.00	8.9
54	CJ0450070	SECURE BRAKE TUBES TO JUNCTION BLOCK. EXCLUDING CJ0220100	82	0	0	0.00	410	0	0.00	12.2
55	CJ0220100	ASSEMBLE FRONT CALIPER TO FRONT KNUCKLE L/R	82	0	0	0.00	410	0	0.00	97.3
56	CJ0220101	ASSEMBLE FRONT CALIPER TO FRONT KNUCKLE R/R	82	0	0	0.00	410	0	0.00	99.3
57	CJ0220090	SEC FRONT BRAKE LINE TO CALIPER - L/R	82	0	0	0.00	400	0	0.00	44.7
58	CJ0220091	SEC FRONT BRAKE LINE TO CALIPER - R/R	82	0	0	0.00	400	0	0.00	44.7
59	CJ0240100	SEC FRONT BRAKE LINE TO BRAKE TUBE - L/R	82	0	0	0.00	410	0	0.00	9.8
60	CJ0240101	SEC FRONT BRAKE LINE TO BRAKE TUBE - R/R	82	0	0	0.00	410	0	0.00	9.8
		MATERIAL								
61	CJ0200060	SECURE FUEL FILLER PIPE TO BODY	82	0	0	0.00	400	0	0.00	3.0
62	CJ0200050	SECURE FUEL TANK TO SNAPSHOT (20 GALLON)	82	0	0	0.00	400	0	0.00	46.3
63	CJ0200050	SECURE FUEL TANK TO SNAPSHOT (20 GALLON)	82	0	0	0.00	400	0	0.00	46.3
64	CJ0300070	INSTALL RETURN HOSE CLAMP	82	0	0	0.00	400	0	0.00	2.0
65	CJ0300020	INSTALL FUEL FILLING CLAMP	82	0	0	0.00	400	0	0.00	1.3
66	CJ7900040	TIRE AND WHEEL ASY. TO VEHICLE L/R	82	0	0	0.00	410	0	0.00	113.7
		MATERIAL								
67	CJ7900061	TIRE AND WHEEL ASY. TO VEHICLE R/R	82	0	0	0.00	410	0	0.00	114.2
68	CJ0200100	ASSEMBLE OAT. CONV/INLET PIPE TO MANIFOLD	79	0	0	0.00	395	0	0.00	34.4
69	CJ0200100	ASSEMBLE INLET PIPE/RESONATOR TO MANIFOLD	79	0	0	0.00	395	0	0.00	31.4
70	CJ0000090	ASSEMBLE GASKET AND FLUX COUPLING TO Y-PIPE	82	0	0	0.00	410	0	0.00	35.5
71	CJ0000110	ASSEMBLE GASKET AND FLUX COUPLING TO NURPLE	82	0	0	0.00	410	0	0.00	35.9
72	CJ0000120	DOOR LATCH ASSEMBLY TO CENTER RAD SHFT	82	0	0	0.00	410	0	0.00	18.2
73	DT1100050	TRANSMISSION OUTLINE CONTROL LEVER TO AXIAL TRANS	79	0	0	0.00	395	0	0.00	10.6
74	DT11000100	SHIFT CABLE SHFT TO AXIAL TRANS.	79	0	0	0.00	395	0	0.00	19.8
75	ED2000100	14000 TO ALTERNATOR CONNECTIONS (3.6L)	79	0	0	0.00	395	0	0.00	6.8
76	ED4510000	INSTALL HEAD SENSORS (drive sensors) GLICKER MACHINES	82	0	0	0.00	410	0	0.00	29.8

**TRANSMISSION VERIFICATION REPORT**

TIME 09/06/1997 09:42  
NAME OAKVILLE BODY PLANT  
EX- 645741  
TEL 519 883 3226

DATE, TIME  
NAME

80/00 00:34  
01-12-1980  
00:00:02  
17  
OK  
STANDARD  
SCM

Operating Procedure  
Vehicle Operations  
Ford Motor Company

ED: VOPFAG241  
Date: October 30, 1998

SUBJECT: Torque Integrity Assurance Program for Assembly Plants  
Procedure VOPFAG241.

VOPFAG241 provides revised and updated direction for performance of the Torque Integrity Assurance Program. This 10/30/98 revision replaces the 2/26/98 issue. The revisions are indicated by a vertical line in the left margin or by the use of italic letters.

The significant changes are in Sections:

- I. Definitions
- II. Setting up Operations, including flow charts
- III. Torque Process Potential Studies, including flow charts
- IV. Dynamic Torque Surveillance, including flow charts
- V. Torque Auditing Route Development
- VI. Record Retention

APPENDIX A      Torque Inspection and Studies Systems Data Analysis Flow chart.

Please refer any questions on this Procedure to R.G. Varto (XVARTO).

Approved by:

Robert G. Varto  
Fastening Systems Supervisor  
Process Strategies and Plant Interface Department

Ken J. Owendal  
Department Manager,  
Process Strategies and Plant Interface Department

**This page was intentionally left blank.**



## Operating Procedure

VOPFAG241

Vehicle Operations  
Ford Motor Company

Issue Date: October 30, 1998  
Previous Issue Date: February 26, 1998

**SUBJECT:** Torque Integrity Assurance Program for Assembly Plants

**PREPARED BY:** Process Strategies & Plant Interface Dept., Vehicle Fastening Systems Section

**ORGANIZATIONAL COMPONENTS AFFECTED:**

**Assembly Plants: Fastening Systems Control Activity**

Production Departments  
Government Regulations Coordinator  
Plant Engineering  
Manufacturing Engineering  
Resident Engineering

**General Office:** Vehicle Fastening Systems  
Global Final Assembly Engineering  
Quality Office - Vehicle Operations

**Other:** Product Engineering

**Summary:**

This publication is an update of the February 26, 1998 version of Operating Procedure VOPFAG241. This is a GLOBAL procedure. Text changes are indicated by a vertical line in the left margin or by the use of *italic letters*.

VOPFAG241 is a comprehensive guide for handling torque in an assembly plant and is an integral part of the torque control program. This procedure covers torque surveillance, corrective actions, torque process potential studies, torque auditing route development, and required reports. The records are compiled in the "Torque Inspection & Study System (TISS)" which, combined with any additional plant controls, effectively serve as each plant's Torque Control Plan.

The implementation of VOPFAG241 is the joint responsibility of the Assembly Plants Production Department and Fastening Systems Control. Fastening Systems Control is responsible for ongoing torque surveillance and performing Torque Process Potential Studies. Fastening Systems Control is also responsible for power tool allocation and procurement (see PT-8, Handling and Control of Power Tools in Assembly Plants). Production responsibilities include using the correct equipment, using it properly and correcting out-of-specification units. Production and Fastening Systems Control are both responsible for implementing corrective actions.

The foundation of this procedure is the Torque Process Potential Study (TPPS). Analysis of each operation occurs through a Torque Process Potential Study, which aligns the operation to the specification mean, determines its process potential ( $P_p$  &  $P_{pk}$ ), and sets residual (audit) torque limits. The residual torque limits become the inspection limits for ongoing torque surveillance, when periodic dynamic torque measurement is not possible. The residual limits are used to detect concerns, not to adjust the process.

Wherever possible, dynamic torque is measured and used to shut off the tool through transducer feedback or, simply, to monitor the operation. Dynamic measurement is also used for torque concern analysis. The goal is to drive dynamic torque Cp and Cpk to 1.33 or better.

Any deviation from this procedure must be requested in writing and submitted to Vehicle Fastening Systems, Vehicle Operations General Office (VOGO), for approval.

This page was intentionally left blank.

I.	Definitions .....	4
II.	Setting Up Operations .....	11
	A. Operation Set-up .....	11
	B. Reallocated or Relocated Operations .....	11
	C. Engineering Changes .....	11
	D. New Model Programs .....	13
III.	Torque Process Potential Studies .....	17
	A. TPPS Prioritization .....	17
	B. TPPS Completion Requirements .....	17
	C. Process Benchmarking .....	19
	D. Conducting a TPPS .....	21
	1. Initial TPPS Setup .....	21
	2. Power Tool Setup .....	23
	a. Dynamic & Residual Torque Study .....	23
	b. Residual Torque Study with Dynamic Mean Adjustment .....	25
	c. Residual Torque Study .....	27
	3. Data Collection .....	29
	a. Single Fastener Operations .....	29
	b. Multiple Fastener Operations .....	29
	c. Multiple Station Operations and Left/Right Operations .....	29
	4. Data Analysis .....	31
IV.	Torque Surveillance .....	35
	A. Dynamic Torque Surveillance .....	35
	1. Automated Fastening Systems With Data Storage And Analysis Capability .....	35
	2. Other Transducerized Systems .....	36
	B. Residual Torque Surveillance .....	39
	C. Corrective Actions .....	43
	Mandatory (M)/Critical (C) Operations .....	44
	Significant Characteristic ("S") or Warranty ("W") Operations .....	44
V.	Torque Concern Notice .....	45
VI.	Surveillance Frequency .....	46
	A. Mandatory (M)/Critical (C) Operations .....	46
	B. Significant Characteristic (S) or Warranty (W) Operations .....	46
	C. Low Volume Process Operations .....	47
VII.	Torque Auditing Route Development .....	48
	A. Calibration .....	48
	B. Element Numbers , Types & Description .....	49
	C. Off-sets .....	49
	D. Multiple Spindle Operations .....	49
	E. Part Usage .....	49
	F. Process Consolidation .....	50
	G. Repair Operations .....	50
	H. Rotation Number .....	50
VIII.	Torque Inspection and Studies System .....	51
IX.	Record Retention .....	52
X.	Forms .....	53
XI.	Exhibits .....	53
XII.	Related Procedures and Documents .....	54
Appendix A: Torque Control Plan Letter to Product Engng. and CR/CR & Alert Resolution Forms .....		56
Appendix B: TPPS Worksheet .....		67
Appendix C: TPPS monthly Study Team Program Reports .....		69
Appendix D: VM/ICB Database Field Codes .....		71

## I: Definitions

It is necessary to establish a baseline of understanding before continuing in this document. It is important that everyone involved in this program use terms consistently, with regard to definition. This section will define terms used in this document and some statistical terms.

**Global Study Process Allocation System (GSPAS)** - The Global Study Process Allocation System is being developed and implemented by Vehicle Operations (VO) for defining assembly processes. Users of GSPAS link part information to process steps (elements), tools, and specific usage information to define a complete assembly operation. In the future, GSPAS will replace MPPS as the primary system.

**Manufacturing Process Planning System (MPPS)** - The Manufacturing Process Planning System is Vehicle Operations (VO) system for defining assembly processes. Users of MPPS link part information to process steps (elements), tools, and specific usage information to define a complete assembly operation. MPPS is the primary system used to transfer assembly process information to the assembly plants.

**Mandatory ("M") Operation** - A Mandatory operation contains a Critical Characteristic. Critical Characteristics are those product requirements (dimensions, specifications, tests) or process parameters which:

- can affect compliance with government regulations or safe vehicle/product function; and
- require specific producer, assembly, shipping, or monitoring actions.

Include Critical Characteristics on Control Plans. Critical Characteristics are identified with the inverted triangle (V) symbol on Ford drawings, specifications, and Control Plans.

In the MPPS system, an "M" in the "C" field of the Tool screen (PF12) will identify Critical Characteristic operations.

**Significant (Warranty) ("S", "W") Operation** - From Engineering Practice No. 30, "Significant Characteristics are those product, process, and test requirements which are important for Customer Satisfaction and for which Quality Planning action must be summarized on a Control Plan."

In the MPPS system, an "S" in the "C" field of the Tool screen (PF12) will identify Significant Characteristic operations, replacing the current "W" used to designate Warranty operations.

**Control Plans** - Control Plans are written descriptions of the system for controlling processes producing products for Ford. Producers must establish Control Plans for all new products and must address all Significant and Critical design characteristics, process parameters, and ES tests.

**Model Year** - This time period is defined from Job #1 of one year to Job#1 of the next year.

**Process Failure Mode and Effects Analysis (FMEA)** - An FMEA is an analytical technique which uses the potential failure modes of a process and the causes to prioritize improvement opportunities. The FMEA should be treated as a living document that is updated as necessary whenever the process changes.

**Torque Process Potential Study** - A Torque Process Potential Study (TPPS) is a procedure for examining threaded fastener operations. It aligns an operation to the dynamic specification mean, determines the dynamic process potential and determines the relationship of the dynamic torque to the residual measurement (sample size is 60 for a full TPPS).

**Mini Torque Process Potential Study** - A Mini TPPS has the same definition as the Torque Process Potential Study listed above with exception of the sample size taken. The sample size is reduced from 60 samples (full TPPS) to 30 samples (Mini TPPS).

**Priority 1 Fastener** - Critical/Mandatory and Significant fasteners, which during pre-Job#1 production builds, have indicated that the residual torque is below the lower dynamic specification limit (or minimum torque if previously specified). (i.e. If the fastener rotates prior to the "click", identify the fastener as Priority 1.)

**I: Definitions**

**Priority 2 Fastener - Critical/Mandatory and Significant fasteners, which during pre-JobPF production builds, have indicated that the residual torque is higher than the lower dynamic specification limit. (i.e. if the wrench "clicks" before any fastener rotation occurs, identify the fastener as Priority 2.).**

**Benchmarking - Benchmarking is the process of measuring an operation to establish a base or reference point.**

**Dynamic Torque - Dynamic torque is the measure of the torque during the securing process. It is measurable only while the fastener is rotating. Installation torque specifications are given as dynamic torque values, in Newton meters (Nm).**

**Dynamic (Installation) Torque Specification - Product Engineering assigns a dynamic torque specification to every threaded fastener operation, as a target mean and tolerance (variance).**

**I: Definitions**

**Residual Torque** - Residual torque is the measure of the torque on a secured fastener. It is the value obtained when the fastener begins to rotate in the tightening direction, when measuring with a torque wrench. This was previously known as static torque, which is a misnomer. Static torque is defined below. (See note, page 6)

**Residual (Audit)Torque Limits** - Audit torque is the upper and lower inspection limits allowed for residual torque on a given operation. These limits are either the dynamic specification limits or the residual mean plus or minus 3 sigma (2δσ), as determined by a Torque Process Potential Study (TPPS). The TPPS values take precedence over other defined values when auditing residual torque. A TPPS will be performed to redefine the audit torque limits anytime the process changes.

**Static Torque (revised definition)** - Static torque is the torque value that exists when a fastener is in a static state (i.e. not moving). There is no method for measuring a static torque value because measurement causes rotation of the fastener, thus, taking it out of the static state.

**Minimum Torque** - Minimum Torque is the lowest acceptable torque value for a specific joint (i.e. dynamic or residual measurements must be above this value).

This value can be used for attribute inspection (i.e. "Is the torque above this value?"). In attribute torque inspection, a click-wrench is set at the minimum torque value and applied to the fastener (in the tightening direction). If the wrench "clicks" before additional rotation occurs, the torque was above the minimum and thus OK. If the wrench "clicks" after additional rotation occurs, the torque was below the minimum and thus NOT OK. In absence of a separately specified minimum torque, the minimum torque is equal to the lower dynamic torque specification. After completion of a TPPS, the minimum torque is equal to the lower value of either the lower residual limit or the lower dynamic torque specification.

**Peak Meter** - A peak meter is an electronic device for measuring the torque output of a transducer.

**Transducer** - A transducer is an electronic strain gage that measures torque applied to a fastener.

**Portable Joint Simulator** - A portable joint simulator imitates threaded fastener joints of different hardness using Belleville washers. Changing the configuration and number of the concave washers changes the torque rate produced. This device is useful for centering a power tool at the dynamic specification mean when using the actual joint is not possible.

**Torque Inspection and Studies System (TISS)** - The Torque Inspection and Studies System provides an integrated method of setting-up, recording, and reporting assembly process information. The system allows the loading and unloading of data from a Datatlyte. The system generates daily and periodic reports.

**VM** - Virtual Machine (VM) is the main frame computer operating system which contains the PROFS electronic mail system and the Information Center/Enhanced (ICE) data management system.

**ICE (Information Center/Enhanced)** - The Information Center/Enhanced (ICE) is the mainframe data management system that contains the Torque Process Potential Study database for each assembly plant.

## I Definitions (continued)

**DataMyte System** - "DataMyte" is the brand name of a portable data collector that uses electronic measuring devices, such as torque wrenches and transducers, to measure and record data. The DataMyte can analyze the data and print various reports, or transfer the data to a computer for analysis in a larger database.

**Peak Mode** - This is a programmable setting for the DataMyte to obtain a torque measurement. The operator must apply torque to the fastener until the fastener moves slightly (as little as possible) and then stop rotating. The highest value measured is recorded. All data collections shall use this mode.

**Breakaway Mode** - This is also a programmable setting for the DataMyte to obtain a torque measurement. This setting detects the change in applied force versus time and records the peak value measured before the change. The assumption is that the change is the start of fastener rotation. This does not consider other reasons for the change, such as parts deflection or a change in the applied force. Do not use this method for residual torque measurement.

### Statistical Terms:

Statistical analysis is used to monitor and improve manufacturing processes. An understanding of statistical methods is necessary to implement this procedure. Seek the help of local statistics experts (i.e. SPC personnel) when using this procedure. The following are brief definitions of common statistical terms. For more information on statistics, refer to the publications listed in Chapter XII, Related Procedures and Documents.

**Histogram** - A histogram is a vertical bar chart of the frequency of results of a process. The possible results are plotted on the horizontal axis while the frequencies of these results are plotted on the vertical axis.

**Individuals Chart** - An individuals chart is a simple graphic representation of a characteristic of a process, showing plotted individual values of some statistic (in this case, dynamic torque) gathered from that characteristic, a central line (mean), and one or two control limits. It has two basic uses: as a judgement to determine if a process has been operating in statistical control, and as an operation to aid in maintaining statistical control.

**Moving Range Chart** - A moving range chart is a simple graphic representation of the range between consecutive individuals on an individuals chart and a center line.

**Statistical Control** - Statistical control is the condition describing a process in which no special causes of variation exist and only common causes remain. Evidence of this state is the lack of non-randomness (trends) or points outside the control limits of a properly prepared control chart.

**Process Stability** - A process is said to be stable if it is in statistical control; contains no special causes of variation; is predictable.

**Normal Distribution** - A continuous, symmetrical, bell-shaped frequency distribution for variables data. A histogram will display a bell-shaped curve if the data used in it is a normal distribution.

**Process Potential Study** - The purpose of a Process Potential Study is to determine if a process can produce output fit for use. It provides a starting point for achieving statistical control. The study result may be an indicator of the need for process improvement actions.

**Process Capability Study** - The continuous statistical analysis of a process to identify and eliminate variability from special and common causes.

**E Definitions (continued)**

**P<sub>p</sub> & P<sub>pk</sub>** - P<sub>p</sub> and P<sub>pk</sub> carry the same definitions as C<sub>p</sub> and C<sub>pk</sub>, respectively, except their calculation is based on data from short-term studies rather than periodic sampling over an extended time. Torque Process Potential Studies use P<sub>p</sub> and P<sub>pk</sub>.

**Common Causes** - 1. Those sources of variability in a process that are truly random (i.e. inherent in the process itself). 2. A source of variation that effects all the individual values of the process output.

**Special (Assignable) Causes** - The sources of variation in a process that are not random. A source of variation that is intermittent, unpredictable and unsatisfactory. A point beyond the control limits, a run or other non-random pattern of points within the control limits indicates the existence of a special cause.

**C<sub>p</sub> (Process Potential)** - C<sub>p</sub> is an index that is the ratio of the tolerance range to the six sigma process spread without regard to the location of the data. It is calculated after verifying the process is in a state of statistical control.

$$C_p = \frac{Tolerance}{6\sigma}$$

C<sub>p</sub> is an indicator of the ability of the process to stay within the engineering specification. The larger C<sub>p</sub> is the more capable the process is of staying within the tolerance. A C<sub>p</sub> of 1.33 is considered acceptable.

**C<sub>pk</sub> (Process Capability)** - C<sub>pk</sub> is an index that considers both the process spread and the proximity of the process spread to specification limits. It is calculated after verifying the process is in a state of statistical control.

$$C_{pk} = \frac{\text{the lesser of } (USL - Mean)}{3\sigma} \text{ or } \frac{(Mean - LSU)}{3\sigma}$$

USL - Upper Specification Limit

LSL - Lower Specification Limit

C<sub>pk</sub> is an index combining C<sub>p</sub> and K to indicate whether the process will produce units within the tolerance limits. If  $C_{pk} = C_p$  if the process is centered on the mean specification. If C<sub>pk</sub> is negative, the process mean is outside the specification limits. If C<sub>pk</sub> is between 0 and 1, then some of the 6 sigma spread falls outside the tolerance limits. If C<sub>pk</sub> is larger than 1, the 6 sigma spread is completely within the tolerance limits.

**Note:** Baseline torque data is not to be used to calculate C<sub>p</sub> & C<sub>pk</sub> (or P<sub>p</sub> & P<sub>pk</sub>) indices, as they may not reflect the dynamic capability of the process.

**Acronyms**

CR/CR - Concern Report/Change Report

FSC - Fastening System Control

MPPS - Manufacturing Process Planning System

GSPAS - Global Study Process Allocation System

PE - Product Engineering

TIAP - Torque Integrity Assurance Program

TIBS - Torque Inspection & Study System

TPPS - Torque Process Potential Study

TOPS - Team Oriented Problem Solving


VM - Virtual Machine (type of IBM mainframe computers Ford uses)

VOGO - Vehicle Operations General Office (formerly BAGO, Body & Assembly General Office)

**This page was intentionally left blank.**

## TIAP - Torque Integrity Assurance Program

### II, A: Setting Up Operations



**I. Setting Up Operations (see flow chart II, A : dated 10/30/98)**

Operations are allocated as required to meet the General Office processing directions shown in the MPPS/GSPA8 computer system. *Setting Up Operations* includes operation set-up, reallocated/relocated operations, engineering changes and new model programs.

The procedure for installing and adjusting power tools is part of Power Tool Standard PT-8, published by Vehicle Fastening Systems. On all operations, a Ford certified power tool of the correct size must be provided with an installation that meets all applicable Ford standards. Ford certified power tools, installation standards, and power tool standards, including PT-8, may be found in the Portable Power Tool Manual (green three ring binder).

**A. Operation Set-up**

1. Obtain processed power tool size (certified - shape may vary for ergonomics)
2. Assure the tool installation is correctly sized.
3. Make sure lubricator is working.
4. Assure that the socket or bit is in good condition.
5. Approximate air pressure or ~~set controls~~ to get the dynamic mean torque specification.
6. Prioritize for a Torque Process Potential Study (TPPS).


**B. Reallocated or Relocated Operations**

1. *Assure the tool is mean centered to the dynamic mean specification.*
2. Take 10 residual torque samples.
3. If any residual torque values from step (2) are below the lower dynamic limit (or lower residual limit if a TPPS has been conducted), start Corrective Actions (Chapter IV, Section C).

**C. Engineering Changes**

1. Take 20 residual torque samples.
  - a. If any residual torque values from step (1) fall below the lower dynamic specification limits, start Corrective Actions (Chapter IV, Section C).
2. Prioritize for a Torque Process Potential Study (TPPS).

## TIAP - Torque Integrity Assurance Program II, D: New Model Programs

1000000  
HARD COPY

## | D. New Model Programs (see flow chart H, D; dated 10/30/96)

1. For Releasable Units refer to Job #1:

- a. For all NEW Mandatory/Critical and Significant fasteners, each operator is provided the following tooling:
  1. Processed power tool (set at the operating station to the mean dynamic torque specification on a joint simulator).
  2. Torque clicker wrench set at the lower dynamic specification unless a minimum torque specification has been given by the PE.
- b. Secure the fastener with the processed power tool, assuring that the tool shuts-off properly.
- c. Apply the clicker wrench to the secured fastener in the tightening direction until the wrench "clicks".
- d. Using a local process, identify the fasteners as to one of the following conditions during the hand torque operation:
  1. If the wrench "clicks" before any fastener rotation occurs, identify the fastener as a Priority 2. This condition indicates that the residual torque is at some value greater than the minimum torque.
  2. If the fastener rotates prior to the "click", identify the fastener as a Priority 1. This condition indicates that the residual torque was at some value less than the minimum torque but has been tightened to the minimum.

Note: Step (d) provides a means of assuring that ALL Critical and Significant fasteners are audited for the correct torque. All fasteners with low torque are hand torqued to the minimum torque specification. Any fasteners that could potentially create a low torque concern are identified as Priority 1.

- e. FSC organization tracks occurrences and trends for fasteners identified as Priority 1.
  1. If no definite trend exists, prioritize the operation for a TPPB after Job #1 when more data will be available for determination of the minimum torque value.
  2. If a Priority 1 trend exists, continue with step (f).
- f. Verify that the power tool is set to the correct mean torque and that the operator is using the correct tool during the securing operation.
- g. Measure the residual torque to determine the minimum torque value. Determine the source/cause of the relaxation in the joint.
- h. Contact the responsible design engineer and request evaluation of the joint. The design engineer has two available options:
  1. Release the minimum torque as part of the engineering specification or
  2. Redesign the joint to eliminate the relaxation.
- i. Issue a CR/CR to document the concern and release the permanent corrective action.
- j. Return to step (a) and reset the hand click wrench to the new minimum torque.

| D. *New Model Programs (continued)*


| | 2. *After Job #1:*

- | | | a. *For all fasteners identified as Priority 2:*
- | | | | 1. Stop the use of hand click wrenches.
- | | | | 2. Start regular torque surveillance (Chapter IV).
- | | | | 3. Prioritize the operation for a TPPS.
- | | | b. *For all fasteners identified as Priority 1:*
- | | | | 1. Write an Alert and PSO to continue the 100% hand torque operation.
- | | | | 2. Start regular torque surveillance after the hand torque operation (Chapter IV).
- | | | | 3. Prioritize the operation for a TPPS.

This page was intentionally left blank.

## TIAP - Torque Integrity Assurance Program

### III, A: TPPS Prioritization



## II: Torque Process Potential Studies

The Plant Fastening System Control Group will conduct a TPPS on every threaded fastener operation.

For "New Model Programs", this may require the use of "bubble teams" to temporarily augment the regular TPPS team. Exception for these incremental responsibilities must be requested through the regular plant budget process. This can be accomplished by staying in contact with the Launch Coordinator and informing them of the plants requirements. Approximately 12-18 months prior to Job#1, the manpower requirements (for pre-build and after Job#1 responsibilities) are input into the launch budget. It is important to remember that additional tooling (i.e. Detachable, transducers, cables, sockets, extensions, etc.) may be needed.

### A. TPPS Prioritization (see flow chart II, A; dated 10/30/98)

1. *New Critical/Mandatory and Significant operations, which during pre-Job#1 production builds, have indicated that the residual torque is below the lower dynamic specification limit (or minimum torque if previously specified).*
2. *New Critical/Mandatory operations which have indicated that the residual torque is higher than the lower dynamic specification limit during pre-Job#1 production builds and Critical/Mandatory Engineering Changes.*
3. *New Significant operations which have indicated that the residual torque is higher than the lower dynamic specification limit during pre-Job#1 production builds.*
4. *New Other (not designated Critical/Mandatory or Significant) operations which have indicated that the residual torque is higher than the lower dynamic specification limit during pre-Job#1 production builds.*

*Note: If an operation is causing production problems, it should be pulled ahead for a TPPS.*

For New Model changes, per procedure VOPGON-B01, 5.5.6, TOOL PROCESS CAPABILITY STUDIES, the Vehicle Operations Manufacturing Engineer will provide a list of the operations that will require a new TPPS to the FSC. For on-going Engineering Change Requests, it is imperative that the PVT personnel/EEngineering Change Coordinator provide the list to the FSC.

## III. TPPS Completion Requirements


1. *New Critical/Mandatory operations require a full TPPS completed within 3 months of Job#1 or the "Effectuated" date of the engineering change.*
2. *New Significant operations require a full TPPS completed within 6 months of Job#1 or the "Effectuated" date of the engineering change.*
3. *New Other (not designated Critical/Mandatory or Significant) operations require a MINI TPPS completed within 12 months of Job#1 or the "Effectuated" date of the engineering change.*

*Exception: All operations that were new or revised with Job#1 dates prior to 02/1/98 will fall under the TPPS completion requirement of Three (3) years for "Other" operations with Mini studies being performed.*

*NOTE: Once a TPPS has been completed on each threaded fastener operation, a new TPPS will only be required if there is a change to the joint composition or fastening process such as:*

- *Fastener Grade*
- *Fastener change*
- *Joint complement change*
- *Torque Specification*

## TIAP - Torque Integrity Assurance Program III, C: Benchmarking Current Production

000000  
00000000

**C. Process Benchmarking (see flow chart III, C; dated 10/30/98)**

When benchmarking a "carryover" operation, the potential exists where the operation is not being performed to the released engineering torque specifications. Past torque concerns on these operations may have been corrected in the plant but the information was never relayed to the PE (Product Engineering) for correction of their engineering releases. In these cases, the FSC must obtain historical inspection data for the operation (if available) along with conducting a TPPS at the current settings and the engineering specifications. The Resident Engineer and/or the PE should be involved in determining whether the existing set-up or the released specification should be used for production based on the TPPS and the Historical Inspection data. The following procedure should be used when "benchmarking" existing assembly operations:

1. Take (10) dynamic torque readings on the operation at the current tool set-up.
2. Calculate the tool dynamic mean.
  - a. If the tool mean is within 15% of the Engineering Specification:
    1. Mean center the tool to the Engineering Specification and begin the TPPS.
      - A. If the process can be done at the Engineering Specification, continue with the TPPS at the Engineering Specification.
      - B. If the process can not be done at the Engineering Specification, adjust the process mean and continue with the TPPS at the new setting.
    2. Go To Data Analysis, (see section III,B,4) review the TPPS with Resident Engineering and identify resolutions.
  - b. If the tool mean is not within 15% of the Engineering Specification, check for historical data on the operation.
    1. If historical data does not exist for the operation, set the process mean to the Engineering Specification and continue with the TPPS. Go to step 2a above.
    2. If historical data does exist, continue with the TPPS at the current tool setting.
  3. Compare the TPPS data with the historical data.
    - a. If the historical data agrees with the TPPS data, Go To Data Analysis, review the TPPS with Resident Engineering and Identify resolutions.
    - b. If the historical data does not agree with the TPPS data,
      1. Set the tool to the Engineering Specification.
      2. Conduct a second TPPS.
      3. Go To Data Analysis, review the TPPS with Resident Engineering and Identify resolutions.

**This page was intentionally left blank.**

**III: Torque Process Potential Studies****D. Conducting a TPPS**

The Torque Process Potential Study (TPPS) is a procedure for benchmarking threaded fastener operations. Its purpose is to align an operation to the dynamic mean specification and to establish residual torque limits for monitoring the operation.

Measuring dynamic torque for each securing cycle requires coupling a transducer between the power tool and the socket (except when a transducer is built into the tool). This will not be possible for every process, due to accessibility concerns or tool design. Therefore, there are three basic study formats:

- **Dynamic & Residual Torque Study** - Dynamic torque is measurable during the securing cycle.
- **Residual Torque Study with Dynamic Mean Adjustment** - Dynamic torque is measurable at the operation only on a joint simulator.

Mandatory/Critical operations must be studied by one of the above TPPS formats.

- **Residual Torque Study** - Dynamic torque is not measurable at the operation.

Non-Mandatory/Critical operations may be studied using any of the above TPPS formats. Whenever possible, use a method that measures dynamic torque.

**1. Initial TPPS Setup**

- a. Fill in the background information portion of the TPPS worksheet (Appendix B).
  1. Use the latest process sheet or data from MPPS/GSPAS.
  2. Sketch the operations with more than one fastener or if needed for clarity.
- b. Verify that the tooling set-up is correct and in proper working order.
  1. Certified tool (listed in the Power Tool Manual)
  2. Transducer (dynamic studies only)
  3. Transducer readout (dynamic studies only)
  4. Tool size (ref. process sheet)
  5. Tool type (stall, air shutoff, clutch)
  6. Hose length
  7. Hose diameter
  8. Pressure gage
  9. Regulator
  10. Lubrication (oil level and function)

Do not conduct a study unless these items are present and in proper working order.


- c. Explain the TPPS to the operator and why it is being performed.

Note: It is important that no units are released by the operator, during the set up and conducting of the study. If the study interferes with production, help the operator keep up.

- d. Make sure the operator is using the tool correctly, not...
  1. Releasing tool trigger before tool shutoff.
  2. Double triggering.
  3. Creating a side load during rundown.
- e. Number multiple spindles and fasteners to segregate dynamic and residual data with the corresponding spindle and fastener. Studies done on multiple fastener operations are to include 50 data samples of both dynamic and residual torque for each fastener.

## TIAP - Torque Integrity Assurance Program

### III, D, 2a: Dynamic & Residual Torque Study

100000  
DRAFT/NOTCUT

|    D. Conducting a TPPS (continued)

|    |    2. Power Tool Setup

|    |    |    e. Dynamic & Residual Torque Study (see flow chart III, D, 2a dated 103048)

Use the Dynamic & Residual Torque Study method to determine the capability of the process. Perform it on all operations where both dynamic and residual torque are measurable. Additionally, use this procedure on operations where the tool can be set dynamically, but where dynamic measurement of the fastener is not possible.

1. Prepare the tool to measure torque by one of the following methods:
  - a. Use the tool's transducer readout
  - b. Plug in a peak meter to the internal transducer
  - c. Attach an external transducer to the tool. Use a DataMyte, in peak mode, to read the transducer.
2. Tape all wires out of the operator's way.
3. Record at least ten (10) rundowns on the operation before making any adjustments.

   a. Calculate the average of the readings.

$$\frac{\text{Sum of the Samples}}{\text{The Number of Samples}} = \text{Sample Average}$$

   b. Calculate the difference from the dynamic mean specification (target mean) to the measured average (tool mean).

$$\frac{\text{Tool Mean} - \text{Target Mean}}{\text{Target Mean}} \times 100\% = \text{Percent Deviation}$$


- c. The tool mean should be within +/- 25% of the target mean. If the tool mean is greater than 25%, adjust the tooling to reduce the deviation. Repeat step (3) until the tool mean is within 25% of the target mean. If it is not possible to get close to the 25% target, replace the tool and/or regulator. Repeat step (3) until the tool mean is within 25% of the target mean.
4. Observe each securing cycle and record any discrepancies.
  - a. If the dynamic specification fails the fastener or abnormally distorts the joint, lower the tool mean to a point below where fastener failure or joint distortion occurs.
  - b. If the drive torque is too close to the dynamic mean specification (i.e. the tool stops before driving the fastener all the way in), raise the tool mean enough to drive the fastener.

Note: The above discrepancies may be caused by out-of-specification parts and new stock may correct the problem. Out-of-specification stock must be removed from the production line and held for disposition. If out-of-specification parts are not the cause, write a CR/CR requesting the release of the torque specification developed in this TPPS. The Resident Engineer should release an Alert, specifying interim actions, including the torque specification developed in this study.  
(See Appendix A, Concern Resolution Submission Forms, CR/CR Form #2 - Request for New Torque Specification.)

c. Perform the TPPS at the new torque level.

# TIAP - Torque Integrity Assurance Program

## III, D, 2b: Resid. Torque Study w/ Dyn. Mean Adjust.

1020046  
RevA/UDY/DMT


**2. Power Tool Setup (continued)****b. Residual Torque Study with Dynamic Mean Adjustment (see flow chart III, D, 2b; dated 10/30/98)**

Use the residual torque study with dynamic mean adjustment method on operations where dynamic measurement is only possible using a joint simulator. For this study, follow the Dynamic And Residual Torque Study procedure with the following revisions:

1. Position the portable joint simulator so the power tool can reach it (without removing the tool from the operation).
2. Couple a transducer with hex adapter to the simulator. The hex adapter must be the same size as the socket on the power tool. This will permit torque sampling while the operator is not using the tool to secure fasteners, without changing the tool configuration.
3. Adjust the tool to the mean of the specification as outlined in step (3) of the Dynamic and Residual Torque Study.
4. Observe each securing cycle and record any discrepancies as outlined in step (4) of the Dynamic and Residual Torque Study.
  - A. If dynamic data can not be taken with the production tool because it is fixtured, use a "slave" tool to determine the correlating residual mean. Adjustments to the production tool are made using the residual compensator of the slave tool. See section (a) in Data Analysis for identification of the study method in the VM system.
  - B. For operations where a "click" wrench is used to secure (or final secure) the fastener, the TPPS shall be completed as follows:
    - a. Set "click" wrench to the dynamic specification mean on the joint simulator - use offset cal value if needed. (See Chapter VI, Section C, Torque Auditing Route Development, Offsets)
    - b. Collect "dynamic" data from operator using "click" wrench on joint simulator before each securing cycle.
    - c. TPPS technicians will loosen the joint simulator between cycles to ensure that there is rotation for the dynamic measurement.

# TIAP - Torque Integrity Assurance Program

## III, D, 2c: Residual Torque Study



FOR OFFICE USE ONLY

## 2. Power Tool Setup (continued)

### a. Residual Torque Study (see flow chart II, D, 2x; dated 10/30/96)

Use the Residual Torque Study method only on ~~non-Mandatory~~Critical operations and when dynamic torque measurement is not possible at the operation. That is, when a power tool without a built-in transducer, is fixtured in such a way that attaching an external transducer to it is not possible. If residual data shows that the torque is not within the specification, establish the proper power tool settings off-line through dynamic torque measurement.

1. Estimate the pressure required to obtain the specification mean.
2. Adjust the air regulator to the pressure estimated in step (1).


PT-8, chapter 2, How to Set-up a New Operation, covers this procedure in detail.

For ~~Non-Mandatory~~Critical operations where dynamic torque cannot be measured on-line, the tools must be dynamically analyzed off-line to determine the correct operational settings. These settings will then be used on the operation. Use the following methods:

1. Tool setups in the tool crib must mirror the operation as closely as possible.
2. Use the portable joint simulator to simulate the joint.
3. Make at least 10 rundown, measuring the dynamic torque with an external transducer. Adjust the tool to within 2% of the dynamic specification mean (use the same process as step (3) in the Dynamic & Residual Torque Study Method).
4. For pressure controlled tools, attach an air pressure gauge between the tool inlet and the supply hose and measure the air pressure reached at that torque (the pressure reached just before the tool stalls).
5. Set the air pressure at the operation using the method in step (4).
6. Install the tools tested in the tool crib on-line.
7. Perform the Torque Process Potential Study using the Residual Torque Study with Dynamic Mean Adjustment method.

# TIAP - Torque Integrity Assurance Program

## III, D, 3: Data Collection

1050W  
RELEASER.DAT

**D. Conducting a TPPS (continued)****3. Data Collection (see flow chart III, D, 3; dated 10/30/98)****a. Single Fastener Operations**

1. Once the tool is properly adjusted, record the settings on the TPPS worksheet and lock the adjustment mechanism.
2. Fill out the "Assembly Operation Under Study" tag and hang it near the air regulator or control panel.
3. Instruct the operator and supervisor not to adjust the tool without FSC approval.
4. Sample 60 units for both dynamic (dynamic data only) and residual torque. The object is to get 60 useable samples of dynamic torque and 60 of residual torque. It is not acceptable to take 22 samples on two shifts and 16 on the third for a total of 60 useable samples. A minimum number of 20 samples must be taken per shift. The Datamyle must be in "Peak" mode. Observe each securing cycle, record any discrepancies & Datamyle sample numbers, and flag the unit. Do not throw out any data without a cause identified.

**A. Take a sample set of 22 units and analyze the sample.**

For dynamic studies, both the dynamic and residual values should be taken from the same fastener.

Before taking the second and third sample sets, check that the process has not changed (i.e. tool, air pressure, etc. have not been changed). After taking the first 10 samples in each set, check that the mean is close to the original setting. For dynamic studies, use Datamyle "Trot" key for Pp and Ppk for the 10 samples.

**B. Take another sample set of 22 units on the following shift.****C. Take the final sample set of 22 units on the next shift.**

**Note:** Each residual data set should be collected by an alternate technician. It is statistically preferable to sample an operation on both day and night shifts. If it is not possible to do this, take samples on consecutive days or nights.

**When conducting a NEW TPPS, it is only necessary to take 30 samples on a single shift.**

**b. Multiple Fastener Operations**


It is necessary to perform a full Torque Process Potential Study (TPPS) on each fastener for a multiple fastener operation (using the "Single Fastener Operation" process listed in 3a above). Each fastener, along with a combined or "range" line, will be entered into the TPPS worksheet and VM system ICE (Information Center/Enhanced). The express routine "Limits" will automatically calculate the residual limits based on the "range" line information entered from the TPPS worksheet.

**c. Multiple Station Operations and Left/Right Operations**

It is necessary to perform a full Torque Process Potential Study (TPPS) on only one station for duplicate operations (including left/right). On the remaining duplicate operations (including left/right), mean center the tool and determine the dynamic Ppk based on 30 samples (per spindle). All duplicate operations must be set to the same dynamic mean and must be monitored by the same inspection limits.

## TIAP - Torque Integrity Assurance Program

### III, D, 4: Data Analysis

1000000  
MPC/AMT

**D. Conducting a TPPS (continued)****4. Data Analysis (see flow chart II, D, 4; dated 10/30/90)**

- a. Using the entire sample set, 60 to 66 samples, print out the following dynamic and residual DataMystic data analysis reports:
  - 1. Individuals chart & moving range charts (X-bar & R chart).
  - 2. Summary & Histogram chart (Histogram).
  - 3. Data report.
- b. Analyze the dynamic data.
  - 1. Is the data distribution on the histogram non-normal?
  - 2. Is Pp or Ppk less than 1.33?

**Note:** The objective for operations with new components and tooling is a minimum Ppk of 1.67. For "critical" operations that have a Ppk less than 1.33, initiate 100% click wrench checking until the process is proven capable. If Ppk is less than Pp, centering the tool to the specification mean will improve this number.

If the answer to any of the above questions is yes, then the process may need improving prior to establishing residual torque limits. See chapter VI, Torque Surveillance, for sampling frequency. (Also, see PT-5, Chapter VI, How to Improve the Capability of a Process.)

If Ppk is less than Pp, centering the tool to the specification mean will improve this number.

Look for special causes for the above conditions (malfunctioning power tool or support equipment, part variability, slip-stick friction, etc) and correct them. If it is necessary to study the process more thoroughly, seek the help of SPC and TOPS trained personnel to set up a work plan. Correcting the concerns may require issuing a CRVCR. See Appendix A for CRVCR standard test. After correcting the concern, repeat the study.

If the data does not have a normal distribution, it must be transformed to determine control limits and to estimate Pp and Ppk. Seek help from the SPC Coordinator to perform this operation.

**Note:** For "Residual Torque Studies", there is only residual data to analyze the operation. Because it is impossible to determine whether the power tool is meeting the dynamic specification, assume the residual measurement reflects the dynamic torque.

- c. Determine if the residual data is normal and stable by analyzing the Histogram and Individuals chart.
  - 1. If the data does not have a normal distribution, it must be transformed to determine control limits. Seek help from the SPC Coordinator to perform this operation.
  - 2. If the data is normal, proceed to step (d).

This page was intentionally left blank.

**4. Data Analysis (continued)**

d. Complete the recap portion of the TPPS worksheet with data from the DataMyte report. For "Residual Torque Studies", enter 'N/A' in the dynamics mean space (MEAN DYN).

e. Enter the information from the TPPS worksheet into the VM system ICE (Information Center/Enhanced) application database (file name: xx/TORQUE). Replace 'xx' by the 2 letter plant code of the specific plant (i.e. ATTORQUE is Atlanta).

**A. "N/A" for residual studies**

B. ":" symbol in front of the value to indicate that the dynamic values Pp and Ppk were derived from simulator data. For values greater than 100, truncate the decimal value to allow room to include the ":" in front of the dynamic mean value. The ":" must be in the correct column to allow for correct analysis of the data.

C. ":" symbol in place of a ":" (step (B)) to indicate that a "slave" tool was used. If dynamic data can not be taken with the production tool because it is fixtured, use a "slave" tool to determine the resulting residual mean. Adjustments to the production tool are made using the residual comparator of the slave tool.

**f. Determine the Residual L3mbs.**

1. Run the express routine "Limits" to automatically calculate residual limits based on the information entered from the TPPS worksheet. "Limits" will identify operations where an Alert must be issued. Use the residual limits generated by the "Limits" express routine when writing a required Alert.


2. Enter the Alert number into the TPPS database as soon as it is written.

3. Enter the residual limits into the TISS for downloading to the torque audit route DataMyte(s).  
(See Chapter VII, Torque Auditing Route Development, Section B, for entering operation descriptions).

4. Enter the Ppk value and study data into the TISS.

# TIAP - Torque Integrity Assurance Program

## IV, A: Dynamic Torque Surveillance

REVIEW  
INSTRUCTOR

**IV: Torque Surveillance**

Torque Surveillance is the monitoring of threaded fastener operations to ensure that they remain within specification and in control. This monitoring may give the first indication that the process is changing or that a concern exists. Monitoring involves taking torque data samples (dynamic or residual) and making contact with the operator. The data are analyzed for indications of process instability or failure to meet specification limits. Existence of these conditions will cause the taking of actions to stabilize the process and to prevent suspect units from getting out of the plant and to the customer. Operator comments also can give valuable information on the operation. Through performing the operation hundreds of times a day, an operator can detect subtle changes, such as noise level and reaction force. These could be indicators of tool or production part changes that need correction. Fastening Systems Control (FSC) and Production are responsible for implementing this procedure.

The surveillance frequency of an operation will vary depending on its designation, Mandatory/Critical or Significant, and its stability and capability. (See Chapter VI, Surveillance Frequency, for details).

See Chapter VII, Torque Auditing Route Development, for setting up auditing routes using the DataMatrix.

**A. Dynamic Torque Surveillance (see flow chart IV, A; dated 10/30/96)**

Perform dynamic torque surveillance on all operations with internal transducers. The design and control logic of the power tool will determine how this surveillance is performed.

**1. Automated Fastening Systems With Data Storage And Analysis Capability**

This type of system will stop and sound an alarm when an out-of-specification condition occurs. The specification programmed into the tool controller is the dynamic mean and high and low limits set by the Product Engineering (PE).

**FSC Responsibilities:**

- a. Add the operation to the Torque Inspection and Studies System (TISS), either manually or through the MPPS/GSPAS Import procedure. Place an "A" in the "Type" field to identify an Automated operation. Update the Cp, Cpk and first run capability fields in the TISS system at least once per month (no dynamic data will be collected in TISS).
- b. Assure that the manufacturer has provided "certification" that the output spindle torque matches the controller display torque for the given calibration value.
- c. Conduct a Torque Process Potential Study (TPPS) on each spindle to determine residual torque limits.
- d. Verify, at least once a month, that the set values are correct and follow manufacturers instructions for corrections. Measure and record (5) residual torque values as part of the calibration check.
- e. Verify, at least once a year, that the power tool's internal transducer measurements match the applied torque. Follow manufacturers instructions for corrections.

**Production Responsibilities:**

- a. Maintain a log of occurrences of equipment shut-off and define the causes and corrective actions. If the operation becomes suspect, contact the FSC.

**A. Dynamic Torque Surveillance (continued)****2. Other Transducerized Systems**

There are two other types of fastening systems that have transducers. They are:

- Automated Fastening Systems With Torque Data Indicator (No data storage or analysis)**  
This type of system displays the applied torque, but cannot store or analyze data.

**b. Fastening Tools With Built-In Transducers**

This type of system can measure the dynamic torque only by attaching a peak meter to the transducer. [An example of this type of tool is a wheel multiple used for lugnut secure. See VII Torque Auditing Route Development section D for more explanation on auditing wheel multiples.]

For dynamic torque surveillance purposes, treat these systems the same. Manually enter the dynamic torque data into a Datamyle or directly into the TISS database. Use the following procedure:

**FSC Responsibilities:**

- Add the operation to the Torque Inspection and Studies System (TISS), either manually or through the MPPS/GSPAS Download process. Mark these operations as type "D" for Dynamic in the TISS database and add them to the appropriate torque route. Use TISS to program the route into the Datamyle, including the dynamic torque specifications.
- If necessary, hook up a peak meter to the securing power tool.
- Take five (5) peak torque readings from the equipment and manually enter the values into the Datamyle or write the values down for manual entry into the database. The Datamyle will sound a long beep if any value is out-of-specification.
- Mark any out-of-specification units.
  - If any value is below specification, notify production with a Torque Concern Notice (see chapter VII, Torque Concern Notice). Go to the Corrective Actions, Chapter IV, Section C.
  - If two or more values are above specification,
    - Visually check the securing power tool and support facilities for discrepancies or changes (i.e., air pressure, after working, etc.). Ask if the operator noticed any changes.
    - Notify the FSC Coordinator to adjust or repair the tool.
    - Enter an "Assignable Cause" into the Datamyle.
    - Proceed with the route.
- For Mandatory (M)/Critical (C) operations that are not stable or have a history of torque related concerns, calculate the average and range for the readings and plot them on a control chart at the operation. Use normal statistical process control (SPC) rules to trigger the following corrective actions:

If the  $Cpk$  is less than 1.00, instruct Production to begin click wrench checking all future units. (If  $Cpk$  is less than  $Cp$ , centering the tool to the specification mean will improve this number.)

If the X-bar chart indicates the operation is out of control (but not out-of-specification), then:

- Form a team, with members from Production, Quality Control, Resident Engineering, FSC, and PVT.
- Determine a root cause. (may or may not need TOPS).
- When parts are the cause, Quality Control should QR the parts and get new parts on the line.
- When it is a design problem, work a CR/CR.
- When a temporary solution has been developed, issue an Alert/Deviation. 100% hand-retorque may be required until concern resolution.

## 2. Other Transducerized Systems (continued)


1. If all readings are within the specification range, proceed with the route.
  1. Upon completion of the route, download the data to the Torque Inspection and Studies System.
  2. Generate the required reports.
2. If the process becomes suspect (i.e. the operator notices a change, torque display indicates bad torque), perform a residual torque check. Residual torque checks are not routinely required, but should be part of the calibration check.
3. Verify, at least once a month, that the cal values are correct and follow manufacturers instructions for corrections. Measure and record (S) residual torque values as part of the calibration check.
4. Verify, at least once a year, that the power tools internal transducer measurements match the applied torque. Follow manufacturers instructions for corrections.

### Production Responsibilities:

- a. Production is responsible for using correct tooling and operating procedures on all operations.
- b. Correct all units flagged by FSC personnel.
- c. Notify the FSC if the process becomes suspect (i.e. operator notices a change, torque display indicates bad torque).
- d. Review TISB reports. For Mandatory "M" / Critical "C" operations with click limits less than 1.00, begin hand checking all future units with click wrench set to the minimum dynamic limit. Continue hand checking until notified by the FSC that corrective actions are in place.

# TIAP - Torque Integrity Assurance Program

## IV, B: Residual Torque Surveillance



**IV: Torque Surveillance (continued)****B. Residual Torque Surveillance (see flow chart IV, B; dated 10/30/99)**

Residual Torque Surveillance is performed on all operations that do not have an internal transducer. Residual torque measurement will detect changes in the process but will not identify the cause (i.e. tool, component, operator, etc.). Process capability cannot be determined from residual data. A dynamic Torque Process Potential Study must be performed to determine a preliminary capability (see chapter IV, Torque Process Potential Studies).

**FSC Responsibilities:**

1. Enter the operation into the TIBS database.
  - a. Enter the operation into TIBS manually or by using the MPPS/QSPAS Import process. Make sure that all the relevant fields are filled out. If residual inspection limits are not used, the "residual" fields should be left blank. Use the following identifiers for the "Type" field:
    - "—" A TPPS has not been completed, dynamic specifications are used as inspection limits.
    - "D" A TPPS has been completed, dynamic specifications are used as inspection limits.
    - "R" A TPPS has been completed, residual limits are used as inspection limits.If a TPPS study has been completed, fill out the "TPPS Data" and "Ppk" fields in the TIBS record.
  - b. Set the DataMyte to measure peak torque (not break away or other algorithm).
2. Measure five (5) units with the DataMyte. When taking a measurement, watch the fastener for movement. When movement begins, stop applying torque to it. The DataMyte will sound.
3. Mark any units that are outside the inspection limits or show any other concern (missing fastener, loose joint, crossed or stripped thread). Write the ROTATION number on the Torque Concern Notice.
  - a. If any one torque value is below the lower inspection limit, notify Production with a Torque Concern Notice (Chapter VII, Torque Concern Notice). Go to Corrective Actions, Chapter IV, Section C.
  - b. If two or more values are above the upper inspection limit:
    1. Visually check the tool and support facilities for discrepancies or changes (i.e. air pressure, oiler working, etc.). Ask the operator if any changes were noticed.
    2. Notify Production and the FSC Coordinator with a Torque Concern Notice. The FSC will assess the situation and make a determination as to further actions required (i.e. tool adjustments, dynamic torque check).
    3. If the FSC determines that units were produced with dynamic torque above the upper spec limit, the FSC will notify Resistant Engineering, to determine what, if any, corrective actions are required.
    4. Proceed with the route.
  - c. If a unit shows another fastener concern (missing or loose fastener, crossed threading or stripped threads, loose joint),
    1. Notify production immediately with a Torque Concern Notice so the unit can be repaired.
    2. Select and enter an "Assignable Cause" into the DataMyte.

**B. Residual Torque Surveillance****3. a. (continued)**

3. Notify the FSC if a concern becomes chronic. The Coordinator will assess the situation and take the required steps (i.e. form a team, initiate problem solving, write CR/CR, etc.) to eliminate the concern.
4. If all readings are within the residual limit, proceed with the route.
5. Upon completion of the route, download the data to the Torque Inspection and Studies System.
6. Generate the required reports (see chapter VIII, Torque Inspection and Studies System).


**Production Responsibilities:**

1. Production is responsible for using correct tooling and operating procedures on all operations.
2. Correct all units flagged by FSC personnel.
3. Notify the FSC if a process becomes suspect (i.e. operator notices a change, fastener is not being driven all the way in, fastener breaks with full rundown).

**This page was intentionally left blank.**

# TIAP - Torque Integrity Assurance Program

## IV, C: Corrective Actions



**IV: Torque Surveillance (continued)****C. Corrective Actions (see flow chart IV, C; dated 10/30/98)**

Use this procedure whenever an operation is below the minimum torque.

**FSC Responsibilities:**

1. Take five (5) more torque samples (dynamic or residual) on the operation.
  - a. If all the samples are within the dynamic specification (dynamic data) or the residual limits (residual data), take five (5) torque samples every hour for the next two (2) hours. If no other out-of-specification samples occur, return to normal sampling (see sections A or B of this chapter, Dynamic Torque Surveillance, or, Residual Torque Surveillance, respectively).
  - b. If one (1) or more of these samples is below the minimum torque:
    1. Instruct production to begin hand checking all future units with a click wrench set at the minimum torque.
    2. Assist production to determine if the concern is plant controllable (tool, socket, operator, air supply, tool setting, lubricator). If the tool setting is suspect, measure the dynamic torque using an external transducer.
    3. Repeat steps (1) and (1a) after production has corrected the operation.
    4. If no immediate action corrects the concern and no root cause is found, notify management.
      - A. Form a team with members from Production, Quality Control, Product Engineering, FSC, and PVT.
      - B. Determine a root cause (may or may not require TQPS).
      - C. When parts are the root cause, Quality Control will QR the parts and remove bad stock from the line.
      - D. When the root cause is a design issue, write a C/WCR.
      - E. When a temporary solution has been developed, issue an Alert/Deviation. 100% hand checking may be required until concern resolution.
    5. Repeat steps (1) and (1a) after production has corrected the operation.
    6. Enter the process adjustment date into TSS if the corrective action resulted in an adjustment or correction to the tool and/or socket.
    7. If the process is identified as "reduced inspection frequency" (see Chapter VI, Surveillance Frequency), reset the "Class" field to its original frequency.
    8. File the completed "Torque Concern Notice" with the records for that operation.

**C. Corrective Actions (continued)****Production Responsibilities:**

1. When informed by FSC, begin hand checking all future production with a click wrench set to the minimum torque. Continue hand checking until the FSC determines that the process is back in control.
2. Correct all plant controllable causes immediately.
3. Campaign downstream units with a clicker wrench set at the minimum torque.

**a. Mandatory (M) / Critical (C) Operations:**

1. Check downstream units:
  - A. to the last sampled unit (4 hours earlier) or
  - B. until all units that have not been shipped are checked.
2. If suspect vehicles have been shipped, refer to Procedure VOPQJU0004, Product Containment and Preventive Actions. It is not necessary to invoke Procedure VOPQJU0004 if the dynamic torque checks reveal the tooling is operating within the dynamic torque specification.

**b. Standard Characteristics ("S") or Warranty ("W") Operations:**

1. Check downstream units:
  - A. to the last sampled unit or
  - B. until (30) units in a row are found with the proper torque (i.e. no scanner rotation) or
  - C. to the point in production where checking becomes impossible without major disassembly of the vehicle.
2. The FSC Leader should consult with the Resident Engineer to determine if any additional action is required.
3. Assist FSC personnel in their responsibilities.
4. Normal operations may resume when FSC testing determines that the operation is within the dynamic specification.
5. Complete the Corrective Actions section of the Torque Concern Notice and give a copy to FSC.

## VI:Torque Concern Notice

The Torque Concern Notice is a written notice to the Line Supervisor identifying an operation that is outside the dynamic specification or the residual limits. A pad of notices should be carried by each Inspector. This form has three copies, two are given to the Line Supervisor, the other is retained by the Inspector. This copy can be discarded when the top copy is returned by the Line Supervisor.

This Inspector will complete the form through box "ROT # LAST OK" (rotation # of last OK unit from prior inspection records in the Datamyle) and sign the form. The Inspector also enters the Torque Concern Notice Number into the Datamyle in the space provided. The Line Supervisor will sign the form and take the top two copies. The Supervisor is required to complete the "ACTION TAKEN" and request a re-audit of the operation to verify the effectiveness of the corrective action. The Inspector will record the re-audit values in "ACTION TAKEN" and indicate the rotation number of last re-audited unit in the "ROT # ALL OK" box.

The top copy will be taken by the Inspector and will be filed with the TEPB records of that inspection. The second copy will can be retained by the Line Supervisor for future follow-up, or discarded. The signatures of the FBC Coordinator and Area Manager are optional.

A locally designed torque concern notice may be used in place of the Torque Concern Notice form BSA 9172, (dated 7/15/91), shown below. The local form must contain, at least, the information shown below. The form must be sequentially numbered for tracking purposes.

**TORQUE CONCERN NOTICE**

NO. \_\_\_\_\_

DATE:	SHIFT:	ROD#:	DISP#:
PROCESS NUMBER:	MANUFACTURE/ASSEMBLY/OPERATION:		TYPE:
PROCESS DESCRIPTION:			
TORQUE PRESET:	MANUFACTURE/DYNAMIC	MIN/MAX	DISP#:
ACTION TAKEN:			
ROT # LAST OK:	ROT # LAST OK:	ROT # ALL OK:	
ACTION TAKEN:			
TORQUE ZONE#:		ZONE REV/SPEC#:	
FBC CODE#:		AREA MGR#:	

BSA 9172 (ISSUED 7/15/91)

**VII: Surveillance Frequency**

The surveillance frequency of an operation will vary depending on its designation and state. Product Engineering designates operations requiring auditing. Those operations have a designation in the CTL column of the Tool Screen (PF12) in GSPAS/WPPS, an "M" designates a mandatory compliance operation, an "S" or "W" designates a significant characteristic or warranty operation. These designations will be in the "Class" field of TIBS. The plant may designate other operations to be monitored with an "O" in the "Class" field. The plant may stop auditing plant designated operations at any time.

Designated operations must be audited at the following frequencies:

**A. Mandatory (M)/ Critical (C) Operations**

The sampling rate on Mandatory/Critical operations will begin at 5 fasteners twice per shift, separated by at least four (4) hours. After a TPPS and after the process is determined stable, the sampling rate may change, as follows:

For operations that have shown process stability for at least one (1) month and have a Ppk greater than or equal to 1.67, determined by a TPPS, or a Cpk greater than or equal to 1.33, determined from dynamic torque surveillance, the sampling rate may be reduced to 5 fasteners per shift. This condition is valid for any delta process only if a campaignable item can be contained within the plant at the reduced audit frequency.

On such operations, the words "Reduced Inspection Frequency" or "RIF" should be entered in the "Comment" field in the TIBS database to document the change. The "Class" field should be changed from M (Mandatory) to G (Mandatory, or "Mandatory, Good capability). The database should already contain the TPPS Data and the Ppk or Cpk for the process, as well as the Last Process Adjust Data. The routes that include the process can then be changed to include only one inspection per shift (instead of two) for this process.

**Note:** If any low torque is found on a "reduced inspection frequency" operation, it must be returned to full inspection frequency. After the process has been stable for one month, the reduced inspection frequency may be reinstated.

**B. Significant Characteristic (S) or Warranty (W) Operations**

The sampling rate on Significant or Warranty operations will begin at 5 fasteners every shift. This rate may be reduced after a TPPS and after the process is determined stable.

For operations that have shown process stability for at least one (1) month and have a Ppk greater than or equal to 1.67, determined by a TPPS, or a Cpk greater than or equal to 1.33, determined from dynamic torque surveillance, the sampling rate may be reduced to 5 fasteners per day, alternating sampling each shift.

On such operations, the words "Reduced Inspection Frequency" or "RIF" should be entered in the "Comment" field in the TIBS database to document the change. The "Class" field should be changed from "S" or "W" to "R" (Reduced). The database should already contain the TPPS Data and the Ppk or Cpk for the process, as well as the Last Process Adjust Data. The routes can then be re-arranged so that the process is sampled alternately on day and night shifts.

**VI: Surveillance Frequency****C. Low Volume Process Operations**

Some operations are used infrequently. This makes it difficult to maintain a consistent sampling rate. Low volume operations are defined as seven (7) or fewer jobs per hour and less than five (5) of the subject fasteners per unit. Create a separate route (matrix) for all low volume operations. Keep low volume readings in the DataMyte until a full sample of five (5) readings is obtained. This is necessary because the database load program will mark as "missed inspections" any sample set containing fewer than five readings. If additional samples are required, record them in a secondary matrix. Create the new matrix using either the set-up or re-scan mode of the DataMyte. These additional readings will not appear in the computer generated reports. For these operations, use the following rule.

1. Mandatory (M)/Critical (C) Compliance Operations - Sample one unit every four (4) hours.
2. Significant Characteristic (S) or Warranty (W) Operations - one unit every shift.

## VII: Torque Auditing Route Development

Torque auditing routes allow the efficient sampling of threaded fastener operations. The operations included in a route are based on zone location and audit frequency. This chapter covers details of route development for special situations.

Torque auditing is normally done with a DataMyte Model 3063. For information on these, see DataMyte's user guide or the B&A DataMyte Training Manual. For more information on torque inspection, refer to the Vehicle Operations (VO) Torque Inspection and Staking System (TISS) User's Guide.

### A. Calibration

*Torque measuring equipment is to be calibrated in accordance with FAP03-018, Control, Calibration, and Maintenance of Test Equipment. Verify DataMyte and Transducer Torque wrenches at least once a month or when abnormal readings are observed.*

Set click wrenches that are used in 100% duty production to the mean of the dynamic specification. Check at least once per week that they maintain that torque level, if the operation is NOT under torque surveillance. Otherwise, check at least once per month.

Set click wrenches that are used in repair operations to the mean of the dynamic torque specification. Check at least once per month that they maintain that torque level.

Set click wrenches that are used in campaigns and hand checking operations (i.e. Corrective Actions) to the minimum torque. Check at least once per month that they maintain that torque level.

All other click and measuring equipment must be verified at least once per month. Suspect wrenches or wrenches that have been dropped must be verified immediately. Maintain a log of verification checks by serial number for each click wrench, measuring wrench, and DataMyte using a suitable record system.

The calibration setting of electric or electronically controlled power tools should be checked at least once per month and five (5) residual torque values recorded. Verify at least once a year, that the power tool's internal transducer measurements match the applied torque from an external "calibration" transducer.

### B. Element Numbers, Types & Description

Data is identified by process number in the TISS. This number is the MPPS/GSP48 process number with the element number appended to it. For example, process CX1250 element 100 is listed as CX1250100.

1. Identify identical left and right side operations with the true element number and the element number incremented by one, respectively. See section G, Process Consolidation, of this chapter, for a full explanation.
2. Place an "A" in the "Type" field when the operation is automated (no daily data is collected).

## VII: Torque Auditing Route Development

### B. Element Numbers, Types & Description (continued)

3. Place a "D" in the "Type" field when dynamic torque data is collected on the operation.
4. Place an "R" in the "Type" field when the audit specification is a residual limit based on a TPPS, not the dynamic specification.
5. Place an "E" in the "Type" field when an off-set adapter is used to collect residual data on the operation.
6. Place an "S" in the "Type" field when a TPPS has been successfully completed on the operation and the residual inspection limits are the dynamic torque specification limits.
7. Leave the "Type" field blank if a TPPS study has not yet been completed for the operation (except for "A" and "D" Types).

### C. Off-sets

The addition of an off-set adapter to an electronic torque wrench will affect the torque value it measures. Any off-set adapter that changes the effective length (lever arm) of the torque wrench changes the value received. Hand position will effect this relationship, also. So, be consistent with hand position and both length and position of the off-set adapter used on an operation.

Create a new gauge in the DataMyte gauge table with a Full Scale Value that is corrected to allow for the off-set. The correct value can be determined using the Power Tool Analyzer. Enter this gauge number into the TISS records for the process, and the TISS gauge table. The DataMyte will handle the correction, there is no need to adjust the residual limits for the off-set. Enter "E" into the "Type" field and a note like "offset" into the "Comment" field in TISS.

### D. Multiple Spindle Operations

Torque data on all multiple spindle power tools may be taken residually. The residual torque for each spindle is to be measured as an individual system. Record and identify the data of each spindle separately. The daily torque inspection sampling is stated under section VI Surveillance Frequency.

The exception to residual torque readings is wheel multiplex (lugnut secure). Torque data from wheel multiplex equipped with transducers is to be taken dynamically using a peak meter or a torque monitor. The dynamic torque for each spindle is to be measured as an individual system. Record and identify the data of each spindle separately. Sampling will be (5) readings per spindle, once per shift. In addition to assure that the monitor and transducers are reading correctly, a sample of (1) residual reading of each spindle every (4) hours per shift must be performed.

### E. Part Usage

If incorrect part usage is observed, notify the Zone Supervisor and FSC Coordinator. Production is responsible for using the processed parts and for identifying and correcting all vehicles with suspect parts.

Enter "WRONG FASTENER" into the "Assignable Cause" field in the DataMyte regardless of whether the readings are in or out of spec.

## VII: Torque Auditing Route Development (continued)

### F. Process Consolidation

Processes may be combined and treated as one operation, regardless of model and vehicle line, when the following conditions are met:

1. Same power tool
2. Same operator
3. Same torque specification

When processes are consolidated, enter the process number that they have been combined with in the "Comment" field of the TISB database (i.e. "See #000000" to document this action). Make sure that ONLY the operation where the data is collected is in an inspection route, and the others (without any data) are just listed in the TISB database for reference.

If a process is done on both sides of the vehicle or in multiple stations, create separate element numbers in the DataMyte, making separate inspections for each side and station.

For symmetrical operations, assign the left side operation the true element number and the right side operation the true element number plus 1 (i.e. If the element number is 30, assign the left side data 30 and the right 31).

For multi-station operations, assign incremental element numbers to each station. Clearly mark each station so future data can be compiled in the correct database.

### G. Repair Operations

Torque control in off-line and on-line repair areas is to include the following:

1. A list of torque specifications for all operations repaired in that area.
2. Power tools capable of achieving the specified torque, or
3. Click or dial Indicator wrenches to assure the correct torque on repair operations.

Set click and dial indicator wrenches that are used in repair operations to the mean of the dynamic specification. Check at least once per month that they maintain that torque level.

Suspect wrenches or wrenches that were dropped must be calibrated immediately. Maintain a log of calibration checks by serial number for each click wrench, measuring wrench, and DataMyte.

### H. Rotation Number

Use rotation numbers to establish points in the production sequence at which corrective actions began or ended. After taking torque readings, enter the rotation number into the DataMyte using the Label feature. Use the rotation of the last unit in the sample set. Rotation numbers are included in some of the computer generated reports, with the actual torque values. Details of the "Label feature" are in the DataMyte User's Manual.

**VIII: Torque Inspection and Studies System**

The Torque Inspection and Studies System (TIBS) is a PC database program for recording, analyzing, and reporting torque process information in an assembly plant. Process information is entered into TIBS manually or through the automated Import MPP/GSPAS Data process. Inspection routes are defined and maintained in TIBS, and downloaded into the DataMates. Data collected in the DataMates is uploaded into TIBS for analysis and report generation.

**A. Major TIBS Reports**

The following are the major TIBS reports. Most reports include options to customize the reports to fit the various needs of the plants.

1. **Daily Report** - This report summarizes the number of operations to be checked, the number checked, and lists all operations that had at least one data point outside the inspection limits. Optionally, it can break the information down by shift for each department (Body, Paint, Trim, Chassis), or by supervisor. This report goes to the area manager, and to the zone supervisor.
2. **Perpective Summary Report** - This is similar to Report 1 except it includes as many days of production as desired.
3. **Process History** - This report provides a process history of a single operation. It can include any number of days.
4. **Process Ranking Summary** - This report is a ranking of all operations by percentage of samples out-of-specification. It has options to include only out-of-spec processes, or all processes. The Process Ranking Summary provides the following information:

- Rank #
- Operation/Element Number
- Process Description
- Number of Data Points In Report
- % Under Specification
- % Over Specification
- Total % Out-of-Specification
- Inspection Limits - Low and High
- Actual Torque Reading - Lowest and Highest

The Process Ranking Summary is presented at the appropriate Plant Management meeting, with plant action on significant out-of-specification conditions.

5. **Quality Operating System (QOS)** - This report lists the processes that have been outside the inspection limits for the current and preceding months. This report is presented at the appropriate Plant Management meeting.
6. **Process Listing** - This report provides a list of processes, with all the information about the processes, except for actual torque readings.
7. **Route List** - This simply lists which processes are on a route, in order.
8. **Export Process History** - This option will export process history of a single operation to an ASCII text file which can be used by Excel, Lotus 123, or other software. This allows flexibility in graphing and analysis of historical data. It can include any number of days.

**VII: Torque Inspection and Studies System (continued)**

TBS provides a number of options for route and file maintenance, data communication, and so on. For more information, see the Torque Inspection and Studies System Users Guide. A few important procedures are highlighted here:

**B. Related Procedures**

1. Import MPPS/GSPAS Data - This procedure can be used to automatically copy all MPPS/GSPAS torque operations, specifications, and tool data into TBS. This simplifies creating the TBS database for a new vehicle line. The procedure can also be used to check MPPS/GSPAS for any changes, and update an existing TBS database. A report can be generated showing all the differences between TBS and MPPS/GSPAS data. The FSC may run this process regularly to ensure that the TBS database is up to date.

**D: Record Retention**

The following records are to be identified on the Document/Records Matrix of the responsible department/activity and retained in accordance with the Global Information Standard 1 (GIS1), OR the Corporate Management Records (CRM) Retention Schedule, the European Records Management Manual (ERMM), or other Regional Records Management System, may be used until March 31, 1999.

**A. Torque Process Potential Studies (Hard Copies and Summaries)**

Retain the latest Torque Process Potential Study (full and min) for each fastener operation for One (1) year after the termination of the operation.

28.04 (GIS1), Last Use + 1 year  
28.04 (CRM), Active +1 year

**B. Inspection Data & Torque Clearance Notices**

Retain all data for One (1) year after the conclusion of the current model year.

28.04 (GIS1), Last Use + 1 year  
28.04 (CRM), Active +1 year

**C. Calibration/Verification Data (Dataloggers, Transducers, Clicker Wrenches, etc.)**

Retain all data for Two (2) years after the date the original calibration/verification record was superseded by the new calibration/verification record.

28.05 (GIS1), Superseded + 2 years  
28.05 (CRM), Active +2 years

**X:** Forms

	Page
Torque Concern Notice (B&A 8172 - issued 7/16/01)	46
TPPB Form #1 - Inspection Limit Notification, dated 1/94	62
CR/CR Form #2 - Request for New Torque Specification, dated 1/94	63
CR/CR Form #3 - Request for New Expanded Torque Spec. or Fastener Finish Change, dat 1/94	64
CR/CR Form #4 - Request for Design Action, dated 1/94	65
Torque Process Potential Study Worksheet (TPPBWKSH-1), revised 8/97	67
TPPB Monthly Study Team Progress Report (TPPBMTTHY, January thru June) revised 10/30/98	68
TPPB Monthly Study Team Progress Report (TPPBMTTHY, July thru December) revised 10/30/98	70

**XII:** Exhibits

## Flow Charts:

	Page
II, A: Setting Up Operations, dated 10/30/98	10
II, D: New Model Programs, dated 10/30/98	12
III, A: TPPB Prioritization, dated 10/30/98	14
III, C: Benchmarking Current Production, dated 10/30/98	18
III, D, 2a: Dynamic & Residual Torque Study, dated 10/30/98	22
III, D, 2z: Residual Torque Study w/Dyn. Mean Adjust, dated 10/30/98	24
III, D, 2c: Residual Torque Study, dated 10/30/98	26
III, D, 3: Data Collection, dated 10/30/98	28
III, D, 4: Data Analysis, dated 10/30/98	30
IV, A: Dynamic Torque Surveillance, dated 10/30/98	34
IV, B: Residual Torque Surveillance, dated 10/30/98	38
IV, C: Corrective Actions, dated 10/30/98	42
III, D, 4: Data Analysis, dated 10/30/98	50
TPPB CR/CR & Alert Resolution Flow Chart, dated 10/30/98	60

**XII: Related Procedures and Documents**

Refer to the Vehicle Fastening Systems Master Document List for the latest revision level of the documents.

**1. Ford Portable Power Tool Manual Standards:**

PT-1, Standard Tool Category (Size) Numbers for Threaded Fastener Tools

PT-2, Ford Power Tool Certification Program

PT-3, B&A Standard Torque Specifications

PT-4, Standard Drive Sizes for Certified Tools

PT-5, Guidelines For Obtaining Threaded Fastener Capability

PT-6, Guide for Socket Clearance Requirements

PT-7, Ergonomic Considerations for the Selection and Specifications of Power Tools

PT-8, Handling and Control of Power Tools in Assembly Plants.

**2. DataMyte Model 3053 User Guide****3. DataMyte Model 3053 Training Manuals****4. VQGO Torque Inspection and Studies System User Guide****5. Ford Continuing Process Control and Process Improvement guide book, #60-01-251****6. Vehicle Operations SPC Manual:**

SPC-101-D, Process Potential Study

SPC-304-C, Monitor Mode - Considerations for Reducing Sampling on Significant Characteristics Having Required Mandatory/Critical Checks

SPC-602-D, Normality Check

**7. FAP03-015, Control Calibration and Maintenance of Measurement and Test Equipment.****8. VOPQUG-004, Product Containment and Preventive Actions.****9. Failure Mode & Effects Analysis (FMEA) Handbook****10. Deleted****11. Videotapes:**

Torque: A Measure of Quality

Team FSC: Roles and Goals of the Fastening Systems Control Team (Part 1 & 2)

**THIS IS THE LAST PAGE OF VOPFAG241**

**This page was intentionally left blank.**

**Appendix A** contains:

- Torque Control Plan Letter to Product Engineering & Signature Page, August 1994.
- Flow Chart III, D, 4; Data Analysis: dated 10/30/98
- TPPS CR/CR and Alert Resolution Flow Chart: dated 10/30/98
- TPPS CR/CR & Alert Resolution
- TPPS FORM #1 - Inspection Alert Notification, 1/94
- CR/CR FORM #2 - Request New Torque Specification, 1/94
- CR/CR FORM #3 - Request Extended Torque Specification, 1/94
- CR/CR FORM #4 - Request Design Change, 1/94

August 1994

To: All Product Design Engineers - All PEOs  
Subject: Torque Process Control Plan  
Reference: B&A Operating Procedure H-A-41 (revised)

The relevant procedure identifies three different torque values:

- **Dynamic Torque:** the installation torque value, which represents the torque specified by Design Engineering.
- **Residual (or Inspection) Torque:** the value that an Inspector measures when he monitors the results of Dynamic Torque applied to a fastener.
- **Minimum (Static) Torque:** the lowest allowable torque value.

The Torque Process Potential Studies (TPPS) described in the relevant procedure clearly indicate that there often is not a precise correlation between these torque values. Accordingly, the respective PEOs must recognize the possible differences between Dynamic Torque, which is the basis for the B&A process to install a fastener to spec, and the Residual Torque, which is seen when a secured joint is inspected (e.g., with a torque wrench).

Operating Procedure H-A-41 and related documentation, which lists the Inspection Limits for each operation, are to be recognized as the *Torque Process Control Plan*.

This signed letter constitutes approval of this Control Plan by the respective PEOs. Additionally, it provides "Master" approval for the use of "Inspection Limits" according to the criteria described below.

- Prior to completion of a TPPS:  
Use dynamic specifications as the Residual (Inspection) Limits.
- After completion of a TPPS and process capability ( $P_{pk} > 1.33$ ) has been established, the Residual (Inspection) Limits will be as follows:
  - A - If the residual limits fall within dynamic specifications, then continue to use the dynamic specifications as the Inspection Limits.
  - B - If the lower residual limit falls below the minimum dynamic specification but is greater than (or equal to) 80% of the minimum dynamic specification, then use the TPPS residual limits as the new inspection limits. No PEO notification is required for this condition.
  - C - If the lower residual limit is less than 80% of the dynamic minimum, then notify the PEO of the minimum (static) torque (via a WERB Alert). B&A will use the residual values determined by the TPPS as the inspection limits. The PEO will either:
    - Notify B&A that the minimum torque is acceptable by adding the Minimum (Static) Value to the engineering specification. (The Control Plan will be updated accordingly.) or
    - Issue a WERB Concern to initiate a design revision and authorize B&A to 100% hand torque with a click wrench set to the dynamic minimum until the design revision is in place.
  - D - If the upper residual limit is more than 20% above the maximum dynamic specification, B&A will notify the appropriate plant resident engineer and use the TPPS residual limits as the inspection limits.

A description of this process is shown on the attached flow chart. The signature page is on the reverse side.

**Torque Integrity Assurance Program (TIAP)**  
**Torque Process Control Plan Sign-off**

Organization

Signature

Body Engineering

J. A. Stinson

Signature

R. E. Johnson  
Truck  
Chief Engineer

Signature

A. McDonald  
Body Technology  
Chief Engineer

PTO Engineering

T. Howard  
Engine  
Chief Engineer

Chassis Engineering

A. R. Kammerer  
Chief EngineerLight Truck  
Engineering

R. H. Munson  
LTC Director

E. Grayboy  
Chassis Other  
Engines

P. H. Forni  
Powertrain Chief  
Engineer

CONOUR

Body and Assembly

J. D. Wilkinson  
SME Manager

B. P. Cambon  
Chief Engineer  
Trim, Chassis,  
Electrical & Hydraulics

J. D. Wilkinson  
Chief Engineer  
Stamping and  
Structures

AMESO


J. L. Adams  
Executive Engineer  
Chassis Assembly  
Suspension

R. H. Munson  
Executive Director

C:\DRIVE\1\DATA\1\TECHNICAL\1\TIAP\1\TIAP1.DOC


# TIAP - Torque Integrity Assurance Program

## III, D, 4: Data Analysis.



# TIAP - Torque Integrity Assurance Program

## TPPS CR/CR & Alert Resolution Flow Chart



TPPS CR/CR & Alert Resolution (see flow chart)

The following is a description of the resolution flow for Torque Process Potential Study CR/CRs and Alerts. Each item number corresponds to a box on the attached flow chart.

1. Assembly Plant Conduct TPPS - The Assembly Plant Fastening Systems Control Group (FSC) should conduct a Torque Process Potential Study, as described in Operating Procedure VOPFA0241.
2. CR or Alert Required? - Based on the study results, the VMCE Database "Limits" program will determine if a CR or Alert is required. In general, a CR/CR is required when a process ~~gap~~ ~~gap~~ be done to the Engineering Specifications. An Alert is required if the Lower Residual Limit is less than 80% of the Dynamic Torque Lower Specification Limit, or if the Upper Residual Inspection Limit is greater than 20% above the Dynamic Torque Upper Specification Limit.
- 2A. Revise Data/Myte Inspection Limits if Required.
3. FSC Fill Out Required TPPS Form - When it is determined that a CR or Alert is required, the FSC must fill out the appropriate TPPS summary form (TPPSFRM1, 2, 3, 4). Each form covers a specific type of torque concern, as follows:  
 TPPSFRM1, Inspection Limit Notification  
 TPPSFRM2, CR/CR DATA FORM - Request for New Torque Specification  
 TPPSFRM3, CR/CR DATA FORM - Request for Expanded Torque Specification or Fastener Pitch Change  
 TPPSFRM4, CR/CR DATA FORM - Request for Design Action  
 Keep this form with the Study package.
4. FSC Contact Sister Plants - In the event that other plants are producing the same vehicle, the FSC Groups in those plant should be contacted to discuss study results. Has a study been completed on the same operation? Were the results similar? Do the plants concur on a resolution to the concern? Do the plants concur on an Audit Specification?
5. Responsible Resident Engineer Review TPPS - The Study package should be reviewed with the responsible Resident Engineer and a course of action determined.
6. Requires Design Action? - Is design action required (i.e. CR/CR and Fix Alert) or is PE Notification of a Minimum Torque value required?
7. Resident Engineer Sign Inspection Limit Notification - The Inspection Limit Notification allows the Inspection Limits in the Torque Auditors' Datamyes to be changed to the required levels (determined by TPPS).
8. Assembly Plant Write Alert - A designated person in the assembly plant write an Alert. Addressess on the Alert should include the affected Resident Engineer and the sister plant FSC Coordinator(s) or Counterpart(s).
9. Audit Minimum Approved by Sister Plants - If study results from sister plants are very different and an Audit Minimum cannot be agreed upon, all data should be sent to VOGO Vehicle Fastening Systems for resolution.
10. Forward Alert to VO Vehicle Fastening Systems for Resolution - VOGO Vehicle Fastening Systems should review the data from the plant studies and determine the correct course of action.
11. Resident Engineer Forward Alert to PE as Required - The Resident Engineer shall forward the Alert to the appropriate PE.
12. Add Minimum to WERS or Issue Concern - PE to add minimum to WERS release or issue a CR/CR to implement design action to resolve the concern. It must be understood by the PE that the fastener is being secured to the Installation Torque Specification. The resulting Residual Torque, from which the inspection limits are derived, CANNOT be altered without a design change to the joint (i.e. Dynamic Torque Specification change, finish change, part change, etc.).

*[Signature]*

## TPPS FORM #1 - INSPECTION LIMIT NOTIFICATION

Submit for all operations where the Lower Residual Limit is less than 80% of the Dynamic Torque Lower Dynamic Specification Limit.

To advise the Product Engineering of the results of this study and the use of unique Residual Inspection Limits, write an Alert using the following text.

Submit this form with the TPPS data package to the affected Resident Engineer.

---

Plant: \_\_\_\_\_ Concur: \_\_\_\_\_ Study Completion Date: \_\_\_\_\_

Process Number: \_\_\_\_\_ Element: \_\_\_\_\_ Man Sign War Other

Originating Activity: \_\_\_\_\_ CPSC Code: \_\_\_\_\_ Sequence Number: \_\_\_\_\_

Description: \_\_\_\_\_

Bolt #: \_\_\_\_\_ Nut #: \_\_\_\_\_ Part #: \_\_\_\_\_

A Torque Process Potential Study was conducted on this operation. It indicates that the process variation is well within the dynamic torque specification, but the resulting residual torque is outside the specification.

Engineering Specification: \_\_\_\_\_ Nm ± \_\_\_\_\_ Nm

Dynamic Capability: \_\_\_\_\_ Pp \_\_\_\_\_ Ppk

Residual Inspection Limit: \_\_\_\_\_ Nm ± \_\_\_\_\_ Nm

Minimum Torque: \_\_\_\_\_ Nm

This Alert has been issued to notify the PE of the Minimum Torque value that is the measured outcome of the process.

The study data is available upon request.

---

Concur:

Sister Plants contacted: \_\_\_\_\_

Concur (Yes/No/Pending): \_\_\_\_\_

FSC Supervisor: \_\_\_\_\_

Date \_\_\_\_\_

Resident Engineer: \_\_\_\_\_

Date \_\_\_\_\_

Alert Number: \_\_\_\_\_

V84 TPPS/FM1

DRAFT

**CR/CR FORM #2 - Request for New Torque Specification**

Submit for any operation where the Dynamic Torque Specification fails the joint or is insufficient to drive and seat the fastener.

Submit this form with the TPPS data package to the affected Resident Engineer.

Write a CR/CR and "TB" Alert requesting the use of the corrected specification and the Minimum Static Torque. Use the following text:

Plant: \_\_\_\_\_ Carline: \_\_\_\_\_ Study Completion Date: \_\_\_\_\_

Process Number: \_\_\_\_\_ Element: \_\_\_\_\_ Man Sign War Other

Originating Activity: \_\_\_\_\_ CPBC Code: \_\_\_\_\_ Sequence Number: \_\_\_\_\_

Description: \_\_\_\_\_

Bolt #: \_\_\_\_\_ Nut #: \_\_\_\_\_ Part #: \_\_\_\_\_

A Torque Process Potential Study was conducted on this operation. It shows that the Engineering Specification, ± Nm, (fails the fastener (assumed to drive and seat the fastener) Lowest/Highest) is being used successfully to preclude this condition.

Drive Torque: \_\_\_\_\_ Nm  
(Failure/Minimum)

Corrected Specification: \_\_\_\_\_ Nm  $\pm$  \_\_\_\_\_ Nm

Dynamic Capability: \_\_\_\_\_ Pp \_\_\_\_\_ Ppk

Minimum Torque: \_\_\_\_\_ Nm

An Alert has been issued to permit the use of the Alternate Specification and the Residual Inspection limits for torque inspection. For permanent corrective action, the Corrected Specification and Minimum Residual Torque value should be released.

The study data is available upon request.

Concur:

Sister Plants contacted: \_\_\_\_\_

Concur (Yes/No/Pending): \_\_\_\_\_

FSC Supervisor: \_\_\_\_\_ Date: \_\_\_\_\_

Resident Engineer: \_\_\_\_\_ Date: \_\_\_\_\_

CR/CR Number: \_\_\_\_\_

1MN TPPS/02

### CR/CR FORM #9 - Request for Extended Torque Specification or Fastener Finish Change

1. Submit for any operation where slip-stick friction is causing an incapable process.
2. Submit for operations where joint design or access dictates the use of a non-standard tool (i.e. tuberut, crowfoot) that is not capable within the standard  $\pm 15\%$  tolerance.

Submit this form with the TPPS data package to the affected Resident Engineer.

Write a CR/CR requesting the necessary corrective actions. Use the following text:

Plant: \_\_\_\_\_ Carline: \_\_\_\_\_ Study Completion Date: \_\_\_\_\_

Process Number: \_\_\_\_\_ Element: \_\_\_\_\_ Men Sign War Other

Originating Activity: \_\_\_\_\_ CPBC Order: \_\_\_\_\_ Sequence Number: \_\_\_\_\_

Description: \_\_\_\_\_

Bolt #: \_\_\_\_\_ Nut #: \_\_\_\_\_ Part #: \_\_\_\_\_

A Torque Process Potential Study was conducted on this operation. It indicates that the process cannot be kept within the Engineering Specification,  $\pm 15\%$  Nm, due to \_\_\_\_\_ (the need for non-standard tooling, which creates torque variability).

A finish change or other design action, or a wider Engineering Torque Specification is required to achieve capability of this joint.

Choose 1 or 2, whichever applies.

1. With the existing specifications and joint the dynamic capability is (standard tool),  $P_p$ , \_\_\_\_\_.
2. Testing of the tool (standard and non-standards) for this operation on a joint simulator indicates that the tool capability is,  $P_p$ , \_\_\_\_\_.

To achieve capability ( $P_p$  of 1.33) with the current joint design, the following Specifications are required.

Dynamic Specification: \_\_\_\_\_ Nm  $\pm$  \_\_\_\_\_ Nm

Minimum Torque: \_\_\_\_\_ Nm

No interim corrective action possible. The study data is available upon request.

Concur:

Sister Plants contacted: \_\_\_\_\_

Concur (Yes/No/Pending): \_\_\_\_\_

FSC Supervisor: \_\_\_\_\_ Date: \_\_\_\_\_

Resident Engineer: \_\_\_\_\_ Date: \_\_\_\_\_

CR/CR Number: \_\_\_\_\_

104 TPPS070403

**CR/CR FORM #4 - Request for Design Action**

Submit for gpx operation that cannot be performed to the Dynamic Torque Specification.

Submit this form with the TPPG data package to the affected Resident Engineer.

Write a CR/CR requesting design action. Use the following text.

Plant: \_\_\_\_\_ Carton: \_\_\_\_\_ Study Completion Date: \_\_\_\_\_

Process Number: \_\_\_\_\_ Element: \_\_\_\_\_ Men Sign War Other

Originating Activity: \_\_\_\_\_ CPSC Code: \_\_\_\_\_ Sequence Number: \_\_\_\_\_

Description: \_\_\_\_\_

Bolt #: \_\_\_\_\_ Nut #: \_\_\_\_\_ Part #: \_\_\_\_\_

A Torque Process Potential Study was conducted on this operation. It indicates that the process CANNOT be performed to the Engineering Torque Specification, \_\_\_\_\_ Nm, because the minimum drive torque and fastener failure are too close together.

Minimum Drive Torque: \_\_\_\_\_ Nm

Failure Torque: \_\_\_\_\_ Nm

To minimize concerns, a tool set at \_\_\_\_\_ Nm is being used to overcome the drive torque and the Operator attempts to release the trigger before failure occurs. This method is not reliable and will cause extreme torque scatter and some failures.

A design revision is required to obtain joint capability.

The ratio between failure torque and drive torque should be greater than 3 to 1.

Contact:

State Plants contacted: \_\_\_\_\_

Concur (Yes/No/Pending): \_\_\_\_\_

FSC Supervisor: \_\_\_\_\_ Date: \_\_\_\_\_

Resident Engineer: \_\_\_\_\_ Date: \_\_\_\_\_

CR/CR Number: \_\_\_\_\_

**THIS IS THE LAST PAGE OF APPENDIX A**

104 TPPG/EM

This page was intentionally left blank.

## Intense Program Potential Study Worksheet

**Plant:** \_\_\_\_\_ **Cultivar:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**PROCESS INFORMATION:**

Process No: \_\_\_\_\_ Element No: \_\_\_\_\_ DataMyte file no/s: Dyr: \_\_\_\_\_ Result: \_\_\_\_\_  
Study By: \_\_\_\_\_ Control: M/S/W/N  
Description: \_\_\_\_\_

#### Torque & Acceleration (Unit)

Dynamic Mean: \_\_\_\_\_ Variance of: \_\_\_\_\_ Minimum (Static) \_\_\_\_\_  
 Tool Codes: Processed: \_\_\_\_\_ Active: \_\_\_\_\_ Part #: \_\_\_\_\_  
 Tool Manufacturer: \_\_\_\_\_ Model Number: \_\_\_\_\_  
 Type: Air Shut-Off / Clutch / Drill / Transducer Reaction Absorbed: Y / N  
 Socket Condition: \_\_\_\_\_ Length of Extension: \_\_\_\_\_ Driver: Bolt / Nut  
 Socket or Bit Size: \_\_\_\_\_ Transducer: \_\_\_\_\_ Bay Location: \_\_\_\_\_  
 Bolt #: \_\_\_\_\_ Nut #: \_\_\_\_\_ Part #: \_\_\_\_\_



## **Stretch of Operation**

Oil Test: None / Trace / Excessive Green Band: Y / N  
Torque Mean Prior To Adjustments was: \_\_\_\_\_ Nm  
Remarks: \_\_\_\_\_

8668 Recup

Process # \_\_\_\_\_

Joint Simulator was used to adjust tool to Dynamic Mean Torque. Y / N  
(10 readings, averaged for Mean setting.)

DataMyte used for: Dynamic Torque Y / N Residual Torque Y / N

For Residual Torque, DataMyte was set to Peak Mode. Y / N

If DataMyte was not used, specify type of equipment: \_\_\_\_\_

Power Tool Air Pressure

PSI

TORQUE PROCESS POTENTIAL STUDY

SPINDLE # 1		#2	#3	#4
#	DYNAMIC RESID	DYNAMIC RESID	DYNAMIC RESID	DYNAMIC RESID
1				
2				
3				
4				
5				
6				
7				
8				
9				
10				
11				
12				
13				
14				
15				
16				
17				
18				
19				
20				
21				
22				
23				
24				
25				
26				
27				
28				
29				
30				

THIS IS THE LAST PAGE OF APPENDIX B

### Study Team Progress Report

PLANT:	JOB #:	DATE:		
CARLINE / YEAR:	FSC SIGNATURE:			
<b>GENERAL STUDY INFORMATION</b>				
TOTAL # OF STUDIES DONE THIS MONTH				
TOTAL # OF STUDIES IN THE PROGRAM				
<b>COMMENTS:</b>				
MANUFACTURING OPERATIONS				
TOTAL MANDATORY OPERATIONS				
TOTAL # COMPLETED				
# OF NEW STUDIES COMPLETED THIS MONTH				
# OF REDO STUDIES THIS MONTH				
<b>COMMENTS:</b>				
SIGNIFICANT OPERATIONS				
TOTAL SIGNIFICANT OPERATIONS				
TOTAL # COMPLETED				
# OF NEW STUDIES COMPLETED THIS MONTH				
# OF REDO STUDIES THIS MONTH				
<b>COMMENTS:</b>				
OTHER OPERATIONS				
TOTAL OTHER OPERATIONS				
TOTAL # SIGNIFIED				
# OF NEW STUDIES COMPLETED THIS MONTH				
# OF REDO STUDIES THIS MONTH				
<b>COMMENTS:</b>				
MANUFACTURING CONCERN / CONNECTION				
# OF CONCERNS / CONNECTIONS				
# OF REALLOCATIONS / MINISTRATIONS				
<b>COMMENTS:</b>				
ALERTS				
# OF ALERTS WRITTEN / APPROVED				
# OF CRITS WRITTEN / APPROVED				
<b>COMMENTS:</b>				
<b>STUDY TEAM CYCLE (S)</b>				
<b>TOTAL STUDIES</b>	<b>IN PROGRAM</b>	<b>COMPLETED</b>	<b>REDO</b>	<b>2 YR CYCLE (S)</b>
MANDATORY				
SIGNIFICANT				
OTHER				
<b>TOTAL</b>				
<b>COMMENTS:</b>				
<b>REMARKS:</b>				
VM4 ID:	PASSWORD:			

Revised on 10/30/98  
TPPSMTHY

Study Team Progress Report				
PLANT:	JOB #1 DATE:	DATE:		
CARLINE / YEAR:	FEC SIGNATURE:			
<b>MANUFACTURING CYCLES</b> (MOTORS, COUPLES, DRIVELINES, ETC.)				
TOTAL # OF STUDIES DONE THIS MONTH				
TOTAL # OF STUDIES IN THE PROGRAM				
COMMENTS:				
<b>MANUFACTURING CYCLES</b> (MOTORS, COUPLES, DRIVELINES, ETC.)				
TOTAL MANDATORY OPERATIONS				
TOTAL # COMPLETED				
# OF NEW STUDIES COMPLETED THIS MONTH				
# OF REDO STUDIES THIS MONTH				
COMMENTS:				
<b>MANUFACTURING CYCLES</b> (MOTORS, COUPLES, DRIVELINES, ETC.)				
TOTAL SIGNIFICANT OPERATIONS				
TOTAL # COMPLETED				
# OF NEW STUDIES COMPLETED THIS MONTH				
# OF REDO STUDIES THIS MONTH				
COMMENTS:				
<b>MANUFACTURING CYCLES</b> (MOTORS, COUPLES, DRIVELINES, ETC.)				
TOTAL OTHER OPERATIONS				
TOTAL # COMPLETED				
# OF NEW STUDIES COMPLETED THIS MONTH				
# OF REDO STUDIES THIS MONTH				
COMMENTS:				
<b>MANUFACTURING CYCLES</b> (MOTORS, COUPLES, DRIVELINES, ETC.)				
# OF CONCIRNS / CORRECTIO				
# OF REALLOCATIONS / MINISTRRIES				
COMMENTS:				
<b>MANUFACTURING CYCLES</b> (MOTORS, COUPLES, DRIVELINES, ETC.)				
# OF ALERTS WRITTEN / APPROVED				
# OF CR/CRS WRITTEN / APPROVED				
COMMENTS:				
TOTAL STUDIES	IN PROGRAM	COMPLETED	REDO	2 YR CYCLE (%)
MANDATORY				
SIGNIFICANT				
OTHER				
TOTAL				
COMMENTS:				
REMARKS:				
VM4 ID:	PASSWORD:			

Revised on 10/30/98  
TPPSMTHY

**THIS IS THE LAST PAGE OF APPENDIX C**

### VM/ICE Database Field Codes/ICE Database Field Codes/ICE Database Field Codes

This appendix is intended as a guide for entering the data from the TPPS studies into the VM/ICE database for calculation of residual inspection limits and alert notification. The following express routines ("programs") are used:

- "ADD" - used to enter additional new studies.
- "LIMITS" - used to summarize and calculate new inspection limits and CR/Alert requirements.
- "Monthly" - used to summarize the study data for a specific month.

#### TPPS DATA ENTRY

When entering TPPS data into the system, the following rules should be followed:

- 1) Keep records in process number sequence. After executing the express routine "ADD" (see below) to get into update mode, position the cursor between the lines where the study process to be entered in sequentially. Depress the "PF-9" key and enter the number of lines to be inserted. Be sure to separate all processes with a blank line.
- 2) If a process is rebedded, enter the new study directly below the previous one (without a blank line). Type "REPLACED" in the Elements field of the previous study.
- 3) After additional study lines have been added, type "RENUMBER" on the command line to renumber column 0 to be able to maintain the process sequence.

Express Routine "ADD" (type "exp add" on the command line).

When "exp add" is entered on the command line, the columns are displayed in update mode for data entry and sequenced to the Study Worksheet format. The following codes must be used for columns 14 & 36:

#### Column Number Description and Acceptable Entries

- |    |  |
|----|--|
| 14 | Engineering problem code (more than one may apply), leave blank if not engineering problem)<br>A = No torque specification given for the process.<br>B = Inadequate dynamic torque specification variance - less than $\pm 10\%$ .<br>C = The drive torque overlaps the dynamic torque specification.<br>D = The failure torque is less than the dynamic torque specification.<br>E = Excessive slip-stick friction evident.<br>F = Dynamic torque specification should be commonized.<br>G = Bolt head height or recess depth is inadequate resulting in a cam out of the bolt head or recess.<br>H = Inadequate tool clearance.<br>I = Specified torque results in loose fastener(s) when assembled. |
| 36 | One of these codes must be in this column:<br>O = Operation - study with a single fastener.<br>F = Fastener - study with more than one fastener.<br>R = Range line of a study with more than one fastener.<br>M = Mini study (in place of "O" AND "R").<br>C = Comment line (no data or date, process and element number only).<br>D = Data is with another process (Set in Remarks field 32).   |

**TPPS AUDIT LIMIT CALCULATION**

Express routine "LIMITS" (type "xp limits" on command line)

The express routine "LIMITS" is executed after the study data has been entered, sorted, and stored.

When this routine is executed, the data in the "Range" and "Operation" lines (column 36) will be displayed with the following information added:

- In column 29: Residual limits needed (YES or NO), or the dynamic Ppk is below 1.33 (PpLOW).
- In column 30: Alert or CR/CR, or notification of resident engineer (ALERT, CR/CR OR NOTE).
- In column 37: The new HIGH LIMIT for residual inspection.
- In column 38: The new LOW LIMIT for residual inspection.
- Column 38 & 39: Zeros if dynamic specs are to be used for inspection limits, or Ppk is less than 1.33.

Report #2 can then be run to print the data and Report #3 to print the process description and remarks. Only the lines (rows) selected in the express routine ("O" or "R" in column 36) will be printed, if requested in conjunction with the "LIMITS" program.

Note: Be sure to STORE the file after the express routine has been executed to save all of the changes.

**TPPS REPORTS**

The following reports have been programmed:

- #1 - Pp Ppk analysis of total data file, or pre-selected data.
- #2 - Summary of data for selected operations.
- #3 - Descriptions and remarks for Report #2.
- #4 - Status of Alert and CR numbers.
- #5 - Summary of studies for a specific month.

***THIS IS THE LAST PAGE OF APPENDIX D***

Intra Office

Vehicle Operations  
General Office

To: Assembly Plant: Quality Managers  
Final Area Managers  
Material Managers  
Pre-Delivery Supervisors  
Fastening System Coordinators  
Government Regulation Coordinators

April 19, 2000

cc:  
Marcy Fisher  
Anne Stevens  
James Telzort  
Assembly Plant Managers  
Directors of Manufacturing Operations

From: Dan Hottel

Subject: Torque Concern Resolution (In System) and Vehicle Containment  
Procedure VOITAG241, Attachment I

**Reference: VOITAG241, Torque Integrity Assurance Program For Assembly Plants**

To ensure quick response time for prevention of shipping vehicles with potential torque concerns identified during assembly plant torque surveillance, Attachment I has been developed for Procedure VOITAG241.

Attachment I defines and reinforces the assembly plant routines required to contain, inspect, rework, and release vehicles properly when a torque concern has been identified.

The direction in Attachment I was reviewed during the Government Regulation Coordinators' Conference on April 12.

Please implement the direction provided in Attachment I, effective immediately.

For any questions, please contact:

George Jowin, Supervisor  
Critical Concerns  
VO Final Assembly Engineering

Gavin Huang, Supervisor  
Fastening Systems  
VO Final Assembly Engineering

Dennis Makine, Manager  
Government Regulations  
VO Quality Office

D. Hottel, Manager  
Tooling and Equipment Engineering  
VO Final Assembly Engineering

Attachments: VOITAG 241  
Attachment I

2063-004 0000

OPERATING PROCEDURE  
VEHICLE OPERATIONS  
FORD MOTOR COMPANY

No: VOPFAG241  
Attachment Date: April 19, 2000  
Previous Issue: None  
Page 1 of 3  
Attachment I

**TORQUE CONCERN REACTION (IN SYSTEM) AND VEHICLE CONTAINMENT**

**I. ORGANIZATIONAL COMPONENTS AFFECTED**

Assembly Plants:

Production Departments

Quality Control

Plant Area Engineering

Fastening Systems Coordinator

Government Regulations Coordinator

Convey/Rail Yard

**II. SUMMARY**

This Attachment I to VOPFAG241 defines:

- The torque concern reaction to ensure quick response time for prevention of shipping vehicles with potential torque concerns.
- The details of the reaction steps in Section IV, C.1.b of VOPFAG241.

**III. RESPONSIBILITIES**

**General:**

When a Torque Surveillance Inspector identifies a torque concern for which a "Torque Concern Notice" will be written, the affected assembly plant Production Supervisor must notify the Quality Manager, or designee, within five minutes. The Quality Manager will tell the Pre-Delivery Manager to stop shipping all vehicles immediately. The responsible plant personnel will implement the reaction required to contain, inspect, rework, and release vehicles properly.

Note: Managers, or designees, that provide notification and direction may vary depending plant organizational responsibilities.

**Production Supervisor:**  
**Torque Surveillance Inspector:**  
**Quality Manager:**  
**Pre-Delivery Supervisor:**  
**Area Superintendent / Production Manager:**

When a torque concern has been confirmed by one reading in a second sample of five (241, IV,C), then the Production Supervisor in the presence of the Torque Surveillance Inspector, will immediately call the Quality Manager with the torque concern information. This should be done within the first five (5) minutes of knowing that there is a torque concern. The Quality Manager will tell the Pre-Delivery Supervisor to stop shipping all vehicles immediately.

The Torque Surveillance Inspector will:

- Identify the rotation number of the last good surveillance reading as soon as he/she has retrieved it from the computer in the Fastening Systems Coordinator's office.
- Issue a "Torque Concern Notice" to the Production Supervisor (241, V).

The Production Supervisor will provide the rotation number to the Pre-Delivery supervisor so vehicles built before the last good rotation number can be released. Vehicles will not be released until it is known that all suspect vehicles on the property have been segregated. Every vehicle on the property and in the convoy/rail yard built after the last good rotation number must be re-torqued.

Begin hand torque wrench checking all units down line from the operation ( Per 241, IV, C ). Record the rotation number of the first vehicle hand torqued down line.

Run a High Option Content (HOC) Report listing of all the rotation and serial numbers from the last good reading rotation number up to the rotation number for which hand torque was started on line.

Get manpower together as quickly as possible and walk them to the Pre-delivery Supervisor to receive instructions before going to the yard to re-torque vehicles so they are not held longer than necessary. Identify all vehicles with a sticker "Okay to Ship" or an alternative method as designated by the Pre-delivery supervisor so the convoy yard can move these vehicles when they are completed.

Turn in all torque audit information including the HOC Report to the Pre-delivery supervisor for verification of all vehicles being completed or shipped without hand torque.

**Pre-delivery Supervisor:**  
**Quality Manager:**  
**Area Superintendent / Production Manager:**  
**Government Regulations Coordinator:**

Immediately call convoy yard to "Stop Shipment" of ALL vehicles when notified by the Quality Manager that a "Torque Concern Notice" has been issued. Record all information in a logbook - who, why, when and sign the entry. The Pre-Delivery supervisor will also follow-up with the Area Superintendent and Production Manager regarding the "Stop Shipment."

Prepare a "Yard Campaign" sheet for the torque concern. This sheet will be attached to the HOC printout received from the production personnel when the yard campaign has been completed.

Assist the production personnel with direction on handling the yard campaign, e.g. how to mark the vehicles completed (Okay to Ship Sticker) or mark vehicles that may have to be returned to the plant for repairs.

Notify the convoy/rail yard a second time when the rotation number of the last good torque reading has been identified so they can ship all vehicles built before that rotation number. If a bar code is missing in the yard, do not ship the vehicle until it can be verified for rotation number. Record the time of this entry in the logbook and sign it.

When the yard campaign is completed, including all the vehicles on the plant property surrounding the plant, notify the convoy/rail yard that it is now okay to ship.

Determine if all vehicles were contained; notify the Quality Manager and the GRC by phone/e-mail of your immediate findings. Return the yard campaign documentation to the GRC as soon as possible.

#### IV. RECORDS

Logbook retained at the Pre-Delivery Office until last use, plus one year. (GIS1, 28.04, LU+1)

Logbook retained in the Convoy/Rail Yard until last use, plus one year. (GIS1, 28.04, LU+1 )

This is the last page of Attachment I of Operating Procedure VOPFAG241.

Attach241

EN03-004 0001