

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

NTPL_C	ST	OR	HR	DLR_C	C	ON	C	REV	CPSC	TOT	COLBR	DUR	BU	NUM	ST_P	TECH	TEXT	TEST	TEXT	AREA	COUNT	SLS	DL	TOTL	COUNTRY	OFF	WFO	WVS	WRT	TR	PLA
001	001	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
77.05	77.05	0.1	0001	NA	IN	31801											REPLACE ACCELERATOR PEDAL AND SENSOR ASSEMBLY DUE TO OPEN IN POSITION FOUND DEFECTIVE PEAR PEDAL ASSY, REPLACED.	PER WHEN PUSING ON THE GAS PEDAL RPM WILL NOT REV UP INTERIM HAS TO LET OFF THE PEDAL ON PRESS DOWN AGAIN	USA	USA	148804	1	USA	NA	FT	011					
78.78	78.78	0.8	01001	NA	ON	31801											ENGINE HESITATION		CAN	CAN	45280	100	CAN	NA	FT	011					
81.02	81.02	1.8	0003	NA	TN	31801											VEHICLE LUNES POWER TO PEDAL 1000 TEST PROBLEM 1 WENT TO 0.4L8 WYLER/WYER LP WORKS WHEN NO RESPONSE ON PEDAL. REPLACE THROTTLE PEDAL. AT TO REPLACE PEDAL.	PER CUSTOMER ENGINE HESITATE WHEN YOU PULL CLUT	USA	USA	100000	072	USA	NA	FT	011					
85.1	100.01	1.8	0000	NA	MS	31801											TEST TP SENSOR SHORTING OUT AS PERFORMED PERFORMANCE DMS, RETRIEVED CODE P0221 PEDAL ASSY FAILURE FOUND TP SENSOR ON PEDAL ASSY SHORTING OUT, REPLACED ACCELERATOR PEDAL ASSY, ROAD TEST OK.	CHECK THROTTLE POTEN FOR HESITATION	CAN	CAN	400004	004	CAN	NA	FT	011					
76.88	280.07	3.0	0001	NA	TX	31801											ROAD TEST TEST BY 1000 TP VOLTAGE GOES TO 0 WENT OFF 0.4L8 INSTALL TP SENSOR ROAD TEST OK.	DOD DMS DELAY ON ACCELERATION AT TIMES	USA	USA	100000	004	USA	NA	FT	011					
80.04	110.04	0.8	0011	NA	IN	31801											ENGINE PERFORMANCE TEST, REPLACE PEDAL ASSEMBLY, ROAD TEST AFTER REPAIRS.	CL ENGINE HAS DELAYED ACCEL, FROM 0-2000	USA	USA	100004	004	USA	NA	FT	011					
87.04	100.07	1.7	0000	NA	TX	31801											ENGINE PERFORMANCE TEST, REPLACE PEDAL ASSEMBLY, ROAD TEST AFTER REPAIRS.	CHECK WHEN AT A STOP, CUSTOMER STATES HE WILL STEP ON ACCEL, BUT THERE IS A 2 TO 3 SEC DELAY BEFORE VOLT ACCEL.	USA	USA	100000	004	USA	NA	FT	011					
78.00	281.01	2.4	770	NA	CA	31801											ROAD TEST ENGINE PERFORMANCE TEST 1-14 INCONCLU SAVE K08 DCL DISPLAY AND MONITOR RECORD PEDAL TEST 07 FOUND NO ON AT 1.0V OFF AT 0.8V REPLACE A ACCELERATOR PEDAL UNIT ON AT 0.7V OFF AT 0.8V'S	CUSTOMER STATES ACCEL PEDAL HAS DELAY BEFORE TAKING OFF	USA	USA	100000	1	USA	NA	FT	011					
80.04	100.78	1.8	0001	NA	CO	31801											THIS WORK USED MIS-PULLED COCKS, FORCE TP HE INPUT 2ING FORCE CONCERN, DMS PERFORMANCE CONCERN STEPS 1 & ACCEL PEDAL HAD SHORT IN SW/DN, REPLACED ACCEL PEDAL, TEST CHECKS FROM 0.4L8 OK.	WHEN STEP ON ACCEL, ENGINE ALMOST STALLS, MUST RELEASE ACCEL, THEN WILL REMAIN POWER TO STEP DOWN ON ACCEL AGAIN	USA	USA	100000	004	USA	NA	FT	011					
78.00	207.04	2.1	700	NA	CA	31801											PEDAL SENSOR FAULT DR DUTY ESC TEST PARCELY TEST ORDERED PEDAL ASSEMBLY PEDAL ASSY AND REINSTALLED DMS, ENGINE PERFORMANCE DMS PERFORMED, FAULT CODE P0221 RETRIEVED, RPE PEDAL ASSY, CLEANED COCKS AND RESET OK.	CUSTOMER REPORTS PROBLE ON ACCELERATION AT 40-3000	USA	USA	100000	2	USA	NA	FT	007					
81.02	100.04	1	0101	NA	MD	31801											IN COLD WEATHER ENGINE WILL NOT REV FOR 2-3 SECS WHEN COLD AND STARTING OUT HAVE TO PUSH ACCELERATOR TO PLOOR AND THEN WILL ALL AT ONCE TIME OFF.	PER WHEN PUSING ON THE GAS PEDAL RPM WILL NOT REV UP INTERIM HAS TO LET OFF THE PEDAL ON PRESS DOWN AGAIN	USA	USA	100000	004	USA	NA	FT	011					
78.00	200.04	2.1	0100	NA	KS	31801											ACCEL PEDAL LOOSE, WORKING RAN ALL TESTS, CALLED DMS, INSTALLED NEW ACCEL PEDAL ASSEMBLY.	DMS PEDAL NOT RESPONDIVE, PUSH DOWN 2 IN BEFORE RPM'S BEGIN TO INCREASE	USA	USA	100000	004	USA	NA	FT	011					
78.00	100.12	1	0001	NA	TX	31801											PEDAL ASSY ESC TEST MONITOR TEST FOUND PEDAL ASSY AT FAULT REPLACED WITH TEST BOARD TEST	AFTER YOU DEPRESS ACCELERATOR PEDAL THERE IS A 30 SECOND DELAY BEFORE ENGINE ACCEL BEGINS.	USA	USA	100000	2	USA	NA	FT	011					

INTL. C	ST. BR	HR	COL. C	LOC	OPAC	TECH TXT1	TECH TXT2	DIAGN. TXT	AREA	COUNT	FILE	DATE	ENGRY	ENT	VPS	LABR	VTL	PLA
DET	CRS	S	D	D	CO	CO	CO	CO	CD	TY	CD	CD	CD	CD	CD	CD	CD	CD
7840	210.01	4	2889	*	NA	TX	31881	1978 ACCEL PEDAL NOT PUT RUN SYMPTOM CHART 7 RUN ENG. PERFORMANCE TEST 1 THR 34 CODE 0021 RUN PW POINT TEST PW THRESH. REPLACE ACCEL PEDAL. REPAIR SEC. TEST PWR. CDS.										
8020	288.10	2.4	4272	*	NA	TX	31881	PERFORMED ENGINE DIAGNOSTIC V.L. ENG. TEST HOOD AND REAR. PREP. INT. CHECK FUEL. OIL. CYLINDER BALL WORK. PREPRESSURE. REPLACED ACCELERATION PEDAL ASSEMBLY. REPAIRED OPEN CIRCUIT AT PEDAL.										
8438	288.26	2.31	7032	*	NA	OK	31881	DO NOT OPERATE RIGHT. ENGINE PERFORMANCE DIAGNOSTIC. T.S.L. DI. TUNED ENGINE. DIAG.										
8548	298.62	4.1	4482	*	NA	TX	31881	PERFORM ENGINE PERFORMANCE DIAGNOSTIC 1 IS. REPLACED ACCELERATOR PEDAL ASSEMBLY FOR PART. TEST DRIVE VEHICLE. NO OTHER PROBLEMS FOUND.										
8182	388.27	6.3	1021	*	NA	MO	31881	CHEESE DRIVE PERFORMANCE DIAGN. AND PULLED OUT SHIRT TESTED AND FOUND BLE. SWITCH FAILURE. REPLACED AND PERFORMED TBS PER 01 10 IS AND UPDATED POWER 0 REPAIR RECORD BOOK.										
FL82	302.72	3.4	882	*	NA	BC	31881	ACC. PEDAL AND SENSOR ASBY. ENGINE PERFORMANCE DIAGNOSTIC. T.S.L. DI. TUNED ENGINE. DIAG.										
8086	318.07	3.7	7881	*	NA	CH	31881	DO NOT OPERATE PROPERLY. PERFORMED PERFORMANCE DIAG. CHECKED AND FOUND INTERMITTENT OPEN CIRCUIT IN PEDAL. REPLACED PEDAL ASSEMBLY. DE.										
7838	274.78	1.4	2888	*	NA	TX	31881	SEN. ACCELERATOR PEDAL. TP. SENSOR BAD. ENGINE, OIL, DIA. OIL. DIA. ENG. ENGINE PERFORMANCE. FOUND CODE P0201. AND P0201 IN HOOD CONTROLLER. HOOD. CLEAN. RAN. PREP. INT. TESTS. REPLACED ACCEL. PEDAL. ASSEMBLY.	Y. WITH FAILED TP. SENSOR. CLEAR CODES AND TEST DRIVE. OK. NO OTHER CONCERNS FOUND AT THIS TIME.									
7838	281.88	1.7	8028	*	NA	BC	31881	REPLACED THE START SWITCH.										
8034	338.84	3.7	3872	*	NA	MS	31881	PERFORMED ONE PER. PERFORMANCE TEST. P0201. PRESENT. HOOD. AND HOOD. PERFORMANCE. PREP. INT. TESTS. CO. 8. THRU. 10. 0.										
8084	284.88	2	8054	*	NA	MO	31881	ENGINE START DIAGNOSTIC SYSTEM. ENGINE START UP. TEST.										
8188	304.82	8.3	2882	*	NA	TX	31881	PERFORMED DIESEL. DIAG. WORKSHEET. ALL TEST PWR. MONITORED. PWR. FOUND THE FUEL PEDAL. INTERMITTENT OPEN. REPLACED THE FUEL PEDAL.										
8084	321.88	1	4788	*	NA	IN	31881	SECTION. RLM. PREP. INT. TEST. REPLACE ACCEL. PEDAL. ASSEMBLY.										
8188	387.18	0.7	8888	*	NA	MS	31881	SYSTEM TEST. FOUND VOLTAGE LOW AT CLOSING THROTTLE. REPAIR. CRUISE SWITCH. CHECK FOR THE CLOSING AND CHECK THE SYSTEM OVER AND NO CODES AND CHECK ALL OVER AND FOUND THE PEDAL. IS BAD AND REPLACE THE PEDAL. AND RECHECK OK.										
8188	178.12	1.4	8882	*	NA	MS	31881											

PC03-044-A 5974

TKR										TRCH TDT	TRCH TDT	CLNT TXT	AREA COLNF CD SV CD	SLC SLTDM R CD KCD	COUNTRY WORLD	LON WGS CD CD	LAT WGS CD CD	PLA CD CD
TOT COLOR	BU REB	ST P	HR	DLR	C B C	ON C	PROV	CPSC	COLE									
142.08	2454	24	20	CA	WV	2787				PERFORM DIAG CHECK & REPT REFLASH ACCELERATOR PEDAL SENSOR AND SWP SENSOR CLASH CODES & REPLASH SWP 700000		CUSTOMER STATES TRUCK HAS NO POWER WHILE ACCELERATING	204 USA	12707 004	USA		341 FT	011
01.02	108.70	1	400	MA	FL	2787				VERIFY CONCENTR FUELING CODE P122, TEST TP SENSOR FOUND TP VOLTAGE NOTHING SUSPENSES LIMIT OF 4.8 VOLTS. REPAIR		CUSTOMER STATES NO POWER ON FUEL THROTTLE & BLURBS ON GOLF STARTUPS SEE FOR K & HISTORY	004 USA	12400 004	USA		341 FT	011
01.02	138.17	0.7	197	MA	NC	2787				ACCELERATOR PEDAL MALFUNCTION SEC (BUCK TEST) DIAGNOSIS PEDAL ACCELERATOR PEDAL ASSEMBLY ADJUSTABLE REPLACE		C & VIC HAS NO POWER ON ACCELL POWER SWITCHES BATTERY CHECK 100.00	704 USA	12120 072	USA		344 FT	011
01.02	265.01	2.8	1200	MA	PA	2787				REPLACE		CUSTOMER STATES THE VEH HAS NO POWER AND RECS BLOWING WIND	210 USA	12000 070	USA		342 FT	011
00.02	017.48	0.7	807	MA	MA	2787				OK NO POWER COLD REFL. REO ARMY PER DOWN PERFORM TEST PER PAGE		CHECK CRUISE OF WILL NOT MOVE IN LAW WAS NO POWER FOR SEVERAL MINUTES TAKE LOWER THE COILS. THE WIND-SEE IN	000 USA	12400 004	USA		341 FT	011
01.02	101.27	1.7	800	MA	MD	2787				VERIFIED CONCERN WAS HOOK UP & DMS. SEE TEST TP. TEST IN MINI PP TEST FOR CODES & CHECKING ADDRESS ID ATLANTIC & WICHOR PDS FOUND NO NOT SYSTEM & LIMIT. ACCEL. PEDAL REACHED 1.00V REFL. TP. SETTY LIMIT ACCELERATOR PEDAL. CODE 40	ACCEL PEDAL BAR PEDAL AN OPERENT OK OUT 12 TP IN TIME	CUSTOMER STATES THAT ALL OF A SUDDEN, ACCEL LINE BEING CUT OFF FUEL. NO POWER. IF FUEL THROTTLE, WILL REVERSE RECOVER AND RECS CONCERN NOT CERTIFY	000 USA	00000 070	USA		341 FT	011
01.02	100.00	1.4	400	MA	TX	2787				WP PERFORMED DIAGN. PERFORMANCE DIAGNOSIS. NO CODES SET IN SYSTEM. CHECKED CIRCUITS TO ACCELERATOR PEDAL. ARMY. THE PEDAL IS BROKEN INTERNALLY. REPLACED ACCELERS.	ACCEL PEDAL ARMY.	CHECK FOR THE VEH HAS NO POWER	201 USA	01000 004	USA		344 FT	011
00.04	000.0	1.0	700	MA	MA	2787				MAN DMS AS PER DMSL DMS WREST. CODE P4011 FOUND FAULTY TP SENSOR. REPLACED SENSOR. CLEAR CODES PERFORM O.K.		CUST STS WHILE DRIVING AND ACCELERATING NO POWER. NO RESPONSE MUST SHUT OFF ENG WHEN WINDSTOP AND SHUTTING IN THE CHAIRMAN ABOUT 200 OF ONE CUST STROKE WHEN ENGINE WAS STARTED. NO RESPONSE NO POWER ON 2. ADVISE	200 USA	12000 004	USA		342 FT	011
01.02	200.27	2.0	800	MA	CA	2787				PERFORMANCE DIAGNOSIS. T.S. DI T.S. DI ENGINE SWP		C & NO POWER WHEN ACCELERATING AT HIGH SPEEDS	001 USA	07100 004	USA		344 FT	011
01.02	200.00	0.2	277	MA	GA	2787				PERFORMANCE DIAGNOSIS. T.S. DI T.S. DI ENGINE SWP			770 USA	00000 004	USA		344 FT	011
01.02	240.00	4.0	2000	MA	TX	2787				PERFORMED DIAGNOSIS IF FUEL TEST FUEL SENSOR FOUND FOUND AP SENSOR BAD REPLACE AP ASSEMBLY WREST T.		CUST STATES THE ENGINE HAS NO POWER AT ALL. DSI	201 USA	00000 004	USA		341 FT	011
01.02	100.00	1	400	MA	TX	2787				PERFORM SEC DIAGNOSIS NO CODES FOUND RUN PERFL. M TEST FOUND NOTHING ROAD TEST FOUND ACCELINAT OR PEDAL NOT RESPONSES REPLACED PEDAL ASSEMBLY		CUSTOMER STATES THAT THE VEHICLE HAS NO POWER WHEN DRIVING TO ACCEL LINE	000 USA	00000 004	USA		341 FT	011
00.00	000.0	0.0	000	MA	OH	2787				OK FOR CODES ON FUEL AND TP SENSOR REPLACE AND RETEST ENGINE DMS. REPLACED TP SENSOR. WREST ON		CUSTOMER STATES THAT THE VEHICLE HAS NO POWER WHEN DRIVING TO ACCEL LINE	700 USA	14000 004	USA		341 FT	011
00.00	000.00	0.0	000	MA	TX	2787				WREST ON		CUSTOMER STATES THAT THE VEHICLE HAS NO POWER WHEN DRIVING TO ACCEL LINE	001 USA	00000 004	USA		344 FT	011
00.00	000.00	0.0	000	MA	CO	2787				PERFORM SEC. DMS. DMS. REPLACED DMS. DMS. DMS.		OK FOR VEH. HAS NO POWER AFTER LETTERS OFF THROTTLE PARK WHY AND THEN TRY TO ACCEL.	201 USA	00000 004	USA		341 FT	011

TOT COL BR	CL	RESI ST P	AREA COUNTY	SUB ST	TRM	CHRY	CHRY WFO	AGE	TR	PLA												
MTN_C ST	JAR	DLA	U	C	OK	C	PROV	CHRY	CD	S	TECH	TEXT	TEXT	TEXT	CD	TRM	CD	AGE	TRM	PLA		
DET	CH	S	D	D	D	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD		
61.62	287.48	2.2	498	NA	FL	31801						SPRNG ACCCEL PEDAL ASBY CODE 48 M D 32188 VERIFY CODES AND DIAG STEPS 1 M FOUND NO CONCERNS PRESENT PID DATA SENSOR ALL APPLICABLE COMPONENTS AND FOUND TP		CUSTOMER STATES THAT VEHICLE HABNO POWER WILL NOT RUN ABOVE 60 MPH GEAR AND ACORSE	62E USA	02488	384	USA	1	1981	FF	311
78.00	127.82	6.8	2942	NA	TX	31801						DIAGNOSTIC TEST REPLACED PEDAL ASBY		ENGINE HAS NO POWER	62E USA	02488	384	USA	1	1981	FF	311
193.43	281.28	6.8	4452	NA	TX	31801						32888 THROTTLE PEDAL W/ 28 28 28 48 ROAD TEST ECC TEST FOUND ERROR CODES OF P0221 AND P0200 PERFORM TEST AND REPLACED THROTTLE PEDAL AND CAMSHAFT SENSOR DUE TO MT. LOSS OF SIGNAL ROAD TEST AF DIAGNOSE CONCERN PERFORMANCE TEST, FOUND CODE P0200, REPOSE TO INTERMITTENT PROBLEMS WITH ACCELERATION POSITION SENSOR, RAN REPLACE ACCELERATOR POSITION SENSOR, RETEST, OK AT THIS TEST	TRIAL REPAIRS ENGINE AND TRANS OPERATING PROPERLY	ENG ON ACCEL, VEH HAS NO POWER INTERMITTENT	71E USA	18000	384	USA	1	1984	FF	311
78.00	146.24	1.2	5788	NA	WI	31801						WIDE DRIVER ACCCEL PEDAL SENSOR 32888 ACCEL PEDAL ASBY, REFORM CODE CODE 48 PERFORMED DIAGN PERFORMANCE DIAG TESTS, FOUND CODE P0221 PRESENT, PERFORMED PERFORM TEST, FOUND ACCEL PEDAL ASBY, AT FAULT, REPLACED ACCEL PEDAL	ASBY, AND TEST DRIVE PERFORMED FURTHER DIAG TESTS TO CHECK PERFORMANCE (RAN) ALL OTHER SYSTEMS OPER NORMALLY, CODE P0221 IS PRESENT IN SYSTEM DUE TO AFTERMARKET PERFORMANCE	CUSTOMER STATES THAT THE VEHICLE HAS NO POWER INTERMITTENT NO POWER	68E USA	14140	1	USA	1	1981	FF	311
78.00	488.01	6.5	2013	NA	TX	31801						ENGINE HAS NO POWER AND CHECK SENSOR LIGHT DIMS ON RAN DIAG AND FOUND THAT THE PEDAL ASBY WAS SHD WHEN LIGHT CAME ON VEHICLE WOULD NOT ACCEL		REAR VEH LOST ALL POWER AND HAS NO POWER LINE HISTORY	61Z USA	02487	384	USA	1	1981	FF	311
78.00	184.78	2.4	385	NA	GA	31801						HOOK UP M88 K03C P0221 AND P0221 K03C P0221 TEST P0221 GO TO P0221		CUSTOMER COMPLAINS THAT ENGINE WILL NOT START W/KEY REMOTE CONTROL UNPLUGGED AND ACCELERATOR THERE IS NO POWER CUSTOMER BROUGHT NO POWER WHEN ACCELERATOR IS DISCONNECTED	70E USA	02488	384	USA	1	1981	FF	311
87.45	153.8	1.1	4880	NA	IN	31801						STORING PERFORM WOT TEST MTIME TO R AND TACCELERATOR PEDAL AND RETEST OPEN PEDAL IN 2800S NEW ENG DIAG K03C P0221 TEST P0221 RUN PERFORM RUN DCL MONITOR TEST REPLACE ACCEL PEDAL, RETESTED AND RETESTED		CUSTOMER BROUGHT NO POWER WHEN ACCELERATOR IS DISCONNECTED	61Z USA	02487	384	USA	1	1981	FF	311
81.00	149.72	1	7380	NA	IL	31801						CR DTC PERFORMED ACCELERATOR TEST FOUND PEDAL NEEDS TO BE REPLACED IN AND REPLACED ACCELERATOR PEDAL AND REFORM MONITOR TEST TO VERIFY SENSOR TO SENSOR ON PEDAL IS WORKING ROAD TEST TO VERIFY CONCERN WOT START UP, M88 ENG TEST P0221, DCL DISPLAY, PERFORM TEST GO, REPLACE ACCEL PEDAL		DCL C VEH HAS NO POWER	61Z USA	02488	384	USA	1	1981	FF	311
81.02	141.25	1.1	5082	NA	SC	31801						CR DTC PERFORMED ACCELERATOR TEST FOUND PEDAL NEEDS TO BE REPLACED IN AND REPLACED ACCELERATOR PEDAL AND REFORM MONITOR TEST TO VERIFY SENSOR TO SENSOR ON PEDAL IS WORKING ROAD TEST TO VERIFY CONCERN WOT START UP, M88 ENG TEST P0221, DCL DISPLAY, PERFORM TEST GO, REPLACE ACCEL PEDAL		CUSTOMER STATES THAT THE TRACK HAS NO POWER ON TAKE OFF LIKE THE DAS TRACK IS NOT WORKING ANYTHING DISCONNECT SYSTEM WHEN SHUT OFFS WHEN APPEL LEADER NOW POWER HAS NO POWER, OVER 3000 RPM WHEN SHIFTERAL P0221 SUPPOSE TEST	60E USA	12188	384	USA	1	1981	FF	311
82.41	148.28	1.1	4610	NA	TX	31801						CR DTC PERFORMED ACCELERATOR TEST FOUND PEDAL NEEDS TO BE REPLACED IN AND REPLACED ACCELERATOR PEDAL AND REFORM MONITOR TEST TO VERIFY SENSOR TO SENSOR ON PEDAL IS WORKING ROAD TEST TO VERIFY CONCERN WOT START UP, M88 ENG TEST P0221, DCL DISPLAY, PERFORM TEST GO, REPLACE ACCEL PEDAL		ENGINE HAS NO POWER AT TIMES CUSTOMER STATES NO POWER ON FULL THROTTLE DCL	61E USA	02488	384	USA	1	1981	FF	311
78.00	122.00	6.8	2882	NA	TX	31801						WIDE DRIVER ACCCEL PEDAL SENSOR 32888 ACCEL PEDAL ASBY, REFORM CODE CODE 48 PERFORMED DIAGN PERFORMANCE DIAG TESTS, FOUND CODE P0221 PRESENT, PERFORMED PERFORM TEST, FOUND ACCEL PEDAL ASBY, AT FAULT, REPLACED ACCEL PEDAL		CUSTOMER STATES VEH HAS NO POWER	62E USA	02488	384	USA	1	1981	FF	311

PC03-044-A 5978

TOT CO LBR		DLR		REGI ST P		MTRL C ST GR		DLR S B C		DLR C NOV		CPRC		TECH TAX		CLBY TAX		AREA	COUNT	DLR	DLR	ENTRY	ENTRY	AREA	AREA	TRM	TRM		
EST	DIS	E	D	D	B	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD		
81.82	195.17	1.1	2994	*	NA	TX	31801											317	USA	10013	001	USA	*	141	FF	811			
DIAGN. PERFORMANCE DIAGNOSIS WAS DONE POST THROTTLE PEDAL PERFORMANCE INTERMITTENT PROBLEM WAS REPLACED WITH THROTTLE THROTTLE PEDAL ASSEMBLY, CLEANED O2 SENSOR AND OTHER COMPONENTS CORRECTED FOR														AC		CUSTOMER STATES SOMETIME POWER HAS NO THROTTLE RESPONSE AND POWER LOSS OF POWER													
81.84	99.06	8.8	1914	*	NA	OR	31801											317	USA	17850	001	USA	*	141	FF	811			
PERFORM DISEL, PUMPY TEST, REPLACED ACCEL PEDAL, CLEAR CODES, NO TEST OK																CUST STATES LOSS OF POWER													
81.85	173.22	1.5	3027	*	NA	AR	31801											470	USA	100011	079	USA	*	144	FF	811			
CHECKED COMBINE MONITORED WEL AC FREQ OUT OF RANGE. PERFORMED WGS SELF TESTS RETRIEVED CODE P0221 TP SENSOR HIGH RESISTANCE. RAN THROUGH PUMPY TESTS & RESPECTED WIRING FOR DAMAGE. FOUND 3														NO ACC PEDAL. REPLACED ACC PEDAL ASSEMBLY & RETESTED. GOOD.		CUSTOMER STATES WHEN PRESSING DOWN ON ACCELERATOR LOSS OF POWER DETECTED. AND WHEN PRESSING CLAMP, ENGINE WILL RUN NORMALLY AFTER INITIAL SHUT OFF													
81.86	178.24	1.8	1944	*	NA	OR	31801											812	USA	140000	001	USA	*	140	FF	811			
PERFORM DISEL. CHECKING DIAG TEST 1 FOUND FAULT CODE P0221 AND REPLACE DEFECTIVE FUEL THROTTLE PEDAL ASSEMBLY. CLEAR CODES AND TEST AND RETEST SYSTEMS																SUSPECT FOR LINT HAVE FOUR ACCEL. ON GOLF START AND SUSPECT LOSS OF POWER. BURNING NOISE.													
81.87	481.50	8.7	3047	*	NA	TX	31801											317	USA	150000	079	USA	*	140	FF	811			
DISEL. PERFORM. REPLACED THROTTLE PEDAL ASSEMBLY. OIL LEAK DIAG. TIGHTENED ALL INTAKE AND INTERCOOLER CLAMP. RETEST OK																SYSTEM LOSS OF POWER RUNNING ROUGH													
81.88	178.21	1.8	3066	*	NA	VA	31801											317	USA	140000	079	USA	*	141	FF	811			
PERFORMED NECESSARY TESTS. REPLACED PEDAL ASSEMBLY SCOPED AND PERFORM TESTS																C & VARY BEING TO HAVE A LOSS OF POWER AT STEADY SPEED & ENGINE TO STALL													
81.89	140.88	1.2	307	*	NA	GA	31801											408	USA	101488	079	USA	*	141	FF	811			
REPLACE NEW THROTTLE PEDAL AND PERFORM TESTS																CHECK FOR LOSS OF POWER													
81.90	355.88	3.7	3094	*	NA	TX	31801											317	USA	100013	001	USA	*	142	FF	811			
PASSAGE. PASSECT PASS. DURING FINAL ROAD TEST. VEHICLE AT A STOP HAD NO RESPONSE FROM ACCEL ERATOR PEDAL. SET CODE IN CONT. POWER IN POINT TEST TO ED CODES AND ACCEL A														COORDINATOR PEDAL ASSEMBLY RETESTED ALL THREE.		CUSTOMER STATES ENGINE DIED WHILE DRIVING. ENGINE RESTARTED DURING FELT LIKE IT WAS A LOSS OF POWER.													
78.39	145.88	1.4	4510	*	NA	TX	31801											350	USA	100000	13.00	USA	*	141	FF	811			
RAN DISEL. ENGINE DIAGNOSTIC AND REPLACE ACCELERATOR PEDAL ASSEMBLY																LOSS OF POWER AT STEPS C & B THE VEHICLE WILL INTERMITTENTLY LOSE THROTTLE WHEN SOBBING DOWN THE ROAD. LOSS OF POWER													
78.86	388.1	4.3	4493	*	NA	TX	31801											377	USA	100000	1.1.00	USA	*	142	FF	811			
PERFORMED PERFORMANCE CHART. REPLACED ACCELERATOR PEDAL ASSEMBLY																CHECK AT THREE TRUCK HAS A LOSS OF POWER. ROAD TEST OR GET GOOD DESCRIPTION. DID NOT HAVE THE PROBLEM TODAY													
78.88	524.45	3	2883	*	NA	MI	31801											694	USA	140000	17.00	USA	*	144	FF	811			
RCP ENGINE PERFORMANCE DIAGNOSTICS T.S. DI AGNOSTIC TESTS RCP CHECK TEST DIAG. TEST DISPLAY TEST. RECOMMEND MONITOR ROAD TEST DISEL. ON POINT TEST DIAGNOSIS. REMOVE ACCELERATOR PEDAL AND REPLACE RECHECK.																CHECK FOR LOSS OF POWER AT HIGHWAY SPEEDS													
81.92	411.41	4.1	3983	*	NA	CT	31801											308	USA	140000	001	USA	*	141	FF	811			
RAN DIAGNOSTIC TO REPLACE P.E. ASSEMBLY																TEST. LOSS OF POWER													

TRUCK	TRUCK	TRUCK	AREA	COURT	PLA. DL	TRK.	CITIZEN	CRIM. NO.	JANES	WRT.	TTL			
NO.	ST. BR.	HR	DLR.C	ELC	ONLC	NOV.	CPNG.	NO.	ST.	NO.	NO.			
CDT	CDT	IN	IN	IN	IN	IN	IN	IN	IN	IN	IN			
01.00	100.0	0.5	2000	MA	AZ	3100	TECH TEST	040	USA	17177	004	USA	FT	011
							040	USA	17177	004	USA	FT	011	
00.04	100.0	1	2000	MA	AZ	3100	TECH TEST	040	USA	2000	004	USA	FT	011
							040	USA	2000	004	USA	FT	011	
70.00	100.07	0.0	770	MA	CA	3100	TECH TEST	040	USA	27000	004	USA	FT	011
							040	USA	27000	004	USA	FT	011	
01.00	100.00	1	000	MA	TX	3100	TECH TEST	040	USA	3000	004	USA	FT	011
							040	USA	3000	004	USA	FT	011	
70.00	101.00	1.0	400	MA	NC	3100	TECH TEST	040	USA	21000	004	USA	FT	011
							040	USA	21000	004	USA	FT	011	
01.00	100.70	4.1	000	MA	TX	3100	TECH TEST	040	USA	10000	004	USA	FT	011
							040	USA	10000	004	USA	FT	011	
70.00	100.00	1.0	000	MA	AL	3100	TECH TEST	040	USA	10100	004	USA	FT	011
							040	USA	10100	004	USA	FT	011	
70.00	100.70	1.0	000	MA	TX	3100	TECH TEST	040	USA	3000	004	USA	FT	011
							040	USA	3000	004	USA	FT	011	
01.00	100.00	2.0	770	MA	CA	3100	TECH TEST	040	USA	12000	004	USA	FT	011
							040	USA	12000	004	USA	FT	011	
00.04	100.10	0.0	000	MA	MI	3100	TECH TEST	040	USA	1000	004	USA	FT	011
							040	USA	1000	004	USA	FT	011	
01.00	100.00	4.1	000	MA	AZ	3100	TECH TEST	040	USA	17000	004	USA	FT	011
							040	USA	17000	004	USA	FT	011	
01.00	100.70	0.5	000	MA	FL	3100	TECH TEST	040	USA	10000	004	USA	FT	011
							040	USA	10000	004	USA	FT	011	
00.01	100.00	2.0	000	MA	TX	3100	TECH TEST	040	USA	3000	004	USA	FT	011
							040	USA	3000	004	USA	FT	011	

JLR										TRCH TEXT	CLNT TXT	AREA CD	COUNT BY CD	R.D. R CD	TDL CD	COUNTRY CD	OPT VRS CD	VRS CD	M. VRT CD	PLA CD		
TCT	CD	LNBR	BU	RESM	ST	CD	CD	CD	CD													
NTRL	C	ST	GR	HR	DUR	C	L	C	CM	C	NOV	CD	SPIC	CD	CD	CD	CD	CD	CD	CD	CD	
OST	CD	B	D	D	D	D	D	D	D	D	D	D	D	D	D	D	D	D	D	D	D	D
81.87	438.02	3.1	2732	NA	IN	3901																
78.86	201.32	1.8	11008	NA	CO	3901																
81.82	188.08	1.9	2821	NA	TX	3901																
78.86	182.80	1.7	7180	NA	IN	3901																
88.4	184.28	1.8	28017	NA	IN	3901																
81.82	180.94	1.9	2821	NA	IN	3901																
80.84	181.80	1.7	888	NA	IN	3901																
80.24	211.18	2.4	8620	NA	IN	3901																
78.86	284.78	4.8	4688	NA	TX	3901																
78.86	188.78	1.8	2848	NA	CT	3901																
81.82	188.80	1.8	1980	NA	TX	3901																
78.86	284.04	3.7	28923	NA	AZ	3901																
81.82	282.88	4.8	4817	NA	TX	3901																
81.82	182.41	1.8	7811	NA	MO	3901																
78.86	234.18	3.1	1201	NA	PA	3901																

PE03-044-A 5989

TDT COLLIER		BLK		SU REGN INT P		MTR, C, ST BR		HR 224, 07 J		UN, C, DRV		SPIC		TRCH TRZ		CLNT TRT		AREA	COUNT	BLK	DATE	CONF	CHARGE	PL	PLA				
DET	OFF	E	D	D	CO	CO	CO	CO	CO	CO	CO	CO	CO	CO	CO	CO	CO	CO	CO	CO	CO	CO	CO	CO	CO				
86A	2845	42	4872		NA	NA							3981	NA	NA	2800	0000	0000	0000	0000	0000	0000	0000	0000	0000	0000			
NA PLS DET DO BENCH PERFORMANCE ENGLISH COOKS PUS IN MEMORY DO REPORT TESTS CLEAR COOKS TEST TESTS REPERFORM TOOM A WHILE POW THE TRUCK TO ACT UP CODE PWRG CRAB														WT NO BUCK TIME		KEEP ON GAS AND CHANGE OVER ALSO LACKS POWER WHEN PULLING FEEL WHEEL													
71AE	1832	14	592		NA	CA							3981	NA	CA	17495	0000	0000	0000	0000	0000	0000	0000	0000	0000				
CHECKS AND CORRECT FUSES FOR FUSE ON BOARD TRUCK FOR LACKS POWER W/KEY TO REPLACE FUSE AND REMOVE AMP TO CORRECT CONDITION																REPORTS VEH LACKS POWER													
81AE	2812	47	828		NA	NA							3981	NA	NA	17467	0000	0000	0000	0000	0000	0000	0000	0000	0000				
BENCH PERFORMANCE DIAG, FLOW CHART, NO FAILURES OBSERVED. PERFORMED MDR ECU DISPLAY, MDR																CLNT STATES THAT VEH LACKS POWER AND THE FUEL METER HAS SET RED IND													
81AE	2804	3	828		NA	VA							3981	NA	VA	12007	0000	0000	0000	0000	0000	0000	0000	0000	0000				
BENCH WOULD ONLY RLE ON A ROAD TEST, RAN BDC TESTS, CODE P2221, RAN FOR POINT TEST, CHECKED FUEL, FLOW AT AND NO DRAGGING ON REVERSE. REPLACED FUEL ASSEMBLY, ROAD TESTED. TRUCK IS AM CLUT														OF FUEL, HAD TO PUT FIVE GALLONS ON FUEL IN TRUCK BLEW AIR		POOR PERFORMANCE LACKS POWER													
71AE	1848	2	843		NA	FL							3981	NA	FL	12499	0000	0000	0000	0000	0000	0000	0000	0000	0000				
DOES NOT DISPOSE PROPERLY PERFORM BDC AND FOR POINT TEST. CODE P2221, R & R ASSEMBLY FOR FUEL ASSEMBLY																CUSTOMER STATES THE TRUCK LACKS POWER UPON ACCELERATION													
71AE	1812	8.8	828		NA	MO							3981	NA	MO	18884	0000	0000	0000	0000	0000	0000	0000	0000	0000				
CHECKED AND FOUND ACCELERATOR PEDAL SENSOR WAS REPLACED AS NEEDED																BENCH LACKS POWER													
18AE	220.16	1	100		NA	L							3981	NA	L	14103	0000	0000	0000	0000	0000	0000	0000	0000	0000				
ECU TEST, NO CODES. VEH LACKS LACK OF POWER WHEN COLD, PERFORM TEST																CK LACKS POWER													
81AE	2828	2.7	2122		NA	CO							3981	NA	CO	28420	0000	0000	0000	0000	0000	0000	0000	0000	0000				
DRAIN LINE OF POWER MESSAGE 1 14 PPT TO BDC ACCEL PEDAL, REPLACE ACCEL PEDAL, RETURN ON TEST DRIVE OK																CUSTOMER SAYS VEH LACKS POWER ON ACCEL, DRG SPIN 110114 NO BLINK LIGHTS ON 07/28/88													
86A	1848	1.2	2818		NA	L							3981	NA	L	14188	0000	0000	0000	0000	0000	0000	0000	0000	0000				
CHECKED ON AIR FLEET RESTRICTION ON TP SENSOR TEST 3 TIME INSTALL NEW PEDAL, AMPY OK NOW																CUSTOMER STATED THE VEHICLE IS LACKING POWER ON ACCEL, FROM A STOP, SURELY ABLE TO GET TO 2000 RPM, THEN COOL OFF UNTIL RPM DROPPED AGAIN FOR 2ND GEAR													
81AE	171.61	1.2	782		NA	CA							3981	NA	CA	17716	0000	0000	0000	0000	0000	0000	0000	0000	0000				
NOTE CHECKED BENCH TEST PMS & ACCURACY FOR EXHAUST LEAK PERFORM BDC TEST DRIVE AND TEMP REPLACE LT CYL NO PLUG SEAL FOR OIL LEAK AT TIME, RE TEST NO CODES																BENCH LACKS POWER AT PRIMARY SPEEDS, BENCH HAS A BDC AT PRIMARY SPEEDS & BENCH SOUNDS DIFFERENT AT PRIMARY SPEEDS													
71AE	18728	1.1	828		NA	OK							3981	NA	OK	18888	0000	0000	0000	0000	0000	0000	0000	0000	0000				
SOLE VALVE/ION SWITCH TESTS BDC CHECK TEST CHANGE																CUSTOMER SAYS VEH LACKS POWER													
86A	2848	2.8	828		NA	WA							3981	NA	WA	17888	0000	0000	0000	0000	0000	0000	0000	0000	0000				
INSPECTIVE W/ SENSOR AND TEST SENSOR FINDING OUT OF RANGE, ROAD TEST FOR EXHAUST FOUND LOW POWER, ALL VEHICLE INTO SHOP AND PERFORM COMPLETE FLOW CHART FOR PERFORMANCE TEST 1 THRU																CUSTOMER STATES THAT VEHICLE LACKS POWER, SMOOTH AND ALONE													
81AE	1832	1.4	488		NA	TX							3981	NA	TX	18708	0000	0000	0000	0000	0000	0000	0000	0000	0000				
TEST DRIVE TO VERIFY BENCH LACKS POWER, VEHAL, INSPECTION ALL OK																BENCH LACKS POWER													

TOT COLSR		DUR		AI RESIST P		MTR C ST OR		DLR CLC		DLG NOV		CPIC		CD S		TECH TXT		TECH INT		CLST TXT		APPR COUNT		MIL CL TMR		CENTR. CRY VTR		AMB		TRM							
CDT	DSR	E	H	P	R	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD							
01.01	162.15	2	3877			NA	OK	2181														ENGINE WILL ONLY BUS MONT NOV	001 USA	10000	100		140	FT	011								
01.05	280.00	2-3	777			NA	CA	2181														CUSTOMER REPORTS THE ENGINE	010 USA	12000	1	USA		700	FT	011							
01.06	113.00	0.7	200			NA	TX	2181														WHEN UNIT IS FLOORED IT ONLY	010 USA	10000	100		140	FT	011								
01.07	210.00	1.3	727			NA	CA	2181														DRIVE & REV GUST STOPS	010 USA	10000	100		140	FT	011								
01.08	414.00	4.3	4917			NA	TX	2181														LAST NIGHT DRIVING ON HIGHWAY,	001 USA	10000	100		140	FT	011								
01.09	180.70	1	281			NA	CA	2181														WHEN ENGINE VIBRATES WILL STOP	000 USA	10000	100		140	FT	011								
01.10	170.00	0.8	200			NA	TX	2181														ENGINE WONT ACCEL AT THIS	000 USA	10000	100		140	FT	011								
01.12	280.00	2.0	040			NA	LA	2181														ENGINE STOPPED WHEN PUTTING	000 USA	10000	100		140	FT	011								
01.13	100.70	1	210			NA	CA	2181														ACCELERATOR PEDAL ASSEMBLY	000 USA	10000	100		140	FT	011								
01.14	120.2	1.8	200			NA	TX	2181														VERIFY THE CONCERN, CORRECT PER TO															
01.15	130.00	1	420			NA	TX	2181														FOUR RUN HISS, SET CODE PER LAP															
01.16	200.00	2.0	200			NA	CA	2181														WHILE DRIVING ENGINE HAS ONLY	010 USA	10000	100		140	FT	011								

PRO3-044-A 6007

TOT_CD	LAB	WVR	BU	WVR	ST_P	CHG	NOV	CHG	NOV	CHG	NOV	TCH	TXT	TCH	TXT	CLST	TXT	AREA	COUNT	FILE	DO	ENTRY	CRV	VFS	ANS	VL	FR	PLA	
001	002	003	004	005	006	007	008	009	010	011	012	013	014	015	016	017	018	019	020	021	022	023	024	025	026	027	028	029	
70.45	378.80	4.7	3010	MA	IL	31801							TEST DRIVE VEHICLE FROM ENGINE POSITION ACCEL PEDAL SWITCH BROKE REPLACED ASSEMBLY AND RETESTED OPERATOR			VEHICLE WILL NOT MOVE FROM A STOP AT THIS	818	USA	11000	301	USA		400	PT	311				
64.38	170.71	1.4	3074	MA	NY	31801							PERFORM TEST DRIVE AND VERIFY CONCERN AD THEN PERFORM ROAD TEST AND NOT CODE P2001 CLEAR AND CHECK WIRING AND CONNECTOR ALL OK FOR REPLACE PEDAL ASSEMBLY AND THEN REINSTALL ALL REMOVED COMPONENTS AND TEST	AT DRIVE CR DID NOT EXPERIENCE CONCERN AND PROBLEMS AND ALL CONTROL BUTTONS WORKING FINE. PERFORM ROAD TEST PASS NO DTCs	CLST STATES VEHICLE WILL NOT MOVE INTERMITTENTLY WHEN PUSHING ON THE ACCELERATOR PEDAL. VEHICLE WILL NOT MOVE AS EVEN WILL NOT MOVE. NEEDS PEDAL.	480	USA	12000	301	USA		400	PT	311					
90.01	184.00	1.2	20821	MA	NY	31801							REPLACE ACCELERATOR PEDAL OR ECU SYSTEM AND CODES PERFORM TEST IN TIME TO REFL THROTTLE PEDAL SENSOR ASBY FOR NO POWER ON ACCEL. CONCERN RESIST. OK			VEH WILL NOT MOVE WHEN STEPPING ON ACCELERATOR CR AND ASSEMBLY.	700	USA	12100	301	USA		400	PT	311				
91.82	185.29	2.4	3070	MA	NY	31801							1004 BRO (CLACK TEST)			CR ASBY PEDAL DOES NOT RESPOND AT THIS TIME. ASSEMBLY PEDAL WILL NOT MOVE. CR P2001 DO NOT GO UP. HAVE TO PUT INTO M-THEM INTO DRIVE TO MOVE.	600	USA	11000	301	USA		400	PT	311				
91.82	300.1	1	3091	MA	CA	31801							VERIFIED NO NO RESPONSE FROM ACCELERATOR FROM TEST. CODES P122 P123 IN REPAIR. REPLICATED TEST OK. ASBY. OUT OF RANGE. QUALITY TEST OK.			CLST STATES WILL NOT MOVE WHEN PUSHING ON ACCELERATOR. REPAIRING P2001. MAY BE THAT IT IS COLD THE VEH WILL NOT MOVE EVEN WHEN ENG. IS RUNNING. MONT TESTING.	600	USA	12100	301	USA		400	PT	311				
70.86	243.81	1.6	3034	MA	MA	31801							CHECK ENGINE NO POWER FOUND FULLY ACCEL. BODY			VEHICLE WILL NOT MOVE IN DRIVE GEAR.	600	USA	11100	301	USA		400	PT	311				
70.04	033.88	1.1	3077	MA	MA	31801							CHARGE ELECTRICAL. CHECK TEST				600	USA	10000	301	USA		400	PT	311				
88.91	137.80	0.6	3180	MA	CA	31801							ROAD TEST NO MIL ON NO PWR. PERFORMED TEST. FOUND DTC P2001 TP ONCLUT. PERFORMED PWR POINT TEST FOUND TP SENSOR BAD. ORDERED TP SENSOR (PWR. KIT OF PEDAL ASSEMBLY REPLACED NEW PEDAL ASSEMBLY. PERFORMED TEST. OK AND VERIFY	CLEARED CODES & PERFORMED CHECK TEST. NO ST C FOUND. ROAD TEST & ALL OK. NO MIL.	CLST STATES THAT AT WHEN STOP ON THE GAS THE VEHICLE WILL NOT MOVE. ENGINE & PWR DO NOT RUC. CHECK & ADVISE.	600	USA	12000	301	USA		400	PT	311					
91.82	181.28	1.3	3074	MA	NY	31801							CONCERN 1 THREAD RESPONSE FROM THROTTLE AND AP ED NOT CHANGE AP DOES BUT NOT AS SWITCH PERFORM ROAD TEST P2001 TP SIGNAL CHECK WIRING AND CONSOLE CTR OR CR. REPLACE	PEDAL ASBY AND RETEST DRIVE ON CLEAR CODES AND RETEST DRIVE CR RETEST AFTER TEST PWR OK PASS NO DTCs PERFORM. ROAD TEST PASS NO DTCs.	VEH WILL NOT MOVE ON ACCELERATION IN NEUTRAL. BACK IN DRIFT WILL GO.	400	USA	12000	301	USA		400	PT	311					
70.86	183.88	1.1	3014	MA	NY	31801							CUSTOMER STATED SEVERAL TIMES THE DEPRESSED ACCELERATOR AND ENGINE DID NOT RESPOND. INSTALL PEDAL ASSEMBLY. ROAD TEST OK.			DEPRESSED ACCEL AND ENGINE WILL NOT MOVE.	300	USA	12000	301	USA		400	PT	311				
88.91	184.32	0.8	3180	MA	MA	31801							FULLY POTENTIOMETER THROTTLE PEDAL CONTROL. VERIFIED CLST CONCERN. GAS FOR PROOF DRIVE TO THROTTLE PEDAL ASSEMBLY, ORDER AND INSTALL REPLACEMENT AND RETEST OK.			ENGINE ENGINE CONTROL TOWED TO STOP. MILS BUT WILL NOT MOVE. NO PWR.	300	USA	12000	301	USA		400	PT	311				
70.86	243.81	2.4	3070	MA	NY	31801							VERIFIED CONCERN AND REPLACED PEDAL ASBY AND RETESTED OK.			VEHICLE INTERMITTENTLY WILL NOT MOVE.	300	USA	12000	301	USA		400	PT	311				

TOT. CO. LBR	CLK	PRSN	STCF	AREA	COUNT	BLE. DL. TOL.	ENTRY	GRY. VTS	MAJ	VRT	TRE
MPLE. D ST. GR	PK	D.L.R. CBL. C	ON. D. REV.	CPSC.	CD	RY. CD	PL. CD	CO. CD	CD	CD	PLA
OS*	OS*	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD
TEST NO.	TEST	TEST	TEST	TEST	TEST	TEST	TEST	TEST	TEST	TEST	TEST
81.82	251.2	3.2	7531 *	NA	TX	2181					
78.88	124.81	0.9	5388 *	NA	ND	2181					
84.26	142.84	1	1968 *	NA	MI	2181					
78.88	140.22	1	2417 *	NA	TX	2181					
81.82	108.41	0.4	1472 *	NA	TX	2181					
78.88	108.32	1.1	6824 *	NA	NY	2181					
86.84	228.28	2	6880 *	NA	ND	2421					
78.88	149.3	0.8	4443 *	NA	TX	2181					
81.82	100.28	0.2	2922 *	NA	AK	2181					
78.88	114.81	0.8	4789 *	NA	KY	2181					
78.88	94.28	1.7	2124 *	NA	GA	2181					
81.82	163.88	1	2428 *	NA	TX	2181					
81.82	205.11	1.7	3221 *	NA	OR	2181					
78.88	206.48	3.7	6222 *	NA	AL	2181					
81.82	81.31	0.2	2825 *	NA	ME	2181					
78.88	106.87	1.8	4478 *	NA	TX	2181					

TEST DO	LAB	TEST	TEST	TEST	AREA/COUNT	BLR	TRM	ENTRY	ENTRY	APR	PLA					
ST. OR	HR	DUR	DL	DL	CD	CD	CD	CD	CD	CD	CD					
CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD					
78.00	388.33	2.9	4443	NA	TX	31901										
TECH TEST NO TESTED VEHICLE TO VERIFY CONCERN CHECK BRAKE LIGHT CAME ON LOWY 14.00 PEDALS PERFORMED DASH TEST 1 14.00 PEDALS DTC PERFORMED, ADDL P1221, PERFORMED P1221 TEST FOR P1221 P1221 MONITOR PID AT					TECH TEST TEST DASH FOUND BAG ACCEL PEDAL SWITCH REPLACED ACCEL PEDAL SWITCH, CLEARING DTC TEST T. DROVE OK		DUTY TEST TRUCK HAS NO ACCELERATION CHECK OUT THE VEHICLE AT STEADY SPEEDS AND AT TIMES THERE IS NO ACCELERATION FROM THE THROTTLE PEDAL		281	USA	132023	1	USA	Y44	PT	011
78.00	387.85	2.7	4384	NA	MI	31801										
TECH TEST VERIFY CHECK CABLE WIRING, CHECKS ON PERFORM DIT P1221 DASH TEST PASS KOEC TEST P1221 KOEC SAU TEST PASS CHECK P1221 DASH TEST P1221 DASH TEST P1221					TECH TEST DASH TEST P1221 DASH TEST P1221 DASH TEST P1221		DUTY TEST VEHICLE WILL NO ACCELERATE		78	USA	138023772	1	USA	Y40	PT	011
78.00	123.06	0.7	1781	NA	PA	31801										
TECH TEST APPROX. CHECK TEST DASH CODE DASH TEST P1221 RESPONSE, CORRECTED. NEED MONITORED AP AND HAS PROG. CONCERN IS VERY INTERMITTENT, COULD NOT GET TO ACT W/ CORRECTED. BREAKOUT BOX TO PGM MONITORED WE P1221 DETERMINE					TECH TEST DASH TEST P1221 DASH TEST P1221 DASH TEST P1221		DUTY TEST NO ACCELERATION CUSTOMER STATE AT TIMES NO ACCEL.		618	USA	118124	2	USA	Y41	PT	011
85.4	383.75	3.1	8703	NA	BC	31801										
TECH TEST REPLACE BAG PEDAL					TECH TEST REPLACE BAG PEDAL		DUTY TEST NO ACCELERATION CUSTOMER STATE AT TIMES NO ACCEL.		694	CAN	487891	2	CAN	Y48	PT	011
81.00	103.37	0.3	3885	NA	NY	31801										
TECH TEST TESTED AND REPLACED SENSOR					TECH TEST TESTED AND REPLACED SENSOR		DUTY TEST NO ACCELERATION CUSTOMER STATE AT TIMES NO ACCEL.		697	USA	114097	2	USA	Y41	PT	011
85.4	126.33	1.3	8880	NA	AL	31801										
TECH TEST 14801 BIC TEST PASS TEST DROVE AND MONITORED FOR AP SENSOR OK @ 47 VOLTS TEST DROVE FOR 15 MIN. SENSOR READING WOULD DROP INTERMITTENTLY REPLACED ACCEL PEDAL ASSEMBLY TEST DROVE AGAIN WORKING OK					TECH TEST 14801 BIC TEST PASS TEST DROVE AND MONITORED FOR AP SENSOR OK @ 47 VOLTS TEST DROVE FOR 15 MIN. SENSOR READING WOULD DROP INTERMITTENTLY REPLACED ACCEL PEDAL ASSEMBLY TEST DROVE AGAIN WORKING OK		DUTY TEST REPAIR VEH HAS NO ACCELERATOR INTERMITTENTLY		78	CAN	440281	2	CAN	Y44	PT	011
78.00	188.88	1.8	3078	NA	MI	31801										
TECH TEST CHECK DTC, PERFORM PIN POINT TEST, NO VOLTAGE TO LOW, CHECKED FOR CHAPPED WIRING, REPLACE PEDAL ASSEM CHECKED AND VERIFIED CONCERN, FOUND THROTTLE PEDAL ASSEMBLY BROKEN, NECESSARY TO RER THROTTLE PEDAL, INSTRUCTED OPERATOR OK AT THE TIME					TECH TEST CHECK DTC, PERFORM PIN POINT TEST, NO VOLTAGE TO LOW, CHECKED FOR CHAPPED WIRING, REPLACE PEDAL ASSEM CHECKED AND VERIFIED CONCERN, FOUND THROTTLE PEDAL ASSEMBLY BROKEN, NECESSARY TO RER THROTTLE PEDAL, INSTRUCTED OPERATOR OK AT THE TIME		DUTY TEST CUSTOMER DASH BL. ON, NO ACCELERATION WHEN PUNING THE ACCELERATOR		405	USA	174028	1	USA	Y44	PT	011
81.00	115.97	0.8	8518	NA	OH	31801										
TECH TEST PUSH BLOWN, RER FUSE & WIRE ACCELERATOR, CHECK CIRCUIT & FOUND SWITCH HAS A BAD SPOT, REPLACE PEDAL & SWITCH ASSY. RE TEST, NO CONCERN					TECH TEST PUSH BLOWN, RER FUSE & WIRE ACCELERATOR, CHECK CIRCUIT & FOUND SWITCH HAS A BAD SPOT, REPLACE PEDAL & SWITCH ASSY. RE TEST, NO CONCERN		DUTY TEST CUSTOMER STATES VEHICLE HAS NO ACCELERATION AT TIMES		383	USA	174012	2	USA	Y44	PT	011
78.00	100.00	1.5	3880	NA	TX	31801										
TECH TEST TRANS NO POWER BL. C. DASH KOEC NO ATC KOEC P1221 P1221 KOEC NO ATC P1221 TEST NORMAL AT IDLE FLUID LEVEL, CORRECT PINPOINT TEST ERRATIC SIGNAL, PROMPT SENSOR REPLACED TP					TECH TEST TRANS NO POWER BL. C. DASH KOEC NO ATC KOEC P1221 P1221 KOEC NO ATC P1221 TEST NORMAL AT IDLE FLUID LEVEL, CORRECT PINPOINT TEST ERRATIC SIGNAL, PROMPT SENSOR REPLACED TP		DUTY TEST VEHICLE HAS NO ACCELERATION		608	USA	182821	2	USA	Y41	PT	011
81.00	224.7	2	3888	NA	AZ	31801										
TECH TEST SENSOR FOR P1221 TEST DASH DASH TEST P1221 DASH TEST P1221					TECH TEST SENSOR FOR P1221 TEST DASH DASH TEST P1221 DASH TEST P1221		DUTY TEST TRANS NOT LIFTHITING AND NO ACCEL LIKE ELECTRICAL WHEN REAL NOT OUTSIDE, SEE RISE NO ACCELERATION		603	USA	171171	2	USA	Y45	PT	011
78.00	371.25	2.4	4028	NA	MI	31801										
TECH TEST DASH TEST DASH TEST KOEC P1221 KOEC PASS, KOEC SWITCHES TEST P1221 P1221 MONITOR AND P1221 SHOWED FAILED P1221 REPLACE ACCELERATOR PEDAL ASSY, CLEAR CODES, RETEST ALL OK WE CLOSED DOWN INTERMAY					TECH TEST DASH TEST DASH TEST KOEC P1221 KOEC PASS, KOEC SWITCHES TEST P1221 P1221 MONITOR AND P1221 SHOWED FAILED P1221 REPLACE ACCELERATOR PEDAL ASSY, CLEAR CODES, RETEST ALL OK WE CLOSED DOWN INTERMAY		DUTY TEST NO ACCELERATION		488	USA	174028	2	USA	Y41	PT	011
84.00	108.00	1.4	8888	NA	OK	31801										
TECH TEST P1221 MONITOR AND P1221 SHOWED FAILED P1221 REPLACE ACCELERATOR PEDAL ASSY, CLEAR CODES, RETEST ALL OK WE CLOSED DOWN INTERMAY					TECH TEST P1221 MONITOR AND P1221 SHOWED FAILED P1221 REPLACE ACCELERATOR PEDAL ASSY, CLEAR CODES, RETEST ALL OK WE CLOSED DOWN INTERMAY		DUTY TEST C & V HAS NO ACCEL		478	USA	132023	2	USA	Y41	PT	011

TOT CO LBR		JUN WASH ST P		MTR C ST OR		DUR C B C		DMLC RCV		CPRC		TECH TKT1		TECH TKT2		CUST TKT		AREA COUNT		SLS DL TMR		ENTRY		CMT VRO		LAWR		TRF					
CO	BY	CD	BY	CD	BY	CD	BY	CD	BY	CD	BY	CD	BY	CD	BY	CD	BY	CD	BY	CD	BY	CD	BY	CD	BY	CD	BY	CD	BY				
78.80	387.50	4.8	7889	*	NA	NY	3181						DID A PERFORM CK AIR AND FUEL SYSTEM HAD 48 PSI ON BOTH CYL HEADS AND 86 WOT HAD 15 PSI ON YLINDS BODY DID ALL NOISE NOISE TESTING HAD OPER FOR R R PEDAL ASBY AND I CODE POSSIBLE ALL THE PM POINT TESTS			TRENT TP PEDAL ASBY ROAD TEST RETEST PASS THERE IS NO OPER FOR R R PEDAL ASBY AND I HAD TWO CLOCK TESTS																	
155.38	367.73	3.3	4483	*	NA	TX	3181						HAD NEW ACE A INTAKE AND STAGE THROTTLE CONTROL ON ROAD TEST CO PERFORMANCE DROPPED NORMAL 8000 CK 2000FF CLEAN FUEL DL, CHECK ENGINE OIL CK INTAKE AIRY CHECKED ON DENNO FUEL INJECTORS CONT DTC			GOODS FUEL INJECTOR INJECTOR TEST AT THE RIGHT HEAD AS FUEL FUEL. PRESS TEST AT THE LEFT HEAD AS FUEL INJECTOR ON DENNO FUEL INJECTOR CONTROL PRESS TEST 1079																	
78.80	164.30	1.2	1180	*	NA	LA	3181						RAN TEST TEST CODES POST PRESS HAD REPORT TEST ON ACCELERATOR PEDAL ASSEMBLY REPLACED ACCELERATOR PEDAL ASSEMBLY WITH TP SENSOR CLEARED CODE ROAD TEST RETEST OK AT THIS TIME																				
81.50	148.00	0.8	3180	*	NA	CO	3181						TJ CI PERFORMANCE DRAG REPORT & REPLACE THROTTLE PEDAL ASBY RETEST OK																				
81.30	308.65	3.4	7883	*	NA	OR	3181						SEK VERIFY CONCERN TEST AND REPEAT CHANGES PASS TEST FOR CLEAN FUEL PRESSURE LEVEL FUEL INJECTOR RESTRICTION FUEL INJECTOR HEAD FUEL PRESSURE AT INJECTOR HEAD FUEL LEFT																				
78.84	377.80	0	2885	*	NA	KY	3181						SEE TEST TEST ORDER ACCELL PEDAL ASSEMBLY REPLACE																				
78.80	181.70	1	8884	*	NA	OK	3181						ERRATIC OPERATION SEC CHECK TEST DIAGNOSIS TEST DRIVE VEHICLE FOR NO ACCELERATION AND FOUND AT THIS UNDER ACCELERATION ENGINE WOULD LOOSE POWER LOW POWER CK FUEL CONTAMINATION, CK ENGINE OIL, CK INTAKE AND EXHAUST RESTRICTION, CK																				
81.50	349.80	4.1	6180	*	NA	NC	3181						FOR AIR IN DI																				
81.50	186.74	1.6	8888	*	NA	VA	3181						SEK TEST DRIVE COULEN NOT SUP SEC TEST NOISE PASS BU BLEZ TEST PAS NO NOISEY FALLT NOISE PASS BLM PW MONITOR TEST ON IDLE SW AND TP FOUND OUT OF WIND ORDER NEW ACCEL PEDAL ASSEMBLY																				
78.80	362.00	0.4	6986	*	NA	VA	3181						CHECK WATER REPLACE THROTTLE ASSEMBLY																				
80.81	399.00	4.3	3015	*	NA	TX	3181						WASER ASBY DRIVE TEST DRAG REPLACED ACCELERATOR PEDAL ASSEMBLY																				
78.80	149.81	1	8888	*	NA	TX	3181						REPLACED PUL SENSOR																				

TRUCK	ST. OR	HR	DUR.	CL	CH.	NOV.	CD	TRUCK	TRUCK	TRUCK	AREA	COUNT	BLA.	DL.	DOM.	ENTRY	CRD.	VFR.	AWB.	ML.	VRL.	TR.	FLA.	
CDT	CDT	E	D	D	D	D	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	
7808	338.81	3.0	1108	*	NA	CO	31801	WAS VERIFY CONCERN, PERFORMANCE DRIVE CODE P0228, P0211, PERFORM TEST. RUR GAS PEDAL, VERIFY REPAIR RUR GAS TESTS ONE FIRST & FUEL PERFORM TEST FE 1 NO FE 2 Y ES FE 3 YES REPLACED ACCELERATOR PEDAL ANY 48 CODES NOT OPERATE PROPERLY CLEARED CODES & RETEST P1111 ROAD		CK ENGINE WONT ACCELERATE	208	USA	18007	1	USA	*	V61	FT	811					
8084	141.86	1	2648	*	NA	TX	31801	TESTED		WONT ACC. AT TIMES	812	USA	18043	812	USA	*	V64	FT	811					
7808	212.8	2	7772	*	NA	CA	31801	RUN DRIVE, DRIFT TUNING TEST MONITOR REPLACE THROTTLE ASSEMBLY, CHECK ALL ADJUST		REPORTS WONT WORK ACCEL PUSH ON ACCL PEDAL, AND ENGINE STAYS AT IDLE	800	USA	17249	1	USA	*	V61	FT	811					
8122	150.83	1.3	28218	*	NA	R	31801	ENGINE PERFORMANCE DIAGNOSTIC Y X, X3 TURBO ENGINE CODE P1111, KOEC P0221, PID MONITORING AND AP INCONSISTENT, CHECKED PROXIMITY SWITCH, OK, PPTTD AP MALFUNCTION REPLACED AP AND CLEARED CODES	PID MONITOR PDS OK BASIC ENGINE CC 42	WONT ACC. AT TIMES CR ROR	84PL	218	USA	14170	84	USA	*	V61	FT	811				
8084	184.88	1.4	28218	*	NA	R	31801	ALSO TESTS CODE P1111, KOEC P022 P0221, KOEC P1111, PERFORM TEST PID MONITOR, REPLACE ACCEL. PED. ASBY AND RETEST, SAME ISSUE, CC 42		INTERIM WONT ACC. CR NOT	84PL	218	USA	14170	1	USA	*	V61	FT	811				
7808	471.08	1.8	28218	*	NA	R	31801	DIAGNOSTIC RUNNING, CONSULT, END TESTED, PERFORM TESTED CODE P0221 MONITOR TESTED, REPLACED PEDAL, ASBY AND RETESTED, OK BASIC ISSUE CODE		WONT ACCELERATE NOT	84PL	218	USA	14170	2	USA	*	V62	FT	811				
8122	183.41	1.3	7880	*	NA	PA	31801	SEC TEST PERFORM TEST PID MONITOR REPLACED SENSOR		ENGINE WONT BUILD UP AT TIMES WHEN ACCELERATING	177	USA	11887	84	USA	*	V60	FT	811					
7808	137.85	0.8	3485	*	NA	PA	31801	PER ACCELERATOR POSITION SENSOR WAS CHECKED & COMPRESSED ENGINE WONT COME OFF IDLE, VISUALLY INSPECTED ACCELERATOR PEDAL, & SENSOR, RAN SEC. SELF TEST, COND. P0222, P1140, P0221, P0340	WY CODE P0222 NO VOLTAGE CLT OF SENSOR, REPLACED SENSOR, CLEARED CODES & TEST DROVE OK	TOWED IN WONT RUN IT, JUST, CLRE	216	USA	118214	1	USA	*	V60	FT	811					
7808	134.51	0.8	3485	*	NA	PA	31801	RUN DRIVE, CODE NO CODES, REPLACE ACCEL. PEDAL		VEHICLE WONT MOVE WHEN DEPRESSING ACCEL.	228	USA	118279	84	USA	*	V61	FT	811					
7808	193.31	1.7	2738	*	NA	M	31801	REPLACE ACCEL. PEDAL, AIRBAG ROAD TEST AND CRD SERV SYSTEM N KOEC P0221, KOEC P0221, N MON THIS PERFORMED EXTENSIVE PERFORM TEST AND DRIVE		VEHICLE STARTS BUT WHEN YOU PUSH ON THE ACCELERATOR VEHICLE WONT MOVE	704	USA	14848	1	USA	*	V61	FT	811					
7808	140.93	0.8	31	*	NA	VA	31801	TEST DRIVE, WONT NO MORE TEST, WSS CODE P0222, P0221, P0221, PERFORM TEST AND TP SENSOR, BAD, REPLACE PADAL, ASBY TEST, DRIVE OK		TOWED IN, CAR WONT MOVE PAST MIDLE, ADVISE	708	USA	117887	2	USA	*	V63	FT	811					
8122	289.34	2.3	2038	*	NA	NY	31801	TP CODES SHORTED ACCEL. PEDAL, ELECTRONIC TRANSMISSION DIAGNOSIS DRIVE OK		TROUBLE FOUND FROM END TO BCL, INTERMITTENT WONT MOVE IN GEAR AT IDLE, PRESS TO ACCEL, ENGINE DOESNT EVEN REV	708	USA	148011	208	CAN	*	V60	FT	811					
7808	048.18	0.8	8430	*	NA	UT	31801	NOTHING FOUND, CODE PRESENT, FREE GO TO PPT POLARIS SW SWITCH DEFECTIVE, NOT ALLOWING TP TO INPUT TO PCM, REPLACE PEDAL, RETEST, OK, DR		VEHICLE HAS NO THROTTLE YOU CAN START IT BUT IT WONT MOVE	801	USA	148011	812	CAN	*	V61	FT	811					
8122	182.88	0.8	8021	*	NA		31801	WAS, PEDAL, DEFECTIVE, RAN, R FUEL PEDAL, CUSTOMER HAD CONCERN IN EARLIER ABOUT THIS CONCERN, PART WAS ORDERED.		C @ VEHICLE WONT MOVE WHEN PRESS IT GEAR, BAD PEDAL, HUNG, NOTE PARTS, ORDERED, REPAIRING, MILES	804		147018	812	USA	*	V61	FT	811					

TOT CO LBR		SU REGN ST P		MTR C BY BR		HR CLR C E C		CM C NOV CPNC		TECH TXT		TECH TXT2		CUST TXT		AREA	COUNT	PLS DL	YOM	CHTRY	ORTRV	WHS	WLT	PLA
DBT	DSS	S	D	D	D	CO	CO	CO	CO	CO	CO	CO	CO	CO	CO	CO	CO	CO	CO	CO	CO	CO	CO	CO
91.4	10.42	2.89	134	*	NA	AS	31801			3011 AS CHECK OUT HISS TEST FOR CORRECT ROAD TEST HISS ON PRO DATA MONITOR AP VOLTAGE TO LOW AT IDLE SUS REPLACE FUEL PEDAL ASSEMBLY ROAD TEST OK				DID REPAIR FOR FUEL PUMP WILL NOT INCREASE RPM'S WHEN STEERING ON IT	48	USA	148120	204	CAN	*	Y04	PT	011	
91.42	10.18	1.1	200	*	NA	CA	31801			PERFORMANCE DASHBOARDS 7.5 IN THROTTLE SENSOR DIAG				CUSTOMER STATES WILL ONLY 2 OF ENTER	69	USA	17198	202	USA	*	Y03	PT	011	
91.42	117.50	3.8	4029	*	NA	ME	31801			PERFORMANCE TESTED, REPLACED ACCEL PEDAL ASSEMBLY, REGISTERED OK 7/29				CUSTOMER STATES WHEN COMING TO STOP VEH. WILL CUNT, CUNT, APPLIED GAS, ENGINE DID NOT REV AND ENGINE STAYED THE SAME. CUSTOMER STATES NO FORWARD MOVEMENT WHEN THROTTLE IS PRESSED	48	USA	40227	272	CAN	*	Y02	PT	011	
101.42	205.01	1.7	2051	*	NA	OR	31801			FAILED RPM AND THROTTLE PEDAL HISS (CLICK TEST) DIAGNOSIS VERIFY AT TIMES ACCELERATOR PEDAL DOES NOT RESPOND HISS TEST QUANTITY OF P0221 CODE PRESENT PRIOR TO TEST INTERRUPTED - FAILURE IN PEDAL ASSEMBLY REPLACE PEDAL ASSEMBLY DUE TO OPEN CIRCUITING VERIFY REPAIR				CUSTOMER SAYS AT TIMES WHEN YOU COME TO A STOP AND TRY TO ACCELERATE, THE VEHICLE DOES NOT MOVE AHEAD LIKE THE PEDAL SEEM WHEN BEING PRESSED	68	USA	17022	272	USA	*	Y04	PT	011	
91.42	126.52	0.8	2058	*	NA	TX	31801							REPAIR	254	USA	40204	284	CAN	*	Y01	PT	011	
79.42	207.28	7.	724	*	NA	CA	31801			THE VOLTAGE CONFIRMED HESITATION SOLE ON ACCEL, GAS PEDAL ASSEMBLY, FAULT CHASING, DISCONNECT THE VOLTAGE, REPLACED THROTTLE PEDAL PERFORM PERFORMANCE OPERATIONS STEPS 1 THRU 14 ON RETROVE CODE HAD CODE P0222 AND P0221 FOUND INTERMITTENT OPEN IN REPLACE GAS PEDAL ASSEMBLY THAT COME WITH SOLE VALIDATION SWITCH ROAD TEST HISSED				WILL GO TO IDLE WHEN ON ACCELERATOR	70	USA	17200	178A	*	Y04	PT	011		
91.42	200.01	4.8	421	*	NA	FL	31801			DEFECTIVE WHEN PEDAL SENSOR ENGINE PERFORMANCE DIAGNOSTICS 7.5 IN THROTTLE SENSOR HISS HISS TEST PEDAL TEST THE MONITOR AND ENGINE PEDAL HISS IS NOT RESPONDING INTERMITTENTLY REPLACED PEDAL SWITCH ASSEMBLY AND RETURN TO VERIFY REPAIR OK IF SENSOR PEDAL ASSEMBLY VERIFY CORRECTION NO ACCEL, CK ENGINE LIGHT ON CK ENG SYSTEM RECEIVED CODE P0221 IN MEMORY AS WELL AS ROAD ENG. TEST	IN CC TECH NO			CUSTOMER STATES TRUCK DOES NOT MOVE AND IT FEELS LIKE IT STALLING	84	USA	12445	218A	2	Y01	PT	011		
79.42	247.78	2.8	2022	*	NA	TX	31801			DEFECTIVE WHEN PEDAL SENSOR ENGINE PERFORMANCE DIAGNOSTICS 7.5 IN THROTTLE SENSOR HISS HISS TEST PEDAL TEST THE MONITOR AND ENGINE PEDAL HISS IS NOT RESPONDING INTERMITTENTLY REPLACED PEDAL SWITCH ASSEMBLY AND RETURN TO VERIFY REPAIR OK IF SENSOR PEDAL ASSEMBLY VERIFY CORRECTION NO ACCEL, CK ENGINE LIGHT ON CK ENG SYSTEM RECEIVED CODE P0221 IN MEMORY AS WELL AS ROAD ENG. TEST				CHECK FOR FUEL NOT GOING WHEN AT ACCELERATOR	84	USA	12052	218A	*	Y01	PT	011		
91.42	100.97	1.1	2054	*	NA	UT	31801			DEFECTIVE WHEN PEDAL SENSOR ENGINE PERFORMANCE DIAGNOSTICS 7.5 IN THROTTLE SENSOR HISS HISS TEST PEDAL TEST THE MONITOR AND ENGINE PEDAL HISS IS NOT RESPONDING INTERMITTENTLY REPLACED PEDAL SWITCH ASSEMBLY AND RETURN TO VERIFY REPAIR OK IF SENSOR PEDAL ASSEMBLY VERIFY CORRECTION NO ACCEL, CK ENGINE LIGHT ON CK ENG SYSTEM RECEIVED CODE P0221 IN MEMORY AS WELL AS ROAD ENG. TEST				CUSTOMER STATES VEH SHAKES AT IDLE WHEN TRYING TO ACCELERATE. CHECK AND ADJUST	80	USA	14172	204	USA	*	Y01	PT	011	
79.42	127.91	0.8	48	*	NA	VA	31801			DEFECTIVE WHEN PEDAL SENSOR ENGINE PERFORMANCE DIAGNOSTICS 7.5 IN THROTTLE SENSOR HISS HISS TEST PEDAL TEST THE MONITOR AND ENGINE PEDAL HISS IS NOT RESPONDING INTERMITTENTLY REPLACED PEDAL SWITCH ASSEMBLY AND RETURN TO VERIFY REPAIR OK IF SENSOR PEDAL ASSEMBLY VERIFY CORRECTION NO ACCEL, CK ENGINE LIGHT ON CK ENG SYSTEM RECEIVED CODE P0221 IN MEMORY AS WELL AS ROAD ENG. TEST				WHEN YOU PRESSED THE GAS PEDAL THE ENGINE DOES NOT BUME ANY MORE RPM'S FOR THROTTLE CABLE WORKY ADJUSTMENT REPORT	70	USA	14708	218A	*	Y01	PT	011		
91.42	104.08	1.8	4082	*	NA	SE	31801			DEFECTIVE WHEN PEDAL SENSOR ENGINE PERFORMANCE DIAGNOSTICS 7.5 IN THROTTLE SENSOR HISS HISS TEST PEDAL TEST THE MONITOR AND ENGINE PEDAL HISS IS NOT RESPONDING INTERMITTENTLY REPLACED PEDAL SWITCH ASSEMBLY AND RETURN TO VERIFY REPAIR OK IF SENSOR PEDAL ASSEMBLY VERIFY CORRECTION NO ACCEL, CK ENGINE LIGHT ON CK ENG SYSTEM RECEIVED CODE P0221 IN MEMORY AS WELL AS ROAD ENG. TEST				CUSTOMER STATES WHEN COMING TO STOP VEH. WILL CUNT, CUNT, APPLIED GAS, ENGINE DID NOT REV AND ENGINE STAYED THE SAME. CUSTOMER STATES NO FORWARD MOVEMENT WHEN THROTTLE IS PRESSED	208	CAN	40207	204	CAN	*	Y01	PT	011	
91.42	104.08	1.8	1728	*	NA	AZ	31801			DEFECTIVE WHEN PEDAL SENSOR ENGINE PERFORMANCE DIAGNOSTICS 7.5 IN THROTTLE SENSOR HISS HISS TEST PEDAL TEST THE MONITOR AND ENGINE PEDAL HISS IS NOT RESPONDING INTERMITTENTLY REPLACED PEDAL SWITCH ASSEMBLY AND RETURN TO VERIFY REPAIR OK IF SENSOR PEDAL ASSEMBLY VERIFY CORRECTION NO ACCEL, CK ENGINE LIGHT ON CK ENG SYSTEM RECEIVED CODE P0221 IN MEMORY AS WELL AS ROAD ENG. TEST				AT TIMES NO THROTTLE ON ACCEL CUSTOMER STATES THAT ALL NOT CHANGE WHEN PUSING ACCEL WHEN COULD DOWN RPM AFTER WEAKEN UP	80	USA	17117	204	USA	*	Y01	PT	011	
91.42	200.01	2.8	402	*	NA	NY	31801			DEFECTIVE WHEN PEDAL SENSOR ENGINE PERFORMANCE DIAGNOSTICS 7.5 IN THROTTLE SENSOR HISS HISS TEST PEDAL TEST THE MONITOR AND ENGINE PEDAL HISS IS NOT RESPONDING INTERMITTENTLY REPLACED PEDAL SWITCH ASSEMBLY AND RETURN TO VERIFY REPAIR OK IF SENSOR PEDAL ASSEMBLY VERIFY CORRECTION NO ACCEL, CK ENGINE LIGHT ON CK ENG SYSTEM RECEIVED CODE P0221 IN MEMORY AS WELL AS ROAD ENG. TEST				WHEN ACCEL. APPLIED VEHICLE WOULD NOT MOVE	204	USA	10250	204	USA	*	Y04	PT	011	
79.42	100.28	0.4	4082	*	NA	TX	31801			DEFECTIVE WHEN PEDAL SENSOR ENGINE PERFORMANCE DIAGNOSTICS 7.5 IN THROTTLE SENSOR HISS HISS TEST PEDAL TEST THE MONITOR AND ENGINE PEDAL HISS IS NOT RESPONDING INTERMITTENTLY REPLACED PEDAL SWITCH ASSEMBLY AND RETURN TO VERIFY REPAIR OK IF SENSOR PEDAL ASSEMBLY VERIFY CORRECTION NO ACCEL, CK ENGINE LIGHT ON CK ENG SYSTEM RECEIVED CODE P0221 IN MEMORY AS WELL AS ROAD ENG. TEST					80	USA	10721	218A	*	Y01	PT	011		

TOT CD LBR	DLX	SU	RESI	ST	P	MPAC	TECH	DATE	GMT	TXI	AREA	COUNT	SLA	DL	TWR	ENTRY	ONT	VPR	AMB	VRT	TPL		
MTK_C ST BR	FR	DLR	C	C	ON	C	REV	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD		
ONT	ONE	S	D	D	D	D	D	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD		
78.06	278.79	3.8	6721	MA	TX	31801	ENGINE DIAGNOSTIC TEST PROCEDURES CHECKED THROTTLE POSITION SWIRL CHECKED WIRING FROM TP TO PCAM WIRING REPLACED				530	USA	12709	072	USA		140	PT	071				
81.08	127.4	1.1	2413	MA	TX	31801	ACCCELERATOR PEDAL ASSEMBLY LAMP FAILING THROTTLE POSITION SENSOR CC-4LIFER VIEWED CONSOLE PERFORMED PERFORMANCE DIAL. 1Y PERFORMED VMAH. INSPECTION FUEL. 2.5L PERFORMED CLEAN FUEL PUMP SOURCE ENGINE OIL LEVEL. PUMP REPLACED	RESTRICTION FINE SPIDER FINE OIL DEMAND TEST PUMP SPONTANEOUS CONTINUOUS CODES PERFORMED PERFORM REPORT TEST REPORT TO PHASED TP SENSOR REPLACED ACCELERATOR PEDAL			817	USA	128913	073	USA		141	PT	071				
80.84	141.48	1.3	4482	MA	TX	31801	READ THE DIAGNOSTIC CODES AND RUN FOR POINT TEST TRACE WIRING HAD TO REPLACE PEDAL ASSEMBLY. OPEN CIRCUIT				68	USA	128181	1	USA		144	PT	071				
81.51	130.32	1.6	6002	MA	TX	31801	DO SYMPTOM DIAGNOSTIC. RUN CLICK TESTS P0221, P0222 DO PERFORM TESTS MONITOR P022. TEST AP CIRCUITS. PER ACCEL PEDAL. INSTALL NEW PEDAL CLEAR DENT DRIVE AND RETEST				70	USA	128920	084	CAN		145	PT	071				
87.05	208.44	1.0	5837	MA	TX	31801	TEAM CONFIRM CONCERN. PERFORMED TESTS 1 IS. PERFORM TESTS FOR CODES P0128/P0201 TP VOLTAGE WOULD DROP OFF AT 1470 RPM SOMETHING WOULD SPRAY ELECTRICAL TP ASSEMBLY. REPLACED PEDAL ASSEMBLY. CLEAR CODES & TP PEDAL ASSEMBLY. RUN PERFORMANCE SHEET DIAGNOSTIC THE ACCEL PEDAL ASSEMBLY TO BE DEFECTIVE. THEN REPLACED PEDAL ASSEMBLY AND TEST DRIVE. ALL OK AT THIS TIME QUALITY CONTROL BY KELLY DAVIS	SEC PASS. TEST DROVE OK NOW.			700	CAN	128945	084	CAN		147	PT	088				
78.06	217.38	4.2	2417	MA	TX	31801	TEAM CONFIRM CONCERN. PERFORMED TESTS 1 IS. PERFORM TESTS FOR CODES P0128/P0201 TP VOLTAGE WOULD DROP OFF AT 1470 RPM SOMETHING WOULD SPRAY ELECTRICAL TP ASSEMBLY. REPLACED PEDAL ASSEMBLY. CLEAR CODES & TP PEDAL ASSEMBLY. RUN PERFORMANCE SHEET DIAGNOSTIC THE ACCEL PEDAL ASSEMBLY TO BE DEFECTIVE. THEN REPLACED PEDAL ASSEMBLY AND TEST DRIVE. ALL OK AT THIS TIME QUALITY CONTROL BY KELLY DAVIS				817	USA	128918	1	USA		148	PT	071				
81.51	128.31	0.8	2399	MA	TX	31801	RAN MSB DIAGNOSTIC TO PULL CODES. WENT TO PERFORM TESTS. FOUND PEDAL ASSEMBLY. REPLACED PEDAL ASSEMBLY TEST PERFORMED SEC FOR POINT TEST FOUND THE ACCEL PEDAL OPEN REPLACED ACCEL PEDAL. RECEIVED CLEARING CODES ON AT THIS TIME RAN PERFORMANCE SHEET PAGES 1 & PP TEST FOR CODE P0221 IN TIME TO REPLACE PEDAL ASSEMBLY						818	USA	128922	072	USA		149	PT	071		
78.06	134.7	1	6000	MA	TX	31801	REPLACED ACCEL PEDAL. RECEIVED CLEARING CODES ON AT THIS TIME RAN PERFORMANCE SHEET PAGES 1 & PP TEST FOR CODE P0221 IN TIME TO REPLACE PEDAL ASSEMBLY						818	USA	128948	1	USA		144	PT	071		
85.04	126.14	1.1	8877	MA	OK	31801	REPLACED ACCEL PEDAL. RECEIVED CLEARING CODES ON AT THIS TIME RAN PERFORMANCE SHEET PAGES 1 & PP TEST FOR CODE P0221 IN TIME TO REPLACE PEDAL ASSEMBLY						820	USA	128950	084	USA		144	PT	071		
87.05	128.08	0.8	8887	MA	OK	31801	REPLACED ACCEL PEDAL. RECEIVED CLEARING CODES ON AT THIS TIME RAN PERFORMANCE SHEET PAGES 1 & PP TEST FOR CODE P0221 IN TIME TO REPLACE PEDAL ASSEMBLY						820	CAN	128950	084	CAN		144	PT	071		
78.06	132.7	0.8	2843	MA	MA	31801	REPLACED ACCEL PEDAL. RECEIVED CLEARING CODES ON AT THIS TIME RAN PERFORMANCE SHEET PAGES 1 & PP TEST FOR CODE P0221 IN TIME TO REPLACE PEDAL ASSEMBLY						820	USA	127990	1	USA		144	PT	071		
141.22	234.99	1.0	1289	MA	FL	31801	PERFORMED CONCERN PERFORMED ENGINE PERFORMANCE DIAL TEST 1 IS REPLACED PEDAL ASSEMBLY. REPLACED BLU FUEL AND RELAY CONNECTED						820	USA	128912	2	USA		141	PT	071		
87.05	237.25	2.2	3284	MA	MA	31801	TEAM CONFIRM CONCERN. PERFORMED TESTS 1 IS. PERFORM TESTS FOR CODES P0128/P0201 TP VOLTAGE WOULD DROP OFF AT 1470 RPM SOMETHING WOULD SPRAY ELECTRICAL TP ASSEMBLY. REPLACED PEDAL ASSEMBLY. CLEAR CODES & TP PEDAL ASSEMBLY. RUN PERFORMANCE SHEET DIAGNOSTIC THE ACCEL PEDAL ASSEMBLY TO BE DEFECTIVE. THEN REPLACED PEDAL ASSEMBLY AND TEST DRIVE. ALL OK AT THIS TIME QUALITY CONTROL BY KELLY DAVIS	TEAM CONFIRM CONCERN. PERFORMED TESTS 1 IS. PERFORM TESTS FOR CODES P0128/P0201 TP VOLTAGE WOULD DROP OFF AT 1470 RPM SOMETHING WOULD SPRAY ELECTRICAL TP ASSEMBLY. REPLACED PEDAL ASSEMBLY. CLEAR CODES & TP PEDAL ASSEMBLY. RUN PERFORMANCE SHEET DIAGNOSTIC THE ACCEL PEDAL ASSEMBLY TO BE DEFECTIVE. THEN REPLACED PEDAL ASSEMBLY AND TEST DRIVE. ALL OK AT THIS TIME QUALITY CONTROL BY KELLY DAVIS					818	USA	127992	084	USA		141	PT	071		

TRC	COL	ST	CR	HR	DLN	CLC	ON	C	NOV	CPNC	TECH	TEXT	TECH	TEXT	CUST	TEXT	AREA	COUNT	CLS	D	DIR	C	CHRY	GRV	V	YR	FLA
001	002	003	004	005	006	007	008	009	010	011	012	013	014	015	016	017	018	019	020	021	022	023	024	025	026	027	028
78.05	380.72	6.2	6017		NA	TX					31801	WAS ENGINE WARM CAME TO VERIFY CONCERN PERFORM CRUEL DRIV PERFORMANCE STEPS 1 TO PERFORMED CODE P0001 PERFORMED MONITOR TEST DRIVE 400 MPH AND	OK AT 600 POUND TP VOLTAGE TO SEE VERIFY AT THIS PERFORM PERFORM TEST REPLACE SPD THROTTLE PEDAL ASSEMBLY RETEST OK TEST DRIVE OK	VEHICLE WHEN ACCELERATING AT TIMES WILL NOT HAVE ANY THROTTLE RESPONSE	201	USA	19820	272	USA		144	F7	811				
80.01	144.08	8.9	6295		NA	ID					31801	THROTTLE PEDAL ASSEMBLY NIP ENGINE PERFORMANCE DIAGNOSTICS 7.3L DI TURBO ENGINE DIAG NOOD TEST, NOOD INJECTION ELECTRICAL SELF TEST, INTAKE RESTRICTION CHECK, REPLACE THROTTLE PEDAL ASSEMBLY		CUST STATES THERE IS NO THROTTLE RESPONSE AT TIMES NO THROTTLE RESPONSE FROM PEDAL	200	USA	19820	272	USA		144	F7	811				
78.05	104.04	3.3	1628		NA	SD					31801	REPLACE THROTTLE PEDAL ASSEMBLY PERFORM TEST AND FOUND CODES P0001 AND P0021 REPLACE THROTTLE PEDAL ASSEMBLY		WAS NO ON INTERMITTENT THROTTLE RESPONSE DUE LACK OF THROTTLE RESPONSE WAS TO PUSH IT DOWN OR OF DISTANCE	200	USA	19820	272	USA		144	F7	811				
80.04	162.04	1.8	7188		NA	ME					31801	REMOVED AND REPLACED THROTTLE PEDAL ASSEMBLY		CUSTOMER STATES NO THROTTLE RESPONSE	200	USA	19820	272	USA		144	F7	811				
87.05	208.05	1.8	4834		NA	MI					31801	NO THROTTLE RESPONSE SEC CHECK TESTS DIAGNOSTICS NO THROTTLE RESPONSE		CUSTOMER STATES NO THROTTLE RESPONSE	200	USA	19820	272	USA		144	F7	811				
78.08	154.08	1	2888		NA	AL					31801	NO THROTTLE RESPONSE		CUSTOMER STATES NO THROTTLE RESPONSE	200	USA	19820	272	USA		144	F7	811				
75.08	150.08	0.6	7050		NA	CA					31801	NO THROTTLE RESPONSE		CUSTOMER STATES NO THROTTLE RESPONSE	200	USA	19820	272	USA		144	F7	811				
80.01	228.1	1.8	7743		NA	CA					31801	CCC TEST, MONITOR RECORD ROAD TEST, FOUND NO PERFORM PIN POINT TEST PERFORM TEST AND FOUND CODES P0001 AND P0021 REPLACE THROTTLE PEDAL ASSEMBLY PERFORM MONITOR TEST DRIVE 400 MPH AND TEST AND FOUND CODE P0001 INSPECT AND REPLACE THROTTLE PEDAL ASSEMBLY TEST AND DRIVE OK		CUSTOMER STATES THAT WHEN AT A STEADY SPEED AND TRY TO ACCEL THE THERE IS NO THROTTLE RESPONSE AND OCCURS INTERMITTENTLY	200	USA	19820	272	USA		144	F7	811				
81.03	115.03	0.7	7188		NA	NE					31801	NO THROTTLE RESPONSE		HARD START WHEN COLD THROTTLE RESPONSE SLOW	200	USA	19820	272	USA		144	F7	811				
78.08	130.08	1	3234		NA	NY					31801	CCC AND PIN POINT TEST FOUND DEFECTIVE ACCELERATOR SENSOR ASBY		THROTTLE AND THROTTLE RESPONSE	210	USA	19820	272	USA		144	F7	811				
81.05	287.05	3.9	8054		NA	OK					31801	ENGINE PERFORMANCE DIAGNOSTICS 7.3L DI TURBO ENGINE DIAG		ON INTERMITTENTLY HAS NO THROTTLE RESPONSE. CAN HOLD PEDAL TO FLOOR AND ENGINE DOES MOVE NO DRIV RESPONSE AT ALL LET UP THEN BACK IT WILL TAKE OFF RESPON FOR MIL ON NO THROTTLE RESPONSE WAS DIAG, REPLACE ACCEL. PEDAL	200	USA	19820	272	USA		144	F7	811				
80.05	170.05	2.3	8197		NA	OH					31801	WAS DIAG, REPLACE ACCELERATOR PEDAL, RETEST		INTERMITTENTLY, NO THROTTLE RESPONSE	200	CAN	48000	1	CAN		140	F7	800				
78.08	148.08	1	7798		NA	CA					31801	CHECKED AND FOUND THE THROTTLE PEDAL NOT OPERATE AND PROPERLY, REPLACED THE THROTTLE PEDAL AND R EBOOKED, OK TEST			200	USA	19820	272	USA		144	F7	811				
80.01	278.01	3	478		NA	GA					31801	WAS OF PERFORM PERFORMANCE DIAG WAS TESTS 14 PERFORM CODE P0001 PERFORM PERFORM TEST REPLACE THROTTLE PEDAL ASSEMBLY RETEST TEST RETEST OK		CUSTOMER SAYS THAT VEH HAS NO THROTTLE RESPONSE. INTERM	770	USA	19140	21	USA		140	F7	811				
81.02	184	1.5	482		NA	GA					31801	ACCELERATOR PEDAL FAILED ENGINE PERFORMANCE DIAGNOSTICS 7.3L DI TURBO ENGINE DIAG ACCELERATOR PEDAL ASSEMBLY FULLY TEST DRIVE AND VERIFIED NO THROTTLE RESPONSE SOMETIMES, CCC TESTED, PERFORMED CODE P0001, FOLLOWED PERFORM TEST, AND		CX FOR VEH HAS NO THROTTLE RESPONSE	770	USA	19140	21	USA		140	F7	811				
80.01	211.01	2.2	368		NA	AR					31801	REPLACE ACCEL PEDAL, RETEST		THERE WAS NO THROTTLE RESPONSE WHEN ACCELERATOR PEDAL WAS DEPRESSED.	671	USA	19820	272	USA		144	F7	811				

TOT. COST	YR	MO	DAY	TIME	ST. P.	TECH	TEST	TEST	TEST	AREA	COUNT	BLK	CL	COL	CWRY	INT	VPS	VC	WV	FLA
MTPLG	ST	BR	HR	DA	BLK	CL	COL	OPSC	TECH	TEST	CD	STY	CD	BLK	CD	CD	CD	CD	CD	CD
78.00	2008	03	23	2008	NA	NY	31801	THRTLE	1 VERIFIED CONCERN CHECKED THROTTLE RESPONSE ACCELERATOR PEDAL SCANNED FOR CODES PERFORMED PERFORMANCE DIAGNOSTIC	TECH TEST										
									CUSTOMER STATES THROTTLE RESPONSE PROBLEMS SOMETIMES NO THROTTLE		018	USA	11300	3	USA		141	FT	011	
41.00	178.00	1.4	095	NA	FL	31801	THRTLE	SPROG CODES 26 M O 2140T VERIFY CONCERN REAR CODES FOR ACCEL PEDAL IN CODE AND DATA MONITOR FOUND LOW	NO THROTTLE RESPONSE ON FOOT PED		200	USA	12110	004	USA		141	FT	011	
									REPLACED TP SENSOR AND PEDAL ASSEMBLY		048	USA	07040	23	USA		144	FT	011	
75.00	180.04	0.8	30	NA	VA	31801	THRTLE	RUN ISC TEST NO CODES. REPLACED ACCELERATOR PEDAL AND SENSOR ROAD TESTED IN USE NO CODES WERE FOUND IN THE REPAIR PIN POINT TEST AND MONITORED SPEED CHECKED. CIRCUITS NO PROBLEMS FOUND AT THE TIME THE PEDAL IS BROKEN OFF OF AND REMOVED AND	WELK WILL DIE BUT HAS NO THROTTLE RESPONSE		040	USA	07340	2	USA		141	FT	011	
									REPLACED THE PEDAL	ALARM DETECTED ON DR	000	USA	11300	1	USA		144	FT	011	
81.00	120.4	8.6	071	NA	CA	31801	THRTLE	TP SENSOR BAD BODY CHASSIS ELECTRICAL TEST	CUSTOMER STATES OK FOR NO THROTTLE RESPONSE AT TIMES		070	USA	17100	000	USA		144	FT	011	
									ACCELERATOR PEDAL AND SENSOR WERE FOUND IN THE REPAIR PIN POINT TEST AND MONITORED SPEED CHECKED. CIRCUITS NO PROBLEMS FOUND AT THE TIME THE PEDAL IS BROKEN OFF OF AND REMOVED AND		000	USA	11300	1	USA		144	FT	011	
81.00	118.20	0.4	001	NA	CA	31801	THRTLE	TP SENSOR BAD BODY CHASSIS ELECTRICAL TEST	THERE IS NO THROTTLE RESPONSE		000	USA	11300	1	USA		141	FT	011	
									PERFORMED DIAGNOSTIC TEST FOR THROTTLE RESPONSE MONITOR TP PEDAL PEDAL NOT BEING SHUT IN PEDAL LOCK OK BY RELAY		001	USA	10200	070	USA		141	FT	011	
81.00	184.10	1.2	001	NA	TX	31801	THRTLE	SPROG CODES 26 M O 2140T VERIFY CONCERN REAR CODES FOR ACCEL PEDAL IN CODE AND DATA MONITOR FOUND LOW	CUSTOMER STATES 7700X HAS NO THROTTLE RESPONSE ENGINE RUNNING		001	USA	10200	070	USA		141	FT	011	
									SENSOR REPLACED TP SENSOR SYSTEM		000	USA	10200	070	USA		142	FT	011	
81.00	200.70	1.7	000	NA	CA	31801	THRTLE	CK ONLY FOUND THE VEHICLE HAS SET CODES CK ALL ENGINE RUNNING CODES AND FOUND NOTHING ROAD TESTED THE VEHICLE AND FOUND INSTALLED THE PEDAL AND RETESTED AND ROAD	CUSTOMER STATES AT TIMES WHEN THROTTLE IS DEPRESSSED VEHICLE WILL HAVE NO THROTTLE RESPONSE CHECK AND ADJUST		000	USA	10200	070	USA		142	FT	011	
									TESTED		000	USA	10200	070	USA		142	FT	011	
78.00	60.4	0.0	000	NA	OH	31801	THRTLE	DO 7.2 ENGINE PERFORMANCE SHEET DO PED & MONITOR OF CK REP OK FOUND AP ERRATIC AT CK AT TEST 14001 HARMON WHERE IT NEEDS 14001 HARMON NO SHORTS OR OPEN CIRCUIT	NO THROTTLE RESPONSE		000	USA	10200	1	USA		140	FT	011	
									REAR BRACKET PEDAL ASSEMBLY		000	USA	10200	070	USA		141	FT	011	
80.4	100.00	1.1	0027	NA	MS	31801	THRTLE	DATA SERIAL SYSTEM AND TRACK NO FILED THROTTLE SERVICE	REPAIR NO THROTTLE RESPONSE		000	USA	10200	070	USA		141	FT	011	
									CHECK SER POWERTRAIN FOR DTCS CHECK FOR COM CODES PASS CHECK ACCEL ON SER AND PASS CHECK PED DATA CHECK AP WAP PL AND R AP SER ROAD TRACKING SER AND PED OK		000	USA	17100	004	USA		140	FT	011	
									INTERMITT ON ACCEL FROM STOP NO THROTTLE RESPONSE		000	USA	17100	004	USA		140	FT	011	
81.00	145.00	1.4	000	NA	TX	31801	THRTLE	VERIFY CONCERN REAR CODES FOR ACCEL PEDAL IN CODE AND DATA MONITOR FOUND LOW	ON VEHICLE HAS NO THROTTLE RESPONSE AT TIMES		000	USA	10200	004	USA		141	FT	011	
									SENSOR REPLACED AND DETEST OK		000	USA	10200	004	USA		141	FT	011	
78.00	130.20	1	2018	NA	VA	31801	THRTLE	REAR BRACKET PEDAL ASSEMBLY	NO THROTTLE RESPONSE AT TIMES		000	USA	10200	004	USA		141	FT	011	
									WELK CHECKING GOING 80 MPH CUSTOMER STATES THE VEHICLE HAS NO THROTTLE RESPONSE		000	USA	10200	004	USA		141	FT	011	
80.00	100.00	1.4	00	NA	SC	31801	THRTLE	CHECK TEST 14001	NO THROTTLE RESPONSE		000	USA	10200	004	USA		141	FT	011	

TOY COLR	CL	ST	GR	HR	DLR	S	C	DLR	NOV	CHRG	TECH TKT	TECH TKT	CLRT TKT	AREA	COUNT	PL	TOOL	ENTRY	QTY	UNIT	PLA	
DET	DES	S	D	D	D	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	
90.84	120.00	8.7	8789	MA	MO	31801					AP SENSOR NOT WORKING PROPERLY PERFORMED EXHAUST, MAF DIAG, REPLACED AP ASSEMBLY		CHECK FOR NO THROTTLE RESPONSE AT TIMES, COME THRU AT ALL SPEEDS	477	USA	12000	1	USA	144	FT	811	
78.86	198.8	1.2	2024	MA	CT	31801					38 GSEMPLEPT 1.7 LIT L. W/ENGINE 1.5 PI. 4180 PERFORMED DIAG, REPLACED ACCELERATOR PEDAL & TESTED OK. ENGINE OPER. INC. TEST CODE FIRST PINPOINT TEST, REPLACED ACCEL PEDAL ASSEMBLY		SEATTLE AND CLUE, NO THROTTLE RESPONSE	303	USA	12000	2	USA	144	FT	811	
90.84	139.00	0.9	20216	MA	AZ	31801					OK FOR REPAIR TO ACC. PERFORMED DIAG AND REPLACE THROTTLE PEDAL ASSEMBLY AND ACC PED. SUSPECTED FOR NO THROTTLE RESPONSE. CODE FIRST IDLE VALIDATION SWITCH, REPLACED ACC. PEDAL ASSEMBLY		NO THROTTLE RESPONSE NOT TRAMP. RELATED.	082	USA	12000	1	USA	144	FT	811	
01.02	180.1	1.2	2025	MA	NY	31801					PERFORMED DIAG AND REPLACE THROTTLE PEDAL ASSEMBLY AND ACC PED. SUSPECTED FOR NO THROTTLE RESPONSE. CODE FIRST IDLE VALIDATION SWITCH, REPLACED ACC. PEDAL ASSEMBLY		OK AT STOPS NO ACCELERATION, NO THROTTLE RESPONSE	878	USA	11500	2	USA	144	FT	811	
84.4	181.07	2.8	20208	MA	AZ	31801					PERFORMED DIAG AND REPLACE THROTTLE PEDAL ASSEMBLY AND ACC PED. SUSPECTED FOR NO THROTTLE RESPONSE. CODE FIRST IDLE VALIDATION SWITCH, REPLACED ACC. PEDAL ASSEMBLY		REPAIR FOR NO THROTTLE RESPONSE	403	CAN	20000	2	CAN	144	FT	811	
90.84	145.84	1	8527	MA	TX	31801					CHECK AND REPAIR SELF TEST FOR CODES AND TROUBLESHOOT. TEST PER ACCEL. PEDAL ASSEMBLY AND CLEAR CODES ROAD TEST AND RETEST OK. MAF TEST FOR ACCEL. PEDAL PER NO LACK OF RESPONSE ON DRIVE		THE CUSTOMER COMPLAINS THAT AT TIMES THE ENGINE LOOSE THROTTLE RESPONSE SOMETIMES CHARLET COMPLETELY OFF THROTTLE AND REARPLY WILL ACCEL.	010	USA	12000	2	USA	144	FT	811	
87.02	488.44	2.7	8228	MA	KS	31801					PERFORMED ENGINE PERFORMANCE DIAG STOPS 112 FIRST PINPOINT TEST FOUND BAD THROTTLE PEDAL, SENSOR ASSEMBLY AND TURBOCHARGER MISSING BOLTS REPLACED THROTTLE PEDAL ASSEMBLY AND TESTED TURBO BOLTS RETEST GOOD ROAD TEST TO VERIFY CONCERN ENGINE LOOSE POWER AND RESPONSE AT TIMES MAF REMOVE CODES NO CODES. NO SELF TEST SYS PASS HOLD SELF TEST SYS PASS CP PROBLEMS TEST PASS IN SPEC. IDLE RPM	AX RPM 1400RPM CYLINDER CONTRIBUTION TEST SYS PASS EXHAUST SYSTEM RESTRICTION TEST SYS PASS. BOOST PRESSURE TEST PASS TYPE MAF PID MONITOR AND ROAD TEST. RECORD PID IN		VEHICLE DIED OUT WHEN IT WAS RESTARTED IT HAD NO THROTTLE RESPONSE AND LACK POWER	978	USA	10010	1	USA	144	FT	811
88.84	223.15	1.7	7528	MA	IL	31801					NO THROTTLE RESPONSE WHEN SAVED OFF FROM A STOP. AT TIMES HAVE TO PUMP THE ACCELERATOR PEDAL BEFORE THE ENGINE WILL RESPOND. PERFORMED INC. TESTS. TESTS INDICATE RESISTANCE READING IN 1000 RPM IN	ACCELERATOR PEDAL, REPLACED THE ACCELERATOR PEDAL ASSEMBLY, RECORDED CORRECTION. OK	(DIN) CUSTOMER STATED ENGINE LOOSE POWER AND THROTTLE RESPONSE AT TIMES	808	USA	10010	1	USA	144	FT	811	
01.02	175.48	1.5	7547	MA	CA	31801					DEFECTIVE PEDAL ASSEMBLY INC. CHECK TESTS. DIAGNOSIS DIAGNOSTIC PEDAL, DIESEL PERFORMANCE DIAGNOSIS, THE ACCELERATOR SENSOR CUT OUT DURING THE ROAD TEST, THERE WAS A CODE FOR TP SENSOR. LOTT PERFORMED THE PINPOINT TESTS THERE WAS SLIGHT VARIANCE IN RESISTANCES		CUSTOMER STATES THERE IS NO THROTTLE RESPONSE WHEN TRAINING OFF FROM A STOP AT TIMES HAVE TO PUMP THE ACCELERATOR PEDAL BEFORE THE ENGINE WILL RESPOND. INSPECT AND ADVISE.	880	USA	10000	1	USA	144	FT	811	
01.02	180.18	0.7	8427	MA	UT	31801					PERFORMED DIAG AND REPLACE THROTTLE PEDAL ASSEMBLY AND ACC PED. SUSPECTED FOR NO THROTTLE RESPONSE. CODE FIRST IDLE VALIDATION SWITCH, REPLACED ACC. PEDAL ASSEMBLY		VEHICLE LOOSE THROTTLE RESPONSE CUSTOMER HAD TO DEPRESS PEDAL SEVERAL TIMES.	436	USA	10000	1	USA	144	FT	811	
05.4	244.87	3.0	20228	MA	AZ	31801					AT THE IDLE VALIDATION SWITCH REPLACED THE IDLE VALIDATION SWITCH. CLEAR CODES AND RETESTED. OK		INSPECT AND REPAIR VEH INTERMITTENTLY HAS NO THROTTLE RESPONSE. NOT NOTICEABLE AFTER COLD START LACK POWER	770	CAN	40000	1	CAN	144	FT	811	
05.4	143.80	0.9	88807	MA	AZ	31801					TEST OUT FOR LOSS OF THROTTLE RESPONSE, MAF PASS, MEMORY CODE RESET, PINPOINT TESTS FOUND INTERMITTENT NO OPERATION, CHECK CONNECTION. OK. REPLY ROAD TEST AND RETEST. OK	AT TIME TO REPLACE MAP ASSEMBLY	LOSS OF THROTTLE RESPONSE	770	CAN	40000	1	CAN	144	FT	811	

TOT COLDR		SUA		ST. P		CNC		TECH		TECH		CMT		AREA		SLS		CNTRY		MFR		TYS	
INTL	ST	ST	SR	SR	SR	SR	SR	SR	SR	SR	SR	SR	SR	SR	SR	SR	SR	SR	SR	SR	SR	SR	SR
OUT	DES	S	D	D	D	D	D	D	D	D	D	D	D	D	D	D	D	D	D	D	D	D	D
21.82	147.82	0.8	2884	NA	CA	31801		THROTTLE PEDAL WAS INSPECTED AND REPLACED THROTTLE PEDAL/JECT SYSTEM				CHECK FOR INTER ON ACCEL NO RESPONSE	287	USA	178211	884	USA		744	FT			811
21.82	148.84	1.3	2882	NA	CA	31801		THEY BROKE THE CRUISE TWO COORDS PAGES AND FOUND THE THROTTLE PED				CUSTOMER STATES INTERMITTANT NO RESPONSE FROM O WHEN PEDAL IS PRESSED WHEN DRIVE NO RESPONSE FROM PEDAL P/C	289	USA	144628	884	USA		741	FT			811
20.91	142.76	0.4	2888	NA	LA	31801		WAS INTERMITTENTLY REPLACED THROTTLE PEDAL ASSEMBLY					885	USA	128007	1088	USA		744	FT			811
19.88	249.02	4.2	4517	NA	TX	31801		WAS DONE MAIN ... PERFORM PEDAL DASH PERFORMANCE STEPS 1 IN RETURNED-DO NOT COVER POWER POINT PERFORMERS MONITORED ROAD TEST PERFORMERS POINT TEST AS PER MANUAL. REPLACE FULLY THROTTLE PEDAL	L ASSEMBLY RETEST SYSTEM OK TEST PERFORMER		ENGINE STARTS BUT THERE IS NO RESPONSE WHEN PUSH PEDAL AT THROTTLE	281	USA	138004	2	USA		744	FT			811	
19.88	145.88	1	4571	NA	CA	31801		ACC PEDAL, MOP ENGINE PERFORMANCE DIAGNOSTIC T.O. DI TURBO ENGINE DIAG				CUSTOMER STATES OK FOR NO THROTTLE RESPONSE AT TIMES	884	USA	171489	2	USA		744	FT			811
21.82	180.2	1.3	2906	NA	TX	31801		SEC DIAGNOSIS, PPL MONITOR AP MS P/D VOLTAGE W/ WIRE. REPLACE AP MS PEDAL ASSEMBLY				CUSTOMER REPORTS TABLE DIAGNOSIS NO RESPONSE FROM ACCELERATOR WHEN PRESSING, TRUCK LAGS POWER. DSE	188	USA	182888	384	USA		741	FT			811
21.82	208.8	2.8	4800	NA	TX	31801		APR. FILED INTERMITTENTLY. REPLACED IT FOR THE TIME				CHECK FOR NO RESPONSE FROM THROTTLE	483	USA	202248	884	USA		744	FT			811
19.88	111.48	0.4	2880	NA	AR	31801		WAS DONE MAIN ... PERFORM PEDAL DASH PERFORMANCE STEPS 1 IN RETURNED-DO NOT COVER POWER POINT PERFORMERS MONITORED ROAD TEST PERFORMERS POINT TEST AS PER MANUAL. REPLACE FULLY THROTTLE PEDAL ASSEMBLY FOR GOOD				SOMETIMES THERE IS NO RESPONSE FROM THE ENGINE WHEN THE LOCK PEDAL	281	USA	128004	2	USA		744	FT			811
19.88	150.02	1.4	488	NA	AL	31801		PEDAL SEC (BLACK TEST) DIAGNOSIS				CUSTOMER HAS DRIVE, ENGINE STARTS, ENGINE DASH, NO RESPONSE THEY TOOK OFF WITH SUDDEN JERK, NO IS.	281	USA	128004	2	USA		744	FT			811
19.88	214.22	1	185	NA	GA	31801		WAS DONE MAIN ... PERFORM PEDAL DASH PERFORMANCE STEPS 1 IN RETURNED-DO NOT COVER POWER POINT PERFORMERS MONITORED ROAD TEST PERFORMERS POINT TEST AS PER MANUAL. REPLACE FULLY THROTTLE PEDAL ASSEMBLY AND RAN CHECK TEST				CUSTOMER STATES AT TIMES THE THROTTLE HAS NO RESPONSE FROM THE PEDAL. OK COVERED	778	USA	121878	884	USA		744	FT			811
19.88	126.71	1	4588	NA	LA	31801		WAS DONE MAIN ... PERFORM PEDAL DASH PERFORMANCE STEPS 1 IN RETURNED-DO NOT COVER POWER POINT PERFORMERS MONITORED ROAD TEST PERFORMERS POINT TEST AS PER MANUAL. REPLACE FULLY THROTTLE PEDAL ASSEMBLY	ALL OK			O NO RESPONSE FROM CAR PEDAL WHEN ACCELERATING	885	USA	128007	2	USA		744	FT			811
19.88	438.18	5.8	2888	NA	TX	31801		WAS DONE MAIN ... PERFORM PEDAL DASH PERFORMANCE STEPS 1 IN RETURNED-DO NOT COVER POWER POINT PERFORMERS MONITORED ROAD TEST PERFORMERS POINT TEST AS PER MANUAL. REPLACE FULLY THROTTLE PEDAL ASSEMBLY	PERFORMERS MONITORED ROAD TEST PERFORMERS POINT TEST AS PER MANUAL. REPLACE FULLY THROTTLE PEDAL ASSEMBLY			CUSTOMER STATES ENGINE INTERMITTENTLY HAS NO RESPONSE WHEN ACCELERATOR IS PRESSED	217	USA	128004	2	USA		741	FT			811
19.88	144.8	1.3	4800	NA	TX	31801		WAS DONE MAIN ... PERFORM PEDAL DASH PERFORMANCE STEPS 1 IN RETURNED-DO NOT COVER POWER POINT PERFORMERS MONITORED ROAD TEST PERFORMERS POINT TEST AS PER MANUAL. REPLACE FULLY THROTTLE PEDAL ASSEMBLY				OCCASIONALLY NO RESPONSE FROM ACCELERATOR PEDAL. BUT POWER STARTS, THERE IS NO RESPONSE	878	USA	128004	1	USA		744	FT			811
19.88	254.41	2	4800	NA	CA	31801		WAS DONE MAIN ... PERFORM PEDAL DASH PERFORMANCE STEPS 1 IN RETURNED-DO NOT COVER POWER POINT PERFORMERS MONITORED ROAD TEST PERFORMERS POINT TEST AS PER MANUAL. REPLACE FULLY THROTTLE PEDAL ASSEMBLY				CUSTOMER STATES LOWS POWER AND BLUDDERHALD AT TIMES WHEN COLD STOP ON ACCEL AND ENGINE HAS NO RESPONSE DSE	778	USA	121878	884	USA		741	FT			811

TRC	TOT. COLMR	DU	ST. P.	TRCH TKT	TRCH TKT	DUET TKT	AREA-COLMT	BLR. DU. TOL	ENTRY	DRY/NO	AMG	UNT	TBL
INT. C. ST. GR	HR	DUR.	LE	CHLGR.	NOV.	CPACC.	CD	TRC	CD	CD	CD	CD	PLA
INT.	GR	H	D	D	CD	CD	TRC	CD	TRC	CD	CD	CD	PLA
78.0	182.21	0.7	3591	NA	CA	3189	789 USA	17480	384	USA	144	PT	311
				FOLDED THROTTLE PEDAL ASSEMBLY OPEN CIRCUIT. REPLACE ASSEMBLY. SERVICE FOR TREN TO VERIFY AND REPROGRAM AND INSTALL ACCELERATOR PEDAL. NO LABOR TIME STANDARD PUBLISHED.			S O THROTTLE PEDAL ASSEMBLY. CUSTOMER STATES SOMEHOW NO RESPONSE FROM ACCELERATOR						
81.58	147.53	0.8	3573	NA	MA	3189	878 USA	11344	384	USA	144	PT	311
				RESPONSE WILL NOW BE REPLACED GAS PEDAL.			WHEN THE ENGINE AT TIMES STOPS ON THE GAS PEDAL NO RESPONSE REPAIR FOR ENGINE LACKS POWER/FLOOR RESPONSE FROM THROTTLE						
88.4	211.34	2.1	3724	NA	NC	3189	288 CAN	48718	372	CAN	144	PT	311
				REPLACE THROTTLE PEDAL.			ON COLD ENGINE ON TYPICAL APPLICATION GET NO RESPONSE. REPLACE THROTTLE PEDAL.						
85.4	137.18	0.8	3733	NA	NC	3189	300 CAN	48022	384	CAN	144	PT	311
				DIAG AND REPLACE THROTTLE PEDAL.			CUSTOMER STATES WHEN YOU FIRST START THE TRUCK COULD IN THE MORNING THERE IS NO THROTTLE RESPONSE, THIS LASTS FOR THE FIRST 30-60 SEC. CHECK AND ADJUST. (TRUCK WAS MIGHT DROPPED AND						
78.0	171.89	0.8	3585	NA	MA	3189	300 USA	17484	2	USA	144	PT	311
				WAS STARTING IN AN ATTEMPT TO DULPLICATE CONDITION OF NO THROTTLE RESPONSE FOR 30 TO 60 SEC. DID NOT DULPLICATE ALTHO I DO NOTE THAT THE VEHICLE POWER LIGHTS WARMED UP A LITTLE, THIS IS NORMAL, DUE TO CHECKED FOR NO ACCELERATOR RESPONSE. PERFORMED SCOR, KOOP, INJECTOR AND FUEL. WERE REPLACED THROTTLE POSITION SENSOR.			THE WARM UP DOES NOT ALLOWING FULL FLOW OF TURBO PRESSURE. RAN OVER, THERE IS A SIGN FOR LACK OF THROTTLE RESPONSE. CLARIFIED THE EVENT THE WARNING LIGHTS WILL ALSO CYCLE. ASK ME TO CONTACT CLAY.						
85.4	165.91	1.8	3709	NA	NC	3189	804 CAN	44707	384	CAN	144	PT	311
				PERFORMED SCOR, KOOP, INJECTOR AND FUEL. WERE REPLACED THROTTLE POSITION SENSOR.			STOPS AND BLENDS BUT WILL NOT GO FASTER THAN BLEND RESPONSE FROM						
78.0	147.57	1.1	3140	NA	CO	3189	738 USA	10028	2	USA	144	PT	311
				PERFORMED SCOR, KOOP, INJECTOR AND FUEL. WERE REPLACED THROTTLE POSITION SENSOR.			THE CUSTOMER STATES THERE IS NO RESPONSE FROM THE THROTTLE. THIS HAS HAPPENED AT LEAST THREE TIMES.						
81.58	151.88	1.7	3593	NA	CA	3189	480 USA	48280	384	CAN	144	PT	311
				DIAG CYCLE TEST P1111 CHECK FUEL PRESSURE AND COORDINATE ELECTRONIC TRANSMISSION. DING CODE P0222 21 MP OUT OF RANGE AT PACE.			BASE PRELIMINARY STATE THAT AT TIMES YOU CAN PUSH ON THE ACCELERATOR AND NO RESPONSE AND THE BLENDS FROM BLEND.						
78.0	188.81	1	3528	NA	WI	3189	718 USA	10828	384	USA	144	PT	311
				ENGINE WILL NOT ACCELERATE WHEN GOLD. WERE REPLACED FUEL ASSEMBLY. ROAD TEST. COMPLAINT, MONITORED ENGINE FUEL AND ELECTRICAL SYSTEMS. TRACED TRICKLE CODES.			NO RESPONSE FROM THROTTLE. CUSTOMER STATES THAT WHEN TURNING OFF THE VEHICLE FALLS ON GAS PACE, BLEND, AT TIMES NO THROTTLE RESPONSE.						
78.0	188.78	1.4	3184	NA	CA	3189	882 USA	17048	1	USA	144	PT	311
				TEST DRIVE PERFORMED WAS DIAG. PERFORMED SCOR, KOOP, INJECTOR AND FUEL. WERE REPLACED THROTTLE POSITION SENSOR TO INTERMITTENT BLEND. LOCATION SWITCH REPLACED SWITCH CLEARED CODES AND RETEST OK.			INTERMITTENT NO RESPONSE WHEN PRESSURE ACCEL SENSOR. REPAIR FOR NO RESPONSE FROM ACCEL PEDAL INTERMITTENTLY S.O.P.						
81.58	135.24	0.8	3538	NA	UT	3189	438 USA	18888	372	USA	144	PT	311
				RAN ENGINE PERFORMANCE DIAGNOSTIC STEP 1 THRU STEP 8. REPLACED THROTTLE PEDAL.									
78.0	188.7	8.8	1882	NA	CA	3189	882 USA	48728	1	USA	144	PT	311
				PERF CHECK AIR AND FUEL SYSTEMS IN PM ON BOTH CYL. HINES AS WOT. THEN I DID ALL ROBO NOISE TESTS. HAD CODE P0221 TO ALL FRONT TEST AND REPLACE A BATTERY/THROTTLE PEDAL ASSEMBLY. NO CHECK FOR THAT IS IN AL. NO TESTS NO CODES IN MEMORY. FOLLOWED PERFORM TEST AND MONITOR FOR WHILE DRIVING. FOLDED PEDAL WERE WORKING AT TIMES, REPLACED PEDAL ASSEMBLY.			CHECK WOT FOR NOT ACCELERATING INTERMITTENT. CUSTOMER STATES THAT HE WILL STOP ON THE PEDAL AND IT WILL GET NO RESPONSE. CUSTOMER STATES THROTTLE PEDAL UNDERSTANDS INTERMITTENTLY. WHEN ENGINE FLEWERS, FLEWERS ACCCEL AND NO RESPONSE FROM ENGINE. REPAIR TUNE POSITION PEDAL AND NO RESPONSE.						
78.0	188.09	1.4	3572	NA	MA	3189	882 USA	18807	384	USA	144	PT	311
				CHECK SYSTEM P0221 AND THE PEDAL AND RECHECK.									
88.4	188.4	8.8	1882	NA	CA	3189	882 CAN	48728	372	CAN	144	PT	311

YTD_COLLN	ST	REG	ST_P	TECH DXT	TECH DXT	CLRT TYP	WASA	COURT	TRAIL	TAL	ENTRY	PRD	WFO	WAS	WFO	TR	FLA	
APPLC BY OR	HR	DUR	C.L.G	ONLC	REV	OPRC	CD	BY CD	PL CD	TR CD	SOLO	CD	CD	CD	CD	CD	CD	
CDST	CDST	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	
31.52	271.52	1.8	888	NA	NA	31501												
TEST FOR NO RESPONSE FROM THROTTLE PEDAL, RPM DEGR. DING NO COOBS, MONITOR PDS ON ROAD TEST, PERFORM TEST, MISC REPLACE THROTTLE PEDAL AND RETEST OK					CUSTOMER STATES POOR POWER NO RESPONSE AS ACCEL UP HILL AFTER COLD START INTERRUPTED, SEE HISTORY					488	USA	17400	284	USA	*	Y1	FT	211
31.24	253.24	2.3	888	NA	NA	31501												
RPM MONITOR INSPECT FOR WACK HISS NO THROTTLE RESPONSE, CHECK COOBS, HAD CODE P132 IN MEMORY, GO TO PPT OBL BOX TO UNABLE TO DUPLICATE CONCERN, USE WOB TO GET SHED DATA LINK, ROAD TEST AND MAKE REC					DROPPED AF VOLTAGE, FOUND VOLTAGE TO DROP TWICE WITH STEADY THROTTLE, REPLACE FROM ASSEMBLY, CLEAR CODES, ROAD TEST AGAIN, DONT GET PRIVATE AF READING AND CODE DID NOT RESET					286	USA	17888	278	USA	*	Y1	FT	211
73.90	191.88	1.8	888	NA	AR	31501												
EGC TEST, PERFORM, REPLACE PEDAL AND SERVOLOGY					THERE IS NO RESPONSE WHEN THE ACCELERATOR PEDAL IS DEPRESSED SERVO WILL ACCELERATE IF PEDAL IS HELD DOWN					801	USA	18884	288	USA	*	Y4	FT	211
31.52	265.2	1.4	888	NA	LA	31501												
OPEN INTX SENSOR TEST DRIVE, RUM PERFORMANCE (DASH STOPS 1 S, PERFORM PP TEST PER NO, PER NO, PER YES, REPLACE PEDAL, ASSEMBLY, QUALITY					G S AT TIMES ON START UP AND PRESS ACCELERATOR PEDAL, NO THROTTLE RESPONSE					318	USA	18888	278	USA	*	Y1	FT	211
31.52	231.76	0.4	788	NA	CA	31501												
DASH THROTTLE PEDAL, DEFECTIVE REPLACED THROTTLE PEDAL AND RETEST OK					INSPECT FOR NO THROTTLE RESPONSE AT TIMES, CHECK WASH, CLRT SENSORS THAT THERE IS A SENSOR ON THE ACCEL PEDAL, THERE IS NO RESPONSE FROM ACCEL PEDAL					302	USA	17888	288	USA	*	Y4	FT	211
31.52	118.88	0.5	318	NA	CO	31501												
INTERNAL FAULT TEST SYSTEM AND REPLACE PEDAL, ASSEMBLY ROAD TEST FOR CONCERN, FOUND CHECK ENGINE LIGHT BLINKS AND GOES TO IDLE, PERFORM DRIVE, DASH PERFORM DCL DISPLAY TEST, PERFORM PROMONITOR ROAD TEST, NECESSARY TO REPLACE PEDAL, ASSEMBLY, RETEST TESTED PASS					AFTER REPAIR					370	USA	18888	278	USA	*	Y17	FT	211
31.58	215.72	4	788	NA	TX	31501												
RPM SENSING PERFORMANCE TESTS 1.2L, REPLACE ACC ELIMINATOR PEDAL, RETEST					2.2L C B WHEN PASSING, VEHICLE HAS NO RESPONSE FROM ACCEL PEDAL					281	USA	18878	284	USA	*	Y4	FT	211
31.58	255.02	4.2	888	NA	TX	31501												
OPEN CIRCUIT NO OPS, REPLACE ACCELERATOR PEDAL, SENSOR ASSEMBLY					AT TIMES WHEN ENGINE IT GOES THERE IS NO RESPONSE FROM PEDAL, LOG S REPORTS M/D					375	USA	18884	278	USA	*	Y4	FT	211
31.52	327.38	0.8	888	NA	TX	31501												
PERF DASH AND FUEL TESTS P132E P0221, MONITOR PDS AND FOUND AP SENSOR FAULTY, REPLACE AP ASSEMBLY, RETEST					CLRT STATES ACCELERATOR PEDAL HAS NO RESPONSE AT TIMES					308	USA	18888	288	USA	*	Y18	FT	211
31.52	328.97	4	308	NA	TX	31501												
RUM ALL PERFORMANCE, DASH TESTS, MONITOR PDS ON ROAD TEST, PERFORM TEST COOBS, P0132 P0121, REPLACE BY SENSOR					TANK THERE HAS BEEN NO RESPONSE WHEN PRESSING THROTTLE					311	USA	18888	278	USA	*	Y16	FT	211
31.52	381.0	4.4	888	NA	TX	31501												
IF VEHICLE DOES NOT RUM, RUM ALL TESTS PER 1.2L DASH SHIRT, FOUND NO VOLTAGE CHANGE FROM AP SENSOR AT TIMES, REPLACE ACCELERATOR PEDAL, ASSEMBLY, RECHECK ON AT THIS TIME					RED LITE COMES ON AND LOOBS DASH FROM RESPONSE					282	USA	18877	278	USA	*	Y18	FT	211
31.52	279.38	2.4	788	NA	CA	31501												
WFO CHECK OUT FOUND NECESSARY TO PER ACCEL PEDAL ASSEMBLY					LACK OF RESPONSE ON ACCEL W COLD, OK W WARM					300	USA	17888	278	USA	*	Y11	FT	211
31.52	145.02	0.8	888	NA	IN	31501												
RUM DASH PERFORM, WPC FILTER, CONTINUOUS CODE P132, REPLACE AP ASSEMBLY, ROAD TEST, OK					REPAIR ENGINE CUTS CLRT WHILE DRIVING, PEDAL, LOOBS RESPONSE					218	USA	18814	288	USA	*	Y12	FT	211
11.88	412.14	4.7	888	NA	TX	31501												

TOT COLBAR	DLR	BU	REG	ST	OPSC	TRCH	TRCH	TRCH	TRCH	AREA	COUNT	SUB	DL	TOTL	ENTRY	CRD	MTS	AWF	TR	FLA
MTPL_C	BY	SR	HR	DLR	C	O	C	NOV	CO	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD
001	002	003	004	005	006	007	008	009	010	011	012	013	014	015	016	017	018	019	020	021
70.81	162.80	1.4	2078	NA	IA	3180	PERFORMED NO BELT TESTS RECEIVED CODES P022 P023 P024 FOR ACCELERATOR SENSOR PERFORMED PROPOINT TEST	PERFORMED NO BELT TESTS RECEIVED CODES P022 P023 P024 FOR ACCELERATOR SENSOR PERFORMED PROPOINT TEST	CUSTOMER SAYS THERE IS NO RESPONSE WHEN PRESSING ON THE GAS PEDAL	85	USA	16280	872	USA		NA	77	811		
79.86	216.89	3.0	3168	NA	MO	3180	CHECK NO THROTTLE RESPONSE SERIAL DMA STEPS 1 TO CODE P0221 PROPOINT TEST PASSED AND REPLACE ACC PEDAL ASSEMBLY	CHECK NO THROTTLE RESPONSE SERIAL DMA STEPS 1 TO CODE P0221 PROPOINT TEST PASSED AND REPLACE ACC PEDAL ASSEMBLY	SOMETIMES THROTTLE HAS NO RESPONSE	814	USA	40884	1	USA		NA	77	811		
81.82	221.5	2	8829	NA	WA	3180	INSPECTED AND ISOLATED CONCERN TO THROTTLE PEDAL ASSEMBLY, REPLACED THROTTLE PEDAL ASSEMBLY AND RE TESTED	INSPECTED AND ISOLATED CONCERN TO THROTTLE PEDAL ASSEMBLY, REPLACED THROTTLE PEDAL ASSEMBLY AND RE TESTED	REPAIR FOR THE VEHICLE HAVING NO THROTTLE RESPONSE (DIP CLUT SWITCH WHILE DRIVING AT TIMES WHEN HAS NO THROTTLE RESPONSE	208	USA	10388	872	USA		NA	77	811		
82.84	207.71	1.8	5471	NA	CA	3180	PERFORMED DIAGNOSTICS T.S.D.3 TLESD ENGINE DIAG ROADTEST, ROAD WITH WORK CODE P0221, PROPOINT TEST, REPLACED ACCELERATOR PEDAL ASSEMBLY AND CLEAR CODES, ROADTEST AND RE TESTED OK	PERFORMED DIAGNOSTICS T.S.D.3 TLESD ENGINE DIAG ROADTEST, ROAD WITH WORK CODE P0221, PROPOINT TEST, REPLACED ACCELERATOR PEDAL ASSEMBLY AND CLEAR CODES, ROADTEST AND RE TESTED OK	REPORT NO RESPONSE WHEN APPLYING THE THROTTLE TO ACCELERATE	881	USA	71428	884	USA		NA	77	811		
82.84	208.71	1.8	88	NA	MD	3180	CODE MP PERFORM DIESEL DIAGNOSTICS PERFORM PROPOINT TESTS AND REPLACE ACCELERATOR PEDAL ASSEMBLY	CODE MP PERFORM DIESEL DIAGNOSTICS PERFORM PROPOINT TESTS AND REPLACE ACCELERATOR PEDAL ASSEMBLY	CHECK ACCELERATOR WONT OPERATE AT TIMES HAS NO RESPONSE	478	USA	14788	872	USA		NA	77	811		
81.82	140.2	0.8	8973	NA	MA	3180	REPLACED THE GAS PEDAL	REPLACED THE GAS PEDAL	GAS PEDAL NO RESPONSE IN THE MORNING AFTER THE VEHICLE HAS BEEN SITTING, WHEN TRYING TO ACCEL THERE IS NO RESPONSE. ALSO HE STATES THAT HE HAS TO ADD OIL TO ENGINE EVERY 1000 MILES	928	USA	11704	888	USA		NA	77	811		
81.82	177.85	1	778	NA	CA	3180	WAS NOT SWITCH TEST, OK. VEHICL OK. NO CODES. ROAD TEST, VERY INTERMITTENT COULD OK HOT. RAN PEDAL TEST	WAS NOT SWITCH TEST, OK. VEHICL OK. NO CODES. ROAD TEST, VERY INTERMITTENT COULD OK HOT. RAN PEDAL TEST	NO RESPONSE WHEN PRESSING ACCELERATOR	818	USA	17288	884	USA		NA	77	811		
81.82	156.81	6.8	8882	NA	LA	3180	WAS NOT TEST CODE P0221 & P0222. DIAGNOSIS IN ACCEL PEDAL SWITCH. REPAIR ACC PEDAL ASSEMBLY. CODES IN ALL NECESSARY TEST MET OR ENGINE OFF KEY ON ENGINE RUM PROPOINT TEST PASSED P0221 PROPOINT TEST PASSED ACCELERATOR PEDAL ASSEMBLY	WAS NOT TEST CODE P0221 & P0222. DIAGNOSIS IN ACCEL PEDAL SWITCH. REPAIR ACC PEDAL ASSEMBLY. CODES IN ALL NECESSARY TEST MET OR ENGINE OFF KEY ON ENGINE RUM PROPOINT TEST PASSED P0221 PROPOINT TEST PASSED ACCELERATOR PEDAL ASSEMBLY	CUSTOMER STATEMENT THAT WHEN GOES TO ACCELERATE NO RESPONSE. CUSTOMER HIT THE BRAKE A COUPLE OF TIMES THEN WILL START TO ACCELERATE	207	USA	82884	878	USA		NA	77	811		
81.82	217.8	2.1	2188	NA	OH	3180	LOOK UP REPAIR WORK NOT DONE WHEN PRESSING ON THE THROTTLE PEDAL PERFORMED PERFORMANCE CHECK STEPS 1 TO 8 AND HAD A CODE OF P0221 PERFORMED PROPOINT TEST AND REPLACED THE THROTTLE PEDAL ASSEMBLY TO FI	LOOK UP REPAIR WORK NOT DONE WHEN PRESSING ON THE THROTTLE PEDAL PERFORMED PERFORMANCE CHECK STEPS 1 TO 8 AND HAD A CODE OF P0221 PERFORMED PROPOINT TEST AND REPLACED THE THROTTLE PEDAL ASSEMBLY TO FI	ON ACCELERATION FROM A STOP AT TIMES THERE IS NO RESPONSE	218	USA	14127	872	USA		NA	77	811		
79.86	188.72	1.7	8884	NA	WA	3180	DO THE CHECK FOR CODES WITH NEW SCOD ON DISK AND SELF TEST P0221 TP SENSOR HIGH CLEAR RESIDUE CONT DTC P0221 CHECK CIRCUIT FOR SHORT TO GROUND OR CHECK CIRCUIT FOR SHORT TO POWER OR CHECK FOR POWER	DO THE CHECK FOR CODES WITH NEW SCOD ON DISK AND SELF TEST P0221 TP SENSOR HIGH CLEAR RESIDUE CONT DTC P0221 CHECK CIRCUIT FOR SHORT TO GROUND OR CHECK CIRCUIT FOR SHORT TO POWER OR CHECK FOR POWER	ON ACCELERATION FROM A STOP AT TIMES THERE IS NO RESPONSE	688	USA	71488	888	USA		NA	77	811		
81.82	149.8	0.2	7888	NA	IL	3180	CHECKED AND REPLACED BRUSH PEDAL ASSEMBLY. ROAD TESTED OK. CHECK FOR INTERMITTENT CHECK ENGINE LIGHT ON, NO RESPONSE FROM ENGINE UPON ACCELERATION. PERFORM ENGINE PERFORMANCE TESTS 1, 2, RETURNED DTC P0221, PROPOINT TEST AND DSEA MONITOR TEST, REPLACE ACC ASSEMBLY	CHECK PERFORM RESISTANCE TEST WHILE DEPRESSING PEDAL, REACHES SWP MAT 3 DIFFERENT POSITIONS. REPLACED THROTTLE POSITION SENSOR PERFORM TEST SYS PASSED.	(DSE) OWNER STATES INTERM THROTTLE STOPPED RESPONDING BACK OFF CRAY	608	USA	18878	888	USA		NA	77	811		
81.82	127.88	0.7	887	NA	NC	3180	CHECK FOR INTERMITTENT CHECK ENGINE LIGHT ON, NO RESPONSE FROM ENGINE UPON ACCELERATION. PERFORM ENGINE PERFORMANCE TESTS 1, 2, RETURNED DTC P0221, PROPOINT TEST AND DSEA MONITOR TEST, REPLACE ACC ASSEMBLY	CHECK FOR INTERMITTENT CHECK ENGINE LIGHT ON, NO RESPONSE FROM ENGINE UPON ACCELERATION. PERFORM ENGINE PERFORMANCE TESTS 1, 2, RETURNED DTC P0221, PROPOINT TEST AND DSEA MONITOR TEST, REPLACE ACC ASSEMBLY	CHECK ACCELERATOR FOR NO RESPONSE AT TIMES	288	USA	18787	8	USA		NA	77	811		
81.82	171.8	1.8	8880	NA	AR	3180	PERFORMED NO BELT TESTS RECEIVED CODES P022 P023 P024 FOR ACCELERATOR SENSOR PERFORMED PROPOINT TEST	PERFORMED NO BELT TESTS RECEIVED CODES P022 P023 P024 FOR ACCELERATOR SENSOR PERFORMED PROPOINT TEST	REPAIR FOR NO RESPONSE FROM ENGINE WHEN GAS PEDAL DEPRESSSED	488	USA	14888	888	USA		NA	77	811		

PE03-044-A 6056

TRF	CD	ST	BR	HR	CLF	C	D	DM	CR	PROV	OPNC	TECH	TRF	AREA	CURT	BLA	DL	DM	ENTRY	ENTR	AMG	TRF	PLA			
CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD			
81.02	49.27	0.3	2895	MA	FL	21801						PERFORMED PERFORMANCE TESTS AND RETRIEVED P1211 AND P211 BOP OPERATOR THAN EXPLODED AND AP SENSOR HIGH INPUT PERFORMED PIN POINT TEST AND MONITOR AND DATA RECORDING FOR P1211 TEST BY A REPAIRING GAS PEDAL SENSOR REPLACED	217	CONTRACTOR CHANGED OUT OF CONNECTOR CHANGING DEC TO SET ALSO FOLDED GAS PEDAL SENSOR BOP REPLACED GAS PEDAL SENSOR AND REPAIRD CONNECTOR C146 AND RETEST												
80.84	118.84	0.7	2842	MA	UT	21801						VERIFY CONSOLE, INSPECT, FOLDING ACCELERATOR PEDAL AND FOLDING OFF, REPLACE PEDAL ASSEMBLY, VERIFY REPAIR, RT FOR NO LAB OPERATION FOR THIS REPAIR.	217	GAS PEDAL BOP	302	USA	12589	RTZ	USA		144	FT	211			
80.4	118.341	0.3	8620	MA	MS	21801																				
71.88	105.38	0.4	2401	MA	TX	21801																				
81.02	327.02	4.1	2828	MA	OK	21801						SPRINGS 42 PWR. DEMO. DIAG. FOUND SHORTED ACCELERATOR PEDAL REPLACE A P, RETEST ALL P1111, ROAD TEST OK	217	CURT STATES GAS PEDAL BEING INOPERATIVE	400	CAN	48829	DM	CAN		144	FT	211			
81.02	327.02	4.1	2828	MA	OK	21801																				
81.02	443.12	4.4	2828	MA	OK	21801						2026 THROTTLE PEDAL SENSOR ASSEMBLY WARN. TESTED, PERFORM PERFORMANCE DIAG SHEET AND R:1 FOR AND INSPECT FUSE AND R:1 AND COVER A AND TEST LOOK TO DME AND WIGGLE TEST FOUND OK. R:1 LOWER DASH TRIM	217	CURT STATES ACCELERATOR PEDAL NOT WORKING ACCEL. COVER	818	USA	16202	DM	USA		144	FT	211			
71.88	288.4	2.3	8620	MA	OK	21801						CHECK FOR LACK OF POWER, HOOKUP WIRE, P12, BLAN. PWRP DIAGNOSTIC, RIGHT TO PINPOINT RESUME AND RE PLACED ACCELERATOR PEDAL ASBY, CLEAR CODES, THROTTLE RESPONSE BETTER BOP	217	TURBO WAE BOP CHECK ON ACCELERATION	300	USA	17402	DM	USA		144	FT	211			
71.88	305.48	0.8	2882	MA	FL	21801						ACCELERATOR PEDAL FOR BOP TEST RETRIEVED P211 CONTINUOUS PERFORMED PINPOINT TEST P211 TESTED PEDAL AND REPLACED ACCEL. PEDAL, RETEST OK.	217	OK ALL GUAGES IN DASH BOP ADVISE POWER WARN CURT STATES GAS PEDAL BOP AT THROTTLE	400	USA	18202	DM	USA		144	FT	211			
81.02	181.80	1.4	772	MA	OK	21801																				
81.02	255.78	1.8	8187	MA	TX	21801						RUN ACCO. RETRIEVED CODES P011 P1118 BOP PERFORMANCE P1118 RUN PINPOINT TEST REPLACED PEDAL ASBY SPRINGS CHANG IN BOP CIRCUIT CLEAR CODES AT ROADTEST P1118 RETURNED ALSO P1118 BOP ADVISED WIGGLE P1118	217	THROTTLE PEDAL BOP SOMETIMES WIGGLE (P0118)	800	USA	18202	DM	USA		144	FT	211			
81.02	105.55	0.4	1341	MA	PA	21801						REPLACE WITH NEW	217	CURT STATES ACCEL. PEDAL BOP ADVICE	300	USA	18202	DM	USA		144	FT	211			
81.02	226.78	2	7887	MA	CA	21801						17) VERIFY ACCELERATOR BOP AT TIMES, WOE DME, RAN ALL ELECTRICAL TESTS FOR T.J.L. & DMS SHEET, FOUND OPEN SLAP SENSOR, REPLACED PEDAL ASSEMBLY, RECHECK OK AT THE TIME INTERNALLY SHORTED ACCELERATOR PEDAL AND SENSOR ASSEMBLY PERFORMED ELECTRICAL DMS, AND REPLACE ACCELERATOR PEDAL AND SENSOR ASSEMBLY, CLEAR CODES AND ROADTEST DMS	217	FUEL PEDAL BOP	810	USA	11400	DM	USA		144	FT	211			
80.9	144.4	0.5	488	MA	TX	21801																				
80.84	155.38	1	2892	MA	CA	21801						PEDAL ASBY BROKEN, TIME NEEDED TO REMOVE AND REPLACE PEDAL ASBY	217	CUSTOMER STATED ALL GAUGES RIGHT BOP FOLLO FUEL BLOWN REPLACED WITH FUSE FROM HOME LIGHT. FUSE BLOW AGAIN	770	USA	18202	DM	USA		144	FT	211			
80.84	155.38	1	2892	MA	CA	21801																				

TOT CO LBR	BU	INSTR	ST P	MTAL C ST BR	PR	CLP C	SL	OR	C ROV	CRSE	TECH	TECH	TECH	AREA	COUNT	SL	DL	TON	ENTRY	CRD	WFO	VL	WRT	TR	PLA
001	048	8	0	2	5	00	00	00	00	00	TECH	TECH	TECH	00	00	00	00	00	00	00	00	00	00	00	00
79.85	171.1	0.7	9718	NA	NY	21801					DIAGNOSE AND REPLACE THROTTLE POSITION SENSOR CHECKED OPERATION														
81.82	288.8	2.8	3172	NA	CO	21801					ALL DIAG T 14 PERFORM TO TRY IN RE OPEN CIRCUIT REAR ACCEL PEDAL ASSEMBLY AND TEST DRIVE OK														
80.84	100.08	1	3012	NA	NY	21801					NO TIME TO DIAGNOSE AND REPLACE THROTTLE ACCEL PEDAL ASSEMBLY CODE P1208														
79.86	87.34	0.3	3092	NA	TX	21801					CC 01 SPRING REPLACED ACCELERATOR PEDAL MECHANISM														
79.86	108.28	0.5	1087	NA	DC	21801					REPLACE GAS PEDAL TEST DRIVE OK. OK CODES. FOUND MECHANICAL PERFORM TEST AND FOUND CIRCUITS OK. PLAYED WITH ACCEL PEDAL AND FOUND THAT WHEN PEDAL BRAKE BACK														
81.82	148.82	0.8	105	NA	MO	21801					SOME TIMES ACCEL IS NOT CUSTOMER STATES ACCELERATOR PEDAL STOP														
101.74	131.34	0.4	1282	NA	PA	21801					REPLACED PEDAL AND SWITCH														
88.84	110.44	0.5	2882	NA	FL	21801					ACCELERATOR PEDAL ASSEMBLY														
81.82	179.34	1.9	3813	NA	TX	21801					PERFORM MONITOR CODES RECAL RETRIEVED CODE P0021 FROM PERFORM TEST AND TO REPLACE PEDAL ASSEMBLY														
81.82	271.87	2.7	8808	NA	MO	21801					INTERMITTANT NO T P SERIAL COMPLETE PERFORMANCE CHECK AND PERFORM CODES RETRIEVED REPLACE THROTTLE PEDAL ASSEMBLY AND														
81.82	108.41	0.8	8882	NA	OR	21801					PERFORM OPERATIONS														
81.82	238.82	2.3	3882	NA	FL	21801					PERFORM OPERATIONS														
81.82	238.82	2.3	3882	NA	FL	21801					ON CLUTCH CONTROLS PERFORMED NOISE AND INSOME CODES PERFORM OUT OF RANGE PERFORM PERFORM TEST HOOK UP AND INSTALLED BRAKE OUTBOX MONITOR FROM FOUND FOOT PEDAL ASSEMBLY														
81.82	179.34	1.8	8815	NA	MA	21801					PERFORM OPERATIONS														
81.82	198.82	0.8	7712	NA	CA	21801					PERFORM OPERATIONS														
79.86	132.14	0.8	2888	NA	FL	21801					PERFORM OPERATIONS														
81.82	179.34	1.8	2188	NA	CO	21801					PERFORM OPERATIONS														
81.82	188.72	1	3182	NA	CO	21801					PERFORM OPERATIONS														

PE03-044-A 6069

TOT. COOL. BR.	BLK.	FROM	EST. P.	SPED.	TECH. TGT.	TECH. TGT.	QUANT. TGT.	AREA	COUNT	PLS. IN. TOL.	CNTY.	QTY.	WTS.	TOL.	
MTR. C. ST. BR.	JHR.	DIA. C. B. C.	CH. GENOV.	CO. S.	TECH. TGT.	TECH. TGT.	QUANT. TGT.	EXP.	REV. CO.	IN. CO.	IN. CO.	IN. CO.	IN. CO.	IN. CO.	
CRY.	CRS.	P.	D.	P.	D.	D.	D.	EXP.	REV. CO.	IN. CO.	IN. CO.	IN. CO.	IN. CO.	IN. CO.	
81.82	202.2	2.8	0880	NA	TX	31801	1	48	USA	182000	USA	1	144	FT	011
82.84	202.2	2.2	2881	NA	TX	31801	1	872	USA	182000	USA	2	141	FT	011
83.84	202.08	4.7	4877	NA	P.	31801	1	904	USA	182000	USA	1	141	FT	011
81.82	128.01	8.8	2881	NA	TX	31801	1	889	USA	171000	USA	1	141	FT	011
78.84	200.981	2.8	2881	NA	TX	31801	1	872	USA	188000	USA	2	141	FT	011
78.84	201.01	2.8	2881	NA	TX	31801	1	888	USA	188000	USA	2	144	FT	011
81.82	128.12	1	488	NA	TX	31801	1	888	USA	182000	USA	1	144	FT	011
81.82	213.84	1.8	887	NA	CA	31801	1	888	USA	128000	USA	1	148	FT	011
84.26	145.48	1	2881	NA	OH	31801	1	813	USA	147000	USA	1	143	FT	008
78.84	178.7	1.8	8078	NA	AR	31801	1	478	USA	188011	USA	1	144	FT	011
81.82	202.07	2.8	88	NA	MD	31801	1	818	USA	182000	USA	1	141	FT	011
78.84	121.07	8.7	2881	NA	NA	31801	1	817	USA	188000	USA	1	144	FT	011
81.82	202.12	1.7	2488	NA	TX	31801	1	872	USA	182000	USA	1	141	FT	011
78.84	202.23	4.8	8180	NA	TX	31801	1	474	USA	145000	USA	2	144	FT	011

PE03-044-A 6074

WTRAL	CO	BY	PR	YR	DLA	C	CL	ON	CHDV	SPCL	TECH	INTZ	CUST	TAT	AREA	COUNT	BUILD	DM	ENTRY	QTY	VPS	VAL	VLT	PLA	
QST	056	5	0	0	0	0	0	0	0	0	TECH	INTZ	TAT	CO	BY	CO	LG	CP	BOLD	CL	CO	CO	CO	CO	CO
60.84	108.84	0.41	4082 *	NA	TX	21801					TESTED ON TO THROTTLE POS. AND WHEEL FOUND EXCESSIVE CLUTCH OF WHICH REPLACED THROTTLE ASSEMBLY.		BAR PEDAL NOT WORKING	800 USA		18070	804	USA	*	144	PT	811			
81.82	84.82	0.2	801 *	NA	NY	21801					GREEN ACCEL. PEDAL NOT WORKING. VERIFY ACCEL. PEDAL LINKAGE CHASE (APART. REMOVE OLD ACCEL. PEDAL & REPLACE WITH NEW. VERIFY PROPER OPERATION.		CUSTOMER STATES ACCEL. PEDAL NOT WORKING AS IT SHOULD BE. CUSTOMER	770 USA		14410	204	USA	*	144	PT	811			
80.4	108.4	0.2	10822 *	NA	NE	21801					INSPECT AND REPLACE ACCELERATOR PEDAL.		GREEN ACCELERATOR PEDAL NOT WORKING	780 CAN		88800	804	CAN	*	148	PT	811			
81.82	126.82	1.1	801 *	NA	TX	21801					COMPRESSOR ACCEL. KAWAII PRESS. PED. MONITOR. ASPECT. SMALL THUMB. OPER. IN TR. REPLACE PEDAL. ASBY. & RETEST ALL.		CUST. STATES ACCELERATOR PEDAL NOT WORKING PROPERLY.	800 USA		18117	812	USA	*	144	PT	811			
80.8	108.8	1.8	8780 *	NA	LA	21801					SPARE WASH CHECKED FOR NO BRIDGE AND THROTTLE PEDAL. BOP CHECKED. FOUND FUSE #18 BLOWN. CHECKED CIRCUIT #40 FOR SHORTS. REMOVED ANTI-START CLUSTER TO GAIN ACCESS TO WIRING. CHECKED FUSED POINT KICK P.	WHEEL FOUND ACCESS POWER CONTROL MODULE CONNECTOR HAD SHORT IN CIRCUIT #40. REPAIRING CIRCUIT REINSTALLED ANTI-START CLUSTER. TESTED OK BUT STILL HAD NO THROTTLE RESPONSE. REPLACED.	Q. CUST SAYS WHILE DRIVING VEH. ALL THE WHEELS SHUT OFF. THROTTLE ENGINE SHUT OFF, BUT BAR PEDAL. WOULD NOT WORK. PULSED ON TRUCK AT TIMES WHEN WHEEL START TRUCK IF ENGINE WAGES. CHECKING. FOUND THE ACCELERATOR NOT WORKING.	800 USA		13207	804	USA	*	144	PT	811			
81.82	128.82	0.8	8481 *	NA	LA	21801					DOES NOT OPERATE PROPERLY. ENGINE PERFORMANCE DEGRADATION. 2.8 IN. IN WASH. ENGINE. THROTTLE OPEN IN THROTTLE WAS HARD TO CONCER THEN MONITOR POS AND FOUND OPEN AT BETWEEN 80 RPM IN THROTTLE. OVERRODE VEHICLE KEY AND RETEST ALL. OK.		CHECK AND ADJUST FOR THROTTLE NOT WORKING AT TIMES. PEDAL ASBY. IS NOT WORKING PROPERLY. ACCELERATOR PEDAL NOT WORKING.	400 CAN		48400	804	CAN	*	144	PT	811			
78.82	87.82	0.4	2517 *	NA	NE	21801					WIRING FOR ACCEL. PEDAL.		BAR PEDAL NOT WORKING	800 USA		18000	2004	USA	*	144	PT	811			
81.82	104.82	1	7916 *	NA	CA	21801					ACCELERATOR PEDAL COMING APART. IN TIME TO REPLACE ACCELERATOR PEDAL.		BLACK TRUCK ACCELERATOR PEDAL NOT WORKING	800 USA		17800	2014	USA	*	144	PT	811			
78.82	102.82	1.2	8481 *	NA	LA	21801					PERFORMER DRAG. DTC P0221 & P0221. READ TWO HAS REPLACED FUEL. PEDAL ASBY.		BAR PEDAL NOT WORKING	800 USA		18220	1404	USA	*	144	PT	811			
81.82	128.82	0.7	808 *	NA	NE	21801					ACCELERATOR PEDAL LOOSE. RE-ASSEMBLE IN PEDAL ASSEMBLY DUE TO PEDAL WOULD NOT GO.		CHECK ACCELERATOR PEDAL. NOT WORKING PROPERLY.	801 USA		18100	2004	USA	*	144	PT	811			
78.84	348.84	2.4	394 *	NA	CA	21801					PROBABLE LINK TEST. INSPECT. EXHAUSTE AND CHANGE WIRING ASBY. REPAIR WIRING. FUEL. ACCESS. WIRING. REPAIR. FUEL. TEST. REPAIR. TEST. OPERATED. TESTED & REPLACED FUEL. THROTTLE PEDAL ASSEMBLY. REPAIR. OPERATION.		AIR COND IS NOT WORKING PROPERLY.	770 USA		11800	2004	USA	*	178	PT	808			
80.4	152.8	0.4	8780 *	NA	SC	21801					REPAIR. TEST. FLAT SPOT IN THE PEDAL. REPLACE PEDAL ASSEMBLY.		BAR PEDAL NOT WORKING PROPERLY.	200 CAN		48200	804	CAN	*	148	PT	811			
81.82	114.82	0.6	888 *	NA	EV	21801					1. PERFORMER TEST. FLAT SPOT IN THE PEDAL. REPLACE PEDAL ASSEMBLY.		AFTER REPAIRS TO GET TRUCK RUNNING. FOUND ACCELERATOR PEDAL AND RESPONSE NOT WORKING.	800 USA		17800	812	USA	*	144	PT	811			
78.82	108.82	0.6	888 *	NA	VA	21801					INSTALL NEW PEDAL ASBY.		CHECK BAR PEDAL. NOT WORKING. BAR PEDAL IS NOT WORKING PROPERLY.	800 USA		17800	2004	USA	*	144	PT	811			
80.4	108.4	0.2	8882 *	NA	NE	21801					REPLACE THE BRACE PEDAL.		BAR PEDAL NOT WORKING PROPERLY.	780 CAN		48800	804	CAN	*	148	PT	811			
81.82	107.82	0.4	8881 *	NA	CA	21801					INSPECT AND VERIFY REPLACE PEDAL ASBY. PLASTIC FOOT CRACK BROKEN. REPLACED FUEL. PEDAL. WAS NOT WORKING PROPERLY.		CUSTOMER STATES THROTTLE PEDAL IS NOT WORKING PROPERLY. FUEL PEDAL IS NOT WORKING PROPERLY. FLAME ADJUST.	800 USA		17400	2004	USA	*	174	PT	808			
80.4	148.8	0.1	88814 *	NA	NE	21801					WORKING PROPERLY.		WORKING PROPERLY.	800 CAN		48800	804	CAN	*	148	PT	811			

TRF. C	ST. GR.	PL. NO.	PL. D.	PL. C.	PL. E.	PL. F.	PL. G.	PL. H.	PL. I.	PL. J.	PL. K.	PL. L.	PL. M.	PL. N.	PL. O.	PL. P.	PL. Q.	PL. R.	PL. S.	PL. T.	PL. U.	PL. V.	PL. W.	PL. X.	PL. Y.	PL. Z.	PL. AA.	PL. AB.	PL. AC.	PL. AD.	PL. AE.	PL. AF.	PL. AG.	PL. AH.	PL. AI.	PL. AJ.	PL. AK.	PL. AL.	PL. AM.	PL. AN.	PL. AO.	PL. AP.	PL. AQ.	PL. AR.	PL. AS.	PL. AT.	PL. AU.	PL. AV.	PL. AW.	PL. AX.	PL. AY.	PL. AZ.	PL. BA.	PL. BB.	PL. BC.	PL. BD.	PL. BE.	PL. BF.	PL. BG.	PL. BH.	PL. BI.	PL. BJ.	PL. BK.	PL. BL.	PL. BM.	PL. BN.	PL. BO.	PL. BP.	PL. BQ.	PL. BR.	PL. BS.	PL. BT.	PL. BU.	PL. BV.	PL. BW.	PL. BX.	PL. BY.	PL. BZ.	PL. CA.	PL. CB.	PL. CC.	PL. CD.	PL. CE.	PL. CF.	PL. CG.	PL. CH.	PL. CI.	PL. CJ.	PL. CK.	PL. CL.	PL. CM.	PL. CN.	PL. CO.	PL. CP.	PL. CQ.	PL. CR.	PL. CS.	PL. CT.	PL. CU.	PL. CV.	PL. CW.	PL. CX.	PL. CY.	PL. CZ.	PL. DA.	PL. DB.	PL. DC.	PL. DD.	PL. DE.	PL. DF.	PL. DG.	PL. DH.	PL. DI.	PL. DJ.	PL. DK.	PL. DL.	PL. DM.	PL. DN.	PL. DO.	PL. DP.	PL. DQ.	PL. DR.	PL. DS.	PL. DT.	PL. DU.	PL. DV.	PL. DW.	PL. DX.	PL. DY.	PL. DZ.	PL. EA.	PL. EB.	PL. EC.	PL. ED.	PL. EE.	PL. EF.	PL. EG.	PL. EH.	PL. EI.	PL. EJ.	PL. EK.	PL. EL.	PL. EM.	PL. EN.	PL. EO.	PL. EP.	PL. EQ.	PL. ER.	PL. ES.	PL. ET.	PL. EU.	PL. EV.	PL. EW.	PL. EX.	PL. EY.	PL. EZ.	PL. FA.	PL. FB.	PL. FC.	PL. FD.	PL. FE.	PL. FF.	PL. FG.	PL. FH.	PL. FI.	PL. FJ.	PL. FK.	PL. FL.	PL. FM.	PL. FN.	PL. FO.	PL. FP.	PL. FQ.	PL. FR.	PL. FS.	PL. FT.	PL. FU.	PL. FV.	PL. FW.	PL. FX.	PL. FY.	PL. FZ.	PL. GA.	PL. GB.	PL. GC.	PL. GD.	PL. GE.	PL. GF.	PL. GG.	PL. GH.	PL. GI.	PL. GJ.	PL. GK.	PL. GL.	PL. GM.	PL. GN.	PL. GO.	PL. GP.	PL. GQ.	PL. GR.	PL. GS.	PL. GT.	PL. GU.	PL. GV.	PL. GW.	PL. GX.	PL. GY.	PL. GZ.	PL. HA.	PL. HB.	PL. HC.	PL. HD.	PL. HE.	PL. HF.	PL. HG.	PL. HH.	PL. HI.	PL. HJ.	PL. HK.	PL. HL.	PL. HM.	PL. HN.	PL. HO.	PL. HP.	PL. HQ.	PL. HR.	PL. HS.	PL. HT.	PL. HU.	PL. HV.	PL. HW.	PL. HX.	PL. HY.	PL. HZ.	PL. IA.	PL. IB.	PL. IC.	PL. ID.	PL. IE.	PL. IF.	PL. IG.	PL. IH.	PL. II.	PL. IJ.	PL. IK.	PL. IL.	PL. IM.	PL. IN.	PL. IO.	PL. IP.	PL. IQ.	PL. IR.	PL. IS.	PL. IT.	PL. IU.	PL. IV.	PL. IW.	PL. IX.	PL. IY.	PL. IZ.	PL. JA.	PL. JB.	PL. JC.	PL. JD.	PL. JE.	PL. JF.	PL. JG.	PL. JH.	PL. JI.	PL. JJ.	PL. JK.	PL. JL.	PL. JM.	PL. JN.	PL. JO.	PL. JP.	PL. JQ.	PL. JR.	PL. JS.	PL. JT.	PL. JU.	PL. JV.	PL. JW.	PL. JX.	PL. JY.	PL. JZ.	PL. KA.	PL. KB.	PL. KC.	PL. KD.	PL. KE.	PL. KF.	PL. KG.	PL. KH.	PL. KI.	PL. KJ.	PL. KK.	PL. KL.	PL. KM.	PL. KN.	PL. KO.	PL. KP.	PL. KQ.	PL. KR.	PL. KS.	PL. KT.	PL. KU.	PL. KV.	PL. KW.	PL. KX.	PL. KY.	PL. KZ.	PL. LA.	PL. LB.	PL. LC.	PL. LD.	PL. LE.	PL. LF.	PL. LG.	PL. LH.	PL. LI.	PL. LJ.	PL. LK.	PL. LL.	PL. LM.	PL. LN.	PL. LO.	PL. LP.	PL. LQ.	PL. LR.	PL. LS.	PL. LT.	PL. LU.	PL. LV.	PL. LW.	PL. LX.	PL. LY.	PL. LZ.	PL. MA.	PL. MB.	PL. MC.	PL. MD.	PL. ME.	PL. MF.	PL. MG.	PL. MH.	PL. MI.	PL. MJ.	PL. MK.	PL. ML.	PL. MM.	PL. MN.	PL. MO.	PL. MP.	PL. MQ.	PL. MR.	PL. MS.	PL. MT.	PL. MU.	PL. MV.	PL. MW.	PL. MX.	PL. MY.	PL. MZ.	PL. NA.	PL. NB.	PL. NC.	PL. ND.	PL. NE.	PL. NF.	PL. NG.	PL. NH.	PL. NI.	PL. NJ.	PL. NK.	PL. NL.	PL. NM.	PL. NN.	PL. NO.	PL. NP.	PL. NQ.	PL. NR.	PL. NS.	PL. NT.	PL. NU.	PL. NV.	PL. NW.	PL. NX.	PL. NY.	PL. NZ.	PL. OA.	PL. OB.	PL. OC.	PL. OD.	PL. OE.	PL. OF.	PL. OG.	PL. OH.	PL. OI.	PL. OJ.	PL. OK.	PL. OL.	PL. OM.	PL. ON.	PL. OO.	PL. OP.	PL. OQ.	PL. OR.	PL. OS.	PL. OT.	PL. OU.	PL. OV.	PL. OW.	PL. OX.	PL. OY.	PL. OZ.	PL. PA.	PL. PB.	PL. PC.	PL. PD.	PL. PE.	PL. PF.	PL. PG.	PL. PH.	PL. PI.	PL. PJ.	PL. PK.	PL. PL.	PL. PM.	PL. PN.	PL. PO.	PL. PP.	PL. PQ.	PL. PR.	PL. PS.	PL. PT.	PL. PU.	PL. PV.	PL. PW.	PL. PX.	PL. PY.	PL. PZ.	PL. QA.	PL. QB.	PL. QC.	PL. QD.	PL. QE.	PL. QF.	PL. QG.	PL. QH.	PL. QI.	PL. QJ.	PL. QK.	PL. QL.	PL. QM.	PL. QN.	PL. QO.	PL. QP.	PL. QQ.	PL. QR.	PL. QS.	PL. QT.	PL. QU.	PL. QV.	PL. QW.	PL. QX.	PL. QY.	PL. QZ.	PL. RA.	PL. RB.	PL. RC.	PL. RD.	PL. RE.	PL. RF.	PL. RG.	PL. RH.	PL. RI.	PL. RJ.	PL. RK.	PL. RL.	PL. RM.	PL. RN.	PL. RO.	PL. RP.	PL. RQ.	PL. RR.	PL. RS.	PL. RT.	PL. RU.	PL. RV.	PL. RW.	PL. RX.	PL. RY.	PL. RZ.	PL. SA.	PL. SB.	PL. SC.	PL. SD.	PL. SE.	PL. SF.	PL. SG.	PL. SH.	PL. SI.	PL. SJ.	PL. SK.	PL. SL.	PL. SM.	PL. SN.	PL. SO.	PL. SP.	PL. SQ.	PL. SR.	PL. SS.	PL. ST.	PL. SU.	PL. SV.	PL. SW.	PL. SX.	PL. SY.	PL. SZ.	PL. TA.	PL. TB.	PL. TC.	PL. TD.	PL. TE.	PL. TF.	PL. TG.	PL. TH.	PL. TI.	PL. TJ.	PL. TK.	PL. TL.	PL. TM.	PL. TN.	PL. TO.	PL. TP.	PL. TQ.	PL. TR.	PL. TS.	PL. TT.	PL. TU.	PL. TV.	PL. TW.	PL. TX.	PL. TY.	PL. TZ.	PL. UA.	PL. UB.	PL. UC.	PL. UD.	PL. UE.	PL. UF.	PL. UG.	PL. UH.	PL. UI.	PL. UJ.	PL. UK.	PL. UL.	PL. UM.	PL. UN.	PL. UO.	PL. UP.	PL. UQ.	PL. UR.	PL. US.	PL. UT.	PL. UU.	PL. UV.	PL. UW.	PL. UX.	PL. UY.	PL. UZ.	PL. VA.	PL. VB.	PL. VC.	PL. VD.	PL. VE.	PL. VF.	PL. VG.	PL. VH.	PL. VI.	PL. VJ.	PL. VK.	PL. VL.	PL. VM.	PL. VN.	PL. VO.	PL. VP.	PL. VQ.	PL. VR.	PL. VS.	PL. VT.	PL. VU.	PL. VV.	PL. VW.	PL. VX.	PL. VY.	PL. VZ.	PL. WA.	PL. WB.	PL. WC.	PL. WD.	PL. WE.	PL. WF.	PL. WG.	PL. WH.	PL. WI.	PL. WJ.	PL. WK.	PL. WL.	PL. WM.	PL. WN.	PL. WO.	PL. WP.	PL. WQ.	PL. WR.	PL. WS.	PL. WT.	PL. WU.	PL. WV.	PL. WW.	PL. WX.	PL. WY.	PL. WZ.	PL. XA.	PL. XB.	PL. XC.	PL. XD.	PL. XE.	PL. XF.	PL. XG.	PL. XH.	PL. XI.	PL. XJ.	PL. XK.	PL. XL.	PL. XM.	PL. XN.	PL. XO.	PL. XP.	PL. XQ.	PL. XR.	PL. XS.	PL. XT.	PL. XU.	PL. XV.	PL. XW.	PL. XX.	PL. XY.	PL. XZ.	PL. YA.	PL. YB.	PL. YC.	PL. YD.	PL. YE.	PL. YF.	PL. YG.	PL. YH.	PL. YI.	PL. YJ.	PL. YK.	PL. YL.	PL. YM.	PL. YN.	PL. YO.	PL. YP.	PL. YQ.	PL. YR.	PL. YS.	PL. YT.	PL. YU.	PL. YV.	PL. YW.	PL. YX.	PL. YY.	PL. YZ.	PL. ZA.	PL. ZB.	PL. ZC.	PL. ZD.	PL. ZE.	PL. ZF.	PL. ZG.	PL. ZH.	PL. ZI.	PL. ZJ.	PL. ZK.	PL. ZL.	PL. ZM.	PL. ZN.	PL. ZO.	PL. ZP.	PL. ZQ.	PL. ZR.	PL. ZS.	PL. ZT.	PL. ZU.	PL. ZV.	PL. ZW.	PL. ZX.	PL. ZY.	PL. ZZ.
01.02	18.77	2.4	1880	MA	TH	31801	REPLACE TP SERVICE AND PEDAL ASSEMBLY AND PEDAL PHOTO AND BRASS FROM KIT. REPLACED WITH	NO TECH INFO	CHECK GAS PEDAL NOT WORKING AT TIMES	670 USA	17100	1 USA	104	PT	011																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																															
08.08	26.76	2.4	2020	MA	CA	31801	REPLACE PEDAL ASSEMBLY CHECK GAS PEDAL NOT WORKING PERFORM BMS TEST PERFORM TEST MONITOR TEST FINAL CLACK TEST CHECK AND REPLACE BRASS SWITCH CHECK AND REPLACE ALL FUEL CHECK OK IN TIME TO REPLACE BRASS PEDAL SWITCH KIT	NO TECH INFO	GAS PEDAL NOT WORKING PROPERLY	1 USA	17100	1 USA	104	PT	011																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																															
14.08	27.28	1.8	2020	MA	NY	31801	NO TECH INFO	ON OPERATION IN BOOK	CUST STATED WHEN TAKING TURN AT 10-20 MPH GAS PEDAL NOT WORKING NOT FUNCTION	670 USA	18004	2 USA	104	PT	011																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																															
08.01	11.17	2.4	2722	MA	SC	31801	REPLACE GAS PEDAL ASSEMBLY CHECK FOR FUEL CODES P0271, C0085 AND FURTHER TESTED MANAGES	NO TECH INFO	REPAIR GAS PEDAL NOT OPERATING PROPERLY	380 CAN	26200	1 CAN	104	PT	011																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																															
08.01	24.77	2.4	2722	MA	CA	31801	REPLACE PEDAL ASSEMBLY AND ACCELERATOR TEST DRIVE ACCELERATOR NOT WORKING. FIN POINT CHECKS OK. FUEL PUMP ACCELERATOR PEDAL. RETEST PROBLEM FIXED	NO TECH INFO	PEDAL DOES NOT OPERATE PROPERLY	680 USA	17200	1 USA	117	PT	008																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																															
08.01	24.77	2.4	2722	MA	CA	31801	REPLACE PEDAL ASSEMBLY AND ACCELERATOR TEST DRIVE ACCELERATOR NOT WORKING. FIN POINT CHECKS OK. FUEL PUMP ACCELERATOR PEDAL. RETEST PROBLEM FIXED	NO TECH INFO	CUSTOMER STATED THE ACCELERATOR IS NOT OPERATING PROPERLY	100 USA	21470	1 USA	104	PT	011																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																															
01.02	118.76	2.4	980	MA	VA	31801	REPLACE ACCELERATOR PEDAL ASSEMBLY DID NOT WORK WHILE CHECKING ON STARTER CHECKING THAT ACCELERATOR PEDAL IS SHOWN. PEDAL FEEL HAS SEPARATED FROM ARM. REPLACE ACCELERATOR PEDAL ASSEMBLY. OK	WIRING CONNECTED. MY LEAD WAS TO NO LEAD OF FOR NON ADJUSTABLE PEDAL.	NOTED WHILE IN SHOP. ACCELERATOR PEDAL NOT OPERATING PROPERLY. OK ACCELERATOR NOT REPAIR WHEN ACCELERATED	640 USA	17200	1 USA	104	PT	011																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																															
01.01	18.09	1	880	MA	VA	31801	REPLACE ACCELERATOR PEDAL ASSEMBLY. OK	NO TECH INFO	NO PEDAL REACTION	270 USA	17100	1 USA	104	PT	011																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																															
08.08	24.76	4	2020	MA	TX	31801	REPLACE ACCELERATOR PEDAL ASSEMBLY. OK	NO TECH INFO	NO PEDAL REACTION	680 USA	18000	1 USA	104	PT	011																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																															
01.02	20.18	4.3	2020	MA	AZ	31801	PERFORMED BMS TEST T4 OK 4.800ST 16.000RND BLUEZ AND ACCEL. ALL FUEL PRESSURE FUEL CODES. FUEL PRESSURE IS FUEL LOW. STABILITY AND THROTTLE PEDAL GOOD OK	NO THROTTLE PEDAL.	CUSTOMER STATES THROTTLE HAS NO RESPONSE AT TIMES IN MANUALLY	620 USA	48000	1 USA	104	PT	011																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																															
08.04	126.18	0.6	2010	MA	NY	31801	REPLACE THROTTLE PEDAL ASSEMBLY AND TEST THROTTLE POSITION SENSOR CODES FIN POINT GAS FUEL THROTTLE POSITION SENSOR AND REPLACE T POSITION SENSOR	NO TECH INFO	THROTTLE WILL NOT THROTTLE UP	377 USA	48700	1 USA	104	PT	011																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																															
01.02	122.85	0.6	1180	MA	OR	31801	PERFORM BMS TEST T4 OK 4.800ST 16.000RND BLUEZ AND ACCEL. ALL FUEL PRESSURE FUEL CODES. FUEL PRESSURE IS FUEL LOW. STABILITY AND THROTTLE PEDAL GOOD OK	NO TECH INFO	INTERMITTENT LOSS OF THROTTLE	1 USA	48700	1 USA	104	PT	011																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																															
08.08	24.77	4.4	2722	MA	CA	31801	PERFORM BMS TEST T4 OK 4.800ST 16.000RND BLUEZ AND ACCEL. ALL FUEL PRESSURE FUEL CODES. FUEL PRESSURE IS FUEL LOW. STABILITY AND THROTTLE PEDAL GOOD OK	NO TECH INFO	CUSTOMER STATES THAT VEHICLE WAS NOT THROTTLE THROTTLE POSITION SENSOR CODES FIN POINT GAS FUEL THROTTLE POSITION SENSOR AND REPLACE T POSITION SENSOR	CUSTOMER STATES THAT VEHICLE WAS NOT THROTTLE THROTTLE POSITION SENSOR CODES FIN POINT GAS FUEL THROTTLE POSITION SENSOR AND REPLACE T POSITION SENSOR	640 USA	17100	1 USA	117	PT	008																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																														
01.02	27.28	4.1	2020	MA	AZ	31801	PERFORM BMS TEST T4 OK 4.800ST 16.000RND BLUEZ AND ACCEL. ALL FUEL PRESSURE FUEL CODES. FUEL PRESSURE IS FUEL LOW. STABILITY AND THROTTLE PEDAL GOOD OK	NO TECH INFO	CUSTOMER STATES THAT VEHICLE WAS NOT THROTTLE THROTTLE POSITION SENSOR CODES FIN POINT GAS FUEL THROTTLE POSITION SENSOR AND REPLACE T POSITION SENSOR	620 USA	17100	1 USA	104	PT	011																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																															
08.08	24.76	1.8	2020	MA	NY	31801	PERFORM BMS TEST T4 OK 4.800ST 16.000RND BLUEZ AND ACCEL. ALL FUEL PRESSURE FUEL CODES. FUEL PRESSURE IS FUEL LOW. STABILITY AND THROTTLE PEDAL GOOD OK	NO TECH INFO	CUSTOMER STATES THAT VEHICLE WAS NOT THROTTLE THROTTLE POSITION SENSOR CODES FIN POINT GAS FUEL THROTTLE POSITION SENSOR AND REPLACE T POSITION SENSOR	610 USA	17100	1 USA	104	PT	011																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																															

MTPL	CD	ST	OR	NR	DL	CL	EC	ON	CD	ROW	CMPL	TRCH	DTX	TRCH	DTX	TRCH	DTX	AREA	COUNT	BL	DLTSM	ENTRY	ENTRNO	AMT	VRT	TR		
CD	OR	NR	DL	CL	EC	ON	CD	ROW	CMPL	TRCH	DTX	TRCH	DTX	TRCH	DTX	TRCH	DTX	CD	RT	CD	R	CD	CD	CD	CD	CD	CD	
01.02	148.00	1	1792	NA	PA	21801						0-2000 AND USMIPED CONCERN FOR BMC TEST AND ALL PASSED CODES. PERFORMED PERFORM TEST AND FOLLO ACCELERATOR PEDAL BAD, REMOVED AND REPLACED PEDAL AND RECHECKED FOR CODES AND NONE FOUND, PERFORM TEST	2 AND ALL OK	CHECK CUSTOMER STATES THAT THE VEHICLE SEEMS IN THE AM COLD THE VEHICLE WILL NOT RESPOND TO FUEL PEDAL WILL JUST	724	USA	144000000	USA	*	NA1	3.0	011						
01.02	128.71	2.0	2014	NA	CA	21801						3 NEW ACCEL PEDAL 3 NEW VEHICLE CONCERN. BSG TEST CONTAINS P0221 P0221. REPLACED ACCEL. PEDAL DUE TO INTERMITTENT FAULT. DA/SMAL SPIN CODE		CUSTOMER STATES ENGINE DOESNT RESPOND TO ACCELERATORS AT TIME NOT 2 TIMES IN 2 HRS	800	USA	171400000	USA	*	NA1	1.1	011						
70.00	200.46	2.0	2020	NA	AZ	21801						CALLED FORD HOTLINE AND CONTACT OF 318 DED 318 NO RELATED INFO PER CONCERN. FOUND INTERMITTENT OPEN CIRCUIT IN PEDAL. ASBY ELECTRICAL CODE P0221 AND REPROGRAM PCM UPDATE PCM. 10/08/00 NO. TEST DRIVE TO	VERIFY. PEELE SLOW TO RESPOND TO ACCEL. AND AT TIMES PEELE STOP. PERFORM T3 DIT TESTS SHEET HGS INSTALLED CODES P0221 PERFORM PERFORM TESTS AND REPLACED ACCEL. PEDAL ASBY. TEST DRIVE 3 TO 4 HOURS ON HILLS	CUSTOMER STATES ON ACCEL. VEHICLE SEEMS TO NOT RESPOND TO ACCEL PEDAL UNTIL PRESSED HARD	400	USA	1711170	2	USA	*	NA1	1.7	011					
01.02	184.00	0.0	2000	NA	NV	21801						WIL ON RPM NORMALLY. REC 1000 PR122/021. NOISE/CLACK PASS. PERFORM TEST. PDS AT 30 TVE OFF. AT ONLY ON POSSIBLE GAS PEDAL. INTERMITTENT ONLY PASS AT THIS TIME. REPLACED GAS PEDAL. CLEAR CODES		CUSTOMER STATES TO CHECK FOR CAUSE WHEN ACCELERATING AT TIMES ENGINE WILL NOT RESPOND LIKE GAS PEDAL IS NOT WORKING IN	770	USA	180000000	USA	*	NA1	1.1	011						
01.02	101.00	0.4	4300	NA	TX	21801						ACCELERATOR PEDAL REMOVED AND FOUND ONE PEDAL VIN NUMBER REPLACED PEDAL ASSEMBLY NCP		ACCELERATOR DOES NOT WORK PROPERLY CUSTOMER STATES GAS PEDAL NOT WORKING PROPERLY	840	USA	100000000	USA	*	NA1	1.7	011						
01.02	120.00	0.0	2000	NA	TX	21801						TEST REFL. ACCELERATOR PEDAL SWITCH RETEST PERFORM		CUSTOMER STATES ENGINE DROPS TO IDLE WHILE DRIVING AT TIMES	800	USA	100000000	USA	*	NA1	1.0	011						
70.00	100.00	0.4	0777	NA	MO	21801						TEST BMC SYSTEMS/ACC P0221/P0222/021 TEST WITH MONITOR. PERFORM TEST. AT TIME TO REFL. GAS PEDAL. ENGINE ASBY FOR WILL NOT ACCELERATE AT TIMES CONCERN		CUSTOMER STATES ENGINE DROPS TO IDLE WHILE DRIVING AT TIMES	700	USA	100000000	USA	*	NA1	1.0	011						
01.02	187.00	1.0	2020	NA	NM	21801						SWITCH FAILURE. REPLACED PEDAL ASBY. ROAD TEST NORMAL OPERATION DATED 10/10/00		CUSTOMER STATES ACCELERATOR PEDAL IN OP OR AND ADVISE PERFORMED ENGINE PERFORMANCE DMS 1 14 ACCEL PEDAL INTERNAL	800	USA	100000000	USA	*	NA1	1.0	011						
01.02	277.00	0.7	1730	NA	GA	21801						ACCELERATOR PEDAL ASSEMBLY ADJUSTABLE REPLACE		NO RESPONSE WHEN YOU PRESS GAS PEDAL	700	USA	100000000	USA	*	NA1	1.0	011						
70.00	200.00	2.7	0840	NA	TN	21801						PERFORM ENGINE PERFORMANCE TESTS 1 4/RECEIVED CODE P0221 PERFORM PERFORM TEST/POSSIBLE TP SENSOR ERRATIC. REPLACE TP SENSOR AND ACCEL. PEDAL ASBY. RETEST. 11/11/00		CUSTOMER STATES ENGINE DROPS TO IDLE WHILE DRIVING AT TIMES	800	USA	100000000	USA	*	NA1	1.7	011						
70.00	200.00	2.7	0840	NA	TN	21801						FOUND CODE P 0221 PEDAL ASBY OPEN CIRCUIT INTERMITTENTLY LOSS OF TP SENSOR. HAVE VEHICLE TELL MENDRY PER S A. CALLED CUSTOMER FOR MORE INFO. SAYS IT GOES IN AND OUT OF BEANS LINE NO ACCEL. OR IN INTERNAL	AT HIGH SPEEDS AND HOT OUTSIDE. IN TOWN TRAFFIC. STOP AND GO DRIVING. TEST DRIVE TO VERIFY. INTERMITTENTLY NO RESPONSE FROM ACCEL PEDAL AT TIMES. PERFORM T3 TEST TESTS SHEET CODES P0221 THROTTLE POS	CUSTOMER STATES ENGINE DROPS TO IDLE WHILE DRIVING AT TIMES	800	USA	100000000	USA	*	NA1	1.7	011						
70.00	100.00	0.0	0001	NA	OR	21801								CUSTOMER STATES ENGINE DROPS TO IDLE WHILE DRIVING AT TIMES	800	USA	100000000	USA	*	NA1	1.7	011						

TOT COLER		JUR		BU INDI		ST P		MTR_C ST_DR		HR CLR_C		C CLR_C		OPW		TRCH_DTY		TRCH_DTY		CRMT_DTY		AREA-COUNT		SUB-DI-TION		CHTRY-INT		ANAL		TTL		
CHT	CHS	E	J	D	D	CO	CO	CO	CO	CO	CO	CO	CO	CO	CO	CO	CO	CO	CO	CO	CO	CO	CO	CO	CO	CO	CO	CO	CO	CO		
78.05	180.18	1.4	7899	NA	NY	31801																	781	USA	171188	USA	USA	1944	NY	811		
48	190.3	2.1	7922	NA	LA	31801																		888	USA	122047	USA	USA	1949	TX	811	
81.82	187	1.1	4828	NA	FL	31801																		884	USA	120888	USA	USA	1948	TX	811	
84.20	140.21	1.1	8889	NA	OK	31801																			888	USA	108888	USA	USA	1941	TX	811
78.85	181.28	1.3	8418	NA	LA	31801																			888	USA	122143	1	USA	1941	TX	811
81.82	281.81	4.4	8388	NA	CA	31801																			888	USA	108888	USA	USA	1941	TX	811
81.82	323.8	3.8	8328	NA	MO	31801																			818	USA	147888	2	USA	1948	TX	811
84.1	288.81	3.8	8888	NA	AR	31801																			888	USA	488888	2	USA	1941	TX	811
81.82	284.81	3.7	4448	NA	TX	31801																			881	USA	108888	USA	USA	1948	TX	811
80.81	85.4	0.4	8813	NA	TX	31801																			888	USA	108888	USA	USA	1944	TX	811
78.85	181.21	1.7	4887	NA	TX	31801																			881	USA	108888	1	USA	1949	TX	811
81.82	188.81	0.8	8821	NA	TX	31801																			715	USA	108888	USA	USA	1941	TX	811
78.85	181.28	1.8	4888	NA	TX	31801																			881	USA	108888	USA	USA	1944	TX	811
81.82	141.81	1	888	NA	MO	31801																			881	USA	108888	USA	USA	1948	TX	811

PE03-044-A 6092

YOT	CO	LNK	BU	ST	PL	MTPL	C	ST	OR	NR	CL	D	E	G	ON	C	TR	OP	TR	TR	AREA	COUNT	S	R	ES	TR	CONTR	DRT	VPS	Y	M	PLA					
001	002	003	004	005	006	007	008	009	010	011	012	013	014	015	016	017	018	019	020	021	022	023	024	025	026	027	028	029	030	031	032	033					
78.00	184.71	0.6	2890	MA	MA	21801																															
78.00	178.00	1.6	1280	MA	MA	21801																															
78.00	128.00	1	8700	MA	MA	21801																															
80.84	98.8	0.2	1880	MA	MA	21801																															
80.84	271.00	1.6	2000	MA	MA	21801																															
81.82	123.00	0.8	1870	MA	MA	21801																															
81.82	137.20	0.9	8700	MA	MA	21801																															
80.77	88.77	3	2000	MA	MA	21801																															
80.84	98.8	0.2	8700	MA	MA	21801																															
78.00	100.00	1.6	7000	MA	MA	21801																															
81.82	100.00	1.2	8700	MA	MA	21801																															
78.00	88.80	2.1	8700	MA	MA	21801																															
78.00	114.20	0.7	8700	MA	MA	21801																															
78.00	100.00	0.8	8700	MA	MA	21801																															

PE03-044-A 6096

TOT. COLS	BLK	ST. P	DRAG	TRCH	TRCH	TRCH	AREA	COUNT	BLK	TOTL	CNTRY	ORIG	PLANT	TEL								
UTRNL	ST. GR	HR	DRUG	BLK	CHLD	NOV	CD	CD	CD	CD	CD	CD	CD	CD								
QTY	QTY	E	D	D	D	CD	CD	CD	CD	CD	CD	CD	CD	CD								
7888	34675	43	1288	*	NA	PL	3581															
				VERIFIED DIAGNOSIS PERFORMING ENGINE TESTS AND TEST 1 IN PERFORM TEST REPLACED PEDAL ASSEMBLY CONCERN CORRECTED								CUSTOMER STATES ON HARD ACCELERATION LOSES POWER GOES TO SOLID CHECK AND ADV				328	USA	13443	USA	144	PT	811
8534	22845	14	787	*	NA	TX	3187															
				4728 8788 TIME TO CK FUEL OIL CK AIR SHORT INSPECTION OK RUN ROAD NOISE OIL PRESSURE PERFORM TEST PE REY REPLACED ACCEL PEDAL SHORTED CLEANED COOBS RE TEST P1111 CHECKED AP NOT WORKING AT TIMES MONITOR AP PRESSURE GAGE AT PARTIAL THROTTLE REPLACED PEDAL UNIT RE TEST GOOD NOW								THE CUST STATES THE WHEN YOU PUSH ACCL NOTHING HAPPENS ENGINE MECHANICAL ACCELERATOR PEDAL REACTS DIFFERENT ENGINE BLUE ACT WIDE OPEN THROTTLE				872	USA	18228	USA	141	PT	811
884	17112	17	8882	*	NA	AR	2180															
				W/ THE GAGE VISIBLE TO FRONT AND SERVICE MGR AND LET THEM DRIVE DRIVE OK BY THEM								WHEN PRESS ACCELERATOR TO BLOCK W/LL NOT FULL				78	USA	48820	USA	154	PT	811
8148	17188	14	888	*	NA	SC	2180															
												WHEN PRESS ACCELERATOR TO BLOCK W/LL NOT FULL				88	USA	17088	USA	151	PT	811