

PE03-044
FORD
5/13/2005
APPENDIX I
BOOK 12 OF 28
PART 3 OF 4

[REDACTED]

From: McDonagh, Scot (S.M.)
Sent: Tuesday, June 24, 2003 10:09 AM
To: Kramer, Michael (M.T.); Toporek, John (J.T.); West, Gregory (G.S.); Liposky, Lawrence (L.J.); Enerson, David (D.W.); DiCicco, Tamara (T.K.)
Subject: SSM# 16913-7.3L accelerator Pedal wire chaffing

FYI

Scot G. McDonagh
Super-Duty/Excursion
Powertrain Quality Leader
Phone-(313)337-8091
Fax-(313)621-8082
E-Mail:smcdonag@ford.com

-----Original Message-----

From: Stollfuss, Joshua (J.)
Sent: Tuesday, June 24, 2003 9:42 AM
To: McDonagh, Scot (S.M.)
Subject: FW: 097-2003-0447 R1 SSM 2002 Super Duty F-Series 7.3L build dates p (FCSD Global Template v1.1 Notification)

SSM on 7.3L accelerator Pedal wire chaffing is now active as SSM 16913.

Joshua Stollfuss
Product Concern Engineer E-Series, PVT & Field Support, FCSD.
DSC II Cube 540 1800 Fairlane Dr, Allen Park Mi 48101
Phone 313-323-9892 Fax 313-390-4457
Pager 313-754-1790 Email jstollfu@ford.com

-----Original Message-----

From: mvanholl@ford.com [mailto:mvanholl@ford.com]
Sent: Tuesday, June 24, 2003 9:37 AM
To: jstollfu@ford.com
Subject: 097-2003-0447 R1 SSM 2002 Super Duty F-Series 7.3L build dates p (FCSD Global Template v1.1 Notification)

*(Begin automated email)

PRIVILEGED AND CONFIDENTIAL
Confidential Information - Do Not Distribute
*** DRAFT ***

This message is being sent on behalf of mvanholl to aferna27@ford.com, kmontgol@ford.com, techhot@ford.com, newspecs@brownart.com, kpasanen@ford.com, whawkin1@ford.com, jstollfu@ford.com, vhart1@ford.com, amaqbo01@ford.com, rsmit291@ford.com, jsprunge@ford.com for purposes of email compatibility.
You are requested to provide input to the author of this message. Forward/send any comments to the author of this message only.

Comments:
This is now active.

Author: JSTOLLFU
Request Type: SSM
Title (subject): 2002 Super Duty F-Series 7.3L build dates prior to 12/1/2001 - Repeat P0122, P0123, P0221 DTC's after replacement of the accelerator pedal sensor

PE83-644 5788

Applications:

(application 1) 2002 F-250, 350, 450, 550. 7.3L diesel 01 Jul 2001 01 Dec 2001

Activity Code: 070 F-SERIES >8500#

QSF/Non-QSF Status: Non-QSF Item

Tracking Number: 097-2003-0447 R1

Is this publication a SPECS concern? Yes

Does this request supersede an active TSB/SSM/ISM? No

TSB/SSM/ISM to supersede:

Message Type: Final

Are Service Chemicals being used? No

Other applicable articles:

Date repair procedure was verified: 6/9/2003 4:00:00 PM

Procedure verified by CDSID: RABAR

Procedure Verification Method: F-superduty powertrain team has verified the information.

Are parts required? No

Are illustrations required? No

Contact information for additional illustrations:

CDSID:

Name:

Phone:

Illustration notes:

Is Calibration CD required? No

Calibrations:

Has a White Paper or Certification Wire been sent to VEE? N/A Date White Paper or Certification Wire sent to VEE: 12:00:00 AM Have you completed a part request for the calibrations listed? N/A Do you have access to a vehicle for time study? N/A Contact for vehicle CDSID: Trustmarks that apply: Ford

Article Distribution: WDMO; NA: Canada, Mexico, United States

OASIS Service Codes: 203200 404000 698298

Causal Basic Part # or Finis Code:

Issue/Cause TSB or SSM Text:

Some 2002 Super Duty F-Series vehicles equipped with a 7.3L, with build dates prior to 12/1/2001, may exhibit repeat P0122, P0123, P0221 DTC's after replacement of the accelerator pedal sensor. If repeat codes occur verify that no shorting or chafing conditions exist on the 14401 wire assembly at the left hand shock tower, or the accelerator pedal circuits at connector C2040. If circuits are damaged or shorted repair the wire, then add convolute to protect the wire or use a wire tie strap to retain wiring clear of the shock tower.

Repair Action TSB:

Service Procedure TSB:

WERS Notice Number, Date Released in WERS

QSF single agenda date/program FRC date: 12:00:00 AM

Parts:

Special instructions/remarks:

Repairs Per 1000 Vehicles: 0

Year(s) of Vehicles:

Criticality of Fix: Dependability perceived affected

Repair quantity needed as estimated by engineers: 0

Is geographic location significant? No

If Yes, Vehicle Populations:

United States: 0

Ford of Canada: 0

Association: 0

Ford of Mexico: 0

Europe: 0

Direct: 0

PE03-044 5787

Asia/Pacific: 0
South America: 0
WDMO: 0
Aston Martin: 0
Mazda: 0
Ford: 0
Mercury: 0
Jaguar: 0
Think: 0
Land Rover: 0
Volvo: 0
Lincoln: 0
Nissan: 0
VW: 0

SSM Number: 16913

BCM Number: 0512


Last act taken (as of 24-Jun-2003, 9:36:57 AM): Final/Complete

(End automated email)"

PE03-044 5788


Quarterback Meeting Summary

3/11/2003	PTAI	<u>Emerging Issue:</u> Engine Heat/Surge when accel., part: ETC pedal, are we producing good vehicles today? should conduct plant audit, send data	Brian Wolfe	3/19/2003	Open	E-Tracker 328534, Larry Liposky E-Tracker closed. KTP Quality Office conducted 200 vehicle audit 3/12/03. 14R fixed
-----------	------	--	-------------	-----------	------	---


- 
1. Spring tester
 2. too much grease on ocul
 - 3.
-

1. Update Road Map - m-can
2. Copies of ~~the~~ Control Plans - signed
CC/SC - signed
3. Update Tier 2 list - 8/30/01 - Ben
motor mount bracket
4. U137/P131 Launch Concern - update
5. List of PPAP By today - ^{m.} can
6. List Thursday Post-PPAP - ^{m.} can
7. Action
plans
for everything not capable

Original Test Data – Recorded 10/6/99



Retest Data – Recorded 2/11/00



File name: U137 Test Data
Originator: Greg Rutkowski



Date: 2/18/00

Subject: U137 ETC -- Failed part at APG

Notes: Alan Farrah and Greg Rutkowski visited APG to review a vehicle with an intermittent condition on the Electronic Throttle Control. We measured the Idle and WOT voltages and transition voltage in vehicle to ensure the part met the functional requirements listed on the drawing. The multi meter was installed into the vehicle and the results are listed below:

Failed pedal:

	Vehicle w/engine not running	Vehicle engine running
Applied Voltage	12.38 V	13.40 V
Idle Voltage	.616 V	.615 V
Switch Transition voltage	1.66 V	1.75 V

Replacement Pedal

	Vehicle w/engine not running	Vehicle engine running
Applied Voltage	12.39 V	13.26 V
Idle Voltage	.695 V	.695 V
Switch Transition voltage	1.02 V	1.03 V

The specification for transition voltage is .085 V above the idle voltage and a maximum of 1.50 V. Based on the initial readings in vehicle we were able to determine that the transition voltage caused the intermittent condition. A further analysis needs to be performed on the part to determine root cause.

File name: U137 ETC APG
Originator: Greg Rutkowski

1

2/18/00

2/10/03

- Code 5 @ launch est to remain in effect 60-90 days.
- Seed every dealer who sold more than 10 retail
- Hold owner letters 60-90 days

Light orders 3 per DCR max at any order
6 per week max

VIN
customer name & address

note that stock units

Bulletin: only
Should ~~not~~ be replacing parts on vehicles with
check engine lights "on".

Can we withhold involved vehicle listing from dealers until owner letters.

DCR to pick-stock, interim, emergency

Seed-stock orders.

Small DCR's - OK for part on shelf w/ phone call.

SERVICE PART: 2C3Z- 9F836-DE PEDAL
 ENGINEERING PART: 2C34 9F836 DF
 SUPPLIER LOC:
 Vendor Part:
 Motorcraft Part:

ORIGIN: WERS
 FINIS: 4476733
 Prime Suplr: T0710
 Role: M

-----Inventory----- -----Stocking Demand-----
 FCSD Available: 1775 Current Month: 374
 Pkgr Available: 0 Prior Month: 1143
 In-Trans Pkgr: 0 Prior Month 2: 1168
 In-Trans FCSD: 1034 Prior Month 3: 1498
 Transfers: 427 Curr Forecast: 1148
 Back Ord Pcs: 0 6-Mo Forecast: 6888
 Tot Inventory: 3236 Out of Tolerance: N
 Tot Curr Pos: 15416 Back Ord Lines: 0
 Est'd Max Pos: 4648 Off B/O Date:
 Firm Release: Y Unit Issue: 1
 AIMS Inventory: 200 Pnd Obs:
 F1=Help F2=GEMA F4=PrvPart F5=NxtPart F6=BOLA F9=DEEA F10=HIA
 F11=CPHA F13=SYKA F14=SMKA F15=SCKA F16=ISBA F17=LXEA F18=RXEA F19=DRIA
 RECORD FOUND
 LP8DM74

3236
~~3000~~
 6236
 28000
 31,236
 6,000 9/10/03
 25,236

check for P/N
 Roll from
 DF to DG
 9327 Sales 2002

1/9/03 - rec by Tech Review
 Jan 03 FRC. Advised part
 avail. date. Per Kim ok
 for FRC, we will pull the
 trigger when we are ready.

Emmit Ryan - STA
 Fred Hawkins - STA Myr
 Arnold

=>

SERVICE PART: 2C3Z- 9F836-DE PEDAL
 RECEIVING LOCATION: DEMAND GROUP:
 CUSTOMER TYPE: BACKCAST: Y
 SDI Code:



A	C	MONTH	YEAR	Quantity	Replaced Part Number	Message
		01	2003	374		
		12	2002	1143		
		11	2002	1168		
		10	2002	1498	2C3Z- 9F836-DA	REPLACED
		09	2002	1184		
		08	2002	1231		
		07	2002	1105		
		06	2002	695		
		05	2002	445		
		04	2002	186		
		03	2002	94		

Daily Rate x Days = 1600

F1=Help F4=FirstRecLoc F5=FirstCustType F6=FirstYear
 MORE RECORDS AVAILABLE

LPSDMA7

==>

SERVICE PART: 2C3Z- 9F836-DE PEDAL
BACKCAST: Y DEMAND GROUP: [REDACTED]

A	YEAR	Quantity	Replaced Part Number		Message
C	----	-----	-----		-----
	2003	396			
	2002	9327	2C3Z-	9F836-DA	REPLACED
	2001	80	2C3Z-	9F836-BA	REPLACED
	2000	0			
	1999	0			
	1998	0			
	1997	0			
	1996	0			
	1995	0			
	1994	0			
	1993	0			
	1992	0			
	1991	0			

F1=Help F2=FirstMonth
MORE RECORDS AVAILABLE

LPSDM74

SERVICE PART: 2C3Z- 9F836-DE PEDAL
 RECEIVING LOCATION: _____ DEMAND GROUP: _____
 CUSTOMER TYPE: _____ BACKCAST: Y
 SDI Code: _____

A

C	MONTH	YEAR	Quantity	Replaced Part Number	Message
	01	2003	374		
	12	2002	1143		
	11	2002	1168		
	10	2002	1498	2C3Z- 9F836-DA	REPLACED
	09	2002	1184		
	08	2002	1231		
	07	2002	1105		
	06	2002	695		
	05	2002	445		
	04	2002	186		
	03	2002	94		

F1=Help F4=FirstRecLoc F5=FirstCustType F6=FirstYear
 MORE RECORDS AVAILABLE

LPSDM74

==>

SERVICE PART: 2C3Z- 9F836-DE PEDAL
 RECEIVING LOCATION: _____ DEMAND GROUP: _____
 CUSTOMER TYPE: _____ BACKCAST: Y
 SDI Code: _____



A

C	MONTH	YEAR	Quantity	Replaced Part Number	Message
	03	2002	94		
	02	2002	52		
	01	2002	43		
	12	2001	27		
	11	2001	22		
	10	2001	15		
	09	2001	10		
	08	2001	2	2C3Z- 9F836-BA	REPLACED
	07	2001	0		
	06	2001	0		
	05	2001	0		

F1=Help F4=FirstRecLoc F5=FirstCustType F6=FirstYear
 MORE RECORDS AVAILABLE

LPSDM74

-->

SERVICE PART: 2C3Z- 9F836-DE PEDAL
 RECEIVING LOCATION: DEMAND GROUP:
 SDI Code: BACKCAST: Y

A	CUST	B						
C	TYPE	C	01-2003	12-2002	11-2002	10-2002	09-2002	08-2002
	APF	1	0	0	0	0	0	0
	DLR	1	363	1131	1162	1492	1178	1216
	EXP	1	4	3	6	6	6	3
	FAR	1	0	0	0	0	0	0
	FOC	1	7	3	0	0	0	12
	FOM	1	0	6	0	0	0	0
	GDS	1	0	0	0	0	0	0
	ICC	1	0	0	0	0	0	0
	PPD	1	0	0	0	0	0	0
	SDS	1	0	0	0	0	0	0
	SMA	1	0	0	0	0	0	0
	Total		374	1143	1168	1498	1184	1231

F1=Help F2=FirstMonths F4=FirstRecLoc
 NO MORE RECORDS AVAILABLE

LPSDM74

Shore, John (J.)

Subject: Updated: Adj Pedal
Location: NPD Conf. Room 1203B

Start: Thu 1/30/03 4:00 PM
End: Thu 1/30/03 5:00 PM

Recurrence: (none)

Meeting Status: Accepted

Required Attendees: Jaeger, Sharon (S.A.); Kaercher, Don (D.F.); Shore, John (J.); Balint, Gary (G.M.); Balint, Gary (G.S.); Hirtzel, Rich (R.J.); NPOC PicTel Rm 1203B (16)

Importance: High

SORRY FOR CONFUSION-- I'LL GO SOAK MY HEAD NOW.
Time Change to 4:00 p.m. Adjustable Pedal
Call Sharon at 248-887-1898 from Conf. Room
Gary will phone in 734-623-3026

==>
 SERVICE PART: 1C3Z- 9F836-BA PEDAL, *all arm*
 ENGINEERING PART: 1C34 9F836 BB
 SUPPLIER LOC:
 Vendor Part:
 Motorcraft Part:

ORIGIN: WERS
 FINIS: 4462174
 Prime Suplr: O638E
 Role: T

-----Inventory-----		-----Stocking Demand-----	
FCSD Available:	184	Current Month:	368
Pkgr Available:	234	Prior Month:	766
In-Trans Pkgr:	0	Prior Month 2:	834
In-Trans FCSD:	893	Prior Month 3:	805
Transfers:	145	Curr Forecast:	872
Back Ord Pcs:	20	6-Mo Forecast:	5648
Tot Inventory:	1436	Out of Tolerance:	N
Tot Curr Pos:	3678	Back Ord Lines:	18
Est'd Max Pos:	3995	Off B/O Date:	
Firm Release:	Y	Unit Issue:	1
AIMS Inventory:	229	Pnd Obs:	
F1-Help F2-GPMA F4-PrvPart F5-NxtPart F6-BDLA F9-DEEA F10-HIIA			
F11-CPHA F13-SYKA F14-SMKA F15-SCKA F16-ISBA F17-LXEA F18-RXEA F19-DRIA			
RECORD FOUND			

LPSDM74

Adjustable 1200

Fixed 770

Keylib

Tasting 2/7 lb compok

- basket
- New tube

- Wabash
 - Kovic
 Tru
 2/3

- ground out on wiring
 - Lake Dr. CO

90K
 30K + launch
 45-60 1 1/2 year

~~car buy~~
 Jim Burrows 337-2505
~~Jim Burrows~~
 Drew Shepherd 764-908
 Supplier responsible - y

Joe Slachta 41200

ENTIRE PAGE CONFIDENTIAL

Non-Adj. pedal design.

ENTIRE PAGE
CONFIDENTIAL

REVISIONS

1. All drawings shall be in accordance with the drawing.
2. All drawings shall be in accordance with the drawing.
3. All drawings shall be in accordance with the drawing.
4. All drawings shall be in accordance with the drawing.
5. All drawings shall be in accordance with the drawing.
6. All drawings shall be in accordance with the drawing.
7. All drawings shall be in accordance with the drawing.
8. All drawings shall be in accordance with the drawing.
9. All drawings shall be in accordance with the drawing.
10. All drawings shall be in accordance with the drawing.
11. All drawings shall be in accordance with the drawing.
12. All drawings shall be in accordance with the drawing.
13. All drawings shall be in accordance with the drawing.
14. All drawings shall be in accordance with the drawing.
15. All drawings shall be in accordance with the drawing.

WIRING SCHEMATIC

DETAILS

SCALE 1:2

REV	DATE	BY	CHKD	APP
1				
2				
3				
4				
5				
6				
7				
8				

REVISIONS

REV	DATE	BY	CHKD	APP
1				
2				
3				
4				
5				
6				
7				
8				

REVISIONS

REV	DATE	BY	CHKD	APP
1				
2				
3				
4				
5				
6				
7				
8				

REVISIONS

REV	DATE	BY	CHKD	APP
1				
2				
3				
4				
5				
6				
7				
8				



PART	DESCRIPTION	PNCH	QTY	MATERIAL	FINISH	MAT. SPEC
1	BASE BRACKET	3001002	1	LC STEEL 1010	E-COAT	ESK-MSP128-A
2	CONN. HOUSING	3001008	1	PA66 (33% GF) (BLACK)	NONE	NSK-4ND643-A
3	COVER HOUSING	3001009	1	PA66 (33% GF) (BLACK)	NONE	NSK-4ND663-A
4	PEDAL LEVER	3001003	1	LC STEEL 1010	E-COAT	ESK-MSP128-A
5	ROTOR SHAFT	3001001	1	LC STEEL 1008	ZINC PLT	NSD-41P65-A2
6	PEDAL PAD	3001012	1	PP (BLACK)	NONE	NSB-440011-A
7	KNURLED PIN	3001000	1	LC STEEL 1008	ZINC PLT	NSD-41P65-A2
8	PAD SPRING	3001019	1	MUSIC WIRE	BLACK OXIDE	
9	RETURN SPRING	3001017	2	MUSIC WIRE	BLACK OXIDE	
10	FRICTION PAD	3001011	2	ACETAL (BLACK)	NONE	PSK-4ND637-A2
11	TERMINALS	3001020	5	BRASS	AN D. SW	
12	DEBRIS COVER	3001027	1	ACETAL (BLACK)	NONE	NSK-4ND637-A2
13	IDLE PIN	3000999	1	LC STEEL 1008	ZINC PLT	NSD-41P65-A2

REFERENCE  WILLIAMS PEDAL SYSTEMS - P/N 1000033

PART MUST COMPLY WITH MATERIAL SPECIFICATION WSS-409P9999-A1 TO HELP SAFEGUARD HEALTH, SAFETY AND THE ENVIRONMENT

DRAFTED IN ACCORDANCE WITH FAO ENGINEERING DRAFTING STANDARD CURRENT AT INITIAL RELEASE.



3RD ANGLE PROJ
DIMENSIONS IN
MILLIMETERS

CAD TYPE S-SORC	CAD LOC.	CAD FILE	E M IS MASTER
OPER. NO.	UNIT	DRAWING ▽ 1C34-9F836-BA	
DESIGN Y PINO	DETAIL T PINO	TITLE PDL & SNS ASY - ACEL	SHT 1 OF 1
CHECKED	SAFETY		
SCALE	DATE	DIVISION	

Shore, John (J.)

From: Baranowski, David (dbaranowski@wabashtech.com)
Sent: Monday, March 24, 2003 8:41 AM
To: Kaercher, Don (D.F.); Mimikos, Marcy (M.A.)
Cc: Shore, John (J.); Jaeger, Sharon (S.A.); Atley III, David (D.); Kharbas, Vijay (V.S.); Fisher, Jean (J.M.); Shields, Dennis (D.A.); Vijay Kharbas (E-mail)
Subject: RE: Need assistance

Don,

I have been requested to have FCSD contact Teleflex directly concerning the issues regarding their product.

The contact is : Greg Mausolf
Phone: 248-672-6242
Email: gmausolf@tfxauto.com

Frank. 260 349 1985 x3001
Kopacka

Please advise if you do not receive the pertinent information required. If you have any questions please feel free to contact me.

Regards,

David Baranowski
Sr. Account Manager
Wabash Technologies
46365 Five Mile Road
Plymouth, MI 48170
Ph: 734-453-5145 (main)
Ph: 734-453-4639 (direct)
Ph: 248-330-9636 (mobile)
Fx: 734-453-5859
Email: dbaranowski@wabashtech.com

- Director of Purchasing
- Jerry Micham -
248-616-3800
Steve Reinhart - Plant mgr

-----Original Message-----

From: Kaercher, Don (D.F.) (mailto:dkaerche@ford.com)
Sent: Thursday, March 20, 2003 8:15 AM
To: Baranowski, David; Mimikos, Marcy (M.A.)
Cc: Shore, John (J.); Kaercher, Don (D.F.); Jaeger, Sharon (S.A.); Atley III, David (D.); Kharbas, Vijay (V.S.); Fisher, Jean (J.M.); Shields, Dennis (D.A.)
Subject: RE: Need assistance

- will not commit to
future releases timing.
- Volumes 4000 weekly
w/o plan on hand!

Thanks Dave - include me, Sharon Jaeger and John Shore in your response as Marcy is off for a few days.... Thx!!

Don Kaercher
Ford Motor Company
FCSD PS&L QSF/Recall/Top 100 Dept. Mgr.
NPDC 1310C Text Pager: (734) 797-5993
e-mail: dkaerche@ford.com
*Phone: (734) 266-9793 *Fax: (734) 266-1166

Recovery Plan
Marty White - Buyer

-----Original Message-----

From: Baranowski, David [mailto:dbaranowski@wabashtech.com]
Sent: Wednesday, March 19, 2003 9:20 PM
To: Mimikos, Marcy (M.A.)
Cc: Shore, John (J.); Kaercher, Don (D.F.); Jaeger, Sharon (S.A.); Atley III, David (D.); Kharbas, Vijay (V.S.); Fisher, Jean (J.M.); Shields, Dennis (D.A.)
Subject: RE: Need assistance

Marcy,

I am currently in Mexicali. I will address this issue with the sales rep for Teleflex to get the appropriate perspective so I may respond back. I will be involved in a meeting with my customer, [REDACTED] all day tomorrow (3/20) and will be traveling back on 3/21. I will respond back as soon as I hear from the Teleflex team.

If you have any questions please feel free to contact me.

Regards,

David Baranowski
Sr. Account Manager
Wabash Technologies
46365 Five Mile Road
Plymouth, MI 48170
Ph: 734-453-5145 (main)
Ph: 734-453-4639 (direct)
Ph: 248-330-9636 (mobile)
F: 734-453-5859
Email: dbaranowski@wabashtech.com

-----Original Message-----

From: Mimikos, Marcy (M.A.) [mailto:mmimikos@ford.com]
Sent: Wednesday, March 19, 2003 10:52 AM
To: Baranowski, David
Cc: Shore, John (J.); Kaercher, Don (D.F.); Jaeger, Sharon (S.A.); Atley III, David (D.); Kharbas, Vijay (V.S.); Fisher, Jean (J.M.); Shields, Dennis (D.A.)
Subject: RE: Need assistance

Dave, we still have a problem with ETC availability at Wabash. We need to understand what the issues are, i.e., capacity, material, etc. Ford is willing to send a team to Wabash if required. Can you please provide an update immediately.

I would like to recommend that we have a conference call to include Ford, Teleflex and Wabash so we can determine the bottlenecks.

Thanks for your assistance.

Marcy Mimikos, Buyer
FCSD Purchasing
QSF/Recall Department
734-266-9913
mmimikos@ford.com

-----Original Message-----

From: Baranowski, David [mailto:dbaranowski@wabashtech.com]
Sent: Friday, March 14, 2003 2:01 PM
To: Minikos, Marcy (M.A.)
Cc: Shore, John (J.); Kaercher, Don (D.F.); Jaeger, Sharon (S.A.); Atley III, David (D.); Kharbas, Vijay (V.S.)
Subject: RE: Need assistance

Marcy,

In response to your question, I have confirmed with the Teleflex sales rep. (Wabash side) Wabash will be up to schedule with Teleflex next week (week 3/17).

Please advise if you have any further questions or if I may be of further assistance.

Regards,

David Baranowski
Sr. Account Manager
Wabash Technologies
46365 Five Mile Road
Plymouth, MI 48170
Ph: 734-453-5145 (main)
Ph: 734-453-4639 (direct)
Ph: 248-330-9636 (mobile)
Fx: 734-453-5859
Email: dbaranowski@wabashtech.com

-----Original Message-----

From: Mimikos, Marcy (M.A.) [mailto:mmimikos@ford.com]
Sent: Thursday, March 13, 2003 2:26 PM
To: Baranowski, David; Kharbas, Vijay (V.S.)
Cc: Shore, John (J.); Kaercher, Don (D.F.); Jaeger, Sharon (S.A.); Atley III, David (D.)
Subject: Need assistance

David/Vijay,

I need some assistance. FCSD has a Field Service Action on the F-series over 8500 lbs. (7.3) pedal assembly. We purchase the pedal from Teleflex. They have had some delays in shipments and tell us it is due to the fact that Wabash is behind schedule on an ETC sensor. Teleflex's requirement to FCSD is 3500/week. Unfortunately, since this is a component to the assembly which we purchase, I do not have your part number.

Can you let me know if Wabash is having difficulty producing the required amount. We have offered to send someone to Wabash's plant, but Teleflex felt it was not required. Last week they told us Wabash would be up to schedule and now Teleflex is not certain if Wabash can keep up with their requirements.

I will be out of the office tomorrow, so when replying please be sure to forward to all addresses. I'll be in the office on Monday.

Your assistance would be appreciated.

John/Don/Sharon -- for your information. David Antley (x27551) is the Production Buyer for Wabash, not Teleflex. David Baranowski's, Rep for Wabash, office number is 734-453-4636; Vijay Kharbas, Resident Engineer for Wabash but located at a Ford office in Dearborn, phone number is 313-845-8546 or just dial the last 5 numbers.

Marcy Mimikos, Buyer
FCSD Purchasing
QSP/Recall Department
734-266-9913
mmimikos@ford.com

This is an e-mail from Wabash Technologies, Incorporated. It is confidential to the ordinary user of the above e-mail address. It may contain copyright and/or legally privileged information. No other person may read, print, store, copy, forward, or act in reliance on it or its attachments. If you received this in error, please e-mail to humanresources@wabashtech.com

This is an e-mail from Wabash Technologies, Incorporated. It is confidential to the ordinary user of the above e-mail address. It may contain copyright and/or legally privileged information. No other person may read, print, store, copy, forward, or act in reliance on it or its attachments. If you received this in error, please e-mail to humanresources@wabashtech.com

This is an e-mail from Wabash Technologies, Incorporated. It is confidential to the ordinary user of the above e-mail address. It may contain copyright and/or legally privileged information. No other person may read, print, store, copy, forward, or act in reliance on it or its attachments. If you received this in error, please e-mail to humanresources@wabashtech.com

From: Mercier, Julie (J.A.)
Sent: Tuesday, January 14, 2003 12:33 PM
To: West, Gregory (G.S.); Patten, Wyman (R.W.); Williams, Trevor (T.G.); Moroz, Brian (B.T.)
Cc: Ballint, Gary (G.S.); Hirtzel, Rich (R.J.); Mercier, Julie (J.A.)
Subject: 02X50 Updated Preliminary volumes - 7.3L P131/Excursion Adj. Pedal

Below are volumes, build dates and search criteria based on the 14D for the above issue and less units found on AWS that were repaired. Also below is a market breakdown report which should be attached to the 14D and referenced in Sect. 1.D. It is the 14D author's responsibility to insure that the criteria in the 14D is such that accurate vehicle counts can be obtained from NAVIS, and that I am informed of any changes to the vehicle population criteria. Please review the search criteria and volumes below, and let me know if any changes need to be made to the search criteria.



02x50 mkt
2k14wr.xls

Also below is data from an extract for the total population prior to deletion of VINs from AWS for reference.

Criteria:

VIN GROUP AA	
LAST MODIFIED:	08-Jan-2003 3:20 PM (J.MERCIER)
MODEL YEAR:	2002, 2003
VEHICLE LINE:	ALL
PRODUCTION DATE:	LESS THAN OR EQUAL TO 17-OCT-2002
SELECTION CRITERIA:	ASSEMBLY PLANT = ALL
	VEHICLE ORDER CODE: 02-62 = M
	: 03-08 = F
	VEHICLE LINE LEVEL = EXCURSION (ML L1T)
	= F-SERIES OVER 8500 GVW (ML : F7T)

Build Dates by Plant & by MY:

	2002 MODEL YEAR	2002 MODEL YEAR
DATE	EARLIEST PRODUCTION DATE	LATEST PRODUCTION
CAMPAIGN	FOR A VIN IN THE CAMPAIGN	FOR A VIN IN THE
KENTUCKY TRUCK PLANT BUILD	20-MAR-2001	30-JUN-2002
CUAUTITLAN PLANT BUILD	31-JUL-2001	21-DEC-2001
	2003 MODEL YEAR	2003 MODEL YEAR
DATE	EARLIEST PRODUCTION DATE	LATEST PRODUCTION
CAMPAIGN	FOR A VIN IN THE CAMPAIGN	FOR A VIN IN THE
KENTUCKY TRUCK PLANT BUILD	26-MAR-2002	17-OCT-2002

Volumes by model & model year:

VEHICLE LINE TOTALS	2002	2003	Total
Ford			
F-SERIES OVER 8500 GVW	62,935	23,135	86,070
EXCURSION	12,141	3,994	16,135
GRAND TOTAL	75,076	27,129	102,205

Sold vs. Unsold:

TOTAL BY STATUS			
SOLD	74,166	18,963	93,172
UNSOLD	867	8,146	9,033
GRAND TOTAL	75,078	27,128	102,305

NAVIS Extract with all VINs - prior to AWS delete list:**Criteria:**

CRITERIA GROUPING(S):	
VIN GROUP AA	
LAST MODIFIED:	09-Jun-2003 3:20 PM (JMERCIER)
MODEL YEAR:	2002, 2003
VEHICLE LINE:	ALL
PRODUCTION DATE:	LESS THAN OR EQUAL TO 17-OCT-2002
SELECTION CRITERIA:	ASSEMBLY PLANT = ALL
	VEHICLE ORDER CODE: 62-62 = M
	: 60-60 = F
	VEHICLE LINE/LEVEL = EXCURSION (VLL1T)
	= F-SERIES OVER 8500 GWW (VL : F7T)

Volumes by Model & MY:

VEHICLE LINE TOTALS			
Ford			
F-SERIES OVER 8500 GWW	63,970	23,172	86,842
EXCURSION	12,300	3,890	16,290
GRAND TOTAL	76,270	27,171	103,441

*Best Regards**Julie Mercier*

FSA Coordinator

FCSD/Recall & Service Programs

DSCII #775

(313) 317-9266 Fax: 845-1024

jmercier@ford.com

GLOBAL CAMPAIGN TARGETING - FORD CONFIDENTIAL			
REPORT TITLE : VEHICLE LINE BY COUNTRY/ROI			
BY MODEL YEAR			
GLOBAL REFERENCE NUMBER : 2087			
LOCAL CAMPAIGN NUMBER : 02X50			
CAMPAIGN DESCRIPTION : 02X50 02-03 7.3L			
F131/Excursion adj pedal			
	2002	2003	TOTAL
Europe - Part of Affiliates			
NORWAY			
Ford			
F-SERIES OVER 8500 GVW	79	0	79
EXCURSION	173	0	173
SUBTOTAL NORWAY	252	0	252
SUBTOTAL Europe - Part of Affiliates	252	0	252
Other Affiliates			
AUSTRALIA			
Ford			
EXCURSION	0	1	1
SUBTOTAL AUSTRALIA	0	1	1
SUBTOTAL Other Affiliates	0	1	1
Canada			
CANADA			
Ford			
F-SERIES OVER 8500 GVW	6,536	2,162	8,698
EXCURSION	320	64	404
SUBTOTAL CANADA	6,856	2,248	9,102
SUBTOTAL Canada	6,856	2,248	9,102
Federalized Territories			
PUERTO RICO			
Ford			
F-SERIES OVER 8500 GVW	72	25	97
EXCURSION	15	3	18
SUBTOTAL PUERTO RICO	87	28	115
SUBTOTAL Federalized Territories	87	28	115
Non-Federalized Territories			
THAILAND			
Ford			
F-SERIES OVER 8500 GVW	1	0	1
EXCURSION	1	0	1

SUBTOTAL THAILAND	2	0	2
UNKNOWN COUNTRY			
Ford			
F-SERIES OVER 8500 GVW	58	11	70
EXCURSION	35	9	44
SUBTOTAL UNKNOWN COUNTRY	94	20	114
SUBTOTAL Non-Federated Territories			
Ford			
F-SERIES OVER 8500 GVW	80	11	71
EXCURSION	38	9	45
	90	20	118
United States of America			
UNITED STATES			
Ford			
F-SERIES OVER 8500 GVW	68,188	20,937	77,125
EXCURSION	11,887	3,887	15,494
SUBTOTAL UNITED STATES	87,785	24,834	92,619
SUBTOTAL United States of America	87,785	24,834	92,619
VEHICLE LINE TOTALS			
Ford			
F-SERIES OVER 8500 GVW	82,935	23,135	85,070
EXCURSION	12,141	3,894	15,135
GRAND TOTAL	75,076	27,129	102,205
*** END OF REPORT - VEHICLE LINE BY COUNTRY ***			

From: Mercler, Julie (J.A.)
Sent: Wednesday, January 29, 2003 12:12 PM
To: Ufford, Donald (D.A.); Osborne, William (W.H.); Dehne, Susan (S.M.)
Cc: West, Gregory (G.S.); Guys, Philip (P.R.)
Subject: 03B03 Assigned: 2002-2003 7.3L -Superduty and Excursion - Adjustable Pedal Sensor

Field Service Action Assigned: Customer Satisfaction Program 03B03

Reference: 02X50 (For Recall & Service Programs Dept. Use Only)

FRC Date: January 29, 2003

Vehicles Affected: 2002-2003 7.3L F-Superduty and Excursion

Concern Description: Adjustable Pedal Sensor

Supplier Resp: Yes

14-D Author: Gregory Scott West

The 14D author will be responsible for reviewing Prevent Action closure with Bill Osborne, Tough Trucks VC Engineering Director, no later than March 29, 2003.

This review will focus on implementation of Prevent Action (Step 13) requiring evidence of incorporation and overall quality of event including systemic root cause and appropriate prevent action selection to capture lessons learned.

Please contact Greg Oswalt for further information and direction. Provide Ramana Divakaruni (RDIVAKAR) with actual Prevent Action Closure Date (required for campaign metrics) and an electronic copy of the Prevent Action closure review paper. We request that the GCE CPS include the Field Service Action number & root cause information in their Fresh Eyes check list as appropriate.

Best Regards

Julie Mercier
FSA Coordinator
FCSD/Recall & Service Programs
DSCII #775
(313) 317-9266 Fax: 845-1024
jmercier@ford.com

PER3-044 12581

KTP
ELECTRICAL HISTORY

AFL

Rayford Williams

Randy McLeod 456-8708

Verbatim,

how have failures occurred

Rick ECI deep dive
Jones

Complete
ERDR

emissions related defect report

What did GM do with failures
what was failure mode

[REDACTED]

Questions pertaining to the U137 Electronic Throttle Control Pedal

1. Electronic Throttle Controls parts from durability vehicles from the inception of programs; VN 127 and U137.
- G X 2. Durability Vehicle test data and log sheets; VN 127 and U137.
3. Vehicle durability tear down of the ETC and Ford sign off's; VN 127 and U137.
4. Temperature vehicle profile at part location; VN 127 and U137.
5. Temperature vehicle profile and the correlation to specification; all vehicles.
- G X 6. Change release history from; inception - product release - production - beyond.
- L X 7. Vibration vehicle profile; VN 127 and U137.
8. Vibration vehicle profile and the correlation to specification; all vehicles.
9. Ford system bench testing data and parts; VN 127 and U137.
10. Ford analysis of the system test bench parts; VN 127 and U137.
11. Warranty profile and demographics.
- 26338 L G X 12. Ford 8D from the electrical problem.
- G X 13. Electrical problem dirty and clean point.
- L X 14. Hot trip data associated with the ETC and any temperature profiles; VN 127 and U137.
15. System FMEA; ~~all vehicles~~.
16. Duty cycle and customer use data; ~~all vehicles~~.

3/10

17 February 2003

From: Love, Keith (K.A.)
Sent: Thursday, September 25, 2003 8:22 AM
To: Souchock, Peter (P.D.)
Subject: FW: VOQ VINs

Pete, below are responses to the outstanding questions from our telecon with NHTSA yesterday, plus Scott Yon's follow up e-mail. They are as follows (and detailed below):

Telecon:

a) 5 pin vs. 10 pin connector usage. 5 pin is used with the two track (2nd gen) system and 10 pin is used with the three track (3rd gen) system.

Follow up questions:

1) The F Super Duty 6.0L diesel had only the three track (3rd gen) design.

2) Pedal efforts on the F Super Duty diesel vehicle ranges from 4.5 lbs. breakaway to 10 lbs. at wide open throttle.

Let me know if you need anything else.

-----Original Message-----

From: Liposky, Lawrence (L.J.)
Sent: Wednesday, September 24, 2003 5:31 PM
To: Love, Keith (K.A.)
Cc: Liposky, Lawrence (L.J.)
Subject: RE: VOQ VINs

Keith three things I owe you from today's discussion:

1.) Question on Five pin vs. Eight/Ten pin output. Five Pin hard-shell is specific to Two track design / Three pins for sensor signal and Two for Idle Validation Switch (IVS). Ten + Eight pin is specific to Three track design. We utilize Seven pins on Ten or Eight pin hard-shell. Redundancy as stated for Accel Pedal Position Signal (APPS). Break-down as follows:

5 pin-Single Track W/IVS

- 1 @ supply voltage
- 1 @ ground
- 1 @ output voltage
- 1 @ input @ IVS
- 1 @ output @ IVS

10/8 pin - Three Track

- 1 @ output voltage pedal position 1
- 1 @ output voltage pedal position 2
- 1 @ output voltage pedal position 3
- 1 @ common ground pedal position 1 + 2
- 1 @ ground pedal position 3
- 1 @ supply voltage pedal position 1 + 2
- 1 @ supply voltage pedal position 3

2.) Single track w/IVS usage was eliminated with introduction of 6.0L Diesel which incorporated Three track design.

3.) Minimum pedal effort breakaway requirement is lbs.. Efforts are more attribute driven, however must maintain returnability for FMVSS124 acceptability. Target for Super Duty is 4.5lb breakaway to 10lbs at wide open throttle.

Larry Liposky
Supervisor - Accelerator Controls
Tough Truck / Outlifters
Phone 24-81728
Pager 786-0948

-----Original Message-----

From: Love, Keith (K.A.)

Sent: Wednesday, September 24, 2003 2:57 PM

To: 'Yon, Scott'

Cc: Souchock, Peter (P.D.); Nevi, Ray (R.A.); Tokarsky, Michael (M.);

Liposky, Lawrence (L.J.)

Subject: RE: VOQ VINs

Scott, I have researched the requested 2002MY F Super Duty/Excursion VINs and report the following:

VIN	MY Series	Engine	Pedal	
1FMSU43F22	2002	Excursion	7.3L Diesel	Adjustable
1FMSU43F22	2002	Excursion	7.3L Diesel	Adjustable
1FTNW20F02	2002	F250 4x2 Crew Cab	7.3L Diesel	Adjustable
1FTNW21F72	2002	F250 4x4 Crew Cab	7.3L Diesel	Adjustable
1FT6W31F32	2002	F350 4x4 Crew Cab	7.3L Diesel	Adjustable

All these vehicles do indeed have adjustable pedals. Per our previous discussion, I added a "U" in the 5th position of the first VIN to create a valid number ("M" in the 3rd position requires "U" in the 5th).

Should have an answer to your other q's shortly.

-----Original Message-----

From: Yon, Scott [mailto:Scott.Yon@nhtsa.dot.gov]

Sent: Wednesday, September 24, 2003 11:59 AM

To: Love, Keith (K.A.)

Subject: RE: VOQ VINs

The VOQ only has 16 digits for the VIN field entry (I copied the data off our database electronically) but it shows the vehicle model as a 2002 Excursion, so I agree that the VIN should be as you guessed.

Thanks,
Scott

-----Original Message-----

From: Love, Keith (K.A.) [mailto:klove@ford.com]

Sent: Wednesday, September 24, 2003 11:19 AM

To: Yon, Scott

Subject: RE: VOQ VINs

Reviewing your VINS now. The first one is shy of a digit. I believe it should be as follows: 1FMSU43F22EB40332 (I added a U to the 5th position and found an Excursion). Please verify that this is correct.

-----Original Message-----

From: Yon, Scott [mailto:Scott.Yon@nhtsa.dot.gov]

Sent: Wednesday, September 24, 2003 10:40 AM

To: Keith Love (E-mail)

Subject: VOQ VINs

Keith,

Thanks for your help on this. There are only 5 VINs because two of the complaints reference the same vehicle which suffered two failures. The attached SS has the numbers.

Two other questions came up after we hung-up. Can you let me know if you can get answers to these? No hurry on number 2.

1) Was there a version of the 6.0L engine built with second generation (single track) ETC or was it only built with the third generation (triple track) system?

2) Is there a design intent throttle force that Ford uses on ETC based systems to get customer acceptable throttle feedback?

Can you advise your phone number? My details are below, feel free to contact me anytime.

Regards,
Scott

Scott Yon
U. S. Department of Transportation
National Highway Traffic Safety Administration
Office of Defects Investigations
Rm 5326
400 7th Street SW
Washington, DC 20590
202-366-6761
Fax-202-366-1767

<<IE03046_VOQ_VINs.xls>>

From: Evangelista, Ello - Troy [eevangelist@TFXAuto.com]
Sent: Wednesday, July 25, 2001 10:30 AM
To: Tomas Skwirsk (E-mail)
Cc: Wally Cropps (E-mail); Daniel Villar (E-mail); Lisa Petrauskas (E-mail); Braniff, Greg - Troy; Feldel, Rolf - Troy; Teller, Bill - Troy; Franklin, Ben - Kendallville
Subject: ES lash testing (1 direction) vs. total lash

Tom,

I spoke to Ben Franklin our Quality Engineer and he would like to show the total lash instead of how ES currently stated. This is deemed a "SC" now so capability is required.

Can not show very good capability as ES written but able to show very good when total lash taken into account. Seems that our design has lash in one direction (per ES) more than other.

Therefore plant requesting that this be stated on drawings.
Please advise

Ello Evangelista
Program Manager - Pedal Systems
Teleflex Automotive Group

1,635 VINE ASSISTED TO
PROGRAM BEFORE LAUNCH.
FINAL
140 WTS NO LONGER IN 140
SYSTEM & THAT TIME SO
UPDATE COULD NOT BE
MADE TO DOCUMENT.

ACTION ITEMS REQUIRED
ON FEU PARTS

BRAKE

- 1) BONDS - 100% END OF LINE TESTED
- 2) NOISE TEST

ACCEL-GAS

- 1) ADD TIC STOP PRIOR TO SHIP

- 2) INVESTIGATE REDUCING PINT PIN CLEARANCE HOLE TO REDUCE LASH (DESIGN)

LATERAL TEST PARTS

- 4) NOISE TEST

4/24/01

ACCEL-DIESEL

- 1) RUN THRU ETC FINAL TESTER
- 2) ADD PERFORMANCE PARTS
- 3) CHANGE SPEC LIST TO NEW LASH
- 4) CHECK ETC LOADS BOTH POSITION

MOTORS

- 1) CHANGE PINT TO NEW SPEC "AA" → "AB"
- 2) NOISE TEST "BA" → "BB"
- 3) VERIFY WIRE/ARMS CONNECTION OK
- 4) CABLE ORIENTATION OK

MOTOR-COAST

- 5) CHANGE SENSOR CABLE FOR BACKWARD COAST

DESIGN

- SC/ - ADD NOISE TO LIST (?) BE/BEW GET BUY IN TO AVOID FEE.

4/24/01

ITEMS ON LINE THAT STILL NEED ACTION ON

1) BRAKE + ACCEL (4 #16)
• BRAKE HOLDING FIXTURE
TO CLEAR WELD - COMPLETE

2) BRAKE + ACCEL (OP #50)
• WORN BORE HOLE LOCATION
HIGH FALL OUT
• VERIFY GUIDE RODS.
• POSSIBLE REWORK TOOLING

3) BRAKE TESTER (OP #80)
NOT WORKING - WORKING NOW
BUT NEED ADJUSTMENT

4) BRAKE GUIDE ROD WELD
• WELD ABOVE FACE
EXCESSIVE - REPAIR

5) REWORKERATE ASSY.
• CHANGE OPER INSTRUCTIONS
TO TIGHTEN SCREW FIRST
THEN TORQUE
REWORK MANUET TIP
• VERIFY HOLE SIZE
+ LOCATION ON BRACKET

6) MOTOR/CABLE ASSY
• NOTEN FIXTURE TO CLEAR
CABLE + SENSOR FOR CABLE
PRESENCE/ORIENTATION

7) SCR/WASHER ASSY
• REVISE NEST
• VERIFY PROGRAMMING

8) ETC - END OF LINE TESTER
• NOT WORKING
CURRENTLY WORKING DRAWING

9) OVERHEAD LIGHTS - ETC LINE

10) LOCKER DISCONNECT
AFTER RIV ASSY

11) TIE STRAP ASSY
NOT EXISTING

12) ACCEL - OVER 60
NO STOP TO AN OVER.



ITEMS ON LINE THAT
STILL NEED ACTION ON

1) BRAKE + ACCEL (4 #4)

- REVISE HOLDING FITTING
TO CLEAR WELD - COMPLETE

2) BRAKE + ACCEL (OP #50)

- WORN BEAR HOLE LOCATOR
HIGH FALLOUT
VERIFY GUIDE RODS.
• POSSIBLE REWORK TOOLING

3) BRAKE TESTER (OP #80)

- NOT WORKING - WORKING NOW
BUT NEED ADJUSTMENT

4) BRAKE GUIDE ROD WELD

- WELD DEMO POOR
EXCESSIVE - REMOVE

5) REMANUFACTURE ASSY.

- CHANGE OPER INSTRUCTIONS
TO HAND ASSEMBLY SCREW FIRST
THEN TORQUE
REMOVE MANET T.I.P.

- VERIFY HOLE SIZE
+ LOCATION ON BRACKET

6) MOTOR/CABLE ASSY

- NOTCH FITTURE TO CLEAR
CABLE + SENSOR FOR CABLE
PRESENCE/ORIENTATION

7) SCR/WASHER ASSY

- REVISE NEST
• VERIFY PROGRAMING

8) ETC - END OF LINE TESTER

- NOT WORKING
CURRENT BOM/TITLE/DESCRIPTION

9) OVERHEAD LIGHTS - ETC LINE

10) LICENSE DISPOWER
AFTER RTV ASSY

11) TIE STRAP ASSY

- NOT EXISTING

12) ACCEL - OVER 60
AND SHUT TO AN OREL.

4.5.01 U137 F.E.U. READINESS (FEU: 4.19.01)

PAGE
1/2

A) How TO ASSURE EDL PART IS ID'd & SHIPPED CORRECTLY

- How TO PROTECT ASSY'S MADE W/ CORRECT COMPONENTS

1) BRAKE PEDAL RATIO → PFMEA / C.P. / Poka Yoke

2) a) ACCEL BRACKET (DSL NIS STOPS) → PFMEA / Poka Yoke

b) " CABLE RETAINER → " " "

FAILURE: ' * HI TOLE * NO W.O.T.

ACCEL: EXT PLATE INTRO. OP 20 → Poka Yoked 30, 40, 50

BRACKET INTRO. OP 60 → Poka Yoke BOTH EXT. & BRKT

BRAKE: EXT PLATES FOR WELDER → SENSED IN WELDER

INTRODUCED - OP 20 → Poka Yoked 30, 40, 50

BRACKET INTRO. OP 60 → Poka Yoke BOTH EXT. & BRKT

GAS VE DSL VERIFIED IN FINAL TEST

30 PLS CAP Study on Motor Mount Asstn Variance

[DBL CHK THAT THIS IS ALL CAPTURED ON PFMEA & CONTROL PLAN]

4-5-01 U137 F.E.U. READINESS

(FEU: 4-19-01)

PAGE 2/2

SHIPPING ISSUES

- PACKAGING FOR MOTORS (DARBORN PKG HAS CONCERNS W/CONTAINER LENGTH)
- ALLER TIE STRAP IS "GO" AT THIS TIME
- ~~BRAKE TIE STRAP IS "MAYBE"~~

PER KTR 4/5
 DUE TO BE CLOSED BY 4-13-01
 ELIO E. to P/UP

* LINE ISSUES

- CHANGES TO LINE FOR DESIGN CHGS TO BE DONE BY 4-13-01
- URGENT LIST OF CHANGES PER OP. W/DATES - M. FOREMAN

WILL SHIP
 FLAT. B. HANDED
 TO CONFIRM P/UP

2000 MY TOP COIS POWERTRAIN ISSUES FOR P131 U137

7.3L DIT Issues

Concern Title	Champion	# of Reports	COIS Folder #	Status
Turbo Loud	J. Wilkins M. Greenwald	74	999590.005094	Working on a Development plan to incorporate the exhaust isolator. Durability testing in progress.
7.3L Engine/Exhaust Morn 7.3L Fuel Oil Issue	C. Johnson	42	999187	No fix planned at this time Crash testing Vehicle #1 completed on 6/25/00. 269 AWH claims for 2000MY (January & February) reviewed by PT Quality Team. 18 Claims for Fuel-Oil (A WH100). The cost of the service fix package is approx. \$500.00. Bob McCliment recommends that this be released as a service fix only.
	Pat DeMarco Doug Pytkason Bob McCliment	35	999186	CR#1113997 Input by Bob McCliment for >5500 FT deck-Engineering review. D.J.P. waiting for Supplier cost & timing. ** Production Fuel conditioner for 2003 will NOT cure the Fuel-Oil Issue-D.J.P **

6.9L V-8 Concerns

Concern Title	Champion	# of Reports	COIS Folder #	Status
6.9L Exhaust Drone	J. Anzil Kath Ralledge	70	999054.997488	Production Y-pipe/catalytic calibration change lined for 01/18/00 implementation at KTF Service/Certification releases are approved. Part requests submitted and approved on 10/17/00. TSB submitted on 10/18/00-Waiting for approval.
6.9L Cat Exhaust Fluter	J. Anzil Kath Ralledge	50	999341.996473	Production Y-pipe/catalytic calibration change lined for 01/18/00 implementation at KTF Service/Certification releases are approved. Part requests submitted and approved on 10/17/00. TSB submitted on 10/18/00-Waiting for approval.
6.9L Engine Stalls	Jeff Keeho Carl Simms Paul Randall Bill Welbeck Aidan Dances Dan Capp Dorede Schutler	22	999487.001855	New 4-Plate IAC Valve testing at IEL on 6.9L in September. Confirmation testing successful on 4.0L B-DHC at IEL Test Lab. Calibration Teams lined-up to get new design in 2000- Parts in October. IAC Valves received from Hitachi Engineering on 11/2/00-Cold Weather/High Altitude testing in progress-Par Kath Ralledge

5.4L V-8 Concerns

Concern Title	Champion	# of Reports	COIS Folder #	Status
5.4L Check Engine Light P0353-359	P. Fendall K. Ralledge	14	002348	Concern closed-SEM #13867 issued on Ignition coil. Code released on 2/21/00 Par Kath Ralledge
5.4L Engine Stalls	P. Fendall K. Ralledge	14	002711	Kath Ralledge contacted the National Service Hotline on 01/16/00. Investigation in progress. IAC Valves for calibration scheduled for week of 11/8/00

2001 MY TOP COIS POWERTRAIN ISSUES FOR P131 U137

7.3L DIT issues

<u>Concern Title</u>	<u>Champion</u>	<u># of Reports</u>	<u>COIS Folder #</u>	<u>Status</u>
LOWER ENGINE KNOCK		14	6831	
FUEL C/JACKLE		14	6673	
LOW OIL PRESSURE - Cust. Built units		15	7022	

6.8L V-10 Concerns

<u>Concern Title</u>	<u># of Reports</u>	<u>COIS Folder #</u>	<u>Status</u>
6.8L ENGINE REPLACEMENT	18	5904	- Engine noise / knock

5.4L V-8 Concerns

<u>Concern Title</u>	<u># of Reports</u>	<u>COIS Folder #</u>	<u>Status</u>
5.4L ENGINE REPLACEMENT	8	6932	- Engine noise / knock - coolant in oil - oil leak

4R100 CONCERNS

NO 1-2 UPSHIFT/TRANS FAILURES	72	6212	
NO ENGAGEMENT	5	5886	- No engagement / Slips
NO UPSHIFT (REPLACED TRANS)	6	9445	
RETURN AFTER 00B54 TRANS REPLACEMENT	4	6987	- No engagement / Slips

3 after 9/15/00 "clean date"

MANUAL TRANSMISSION

5SP - 4TH GEAR JUMPOUT	5	6987	
------------------------	---	------	--

**FCSD Technical Hotline Concern Tracking List
7.3L POWERSTROKE DIESEL
NOVEMBER 200**

Name: [REDACTED]
Phone: 31-79337
CDS ID: [REDACTED]

Start Date	Vehicle Concern Description	Call Volume			Service Messages				Service Action		GSF		Additional Comments
		Month	Total	History	Hotline ISM	OASIS SSM	TSB	ONP Recall	Current Recommendations	Repair Effectiveness	Y/N	Number	
08/01/1998	1998-2001 MY E, F-Series, Excursion 7.3L DIESEL LACKS POWER	126	1748	MAY-96 JUN-94 JUL-103 AUG-113 SEP-87 OCT-123	89-11-40	11819 13688	96-17-16 95-06-04 97-15A 98- 18-11		Verify the fuel pressure under a load 80-85, check for a restricted air filter, check for popped off GAC tubes, run performance sheet. Check for fuel inlet restriction, possible plugged fuel pickup for low pressure under a load.	80% EFFECTIVE IF DIRECTIONS ARE FOLLOWED BETWEEN TSB'S AND HOTLINE RECOMMENDATIONS	N		THE CONCERNS OF FUEL GELLING AND AIR FILTER RESTRICTIONS ARE BEING LOOKED AT BY POWERTRAIN DEVELOPMENT
09/01/1998	1998-2001 MY E, F-Series, Excursion 7.3L DIESEL MISSES/ROUGH IDLE	176	2162	MAY-148 JUN-189 JUL-195 AUG-185 SEP-152 OCT-157		12649 14298	00-06-10		Check for contaminated fuel, possible scored injectors pre 12-7-98 production. Use ROTUNDA IPA part# 164-R2535 to perform manual cylinder contribution test using NGS or WDS and pid MPDES.	85% EFFECTIVE WHEN HOTLINE DIAGNOSIS AND ROTUNDA'S IPA ARE USED.	N		
08/01/1999	1998-2001 MY E, F-Series, Excursion 7.3L DIESEL CRANK NO START HARD START	184	1858	MAY-87 JUN-95 JUL-107 AUG-106 SEP-117 OCT-146	00-06-57 00-06-28	12562 12563 11776	97-15A PG 87		Perform the crank no start diagnostic sheet, with no communications with the PCM. Check the powers and grounds at the PCM. Check for v-ref at pin 90. If no v-ref at pin 90 then start unplugging 3 wire sensors, starting with the EBP (most common).	85% EFFECTIVE IS ALL HOTLINE AND TSB'S ARE FOLLOWED.	N		

PE03-014 11896

FCSD Technical Hotline Concern Tracking List
7.3L POWERSTROKE DIESEL
NOVEMBER 200

Name: [REDACTED]
 Phone: 31-79337
 CDS ID: [REDACTED]

Start Date	Vehicle Concern Description	Call Volume			Service Messages				Service Action		GSF		Additional Comments
		Month	Total	History	Hotline ISM	OASIS SSM	TSB	ONP Recall	Current Recommendations	Repair Effectiveness	Y/N	Number	
09/01/1999	1995-2000 MY E, F-Series, Excursion 7.3L DIESEL ENGINE KNOCKS	42	1329	MAY-77 JUN-123 JUL-68 AUG-78 SEP-43 OCT-49	00-09-015		98-17-16 00-10-01 00-22-00 00-23-05		On early 99's built before 12-7-98 use TSB 00-23-05 on 99.5 and 2000 use TSB 00-22-00	80% EFFECTIVE DEPENDING ON ELEVATION AND AMBIENT TEMPS.	N		SSM HAS BEEN WRITTEN FOR EARLY 1999 D/S .
08/01/1999	1998-2001 MY E, F-Series, Excursion 7.3L DIESEL OIL CONSUMPTION	55	609	MAY-38 JUN-33 JUL-36 AUG-35 SEP-28 OCT-37		11982	97-15A PG 122 99-6-4		Verify the capacity with the oil change 14qts on a pre 12/7/98 and 15qts on a after 12/7/99 with filter. Make sure the air filter is not restricted, then use TSB 97-15A, pg 122 for further diagnostics.	95% EFFECTIVE IF HOTLINE AND TSB 97-15A IS FOLLOWED.	N		
08/01/1999	1998-2001 MY E, F-Series, Excursion 7.3L DIESEL STALLS WHEN DRIVING/IDLE	76	876	MAY-48 JUN-44 JUL-54 AUG-55 SEP-71 OCT-57	00-06-28	12849 13743	87-15A pgs 124- 129		Verify if the injectors are scuffed. Check the fuel pressure. If in a cold climate, check for fuel gelling. If in a warm climate check for the restriction in the fuel tank, check for a loss of ICP or rpm signal, monitor the power and grounds at the PCM.	80% EFFECTIVE BECAUSE OF THE COLD FUEL GELLING CAN STILL HAPPEN WITH THE ADDITIVE INSTALLED.	N		

PER3-044 11897

FCSD Technical Hotline Concern Tracking List
7.3L POWERSTROKE DIESEL
NOVEMBER 200

Name: [REDACTED]
 Phone: 31-79337
 CDS ID: [REDACTED]

Start Date	Vehicle Concern Description	Call Volume			Service Messages				Service Action		OSF		Additional Comments
		Month	Total	History	Hotline ISM	OASIS SBM	TSS	ONP Recall	Current Recommendations	Repair Effectiveness	Y/N	Number	
8/1-199	1998-2001 MY E, F-Series, Excursion 7.3L DIESEL OIL LEAKS AT CAC COLD SIDE	41	777	MAY-72 JUN-57 JUL-16 AUG-57 SEP-18 OCT-23		11982	98-8-4		Check for the engine being overfilled with oil. Also check to see if the air filter is restricted. Check the cop to determine if it is a base engine concern.	50% EFFECTIVE POSSIBLE DESIGN CHANGE NEEDED.	N		POWERTRAIN DEVELOPMENT IS LOOKING INTO THIS CONCERN
08/01/1998	1998-2001 MY E, F-Series, Excursion 7.3L DIESEL CRUISE SURGE/BUCK JERK WITH THE CRUISE CONTROL ON OR STEADY THROTTLE	29	659	MAY-35 JUN-43 JUL-42 AUG-45 SEP-36 OCT-43		12876 11854 12898 14434			Advise the dealers to recalibrate the pcm to repair concern using sum 14434.	90% EFFECTIVE FOR 98, 99.5, 00 and 01	Y	700039	TSS SHOULD BE RELEASED BY NOVEMBER 1ST, 2000
09/01/1999	1998-2001 MY E, F-Series, Excursion 7.3L DIESEL POOR MILEAGE	43	528	MAY-21 JUN-35 JUL-19 AUG-27 SEP-19 OCT-31		13988	97-08-08 99-26-09		Perform the performance diagnostic sheet and then verify the mileage on a 60 mile road test at 60 miles an hour. Advise the tech to let customer know to drive the vehicle in the power band of 2200 to 2800 rpm.	75% EFFECTIVE SOME CUSTOMERS EXPECTATIONS CAN'T BE REPAIRED.	N		
09/01/1999	1998-2001 MY E, F-Series, Excursion 7.3L DIESEL PLUGGED OR RESTRICTED AIR FILTERS USED IN SEVERE DUTY APPLICATIONS	16	238	MAY-10 JUN-28 JUL-10 AUG-14 SEP-7 OCT-16			98-18-11 99-08-04		On early 98 DI's built pre 12-7-98, install filter housing from TSS 99-8-4, if built after that point file EDSR'S on all vehicles.	10% EFFECTIVE IF VEHICLE IN VERY SEVERE ENVIRONMENT.	N		3" filter went into production 11-20-00

PEB3-044 11888

FCSD Technical Hotline Concern Tracking List
7.3L POWERSTROKE DIESEL
NOVEMBER 200

Name: [REDACTED]
 Phone: 31-79337
 CDS ID: [REDACTED]

Start Date	Vehicle Concern Description	Call Volume			Service Messages				Service Action		QBF		Additional Comments
		Month	Total	History	Hotline ISM	OASIS SSM	TSB	ONP Recall	Current Recommendations	Repair Effectiveness	Y/N	Number	
08/01/1998	1998-2001 MY E, F-Series, Excursion 7.3L DIESEL EXHAUST SMOKES	23	388	MAY-24 JUN-25 JUL-24 AUG-30 SEP-18 OCT-22		4301 10814	97-15A PG 120		Use TSB 9-15A pg 120. Check for excessive crankcase pressure/low compression. Check the oilain of the fuel, needs to be 40+. Use a temp probe on the exhaust manifold to determine a hotter cylinder (black smoke), or cooler (white smoke). And replace the suspect injector and reset.	90% EFFECTIVE BECAUSE SOME CUSTOMERS WILL NOT ACCEPT A SMOKE THAT IS A CHARACTERISTIC OF THE VEHICLE.	N		

PERC-044 11898

O/8500# QRT FLEET ISSUES

CCC	Fleet	Concern Description	Champion	Current Status	Date	Projected Close Date
DB0	Northwestern Resources	Wiring convolutes wearing through CAC tubes	Jeff Christensen	C11881786. Heater hose convolute changed to "Sealco-Blind".	8/18/00 (A)	CLOSED
PS0	Northwestern Resources	Shift cable breaks	Jim Thomas	Jul 08 - J. Helmen verified correct assembly process being followed at KTP. Assembly process changed Apr 99. The three trucks with broken cables were built in May 99.	Jul-99 (A)	CLOSED
PS2	Northwestern Resources	Manual hublocks freeze	Todd Kearney	C11884838. Dial seal design changed from an O-ring to a U-cup. New design installed at MWR. Previous test samples failed. May-99 test developed. Key-life test failure complete. U-cup seal in production. OCE testing complete. Results evaluated. Course of action proposed for further improvements, if necessary.	8/9/00 (A) Aug-99 (A) 9/5/00 (A) 11/10/00 (A) 12/18/00 (S) 12/22/00 (S)	Dec-00
L72	Suncor Energy	AR180 / E400 front seal / torque converter failures	Rex Patis	Original proposal - metal stamping surrounded by Varied or Silicone (better temp resistance / able to withstand power wash process). Quotes from FNOK (\$8.44) and Chicago Rawhide (\$8.88) for revised seal vs. existing seal cost of \$0.12 deemed unacceptable. Design complete. Engineering direction to injection molded nylon design. Piece cost: \$1.08 (delta = \$.86). Tooling: \$125K. Prevalent and validation of new design complete. C18821888. Revised seal released. Parts available (18 weeks from design completion).	10/17/00 (S) 3/24/01 (S)	Feb-01
P24	Suncor Energy	Clutch disc fails	Phil Thomas Michael De Gules	C11048760. Revised clutch disc released. Search test developed to reproduce failure Field failures reproduced in Recruit test vehicle. C11142148. Revised spec (higher temp capacity) grease for current bearing released. SPD at KTP - 11/18/00. C11150484. Clutch disc Assy with larger diameter release plate on flywheel side of disc released. Parts available for production 1/24/01. C11171154. Revised design bearing (larger bearing) released. Parts available for production 2/18/01.	8/22/00 (A) 9/11/00 (A) 9/19/00 (A) 10/24/00 (A) 12/15/00 (S) 12/18/00 (S)	Dec-00
D50	Suncor Energy	Crankshaft position sensor failure (S.E.)	Paul Kothwala Pete Pandolfi Keith Kothage	Parts return request submitted for additional failed parts. Parts previously sent from Suncor (1) and dealership (2) were lost. Crankshaft position sensor released. SO received from Wabash. Report out at QRT.	8/23/00 (A) 10/26/00 (A) 12/1/00 (S)	OPEN
L72	Suncor Energy	Transmission fluid leaking at dipstick tube - AR180	Ricardo Galindo Kevin Seifing Ed Anderson Dean MacIntyre	Root cause of trans fluid leak is plugged vent tube caused by severe duty environment. PTSE Program Manager approves proposed course of action. Test equipment ordered. Instrumentation mounting package developed. Instrumented two (2) Suncor vehicles to gather data on seal trans fluid operating temperature and radiator top tank temperatures, with and without in-tank trans oil cooler (winter). Suncor data gathered. Reviewed data. Course of action proposed.	7/17/00 (A) 1/28/00 (A) 6/8/00 (A) 1/12/00 (S) 2/13/01 (S) 7/27/01 (S) 8/31/01 (S)	Aug-01

O/8500# QRT FLEET ISSUES

OCC	Fleet	Concern Description	Champion	Current Status	Date	Projected Close Date
R24	Zachry Construction	Excessive oil consumption	Ron Greenwald Pete Fensell John Lintal	Remove worst performing engine for detailed tear-down analysis. Tear-down analysis complete. Evaluate idle time versus actual mileage. Ron Greenwald / John Lintal will handle the installation of hour meters on two fleet vehicles. Evaluation on hold pending results of engine tear-down.	12/22/04 (S)	OPEN
L86	Northwestern Resources	T-coke engagement indicator switch failure	Eric Peters Gary Fowth	Part returned by NRG had severe contamination in the connector, as if unplugged while in service and then reconnected with internal debris, causing a faulty connection. EO received from NRG / Poltek. Exact root cause undetermined. Single occurrence. Unable to pursue further without additional failed parts. Two (2) failed pressure switches returned. Parts sent to NRG / Poltek. Seven (7) failed pressure switches returned. Parts sent to NRG / Poltek. Response to RFG for revised switch req'd from Poltek. Poltek has completely redesigned part to meet 384F design reqmt. -New design is costly and will require long lead time. Perform additional vehicle testing to refine temp reqmts for switch. Perform joint (NRG / Poltek) tear-down analysis to verify failure mechanism. EO done from NRG / Poltek. Release revised indicator switch. Implement revised design indicator switch.	7/17/04 (A) 9/27/04 (A) 10/28/04 (A) 11/5/04 (A)	OPEN

12:18 FEB 05, 2003
PRODUCTION DATE: FEB 05, 2003
CS011101 VER. 07:57 12/11/02

FORD CUSTOMER SERVICE DIVISION
SERVICE, WARRANTY, AND FINANCIAL SYSTEMS DEPARTMENT
CAMPAIGN NOTIFICATION AND ADMINISTRATION CONTROL SYSTEM

PAGE 1
JOB 38876-01
SECTION 40.40.001

CS011101 G

CSSTEPS

APPLY MAVIS EXTRACT AUDIT/CONTROL REPORT

Rich, 03B03 Load

CAMPAIGN	EXTRACT RECORDS		
	IN	PROCESSED	REJECTED
03B03	101,206	101,206	0
TOTALS:	101,206	101,206	0

CAMPAIGN	PLANT RECORDS		
	PLANT	BEGIN DATE	END DATE
03B03	E	20010320	20021017
03B03	N	20010731	20011221

RESPONSIBLE DEALER USED : 99,895
SHIP TO DEALER WITHIN 100 MILES: 0
FACING DEALER WITHIN 100 MILES : 0
PROXIMITIZED FORD DEALER USED : 1,311
PROXIMITIZED MER DEALER USED : 0
SHIP TO DEALER (NO NAME) USED : 0
FACING DEALER (NO NAME) USED : 0
SHIP TO BODY BUILDER DEALER USED: 0
FACING BODY BUILDER DEALER USED: 0
DEFAULT '181000' DEALER USED : 0
DEFAULT '4H1549' DEALER USED : 0
DEFAULT '59X440' DEALER USED : 0
DEFAULT 'J05765' DEALER USED : 0
JCL RESPONSIBLE DEALER USED : 0
JCL FACING DEALER USED : 0
JCL SHIP TO DEALER USED : 0
JCL DEFAULT DEALER USED : 0
NEW VEHICLE PROCESSED: 0
EXISTING VEHICLE PROCESSED: 101,206

Hirtzel, Rich (R.J.)



From: Rivera, Santos (S.)
Sent: Tuesday, February 04, 2003 2:09 PM
To: Wooten, Richard (R.L.); Hirtzel, Rich (R.J.)
Cc: Foster, Greg (G.); Adorjan, Phil (P.); Gerstenberger, Mark (M.)
Subject: 03B03 - Pay Status Confirmation

This Labor Operation has been set to pay in GSLTS with an effective date of Nov. 1,2002 for 2002-2003 F-Super Duty 4x2/4x4 and Excursion 4x2/4x4.

03B03B.....Clear Continuous codes and replace the accel. pedal.....0.4hrs

SANTOS RIVERA
Service Labor Time Standards Analyst
Ford Consumer Services Group
Tel 313-84-55122 Fax 313-390-8727
srivera5@ford.com

Hirtzel, Rich (R.J.)

From: Rivera, Santos (S.)
Sent: Tuesday, February 04, 2003 7:11 AM
To: Hirtzel, Rich (R.J.)
Subject: RE: 03B03 Attach III

Hi Rich

[This looks good, I'm going to set it to pay with the 0.4hrs.]

SANTOS RIVERA
Service Labor Time Standards Analyst
Ford Consumer Services Group
Tel 313-84-55122 Fax 313-390-8727
sriviera5@ford.com

-----Original Message-----

From: Hirtzel, Rich (R.J.)
Sent: Monday, February 03, 2003 4:01 PM
To: Rivera, Santos (S.)
Subject: 03B03 Attach III

For your review
<< File: 03B03_d1.pdf >>
I'll take any changes you want made Santos.

Richard J. Hirtzel
rhirtzel@ford.com
313-317-4997
Knowledge is Power!

Hirtzel, Rich (R.J.)

From: Wooten, Richard (R.L.)
Sent: Wednesday, February 05, 2003 12:07 PM
To: Hirtzel, Rich (R.J.)
Subject: RE: 03803 Adjustable Accelerator Pedal

OK, no changes.

Rick Wooten
ACES Controls
Phone (313) 845-4393 FAX (313) 845-4408
Mail Drop 3NE-1D, Regent Court Building
Room 3N491 (3rd Floor North)

-----Original Message-----

From: Hirtzel, Rich (R.J.)
Sent: Wednesday, February 05, 2003 9:23 AM
To: Wooten, Richard (R.L.)
Subject: 03803 Adjustable Accelerator Pedal

Please give me your approval as soon as possible (sometime today)
Thanks Rick

<< File: 02X50AdjPedalLetters.doc >> << File: 03803_d1.pdf >> << File: Pg1Cust.pdf >>

Richard J. Hirtzel
rhirtzel@ford.com
313-317-4997
Knowledge is Power!

REPAIR TIME: 3 hrs RTR

SECTION 310-02: Acceleration Control
REMOVAL AND INSTALLATION


2003 F-Super Duty/Excursion Workshop Manual

CLEAR CODE


Accelerator Pedal — Adjustable, Diesel Engines

Removal and Installation


1. Position the accelerator pedal in the most rearward (toward the driver) position.
2. Disconnect the accelerator pedal adjuster cable.



3. Remove the bolts and position the accelerator pedal aside.



4. Disconnect the electrical connector, and remove the accelerator pedal.



5. To install, reverse the removal procedure.
 - If a new accelerator pedal is being installed, make sure the brake pedal is in the most rearward (toward the driver) position before connecting the accelerator pedal adjuster cable.

ADJUSTABLE ACCELERATOR PEDAL REPLACEMENT

AFFECTED VEHICLES: CERTAIN 2002 AND 2003 F-SUPER DUTY
AND EXCURSION MODELS EQUIPPED
WITH A 7.3L DIESEL ENGINE

OVERVIEW

This procedure will direct you to replace the adjustable accelerator pedal assembly and clear any DTCs. No diagnosis is required.

SERVICE PROCEDURE

NOTE: Do not perform any diagnosis. Simply replace the pedal, then clear any DTCs present.

1. Replace the adjustable accelerator pedal assembly as outlined in Section 310-02 of either the 2002 or 2003 F-Super Duty/Excursion Workshop Repair Manual.
2. Clear all DTCs using the appropriate scan tool.

Ford Motor Company

CPR © 2003 FORD MOTOR COMPANY
DEARBORN, MICHIGAN 48121
01/03

** BEGIN PROGRAM : C8011102
GSAN SEGS READ : 0001635
PART DIST SEGS WRITTEN : 0000000
VENDOR SEGS WRITTEN : 0001564
PART LAB SEGS WRITTEN : 0001635
PART SUMM SEGS WRITTEN : 0001635
** END PROGRAM : C8011102

032503

032503

0000000

Kid
03B03 - Suff: A -

23:43 MAR 25, 2003
PRODUCTION DATE: MAR 25, 2003
CS011101 VER. 15:35 03/11/03

FORD CUSTOMER SERVICE DIVISION
SERVICE, WARRANTY, AND FINANCIAL SYSTEMS DEPARTMENT
CAMPAIGN NOTIFICATION AND ADMINISTRATION CONTROL SYSTEM

PAGE 1
JOB 38876-01
SECTION 40.40.001

CS011101 G

CSSTEPS

APPLY NAVIS EXTRACT AUDIT/CONTROL REPORT

CAMPAIGN	EXTRACT RECORDS		
	IN	PROCESSED	REJECTED
03803	1,635	1,635	0
TOTALS:	1,635	1,635	0

SUPPLEMENT CODE : A

CAMPAIGN	PLANT	PLANT RECORDS	
		BEGIN DATE	END DATE
03803	E	20010613	20021017
03803	M	20010823	20011220

RESPONSIBLE DEALER USED :	1,224
SHIP TO DEALER WITHIN 100 MILES :	0
FACING DEALER WITHIN 100 MILES :	0
PROXIMITIZED FORD DEALER USED :	266
PROXIMITIZED MER DEALER USED :	0
SHIP TO DEALER (NO NAME) USED :	2
FACING DEALER (NO NAME) USED :	46
SHIP TO BODY BUILDER DEALER USED :	0
FACING BODY BUILDER DEALER USED :	0
DEFAULT '181000' DEALER USED :	97
DEFAULT '4H1569' DEALER USED :	0
DEFAULT '59X440' DEALER USED :	0
DEFAULT 'J05765' DEALER USED :	0
JCL RESPONSIBLE DEALER USED :	0
JCL FACING DEALER USED :	0
JCL SHIP TO DEALER USED :	0
JCL DEFAULT DEALER USED :	0
NEW VEHICLE PROCESSED:	375
EXISTING VEHICLE PROCESSED:	1,260



ENGINEERING SUBSYSTEM

Subsystem Name:

Adjustable Brake
and Accelerator
Subsystem

Model Year: 2002	Vehicle/Program ID P131/U137	Engineering Office/PEO/PMT: PMT 108	Date 12/14/00
---------------------	---------------------------------	--	------------------

If you answer "No" to any of the following questions, please indicate shortfall and recovery plan on attachments

Product Engineering

1. Have all SUBSYSTEM, SYSTEM, AND Total Vehicle Functional Objectives been met?
 Yes No
2. Has 100% of DVP&R Testing been completed successfully?
 Yes No 3/3/01 - completion date
3. Has all COMPANY GENERATED REGULATORY CERTIFICATION and SAFETY GUIDELINES documentation been completed (see FAP03-202)?
 Yes No
4. Are PRODUCT ENGINEERING CR's closed, validated, and maintainable to support IPP?
 Yes No C11157539 to be closed 2/1/01
5. Are 100% of ALL Parts projected ready for IPP at PSW level?
 Yes No 6/4/01 is the PSW date
6. Are all CRITICAL Parts identified?
 Yes No
7. Have Service Parts been released on WERS (including service fields filled in) and submitted to PCSD?
 Yes No
8. Have Service Diagnostics, owner and shop manual publications, training and unique tool requirements been identified signed off?
 Yes No

MANUFACTURING ENGINEERING

9. Have VEHICLE OPERATIONS Process Sheets been completed?
 Yes No Completion 3/3/01
10. Has Manufacturing Process Capability been demonstrated through the use of surrogate parts?
 Yes No
11. Has ASSEMBLY PROCESS CAPABILITY been demonstrated through the use of surrogate parts?
 Yes No
12. Has FIT AND FINISH (Craftsmanship) been met?
 Yes No


Engineer/PMT Leader	Manager/Project Manager
Lisa Petrauskas/Phil Beckelero	Tom Walsh

2001 P431/U137 CSE PROGRAM - MAJOR/MINOR RISK STATUS SUMMARY

#	Manager/ Supervisor	PMT	Issue/Status	Resolution Plan	MAJOR Eng. Risk (Test validation issue)(QC)	MINOR Eng. Risk (Test validation issue)(QC)	Asny. Issue @ PEW Yes/No	Late PDW @ 4p Yes/No	Risk @ Engng S/O 3/1/01	Risk @ 4p	Risk @ PEU 4/22/01	Risk @ Job #1 7/28/98	No Risk Date
1	Baukshere	10B	Late DV Life Cycle Test	Complete Test on 3/5/01		X	No	N/R	Minor	N/R	No Risk	No Risk	3/5/2001

PERS-044-R 8724





**ENGINEERING SUBSYSTEM
SIGN-OFF**

Subsystem Name Adjustable Pedals	Record Copy Stamp
--	-------------------

Model Year 2002	Vehicle/Program ID P131/U137	Engineering Office/PEO/PMT: PMT 10B	Date 12/14/00
--------------------	---------------------------------	--	------------------

I. Subsystem Description
 03.18.01 Adjustable Accelerator Pedals
 06.06.02 Adjustable Brake Pedals

II. Subsystem Design Objective Assessments (include functional image as applicable)

III. Risk Assessment (Risk vs. Design Objectives, WCL, FVE and Customer Satisfaction)

Issues/Resolutions	Current Risk	W/P Risk
Low Life Cycle DV Testing	Minor	Minor

Engineer/PMT Leader Lisa Patrykczak/Phil Bauckelars	Manager/Project Manager Tom Walsh
---	---

2002 P131/U137 CSE PROGRAM

ENGINEERING SIGN-OFF SUMMARY ~ Adjustable Pedals

- A) **Program Risk Assessment**
(Summarize # of major crisis and expected dates to convert to minor/low risk)
Adjustable Pedals Life Cycle DV testing for verification of concern C11157559
scheduled for completion on 3/5/01.
- B) **Functional Attributes**
Complies with Functional Requirements
- C) **PMT Sign-Off Checklist (Form FAO 816)**
(List PMT's included here)

PMT 10B - Brakes
- D) **Program DVP&R Test Status**
(Summarize test % complete and expected 100% complete dates here. If more than 5 tests
then list in the Excel form)

DVP&R 98% Complete.
Life Cycle Test scheduled completion 3/5/01.
- E) **Product Engineering Concern Status**
(Summarize # concerns unresolved and expected resolution dates-parts released)
Three concerns
• C11157559: Drop Test Failure - waiting for cost resolution 2/1/01
- F) **PSW Part Status for IPP**
(Summarize # parts not making PSW at IPP and total # parts, % making PSW at IPP)
6 parts not making PSW at IPP. Total of 6 new parts.
0% PSW at IPP
- G) **WCR Risks and Deviations**

None
- H) **Compliance Demonstration Plan and Report (CDP&R) Status**

Complete.

2002 P131/U137 - ENGINEERING SIGN-OFF

UNRESOLVED CONCERN SUMMARY

CONCERN NUMBER	ISSUE	RESOLUTION DATE	FUNCTIONALITY IMPACT (Y/N)
C11157559	Drop test failure (Adj. Accel & Brake) -Authorization held up for cost.	2/1/01	Yes

2002 P131/U137 CSE PROGRAM - ENGINEERING SIGN-OFF

PSW PART AVAILABILITY/MANUFACTURING PROCESS CAPABILITY STATUS

Forecast the part availability for IPP @ PSW level and demonstrating manufacturing process capability

Total number of parts required for IPP @ PSW level: 6

Number of parts available for IPP @ PSW level: 0, (0)%

Number of parts not demonstrating Manufacturing Process Capability: 0, (0)%

For the Parts Not Available at IPP:

Activity (Insource/Supplier)	Part Description	Part Number	Alert Number to Support IPP	Projected PSW Date
Teleflex	Adj. Accel. Pedal - Diesel	2C35-9P836-AB	A11186594	6/4/01
Teleflex	Adj. Accel. Pedal - Gas	2C35-9726-AB	A11186594	6/4/01
Teleflex	Adj. Brake Pedal - Gas	2C35-2450-CB	A11186594	6/4/01
Teleflex	Adj. Brake Pedal - Diesel	2C35-2450-DB	A11186594	6/4/01
Teleflex	Motor Assy - Adj. Brake - Non Memory	2C34-9G664-AA	A11186594	6/4/01
Teleflex	Motor Assy - Adj. Brake - Memory	2C34-9G664-BA	A11186594	6/4/01

2002 P131/U137 CSE PROGRAM - ENGINEERING SIGN-OFF

MAJOR RISK OR MINOR RISK
(Please Circle Risk)

ISSUE:

Adjustable Pedals

CHAMPION:

Lisa Petrauskas

DESCRIPTION:

Late change to resolve drop test concern has delayed the Adj. Pedals Life Cycle DV test.

RESOLUTION PLAN:

Complete Adj. Pedal Life Cycle DV Test on 3/5/01

OUTLOOK:

High confidence for successful completion of Life Cycle Test with drop test fixes.

Prior level design has successfully completed test. Changes required to meet drop test are judged to have little or no effect on life cycle performance.

RISK ASSESSMENT @ JOB #1 Major or Minor

No Risk at Job #1

[REDACTED]

From: Jones, Rick (W.P.)
Sent: Friday, December 06, 2002 9:39 AM
To: Selli, Frank (F.E.); Trzeciak, Robert (R.T.)
Cc: Liposky, Lawrence (L.J.)
Subject: FW:

Hi guys, there was a tech review yesterday before CCRG and it was requested that ECI do an investigation on this issue. I'm not sure which one of your groups it belongs to, but please decide and get back to Larry with the results. Thanks.

-----Original Message-----

From: Liposky, Lawrence (L.J.)
Sent: Thursday, December 05, 2002 6:58 PM
To: Jones, Rick (W.P.)
Cc: Brennan, Patrick (P.M.); West, Gregory (G.S.)
Subject:

Rick, spoke to you earlier today regarding a pareto of customer verbatim's. This is specific to the accelerator pedal sensor failure experienced on the 02/03 Diesel Super Duty and Excursion. We are trying to determine what the customer experiences such as quit on the road, requires towing etc. Also, is there any way to determine if vehicle operation is altered at steady state conditions such as road load 70 mph cruise, or tip in from idle condition. Trying to define what the vehicle state is when the customer experiences a problem. Please call me if you need more explanation. thanks

Larry Liposky
Supervisor - Tough Truck
Accelerator/VMV Components
Phone 24-81728
Pager 796-0949

PE93-044 17085

Subject: 14-D Follow-up: 2002-2003 F-Superduty & Excursion adjustable accelerator pedal sensor
Location: PDC 1B-E45

Start: Tue 10/1/2002 8:00 AM
End: Tue 10/1/2002 9:00 AM
Show Time As: Tentative

Recurrence: (none)

Meeting Status: Not yet responded

Required Attendees: West, Gregory (G.S.); McDonagh, Scot (S.M.); Liposky, Lawrence (L.J.); Kramer, Michael (M.T.); Zhou, Jianhua (J.); Oswald, Greg (G.G.); Blackburn, Thomas (T.J.); Shore, John (J.); Hirtzel, Rich (R.J.); PDC Conf Rm 1B-E45 (20)

Optional Attendees: Musselman, Thomas (T.A.); Balint, Gary (G.S.); McNorton, Michael (M.C.); Swamy, Rainer (R.)

Silangpa, Don (D.C.)

From: Pino, Tomas [Tpino@WMCO.com]
Sent: Wednesday, May 10, 2000 2:50 PM
To: DHomovec@aol.com
Cc: Bronson, Walter
Subject: RE: New connector direction from Ford.



Draw,

I looked at the different possibilities regarding the new connector pin-out. It turns out having to connect the grounds and Vrefs makes things a lot harder. If we went with the double row, I am including a couple of variants that would work for us. Anything else would either be physically impossible, or require extensive modifications.
For the B In-line, we basically can do this:

A.....Vref
B.....S2
C.....Vref
D.....S3
E.....GND
F.....GND
G.....S1

As with the other one, S2 & S3 are interchangeable.

It would also be important to know if the pitch between terminals is the same as in our current connector.

Thank you,

Tomas Pino
Product Design
Aptek Williams
954-421-8450 x370
Tpino@WMCO.com

-----Original Message-----
From: DHomovec@aol.com [mailto:DHomovec@aol.com]
Sent: Wednesday, May 10, 2000 10:27 AM
To: Tpino@wmco.com
Subject: Re: New connector direction from Ford.

PLEASE PROVIDE any and all pin out information, drawings, etc. so I can share this with FORD on Thursday.
Thank you Tomas.
Draw Homovec

7-PIN
smaller pins - bad

[REDACTED]

Salamanca, Don (D.C.)

From: Pino, Tomas [Tpino@WMCO.com]
Sent: Tuesday, May 09, 2000 4:10 PM
To: Homovec, Drew
Cc: Bronson, Walker; Martin, Tom; Drew Homovec; Salamanca, Carlos; Dan Johnston (Dolphin)
Subject: New connector direction from Ford.

Drew,

I understand that Ford has been toying with the idea of adopting the European philosophy regarding common pins. As a result, instead of three pins per circuit, the + and gnd. would be shared in pairs to reduce the pin count from nine to seven. We have included a ten pin connector on the 2001MY sensor to be able to use the three track version with virtually zero tooling. If the plan to shift to a seven pin (eight pin shell) connector succeeds, our current housing will have to be modified (more likely, a new mold made) to incorporate the 8 pin version for 2003.

Ford has offered two configurations for this new connector, one with seven inline, and one with a double row. Assuming the pitch between terminals remains at 5.5mm, I would favor the double row. This follows the same basic design as the current 10 pin, in a smaller shell. The inline version would only be practical if we orient the connector straight up, as with our GM designs. Right now I don't know if internally this would be feasible, though.

If you need a pin-out proposal, please let me know soon. Thursday will be my last day before going on vacation.

Thanks,

Tomas Pino
Product Design
Aptek Williams
854-421-8450 x370
Tpino@WMCO.com

P/T Attributes and Standards Department
NAE P/T Campaign Prevention Specialist
(Phone) 313-33-73831 / (Fax) 313-82-18020
(Pager) 313-795-1878
Cuba 1AF12, MD #3, FPC-A
tshipp@ford.com <mailto:tshipp@ford.com>
www.ford.com <http://www.ford.com>

-----Original Message-----

From: Liposky, Lawrence (L.L.)
Sent: Friday, March 07, 2003 5:52 PM
To: Gleghen, Tom (T.A.); Abar, Robert (R.B.)
Cc: Figurski, Patrick (P.M.); Auler, Jim (J.E.); West, Gregory (G.S.); Shipp, Teri (T.L.); Reed Jr., Bill (W.P.)
Subject: ETC / 6.0L Diesel

Included is the Voice of Customer 6 panel cover sheet addressing Emerging Issue # 328534. We believe that issues associated with the Teleflex Lube Migration issue is tainting our 3 track ETC pedal. We were able to get 5 returned pedals thru a calibration truck today. The pedals executed flawless performance under multiple loading conditions. These pedals were initially returned to supplier and verified good. We have initiated the process thru QRT to send a Special Service Message (SSM) to our dealerships. As noted, Greg West called one dealership that had recently replaced 4 pedals. Service manager could not speak with authority about diagnostic procedure. Just replaced pedals because of previously known issue. Also, I believe warranty dollars include recall parts and are incorrectly represented. I included data directly out of AWS. [Any questions, home # (313) 388-8938.]

<< File: QB 6-Panel328534.ppt >>

Larry Liposky
Supervisor - Accelerator Controls
Tough Truck / Outfitters
Phone 24-81726
Pager 796-0949

-----Original Message-----

From: Desormeaux, Joseph (J.L.)
Sent: Tuesday, June 03, 2003 1:03 PM
To: Abar, Robert (R.B.); McNorton, Michael (M.C.); Howell, Joseph (.);
Chacko, John (J.M.)
Cc: West, Gregory (G.S.); Liposky, Lawrence (L.J.); Figurski, Patrick
(P.M.); Armbruster, Phil (P.J.)
Subject: RE: 2002 7.3L 14401 wiring issues
Importance: High

Team:

I am handling the NAT QB for all of our nameplates. Fortunately, we have leads on each nameplate that are looking into their unique concerns - such as the 7.3L. For the P131/U137/VN127 - contact the following individuals so we can pursue actions. In fact, I know McNorton already initiated this process last week!

P131/U137 - Joseph Howell 14, Michael McNorton
VN127 - John Chacko

Thank You for sending this to us - we really appreciate it! Keep the ideas flowing

Joe

-----Original Message-----

From: Abar, Robert (R.B.)
To: Desormeaux, Joseph (J.L.)
Cc: Abar, Robert (R.B.); West, Gregory (G.S.); Liposky, Lawrence (L.J.); Figurski, Patrick (P.M.); Armbruster, Phil (P.J.)
Sent: 6/3/03 11:38 AM
Subject: FW: 2002 7.3L 14401 wiring issues
Importance: High

Joe,
Please see questions below.

Robert B. Abar
Manager, Powertrain

(313) 84-54247
rabar@ford.com
Room: 1CP20/Rotunda Ct #4

FAX: (313) 24-89073

Mail Drop: LM410

FE03-044 23284

-----Original Message-----

From: McKenzie, Herman (H.)
Sent: Tuesday, June 03, 2003 11:26 AM
To: Abar, Robert (R.B.)
Cc: Desormeaux, Joseph (J.L.)
Subject: FW: 2002 7.3L 14401 wiring issues
Importance: High

Robert,

You should contact Joe Desormeaux on this. He is managing the wiring warranty for Truck Electrical.

Herman McKenzie, P.E.
EBSR EDS Standards & Components
(313) 39-08352

-----Original Message-----

From: Abar, Robert (R.B.)
Sent: Monday, June 02, 2003 10:34 AM
To: McKenzie, Herman (H.)
Cc: Abar, Robert (R.B.); West, Gregory (G.S.); Liposky, Lawrence (L.J.);
Figurski, Patrick (P.M.); Armbruster, Phil (P.J.)
Subject: FW: 2002 7.3L 14401 wiring issues
Importance: High

Herman,
I'm the sub-QB under Brian Wolfe for accel pedals and other PT as-installed components.

We are seeing a spike in our pedal assy warranty (including repeat repairs) associated with the wire routing and the resulting chafing in the area of the shock tower in the 2002 7.3L F-SD series build thru Jan 2002. (See Attached file)

Is your team working on spike recovery from AFL for warranty associated with their wiring design/routing for this specific issue? Given that other systems are also affected by this wiring harness are they also

being pursued?

If not, can we can we go after this as a spike recovery action relating to accelerator pedal warranty and other systems as well for our warranty roadmaps?

Robert B. Abar
Manager, Powertrain

(313) 84-54247 FAX: (313) 24-89073
rabar@ford.com
Room: 1CP20/Rotunda Ct #4 Mail Drop: LM410

-----Original Message-----

From: West, Gregory (G.S.)
Sent: Monday, June 02, 2003 9:19 AM
To: 'MacLeod, Randy'
Cc: Abar, Robert (R.B.); Figurski, Patrick (P.M.); Liposky, Lawrence
(L.J.); Kramer, Michael (M.T.); West, Gregory (G.S.)
Subject: 2002 7.3L 14401 wiring issues

Thanks for the info Randy, I'm aware of the following 14401 circuits affected in the area of the shock tower:

640 R/S power for ETC
1285 IVS for ETC
355 AP for ETC
357 APGRD for ETC
351 VREF for ETC
39, TEMPERATURE GAGE TO TEMPERATURE SENDING UNIT, Red, White
45, HOT WATER TEMPERATURE RELAY TO HOT WATER TEMPERATURE SENDING UNIT,
Yellow, Red
142, DIESEL FUEL FILTER WARNING LAMP INDICATOR FEED, Lt Blue, Red
238, MODULE, POWERTRAIN CONTROL TO FUEL PUMP MONITOR /FUEL PUMP RELAY TO
SAFETY SWITCH, Dk Green, Yellow
787, FUEL PUMP POWER, Pink, Black

Can you tell me if any additional circuits are affected and have AFL look into any warranty spikes related to these affected components from 2002 job #1 through December 2002. Thanks in advance.

-----Original Message-----


From: MacLeod, Randy [mailto:Randy.MacLeod@alcoa.com]
Sent: Monday, June 02, 2003 7:52 AM
To: Gregory West (G.S.) (E-mail)
Subject: 2C3T-14401-JP_JV

These are the harnesses you requested. The release dates are on
the
file
names.

Randy MacLeod, AFL, systems, mailto:Randy.MacLeod@alcoa.com
(313)436-8708 Fax: (313)436-8780 Pager: (313)796-9029


<<QB 9F836 7-3L Repeats 6-2-03.xls>>

2C3Z - 8F836 - DA/DE Pedal Assembly Repeat Repairs
 (Level and Count of Potentially Causal Part)



9500-944 23280

9F836 - Accelerator Pedal Warranty - 2C3Z (DA and DE)
 All 7.3L Diesel Applications



PN93-944 23299

MODEL YR	PROD MC	3	6	12	24	36	RMO
2000	Jul-99	0	0.1	1.32	2.83	3.77	Aug-01
	Aug-99	0.36	0.67	1.02	2	3.14	Sep-01
	Sep-99	0.18	0.44	0.83	2.87	4.07	Oct-01
	Oct-99	0.22	0.35	0.85	1.79	3.14	Nov-01
	Nov-99	0.15	0.34	0.73	2.16	2.86	Dec-01
	Dec-99	0.22	0.43	0.97	2.49	3.29	Jan-02
	Jan-00	0.25	0.49	0.89	2.85	3.76	Feb-02
	Feb-00	0.21	0.38	0.72	2.15		Mar-02
	Mar-00	0.12	0.2	0.67	2.84		Apr-02
	Apr-00	0.17	0.44	0.74	2.28		May-02
	May-00	0.17	0.33	0.82	2.81		Jun-02
	Jun-00	0.18	0.28	0.85	2.54		Jul-02
	Jul-00	0.07	0.34	1.31	2.77		Aug-02
Aug-00	0.89	0.89	2.88	2.88		Sep-02	
2001	Jul-00	0	0	2.03	2.03		Oct-02
	Aug-00	0.36	0.81	2.21	4.48		Nov-02
	Sep-00	0.36	0.64	2.44	5.04		Dec-02
	Oct-00	0.17	0.37	1.71	3.21		Jan-03
	Nov-00	0	0.33	1.28	2.53		Feb-03
	Dec-00	1.08	2.89	8.09	20.86		Mar-03
	Jan-01	0.82	2.01	8.37	21.83		Apr-03
	Feb-01	0.1	0.38	2.47			May-03
	Mar-01	0.12	0.58	0.64			
	Apr-01	0	0.08	0.34			
	May-01	0.07	0.18	0.44			
	Jun-01	0.22	0.37	0.72			
	Jul-01	0	0	0			
2002	Jun-01	0	0	0			
	Jul-01	0.09	0.43	0.52			
	Aug-01	0.12	0.2	0.72			
	Sep-01	0.17	0.23	0.76			
	Oct-01	0.07	0.19	0.78			
	Nov-01	0.23	0.41	0.46			
	Dec-01	0.06	0.06	0.67			
	Jan-02	0	0.09	0.48			
	Feb-02	0.15	0.2				
	Mar-02	0	0.05				
	Apr-02	0.06	0.1				
	May-02	0.23	0.23				
	Jun-02	0.05	0.15				
2003	Jul-02	0.09	0.6				
	Aug-02	0					
	Sep-02	0.07					
	Oct-02	0.08					

606c646

PRODMO Total

Oct-02	2
Nov-02	33
Dec-02	78
Jan-03	77

PRODMO	Nov-02	Dec-02	Jan-03	Feb-03	Mar-03
Oct-02			1	1	
Nov-02	1	8	2	3	12
Dec-02		5	11	10	34
Jan-03			7	13	22

Feb-03	14	Feb-03
Mar-03	2	Mar-03
Apr-03	4	Apr-03

5 7

6.OL 9900+9901

PROD MONTH	
Dec-02	5
Jan-03	9
Feb-03	22
Mar-03	35
Apr-03	11
May-03	
Jun-03	

9N622


MODEL YR	PROD MO	0 MIS	1 MIS	2 MIS	3 MIS	6 MIS	12 MIS
2002	Jun-01	0	0	0	0	0	0
	Jul-01	0.09	0.09	0.19	0.19	0.37	0.47
	Aug-01	0.04	0.13	0.22	0.26	0.26	0.67
	Sep-01	0	0.13	0.32	0.38	0.38	0.77
	Oct-01	0	0.08	0.12	0.16	0.37	1.01
	Nov-01	0	0.14	0.19	0.19	0.47	0.93
	Dec-01	0	0.06	0.06	0.16	0.27	0.62
	Jan-02	0	0	0	0	0.14	0.3
	Feb-02	0	0.05	0.05	0.05	0.05	0.18
	Mar-02	0	0	0.05	0.1	0.15	0.32
	Apr-02	0	0	0	0	0	
	May-02	0.09	0.09	0.14	0.23	0.37	
	Jun-02	0	0.05	0.05	0.05	0.25	
Jul-02	0	0	0	0	0		
2003	Jul-02	0	0	0	0	0	
	Aug-02	0	0.05	0.15	0.21	0.21	
	Sep-02	0	0.05	0.05	0.12	0.12	
	Oct-02	0.12	0.12	0.19	0.19		
	Nov-02	0.73	1.65	2.48	4.72		
	Dec-02	0.34	2.01	5.49	9.53		
	Jan-03	0.08	0.73	1.58			
	Feb-03	0	0.67				
Mar-03							

Apr-03
May-03

PRODMO	7.2L	6.0L
Jan-00	1081	
Feb-00	748	
Mar-00	555	
Apr-00	570	
May-00	558	
Jun-00	785	
Jul-00	350	
Aug-00	603	
Sep-00	618	
Oct-00	924	
Nov-00	162	
Dec-00	113	
Jan-01	142	
Feb-01	102	
Mar-01	153	
Apr-01	168	
May-01	119	
Jun-01	152	
Jul-01	70	
Aug-01	220	
Sep-01	190	
Oct-01	190	
Nov-01	141	
Dec-01	88	
Jan-02	107	
Feb-02	123	
Mar-02	90	
Apr-02	93	
May-02	74	
Jun-02	79	
Jul-02	23	
Aug-02	42	
Sep-02	16	
Oct-02	9	2
Nov-02		33
Dec-02		78
Jan-03		77
Feb-03		14
Mar-03		2
Apr-03		4

6.0 9F836

	0	0.71	7.1	8.82
10/1/2002	0	0.71		
11/1/2002	0.82	3.54	7.1	8.82
12/1/2002	0.85	2.68	4.62	6.94
1/1/2003	0.27	1.24	3.28	
2/1/2003	0.36	2.04		



MODEL YR	PROD. MCT/DS - NA/T/YB - 6.0	T/DS - NA/T/YB - 6.0	T/DS - NA/T/YB - 6.0	T/DS - NA/T/YB - 6.0	T/DS - NA/T/YB - 6.0
2002	Jun-01	0	0	2	2
	Jul-01	0	1	7	21
	Aug-01	2	4	13	55
	Sep-01	3	5	24	70
	Oct-01	4	8	15	53
	Nov-01	1	6	15	61
	Dec-01	3	4	7	35
	Jan-02	3	7	22	43
	Feb-02	7	12	23	49
	Mar-02	5	7	17	55
	Apr-02	2	3	13	53
	May-02	1	4	24	67
	Jun-02	2	8	26	91
2003	Jul-02	2	7	18	48
	Aug-02	4	7	34	85
	Sep-02	3	5	24	57
	Oct-02	4	5	9	
	Nov-02		14	24	44
	Dec-02		9	27	88
	Jan-03		6	33	
	Feb-03		6	14	
	Mar-03				
	Apr-03				
May-03					

7.3 6C848

Total	MODEL YR	PROD MO	MIS 0	MIS 1	MIS 2	MIS 3	MIS 4
1	2000	7/1/1999	0.12	0.37	0.5	0.62	1.12
5		8/1/1999	0.14	0.48	0.86	1.15	1.67
10		9/1/1999	0.08	0.34	0.93	1.57	2.37
18		10/1/1999	0.16	0.32	0.48	0.62	1.24
22		11/1/1999	0.05	0.05	0.24	0.57	1.08
28		12/1/1999	0	0.2	0.51	1.07	1.68
41		1/1/2000	0.08	0.25	0.78	1.53	2.02
75		2/1/2000	0.04	0.25	0.67	1.08	1.5
150		3/1/2000	0.07	0.11	0.33	0.47	0.69
284		4/1/2000	0.08	0.08	0.21	0.59	0.96
426		5/1/2000	0.08	0.21	0.62	0.62	1.21
733		6/1/2000	0	0.08	0.08	0.46	1
884		7/1/2000	0.07	0.14	0.43	0.67	1.51
948		8/1/2000	0	0	0.94	1.87	1.67
1087	2001	7/1/2000	0	0	0	0	0
858		8/1/2000	0.04	0.21	0.64	0.94	1.5
964		9/1/2000	0	0.12	0.25	0.62	1.19
971		10/1/2000	0.17	0.21	0.3	0.47	0.6
402		11/1/2000	0.05	0.05	0.27	0.37	0.48
48		12/1/2000	0	0	0.17	0.23	0.36
6		1/1/2001	0.13	0.21	0.26	0.34	0.52
4		2/1/2001	0.14	0.19	0.24	0.28	0.28
		3/1/2001	0.04	0.21	0.3	0.38	0.47
		4/1/2001	0.05	0.1	0.24	0.34	0.39
		5/1/2001	0.09	0.13	0.16	0.18	0.36
		6/1/2001	0.04	0.13	0.17	0.35	0.38
		7/1/2001	0	0	0	0	0
	2002	6/1/2001	0	0	4.88	4.88	4.88
		7/1/2001	0	0	0.09	0.19	0.19
		8/1/2001	0.04	0.04	0.18	0.31	0.7
		9/1/2001	0.13	0.25	0.38	0.78	1.33
		10/1/2001	0.04	0.2	0.24	0.33	0.67
		11/1/2001	0.05	0.19	0.19	0.19	0.52
		12/1/2001	0.06	0.06	0.06	0.11	0.22
		1/1/2002	0.05	0.14	0.43	0.62	0.82
		2/1/2002	0.05	0.26	0.32	0.64	0.69
		3/1/2002	0.1	0.15	0.35	0.4	0.6
		4/1/2002	0.06	0.1	0.21	0.41	0.52
		5/1/2002	0.05	0.09	0.23	0.6	0.68
		6/1/2002	0.06	0.28	0.33	0.47	0.62
		7/1/2002	0	0	0	0	0
	2003	7/1/2002	0.1	0.38	0.69	0.8	1.15
		8/1/2002	0.1	0.2	0.25	0.6	1.04
		9/1/2002	0	0	0.12	0.24	0.46
		10/1/2002	0.12	0.12	0.12	0.28	0.28
		11/1/2002	0	0	0	0	0
		12/1/2002	0	0	0	0	0
		1/1/2003	0	0	0	0	0
		2/1/2003	0	0	0	0	0
Apr-03							
6							
18							
35							

90736

MODEL YR	PROD	MO	0 MIS	1 MIS	2 MIS	3 MIS	6 MIS
2000	Aug-99		0	0	0	384.88	560.05
	Sep-99		133.75	1249.45	2197.89	2394.55	3341.34
	Oct-99		0	313.9	700.06	700.06	1778.07
	Nov-99		0	183.99	512.77	684.07	1723.82
	Dec-99		171.55	771.1	982.38	1145.33	1639.47
	Jan-00		74.07	74.07	74.07	433.55	789.93
	Feb-00		29.32	425.93	738.05	1195.14	1947.35
	Mar-00		462.86	647.64	1345.06	2345.33	3285.96
	Apr-00		738.28	1066.12	1066.12	1982.55	2617.92
	May-00		132.72	485.28	1178.32	1784.9	2274.6
	Jun-00		0	358.4	909.84	1542.97	2330.31
	Jul-00		170.9	525.4	802.81	1100.14	1735.72
Aug-00		0	0	135.87	135.87	303.63	
2001	Aug-00		255.39	1064.2	1064.2	1064.2	1719.94
	Sep-00		447.2	796.82	981.76	1387.87	1727.54
	Oct-00		0	474.02	474.02	508.31	642.48
	Nov-00		153.26	153.26	153.26	153.26	842.64
	Dec-00		0	330.49	619.15	1210.71	1508.02
	Jan-01		181.08	341.36	341.36	341.36	673.41
	Feb-01		147.95	427.72	736.89	883.84	1351.7
	Mar-01		186.18	695.38	884.31	1209.28	2089.01
	Apr-01		305.25	776.46	776.46	776.46	1482.18
	May-01		0	708.77	1324.56	1473.89	2474.08
	Jun-01		178.07	341.02	1832.13	1797.05	2183.81
	Jul-01		0	199.92	199.92	199.92	199.92
2002	Jul-01		380.8	834.73	834.73	834.73	811.31
	Aug-01		215.16	1106.42	1614.37	2408.54	2833.15
	Sep-01		0	774.47	1001.27	1486.57	1885.89
	Oct-01		0	1837.73	2700.45	3341.99	3938.43
	Nov-01		735.35	1417.97	1633.92	1633.92	2008.76
	Dec-01		290.23	891.76	1254.28	1849.7	2482.44
	Jan-02		0	775	775	775	1372.97
	Feb-02						
2003	Feb-02						
	Mar-02		716.74	864.92	1084.77	*1084.77	1807.48
	Apr-02		358.64	1413.18	1413.18	1738.18	2839.75
	May-02		689.89	1496.39	1780.63	1780.63	2519.81
	Jun-02		3014.3	9748.11	14160.34	18878.39	23068.85
	Jul-02		2023.64	7420.64	8099.48	12718.59	17088.78
	Aug-02		3844.93	17232.95	22682.67	27912.18	35843.5
	Sep-02		508.08	7053.72	10008.82	12064.58	16306.35
	Oct-02		1171.75	10286.13	17687.42	22491.57	
	Nov-02		619.54	4039.47	5070.91	7270.72	
	Dec-02		276.3	1388.82	1848.83	2329.98	
	Jan-03		0	971.03	1380.32		
	Feb-03		146.58	489.08			

9C735 3D

PRODMO	Oct-99	Nov-99	Dec-99	Jan-00	Feb-00	Mar-00
Aug-99			1	2		
Sep-99	2	3		2	1	1
Oct-99			1		2	1
Nov-99				1		
Dec-99				1	1	1
Jan-00					1	
Feb-00					1	
Mar-00						
Apr-00						
May-00						
Jun-00						
Jul-00						
Aug-00						
Sep-00						
Oct-00						
Nov-00						
Dec-00						
Jan-01						
Feb-01						
Mar-01						
Apr-01						
May-01						
Jun-01						
Jul-01						
Aug-01						
Sep-01						
Oct-01						
Nov-01						
Dec-01						
Jan-02						
Mar-02						
Apr-02						
May-02						
Jun-02						
Jul-02						
Aug-02						
Sep-02						
Oct-02						
Nov-02						
Dec-02						
Jan-03						
Feb-03						
Mar-03						
Apr-03						

11.58

T/DS - NAVISTAR 7.3L OHV DI TC V8 DSL

3
70
178
193
168
175
133
177
209
194

MIS 5	MIS 6	MIS 7	MIS 8	MIS 9	MIS 10	MIS 11	MIS 12	MIS 13
1.62	2.25	2.87	3.37	3.82	3.74	4.37	4.87	5.49
2.2	3.16	3.92	4.74	5.41	6.03	6.65	7.37	7.94
3.9	5.04	6.14	7.45	8.94	10.42	11.22	11.86	12.58
1.6	2.12	2.88	3.68	4.2	4.68	5.36	6.2	7.16
1.81	2	2.38	2.81	3.47	3.9	4.62	5.09	5.81
1.99	2.65	3.62	4.68	5.5	6.87	8.91	10.54	12.27
2.77	3.72	5.29	6.81	8.43	10.12	11.85	13.51	15.78
1.88	2.36	3.08	4.48	5.92	7.21	8.84	10.5	11.63
1.12	1.78	2.36	3.01	3.85	4.75	5.33	6.05	6.6
1.38	1.84	2.51	3.38	4.52	5.48	6.11	7.2	7.68
1.83	2.37	3.24	4.16	5.12	5.95	6.99	7.66	8.2
1.5	2.15	2.96	3.77	5.16	6.15	6.89	7.81	8.46
2.16	2.6	3.1	3.9	4.54	5.12	5.77	6.42	7.14
1.87	2.81	3.75	5.62	5.62	6.55	8.43	9.36	11.24
0	1.07	1.07	3.2	4.27	4.27	5.34	6.42	7.49
2.28	3.09	3.87	4.51	4.98	5.97	6.71	7.61	8.82
1.77	2.47	3.33	4.24	4.85	5.55	6.5	7.56	8.82
0.85	1.15	1.62	1.97	2.27	2.87	3.51	4.11	4.84
0.8	1.02	1.12	1.39	1.55	1.77	2.04	2.3	2.63
0.4	0.82	0.69	0.98	1.09	1.44	1.61	1.67	1.96
0.6	0.82	0.94	1.25	1.37	1.68	1.81	2.19	2.58
0.33	0.47	0.61	0.75	0.99	1.13	1.46	1.78	1.94
0.69	0.89	1.02	1.23	1.36	1.78	2.33	2.5	2.67
0.49	0.92	1.22	1.9	2.29	3.02	3.36	3.81	3.95
0.49	0.58	0.8	1.12	1.21	1.48	1.88	2.06	2.24
0.43	0.69	1	1.43	1.74	2	2.53	2.71	3.11
0	0	0	0	0	0	0	0	0
4.88	4.68	9.78	9.78	9.78	9.78	9.78	9.78	9.78
0.68	0.66	0.75	1.23	1.71	2.29	2.69	2.69	3.31
1.19	1.41	1.9	2.35	3.02	3.21	3.72	4.28	5.04
1.71	2.15	2.63	3.17	3.89	4.55	5.01	6.03	7.13
0.85	1.35	1.8	2.1	2.48	3	3.66	4.2	4.9
0.71	1.29	1.43	1.86	2.23	2.85	3.38	4.04	5.21
0.27	0.71	0.82	1.32	1.96	2.38	2.81	3.21	3.99
0.91	1.06	1.3	1.81	2.13	2.62	3.49	4.21	4.89
0.85	1.23	1.67	2.24	3.14	4.24	6.92	6.56	7.28
1	1.36	1.78	2.27	2.82	3.97	4.36	4.95	
0.88	1.33	1.89	2.82	4.28	4.85	5.37		
1.21	1.35	1.97	2.85	3.83	3.94			
1.17	1.95	2.91	3.38	4.24				
0	0	0	0					
1.56	2.04	3.16	3.16					
1.67	2.25	2.61						
0.46	0.95							
0.58								

12 MIS	16 MIS	24 MIS	30 MIS	36 MIS	42 MIS
1449.31	2459.5	3182.45	3688.42	3948.89	3948.89
4306.44	8110.4	8621.01	8779.49	7110.11	7110.11
3493.81	5959.06	7756.5	8502.75	8941.08	
4015.63	6155.55	7469.41	8768.36	8768.36	
2015.42	3510.1	3896.55	6421.91	7090.77	
1482.76	2383.11	2818.37	3812.3	3857.69	
2916.86	3760.04	4865.02	5187.95	5490.01	
4976.19	7442.99	9405.36	9706.67	9706.67	
3820.59	4747.98	5637.74	7180.39		
4485.45	5806.69	6804.74	9124.12		
4322	6350.51	7365.32	7894.13		
2832.88	3098.2	3132.49	3368.89		
486.05	744.02	1825.78	1987.24		
2777.89	3147.17	3951.42	4022.87		
2485.89	3509.16	4810.58	5008.96		
2152.55	3115.86	3821.47			
1612.52	4948.78	6037.81			
1856.49	2576.5	4239.73			
1184.15	1880.87	2307.65			
1918.43	2103.52	3102.73			
3824.21	4364.94	4364.94			
3168.84	4524.84				
3205.21	4084.82				
3038.52	5207.66				
377.82	663.15				
1330.88	1508.69				
3825.39	4828.67				
2890.8	3845.16				
4963.08					
3245.27					
3324.84					
2052.15					

Apr-00	May-00	Jun-00	Jul-00	Aug-00	Sep-00	Oct-00	Nov-00	Dec-00
	1	1		1	1	2		1
3		2	4	1	2	2	1	2
1	1	2	1	1		2	4	2
2	1	2	1		2	1		1
1	1	4			1	2	1	2
	3			1		2	3	
	3	3	1	1		1	1	1
1		4	3	3	2	1	1	1
	5		1	1	2	6	1	1
			2	2	1	3	2	2
				1	2	2	3	3
				3			3	3
					1	1		
						1	2	
								1
								1

MIS 14	MIS 15	MIS 16	MIS 17	MIS 18	MIS 19	MIS 20	MIS 21	MIS 22
5.74	5.89	6.49	6.99	7.82	8.12	8.82	8.87	9.24
8.71	9.52	10.16	11.1	11.58	12.49	13.07	13.98	14.27
13.17	14.11	14.74	15.6	16.85	17.54	18.26	19.49	20.09
7.88	8.72	9.36	9.84	10.66	11.36	12.04	12.73	13.29
6.88	7.85	8.71	9.52	10.28	10.61	10.95	11.38	12
13.85	15.38	16.5	17.41	17.97	18.48	19.2	20.27	21.6
17.8	19.46	20.57	21.36	22.64	23.39	24.55	25.54	27.04
12.69	13.51	14.34	14.87	15.8	16.68	17.43	18.31	19.06
6.96	7.76	8.16	8.78	9.5	10.08	10.85	11.68	12.56
8.16	8.5	9.17	9.84	10.43	11.27	12.69	14.12	15.3
8.86	9.4	10.07	10.69	11.44	12.32	13.57	14.7	15.92
9.77	10.76	11.82	12.97	13.98	15.18	16.84	18.28	19.45
7.94	8.73	9.82	11.48	12.58	14.38	15.47	16.49	17.86
12.17	13.11	13.11	14.05	14.05	14.98	14.98	14.98	16.88
7.49	9.88	11.82	14	16.17	16.17	18.41	19.54	21.85
8.85	11.69	12.82	13.95	15.45	16.52	17.85	18.4	18.78
10.07	12.03	13.49	14.5	15.82	17.11	17.82	19.18	20.01
6.23	5.75	6.27	7.64	8.29	9.09	9.79	10.34	11.12
3.22	3.92	4.2	4.74	4.96	5.47	6.76	6.23	6.54
2.48	2.89	2.95	3.24	3.54	3.84	4.34	4.6	5
2.78	3.11	3.5	3.81	3.9	4.27	4.42	4.78	5.11
2.08	2.22	2.51	2.78	3.2	3.3	3.47	3.58	4.02
2.93	3.15	3.28	3.72	4.21	4.77	5.03	5.36	5.98
4.3	4.54	4.99	5.5	5.76	6.31	6.85	7.79	8.26
2.47	2.56	2.7	3.08	3.38	4.35	5.18	5.7	6.12
3.25	3.7	4.28	4.88	5.48	6.24	6.68	7.34	
0	0	0	0	0.87	0.87	0.87		
9.78	9.78	9.78	9.78	9.78				
3.83	4.48	5.06	5.94	6.87	7.93	8.48		
5.83	6.84	7.78	8.89	9.86	10.9			
8.28	9.47	10.95	12.25	13.29				
5.89	6.93	8.09	8.9					
5.91	7.04	7.84						
4.81	5.93							
6.07								

Jan-01	Feb-01	Mar-01	Apr-01	May-01	Jun-01	Jul-01	Aug-01	Sep-01
1	1	1		1			1	
3	3			2		1		
2	1	2	1	3		2	1	2
2	3		1	2	2	1	3	2
	1	1		2	1		1	1
	1			1	2			1
1				1		1	1	
1			2	3	1	4	3	3
1		3	1	1		1		1
4	1		1	1	5		2	
	2			4	1		2	2
1		1	2	2				1
1			2	3		1	4	1
2			1	2	1		1	
1	1				1			1
					2	2	1	1
	1	1	2		1	3		
	2					1		1
				1		3		
				1		1		
			1		1		4	1
							2	1
							5	1
							1	3

MIS 23	MIS 24	MIS 25	MIS 26	MIS 27	MIS 28	MIS 29	MIS 30	MIS 31
10	10.88	11.38	11.78	12.14	12.65	13.04	13.55	14.19
14.85	14.89	15.42	16	16.34	17.46	18.28	19.31	20.14
21.37	22.01	22.86	23.46	24.19	25.22	25.78	26.48	27.61
18.97	14.78	15.67	16.48	17.26	18.16	18.85	19.68	20.14
12.91	13.63	14.38	15.26	16.18	16.9	17.68	18.32	18.91
22.88	23.75	25.7	27.35	29.17	30	30.78	31.52	32.42
28.49	30.54	32.33	34.06	35.79	36.52	37.33	38.19	38.98
20.24	21.58	22.85	24.04	24.55	25.33	26.11	26.76	27.34
13.51	14.06	14.73	15.32	15.92	16.3	16.75	17.1	17.46
16.57	17.63	18.02	18.64	19.38	19.71	20.11	20.38	21.13
16.81	17.44	18.08	18.73	19.34	19.74	20.01	20.76	21.3
20.23	20.9	21.66	22.63	23.67	24.34	25.39	26.67	28.3
18.1	19.07	19.69	20.67	20.23	21.15	22.13	22.9	23.67
16.88	16.88	17.86	17.86	17.86	18.98	20.15	25.58	27.42
23.03	23.03	26.82	28.14	28.5	28.5	31.06	31.06	31.06
19.71	20.62	21.51	22.5	23.13	24.37	25.51	26.52	26.91
20.55	21.31	22.31	23.43	24.2	25.57	26.96	27.86	
11.47	11.84	12.5	12.92	13.43	14.36	15.18		
5.86	7.62	7.98	8.46	9	9.45			
5.22	5.8	6.19	6.87	7.22				
5.77	6.11	6.67	7.09					
4.23	4.82	5.56						
6.68	8.97							
8.47								

Oct-01	Nov-01	Dec-01	Jan-02	Feb-02	Mar-02	Apr-02	May-02	Jun-02
1	1					1		
	1	1						
1	1	1	1		3		1	
2		1	3		1			2
1	2	4				2	2	2
1	1				1	1		2
2			4	1	1			
2	2		2	5	3			1
2			1		3			
2	2	2	3	1		1	1	
2		2	1	2		1		
2		1						1
1	2		1	2	2		1	
1	2	1	1	2	1		3	1
1	2	1	1	1	1	1		1
1			1	1	3	4	2	
1				2				
			1	1		1	1	
1	2	1			1		2	2
5	2	3	2	1	1	2	1	2
1			2	3	3		1	3
1	3	2			1			1
1		1		1	1	1		1
					1	2	1	1
1	3		1		2	1	4	1
1	1		2	1		2	2	1
		1	2	1	4	1	1	7
	1			1		4	4	2
			1	1	1		3	2
							2	
								1
							1	4

MIS 32	MIS 33	MIS 34	MIS 35	MIS 36	MIS 37	MIS 38	MIS 39	MIS 40
14.45	14.71	15.5	15.76	16.3	16.57	17.27	17.65	17.84
20.74	21.43	21.98	22.49	22.95	23.16	23.42	23.7	23.82
28.35	28.70	28.73	30.22	30.88	31.19	31.76	32.31	32.89
20.69	21.16	21.63	22.03	22.89	23.61	24.4	24.98	25.53
19.67	19.92	20.6	21.02	21.46	22.2	22.86	23.74	24.37
32.60	33.56	34.45	35.36	36.07	36.82	37.64	38.21	
39.36	40.16	41.01	41.84	43.31	44.82	45.31		
27.84	28.21	28.89	29.5	30.5	31.58			
17.95	18.55	19.24	19.9	20.44				
21.81	22.7	23.34	24.45					
22.32	23.22	23.73						
28.72	30.24							
24.42								

31.06

Jul-02	Aug-02	Sep-02	Oct-02	Nov-02	Dec-02	Jan-03	Feb-03	Mar-03
				1				
		1						
1	1	1	1		1			
			1				1	
1	1		1	1				
2								
2	1	1	1	2	1	3	1	2
1	1	1	2	1	3	2		
1	1			2	1			
						1		
	1	1		1	1	2		
	2	1	2		1	1	1	
1	1	1		2		1		
	1	2	1					1
1	2		1	2	3			
			1	2				1
1			1			1	1	1
1	2		1			2	1	1
3	2		1	3	1	1	1	
					1		1	1
1		4	1		1	1		2
1	2	3	1	1		1	1	2
5		1	1		2		1	
1	1		4	1	1		1	1
3		2	1	1		1	1	1
2	3			1			2	
1	1	1	2	2			1	4
1	1	1	2	1	3	4	1	1
3	2	1	3	2	4	4		1
7	15	20	22	23	14	22	10	17
	8	11	24	14	13	17	4	11
	2	13	26	26	34	38	16	18
		3	4	20	14	19	15	15
				3	21	56	35	31
				2		4	9	12
					3		8	5
						1	1	6
							1	2

MIS 41	MIS 42	MIS 43	MIS 44
18.3	18.8	19.36	19.61
24.4	24.85	25.78	
33.53	34.35		
25.81			

Apr-03

1

2

1

1

2

2

1

1

3

8

7

21

7

31

10

6

5

6

2

1



2001		2002		2003 (January to 2003 CY Proj)		2003 Proj w/Ret			
\$	0.97	\$	0.97	\$	1.05	\$	1.07	\$	0.89

Vehicle Line	9F836 - PEDAL & 80840 - DUCT AS	8038 - INSULATOR	80735 - SERVO S	8028 - BRKT ASY-	9800 - DUCT SH-
T/F7 - F250	\$ 827,042	\$ 654,401	\$ 10,884	\$ 20,013	\$ 66,156
C/AJ - ESCORT/TRACER (CT120) [87-03]			\$ 180,097	\$ 2,187	\$ 207,764
C/AK - FOCUS (CW170) [94-03]	\$ 126	\$ 106,086	\$ 34,117	\$ 508	\$ 18,011
T/F5 - F150	\$ 1,043	\$ 282	\$ 63,726	\$ 67,908	\$ 783
C/DD - TAUF	\$ 216	\$ 68,361	\$ 34,870	\$ 177	\$ 18,212
T/L1 - EXCU	\$ 74,855	\$ 64,401	\$ 1,787	\$ 5,768	\$ 7,816
T/R7 - EXPE	\$ 74	\$ 4,323	\$ 106,348		\$ 1,138
T/E4 - ECON	\$ 26,180	\$ 482	\$ 8,873	\$ 30,282	\$ 33
T/M1 - ESCA	\$ 78	\$ 4,857	\$ 28,059		\$ 2,282
T/U5 - EXPL	\$ 411	\$ 282	\$ 10,388	\$ 22,641	\$ 10,073

Pickup Tru	T/F7 - F250HD	1489942.32
	T/F5 - F150/25	210603.63
	T/L1 - EXCUR	159713.11
	T/E4 - ECON	126583.21
	T/R8 - RANGE	83791.78
	T/Y3 - F-STRIF	42704.01
	H/FC - H215 (29801.19
Small FWD	C/AJ - ESCOR	433156.96

Original: Joe Case/jcase1
 QB 9F836 7-GL Reports 8-2-03.xls

	C/AK - FOCUS	220327.95
	C/ZE - MUSTA	84083.4
	T/A3 - WINDS	79384.85
SUVs and	T/B7 - EXPEDI	126749.68
	T/M1 - ESCAP	97276.39
	T/U5 - EXPLOI	85274.6
	C/VC - LINCOL	73383.25
	C/FP - GRAND	58505.86
	C/LQ - LINCOL	54488
	T/B4 - NAVIGA	46825.23
	T/B3 - EXPEDI	41885.78
	C/FB - CROWI	38004.8
	T/U3 - EXPLOI	34477.59
Med/Large	C/DD - TAURL	237606.21
	C/DC - TAURL	347.66

2008 Target		2002				
\$	0.7	January-02	February-02	March-02	April-02	May-02
		\$ 1.19	\$ 0.94	\$ 0.98	\$ 0.95	\$ 0.88

Jan-02	\$ 1,132,475	1.13247482
Feb-02	\$ 838,827	0.93882692
Mar-02	\$ 877,892	0.97789245
Apr-02	\$ 854,172	0.85417227
May-02	\$ 881,901	0.88190082
Jun-02	\$ 832,148	0.83214751
Jul-02	\$ 840,254	0.94025425
Aug-02	\$ 872,593	0.97259262
Sep-02	\$ 888,050	0.88805048
Oct-02	\$ 1,072,191	1.07219124
Nov-02	\$ 950,853	0.95085276
Dec-02	\$ 892,349	0.99234892
Jan-03	\$ 1,243,306	1.24330616
Feb-03	\$ 888,179	0.98817939
Mar-03	\$ 891,300	0.89130001
Apr-03	\$ 856,736	0.8567357
May-03		

0008 - INSULATOR	0A768 - CABLE-AC	0A825 - ACTUATC	0B808 - TUBE-AIR CLNR	OUTLET
\$ 7,513	\$ 1,558	\$ 706	\$ 2,943	
\$ 54,835	\$ 1,081	\$ 111	\$ 840	
\$ 23,528	\$ 12,884	\$ 5,985	\$ 1,082	
\$ 15,258	\$ 8,071	\$ 4,901	\$ 8,089	
\$ 18,004	\$ 30,861	\$ 4,803	\$ 5,128	
\$ 440	\$	\$ 93	\$ 258	
\$ 881	\$ 1,044	\$ 1,028	\$ 808	
\$ 2,791	\$ 3,105	\$ 811	\$ 1,830	
\$ 8,898	\$ 25,180	\$ 15,887	\$ 745	
\$ 3,498	\$ 27,398	\$ 3,670	\$ 3,838	

Originator: Joe Case/jcase1
CB 9F836 7-3L. Reports 6-2-03Lds

Page 4 of 8

Date Issued:
Date Revised: 4/3/03

FE83-644 23312

June-02	July-02	August-02	September-02	October-02	November-02	December-02
\$ 0.83	\$ 0.94	\$ 0.97	\$ 0.90	\$ 1.07	\$ 0.95	\$ 0.99

2003				
January-03	February-03	March-03	April-03	May-03
\$ 1.24	\$ 1.00	\$ 0.89	\$ 0.86	

2002 P131U137 CSE PROGRAM

PAV DURABILITY ASSESSMENT AT ENGINEERING SIGN-OFF

MAJOR/MINOR RISKS:

For has at meeting

P131 Rear Air Suspension (3 of 3 vehicles; 6% Structures; CR C11177498, C11144394)
Multiple issues all units: loose and broken fasteners. Not being able to maintain ride heights etc.
Approximately 15 CR's have been written against P131 Air Suspension since testing began. Various components/issues are not proven out on full Durability. Projected Minor Risk: Spring 2001

P131U137 New Electrical Architecture (2 of 3 vehicles; 4% Structures; CR C11147878, C11148124, new CR pending on recent issue - North Kiewit)
Issues on power distribution box relocated to inside of vehicle: Fuses falling out - terminal tension is too low. Relay loose in power distribution box on 12/14/00 - new CR pending. Projected Minor Risk: Spring 2001

Do

P131 18+40 gallon fuel system (3 of 3 vehicles; 75% Structures; CR C11893388)
Broken Fuel Tank Straps. Projected Minor Risk: Spring 2001

U137 Rear Seat Entertainment Center (1 of 1 vehicles; 25% Structures; CR C11161250, C11197167)
Issues with DVD attachment to roof and DVD player. DVD screen fringes fasteners pulled out/screen dropped down. DVD player assembly would not stay attached to roof at right retainer clip. Updates have been made but the Various components/issues are not proven out on full Durability. Projected Minor Risk: Spring 2001

Phil

P131U137 Adjustable Brake Pedal/Accelerator pedal (2 of 2 vehicles; CR C11182255, C11157688)
Within several hundred test miles of update, the updated Accelerator pedal (1C3E-9728-ACX) binds resulting in 1000 to 2000 rpm high idle. Both units (310W319 & 310W321) had original production Accelerator pedals reinstalled to continue testing. Updated components not available yet. Projected Minor Risk: Summer 2001

Redid updated 1/03 12/18/2000

*Denise -
Please copy Phil B., Dan M^c
This was on today's 2002 Signoff
Book. Have the issues been
resolved? Tom*