


**PE03-044**  
**FORD**  
**5/13/2005**  
**APPENDIX I**  
**BOOK 22 OF 28**  
**PART 3 OF 4**

**002 MYTD 7.3L SUPER DUTY - 9F836 - Stack Chart**  
**Part Num Full (causal) [typed] = [2C3Z,9F836,%]**



PE03-944 23703

Prepared by P133A/1327/WH127 P10/RT  
 Contact: TONAL

**Burrows, Jim (J.A.)**

---

**From:** Conrad, James (J.A.)  
**Sent:** Tuesday, June 25, 2002 11:32 AM  
**To:** Burrows, Jim (J.A.)  
**Subject:** ETC Pedal Warranty

**Follow Up Flag:** Follow up  
**Flag Status:** Flagged

Jim,

Here is the 2001 and 2002 warranty in the format Bill likes used originally. The big bulge starting in Aug. 2000, was caused primarily by the accelerator pedal pad falling off. This is at least the third time this has happened to Teleflex that I know of. The knurled pin holding the pad on was out of spec. Interestingly, the dealers are using the Williams pedal as the replacement, if the part number listed on the claims is correct. The sudden increase in the 8 MIS warranty line between Aug and Sep. 2001, appears to be caused by PCM and wiring problems being billed against the pedal.




MOP pedal  
warranty.xls

*Jim Conrad*

Accelerator Controls & Air Induction Subsystems  
Powertrain Subsystems Engineering Technology Dept.  
GCE / P&AE - Core & Adv P/T Engrg. (CAPE)  
Location: FPC-A Mail Drop: #3 Cube: 1A15  
E-MAIL: jconrad1@ford.com  
Phone: (313) 33-76483 Fax: (313) 62-18020

<mailto:conrad1001.fpc.ford.com/1362/index.asp.html>

>8500 ETC Diesel Pedal Warranty




FE83-044 23783


	3 MIS	6MIS	9MIS	12MIS
Aug, 2000	2.16	3.22	4.35	
Sep, 2000	3.31	4.68	6.24	
Oct, 2000	1.58	3.84	7.45	
Nov, 2000	3.21	9.5	16.65	
Dec, 2000	3.38	11.01	19.39	
Jan, 2001	9.84	21.84	32.86	
Feb, 2001	7.97	18.26	28.63	
Mar, 2001	10.34	16.63	21.43	
Apr, 2001	7.63	10.71	13.31	
May, 2001	7.68	10.04	12.69	
Jun, 2001	0.94	1.88	2.65	
Jul, 2001	2.16	3.62	4.25	
Aug, 2001	3.01	4.51		
Sep, 2001	4.89	6.58		
Oct, 2001	2.66	9.81		
Nov, 2001	3			
Dec, 2001	3.16			
Jan, 2002	3.73			
Feb, 2002				
Mar, 2002				
Apr, 2002				
May, 2002				

U-137


MY-2001




100K cycles TA 7749




FEB-64 11665




100K cycles TA 7749






100K cycles TA 7749




FE83-044 11687







200K cycles TA 7749




PER3-844 11885




200K cycles TA 7749



PER3-044 11888




200K cycles TA 7149




PER3-844 1187B

From "Greg Braniff" <gbraniff@tfxauto.com>  
Date Monday, September 9, 2002 12:11 pm  
To zkhan1@tfxauto.com, Greg West <gwest2@ford.com>, Larry Liposky  
<lliposky@ford.com>, kzolan@tfxauto.com, Joe Vitale <jvital@wabashtech.com>  
Subject Phenolic Parts after 461K cycles

Greg Braniff  
Teleflex Automotive  
Ph 248-616-3107  
Cell 248-840-1840  
gbraniff@tfxauto.com




File: 461-1.jpg




File: #61-2.jpg






File: 461-3.jpg







File: 461-4.jpg



File: 461-5.jpg





File: 461-6.jpg

[http://www.fcc.gov/html](#)  
[Redacted]



From "Zulqarnain Khan" <zkhani@tfxauto.com>

Date Monday, October 21, 2002 3:11 pm

To zkhani@tfxauto.com

Subject u-137 DOE


Attachments [Mvc-114f.411](#) 4K [Mvc-115f.411](#) 4K [Mvc-116f.411](#) 4K  
[Mvc-118f.411](#) 4K [Mvc-125f.411](#) 4K [Mvc-127f.411](#) 4K  
[Mvc-130f.411](#) 4K

U-137

Post 1M cycles

TA# 7749

PHENOLIC BOARD.



File: 1 MN--1.JPG

10/21/02

PE83-844 11876




File: 1 NII--5a.JPG



10/21/02

PE63-044 11877




File: 1 FBI-5b.JPG



10/21/02

PER3-844 11878




File: 1 Mill-6.JPG .



10/21/02

PEB3-844 11673




File: 1MHI-2.JPG



10/21/02

FEB3-044 11000




File: 1MB-3.JPG



10/21/02

PE03-044 11001



File: 1N111-4.JPG



10/21/02


FBI-044 11882

From "Zulqarnain Khan" <z Khan1@tfxauto.com>  
Date Tuesday, October 1, 2002 4:36 pm  
To gwest2@ford.com, lliposky@ford.com, kzolan@tfxauto.com,  
gbrani1@tfxauto.com, bpietrzak@wabashtech.com  
Subject Fwd: U-137 Adj ETC with Phenolic after 2M cycles.  
Attached, are the digital pictures of six pedals with phenolic after 2M cycles.

Khan

----- Original Message -----

From "Zulqarnain Khan" <z Khan1@tfxauto.com>  
Date Tue, 01 Oct 2002 16:26:19 -0400  
To z Khan1@tfxauto.com  
Subject U-137 Adj ETC with Phenolic







248



File: 774901a.jpg




File: 774901b.jpg




11884






File: 774902a.jpg





File: 774902b.jpg





File: 774903a.jpg





File: 774903b.jpg






File: 774904a.jpg





File: 774904b.jpg





File: 774905a.jpg





File: 774905b.jpg





File: 774906a.jpg







File: 774906b.jpg



*Sleatha - meet w/ Purchaser  
before Purch/Reliefly  
meeting.*

## Adjustable Pedals Issues Meeting

11/30/2000

Issues:

Concerns:

- C11157559 - Accelerator pedal broke when dropped

### Reinforced Accelerator Bracket with Steel Stamping

1. Design Reinforced Accel Bracket Support:	2wks	11/28/00	12/8/00
2. Prototype new Design	3wks	12/8/00	12/22/00
3. DV Testing	8wks	1/3/01	2/28/01
4. Production tooling for bracket	16wks	12/8/00	3/30/01
5. Tool Tryout	1 wk	3/30/01	4/6/01
6. PSW Steel bracket reinforcement to Kendellvill	1 wk	4/6/01	4/8/01
7. Revise Plastic Accel bracket	7 wks	12/8/00	2/1/01
8. Assembly Equipment	7 wks	12/8/00	2/1/01
9. Equipment Layout	1 wk	2/2/01	2/9/01
10. PSW run	1 wk	2/12/01	2/19/01
11. PV Test	8 wks	2/12/01	4/9/01
12. PSW		4/16/01	

### Steel Throttle Retainer:

1. Design Steel Throttle Retainer	2wks	11/28/00	12/8/00
2. Prototype new Design	3wks	12/8/00	12/22/00
3. DV Testing	8wks	1/3/01	2/28/01
4. Production tooling for retainer	7wks	12/8/00	2/2/01
5. Tool Tryout	1 wk	2/2/01	2/9/01
6. PSW Steel retainer to Kendellville	1 wk	4/6/01	4/8/01
7. Weld fixturing	7 wks	12/8/00	2/1/01
8. Weld Tryout	1 wks	12/8/00	2/1/01
9. Install/Debug weld equipment Kendellville	1 wk	2/2/01	2/9/01
10. PSW run	1 wk	2/12/01	2/19/01
11. PV Test	8 wks	2/12/01	4/9/01
12. PSW		4/16/01	

\*DV testing is Drop Test

PV testing with low volume tool - everything else will be production

11/30/2000 10:54 AM

PE83-844-R 8792

**Anti-rotation ribs for ETC support:**

1. HTFB
2. PSW

12/8/00

2/12/01

**Brake Motor & Memory Sensor**

Under investigation.

- Wrapping motor & sensor in foam (Noise level should improve)
- Provide protection bracket around motor/sensor

- C11157558 -- BOO switch wiring interferes with accel pedal

Under investigation.

- CAD shows 6mm of clearance - 19mm is needed
- Move guide rod down to provide 19mm of clearance from switch
- Tolerance study from electrical - due today at Noon
- CAD data showing switch and foot clearance zone required for Teleflex

- C11157564 -- Clearance between heat duct & accelerator track rod

Waiting for cost & timing from Visteon/Lear

Provide 19mm of clearance around track rod

Possibilities:

- New attachment point for foot heater duct - need VO buy in
- Strengthening flange on duct - adding more ribs
- bracket come pia to duct for easier installation

- C11157557 -- Accelerator pedal has contact with carpet

Propose closure for this concern.

CAD data shows 4.13mm clearance between diesel accelerator pedal in WOT and floor carpet. The standard allows zero clearance to carpet for pedal with a positive stop. WOT. The diesel adjustable pedal has positive stop. LT-26 test will be performed to confirm there are no any binding issues.

*FRUSS Related  
SDB - design Standard*

*- if it's easy with  
lost comfort  
- EVT - experience  
of carpet hitting  
carpet*

11/30/2000 12:47 PM

PE83-944-A 0783

---

**From:** Kramer, Michael (M.T.)  
**Sent:** Thursday, January 16, 2003 4:56 PM  
**To:** Liposky, Lawrence (L.J.); West, Gregory (G.S.)  
**Subject:** FW: 2002 and 2003 F Series Super Duty and Excursion Adjustable Pedal

CQIS and NHTSA VOQ info. Especially note VOQ info. at bottom of note. Will have AWS claims info. tomorrow.

*The company that builds and delivers the best products wins!*

**Mike Kramer**

**Supervisor, Super Duty/Excursion/E-Series PTQRT & OPD PT PMT (non-MCR)**

**Six Sigma Black Belt**

**Phone/fax:** (313) 594-2003

**Page:** (313) 201-9852 (beep); <<http://m4.detroit.ford.com/cpl/hairpage/>> (internal text); [http://mysatmail.com/](mailto:mikr@mysatmail.com) (external text)

**Email:** [mikramer1](mailto:mikramer1) (internal); [mikramer1@ford.com](mailto:mikramer1@ford.com) (external)

-----Original Message-----

**From:** Matthews, Steve (S.O.)  
**Sent:** Thursday, January 16, 2003 4:18 PM  
**To:** Kramer, Michael (M.T.)  
**Subject:** FW: 2002 and 2003 F Series Super Duty and Excursion Adjustable Pedal

-----Original Message-----

**From:** Matthews, Steve (S.O.)  
**Sent:** Thursday, January 16, 2003 4:04 PM  
**To:** Kramer, Michael (M.)  
**Cc:** Jones, Rick (W.P.)  
**Subject:** 2002 and 2003 F Series Super Duty and Excursion Adjustable Pedal

Mike,

Attached to this email is an excel file listing the specific vehicle VINs that I was able to identify, that have CQIS reports or VOQ (NHTSA) reports regarding the function of the accelerator pedal/throttle pedal on 2002 and 2003 F Series Super Duty and 2002 and 2003 Excursion vehicle lines. The counts include only vehicles equipped with adjustable pedals.

There are reports of similar concerns on vehicles equipped with non-adjustable (fixed) pedals. I have not included those reports in the counts provided below.

A summary of the CQIS reports:

F Series Super Duty:	191 distinct VINs for 2002 MY 3 distinct VINs for 2003 MY
Excursion:	35 distinct VINs for 2002 MY 0 distinct VINs for 2003 MY

I did not identify any CQIS reports indicating there have been any accidents or injuries related to this

PE83-044 23388

concerns.

A summary of the VOQ (NHTSA) reports:

F Series Super Duty:                    2 distinct reports for 2002 MY  
(1 of the VOQ reports has an invalid VIN so I was not to confirm  
whether or not the vehicle was equipped with adjustable pedals)

Excursion:                                2 distinct reports for 2002 MY

VOQ report, ODI # 8012549, (2002 MY Excursion) indicates the vehicle was involved in an accident and 6 people were injured. The AWS data for this vehicle indicates it is equipped with adjustable pedals, and the pedal assembly was replaced on September 5, 2002 by Stan Martin Ford, Inc., located in Hudson, New York.



2002 and 2003 F  
Super Duty & E...

Please contact me if you have any questions regarding the information provided.

**Steve Matthews**

Enhanced Concern Identification

313.248.7770

F Serie

2002 MY - 192 VINs

VIN	QMS Report Miles	Production Date
1FDAF58F92E	9632	10/31/01
1FDAX57F52E	20792	01/14/02
1FDWW38F02E	46550	10/24/01
1FDXF48F62E	13735	10/28/01
1FDXF48F82E	35840	07/24/01
1FDXW47F42E	13929	01/06/02
1FTNW20F32E	44162	12/14/01
1FTNW20F32E	14000	05/02/02
1FTNW20F52E	16370	01/02/02
1FTNW20F62E	10282	12/21/01
1FTNW20F62E	10573	01/06/02
1FTNW20F62E	22061	12/21/01
1FTNW20FX2E	18000	11/02/01
1FTNW20FX2E	8728	01/17/02
1FTNW21F02E	10488	08/27/01
1FTNW21F02E	13000	11/15/01
1FTNW21F02E	6877	12/08/01
1FTNW21F02E	16000	01/04/02
1FTNW21F02E	17349	01/17/02
1FTNW21F12E	2233	08/08/01
1FTNW21F12E	17811	08/30/01
1FTNW21F12E	12000	09/07/01
1FTNW21F12E	18023	10/30/01
1FTNW21F12E	18266	01/08/02
1FTNW21F12E	17708	12/21/01
1FTNW21F22E	22505	08/14/01
1FTNW21F22E	10000	10/19/01
1FTNW21F22E	19836	11/25/01
1FTNW21F22E	8180	11/12/01
1FTNW21F22E	42538	01/14/02
1FTNW21F22E	12810	01/30/02
1FTNW21F32E	25405	08/06/01
1FTNW21F32E	13000	12/17/01
1FTNW21F32E	13000	12/17/01
1FTNW21F32E	9000	01/04/02
1FTNW21F32E	11000	02/13/02
1FTNW21F32E	8856	03/07/02
1FTNW21F42E	14508	01/16/02
1FTNW21F42E	3181	02/11/02
1FTNW21F52E	9223	09/12/01
1FTNW21F52E	32461	10/22/01
1FTNW21F52E	28091	11/25/01
1FTNW21F52E	5200	01/16/02
1FTNW21F62E	4596	08/12/01
1FTNW21F62E	20555	10/24/01
1FTNW21F62E	19071	01/06/02
1FTNW21F62E	21200	01/16/02

1FTNW21F62E	9793	02/12/02
1FTNW21F72E	9301	12/07/01
1FTNW21F72E	9500	12/07/01
1FTNW21F72E	8902	01/04/02
1FTNW21F72E	42110	01/06/02
1FTNW21F82E	15481	10/26/01
1FTNW21F82E	22050	11/30/01
1FTNW21F82E	25991	12/12/01
1FTNW21F82E	17500	12/21/01
1FTNW21F82E	14955	12/14/01
1FTNW21F82E	10473	12/19/01
1FTNW21F82E	15854	01/11/02
1FTNW21F82E	15848	01/09/02
1FTNW21FX2E	38200	09/10/01
1FTNW21FX2E	8574	05/28/02
1FTNX20F82E	8705	02/07/02
1FTNX21F02E	13625	12/21/01
1FTNX21F22E	14345	10/25/01
1FTNX21F32E	8282	12/05/01
1FTNX21F32E	17338	04/27/02
1FTNX21F42E	20000	10/29/01
1FTNX21F42E	28790	11/03/01
1FTNX21F42E	9927	12/15/01
1FTNX21F42E	27720	02/04/02
1FTNX21F42E	1847	05/31/02
1FTNX21F62E	11418	10/26/01
1FTNX21F62E	14213	11/03/01
1FTNX21F62E	12441	11/24/01
1FTNX21F62E	16516	05/05/02
1FTNX21F82E	7726	12/12/01
1FTNX21F92E	24416	10/26/01
1FTNX21F92E	5260	06/01/02
1FTNX21FX2E	29708	09/01/01
1FTNX21FX2E	7603	01/02/02
1FTSF31F32E	7659	12/14/01
1FTSF31F32E	10390	12/13/01
1FTSW30F12E	6500	01/24/02
1FTSW30F82E	8218	12/16/01
1FTSW31F02E	21331	09/24/01
1FTSW31F02E	25907	12/05/01
1FTSW31F02E	22564	12/19/01
1FTSW31F12E	14189	10/23/01
1FTSW31F12E	10962	12/13/01
1FTSW31F12E	18335	01/03/02
1FTSW31F12E	7565	01/10/02
1FTSW31F22E	9992	10/27/01
1FTSW31F22E	10489	11/18/01
1FTSW31F22E	24976	12/10/01
1FTSW31F22E	25892	01/02/02
1FTSW31F22E	11500	01/09/02
1FTSW31F22E	810	03/30/02
1FTSW31F32E	6149	07/26/01

1FTSW31F32	31597	09/10/01
1FTSW31F32	39438	10/24/01
1FTSW31F32	8887	01/14/02
1FTSW31F42	37046	07/19/01
1FTSW31F42	28884	09/10/01
1FTSW31F42	20377	09/09/01
1FTSW31F42	9424	09/12/01
1FTSW31F42	28473	09/25/01
1FTSW31F42	18298	12/03/01
1FTSW31F52	1200	10/11/01
1FTSW31F52	15884	02/11/02
1FTSW31F62	5826	07/18/01
1FTSW31F62	19166	11/30/01
1FTSW31F62	14361	01/22/02
1FTSW31F72	34884	09/21/01
1FTSW31F72	9506	01/03/02
1FTSW31F72	13028	01/08/02
1FTSW31F82	8000	10/11/01
1FTSW31F82	18218	12/04/01
1FTSW31F82	21810	01/15/02
1FTSW31F82	10884	01/30/02
1FTSW31F82	8801	04/16/02
1FTSW31F92	18143	09/22/01
1FTSW31F92	15505	09/22/01
1FTSW31F92	27443	01/17/02
1FTSW31FX2	12848	10/08/01
1FTSW31FX2	8229	12/21/01
1FTSW31FX2	14484	01/11/02
1FTSX31F02	16235	12/07/01
1FTSX31F02	20246	12/07/01
1FTSX31F22	34480	10/11/01
1FTSX31F52	8171	11/03/01
1FTSX31F62	5988	10/04/01
1FTSX31F62	7372	08/03/02
1FTSX31F72	26799	10/30/01
1FTWW32F12	10	09/17/01
1FTWW32F12	23383	10/24/01
1FTWW32F32	10757	12/08/01
1FTWW32F42	45486	10/18/01
1FTWW32F42	20270	01/04/02
1FTWW32F52	6472	12/21/01
1FTWW32F62	18533	10/04/01
1FTWW32F62	26554	05/08/02
1FTWW32F72	32998	08/27/01
1FTWW32F72	35433	05/18/02
1FTWW32F82	42666	11/07/01
1FTWW32FX2	6484	12/18/01
1FTWW33F02	83	08/08/01
1FTWW33F02	10883	01/14/02
1FTWW33F12	27974	12/14/01
1FTWW33F22	31887	12/07/01
1FTWW33F32	22000	08/07/01



1FTWW33F32	26806	11/06/01
1FTWW33F32	13873	12/23/01
1FTWW33F32	4575	01/03/02
1FTWW33F32	15000	06/18/02
1FTWW33F42	8000	06/29/01
1FTWW33F42	26000	10/17/01
1FTWW33F42	20372	11/01/01
1FTWW33F42	17913	12/07/01
1FTWW33F42	12847	01/04/02
1FTWW33F42	15150	01/14/02
1FTWW33F52	17832	04/07/02
1FTWW33F62	17046	12/17/01
1FTWW33F82	17637	12/21/01
1FTWW33F72	15450	09/12/01
1FTWW33F72	8673	01/23/02
1FTWW33F82	35582	10/25/01
1FTWW33F82	18185	10/26/01
1FTWW33F82	10224	01/18/02
1FTWW33F92	22000	10/18/01
1FTWW33F92	3400	11/11/01
1FTWW33F92	19020	12/21/01
1FTWW33FX2	21102	10/08/01
1FTWW33FX2	29992	10/09/01
1FTWW33FX2	27885	01/18/02
1FTWW33FX2	12713	01/15/02
1FTWX32F02E	1851	09/14/01
1FTWX33F12E	1109	11/08/01
1FTWX33F22E	25048	10/15/01
1FTWX33F72E	18570	01/22/02
1FTWX33F92E	14255	12/03/01
1FTWX33FX2E	13717	10/31/01
3FTNW20F02M	18546	12/18/01
3FTNW21F02M	13127	12/11/01
3FTNW21F82M	19893	12/13/01
3FTNW21F72M	13211	12/21/01
3FTNW21F82M	5	09/18/01
3FTNW21F92M	11578	10/16/01
3FTNW21FX2M	12977	09/25/01
3FTSW30F32M	11000	11/15/01
3FTSW30F82M	789	10/20/01
3FTSW31F82M	16256	10/31/01

**is Super Duty**

**2003 MY - 3 VINs**

VIN	CQIS Report Miles	Production Date
1FTNW21F03E	229	10/13/02
1FTNW21FX3E	4555	08/12/02
1FTNX21F13E	6165	07/28/02

**Excursion**

**2002 MY - 35 VINS (2003 MY - 0 VINS)**

VIN	CQIS Report Miles	Production Date
1FMNU42F22	16399	01/05/02
1FMNU42F82	8845	02/07/02
1FMNU42F62	9970	12/21/01
1FMSU43F52	8514	09/18/01
1FMSU43F92	12174	09/17/01
1FMSU43F82	15222	11/13/01
1FMSU43F82	12427	11/12/01
1FMSU43F22	13158	12/04/01
1FMSU43F22	16778	11/10/01
1FMSU43F22	12032	11/13/01
1FMSU43F82	12561	11/12/01
1FMSU43F22	18778	11/10/01
1FMSU43F42	1	12/19/01
1FMSU43FX2	20703	12/18/01
1FMSU43F42	5155	01/18/02
1FMSU43F72	8864	10/27/01
1FMSU43F82	8837	10/04/01
1FMSU43F42	13058	01/16/02
1FMSU43F22	13670	11/12/01
1FMSU43F12	15000	10/02/01
1FMSU43FX2	8035	02/08/02
1FMSU43F22	10238	02/19/02
1FMSU43F32	20687	10/18/01
1FMSU43F72	25931	09/21/01
1FMSU43F72	14880	02/19/02
1FMSU43F52	17884	10/08/01
1FMSU43F42	14600	11/02/01
1FMSU43F92	8835	11/14/01
1FMSU43F52	9222	01/09/02
1FMSU43FX2	32377	12/17/01
1FMSU43FX2	20213	12/07/01
1FMSU43F02	17496	10/05/01
1FMSU43F52	14585	01/08/02
1FMSU43F32	12357	05/29/02
1FMSU43F52	13398	01/03/02



---

From: Avtar Karki (akarki@fcauto.com)  
Sent: Wednesday, August 21, 2002 12:54 PM  
To: Larry Lposki; Greg West; Greg Braniff  
Subject: Life test tear down.ppt



Life test tear  
down.ppt

Larry,

Attached please two three track life test torn down parts. As you would notice fingers on all three tracks on both pedals are in a perfectly good condition.

I just left a message for Wabash VP of engineering to expedite the plan for further root cause analysis. Our president has sent e-mail to Wabash's president to pay extra attention to this issue. I'll forward the information to you as soon as I receive something from them.


Thanks for your patience.  
Avtar

# Pedal 01113




PE83-844 9679

Pedal 0117



PERC-844 0888


Lube



Most areas of the relative tracks appear to have had the lube applied to the tracks. The abrasive slurry wore the contact fingers off but did not significantly wear the relative ink.







Above FTIR analysis from Webch indicates a match to rub bar lube.

Also, Teleflex is conducting another FTIR analysis from 3<sup>rd</sup> party to verify results of Webch test.

We will be testing a known returned pedal with worn fingers, and a new part with no lube on rub bar which will be soaked at high temperature overnight in shipping position and then tested for presence of lube.

**5. Implement & Verify Corrective Actions:**

- Eliminate Rub Bar Lube from both intermediate housing and cover
- Conduct LifeTest on 5 samples without Lube on intermediate rub bar and cover, and 1 sample with Lube purposely put on track. Evaluate samples 1-5 for potential wear on rotor at cover rub bar area. Evaluate sample 6 (no lube) for possible wear on wiper fingers.

**6. Implement Permanent Corrective Actions:**

**7. Prevent Problems Recurrence:**

**8. Recognize Project Team:**

**From:** Shawn Hansen [shansen@yazaki-na.com]  
**Sent:** Tuesday, April 29, 2003 3:26 PM  
**To:** gmetz@ford.com; gwest2@ford.com; kpyle@wmc.com  
**Cc:** dhomovec@aol.com; jwillia5@ford.com; dhomovec@wmc.com; dsillanpaa@wmc.com;  
jmiers@wmc.com; Vijay Keshavamurthy  
**Subject:** RE: P131 FIXED AND ADJUSTABLE PEDAL CONNECTORS

Revised pedal  
testing 042903.p...

Hallo Ken Pyle,

Attached is a summary of the data that has been compiled by Yazaki for the revised accelerator pedal. As can be seen in the summary, the connector now passes the testing that was performed. Please also observe the notes at the bottom of the summary page. The lack of overtravel could potentially cause future locking issues. Please feel free to contact me if any additional information is required.

Regards,

Shawn M. Hansen  
Connector Development and Engineering  
Yazaki North America, Inc.  
6801 Haggerty Rd  
Canton, MI 48187  
Tel- (734)983-2972 Fax- (734)983-2973  
E-mail: shansen@yazaki-na.com

>>> "Pyle, Ken" <kpyle@wmc.com> 04/22/03 04:46PM >>>  
Gary...Have you received any information from Yazaki on these two pedals.

Thanks,  
Ken Pyle  
General Manager  
Williams Controls  
(941)727-5596 x15

-----Original Message-----

**From:** Metz, Gary (G.D.) [mailto:gmetz@ford.com]  
**Sent:** Friday, April 11, 2003 9:19 AM  
**To:** 'Pyle, Ken'; West, Gregory (G.S.)  
**Cc:** Williams Jr., James (J.P.); Metz, Gary (G.D.); 'dhomovec@aol.com';  
Hemovec, Drew; Miers, Jerry; Sillanpaa, Don; 'vkeshava@yazaki-na.com'  
**Subject:** RE: P131 FIXED AND ADJUSTABLE PEDAL CONNECTORS

Ken:

Can you please also provide recent samples of the connector interface? I can have Yazaki again double check the dimensions and also do some connector insertion and retention force testing.

thanks.

-----Original Message-----

**From:** Pyle, Ken [mailto:kpyle@wmc.com]  
**Sent:** Thursday, April 10, 2003 3:59 PM  
**To:** 'West, Gregory (G.S.)'  
**Cc:** 'jwillia5@ford.com'; 'gmetz@ford.com'; 'dhomovec@aol.com'; Hemovec,  
Drew; Miers, Jerry; Sillanpaa, Don  
**Subject:** RE: P131 FIXED AND ADJUSTABLE PEDAL CONNECTORS

## 04HB Driver OOP Series #11 Test Matrix & Results

FMVSS208 New Final Rule (Dec. 2001)

No.	Dummy Position	Dummy Injury Value (%ile Dummy)								
		HIC [700]	Chest G [g]	Chest Def. [2.0in]	Comp. Fz [500 lb]	Tension Fz [425 lb]	N <sub>i</sub> max[1]			
							N <sub>ts</sub>	N <sub>lf</sub>	N <sub>cc</sub>	N <sub>cf</sub>
V0800.2	N2	1.0%	33.3%	62.0%	3.4%	28.0%	37.0%	14.0%	2.0%	15.0%
V0800.1	N1	6.1%	34.7%	30.0%	0.0%	24.1%	31.0%	20.0%	0.0%	22.0%

Notes: Initiator: Takata PSD1-4 (100/200psi peak), 130ms squib fire delay

Dummy Position (N1): NHTSA Position 1

Dummy Position (N2): NHTSA Position 2

After some struggles, I had the connector interfaces of both parts measured and analyzed by Yazaki connector engineering (they make the mating connector, shown attached).

The result of the measurements (see page 2 of .pdf file) was that more dimensions were out of print than were in. Yazaki analyzed the dimensions that were out and have recommended which ones need to be fixed the soonest (see page 1 of .pdf file).

Yazaki also gave me a sample of a harness connector which they had cut in half. It shows that when you mate the connector to the adjustable pedal assembly, the seal rolls up, almost preventing the connector from physically being able to be locked up. This is due to dimension 10 being so far out of spec on the low side. I'll overnight these parts back to you if you can send me your mailing address so you can see for yourself and demonstrate this to Teleflex if they're in denial.

I would appreciate your help in getting the supplier for both pedal assemblies to correct their molds ASAP. I'd be happy to have any modified parts tested again by Yazaki to ensure their mold changes are effective.

Thanks.

-----Original Message-----

From: Shawn Hansen [mailto:shansen@yazaki-na.com]  
Sent: Thursday, April 03, 2003 11:22 AM  
To: gmetz@ford.com  
Cc: Sherria Samuels; Vijay Keshavamurthy  
Subject: RE: Emerging Issue 328534 - Help needed from Electrical and KTP PVT team

Gary,  
Attached are the results of the pedal study that Vijay reviewed with you earlier today. Please let me know if any additional information is required.

Regards,  
Shawn Hansen

>>> "Metz, Gary (G.D.)" <gmetz@ford.com> 03/11/03 12:19PM >>>  
Resending with drawing in .tif format. Hope you guys can open this one.

<<sr8t1d464bb.tif>>

> -----Original Message-----

> From: Metz, Gary (G.D.)  
> Sent: Tuesday, March 11, 2003 12:10 PM  
> To: West, Gregory (G.S.)  
> Cc: Liposky, Lawrence (L.J.); Rabman, Bayeams (N.); Flynn, Pat (J.P.);  
Williams, Brent (B.A.); 'rayford.williams@alcoa.com'; Dixon, Wilfred (W.);  
McNorton, Michael (M.C.); Abar, Robert (R.B.); 'mgrant@yazaki-na.com';  
Andrus, Daniel (D.M.); 'vkeshava@yazaki-na.com'  
> Subject: RE: Emerging Issue 328534 - Help needed from Electrical and  
KTP PVT team

> Importance: High

>  
> Greg:

> I was at KTP two weeks back and reviewed the connector interfaces for both pedal assemblies (fixed and adjustable). I am fairly certain the connector interface on the pedal assemblies do not conform to the dimensional requirements outlined by the mating connector supplier (Yazaki).

> Please forward the attached drawing which provides those interface dimensional details (see upper LH corner) and have them check capability on the following dimensions:

- > 1) Connector lock ramp position (8.25 +0.1/-0)
- > 2) Connector lock ramp height (15.625 - basic dimension)

> In parallel, I have samples of both the fixed and adjustable pedal assemblies (Thank you Brent Williams). I will provide those to Yazaki today and have them analyzed in parallel. I will request a written report from them by Monday of next week and suggest you do the same.

> Thanks.

> << File: xr8t14a464bb.tg4 >>

> -----Original Message-----

> From: Rahman, Nayeema (N.)

> Sent: Tuesday, March 11, 2003 10:16 AM

> To: Williams, Brent (B.A.); Flynn, Pat (J.P.);

'rayford.williams@alcoa.com'; Dixon, Wilfred (W.)

> Cc: Lipoosky, Lawrence (L.J.); West, Gregory (G.S.); McNorton, Michael

(M.C.); Abar, Robert (R.B.); Metz, Gary (G.D.)

> Subject: RE: Emerging Issue 328534 - Help needed from Electrical and  
KTP PVT team

> Brent/Pat:

> Can you comment on the process question listed in the original note from Robert Abar?

> Rayford/Wilfred:

> Do you have any comment on the wiring connector design.

> Thanks!

> -----Original Message-----

> From: Abar, Robert (R.B.)

> Sent: Tuesday, March 11, 2003 9:08 AM

> To: Rahman, Nayeema (N.)

> Cc: Abar, Robert (R.B.); Lipoosky, Lawrence (L.J.); West, Gregory (G.S.);

McNorton, Michael (M.C.)

> Subject: FW: Emerging Issue 328534 - Help needed from Electrical and  
KTP PVT team

> Importance: High

> Nayeema,

> See request below in Mike McNorton's absence.

> Robert B. Abar

> Manager, Powertrain

> (313) 84-54247

FAX: (313) 24-89073

rabar@ford.com

> Room: ICP20/Rotunda Ct #4

Mail Drop: LAM10

> -----Original Message-----

> From: Abar, Robert (R.B.)

> Sent: Tuesday, March 11, 2003 9:05 AM

> To: McNorton, Michael (M.C.)

> Cc: Abar, Robert (R.B.)

> Subject: FW: Emerging Issue 328534 - Help needed from Electrical and  
KTP PVT team

> Importance: High

> Mike,

> See request below.

> Robert B. Abar

> Manager, Powertrain

> (313) 84-54247

FAX: (313) 24-89073

rabar@ford.com

> Room: ICP20/Rotunda Ct #4

Mail Drop: LAM10

> -----Original Message-----

> From: Gertley Sr., Jeffrey (J.B.)  
> Sent: Tuesday, March 11, 2003 8:26 AM  
> To: Abar, Robert (R.B.)  
> Subject: RE: Emerging Issue 328534 - Help needed from Electrical and  
KTP PVT team

> Please forward this to Mike McNorton. I'm not on P131 anymore!

> -----Original Message-----

> From: Abar, Robert (R.B.)  
> Sent: Tuesday, March 11, 2003 7:11 AM  
> To: Gertley Sr., Jeffrey (J.B.); Williams, James (J.P.); Williams, Brent  
(B.A.); Reed Jr., Bill (W.P.)  
> Cc: Abar, Robert (R.B.); Carr, Richard (R.T.); Liposky, Lawrence (L.J.);  
West, Gregory (G.S.); Figurski, Patrick (P.M.); Gisleghen, Tom (T.A.)  
> Subject: Emerging Issue 328534 - Help needed from Electrical and KTP  
PVT team

> Importance: High

>

>

> Background:>

> Emerging Issue 328534 is listed for F250HD/F350/450/550  
V8T-S11-Powertrain VFG-V41-Smooth response CCC-D36-Engine Hesitates /  
surges when accelerating

>

> The issue has initially been binned against accelerator pedal by the  
warranty analyst based on their review of the claims and the parts being  
replaced.

>

>

> Greg West's analysis of the current AWS claims includes the following:

29 Teleflex (adjustable pedal assy's) - with 6 reporting legitimate codes  
15 Williams (fixed pedal assy's) - with 3 reporting legitimate codes  
15 unknown due to poor dealer coding

>

> Breakdown from the the verbatims of 58 total 6.0L Pedals on AWS

> 10% (6) Electrical - hard shell not fully seated

> 16% (9) Mis-binned - listed as 7.3L pedal

> 29% (17) Non related hardware (ICP) and/or calibration

> 10% (6) non-pedal related - glow plugs not plugged in, black smoke on  
accel

> 35% (20) Unexplained - 4 pedals verified through dealership used pin  
point, no codes, changed anyway

>

>

> Returned Pedal - 5 total three track to date

> Williams - 3 of 3 NTF at supplier and further verified on calibration  
truck as functionally acceptable

> Teleflex - 2 of 2 NTF at supplier and further verified on calibration  
truck as functionally acceptable. One of these had a DTC specific to pedal,  
even though it was verified as acceptable at supplier and in vehicle.

>

>

> Additional pedal assy's are being returned for analysis by supplier and  
the powertrain accel group.

>

>

> Powertrain team would like a deeper understanding of the electrical  
connector and the interface to the pedal assy to make sure the connector is  
always seated and that proper contact is achieved if it is seated. We are  
looking for system interactions that may explain the codes that are not  
evident on the existing returned parts the NTF.

>

>

> REQUESTED ACTIONS FROM ELECTRICAL AND PT PVT TO SUPPORT POWERTRAIN

INVESTIGATION:

>

> Review installation process of electrical connector at KTP to both the adjustable and fixed pedal assy and provide process to powertrain team in Dearborn. It was note when we were trying to install a connector on to the pedal assy that if you were pushing on the red locking tab (while starting to push on the connector) that you could hear a click but hadn't even started to seat the connector. Is this a blind operation or can the operator see the connection while they are doing it? Does the operator push on the connector and then go back and move the red tab or do they try to do it simultaneously? Do they pull on the connector to confirm its seated before seating the locking tab or even after seating the locking tab? Some other process?

>

> Jim Williams indicated that there were occasionally issues with getting the red button set on the fixed pedals, but not on the adjustable pedals. Are there physical differences between the pedals in the connector area or assy process that would account for this? Have parts that have had the issue been removed for inspection/analysis?

>

>

>

> Jeff, Would also like to understand the design of the wiring connector relative to the mating part on the pedal assy:

> - Given reports of loose connectors, is it possible to partially seat the connectors and make electrical contact? When do the pins make contact during the assembly process of the connector (as the shells first come together, only after the locking tab starts up the tab ramp, etc)?

> - What are the tolerance stacks of the pins and mating slots?

> - Can someone in Dearborn take us thru the design in the next day or two?

>

>

>

> Thanks in advance for your assistance in helping us get to root cause of this issue.

>

>

>

> Robert B. Abar  
> Manager, Powertrain

>

> (313) 84-54247

FAX: (313) 24-89073

rabar@ford.com

> Room: 1CP20/Rotunda Ct #4

Mail Drop: L8410

>



## Revised Pedal Module Testing

### Connector-Module Mating Force

No.	Force (N)
1	59.8
2	64.8
average	62.3

USCAR Spec: 75N max

### CPA Mating Force


No.	Force (N)
1	8.8
2	6.3
average	7.6

SOS 11.0 Spec: 15N max

### Connector-Module Retention Force w/o CPA

No.	Force (N)
1	128.0
2	114.8
average	120.4

USCAR Spec: 110N min



Note 1: No lock overtravel was observed during the mating process.

Note 2: Inspection results of dimension 6 (14.326 lock height) now show it is in spec 14.25 & 14.24.

Note 3: Inspection results of dimension 3 (18° lock back angle) show it to still out at 6.5 & 6.6.

Tested by: Shawn Hansen  
Yazaki North America, Inc.  
April 29th, 2003

PE03-044 18124

CL-Remo #CLF07\_02

PE03-B44 11487

---

**From:** Hudson, Lou - Troy [lhudson@TFXAuto.com]  
**Sent:** Wednesday, November 29, 2000 11:39 AM  
**To:** Petrauskas, Lisa (L.E.)  
**Subject:** RE: Need DDLs for Concerns

You ever get these DDL's?

In other news....

Have your drawings. I can drop them off any time.

I like to stop by to take digital pictures of the tunnel area on a truck or two if that's possible. Sure would add design of the backup plate to the ETC bracket. The idea is to have the plate extend 3mm past the edges of the bracket. That way, no matter how it's dropped, it hits the steel plate before it hits the plastic of the mounting area. The design issue is potential interference in the tunnel area (carpet, insulation, ducting, etc.) with parts that we don't have in CAD. Do you have any adjustable trucks in Dearborn?

(An issue to hit Bill up with later: What happens to that steel bracket when it's dropped? Do the edges of the steel fold over the back, toward the firewall in vehicle? At 1.5mm thick, it might not be so easy to bend it back for installation, and the plant could go berserk.)

The attachment is the issues list Elio worked up, with due dates. I don't know if he sent it to you or not (He's out today.). If he didn't, please keep this to yourself. Call if you need anything.

<<J137\_APQP Open Issue.doc>>

—Original Message—

**From:** Petrauskas, Lisa (L.E.) [mailto:petraus@ford.com]  
**Sent:** Tuesday, November 21, 2000 3:46 PM  
**To:** Lou F. Hudson (E-mail); Elio G. Evangelista (E-mail); William Teller (E-mail)  
**Subject:** Need DDLs for Concerns

Need DDLs for C11159112, C11162269

Lisa Petrauskas  
Heavy F-Series Chassis Design  
PDC 2B-A60  
313-39-08070  
(fax) 313-317-2349  
lpetraus@ford.com

## U137/APQP OPEN ISSUES

**Program:** U137  
**Description:** Adjustable Pedals  
**Code:** U137  
**TFX P/N:** 016T-G0058,59,60,61

**Ford P/N:** 1C35 2450 AE/BE  
 1C35 9726 AD & 9F836 AD

**Ford Engineer:** Lisa Petrauskas  
**TFX Engineer:** Bill Teller  
**Account Manger:** Conrad Niester  
**Description:** APS

Issue #	Description	Date Opened	Responsible	Update / Status	Date Due	Date Closed
1	Change Track Rod Position	11/21/00	Bill Teller/Andy Volker	Following components/items would be revised: (DESIGN CHANGE ONLY) 1) Brake Arm (Dwg., tool & gages) 2) Extension Plate(s) (Dwg. tools & gages) 3) Extension Plate sub-assy. (Dwg., tool & gages) 4) Brake Cable (dwg. parts) 5) Weld fixtures & gages 6) Assembly fixtures & gages	12/8/00 (design)	
2	Drop Requirement - Adding ribs to accel housing to protect ETC	11/21/00	Avtar Kalsi/Andy Volker	Requires changes to accel housing (dwg. & mold)	12/8/00 (design)	
3	Drop Requirement - Back steel plate to protect plastic accel housing	11/21/00	Avtar Kalsi/Andy Volker	Following components/items would be revised &/or added: (DESIGN CHANGE ONLY) 1) Modify accel. Housing, add thru holes & bosses (dwg. & mold) 2) New back plate (dwg. & new tool) 3) 2-3 self-tapping screws 4) Assy equipment to asm. plate & housing (scr. driver)	12/8/00 (design)	
4	Drop Requirement - Cable Retainer	11/21/00	Bill Teller/Andy Volker	Following components/items would be revised &/or added: (DESIGN CHANGE ONLY) 1) Replace plastic retainer with steel retainer. 2) New steel retainer ( tool & gages) 3) Weld fixtures & gages 4) Assy fixtures	12/8/00 (design)	
5	Drop Requirement - Motor support/protection	11/21/00	Bill Teller/Andy Volker	T.B.D.	T.B.D.	
6	Drop Testing for items 1-4	11/21/00	Elio Evangelista/Avtar Kalsi/ Bill Teller	1) Fab 20 parts with changes mentioned items 1-4 (Elio) 2) DV Test (Avtar / Bill)	12/6/00 12/8/00	

**Author:** Elio Evangelista  
**Filename:** U137\_APQP Open Issue.doc

**Last printed:** 11/17/03  
**Last Updated:** 11/17/03

**Created on:** 10/28/00  
**Page 1 of 1**

PERC-044 22026

---

**From:** Hudson, Lou - Troy [lhudson@TFXAuto.com]  
**Sent:** Monday, November 13, 2000 2:19 PM  
**To:** Petrauskas, Lisa (L.E.)  
**Subject:** RE: issues list

A few fields have revisions. What they'll be looking for is issue resolution and implementation dates. If we can tell them the KTP drop review is scheduled for this week, that'd be better than TBD. We have to show progress or we'll all look like idiots, Lisa. (For example, the DV testing timing of 12/1 looks great. If we could put dates on everything else...)

—Original Message—

**From:** Petrauskas, Lisa (L.E.) [mailto:lpetraus@ford.com]  
**Sent:** Monday, November 13, 2000 1:21 PM  
**To:** Lou F. Hudson (E-mail); William Teller (E-mail)  
**Subject:** issues list

<<ADJ\_TRIAL\_ISSUES\_2.rtf>>

Lisa Petrauskas  
Heavy F-Series Chassis Design  
PDC 2B-A60  
313-39-08070  
(fax) 313-317-2349  
lpetraus@ford.com

g	Area/Issue	Issue with part	Issue with process	Concern Mfr	Cost	PSW Timing	Status/Comments	Supplier	Vehicle	R/R/S
1	Clutch	Accelerator pedal sticking/high idle 900-1100 rpm		Throttle is not A number of			Technical will investigate	Teledyne	UJ37	R
2	Idle speed	The color of the idle panel is not ready. Will not meet 13/1/00 PSW.		C11144483		14/2001		Visteon	P181A/137	Y
3	Down Plug	Down plug will not be PSW until 14/01		C11144483	1	14/2001		Visteon	P181A/137	Y

PERC-DIA 218713



---

**From:** Liposky, Lawrence (L.J.)  
**Sent:** Monday, March 03, 2003 2:53 PM  
**To:** West, Gregory (G.S.)  
**Subject:** FW: Winco Mechanical Studies

Larry Liposky  
Supervisor - Accelerator Controls  
Tough Truck / Outfitters  
Phone 24-81726  
Pager 796-0940

—Original Message—  
**From:** Milers, Jerry [mailto:jmilers@winco.com]  
**Sent:** Monday, March 03, 2003 9:09 AM  
**To:** 'liposky@ford.com'  
**Subject:** Studies

Attached are the latest studies that were performed utilizing the controlling features.  
If you have any comments, please feel free.

10/2/2003

FEB3-044 10506



TY Slot angle	Delta To Nom.		Debris	Rotor Depth	Rotor Angle
1	77.491	0.111	0.390	0.380	89.484
2	77.600	0.200	0.328	0.360	89.669
3	77.490	0.110	0.329	0.379	89.702
4	77.491	0.191	0.328	0.380	89.508
5	77.439	0.139	0.330	0.379	89.444
6	77.501	0.201	0.328	0.380	89.663
7	77.421	0.121	0.328	0.379	89.671
8	77.441	0.141	0.329	0.380	89.730
9	77.442	0.142	0.328	0.379	89.681
10	77.406	0.106	0.328	0.379	89.680
11	77.610	0.310	0.329	0.381	89.690
Average	77.461	0.161	0.329	0.380	89.694
STD	0.000986	0.000988	0.000761	0.000674	0.178423

Element	CT 1	WOT 1	CT 2	WOT 2	CT 3	WOT 3
1	80.70	10.20	33.70	87.40	22.40	75.50
2	80.40	9.80	34.30	87.80	22.80	76.00
3	81.80	10.70	34.00	87.40	22.00	75.00
4	80.70	9.90	34.30	88.00	22.70	76.00
5	80.00	9.80	34.40	88.00	22.90	75.80
6	80.80	10.20	34.10	87.70	22.80	75.40
7	80.00	9.70	34.30	87.80	22.70	75.70
8	82.90	11.80	33.20	87.90	21.80	74.90
9	80.00	10.00	33.80	87.70	22.80	75.40
10	80.80	10.00	34.90	87.90	22.80	75.90
11	81.70	10.70	34.00	87.70	22.60	75.80
Average	80.97	10.20	34.00	87.70	22.20	75.64
STD	0.868	0.600	0.366	0.241	0.379	0.441
Min	80.000	9.800	33.200	87.900	21.800	74.900
Max	82.900	11.800	34.400	88.000	22.900	76.000
Range	-2.500	-2.000	-1.200	-0.700	-1.200	-1.600

ETC	CT 1	WOT 1	CT 2	WOT 2	CT 3	WOT 3
1	79.50	11.16	30.85	83.85	19.48	71.62
2	79.86	11.14	30.93	83.44	19.34	71.38
3	81.13	12.01	30.54	83.48	18.85	70.61
4	80.81	11.41	31.10	84.27	19.39	72.07
5	80.42	12.13	30.85	83.82	18.80	70.68
6	80.47	11.84	30.87	83.54	18.47	71.12
7	81.00	12.85	30.02	82.65	18.11	70.12
8	82.24	13.24	30.17	83.39	18.48	70.79
9	80.67	11.78	30.39	83.51	18.61	72.21
10	79.19	10.28	31.98	84.66	20.47	72.73
11	79.96	11.12	31.72	84.38	20.02	72.38
Average	80.51	11.71	30.80	83.65	19.28	71.43
STD	0.848432	0.813908	0.584106	0.567422	0.671748	0.633652
Min	79.19	10.28	30.02	82.65	18.11	70.12
Max	82.24	13.24	31.98	84.66	20.47	72.73
Range	-3.050	-2.960	-1.940	-2.000	-2.360	-2.610

Delta	Ele-ETC	CT 1	WOT 1	CT 2	WOT 2	CT 3	WOT 3
	0.46	-1.51	3.10	4.05	2.82	4.21	

Tolerance Study Idle Electrical Reading "D" Slot Angle/Debris Cover Rad./Rotor Depth Angle

Unit e Test Results Gr./Rad	Sample Number	"D" Slot angle Degrees	Debris Idle Stop Rad. Inches	Rotor Depth Inches	Rotor Angle Degrees	CT 1 Element	CT 1 ETC	CT 1 Delta Element/ETC	CT 2 Element	CT 2 ETC	CT 2 Delta Element/ETC	CT 3 Element	CT 3	CT 3 Delta Element/ETC
	1	77.411	0	0.380			79.50	1.20		30.55			19.45	
	2	77.500	0	0.380			79.98	0.48		30.53			19.34	
	3	77.410	0	0.379			81.13	0.47		30.54			19.05	
	4	77.491	0	0.380			80.51	-0.11		31.10			19.39	
	5	77.438	0	0.379			80.52	-0.22		30.55			18.90	
	6	77.501	0	0.380			80.47	0.33		30.57			18.47	
	7	77.421	0	0.379			81.00	-1.00		30.52			18.11	
	8	77.441	0	0.380			82.24	0.28		30.17			18.45	
	9	77.442	0	0.379			80.57	0.33		30.39			19.81	
	10	77.408	0	0.379			78.19	1.61		31.55			20.47	
	11	77.510	0	0.381			79.98	1.76		31.72			20.02	
	Average	77.451	0	0.380			80.51	0.48		30.50			19.25	
	STD	0.069088	0.000000	0.000074	0.000000		0.549433			0.554108			0.274749	
	Min	77.402	0	0.379			79.19			30.02			18.11	
	Max	77.510	0	0.381			82.24			31.95			20.47	
	Range	-0.204	0	-0.002			-3.050			-1.940			-2.360	

PERS-041 18200

Ford Lever Stack Tol. 02-15-03.xls

CT Comp.

Idle

Unit & Test Results Gr./Rad	Sample Number	TD Slot angle Degrees	Delta's Idle Stop Rad. Inches	Rotor Angle Degrees	CT 1 Element	CT 1 ETC	CT 1 Delta Element/ETC	CT 2 Element	CT 2 ETC	CT 2 Delta Element/ETC	CT 3 Element	CT 3	CT 3 Delta Element/ETC
	1	77.411	0.330	89.484	80.70	79.80	1.20	33.70	30.98			19.48	
	2	77.800	0.328	89.858	80.40	79.85	0.45	34.30	30.93			19.34	
	3	77.410	0.329	89.702	81.60	81.13	0.47	34.00	30.84			18.85	
	4	77.461	0.328	89.808	80.76	80.81	-0.11	34.30	31.10			19.39	
	5	77.439	0.330	89.444	80.80	80.82	-0.22	34.40	30.85			18.80	
	6	77.801	0.328	89.863	80.80	80.47	0.33	34.10	30.87			19.47	
	7	77.421	0.329	89.871	80.00	81.00	-1.00	34.30	30.02			18.11	
	8	77.441	0.329	89.730	82.60	82.24	0.28	33.20	30.17			18.49	
	9	77.442	0.329	89.881	80.90	80.57	0.33	33.80	30.39			19.61	
	10	77.406	0.328	89.990	80.80	79.19	1.61	34.10	31.99			20.47	
	11	77.810	0.329	89.950	81.70	79.95	1.75	34.00	31.72			20.02	
	Average	77.481	0.329	89.894	80.87	80.51	0.46	34.00	30.60			19.28	
	STD	0.060966	0.000751	0.178423	0.699	0.848432		0.306	0.554108			0.671748	
	Min	77.406	0.328	89.444	80.000	79.19		33.200	30.02			18.11	
	Max	77.810	0.330	89.860	82.600	82.24		34.400	31.95			20.47	
	Range	-0.204	-0.002	-0.816	-2.600	-3.060		-1.200	-1.840			-2.360	

Delta Nom	0.18	-0.005	-0.31	0.22	-0.24		4.30	-1.20		3.50	-0.58
USL	77.55	0.354	90.25		83.25			32.20			21.20
Nom	77.30	0.334	90.00	80.75	80.75		29.7	29.7		18.7	18.7
LSL	77.06	0.314	89.75		76.25			27.20			16.20
		Element	USL		83.21			34.80			23.82
		Element	Nom		81.21			32.60			21.82
		Element	LSL		79.21			30.80			19.82

Ford Lever Stack Tol, 02-16-03.xls

CT Camp Angle

Unit & Test Results Gr./Road	Sample Number	D Slot angle Degrees	Debris Idle Stop Rad. Inches	Motor Angle Degrees	CT 1 Element	CT 1 ETC	CT 1 Delta Element/ETC	CT 2 Element	CT 2 ETC	CT 2 Delta Element/ETC	CT 3 Element	CT 3 ETC	CT 3 Delta Element/ETC
	1	77.411	0		80.70				30.85	2.75		19.48	2.82
	2	77.500	0		80.40				30.83	3.37		18.34	3.48
	3	77.410	0		81.60				30.84	8.08		18.95	3.05
	4	77.491	0		80.70				31.10	3.20		19.39	3.31
	5	77.439	0		80.80				30.85	3.55		18.80	3.70
	6	77.501	0		80.80				30.87	3.23		18.47	3.33
	7	77.421	0		80.00				30.02	4.28		18.11	4.59
	8	77.441	0		82.50				30.17	3.03		18.48	3.12
	9	77.442	0		80.80				30.39	3.21		18.61	3.18
	10	77.408	0		80.80				31.98	2.14		20.47	2.13
	11	77.610	0		81.70				31.72	2.28		20.02	2.58
	Average	77.484	0.000		80.67		0.48		30.60	3.18		19.28	3.22
	STD	0.060988	0.000		0.888		0.8		0.584106			0.071748	
	Min	77.408	0		80.000				30.02			18.11	
	Max	77.610	0		82.600				31.98			20.47	
	Range	-0.204	0		-2.600				-1.940			-2.360	

Delta Nom	0.18	-0.005	-0.31	0.22	-0.24	4.30	-1.20	3.60	-0.58
USL	77.55	0.354	80.25		83.25		32.20		21.20
Nom	77.30	0.334	80.00	80.75	80.75	29.7	29.7	18.7	19.7
LSL	77.05	0.314	89.75		78.25		27.20		18.20
		Element	USL			34.50		23.92	
		Element	Nom			32.80		21.92	
		Element	LSL			30.80		19.92	

Delta

Unit & Test Results Gr./Rad	Sample Number	T <sub>D</sub> Slot angle Degrees	Debris Idle Stop Rad. Inches	Rotor Angle Degrees	CT 1 Element	CT 1 ETC	CT 1 Delta Element/ETC	CT 2 Element	CT 2 ETC	CT 2 Delta Element/ETC	CT 3 Element	CT 3	CT 3 Delta Element/ETC
	1	0.111	-0.004	-0.536				4.000	1.280		3.700	0.780	
	2	0.200	-0.008	-0.344				4.600	1.230		4.100	0.840	
	3	0.110	-0.005	-0.288				4.300	1.240		3.300	0.250	
	4	0.191	-0.008	-0.492				4.800	1.400		4.000	0.990	
	5	0.139	-0.004	-0.588				4.700	1.150		3.800	0.100	
	6	0.201	-0.008	-0.137				4.400	1.170		4.100	0.770	
	7	0.121	-0.003	-0.329				4.500	0.320		4.000	-0.590	
	8	0.141	-0.005	-0.270				3.500	0.470		2.900	-0.220	
	9	0.142	-0.005	-0.319				3.900	0.890		4.100	0.810	
	10	0.108	-0.008	-0.040				4.466	2.260		3.000	1.770	
	11	0.310	-0.008	-0.050				4.300	2.020		3.900	1.320	
	Average	0.161	-0.005	-0.308			0.46	4.30	1.20		22.20	0.58	
	STD	0.060888	0.000751	0.178423		0.84-1.2		0.368	0.584106		0.379	0.671748	
	Min	0.108	-0.008	-0.558				3.500	0.32		2.900	-0.59	
	Max	0.310	-0.004	-0.040				4.700	2.26		4.100	1.77	
	Range	-0.204	-0.002	-0.516				-1.200	-1.940		-1.200	-2.380	

Delta Nom	-77.14	-0.338	-80.31	-80.63	-80.89	-25.40	28.50	3.50	18.12
USL	77.55	0.384	80.26		83.25		32.20		21.20
Nom	77.30	0.334	80.00	-80.75	80.75	29.7	28.7	18.7	18.7
LSL	77.05	0.914	88.75		78.25		27.20		16.20
		Element USL		83.21		34.80		23.92	
		Element Nom		81.21		32.80		21.92	
		Element LSL		79.21		30.80		19.92	

PAGE 044 1001

Tolerance Study WOT Electrical Readings "D" Slot Angle/Debris Cover Rad./Rotor Depth Angle

Slit's Test Results Cr./Rod	Sample Number	Top Slot angle Degrees	Debris Idle Stop Rad. Inches	Rotor Depth Inches	Rotor Angle Degrees	WOT 1 Element	WOT 1	WOT 1 Delta Element/ETC	WOT 2 Element	WOT 2 ETC	WOT 2 Delta Element/ETC	WOT 3 Element	WOT 3 ETC	WOT 3 Delta Element/ETC
	1	77.411	0.330	0.380	89.484	0	11.18		0				71.82	
	2	77.600	0.328	0.380	89.626	0	11.14		0				71.39	
	3	77.410	0.329	0.379	89.702	0	12.01		0				70.81	
	4	77.481	0.328	0.380	89.538	0	11.41		0				72.07	
	5	77.439	0.330	0.379	89.444	0	12.13		0				70.58	
	6	77.601	0.328	0.380	89.883	0	11.84		0				71.12	
	7	77.421	0.329	0.379	89.871	0	12.85		0				70.12	
	8	77.441	0.329	0.380	89.730	0	13.24		0				70.79	
	9	77.442	0.329	0.379	89.881	0	11.78		0				72.21	
	10	108	0.328	0.379	89.960	0	10.28		0				72.73	
	11	110	0.329	0.381	89.950	0	11.12		0				72.38	
	Average	81	0.328	0.380	89.854	0	11.71		0				71.43	
	STD	0.000781	0.000781	0.000874	0.175423	0	0.813009		0				0.833652	
	Min	108	0.328	0.379	89.444	0	10.28		0				70.12	
	Max	110	0.330	0.381	89.880	0	13.24		0				72.73	
	Range	204	-0.002	-0.002	-0.616	0	-2.960		0				-2.610	

PERC-844 18512

Ford Lever Stack Tol. 02-15-03.xls

WOT Comp.

WOT

Unit # Test Results Gr/Red	Sample Number	D <sup>0</sup> Slot angle Degrees	Delta Hole Stop Rad. Inches	Rotor Angle Degrees	WOT 1 Element	WOT 1	WOT 1 Delta Element/ETC	WOT 2 Element	WOT 2 ETC	WOT 2 Delta Element/ETC	WOT 3 Element	WOT 3 ETC	WOT 3 Delta Element/ETC
	1	77.411	0.330	89.484	10.20	1.00	87.40	3.65	76.90	71.82	3.98		
	2	77.500	0.328	89.656	9.80	1.00	87.80	4.38	76.00	71.38	4.62		
	3	77.410	0.328	89.702	10.70	1.00	87.40	3.81	76.00	70.81	4.19		
	4	77.481	0.328	89.504	9.00	1.00	88.00	3.73	76.00	72.07	3.93		
	5	77.439	0.330	89.444	9.80	1.00	88.00	4.09	76.80	70.58	6.02		
	6	77.501	0.328	89.653	10.20	1.00	87.70	4.18	76.40	71.12	4.28		
	7	77.421	0.328	89.671	9.70	1.00	87.80	3.15	76.70	70.12	6.58		
	8	77.441	0.328	89.730	11.80	1.00	87.30	3.81	74.80	70.79	4.11		
	9	77.442	0.328	89.681	10.00	1.00	87.70	4.19	76.40	72.21	4.19		
	10	77.406	0.328	89.980	10.00	1.00	87.80	3.25	76.80	72.73	3.17		
	11	77.610	0.328	89.950	10.70	1.00	87.70	3.31	76.80	72.38	3.22		
	Average	77.481	0.329	89.624	10.20	1.00	87.70	4.08	76.64	71.40	4.21		
	STD	0.060888	0.000751	0.178423	0.800	0.813000	0.241	0.000000	0.441	0.833852			
	Min	77.408	0.328	89.444	9.800	10.28	87.300		74.800	70.12			
	Max	77.610	0.330	89.980	11.800	13.24	88.000		76.400	72.73			
	Range	-0.204	-0.002	-0.516	-2.000	-2.950	-0.700		-1.300	-2.610			

Delta Nom	0.18	-6.005	-0.31	-2.90	-1.39	6.70	2.65	5.84	1.43
USL	77.65	0.364	89.26		15.60		83.50		72.50
Nom	77.30	0.334	89.00	13.10	13.10	81	81	70	70
LSL	77.05	0.314	89.75		10.80		78.50		67.50

Element: USL	13.69	87.05	76.21
Element: Nom	11.59	85.05	74.21
Element: LSL	9.59	83.05	72.21

PERC-044 10013

Ford Lever Stack Tol. 02-15-03.xls

WOT Comp Angle

WOT

Delta

Unit x Test Results Cr./Rad	Sample Number	Top Slot angle Degrees	Debris Mils Strip Rad. Inches	Rotor Angle Degrees	A # 1 Element	Wot 1 ETC	Wot 1 Delta Element/ETC	Wot 2 Element	Wot 2 ETC	Wot 2 Delta Element/ETC	A # 3 Element	Wot 3	Wot 3 Delta Element/ETC
	1	0.111	-0.004	-0.538	0			8.400					
	2	0.200	-0.008	-0.344	0			8.800					
	3	0.110	-0.005	-0.288	0			8.400					
	4	0.181	-0.008	-0.482	0			7.000					
	5	0.138	-0.004	-0.558	0			7.000					
	6	0.201	-0.006	-0.137	0			6.700					
	7	0.121	-0.008	-0.329	0			6.800					
	8	0.141	-0.006	-0.270	0			6.300					
	9	0.142	-0.006	-0.319	0			6.700					
	10	0.188	-0.008	-0.040	0			6.800					
	11	0.310	-0.005	-0.050	0			6.700					
	Average	0.181	-0.005	-0.308	0			6.70					
	STD	0.060888	0.000781	0.178423	0	0.8		0.241	0.5			0.8	
	Min	0.108	-0.008	-0.558	0			6.300					
	Max	0.310	-0.004	-0.040	0			7.000					
	Range	-0.204	-0.002	-0.518	0			-0.700					

Delta Nom	-77.14	-0.336	-80.31	-83.65	-82.14	-23.00	27.05	3.60	17.27
USL	77.55	0.354	80.25	83.25	83.25		32.20		21.20
Nom	77.30	0.334	80.00	80.75	80.75	28.7	28.7	18.7	18.7
LSL	77.05	0.314	80.75	78.25	78.25		27.20		18.20
		Element	USL	61.24		35.75		24.91	
		Element	Nom	79.24		33.75		22.91	
		Element	LSL	77.24		31.75		20.91	

PENG-04-10014

Ford Lever Stack Tol. 02-15-03.xls

WOT Comp Angle



T <sup>d</sup> Slot angle	Delta To Nom.	Debris	Rotor Depth	Rotor Angle	
1	77.314	0.014	0.3305	0.3780	89.780
2	77.308	0.008	0.3300	0.3780	89.840
3	77.329	0.029	0.3300	0.3780	89.870
4	77.324	0.024	0.3300	0.3785	89.830
5	77.321	0.021	0.3310	0.3775	89.880
6	77.326	0.026	0.3300	0.3780	89.750
7	77.309	0.009	0.3300	0.3780	89.830
8	77.323	0.023	0.3310	0.3780	89.860
9	77.349	0.049	0.3310	0.3775	89.940
10	77.308	0.008	0.3310	0.3780	89.810
Average	77.321	0.021	0.330	0.378	89.838
STD	0.012547	0.012547	0.000497	0.000284	0.059029

Element	CT 1	WOT 1	CT 2	WOT 2	CT 3	WOT 3
1	81.80	10.00	33.20	87.80	22.20	78.20
2	81.60	11.10	32.60	86.70	21.70	78.30
3	81.80	11.00	32.60	86.40	21.90	75.70
4	81.00	10.40	32.70	86.70	21.60	75.10
5	80.90	9.80	33.10	87.70	22.10	78.10
6	81.50	10.90	32.30	86.70	21.30	75.00
7	81.70	11.00	32.60	86.80	21.80	75.40
8	82.40	11.50	32.30	86.80	21.80	75.30
9	83.80	12.10	32.60	86.80	21.50	75.20
10	82.10	11.60	32.30	86.80	21.60	75.00
Average	81.71	10.94	32.60	86.90	22.20	75.43
STD	0.882	0.716	0.320	0.422	0.272	0.432
Min	80.900	9.800	32.300	86.400	21.300	75.000
Max	83.800	12.100	33.200	87.700	22.200	78.200
Range	-2.900	-2.300	-0.900	-1.300	-0.900	-1.200

ETC	CT 1	WOT 1	CT 2	WOT 2	CT 3	WOT 3
1	78.02	9.46	31.75	84.75	20.58	75.53
2	78.78	10.90	30.74	83.84	20.18	72.61
3	82.20	13.67	28.81	81.35	18.06	70.82
4	82.19	13.98	27.98	80.69	18.88	69.20
5	82.63	13.82	28.38	81.58	17.37	70.29
6	79.61	11.17	30.32	83.62	19.61	72.27
7	84.46	15.90	27.02	80.50	18.44	69.23
8	86.32	18.37	26.52	80.18	18.18	68.99
9	82.53	13.98	29.43	82.61	18.35	70.82
10	83.54	15.24	27.92	81.19	17.12	69.58
Average	81.92	13.40	28.88	82.02	18.07	70.99
STD	2.402248	2.225214	1.673505	1.668136	1.673348	2.036954
Min	78.02	9.46	26.52	80.18	18.18	68.99
Max	86.32	18.37	31.75	84.75	20.69	75.53
Range	-7.300	-8.910	-5.230	-4.570	-4.410	-6.540

Delta	Ele-ETC	CT 1	WOT 1	CT 2	WOT 2	CT 3	WOT 3
	-0.21	-2.46	3.74	4.88	4.13	4.50	

Tolerance Study Idle Electrical Reading "D" Slot Angle/Debris Cover Rad./Rotor Depth Angle

Unit & Test Results Gr./Rad	Sample Number	"D" Slot angle Degrees	Delta n, Idle Stop Rad. Inches	Rotor Depth Inches	Rotor Angle Degrees	CT 1 Element	CT 1 ETC	CT 1 Delta Element/ETC	CT 2 Element	CT 2 ETC	CT 2 Delta Element/ETC	CT 3 Element	CT 3 ETC	CT 3 Delta Element/ETC
	1			0.378		81.10			0				20.69	1.61
	2			0.378		81.20			0				20.16	1.54
	3			0.378		81.60			0				18.08	3.85
	4			0.379		81.00			0				18.85	4.75
	5			0.378		80.90			0				17.37	4.73
	6			0.378		81.80			0				19.81	1.89
	7			0.378		81.70			0				18.44	5.38
	8			0.378		82.40			0				18.18	5.82
	9			0.378		83.10			0				18.35	3.15
	10			0.378		82.10			0				17.12	4.48
	Average			0.378		81.71			0				18.07	3.68
	STD	0.0	0.0	0.000284	0	0.682	2		0	1			1.573348	
	Min			0.378		80.90			0				16.18	
	Max			0.379		83.10			0				20.56	
	Range			-0.001		-2.200			0				-4.410	

STAT 140-CHE4

Ford Lever Stack Tol. 02-17-03.xls

CT Comp.

Idle

Unit s Test Results Cr/Rod	Sample Number	T <sup>h</sup> Slot angle Degrees	Debris Idle Slop Rad. Inches	Rotor Angle Degrees	CT 1 Element	CT 1 ETC	CT 1 Delta Element/ETC	CT 2 Element	CT 2 ETC	CT 2 Delta Element/ETC	CT 3 Element	CT 3	CT 3 Delta Element/ETC
	1	77.314	0.3306	89.750	81.100	78.02	3.08	20	3	1.45	22.20	20.59	1.61
	2	77.308	0.3300	89.840	81.500	78.78	2.72	40	4	1.78	21.70	20.19	1.54
	3	77.328	0.3300	89.870	81.800	82.20	-0.40	80	4	3.80	21.90	18.05	3.85
	4	77.324	0.3300	89.830	81.000	82.19	-1.19	90	4	4.72	21.80	18.85	4.75
	5	77.321	0.3310	89.880	80.900	82.53	-1.63	10	17	4.77	22.10	17.37	4.73
	6	77.328	0.3300	89.750	81.500	79.81	1.69	30	12	1.68	21.30	19.61	1.69
	7	77.308	0.3300	89.830	81.700	84.48	-2.78	10	2	5.56	21.80	15.44	5.36
	8	77.323	0.3310	89.880	82.400	84.32	-2.92	10	2	5.78	21.80	16.18	5.62
	9	77.348	0.3310	89.840	83.100	82.83	0.27	10	4	3.07	21.60	15.35	3.15
	10	77.308	0.3310	89.810	82.100	83.54	-1.44	10	2	4.38	21.80	17.12	4.48
	Average	77.321	0.330	89.888	81.71	81.92	-0.21	20	3	3.74	22.20	18.07	3.68
	STD	0.012547	0.000497	0.059028	0.652	2.402248		20	1.6733		0.272	1.573348	
	Min	77.308	0.330	89.750	80.900	78.02		10	2		21.300	16.18	
	Max	77.348	0.331	89.940	83.100	85.32		10	4		22.200	20.59	
	Range	-0.041	-0.001	-0.190	-2.200	-7.300		10	2		-0.900	-4.410	

Delta Nom	0.02	-0.004	-0.16	0.96	1.17		2.90	0.64		3.50	0.63	
USL	77.56	0.354	90.25		83.25			32.20			21.20	
Nom	77.30	0.334	90.00	80.75	80.75		29.7	29.7		18.7	18.7	
LSL	77.05	0.314	89.75		78.25			27.20			16.20	
		Element	USL		82.64		36.44			24.38		
		Element	Nom		80.54		33.44			22.38		
		Element	LSL		78.54		31.44			20.38		

Ford Lever Stack Tol. 02-17-03.xls

CT Comp Angle

P03-044 10/17

Unit's Test Results Gr./Rad	Sample Number	T <sub>1</sub> Slot angle Degrees	Delta Idle Stop Rad. Inches	Rotor Angle Degrees	CT 1 Element	CT 1 ETC	CT 1 Delta Element/ETC	CT 2 Element	CT 2 ETC	CT 2 Delta Element/ETC	CT 3 Element	CT 3	CT 3 Delta Element/ETC
	1	77.314	0.3306	80.750	81.10	78.02		0		1.48	22.20	20.69	1.61
	2	77.308	0.3300	80.840	81.50	78.78		0		1.78	21.70	20.18	1.54
	3	77.329	0.3300	80.870	81.60	82.20		0		3.88	21.90	18.05	3.85
	4	77.324	0.3300	80.830	81.00	82.10		0		4.72	21.60	18.86	4.76
	5	77.321	0.3310	80.880	80.90	82.63		0		4.77	22.10	17.37	4.73
	6	77.328	0.3300	80.750	81.50	79.81		0		1.98	21.30	19.61	1.69
	7	77.309	0.3300	80.830	81.70	84.48		0		5.58	21.80	18.44	5.36
	8	77.323	0.3310	80.880	82.40	85.32		0		5.78	21.80	18.18	5.62
	9	77.349	0.3310	80.940	83.10	82.63		0		3.07	21.80	18.35	3.15
	10		0.3310	80.810	82.10	83.64		0		4.38	21.80	17.12	4.48
	Average		0.330	80.838	81.710	81.71				28.88	22.20	21.78	18.07
	STD	0.000487	0.000487	0.059028	0.882235	0.682235		0.3722		1.559	0.271825		
	Min		0.330	80.750	80.900	80.90		0		1.460	21.30		
	Max		0.331	80.940	83.100	85.10		0		5.780	22.20		
	Range		-0.001	-0.190	-2.200	-2.200		0		-4.330	-0.900		

Delta Nom	0.02	-0.004	-0.16	0.98	0.98	-29.91	-2.90	3.50	-3.05
USL	77.55	0.354	80.25	80.75	80.75	80.55	32.20	38.77	21.20
Nom	77.30	0.334	80.00	80.75	80.75	29.7	29.7	18.7	18.7
LSL	77.05	0.314	80.75	80.75	78.25	27.20	27.20	16.20	16.20
		Element	USL	184.87		80.55		38.77	
		Element	Nom	162.87		58.58		38.77	
		Element	LSL	160.87		58.58		34.77	

## Delta

Unit s Test Results Gr./Rad	Sample Number	"D" Slot angle Degrees	Debris life Stop Rad. Inches	Rotor Angle Degrees	CT 1 Element	CT 1 ETC	CT 1 Delta Element/ETC	CT 2 Element	CT 2 ETC	CT 2 Delta Element/ETC	CT 3 Element	CT 3	CT 3 Delta Element/ETC
	1	0.014	-0.004	-0.250	0.350	-2.730	3.080	3.500		1.450			1
	2	0.008	-0.004	-0.180	0.780	-1.070	2.720	2.800		1.750			1
	3	0.028	-0.004	-0.130	1.060	1.450	-0.400	2.800		3.680			3
	4	0.024	-0.004	-0.170	0.250	1.440	-1.190	3.000		4.720			4
	5	0.021	-0.003	-0.120	0.150	1.780	-1.830	3.400		4.770			4
	6	0.026	-0.004	-0.250	0.750	-1.140	1.880	2.500		1.850			1
	7	0.009	-0.004	-0.170	0.860	3.710	-2.780	2.900		5.580			5
	8	0.023	-0.003	-0.120	1.560	4.570	-2.820	2.800		5.780			5
	9	0.048	-0.003	-0.060	2.350	1.780	0.570	2.800		3.070			3
	10	0.008	-0.003	-0.180	1.350	2.790	-1.440	2.800		4.380			4
	Average	0.021	-0.004	-0.162	0.660	0.66	1.17	-0.21		-0.64			
	STD	0.012547	0.000467	0.059028	0.682235	0.682235		2.181	0.3			0.	
	Min	0.008	-0.004	-0.250	0.160	0.15		-2.020					
	Max	0.048	-0.003	-0.060	2.350	2.35		3.080					
	Range	-0.041	-0.001	-0.180	-2.200	-2.200		-0.003					

Delta Nom	-77.26	-0.336	-80.16	-79.79	-79.79		-29.91	26.80		3.50	15.65
USL	77.56	0.354	80.25	80.25	80.25			32.20			21.20
Nom	77.30	0.334	80.00	80.75	80.75		29.7	29.7		18.7	18.7
LSL	77.05	0.314	80.75		76.25			27.20			18.20
		Element	USL		83.02			30.88		20.07	
		Element	Nom		81.02			25.88		18.07	
		Element	LSL		79.02			26.88		18.07	