

RQ03-008


FORD

**FORD 12/12/03 LETTER
TO ODI 4 BOOKS**

ATTACHMENT L

**PART 2 OF 3
BOOK 3 OF 4**

D186 Overview of Brake Pedal Design



TIS Reported = 0, 3, 6, 12, 18, 24, 36

D186 00MY Design Overview:

-Wiring: issues due to pkg'g constraints; wiring gets caught in steering wheel shaft; routing & retaining finalized by 01MYJ1


-Sheetmetal: (cowl) sporadically in-control potentially impacting the anchoring of brake booster and pedal box- impacting booster rod alignment to pedal box mounting pin.

-Pedal box: D186 first platform with adjustable pedal. DV testing identified known lateral lash which worsens over time. Many (38) changes occurred on the design over 2.5yrs.

-Brake booster: Wagon & Sedan booster rods are unique due to brake ratios.

-Pollak switch: First platform with 2 terminal design.

D186 Adj Pedal Design Summary



D186 00MY Design Evolution:

Pedal box:

- 00/1 Teleflex moves mfg from OH to IN. Also mfg change on bracket from laser cutting to hard tooling.
- 00/1 thru 00/3 Welding changes on brackets also occurred. Also, Mounting pin process change to welding.
- 00/8 Grease used on pedal spring changed to match grease used on fix pedal (RECALL: oil onto switch)
- 01/7 Change to anti-lash bushings to address lash.
- 01/11 Reduce welding on booster pin- excessive causing boo to stick
- 02/3 CMM on mig welding
- 02/11 LDM busting out of spec.
- 03/3 Mounting pin length increased based on VSA study which identified offset

Booster:

- 00/8 Wagon production stopped due to pedal ratio issues.
- 00/12 Wagon production resumes with new booster rod

Steering:

- (CowI&IP) sporadically in-control potentially impacting booster rod alignment to pedal box mounting pin

Pollok switch:

- 99/10 CAP&Pollok identified fixed terminal distance not matching go/no go gage resulting in lower actuation (its on)
- 00/8 J1 Polk yoke switches (mounting)
- 02/2 Plating extended to quieten the switch.
- 02/2 Low end shifted from 0.706 to 0.709.
- 03/11 Shift in range on all 2 terminal application. Also changed radius on terminal due to stress fractures.

Wiring:


- 00/3 Wire length changed
- 00/8 Hockeystick added to assist in routing.

24Sep03

Rev 10/13/05 MSAVAG10

2

D186 Fix Pedal Design Summary



D186 080CY Design Evolutions

Pedal box:

-KSR's design changes:

00/6 (Sedan) reoriented booster pin.

00/5 (Sedan) deact flag reference dimension changed.

99/8 (Sedan) pin orientation.

8/00 (Wagon) pedal ratio changed

02/11 LDM busing out of spec.

Booster:

00/8 Wagon production stopped due to pedal ratio issue.

00/12 Wagon production resumes with new booster rod

Sheetmetal:

-(Cowl&IP) sporadically in-control potentially impacting booster rod alignment to pedal box mounting pin.

Pollak switch:

-99/10 CAP&Pollak id fixed terminal distance not matching go/no go gage resulting in lower actuation (its on)

-00/8 J1 Pole yoke switches (mounting)

-02/3 Plating extended to quieten the switch. & Low end shifted from 0.706 to 0.709.

-03/11 Shift in range on all 2 terminal application. Also changed radius on terminal due to stress fractures.

Wiring:

-00/3 Wire length changed

-00/8 Rockerstick and tie strap added to assist in routing.

24Sept03


Rev 10/13/03 MSAVAC10

3

R083-088 4614

D186 02-03MY BOO (*pedal deact)


D186 02-03MY Total BOO



Production Month / Model Year
 *TIS = 0 TIS = 3 TIS = 6 TIS = 12 TIS = 18

TIS Reported = 0,3,6,12,18


D186 Adj Pedal BOO (02-03MY)



Production Month / Model Year
 *TIS = 0 * TIS = 3 * TIS = 6 * TIS = 12 * TIS = 18

TIS Reported = 0,3,6,12,18


D186 Fix Pedal (02-03MY)






Production Month / Model Year
 *TIS = 0 * TIS = 3 * TIS = 6 * TIS = 12 * TIS = 18

TIS Reported = 0,3,6,12,18


Littelfuse Past Performance on D186 (Fixed Pedal)



Other platform performance (Adjustable and Fixed) with Littelfuse



Other Platform Performance (Adjustable and Fixed) with Littelfuse



TIS Reported = 0,3,6,12,18,24,36

Note:
Adjustable pedal and Fix pedal cannot be filtered due to the complexity of the 'option pkg' offered.

D186 Summary Test Results

Component testing (12/02-3/03):

- **Box pedal grease**
 - Test stand cycle testing of Pollak switch replicated field issue of switch failure when subject to oil from grease.
 - Test stand cycle testing of Littelfuse showed no failures when exposed to the grease.

Subsystem testing (12/02-3/03):

- Testing of both switches when exposed to D186's system noise of wiring and rod offset for 400,000 cycles;
 - The Pollak switch showed operational failures on 1 out of 6 switches. In addition, 3 of the 6 showed signs of switch housing degradation due to heat generation.
 - The Littelfuse switch had no failures.
 - Wiring robustness was also proven; high flex wire should be used on platforms with rod actuated boo switch.

In vehicle/System testing to chassis requirements (2/03-5/03):

- Both switches were tested on 12 (02-03MY) vehicles for suitability for field and production system designs.
 - Pollak and Littelfuse original spring strength (8.5-12lb) was too weak causing some flicker.
 - Higher spring strength (10-14.5lb) with both switches pass the chassis taillamp flicker test.
 - The field kit released the Littelfuse switch with the higher spring range.

Dimensional Stack-up Analysis of D186 (12/02-2/02):


- Multiple studies done by VSA identifying system issues. These studies use the Ford print tolerances as the basis and also estimate the capability of each supplier based on these dimensions. Some of the chassis and electrical changes this year were based on these studies.

REPEAT VNS based on 13490 AWS

build month	(aka revisit) 00MY singl rpt	(aka 3 visits) 00MY dbl rpt	(aka 4 visits) 00MY > 3 rpts	(aka revisit) 01MY singl rpt	(aka 3+ visits) 01MY dbl rpt	(aka revisit) 02MY singl rpt
Aug-99	3	0	0			
Oct-99	11	3	8			
Nov-99	33	1	9 (1=5x)			
Dec-99	180	6	7			
Jan-00	782	74	8			
Feb-00	1248	88	9			
Mar-00	1188	91	0			
Apr-00	778	88	0			
May-00	810	27	1			
Jun-00	88	6	0			
Jul-00	18	2	0			
Aug-00	44	0	1	8		
Sep-00				16	1	
Oct-00				11		
Nov-00				15		
Dec-00				4		
Jan-01				4		
Feb-01				2		
Mar-01				4		
Apr-01				3		
May-01				2		
Jun-01				4	1+1 (4x)	
Jul-01				5		
Aug-01						1
Sep-01						1
Oct-01						2
Nov-01						5
Dec-01						0
Jan-02						8
Feb-02						4
Mar-02						3+ 1x3 + 1x4
Apr-02						6
May-02						1
Jun-02						
Jul-02						

NOTES:	9wagons	5wagons	1wagon	1wagon		Oregon

F150 13480 TIS



TIS Reported = 0,3,6,12,18,24,36

Advanced Product Quality Planning Status Report

Date: March 28, 2001

R003-000 4822

Review No.: 2

Diamond Point

Supplier	Polak Engineered Products
Location	Canton, Ma
Supplier Code	P545K
Risk Assessment	
New:	Site Technology X Process
Other Risks	Late kick off

Program	U222/U225
Model Year	2002
Part Number	2L1T-13480-A
Part Name	Six Terminal BOO Switch
Notice Level	AE00-E-11059542-000
User Plant(s)	Michigan Truck

Team Members	Company/Title	Phone's-mail
Michael A. Vidal	Polak / Principal Product Eng.	781-330-5476 / mike.vidal@polak.com
Brian Nadeau	Polak / Sales Engineer	248-324-3830 / brian.nadeau@polak.com
Drew Barton	Polak / Manufacturing Engineer	781-330-5574 / drew.barton@polak.com
Jim O'Rourke	Polak / Quality Engineer	781-330-5300 / jim.orourke@polak.com
Bob Melanovsky	Polak / Sales Manager	248-333-8280 / melanovb@habet.com
Mike O'Reilly	Polak / Engineering Manager	781-330-5444 / mike.oreilly@polak.com
Kathy Olson	Ford / Application Eng. U222	313-317-7868 / kolson5@ford.com
Mark Schneider	Ford / Application Eng. U228	313-208-2716 / mschne13@ford.com
Dele Stappelmier	Ford / Core Switch Engineer	313-645-7696 / delst12@ford.com
John Rentsie	Ford / Supplier Quality Assur.	313-337-8627 / jrents@ford.com

Build Level (MFR)	Material Required Date	Quantity	Concurred		P.L.T. %	P.L.P.Q. %
			No. BCs	No. CCs		
AP			N/A			
CP	7/2/00	125				
1PP	2/23/01					
FEU	4/13/01					
Continuous						
Integrated	5/23/01					
Job1	7/23/01					

APOP Elements	GYR Status	Focus Element Rating	Program Need Date	Supplier Timing Date	Closed Date	Resp. Engineer Initials	Remarks or Assistance Required
1) Sourcing Decision	R		(12-1-99)	5/8/00	5/8/00	Ford Purch's	
2) Customer Input Requirements	Q			7/15/99	7/15/99	BN	
3) Design FMEA	R			2/21/00	2/21/00	MV	
4) Design Review(s)	R		Ongoing	2/22/00	2/22/00	MV/BN	
5) Design Verification Plan	R			10/23/00	10/23/00	MV	
6) Subcontractor APOP Status						MV	
7) Facilities, Tools and Gages	R			5/19/00	5/19/00	DB	
8) Prototype Build Control Plan	R			5/19/00	5/19/00	JOR	
9) Prototype Builds	Q		2/1/00	2/1/00	2/1/00	MV	Build of revised design. Original date: 5/12/00
10) Drawings and Specifications	Y		5/5/00	5/5/00		MV/DB	Need EB approval
11) Team Feasibility Commitment	Q			11/5/99	11/5/99	BN	
12) Manufacturing Process Flow Chart	Q		10/31/00	1/31/00	1/31/00	DB	
13) Process FMEA	Q		10/31/00	2/21/00	2/21/00	DB	
14) Measurement Systems Evaluation	Q			5/25/00	5/25/00	MV	
15) Pre-Launch Control Plan	Q		2/17/00	2/17/00	2/17/00	JOR	
16) Operator Process Instructions	Q			10/15/00	10/15/00	DB	
17) Packaging Specifications	Q		11/15/00	2/2/00	2/2/00	DB	
18) Production Trial Run	R			1/30/01	2/15/01	MOR	
19) Production Control Plan	Q		2/13/00	2/13/00	2/13/00	JOR	
20) Preliminary Process Capability Study	Q			2/16/01		JOR	
21) Production Validation Testing	R		2/5/01	2/11/01		MV	Decision req'd for what level parts to ship for 1PP
22) Production Part Approval (PPW)	R		4/5/01	2/13/01		JOR	
23) PPW Part Delivery at MFR	R		4/5/01	2/13/01		MOR	

COMMENTS: Q:\Pd_Pred28-112\OutDoc\APOP

Component Name:	6-Terminal Gate Switch - RIGHT HAND MOUNT
Part Number:	SL17-12900-00
Sub-System:	Busway 06.06.04

D&P Engineer (Fwd):	Megan Savage
Department:	RVT Electrical
Phone:	2132322-4340
PROPS ID:	vmsavag10

Supplier Contact:	MINE VICAL
Company:	POLLAK
Phone:	(781) 820-6470
PROPS ID / E-Mail:	vmsavag10@pollak.com

Electrical Hardware Requirements Matrix

Connector Number / Pin Number	Signal Name	Functional Class	Operating Voltage				Operating Current			Power Dissipation		Resistance		Type	Timing						Gap	Comments
			Minimum Rated Voltage (V)	Normal Rated Voltage (V)	Maximum Rated Voltage (V)	Maximum Rated Switch Current (I _{sw})	Minimum Rated Switch Current (I _{min})	Maximum Rated Load Current (I _{act})	Max. Rated Instantaneous Power Dissipation (P _{inst})	Max. Rated Continuous Power Dissipation (P _{cont})	Typical Closed Contact Resistance (Ω)	Tolerance of Closed Contact Resistance (mΩ)	Typical Contact Open Resistance (Ω)		Break Type (opt)	Minimum Time to Make (t _{make_min})	Normal Time to Make (t _{make})	Maximum Time to Make (t _{make_max})	Minimum Time to Break (t _{break_min})	Normal Time to Break (t _{break})		
1	Phase B+ 60	c	16	16	0	80	3.5	16.5	--	2.7	0.005	--	1 MΩ	--	--	--	--	--	--	0.4	5 ms	velocity and timing are operator dependent
2	Stop Lamps	e	16	16	0	80	3.0	16.5	--	2.7	0.005	--	1 MΩ	--	--	--	--	--	0.4	5 ms		
3	Phase B+ 60	c	16	16	0	80	3.0	16.5	--	2.7	0.005	--	1 MΩ	--	--	--	--	--	0.4	5 ms		
4	OVERSE & Pull Up Mod	e	65	72	0	80	3.5	12.5	--	2.7	0.005	--	1 MΩ	--	--	--	--	--	0.4	5 ms		
5	Ground	e	16	16	0	0.017		0.017	--	0.004	0.005	--	1 MΩ	--	--	--	--	--	0.4	5 ms	velocity and timing are operator dependent	
6	Pull Down Modulus	c	16	13	0	0.017		0.017	--	0.004	0.005	--	1 MΩ	--	--	--	--	--	0.4	5 ms		

Customer Name: _____
 Part Number: _____
 Revision: _____

Part Number: _____
 Description: _____
 Date: _____
 Rev: _____

Supplier Code: _____
 Company: _____
 Part: _____
 Rev: _____


Electrical Hardware Requirements Matrix

Req ID	Description	Units	Min	Max	Tolerance	Notes	Status	Requirements	
								Value	Units
	Functional Class								
	Minimum Rated Voltage (V)								
	Nominal Rated Voltage (V)								
	Maximum Rated Voltage (V)								
	Maximum Allowable Current (A)								
	Minimum Rated Ambient Current (A)								
	Maximum Rated Load Current (A)								
	Min. Rated Inductance Power Consumption (W)								
	Max. Rated Dissipated Power Consumption (W)								
	Typical Current (mA)								
	Temperature of Circuit (Celsius)								
	Typical Contact Open Resistance (ohm)								
	Mean Time To Failure (MTTF)								
	Rated Time to Make (ms)								
	Rated Time to Break (ms)								
	Minimum Tripping Current (mA)								
	Maximum Tripping Current (mA)								
	Rated Time to Make (ms)								
	Rated Time to Break (ms)								
	Maximum Trip to Open (ms)								
	Open Contact Delay (ms)								
	Closing/Opening Contact Voltage (V)								
	Temperature of env. (C)								
	Contact Material								

Customer Name: _____
 Part Number: _____
 Revision: _____


Part Number: _____
 Description: _____
 Date: _____
 Rev: _____

MODEL YEAR MATRIX



TIS Reported = 8,12,24,36


MODEL YEAR MATRIX




TIS Reported = 6,12,24,36

D188 Total 13480 Ft's

MODEL YEAR MATRIX




MODEL YEAR MATRIX




D188 Total Adjustable

MODEL YEAR MATRIX



TIS Reported = 5,12,24,36


MODEL YEAR MATRIX




TIS Reported = 5,12,24,36

D180 Total Adjustable

MODEL YEAR MATRIX




MODEL YEAR MATRIX




D186 Total for Sedan Adjustable


MODEL YEAR MATRIX




MODEL YEAR MATRIX



D186 Total Weapon Adjustable




TIS Reported = 0,12,24,36




TIS Reported = 0,12,24,36

D166 Total Weapon Adjustable

MODEL YEAR MATRIX




MODEL YEAR MATRIX




D188 Total Flared

MODEL YEAR MATRIX





T18 Reported = 6,12,24,36

MODEL YEAR MATRIX



T18 Reported = 6,12,24,36


D188 Total Flood



SPETERS
1/14/03


D188 Sedan Fixed

MODEL YEAR MATRIX





TIS Reported = 6,12,24,36

MODEL YEAR MATRIX



TIS Reported = 6,12,24,36

D186 Section Flood




SPETERS
1/14/03

Formatted: MSavegs
12/4/2003
MSavegs_13480_D186_trend charts.xls


D186 Wagen Pferd

MODEL YEAR MATRIX




TIS Reported = 6, 12, 24, 36

MODEL YEAR MATRIX




TIS Reported = 6, 12, 24, 36


MODEL YEAR MATRIX



MODEL YEAR MATRIX




MODEL YEAR MATRIX




TB Reported = 6,12,24,36

MODEL YEAR MATRIX




TB Reported = 6,12,24,36


MODEL YEAR MATRIX



MODEL YEAR MATRIX




MODEL YEAR MATRIX




TIS Reported = 8,12,24,36

MODEL YEAR MATRIX




TIS Reported = 8,12,24,36


MODEL YEAR MATRIX




MODEL YEAR MATRIX




MODEL YEAR MATRIX



MODEL YEAR MATRIX




MODEL YEAR MATRIX




TIS Reported = 0,12,24,36

MODEL YEAR MATRIX




TIS Reported = 0,12,24,36


MODEL YEAR MATRIX



MODEL YEAR MATRIX




MODEL YEAR MATRIX




TIS Reported = 8, 12, 24, 36

MODEL YEAR MATRIX




TIS Reported = 8, 12, 24, 36


MODEL YEAR MATRIX



MODEL YEAR MATRIX




MODEL YEAR MATRIX





TIS Reported = 6,12,24,36

MODEL YEAR MATRIX



TIS Reported = 6,12,24,36



Polak BSO Review

DTSS History

AWS: 00MY vs 01-03MY	Adjustable pedal worse than Fixed pedal (consistent also on wagon and sedan with different pedal ratios); lights on and Brake shift Interlock issues identified in field.
CCRG:	Separate recalls for pedal separation and grease contamination. Internal Inquiries on wiring (00MY). Internal inquiry on switch and grease reopened (02-03oy) due to trending.
Design changes by Chassis	Change in grease used on adjustable pedal box. Booster rod offset corrected by lengthening mounting pin (Mar03). Pedal lash not addressed.
Design changes by Electrical	Wiring routing changes finalized by 01MY Wiring fatiguing due to mechanical strain id'd via testing. Crosslink wire to be incorp in production in Oct03oy. The Littlefuse switch was observed to be more tolerant to pedal grease as well as CHMSL flicker- lit released- FCSD to issue to field. Polak switch actuation range has been shifted to high side of range to attempt to compensate for too much preload from rod (PSW due Oct 03: C11470665). Under review: Polak spring force can be increased to reduce lights on field issue...but requires component and field testing. Also Polak reevaluating design to increase contact force...

W126 History

AWS: 00MY vs 01-03MY	Adjustable pedal worse than Fixed pedal. Lights on is predominant problem.
CCRG:	Oct 02 68M issued for lights on (C11614774)
Design changes by Chassis	Feb-Aug 02 chassis ran runner & reduced booster force which coincides w/ warranty spike in 02MY. TRW IVD with adjustable found to be high on spec. Unknown if actions are being taken for W126. Stack study conducted for V229- system is in tolerance.
Design changes by Electrical	88M went out for OCT02 with higher make switches to compensate for booster rod offset . Switch actuation range has been increased (due Oct03). Unknown if V229 uses high flex wire. W126 did use high flex. Recommendations: Option 1 Polak spring force can be increased to reduce lights on W126 field issues...but requires component & vehicle testing. Testing and Timing: Vehicle Cobblestone testing and cycle testing to make sure no contact stress due to increased force. Timing by Also Polak reevaluating design to increase contact force... Fleet under review - low mileage failure id.

U152 /231 History

AWS:	U150 had 5 terminal with less than 4r/1000 for 38mie U152 02MY & 03MY are tracking sporadically avg 10r/1000 for 24mie. Worse appears to be fixed pedal- however take rates on U152 were not built as forecasted. Lights on and park shift Interlock are id'd as issues. U152 adjustable with IVD was introduced with problem identified on force balance with IVD booster & deact; correction targeted for J104MY. U231 has adjustable and IVD (option). AWS is immature however 3-6 mie is approaching 2r/1000.
CCRG:	None
Design changes by Chassis	Pedal mounted redundant deact (IVD only) force to be changed at 04MY J1 should address 'lights on' for U152. Fleet vehicles evaluated by chassis indicated that wire harness too stiff when cold causing lights on. See electrical 's report to change harness). Stack study conducted showing system in tolerance. Additional study underway by greenbelts; OMM all system components underway at PDC

Design changes by Electrical

Fleet data under review - low mileage failures id.

Pedal mounted redundant deact (IVD only) force to be changed at D4MY J1 should address 'lights on' for U162.

Inquiry to platform made to change to high flex wire based on vibration...resistance from platform. Polak switch actuation range has been shifted to high side of range as well as correct for cranking of terminal on few field returns (PSW due Oct 03: C11470585).

Under review; Polak spring force can be increased to reduce lights on field issue...but requires component and field testing. Also Polak revaluing design to increase contact force...

D186 History

AWS: 00MY vs 01-03MY	Adjustable pedal worse than Fixed pedal (consistent also on wagon and sedan with different pedal ratios); 'Lights on' and 'Brake shift interlock' issues identified in field.
CCRG:	-Separate recalls for pedal separation and grease contamination. -Internal inquiries on wiring (00MY). -Internal inquiry on switch and grease reopened (02-03cy) due to trending.
Design changes by Chassis	-Change in grease on adjustable pedal box. -Booster rod offset corrected by lengthening mounting pin (Mar03). -Pedal lash <u>not</u> addressed.
Design changes by Electrical	-Wiring routing changes finalized by 01MY -Wiring fatiguing due to mechanical strain id'd via testing. Crosslink wire due in production in Oct03cy. -The Littlefuse switch was observed to be more tolerant to pedal grease as well as CHEMEL flicker- kit released- FCSD to issue to field. Production options: - Revert to Littlefuse (coordinated change). - Continue with Poltek Changes: a) switch actuation range has been shifted to high side of range to attempt to compensate for too much preload from rod (PSW due Oct 03: C11470685). b) 2 terminal spring force can be increased to reduce lights on W128 field issue...but requires component & vehicle testing. Vehicle Cobblestone testing & switch cycle testing to make sure no contact stress due to increased force. Estimated test timing: 14 weeks c) Poltek reevaluating design to increase contact force...via material thickness.

W128 History

AWS: 00MY vs 01-03MY	Adjustable pedal worse than Fixed pedal. Lights on is predominant field problem.
CCRG:	Oct 02 88M issued for lights on (C11614774)
Design changes by Chassis	-Feb-Aug 02 chassis run runner & reduced booster force which coincides w/ warranty spike in 02MY. -TRW IVD with adjustable found to be high on spec. -Unknown if actions are being taken for W128. -Stack study conducted for V229- system is in tolerance. No plant issues during any builds nor during vehicle durability.
Design changes by Electrical	-88M went out for OCT02 with higher make switches to compensate for booster rod offset. -Switch actuation range has been increased (due Oct03). -W128 did use high flex. Unknown if V229 uses high flex wire. -W128 Fleet under review - low mileage failures id. Field returns are being analyzed by Poltek. Options for Field: Continue with Poltek changes: a) switch actuation range has been shifted to high side of range to attempt to compensate for too much preload from rod (PSW due Oct 03: C11470685). b) 2 terminal spring force can be increased to reduce lights on W128 field issue...but requires component & vehicle testing. Vehicle Cobblestone testing & switch cycle testing to make sure no contact stress due to increased force. Estimated test timing: 14 weeks c) Poltek reevaluating design to increase contact force...via material thickness. <u>Alternative option:</u> Finish Pkg studies for 5 terminal boo (low current) to address field spike.

U152 /231 History

AWS:	-U160 had 5 terminal with less than 4r/1000 for 38m/s -U152 02MY & 03MY are tracking sporadically avg 10R/1000 for 24m/s. Worse appears to be fixed pedal- however take rates on U152 were not built as forecasted. 'Lights on' and 'park shift interlock' are id'd as issues. -U152 adjustable with IVD was introduced with problem identified on force balance with IVD booster & deck; correction targeted for J104MY. -U231 has adjustable and IVD (option). AWS is immature however 3-6 m/s is approaching 2r/1000.
CCRG:	None
Design changes by Chassis	-Spd decel flags to be stiffened.(IVD only) at 04MY J1 should address adjustable pedal 'lights on'. -Stack study conducted showing system in tolerance. -Additional study underway by greenbelts; CMM all system components underway at PDC

Design changes by Electrical

-Pedal mounted redundant deact (FVD only) to change to preset switch at O4MY J1 (eliminating assembly issues for setting switch)should address 'lights on' for U152 adj pedal issue.
-Inquiry to platform made to change to high flex wire based on verbalisms...resistance from platform.
-Polak switch actuation range has been shifted to high side of range as well as correct for cracking of terminal on few field returns (PSW due Oct 03: C11470585).
Options for Production & Field:
- Revert to Littelfuse. (coordinated change)
- Continue with Polak Changes:
a) switch actuation range has been shifted to high side of range to attempt to compensate for too much preload from rod (PSW due Oct 03: C11470585).
b) 2 terminal spring force can be increased to reduce lights on W128 field issue...but requires component & vehicle testing. Vehicle Cobblestone testing & switch cycle testing to make sure no contact stress due to increased force. Estimated test timing: 14 weeks
c) Polak reevaluating design to increase contact force...via material thickness.

	Description	Fix Claims	Adj Claims	Fix Claims	Adj Claims	Fix Claims	Adj Claims
		02MY (12/02CY Pull)	02MY (12/02CY Pull)	02MY (3/03CY Pull)	02MY (3/03CY Pull)	03MY (3/03CY Pull)	03MY (3/03CY Pull)
Discrepancies in rows are due not enough info and/or misc claims	V70						
	MMSC						
	V18 PWR/BATT	7	0	11	2	1	
	V41 CRUISE	28	3	38	3		
	V21 BRAKING, PARK	205	16	310	35	4	5
	Verbatim= Lts on & Park						
	Verbatim= Lts on						
	Verbatim= Lts Inop						
	Verbatim= Lts Inop & Park						
	Verbatim Park		1				
	V47 TRANSMISSION: PARK	148	18	205	22	2	1
	Verbatim= Lts on & Park						
	Verbatim= Lts on						
	Verbatim= Lts Inop						
	Verbatim= Lts Inop & Park		1				
	Verbatim Park		17				
	V45 TRANSMISSION: PARK	10	1	15	3		1
	Verbatim= Lts on & Park						
	Verbatim= Lts on						
	Verbatim= Lts Inop						
	Verbatim= Lts Inop & Park						
	Verbatim Park		1				
	V17 Lts ON/PARK	136	11	200	17	1	
	Verbatim= Lts on & Park						
	Verbatim= Lts on		5				
	Verbatim= Lts Inop						
	Verbatim= Lts Inop & Park						
	Verbatim Park						
V77 TOTAL LIGHTING	611	66	1268	191	3	16	
Verbatim= Lts on & Park							
Verbatim= Lts on		34					
Verbatim= Lts Inop		1					
Verbatim= Lts Inop & Park							
Verbatim Park							
TOTAL CLAIMS	1348 / 1448	106 / 118	2051 / 2183	223 / 243	16	30	

EDS Related	TBD	TBD	125	25	3	3
REPEAT VIN's			84		6	

TOTAL OOMY D186 AWS (Dec02 AWS)

Description	Fixed Total Claims OOMY	Fixed Total Claims O1MY	Fixed Total Claims 02-03MY	Adj Total Claims OOMY	Adj Total Claims O1MY	Adj Total Claims 02-03MY
VFG						
V19 PWR/BATT	2	3	1	20	0	0
V41 CRUISE	2	2	4	20	1	1
V21 Braking; aka	25	16	2	327	15	1
V47 Transmission;	204	32	21	1202	32	6
V48 Transmission;	3	6	0	86	0	0
V77 Lighting	146	84	33	1457	33	8
Verbatim= Lts on						
Verbatim= Lts Inop or Park						
V17 LTS ON/PARK	38	18	8	311	8	1
VFG CUM	416	137	62	3425	69	17
CC						
30 chafe	2	0	0	12	0	0
B4 pinched	18	2	1	15	1	0
X1,X2,X4,X7 gnd, eds, etc	38	3	1	103	3	1
42 does not oper	222 (B1eds)	88	39	2170	53	7
28 'open' (vague)	95 (50eds)	27	13	679	18	5
48 burned	27 (17eds)	6	3	299	7	1
1 broken (switch)	16 (11eds)	0	2	68	4	0
41 sick/birds	8			186	8	0
CC CUM	418	126	68	3532	92	14
TOTAL CLAIMS	434	149	68	3614	101	17

TOTAL OOMY D186 AWS (Dec02 AWS)

Description	Fixed Total Claims OOMY	Fixed Total Claims O1MY	Fixed Total Claims 02-03MY	Adj Total Claims OOMY	Adj Total Claims O1MY	Adj Total Claims 02-03MY
VFG						
V19 PWR/BATT	55	21	4	186	5	8

V41 CRUISE	128	83	15	250	31	28
V21 Braking; aka	781	124	38	3221	162	131
V47 Transmission;	2589	243	72	7658	590	74
V48 Transmission;	193	17	3	601	43	4
V77 Lighting	3328	482	124	13988	648	619
Verbatim= Lts on						
Verbatim= Lts Inop or Park						
V17 LTS ON/PARK	747	119	41	2718	137	71
VFG CUM	6789	1049	295	28790	1607	938
CC						
30 chafe	38	1	0	42	3	1
B4 pinched	308	10	1	111	6	3
X1,X2,X4,X7 gmtd, eds, etc:	690	47	13	862	53	27
42 does not open	4611	636	178	18085	055 (77eds+sw)	587 (38 eds+sw)
28 'open' (vague)	1828	189	50	5530	315	134 (16 eds+sw)
48 burned	680	87	19	2485	118	65 (2 eds)
1 broken (switch)	380	28	3	389	22	6
41 slots/bands	332			2073	104	125
CC CUM	6983	1008	284	29568	1678	975
TOTAL CLAIMS	9390	1188	332	38270	1734	894

Data Sorted based on 1Mar01-Jan03 (Post Recall/Service Kit) Repair Cutoff dates (used for CCRG paper Feb03):

	Description	Fixed Claims OCMY	All Claims OCMY post 3/1/01
all/mo	VFG		
	MSC		140
	V19 PWR/BATT		7
	V41 CRUISE		18
	V21 BRAKING; PARK		327
	Verbatim= Lts on & Park		3
	Verbatim= Lts on		260
	Verbatim= Lts Inop		6
	Verbatim= Lts Inop & Park		8
	Verbatim Park		98
	V47 TRANSMISSION: PARK		1087

Discrepancies in nos are due not enough info and/or miss o

Verbatim= Lts on & Park	9	
Verbatim= Lts on	1	
Verbatim= Lts Inop	0	
Verbatim= Lts Inop & Park	73	
Verbatim Park	948	
V48 TRANS ISSIO	85	
Verbatim= Lts on & Park	0	
Verbatim= Lts on	1	
Verbatim= Lts Inop	8	
Verbatim= Lts Inop & Park	0	
Verbatim Park	78	
V17 LTS ONPARK	218	
Verbatim= Lts on & Park	2	
Verbatim= Lts on	81	
Verbatim= Lts Inop	9	
Verbatim= Lts Inop & Park	22	
Verbatim Park	77	
V77 TOTAL LIGHTING	1885	
Verbatim= Lts on & Park	15	
Verbatim= Lts on	803	
Verbatim= Lts Inop	92	
Verbatim= Lts Inop & Park	175	
Verbatim Park	0	
TOTAL CLAIMS	9308	2836

Verbatim Summary	2836
Verbatim= Lts on & Park	29
Verbatim= Lts on	1158
Verbatim= Lts Inop	114
Verbatim= Lts Inop & Park	278
Verbatim= Park	1199

Data Sorted based on 1Mar91-Jan03 (Post Recall/Service Kit) Repair Cutoff dates (used for CCRQ paper Feb03):

	Description	Fixed Classes 00MY	All Claims 00MY post 3/1/01
VEG			
	MISC		937
	V19/PWRBATT		198
	V41 CRUISE		162

Discrepancies in rows are due not enough info and/or miss claims

V21 BRAKING: PARK	1663
Verbatim= Lts on & Park	
Verbatim= Lts on	
Verbatim= Lts Inop	
Verbatim= Lts Inop & Park	
Verbatim Park	
V47 TRANSMISSION: PARK	8071
Verbatim= Lts on & Park	
Verbatim= Lts on	
Verbatim= Lts Inop	
Verbatim= Lts Inop & Park	
Verbatim Park	
V48 TRANSMISSION	408
Verbatim= Lts on & Park	
Verbatim= Lts on	
Verbatim= Lts Inop	
Verbatim= Lts Inop & Park	
Verbatim Park	
V17 LTS ON/PARK	1728
Verbatim= Lts on & Park	
Verbatim= Lts on	
Verbatim= Lts Inop	
Verbatim= Lts Inop & Park	
Verbatim Park	
V77(TOTAL LIGHTING	8033
Verbatim= Lts on & Park	32
Verbatim= Lts on	3,912
Verbatim= Lts Inop	228
Verbatim= Lts Inop & Park	280
Verbatim Park	188
CC	
30 chafe	
84 pinched	
X1,X2,X4,X7 gnd, eds, etc	
42 does not operate	
28 'open' (vaguely used by tech's)	
48 burned	
1 broken (switch)	
41 sick/brake	

4,000 claims evaluated III

Verbatim Summary	
Verbatim= Lts on & Park	
Verbatim= Lts on	
Verbatim= Lts Inop	
Verbatim= Lts Inop & Park	
Verbatim= Park	

CC CUM		
TOTAL CLAIMS		
TOTAL CLAIMS		20323

REPEAT VISITS based on 13480 AHS

build month	(aka revlat)	(aka 3 visits)	aka 4 visits(aka revlat)	(aka 3+ visits)	(aka revlat)
	00MY singl rpt	00MY dbl rpt	00MY> 3 rpts	01MY singl rpt	02MY singl rpt
Aug-00	3	0	0		
Oct-00	11	3	8		
Nov-00	33	1	9 (1=5x)		
Dec-00	188	5	7		
Jan-01	782	74	8		
Feb-01	1248	98	9		
Mar-01	1198	91	0		
Apr-01	779	88	0		
May-01	310	27	1		
Jun-01	88	5	0		
Jul-01	18	2	0		
Aug-01	44	0	1	8	
Sep-01				18	1
Oct-01				11	
Nov-01				15	
Dec-01				4	
Jan-02				4	
Feb-02				2	
Mar-02				4	
Apr-02				3	
May-02				2	
Jun-02				4	1 +1 (4x)
Jul-02				5	
Aug-02					1
Sep-02					1
Oct-02					2

ALAS 808-1300

Nov-01	5
Dec-01	0
Jan 02	6
Feb 02	4
Mar 02	3+ 1x3 + 1x4
Apr 02	5
May 02	1
Jun 02	
Jul 02	

NOTES:	0wagons	55wagons	1wagon	1wagon	0wagon

Pedal Spacing recall?

Wire claims

	Taurus Sedan	Taurus Wagon
2000 Total Fix	10,798	858
EDS Mentioned	473/1200	194
2000 Total Adj		3,121
EDS Mentioned		232/2347
2001 Total Adj		162
EDS Mentioned		27
2002&3 Total Fix		
EDS Mentioned		

Platform	Adj Total Claims 00-03MY	00MY	01MY	02MY	03MY
D185 Sedan					
#1 CCC					
#2 CCC					
Wire Repairs					
D189 Wagon	3313	3121	163	28	1
#1 CCC		P01(886)	P01(51)	P01(11)	-
Actual per verbalism			83+13	9+1	
#2 CCC		L26 (802)	L26(48)	L26(8)	-
Actual per verbalism			59	5	
Wire Repairs		77/1000	23	3	-

2002/03 Total		29
Adi		
EDS Mentioned		4

Discrepancies in
nos are due not
enough info

	Description (Dec 02 Pull)	Fixed Claims 00MY	Adj Claims 00MY	Fixed Claims 01MY	Adj Claims 01MY	Fixed Claims 02MY	Adj Claims 02MY	Fixed Claims 03MY	Adj Claims 03MY
V33									
	MISC								
	V19 PWR/BATT	33		10		60			
	V41 CRUISE	34		60		22			
	V31 BRAKING: PARK	271		230		245		4	
	V47 TRANSMISSION: PARK	107		47		40		4	
	V48 TRANSMISSION: PARK	10		6		1			
	V17 LTS ON/PARK	120		33		171			
	V77 TOTAL LIGHTING	287		788		1007		5	
	TOTAL CLAIMS	1577	430	1280	TBD	1732	TBD	15	TBD
	Repairs								
	EDS related	55	10	51	TBD	75	TBD	4	TBD

ELECTRICAL QUARTERBACK KEY ATTRIBUTE/HEALTH CHART SWITCH SUBSYSTEM

Item	Design Metric	Key Deliverable	Lead Responsibility	Overall Switch Health to Program	Platform Application		Comments
					Platform	Part	
1		X			SPIT-1-8480-AA (2 TERMINAL)	D185 Sedan	
5		X			SPIT-1-8480-BA (2 TERMINAL)	D185 Wgn	
9		X			SPIT-1-8480-AA (2 TERMINAL)	J162	
11		X			SPIT-1-8480-AA (2 TERMINAL)	W126	
13		X			SPIT-1-8480-AA (2 TERMINAL)	W126 (Field)	
14		X			SPIT-1-8480-AA (2 TERMINAL)	V228 (Field only)	
15		X			SPIT-1-8480-CA (2 TERMINAL)		
16		X			SPIT-1-8480-BA (6 TERMINAL)	JP207, PN180, P131, P186	
18		X			SPIT-1-8480-AB (2 TERMINAL)	U1180, U1000	
25		X			SPIT-1-8480-AA (2 TERMINAL)	LQ22/228 & P221 (03-)	
29		X					
33		X					
34		X					

Pollak BOO Packaging & Forward Application

Projected Volume/Usage for Loss Travel:

<u>2T</u>		<u>5T</u>		<u>6T/4T</u>	
V229-	223k	P150-	300k	U222/228-	171k
D186 thru 067-	480k	P131/96 -	365k		
V127 thru 07/87-	173k	EN/PN-	280k		

Volume= 1.5M @ 07/08MY (without D186)

Present (5/03) price based
on present volumes

		Pkg's Dimensions		
		H	L	W
2T= \$0.85 lo (V229)				
\$1.04 high (D186/U152/U231)	2T	70.6	38.2	35
5T= \$1.43 (UP207/P150/PN96/P131)	5T	52.1	37.4	25
6T= \$2.12 (U222/228/P221)	6T/4T	78.4	38.2	35
4T= \$2.02 (U222/228/P221)				

H = dimension from center of mounting pin hole to end of switch as an extension of booster rod.

DV - Durability per specs released

2T: Total cycles= 1M
#cycles @ 16.5A= 100k at different increments
900k @ 10A
24 cycles /minute w/ 0.5 sec on time.

Plunger= GF Poly
Contacts = Stat= C194
Move= ?

6T: Total cycles= 1M
#cycles @ 16.5A= 98k at different increments
remaining cycles @ 12A
24 cycles /minute w/ 0.8 sec on time.

Plunger= FBT GF
Contacts = Stat= 1927
Move= Olin 7025 alt; Cu beryllium 17410

5T: Total cycles= 500k @ 16.5A
5 or 10 cycles /minute w/ 1 sec on time, 10 sec off or 5 sec if 2 banks used.

Plunger= GF Poly
Contacts = Stat= 1927 Or EP110
Move= Cu beryllium 17410

New proposed plunger material for extended durability=

R003-000 0000

Pollak				
2 Terminal Switch	Customer /Tech	Field Analysis	Switch Design Changes	System Changes
D168	Lts On & Park Shift Interlock	- Field returns show no problem found	- Change to <u>stronger spring</u> within switch to counter pedal weight (ETA Post J1 pending testing). -Change the <u>switch actuation</u> range to compensate for system interaction. (C11470685; ETA NOV 03)	-Hi flex wire adopted to prevent wiring breakage. -Chassis & Switches developing System FMEA: cascade SC's to all suppliers
W128/V228	Lts On	- Field returns show no problem found	- Change to <u>stronger spring</u> within switch to counter pedal weight (ETA Post J1 pending testing). -Change the <u>switch actuation</u> range to compensate for system interaction. (C11470685; ETA NOV 03)	- V228 improved robust pedal box - Wiring TBD (New supplier) - Chassis & Switches developing System FMEA: cascade SC's to all suppliers
U152	Lts On & Park Shift Interlock	TBD	- Change to <u>stronger spring</u> within switch to counter pedal weight (ETA Post J1 pending testing). -Change the <u>switch actuation</u> range to compensate for system interaction. (C11470685; ETA NOV 03)	- Redundant Speed deact switch changes @ J1 to address adj IVV vehicle problem with Lts on. - Chassis & Switches developing System FMEA: cascade SC's to all suppliers
U231	Lts Off	TBD	- Change to <u>stronger spring</u> within switch to counter pedal weight (ETA Post J1 pending testing). -Change the <u>switch actuation</u> range to compensate for system interaction. (C11470685; ETA NOV 03)	- Under investigation - Chassis & Switches developing System FMEA: cascade SC's to all suppliers

Pollak				
555 Terminal Switch	Customer /Tech	Field Analysis	Switch Design Changes	System Changes
U222/228	Lts On & Park Shift Interlock	- Field returns show no problem found	- Added fine silver to low current contacts and delete to sets of contacts for improved closing forces and cost save.	
Fseries	Lts On	- Field returns show no problem found		-Hi flex TBD
UP207	Lts On & Park Shift Interlock	TBD		-Hi flex wire being adopted to prevent breakage.

Line/ups				
Switch	Customer /Tech	Field Analysis	Switch Design Changes	System Changes
EN	Park Shift Interlock			-Speed deact changed in Oct 02. Trending warranty.
FN	Lts On			
V127	n/a	Low F's	None required	
SN195	n/a	Low F's	None required	

Methods				
Switch	Customer /Tech	Field Analysis	Switch Design Changes	System Changes
C170				
DEW				
M206				
U204				-Speed deact Change (Oct02) -Brake pedal box- process control tightened- improved warranty trended down (Dec02)

Poltek 2 Terminal Switch	Customer /Tech	Field Analysis	Switch Design Changes	System Changes
D186	Lts On & Park Shift Interlock	- Field returns show no problem found - Pedal box lash & wiring issues	- Change to <u>stronger spring</u> within switch to counter pedal weight (ETA Post J1 pending testing). -Change the <u>switch actuation</u> range (upwards) to compensate for system interaction. (C11470585: ETA NOV 03)	- Hi flex wire adopted to prevent wiring breakage. -Chassis & Switches developing System FMEA: cascade SC's to all suppliers
W126/ V229	Lts On	- Field returns show no problem found - W126 rod is major contributor to lts on	See above	- V229 improved robust pedal box & booster rod changed. - Wiring TBD (New supplier) - Chassis & Switches developing System FMEA: cascade SC's to all suppliers
U152	Lts On & Park Shift Interlock	-IVD vehicles predominantly. -Also 03MY not trending like 02MY.	See above	- Wiring sheathing on 03MY and takeout length reqs revision- Identified . - Redundant Speed deact switch changes @ J1 to address adj IVD vehicle problem with Lts on. - Chassis & Switches developing System FMEA: cascade SC's to all suppliers
U231	Lts On	TBD- Problem reported last week (Jun21)	See above	-Hi flex wire under review (3/10 claims). - Chassis & Switches developing System FMEA: cascade SC's to all suppliers

Poltek 5&6 Terminal Switch	Customer /Tech	Field Analysis	Switch Design Changes	System Changes
U222/228	Lts On & Park Shift Interlock	- Field returns show no problem found	- Added fine silver to low current contacts and deleted a set of contacts for improved closing forces and cost save. (CR 11433160 ETA 04MY J1)	TBD
F series	Lts On	Low R's	-Same as above	- Hi flex under review with systems engineering.
UP207	Lts On & Park Shift Interlock	Low R's	Low R's	- Hi flex wire being considered - Module/system operating below minimum current on select vehicles.
P150	Park Shift Interlock	Low R's	Low R's	- Hi flex wire being considered. - Module/system operating below minimum current on select vehicles.

R020-088 5194

Littlefuse Switch	Customer /Tech	Field Analysis	Switch Design Changes	System Changes
EN	Park Shift Interlock	No problem found	None required	-Speed deact changed in Oct 02. Trending warranty. -Booster rod might be changed pending testing.
FN	Lts On	No problem found	None required	-Speed deact changed in Oct 02. Trending warranty. -Booster rod might be changed pending testing.
VN127	n/a	Low R's	None required	None required
SN195	n/a	Low R's	None required	None required

Methods Switch	Customer /Tech	Field Analysis	Switch Design Changes	System Changes
C170	Lts On & Park Shift Interlock	TBD	None at this time	-System released by Europe; changes made unknown.
U204	Lts On & Park Shift Interlock	TBD	None at this time	- Speed deact change (Oct02) - Brake pedal box- process control tightened (Dec02)
DEW	Lts On & Park Shift Interlock	Low R's	None at this time	None at this time
M205	Lts On & Park Shift Interlock	Low R's	None at this time	None at this time

Switch	mV @ Terminal Block	mV @ Switch
1	210	26
2	294	27
3	206	27
4	283	27
5	202	34
6	298	38
7	345	81
8	212	26
9	299	44
10	213	33
11	282	38
12	210	89

12/3/02: All Switches operating normally

Switch	mV @ Terminal Block	mV @ Switch
1	224	27
2	297	34
3	220	28
4	290	30
5	205	29
6	385	40
7	333	134
8	250	33
9	309	30
10	221	35
11	310	60
12	237	57

12/4/02: Switch 1, 2, 8 sticking ON intermittently

Switch	mV @ Terminal Block	mV @ Switch
1	228	36
2	305	25
3	218	26
4	298	28
5	215	34
6	337	72
7	282	34
8	283	27
9	308	27
10	215	31
11	315	87
12	214	39

12/8/02: Switch 1, 2, 3, 8, 9 sticking ON intermittently

Switch	mV @ Terminal Block	mV @ Switch
1	216	38
2	295	26
3	223	30
4	308	42
5	221	33
6	328	45
7	288	44
8	235	44
9	318	32
10	220	48
11	277	30
12	218	33

Switch 1, 2 Intermittently stuck ON
Switch 3 slow to close

Switch	mV @ Terminal Block	mV @ Switch
1	36	219
2		
3	27	239
4	36	323
5	30	244
6	33	411
7	44	333
8	47	238
9	32	420
10	36	227
11	38	267
12	36	225

Replaced #2 Harness, wire was damaged possibly during service of chamber heating unit.

Switch	mV @ Terminal Block	mV @ Switch
1	238	36
2	275	28
3	307	42
4	310	41
5	222	32
6	548	47
7	409	36
8	218	33
9	440	26
10	228	33
11	298	25
12	228	35

Switch 1, 2 stuck ON
Switch 3 slow to close
Log reports switch 6 not lighting at 187338 cycles
12/16/2002 13:48
189450 Cycles

Test restarted at 2:55 PM 12/16/2002 189450 cycles.

Switch 3, 8, 9 show signs of overheating: Beam discoloration, contact carbon, lower beam support deformation.
Switch 1, 2 show signs of contact point carbon buildup.
Switch 7 shows normal wear.

Switch	mV @ Terminal Block	mV @ Switch
1	211	25
2	312	29
3	210	41
4	249	34
5	192	29
6	272	110
7	405	37
8	234	62
9	755	27
10	199	27
11	261	27
12	203	37

#6 Stays ON Intermittently

#8 is late to light

#9 Strand breakage, Harness Replaced at 280,690 Cycles

#4 Strand breakage, Harness Replaced at 251,073 Cycles

Switch	mV @ Terminal Block	mV @ Switch
1	234	30
2	470	51
3	245	33
4	292	33
6	238	36
8	292	34
7	390	36
8	293	79
9	275	39
10	233	43
11	294	31
12	247	42

1/3/03 9:45AM

Switch # 2 Strand breakage, harness replaced at 300,087 Cycles.

Switch	mV @ Terminal Block	mV @ Switch
1	236	60
2	270	35
3	245	35
4	292	42
5	253	31
6	328	67
7	420	38
8	317	109
9	284	29
10	240	38
11	305	34
12	245	51

1/7/03 10AM

#7 Possible harness strand breakage

Switch	mV @ Terminal Block	mV @ Switch
1	255	38
2	660	41
3	260	35
4	498	41
5	251	31
6	369	88
7	275	26
8	283	49
9	332	48
10	233	37
11	296	34
12	263	38

1/13/03 2PM

#2,#4,#9 connectors are warm

Switch & Pig	Wire Type	Switch ON Point	Natural Gap	Gap on Failure	Gap w/ 0.005" shim	mV @ Terminal Block	mV @ Switch	
1	Hi-Flux	0.71	0.051	0.028	0.02	211	26	New Poltek 0.710 switches installed at 189430 cycles 2:56 Pm 12/18/2002
2		0.71	0.05	0.031	0.018	272	20	
3	Hi-Flux	0.71	0.05	0.032	0.024	306	26	
4		0.7185	0.052	0.058	0.045	288	27	
5	Hi-Flux	0.7185	0.052	0.054	0.030	197	31	New Poltek 0.710 switches installed at 189450 cycles 2:58 Pm 12/18/2002
6		0.718	0.057	0.045	0.022	271	26	
7		0.71	0.052	0.035	0.02	297	27	
8	Hi-Flux	0.71	0.054	0.035	0.023	210	34	
9		0.71	0.05	0.034	0.022	376	29	
10	Hi-Flux	0.717	0.057	0.049	0.035	194	27	
11		0.717	0.057	0.051	0.044	267	30	
12	Hi-Flux	0.718	0.058	0.050	0.040	189	28	

Less Travel Available -of no length-related -shortened to regular -width contained (for-see 10)	ET- 0P21- 16.36 to 17.00 (over)	ET- 0P21- 16.36 to 17.00 (over)	ET- 0P25-CA 1-0P21- 16.29 to 16.05 (over)	ET- 1P17 & 2P17 - 16.04 to 17.00 (over)					ET- 16.04 to 17.00 (over)						ET- (High A) 16.36-16 to 17.00 (over) (to A) 16.36-16 to 17.00 ET- 0L17	
	W120 in	W120 in		D100 in	D100 in	L120 in	L120 in	1600 in	P100	UP00	P00	P00	P10	P10	16200 in	16200 in
Standard pin			1200													
Partial lower pin																
1.000 inch																
rod to																
rod distance from 1d to 1st																
rod of the																
mounting pin 0-0																
pin length from panel 100 to 100																
mounting distance																
rod distance																
(1) 100 rod to 1st A																
rod and pin A same length																
(2) 100 rod to 1st A																
rod and pin A same length																
(3) 100 rod to 1st A																
rod and pin A same length																
(4) 100 rod to 1st A																
rod and pin A same length																

Less Travel Available -rod to 1st A -rod to 1st A -rod to 1st A -rod to 1st A -rod to 1st A	W120 in	W120 in
rod length from 100 to 100		
rod distance from 100 to 100		

D100 in	D100 in	L120 in	L120 in	1600 in	P100	UP00	P00	P00	P10	P10	16200 in	16200 in
				2.0 degree	1.0 degree							

FORM 800-000 01.18

6T= 18.24/.30 to 17.83 (mm)
4T= 4L1T

Low Travel Analysis: - assume eccentric bushing - assume sheetmetal is negligible - clevis not installed Booster pin Pedal box pin LDM bushing rod id rod distance from id to flat radius of flat mounting pin cd pin length from pedal arm to hole bushing thickness Max angle [deg] offset to create lights on		P221 8x	P221 adj
		18.25-18.23	Same
		2.95-2.95	Same
		25.4 (+/-)	Same
		14.20-14.15	Same
		0.673-0.622	Same

Customer Issue	Extreme 'system is short' based on Tol. w/ Pedal pressed			Acceptable range
Chassis Short = BSI, no fit (no offset)	Chassis System full travel = min rod id to flat + min rod id - max bushing (assuming no offset and radius on flat = 25.4mm)	18.456	Same	18.4023-18.6055
Chassis Short = BSI, no fit (max offset)	Chassis System full travel = min rod id to flat + min rod id - max bushing Max Angular offset which minimize travel (1deg = 4mm ; P150)			18.4023-18.6055
Customer Issue	Extreme 'system is long' based on Tol. w/ Pedal pressed			Acceptable range
Chassis Long = fit on, belt drain	Chassis system full travel = max rod id to flat + max rod id - min bushing (assuming no offset and radius on flat = 25.4mm)	18.608	Same	18.4023-18.6055
Chassis Long = fit on, belt drain (max offset)	Chassis system full travel = max rod id to flat + max rod id - min bushing Max Angular offset which minimize travel (1deg = 4mm ; P150)			18.4023-18.6055

MSAVAS10
30A00

Summary Report from Pollak (Canton) visit of May 13-15, 2003

Day 1: Discussion of ES spec and BOO revision list.

- ES spec : 10mV & 15mA requires equipment capability micro-Volt level for accuracy which is susceptible to noise- equipment not available- particularly for the number of cycles that BOO must endure for continuous monitoring. The 4x4 switch that is produced for Ford is resistor ladder which has different operation currents and voltages and cycles.
- New material on 5 terminal was briefly discussed. Pollak gave assurance that noise would be addressed with new material also should reduce shaving on plunger by the contacts as seen internal to Pollak in testing, etc. Present testing underway to confirm if new material will make switch more robust to last 1.5M cycles (GenII application).
- Forward model system design requires clarification (Meg/Brian):
 - o Module milli-amp (15mA per ES Spec- however OSMY UP207 & P150 requesting to operate at less than 5mA!!!!) Also both platforms are not grounding through the lamp bulbs necessitating a ground terminal in switch which will add complexity for next GEN. Contact force on present design 5T will make 1.5M difficult to meet.
 - o Tow package requirements. Note: all 3 Ford/Pollak specs identify diff't electrical durability parameters; this adds doubt as to what each switch can endure in meeting 1.5M+. Need confirmation from truck that 16A is not excessive.
- Design change#1 for 2 terminals: Spring strength on 2 terminal switches. The springs were received, however the spring strength is on the high side. I've requested that Carl produce prototypes for me to run on vehicles (V229, D186(adn & wgn), U132) to gage if flicker will not occur. Samples are to be representative as follows (or as close as possible):

2 @ 10-12lb w/ make 0.710-0.712	2 @ 10-12lb w/ make 0.713-0.715	2 @ 10-12lb w/ make 0.715-0.718
2 @ 12-14.5lb w/ make 0.710-0.712	2 @ 12-14.5lb w/ make 0.713-0.714	2 @ 10-14.5lb w/ make 0.715-0.718
- This testing should confirm that spring strength change will address field issues with lights on. Incorporate as soon as Aug/Sept timeframe (Post J1) pending cycle testing.
- Design change#1 for 2 terminals: The radius change and plunger overhaul will proceed pending approval timed for Nov- Dec 03CY ...if not frozen due to J2's (MCR) in Dec on most platforms which would push this out to Jan/Feb04CY. DV to be firm'd up asap- defiantly cycle testing with

Day2: Mfg Tour, Lab Tour, other technology & further discussion on GEN II BOO.

- Mfg tour; (see notes)
- MSD Pads and Plugs- Separate cell for build up of plungers for the assembly. No QC check on dimensional of wiper (distance between endpts) after they are staked. Staked parts after passing preliminary assay, are then bulk toted to main assembly line for insertion into body. Assembly line checks for all electrical checks once assembled, but the assembly can (feasibly) pass electrical with a wiper that is 'wet' (due to handling from the build-up cell to the main line). This line is not fully automated so the added check could be inserted as PFMEA improvement. Also operators are doing a visual on grease application- room for improvement (automation- pressure sensing or optical).
- FSOS - synchronous line with electrical checks throughout, end of line tests 30G rmt. Note: Bracket assay cell separate from main line. Brackets assembled after all testing. Automated BOL testing - results are 'soft' and retained on network.
- BOO (2T)- Asynchronous. Bowl feed contacts (new die running recently). Stationary terminal bent on-line w/ gp/no go. Deionizing air. Automated BOL testing - results are 'soft' and retained on network.
- BOO (5T)- Asynchronous. Cavities sorted for optimal circuit performance (1-2, 3-4, 4-5). Bowl feed contacts. Force on cct 1-2 tested. Automated BOL testing - results are 'soft'. ? QC responsible for variable data- is equipment in lab calibrated to mfg equipment?
- BOO (6T/4T)- Synchronous for better control. Bowl feed with ionizing blowoff. Other boos are calibrated on pellet versus probing on non-movable area. Prior to cover assembled mVOLT tested (2T and 5T tested with covers on) Note: 'break' info is starting to be monitored on 6T but not yet controlled. Automated BOL testing - results are 'soft'.
- Door Ajar- ¾ Lines still running close to rate. No forecast (internally) to bring line down (so far). Asynchronous line. Setting of switch is based off of roll of metal housing. Make and height monitored. Force is also checked. Note: Grease terminals first then mV checked afterwards.

- Fuel filler door- Magnets inserted into bag and heat staked into housing. Magnets 'Set' end of line via gauss meter. Automated BOE testing- results are 'soft'.
- NOTE: No time to review PFMEA & DFMEA during this visit.
- QC/Test Lab; tour of equipment. Verified ZT hysteresis is running (60K cycles) however test data not reviewed. DVPR nor DFMEA test data not reviewed during this visit.
- GEN II discussion: Discussion of potential volume pending 'system design' (i.e. hi/lo current and grounding needs) on platforms that would use the new switch; V229, VN127, EN/PN, P150, P131/96, P221, U222/228. Estimated volume for these platforms is over 2Million. Warranty on 6 & 5 terminal fairly low in comparison to 2 Terminal. I expressed that it would be a difficult sell to all platforms with low warranty to convert to new switch which has (1) no warranty history and a new contact design to Ford, (2) potential pc price cost hit and (3) tooling hit. Cost for the GENII proposed to Ford earlier this year has not been confirmed yet.

Alternate options to Pollak GENII proposal:

a) Use new 4 terminal (formerly 6 terminal) as basis for all platforms for 07MY (system architecture need to support (P150)) & tweak plunger and contact to meet 1.5M as well as address other outstanding deviations. Present (5/03) cost of 4 terminal is \$2.02 based on P221, U222/228 volume.

b) Use 5 terminal as basis for platforms and tweak plunger and contact to meet 1.5M as well as address other outstanding deviations. Possibility to remove grid from switch would improve contact force on low terminal in order to meet/exceed 1.5M. Present (5/03) cost of 5 terminal is \$1.43 based on P150/P96/P131 volume.

- Both options would need to be flexible to adapt for strictly high current or low current applications (VN127 & V229). Either set of unused contacts would be 'depopulated' for application and would bring the respective price down for the platforms.

The 2 terminal plng change to shift make range is tooling hit and it is increasing pc price from original price of 0.85 (lo) and 1.04 (hi) to hit 0.10-0.14 more/pc. With added volume on 5 terminal price might be in a respectable ball park?

Forward model info (as discussed during previous day) needs to be confirmed in order to assure appropriate parameters in ES spec and simplify mfg complexity.

-Gen II FMEA as proposed to Ford earlier this year was not reviewed during this visit however Carl identified that it is outlined/nearly complete. S/W used for creation of FMEA is BYTEWORKS not FMEApplus.

- Briefly reviewed new technology using ball effect on pedal.

END.

Brake Lights Off, Pedal Pressed

4
3

1

2

Booster Push Rod	Diameter	16.255	0.025	0.025
Booster Push Rod	Arnif Thickness	2.900	0.050	0.050
Bushing	Thickness	0.648	0.025	0.025
Pedal	Pin Diameter	14.175	0.025	0.025
Switch	As Shipped Plunger Height (with holes applied)			

Channel Component Stack-Up

Interference is the (pin, bushing, arnif) channel component stack-up minus the "as shipped plunger height."

Switch Make Range = (17.93 - 18.24)


Assume bushing to pedal pin gap is collapsed during actuation, and irrelevant when pedal is at rest.

	Minimum	Maximum
Switch Make Distance	17.93	18.24

X
Z
Y

Vehicle Position

Bill Strickland
Core Activation



1003-001 8124

Stack-Up Study - Switch Make Point - Switch Rotated About Pedal Pin Center

0.000 0.250 0.500

Enter Angle of
Relative Part **3.9**

Interference in the pin, bushing, and/or
clevis component stack-up above the
pin slipped plunger height.

Switch Rotation:
Switch rotation about the Z-axis of the vehicle is
limited by the clearance between the switch
mounting holes and the pedal pin. The clearance
between these components ranges from (0.02 -
0.20) mm.

0.25	0.04	0.40
0.40	0.21	0.50

Standard
Metric

Stack-Up Study - Switch Make Point - Switch Rotated About Pedal Pin Center

Enter Angle of Rotation (Deg)	11.23
-------------------------------	-------

Interference to the left, bushing,
level of chassis component stack-up
minus the "as shipped" plunger height.

ROB-099 5126

TYPES OF STOP LAMP SWITCHES

Loss Travel type switches:

- This switch & booster rod are mounted on a pin which extends from the brake pedal.
- When the pedal is pressed, the booster rod moves rearward toward the switch to actuate it within a specified range of movement.
- Single contact & multiple contact switches are used on various applications
- Littefuse and Pollak are the suppliers

Plunger type switches:

- This switch is mounted on a stationary 'flag' on the pedal box and opens the circuit when the target flag moves away from the switch.
- As the brake pedal is pressed, the pedal arm moves toward the engine compartment; the target flag which is mounted on the pedal arm moves away from the switch causing the switch to change state.
- One set of contacts are used with this style of switch.
- Methode is the supplier

Loss Travel/Rod actuated type
Brake On/Off switch:

- **Switch's actuation is dependent on pedal box and booster rod and thus tight tolerancing required.**
- **This switch & booster rod are mounted together on a mounting pin extending from the brake pedal arm.**
- **When the pedal is pressed, the booster rod moves rearward toward the switch to actuate it within a specified range of movement.**
- **Single contact & multiple contact switches are used on various applications**
 - **Littelfuse and Pollak are Ford approved suppliers**

Report Information for Recall ID 72510149: Red

Request Name=134 60 Fee/ies Park problem

Ion=134 60 Fee/ies Park problem

Run Date And Time=17 Jul 2003 17.28

Completion Date And Time=17 Jul 2003 17.30

Job Size=185

Execution Time=2

Pracalc Processing=

Cut Off Date=30 Jun 2003

Load Date=18 Jul 2003

Currency Exchange=6

Generated By=MSAVA G10

Customer Concern Code = DIFFICULT TO OPERATE SHIFT LEVER, CHANGE GEARS[P01, V47], DIFFICULT TO OPERATE SHIFT LEVER[P51, V48]

Cost Category = Region

Model Year = All Vehicle Sold = North / America [NA]

MY_03[2003] Coverages / [1.%, %]

Contractual [NA]

Country Sold / [USA, USA]

Vehicle Line Area = F 650/750[F7]

F160/250LD/ CR CAB[F5]

Part Num Eng Base F250HD/350/ 450/550[F7]

Part Num Eng Base [13480, %]

Report Selection Criteria:	Report Name=Stand List	Model Year=2003, 2002	Dest/ret Ion=DB	Cov Name=CLML 8149	Order By=VIN	Maximum Claims=Un/ Initiated	Logic=Corpo rate	Tie Claims=ALL	Claims With Comments =ALL	Request ed Currenc y=USD	Reported Currency=U SD	Requested Distance=KI ometers	Reported Distance= MI/ice	Description=Ye s	Default Claims (no Date Filters)=Up to current cutoff date
----------------------------	------------------------	-----------------------	-----------------	--------------------	--------------	------------------------------	------------------	----------------	---------------------------	--------------------------	------------------------	-------------------------------	---------------------------	------------------	--

2002	FTW000000000000	211.08	TFY	TF	TBD	TBR	TBR	TBR	TWA	TDE	A1	4-Oct-01	18-Feb-02	TV01	*	14280	*	PO1	1	11-Feb-02	0	5
2002	FTW000000000000	21.44	TFY	TF	TBD	TBR	TBR	TBR	TWA	TDE	AJ	5-Oct-01	20-Oct-01	TV01	F07Z	13480	AA	PO1	42	3-Oct-02	12	26144
2002	FTW000000000000	19.37	TFY	TF	TBD	TBR	TBR	TBR	TVA	TDE	AJ	5-Oct-01	10-Dec-01	TV01	F07Z	13480	AA	PO1	42	10-Jun-03	19	23040
2002	FTW000000000000	20.98	TFY	TF	TBD	TBR	TBR	TBR	TVA	TDE	AJ	5-Oct-01	19-Dec-01	TV01	*	13480	*	PO1	XZ	21-May-03	18	26148
2002	FTW000000000000	26.1	TFY	TF	TBD	TBR	TBR	TBR	TVA	TDE	A1	9-Oct-01	20-Oct-01	TV01	F07Z	13480	AA	PO1	28	20-Aug-02	18	14120
2002	FTW000000000000	08	TFY	TF	TBD	TCD	TRE	TDS	TBR	TBR	A1	7-Oct-01	0-Nov-01	TV01	F07Z	13480	AA	PO1	42	18-Feb-03	15	26070
2002	FTW000000000000	37.2	TFY	TF	TBD	TBR	TBR	TBR	TVA	TDE	AJ	9-Oct-01	29-Oct-01	TV01	F07Z	13480	AA	PO1	46	2-Jun-03	15	26790
2002	FTW000000000000	14.88	TFY	TF	TBD	TBR	TBR	TBR	TVA	TDE	AJ	10-Oct-01	23-Nov-01	TV01	F07Z	13480	AA	PO1	28	13-Apr-02	5	20184
2002	FTW000000000000	44	TFY	TF	TBD	TBR	TBR	TBR	TVA	TDE	AJ	13-Oct-01	26-Feb-02	TV01	*	13480	*	PO1	7	1-Oct-02	6	4461
2002	FTW000000000000	18.11	TFY	TF	TBD	TBR	TBR	TBR	TVA	TDE	AJ	15-Oct-01	3-Jun-02	TV01	F07Z	13480	AA	PO1	42	18-Apr-02	3	1322
2002	FTW000000000000	21.98	TFY	TF	TBD	TBR	TBR	TBR	TVA	TDE	AJ	18-Oct-01	28-Dec-01	TV01	F07Z	13480	AA	PO1	26	5-Mar-01	0	12
2002	FTW000000000000	147.88	TFY	TF	TBD	TCD	TRE	TDS	TBR	TBR	A2	19-Oct-01	9-Nov-01	TV01	F07Z	13480	AA	PO1	42	1-May-03	8	10140
2002	FTW000000000000	19.88	TFY	TF	TBD	TBR	TBR	TBR	TVA	TDE	AJ	22-Oct-01	7-Nov-01	TV01	F07Z	13480	AA	PO1	42	11-Sep-02	11	11580
2002	FTW000000000000	44.71	TFY	TF	TBD	TBR	TBR	TBR	TVA	TDE	AJ	23-Oct-01	15-Dec-01	TV01	F07Z	13480	AA	PO1	1	18-Apr-02	3	7828
2002	FTW000000000000	49.73	TFY	TF	TBD	TBR	TBR	TBR	TVA	TDE	AJ	23-Oct-01	13-Nov-01	TV01	F07Z	13480	AA	PO1	26	7-Mar-03	40	21030
2002	FTW000000000000	34	TFY	TF	TBD	TCD	TRE	TDS	TBR	TBR	A1	25-Oct-01	15-Nov-01	TV01	F07Z	13480	AA	PO1	39	7-Aug-02	6	4988
2002	FTW000000000000	119.18	TFY	TF	TBD	TBR	TBR	TBR	TVA	TDE	A1	24-Oct-01	4-Dec-01	TV01	F07Z	13480	AA	PO1	42	10-Apr-02	6	13134
2002	FTW000000000000	52.14	TFY	TF	TBD	TBR	TBR	TBR	TVA	TDE	A1	27-Oct-01	18-Nov-01	TV01	F07Z	13480	AA	PO1	28	27-Mar-03	17	18038
2002	FTW000000000000	31.3	TFY	TF	TBD	TBR	TBR	TBR	TVA	TDE	A1	27-Oct-01	5-Nov-01	TV01	F07Z	13480	AA	PO1	42	11-May-02	7	13340
2002	FTW000000000000	23.4	TFY	TF	TBD	TBR	TBR	TBR	TVA	TDE	A1	31-Oct-01	8-Nov-01	TV01	F07Z	13480	AA	PO1	42	24-Jul-02	3	18903
2002	FTW000000000000	65.84	TFY	TF	TBD	TBR	TBR	TBR	TVA	TDE	AJ	8-Nov-01	3-Dec-01	TV01	F07Z	13480	AA	PO1	1	21-Feb-03	65	17108
2002	FTW000000000000	108.6	TFY	TF	TBD	TCD	TRE	TDS	TBR	TBR	A1	7-Nov-01	3-Jan-02	TV01	F07Z	13480	AA	PO1	48	13-Dec-02	7	18840
2002	FTW000000000000	23.84	TFY	TF	TBD	TBR	TBR	TBR	TVA	TDE	AR	7-Nov-01	14-May-02	TV01	F07Z	13480	AA	PO1	26	22-Oct-02	6	4987
2002	FTW000000000000	67.6	TFY	TF	TBD	TBR	TBR	TBR	TVA	TDE	A1	7-Nov-01	4-Dec-01	TV01	F07Z	13480	AA	PO1	42	18-Dec-01	1	548
2002	FTW000000000000	40.88	TFY	TF	TBD	TBR	TBR	TBR	TVA	TDE	A1	7-Nov-01	23-Nov-01	TV01	*	13480	*	PO1	1	11-Nov-02	12	26230
2002	FTW000000000000	374.68	TFY	TF	TBD	TBR	TBR	TBR	TVA	TDE	A4	8-Nov-01	29-Dec-01	TV01	F07Z	13480	AA	PO1	42	10-Jul-02	7	12830
2002	FTW000000000000	21.91	TFY	TF	TBD	TBR	TBR	TBR	TVA	TDE	AJ	14-Nov-01	8-Dec-01	TV01	*	13480	*	PO1	XZ	21-Jan-02	2	1008
2002	FTW000000000000	67.90	TFY	TF	TBD	TBR	TBR	TBR	TVA	TDE	A1	15-Nov-01	13-May-02	TV01	F07Z	13480	AA	PO1	42	13-Sep-02	7	16740
2002	FTW000000000000	77.89	TFY	TF	TBD	TBR	TBR	TBR	TVA	TDE	A1	18-Nov-01	21-Dec-01	TV01	F07Z	13480	AA	PO1	42	16-Jul-02	7	33270
2002	FTW000000000000	24.89	TFY	TF	TBD	TBR	TBR	TBR	TVA	TDE	A1	21-Nov-01	4-Dec-01	TV01	F07Z	13480	AA	PO1	42	10-Jan-03	14	13247
2002	FTW000000000000	87.6	TFY	TF	TBD	TBR	TBR	TBR	TVA	TDE	AJ	27-Nov-01	12-Dec-01	TV01	F07Z	13480	AA	PO1	42	16-Jan-03	13	24718
2002	FTW000000000000	11.01	TFY	TF	TBD	TBR	TBR	TBR	TVA	TDE	A4	13-Dec-01	20-Jan-02	TV01	*	13480	*	PO1	42	11-Feb-02	1	683
2002	FTW000000000000	68.23	TFY	TF	TBD	TBR	TBR	TBR	TVA	TDE	AJ	13-Dec-01	13-May-02	TV01	F07Z	13480	AA	PO1	26	29-Mar-02	7	16738
2002	FTW000000000000	187.3	TFY	TF	TBD	TCD	TRE	TDS	TBR	TBR	A1	14-Dec-01	3-Jan-02	TV01	F07Z	13480	AA	PO1	48	18-Dec-02	12	26144
2002	FTW000000000000	283.11	TFY	TF	TBD	TCD	TRE	TDS	TBR	TBR	A1	17-Dec-01	31-Dec-01	TV01	F07Z	13480	AA	PO1	42	14-Mar-03	18	18532
2002	FTW000000000000	36.44	TFY	TF	TBD	TCD	TRE	TDS	TBR	TBR	A1	17-Dec-01	28-Dec-01	TV01	F07Z	13480	AA	PO1	41	8-May-02	8	4988
2002	FTW000000000000	87.24	TFY	TF	TBD	TBR	TBR	TBR	TVA	TDE	A1	21-Dec-01	10-Jan-02	TV01	F07Z	13480	AA	PO1	26	7-May-02	10	15281
2002	FTW000000000000	114.08	TFY	TF	TBD	TBR	TBR	TBR	TVA	TDE	A1	21-Dec-01	18-Jan-02	TV01	F07Z	13480	AA	PO1	42	29-Jul-02	7	8983
2002	FTW000000000000	117.3	TFY	TF	TBD	TCD	TRE	TDS	TBR	TBR	A1	4-Jan-02	22-Jan-02	TV01	F07Z	13480	AA	PO1	42	14-Aug-02	7	18228
2002	FTW000000000000	189.7	TFY	TF	TBD	TBR	TBR	TBR	TVA	TDE	AR	17-Jan-02	18-Apr-02	TV01	F07Z	13480	AA	PO1	42	8-Jul-02	3	8548
2002	FTW000000000000	186.14	TFY	TF	TBD	TCD	TRE	TDS	TBR	TBR	A1	24-Jan-02	1-Mar-02	TV01	F07Z	13480	AA	PO1	1	16-Sep-02	7	16607
2002	FTW000000000000	83.8	TFY	TF	TBD	TBR	TBR	TBR	TVA	TDE	A1	26-Jan-02	18-Mar-02	TV01	F07Z	13480	AA	PO1	42	3-Mar-03	12	27078
2002	FTW000000000000	54.4	TFY	TF	TBD	TBR	TBR	TBR	TVA	TDE	AR	8-Feb-02	22-Feb-02	TV01	F07Z	13480	AA	PO1	42	23-Aug-02	7	5974
2002	FTW000000000000	87.81	TFY	TF	TBD	TBR	TBR	TBR	TVA	TDE	AJ	26-Feb-02	14-Jun-02	TV01	F07Z	13480	AA	PO1	42	23-Oct-02	8	9188
2002	FTW000000000000	57.51	TFY	TF	TBD	TBR	TBR	TBR	TVA	TDE	AJ	29-Feb-02	14-Jun-02	TV01	F07Z	13480	AA	PO1	42	26-Dec-02	7	12939
2002	FTW000000000000	80.01	TFY	TF	TBD	TCD	TRE	TDS	TBR	TBR	A1	28-Feb-02	15-Mar-02	TV01	F07Z	13480	AA	PO1	42	12-Mar-02	6	3
2002	FTW000000000000	85.8	TFY	TF	TBD	TCD	TRE	TDS	TBR	TBR	A1	28-Feb-02	28-Mar-02	TV01	F07Z	13480	AA	PO1	42	25-Dec-02	10	16206
2002	FTW000000000000	26.44	TFY	TF	TBD	TBR	TBR	TBR	TVA	TDE	AJ	8-Mar-02	18-Apr-02	TV01	F07Z	13480	AA	PO1	42	8-Aug-02	4	22084
2002	FTW000000000000	20.63	TFY	TF	TBD	TBR	TBR	TBR	TVA	TDE	AJ	8-Mar-02	14-Dec-02	TV01	F07Z	13480	AA	PO1	42	7-Oct-02	6	21
2002	FTW000000000000	37	TFY	TF	TBD	TBR	TBR	TBR	TVA	TDE	A1	11-Mar-02	10-Mar-02	TV01	*	13480	*	PO1	28	27-Sep-02	7	16898
2002	FTW000000000000	81.59	TFY	TF	TBD	TBR	TBR	TBR	TVA	TDE	A1	11-Mar-02	4-Apr-02	TV01	F07Z	13480	AA	PO1	42	16-Jul-02	4	4082
2002	FTW000000000000	34.82	TFY	TF	TBD	TBR	TBR	TBR	TVA	TDE	A1	11-Mar-02	20-Mar-02	TV01	F07Z	13480	AA	PO1	42	3-Oct-02	7	11488
2002	FTW000000000000	47.28	TFY	TF	TBD	TBR	TBR	TBR	TVA	TDE	A1	12-Mar-02	6-May-02	TV01	F07Z	13480	AA	PO1	26	2-Jun-03	7	15771
2002	FTW000000000000	37.71	TFY	TF	TBD	TBR	TBR	TBR	TVA	TDE	AJ	20-Mar-02	4-May-02	TV01	F07Z	13480	AA	PO1	42	6-Mar-03	11	9018
2002	FTW000000000000	15.88	TFY	TF	TBD	TCD	TRE	TDS	TBR	TBR	A1	21-Mar-02	23-Apr-02	TV01	F07Z	13480	AA	PO1	26	29-Jun-02	2	4280
2002	FTW000000000000	17.24	TFY	TF	TBD	TCD	TRE	TDS	TBR	TBR	A1	22-Mar-02	28-Mar-02	TV01	F07Z	13480	AA	PO1	42	8-Mar-02	8	24782
2002	FTW000000000000	14.88	TFY	TF	TBD	TBR	TBR	TBR	TVA	TDE	AJ	23-Mar-02	29-Mar-02	TV01	F07Z	13480	AA	PO1	26	19-Nov-02	6	9530
2002	FTW000000000000	55.1	TFY	TF	TBD	TBR	TBR	TBR	TVA	TDE	A4	25-Mar-02	1-Jul-02	TV01	F07Z	13480	AA	PO1	42	5-Jun-03	12	11058
2002	FTW000000000000	18.88	TFY	TF	TBD	TBR	TBR	TBR	TVA	TDE	A4	11-Apr-02	10-Jun-02	TV01	F07Z	13480	AA	PO1	26	26-Dec-02	7	5741
2002	FTW000000000000	22.5	TFY	TF	TBD	TBR	TBR	TBR	TVA	TDE	A1	16-Apr-02	9-Jul-02	TV01	F07Z	13480	AA	PO1	41	5-Aug-02	1	823
2002	FTW000000000000	386.8	TFY	TF	TBD	TBR	TBR	TBR	TVA	TDE	AR	23-Apr-02	29-Apr-02	TV01	F07Z	13480	AA	PO1	42	17-Jan-03	6	11212
2002	FTW000000000000	52.78	TFY	TF	TBD	TCD	TRE	TDS	TBR	TBR	A1	27-Apr-02	25-Nov-02	TV01	*	13480	*	PO1	42	15-Jun-03	7	9488

2002	1FTWACHLASED0000	87.94	TF7	TF	TBD	TCD	TE	TAZ	TDB	A1	27-Aug-02	28-Nov-02	7/01	FBZ	13480	AA	FB1	42	25-Jan-03	8	8891
2002	1FTWACTHACB0000	86.48	TF8	TF	TBD	TAM	TE	TALY	TDU	AR	28-Aug-02	8-Jul-02	7/01	FBZ	13480	AA	FB1	46	8-Aug-02	2	3813
2002	1FTWAZ2F02ED0002	80.11	TF7	TF	TBC	TBD	TE	TDB	TDB	A1	24-May-02	22-May-02	7/01	FBZ	13480	AA	FB1	X1	8-Aug-02	3	7304
2002	1FTWAZ2F02ED0008	80.5	TF7	TF	TBC	TBD	TE	TABA	TDB	A1	4-May-02	13-Jun-02	7/01	FBZ	13480	AA	FB1	46	28-Aug-02	3	8548
2002	2FTWAZ2F02ED0007	84.26	TF8	TF	TBD	TAM	TE	TAZ	TDU	A4	25-May-02	27-Jul-02	7/01	FBZ	13480	AA	FB1	20	29-Jul-02	1	437
2002	1FDAP5F02ED0004	88.78	TF7	TF	TBD	TES	TE	TDS	TDB	A1	15-May-02	3-Oct-02	7/01	FBZ	13480	AA	FB1	42	12-Feb-03	5	3725
2002	1FTWAZ2F02ED0008	86.37	TF7	TF	TBC	TBD	TE	TDB	TDB	A1	29-May-02	30-Jun-02	7/01	FBZ	13480	AA	FB1	42	7-Jan-03	12	21436
2002	1FTWAZ2F02ED0007	14	TF6	TF	TBC	TAM	TE	TAZ	TDU	AJ	20-May-02	23-Jul-02	7/01	*	13480	*	FB1	42	20-May-03	11	12871
2002	1FTWAZ2F02ED0008	100.78	TF7	TF	TBC	TBD	TE	TDS	TDB	A1	29-May-02	3-Sep-02	7/01	FBZ	13480	AA	FB1	41	10-Sep-02	1	898
2002	1FTWAZ2F02ED0004	89.32	TF6	TF	TBC	TAM	TE	TAZ	TDU	AJ	29-May-02	11-Sep-02	7/01	FBZ	13480	AA	FB1	42	28-Jul-02	0	23
2002	1FTWAZ2F02ED0004	21.45	TF7	TF	TBD	TCD	TE	TDB	TDB	A1	20-May-02	14-Jun-02	7/01	FBZ	13480	AA	FB1	29	26-Sep-02	4	7301
2002	1FTWAZ2F02ED0008	102.24	TF7	TF	TBC	TBD	TE	TDB	TDB	A1	1-Jun-02	8-Jul-02	8/03	FBZ	XZ718	A	FB1	42	8-Jul-02	1	97
2002	1FTWAZ2F02ED0002	18.82	TF7	TF	TBD	TCD	TE	TDS	TDB	A1	2-Jun-02	25-Jun-02	7/01	FBZ	13480	AA	FB1	42	14-Aug-02	2	4227
2002	1FTWAZ2F02ED0008	22.39	TF7	TF	TBC	TCD	TE	TDB	TDB	A1	3-Jun-02	29-Sep-02	7/01	FBZ	13480	AA	FB1	42	17-Apr-03	7	19888
2002	1FTWAZ2F02ED0002	48.29	TF7	TF	TBC	TCD	TE	TDB	TDB	A1	3-Jun-02	19-Jul-02	7/01	FBZ	13480	AA	FB1	29	27-May-02	2	8376
2002	1FTWAZ2F02ED0008	18.76	TF7	TF	TBC	TCD	TE	TDB	TDB	A1	3-Jun-02	14-Jun-02	7/01	FBZ	13480	AA	FB1	42	21-Aug-02	3	4371
2002	1FTWAZ2F02ED0008	58	TF7	TF	TBD	TCD	TE	TMA	TDB	A1	3-Jun-02	10-Jun-02	7/01	FBZ	13480	AA	FB1	42	30-Apr-02	11	1244
2002	2FTWAZ2F02ED0008	138.88	TF3	TF	TBD	TAM	TE	TAM	TDU	A4	4-Jun-02	27-Jun-02	7/01	FBZ	13480	AA	FB1	48	8-Dec-02	8	11868
2002	2FTWAZ2F02ED0008	22.78	TF8	TF	TBD	TAM	TE	TAM	TDU	A4	4-Jun-02	20-Sep-02	7/01	FBZ	13480	AA	FB1	42	10-Jul-02	0	7
2002	2FTWAZ2F02ED0008	18.39	TF8	TF	TBD	TAM	TE	TAZ	TDU	A4	4-Jun-02	1-Aug-02	7/01	FBZ	13480	AA	FB1	42	19-Jul-02	0	11
2002	1FTWAZ2F02ED0002	37.39	TF7	TF	TBD	TCD	TE	TMA	TDB	A1	4-Jun-02	4-Jun-02	7/01	FBZ	13480	AA	FB1	X1	20-Jun-02	8	126
2002	1FTWAZ2F02ED0008	88.81	TF7	TF	TBC	TBD	TE	TDS	TDB	A1	4-Jun-02	6-Sep-02	7/01	FBZ	13480	AA	FB1	42	30-Oct-02	2	8672
2002	1FTWAZ2F02ED0007	22.89	TF7	TF	TBD	TCD	TE	TAZ	TDB	A1	4-Jun-02	8-Aug-02	7/01	*	13480	*	FB1	41	27-Nov-02	4	8383
2002	1FTWAZ2F02ED0008	18.43	TF3	TF	TBD	TAM	TE	TAZ	TDU	AR	8-Jun-02	21-Jun-02	7/01	FBZ	13480	AA	FB1	28	9-Sep-02	3	817
2002	1FTWAZ2F02ED0008	18.82	TF8	TF	TBC	TAM	TE	TAZ	TDU	AJ	8-Jun-02	16-Jul-02	7/01	*	13480	*	FB1	42	12-Aug-02	1	1430
2002	1FTWAZ2F02ED0008	114.81	TF5	TF	TBD	TAM	TE	TAZ	TDU	AR	7-Jun-02	3-Sep-02	7/01	*	13480	*	FB1	28	26-Jul-02	8	32
2002	1FTWAZ2F02ED0008	54.29	TF8	TF	TBD	TAM	TE	TAM	TDU	AR	8-Jun-02	16-Jul-02	7/01	FBZ	13480	AA	FB1	42	22-Jul-02	1	277
2002	1FTWAZ2F02ED0008	51.74	TF3	TF	TBD	TAM	TE	TAM	TDU	AR	8-Jun-02	20-Jun-02	7/01	FBZ	13480	AA	FB1	42	20-Jun-02	8	84
2002	1FTWAZ2F02ED0008	21.71	TF7	TF	TBC	TBD	TE	TDB	TDB	A1	8-Jun-02	1-Aug-02	7/01	FBZ	13480	AA	FB1	42	8-Jun-02	11	20184
2002	1FTWAZ2F02ED0008	98.9	TF7	TF	TBC	TCD	TE	TDS	TDB	A1	8-Jun-02	10-Aug-02	7/01	FBZ	13480	AA	FB1	42	14-Aug-02	1	302
2002	1FTWAZ2F02ED0008	88.21	TF7	TF	TBC	TCD	TE	TDS	TDB	A1	12-Jun-02	31-Jul-02	7/01	FBZ	13480	AA	FB1	29	20-Jul-02	0	84
2002	1FTWAZ2F02ED0008	16.8	TF8	TF	TBD	TAM	TE	TAZ	TDU	AR	12-Jun-02	5-Jul-02	7/01	FBZ	13480	AA	FB1	28	19-Feb-03	8	11181
2002	1FTWAZ2F02ED0008	89.73	TF7	TF	TBD	TCD	TE	TDB	TDB	A1	13-Jun-02	3-Sep-02	7/01	FBZ	13480	AA	FB1	28	20-Jun-02	5	3833
2002	1FTWAZ2F02ED0008	87.18	TF7	TF	TBC	TBD	TE	TDB	TDB	A1	12-Jun-02	28-Sep-02	7/01	FBZ	13480	AA	FB1	28	2-Oct-02	1	282
2002	1FTWAZ2F02ED0008	22.4	TF7	TF	TBC	TBD	TE	TDS	TDB	A1	12-Jun-02	21-Aug-02	7/01	FBZ	13480	AA	FB1	42	1-Aug-02	0	208
2002	1FTWAZ2F02ED0008	84.08	TF8	TF	TBC	TAM	TE	TAZ	TDU	AJ	14-Jun-02	29-Oct-02	7/01	FBZ	13480	AA	FB1	42	6-Aug-02	0	428
2002	1FTWAZ2F02ED0008	20.21	TF8	TF	TBC	TAM	TE	TAZ	TDU	AJ	17-Jun-02	29-Sep-02	7/01	FBZ	13480	AA	FB1	1	18-Sep-02	0	18
2002	1FTWAZ2F02ED0008	31.8	TF8	TF	TBC	TAM	TE	TAZ	TDU	AJ	18-Jun-02	12-Oct-02	7/01	*	13480	*	FB1	28	14-Apr-03	7	6917
2002	1FTWAZ2F02ED0008	74.83	TF7	TF	TBC	TBD	TE	TDS	TDB	A1	28-Jun-02	31-Aug-02	7/01	FBZ	13480	AA	FB1	42	28-Jun-02	10	8788
2002	1FTWAZ2F02ED0008	49.39	TF8	TF	TBD	TAM	TE	TAZ	TDB	AR	28-Jun-02	17-Jul-02	7/01	FBZ	13480	AA	FB1	42	29-Aug-02	2	29282
2002	1FTWAZ2F02ED0008	19.8	TF7	TF	TBD	TBD	TE	TDS	TDB	A1	29-Jun-02	11-Jul-02	7/01	FBZ	13480	AA	FB1	42	8-Jun-02	8	8851
2002	1FTWAZ2F02ED0008	21.88	TF7	TF	TBC	TBD	TE	TDB	TDB	A1	18-Jul-02	6-Dec-02	7/01	FBZ	13480	AA	FB1	42	15-Aug-02	0	188
2002	1FTWAZ2F02ED0008	22.33	TF6	TF	TBD	TAM	TE	TAM	TDU	AJ	17-Jul-02	3-Aug-02	7/01	FBZ	13480	AA	FB1	28	28-May-02	80	8834
2002	1FTWAZ2F02ED0008	88	TF8	TF	TBC	TAM	TE	TAZ	TDU	AJ	17-Jul-02	29-Aug-02	7/01	FBZ	13480	AA	FB1	28	29-Aug-02	0	21
2002	1FTWAZ2F02ED0008	22.85	TF6	TF	TBC	TAM	TE	TAZ	TDU	AJ	18-Jul-02	28-Jul-02	7/01	FBZ	13480	AA	FB1	42	12-Apr-03	8	11718
2002	1FTWAZ2F02ED0008	83.88	TF7	TF	TBC	TCD	TE	TDB	TDB	A1	18-Jul-02	19-Oct-02	7/01	*	13480	*	FB1	42	21-Nov-02	2	1827
2002	1FTWAZ2F02ED0008	88.98	TF7	TF	TBC	TBD	TE	TDB	TDB	A1	18-Jul-02	14-Dec-02	7/01	FBZ	13480	AA	FB1	28	3-Sep-02	0	37
2002	1FTWAZ2F02ED0008	88.43	TF3	TF	TBC	TAM	TE	TAZ	TDU	AJ	19-Jul-02	31-Oct-02	7/01	FBZ	13480	AA	FB1	41	21-Oct-02	0	124
2002	1FTWAZ2F02ED0008	47.87	TF8	TF	TBC	TAM	TE	TAZ	TDU	AJ	22-Jul-02	12-Oct-02	7/01	FBZ	13480	AA	FB1	28	20-Mar-02	8	5813
2002	1FTWAZ2F02ED0008	47.9	TF7	TF	TBC	TCD	TE	TDS	TDB	A1	22-Jul-02	8-Sep-02	7/01	FBZ	13480	AA	FB1	42	8-Sep-02	0	37
2002	1FTWAZ2F02ED0008	41.8	TF7	TF	TBC	TCD	TE	TDB	TDB	A1	22-Jul-02	11-Oct-02	7/01	FBZ	13480	AA	FB1	42	14-Oct-02	1	213
2002	1FTWAZ2F02ED0008	88.87	TF7	TF	TBD	TBD	TE	TDS	TDB	A1	22-Jul-02	9-Oct-02	7/01	FBZ	13480	AA	FB1	42	18-Apr-03	7	8858
2002	1FTWAZ2F02ED0008	13.87	TF7	TF	TBC	TBD	TE	TDB	TDB	A1	22-Jul-02	30-Sep-02	7/01	FBZ	13480	AA	FB1	42	20-Mar-03	8	9113
2002	1FTWAZ2F02ED0008	88.94	TF7	TF	TBC	TBD	TE	TDS	TDB	A1	22-Jul-02	8-Sep-02	7/01	FBZ	13480	AA	FB1	41	8-Nov-02	2	3307
2002	1FTWAZ2F02ED0008	28.24	TF5	TF	TBD	TAM	TE	TAM	TDU	AR	22-Jul-02	9-Oct-02	7/01	FBZ	13480	AA	FB1	42	23-May-03	8	20878
2002	1FTWAZ2F02ED0008	88.9	TF8	TF	TBC	TAM	TE	TAZ	TDU	AJ	22-Jul-02	27-Aug-02	7/01	*	13480	*	FB1	42	21-Jul-02	0	3
2002	1FTWAZ2F02ED0008	27.85	TF3	TF	TBC	TAM	TE	TAZ	TDU	AJ	22-Jul-02	15-Dec-02	7/01	*	13480	*	FB1	X2	22-Aug-02	0	210
2002	1FTWAZ2F02ED0008	72.85	TF7	TF	TBC	TCD	TE	TDS	TDB	A1	22-Jul-02	7-Jun-02	7/01	FBZ	13480	AA	FB1	42	22-May-03	8	9836
2002	1FTWAZ2F02ED0008	48.3	TF7	TF	TBD	TCD	TE	TAZ	TDB	A1	22-Jul-02	28-Sep-02	7/01	FBZ	13480	AA	FB1	42	5-Aug-02	0	12
2002	1FTWAZ2F02ED0008	23.7	TF7	TF	TBC	TBD	TE	TMA	TDB	A1	22-Jul-02	12-Dec-02	7/01	FBZ	13480	AA	FB1	42	10-Dec-02	0	19
2002	1FTWAZ2F02ED0008	41.39	TF7	TF	TBC	TBD	TE	TDB	TDB	A1	22-Jul-02	19-Dec-02	7/01	FBZ	13480	AA	FB1	42	18-Jan-03	2	3118
2002	2FTWAZ2F02ED0008	32.13	TF5	TF	TBD	TAM	TE	TAZ	TDU	A4	28-Jul-02	11-Dec-02	7/01	FBZ	13480	AA	FB1	48	6-Sep-02	0	28

2902	FTTR0118L3CA06188	14.88 TFS	TF	TBD	TAM	TE	TWZ	TDU	A4	25-Jul-02	23-Sep-02	T601	F87Z	13480 AA	P01	42	20-Feb-03	8	8228
2902	FTTR0118L3CA06188	14.88 TFS	TF	TBD	TAM	TE	TWZ	TDU	AJ	25-Jul-02	23-Sep-02	T601	F87Z	13480 AA	P01	28	14-Aug-02	1	178
2902	FTTR0118L3CA06188	72.88 TFS	TF	TBD	TAM	TE	TWZ	TDU	AJ	29-Jul-02	23-Aug-02	T601	F87Z	13480 AA	P01	28	3-Oct-02	2	3334
2903	FTTR0118L3CA06188	57.17 TFS	TF	TBD	TAM	TE	TWZ	TDU	A4	26-Jul-02	14-Sep-02	T601	F87Z	13480 AA	P01	42	29-Nov-02	3	2912
2903	FTTR0118L3CA06188	98.87 TFS	TF	TBD	TAM	TE	TWZ	TDU	A1	26-Jul-02	18-Aug-02	T601	F87Z	13480 AA	P01	42	8-Nov-02	3	4183
2903	FTTR0118L3CA06188	123.04 TFS	TF	TBD	TAM	TE	TWZ	TDU	A4	26-Jul-02	18-Sep-02	T601	F87Z	13480 AA	P01	42	18-Dec-02	4	3586
2902	FTTR0118L3CA06188	157.15 TFS	TF	TBD	TAM	TE	TWZ	TDU	A4	1-Aug-02	7-Sep-02	T601	F87Z	13480 AA	P01	42	4-Oct-02	1	2026
2902	FTTR0118L3CA06188	87.1 TFS	TF	TBD	TAM	TE	TWZ	TDU	AJ	2-Aug-02	1-Sep-02	T601	F87Z	13480 AA	P01	29	8-May-03	0	1743
2902	FTTR0118L3CA06188	21 TFS	TF	TBD	TAM	TE	TWZ	TDU	AJ	6-Aug-02	6-Aug-02	T601	F87Z	13480 AA	P01	29	5-Sep-02	2	2919
2903	FTTR0118L3CA06188	18.8 TFS	TF	TBD	TAM	TE	TWZ	TDU	AR	8-Aug-02	28-Dec-02	T601	F87Z	13480 AA	P01	42	17-Mar-03	3	2295
2905	FTTR0118L3CA06188	17.62 TFS	TF	TBD	TAM	TE	TWZ	TDU	A1	5-Aug-02	23-Aug-02	T601	F87Z	13480 AA	P01	42	23-Mar-02	4	5872
2902	FTTR0118L3CA06188	88.18 TFS	TF	TBD	TAM	TE	TWZ	TDU	A4	6-Aug-02	3-Oct-02	T601	F87Z	13480 AA	P01	29	18-Apr-03	7	2809
2902	FTTR0118L3CA06188	23.12 TFS	TF	TBD	TAM	TE	TWZ	TDU	AJ	6-Aug-02	18-Sep-02	T601	F87Z	13480 AA	P01	42	25-Mar-03	7	3910
2903	FTTR0118L3CA06188	45.38 TFS	TF	TBD	TAM	TE	TWZ	TDU	AJ	7-Aug-02	24-Sep-02	T601	F87Z	13480 AA	P01	42	13-Nov-02	2	2971
2902	FTTR0118L3CA06188	25.28 TFS	TF	TBD	TAM	TE	TWZ	TDU	AJ	7-Aug-02	20-Sep-02	T601	F87Z	13480 AA	P01	42	15-Aug-03	0	5
2903	FTTR0118L3CA06188	20.81 TFS	TF	TBD	TAM	TE	TWZ	TDU	A1	7-Aug-02	15-Aug-02	T601	F87Z	13480 AA	P01	41	22-Aug-02	1	308
2902	FTTR0118L3CA06188	22.29 TFS	TF	TBD	TAM	TE	TWZ	TDU	AJ	8-Aug-02	23-Nov-02	T601	F87Z	13480 AA	P01	42	13-Feb-03	3	2769
2903	FTTR0118L3CA06188	181.79 TFS	TF	TBD	TAM	TE	TWZ	TDU	AJ	8-Aug-02	24-Oct-02	T601	F87Z	13480 AA	P01	42	9-Oct-02	0	8
2902	FTTR0118L3CA06188	58.9 TFS	TF	TBD	TAM	TE	TWZ	TDU	AJ	8-Aug-02	8-Sep-02	T601	F87Z	13480 AA	P01	28	18-Mar-03	7	1188
2903	FTTR0118L3CA06188	68.87 TFS	TF	TBD	TAM	TE	TWZ	TDU	AJ	8-Aug-02	18-Sep-02	T601	F87Z	13480 AA	P01	42	14-May-03	8	17023
2903	FTTR0118L3CA06188	60.5 TFS	TF	TBD	TAM	TE	TWZ	TDU	AR	8-Aug-02	23-Feb-03	T601	F87Z	13480 AA	P01	42	20-May-03	3	16932
2903	FTTR0118L3CA06188	34.77 TFS	TF	TBD	TAM	TE	TWZ	TDU	A4	12-Aug-02	27-Aug-02	T601	F87Z	13480 AA	P01	42	7-Apr-03	8	16983
2903	FTTR0118L3CA06188	84.77 TFS	TF	TBD	TAM	TE	TWZ	TDU	A4	12-Aug-02	27-Aug-02	T601	F87Z	13480 AA	P01	42	18-Jan-03	10	21242
2903	FTTR0118L3CA06188	83.89 TFS	TF	TBD	TAM	TE	TWZ	TDU	AJ	12-Aug-02	23-Aug-02	T601	F87Z	13480 AA	P01	35	28-Aug-02	5	327
2903	FTTR0118L3CA06188	124.6 TFS	TF	TBD	TAM	TE	TWZ	TDU	A4	12-Aug-02	6-Oct-02	T601	F87Z	13480 AA	P01	29	20-Apr-03	7	6876
2903	FTTR0118L3CA06188	42.84 TFS	TF	TBD	TAM	TE	TWZ	TDU	AJ	14-Aug-02	28-Aug-02	T601	F87Z	13480 AA	P01	42	3-May-03	9	16748
2905	FTTR0118L3CA06188	43.2 TFS	TF	TBD	TAM	TE	TWZ	TDU	A1	14-Aug-02	1-Oct-02	T601	F87Z	13480 AA	P01	42	3-Oct-02	1	1417
2903	FTTR0118L3CA06188	88.79 TFS	TF	TBD	TAM	TE	TWZ	TDU	AJ	18-Aug-02	27-Nov-02	T601	F87Z	13480 AA	P01	42	20-Feb-03	4	6930
2903	FTTR0118L3CA06188	18.07 TFS	TF	TBD	TAM	TE	TWZ	TDU	AJ	18-Aug-02	28-Aug-02	T601	F87Z	13480 AA	P01	42	21-Aug-02	0	0
2903	FTTR0118L3CA06188	22.4 TFS	TF	TBD	TAM	TE	TWZ	TDU	AJ	18-Aug-02	12-Mar-03	T601	F87Z	13480 AA	P01	33	31-Mar-03	1	612
2903	FTTR0118L3CA06188	18.06 TFS	TF	TBD	TAM	TE	TWZ	TDU	AJ	18-Aug-02	16-Sep-02	T601	F87Z	13480 AA	P01	42	1-May-03	5	4728
2905	FTTR0118L3CA06188	13.26 TFS	TF	TBD	TAM	TE	TWZ	TDU	AJ	18-Aug-02	8-Jul-03	T601	F87Z	13480 AA	P01	33	16-Oct-02	0	25
2905	FTTR0118L3CA06188	18.29 TFS	TF	TBD	TAM	TE	TWZ	TDU	A4	20-Aug-02	24-Oct-02	T601	F87Z	13480 AA	P01	42	11-Nov-02	1	1859
2905	FTTR0118L3CA06188	88.3 TFS	TF	TBD	TAM	TE	TWZ	TDU	AR	20-Aug-02	28-Oct-02	T601	F87Z	13480 AA	P01	29	5-Sep-02	0	13
2905	FTTR0118L3CA06188	49.4 TFS	TF	TBD	TAM	TE	TWZ	TDU	AR	20-Aug-02	10-Sep-02	T601	F87Z	13480 AA	P01	42	11-Sep-02	1	94
2905	FTTR0118L3CA06188	81.2 TFS	TF	TBD	TAM	TE	TWZ	TDU	AR	21-Aug-02	2-Jan-03	T601	F87Z	13480 AA	P01	29	8-Oct-02	0	16
2903	FTTR0118L3CA06188	43.84 TFS	TF	TBD	TAM	TE	TWZ	TDU	AR	21-Aug-02	17-Mar-03	T601	F87Z	13480 AA	P01	42	28-Oct-02	0	58
2903	FTTR0118L3CA06188	29.25 TFS	TF	TBD	TAM	TE	TWZ	TDU	AR	21-Aug-02	28-Oct-02	T601	F87Z	13480 AA	P01	33	19-Nov-02	1	430
2903	FTTR0118L3CA06188	16.18 TFS	TF	TBD	TAM	TE	TWZ	TDU	A1	22-Aug-02	9-Sep-02	T601	F87Z	13480 AA	P01	42	17-Apr-03	8	6857
2903	FTTR0118L3CA06188	33.48 TFS	TF	TBD	TAM	TE	TWZ	TDU	AJ	23-Aug-02	28-Sep-02	T601	F87Z	13480 AA	P01	29	10-Apr-03	7	2782
2903	FTTR0118L3CA06188	80.3 TFS	TF	TBD	TAM	TE	TWZ	TDU	AR	25-Aug-02	23-Jan-03	T601	F87Z	13480 AA	P01	42	17-Apr-03	3	3636
2903	FTTR0118L3CA06188	20.83 TFS	TF	TBD	TAM	TE	TWZ	TDU	AR	28-Aug-02	8-Oct-02	T601	F87Z	13480 AA	P01	42	8-Jun-03	4	5421
2903	FTTR0118L3CA06188	51.29 TFS	TF	TBD	TAM	TE	TWZ	TDU	A4	27-Aug-02	13-Oct-02	T601	F87Z	13480 AA	P01	42	28-Mar-03	6	11844
2903	FTTR0118L3CA06188	38.9 TFS	TF	TBD	TAM	TE	TWZ	TDU	A4	27-Aug-02	12-Oct-02	T601	F87Z	13480 AA	P01	42	5-Jun-03	9	17837
2903	FTTR0118L3CA06188	16.85 TFS	TF	TBD	TAM	TE	TWZ	TDU	A4	27-Aug-02	6-Jan-03	T601	F87Z	13480 AA	P01	42	28-Apr-03	4	3367
2903	FTTR0118L3CA06188	68.76 TFS	TF	TBD	TAM	TE	TWZ	TDU	AJ	27-Aug-02	2-Nov-02	T601	F87Z	13480 AA	P01	X2	3-Feb-03	4	8038
2903	FTTR0118L3CA06188	88.41 TFS	TF	TBD	TAM	TE	TWZ	TDU	A4	28-Aug-02	17-Sep-02	T601	F87Z	13480 AA	P01	29	10-Dec-02	3	2512
2903	FTTR0118L3CA06188	44.1 TFS	TF	TBD	TAM	TE	TWZ	TDU	AR	28-Aug-02	2-Nov-02	T601	F87Z	13480 AA	P01	42	18-Apr-02	1	734
2905	FTTR0118L3CA06188	122.82 TFS	TF	TBD	TAM	TE	TWZ	TDU	AJ	28-Aug-02	23-Jan-03	T601	F87Z	13480 AA	P01	28	30-Jan-03	0	8718
2905	FTTR0118L3CA06188	142 TFS	TF	TBD	TAM	TE	TWZ	TDU	AJ	28-Aug-02	14-Jan-03	T601	F87Z	13480 AA	P01	1	15-Feb-03	1	3885
2905	FTTR0118L3CA06188	18.8 TFS	TF	TBD	TAM	TE	TWZ	TDU	A1	28-Aug-02	23-Nov-02	T601	F87Z	13480 AA	P01	X2	3-Mar-03	4	16673
2905	FTTR0118L3CA06188	175.89 TFS	TF	TBD	TAM	TE	TWZ	TDU	AJ	30-Aug-02	17-Sep-02	T601	F87Z	13480 AA	P01	48	10-Sep-02	6	8
2905	FTTR0118L3CA06188	32.01 TFS	TF	TBD	TAM	TE	TWZ	TDU	A1	1-Sep-02	27-Feb-03	T601	F87Z	13480 AA	P01	29	5-Oct-02	9	298
2905	FTTR0118L3CA06188	40 TFS	TF	TBD	TAM	TE	TWZ	TDU	A4	3-Sep-02	19-Oct-02	T601	F87Z	13480 AA	P01	42	18-Apr-03	7	13912
2905	FTTR0118L3CA06188	88.14 TFS	TF	TBD	TAM	TE	TWZ	TDU	AJ	3-Sep-02	11-Oct-02	T601	F87Z	13480 AA	P01	42	27-Dec-02	3	4087
2905	FTTR0118L3CA06188	28.73 TFS	TF	TBD	TAM	TE	TWZ	TDU	AJ	4-Sep-02	13-Sep-02	T601	F87Z	13480 AA	P01	28	1-Oct-02	2	683
2905	FTTR0118L3CA06188	12.38 TFS	TF	TBD	TAM	TE	TWZ	TDU	AR	5-Sep-02	8-Sep-02	T601	F87Z	13480 AA	P01	X2	19-Mar-02	1	494
2905	FTTR0118L3CA06188	69.22 TFS	TF	TBD	TAM	TE	TWZ	TDU	A1	8-Sep-02	23-Oct-02	T601	F87Z	13480 AA	P01	42	13-May-03	5	3488
2905	FTTR0118L3CA06188	44.04 TFS	TF	TBD	TAM	TE	TWZ	TDU	AJ	7-Sep-02	1-Oct-02	T601	F87Z	13480 AA	P01	X1	21-Feb-03	5	8430
2905	FTTR0118L3CA06188	64.89 TFS	TF	TBD	TAM	TE	TWZ	TDU	AR	10-Sep-02	19-Oct-02	T601	F87Z	13480 AA	P01	42	28-Dec-02	3	1130
2905	FTTR0118L3CA06188	38.08 TFS	TF	TBD	TAM	TE	TWZ	TDU	AJ	10-Sep-02	18-Nov-02	T601	F87Z	13480 AA	P01	42	29-Nov-02	1	377
2905	FTTR0118L3CA06188	87.21 TFS	TF	TBD	TAM	TE	TWZ	TDU	AJ	10-Sep-02	11-Nov-02	T601	F87Z	13480 AA	P01	42	10-Dec-02	1	4008

2003	1FTTR006L30KA0002	30	TFR	TF	TBC	TAM	TE	TAZ	TDU	AJ	15-Sep-02	25-Oct-02	7001	FRZ	13480	AA	P01	42	16-Jan-03	8	9487
2003	1FTTR007H30KA37000	270.88	TFS	TF	TBC	TAM	TE	TAZ	TDU	AJ	10-Sep-02	17-Dec-02	5901	*	13480	AA	P01	48	3-Feb-03	2	12001
2003	1FTTR01H30KA31473	51.82	TFS	TF	TBC	TAM	TE	TAZ	TDU	AR	12-Sep-02	3-Jan-03	7001	FRZ	13480	AA	P01	26	4-Jan-03	1	406
2003	1FTTR006L30KA47001	33.88	TFS	TF	TBC	TAM	TE	TAZ	TDU	AJ	15-Sep-02	2-Dec-02	7001	FRZ	13480	AA	P01	28	21-Mar-03	4	3521
2003	1FTTR006DCA00000	29.88	TFS	TF	TBC	TAM	TE	TAZ	TDU	AJ	16-Sep-02	16-Apr-03	7001	*	13480	AA	P01	28	23-Sep-02	0	4
2003	1FTTR006L30KA37012	32.88	TFS	TF	TBC	TAM	TE	TAZ	TDU	AJ	17-Sep-02	5-Dec-02	7001	FRZ	13480	AA	P01	28	16-Mar-03	4	8550
2003	1FTTR07243KA37000	20.78	TFS	TF	TBC	TAM	TE	TAZ	TDU	AR	17-Sep-02	10-Mar-03	7001	FRZ	13480	AA	P01	42	14-Apr-03	2	708
2003	1FTTR007L30KA05002	18.78	TFS	TF	TBC	TAM	TE	TAZ	TDU	AJ	18-Sep-02	28-Dec-02	7001	FRZ	13480	AA	P01	42	19-Mar-03	3	2008
2003	1FTTR01H30KA44002	24	TFS	TF	TBC	TAM	TE	TAZ	TDU	AR	18-Sep-02	8-Dec-02	7001	FRZ	13480	AA	P01	42	25-Jan-03	2	2377
2003	1FTTR006L30KA44000	61.88	TFS	TF	TBC	TAM	TE	TAZ	TDU	AJ	18-Sep-02	31-Jan-03	7001	FRZ	13480	AA	P01	28	6-Mar-03	2	3005
2003	1FTTR006L30KA00000	108.78	TFS	TF	TBC	TAM	TE	TAZ	TDU	AJ	18-Sep-02	4-Dec-02	7001	*	13480	AA	P01	33	11-Dec-02	1	12
2003	1FTTR006L30KA00070	58.28	TFS	TF	TBC	TAM	TE	TAZ	TDU	AJ	18-Sep-02	18-Dec-02	7001	FRZ	13480	AA	P01	42	9-Jan-03	1	1204
2003	1FTTR007L30KA00002	40.14	TFS	TF	TBC	TAM	TE	TAZ	TDU	AJ	18-Sep-02	1-Feb-03	7001	FRZ	13480	AA	P01	42	13-Apr-03	3	3806
2003	1FTTR007L30KA00120	48.8	TFS	TF	TBC	TAM	TE	TAZ	TDU	AJ	20-Sep-02	25-Oct-02	8901	P202	32719	A	P01	48	5-Dec-02	2	1849
2003	1FTTR1H30KA42002	17.4	TFS	TF	TBC	TAM	TE	TAZ	TDU	AR	20-Sep-02	15-Nov-02	7001	FRZ	13480	AA	P01	42	24-Apr-03	8	4805
2003	1FTTR006L30KA70001	22.58	TFS	TF	TBC	TAM	TE	TAZ	TDU	AJ	21-Sep-03	20-Jan-03	7001	*	13480	AA	P01	32	6-Feb-03	1	5380
2003	1FTTR01H30KA47002	29.88	TFS	TF	TBC	TAM	TE	TAZ	TDU	AR	23-Sep-02	23-Dec-02	7001	FRZ	13480	AA	P01	42	28-Oct-02	8	14
2003	1FTTR006L30KA07000	18.54	TFS	TF	TBC	TAM	TE	TAZ	TDU	AJ	24-Sep-02	4-Dec-02	7001	*	13480	AA	P01	7	2-Jan-03	1	350
2003	1FTTR007H30KA70007	18.82	TFS	TF	TBC	TAM	TE	TAZ	TDU	AJ	26-Sep-02	13-Feb-03	7001	FRZ	13480	AA	P01	42	7-May-02	0	21
2003	1FTTR007H30KA00704	182.88	TFS	TF	TBC	TAM	TE	TAZ	TDU	A1	26-Sep-02	30-Oct-02	8901	P202	32719	A	P01	42	29-Dec-02	2	2518
2003	1FTTR02H30KA00000	60.88	TFS	TF	TBC	TAM	TE	TAZ	TDU	A1	30-Sep-02	19-Oct-02	7001	*	13480	AA	P01	42	12-Oct-02	2	10223
2003	1FTTR02H30KA00004	257.24	TFS	TF	TBC	TAM	TE	TAZ	TDU	A1	4-Oct-02	18-May-03	7522	P202	146009	AA	P01	42	22-May-03	1	351
2003	1FTTR006L30KA00217	87.48	TFS	TF	TBC	TAM	TE	TAZ	TDU	AJ	7-Oct-02	14-Dec-02	7001	*	13480	AA	P01	28	10-Dec-02	1	288
2003	2FTTR01H30KA10002	13.2	TFS	TF	TBC	TAM	TE	TAZ	TDU	A4	8-Oct-02	20-Dec-02	7001	*	13480	AA	P01	42	13-Feb-03	2	764
2003	1FTTR01H30KA0001147	15.88	TFS	TF	TBC	TAM	TE	TAZ	TDU	AR	11-Oct-02	25-Dec-02	7001	FRZ	13480	AA	P01	42	18-Feb-03	2	888
2003	1FTTR006L30KA0000073	74.4	TFS	TF	TBC	TAM	TE	TAZ	TDU	AJ	11-Oct-02	19-Jan-03	7001	FRZ	13480	AA	P01	42	9-Dec-02	1	4436
2003	1FTTR006L30KA007240	23.12	TFS	TF	TBC	TAM	TE	TAZ	TDU	AJ	11-Oct-02	2-Jan-03	7001	FRZ	13480	AA	P01	42	25-Jan-03	1	1189
2003	1FTTR007H30KA010018	17.44	TFS	TF	TBC	TAM	TE	TAZ	TDU	AJ	23-Oct-02	16-Nov-02	7001	FRZ	13480	AA	P01	42	17-Dec-02	2	2757
2003	1FTTR006L30KA0007002	20.52	TFS	TF	TBC	TAM	TE	TAZ	TDU	AJ	7-Nov-02	6-Jan-03	7001	FRZ	13480	AA	P01	38	24-Jan-03	1	478
2003	1FTTR007L30KA00000	22.53	TFS	TF	TBC	TAM	TE	TAZ	TDU	A1	7-Nov-02	18-Jan-03	7001	FRZ	13480	AA	P01	42	23-Jun-03	1	383
2003	2FTTR01H30KA000007	185.34	TFS	TF	TBC	TAM	TE	TAZ	TDU	A4	11-Nov-02	14-Dec-02	7001	FRZ	13480	AA	P01	42	14-Dec-02	0	41
2003	1FTTR1720KA070000	43.84	TFS	TF	TBC	TAM	TE	TAZ	TDU	AR	12-Nov-02	8-Jan-03	7001	FRZ	13480	AA	P01	42	11-Feb-03	2	2540
2003	1FTTR007L30KA000007	68.2	TFS	TF	TBC	TAM	TE	TAZ	TDU	AJ	20-Nov-02	7-Feb-03	8901	P202	32719	A	P01	42	21-Feb-03	1	537
2003	2FTTR01H30KA0000002	20.22	TFS	TF	TBC	TAM	TE	TAZ	TDU	A4	19-Dec-02	8-Mar-03	7001	FRZ	13480	AA	P01	28	19-Mar-03	1	454
2003	1FTTR02H30KA0000000	181.82	TFS	TF	TBC	TAM	TE	TAZ	TDU	A1	19-Dec-02	14-Jan-03	7001	FRZ	13480	AA	P01	42	14-Jan-03	0	170
2003	2FTTR01H30KA0000001	53.38	TFS	TF	TBC	TAM	TE	TAZ	TDU	A4	17-Dec-02	7-Jan-03	7001	*	13480	AA	P01	42	3-Feb-03	2	9315
2003	1H30KA00130KA0000003	62.88	TFS	TF	TBC	TAM	TE	TAZ	TDU	A1	18-Dec-02	7001	FRZ	13480	AA	P01	42	15-Jan-03	-1	8	
2003	1FTTR021H30KA0000000	20.78	TFS	TF	TBC	TAM	TE	TAZ	TDU	A1	7-Jan-03	21-May-03	7001	FRZ	13480	AA	P01	42	20-Jun-03	2	1302
2003	1FTTR01H30KA0000000	18.8	TFS	TF	TBC	TAM	TE	TAZ	TDU	AR	15-Jan-03	31-Jan-03	7001	FRZ	13480	AA	P01	41	27-Mar-03	2	3216
2003	1FTTR01H30KA0000000	12.56	TFS	TF	TBC	TAM	TE	TAZ	TDU	AR	7-Feb-03	6-Apr-03	7001	*	13480	AA	P01	42	30-Apr-03	1	980
2003	1FTTR01H30KA0000004	57.8	TFS	TF	TBC	TAM	TE	TAZ	TDU	AR	20-Feb-03	20-Mar-03	7001	FRZ	13480	AA	P01	42	21-Mar-03	1	87
2003	2FTTR007H30KA0000000	8.78	TFS	TF	TBC	TAM	TE	TAM	TDU	A4	24-Feb-03	7001	*	13480	AA	P01	53	28-May-03	-1	12	
2003	1FTTR006L30KA0000000	60.8	TFS	TF	TBC	TAM	TE	TAZ	TDU	AJ	6-Mar-03	7001	FRZ	13480	AA	P01	42	2-May-03	-1	126	

MTRL_	TOT_COST	LSR_H	REGION_C	ST_PROV_	CPSC_C
COST_	_GROSS	RS	D	CD	D_S
7.85	180.23	1.1	NA	HU	00004
0	44.02	0.7	NA	MN	00004
0.05	80.4	0.8	NA	MN	00004
0.05	20.14	0.3	NA	PA	00004
0.05	47.3	0.8	NA	MA	00004
0.05	20.26	0.3	NA	UT	00004
0.05	40.79	0.8	NA	NY	00004
0	84.1	1	NA	LA	00004
0.05	45.26	0.5	NA	WA	00004
0.05	28.1	0.5	NA	CA	00004
0.05	23.86	0.8	NA	WA	00004
0.05	40.82	0.8	NA	NC	00004
0.05	40.34	0.8	NA	CA	00004
0.05	20.80	0.3	NA	TX	00004
223.26	264.70	2.1	NA	IA	100100
0	48.25	0.7	NA	AZ	00004
0.05	25.5	0.3	NA	MI	00004
0.05	30.86	0.8	NA	AL	00004
0.05	21.86	0.3	NA	WI	00004
0.05	22.6	0.3	NA	NC	00004
0.05	25.26	0.3	NA	MD	00004
2.05	62.85	1.2	NA	NY	00004
0.05	24.20	0.8	NA	TX	00004
0.05	174.83	2.1	NA	CA	020000
0.05	22.29	0.8	NA	NY	00004
0.05	82.74	0.8	NA	TX	00004
42.70	182.26	2	NA	CA	110401
42.70	128.22	2	NA	FL	110401
10.61	70.80	0.7	NA	NJ	100102
0.05	148.22	1.9	NA	CO	00004
0.05	20.70	0.3	NA	CA	00004
27.02	80.40	0.8	NA	MN	00004
0.05	24.88	0.3	NA	TX	00004
0.5	62.84	1	NA	WI	00004
0	27.8	0.8	NA	LA	00004
0	28.7	0.8	NA	CT	00004
0.05	88.97	0.3	NA	VA	00004
0.05	25.8	0.3	NA	OH	00004
10.41	411.83	8	NA	DR	00004
0.05	22.27	0.8	NA	PA	00004
0.05	28.26	0.3	NA	MN	00004
0.05	40.72	0.8	NA	FL	00004
7.05	20.28	0.3	NA	IL	00004
201.74	270.26	4.7	NA	TX	100100
0.05	85.40	0.8	NA	TX	00004
42.70	141.24	1.7	NA	TX	110401
0.01	20.81	0.8	NA	LA	100100
0.05	62.86	0.8	NA	FL	00004
0.05	61.88	0.8	NA	FL	00004
0.05	62.8	1.8	NA	NC	00004
0.05	60.26	1	NA	NY	00004
0.05	84.02	1.4	NA	MA	00004
0.05	80.80	0.8	NA	CA	00004
0	118.5	1.7	NA	TX	00004
0.05	20.90	0.3	NA	CA	00004
14.05	170.07	1.8	NA	CA	110401
0.05	25.78	0.3	NA	OK	00004

6.86	218.24	2.4 NA	NJ	180401
6.86	26.02	6.3 NA	TX	80884
6.86	21.88	6.3 NA	TX	80884
0	20.28	6.4 NA	TX	80884
6.86	42.88	6.8 NA	NY	80884
6.58	71.58	1 NA	MD	80884
44.88	61.28	6.3 NA	MA	80884
6.86	21.87	6.3 NA	GA	80884
0	44	8.7 NA	OH	80884
6.86	24.88	6.3 NA	TX	80884
6.58	28.23	6.3 NA	IN	80884
6.86	124.24	1.7 NA	TX	80884
6.86	28.84	0.3 NA	PA	80884
6.86	61.29	6.7 NA	FL	80884
6.86	68.31	6.9 NA	FL	80884
6.86	40.88	0.8 NA	NC	80884
6.58	124.73	2.3 NA	AR	80884
6.86	68.72	8.8 NA	VT	80884
6.86	67.88	6.8 NA	FL	80884
7.08	68.48	6.3 NA	IL	80884
6.58	72.42	0.9 NA	CO	80884
6.86	113.88	1.8 NA	PA	80884
7.22	61.68	6.3 NA	NJ	80884
6.86	84.88	0.8 NA	TX	80884
6.58	28.88	0.3 NA	OR	81884
42.78	47.88	6.5 NA	MI	118401
0	61.81	0.4 NA	CT	80884
18.17	72.75	0.7 NA	VA	80884
6.01	88	1.1 NA	VA	80884
6.58	41.27	0.7 NA	SD	80884
6.86	34.88	6.5 NA	CA	80884
0	11.81	6.2 NA	WV	80884
6.86	71.83	0.9 NA	TX	80884
42.78	148.88	2 NA	AR	118401
62.88	248.67	3.8 NA	MI	118401
6.86	42.88	6.7 NA	MS	80884
6.58	62.82	1.3 NA	WA	80884
6.86	120.88	1.7 NA	WA	80884
6.48	128.28	1.8 NA	TX	80884
42.78	182.48	1.8 NA	AK	118401
48.73	221.87	2.6 NA	CO	188401
6.86	70.48	6.8 NA	UT	80884
6.86	60.88	6.8 NA	UT	80884
6.86	68.8	6.9 NA	TX	80884
6.01	68.83	3.8 NA	TX	80884
6.86	68.84	6.8 NA	MO	80884
6.48	63.88	6.8 NA	NJ	80884
6.58	38.82	6.6 NA	AL	80884
6.86	37.81	6.3 NA	TX	80884
7.78	44.78	6.8 NA	WI	80884
16.6	62.83	1.1 NA	CA	80884
6.86	41.4	6.6 NA	ND	80884
6.58	28.28	6.9 NA	LA	80884
6.86	72.28	6.8 NA	CA	80884
6.86	26.67	6.8 NA	SC	80884
6.86	38.82	6.8 NA	MO	80884
6.86	21.88	6.3 NA	SD	80884
28.88	76.88	6.8 NA	AL	80884
6.86	26.44	6.3 NA	OH	80884
7.08	28.52	6.5 NA	IN	80884
6.78	26.28	6 NA	GA	80884
0	62.78	6.6 NA	NJ	80884

7.88	86.82	1 NA	NJ	0004
6.88	25.88	0.3 NA	FL	0004
6.88	88.88	0.3 NA	LA	0004
6.88	22.88	0.3 NA	MO	0004
6.88	88.82	0.3 NA	FL	0004
6.88	88.34	2.1 NA	CA	0004
6.88	71.25	0.3 NA	TX	0004
6.88	24.88	0.3 NA	PA	0004
6.88	118.34	1.8 NA	NY	0004
6.88	84.8	0.3 NA	TX	0004
6.88	28.88	0.3 NA	CA	0004
42.78	148.82	1.8 NA	MO	11041
7.88	28.87	0.3 NA	IN	0004
6.88	28.87	0.3 NA	CA	0004
6.88	84.88	0.3 NA	NE	0004
6.88	24.78	0.3 NA	NE	0004
6.88	84.88	0.3 NA	OH	0004
6.88	148.14	2.1 NA	MA	0004
6.88	38.31	0.3 NA	CA	0004
7.88	22.44	0.3 NA	IL	0004
10.88	48.18	0.3 NA	AZ	0004
6.88	81.48	0.3 NA	FL	0004
6.88	38.37	0.3 NA	MI	0004
6.88	22.07	0.3 NA	NY	0004
0.44	38.38	0.3 NA	IN	0004
11.87	128.48	1.8 NA	MO	0004
42.78	87.87	1 NA	IN	0004
42.48	87.87	0.7 NA	IN	0004
6.88	38.28	0.3 NA	FL	0004
6.88	48.88	0.3 NA	FL	0004
6.88	81.78	0.3 NA	ID	0004
6.84	22.44	0.3 NA	TX	0004
6.88	88.31	0.3 NA	CA	0004
6.88	81.78	0.3 NA	AL	0004
6.88	38.38	0.3 NA	AZ	0004
6.88	188.88	1.8 NA	AL	0004
6.88	28.78	0.3 NA	IN	0004
0.27	38.37	0.3 NA	AL	0004
48.28	124.11	0.8 NA	CA	0004
6.88	48.31	0.3 NA	MT	0004
6.88	25.48	0.3 NA	TX	0004
6.88	38.48	0.3 NA	AL	0004
6.88	28.81	0.3 NA	CA	0004
6.88	108.88	1.8 NA	FL	0004
6.88	28.88	0.3 NA	GA	0004
6.88	70.48	0.3 NA	AZ	0004
6.88	27.88	0.3 NA	FL	0004
6.88	70.81	0.3 NA	AZ	0004
6.81	88.88	0.3 NA	FL	0004
6.88	84.18	0.3 NA	TX	0004
6.88	48.18	0.3 NA	NC	0004
6.88	88.88	0.3 NA	SC	0004
6.88	28.38	0.3 NA	KS	0004
6.88	87.22	0.3 NA	CO	0004
6.88	27.32	0.3 NA	FL	0004
2.21	88.81	0.3 NA	GA	0004
0	27.88	0.4 NA	TX	0004
6.88	78.84	1 NA	OR	0004
6.88	77.78	0.3 NA	NJ	0004
6.88	80.38	0.3 NA	CA	0004
6.88	47.87	0.3 NA	SD	0004
6.88	28.71	0.3 NA	NE	0004

0.50	21.43	0.3 NA	WI	00004
0.50	20.4	0.3 NA	NY	00004
0.50	20.00	1 NA	PA	00004
0.50	20.25	0.9 NA	TX	00004
0.50	20.55	0.3 NA	VA	00004
7.50	191.82	1.9 NA	CA	00004
02.70	140.93	1.7 NA	MA	110001
0.50	79.00	0.9 NA	AZ	00004
0.50	27.00	0.3 NA	KS	00004
7.50	23.00	0.3 NA	IL	00004
0.50	24.1	0.3 NA	PA	00004
0.50	02.79	0.9 NA	FL	00004
0.50	28.7	0.3 NA	MO	00004
0.50	04.07	0.7 NA	WA	00004
0.1	07.00	0.5 NA	AZ	00004
0.50	27.00	0.3 NA	PA	00004
7.50	28.04	0.3 NA	IL	00004
02.70	104.51	2.4 NA	PA	110001
0.50	04.00	0.9 NA	AL	00004
0.50	23.00	0.9 NA	GA	00004
0	00.5	1.1 NA	GA	00004
0.50	41.00	0.9 NA	CO	00004
0.50	71.05	0.9 NA	CO	00004
0	00.00	1 NA	MO	00004
44.00	100.00	1.8 NA	FL	110001
0.50	00.12	0.9 NA	AZ	00004
7.50	02.25	0.9 NA	IL	00004
0	00.70	0.7 NA	NJ	00004
7.50	20.12	0.3 NA	IN	00004
0.5	22.0	0.3 NA	CO	00004
0.50	20.14	0.5 NA	MI	00004
0.5	13.00	0.2 NA	TX	00004
0.50	21.00	0.3 NA	PA	00004
0.50	05.00	0.7 NA	MO	00004
0.50	00.00	0.9 NA	MN	00004
0.50	07.70	0.9 NA	TN	00004
0.50	02.00	0.9 NA	NC	00004
0.50	27.13	0.3 NA	OK	00004
0.50	24.70	0.3 NA	NE	00004
0.50	00.07	0.9 NA	MA	00004
0.50	75.00	0.9 NA	MN	00004
0.50	00.21	0.3 NA	TX	00004
0	31.00	0.5 NA	MA	00004
0.50	40.40	0.9 NA	MA	00004
0.50	25.14	0.3 NA	MN	00004
0	00.70	1.4 NA	CA	00004
0.50	02.00	0.9 NA	TX	00004
0.50	00.00	0.9 NA	IL	00004
0.50	120.0	1.9 NA	NC	00004
7.07	140.07	2 NA	MA	00004
0	10.0	0.3 NA	MO	00004
02.70	210.54	2.3 NA	MA	110001
0.50	20.00	0.3 NA	MI	00004
0.50	40.00	0.5 NA	MA	00004
0.50	71.72	0.9 NA	NV	00004
0.50	27.31	0.3 NA	WI	00004
0	02.00	0.2 NA	WI	00004
0.50	00.0	0.9 NA	CA	00004
0.50	50.02	0.3 NA	NY	00004
0.50	101.44	1.5 NA	OR	00004
0.50	05.25	0.9 NA	GA	00004
0.50	70.70	1.3 NA	VA	00004

6.88	38.58	0.8 NA	MI	80804
44.88	322.82	2.8 NA	MD	110801
6.88	38.1	0.8 NA	MI	80804
6.88	42.88	0.8 NA	NY	80804
0	28.88	0.5 NA	IL	80804
6.88	38.44	0.8 NA	TX	80804
6.88	27.37	0.5 NA	DE	80804
8.88	28.73	0.3 NA	FL	80804
6.88	20.88	0.3 NA	MA	80804
8.88	88.88	0.9 NA	FL	80804
0	100.74	1.4 NA	CA	80804
6.88	88.88	0.8 NA	CO	80804
6.88	48.72	0.6 NA	FL	80804
42.78	82.88	0.8 NA	AL	110801
6.88	28.88	0.3 NA	WV	80804
0	22.88	0.4 NA	MI	80804
6.88	38.88	0.5 NA	MD	80804
0	18.84	0.3 NA	PA	80804
7.25	28.87	0.3 NA	IN	80804
42.78	228.48	2.8 NA	ID	110401
0	80.88	0.9 NA	MD	80804
283.88	480.88	3.3 NA	CA	900108
0	87.88	1.3 NA	MD	80804
6.88	18.78	0.3 NA	ME	80804
6.88	22.27	0.3 NA	PA	80804
8.88	88.88	1.2 NA	TX	80804
6.88	28.7	0.3 NA	MD	80804
8.88	34.88	0.3 NA	OK	80804
6.88	28.8	0.3 NA	PA	80804
6.88	28.81	0.3 NA	MI	80804
6.88	188.12	3.3 NA	CA	80804
7.28	81.4	0.7 NA	NC	80804
47.21	118.41	1.1 NA	IL	110401
6.88	28.8	0.3 NA	IA	80804
8.88	188.1	2.7 NA	TX	80804
7.28	48.88	0.5 NA	AZ	80804
6.88	88.48	0.8 NA	NY	80804
6.88	27.37	0.3 NA	TX	80804
8.88	28.88	0.3 NA	TN	80804
0	12.88	0.2 NA	IN	80804
6.88	84.18	0.8 NA	TN	80804
0	8.78	0.3 NA	WI	80804
6.88	87.48	0.8 NA	WI	80804

TECH_TXT1

VERIFIED CONCERN TESTED FUSES IN CIRCUIT OK TESTED POWER TO BRAKE PRESSURE SWITCH OK TESTED FOR POWER AT SHFT LOCK SOLENOID OK TESTED GROUND OK DIAGNOSE AND REPLACED FAULTY BRAKE PRESSURE SWITCH

WFS9 BRAKE PEDAL POSITION SWITCH SENSOR OPEN CC 46,CC P01 VERIFY CONCERN,MOBI TEC SYS DIAG NO DTCS PRESENT,TEST & RE PLACE BPP9 & RETEST. 0626 403
TECH 127 VERIFIED CONDITION,PERFORMED DIAGNOSIS AND FOUND OPEN IN BRAKE LAMP SWITCH,REPLACED BRAKE LAMP SWITCH AND RETESTED,CONDITION NO LONGER PRESENT AT THIS TIME
3048 28 TEST DROVE VERY MT. BRAKE LIGHTS DO NOT COME ON WILL NOT SHFT DIA PINPOINT TESTING OF HARNESS OK TEST BRAKE LIGHT SWITCH FAILED REMOVED AND REPLACED BRAKE LIGHT SWITCH RETESTED OK XXXXXXXX
1732 DIAG COULD NOT DUPLICATE,REPLACED BOO SWITCH AS PER DENIM SHAPING
TEST AND REPLACE BRAKE LITE SWITCH
28 OPEN CIRCUIT BRAKE SWITCH PLUG 14481 13480 XE VERIFY CONCERN. REINSTALL BRAKE SWITCH PLUG TO OPERATE TRANS. LOCK AND BRAKE LIGHTS. OK. REPAIR OK.
11488 0282 BOO SWITCH WARRANTY ROADTEST WITH CUSTOMER TO VERIFY CONCERN. PERFORMED BODY CHASSIS ELECTRICAL TEST AND ACCESS INSTRUMENT PANEL TO REROUT HARNESS TO BOO SWITCH. REPLACED BOO SWITCH W/
CHK FUSES CHK BRAKE SWITCH SWITCH BAD REPLACED SWITCH.
OK OPP FOUND BRAKE SWITCH BAD NESS REPLACE STOP LIGHT SWITCH
PERFORMED BRAKE SWITCH ELECTRICAL/PINPOINT TEST REPLACED SWITCH ASSEMBLY
BRAKE SWITCH WORKS INTERMITTANTLY SWITCH STOP LAMP REPLACE
CHECK OUT VEH WILL NOT SHFT INTO PARK AT TIMES, REPLACE BRAKE LIGHT SWITCH (OPEN CIRCUIT)
TESTED CIRCUITS,FOUND THE BRAKE FUSE WAS BLOWN FOR THE SHFT INTERLOCK SWITCH BAD OPEN CIRCUIT,ALSO FOUND THE FUSE PANEL BAD,REPLACED THE BRAKE SWITCH AND THE FUSE PANEL,TEST DROVE FOUND STILL INTERM
DISPECTED BRAKE LIGHTS. INOP. CHECKED FUSE. OK. PERFORMED PINPOINT TEST. OPEN IN BRAKE LIGHT SWITCH HARNESS. REPAIRED OPEN. RE TESTED. OK.
ROAD TESTED AND TESTED OPERATION OF THE SHIFTER. IT COMES OUT OF PARK EVERY TIME,ADVISED AND ROAD TESTED HOME STILL.
1608 PERFORM B C E DIAG FOLLOWED PINPOINT TEST REPLACED BRAKE PEDAL POSITION SWITCH RETEST O.K. CC 43.
BRAKE LIGHTS DO NOT WORK FOUND BROKEN BRAKE SWITCH REPLACED AND RETEST
REPLACE BRAKE SWITCH
REPLACE BRAKE LIGHT SWITCH
OK REPLACED FUSE OK FOR SHORT REPAIR SHORTED WIRE IN COLUMN FOR BRAKE LITE SWITCH
VERIFY CUSTOMER CONCERN TEST AND REPLACE OPEN BREAK LIGHT SWITCH RETEST OK
24129 2516A 1.8 13480A 3 OK GEAR SHFT OPER. FOUND BINDING GEAR SHIFTER, NO TO IN/STEERING COLUMN TO OK OPERATION. FOUND INTERMITTENT LOSS OF POWER AT SHIFTER SOLENOID. CAUSED BY FAULTY BK SWITCH
CHECKED CIRCUITS, BRAKE LIGHT SWITCH HAS OPEN CIRCUIT R/R BRAKE LIGHT SWITCH
OPEN CIRCUIT BODY CHASSIS ELECTRICAL (BCE) TEST
THE SHFT LEVER STICKS IN PARK AT TIMES. TESTS INDICATE A FAULT IN THE SHFT INTERLOCK SOLENOID. REPLACED THE SHFT INTERLOCK SOLENOID AND RECHECKED OPERATION OK.
OK SHFT INTERLOCK REPL SHFT INTER LOCK BOLD AND BK SW AMF FUSE OK FOR SERVICE
REPAIR WIRING AT BRAKE LIGHT SWITCH AND REPLACE SWITCH
OPEN CIR ELECT TRANS DIAG PINPOINT REPLACE BOO SWITCH REROD TEST
SWITCH DIAGNOSIS CONCERN IN BRAKE LIGHT SWITCH, R/R SWITCH RETEST ALL ACCR
HAD TO PARK NEAR BRAKE LINE. CHECKED CONCERN FOR NOT COMING OUT OF PARK. FOUND BRAKE SWITCH ACTING UP.
BRAKE LIGHT SWITCH OK VEHICLE NOT COMING OUT OF PARK. FOUND BRAKE LIGHT SWITCH SHORTED. REMOVED AND REPLACED BRAKE LIGHT SWITCH. RETEST, OK
FOUND PIN FOR BRAKE SWITCH MISSING REPLACED
VERIFY CONCERN FOUND NO BRAKE LIGHTS FUSES OK OK CHED VOLTAGE AT GREEN WIRE ON BRAKE LIGHT SWITCH NO VOLTS WITH PEDAL DEPRESED WIRE TERMINAL. REPAIRED TERMINAL, OK OK
VERIFY CONCERN, TROUBLE SHOOT INTERLOCK SYSTEM,CONNECTOR C278 WONT LOCK ONTO BRAKE ON OFF SWITCH,BOO SWITCH PIN 3 OK 22 BENT,STRAIGHTEN PIN,LOCK CONNECTOR,OK
26118 W VERIFIED CUSTOMERS CONCERN SHIFTER WOULD NOT COME OUT OF PARK REPLACE BRAKE LIGHT SWITCH ASSY.
BRAKE SWITCH INOP. TESTED CKT O.K. REPLACED SWITCH. SHFT INTERLOCK NOW WORKS.
VERIFY CONCERN,PERFORMED DASH SWITCH DIAG AN PINPOINT TEST TEST POWER AN GROUND,NECESSARY TO ACCESS DASH TO ACCESS HARNESS TEST GR YE WIRE WITH CHM METER WIRE TEST BAD WIGGLE TEST HARNE IS REPA
CHECKED AND REPLACED BRAKE SWITCH
P01 SWITCH STOP LAMP REPLACE
CONFIRMED CUSTOMER COMPLAINT PERFORMED INSPECTION OF BRAKE LIGHTS OPERATION AND FOUND BRAKE LIGHTS TO BE INOP PERFORMED PIN POINT TEST FOUND BRAKE SWITCH TO HAVE AN INTERNAL OPEN IN CIRCUIT REPLACED B
1 VERIFIED CONCERN, PINPOINT TO CIRCUIT 619 REPLACE DEFECTIVE STOP LIGHT SWITCH
30P FUSE BLOWN UNDER DASH OKED OUT AND VERIFY CONCERN,SHFT INTERLOCK. INOP OKED FUSES OK OKED POWER AND GROUND. NO POWER TO CIRCUIT 160 NEEDS WIRE WITH BRAKE APPLIED NO POW
OK CIRCUITS REPLACE STOP LIGHT SWITCH
18258 CODE 42 WARRANTY DUPLICATED COMPLAINT FOUND BRAKE SWITCH CONNECTOR TERMINAL HAD BACKED OUT AND WAS ARCING,SHORTED BRAKE SHFT LOCK SOLENOID AND BRAKE SWITCH ITSELF ALSO NOT WORKING CONNECT
4838 FOUND SHFT LOCK FUSE BURNT REPLACED SHORTED ELECTRONIC BRAKE SWITCH INSTALLED AMP METER AND FOUND NO EXCESSIVE DRAIN. REPLACED FUSE AND OPERATION IS NORMAL
14244 #13488 COND CODE 42 100 SHIFTER FOR. TRANSMISSION HARD TO GET OUT OF PARK,TEST ALL LINKAGE,OK. TEST FOR BRAKE LIGHTS ON, THEY DO WORK. CHECK FOR POWER TO SOLENOID FOR RELEASE. NO POWER TO SOLE
DEFECTIVE SWITCH SWITCH STOP LAMP REPLACE
PERFORM CIRCUIT TEST PINPOINT TEST REPAIR SHORTED BRAKE PEDAL SWITCH WIRING ON STEERING SHAFT REPAIR WIRING AND REPLACE FUSE
INTERNALLY SHORTED CHECK OUT NGS PID MONITOR,REPLACE BRAKE SWITCH
CHECK CIRCUIT NOO POWER AT SHFT LOCK SOLENOID WITH BRAKE DEPRESED
REPLACE SWITCH ASY
PERFORM NGS TEST, PINPOINT TEST. NO BOO SIGNAL. REPLACE 6 AM P FUSE. REMOVE STEERING COLUMN. TRACE SHORT AND REPAIR SHORT ED CIRCUIT 610
BRAKE SWITCH BAD, REPLACED BRAKE LIGHT SWITCH
MT NO 810 LOWER STEERING COLUMN TO REPLACE SHFT SOLENOID.
BRAKE PEDAL SWITCH P18 13480 VERIFIED CONCERN USED THE NGS AND CHECKED THE PIDS FOUND THE BRAKE LAMP SWITCH TO NOT BE BENDING THE SIGNAL TO

WIRE CUT ON DASH FRAME AND BRAKE SWITCH TAB BROKEN VEHICLE WILL NOT COME OUT OF PARK. BRAKE LAMP SWITCH BROKEN TAB. REPLACE BRAKE PEDAL SWITCH. STILL NOT BRAKE TEST AND REPLACE BOD SWITCH. RETEST

INTERMITTENT OPEN IN STOP LIGHT SWITCH REPLACE STOP LIGHT SWITCH

WIRE TERMINAL PULLED LOOSE FROM CONNECTOR AT BRAKE LIGHT SWITCH REINST

OPEN CIRCUIT IN BRAKE SWITCH SWITCH STOP LAMP REPLACE

R AND R BRAKE SWITCH

TESTED SYSTEM AND REPLACED BRAKE SWITCH AND SHIF LOCK AT SOLENOID

TRANS HARD TO GET OUT OF PARK. CHECK SYSTEM AND FOUND THAT THE BOD SWITCH WAS BAD. REPLACED SWITCH TO REPAIR.

4451 CUST. STATES WONT COME OUT OF PARK VERIFIED CUST. CONCERN/RAN CASS,NO TIRE OR SENS,REMOVED LINKAGE,FOUND NO PROBLEMS IN LINKAGE,REMOVED BRAKE SWITCH,TESTED FOR PWR, BRAKE SWITCH IS FUNCTION

1 TESTED TRANS SHIFTER ASSEMBLY AND FOUND BRAKE SWITCH WAS NOT WORKING REPLACED SWITCH AND RETESTED ALL OK NOW 42

CHECK INTERLOCK CIRCUITS, REPLACE BRAKE LIGHT SWITCH, RECHECK, OK. CLOSED BY WPI

1 COMPLETED STEERING COLUMN DIAG. ACCESS STEERING COL TO GAIN ACCESS TO TEST WIRES TO BRAKE SWITCH WIRES TESTED

7828 OK SHIFTER REPLACE BRAKE LITE SWITCH (OPEN) RETEST

21848 CHECK OUT BRAKE LIGHT SWITCH BAD, REPLACE BRAKE LAMP SWITCH. RECHECK

28 VERIFY COMPLAINT CHECK FUSES OK CHECK FOR POWER AND GROUND AND SHIF LOCK SOLENOID, 8 VOLTS BEC DIAG VERIFY LG RD

FUSE BLOWING. TEST DROVE. RAN BRAKE SWITCH

VERIFY CONCERN CHECKED ELECTRICAL SYSTEM FOUND BRAKE LIGHT SWITCH NOT OPERATING PROPERLY REPLACED BRAKE LIGHT SWITCH VERIFY REPAIR

SWITCH INOP SWITCH STOP LAMP REPLACE

TEST CIRCUITS & REPLACED BRAKE LIGHT SWITCH

CONFIRM CUST CONCERN TEST VEH. WITH NISS MONITORED PIDS FOUND BRAKE ON OFF SWITCH OPEN INTERMITTLY PERFORMED PIN REPLACED BRAKE ON OFF SWITCH RETEST PASS ALL WORKING AS INTENDED AT THE TIME

SHORTY BDC DIAGNOSIS, PINPOINT TEST, REPLACE FUSE, REPLACE STOP LIGHT SWITCH. STOP LAMP SWITCH WIRE RUBBED THROUGH.

SHORTED BRAKE SWITCH DIAG AND LOCATE CONCERN REPLACE BRAKE SWITCH

BDC TEST PINPOINT TEST REPLACED STOP LIGHT SW ON

TEST VEHICLE OPERATION AND VERIFY CONCERN INSPECT STEERING COLUMN AND FOUND BRAKE SWITCH BROKEN. REPLACE BRAKE SWITCH AND RETEST FUNCTION AS DESIGNED.

INSPECT VEHICLE, RAN CASS AND TSB FOR THE CONCERN. RAN TEST FOUND BRAKE LIGHT SWITCH DEFECTIVE. REPLACE SWITCH FOUND INTER. POWER ON RED BLACK WIRE FROM SWITCH AND ACTUATOR. TRACE WIRING, DASH ACCESS

WIRING ASSEMBLY REPAIR

CHECKED REPLACED BRAKE LIGHT SWITCH REPAIRED SHIF CABLE WARR

BODY CHASSIS ELECTRICAL (BCH) TEST

CHECKED FUSES OK WORKS AT TIMES TAP ON BRAKE SWITCH ACTS UP REPLACED BRAKE SWITCH

PARK INTERLOCK WORKING WELL IN BAY INSPECTED INTERLOCK AND BRAKE LIGHT SYSTEM DIAG AND REPLACED SUSPECT BRAKE LIGHT SWITCH

TESTED ALL FUSES WITH FLURE METER AND GOOD WIRING AT STOP LAMP SWITCH FOUND 13480 CONNECTOR NOT ATTACHED BEATED CONNECTOR RETESTED OK

BDC TEST, PIN POINT TEST, FOUND BRAKE LIGHT SWITCH OPEN CIRCUIT. REPLACE SWITCH AND RETEST

2148 CHECKED AND FOUND SHIF INTERLOCK INOP AT TIMES REPLACED SHIF INTERLOCK SOLENOID ALSO REPLACED BRAKE LIGHT SWITCH TO FIX TEST DROVE TO VERIFY

STOP LIGHT SWITCH INOP AND FAILED SHIF INTERLOCK ACTUATOR. PERFORMED BDC DIAG, REPLACED STOP LIGHT SWITCH. RETEST, PINPOINT TEST, CHECKED CONNECTORS AND FUSES. ACCESS STEERING

VERIFY CONCERN TEST FOR TO STOP LITE SWITCH OK DIAG BAD SWITCH REMOVE AND REPLACE SWITCH TOO CORRECT THE CONCERN

VERIFIED CUSTOMERS CONCERN HAPPENED BRAKE LIGHTS DIDNT FUNCTION INTERMITTENTLY PROBLEM WITH BRAKE LIGHT SWITCH REPLACED BRAKE LIGHT SWITCH VEHICLE STILL INTERMITTENTLY DIDNT COME OUT OF PARK HAD TO REMOVE

RAN TRANS DIAG TESTS AND REPLACE STOP LIGHT SW

SOLENOID INOP STEERING COLUMN ASSEMBLY REMOVE AND INSTALL

16887 DIAG SHIF PROBLEM WARR CHECK OUT FUSES, ABS BLOWN FUSE, REPLACE FUSE, FUSE POPED. CHECK WIRING HARNESS FOR ANY SHORTS OR LOOSE GROUNDS. DID NOT FIND ANY. CHECK BRAKE SWITCH, WHEREIT HOOKS T

VERIFIED THE CONCERN AND REPLACED THE BRAKE SWITCH AND VERIFIED THE REPAIR.

128510 J 1285102 J 13488A J CC 42 CCC P01 VERIFIED CONCERN HOOKED UP WDS AND CHECKED OPERATION OF BRAKE SWITCH FOUND IT WORKING ABOUT HALF THE TIME REPLACED

VERIFY CONCERN CHECK GEAR SELECTOR FOR SHORT TO GROUND PINPOINT TEST FOUND STOP LAMP SWITCH SHORTING REPLACED STOP LAMP SWITCH AND RECHECKED OK

GEAR SHIFTER WILL NOT GO INTO GEAR CHECKED BRAKE LAMP SWITCH SHORTED OUT R N R BRAKE LAMP SWITCH ROAD TESTED OK AT THIS TIME

BRAKE SWITCH NOT OPERATING PROPER SWITCH STOP LAMP REPLACE

OK CODES REPLIC SW

REPLACED BRAKE STOP LIGHT SWITCH RAN PIN POINT DIAG

CC 43 CP 13486 BRAKE LIGHT SWITCH INOP REPLACED SWITCH UNTEST

BRAKE LIGHT SWITCH INOP REPLACED BRAKE SWITCH. CLOSED BY WPI

CHECKED AND VERIFIED CONCERN PERFORMED PIN POINT TEST AND FOUND FUSE 34 AND 10 AMP BLOWN PERFORMED CIRCUIT TEST AND

DEFECTIVE STOP LAMP SWITCH BODY CHASSIS ELECTRICAL PIN POINT TEST DIAGNOSIS

VARIFIED CONCERN NO BRAKE LIGHTS PINPOINT TEST REPLACED BRAKE LIGHT SW

TEST AND REPLACE INOP STOP LAMP SWITCH.

DIAGNOSIS REPLACE BRAKE LIGHT SWITCH DUE TO OFF N AND RETEST.

SWITCH STICKING

DIAG REPLACED BRAKE LIGHT SWITCH

RAN ELECTRICAL TEST AND RAN PINPOINT TEST AND FOUND INOP BRAKE LIGHT SWITCH AND TESTED

ITEM WONT COME OUT OF PARK AT TIMES WARR REPLACE ERRATIC STOP LAMP SWITCH

STICKING. VERIFIED PROBLEM AND REPLACED THE BRAKE LIGHT SWITCH.

RAN FUSE, BLOW AGAIN. TEST SYSTEM, DISCONNECT PCM, SECURITY MODULE, ABS MODULE, BRAKE POSITION SWITCH, & GEM MODULE. RETEST EACH; STILL BLOW FUSE. HOOKED RESETTABLE FUSE IN LINE TO RD GN WIRE AT BR

CHECK WONT COME OUT OF PARK PERFORM MSJ TEST PINPOINT TEST FINAL QUICK TEST CHECK AND CHECK WIRING REPLACE BURNED OUT FUSE CHECK OK

CHECK WONT COME OUT OF PARK PERFORM NGS TEST PINPOINT TEST CHECK AND REPLACE BRAKE SWITCH AS PER TECH HOTLINE REPLACE FUSE CHECK OK

SHORTED RAN PINPOINT TEST FOUND BREAK LIGHT SWITCH NOT WORKING PROPERLY RER BREAK LIGHT SWITCH

INSF VEHICLE WOULD NOT DISENGAGE SHIFT INTERLOCK WHEN BRAKE WAS PUSHED CHECKED FUSE 27 18A T 34 18A CHECKED FOR POWER ON CIRCUIT MURCUG NO POWER REPLACED BRAKE PEDAL SWITCH AND RETESTED

WILL NOT COME OUT OF PARK CHECKED SYSTEM BRAKE LIGHT SWITCH IS BAD R&R SWITCH AND RECHECKED OK 1

1 VERIFIED CONCERN CHECK STOP LAMP AND INTERLOCK SWITCH REPLACE STOP LAMP SWITCH AND RETEST VERIFIED REPAIR

1 REPLACED BRAKE SWITCH RETEST OK

VERIFY. ELECT DIAG. PINPOINT. FOUND BRAKE LIGHT SWITH INOP AT TIMES. REPLACE SWITCH. RETEST ALL OK

NOT WORKING PROPERLY SWITCH STOP LAMP REPLACE

899 WILL NOT COME OUT OF PARK 41 WILL NOT COME OUT OF PARK. I PERFORMED AUTO TRANS SYSTEM DIAG. I TESTED THE SHIFT LOCK SOLENOID AND FOUND OK. I THEN TESTED ALL CIRCS AND FOUND OK. I THEN TESTED TH

23 RAN PINPOINT TEST ON BRAKE LIGHT. R&R BRAKE LIGHT SWITCH TO REPLACE WITH NEW ONE TEST DROVE 4.8 C/P 13488 C/P 42

7391 W TEST & DO PINPOINT TEST REPLACE BRAKE LIGHT SWITCH RETEST OK

TEST DROVE VEH. WILL NOT COME OUT OF PARK ALL THE TIME. OKD FOR BRAKE LIGHTS OK. WENT TO PIN POINT TESTS A IN MANUAL. INSTALLED NEW SHIFT LOCK ACTUATOR. OKD OPERATION STILL HAS CONCERN. TRIED NEW BRAK

SWITCH BAD SWITCH STOP LAMP REPLACE

17888 BAD BRAKE SWITCH 13488A 0.3 T 0.5 HRS R R SWITCH AND TESTED NORMAL. JOB COMPLETE

6289 PINPOINT TESTED. FOUND BRAKE LIGHT WORK OK. BUT NO SIGNAL SENT TO THE SHIFT LOCK SOLENOID. REPLACED BRAKE SWITCH AND REASSEMBLED. VEHICLE SHIFTS OUT OF PARK OK.

TEST DROVE AND FOUND BRAKE SWITCH NOT FUNCTIONING PROPERLY R&R SWITCH

TEST OPERATION FOUND BAD BRAKE SWITCH REPLACED SWITCH

BRAKE LIGHT SWITCH BURNT OUT

7 INOP 8.4 DISENGAGE FOR AND REPLACE BRAKE LIGHT SWITCH RETEST OK

REPLACED BRAKE LIGHT SWITCH ERRATIC OPERATION

126 13488 FOUND OUT THAT P234 WAS OPENED DUE TO INTERNAL SHORT. REPLACED FUSE 10 AMP FUSE AND TRACED CIRCUIT AND FOUND OUT THERE WAS A SHORT IN THE BRAKE SWITCH. REPLACED BRAKE SWITCH. TEST AFTER

13488 INOP CC 42 REPLACED BRAKE ON OFF SWITCH. RETEST

COULD NOT VERIFY IN LOT RAN DASH NOTHING FOUND DRY VEHICLE TO A HILL ENGAGE PARK AND DISENGAGE. BOTH UPHILL AND DOWNHILL HARDER WHEN PRKD DOWNHILL. NEED TO ENGAGE PARK BRK SPRE RELEASING BRK PEDAL. AFTR

BRAKE LIGHT SWITCH FAILED TEST PARK LOCK OUT AND REPLACE DEFECTIVE BRAKE LIGHT SWITCH.

INT. TIME TO REPLACE CLIP ON SWITCH SWITCH

12 482 FOUND FUSE BLOWN REPLACED FUSE BLEW AGAIN TRACE WIRE WIRE WAS PINCHED ON COLUMN REPAIR WIRING INSTALL FUSE STILL WONT MOVE REPLACED BRAKE LIGHT SWITCH OK 482

VERIFIED CUSTOMER CONCERN RAN PINPOINT TEST FOUND SHIFT INTERLOCK SOLENOID AND BRAKE LIGHT SWITCH BAD. RESOLVED AND REPLACED BRAKE LIGHT SWITCH AND SHIFT SOLENOID

84 OK OUT REPL. BRAKE SWITCH AND SHIFT SOLENOID 13488 42 32719 42

REPLACED THE BRAKE PEDAL SWITCH ASBY. RECHECKED OK

DIAG. REPLACED BRAKE LIGHT SWITCH. RETEST OK

INTERMITTENTLY OPEN BODY CHASSIS ELECTRICAL (BCE) TEST, BODY CHASSIS ELECTRICAL PINPOINT TEST REPLACE STOP LAMP SWITCH

RAN BRAKE SWITCH

HARD SHIFTING OUT OF PARK. TESTED AND REPLACED STOP LAMP SW ASSY TO CORRECT SHIFTER TO ENGAGE

208 BAD BRAKE SWITCH 28 VERIFIED VEHICLE WONT COME OUT OF PARK. CHECKED SYSTEM FUSES. ALL OK. CHECK BRAKE LIGHTS. OK. CHECKED FOR POWER TO SHIFT LOCK ACTUATOR. FOUND NO POWER FROM BRAKE LIGHT SWIT

VERIFIED R&R SHIFTER WILL NOT COME OUT OF PARK R&R SHIFTER WILL COME OUT OF PARK. PINPOINT TEST AFTER ALL PINPOINT TESTS R&R BRAKE LAMP SWITCH FOR BAD INTERNAL CONTACT RETEST OK. M TIME REQUESTED FOR

REPLACE BRAKE LAMP SWITCH

PIN MISSING OK AND FOUND BRAKE LIGHT SWITCH LOOSE PIN WAS MISSING. INSTAL LED PIN.

VERIFY SHIFTER NOT COMING OUT OF PARK. ELECTRICAL SYSTEM DIAG AND FOUND OPEN STOP LAMP SWITCH. REPLACE STOP LAMP SWITCH AND RECHECK SHIFTER COMES OUT OF PARK OK.

BRAKE SWITCH RAN THROUGH DIAG. REPLACED BRAKE SWITCH

VERIFIED CONCERN RAN PP TEST CHECKED ELECTRICAL CONNECTIONS ON BRAKE LIGHT SWITCH FOUND OUT OF ADJUSTMENT ADJUSTED SWITCH TESTED COULD NOT ADJUST ENOUGH R & R SWITCH RECHECKED OK

OPEN CIRCUIT 28 TEST TRACE AND CHECK WIRING REMOVE AND REPLACE SWITCH TEST OK

CC 42 IN 3400 WARR REPLACED BRAKE LAMP SWITCH

TEST SYSTEM PINPOINT FOUND BRAKE SWITCH HAS INTERMITTANT OPEN REPLACED SWITCH AND RETEST OK

OPEN SWITCH STOP LAMP REPLACE

TESTED AND REPLACED BRAKE LIGHT SWITCH.

SPW ON BRAKE LAMP ON AND OFF SWITCH. VERIFIED CONCERN. LUCKS DIAGNOSIS. PINPOINT TESTED. BRAKE LAMP SWITCH SHORTED INTERNALLY/KEPT BLOWING

INTERNAL DEFECT IN BRAKE SWITCH SWITCH STOP LAMP REPLACE

DIAG R&R PARK BRAKE SWITCH KW

808 VERIFIED CURT CON CIRCUIT WGS QUICK TEST NO CODES PRES PERFORMED PINPOINT TEST FOUND BRAKE SW BAD REMOVED AND REPLACED OKED OPEN OK ATT

STOP LAMP SWITCH IS DEFECTIVE. REPLACE SWITCH.

VERIFIED CONCERN. INTERMITTENTLY SELECTOR WOULD NOT GO INTO REVERSE. WGS TEST, NO CODES. CARRIED OUT PINPOINT TEST FOUND SWITCH SLOW TO RESPOND IF AT ALL. WHILE MONITORING PIDS. R&R SWITCH TEST OK

800 SWITCH SHORTED. DID PP. REPLACE 800 SWITCH PER PPT, TECH 808

STEERING COLUMN DASH DIAGNOSIS. INSTALLED CLIP AND SPACER ON BRAKE SWITCH (PARTS MISSING).

BRAKE SWITCH LEFT HANGING. REINSTALLED BRAKE SWITCH AND BUSHING. REPLACED R PIN.

INOP WIRING ASSEMBLY REPAIR

VERIFIED CONCERN NGS DIAG MONITOR PIDS FOR 800 AND REPLACE BRAKE LAMP SW RECHECK OPERATION AND RETEST SYSTEM OK

STOP LAMP SWITCH INOP SWITCH STOP LAMP REPLACE

REMOVE STEERING COLUMN TO INSPECT SHIFT LEVER. USE DVM TO CHECK VOLTAGE AT SHIFT INTERLOCK. IV AS PUSH DOWN ON PEDAL. < 12V AND THE NEXT TIME PUSH ON BRAKE PEDAL. 12V INITIALLY. R&R 800 SWITCH

28 WARR CHECK OUT TEST CIRCUIT REPLACE BRAKE LITE SWITCH

FAULTY BRAKE PEDAL POSITION SWITCH REPLACE WITH NEW
 180 VERIFY OPERATION WONT COME OUT PARK CHECK CIRCUIT 9 10 LG OG OG LB NO BRAKE LIGHTS CHECK CIRCUIT AT BRAKE LIGHT SWITCH FOR POWER CIRCUIT W01 WH YE OK CHECK CIRCUIT NO LG NO POWER AT TIMES FOUR
 PERFORM BCC DIAGNOSIS, PERFORM PINPOINT, NCS DCL, FOUND OPEN CIRCUIT IN BRAKE LAMP SWITCH, REPLACE SWITCH, RECHECK, OKAY.
 PERFORM ELEC PINPOINT TEST, AND REPLACE BOO SWITCH. RETEST
 RSR BRAKE LIGHT SWITCH
 OK VERIFIED WONT COME OUT OF PARK, TRACED TO FAULTY BRAKE LIGHT SWITCH REPLACED SWITCH
 VERIFIED CONCERN, HARD TO DUPLICATE. R AND R STOP LAMP SWITCH LOWER STEERING COLUMNS REPLACE SHIFT INTERLOCK
 STEERING COLUMN DASH SWITCH DIAG TO TEST THE SHIFT LOCK SYSTEM FOUND STOP LAMP SWITCH TO HAVE OPEN REPLACED SWITCH AND RETESTED OK ROAD TESTED OK
 SW18 WONT ALWAYS COME OUT OF PARK WARR. INSPECT BRIGHT SW. OPERATION INTERMITTANT RSR BRK. LIGHT SW. RE TEST NUMEROUS TIMES, OK
 CHECKED AND WILL NOT COME OUT OF PARK, ORDERED BRAKE LIGHT SWITCH REMOVED AND REPLACED BRAKE LIGHT SWITCH AND OPERATING NORMAL
 TEST AND REPLACE BRAKE LIGHT SWITCH
 13488 28 MD 8006 VERIFY INTERMITTANT CONCERN. BCC DIAG. PINPOINT TEST, FOUND INTERMITTANT OPEN IN BRAKE SWITCH. R/J NEW SWITCH,
 DEFECTIVE BRAKE LAMP SWITCH. CHECKED AND REPLACED BRAKE LAMP SWITCH.
 FAULTY BRAKE LITE SWITCH IN TIME TO DIAGNOSE AND PINPOINT INTERMITTANT SWITCH OPERATION, INSTALL AND RETEST OK.
 INSPECTED AND FOUND STOP LIGHT SWITCH AND CLIP BAD. REMOVED AND REPLACED, ALL OK
 308 TEST SWITCH AT BRAKE PEDAL. REMOVE AND REPLACE SWITCH AND RECHECK.
 42 1940 P01 OK OUT AND REPLACE STOP LIGHT SWITCH
 TECH 127 VERIFIED CONCERN. RAN CASE, NO CONCERNS FOUND. PINPOINT TEST A1, CK POWER, GROUND AND CONTINUITY. ALL OK. REPLACE SHIFT LOCK ACTUATOR AS PER PINPOINT TEST. REMOVED STEERING COLUMN AND REPLACED
 9812 PERFORMED STR COLUMN AND DASH ASBY SWITCHES DIAG. P P TEST, REPLACED BRAKE LAMP SWITCH RETEST OK OK C28
 TEST & REPLACE BRAKE LIGHT SWITCH
 CHECKED STOP LAMP SWITCH CHECKED WIRES AND CONNECTORS NO PROBLEM FOUND
 1888 TEST BRAKE LIGHT SWITCH AND SYSTEM FOUNE BAD SWITCH REPLACE SWITCH AND RETEST OK
 2124 R/JN NCS CODES 18342 BOO SWITCH FAILURE R/JN PINPOINT TESTS AND REPLACE BOO SWITCH RETEST AND CLEAR CODES OK
 SECURE STOP LIGHT SWITCH BRACKET
 VERIFY CONCERN FOUND REAR BRAKE LIGHT INOP AT TIME 8 SHIFTER WILL NOT GET OF GEAR CHECK ALL FUSE & CHECK LINKAGE FOUND BOO SWITCH NOT RESPONDING AT TIME CHECK HARNESS PASS, REPLACE BOO SWITCH RE TEST
 CCC P01 VERIFIED CONCERN. MONITORED PEDS AND FOUND BOO SWITCH OPERATING. PUSHED DOWN A LITTLE HARDER ON PEDAL AND IT WOULD COME OUT OF PARK. REPLACED BRAKE ON/OFF SWITCH AND VERIFIED REPAIR
 RAN PIN POINT FOUND BRAKE ON/OFF SWITCH BAD. R R SWITCH RETESTED OK
 INSPECTED AND FOUND A LOOSE WIRE TO THE BRAKE LIGHT SWITCH REPAIRED WIRE AND RETESTED
 CHECK PROBLEM OUT/REPLACE PARK BRAKE SWITCH ASSY
 CLIP WAS MISSING
 REPLACE THE STOP LAMP SWITCH
 25 WILL NOT SHIF FROM PARK INSPECTED AND FOUND BRAKE LIGHT SWITCH RETAINING CLIP MISSING AND SWITCH CAME OFF BRAKE PEDAL REINSTALLED SWITCH AND INSTALLED NEW RETAINING CLIP RETESTED OK.
 FOUND VEHICLE WONT COME OUT OF PARK. FOUND STOP LAMP SWITCH BAD. REPLACE SWITCH, RECHECK OPERATION, OK.

CC 28 BAME PART# 13488 VERIFIED CONCERN, ALSO NOTICED THAT THE BRAKE LIGHTS DID NOT WORK. PIN POINT TESTED BRAKE SWITCH AND FOUND THAT IT HAD
 17 BIT OPEN IN BRAKE LIGHT SWITCH DIAG SHIF LOCK NOT RELEASING, NO SIG FROM BRAKE SW REPLACE BRAKE SW & RETEST OK OPERATION OK.
 BASIC ELECTRICAL TEST REPLACE BRAKE SWITCH
 BRAKE LIGHT SWITCH DEFECTIVE OPEN CIRCUIT. REPLACE DEFECTIVE BRAKE LIGHT SWITCH BRAKE LIGHTS WERE INOP AND GEAR SHIFTER WOULD NOT COME OUT OF PARK.
 INSPECT THE SHIF LOCK CONCERN CIRD THE FUSE, GROUND AND SWITCH AND RSR SWITCH
 TEST OUT REPLACE SWITCH
 INSPECT SHIF LOCK OPERATION, WORKING OK AT THIS TIME, INSPECT BRAKE LIGHT OPERATION, INSPECT FUSE F2, 16, INSPECT C278 AND
 N88 TEST AND CODE SUBJECT SYSTEM DIAG, PINPOINT TESTED, NECESSARY TO REPLACE BRAKE LIGHT SWITCH INOP RETESTED
 SHIFTER WILL NOT COME OUT OF PARK UNLESS BRAKE PEDAL IS DEPRESSSED DOOR LOCKS WILL NOT CYCLE TO LOCK UNLESS GEM MODULE SEES BRAKE PEDAL RELEASED RAN VIN OVER OASIS NO MESSAGES PINPOINT TESTED TESTED N4
 FOUND VEHICLE HAS NO BRAKE LIGHT OPERATION CHECKED FOR POWER AT BRAKE SWITCH POWER CHECKED OK TEST BRAKE SWITCH AND FOUND OPEN IN SWITCH REPLACED SWITCH AND ROAD TEST OK
 CCC P01 CC 42 CAUSAL 13488 VERIFY CONCERN. FOUND BRAKE PEDAL POSITION SENSOR SWITCH IS INTERMITTENTLY INOP. REPLACED SWITCH AND VERIFIED NORMAL SHIFTER OPERATION.
 BAD CONNECTION AT BRAKE LIGHT SWITCH REPAIRED CONNECTION.
 BRAKE LIGHT SWITCH INOP AT TIMES TEST CIRCUITS FOUND BRAKE SWITCH TO BE INTERMITTANT REPLACED SWITCH AND RETESTED OK
 TESTING FOUND FAULTY STOP LIGHT SWITCH
 ELECTRONIC TRANSMISSION DIAGNOSIS DIAGNOSIS
 VERIFIED CONCERN. FOUND LOOSE CONNECTOR TO SHIF T INTERLOCK CONTROL. REPAIRED WIRING PROBLEM. R R CHECKED, ALL O.K. AT THIS TIME.
 OK OUT WIRE UNHOOK BY BRAKE SWITCH
 VERIFIED CONCERN, FOUND FAULTY SHIF LOCK ACTUATOR. REPLACED ACTUATOR
 STOP LITE SWITCH INOP AT TIMES REPLACED SWITCH FOR TRANS CONCERN. TEST AFTER SHIFTER WORKS NORM NOW
 DIAGNOSIS TIME TESTED AND REPLACED BRAKE LIGHT SWITCH RETEST 8784
 BRAKE LIGHT SWITCH STEERING COLUMN DASH SWITCH ASSEMBLES DIAGNOSIS
 DIAG CONCERN NO COMING OUT OF PARK PINPOINT TEST REPLACE BRAKE SWITCH
 26 TRIED SHIF HANDLE WOULD NOT MOVE CHECK BRAKE LIGHT SWITCH FOUND CONNECTOR LOOSE REFASTEN CONNECTOR AND TRY SHIF HANDLE WORKS OK
 VERIFY CONCERN FOUND BRAKE SWITCH AT FAULT. REPLACE AND RECHK OKAY.
 TEST AND REPLACE SHORTED BRAKE SWITCH
 GEM MODULE CHECK PASS BEC CHECK PASS CHECK P108 ORDERED BRAKE SWITCH DCL REPLACED BRAKE SWITCH RE CHECK PASS
 CONFIRM TEST BRAKE RATCHET NOT WORKING PROPERLY REC TO REPLACE SWITCH, RMEC TO REPLACE SWITCH RETEST
 4008 DIAG SHIF LOCK R/JN PINPOINT ON HARNESS REPLACE STOP LITE SWITCH HAVE TO PUSH TOO HARD TO RELEASE SHIF LOCK

SWITCH STOP NOT SHIFTING OUT PARK SWITCH STOP LAMP REPLACE
FOUND BRAKE LIGHT SWITCH MALFUNCTIONING AND SOLENOID REPLACED SWITCH AND SOLENOID; RETESTED BY SERVICE DIRECTOR; R/R STEERING COLUMN TO LUBE SHIFT SHAFT INSIDE COLUMN
485 BRAKE SWITCH INTERNAL OPEN CIRCUIT INSPECT AT TEST BRAKE SWITCH AND CIRCUITS PERFORMED PINPOINT TEST REPLACED BRAKE SWITCH AND RETEST OK
VERIFIED CONCERN AND PERFORMED PIN POINT TESTS. REPLACED BRAKE LAMP SWITCH. MY TIME TO PERFORMED PIN POINT TEST IN SHOP MANUAL.
VERIFIED VEHICLE WONT SHIFT OUT OF PARK. CHECK BRAKE LIGHTS TO VERIFY PROPER OPERATION. CHECKED ALL FUSES. CHECKED FOR SIGNAL AT SHIFT INTERLOCK SOLENOID. DETERMINED NO SIGNAL. CHECKED WIRING. FOUND B
13485A 284ND VERIFY CONCERN. TRANS SHIFTER HARD TO REMOVE FROM PARK AT TIMES. PERFORM ELECTRICAL DIAG. MONITOR BRAKE SWITCH
REPLACE STOP LAMP SWITCH ASY
VERIFY CONCERN. REPLACE BRAKE LIGHT SWITCH
DIAG AND REPLACE BRAKE SWITCH. RETEST 6288
VERIFIED CUSTOMERS CONCERN. REPLACED BRAKE LIGHT SWITCH
12 OPEN CIRCUIT (284ND D2 3H14A 1220A 1.) R AND 1 STEERING COLUMN TEST SHIFT LOCK ACTUATOR FOUND NO VOLTAGE AT ACTUATOR PINPOINT TESTS TO BRAKE LAMP SWITCH CONNECTOR NOT MATED TO BRAKE LAMP SWITCH

OK. FOR CONCERN. FOUND THAT TRUCK NOT WANTING TO COME OUT OF GEAR AT TIMES. DID PIN POINT TEST AND FOUND CONCERN TO BE IN BRAKE LIGHT SWITCH. REMOVE BRAKE LIGHT SWITCH AND INSTALL NEW SWITCH. ALL O.K
CHECK AND REPLACE BRAKE LIGHT SWITCH AND SHIFT LOCK ACTUATOR
BRAKE LAMP SWITCH INTERMITTANT OPEN INTERNALLY REPLACED BRAKE ON AND OFF SWITCH RETEST

WEEK CONNECTION REPAIRED WEAK CONNECTORS AT BRAKE SWITCH INTER LOCK
FAULTY BRAKE LAMP SWITCH SWITCH STOP LAMP REPLACE
CHECK FOR HARD TO GET OUT OF GEAR. ADJUSTED BRAKE SWITCH. R/R TEST, OK.
WONT COME OUT OF PARK SWITCH STOP LAMP REPLACE
BRAKE SWITCH AND OPEN WIRE SSC (QUICK TEST) DIAGNOSIS, RECORDER MONITOR ROAD TEST, REPLACE STOP LAMP SWITCH REPAIR OPEN IN WIRE. R/R STEERING COLUMN FOR ACCESS AND REPLACE SHIFT MOTOR
RUN DASH SWITCH DIAG. REPAIR LOOSE CONNECTOR AT BRAKE LIGHT SWITCH.
REPL BRK SWITCH AND RECK CIRCUITS; STILL HAS PROB. NEEDS FUSE BOX. AS PER STORE OWNER OK TO INST F USE BOX FROM STK UNIT TO GET CLUT ON THE ROAD. XREF RD 17287
388 CHECK SHIFTER LOCK OUT CIRCUIT TRACE CIRCUIT 310 ACCESS DASH AND REPAIR WIRE CONNECTOR AT BRAKE PEDAL POSITION SWITCH CONNECTOR 279 CIRCUIT 618 RD LG CONNECTOR NOT FULLY SEATED
BRAKE LIGHT SWITCH STICKING REPLACED SWITCH O.K. WORK
FAULTY BRAKE LAMP SWITCH SWITCH STOP LAMP REPLACE
425 INOP. SHORTED SWITCH BLOWN FUSE. NBS TESTING OF BCE CIRCUITS. CODE 81372 PRESENT PINPOINT TESTING. R/R STEERING COLUMN SHROUD, FOR ACCESS. REPLACE SHORTED STOP LAMP SWITCH. REPLACE TWO BLOWN F
1 REPLACED BRAKE SWITCH

INTERNAL SWITCH STOP LAMP REPLACE
CHECKED AND REPLACED BRAKE LAMP SWITCH
CHECKED AND PERF. WDS DIAG. NO CODES FOUND IN SYL. PERF. PIN POINT TEST AND REPLACED FAULTY BRAKE LAMP SWITCH INTERLOCK SWITCH
WIRING PULLED LOOSE AT STOP LIGHT SWITCH AND FUSE BLOCK. REINSTALL STOP LIGHT WIRING AT FUSE BLOCK. INSPECTED, FOUND NO POWER OUT TO STOP SHIFT INTERLOCK SOL. FROM BRAKE LIGHT SWITCH. FOUND BRAKE SWIT
VERIFIED CONCERN REPLACED BRAKE LIGHT SWITCH AND FUSE
TESTED VEHICLE FOR OPERATION. PERFORMED DIAGNOSTIC TESTS ON SHIFT INTERLOCK. ACCESSSED AND REPLACED SHIFT INTERLOCK SOLENOID. INSTALLED NEW BRAKE LAMP SWITCH. RETESTED FOR OPERATION OK
1 CHECKED AND REPLACED BRAKE LIGHT SWITCH 2 WARNED VEHICLE
TR BCE DIAG PIN PT R AND L COLUMN FOR ACCESS TO TRACE FOUND NO PWR GOING TO SHIFT LOCK ACTUATOR PIN PT FOUND FAULT BRAKE PEDAL SWITCH REPLACE AND RESET ALL OK AT THIS TIME BRAKE LIGHTS WORK ALL OK
OK FUSES FOUND FUSE #44 SUP BLOWN OK FOR SHORT TO GROUND FOUND STOP LT SWITCH INTERNAL SHORT TO GROUND REPLACE STOP LT SWITCH REPLACE FUSE OK OPERATION OK
B VERIFIED CONCERN. WILL NOT SHIFT OUT OF PARK. PERFORMED BELTTEST NO CODES. REMOVED UPPER AND LOWER STEERING COLUMN FROM PANEL. CHECKED FOR POWER AND GROUND AT SHIFT INTERLOCK. FOUND POWER CIRCUIT
1982 CHECK SYSTEM FOUND OPEN IN BRAKE LIGHT SWITCH. R & L AND REPLACE SWITCH. RETEST SYSTEM OK. 42 13480.
FOUND BRAKE LIGHT SWITCH STICKING SOMETIMES
SWITCH LOOSE ADDITIONAL. MISC. REPAIRS
IF ELEC DIAG MONITORED PIDS PERFORMED PIN POINT TESTS. INSPECTED WIRING CONNECTOR R/R BRAKE SWITCH AND REPLACED WITH NEW ONE RETESTED OK
BOO SWITCH WAS OFF THE PEDAL. REINSTALLED BOO SWITCH. RETESTED ALL GOOD
VERIFY. OK SHIFT INTERLOCK OPERATION AND BRAKE LIGHT CIRCUIT. SWITCH WILL NOT ALWAYS ENERGIZE SHIFT INTERLOCK. BRAKE LIGHTS OPERATE NORMALLY. OK OASIS AND CALL TECH HOTLINE FOR INFO (KRECY01) SUBST

TECH_TXT2
ENTER OK MT TO DIAGNOSE

XXXXXXXXXXXXXXXXXXXX

R CONSULT WITH JP. RETEST FOUND CONCERN NO LONGER HAPPENS AT THIS TIME. THANKS JEFF RUSH 488

TTANTLY WORKING. CALLED TECH HOTLINE 800HP24. TOLD TO CHECK SPLICES IN CIRCUIT #16. INSTRUMENT PANEL WIRING HAS A OPEN CIRCUIT. RAN A NEW WIRE AROUND SPLICE AND RETEST OPERATION OK. M TIME FOR NO LABOR OF

, REPLACED, RETEST, OK

RED BROKEN WIRE RETEST SHIFTER ACTUATOR W/O BRING NORMAL. NECESSARY TO REPLACE BRAKE SWITCH AND ONLY CUT OFF SWITCH DUE TO SHORTED WIRE. VEHICLE WORKING PROPERLY

ARE SWITCH. RETESTED ALL OK OPERATING TO SPECS

ER TO PIN 3 CIRCUIT 22 LEAD WIRE. RETEST FUSE 4 GAIN ACCESS TO LOWER DASH AND KICK PANEL. RER FUSE BLOCK DISCONNECT CONNECTOR. 370A OHM CIRCUIT

REPAIRED TERMINAL IN BRAKE SWITCH CONNECTOR AND REMOVED AND REPLACED BRAKE SWITCH AND SHIFTER LOCK SOLENOID. NO OTHER PROBLE FOUND. AFTER REPAIR COMPLETE, PROBLEM WAS IN CIRCUIT

ND. CHECK POWER AT BRAKE LIGHT SWITCH TO RELEASE. NONE. REPLACE SWITCH AND RETEST. WORKS NOW.

1000-000 4831

WAS REASSEMBLED AND ADJUSTED BRAKE SWITCH, NOW SHIFTING THROUGH ALL GEARS NORMALLY

TO REPAIR, SPlice 100 ALONG THE FIRE WALL. PARTIAL CONNECTION. REPAIR. ACTUATOR ALSO DEFECTIVE. REPLACE ACTUATOR.

RE LOWER KICK PANEL BELOW

ON THE PEDAL, WAS CRACKED. REPLACE SWITCH. AFTER REPLACING CRACKED SWITCH TRACKED DOWN LOCK ACTUATOR FOR SHORT. WOULD NOT DISENGAGE SHIFT LEVER. R AND R STEERING COLUMN AND REPLACE

1963-68 4832

WAS LIGHT SWITCH, DISCONNECT C12; STILL BLEW FUSE. DISCONNECT C14; SHORT OUT. BACK PROBE WIRE. R&L DIST BOX; CHAPPED WIRE FROM DIST BOX AT DIST BRACKET. REPAIR, RETEST, OK. REINSTALL ALL MODUL

E BRAKE ON OFF SWITCH AND FOUND IT TO BE SHORTED INTERNALLY. I THEN REPLACED THE BRAKE ON OFF SWITCH AND RETESTED ALL IS WELL.

E LIGHT SWITCH FROM NEW TRUCK, FORCED CONCERN. REPL. BRAKE LIGHT SWITCH, M TIME III FOR REPL. SHIFT LOCK ACTUATOR AND PW TESTS

REPAIR OK. REINSTALLED SHIFT INDICATOR PRNDLE DUE TO IT NOT BEING IN PLACE.

ENGAGING TRAME IN P THIS IS NORM OP AND

ON TO LOCK ACTUATOR. PERFORMED WIRING PINPOINT TEST AND FOUND A BAD BRAKE SWITCH. REPLACED THE BRAKE SWITCH. RETESTED OK.
INACCURATE PINPOINT TEST IN MANUAL.

NO CODES

NO SHORTED BRAKE LIGHT SWITCH REPLACE BRAKE LIGHT SWITCH REVERIFY COMES OUT PARK

ED SWITCH, PROBLEM STILL THERE. INSTALL BRAKE ON OFF SWITCH, RETEST. OK AT THIS TIME.

STST PARK FOUND AFTER SEVERAL ATTEMPT OF SHIFTING FOUND LEVER ACTUATOR NOT RESPONDING R/R STEERING COVER TO BE ABLE TO REMOVE STEERING COVER TO BE ABLE TO R/REPLACE STEERING LOCK ACTUATOR CHECK SYST TO VI

POWER AND SWITCHING NEED TO ORDER BRAK

1000-000 4004

BRK SWTCH CONNECTOR DAMAGED. REPAIRED TERMINALS AND RECHECKED. VERIFIED VEHICLE SHIFTING OUT OF PARK.

H RECLINE CONNECTOR RETEST SHFT LOCK ACTUATOR TEST OK BRAKE LAMPS OK CC CHECKED BY TECH
.CC 42

US25. CLEAR CODE. RETEST SCE CIRCUITS. 78

CH INTERNAL SHORTED. REPLACED SWITCH, SYSTEM OK AT THE TIME.

NTERM OPEN PERFORMED PINPOINT TESTS, FOUND BRAKE LAMP SWITCH INTERM OPEN DN CIRCUIT. REPLACED BRAKE LAMP SWITCH. VERIFIED REPAIR. OK

TTUTE KNOWN GOOD SWITCH PER HOTLINE. OK. REPLACED BRAKE LIGHT SWITCH AND RECHECK OPERATION OK. ABNORMAL DIAG REPAIR TIME FOR INTERMITTENT CONCERN

CUST_DXT

CUSTOMER STATES GEAR SELECTOR LOOKS IN PARK MODE AT TIMES HAVE TO PLAY WITH TO DISENGAGE HEARS CLICK SEE NOTE REPORT

CUSTOMER REPORTS TRANS VERY HARD OR WONT COME OUT OF PARK AT

STILL NOT COMING OUT OF PARK PROPERLY SHOP FOREMAN VERIFIED COMPLAINT

CUST STATES HAS TO STRUGGLE TO GET SHIFTER OUT OF PARK, BLAMS BRAKE, OR JIGGLES MODULE UNDER DASH TO GET FREE WILL NOT COME OUT OF PARK

SHIFTER SOMETIMES WILL NOT GO INTO GEAR

CHK SHIFTER WONT COME OUT OF PARK NO BRAKE LIGHTS ARE

C IS STILL WILL NOT SHIFT OUT OF PARK AT TIMES. HAS TO SMASH BRAKE PEDAL TO FLOOR IN ORDER TO SHIFT OUT OF PART. HISTORY

STATES SHIFTER WONT COME OUT OF PARK, ADVISE

CHECK CAUSE OF NOT BEING ABLE TO GET OUT OF PARK AT TIMES

WILL NOT COME OUT OF PARK

WHEN TRYING TO PUT INTO DRIVE FROM PARK SHIFT LEVER WILL HANG UP AT TIMES IT TAKES 2-10 TIMES TO GET IT INTO DRIVE CHECK AND REPORT

ON VEHICLE WILL NOT SHIFT INTO PARK

CUSTOMER STATES THE TRUCK WILL NOT COME OUT OF PARK.

C IS CAR NOT PUT INTO GEAR FROM PARK. BRAKE LIGHTS DO NOT WORK.

PO1 SEE HISTORY (CHV) CONTINUES TO HAVE INTERMITTANT CONCERN FOR NOT BEING ABLE TO SHIFT OUT OF PARK. OWNER HAS

REPAIR WONT COME OUT OF PARK HAVE TO PUT IN NEUTRAL TO CRANK

CUSTOMER STATES THAT VEHICLE WILL NOT SHIFT OUT OF PARK

CHECK BRAKE PEDAL HAS TO BE PUSHED HARD

WONT COME OUT OF PARK

STUCK IN PARK, THEY BROKE IT, W/ SHIFT WITHOUT STEPPING ON BRAKE

PO1 C-S VEHICLE HARD TO GET OUT OF PARK AT TIMES

CUST STATES SHIFTER STICKS IN PARK TECH 044

CUSTOMER STATES: CANT GET SHIFT GEAR OUT OF PARK

OK CUSTOMER CANNOT GET TRUCK OUT OF PARK, TOW IN PARKED ON SERVICE DRIVE. CUSTOMER IS IN LOANER CAR.

CUSTOMER STATES THE SHIFT LEVER STICKS IN PARK AT TIMES. INSPECT AND ADVISE.

OK SHIFTER WONT COME ALL THE WAY BACK

OK SHIFTER HARD TO GET OF GEAR AT TIMES

WILL NOT COME OUT OF PARK GETS STUCK IN GEAR

WILL NOT RELEASE OUT OF PARK INTERMITTANT PLAYED WITH BRAKE SWITCH THEN RELEASED

C S HE COULD NOT GET VEHICLE OUT OF PARK...AND THEN SUDDENLY DRIVER SIDE REAR BRAKE LINE BUBB

CUSTOMER STATES THAT TRANS WILL NOT COME OUT OF PARK AT TIME

VEH WILL NOT SHIFT OUT OF PARK WHEN RUNNING

SHIFTER WILL NOT COME OUT OF PARK

TRANS WONT COME OUT OF PARK DELAYS INTO GEAR

INTERM WONT COME OUT OF PARK NO PATTERN TO IT

HARD TO GET OUT OF PARK NEED TO PUSH PEDAL HARD TO FLOOR

CUSTOMER STATES VEH WILL NOT COME OUT OF PARK

CUSTOMER STATES HAVE TO PUSH HARD ON BRAKE PEDAL TO GET OUT OF PARK

S HE CK ADN ADV TOW IN VEH WILL NOT SHIFT OUT OF PARK

CHECK ADVISE HARD TO GET OUT OF PARK

AT TIMES UNABLE TO REMOVE FROM PARK

TRUCK WILL NOT COME OUT OF PARK

CUSTOMER STATES VEHICLE WILL NOT COME OUT OF PARK INTERNAL

PO1 THE VEHICLE IS HARD TO SHIFT OUT OF PARK

DASH HARD TO GET OUT OF PARK

PO1 CUST STATES HARD TO GET OUT OF PARK INTERMITTANTLY

CUSTOMER STATE BRAKE PEDAL HAS TO BE PLAYED WITH TO GET VEHICLE OUT OF PARK

CHECK VEHICLE WILL NOT COME OUT OF PARK

HARD TO SHIFT OUT OF PARK

CUST STATES SHIFT LEVER HARD TO GET INTO GEAR

CUST STATES VEHICLE WON T COME OUT OF PARK

CUST STATES SHIFTER STICKS IN PARK

SHIFTER BIDS UP COMING OUT OF GEAR.

CUSTOMER STATES THAT HE CAN NOT SHIFT FROM PARK INTERMITTENTLY

AREA_CD	CNT_PTY_SOL	WPK_CD	AWS_VLC	WPK_CD	TBL_FLG
201	USA	V47	F7	011	
703	USA	V47	F7	011	
807	USA	V47	F7	011	
724	USA	V47	F7	011	
508	USA	V47	F7	011	
801	USA	V47	F7	011	
385	USA	V47	F7	011	
218	USA	V47	F7	011	
280	USA	V47	F7	011	
705	USA	V47	F6	011	
509	USA	V47	F7	011	
282	USA	V47	F7	011	
680	USA	V47	F7	011	
488	USA	V47	F7	011	
712	USA	V47	F7	011	
820	USA	V47	F7	011	
918	USA	V47	F7	011	
285	USA	V47	F7	011	
715	USA	V47	F7	011	
810	USA	V47	F7	011	
410	USA	V47	F7	011	
315	USA	V47	F7	011	
251	USA	V47	F7	011	
310	USA	V48	F7	011	
715	USA	V47	F6	011	
291	USA	V47	F6	011	
989	USA	V47	F6	011	
450	USA	V47	F7	011	
979	USA	V47	F7	011	
305	USA	V47	F6	011	
989	USA	V47	F7	011	
734	USA	V47	F6	011	
234	USA	V47	F7	011	
715	USA	V47	F6	011	
318	USA	V47	F6	011	
680	USA	V47	F7	011	
757	USA	V47	F6	011	
419	USA	V47	F6	011	
341	USA	V47	F6	011	
814	USA	V47	F7	011	
348	USA	V47	F6	011	
684	USA	V47	F6	011	
847	USA	V47	F6	011	
877	USA	V47	F7	011	
291	USA	V47	F6	011	
381	USA	V47	F7	011	
885	USA	V47	F7	011	
282	USA	V47	F7	011	
386	USA	V47	F7	011	
704	USA	V47	F6	011	
888	USA	V47	F7	011	
413	USA	V47	F7	011	
815	USA	V47	F7	011	
872	USA	V47	F6	011	
848	USA	V47	F6	011	
930	USA	V47	F6	011	
818	USA	V47	F6	011	

CUST STATES KEY STUCK IN IGNITION
LHS CK GEAR SHIFTER WILL NOT WORK PROPERLY.
CHECK GEAR SHIFTER LEVER WONT COME OUT OF PARK
CHECK HARD TO MOVE SHIFTER OUT OF PARK
ALSO STATES SHIFTER WONT COME OUT OF PARK AT TIMES
CUSTOMER STATES THE VEHICLE WONT COME OUT OF PARK
VEHICLE WONT SHIFT OUT OF PARK
OWNER CLAIMS THAT TRANS HAD TO GET OUT OF PARK.
CUST STATES THAT THE TRUCK WILL NOT COME OUT OF PARK
CUST STATES VEH WILL NOT COME OUT OF PARK

STUCK IN PARK AT TIMES

CUSTOMER SAID TRUCK IS HARD TO SHIFT OUT OF PARK
CUST STATES AT TIMES VEH WILL NOT COME OUT OF PARK
CUSTOMER STATES SHIFTER WILL NOT COME OUT OF PARK CC POT
CUST STATES INTERMITT FUSE WILL BLOW AND IS UNABLE TO GET TRANS SHIFTER LEVER OUT OF PARK OR ENGAGE 4X4 UNLESS REPLACE FUSE
CUSTOMER STATES THAT THE VEHICLE WILL NOT SHIFT OUT OF PARK CHECK AND ADVISE
CUSTOMER STATES VEH WONT SHIF OUT OF PARK
CHECK SHIFTER DOESNT COME OUT OF GEAR ADVISE
CUST STATES INTERMITT THE VEH DOES NOT WANT TO COME OUT OF PARK, HAVE TO WIGGLE THE KEY AND SHIFTER TO GET IT TO POP
CUSTOMER STATES CANNOT SHIF FROM PARK
TOW IN, VEHICLE WILL NOT GO INTO GEAR
VEHICLE WILL NOT COME OUT OF GEAR
CUSTOMER STATES VEHICLE WONT SHIF FROM PARKING UNLESS IS IN NEUTRAL WHEN START.
THE SHIFTER WILL NOT COME OUT OF PARK INTERMITTENTLY.
CUST STATES THAT TRUCK WILL NOT COME OUT OF PARK
CHECK FOR REASON THE TRANS WILL NOT SHIFT OUT OF PARK
LOCKS IN PARK
CAN NOT PULL SHIFTER LEVER OUT OF PARK
VEHICLE WILL NOT COME OUT OF PARK.
CUSTOMER STATES THAT VEHICLE WILL NOT COME OUT OF PARK
GEAR SELECTOR WILL NOT REMOVE FROM PARK TID
C B WONT COME OUT OF PARK AT TIMES
CUST STATES GEAR SHIFTER DOES NOT COME OUT OF PARK
VEHICLE WILL NOT GO FROM PARK INTO GEAR

CUSTOMER CONCERN OF TRUCK NOT COMING OUT OF PARK INTERMITTENTLY
CORRECT HARD TO GET OUT OF PARK
VEH WONT SHIF OUT OF PARK AT TIMES
CHECK SHIFTER INNER LOCK ON SHIFTER WOP WILL NOT COME OUT OF GEAR
CST STATES THE VEHICLE WILL NOT COME OUT OF PARK.
OFFICER COULD NOT GET VEHICLE TO SHIF FROM PARK. CALLED ROADSIDE GOT TO SHIF. NOW NO POWER WINDOWS
CUST STATES SHIFTER WONT COME OUT OF PARK CK AND ADV
CUST STATES SHIFTER IS GETTING STUCK CK AND ADV
CHECK FOR NOT COMING OUT OF PARK
CK CUST SAYS WILL NOT COME OUT OF PARK
VEHICLE WILL NOT GO INTO DRIVE
ANS CUSTOMER STATES CANNOT SHIF OUT OF PARK WITH ENGINE RUNNING

CUSTOMER STATES THE SHIFTER WILL NOT COME OUT OF PARK
HARD TO GET OUT OF PARK
CUSTOMER STATES HARD TO COME OUT OF PARK

CUST STATES VEH WILL NOT SHIF OUT OF PARK INTERMITTENT
C B TRANSMISSION IS HARD TO GET OUT OF PARK INTERMITTENTLY
CUST STATES VEHICLE WILL NOT RELEASE BRAKE PEDAL
CONCERN VEH WONT COME OUT OF PARK
CUST STATES THE TRUCK WONT COME OUT OF PARK AT TIMES
CHECK TRUCK WONT COME OUT OF PARK.
CUSTOMER STATES THAT TRANSMISSION WILL NOT COME OUT OF PARK.
CUST TOWED IN TRUCK WILL NOT COME OUT OF PARK

201 USA V47	F7	511
214 USA V47	F6	511
238 USA V47	F6	511
238 USA V47	F5	511
215 USA V47	F7	511
418 USA V47	F7	511
528 USA V47	F6	511
728 USA V47	F8	511
815 USA V47	F6	511
854 USA V47	F5	511
219 USA V47	F9	511
872 USA V47	F7	511
870 USA V47	F6	511
807 USA V47	F5	511
883 USA V47	F6	511
704 USA V47	F7	511
870 USA V47	F7	511
802 USA V47	F7	511
407 USA V47	F7	511
847 USA V47	F7	511
718 USA V47	F6	511
610 USA V47	F7	511
873 USA V47	F6	511
281 USA V47	F7	511
803 USA V47	F7	511
917 USA V47	F6	511
203 USA V47	F6	511
703 USA V47	F7	511
787 USA V47	F7	511
805 USA V47	F7	511
818 USA V47	F5	511
394 USA V47	F6	511
972 USA V47	F6	511
478 USA V47	F7	511
733 USA V47	F7	511
887 USA V47	F7	511
889 USA V47	F7	511
699 USA V47	F7	511
983 USA V47	F7	511
330 USA V47	F5	511
283 USA V47	F7	511
425 USA V47	F7	511
435 USA V47	F8	511
985 USA V47	F6	511
868 USA V47	F6	511
477 USA V47	F7	511
829 USA V47	F7	511
286 USA V47	F6	511
281 USA V47	F6	511
828 USA V47	F7	511
825 USA V47	F7	511
801 USA V47	F7	511
318 USA V47	F7	511
780 USA V47	F6	511
864 USA V47	F7	511
477 USA V47	F7	511
805 USA V47	F6	511
205 USA V47	F6	511
515 USA V47	F5	511
218 USA V47	F7	511
770 USA V47	F5	511
873 USA V47	F7	511

TRUCK WILL NOT COME OUT OF PARK
CUSTOMER STATES SHIFTER INTERLOCK WILL NOT WORK MUST MESS WITH BRAKES
CUSTOMER STATES WILL NOT SHIFT OUT OF PARK
P01 CK TRANS WILL NOT SHIFT OUT OF PARK W RUNNING
CUSTOMER STATES VEHICLE HARD TO GET OUT OF PARK
CK WONT SHIFT FROM PARK
TRUCK WONT COME OUT OF PARK
CUST STATES AT TIMES NOW A COUPLE TIMES SHIFTER WOULD NOT COME OUT OF PARK
SAYS HAS BEEN HAVING TROUBLE GETTING OUT OF PARK
CUSTOMER REQUESTS TRANS DIAGNOSIS WILL NOT COME OUT OF PARK
CHECK SHIFTER WONT MOVE OUT OF PARK
CUSTOMER STATES GEAR SHIFTER SOMETIMES WONT SHIFT OUT OF PARK
VEHICLE WILL NOT COME OUT OF PARK
5 TIMES SINCE TAKING DELIVERY CUST HAS NOT BEEN ABLE TO GET SHIFT LEVER OUT OF PARK
VEHICLE GEAR SHIFT WILL NOT COME OUT OF PARK
CUST STATES TRUCK WONT COME OUT OF PARK CUST REACHED UNDER DASH AND PUSHED ON SAFTY SWITCH TO GET OUT OF PARK
CK DUT WONT COME OUT OF PARK AT TIMES
CK FOR WILL NOT COME OUT OF PARK
VEHICLE WILL NOT COME OUT OF PARK. BRAKE LIGHTS DO WORK. THE TRANSMISSION SHIFT LINKAGE HAS BEEN DISCONNECTED BY
VEHICLE WONT COME OUT OF PARK
WONT COME OUT OF PARK
CK VEHICLE WILL NOT COME OUT OF BEAR
CK VEHICLE WILL NOT COME OUT OF PARK
CUSTOMER STATES VEHICLE KEEPS GETTING STUCK IN PARK, AND WILL NOT COME OUT
C S SHIFTER WILL NOT COME OUT OF PARK AT TIMES, NEEDS TO APPLY EXCESSIVE FORCE TO RELEASE
C S THE VEHICLE WONT COME OUT OF PARK WHEN VEHICLE IS STARTED B, WILL ONLY COME GO INTO DRIVE IF STARTED FROM NEUTRAL
CUST STATED THAT VEH HARD TO GET OUT OF PARK
CUSTOMER STATES SHIFTER WOULD NOT COME OUT OF PARK
WILL NOT COME OUT OF PARK AT TIMES
CUST STATES HAS TO PUT IN NEUTRAL TO START WILL NOT COME OUT OF PARK
VEHICLE WILL NOT GO FROM PARK TO DRIVE
VEHICLE WILL NOT COME OUT OF PARK
VEHICLE WONT COME OUT OF PARK.
??
QUEST STATES THE VEH WILL NOT SHIFT OUT OF PARK UNLESS YOU PRESS VERY HARD ON THE BRAKE
THE GEAR SHIFT SELECTOR WILL GET HUNG UP INTERMITTEN ADVISE
WILL NOT COME OUT OF PARK
.. CUST STATES GEAR SHIFTER WONT COME OUT OF PARK
THE VEH IS HARD TO COME OUT OF PARK
WONT SHIFT OUT OF PARK AT TIMES
CUSTOMER STATES THE SHIFTER WILL NOT COME OUT OF PARK P01
WONT SHIFT OUT OF PARK
CK PARK WOULD NOT COME OUT ONE TIME DOOR
CUST NOTES VEHICLE WILL NOT COME OUT OF PARK WHEN STEPPING ON BRAKE WITH ENGINE RUNNING HAS TO TURN KEY FORWARD ONE CLICK PUT VEHICLE INTO NEUTRAL THEN START
OWNER STATES SHIFTER WILL NOT COME OUT OF PARK AT TIMES CHECK AND ADVISE
CUSTOMER STATES SHIFTER GETS STUCK IN PARK
CAN NOT SHIFT OUT OF PARK
WONT GO OUT OF PARK
CUST REPORTS THAT VEH WOULD START BUT WOULD NOT COME OUT OF GEAR
CUST STATES CHECK SHIFT OPERATION, STICKS COMING OUT OF PARK
UNIT WILL NOT START OUT OF PARK
CHECK HARD TO SHIFT OUT OF PARK
TRANS WILL NOT COME OUT OF PARK
C S VEHICLE GETS STUCK IN PARK
SHIFTER WONT COME OUT OF PARK AT TIMES
START VEHICLE WONT COME OUT OF PARK HAS HAPPENED TWICE
CHECK AND ADVISE ON SHIFT LEVEL WILL NOT COME OUT OF PARK
CUST STATES DIFFICULT TO GET VEHICLE OUT OF PARK INTERMITTENT, CHK ADVISE
AND VEHICLE WILL NOT COME OUT OF PARK
CUSTOMER REPORTS WILL NOT COME OUT OF PARK AT TIMES
WILL NOT COME OUT OF PARK CC P01
GEAR SHIFT WONT MOVE ALL WEEK END HAD TO LEAVE VEHICLE

715 USA V47 FE 011
716 USA V47 FE 011
816 USA V47 FS 011
214 USA V47 FE 011
436 USA V47 F7 011
208 USA V47 FE 011
808 USA V47 FS 011
490 USA V47 FE 011
316 USA V47 FE 011
018 USA V47 FE 011
575 USA V47 FT 011
238 USA V47 FE 011
036 USA V47 FE 011
388 USA V47 FE 011
334 USA V47 FE 011
218 USA V47 F7 011
018 USA V47 FE 011
724 USA V47 FE 011
205 USA V47 FE 011
776 USA V47 FE 011
228 USA V47 FE 011
303 USA V47 FE 011
303 USA V47 FE 011
214 USA V47 FE 011
024 USA V47 FE 011
488 USA V47 FE 011
018 USA V47 FT 011
221 USA V47 FS 011
258 USA V47 FS 011
078 USA V47 FS 011
888 USA V47 FE 011
281 USA V47 FE 011
014 USA V47 FE 011
214 USA V47 FS 011
952 USA V47 FE 011
403 USA V47 FS 011
028 USA V47 FE 011
408 USA V47 FS 011
402 USA V47 FT 011
781 USA V47 FS 011
051 USA V47 FE 011
281 USA V47 FE 011
008 USA V47 FE 011
808 USA V47 FS 011
002 USA V47 FE 011
808 USA V47 FS 011
908 USA V47 FE 011
318 USA V47 FS 011
704 USA V47 FE 011
781 USA V47 FS 011
701 USA V47 FT 011
781 USA V47 FS 011
808 USA V47 FT 011
877 USA V47 FS 011
702 USA V47 FE 011
248 USA V47 FE 011
282 USA V47 FE 011
000 USA V47 FT 011
098 USA V47 FE 011
041 USA V47 FE 011
770 USA V47 FE 011
787 USA V47 FE 011

WILL NOT SHIFT OUT OF PARK AT TIMES
 WILL NOT ALWAYS COME OUT OF GEAR, MUST OVER RIDE TO GET OUT OF GEAR,
 CUSTOMER STATES THAT VEHICLE WILL NOT COME OUT OF PARK WHEN STARTED
 CUST STATES WILL NOT COME OUT OF PARK
 CUSTOMER STATES VEHICLE WONT SHIFT OUT OF PARK
 CUSTOMER STATES AT TIMES HARD TO SHIFT OUT OF GEAR, AT TIMES WHEN IN UPHILL, REALLY HAS TO PULL TRANS LEVER DOWN
 CUSTOMER STATES THAT VEHICLE WILL NOT COME OUT OF PARK
 CUSTOMER STATES AT TIMES WONT COME OUT OF GEAR
 C S HAS TO PUSH BRAKE ALMOST TO FLOOR TO SHIFT FROM PARK TO DRIVE. THIS IS AN INTERMITTENT PROBLEM. THE OTHER DAY IN DRIVE BUT WOULDNT MOVE, INTERMIT
 CUSTOMER STATED THAT HAD HARD TIME GETTING TRUCK OUT OF PARK HAD TO UNLOCK STEERING THEN START TO GET IN GEAR.
 AFTER STARTING WONT SHIFT OUT OF PARK

CUST STATES GEAR SHIFTER HARD TO GET OUT OF PARK INTERMITTANTLY
 CHECK WOULD NOT COME OUT OF PARK
 G B VEHICLE WONT COME OUT OF PARK WHEN PUT FOOT ON BRAKE. HAS HAPPENED TWICE LATELY.
 CHECK AT TIMES WONT COME OUT OF PARK
 VEHICLE WILL NOT COME OUT OF PARK
 OK FOR HARD TO GET OUT OF PARK AT TIMES
 OK VEHICLE HAVING TROUBLE COMING OUT OF PARK
 CHECK INTER. WILL NOT SHIFT OUT OF PARK. WORSE AFTER DRIVING
 VEHICLE WONT COME OUT OF PARK
 CUSTOMER STATES SHIFTER WILL NOT COME OUT OF PARK CMLADVICE
 CHECK TRANSMISSION SHIFTER WONT COME OUT OF GEAR AT TIMES
 Y???

SHIFTER STICKS IN PARK AT TIMES
 TRUCK WILL NOT COME OUT OF PARK
 1 WILL NOT COME OUT OF PARK AT TIMES
 HARD TO COME OUT OF GEAR
 TOW IN CUSTOMER STATES WONT COME OUT OF PARK
 CUSTOMER SAYS THE TRANSMISSION WILL NOT SHIFT UNLESS YOU PRESS THE GAS
 CUSTOMER STATES THE TRUCK WILL NOT SHIFT OUT OF GEAR
 CUSTOMER STATES SHIFTER WONT COME OUT OF PARK AFTER STARTING ENGINE.
 CUSTOMER STATES SHE COULDNT GET VEHICLE OUT OF PARK.
 CUSTOMER STATES THAT THE TRUCK WILL NOT COME OUT OF PARK
 VEH WONT GO INTO GEAR UNLESS MESSING WITH KEY FEE
 C S VEHICLE WILL NOT SHIFT OUT OF PARK
 TRUCK WILL NOT COME OUT OF PARK
 PFS CANNOT SHIFT OUT OF PARK
 VEHICLE WILL NOT COME OUT OF GEAR SOMETIMES
 OK STUCK IN PARK AND HAD TO ROCK THE TRUCK TO GET IT OUT OF PARK, HAPPENED ONLY ONE TIME
 VEH WOULD NOT PULL OUT OF PARK ADJUSTED THE BRAKE PETAL AND THEN IT WENT OUT
 SHIFTER WILL NOT MOVE OUT OF PARK
 C S TRUCK WILL NOT SHIFT OUT OF PARK

808 USA V47	FB	311	
301 USA V47	F3	311	
288 USA V47	FB	311	
718 USA V47	F5	311	
217 USA V47	FB	311	
858 USA V47	F5	311	
302 USA V47	FB	311	
388 USA V47	F5	311	
877 USA V47	FB	311	
238 USA V47	F5	311	
808 USA V47	FB	311	
303 USA V47	FB	311	
804 USA V47	FB	311	
205 USA V47	FB	311	
304 USA V47	F5	311	
231 USA V47	FB	311	
417 USA V47	FB	311	
724 USA V47	FB	311	
317 USA V47	F5	311	
208 USA V47	F7	311	
802 USA V47	F7	311	
531 USA V47	F7	311	
418 USA V47	FB	311	
207 USA V47	FB	311	
814 USA V47	F5	311	
803 USA V47	FB	311	
828 USA V47	F3	311	
880 USA V47	FB	311	
412 USA V47	FB	311	Ⓢ
348 USA V47	F7	311	Ⓢ
520 USA V47	F3	311	
704 USA V47	FB	311	
217 USA V47	FB	311	
515 USA V47	FB	311	
713 USA V47	F7	311	
828 USA V47	FB	311	
716 USA V47	F7	311	Ⓢ
713 USA V47	F7	311	Ⓢ
751 USA V47	FB	311	
812 USA V47	FB	311	
628 USA V47	F5	311	
414 USA V47	FB	311	Ⓢ
USA V47	FB	311	Ⓢ

Report Information for Result ID

99400125: Status=Finished

Request Name=PN131 2-2003 MY 13480
 Description=200 Run Date And Time=23 Apr 2003 13.09
 Completion Date And Time=23 Apr 2003 13.10
 Job Size=55 Execution Time=0
 Precalc Processing= Cut Off Date=31 Mar 2003 Load Date=21 Apr 2003

Data Selection Criteria: Model Year = MY_03[2003], MY_02[2002]

Cost Category = All Vehicle
 Coverages / Contractual[1,%, %]
 Region Sold = North America[NA]
 Country Sold / Repaired [typed] = [USA,USA]
 Vehicle Line Awp = F250HD/350/45 0/550[F7]
 Part Num Base (cause) [typed] = [13480,%,%]
 Voc / Eoc [typed] = [02#-M, %]

Report Selection Criteria:

Report Name=Standard Claims List

Model Year=2003, 2002
 Cev Name=CLMLS1 25
 Order By=Customer Concern Code
 Maximum Claims=1000
 Logic=Corporate Tie
 Claims=ALL
 Claims With Comments=ALL
 Requested Currency=USD

MDL_YR	VIN_CD	LBR_COST	VEH_LINE_CD	MKT_DERIVED	BOO_CAB_STL_CD	DRIVE_CD	ENG_CD	TRANS_CD	PLANT_CD
2002	1FTNW21F82EA06288	48.81	T/F7	T/F	T/B0	T/E	T/D8	T/D8	A1
2002	1FTSW31FX2ED55854	20.09	T/F7	T/F	T/B0	T/E	T/D8	T/D8	A1
2002	1FTSW31FX2ED55854	20.09	T/F7	T/F	T/B0	T/E	T/D8	T/D8	A1
2002	1FTN021F72ED35817	19.65	T/F7	T/F	T/B0	T/E	T/D8	T/D8	A1
2002	3FTSW31F02MA00124	185.9	T/F7	T/F	T/B0	T/E	T/D8	T/D8	A2
2002	1FTSX31F22EA18821	22.79	T/F7	T/F	T/B0	T/E	T/D8	T/D8	A1
2002	1FTSX31F32EA19813	88.37	T/F7	T/F	T/B0	T/E	T/D8	T/D8	A1
2002	1FTNW21FX2EA71718	86.78	T/F7	T/F	T/B0	T/E	T/D8	T/D8	A1
2002	1FTN021FX2EA83054	58.1	T/F7	T/F	T/B0	T/E	T/D8	T/D8	A1
2002	1FTSW31F82EA72820	62.07	T/F7	T/F	T/B0	T/E	T/D8	T/D8	A1
2002	1FTVW33F02EC41983	18.97	T/F7	T/F	T/B0	T/E	T/D8	T/D8	A1
2002	1FTVW33F32ED09055	201.88	T/F7	T/F	T/B0	T/E	T/D8	T/D8	A1
2002	1FTNW21F12EB94688	63.9	T/F7	T/F	T/B0	T/E	T/D8	T/D8	A1
2002	1FTNW21F12ED39780	108.76	T/F7	T/F	T/B0	T/E	T/D8	T/D8	A1
2002	1FTNW21F52ED68880	22.4	T/F7	T/F	T/B0	T/E	T/D8	T/D8	A1
2002	1FTNW21F82ED68883	57.15	T/F7	T/F	T/B0	T/E	T/D8	T/D8	A1
2002	1FTNW21F72EA03800	38.78	T/F7	T/F	T/B0	T/E	T/D8	T/D8	A1
2002	1FTNW21F82ED45888	56.91	T/F7	T/F	T/B0	T/E	T/D8	T/D8	A1
2002	1FTNW21632EB43256	34.88	T/F7	T/F	T/B0	T/E	T/D8	T/D8	A1
2002	1FTN021F42EB65382	114.08	T/F7	T/F	T/B0	T/E	T/D8	T/D8	A1
2002	1FTN021F82EA08178	38.7	T/F7	T/F	T/B0	T/E	T/D8	T/D8	A1
2002	1FTN021L52EA08000	18.92	T/F7	T/F	T/B0	T/E	T/D8	T/D8	A1
2002	1FTSW31F12EB08202	34	T/F7	T/F	T/B0	T/E	T/D8	T/D8	A1
2002	1FTSW31F22EA58572	24.21	T/F7	T/F	T/B0	T/E	T/D8	T/D8	A1

2002	1FTSW31F72EA21851	45.15	T/F7	T/F	T/B/C	T/C/D	T/E	T/D/S	T/D/S	A1
2002	1FTSW31F82EA01827	40.72	T/F7	T/F	T/B/C	T/C/D	T/E	T/D/S	T/D/S	A1
2002	1FTSW31FX2ED48282	48.26	T/F7	T/F	T/B/C	T/C/D	T/E	T/D/S	T/D/S	A1
2002	1FTSW31FX2ED59129	58.21	T/F7	T/F	T/B/C	T/C/D	T/E	T/D/S	T/D/S	A1
2002	1FT3X31F42EB13044	108.5	T/F7	T/F	T/B/D	T/C/D	T/E	T/D/S	T/D/S	A1
2002	1FT3X31F82EA08870	65	T/F7	T/F	T/B/D	T/C/D	T/E	T/D/S	T/D/S	A1
2002	1FTWW33F12EC35779	50.01	T/F7	T/F	T/B/C	T/C/D	T/B	T/D/S	T/D/S	A1
2002	1FTWW33F12EC37853	58.6	T/F7	T/F	T/B/C	T/C/D	T/B	T/D/S	T/D/S	A1
2002	1FTWW33F12EC39858	17.24	T/F7	T/F	T/B/C	T/C/D	T/B	T/D/S	T/D/S	A1
2002	1FTWW33F42EA36381	17.02	T/F7	T/F	T/B/C	T/C/D	T/B	T/D/S	T/D/S	A1
2002	1FTWW33F82EC88318	18.99	T/F7	T/F	T/B/C	T/C/D	T/B	T/D/S	T/D/S	A1
2002	1FTSW31F82EB48322	16.5	T/F7	T/F	T/B/C	T/C/D	T/E	T/D/S	T/D/S	A1
2002	8FTSW31F22MA07219	19.77	T/F7	T/F	T/B/C	T/C/D	T/E	T/D/S	T/D/S	A2
2002	1FTSW31F82EB31482	215.29	T/F7	T/F	T/B/C	T/C/D	T/E	T/D/S	T/D/S	A1
2002	1FTNW20F22EA23786	18.7	T/F7	T/F	T/B/C	T/B/D	T/B	T/D/S	T/D/S	A1
2002	1FTNW21F12EB38400	16	T/F7	T/F	T/B/C	T/B/D	T/E	T/D/S	T/D/S	A1
2002	1FTNW21F82EB84458	16.84	T/F7	T/F	T/B/C	T/B/D	T/E	T/D/S	T/D/S	A1
2002	3FTNW21F52MA23115	58.12	T/F7	T/F	T/B/C	T/B/D	T/E	T/D/S	T/D/S	A2
2002	1FDWF38F82EB25530	19.13	T/F7	T/F	T/B/S	T/C/D	T/B	T/D/S	T/D/S	A1
2002	1FTNW20FX2EA13361	33.14	T/F7	T/F	T/B/C	T/B/D	T/B	T/D/S	T/D/S	A1
2002	1FTNW21F02EB88455	19.26	T/F7	T/F	T/B/C	T/B/D	T/E	T/D/S	T/D/S	A1
2002	1FTNW21F12ED18348	85.86	T/F7	T/F	T/B/C	T/B/D	T/E	T/D/S	T/D/S	A1
2002	1FTNW21F42ED58784	41.14	T/F7	T/F	T/B/C	T/B/D	T/E	T/D/S	T/D/S	A1
2002	1FTNW21F72EA86653	16.5	T/F7	T/F	T/B/C	T/B/D	T/E	T/D/S	T/D/S	A1
2002	1FTNX20L82EB13491	24.87	T/F7	T/F	T/B/D	T/B/D	T/B	T/V/Z	T/D/S	A1
2002	1FTNX20812EC78233	14.4	T/F7	T/F	T/B/D	T/B/D	T/B	T/W/A	T/D/S	A1
2002	1FTNX21F12ED34485	24.7	T/F7	T/F	T/B/D	T/B/D	T/E	T/D/S	T/D/S	A1
2002	1FTSW30F02ED57598	21.78	T/F7	T/F	T/B/C	T/C/D	T/B	T/D/S	T/D/S	A1
2002	1FTSW31F02EA07430	188.43	T/F7	T/F	T/B/C	T/C/D	T/E	T/D/S	T/D/S	A1
2002	1FTSW31FX2EB94388	18.92	T/F7	T/F	T/B/C	T/C/D	T/E	T/D/S	T/D/S	A1
2002	1FT8X31LX2EA38805	303.24	T/F7	T/F	T/B/D	T/C/D	T/E	T/V/Z	T/D/S	A1
2002	1FTWW33F72EA79186	90.25	T/F7	T/F	T/B/C	T/C/D	T/B	T/D/S	T/D/S	A1
2002	3FTNW21F22MA18294	88.24	T/F7	T/F	T/B/C	T/B/D	T/E	T/D/S	T/D/S	A2
2002	1FTSW31F42EB31773	186.08	T/F7	T/F	T/B/C	T/C/D	T/E	T/D/S	T/D/S	A1
2002	1FTSW31F82EC73021	22.85	T/F7	T/F	T/B/C	T/C/D	T/E	T/D/S	T/D/S	A1
2002	1FTWW32F22EA08598	15.5	T/F7	T/F	T/B/C	T/C/D	T/B	T/D/S	T/D/S	A1
2002	3FTNX21F22MA01828	88.93	T/F7	T/F	T/B/D	T/B/D	T/E	T/D/S	T/D/S	A2
2002	1FTNW20F32EA04070	45.44	T/F7	T/F	T/B/C	T/B/D	T/B	T/D/S	T/D/S	A1
2002	3FTNW20F22MA07438	19.5	T/F7	T/F	T/B/C	T/B/D	T/B	T/D/S	T/D/S	A2
2002	1FTNW20F22EA27341	19.5	T/F7	T/F	T/B/C	T/B/D	T/B	T/D/S	T/D/S	A1
2002	1FDWF38F82EB25530	19.13	T/F7	T/F	T/B/S	T/C/D	T/B	T/D/S	T/D/S	A1
2002	1FTSW31F72EA10185	44.36	T/F7	T/F	T/B/C	T/C/D	T/E	T/D/S	T/D/S	A1

2002 1FT8W31F42EC73475	51.2 T/F7	T/F	T/BC	T/CD	T/E	T/DS	T/DS	A1
2002 1FTNW21F82ED81848	38.08 T/F7	T/F	T/BC	T/BD	T/E	T/DS	T/DS	A1
2002 1FTSW31F72ED05027	20.08 T/F7	T/F	T/BC	T/CD	T/E	T/DS	T/DS	A1
2002 1FTNW21F82EC82527	55.47 T/F7	T/F	T/BC	T/BD	T/E	T/DS	T/DS	A1
2002 1FTNW21F82EB81547	51.07 T/F7	T/F	T/BC	T/BD	T/E	T/DS	T/DS	A1
2002 1FTNX21F82ED35148	72.5 T/F7	T/F	T/BD	T/BD	T/E	T/DS	T/DS	A1
2002 1FTNW20FX2EB32187	135.4 T/F7	T/F	T/BC	T/BD	T/B	T/DS	T/DS	A1

Currency Exchange=v6 Generated By=AKARIZAT

Reported Currency=USD	Requested Distance=Kilo meters	Reported Distance=Miles	Description=Yes	Default Claims (no Date Filers)=Up to current cutoff date	WCC_C	PART_NUM_C	PART_NUM_C	PART_NUM_C	CUST_C	COND_C
PRODN_DT	WRTY_START_DT	NAME	DOC_NUM	PH_NUM	D	AUS_PREF	AUS_BASE	AUS_SUFF	ONG_CD	D
7-Aug-01	29-Aug-01	HAYWARD FORD	36788001	8811200	7V01	*	13480	*	T90	33
13-Jun-02	31-Aug-02	MAC HAIK FORD	182857B	9328000	7V01	F87Z	13480	AA	T90	1
13-Jun-02	31-Aug-02	MAC HAIK FORD	182857D	9328000	7V01	F87Z	13480	AA	T90	1
24-May-02	13-Jun-02	CHAMPION FORD LINCOLN-MERCURY	4558551	8641441	7V01	F87Z	13480	AA	P83	41
2-Aug-01	8-Oct-01	BOB TOMES FORD, INC.	18909002	8981010	7V01	F87Z	13480	AA	P83	48
18-Jul-01	15-Nov-01	BEACH FORD, INC.	452411A	4882717	7V01	F87Z	13480	AA	P24	42
19-Jul-01	28-Sep-01	BEACH FORD, INC.	437181A	4882717	7V01	F87Z	13480	AA	P24	28
20-Sep-01	18-Dec-01	WORLD FORD-PENSACOLA	8818951	4769050	7V01	F87Z	13480	AA	P09	42
1-Oct-01	28-Oct-01	WALNUT CREEK FORD	369812D	8322800	7V01	F87Z	13480	AA	P09	42
20-Sep-01	22-Oct-01	PIONEER FORD SALES	25432301	2571933	7V01	F87Z	13480	AA	P08	41
5-Mar-02	22-Mar-02	HAMILTON BIG COUNTRY FORD, INC	80288901	7824427	7V01	F87Z	13480	AA	P08	42
3-May-02	23-May-02	TOWN & COUNTRY FORD	285217A	4813873	7V01	F87Z	13480	AA	P08	42
24-Jan-02	19-Mar-02	GRANDALL FORD-MERCURY	065666B	6473573	7V01	F87Z	13480	AA	P01	42
28-May-02	3-Sep-02	CAPITAL FORD-MERCURY	127831A	8825333	7V01	F87Z	13480	AA	P01	41
13-Jun-02	21-Aug-02	EARNHARDT FORD SALES COMPANY	455782A	8386000	7V01	F87Z	13480	AA	P01	42
13-Jun-02	28-Sep-02	JIM SKINNER FORD	083808B	8542222	7V01	F87Z	13480	AA	P01	28
31-Jul-01	1-Oct-01	HOBLIT MOTORS	8068483	4582151	7V01	F87Z	13480	AA	P01	42
4-Jun-02	8-Sep-02	TALLAHASSEE FORD	7464402	8771171	7V01	F87Z	13480	AA	P01	42
21-Nov-01	4-Dec-01	PIONEER FORD, INC.	562901	3672311	7V01	F87Z	13480	AA	P01	42
21-Dec-01	18-Jan-02	DISCOVERY FORD LINCOLN MERCURY	8882704	7854551	7V01	F87Z	13480	AA	P01	42
25-Jul-01	13-Jul-02	VANCOUVER FORD INC	410340A	8948501	7V01	F87Z	13480	AA	P01	42
3-Aug-01	3-Oct-01	DUTHLER FORD SALES, INC.	10008201	8886511	7V01	F87Z	13480	AA	P01	42
23-Oct-01	16-Nov-01	TOWN & COUNTRY FORD, INC.	29030401	8388800	7V01	F87Z	13480	AA	P01	28
3-Sep-01	14-Sep-01	PERSON FORD	1117051	5937411	7V01	F87Z	13480	AA	P01	42

1003-003 4947

3-Aug-01	31-Aug-01	HUDGEONS' FORD-MERCURY INC	4006901	7285470 7V01	*	13480	*	P01	28
19-Jul-01	5-Oct-01	FORD OF HYANNIS, INC.	140618C	7765912 7V01	F87Z	13480	AA	P01	28
3-Jun-02	18-Jul-02	ANDERSON FORD LINCOLN MERCURY	087589G	3941700 7V01	F87Z	13480	AA	P01	28
12-Jun-02	31-Jul-02	DAN WIEBOLD FORD	8706851	4864615 7V01	F87Z	13480	AA	P01	28
7-Nov-01	3-Jun-02	NORRISTOWN AUTOMOBILE COMPANY,	15844801	5385400 7V01	F87Z	13480	AA	P01	46
7-Oct-01	9-Nov-01	RAMSEY FORD LINCOLN MERCURY	081955A	8584801 7V01	F87Z	13480	AA	P01	42
28-Feb-02	15-Mar-02	DON VANCE FORD, INC.	2447461	8592800 7V01	F87Z	13480	AA	P01	42
28-Feb-02	28-Mar-02	COUNTRY FORD-MERCURY	087480A	3588111 7V01	F87Z	13480	AA	P01	42
22-Mar-02	29-Mar-02	CARTHAGE FORD-MERCURY	043962A	3584037 7V01	F87Z	13480	AA	P01	42
12-Aug-01	7-Dec-01	FORD OF LILLINGTON	103330C	8142243 7V01	F87Z	13480	AA	P01	42
21-Mar-02	23-Apr-02	FAIRWAY FORD OF ANDERSON	138822A	2254151 7V01	F87Z	13480	AA	P01	28
5-Dec-01	18-Feb-02	SULLIVAN MOTOR CO INC	1278803	5442134 7V01	*	13480	*	N58	42
25-Sep-01	12-Oct-01	TOWN EAST FORD	798688B	2708441 7V01	F87Z	13480	AA	L83	D1
8-Nov-01	12-Aug-02	ELVIN HAYES FORD	5486751	3280585 7V01	F87Z	13480	AA	L30	42
8-Aug-01	13-Nov-01	DALE JARRETT FORD	16027801	2838521 7V01	F87Z	13480	AA	L29	42
29-Nov-01	26-Sep-02	JACK KISSEE FORD, INC.	8163801	3410101 7V01	F87Z	13480	AA	L28	42
11-Jan-02	2-Feb-02	JIM PEACH MOTORS, INC.	038087B	8678212 7V01	F87Z	13480	AA	L29	42
11-Dec-01	27-Feb-02	JIM PEACH MOTORS, INC.	038288A	8678212 7V01	F87Z	13480	AA	L29	42
7-Nov-01	18-Dec-01	APPEL FORD-MERCURY, INC.	5380001	8383889 7V01	F87Z	13480	AA	L28	42
7-Aug-01	23-Oct-01	WEST TEXAS FORD, INC.	3223801	8233211 7V01	F87Z	13480	AA	L28	42
20-Dec-01	2-Jan-02	COURTESY FORD	7890803	3288000 7V01	*	13480	*	L28	7
9-May-02	22-May-02	RODRIGUEZ FORD-MERCURY, INC.	3742801	6882452 7V01	*	13480	*	L28	28
14-Jun-02	20-Jul-02	AL PACKER FORD WEST	081730B	7901100 7V01	F87Z	13480	AA	L28	28
15-Oct-01	31-Dec-01	DUNN FORD COMPANY	8084061	8874321 7V01	F87Z	13480	AA	L28	42
12-Nov-01	14-Jan-02	FUTURE FORD	452203A	7883673 7V01	*	13480	*	L28	38
9-Apr-02	16-Apr-02	GATEWAY FORD INC	3810801	3887780 7V01	F87Z	13480	AA	L28	42
15-Jun-02	29-Aug-02	KOONS FORD INC.	638151	2417200 7V01	F87Z	13480	AA	L28	42
28-Jun-02	28-Jul-02	DREW FORD	9747851	4847777 7V01	F87Z	13480	AA	L28	42
18-Oct-01	31-Oct-01	APPLE VALLEY FORD	25750301	4318300 7V01	F87Z	13480	AA	L28	42
24-Jan-02	1-Mar-02	STAYTON MOTORS INC	5735201	7886888 7V01	*	13480	*	L28	48
7-Sep-01	27-Sep-02	THOMAS FORD SALES INC	094284A	9220059 7V01	*	13480	*	L28	42
11-Oct-01	30-Oct-01	FREEDOM FORD, INC.	288747A	5832871 7V01	F87Z	13480	AA	L28	28
21-Nov-01	18-Dec-01	KEYSTONE FORD	1020152	8880825 7V01	F87Z	13480	AA	L28	48
15-Nov-01	28-Nov-01	MIDWAY FORD TRUCK CENTER, INC.	202180E	4883000 7V01	*	13480	*	L07	42
26-Mar-02	13-Jul-02	FRAMINGHAM FORD	14065402	8791328 7V01	F87Z	13480	AA	H20	42
30-Jul-01	14-Aug-01	HARVEST FORD LINCOLN MERCURY	053078A	8870801 7V01	F87Z	13480	AA	H20	42
13-Aug-01	24-Sep-01	M & M FORD LINC-MERC, INC.	20184701	2635324 7V01	*	13480	*	H20	38
29-Jul-01	28-Sep-01	GILBERT & BAKER FORD	1781802	8913000 7V01	F87Z	13480	AA	H19	42
28-Sep-01	23-Jan-02	SHEEHY FORD MERCURY	10189101	7984791 7V01	*	13480	*	H19	28
17-Aug-01	18-Nov-01	HENSON FORD, INC.	12772802	3488910 7V01	F87Z	13480	AA	H02	42
7-Nov-01	18-Dec-01	APPEL FORD-MERCURY, INC.	5367001	8363889 7V01	F87Z	13480	AA	G29	42
18-Jul-01	28-Nov-01	DOHERTY FORD	5524301	3573114 7V01	*	13480	*	G29	38

28-Mar-02	17-Sep-02 WILSON MOTORS	5543151	7524201 TV01	F87Z	13480	AA	D50		42
17-Jun-02	30-Jul-02 BAYTOWN FORD	15900001	8393300 TV01	F87Z	13480	AA	A65		42
1-May-02	2-Sep-02 MAC HARK FORD	154053A	9325000 TV01	F87Z	13480	AA	A88		42
15-Mar-02	25-May-02 ROCKWALL FORD-MERCURY	6048001	2602208 TV01	*	13480	*	A25	X2	
5-Dec-01	14-Dec-01 DELAND FORD	062857B	7781000 TV01	F87Z	13480	AA	A25		42
14-Jun-02	27-Aug-02 FORD OF KIRKLAND, INC.	33933201	8218811 TV01	*	13480	*	A25	X2	
3-Jan-02	4-Mar-02 ERNIE HAIRE FORD, INC.	1173554	9398571 TV01	F87Z	13480	AA	A07		42

RPR_DT	TIS_WS D	CLM_KEY	MILGE	MTRL_COST	TOT_COST_G ROSS	LBR_HRS	DLR_CD	DLR_SUB_CD	REGION_CD	ST_PRO V_CD	CPSC_CD_6
21-Nov-01	3	347874	5027		84.26	0.5	7729 *		NA	CA	80804
30-Dec-02	5	4028481	5281	8.58	28.67	0.3	4511 *		NA	TX	80804
30-Dec-02	5	4028483	8261	6.58	26.67	0.3	4511 *		NA	TX	80804
28-Aug-02	3	2488641	8344	8.58	29.23	0.3	5700 *		NA	KY	80804
28-Oct-02	13	3241121	28403	6.58	182.48	2.8	2531 *		NA	TX	80804
19-Mar-02	5	1217278	10124	6.58	29.37	0.3	8727 *		NA	VA	80804
17-Dec-01	3	433848	3559	6.58	74.85	0.9	8727 *		NA	VA	80804
18-Nov-02	12	3514885	31184	6.58	73.38	1.1	4852 *		NA	FL	80804
29-Aug-02	11	2488773	20429	6.58	89.88	0.6	7820 *		NA	CA	80804
1-Mar-02	5	763883	8334	6.58	68.85	0.9	20400 *		NA	AZ	80804
24-Feb-03	12	4703428	38980	6.58	28.58	0.3	20422 *		NA	NM	80804
27-Feb-03	10	4770045	24905	6.58	208.24	3.1	3385 *		NA	AL	80804
3-Mar-03	12	4843386	27878	6.58	70.48	0.8	8328 *		NA	UT	80804
18-Sep-02	1	2748877	889	6.58	116.34	1.6	7882 *		NA	NV	80804
1-Aug-02	8	2138452	208	6.58	28.88	0.3	20313 *		NA	AZ	80804
2-Oct-02	1	2857515	282	6.58	83.73	0.9	224 *		NA	AL	80804
8-Dec-01	3	428032	4676	6.58	48.34	0.6	7735 *		NA	CA	80804
30-Oct-02	2	3244178	8672	6.58	83.49	0.9	4844 *		NA	FL	80804
13-Jan-03	14	4188294	13247	6.58	41.27	0.7	9852 *		NA	SD	80804
29-Jul-02	7	2784408	8885	6.58	120.88	1.7	1170 *		NA	WA	80804
22-Nov-02	5	3817898	11488	6.58	45.28	0.5	8547 *		NA	WA	80804
19-Mar-03	18	5884833	21255	6.58	26.5	0.3	9870 *		NA	MI	80804
7-Aug-02	9	2253127	8858	6.58	48.58	0.5	1057 *		NA	NC	80804
28-Feb-03	18	4788308	25884	6.58	30.78	0.3	5858 *		NA	CA	80804

12-Jun-02	10	1501677	15425	0	45.15	0.7	20878 *	NA	AZ	60604
18-Feb-03	17	4890825	20458	6.58	47.3	0.6	1827 *	NA	MA	60604
27-Nov-02	5	3978850	8979	6.58	54.85	0.8	7116 *	NA	NE	60604
28-Jul-02	0	2105813	54	6.58	62.79	0.8	8325 *	NA	ID	60604
10-Dec-02	7	3924886	15849	6.58	113.08	1.5	1350 *	NA	PA	60604
18-Feb-03	18	4927127	29878	6.58	71.88	1	4073 *	NA	MD	60604
12-Mar-02	0	850106	5	6.58	58.58	0.9	5098 *	NA	MO	60604
28-Dec-02	10	3948502	16205	9.48	63.08	0.8	1223 *	NA	NJ	60604
6-Nov-02	8	3348819	24792	6.58	23.82	0.3	2838 *	NA	MO	60604
20-Sep-02	10	3244274	29589	6.58	23.8	0.3	4119 *	NA	NC	60604
13-Jun-02	2	1808241	4288	6.58	23.57	0.3	2347 *	NA	SC	60604
7-Feb-02	0	855284	877	0	18.5	0.3	4580 *	NA	TX	60604
11-Jun-02	9	1588236	19871	6.58	28.35	0.3	8182 *	NA	TX	60604
12-Nov-02	4	3455192	5033	12.29	227.57	3.5	4448 *	NA	TX	60604
20-Jul-02	8	1972583	24539	6.58	25.28	0.3	1014 *	NA	NC	60604
9-Dec-02	3	3770427	4300	6.58	24.88	0.3	8858 *	NA	OK	60604
30-May-02	4	1872805	15954	6.58	23.42	0.3	1124 *	NA	AL	60604
13-Sep-02	7	2883452	15258	6.54	64.85	1	1124 *	NA	AL	60604
15-Jul-02	7	1931888	9253	6.58	25.71	0.3	4500 *	NA	TX	60604
20-Dec-01	2	467677	3404	6.58	39.72	0.8	1118 *	NA	TX	60604
8-Mar-02	3	1034888	5851	0	19.25	0.3	1825 *	NA	FL	60604
25-Oct-02	6	3183208	18813	0.84	88.52	1.5	4450 *	NA	TX	60604
26-Feb-03	8	4882522	7431	6.58	47.72	0.6	2838 *	NA	FL	60604
27-Jan-03	14	4388551	31573	6.58	23.08	0.3	8882 *	NA	OK	60604
5-Feb-02	1	858615	51	0	24.57	0.3	7748 *	NA	CA	60604
4-Sep-02	5	2497179	17499	6.58	20.98	0.3	6475 *	NA	LA	60604
28-Oct-02	3	8885245	1954	6.58	31.28	0.3	38 *	NA	VA	60604
9-Jan-03	8	4100011	17053	6.58	28.34	0.3	5485 *	NA	CA	60604
17-Aug-02	10	2348728	3691	13.97	170.4	1.8	9217 *	NA	MN	60604
12-Sep-02	7	2727086	13856	6.58	25.2	0.3	8507 *	NA	OR	60604
11-Oct-02	1	3024389	385	0	303.24	4.3	8822 *	NA	MA	60604
27-Dec-01	2	480067	4821	6.58	96.83	1.4	139 *	NA	VA	60604
21-Oct-02	11	3532570	28338	6.58	72.82	0.9	5504 *	NA	CA	60604
8-May-02	8	1328791	16583	41.31	237.4	2.8	5008 *	NA	MO	60604
19-Jul-02	1	2031338	125	6.58	29.23	0.3	8928 *	NA	MA	60604
24-Aug-01	1	178894	752	6.58	23.08	0.3	6403 *	NA	LA	60604
1-Jun-02	9	1684098	16571	0	69.93	0.5	20008 *	NA	IA	60604
13-Nov-01	2	318826	4779	6.58	53.02	1	5898 *	NA	AL	60604
2-Nov-01	0	374164	25	6.58	28.08	0.3	4224 *	NA	VA	60604
16-Nov-01	0	327880	20	6.58	28.08	0.3	3013 *	NA	TX	60604
17-Jul-02	8	1848800	8888	6.58	25.71	0.3	4500 *	NA	TX	60604
9-Jul-02	8	2015881	18827	0	44.38	0.6	8883 *	NA	OR	60604

15-Jan-03	5	4187461	6489	6.58	57.78	0.8	8539 *	NA	OR	80804
9-Sep-02	2	2538202	2968	6.58	84.88	0.8	634 *	NA	TX	80804
20-Jan-03	5	4230765	18158	6.58	28.87	0.3	4511 *	NA	TX	80804
21-May-02	0	1368062	38	1.43	86.0	0.8	3587 *	NA	TX	80804
7-Aug-02	8	2182234	24880	8.58	57.85	0.8	3898 *	NA	FL	80804
18-Dec-02	4	3867958	4378	0	72.8	1	847 *	NA	WA	80804
25-Feb-03	12	4715158	28894	18.17	183.57	2	4668 *	NA	FL	80804

TECH_TXT1

WIRE CLIP PELL OFF REPLACED WIRE CLIP

5261 C.C 13480 13480A .3 REPLACE BRAKE LAMP SWITCH FOR BRAKE LAMPS BEIN G INOP

5261 13480 13480A .3 SPR FROM LINE B

SWITCH REPLACED BRAKE SWITCH ASSY

ELECTRIC TRANS DIAGNOSIS, REPAIRED TRACED OUT REPAIRED BRAKE LIGHT SWITCH CIRCUIT

10124 W CVP PER GARLAND REPLACED BRAKE SWITCH, RETEST TO MAKE SURE WORKING PROPERLY

3550 SHIFT INTERLOCK BRAKE LIGHT SWITCH WARR TEST OPERATION OF THE SHIFTER VERIFIED WOULD NOT COME OUT OF PARK. PERFORMED PINPOINT TEST AND FOUND SWITCH STOP LAMP REPLACE

28428 CHECKED FOR NOT COMING OUT OF PARK. TRIED MOVING SHIFT OUT OF PARK AND WORKS OK AT THIS TIME. SPOKE W WRITER, THIS IS INTERMITT PROB. PERFORM DIAG AND REPLACED STOPLIGHT SWITCH.

1 & 2 SAME TEST BRAKE LIGHT FUSE IS OK. CHECK BRAKE SWITCH CIRCUIT IS NO GOOD. REPLACE BRAKE SWITCH

PERFORMED STEERING COLUMN DASH SWITCHES TESTS, REMOVED STEERING COLUMN FOR ACCESS TO REPAIR OPEN CIRCUIT & REPLACE BRAKELAMP SWITCH

VERIFIED THE CONCERN AND REPLACED THE BRAKE SWITCH AND VERIFIED THE REPAIR.

889 WILL NOT COME OUT OF PARK 41 WILL NOT COME OUT OF PARK. I PERFORMED AUTO TRANS SYSTEM DIAG. I TESTED THE SHIFT LOCK SOLENOID AND FOUND OK. I TH

205 BAD BRAKE SWITCH 28 VERIFIED VEHICLE WONT COME OUT OF PARK. CHECKED SYSTEM FUSES, ALL OK. CHECK BRAKE LIGHTS. OK. CHECKED FOR POWER TO SHIF

HARD SHIFTING OUT OF PARK. TESTED AND REPLACED STOPLAMP SW ASSY TO CORRECT SHIFTER TO ENGAGE

BRAKE SWITCH WORKS INTERMITTANTLY SWITCH STOP LAMP REPLACE

13480 INOP CC 42 REPLACED BRAKE ON OFF SWITCH. RETEST

CHECKED FUSES OK WORKS AT TIMES TAP ON BRAKE SWITCH ACTS UP REPLACED BRAKE SWITCH

VERIFIED CUSTOMERS CONCERN HAPPENED BRAKE LIGHTS DIDNT FUNCTION INTERMITTENTLY PROBLEM WITH BRAKE LIGHT SWITCH REPLACED BRAKE LIGHT SWITCH VEH

11468 CC42 BOO SWITCH WARRANTY ROADTEST WITH CUSTOMER TO VERIFY CONCERN. PERFORMED BODY CHASSIS ELECTRICAL TEST AND ACCESS INSTRUMENT PANEL

ROAD TESTED AND TESTED OPERATION OF THE SHIFTER, IT COMES OUT OF PARK EVERY TIME. ADVISED AND ROAD TESTED HOME STILL

28 VERIFY COMPLAINT CHECK FUSES OK CHECK FOR POWER AND GROUND AND SHIFT LOCK SOLENOID, 0 VOLTS BEC DIAG VERIFY LG RD

SWITCH DIAGNOSIS CONCERN IN BRAKE LIGHT SWITCH, R R SWITCH RETEST ALL ACCE

INSPECTED BRAKE LIGHTS, INOP. CHECKED FUSE, OK. PERFORMED PINPOINT TEST. OPEN IN BRAKE LIGHT SWITCH HARNESS. REPAIRED OPEN RE TESTED. OK.
20460 28 TEST DROVE VERY INT. BRAKE LIGHTS DO NOT COME ON WILL NOT SHIFT DIA PINPOINT TESTING OF HARNESS OK TEST BRAKE LIGHT SWITCH FAILED REMOVED,
8360 PINPOINT TESTED. FOUND BRAKE LIGHT WORK OK BUT NO SIGNAL SENT TO THE SHIFT LOCK SOLENOID. REPLACED BRAKE SWITCH AND REASSEMBLED. VEHICLE S
INTERMITTENT OPEN BODY CHASSIS ELECTRICAL (BCE) TEST, BODY CHASSIS ELECTRICAL PINPOINT TEST REPLACE STOP LAMP SWITCH
SHORT BCE DIAGNOSIS, PINPOINT TEST. REPLACE FUSE. REPLACE STOP LIGHT SWITCH. STOP LAMP SWITCH WIRE RUBBED THROUGH.

R AND R BRAKE SWITCH
BRAKE SWITCH NOT OPERATING PROPER SWITCH STOP LAMP REPLACE
CK CODES REPLC SW
SWITCH STICKING

REPLACE BRAKE SWITCH
DIAGNOSIS REPLACE BRAKE LIGHT SWITCH DUE TO OPE N AND RETEST.
VERIFY BRAKE LAMP SWITCH CLICKING NORMAL OPERATION

19871 VERIFIED CUST CONCERN. PERFORMED INSPECTION. FOUND SOURCE OF FLUID TO BE BOD SWITCH REPLACED SWITCH AND RETESTED PROBLEM CORRECTED
BLOWS 20 AMP FUSE #P2.18 REPLACED AND CK BLOWS FUSES AS SOON AS USED RIGHT TURN REMOVED RIGHT REAR TAIL LAMP ASSY AND RIGHT HEAD LAMP ASSY REM
FOUND SWITCH SHORTED STAYING CONNECTED. REPLACED SWITCH WORKS WELL. TESTED ALL OK.

CP 13480 CC 42. REPLACED FAILED BRAKE LIGHT SWITCH. OK NOW.
REPLACED BRAKE LIGHT SWITCH

TEST REPLACED BRAKE SWITCH AND FUSE
REPLACED BRAKE LAMP SWITCH. RETEST O.K.
PERFORMED EEC TEST ON LAMPS ALL PASS STOP LIGHT STAYING ON AT TIMES REPL STOP LIGHT SWITCH LOCK WIRING FOR DAMAGE.
ADJUST BACKUP LITE SWITCH

VERIFY STOP LIGHTS NOT WORKING. FOUND BURNED FUSE. FOUND BROKEN WIRE CIRCUIT 511. REPAIR WIRING REPLACE FUSE. OPER OK
7923 BRAKE LIGHTS INOP. DIAG, PIN POINT TEST, REPLACE BRAKE SWITCH, ROAD TEST OK

TURN SIGNAL SWITCH NOT WORKING SWITCH STOP LAMP REPLACE
FOUND BRAKE LIGHT SWITCH CAME LOOSE AT RETAINER RESET BRAKE LIGHT SWITCH
TEST SYSTEM AND REPLACE BRAKE LIGHT SWITCH
00 SWITCH STOP LAMP REPLACE

VERIFY NO BRAKE TEST AND REPLACE BRAKE LAMP SWITCH
CC42 REPLACED FUSE AND BLEW FUSE RIGHT AWAY. CHECKED WIRES FOR BRAKES. FOUND SHORTED WIRE TO MULTI FUNCTION SWITCH.

CHECK VEHICLE NO BRAKE LIGHT CHECK STOP LIGHT CIRCUIT FUSES CONNECTOR WIRES AND BULBS CHECK POWER AT BRAKE PEDAL SWITCH CHECKS OK CHECK POW
4822 BRAKE LIGHT SWITCH BAD, CK BRAKE LIGHTS INOP INTERMITTENT, PINPOINT TEST, REPL BRAKE LIGHT SWITCH, RETEST
FAULTY LIGHT SWITCH STEERING COLUMN DASH SWITCH ASSEMBLIES DIAGNOSIS

18563 473 W08 TEST NO CODES CK OUT AUTO LOCKS AND PERFORM PINPOINT TEST FOR INTERMIT OPERATION AND REMOVE AND REPLACE BRAKE SWITCH AND RECK
CC 42 BASIC 13480 INSTALL NEW BRAKE LIGHT SWITCH, CHECK BRAKE LIGHTS.

REPLACE STOP LAMP SWITCH
INSPECTED AND FOUND CLIP ON BRAKE SWITCH COME OFF AND WAS MISSING INSTALLED NEW CLIP AND TEST DROVE OK
REPLACED SWITCH
REPLACED BRAKE LIGHT SWITCH

REPLACE BRAKE LIGHT SWITCH
TEST SYSTEM, LOCATE LOOSE WIRE AT BRAKE LIGHT SWITCH LUBE ALL DOOR SWITCHES, ROAD TEST

INOP

EEC (QUICK TEST) DIAGNOSIS

PIN POINT TESTED INSPECTED AND FOUND A OPEN IN THE BRAKE SWITCH. REPLACED THE BRAKE SWITCH RETESTED AL OK

13158 13480 VERIFIED CONCERN VEH WOULD NOT SHIFT OUT OF PARK AT TIMES. DID ELECTRICAL DIAG ON BRAKE LIGHT SYSTEM. BRAKE SWITCH NOT MAKING CONTACT

PERFORM TEST DRIVE FOR CRUISE NOT WORKING PERFORM DIAG AND PINPOINT TEST AND REPLACE BLOWN FUSE AND REPAIR

CRUISE DAIGNOSIS AND BRAKE LIGHT SWITCH IS SHORTED TO POWER. REPLACE SWITCH AND RETEST

VERIFIED CONCERN PERFORM DIAGNOSIS, FOUND WIRE CONNECTOR AT DEACTIVATION SWITCH WAS INCORRECTLY PLUGGED IN 1

OPEN RPL WITH NEW STILL RADIO WENT ON AND OFF THEN FOUND G6100 AND G300 BAD HAD TO R R BATTERY TO CLEAN G400 AND HAD TO REMOVE SPARE TIRE TO CLEAR

TECH_TXT2

WITCH. PERFORMED RNR BRAKE LIGHT SWITCH THEN RETESTED TO VERIFY REPAIRS OK.

WITCH TO MAIN CONNECTOR UNDER DASH. BRAKE LIGHTS ARE WORKING AT THIS TIME. R&R BOO SWITCH FOR INTERMITT PROB. 13450 42.

E BRAKE ON OFF SWITCH AND FOUND IT TO BE SHORTED INTERNALLY. I THEN REPLACED THE BRAKE ON OFF SWITCH AND RETESTED ALL IS WELL.
CH TO LOCK ACTUATOR. PERFORMED WIRING PINPOINT TEST AND FOUND A BAD BRAKE SWITCH. REPLACED THE BRAKE SWITCH. RETESTED OK.

E LOWER KICK PANEL. BELOW

R CONSULT WITH JP, RETEST FOUND CONCERN NO LONGER HAPPENS AT THIS TIME. THANKS JEFF RUSH 485

XXXXXXXXXXXXXXXXXXXXXXXXX
SHIFTS OUT OF PARK OK

UNPLUGGED TAIL LAMP AND FRT TURN STILL BLOWS SHORT BETWEEN CENTRAL JUNCTION BOX AND TURN SIGN SWITCH

MULTIFUNCTION SWITCH ACCESS DAS H STEERING COLUMN OPEN HARNESS AND CHECK WIRING CIRCUIT 511 REPAIRED PULLED PIN CONNECTOR AT C202A MULTIFUNCTION SW

OKED FOR 5 MIN. COULD REACTIVATE. CALL HOT LINE ON CONCERN START

START M TIME

473 CONTINUE M TIME

T AT TIMES. REPLACED SWITCH RETESTED. O.K

N WIRE EN D THEN TEST OK

FORM-908 4/55