

414 Commerce Drive * Suite 100 * Fort Washington, PA 19034

PERSONAL AFFAIRS
SECTION March 26, 2002

Jack G & Lourene Robinson
113 Bald Mountain
Wilkes-barre, PA 18702-9538

2 APR -3 11:32

OUR INSURED: [REDACTED]
OUR CLAIM NUMBER: [REDACTED]
DATE OF LOSS: 03-23-2002



99 FORD RANGER X
VIN # 1FTZR15X9X [REDACTED]

To Whom It May Concern,

Please be advised that I represent Nationwide Insurance Company. The above vehicle was involved in a vehicle fire, which resulted from an alleged defect. The fire occurred on 03-23-2002 in the engine compartment.

In order to determine the cause of the vehicle fire, including a determination as to whether any defect in the vehicle was in existence at the time of the fire, an inspection and testing of the vehicle will be conducted by North Eastern Technical Services, Inc. an authorized representative of the above. This inspection will take place at Copart 2704 Geryville Pike Pennsburg, PA 18073 in ten days.

As you may have an interest in this matter, from both a safety precaution standpoint and as potential defendants in litigation, you are invited to have an expert attend and participate in the inspection and testing procedures.

To coordinate the inspection date and time, please contact North Eastern Technical Services, Inc. at (508) 675-0999 within ten days of receipt of this letter. Should you have any questions pertaining to this matter, or wish to discuss the same in further detail, you may contact the undersigned at the number below.

I would like to caution that should your expert fail to appear at the inspection, you will forfeit any right to subsequently claim prejudice/spoliation under Nally vs. Volkswagen of America, Inc., 405 MASS 191 (1989).

NATIONWIDE MUTUAL INSURANCE COMPANY

ENR5-005-LC-9831

Marcin Lubaczewski (PA-20-FWAS)
Claims Department
(215)619-4618



M. A. STRINGER & ASSOCIATES, INC.

2805 Division Street • Suite 101 • Metairie, Louisiana • 70002

(504) 454-0466 • FAX (504) 454-0458

January 18, 1999

Ms. Mary Walters, Claim Specialist
State Farm Insurance Company
4811 Harding Boulevard
Baton Rouge, Louisiana 70811

RE: Fire Analysis Report
Insured: [REDACTED]
Address of Loss: I-10 at Prairieville Exit
Prairieville, Louisiana
Date of Loss: 12-09-98
Claim Number: [REDACTED]
MASA Contract Number: 12983070M

Dear Ms. Walters:

In response to the December 15, 1998 request of Ms. Kay Walters, Claim Specialist, State Farm Insurance Company, Baton Rouge, Louisiana, M. A. Stringer and Associates, Incorporated (MASA) has examined and analyzed the above captioned vehicle fire loss. The vehicle was carefully examined on December 18, 1998 by Marvin A. Stringer, MASA Chief Fire Specialist, at which time photographs were taken, some of which are included at the end of this report with the remainder being retained in the MASA file.

It was reported the vehicle was run off the road by another vehicle and subsequently collided with a tree causing impact damage to the right front fender. As the operator was being loaded into an ambulance she saw a fire from the area of the engine compartment. The vehicle, a 1998 Ford Explorer, had been purchased new on July 16, 1998 and had less than 7,000 miles on the odometer. An internet search of the National Highway Transportation Safety Administration (NHTSA) Office of Defects Investigation Recall Database showed only one fire related recall dealing with the use of the stainless steel fuel line braid as a ground for jump starting the vehicle. This recall does not appear to be relevant in this instance.

RECEIVED
JAN 21 1999
NBR CLAIMS

Figures 1 through 7 are exterior views of the vehicle and as can be seen there is impact damage to the rear of the right front fender, as shown in Figures 2, 3 and 4. Figure 8 is a view of the Vehicle Identification Number (VIN) and Figure 9 shows the vehicle's license plate. Figure 10 is a view of the rear storage area, Figure 11 is a view of the interior from the rear, Figures 12 and 13 show the front and rear seats as viewed from the left side and Figures 14 and 15 show the front and rear seats as viewed from the right side. Figure 16 is a front view of the engine compartment from above and Figure 17 is a left side view. As can be seen the fire damage is severe throughout the entire vehicle, however, the overall damage gradients and burn patterns indicate the fire originated in the right side area of the engine compartment. Figure 18 is a view of the engine compartment from the right side with the impact damage to the rear of the right front fender clearly seen in the lower left. Figures 19 and 20 are views of the right rear area of the engine compartment, the area adjacent to the impact damage, and the remains of what appears to be a canister from the air condition system.

Figures 21 through 24 show the engine oil dipstick and transmission fluid dipsticks showing adequate levels for the normal operation of the vehicle. Figure 25 is an overview of the engine after the removal of the loose debris and examination of the electrical wiring, also shown in Figures 26 and 27. No evidence of any arcing or shorting was found, however, not all of the electrical system remained intact for examination. Figure 27 also shows the remains of the aforementioned air conditioner canister, which was wedged under the top of the coil spring retainer, as shown in Figures 28 and 29. Also note the vehicles exhaust system is located in this area. Figure 30 is a view of the front interior of the vehicle after the removal of the driver's side floor debris. Portions of the vehicles floor mat were still somewhat intact and no unusual odors were detected.

As can be seen in a study of the figures the damage gradients and burn patterns show the fire originated in the right front area of the engine compartment, in the area where a canister for the air conditioning system had been displaced and wedged under the coil spring retainer. The displacement of this canister would have resulted in the freon and oil in the air conditioning system being expelled and the contact of the oil with the hot exhaust manifold could result in ignition of the oil. The facts, circumstances and physical evidence indicate that this is the most probable cause for this fire.

Based on the results of the investigation conducted by MASA, as set forth in this report, it is the opinion of M. A. Stringer and Associates, Incorporated that the December 12, 1998 fire in the Robert and Kriste Rispono 1998 Ford Explorer vehicle originated in the right front area of the engine compartment and was caused by impact damage that displaced a canister containing a combustible fluid that was ignited by the heat of the exhaust system.

RECEIVED
JAN 21 1999
NBR CLAIMS

MASA appreciates the opportunity to be of service to you and State Farm Insurance Company in this matter. If we can be of additional assistance in this or other matters, please do not hesitate to contact us.

Sincerely,

M. A. Stringer and Associates, Inc.

Mervin A. Stringer

Mervin A. Stringer
Chief Fire Specialist

Ted K. Kaplon

Ted K. Kaplon, P.E.
Consulting Engineer

MAS/ls

Original and One Copy

Ms. Mary Walters, Claim Specialist
State Farm Insurance Company
4811 Harding Boulevard
Baton Rouge, Louisiana 70811

Report Copy

MASA File



RECEIVED
JAN 21 1999
NBR CLAIMS



Figure 1



Figure 2




Figure 3



Figure 4



Figure 5



Figure 6

ERES-805-LC-9038

BMCS-003-LC-0010



Figure 7




Figure 8

1400-07-000-0003




Figure 9



Figure 10




Figure 11



Figure 12

2005-07-08-0000



Figure 13



Figure 14

1005-07-000-0002



Figure 15



Figure 16



Figure 17

ENCLOSURE LC-9047



Figure 18

ENCLOSURE LC-0049



Figure 19



Figure 20



Figure 21



Figure 22

6108-07-200-2012



Figure 23

0508-37-508-5003



Figure 24




Figure 26



Figure 26

2005-005-10-0052



Figure 27



Figure 28



Figure 29



Figure 30






FARMERS

National Document Center
P.O. Box 268992
Oklahoma City, OK 73126-8992
claimedocument@farmersinsurance.com
Fax: 877-277-1389

06/03/2005

Ford Motor Company
Parklane Towers West, Ste 300
Three Parklane Blvd.
Dearborn, MI 48126-2568



Re: Our Insured: [REDACTED]
Loss Date: 05/14/2005
Claim Number: [REDACTED]
Total Amount Owed: \$7,384.85

Dear Sir or Madam,

A review of the facts of the above loss indicates that your product failed and caused damage to our insured's property. We have made payment to our insured for these damages, and now seek reimbursement from you. **WE RESPECTFULLY ASK THAT YOU NOT RESPOND TO OUR REQUEST WITH A FORM LETTER.**

You will find this correspondence and its enclosures contain substantive information and support adequate for your firm to make a decision concerning your liability.

The entities in the stream of commerce, such as you, a manufacturer, are liable in both negligence and product liability. As you know, your obligation is to properly design and test, manufacture, and give appropriate instructions for installation and use of your product.

Our insured's 1997 Ford Expedition, VIN 1FMPU18L1V[REDACTED] caught fire damaging our insured's driveway and some personal property. According to the enclosed cause & origin report, the origin of the fire was at the power distribution box in the left rear of the engine compartment. It was a catastrophic short between the power feed wire to the power distribution box and a metal bracket.

Your product did not meet the expectations of my insured, the consumer. Your product failed and caused the loss resulting in damages of 7,384.85. Attached are documents substantiating payment.

It is our desire to settle this claim without causing you the additional time and cost of litigation or arbitration. After reviewing the enclosed, please call me to discuss resolving this matter.

Sincerely,
Fire Insurance Exchange

ER05-003-LC-0037

Allison Herrera

Allison Herrera
Property Subrogation Representative
512-238-5730
allison.herrera@farmersinsurance.com
ENCLOSURES

FORENSIC AUTOMOTIVE

P.O. BOX 22333
DENVER, COLORADO 80222
(303) 758-3665

June 1, 2005

Michael Kindig
Farmers Insurance Co.
7585 E. Hampden Ave. Suite 302
Denver, Co. 80231

RE: Insured - [REDACTED]
Claims # - [REDACTED]
Date of loss - 05/14/05
Our file # 3000 RM

Dear Mr. Kindig,

Per your request, we have made an inspection of a 1997 Ford Expedition bearing VIN # 1FMEU10L1V[REDACTED] having an odometer reading of unknown miles.

The purpose of our inspection was to determine the origin and cause of the vehicle fire that occurred May 14, 2005.

For this inspection, we were provided with or obtained the following information, materials and/or inspections:

1. Physical inspection of the vehicle at Cozy Corner Towing, 188 S. 120th St., Lafayette, Co. 05/23/05.
2. Research of National Highway Transportation Safety Administration (NHTSA) website
3. Research of wiring diagrams
4. Oil analysis - Titan Labs, 1380 Zuni St., Denver, Co.

BACKGROUND:

According to the information provided by your office, the insured had parked the vehicle in his driveway approximately 30 minutes prior to a neighbor noticing that the vehicle was on fire.

OBSERVATIONS:

1. The vehicle is a 4-wheel drive SUV equipped with a fuel-injected 5.4L V8 engine coupled to an automatic transmission and transfer case.
2. Exterior damage is heaviest to engine compartment and grille. The aluminum alloy hood was consumed except for a small section at the right rear above the location of the battery. The entire plastic grille was consumed. The paint is burnt off approximately half way back on the right front fender. The right inner fender liner was partially melted and the right front tire was slightly damaged by the heat and flames, but still held air. All of the paint was burnt off of the left front fender except part of the trailing edge. Part of the left front door adjacent to the mirror was also damaged. The left front tire was burnt and flat. The windshield is heavily damaged from the lower left corner as the flames impinged the passenger compartment. All of the remaining glass and body panels are intact.

Our File No. 3060RM

Page 2

3. Interior damage is heavy on top of the left side of the dash. The flame travel from the dash can be observed up to the visors and headliner. The plastic overhead HVAC control panel is melted and hanging down by its wiring harness. The damage decreases toward the rear. A large amount of drop-down was noted under the dash on the left front floor. The seats and remainder of the interior are only slightly smoke damaged.
4. All of the engine compartment accessories are present and correctly located. The battery is mounted near the right rear corner of the engine compartment. A section of the aluminum hood remains over the battery. The lead battery posts are melted and the plastic battery case consumed. A large portion of the aluminum radiator was consumed in the center. The plastic and rubber components located in the engine compartment were consumed including the fuel lines.
5. The battery cables are fire damaged but do not exhibit evidence of a catastrophic short. Two primary wires from the battery to the starter solenoid are rigid but not shorted. The alternator output wire is fire damaged but not shorted. A major voltage supply wire traverses the rear of the engine compartment terminating at the power distribution box in the left rear corner. This wire is shorted against the metal bracket of the power distribution block. The wire strands are partially fused to the metal bracket. A large amount of oxidation and clean-burn is present along the left inner fender.
6. Laboratory analysis of an engine oil sample taken from the crankcase revealed normal wear metals and is positive for water contamination from condensation. A sample from the transmission revealed high lead and tin from extended service. The metals originate from wear on bushings and/or thrust washers.

CONCLUSIONS:

In conclusion, based upon my education, experience and background, it is my professional opinion that the origin of the fire is at the power distribution box in the left rear of the engine compartment as evident by the fire burn patterns, flame travel, and decreasing damage away from this area.

The cause of the fire was determined to be a catastrophic short between the power feed wire in the power distribution box and a metal bracket. The wire is partially fused to the bracket where it grounded. The first material ignited was the insulation on the shorted wire.

Other systems, such as the fuel, ignition, or exhaust system were not involved, as the vehicle was not being operated at the time of the fire.


No related information was obtained through research of safety recalls, T.S.B's., or defect investigations. Given possible related consumer complaints were discovered on the N.T.H.S.A. website, however details of the fire and the investigations are not available on the site. Copies of the complaints are included for your review.

Oil analysis is a rapid screening method for internal wear but still requires teardown for confirmation.

Our File No. 3000F01
Page 3

Enclosed is a series of photographs pertaining to our inspection along with a statement for services rendered.

Very truly yours,



James (Rob) Myers
ASE Master Auto & Truck Technician
ASE Certified Engine Mechanic
ASE Certified Collision Repair Technician

JMM:dy
ENCL

*****NOTICE*****

IF ANY PARTS OR ITEMS WERE RETAINED PERTAINING TO THIS CASE, THEY WILL BE DISPOSED OF AFTER 8 MONTHS FROM THE DATE OF THIS REPORT. THIS ENTIRE REPORT AND FILE WILL BE DESTROYED AFTER 3 YEARS FROM THE ABOVE DATE, UNLESS WRITTEN NOTICE IS RECEIVED BY FORENSIC AUTOMOTIVE, AT:

P.O. BOX 22883, DENVER, CO 80222

FAX (303) 308-2107

NO FURTHER NOTIFICATION WILL BE MADE

ER03-003-LC-0061

Mountain View FPD Incident Report

Printed: 5/14/2005 4:00:07 PM

Run # Reporting Person Date Dispatch Arrive/Cancel In Service Response On Scene

0949 Bennett, Cody 6/14/2005 14:11 14:22 14:54 11 32

8317 Pawnee Ln., CO 0

Occupant:

MAPREF: L8

Location:

Situation Found:

- ☐ Structure Fire
☒ Vehicle Fire
☐ Tree/Brush/Grass Fire
☐ AG Burn Attended
☐ AG Burn Not Attended
☐ Smoke Investigation
☐ Fire Alarm

- ☐ Trash Fire
☐ Electrical Fire
☐ Air/Gas Leak Fire
☐ Explosion Fire
☐ Other Fire
☐ Hazardous
☐ Suspicious

- ☐ MVC w/ Injuries
☐ MVC w/o Injuries
☐ Emergency Medical Call
☐ Service/Assist Call
☐ Standby
☐ Unable To Locate
☐ Cancelled In Route

- ☐ Mutual Aid Given
☐ Mutual Aid Received
 Entry:
 # Of Alarms 9
☐ Supplemental Report
☐ Refer To Investigation

Ignition Factor:

- ☐ Incendary
☐ Mechanical Failure
☐ Reckless
☐ Construction Deficiency
☐ Misuse Of Heat
☐ Natural Condition
☐ Other

Action Taken:

- ☐ Investigate Only
☐ Medical Assist Transport
☐ Medical Assist No Transport
☒ Extinguishment
☐ Remove Hazard
☐ Fill In/Info
☐ Outside Agency Transport

- ☐ Extrication
☐ Standby
☐ Not Classified
☐ Salvage
☐ Undetermined

Participation:

Aerial: 0
 Ambulance: 1
 Brush: 0
 Engine: 1
 Personnel: 4
 Rescue: 1
 Tanker: 0
 Other: 0

Responding Agency:

- ☐ LEU ☐ TAAD ☐ CSP
☐ EPD ☐ WAS ☐ OPD
☐ SSO ☐ WSO ☐ Long FD
☐ FPD ☐ FPD ☐ EPA
☐ Flight For Life ☐ FFFPD
☐ SCP ☐ PMA ☐ AirLife
☐ LAFD ☐ NW Metro

Station Dispatched:

- ☒ Station1 ☒ 2201 ☐ 2251 ☐ 2252 ☐ 2253 ☐ 2254
☐ Station2 ☐ 2202 ☐ 2222 ☐ 2232 ☐ 2242
☐ Station3 ☐ 2203 ☐ 2233 ☐ 2243
☒ Station4 ☐ 2204 ☐ 2215 ☒ 2224 ☐ 2234 ☐ 2244
☐ Station5 ☐ 2205 ☐ 2235 ☐ 2245
☐ Station6 ☐ 2206 ☒ 2221 ☐ 2226 ☐ 2236
☐ Station7 ☐ 2207 ☐ 2208 ☐ 2237 ☐ 2247


Personnel:

Beecher, Philip
 Bennett, Cody
 Cohen, Mitchell
 Deble, Todd
 Plank, Josh

2201/2221/2224 to above address on a car fire. 2221 in service, cancelled in route. 2201 arrival, assisting 2224 with extinguishment, 2201 in service.

Incident Commander: Paul Gerosa, Engineer

Signature: 




**APPLIED TECHNICAL SERVICES, INCORPORATED****ISO 9001**1198 Atlanta Industrial Drive Marietta, GA 30066 (770) 423-1400 Fax (770) 424-6415 e-mail tsa@atslab.com www.atslab.com

May 23, 2005

Shawn Norton
Ford Motor Company
300 Parklane Towers West
3 Parklane Boulevard
Dearborn, MI 48126

Subject: Insured: [REDACTED]
Claim #: 63-1656-01
Fire loss involving a 1997 Ford F150 truck and residence

RECEIVED MAY 23 2005



Dear Ms. Norton:

ATS has been retained by Auto Owners Insurance Company in Macon, Georgia to inspect a 1997 Ford F150 truck owned by the insured. It was reported that the fire originated within the engine compartment. I inspected the vehicle on May 20, 2005 and my inspection shows that the fire originated at the Speed Control Disconnect Switch.

Evidence of the fire damage has been documented by still photography and a video record of the x-ray inspection of the switch has been performed.

The vehicle is at the insured's residence located at [REDACTED] Morrow, Georgia [REDACTED]

Based on findings to date, it is likely that Auto Owners will be looking to Ford for reimbursement of their loss. I have the appropriate documentation of the vehicle and will gladly make it available to any Ford representative. As such, I would like to extend the invitation to Ford Motor Company representatives to inspect the insured vehicle and residence.

I am familiar with Ralph Newell and understand that he or one of his associates would most likely be utilized by Ford, and as such, I would be happy to coordinate directly with them if it would be more convenient. Should you have any questions or need any further information, please do not hesitate to contact me. Thank you for your time.


Sincerely,

APPLIED TECHNICAL SERVICES, INC.,

J. T. Merrill, CVFI
Direct Dial 770-218-2180 ext. 3066
Mobile 770-815-2689

Professional Engineers and Scientists
Design - Consulting - Testing and Inspection

Members in: AAFS, ACE, ASM, ASME, ASNT, ASQC, ASTM, AWS, FSC, IAL, NACE, NCSL, NFPA, SACS
GEORGIA SOCIETY OF PROFESSIONAL ENGINEERS, NATIONAL SOCIETY OF PROFESSIONAL ENGINEERS





April 22, 2005

Global Investigations
Ford Motor Company
1 American Road, Suite 127
Dearborn, MI 48126

RECEIVED


MAY 05 2005

MAY 05 2005

RECEIVED

File:

Irving, Texas
214-441-9112



NAE File No.: 4445
Claim No.: GCPD US 039784
Date of Loss: 04/19/2005

Dear Sir or Madam:

This letter is to serve as written notice that representatives from Nelson Architectural Engineers, Inc., as requested by USF&G Specialty (vehicle owner's insurance company), have observed the remnants of a 1999 Ford F-150 pickup subject to a fire loss at the above-referenced residence. It is our preliminary opinion that the origin of fire is in and around cruise control solenoid adjacent to the brake fluid reservoir on the driver's side of the engine compartment. Due to the nature of the fire being a possible material defect, our office, in coordination with USF&G, are making the vehicle available for observation and investigation. It is our understanding that the vehicle has not been moved from its original location since the onset of the fire, and will remain there for the next five (5) business days - to be removed after Friday, April 29, 2005. The vehicle will then be moved to an evidence storage facility and stored for an additional 30 days - until Monday, May 30, 2005. After the 30 days, if no response has been received, the vehicle will then be released for disposal. At this time, the storage facility has not yet been determined.

USF&G's representative is Mr. George Aophoff and he can be reached at 866-237-3179. The adjuster for the claim is Mr. Kevin Carr and he can be reached at 214-794-8257. A quick response of your intentions regarding this matter would be greatly appreciated. If you have any questions regarding this letter, please do not hesitate to call.

With kindest regards,

NELSON ARCHITECTURAL ENGINEERS, INC.
Texas Certificate of Registration # F-000950
Florida Certificate of Authorization #00008255

William R. Young

William R. Young, C.F.I.
Consultant

Andrew J. Feenstra, B.S.
Senior Associate - Engineer

NAE: Letter1-4445.doc

Offices in Texas and Florida

2740 Dallas Parkway, Suite 220 Plano, Texas 75093 tel 469-429-9000 fax 469-126-5200 toll free 1-877-850-8765
www.architecturalengineers.com Teleclaim - Online request for engineering services

MAY 05 '05 15:14

13132484416

PAGE.02

ENR5-005-LC-8064





EA03-085-LC-0085



ER05-005-LC-9056



EA05-085-LC-0057



EA05-025-LC-0058



PRIVILEGED AND CONFIDENTIAL

REPORT DATE: May 26, 2004

REPORT RECIPIENT:
Nationwide Insurance Company
1001 Hector Street, Suite 300
Conshohocken, PA 19428

ATTENTION: Michael Krause

INSURED: [REDACTED]

DATE OF LOSS: May 12, 2004

EXAMINATION LOCATION: Copart - Granville, PA

CLAIM NUMBER: [REDACTED]

CIS FILE NUMBER: 7217-000081

PREPARED BY: John Pflanz, CFEI
Certified Fire & Explosion Investigator

File Status:

- ☒ First and Final Report
- ☐ Initial Report
- ☐ Interim report
- ☐ Final report - File closed

THIS REPORT IS FURNISHED AS PRIVILEGED AND CONFIDENTIAL TO ADDRESSEE.
RELEASE TO ANY OTHER COMPANY, CONCERN, OR INDIVIDUAL IS SOLELY
THE RESPONSIBILITY OF ADDRESSEE.

Insured: [REDACTED]
File No.: 7217-008881

1

ASSIGNMENT:

Received from: Michael Krause, Nationwide Insurance
Instructions: Conduct an Origin and Cause examination of a vehicle fire

Received on: Monday May 17, 2004 3:50 PM
Commenced on: Friday May 21, 2004 8:30 AM
Completed on: Friday May 21, 2004 1:45 PM

Verbal report on: Friday May 21, 2004 3:45 PM
Verbal report to: Mike Krause of Nationwide Insurance Company

RISK:

Make	1999 Ford	Model	Ranger Pick-up
VIN	1FTYR11VXX[REDACTED]	License Plate	None

ORIGIN AND CAUSE SUMMARY:

The area of origin for this fire is the engine compartment, forward most section.

From the area of origin, the fire spread to the combustible materials (hoses, belts, and wiring insulation) and flammable products (gasoline, oils, and other fluids) common to the engine area before entering the passenger compartment through the windshield/dash area.

The ignition source for this fire is undetermined. Most of the lightweight materials were consumed by the fire due to the fiberglass hood burning away and allowing for unrestricted flame progression.

The first material ignited is undetermined due to the full consumption of most flammable and combustible engine parts.

The event that brought the ignition source and the first material ignited together is undetermined.

BACKGROUND:

There was no background information on the fire event available on this file.

Insured: [REDACTED]
File No.: 7217-000061

2

VEHICLE EXAMINATION:

The vehicle examination took place at the COPART facility in Grantville, PA, where the vehicle was stored under Lot [REDACTED]. The vehicle identity was confirmed by the VIN plate on the driver's side doorpost.

EXTERIOR:

The examination of the vehicle started with the front, and the front area of this vehicle sustained intense fire, heat, and smoke damage. The fiberglass hood and front grill assembly were completely consumed by the fire and most of the remains were lost in transportation. The remaining burned sections of fiberglass from the hood were found down on top of the engine block and in other areas inside the engine section. The front bumper (chrome) was heat stained equally from left to right. The light assemblies on both the driver's and passenger's side were consumed by the fire and not in place at the time of the examination. There was some fiberglass remains to the headlight assembly still attached on the passenger's side of the vehicle only.

The front windshield was not completely broken out, with crazing marks throughout and heavy soot coating on both the inside and outside of the remaining glass. The burn through at the firewall into the passenger compartment was greater on the driver's side front most edge than on the passenger's side.

All the paint from the driver's side fender is burned off down to the bare metal. The holes in the frame for the wheel well plastic framing were exposed and the remains of the plastic wheel well covers were consumed by the fire. The driver's side door of the vehicle was burned off its paint back to approximately midway position and the door was found to have been in the closed position at the time of the fire. The remaining paint on the vehicle is a bright red and it is the same color as the flat cap on the back of the bed. The driver's side door mechanism and locking keyhole appear to be in good shape and unaffected by the fire.

The driver's side window had been in a down position by approximately 2 inches at the time of the fire, and the plastic rain guard over the top half of the window had melted down onto the open window frame. This glass on the driver's side door is unbroken and soot covered, with burned plastic remains attached. The bed driver's side fender area was unaffected by the fire and there is some smoke damage noted greater in the forward section than the rear section. The gas fill cap is in place and this area is unaffected by the fire.

The rear of the vehicle is unaffected by the fire, and the chrome bumper and plastic bumper covering as well as the light assemblies are also unaffected by the fire.

The passenger's side rear fender area is in good shape although there is more paint damage by the fire on this side than on the driver's side, mostly in the forward most section closest to the passenger's side door. There is some melting to the wheel well frames on the passenger's side for the rear wheel tire, although there was none on the driver's side. The front passenger's side door has most of the paint burned off back to the door edge. This door also was in the closed position at the time of the fire. The window was broken out but the remains of the glass are still in place up to the upper most edge, indicating the glass was in a closed position before being broken out. The door opening latch and the keyhole mechanism for the passenger's side doors are both affected by the heat and fire, but there are no signs of any tampering. The paint on the passenger's side front fender is completely burned off and is similarly affected as the driver's side was.

The front two tires were completely burned by the fire, with little or no remains. The rear two tires were in good condition and still inflated. All tires appear to have been the matching Goodyear Wrangler RT/S.

INTERIOR:

The interior of the vehicle was examined and found to be heavily smoke and heat damaged. The greatest damage to the interior of the vehicle was on the front most passenger's side where the fire had extended from the engine into the HVAC opening at the glove compartment section. There was also a large amount of burned debris on the passenger's side front floor area. This material appeared to have been in that location prior to the fire. This debris had no effect or involvement with this fire, as it was a non-combustible material.

ENGINE COMPARTMENT:

The examination of the engine compartment showed that the main body of fire originated from this location. Most of the combustible materials (hoses, belts, and wiring insulation) and flammable products (gasoline, oils, and other fluids) common to the engine area were consumed by the fire or lost in transport. As the vehicle was equipped with a fiberglass hood, which was also consumed by the fire, a metal hood covering did not restrict the fire progression.

Based on the most extensive fire damage to the engine parts, the forward most upper section of the engine compartment was determined to be the area of origin of this fire. The entire radiator assembly and mounting brackets were either consumed by the fire or lost in transport. The wiring harness running through the area of origin, over the original radiator location, was extensively damaged by fire. All of the insulation was burned off and some sections of copper wiring were not continuous.

The fire consumed all fuel lines, brake lines, and other liquid flexible lines running through the front and center sections of the engine. The only remaining sections of burned hoses were located at the top rear of center section of the engine area. Upon completion of the examination of the engine compartment, the area of origin was determined; however, the ignition source could not be determined.

VEHICLE UNDERCARRIAGE:

The undercarriage of the vehicle was examined starting at the rear. There was no fire damage to the rear section of the cab aft of the rear wheel axle. There was less of the undercoat paint burned off on the passenger's side than on the driver's side extending back from the rear axle forward. On the driver's side just forward of the fuel tank were the fuel filter and fuel flexible lines running forward and rear. The rear lines were more intact than the forward lines although both had separated. There was only approximately one-half inch of flexible line remaining on the front connector to the filter, while there were six inches remaining on the rear section. The fuel from these lines accounts for the greater damage on the driver's side, although the fire damage is fairly even from the transmission housing forward.

All the combustible and flammable parts from the rear section of the drive shaft forward were completely consumed by the fire with the exception of a few rubber grommets on the protected sections by the framing. The damage noted at the front forward most engine section from the undercarriage shows extensive and complete consumption of all combustibles from the engine block forward. This includes the radiator housing line and hoses and attachments.

Most of the electrical wiring is not complete and has been burned through in many sections. The sections that are still complete and attached at both ends have no insulation protection for the wiring remaining. The fire consumed all the flexible rubber type hoses, with just the metal connection grommet still in place.

INTERIOR TRUCK BED:

The flat cap was raised and the interior of the truck bed was examined. There was some loose debris that had been placed back in the bed apparently from the site of the fire. There were large sections of the driver's side tire that were still not in place on the vehicle that were found in the bed, as were the remains of the metal vent unit for the passenger's compartment heat/AC. There were also a number of sections of electrical wiring, electrical components, and a coil type thermostatic control. All these items were extensively damaged and had fallen off of the vehicle apparently before initial transportation.

CONCLUSION:

After a thorough inspection of the entire vehicle, including an evaluation of the critical vehicle systems (fuel, electrical, mechanical) and all fluids, I have determined that this fire originated in the engine compartment; however, due to the extensive fire damage consuming most light materials and fluids and the number of missing engine parts, the ignition source is undetermined.


FILE STATUS:

At the present time and with no further investigation immediately anticipated, this file is being closed. Should future circumstances warrant, this file can be easily reopened to allow for additional investigation.

Respectfully,

John Pflanz
Certified Fire & Explosion Investigator
Broomall, Pennsylvania
(610) 358-8518

(Address all correspondence concerning this file to the following address. Please include the CIS file number.)
Crawford Investigation Services, Inc.
National Operations Center
286 W. Esplanade Ave., Suite 200
Kenner, LA 70065



TRAVELERS


TRAVELERS PROPERTY CASUALTY INSURANCE COMPANY
 SHARON T. REIS
 PO BOX 3822
 FALL RIVER, MA 02722-3822
 (508) 324-8289 x 8289
 (508) 324-8289

MAY 17 2005

CUSTOMER
 RELATIONSHIP
 CENTER

MAY 16 A 8 09

FORD MOTOR CO
 CONSUMER AFFAIRS
 P.O. BOX 6248
 MD-3NE-B
 DEARBORN MI 48126



Our Client: [REDACTED]
 Claim/File #: [REDACTED]
 Date of Loss: [REDACTED]
 Your Insured: [REDACTED]
 Your File #: RECALL
 Reference: Subrogation Claim

Dear FORD MOTOR:

We are managing a claim on behalf of [REDACTED] who sustained damages on 04/25/2005.

Based on our investigation, we have determined that your insured may be responsible for this loss. Our adjuster has not yet completed the adjustment. Once this is complete, we will forward our supporting documents for your consideration.

Sincerely,
 SHARON T. REIS
 Claim Representative
 (508) 324-8289
 Fax:
 Email:




EP05-885-LC-8873

5/26/2005




ER85-005-LC-8876

5/26/2005



ER05-005-LC-0077

5/26/2005



Wolf TECHNICAL SERVICES INC.

Technical Investigations

Forensic Analysis

Engineering Consultants

Demonstrative Evidence

6836 Hawthorn Park Drive • Indianapolis, IN 46220-3909 • (800) 783-9653 • (317) 842-6075 • FAX (317) 842-6974

www.wolftechnical.com

May 11, 2001

Guide One Insurance
7702 Woodland Drive
Suite 100
Indianapolis, IN 46278

Attention: [REDACTED]

RE: [REDACTED] (insured)

Client File #: 13A 31088
WOLF Project #: 01-2858-0239



This narrative is accompanied by WOLF six (6) pages of Vehicle Examination Report, twenty-four photographs, a photograph description sheet, NHTSA recall information and ALLDATA service bulletins.

Our examination of this vehicle was performed on April 12, 2001, in Indianapolis, Indiana. The examination revealed that there was no evidence of any components of this vehicle having been removed or altered prior to the fire. All the tires and wheels matched and were serviceable. The exterior and the interior of this vehicle appeared to be maintained in a normal fashion. There was no evidence of body damage prior to fire. The engine and its components also appeared to be intact, except for the fire damage. There was no evidence of any alterations to the engine or any of the components prior to the fire.

We examined the vehicle's exterior and observed a burn pattern on the passenger's side of the vehicle. This burn pattern was in the form of paint damage to the front fender, the engine compartment hood and on the passenger's side of the vehicle. The front tire on the passenger's side also showed evidence of fire damage in that the top of the tire was partially melted.

We examined the interior of the vehicle and observed that there was evidence of fire damage to the interior of the glove compartment. The glove compartment housing was totally destroyed by fire. We looked into the damaged glove compartment and were able to see into the engine compartment through a hole in the fire wall, where the heating & cooling fan unit had been

01-2858-0239, FWW

1

"...Pursuing and applying truth through scientific analysis." for over 20 years

EA05-005-LC-0078

WOLF TECHNICAL SERVICES INC.

May 11, 2001

mounted. Adhered to the inside of the glove compartment door was evidence of melted plastic. On the floor of the passenger's side, we observed a cardboard box. Inside the box, we located and photographed fire damage to the components from the engine compartment. The cardboard box had been placed in the vehicle after the fire to secure any loose items from the vehicle. We do not know who may have gathered the items or furnished the box. The rubber floor mat from the passenger's side was located and photographed. It had suffered fire damage in that the upper one-third had been destroyed. Adhered to the floor mat was a plastic component that appeared to be a part of heating and an condition system.

There is fire damage to the engine in the engine compartment. This fire damage is in the form of melting of the rubber and the plastic components nearest the origin. The metal components show evidence of fire damage in the form of oxidation. The fire damage is much greater on the passenger's side of the engine, near the fire wall immediately behind the glove compartment. We located and photographed a component that was severely damaged from the heat in this immediate area, but was still attached to the electrical wiring. The component was the resistor assembly used to regulate the speed of the blower motor.

We located and photographed the fuse panel and fuses. There are a total of 25 fuses in the panel. They range in sizes of 7.5 amps to 30 amps. Of the 25 fuses, the following 9 fuses were blown.

1. #10-7.5 amps for speed control servo-shift lock actuator -AC- heater assembly, turn signals
2. #13-20 amps for brake pedal position switch
3. #16-30 amps for windshield wiper motor, wiper hi-low relay, park relay
4. #17-25 amps for cigar lighter
5. #18-15 amps for driver's unlock relay, all lock relay
6. #21-15 amps for flashers
7. #22-20 amps for auxiliary power relay
8. #26-10 amps for battery saver relay, elect shift relay, interior light relay, power window relay, dome light, GEM, instrument Cluster
9. #29-15 amps for radio
10. Fuses #16 and #29 were observed to have evidence of heat damage, see photographs #23 and #24

The origin of this loss is the heater case in the engine compartment. The cause is unknown at this time, but there is no doubt that a product placed in the vehicle at the

WOLF TECHNICAL SERVICES INC.

May 11, 2001

time of manufacturing by the Ford Motor Company malfunctioned and caused ignition of combustibles in proximity. There appears to be an avenue of subrogation in this loss.

Due to spoilation issues, we have not removed anything. All of the evidence that we examined and photographed, was left in the vehicle. We did not remove or alter anything.

We suggest that an engineer observe the examination of the evidence by a Ford representative. If we can be of any further assistance in this matter or any other matter, please feel free to contact our office.

Respectfully Submitted,


Floyd White,
Fire Investigation Specialist

For the laboratory,


James Casassa, P.E.

FWW / js
Enclosures:

WOLF TECHNICAL SERVICES INC.

May 11, 2001

PHOTOGRAPHIC INFORMATION SHEET

01-2858-0239

1. Front of vehicle
2. Passenger side of vehicle
3. Rear of vehicle
4. Driver's side rear of vehicle
5. Driver's side front of vehicle
6. Dashboard driver's side
7. Dashboard passenger's side
8. Glove compartment passenger's side
9. Interior of glove compartment
10. Miscellaneous components from area of glove compartment
11. Burn pattern on front fender of passenger's side
12. Top of burn pattern
13. Top of engine from front of vehicle
14. Top of engine from passenger's side
15. Engine side of fire wall behind glove compartment
16. Section of damaged fire wall
17. Top of unidentified electrical component from area of glove compartment
18. Bottom of unidentified electrical component from area of glove compartment
19. Front of unidentified electrical component from area of glove compartment
20. Fuse Panel
21. Fuse panel damage to #16
22. Rear of fuse panel and connecting wiring
23. Fuse #16
24. Fuse #29

WOLF TECHNICAL SERVICES, INC.



1
Photo Number



2
Photo Number

EP05-005-LC-0002

Page Number 1 of 12

WTS Project Number 01-2858-0239

WOLF TECHNICAL SERVICES, INC.



3
Photo Number



4
Photo Number

ERG-885-LC-8083

Page Number 2 of 12

WTS Project Number 01-2858-0239

WOLF TECHNICAL SERVICES, INC.



5
Photo Number



6
Photo Number

ENFS-005-10-0004

Page Number 3 of 12

01-2858-0239

WOLF TECHNICAL SERVICES, INC.



7
Photo Number



8
Photo Number

2005-085-10-0005


Page Number 4 of 12

WTS Project Number 01-2858-0239

WOLF TECHNICAL SERVICES, INC.



9
Photo Number



10
Photo Number

ERR-005-10-0005

Page Number 5 of 12

WTS Project Number 01-285P-0239

WOLF TECHN



11

Photo Number



12

Photo Number

ENC-885-LC-8887

Page Number 6 of 12

WTS Project Number 01-2858-0239

WOLF TECHNICAL SERVICES, INC.



13
Photo Number



14
Photo Number

EAHS-003-LC-0008

Page Number 7 of 12

WTS Project Number 01-2858-0239

WOLF TECHNICAL SERVICES, INC.



15

Photo Number



16

Photo Number

2005-000-LC-0000


Page Number 8 of 12

WTS Project Number 01-2858-0239

WOLF TECHNICAL SERVICES, INC.



17
Photo Number



18
Photo Number

EN03-002-LC-0028

Page Number 9 of 12

WTS Project Number 01-2858-0239

WOLF TECHN



19

Photo Number



20

Photo Number

ENG-885-LC-8891

Page Number 10 of 12

WTS Project Number 01-2858-0239

WOLF TECHN.



21

Photo Number

22


Photo Number

EROS-BOS-4C-0002

Page Number 11 of 12


WTS Project Number 01-2858-0219

WOLF TECHNICAL SERVICES, INC.



23

Photo Number



24

Photo Number

0000-000-10-0000

Page Number 12 of 12

WTS Project Number 01-2858-0239

BEDFORD FIRE DEPARTMENT FIRE REPORT

2324

INCIDENT NO

DATE 3-29-01 SHIFT 3 TIME OUT 17:32 ARRIVAL TIME 17:35
OFFICER IN CHARGE AT SCENE Viscavara TIME IN 18:05
TYPE OF INCIDENT FIRE ☒ EXTRICATION ☐ HAZ MAT ☐
SERVICE CALL ☐ OTHER ☐
ADDRESS [REDACTED] PHONE [REDACTED]
OWNER OF PROPERTY [REDACTED]
OCCUPANTS [REDACTED]
OF INJURIES # OF FATALITIES STATIONS RESPONDING 1 2 3
EQUIPMENT DISPATCHED ENGINES 1 2 3 4 7 RESCUE 5 10
VAN 8 CAR 1 15 16
HOSE USED BOOSTER ☒ 1 1/2 2 1/2 HYDRANT USED
INSURANCE CO. Met Life AGENT DOLLAR LOSS
OFFICER MAKING REPORT Yarr
ADDITIONAL INFORMATION See file



MEACHUM SPAHR COZZI POSTEL & ZENZ
ATTORNEYS AT LAW
11 SOUTH LASALLE STREET
SUITE 2800
CHICAGO, ILLINOIS 60603
TELEPHONE: (312) 726-6317
FAX: (312) 443-9282

LAURENCE MEACHUM
ELLEN L. SPAHR
JOSEPH A. POSTEL
RICHARD L. ZENZ

MICHELLE ANDERSON
KEVIN L. BECKER
JOHN L. BOYLE
ADAM J. COOK
DREW J. DAVIS
STEPHEN L. JACKSON
MARSHALL L. KELLY
EDWARD L. KOSCHOWSKI
RICHARD L. KOSCHOWSKI
WILLIAM M. KELLEY
GARY A. MARSH
ELIZABETH M. MYER
PATRICK H. NICHOLS
CAREY J. O'NEILL
CARL A. REDMOND

A Staff Legal Office of the Liberty Mutual Group
Not a Partnership or Professional Corporation

THOMAS W. STARK
JAMES C. STEPHENSON
THOMAS E. STOKALALA
HOWARD T. TRAPMAN

EL PARALAGAL
GENEVA KENNEDY

PARALEGALS
SHARON K. KYLE
MARIONA BRANER
ELISA DE LA FUENTE
RUSTIN DUBASH
MICHAEL HAMILTON
DEBRA L. JENSEN
JUSTY A. JOHNSON
SCOTT J. MULLO
SANDY M. MARY
LATCHANA E. RICKERS
CHRISTINE TERRY

May 10, 2005

Ford Motor Company
Risk Management Department
P.O. Box 6248
Dearborn, MI 48126

Insured: [REDACTED]
Date of Loss: May 4, 2005
Location of Loss: [REDACTED] Camby, Indiana
Claim No: [REDACTED]

195 F-150

To Whom It May Concern:

We have been retained to represent Indiana Insurance Company with regard to the above-referenced loss. Indiana insures the property at the above reference location. This loss arises out of a fire that occurred at our insured's premises on May 4, 2005. Damages from this loss are approximately \$400,000.00.

Our preliminary investigation reveals that Mr. Ragan's F-150 truck was parked in his garage when the engine caught fire due to a faulty switch on the cruise control. The fire quickly began to spread and ultimately damaged the entire truck and house. Luckily, no one was injured. Our insured was the original owner of the truck. Accordingly, please accept this letter as notice of claim against Ford Motor Company. Please forward this letter to your insurance carrier immediately, and have them contact the undersigned. Although we have conducted a fire scene investigation of the loss site it is still available for inspection. Furthermore, we intend to perform destructive testing on the component parts that caused this fire. Since our insured must mitigate its damages, time is of the essence. It is, therefore, critical that you or your insurance carrier retain any necessary experts and have them available to participate in future testing/investigation as soon as possible.

We would also appreciate your assistance in identifying any additional parties who may bear responsibility for this loss. If there are any additional parties, including any subcontractors or suppliers whom you believe should be placed on notice, please let us know.

EN05-005-LC-0005

Ford Motor Company

May 10, 2005

Page 2

Please preserve any documents, contracts, warranties, product literature, warnings or any other materials relevant to components in the engine and cruise control identified above. Additionally, send copies of any such documents to the undersigned at your convenience.


We look forward to working with you to resolve this potential claim. Should you have any questions or concerns please feel free to contact me or my paralegal, Meka Hamilton-Dukes.

Very Truly Yours,


Gary A. Marek

GAM/mhd

ER35-005-LC-9085




THE CHARTER OAK FIRE INSURANCE COMPANY
MARK SLUDER
PO BOX 2954
MILWAUKEE WI 53281-2954
(888) 623-6337 X 4785
(262) 787-4785

MAY 05 2005

April 28, 2005

FORD MOTOR COMPANY
PO BOX 6248
DEARBORN MI 48121



Our Client: [REDACTED]
Claim/File #: [REDACTED]
Date of Loss: 04/21/2005
Reference: Subrogation Claim

Dear Consumer Affairs Division:

We are investigating a claim for [REDACTED] who sustained a loss on 04/21/2005.

Our investigation reveals that you may be responsible for this loss. If you have insurance, please complete the attached form and return it to me. Please refer this letter to your insurance carrier immediately, requesting that they contact our office. Should you not have insurance, please contact me to discuss this loss.

Please call me with any questions.

This loss is involving a 2000 Ford Ranger that caught on fire.

Sincerely,
MARK SLUDER
Claim Representative
(262) 787-4785
Fax: 866-280-7367
Email:

Nothing in this letter is intended or should be construed as an admission or denial of coverage to our insured.

Enclosure: Insurance Questionnaire

EM00-005-10-0097

Subro Rep. Name: MARK SLUDER

Insured: [REDACTED]

Date of Loss: 04/21/2005

Our File No.: 266 FR L0Y3595 H

Your Insurance Company's Name: _____

Your Insurance Company's Address: _____

ZIP _____

Phone: (____) _____

Your Insurance Agent's Name: _____

Address: _____

ZIP _____

Phone: (____) _____


Your Policy Number: _____

Your File Number: _____

Your Adjuster's Name: _____

Phone: (____) _____

EP00-000-LC-0000





KENTUCKY BASIC INCIDENT REPORT

Notes contained in this report are intended for the sole use of the State Fire Marshal, Kentucky, and are not to be used for any other purpose. Any representation as to the validity or accuracy of reported conditions outside the State Fire Marshal's office is neither intended nor implied.

NFIRS - 1

THIS REPORT
IN OWN WORDS

FIRE DEPARTMENT

1. ☐ DELETE
2. ☐ CHANGE

FD#	INCIDENT NO.	MAP NO.	NO.	DAY	YEAR	DAY OF WEEK	ALARM TIME	ARRIVAL TIME	TIME IN SERVICE
219112	990495	1	0304	95		1. Sunday 2. Monday 3. Tuesday 4. Wednesday 5. Thursday 6. Friday 7. Saturday	0312	0317	0005

TYPE OF STRUCTURE	TYPE OF ACTION TAKEN	MUTUAL AID
<input type="checkbox"/> 1. Structure fire <input type="checkbox"/> 2. Outside of structure fire <input type="checkbox"/> 3. Vehicle fire <input type="checkbox"/> 4. Trench, brush, grass fire <input type="checkbox"/> 5. Refuse fire	<input type="checkbox"/> 1. Extinguishment <input type="checkbox"/> 2. Removal only <input type="checkbox"/> 3. Investigation only <input type="checkbox"/> 4. Removal of structure <input type="checkbox"/> 5. Salvage <input type="checkbox"/> 6. Salvage only <input type="checkbox"/> 7. Salvage of structure <input type="checkbox"/> 8. Salvage of contents <input type="checkbox"/> 9. Salvage of structure and contents <input type="checkbox"/> 10. Salvage of structure and contents and structure	<input type="checkbox"/> 1. Yes <input type="checkbox"/> 2. No <input type="checkbox"/> 3. Other

LOCAL PROPERTY LOSS	IGNITION FACTOR
4000000	SHORT CIRCUIT

ZIP CODE	CENSUS TRACT
60611	514

ADDRESS	TELEPHONE
500 MOTOR CREDIT CO.	800-727-7000

METHOD OF ALARM FROM PUBLIC	NUMBER FIRE SERVICE PERSONNEL	NUMBER ENGINE RESPONSE	NUMBER ALARM APPARATUS RESPONSE	NUMBER OTHER VEHICLES RESPONSE
<input type="checkbox"/> 1. Telephone alarm <input type="checkbox"/> 2. Bell alarm <input type="checkbox"/> 3. Bell alarm with siren <input type="checkbox"/> 4. Bell alarm with siren and light	1017	991	1010	1010

NUMBER OF INJURIES	NUMBER OF PRIORITIES
0	0

NUMBER OF INJURIES	NUMBER OF PRIORITIES
0	0

NUMBER OF INJURIES	NUMBER OF PRIORITIES
0	0

NUMBER OF INJURIES	NUMBER OF PRIORITIES
0	0

NUMBER OF INJURIES	NUMBER OF PRIORITIES
0	0

NUMBER OF INJURIES	NUMBER OF PRIORITIES
0	0

NUMBER OF INJURIES	NUMBER OF PRIORITIES
0	0

NUMBER OF INJURIES	NUMBER OF PRIORITIES
0	0

NUMBER OF INJURIES	NUMBER OF PRIORITIES
0	0

NUMBER OF INJURIES	NUMBER OF PRIORITIES
0	0

NUMBER OF INJURIES	NUMBER OF PRIORITIES
0	0

NUMBER OF INJURIES	NUMBER OF PRIORITIES
0	0

NUMBER OF INJURIES	NUMBER OF PRIORITIES
0	0

NUMBER OF INJURIES	NUMBER OF PRIORITIES
0	0

NUMBER OF INJURIES	NUMBER OF PRIORITIES
0	0

NUMBER OF INJURIES	NUMBER OF PRIORITIES
0	0

NUMBER OF INJURIES	NUMBER OF PRIORITIES
0	0

NUMBER OF INJURIES	NUMBER OF PRIORITIES
0	0

NUMBER OF INJURIES	NUMBER OF PRIORITIES
0	0

NUMBER OF INJURIES	NUMBER OF PRIORITIES
0	0

NUMBER OF INJURIES	NUMBER OF PRIORITIES
0	0

NUMBER OF INJURIES	NUMBER OF PRIORITIES
0	0

NUMBER OF INJURIES	NUMBER OF PRIORITIES
0	0

ENCLOSURE

CONTACT FOR ALL INFORMATION

CONTACT FOR ALL INFORMATION

CONTACT FOR ALL INFORMATION

CONTACT FOR ALL INFORMATION

CROFTON VOLUNTEER FIRE DEPARTMENT
P.O. BOX 261
CROFTON KY 42217

RUN SHEET

DATE: 3 / 4 / 95 TIME: ALARM 23:22 10:8 23:24 10:9723 :27 10-9823:55
10-10 20:10 5
TYPE OF FIRE: HOUSE () BARN () VEHICLE (✓) GRASS () OTHER: _____

LOCATION: 2 1/2 MILES NORTH ON OLD MADISONVILLE RD.

OWNER: [REDACTED] ADDRESS: [REDACTED] CROFTON, KY
PHONE: [REDACTED]

OCCUPANT: FORD MOTOR CO. PHONE: 1-800-727-7000
ADDRESS: P.O. BOX 98306 CHICAGO ILL. 60680-7306

OFFICER IN CHARGE: NELSON A. COKER TITLE: CHIEF
OF FIRE PERSONEL: 7 # OF ENGINES: 1 # OF TANKERS: 0
WAS MUTUAL AID RECEIVED: NO FROM WHAT DEPT.: _____

DESCRIBE ACTION TAKEN: EXTINGUISHMENT, WITH A A.B.C. EXTINGUISHER

OWNER'S INSURANCE CO: ALLSTATE AGENT: DARRYL CUNNINGHAM
ADDRESS: 806 B COUNTRY CLUB LN PHONE: 886-0650 AGENT#

IF VEHICLE OR MOBILE HOME:
YEAR: 1995 MAKE: FORD MODEL: F-150 XL SERIAL: _____
LICENCE# [REDACTED] STATE: KY

LIST FIREFIGHTERS RESPONDING:

NELSON A. COKER
HENRY HULBERT
KAY DURHAM
TAD DURHAM
AGNES NOEL
RONNIE E. BROWNING
RONNIE J. BROWNING

IFTEFISN3S [REDACTED]

REMARKS: SHORT CIRCUIT IN WIRING HARNESS UNDER DASH BOARD.
SMALL FIRE IN DASH BOARD AND FLOOR BOARD ON DRIVERS SIDE.

FIREFIGHTER MAKING REPORT: Nelson A. Coker DATE: 3/4/95.

1. The first step in the process is to identify the problem or issue that needs to be addressed. This involves gathering information and understanding the context of the problem.

2. Once the problem is identified, the next step is to analyze the problem and determine the causes. This involves looking at the data and identifying the factors that are contributing to the problem.

3. After analyzing the problem, the next step is to develop a plan of action. This involves determining the steps that need to be taken to solve the problem and assigning responsibilities to the appropriate individuals.

ALLSTATE INSURANCE
715 SECOND ST.
HENDERSON KY 42420

Date: 20-MAR-95 035

Make: FORD TRUCK

Model: F150

Year: 1995

No recall information on above vehicle(s).

MAR-24-1995

INS INVESTIGATIONS BUREAU, INC.
PHOTOGRAPH NEGATIVES

INSURED

LOCATION

POLICY NO.

TAKEN BY

CLAIM NO.

INS FILE NO.

ENCLOSURE

Form 1002 (1/70)

ENCLOSURE-10-8163

1995

NS


4 0000 (11/00)

Photo Sheet

INS No.

90501 06463

Insured



No.

11



EMD-200-10-0104

No.

12


8001 1 1000

Page

6 of 6

Photo Sheet

INS No. 94501-06463
Insured [REDACTED]



No. 9



No. 10

APR 7 1995

Page 5 of 6

ENR-005-LC-0105

Photo Sheet

INS No. 94501-01463

Insured [REDACTED]



No. 7



No. 8

APR 7 1988

ENR-080-10-0188

Page 4 of 6

Photo Sheet

INS No. 94501-06463
Insured [REDACTED]



No. 5



No. 6

APR 7 1995

DNB-003-LC-9187

Page 3 of 6

Photo Sheet

INS No. 94501-06463
Insured [REDACTED]



No. 3



No. 4

APR 7 1995

Page 2 of 6

ENR-800-LC-9186

Photo Sheet

INS No.


9450-06463

Insured



No.

1



No.

2

ENCLOSURE LC-9189

Page

1 of 6

APR 7 1985

INS

Form 8010 (1/86)

Diagram Sheet

Name (Property Owner)

Location


2 miles North of Canton, Ky

Identification No.

94501-06463

②

③



EPR-805-LC-911B

APR 7 1995

→ PHOTO. NO + DIRECTION TAKEN

①

Prepared By

PAUL BARNES, CFEL

Date

3-14-95

Scale

NOT TO SCALE

①

	Yes	No		Yes	No
Open during fire	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Oil below lowest mark on dipstick	<input type="checkbox"/>	<input checked="" type="checkbox"/>
or melted	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Evidence of excessive oil leakage	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Radiator hose burned	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Holes or cracks in transmission case	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Radiator hose burned	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Transmission case burned/melted	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Belts burned	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Transmission has inadequate lubrication	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Hoses burned	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Any problems with drive train/suspension	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Idler arm burned	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Motor mounts burned	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Enders burned	<input type="checkbox"/>	<input checked="" type="checkbox"/>			
Ignition system burned	<input type="checkbox"/>	<input checked="" type="checkbox"/>			

Remarks

	Missing	Burned	Distorted/ Melted	Shorted/ Arced
Wiring	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Wiring connections	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Wiring cables	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Alternator	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Alternator/generator	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
On system	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Panel	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Wiring harness	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

Remarks

	Missing	Burned	Distorted/ Melted
Oil cap	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Oil assembly	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Oil tank assembly	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Oil lines	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Oil pump(s)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Oil filter(s)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Injector/injectors/turbos	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Intake filters	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Evaporator/recovery system	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Exhaust and tail pipes	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Catalytic converter	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Are loose fuel line connections?	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Is evidence of tampering?	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Fuel tank	<input type="checkbox"/> Empty	<input checked="" type="checkbox"/> 1/4	<input type="checkbox"/> 1/2 <input type="checkbox"/> 3/4 <input type="checkbox"/> Full

Remarks

Evidence of any explosion or rupture?	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Was an oil sample obtained?	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Was a fuel sample obtained?	<input type="checkbox"/> Yes	<input type="checkbox"/> No
Were debris samples obtained?	<input type="checkbox"/> Yes	<input type="checkbox"/> No

Remarks

Special Agent

PAUL BARNES, CEET

Date

3-14-95

INS

805-8251

VEHICLE FIRE EXAMINATION REPORT

Insured				INS File Number	94501-06463
Manufacturer	Ford	Year	1995	Model	F-150 XL
Body Style	PU				
State Inspection State	NA	Date	NA	Odometer	003003
Displayed on Vehicle					
Tag Number	307DAE	Year	1995	State	KY.
VIN No.	1-8 ST Ford				
Vehicle Examination Date	3-17-95		Location Little River Ford, Hopkinsville, Ky.		

Fire Damaged Areas	<input type="checkbox"/> Exterior	<input checked="" type="checkbox"/> Interior	<input type="checkbox"/> Engine Compartment
--------------------	-----------------------------------	--	---

	Burned	Distorted/ Melted	Accelerant Patterns	Collision Damage
Bumper and Grill	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Hood	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Left Front	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Right Front	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Roof	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Left Door(s)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Right Door(s)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Trunk	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Left Rear	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Right Rear	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Rear Bumper Area	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Underside	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

TIRES	Burned	CONDITION PRIOR TO FIRE		
		Serviceable	Unserviceable	Uneven Tread Wear
Left Front	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Right Front	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Left Rear	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Right Rear	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Spare	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Tires indicate signs of recent removal/exchange? ☐ Yes ☐ No

Wheels/wheel covers indicate recent removal/exchange? ☐ Yes ☐ No

Indicate areas of forced entry ☐ Door(s) ☐ Hood ☐ Trunk ☐ Glass

GLASS	Smoked	Cracked	Distorted/ Melted	Broken
Windshield	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Left Door(s)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Right Door(s)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Rear	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Sunroof	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Remarks

INTERIOR	Yes		No		Remarks
	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Door(s) open during fire	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	ONLY Damage was to 14401 Writing Markings ON Left Interior of Vehicle. APR 7 1995
Window(s) open during fire	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Was key in the ignition	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Have any accessories been removed	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Any unusual burn patterns	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Any abnormal melting	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Any unusual objects in vehicle	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Was trunk open during fire	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Any unusual objects in trunk	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	

94501-06463

-4-

April 4, 1995

Insured: [REDACTED]

he wanted to talk with the Chief. [REDACTED] looked at him and said, "I'll see you later" and then left. This was 15 to 20 minutes prior to seeing your Insured running toward Crofton on Grapevine Road.

DETERMINATION OF ORIGIN & CAUSE

Due to the amount of destruction to the wiring harness beneath the dash in the cab of this vehicle, it is my opinion that this fire was the result of a manufacturing defect within the wiring harness of this vehicle.

COMMENTS

Mike Utzig, Service Manager at Little River Ford, and Scott Plog stated a Ford representative would be removing the dash so they could get a better observation of all of the wiring in that area. When they are ready to do this examination, they are to notify me so I can be present.

In accordance with your instructions, this file is being placed in closed status but may be reopened at any time upon request.

Paul H. Barnes
Senior Investigator
Telephone/FAX: 602-885-0733

PHB*js

ENDS-885-LC-9113

(a)

April 4, 1995

Insured: [REDACTED]

INVESTIGATION

While driving south on Grapevine Road, approximately two miles north of Crofton, Kentucky, your insured smelled smoke and then felt heat around his feet. Shortly thereafter, the lights began to intermittently go on and off. He pulled the vehicle off to the side of the road, saw a red glow on the floorboard, and both his legs and feet were getting warm. Before exiting the vehicle and closing the door, he made sure the windows were in the up position. [REDACTED] said he started running south toward Crofton and saw Police Chief Otis Henderson's cruiser approaching him. He flagged down the Chief and told him his truck was on fire.

Your insured said he had experienced no problems with the vehicle, other than it pulling somewhat to the left. He was scheduled to take it to Little River Ford, from where he had it leased, to have that deficiency repaired.

My information was that [REDACTED] had used a cellular telephone to call the fire department. When asked about this, he said he had not had a cellular telephone for several months. I also asked him why he did not use his radio to call the fire department. He explained that when his lights began to flicker and the horn started blowing, he knew it was electrical in nature and did not think his radio would work as it was connected to the electrical system. Also, he said that by the time he got the vehicle stopped and observed the fire beneath the dash, the smoke and heat were too intense to remain in the vehicle and attempt to use the radio.

I talked with Kay Durham and Jim Browning, who are EMT's and firefighters with the Crofton Volunteer Fire Department. Ms. Durham told me she thought [REDACTED] had reported the fire on a cellular telephone. She and Mr. Browning stated that when they arrived at the scene, the fire was out and they found that it had been contained to the wiring harness beneath the dash. The vehicle's horn was intermittently blowing and the lights were occasionally flashing. Mr. Browning said that although the fire was nearly out when they arrived, a chemical fire extinguisher was used to ensure extinguishment of any remaining fire.

During a conversation with Police Chief Otis Henderson, he confirmed that he was flagged down by your insured approximately one mile north of Crofton. He said he asked [REDACTED] what he was doing out there and [REDACTED] told him his truck had caught fire. Chief Henderson called the fire department via his radio as he and your insured were returning to the truck. When they arrived, smoke was coming from the cab of the vehicle but no flames were visible. They left the doors in the closed position and awaited the arrival of the fire department.

When Chief Henderson approached the driver's side of the vehicle with his flashlight, he saw a disposable butane cigarette lighter lying in the road by the truck and he asked your insured where it came from. Your insured told him that it must have fallen out of his pocket or from the truck when he exited the vehicle. During my examination, I observed a disposable lighter and several packs of cigarettes lying in the driver's seat.

According to Chief Henderson, he had been conducting an interview in his patrol car earlier in the evening. Your insured pulled up beside his vehicle and sat there as if

add on
[Signature]

EAP-825-10-9114

APR 7 1995

(8)

April 4, 1995

ed: [REDACTED]

IGNMENT

assignment was received March 13, 1995 and the investigation commenced March 14. My instructions were to conduct an origin and cause examination.

CLOSURES

Vehicle fire examination report;
1 diagram;
12 photographs and all negatives.

VEHICLE EXAMINATION

I examined this vehicle at Little River Ford in Hopkinsville, Kentucky. Present during a portion of that examination were the Service Manager for Little River Ford, Mike [REDACTED], and their technician, Scott Plog. There were no adverse conditions affecting the examination and although the vehicle had been towed to Little River Ford from the location where the fire occurred, it did not appear to have been altered since the

The exterior of this vehicle displayed no evidence of this fire, with the exception of a light soot build up at the bottom of the interior of the windshield. There was no forced entry to the truck as your insured left it unlocked for fire department personnel. The windows were in the up position and both doors were closed during the course of the fire.

The fire was contained to a small portion beneath the dash in the passenger compartment and originated in the 14401 wiring harness beneath the dash at the far left of the cab. Some heated and molten plastic materials fell to the floorboard and caused some damage to the rubber floor matting in proximity to the fire wall on the driver's side of the cab.

An examination of the wiring harness beneath the dash caused extensive damage to the wiring, especially on the driver's side of the passenger compartment. The hood release appeared to have been fused to the wiring harness and when the technician attempted to use this release to examine the engine compartment, the hood release broke away from its mounting.

During my examination of the wiring in the engine compartment, I discovered no evidence of shorting or arcing. The fuse panel contained two blown fuses, both of which were to the instrumentation and lighting within the cab of the truck.

I examined the positive and negative wires your insured ran to the negative and positive posts of the battery and then through the fire wall to supply power to two radios. In examination of the wiring from the battery, as well as the external wiring to the radios, both of which were fused and the fuses intact, I found that none of this wiring suffered any damage.

No physical evidence was removed from this vehicle by me. The enclosed photographs remain as documentation of my findings.

NS

INS INVESTIGATIONS BUREAU, INC.

2345 South Lynhurst Drive, Suite 220
Indianapolis, Indiana 46241
800-328-8034
317-243-3257
FAX: 317-243-8639

PRIVILEGED AND CONFIDENTIAL

REPORT NUMBER ONE & FINAL

April 4, 1995

PREPARED FOR:

Allstate Insurance Company
715 Second Street
Henderson, Kentucky 42420

ATTENTION:

Ms. Sandy Hanes

INSURED:



DATE OF LOSS:

03/04/95

LOSS LOCATION:

Crofton, KY

POLICY NUMBER:

Not available

CLAIM NUMBER:

2201526940

INS FILE NUMBER:

94501-06463

THIS REPORT FURNISHED AS PRIVILEGED AND CONFIDENTIAL TO ADDRESSEE.
RELEASE TO ANY OTHER COMPANY, CONCERN OR INDIVIDUAL IS SOLELY
THE RESPONSIBILITY OF ADDRESSEE.

INS

EA05-005-LC-9116

Allstate

Field Claim Office
715 Second Street
Henderson, KY 42420
502-626-1994

4/7/95

Ford Motor Credit Corp.
618 N. Green St.
Henderson, Ky. 42420

Dear Chris,


Attached you will find the cause and origin report on
[REDACTED] 1995 Ford F150 XL pickup, per our discussion.
This report advises that the fire started as a result of a
manufacturing defect within the wiring harness.

Mr. Pyle has comprehensive coverage which will pay for the
fire damage, however we would then subrogate Ford Motor Co.


Please speak with your supervisor and consider handling this
loss directly with Little River Ford in Hopkinsville, to resolve
since the pickup has been repossessed.

Please contact me in my office at the above number.

Sincerely,


Sr. Staff Claim Rep.

EN85-225-LC-0117



GEICO

- Government Employees Insurance Company
- GEICO General Insurance Company
- GEICO Indemnity Company
- GEICO Casualty Company

One GEICO Blvd. ■ Fredericksburg, VA 22412-0001

July 9, 1996

FORD MOTOR COMPANY
OFFICE OF GENERAL COUNSEL
PARKLANE TOWERS WEST STE 300
300 PARKLANE BLVD
DEARBORN MI 48126

Claim Number [REDACTED]

Insured [REDACTED]

Date of Loss: 6-21-96

To Whom It May Concern:

Please be advised we are in the process of handling the above referenced fire loss of a 1997 Ford F150. Our intent is to file subrogation in this matter as our investigation indicates your company may be considered liable for this loss.

If you would like to inspect the damaged vehicle, please contact the below named adjuster for information regarding the location of the vehicle. The vehicle and all parts will be retained to provide you an opportunity to complete your investigation of this matter.

Please be advised our insured has incurred personal losses in this matter and may be contacting you regarding the separate handling of his claim.

If you have any questions or concerns, please call me at 1-800-841-1003 ext. 4638, Monday - Friday from 8:00 a.m. to 4:00 p.m. EST and I will be happy to discuss them.

Thank you for your time and attention in this matter.

Sincerely,

Jo G. Bayliss
Theft Examiner I

JGB/dp

cc: Culpeper Ford c/o Neil Merchant
PO Box 1836
Culpeper VA 22701

FA05-005-10-9118

GEICO

■ Government Employees Insurance Company
■ GEICO General Insurance Company
■ GEICO Indemnity Company
■ GEICO Casualty Company

One GEICO Blvd. ■ Fredericksburg, VA 22412-0001

August 21, 1996

FORD MOTOR COMPANY
PARKLANE TOWERS WEST SUITE 400
THREE PARKLANE BOULEVARD
DEARBORN, MI 48126-2568

Claim#:

Our Insured

Date of Loss: 06/21/96

Vehicle: 1997 Ford F150

To Whom It May Concern:

In response to your acknowledgment letter dated July 19, 1996, GEICO is able to provide the following information related to the mechanical fire:

1. On June 21, 1996, [REDACTED] was operatin his vehicle on Rt. 629 near Rt. 729 when he noticed smoke coming from the engine compartment of the vehicle. [REDACTED] proceeded to stop the vehicle, and call the fire department. By the time the authorities responded to the scene, the vehicle had been totally consumed by fire. No fire report was written.
2. The vehicle was a 1997 Ford F150 serial # 1FtdF172SV [REDACTED]
3. At the time of the loss, the vehicle had been driven approximately 3,768 miles.
4. William H. Seals investigated the loss and concluded that the fire was caused by a defective alternator.
5. The vehicle is located at Cosner Salvage located on Rt. 250 in Troy, VA. Their Phone number is (800) 248-6161 and is available for your inspection.

If you have any questions, feel free to contact any of the following:

Matt Wiseman:	Auto Damage Adjuster	(804) 981-0650
William H. Seals:	Certified Fire Inspector	(703) 754-4721
James Carey:	Payment Recovery Examiner	(800) 841-1003 extension 4378

Sincerely,



James Carey
Payment Recovery Examiner

JC/wdd

ER05-005-LC-0119





**WOLF
TECHNICAL
SERVICES, INC.**

Technical Investigations
Forensic Analysis
Engineering Consultants

6828 Hawthorn Park Drive • Indianapolis, IN 46220-3809 • (317) 842-6075 • FAX (317) 842-0874

IN. 5231251
10-7-10/11
ef

July 13, 1995

USAA Auto Insurance
P.O. Box 33490
San Antonio, TX 78265

Attn: Sue Guerriero

Re: Your file # 5231251
WTS Project #: 95-805-422



BACKGROUND OF THE INCIDENT

This investigation involved a fire in a 1995 Ford Club Van reported to have occurred on Friday, May 25, 1995 in Gosport, Indiana. The reported owner was Judith Purdie, of Ellettsville, Indiana. The vehicle was subsequently removed to the Indiana Auto Storage Pool in Indianapolis where this examination was performed.

Wolf Technical Services, Inc. (WTS) was contacted on Friday, June 9, 1995 with instructions to conduct an origin and cause investigation into the loss. This investigation was initiated by John Wood, Fire Investigation Specialist, with assistance from Ronald Taylor, Fire Investigation Specialist with Wolf Technical Services, Inc. (WTS)

CONCLUSION

It is our technical opinion based upon the examination of physical evidence combined with witness information that the fire originated in the engine compartment, at the left rear of the engine. The area was at or near the fuel regulator supplying fuel to the engine.

The exact cause of the fire could not be determined, however, a failure in one of the fuel lines to or from the fuel regulator cannot be eliminated as the cause.

DISCUSSION

The driver of the vehicle advised that he had been driving the vehicle and had stopped at a dump station. After parking the vehicle and walking away, he heard a noise from the van. Looking toward the van, he observed fire coming from the under side of the van. The nearest telephone was over a mile from the scene, and it was necessary to travel this distance by foot to report the incident to the fire department. The location was somewhat remote and additional time was involved before the fire department arrived to extinguish the fire.

The vehicle was a green 1995 Ford Club Van E-350 equipped with a 5.8 Liter engine. The vehicle was located at the Indiana Auto Storage Pool under hold # 78471. This vehicle was also found to have an auxiliary hydraulic wheel chair lift installed onto the frame. On viewing, the vehicle displayed effect of heat and flame impingement over the entire exterior body. This situation was also observed in the interior of the passenger compartment and the engine compartment.

No collision damage normally associated with a traffic accident was observed. The left front tire appeared to have been nearly destroyed by the fire, with the remaining tires found in place in a deflated condition. All wheels were found with the lug nuts in place and the wheel covers with exception of the left front in place.

The door to the fuel filler cap and tube was found in a closed position with the cap melted and the filler tube in a melted condition. The gasoline tank was found intact with no evidence of a leak from the tank.

The hood was found to have been constructed of a fiberglass material and was consumed during the fire. The front grille and other combustible material associated with that area had been destroyed. The radiator was melted from the top downward. The upper portion of the components within the engine compartment below the hood, displayed damage indicating the path of the fire to have been from the rear moving toward the front. The lower front areas of the engine compartment were found generally intact.

Inspection of the passenger compartment showed all combustible material have been consumed. The frame work of the seats in the vehicle were present. The passenger seat in the front appears to have been removed prior to the fire, to facilitate the use of a wheel chair. The heaviest amount of damage was found to be in the front of the compartment that was found to extend upward and outward from the engine shroud on the driver's side.

July 13, 1995

With the use of a mobile lift device, the vehicle was raised to allow inspection of the underside. Damage from heat and smoke impingement was observed the approximate "B" pillar toward the rear of the vehicle. From this location, toward the front, on the left side there was evidence of burning to the components. The fuel filter and fuel rail along the left inside of the frame was found to have had direct flame contact that has damaged the filter and housing. There was evidence of a fuel involved fire from this location that propagated upward and outward.

Examination of the line connected to the fuel filter indicated that the fuel line from the tank has separated and allowed fuel to flow. The return line was found to have sustained heat damage, however, it was connected. From the heat patterns found in this area it appears that the burning was caused by falldown material from the fire above.

In the area of the left front wheel well there was extensive burn damage noted. This damage was attributed to the fire traveling upward from the area of the fuel filter and the separation of the brake line that allowed the brake fluid to be introduced to the heat. The fire had also propagated into the rubber tire.

The origin of fire was found to be at the left rear of the engine. This part of the engine is below the shroud or cover that protrudes into the passenger compartment. In this area an inspection of the electrical conductors was conducted. There was no evidence of electrical faulting or arcing found, eliminating them from causal effect.

Further found in this area was the fuel regulator for the fuel injector system. The return line was found to be missing from the regulator, however, the inlet line was intact.

It had been reported by the owner that the vehicle has experienced a situation where gasoline fumes were noted in the interior. This situation was checked at the dealership on at least one occasion. It was further reported that this condition had re-appeared and the vehicle was scheduled to be returned to the dealer to correct the situation.

During the examination it was found that supply line to the left bank injector and the return line from the right bank were missing and believed destroyed by the fire. Also missing was the return line to the fuel storage tank from the regulator.

July 13, 1995

This fuel system on this engine as with most fuel injected systems is a closed pressurized system. The smell of gasoline is an indication of a leak of fuel. The pressure in the system is normally set at approximately 39 P.S.I. from the fuel pump. During the running of the engine this pressure is variable by manifold pressure. Normal pressure when the ignition in the off position is held at 40 P.S.I. A leak in the area of the regulator from a supply line could produce a situation of gasoline fumes conducive to ignition by the heat of the engine. The use of ethanol mixed fuel could, combined with a leak, create an explosive condition.

After completion of the examination and elimination of all other causes the scenario described above cannot be ruled out.

This file will be held in an open status awaiting further instructions. The samples of the engine oil and the transmission fluid will be retained for future examination. Should you have any questions, please feel free to contact us.

Respectfully submitted,



John R. Wood, CFI
Fire Investigation Specialist

For the Laboratory,



James Casassa, P.E.

JRW

STATE OF INDIANA)

COUNTY OF HAMILTON)


FILED

IN THE HAMILTON CIRCUIT COURT

) SS:

29C01-9610 CP 777

96 OCT 1 CAUSE NO. 417 9-54



Larry Roberts

PLAINTIFFS

Plaintiffs

vs.

FORD MOTOR COMPANY and
TOM WOOD FORD, INC.,

Defendants

COMPLAINT AND DEMAND FOR JURY TRIAL

Come now the Plaintiffs [REDACTED] individually and as husband and wife, and [REDACTED] as guardian of [REDACTED] by counsel, and for their causes of action against Ford Motor Company and Tom Wood Ford, Inc., allege:

1. The Plaintiffs [REDACTED] as individuals and [REDACTED]

[REDACTED] as guardian of [REDACTED] The Plaintiffs reside in Marion County, Indiana. At all times relevant hereto, the Plaintiffs are husband and wife.

2. The Defendant, Ford Motor Company, is a foreign corporation incorporated in the State of Delaware with its principal place of business in Dearborn, Michigan, with a registered agent, C T Corporation System, in Marion County, Indiana.

3. At all times herein relevant, Tom Wood Ford, Inc., was an Indiana corporation.

4. The 1991 Ford Aerostar van in which [REDACTED] was injured, was manufactured by the Ford Motor Company.

5. The 1991 Ford Aerostar van in which [REDACTED] was injured, was sold by Tom Wood Ford, Inc., to [REDACTED] on or about the 14th day of September, 1993.

6. On or about December 10, 1994 the Plaintiff, [REDACTED] was operating the 1991 Ford Aerostar van in Putnam County, Indiana, with his wife, [REDACTED] as a passenger when the Plaintiffs thereafter had a motor vehicle collision.

7. In the collision the Plaintiff, [REDACTED] suffered serious and permanent bodily injuries.

8. Plaintiff [REDACTED] medical expenses are continuing in nature and at this time are unknown in total amount. In addition, the Plaintiff [REDACTED] has lost income and the opportunity to earn income in the future in an unknown amount. The [REDACTED] has suffered damages in loss of services and consortium.

9. The Defendants, Ford Motor Company and Tom Wood Ford, Inc., breached their duty to exercise reasonable care and the breach of this duty was a proximate cause of the Plaintiffs' injuries and damages.


10. The Ford motor vehicle owned by the Plaintiffs was in a defective condition unreasonably dangerous and said condition was a proximate cause of the damages to Plaintiffs.

11. The Defendant, Tom Wood Ford, Inc., breached its warranties to the Plaintiffs causing Plaintiffs' damages.

WHEREFORE, the Plaintiffs pray for a judgment which is just under the evidence, prejudgment interest, and all other proper relief.

Respectfully submitted,


PARDIECK, GILL & VARGO
A Professional Corporation

By: 
Roger L. Pardieck, #5859-36
100 North Chestnut Street
P.O. Box 608
Seymour, IN 47274
(812) 523-8686

DEMAND FOR JURY TRIAL

The Plaintiffs demand trial by jury.


PARDIECK, GILL & VARGO
A Professional Corporation

By: 
Roger L. Pardieck, #5859-36
100 North Chestnut Street
P.O. Box 608
Seymour, IN 47274
(812) 523-8686

STATE OF INDIANA,)
) SS:
COUNTY OF HAMILTON,)

IN THE HAMILTON CIRCUIT COURT

CAUSE NO. 29C01-9610 CP.777



Plaintiffs

v.

FORD MOTOR COMPANY and
TOM WOOD FORD, INC.

Defendants

FILED
CLERK, HAMILTON COUNTY COURTS
October 11, 1996


96 OCT 11 AM 9:53

FILED

APPEARANCE BY ATTORNEY IN CIVIL CASE

Party Classification: Initiating X Responding Intervening

1. The undersigned attorney and all attorneys listed on this form now appear in this case for the following party member(s):



2. Applicable attorney information for service as required by Trial Rule 5(B)(2) and for case information as required by Trial Rules 3.1 and 77(B) is as follows:

Name: Roger L. Pardieck
Address: 100 N. Chestnut Street
P.O. Box 608
Seymour, IN 47274

Atty Number: #5859-36
Phone: (812) 523-8686
FAX: (812) 522-4199
Computer Address: pgv@pgvlaw.com

[List on continuation page the additional attorneys appearing for above party member(s).]

3. There are other party members: Yes No X (If yes, list on continuation page.)

4. If first initiating party filing this case, the Clerk is required to assign this case the following Case Type under Administrative Rule 8(b)(3): _____

5. I will accept service by FAX at the above noted number: No

6. This case involves support issues: No.

7. There are related cases: Yes ____ No X (If yes, list on continuation page.)

8. This form has been served on all other parties. Certificate of service is attached: Yes.

9. Additional information required by local rule:


Roger L. Pardieck, Attorney-at-Law
Attorney Information Shown Above

CERTIFICATE OF SERVICE

I certify that a copy of the above and foregoing pleading was deposited in the United States mail, with postage prepaid, addressed to Ford Motor Company and Tom Wood Ford, Inc. at the addresses listed on the Summons, this 11 day of October, 1996.


Roger L. Pardieck

C.R.

STATE OF INDIANA) IN THE HAMILTON CIRCUIT COURT
COUNTY OF HAMILTON) SS:
CAUSE NO. 29C01-9610-CP-777

[REDACTED]

Plaintiffs

v.

FORD MOTOR COMPANY,
TOM WOOD FORD, INC.,
GARY AUTREY,
PALMENTERE BROS. CARTAGE
SERVICES, INC.,

Defendants

95 DEC -6 PM 3:10
FILED IN HAMILTON CIRCUIT COURT
JANUARY 1996

AMENDED COMPLAINT AND DEMAND FOR JURY TRIAL

Come now the Plaintiffs, [REDACTED]

individually and as husband and wife, as [REDACTED] as guardian of [REDACTED], by counsel, and for their causes of action against Ford Motor Company, Tom Wood Ford, Inc., Gary Autrey and Palmentere Bros. Cartage Service, Inc., alleges:

1. The Plaintiffs are [REDACTED] as individuals and [REDACTED] as guardian of [REDACTED]. The Plaintiffs reside in Marion County, Indiana. At all times relevant hereto, the Plaintiffs have been husband and wife.

2. At all times relevant, the Defendant, Ford Motor Company, was a foreign corporation incorporated in the State of Delaware with its principal place of business in Dearborn, Michigan, with a registered agent, C T Corporation System, in Marion County, Indiana.

3. At all times herein relevant, Tom Wood Ford, Inc., was an Indiana corporation.

4. At all times relevant, Defendant, Gary Autrey was a resident of Florida and was an employee of Palmentere Bros. Cartage Service, Inc. acting in the scope and furtherance of his employment.

5. At all times relevant, Defendant, Palmentere Bros. Cartage Service, Inc. was a foreign corporation with its principal place of business in Missouri.

6. The 1991 Ford Aerostar van in which T [REDACTED] was injured, was manufactured or otherwise introduced into the stream of commerce by the Ford Motor Company.

7. The 1991 Ford Aerostar van in which [REDACTED] was injured, was sold by Tom Wood Ford, Inc., to Barbara Purvis on or about the 14th day of September, 1993.

8. On or about December 10, 1994 the Plaintiff, [REDACTED], was operating the 1991 Ford Aerostar van in Putnam County, Indiana, with his wife, [REDACTED] as a passenger. The Plaintiffs thereafter had a motor vehicle collision in which their vehicle was struck by a semi operated by Gary Autrey. At the time of the collision, Gary Autrey was acting in the scope and furtherance of his employment with Palmentere Bros. Cartage Service, Inc.

9. In the collision the Plaintiff, [REDACTED] suffered serious and permanent bodily injuries.

10. Plaintiff [REDACTED] medical expenses are continuing in nature and at this time are unknown in total amount. In addition, the Plaintiff, [REDACTED] has lost income and the opportunity to earn income in the future in an unknown amount.

The Plaintiff, [REDACTED] has suffered damages in loss of services and consortium.

11. The Defendants, Ford Motor Company, Tom Wood Ford, Inc., and X-Corporation breached their duty to exercise reasonable care and the breach of this duty was a proximate cause of the Plaintiffs' injuries and damages.

12. The Ford Aerostar van operated by Plaintiff, Thomas Purvis, was in a defective condition unreasonably dangerous and said condition was a proximate cause of the damages to Plaintiffs.

13. The Defendant, Tom Wood Ford, Inc., breached its warranties to the Plaintiffs causing Plaintiffs' damages.

14. Defendant Gary Autrey was negligent in the operation of the semi tractor trailer while acting in the scope and furtherance of his employment with Palmentere Bros. Cartage Service, Inc. The negligence of Gary Autrey acting in the scope and furtherance of his employment with Palmentere Bros. Cartage Service, Inc. was a proximate cause of the damages suffered by Plaintiffs.

15. That Palmentere Bros. Cartage Service, Inc. is responsible for the negligence of Gary Autrey in the scope and furtherance of his employment under the doctrine of respondeat superior.

WHEREFORE, the Plaintiffs pray for a judgment which is just under the evidence, prejudgment interest, and all other proper relief.

Respectfully submitted,


DIECK, GILL & VARGO
A Professional Corporation

By: *Roger L. Pardieck*

Roger L. Pardieck, #5859-36
Bruce A. MacTavish, #11251-27
100 North Chestnut Street
P.O. Box 608
Seymour, IN 47274
(812) 523-8686

DEMAND FOR JURY TRIAL

The Plaintiffs demand trial by jury.

Respectfully submitted,

PARDIECK, GILL & VARGO
A Professional Corporation

By: *Roger L. Pardieck*

Roger L. Pardieck, #5859-36
Bruce A. MacTavish, #11251-27
100 North Chestnut Street
P.O. Box 608
Seymour, IN 47274
(812) 523-8686

CERTIFICATE OF SERVICE

I certify that a copy of the above and foregoing pleading was deposited in the United States mail, with postage prepaid, addressed to Joan Fullam Irick, Esq., KIGHTLINGER & GRAY, 660 Market Square Center, 151 North Delaware Street, Indianapolis, IN 46204; Charles R. Sheeks, Esq., SHEEKS ITTENBACH & JOHNSON, 6350 N. Shadeland Avenue, Suite 4, Indianapolis, IN 46220; and Ellen Boashkoff, Esq. and Albert J. Dahm, Esq., BAKER & DANIELS, 300 North Meridian, Suite 2700, Indianapolis, IN 46204, on this *6th* day of December, 1996.

Roger L. Pardieck

Roger L. Pardieck

IN THE CIRCUIT COURT OF HAMILTON COUNTY

STATE OF INDIANA

[REDACTED]
Individually and as Husband and Wife,
and
[REDACTED]

Plaintiffs,

v.

CAUSE NO. 29C01-9610-CP-777

FORD MOTOR COMPANY, TOM WOOD FORD,
INC., GARY AUTRY, PALMENTERE BROS.
CARTAGE SERVICE, INC.,
Defendants

ORDER

Come now the Plaintiffs, by counsel, and file their Motion for Leave to Amend
Complaint and Demand for Jury Trial, which is in the following words and figures, to-
wit:

(H.L.)

And the Court being duly advised in the premises now finds that Plaintiffs'
Motion should be granted.

IT IS THEREFORE, ORDERED, ADJUDGED AND DECREED that
Plaintiffs are hereby granted Leave to File their Amended Complaint and Demand for
Jury Trial.

ALL OF WHICH IS SO ORDERED THIS 6 **DAY OF DECEMBER,**
1996.

Quaden L. Roffitt
JUDGE, HAMILTON CIRCUIT COURT

Distribution:

**Joan Irick
660 Market Square Center
151 North Delaware Street
Indianapolis, IN 46204**

**Charles Sheeks
6350 North Shadeland Avenue
Suite 4
Indianapolis, IN 46220**

**Ellen Boshkoff
Albert Dahm
BAKER & DANIELS
300 North Meridian
Suite 2700
Indianapolis, IN 46204**

**Roger Pardieck
Bruce Mac Tavish
100 North Chestnut Street
P.O. Box 608
Seymore, IN 46274**

FILED
LORAIN CO. OHIN THE COURT OF COMMON PLEAS OF LORAIN COUNTY
LORAIN COUNTY, OHIO

JAN 24 2 29 PM '96

CASE NO.:

CLERK OF COURT
DONALD J. ROTHGERY

JUDGE:

96CV115670

COMPLAINT

JUDGE LYNETT M. McGOUGH

-VS-

FORD MOTOR COMPANY,
% Statutory Agent
C.T. Corporation System
815 Superior Avenue N.E.
Cleveland, Ohio 44114

Defendants.

1. Plaintiff insurance company was at all times material herein, the insurer, assignee and subrogee of Judy and Alfred Purdie.

2. Defendant Ford Motor Company is a corporation licensed to do business in the State of Ohio, and is a manufacturer as defined by Ohio Revised Code §2307.71(I), engaged in the design, construction, assemblage, formulation and/or creation of motor vehicles for sale to consumers.

3. On or about December 12, 1994, Plaintiff's insureds purchased a motor vehicle, a 1995 Ford van, VIN Number 1FMHE31B6SH, said motor vehicle being the subject of this cause of action.

4. The above referenced motor vehicle was formulated, designed, constructed and/or assembled by Defendant Ford Motor Company, with a final assembly point of said motor vehicle being at the Lorain Ford Plant, Lorain County, Ohio.

5. On or about May 25, 1995, in the City of Ellettsville, State of Indiana, Plaintiff's insureds motor vehicle was damaged and caused to depreciate in value when it caught fire and burned, destroying the motor vehicle and the contents therein.

6. Plaintiff's insured's motor vehicle, as produced by Defendant Ford Motor Company, was defective in design, manufacture, formulation, construction and/or assemblage, and was defective when it left the control of Defendant Ford Motor Company.

7. Defendant Ford Motor Company was negligent in the design, formulation, construction, manufacturing and/or assemblage of Plaintiff's insured's motor vehicle.

8. Defendant Ford Motor Company breached implied and expressed warranties of merchantability in that the motor vehicle manufactured and sold by Defendant was unsafe and unfit for the purposes for which such motor vehicles used.

9. Defendant Ford Motor Company breached implied and expressed warranties of fitness for a particular purpose in that the motor vehicle sold by Defendant was unsafe and unfit for the purposes for which the vehicle was intended to be used by Plaintiffs insureds.

10. As a direct and proximate result of Defendant Ford Motor Company's negligence and as a result of Defendant's breach of warranties as more fully set forth above, Plaintiff's insured's motor vehicle and personal property were damaged and destroyed, and Plaintiff's insured's suffered loss in the amount of \$37,390.05.

11. Plaintiff insurance company was required to pay to or on behalf of its insureds the sum of \$37,340.05 and thereby became subrogated to that amount.

WHEREFORE, Plaintiff demands judgment against the Defendant in the amount of \$37,340.05; and for the costs incurred in bringing this action.


KREINER & PETERS CO., LPA

KEITH R. MCMURDY
Attorney for Plaintiffs
6047 Frantz Road #203
Dublin, Ohio 43017
(614) 793-1770
Registration No. 0062108



USAA CASUALTY INSURANCE COMPANY
9800 Frederickaburg Road, San Antonio, TX 78208

FORD MOTOR COMPANY
OFFICE OF THE GENERAL COUNSEL
PARKLANE TOWERS WEST
STE 300
3 PARKLANE BLVD
DEARBORN MI 48126



June 9, 1995

Policyholder: [REDACTED]
Reference Number: [REDACTED]
Date Of Loss: May 25, 1995
Loss Location: Gosport, Indiana
REFERENCE: TOTAL FIRE CLAIM - 95 FORD CLUB WAGON
INVESTIGATING: FUEL LEAK
OWNER: [REDACTED] ✓

DEAR SIR:

This is to advise Ford Motor Company that I am handling a claim for our insured Judy Pardie. [REDACTED] owns a 1995 Ford Club Wagon that caught on fire and was deemed to be a total loss. We are investigating this claim to determine whether we will have a claim against your company. Our insured has documentation of the problems she has reported to Bloomington Ford in Bloomington, Indiana. One of the problems was the smell of gas.

If you would like to have your own representative inspect this vehicle call [REDACTED] for location.

Sincerely,

Sue Guerrero

Sue M. Guerrero
Senior Auto Claims Representative
Great Lakes Region
Phone: 1-800-531-8222 Ext. 79329

5231251-- 10 - IN - 05/25/95 - 1010 - 37 - C200

EA05-005-LC-8137

523 13 51

1015-11





JUN 07 2005

SPARTAN ADJUSTING COMPANY, L.L.C.


CUSTOMER
RELATIONSHIP
CENTER

P.O. Box 1608
Friendswood, Tx. 77549-1608

Telephone (281) 652-3698
Fax (281) 652-3663

June 1, 2005

Ford Motor Company
Consumer Affairs
PO Box 6248 MD-3NE-B
Dearborn, Michigan 48126



RE: Our Insured [REDACTED]
Our Claim Number [REDACTED]
Date of Loss :10-29-04
Total Amount Due :\$17129.18
Company Portion :\$16612.18
Insured's Portion :\$517.00

To Whom It May Concern:

I am submitting a subrogation demand for the above amounts in reference to a loss associated with recall number 05S28 Cruise Control. On 10-29-04 [REDACTED] 2001 Ford F-150 Lariat caught on fire, all indications point to the cruise control as the ignition point of fire.

Please accept this letter as notice of our subrogation rights under vehicle damage. We have made payment to our insured regarding this loss and request reimbursement.

If you have any questions, please contact me at the above number at extension 3532.

Sincerely,

A handwritten signature in cursive script, appearing to read "Vanessa Filla".

Vanessa Filla
Claims Adjuster

11/03/2004 at 12:35 PM File# 74599-00008937

File ID 004-110408

Owner: [REDACTED]

Appraiser: David Betcher

2001 FORD F150 4X2 SUPERCAB 6-4.2L-FI 4D SHORT GOLD Int:TAN


DCA ENTERPRISES

P.O.Box1619


New Caney, TX 77357

Business: (281)399-0900

IMAGE REPORT



11/02/2004: EST01:



11/02/2004: EST01:

11/03/2004 at 12:35 PM File# 74599-00008937


File ID 004-1104DB

Owner: [REDACTED]


Appraiser: David Betcher

2001 FORD F150 4X2 SUPERCAB 6-4.2L-FI 4D SHORT GOLD Int:TAN

IMAGE REPORT



11/02/2004: EST01:



11/02/2004: EST01:

11/03/2004 at 12:35 PM File# 74599-00008937


File ID 004-110408

Owner:


Appraiser: David Betcher

2001 FORD F150 4X2 SUPERCAB 6-4.2L-FI 4D SHORT GOLD Int:TAN

IMAGE REPORT



11/02/2004: EST01:




Accelerated Recovery Services, Inc.

P.O. Box 2368 Redwood City, California 94064 Tel: 850.299.0183 Toll Free: 800.335.9474 Fax: 850.299.9191

February 12, 2004

CORNING FORD
ATTN: STEVE LOWERY
2280 SHORT DRIVE
CORNING, CA 98021



Re: Account [REDACTED]
Current Balance: \$26,539.86
Re: California State Automobile Association

Dear CORNING FORD:

This firm represents California State Automobile Association ("CSAA") regarding the auto fire that happened on October 21, 2002. I have a subrogation demand in the amount of \$26,539.86, that represents payments made by CSAA to their insured and the loan company for the loss, as well as rental costs for their insured. Attached, please find the fire investigation report, drafts, estimates and photographs to substantiate the payments made by CSAA on behalf of their insured.

Upon acceptance of liability please forward your draft made payable to CSAA to:
Post Office Box 2368, Redwood City, CA 94064 to my attention.

Should you have any questions regarding this subrogation demand please do not hesitate to contact me at 800.335.9474 X 202. Your professional attention to this matter is appreciated.

Sincerely,

Accelerated Recovery Services, Inc.


Julie Bridges, Subrogation Legal Specialist

Handwritten notes:
\$26,539.86
10/21/02
- 100 Excl
26,539.86 (20) ??
+ Rental included.

This is an attempt to collect a debt. Any information obtained will be used for that purpose.

Fire Investigation Report

Opinions rendered in this report are based upon available information at the time the report was drafted and draw upon the training, education, and experience of the personnel involved in the investigation.

REPORT DATE: 11/4/02	INSURED: [REDACTED]
REQUEST BY: A. MORGAN	CLAIM #: [REDACTED]
INSPECTION DATE: 10/31/02	DATE OF LOSS: 10/21/02
ODOMETER: DESTROYED	UNIT: 2000 FORD EXPLORER
VIN: 1FMZU74E3YZA48383	LICENSE: 4JFY271
LOCATION OF UNIT:	COPART 1705 MARIETTA WAY SPARKS, NV. 89431
INSPECTION PURPOSE:	DETERMINE ORIGIN AND CAUSE OF A FIRE LOSS.

Background

I received a request from Amy Morgan, CSAA Salvage Department, to inspect the insured's vehicle to determine the origin and cause of a fire loss. The insured reported the vehicle caught fire in the engine compartment while being operated when entering a parking lot. The insured also reported that recent repairs were performed under warranty to repair a leak from the rear differential assembly 9/17/02 at odometer reading 52,727.

Inspection

The vehicle was inspected at the Copart Salvage Facility in Sparks, NV. I identified the vehicle using the VIN plate and Federal Safety Label. Examination found evidence of a relatively localized fire having occurred at the forward portion of the vehicle. The left front fender and hood panel were scorched. The left side of the front grille and left lamp assembly were melted and sagging. The left front tire was burned and deflated. Black soot was visible at the lower left portion of the front windshield.

Interior examination found fire damage limited to the left side of the instrument panel and firewall area due to flame penetration through firewall openings from the engine compartment. Inspection of interior electrical wiring found no evidence of electrical short circuit to ground or electrical overload. Inspection of the vehicle odometer found that it was physically damaged from some type of object or tool not related to the actual fire itself. It was not determined during the course of this investigation who intentionally damaged the odometer.

Undercarriage examination found no evidence of oil or hydraulic fluid leaks prior to this fire. No evidence of leakage was found at any portion of the recently serviced rear differential assembly. Examination of exhaust system components found no soot or char that would indicate the ignition of a combustible substance in contact with exhaust system components.

INSURED: [REDACTED]	CLAIM OR POLICY NUMBER: [REDACTED]	DATE OF LOSS: 10/21/02
------------------------	---------------------------------------	---------------------------

Engine compartment examination found heavy damage from fire. Plastic and rubber materials were either burned or melted with the least amount of damage at the right side of the compartment. The heaviest burn damage was at the left side of the engine compartment between the engine assembly itself and the left front fender. The engine oil was found at a safe operating level. The automatic transmission fluid registered about one inch above the "Full" mark which would be considered normal with out the engine running. The plastic power steering reservoir at the left front of the engine compartment was burned and melted allowing the escape of power steering fluid. The brake master cylinder and brake fluid reservoir were missing and presumed to have been consumed by fire. The plastic left inner fender well was also missing and presumed to have been consumed by fire.

Examination at the area of greatest fire damage found the flexible portion of the fuel supply line disconnected from the rigid portion of fuel supply line at the left front frame rail area. Examination of the braided steel flexible portion of line found it heavily kinked adjacent to where it would normally connect to the rigid line. This flexible portion of line is intended to be permanently attached to the rigid line with a machine crimped retaining clamp. This clamp was found to be still in place at the end of the flexible line. No tool marks that would indicate the crimped connection had be serviced or modified since it was originally manufactured were found. Inspection of disconnected flexible fuel line routing revealed it was improperly positioned when clamped in the retaining bracket at the left side of the engine assembly. This left an excessive amount of flexible fuel line between the engine bracket and fuel injector rail and an insufficient amount of flexible line between the engine bracket and the rigid line at the frame rail.

Summary

- A. Insured's vehicle catches fire in engine compartment while being operated. Insured reported recent repairs for a rear differential leak condition.
- B. Examination found evidence of a relatively localized fire having occurred in the engine compartment.
- C. Area of greatest fire damage at left side of engine compartment between engine assembly and left front fender. No evidence of oil or hydraulic fluid leaks prior to this fire was found. No evidence of electrical short circuit to ground or electrical overload found.
- D. Flexible fuel supply line disconnected from rigid fuel line at left front frame rail area at area of greatest fire damage.
- E. Flexible fuel line kinked near disconnected end. Flexible fuel line mispositioned at engine bracket. Insufficient slack in flexible portion of fuel line between engine bracket and rigid line at frame rail due to improper installation at engine bracket.
- F. Engine replaced under warranty 1/11/01 at odometer reading 031,081. ✓

INSURED: [REDACTED]	CLAIM OR POLICY NUMBER: [REDACTED]	DATE OF LOSS: 10/21/02
------------------------	---------------------------------------	---------------------------

Conclusion and Opinion

Following examination of the insured's vehicle, it is my opinion that this fire originated at the left side of the engine compartment. The cause should be considered the ignition of fuel vapors due to a disconnected fuel supply line. Ignition of the fuel vapors was likely from charging system or ignition sparks normally present in the engine compartment while the vehicle is being operated.

The fuel supply line was obviously pulled off due to insufficient slack between the engine and the frame rail. The engine itself is isolated from the frame of the vehicle allowing the engine to move somewhat in relation to the frame. This continued movement of the engine would have continuously pulled on the flexible portion of fuel line resulting in the noted kink in the line and eventually pulling the line off near the frame rail.

The bracket that secures the flexible line to the engine block actually clamps the line to the bracket eliminating any sliding type movement of the fuel line. There was no provision for the fuel line to be secured in a particular position in the bracket leaving it up to the installer to visually position the fuel line correctly to prevent the line from being kinked or pulled off during normal vehicle operation. Since this flexible portion of fuel line had to be removed when the engine was replaced, this should not be considered a manufacturing defect. The only repair to the vehicle that was found in the invoices supplied by the insured that would require removal of the fuel line is the engine replacement on 1/11/01 at Future Ford under warranty claim #396027. It is my opinion that subrogation be pursued.

Douglas E. Bailey

Douglas E. Bailey,
Mechanical Evaluator/Fire Investigator

INSURED:


CLAIM OR POLICY NUMBER:

DATE OF LOSS:

10/21/02




LEFT FRONT VIEW




RIGHT REAR VIEW

DATE OF LOSS:	CLAIM OR POLICY NUMBER:
10/21/02	



LICENSE



FEDERAL SAFETY LABEL

INSURED:


CLAIM OR POLICY NUMBER:

DATE OF LOSS:

10/21/02



ODOMETER




INTERIOR VIEW

INSURED:	GLADSON POLICY NUMBER:	DATE OF LOSS:
		10/21/02



INTERIOR VIEW FROM REAR



RIGHT FRONT VIEW

INSURED:


CLAIM OR POLICY NUMBER:

DATE OF LOSS:

10/21/02



LEFT FRONT VIEW




FRONT VIEW

INSURED:

CLAIM OR POLICY NUMBER:

DATE OF LOSS:

10/21/02



HOOD PANEL



UNDERSIDE OF HOOD PANEL

INSURED:	CLAIM OR POLICY NUMBER:	DATE OF LOSS:
		10/21/02



INSURED:

CLAIM OR POLICY NUMBER:

DATE OF LOSS:

10/21/02



ENGINE COMPARTMENT VIEW FROM RIGHT SIDE



ENGINE COMPARTMENT VIEW FROM LEFT SIDE

INSURED:	CLAIM OR POLICY NUMBER:	DATE OF LOSS:
		10/21/02



INSURED:


CLAIM OR POLICY NUMBER:

DATE OF LOSS:

10/21/02



DISCONNECTED FUEL LINE AT LEFT SIDE OF ENGINE COMPARTMENT



VIEW OF KINK AT BRAIDED PORTION OF FUEL LINE

INSURED:

CLAIM OR POLICY NUMBER:

DATE OF LOSS:

10/21/02



AREA WHERE FUEL LINE IS CLAMPED TO SIDE OF ENGINE BLOCK



CLOSE UP OF CLAMP USED TO SECURE BRAIDED FUEL LINE TO ENGINE BLOCK

INSURED:

CLAIM OR POLICY NUMBER:

DATE OF LOSS:

10/21/02



INSURED:


CLAIM OR POLICY NUMBER:

DATE OF LOSS:

10/21/02



VIEW OF FUEL LINE AT LEFT FRONT FRAME RAIL AREA OF EXEMPLAR VEHICLE
WITH NO KINK PRESENT.



FRONT UNDERCARRIAGE VIEW OF INSURED'S VEHICLE

INSURED: [REDACTED]	CLAIM OR POLICY NUMBER: [REDACTED]	DATE OF LOSS: 10/21/02
------------------------	---------------------------------------	---------------------------