



2005-175 10-

NO. _____

IN THE DISTRICT COURT

Plaintiffs,

V.

OF HARRIS COUNTY TEXAS

FORD MOTOR COMPANY AND
TEXAS INSTRUMENTS, INC.
Defendants.

§
§
§
§
§
§
§
§

55 JUDICIAL DISTRICT

PLAINTIFFS' ORIGINAL PETITION

TO THE HONORABLE JUDGE OF SAID COURT:

NOW COME [REDACTED] hereinafter called
Plaintiffs, complaining of and about FORD MOTOR COMPANY and TEXAS INSTRUMENTS,
hereinafter called Defendants, and for cause of action show unto the Court the following:

DISCOVERY CONTROL PLAN LEVEL

1. Plaintiffs intend that discovery be conducted under Discovery Level 2.

PARTIES AND SERVICE

2. Plaintiff, [REDACTED] is an individual whose address is [REDACTED]
Road, Houston, Texas [REDACTED]

Plaintiff, [REDACTED], is an individual whose address is [REDACTED]
Houston, Texas [REDACTED]

3. Defendant FORD MOTOR COMPANY, a Nonresident Corporation, may be served pursuant to article 2.09 of the Business Corporation Act by serving the registered agent of the corporation, CT CORPORATION SYSTEMS, at 350 North St. Paul, Dallas, Texas 75201, its registered office. Service of said Defendant as described above can be effected by personal delivery.

4. Defendant TEXAS INSTRUMENTS, INCORPORATED, a Nonresident Corporation, may be served pursuant to article 2.09 of the Business Corporation Act by serving the registered agent of the corporation, JOSEPH F. HUBACH, at 7839 Churchill Way, Dallas, Texas 75251, its registered office. Service of said Defendant as described above can be effected by personal delivery.

JURISDICTION AND VENUE

5. The subject matter in controversy is within the jurisdictional limits of this court.

6. This court has jurisdiction over Defendant FORD MOTOR COMPANY, because said Defendant purposefully availed itself of the privilege of conducting activities in the state of Texas and established minimum contacts sufficient to confer jurisdiction over said Defendant, and the assumption of jurisdiction over Ford Motor Company will not offend traditional notions of fair play and substantial justice and is consistent with the constitutional requirements of due process.

7. Furthermore, Plaintiff would show that Defendant FORD MOTOR COMPANY engaged in activities constituting business in the state of Texas as provided by Section 17.042 of the Texas Civil Practice and Remedies Code, in that said Defendant committed a tort in whole or in part in Texas.

8. The acts complained of occurred in this county.

9. This court has jurisdiction over Defendant TEXAS INSTRUMENTS, INCORPORATED, because said Defendant purposefully availed itself of the privilege of conducting activities in the state of Texas and established minimum contacts sufficient to confer jurisdiction over said Defendant, and the assumption of jurisdiction over TEXAS INSTRUMENTS, INCORPORATED will not offend traditional notions of fair play and substantial justice and is consistent with the constitutional requirements of due process.

10. Furthermore, Plaintiff would show that Defendant TEXAS INSTRUMENTS, INCORPORATED engaged in activities constituting business in the state of Texas as provided by Section 17.042 of the Texas Civil Practice and Remedies Code, in that said Defendant committed a tort in whole or in part in Texas.

11. The court has jurisdiction over the lawsuit because the cause of action arises in Harris County.

12. Venue in HARRIS County is proper in this cause.

FACTS

13. On or about July 16, 2004 [REDACTED] was the owner of, and while using the 2000 FORD EXPLORER for the purpose and in the manner in which it was intended to be used, suddenly and without warning the vehicle's cruise control ignition switch caused the vehicle to erupt in flames and caused plaintiff's home to suffer fire damage, injuring [REDACTED] as hereinafter described.

14. On or about July 16, 2004 [REDACTED] was the owner of, and while using the 2000 FORD EXPLORER for the purpose and in the manner in which it was intended to be used, after being parked at 5023 Kilkenney Drive in Houston, Texas, suddenly and without warning the vehicle's cruise control ignition switch caused the vehicle to erupt in flames and caused plaintiff's home to suffer fire damage, injuring [REDACTED] as hereinafter described.

LIABILITY OF FORD MOTOR COMPANY

15. While engaged in the manufacture and sale of the 2000 FORD EXPLORER, Defendant, FORD MOTOR COMPANY manufactured and sold a certain 2000 FORD EXPLORER and other like products, to consumers within the stream of commerce. Defendant, FORD MOTOR

COMPANY intended and expected that the 2000 FORD EXPLORER, so introduced and passed on in the course of trade would ultimately reach a consumer or user in the condition in which it was originally sold.

16. Plaintiffs, [REDACTED] and [REDACTED] also allege that the product in question, namely the 2000 FORD EXPLORER, was defective and unsafe for its intended purposes at the time it left the control of FORD MOTOR COMPANY and at the time it was sold in that it failed in its design to prevent the ignition from withstanding the constant source of heat which caused the vehicle to ignite while it was not running. Due to the unsafe operation of, but not limited to, the cruise control switch, the product was defectively designed and unreasonably dangerous in that the vehicle was ignited while inoperable.

17. Plaintiffs therefore invoke the doctrine of strict liability in Section 402A, Restatement of the Law of Torts, 2d, and as adopted by the Supreme Court of Texas. Further, in this connection, Plaintiffs would show the court that the defect in design was a producing cause of the injuries and damages set forth below.

18. In addition, Plaintiffs would show the court that the occurrence made the basis of this suit and the resulting injuries and damages set out below were a direct and proximate result of the negligence of FORD MOTOR COMPANY in one or more of the following respects, or by combination thereof:

- A. Failure of the cruise control switch or other systems of said 2000 FORD EXPLORER and its attendant equipment
- B. Failing to inspect said 2000 FORD EXPLORER and its attendant equipment
- C. Failing to properly warn Plaintiff about the condition of said 2000 FORD EXPLORER and its attendant equipment

19. Pleading further, Plaintiffs would show the court that the occurrence made the basis

of this suit and the resulting injuries and damages set out below were a direct and proximate result of negligence attributable to FORD MOTOR COMPANY in one or more of the following respects, or by a combination thereof:

- A. Failing to use due care in the manufacture of the 2000 FORD EXPLORER
- B. Failing to use due care in the design of the 2000 FORD EXPLORER
- C. Failing to use proper materials reasonably suited to the manufacture or design of the 2000 FORD EXPLORER or the component parts thereof
- D. Failing to use due care to test and/or inspect the 2000 FORD EXPLORER or the component parts thereof to determine its durability and function ability for the purpose for which it was intended

20. Pleading further, Plaintiffs would show the court that the occurrence made the basis of this suit and the resulting injuries and damages set out below were a direct and proximate result of the negligence of FORD MOTOR COMPANY in one or more of the following respects, or by a combination thereof:

- A. Failing to design the 2000 FORD EXPLORER to prevent the ignition from withstanding the constant source of heat which caused the vehicle to ignite while it was not running due to a malfunction
- B. Failing to design the 2000 FORD EXPLORER without a guard or shield on it as would have been done by a reasonable and prudent manufacturer under the same or similar circumstances
- C. Failing to place the 2000 FORD EXPLORER on the market with a warning to the users of the device that the 2000 FORD EXPLORER might ignite due to a malfunction

All of which Defendant, FORD MOTOR COMPANY knew, or in the exercise of ordinary care, should have known.

21. In addition, Defendant FORD MOTOR COMPANY expressly and impliedly warranted to the public generally, that the 2000 FORD EXPLORER was of merchantable quality and

was safe and fit for the purpose intended when used under ordinary conditions and in an ordinary manner. Plaintiffs relied upon these express and implied warranties and suffered the injuries and damages set forth below as a proximate result of the breach of these warranties.

22. Plaintiffs cannot more specifically allege the act of negligent design on the part of Defendant, FORD MOTOR COMPANY, aside from FORD MOTOR COMPANY's failure to design the 2000 FORD EXPLORER in question in a manner which would have prevented the ignition from withstanding the constant source of heat which caused the vehicle to ignite while it was not running, for the reason that facts in that regard are peculiarly within the knowledge of the Defendant, FORD MOTOR COMPANY, and, in the alternative, in the event Plaintiffs are unable to prove specific acts of negligent design, Plaintiffs rely on the doctrine of Res Ipsa Loquitur.

23. In this connection, Plaintiffs will show the court that the design of the 2000 FORD EXPLORER was within the exclusive control of Defendant, FORD MOTOR COMPANY, Plaintiffs had no means of ascertaining the method or manner in which the product was designed, and it was used by Plaintiffs in the same condition it was in when it left control of Defendant, FORD MOTOR COMPANY.

24. The occurrence causing harm to Plaintiffs, as described above, was one which, in the ordinary course of events, would not have occurred without negligence on the part of Defendant, FORD MOTOR COMPANY. Thus, FORD MOTOR COMPANY was negligent in the design of the 2000 FORD EXPLORER, which negligence was a proximate cause of the injuries and damages sustained by Plaintiffs.

25. At all times material hereto, all of the agents, servants, and/or employees for Defendant, FORD MOTOR COMPANY, who were connected with the occurrence made the subject of this suit, were acting within the course and scope of their employment or official duties and in

furtherance of the duties of their office or employment. Therefore, Defendant, FORD MOTOR COMPANY, is further liable for the negligent acts and omissions of its employees under the doctrine of Respondent Superior.

26. Defendant's aforementioned conduct constitutes a careless, negligent, and reckless disregard of a duty of care for others.

LIABILITY OF TEXAS INSTRUMENTS, INC.

27. While engaged in the manufacture and sale of the ignition switches, Defendant, TEXAS INSTRUMENTS, INC. manufactured and sold a certain ignition and or cruise control devices, and other like products, to consumers within the stream of commerce. Defendant, TEXAS INSTRUMENTS intended and expected that the devices, so introduced and passed on in the course of trade would ultimately reach a consumer or user in the condition in which it was originally sold.

28. Plaintiffs [REDACTED], also allege that the product in question, namely the ignition switches or cruise control component, was defective and unsafe for its intended purposes at the time it left the control of TEXAS INSTRUMENTS and at the time it was sold in that it failed in its design to prevent the ignition from withstanding the constant source of heat which caused the vehicle to ignite while it was not running. Due to the unsafe operation of, but not limited to, the cruise control switch, the product was defectively designed and unreasonably dangerous in that the vehicle was ignited while inoperable.

29. Plaintiffs therefore invoke the doctrine of strict liability in Section 402A, Restatement of the Law of Torts, 2d, and as adopted by the Supreme Court of Texas. Further, in this connection, Plaintiffs would show the court that the defect in design was a producing cause of the injuries and damages set forth below.

30. In addition, Plaintiffs would show the court that the occurrence made the basis of this

suit and the resulting injuries and damages set out below were a direct and proximate result of the negligence of TEXAS INSTRUMENTS, INC. in one or more of the following respects, or by combination thereof:

- A. Failure of the cruise control switch or other systems of said 2000 FORD EXPLORER and its attendant equipment
- B. Failing to inspect said device and its attendant equipment
- C. Failing to properly maintain said cruise control ignition switch and its attendant equipment
- D. Failing to properly warn Plaintiff about the condition of said device and its attendant equipment

31. Pleading further, Plaintiffs would show the court that the occurrence made the basis of this suit and the resulting injuries and damages set out below were a direct and proximate result of negligence attributable to TEXAS INSTRUMENTS, INC. in one or more of the following respects, or by a combination thereof:

- A. Failing to use due care in the manufacture of the switch used in 2000 FORD EXPLORER
- B. Failing to use due care in the design of the cruise control ignition switch used in the 2000 FORD EXPLORER
- C. Failing to use proper materials reasonably suited to the manufacture or design of the cruise control ignition switch used in the 2000 FORD EXPLORER or the component parts thereof
- D. Failing to use due care to test and/or inspect the cruise control ignition switch used in the 2000 FORD EXPLORER or the component parts thereof to determine its durability and function ability for the purpose for which it was intended

32. Pleading further, Plaintiffs would show the court that the occurrence made the basis of this suit and the resulting injuries and damages set out below were a direct and proximate result of the negligence of TEXAS INSTRUMENTS, INC. in one or more of the following respects, or by a

combination thereof:

- A. Failing to design the device used in the 2000 FORD EXPLORER to prevent the ignition from withstanding the constant source of heat which caused the vehicle to ignite while it was not running due to a malfunction
- B. Failing to design the cruise control component used in the 2000 FORD EXPLORER without a guard or shield on it as would have been done by a reasonable and prudent manufacturer under the same or similar circumstances

All of which Defendant, TEXAS INSTRUMENTS, INC. knew, or in the exercise of ordinary care, should have known.

33. In addition, Defendant TEXAS INSTRUMENTS, INC. expressly and impliedly warranted to the public generally, that the cruise control ignition switch used in the 2000 FORD EXPLORER was of merchantable quality and was safe and fit for the purpose intended when used under ordinary conditions and in an ordinary manner. Plaintiffs relied upon these express and implied warranties and suffered the injuries and damages set forth below as a proximate result of the breach of these warranties.

34. Plaintiffs cannot more specifically allege the act of negligent design on the part of Defendant, TEXAS INSTRUMENTS, INC. aside from TEXAS INSTRUMENTS INC.'s failure to design the cruise control ignition switch used in the 2000 FORD EXPLORER in question in a manner which would have prevented the ignition from withstanding the constant source of heat which caused the vehicle to ignite while it was not running, for the reason that facts in that regard are peculiarly within the knowledge of the Defendant, TEXAS INSTRUMENTS, INC. and, in the alternative, in the event Plaintiffs are unable to prove specific acts of negligent design, Plaintiffs rely on the doctrine of Res Ipsa Loquitur.

35. In this connection, Plaintiffs will show the court that the design of the switch used in

the 2000 FORD EXPLORER was within the exclusive control of Defendant, TEXAS INSTRUMENTS, INC., Plaintiffs had no means of ascertaining the method or manner in which the product was designed, and it was used by Plaintiffs in the same condition it was in when it left control of Defendant, TEXAS INSTRUMENTS, INC.

36. The occurrence causing harm to Plaintiffs, as described above, was one which, in the ordinary course of events, would not have occurred without negligence on the part of Defendant, TEXAS INSTRUMENTS, INC. Thus, TEXAS INSTRUMENTS, INC. was negligent in the design of the cruise control ignition switch used in the 2000 FORD EXPLORER, which negligence was a proximate cause of the injuries and damages sustained by Plaintiffs.

37. At all times material hereto, all of the agents, servants, and/or employees for Defendant, TEXAS INSTRUMENTS, INC., who were connected with the occurrence made the subject of this suit, were acting within the course and scope of their employment or official duties and in furtherance of the duties of their office or employment. Therefore, Defendant, TEXAS INSTRUMENTS, INC., is further liable for the negligent acts and omissions of its employees under the doctrine of Respondent Superior.

38. Defendant's aforementioned conduct constitutes a careless, negligent, and reckless disregard of a duty of care for others.

EXEMPLARY DAMAGES

39. Defendant FORD MOTOR COMPANY's acts or omissions described above, when viewed from the standpoint of Defendant FORD MOTOR COMPANY at the time of the act or omission, involved an extreme degree of risk, considering the probability and magnitude of the potential harm to Plaintiffs and others. Defendant FORD MOTOR COMPANY had actual, subjective awareness of the risk involved in the above described acts or omissions, but nevertheless

proceeded with conscious indifference to the rights, safety, or welfare of Plaintiffs and others.

40. Based on the facts stated herein, Plaintiffs request exemplary damages be awarded to Plaintiffs from Defendant FORD MOTOR COMPANY in the amount of \$10,000,000.00.

41. Defendant TEXAS INSTRUMENTS INC.'s acts or omissions described above, when viewed from the standpoint of Defendant TEXAS INSTRUMENTS, INC. at the time of the act or omission, involved an extreme degree of risk, considering the probability and magnitude of the potential harm to Plaintiffs and others. Defendant TEXAS INSTRUMENTS, INC. had actual, subjective awareness of the risk involved in the above described acts or omissions, but nevertheless proceeded with conscious indifference to the rights, safety, or welfare of Plaintiffs and others.

42. Based on the facts stated herein, Plaintiffs request exemplary damages be awarded to Plaintiffs from Defendant TEXAS INSTRUMENTS, INC. in the amount of \$10,000,000.00.

DAMAGES FOR PLAINTIFF [REDACTED]

43. As a direct and proximate result of the occurrence made the basis of this lawsuit, Plaintiff, [REDACTED] was caused to suffer destruction of his vehicle and property damage at [REDACTED] Houston, Texas [REDACTED] the amount of \$249,000.00.

DAMAGES FOR PLAINTIFF [REDACTED]

44. As a direct and proximate result of the occurrence made the basis of this lawsuit, Plaintiff [REDACTED] was caused to suffer property damage to the contents of her home.

45. As a direct and proximate result of the occurrence made the basis of this lawsuit, Plaintiff, [REDACTED] was caused to suffer personal injuries, and has incurred the following damages:

- A. Reasonable medical care and expenses in the past. These expenses were incurred by Plaintiff for the necessary care and treatment of the injuries resulting from the accident complained of herein and such charges are

reasonable and were usual and customary charges for such services in HARRIS County, Texas;

- B. Reasonable and necessary medical care and expenses which will in all reasonable probability be incurred in the future;
- C. Physical pain and suffering in the past;
- D. Physical pain and suffering in the future;
- E. Physical impairment in the past;
- F. Physical impairment which, in all reasonable probability, will be suffered in the future;
- G. Loss of earnings in the past;
- H. Loss of earning capacity which will, in all probability, be incurred in the future;
- I. Property damages in the amount of \$75,000.00;
- J. Mental anguish in the past;
- K. Mental anguish in the future;
- L. Fear of future disease or condition; and
- M. Cost of medical monitoring and prevention in the future.

PRAYER

WHEREFORE, PREMISES CONSIDERED, Plaintiffs [REDACTED] and

[REDACTED] respectfully pray that the Defendants be cited to appear and answer herein, and that upon a final hearing of the cause, judgment be entered for the Plaintiffs against Defendants, jointly and severally, for damages in an amount within the jurisdictional limits of the Court; exemplary damages, as addressed to each Defendant per Section 41.006, Chapter 41, Texas Civil Practice and Remedies Code, excluding interest, and as allowed by Sec. 41.008, Chapter 41, Texas Civil Practice and Remedies Code; together with pre-judgment interest (from the date of injury

through the date of judgment) at the maximum rate allowed by law, post-judgment interest at the legal rate, costs of court; and such other and further relief to which the Plaintiffs may be entitled at law or in equity.

Respectfully submitted,

LAW OFFICE OF TRACIE L. TIPPEN

By: 

TRACIE L. TIPPEN

Texas Bar No. 00788891

1306 Rosedale Street

Houston, Texas 77004

Tel. (713)533-0782


Fax. (713)533-0114

Attorney for Plaintiffs

RALEIGH L. WOODARD

and BEATRICE COLLINS

PLAINTIFFS HEREBY DEMAND TRIAL BY JURY



July 12, 2004



Ford Motor Company Consumer Affairs
P O Box 6248
MD-3NE-B
Dearborn MI 48126

CONSUMER AFFAIRS
SECTION

4 JUL 15 09:47

RE: Insured: [REDACTED]
Claim No.: [REDACTED]
Date of Loss: 05/30/04
Subrogation Amt: \$5,393.79

FORD MOTOR COMPANY
RECEIVED
CLAIMS UNIT

JUL 16 2004

OFFICE OF THE
GENERAL COUNSEL

Dear Ford Motor Company Consumer Affairs,

On or about May 30th, 2004, a transmission, recently purchased and installed by Kerry Lincoln Mercury, had caused fire damages to our insured's 2001 Ford Explorer. We have settled with our policyholder and now look to you for reimbursement of \$5,393.79. The transmission was purchased and installed on March 30th, 2004. A copy of the invoice is also enclosed for your review.

If you were covered by insurance merely complete Section 1 of the attached form and return the form to us. We will then deal directly with your insurance company. If you were not covered by insurance, please send us your check for the above amount. If this amount is such that you cannot pay it all at once, please complete Section 2 of the attached form and return the form to us. Failure to pay or to make arrangements for payment may result in revocation of your driving rights by the Financial Responsibility Division of the State. (See Section 3 and complete this.)

Please complete the attached form and return it to us within two weeks.

Thank you.

Sincerely,

Jason F. Baldwin
Claim Representative

Enclosure

A 08013 08 Date 05 20 2004 051 Station 04-0004141 000 Supervisor 08134 -1 Major	
B Location <input checked="" type="checkbox"/> Street address [redacted] <input type="checkbox"/> Intersection [redacted] Street of Highway <input type="checkbox"/> In front of [redacted] Mt. Crab <input type="checkbox"/> Rear of [redacted] <input type="checkbox"/> Adjacent to [redacted] <input type="checkbox"/> Directions [redacted] (Please print or type name, as applicable)	
C Incident Type <input checked="" type="checkbox"/> 111 Passenger vehicle fire <input type="checkbox"/> 112 Other fire <input type="checkbox"/> 113 Other fire	
D Aid Given or Received <input type="checkbox"/> 1 Mutual aid received <input type="checkbox"/> 2 Automatic aid sent <input type="checkbox"/> 3 Mutual aid given <input type="checkbox"/> 4 Automatic aid given <input type="checkbox"/> 5 Other aid given <input checked="" type="checkbox"/> 6 None (Type from table) (Type Resident Number)	
E Data & Times Check hours if alarm was 2nd alarm Alarm 05 30 2004 15:46:00 Arrival 05 30 2004 16:02:00 Depart 05 30 2004 16:20:00 (Check box if response time is 15 minutes or less)	
F Actions Taken <input checked="" type="checkbox"/> 06 Investigate (Primary action taken) (Additional action taken) (Additional action taken)	
G Estimated Dollar Losses & Values (Check box if response time is 15 minutes or less) Property \$ 000,000 Contents \$ 000,000 Other \$ 000,000 (Check box if response time is 15 minutes or less)	
H Casualties <input type="checkbox"/> 1 Fatalities <input type="checkbox"/> 2 Injuries <input type="checkbox"/> 3 Other	
I Hazardous Materials Release <input type="checkbox"/> 1 Release <input type="checkbox"/> 2 Release <input type="checkbox"/> 3 Release <input type="checkbox"/> 4 Release <input type="checkbox"/> 5 Release <input type="checkbox"/> 6 Release <input type="checkbox"/> 7 Release <input type="checkbox"/> 8 Release <input type="checkbox"/> 9 Release <input type="checkbox"/> 0 Release	
J Property Use <input type="checkbox"/> 131 Church, place of worship <input type="checkbox"/> 141 Restaurant or cafeteria <input type="checkbox"/> 151 Bar/club or nightclub <input type="checkbox"/> 161 Elementary school or kindergarten <input type="checkbox"/> 171 High school or junior high <input type="checkbox"/> 181 College, adult education <input type="checkbox"/> 191 Care facility for the aged <input type="checkbox"/> 201 Hospital <input type="checkbox"/> 211 Outside <input type="checkbox"/> 221 Playground or park <input type="checkbox"/> 231 Camp or resort <input type="checkbox"/> 241 Airport (timberland) <input type="checkbox"/> 251 Outdoor storage area <input type="checkbox"/> 261 Dump or sanitary landfill <input type="checkbox"/> 271 Open land or field	
K Miscellaneous <input type="checkbox"/> 301 Construction site <input type="checkbox"/> 311 Industrial plant yard <input type="checkbox"/> 321 Warehouse <input type="checkbox"/> 331 Storage yard <input type="checkbox"/> 341 Other	

06/19/2004 16:37 9374444788

MT. CRAB FIRE DEPT.

PAGE 05

K1 Person/Entity Involved

Local Office: _____ Business name (if applicable): _____ Area Code: _____ Phone Number: _____

☐ Check this box if your address is outside Oregon. Then fill in the three additional address lines.

Mr./Ms./Mx. First Name: _____ MI: _____ Last Name: _____ Office: _____

Address: _____ Profile Street or Highway: _____ Street Type: _____ Zip: _____

Post Office Box: _____ Apt./Unit/Room: _____ City: _____

State: _____ Zip Code: _____

☐ Were people involved? Check this box and attach Supplemental Forms (K111a-1d) as necessary.

K2 Owner

☐ Same as person involved? Then check this box and skip the rest of this section. Business name (if applicable): _____ Area Code: _____ Phone Number: _____

☒ Check this box if other address or telephone number. Then fill in the three additional address lines.

Mr./Ms./Mx. First Name: _____ MI: _____ Last Name: _____ Office: _____

Address: _____ Profile Street or Highway: _____ Street Type: _____ Zip: _____

Post Office Box: _____ Apt./Unit/Room: _____ City: _____

State: _____ Zip Code: _____

CH: _____

I. Remarks

Local Office

Upon our arrival owner had fire out. Most of the fire damage was near the bottom of the fire wall in engine area. Upon investigate of the fire found what looked to be a trail of transmission fluid coming up for the rear of the vehicle.

I. Authorization

KING01 **King, Michael S** **AC** **1M11** **06** **19** **2004**

Officer in charge ID: _____ Signature: _____ Position or rank: _____ Assignment: _____ Month: _____ Day: _____ Year: _____

☒ Check box if you are carrying on duty.

KING01 **King, Michael S** **AC** **1M11** **06** **19** **2004**

Officer in charge ID: _____ Signature: _____ Position or rank: _____ Assignment: _____ Month: _____ Day: _____ Year: _____

A 08013 08 05 33 2004 071 04-0006141 000 TPOD State Incident Date Station Number Incident Number		Victim Chapter No Activity		MPFD-2 Fire
B Property Details B1 0001 <input type="checkbox"/> Not Residential Estimated Number of residential living units in building of origin whether or not all units became involved B2 <input type="checkbox"/> Buildings not involved Number of buildings involved B3 <input type="checkbox"/> None Areas Involved (Outside Space) <input type="checkbox"/> Less than one acre		C On-Site Materials or Products Enter up to three codes. Check one or more boxes for each code entered. 0000 None On-site material (1) On-site material (2) On-site material (3) 1 <input type="checkbox"/> Bulk storage or warehousing 2 <input type="checkbox"/> Processing or manufacturing 3 <input type="checkbox"/> Packaged goods for sale 4 <input type="checkbox"/> Repair or service 1 <input type="checkbox"/> Bulk storage or warehousing 2 <input type="checkbox"/> Processing or manufacturing 3 <input type="checkbox"/> Packaged goods for sale 4 <input type="checkbox"/> Repair or service 1 <input type="checkbox"/> Bulk storage or warehousing 2 <input type="checkbox"/> Processing or manufacturing 3 <input type="checkbox"/> Packaged goods for sale 4 <input type="checkbox"/> Repair or service		
D Ignition D1 03 Engine area, running Area of fire origin D2 12 Radiated, conducted Heat source D3 02 Flammable liquid/gas - Area first ignited 1 <input type="checkbox"/> Gas confined in closed or sealed D4 00 Flammable or Type of material first ignited		E Cause of Ignition <input type="checkbox"/> Check box if this is a separate report. Skip to section 6 1 <input type="checkbox"/> Intentional 2 <input type="checkbox"/> Unintentional 3 <input type="checkbox"/> Failure of equipment or heat source 4 <input type="checkbox"/> Act of nature 5 <input type="checkbox"/> Cause under investigation 6 <input type="checkbox"/> Cause undetermined after investigation F Factors Contributing To Ignition 03 Leak or break Factors contributing to ignition (1) Factors contributing to ignition (2)		
F1 Equipment Involved In Ignition <input type="checkbox"/> None Equipment involved Brand Model Serial # Year		F2 Equipment Power Equipment power source F3 Equipment Portability 1 <input type="checkbox"/> Portable 2 <input type="checkbox"/> Stationary Portable equipment usually can be moved by one person, is designed to be used in multiple locations, and requires no tools to install.		
G Fire Suppression Factors Enter up to three codes. <input type="checkbox"/> None 0000 None Fire suppression factor (1) Fire suppression factor (2) Fire suppression factor (3)		H Mobile Property Involved <input type="checkbox"/> None 1 <input type="checkbox"/> Not involved in ignition, but burned 2 <input type="checkbox"/> Involved in ignition, but did not burn 3 <input checked="" type="checkbox"/> Involved in ignition and burned H1 Mobile Property Type & Make 11 Passenger car White property type 00 Ford White property make Local Use <input type="checkbox"/> Non-Use Best of the information presented in this report may be based upon reports from other agencies <input type="checkbox"/> Agency report attached <input type="checkbox"/> Police report attached <input type="checkbox"/> Commercial report attached <input type="checkbox"/> Other reports attached		
Employer Mobile property report 2001 State VIN Number		MPFD-2 Revision 01/15/99		

June 18, 2004

Mr. Jason Baldwin
Grange Insurance Company
PO Box 182320
Columbus, OH 43218-2320

Re: Vehicle Fire Origin & Cause
Williamsburg, OH
Your Insured [REDACTED]
Your File APV 000238063
Rzesutock Engineering Project No. OH040611A

Dear Mr. Baldwin

At your request, June 12, 2004, I traveled to Chasetown Tractor Sales in Fayetteville, Ohio, and the residence of [REDACTED] in Williamsburg, Ohio, in order to examine a 2001 Ford Explorer which had burned on May 30, 2004. You requested that I offer an engineering opinion in regard to the circumstances, cause and origin of the fire

According to [REDACTED] a Ford remanufactured transmission (purchased from Kerry Ford) had been installed in the Explorer on March, 30, 2004. At that time, the mileage of the Explorer was 50,253. The repairs were performed by a technician at Kerry Ford. [REDACTED] stated that the repair was required as the transmission would slip while in overdrive and the overdrive light would flicker off and on. Several weeks after the transmission was installed, the same driveability problems re-occurred. The Explorer was returned to Kerry Ford for several weeks. The transmission was not repaired and [REDACTED] stated that the technician told him to drive the Explorer until the transmission failed. After the Explorer was returned to [REDACTED] it was examined by Mt. Orab Ford. Mt. Orab Ford reported that the overdrive light was flashing, the transmission was "missing" and that no electrical fault codes were retrieved from the PCM.

Mr. Woods stated that on the day of the fire he and his wife drove to a flea market near



Rzesutock Engineering
Forensic Motor Vehicle Engineering

2168 U.S. Route 50 • Fayetteville, Ohio 45118 • Phone/Fax: 888-875-5204

EA05-005-LC-10088

Franklin, Ohio. While they were returning to their residence, the transmission was not operating properly. When they arrived at their driveway the Explorer would not move forward [redacted] wife walked to their house and [redacted] restarted the Explorer. He drove it to the house and then observed smoke was being emitted from the hood. He opened the hood, saw flames and extinguished the fire with a garden hose.

Figure 1, in the photograph supplement to this report, is a view of the drive way at the [redacted] residence. [redacted] identified the oil stain shown in Figure 2 as the location where the Explorer first stopped operating. The oil stain pointed out by the arrow added to Figure 3 is the location where he parked the Explorer and extinguished the fire. Figure 4 is a closer view of this location.

Figures 5 through 9, are general views of the 2001 Ford Explorer. The VIN was 1FMYU70E91U [redacted] and the Ohio license plate was [redacted]. The odometer had recorded 52,221 miles. The Explorer featured a V8 engine, a 3 speed automatic transmission with over drive and four wheel drive. Over drive is enabled when the overdrive button is depressed by the driver. The automatic transmission featured electronic controls and featured both an external transmission fluid cooler and a radiator fluid cooler.

Figures 10 through 12 are views of the engine compartment. The engine compartment featured burn damage where the plastic components had been melted by heat or where the exposed surfaces had sustained superficial direct burn damage. No components had been completely consumed by the fire. All fluid levels were adequate. The automatic transmission fluid (ATF) featured a strong odor consistent with overheating. Figures 13 and 14 are views of the ATF filler tube and cap. The position of the ATF dipstick cap at the time of the fire (either tight on the tube or not fully inserted) was not known. No indications of the origin of the fire were observed in the engine compartment.

Figures 15 and 16 are views of the interior of the Explorer. The interior had sustained no burn damage. Figure 17 is a view of the passenger side carpet under layment; again no burn damage was observed.

Figure 18 is a view of the underside of the Explorer. The underside featured a light coating of fluid consistent in color and odor with ATF. No fluid leaks were observed at either ATF cooler or at the conduits leading to the coolers. Fluid stains were observed on the underside of the heat shield located adjacent to the cooler line connections and the dip stick tube connection at the passenger side of the transmission housing. The ATF dipstick tube is pointed out by the upper arrow added to Figure 19 and the cooler fluid conduits are pointed out by the lower added to Figure 19. Fluid stains are also visible on the heat shield of the catalytic converter. Figure 20 is a closer view of the fluid stains on the under side of the vehicle at a location adjacent to the transmission.

An examination of the cooling conduits indicated that their connectors were at least hand tight on the transmission housing (it was not possible to place a wrench on the hex

fitting). Fluid stains were present where the filler tube was pressed into the transmission housing. The location of the fluid stains on the filler tube indicated that the fluid did not erupt from the upper opening of the filler tube; there were no stains along the length of the tube or on components adjacent to the tube. All fluid stains were located at the bottom of the tube.

Based on the reports of the incident including the operation of the transmission, the observed burn damage, and the fluid stains, the fire originated when transmission fluid leaked from the bottom fitting of the filler tube and was ignited by the heat of the catalytic converter. Heat and flames then entered the engine compartment.

The exact reason for the fluid eruption is unknown. However, based on the repairs records and the reported driveability problems experienced by the drivers of the Explorer, the transmission was malfunctioning and this malfunction was the cause of the fluid eruption. Furthermore, This malfunction prevented the Explorer from being driven immediately prior to the fire. Thus, the transmission was not operating properly prior to the fire and most likely was damaged prior to the fire.

A search of the National Highway and Transportation Safety Administration (NHTSA) website did not return any recalls, defect investigations or consumer complaints consistent with the reports of the incident.

Based on the foregoing observations and analysis, the following are my opinions, to a reasonable degree of engineering certainty, regarding the origin and cause of the fire in the Ford Explorer. The fire originated at the passenger side catalytic converter; the first material ignited was automatic transmission fluid and the heat of ignition was provided by the catalytic converter. The cause of the fire was an eruption of transmission fluid from the filler tube of the malfunctioning transmission.

As your request, this letter is being sent in order to summarize my findings. If you should have any questions, please feel free to contact me. I appreciate the opportunity to have been of service to you.

Sincerely,

Michael P. Razutock

Michael P. Razutock
Professional Engineer
State of Ohio
Registration E-51954



enclosures

Project: OH040611A
Page 3




Figure 1. View of Driveway at Woods' Residence



Figure 2. View of Oil Stain at Location Where Explorer Stopped
Operating




Figure 3. View of Location of Fire



Figure 4. Closer View of Location of Fire



Figure 5. Front View of Explorer




Figure 6. Passenger Side Front View of Explorer



Figure 7. Passenger Side Rear View of Explorer




Figure 8. Driver Side Rear View of Explorer




Figure 9. Driver Side Front View of Explorer




Figure 10. View of Engine Compartment



Figure 11. View of Engine Compartment



Figure 12. View of Engine Compartment



Figure 13. View of Automatic Transmission Fluid Dipstick Cap




Figure 14. View of Automatic Transmission Fluid Dipstick Cap



Figure 15. View of Driver Side of Interior




Figure 16. View of Passenger Side of Interior



Figure 17. View of Under Layment



Figure 18. Passenger Side View of Fluid Stain

APV 238063



Figure 19. View of Dip Stick Tube, Conduits to Coolers and Catalytic Converter



Figure 20. Closer View of Fluid Stain

Claim Reference Id

File Name

File Date

Label

Note

PHOTO3

08/02/2004

Style:1, FORD, EXPLORER 4X4
SPORT Internal:Woods, Douglas

Photo Location

Photo Taken By

Estimate Indicator

Rich Krauss

000

Claim Reference Id

File Name

File Date

Label

Note

PHOTO1

08/02/2004

Style:1, FORD, EXPLORER 4X4
SPORT Internal:Woods, Douglas

Photo Location

Photo Taken By

Estimate Indicator

Rich Krauss

000

Claim Reference Id

File Name

File Date

Label

Note

APV00000000-001-1

PHOTO2

08/02/2004

Style:1, FORD, EXPLORER 4X4
SPORT Internal:Woods, Douglas

Photo Location

Photo Taken By

Estimate Indicator

Rich Krauss

000

Claim Reference Id

File Name

File Date

Label

Note

APV00000000-001-1

PHOTO4

08/02/2004

Style:1, FORD, EXPLORER 4X4
SPORT Internal:Woods, Douglas

Photo Location

Photo Taken By

Estimate Indicator


Rich Krauss

000



Claim Reference Id [REDACTED]
File Name PHOTOS
File Date 08/02/2004
Label
Note Style:1, FORD, EXPLORER 4X4
SPORT] Inland/Woods, Douglas

Photo Location
Photo Taken By Nick Kruse
Ballistic Indicator 503



Claim Reference Id [REDACTED]
File Name PHOTOS
File Date 08/02/2004
Label
Note Style:1, FORD, EXPLORER 4X4
SPORT] Inland/Woods, Douglas

Photo Location
Photo Taken By Nick Kruse
Ballistic Indicator 503



Claim Reference Id [REDACTED]
File Name PHOTOS
File Date 08/02/2004
Label
Note Style:1, FORD, EXPLORER 4X4
SPORT] Inland/Woods, Douglas

Photo Location
Photo Taken By Nick Kruse
Ballistic Indicator 503



Claim Reference Id [REDACTED]
File Name PHOTOS
File Date 08/02/2004
Label
Note Style:1, FORD, EXPLORER 4X4
SPORT] Inland/Woods, Douglas

Photo Location
Photo Taken By Nick Kruse
Ballistic Indicator 503



Chain Reference Id [REDACTED]
File Name PHOTO6
File Date 08/02/04
Label
Note Subject, FORM, EXPLORER 4X4
SPORT] Inland:Woods, Douglas

Photo Location
Photo Taken By TOM ELLIOTT
Estimate Indicator 001




Chain Reference Id [REDACTED]
File Name PHOTO6
File Date 08/02/04
Label
Note Subject, FORM, EXPLORER 4X4
SPORT] Inland:Woods, Douglas

Photo Location
Photo Taken By TOM ELLIOTT
Estimate Indicator 001



Chain Reference Id [REDACTED]
File Name PHOTO6
File Date 08/02/04
Label
Note Subject, FORM, EXPLORER 4X4
SPORT] Inland:Woods, Douglas

Photo Location
Photo Taken By TOM ELLIOTT
Estimate Indicator 001



Chain Reference Id [REDACTED]
File Name PHOTO6
File Date 08/02/04
Label
Note Subject, FORM, EXPLORER 4X4
SPORT] Inland:Woods, Douglas

Photo Location
Photo Taken By TOM ELLIOTT
Estimate Indicator 001



Chain Reference Id

File Name

File Date

Label

Note

PHOTO

06032004

Style:1, FORD, EXPLORER 4X4
SPORT, Inland:Woods, Douglas

Photo Location

Photo Taken By

Estimate Indicator

Chain Reference Id

File Name

File Date

Label

Note

TON ELLIOTT

001

PHOTO

06032004

Style:1, FORD, EXPLORER 4X4
SPORT, Inland:Woods, Douglas

Photo Location

Photo Taken By

Estimate Indicator

TON ELLIOTT

001




Chain Reference Id [REDACTED]
File Name PHOTO3
File Date 06/24/2004
Label
Note Subject: FORD, EXPLORER 4x4
SPORT] Internal:Woods, Douglas]

Photo Location
Photo Taken By Rick Kross
Estimate Indicator 801



Chain Reference Id [REDACTED]
File Name PHOTO3
File Date 06/24/2004
Label
Note Subject: FORD, EXPLORER 4x4
SPORT] Internal:Woods, Douglas]

Photo Location
Photo Taken By Rick Kross
Estimate Indicator 801



Chain Reference Id [REDACTED]
File Name PHOTO3
File Date 06/24/2004
Label
Note Subject: FORD, EXPLORER 4x4
SPORT] Internal:Woods, Douglas]

Photo Location
Photo Taken By Rick Kross
Estimate Indicator 801



Chain Reference Id [REDACTED]
File Name PHOTO3
File Date 06/24/2004
Label
Note Subject: FORD, EXPLORER 4x4
SPORT] Internal:Woods, Douglas]

Photo Location
Photo Taken By Rick Kross
Estimate Indicator 801

Claim Reference Id

File Name

File Date

Label

Note

PHOTO6

08/08/2004

Style:1, FORD, EXPLORER 4X4
SPORT] Inland/Woods, Douglas]

Photo Location

Photo Taken By

Reference Indicator

Claim Reference Id

File Name

File Date

Label

Note

Rick Krause

003

PHOTO7

08/08/2004

Style:1, FORD, EXPLORER 4X4
SPORT] Inland/Woods, Douglas]

Photo Location

Photo Taken By

Reference Indicator

Claim Reference Id

File Name

File Date

Label

Note

Rick Krause

003

PHOTO8

08/08/2004

Style:1, FORD, EXPLORER 4X4
SPORT] Inland/Woods, Douglas]

Photo Location

Photo Taken By

Reference Indicator

Claim Reference Id

File Name

File Date

Label

Note

Rick Krause

003

PHOTO9

08/08/2004

Style:1, FORD, EXPLORER 4X4
SPORT] Inland/Woods, Douglas]

Photo Location

Photo Taken By

Reference Indicator

Rick Krause

004



Claim Reference ID [REDACTED]
File Name PHOTO1
File Date 08/04/2004
Label
Note Style:1, FORD, EXPLORER 4X4
SPORT] Inwood-Woods, Douglas]

Photo Location
Photo Taken By Rick Kruse
Reference Indicator 000



Claim Reference ID [REDACTED]
File Name PHOTO2
File Date 08/04/2004
Label
Note Style:1, FORD, EXPLORER 4X4
SPORT] Inwood-Woods, Douglas]

Photo Location
Photo Taken By Rick Kruse
Reference Indicator 000




Claim Reference ID [REDACTED]
File Name PHOTO3
File Date 08/04/2004
Label
Note Style:1, FORD, EXPLORER 4X4
SPORT] Inwood-Woods, Douglas]

Photo Location
Photo Taken By Rick Kruse
Reference Indicator 000



Claim Reference ID [REDACTED]
File Name PHOTO4
File Date 08/04/2004
Label
Note Style:1, FORD, EXPLORER 4X4
SPORT] Inwood-Woods, Douglas]

Photo Location
Photo Taken By Rick Kruse
Reference Indicator 000



RELIANCE
Personal Insurance


2049 Silas Deane Highway, Rocky Hill, CT 06067
Phone: 860-721-8570 Fax: 860-721-1531

CUSTOMER SUPPORT
CENTER

2000 JAN 19 'A & 14'

CERTIFIED AND REGULAR U.S. MAIL

2ND NOTIFICATION



January 10, 2000

Ford Motor Company - Legal Department
P.O. Box 6248
Dearborn, MI 48126

To whom it may concern:

Attached you will find a letter I previously sent to your Ford Dealer in Maine. I have not received a response. I also attempted to reach you via your customer Connection on e-mail. Please contact me as soon as possible if you wish to participate in the examination described in the attached December 22, 1999 letter.

Reliance Personal Insurance Co.
Attn James P. Meehan
2049 Silas Deane Highway
Rocky Hill, CT 06067

Sincerely

A handwritten signature in cursive script that reads "James P. Meehan".

James P. Meehan

ER05-005-LC-10119

RELIANCE

Personal Insurance

392 Wampanoag Trail, East Providence, RI 02915
Toll Free: 800-686-8828
Phone: 401-434-1994 Fax: 401-434-4296

CERTIFIED AND REGULAR U.S. MAIL

December 22, 1999

Ford Customer Assistance
ATTN: Legal Department
Wiscasset Ford Inc.
Box 253
Wiscasset, ME 04578

RE: Vehicle : 1999 Ford Ranger Pickup truck

VIN: 1FTZR15V4XT [REDACTED]

Owner: [REDACTED]

NETS#: 001340

CLAIM#: 00-18601

To Whom It May Concern:


I represent Reliance Personal Insurance Company's Special Investigation Unit. The above vehicle was involved in a fire of alleged unknown origin. The loss occurred in New Hampshire.

In order to determine the cause of the fire, including a determination as to whether any defect in the vehicle was in existence at the time of the loss, a representative of North Eastern Technical Services, Inc., will conduct an inspection and testing of the vehicle. This inspection will take place at Auto Placement Center in East Providence, Rhode Island.

As Ford Motor Corporation has an interest in this matter, from both a safety precaution standpoint and as a potential defendant in litigation, you are invited to have an expert attend and participate in the inspection and testing procedures.

To coordinate the inspection date and time, please contact North Eastern Technical Services, Inc., at 508-675-0999. If you have any questions pertaining to this matter, you may contact the undersigned at 1-860-721-0570.

Please note that if you choose not to participate in the inspection, you will forfeit any right to subsequently claim prejudice under Nally Vs. Volkswagen, Inc., 405 Mass 191 (1989)

Sincerely,

James P. Meehan
S.I.U. Investigator

Policies Underwritten By:

Reliance National
Insurance Company

Reliance Insurance
Company

Reliance National
Indemnity Company


United Pacific
Insurance Company

Reliant Insurance
Company

Reliant Casualty
Insurance Company

Reliance Direct
Insurance Company

ER05-005-LC-10120



IN THE CIRCUIT COURT FOR
SHELBY COUNTY, ALABAMA

[REDACTED]

Plaintiffs,

FORD MOTOR COMPANY,

Defendant.

CV-2002-_____

COMPLAINT

PARTIES

1. American National Property and Casualty Company is a corporation with its principal place of business in Missouri doing business by agent in Shelby County, Alabama.
2. [REDACTED] are husband and wife. They are over the age of nineteen (19) and reside in Shelby County, Alabama.
3. Ford Motor Company is a corporation with its principal place of business in Michigan. At all times relevant to the allegations of this Complaint, Ford Motor Company did business by agent in Shelby County, Alabama.

FACTS

[REDACTED] purchased a 1997 Ford F-150 Pickup.

On February 21, 2002 said truck was parked with the engine off on the property of [REDACTED]. Said truck caught fire and was destroyed.

5. At the time of said fire [REDACTED] were insured by American National Property and Casualty Company. As a proximate result of the loss of said truck, American National was caused to expend \$9,025.00 for damage to the vehicle and \$750.00 for a rental vehicle. The [REDACTED] were caused to lose their deductible, \$500.00.

COUNT ONE

BREACH OF WARRANTY

6. Plaintiffs incorporate by reference all preceding paragraphs of this Complaint as if fully set out herein.
7. The truck manufactured by Ford Motor Company failed due to defective materials, design and/or workmanship. Said failure constitutes a breach of warranty, both express and implied on the part of Ford Motor Company.

WHEREFORE, PREMISES CONSIDERED, American National demands judgment in the amount of \$9,775.00. [REDACTED] demand judgment in the amount of their deductible, \$500.00.

COUNT TWO

ALABAMA MANUFACTURER'S EXTENDED LIABILITY DOCTRINE

8. Plaintiffs incorporate by reference all preceding paragraphs of this Complaint as if fully set out herein.
9. Ford Motor Company was in the business of selling trucks such as the truck purchased by [REDACTED]. Said truck was expected to reach the user, in this case, [REDACTED] without substantial

change in condition. Said truck was defective and, as a proximate result of said defect, was destroyed by fire, causing loss on the part of American National and [REDACTED] Said facts render Defendant liable under the Alabama Manufacturer's Extended Liability Doctrine.

WHEREFORE, PREMISES CONSIDERED, American National demands judgment in the amount of \$9,775.00. [REDACTED] demand judgment in the amount of their deductible, \$500.00.

COUNT THREE

FAILURE TO WARN

10. Plaintiffs incorporate by reference all preceding paragraphs of the Complaint as if fully set out herein.

11. Ford Motor Company failed to warn [REDACTED] that its product could burn and be destroyed by fire. As a proximate result of said failure to warn, the truck was destroyed, causing loss to American National and [REDACTED]

WHEREFORE, PREMISES CONSIDERED, American National demands judgment in the amount of \$9,775.00. [REDACTED] demand judgment in the amount of their deductible, \$500.00.

COUNT FOUR

MAGNUSON-MOSS ACT

12. Plaintiffs incorporate by reference all preceding paragraphs of the Complaint as if fully set out herein.

13. Defendant placed said defective truck in the stream of commerce.


Said truck was intended to reach, and did reach, [REDACTED] in a condition unchanged from when it left the possession of the Defendant. Plaintiffs were damaged as a proximate result of the defective condition of said truck.

14. Defendant has been notified of said defects and damages by Plaintiffs and has failed or refused to reimburse Plaintiffs for their loss.

15. Defendant's failure or refusal to reimburse Plaintiffs for their loss constitutes a violation of the Magnusson-Moss Warranty-Federal Trade Commission Improvement Act (the Magnusson-Moss Act).

WHEREFORE, PREMISES CONSIDERED, American National demands judgment in the amount of its subrogation interest, \$9,775.00. [REDACTED]

[REDACTED] demand judgment in the amount of their deductible, \$500.00. In addition, Plaintiffs demand costs and attorney's fees incurred in this action.



JEFFREY W. SMITH (SMI088)
Attorney for Plaintiff American
National Property and Casualty
Company and Larry Wyatt and
Mindy Wyatt

OF COUNSEL:
Post Office Box 4486
Montgomery, AL 36103-4486
(334) 264-1640

DEFENDANT MAY BE SERVED AT:
Office of General Counsel
Ford Motor Company
Parklane Towers West, Suite 300
Three Parklane Boulevard
Dearborn, MI 48126-2566

JEFFREY W. SMITH
ATTORNEY AT LAW
(334) 264-1640
FACSIMILE (334) 264-8640

640 S. McDONOUGH ST.
MONTGOMERY, AL 36104

MAILING ADDRESS:
P.O. Box 4486
MONTGOMERY, AL 36103-4486

June 25, 2002

Claims Department
Ford Motor Company
Parklane Towers West
3 Parklane Boulevard, Suite 300
Dearborn, MI 48128

ATTN: Shawn Norton

RE: American National Property and Casualty Company
Claim No. : [REDACTED]
Insured : [REDACTED]
DOL : 2/21/02

Dear Mr. Norton:

This office represents American National Property and Casualty Company and its insured, [REDACTED] in relation to a fire which destroyed [REDACTED] 1997 Ford F-150 Supercab Pickup. The VIN on this vehicle is 1FTDX172XVI [REDACTED]

You are aware of this loss and have been provided a copy of the Fire Cause and Origin Report by Karen Steury of American National. As you know, American National's loss is \$8,775.00. This includes [REDACTED] \$500.00 deductible and \$750.00 for rental expenses.


As you know this vehicle is located at the Sadiesco Salvage Pool in Birmingham, AL. I have advised Ms. Steury to pay storage fees for one month from the date of this letter to allow you one final opportunity to investigate this loss. If Ford declines to do that within that time, my advice will be to abandon this total loss rather than continue to pay storage fees. I suggest you consult with Alabama counsel on the law regarding spoliation. A claimant is under no duty to indefinitely preserve evidence in the face of indifference on the part of Ford Motor Company.

ER85-085-LC-10125

Claims Department
Attn: Shawn Norton
June 25, 2002
Page -2-

If it is Ford's position that there is no responsibility for the fire loss of this vehicle, please notify me to this effect within two weeks. If I do not hear from you within that time, I will advise American National to file suit. I look forward to hearing from you on this matter.

Very truly yours,



Jeffrey W. Smith

JWS/cmc

6939 Honor Keith Road
Tusculum, AL 35173



Business (205) 655-5404
Fax (205) 655-7024

COMPLETE FIRE AND GENERAL INVESTIGATIONS

**PRIVILEGED AND CONFIDENTIAL
REPORT NUMBER ONE
March 23, 2002**

PREPARED FOR:

American National Property
& Casualty Insurance Co.
1949 East Sunshine Street
Springfield, MO 65899-0001

ATTENTION:

Mark Bowers

INSURED:



VEHICLE DESCRIPTION:

1997 Ford F-150
4X2 Supercab Styleside

VEHICLE ID NUMBER:

1FTDX172XVN



DAY, DATE & TIME OF LOSS:

Thursday, February 21, 2002
6:00 P.M.

POLICY NUMBER:



CLAIM NUMBER:

PYRTECH FILE NUMBER:

22058

ENCLOSURES:

1. A vehicle diagram with legend and overlay
2. Twenty-seven mounted color photographs
3. Unmounted photographs and all negatives

ASSIGNMENT:

This assignment was received on February 23, 2002 from Mr. Mark Bowers with specific instructions to conduct an origin and cause examination. This examination was conducted on February 28, 2002 at the incident site and residence of the insured, [REDACTED] Alabaster, Alabama [REDACTED]

VEHICLE DESCRIPTION:

This is a black 1997 Ford F-150, 4X2 Supercab Styleside pick-up truck. The manufacturer's data plate indicates the vehicle was manufactured in September 1996 and the odometer registers 127,412 miles. The Alabama license plate reads [REDACTED] and expires in October 2002. The vehicle is powered by a 4.2-liter V-6, electronically fuel injected gasoline engine and a manual transmission.

All directional references to the vehicle are as if one is seated in the driver's seat.

EXTERIOR EXAMINATION:

The aluminum hood is almost completely melted away, with small areas remaining at the extreme left front and rear corners. The left front tire is deflated due to fire damage and the left front fender has heat damage and paint remaining at the front and the rear edges. The right front tire is also deflated due to fire damage and the right front fender is damaged immediately above. The plastic grill is more extensively damaged at the right side and there is an extensive burn pattern on the right side of the roof that decreases steadily from the windshield channel toward the rear.

The right side of the rear window exhibits slightly more significant fire damage than the left side. Burn patterns indicate this fire originated at the right side of the engine compartment.

INTERIOR EXAMINATION:

Extensive fire damage present throughout increases steadily toward the roof and forward to the right side of the dash. Upper surface burning occurred on children's car seats and other personal items in the rear seat due to heat that extended from the front. The right front seat exhibits more extensive damage than the left front and charring of the dash upholstery is more extensive on the right side. The burn pattern on the underside of the right side of the roof corresponds with damage to the right side of the interior and coincides with the pattern across the top of the roof. Patterns of burning indicate fire extended into the interior from the right side of the engine compartment.

ENGINE COMPARTMENT EXAMINATION:

Fire damage is confined primarily to upper surface burning that decreases steadily toward grade level. The large, plastic air intake and air filter assembly that attaches to the intake manifold at the top center of the engine and extends forward and to the left side is completely burned away. Burning of these components eventually involved the power steering fluid reservoir and the master cylinder brake fluid reservoir, which apparently accounts for the damage to the left side of the engine compartment and the left front fender. Charring of plastic and rubber components increases steadily to the right side of the engine where significant melting of aluminum and light metal components used in the manufacture of the intake manifold and accessory brackets is present. The battery, mounted inside the right side fender, is melted and the lead plates are exposed along its left side and rear. The worst area of burning occurred at the right side of the engine and encompasses a metal bracket, which bolts to the upper right side of the cowl. Components of the power distribution panel are normally attached there.

ORIGIN AREA EXAMINATION:

Components of the power distribution panel are completely destroyed. A cursory examination of wiring between the panel and the alternator mounted to the right front of the engine revealed a number of short, brittle pieces of copper conductors. Arc beading is present on the large gauge conductor that supplies power to the distribution panel from the positive post of the battery. Due to the probability of subrogation, no destructive testing was undertaken.

INVESTIGATION:

██████████ husband of the insured ██████████ stated he arrived home from work at about 5:00 P.M. and had prepared hotdogs for his two, small children. As he was seated at the dining room table he looked out the window and saw his truck on fire. He immediately called the fire department and went outside where he watched his children while some of his neighbors used a garden hose to keep the fire from spreading to his house.

Research of the National Highway Traffic Safety Administration Recall Database revealed no recalls pertaining to a problem of this type but I have recently examined four other Ford F-150 pick-up trucks that exhibit similar burn patterns and, in my opinion, these fires originated in this same area. I have notified Ms. Teresa Sweeney of Farmers Insurance Company, 1-800-944-7515, of the possibility of working with you concerning subrogation against the manufacturer.

DETERMINATION OF ORIGIN AREA AND CAUSE:

Origin area and causal hypotheses were formed using factual and witness information and were tested against all known data. Using my skills, knowledge, education, training and experience, I formed the following hypothesis, which withstood all test.

In my opinion, this fire originated at the right rear of the engine compartment and was most likely caused by a malfunction of the components of the power distribution panel and its related circuitry. I consider this fire to be accidental in nature. In anticipation of subrogation, no destructive examination was undertaken.

At this time I have completed all assigned investigation. Should you desire further investigation or if you have any questions please do not hesitate to call.

L. Gary Coggins, CFI
Automotive Division, Manager
Senior Investigator

Reviewed by:
Richard J. Keith, CFI, CFPO, CFEL, CET
President

VEHICLE EXAMINATION DIAGRAM


ENCLOSURE: 1

INSURED: [REDACTED]

MAKE: FORD MODEL: F-150 Year: 1997

VIN#: 1FTDX172KVE TAG # AND STATE: [REDACTED] AL

① ⑨ ④



NUMBER AND DIRECTION OF PHOTOGRAPHS AREA OF ORIGIN AREA OF EVIDENCE SAMPLE REMOVAL

[illegible]

TYPE OR PRINT IN BLACK INK

ACUC-82 REV. 8-04

PHOTOGRAPH SHEET

INSURED: [REDACTED] NO. 1 OF 27


The front and left side



PHOTOGRAPH SHEET

INSURED: [REDACTED] NO.: 2 OF 27

Left side and rear



PHOTOGRAPH SHEET

INSURED: [REDACTED]

NO. 3 OF 27

Rear and right side



PHOTOGRAPH SHEET

INSURED: [REDACTED] NO.: 4 OF 27

Right side and front



PHOTOGRAPH SHEET

INSURED: [REDACTED] NO. 5 OF 27

Vehicle ID number




PHOTOGRAPH SHEET

INSI RED: [REDACTED]

NO.: 6 OF 27

Manufacturer's data plate



PHOTOGRAPH SHEET

INSERTED:



NO. 2 OF 27

License plate



PHOTOGRAPH SHEET

INSURED: [REDACTED]

NO.: 8 OF 27


Odometer



PHOTOGRAPH SHEET

INSURED: [REDACTED] NO.: 9 OF 27

Fire damage to the front



5/11/64

PHOTOGRAPH SHEET

INSURED: [REDACTED] NO.: 10 OF 27

The burn patterns on the roof



PHOTOGRAPH SHEET

INSURED: [REDACTED] NO. 24 OF 27

The front of the engine



PHOTOGRAPH SHEET

INSURED: [REDACTED]

NO.: 25 OF 27

Right rear of the engine compartment



EOSS-083-LC-16148

PHOTOGRAPH SLIDE

INSURED: [REDACTED]

NO. 26 OF 27

Wiring at the right side of the engine



PHOTOGRAPH SHEET

Apollon 17-1

INSURED: [REDACTED]

NO.: 27 OF 27

Power distribution panel mounted to right side of cowl




01A047768

MICROGRAPH

INDEXED

22

1962



ERG-803-LC-15140

PRODUCED BY FORD

01A04749


MEMORANDUM SHEET

RECEIVED: [REDACTED] 1962-24 67 27

The following information is being furnished to you for your information:



1962-24-LC-10160



Zellner Vehicle Inspection, cms 40 9801

Inspection Date: April 18, 2000
Location: Nik's Junk Yard, N8309 Harwood Rd, Menasha, Wisconsin
In attendance: Cal Phillips - Fire Investigator for the plaintiff
Myself - Norman LaPointe, Ford Motor Co., DAE
Vehicle: This is a 1998 Ranger Supercab, XLT, 4x4, 4.0L V6; a dark gray vehicle.
I have the factory invoice with me - PA21484 is the last portion of that serial number and it does match the VP windshield tag.

Vehicle Walk-Around w/ tape recorder.

Missing Components

Starting at the rear corner of the vehicle there is no pickup box.

All the wheels are off, but two are under the vehicle supporting it by the cross members, not sure if these wheels belong to this vehicle.

Both left and right doors have been removed and are missing. There is no door identification tag, but verified the vehicle by the VIN number on the windshield - airbag position.

The front left wheel assembly and lower suspension is gone.

The right front wheel and tire is missing. There are no wheel spindles remaining on either the left or right sides.

The engine has been removed from the vehicle and is not present. The transmission is gone along w/ the cooler lines. The drive shaft is gone.

The engine compartment hood is gone.

The entire rear suspension is gone.

Removed Components but with the vehicle

Exhaust System

Two exhaust pipe assemblies had been removed and were sitting on three of the tires in the back of the vehicle on the frame.

The exhaust pipe assembly had been removed from the engine and there is some damage at the attachment flange - it is outwards in deformation.

Fuel System

The fuel tank doesn't seem to be damaged in anyway. The fuel sender has been removed from the tank and is inside the passenger compartment. The fuel filter hoses are w/ the tank. There doesn't seem to be any fire or accident damage here just behind the cab. Still mounted on the frame is the fuel vapor canister that has no damage to it.

Fuel Line

Cal, who is here w/ me, has a fuel line from the engine and I am going to break off from the vehicle inspection and take a look at it. Cal has brought the alternator and harness wire that we have already seen at the laboratory and the box that we had shipped it back to him in. The only new things in the box are various warranty books and paper work that comes w/ the vehicle. Some of manuals are scorched. I looked through each one but did not find anything of particular interest.

What remains here in the box is the fuel line that I will take some photographs of. The clip that goes over the garter ring housing seems looser than usual - it slips over and off real easily but the fuel line is together in a very secure mode. I cannot pull it apart by pulling on the two ends.

Looking at the opposite end, what is the pressure damper end, it has a green o-ring that is exposed and it looks in good shape.

I have separated the hex-connector that has a tube with a flare on the inside that connects to the valve. Both mating surfaces are marked 360 degrees - i.e. they were in contact - it is not clear to me in any way that they were leaking.

Looking at the relief valve side, it is seated up on the outside. Again, just to re-emphasize, the O-ring is in good shape, there is no cuts or tears; it is not hard or brittle. The fitting to which the line would hook to does not look cross-threaded or anything like that - it looks in good shape. Likewise, w/ the nut fitting - that is, the mating part of the threads also look good. A flared portion of this seat that is internal looks like it may have been grooved, that it had a good seat. Basically, the parts appear to be unremarkable.

Front Suspension

The upper suspension arms remain for both the left and right sides.

The lower suspension arm to the right hand side is still in place.

The FR lower arm suspension, has the shock absorber still in place, it's mounted to the frame and to the lower arm but the portion of the piston rod that attaches to the lower arm is definitely bent - like this vehicle may have been in an accident and coupled with the damage that I saw on the lower radiator frame, it looks like it may have been in an accident.

Both ball studs on the right hand side to the upper and lower arms are angled to the forward direction, more so for the lower arm.

The stabilizer bar has been removed from the vehicle and it was laying in the backseat.

The LF torsion bar was inside the vehicle.

There is a rusty rotor inside the vehicle - unknown OEM location.

Engine Compartment

Looking at the lower right side of the radiator, it is severely bent up - like something struck it and severely damaged it.

The front right fender has a burn pattern in a V-shape - centered over the wheel. There is no tire here at the inspection site to view. All the plastic components that are normally on the right hand side are missing. There is really not much left.

All that remains basically is the master cylinder and brake booster, which is burned, and a small cooler line and the radiator. The headlights remain. The headlight is burned on the right hand side, burned through the top. The bulb is melted in place. The cables that lead to the light are bare from the fire but a couple of inches back, the cable are still in good shape. The convolute is slightly darkened but it is still in place. Much of the harnesses that survived here have been cut away.

There is a device that is mounted on the right front fender - inboard and it looks like a speed control servo motor, just the housing and internal gearing, the plastic cover is burned away, the harness that goes to it is gone. The unit is corroded from the weather.

I found the ground wire of the battery and it is bare of insulation for roughly six inches but the rest of the insulation is intact for the remaining approximately 18 inches, so the battery cable basically looks pretty good except for the first couple of inches from the battery connection. The harnesses around the battery on the driver's side are charred, some portions of the convolute are missing, and the wires are discolored, they have turned white, but the insulation are still on the wires that run behind the radiator. It looks like the heat got over here, but did not burn the insulation off.

We have a body ground wire that comes out of the main harness that goes atop of the radiator and the ground wire is burned off for about 3 to 4 inches, but where it goes into the take-off, it still has a coating of insulation.

Also in the zone, is a rubber hose that is approximately 20 inches long -- its identity is 3/8" I.D. DF3251. It looks to be a power steering hose. It is in good shape, not damaged at all. The ends of it are rusty but the hose itself is in pristine shape. There is no fire damage to it whatsoever.

Looking down on the left hand side of the engine compartment I also see the steering shaft, its boot is in good shape and not fire damaged.

I found a red cable probably the battery B+ cable, cut, approx. 12" long, it looks in good shape on the insulation. The opposite end of it, however, has been burned and the wires are frayed.

Most of the wiring harness over on the driver's side is basically still intact. The outside covering of the harness has been burned and is charred, but the insulation is still on the wires and I can see the wires and the wires have their insulation and you can identify color.

Looking around the engine compartment, the driver's side, I found what appears to be a vacuum line underneath the booster. The line was not burned -- it is good shape -- but the end of the line has some white fire debris in it -- like the line wasn't connected at some time and it is possible that it's a vacuum line that went to some part over here, but the line has this white melt in it which seems like it shouldn't be there had the line been connected. The end of the line is not fire damaged, looks like it is just cut in a normal manufactured fashion. It's possible the vehicle was just running rough because this vacuum line was not connected -- strictly speculation.

Most of the combustibles below approx. half way of the engine compartment are intact. The fire seems to have centered on the passenger side of the engine and it has taken out the inner fender well plastic -- probably the tire was involved and may have made a hot spot over on that side.

Most of the apron parts are gone on the passenger side. Some of the components seem to be untouched by the fire. The radiator itself has a large gash in it -- just a little bit below the Ford oval on the forward side of the passenger side. It has been damaged from the outside.

The smaller finned cooler & line is for the power steering; the hose is unburned -- looks like you could reuse it.

The inner fender on the passenger side has been burned and melted down in an arc around the normal tire position. The only thing left above the tire on that fender side is the speed control servomechanism and it is completely fire damaged. I cannot read any part numbers remaining on it.

The heater core does not seem to be melted or damaged which is sitting in a pile of rubble on the passenger side of the firewall. Again, behind the firewall on the cabin side the plastic components around the heater core are melted, but they don't seem to be charred. So, it seems like the fire may have been centered in the engine compartment on the right hand side for causes unknown.

Again, I have picked up the positive cable for the battery, and while the insulation is intact and not melted on one end of this roughly 12-14 inch piece, the wires are frayed and separated, but I don't see any beading or shorts. Likewise, I don't see any shorts on the ground cable to the battery, which still has its round steel connector.

The three small cables that lead to the FR lamp are absent of any insulation, but at the takeout point the cable is intact and the convolute is still there, but slightly melted. So, the fire seems to be - as said earlier - in the upper portion of the engine and slightly right of center on the top of the firewall looks like the EEC module remains - it's been melted and burned. It's hard to tell much more than that. Basically the right side of the engine compartment is rusted on the frame, inter-fender, and firewall. There is rusting in the engine compartment on the firewall where the blower motor and the heater core sit and those plastic parts are all basically melted and they flowed downward. The left side still has a lot of black primer paint. The cowl, just in front of the windshield, has been smoked and has paint damage and it looks like the fire came up through the rear edge of the hood, roughly in the middle, then attacked the glass, melted, and broke the glass.

The transfer differential housing for the 4x4 was in place.

Brakes

The master cylinder reservoir is burned away. The plastic that was mounted above it along with the switch is charred but does not seem to have any melting of the aluminum master cylinder itself. The brake lines, to and from, the proportioning valve and the master cylinder still look to be intact, they are secure, and they run down to the frame of the vehicle and across to the other side except where the wheels have been removed and that is where they terminate.

The booster is still in place and it's all rusty and the rubber vacuum plug has been melted.

A single brake caliper was found inside the vehicle, its OEM position is unknown.

Interior Components

Moving to the interior, it is piled with parts. The fuel sender is sitting here - harness no. F87UAA looks in good shape. One hose has been cut from it. The connector has been removed from the other side. The driver steering wheel has been partially taken apart. The air bag module has been removed and is missing from the vehicle. The I/P is in pieces laying all over seats and floors. The odometer from the I/P is at 6133 miles. The I/P fuse panel is hanging free. I/P fuse panel looks like fuses 1, 2, 3 and 4 are in place. No. 6 fuse is missing and No. 12 is missing. No. 23 is missing. No. 36 is missing, so is No. 31 and No. 32 and No. 34.

The key was still in the ignition with the key fob. Much of the interior of the vehicle has been torn out on the instrument panel recovering radios and instrument cluster.

The door panel for the right side is in the vehicle. It looks like the left and right hand bezels from the doors are here - they are in good shape. There doesn't seem to be any fire damage at all, nor is the door liner damaged.

And now at the floor of the passenger side, we have a lot of melted plastic. It is not burned but looks like the fire was breaking into the passenger compartment from the engine side. The plastic is not charred, but simply melted and has run down on the floor at the firewall.

The I/P vents are melted - they show melting - like the heat came through the vents. They are not melted badly, but they are deformed and out of shape. The passenger side airbag has been deployed and has been pushed back into the I/P and I cannot open the glove box to inspect.

The radio and other center IP instrumentation have all been removed. All that is left here are the terminals and harnesses.

The heater controls were out of the IP, but in the vehicle, the three switches are set straight up. The heater control is in the off position. The temperature control knob in the center is set straight up, which is a mix of heating and cooling and the fan switch is turned to the lowest off position - that is full straight up. There is no direct fire damage to IP. The connectors all look good. No fire damage or melting.

The windshield is cracked - just about mid position - but not all the way up.

The instrument panel on the right hand side - just above the airbag - is melted back, away from the window.

The windshield is cracked and it has begun to fall in.

My inspection is concluded.

file/ZetnerVehicleInsp.doc - Microsoft Word

ANALYSIS

Alternator Assembly

The heat deformation present at the top of the alternator housing indicates that the top of the alternator was exposed to higher temperatures than was the bottom. The bus bar was warped out of position during the fire because the plastic insulators used to insulate the rivets connecting the bus bar to the ground portion of the alternator softened in the heat of the fire and allowed the bus bar to be pulled out of position by the weight of the wire connected to the B+ terminal, as well as the weight of the B+ terminal and the bus bar itself. The fact there are distinct marks from the brushes on the inner and outer slip rings indicates that the alternator was not turning during the fire.

The voltage reading of 0.924 Volts that was obtained when checking the ground to B+ side of the circuitry indicates that all of the diodes in the rectifier bridge are functioning properly and that there are no shorts in the stator / rectifier circuitry. The resistance reading of 2.5 Ohms across the inner and outer slip rings indicates that the field coil circuitry is not shorted to housing.

The stator / rectifier circuitry and the field coil or rotor circuitry are electrically in tact. There are no shorts in either of these two circuits, and there is no evidence indicating that either of these two circuits were not operating properly at the time of the fire. Therefore, this alternator is judged to not have been the cause nor origin of this fire.

Alternator Wiring Harness

The short that caused the wire to arc and weld itself to the support bracket was a result of the fire, not the cause nor origin. The wiring harness is judged to have arced and welded itself to the support bracket after the insulation was burned away from this point of the wire by the fire. Once the wire arced and welded to the bracket, current flowing from the battery towards the arc point blew the 175 Amp fuse located in the engine compartment fuse box. This fuse blew, and thus current stopped flowing, before the wire had time to heat up. If the fuse had not blown, current would have heated up the wire uniformly and melted away the insulation on the entire stretch of wire between the fuse box and the arc point. Since the majority of the insulation is still in tact along this stretch of wire, the fuse must have blown, and the wire did not get hot enough to consume the insulation. A short itself could not have caused this fire because the fuse blew before the wire got hot enough to consume the insulation and start a fire.

The insulation on the wire between the arc point and the alternator was consumed by the fire and could not have been melted away from heat generated by current flow because the alternator was not turning during the fire, and thus no current was flowing through this section of wire. All of the damage to this section of wire is due to the fire.


As with the alternator, the wiring harness is judged to not have been the cause nor origin of this fire.

PART / TAG I.D. / SUPPLIER


Alternator assembly / F6PU-10346-LA /

Alternator wiring harness / F6HT-14305-MG /

Concur



N. R. LaPointe
Design Analysis



J. P. Joyce
Design Analysis

AMP/MMB/MAO 00-0215F283


STATE OF WISCONSIN

CIRCUIT COURT
BRANCH 3

WOOD COUNTY


Auburndale, WI

and


Case No. 00-CV-46
Code No. 30301

Plaintiffs,

vs.

FORD MOTOR COMPANY
Parklane Towers West, Suite 300
3 Parklane Boulevard
Dearborn, MI 48126-2568

Defendant.

AFFIDAVIT OF NORMAN LaPOINTE

Your affiant, Norman LaPointe, hereby deposes and states on personal knowledge as follows:

I am a Design Analysis Engineer with Ford Motor Company. A copy of my curriculum vitae is attached and is current and up to date. My education, training and experience, as detailed in the attached curriculum vitae, qualifies me to offer opinions on matters involving vehicle engineering principles as well as the determination of the cause and origin of vehicle fires.

On April 19, 2000, I attended an inspection of the 1998 Ford Ranger at issue in this case. The inspection was also attended by Cal Phillips.

Before the inspection, I reviewed the report authored by Gary Kaufman following his April 17, 1998 inspection. I also reviewed all photographs of the subject vehicle which had been taken to that point.

Available for my inspection were the frame, portions of the body, suspension and fuel system that remained aft of the engine. Also available for inspection were the alternator, a portion of the alternator wiring, and a fuel return line, although they had been previously removed from the vehicle by Gary Kaufman.

Missing from the vehicle at the time of my inspection was the entire engine, the transmission, the drive shaft, the engine compartment hood, portions of the front suspension, the rear suspension, the pick-up box, and both doors.

The seven photographs attached to Ford Motor Company's motion for summary judgment were taken by me at the inspection. The photographs truly and accurately depict the appearance of the vehicle on the date of my inspection.

Based on the facts of this case, it is my opinion to a reasonable degree of engineering certainty that the alternator and associated wiring was not the cause of the vehicle fire. Testing confirmed that the alternator in the vehicle contained no internal defect which caused or contributed to the fire. Additionally, because the vehicle was turned off just prior to the fire, no current was flowing through the wiring alleged by plaintiff to be the cause of the fire. With no current flowing, no heat is generated sufficient to ignite a fire. Had current been flowing from the battery due to the alleged short in the wires, the fuse between the battery and the alternator would have blown, ending any current flow through the alternator wiring alleged by plaintiff to have caused the fire.

Based on the missing engine and other components of the vehicle, as detailed above, I am unable to determine to a reasonable degree of engineering certainty the cause of the vehicle fire.

There is no evidence in this case that there existed a defect in the 1998 Ford Ranger at issue at the time the vehicle left Ford Motor Company's control.

There exist numerous potential causes for a vehicle fire which do not involve any defect which existed at the time the vehicle leaves the control of a manufacturer. Those possible causes include improper maintenance, such as oil changes and vandalism. Both of those potential causes exist in this case.

FURTHER AFFIANT SAYETH NOT.

Norman LaPointe
Norman LaPointe

Dated: 1-26-2001

SUBSCRIBED AND SWORN
to before me this 26th day
of January, 2001.

Francis Mary Klesch
NOTARY PUBLIC

END-000-10-10100

[REDACTED]
and
[REDACTED]

COMPLAINT

Case No. 00CV46


Code No. 30301

Plaintiffs,

vs.

FORD MOTOR COMPANY

Defendant.



Plaintiffs [REDACTED] and Heritage Mutual Insurance Company, by their attorneys, Nash, Podvin, Tuchscheler, Huttenburg, Weymouth & Kryshak, S.C., by Robert V. Kryshak, submit the following as their complaint against the above named defendants herein:

1. Plaintiffs [REDACTED] are adult married residents of Wood County whose residence address is [REDACTED] Auburndale WI [REDACTED]

2. Heritage Mutual Insurance Company is a Wisconsin insurance corporation duly authorized to engage in the sale of automobile and other types of insurance, whose principal place of business is located at 2800 South Taylor Drive, Sheboygan WI 53082.

3. Ford Motor Company is upon information and belief a Michigan corporation whose primary offices are located at Parklane Towers West, Suite 300, Parklane Boulevard, Dearborn MI 48126-2568, and is in the business of producing, manufacturing and distributing motor vehicles for sale to the general public.

4. In January 1998, plaintiffs [REDACTED] purchased a new 1998 Ford Ranger from an authorized Ford dealer. After approximately 6,000 miles of use and without any mechanical or repair work being done to the vehicle in the interim, the vehicle caught fire while parked in said plaintiffs' driveway on April 13, 1998, resulting in its destruction.

5. On the day of the fire involving the aforementioned vehicle, Heritage Mutual Insurance Company had in full force and effect a policy of insurance with [REDACTED] that covered the loss of that vehicle. Said policy of insurance had a \$500.00 comprehensive coverage deductible, and Heritage Mutual Insurance Company paid out a total of \$18,110.00 to plaintiffs [REDACTED] for their loss. Said amount did not include [REDACTED] deductible, and ultimately Heritage Mutual Insurance

Company recovered \$2,881.00 in salvage for the vehicle, resulting in a net payment by Heritage Mutual Insurance Company to the [REDACTED] in the amount of \$15,729.00.

6. Upon information and belief, the fire was caused due to an electrical/mechanical failure that was not caused or occasioned by any act or omission of plaintiffs. Upon information and belief, Ford Motor Company is held responsible for said loss under principals of strict liability and/or their breach of express and implied warranties of merchantability and fitness for which the vehicle was manufactured.

7. Demand has been made upon Ford Motor Company for plaintiffs' loss, with said demand being denied.

WHEREFORE, plaintiffs [REDACTED] demand judgment against Ford Motor Company for their \$500.00 deductible, and Heritage Mutual Insurance Company demands judgment against Ford Motor Company in the amount of \$15,729.00, plus their costs, disbursements, attorney's fees, and such other and further relief as the Court deems just and equitable.

Dated this 15 day of February, 2000.


NASH, PODVIN, TUCHSCHERER,
HUTTENBURG, WEYMOUTH & KRYSHAK, S.C.

By: Robert V. Kryshak

Robert V. Kryshak (1008286)
Attorneys for Plaintiffs
170 Third Street North
P.O. Box 997
Wisconsin Rapids WI 54495-0997
Telephone: (715) 423-8200

SERVED ~~PERSON~~ SUBSTITUTE AT 0805 M
THIS 23 DAY OF February 20 00
AT THE CITY OF MADISON
GARY H. HAMBLIN
BY [Signature]
Deputy Sheriff

EC85-885-LC-18171



Ford Motor Company

Product Development
Ford Motor Company

Parklane Towers West
Suite 408
Three Parklane Boulevard
Dearborn, Michigan 48128
FAX: 313-849-1811

April 10, 2001

VIA AIRBORNE EXPRESS

Anthony M. Pinto, Esq.
Donohue Brown Mathewson & Smyth
140 South Dearborn
Suite 700
Chicago, Illinois 60603

Re: [REDACTED] Ford Motor Company
LMMS No. 40-9801
Your File No. 00-0215

Dear Anthony:

Please find enclosed two photographs and two drawings. These items are what I propose we use at trial.

Very truly yours,

Norm LaPointe /ek

Norm LaPointe
Design Analysis

Enclosure

DONOHUE BROWN MATHEWSON & SMYTH

Attorneys at Law

140 South Dearborn
Suite 700
Chicago, Illinois 60603
FAX (312) 422-0909
Telephone (312) 422-0900

Norman J. Barry, Jr.
Mark H. Boyle
Donald J. Brown, Jr.
Mark M. Burden
John T. Coleman
Karen K. DeGrand
Richard H. Donohue
Richard B. Foster
Maura D. Hathcock
John A. Krivich
J. Kent Mathewson
Robert W. Smyth, Jr.
L. Michael Tarpy

Sherri M. Arrigo
Virginia L. Beach
Eleanor P. Caberé
John J. Duffy
Charles E. Harper, Jr.
Carrie A. Howard
Timothy M. Kennedy
Julia K. Lynch
Anthony M. Pizzo
James D. Sloan

Writer's Direct Line (312) 422-0974
anthony.pinto@dbmlaw.com

Of Counsel
Louis J. Bencini
* Admitted in MD and CA

February 26, 2001

Mr. Norm LaPointe
Ford Motor Company
Parklane Towers West
Suite 604
Three Parklane Boulevard
Dearborn, Michigan 48126

Re: [REDACTED] v. Ford Motor Company
CMS No. 409801
Our File No. 00-0215

Dear Norm:

Enclosed for your review please find four exemplar vehicle photographs provided by plaintiff's expert, Mr. Philips.

Very truly yours,



Anthony M. Pinto


AMP/skw A170.amp

12-1 CHARGING SYSTEM

1995 RANGER

For diagnostic information, refer to Section 414-00 of the Workshop Manual.

With voltage applied, regulator is activated, allowing current to flow from sense A circuit to generator field coil. Generates an AC output which is converted to a DC output by a rectifier assembly internal to generator, and is supplied to vehicle through the B+ terminal. S (sense) circuit is used to feed back a voltage signal from generator to regulator. This voltage (typically half battery voltage), is used by regulator to turn off indicator.




12-1 CHARGING SYSTEM

1980 RANGER


For diagnostic information, refer to Section 414-00 of the Workshop Manual.

With voltage applied, regulator is activated, allowing current to flow from sense A circuit to generator field coil. Generates an AC output which is converted to a DC output by a rectifier assembly internal to generator, and is supplied to vehicle through the B+ terminal. S (stator) circuit is used to feed back a voltage signal from generator to regulator. This voltage (typically half battery voltage), is used by regulator to turn off indicator.





8205-005-LC-10177



NASH, PODVIN, TUCHSCHERER,
HUTTENBURG, WEYMOUTH & KRYSHAK, S.C.

LAWRENCE A. NASH
FRANCIS J. PODVIN
H. JAMES TUCHSCHERER
JEFFREY L. HUTTENBURG
RICHARD D. WEYMOUTH
ROBERT V. KRYSHAK
R. JOHN SYMONES
AMY J. SOETTCHE

LAWYERS
LIMITED LIABILITY ORGANIZATION
170 THIRD STREET NORTH
P.O. BOX 997
WISCONSIN RAPIDS WI 54495-0997

TELEPHONE (615) 434-0000
FACSIMILE (615) 434-0000

DIRECT E-MAIL
R.Kryshak
R.Nash@podvinlaw.com

January 25, 2001

Mr. Anthony M. Pinto
Donoghue, Brown, Mathewson & Smyth
1140 South Dearborn
Suite 700
Chicago IL 60603

FEB 6 2001
60603
Ampl/mb/pino

RE: [REDACTED] vs. Ford Motor Company
Your File No. 00-0215

Dear Mr. Pinto:

Enclosed is a copy of Mr. Cal Phillips' file.

Yours very truly,

NASH, PODVIN, TUCHSCHERER,
HUTTENBURG, WEYMOUTH & KRYSHAK, S.C.

By:

Robert V. Kryshak
Robert V. Kryshak

BH
enclosures

cc: Mr. Kelly C. Cavanaugh; Claim No. H54124 (letter only)
Mr. Jeffrey T. DeMeuse (letter only)
Mr. Cal Phillips (returning originals)

S:\data\DOCS\H\HMC\COL-zellner L-Pinto.1.wpd

ER95-005-LC-10179

Owner
1998 Ford Ranger
VIN 1FTZR15X7WF
Claim Number
Date Of Loss: April 13, 1998

CAL's Photograph List

1. Front of vehicle - Notice missing parts.
2. Passenger side - Vehicle stripped of parts.
3. Passenger side - Note flame pattern from top down on fender.
4. Passenger side - Photo shows interior and lack of fire damage.
5. Driver's side - Photo shows parts missing and lack of interior damage.
6. Driver's side - Note lack of fire damage on fender - fire spread towards passenger side.
7. Driver's side - Note lack of fire damage in the interior.
8. Rear of vehicle - Note box gone as well as rear axle and other parts dismantled
- 9, 10, 11 & 12. Engine compartment - These four photos show the engine compartment. Note engine missing. Damage at the fire wall high up. Fire in all photos indicates high burning. No low burning. The radiator still intact. This also indicates fire at high level.

Please review

27 April 2000

Attorney Robert Kryshak
Nash, Podniz, Tuchocher, Huttenberg, Weymouth & Kryshak
PO Box 997
Wisconsin Rapids, WI 54495-0997

Re: Vehicle Fire
1998 Ford Ranger
VIN: 1F1ZR15X7W
Date of Loss: 13 April 1998
Owner & Insured:
Heritage Insurance
Claim No:
Date of Investigation: 17 April 1998
Investigation originally conducted by: Gary Kaufmann of Cal Philipps & Associates

Basic Information

I met Ford Motor Company's expert, Mr. Norman LaPoint, on 19 April 2000 at Nik's Auto Salvage in Sherwood, Wisconsin. Mr. LaPoint & I were both present during the entire course of the joint examination of the remains of the vehicle.

It is important to note that the at some time after the fire incident and prior to our examination on 19 April 2000, the remains of the vehicle had been hauled to Nik's Auto Salvage and, in the process, received some damage. In addition, the remains of the vehicle had been stripped. At the time of the 19 April 2000 examination, the following includes some of the items missing from the vehicle were: the entire engine and it's components, the engine hood, doors, axles, wheels, tires and rear truck box.

I examined the full remains of the vehicle and photographed fire patterns that were present on the remains.

Conclusions

Based on the data obtained through the examination process, in my opinion, the fire patterns on the remains of the vehicle support the opinions developed from the original investigation conducted by Investigator Gary Kaufmann pertaining to the causation of the vehicle fire. As Investigator Kaufmann states in his report, in his opinion, the point of fire origin was at the alternator, which was located toward the passenger side of the engine compartment. In Investigator Kaufmann's opinion, the heat source of the fire was the main electrical conductor from the alternator.

page 2

A complete set of the photographs taken during the course of the 19 April 2000 examination are included.

Thank you for the opportunity to be of service to you. Should there be further questions, please call.

Sincerely,

Cal Philipps
Certified Fire Investigator - Consultant

Enclosures:

- One Set Examination Photographs
- Statement for Services to date

ER05-085-LC-10182



HERITAGE COMPANIES

Heritage Mutual Insurance Company
Grassmy Insurance Company
Heritage Financial Corporation

Claims Office • 2801 Robin Lane • PO Box 945 • Wausau WI 54402-0945

(715) 848-8200

October 1, 1998

Ford Motor Company
Office of the General Counsel
Parklane Towers West, Suite 400
3 Parklane Boulevard
Dearborn, MI 48126-2568

Attention: Nadine Grabowski

RE: Our Insured: [REDACTED]

Our Claim No. [REDACTED]

Date of Loss: 04-13-98

Thank you for your letter of August 18, 1998 acknowledging receipt of our subrogation claim. Enclosed with this letter is an Expert's report done by Cal Phillipps & Associates, Inc., along with the photographs taken by them on April 17, 1998. The vehicle involved was a 1998 Ford Ranger Extended Cab 4X4, VIN 1FTZR15X7W[REDACTED]. We have also included the Total Loss Evaluation sheet regarding the damage to this vehicle, as well as copies of the draft payment. We do not have the complete service history for the vehicle involved, including any tune-ups or oil changes. We do know, however, that the vehicle only had 6,000 miles on it when this incident happened. The parts that you may need to inspect are in storage at Cal Phillipps & Associates in Oshkosh, Wisconsin. You may contact Gary Kaufmann at 920-233-4001 to see these parts. The vehicle itself is located at Nik's Auto Sales at N966 Quality Drive in Greenville, Wisconsin 54912. The person you would need to speak with is Scott at 920-836-2036.

I hope this provides you with the information you need to do your investigation. I apologize for the length of time it has taken me to get you this information.

Thank you for your cooperation in this matter, and certainly feel free to contact me should you have any further questions or need any further information.

Sincerely,

Michelle K. Schoepke

Michelle Klaus-Schoepke
Field Claims Representative
Wausau District Office

MKS/av
Enclosures

EA05-005-LC-18191

**CAL PHILLIPPS & ASSOCIATES, INC.**

322 Court Street

Oshkosh, Wisconsin 54901

Phone: (920) 233-4001 • Fax: (920) 233-4126

Cal Phillipps • Rick Reilen

24 June 1998

Ms. Michelle Schoepke
Heritage Mutual Insurance
PO Box 846
Wausau, WI 54402

Re: Vehicle Fire
1998 Ford Ranger
VIN: 1FTZR15X7W [REDACTED]
Date of Loss: 13 April 1998
Owner & Insured [REDACTED]
Heritage Mutual Insurance
Claim No. [REDACTED]
Date of Investigation: 17 April 1998

The following is the report of my investigation of the above referenced fire.

BASIC INFORMATION

I was assigned to this case after our office received a telephone call from Ms. Michelle Schoepke of Heritage Mutual Insurance, who requested that an investigation be conducted to determine the causation of the above referenced fire. Ms. Schoepke provided information pertaining to the loss. The vehicle was located at the home of the insured in Auburndale, Wisconsin.

On 17 April I drove to 6106 Railroad Drive in Auburndale and spoke with the insured, [REDACTED] stated the vehicle was purchased from a local dealership near Thanksgiving of 1997. At a later date, [REDACTED] heard on the radio there was a recall on Ford trucks and took the vehicle to the same dealership, where he was informed that there was not a recall on this truck model.

[REDACTED] said there was about 6000 miles on the odometer at the time of the fire. The day of the fire, approximately 70 miles were driven during the course of running errands. [REDACTED] knew the mileage driven as he had just put gas in the truck and had returned the trip odometer to zero. Upon returning home, the truck was parked in the garage.

According to [REDACTED] the truck was running sluggish on 13 April. He also was not able to get the transmission into fifth gear. He telephoned the dealer and scheduled an appointment with the service department for the next day. [REDACTED] decided to park the

page 2

truck in the driveway overnight rather than leave it in the garage. He stated he saw some fluid, which smelled like gasoline, on the ground under the passenger side of the vehicle. [REDACTED] proceeded to open the engine hood and look on the passenger side of the engine for the cause of the leakage. Not finding the source of the leak, he returned indoors. At approximately 1445 hours while watching television, his young daughter went to get a drink of water. Using a chair to reach the faucet and being able to see out the kitchen window, she told [REDACTED] that there was smoke coming out of the truck. Finding the vehicle on fire, [REDACTED] notified the fire department. The Auburndale Fire Department's report notes the time of the call at 1452 hours.

[REDACTED] informed me that his house and garage had been the subjects for obscene language graffiti applied by person or persons unknown. During the course of my conversation with [REDACTED] he was very emotional in regards to the fire incident with the truck. It was the first new vehicle he had ever owned, and he had saved a long time to make the purchase. [REDACTED] stated he was very careful with the truck; he did not allow anyone else to drive it. He would also lift and place his young children into the seats so they would not accidentally scratch the rocker panels.

Following my investigation, a search was made of the National Highway Transportation Safety Administration Office of Defects Investigation Recall Database for information pertaining to late model Ford Rangers with a 4.0 liter engine. Two recall notices were found. Both of the recalls were on account of non-metallic fuel lines being too close to the exhaust manifold. The fuel lines involved were on the driver's side portion of the engine and did not pertain to this fire incident as the fire clearly originated on the passenger side of the engine compartment in an area not associated with the fuel lines.

INVESTIGATION **EXTERIOR**

The exterior of the vehicle was examined and photographed. It was readily apparent the majority of the fire damage was in the engine compartment. The engine hood was severely physically damaged as a consequence of the fire department's activities to access the engine compartment. The hood was not attached to the vehicle at the time of my investigation.

The front passenger side fender contained a large burn pattern and the front passenger side tire was found deflated. The windshield was cracked on the passenger side. A few small burn patterns were noted on the driver's side front fender. See photographs 1 - 4.

The engine hood, which was being stored in the truck bed, was returned to its original position. The burn patterns on the hood indicated the fire was most intense on the passenger side of the engine compartment.

page 3

Fluid samples were not taken from the ground below the vehicle as the truck was not in the position it was at the time of the fire, and rain had fallen since the incident. Examination of the damage on the underside of the truck indicated that the fire traveled to this area from the engine compartment.

INTERIOR

The interior of the vehicle was examined and photographed. The most severe damage was on the passenger side. The fire had caused the inflation of the passenger side air bag device as it began to make entry into the glove compartment. See photograph 5.

The cigarette lighter was in place. The temperature control was set at "warm" for the defroster and floor areas. The fan was on the first setting. See photograph 6. The panel containing the odometer, speedometer and other gauges had been removed by the fire department during overhaul operations.

The fuse panel was located and the following fuses were found "tripped:" 13 (brake pedal position switch), 17 (cigarette lighter), 18 (driver's side door lock relay), 22 (auxiliary power socket) and 35 (RABS test connector). All fuses were of the proper size. See photograph 7. [REDACTED] also indicated he had not experienced any problems with fuses since owning the vehicle.

The engine compartment was examined. The fuel lines and connections to the engine, located on the driver's side portion of the engine, were intact. The lines came up to the top of the engine and across to the fuel injector. The fuel lines were retained as evidence and are in the possession of Cal Phillipps & Associates, Inc. for further examination/evaluation at your discretion. See Evidence Tag & Form.

The most severe fire damage was found at the front passenger side of the engine compartment. The damage to the engine in this area extended from the front to the fire wall. The heater core was located next to the fire wall - see photograph 10. Electrical conductors transversing or passing through the fire wall of the vehicle were examined. There was no evidence of any unusual electrical activity or malfunction found.

Located in the area of most damage were the air filter assembly and the engine coolant reservoir adjacent to the windshield wash reservoir. All of these components were made from plastic. Connections were made with either rubber or plastic hoses. The wheel well was also comprised of a plastic material. Most of these combustibles were either consumed or heavily damaged in the fire.

The starter, alternator and air conditioning unit were intact. A visual examination of the starter indicated the fire did not originate at the device. The air conditioning unit sustained damage from exterior fire damage and was not associated with the fire origin. The main electrical conductor from the alternator to the variable electrical assembly had

page 4

fused to a metal support bracket on top of the alternator - see photograph 14. Evidence of unusual electrical activity was also found on the copper strands of the same conductor. The alternator and associated conductors were removed from the vehicle, retained as evidence and is in the possession of Cal Phillippe & Associates, Inc. for further examination/evaluation at your discretion. See Evidence Tag & Form.

In photograph 15 the location of the alternator and its main electrical conductor in the engine compartment is seen. Photographs 16 and 17 display the engine hood damage in relation to the location of the alternator.

After my investigation, a vehicle of similar make and vintage was examined at a local dealership in Oshkosh. The main electrical conductor from the alternator, sheathed in a corrugated plastic loom, ran across the top of the unit and was secured to a metal bracket with a plastic fastener as it continued its route to the battery control unit. See photographs 19-21.

In speaking with a mechanic of this dealership, this main conductor from the alternator would be energized at all times, even when the engine was not operating.

In our office and with an ordinary cigarette lighter, a flammability test was conducted on the insulation of the conductors of the alternator. The insulation was self extinguishing, however, the corrugated plastic loom material in which the conductor was sheathed, was very flammable and burned easily with a minimal amount of heat application.

It was evident in examining the dealership vehicle, a good portion of engine components on the passenger side were made of combustible materials. All of these components in [redacted] vehicle were destroyed in the fire.

As a result of my examination of the vehicle, the evidence found and the information received, the following are my opinions as to the causation of the above referenced fire.

POINT OF ORIGIN

In my opinion, the point of origin was at the alternator in the engine compartment where the main electrical conductor was fused to the metal support bracket. There were no other points or areas of fire origin found within the vehicle.

HEAT SOURCE

In my opinion, the heat source of the fire was the failure of the main electrical conductor from the alternator. The heat source is determined by the process of elimination, either by its examination or by its absence at the origin of the fire. In this case, there were no other possible heat sources present at the point of fire origin. The fusing of the alternator conductor to the metal bracket and the evidence of unusual electrical activity on the

page 5

copper strands of the conductor clearly support the conductor being the heat source of this fire.

CATEGORY

In my opinion, this was an accidental fire. At the time of my investigation, I did not find any evidence indicating an incendiary arson fire.

Thank you for the opportunity to be of service to you. Should there be further questions, please do not hesitate to call.

Sincerely,

Gary N. Kaufmann

Gary N. Kaufmann
Fire Investigator

Enclosures:

- 22 Numbered & Identified Investigation Photographs
- Corresponding Photograph List
- Additional Investigation Photographs
- Evidence Tags & Form
- Statement for Services.

ENC-003-LC-10195



CAL PHILLIPPS & ASSOCIATES, INC.

322 Court Street

Oshkosh, Wisconsin 54901

Phone: (920) 233-4001 • Fax: (920) 233-4126

Cal Phillipps • Rich Relien

Vehicle Fire

1998 Ford Ranger

VIN: 1FTZR15X7W [REDACTED]

Date of Loss: 13 April 1998

Fire Department Dispatch Time: 1452 Hours

Insured: [REDACTED]

Heritage Mutual Insurance

Claim No: [REDACTED]

Date of Investigation: 17 April 1998



CAL PHILLIPPS & ASSOCIATES, INC.

322 Court Street

Oshkosh, Wisconsin 54901

Phone: (920) 233-4001 • Fax: (920) 233-4126

Cal Phillipps • Rich Relian

24 June 1998

Ms. Michelle Schoepke
Heritage Mutual Insurance
PO Box 846
Wausau, WI 54402

Re: Vehicle Fire
1998 Ford Ranger
VIN: 1FTZR15X7W [REDACTED]
Date of Loss: 13 April 1998
Owner & Insured [REDACTED]
Heritage Mutual Insurance
Claim No. [REDACTED]
Date of Investigation: 17 April 1998

PHOTOGRAPH LIST

Number

1. The front of the vehicle. The engine hood had been physically damaged and removed by the fire department to access the engine compartment. At the time of my investigation, the hood was in the bed of the truck and I returned it to its original position for reconstruction purposes.
2. The driver's side of the vehicle. A small burn pattern is seen on top of the front fender.
3. The rear of the truck which did not sustain any fire damage.
4. The front passenger side of the vehicle. The corresponding front tire was found deflated, as shown in photograph 13. Note the large burn pattern on the top of the fender.
5. A view of the interior passenger side of the truck. Note the crack in the windshield and the air bag, which activated when the fire began to access the glove compartment from the engine. The dashboard underwent some warping due to the heat exposure, but note that the fire did not make headway into the passenger compartment of the vehicle.
6. The middle console portion of the interior. Note the lack of fire damage to the area.

7. The fuse panel of the vehicle. All fuses were intact, however, several had "tripped." All fuses were of the proper size.
8. The camera is at the front driver's side of the vehicle and aimed into the engine compartment. Note the minor amount of fire damage on the top of the fender. While damaged from products of combustion, combustible materials remain on the driver's side portion of the engine.
9. The camera is at the front passenger side of the vehicle and is aimed into the engine compartment. Note the absence of the plastic engine coolant reservoir, windshield wash reservoir and other combustible materials in this portion of the engine.
10. The wiring harness as it enters the fire wall of the vehicle. The conductors seen in the photograph were examined. No indications of internal heating or malfunction were found and the conductors of the wiring harness were eliminated as the heat source of the fire.
11. The camera is at the passenger side near the front of the vehicle and is aimed at the front portion of the engine compartment. The air conditioning unit and alternator are seen in the photograph above the red arrow. The damage to the hose below the alternator, see the arrow, indicates the fire attacked the hose at its top surfaces.
12. The arrow marks the valve to the fuel injection system and to which was attached a fuel line. All components of the system and fuel lines were intact.
13. An underside view of the vehicle and the front passenger side tire. The lack of fire damage to the underside indicates the fire originated above in the engine compartment.
14. A view of the alternator's main conductor that was found fused to a metal bracket - see the arrow.
15. A general view of the engine compartment. The arrow marks the fused alternator conductor to the metal bracket.
16. The engine hood has been returned to position. The arrow marks the most severe heat pattern on the hood surface, which is in direct relationship to the location of the alternator.
17. The camera is on top of the truck and is aimed down at the engine hood. Note the heat patterns on the exterior hood surface which correspond to the location of the alternator.
18. The alternator and associated conductors have now been removed from the vehicle and retained as evidence. See enclosed Evidence Tag and Form

19. - 21. General photographs of the location of the main electrical conductor alternator in a 1998 Ford Ranger of similar make. The conductor, sheathed in the corrugated plastic loom, crosses over the alternator and is secured to the metal bracket with a plastic fastener - see the arrows. Note the large amount of combustible materials in the engine compartment, which contributed to the severity of the damage to [REDACTED] Ranger.



HERITAGE INSURANCE

Heritage Mutual Insurance Company - Sheboygan, Wisconsin 53081

PHOTO INVESTIGATION

Claims Representative: 1003 Claim Number: 1001 Insured: 1001



Description: 1001E

Distance-lens to object: _____ Direction taken: _____ Flashbulb: _____

Date: _____ Time: _____ Weather: _____



Description: AC 14

Distance-lens to object: _____ Direction taken: _____ Flashbulb: _____

Date: _____ Time: _____ Weather: _____



HERITAGE INSURANCE

Heritage Mutual Insurance Company - Sheboygan, Wisconsin 53081

PHOTO INVESTIGATION

Claims

Representative: 663

Claim Number: 111111

Insured: 111111



Description: 3 of 18

Distance-lens to object: _____

Direction taken: _____

Flashbulb: _____

Date: _____

Time: _____

Weather: _____



Description: 4 of 18

Distance-lens to object: _____

Direction taken: _____

Flashbulb: _____

Date: _____

Time: _____

Weather: _____



HERITAGE INSURANCE

Heritage Mutual Insurance Company - Sheboygan, Wisconsin 53081

PHOTO INVESTIGATION

Claims

Representative:

Claim Number:

Insured:



Description:

Sc 19

Distance-lens to object:

Direction taken:

Flashbulb:

Date:

Time:

Weather:



Description:

Sc 19

Distance-lens to object:

Direction taken:

Flashbulb:

Date:

Time:

Weather:

2003-003-LC-10203



HERITAGE INSURANCE

Heritage Mutual Insurance Company • Sheboygan, Wisconsin 53081

PHOTO INVESTIGATION

Claims

Representative: 1113

Claim Number: 1571113

Insured: _____



Description: _____

1/21/18

Distance-lens to object: _____

Direction taken: _____

Flashbulb: _____

Date: _____

Time: _____

Weather: _____



Description: _____

1/21/18

Distance-lens to object: _____

Direction taken: _____

Flashbulb: _____

Date: _____

Time: _____

Weather: _____



HERITAGE INSURANCE
Heritage Mutual Insurance Company • Sheboygan, Wisconsin 53081

PHOTO INVESTIGATION

Claims
Representative:

1111

Claim Number:

1111

Insured:

1111



70612

2005-002-10-10000


C-00(5-08)

PRODUCED BY FORD

11/1/87

INVESTIGATION

Claims
Representative:



11/1/87

11/1/87

DNV-005-LC-10208

11/11/11

INVESTIGATION

Claims
Representative:

[Empty rectangular box for description]

Description:



130115
DMS-805-LC-10207

10011 - 2

INVESTIGATION

Claims
Representative:

DESCRIPTION: _____

Distance-lens to object: _____ Direction taken: _____ Flashbulb: _____

Date: _____ Time: _____ Weather: _____




ENCLOSURE

11/11 - 2

INVESTIGATION

Claims
Representative:



PROD-665-A-C-10200