



**FARMERS**

Baltimore Subrogation Center of Excellence

P.O. Box 4478


Timonian, MD 21094-4478

Bus number: 800-944-7511

Fax number: 410-261-7300

November 6, 2002

Ford Motor Company  
Attention: Shawn Norton  
Parklane Towers West  
Suite 300  
Three Parklane Blvd.  
Dearborn, MI 48126



Re: Our Claim #: [REDACTED]  
Our Insured:  
Date of loss:  
VIN:

1J0601

1ftz0723wld [REDACTED]

Dear Ms Norton:

We are the insurance carriers for Bruce Luster. On January 6, 2001, [REDACTED] 1998 Ford XL 150 Pick-Up was damaged by a fire. An independent C&O report requested by Farmers Insurance Group concluded the fire was the result of a mechanical failure in the fuel system. (See attached report). We are now making a subrogation claim against Ford as the manufacturer of the truck. Please review the enclosed materials and advise of your decision on liability at your earliest convenience.

Please call me with any questions or concerns.

Sincerely,

Timothy J. Byrne  
Extension 7337  
Claim Representative  
Farmers Insurance Exchange

1/6/01  
VW  
198 F-150  
11.4.201  
EXP

Farmers Insurance Exchange

Mid Century Insurance Company

Truck Insurance Exchange

Farmers New World Life Insurance Company

Fire Insurance Exchange

Farmers Group, Inc.

EN85-885-LC1-8431

Claim No.: [REDACTED]

D.O.L.: January 7, 2001

Report for:

**Mr. Gregg Frizzell**

· Farmers Insurance Group



*Clarence M. KELLEY and Associates, Inc.*

3217 Broadway, Fourth Floor

Kansas City, Missouri 64111

816.756.2458

Tom Behrendsen, Dir. Fire Investigations, ext. 335

January 24, 2001

Case #: 17070-85E

**CONFIDENTIAL**

## TABLE OF CONTENTS

PREDICATION .....	1
FIRE SCENE INVESTIGATION.....	2
CONCLUSION.....	5
ADDENDA.....	6

PREDICATION

On January 17, 2001, Mr. Gregg Frizzell, Farmers Insurance Group, Moore, Oklahoma, requested an origin and cause investigation be conducted on a 1998 Ford XL 150 pickup. Mr. Frizzell further related the date of loss being January 7, 2001, insured [REDACTED] [REDACTED] Oklahoma City, Oklahoma, and the vehicle currently located at I-35 Salvage Pool #716696.

Mr. Frizzell further stated the insured was driving the vehicle when he saw sparks and smoke coming from around the vents.

CONFIDENTIAL

- 1 -

ERG5-885-LC1-8434

### FIRE SCENE INVESTIGATION

On January 18, 2001, a fire scene origin and cause investigation was conducted on the 1998 Ford XL 150 pickup. The vehicle was located in the I-35 Insurance Pool facing in a westerly direction amidst a row of other vehicles.

Upon examination of the vehicle beginning with the left front, it was observed that the left front of the vehicle showed some damage where the hood had been bent out of shape due to suppression efforts. Also, the back of the hood had burned away. The windshield and side glass had also burned away and/or were missing.

Proceeding down the driver's side, severe fire damage was noted to the driver's side door, this being from the bottom of the door to the top. Damage subsided somewhat at the rear of the door. No fire damage was observed on the left rear panel of the vehicle, nor to the rear of the vehicle.

Upon examination of the bed of the vehicle, slight fire damage was located directly behind the cab. The rear window of the vehicle was missing and the glass had melted and burned out. Also, damage to the top of the cab to the rear was observed.

Proceeding around to the passenger's side, no fire damage was noted to the right rear panel. Proceeding up to the passenger's side door, burning was observed at a higher level than previously observed on the driver's side. Glass was also missing from this door.

CONFIDENTIAL

Proceeding on to the right front fender, no fire damage was displayed with the exception of some light smoke damage.

Examination of the interior revealed all combustibles had burned up.

Examination of the wiring showed shorting in the area above the steering column on the driver's side of the dash. Some slight shorting was noted where the cable spread across to the passenger's side.

The seats were burned out of the vehicle and no combustibles were observed in the interior.

Upon examination of the engine compartment, it appeared that fluids were in the normal operating range with the exception of the engine oil as the dip stick handle had burned off making it impossible to check.

Observation of the engine compartment revealed very little burning at the front. Most of the burning was confined to the rear area near the firewall. Closer examination of this area, just slightly left of center being closer to the driver's side, showed severe burning at the rear of the engine and the firewall level. This burning proceeded down towards the lower portion of the engine. This was an area where the fuel lines came across. An area was also observed on the driver's side where the fire had entered the cab area from the engine compartment. This was through an area where the firewall had been breached for

CONFIDENTIAL

the purpose of wiring. It was observed that the fire had actually entered the cab area from the driver's side at a low level under the dash. Some shorting of the wiring in this area was observed. However, this shorting is believed to be from exposure to the fire itself.

All indications show that a fuel leak had occurred at the rear of the engine. This, in turn, caused the burning to the firewall. The fire then proceeded to enter the cab area, which had been breached at the lower portion of the firewall near the driver's side.

CONFIDENTIAL

- 4 -

ERSS-005-LC1-0437



### CONCLUSION

It is the professional opinion of this investigator through facts and indicators established at the scene that this fire was of an accidental nature due to mechanical failure of the fuel system.

All indications show this to have been a fuel leak, which spread up on the firewall in the engine compartment then igniting, thus, spreading into the cab of the vehicle. Further indications show that this vehicle was more than likely in motion when this fire occurred.

CONFIDENTIAL

### ADDENDA

Note: It was discovered that some 1997-1998 F-150 had a recall notice of fuel line failure in the engine compartment. This investigator would advise further investigation on verifying the VIN and questioning the owner on any recall notice, for possible subrogation possibilities.

CONFIDENTIAL

- 6 -

EN05-003-LC1-0420





Liberty Mutual Fire Insurance Company  
P.O. Box 15041  
3 Lear Jet Ln  
Albany NY 12212-5041  
Tel: (518) 782-2541 / (800) 252-5730  
Fax: (518) 782-2556

April 18, 2000

FORD MOTOR COMPANY  
PARKLANE TOWERS W 1 PARKLANE BLVD #400  
DEARBORN MI 48126

ATTN: OFFICE OF GENERAL COUNSEL

INSURED: [REDACTED]  
CLAIMANT: [REDACTED]  
DATE OF LOSS: 02/26/2000  
CLAIM NUMBER: [REDACTED]

Dear SIRs:-

THIS LETTER IS TO PUT YOU ON NOTICE OF A POSSIBLE CLAIM AGAINST YOUR COMPANY. OUR POLICYHOLDER'S NAME IS [REDACTED] MONTGOMERY, NY [REDACTED] HIS 1998 FORD EXPEDITION, SERIAL # 1PMRU1FWXW1 [REDACTED] WAS CAUGHT ON FIRE WHILE HE WAS DRIVING IT ON FEBRUARY 26, 2000.

THE VEHICLE IS BEING HELD AT AUTO PLACEMENT CENTER WHICH IS A SALVAGE YARD LOCATED AT 39 STONE CASTLE RD ROCKTAVERN, NY 12575. THE TELEPHONE IS 914-367-6366 AND PLEASE REFER TO STOCK #P4920. THE VEHICLE WILL BE AVAILABLE FOR YOUR INSPECTION UNTIL JUNE 18, 2000. IT WILL BE DISPOSED OF AFTER THAT.

THANK YOU FOR YOUR ATTENTION TO THIS MATTER.

Sincerely,  
NORRENE WINKLER *Norrene Winkler*  
Claims Department  
Ext. 335



Helping People Live Safer, More Secure Lives

PERFILM

FORM-805-LC1-0448



FIRE AND EXPLOSION ANALYSIS - ANALYTICAL LABORATORY  
INVESTIGATIVE ENGINEERING SERVICES

## PETER VALLAS ASSOCIATES Inc.

A Professional Corporation

Internet: <http://www.petervallas.com>

Email: [experts@petervallas.com](mailto:experts@petervallas.com)

★ Corporate Headquarters

705 Main Street  
Hackensack, NJ 07601  
(201) 487-8801  
Fax: 201-487-1253

Date of Report: May 5, 2000

Total pages: 22

★ Northern Regional Office

108 Washington Avenue  
Endicott, NY 13760  
(807) 785-8252  
Fax: 807-785-8541

Ms. Betty Brunell  
LIBERTY MUTUAL INSURANCE COMPANY  
P.O. Box 15041  
Albany, New York 12212-5041

Fax Number:

★ Eastern Regional Office

100 Mill Plain Road  
Danbury, CT 06811  
(203) 751-0100  
Fax: 203-751-0200

☐ VIA MAIL AND FACSIMILE (\_\_\_\_ PAGES)

File: 001254  
Re: [REDACTED]  
Pol/CF: 631791-01  
D/L: 2/26/00

★ Northeast Regional Office

180 North Main Street  
Wassenaar, NY 14538  
(716) 788-0980

Prepared by: David R. Redsicker  
Corporate Director of Investigations

★ Laboratory Facility

86 Zabriskie Street  
Hackensack, NJ 07601  
(201) 487-0288

PETER VALLAS ASSOCIATES Inc. reserves the right to amend and/or supplement this report in the event additional information, documentation or evidence becomes available.

★ Pennsylvania Regional Office

Pennsylvania Avenue  
Philadelphia, PA 19130  
(215) 854-2488

THIS REPORT FURNISHED AS PRIVILEGED AND CONFIDENTIAL TO ADDRESSEE. RELEASE TO ANY OTHER COMPANY, CONCERN OR INDIVIDUAL IS SOLELY THE RESPONSIBILITY OF ADDRESSEE.

• National Fire Protection Association • National Association of Fire Investigators • International Association of Arson Investigators  
• New Jersey Chapter IAIF • New York Chapter IAIF • International Association of Fire Investigators and Fire Scientists • American Chemical Society  
• ASAC, OSHA and OSHA Regional Office • International Association of Fire Investigators • Fire Protection Association  
• International Association of Fire Investigators • International Association of Fire Investigators

ENC5-005-LC1-0441

# **PETER VALLAS ASSOCIATES Inc.**

Page 1  
001254

## **PURPOSE OF THE ASSIGNMENT**

In accordance with your request, this organization conducted an inspection of the insured's vehicle in reference to the cause of the fire. The assignment also includes the issuance of a written report based on our analysis.

## **PRELIMINARY REMARKS**

An inspection was conducted on Wednesday, April 19, 2006 at Co-Part Salvage in Rock Tavern, New York.

## **DESCRIPTION OF THE VEHICLE**

The vehicle is a 1998 Ford Expedition 4 X 4 SUV, color green. The vehicle identification number is 1FMRU18WXLW1. The salvage yard stock number was P4920. It was located in row [REDACTED]

## **INSPECTION OBSERVATIONS**

The vehicle shows extensive fire damage in the front engine compartment area extending horizontally and vertically to the passenger compartment by the windshield and dashboard area. Fire patterns extend to and through the back storage area of the vehicle.

Inspection of the underside of the vehicle revealed no evidence of fire originating from or extending to this area. The fuel filler cap was intact in the left rear quarter panel of the vehicle.

Closer inspection of the passenger compartment area revealed extensive fire damage in the dashboard area. However, the wiring harness extending through the left side of the fire wall was intact and the damage at the fuse panel was due to external heat and flame impingement. There was no evidence of a key found in the debris on the floor under the steering column. The stereo was intact.

Inspection of the engine compartment revealed the aluminum hood was extensively melted by the fire. The top of the radiator and cooling coil for the air conditioning unit were melted. The transmission cooling lines were intact on the left side of the radiator. The lines between the coils and the compressor for the air conditioning unit were still intact.

The brake master cylinder and brake fluid reservoir were melted down due to heat flame impingement. The ABS system and lines were intact.

Inspection of the fuel lines entering the engine compartment from the left rear corner revealed the connectors were still intact. The throttle body showed evidence of extensive melt down on the front. The alternator was intact. The battery cable between the alternator

## PETER VALLAS ASSOCIATES Inc.

Page 2  
001254

and battery was intact, however, the battery post was melted. Further inspection of the battery cables revealed the ground cable was intact. It was noted, however, that one of the positive cables between the battery and the fuse panel had arced through at the right rear of the engine compartment.

### OTHER RELEVANT INFORMATION

Follow-up with the National Highway Traffic Safety Administration Office of Defects Investigations revealed only two database references, one for fuel related fires and the other for electrical related fires. There was no specific recall noted for the main battery wiring cable.

### CONCLUSION

Based on the on scene inspection and research to date, it is the opinion of this organization that the fire originates in the engine compartment. The point of origin is in the right side of the engine compartment. The exact cause is undetermined, however, the following two possibilities have not been eliminated.

1. A fuel related fire.
2. Electrical failure in the battery cables.

### COMMENTS AND RECOMMENDATIONS

It is recommended that follow-up interviews with the insured in reference to any recent work or notices of service bulletins they may have received either from the manufacturer, Ford Motor Company, or their authorized Ford dealership.

We want to thank you for the opportunity to have been of service to you. If any additional information is required or follow-up is to be conducted, please contact us.

Respectfully submitted,

PETER VALLAS ASSOCIATES Inc.

  
David R. Redwicker  
Corporate Director of  
Investigations

DER/mld

### PHOTOGRAPHIC DOCUMENTATION AND/OR OTHER ATTACHMENTS

FIRE AND EXPLOSION ANALYSIS ★ ANALYTICAL LABORATORY ★ INVESTIGATIVE ENGINEERING SERVICES

EA25-025-LC1-2443



1. Overall view of the left side of the vehicle.



2. Close up view of the vehicle identification number plate location indicated by the arrow.





3. Overall view into the rear storage area. Note the seat is not from this vehicle.



4. Overall view into the middle seat area of the vehicle.



5. Overall view of the fire patterns on the rear of the vehicle.



6. View of the fuel filler cap location in the left rear quarter panel.



7. Overall view of the right side of the vehicle from the right front.



8. View into the passenger compartment through the windshield.



9. Overall view into the front passenger compartment area from the driver side.



10. View into the front passenger compartment from the right side.



11. View of the driver's side prior to clearing of the debris.



12. View of the driver side after clearing of the debris.



13.  
(Photos 13 and 14 are documentation of the wiring harness in  
the left side of the dashboard.)



14.



15. Overall view of the front of the vehicle.



16. Closer view of the engine compartment. Note the piece of aluminum hood that remains.






17. View after replacing the piece of aluminum hood to it's original position as indicated by the arrow.



18. Closer view of the fire damage to the throttle body.



19. Close up view of the melted throttle body.




20. View into the left wheel well.



21. Another view looking towards the front in the left wheel well. Note the oil filter is still intact.



22. Overall view into the engine compartment from the left side.




23. Closer view of the left side of the engine compartment.



24. View looking towards the ABS brake system on the left side of the engine compartment.



25. Close up view of the fuel lines entering the left rear of the engine compartment indicated by the arrow.



26. Overall view of the engine compartment from the right side.



27. View into the engine compartment from the right wheel well.



28. Overall view of the right side of the engine compartment where the electrical system is located.



29. Closer view of the battery cables during my inspection.



30. Close up view of the battery cable connected to the alternator indicated by the arrow.



31. Overall view of the damaged battery cables.



32. Closer view. Arrow indicates the cable that is burned through.






33. View of the battery cables with a scale of reference.



34. View of the section of cables being removed.



35. View after removing the cables and connectors.



# State Farm Insurance Companies



P.O. Box 749  
Winter Haven, FL 33882-0749

Certified Mail - Return Receipt Requested

September 18, 2000

Ford Motor Company  
Parklane Tower West  
Suite 400  
3 Parklane Blvd.  
Dearborn, MI 48126



RE: Claim Number: [REDACTED]  
Date of Loss: May 24, 2000  
Our Insured: [REDACTED]  
Amount of Loss: \$820,672.75  
Vehicle: 1998 Ford F150  
1FTZX1765WN [REDACTED]

The identified vehicle is insured by State Farm Mutual Automobile Insurance Company. This vehicle experienced a fire loss.

State Farm would like to give you an opportunity to inspect the vehicle and give you advance notice of our potential subrogation claim. Please contact me at (800) 707-7408 to setup a time for your inspection.

Sincerely,

John Easley  
Claim Specialist  
(800) 707-7408

State Farm Mutual Automobile Insurance Company

wmm

Enclosure: Supporting Documentation

- 198 F-150  
- \$820,673.-  
- 5-24-00  
- EXP. Rpt.

HOME OFFICES: BLOOMINGTON, ILLINOIS 61710-0001

ENCL-003-1C1-8483

**WARD & WHITEMORE**

UNIVERSAL FIRE CONSULTANTS

# WARD & WHITMORE

## UNIVERSAL FIRE CONSULTANTS

CINCINNATI  
DALLAS / FT. WORTH  
JACKSONVILLE  
LOS ANGELES  
MIAMI  
MINNEAPOLIS  
TALLAHASSEE

P.O. BOX 10636  
JACKSONVILLE, FL 32247  
(904) 247-8006  
FAX: (904) 247-8001  
TOLL FREE: 1-877-351-FIRE

July 11, 2000

Ms. Corey Alexander  
State Farm Insurance Company  
646 Ocoee Commerce Parkway  
Ocoee, Florida 34761

Re: Insured: [REDACTED]  
Claim No. [REDACTED]  
Date of Loss: May 24, 2000  
WWUFC #: 00-J199

Dear Ms. Alexander:

On June 12, 2000, Ward & Whitmore Universal Fire Consultants was retained by you for the purpose of conducting an investigation to determine, if possible, the origin, and cause of a fire that occurred in a 1998 Ford F150, VIN 1FTZX1765W[REDACTED]. The loss occurred on May 24, 2000. On June 14, 2000, I examined the vehicle at RPS Towing in Orlando, Florida. At that time the vehicle was examined, and documented with photographs, a recall research was conducted, and information was received from you.

After I examined the vehicle I called your office, and left a message pertaining to our findings, and recommendations. We requested that you put the manufacturer, the dealer, and any other parties that may have performed maintenance to the truck on notice for potential subrogation issues. We then requested that you have the vehicle secured, and covered to allow the other interested parties, the opportunity to examine the vehicle as it was.

This report will furnish you with a synopsis of that particular investigation.

### BACKGROUND INFORMATION

[REDACTED] is the owner, and operator of the aforementioned vehicle. The license tag on the vehicle is registered in Orange County, Florida, and expires in August of 2000. The tag number is [REDACTED].

RECEIVED

Ms. Corey Alexander  
State Farm Insurance Company  
July 11, 2000  
Page 2

Re: Injured: [REDACTED]  
Claim No. [REDACTED]  
Date of Loss: May 24, 2000  
WWUFC #: 00-J199

#### ANALYSIS

During my preliminary examination of the vehicle I observed fire patterns that were consistent with the fire originating inside the engine compartment on the passenger side. The fire then entered the passenger compartment through the openings in the firewall. The fire also damaged the windshield, and the glass failed. When the glass failed the fire then progressed into the passenger compartment.

The front passenger side tire was melted, and the front passenger wheel well revealed intense heat, and fire damage.

After I determined the fire originated inside the engine compartment, a closer examination of that area for potential ignition sources was initiated. I observed heavy fire damage on the passenger side of the engine. There was intense heat on the side of the engine, and the firewall behind the engine.

I checked the electrical system, and observed some areas that the wiring appeared to be arced. There was one area where an electrical supply line was pressed against a metal bracket, and the wires were melted to it. I also observed the transmission fluid stick protruding out from the tube. There were other wires in that area of origin that revealed intense heat, and electrical failure.

All of the wiring, and electrical components in this area were very brittle, and sensitive. I then stopped my examination for fear of doing more damage to the wires. It appeared at that time that there maybe some type of subrogation. I left it as I found it to allow other interested parties to examine the vehicle as it was.

05-LAND 1237

71134

RECEIVED

0005-005-LC1-0466

Ms. Corey Alexander  
State Farm Insurance Company  
July 11, 2000  
Page 3

Re: Insured: [REDACTED]  
Claim No.: [REDACTED]  
Date of Loss: May 24, 2000  
WWUFC #: 00-J199

#### CONCLUSION

Based on the examination of the vehicle, and all of the information received at this time we have reached the following conclusions. This fire originated inside the engine compartment, and the cause for the fire appeared to be some type of mechanical failure in the electrical system or lubricating system.

Further, the exact cause for the fire could not be determined, but we would recommend that the aforementioned parties be put on notice so a closer examination of these systems can be conducted. This may allow us to make a more accurate determination for the fire cause.

This concludes our investigation into this matter at this time. Should you have any further questions or directives, please contact us at (904) 247-8005, or toll free at (877) 361-3473, and reference our File No. 00-J199.

Respectfully,

  
Jack A. Ward

Enclosures: Photographs  
Recall bulletins

ORLANDO, FL

RE



# INVESTIGATIVE PHOTOS

W&W File No. 00-J199

Claim No. [REDACTED]

Location/View: Several of a 1998 Ford F150, VIN 1FTZX176SWN [REDACTED] located at RPS towing in Orlando, Florida

Date/Time: June 14, 2000

By: Jack Ward

Photo No. 1-5

Comments: Show the exterior of the vehicle looking at all four sides. The heat, and fire patterns indicate the fire originated inside the engine compartment on the passenger side.



ORLANDO, FLA.

JUL 21

RECEIVED

**WARD & WHITEMORE**

UNIVERSAL FIRE CONSULTANTS

888-888-101-8488

Photo No. 2



Photo No. 3



Photo No. 4



Photo No. 5



# INVESTIGATIVE PHOTOS

W&W File No. 00-J199

Claim No. [REDACTED]

**Location/View:** Several of a 1998 Ford F150, VIN 1FTZX1765WN [REDACTED] located at RPS towing in Orlando, Florida.

**Date/Time:** June 14, 2000

**By:** Jack Ward

**Photo No.** 6

**Comments:** Shows the front passenger side of the vehicle. Note the heat, and fire patterns are very intense in this area, and progress from inside the engine compartment.

---



# INVESTIGATIVE PHOTOS

W&W File No. 00-J199

Claim No. [REDACTED]

Location/View: Several of a 1998 Ford F150, VIN 1FTZX1765W [REDACTED] located at RPS towing in Orlando, Florida.

Date/Time: June 14, 2000

By: Jack Ward

Photo No. 7

Comments: Shows the windshield. The heat, and fire patterns on the lower portion of the windshield on the passenger side are consistent with the fire originating inside the engine compartment on the passenger side.

---



EC00-005-L01-0472

# INVESTIGATIVE PHOTOS

W&W File No. 00-J199

Claim No. [REDACTED]

**Location/View:** Several of a 1998 Ford F150, VIN 1FTZX176SWN [REDACTED] located at RPS towing in Orlando, Florida.


**Date/Time:** June 14, 2000

**By:** Jack Ward

**Photo No.** 8-10

**Comments:** Show the interior of the vehicle. The heat, and fire damage inside this compartment indicate the fire originated inside the engine compartment, and progressed through the openings of the bulkhead.

---



FA88-883-LC1-8473

Photo No. 9



Photo No. 10



# INVESTIGATIVE PHOTOS

W&W File No. 00-J199

Claim No. [REDACTED]

Location/View: Several of a 1998 Ford F150, VIN 1FTZX1765W7 [REDACTED] located at RPS towing in Orlando, Florida.

Date/Time: June 14, 2000

By: Jack Ward

Photo No. 11-12

Comments: Show the dashboard area of the vehicle. Note the heat, and fire damage is consistent with the fire coming into the passenger compartment through the openings in the firewall from the engine compartment on the passenger side.

---



ERG5-005-LC1-0475



W&W File No: 00-J199

Claim No. [REDACTED]

Refer to Previous Photo No. 11

Photo No. 12



E005-005-LC1-0478

**INVESTIGATIVE PHOTOS**

**W&W File No.** 00-J199

**Claim No.** [REDACTED]

**Location/View:** Several of a 1998 Ford F150, VIN 1F1ZX1765WN [REDACTED] parked at RPS  
towing in Orlando, Florida.

**Date/Time:** June 14, 2000

**By:** Jack Ward

**Photo No.** 13-13

**Comments:** Show the engine compartment looking from the front. Note the heat, and  
fire damage is more intense on the passenger side of the vehicle.

---



**EAS-085-LC1-0477**

W&W File No: 00-J(99)

Claim No. [REDACTED]

Refer to Previous Photo No. 13

Photo No 14



EAGS-005-LC1-0478

W&W File No: 00-J199

Claim No. [REDACTED]

Refer to Previous Photo No. 13

Photo No 15



ERG-885-LC1-8478

# INVESTIGATIVE PHOTOS

W&W File No. 00-J199

Claim No. [REDACTED]

Location/View: Several of a 1998 Ford F150, VIN 1FTZX1765W [REDACTED] located at RPS  
towing in Orlando, Florida.


Date/Time: June 14, 2009

By: Jack Ward

Photo No. 16-19

Comments: Show the electrical supply, and circuitry wiring on the passenger side of  
the engine compartment. Note there was some intense heat, and damage to  
the copper wiring that is consistent with arcing.

---



W&W File No: 88-3199

Claim No. [REDACTED]

Refer to Previous Photo No. 16

Photo No. 17



2025-005-LC1-6481

W&W File No: 00-J199

Claim No. [REDACTED]

Refer to Previous Photo No. 16

Photo No. 18



ENG-005-LC1-0482

W&W File No: 00-J199

Claim No. [REDACTED]

Refer to Previous Photo No. 16

Photo No 19



ED05-005-LC1-0483



# INVESTIGATIVE PHOTOS

W&W File No. 00-J199

Claim No. [REDACTED]

Location/View: Several of a 1998 Ford F150, VIN 1FTZX1765W [REDACTED] located at RPS  
towing in Orlando, Florida.  
Date/Time: June 14, 2000  
By: Jack Ward  
Photo No. 20-21  
Comments: Show the transmission fluid check stick. Note there was fluid registering  
on the stick.

---



W&W File No: 08-J199

Claim No. [REDACTED]

Refer to Previous Photo No. 20

Photo No 21



SP25-825-LC1-2485

# INVESTIGATIVE PHOTOS

W&W File No. 00-J199

Claim No. [REDACTED]

Location/View: Several of a 1998 Ford F150, VIN 1FTZX1765WN [REDACTED] located at RPS  
towing in Orlando, Florida.


Date/Time: June 14, 2000

By: Jack Ward


Photo No. 22

Comments: Shows the oil check stick. Note it was still in place, and the top had burned  
off.

---



0000-005-LC1-0448



1-800 366-1116

# Horry County Fire Department Incident Report

INCIDENT #	DATE	STATION	TIME OUT
00-10552	26 Dec 00	4	1030
RESPONDING	ON SCENE	UNDER CONTROL	CANCELLED
1031	1038	1051	
LOCATION			
Postal Way			

YOUR PRIMARY RESPONSE STATION <input checked="" type="checkbox"/> OTHER HERRING STATIONS RESPONDING <input type="checkbox"/>	
OTHER RESPONDING FIRE DEPARTMENT <input type="checkbox"/>	
MUTUAL-AID RESPONSE TO	
NUMBER OF VOLUNTEERS	CARRIER
FROM YOUR STATION	TOTAL
FROM OTHER HERRING STATIONS	TOTAL
NUMBER OF VEHICLES FROM OTHER DEPARTMENTS	

## TYPE OF INCIDENT

### STRUCTURE

1 Single Family Structure 1b Commercial 1d Educational 1f Hotel/Motel 1h Other  
 1a Townhouse/Condo 1c Agricultural 1e Medical Facility 1g Duplex

SMOKE DETECTORS: YES NO HOW MANY WORKING NOT WORKING

2 MANUFACTURED HOME		2a Single wide	2b Double wide	2c Triple wide
YEAR	MAKE	MODEL	SERIAL #	END

3 AUTO FIRE (3a PU Truck)		3b Other Truck	3c Agricultural	3d Motor Home	3e Boat	3f Other
YEAR	MAKE	MODEL	TAG #	SERIAL #		
1997	Ford	F-150	164-FTK	1P70F1721VN		

RESCUE	4a Entrapment	4b Eviction	4c Search	4d Traffic Control	4e Medical Assistance
--------	---------------	-------------	-----------	--------------------	-----------------------

VEHICLE ACCIDENT: 24 Medical Assistance	24a Eviction	24b Traffic Control	24c Assist EMS	24d Fuel Spill
5 Brush Fire	11 Fuel Spill	17 Alarm Malfunction	22 Investigation Only	
6 Woods Fire	12 Chemical Spill	17a Alarm Activation	23 Rollover	Original #
7 Trash Fire	13 Power Line Down	18 Malicious Falses	24 Cancelled	Type of Call
8 Uncontrolled Burning	14 Airing Gas Equipment	19 Explosion	25 Hazmat	
9 Controlled Burning	15 Smoke Removal	20 Unclassified Fire	26 Public Service	
10 Water Removal	16 Smoke Bags	21 Unclassified Non-Fire		

Civilian Injuries ☐ Civilian Deaths ☐ Firefighter Injuries ☐ Firefighter Deaths ☐

Total Engines	Total Trucks	Total Tankers	Total Rescues	Other Units	Total Apparatus
1	0	0	0	1	2
Driver's Name					
Driver's Address					
Driver's Phone					
Occupant's Name					
Occupant's Address					
Occupant's Insurance Carrier					
CAUSE OF FIRE: <input type="checkbox"/> SMOKING MATERIAL <input type="checkbox"/> ELECTRICAL <input type="checkbox"/> FIREWORKS <input type="checkbox"/> UNDER INVESTIGATION					
<input type="checkbox"/> COOKING EQUIPMENT <input type="checkbox"/> HEATING/GAS SYSTEM <input type="checkbox"/> APPLIANCE <input checked="" type="checkbox"/> UNDETERMINED <input type="checkbox"/> OTHER					
Signature: [Signature]					

White Copy - Office Yellow Copy - Station Pink Copy - Fleet Copy

AD Query

**Estimate Photo 01 for Claim Number [REDACTED]**

Photo date: 27/12/2000 11:43:25:00 Size: 100280

Description:

Insured [REDACTED]

Policy Number: [REDACTED]

Vehicle: 97, FORD, F150 4X2 STANDARD

VIN: 1FTDF1727VN [REDACTED]

Loss date: 12/26/00

Estimator: ALLEN JACKSON



**Estimate Photo 02 for Claim Number [REDACTED]**

[REDACTED]

4/27/01

EROS-885-LC1-0408

Photo date:27/12/2000 11:43:27:00 Size:126844

Description:

Insured:


Policy Number:

Vehicle:97, FORD, F150 4X2 STANDARD

VIN:1FTDF1727VN [REDACTED]

Loss date:12/26/00

Estimator:ALLEN JACKSON



**Estimate Photo 03 for Claim Number [REDACTED]**

Photo date:27/12/2000 11:43:28:00 Size:101148

Description:

Insured:

Policy Number:23425390

4/27/01

ERB-005-LC1-0488

Vehicle: 97, FORD, F150 4X2 STANDARD

VIN: 1FTDF1727VN [REDACTED]

Loss date: 12/26/00

Estimator: [REDACTED]



**Estimate Photo 04 for Claim Number [REDACTED]**

Photo date: 27/12/2000 11:43:30:00 Size: 98024

Description: [REDACTED]

Insured: [REDACTED]

Policy Number [REDACTED]

Vehicle: 97, FORD, F150 4X2 STANDARD

VIN: 1FTDF1727VN [REDACTED]

Loss date: 12/26/00

Estimator: ALLEN JACKSON

[REDACTED] 4/27/01





4/27/01

ENGE-005-LC1-0491





ALLSTATE COUNTY MUTUAL INSURANCE COMPANY  
P.O. BOX 149288  
IRVING TX 75016


(800) 274-4246

06 21 02

CONSUMER AFFAIRS  
SECTION

2 JUL 16 P2:13

FORD MOTOR COMPANY  
15800 EXECUTIVE PL  
DEARBORN MI 48121



OUR INVESTIGATION INDICATES THAT YOUR INSURED WAS RESPONSIBLE FOR THIS LOSS.

SINCE WE HAVE ALREADY MADE A SETTLEMENT WITH OUR POLICYHOLDER THE CLAIM HAS BEEN ASSIGNED TO US. COPIES OF THE FINAL PAPERS RELATING TO THE LOSS ARE ENCLOSED.

PLEASE ACCEPT THIS LETTER AS NOTICE OF OUR SUBROGATION CLAIM. PLEASE FORWARD YOUR PAYMENT WITH OUR CLAIM NUMBER TO:

ALLSTATE PAYMENT PROCESSING CENTER  
P.O. BOX 227257  
DALLAS, TX, 75222-7257

DIRECT ANY OTHER CORRESPONDENCE TO THE ADDRESS AT THE TOP OF THIS LETTER.

SINCERELY,

SUBROGATION CLAIM REP

ALLSTATE COUNTY MUTUAL INSURANCE COMPANY

CBP:16

YOUR FILE NO. : CUST REL AT CENTER  
YOUR INSURED : [REDACTED]  
ADDRESS : 15800 EXECUTIVE PL  
DEARBORN MI [REDACTED]

OUR CLAIM NO. : [REDACTED] SUB  
OUR INSURED : [REDACTED]  
LOSS DATE : 05/15/02

LOCATION :  
BELTWAY 8, NEAR INT 45 HOUSTON

AMOUNT OF LOSS: \$8,570.13

EN05-005-LC1-0482

Forensic Analyst, Inc.

**PRELIMINARY  
REPORT OF FINDINGS**

CLAIM NO: [REDACTED]

INSURED: [REDACTED]

Prepared for:

ALLSTATE INSURANCE COMPANY  
800 CITY WEST BLVD, SUITE 700  
HOUSTON, TEXAS 77042

ATTN: MR. HUGO BENAVIDES

  
Jeffrey R. Alcala, CR, CPE, ASE  
President

June 4, 2002

FAL 78a No. 1174

June 4, 2002

**Table of Contents**

	Page
I. INTRODUCTION	3
II. CONCLUSION	4
III. DISCUSSION	5
• FORD VEHICLE IDENTIFICATION	
• FORD VEHICLE INSPECTION	
• INTERVIEW WITH THE INSURED	
• RECOMMENDATION	
IV. BASIS OF REPORT	17
V. ATTACHMENTS -- PHOTOGRAPHS	18

Page 2

FAL 78a No. 1174

2005-005-LCI-8483

## I. INTRODUCTION

Reportedly, on May 16, 2002, a fire occurred involving a 1997 Ford F-150 XL Pickup vehicle. On May 16, 2002, Forensic Analysis, Inc. was retained by Mr. Hugo Benavides of Allstate Insurance Company to inspect the vehicle and determine the origin and cause of the fire.

On May 17, 2002, Mr. Jeffrey Adams, CR, CFI, ASE, of Forensic Analysis, Inc., inspected and photographed the Ford F-150 XL Pickup vehicle at Allstate Collision Center, Inc., 12651 Veterans Memorial, Houston, Texas.

Samples of engine oil and automatic transmission fluid were taken, should an oil analysis be desired to help determine the pre-fire condition of the engine and/or transmission. All samples are being stored at the offices of Forensic Analysis, Inc., pending further instructions from Allstate Insurance Company.

This report is based upon information available to us at this time, and is not necessarily final. Should additional information be presented or discovered, we reserve the right to review and, if necessary, revise this report and our conclusions in light of that information.

## II. CONCLUSION

Forensic Analysis, Inc., inspected and photographed the Ford F-150 XL Pickup vehicle.

In conclusion, based on our observations and the findings as noted in this report, it is our opinion that this 1997 Ford F-150 XL Pickup vehicle engine compartment fire was the result of ignition of gasoline fumes, leaking from the fuel injection system, immediately behind the left side of the engine. It is further our opinion that Ford Motor Corporation should be held responsible for this loss as fuel lines should not fail in a fire-generating fashion.

## III. DISCUSSION

The scope of our inspection was to determine the origin and cause of a vehicle fire.

### FORD VEHICLE IDENTIFICATION

The vehicle was identified as a red, two-door, 1997 Ford F-150 XL Pickup vehicle, bearing Texas license plate No. [REDACTED] and a partial vehicle identification No. ...C92699. This vehicle identification number matched the vehicle identification number furnished to us from Allstate Insurance relating to the insured's 1997 Ford F-150 Pickup vehicle.

### FORD VEHICLE INSPECTION

Our inspection of the vehicle exterior revealed a fire that was distinctively most intense at, and immediately surrounding, the left rear corner of the engine compartment. More specifically:

1. Little burn was experienced on the tailgate or at, and immediately surrounding, the rear bumper of the vehicle. It must be noted, however, that the left rear brake lamp/turn signal assembly experienced significant burn, and partial consumption.
2. Even though we did not describe the interior burn of the truck bed as severe, it must be noted that the truck bed contained a plastic composite liner that was severely burned on the front, right, and left sides. The flooring portion of the bed liner was primarily intact, and

attached, at the time of our inspection. The combustible right and left side truck bed liner, however, did, indeed, communicate burn to both top portions of the right and left truck bed side, and it the reason for communicated fire damage on the left rear brake lamp/turn signal assembly.

3. All exterior window glass was shattered as a result of the fire.
4. Both rear tire and wheel assemblies were unburned, as a result of the fire.
5. The left side door panel experienced widespread burn, consuming approximately eighty percent (80%) of the exterior painted surface. The bottom three to six inches (3"-6"), however, of the left side door panel was relatively unburned.
6. The right side door panel also experienced widespread burn, consuming approximately sixty percent (60%) of the painted surface. The right side, obviously, was significantly less burned than the left side door panel. In fact, the front three to twelve inches (3"-12") of the right side door panel still contained intact, and unburned paint.
7. The right front fender of the vehicle was primarily, unburned. However, it did contain a relatively thick layer of soot, immediately to the right of the closed vehicle hood. The left front fender was significantly more burned than the right front fender, as approximately fifty percent (50%) of the paint was consumed, primarily, on the rear half of the left front fender.

8. Both right front and left front tire and wheel assemblies were relatively unburned. It must be noted, however, that the right front plastic wheel well cover was intact, attached, and relatively unaffected by this fire. The left front plastic wheel well cover, however, was severely burned, and partially consumed. This, obviously, is consistent with a fire that was significantly more intense on the left side of the engine compartment than on the right side.
9. The front grille, front headlamp assemblies, and front bumper were relatively unaffected by this fire.
10. The vehicle hood was approximately sixty percent (60%) unburned and forty percent (40%) severely burned. In fact, the left rear corner and left rear twenty-five percent (25%) of the closed aluminum alloy vehicle hood was consumed in this relatively mild engine compartment fire. The area of greatest consumption was immediately to the left of center in the rear portion of the engine compartment, as indicated by the consumption of the aluminum vehicle hood.

In summary of our inspection of the vehicle exterior, the fire appeared to be intense within the left rear corner of the engine compartment, or well or within the vehicle interior, concentrating, however, on the left side of the vehicle.

Our inspection of the vehicle interior revealed:

1. The skeletal remains of the bench seat.

2. The burned remains of a significant amount of personal belongings, immediately behind the bench seat, which included clothing and shoes.
3. We observed the severely burned, and primarily consumed, interior door panels. The right side interior door panel was approximately eighty percent (80%) consumed, while the left side interior door panel was nearly completely consumed, again, indicative of a fire that was more intense on the left side of the vehicle interior.
4. We observed the severely burned vehicle dash. It must be noted, however, that there was a significant amount of unconsumed combustible materials surrounding the vehicle dash, including the portion immediately above the right third of the vehicle dash, as well as the portion immediately above the steering column.
5. We also observed the severely burned steering column. In fact, the steering wheel was consumed in this interior fire.
6. We observed the primarily protected floor covering throughout the vehicle interior.

It appeared that a significant amount of the fold-down protected the floor covering throughout the vehicle interior. This is consistent with a burn that did not originate, and did not intensify in any one specific area, within the vehicle interior, and is inconsistent with what would be classified as an incendiary burn.

A closer inspection of the burn experienced by the vehicle dash revealed:

June 6, 2002

Page 7

FAT File No. 2374

June 6, 2002

Page 8

FAT File No. 2374

1. The aluminum air conditioning evaporator core, under the right third of the vehicle dash was relatively unburned, and fully intact, at the time of our inspection. There was also a significant amount of plastic composite housing material surrounding the evaporator core. This is indicative of a fire that did not originate within the vehicle interior. The fact that the bottom portion of the plastic composite evaporator core housing was intact, as well, is indicative of a fire that did not originate under the right third of the vehicle dash.
2. The center third of the vehicle dash was severely burned, but primarily intact, and lay near floor level. The Heating Ventilation and Air Conditioning (HVAC) controls had fallen on-top of the center console, as well as immediately neighboring the severely burned stereo system.
3. As previously stated, there was a significant amount of combustible materials that were not consumed, immediately above the steering column. The widespread burned remains, above the steering column, are consistent with a fire that did not originate at, or immediately surrounding, the steering column, as this area is easily consumed. Additionally, there was a significant amount of unconsumed wiring insulation at the top of the left third of the vehicle dash, again, consistent with a fire that did not originate within the vehicle interior, but, likely, spread through the firewall access holes from the left side of the firewall into the vehicle interior.
4. The area of greatest burn that was observed surrounding the vehicle dash was immediately to the right of the burned remains of the steering column. In fact, there was a "V" shaped, consumed

pattern, immediately to the right of the steering column, that went toward the firewall access hole, immediately to the right of the steering column. This is indicative of a fire that traveled from the engine compartment, through the firewall access hole, into the interior, through the left third of the vehicle dash. This should also be confirmed by a corroborating burn pattern, observed within the engine compartment.

Our inspection of the engine compartment revealed that this vehicle is equipped with a V6, distributorless, multipoint fuel injected engine, and an automatic transmission. Specifically:

1. This was a V6 4.2 liter engine.
2. The burn in the right half of the engine compartment is described as very mild, although unusually widespread. More specifically, even the top portion of the battery was mildly burned, and deformed, as a result of this relatively mild engine compartment fire. Even the wiring harness sheathing, in the protected right rear corner of the engine compartment, behind the battery, was partially consumed, and distorted, as a result of the heat intensity within the engine compartment. This would be classified as a burn, consistent with fuel within the engine compartment, and a fire that originated under the closed vehicle hood, and was propagated by a fuel.
3. As we moved toward the center third of the engine compartment, we continued to observe an upper level burn, severely burning, and partially consuming, the tops of the cooling hoses, as well as



partially consuming wiring insulation immediately above the right side of the air intake manifold.

4. The upper radiator hose, which was situated approximately two inches (2") below the air conditioning lines, was relatively unburned. However, there was a hole that was consumed in the very top portion of the high pressure air conditioning hose two inches (2") above. Again, this is consistent with widespread heat intensification under the closed vehicle hood.
5. The upper radiator shroud, which was a plastic composite material, was distorted across its entire width.
6. The air intake plumbing, which was routed across the left half of the front of the engine compartment, was only mildly burned on the very front, but intensely burned, and partially consumed, on the very rear. This is consistent with a fire that was traveling from the rear toward the front. In the left half of the engine compartment, it must also be noted that the right side of this air intake plumbing was relatively unburned, while the left side was severely burned, again, consistent with a fire that was traveling from the rear toward the front, and from the left to the right, within this engine compartment.
7. There was a significant amount of black soot on the left side of the upper air intake manifold, while the right side of the upper air intake manifold was significantly less coated with the soot.
8. The brake master cylinder, which was constructed of an aluminum alloy material, was relatively unburned, even though the brake master cylinder plastic composite reservoir was severely burned,

and partially consumed. Again, the intensity of this fire was significantly upper level, across the entire width of the engine compartment. The fact that the easily consumed aluminum brake master cylinder was completely intact at the time of our inspection is indicative a fire that did not originate below, or immediately surrounding, this brake master cylinder.

9. The left rear engine compartment mounted power distribution center was severely burned, and only partially consumed. The partial consumption of this left rear plastic housing was on the rear and the right side, consistent with a burn that was traveling, from the left side of the engine, toward this housing, and from the rear portion of the engine compartment toward the front.
10. The left side engine spark plug wires were severely burned on the very top, but were relatively unburned at the spark plug boot. The burn was significantly more intense from the top of the valve cover to under the closed vehicle hood. This, again, is consistent with a burn intensity that was greater within the top six to eight inches (6"-8") under the closed vehicle hood.
11. The right side of the brake power booster experienced significantly greater burn on the top half than the left side. Again, this is consistent with a fire that was traveling from the right side of the brake power booster toward the left.
12. There was a wiring harness run that was routed across the top portion of the firewall, across the entire width of the engine compartment. This wiring harness run did have severely burned, but partially clad, wiring insulation, immediately above the brake power

booster. However, as we continued to move toward the right side of the brake power booster, the wiring insulation was completely consumed in the area immediately above the left side valve cover. As we continued to move across the right half of the engine, we observed that the amount of severely burned, but intact, wiring insulation was more prevalent, again, indicative of a fire that was most intense in the rear portion of the engine compartment, immediately above the left side valve cover.

13. There was a "V" shape burn pattern, immediately above the left side engine valve cover, that was approximately ten inches (10") below the closed vehicle hood at the apex. The apex was immediately to the left of the left side engine valve cover. The "V" burn pattern was very distinct, and delimited itself approximately two inches (2") below a relatively large, three-inch (3") diameter firewall access hole, which was immediately to the right of the power booster. This access hole was the opening which allowed the fire to travel from the engine compartment into the interior, consuming this portion of the interior of the vehicle dash, as was described in the inspection of the vehicle interior.

A closer inspection of the area at, and immediately surrounding, the most intensely burned area, above the left side engine valve cover revealed:

1. As previously stated, this vehicle was equipped with multipoint fuel injection, and all three (3) left side fuel injectors were intact, attached, and relatively unburned. These were immediately to the right of the left side engine valve cover.

June 4, 2002

Page 13

FAI No. 2374

2. The fuel injection rail was supplied fuel via the fuel injection supply and return lines, immediately above, and to the left of, these left side engine fuel injectors.
3. The fuel injection fuel supply and return line sheathing, which was a plastic composite material, was severely burned, and partially consumed on the very top.
4. The spark plug wires, which were routed across the rear portion of the left side valve cover, to the centrally, top engine-mounted ignition coil pack, were severely burned, and partially consumed, within approximately six inches (6") of the closed vehicle hood. It must be noted that below approximately six inches (6") under the closed vehicle hood, these spark plug wires were relatively unburned. There was a very sharp line of demarcation, consistent with a very large heat release role, and consistent with fire intensification, as a result of leaking gasoline.

It is no coincidence that the fuel injection fuel supply and return lines were immediately below, and within a few inches of, the "V" shaped burn pattern that was observed immediately above the left side valve cover on the firewall. All evidence is also consistent with a fire that was intensified by leaking gasoline within the engine compartment. The only source of fuel, which could intensify the burn pattern from the area observed, is from leaking fuel lines or fuel injectors. The gasoline fumes from the leaking fuel system could then easily become ignited by an event spark within the engine compartment. This fire can also develop while the vehicle is being driven, which would intensify the burn at, and immediately to the right of, this firewall access hole, through which the fire entered into the vehicle interior.

June 5, 2002

Page 14

FAI No. 2374

FAIR-002-1-01-0408

#### INTERVIEW WITH THE INSURED

An interview with the insured helped construct an order of events immediately preceding the onset of this vehicle fire:

1. He stated that he was driving his girlfriend home, of approximately 10:30 P.M., on the date of the loss.
2. He said that very quickly his girlfriend saw smoke from under the rear portion of the engine compartment.
3. He said that he was traveling for approximately fifteen to twenty (15-20) minutes prior to this occurrence, and thought he was driving at approximately fifty miles per hour (50 mph).
4. He said that there is no question in both of their minds that the initial observation of fire was observed in the rear portion of the engine compartment.
5. He said that he smokes, but he did not throw any lighted material within the vehicle interior.
6. He said that the fire burned a hole in the left side of the closed vehicle hood.
7. He said that while he was pulling over to the side of the road, someone called 9-1-1 to alert the fire department.
8. He said that it only took between five and ten (5-10) minutes before the fire department came, and extinguished the fire.

June 4, 2002

Page 12

UAI File No. 1224

#### RECOMMENDATIONS

We recommend that the 1997 Ford F-150 XL Pickup vehicle be retained, secured, and protected regarding any further testing or inspection by other interested parties. We also reserve the right to be present and observe any and all inspections or testing of the 1997 Ford F-150 XL Pickup vehicle by any other concerned parties.

June 4, 2002

Page 13

FBI File No. 2324

2025 RELEASE UNDER E.O. 14176

#### IV. BASIS OF REPORT

This report is based upon the following:

1. Inspection of the 1997 Ford F-150 XL Pickup vehicle.
2. Interview with the insured.
3. Information and observations as noted in this report.

Page 4, 2002

Page 17

FAI PB# No. 2374

#### V. ATTACHMENTS

PHOTOGRAPHS

Page 6, 2002

Page 18

FAI PB# No. 2374

ENDS-000-LC1-0001

1. View of the front of the Ford vehicle.



2. View of the left side of the Ford vehicle.



June 6, 1962

Page 21

RAI 276 No. 2734

3. View of the right side of the Ford vehicle.



4. View of the rear of the Ford vehicle.




June 6, 1962

Page 22

RAI 276 No. 2734

2025-10-17-200-0000

5. View of the remains of the vehicle identification tag.



6. View of the relatively unburned truck bed as viewed from the right.



June 6, 2005

Page 21

FBI File No. 2874

7. Overview of the unburned right rear tire and wheel assembly.



8. Overview of the relatively unburned right front tire and wheel assembly.



June 6, 2005

Page 22

FBI File No. 2874

BA000-000-L01-0500

9. View of the unburned right front wheel well plastic interior.



10. Overview of the relatively unburned left front tire and wheel assembly. Please note that the plastic interior portion of the wheel well was severely burned at the rear.




Page 5, 3083

Page 23

PAI File No. 2274

11. View of the remainder of the interior bench seat.



12. Overview of the vehicle dash.



Page 6, 3083

Page 24

PAI File No. 2274

ENC-905-L01-9804

13. Closer view of the relatively unburned right side of the vehicle dash and the unburned aluminum air conditioning evaporator core.



14. View of the burned but primarily intact remains of the center stack of the vehicle dash.



Aug 5, 2017

Page 24

FAI 794 No. 2374

15. Overview of the remains of the steering column.



16. Overview of the burn experienced by the hood as viewed from the left.



Aug 6, 2017

Page 25

FAI 794 No. 2374

5405-005-1-C1-0509



17. Overview of the engine compartment.



18. View of the engine compartment as viewed from the left.



June 6, 2002

Page 21

RASTPb No. 2201

19. View of the engine compartment as viewed from the right.



20. Overview of the engine identification tag under the closed vehicle hood.




June 6, 2002

Page 22

RASTPb No. 2201

ESMS-005-1-01-0008

21. Closer view of the limited burn experienced at and immediately surrounding the right side mounted battery.



22. View of the limited burn experienced by the upper radiator hose as viewed from the right.



23. Closer view of the hole that was burned in the top of the air conditioning hose immediately above the unburned upper radiator hose. This is the result of intense heat that was widespread under the closed vehicle hood.



24. Overview of the burn experienced by the front of the air intake plenum.



25. View of the burn experienced by the rear of the air intake plumbing.



26. View of the area surrounding the fuse and relay holder in the left rear corner of the engine compartment. Please note the intensity of both was greatest closest to the firewall and pointing toward the center of the engine.



June 4, 2003


Page 31

FBI File No. 2574

27. View of the limited burn surrounding the brake master cylinder and the partial consumption of the plastic brake master cylinder reservoir.



28. Overview of the upper air intake manifold as viewed from the front.



June 4, 2003

Page 32


FBI File No. 2574

ENR05-005-101-0500

29. View of the unconsumed wiring insulation in front of the firewall in the right field of the engine compartment.



30. View of the insulation void wiring immediately above the left half of the upper of intake manifold.




APR 6 2002


Page 33

FBI File No. 2274

31. View of the primarily insulation void wiring immediately to the right of the brake power booster.



32. View of the severely burned and partially consumed insulation surrounding the wiring harness which was previously situated immediately above the brake power booster.



APR 6 2002

Page 34

FBI File No. 2274

00000-1017-000-0000

33. Overview of the V-shape burn pattern observed immediately to the right of the firewall access hole which was to the right of the brake power booster.



34. Overview of the continuation of the V-shape burn pattern on the top portion of the firewall immediately above the rear portion of the upper air intake manifold.




June 4, 1983

Page 22

YAL File No. 2274

35. View of the severe upper level burn on the spark plug wires that were routed to the rear of the engine.



36. Overview of the area immediately behind the left side of the engine.



June 4, 1983

Page 23


YAL File No. 2274

BR-800-101-0518

37. Closer view of the fuel injection fuel supply and return hoses that were immediately below and approximately four inches to the right of the area of most intense burn immediately behind the engine.



38. Even closer view of the fuel injection fuel supply and return hoses that were immediately below and approximately four inches to the right of the area of most intense burn immediately behind the engine.



June 6, 2002

Page 22

FAZ PGs No. 3374

39. View of the intense burn that was observed immediately above the left side rear most mounted fuel injector.




Page 24

FAZ PGs No. 3374

June 6, 2002

2002-0606-LCT-0011





Coventry Police Department  
Coventry Police Department  
Incident Report

Page: 1

Page: 1  
04/03/2002

Incident #: 02-634-OF  
Call #: 02-5992

Date/Time Reported: 04/01/2002 2006  
Report Date/Time: 04/01/2002 2006  
Occurred On: 04/01/2002 2006  
Status: Incident Open  
Reporting Officer: OFF PETER ZALABOWSKI  
Approving Officer: SGT JAMES MCCARRON

Signature: \_\_\_\_\_

#	OFFENSE(S)	N/C	TITLE/CHAP	SECTION
---	------------	-----	------------	---------

LOCATION TYPE: Residence/Home/Apt./Condo Zone: AREA 3  
75 LEUSA RD  
COVENTRY RI 02816

1	INFORMATION ONLY-VEHICLE FIRE			C
	OCCURRED: 04/01/2002 2006			

#	VICTIM(S)	SEX	RACE	AGE	SSN	PHONE
---	-----------	-----	------	-----	-----	-------

1	[REDACTED]					
	COVENTRY RI					
	DOB: 09/07/1966					
	ETHNICITY: Not of Hispanic Origin					
	RESIDENT STATUS: Resident					
	VICTIM CONNECTED TO OFFENSE NUMBER(S): 1					

VEHICLE(S)	YEAR	MAKE	STYLE	COLOR1	COLOR2	REG	VALUE
------------	------	------	-------	--------	--------	-----	-------

F150	1997	FORD	FX	RED		RI 113011	\$14000.00
------	------	------	----	-----	--	-----------	------------

STATUS: Burned  
OWNER: [REDACTED]  
VIN: 1F3DF17ZKVM [REDACTED]  
DATE: 04/01/2002



On 4-1-2002 at approx. 2006 hrs., I responded to 75 Leuba Rd. for a report of a motor vehicle on fire. Upon my arrival, I observed the cab and engine compartment of a vehicle bearing RI comm. reg. 113011 fully engulfed in flames. The vehicle was parked in the driveway of 75 Leuba and was approx. ten feet away from the residence. I also noted that there were several explosions coming from the cab area of the pickup truck as the fire dept. was extinguishing the blaze.

I then located the vehicle's owner and identified him as [REDACTED]. [REDACTED] stated that he had arrived home approx. thirty minutes earlier and had parked the vehicle in his driveway. He advised that he went into the house and that a short time later he noticed a "glow" coming from the front of the house. He stated that when he looked outside, he observed that the vehicle was on fire. He stated that he then dialed 911 and then evacuated his family from the residence.

[REDACTED] advised that he hadn't noticed any problems with the vehicle, other than that the Check Engine light was activated constantly. He stated that he advised the dealer where he bought the vehicle of the problem, and that he has taken it to the dealer but it has not been fixed. He then provided the insurance information for the vehicle which was covered by Geico policy # [REDACTED]. I took several photographs of the vehicle and later downloaded the pictures at HQ's. Washington Deputy Fire Chief Warren advised that there was nothing suspicious about the fire, and further that the cause appeared to be due to a faulty electrical problem.



RHODE ISLAND  
FIRE INCIDENT REPORTING SYSTEM  
BASIC INCIDENT REPORT

NRPS 1

1 ☐ DELETE  
2 ☐ CHANGE

10	PERO 0,0,6,0,8	INCIDENT NO. 0,2,0,3,2,0	PROP NO. 0,0,0,4	DAY 0,1,0,2	YEAR MON	DAY OF WEEK 2	ALARM TIME 2,0,0,4	TIME ON SCENE 2,0,0,9	TIME IN SERVICE 2,0,5,7
TYPE OF SITUATION FOUND PICK-UP TRUCK FIRE		TYPE OF ACTION TAKEN 113 EXTINGUISHED		LOCATION FACTOR 9,6,3		VEHICLE TYPE UNDER DETERMINED		VEHICLE NO. 00	
PROPERTY TYPE DRIVEWAY		ADDRESS [REDACTED]		ZIP CODE [REDACTED]		CENSUS TRACT 2,0,7,0,0		ROOM OR AREA [REDACTED]	
TELEPHONE [REDACTED]		TELEPHONE [REDACTED]		TELEPHONE [REDACTED]		TELEPHONE [REDACTED]		TELEPHONE [REDACTED]	
DRIVER NAME / LAST / FIRST FOR [REDACTED]		ADDRESS [REDACTED]		ADDRESS [REDACTED]		ADDRESS [REDACTED]		ADDRESS [REDACTED]	
METHOD OF ALARM FROM PUBLIC 911		METHOD OF ALARM FROM PUBLIC 911		METHOD OF ALARM FROM PUBLIC 911		METHOD OF ALARM FROM PUBLIC 911		METHOD OF ALARM FROM PUBLIC 911	
NO. OF ENGINES RESPONDED 1006		NO. OF ENGINES RESPONDED ENG 11		NO. OF APPARATUS RESPONDED 10,0,1		NO. OF APPARATUS RESPONDED 10,0,0		NO. OF OTHER VEHICLES RESPONDED CAR 33	
NUMBER OF INJURIES FIRE SERVICE		NUMBER OF INJURIES OTHER		NUMBER OF FATALITIES FIRE SERVICE		NUMBER OF FATALITIES OTHER		NUMBER OF FATALITIES OTHER	
CAUSE NONE		CAUSE 9,8		VEHICLE TYPE PICK-UP TRUCK		VEHICLE TYPE PICK-UP TRUCK		VEHICLE TYPE PICK-UP TRUCK	
AREA OF FIRE ORIGIN [REDACTED]		AREA OF FIRE ORIGIN [REDACTED]		AREA OF FIRE ORIGIN [REDACTED]		AREA OF FIRE ORIGIN [REDACTED]		AREA OF FIRE ORIGIN [REDACTED]	
FORM OF HEAT OF IGNITION [REDACTED]		TYPE OF MATERIAL FUELED [REDACTED]		FORM OF MATERIAL FUELED [REDACTED]		FORM OF MATERIAL FUELED [REDACTED]		FORM OF MATERIAL FUELED [REDACTED]	
METHOD OF EXTINGUISHMENT E-11 AGE-CORRECT		METHOD OF EXTINGUISHMENT E-11 AGE-CORRECT		METHOD OF EXTINGUISHMENT E-11 AGE-CORRECT		METHOD OF EXTINGUISHMENT E-11 AGE-CORRECT		METHOD OF EXTINGUISHMENT E-11 AGE-CORRECT	
EXTENT OF FLAME DAMAGE [REDACTED]		EXTENT OF FLAME DAMAGE [REDACTED]		EXTENT OF FLAME DAMAGE [REDACTED]		EXTENT OF FLAME DAMAGE [REDACTED]		EXTENT OF FLAME DAMAGE [REDACTED]	
EXTENT OF SMOKE DAMAGE [REDACTED]		EXTENT OF SMOKE DAMAGE [REDACTED]		EXTENT OF SMOKE DAMAGE [REDACTED]		EXTENT OF SMOKE DAMAGE [REDACTED]		EXTENT OF SMOKE DAMAGE [REDACTED]	
DETECTOR PERFORMANCE [REDACTED]		DETECTOR PERFORMANCE [REDACTED]		DETECTOR PERFORMANCE [REDACTED]		DETECTOR PERFORMANCE [REDACTED]		DETECTOR PERFORMANCE [REDACTED]	
SPRINKLER PERFORMANCE [REDACTED]		SPRINKLER PERFORMANCE [REDACTED]		SPRINKLER PERFORMANCE [REDACTED]		SPRINKLER PERFORMANCE [REDACTED]		SPRINKLER PERFORMANCE [REDACTED]	
IF SMOKE SPREAD BEYOND ROOM OF ORIGIN [REDACTED]		TYPE OF MATERIAL GENERATING MOST SMOKE [REDACTED]		TYPE OF MATERIAL GENERATING MOST SMOKE [REDACTED]		TYPE OF MATERIAL GENERATING MOST SMOKE [REDACTED]		TYPE OF MATERIAL GENERATING MOST SMOKE [REDACTED]	
IF SMOKE SPREAD BEYOND ROOM OF ORIGIN [REDACTED]		TYPE OF MATERIAL GENERATING MOST SMOKE [REDACTED]		TYPE OF MATERIAL GENERATING MOST SMOKE [REDACTED]		TYPE OF MATERIAL GENERATING MOST SMOKE [REDACTED]		TYPE OF MATERIAL GENERATING MOST SMOKE [REDACTED]	
IF VEHICLE PROPERTY 13		YEAR 9,7		MAKE FORD		MODEL PICK-UP		SERIAL NO. [REDACTED]	
IF EQUIPMENT REPORTED [REDACTED]		YEAR [REDACTED]		MAKE [REDACTED]		MODEL [REDACTED]		SERIAL NO. [REDACTED]	
CHECK IF COMMENTS ON REVERSE SIDE		CHECK IF COMMENTS ON REVERSE SIDE		CHECK IF COMMENTS ON REVERSE SIDE		CHECK IF COMMENTS ON REVERSE SIDE		CHECK IF COMMENTS ON REVERSE SIDE	
OFFICER IN CHARGE / NAME / POSITION / ASSIGNMENT / DATE LT. BLANDING #1162		OFFICER IN CHARGE / NAME / POSITION / ASSIGNMENT / DATE LT. BLANDING #1162		OFFICER IN CHARGE / NAME / POSITION / ASSIGNMENT / DATE LT. BLANDING #1162		OFFICER IN CHARGE / NAME / POSITION / ASSIGNMENT / DATE LT. BLANDING #1162		OFFICER IN CHARGE / NAME / POSITION / ASSIGNMENT / DATE LT. BLANDING #1162	
FIRE CAUSE ACCIDENTAL		INCENDIARY [REDACTED]		SUSPICIOUS [REDACTED]		UNDETERMINED [REDACTED]		INSURANCE G.I.E.C.O.	
FIRE CAUSE ACCIDENTAL		INCENDIARY [REDACTED]		SUSPICIOUS [REDACTED]		UNDETERMINED [REDACTED]		INSURANCE G.I.E.C.O.	



## CLAIM PHOTOGRAPH

Claim No. [REDACTED]

## RECORD

Insured [REDACTED]

1  
TAKEN

DATE

Yes

No

RISK

PHOTO # 2 TAKEN

Negative available?

DESCRIPTION

RISK

COMMENTS:

SUBMITTED BY:

P. Holy

NAME

04/24/02

DATE

E905-005-LC1-0515

CLAIM PHOTOGRAPH  
RECORD

Claim No. [REDACTED]

Insured [REDACTED]



3

TAKEN

DATE

Yes

No

OVERHEAD DOOR  
4511 1/2 AREA  
OF HEAT DAMAGE  
WOOD SHAPES  
SINKING

PHOTO # 4 TAKEN

Negative available?

DESCRIPTION

OVERHEAD  
DOOR JAMB  
1/2 CASING  
BLISTERED  
PAINT FINISH

COMMENTS:

SUBMITTED BY:


*R. H. G.*

04/24/02

DATE

CLAIM PHOTOGRAPH  
RECORD

Claim No. [REDACTED]  
Insured [REDACTED]



5

TAKEN

DATE

Yes

No

HEAT DAMAGE  
TO LINEN  
CORNICE TRIM

PHOTO # 6 TAKEN

Negative available?

DESCRIPTION

HEAT DAMAGE  
TO OVERHEAD  
DOOR CASING

COMMENTS:

SUBMITTED BY:

*R. Haly*

04/24/02

DATE

CLAIM PHOTOGRAPH  
RECORD

Claim No.

Insured



7

TAKEN

DATE

Yes

No

ASPHALT  
DRIVEWAY  
FIRE 'N' HEAT  
DAMAGE

PHOTO # 8 TAKEN

Negative available?

DESCRIPTION

ASPHALT  
DRIVEWAY  
OVERVIEW

COMMENTS:

SUBMITTED BY:

R. Holt

04/24/02

CLAIM PHOTOGRAPH  
RECORD

Claim No. [REDACTED]

Insured [REDACTED]



9

TAKEN

DATE

27

Yes

No

ASPHALT  
DRIVEWAY  
FIRE DAMAGE

PHOTO # 10 TAKEN

Negative available? ☐

DESCRIPTION

FAMILY ROOM  
CEILING SCOT  
STAINLESS

AFTER CLEANING  
PROCESS

COMMENTS:



SUBMITTED BY:

*[Signature]*

DATE

04/24/02

DATE



CLAIM PHOTOGRAPH  
RECORD

Claim No. [REDACTED]

Insured [REDACTED]



11

TAKEN

DATE

Yes

No

FAMILY ROOM  
SOOT STAINED  
CEILING

OVERVIEW

PHOTO # 12 TAKEN

Negative available? ☐

DESCRIPTION

SOOT STAINED  
ON CEILING  
AFTER CLEANING  
PROCESS

COMMENTS

SUBMITTED BY:

R. Holz

ALB SEC

04/24/02

DATE

# SUBROGATION PARTNERS

A DIVISION OF UNIVERSAL RECOVERIES, INC.  
INSURANCE SUBROGATION AND MANAGEMENT SERVICES

P.O. Box 657, Farmingville, NY 11738  
Phone - 866-697-8276 Fax - 631-696-9767  
CONSUMER AFFAIRS  
SECTION

September 15, 2003

RECEIVED NOV 3 2003

3 OCT 29 49:43

Ms. Ann O'Neill  
Ford Motor Company  
P. O. Box 1904  
Dearborn, MI 48121

Re: Arrowhead General Insurance/Clarendon National Insurance Co. (Clarendon)  
Clarendon Insured: [REDACTED]  
Date of Loss: 04/01/02  
Clarendon Claim No: [REDACTED]  
Loss location: 75 Leuba Road Coventry RI  
Damages: \$9,661.35 (inclusive of \$500 deductible)  
Vehicle: 1997 F-150 Ford Truck VIN 46684  
Recall Number: 00522-Fuel Line Inspection

OCT 29 2003

Dear Ms O'Neill,

Please be advised that Subrogation Partners represents Clarendon with respect to the recovery of the above-referenced loss.

Clarendon has paid its insured damages arising out of this occurrence. Upon issuance of any payment to their insured or on their behalf, Clarendon receives the right of recovery for all monies expended on the loss, including any applicable deductible.

[REDACTED] pick up truck caught on fire while the truck was parked in the driveway. Enclosed for your review is a copy of police report detailing the incident.

Kindly contact me to resolve any disputes, and submit this letter to the liability carrier for further claim handling.

Thank you for your prompt attention and assistance in this matter.

Respectfully

  
Marina Cheung  
Subrogation Partners  
866-697-8276 x 1174  
mcheung@subropartners.com

Enclosure

EAS-605-LC1-0522



**UNITED AUTOMOBILE INSURANCE COMPANY**

P.O. BOX 600580 • NORTH MIAMI, FL 33160

305-940-7299 • 954-462-6883


SEPTEMBER 17, 2004

FORD MOTOR CO.  
CONSUMER AFFAIRS  
P.O. BOX 6248MD-3NE-B  
DEARBORN, MI. 48126

CONSUMER AFFAIRS  
SECTION

4 SEP 21 PM 102

Re: Our Insured: [REDACTED]  
Claim No.: [REDACTED]  
Policy No: [REDACTED]  
Date of Loss: 08/03/03  
Your Claim/File No: UNKNOWN  
Company Payment: \$7,335.00 (includes salvage proceeds of \$2,000.00)  
Insured's Deductible: \$1,000.00




Dear SIR/MADAM:

Our above insured's vehicle-1997 Ford F-150 XLT 2 Dr. Ext. Cab P/U was properly parked with engine turned off. Our insured was notified by a witness advising his vehicle was in flames. The Miami-Dade Fire Department was called and they finalized their investigation advising fire originated from the engine compartment. Our licensed appraiser states fire was caused by a wire short. As a result of this loss, we have paid our insured, and our insured has paid his/her deductible interest, in the amounts stated in the caption of this letter.

Our investigation establishes that there is a recall on this particular model for electrical problems. Therefore, under our right of subrogation, we request reimbursement for both the company payment and deductible amount shown above. We did not pay our insured for his out of pocket expense regarding rental. Therefore, we are not seeking reimbursement for loss of use. Enclosed are our supporting documents for your review.

We have diaried our files for (15) fifteen days. Your prompt attention to this matter will be appreciated.

Sincerely,  
  
Jose Lopez  
Subrogation Department  
(305) 940-7299, ext. 2214  
Enclosure: Supporting Documents

OC1/15 DAYS

E905-B05-LC1-0535

RECORD

82

## FIRE / PROPERTY RECORD

FIRE RESCUE INCIDENT REPORT MAHARAJA COUNTY, FLORIDA

UNIT REPORTING

329

SHIFT

C

DEPT	INCIDENT NUMBER	INCIDENT ADDRESS
30	9114757080303	1240 SW 52AVE
PROPERTY ADDRESS	TIME REPORTED	
1240 SW 132 AVE	2:08	
OWNER NAME	LAST NAME	FIRST NAME
STRUCTURE TYPE	STORIES & HEIGHT	SQUARE FEET
1	11	2
OCCUPANT NAME	SPECIFIC PROPERTY	MOBILE PROPERTY
	411	
APPARENT DAMAGE	APPARENT DAMAGE	CONDOFFICE
ON 1ST UNIT ARRIVAL	WHEN FIRE OUT	ON ARRIVAL
5	5	7
DETECTOR TYPE	POWER SUPPLY	PERFORMANCE
8	8	8
PROPERTY DAMAGE NUMBER	TOWNSHIP	POWER COMPANY
YEAR	MAKE	MODEL
EQUIPMENT INVOLVED	TYPE MATERIAL INVOLVED	TYPE MATERIAL INVOLVED
98 8 Exempt	19 Slave Component	23 Farm vehicle
FROM HEAT IGNITION	IGNITION FACTOR	STATUS OF LOSS
69 open flame	93 Exposure	100
AREA OF ORIGIN	LEVEL ORIGIN FIRE	CONTENTS
83 vehicle/engine	31	0
INVESTIGATOR	DATE	
GROUND AERIAL	WALLS TO BEYOND	TOTAL USED
LAUNDRY LARDED		
2 (T/M)	20	30
INJURY	DEATH	
02	0	
PROP INVOLVED	DEATH	
02	0	
5-24	8-3-13	

5-24 arrived to find auto fire next to his property in front of garage door. Property damage involves car dripping off roof of garage door and burning vehicle to vehicle.

REMARKS

Video - Original Video - LEO PAK - Screen

KRO-905-LC1-6536

OFFENSE INCIDENT REPORT

~~FOUO-005-LC1-0537~~

08032003

MAH-DADE POLICE DEPARTMENT

415293B

VEH FIRE

NONE

217 9 9 2 1997 FORD F-150 TRUCK

FL 73 16374954 REG.

TEXEX 17L9VN

SILVER

BURNED

EXCALIBUR

74294 SW1428

217 9 9 R VEH ENGINE

8000.00

217 9 9 X OVERHANG DAMAGE

800.00

TOTAL DAMAGE \$ 8800.00

MS. DAKER

3953-B1

H-1102

8-703

## MIAMI-DADE POLICE DEPARTMENT

## VEHICLE STORAGE RECEIPT

MIAMI-DADE COUNTY, FLORIDA

OTHER DEPT.  
CASE NO.

CASE NO.

415293-B

YEAR 1977	MAKE FORD	MODEL F-150	COLOR SID.	BODY TYPE TK	TAX NO.	VR 03	STATE FL	DECAL NO. 16374954	VR
--------------	--------------	----------------	---------------	-----------------	---------	----------	-------------	-----------------------	----

LOCATION VEHICLE TOWED FROM

VEHICLE IDENTIFICATION NUMBER

1FTEX1769VN

DATE AND TIME TOWED

8-3-03

REASON

VEHICLE FIRE INVESTIGATION

OPERATOR

NONE

INCARCERATED

YES NO

HOLD FOR (INDIVIDUAL AUTHORIZING HOLD)

ARSON INVEST.

INDIVIDUAL REQUESTING PROCESS

ENGINE #9 FIRE ARSON INVESTIG.

DATE AND TIME CONTACTED

REASON FOR HOLD

POSSIBLE ARSON

VEHICLE TO BE PROCESSED BY: (BUREAU/SECTION/UNIT)

## JOINT PROPERTY INVENTORY TAKEN BY OFFICER(S) AND TOW DRIVER (CHECK APPROPRIATE ITEMS)

RADIO	<input checked="" type="checkbox"/> SPARE TIRE	<input checked="" type="checkbox"/> FOG LIGHTS	<input type="checkbox"/> AIR CONDITIONER	<input checked="" type="checkbox"/> KEY IN IGNITION	YES	NO
TAPE DECK	<input checked="" type="checkbox"/> TIRE CAPS	<input type="checkbox"/> HUB WHEELS	<input type="checkbox"/>	<input type="checkbox"/> TRUNK LOCKED	YES	NO
WHEELS	<input checked="" type="checkbox"/>	<input type="checkbox"/> HEATER	<input type="checkbox"/>	<input type="checkbox"/> REGISTRATION PAPERS	YES	NO

MISCELLANEOUS PROPERTY IN VEHICLE (TOOLS, CLOTHING, ETC.)

MESSAGE CENTER INFORMATION

OPERATOR

TIME 147A

NCH RESULTS: NEG

FCIC RESULTS: NEG

PROPERTY RECEIPT YES NO (CIRCLE)

(ENTER NUMBER OF ITEMS VISIBLY DAMAGED AND/OR MISSING)

STANDARD PARTS: MISSING DAMAGED

WHEELS	TRANSMISSION	ENGINE	MISSING DAMAGED
HEATER	HOOD	REAR END	
LIGHTS	DOOR(S)	WINDOW(S)	
GENERATOR	SEAT(S)	PENNER(S)	
BATTERY	TIRE(S)	OTHER	

SIGNATURE OF DRIVER AND/OR DRIVER IF RELEASED AT SCENE

WE, THE UNDERSIGNED OFFICER(S) AND TOW TRUCK DRIVER, HEREBY CERTIFY THAT THE ABOVE LISTED JOINT PROPERTY INVENTORY IS CORRECT TO THE BEST OF OUR KNOWLEDGE.

*[Signature]*  
TOW TRUCK DRIVER

M. DAKER *[Signature]*  
INVESTIGATING OFFICER(S)

BADGE NO. 13953 DEPT 30 DISTRICT 4

DATE RELEASED TO (ENTER NAME)  
DRIVER LICENSE NO.

## GENERAL INSTRUCTIONS TO GARAGES AND VEHICLE OWNERS

- Vehicles without HOLD ORDERS become the responsibility of the garage at time of tow-in and may be released without Miami-Dade Police Department authorization.
- Vehicles with HOLD ORDERS must have written authorization from the Miami-Dade Police Department. Release may be authorized by:

(INVESTIGATING UNIT) Telephone

Documents required for release are:

- Valid Driver's License and
- Vehicle Title or
- Current Registration or
- Other proof of right to possession.

Release will be facilitated by presentation of this Vehicle Storage Receipt.



















BOAT INFORMATION			
YEAR	MAKE	REGISTRATION NO.	SIZE
SERIAL NO.			COLOR

MIAMI-DADE POL. 201

THE VEHICLE STORAGE RECEIPT


RECORDS BUREAU COPY


FBI-005-LC1-0538



[REDACTED] 9/17/04







## FORT WORTH FIRE DEPARTMENT INVESTIGATIVE REPORT

F.D. 856  
04-01-93

INCIDENT NO. 47640	EXP. NO.	MONTH 09	DAY 10	YEAR 00	DAY OF THE WEEK SUNDAY	ALARM TIME 0025	DISTRICT 6
CORRECT ADDRESS NO. 3713	DIR.	NAME			TYPE Dr	ZIP CODE	BOX NO. 3123
OCCUPANT NAME: LAST Vehicle		FIRST		ML	TELEPHONE		ROOM OR APT.
OWNER NAME: LAST		FIRST		ML	NO.	DIR.	NAME
CITY Fort Worth		ST.		ZIP CODE		TELEPHONE 232-1506	
ESTIMATED OR ACTUAL		STRUCTURE VALUE		CONTENTS VALUE		STRUCTURE LOSS	
INSURED						8,500	
INSURANCE COMPANY NAME State Farm					AGENT Mike Davis		
TYPE OF SITUATION FOUND Vehicle fire				TYPE OF ACTION TAKEN Investigate			
IF MOBILE PROPERTY:		MAKE 1995 Ford	MODEL PU	SERIAL NO. 1FTEX15NXSE	LICENSE NO. (IF ANY) Tx PGJ 632		
IF EQUIPMENT INVOLVED IN IGNITION:		MAKE	MODEL	SERIAL NO.	VOLTAGE (IF ANY)		
COMPLEX Vehicle Storage				DOING BUSINESS AS			
FIXED PROPERTY USE Garage				MOBILE PROPERTY TYPE Automobile			
STRUCTURE TYPE		CONSTRUCTION TYPE		CONSTRUCTION METHOD			
EXTENT OF FLAME DAMAGE		EXTENT OF SMOKE DAMAGE		EXTENT OF WATER DAMAGE		EXTENT OF FIRE CONTROL DAMAGE	
LEVEL OF ORIGIN Grade		AREA OF ORIGIN Engine Area		TERMINATION STAGE Flame			
EQUIPMENT INVOLVED IN IGNITION Undetermined				FORM OF HEAT IGNITION Electrical			
TYPE OF MATERIAL IGNITED Undetermined		FORM OF MATERIAL IGNITED Undetermined		IGNITION FACTOR Electrical Failure			
DETECTOR PERFORMANCE		INJURIES		FATALITIES		MULTIPLE ALARM	
OFFICER IN CHARGE (NAME, POSITION, ASSIGNMENT) Parker, Battalion 6 Chief				MEMBER MAKING REPORT (IF DIFFERENT) T.L. Crow			

## REMARKS:

This incident was a vehicle fire that was investigated at the above stated address. The area of the fire was in the engine compartment on the left side of said vehicle. The fire's point of origin is undetermined at this time. Evidence indicates that an electrical failure occurred causing fire to spread throughout the compartment into the passenger area. In addition, the exterior was heavily damaged. This officer notes that another vehicle was also located inside the garage at the time of this accidental fire.

TARRANT WEST  
SEP 29 2000  
FIRE CLAIMS

8741-090

EWS-005-LC1-0542

## FORT WORTH FIRE DEPARTMENT INVESTIGATIVE REPORT

F.D. 856  
04-01-93

INCIDENT NO. <b>47640</b>	EXP. NO. <b>01</b>	MONTH <b>09</b>	DAY <b>10</b>	YEAR <b>00</b>	DAY OF THE WEEK <b>SUNDAY</b>	ALARM TIME <b>0025</b>	DISTRICT <b>6</b>
CORRECT ADDRESS NO. <b>3713</b>	DIR.	NAME <b>Periwinkle</b>			TYPE <b>Dr</b>	ZIP CODE <b>[REDACTED]</b>	BOX NO. <b>3123</b>
OCCUPANT NAME: LAST <b>Vehicle</b>		FIRST		MI.	TELEPHONE		ROOM OR APT.
OWNER NAME: LAST <b>[REDACTED]</b>	FIRST	MI.	NO.	DIR.	NAME		TYPE
CITY <b>Fort Worth</b>				ST. <b>Tx</b>	ZIP CODE		TELEPHONE <b>[REDACTED]</b>
ESTIMATED OR ACTUAL		STRUCTURE VALUE		CONTENTS VALUE		STRUCTURE LOSS <b>18,000</b>	CONTENTS LOSS
INSURED							
INSURANCE COMPANY NAME <b>State Farm</b>					AGENT <b>Mike Davis</b>		
TYPE OF SITUATION FOUND <b>Vehicle fire</b>				TYPE OF ACTION TAKEN <b>Investigate</b>			
IF MOBILE PROPERTY: MAKE <b>1998 Mazda</b>				MODEL <b>4-Dr</b>		SERIAL NO. <b>1YVGFZZCZV</b>	
IF EQUIPMENT INVOLVED IN IGNITION: MAKE				MODEL		SERIAL NO. <b>[REDACTED]</b>	
COMPLEX <b>Vehicle Storage</b>				DOING BUSINESS AS			
FIXED PROPERTY USE <b>Garage</b>				MOBILE PROPERTY TYPE <b>Automobile</b>			
STRUCTURE TYPE		CONSTRUCTION TYPE		CONSTRUCTION METHOD			
EXTENT OF FLAME DAMAGE		EXTENT OF SMOKE DAMAGE		EXTENT OF WATER DAMAGE		EXTENT OF FIRE CONTROL DAMAGE	
LEVEL OF ORIGIN <b>Grade</b>		AREA OF ORIGIN <b>Exterior Surface</b>		TERMINATION STAGE <b>Flame</b>			
EQUIPMENT INVOLVED IN IGNITION <b>None</b>				FORM OF HEAT IGNITION <b>Heat from direct flame</b>			
TYPE OF MATERIAL IGNITED <b>Multiple</b>		FORM OF MATERIAL IGNITED <b>Multiple</b>		IGNITION FACTOR <b>Exposure fire</b>			
DETECTOR PERFORMANCE		INJURIES		FATALITIES		MULTIPLE ALARM	
OFFICER IN CHARGE (NAME, POSITION, ASSIGNMENT) <b>Parker, Battalion 6 Chief</b>				MEMBER MAKING REPORT (IF DIFFERENT) <b>T.L. Crow</b>			

## REMARKS:

This incident was an exposure fire involving the above stated vehicle at the address stated above. The area of the fire involved the entire vehicle. Evidence indicates that fire spread from the original car fire throughout the garage over to this vehicle, causing heavy fire, heat, and smoke damage to both the interior and exterior, resulting in a total loss.



Photo No. 1

Location/View

*Back*




Photo No. 2

Location/View

*Truck that fire  
started in -  
sign of to driveway*



Photo No. 3

Location/View

*Car that  
was parked next to  
truck*

Date/Time

*9/11/00*

By

**BLAD GUSTAF**



Photo No. 4

Location/Room

*Bike, minor damage*



Photo No. 5

Location/Room

*Bed headboard &  
footboard &  
golf clubs found*




Photo No. 6

Location/Room

*Garage  
door locked*

Date/Time

*9/11/0*

By

**LEAD CENTER**



Photo No. 7

Location/View

*Grange constants  
burned*



Photo No. 8

Location/View

*Waves burned*



Photo No. 9

Location/View

*Grange  
constants burned*

Date/Time

*9/1/00*

By

**BRAD CHURCH**




Photo No. 10  
 Location/View  
*Gring emerging  
 band of*




Photo No. 11  
 Location/View  
*Front  
 soffit-burned*



Photo No. 12  
 Location/View  
*Front soffit & fascia  
 smoked & burned*  
 Date 9/11/00  
 By  
 REAS GUNTER






Photo No. 13

Location/View

Rear side of the  
smokestack



Photo No. 14

Location/View

Left side - doorway &  
soffit




Photo No. 15

Location/View

A/C  
ducts, outside  
grange as well as  
electrical

Date/Time 9/11/00

By

HEAD OFFICE



Photo No. 16

Location/View

Back side  
smoked



Photo No. 17

Location/View

Front slope back  
matted



Photo No. 18

Location/View

Front right slope  
matted & soot

Date/Time

9/11/00

By

ELAS SHERIFF




Photo No. 19

Location/View

Left slope  
rather well covered



Photo No. 20

Location/View

Back slope - mostly  
barren & shrubby




Photo No. 21

Location/View

Left slope over  
surge to walk

Date/Time 9/11/00

By

BLANCK GUNTER




Photo No. 22

Location/View

Front slope over

grass  
thickly bed



Photo No. 23

Location/View

Front porch

ceiling removed



Photo No. 24

Location/View

Roof toward

door area -

emergency board up

Date 9/11/00

By

BLAD CHARTER



Photo No.

25

Location/View

Storage back  
left - hot  
with hts & elect.




Photo No.

26

Location/View

Storage Back  
right Central  
air unit &  
straw



Photo No.

27

Location/View

Storage - hot water  
heater

Date/Time

9/11/00

By

JEAN CHAPPEL




Photo No. 28

Location/View

*Along airframe*



Photo No. 29

Location/View

*Door open*



Photo No. 30

Location/View

*A/C lines in other*

Date/Time

*9/11/00*

By

**BRAD GIBSON**

EGG-005-L01-0053



Photo No. 31

Location/View

Left side of  
house




Photo No. 32

Location/View

Central air unit




Photo No. 33

Location/View

Front door &  
entry overview

Date/Time 9/11/00

By

BLAD CROFT



Location/View

gray dim into  
Entry



Photo No. 95

Location/View

Entry hall  
corridor switch




Photo No. 96

Location/View

in Rm over  
from entry

Date 9/11/00

By

SEAN GIBLIN





Photo No. 37

Location/View

Li Brit Kitchen  
 Area Area



Photo No. 38

Location/View

Kitchen area  
 outside



Photo No. 39

Location/View

Dining  
 area outside

Date/Time 9/11/00

By

BLAS GARCIA



Photo No. 90

Location/View

Lin. in view from  
Litch



Photo No. 91

Location/View

Utility room sent




Photo No. 92

Location/View

Utility room  
Delivery

Exposure 9/11/00

By

SEAS GUNITE



Photo No. 43

Location/View

Master Bedroom

Photo No. 44

Location/View

Master closet  
door

Photo No. 45

Location/View

Bathroom  
area to Master Bed  
room

Date/Time

9/11/00

By

LEAD GROUP



46

Meta Beth sent  
Chaz




Photo No. 47

Location/View

Leone-Belen  
Admission



Photo No. 48

Location/View

Sturdy Overview

Date/Time 9/11/00

By

BLAS GONZALEZ



Photo No. 47

Location/View

Hall bed

Ordnance

Photo No.

Location/View

Photo No.

Location/View

Date/Time 9/11/00

By

BLAD CHEN

and paper



**INVESTIGATIVE CONSULTANTS, INC.**

**CAUSE & ORIGIN REPORT**

ICI FILE # 200-09-330

CLAIM #: [REDACTED]

**TARRANT WEST**

**OCT 10 2000**

**PREPARED FOR:**

**STATE FARM INSURANCE COMPANY  
REQUESTOR: BRAD GRIFFITH**

**PREPARED BY:**

**DAVID J. BRISTOW  
FIRE INVESTIGATOR**

All information contained within this report is privileged and confidential. Reports are furnished to our clients only, and release of any and all information contained within them is the sole responsibility of the client.

**CONFIDENTIAL**

**INVESTIGATIVE CONSULTANTS, INC.**  
2205 W. DIVISION, SUITE #G-3  
ARLINGTON, TEXAS 76012  
METRO (817) 469-1848 LOCAL (817) 459-0922

NAME: [REDACTED]	TYPE OF INVESTIGATION:
CLAIM #: [REDACTED]	CAUSE & ORIGIN
ICI #: 200-09-330	ACCOUNT #: 292
DATE OF LOSS: 9/10/00	REPORT DATED: 10/5/00
LOSS LOCATION:	REQUESTOR: BRAD GRIFFITH
[REDACTED]	PHONE #: (817) 735-3738
PORT WORTH, TEXAS [REDACTED]	

**REQUEST:** The investigation was authorized on 9/11/00, by Mr. Brad Griffith, a claims representative with State Farm Insurance Company. The purpose of this investigation was to determine the cause and origin of a fire that occurred on 9/10/00, located at [REDACTED] Fort Worth, Texas.

**ENCLOSURES:**

1. Recall information from the National Highway Traffic Safety Administration.
2. Copies of Fort Worth Fire Dept. Investigation Reports
3. Photograph Documentation

**PERSONS CONTACTED:**

1. Christopher Miller - Insured

**INSURED PROPERTY:** The insured property consisted of the building and contents of a single story family residence. The building was of ordinary wood construction, covered with brick veneer siding and was resting on a concrete slab foundation.

The building was supplied with electrical power at the time the fire occurred. Climate control to the residence was provided by electrically operated central heating and air conditioning units. The structure appeared to be in good condition at the time of the fire. The structure was located in a residential neighborhood of similar type value structures and was protected by the Fort Worth Fire Department.

Also located within the residence were two vehicles, one being a 1995 Ford F150 pickup truck and the other was a 1998 Mazda 626. The Ford pickup reportedly was in the area where the first fire was discovered and it was considered to be the area of origin.

NAME: [REDACTED]

PAGE #: 2

CLAIM #: [REDACTED]

**CONFIDENTIAL**

**FIRE SCENE EXAMINATION:** The fire scene examination commenced on 9/13/00 at approximately 10:00 a.m. Photographs of the residence and the vehicles were made, however, a field diagram was not prepared, at the direction of the State Farm representative. Present throughout the majority of my investigation was the insureds, [REDACTED]

Although the fire scene had been altered by the fire department, as well as other personnel during their salvage and overhaul operations, I did not consider their actions to be adverse relative to my cause and origin determination. Near all of the contents, as well as the vehicles, had been removed from the garage area where the fire had initiated prior to my investigation.

The property surrounding the structure was examined, finding no evidence of fire damage beyond the immediate perimeter of the structure. During the exterior examination no evidence was discovered to indicate any type of low order explosion or abnormal pressure buildups had occurred prior to or during the fire.

An exterior examination of the residence was conducted in an effort to identify all areas of fire involvement within the confines of the building, possible points of forced entry to the structure, as well as fire ventilation patterns through the exterior walls and/or roof. During this preliminary exterior examination heat and soot patterns were noted extending from the soffit area above the garage door. The majority of heat and smoke was confined to the southwest portion of the garage area. It should be noted that the metal doors and its associated framing components around the doors had been removed prior to the fire scene examination. The doors within the garage area were examined, finding the greatest amount of heat stressing was within the area where the 1995 Ford pickup was parked. During the remainder of the exterior examination no other areas of major fire involvement was noted.

An inspection of the interior living quarters revealed only minor heat and soot damage in the hallway leading into the den area. As shown in photographs #5 and #6, in the areas within the den, kitchen and dining areas, soot accumulations were noted along the upper portions of the ceiling. However, there was no evidence of direct flame impingement into this region. As shown in photograph #7, the entryway into the garage from the hallway of the den revealed some soot staining on the sheet rock partition wall directly above the door. The interior side of the garage door was also heavily charred. The burn patterns and combustion effects noted during the interior examination of the structure revealed that the fire was confined within the southwest portion of the structure which consists of the garage area.



NAME: [REDACTED]  
CLAIM #: [REDACTED]

PAGE #: 3

**CONFIDENTIAL**

---

An examination of the garage area revealed the majority of the contents had been removed with the exception of some wooden products and some charred cardboard boxes. There were other small items of contents within the garage, however, this was not inventoried.

An examination of the burn patterns within the garage area revealed heavy soot accumulations and some heat deterioration on the ceiling sheetrock. Within areas in the west portion of the garage the sheetrock had either collapsed or had been pulled down by the fire department during their fire suppression activities. Heavy soot accumulations were noted extending to the mid point of the unfinished sheetrock wall and it appeared that the greatest amount of heat deterioration was within the northwest portion of the wall partition (refer to photograph #9).

The burn patterns indicated that the fire had originated within the west portion of the garage where the 1995 Ford pickup was located. However, as the fire had extended from the vehicle, flames had entered into the attic cavity through the pull down staircase, as shown in photograph C#10. As flames entered into the attic cavity region, portions of the ceiling joists, roof trusses and other wooden framing members in the area of the pull down staircase. An examination of the visible branch circuit wiring within this area revealed some of the insulation was melted, however, there was no evidence of electrical faults and there were no indications that the fire had originated within the attic cavity region. Burn patterns clearly indicated that fire had migrated from the Ford pickup into the attic cavity.

An examination of the garage for any possible ignition sources was conducted. The examination of the electrical circuitry within the garage was conducted, finding the structure's panel breaker box was located on the northwest exterior wall of the garage. An examination of the breakers revealed that they were all in the OFF position at the time of the fire scene examination. It was apparent that a person or perhaps the fire department had turned the breakers to the OFF position. According to the insured, at the discovery of the fire, electrical power was still supplied to the structure and there was no interruption of power until later in the progression of this incident.

According to the insured, he had a small battery charger plugged into a power strip which had received its power from a duplex receptacle located on the north wall of the garage. A portion of the power strip had received some fire damage which had melted the insulation of the power strip. An examination of the remains of the power strip revealed no evidence of electrical faulting and no indications that the fire had initiated at or near where the power strip was located. According to the insured, a battery charger was plugged into the power strip and was later found in the debris on the exterior of the residence. An examination of the remains of the battery charger, as

EA05-002-1C1-0064

NAME: [REDACTED]  
CLAIM #: [REDACTED]

PAGE #: 4

**CONFIDENTIAL**

shown in photographs #26 and #27, revealed that it was slightly melted, however, there was no indications of any internal heating of the batteries or the electrical components. The power cord to the batteries was fire damaged but no electrical faults were noted on the battery. It should be noted that after the discovery of the fire, the insured was standing near the area where the battery charger was plugged in and there was no evidence of visible fire.

The duplex receptacle where the power strip was plugged into was examined, finding it to be externally damaged, however, there were no indications of electrical faulting of the wiring to the receptacle. A visual examination of the receptacle revealed that it was in relatively good condition and no arcing in the internal components of the receptacle was noted. As shown in photograph #19, the two components (the power cord to the receptacle and the remains of the stab blades for the battery charger) was examined, finding no evidence of internal heating or electrical arcing.

During the course of the examination other electrical components in the garage were examined such as the electrical door opener. As shown in photograph #20, the electrical door opener had suffered some exterior heat damage, however, there was no evidence of electrical faulting that could be attributed to initiating the fire. It is significant to note that at the discovery of the fire, the insured was able to activate the garage door opener and it opened properly.

The central heating and air conditioning unit, which is located in the northeast portion of the garage, was surface damaged, but there was no indication of internal faulting of the wiring within the central heating and air conditioning unit. Also noted during the interview with the insured, the central heating and air conditioning unit was operating properly after the discovery of the fire. He did state that as he heard the unit come on, shortly after he began to smell smoke emitting from the vents within the structure.

The water heater, which is electrically operated, is located in the northwest portion of the garage, was examined, finding the painted surfaces of the water heater was fire damaged, however, there were no indications that the fire had originated within the water heater itself. The power cords to the water heater, as shown in photograph #22, was fire damaged and the insulation was partially consumed in a small area near the connection of the water heater. An examination of the power cord for evidence of electrical faults was conducted and none were found. The damage to the water heater was a result of external flame impingement from the Ford pickup.

After examining the garage area and eliminating any other possible ignition sources, the debris that had been removed from the garage and had been placed on the southwest portion of the garage was examined. The debris consisted of metal storage cabinets and

NAME: [REDACTED]  
CLAIM #: [REDACTED]

PAGE #: 5

**CONFIDENTIAL**

an assortment of garden supplies and other contents. According to the insured, at the discovery of the fire the contents of the metal stand, as well as any appliances positioned on the stand, were not involved in the fire. Several extension cords and other electrical appliances were noted in the debris and were examined, finding none were energized at the time of the fire. Apparently, in the progression of the fire, the metal stand was heat stressed to the point that it collapsed and had fallen against the vehicle. During the examination of the contents no evidence of electrical faulting were noted in the electrical appliances and there were no indications that the fire had originated within the storage area in the northwest portion of the garage.

As previously stated, two vehicles were parked in the garage at the time the fire occurred. One being a 1995 Ford F150 pickup which was positioned in the west portion of the garage. The vehicle was bearing Texas license [REDACTED] and the VIN was 1FTEX15NXXSK [REDACTED]. The other vehicle being a 1998 Mazda 626 bearing Texas license [REDACTED] and the VIN was 1YVGFZZCZV [REDACTED]. The burn patterns noted during the initial examination of the vehicles revealed the area of most fire damage had occurred within the 1995 Ford pickup. The burn patterns on the Mazda vehicle were external fire damage and was the result of flames extending from the Ford pickup.

An examination of the burn patterns within the Ford pickup revealed the majority of the painted surfaces in the forward portion of the vehicle was consumed. Flames had also extended to the roof line of the vehicle, consuming the paint and melting the plastic molding, as well as some of the chrome components. During the initial examination of the vehicle it was noted that the hood shell was missing and was discovered in the fire debris. The burn patterns indicated a greater amount of heat stressing on the left side of the hood. Flames had also extended along the right side of the vehicle, consuming a large portion of the paint along the area toward the bed of the vehicle. However, the burn patterns indicated that the damage was the result of flames extending from the engine compartment. The lights, lenses and chrome components of the vehicle were more heavily damaged in the front portion of the vehicle. The rear taillight assemblies, as shown in photograph #32, were in relatively good condition, with the exception of light soot accumulations.

The tires and wheels were examined, finding the two front tires were fire damaged and deflated. The two rear tires were still inflated and only minor fire damage was noted. The window glass was inspected, finding all of the glass was heat fractured and had collapsed from the frames.

An examination of the undercarriage of the vehicle revealed no major areas of heat stressing with the exception of the left front portion of the suspension. The main frame of the vehicle was in relatively good condition and no evidence that the fire had

NAME: [REDACTED]  
CLAIM #: [REDACTED]

PAGE #: 6

**CONFIDENTIAL**

originated within the undercarriage of the vehicle. The damage noted in the left front area was a result of the combustion and collapse of the combustible materials in the engine compartment.

An examination of the passenger compartment revealed a large portion of the upholstery was fire damaged, along with heavy charring to the foam padding. The burn patterns within the upholstery of the vehicle indicated that flames had extended from the engine compartment into the passenger compartment. The greatest amount of fire damage was noted within the instrument panel area, where flames had extended through the fire wall and consumed a large portion of the plastic and vinyl components of the instrument panel. The right side of the instrument panel, as shown in photograph #39, was melted and collapsed within the floorboard area. An examination of the wiring harness within the instrument panel area was conducted, finding the conductors were fire damaged and some of the insulation was consumed. However, an examination of the conductors did not reveal any evidence of electrical fault conditions. The ignition system attached to the steering column area was also examined, finding it to be externally fire damaged, however, there were no indications that the fire had initiated around the ignition system (refer to photograph #40). While examining the instrument panel area the fuse box was examined, finding 3 fuses to be BLOWN. As depicted in photograph #41, a 25 amp, a 10 amp and a 15 amp fuse were BLOWN. The identification plate for the fuses was not identifiable, therefore, no determination could be made as to what these fuses protected.

An inspection of the other electrical components in the instrument panel area revealed the stereo system was externally fire damaged, however, there were no indications of an internal failure within the radio. The debris within the floorboard was also removed, finding no evidence of concentrated fire damage within the lower portions of the passenger compartment. The damage noted within the floorboard was a result of the molten burning plastic from the instrument panel collapsing to the floor area.

An examination of the engine compartment revealed heavy fire damage throughout which had consumed near all of the belts, hoses and plastic reservoirs. The burn patterns indicated that the fire had originated within the left side of the engine compartment and flames had migrated across the upper portions of the engine. As a result of this flame extension, some melting to the light alloy metal products in the engine had occurred. Portions of the aluminum tubing for the air conditioning system was either fire damaged or totally melted. A large area of the radiator and air conditioning condensing coils was also melted on the left side of the vehicle.

An examination of the engine compartment began with an inspection of the electrical circuitry, including the battery. The battery, as shown in photograph #45, was severely

NAME: [REDACTED]  
CLAIM #: [REDACTED]

PAGE #: 7

**CONFIDENTIAL**

fire damaged and the casing was melted to a point that it exposed some of the interior plates. The battery posts were also melted, which had allowed the battery cable clamps to be partially displaced from the battery. An inspection of the battery cables revealed most of the insulation was consumed, however, no faults were noted on either the positive or negative cables. A solenoid mounted to the right front fender well, which receives it's power directly from the battery, was examined, finding that the Bake-Lite casing was severely heat stressed, however, a major portion still remained attached to the solenoid. An examination of the conductors attached to the solenoid did not exhibit any evidence of electrical faulting or internal heating.

The alternator was examined, finding the casing to be externally fire damaged and the plastic portions of the connections to the alternator were melted. The debris was removed around the connections, finding no evidence of electrical faulting in the connections or within the windings of the alternator.

The wiring harness routed along the front portion of the engine compartment to the left side of the vehicle was noted to be void of insulation and some of the conductors were broken in two as a result of external heating. The conductors were separated as shown in photograph #50, finding no evidence of internal heating in this particular section of wiring. The remainder of the wiring harness in the left side of the engine compartment was examined, finding most to be void of insulation and was annealed and some of the conductors had broken in two. It appeared that the greatest amount of heat stressing to the wiring harness was in the left side.

The power distribution center, which is also positioned in this area, was severely fire damaged and had consumed most of the fuses and the plastic covers for relays in the power distribution center. The wiring to and exiting from the power distribution center was examined, finding the conductors were void of insulation and were heat stressed. During the separation and examination of the main wiring harness on the left side of the engine compartment, evidence of electrical fault conditions were noted in the mid section of the wiring bundle. As shown in photographs #56 and #57, the various conductors had electrically faulted and some had fused together. The fault conditions noted on the conductors corresponded with the burn patterns in the engine compartment and indicated that this was the area of the fire's origin. After the wiring harness was partially separated and the fault conditions were photographed, the faulted area of the wiring harness was covered and taped for preservation of the evidence. While examining other portions of the wiring harness in the left side of the engine compartment, some smaller gauge circuits routed from the left side of the engine compartment toward the engine was also found to be annealed and some of the stranded wire conductors were broken. As shown in photograph #54, some of these smaller gauge conductors did have some molten

NAME: [REDACTED]  
CLAIM #: [REDACTED]

PAGE #: 8

**CONFIDENTIAL**

aluminum adhering to the conductors and the damage in melting to the conductors may be the result of eutectic melting.

During the course of the examination of the engine compartment the fuel system was examined, finding that the air filter system was totally consumed from the throttle body. A small portion of the throttle body had melted as a result of the fire. The rubber sections of the fuel lines, as well as some of the vacuum hoses, were also consumed in the fire. The fuel rail and injectors were examined, finding no evidence of fuel leaks or any indications that the fire had originated within the fuel train system.

After examining the vehicle, the burn patterns indicated that the fire had originated within the left side of the vehicle at or near where the electrical faults in the wiring harness was discovered.

The 1998 Mazda which was parked on the east side of the garage was also examined, finding a large portion of the painted surfaces on the left side of the vehicle were consumed. The window glass in the vehicle was also more heavily damaged on the left side and the burn patterns indicated that the flames had extended from the Ford pickup. This was also confirmed by the insured that the Mazda was not involved at the discovery of the fire.

The interior of the vehicle was examined, finding the damage was a result of external flame impingement from the vehicle. The upholstery and other components were fire damaged, however, most of this damage occurred as the headliner was ignited and then collapsed to the seating area. There were no indications during the examination of the Mazda to indicate that the fire had originated within this area.

During the investigation interviews were conducted with [REDACTED] the insured. [REDACTED] stated that he had parked the Ford pickup in the garage at approximately 10:30 p.m. prior to the fire. He stated that shortly after 12:00 midnight he began to smell smoke shortly after he had heard the air conditioning system activate. He stated that he went to the garage and as he entered the garage he noticed smoke emitting from the left side of the engine compartment of the 1995 Ford pickup. He stated that he activated the electric door opener of the garage to allow the smoke to emit from the garage. He stated that the fire department was summoned and during the course of discovery of the fire he tried to extinguish the fire by applying water within the vehicle. He stated that a neighbor across the street also came with a fire extinguisher and they tried to extinguish the fire by using the fire extinguisher, however, it was to no avail. He stated that he did not open the hood and eventually the smoke was so intense that they had to leave the garage area. [REDACTED] stated that he was certain that the fire was only confined to the pickup due to the fact that he was able to get close enough to put water

NAME: [REDACTED]  
CLAIM #: [REDACTED]

PAGE #: 9

**CONFIDENTIAL**

on the vehicle and use a fire extinguisher. He also stated that there was no other items within the garage area that was involved at the discovery of the fire. [REDACTED] stated that when he was made aware of the fire that the electricity in the residence was still operative. He and his wife were watching television at the time of the fire and noticed no problems. He also stated that the electrical circuitry within the garage also appeared to be operating properly during the initial stages of the fire. He did state that the garage door operated properly when he activated the switch.

During the interview with [REDACTED] I inquired as to any previous problems with the vehicle. [REDACTED] stated that when last driving the vehicle he had noticed nothing unusual with the vehicle and everything appeared to be working properly. [REDACTED] stated that he had been out in the garage approximately an hour to 45 minutes prior to discovering the fire. He stated that at that time he had noticed nothing unusual in the vehicle. He stated that as far as maintenance on the vehicle, the last thing that he could remember was having the oil changed in July of 2000 and had brake work conducted in April, 2000. Other than these items [REDACTED] could not recall any other maintenance.

**CONCLUSION:** In conclusion it is my opinion that this fire originated within the southwest portion of the garage area, where the 1995 Ford pickup was parked. Furthermore, it is my opinion that the fire originated within the left side of the engine compartment of the Ford pickup. As noted in the report text, during the examination of the engine compartment, electrical fault conditions were noted in the wiring harness positioned in the left side of the engine compartment. As these electrical faults occurred, the wiring insulation and other combustible products in the engine compartment were ignited. Due to the fact that several circuits had electrically faulted, no specific circuit could be identified as the circuit that had initiated the fire. During the course of the examination no other ignition sources were discovered.

**INVESTIGATION CONDUCTED BY:**

David J. Bristow, CFEI  
Fire Investigator

DJB/la

**PHOTO #1:** Shows an exterior view of the front of the structure. Note that the structure is facing a southerly direction.


**PHOTO #2:** Shows an exterior view of the southwest portion of the structure.



#1



#2




**PHOTO #3:** Shows an exterior view of the southeast portion of the structure.

**PHOTO #4:** Shows a view of the front entrance. Note the entryway to the garage is to the left of the foyer.

#3



#4




ER05-005-LC1-8574


**PHOTO #5:** Shows a view of the den taken from the front entryway. Note there is only minor soot accumulations on the upper portions of the ceilings.

**PHOTO #6:** Shows a view of the kitchen and dining areas taken from the den. Note there is no significant fire damage with the exception of a light coating of soot.

#5



#6



**PHOTO #7:** Shows an opposing view of the front entryway taken from the den. Note the charred door is the entryway to the garage.

**PHOTO #8:** Shows a view of the southwest portion of the garage taken from the entryway from the foyer.

#7



#8



ER05-005-LC1-0575

**PHOTO #9:** Shows a view of the northwest portion of the garage. Note the greatest amount of heat deterioration to the ceiling sheet rock was in this area. Note the Ford pick up was parked beneath the severely heat stressed sheet rock.

**PHOTO #10:** Shows a view of the northeast portion of the garage and the entryway to the hallway.



#9



#10



**PHOTO #11:** Shows a view of the southeast portion of the garage. Note the damage to the ceiling and the wall partitions is not as severe. Note this is the area where the Mazda vehicle was positioned.

**PHOTO #12:** Shows a view of the pull down stairway located in the north portion of the garage. Note flames had consumed the plywood covering of the staircase and entered the attic cavity.

#11




#12



**PHOTO #13:** Shows a view of the attic cavity above the pull down stairway. Note some of the ceiling joists and roof trusses in the area were charred as a result of the flame extension. Note there were no indications that the fire had originated in the attic area.

**PHOTO #14:** Shows a view of the panel breaker box which is located on the northeast garage wall. Note all of the breakers were turned in the OFF position at the time of the investigation.

#13



#14



**PHOTO #15:** Shows a view of the power cord to a power strip plugged into a receptacle on the north wall of the garage.

**PHOTO #16:** Shows a close up view of the duplex receptacle and power cable to the power strip on the north wall of the garage. Note there was no electrical faulting in the power cord or the power strip.

#15



#16



**PHOTO #17:** Shows a view of the duplex receptacle where the power strip was plugged into. Note the insulation on the wiring was in good condition and there was no evidence of electrical faulting in the receptacle.


**PHOTO #18:** Shows a view of the remains of the power strip where the battery charger had received it's power. Note the outer casing was slightly melted but there was no evidence of electrical faulting.



#17



#18



**PHOTO #19:** Shows a view of the stab blades for the power strip and the battery charger. Note neither had evidence of internal heating or electrical arcing.

**PHOTO #20:** Shows a view of the garage door opener taken from the southwest portion of the garage. Note there was no electrical fault conditions that could be attributed to initiating the fire. Note also that it was operational after the fire was discovered.

#19




#20



**PHOTO #21:** Shows a view of the HVAC system which is located in the northeast portion of the garage. Note the exterior was fire damaged but there was no significant interior damage.

**PHOTO #22:** Shows a view of the electric water heater. Note the power cable was slightly damaged but there were no electrical faults noted in the conductors.

#21




#22



**PHOTO #23:** Shows a view of a portion of the contents that had been removed from the garage. Note an examination of the debris revealed no evidence of any electrical appliances that had failed.

**PHOTO #24:** Shows an opposing view of some of the contents removed from the garage.

#23



#24



**PHOTO #25:** Shows a view of some extension cords that were positioned on a metal storage tray. Note they were not energized at the time of the fire.

**PHOTO #26:** Shows a view of the remains of a battery charger that was positioned along the north side of the wall. Note the plastic storage chest was melted as a result of external flame impingement.



#25



#26




1005-225-LC1-0506

**PHOTO #27:** Shows a close up view of the battery charger. Note some of the batteries were removed and there was no evidence of internal failure in the battery charger. Note the power cord was void of insulation but no electrical faults were noted.

**PHOTO #28:** Shows a view of the left front portion of the vehicle prior to the examination. Note this is the 1995 Ford pickup.

#27



#28



**PHOTO #29:** Shows a view of the VIN plate on the 1995 Ford pick up.

**PHOTO #30:** Shows a view of the left rear portion of the vehicle.

