

Document Name: Session1

804367 - out 05

OTRNO CITY OF MIAMI FIRE-RESCUE
Alarm: 48384 FIRE INCIDENT REPORT (IRS)

VPI 788021

b/k

Data Received: 08/03/04

Time Received: 06:40 MPDS Reported:

Dispatched: 06:40 Found: F200 VEHICLE FIRE

Arrived: 06:45 Action Taken: 04 Extnsgshmnt/ FD w/ Handline(s)

Secured: 07:24

Address Reported: 830.NW.23.CT;

Corrected: 830.NW.23.CT;

Found: 830 NW 23 CT

Remarks:

Structure Loss:

Present Injured Dead

Content Loss:

Occupants:

Firefighters:

Hoses Used

Aerial Ladders Used For Feet 3/4 -1 lines at Feet

Ground Ladders Used For Feet 1 1/2 lines at Feet

Water Volume to Control 150 Gal 1 3/4 lines 1 at 200 Feet

Total Water Used 200 Gal 2 1/2 lines at Feet

3 Plus lines at Feet

Number of Properties: 1

Classifying Officer: PACE, JAMES F

Number of Unit Reports: 1

Report Cleared By: MARTI, NORBERTO

Number of Casualty Reports:



Date: 11/4/2004 Time: 2:48:53 PM

ER05-005-LC-3523

Document Name: Session1

OEQUO CITY OF MIAMI FIRE-RESCUE TRANS REPORT
Alarm: 48384 Date: 08/03/04 Property Class: 961 AUTOMOBILE
Address 000830 NW 23 CT Occupants
Structure Loss: Present:
Content Loss: Injured:
Ign Equipment: VEHICLE(INCLUDES ALL VEH FIRES Dead:
Form of Heat: HEAT FROM GAS FUELED EQUIPMENT
Type of Matl: CHEM,METAL,PLASTIC,PAINT-INSUF Owner: JOSE ALBRISA
Form of Matl: FUEL Addr: 830 NW 23 CT
Act or Omission: ACT OR OMISSION;(INSUF INFO) Phone: MIAMI FL
Area of Origin: TRANSP EQUIP-ENG AREA,RUN GEAR
Spread: Oper:
Type Constr: METAL (FERROUS) Addr:
Ext Flame Dam: CONFINED TO OBJECT OF ORIGIN Phone:
Ext Other Dam:
Obstacle: Dis by SAME
Alarm System: Addr:
Detect System: NO DETECTORS PRESENT Phone:
Sprinkler Sys:
Standpipe Sys: L-I-C:
Priv Fire Brig: Addr:
Phone:
Year made: 97 Make: FORD Model: F150
License tag: V21HV1 Year: 4 State/Country: FL

Date: 11/4/2004 Time: 2:48:54 PM

EA05-005-LC-3524

Document Name: Session1

REPO CITY OF MIAMI FIRE-RESCUE

PART AND EQUIP
Equip Used:

Alarm 48384 Date 08/03/04 Pd

Comp Disp Arr Xport Hosp 09 Remarks

E7 06:40 06:45 07:24

Personnel Present Injured Dead:

Material Led Used for feet 3/4-1 lines at feet
Ground Led Used for feet 1 1/2 lines at feet
Water Vol to Control 150 gal 1 3/4 lines 1 at 200 feet
Total Water Used 200 gal 2 1/2 lines at feet
Narrative: 3 PIs lines at feet

Conditions encountered:

CAR FIRE

Operations:

VEHICLE FIRE / FULLY INVOLVED/ OWNER OTS/ ADVISED THAT HE PARKED VEHICLE IN THE PM/ FIRE IN ENGINE COMPARTMENT/ EXTINGUISHED. MPD OTS FOR F/U/P REPORT

Date: 11/4/2004 Time: 2:48:55 PM

ER05-005-LC-3525

Interscience, Inc.

7705 Ann Ballard Road
Tampa, FL 33634-2334
(813) 885-4774
Fax (813) 889-9157

Our Project No: L1269-02
Insured: Unknown
Claim No: 804367
Date of Loss: Unknown
Date of Notification: November 3, 2004
Date of Inspection: November 15, 2004

Report
Prepared For:

United Automobile Insurance Company
3909 NE 163rd Street
North Miami Beach, FL 33160

Attn: Mr. Juan Delgado

Report
Prepared By:

Sean P. Clinca, BSME

Interscience, Inc.

7705 Ann Ballard Road
Tampa, FL 33634-2334
(813) 885-4774
Fax (813) 889-9157


November 19, 2004

United Automobile Insurance Company
3909 NE 163rd Street
North Miami Beach, FL 33160

Attn: Mr. Juan Delgado

Re: Our Project No: L1269-02
Insured: Unknown
Claim No: 804367
Date of Loss: Unknown
Date of Notification: November 3, 2004
Date of Inspection: November 15, 2004

Dear Mr. Delgado:

As requested, Interscience, Inc. has conducted an examination of the insured vehicle in connection with the subject fire loss, and submits its findings in this report.

BACKGROUND

It was reported that the subject vehicle had been parked in the driveway of the insured's residence at the time of the loss. A neighbor alerted the insured of the subject fire. Other neighbors attempted to extinguish the fire. The fire department was contacted and the fire was subsequently extinguished.

The incident was reported to United Automobile Insurance Company and Interscience, Inc. was subsequently requested to conduct an investigation into the subject fire. The vehicle was transported to Co-Part located in Opa Locka, Florida.

OBSERVATIONS/DISCUSSION

On November 15, 2004, Interscience, Inc. visited the Co-Part Auto Salvage, at 12850 NW 27th Ave., Opa Locka, Florida. The purpose of this visit was to conduct an origin and cause investigation of the subject vehicle fire.

The subject vehicle was a white 1997, Ford F-150 bearing vehicle identification number (VIN) 1FTDX1767VN [REDACTED]. The odometer reading could not be determined at the time of the inspection as the odometer was damaged by the fire.

A visual examination of the interior and exterior of the subject vehicle revealed that the windshield of the vehicle had sustained fire damage as a result of radiant heat from the engine compartment. The hood of the engine compartment had been consumed. This was caused by the subject fire which had melted the metal of the vehicle's hood. The interior of the vehicle had evidence of fire and smoke damage. There was also isolated fire damage to the interior side of the firewall below the dashboard on the driver's side. This was caused by heat transfer from the engine compartment. Inspection of the passenger compartment did not reveal any fire causing malfunction.

The area of fire origin was determined to be located within the engine compartment of the vehicle. The engine compartment of the vehicle was systematically and thoroughly inspected and photo documented.

Evidence remaining indicated that the cause of the fire was most probably electrical in nature. Since the vehicle had been parked for a period of time the possibility of this being a fuel related fire was eliminated. The fire pattern in the engine compartment and the front portion of the vehicle indicated that the fire had originated on the driver's side of the engine compartment. Located in this area was a cruise control deactivation switch. This switch was located on the brake master cylinder on the driver's side of the engine compartment. The deactivation switch and master cylinder were destroyed by the intense heat of the fire and were not available for an examination.

Failures of cruise control deactivation switches have been observed by Interscience, Inc. personnel in the past. Research also revealed that there had been a number of complaints filed with the National Highway Traffic Safety Administration (NHTSA) about a similar failure in the Ford F-150 and Ford Expedition.

CONCLUSIONS

It is the conclusion of Interscience, Inc. that the subject fire originated within the engine compartment of the vehicle. Due to the extensive fire damage present, a specific

EA025-002-LC-3529

point of origin could not be identified.

The point of origin was most likely within a cruise control deactivation switch located in the engine compartment on the driver's side. This type of failure has been observed by Interscience, Inc. personnel in the past. Research also revealed that there had been a number of complaints filed with the National Highway Traffic Safety Administration about similar failures in the past. No other fire-causing malfunction was identified.

Interscience, Inc. operates as an independent contractor. The opinions expressed are based upon information available at the time this report was drafted and draw upon the background, training and experience of the personnel involved in the investigation. The evaluation is subject to modification, amendment, and revision without prejudice, as further information may be revealed by continuing discovery.

In accordance with the ASTM standards, Interscience, Inc. will retain all records related to this assignment for seven years.

ENG-003-1-C-3838

United Automobile Ins. Co.
November 19, 2004
L1269-02 - Page 5

Respectfully submitted,

INTERSCIENCE, INC.

Sean P. Clince
Sean P. Clince, BSME *klc*

SPC:klc

Signed in the absence of
to avoid delay in mailing

Reviewed by,

Gene Bullington
Gene Bullington

C
N
O
V
E
M
B
E
R
1
9
2
0
0
4
L
1
2
6
9
-
0
2
-
P
a
g
e
5



PHOTO INDEX- L1269-02

1-12. Exterior views of the subject vehicle.



EMPS-989-LC-3032

3.



4.



8905-005-1-C-3813

5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62
63
64
65
66
67
68
69
70
71
72
73
74
75
76
77
78
79
80
81
82
83
84
85
86
87
88
89
90
91
92
93
94
95
96
97
98
99
100

5.



6.



ENC-005-LC-3034

7.



8.



BM25-485-1C-3535

13. A view of the subject vehicle odometer.




14-22. Interior views of the subject vehicle.



EMPS-005-LC-3530



17.



18.



1968-07-008-008E


A vertical strip of text, possibly a film edge or a scanning artifact, running along the right side of the page. The text is highly distorted and difficult to read, appearing as a series of vertical lines and characters.





SECRET

21.



22.



ENG5-883-LC-3944

23-26. Views of the wheel wells of the subject vehicle.



5953-608-10-3543

7
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62
63
64
65
66
67
68
69
70
71
72
73
74
75
76
77
78
79
80
81
82
83
84
85
86
87
88
89
90
91
92
93
94
95
96
97
98
99
100

25.




26.



EROS-005-LC-3545

C
A
R
R
I
E
R
S
I
N
T
H
E
P
A
S
T
I
C
A
L
I
T
Y
I
N
T
H
E
P
A
S
T
I
T
Y
I

27-28. Views of the subject vehicle VIN.



BBB-000-LC-0547

9-50. Views of the engine compartment.



EMOS-028-10-2848

31.



32.



ENG-888-1C-3549



35.



36.



1903-005-10-0051

37.



38.



ENR-005-LC-3002

39.



40.



ENG-005-10-0003

SECRET

41.




42.



2025-082-LC-3524

43.



44.



2025-055-LC-3555

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62
63
64
65
66
67
68
69
70
71
72
73
74
75
76
77
78
79
80
81
82
83
84
85
86
87
88
89
90
91
92
93
94
95
96
97
98
99
100

45.



46.




EPNS-005-L-C-3025

47.



48.




EMCS-000-10-2057

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

49.



50.



EMM-825-10-3258

51-54. Views of the area below the dashboard.



ENG-603-1C-2010

53.



54.



ENG-885-LC-2988

55-58. Views of the remains of the hood of the subject vehicle.



EMD-882-LC-3981

FBI LABORATORY

57.



58.





ERR-805-LC-0982

59-60. Views of the lower portion of the windshield area.



5902-07-088-5087

(1) 70. Views of the engine compartment.



EMC-625-LC-3504

63.



64.



EMRG-005-LO-3095

65.



66.



EMOS-003-LC-31808

69.



70.



ERRIS-000-10-0000

71-74. Views of the remains of an accessory belt located on the passenger side of the engine compartment.



71-74-006-10-3061

73.



74.



0155-01-028-028E

75-81. Views of the remains of the brake master cylinder.



ENG-903-LC-2571

77.



78.



EMOS-005-LC-2572

79.



80.



EMMS-005-LC-0573

81.



EROS-005-LC-3574



UNITED AUTOMOBILE INSURANCE COMPANY

P.O. BOX 600580 • NORTH MIAMI, FL 33160
305-940-7299 • 954-462-6803

RECEIVED JAN - 7 2005

JANUARY 03, 2005

FORD MOTOR COMPANY OFFICE OF THE GENERAL COUNSEL
MR. SHAWN L. NORTON
PARKLANE TOWERS WEST, SUITE #300
THREE PARKLANE BLVD.
DEARBORN, MICHIGAN 48126-2568

FORD MOTOR COMPANY
RECEIVED
JAN 07 2005
OFFICE OF THE
GENERAL COUNSEL

Re: Our Insured: [REDACTED]
Claim No.: [REDACTED]
Policy No.: [REDACTED]
Date Of Loss: 08/03/04
Vehicle: 1997 FORD F-150
VIN: 1FIDX1767VN [REDACTED]
Your Claim/File No: UNKNOWN
Company Payment: \$5,295.00 (pending salvage proceeds)
Insured's Deductible: \$500.00

Dear Mr. Shawn L. Norton:

Our above insured's vehicle was properly parked with the engine turned off when vehicle came on fire. The insured parked vehicle in front of his residence at 8:00 pm 08/02/04 and on 08/03/04 5:00 am was awakened by neighbors to advise his vehicle was on fire. The fire engulfed the engine and subsequently the fire spread to the house. The Miami Fire Department was called to extinguish the fire and inspect the incident. The Fire Department's investigator determined that the fire started in the engine compartment due to a short circuit that ignited the fuel.

Our investigation establishes the point of origin for the fire was the cruise control deactivation switch located in the engine compartment on the driver's side. This type of failure has been observed and researched by Interscience, Inc. and has been revealed that there had been a number of complaints filed with the National Highway Traffic Safety Administration about similar cases in the past. I will submit four more cases similar to this one to Ford Motor Company. Therefore, under our right of subrogation, we request reimbursement for both the company payment and deductible amount shown above. Enclosed are our supporting documents for your review.

We have diaried our files for (15) fifteen days. Your prompt attention to this matter will be appreciated.

WSD. 7/24/96
ESP- NO
DCC + BOW - 4415 (esp 7/24/00)

8/3/04
- 197 F-150
- VIN
- \$5,295
- Miami, FL
- 150,000 (2)



UNITED AUTOMOBILE INSURANCE COMPANY

P.O. BOX 600580 • NORTH MIAMI, FL 33160

305-940-7299 • 954-462-6803

Sincerely,



Jose Lopez


Subrogation Department

(305) 940-7299, ext. 2214

Enclosure: Supporting Documents

001/11 DAYS


ER05-005-LC-3576



RECEIVED MAY 17 2005



Allstate Insurance Company
16700 East Hardy, Suite A
Houston, TX 77032



New

05/12/05

Ford Motor Company
General Counsel's Office
3 Parklane Blvd
Dearborn, Michigan 48126

RE: Our Claim Number: [REDACTED]
Our Insured: [REDACTED]
Vehicle: 1997 Ford Pickup F150
VIN #: 1ftex1714v [REDACTED]
Date of Loss: 04/08/05
Loss Location: Comroe, Texas
Amount of Loss: 6850.00

Dear Ms. Norton,

Please accept this letter as notice to your company of a claim for subrogation. Our policyholder sustained fire damage to the above referenced vehicle. The damages are possibly linked to the brake deactivation switch.


Forensic Analysts, Inc. has completed the initial inspection. Please contact Jeff Abrams at 281-558-9396 to make arrangements for a joint inspection. The vehicle is located at Bayou City Auction Pool in Houston, Texas.

If any further information is needed, I can be reached at 281-618-5324.

Sincerely,

Diane C Gonzales
Staff Claim Service Adjuster
Allstate Insurance Claim Service Organization

ER05-005-LC-3577



IN THE DISTRICT COURT OF FORD COUNTY, KANSAS

G

[REDACTED]

Plaintiff

vs.

Case Number: 046123

FORD MOTOR COMPANY AND SKAGGS MOTORS, INC.

Defendants

PETITION
Pursuant to Chapter 60

COMES NOW the plaintiff by and through his attorney, Todd B. Butler of Butler & Associates, P.A., and for his cause of action against the Defendants, states and alleges as follows:

1. Plaintiff is a resident of Kansas and may be served by serving his counsel for the purposes of these proceedings.
2. Defendant, Ford Motor Company, may be served by serving its Resident Agent, Peter J. Sherry, by Certified Mail Service at One American Road, Dearborn, MI 48126.
3. Defendant, Skaggs Motors, Inc., may be served by serving its Resident Agent, H.M. Skaggs, by Personal/Residential Service at 200 Military St, Dodge City, KS 67801.
4. On or about Mar 1, 2003, the plaintiff purchased from the defendant, Skaggs Motors, Inc., a 2001 Ford F-150, VIN 1FTRX17W41N [REDACTED]
5. Defendant, Ford Motor Company, was the manufacture of plaintiff's vehicle.

6. On or about March 7, 2003, the plaintiff's above-described vehicle caught fire while parked at the plaintiff's residence at 1208 12th Ave, Dodge City, KS.
7. That pursuant to K.S.A. 60-308 (b) (1), (2), (5), and (7), jurisdiction is proper in this court.
8. That the fire started in the engine compartment as a result of a faulty fuel regulator.
9. That the vehicle damages and reasonable rental car expenses are in the amount of \$20,592.32.
10. That the defendants did so carelessly, negligently and recklessly manufacture, design, construct, make, install, assemble, sell, distribute, retail and/or otherwise place or cause to be placed into the stream of commerce the 2001 Ford F-1500, which defendants knew, or in the exercise of reasonable care diligence should have known, was dangerous and defective, and which defendants further knew and/or in the exercise of reasonable diligence should have known, lacked adequate warnings which defendants negligently and carelessly failed and refused to provide to plaintiff, and further, defendants knew that such acts, conduct and/or omissions would, and in fact did, cause harm, damages and injuries to the plaintiff, as a result of such a defective and dangerous condition.
11. That the defendants knew that such products would be used and in fact were used, in a manner intended by the defendants, without inspection for defects, and further, that as a result of the dangerous and defective conditions of the products, as described herein above, defects known by the defendants to have

existed or which in fact existed when they left the control of the defendants, plaintiff was caused to suffer damages as alleged herein.

12. That the defendants did implicitly and expressly warrant that such products as herein described would be merchantable and would serve the purpose intended and was safe and fit for their intended uses and purposes. As a direct result of the defective conditions of such products, the plaintiff sustained damages, and as a direct result of such damages, the defendants breached such implied and express warranties resulting in the damages herein alleged.
13. That the defendants were negligent in the design and manufacturing of the 2001 Ford F-150, and as a result of the negligent design and manufacturing, plaintiff suffered damages in the amount of \$20,592.32.
14. That demand has been made upon the defendants to pay this amount, but the defendants have failed and refused to do so.

WHEREFORE, plaintiff prays for money judgment against the defendants in the amount of \$20,592.32, costs of this action, interest at the statutory rate after the date of judgment, and for such other relief as the court may deem just and equitable.

Butler & Associates, P.A.

Todd B. Butler 12711
Gary L. Fanning, Jr. 16669
3706 S. Topeka Blvd. Suite 300
Topeka, Kansas 66609
(785) 267-6444 Office
(785) 267-7341 Fax
butlerlaw@inlandnet.net
Attorneys for Plaintiff

B Location Check this box to indicate that the address for this incident is provided on the Wildland Fire Module in Division 5 "Alternative Location Specification". Use only for Wildland Class.
 Street address **Intersection** **In front of** **Rear of** **Adjacent to** **Directions**
 [Redacted] **Dodge City** **KS** **67801**
 City State Zip Code
 Cross street or direction, as applicable

C Incident Type * **131** **Passenger vehicle fire**
E1 Date & Times **Midnight is 0000**
 Check boxes if dates are the same as Alarm **Alarm always required**
 Date: **03** **07** **2003** **21:59:00**
E2 Shift & Alarm Local Option **A** **1**
 Shift or Alarm District **1**

D Aid Given or Received *
 1 **Mutual aid received** **Their FDID** **Their State**
 2 **Automatic aid recvd.**
 3 **Mutual aid given**
 4 **Automatic aid given**
 5 **Other aid given**
 6 **None**
 Their Incident Number: [Redacted]

E3 Special Studies Local Option
 Special Study Fee Special Study Value

F Actions Taken * **11** **Extinguish**
 Primary Action Taken (1)
 Additional Action Taken (2)
 Additional Action Taken (3)

G1 Resources * Check this box and skip this section if an Apparatus or Personnel form is used.
 Apparatus **0002** **0804**
 Personnel **0002** **0804**
 Other
 Check box if resource counts include aid received resources.

G2 Estimated Dollar Losses & Values **LOSSES:** Required for all fires if known. Optional for non fires.
 Property \$ **015,000**
 Contents \$ **001,000**
 Property \$ **018,000**
 Contents \$ **001,000**
FWB-INCIDENT VALUE: Optional

Completed Modules
 Fire-2
 Structure-3
 Civil Fire Cas.-4
 Fire Surv. Cas.-5
 MCU-6
 Rescue-7
 Wildland Fire-8
 Apparatus-9
 Personnel-10
 Arson-11

H1 Casualties **Deaths** **Injuries**
 Fire
 Service
 Civilian

H2 Detonator Required for Confined Fires.
 1 Detonator alerted occupants
 2 Detonator did not alert them
 0 Unknown

H3 Hazardous Materials Release
 1 **Natural Gas:** also leak, or overflow or under pressure
 2 **Propane gas:** < 40 lb. tank or in hose > 600 gallons
 3 **Gasoline:** vehicle fuel tank or portable container
 4 **Kerosene:** fuel heating equipment or portable storage
 5 **Diesel fuel/fuel oil:** engine fuel tank or portable
 6 **Household solvents:** home/office sprays, cleaning oils
 7 **Motor oil:** from engine or portable container
 8 **Paint:** from paint cans totaling < 10 gallons
 9 **Other:** special notice unless explained on spill > 10 gal., **Class number on label form**

I Mixed Use Property
 MN **Not Mixed**
 10 **Assembly use**
 20 **Education use**
 30 **Medical use**
 40 **Residential use**
 50 **Law of stores**
 55 **Enclosed mall**
 58 **Bus. & Residential**
 59 **Office use**
 60 **Industrial use**
 63 **Military use**
 65 **Farm use**
 00 **Other mixed use**

J Property Use **Structures**
 131 **Church, place of worship**
 161 **Restaurant or cafeteria**
 162 **Bar/Tavern or nightclub**
 213 **Elementary school or kindergarten**
 215 **High school or junior high**
 241 **College, adult education**
 311 **Care facility for the aged**
 331 **Hospital**

Outside
 124 **Playground or park**
 655 **Crops or orchard**
 669 **Forest (timberland)**
 807 **Outdoor storage area**
 919 **Camp or sanitary landfill**
 931 **Open land or field**

341 **Clinic, clinic type infirmary**
 342 **Dentist/dentist office**
 361 **Prison or jail, not juvenile**
 419 **1- or 2-family dwelling**
 429 **Multi-family dwelling**
 439 **Rooming/boarding house**
 449 **Commercial hotel or motel**
 459 **Residential, board and care**
 464 **Dormitory/barracks**
 519 **Food and beverage sales**

536 **Vacant lot**
 938 **Graded/care for plot of land**
 946 **Lake, river, stream**
 951 **Railroad right of way**
 960 **Other street**
 961 **Highway/divided highway**
 962 **Residential street/driveway**

539 **Household goods, sales, repairs**
 579 **Motor vehicle/boat sales/repair**
 571 **Gas or service station**
 599 **Business office**
 618 **Electric generating plant**
 629 **Laboratory/science lab**
 700 **Manufacturing plant**
 819 **Livestock/poultry storage (barn)**
 882 **Non-residential parking garage**
 891 **Warehouse**

981 **Construction site**
 984 **Industrial plant yard**

Lookup and enter a Property Use code only if you have not checked a Property Use box:
 Property Use **000**
Property Use, Other
 MFERS-1 Revision 03/11/99

K1 Person/Entity Involved

Local Option

Business name (if applicable)

Area Code

Phone Number

 Check this box if same address as incident location. Then skip the three duplicate address lines.

Mr./Ms./Mrs.	First Name	MI	Last Name	Suffix
Number	Prefix	Street or Highway	Street Type	Suffix
Post Office Box	Apt./Suite/Room	City		
State	Zip Code			

 More people involved? Check this box and attach Supplemental Forms (SWIRS-18) as necessary
K2 Owner
 Same as person involved? Then check this box and skip the rest of this section.

Local Option

Business name (if applicable)

Area Code

Phone Number

 Check this box if same address as incident location. Then skip the three duplicate address lines.

Mr./Ms./Mrs.	First Name	MI	Last Name	Suffix
Number	Prefix	Street or Highway	Street Type	Suffix
Post Office Box	Apt./Suite/Room	Dodge City		
State	Zip Code			

L Remarks

Local Option

A shift responded to a vehicle fire at 1208 twelfth. Upon arrival the vehicle was engulfed in flames from the engine compartment. After extinguishment and investigation cause of the fire was undetermined but did not appear to be suspicious. There was no one home at this address so the owner has not yet been notified.

03/07/2003 23:02:43 Cliff Bell

L Authorization

2125

Officer in charge ID

SPENCER, KEN D

Signature

CAP

Position or rank

Assignment

03

07

2003

Month Day Year

 Check box if same as Officer in charge.

558

Number making report ID

BELL JR, CLIFF L

Signature

ENG

Position or rank

Assignment

03

07

2003

Month Day Year

State Farm Insurance Companies®



March 25, 2003

CERTIFIED MAIL - RETURN RECEIPT REQUESTED

FORD MOTOR COMPANY
PARK LANE TOWERS WEST STE 400
3 PARK LANE BLVD
DEARBORN MI 48126-2568



Claim Office
2804 Pearly Jane Street
P.O. Box 1748
Garden City, KS 67846-1748
620-276-5500
1-800-728-5905
Fax: 620-276-5555
Office Hours: Mon-Fri 8:00-5:00

RE: Claim Number: [REDACTED]
Our Insured: [REDACTED]
Date of Loss: March 7, 2003
Make, Model and
Year of Product: 2001 Ford F-150 XLT Extended Cab
VIN: 1FTRX17W41N [REDACTED]

Dear Sir/Madam:

The identified vehicle is insured by State Farm Fire and Casualty Company. This vehicle experienced a fire.

State Farm® would like to give you an opportunity to inspect the vehicle and give you advance notice of our potential subrogation claim.

A cause and origin inspector will be inspecting the identified vehicle at Wichita Insurance Pool 270 W 53rd Street North, Wichita, KS 67204 on April 1, 2003. You are invited to observe his inspection on this date.

If you have questions regarding this claim, please call me at the number below.

Sincerely,

Amy Zwegardt
Claim Representative
620-276-5502
State Farm Fire and Casualty Company

13/0321004N

Handwritten notes: 3/27/03, 101 F-150, VIN

State Farm Insurance Companies®



April 25, 2003

Claim Office
2804 Peary Jane Street
P.O. Box 1748
Garden City, KS 67848-1748
620-278-5500
1-800-728-5505
Fax: 620-278-5555
Office Hours: Mon-Fri 8:00-5:00

SHAWN NORTON
FORD MOTOR COMPANY
PARKLANE TOWERS WEST STE 300
3 PARKLANE BLVD
DEARBORN MI 48126-2588

RECEIVED MAY 5 2003

RE: Our Claim Number: [REDACTED]
Our Insured: [REDACTED]
Date of Loss: March 7, 2003

Dear Mr. Norton:

This letter is in response to your April 9th letter. The following are answers to your questions as requested:

1. The date of the loss was March 7, 2003, at [REDACTED] residence. His address is [REDACTED] in Dodge City, Kansas [REDACTED]
2. The owner [REDACTED] parked the 1997 Ford F-150 in his driveway at 8:00 p.m. on March 7, 2003. He left his residence in another vehicle and returned home at 10:00 p.m., on the same evening. [REDACTED] did not notice the damage until the next morning when he went to take the pickup to work. Neighbors noticed the fire and called the fire department. The fire was extinguished while the owner was away from his home.
3. Enclosed is a copy of the fire report from the Dodge City Fire Department.
6. The mileage was unreadable upon inspection of the vehicle.
7. Original photos were not obtained as digital photos were taken. These digital photos are included in the expert's report.
10. It appears that a gasoline leak in the fuel pressure regulator was the origin of the fire.
11. Enclosed is a copy of our expert's report as requested. The report was completed by Technical Forensic Services in Liberty, Missouri.

29,079 on purchase at 2/10/03
Dodge City, KS
97 F-150


April 25, 2003

14. Due to the damage to the vehicle, it was determined to be a total loss. Enclosed is the worksheet and a copy of the draft to pay for the total loss.
15. The insured has no service history on this vehicle as it was bought on Saturday, March 1, 2003.
16. No aftermarket additions or modifications were made to the vehicle.
21. The engine was not running at the time the fire started.
22. The keys were not in the ignition at the time the fire started.
25. The vehicle was purchased on March 1, 2003, from Skaggs Motors, Inc., 200 Military Avenue, Dodge City, Kansas 67601. Their phone number is 620-227-3171. At the time of the purchase the mileage read 29,079 miles.

If you need any other additional information, please contact us.

This claim will now be handled by our Subrogation Department. Their phone number is 888-660-1917. Please contact them for further correspondence.

Sincerely,



Amy Zwegardt
Claim Representative
620-276-5502
State Farm Mutual Automobile Insurance Company

14/0426010

Enclosure

[REDACTED]

PLAINTIFF

VS.

CIVIL ACTION NO. M2003-034

FORD MOTOR COMPANY

DEFENDANT

COMPLAINT

COMES NOW the Plaintiff [REDACTED] by and through counsel in the above styled matter, and files this his Complaint against the Defendant, Ford Motor Company, and would respectfully show unto the Court the following:

I.

That the Plaintiff [REDACTED] is a resident citizen of Marshall County, Mississippi.

II.

That the Defendant, Ford Motor Company, is a corporation organized and existing under the laws of the State of Delaware, which is authorized to conduct business within the State of Mississippi, and which can be served with process of this Court through its registered agent for service of process, C. T. Corporation System, 631 Lakeland East Drive, Flowood, Mississippi 39232-8815.

III.

That jurisdiction and venue are proper with this Court.

IV.

That this Complaint and cause of action is based upon the theory of product liability, whereby the Defendant produced, marketed, and sold a motor vehicle which had been defectively designed and/or manufactured.

FILED

JAN 28 2003

LUCY CARPENTER
Circuit Clerk, Marshall Co., MS
BY CS D.C.

EP05-095-LC-0688

V.

That on or about August 4, 1999, the Plaintiff, [REDACTED] at that time seventeen [REDACTED] years of age, did purchase from Beik Ford-Mercury-Toyota, Inc. in Oxford, Mississippi, a 1997 Ford F-150 Extended Cab XL pickup truck, VIN 1FTDX1766VN [REDACTED] which had been designed and manufactured by the Defendant, Ford Motor Company.

VI.

That, less than five (5) months thereafter, on or about January 24, 2000, the aforementioned motor vehicle of the Plaintiff did, for no apparent reason, catch fire and burn, resulting in a total loss.

VII.

That in November of 2000, the Plaintiff did receive a recall notification from Ford Motor Company, indicating that his vehicle, and others similar, did contain a design and/or manufacturing defect whereby the fuel line assembly was negligently and improperly positioned with relation to the engine and components, and that this condition could lead to a potential fire if repairs were not made accordingly.

VIII.

That, at the time of the receipt by Plaintiff of the aforementioned notification, his vehicle had already burned and was rendered a total loss.

IX.

That, upon information and belief, the vehicle of the Plaintiff was caused to catch fire and burn when the fuel line assembly began to leak as a result of the design and/or manufacturing defects of the Defendant.

X.

That as a result of the negligence of the Defendant, in defectively designing and/or manufacturing the Plaintiff's vehicle, the Plaintiff has been caused to sustain actual and


consequential damages, including, but not limited to, the reasonable value of his vehicle, plus all other incidental expenses.

WHEREFORE, PREMISES CONSIDERED, the Plaintiff [REDACTED] hereby seeks and demands judgment against the Defendant, Ford Motor Company, in the amount of Fifteen Thousand Dollars (\$15,000.00), plus pre-judgment and post-judgment interest, and all costs of court. The Plaintiff requests any such further or general relief as this Court may deem proper in the premises.

Respectfully submitted, this the 24th day of January, 2003.

[REDACTED] Plaintiff

By:


Christopher G. Evans (Miss. Bar No. 10121)
EVANS & BAILEY, PLLC
117 North Broadway Street
Post Office Box 7326
Tupelo, Mississippi 38802-7326
(662) 844-6040 / Telephone
(662) 844-8333 / Facsimile

COUNSEL FOR THE PLAINTIFF

ISSUE LIST

Last Handling Date/ Issue Status	Name/ Reason Desc	Vin/ Case No.	Model Year and Vehicle Line	Issue Type
11/13/2002 CLOSED	[REDACTED] MISC INQUIRY - CHANGE OF ADDRESS	1FTDX1766V[REDACTED] 1418170280	1997 F-SERIES	02
3/30/2000 CLOSED	[REDACTED] LEGAL - OTHER ATTORNEY DEMAND	1FTDX1766V[REDACTED] 1418170280	1997 F-SERIES	07
2/7/2000 CLOSED	[REDACTED] PROD/COMP DUR/PERF - VEHICLE QUALITY	1FTDX1766VNA58774 1418170280	1997 F-SERIES	02
2/3/2000 CLOSED	[REDACTED] PROD/COMP DUR/PERF - VEHICLE QUALITY	1FTDX1766V[REDACTED] 1418170280	1997 F-SERIES	02
1/31/2000 CLOSED	[REDACTED] LEGAL - FIRE&PERSONALPROPERTY DAMAGE CLAIM	1FTDX1766V[REDACTED] 1418170280	997 F-SERIES	07

EPC-005-LO-0000

[REDACTED] 2/26/2003

All Action Details for Issue

Print

VIN: 1FTDX1768VN [REDACTED] Year: 1997 Model: F-SERIES Case: 1418170280
 Name: [REDACTED] Owner Status: Subsequent WSD: 1996-06-11
 Symptom Desc: Primary Phone: [REDACTED]
 Reason Desc: MISC INQUIRY - CHANGE OF ADDRESS Secondary Phone: [REDACTED]
 Issue Type: 02 INFORMATION Issue Status: CLOSED

Action: UPDATE CUSTOMER ADDRESS OR PHONE NUMBER
 Dealer: 06000 COUNTRY FORD INC Origin Desc: MANUAL - PHONE CSR
 Odometer: Comm Type: PHONE
 Analyst Name: MATT CROSBY Analyst: MCROSBY1
 Action Date: 11/13/2002 Action Time: 10.49.37.189 Action Data: No

Caller Information if Different From Vehicle Owner:

First Name	Middle Initial	Last Name	Day Phone	Relationship
------------	----------------	-----------	-----------	--------------

Comments CUSTOMER SAYS: -UPDATE INFO PER CUSTOMER, DEALER SAYS: -NONE CAC ADVISED: (NOTE TO CSR - THIS MAC IS TO BE USED FOR UPDATING CUSTOMER INFORMATION ONLY. DO NOT USE FOR DOCUMENTING ANY OTHER ISSUES.)

EMMS-005-10-3590

[REDACTED] 5/26/2003

All Action Details for Issue

Print

VIN: 1FTDX1765V [REDACTED] Year: 1997 Model: F-SERIES Case: 1418170280
 Name: [REDACTED] Owner Status: Subsequent WSD: 1996-06-11
 Symptom Desc: FIRE/SMOKE SCORCHED/BURNT Primary Phone: [REDACTED]
 Reason Desc: LEGAL - OTHER ATTORNEY DEMAND Secondary Phone: [REDACTED]
 Issue Type: 07 LEGAL Issue Status: CLOSED

Action: OPEN LEGAL CONTACT - ATTORNEY DEMAND
 Dealer: 06000 COUNTRY FORD INC Origin Desc: CONSUMER AFFAIRS - LITIGATION PREVENTION
 Odometer: 1 MI Comm Type: MAIL
 Analyst Name: SHAWN COX Analyst: SCOX15
 Action Date: 03/29/2000 Action Time: 16.06.42.802 Action Data: Yes

Comments *****ATTORNEY DEMAND LETTER***** REC:03/29/00 ATTORNEY ALLEGES DEFECTIVE VEHICLE. CUSTOMER STATES THAT THE VEHICLE CAUGHT FIRE. ***NO RESOLUTION STATED.***

Data Element Name	Data Value
NAME OF LAW FIRM	PRIEST, WISE & RUSSELL ATTORNEY'S AT LAW
ATTORNEY NAME	S. BO RUSSELL & RUSSELL ATTORNEY'S AT LAW
ATTORNEY PHONE NUMBER	6018424658ELL & RUSSELL ATTORNEY'S AT LAW

Action: MAKE OUTBOUND CALL TO ATTORNEY
 Dealer: 06000 COUNTRY FORD INC Origin Desc: CONSUMER AFFAIRS - LITIGATION PREVENTION
 Odometer: 1 MI Comm Type: MAIL
 Analyst Name: LOURDES FONSECA Analyst: 9826LF
 Action Date: 03/30/2000 Action Time: 14.17.48.726 Action Data: Yes

Comments LPA CALLED ATTY'S OFFICE AND INFORMED WE HAVE RECEIVED THEIR LETTER AND WILL RESEARCH AND RECONTACT WITH A DECISION.

Data Element Name	Data Value
CONTACT PERSON	VOICE MAILELL & RUSSELL ATTORNEY'S AT LAW

Action: FINAL CASE DISPOSITION
 Dealer: 06000 COUNTRY FORD INC Origin Desc: CONSUMER AFFAIRS - LITIGATION PREVENTION
 Odometer: 1 MI Comm Type: MAIL
 Analyst Name: LOURDES FONSECA Analyst: 9826LF
 Action Date: 03/30/2000 Action Time: 15.30.38.700 Action Data: No

Comments LPA HAD PREVIOUSLY DENIED CLAIM AS VEHICLE IS BEYOND THE WARRANTY. LPA FAXED LETTER TO THE ATTY DENYING THE CLAIM. NO FURTHER ACTION.

E905-005-L0-0301

All Action Details for Issue

Print

VIN: 1ETDX1766V8	Year: 1997	Model: F-SERIES	Case: 1418170280
Name: [REDACTED]	Owner Status: Subsequent	WSD: 1998-06-11	
Symptom Desc:		Primary Phone: [REDACTED]	
Reason Desc: PROD/COMP DUR/PERF - VEHICLE QUALITY		Secondary Phone: [REDACTED]	
Issue Type: 02 INFORMATION	Issue Status: CLOSED		

Action: SUPPORT DEALER'S/REGION'S DECISION

Dealer: 05814 BELK FORD-MERCURY INC	Origin Desc: US CONCERN CASE BASE
Odometer: 104000 MI	Comm Type: PHONE
Analyst Name: ANTHONY THOMPSON	Analyst: ATHOMP22
Action Date: 02/07/2000	Action Time: 11.43.07.384
	Action Date: No

Comments: CUSTOMER SAYS: CUST SAYS THE VEH CAUGHT ON FIRE ON MONDAY JAN 24/99. — THE FIRE ORIGINATED IN THE ENGINE UNDER THE HOOD. VEH WAS NOT ON WHEN FIRE OCCURRED, FIRE CAME OUT ON THE DRIVERSIDE. THE ENGINE EXPLODED. —VEH PART ON THE STREET (HENRY DON ST, MEMPHIS TENNESSE SHELBY COUNTER. CUST WAS HAVING DINNER AT A FRIEND'S HOUSE. —VEH IS AT 181 CENETARY RD POTTS CAMP MISSISSISSIPPI (HOUSE ADDRESS) —SHELBY COUNTY FIRE DEPARTMENT PUT OUT THE FIRE, SAYS FIRE STARTED IN THE ENGINE. REPORT # UNKNOWN —VEH IS TOTALLED. - RECEIVED LETTER FROM CONSUMER AFFAIRS STATING IT IS A MATTER WITH THE INSURANCE CO. - CUST FEELS IT IS A DEFECT PER CUSTOMER, DEALER SAYS: NONE CAC ADVISED: - INFORMATION DOCUMENTED - FORD SUPPORTS DLR/REGION DECISION INFERENCE CASE ID: 1615

ERRS-005-LC-3882

All Action Details for Issue

Print

VIN: 1E1DX1766V [REDACTED] Year: 1997 Model: F-SERIES Case: 1418170280
 Name: [REDACTED] Owner Status: Subsequent WSD: 1996-06-11
 Symptom Desc: ENGINE GENERAL CONCERN MECH FAILURE Primary Phone: [REDACTED]
 Reason Desc: PROD/COMP DUR/PERF - VEHICLE QUALITY Secondary Phone: [REDACTED]
 Issue Type: 02 INFORMATION Issue Status: CLOSED

Action: CB-SUPPORT DEALERSHIP'S/REGION'S POSITION
 Dealer: 05814 BELK FORD-MERCURY INC Origin Desc: US CONCERN CASE BASE
 Odometer: 104000 MI Comm Type: PHONE
 Analyst Name: ANGELO POLIUS Analyst: APOLIUS
 Action Date: 02/03/2003 Action Time: 17.37.38.790 Action Date: No

Comments CUSTOMER SAYS: -CUST IS CALLING TO FIND OUT IF THERE ARE ANY RECALLS ON VEH -CUST CALLED IN PREVIOUSLY, REGARDING SAME ISSUE ,PLS REFER TO CUST HISTORY --CUST DCLAIMS VEH CAUGHT ON FIRE ,NO ONE WAS IN THE VEH AT THE TIME -VEH IS TOTALLED PER CUSTOMER, DEALER SAYS: -NONE CAC ADVISED: - INFORMATION DOCUMENTED - FORD SUPPORTS DLR/REGION DECISION --INFORMED CUST OF 98S14,98S22 AND 98R01 -PLS BE PATIENT ,AS THIS ISSUE IS NOW IN THE HANDS OF THE CONSUMER AFFAIRS DEPT ,AND THEY SHOULD BE CONTACTING YOU INFERENCE CASE ID: 1538

EX03-005-1C-0303

All Action Details for Issue

Print

VIN: 1FTDX1788V [REDACTED] Year: 1997 Model: F-SERIES Case: 1418170280
 Name: [REDACTED] Owner Status: Subsequent WSD: 1996-06-11
 Symptom Desc: FIRE/SMOKE VISIBLE FLAME UNDERHOOD Primary Phone: [REDACTED]
 Reason Desc: LEGAL - FIRE&PERSONAL/PROPERTY DAMAGE CLAIM Secondary Phone: [REDACTED]
 Issue Type: 07 LEGAL Issue Status: CLOSED

Action: ADVISE CUSTOMER INFORMATION FORWARDED TO CONSUMER AFFAIRS DEPT
 Dealer: 05814 BELK FORD-MERCURY INC Origin Desc: US CONCERN CASE BASE
 Odometer: 104000 MI Comm Type: PHONE
 Analyst Name: LEAH MOTIRAM Analyst: LMOTIRAM
 Action Date: 01/28/2000 Action Time: 11.34.37.623 Action Data: Yes

Comments CUSTOMER SAYS: CUST SAYS THE VEH CAUGHT ON FIRE ON MONDAY JAN 24/98 — THE FIRE ORIGINATED IN THE ENGINE UNDER THE HOOD. VEH WAS NOT ON WHEN FIRE OCCURRED. FIRE CAME OUT ON THE DRIVERSIDE. THE ENGINE EXPLODED. —VEH PART ON THE STREET (HENRY DOW ST, MEMPHIS TENNESSE SHELBY COUNTER. CUST WAS HAVING DINNER AT A FRIEND'S HOUSE. —VEH IS AT 181 CEMETARY RD POTTS CAMP MISSISSIPPI (HOUSE ADDRESS) —SHELBY COUNTY FIRE DEPARTMENT PUT OUT THE FIRE, SAYS FIRE STARTED IN THE ENGINE. REPORT # UNKNOWN —VEH IS TOTALLED. PER CUSTOMER, DEALER SAYS: MUNNS BELK FORD IN OXFORD MISSISSIPPI CAC ADVISED: -OTHER OPEN RECALLS AND ONP 98S14 WHEEL LUGNUT, 98R01 PCV FREEZING; 98S62 SEAT BELT. — THIS INFORMATION HAS BEEN FORWARDED TO THE CONSUMER AFFAIRS DEPARTMENT FOR REVIEW - A REPRESENTATIVE FROM CONSUMER AFFAIRS WILL FOLLOW UP ON YOUR CLAIM - NO TIME FRAME AVAILABLE - IF YOU HAVE NOT ALREADY CONTACTED YOUR INSURANCE CARRIER TO REPORT THE CONCERN, PLEASE DO SO IN REFERENCE CASE ID: 81

Data Element Name	Data Value
ONP #	98R01

Action: MAKE OUTBOUND CALL TO DEALER
 Dealer: 05814 BELK FORD-MERCURY INC Origin Desc: CONSUMER AFFAIRS - LITIGATION PREVENTION
 Odometer: 104000 MI Comm Type: PHONE
 Analyst Name: LOURDES FONSECA Analyst: 9826LF
 Action Date: 01/28/2000 Action Time: 16.48.03.838 Action Data: Yes

Comments LPA SPOKE WITH CUSTOMER'S GRANDMOTHER, SHE WAS THE ONE THAT MADE THE PHONE CALL TO THE CAC. LPA INFORMED WE WOULD RESEARCH AND RECONTACT.

Data Element Name	Data Value
CONTACT PERSON	MRS. MUNNS

Action: REFER TO INSURANCE CARRIER- BEYOND WARRANTY
 Dealer: 05814 BELK FORD-MERCURY INC Origin Desc: CONSUMER AFFAIRS - LITIGATION PREVENTION
 Odometer: 104000 MI Comm Type: PHONE
 Analyst Name: LOURDES FONSECA Analyst: 9826LF
 Action Date: 01/31/2000 Action Time: 09.24.04.696 Action Data: No

Comments VEHICLE BEYOND WARRANTY, NO RECALLS W/POTENTIAL FOR A FIRE AT THIS TIME. LPA MAILED A LETTER TO THE CUSTOMER REFERRING HIM TO HIS INSURANCE COMPANY.

EWS-005-10-2004

INVESTIGATIVE RESOURCES
&
CONSULTANTS IN SECURITY, INC.
P.O. BOX 4555 Johnson City, TN 37602-4555 423/477-8808

IRCS Case # FA 006-02
SFIC Claim # [REDACTED]

MR. PHILLIP LONG
State Farm Insurance Company

RECEIVED

FEB 14 2002

TRI-CITIES CLAIMS OFFICE

CONFIDENTIAL

FIRE / MECHANICAL ORIGIN AND CAUSE REPORT

IRCS Case # FA 006-02

SFIC Claim # [REDACTED]

Client/Company: Mr. Phillip Long / State Farm Insurance Company

Directive: Determine origin and cause of fire

Owner/Insured: [REDACTED]

Subject of Report: 1995 Ford F-150 pickup truck

Location of Inspection: [REDACTED] Mosheim, TN

Date of Loss: January 24, 2002

Date of Assignment: January 25, 2002

Date of Inspection: January 26, 2002

Report prepared by: R.G. Young, Jr., L.P.I., C.A.T.

J.M. Collida, L.P.I., C.F.E.I.

CONSTRUCTION / DESCRIPTION: The subject vehicle was a 1995 Ford F-150 pickup truck; VIN # 1FTEX14H4SE [REDACTED] V-8 gasoline engine; automatic transmission; 4-wheel drive; bucket seats; power steering; power windows; alum/mag alloy wheels; power locks; air conditioning; cruise control (OKM); air bag; trailer hitch; step bumper; running boards; and auxiliary fuel tank. The RVTC Wide Climber 32x11.50/R15LT tires on the rear had tire tread depths of LR - 10/32 and RR - 4/32. The two front tires were destroyed by the fire.

INSPECTION: On January 26, 2002, the IRCS investigative team traveled to 7782 Blue Springs Parkway, Mosheim, TN. Upon arrival, we were met by [REDACTED]. They answered our questions and remained with us throughout our investigation. [REDACTED] stated he had purchased the subject truck from a local bank after it had been repossessed. He did not know the circumstances of the repossession nor the previous owner's name.

An initial "walk-around" revealed that the subject truck, parked in the right side of the garage, had been destroyed by fire. Extensive damage had also occurred to the garage and a 1991 Pontiac Grand Prix SE.

The Pontiac had been removed to the outside of the garage, just in front of the left entrance to the garage. The Pontiac had not suffered the same amount of fire damage as the truck (subject vehicle). [REDACTED] stated the Pontiac had been parked in the garage all day and was not driven on the day of the fire. Based on the much lesser degree of fire damage, the Pontiac was ruled out of the area of the fire's origin and ruled out as the cause of the fire. (See photos showing damage to Pontiac in Photo Index).

The examination of the garage revealed that the most severe fire damage had occurred to the right side (facing garage) where the 1995 Ford F-150 pickup truck had been parked. The only items stored in the garage were bicycles, lawn chairs, and a portable light. There were no ignitable liquids nor items using ignitable liquids in the garage. Electrical wiring, in metal conduit, and receptacle boxes had been installed; however, there was no electrical power to the garage. Based on the aforementioned findings, the garage's components were ruled out as the cause of the fire.

The 1995 Ford F-150 pickup truck was examined. A "walk-around" of the vehicle revealed that paint remained on the rocker panels. The front tires had burned away, with severe damage to the wheels. The rear tires had not become involved in the fire. The burn patterns and area of the most severe fire damage indicated the front end of the truck was the area of the fire's origin.

The interior of the subject truck was carefully examined. The melted, front windshield glass was laying across and on top of the fire debris. The condition of the windshield glass indicated the windshield's molding and insulation had failed, due to heat, and caused the windshield glass to fall inward. The burn patterns to the aluminum molding, around the front windshield, indicated the fire originated in the engine compartment and traveled toward the passenger compartment.

The fire debris in the passenger compartment was layered, examined, and removed. The debris was checked for the presence of any ignitable liquid(s) - none was present.

Remains of personal items were recovered from the debris, to include a Carhartt jacket and a pair of binoculars.

The remains of rubber mats were present on both sides of the front floorboard. This indicates the fire did not originate at floorboard level in the passenger compartment.

After debris examination and careful removal, the dash wiring harness was examined. Minor shorting was found. The minor shorting and fragmentation was due to "fall-down" and live wires coming into contact with grounds, by other circuits or body grounds. All electrical wiring in the passenger compartment was examined and ruled out as the cause of the fire.

Having found no evidence of an electrical, accidental, or "set" cause in the interior, the investigation proceeded to the engine compartment.

The fuel lines and fuel rail were still connected. No sign(s) of leakage or seepage was found. The emission system, the starter and related wiring, the coolant system, and the power steering system were all examined and ruled out as the cause and/or origin of the fire.

The electrical system, which includes the engine compartment wiring harness, the charging system, and the battery were each examined. The battery had suffered only "melt-down" damage as a result of the fire, therefore was ruled out as the cause of the fire.

The engine wiring harness had suffered some fragmentation due to "fall-down" and some minor shorting. However, after a thorough examination, the electrical wiring was ruled out as the cause of the fire.

The alternator was carefully examined. The feeder circuit was loose at the rectifier connector battery bolt. The alternator presented evidence of high resistance and overheating of the feeder circuit connector. Some of the diodes had separated and contributed to the high resistance found in the alternator. The burn patterns and fire damage to the plenum chamber and other components in the engine compartment indicated the alternator was at the point of the fire's origin.

CONCLUSION: After a thorough examination of the subject vehicle, it was concluded that the fire originated in the engine compartment. The cause of the fire was the shorting of the alternator due to the loose connection. The fire then spread, through the normal factory openings in the firewall, to the passenger compartment.


PHOTO INDEX
FA 006-02

Photos 1-4

Exterior views of [redacted] garage [redacted] Mosheim, TN showing subject 1995 Ford F-150 pickup truck still in place as at the time of the fire (1) and that most severe fire damage to garage is at truck's location (1-2).





ENR-025-10-3559



8906-37-280-0003

Photos 5-10

Views of 1991 Pontiac Grand Prix which was parked in left side of garage - out of the fire's origin.



1991-005-LP-3801



BR25-093-LC-3882



Photos 11-14 Interior views of garage showing fixed electrical wiring had been installed (12-13), but NO electrical power to garge (14).



2025 RELEASE UNDER E.O. 14176



EMD-005-LC-3884

Photos 15-20


Exterior views of subject 1995 Ford F-150 pickup truck showing most severe fire damage was to front end (15).



EMPS-005-LC-36003



PHOTO-805-LC-3898



Photos 21-22 Views of front wheels showing damage. NOTE: rear tires and wheels were in good condition.



2025-005-10-3107



Photos 23-29 Interior views prior to (23-25) and after (26-29) debris removal. NOTE: floor mats remained on both sides (28-29) indicating fire's origin was not at floorboard level.



DAVID-802-1-C-3828



24



25



26

EMPS-003-10-3608



Photos 30-31 Views of engine compartment.



ENG-003-10-3511

Photo 32

View of battery - ruled out as cause of fire.



32

Photo 33

View of starter - ruled out as cause of fire.



33

Photo 34

View of fuel lines showing some still connected to fuel rails.



Photos 35-36

Views of plenum showing good condition of left (driver) side (35) and severely fire damaged right (passenger) side (36) which indicated fire's origin was on right side in engine compartment.



EMPS-809-LC-3613



Photo 37 *View of main supply circuit to alternator.*



Photo 38


View of inside coil of solenoid.



Photos 39-40

Views of rectifier assembly recovered from fire debris showing severe fire damage. The rectifier is mounted inside the alternator and 1) lets current flow more readily in one direction than in reverse direction and 2) changes alternating current to direct current.





Photos 41-42 Views of alternator rotor and stator assembly recovered from fire debris showing severe damage.



BBB-80-1-03818




END OF PHOTO INDEX



EPMS-005-LC-3818



6905-009-LC-2019



EMF-003-LC-3020



5905-085-LC-3621



ENG-685-LC-3822



BRN-005-LO-3823



ENG-885-LC-3824

12-1446 - 842 (ref)
42-1446 - 841 (ref)

Att: 11/10 (ref)

423-477-3201 (ph)
423-477-5309 (fax)

TOWN OF MOSHEIM FIRE DEPARTMENT
1000 MAIN STREET 422-7401

DATE: 1-24-02 TIME OUT: 01:24 TRUCK RETURN: 09:20 AM

NAME OF OWNER: [REDACTED] TEMP. WET/DRY 50

ADDRESS: [REDACTED] PHONE: [REDACTED]

STRUCTURE: GRASS: AUTO: MVA STANDBY:

OTHER: MVA TAG NUMBER ON VEHICLES: [REDACTED]

INSURANCE INFORMATION: State Farm

POSSIBLE CAUSE OF FIRE: Electric short in truck

ESTIMATED DAMAGE: TOTAL LOSS

DESCRIPTION OF FIRE ON ARRIVAL: Fully Involved
95 Ford 92 Grand Prix Garage

WAS ANYTHING SAVED: NO

PERSONS PRESENT AT TIME OF CALL: NORMA MELTON

COMMENTS: 911 Paged out Fire Dept. at
1:24 we arrived at 126 garage was
fully involved all contents and garage
TOTAL LOSS.

UNITS RESPONDING: 1110 MILEAGE 22587
8 TRUCK HOOPS
26 members
1111 MILEAGE 16614
1112 MILEAGE 65991
1113 MILEAGE 57499

PQO

OFFICER IN CHARGE: [Signature]
OFFICER APPROVED: [Signature]

REPORT FILED: [Signature]

ORIGINAL COPY
MAR 26 2002



FORMS-025-1C-3025

FIREFIGHTERS ON CALL

- | | |
|-------------------------------|----------------------------------|
| 1. DONALD NORTON <u>X</u> | 2. JESSIE LOWERY <u> </u> |
| 3. ANTHONY SHIPLEY <u> </u> | 4. MIKE HIXSON <u>X</u> |
| 5. RONNIE BROWN <u>X</u> | 6. TIM. FRYE <u>X</u> |
| 7. RICK SAYNES <u> </u> | 8. TONY MOORMAN <u>X</u> |
| 9. JIM BARTMAN <u> </u> | 10. CAROLL COMBS <u>X</u> |
| 11. TIM JONES <u> </u> | 12. PAUL PARTIN <u>X</u> |
| 13. DONALD SMITH <u> </u> | 14. MICHAEL PARKS <u>X</u> |
| 15. JUSTIN BROWN <u>X</u> | 16. EARL FLETCHER <u> </u> |
| 17. DARRYL DAVIS <u> </u> | 18. RONNIE CARMICHAEL <u> </u> |
| 19. DAVE CHANDLER <u>X</u> | 20. JAMES FOSHIE <u> </u> |

*James Foshie
Cajey Greente
Kevin Ricker*

ASSISTED BY:

FIRE DEPARTMENT: Bulls CAP 1 Tanker 1 Pumper
8 members

RESCUE: EMS

SHERIFF'S DEPARTMENT: 4 units CO Terry Rader

IDEA / BILL BROWN: ✓

COMMENTS: FBK 701 95 Ford
Belonging to JAP Paula Patterson
FBK 944 92 motor.

Belonging to same total loss on both
AND charge total ADAD support BURNS

*Wrote from heat
D!! contents lost*

PAGE: 0124
TIME OUT: 0122
ON SCENE: 0134
CLEAR CALL: 0310
BACKSTATION: 0520

PQO

Small yard Damage at 7782 ul
neighbor's yard

ORIGINAL COPY
MAR 26 2002

ENG-005-10-3827

EDMS-SMS-LO-0028

121

121

50

EX-105-LC-3828



EXHIBIT - 00001 - L.C. - 00001

ENG-885-LC-3631

EX-105-685-11-2012



State Farm Insurance Companies



South Central Office
2500 Memorial Boulevard
P.O. Box 20727
Memphis, TN 37128-0082

April 26, 2002

Alan Robinson
Ford Motor CO
3 Parklane Blvd, Ste 400
Dearborn, MI 48126-2568

RE: Claim Number: [REDACTED]
Date of Loss: January 24, 2002
Our Insured: [REDACTED]
Amount of Loss: \$3,887.00

Dear Mr Robinson:

The information we have in our file indicates you are responsible for damage to our insured's property which occurred on the above date.


By virtue of our payment, we are entitled to recovery of the amount paid on behalf of our insured from the responsible party. If you have insurance to protect you against such liability, please refer this letter to your insurance company and advise us as to your insurance company's name, address, and your phone number.

If you do not have insurance to protect you for this loss, we request payment of the total amount due within 30 days from the date of this letter.

If you cannot arrange payment in full as requested, please contact us at the above address to discuss payment terms. Should we not hear from you within the specified time, we will have no alternative other than to refer this matter to our attorney.

Sincerely,
James E. Gregory

James E. Gregory
Claim Specialist
(888) 898-6216
SUBROGATION UNIT
State Farm Mutual Automobile Insurance Company



IN THE CIRCUIT COURT OF THE 11TH JUDICIAL
CIRCUIT IN AND FOR MIAMI-DADE COUNTY, FLORIDA
GENERAL JURISDICTION DIVISION
CASE NO.

STATE FARM MUTUAL AUTO INSURANCE CO,
as subrogee of [REDACTED]

2001 2 24 18 CA 10

vs.

COMPLAINT

FORD MOTOR COMPANY,

Florida Bar No. 221260

Defendant

Plaintiff sues the Defendant, and alleges:

1. This is an action for damages within the jurisdictional limits of this Court.
2. On or about October 22, 2001, at or near Collins Avenue and 200 Street, Miami Beach, Dade County, Florida, Plaintiff's subrogor owned a 1997 Ford Expedition, Florida license plate number [REDACTED]
3. At the above time and place, the vehicle of Plaintiff's subrogor caught fire due to the improper and or negligent design and or engineering by Defendant, FORD MOTOR COMPANY.

Count II against Ford Motor Company:

4. Defendant, FORD MOTOR COMPANY, manufactured a product known and described as a 1997 Ford Expedition.
5. Defendant, FORD MOTOR COMPANY, warranted that the product was reasonably fit for its intended use as a private passenger automobile.
6. On October 22, 2001 at or near Collins Avenue and 200 Street, Miami-Dade County, Florida, a fire erupted from an electrical malfunction due to a manufacturing defect during assembly as the vehicle was being used for it's intended purpose causing a loss of the vehicle.
7. As a result of the negligence of said Defendant, the vehicle of Plaintiff's subrogor was damaged and depreciated in value and the value of its use was lost.
8. By reason of the incident alleged, STATE FARM MUTUAL AUTO INSURANCE COMPANY, became liable under a policy of comprehensive insurance issued to its subrogor to pay and at diverse times did pay to or the benefit of its insured, the losses resulting in a total sum as claimed. Plaintiff's insured has an uncompensated deductible in the amount of \$500.00, which STATE FARM MUTUAL AUTO INSURANCE COMPANY claims as assignee of it's insured.
9. By reason of the above payments and the above assignment, Plaintiff, STATE FARM MUTUAL AUTO INSURANCE CO, became subrogated to the rights of its insured against the Defendant.

WHEREFORE, Plaintiff demands Judgment in the sum of \$15,651.63, together with Court costs, pre-judgment interest if applicable, appropriate loss of use and diminution in value, and any further costs the Court may assess.

STEPHEN C. SHENKMAN & ASSOC., P.A.
Attorneys for Plaintiff
10121 S.W. 40th Street
Miami, FL 33165
Telephone: (305) 559-2200
Outside Dade: (305) 1-800-255-5485

BY: _____

STEPHEN C. SHENKMAN

IMPORTANT

comme ci-dessous.

EROS-005-LC-3635

ISSUE LIST

Last Handling Date/ Issue Status	Name/ Reason Desc	Vin/ Case No.	Model Year and Vehicle Line	Issue Type
11/1/2001 CLOSED	[REDACTED] LEGAL - INSURANCE COMPANY SETTLEMENT	1FMEU1783VLB13078 482863041	1997 EXPEDITION	02

ENR03-003-1C-3028

All Action Details for Issue

Print

VIN: 1FMEU1783V [REDACTED]	Year: 1997	Model: EXPEDITION	Case: 482863041
Name: [REDACTED]	Owner Status: Subsequent	WSD: 1997-10-09	
Symptom Desc:		Primary Phone: [REDACTED]	
Reason Desc: LEGAL - INSURANCE COMPANY SETTLEMENT		Secondary Phone: [REDACTED]	
Issue Type: 02 INFORMATION	Issue Status: CLOSED		

Action: ADVISE CUSTOMER TO CONTACT THEIR INSURANCE COMPANY FOR ASSISTANCE

Dealer:

Odometer: 60000 MI

Analyst Name: DENNIS RENWICK

Action Date: 10/31/2001

Comm Type: PHONE

Analyst: DRENWICK

Action Time: 13.24.58.594

Origin Desc: US CONCERN CASE BASE

Action Date: No

Comments CUSTOMER SAYS: EXPEDITION CAUGHT ON FIRE - ENGINE COMPARTMENT CUST FEELS THAT IT WAS DUE TO WINDSHIELD WIPER FAILURE INSURANCE CO WROTE IT OFF AND CUST DOES NOT KNOW THE PAYOFF FIGURE SEEKING TRADE IN ASSISTANCE FOR PURCHASING ANOTHER FORD - FEELS THAT FORD SHOULD SUPPLEMENT PAYOFF FROM INS CO PER CUSTOMER, DEALER SAYS: NONE CAC ADVISED: - PLEASE DISCUSS THIS ISSUE WITH YOUR INSURANCE COMPANY. IF YOUR INSURANCE COMPANY FEELS THAT FORD IS AT FAULT THEY HAVE THE RIGHT TO PURSUE CLAIMS FOR REIMBURSEMENT AGAINST FORD. INFERENCE CASE ID: 5350

Action: ADVISE CUSTOMER TO CONTACT THEIR INSURANCE COMPANY FOR ASSISTANCE

Dealer:

Odometer: 60000 MI

Analyst Name: CHELSEY I. DECHER

Action Date: 11/01/2001

Comm Type: MAIL

Analyst: CDECHER

Action Time: 10.02.21.220

Origin Desc: US CONCERN CASE BASE

Action Date: No

Comments CUSTOMER SAYS: VEH CAUGHT ON FIRE AND IS TOTALLED WANTS A COUPON OR VOUCHER TO GET A NEW VEH -DOES NOT WANT TO BE PENALIZED FOR BEING A LOYAL FORD CUST -FIRE STARTED UNDER HOOD, -POLICE CALLED -INSURANCE CLAIM FILED PER CUSTOMER, DEALER SAYS: CALL CRC- CAC ADVISED: - PLEASE DISCUSS THIS ISSUE WITH YOUR INSURANCE COMPANY. IF YOUR INSURANCE COMPANY FEELS THAT FORD IS AT FAULT THEY HAVE THE RIGHT TO PURSUE CLAIMS FOR REIMBURSEMENT AGAINST FORD. INFERENCE CASE ID: 5350

E005-005-L-C-0037

CAUSE NO. 2003-CCL-14 FILED FOR RECORD

[REDACTED]

VS.

FORD MOTOR COMPANY

*
*
*
*
*
*

AT 1 O'CLOCK PM
IN THE COUNTY COURT
FEB 18 2003
AT LAW NO. 1
JOE G. RIVERA
CAMERON COUNTY CLERK
OF CAMERON COUNTY, TEXAS Deputy

PLAINTIFFS' ORIGINAL PETITION

TO THE HONORABLE JUDGE OF SAID COURT:

COMES NOW [REDACTED]

Plaintiffs, complaining of FORD MOTOR COMPANY, hereinafter "Defendant", and for cause of action would respectfully show as follows:

1.

Discovery in this action shall be conducted under Rule 190.3 of the Texas Rules of Civil Procedure.

2.

Plaintiffs are residents of Cameron County, Texas.

3.

Defendant is a foreign corporation doing business in Cameron County, Texas, and may be served with by serving its registered agent, CT Corp, at its registered address for service of process, 350 N. St. Paul, Dallas, Texas, 75201.

4.

This suit is filed pursuant to the provisions of Tex. Bus. & Com. Code Ann. Sec. 17.41 et seq., commonly known as the Deceptive Trade Practices-Consumer Protection Act and hereinafter referred to as "D.T.P.A." upon the grounds that the acts or omissions described herein are prohibited by this statute.

5.

Written notice of the claims made herein have been given in the manner and form required by the D.T.P.A.

6.

Whenever in this petition it is alleged that Defendant did any act or thing it is meant that the Defendant's officers, agents, servants, employees or representatives did such act or thing and that at the time of such act or thing was done, it was done with the full authorization or ratification of Defendant, or it was done in the normal, routine course and scope of employment of Defendant's officers, agents, servants, employees or representatives.

7.

Plaintiffs purchased a 1997 Ford F-150 pickup truck, vehicle identification number 1FTEX17L4VN [REDACTED] which was designed and manufactured by Defendant. On or about August 12, 2001, the vehicle

EW-5-000-LC-3639

was driven and then parked in Plaintiffs' garage at 701 N. Indiana, Brownsville, Texas. Due to a defect in the pickup truck gasoline leaked and was ignited by the hot motor, causing a fire which ultimately gutted Plaintiffs' house.

8.

Said defect amounted to a breach of the implied warranty of merchantability in violation of section 17.50 (a) (2) of the DTPA and was a producing cause of the following damages:

- a. Damage to Plaintiffs' house and its contents in the amount of \$250,000.00;
- b. Loss of use of Plaintiffs' home since the fire; and,
- c. Extreme mental anguish and inconvenience.

9.

The unlawful acts and practices described-above were committed knowingly by Defendant.

10.

The undersigned attorney has been retained by Plaintiff to pursue the causes of action alleged herein. Pursuant to D.T.P.A. Sec. 17.50, all attorneys fees that are reasonable and necessary in this cause may be recovered by Plaintiff.

ENR-809-LO-3840

11.

WHEREFORE, Plaintiffs pray that Defendant be cited according to law to appear and answer herein and that after trial by jury that Plaintiffs have judgment against Defendant for those damages described-above in the full amount allowed by law, together with pre and post-judgment interest on such amount at the legal rate;

Plaintiffs further pray for additional damages pursuant to Section 17.50 of the D.T.P.A., in an amount not to exceed three times the amount of actual damages.

Plaintiffs further pray for attorneys fees that are reasonable and necessary in this cause as set-forth above, and for costs of court.

Plaintiffs further prays for such other and further relief to which Plaintiffs may be justly entitled.

Respectfully submitted,



BARRY R. BENTON
284 Ebony Avenue
Brownsville, Texas 78520
(210) 546-9900 Telephone
(210) 546-9997 Facsimile
State Bar No. 02176500
Cameron County I.D. No. 3101
ATTORNEY-IN-CHARGE FOR
PLAINTIFFS

EX-105-10-3011

Darryl R. Denton



284 Ebony Avenue
Brownsville, Texas 78520-8014

Attorney at Law

(956) 546-9900
Fax (956) 546-8997

July 23, 2002

Shawn L. Norton
Claims Analyst
Ford Motor Company
Parklane Towers West
Suite 300
Three Parklane Blvd.
Dearborn, Michigan 48126-2568

CMRRR No. 70010320000555199760

Re: [REDACTED] and one 1997 Ford F-150 pickup truck

Dear Mr. Norton:

I have been retained by [REDACTED] to help them in their claim against your company. Their prior correspondence to you, along with documentation of their claim, has to date proved fruitless.

My clients' claim arises under the following facts and circumstances:

On August 12, 2001 my clients' 1997 Ford F150 pickup truck, serial no. 1FTEX17L4VN [REDACTED] caused a fire in the [REDACTED] home, destroying the house and contents. The 3,800 square foot home is valued at \$190,000.00, the contents \$60,000.00. My clients were without homeowner's insurance at the time.

From reviewing the file I see that my clients have already sent to you a copy of the Fire Marshall's report, indicating that the fire seems to have originated in the engine compartment of the truck, and a copy of the Recall Summary for the truck, which indicates that the front fuel line

EN02-003-LC-2842

assembly could have a hole rubbed through it in two locations which could result in fuel leakage and ultimately a fire. We believe this is the likely cause of my clients' damage and amounts to a breach of the implied warranty of merchantability.

My clients' claim is being made pursuant to the Texas Deceptive Trade Practices-Consumer Protection Act. If your company will pay my clients' actual damages of \$250,000 within 60 days of your receipt of this letter, my clients will gladly sign a release of all claims. Otherwise, you will leave me no choice than to recommend my clients that suit be filed in which we will seek, in addition to my clients' actual damages, treble damages as provided for in the act, attorney's fees, expenses, and costs of court.

I see from my file that my clients have sent you substantial documentation. However, if you are in need of any additional information to evaluate this claim, please advise.

Cordially Yours,

A handwritten signature in black ink, appearing to read "Barry R. Benton". The signature is fluid and cursive, with a long horizontal stroke at the end.

Barry R. Benton

BRB/ph
c: Mr. and Mrs. Julio Ramirez
(address on file)

ER05-005-LC-3843




FIRE INVESTIGATION REPORT

Fire Marshal's Office
 Dept. g. Nelson
 Cameron County Courthouse
 964 E. Harrison St.
 Administrative Bldg. 4th Floor
 Brownsville, Texas
 (956) 544-0900 Office
 (956) 284-5244 Fax

FIRE DATE	August 12, 2001
TIME ALARM RING	1443 hrs.
INCIDENT #	01000022 (county)
WEATHER	Cloudy
OFFICER IN CHARGE	Aunt. Chief Joe Casarez B.F.I.
UNITS RESPONDING	Brownsville, Los Frances Fir Dept.
ADDRESS OF FIRE	[REDACTED] Brownsville, Tx (rear)
SIZE	
TYPE OF OCCUPANCY	Residential
NAME OF OCCUPANT	[REDACTED]
ADDRESS	[REDACTED]
NAME OF OWNER	[REDACTED]
ADDRESS	[REDACTED]
DATE INVESTIGATED	Aug. 12, 2001
TIME ARRIVED	1618 hrs
PHOTOS TAKEN	Yes
PERSONS INJURED/KILLED	No injuries
INVESTIGATOR	Dept. g. Nelson
EVIDENCE REMOVED	No
ORIGIN OF FIRE	Vehicle in enclosed garage attached to home.
FIRE CAUSE	Undetermined
INVESTIGATOR'S REMARKS	Fire seems to have originated in the engine compartment of a 1987 Ford F150. License Plate 3 HUCV68 Texas VIN 8 FT8X7LAV [REDACTED] Approximately \$18,000.00 loss on vehicle. Insurance with Phoenix Agency LLC, P.O. Box 277 Min, Tx. (956) 763-2111. Fire spread thru ceiling in enclosed garage to the main area of the house causing heavy damage throughout the house. House valued at approximately \$50,000.00. House not listed as per owner.
INVESTIGATOR'S SIGNATURE	[Signature]
DATE	August 12, 2001

LISA.
 HERE IS THE
 FIRE RPT. WE GOT
 FROM THE INSURED.

Julio Ramirez
701 N. Indiana Ave.
Brownsville, Tx. 78521-6842
956-831-7233



Ford Motor Company
Parklane Towers West
Suite 300
Three Parklane Boulevard
Dearborn, Michigan 48126-2568

ATTENTION: MR. SHAWN NORTON

RE: Claimant: [REDACTED]

Dear Mr. Norton:

Thank you for your request into my 1997 Ford F-150 pick up truck that caught on fire. Here is the response to your questions.

1. The date of the incident occurred on August 12, 2001 in Brownsville, Tx. 78521
2. My brother-in-law [REDACTED] drove my pick up truck about one block and parked it back into the garage of my home. He closed the garage door and then left. A passing motorist saw the smoke coming from my house and called the fire department. My security company received an alarm from my house and proceeded to call the fire department. The fire department arrived at 2:43 PM and extinguished the fire.
3. Copy of Fire Investigation Report attached.
4. N/A
5. 1997 Ford F-150 Pick-Up Truck Serial # 1FTEX17L4V1 [REDACTED]
6. Approximately 205,000 miles.
7. Photographs enclosed.
8. N/A
9. N/A
10. The engine compartment.
11. Copy of Fire Investigation Report attached.
12. No
13. A [REDACTED] Brownsville, Tx [REDACTED]
14. Attached is a copy of the draft for the pick up truck and my house was a total loss.
15. I personally performed one oil change on my truck since purchasing it in December of 2000.
16. None
17. N/A

18. N/A

19. N/A

20. N/A

21. No

22. No

23. Phsonix Agency - 1315 West Polk #22, Pharr, Tx. 78577 (956)-783-8500

Policy [REDACTED]

24. No.

25. Attached copy of Bill of Sale.

If you need any further information regarding this claim please do not hesitate to contact me.

Thank you,



Julio Ramirez

VIN: 1FTEX17L4VN [REDACTED] Year: 1997 Model: F-SERIES
 Owner Status: SUBSEQUENT WSD: 10/24/96
 Name: [REDACTED] Hm Ph: [REDACTED]
 Trmt: Case: 1606983021 Day Ph: [REDACTED]
 Symptom Desc: FIRE/SMOKE SCORCHED/BURNT UNDERHOOD
 Reason Desc: FIRESTONE TIRE ISSUE
 Dealer: TIPTON MOTORS INC
 Issue Type: 07 LEGAL Issue Status: O OPEN
 Comm Type: PH PHONE Odometer Reading: 200000 MI
 Analyst: DFLETCHER DENISE FLETCHER Document Number:
 Action Date: 10/29/01 Action Data: Action Time: 16:32:49 EST
 Origin Desc: US CONCERN CASE BASE
 Action Desc: ADVISE CUSTOMER INFORMATION FORWARDED TO CONSUMER AFFAIRS
 Comments: CUSTOMER SAYS: -VEH WAS SITTING IN GARAGE AND VEH JUST CAU
 GHT ON FIRE WITHOUT THE IGNITION BEING ON -HOUSE WAS BURNED
 DOWN BECAUSE OF THIS -CUST WANTS TO KNOW WHY THIS HAPPENED
 -INSURANCE COMPANY HAS BEING CONTACTED -FIRE MARSHALL SAI
 D THAT VEH BURNED THE HOUSE DOWN -NO ONE WAS HURT PER CUS
 TOMER, DEALER SAYS: -NONE CAC ADVISED: - THIS INFORMATIO

F1=Help F2=AddAction F4=PrevAction F5=NextAction F6=ActionData
 F9=PrevComments F10=NextComments F11=Menu F12=Return F13=ESP
 MORE COMMENTS AVAILABLE LPREL49

~~Teresa~~ Home burned down completely
 I
 8-5pm Total loss
 PO Box 4840
 Brownville 78523



==>
 VIN: 1FTEX17L4VN [REDACTED] Year: 1997 Model: F-SERIES
 Owner Status: SUBSEQUENT WSD: 10/24/96
 Name: [REDACTED] Hm Ph: [REDACTED]
 Trmt: Case: 1606983021 Day Ph: [REDACTED]
 Symptom Desc: FIRE/SMOKE SCORCHED/BURNT UNDERHOOD
 Reason Desc: FIRESTONE TIRE ISSUE
 Dealer: TIPTON MOTORS INC
 Issue Type: 07 LEGAL Issue Status: 0 OPEN
 Comm Type: PH PHONE Odometer Reading: 200000 MI
 Analyst: DFLETCHER DENISE FLETCHER Document Number:
 Action Date: 10/29/01 Action Data: Action Time: 16:32:49 EST
 Origin Desc: US CONCERN CASE BASE
 Action Desc: ADVISE CUSTOMER INFORMATION FORWARDED TO CONSUMER AFFAIRS

Comments: TOMER, DEALER SAYS: -NONE CAC ADVISED: - THIS INFORMATION HAS BEEN FORWARDED TO THE CONSUMER AFFAIRS DEPARTMENT FOR REVIEW - A REPRESENTATIVE FROM CONSUMER AFFAIRS WILL FOLLOW UP ON YOUR CLAIM - NO TIME FRAME AVAILABLE - PLEASE MAKE SURE YOU NOTIFY YOUR INSURANCE CARRIER AND REPORT THE INCIDENT - NOTE TO CSR: IF CUSTOMER IS WORKING WITH A NON-FORD D

F1=Help F2=AddAction F4=PrevAction F5=NextAction F6=ActionData
 F9=PrevComments F10=NextComments F11=Menu F12=Return F13=ESP
 MORE COMMENTS AVAILABLE

LPREL49

==>
VIN: 1FTEK17L4VA [REDACTED] Year: 1997 Model: F-SERIES
Owner Status: SUBSEQUENT WSD: 10/24/96
Name: [REDACTED] Hm Ph: [REDACTED]
Trmt: [REDACTED] Case: 1606983021 Day Ph: [REDACTED]
Symptom Desc: FIRE/SMOKE SCORCHED/BURNT UNDERHOOD
Reason Desc: FIRESTONE TIRE ISSUE
Dealer: TIPTON MOTORS INC
Issue Type: 07 LEGAL Issue Status: O OPEN
Comm Type: PH PHONE Odometer Reading: 200000 MI
Analyst: DFLETCHER DENISE FLETCHER Document Number:
Action Date: 10/29/01 Action Data: Action Time: 16:32:49 EST
Origin Desc: US CONCERN CASE BASE
Action Desc: ADVISE CUSTOMER INFORMATION FORWARDED TO CONSUMER AFFAIRS
Comments: NT - YNOTE TO CSR: IF CUSTOMER IS WORKING WITH A NON-FORD D
EALERSHIP, PLEASE ASSIGN THE NEAREST FORD DEALERSHIP TO THE
CONTACT INFERENCE CASE ID: 5305

F1=Help F2=AddAction F4=PrevAction F5=NextAction F6=ActionData
F9=PrevComments F10=NextComments F11=Menu F12=Return F13=ESP
NO MORE COMMENTS AVAILABLE

LPREL49

=>

VIN: 1FTEX17L4VW Year: 1997 Model: F-SERIES
 Name:
 Trmt: Case: 1606983021
 Issue Type: 07 LEGAL Issue Status: C INVESTIGAT
 Comm Type: PH PHONE Odometer Reading: 200000
 Dealer: 04421 TIPTON MOTORS INC Odometer Type: MI
 Symptom Desc: FIRE/SMOKE SCORCHED/BURNT UNDE Document Number:
 Reason Desc: FIRESTONE TIRE ISSUE Legal Issue Type:
 Origin Desc: CONSUMER AFFAIRS - LITIGATION CAN Court Code:
 Action Desc: REDIRECT TO OGC - PROPERTY DAM CAN Award Code:
 Comments: LPA IS FORWARDING ISSUE TO OGC. CUSTOMER ALLEGES VEHICLE FI
 RE CAUSE HOUSE TO BURN DOWN COMPLETELY. TOTAL LOSS. INFORM
 ATION FORWARDED TO OGC.

F1=Help F2=ActionList F5=Add F6=DealerInfo
 F9=PrevComments F10=NextComments F11=Menu F12=Return F13=DealerList
 UPDATE SUCCESSFUL LPREL49


000 488 WEST

DATE	TIME	TO/FROM	MODE	MIN/SEC	PGS	JOB#	STATUS
10	11/06	11:33 RALPH NEMELL	EC-S	00:11	001	152	OK

LINCOLN LINCOLN JUDGE FRAYSON JEFF WARR

FIRE INVESTIGATION REPORT	
The Sheriff's Office Dept. of Justice Criminal Justice Institute 204 E. Harrison St. Administration Bldg. 4 th Floor Brownsville, Texas (361) 534-6000 ext. (361) 534-6246 fax	
FIRE DATE	August 12, 2001
TIME OF INCIDENT	1745 hrs.
INCIDENT'S ADDRESS	1745 hrs.
WEATHER	Cloudy
OFFICER IN CHARGE	SAUL CHAZ JEN CHAZO S.F.D.
UNIT/REPORTING	Brownsville, Lab Police PD Dept.
ADDRESS OF FIRE	1745 hrs.
TYPE OF OCCUPANCY	Residential
NAME OF OCCUPANT	[REDACTED]
ADDRESS	1745 hrs.
DATE OF INCIDENT	Aug. 12, 2001
TIME ARRIVED	1745 hrs.
PROCES TAKEN	Yes
PERSONS INJURED/KILLED	NO INJURY
INVESTIGATOR	COUL G. NEMELL
INCIDENT REPORTED	NO
CHARACTER OF FIRE	Match in cigarette ignited in room.
FIRE CAUSE	Undetermined
IDENTIFICATION NUMBER	Fire cause to have originated in the engine compartment of a 2001 Ford Fire Truck #20000 from the U.S. Fire Dept. (approximately \$15,000 loss of value). Reported with Police Agency 1127 P.M. from 1127 West, TX 77801. Fire spread causing an extensive garage fire with loss of life because of fire. Although throughout the house, there was a loss of approximately \$20,000.00. House not insured to per value.
INVESTIGATOR'S SIGNATURE	[Signature]
DATE	11/06/02


LISA.
 HERE IS THE
 FIRE RPT. WE GOT
 FROM THE INSURED.



Chrysler Insurance Company

June 2, 2000

FORD MOTOR COMPANY
CONSUMER AFFAIRS
16800 EXECUTIVE PLAZA DRIVE MD#3NE-B
DEARBORN MI 48126-4207



CUSTOMER SUPPORT CENTER
CHRYSLER INSURANCE

Our Insured : Quality Ford-Mercury, dba Ron King Motors
Claim Number : 200005732
Vehicles : 1999 Ford F-150 Lariat XLT 1FTRX18L8XX [REDACTED]
Date of Loss : May 20, 2000

To Whom It May Concern:

We have concluded our investigation into the above referenced vehicle fire loss.

The investigator determined that the fire originated within the engine compartment where oil was leaking from the valve cover, running down onto the exhaust manifold where upon ignition, the fire extended up and outward from that location causing the resulting damage.

\$21,500.00

The origin of the fire is substantiated by our insured's statement that the fire was observed venting out of the wheel well on the left side in addition to the extensive fire damage to the fiberglass valve cover.

As the fire was the direct result of a mechanical failure and the vehicle's 36 month, 36,000 mile warranty remains in full force and effect, we are seeking complete reimbursement of our damages from Ford Motor Company.

This letter serves as our legal written notice of subrogation. Our insured suffered and Chrysler Insurance Company has paid damages in the amount of \$21,500.

The vehicle is currently at Copart, 6100 Woodmar, Hammond IN 46320 telephone # 219-844-4060 stock # 2895170. The vehicle will remain at this location for sixty days.

Please take the steps necessary to inspect the vehicle and contact me at the telephone number indicated below.

Sincerely,

Craig S. Boury
Craig S. Boury
Claim Representative
248-948-4846

P.O. Box 5168
Southfield, MI 48086-5168

ER05-005-LC-3852

July 5, 2000

IN RE: Chrysler Insurance Claim No. [REDACTED]
H&A File No. 00-1212VF
QUALITY FORD-MERCURY, d/b/a RON KING MOTORS

HERNDON
ASSOCIATES

Investigators/Consultants

585 East Larned, Suite 100
Detroit, Michigan 48226-4314
FAX: 313 964-0336

1 800 961-2909
walt@herndon-assoc.com
dave@herndon-assoc.com

P.O. Box 27
Bozysa City, Michigan 49712
231 582-3543

Licensed in Michigan,
Ohio, Illinois

PREDICATION:

This report is predicated upon the request of Mr. Craig Boury, Chrysler Insurance Claims Representative, to conduct an investigation into Quality Ford-Mercury, d/b/a Ron King Motors, with special reference to the fire loss of a 1999 Ford, F-150.

INSPECTION:

On June 28, 2000 at 3:30 p.m., Investigators Walt Herndon and Devin Jordan arrived at Copart in Hammond, Indiana to conduct an investigation into the fire loss of a 1999 Ford, F-150.

Once at the scene, a close inspection provided the following information:

SEE ENCLOSED INVESTIGATION REPORT

Prior to leaving the scene, several 35mm color photographs were taken and are enclosed.

ORIGIN AND CAUSE INVESTIGATION:

On June 28, 2000 at 3:30 p.m., Investigators Walt Herndon and Devin Jordan arrived at Copart in Hammond, Indiana to conduct an origin and cause investigation into the fire loss of a 1999 Ford, F-150, Lariat KLT, blue in color, Vehicle Identification Number 1FTRX18L8X[REDACTED]. Upon arriving at the facility, the vehicle is brought forward and is identified by its vehicle identification number located in the area of the windshield and dash. Initial

ER05-085-LC-3853

IN RE: Chrysler Insurance Claim No. [REDACTED]
H&A File No. 00-1212VF
QUALITY FORD-MERCURY, d/b/a RON KING MOTORS

July 5, 2000
Page 2.

observations reveal evidence of a fire to have originated within the engine compartment, with the most severe damage present to the left or driver's side. The fire has extended to consuming a portion of the left front tire causing it to deflate, further extending to consuming sections of the plastic wraparound bumper on the left or driver's side. The examination further reveals that the headlight assembly has melted, falling out during the course of the fire on the driver's side; however, the one on the right or passenger side is fire damaged yet intact. The examination further reveals the remains of the aluminum hood on the right or passenger side, with the aluminum hood totally consumed on the left or driver's side. The examination continues and the left front tire is intact, inflated, with plastic from the inner wheel well having melted over the tire.

The examination continues and the fire has breached the bulkhead and windshield, entering the passenger compartment, causing the first stages of melting of the dashboard, rolling over the roof, causing fire damage from the top down.

The investigation is now focused to the bed of the truck where there is no evidence of any direct fire impingement. The examination of both rear tires, as well as the underside of the vehicle, reveals that it is free of any fire damage.

The examination is now focused to the fuel tank, fill tube, and gas which are intact, with no evidence of any fuel leakage.

The investigation is now focused to the rear jump seat area where there is evidence of high burning, caused from when the fire rolled over the roof causing fire damage from the top down. The examination further reveals that the upper portion of the front seats are partially consumed and the lower section of the seats are intact.

The investigation continues and the driver's door window has been broken in during the course of firefighting and all other remaining glass, with the exception of the windshield, is intact. At this time, after completing an examination of the passenger compartment, no evidence of any fire origin could be found.

The investigation is now focused to the engine compartment where a check of the fluid levels reveal the oil and transmission fluids are full, and all other fluids drained during the course of the fire. The examination further reveals that the battery is

IN RE: Chrysler Insurance Claim No. [REDACTED]
H&A File No. 00-1212VF
QUALITY FORD-MERCURY, d/b/a RON KING MOTORS

July 5, 2000
Page 3.

located in the right front, is heat damaged, exposing the plates. Upon examining the battery cables, although they have melted out of the battery, there is no evidence of any electrical faulting.

The examination is now focused to the starter relay which is intact, and upon tracing the cable that travels from the starter relay to the alternator, although void of insulation, there is no evidence of any electrical faulting. The examination of the heater hoses reveal evidence of exposure damage on the right or passenger side, there is evidence of exposure fire damage to the valve cover; however, the damage is less severe than that of the left or driver's side.

The investigation is now focused to the transmission cooler hoses which have been consumed during the course of the fire. The examination further reveals that this is secondary, based upon combustibles remaining in the immediate area of the transmission cooler hoses.

The investigation is now focused to a power steering hose in the left front, there is hose remaining and, at this time, it is determined that this is secondary. The examination of the radiator hose on the left or driver's side reveals evidence of exposure fire damage, however, no evidence of any fire origin.

The examination is now focused to the front section of the engine, specifically the cast aluminum plenum where the fire damage is much more pronounced than that of the rear of the engine. The examination further reveals that the fuel rail on the left or driver's side is intact, fuel injectors are fire damaged, and the combustible fuel hoses that connect into the fuel rail have been consumed. The examination continues and upon examining the power distribution center in the left rear of the engine, a substantial amount of combustibles remain, ruling out the fire as having originated within this area. The examination of the left front of the engine compartment reveals wiring void of insulation, however, there is no evidence of any electrical faulting.

The examination is now focused to the wiring harness that travels along the bulkhead and, although it is void of insulation, there is no evidence of any electrical faulting.

At this time, the investigation is focused to the valve cover on the left or driver's side where upon removing the valve cover, there is evidence of a section of the rubber gasket closest the

IN RE: Chrysler Insurance Claim No. [REDACTED]
H&A File No. 00-1212VF
QUALITY FORD-MERCURY, d/b/a RON KING MOTORS

July 5, 2000
Page 4.

exhaust manifold heavily fire damaged, and there is a section of the rubber gasket exposed from the valve cover as well. The section of the rubber gasket in the left front was consumed, which was confirmed by the fact that the fiberglass valve cover within this area was consumed.

At this time after completing the above inspection and examination, no evidence of any electrical failure could be found and attributed to the cause of the fire. The fire originates within the engine compartment where oil was leaking from the valve cover onto the exhaust manifold and, upon ignition, the fire extended upward and outward from that location causing the damage present. The fire is deemed to be an accidental fire.

NICB VINASSIST:

A review of the NICB Vinassist indicates that the 1999 Ford, F-150 4X4, is equipped with a 5.4 liter V-8 engine, and was assembled in Kansas City, Claycomo, Missouri.

NATIONAL HIGHWAY TRAFFIC & SAFETY ADMINISTRATION:

A search of the National Highway Traffic & Safety Administration, Recall Database, produced three records pertaining to the vehicle in question. Upon reviewing same, none were found to pertain to the fire in question.

A further search was conducted of the National Highway Traffic & Safety Administration, Investigations Database, which produced one record pertaining to the vehicle in question. Upon reviewing same, it was found not to pertain to the fire in question.

ALldata SYSTEM:

A search of the Alldata System produced a number of technical service bulletins pertaining to the vehicle in question. Upon reviewing same, none were found to pertain to the fire in question.

IN RE: Chrysler Insurance Claim No. [REDACTED]
H&A File No. 00-1212VF
QUALITY FORD-MERCURY, d/b/a [REDACTED]

July 5, 2000
Page 5.

OWNER INTERVIEW:

On June 13, 2000 at 4:15 p.m., Investigator Devin Jordan conducted an interview with [REDACTED] d/b/a Quality Ford-Mercury. Quality Ford-Mercury, d/b/a [REDACTED] is also the named insured. At the time of the fire, his wife and son had been passengers in the truck. Further questioning revealed that no one else operates the truck, other than [REDACTED]

The fire was discovered on May 20, 2000 at 8:00 p.m. and the weather conditions were hot with very little wind. The location of the fire was [REDACTED] East Road, Milford, Illinois. Subsequently, his wife contacted 911 and the Milford Fire Department responded in ten minutes and extinguished a fire involving the 1999 Ford, F-150 4X4. The vehicle in question is equipped with a 5.9 liter V-8 engine and came in on trade one week prior to the fire.

At the time of the fire, there was a 3 year/36,000 mile warranty in effect on the vehicle.

When questioned regarding any service work performed on the vehicle, it was learned that an oil, lube, and filter had been performed.

At the time of the fire, the fuel tank was approximately half full and normally his Service Department will check the fluid levels. The last person to have entered the engine compartment would have been the Service Department for an oil change one week prior to the fire.

Since ownership of the truck, they have not had to add any other fluids to the truck and they have not experienced any mechanical or electrical problems with the truck. Mileage at the time of acquiring the vehicle was 14,500 miles; mileage at the time of the fire loss was the same.

Since ownership of the truck, they have not received any recall notices, campaigns, or correspondence from the manufacturer. Further questioning revealed that the insured is a non smoker and no one was smoking in the vehicle prior to the discovery of the fire.

IN RE: Chrysler Insurance Claim No. [REDACTED]
H&A File No. 00-1212VF
QUALITY FORD-MERCURY, d/b/a [REDACTED]

July 5, 2000
Page 6.

When questioned regarding adding any accessories to the vehicle since acquiring same, nothing has been added to the vehicle, all equipment is factory equipment. Further it was learned that there is a factory remote-type alarm system on the truck as well.

Since acquiring the vehicle, it has not been involved in an accident. It was learned at the time of the fire, the vehicle had just been parked. He, his wife, and son had exited the truck and the fire discovered five minutes later.

Accessories being utilized prior to parking the truck included the air conditioning and radio and all accessories functioned.

When questioned regarding any fluid leaks, the insured stated he observed no fluid leaks, did not experience any operability problems, no warning lights were illuminated, he did not detect any odors or hear any noises.

In a short scenario, [REDACTED] stated that he drove the vehicle two hours to Indianapolis with no operability problems. He then drove back two hours, again with no operability problems and parked the vehicle at home. Within five minutes, his wife observed flames coming from the front of the truck. [REDACTED] went to the truck and observed flames and smoke coming out the wheel well on the left or driver's side. His wife called 911 and he began to extinguish the fire with a garden hose until he heard an explosion. At the time of the fire, the hood was closed and remained closed until the fire department arrived. All doors were closed and all windows were up. [REDACTED] indicated that he secured photographs after the fire and the firemen indicated the probable cause was the front brake. In conclusion, Mr. King states he has no idea as to the cause of the fire.

CONCLUSION:

Having completed an examination of the truck, conducted research pertaining to the truck, reviewed an interview with the insured, and based upon all of the information known at the time of the preparation of this report, it is the opinion of both investigators that the fire was accidental in nature. It is further the opinion of both investigators that the fire originated within the engine compartment where oil was leaking from the valve cover, running down onto the exhaust manifold and, upon ignition, the fire extended upward and outward from that location causing the damage present. The origin of the fire is

IN RE: Chrysler Insurance Claim No. [REDACTED]
H&A File No. 00-1212VF
QUALITY FORD-MERCURY, d/b/a [REDACTED]

July 5, 2000
Page 7.

substantiated by the insured's statement, that the fire was observed venting out the wheel well on the left or driver's side, as well as the extensive fire damage present to the fiberglass valve cover.

At this time, all requests for services have been completed, we are closing our file and forwarding our report and photographs for your review.


Walter O. Herndon, Jr.


Devin C. Jordan

WOB/jj

Investigators/Consultants
 345 East Larned, Suite 100
 Detroit, Michigan 48226-4316
 FAX: 313 964-0336

1 800 961-2909
 web@herndon-assoc.com
 dani@herndon-assoc.com

P.O. Box 27
 Boyne City, Michigan 49712
 616 582-5543

Licensed in Michigan,
 Ohio, and Ohio

Fire Dept. MILFORD, ILLINOIS
 Incident No. ON ORDER

Date/Time Of Investigation 6-28-00 @ 3:30 PM
 Vehicle Examined At COMP. HUNNARD, IN
 Location At Time Of Fire MILFORD, ILLINOIS
 Alley Building Driveway/Garage Field Freeway Park Pk Lot Street
 Date Of Fire 5-20-00 Day Saturday Time Of Call 8:00 Arrived Clear
 Description Of Vehicle

Title Holder _____
 Owner _____
 Address _____ MILFORD, ILLINOIS
 Year 1999 Make Ford Model F-150 LARIAT XLT
 Color: (Top) BLUE (Bottom) BLUE
 License Plate: _____
 State _____ Number _____ Expiration Date _____
 Vehicle Identification Number: 1FTRX18L8XK _____
 Lien Holder: NONE LISTED
 Insurance Company: CHRYSLER FAS.

Passenger Compartment (Interior)

1	Dashboards:	Intact	Missing	Partially Consumed	Consumed	
2	Radio:	Intact	Missing			
3	Speakers:	Intact	Missing			
4	Firewall:	Intact	Breached By Fire			
5	Ignition:	Intact <input checked="" type="checkbox"/> Missing <input type="checkbox"/> On Position <input type="checkbox"/> Off Position <input checked="" type="checkbox"/> Locked <input checked="" type="checkbox"/> Thumb Assist Off <input type="checkbox"/>				
	Tampered With/Intact	<input type="checkbox"/>	Tampered With/Defeated	<input type="checkbox"/>	Destroyed By Fire <input type="checkbox"/> In Debris <input type="checkbox"/>	
6	Steering Column:	Intact/Locked <input checked="" type="checkbox"/> Intact/Unlocked <input type="checkbox"/> Tampered With/Intact <input type="checkbox"/>				
	Tampered With/Defeated	<input type="checkbox"/>	Missing	<input type="checkbox"/>	Destroyed By Fire <input type="checkbox"/>	
7	Front Seat:	Intact	Missing	Partially Consumed	Consumed	
8	Rear Seat:	Intact	Missing	Partially Consumed	Consumed	N/A
9	Glove Box:	Intact <input checked="" type="checkbox"/> Missing <input type="checkbox"/> Partially Consumed <input type="checkbox"/> Consumed <input type="checkbox"/> Removed <input type="checkbox"/>				
	Items In Glove Box:	Owner's Manual <input type="checkbox"/>	Miscellaneous Papers <input type="checkbox"/>			
10	Air Bag:	Intact <input type="checkbox"/> Missing <input checked="" type="checkbox"/> Deployed <input type="checkbox"/> Fire Damaged <input checked="" type="checkbox"/> N/A <input type="checkbox"/>				
	Driver's Side	Intact <input type="checkbox"/> Missing <input checked="" type="checkbox"/> Deployed <input type="checkbox"/> Fire Damaged <input type="checkbox"/> N/A <input type="checkbox"/>				
	Pass. Side	Intact <input type="checkbox"/> Missing <input checked="" type="checkbox"/> Deployed <input type="checkbox"/> Fire Damaged <input type="checkbox"/> N/A <input type="checkbox"/>				
11	Ignition Key:	None Found <input checked="" type="checkbox"/> In Ignition <input type="checkbox"/> At Scene <input type="checkbox"/> In Debris <input type="checkbox"/>				
12	Odometer Reading:	Actual <input type="checkbox"/> Digital <input type="checkbox"/> Oil Change <input type="checkbox"/> Removed <input type="checkbox"/> Destroyed By Fire <input checked="" type="checkbox"/>				
13	Title Information: (Date Of Transfer To Current Owner/Mileage)					

14 Personal Effects In Passenger Compartment

Engine Compartment

15	Engine Accessibility:	Limited (Hood Jammed) <input type="checkbox"/>	Open <input checked="" type="checkbox"/>	Forced Open By Investigator <input type="checkbox"/>
16	Engine:	Intact <input type="checkbox"/>	Missing <input type="checkbox"/>	Partially Stripped <input type="checkbox"/>
17	Battery:	Intact <input type="checkbox"/>	Missing <input type="checkbox"/>	Fire Damaged <input checked="" type="checkbox"/>
18	Radiator:	Intact <input type="checkbox"/>	Missing <input type="checkbox"/>	Fire Damaged <input checked="" type="checkbox"/>
19 Fluid Levels:		NOTE: D.B.F. = DRAINED BY FIRE		
	Oil	Transmission	Radiator	Brake
	Full	Full		
	D.B.F.	D.B.F.	D.B.F. <input checked="" type="checkbox"/>	D.B.F. <input checked="" type="checkbox"/>
20	Belts:	Intact <input type="checkbox"/>	Partially Consumed <input checked="" type="checkbox"/>	Consumed <input type="checkbox"/>
21	Upper Hose:	Intact <input type="checkbox"/>	Partially Consumed <input checked="" type="checkbox"/>	Consumed <input type="checkbox"/>
22	Lower Hose:	Intact <input type="checkbox"/>	Partially Consumed <input checked="" type="checkbox"/>	Consumed <input type="checkbox"/>
23	Engine Parts Missing:	○		
24	Anti-Theft System:	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	Unknown <input type="checkbox"/>
25	Additional Information:	SECURI-LOCK		

Exterior Examination

26 Tires:				
27	Type	Custom Wheels/ Wheelcovers	Treadwear	No. Of Lugs
28	AWANSON TIRES	A	75%	ALL
29				
30				

Door Cylinders (Locks)

31	Left Door:	Intact <input checked="" type="checkbox"/>	Fire Damaged <input type="checkbox"/>	Forced Entry <input type="checkbox"/>
32	L. Sliding:	Intact <input type="checkbox"/>	Fire Damaged <input type="checkbox"/>	Forced Entry <input type="checkbox"/>
33	Rear Cargo:	Intact <input type="checkbox"/>	Fire Damaged <input type="checkbox"/>	Forced Entry <input type="checkbox"/>
34	R. Sliding:	Intact <input type="checkbox"/>	Fire Damaged <input type="checkbox"/>	Forced Entry <input type="checkbox"/>
35	Right Door:	Intact <input checked="" type="checkbox"/>	Fire Damaged <input type="checkbox"/>	Forced Entry <input type="checkbox"/>

Trunk Compartment Examination

36	Pickup <input checked="" type="checkbox"/>	Van <input type="checkbox"/>	Utility Vehicle <input type="checkbox"/>				
37	Trunk Lock:	Intact <input type="checkbox"/>	No <input type="checkbox"/>	Fire Damaged <input type="checkbox"/>	Locked <input type="checkbox"/>	Open <input type="checkbox"/>	Forced <input type="checkbox"/>
38	If Forced, By Whom?						
39	Trunk Release:	Yes <input type="checkbox"/>	No <input type="checkbox"/>	Unknown <input type="checkbox"/>	Entry To Trunk: Yes <input type="checkbox"/>	No <input type="checkbox"/>	

VEHICLE FIRE INVESTIGATION 3

Trunk Contents

36	Spare Tire:	Intact <input checked="" type="checkbox"/>	Missing <input checked="" type="checkbox"/>	On Vehicle <input type="checkbox"/>	Fire Damaged <input type="checkbox"/>
37	Tire Change Equipment:	Intact <input checked="" type="checkbox"/>	Missing <input type="checkbox"/>	At Scene <input type="checkbox"/>	Engine Compartment <input type="checkbox"/>
38	Other Contents/Personal Effects In Trunk Compartment/Cargo Area:				

Glass Condition

39	Windshield:	Intact <input type="checkbox"/>	Missing <input type="checkbox"/>	Melted/Cracked By Heat <input checked="" type="checkbox"/>	Broken <input type="checkbox"/>	In <input checked="" type="checkbox"/>	Out <input type="checkbox"/>
	Electric Windows:	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>				
41	Driver's Window:	Intact <input type="checkbox"/>	Missing <input type="checkbox"/>	Melted/Cracked By Heat <input type="checkbox"/>	Broken <input checked="" type="checkbox"/>	In <input checked="" type="checkbox"/>	Out <input type="checkbox"/>
	Position	Up <input checked="" type="checkbox"/>	Down <input type="checkbox"/>				
42	Left Rear Window:	Intact <input checked="" type="checkbox"/>	Missing <input type="checkbox"/>	Melted/Cracked By Heat <input type="checkbox"/>	Broken <input type="checkbox"/>	In <input type="checkbox"/>	Out <input type="checkbox"/>
	Position	Up <input type="checkbox"/>	Down <input type="checkbox"/>	Stationary <input checked="" type="checkbox"/>			
43	Left Rear 3rd. Window:	Intact <input type="checkbox"/>	Missing <input type="checkbox"/>	Melted/Cracked By Heat <input type="checkbox"/>	Broken <input type="checkbox"/>	In <input type="checkbox"/>	Out <input type="checkbox"/>
	Position	Stationary <input type="checkbox"/>					
44	Rear Window:	Intact <input checked="" type="checkbox"/>	Missing <input type="checkbox"/>	Melted/Cracked By Heat <input type="checkbox"/>	Broken <input type="checkbox"/>	In <input type="checkbox"/>	Out <input type="checkbox"/>
45	Right Rear 3rd. Window:	Intact <input type="checkbox"/>	Missing <input type="checkbox"/>	Melted/Cracked By Heat <input type="checkbox"/>	Broken <input type="checkbox"/>	In <input type="checkbox"/>	Out <input type="checkbox"/>
	Position	Stationary <input type="checkbox"/>					
46	Right Rear Window:	Intact <input checked="" type="checkbox"/>	Missing <input type="checkbox"/>	Melted/Cracked By Heat <input type="checkbox"/>	Broken <input type="checkbox"/>	In <input type="checkbox"/>	Out <input type="checkbox"/>
	Position	Up <input type="checkbox"/>	Down <input type="checkbox"/>	Stationary <input checked="" type="checkbox"/>			
47	Passenger Window:	Intact <input checked="" type="checkbox"/>	Missing <input type="checkbox"/>	Melted/Cracked By Heat <input type="checkbox"/>	Broken <input type="checkbox"/>	In <input type="checkbox"/>	Out <input type="checkbox"/>
	Position	Up <input checked="" type="checkbox"/>	Down <input type="checkbox"/>				
48	Sun Roof:	Open <input type="checkbox"/>	Missing <input type="checkbox"/>	Closed <input type="checkbox"/>	Fire Damaged <input type="checkbox"/>		
49	Convertible:	Up <input type="checkbox"/>	Missing <input type="checkbox"/>	Down <input type="checkbox"/>	Fire Damaged <input type="checkbox"/>		
50	T-Top:	On <input type="checkbox"/>	Missing <input type="checkbox"/>			Fire Damaged <input type="checkbox"/>	

Under Vehicle

51	Fuel Tank:	Intact <input checked="" type="checkbox"/>	Missing <input checked="" type="checkbox"/>	Fire Damaged <input type="checkbox"/>		
52	Gas Cap:	Intact <input checked="" type="checkbox"/>	Missing <input type="checkbox"/>	Fire Damaged <input type="checkbox"/>		
53	Fill Pipe:	Intact <input checked="" type="checkbox"/>	Missing <input type="checkbox"/>	Fire Damaged <input type="checkbox"/>		
54	Transmission:	Intact <input checked="" type="checkbox"/>	Missing <input type="checkbox"/>	Leakage Noticed	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
55	Oil Pan:	Intact <input checked="" type="checkbox"/>	Missing <input type="checkbox"/>	Leakage Noticed	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>

Rust And Damage


Areas	Open	Closed	Missing	Rust	Damaged	Vandalized
56 Front Bumper:						
57 Hood:						
58 Grille:						
59 Left Fender:						
60 Driver's Door:		X				
61 Left Rear Door:		X				
62 Left Quarter Panel:						
63 Trunk Lid:						
64 Rear Bumper:						
65 Roof:						
66 Right Quarter Panel:						
67 Right Rear Door:		X				
68 Passenger Door:		X				
69 Right Fender:						

Utility Or Van

70	Rear Cargo Doors:							
71	Side Cargo Doors:							
72	Body Condition:		Excellent	Good	X	Fair	Poor	

73	Number Of Photographs Taken: _____	
74	Evidence Confiscated: _____	

Investigated By: W. O. H. [Signature]




1. A close-up view of vehicle identification number 1FTRX16L8XK [REDACTED] identifying the 1999 Ford F-150 Pick-up Truck.
-
2. A view of the front of the vehicle.






3. A view of the left front.

4. A view of the gas cap intact.



EX-102-085-LC-3885




5. A view of the left rear.

6. A view of the rear.




8908-087-1-0-3885



7. A view of the bed of the truck.

8. A view of the right rear.



EA05-005-10-3007



9. A view of the passenger side from the right front.

.....
10. A view of the front passenger compartment from the drivers side.



EA08-000-LC-3868



11. A view of the rear passenger compartment from the drivers side.

.....
12. A view of the rear passenger compartment from the passenger side.



EMPS-802-LC-3059




13. A view of the front passenger compartment from the passenger side.

.....
14. A view of the engine compartment from the front depicting fire damage to the air conditioning condenser and radiator with the damage more pronounced on the left or drivers side.



ENG-000-1C-3570



15. A view of the engine from the front.

.....
16. A view of the engine from the drivers side.



ENG-005-LC-3671



17. A view of the engine from the passenger side.

.....
18. A view of the remains of the battery.



EMD-081-LC-3872



19. A view of fire damage to the alternator.

.....
20. A view of a power steering line with combustible
hose remaining.



EMRS-003-LC-3873



21. A view of the lower radiator hose.

.....
22. A view of the transmission cooler lines with the
combustible section of the line consumed by the
fire.



DP-8-815-LC-3874



23. A view of the metal fuel line connections
closest the bulkhead.

.....
24. A view of the valve cover on the right or
passenger side.



ENC-885-LC-2875



25. A view of the valve cover on the left or drivers side.

.....



26. A view of burned sections of the valve cover
jacket protruding out of the valve cover directly
the engine compartment.



27. Another view of the valve cover gasket protruding from the left or drivers side valve cover.

.....
28. Another view of the valve cover gasket protruding from the left or drivers side valve cover.






29. A view of the left or drivers side of the engine with the valve cover removed.

.....
30. A view of the left or drivers side of the engine with the valve cover removed depicting the area closest the bulkhead.





31. A view of the head of the engine on the left of drivers side where the valve cover gasket was protruding.
-
32. A view of the remains of the combustible valve cover and valve cover gasket with a section closest the exhaust manifold consumed.





33. A close-up view of a section of the valve cover gasket consumed.

.....
34. A view of a section of the valve cover gasket which has been flattened and no longer maintains its shape.





35. A view of the remains of the valve cover and valve cover gasket placed in a evidence bag and left within the passenger compartment on the vehicle by Investigators.

[The page contains extremely faint and illegible text, likely bleed-through from the reverse side of the document. The text is too light to be transcribed accurately.]

STATE OF MICHIGAN

IN THE CIRCUIT COURT FOR THE COUNTY OF BERRIEN

**STATE FARM MUTUAL AUTOMOBILE
INSURANCE COMPANY,**
as Subrogee of [REDACTED]

Plaintiffs,

vs.

Case No. *04-3026-NP-T*

**FORD MOTOR COMPANY, AND
THREE OAKS FORD,**

Defendants,

DUPLICATE ORIGINAL!

EDWARD L. JOHNSON P54646
Attorneys for Plaintiffs
1249 Washington Boulevard
Suite 2900
Detroit, Michigan 48226
(313) 965-6277

COMPLAINT AND JURY DEMAND

NOW COME Plaintiffs State Farm Mutual Automobile Insurance Company, as Subrogee of [REDACTED] by and through its attorney, Edward L. Johnson, and for its Complaint against the Defendants Ford Motor Company and Three Oaks Ford, states as follows:

COUNT I

1. Plaintiffs is a foreign corporation conducting business in the City of Three Oaks, County of Berrien, State of Michigan.
2. Defendant Ford Motor Company, is a foreign corporation, conducting business in

the City of Three Oaks, County of Berrien, State of Michigan.

3. Defendant Three Oaks Ford, is a Michigan business conducting business in the City of Three Oaks, County of Berrien, State of Michigan.

4. The Defendants manufactured, sold and/or supplied a 1999 F-150 VIN 1FTRX17W9X1 [REDACTED] t [REDACTED]

5. On March 24, 2003, Plaintiff's insured 1999 F-150 was parked at parked at 7700 Martin, in the City of Three Oaks, when the subject vehicle was damaged.

6. Defendants having sold, manufacture, and/or supplier of 1999 F-150, knew or should have known that property damages concerning the 1999 F-150 could occurred during operation. Notwithstanding said knowledge, Defendant failed to act as a reasonable seller, manufacturer, and/or supplier of the 1999 F-150, and failed to take adequate precautions to guard against such foreseeable and unreasonable risks of damage.

7. The Defendants were negligent and such negligence was a proximate cause of Plaintiff's damages, and consisted of, but were not limited to the following:

- A. Failure to properly and adequately manufacture, and sell the 1999 F-150 so as to protect against foreseeable and unreasonable risks of damage, such as occurred to Plaintiff's insured's vehicle.
- B. Failure to properly and adequately inspect and test its product to insure against foreseeable an unreasonable risks of damage by its users, specifically Plaintiff's insured [REDACTED]
- C. In manufacturing, supplying and selling a 1999 F-150 with a faulty junction box.
- D. Failure to warn of the hazards of the junction box,

contrary to ANSI Standard B71.3-1975.

- E. Failure to provide adequate warning in a manner sufficient to advise the operator of the dangers associated with the junction box connection, contrary to ANSI Standard B71.3-1975.
- F. In manufacturing, supplying and selling a 1999 F-150 with a junction box could fail, and in failing to warn of this condition.

8. As a direct and proximate result of the negligence of the Defendant as aforesaid, Plaintiff in the amount of \$33,922.51 Dollars.

WHEREFORE, Plaintiffs demand Judgment against Defendants Ford Motor Company and Three Oaks Ford, in an amount of \$33,922.51 Dollars, plus costs, interest and attorney fees.

COUNT II

9. Plaintiffs reallege and incorporate by reference each and every allegation as contained in Count I as if set forth fully herein, and for Count II state as follows.

10. At the time the Defendants Ford Motor Company and Three Oaks Ford, manufactured, supplied and sold its 1999 F-150 as previously described, it warranted expressly and impliedly that said F-150 was safe and fit for the purposes and uses reasonably foreseeable and intended when it left Defendant's control, but contrary to said warranties, said F-150 was not reasonably fit for the purposes and uses reasonably foreseeable, but was defective in the following, but not limited to the following particulars:

- A. The Defendant failed to properly and adequately manufacture and sell the subject F-150 so as to protect against foreseeable and unreasonable risks of damage, such as occurred to Plaintiff insured vehicle.
- B. The Defendants failed to properly and adequately inspect and test

its

product to insure against foreseeable and unreasonable risks of damage Plaintiff's insured [REDACTED] 1999 F-150.

- C. Defendants knew and recognized that the junction box could fail.
- D. In manufacturing, supplying and selling a vehicle with a junction box which could fail.
- E. The Defendants failed to warn of the hazards of the junction box, contrary to ANSI Standard B71.3-1975.
- F. The Defendants failed to provide adequate warning in a manner sufficient to advise the operator of the dangers associated with the junction box, contrary to ANSI Standard B71.3-1975.

11. As a direct and proximate result of the above described breaches of implied and express warranties by the Defendants, said 1999 F-150 was defective and caused Plaintiff to suffer damages in the amount of \$33,922.51 Dollars.

COUNT III

12. Plaintiffs reallege and incorporate by reference each and every allegation as contained in Count I, Count II as if set forth fully herein, and for Count III state as follows.

13. That prior to March 24, 2003, Plaintiff's insured purchased the subject vehicle from the Defendants.

14. The paperwork which was presented to Plaintiff's insured did not match the deal which was worked out with the salesperson.

15. Under the Michigan Consumer Protection Act, the Defendants were in the process

of conducting trade or commerce as that term is defined in MCLA 445.902(d).

16. The Defendants violated the Consumer Protection Act by acting in an unfair, unconscionable and deceptive manner including, without limitation:

- a. Representing that vehicle had characteristics, uses, and benefits it the not have in violation of the prohibition in MCLA 445.903(l)(c);
- b. There were gross discrepancies between the oral presentations of the seller and the written agreement covering the same transaction despite the prohibition in MCL 445.903(l)(y);
- c. Violating other provisions in the Michigan Consumer Protection Act including, without limitation, MCL 445.903(l)(d),(e),(n), (p),(x), and/or (bb).

17. The Defendants also made certain representations as to the quality of the vehicle and the lack of need for repair.

18. Those representations were false and were made in violation of the Consumer Protection Act.

19. As a direct and proximate result of the Defendants' actions, Plaintiff and its insured has suffered and will continue to suffer damages in the amount of \$33,922.51 including, without limitation:

- a. Loss of use of the subject vehicle;
- b. Incidental damages;
- c. Loss of enjoyment of vehicle;
- d. Attorney's fees;

WHEREFORE, Plaintiffs demand Judgment against Defendant Ford Motor Company and Three Oaks For, in the amount of \$33,922.51 Dollars, plus costs, interest and attorney fees.

COUNT IV

20. Plaintiffs reallege and incorporate by reference each and every allegation as contained in Count I, Count II, Count III as if set forth fully herein, and for Count IV state as follows.

21. That the subject vehicle was purchased by Plaintiff's insured on or about March 21, 2003, from Three Oaks Ford.

22. That only three days after the subject vehicle was purchased it burst into flames while parked in Plaintiff's insured driveway.

23. That the Defendants pursuant to MCLA 440.2314 and MCLA 440.2315 had a duty to manufacture, supply and sell a vehicle of merchantable quality and fit for its particular purpose.

24. That the Defendants breached their duty to manufacture, supply, and sell a vehicle of merchantable quality and fit for its particular purpose

25. As a direct and proximate result of the Defendants' breaches, Plaintiff and its insured has suffered and will continue to suffer damages in the amount of \$33,922.51.

WHEREFORE, Plaintiffs demand Judgment against Defendant Ford Motor Company and Three Oaks For, in the amount of \$33,922.51 Dollars, plus costs, interest and attorney fees.

Respectfully submitted,

BY: 

Edward L. Johnson (P54646)
Attorney for Plaintiff
1249 Washington Boulevard
Suite 2900
Detroit, MI 48226
(313) 965-6277

State Farm Insurance Companies



April 18, 2003

Ford Motor Company
Parklane Tower West suite 400
Dearborn, MI 48126-2568

State Farm Insurance Company
Subrogation
PO Box 4078
Kalamazoo, MI 49003-4078
Toll free: 877-782-6424
Fax: 888-845-8680



RE: Claim Number: [REDACTED]
Our Insured: March 24, 2003
Date of Loss: [REDACTED]
Make, Model and Year of Vehicle: 1999 Ford F150
Serial or Vehicle Identification Number: 1FTRX17W9XN [REDACTED]

The identified vehicle is insured by State Farm Insurance. This vehicle experienced a engine fire.

State Farm would like to give you an opportunity to inspect the vehicle and/or part and give you advance notice of our potential claim.

In order to assist you in evaluating and processing the subrogation claim we are asserting, we may provide nonpublic personal information about our customer. We are sharing this information to effect, administer, or enforce a transaction authorized by the consumer. However, you are neither authorized nor permitted to: (1) use the customer information we provide for any purpose other than to evaluate and process the subrogation claim, or (2) disclose or share the customer information we provide for any purpose other than to evaluate and process the subrogation claim.

Please contact me at (877) 782-6424 to set up a time for your inspection.

Sincerely,

Alan Brubaker x8517
Claim Representative
(877) 782-6424


State Farm Mutual Automobile Insurance Company

199 F150
VIN
-3/24/03




ERG-003-LC-3891

3/28/03



3/28/83



ENC-805-LC-3883




EROS-005-LC-3654

3/28/03




3/28/03





ER05-005-LC-3687



ER05-005-LC-3008


3/28/93



ER05-000-LC-3009



3/28/03




ENC-885-LC-3781

3/28/03

ER05-085-LC-3782

3/28/93



ERCS-005-LC-3783



ER05-005-LC-3704

April 1, 2003

APR 09 2003

IN RE: State Farm Claim No. 22V936906
H&A File No. 03-0621VF
RICHARD AND CONNIE RUBECK

PREDICATION:

This report is predicated upon the request of Mr. Todd Soos, State Farm Claims Representative, to conduct an investigation into Richard and Connie Rubeck, with special reference to the fire loss of a 1999 Ford, F-150, 4 x 2.

SECRETARY OF STATE:

Through the Secretary of State, the following information was obtained:

1999 FORD 1FTRX17W9XN [REDACTED] 25 PICKUP FOREIGN
03/21/2003 210P079D107 LGT CONVTL 'F' 54993 A

[REDACTED]
THREE OAKS
[REDACTED]
NO SECURED INTEREST ON RECORD

REGISTRATION INFORMATION:

E6709U CO-TRANSFER **BRIDGE**
12/10/2003 R-120-738-285-939
MI SOS

INSPECTION:

On March 27, 2003 at 12:45 p.m., this Investigator arrived at [REDACTED] Oaks, Michigan, to conduct an investigation into the fire loss of a 1999 Ford, F-150, 4 x 2.

Once at the scene, a close inspection provided the following information:

SEE ENCLOSED INVESTIGATION REPORT

Prior to leaving the scene, several 35mm color photographs were taken and are enclosed.

ER85-005-LC-3788

BERNDON
ASSOCIATES

Investigators / Consultants

36135 Schoolcraft
Livonia, Michigan 48150
Fax: 734-991-0140

1 800 961-2909
wtk@berndon-assoc.com
den@berndon-assoc.com

P.O. Box 27
Boysie City, Michigan 49712
231 582-5543

Licensed in Michigan,
Ohio, Illinois, Indiana and Arizona

www.berndon-assoc.com

IN RE: State Farm Claim No. [REDACTED]
U.S.A. File No. 03-0651108
[REDACTED]

April 1, 2003
Page 2

ORIGIN AND CAUSE INVESTIGATION:

On March 27, 2003 at 12:45 p.m., this Investigator arrived at [REDACTED] in Three Oaks, Michigan, to conduct an origin and cause investigation into the fire loss of a 1999 Ford, F-150, burgundy in color, Vehicle Identification Number 1FTRX17W9XQ [REDACTED]. Upon arriving at the facility, the vehicle is parked facing a northerly direction. The examination further reveals that the vehicle identification number in the area of the windshield and dash has been destroyed and is not legible. At this time, the license plate has been removed from the rear, however, a label indicates the selling dealer as Three Oaks Ford, Three Oaks, Michigan.

Initial observations reveals evidence of a fire to have originated within the engine compartment, with the most severe damage present on the right or passenger's side. The fire has further extended, breaching the bulkhead and windshield, entering the cab area, extending, radiating through into the bed of the truck, where it was there confined.

At this time, the investigation is focused to the bed of the truck, where the rear window has fallen inward into the bed of the truck, and located are two bags of fertilizer for vegetables gardens, a hammer, and tree trimmers. The examination of the bed of the truck reveals all of the fire damage is an extension, and no evidence of any fire origin could be found.

The investigation is now focused to the fuel tank, fill tube and fuel cap, as well as the underside of the truck, where no evidence of any fire origin could be found. The examination further reveals no evidence of any fuel leakage.

At this time, the investigation is focused to the rear passenger compartment, where the floor areas are present, rubber tie down straps are present on the left rear floor area, combustibles remain, and no evidence of any fire origin could be found.

The investigation is now focused to the front passenger compartment, where window glass has melted on the right rear seat, and window glass has melted between the driver's seat and driver's door. The examination further reveals almost all of the cushion and seat material to have been consumed on the front seats.

The examination of the front floor areas reveals the floor areas are present, combustibles are present in the area of the odometer/speedometer cluster, wiring with charred insulation is still present in the dashboard. The examination further reveals high burning to the heater core, and the remains of business cards and miscellaneous papers, charred, are found throughout the cab area. At this time, no evidence of any fire origin within the cab area could be found.

IN RE: State Farm Claim No. [REDACTED]
H&A File No. 03-0621VP
RICHARD AND [REDACTED]

April 1, 2003
Page 3

The investigation is now focused to the front clip of the vehicle, where the left front custom wheel is basically intact, and rubber tire remains around the wheel. The examination further reveals some evidence of the left front headlight assembly and aluminum trim. The examination of the right front reveals the custom wheel has been almost totally destroyed during the course of the fire, and only tire pad remains under the wheel. The examination further reveals that the battery has melted, falling onto the ground, where the plates are visible.

The investigation is now focused to the front of the engine, where the radiator and air conditioning condenser has been almost totally consumed during the course of the fire. The examination further reveals wiring laying on the radiator support with evidence of melting.

The examination is now focused to the left or driver's side, where some combustibles remain in the area of the power distribution center, and some paper air filter element remains. The examination is now focused to the fuel lines in the left rear of the engine compartment, and the fuel lines have been consumed during the course of the fire and are no longer connected. The examination further reveals melting from the top down to the cast aluminum plenum, and there is evidence of melting of the casing for the alternator located in the center front of the engine. The examination further reveals melting to the cast aluminum in the left and right front, with the damage much more pronounced on the right or passenger's side.

The investigation is now focused to the fiberglass valve covers, where the damage is much more pronounced on the right or passenger's side versus that of the left or driver's side. The examination further reveals all hoses to have been consumed during the course of the fire. The examination is now focused to the fluid levels, where the brake fluid, power steering fluid and radiator have all drained during the course of the fire. The examination of the transmission fluid reveals it is full and clean, and the oil is overfull, clean and contaminated with water due to fire extinguishment.

The examination is now focused to the main lead that travels to the alternator, it is completely void of insulation, and as you trace the wiring over to the right rear of the engine, there is evidence of electrical faulting. The examination further reveals approximately three additional inches of the wiring with electrical faulting, and there is melting and electrical faulting to the connector found on top of the valve cover on the right or passenger's side. The examination further reveals the main lead that travels from the power distribution center and connects over into the junction at the bulkhead on the passenger's side, shows evidence of electrical faulting as well.

IN RE: State Farm Claim No. [REDACTED]
H&A File No. 03-0621VF
[REDACTED]

April 1, 2003
Page 4

The investigation is now focused to the bracket directly beneath the starter solenoid, and there is splattering and evidence of copper wiring fused to the bracket.

The investigation is now focused to the battery cables, where they are void of insulation, there is evidence of electrical faulting, and the cables are fused to one another.

At this time, after completing an examination of the vehicle, it was the opinion of this Investigator that the fire originated in the right rear or passenger's side of the engine compartment, and at this time, the investigation continues.

It should be noted that the three inches of cable which was no longer connected, showing evidence of electrical faulting, as well as the copper connectors, were placed into a nylon bag and tied to the passenger's seat for safekeeping.

TITLE INFORMATION:

A review of the title information indicates that the vehicle was titled out of state and transferred into the name of [REDACTED] Three Oaks, Michigan, on March 21, 2003. At the time of the transfer, the odometer showed 59,993 actual miles. There is no secured interest listed on record, and the license plate of [REDACTED] was not due to expire until December 10, 2003. The driver's license number listed on the registration was [REDACTED].

NICB VINASSIST:

A review of the NICB Vinassist indicates that the 1999 Ford, F-150, 4 x 2 is equipped with a 4.6 liter engine, and was assembled in Norfolk, Virginia.

NATIONAL HIGHWAY TRAFFIC & SAFETY ADMINISTRATION:

A search of the National Highway Traffic & Safety Administration, Recall Database, produced five records pertaining to 1999 Ford, F-150 trucks. A review of the recalls revealed none pertain to the fire in question.

IN RE: State Farm Claim No. [REDACTED]
H&A File No. 03-0621VF
[REDACTED]

April 1, 2003
Page 5

A further search was conducted of the National Highway Traffic & Safety Administration, Defect Investigations Database, which produced one record pertaining to 1999 Ford, F-150s. A review of the record revealed it has nothing whatsoever to do with the fire in question.

ALL DATA SYSTEM:

A search of the All Data System produced four recalls and three campaigns pertaining to 1999 Ford, F-150s equipped with 4.6 liter engines. A review of these records revealed none pertain to the fire in question.

A further search was conducted of the technical service bulletins, and none were found to pertain to the fire in question.

THREE OAKS FIRE DEPARTMENT:

Correspondence has been forward to the Three Oaks Volunteer Fire Department, requesting a copy of their fire incident report. Upon receipt of the report, it will be forwarded to the Claims Representative.

INTERVIEW (Richard Rubeck):

On March 25, 2003 at 10:00 a.m., Investigator Robert Persyn conducted an interview with [REDACTED] who is the titleholder, named insured and primary driver of the truck in question. Further questioning revealed that no one else operates the truck other than himself.

When questioned regarding any recent complaints or problems with the truck, he indicated he detected a burning odor prior to parking the truck.

The fire was discovered on March 24, 2003 at 11:00 p.m., and the weather conditions were windy. The wind was traveling from the front of the truck to the rear of the truck. The location of the fire was in the driveway at 7700 Martin, Three Oaks, Michigan. Subsequently, the insured contacted 911, and the Three Oaks Volunteer Fire Department responded somewhere between 20 and 30 minutes, and extinguished a fire involving the 1999 Ford, F-150 equipped with a V8 engine. The vehicle in question was purchased used in March of 2003 from Three Oaks Ford.

IN RE: State Farm Claim No. [REDACTED]
H&A File No. 03-0621VF
[REDACTED]

April 1, 2003

Page 6

At the time of the purchase, there was no warranty in effect, and no extended warranty was obtained.

When questioned regarding any service work performed on the vehicle, other than routine maintenance, no other service has been performed.

At the time of the fire, it was learned that the fuel tank was approximately half full, and the insured indicates that he normally checks the fluid levels. The last person to have entered the engine compartment was a friend identified as Larry Metzger, who performed an oil change the day before the fire. Further questioning revealed that the insured has not had to add any fluids to the vehicle since the purchase.

When questioned regarding any mechanical or electrical problems with the vehicle, the insured indicated he has had none.

Mileage at the time of the purchase was approximately 59,000 miles, mileage at the time of the loss was approximately 59,000 miles.

When questioned regarding receiving any recall notices, campaigns or correspondence from the manufacturer, the insured indicated he has received none.

The insured went on to state that he is a nonsmoker, and no one was smoking in or around the vehicle.

When questioned regarding adding any accessories to the vehicle since the purchase, he indicated he has added none. The insured went on to state that to his knowledge, there is no non-factory wiring on the vehicle, and that the vehicle is equipped with a factory keyless entry.

Since ownership of the vehicle, it has not been involved in an accident, and it was learned that the vehicle had been driven ten minutes prior to it being parked at 10:15 p.m., with the fire discovered at approximately 11:00 p.m. Accessories being operated prior to parking the truck included the lights, heater, radio and wipers, and all accessories functioned.

The insured went on to state that the truck is wired by the factory for trailer wiring.

Just prior to parking the truck, the insured did not observe any fluid leaks, experience any operability problems, there no warning lights illuminated, and no changes in the gauges. The insured did indicate that he detected a burning smell prior to parking the truck. The smoke was

IN RE: State Farm Claim No. [REDACTED]
H&A File No. 03-0621VF
[REDACTED]

April 1, 2003

Page 7

first observed rising up from the engine compartment, was gray then black. The fire was first observed in the engine compartment, and the flames were orange. The hood was closed, all doors were closed and locked, and all windows were up at the time of the discovery of the fire.

In a short scenario, the insured stated he heard the dog barking, he looked out and observed the entire engine compartment engulfed in flames. He contacted the fire department, however, it was so windy out, the flames blew back, igniting the passenger compartment. No one photographed the vehicle at the fire scene, and the firemen did not indicate any probable regarding the fire. The insured states he has no idea as to the cause of the fire.

As a result of the fire, vinyl siding on the front of the garage was damaged, shrubbery was damaged and a wood fence.

As of this date, no other fire investigators, public or private, have contacted the insured, and no items were removed from the vehicle at the fire scene.

When questioned regarding any contents in the vehicle, the insured indicated he had eight CDs and four cassette tapes. In conclusion, the insured states that he had taken the vehicle to Three Oaks to wash it, he parked the vehicle at 10:15 p.m., with the fire discovered at 11:00 p.m.

CONCLUSION:

Having completed an examination of the vehicle, reviewed an interview obtained from the insured who was the last operator of the truck and witness to the fire, conducted research pertaining to the vehicle in question, and based upon all of the information known at the time of the preparation of this report, it is the opinion of this Investigator that the fire was accidental in nature. It is further the opinion of this Investigator that the fire originated in the right rear of the engine, where they alternator cable, power distribution cable and battery cables connect into a junction, where there is evidence of electrical faulting, sufficient to ignite the wiring insulation and immediate combustibles into open flame, with the fire extending, causing the damage present. The fire is deemed to be an accidental fire, electrical in nature.

It should be noted that a section of wiring, as well as the connectors were placed into a nylon bag and were tied to the right front passenger seat.

IN RE:

State Farm Claim No. [REDACTED]
H&A File No. 03-0621VF
[REDACTED]

April 1, 2003

Page 8

At this time, all requests for services have been completed, we are closing our file and forwarding our report and photographs for your review.



Walter O. Herndon, Jr.

WOH/kp

EGS-885-LC-3712