

MITSUBISHI
4/6/2005
LETTER TO ODI
ATTACHMENT
DOCUMENT NO. 13 - 25
PART 3 OF 4

Document No.13

Meeting Minutes : Document Number J801-B091

Approved by Interior Design Dept. Mr. Nakajima

Created on 01.5.31 by Electrical System Design Mr. Tozuka

<MMNA Headlamp Connector Melting Damage Meeting 01.5.31 >

Attendees

Refer to attached list

Place

Okazaki Meeting Room S42

1. Report of Investigation Results for Actual Parts Recovered... Attachment ①, ② Reference
 • 2 parts recovered locally (connector side only) . . . COM terminals with melting damage
 (for reference, bench tested part at Ele testing (salt water droplet test) analyzed too)

- significant contact resistance : 146.6 (Lo) / 206.8 (Hi) mΩ } cause at terminal
- resistance at clamp portion : 0.78~1.17 mΩ nominal value }
- Almost none detected for Cl. (significant detection for Cu, Ca, Sn) ⇒ believe salt water and/or salt are not causes
- No irregularities of crimp height as within standard and cross-section shape
- Observed wire bias, but what is the reason? (Ele testing) ⇒ applies to terminals 0.5~2sq. CAVS was made of 7 core wires, Judging as normal from wire compression ratio, contact resistance, fixed strength (Yazaki Corp.)
- Clamped by 0.5~2.0 bonding tool ⇒ Cramp configuration in case of using 0.5 bonding tool ⇒ Yazaki Corp.

2. Cause Clarification Discussions

- 1) Creep characteristic measurement status of Current harness side terminal . . .
 Attachment ③ (Yazaki Corp.)

(1) thermal stress relaxation characteristics of 312 terminal (AMP name: Q terminal)

- Figure at right shows current status
- Plan to conduct up to 500 hours. Report for 300 hour point. (Yazaki Corp. ⇒ MMC)

- 2) Report on Wiggling Reproduction Test when Connecting Actual Vehicle Connector for ST28(24)/ST41 . . . Attachment ④, ⑤

- Simulation of MMNA production line assembly environment for actual vehicles
- Inserting once and the pushed side of the terminal demonstrates a tendency to widen (opens up to 0.7mm)
 (countermeasure parts (NQ) inserted at an angle have no problems)
- the 2nd insertion, there is a tendency for further overall widening greater than the 1st insertion

- when the female terminal is at its widest, observation of the male bulb terminal bending is about 0.1mm

3) FTA Results (Ele testing) . . . Attachment ⑤

the related part of the vehicle is the part surrounding □

- No salt to oxidize. Water has relationship to corrosion (but contribution to this problem is small)
- Head LP temperature increase . . report lately
- Metallic plate cracking . . cannot analyze
- Wiggling . . conduct reproduction test 2 above

<FTA Considerations >

The following are the factors that have been narrowed down as of today

- ① 5 items for terminal deformation
- ② 8 items for thermal stress relaxation due to irregular temperature increases
(③ water is significantly impacts corrosion, but does not significantly impact melting damage)

3. Report on Results of Bench Temperature Measurements at Lamp Assembly for 6 Models Attachment ⑦ (Yazaki Corp.)

- temperature of GE bulb 10°C higher than KOITO with the same lamp
- ST41 temperature 10°C higher compared to JT44XL, DZL with lamp assembly with same bulb
⇒ ST41 (GE) is 20°C higher compared to JT44XL(KOITO) (at bench test)
- Bulb base height from ground 80 to 50cm, windless

4. Report on Lamp Manufacturer Test same as 3 Above (Body Ext Design) . . Attachment ⑧

- bulbs (Lo terminal) with the same lamp exhibit temperature drops in descending order as follows Phillips > GE > Osram, but no major differences
- No difference with lamp assembly with same bulb (Phillips)
- Difference between Stanley and Yazaki bench test temperatures with Ele testing vehicles . . . Slight difference occurs since wind convection cannot be avoided,
..... Attachment ⑧
- a difference in heat dissipation behavior from lamp assembly base was clarified as a result of the investigation

☆ Based on above 3 and 4, temperature increase values (Lo terminal) due to lamp assembly differences and differences in bulbs approximately 50 to 60°C.

5. E/ROOM Temperature (LH, close to H/Lamp, ambient temperature=40°C)

MMC measured temperature (reference data) Attachment ⑧"

	Idle (0.5h)	120km/h (3% slope to drive up)
ST22	91°C	88°C
ST	85°C	46°C
ST41	84°C	77°C

6. Bulb body type list for all models

(Direct-mount type)

- AMP (non-watertight) . . HB2 . . Brass+tin plating . . affected by wiggling
- SEI (watertight) . . HB 5 . . copper alloy . . wiggle prevention design—ST22
- MCI (watertight) . . $\left\{ \begin{array}{l} \text{HB 3, 4} \\ \text{H 1, H 4} \end{array} \right\}$ copper alloy . . wiggle prevention design—2W00, 2J9SX

- Ele testing conduct idle soak test for each bulb type, depending on the results, to decide whether or not to extend testing necessary
- Drafting of proposed test method already completed
- Summary for Instances of Bulb terminal melting damage Attachment ⑩-1

Items indicated by MRDA

Bulb male terminal bend control modifications since 99.5.11. Melting damage continued to occur even after that time and thus not major cause.

- Market information analysis ⑩-2

search by MB943636 and MU801307as key⇒ f36 value

MMNA production is rather significant

- ST41 0.78%
- ST24S/28 1.29%
- Domestic ST 0.1% level
- EU ST 0.02% level

3. Summary

1) Countermeasure Proposal

- Production Vehicle Countermeasure : change to NQ connector (Yazaki Corp.)
- Countermeasure for vehicles already sold : coordinate with MMA PSC (QP)

2) Cause (Inferred) : believe there are no regional characteristics in North America

- | | |
|-----------------------------|-------------------|
| • ENG ROOM temperature | ST series : 80°C |
| + | + |
| • H/LP temperature increase | <u>50 to 60°C</u> |
| ↓ | =130 to 140°C |

exceeds heat stress relaxation temperature limit (120°C)

↓ wiggling, chattering

reached to melting damage? Conduct melting damage test (Yazaki Corp.)

3) Future Steps

① Conduct Melting Damage Reproduction Test (Yazaki Corp.)

heat stress relaxation ⇒ contact resistance increase ⇒ temperature increases
repetitive this cycle . . . validation of this mechanism

- ambient temperature 80°C
- H/LP . . . 13.3V terminal superimposed voltage (Lo beam)
- Water aspersion . . . 10cc/day
- Conduct with lamp assembly
- after connector terminal wiggling (0.8mm gap level)
- insert interval after injecting water to allow for oxidation

② ST24/41 E/ROOM (around lamp) repair history investigation (Ele Sys Design ⇒ MEDA)

③ North America ST, P45, MG engine room temperatures P45 (by 6/8) , MG (by 6/14)
Measured temperatures for ST, JT41, MGX, DX

④ Line claim analysis for MMNA ST (98/7 ~ ST41 mass production start ~) (Yazaki Corp.)

⑤ measure H/LP Gravity & vibration frequencies for ① (by No1 vehicle testing) (by 6/8)

⑥ review FTA from perspective of unique characteristics of North America (Ele testing
Ele Sys Design 6/8)

⑦ investigation of shipment status of spare parts

Document No.14

(Attachment ①,② for Document No.13)

Company	Mitsubishi Motors Corporation																
Subject: MMNA Headlamp Connector Melting Damage Report (Harness supplier terminal clamping control investigation) Date of Issue: May 31, 2001 Report No.: J801-B901 Author: YAZAKI Date of Test: Unknown (close to May 31, 2001) Test Place: YAZAKI																	
Test Vehicle and Sample Sample: Harness terminal Plant: YAZAKI Nimi plant, Daitoh plant, EMI, YTMI																	
Scope(s) Investigate control of terminal clamping activities at wiring harness supplier																	
Summary of Test Conditions and Test Results -Conclusion: (1)Contact force control, Wire tension (Fixing force) control 1)Contact force control : Not controlling. 2)Wire tension (Terminal Fixing force) : controlling (2)Applicator variation, clamping shape and press machine control																	
<table border="1"> <thead> <tr> <th>Machine</th> <th>Type</th> <th>Items Checked</th> <th>Checking Frequency</th> </tr> </thead> <tbody> <tr> <td>Applicator</td> <td>87</td> <td>from Applicator Periodical Check Sheet</td> <td>1 time/3months</td> </tr> <tr> <td>Clamp press</td> <td>YCM-2(2.5ton)</td> <td>from YCM-2 Periodical Check Record Sheet</td> <td>1 time/2years</td> </tr> <tr> <td>Clamp tool</td> <td>See below</td> <td>Check terminal back for protrusions according to inspection standard, if protrusion observed change clamp tool</td> <td>anytime</td> </tr> </tbody> </table>		Machine	Type	Items Checked	Checking Frequency	Applicator	87	from Applicator Periodical Check Sheet	1 time/3months	Clamp press	YCM-2(2.5ton)	from YCM-2 Periodical Check Record Sheet	1 time/2years	Clamp tool	See below	Check terminal back for protrusions according to inspection standard, if protrusion observed change clamp tool	anytime
Machine	Type	Items Checked	Checking Frequency														
Applicator	87	from Applicator Periodical Check Sheet	1 time/3months														
Clamp press	YCM-2(2.5ton)	from YCM-2 Periodical Check Record Sheet	1 time/2years														
Clamp tool	See below	Check terminal back for protrusions according to inspection standard, if protrusion observed change clamp tool	anytime														
<table border="1"> <thead> <tr> <th>Terminal Part No.</th> <th>Wire clamber</th> <th>Insulation clamber</th> <th>Anvil</th> </tr> </thead> <tbody> <tr> <td>7116-3355-02</td> <td>7116-3355-A</td> <td>7116-3355-A</td> <td>7116-3355-A</td> </tr> <tr> <td>7116-3358-02</td> <td>7116-3355-A</td> <td>7116-3355-A</td> <td>7116-3355-A</td> </tr> </tbody> </table>		Terminal Part No.	Wire clamber	Insulation clamber	Anvil	7116-3355-02	7116-3355-A	7116-3355-A	7116-3355-A	7116-3358-02	7116-3355-A	7116-3355-A	7116-3355-A				
Terminal Part No.	Wire clamber	Insulation clamber	Anvil														
7116-3355-02	7116-3355-A	7116-3355-A	7116-3355-A														
7116-3358-02	7116-3355-A	7116-3355-A	7116-3355-A														
(3)Delivered terminal parts inspection and history 1)Japan domestic factory: factory does not conduct delivery check, guaranteed by terminal supplier 2)EMI/YTMI: conduct visual, deformation, leak, and corrosion check																	
(4)Control of C/H (crimp height), C/W (crimp width) YAZAKI conducts the following according to its own internal standard.																	
<table border="1"> <thead> <tr> <th>Timing</th> <th>Measuring QTY</th> <th>Tool</th> <th>Record</th> </tr> </thead> <tbody> <tr> <td>when terminal replaced</td> <td>first terminal</td> <td>Microrometer</td> <td>Working</td> </tr> <tr> <td>when wire size and/or type changed</td> <td>last terminal</td> <td></td> <td>daily report</td> </tr> </tbody> </table>		Timing	Measuring QTY	Tool	Record	when terminal replaced	first terminal	Microrometer	Working	when wire size and/or type changed	last terminal		daily report				
Timing	Measuring QTY	Tool	Record														
when terminal replaced	first terminal	Microrometer	Working														
when wire size and/or type changed	last terminal		daily report														
(5)Check for change in wire purchasing route and wire changes Nimi factory/Daito factory (in Japan): procure from Hirosegawa factory Ohita part. No change since 1996. EMI-YTMI(Philippine): procure from YTMI and no change from 1996.																	
(6)Countermeasure part schedule plan 1)Nimi factory/Daito factory (in Japan): Deliver 2 months after EO received 2)EMI-YTMI (Philippine) Deliver 3 months after EO received																	
Comments																	

(EMI)

7116-3212-02					7116-3211-02				
C/H 1.20~1.30					C/H 1.20~1.30				
C/W 2.30~2.50					C/W 2.30~2.50				
NO	C/H	C/W			NO	C/H	C/W		
1	1.25	2.38	0.2	○	1	1.26	2.38	0.4	○
2	1.25	2.40	0.4	○	2	1.26	2.39	0.4	○
3	1.25	2.39	0.3	○	3	1.25	2.40	0.3	○
4	1.24	2.38	0.2	○	4	1.26	2.39	0.3	○
5	1.24	2.38	0.3	○	5	1.26	2.40	0.3	○

7116-3358-02					7116-3355-02				
C/H 1.20~1.30					C/H 1.20~1.30				
C/W 1.90~2.00					C/W 1.90~2.00				
NO	C/H	C/W			NO	C/H	C/W		
1	1.25	1.98	0.4	○	1	1.26	2.00	0.3	○
2	1.25	1.98	0.3	○	2	1.26	2.00	0.3	○
3	1.25	1.98	0.5	○	3	1.26	2.00	0.4	○
4	1.25	1.98	0.2	○	4	1.26	2.00	0.3	○
5	1.25	1.98	0.3	○	5	1.26	2.00	0.3	○

(YTM)

7116-3212-02					7116-3211-02				
C/H 1.20~1.30					C/H 1.20~1.30				
C/W 2.30~2.50					C/W 2.30~2.50				
NO	C/H	C/W			NO	C/H	C/W		
1	1.24	2.39	0.2	○	1	1.25	2.38	0.2	○
2	1.25	2.39	0.2	○	2	1.25	2.39	0.3	○
3	1.25	2.39	0.2	○	3	1.25	2.40	0.4	○
4	1.24	2.40	0.2	○	4	1.25	2.39	0.3	○
5	1.25	2.39	0.2	○	5	1.25	2.39	0.3	○

7116-3358-02					7116-3355-02				
C/H 1.20~1.30					C/H 1.20~1.30				
C/W 1.90~2.00					C/W 1.90~2.00				
NO	C/H	C/W			NO	C/H	C/W		
1	1.24	1.98	0.2	○	1	1.24	1.98	0.2	○
2	1.24	1.99	0.2	○	2	1.24	1.98	0.2	○
3	1.24	1.98	0.5	○	3	1.25	1.98	0.3	○
4	1.24	1.99	0.4	○	4	1.25	1.99	0.2	○
5	1.25	1.98	0.5	○	5	1.25	1.98	0.2	○

H/

7116-3356-02					7116-3355-02				
C/H 1.20~1.30					C/H 1.20~1.30				
C/W 1.90~2.00					C/W 1.90~2.00				
NO	C/H	C/W			NO	C/H	C/W		
1	1.25	1.97	0.2	○	1	1.25	1.96	0.1	○
2	1.25	1.88	0.1	○	2	1.27	1.96	0.2	○
3	1.25	1.97	0.1	○	3	1.25	1.97	0.2	○
4	1.25	1.97	0.2	○	4	1.25	1.98	0.2	○
5	1.25	1.88	0.2	○	5	1.25	1.89	0.2	○


7116-3356-02					7116-3355-02				
C/H 1.20~1.30					C/H 1.20~1.30				
C/W 1.90~2.00					C/W 1.90~2.00				
NO	C/H	C/W			NO	C/H	C/W		
1	1.25	1.98	0.3	○	1	1.25	1.97	0.2	○
2	1.25	1.99	0.3	○	2	1.25	1.98	0.3	○
3	1.25	1.99	0.2	○	3	1.25	1.98	0.3	○
4	1.24	1.98	0.2	○	4	1.25	1.98	0.3	○
5	1.24	1.99	0.3	○	5	1.25	1.98	0.2	○

Company	Mitsubishi Motors Corporation
Subject: Investigation of parts recovered from market (Investigation of parts recovered from market) Date of Issue: unknown Report No.: N/A Author: N/A (Yazaki) Date of Test: unknown Test Place: unknown (maybe YAZAKI in Washizu City)	
Test Vehicle and Sample Vehicle: Model(s): ST24S Sample1: Recovered parts 256713 (April 12, 2001) Sample2: Recovered parts 256491 (April 11, 2001)	
Scope(s) Investigate parts recovered from the market and contribute to analysis of root cause	
Summary of Test Conditions and Test Results -Conclusion: (1) Visual inspection No marks at mating side of terminals corrosion present on terminal surface (2) Electrical resistance values Resistance at the clamp is relatively low, however the terminal contact resistance is significantly high. (3) Impurities specifying investigation After bench test, significant amount of chlorine (Cl) detected from the sample. However, little Cl detected from the recovered samples. (4) Terminal gap investigation Com terminal gap wider than male terminal width (0.75mm), thus no contact The deeper the terminal is from entrance of male connector, the wider the Com terminal gap becomes. (5) Wiring hardness investigation The exothermic source could not be identified as either the terminal contact or clamp.	
Comments	


80	258713	258491	—
	2001.04.12	2001.04.11	—

		物7A(D)		
COM		測定不可 (0.48)	測定不可 (1.17)	—
Lo		4.28 (1.27)	148.6 (1.07)	—
Hi		9.80 (0.71)	208.8 (0.78)	—
Lo	A部	多量 Cu, Sn, I 少量 O, S, Cl, K	多量 Cu, Sn 少量 O, Na, S, Cl, Ca	多量 Cl, Fe, Cu, Zn, Sn 少量 O
	B部	多量 Cu, Sn 少量 O, Cl, Zn	多量 — 少量 —	多量 Cl, Cu, Sn 少量 O, Cr, Fe, Zn, Te
Hi	A部	多量 Ca, Cu, Sn 少量 C, O, Mg, S, Cl, K, Zn	多量 Sn 少量 O, Na, S, Cl, Cu	—
	B部	多量 Cu, Sn 少量 C, O, Mg, Cl	多量 — 少量 —	—
COM	G部	1.40(入口), 1.08(奥)	1.94(入口), 1.27(奥)	—
	D部	0.85	0.87	—
Lo	G部	0.88	0.88	—
	D部	0.88	0.88	—
Hi	G部	0.85	0.78	—
	D部	0.83	0.70	—
4mm		—	138	—
10mm		—	138	—
18mm		—	182	—

注1)



(所見)



m) : 3.73
m) : 2.45

m) : 2.38
m) : 1.24
l) : 77.2

n) : 3.75
n) : 2.37

n) : 2.32
n) : 1.26
: 76.9


l) : 3.70
l) : 2.47

) : 2.41
) : 1.28
: 77.2

) : 3.71
) : 2.40

) : 2.40
l) : 1.26
: 75.5

: 3.62
: 2.42




Document No.16
(Attachment ③ for Document No.13)

③

資料

◀ Q Terminal STRESS relaxation by samples at 100°C ▶
[Redacted]
100°C
(JK)



[Redacted]

Document No.17

(Attachment ④ for Document No.13)

Company	Mitsubishi Motors Corporation
Subject: Comparison of Temperatures around Headlamps with Other Vehicles (Headlamp temperature increase test) Date of Issue: May 31, 2001 Report No.: None Author: Sakamoto Date of Test: Unknown (close to June 6, 2001) Test Place: MMC Okazaki Plant	
Test Vehicle and Sample Vehicle: Model(s) and Model Year: ST41 02MY, ST28 02MY, Toyota Camry, ST22 02MY, PSU 04MY	
Scope(s) Terminal temperature increases after wiggling terminal could be the secondary cause of connector melting. Headlamp body heat radiation, engine room atmospheric temperature, harness wire diameter, connector heat conductivity are listed as potential factors in increasing temperatures. These factors are compared between ST28(ST24S), ST41, other MMC vehicles, and also other car manufacturers' vehicles.	
Summary of Test Conditions and Test Results • Conclusion: (1) ST41 LO and OOM terminal temperatures after idle saturation are about 30 degrees higher than 4 other vehicles. (2) ST28 (24S) all 3 terminal temperatures after idle saturation are 5~10 degrees lower than Camry. (3) The terminal temperature difference between LO and HI terminal is as large as 25 deg Celsius for ST41. • Measurements and/or Inspections: (1) Power source Engine off: fixed 13.3V from stable power source Idle and driving: actual battery used (2) Measurement level Record stable saturated temperature by monitoring with hybrid recorder (3) Driving conditions Drive until temperature saturated and then leave at idle till temperature saturated again* * Max temperature at idle: Drive until temperature saturates and soak at idle condition until saturated again. Only reference value since such a long idle soak with headlamps on rarely occurs. (This is only an abuse test to focus on potential differences between vehicles.) (4) Measuring condition At Eng off: other electrical loads off, engine room hood: open At Idle : other electrical loads off, engine room hood: closed	
Comments	

資料④

02MY ST41 0G72 A/T				02MY ST2B 4064 M/T				97 トヨタ カムリ V8 A/T				02 ST22 0G72 A/T				PSU F試	
2灯 GE HB2				2灯 GE HB2				2灯 HB2				2灯				シルバ三	
25.0°C	-	-	-	22.0°C	-	-	-	23.0°C	-	-	-	24.0°C	-	-	-	40.0°C	-
65.0°C	-	40.0°C	96.6°C	65.5°C	83.5°C	43.5°C	61.5°C	58.0°C	89.0°C	35.0°C	66.0°C	67.0°C	83.5°C	43.0°C	59.5°C	59.4°C	79.2°C
57.5°C	114.6°C	32.5°C	89.6°C	76.5°C	78.4°C	54.5°C	56.4°C	53.5°C	89.0°C	30.5°C	66.0°C	75.0°C	78.4°C	51.0°C	54.4°C	53.3°C	75.1°C
38.0°C	96.0°C	13.0°C	71.0°C	53.0°C	82.0°C	31.0°C	60.0°C	59.0°C	92.5°C	36.0°C	69.5°C	71.0°C	82.0°C	47.0°C	58.0°C	65.2°C	82.7°C
102.0°C	146.7°C	77.0°C	121.7°C	103.0°C	119.4°C	81.0°C	97.4°C	82.0°C	112.9°C	59.0°C	89.9°C	124.0°C	119.4°C	100.0°C	95.4°C	182.3°C	191.0°C
110.5°C	147.6°C	85.5°C	122.6°C	102.0°C	118.0°C	80.0°C	96.0°C	86.0°C	117.5°C	63.0°C	94.5°C	-	-	-	-	80.3°C	97.4°C
31.5°C	75.0°C	6.5°C	50.0°C	29.0°C	55.0°C	7.0°C	33.0°C	32.0°C	69.5°C	9.0°C	46.5°C	47.0°C	55.0°C	23.0°C	31.0°C	45.8°C	64.6°C
29.0°C	70.0°C	4.0°C	45.0°C	23.0°C	47.0°C	1.0°C	25.0°C	29.0°C	68.0°C	6.0°C	45.0°C	42.0°C	47.0°C	18.0°C	23.0°C	42.5°C	59.2°C
44.5°C	78.0°C	19.5°C	53.0°C	37.0°C	38.0°C	15.0°C	16.0°C	29.0°C	67.0°C	6.0°C	44.0°C	-	-	-	-	-	-

⑦

Document No.18

(Attachment ⑤ for Document No.13)

Company	Mitsubishi Motors Corporation			
Subject: Head Lamp Connector Terminal Wiggling Confirmation Test on Actual vehicles (Terminal wiggling confirmation test) Date of Issue: May 29, 2001 Report No.: C01-AA-287-033 Author: Endoh, Kawasaki, Itoh (Yazaki reps.) Date of Test: Unknown (close to June 8, 2001) Test Place: Yazaki (Washizu City)				
Test Vehicle and Sample Vehicle: Model(s): ST28, ST41 Sample:				
	Name	Type	P/N	Supplier
	Terminal	Q	7116-3211	AMP
		NG	7116-3400	YAZAKI
	Female connector	Q	7123-3230	AMP
		NG	7123-3233	YAZAKI
Scope(s) Confirm extent of terminal widening from abusive wiggling on actual vehicles. Wiggling is considered a potential factor in terminal widening.				
Summary of Test Conditions and Test Results • Conclusion: Q type terminal seems more susceptible to wiggling action than NG type terminal. (1) Q type terminals: 1) Terminal gap is significantly widened from wiggling action 2) Wiggling up-down direction tends to make the Lo terminal gap widen Wiggling left-right tends to make the COM terminal gap widen (2) NG type terminals: No gap enlargement from wiggling action. • Measurements and/or Inspections: Conduct tests below for each vehicle with headlamps on both sides and Q&NG terminals Measure each terminal enlargement value according to the independent procedures below. (1) No wiggling : n=1 (2) Up-down wiggling (Lo terminal rear most portion pushed down around vertical axis) : n=2 (3) Left-right wiggling (COM terminal rear most portion pushed around horizontal axis) : n=2				
Comments				

表-2

車種	コネクタ	コリ	部位	No	測定値	標準値	差	車種	コネクタ	コリ	部位	No	測定値	標準値	差	車種	コネクタ	コリ	部位	No	測定値	標準値	差	Com.					
																								mm	mm				
BT41	Q-AMP	1	左	1				BT28	Q-AMP	1	左	1	41.15	41.00	0.15	0.00	0.00	0.00	2	左	1	41.15	41.00	0.15	0.00	0.00	0.00	0.00	0.00
				2	42.00	42.00	0.00					0.00	0.00	0.00	0.00	0.00	0.00	0.00											
				3	42.87	42.87	0.00					0.00	0.00	0.00	0.00	0.00	0.00	0.00											
			右	1	42.17	42.17	0.00				0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00											
				2	42.88	42.88	0.00				0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00											
				3	43.75	43.75	0.00				0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00											
		2	左	1	42.17	42.17	0.00			0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00											
				2	42.88	42.88	0.00			0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00												
				3	43.75	43.75	0.00			0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00												
			右	1	42.17	42.17	0.00			0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00												
				2	42.88	42.88	0.00			0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00												
				3	43.75	43.75	0.00			0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00												
	NG-500	1	左	1				BT28	NG-500	1	左	1	61.35	61.00	0.35	0.00	0.00	0.00	2	左	1	61.35	61.00	0.35	0.00	0.00	0.00		
				2	62.20	62.20	0.00					0.00	0.00	0.00	0.00	0.00	0.00												
				3	63.07	63.07	0.00					0.00	0.00	0.00	0.00	0.00	0.00												
			右	1	62.37	62.37	0.00				0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00											
				2	63.22	63.22	0.00				0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00											
				3	64.09	64.09	0.00				0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00											
		2	左	1	62.37	62.37	0.00			0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00												
				2	63.22	63.22	0.00			0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00												
				3	64.09	64.09	0.00			0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00												
			右	1	62.37	62.37	0.00			0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00												
				2	63.22	63.22	0.00			0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00												
				3	64.09	64.09	0.00			0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00												

表-3 定規測ごり表

車種	コネクタ	部位	No	測定値	標準値	差
BT28	Q-AMP	左	1			
BT41						
BT28	NG-500	左	1			
BT41						

(mm)

	NG	Comp
—	—	0.01
Q	2	0.17
NG	1	0.05

Document No.19
(Attachment ⑦ for Document No.13)

Company	Mitsubishi Motors Corporation				
Subject: Investigation of Temperature around Head Lamp (Head Lamp Temperature Increase Test)					
Date of Issue: May 29, 2001					
Report No.: C01-AA-287-032					
Author: Endoh, Kawasaki, Itoh, Imamura (Yazaki repa.)					
Date of Test: Unknown (close to May 29, 2001)					
Test Place: Yazaki (Yashizu City)					
Test Vehicle and Sample					
Vehicle: Mode(Ks): Sample: O: Test conducted ⊙: Connector Difference Confirmed					
ST41	GE H4/HB2	PHILIPS H4	OSRAM H4	KOITO H4	KOITO H4/HB2
ST24S	⊙	○	○	○	○
CK	○	○	○	○	○
CBZ	○	○	○	○	○
JT44X	○	○	○	○	○
DZL	○	○	○	○	○
Connector & terminal		P/N	Material		
Yazaki	Connector	7123-3233-30	PBT		
	Terminal	7116-3400-02	Copper Alloy t=0.4 Tin plating		
AMP	Connector	7123-3230-30	66 nylon		
	Terminal	7116-3211	Brass t=0.32 Tin Plating		
		7116-3212	Brass t=0.32 Tin Plating		
Scope(s)					
Investigate and compare differences in bulb terminal temperature ranges for other MMC vehicles on bench.					
Bulb terminal temperature is considered a potential secondary factor.					
Investigate temperature differences according to different bulbs and connectors					
Summary of Test Conditions and Test Results					
•Conclusions:					
(1)Difference in temperature increases due to different headlamp shape The temperature increase value was highest for ST41, but there was no significant difference compared to other vehicles.					
(2)Difference in temperature increases due to different headlamp bulbs GE had the highest temperature increase, but there was no significant difference compared with other vehicles					
(3)Difference in temperature increases due to different connector types No significant differences compared to other vehicles.					
•Measurements and/or Inspections:					
Apply DC 13.3V to headlamp and measure temperatures for each location					
Measurements taken under windless conditions					
Measurement locations)					
1)Lamp terminal (Lo)					
2)Lamp terminal (Com)					
3)Lamp terminal (Hi)					
4)Bulb body					
5)Bulb body attachment hook					
6)Harness surface: 1place 5mm away from COM terminal clamp					
7)Atmospheric temperature behind connector					
Comments					

連同条件除く

4-2-2(1)										4-2-2(2)				4-2-2(3)				
項目	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18
20.0	20.0	20.0	20.0	20.0	20.0	20.0	20.0	20.0	20.0	20.0	20.0	20.0	20.0	20.0	20.0	20.0	20.0	20.0
63.5	67.5	70.0	72.1	73.5	74.3	74.4	74.7	75.0	75.0	75.0	75.0	75.0	75.0	75.0	75.0	75.0	75.0	75.0
77.2	81.2	84.1	86.0	87.1	87.5	87.6	87.7	87.8	87.8	87.8	87.8	87.8	87.8	87.8	87.8	87.8	87.8	87.8
126.0	130.0	132.1	133.0	133.5	133.6	133.6	133.6	133.6	133.6	133.6	133.6	133.6	133.6	133.6	133.6	133.6	133.6	133.6
162.4	164.4	164.9	165.0	165.0	165.0	165.0	165.0	165.0	165.0	165.0	165.0	165.0	165.0	165.0	165.0	165.0	165.0	165.0
207.7	212.7	215.0	216.0	216.5	216.6	216.6	216.6	216.6	216.6	216.6	216.6	216.6	216.6	216.6	216.6	216.6	216.6	216.6
254.4	261.4	263.1	264.0	264.5	264.6	264.6	264.6	264.6	264.6	264.6	264.6	264.6	264.6	264.6	264.6	264.6	264.6	264.6

4-2-2(4)										4-2-2(5)				4-2-2(6)				
項目	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18
20.0	20.0	20.0	20.0	20.0	20.0	20.0	20.0	20.0	20.0	20.0	20.0	20.0	20.0	20.0	20.0	20.0	20.0	20.0
67.4	71.2	73.2	74.7	75.0	75.1	75.1	75.1	75.1	75.1	75.1	75.1	75.1	75.1	75.1	75.1	75.1	75.1	75.1
81.0	85.0	87.0	88.0	88.5	88.6	88.6	88.6	88.6	88.6	88.6	88.6	88.6	88.6	88.6	88.6	88.6	88.6	88.6
126.0	130.0	132.1	133.0	133.5	133.6	133.6	133.6	133.6	133.6	133.6	133.6	133.6	133.6	133.6	133.6	133.6	133.6	133.6
162.4	164.4	164.9	165.0	165.0	165.0	165.0	165.0	165.0	165.0	165.0	165.0	165.0	165.0	165.0	165.0	165.0	165.0	165.0
207.7	212.7	215.0	216.0	216.5	216.6	216.6	216.6	216.6	216.6	216.6	216.6	216.6	216.6	216.6	216.6	216.6	216.6	216.6
254.4	261.4	263.1	264.0	264.5	264.6	264.6	264.6	264.6	264.6	264.6	264.6	264.6	264.6	264.6	264.6	264.6	264.6	264.6









図-1 概観

Document No.20
(Attachment ⑧' for Document No.13)

Company	Mitsubishi Motors Corporation
Subject: Investigation of Headlamp Connector Temperatures (Headlamp temperature increase test) Date of Issue: May 31, 2001 Report No.: None Author: Sakamoto Date of Test: May 31, 2001 Test Place: MMC Okazaki Plant	
Test Vehicle and Sample Vehicle: Model(s) and Model year: ST41 02MY, ST41 03MY, ST28 02MY, CK 02MY, Toyota Camry	
Scope(s) Terminal temperature increases after wiggling terminal could be the secondary cause of connector melting. Headlamp body heat radiation, engine room atmospheric temperature, harness wire diameter, connector heat conductivity are listed as potential factors in increasing temperatures. These factors are compared between ST28(ST24S), ST41, other Mitsubishi vehicles and also other car manufacturers' vehicle.	
Summary of Test Conditions and Test Results - Conclusion: (1) For ST41 03MY, there are differences in temperature values between MMC actual vehicle test & Stanley bench test. → Actual vehicle has higher temperature than the bench test. (2) Stanley bench test shows approximately 10 deg difference between placement directly on a table and 100mm above table. → 100mm offset results in 10 deg decrease. This may be partly from heat convection. (1) Power source Eng off: fixed 13.3V from stable power source At idle and at driving: actual battery used (2) Measurement level Record stable saturated temperature by monitoring with hybrid recorder (3) Driving conditions After driving till the temperature saturated, then leave at idle till the temperature is saturated.* * Max temperature at idle: Drive until temperature saturates and then soak at idle until saturated again Only reference value since such a long idle soak with head lamps on rarely occurs. (This is only an abuse test to focus on potential differences between vehicles.) (4) Measurement conditions At Eng off: other electrical loads off, engine room hood: open At idle: other electrical loads off, engine room hood: closed	
Comments	

ITEM 0211 0212 0213 0214 0215 0216 0217 0218 0219 0220										ITEM 0221 0222 0223 0224 0225					ITEM 0226 0227 0228 0229 0230					
ITEM NO.	QTY	UNIT	DESCRIPTION	ITEM NO.	QTY	UNIT	DESCRIPTION	ITEM NO.	QTY	UNIT	DESCRIPTION	ITEM NO.	QTY	UNIT	DESCRIPTION	ITEM NO.	QTY	UNIT	DESCRIPTION	
0211	1	PCB	0211	1	PCB	0212	1	PCB	0213	1	PCB	0214	1	PCB	0215	1	PCB	0216	1	PCB
0217	1	PCB	0218	1	PCB	0219	1	PCB	0220	1	PCB	0221	1	PCB	0222	1	PCB	0223	1	PCB
0224	1	PCB	0225	1	PCB	0226	1	PCB	0227	1	PCB	0228	1	PCB	0229	1	PCB	0230	1	PCB



Document No.21
(Attachment ⑧ for Document No.13)

TO: MMC [Redacted] R MGR

STANDY.
 OHSUMI FACTORY
 2001.05.20

<Title: H87 BUILD TOWER STAGE MEASUREMENT RESULT.>

BUILD BODY (CONNECTOR SIDE BODY PARTIAL)

BUILD BODY METALL. HOOF. ST Measurement (LHD)

← HRC exposure test on vehicle (RHSide)

← (LHSide)

← ST Measurement (LH side)

Measurement portion	BT測定(LHD)	MM (RHD) ← Hi beam ON		← (LHSide)	
	LoE-△点灯	Lo beam ON LoE-△点灯	LoE アイフル時	LoE アイフル時	LoE-△点灯
	Eng Off	Eng Off	Eng Off	Eng Off	Eng Off
	27.5	25.6	27.8	28.2	25.8
	86.2	112.3	134.7	138.0	120.3
	86.1	108.0	135.0	151.7	108.6
	82.8	89.7	116.5	147.0	90.0
	124.1	140.6	160.8	185.5	139.9
	105.4	109.4	132.9	149.8	107.8
	-	50.6	89.2	96.0	48.4
	-	27.4	27.6	81.4	30.3
hid lamp	-	-	-	-	-
(lamp) 107.7	-	-	-	-	106.6
(Lo) 108.0	-	-	-	-	108.7
(Lo) 107.5	-	-	-	-	100.6

03MY ST41 4G84

03MY ST41 4G84

03MY ST41 4G84

24Vル-保有のランプ

03MY ST41 4G84

Remarks
備考

(5/29)

Change terminal measuring poi.
 to be identical to MMC
 Lamp body is lifted up 20mm
 from the top of table.

① HMC BODY DESIGN
H.K. TERADA
MGR.

HB2, H4バルブ温度結果
TITLE: HB2, H4 BULB TEMPERATURE
MEASUREMENT RESULT

2001年03月23日
STANLEY ELEC.
2001/3/30
DATA ADDED

⑧

THE FOLLOWING TEST REPORT COMPANY IS REPORTED AS FOLLOWS:

STANLEY MEASUREMENT RESULTS & BULB TEMPERATURE MEASUREMENT RESULT.

Comparison of temperature after Hi & Lo simultaneous on.

Stanley measured data (1) to show lamp body temperature of different bulb suppliers.

Stanley measured data (2) with same bulb, measure at different lamp bodies. (Bulb was unified as Philips)

MEASUREMENT POINT	BULB SUPPLIER	LAMP BODY	VOLTAGE	CURRENT	TEMPERATURE (°C)		TEMPERATURE (°C)			TEMPERATURE (°C)			REMARKS
					Hi	Lo	①	②	③	④	⑤	⑥	
HMC Measured Bulb	HB2	GE	13.2v	Lo	121.0	124.0	Bulb Terminal			Connector			111.0
	HB2	GE	13.2v	Lo	122.0	126.0							87.0
	HB2	T	13.2v	Lo	92.0	113.0							85.0
	HB2	?	13.2v	Lo	115.0	113.0							88.0
STANLEY MEASUREMENT DATA (1) H4 Stanley measured data (2)	HB2	GE	13.2v	Lo	111.0	122.0	104.3	108.1	94.3	87.4	92.8	81.8	45.8
	HB2	GE	13.2v	Lo	128.0	125.0	128.0	130.0	121.9	98.3	104.8	101.1	48.8
	HB2	GE	13.2v	Lo	130.0	121.0	122.7	123.8	102.1	98.3	90.2	81.8	42.4
	H4	ST41	13.2v	Lo	112.0	124.2	91.8	108.4	84.8	87.4	87.7	83.1	48.8
	H4	ST41	13.2v	Lo	110.0	121.0	112.0	116.8	102.8	100.8	102.3	88.8	48.8
	H4	ST41	13.2v	Lo	120.0	122.5	120.6	126.7	122.8	114.8	105.8	107.8	62.8
	H4	ST41	13.2v	Lo	124.1	119.7	121.7	108.2	84.8	89.7	83.8	84.4	44.0
	H4	ST41	13.2v	Lo	122.1	124.1	127.1	131.8	128.8	101.4	108.8	107.8	47.8
	H4	ST41	13.2v	Lo	122.1	124.1	127.1	131.8	128.8	101.4	108.8	107.8	47.8
	H4	ST41	13.2v	Lo	122.1	124.1	127.1	131.8	128.8	101.4	108.8	107.8	47.8
STANLEY MEASUREMENT DATA (2) H4 Stanley measured data (3)	HB2	GE	13.2v	Lo	108.0	120.0							89.8
	HB2	GE	13.2v	Lo	122.0	120.0							89.8
	HB2	GE	13.2v	Lo	128.0	120.0							89.8
	HB2	GE	13.2v	Lo	128.0	120.0							89.8
STANLEY MEASUREMENT DATA (3) H4 Stanley measured data (3)	HB2	GE	13.2v	Lo	108.0	120.0							89.8
	HB2	GE	13.2v	Lo	122.0	120.0							89.8
	HB2	GE	13.2v	Lo	128.0	120.0							89.8
	HB2	GE	13.2v	Lo	128.0	120.0							89.8

Extracted from sample.

* Atm: 25.0°C
* Atm: 27.8°C
* Atm: 28.2°C
* Atm: 28.2°C
Sample submitted by STANLEY
MPIC measured at STANLEY
Measure actual vehicle
on board Atm: 29.0°C

* Atm: Atmosphere

Stanley measured Data (3)




Fig. 1. Bulb




Fig. 2. Terminal



Fig. 3. Connector

CONCLUSION:
ランプ本体での温度を比較し、上記図面参照より、バルブメーカーの違い及び灯体差による大きな温度差は認められませんでした。

There is no significant difference among the bulb supplier & lamp bodies, from Lamp Unit independent temperature measure ment. test result.

⑤

Document No.22

(Attachment ⑧" for Document No.13)


TITLE: ENGINE
 Based on
 at Idle &
 Summary
 previous data

DBTECT VEHICLES 調査車両	測定条件(高温度 40°C)		Experiment Report No. 要試験報告番号
	アイドル Idle	120km/h, 3% 走行	
ST41 MMMA 01MY 6G72	83.8°C	78.8°C	XLJ1-180463
ST248 F2 ^{F241} 4G64	86.3°C	84.3°C (70k,6%)	XLJ1-126803
ST22 MMMA 6G72	81.7°C	88.2°C	XLJ1-152148
YR DOM 6G72 4WD 5AT	81.4°C	71.7°C	T261-R026
JT41 4G93 GDI F1 ^{F241}	84.8°C	48.1°C	XLJ2-148878
JT45 4G93 GDI T/O F1 ^{F241}	72.1°C	80.1°C	XLJ2-152936
JT44X			
JT44XL 02MY 4G93 GDI	80.0°C	74.8°C	XLJ2-160904
DZL 02MY 4G84 GDI 4AT	80.2°C	69.2°C	XLJ2-156348
DZ			予-22L No data
DZX			予-22L No data
DX 98MY 4G63 4AT	76.8°C	62.9°C	XLJ1-033719 (T264-T049)
MGX 4G15 F2 ^{F241}	83.7°C	84.7°C	XLJ1-120388 (T264-T081)
CK 00MY DOM 4M41	88.2°C	61.3°C	XLJ1-133704
KR 01MY DOM 4G93 T/O	85.0°C	64.0°C	XLJ1-154242
P MMA 6G72 5A 4AT	82.3°C	77.0°C	XLJ1-012278 (T267-Q017)
P45			予-22L No data
MG DOM 4G93 T/O A/T	100.8°C	75.8°C	XLJ1-020647 (T267-R032)
MG DOM 4G15 4WD A/T	72.9°C	69.5°C	XLJ1-020578 (T267-R030)
W 95DOM 4G56 T/O 4WD	81.5°C	72.6°C	XLJ1-014746 (T267-Q025)
NGZ DOM 4G63 MPI T/O 4WD	81.4°C	61.4°C	XLJ1-161662

Document No.23

(Attachment ⑩-1 for Document No.13)

《Title : Mitsubishi R&D Information ST24/ST41 Head Lamp Connector problems per month》



5/1 (ANN) 5/1 (in) A A/ (4) 20
 Bulb bent modification done from 5/1 delivered lot.

10

1-67 材料

Document No.24

(Attachment ⑩-2 for Document No.13)

Document No.25

Meeting Minutes : Document Number J801-B097

Approved by Interior Design Dept. Mr. Nakashima

Created on June 6, 2001 by Electrical system Design(Ele Sys Design) Mr. Tozuka

(ST Headlamp Connector Melting Countermeasure Meeting June 6, 2001)

Attendees

Yazaki Corp: Mr. Sugiyama, Mr. Ito, Mr. Goto, Mr. Matsuo, Mr. Ohmura

Mitsubishi Motors Corp.: Mr. Nakashima, Mr. Harada, Mr. Tozuka, Mr. Tatemoto,
Mr. Kamiya, Mr. Sakamoto

1. June 4, 2001 problem parts returned from 7 instances via MRDA (including 3 bulbs and 1 bulb base returned)

Particular Items:

- wide affected region including CA, PA, DE, MI
- one case of reoccurrence after replacing at 3,000 miles
- Age deterioration - necessary to investigate cause and countermeasures
- Determine measures after analyzing cases 1 by 1

2. Detailed Analysis (meeting discussion for initial analysis level)

Overall: Significant probability of heat dissipation due to arc from melting condition

(would not go to this extent from Joule heat?)

→Previously conducted testing where arc made to intentionally jump (Yazaki→MMC)

- ① No.5: no arc marking on bulb terminal, only marking believed to be from sliding marking
- ② No.2: bulb Lo filament has severe damage, and observed yellow color around Lo in bulb
Arc marking on bulb COM terminal
Deformation of the connector Hi terminal believed to be from factors such as driver servicing
Connector COM terminal seem to be widened---detailed investigation necessary
- ③ No.4 : Connector COM terminal widening is significant
No tin plating luster for Hi, Lo, believed to be advanced corrosion
- ④ No.1: bulb & connector cannot separate sample, Yazaki Corp. will investigate in detail
- ⑤ No.6: 1* connector melting damage, replaced with repair connector, reoccurrence at 3000mile (3 month period)
Connector Hi, Lo terminal are clean with no corrosion
Connector COM terminal itself also tin specimen has no discoloration and clean
- ⑥ No.7: Connector COM terminal lost retention and fall off due to melting damage.
The COM terminal which fall of has a gap widened to approximately 0.8mm

- ⑦ No.3: housing, COM, Lo terminals both have thermal deformation
 Housing cracks and COM terminal irregular deformation are assumed to be occurring from mechanical damage when taking out the bulb from the connector

3. Future Steps

1) Schedule for Analyzing today's 7 samples (Yazaki Corp: by June 11th)

<1>Connector: Analysis Content

- ① terminal gap
- ② resistance values (clamp portion & overall terminal)
- ③ arc markings
- ④ bulb & connector cannot-separate sample returned part resistance values (break bulb glass and analyze) , breakdown analysis
- ⑤ surface analysis for only parts with tin plating discoloration
- ⑥ inferences for increased temperature from melting damage area (only this one by 6/15)

<2>Bulb: Bulb Investigation (Stanley Corp.)

- Filament damage
- analysis of yellow color fouling onto glass
- investigation of black discoloration of base

2) Inferences of Problem Causes

<1> Correlation with previous Column S/W Recall:

- ① Problem occurred continuously after replacement with countermeasure parts on 00/10/27, which shows weak relationship with occurrences

<2> Assume cause is due to factor other than column S/W when Hi/Lo are both turned on simultaneously

- Turn on Hi & Lo at the same time at bench and monitor melting location (Ele testing 6/8~)

<3> Possibility of Melting due to Arc

- bench testing preparations underway - Test to be done on 31 May.
- Wiggling + high temperature + vibration + water drop (Yazaki Corp.: jig by 6/8, test after 6/11)
- The results of previously conducted Yazaki Corp test showed similar melting to the Lo terminal at 0.8mm gap+vibration

<4> FTA Review

- difference between Domestic/North America ST

according to analysis results, only the salt difference – this was not a major factor according to the analysis result.

- Difference between ST and P45 for North America

<5> Considerations for reason to concentrate occurrence on COM terminal

- From the fixed bulb structure (if Lo beam frequency is taken as a major precondition) when applying current to Lo terminal, horizontal vibration, arc more readily occurs at the COM terminal (Mechanically, COM and Hi may be the same. The current existence difference makes COM occur more.)

<6> Consideration for reasons occurring only in North America

- Difference in base bulb retention strength (spring strength) ? (by 6/)
- Is DRL assembly aftermarket kit a factor?
- Each group reviews and submits potential factors (addressed to Mr. Nakashima Manager by 6/7)

(51)

01. 6. 6
内設部

NO	車種	VIN	ENG				備考
1	00galant	4A3AA18G4Y	4G64/A/T IL,CHICAGO		2	2065	RH
2	00galant	4A3AA18G5Y	4G84/A/T CA,CORONA	98,10,14	01,5,2	23621	
3	00galant	4A3AA18G0Y	4G84/A/T TX,HOUSTON	00,1,20	01,5,1	26761	LHJ
4	00eclipse	4A3AC84L9Y	6G72/A/T NY,ELMHURST	88,7,13	01,5,2	14420	RH
5	00eclipse	4A3AC54L0Y	6G72/M/T DE,WILMINGT	99,10,21	01,4,16	24000	LHJ
6	00eclipse	4A3AC54L5Y	6G72/A/T PA,PHILA	98,11,22	01,1,10	18895	
					01,4,13	19583	
7	01eclipse	4A3AC84H11	6G72/A/T NY,GLENDALE	01,1,9	01,5,2	3402	RH