



**Honda presentation
to
NHTSA Office of Defect Investigation
(00-01M Odyssey coil spring)**

April 20th 2006


Agenda

- Mechanism of spring fracture
- Tire Interference situation
- Warranty Analysis Overview
- Comparison to other manufacturers
- Conclusion

Mechanism of spring fracture

Structure of Front Strut Suspension


Honda Odyssey




Silencer tube

Coil spring


Spring lower seat



Mechanism of spring fracture by corrosion at the silencer tube of upper spring




Mechanism of spring fracture by corrosion at the lower spring seat



As the spring moves, it rubs against part of the spring seat, and the paint is stripped off of that portion of the spring.

Road dirt or sand and (salt) water collects on the spring seat and promotes rusting of the spring, which eventually results in fracture.



Tire Interference situation

ODYSSEY Front Spring Fracture Duplication Test

■ Test contents

Vehicle: ODYSSEY

The front spring was tested by breaking it at intervals of 30 degrees to establish whether such fracture would cause the alleged symptom of a punctured tire.

(Excluding the top and bottom end coils, the 2nd through 4th coils were broken at intervals of 30 degrees)

Behavior of broken spring:

The behavior of a broken spring at a given point would relate to a potential puncture in the involved tire. Both R and L springs were broken at intervals of 30 degrees, beginning with the 2nd coil from the bottom

At intervals of 30 degrees X 39 points (both R/L)

At intervals of 30 degrees




39 points









Broken location of spring, which resulted in puncture in tire

	NO.	Broken location	R side	L side		NO.	Broken location	R side	L side
			Puncture	Puncture				Puncture	Puncture
2nd coil from the bottom	1	360			4th coil from the bottom	25	1080		
	2	390				26	1110		
	3	420				27	1140		
	4	450				28	1170		
	5	480				29	1200		
	6	510				30	1230		
	7	540				31	1260		
	8	570				32	1290		
	9	600				33	1320		
	10	630				34	1350		
	11	660				35	1380		
	12	690				36	1410		
3rd coil from the bottom	13	720			37	1440			
	14	750			38	1470			
	15	780			39	1500			
	16	810			1 or more turns from the top				
	17	840							
	18	870							
	19	900							
	20	930							
	21	960							
	22	990							
	23	1020							
	24	1050							









Smoke and noise will occur and may have puncture
Smoke and noise will occur and may have tire failure
Smoke and noise will occur but no tire failure
No contact with tire, noise occur

● Confirmation of the situation in which the spring was broken at 360 degrees from the bottom

	Condition after fracture	Condition of tire	Broken location (▼)			
L side	Spring side face interfered with tire sidewall	Interference did not result in failure during 100km driving at 60km/h				
			<table border="1"> <tr> <td>Puncture may occur</td> </tr> <tr> <td>Tire failure may occur</td> </tr> <tr> <td>No puncture</td> </tr> <tr> <td>No contact with tire</td> </tr> </table>	Puncture may occur	Tire failure may occur	No puncture
Puncture may occur						
Tire failure may occur						
No puncture						
No contact with tire						
R side	Spring did not interfere with tire	No interference				
			<table border="1"> <tr> <td>Puncture may occur</td> </tr> <tr> <td>Tire failure may occur</td> </tr> <tr> <td>No puncture</td> </tr> <tr> <td>No contact with tire</td> </tr> </table>	Puncture may occur	Tire failure may occur	No puncture
Puncture may occur						
Tire failure may occur						
No puncture						
No contact with tire						


● Confirmation of the case in which the spring was broken at 1500 degrees from the bottom (at a point concealed in the silencer tube)

	Condition after fracture	Condition of tire	Broken location (▼)			
L side	Spring did not interfere with tire 	No Interference 	 1500 degrees from the bottom			
			<table border="1"> <tr><td>Puncture may occur</td></tr> <tr><td>Tire failure may occur</td></tr> <tr><td>No puncture</td></tr> <tr><td>No contact with tire</td></tr> </table>	Puncture may occur	Tire failure may occur	No puncture
Puncture may occur						
Tire failure may occur						
No puncture						
No contact with tire						
R side	Spring did not interfere with tire 	No Interference 	 1500 degrees from the bottom			

Water splash test for front coil spring


Test method:

- 1 Apply the water detection reagent on the damper spring.
- 2 Confirm the water splash point by a road test through water.









Splash road test : 20Km/h(12.4mil/h) 2 times(40m)

Tested vehicle : MDX (2HNYD18245H522775)




Odyssey front coil spring fracture rate is low, because Odyssey did not attach a silencer tube at lower part of spring.

MDX Main fracture point	MDX	ODYSSEY
 <p data-bbox="170 1019 514 1096">The water situation after a splash test</p> <div data-bbox="722 386 1381 748"> <p data-bbox="751 391 1304 435">Inside of a top silencer tube</p>  <p data-bbox="1056 459 1283 503">slight water</p>  </div> <div data-bbox="714 808 1390 1138"> <p data-bbox="751 813 1346 857">Inside of a lower silencer tube</p>  <p data-bbox="1014 878 1354 922">much muddy water</p>  </div> <div data-bbox="714 1182 1024 1425"> <p data-bbox="751 1187 1293 1230">Inside of a damper spring seat</p>  </div>	<p data-bbox="1430 483 1650 706">Fracture point (silencer tube attached after Jun/2001)</p> <div data-bbox="1415 846 1633 1224" style="border: 2px solid black; border-radius: 15px; padding: 5px;"> <p data-bbox="1444 878 1604 1187">Main fracture point at lower silencer tube</p> </div> <p data-bbox="1430 1263 1604 1356">Fracture point</p>	<p data-bbox="1692 483 1866 576">Fracture point</p> <p data-bbox="1713 878 1887 1031">NO silencer tube</p> <p data-bbox="1692 1263 1866 1356">Fracture point</p>

Fracture locations of springs returned from the market and fracture locations which are likely to result in puncture or failure

5 Odyssey springs were returned from the market. Most of the springs showed that the paint on the end coils was removed and that fracture occurred at a location where high stress is applied and road dirt or sand is apt to collect or at a location near the top of the spring where the silencer tube is fitted.


None of the 5 springs were broken at the location which could most likely result in tire failure.




Warranty Analysis Overview

of Occurrences by Model Year and Result

by Model Year



by Fractured spring or Tire Interference



Locations where fracture occurred in the field (00-01M)

Analysis of fractured springs returned from the market confirm that fracture occurred in locations not likely to result in a tire puncture or failure. In fact, no puncture or failure was reported in these cases.

Locations where fracture occurred in the field (Parts checked by HCM)

Top of Spring


VIN	Broken Portion		Puncture or failure
2HKRL18511H528008	1460°	1.05 turn from Top	No
2HKRL18571H527221	1460°	1.05 turn from Top	No
2HKRL1853YH543619	1460°	1.05 turn from Top	No

Bottom of Spring


VIN	Broken Portion		Puncture or failure
2HKRL1851YH516855	310°	0.85 turn from Bottom	No
2HKRL18631H579938	180°	0.5 turn from Bottom	No

(Angle shown is the degrees from the bottom end of the spring)

Warranty: Cumulative Coil Springs Fracture Rate by Months in Service



Warranty: Market Occurrence Data by States




Comparison to other manufacturers

Front Coil Spring Fracture Rate (US salt region)

4.6% ★
 2.0% ●
 1.3% ✦
 1.20% ■

1.25% ★



Conclusion

Conclusion

- 1. Analysis of available data and our understanding of the causes and effects of broken coil springs in these vehicles suggests that the failure rate will remain quite low, even areas of heavy road salt usage.**
- 2. Most of the failures that have occurred were either in the silencer tube (upper portion of the spring) or within the lower spring seat area, which cannot result in a tire puncture even if a broken spring contacts the tire.**
- 3. Of the small number of failures that have occurred outside of the silencer tube or spring seat areas, the broken spring in these vehicles provided the drivers with clear warning signs, including smoke and noise, with no report of any subsequent tire failure.**
- 4. We believe this problem does not merit a recall.**

End