PE06-042 HYUNDAI 12/22/06 ATTACHMENT 1 & 2

RECEIVED NVS-230

OFFICE OF DEATH

Supplemental Response Preliminary Evaluation (PE06-042)

2002MY Sportage Engine Cooling Fan

December 22, 2006

PE06-042 HYUNDAI 12/22/06 LETTER TO ODI TAB 1

02MY Sportage Cooling Fan Crack, Separation Reconstruction Testing Report

2006. 12. 06


KMC Quality Assurance Team 2


1. Test Introduction


- Purpose: Investigation on 02MY Sportage Cooling Fan Separation
- Date and Location: '06. 11/6 \sim 11/30, Hwasung R&D testing facility/GMB testing facility
- Test Method: Install artificially cracked fans in test vehicle to duplicate actual crack conditions (partial separation).
- Test Vehicle: Sportage in KMC's custody
- Testing Items:
- assess extent of noise and vibration during each cracked fan blade separation.
- Evaluate directional angle of separating fan blades and resulting damage to other engine parts.
 - testing done at various rpm levels (by engine rpm)

2. Test Reports

1) Damaged Cooling Fan's effect on steering wheel's vibration and noise







Damaged cooling fan blades (Two Blades) increases steering wheel vibration and noise. Driver can recognize the condition.

▶ At 3,000 rpm condition Vibration: 14.5 dB ↑ Noise: 12 dB ↑ b


2. Test Result

2) Directional angle of separating fan blades and resulting damage to other engine components. (Driving Condition and Non-Driving Condition)

Test Condition

Test Result

Install used cooling fan add addition cracks



- ▶ Driving condition: engine rpm range (1,000~4,000 rpm) cooling fan ON
- ► Non-Driving condition: engine rpm range (800~2,500 rpm) cooling fan ON

► Cooling Fan Damage Condition

	Engine rom	Happen	
Driving	3,000	Damage 1 Fan	
Non- Driving	2,500	8 Fans Individual fans damaged one at a time	

- ▶ Damaged fan blade causes a, "doo doo dook" noise and vibration on steering wheel (driving condition)
- ► Damaged fan blade hits Shroud Panel and falls to the ground
- No radiator damage (No coolant leaking)

2. Test Result

3) Directional angle of separating fan blades and resulting damage to other engine parts. (Fan Assembly Condition)

Test Condition

Install cooling
fan to test machine
with induced cracks
similar to those



reflected on used parts

► Tested at 2,500 rpm condition. (normal cooling fan assembly condition is 1600 rpm)

Test Result

► Of the 8 fan blades, 4 separated



- ► The 4 separated blades hit Shroud Panel: 2 on top, 1 on side, 1 on bottom; then fell to the ground
- ► No evidence of damage to the front area (radiator direction)

3. Test Opinion


- Driver can recognize fan separation condition by noise and vibration. Even if ignored, driver may notice a rise in the temperature gauge.
- If driver fails to recognize these conditions, engine overheating will occur.


3. Test Opinion


■ If fan blade separation occurs during repair (Engine ON), the fan blade will hit the Shroud Panel or other engine components before falling to the ground.


- Test results show that the blade hits Shroud Panel and falls to the

ground











Right Side Front Left Side



Cooling Fan Structure and Its Operation


Location





Operation


- ▶ Powered by Water Pump pulley, Fan Clutch controls Fan Speed based on ambient temperature from radiator





Operating Condition of Cooling Fan Assembly


Shaft Speed	Ambient Temp		Fan Speed	Hysteresis
4,200 rpm	ON	80 ± 5 ℃	$3,500 \pm 100 \text{ rpm}$	< 10 °C
	OFF	-	1,400 rpm (Max)	≤ 10 °C



■ Test Photos





Test Vehicle Measuring Equipments Noise Tester







Testing Sample (Blades)











♦ Test Report ◆

Team	Function T 3, Noise Vib Gr.		r. M	M No. –		※ Rep	_	
Reporter	J.H Ha	an 🕿 7032	D	ate	20	06. 11. 1	※ M/Fno	-* Original No
Title	2002MY Sportage Cooling Fan Damage NVH evaluation							
Drawing #	-				Parts	_		
Project. No.	Development	E/G	T/M	BOD'	Y	Material	11010	TDP-Function-01-01-0
_	MP	Gasoline 2000c¢	· -	_		_	Method	idle Vibration testing
Test Date	2006. 10. 20					Vendor	_	
Distribution	QA2, Design Ir	nprovement 2,Testing	13, Quality	Strategy	.Overs	sea Service 1/2	Attachement	None

1. Purpose and Methods

- Evaluate the effect of North America 2002MY Sportage cooling fan blades separation on NVH
- Comparative evaluation after fan blade separation (Intact fan/ 1 blade separation / 2 blade separation)

2. Conclusion

☑ Vibration increase significantly

→ Lay person can recognize it

3. Test Result

- Steering Wheel Vibration (unit: dB)

	ldle	2000 rpm	3000 rpm	
Intact	113.0	119.6	122.2	
1 Blade Separation	115.0	124.9	124.2	
2 Blade Separation	125.5	125.2	136.7	

4. Testing Condition


1) Vehicle: Sportage KNDJB7233W5 556328 (2WD M/T)

2) Location: Hwasung Plant


3) Tester: JH Han

<note> 1.※ Must be filled by tech management team</note>	Draft	Evaluation	Approval
 Must put control number Color photos and video are managed separately 			
	,	,	,

Intact
Intact
I Blade Separation
I Blades Separation




Intact
Intact
Intact
I Blade Separation
I Blade Separation



■ 3000 rpm

Intact
Intact
Intact
I Blade Separation
I Blade Separation



PE06-042 HYUNDAI 12/22/06 LETTER TO ODI TAB 2

Engine Compartment

