



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

ODI RESUME

Investigation: RQ08-006
Date Opened: 09/08/2008
Principal Investigator: Steve McHenry
Subject: Ignition Park-Shift Interlock

Manufacturer: Honda (American Honda Motor Co.)
Products: 2002 – 2003 Honda Accord Models with automatic transmission
Population: 680,000 (Estimated)

Problem Description: The interlock operation of the ignition switch may not function properly, making it possible to turn the ignition key to the "off" position and remove the key without shifting the transmission to park, increasing the possibility of a rollaway crash.

FAILURE REPORT SUMMARY

	ODI	Manufacturer	Total
Complaints:	15	0	0
Crashes/Fires:	10	0	0
Injury Incidents:	0	0	0
# Injuries:	0	0	0
Fatality Incidents:	0	0	0
# Fatalities:	0	0	0
Other*:	0	0	0

*Description Of Other:

Action: A Recall Query has been opened.

Engineer: Steve McHenry *SMCH*
Div. Chief: Jeffrey L. Quandt
Office Dir.: Kathleen C. DeMeter

Date: 09/08/2008
Date: 09/08/2008
Date: 09/08/2008

Summary: ODI has received 15 complaints regarding Model Year (MY) 2002 and 2003 Honda Accord vehicles allegedly experiencing a failure of the ignition park-shift interlock system which allowed the ignition key to be removed from the ignition switch without the vehicle being shifted to park. Ten of those complaints alleged the removal of the key without the vehicle being shifted into park resulted in a rollaway crash. One owner alleged that she was almost into her house when she noticed the car rolling out of the garage and down the driveway and that when she tried to stop the car it almost ran over her, before crashing into a cable box at the end of the driveway. Another owner alleged that the vehicle rolled out of the driveway and struck a tree across the street. There are eight other reports of the subject vehicles allegedly rolling away and striking other vehicles or objects.

In October 2003, American Honda Motor Company initiated Recall 03V-423 to correct an ignition park-shift interlock defect in certain MY 1999 Honda Odyssey, MY 1997-1999 Acura CL, MY 1999 Acura TL, and MY 1998-1999 Honda Accord vehicles. In January 2005, Honda initiated another recall to address defective ignition park-shift interlocks (Recall 05V-025), this time covering MY 1997-2001 Honda Prelude, MY 1999-2000 Acura TL, and certain MY 1999-2002 Honda Accord vehicles. Not all MY 2002 Honda Accords were covered under Recall 05V-025. The remaining MY 2002 and all MY 2003 Accord vehicles are covered in the scope of this Recall Query.

A Recall Query has been opened to assess the scope, frequency, and potential safety-related consequences of the alleged defect.

#