Sensing tomorrow™

Doc.No.AQ-F080017(1/10)

Cc: MMC-Japan

3A45 P/W AS SW Failure Returned Part Analysis Result Report

March 4, 2008
Omron Corporation AEC Company
Quality Assurance Division
Omron Dualtec Automotive Electronics Inc.
Quality Assurance

Table of Contents



Doc.No.AQ-F080017(2/10)

- 1. Failure Outline
- 2. Conclusion
- 3. Returned Part Investigation Result
 - (1) Trim appearance examination
 - (2)P/W SW appearance examination
 - (3)X-ray internal examination
 - (4)SW internal examination
 - (5) Element analysis
- 4. Countermeasure Implementation History

1 Failure Outline



Objective

Doc.No.AQ-F080017(3/10)

P/W AS SW on 3A45 owned by the employee at MMNA Cypress developed a smoking failure. The root cause of this failure needs to be identified.

◆ Failure Occurrence Status

- •In the evening of January 14, 2008, smoke started from AS seat P/W SW immediately after IG was turned on giving off burnt smell.
- •Approximately since two months ago, P/W SW operational failure has been occurring and DR seat Master SW becomes inoperative. AS seat SW sometimes becomes inoperative.

Vehicle No.	VIN:4A4MM31S64E113251(04.5MY)
Vehicle manufactured date	March 15, 2004
Vehicle sales date	October 23, 2004
Failure occurrence date	January 14, 2008
Mileage	Not confirmed
P/W SW production lot No.	A4050(Manufactured on Feb.19, 2004)

2 Conclusion



Sensing tomorrow™

♦ Conclusion

Doc.No.AQ-F080017(4/10)

We have concluded that the recent SW failure led to smoking by the same mechanism as 2C41 P/W AS SW failure reported back on September 17, 2004.

Based on the following consideration (*1, *2 respectively), the recent failure is thought to be an extremely rare case.

- *1: The possibility of its occurrence in the market is very low.
- *2: Recreation test result shows that the probability of recurrence is low.

[Mechanism of occurrence]

Liquid with high content of electrolytes, such as sports drink, was spilled in a large quantity (250ml or more) at once in the vicinity of Sub SW knob area.

Liquid that entered the switch adhered to the broached area between IG-MU.

Adhered moisture dried out leaving deposit of electrolytes and carbide between traces.

Deposit of electrolytes and carbide absorbed moisture leading to a leakage between traces.

Heat and smoke generated as certain resistance value was reached.

*1




Sensing tomorrow™

Trim appearance examination

Doc.No.AQ-F080017(5/10)

· Carbonization was confirmed in the vicinity of UP side NO contact on insert-molded base of P/W SW.

·Confirmed melting of P/W SW connector housing and the harness coating in the




OMRON

Sensing tomorrow™

♦ SW appearance examination

Doc.No.AQ-F080017(6/10)

- Contamination confirmed in the vicinity of P/W SW knob and D/L SW knob.
- Confirmed melting at the upper portion of UP side NO contact on case surface.




OMRON

Sensing tomorrow™

◆ X-ray internal examination

Doc.No.AQ-F080017(7/10)

•Confirmed broken IG trace in the vicinity of Up side NO contact area (connector side) and melted MU trace with a narrowed width.




OMRON

Sensing tomorrow™

◆ P/W SW internal examination

Doc.No.AQ-F080017(8/10)

- ·Confirmed significant carbonization in the vicinity of UP side NO contact area.
- •Confirmed that movable plate in UP side is sticking due to melting of insert-molded base resin.
- •Confirmed carbonization in the upper portion of UP side NO contact (between IG-MU) on the back of the case.
- ·Confirmed UP side plunger got carbonized and broken.



OMRON


Sensing tomorrow™

3 Returned Part Investigation Result

Element analysis

From the fact that ionic impurities (i.e. K,Ca,Cl,Mg,etc.) are found under P/W SW knob, fluid intrusion inside SW is considered a high possibility.

Doc.No.AQ-F080017(9/10)



4 Countermeasure Implementation History Sensing tomorrow

OMRON

History of countermeasure implementation

Doc.No.AQ-F080017(10/10)

* Grease change

NS1696(Syn-tech) → Multemp D #2

Sep-1, 2004

* Case change

Jan-27,2005

