Jan 19 01 05:31p 01/11/01 18:38 FAX



ENGINEERING ANALYSIS ASSOCIATES, INC.

30700 Telegraph Road - Suite 4546 Bingham Farms, telchigan 46025-4326

PHONE: 248-642-3232

FAX: 248-642-4558 NOTICE: DC is looking into starting a pilot program in the Detroit and San Francisco areas using digital cameras. The pilot has a tenntative start date of

Feb. 1, 01. We will have more information to distribute as it becomes available to us. Facsimile Cover Sheet DaimierChrysler Vehicle Investigation Report (VIR) Delorae Time: 2.5 Honr(s) Deluxanc Miles: 98 +40 = 128 Owne Transmitting

EAA No: DF01- 341701	If transmission not complete, ple call the above phone number.			
CAIR No: 810000	call the above phone number			
	From: Tina Martin			
То:	Date Faxed:			
Phone No:	Due Date: Co			
Fex No: 203 746 3000				

Please acknowledge promptly by FAX or phone. DATE /~//-0/ Receipt of CAIR and Accepting case for investigation YES

	AA for closure) erChrysler Fax Num	ber: 248-512-8743
Bennie (248) 944-7036 Bott (248) 944-7056 Gilbert (248) 944-7037	☑ Marteil ☐ Mucci ☐ Porterfield	(248) 944-7038 (248) 944-7039 (248) 944-7134
Comments:		
	· · · · · · · · · · · · · · · · · · ·	

() CHILY	SLER ORATION Pro	Confidential iminary Vehicle Investigation	Report REF. # 8/75357
01 8	THE PROPERTY OF THE PARTY OF THE PARTY OF	CHIP / 3 MG / G	1,0,2,3 06 1,21,8 9-14-00
		34 Phospect	57-
OTY TO	20	CT.	Estati
ILLING DEALES	enyville	ZONE DIR CODE CITY	05
		31 41336 TORRINGT	MINOR HEPAMERIMATE
HAYSLAN NEW	IL KING EAA		EST. ATTACHED.
 		INTERVIEW	TIME OF INCIDENT INSPECTION DATE
NTERVIEW WITH	N NAML	INTERIOR DATE OF INCIDENT	11.00 (M) A 1. 10.01
DRIVER SOWNER OTHER		0,1 1,9 0,1 0,1 0,6	
OLIN OLIN	FIVENT INCLUDING WEATHER CONDITION	ME HOOD FLEW OPEN WHI	LE DIUVING ON 19E
M Conver's a	makes the children was	ALLEN FEEL STURT THE	SECONO " MY.
finactions of the control of the con	's description il	ETIVE . IT WAS BENT A	NO DID MOT HOLD.
What? W	Then? Whoro?	<u> </u>	
Exact ord	ter of overois		
Did this h	nappen before?		. 441 11
	Personal Injury: Were th	nore Personal Injuries? Li Yes Mi No	If yes, complete section "L."
		NT: SHOW TO NO ONE & DRAW NO CO	NCLUSIONS
	كالمستهدي والمستوان والمستوان والمستوان والمستوان	UT UPPER PART OF FORM.	
 - · · · ·	• FOLLO	OW INSTRUCTIONS FOR SECTION "A" ON OW INSTRUCTIONS FOR SPECIFIC ALLEGATION ANY ADDENDUMS TO REPORT AND STATEMENT MISSING COMPONENTS AND WHO READY AFTERMARKET EQUIPMENT INSTALL	TE SECTION IT PERTAINS TO
ALLEG.	PHOTOGRAPH REQUIRED	INFORMATION	EVALUATION
General	☐ From center of volucle front every 45 degrees (8 total)	Police report VO Si Vohicle service lile VS Of uncupant of inciden	s description . discum and measurements
_		Any reports/photos by others UNK - What? W	high? Where?
Α	both original lateral sight lines. (8 total)	Exact ord	er of events
 -		EDWARD I-WILSONS GOOD HIS HIS	appen before? MD
		(Dodge) SONS TOLRINGTON, CT.	
	Q Send neg. & 2 sets of prints	TORRINGTON, CT.	and the same of th
	· · · · · · · · · · · · · · · · · · ·	-	Evidence of tampening or
Airbag(s)	☐ Steering Whice!	☐ Record: ☐ Was Arrbag deployed? ☐ Use DAB II	disassembly?
	U Arbag(s) U Knee Blockers	Driver 🔘 Yes 🗓 No 💛 Hudard Existin	g Readings
	CI All posible body contact areas	Passenger Li Yes Li No I—	· ·
	All code readings using DRB it	☐ THE ☐ Sid. ☐ Record Stores	
R		LJ Condition of Steering Wheel	
		?	
		Condition of Steering Wheel Mounting (measure column collapse) Li Important: DC DTB II READ	NOT ERASE

Jan 19 01 05:31p CAROL &BILL KING 203 745 3553

9175257

- - -

054 # 817 <u>6357</u>

ADDITIONAL COMMENTS

CAIR #: 8175357

PRIMARY HOOD LATCH ASSEMBLY:

 THE PRIMARY HOOD LATCH RELEASE CABLE, BETWEEN THE RELEASE LEVER AND HOOD LATCH MECHANISM WAS INTACT AND FUNCTIONED FREELY WITHOUT BINDING OR STICKING WHEN TESTED REPEATEDLY AT THE TIME OF INSPECTION. IT IS NOTED THAT THE HOOD SPRUNG OPEN (MINOR) WHEN THE HOOD WAS RELEASED DUE TO THE HOOD SPRINGS BEING BENT.

SECONDARY HOOD LATCH ASSEMBLY:

• THE SECONDARY HOOD LATCH FUNCTIONED PROPERLY WHEN TESTED REPEATEDLY AT THE TIME OF INSPECTION.

NOTE: THE DEALERSHIP BODY SHOP MANAGER STATED THAT THE UPPER PORTION OF THE SECONDARY LATCH ASSEMBLY (ATTACHED TO HOOD PANEL) WAS BENT BACK ABOUT 75 PERCENT FROM IT'S NORMAL POSITION AT THE TIME OF HIS INSPECTION FOLLOWING THE ALLEGED INCIDENT. THE BODY SHOP MANAGER STATED THAT HE STRAIGHTEND THE UPPER LATCH MECHANSIM TO ENABLE THE CUSTOMER TO USE THE VEHICLE. THE CUSTOMER STATED THAT THE BODY SHOP MANAGER STRAIGHTEND THE UPPER LATCH HOOK WITH HIS FINGERS PURPORTING THAT THE LATCH HOOK LACKED INTEGRITY.

BOTH THE PRIMARY AND SECONDARY HOOD LATCH ASSEMBLIES FUNCTIONED PROPERLY AT THE TIME OF INSPECTION.

Noth, inches and a Due to THE CIECUMSTANCES COVERING THIS INCIDENT, I would TIKE to be CONTACTED BY THE TONESTIGHTON FROM Dodge: You HAVE my COII \$ 307-9170. A Cittle BACKGROUND to +HIS INCIDENT, AS YOU MAY RECALL THE MECHANIC WHO FULLED THE TRUCK 1200 HAS GARAGE STATED " +HE LATCH DID WORK," WHEN YOU AND I WONT INTO I + HE GARAGE YOU SAW THAT IN FACT IT DID NOT, NOW I HAD NO ROBON to CONTACT THE DEDIOR ABOUT TRIS ITEM DUE TO THE SAPETY ONTEN NOT GORKING FROM PRY ONE BECAUSE IF it DONT WORK WITH 17.8 MILES ON it WHEN I BOUGHT it; HOW D.O I KNOW IT WAS AN ITEM THAT WAS BROKE AS THE OFFICE of Consumer PROTECTION SAYS WHAT DOES THE MILBERT HAVE TO DO WITH THE SAFETY CATCH. Also IF Your Body MAN DOES 10 of THESE HOODS A YEAR I THINK THORE JUST MIGHT BO A

DEFECT IN MANAFACTURING TOR DESIGN THAT NEEDS TO BE RODRESSED. THE SECOND MATTER 15 You'll NOTICE THE SMALL CHIP ON THE UPPER LEFT CORNER ON THE BACK DOOR THIS CAUSED BY THE FRONT DOOR INVERMITTENTY SHIFTING AND CATCHING ON THE CORNER THIS DOES NOT HAPPEN CONSISTENTLY BUT THE CHIPPED PAINT PROVES THAT IT DOES HAPPEN - Blows CHECK THIS OUT AND COT ME KNOW WHAT THE CAUSE AND Remody is FOR THIS PROBLEM THANK YOU

MA SPELL IN LOOS/EL/LO 68442

Job Number:

WILSON DODGE NISSAN

License #:05-84144-000 Federal ID #:060667538

Serving Torrington Since 1926

1530 East Main St.

Terrington, CT 86798 (860)482-SSSS Fax: (860)496-4013

PRELIMINARY ESTIMATE

Written by: Norman Deneault # Adjuster:

Insured: Owner:

Address:

Day:

Evening:

Claim # Policy #

Deductible: Date of Loss: Type of Loss:

Point of Impact: 12. Front

Inspect WILZON DODGE NIZZAN Location: 1530 East Main St.

Torrington, (T D5790

Insurance

Company:

Days to Repair

Business: (860)482-5555

2001 DODG BRISOD 4X4 QUAD CAB 8-5-21-FI 4D SHORT GOLD Int: VIN: 387HF13Y916 Lic:

Intermittent Wipers Power Steering Driver Airbag

Dual Mirrors Power Brakes Passenger Airbag

Prod Date:

Odometer: Clear Coat Paint Anti-Lock Brakes (2) Split Bench Scats

Rear Step Bumper Styled Steel Wheels

NO.	0P.	DESCRIPTION	QTY	EXT. PRI	CE LABOR	PAINT
1.		HOOD & GRILLE				
5	Repl Hoo	d from 12/4/3	ľ	695.00	1.5	3.2
3	Add	for Clear Coat				1.3
4	Add	for Underside(Complete)				1.6
5		for Clear Coat				0.3
ь		ety catch	J.	11.25	Incl-	
7		Hinge from 10/20/97	1.	76.50	0.3	0.3
	Repl LT	Hinge from 10/20/97	ı	76.50	0.3	0.3
		Subtolals ==>		A59.25	2.1	7.0

p.10

D1/19/2001 at 11:42 AM 68442

Job Number:

PRELIMINARY ESTIMATE

2001 DODG BR1500 4X4 QUAD CAB 8-5-2L-FI 4D SHORT GOLD Int:

Parts	859-25
Body Labor	2-1 hrs â ≎ 40-00/hr — 84-00
Paint Labor	7-0 hrs a \$ 40-00/hr
Paint Supplies	7.0 hrs 0 + 16.00/hr 112.00
Body Supplies	2.1 hrs 0 + 2.00/hr 4.20
CHOTATAL	- 1330 us
ZUBTOTAL	* 1339.45
Sales Tax	\$ 1339.45 a 6.0000% 80.37
GRAND TOTAL	* 1419·82
:ZTMATZULGA	
Deductible	٥٠٥٥
CUSTOMER PAY	• 0.00
INSURANCE PAY	\$ 1419.82

This is a visible damage quotation only. Additional damage may be discovered upon tear down resulting in additional parts, labor, and expense.

Estimate based on MOTOR CRASH ESTIMATING GUIDE. Unless otherwise noted all items are derived from the Guide DR3TA94 Database Date 11/2000 and the parts selected are OEM-parts manufactured by the vehicles Original Equipment Manufacturer. Asterisk (*) or Double Asterisk (**) indicates that the parts and/or labor information provided by MOTOR may have been modified or may have come from an alternate data source. Non-Original Equipment Manufacturer aftermarket parts are described as AM or Qual Repl Parts. Used parts are described as LKG, Qual Rery Parts, R(Y, or USED. Reconditioned parts are described as Recon. Record parts are described as Record. NAGS Part Numbers and Prices are provided from National Auto Glass Specifications. Inc. Pound sign (#) Items indicate manual

Pathways - A product of CCC Information Services Inc-

DAIMLERCHRYSLER

DaimlerChrysler Motors Corporation

January 22, 2001

Terryville, CT

Reference No.: 8175357

V.I.N.: 3B7HF13Y91G

Dear

This will further acknowledge your recent contact with DaimlerChrysler Motors Corporation, regarding an incident with the above-mentioned vehicle.

I have had the opportunity to review the inspection report generated by our engineering firm, and can advise you that we are not convinced of a manufacturer's responsibility.

Based on this information, I can only suggest allowing your insurance carrier to continue the handling of this claim.

Should they determine DaimlerChrysler Motors Corporation has a responsibility, they have full subrogation rights under the terms of your policy.

Sincerely,

M. H. Martell Special Investigations (248) 944-7038

MHM/kat