The second section of the second section is the second section of the second section in the second section is

863 6017

05/15/2001 at 12:18 PM 15469 Job Number:

FERMAN COLLISION CENTER

43520 U.S. Hwy 19 North Tarpon Springs, FL 34689 (727)934-5789 Fax: (727)937-1727

PRELIMINARY ESTIMATE

Written by: DON HEIRHOLZER # Adjuster:

Insured:
Owner:
Address:
LUTZ, FL

Claim #
Policy #
Deductible:
Date of Loss:
Type of Loss:
Point of Impact:

Inspect Location:

Cellular:

Insurance Company:

Days to Repair

2001 DODG BR1500 4X2 QUAD CAB 8-5.2L-FI 4D LONG BLUE Int:

VIN: 3B7HC13YX1G Lic:
Intermittent Wipers Dual Mirror
Power Steering Power Bra
Priver Airbag Passenger

Dual Mirrors
Power Brakes
Passenger Airbag
Styled Steel Wheels

: Odometer: 6506 Clear Coat Paint Anti-Lock Brakes (2) Split Bench Seats

river Air ear Step	bag Bumper	Passenger Alibay Styled Steel Wheels				
NO.	OP.	DESCRIPTION	YTQ	EXT. PRICE	LABOR	PAINT
1 2	Repl	HOOD & GRILLE Hood from 12/6/93 Add for Clear Coat	1	695.00	1.5	3.2 1.3 1.6
3 4 5 6	n 1	Add for Underside (Complete) Insulator retainer Safety catch Handle w/rod w/Sport package	10 1 1	15.00 11.25 8.25	Incl.	2 · ·
7 8 9 10	Repl Repl Repl	Guide RT Hinge from 10/20/97 LT Hinge from 10/20/97 Grille all blue	1 1 1	3.10 76.50 76.50 460.00	0.3 0.3 Incl. 0.3	0.3
11 12* 13	Rpr	Frame w/o chrome Nameplate	1	10.70	Incl.	1.0
14# 15 16#	Refr	OTHER CHARGES E.P.C.	1	3.00		
		Subtotals ==>		1359.30	2.4	7.7

05/15/2001 at 12:18 PM 15469

Job Number:

PRELIMINARY ESTIMATE

2001 DODG BR1500 4X2 QUAD CAB 8-5.2L-FI 4D LONG BLUE Int:

Parts Body Labor Paint Labor Paint Supplies Body Supplies Other Charges	2.4 hrs @ \$ 35.00/hr 7.7 hrs @ \$ 35.00/hr 7.7 hrs @ \$ 18.00/hr 2.4 hrs @ \$ 1.00/hr	1356.30 84.00 269.50 138.60 2.40 3.00
SUBTOTAL Sales Tax	\$ \$ 1853.80 @ 7.0000%	1853.80 129.77
GRAND TOTAL	\$	1983.57

This Estimate is based on a visual inspection of noted damage only. After repair is started, additional or hidden damage is likely. This additional damage and or parts will result in a higher price for this repair. The part prices are from the current listed MOTOR's suggested guide price. Actual cost may differ from the manufacturer at time of repair.

FAILURE TO USE THE INSURANCE PROCEEDS IN ACCORDANCE WITH THE SECURITY AGREEMENT, IF ANY, COULD BE A VIOLATION OF S. 812.014, FLORIDA STATUTES. IF YOU HAVE ANY QUESTIONS, CONTACT YOUR LENDING INSTITUTION.

Estimate based on MOTOR CRASH ESTIMATING GUIDE. Unless otherwise noted all items are derived from the Guide DR3TA94 Database Fure 2/2001 and the parts selected are OEM-parts manufactured by the vehicles Original Equipment Manufacturer. Asterisk (*) or Double Asterisk (**) indicates that the parts and/or labor information provided by MOTOR may have been modified or may have come from an alternate data source. Non-O: ginal Equipment Manufacturer aftermarket parts are described as AM or Qual Repl Parts. Used parts are described as LKQ, Qual Recy Parts, RCY, or USED. Reconditioned parts are described as Recon. Recored parts are described as Recore. NAGS Part Numbers and Prices are provided from National Actor Glass Specifications, Inc. Pound sign (#) items indicate manual entries.

Pathways - A product of CCC Information Services Inc.

Delorme Time:_	99 + 40 = 139
Delorme Miles:	99 +40 = 139
(The extra 40 Mi DRB pick up and to pick up police :	les is for traveling to accident site, of return if required and traveling

ENGINEERING ANALYSIS ASSOCIATES, INC.

30700 Telegraph Road - Suite 4566 Bingham Farms, Michigan 48025-4532 (248) 642-3232 FAX (248) 642-4558

> PHONE: 248-642-3232 FAX: 248-642-4558

Facsimile Cover Sheet ysler Vehicle Investigation Report (VIR)

Owner:	
EAA No:	DF01- 41992
CAIR No:	8636017

To:	· Wick	Adlandyse	
Phon			
Fax I	vo: 813-	- 445-5538	,

Transmitting_	(3)	pages.	-
If transmission	not com	piete, pi	ease
call the above	phone nu	ımber.	

From: Felicia	Mathis	
Date Faxed:	5.14	
Due Date:	5.17	

Please acknowledge promptly by FAX or phone.

Receipt of CAIR and Accepting case for investigation

YES NO DATE

5-14

Fax Cover	sheet for DaimlerChr	ysler (Service Assoc EAA for closure)	ciate Use Only)				
losure Date:	sure Date: DaimlerChrysler Fax Number: 248-512-8748						
<u>/6-</u> lumber of pages (
O:							
🗆 Bennis (2	48) 944-7036	☐ Martell	(248) 944 -7038				
	48) 944-7056	☐ Mucci	(248) 944-7039				
茂 Gilbert (2	.4 8) 944-703 7	☐ Porterfield	(248) 944-7134 ₃₉				
Comments:	Asserse	T Compl	stor 5-16.0)				
_							

May-16-01 14:20 R.J. FALANDYSZ 813 645-5538 P.O2 MAY 16 '01 15:24 813 645 5538 PAGE.002

P.01

Delorme Time: 5,0 Hour(s)	•
Delorme Time: 5.0 Hour(s) Delorme Miles: 99 +40 = 13	9
(The extra 40 Miles is for traveling to DRB pick up and return if required	accident site, and traveling
to pick up police report)	


ENGINEERING ANALYSIS ASSOCIATES, INC.


30700 Telegraph Road - Suite 4566 Bingham Farms, Michigan 48025-4532 (248) 642-3232 FAX (248) 642-4558

> PHONE: 248-642-3232 FAX: 248-642-4558

wner: AA No: DF01- 41997- AIR No: 8636017	Transmitting pages. !f transmission not complete, please call the above phone number.
to: Dick Felandyst thone No: 10: Wax No: 813-445-5538	From: Felicia Mathis Date Faxed: 5.14 Due Date: 5.17
Please acknowledge promptly by FAX or phore	stigation YES NO DATE 5-14
Please acknowledge promptly by FAX or phore Receipt of CAIR and Accepting case for inves Fax Coversheet for DaimlerChi (also fax to Daim)	rysier (Service Associate Use Only) EAA for closure) lerChrysler Fax Number: 248-512-8748
Please acknowledge promptly by FAX or phore Receipt of CAIR and Accepting case for inves Fax Coversheet for DaimlerChair (also fax to	rysler (Service Associate Use Only) EAA for closure)

CHRYSLER CORPORATION Prei		Confidential minary Vehicle Investigation Report REF # <u>84340/</u>		
YEAR MODEL KSO D	VEHICLE IDENT	IFICATION NUMBER	OOOMETER	M.U.H. DELIVERY CATE
NAME OF COURSE OF ACT	en 3/13/1	CI :3 Y X / C	1 1651016	018/18/19 2-5-01
Altra de la constanta de la co		120		
LUTZ		STATE ZIP	HIGH FEE BUANE	HOME SHOWE
SELLING DEALER NAME	4 /	ZONE DLA CODE	CITY	STATE
CHRYSLER REPRESENTATIVE - PRINT	Deelgy	20NE 71/2/2/	PHONE	MINOR REPAIR ESTIMATE
R.J. Falana	VSZ E.A	A. ORLANDO		MAJOR \$ /583.57
		INTERVI		
INTERVIEW WITH NAME BORIVER OWNER OTHER TRUS S		INTERVIEW DATE		OF INCIDENT INSPECTION DATE
DESCRIPTION OF EVENT (INCLUDING.	CHAUDUL WEATHER CONDITIONS AND		105/40/	8:30 = 05/601
		Sou	TACKER OF	
Driver's and/or occupant's description of incident				
What? When? Where?				
How? © Exact order of events				
O Did this happen before?				
Personal Inju	ry: Were there	Personal Injuries?	⊇ Yes XNo If yes, co	mplete section "L."
	IMPORTANT:	SHOW TO NO ONE	DRAW NO CONCLUSIO	ONS
COMMENT	• ATTACH A	NY ADDENDUMS TO F	PECIFIC ALLEGATIONS FOR EPORT AND STATE SECTION NTS AND WHO REMOVED IPMENT INSTALLED AND E	ON IT PERTAINS TO.
ALLEG. PHOTOGRAPI	H REQUIRED	INFOR	MATION	EVALUATION
from every corriboth original lat (8 total)	es (6 total) ged — perspective per of vehicle down eral sight lines.	Police report Vehicle service file Any reports/photos by others Location of inspection	☐ Driver's and/or occupant's description of incident ☐ What? When? Where? How? ☐ Exact order of events ☐ Did this happen before	
Send neg. & 2	эелэ от рипка			
Airbag(s) Steering Whee Airbag(s) Knee Blockers All posible bod All code readin	y contact areas gs using DR8 ii	Record: Was Airbag deployed? Driver Yes No Passenger Yes No Type of Steering Wheel Candition of Steering Wheel Condition of Steering Wheel	3	☐ Evidence of tampering or disassembly? / ☐ Yes ☐ No
		Mounting (measure column collapse)	DRB II READINGS. —	





the state of the s

CAIR #8636017 Attachment, Page 1 of 2. May 16, 2001.

Description Of Event:

The owner states that her husband had changed the oil the day before and that the hood latch had broke so they tied the hood down with a bungee cord. When she left the next morning for work she had driven up to approximately 20-25 MPH, and had traveled approximately 500 feet when the hood broke loose and flew up damaging the hood. No other vehicle was involved and no one was injured. She said she turned around and drove back home.

Additional Comments:

The vehicle was inspected at Ferman Collision Center in Tarpon Springs, Florida. Following are details of the inspection:

- The hood on the vehicle was badly damaged. Hinges on both sides were also damaged. However, there is no damage to the vehicle roof or windshield and the top of the hood is not scratched.
- The primary hood latch was found in the open position and ready to receive the hood portion of the latch. A screwdriver was used to test the latch by forcing it down to see if it would lock and it did operate as designed. Also, it released when the release lever was pulled in the inside of the cab.
- The secondary hood latch has been bent upward toward the under side of the hood and the secondary hood latch control lever was missing. The missing control lever was later found under the seat armrest inside the cab. The connector which connects the secondary hood latch to the hood latch control lever was still missing, however, it had scratches on it showing it was once connected to the lever. With this secondary hood latch bent upward into the hood it would have been impossible to close the hood completely.
- DRB tests were made as per the inspection request:

POWERTRAIN CONTROL MODULE INFORMATION

2001 BR 5.2L V8 SFI

MODULE: CAL 10.0 APR 28

NATURAL ASP, UNLEADED FUEL

FEDERAL/CANADIAN MODULE

AUTOMATIC TRANS, RW DRIVE

JEEP TRUCK ENGINE, JTEC+

NO ELECT FAN

PCM PART #: 56040269AB

HOMOLOGATION ID: RBYAA

EPA OBD VEHICLE

CAIR #8636017 Attachment, Page 2 of 2. May 16, 2001.

> - Results of DRB tests, continued: READ ENGINE DTC'S NO DTC'S DETECTED

STARTS SINCE CLEAR: 229

ABS SYSTEM
READ DTC'S
NO DTC'S DETECTED, was read in both the active and stored modes.

AIRBAG SYSTEM
READ DTC'S
NO DTC'S DETECTED, was read in both the active and stored modes.

Police Report: No police were involved.

Written Estimate Of Repair: Enclosed.

Photos: Two rolls of film were mailed this date.

DALMLERCHRYSLER

DaimlerChrysler Motors Corporation

May 18, 2001

Lutz, FL

Reference No.: 8636017 V.I.N.: 3B7HC13YX1G

Dear

This is in regards to the inspection that was performed on your vehicle on May 16, 2001, by a representative from Engineering Analysis Associates.

Naturally, we were sorry to learn of the incident. However, a review of our investigation does not lead us to believe that there was manufacturing responsibility associated with the incident. Therefore, we must respectfully decline any costs associated with this matter.

Thank you for allowing us the opportunity to review this with you.

Sincerely,

A. L. Gilbert Special Investigations (248) 944-7037

ALG/lls