

VIN	Non-Keyword Qualifier	Mileage
1G1YY26U275	U2100 U2106 U2108	4802
1G1YY26U475	ACTIVE HANDLING LAMP C0710	4838
1G1YY26U675	C0050 SYM00	7844
1G1YY26U275	ABS Light C0710 SYM00 SYM1A SYM1F	3707
1G1YY26U975	SERVICE ACTIVE HANDLING C0253 SYM00 C0196 SYM09	4307

Customer concern - The service stabilitrac, security light and the content theft light is on. The tech has duplicated the concern which is intermittent and he has history codes u2100, u2106, u2108 and he is asking for information on similar cases. Tac advised the tech of cases where BCMs were replaced for this concern. Tac also advised the tech of cases where ECMs and BPMVs were replaced for this concern and call back if further assistance is needed.

Active handling message . Tech states he has active handling message and can not duplicate concern . Tech states he has performed diagnostics and checks OK .-Tac found several cases for restringing harness to SWPS . Tac found no other bulletins or pi's related to concern H33

ABS light, traction light turns on.Dealer states:C0050 SYM00 is history in the EBCM. Dealer hasn't been able to duplicate the concern but the EBCM and rear right hub bearing were replaced but the concern is still present. The wiring resistance was inspected and the harnesses manipulated but the concern is still present. Dealer is to view Document ID# 1772083. Advised dealer to attempt to install a VDR by programming the VDR as a 2006 and note if information will record correctly. If so, dealer is to obtain one snapshot of the system working correctly, then install the VDR in for the customer on a DTC triggered centered snapshot and have the customer obtain a snapshot of the concern.

Customer states that the service active handling light comes on.C0710. Dealer states that there are symptoms are 00 and 1A. Dealer states that the SWPS was replaced on the last visit back in April. Dealer states that the concern is intermittent and has not been duplicated. Dealer states that no other parts have been replaced. TAC advised dealer of like cases for SWPS replacement as well as wiring and connection repairs. TAC advised dealer to manipulate the harness and see if the position signals start to fluctuate. TAC advised dealer to perform a pin drag test on all connections inline and repair as necessary.

Service active control light on and click Dealer reports he has code C0253 and C0196. Dealer reports the Yaw rate voltage is 4.98. Dealer was calling for advice and is also unable to locate the yaw sensor.Advised Dealer to review Document ID# 1772089 and Document ID# 1495673. Advised dealer to check power and ground to the yaw sensor and circuit 716 signal wire. Dealer to report results