



**Bendix Commercial Vehicle Systems LLC**  
901 Cleveland Street, Elyria, Ohio 44035  
Tel: 440.329.9000 • Fax: 440.329.9203

Rafael Dominguez  
Director - Product Safety  
Direct: 440/329-9386  
Fax: 440/329-9139

January 7, 2010

**VIA ELECTRONIC MAIL**  
Timothy.lafon@volvo.com

Mr. Tim LaFon  
Mack Trucks, Inc.  
7900 National Service Road  
PO Box 26115  
Greensboro, NC 27409

Re: **EA09-009**

Dear Tim,

This letter is to provide you with test findings of the Bendix valves you provided to us and requested to have inspected and tested from the field evaluation conducted the week of August 3, 2009.

Background Information

A team consisting of representatives from Mack, NHTSA, Bendix, Meritor and Haldex inspected 5 vehicles in Pennsylvania during the week of August 3, 2009. Various air brake components were removed from the vehicles for evaluation, including Bendix valves. The Bendix valves that were removed and required analysis were 3 MV-3, 5 E-8P and 1 R-14 (used to replace a Haldex relay valve).

Inspection/Test Results

The following tests were performed:

1. Valve operation according to the relevant Bendix specification for new E-8P, MV-3, and R-14.
2. Disassembly of all valves and inspection of seals.
3. Durometer analysis of o-Ring (of select components) and rubber spring of E-8P.

The criteria for Pass/Fail are part of the Bendix test specification and considered to be proprietary. If needed, Bendix can and will request Confidentiality (49 CFR Part 512) from NHTSA and submit the criteria directly to NHTSA.

**E-8P** – As noted in the table below, the valves performed within the parameters defined in the Bendix specification for new valves. Force versus delivery curves indicate normal operation. Ascending and descending hold pressures of 20, 40 and 60 psi (primary delivery) did not indicate any major shifts in delivery pressures.

Operational Test Results of the E-8P

<b>TEST PARAMETER</b>	<b>RESULT</b>
Leakage with 120 PSI at both primary & secondary supply and 0 PSI delivery pressure	PASS
Full Application leakage with 120 PSI at both primary & secondary supply	PASS
Dynamic Application Differential with 120 PSI at both primary & secondary supply	PASS
Primary Supply leakage with 80 psi delivery and 120 PSI at the supply	PASS
Secondary Supply leakage with 80 psi delivery and 120 PSI at the supply	PASS

The valves were disassembled and inspected for foreign contaminants, degradation of rubber seals, or damage to internal components. The rubber springs showed compression, which may have contributed to differential spike at low pressure. There were heavy impressions on the Inlet/Exhaust valves. Durometer readings indicate minimal difference from nominal values. Some oil was present in the valves, which possibly could be heat related.

**R-14** – As noted in the table below, initial test found the valve leaking between service cover and body; the valve did not meet all the parameters of the test specification. The cover was removed and the static o-ring was found to be pinched. The customer had replaced a Haldex relay valve with the Bendix R-14 valve. It was confirmed by a Bendix representative that the cover had been removed during its installation and its removal to retrieve fittings and this is likely how the o-ring was pinched. Also the assembly drawing calls out a 90° service port location, however the part was at 180° off location. This supports that the customer disassembled and re-assembled the unit. The o-ring was replaced with a new o-ring and the valve performed within the parameters defined in the Bendix specification for new valves. Operational and differential curves show that the valve functioned satisfactorily.

Operational Test Results of the R-14

<b>TEST PARAMETER</b>	<b>Results As Received</b>	<b>Results Replace O-ring</b>
Leakage with 120 PSI at supply and 0 PSI delivery pressure	PASS	PASS
Delivery with 120 PSI at supply and apply & release 120 PSI at balance port	PASS	PASS
Balance leakage with 120 PSI at supply and 10 PSI at balance port	PASS	PASS
Balance leakage with 0 PSI at supply and 120 PSI at balance port	PASS	PASS
Delivery with 120 PSI at supply and gradual increase to 120 PSI at delivery	NOT PASS	PASS
Supply leakage with 60 PSI at delivery and 120 PSI at the supply	NOT PASS	PASS
Supply leakage with 100 PSI at delivery and 120 PSI at the supply	NOT PASS	PASS
Delivery leakage with 0 PSI at supply and 120 PSI at delivery	NOT PASS	PASS

The valves were disassembled and inspected for foreign contaminants, degradation of rubber seals, or damage to internal components. There was heavy oil and grit contamination. The inlet/exhaust seat showed wear from the oil mix contamination.

**MV-3** –As noted in the table below, the valves did not perform within all the parameters defined in the new valve Bendix specification.

Operational Test Results of the MV-3

<b>TEST PARAMETER</b>	<b>RESULT CXN612- 1696</b>	<b>RESULT CXN612- 4367</b>	<b>RESULT CXN612- 4366</b>
With both buttons in, Delivery pressure build with no lag with 120 PSI at supply	PASS	PASS	PASS
Pull parking button out, Trailer supply button to also pop out	PASS	PASS	PASS
With both buttons in, pull Trailer supply button out, Parking button to remain pushed in.	PASS	PASS	PASS
120 PSI at primary supply port, secondary supply port open to atmosphere, push both buttons in, measure leakage at primary supply.	NOT PASS	NOT PASS	NOT PASS
With Trailer button in, bleed down supply, measure trip pressure.	PASS	PASS	PASS
With Parking button in, bleed down supply, measure trip pressure.	PASS	PASS	PASS
With Trailer button held in, bleed down supply, delivery must exhaust.	PASS	NOT PASS	NOT PASS
Supply pressure at both primary and secondary supply, push Trailer button in, bleed down primary supply to verify double check valve function.	PASS	PASS	PASS
Primary supply open to atmosphere, secondary supply with pressure, both buttons out, measure leakage at secondary supply.	PASS	PASS	PASS

The valves were disassembled and inspected for foreign contaminants, degradation of rubber seals, or damage to internal components. The double check valve on all three valves were contaminated with oil and damaged in one valve (...1696). This caused the leakage in the “buttons in” test. When the damaged double check valve was replaced in the one valve (...1696), the valve passed all performance requirements. The exhaust seal of the tractor plunger was contaminated and damaged in two of the valves (...4367 & 4366). Material analysis determined that the substance found on the o-rings and exhaust seal was a mixture of the standard Bendix grease, water and an alcohol. The durometer of several o-rings was found to be under specification, which may have contributed to the Buttons In leakage results.

**Comments:**

With the exception of the MV-3, all devices performed within the tolerances allowed in the respective Bendix specifications for new valves. The E-8P valves required extra travel to apply compared to the new valve specifications. This is consistent with the results expected of valves with compressed graduation springs (rubber springs). The measured compression is not necessarily beyond what is expected of products that have been on in-service vehicles for this length of time. As noted above, the R-14 was disassembled at the inspection site and not properly re-assembled, which resulted in a pinched o-ring. After replacing the o-ring the valve met all the new valve specifications.

With respect to the MV-3 valves evaluated, the valves did not meet the new valves specifications for leakage with both buttons pushed in and there was contamination found in all valves. As stated, material analysis will be conducted on the contamination.

Note: None of the vehicles had complaints concerning the parking brake system, as the vehicles were in service at the time of the inspection.

Should you have any further questions or concerns, please contact me at 440/329-9386.

Best Regards,

A handwritten signature in cursive script that reads "Rafael Dominguez". The signature is written in black ink and includes a long horizontal flourish at the end.

Rafael Dominguez  
Director Product Safety

Cc: Jim Szudy – Bendix CVS

**Appendix 1 – E8-P**

E-8P – Unit CXN612-4367

Secondary Inlet/Exhaust Valve



Secondary Body Cavity



Secondary Piston



Plunger Side Cavity




Primary Plunger



Rubber Spring



Primary Cavity



Primary Inlet/Exhaust Valve



E-8P – Unit CXN612-1696

Secondary Inlet/Exhaust Valve



Secondary Body Cavity



Secondary Piston



Plunger Side Cavity



Primary Plunger



Rubber Spring



Primary Inlet/Exhaust Valve



Secondary Inlet/Exhaust Valve




Secondary Body Cavity




Secondary Piston



Top View of plunger and rubber spring washer



Plunger Side Cavity



Primary Plunger



Rubber Spring



Primary Inlet/Exhaust Valve



Internal Oil Wetness



**APPENDIX 2 – R-14**

**R-14 – Unit CXN612-1696**



As received, found no part number or date code on body. OE label 5012296. Assembly drawing calls out a 5013270 with a 90° service port location. Photo shows the service port is 180° off location. Thus, customer may have disassembled and assembled unit.




Photo shows that the exhaust cover was not disassembled.



The cover bolts with fresh wrench markings indication of disassemble.



Initial bench test blow leakage found static o-ring pinched. Again, indication of improper re-assembly by customer. Note that a new o-ring was installed so to complete the evaluation.



Excessive oil mix grit contamination on top of the control piston.



Excessive oil contamination inside the service quick release cavity



The quick release diaphragm appears normal. Light cupping.



Excess oil residue inside service cap port area.



Exhaust inlet cavity shows less contaminates. Lacking grease.




I/E valve OD surface lacks grease.



I/E valve seat shows excessive wear from oil mix grit contaminates.




Control piston's delivery side shows excessive oil and grit contaminates.



The control piston's delivery side, below the seat, has a tacky like oil residue.



The piston o-ring groove area shows oil contaminates residue.



The body's delivery cavity shows oil grit contaminates.

**APPENDIX 3 – MV-3**

MV-3 – Unit CXN612-1696

Separation Cover



Trailer Plunger



Crude on Overdrive



Double Check Valve



Double Check Valve



Double Check Valve



Side View



Override Spring



Tractor Plunger – dry o-ring



Tractor exhaust seal – dry o-ring



MV-3 – Unit CXN612-4367

Tractor exhaust seal




Tractor exhaust seal



Trailer exhaust seal



Double check valve



Double check valve



Double check valve bore – oil



Tractor exhaust seal



Tractor exhaust seal



Tractor exhaust seal



Trailer exhaust seal

