

U.S. Department of Transportation

National Highway Traffic Safety Administration

ODI RESUME

Investigation: PE 10-017
Date Opened: 05/14/2010
Principal Investigator: Michael Lee

Subject: Driver's Frontal Air Bag Wiring Failure

MANUFACTURER & PRODUCT INFORMATION

Manufacturer: MERCEDES-BENZ USA, LLC.

Products: 2005-2006 Mercedes-Benz E-Class

Population: 100,000 (Estimated)

Problem Description: The steering column wiring harness containing the wiring to the driver's frontal air bag

module may be too short for telescopic movement of the column. The wire ends may

pull out of the connector block causing an open in the driver air bag circuits.

FAILURE REPORT SUMMARY

	ODI	Manufacturer	Total
Complaints:	4	TBD	TBD
Crashes/Fires:	0	TBD	TBD
Injury Incidents:	0	TBD	TBD
Fatality Incidents:	0	TBD	TBD

ACTION / SUMMARY INFORMATION

Action: Open a Preliminary Evaluation.

Summary:

ODI has received four complaints of steering column module wiring harness failures on MY 2005-2006 Mercedes-Benz E-Class vehicles. In December 2005, Mercedes-Benz USA issued a technical service bulletin (TSB No. P-B-91.60/99) and subsequently issued several minor revisions to the original TSB. The TSBs address reports of air bag warning lamp illumination accompanied by a diagnostic fault code 9103 or 9123 indicating a high resistance in the driver's frontal air bag ignition squib 1 or 2 (the air bag firing circuits), respectively. This condition may result in failure of the driver's first stage and/or second stage inflator to deploy in the event of an above deployment threshold frontal crash. According to the TSBs, the repair involves significant lengthening of the steering column module wiring harness by cutting and splicing each wire in the harness. Thus, it appears possible that the wire ends in the original, shorter harness could pull out of the connector block thereby causing an open-circuit condition in the driver's air bag circuits. Additionally, the TSBs cover MY 2003-2009 E-Class and MY 2006-2010 CLS-Class vehicles. Although ODI has not received complaints involving all of these vehicles, ODI will inquire about all vehicles covered by the above TSBs.

Investigation: PE 10-017 Open Resume Page 1 of 1