



AUTO ALLIANCE
DRIVING INNOVATION®

President and CEO

November 12, 2014

Ms. Jennifer Timian
Chief, Recall Management Division
Office of Defects Investigation
Enforcement
National Highway Traffic Safety Administration
1200 New Jersey Avenue, S.E.
Washington, DC 20590

Dear Ms. Timian:

Re.: AQ10-001, Audit of Rental Car Safety Recall Campaign Completion

Ref.: [1] Your letters dated October 14, 2014 (INIM-AQ10001-60381 through 60389); same subject

[2] My letter dated October 28, 2014; same subject

Further to my letter dated October 28, 2014, the purpose of this letter is to provide a copy of the final analysis of publicly available safety recall data for light passenger vehicles commissioned by the Alliance. A copy of the completed analysis is enclosed. This analysis is being provided to assist the agency in its evaluation of the Alliance's legislative proposal for remedying rental cars subject to a safety recall.

Specifically, the enclosed analysis identifies those safety recalls involving light passenger vehicles that were conducted during the 14-year-period of 2000 through 2013. Each of the safety recalls identified were analyzed in order to classify them according to whether any pre-remedy precautionary advice was given to owners of the affected vehicles.

In total, over 2,100 recalls were reviewed. The analysis was performed by gathering and analyzing the Defect Information Reports required to be submitted to the agency pursuant to 49 C.F.R. Part 573 and the Owner Notification Letters required under 49 C.F.R. Part 577 that were submitted to NHTSA for review and approval prior to issuance. All of this information was obtained via the agency's website, www.safercar.gov.

ALLIANCE OF AUTOMOBILE MANUFACTURERS, INC.

BMW Group • Chrysler Group LLC • Ford Motor Company • General Motors Company • Jaguar Land Rover •

Mazda • Mercedes-Benz USA • Mitsubishi Motors • Porsche • Toyota • Volkswagen • Volvo

803 7th Street N.W, Suite 300, Washington, DC 20001 • Phone 202.326.5500 • Fax 202.326.5567 •

www.autoalliance.org

The recalls conducted during the subject period were also analyzed to determine if they were conducted nationally or regionally.

The findings from this analysis are:

- During this period, an average of 150 safety recalls involving light passenger vehicles were conducted annually.
- On average, approximately 20 percent (20%) of these safety recalls included owners being given pre-remedy precautionary “do not drive” or risk mitigation advice. Specifically:
 - 5 percent (5%) of the safety recalls conducted included advice to owners to stop driving the affected vehicle if the occurrence of certain condition(s) is observed before the defect or noncompliance is remedied (“conditional ‘do not drive’ advice”);
 - 1 percent (1%) of the safety recalls conducted included advice to owners to stop driving the affected vehicle before the defect or noncompliance is remedied (“unconditional ‘do not drive’ advice”); and
 - 13 percent (13%) of the safety recalls conducted included advice that owners should take, before the defect or noncompliance is remedied, to reduce the chance that the malfunction for which the vehicle is being recalled will occur (“risk mitigation advice”).
- On average, approximately 3 percent (3%) of the safety recalls conducted during this period were conducted regionally as opposed to nationally.

If you have any questions regarding the Alliance’s analysis, or would like to discuss this matter further, please do not hesitate to contact me or Rob Strassburger of my staff.

Sincerely,

ALLIANCE OF AUTOMOBILE MANUFACTURERS, INC.



Mitch Bainwol

Enclosure


Analysis of Light Passenger Vehicle Recalls, 2000–2013

Alliance of Automobile Manufacturers, Inc.

November 12, 2014


Analysis of Light Passenger Vehicle Recalls, 2000–2013

Number of Recalls in Which “Do Not Drive” or Risk Mitigation Advice Given




Analysis of Light Passenger Vehicle Recalls, 2000–2013

Average Percentage of Recalls in Which “Do Not Drive” or Risk Mitigation Advice Given



Analysis of Light Passenger Vehicle Recalls, 2000–2013

Average Percentage of Regional Recalls



Analysis of Light Passenger Vehicle Recalls, 2000–2013

“Do Not Drive” or Risk Mitigation Advice Given

Definitions

“Do Not Drive” Advice – Unconditional: Pre–remedy precautionary advice to owners to stop driving the vehicle before the defect or noncompliance is remedied

“Do Not Drive” Advice – Conditional: Pre–remedy precautionary advice to owners to stop driving the vehicle if the occurrence of certain condition(s) is observed before the defect or noncompliance is remedied

Risk Mitigation Advice: Pre–remedy precautionary advice that owners should take, before the defect or noncompliance is remedied, to reduce the chance that the malfunction for which the vehicle is being recalled will occur

Analysis of Light Passenger Vehicle Recalls, 2000–2013

“Do Not Drive” or Risk Mitigation Advice Given

Data Table

Recall Type	2000	2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	Total	Average	
	(#)	(#)	(#)	(#)	(#)	(#)	(#)	(#)	(#)	(#)	(#)	(#)	(#)	(#)	(#)	(#)	(%)
Do Not Drive (DND) Recalls																	
Conditional Advice	13	9	8	1	6	3	3	1	4	6	11	11	8	15	99	7	5%
Unconditional Advice	1	2	2	2	2	3	0	0	0	1	1	1	3	1	19	1	1%
No Supplemental Advice Given	205	145	118	161	213	135	100	95	103	102	146	123	159	181	1986	142	94%
Subtotal	219	156	128	164	221	141	103	96	107	109	158	135	170	197	2104	150	100%
Risk Mitigation Recalls																	
Advice Given	35	41	30	20	33	32	14	17	19	26	34	22	32	39	394	28	19%
No Supplemental Advice Given	184	115	98	144	188	109	89	79	88	83	124	113	138	158	1710	122	81%
Subtotal	219	156	128	164	221	141	103	96	107	109	158	135	170	197	2104	150	100%
Regional Recalls																	
Regional Recalls	3	6	2	3	2	2	2	8	4	8	8	3	11	9	71	5	3%
National Recalls	216	150	126	161	219	139	101	88	103	101	150	132	159	188	2033	145	97%
Subtotal	219	156	128	164	221	141	103	96	107	109	158	135	170	197	2104	150	100%
Summary Statistics																	
"Do Not Drive (DND)" - Conditional Advice	13	9	8	1	6	3	3	1	4	6	11	11	8	15	99	7	5%
"Do Not Drive (DND)" - Unconditional Advice	1	2	2	2	2	3	0	0	0	1	1	1	3	1	19	1	1%
Risk Mitigation Advice Given; Other than DND	21	30	20	17	25	26	11	16	15	19	22	10	21	23	276	19	13%
No Supplemental Advice of Any Kind Given	184	115	98	144	188	109	89	79	88	83	124	113	138	158	1710	117	81%
TOTAL Light Vehicle Recalls	219	156	128	164	221	141	103	96	107	109	158	135	170	197	2104	144	100%

Source: Derived from data available at <http://www.safercar.gov>

Source: Derived from data available at <http://www.safercar.gov>

Light Passenger Vehicle Recall Analysis
Do Not Drive, Risk Mitigation Instructions, Regional
2000 to 2013

Executive Summary

Light Passenger Vehicle Recalls from 2000 through 2013 were analyzed to determine the number of regional recalls in each year and to determine the number of recalls that had (in the part 577 letter from Manufacturers to Owners) do not drive instructions and risk mitigation instructions. The detailed text of the instructions and the regional information are available in the appendices. The table below summarizes the findings of this analysis.

	2013	2012	2011	2010	2009	2008	2007	2006	2005	2004	2003	2002	2001	2000
Recall Type														
Conditional DND	15	8	11	11	6	4	1	3	3	6	1	8	9	13
Unconditional DND	1	3	1	1	1	0	0	0	3	2	2	2	2	1
RMI excluding DND	23	21	10	22	19	15	16	11	26	26	17	20	30	21
Neither RMI nor DND	158	138	113	124	83	90	78	89	109	187	144	98	115	184
Subtotal	197	170	135	158	109	109	95	103	141	221	164	128	156	219
Regional	9	11	3	8	12	3	6	2	2	2	3	2	6	3
Not Regional	188	159	132	150	97	106	89	101	139	219	161	126	150	216
Subtotal	197	170	135	158	109	109	95	103	141	221	164	128	156	219

Table 1. Summary of findings

TABLE OF CONTENTS

Executive Summary	1
Table of Contents	2
Introduction	3
Do Not Drive LPV Recall Charts	4
Risk Mitigation LPV Recall Charts	18
Regional LPV Recall Charts	31
Appendix A – Do Not Drive Recall Instructions	39
Appendix B – Risk Mitigation Recall Instructions	64
Appendix C – Regional Recall Information	145

INTRODUCTION

This report identifies and quantifies the number of Light Passenger Vehicle recalls from 2000 through 2013 that:

1. Specify that the owner should not drive the vehicle until it has been remedied
2. Provide instructions for mitigating the safety risk prior to the vehicle being remedied
3. Identify and quantify regional recalls

To conduct this analysis we gathered, culled and analyzed the 2000 through 2013 Part 573 and Part 577 letters submitted by manufacturers related to recalls of LPV's. The data gathered, culled, analyzed and provided in this report comes from manufacturers submissions to NHTSA. Information used for this report was accessed through www.safercar.gov

Do Not Drive (DND) LPV Recalls

2013 DND LPV Recalls.

Sixteen (16) of the one hundred ninety seven (197) 2013 LPV recalls contained DND instructions. Fifteen (15) of those DND instructions were conditional. Fourteen (14) of these recalls with DND instructions were upon owner detection of a defect and one (13V194) if the owner preferred not to operate until repairs were completed. Only one recall (13V103) had an unconditional “do not drive” vehicle instruction. In the graph in figure 1 this single recall is counted and categorized as a recall with “unconditional” DND instructions. For the text detailing the DND instructions for the 2013 LPV recalls see Appendix A-1.




Figure 1. 2013 LPV Recalls with Do Not Drive Instructions

2012 DND LPV Recalls.

Eleven (11) of the one hundred seventy (170) 2012 LPV recalls contained DND instructions. Eight (8) of those DND instructions were conditional upon owner detection of a defect. Three recalls (12v336, 12v475, and 12v504) had unconditional “do not drive” recommendations. In the graph in figure 2 these three recalls are counted and categorized as recalls with “unconditional” DND instructions. For the text detailing the DND instructions for the 2012 LPV recalls see Appendix A-2.




Figure 2. 2012 LPV Recalls with Do Not Drive Instructions

2011 DND LPV Recalls.

Twelve (12) of the one hundred thirty five (135) 2011 LPV recalls contained DND instructions. Eleven (11) of those DND instructions were conditional upon owner detection of a defect (if you notice fluid leaks, or loss of power, or your engine stalls, etc..., then do not drive the vehicle). Only one recall (11v007) had an unconditional “do not drive” vehicle recommendation. In the graph in figure 3 this single recall is counted and categorized as a recall with “unconditional” DND instructions. For the text detailing the DND instructions for the 2011 LPV recalls see Appendix A-3.




Figure 3. 2011 LPV Recalls with Do Not Drive Instructions

2010 DND LPV recalls.

Twelve (12) of the one hundred fifty eight (158) 2010 LPV recalls contained “do not drive” (DND) instructions. Eleven (11) of those DND instructions were conditional upon owner detection of a defect (if you notice fluid leaks, or loss of power, or your engine stalls, etc..., then do not drive the vehicle). Only one recall (10v643) had an unconditional “do not drive” vehicle recommendation. In the graph in figure 4 this single recall is counted and categorized as a recall with “unconditional” DND instructions. For the text detailing the DND instructions for the 2011 LPV recalls see Appendix A-4.




Figure 4. 2010 LPV Recalls with Do Not Drive Instructions

2009 DND LPV Recalls.

Seven (7) of the one hundred nine (109) 2009 LPV recalls contained DND instructions. Six (6) of those DND instructions were conditional upon owner detection of a defect. Only one recall (09V155) had an unconditional “do not drive” vehicle recommendation. In the graph in figure 5 this single recall is counted and categorized as a recall with “unconditional” DND instructions. For the text detailing the DND instructions for the 2009 LPV recalls see Appendix A-5.




Figure 5. 2009 LPV Recalls with Do Not Drive Instructions

2008 DND LPV Recalls.

Four (4) of the one hundred thirty five (107) 2008 LPV recalls contained DND instructions. All of those DND instructions were conditional upon owner detection of a defect. No recalls had an unconditional “do not drive” vehicle recommendation. Figure 6 shows the number of 2008 LPV recalls that had DND instructions. For the text detailing the DND instructions for the 2008 LPV recalls see Appendix A-6.




Figure 6. 2008 LPV Recalls with Do Not Drive Instructions

2007 DND LPV Recalls.

One (1) of the ninety six (96) 2007 LPV recalls contained DND instructions. No recalls had an unconditional “do not drive” vehicle recommendation. Figure 7 shows the number of 2007 LPV recalls that had DND instructions. For the text detailing the DND instructions for the 2007 LPV recall see Appendix A-7.




Figure 7. 2007 LPV Recalls with Do Not Drive Instructions

2006 DND LPV Recalls.

Three (3) of the one hundred three (103) 2006 LPV recalls contained DND instructions. All of those DND instructions were conditional upon owner detection of a defect. No recalls had an unconditional “do not drive” vehicle recommendation. Figure 8 shows the number of 2006 LPV recalls that had DND instructions. For the text detailing the DND instructions for the 2006 LPV recalls see Appendix A-8.




Figure 8. 2006 LPV Recalls with Do Not Drive Instructions

2005 DND LPV Recalls.

Six (6) of the one hundred forty one (141) 2005 LPV recalls contained DND instructions. Three (3) of those DND instructions were conditional upon owner detection of a defect. Three (3) recalls had an unconditional “do not drive” vehicle recommendation. In the graph in figure 9 these three recalls are counted and categorized as recalls with “unconditional” DND instructions. For the text detailing the DND instructions for the 2005 LPV recalls see Appendix A-9.




Figure 9. 2005 LPV Recalls with Do Not Drive Instructions

2004 DND LPV Recalls.

Eight (8) of the two hundred twenty one (221) 2004 LPV recalls contained DND instructions. Five (6) of those DND instructions were conditional upon owner detection of a defect. Two (2) recalls had an unconditional “do not drive” vehicle recommendation. In the graph in figure10 these two recalls are counted and categorized as recalls with “unconditional” DND instructions. For the text detailing the DND instructions for the 2004 LPV recalls see Appendix A-10.




Figure 10. 2004 LPV Recalls with Do Not Drive Instructions

2003 DND LPV Recalls.

Three (3) of the one hundred sixty four (164) 2003 LPV recalls contained DND instructions. One (1) of those DND instructions was conditional upon owner detection of a defect. Two (2) recalls had an unconditional “do not drive” vehicle recommendation. In the graph in figure 11 these two recalls are counted and categorized as recalls with “unconditional” DND instructions. For the text detailing the DND instructions for the 2003 LPV recalls see Appendix A-11.




Figure 11. 2003 LPV Recalls with Do Not Drive Instructions

2002 DND LPV Recalls.

Ten (10) of the one hundred twenty eight (128) 2002 LPV recalls contained DND instructions. Eight (8) of those DND instructions were conditional upon owner detection of a defect. Two (2) recalls had an unconditional “do not drive” vehicle recommendation. In the graph in figure 12 these two recalls are counted and categorized as recalls with “unconditional” DND instructions. For the text detailing the DND instructions for the 2002 LPV recalls see Appendix A-12.




Figure 12. 2002 LPV Recalls with Do Not Drive Instructions

2001 DND LPV Recalls.

Eleven (11) of the one hundred fifty six (156) 2001 LPV recalls contained DND instructions. Nine (9) of those DND instructions were conditional upon owner detection of a defect. Two (2) recalls had an unconditional “do not drive” vehicle recommendation. In the graph in figure 13 these two recalls are counted and categorized as recalls with “unconditional” DND instructions. For the text detailing the DND instructions for the 2001 LPV recalls see Appendix A-13.




Figure 13. 2001 LPV Recalls with Do Not Drive Instructions

2000 DND LPV Recalls.

Fourteen (14) of the two hundred nineteen (219) 2000 LPV recalls contained DND instructions. Thirteen (13) of those DND instructions were conditional upon owner detection of a defect. One (1) recall had an unconditional “do not drive” vehicle recommendation. In the graph in figure 14 this recall is counted and categorized as a recall with “unconditional” DND instructions. For the text detailing the DND instructions for the 2001 LPV recalls see Appendix A-14.




Figure 14. 2000 LPV Recalls with Do Not Drive Instructions

Risk Mitigation Instructions

2013 Risk Mitigation Instructions.

We identified thirty nine (39) of one hundred ninety seven (197) 2013 LPV recalls that included risk mitigation instructions. This includes the sixteen (16) recalls with DND instructions as DND instructions are also risk mitigation instructions. For the text detailing the risk mitigation instructions from the part 577 letters of the 2013 LPV recalls see Appendix B-1.




Figure 15. 2013 LPV Recalls with Risk Mitigation Instructions

2012 Risk Mitigation Instructions.

We identified thirty two (32) of one hundred seventy (170) 2012 LPV recalls that included risk mitigation instructions. This includes the eleven (11) recalls with DND instructions as DND instructions are also risk mitigation instructions. For the text detailing the risk mitigation instructions from the part 577 letters of the 2012 LPV recalls see Appendix B-2.




Figure 16. 2012 LPV Recalls with Risk Mitigation Instructions

2011 Risk Mitigation Instructions.

We identified twenty two (22) of one hundred thirty five (135) 2011 LPV recalls that included risk mitigation instructions. This includes the twelve (12) recalls with DND instructions as DND instructions are also risk mitigation instructions. For the text detailing the risk mitigation instructions from the part 577 letters of the 2011 LPV recalls see Appendix B-3.




Figure 17. 2011 LPV Recalls with Risk Mitigation Instructions

2010 Risk Mitigation Instructions.

We identified thirty four (34) of one hundred fifty eight (158) 2010 LPV recalls that included risk mitigation instructions. This includes the twelve (12) recalls with DND instructions as DND instructions are also risk mitigation instructions. For the text detailing the risk mitigation instructions from the part 577 letters of the 2010 LPV recalls see Appendix B-4.




Figure 18. 2010 LPV Recalls with Risk Mitigation Instructions

2009 Risk Mitigation Instructions.

We identified twenty six (26) of one hundred nine (109) 2009 LPV recalls that included risk mitigation instructions. This includes the seven (7) recalls with DND instructions as DND instructions are also risk mitigation instructions. For the text detailing the risk mitigation instructions from the part 577 letters of the 2009 LPV recalls see Appendix B-5.




Figure 19. 2009 LPV Recalls with Risk Mitigation Instructions

2008 Risk Mitigation Instructions.

We identified nineteen (19) of one hundred seven (107) 2008 LPV recalls that included risk mitigation instructions. This includes the four (4) recalls with DND instructions as DND instructions are also risk mitigation instructions. For the text detailing the risk mitigation instructions from the part 577 letters of the 2008 LPV recalls see Appendix B-6.




Figure 20. 2008 LPV Recalls with Risk Mitigation Instructions

2007 Risk Mitigation Instructions.

We identified seventeen (17) of ninety six (96) 2007 LPV recalls that included risk mitigation instructions. This includes the one (1) recall with DND instructions as DND instructions are also risk mitigation instructions. For the text detailing the risk mitigation instructions from the part 577 letters of the 2007 LPV recalls see Appendix B-7.




Figure 21. 2007 LPV Recalls with Risk Mitigation Instructions

2006 Risk Mitigation Instructions.

We identified fourteen (14) of one hundred three (103) 2006 LPV recalls that included risk mitigation instructions. This includes the three (3) recalls with DND instructions as DND instructions are also risk mitigation instructions. For the text detailing the risk mitigation instructions from the part 577 letters of the 2006 LPV recalls see Appendix B-8.




Figure 22. 2006 LPV Recalls with Risk Mitigation Instructions

2005 Risk Mitigation Instructions.

We identified thirty two (32) of one hundred forty one (141) 2005 LPV recalls that included risk mitigation instructions. This includes the six (6) recalls with DND instructions as DND instructions are also risk mitigation instructions. For the text detailing the risk mitigation instructions from the part 577 letters of the 2005 LPV recalls see Appendix B-9.




Figure 23. 2005 LPV Recalls with Risk Mitigation Instructions

2004 Risk Mitigation Instructions.

We identified thirty three (33) of two hundred twenty one (221) 2004 LPV recalls that included risk mitigation instructions. This includes the seven (7) recalls with DND instructions as DND instructions are also risk mitigation instructions. For the text detailing the risk mitigation instructions from the part 577 letters of the 2004 LPV recalls see Appendix B-10.




Figure 24. 2004 LPV Recalls with Risk Mitigation Instructions

2003 Risk Mitigation Instructions.

We identified twenty (20) of one hundred sixty four (164) 2003 LPV recalls that included risk mitigation instructions. This includes the three (3) recalls with DND instructions as DND instructions are also risk mitigation instructions. For the text detailing the risk mitigation instructions from the part 577 letters of the 2003 LPV recalls see Appendix B-11.




Figure 25. 2003 LPV Recalls with Risk Mitigation Instructions

2002 Risk Mitigation Instructions.

We identified thirty (30) of one hundred twenty eight (128) 2002 LPV recalls that included risk mitigation instructions. This includes the ten (10) recalls with DND instructions as DND instructions are also risk mitigation instructions. For the text detailing the risk mitigation instructions from the part 577 letters of the 2002 LPV recalls see Appendix B-12.




Figure 26. 2002 LPV Recalls with Risk Mitigation Instructions

2001 Risk Mitigation Instructions.

We identified forty one (41) of one hundred fifty six (156) 2001 LPV recalls that included risk mitigation instructions. This includes the eleven (11) recalls with DND instructions as DND instructions are also risk mitigation instructions. For the text detailing the risk mitigation instructions from the part 577 letters of the 2001 LPV recalls see Appendix B-13.




Figure 27. 2001 LPV Recalls with Risk Mitigation Instructions

2000 Risk Mitigation Instructions.

We identified thirty five (35) of two hundred nineteen (219) 2000 LPV recalls that included risk mitigation instructions. This includes the fourteen (14) recalls with DND instructions as DND instructions are also risk mitigation instructions. For the text detailing the risk mitigation instructions from the part 577 letters of the 2000 LPV recalls see Appendix B-14.




Figure 28. 2000 LPV Recalls with Risk Mitigation Instructions

Regional Recalls

2013 Regional Recalls.

We identified nine (9) regional recalls of the one hundred ninety seven (197) light passenger vehicle recalls for 2013. They are 13V081, 13V385, 13V093, 13V354, 13V556, 13V547, 13V550, 13V541, 13V110. See Appendix C-1.




Figure 29. 2013 LPV Regional Recalls

2012 Regional Recalls.

We identified 11 regional recalls of the 170 light passenger vehicle recalls for 2012. They are 12V085, 12V151, 12V193, 12V194, 12V195, 12V306, 12V388, 12V406, 12V459, 12V542, and 12V597. See Appendix C-2.




Figure 30. 2012 LPV Regional Recalls

2011 Regional Recalls. We identified 3 regional recalls of the 135 light passenger vehicle recalls for 2011. They are 11v030, 11v244, and 11v464. See Appendix C-3.




Figure 31. 2011 LPV Regional Recalls

2010 Regional Recalls.

We identified 8 regional recalls of the 158 light passenger vehicle recalls for 2010. They are 10v007, 10v008, 10v065, 10v105, 10v160, 10v385, 10v436, and 10v457. See Appendix C-4.




Figure 32. 2010 LPV Regional Recalls

2009 Regional Recalls. We identified 12 regional recalls of the 109 light passenger vehicle recalls for 2009. They are 09V123, 09v124, 09v125, 09v183, 09v310, 09v338, 09v392, 09v393, 09v419, 09v444, 09v468, and 09v483. See Appendix C-5.




Figure 33. 2009 LPV Regional Recalls

2008 Regional Recalls. We identified 3 regional recalls of the 109 light passenger vehicle recalls for 2008. They are 08V094, 08V410, and 08V690. See Appendix C-6.




Figure 34. 2008 LPV Regional Recalls

2007 Regional Recalls. We identified 6 regional recalls of the 95 light passenger vehicle recalls for 2007. They are 07v152, 07v197, 07v328, 07v349, 07v435, 07v549. See Appendix C-7.




Figure 35. 2007 LPV Regional Recalls

2006 Regional Recalls. We identified 2 regional recalls of the 135 light passenger vehicle recalls for 2011. They are 06V383 and 06V463. See Appendix C-8.




Figure 36. 2006 LPV Regional Recalls

2005 Regional Recalls. We identified 2 regional recalls of the 135 light passenger vehicle recalls for 2005. They are 05V300 and 05V385. See Appendix C-9.




Figure 37. 2005 LPV Regional Recalls

2004 Regional Recalls. We identified 2 regional recalls of the 221 light passenger vehicle recalls for 2004. They are 04V332 and 04V495. See Appendix C-10.




Figure 38. 2004 LPV Regional Recalls

2003 Regional Recalls. We identified 3 regional recalls of the 164 light passenger vehicle recalls for 2003. They are 03V153, 03V232, and 03V251. See Appendix C-11.




Figure 39. 2005 LPV Regional Recalls

2002 Regional Recalls. We identified 2 regional recalls of the 128 light passenger vehicle recalls for 2002. They are 02V101 and 02V341. See Appendix C-12.




Figure 40. 2002 LPV Regional Recalls

2001 Regional Recalls. We identified 6 regional recalls of the 156 light passenger vehicle recalls for 2001. They are 01V040, 01V068, 01V199, 01V200, 01V255, 01V306. See Appendix C-13.




Figure 41. 2001 LPV Regional Recalls

2000 Regional Recalls. We identified 3 regional recall of the 219 light passenger vehicle recalls for 2000. They are 00V063, 00V189, 00V256. See Appendix C-14.




Figure 42. 2000 LPV Regional Recalls

Appendix A-1

2013 Recalls with do not drive instructions from manufacturer to owner

The text for each recall in this appendix is taken from Owner Notification Letters (Part 577).

13V017

If this condition occurs while driving, your vehicle will lose power. If this happens, carefully move away from traffic and pull over to a safe location; **do not continue to drive your vehicle**. Contact BMW ActiveE Roadside Assistance at 1-800-497-9940 immediately to have your vehicle brought to the nearest authorized BMW ActiveE center.

13V031

If your vehicle's brake warning light illuminates and the brake warning buzzer is heard, do not drive your vehicle.

13V041

If an oil cooler line failure occurs the driver may observe one or more of the following warning signs:

- (1) Oil pressure warning light illuminated whilst the engine is running;
- (2) Signs of oil under the front or rear of the vehicle whilst the vehicle is parked;
- (3) Excessive oil consumption;
- (4) Trail of oil on the road;

If you observe any of the above before driving, **do not drive the car** and contact your Lotus dealer.

13V044

If you notice a momentary flickering of the display in the instrument cluster during driving or a momentary (less than one second) engine shutdown, carefully move away from traffic and pull over to a safe location as soon as possible. **Do not continue to drive your vehicle**. Contact BMW Roadside Assistance at 1-800-332-4269 immediately to have your vehicle brought to the nearest authorized BMW center.

13V045

IN THE EVENT YOU NOTICE A DECREASE OF POWER BRAKE ASSIST, **DO NOT CONTINUE TO DRIVE YOUR VEHICLE**. Carefully move away from traffic and pull over to a safe location as soon as possible. Contact BMW Roadside Assistance at 1-800-332-4269 to have your vehicle brought to the nearest authorized BMW center.

13V077

If you notice that the moonroof glass is loose, **do not operate the vehicle**. Immediately contact your Subaru dealer for assistance.

13V078

If you notice or smell smoke in the front cowl area of the vehicle, be sure the ignition switch is in the “off” position and do not operate the vehicle. Immediately contact your Subaru dealer for assistance.

13V103

Contact your nearest Chrysler, Jeep, or Dodge dealer immediately to have your vehicle battery disconnected. **Discontinue driving your vehicle.**

13V110

If you notice fluid leaking from the vehicle, **do not operate the vehicle.** Immediately contact your Subaru dealer for assistance.

If the brake system warning light remains illuminated on the instrument panel with the parking brake fully released, **do not operate the vehicle.** Immediately contact your Subaru dealer for assistance.

13V114

If your brake lights are not working properly, you may request that your vehicle be towed to the nearest Kia dealer at no cost to you by phoning Kia Roadside Assistance at (800)-333-4KIA (4252).

13V139

If you hear a noticeable noise or feel a vibration from the front wheels, stop driving your vehicle and contact your dealer as soon as possible to have the vehicle inspected.

13V194

If you prefer not to operate your vehicle until repairs are made, please contact your nearest Subaru dealer to make arrangements to **have your vehicle towed** to that dealer at no cost to you.

13V430

If the MIL is illuminated, contact your Infiniti retailer immediately and it will make arrangements for an immediate repair. **Do not continue using your vehicle** with the MIL illuminated.

13V451

If you notice that the Brake Warning Light in your Titan is illuminated, we strongly urge you to contact your Nissan dealer and bring your vehicle in for inspection as soon as possible. **Do not continue driving** with the Brake Warning Light on.

13V454

If you notice a decrease of power brake assist, **do not continue to drive your vehicle.** Carefully move away from traffic and pull over to a safe location as soon as possible.

Contact BMW Roadside Assistance at 1-800-332-4269 to have your vehicle brought to the nearest authorized BMW center.

13V550

If your vehicle is experiencing directional control issues (wobbling), contact Kia Roadside Assistance directly at 800-333-4542(4Kia) to **request a tow** to the nearest Kia dealer for repair.

Appendix A-2

2012 Recalls with do not drive instructions from manufacturer to owner

The text for each recall in this appendix is taken from Owner Notification Letters (Part 577).

12V008

In some cases, a plastic burning smell or burning and/or smoke from the front of the vehicle may be noticed. Should any of these warning occur, pull of the road to a safe location away from traffic, and switch off the engine. If you notice a plastic burning smell or burning and/or smoke from the front of the vehicle, do not open the hood. All occupants should carefully exit the vehicle and move to a location away from traffic. **Do not continue to drive your vehicle.** Contact MINI Roadside Assistance at 1-866-646-4772 immediately to have your vehicle brought to the nearest authorized MINI dealer.

12V126

If you encounter a plastic burning smell or burning and/or smoke from the rear of the vehicle, your vehicle may be experiencing this condition. If driving, pull off the road to a safe location away from traffic, and switch off the engine. Do not open the trunk lid. All occupants should carefully exit the vehicle and move to a safe location away from traffic. **Do not continue to drive your vehicle.** Call 911 for emergency assistance. Also, contact BMW Roadside Assistance at 1-800-332-4269 to have your vehicle brought to the nearest authorized BMW center.

12V161

In some cases, a plastic burning smell or burning and/or smoke from the front of the vehicle may be noticed. Should any of these warning occur, pull of the road to a safe location away from traffic, and switch off the engine. If you notice a plastic burning smell or burning and/or smoke from the front of the vehicle, do not open the hood. All occupants should carefully exit the vehicle and move to a location away from traffic. **Do not continue to drive your vehicle.** Contact BMW Roadside Assistance at 1-800-2332-4269 immediately to have your vehicle brought to the nearest authorized BMW center.

12V166

In some cases, a plastic burning smell or burning and/or smoke from the front of the vehicle may be noticed. Should any of these warning occur, pull of the road to a safe location away from traffic, and switch off the engine. If you notice a plastic burning smell or burning and/or smoke from the front of the vehicle, do not open the hood. All occupants should carefully exit the vehicle and move to a location away from traffic. **Do not continue to drive your vehicle.** Contact Rolls-Royce Roadside Assistance at 1-877-671-3039 immediately to have your vehicle brought to the nearest authorized Rolls-Royce dealer.

12V267

2. If you experience loss of power steering assist while driving, pull over carefully as soon as possible to a safe location and away from traffic. **Do not continue to drive your vehicle.** Contact BMW Roadside Assistance at 1-800-332-4269 immediately to have your vehicle brought to the nearest authorized BMW center
3. If you notice a burning smell or burning and/or smoke from the front of the vehicle, pull over carefully as soon as possible to a safe location and away from traffic. **Do not continue to drive your vehicle.** Switch off the engine. Do not open the hood. All occupants should carefully exit the vehicle and move to a location away from traffic. Contact BMW Roadside Assistance at 1-800-332-4269 immediately to have your vehicle brought to the nearest authorized BMW center.

12V302

If you experience a loss of power steering assist while driving, you may continue to drive your vehicle, but drive cautiously and carefully. If you feel uncomfortable with this condition, then you should pull over carefully as soon as possible to a safe location and away from traffic; **do not continue to drive your vehicle.** Contact BMW Roadside Assistance at 1-800-332-4269 (1-800-497-9940 for ActiveE drivers) immediately to have your vehicle brought to the nearest authorized BMW center / BMW ActiveE center.

12V336

Until the recall service has been completed, **DO NOT DRIVE YOUR VEHICLE.**

12V430

If you detect the presence of red fluid on the floor at the rear left side of your vehicle or smoke occurring in the same area, **please contact your Lamborghini dealer to get your vehicle towed.**

12V475

1. BMW recommends that you **do not continue to drive your vehicle.** Contact your authorized BMW Center immediately to have the necessary repair performed as soon as possible.
2. If you continue to drive your vehicle and this condition occurs, you may hear a noise and/or feel a vibration coming from the front of the vehicle. .
3. If there is a sudden loss of oil pressure, the low oil pressure warning indicator illuminated in red and warning message “Engine oil pressure; Stop carefully” will be displayed in the instrument cluster. An additional warning message will be displayed in the vehicle’s control display as follows: “Engine oil pressure too low: Stop carefully and stop engine. Risk of engine damage with continued driving. Call Roadside Assistance.”
4. If the condition in #2 or 3 occurs, carefully move away from traffic and pull over to a safe location as soon as possible. **Do not continue to drive your vehicle.** Contact BMW Roadside Assistance at 1-800-332-4269 immediately to have your vehicle brought to the nearest authorized BMW center.

12V504

1. BMW recommends that you **do not continue to drive your vehicle**. Contact your authorized BMW Center immediately to have the necessary repair performed as soon as possible.
2. If the door does not close or stay latched, **do not continue to drive your vehicle**. Do not attempt to drive while trying to hold the door closed. Contact BMW Roadside Assistance at 1-800-332-4269 immediately to have your vehicle brought to the nearest authorized BMW center.

12V550

If you experience loss of power steering assist while driving, pull over carefully as soon as possible to a safe location and away from traffic. **Do not continue to drive your vehicle**. Contact BMW Roadside Assistance at 1-800-332-4269 immediately to have your vehicle brought to the nearest authorized BMW center”

Appendix A-3

2011 Recalls with do not drive instructions from manufacturer to owner

The text for each recall in this appendix is taken from Owner Notification Letters (Part 577).

11V007

If your vehicle has not been serviced for the safety issue described in this letter, **DO NOT DRIVE YOUR VEHICLE.**

11V153

ADDITIONAL IMPORTANT NOTICE: If you are unable to select or engage drive gears in your vehicle, contact your Kia dealer to have the vehicle inspected. Under such circumstances, you may request that **your vehicle be towed** to the nearest Kia dealer at no cost to you by phoning Kia Roadside Assistance at (800) 333-4KIA (4542).

11V332

If you experience stalling while driving, pull over carefully as soon as possible to a safe location and away from traffic. **Do not continue to drive your vehicle.** Contact BMW Roadside Assistance at 1-800-332-4269 immediately to have your vehicle brought to the nearest authorized BMW center.

11V341

If you experience a loss of power steering assist while driving, a yellow warning symbol in the instrument cluster will illuminate, accompanied by a short message in the instrument cluster to drive moderately. You may continue to drive your vehicle, but drive cautiously and carefully. If you feel uncomfortable with this condition then you should pull over carefully as soon as possible to a safe location and away from traffic; **do not continue to drive your vehicle.** Contact BMW Roadside Assistance at 1-800-332-4269 immediately to have your vehicle brought to the nearest authorized BMW center.

11V438

If one of the tail lamp warning symbols appear (4), please drive carefully and cautiously, as the driver of the vehicle behind you may not notice that one of the rear lamps are not working. If this condition is present, and if you feel unsafe, please contact BMW Roadside Assistance at 1-800-332-4269 immediately to **have your vehicle brought to the nearest authorized BMW center.**

11V441

If you encounter a non-starting condition, your vehicle may be experiencing this condition. Contact BMW Roadside Assistance at 1-800-332-4269 immediately to **have your vehicle brought to the nearest authorized BMW center.** BMW recommends that you always wear your safety belt, and that all passengers are properly seated and restrained at all times. If you are not the only driver of this vehicle, please advise all other drivers and passengers of this important information.

11V469

If you notice or smell smoke in the front cowl area of the vehicle, be sure the ignition switch is in the “off” position and **do not operate the vehicle**. Immediately contact your Subaru dealer for assistance.

11V476

If this condition is occurring, pull over as carefully as possible to a safe location and away from traffic. **Do not continue to drive your vehicle**. Contact BMW Roadside Assistance at 1-800-332-4269 immediately to have your vehicle brought to the nearest authorized BMW center.

11V510

If an oil cooler line failure occurs the driver may observe one or more of the following warning signs: (1) Oil pressure warning light illuminated whilst the engine is running; (2) Signs of oil under the front or rear of the vehicle whilst the vehicle is parked; (3) Excessive oil consumption; (4) Trail of oil on the road; If you observe any of the above before driving, **do not drive the car** and contact your Lotus dealer.

11V521

In some cases, a plastic burning smell, or burning and/or smoke from the front of the vehicle may be noticed. Should any of these warnings occur, pull off the road to a safe location away from traffic, and switch off the engine. If you notice a plastic burning smell, or burning and/or smoke from the front of the vehicle, do not open the hood. All occupants should carefully exit the vehicle and move to a location away from traffic. **Do not continue to drive your vehicle**. Contact BMW Roadside Assistance at 1-800-332-4269 immediately to have your vehicle brought to the nearest Authorized BMW Center.

11V522

In some cases, a plastic burning smell, or burning and/or smoke from the front of the vehicle may be noticed. Should any of these warnings occur, pull off the road to a safe location away from traffic, and switch off the engine. If you notice a plastic burning smell, or burning and/or smoke from the front of the vehicle, do not open the hood. All occupants should carefully exit the vehicle and move to a location away from traffic. **Do not continue to drive your vehicle**. Contact Rolls-Royce Roadside Assistance at 1-877-671-3039 immediately to have your vehicle brought to the nearest Authorized Rolls Royce Dealer.

11V598

For your convenience, or, if you are not comfortable using the vehicle before the battery has been replaced, your Fisker retailer will arrange to **pick up your vehicle** and return it to you after it has been serviced.

Appendix A-4

2010 Recalls with do not drive instructions from manufacturer to owner

The text for each recall in this appendix is taken from Owner Notification Letters (Part 577).

10V018

If you experience a condition while driving in which the vehicle continues to accelerate rapidly after releasing the accelerator pedal, this could be an indication of floor mat interference or a sticking accelerator pedal. If this occurs, GM recommends that you take the following actions: • If possible and safe to do so, pull back the floor mat and dislodge it from the accelerator pedal; then pull over and stop the vehicle. • If the floor mat cannot be dislodged, or if no floor mat is present, then firmly and steadily step on the brake pedal with both feet. Do not pump the brakes repeatedly because that may deplete vacuum assist, requiring increased brake pedal force. • The engine can also be disabled by shifting the transmission to Neutral. After shifting to Neutral, firmly apply the brakes and steer the vehicle to a safe location on the side of the road; come to a complete stop, shift to Park, and turn the ignition key OFF. • Call your dealer to pick up the vehicle. **Do not drive it.**

10V072

If you experience any unusual looseness in your brake pedal, **do not drive your vehicle** and call your dealer or Infiniti Consumer Affairs at 1-800-662-6200 for further instructions.

10V196

If you notice a fluid leak, **do not operate the vehicle**. Immediately contact your Subaru dealer for assistance. If you notice a loss of power, carefully steer the vehicle to a safe place on the side of the road. Turn the ignition off and **do not operate the vehicle**. Immediately contact your Subaru dealer for assistance.

10V215

If you detect the odor of fuel or observe fuel on the ground, please contact your Lamborghini dealer to **get your vehicle towed to service**.

10V326

If you notice a loss of power, carefully steer the vehicle to a safe place on the side of the road. Turn the ignition off and **do not operate the vehicle**. Immediately contact your Subaru dealer for assistance.

10V331

If you experience stalling while driving, pull over carefully as soon as possible to a safe location and away from traffic. **Do not continue to drive your vehicle**. Contact BMW Roadside Assistance at 1-800-332-4269 immediately to have your vehicle brought to the nearest authorized BMW center.

10V446

In the event you notice a decrease in power brake assist, **do not continue to drive your vehicle**. Immediately contact BMW Roadside Assistance at 1-800-332-4269 or your nearest authorized BMW center to have your vehicle brought to an authorized BMW center.

10V447

In the event you notice a decrease in power brake assist, **do not continue to drive your vehicle**. Immediately contact Rolls-Royce Roadside Assistance at 1-877-671-3029, or your nearest authorized Rolls-Royce dealer, to have your vehicle brought to an authorized Rolls-Royce dealer.

10V518

If you experience engine stalling while driving, pull over carefully as soon as possible to a safe location and away from traffic. **Do not continue to drive your vehicle**. Contact BMW Roadside Assistance at 1-800-332-4269 immediately to have your vehicle brought to the nearest authorized BMW SAV center.

10V599

Immediately check the Low Brake Fluid Level Warning Light on your instrument panel. If it is illuminated, **DO NOT DRIVE your vehicle**. Contact Kia Roadside Assistance (800) 333-4KIA (4542) to have your vehicle towed to the nearest Kia dealer at no cost to you.

10V613

Until you have your vehicle inspected, frequently look at the Low Brake Fluid Level Warning Lamp on the instrument panel. If the warning lamp turns on and remains on, carefully drive to the nearest safe location and park your vehicle. **DO NOT CONTINUE TO DRIVE your vehicle** if the Low Brake Fluid Level Warning Lamp turns on and remains on. Contact Hyundai Roadside Assistance at 1-800-243-7766 to have your vehicle towed to the nearest Hyundai dealer at no charge to you.

10V643

If your vehicle has not been serviced for the safety issue described in this letter, **DO NOT DRIVE YOUR VEHICLE**. Contact your GM dealer immediately for additional information and instructions regarding this recall.

Appendix A-5

2009 Recalls with do not drive instructions from manufacturer to owner

The text for each recall in this appendix is taken from Owner Notification Letters (Part 577).

09V048

If the convertible top warning light illuminates or any fluid is seen leaking from under the car, please stop driving the vehicle immediately and avoid driving it until the repairs described below have been performed.

09V130

Important Notice:

If you currently have any of the problems indicated by the bullet points above, please immediately contact your Kia dealer to have the repair conducted. Under such circumstances, you may request that your vehicle be towed to the nearest Kia dealer at no cost to you by phoning Kia Roadside Assistance at (800) 333-4KIA (4542).

09V155

You should not operate your vehicle until your Chevrolet dealer has had the opportunity to inspect and repair your vehicle.

09V164

Affected vehicles can continue to be driven as usual, but if a knocking sound is heard coming from beneath the vehicle, customers should stop driving and have the vehicle inspected by an authorized Volkswagen dealer as soon as possible.

09V183

Inspect your front wheels after setting them in a straight ahead position. If you observe that your front wheels are visibly tilted either inward or outward or if they are not pointing in the same direction, do not drive your vehicle. Contact the Customer Assistance Center at the telephone number provided below, and they will arrange for your vehicle to be towed to the closest Kia dealer for inspection.

09V277

If you notice the smell of gasoline, do not operate the vehicle. Immediately contact your Subaru dealer for assistance.

09V431

If you notice that the Brake Warning Light in your Sentra is illuminated, we strongly urge you to immediately check the brake fluid level in your vehicle and add additional DOT 3 brake fluid if necessary. The instructions are in Section 8 of your Owner's Manual. Do not continue driving with the Low Brake Fluid Warning Light on.

Appendix A-6

2008 Recalls with do not drive instructions from manufacturer to owner

The text for each recall in this appendix is taken from Owner Notification Letters (Part 577).

08V214

If the clutch sensor warning light illuminates, please stop driving the vehicle immediately and avoid driving it until the repairs described below have been performed.

08V311

If you notice that the Brake Warning Light in your Sentra is illuminated, we strongly urge you to immediately check the brake fluid level in your vehicle and add additional DOT 3 brake fluid if necessary. The instructions are in Section 8 of your Owners Manual. Do not continue driving with the Low Brake Fluid Warning Light on.

08V459

Important Additional Notice: If you already have engine performance problems while starting or driving, please immediately contact your Kia dealer to have the repair conducted. Under such circumstances, you may request that your vehicle be towed to the nearest Kia dealer by phoning the Customer Assistance Center at the telephone number provided below.

Please do not take any out of area trips until you have this repair conducted. We are concerned that customers away from home are less likely to arrange for a repair if the problem starts to develop. Thus, please immediately call your dealer to arrange for a repair if you have any out of area travel planned.

08V460

There are two important precautions you should take until this recall has been performed:

- It is highly recommended that you not park your vehicle in a garage, car port or other structure.
- If you notice an oil leak or burning odor, do not operate the vehicle. Immediately contact your Subaru dealer for assistance.

Appendix A-7

2007 Recalls with do not drive instructions from manufacturer to owner

The text for the recall in this appendix is taken from the Owner Notification Letter (Part 577).

07V043

If you encounter a blown fuse, an illuminated air bag system warning light, smell smoke, or have replaced a blown fuse #6 without correcting the underlying problem, do not operate the vehicle. Contact your nearest Subaru dealer as soon as possible for guidance.

Appendix A-8

2006 Recalls with do not drive instructions from manufacturer to owner

The text for each recall in this appendix is taken from Owner Notification Letters (Part 577).

06V277

If you notice a change in vehicle handling/control, or hear an unusual noise coming from the area of the rear axle, your vehicle may be experiencing this problem. In that case, you should pull over carefully to a safe location, and away from traffic. Do not continue to drive the vehicle. Please contact BMW Roadside Assistance immediately at 1-800-332-4269 to have the vehicle brought to the nearest Authorized BMW Center.

06V327

If you notice a change in handling/control of your car, or hear an unusual noise coming from the area of the rear axle, your car may be experiencing this problem. In that case, you should pull over carefully to a safe location, and away from traffic. Do not continue to drive the car. Please contact Rolls-Royce Roadside Assistance immediately at 1-800-731-4488 to have your car brought to the nearest Rolls-Royce Dealer.

06V400

If you notice a vibrating steering wheel, or a pull to one side during vehicle braking, your vehicle may be experiencing this problem. In that case, you should pull over carefully to a safe location, and away from traffic. Do not continue to drive the vehicle. Please contact BMW Roadside Assistance immediately at 1-800-332-4269 to have the vehicle brought to the nearest Authorized BMW Center.

Appendix A-9

2005 Recalls with do not drive instructions from manufacturer to owner

The text for each recall in this appendix is taken from Owner Notification Letters (Part 577).

05V018

Contact your GM dealer as soon as possible to arrange to have your vehicle towed to the dealership. Do not drive your vehicle to the dealership.

05V159

If you are hearing loud noises which appear to be coming from the area of your wheels, or if you are experiencing significant unusual vibrations while driving your vehicle, contact the Kia Customer Assistance number below to have your vehicle towed to your nearest dealer.

05V183

Please call your Kia dealer to schedule a service appointment and have your vehicle towed. *IMPORTANT. DO NOT DRIVE YOUR VEHICLE to the dealer. Arrangements will be made to tow your vehicle and courtesy transportation will be provided.

05V319

If the charge warning and brake warning lamps come on while you are driving, you should pull off the road to a safe location and arrange to have your vehicle towed to a Nissan dealer.

05V412

If you are concerned about driving your MAZDA5 to your Mazda dealer, please contact Mazda's Roadside Assistance Program at 1 (800) 866-1998 (telephone number is also available in your MAZDA5 owner's manual) and arrangements will be made to pick up your vehicle and provide you with a rental or loaner car (at no cost to you) while repairs are being scheduled.

05V452

To minimize the risk of injury or death, do not ride, your Suzuki dealer will perform the necessary inspection and repair for your vehicle.

Appendix A-10

2004 Recalls with do not drive instructions from manufacturer to owner

The text for each recall in this appendix is taken from Owner Notification Letters (Part 577).

04V090

Slow engine cranking and difficulty starting the engine could indicate a low battery. Poor driveability or a check engine light could indicate a fuel pressure regulator leak. If you experience these conditions have your dealer check and repair your vehicle.

If your vehicle does not start and you hear a loud bang, there could be a fuel leak. Do not try to start it again. Contact your dealer for assistance.

04V182

PRECAUTIONS

1. Contact your authorized BMW Center immediately to have the necessary repair performed as soon as possible.
2. If you experience engine stalling while driving, pull over carefully as soon as possible to a safe location and away from traffic. Do not continue to drive your vehicle. Contact BMW Roadside Assistance at 1-800-332-4269 immediately to have your vehicle brought to the nearest Authorized BMW Center.
3. If you are not the only driver of this vehicle, please advise all other drivers of this important information.

04V183

PRECAUTIONS

1. Contact your authorized BMW Center immediately to have the necessary repair performed as soon as possible.
2. If you experience a sudden loss of the pressure or the failure while driving, then you should pull over carefully as soon as possible to a safe location and away from traffic. Do not attempt to change your tire. Do not continue to drive your vehicle. Contact BMW Roadside Assistance at 1-800-332-4269 immediately to have your vehicle brought to the nearest Authorized BMW center for repair.
3. BMW recommends that you always wear your safety belt, and that all passengers are properly seated and restrained at all times.
4. If you are not the only driver of this vehicle, please advise all other drivers of this important information.

04V344

PRECAUTIONS

1. DO NOT DRIVE YOUR VEHICLE.
2. CONTACT YOUR AUTHORIZED BMW SALES CENTER IMMEDIATELY TO HAVE THE NECESSARY REPAIR PERFORMED AS SOON AS POSSIBLE. YOUR AUTHORIZED BMW SALES CENTER WILL ARRANGE FOR PICK-UP AND REPAIR OF YOUR VEHICLE, INCLUDING ALTERNATE TRANSPORTATION.

3. If you experience engine stalling while driving, pull over carefully as soon as possible to a safe location and away from traffic. Do not continue to drive your vehicle. Contact BMW Roadside Assistance at 1-800-332-4269 immediately to have your vehicle brought to the nearest Authorized BMW SAV Center.
4. If you are not the only driver of this vehicle, please advise all other drivers of this important information.

04V348

If you experience a flat tire while driving, then you should pull over carefully as soon as possible to a safe location and away from traffic. Do not continue to drive your vehicle. Contact MINI Roadside Assistance at 1-866-646-4772 immediately to have your vehicle brought to the nearest Authorized MINI dealer.

04V402

- Do not operate your vehicle with the fuel tank gauge indicating that the tank is less than half-full. Engine stalling could occur even though the gauge indicated that there is sufficient fuel in the tank. Therefore, you should refuel before the gauge indicates that the tank is half-full.
- If you experience engine stalling while driving, you should pull over carefully to a safe location, and away from traffic. Do not continue to drive the vehicle. Please contact BMW Roadside Assistance immediately at 1-800-332-4269 to have the vehicle brought to the nearest Authorized BMW SAV Center.

04V473

If you encounter an oil leak, do not operate the vehicle. Contact the nearest Subaru dealer.

04V604

Your vehicle should not be driven until this recall service has been performed.

Appendix A-11

2003 Recalls with do not drive instructions from manufacturer to owner

The text for each recall in this appendix is taken from Owner Notification Letters (Part 577).

03V001

PRECAUTIONS - If one or more of the following conditions occurs:

A loss of brake performance is noticed, The brake warning light is activated,
Your hear a thumping or a rubbing noise coming from the front wheel housing,

Then you should pull over carefully as soon as possible to a safe location and away from traffic. Do not continue to drive your vehicle. Contact BMW roadside Assistance at 1-800-332-4269 immediately to have your vehicle brought to the nearest BMW SAV center.

03V052

In certain 2003 model year Buick Rendezvous and Pontiac Aztek vehicle, the diameter of the steering column intermediate shaft is too small. This condition could allow the intermediate shaft to spin inside the steering column coupling, resulting in a loss of directional control of the vehicle. A crash could result without prior warning.

You may have already been contacted regarding this recall by your GM dealer or by the GM Customer Assistance Center. If not, please contact your GM dealer immediately and tell the service department that your vehicle is involved in recall 03009. **DO NOT DRIVE YOUR VEHICLE.**

03V322

A condition may exist which causes the right front air bag to not deploy in an accident. The affected vehicles are 2004 Hyundai Elantras produced on or between June 12, 2003 and August 11, 2003.

Hyundai Motor America has shipped some of these vehicles to your company (Enterprise Rent A Car) and we are requesting that you not place these vehicles into service until a correction can be installed. If any of these vehicles have already been placed into service, please remove them from service and hold them until a correction can be installed.

Appendix A-12

2002 Recalls with do not drive instructions from manufacturer to owner

The text for each recall in this appendix is taken from Owner Notification Letters (Part 577).

02V027

Because of the potential for severe injury we strongly recommend that you do not drive your vehicle until it has been serviced for the defect described in this letter. Please call us at 866-944-9090 or contact your dealer right away for information on towing and courtesy transportation.

02V057

If you should experience a flat front tire, do not jack up your car and attempt to change it yourself. Contact BMW Roadside Assistance at 1-800-332-4269, or your nearest BMW center, immediately to have your car brought to that center for repair.

02V066

PLEASE note the attached wheel diagram and carefully inspect the spokes of your wheels for lateral cracks in the noted areas. If you see any cracks, stop driving your car immediately and contact your dealer or Saleen's Warranty Department at (949) 597-3837. Arrangements will be made to pick up your vehicle for repairs.

02V088

In the meantime, do not drive the vehicle nor let anyone else drive it. If you must drive your car and this problem occurs, pull over carefully to a safe location away from traffic. Contact your authorized BMW center or BMW Roadside Assistance at 1-800-332-4269 immediately to have your vehicle brought to the center for repair.

02V138

Potential engine overheating will be indicated by the needle in the coolant temperature gauge moving from the approximate middle position to the red zone, and on some models by display of the message "COOLANT TEMPERATURE" in the instrument cluster.

In some cases, an electrical smell, or burning and/or smoke from the front of the vehicle may be noticed.

Should any of these warnings occur, pull off the road to a safe location and switch off the engine. If you notice an electrical smell, or burning and/or smoke from the front of the vehicle, do not open the hood. All occupants should carefully exit the vehicle and move to a location away from traffic. Contact BMW Roadside Assistance at 1-800-332-4269 immediately to have your vehicle brought to the nearest BMW center.

02V146

If you notice a knocking sound from the front of your vehicle and/or abnormal steering, you should stop driving and contact your Infiniti dealer to arrange to have the vehicle towed to the dealer for repair.

02V150

Do not operate vehicle with the fuel tank less than half full. If you experience any loss of power do not continue to drive your vehicle

02V194

In the meantime, if there is a sudden, noticeable increase in side to side play of the brake pedal, do not drive the vehicle. If this increase in play is noticed while driving, pull over carefully to a safe location away from traffic. Contact your authorized BMW X5 SAV center or BMW Roadside Assistance at 1-800- 332-4269 immediately to have your vehicle brought to the center for repair.

If the brake pedal detaches while driving, you can stop the vehicle by downshifting the transmission and carefully applying the parking brake. After stopping in a safe location away from traffic, contact your authorized BMW.X5 SAV center or BMW Roadside Assistance at 1-800-332-4269 immediately to have your vehicle brought to the center for repair.

02V305

To reduce the possibility of losing control due to this condition, you should avoid driving over 35 mph or during inclement weather. If the amber-colored ABS tell-tale lamp illuminates or you hear grinding noise, you should immediately pull off of the road and call Roadside Assistance at the appropriate number below to have your vehicle towed to the nearest GM dealer for repair.

02V330

To reduce the possibility of losing control due to this condition, you should not drive your vehicle until the attaching nut has been inspected for the proper torque specification.

Appendix A-13

2001 Recalls with do not drive instructions from manufacturer to owner

The text for each recall in this appendix is taken from Owner Notification Letters (Part 577).

01V026

Due to the potential for severe injury, we strongly recommend that you do not drive your vehicle until it has been serviced for the defect described in this letter. Please contact your dealer right away for information on towing and courtesy transportation.

01V126

What You Should Do: Contact your GM dealer as soon as possible to arrange to have your vehicle towed to the dealership. Do not drive your vehicle to the dealership. Your dealer will provide you with alternate transportation while your vehicle is at the dealership for this repair.

01V152

As a safety precaution, you must not drive your minivan until this service is performed. Contact your dealer right away to schedule an appointment to have your minivan picked up or call Chrysler Roadside Assistance at 1-800-521-2779 and arrange to have your minivan towed to a dealer immediately.

01V173

A sudden, significant increase in steering effort, or continuous illumination of the battery charge indicator in the instrument cluster will be indications that this problem has occurred. Also, potential engine overheating will be indicated by the needle in the coolant temperature gauge moving towards the red zone, and by display of the message "COOLANT TEMPERATURE" in the instrument cluster.

Should any of these warnings occur, pull off the road to a safe location and switch off the engine. Contact BMW Roadside Assistance at 1-800-332-4269 immediately to have your vehicle brought to the nearest BMW X5 SAV center.

01V174

As a precaution until the vehicle is repaired, listen for any unusual noise coming from underneath the front of the vehicle and/or steering wheel vibration when hitting bumps. If the steering feels unusual or the vehicle becomes difficult to steer, do not drive the vehicle. Please contact your dealer.

01V195

If the "BRAKE" warning lamp in the instrument cluster illuminates continuously, or the "CHECK BRAKE FLUID" message (also in the cluster) is displayed, do not drive the vehicle. If this occurs while driving, or if the brake pedal travel increases significantly during brake application, pull off the road to a safe location. Contact BMW Roadside

Assistance at 1-800-332-4269 immediately to have your vehicle brought to the nearest BMW X5 SAV center.

01V196

If the automatic transmission warning lamp in the instrument cluster illuminates continuously or the “TRANS. FAIL-SAFE PROG” message (also in the cluster) is displayed after starting the engine, do not drive the vehicle. If this occurs while driving, or your transmission will not upshift from lower gears, pull off the road to a safe location. In either case, first follow the instruction in the Owner’s Manual (see “Automatic Transmission” section) to try to restore normal transmission performance. If this is not successful, do not drive your vehicle. Contact BMW Roadside Assistance at 1-800-332-4269 immediately to have your vehicle brought to the nearest BMW X5 SAV center.

01V197

If brake pedal travel increases significantly during brake application, or if there is a significant reduction in brake power assist, pull off the road to a safe location. Contact BMW Roadside Assistance at 1-800-332-4269 immediately to have your vehicle brought to the nearest BMW X5 SAV center.

01V206

Should any of these warnings occur, pull off the road to a safe location and switch off the engine. If you notice an electrical smell, or burning and/or smoke from the front of the vehicle, do not open the hood. All occupants should carefully exit the vehicle and move to a location away from traffic. Contact BMW Roadside Assistance at 1-800-332-4269 immediately to have your vehicle brought to the nearest BMW center.

01V229001

Since the solenoid malfunction can occur without prior warning, your vehicle should not be driven until it has been inspected and it has been determined that the affected solenoid is not installed on your vehicle.

If you have not yet been contacted by your Land Rover retailer, your vehicle should be towed to an authorized Land Rover retailer where the specified repairs can be performed.

01V245

If you hear a metallic noise, such as scraping, rattling, grinding, etc., from the rear brake area while driving, do not continue to drive. Pull off the road to a safe location. Contact BMW Roadside Assistance at 1-800-332-4269 immediately to have your vehicle brought to the nearest BMW center.

Appendix A-14

2000 Recalls with do not drive instructions from manufacturer to owner

The text for each recall in this appendix is taken from Owner Notification Letters (Part 577).

00V010 PRECAUTIONS

1. CONTACT YOUR AUTHORIZED BMW CENTER IMMEDIATELY TO HAVE THE NECESSARY INSPECTION/REPAIR PERFORMED AS SOON AS POSSIBLE.
2. If your BMW center confirms that your vehicle has not yet been inspected/repaired, do not drive the vehicle.
3. If this problem occurs, your vehicle's steering capability could be lost without warning and, depending on environmental and traffic conditions and the driver's reaction, a crash could occur.
4. If you are not the sole driver of your car, please advise all other drivers not to drive the vehicle.

00V036 Depending upon the severity of the leak, the ACE warning lamp will illuminate amber or red. The illuminated AE lamp indicates that the vehicle should be stopped as soon as safely possible and the engine switched off. The vehicle should be towed to an authorized Land Rover retailer where the specified repairs can be performed. Should the auxiliary drive system fail, the battery charge warning lamp will illuminate. In the event of such a failure, the engine should be switched off as soon as safely possible and the vehicle should not be driven. It should be towed to an authorized Land Rover retailer where the specified repairs can be performed. If you are not the sole driver of this vehicle, please advise all other drivers of these necessary precautions.

00V039 If, prior to having the corrective work performed, you should smell fuel vapors originating in the engine compartment, please refrain from driving your vehicle and contact your nearest authorized Volkswagen dealer immediately.

00V048 PRECAUTIONS

1. CONTACT YOUR AUTHORIZED BMW CENTER IMMEDIATELY TO HAVE THE NECESSARY INSPECTION/REPAIR PERFORMED AS SOON AS POSSIBLE.
2. Before the repair, brake lamp operation should be checked with the vehicle stationary by turning the key to position 2 ("ignition" or "on") and depressing the brake pedal. An observer facing the rear of the vehicle can determine if the brake lamps are working properly. If the brake lamps are inoperative or continuously lit, the vehicle should not be driven. Arrangements should be made for pickup and repair.
3. If the inoperative or continuously-lit brake lamps are ignored and the vehicle is driven, a crash involving another vehicle (or vehicles) could occur without prior warning, depending on environmental and traffic conditions.
4. If you are not the sole driver of your car, please advise all other drivers of these necessary precautions.

00V069 Users and/or Customers of Generation I, 1997 Evs are urged to park their vehicle and

immediately discontinue any and all vehicle charging. It is recommended that customers park their vehicle away from the charger to help prevent inadvertent use of the charging system.

00V142 Should the serpentine drive belt fail, the battery charge warning lamp will illuminate immediately. The amber ACE warning lamp may illuminate.

In the event of such a failure, the engine should be switched off as soon as safely possible and the vehicle should not be driven. It should be towed to an authorized Land Rover retailer where the specified repairs can be performed. If you are not the sole driver of this vehicle, please advise all other drivers of these necessary precautions.

00V187 Should abnormal noise or vibration occur upon the application of the brakes, the vehicle should be stopped as soon as safely possible. The vehicle should not be driven if unusual braking characteristics are encountered. It should be towed to an authorized Land Rover retailer where appropriate repairs can be performed. If you are not the sole driver of this vehicle, please advise all other drivers of these necessary precautions.

00V288 As a precaution until the vehicle is repaired, keep your foot on the brake pedal and release it slowly after shifting gears to ensure that the transmission is in the gear that you have selected. If the transmission becomes stuck in the Park position but the shift selector moves, do not attempt to get out of Park or drive the vehicle. Please contact your dealer. Always set the parking brake when the transmission is in Park.

00V317 Please make a quick check of the operation of your car's electrical accessories such as the turn signals, windshield wipers, headlights or electrical windows after you have started the engine and before you begin driving in order to make sure that they function properly. If they do not function, switch off the engine and restart it and check again, or, call your authorized dealer so that repairs can be performed. Do you drive your Audi if the turn signals, windshield wipers or headlights do not operate after you have started the engine.

00V341 PRECAUTIONS

1. CONTACT YOUR AUTHORIZED BMW X5 SAV CENTER IMMEDIATELY TO HAVE THE NECESSARY INSPECTION/REPAIR PERFORMED AS SOON AS POSSIBLE.X

2. If you experience significant steering wheel play and/or misalignment (approximately 30 degrees or more), or noise from the steering linkage, do not drive the vehicle. In this case, or if you feel uncomfortable driving your vehicle as a result of this recall notice please contact BMW Roadside Assistance at 1-800-332-4289 or your nearest X5 SAV center to arrange for towing service to that center.

3. If you do not observe this precaution and this problem occurs, your vehicle's steering capability could be drastically reduced and, depending on environmental and traffic conditions and the driver's reaction, a crash could occur.

4. If you are not the sole driver of your car, please advise all other drivers not to drive the vehicle if the conditions described in paragraph 2 occur.

00V383 PRECAUTIONS

1. CONTACT YOUR AUTHORIZED BMW CENTER IMMEDIATELY TO HAVE THE

NECESSARY INSPECTION/REPAIR PERFORMED AS SOON AS POSSIBLE.

2. If you feel uncomfortable driving your vehicle as a result of this recall, please contact BMW Roadside Assistance at 1-800-332-4289 or your nearest BMW center to arrange for towing service to that center.

3. If this problem occurs, your vehicle's handling and control would be drastically affected and, depending on environmental and traffic conditions and the driver's reaction, a crash could occur.

4. If you are not the sole driver of your car, please advise all other drivers of this important information.

00V388 Please ensure that you and all vehicle occupants wear your seat belts, sit back properly, and do not lean on either front door. Prior to your scheduled service appointment, if the supplemental restraint system (SRS) indicator lamp remains illuminated after start up, or comes on while driving, we recommend you stop driving your vehicle immediately and contact your retailer.

00V410 As a precaution until the vehicle is repaired, watch for any looseness in the ignition key lock. If the end cap is loose or you are able to slide the ignition lock mechanism in and out, do not drive the vehicle. Please contact your dealer to have your vehicle towed to the dealership if any of the above symptoms occur, or if you are unsure of their occurrence.

00V423 Depending on the severity of the leak, the ACE warning lamp will illuminate amber or red. The illuminated ACE lamp indicates that the vehicle should be stopped as soon as safely possible and the engine switched off. The vehicle should be towed to an authorized Land Rover Retailer where the specified repairs can be performed. Should the auxiliary drive system fail, the battery charge warning lamp will illuminate. In the event of such a failure, the engine should be switched off as soon as safely possible and the vehicle should not be driven. It should be towed to an authorized Land Rover Retailer where the specified repairs can be performed. If you are not the sole driver of this vehicle, please advise all other drivers of these necessary precautions.

Appendix B-1

2013 Recalls with Risk Mitigation Instructions in Part 577 letters

Recalls that contain Do Not Drive instructions are starred with an asterisk (*) in this appendix. 2013 Recalls with Do Not Drive instructions also appear separately in appendix A-1, however, they are included here so that this appendix can stand alone as the complete list of Risk Mitigation Instructions. The text for each recall in this appendix is taken from Owner Notification Letters (Part 577).

***13V017**

Precautions for your safety:

1. Contact your authorized BMW ActiveE Center immediately to have the necessary repair performed as soon as possible.
2. If you need to locate the nearest authorized BMW ActiveE center, please contact BMW ActiveE customer relations at 1-855-236-1025, or via email at ActiveECustomerRelations@BMWUSA.com you can also contact BMW Roadside specifically for ActiveE at 1-800-497-9940.
3. If this condition occurs while driving, your vehicle will lose power. If this happens, carefully move away from traffic and pull over to a safe location; do not continue to drive your vehicle. Contact BMW ActiveE Roadside Assistance at 1-800-497-9940 immediately to have your vehicle brought to the nearest authorized BMW ActiveE center.
4. If you are not the only driver of this vehicle, please advise all other drivers and passengers of this important information.

13V030

In the meantime, please make sure to clear off any heavy snow and/or ensure the wipers are not frozen to the windshield before turning them on.

In the event this condition occurs while driving in inclement weather, safely move the vehicle to the shoulder of the road or another safe location, until you can see to drive safely.

***13V031**

If your vehicle's brake warning light illuminates and the brake warning buzzer is heard, do not drive your vehicle. Please immediately contact your local certified i-MiEV dealer for repair.

***13V041**

If an oil cooler line failure occurs the driver may observe one or more of the following warning signs:

- (1) Oil pressure warning light illuminated whilst the engine is running;
- (2) Signs of oil under the front or rear of the vehicle whilst the vehicle is parked;
- (3) Excessive oil consumption;
- (4) Trail of oil on the road;

If you observe any of the above before driving, do not drive the car and contact your Lotus dealer. If your oil pressure warning light illuminates whilst driving, or if you have any other reason to suspect that an oil line has become detached, stop your vehicle immediately in a safe and controlled manner and contact your Lotus dealer.

***13V044**

PRECAUTIONS FOR YOUR SAFETY

1. CONTACT YOUR AUTHORIZED BMW CENTER IMMEDIATELY TO HAVE THE NECESSARY REPAIR PERFORMED AS SOON AS POSSIBLE.
2. If your vehicle does not start, contact BMW Roadside Assistance at 1-800-332-4269 immediately to have your vehicle brought to the nearest authorized BMW center.
3. If you notice a momentary flickering of the display in the instrument cluster during driving or a momentary (less than one second) engine shutdown, carefully move away from traffic and pull over to a safe location as soon as possible. Do not continue to drive your vehicle. Contact BMW Roadside Assistance at 1-800-332-4269 immediately to have your vehicle brought to the nearest authorized BMW center.
4. If you are not the only driver of this vehicle, please advise all other drivers and passengers of this important information.

***13V045**

PRECAUTIONS FOR YOUR SAFETY

1. CONTACT YOUR AUTHORIZED BMW CENTER IMMEDIATELY TO HAVE THE NECESSARY REPAIR PERFORMED AS SOON AS POSSIBLE.
2. If this condition occurs on your vehicle, manual braking is still available to slow and stop the vehicle.
3. IN THE EVENT YOU NOTICE A DECREASE OF POWER BRAKE ASSIST, DO NOT CONTINUE TO DRIVE YOUR VEHICLE. Carefully move away from traffic and pull over to a safe location as soon as possible. Contact BMW Roadside Assistance at 1-800-332-4269 to have your vehicle brought to the nearest authorized BMW center.
4. If you are not the only driver of this vehicle, please advise all other drivers and passengers of this important information.

13V061

There are several important precautions you should take until this repair has been performed:

- The batteries should be removed from the RES transmitter fobs rendering them completely inoperable. (See battery removal instructions at the end of this letter.)
- As a precautionary measure, it is highly recommended that you not park your vehicle in an enclosed garage unless the transmitter fob batteries have been removed or the fobs replaced.

13V069

If the red air bag warning light in your vehicle continuously illuminates after the vehicle is started, please take your vehicle to the dealership as soon as possible. In the interim do not allow passengers to ride in the passenger seat.

***13V077**

There are two important precautions you should take until this repair has been performed:

- Do not operate the moonroof. It should be left in the fully closed position.
- If you notice that the moonroof glass is loose, do not operate the vehicle. Immediately contact your Subaru dealer for assistance.

***13V078**

There are several important precautions you should take until this repair has been performed:

- Be sure the cowl area where the windshield wipers park, when turned off, is free of any obstructions.
- If you notice or smell smoke in the front cowl area of the vehicle, be sure the ignition switch is in the "off" position and do not operate the vehicle. Immediately contact your Subaru dealer for assistance.
- As a precautionary measure, it is highly recommended that you not park your vehicle in a garage, car port or other structure.

***13V103**

Contact your nearest Chrysler, Jeep, or Dodge dealer immediately to have your vehicle battery disconnected. Discontinue driving your vehicle. Do not park your vehicle in your garage, near other vehicles, or near any building/structure.

***13V110**

There are several important precautions you should take until this repair has been performed:

- If you experience the condition described above while braking, continue to apply steady pressure on the brake pedal until the vehicle comes to a stop. Immediately contact your Subaru dealer for assistance.
- If you notice fluid leaking from the vehicle, do not operate the vehicle. Immediately contact your Subaru dealer for assistance.
- If the brake system warning light remains illuminated on the instrument panel with the parking brake fully released, do not operate the vehicle. Immediately contact your Subaru dealer for assistance.
- Always maintain a safe distance from other vehicles while driving. The normally recommended minimum distance is one car length of space for every 10 mph of speed.
- As a precautionary measure, it is highly recommended that you use extra care while operating the vehicle in confined areas such as parking lots and while parking your vehicle in a garage, car port or other structure.

***13V114**

If your brake lights are not working properly, you may request that your vehicle be towed to the nearest Kia dealer at no cost to you by phoning Kia Roadside Assistance at (800)-333-4KIA (4252).

***13V139**

If you hear a noticeable noise or feel a vibration from the front wheels, stop driving your vehicle and contact your dealer as soon as possible to have the vehicle inspected.

13V158

Note: We recommend that you refrain from placing anything in your trunk or putting the temporary spare into service until you have had your vehicle inspected.

13V159

You should immediately remove the driver's carpeted floor mat from the vehicle and store it for future return. Do not replace it with any of the other mats.

***13V194**

You should immediately contact your Subaru Dealer for an appointment to have this repair performed at no cost to you. If you prefer not to operate your vehicle until repairs are made, please contact your nearest Subaru dealer to make arrangements to have your vehicle towed to that dealer at no cost to you.

There are several important precautions you should take until this repair has been performed. Never adjust the steering wheel tilt/telescopic position while driving. This may cause loss of vehicle control and result in personal injury. This applies even after the steering column in your vehicle has been replaced. The following precautions should be observed while the vehicle is safely stopped:

- Before driving the vehicle, ensure the front wheels respond when the steering wheel is turned.
- Do not adjust the steering wheel tilt/telescopic position until this repair is made. This may cause loss of vehicle control and result in personal injury.

13V239

NOTE: To minimize the possibility of the above condition occurring, avoid high torque/heavy load driving maneuvers while in the four wheel drive mode.

13V260

Because of the risk of fire, owners are advised to park their vehicle outside until it can be inspected or a replacement switch has been installed.

13V270

If you need to use the child safety lock feature before Safety Recall 13S07 is completed, it is recommended that the child safety lock be set prior to each drive (see your Owner Manual for details).

13V324

Contact your Nissan dealer as soon as possible in order to arrange an appointment to have your vehicle repaired. However, if you observe that the rear seats on your 2014 Nissan Versa Note are not latching properly, please take your vehicle to a dealership immediately for diagnosis and repairs and do not let anyone ride in the rear seat until repairs are completed.

13V336

Properly applying the parking brake will ensure your vehicle remains stationary while parked. This is always recommended and particularly important at this time. As indicated in your owner's manual, never rely on the transmission alone to hold the vehicle. To set the parking brake, press the brake pedal firmly and hold it down while applying the parking brake.

If the transmission fails to disengage from the park position when the select lever is moved out of the "P" (Park) position, immediately return the lever to the park position and turn the engine off. Do not attempt to "rock" the vehicle by pressing the accelerator pedal or switching between forward and reverse gears. Doing so could result in the vehicle moving unexpectedly and the driver losing control. Contact your Subaru dealer for assistance.

13V339

1. Contact your authorized BMW Center immediately to have the necessary repair performed as soon as possible.
2. If you encounter a non-starting condition, your vehicle may be experiencing this condition. Contact BMW Roadside assistance at 1-800-332-4269 immediately to have your vehicle brought to the nearest authorized BMW center.
3. BMW recommends that you always wear your safety belt, and that all passengers are properly seated and restrained at all times.
4. If you are not the only driver of this vehicle, please advise all other drivers and passengers of this important information.

13V356

When parking the vehicle on an incline, make sure to engage the parking brake in accordance with the instructions contained on page 5-33 of your owner's manual.

13V405

Do not install a child or infant restraint system in the front passenger seat until your vehicle is repaired – Suzuki recommends that whenever possible children should be seated in the rear seat. Likewise, do not have a small person, such as a child who has outgrown child restraints, or a very small adult, sit in the front passenger seat. Consult your Vehicle Owners Manual for seating information. Lastly, please always be sure that all occupants wear their seat belts.

13V407

1. Contact your authorized BMW Center immediately to have the necessary repair performed as soon as possible.
2. If the vehicle is experiencing this condition, you may continue to drive your vehicle, but drive cautiously and carefully, as the driver of a vehicle behind you may not notice a bulb outage.
3. If this issue were to occur, the non-affected lamp and the center high-mounted stop lam ("third brake lamp") would provide redundant lamp functions to the driver of a vehicle behind you.
4. If the vehicle is experiencing this condition, a number of visual and audible warning are provided. A warning symbol will appear in the vehicle's "message center" in the instrument panel. If the condition involves the turn signal, the turn signal symbol in the instrument panel flashes (and sounds) at twice its normal frequency. In addition, each time the vehicle is started, an audible signal is made.
5. If you are not the only driver of this vehicle, please advise all other drivers and passengers of this important information.

***13V430**

If the MIL is illuminated, contact your Infiniti retailer immediately and it will make arrangements for an immediate repair. Do not continue using your vehicle with the MIL illuminated.

13V448

We recommend that you keep the sunroof shade fully closed until this recall repair has been completed. This will help minimize the chance of broken glass falling into the passenger compartment, should the sunroof glass break.

***13V451**

If you notice that the Brake Warning Light in your Titan is illuminated, we strongly urge you to contact your Nissan dealer and bring your vehicle in for inspection as soon as possible. Do not continue driving with the Brake Warning Light on.

13V452

Until you have your vehicle repaired, you should apply the park brake before you exit the vehicle to prevent the vehicle from moving unexpectedly.

***13V454**

1. Contact your authorized BMW Center immediately to have the necessary repair performed as soon as possible
2. If you notice a loss of power assist braking (greater pedal pressure is required), the vehicle may be experiencing this condition.
3. If this condition occurs, hydraulic braking (braking without power assist) remains available, although a longer distance would be needed to stop the vehicle.

4. If you notice a decrease of power brake assist, do not continue to drive your vehicle. Carefully move away from traffic and pull over to a safe location as soon as possible. Contact BMW Roadside Assistance at 1-800-332-4269 to have your vehicle brought to the nearest authorized BMW center.
5. If you are not the only driver of this vehicle, please advise all other drivers and passengers of this important information.

13V456

If you received this notice, we recommended that you do not allow passengers to ride in the front passenger seat until your vehicle is remedied.

13V500

Until then, please read the accompanying instructions regarding steps you can take to prevent the unintended braking from occurring. A copy of these instructions, along with a helpful video tutorial can be found at www.recalls.honda.com.

STARTING YOUR VEHICLE

Follow this procedure every time you start your car in order to prevent unintended braking.

1. Start the engine but keep the vehicle stationary until the VSA indicator illuminates and then goes off. This will take about 2 seconds.
2. Before shifting out of PARK, make sure the front wheels point straight ahead.
3. Keep the front wheels in a straight ahead position for the first several feet as you initially operate your vehicle, in forward or reverse gear. This will allow the VSA system to properly complete calibration.

VSA Indicator

STARTING YOUR VEHICLE WITH THE WHEELS TURNED

If you need to turn the wheels as you initially drive away (curbside parking):

1. After starting the engine, there are two ways to drive the car until you can move to a safe location to perform the starting procedure:

Drive the vehicle at a speed of less than 25 miles per hour

OR

Switch OFF the VSA system by pressing the VSA OFF button [located on the driver's side instrument panel as shown]. When the VSA is off, the VSA activation indicator comes on as a reminder.

Note: For information about operating your vehicle with the Vehicle Stability Assist system turned off, refer to the "Driving" section in your vehicle Owner's Manual.

2. Proceed to drive and park your vehicle in a safe location, such as a driveway or parking lot and completely turn off the vehicle.
3. Perform the STARTING YOUR VEHICLE procedure found at the top of this page.

LX, DX and EX model shown

In the event the previous procedures were not performed, here is what to do if The VSA system inadvertently applies the brakes while you are driving:

1. Gently apply the brakes; this will immediately stop the self-braking action.
2. As soon as possible, either:

Drive the vehicle at a speed of less than 25 miles per hour.

OR

Switch OFF the VSA system by pressing the VSA OFF button [located on the driver's side instrument panel as shown]. When the VSA is off, the VSA activation indicator comes on as a reminder

Note: For information about operating your vehicle with the Vehicle Stability Assist system turned off, refer to the "Driving" Section in your vehicle Owner's Manual.

3. Proceed to drive and park your vehicle in a safe location, such as a driveway or parking lot and completely turn off the vehicle.

4. Perform the STARTING YOUR VEHICLE procedure found at the top of page 1.

13V502

Until the recall is performed, the vehicle is still safe to drive. However, the front passenger seat should not be used under any circumstances due to the risks described above.

13V506

Until the recall is performed, the vehicle is still safe to drive. However, in order to avoid running out of fuel, the fuel gauge should not be allowed to go lower than the ½ point; i.e., you should always refill while at least one-half tank of gas remains showing on the fuel gauge.

13V523

In the event that your vehicle experiences this condition prior to having this recall performed, your vehicle can be restarted by following these steps:

- 1) Stop the vehicle, shift into park, and take your foot off the brake pedal.
- 2) Press the power button to shut off the vehicle.
- 3) Wait 60 seconds.
- 4) Restart the vehicle using normal start-up procedures.

***13V550**

If your vehicle is experiencing directional control issues (wobbling), contact Kia Roadside Assistance directly at 800-333-4542(4Kia) to request a tow to the nearest Kia dealer for repair.

Read the information and follow the instructions in the "Underbody Maintenance" section of your owner's manual regarding the ongoing maintenance and cleaning of the underbody of your vehicle to limit the effects of road salt in the future.

13V583

Ford will re-notify you by mail when replacement parts are available to address overheating. In the meantime,

- 1) If your vehicle exhibits symptoms of overheating, or an engine oil or coolant leak, please contact your dealer and request a service appointment for proper diagnosis and repair.
- 2) Maintain proper engine coolant level by following the Coolant Check procedure in the Maintenance section of your Owner's Manual to substantially reduce the risk of overheating leading to a fire.

13V584

Ford will re-notify you by mail when replacement parts are available to address overheating. In the meantime,

- 1) If your vehicle exhibits symptoms of overheating, or an engine oil or coolant leak, please contact your dealer and request a service appointment for proper diagnosis and repair.
- 2) Maintain proper engine coolant level by following the Coolant Check procedure in the Maintenance section of your Owner's Manual to substantially reduce the risk of overheating leading to a fire."

Appendix B-2

2012 Recalls with Risk Mitigation Instructions in Part 577 letters

Recalls that contain Do Not Drive instructions are starred with an asterisk (*) in this appendix. 2012 Recalls with Do Not Drive instructions also appear separately in appendix A-2C, however, they are included here so that this appendix can stand alone as the complete list of Risk Mitigation Instructions. The text for each recall in this appendix is taken from Owner Notification Letters (Part 577).

12V005

Until Safety Recall 11S24 is performed, it is recommended that you park your vehicle outdoors away from structures to prevent a potential fire from spreading in the unlikely event that your ASS module develops an electrical short.

***12V008**

1. Contact your authorized MINI dealer immediately to have the necessary repair performed as soon as possible.
2. In some cases, a plastic burning smell or burning and/or smoke from the front of the vehicle may be noticed. Should any of these warning occur, pull off the road to a safe location away from traffic, and switch off the engine. If you notice a plastic burning smell or burning and/or smoke from the front of the vehicle, do not open the hood. All occupants should carefully exit the vehicle and move to a location away from traffic. Do not continue to drive your vehicle. Contact MINI Roadside Assistance at 1-866-646-4772 immediately to have your vehicle brought to the nearest authorized MINI dealer.
3. MINI recommends parking your vehicle outdoors until repairs have been performed.
4. MINI recommends that you always wear your safety belt, and that all passengers are properly seated and restrained at all times.
5. If you are not the only driver of this vehicle, please advise all other drivers and passengers of this important information.

12V016

Until Safety Recall 6712A is performed, it is recommended that you park your vehicle outdoors away from structures to prevent a potential fire from spreading in the unlikely event that your ABS module develops an electrical short.

12V019

1. Contact your authorized BMW SAV Center immediately to have the necessary repair performed as soon as possible.
2. You may continue to drive your vehicle but, when parking and before leaving your vehicle, please make sure that the parking position "P" is engaged AND the parking brake is engaged.
3. Do not park on a hill/incline.

4. BMW recommends that you always wear your safety belt, and that all passengers are properly seated and restrained at all times.
5. If you are not the only driver of this vehicle, please advise all other drivers and passengers of this important information.

12V076

Please maintain the fuel level in your vehicle so that the fuel gauge reads above the one quarter position.

12V088

In the meantime, please maintain the fuel level in your vehicle so that the fuel gauge reads above the one half position. If your fuel gauge always indicates full, please use your odometer trip meter to measure your mileage in between fill-ups. We recommend you fill up every 250 miles.

12V099

A CRS should NOT be used in the rear seat center position until the seatbelt assembly has been repaired.

***12V126**

1. Contact your authorized BMW SAV Center immediately to have the necessary repair performed as soon as possible.
2. If you encounter a plastic burning smell or burning and/or smoke from the rear of the vehicle, your vehicle may be experiencing this condition. If driving, pull off the road to a safe location away from traffic, and switch off the engine. Do not open the trunk lid. All occupants should carefully exit the vehicle and move to a safe location away from traffic. Do not continue to drive your vehicle. Call 911 for emergency assistance. Also, contact BMW Roadside Assistance at 1-800-332-4269 to have your vehicle brought to the nearest authorized BMW center.
3. As a precaution, owners are advised to park outside until the Recall has been completed.
4. If you are not the only driver of this vehicle please advise all other drivers and passengers of this important information.

***12V161**

1. Contact your authorized BMW SAV Center immediately to have the necessary repair performed as soon as possible.
2. If the water pump fails, or if there is a reduction in engine cooling, a warning message will, in most cases, appear in the instrument cluster's "message center" during driving and when stopping the vehicle.
3. In some cases, a plastic burning smell or burning and/or smoke from the front of the vehicle may be noticed. Should any of these warning occur, pull off the road to a safe location away from traffic, and switch off the engine. If you notice a plastic burning

smell or burning and/or smoke from the front of the vehicle, do not open the hood. All occupants should carefully exit the vehicle and move to a location away from traffic. Do not continue to drive your vehicle. Contact BMW Roadside Assistance at 1-800-2332-4269 immediately to have your vehicle brought to the nearest authorized BMW center.

4. BMW recommends parking your vehicle outdoors until repairs have been performed.
5. BMW recommends that you always wear your safety belt, and that all passengers are properly seated and restrained at all times.
6. If you are not the only driver of this vehicle, please advise all other drivers and passengers of this important information.

***12V166**

1. Contact your authorized Rolls-Royce dealer immediately to have the necessary repair performed as soon as possible.
2. If the water pump fails, or if there is a reduction in engine cooling, a warning message will, in most cases appear in the instrument cluster's "message center" during driving and when stopping the vehicle.
3. In some cases, a plastic burning smell or burning and/or smoke from the front of the vehicle may be noticed. Should any of these warning occur, pull off the road to a safe location away from traffic, and switch off the engine. If you notice a plastic burning smell or burning and/or smoke from the front of the vehicle, do not open the hood. All occupants should carefully exit the vehicle and move to a location away from traffic. Do not continue to drive your vehicle. Contact Rolls-Royce Roadside Assistance at 1-877-671-3039 immediately to have your vehicle brought to the nearest authorized Rolls-Royce dealer.
4. Rolls-Royce recommends parking your vehicle outdoors until repairs have been performed.
5. Rolls-Royce recommends that you always wear your safety belt, and that all passengers are properly seated and restrained at all times.
6. If you are not the only driver of this vehicle, please advise all other drivers and passengers of this important information.

12V221

Until your vehicle is remedied, if it is safe and possible to do so, you can prevent the steering wheel from becoming off-centered by centering it when you park before turning the ignition "OFF".

12V245

If you are in a frontal collision before you have this recall repair performed, your brake pedal mount may break off if your foot is on the brake pedal at the moment of impact in order to help protect your leg from injury. However, such breakage may occur in a collision which still allows your vehicle to roll. Therefore, after any collision, set your parking brake to eliminate any possible additional vehicle movement and the risk of a further impact until you can confirm your vehicle's brake is functioning. Failure to do so could result in a secondary impact.

***12V267**

1. Contact your authorized BMW Center immediately to have the necessary repair performed as soon as possible.
2. If you experience loss of power steering assist while driving, pull over carefully as soon as possible to a safe location and away from traffic. Do not continue to drive your vehicle. Contact BMW Roadside Assistance at 1-800-332-4269 immediately to have your vehicle brought to the nearest authorized BMW center
3. If you notice a burning smell or burning and/or smoke from the front of the vehicle, pull over carefully as soon as possible to a safe location and away from traffic. Do not continue to drive your vehicle. Switch off the engine. Do not open the hood. All occupants should carefully exit the vehicle and move to a location away from traffic. Contact BMW Roadside Assistance at 1-800-332-4269 immediately to have your vehicle brought to the nearest authorized BMW center.
4. If you are not the only driver of this vehicle, please advise all other drivers and passengers of this important information.

12V299

We recommend that you keep the sunroof shade fully closed when the vehicle is driven in very cold temperatures (below -4°F / -20°C) until this recall repair has been completed. This will help minimize the chance of broken glass falling into the passenger compartment, should the front sunroof panel break when the vehicle is driven in very cold temperatures (below -4°F / -20°C).

***12V302**

1. Contact your authorized BMW Center immediately to have the necessary repair performed as soon as possible. For customers with a model year 2011 BMW ActiveE please contact your BMW ActiveE center.
2. If you need to locate the nearest authorized BMW ActiveE center, please contact BMW ActiveE customer relations at 1-855-236-1025, or via email at ActiveECustomerRelations@BMWUSA.com you can also contact BMW Roadside specifically for ActiveE at 1-800-497-9940.
3. If you experience a loss of power steering assist while driving, you may continue to drive your vehicle, but drive cautiously and carefully. If you feel uncomfortable with this condition, then you should pull over carefully as soon as possible to a safe location and away from traffic; do not continue to drive your vehicle. Contact BMW Roadside Assistance at 1-800-332-4269 (1-800-497-9940 for ActiveE drivers) immediately to have your vehicle brought to the nearest authorized BMW center / BMW ActiveE center.
4. If the vehicle is experiencing this condition, the warning symbol depicted below will be illuminated yellow in the vehicle's instrument cluster. Please refer to the Description of Problem section above for more details regarding the warning symbol.

5. If you are not the only driver of this vehicle, please advise all other drivers and passengers of this important information.

12V305

Until these important remedies are completed, we request that you take out any removable driver's floor mat, place it in the trunk, and NOT replace it with any other floor mat until the campaign remedy has been implemented on your vehicle.

If you have an optional genuine Lexus All Weather Floor Mat, please bring it to the dealership at the time of your remedy.

In the event you choose not to take out your removable floor mat, Lexus strongly recommends that you ensure that the correct floor mat is being used; you may use the table below to confirm if your vehicle has the most current floor mat part number installed. If your vehicle has the most current floor mat installed ensure that it is properly installed and secured, that it is not flipped over with the bottom-side up, and that one floor mat is not stacked over another. If your vehicle does not have one of these mats properly installed, please remove it immediately.

Floor Mat Type	Color	Correct Part Number
Carpet	Black	PT206-48100-22
	Dark Brown	PT206-48100-09
Carpet (Premium)	Black	PT919-48100-20
	Ivory	PT919-48100-01
	Gray	PT919-48100-12
Lexus All Weather Floor Mat	Black	PT908-48102-02

What should you do if you experience accelerator pedal interference?

Should the vehicle continue to accelerate rapidly after releasing the accelerator pedal, this could be an indication of floor mat interference. If this occurs, Lexus recommends you take the following actions:

First, if it is possible and safe to do so, pull back the floor mat and dislodge it from the accelerator pedal; then pull over and stop the vehicle.

If the floor mat cannot be dislodged, then firmly and steadily step on the brake pedal with both feet. Do NOT pump the brake pedal repeatedly as this will increase the effort required to slow the vehicle.

Shift the transmission gear selector to the Neutral (N) position and use the brakes to make a controlled stop at the side of the road and turn off the engine.

If unable to put the vehicle in Neutral, turn the engine OFF by firmly and steadily pushing the Engine Start/Stop button for at least three seconds. Do NOT tap the Engine Start/Stop button. This will not cause loss of steering or braking control, but the power assist to these systems will be lost.

Please place this letter in your Owner's Manual for future reference.

***12V336**

Until the recall service has been completed, **DO NOT DRIVE YOUR VEHICLE**. Please contact your dealer immediately to make arrangements for your vehicle to be transported to the dealership to have Safety Recall 12S35 performed.

12V353

You can avoid this condition by not fully or almost-fully depressing the accelerator pedal until the vehicle is repaired. Should you experience what you believe is a stuck throttle in this or any other vehicle, you should firmly and steadily apply the brakes without pumping the brake pedal, shift to neutral, steer the vehicle to a safe location and shut the engine off after the vehicle is safely stopped.

12V357

You can temporarily reduce the possibility of this condition occurring by not fully or almost-fully depressing the accelerator pedal until the vehicle is repaired. If you experience what you believe is a stuck throttle in this or any other vehicle, you should firmly and steadily apply the brakes without pumping the brake pedal, shift to neutral, steer the vehicle to a safe location and shut the engine off after the vehicle is safely stopped.

12V373

Until these important remedies are completed, we request that you take out any removable driver's floor mat, place it in the trunk, and **NOT** replace it with any other floor mat until the campaign remedy has been implemented on your vehicle. If you have an optional genuine Lexus All Weather Floor Mat, please bring it to the dealership at the time of your remedy.

In the event you choose not to take out your removable floor mat, Lexus strongly recommends that you ensure that the correct floor mat is being used; you may use the table below to confirm if your vehicle has the most current floor mat part number installed. If your vehicle has the most current floor mat installed ensure that it is properly installed and secured, that it is not flipped over with the bottom-side up, and that one floor mat is not stacked over another. If your vehicle does not have one of these mats properly installed, please remove it immediately.

Should the vehicle continue to accelerate rapidly after releasing the accelerator pedal, this could be an indication of floor mat interference. If this occurs, Lexus recommends you take the following actions:

First, if it is possible and safe to do so, pull back the floor mat and dislodge it from the accelerator pedal; then pull over and stop the vehicle. If the floor mat cannot be dislodged, then firmly and steadily step on the brake pedal with both feet. **DO NOT** pump the brake pedal repeatedly as this will increase the effort required to slow the

vehicle. Shift the transmission gear selector to the Neutral (N) position and use the brakes to make a controlled stop at the side of the road and turn off the engine. If unable to put the vehicle in Neutral, turn the engine OFF by firmly and steadily pushing the Engine Start/Stop button for at least three seconds. Do NOT tap the Engine Start/Stop button. This will not cause loss of steering or braking control, but the power assist to these systems will be lost. Please place this letter in your Owner's Manual for future reference.

12V398

Please maintain the fuel level in your vehicle at ½ tank of fuel, or more, until you have your vehicle inspected by an authorized Infiniti retailer.

12V406

It is advised that you park the vehicle outdoors until it has been remedied.

***12V430**

If you detect the presence of red fluid on the floor at the rear left side of your vehicle or smoke occurring in the same area, please contact your Lamborghini dealer to get your vehicle towed.

12V443

It is recommended that the lift not be used until the corrective procedures associated with this recall are completed.

***12V475**

1. BMW recommends that you do not continue to drive your vehicle. Contact your authorized BMW Center immediately to have the necessary repair performed as soon as possible.
2. If you continue to drive your vehicle and this condition occurs, you may hear a noise and/or feel a vibration coming from the front of the vehicle.
3. If there is a sudden loss of oil pressure, the low oil pressure warning indicator illuminated in red and warning message "Engine oil pressure; Stop carefully" will be displayed in the instrument cluster. An additional warning message will be displayed in the vehicle's control display as follows: "Engine oil pressure too low: Stop carefully and stop engine. Risk of engine damage with continued driving. Call Roadside Assistance."
4. If the condition in #2 or 3 occurs, carefully move away from traffic and pull over to a safe location as soon as possible. Do not continue to drive your vehicle. Contact BMW Roadside Assistance at 1-800-332-4269 immediately to have your vehicle brought to the nearest authorized BMW center.
4. If the vehicle is experiencing this condition, the warning symbol depicted below will be illuminated yellow in the vehicle's instrument cluster. Please refer to the Description of Problem section above for more details regarding the warning symbol.
5. If you are not the only driver of this vehicle, please advise all other drivers and passengers of this important information.

12V486

As a precaution, owners are advised to park outside until the recall repair has been performed.

12V491

In the meantime, do not attempt to make repairs by applying commercially available chemicals (for example, lubricants or cleaners) into the PWMS assembly. Doing so may cause the assembly to smoke, melt or under some circumstances cause a fire. In the event commercially available chemicals have already been applied to the PWMS assembly, please make an appointment with your dealer as soon as possible to have the PWMS assembly inspected.

12V502

Failure to observe the following precautions could increase the risk of vehicle rollaway and may cause personal injury.

1. When parking your vehicle:

- Press the engine Start/Stop button only once to turn off the engine.
- Confirm that the transmission is in Park ("P").
- Please always use the parking brake before exiting the vehicle. Even on what may appear to be a level parking surface, any vehicle left in Neutral (N) without using the parking brake can roll away. Pay attention to any audible warning sounds or visual symbols coming from your vehicle, such as a gong or message on your dashboard.

2. Please consult your Owner's Manual for further information. You may also contact BMW Customer Relations and Services at 1-800-525-7417, or via email at CustomerRelations@bmwusa.com.

3. If you are not the only driver of this vehicle, please advise all other drivers and passengers of this important information.

***12V504**

1. BMW recommends that you do not continue to drive your vehicle. Contact your authorized BMW Center immediately to have the necessary repair performed as soon as possible.

2. If the door does not close or stay latched, do not continue to drive your vehicle. Do not attempt to drive while trying to hold the door closed. Contact BMW Roadside Assistance at 1-800-332-4269 immediately to have your vehicle brought to the nearest authorized BMW center.

3. BMW recommends that you always wear your safety belt, and that all passengers are properly seated and restrained at all times.

4. If you are not the only driver of this vehicle, please advise all other drivers and passengers of this important information.

12V525

Do not use that seating position until the new head restraint is installed.

***12V550**

1. Contact your authorized BMW Center immediately to have the necessary repair performed as soon as possible.
2. If there is a sudden loss of power steering assist, manual steering capability is still retained, although additional effort will be required to steer the vehicle.
3. If there is a sudden loss of power steering assist the alternator warning lam (the battery symbol) will illuminate in the vehicle's instrument cluster, along with the warning message "Charging malfunction." The message, "Charging malfunction: Battery is not recharging. Stop carefully. Consult nearest service center." Will also be displayed.
4. If you experience loss of power steering assist while driving, pull over carefully as soon as possible to a safe location and away from traffic. Do not continue to drive your vehicle. Contact BMW Roadside Assistance at 1-800-332-4269 immediately to have your vehicle brought to the nearest authorized BMW center
5. If you are not the only driver of this vehicle, please advise all other drivers and passengers of this important information.

12V602

There are several important precautions owners of vehicles equipped with optional puddle lights should take until this repair has been performed:

- If you notice or smell smoke in the left or right rocker panel area of the vehicle, be sure the ignition switch is in the "off" position and do not operate the vehicle. Immediately contact your Subaru dealer for assistance.
- As a precautionary measure, it is highly recommended that you not park your vehicle in a garage, car port or other structure.

Appendix B-3

2011 Recalls with Risk Mitigation Instructions in Part 577 letters

Recalls that contain Do Not Drive instructions are starred with an asterisk (*) in this appendix. 2011 Recalls with Do Not Drive instructions also appear separately in appendix A-3, however, they are included here so that this appendix can stand alone as the complete list of Risk Mitigation Instructions. The text for each recall in this appendix is taken from Owner Notification Letters (Part 577).

***11V007**

Contact your GM dealer immediately for additional information and instructions regarding this recall.

11V112

Until the remedy parts are available, you may minimize the possibility of this condition occurring by verifying that the forward Retention Clip is properly installed and the Floor Carpet Cover is not leaning. The location of the forward retention clip is depicted in the diagram. If you are not comfortable conducting the inspection, any Toyota dealer will be happy to perform the interim inspection at no charge.

11V113

Until these important remedies are completed, we request that you take out any removable driver's floor mat, place it in the trunk, and NOT replace it with any other floor mat until the campaign remedy has been implemented on your vehicle. If you have an optional genuine Lexus All Weather Floor Mat, please bring it to the dealership at the time of your remedy. In the event you choose not to take out your removable floor mat, Lexus strongly recommends that you ensure that the correct floor mat is being used, that it is properly installed and secured, that it is not flipped over with the bottom-side up, and that one floor mat is not stacked over another. Please visit <http://www.lexus.com/floormats> for additional information. What should you do if you experience accelerator pedal interference? Should the vehicle continue to accelerate rapidly after releasing the accelerator pedal, this could be an indication of floor mat interference. If this occurs, Lexus recommends you take the following actions: First, if it is possible and safe to do so, pull back the floor mat and dislodge it from the accelerator pedal; then pull over and stop the vehicle. If the floor mat cannot be dislodged, then firmly and steadily step on the brake pedal with both feet. Do NOT pump the brake pedal repeatedly as this will increase the effort required to slow the vehicle. Shift the transmission gear selector to the Neutral (N) position and use the brakes to make a controlled stop at the side of the road and turn off the engine. If unable to put the vehicle in Neutral, turn the engine OFF by firmly and steadily pushing the Engine Start/Stop button for at least three seconds. Do NOT tap the Engine Start/Stop button. This will not cause loss of steering or braking control, but the power assist to these systems will be lost. Please place this letter in your Owner's Manual for future reference.

11V139

Until this repair is completed, the vehicle can be driven. However, as a precaution, all drivers are advised to remove all objects from the FOB/K (such as additional keys, key chains, etc.) and ensure that the FOB/K is securely and correctly aligned in the "On" position and not aligned between the "On" and "Accessory" position before driving the vehicle.

11V151

Until this repair has been completed, affected vehicles can continue to be driven as usual. However, as a precaution, customers are advised to remove all objects from the key fob (such as additional keys, key chains, etc.). This may help lessen the likelihood that the vehicle will experience the problem described in this recall. Additionally, the driver should ensure that the key is securely and correctly positioned in the RUN position before driving the vehicle.

***11V153**

IMPORTANT NOTICE: Always engage the parking brake when placing your vehicle in Park. This is especially important until you can take your vehicle to the dealer to have this campaign performed.

11V245

You may reduce the risk of injury by having all occupants properly seated with their seat belts fastened, including all infant and child occupants fastened in child restraints, prior to turning on the vehicle ignition. All vehicle occupants should remain properly seated with their seat belts fastened while the vehicle is in operation. In addition, please pay close attention to the air bag warning light. The air bag warning light is designed to come on, during the ignition cycle check function, when the engine switch is turned to the "ON" position. The light then goes off after about 6 seconds. This means the system is operating as designed. If the airbag warning light (1) illuminates or remains illuminated after this 6 second check period, or (2) comes on while driving, or (3) at times previously stayed illuminated while driving, please contact your local Toyota dealer immediately for diagnosis and appropriate repair. If the problem is related to the issue addressed by this recall, the repair will be performed at no charge to you.

11V285

The necessary replacement work will take approximately 1.5 to 3 hours to perform and will be done at no cost to you. Until you have had this work performed, do not use your vehicle on the race course or for any competitive event. If you have used your vehicle for such events, Porsche recommends extreme caution driving your vehicle until the new hubs have been installed. If you do not wish to drive your vehicle during this period, Porsche will compensate you for alternate transportation. Porsche also has issued revised instructions for the usage of your center-locking wheels. Enclosed with this letter is a supplementary insert for your Porsche Owner's Manual. Please familiarize

yourself with its contents. The new page has an adhesive backing. It should be affixed in the “Practical Tips, Emergency Service” section in your Owner’s Manual. If you prefer, please bring the new Owner’s Manual page with you when you bring your Porsche vehicle to your authorized Porsche dealer to have this recall service performed. They will be pleased to affix the supplementary insert for you.

***11V332**

If you experience stalling while driving, pull over carefully as soon as possible to a safe location and away from traffic. Do not continue to drive your vehicle. Contact BMW Roadside Assistance at 1-800-332-4269 immediately to have your vehicle brought to the nearest authorized BMW center. BMW recommends that you always wear your safety belt, and that all passengers are properly seated and restrained at all times. If you are not the only driver of this vehicle, please advise all other drivers and passengers of this important information.

***11V341**

If you experience a loss of power steering assist while driving, a yellow warning symbol in the instrument cluster will illuminate, accompanied by a short message in the instrument cluster to drive moderately. You may continue to drive your vehicle, but drive cautiously and carefully. If you feel uncomfortable with this condition then you should pull over carefully as soon as possible to a safe location and away from traffic; do not continue to drive your vehicle. Contact BMW Roadside Assistance at 1-800-332-4269 immediately to have your vehicle brought to the nearest authorized BMW center. BMW recommends that you always wear your safety belt, and that all passengers are properly seated and restrained at all times. If you are not the only driver of this vehicle, please advise all other drivers and passengers of this important information.

***11V438**

If one of the tail lamp warning symbols appear (4), please drive carefully and cautiously, as the driver of the vehicle behind you may not notice that one of the rear lamps are not working. If this condition is present, and if you feel unsafe, please contact BMW Roadside Assistance at 1-800-332-4269 immediately to have your vehicle brought to the nearest authorized BMW center. BMW recommends that you always wear your safety belt, and that all passengers are properly seated and restrained at all times. If you are not the only driver of this vehicle, please advise all other drivers and passengers of this important information.

***11V441**

If you encounter a non-starting condition, your vehicle may be experiencing this condition. Contact BMW Roadside Assistance at 1-800-332-4269 immediately to have your vehicle brought to the nearest authorized BMW center. BMW recommends that you always wear your safety belt, and that all passengers are properly seated and restrained at all times. If you are not the only driver of this vehicle, please advise all other drivers and passengers of this important information.

11V467

There are two important precautions you should take until this repair has been performed: Do not operate the moonroof. It should be left in the fully closed position. If you notice that the moonroof glass is loose, do not operate the vehicle. Immediately contact your Subaru dealer for assistance.

***11V469**

There are several important precautions you should take until this repair has been performed: Be sure the cowl area where the windshield wipers park, when turned off, is free of any obstructions. If you notice or smell smoke in the front cowl area of the vehicle, be sure the ignition switch is in the “off” position and do not operate the vehicle. Immediately contact your Subaru dealer for assistance. As a precautionary measure, it is highly recommended that you not park your vehicle in a garage, car port or other structure.

11V473

Always have your front passenger wear his or her seatbelt. Seatbelts are the most important safety device available. Children under 12-years old and younger should sit in the backseat, using age-appropriate and size-appropriate child seats, boosters and seatbelts as warranted for the particular seat. Additional information on child passenger safety and seating positions is available to the public at www.safercar.gov. When an adult is in the front passenger seat, and after starting your engine, check the center instrument panel to see if the “PASSENGER AIRBAG OFF” light is illuminated. If the PASSENGER AIRBAG OFF light is illuminated with an adequately sized adult present, reset the OCS by either turning the engine off and on, or having the passenger get off the seat cushion for 3 seconds. Then have the front passenger sit “with the seat in an upright position, centered on the seat cushion, with the person’s legs comfortably extended, feet on the floor, and wearing the safety belt properly” as provided by the Owner’s Manual. Classification of the front passenger should occur immediately, but can take as long as 15 seconds with certain persons, and occasionally as long as 30 seconds to complete. (Longer is possible in very cold weather). After this classification, the front passenger can adjust his or her seating position without changing the working status of the airbag, so long as the engine remains on and the occupant does not get completely off of the seat cushion.

***11V476**

If this condition is occurring, pull over carefully as possible to a safe location and away from traffic. Do not continue to drive your vehicle. Contact BMW Roadside Assistance at 1-800-332-4269 immediately to have your vehicle brought to the nearest authorized BMW center. BMW recommends that you always wear your safety belt, and that all passengers are properly seated and restrained at all times. If you are not the only driver of this vehicle, please advise all other drivers and passengers of this important information.

***11V510**

Prior to the issue of the campaign, we recommend that you monitor your vehicle closely for indications of oil leaks. If an oil cooler line failure occurs the driver may observe one or more of the following warning signs: (1) Oil pressure warning light illuminated whilst the engine is running; (2) Signs of oil under the front or rear of the vehicle whilst the vehicle is parked; (3) Excessive oil consumption; (4) Trail of oil on the road; If you observe any of the above before driving, do not drive the car and contact your Lotus dealer. If your oil pressure warning light illuminates whilst driving, or if you have any other reason to suspect that an oil line has become detached, stop your vehicle immediately in a safe and controlled manner and contact your Lotus dealer.

***11V521**

PRECAUTIONS FOR YOUR SAFETY 1. CONTACT YOUR AUTHORIZED BMW CENTER IMMEDIATELY TO HAVE THE NECESSARY REPAIR PERFORMED AS SOON AS POSSIBLE. 2. If the water pump fails, or if there is a reduction in engine cooling, a warning message will, in most cases, appear in the instrument cluster's "message center" during driving and when stopping the vehicle. 3. In some cases, a plastic burning smell, or burning and/or smoke from the front of the vehicle may be noticed. Should any of these warnings occur, pull off the road to a safe location away from traffic, and switch off the engine. If you notice a plastic burning smell, or burning and/or smoke from the front of the vehicle, do not open the hood. All occupants should carefully exit the vehicle and move to a location away from traffic. Do not continue to drive your vehicle. Contact BMW Roadside Assistance at 1-800-332-4269 immediately to have your vehicle brought to the nearest Authorized BMW Center. 4. BMW recommends parking your vehicle outdoors until repairs have been performed. 5. BMW recommends that you always wear your safety belt, and that all passengers are properly seated and restrained at all times. 6. If you are not the only driver of this vehicle, please advise all other drivers and passengers of this important information.

***11V522**

PRECAUTIONS FOR YOUR SAFETY 1. CONTACT YOUR AUTHORIZED ROLLS-ROYCE DEALER IMMEDIATELY TO HAVE THE NECESSARY REPAIR PERFORMED AS SOON AS POSSIBLE. 2. If the water pump fails, or if there is a reduction in engine cooling, a warning message will, in most cases, appear in the instrument cluster's "message center" during driving and when stopping the vehicle. 3. In some cases, a plastic burning smell, or burning and/or smoke from the front of the vehicle may be noticed. Should any of these warnings occur, pull off the road to a safe location away from traffic, and switch off the engine. If you notice a plastic burning smell, or burning and/or smoke from the front of the vehicle, do not open the hood. All occupants should carefully exit the vehicle and move to a location away from traffic. Do not continue to drive your vehicle. Contact Rolls-Royce Roadside Assistance at 1-877-671-3039 immediately to have your vehicle brought to the nearest Authorized Rolls Royce Dealer. 4. Rolls-Royce recommends parking your vehicle outdoors until repairs have been performed. 5. Rolls-Royce

recommends that you always wear your safety belt, and that all passengers are properly seated and restrained at all times. 6. If you are not the only driver of this vehicle, please advise all other drivers and passengers of this important information.

11V562 If the brake master cylinder were to malfunction, brake pedal travel distance will increase. The driver might misjudge the amount of brake pedal travel required to achieve the desired stopping distance, increasing the risk of a crash. There are several important precautions you should take until this repair has been performed: If you experience the condition described above while braking, continue to apply steady pressure on the brake pedal until the vehicle comes to a stop. Immediately contact your Subaru dealer for assistance. Always maintain a safe distance from other vehicles while driving. The normally recommended minimum distance is one car length of space for every 10 mph of speed. As a precautionary measure, it is highly recommended that you use extra care while operating the vehicle in confined areas such as parking lots and while parking your vehicle in a garage, car port or other structure.

11V591

Please follow the instructions shown in your vehicle's Owner Manual when using the "M" or manual mode. For your convenience, a copy of these instructions can be found on the reverse side of this letter. We also recommend that you upshift regularly to avoid driving in manual mode and first gear for more than 5 minutes at an engine speed of 4,000 RPM or more.

***11V598**

If you choose to charge and/or drive your vehicle prior to having this service performed, please be aware of this condition. For your convenience, or, if you are not comfortable using the vehicle before the battery has been replaced, your Fisker retailer will arrange to pick up your vehicle and return it to you after it has been serviced.

Appendix B-4

2010 Recalls with Risk Mitigation Instructions in Part 577 letters

Recalls that contain Do Not Drive instructions are starred with an asterisk (*) in this appendix. Recalls with Do Not Drive instructions also appear separately in appendix A-4, however, they are included here so that this appendix can stand alone as the complete list of Risk Mitigation Instructions. The text for each recall in this appendix is taken from Owner Notification Letters (Part 577).

***10V018**

Do not place these, or any other floor mats, in the driver's side footwell. In the event that you choose to install the driver's side floor mat, General Motors strongly recommends that you use only floor mats designed specifically for the model and model year of your vehicle, and that it is properly installed and secured. DO NOT use a mat that is flipped over with the bottom-side up, and DO NOT stack one floor mat over another. In addition, check the operation of the accelerator, brake, and clutch (if applicable) pedals to assure that the floor mat does not interfere with them.

10V023

Take out any removable driver's floor mat, place it in the trunk, and NOT replace it with any other floor mat until the campaign remedy has been implemented on your vehicle.

10V024

Take out any removable driver's floor mat, place it in the trunk, and NOT replace it with any other floor mat until the recall remedy has been performed on your vehicle.

10V025

Avoid extreme driving maneuvers at high speed, e.g., fast lane changes. BMW recommends that you always wear your safety belt, and that all passengers are properly seated and restrained at all times. If you are not the only driver of this vehicle, please advise all other drivers and passengers of this important information.

10V047

The rear seating row of your vehicle should be occupied by at most, two (2) persons. BMW recommends that you always wear your safety belt, and that all passengers are properly seated and restrained at all times. If you are not the only driver of this vehicle, please advise all other drivers and passengers of this important information.

***10V072**

If you experience any unusual looseness in your brake pedal, do not drive your vehicle and call your dealer or Infiniti Consumer Affairs at 1-800-662-6200 for further instructions.

10V074

It is important that you continue to maintain the fuel level in your vehicle so that the fuel gauge reads above the one half position until your service appointment.

10V075

...please maintain the fuel level in your vehicle so that the fuel gauge reads above the one half position.

10V138

We strongly recommend you not park your vehicle in a garage...

10V152

BMW recommends that you always wear your safety belt, and that all passengers are properly seated and restrained at all times. If you are not the only driver of this vehicle, please advise all other drivers and passengers of this important information.

10V175

If a RED air bag warning light located in your instrument cluster illuminates together with the YELLOW "Pass Air Bag Off" status light (located in the center display next to the clock) and stays on for longer than a few seconds, the passenger airbag in your vehicle will not operate. If this happens, you should take your car to an Infiniti dealer for repair as soon as possible, and you should not let anyone ride in the front passenger seat until the dealer has repaired your vehicle. If a YELLOW "Pass Air Bag Off" status light (located in the center display next to the clock) illuminates, but the RED air bag warning does not, this is normal and does not mean that that (sic) the passenger air bag is malfunctioning (see your Owners Manual). However, you should still bring your vehicle for repair at your earliest convenience.

10V176

In order to prevent this condition, after the vehicle battery is removed or replaced, drive the vehicle straight ahead at 10 mph or more for greater than 5 seconds, and at the very first vehicle stop, wait for more than 3 seconds before turning the ignition switch off. This should allow sufficient time for the Skid Control ECU to store the center position of the Steering Angle Sensor correctly.

***10V196**

If you notice a fluid leak, do not operate the vehicle. Immediately contact your Subaru dealer for assistance. If you notice a loss of power, carefully steer the vehicle to a safe place on the side of the road. Turn the ignition off and do not operate the vehicle. Immediately contact your Subaru dealer for assistance.

***10V215**

If you detect the odor of fuel or observe fuel on the ground, please contact your Lamborghini dealer to get your vehicle towed to service.

10V222

Remember to apply the parking brake whenever exiting your vehicle.

10V233

Should you need to adjust the tire pressure, please consult your vehicle's Owner's Manual for the correct pressure based upon your vehicle's specific tire size. You will find the tire size stamped on the sidewall of the tire. BMW recommends that you always wear your safety belt, and that all passengers are properly seated and restrained at all times. If you are not the only driver of this vehicle, please advise all other drivers and passengers of this important information.

10V254

BMW recommends that you always wear your safety belt, and that all passengers are properly seated and restrained at all times. If you are not the only driver of this vehicle, please advise all other drivers and passengers of this important information.

***10V326**

There are several important precautions you should take until this recall has been performed: If you notice a groaning sound coming from the transmission area while driving, discontinue use of the vehicle and immediately contact your Subaru dealer for assistance. If you notice a loss of power, carefully steer the vehicle to a safe place on the side of the road. Turn the ignition off and do not operate the vehicle. Immediately contact your Subaru dealer for assistance.

***10V331**

Review the odometer reading in the instrument cluster to track miles traveled and fill up every 200 miles or less. Before having the repair performed, drive to the nearest gas station and refuel your car. If you experience stalling while driving, pull over carefully as soon as possible to a safe location and away from traffic. Do not continue to drive your vehicle. Contact BMW Roadside Assistance at 1-800-332-4269 immediately to have your vehicle brought to the nearest authorized BMW center. BMW recommends that you always wear your safety belt, and that all passengers are properly seated and restrained at all times. If you are not the only driver of this vehicle, please advise all other drivers and passengers of this important information.

10V374

If power steering assist becomes inoperable, the power steering malfunction indicator light illuminates. Steering is still possible, but requires more physical effort. Should this situation occur, pull safely to the side of the road and turn off the engine. After a short period of time restart the engine. The power steering malfunction indicator light may go out, and power steering assist may return. Should you experience this condition, please contact an authorized Mazda dealer.

10V392

If it is determined that your nüvi is affected by this recall, you must immediately stop using the device until after Garmin has completed the recall service. Do not attempt to remove the battery yourself. Promptly discharge the battery in any recalled unit to eliminate the possibility of overheating. To safely discharge the battery, perform the following actions in order: (1) Disconnect the unit from the mounting on the dash. (2) Turn on the unit. The top right corner of the main menu displays the battery symbol and indicates the current battery charge level. (3) With the unit in the on position, allow the unit to completely discharge until the unit shuts off. (4) Do not recharge or continue to use the recalled unit.

10V401

DO NOT USE THE GPS UNIT. We urge you to go to the Garmin website immediately to check if your Garmin nüvi® 750 portable GPS unit is affected by entering the serial number located on the bottom of your unit. If your unit is affected, please follow the remedy instructions provided on the Garmin website: www.garmin.com/nuvibatterypcbrecall. You may also call the Garmin 800 Number (866 957-1981) to determine if your GPS unit is affected and receive instructions on how to have it repaired. Customers should not go to the Nissan dealer to have their GPS unit repaired.

10V436

If your vehicle is not drivable due to corrosion in the bracket area, please call Honda Automobile Customer Service at 1-800-999-1009, and select option 4, to arrange to have your vehicle transported to a Honda dealership to be inspected and to receive an appropriate remedy.

***10V446**

In the event you notice a decrease in power brake assist, do not continue to drive your vehicle. Immediately contact BMW Roadside Assistance at 1-800-332-4269 or your nearest authorized BMW center to have your vehicle brought to an authorized BMW center.

***10V447**

In the event you notice a decrease in power brake assist, do not continue to drive your vehicle. Immediately contact Rolls-Royce Roadside Assistance at 1-877-671-3029, or your nearest authorized Rolls-Royce dealer, to have your vehicle brought to an authorized Rolls-Royce dealer.

10V499

In the event the brake warning light has illuminated and/or you notice the feel of the brake pedal change, please verify the brake fluid level in the reservoir. If the brake fluid

level is low it is an indication that brake fluid is leaking. Please add DOT3 brake fluid and make an appointment to have this remedy completed immediately.

***10V518**

If you experience engine stalling while driving, pull over carefully as soon as possible to a safe location and away from traffic. Do not continue to drive your vehicle. Contact BMW Roadside Assistance at 1-800-332-4269 immediately to have your vehicle brought to the nearest authorized BMW SAV center.

10V566

Please stop using your Garmin portable GPS device immediately, and visit the Garmin website below to determine if your unit is affected. Vehicle owners should not visit a Volvo retailer for this Garmin recall repair. www.garmin.com/nuvibatterypcbrecall.

10V575

Please place the enclosed Owner Manual Supplement in your Owner Manual in the Seats and Restraint section for future reference. Because a child in a child restraint in the front center seat position can be seriously injured or killed by the frontal airbags if they inflate, Isuzu does not recommend installing child restraints in the front center seat position.

***10V599**

Immediately check the Low Brake Fluid Level Warning Light on your instrument panel. If it is illuminated, DO NOT DRIVE your vehicle. Contact Kia Roadside Assistance (800) 333-4KIA (4542) to have your vehicle towed to the nearest Kia dealer at no cost to you. If the Low Brake Fluid Level Warning Light is NOT illuminated, please contact your Kia dealer as soon as possible to schedule a service appointment. The actual time required to repair your vehicle can vary depending on the dealer's work load, therefore, we recommend scheduling a service appointment to minimize inconvenience. Please present this notice to your dealer at the time of your appointment.

***10V613**

Until you have your vehicle inspected, frequently look at the Low Brake Fluid Level Warning Lamp on the instrument panel. If the warning lamp turns on and remains on, carefully drive to the nearest safe location and park your vehicle. DO NOT CONTINUE TO DRIVE your vehicle if the Low Brake Fluid Level Warning Lamp turns on and remains on. Contact Hyundai Roadside Assistance at 1-800-243-7766 to have your vehicle towed to the nearest Hyundai dealer at no charge to you.

10V620

Prior to your appointment, please be aware of the close proximity of the stop lamp switch bracket to the parking brake pedal, shown in the diagram below. You may minimize the possibility of this condition occurring until the remedy is performed by assuring the bracket is not bent. We apologize for any inconvenience created by this condition.

10V621

Affected vehicles can continue to be driven as usual, but if you can smell fuel in the vehicle proceed immediately to the nearest authorized Volkswagen dealer or qualified workshop if you believe that it is safe to do so in order to have the fuel system on the vehicle inspected.

10V643

If your vehicle has not been serviced for the safety issue described in this letter, **DO NOT DRIVE YOUR VEHICLE**. Contact your GM dealer immediately for additional information and instructions regarding this recall.

Appendix B-5

2009 Recalls with Risk Mitigation Instructions in Part 577 letters

Recalls that contain Do Not Drive instructions are starred with an asterisk (*) in this appendix. 2009 Recalls with Do Not Drive instructions also appear separately in appendix A-5, however, they are included here so that this appendix can stand alone as the complete list of Risk Mitigation Instructions. The text for each recall in this appendix is taken from Owner Notification Letters (Part 577).

***09V048**

If the convertible top warning light illuminates or any fluid is seen leaking from under the car, please stop driving the vehicle immediately and avoid driving it until the repairs described below have been performed.

09V093

Affected vehicles can continue to be driven as usual, but If you can smell fuel in your vehicle, customers are advised to proceed immediately to the nearest authorized Volkswagen dealer or qualified workshop if they believe that it is safe to do so in order to have the fuel system on the vehicle inspected.

09V116

There are two very important precautions you should take before your vehicle is serviced:

- We strongly recommend you do not park your vehicle in a garage, car port, or other structure.
- If you notice a burning odor, you should have your GM dealer inspect your vehicle immediately. The dealer will inspect your vehicle without charge.

***09V130**

Important Notice: If you currently have any of the problems indicated by the bullet points above,

Please immediately contact your Kia dealer to have the repair conducted. Under such circumstances, you may request that your vehicle be towed to the nearest Kia dealer at no cost to you by phoning Kia Roadside Assistance at (800) 333-4KIA (4542).

09V143

You may continue to drive your vehicle; however, you must have this problem corrected immediately. PRECAUTIONS

1. CONTACT YOUR AUTHORIZED MINI DEALER IMMEDIATELY TO HAVE THE NECESSARY REPAIR PERFORMED AS SOON AS POSSIBLE.
2. MINI recommends that you always wear your safety belt, and that all passengers are properly seated and restrained at all times.
3. If you are not the only driver of this vehicle, please advise all other drivers and passengers of this important information.

***09V155**

You should not operate your vehicle until your Chevrolet dealer has had the opportunity to inspect and repair your vehicle.

***09V164**

Affected vehicles can continue to be driven as usual, but If a knocking sound s heard coming from beneath the vehicle, customers should stop driving and have the vehicle inspected by an authorized Volkswagen dealer as soon as possible.

***09V183**

If your vehicle is experiencing significant misalignment involving pulling to the right, other steering stress while driving, rapid or unusual tire wear or you hear noises you cannot identify coming from the front end, schedule an appointment immediately. The time required to inspect and repair your vehicle can vary depending upon the dealer's work schedule, therefore an appointment is recommended. Please present this notice when you arrive at the dealer.

- Inspect your front wheels after setting them in a straight ahead position. If you observe that your front wheels are visibly tilted either inward or outward or if they are not pointing in the same direction, do not drive your vehicle. Contact the Customer Assistance Center at the telephone number provided below, and they will arrange for your vehicle to be towed to the closest Kia dealer for inspection.

- Read the information and follow the instructions in the "Underbody Maintenance" section of your owner's manual regarding the ongoing maintenance and cleaning of the underbody of your vehicle to limit the effects of road salt conditions in the future. These instructions are also provided on the enclosed insert card, which you should place in your glove compartment for easy reference.

09V187

Unless your DSC light is illuminated continue to drive your Mazda3 vehicle until the recall is performed. If your DSC light is on please contact an authorized Mazda dealer.

09V223

Please assist us by affixing the enclosed Addendum Label to your vehicle. Installation instructions are located on the following page.

09V234000

Apply the enclosed labels and owner's manual inserts using the provided instructions. If you are not comfortable installing the provided materials, please contact any authorized Toyota dealer to schedule an appointment to have the materials applied at NO CHARGE to you. If you prefer to have a new certification label instead of the certification addendum label please contact your authorized Toyota dealer. You will need to provide the dealer with the VIN number so the dealership can order the replacement certification label. It will take several days for the dealer to receive the label; once it is

received the dealer will contact you to schedule an appointment to have the new label applied at NO CHARGE to you.

09V244000

You may choose to install this insert into your vehicle's owner's manual yourself, or if you prefer, you may have the insert installed by your authorized Volkswagen dealer free of charge. Precautions you should take: As with any airbag-equipped vehicle, people should refrain from placing objects over or near the airbag on the instrument panel, because any such objects could cause harm if the vehicle is in a crash severe enough to cause the airbag to inflate.

09V255000

You may continue to drive your vehicle; however, you must have the problem corrected immediately. Failure to observe the following precautions, in conjunction with traffic and road conditions, and the driver's reactions, could increase the risk in the the event of a crash.

PRECAUTIONS:

1. CONTACT YOUR AUTHORIZED BMW CENTER IMMEDIATELY TO HAVE THE NECESSARY REPAIR PERFORMED AS SOON AS POSSIBLE.
2. BMW recommends that you always wear your safety belt, and that all passengers are properly seated and restrained at all times.
3. If you are not the only driver of this vehicle, please advise all other drivers and passengers of this important information.

09V257000

You may continue to drive your vehicle; however, you must have the problem corrected immediately. Failure to observe the following precautions, in conjunction with traffic and road conditions, and the driver's reactions, could increase the risk in the the event of a crash.

PRECAUTIONS FOR YOUR SAFETY

1. CONTACT YOUR AUTHORIZED BMW CENTER IMMEDIATELY TO HAVE THE NECESSARY REPAIR PERFORMED AS SOON AS POSSIBLE.
2. IF YOU NOTICE ILLUMINATION OF THE AIR BAG WARNING LAMP IN THE INSTRUMENT CLUSTER, YOUR VEHICLE MAY BE EXPERIENCEING THIS PROBLEM. CONTACT YOUR AUTHORIZED BMW CENTER IMMEDIATELY TO HAVE THE VEHICLE CHECKED AND SERVICED WITHOUT DELAY.
3. IF YOU NOTICE ILLUMINATION OF THE AIR BAG WARNING LAMP, BMW RECOMMENDS THAT YOU NOT USE THE FRONT PASSENGER SEAT UNTIL THE VEHICLE HAS BEEN SERVICED.
4. BMW recommends that you always wear your safety belt, and that all passengers are properly seated and restrained at all times.
5. If you are not the only driver of this vehicle, please advise all other drivers and passengers of this important information.

***09V277**

There are two important precautions you should take until this repair has been performed:

- It is highly recommended that you not park your vehicle in a garage, car port or other structure.
- If you notice the smell of gasoline, do not operate the vehicle. Immediately contact your Subaru dealer for assistance.

09V327

You may continue to drive your vehicle; however, you must have the problem corrected immediately. Failure to observe the following precautions, in conjunction with traffic and road conditions, and the driver's reactions, could increase the risk in the event of a crash.

PRECAUTIONS FOR YOUR SAFETY

1. CONTACT YOUR AUTHORIZED BMW CENTER IMMEDIATELY TO HAVE THE NECESSARY REPAIR PERFORMED AS SOON AS POSSIBLE.
2. IF YOU NOTICE ILLUMINATION OF THE AIR BAG WARNING LAMP IN THE INSTRUMENT CLUSTER, YOUR VEHICLE MAY BE EXPERIENCEING THIS PROBLEM. CONTACT YOUR AUTHORIZED BMW CENTER IMMEDIATELY TO HAVE THE VEHICLE CHECKED AND SERVICED WITHOUT DELAY.
3. IF YOU NOTICE ILLUMINATION OF THE AIR BAG WARNING LAMP, BMW RECOMMENDS THAT YOU NOT USE THE FRONT PASSENGER SEAT UNTIL THE VEHICLE HAS BEEN SERVICED.
4. BMW recommends that you always wear your safety belt, and that all passengers are properly seated and restrained at all times.
5. If you are not the only driver of this vehicle, please advise all other drivers and passengers of this important information.

09V343

Please note: If you experience the condition above prior to having this recall completed, the vehicle can be restarted by turning the ignition off and waiting one minute before restarting the engine.

09V388

Until these important remedies are completed, we request that you take out any removable driver's floor mat, place it in the truck, and NOT replace it with any other floor mat until the campaign remedy has been implemented on your vehicle. In the event that you choose not to take out your removable floor mat, Toyota strongly recommends that you ensure that the correct floor mat is being used, that it is properly installed and secured, that it is not flipped over with the bottom-side up, and that one floor mat is not stacked over another.

09V399

Until you have the recall service performed, park your vehicle outdoors away from structures to prevent a potential fire from spreading.

09V414

Until you have the recall service performed, park your vehicle away from structures to prevent a potential fire from spreading.

***09V431**

If you notice that the Brake Warning Light in your Sentra is illuminated, we strongly urge you to immediately check the brake fluid level in your vehicle and add additional DOT 3 brake fluid if necessary. The instructions are in Section 8 of your Owner's Manual. Do not continue driving with the Low Brake Fluid Warning Light on.

09V436

Please place the addendum letter in the Owner's Manual of your vehicle for reference by you or future owners.

09V444

If you have not experienced this condition, please insert this letter into your Toyota Owner's Manual Supplement or Owner's Warranty Information booklet or in the vehicle's glove box for future reference.

09V468

Please tell the dealer if you have noticed any smell of gasoline in the past when starting up in cold weather.

09V474

1. MINI recommends that you always wear your safety belt, and that all passengers are properly seated and restrained at all times.
2. If you are not the only driver of this vehicle, please advise all other drivers and passengers of this important information.

09V480

The three labels for your vehicle are enclosed. To reduce your inconvenience, you can install the labels easily by following the enclosed instructions. If you desire, however, you may take the labels to your dealer for installation within the next 60 days. This service will be performed for you at no charge. If you would like your dealer to install the labels, you should contact your GM dealer to arrange a service appointment as soon as possible. Bring the labels with you when you visit your dealer.

Appendix B-6

2008 Recalls with Risk Mitigation Instructions in Part 577 letters

Recalls that contain Do Not Drive instructions are starred with an asterisk (*) in this appendix. 2008 Recalls with Do Not Drive instructions also appear separately in appendix A-6, however, they are included here so that this appendix can stand alone as the complete list of Risk Mitigation Instructions. The text for each recall in this appendix is taken from Owner Notification Letters (Part 577).

08V082

We urge you to have this recall performed as soon as possible. **However, in the meantime, you can eliminate any real world risk associated with this noncompliance by making certain that the front seat passenger is wearing a safety belt and that the seat is positioned rearward, away from the airbag.** Ford recommends that all vehicle occupants always wear a safety belt.

08V118

There are two very important precautions you should take before your vehicle is serviced:

- We strongly recommend you not park your vehicle in a garage, car port, or other structure.
- If you notice a burning odor, you should have your GM dealer inspect your vehicle immediately. The dealer will inspect your vehicle without charge.

For your continued satisfaction with your vehicle, you should know:

- Your vehicle requires premium fuel (91 octane or higher). as stated in your vehicle owner's manual. Exhaust manifold temperatures are higher if regular fuel is used.
- Gaskets, including the new front rocker cover gasket that will be installed in your vehicle, eventually may need replacement. If oil seepage is observed, see your dealer for this regular maintenance.

08V135

In the meantime, until the tailgate stay hardware has been inspected and, if necessary repaired, we recommend that you remain alert for the condition and safety hazard described in this letter and take appropriate precautions when operating the tailgate. If one or both of the tailgate stays is currently detached from the tailgate, it is recommended that you not operate the tailgate until it has been repaired by your Subaru dealer.

08V161

You should make sure that adult passengers seated in the right front seat always sit upright with the seatback in an upright position, centered on the seat cushion, with the seat belt on and legs comfortably extended. This will help the OCS to recognize the seated occupant as an adult.

If your vehicle's "PASSENGER AIR BAG OFF" lamp illuminates while the right front seat is occupied by an adult or if your vehicle's "AIR BAG" warning lamp is illuminated, we urge you to call your Hyundai dealer to schedule an appointment to have this work performed as soon as possible.

08V170

PRECAUTIONS

1. CONTACT YOUR AUTHORIZED BMW SAV CENTER IMMEDIATELY TO HAVE THE NECESSARY REPAIR PERFORMED AS SOON AS POSSIBLE.
2. AVOID EXTREME DRIVING MANEUVERS AT HIGH SPEED, E.G., FAST LANE CHANGES.
3. Should you need BMW Roadside Assistance, they can be contacted at 1-800-332-4269.
4. BMW recommends that you always wear your safety belt, and that all passengers are properly seated and restrained at all times.
5. If you are not the only driver of this vehicle, please advise all other drivers and passengers of this important information.

08V181

Owners are requested to contact their local Toyota dealer for diagnosis and repair. Until this Safety Recall is completed, please advise the customer continue to restrain children utilizing a properly installed CRS in the second row seat or utilize a CRS which does not have a short belt path in the third row seats.

08V200

At least until your vehicle is serviced, please apply the parking brake every time you park your vehicle.

***08V214**

If the clutch sensor warning light illuminates, please stop driving the vehicle immediately and avoid driving it until the repairs described below have been performed.

08V235

Precautions You Should Take: Your vehicle can be driven until the inspection/repair is conducted. However, to minimize the possibility of engine surge, do not operate the air conditioning in your vehicle until the recall work has been performed.

08V244000

Even after you receive your replacement struts, you need to pay attention to the condition of your liftgate. Toyota is providing the following operational instructions and warnings for continued usage of the Rear Liftgate:

- Please be sure to wait at least an additional 2 seconds from the time the liftgate is in the fully opened position prior to standing under it.

- In the event your Power Liftgate Strut(s) performance has degraded, your liftgate will automatically close with an audible alarm and flashing of the hazard lamps. The Toyota Sienna Power Rear Liftgate is equipped with jam and pinch protection which also includes auto reversal of the Rear Liftgate. Please use your best judgment about the condition of your Rear Liftgate and obtain repairs promptly if the liftgate appears to show degradation.
- Refer to your Owner's Manual for additional operating instructions.

***08V311000**

If you notice that the Brake Warning Light in your Sentra is illuminated, we strongly urge you to immediately check the brake fluid level in your vehicle and add additional DOT 3 brake fluid if necessary. The instructions are in Section 8 of your Owners Manual. Do not continue driving with the Low Brake Fluid Warning Light on.

08V313000

Drivers should use the transmission and brakes to keep the vehicle speed below 75 miles (121 kms) per hour or the posted speed limit, whichever is lower.

08V384000

PRECAUTIONS

1. If the air bag warning lamp and the passenger air bag "on-off" lamp are illuminated, please have the vehicle checked and serviced without delay, as described in the Owner's Manual.
2. As a precaution, if the air bag warning lamp and simultaneously the passenger air bag "on-off" lamp are illuminated, BMW recommends not to use the front passenger's seat until the vehicle has been serviced.
3. BMW recommends that you and all occupants always wear safety belts.
4. Please advise all other drivers and passengers of this vehicle of this important information.

***08V459**

Important Additional Notice: If you already have engine performance problems while starting or driving, please immediately contact your Kia dealer to have the repair conducted. Under such circumstances, you may request that your vehicle be towed to the nearest Kia dealer by phoning the Customer Assistance Center at the telephone number provided below.

Please do not take any out of area trips until you have this repair conducted. We are concerned that customers away from home are less likely to arrange for a repair if the problem starts to develop. Thus, please immediately call your dealer to arrange for a repair if you have any out of area travel planned.

***08V460**

There are two important precautions you should take until this recall has been performed:

- It is highly recommended that you not park your vehicle in a garage, car port or other structure.
- If you notice an oil leak or burning odor, do not operate the vehicle. Immediately contact your Subaru dealer for assistance.

08V521

If the red air bag warning light in your vehicle continuously flashes after the vehicle is started, please take your vehicle to the dealership as soon as possible. In the interim do not allow passengers to ride in the passenger seat.

08V595**PRECAUTIONS FOR YOUR SAFETY**

1. Contact your authorized BMW center immediately to have the necessary repair performed as soon as possible.
2. Unless traffic and driving conditions require it, attempt to avoid rapid vehicle deceleration.
3. BMW recommends that you always wear your safety belt, and that all passengers are properly seated and restrained at all times.
4. If you are not the only driver of this vehicle, please advise all other drivers and passengers of this important information.

08V645

In the meantime, until the VDC G sensor has been inspected and, if necessary repositioned, we recommend that you “turn off” your vehicle’s Traction Control System. Disabling the system will eliminate the possibility of a malfunction associated with an incorrectly installed VDC G sensor. However, please be aware that it will also completely disable your vehicle’s electronic stability / traction control system. The system can be “turned off” by depressing the Traction Control System switch located at the left lower instrument panel. When the system is turned off, the Vehicle Dynamics Control monitor light will illuminate on the instrument cluster indicating the system is deactivated. It will be necessary to follow this procedure each time the vehicle’s engine is started. Please see the following sections in chapter 7 of your Tribeca Owner’s Manual for additional information: 1) “Vehicle Dynamics Control system monitor”, and (2) “Traction Control system OFF switch”.

If you choose not to turn off the VDC system, please remain alert for the conditions and safety hazards described in this letter and take appropriate precautions when operating your vehicle.

08V690

If the red air bag warning light in your vehicle comes on and remains continuously illuminated, please take your vehicle to the dealership as soon as possible.

Appendix B-7

2007 Recalls with Risk Mitigation Instructions in Part 577 letters

Recalls that contain Do Not Drive instructions are starred with an asterisk (*) in this appendix. 2007 Recalls with Do Not Drive instructions also appear separately in appendix A-7, however, they are included here so that this appendix can stand alone as the complete list of Risk Mitigation Instructions. The text for each recall in this appendix is taken from Owner Notification Letters (Part 577).

07V030

What can you do to help ensure that this problem does not occur?
Please refrain from using your speed control while driving until your vehicle is inspected/repaired at a servicing Toyota dealer.

*07V043

If you encounter a blown fuse, an illuminated air bag system warning light, smell smoke, or have replaced a blown fuse #6 without correcting the underlying problem, do not operate the vehicle. Contact your nearest Subaru dealer as soon as possible for guidance.

07V048

To avoid the risk of accident, do not use the cruise control on your car until it has been checked and, if necessary, replaced. If you do use the cruise control before it has been checked and, if necessary, replaced, please remember that the safety devices built into the cruise control unit will disengage the throttle if the driver steps on the brake while the cruise control unit is still "on".

07V052

Mazda is concerned about your safety, so please remove both the driver's and front passenger's all-weather floor mats immediately. You may continue to use the original carpeted floor mats. If you feel you cannot correctly identify the mats remove them from your vehicle immediately. Please bring both front all-weather floor mats and the attached Customer Shipping Information Form to your nearest Mazda dealer.

07V078

Until you have the recall service performed, park your vehicle away from structures to prevent a potential underhood fire from spreading.

07V093

What you must do to ensure your safety: We ask that you apply the enclosed Certification label overlay, Tire and Loading Information label overlay, and Supplemental Tire Pressure Information label so that they cover the original incorrect tire inflation pressure as described on the reverse side of this letter.

07V094

If a RED air bag warning light located in your instrument cluster illuminates together with the YELLOW "Pass Air Bag Off" status light (located on the center portion of the instrument panel next to the radio) and stays on for longer than a few seconds, the passenger side frontal airbag in your vehicle will not operate. If this happens, you should not let anyone ride in the front passenger seat until the dealer has repaired your vehicle.

07V178**PRECAUTIONS FOR YOUR SAFETY**

1. PLEASE CONTACT YOUR AUTHORIZED BMW CENTER IMMEDIATELY TO HAVE THE NECESSARY REPAIR PERFORMED AS SOON AS POSSIBLE.
2. If the front passenger seat is occupied by a small adult, and this condition occurs, illumination of the passenger air bag indicator lamp in the overhead console with the message "PASSENGER AIR BAG OFF" would be visible.
3. BMW recommends that you always wear your safety belt, and that all passengers are properly seated and restrained at all times.
4. Please advise all other drivers and passengers of this vehicle of this important information.

07V248000

If you hear a rattling noise and notice any vibration, you should take your car to a Nissan dealer for repair as soon as possible. If this situation should occur you may have difficulty steering the vehicle, and we therefore strongly advise that the vehicle be towed to the dealer for repair.

07V284000

Your vehicle can continue to be driven until the inspection/repair is conducted. If you can smell fuel in your vehicle, customers are advised to proceed immediately to the nearest authorized Volkswagen dealer or qualified workshop, if they believe it is safe to do so, in order to have the fuel system on the vehicle inspected.

07V336000

Until you have the recall service performed, park your vehicle away from structures to prevent a potential underhood fire from spreading.

07V344000

Whenever the front passenger seat is occupied, the driver should always check the airbag indicator to see if the airbag is on or off. If it is not correct for the situation, the passenger should be moved to a different seat. A child restraint installed properly in the back seat is the safest place for children.

07V465000

Thus, while you must not use the rear outboard seat belts to secure a child restraint until the recall seat belt replacement has been performed, the LATCH system is fully operational in your vehicle and is the best way to secure a LATCH compatible child restraint. Mercedes strongly encourages you always to restrain children properly in the rear seat using LATCH-equipped child restraints whenever possible. The National Highway Traffic Safety Administration has mandated that new motor vehicles and new child restraints be LATCH-equipped because the LATCH systems better protect the children in the event of a crash.

07V468

GM recommends that you always lock your car when you leave it and never allow children to remain in it unsupervised. Following these recommendations will help to avoid the potential for an injury related to this condition.

07V479

You may continue to drive your vehicle; however, you must have the problem corrected promptly. Failure to observe the following precautions, in conjunction with traffic and road conditions, and the driver's reactions, could increase the risk of a crash.

PRECAUTIONS FOR YOUR SAFETY

1. PLEASE CONTACT YOUR AUTHORIZED BMW CENTER IMMEDIATELY TO HAVE THE NECESSARY REPAIR PERFORMED AS SOON AS POSSIBLE.
2. If you experience engine stalling while driving, pull over carefully as soon as possible to a safe location and away from traffic. Do not continue to drive your vehicle. Contact BMW Roadside Assistance at 1-800-332-4269 immediately to have your vehicle brought to the nearest Authorized BMW Center.
3. BMW recommends that you always wear your safety belt, and that all passengers are properly seated and restrained at all times.
4. Please advise all other drivers and passengers of this vehicle of this important information.

07V533

The problem involves the vehicle's tire information label which can be viewed when the driver's door is opened. The standard requires that the tire size and corresponding tire pressure be indicated on the label. On your vehicle, the label does not correspond to the actual tires mounted on your vehicle. However, the correct information is listed in your vehicle's Owner's Manual.

Your vehicle can still be driven. However, do not leave this problem unattended. Too low or too high tire pressure can cause premature wear and/or tire damage, and could lead to unfavorable driving conditions.

Should you need to adjust the tire pressure, please consult your vehicle's Owner's Manual for the correct pressure based upon your vehicle's specific tire size. You will find the tire size stamped on the sidewall of the tire.

Appendix B-8

2006 Recalls with Risk Mitigation Instructions in Part 577 letters

Recalls that contain Do Not Drive instructions are starred with an asterisk (*) in this appendix. 2006 Recalls with Do Not Drive instructions also appear separately in appendix A-8, however, they are included here so that this appendix can stand alone as the complete list of Risk Mitigation Instructions. The text for each recall in this appendix is taken from Owner Notification Letters (Part 577).

06V043

Please affix the enclosed label to your vehicle in accordance with the instructions included with this letter. You may choose to install the label yourself, or if you prefer, you may have the label affixed by your authorized Volkswagen dealer free of charge.

- If you choose to affix this label yourself, as soon as the label has been affixed we ask that you please complete and return to us the self-addressed, postage-paid owner reply card enclosed with this letter.
- If you choose to have your authorized Volkswagen dealer affix this label, please arrange for an appointment without delay. This service will take just a few minutes. Please keep in mind that your dealer may need additional time for the preparation of the repair, as well as to accommodate their daily workshop schedule. Remember to bring the enclosed label with you to your service appointment.

06V051

The certification label and tire and wheel information label for your vehicle are enclosed. To reduce your inconvenience, you can install the labels easily by following the enclosed instructions. If you desire, however, you may take the labels to your dealer for installation within the next 60 days.

06V066

Until stainless steel support cables can be installed on your vehicle, do not stand, sit, or apply loads directly onto the tailgate when it's in the full open (horizontal) position. This will reduce the potential of personal injury and damage to the outer panel of your tailgate. Additionally, when loading or unloading cargo from the pickup box, the tailgate should be removed.

Owners should NEVER permit an individual to sit on the opened (horizontal) tailgate when the vehicle is in motion. Even when the vehicle is operated at low speeds, individuals seated on the tailgate can easily lose their balance in response to vehicle maneuvers, unexpected jolts due to road conditions, etc. Individuals who fall from a moving vehicle may be seriously injured or killed.

06V131

In the time prior to the Recall repair Land Rover recommends that extra care be exercised when parking the vehicle to ensure that the shifter is in the "P" park position before removing the key. Land Rover also recommends, as stated in the Owner's Handbook that the parking brake be applied in conjunction with selecting Park.

06V135

In the time prior to the Recall repair Land Rover recommends that you avoid turning the steering wheel sharply to the left while in "crawl" or "access" suspension height.

06V144

Important Note: To ensure proper operation of the windshield wipers under any conditions, particularly ice and snow, please make sure the area around the wipers is free of any debris.

06V223

As with any vehicle, be sure to regularly check engine oil level as specified in your Owner's Manual. If the vehicle shows any signs of more than $\frac{1}{2}$ quart of oil use in 3,500 miles, you should contact your dealer as soon as possible to have your vehicle inspected.

There are 3 Owner notification letters for this one in one of the 577 letters it advises the following:

Ensuring that your engine always has correct amount of oil will reduce the risk of engine damage. Until Nissan contacts you with further information, we strongly recommend that in addition to following the instructions in your owners manual regarding engine oil, you check your Altima's engine oil every 700 miles and top of the oil level to the H indicator on the dip stick if it is below that mark.

06V234

We are asking you to inspect your sun visors to make sure that the air bag warning labels are securely attached. If the labels are secure, do not take any further action. If any label is distorted, not securely attached or missing, we urge you to replace that label. Enclosed with this letter are two replacement labels for each of the above air bag warning label types. An instruction sheet is enclosed to help you to properly install the replacement labels, if it is necessary.

***06V277**

If you notice a change in vehicle handling/control, or hear an unusual noise coming from the area of the rear axle, your vehicle may be experiencing this problem. In that case, you should pull over carefully to a safe location, and away from traffic. Do not continue

to drive the vehicle. Please contact BMW Roadside Assistance immediately at 1-800-332-4269 to have the vehicle brought to the nearest Authorized BMW Center.

06V307

A label that will correct the label originally installed on your vehicle is enclosed. To reduce your inconvenience, you can install the label easily by following the enclosed instructions. If you desire, however, you may take the label to your dealer for installation within the next 60 days.

***06V327**

If you notice a change in handling/control of your car, or hear an unusual noise coming from the area of the rear axle, your car may be experiencing this problem. In that case, you should pull over carefully to a safe location, and away from traffic. Do not continue to drive the car. Please contact Rolls-Royce Roadside Assistance immediately at 1-800-731-4488 to have your car brought to the nearest Rolls-Royce Dealer.

06V375

We are sending you the enclosed label with the correct information to apply it using the instructions on the next page, or your authorized Volvo retailer can affix the label for you at no charge.

***06V400**

If you notice a vibrating steering wheel, or a pull to one side during vehicle braking, your vehicle may be experiencing this problem. In that case, you should pull over carefully to a safe location, and away from traffic. Do not continue to drive the vehicle. Please contact BMW Roadside Assistance immediately at 1-800-332-4269 to have the vehicle brought to the nearest Authorized BMW Center.

06V434

The addendum on the back of this letter supplements your Owner Manual. Please place this letter in the Owner's Manual of your vehicle for reference by you or future owners.

06V445

To reduce the chance of injuries that may result from deployment while not wearing a seat belt, Hyundai strongly urges you to always properly wear your seat belt when driving your vehicle.

Appendix B-9

2005 Recalls with Risk Mitigation Instructions in Part 577 letters

Recalls that contain Do Not Drive instructions are starred with an asterisk (*) in this appendix. 2005 Recalls with Do Not Drive instructions also appear separately in appendix A-9, however, they are included here so that this appendix can stand alone as the complete list of Risk Mitigation Instructions. The text for each recall in this appendix is taken from Owner Notification Letters (Part 577).

***05V018**

Contact your GM dealer as soon as possible to arrange to have your vehicle towed to the dealership. **Do not drive your vehicle to the dealership.**

05V022

If you must drive your vehicle before having the recall repair performed, be careful not to let your foot slip off the brake pedal and not to pull up on the brake pedal with the top of your foot.

05V025

Always shift the transmission to Park and set the parking brake before exiting the vehicle.

05V098

We have enclosed an owner manual update that describes the location and proper use of the anchorages in all three rear seating positions. Please review this information and then place it in your owner manual for future reference.

05V120

The safest way to operate your vehicle is to turn off the ESP until the recall repair is conducted on your vehicle. The ESP switch is located on the instrument panel to the left of the steering wheel.

If you anticipate driving conditions which are likely to be unstable, you may use the ESP, but you then **MUST** always start driving your Sportage with the wheels in a straight ahead direction until you are going more than 1 mph. Since you must remember this instruction each time you start your Sportage, have this important safety recall conducted as promptly as possible.

05V127

We have enclosed an owner manual update that describes the location and proper use of the anchors. Please review this information and then place it in your owner manual for future reference.

***05V159**

If you are hearing loud noises which appear to be coming from the area of your wheels, or if you are experiencing significant unusual vibrations while driving your vehicle, contact the Kia Customer Assistance number below to have your vehicle towed to your nearest dealer.

***05V183**

Please call your Kia dealer to schedule a service appointment and have your vehicle towed. ***IMPORTANT. DO NOT DRIVE YOUR VEHICLE** to the dealer. Arrangements will be made to tow your vehicle and courtesy transportation will be provided.

05V212

As this problem occurs at a full tank condition, do not top-off and avoid full throttle starts. Please have your vehicle repaired as promptly as possible as described below.

05V254

We request your assistance in affixing the enclosed warning label to the inside of your glove box as indicated in the attached instruction sheet. The warning label describes the configuration of your vehicle and the location of the two child restraint anchorage systems in the rear seat. The label also recommends installing your Child Restraint System in the rear seat which is the safest place for your children.

If you prefer, your local Toyota dealer will be more than happy to assist you in installing the label into your vehicle at NO CHARGE. If you choose to have the Toyota dealer affix the new label, please present this notice and the enclosed label to the dealer at the time of your appointment.

05V300

A door lock mechanism that was not manufactured to specification may allow the left hand rear door to be opened from inside the vehicle, when it is believed that the child lock is engaged. Always properly secure children in the rear seats.

05V305

Your vehicle can be driven until the inspection/repair is conducted. IF you can smell fuel in your vehicle, proceed immediately to the nearest authorized Volkswagen dealer or qualified workshop if you believe that it is safe to do so in order to have the fuel system on your vehicle inspected.

***05V319**

If the charge warning and brake warning lamps come on while you are driving, you should pull off the road to a safe location and arrange to have your vehicle towed to a Nissan dealer.

05V327

Until the recall repair is completed, vehicle occupants sitting in the affected seating positions should verify the shoulder belt portion of the seatbelt is retracting smoothly.

If the seatbelt bins, it may be unbound by pulling the seatbelt outward and then allowing it to retract.

05V342

To prevent your vehicle from rolling while it is parked, always place the automatic transmission in the Park position and place the manual transmission gearshift in one of the gear positions, even if you have engaged the parking brake.

05V376

In the time prior to the Recall repair Land Rover recommends, as a precaution, that your fuel tank be filled no more than 3/4 full. This precaution will reduce the likelihood of fuel ingress into a breather tube that might have detached. The precaution is particularly important in hot climate conditions.

***05V412**

If you are concerned about driving your MAZDA5 to your Mazda dealer, please contact Mazda's Roadside Assistance Program at 1 (800) 866-1998 (telephone number is also available in your MAZDA5 owner's manual) and arrangements will be made to pick up your vehicle and provide you with a rental or loaner car (at no cost to you) while repairs are being scheduled.

05V431

Kia recommends that all children aged 12 and under be seated in the rear seats. This recommendation applies to all vehicles, including those subject to this campaign. Even if you do not anticipate using a child seat in the front passenger seat, we strongly urge you to have your vehicle's programming updated to protect others who may use child seats in the front passenger position at some time in the future.

05V450

WARNING: Hyundai recommends that children must always be seated in the rear seat, properly wearing the seat belt, and Child Restraint Seats (CRS) must always be properly installed in the rear seat. Children must never be seated in the front seat and Child Restraint Seats must never be installed in the front seat. Should an accident occur and cause the right front airbags to inflate, it could cause severe injury or death for a child seated in the front seat or an infant or child seated in a CRS.

***05V452**

To minimize the risk of injury or death, do not ride, your Suzuki dealer will perform the necessary inspection and repair for your vehicle.

05V458

Do not use the tow hitch on your vehicle until it is replaced with the new one.

05V470

Too low or too high tire pressure can cause premature wear and/or tire damage, and could lead to unfavorable driving conditions. Too low tire pressure will also hurt the vehicle's fuel economy. Should you need to adjust your tire pressure, please consult the vehicle Owner's Manual for the correct pressure based upon your vehicle's specific tire size. You will find the tire size stamped on the sidewall of the tire.

In the interest of safety and fuel economy, please install the label as soon as possible.

If you do not wish to perform this yourself, you may bring your vehicle to an Authorized MINI Dealer who will perform this service for you free of charge.

We recommend that you always wear your safety belt, and that all passengers are properly seated and restrained at all times.

05V483

In the worst case, pieces of the Wind Deflector glass which have separated from the frame may fall upon the vehicle occupants causing driver distraction and/or injury. You may reduce the likelihood of this occurring on your vehicle by not opening the moon roof until the Special Service Campaign repair has been performed.

05V486

Since the new label can be easily installed, and to reduce inconvenience, the label and installation instructions are being sent with this letter. If you desire, however, you may take the label to your dealer for installation.

05V502

Land Rover recommends, as stated in the Owner's Handbook, that you always set the hand parking brake or electric parking brake in conjunction with selecting Park. Proper use of the parking brake will eliminate the possibility of unintended vehicle movement from a parking pawl failure.

05V503

Jaguar recommends that until such time as this repair is carried out, you should ensure that when the gear selector is moved to the position 'P' (park) that the parking brake is also applied.

05V504

Always engage the parking brake when the vehicle is parked.

05V519

REMINDER: As recommended in your owners guide, always be sure to fully apply the parking brake when leaving your vehicle unattended.

05V552

Since the new label can be easily installed, and to reduce inconvenience, the label and installation instructions are being sent with this letter. If you desire, however, you may take the label to your dealer for installation.

05V555

It will be necessary that your fuel tank be no more than one-quarter full when you bring your vehicle to the dealer in order to minimize the possibility of fuel spill during the repair.

05V557

Until the recall repair is completed, follow the instructions provided by your child seats manufacturer on how to properly install the child seat with your vehicle's rear safety belts.

05V558

Occupants in a vehicle should always wear a safety belt or an increased risk to personal injury can occur in the event of a vehicle crash.

Appendix B-10

2004 Recalls with Risk Mitigation Instructions in Part 577 letters

Recalls that contain Do Not Drive instructions are starred with an asterisk (*) in this appendix. 2004 Recalls with Do Not Drive instructions also appear separately in appendix A-10, however, they are included here so that this appendix can stand alone as the complete list of Risk Mitigation Instructions. The text for each recall in this appendix is taken from Owner Notification Letters (Part 577).

04V001

Significantly, it is important to know that:

- To avoid serious injury and insure maximum protection in all types of crashes, you must wear your safety belt.
- Do not install rearward facing child seats.
- Do not sit or lean unnecessarily close to the air bag.
- Do not place any objects over the air bag cover or between the air bag and yourself.
- When children are riding in the passenger seat, adjust the seat to its most rearward (aft) position.

04V036

If you are experiencing problems starting your car, have it repaired promptly and do not leave the car in a building.

Please know that we understand the concern this may cause and the need to correct it as quickly as we can. Until we are able to install a relay kit in your car that will prevent high current from flowing through the ignition switch, there are two very important precautions you can take to reduce the potential for a fire:

Do not hold the key in the "start" position if the starter does not immediately begin cranking the engine. A low battery charge and other alerting system problems can create a situation where the driver turns the key to the "start" position and nothing happens other than a clicking sound. If that happens, turn the key back to "off" immediately. Holding the key in "start" longer will not help to start the car, but can cause damage to the ignition switch that can eventually lead to a fire.

If you encounter difficulty starting your car, have it repaired promptly to minimize the potential for damage to the ignition switch. The ignition switch in your vehicle may become damaged and the damage could lead to a fire if you:

1. have a failing battery and do not replace it promptly and
2. experience "click" with no start three or more times and
3. jump-start the car three or more times

04V048

- We ask that you apply the enclosed label overlay as described on the reverse side of this letter.

- If preferred, you may contact your dealer to schedule a service appointment for installation of the label overlay.

04V060

Until your Corvette is repaired, you can easily verify that the column is unlocked by turning the steering wheel a full turn before shifting into gear. If you hear a ratcheting noise while turning the wheel or experience column lock after starting the engine, contact your dealer to arrange for repair.

***04V090**

Slow engine cranking and difficulty starting the engine could indicate a low battery. Poor driveability or a check engine light could indicate a fuel pressure regulator leak. If you experience these conditions have your dealer check and repair your vehicle.

If your vehicle does not start and you hear a loud bang, there could be a fuel leak. Do not try to start it again. Contact your dealer for assistance.

04V095

A Tire and Loading Information label is provided with this letter. Remove the clear film from the original Tire and Loading Information Label on the vehicle. Then remove the backing from the new label and affix it over the original label. If you do not wish to affix the new label yourself, bring the label to your Authorized Mitsubishi Dealer to affix the label.

04V103

Even with the Occupant Detection System in your Quest, Nissan recommends that children 12 and under be properly restrained in a rear seat using a child restraint, booster seat, or vehicle seat belt, as appropriate for the child's size. According to accident statistics, children are safer when properly restrained in the rear seat than in the front seat. You should especially follow this recommendation until the front passenger seat is repaired.

04V129

Until stainless steel support cables can be installed on your vehicle, do not stand, sit, or apply loads directly onto the tailgate when it's in the full open (horizontal) position. This will reduce the potential of personal injury and damage to the outer panel of your tailgate. Additionally, when loading or unloading cargo from the pickup box, the tailgate should be removed. Please see your Owner's Manual for tailgate removal instructions.

04V131

Until then, if you wish to prevent the possibility of ABS operation at speeds below 5 mph prior to receiving the ABS ECU reprogramming service, you may remove this ABS fuse located in the underhood fuse and relay box. Please refer to your owner's manual. Removing the ABS fuse will prevent the ABS system operation and will cause the ABS warning light to illuminate, but will not affect normal brake operation.

04V132

Since the new labels can be easily installed and to reduce your inconvenience, the labels and installation instructions are included with this letter. If you desire, however, you may take the labels to your dealer for installation.

04V177

Since this label can easily be installed, and to reduce your inconvenience, the redesigned label and application instructions are included with this letter. If you desire, however, you may take the labels to your GM dealer for installation.

04V182*PRECAUTIONS**

1. Contact your authorized BMW Center immediately to have the necessary repair performed as soon as possible.
2. If you experience engine stalling while driving, pull over carefully as soon as possible to a safe location and away from traffic. Do not continue to drive your vehicle. Contact BMW Roadside Assistance at 1-800-332-4269 immediately to have your vehicle brought to the nearest Authorized BMW Center.
3. If you are not the only driver of this vehicle, please advise all other drivers of this important information.

***04V183**

- If you experience a sudden loss of the pressure or the failure while driving, then you should pull over carefully as soon as possible to a safe location and away from traffic. Do not attempt to change your tire. Do not continue to drive your vehicle. Contact BMW Roadside Assistance at 1-800-332-4269 immediately to have your vehicle brought to the nearest Authorized BMW center for repair.

04V186

Until your vehicle is repaired, leave the shift lever in the P (Park) position until the power sliding doors are fully closed.

04V197

If you have this trailer hitch wiring harness on your vehicle, do not use the trailer wiring harness on your vehicle by towing a trailer until the wiring harness is replaced.

04V221

We ask that you apply the enclosed label overlay so that it covers the original incorrect information as described on the reverse side of this letter.

04V232

Enclosed you will find two supplemental rear tire pressure labels. Please attach these labels to your E-350 wagon. One label is to be applied next to the Vehicle Certification

Label and the other label is to be applied above the label located inside the fuel filter door of your E-350 wagon. Instructions are provided with this letter. If you prefer, your Ford dealer will install the labels for you at no charge.

04V282

Please affix the enclosed Supplemental Tire Information Label containing the correct tire inflation pressure to your vehicle. To affix the label properly, please use the instruction sheet provided with this letter.

04V302

Since the inspection is easy to perform, and to reduce any inconvenience to you, we have included the inspection procedure with this letter. However, if you desire you can take your vehicle to your dealer for the inspection.

If you decide to inspect the transmission shifter operation yourself and you find that the shifter park lock cable requires adjustment, you should contact your GM dealer to schedule an appointment for the adjustment.

If the inspection determines that the cable DOES NOT require adjustment, please check the box marked "Other" on the enclosed customer reply form and mail it back to us. This will remove your name from our list so that you won't be contacted about this again.

04V303

CONTACT YOUR AUTHORIZED BMW SAY CENTER IMMEDIATELY TO HAVE THE NECESSARY REPAIR PERFORMED AS SOON AS POSSIBLE.

BMW recommends that you always wear your safety belt, and that all passengers are properly seated and restrained at all times.

04V326

Until your vehicle is repaired, you may wish to keep the shade for the SkyView roof closed. If the glass should break, this will help reduce the chance that broken glass will unexpectedly fall inside the occupant compartment.

***04V344**

PRECAUTIONS

1. DO NOT DRIVE YOUR VEHICLE.
2. CONTACT YOUR AUTHORIZED BMW SAY CENTER IMMEDIATELY TO HAVE THE NECESSARY REPAIR PERFORMED AS SOON AS POSSIBLE. YOUR AUTHORIZED BMW SAY CENTER WILL ARRANGE FOR PICK-UP AND REPAIR OF YOUR VEHICLE, INCLUDING ALTERNATE TRANSPORTATION.
3. If you experience engine stalling while driving, pull over carefully as soon as possible to a safe location and away from traffic. Do not continue to drive your

vehicle. Contact BMW Roadside Assistance at 1-800-332-4269 immediately to have your vehicle brought to the nearest Authorized BMW SAV Center

4. If you are not the only driver of this vehicle, please advise all other drivers of this important information.

***04V348**

- If you experience a flat tire while driving, then you should pull over carefully as soon as possible to a safe location and away from traffic. Do not continue to drive your vehicle. Contact MINI Roadside Assistance at 1-866-646-4772 immediately to have your vehicle brought to the nearest Authorized MINI dealer.
- If your vehicle is equipped with Run-Flat Tires, and you experience a flat tire while driving, you may continue to drive your vehicle with certain speed and mileage restrictions. Drive cautiously and carefully, Do not exceed 50 mph. Specific mileage restrictions are contained in the Owner's Manual, and depend upon the number of passengers and additional load. Please refer to your Owner's Manual for specific details.

04V389

Please inspect the certification label as explained below. NOTE: If you are not comfortable inspecting the certification label yourself, please contact any authorized Honda dealer and make an appointment for the inspection.

1. Open the driver's door, and located the certification label. The label is attached to the lower right corner of the doorjamb.
2. Look at the GVWR (gross vehicle weight rating) number on the second line of the label.
 - If the GVWR reads 760 KG (1680 LBS), the label is incorrect. Call any authorized HONDA automobile dealer and make an appointment to have your vehicle updated. The dealer will apply a correction sticker over the incorrect information on the certification label. This work will be done free of charge.
 - If the GVWR reads 2700 (5950 LBS), the label is correct. Please complete and mail the enclosed, postage-paid Customer Response Card. Federal regulations require us to record recall inspection and repair information for each potentially affected vehicle.

***04V402**

- Do not operate your vehicle with the fuel tank gauge indicating that the tank is less than half-full. Engine stalling could occur even though the gauge indicated that there is sufficient fuel in the tank. Therefore, you should refuel before the gauge indicates that the tank is half-full.
- If you experience engine stalling while driving, you should pull over carefully to a safe location, and away from traffic. Do not continue to drive the vehicle. Please contact BMW Roadside Assistance immediately at 1-800-332-4269 to have the vehicle brought to the nearest Authorized BMW SAV Center.

04V442

WARNING: Until this recall has been performed, do not open or close your liftgate glass. The larger liftgate door is not affected by this recall, so you can still use it to access the rear compartment of your vehicle. See the attached illustration for guidance.

***04V473**

If you encounter an oil leak, do not operate the vehicle. Contact the nearest Subaru dealer.

04V495

We also remind you to follow all the information in your owner's manual regarding the floor mats in your vehicle, including securing your factory floor mats properly to prevent any unwanted interference with the throttle pedal, and using only genuine Audi mats.

04V550

Inspect your front seat belt anchors. As soon as possible, check the movement of the driver's and front passenger's seat belt lower anchors. The lower anchors are between the seat and the door, bolted below the door (see the illustration below). Both anchors should move freely without binding or sticking. If either anchor binds or sticks, your vehicle needs to be repaired.

04V581

Until your vehicle is repaired, do not use the tow hitch.

04V595

Please note that Toyota recommends that you never install a rear-facing child restraint in the front passenger seat, even if the passenger "Airbag OFF" lamp is illuminated. The safest place for children is in the rear seat. Please refer to your Owner's Manual for additional details.

04V597

Until the vehicle is serviced, the interior handle should not be used to open the door. The driver can open and close the door from switches at the driver's position or by using the remote key fob. The driver should tell passengers to use the switch located in front of the door to open or close the door. The driver should also use the override switch to prevent operation of the power door by children or by others who are not familiar with its use.

***04V604**

Your vehicle should not be driven until this recall service has been performed.

Appendix B-11

2003 Recalls with Risk Mitigation Instructions in Part 577 letters

Recalls that contain Do Not Drive instructions are starred with an asterisk (*) in this appendix. 2003 Recalls with Do Not Drive instructions also appear separately in appendix A-11, however, they are included here so that this appendix can stand alone as the complete list of Risk Mitigation Instructions. The text for each recall in this appendix is taken from Owner Notification Letters (Part 577).

***03V001**

PRECAUTIONS

If one or more of the following conditions occurs: A loss of brake performance is noticed, the brake warning light is activated, you hear a thumping or a rubbing noise coming from the front wheel housing,

Then you should pull over carefully as soon as possible to a safe location and away from traffic. Do not continue to drive your vehicle. Contact BMW roadside Assistance at 1-800-332-4269 immediately to have your vehicle brought to the nearest BMW SAV center.

03V028

Until you have this recall completed, there are a few things you can do to minimize the possibility of ice on the throttle valve. Before starting your vehicle on a cold morning or after it has cooled down completely on a cold day, you should check the throttle for binding by pretesting it. If you do not detect any binding, start the vehicle and allow it to warm up for 5 to 10 minutes, or approximately half way on the temperature gauge.

03V032

Your vehicle can be driven; however, for the safety of the driver and front passenger do not leave this problem unattended.

Precautions

1. CONTACT YOUR AUTHORIZED BMW CENTER IMMEDIATELY TO HAVE THE NECESSARY REPAIR PERFORMED AS SOON AS POSSIBLE.

***03V052**

In certain 2003 model year Buick Rendezvous and Pontiac Aztek vehicle, the diameter of the steering column intermediate shaft is too small. This condition could allow the intermediate shaft to spin inside the steering column coupling, resulting in a loss of directional control of the vehicle. A crash could result without prior warning.

You may have already been contacted regarding this recall by your GM dealer or by the GM Customer Assistance Center. If not, please contact your GM dealer immediately

and tell the service department that your vehicle is involved in recall 03009. DO NOT DRIVE YOUR VEHICLE.

03V084

Contact your Nissan dealer at your earliest convenience in order to arrange an appointment to have your vehicle repaired. Until then, check engine oil regularly and fill as needed. If you notice excessive engine noise or an abnormal odor from the engine compartment, you should stop driving and contact your Nissan dealer to arrange to have the vehicle towed to the dealer for repair.

03V086

If you experience this problem while driving, then you should pull over carefully as soon as possible to a safe location away from traffic. Do not continue to drive your vehicles. Contact MINI Roadside Assistance at 1-888-848-4772 immediately to have your vehicle brought to the nearest Authorized MINI dealer.

03V097

We urge you to call your Hyundai dealer to schedule an appointment to have this work performed as soon as possible.

If you must install a T125/70D-15 compact tire on a front wheel position, turn off the TCS. The traction control system may be turned off by pressing the TCS switch on the instrument panel to avoid inadvertent traction control activation. The TCS automatically turns on when the vehicle is started, so it must be manually turned off each time the engine is restarted.

03V123

As a precaution until the vehicle is repaired, keep your foot on the brake pedal and release it slowly after shifting gears to ensure that the transmission is in the gear that you have selected. Always set the parking brake when the transmission is in Park.

03V124

If you experience this problem while driving, then you should pull over carefully as soon as possible to a safe location and away from traffic. Do not continue to drive your vehicle. Contact BMW Roadside Assistance at 1-800-332-4269 immediately to have your vehicle brought to the nearest Authorized BMW center.

03V150

Always wear your seatbelts, sit upright and buckle up properly – lap and shoulder belts for adults, and child restraints, booster seats, or lap and shoulder belts as appropriate for the size and age of the child.

Always place children 12 years old and under in the rear (and make sure they are properly restrained).

Never put a rear-facing child seat in the front seat if the vehicle is equipped with a passenger air bag.

Always move both driver and passenger seats as far back from the air bag as practical.

03V160

Your vehicle can still be driven; however, for the safety of the driver and any passengers, do not leave this problem unattended.

Precautions

1. CONTACT YOUR AUTHORIZED BMW CENTER IMMEDIATELY TO HAVE THE NECESSARY REPAIR PERFORMED AS SOON AS POSSIBLE.
2. Do not leave any children unattended in the vehicle with the ignition key.
3. Avoid placing any fingers, arms, etc. in the opening of any window while it is being closed.
4. If you are not the only driver of this vehicle, please advise all other drivers of this important information.

03V197

Your vehicle can still be driven; however, for the safety of the driver and any passengers, do not leave this problem unattended. A loss of front brake force may occur. Depending on traffic conditions and the driver's reaction, this could lead to a crash.

PRECAUTIONS

1. CONTACT YOUR AUTHORIZED BMW SAV CENTER IMMEDIATELY TO HAVE THE NECESSARY REPAIR PERFORMED AS SOON AS POSSIBLE.
2. If the brake warning light is activated, or a loss of front brake performance is noticed, pull off the road as soon as possible to a safe location away from traffic. Do not continue to drive your vehicle. Contact BMW Roadside Assistance at 1-800-332-4269 immediately to have your vehicle brought to the nearest BMW SAV center.
3. If you are not the only driver of this vehicle, please advise all other drivers of this important information.

03V214

Precautions

1. CONTACT YOUR AUTHORIZED BMW CENTER IMMEDIATELY TO HAVE THE NECESSARY REPAIR PERFORMED AS SOON AS POSSIBLE.
2. Drive carefully, and drive carefully, and avoid excessive steering maneuvers when possible. If a loss of tire pressure occurs while driving, pull off the road as soon as possible to a safe location. Contact BMW Roadside Assistance at 1-800-332-4269 immediately to have your vehicle brought to the nearest BMW SAV center.

3. If you are not the only driver of this vehicle, please advise all other drivers of this important information.

03V240

PRECAUTIONS

1. CONTACT YOUR AUTHORIZED BMW SAV CENTER IMMEDIATELY TO HAVE THE NECESSARY REPAIR PERFORMED AS SOON AS POSSIBLE.
2. If you experience either a rough-running engine, an illumination of the check engine light, or a display of “engine malfunction, drive with moderation” in the vehicle's instrument cluster message area, then you should pull over carefully as soon as possible to a safe location away from traffic. Do not continue to drive your vehicle. Contact BMW Roadside Assistance at 1-800-332-4269 immediately to have your vehicle brought to the nearest BMW SAV center.
3. BMW recommends that you always wear your safety belt, and that all passengers are properly seated and restrained at all times.
4. If you are not the only driver of this vehicle, please advise all other drivers of this important information.

***03V322**

Hyundai Motor America has shipped some of these vehicles to your company (Enterprise Rent A Car) and we are requesting that you not place these vehicles into service until a correction can be installed. If any of these vehicles have already been placed into service, please remove them from service and hold them until a correction can be installed.

03V324

The defect involves an incorrect tightening torque of the engine oil filter drain plug on certain 2003 BMW 7 series vehicles. If this happens, the oil pressure warning light will illuminate, and “engine oil pressure Stop carefully” will appear in the vehicle's instrument cluster message display area.

PRECAUTIONS

1. CONTACT YOUR AUTHORIZED BMW SAV CENTER IMMEDIATELY TO HAVE THE NECESSARY REPAIR PERFORMED AS SOON AS POSSIBLE.
2. If the oil pressure warning light illuminates, or “engine oil pressure! Stop carefully” appears in the vehicle's instrument cluster message display area, then you should pull over carefully and as soon as possible, to a safe location and away from traffic. Do not continue to drive the vehicle. Contact BMW Roadside Assistance at 1-800-332-4269 immediately to have your vehicle brought to the nearest BMW SAV center.
3. BMW recommends that you always wear your safety belt, and that all passengers are properly seated and restrained at all times.
4. If you are not the only driver of this vehicle, please advise all other drivers of this important information.

03V325

The rear brake hoses may split open during riding condition in which full extension of the rear suspension occurs on certain 2003 Model Year BMW R 1150 GS Adventure motorcycles.

PRECAUTIONS

1. CONTACT YOUR AUTHORIZED BMW RETAILER IMMEDIATELY TO HAVE THE NECESSARY REPAIR PERFORMED AS SOON AS POSSIBLE.
2. You may continue to ride your motorcycle. However, ride cautiously and carefully. If you are in any way concerned with your ability to safely operate the motorcycle, please contact your BMW retailer to arrange for pickup and repair of the motorcycle.
3. If you experience a loss of brake fluid/pressure, or notice fluid leakage from the rear brake, carefully bring the motorcycle to a stop using the front brake. Contact your BMW retailer for immediate pickup and repair of the motorcycle.
4. If you are not the only rider of this motorcycle, please advise all other drivers of this important information.

03V421

The defect involves a microprocessor in the airbag module that could cause one or more airbags to deploy when placing the key in the ignition to the ON position or when starting the vehicles. Certain 2001 BMW 5 series vehicles are involved.

PRECAUTIONS

1. CONTACT YOUR AUTHORIZED BMW SAV CENTER IMMEDIATELY TO HAVE THE NECESSARY REPAIR PERFORMED AS SOON AS POSSIBLE.
2. When placing the key in the ignition ON position, or when starting the vehicle, occupants should NOT be in close proximity to the driver or front passenger airbag, or the side airbag (including Head Protection System (HPS)). Drivers should not place themselves near the airbag cover located on the steering wheel, and front passengers should not place themselves near the airbag cover located on the instrument panel about the glove box. Occupants should be sitting upright against the back of their seat.
3. In addition, when placing the key in the ignition ON position, or when starting the vehicle, never let an occupant's head rest near any side airbag. Do not lean towards or against a door with a side airbag.
4. Refer to the appropriate safety information in your Owner's Manual, and observe the warnings contained in the airbag warning labels on your car.

03V423

Certain 1989-99 Honda Accord and 1988 Honda Odysseys with automatic transmission may have a defect which prevents proper interlock operation. The interlock ensures the transmission is in Park before the ignition key can be removed. Failure of the interlock may allow the ignition key to be removed when the gear selector lever is not in park and the vehicle could roll and a crash could occur.

Until your vehicle is repaired, be sure to shift the transmission to Park and set the parking brake whenever you park.

03V475

Certain BMW X5 Sports Activity Vehicles have insufficient tightening of the front drive train fasteners that hold the front differential, the right output shaft housing flange at the engine and the right hand engine support. With prolonged driving, sufficient loosening of the fastener could cause damage to the engine and transmission housings. In extreme cases the right output shaft could become disconnected and the ability to control the vehicle would be reduced.

PRECAUTIONS

1. CONTACT YOUR AUTHORIZED BMW SAV CENTER IMMEDIATELY TO HAVE THE NECESSARY REPAIR PERFORMED AS SOON AS POSSIBLE.
2. If you hear a rattling noise coming from the engine compartment, your vehicle may be experiencing this problem. In that case, you should pull over carefully to a safe location, and away from traffic. Do not continue to drive the vehicle. Please contact BMW Roadside Assistance Immediately at 1-800-322-4269 to have the vehicle brought to the nearest Authorized BMW SAV center.
3. BMW recommends that you always wear your safety belt and that all passengers are properly seated and restrained at all times.
4. If you are not the only rider of this vehicle, please advise all other drivers of this important information.

Appendix B-12

2002 Recalls with Risk Mitigation Instructions in Part 577 letters

Recalls that contain Do Not Drive instructions are starred with an asterisk (*) in this appendix. 2002 Recalls with Do Not Drive instructions also appear separately in appendix A-12, however, they are included here so that this appendix can stand alone as the complete list of Risk Mitigation Instructions. The text for each recall in this appendix is taken from Owner Notification Letters (Part 577).

02V008

OWNERS WILL BE SENT A CORRECTED TIRE INFORMATION LABEL AND INSTALLATION INSTRUCTIONS. THE CUSTOMER MAY ALSO HAVE THE DEALER INSTALL THE LABEL ON THE VEHICLE, IF THEY SO DESIRE.

02V027

Because of the potential for severe injury we strongly recommend that you do not drive your vehicle until it has been serviced for the defect described in this letter. Please call us at 866-944-9090 or contact your dealer right away for information on towing and courtesy transportation.

02V031

If the "ABS light" on your instrument panel comes on prior to the completion of this service, please contact your Volkswagen dealer immediately.

02V035

In order to reduce the likelihood of rear axle differential damage before your scheduled service date we suggest you avoid accelerating from stops rapidly and avoid spinning your tires until repair has been made.

02V043

As a precaution until a new pedal stopper is installed, do not forcefully push the accelerator pedal all the way down to the stopper. Contact your Nissan dealer at your earliest

02V051

NOTE: You need to inspect all rear seat belt buckles, left, right, and center. If you already looked at the outer rear buckles, you still need to inspect the center buckle.

You'll find an assembly number stamped on the back of the buckle. The assembly number isn't easy to see; you may need a flashlight and a magnifying glass. Buckles that need replacement are stamped with one of the numbers shown below.

02V053

As with all vehicles, you should never exit the vehicle while the engine is running and you should always remove the key from the ignition and apply the park brake before leaving the vehicle. Your vehicle will not allow you to remove the key unless the shifter is fully engaged in the Park position.

The following indicators can also be used to ensure that you have fully engaged the shifter into the "Park" position:

- Ensure that the shift indicator is in the "P" position.
- Depress the shifter button on the shifter lever and move the lever all the way forward until it stops.
- When fully engaged in "Park," you should not be able to move the shifter rearward without depressing the shifter button.

02V056

As a precaution until you have had your vehicle inspected, you should remove the driver side floor mat.

02V057

If you should experience a flat front tire, do not jack up your car and attempt to change it yourself. Contact BMW Roadside Assistance at 1-800-332-4269, or your nearest BMW center, immediately to have your car brought to that center for repair.

02V066

PLEASE note the attached wheel diagram and carefully inspect the spokes of your wheels for lateral cracks in the noted areas. If you see any cracks, stop driving your car immediately and contact your dealer or Saleen's Warranty Department at (949) 597-3837. Arrangements will be made to pick up your vehicle for repairs.

02V070

Until we are able to install a relay kit in your car that will prevent high current from flowing through the ignition switch, there are two very important precautions you can take to reduce the potential for a fire:

- Do not hold the key in the "start" position if the starter does not immediately begin cranking the engine. A low battery charge and other starting system problems can create a situation where the driver turns the key to the "start" position and nothing happens other than a clicking sound. If that happens, turn the key back to "off" immediately. Holding the key in "start" longer will not help to start the car, but can cause damage to the ignition switch that can eventually lead to a fire.

- If you encounter difficulty starting your car, have it repaired promptly to minimize the potential for damage to the ignition switch. The ignition switch in your vehicle may become damaged and the damage could lead to a fire if you:
 - have a failing battery and do not replace it promptly and
 - experience "click" with no start three or more times and
 - jump-start the car three or more times.

02V078

OWNERS WILL BE SENT CERTIFICATION LABELS AND OWNERS MANUAL INSERTS

02V079

Until your car is repaired, make sure your front seat passenger is properly secured by the seat belt, since the passenger's airbag may not provide adequate protection in a collision.

02V088

In the meantime, do not drive the vehicle nor let anyone else drive it. If you must drive your car and this problem occurs, pull over carefully to a safe location away from traffic. Contact your authorized BMW center or BMW Roadside Assistance at 1-800-332-4269 immediately to have your vehicle brought to the center for repair.

02V125

Until you are able to have your seat belt buckles inspected, firmly insert the seat belt tongue straight into the buckle. Check to see that it is properly latched by firmly pulling the tongue end of the belt away from the buckle. Ask the front passenger to do the same if that seat is being used.

02V129

When operating the vehicle with the spare tire installed, please observe the following precautions.

- Replace tire/steel wheel with upgrade tire/alloy wheel as soon as possible.
- Do not use for long periods of time at speeds over 50 mph (80 km/h).
- Do not drive at high speeds on unpaved roads.
- The vehicle slip indicator may illuminate briefly during periods of medium to heavy acceleration or pulling heavy loads.

We have enclosed a label with installation instructions and a reference insert for the glove box. Any Southeast Toyota Dealer will install the label at no charge for you. [If you choose to install the label yourself, the label with installation instructions is enclosed. We have also provided a copy of the label as a glove box insert for easy reference. It should be retained with the owner's manual in the glove box. Should installation of the spare tire ever become necessary, please review and follow the items listed on the caution label.]

02V136

Enclosed with this letter is a "Safety First" booklet that contains the correct instructions. Please remove the current "Safety First" booklet from the Owner's Manual and exchange it with this corrected booklet. After exchanging the booklet, discard the incorrect booklet.

02V138

Potential engine overheating will be indicated by the needle in the coolant temperature gauge moving from the approximate middle position to the red zone, and on some models by display of the message "COOLANT TEMPERATURE" in the instrument cluster.

In some cases, an electrical smell, or burning and/or smoke from the front of the vehicle may be noticed.

Should any of these warnings occur, pull off the road to a safe location and switch off the engine. If you notice an electrical smell, or burning and/or smoke from the front of the vehicle, do not open the hood. All occupants should carefully exit the vehicle and move to a location away from traffic. Contact BMW Roadside Assistance at 1-800-332-4269 immediately to have your vehicle brought to the nearest BMW center.

02V145

To prevent inadvertent side impact airbag deployment prior to replacement of the side impact airbag satellite sensors; please avoid forcefully slamming your vehicle's doors closed.

02V146

If you notice a knocking sound from the front of your vehicle and/or abnormal steering, you should stop driving and contact your Infiniti dealer to arrange to have the vehicle towed to the dealer for repair.

***02V150**

Do not operate vehicle with the fuel tank less than half full. If you experience any loss of power do not continue to drive your vehicle.

02V152

MBUSA plans to send vehicle owners headlamp aiming instructions, and directions for affixing these inserts to the operator's manual in early July 2002.

02V194

In the meantime, if there is a sudden, noticeable increase in side to side play of the brake pedal, do not drive the vehicle. If this increase in play is noticed while driving, pull over carefully to a safe location away from traffic. Contact your authorized BMW

X5 SAV center or BMW Roadside Assistance at 1-800- 332-4269 immediately to have your vehicle brought to the center for repair.

If the brake pedal detaches while driving, you can stop the vehicle by downshifting the transmission and carefully applying the parking brake. After stopping in a safe location away from traffic, contact your authorized BMW.X5 SAV center or BMW Roadside Assistance at 1-800-332-4269 immediately to have your vehicle brought to the center for repair.

02V196

Until your car is repaired, make sure your front seat passenger is properly secured by the seat belt since the passenger's airbag may not provide adequate protection in a collision.

02V213

Please do not let anyone sit in the front passenger seat until this repair is completed.

02V223

Until the modification is performed, caution should be exercise when encountering rough road, potholes, curbs, etc. In such conditions proceed carefully, avoiding excessive speed and sever bumps.

All occupants should always be properly restrained (children in child restraint systems appropriate for their age and size; larger children and adults using safety belts) and sitting upright. Never let an occupant's head rest near any side airbag. Do not lean towards or against a door with a side airbag.

Refer to the appropriate safety information in your Owner's Manual (see pages 54-60) and the BMW Safety Tips card. Observe the warnings contained in the airbag warning labels on your car.

02V305

To reduce the possibility of losing control due to this condition, you should avoid driving over 35 mph or during inclement weather. If the amber-colored ABS tell-tale lamp illuminates or you hear grinding noise, you should immediately pull off of the road and call Roadside Assistance at the appropriate number below to have your vehicle towed to the nearest GM dealer for repair.

02V316

As a precaution until the repair is completed, do not install the spare wheel and tire on the front of the vehicle.

02V330

To reduce the possibility of losing control due to this condition, you should not drive your vehicle until the attaching nut has been inspected for the proper torque specification.

Appendix B-13

2001 Recalls with Risk Mitigation Instructions in Part 577 letters

Recalls that contain Do Not Drive instructions are starred with an asterisk (*) in this appendix. 2001 Recalls with Do Not Drive instructions also appear separately in appendix A-13, however, they are included here so that this appendix can stand alone as the complete list of Risk Mitigation Instructions. The text for each recall in this appendix is taken from Owner Notification Letters (Part 577).

***01V026**

Due to the potential for severe injury, we strongly recommend that you do not drive your vehicle until it has been serviced for the defect described in this letter. Please contact your dealer right away for information on towing and courtesy transportation.

01V030

If you feel uncomfortable driving your vehicle as a result of this recall notice, please contact BMW Roadside Assistance at 1-800-332-4268 or your nearest X5 SAV center to arrange for towing service to that center.

01V039

We ask that you apply the enclosed tire label so that it covers the original incorrect label. The original label is located on the rear edge of the driver's door. To assure good adhesion, be sure the original tire label is clean and dry before applying the new label. If you prefer not to install the label yourself, simply contact your dealer to schedule a service appointment.

01V040

To ensure that the primary hood latch is engaged, open and close your hood strongly, then attempt to pull up on the hood. If the primary hood is engaged, the hood should not lift.

As a further measure we ask that you lubricate the secondary hood latch in accordance with the instructions on the back of this letter. Lubrication will prevent the secondary hood latch from binding. If you prefer, you may make a service appointment with your dealer and your dealer will lubricate the secondary hood latch free of charge.

01V053

Do not use your Bose audio system until your car is repaired. If you do use the audio system and hear unusual noises such as popping or clicking coming from the speakers, turn the system off immediately. If you smell smoke, pull over to the side of the roadway safely, open the trunk and check the amplifier located on the upper left corner of the rear seat back. If you experience either problem, you should contact your Acura dealer as soon as possible.

01V077

Place this letter in your Owner's Manual for future reference. An Owner's Manual addendum is provided on the reverse side of this letter. The addendum describes new 4x4 control switch lighting operation and a vehicle storage procedure.

01V109

Since the new labels can be easily installed, and to reduce your inconvenience, the labels and installation instructions are being sent with this letter. You may install the labels directly over the incorrect labels. However, if you desire, you may bring the labels to your dealer for installation. This service will be performed for you at no charge.

01V125

What Will Be Done: A new label will be installed on the driver's door, overlaying the previous tire and tire pressure information on the Certification & Tire Pressure Label. Since a new label can be easily installed, and to reduce the possible inconvenience to you, we are enclosing the label and installation instructions for installing the label. However, if you desire, you may take the label to your dealer for installation. This service will be provided for you at no charge.

***01V126**

What You Should Do: Contact your GM dealer as soon as possible to arrange to have your vehicle towed to the dealership. Do not drive your vehicle to the dealership. Your dealer will provide you with alternate transportation while your vehicle is at the dealership for this repair.

***01V152**

As a safety precaution, you must not drive your minivan until this service is performed. Contact your dealer right away to schedule an appointment to have your minivan picked up or call Chrysler Roadside Assistance at 1-800-521-2779 and arrange to have your minivan towed to a dealer immediately.

01V156

Please refrain from using your driver's side seat adjustment mechanisms until the repair is completed. Under no circumstances should you adjust your seat while your vehicle is in motion.

01V157

Precautions You Can Take

Please set the trip odometer of your Audi A6 quattro to zero miles each time that you fill your fuel tank and refuel when the trip odometer has reached 200 to 250 miles. In

following this procedure you will be sure that you will always have enough fuel in your tank until the recall service can be completed.

01V159

Since the inspection is a visual inspection, and to reduce the possible inconvenience to you, we are enclosing an inspection procedure with this letter. However, if you desire, you can take your vehicle to your Chevrolet dealer for this inspection.

If you should choose to perform the inspection yourself and find one of the specified lot numbers on any of your seat belts, contact your dealer to schedule an appointment to have a new seat belt installed. This service will be performed for you at no charge.

01V161

Until your car is repaired, if the driver's window is open, keep the window's path clear of hands, fingers, or other objects. Acura strongly recommends that you never leave small children unattended in any vehicle – children left alone with the key in the ignition may become injured by the driver's power window. Keep car keys out of the reach of children – even very young children learn how to unlock doors and turn the ignition.

***01V173**

A sudden, significant increase in steering effort, or continuous illumination of the battery charge indicator in the instrument cluster will be indications that this problem has occurred. Also, potential engine overheating will be indicated by the needle in the coolant temperature gauge moving towards the red zone, and by display of the message "COOLANT TEMPERATURE" in the instrument cluster.

Should any of these warnings occur, pull off the road to a safe location and switch off the engine. Contact BMW Roadside Assistance at 1-800-332-4269 immediately to have your vehicle brought to the nearest BMW X5 SAV center.

***01V174**

As a precaution until the vehicle is repaired, listen for any unusual noise coming from underneath the front of the vehicle and/or steering wheel vibration when hitting bumps. If the steering feels unusual or the vehicle becomes difficult to steer, do not drive the vehicle. Please contact your dealer.

***01V195**

If the "BRAKE" warning lamp in the instrument cluster illuminates continuously, or the "CHECK BRAKE FLUID" message (also in the cluster) is displayed, do not drive the vehicle. If this occurs while driving, or if the brake pedal travel increases significantly during brake application, pull off the road to a safe location. Contact BMW Roadside Assistance at 1-800-332-4269 immediately to have your vehicle brought to the nearest BMW X5 SAV center.

***01V196**

If the automatic transmission warning lamp in the instrument cluster illuminates continuously or the "TRANS. FAIL-SAFE PROG" message (also in the cluster) is displayed

after starting the engine, do not drive the vehicle. If this occurs while driving, or your transmission will not upshift from lower gears, pull off the road to a safe location. In either case, first follow the instruction in the Owner's Manual (see "Automatic Transmission" section) to try to restore normal transmission performance. If this is not successful, do not drive your vehicle. Contact BMW Roadside Assistance at 1-800-332-4269 immediately to have your vehicle brought to the nearest BMW X5 SAV center.

***01V197**

If brake pedal travel increases significantly during brake application, or if there is a significant reduction in brake power assist, pull off the road to a safe location. Contact BMW Roadside Assistance at 1-800-332-4269 immediately to have your vehicle brought to the nearest BMW X5 SAV center.

01V202

In the event your windshield wiper arms become entangled, please turn them off and immediately contact the Service department of your authorized Audi dealer and schedule an appointment for the repair.

***01V206**

Should any of these warnings occur, pull off the road to a safe location and switch off the engine. If you notice an electrical smell, or burning and/or smoke from the front of the vehicle, do not open the hood. All occupants should carefully exit the vehicle and move to a location away from traffic. Contact BMW Roadside Assistance at 1-800-332-4269 immediately to have your vehicle brought to the nearest BMW center.

01V222

Until your dealer can install the grounding strap, please avoid cleaning or dusting of the dashboard, particularly in cold, dry weather since these conditions are more conducive to the build up of static electricity.

***01V229001**

Since the solenoid malfunction can occur without prior warning, your vehicle should not be driven until it has been inspected and it has been determined that the affected solenoid is not installed on your vehicle.

If you have not yet been contacted by your Land Rover retailer, your vehicle should be towed to an authorized Land Rover retailer where the specified repairs can be performed.

***01V245**

If you hear a metallic noise, such as scraping, rattling, grinding, etc., from the rear brake area while driving, do not continue to drive. Pull off the road to a safe location. Contact BMW Roadside Assistance at 1-800-332-4269 immediately to have your vehicle brought to the nearest BMW center.

01V247

Please remember to always dim your high beams in the presence of oncoming vehicles.

01V253

You may repair your vehicle yourself by following the instructions printed on the reverse side of this letter. The repair only involves the removal of the power seat circuit breaker. If you prefer not to remove the circuit breaker yourself, simply contact your dealer right away to schedule a service appointment.

01V258

Before repairs are made, you may reduce the likelihood for the condition to occur by not using the intermittent function of the wiper system, and by clearing the windshield (during winter months) of packed snow or ice.

01V259

If you should notice fuel odor prior to the time that the corrective work will be performed and/or the MIL light on your vehicle's instrument panel should come on, please contact your Audi dealer immediately.

01V261

Before repairs are made, you may reduce the likelihood of the switch malfunction condition occurring by not using the intermittent function of the wiper system, and by clearing the windshield (during winter months) of packed snow or ice.

01V264

Until we are able to inspect and, if necessary, replace the power sliding door unlatch actuator in your vehicle, there are some precautions you can take to reduce the potential for serious injury.

- Before starting the vehicle, please make sure that all vehicle occupants are properly seated and restrained by a safety belt. It is important that you and your passengers always buckle up, with children age 12 and under properly secured in a rear seating position. Please refer to your Owner's Manual for specific instructions about correct safety belt use.
- If possible avoid using seating positions nearest to the power sliding door. Also, please make sure that any loose objects in the rear seating area are secured by a convenience net or placed in a storage compartment.
- The power sliding door system has a warning buzzer; however the operator must leave the "power door" feature on for it to work. The buzzer sounds any time that the transmission is not in the "Park" position and the system detects a door that is open, not fully latched or in the process of closing. Additionally, a "door ajar" light will illuminate on the instrument panel when the power sliding door is not completely closed and the ignition is turned to the "run" or "start" position. If you hear the warning buzzer or observe the "door ajar" light, turn off the power sliding door then manually open and close it. Pull back on the door to ensure that it is

latched. Turn the power to the sliding door back on. If the warning buzzer or “door ajar” light are again activated, please take your vehicle to the nearest dealership for inspection and repair if required. There will be no charge for this service.

01V273

We ask that you install the mini-storage bins that are enclosed with this letter. The storage bins enhance head impact protection while providing a convenient location to store sunglasses and other personal items. Please follow the installation instructions printed on the reverse side of this letter.

If you prefer not to install the mini-storage bins yourself, simply contact your dealer right away to schedule a service appointment.

01V282

As a precaution until the vehicle is repaired, listen for any rattling noises from the rear of the vehicle. Always use caution when opening or closing the rear door.

01V307

Please peel off and discard the tire inflation pressure label affixed to the driver’s door. A new label containing the P205/60 R16 tire size and inflation pressure is enclosed with this letter. Please apply the new label to the driver’s door as shown on the attached sketch.

Should you have or anticipate any trouble installing the new label, or if you would rather have your Hyundai Dealer assist you, please call your Hyundai Dealer to make an appointment with them to have the label installed.

01V310

To ensure that this information is available for reference by you or future owners of the vehicle, please place this letter with your minivan’s owner’s manual in the glove box or storage compartment.

01V324

If you notice a burning odor originating in the area of the rear speakers, please turn off the Bose Music System. Stop the vehicle and contact your dealer. Discontinue the use of the Bose Music System until it has been examined by your authorized Audi dealer.

01V325

Prior to having this work performed, please observe any abnormal noises in the vicinity of the rear axle. Should you detect any, please contact the Service Department of your authorized Audi dealer for further instructions.

01V334

Until that service is completed, the driver should always apply the parking brake before exiting the vehicle.

01V345

Hyundai strongly recommends that all occupants always wear seat belts. Infants and small children must be properly restrained in child safety seats or seat belts in the rear seat.

01V357

If the “Service Engine Soon” light comes on, contact your dealer as soon as possible to have your vehicle inspected.

01V380

As soon as possible, you should check all three rear seat belt buckles to determine whether they are affected by this recall. You will find an assembly number stamped on the back of the buckle. For example, an assembly number of 00185AAHMAM. The buckles that need replacement will be stamped with one of the numbers listed in the drawing below.

If any of the rear buckles are marked with a number indicated in the drawing, you should promptly contact any authorized Honda automobile dealer and make an appointment to have the buckles replaced.

If you cannot clearly see the buckle assembly number, or if you are not comfortable inspecting the buckles yourself, please contact any authorized Honda dealer and make an appointment for an inspection.

01V383

Until this service is performed, follow the child seat manufacturer’s instructions for checking to see that a LATCH-type child restraint is installed securely. If there is any question, secure the child restraint with the safety belts, following the instructions of the child seat manufacturer and your vehicle’s owner’s manual.

Appendix B-14

2000 Recalls with Risk Mitigation Instructions in Part 577 letters

Recalls that contain Do Not Drive instructions are starred with an asterisk (*) in this appendix. 2000 Recalls with Do Not Drive instructions also appear separately in appendix A-14, however, they are included here so that this appendix can stand alone as the complete list of Risk Mitigation Instructions. The text for each recall in this appendix is taken from Owner Notification Letters (Part 577).

***00V010**

0

PRECAUTIONS

1. CONTACT YOUR AUTHORIZED BMW CENTER IMMEDIATELY TO HAVE THE NECESSARY INSPECTION/REPAIR PERFORMED AS SOON AS POSSIBLE.
2. If your BMW center confirms that your vehicle has not yet been inspected/repared, do not drive the vehicle.
3. If this problem occurs, your vehicle's steering capability could be lost without warning and, depending on environmental and traffic conditions and the driver's reaction, a crash could occur.
4. If you are not the sole driver of your car, please advise all other drivers not to drive the vehicle.

00V016

Do not use your S2000 convertible top cover until it has been replaced.

***00V036**

Depending upon the severity of the leak, the ACE warning lamp will illuminate amber or red. The illuminated AE lamp indicates that the vehicle should be stopped as soon as safely possible and the engine switched off. The vehicle should be towed to an authorized Land Rover retailer where the specified repairs can be performed.

Should the auxiliary drive system fail, the battery charge warning lamp will illuminate. In the event of such a failure, the engine should be switched off as soon as safely possible and the vehicle should not be driven. It should be towed to an authorized Land Rover retailer where the specified repairs can be performed. If you are not the sole driver of this vehicle, please advise all other drivers of these necessary precautions.

***00V039**

If, prior to having the corrective work performed, you should smell fuel vapors originating in the engine compartment, please refrain from driving your vehicle and contact your nearest authorized Volkswagen dealer immediately.

***00V048**

PRECAUTIONS

1. CONTACT YOUR AUTHORIZED BMW CENTER IMMEDIATELY TO HAVE THE NECESSARY INSPECTION/REPAIR PERFORMED AS SOON AS POSSIBLE.
2. Before the repair, brake lamp operation should be checked with the vehicle stationary by turning the key to position 2 ("ignition" or "on") and depressing the brake pedal. An observer facing the rear of the vehicle can determine if the brake lamps are working properly. If the brake lamps are inoperative or continuously lit, the vehicle should not be driven. Arrangements should be made for pickup and repair.
3. If the inoperative of continuously-lit brake lamps are ignored and the vehicle is

driven, a crash involving another vehicle (or vehicles) could occur without prior warning, depending on environmental and traffic conditions.

4. If you are not the sole driver of your car, please advise all other drivers of these necessary precautions.

00V066 We ask that you apply the enclosed child protection door lock labels so that they cover the original labels. The original labels are located on both rear doors near the door latch (see graphic on the back of this letter). TO assure good adhesion, be sure the original labels are clean and dry before applying the new labels.

If you prefer not to install the labels yourself, simply contact your dealer to schedule a service appointment.

***00V069** Users and/or Customers of Generation I, 1997 Evs are urged to park their vehicle and immediately discontinue any and all vehicle charging. It is recommended that customers park their vehicle away from the charger to help prevent inadvertent use of the charging system.

00V106 Always ensure that the vehicle gearshift selector is placed into the park position, the ignition key is removed and the parking brake is applied before exiting your vehicle.

00V121 You should continue to take special precautions until your vehicle has been returned to the dealer. First, always wear your safety belt. Safety belts provide excellent protection against all types of injuries, including head impact. Second, keep the passenger-side sun visor in its stowed position (against the roof and away from the windshield) and the driver's sun visor in the stowed position unless necessary for safe driving.

***00V142** Should the serpentine drive belt fail, the battery charge warning lamp will illuminate immediately. The amber ACE warning lamp may illuminate. In the event of such a failure, the engine should be switched off as soon as safely possible and the vehicle should not be driven. It should be towed to an authorized Land Rover retailer where the specified repairs can be performed. If you are not the sole driver of this vehicle, please advise all other drivers of these necessary precautions.

***00V187** Should abnormal noise or vibration occur upon the application of the brakes, the vehicle should be stopped as soon as safely possible. The vehicle should not be driven if unusual braking characteristics are encountered. It should be towed to an authorized Land Rover retailer where appropriate repairs can be performed. If you are not the sole driver of this vehicle, please advise all other drivers of these necessary precautions.

00V200 You may install the revised instructions/labels yourself, or have the service performed by your dealer free of charge.

00V205 To correct this error, we have enclosed a sticker for you to apply to the page with the error in your Owner's Manual. Please apply this sticker using the instructions below...

If you misplace or spoil the sticker, you may go to your dealer to obtain a replacement sticker.

00V242 Enclosed is a supplemental label to place next to the existing safety certification

label. This label has the appropriate load information. The supplemental certification label is provided free of charge. To install the label yourself, instructions are enclosed. If you prefer, your dealer will install the safety certification label for you at no cost.

00V256 Until the repair is done, owners should make sure their engine has reached operating temperature prior to use.

00V258 Since a new label can be easily installed, and to reduce the possible inconvenience to you, we are enclosing a label and instruction on installing the label. However, if you desire, you may take the label to your dealer for installation.

00V280 The defect relates to the control arm of the vehicle's front suspension. Volkswagen has found that in a small number of instances one of two brackets used to bolt the control arm in front of the vehicle to the body structure may not have been welded sufficiently to meet the manufacturer's specifications. Depending on the strength of the weld seams, the control arm could gradually loosen and ultimately separate from its bracket in normal driving which could cause the vehicle to be difficult to control or result in loss of control. As the bracket loosens, loud metallic knocking sounds in front of the vehicle will be heard. If you hear such a sound, please bring the vehicle to a safe stop immediately and telephone your Volkswagen dealer. If this warning is not heeded, a vehicle accident could occur.

00V286 Enclosed, please find an update owner's manual. Please review the information about top strap anchor brackets on pages 2-13 and 2-14 of the updated owner's manual. Discard the previous owner's manual and place the updated manual in the glove box of your car for future reference.

00V287 If you are experiencing problems starting your car, have it repaired promptly and do not leave the car in a building.

***00V288** As a precaution until the vehicle is repaired, keep your foot on the brake pedal and release it slowly after shifting gears to ensure that the transmission is in the gear that you have selected. If the transmission becomes stuck in the Park position but the shift selector moves, do not attempt to get out of Park or drive the vehicle. Please contact your dealer. Always set the parking brake when the transmission is in Park.

00V310 You may choose to perform a simple functional check yourself using the enclosed inspection procedure. If the vehicle performs as it should in this check the above condition should not be possible, and no park lock cable assembly adjustment is necessary. If it does not perform correctly, your Saturn Retailer will make the necessary adjustment.

If you are not comfortable performing this inspection yourself, your Saturn Retailer can perform the inspection for you and, if necessary, make the needed adjustment.

***00V317** Please make a quick check of the operation of your car's electrical accessories such as the turn signals, windshield wipers, headlights or electrical windows after you have started the engine and before you begin driving in order to make sure that they function properly. If they do not function, switch off the engine and restart it and check again, or, call your authorized dealer so that repairs can be performed. Do you drive your Audi if the turn signals, windshield wipers or headlights do not

operate after you have started the engine.

***00V341** PRECAUTIONS

1. CONTACT YOUR AUTHORIZED BMW X5 SAV CENTER IMMEDIATELY TO HAVE THE NECESSARY INSPECTION/REPAIR PERFORMED AS SOON AS POSSIBLE.X
2. If you experience significant steering wheel play and/or misalignment (approximately 30 degrees or more), or noise from the steering linkage, do not drive the vehicle. In this case, or if you feel uncomfortable driving your vehicle as a result of this recall notice please contact BMW Roadside Assistance at 1-800-332-4289 or you nearest X5 SAV center to arrange for towing service to that center.
3. If you do not observe this precaution and this problem occurs, your vehicle's steering capability could be drastically reduced and, depending on environmental and traffic conditions and the driver's reaction, a crash could occur.
4. If you are not the sole driver of your car, please advise all other drivers not to drive the vehicle if the conditions described in paragraph 2 occur.

00V346 Before this repair is complete, if the wipers stop operating in the low or intermittent settings or the washer runs continuously, the wipers will usually work if you select the high setting. If that does not work, stop in a safe place. Turning the engine off and then restarting it will restore normal operation.

00V366 To ensure that you understand the proper way to attach a child restraint system tether strap and that you know which seat positions have tether anchorages, DaimlerChrysler is sending you the enclosed owner's manual addendum card. Please take the time to review the instructions and then place the card in the vehicle's glove box or storage compartment with your owner's manual. This will keep the card available for reference by you or future owners, if your vehicle is sold.

00V377 To minimize the risk of fire, owners should seek assistance from a Land Rover Retailer if any under-hood fluid loss is observed prior to the performance of this recall.

If you are not the sole driver of this vehicle, please advise all other drivers of these necessary precautions.

***00V383** PRECAUTIONS

1. CONTACT YOUR AUTHORIZED BMW CENTER IMMEDIATELY TO HAVE THE NECESSARY INSPECTION/REPAIR PERFORMED AS SOON AS POSSIBLE.
2. If you feel uncomfortable driving your vehicle as a result of this recall, please contact BMW Roadside Assistance at 1-800-332-4289 or your nearest BMW center to arrange for towing service to that center.
3. If this problem occurs, your vehicle's handling and control would be drastically affected and, depending on environmental and traffic conditions and the driver's reaction, a crash could occur.
4. If you are not the sole driver of your car, please advise all other drivers of this important information.

***00V388** Please ensure that you and all vehicle occupants wear your seat belts, sit back properly, and do not lean on either front door. Prior to your scheduled service appointment, if the supplemental restraint system (SRS) indicator lamp remains

- illuminated after start up, or comes on while driving, we recommend you stop driving your vehicle immediately and contact your retailer.
- 00V392** In the meantime, persons who cannot comfortably fit in the seatbelt should not sit in the center rear seat position.
- 00V396** Enclosed is a label to place over one page of the existing Owner's Guide. This label contains all of the safety positions available for a child seat. This Owner's Guide page label is provided free of charge.
To install the label yourself, please refer to the enclosed instructions. If you prefer, your dealer will install this label for you at no cost.
- *00V410** As a precaution until the vehicle is repaired, watch for any looseness in the ignition key lock. If the end cap is loose or you are able to slide the ignition lock mechanism in and out, do not drive the vehicle. Please contact your dealer to have your vehicle towed to the dealership if any of the above symptoms occur, or if you are unsure of their occurrence.
- 00V414** Precautions you can take
If, prior to the time that the corrective work is performed, you experience a "knocking" sound from your steering assembly, especially while driving over rough road conditions, or feel "loose" steering, please contact your authorized Volkswagen dealer as soon as you can do so.
- 00V415** We ask that you apply the enclosed tire label so that it covers the original incorrect label. The original label is located on the rear edge of the driver's door (Figure 1). To assure good adhesion, be sure the original tire label is clean and dry before applying the new label.
If you prefer not to install the label yourself, simply contact your dealer to schedule a service appointment.
- *00V423** Depending on the severity of the leak, the ACE warning lamp will illuminate amber or red. The illuminated ACE lamp indicates that the vehicle should be stopped as soon as safely possible and the engine switched off. The vehicle should be towed to an authorized Land Rover Retailer where the specified repairs can be performed. Should the auxiliary drive system fail, the battery charge warning lamp will illuminate. In the event of such a failure, the engine should be switched off as soon as safely possible and the vehicle should not be driven. It should be towed to an authorized Land Rover Retailer where the specified repairs can be performed. If you are not the sole driver of this vehicle, please advise all other drivers of these necessary precautions.
- 00V432** Since a new label can be easily installed, and to reduce your inconvenience, the label and installation instructions are being sent with this letter. You may install the label directly over the incorrect label on the rear vertical face of the driver's door. However, if you desire, you may bring the label to your dealer for installation at no charge.

Appendix C-1

2013 Regional Recalls

The text for each recall in this appendix is taken from Owner Notification Letters (Part 577) or the Defect and Noncompliance Notice (Part 573).

13V081

Certain vehicles originally sold in or currently registered in Connecticut Delaware Illinois Indiana Iowa Maine Maryland Massachusetts Michigan Minnesota Missouri New Hampshire New Jersey New York Ohio Pennsylvania Rhode Island Vermont West Virginia Wisconsin and the District of Columbia.

13V385

The affected vehicles are currently registered or were originally sold in Connecticut Delaware the District of Columbia Illinois Indiana Iowa Kentucky Maine Maryland Massachusetts Michigan Minnesota Missouri New Hampshire New Jersey New York Ohio Pennsylvania Rhode Island Vermont Virginia West Virginia and Wisconsin.

13V093

Certain vehicles originally sold in or currently registered in Connecticut Delaware Illinois Indiana Iowa Kentucky Maine Maryland Massachusetts Michigan Minnesota Missouri New Hampshire New Jersey New York Ohio Pennsylvania Rhode Island Vermont Virginia West Virginia Wisconsin and the District of Columbia.

13V354

Certain vehicles originally sold in or currently registered in Connecticut Delaware Illinois Indiana Iowa Maine Maryland Massachusetts Michigan Minnesota Missouri New Hampshire New Jersey New York Ohio Pennsylvania Rhode Island Vermont West Virginia Wisconsin and the District of Columbia.

13V556

Certain vehicles sold in or currently registered in Massachusetts Maryland Michigan New Hampshire New York Pennsylvania Vermont Wisconsin Connecticut Delaware Iowa Illinois Indiana Maine Minnesota Missouri New Jersey Ohio Rhode Island West Virginia and the District of Columbia.

13V547

Certain vehicles originally sold in or are currently registered in Maine New Hampshire Vermont Massachusetts Rhode Island Connecticut New York New Jersey Pennsylvania Delaware Maryland the District of Columbia West Virginia Ohio Indiana Michigan Illinois Wisconsin Minnesota Iowa Kentucky and Missouri.

13V550

Certain vehicles originally sold in or currently registered in Massachusetts Maryland Michigan New Hampshire New York Pennsylvania Vermont Wisconsin Connecticut Delaware Iowa Illinois Indiana Maine Minnesota Missouri New Jersey Ohio Rhode Island West Virginia or the District of Columbia.

13V541

Certain vehicles originally sold in or currently registered in Florida Georgia Alabama Mississippi Louisiana and Texas.

13V110

Certain vehicles currently or formerly registered in Connecticut Delaware Illinois Indiana Iowa Maine Maryland Massachusetts Michigan Minnesota Missouri New Hampshire New Jersey New York Ohio Pennsylvania Rhode Island Vermont West Virginia Wisconsin and the District of Columbia.

Appendix C-2

2012 Regional Recalls

The text for each recall in this appendix is taken from Owner Notification Letters (Part 577) or the Defect and Noncompliance Notice (Part 573).

12V085

ORIGINALLY SOLD OR CURRENTLY REGISTERED IN CONNECTICUT DELAWARE ILLINOIS INDIANA IOWA MAINE MARYLAND MASSACHUSETTS MICHIGAN MINNESOTA MISSOURI NEW HAMPSHIRE NEW JERSEY NEW YORK OHIO PENNSYLVANIA RHODE ISLAND VERMONT WEST VIRGINIA WISCONSIN AND THE DISTRICT OF COLUMBIA"

12V151

Certain vehicles registered in areas with moderate to heavy annual snowfall. These areas are listed below. Canada Indiana Nebraska South Dakota Alaska Iowa New Hampshire Utah Colorado Maine New Jersey Vermont Connecticut Maryland New York West Virginia Delaware Massachusetts North Dakota Wisconsin District of Columbia Michigan Ohio Wyoming Idaho Minnesota Pennsylvania Illinois Montana Rhode Island.

12V193

CURRENTLY REGISTERED OR ORIGINALLY SOLD IN VIRGINIA.

12V194

CURRENTLY REGISTERED OR ORIGINALLY SOLD IN VIRGINIA.

12V195

Certain vehicles REGISTERED IN PUERTO RICO.

12V306

Certain vehicles ORIGINALLY SOLD OR ARE CURRENTLY REGISTERED IN THE STATES OF MAINE NEW HAMPSHIRE VERMONT MASSACHUSETTS RHODE ISLAND CONNECTICUT NEW YORK NEW JERSEY PENNSYLVANIA DELAWARE MARYLAND THE DISTRICT OF COLUMBIA WEST VIRGINIA OHIO INDIANA MICHIGAN ILLINOIS WISCONSIN MINNESOTA IOWA MISSOURI AND KENTUCKY.

12V388

Certain vehicles originally sold or currently registered in Connecticut Delaware Illinois Indiana Iowa Maine Maryland Massachusetts Michigan Minnesota Missouri New Hampshire New Jersey New York Ohio Pennsylvania Rhode Island Vermont West Virginia Wisconsin and the District of Columbia.

12V406

Certain vehicles currently or previously registered in Connecticut, Delaware, District of Columbia, Illinois, Indiana, Iowa, Maine, Maryland, Massachusetts, Michigan,

Minnesota, Missouri, New Hampshire, New Jersey, New York, Ohio, Pennsylvania, Rhode Island, Vermont, West Virginia, Wisconsin, New Brunswick, Newfoundland, Nova Scotia, Ontario, Prince Edward Island, Quebec, Europe, Japan, and Russia.

12V459

Certain vehicles originally sold or currently registered in Arkansas Arizona California Florida Nevada Oklahoma or Texas.

12V542

Certain vehicles originally sold or currently registered in the following cold climate states with high road salt usage: Connecticut Delaware Illinois Indiana Kentucky Maine Maryland Massachusetts Michigan Minnesota New Hampshire New Jersey New York Ohio Pennsylvania Rhode Island Vermont Virginia West Virginia Wisconsin and the District of Columbia.

12V597

Originally sold or currently registered in Arizona California Nevada and Texas.

Appendix C-3

2011 Regional Recalls

The text for each recall in this appendix is taken from Owner Notification Letters (Part 577) or the Defect and Noncompliance Notice (Part 573).

11V030

Connecticut, Delaware, the District of Columbia, Illinois, Indiana, Iowa, Kentucky, Maine, Maryland, Massachusetts, Michigan, Minnesota, Missouri, New Hampshire, New Jersey, New York, Ohio, Pennsylvania, Rhode Island, Utah, Vermont, West Virginia, and Wisconsin.

11V244

Connecticut, Delaware, Iowa, Illinois, Indiana, Massachusetts, Maine, Maryland, Michigan, Minnesota, Missouri, New Hampshire, New Jersey, New York, Ohio, Pennsylvania, Rhode Island, Vermont, Washington D.C., West Virginia and Wisconsin.

11V464

Connecticut, Maine, New Hampshire, Vermont, Delaware, Maryland, New Jersey, West Virginia, District of Columbia, Massachusetts, New York, Wisconsin, Illinois, Michigan, Ohio, Indiana, Minnesota, Pennsylvania, Iowa, Missouri, Rhode Island.

Appendix C-4

2010 Regional Recalls

The text for each recall in this appendix is taken from Owner Notification Letters (Part 577) or the Defect and Noncompliance Notice (Part 573).

10V007

Puerto Rico

10V008

20 salt belt states plus DC, KY, ND, SD, UT, NE, KS and AK

10V065

U.S. salt-belt states, the adjoining states, cold weather states, and Canada

10V105

Connecticut, Delaware, Illinois, Indiana, Iowa, Maine, Maryland, Massachusetts, Michigan, Minnesota, Missouri, New Hampshire, • New Jersey, New York, Ohio, Pennsylvania, Rhode Island, Vermont, Washington D.C., West Virginia and Wisconsin

10V160

The following 20 Severe Cold Climate States and the District of Columbia. CT, DE, IL, IN, KY, MA, MD, ME, MI, MN, NH, NJ, NY, OH, PA, RI, VA, VT, WI & WV

10V385

Utah, Connecticut, Delaware, the District of Columbia, Illinois, Indiana, Iowa, Kentucky, Maine, Maryland, Massachusetts, Michigan, Minnesota, Missouri, New Hampshire, New Jersey, New York, Ohio, Pennsylvania, Rhode Island, Vermont, West Virginia, and Wisconsin.

10V436

Maine, New Hampshire, Vermont, Massachusetts, Rhode Island, Connecticut, New York, New Jersey, Pennsylvania, Delaware, Maryland, the District of Columbia, West Virginia, Ohio, Indiana, Michigan, Illinois, Wisconsin, Minnesota, Iowa and Missouri, as well as Kentucky, which is not always considered to be in the "salt belt".

10V457

Puerto Rico

Appendix C-5

2009 Regional Recalls

The text for each recall in this appendix is taken from Owner Notification Letters (Part 577) or the Defect and Noncompliance Notice (Part 573).

09V123

CERTAIN VEHICLES ORIGINALLY SOLD IN OR CURRENTLY REGISTERED IN THE STATES OF CONNECTICUT DELAWARE ILLINOIS INDIANA IOWA MAINE MARYLAND MASSACHUSETTS MICHIGAN MINNESOTA MISSOURI NEW HAMPSHIRE NEW JERSEY NEW YORK OHIO PENNSYLVANIA RHODE ISLAND VERMONT WEST VIRGINIA WISCONSIN AND THE DISTRICT OF COLUMBIA.

09V124

CERTAIN VEHICLES ORIGINALLY SOLD IN OR CURRENTLY REGISTERED IN THE STATES OF CONNECTICUT DELAWARE ILLINOIS INDIANA IOWA MAINE MARYLAND MASSACHUSETTS MICHIGAN MINNESOTA MISSOURI NEW HAMPSHIRE NEW JERSEY NEW YORK OHIO PENNSYLVANIA RHODE ISLAND VERMONT WEST VIRGINIA WISCONSIN AND THE DISTRICT OF COLUMBIA

09V125

CERTAIN VEHICLES ORIGINALLY SOLD IN OR CURRENTLY REGISTERED IN THE STATES OF CONNECTICUT DELAWARE ILLINOIS INDIANA IOWA MAINE MARYLAND MASSACHUSETTS MICHIGAN MINNESOTA MISSOURI NEW HAMPSHIRE NEW JERSEY NEW YORK OHIO PENNSYLVANIA RHODE ISLAND VERMONT WEST VIRGINIA WISCONSIN AND THE DISTRICT OF COLUMBIA

09V183

CERTAIN VEHICLES ORIGINALLY SOLD IN OR CURRENTLY REGISTERED IN THE STATES OF CONNECTICUT DELAWARE ILLINOIS INDIANA IOWA MAINE MARYLAND MASSACHUSETTS MICHIGAN MINNESOTA MISSOURI NEW HAMPSHIRE NEW JERSEY NEW YORK OHIO PENNSYLVANIA RHODE ISLAND VERMONT WEST VIRGINIA WISCONSIN AND THE DISTRICT OF COLUMBIA

09V310

PASSENGER VEHICLES ORIGINALLY SOLD IN OR CURRENTLY REGISTERED IN THE STATES OF ALABAMA ARIZONA FLORIDA GEORGIA HAWAII LOUISIANA MISSISSIPPI NEVADA NEW MEXICO PUERTO RICO SOUTH CAROLINA TEXAS U.S. VIRGIN ISLANDS AND UTAH.

09V338

ORIGINALLY SOLD IN OR CURRENTLY REGISTERED IN THE STATES OF ALASKA COLORADO IDAHO ILLINOIS IOWA KANSAS MAINE MICHIGAN MINNESOTA MONTANA NEBRASKA NEVADA NEW HAMPSHIRE NEW YORK NORTH DAKOTA SOUTH DAKOTA VERMONT WISCONSIN AND WYOMING.

09V392

ORIGINALLY SOLD IN OR CURRENTLY REGISTERED IN THE STATES OF ALASKA COLORADO IDAHO ILLINOIS IOWA KANSAS MAINE MICHIGAN MINNESOTA MONTANA NEBRASKA NEVADA NEW HAMPSHIRE NEW YORK NORTH DAKOTA SOUTH DAKOTA VERMONT WISCONSIN AND WYOMING.

09V393

NISSAN IS RECALLING CERTAIN MODEL YEAR 2008-2010 VEHICLES ORIGINALLY SOLD IN OR CURRENTLY REGISTERED IN THE STATES OF CONNECTICUT DELAWARE IOWA ILLINOIS INDIANA MASSACHUSETTS MAINE MARYLAND MICHIGAN MINNESOTA MISSOURI NEW HAMPSHIRE NEW JERSEY NEW YORK OHIO PENNSYLVANIA RHODE ISLAND VERMONT WASHINGTON D.C. WEST VIRGINIA AND WISCONSIN.

09V419

CERTAIN VEHICLES ORIGINALLY SOLD IN OR CURRENTLY REGISTERED IN THE STATES OF ARIZONA AND NEVADA; AND MODEL YEAR 2007 CHEVROLET COBALT PONTIAC G5 AND SATURN ION VEHICLES ORIGINALLY SOLD IN OR CURRENTLY REGISTERED IN THE STATES OF ARIZONA CALIFORNIA FLORIDA NEVADA AND TEXAS.

09V444

CERTAIN VEHICLES ORIGINALLY SOLD IN OR CURRENTLY REGISTERED IN THE FOLLOWING STATES: CONNECTICUT DELAWARE ILLINOIS INDIANA KENTUCKY MAINE MARYLAND MASSACHUSETTS MICHIGAN MINNESOTA NEW HAMPSHIRE NEW JERSEY NEW YORK OHIO PENNSYLVANIA RHODE ISLAND VERMONT VIRGINIA WEST VIRGINIA WISCONSIN AND THE DISTRICT OF COLUMBIA.

09V468

CERTAIN MODEL YEAR 2002 AND 2003 IMPREZA WRX VEHICLES ORIGINALLY SOLD IN OR CURRENTLY REGISTERED IN THE STATES OF SOUTH DAKOTA NEBRASKA NORTH DAKOTA MINNESOTA IDAHO IOWA MONTANA COLORADO WISCONSIN NEW YORK WYOMING MICHIGAN ALASKA NEW HAMPSHIRE VERMONT AND MAINE.

09V483

CERTAIN VEHICLES SOLD IN OR REGISTERED IN THE STATES OF ALABAMA ARIZONA ARKANSAS CALIFORNIA FLORIDA GEORGIA HAWAII KENTUCKY LOUISIANA MISSISSIPPI NEVADA NEW MEXICO NORTH CAROLINA OKLAHOMA SOUTH CAROLINA TENNESSEE TEXAS UTAH VIRGINIA AND THE U.S. TERRITORIES.

Appendix C-6

2008 Regional Recalls

The text for each recall in this appendix is taken from Owner Notification Letters (Part 577) or the Defect and Noncompliance Notice (Part 573).

08V094

Affected Salt Belt Regions: Connecticut, Delaware, Illinois, Indiana, Iowa, Kentucky, Maine, Maryland, Massachusetts, Michigan, Minnesota, Missouri, New Hampshire, New Jersey, New York, Ohio, Pennsylvania, Rhode Island, Vermont, Virginia, West Virginia, Wisconsin, and Washington D.C.

08V410

General Motors has decided that a defect that relates to motor vehicle safety exists in certain 2008 Buick Enclave, and 2007-2008 GMC Acadia and Saturn Outlook vehicles currently or previously registered in areas with moderate to heavy annual snowfall. These areas are listed below.

Canada, Alaska, Colorado, Connecticut, Delaware, District of Columbia, Idaho, Illinois, Indiana, Iowa, Maine, Maryland, Massachusetts, Michigan, Minnesota, Montana, Nebraska, New Hampshire, New Jersey, New York, North Dakota, Ohio, Pennsylvania, Rhode Island, South Dakota, Utah, Vermont, West Virginia, Wisconsin, Wyoming.

08V690

In those areas of the country which use heavy concentrations of road salt in the winter ("Salt States"), a mixture of snow/water and salt can enter into the front crash zone sensor (CZS) housing during continuous driving. As a result, corrosion can occur and the CZS may internally rust resulting in a signal interruption. If this happens, the red air bag warning light will illuminate to alert the vehicle operator. This could result in the driver and passenger front air bags not inflating in a crash. Below are the states that regularly use road salt in winter:

Connecticut, Delaware, District of Columbia, Illinois, Indiana, Iowa, Maine, Maryland, Massachusetts, Michigan, Minnesota, Missouri, New Hampshire, New Jersey, New York, Ohio, Pennsylvania, Rhode Island, Vermont, West Virginia, Wisconsin.

Appendix C-7

2007 Regional Recalls

The text for each recall in this appendix is taken from Owner Notification Letters (Part 577) or the Defect and Noncompliance Notice (Part 573).

07V152

The vehicles involved in this recall are certain MY2001 and MY2002 S60 Volvo vehicles within the States of Arizona and Nevada.

07V197

Therefore, Hyundai Motor Company has decided to conduct a recall in Puerto Rico to replace the driver airbag module of 2005 through 2007 model year Hyundai Tucson vehicles . . .

07V328

Chevrolet Optra: 78 vehicles in Guam/Saipan
(Guam: 75 veh., Saipan 3 veh.)

07V349

The vehicle population is Rendezvous and Aztek vehicles built in May 2003, Venture and Montana vehicles built in June through August 2002 and all vehicles registered in Nevada, Arizona, Virgin Islands, Puerto Rico and Hawaii.

07V435

The fuel filler tube in your Pathfinder may have insufficient amount of coating at the lower mounting bracket. If there is insufficient coating, corrosion may occur in geographic areas that regularly use road salt in the winter. The corrosion can result in perforation of the fuel filler tube and fuel leakage. If there is a fuel leakage, in the presence of an ignition source, a fire can result. Below are States that regularly use road salt in the winter: Connecticut, Delaware, District of Columbia, Illinois, Indiana, Iowa, Kentucky, Maine, Maryland, Massachusetts, Michigan, Minnesota, New Hampshire, New Jersey, New York, Ohio, Pennsylvania, Rhode Island, Tennessee, Vermont, Virginia, West Virginia, Wisconsin.

07V549

Affected Salt belt Regions: Connecticut, Delaware, Illinois, Indiana, Iowa, Kentucky, Maine, Maryland, Massachusetts, Michigan, Minnesota, Missouri, New Hampshire, New Jersey, New York, Ohio, Pennsylvania, Rhode Island, Vermont, Virginia, West Virginia, Wisconsin, and Washington D.C.

Appendix C-8

2006 Regional Recalls

The text for each recall in this appendix is taken from Owner Notification Letters (Part 577) or the Defect and Noncompliance Notice (Part 573).

06V383

Number of Vehicles Involved - Ford estimates that there are approximately 139,537 affected vehicles currently registered in the following states that will be part of this safety recall:

Alaska	Iowa	Michigan	New Jersey	South Dakota
Colorado	Kansas	Minnesota	New York	Utah
Connecticut	Kentucky	Missouri	North Dakota	Vermont
Delaware	Maine	Montana	Ohio	West Virginia
Idaho	Maryland	Nebraska	Pennsylvania	Wisconsin
Illinois	Massachusetts	New Hampshire	Rhode Island	Wyoming
Indian				

06V463

Affected Areas:

Alaska, Connecticut, Colorado, Delaware, Idaho, Illinois, Indiana, Iowa, Kansas, Kentucky, Maine, Maryland, Massachusetts, Michigan, Minnesota, Missouri, Montana, Nebraska, New Hampshire, New Jersey, New York, North Dakota, Ohio, Pennsylvania, Rhode Island, South Dakota, Utah, Vermont, West Virginia, Wisconsin, Wyoming

Appendix C-9

2005 Regional Recalls

The text for each recall in this appendix is taken from Owner Notification Letters (Part 577) or the Defect and Noncompliance Notice (Part 573).

05V030

CERTAIN VEHICLES ORIGINALLY SOLD IN OR CURRENTLY REGISTERED IN CONNECTICUT DELAWARE ILLINOIS INDIANA IOWA MAINE MARYLAND MASSACHUSETTS MICHIGAN MINNESOTA MISSOURI NEW HAMPSHIRE NEW JERSEY NEW YORK OHIO PENNSYLVANIA RHODE ISLAND VERMONT WEST VIRGINIA WISCONSIN AND THE DISTRICT OF COLUMBIA

05V385

CERTAIN VEHICLES ORIGINALLY SOLD IN OR CURRENTLY REGISTERED IN THE STATES OF CONNECTICUT DELAWARE ILLINOIS INDIANA IOWA KENTUCKY MAINE MARYLAND MASSACHUSETTS MICHIGAN MINNESOTA MISSOURI NEW HAMPSHIRE NEW JERSEY NEW YORK OHIO PENNSYLVANIA RHODE ISLAND VERMONT VIRGINIA WEST VIRGINIA WISCONSIN AND THE DISTRICT OF COLUMBIA.

Appendix C-10

2004 Regional Recalls

The text for each recall in this appendix is taken from Owner Notification Letters (Part 577) or the Defect and Noncompliance Notice (Part 573).

04V332

Approximately 899,060 total vehicles currently registered in the states of Connecticut, Delaware, District of Columbia, Illinois, Indiana, Iowa, Kentucky, Maine, Maryland, Massachusetts, Michigan, Minnesota, Missouri, New Hampshire, New Jersey, New York, Ohio, Pennsylvania, Rhode Island, Vermont, West Virginia, and Wisconsin.

04V495

VWoA plans to notify all owners of affected vehicles in cold-weather states and instruct them to ring their vehicles in so that a replacement throttle body kit can be installed at no charge. VWoA has identified the following cold-weather states based on known occurrences or geographic location: Alaska, Colorado, Connecticut, Delaware, Idaho, Illinois, Indiana, Iowa, Maine, Maryland, Massachusetts, Michigan, Minnesota, Montana, Nebraska, Nevada, New Hampshire, New Jersey, New York, North Dakota, Ohio, Oregon, Pennsylvania, Rhode Island, South Dakota, Vermont, Washington, Wisconsin, and Wyoming.

Appendix C-11

2003 Regional Recalls

The text for each recall in this appendix is taken from Owner Notification Letters (Part 577) or the Defect and Noncompliance Notice (Part 573).

03V153

Subaru has determined that your vehicle may have been manufactured with a rear sub-frame assembly with poor paint quality. If the vehicle is operated for an extensive period in a “salt-belt” area (see list of states above that use salt on the roads in the winter), continued exposure to salt could cause the rear sub-frame assembly to rust-out and eventually break.

Subaru has decided that a defect which relates to motor vehicle safety, exists in some 2000-2003 model year Subaru Legacy, Outback and BAJA vehicles originally sold or currently registered in the states of: Connecticut, Delaware, District of Columbia, Illinois, Indiana, Iowa, Kentucky, Maine, Maryland, Massachusetts, Michigan, Minnesota, Missouri, New Hampshire, New Jersey, New York, Ohio, Pennsylvania, Rhode Island, Vermont, Virginia, West Virginia and Wisconsin.

03V232

This defect report concerns certain 2003 Subaru Legacy and Outback vehicles in “salt-belt” states.” Certain left hand front transverse link components were produced by the supplier with poor electro-deposition coating quality which, after continued exposure to corrosive road salts for a period of several years, may result in rust-out of the component and possible breakage of the transverse link.

The left-hand front transverse link of vehicles operated in the salt belt states will be rust-proofed with anti-rust wax at no cost to the owner.

03V251

This applies to 2002-2003 model year Nissan Altima vehicles produced from August 1, 2001 to May 20, 2003. At extremely cold temperatures, moisture in the fuel tank may freeze and form ice crystals. These ice crystals may obstruct the suction opening of the fuel pump. This can prevent the supply of fuel to the engine and cause the engine to stop.

Owners of vehicles in states where extremely cold temperatures can occur in the winter will be request to take their vehicle to a Nissan dealer. The states include Alaska, Colorado, Connecticut, Iowa, Idaho, Illinois, Indiana, Kansas, Massachusetts, Maine, Michigan, Minnesota, Missouri, Montana, North Dakota, Nebraska, New Hampshire, New York, Ohio, Pennsylvania, Rhode Island, South Dakota, Utah, Vermont, Wisconsin and Wyoming.

Appendix C-12

2002 Regional Recalls

The text for each recall in this appendix is taken from Owner Notification Letters (Part 577) or the Defect and Noncompliance Notice (Part 573).

02V101

Number of Vehicles Involved: Approximately 250,283 originally sold or currently registered in the states of Connecticut, Delaware, District of Columbia, Illinois, Indiana, Iowa, Maine, Maryland, Massachusetts, Michigan, Minnesota, Missouri, New Hampshire, New Jersey, New York, Ohio, Pennsylvania, Rhode Island, Vermont, West Virginia, and Wisconsin will be inspected and crossover brake lines will be replaced if necessary.

02V341

Hyundai has decided that a defect which relates to motor vehicle safety, exists in certain 1995, 1996 and 1997 Accent vehicles manufactured through August 31, 1996 and registered and operated in the states of Connecticut, Delaware, Illinois, Indiana, Iowa, Maine, Maryland, Massachusetts, Michigan, Minnesota, Missouri, New Hampshire, New Jersey, New York, Ohio, Pennsylvania, Rhode Island, Vermont, West Virginia, and Wisconsin, and the District of Columbia.

Appendix C-13

2001 Regional Recalls

The text for each recall in this appendix is taken from Owner Notification Letters (Part 577) or the Defect and Noncompliance Notice (Part 573).

01V040

DaimlerChrysler will institute the recall consistent with NHTSA's published list of states within the salt belt (per the NHTSA's definition dated September 4, 1998: Maine, New Hampshire, Vermont, Massachusetts, Rhode Island, Connecticut, New York, New Jersey, Pennsylvania, Delaware, Maryland, the District of Columbia, West Virginia, Ohio, Indiana, Michigan, Illinois, Wisconsin, Minnesota, Iowa and Missouri).

01V068

Your dealer will replace the passenger side Windshield wiper pivot housing for vehicles in all Canadian provinces and in states with moderate to heavy annual snowfall:

Alaska	Colorado	Connecticut	Delaware	District of Columbia
Idaho	Illinois	Indiana	Iowa	Maine
Maryland	Massachusetts	Michigan	Minnesota	Montana
Nebraska	New Hampshire	New Jersey	New York	North Dakota
Ohio	Pennsylvania	Rhode Island	South Dakota	Utah
Vermont	West Virginia	Wisconsin	Wyoming	

01V199

Certain 1997 and 1998 model year Ford Windstar vehicles built at the Oakville Assembly Plant from August 28, 1996 through July 3, 1998 and currently registered in the states of Connecticut, Delaware, District of Columbia, Illinois, Indiana, Iowa, Maine, Maryland, Massachusetts, Michigan, Minnesota, Missouri, New Hampshire, New Jersey, New York, Ohio, Pennsylvania, Rhode Island, Vermont, West Virginia, and Wisconsin and in the Canadian provinces of New Brunswick, Newfoundland, Nova Scotia, Ontario, Prince Edward Island, and Quebec.

01V200

The safety recall will include 1996 and 1997 T 105*6 utilities built in the months of November 1995, June 1996, and October 1996 and located in Minnesota, Wisconsin, Iowa, Missouri, Illinois, Michigan, Indiana, Ohio, West Virginia, Pennsylvania, Maryland, Washington DC, Delaware, New York, New Jersey, Connecticut, Rhode Island, Massachusetts, Vermont, New Hampshire and Maine.

01V255

Approximately 108,000 total vehicles manufactured at Ford's Kansas City Assembly Plant from September 9, 1996 through April 18, 1998, including approximately 82,000 originally sold or currently registered in the states of Connecticut, Delaware, District of Columbia, Illinois, Indiana, Iowa, Maine, Maryland, Massachusetts, Michigan,

Minnesota, Missouri, New Hampshire, New Jersey, New York, Ohio, Pennsylvania, Rhode Island, Vermont, West Virginia, and Wisconsin and approximately 26,000 in the Canadian provinces of New Brunswick, Newfoundland, Nova Scotia, Ontario, Prince Edward Island, and Quebec.

01V346

Some 200 and 2001 Hyundai Accent vehicles produced beginning August 30, 1999 through May 22, 2001 that are registered in and operated in the following 23 “cold weather” states: Alaska, Colorado, Iowa, Idaho, Illinois, Indiana, Kansas, Massachusetts, Maine, Michigan, Minnesota, Missouri, Montana, North Dakota, Nebraska, New Hampshire, New York, Ohio, Pennsylvania, South Dakota, Vermont, Wisconsin, and Wyoming.

Appendix C-14

2000 Regional Recalls

The text for each recall in this appendix is taken from Owner Notification Letters (Part 577) or the Defect and Noncompliance Notice (Part 573).

00V063

Connecticut, Kansas, Minnesota, Pennsylvania, Delaware, Kentucky, Missouri, Rhode Island, District of Columbia, Maine, New Hampshire, Vermont, Illinois, Maryland, New Jersey, Virginia, Indiana, Massachusetts, New York, West Virginia, Iowa, Michigan, Ohio, Wisconsin.

00V189

This recall campaign will include vehicles in: Connecticut, Delaware, District of Columbia, Illinois, Indiana, Iowa, Maine, Maryland, Massachusetts, Michigan, Minnesota, Missouri, New Hampshire, New Jersey, New York, Ohio, Pennsylvania, Rhode Island, Vermont, West Virginia, Wisconsin.

00V256

PASSENGER VEHICLES ORIGINALLY SOLD OR CURRENTLY REGISTERED IN THE STATES OF ALASKA COLORADO IDAHO ILLINOIS IOWA KANSAS MAINE MICHIGAN MINNESOTA MONTANA NEBRASKA NEVADA NEW HAMPSHIRE NEW YORK NORTH DAKOTA SOUTH DAKOTA VERMONT WISCONSIN AND WYOMING.