

Quality Assurance - Early Warning Report



TQCN DOC#: EVRG101821C	RTS#: 13412-1	RTS Disposition: Forward	TMS QA Dept: QA-Powertrain	Assigned PE: STEGERT	Distribution Date: 1/24/02
Report Source: FPE	Primary Model: ES 300	Model Year: 2002	Production Date: 10-2001	Miles: 1105	VIN: (CONFIRM 17 DIGITS) JTHBF30G420 [REDACTED]
Condition Title: SURGE ON ACCELERATION - A/F SENSOR FAILURE				Author: MATT HENNESSEY	Dealer Code: 64204

Do not type in shaded fields - input from TQCN attributes:

Problem Area: <input checked="" type="checkbox"/> Base Vehicle <input type="checkbox"/> PPO/DIO	Problem Type: <input type="checkbox"/> Manufacturing <input type="checkbox"/> Design <input type="checkbox"/> Durability <input checked="" type="checkbox"/> New Model		
Optional Approval:	Ref#: 18391	Repair Date: 1/18/02	Dealer Name: Sewell Lexus

Condition Description:

Customer states the vehicle surges when accelerating from a stop.

No Diagnostic Trouble Codes are present.

A Snapshot was taken with the Scan Tool and it attached to this document.



Probable Cause:

The Short Fuel Trim #1 is very erratic.


When the throttle is opened short fuel trim goes to 19.5%. When the throttle is closed it is -14% A/F sensor failure

Failed Part # 1: 8946733060	Failed Part # 2:	Failed Part # 3:	Part shipped to: / Date: Tom Steger 1/18/02	Attachment: Part/picture/snapshot
-----------------------------	------------------	------------------	---	-----------------------------------


Remedy:

Replacing the Bank 1 A/F sensor repaired the vehicle.

Production Date of A/F sensor 09C29




Failed Part



Short FT#1


Quality Assurance – Early Warning Report



TQCN DOC#: EVRG101821C	RTS#: 13412-1	RTS Disposition: Forward	TMS QA Dept: QA-Powertrain	Assigned PE: STEGERT	Distribution Date: 1/24/02
Report Source: FPE	Primary Model: ES 300	Model Year: 2002	Production Date: 10-2001	Miles: 1105	VIN: (CONFIRM 17 DIGITS) JTHBF30G420 [REDACTED]
Condition Title: SURGE ON ACCELERATION - A/F SENSOR FAILURE				Author: MATT HENNESSEY	Dealer Code: 64204

Parts Recovery Control Sheet

Powertrain - 2199 Chassis - 2399 Electrical - 2599 Body/Paint - 2799 Accessory - 3500						
Ship to TMS Line Code: 2115			Shipping Tracking #:			
1	Date Shipped 1/25/02	Part Number 89467-33060	Part Name A/f sensor		Qty. 1	Comments: Shipped to Tom Steger
	VIN #	Prod. Date	Repair Date	Mileage	Unit Cost (1/4)	
2	Date Shipped	Part Number	Part Name		Qty.	Comments:
	VIN #	Prod. Date	Repair Date	Mileage	Unit Cost (1/4)	
3	Date Shipped	Part Number	Part Name		Qty.	Comments:
	VIN #	Prod. Date	Repair Date	Mileage	Unit Cost (1/4)	
4	Date Shipped	Part Number	Part Name		Qty.	Comments:
	VIN #	Prod. Date	Repair Date	Mileage	Unit Cost (1/4)	
5	Date Shipped	Part Number	Part Name		Qty.	Comments:
	VIN #	Prod. Date	Repair Date	Mileage	Unit Cost (1/4)	
6	Date Shipped	Part Number	Part Name		Qty.	Comments:
	VIN #	Prod. Date	Repair Date	Mileage	Unit Cost (1/4)	
7	Date Shipped	Part Number	Part Name		Qty.	Comments:
	VIN #	Prod. Date	Repair Date	Mileage	Unit Cost (1/4)	
8	Date Shipped	Part Number	Part Name		Qty.	Comments:
	VIN #	Prod. Date	Repair Date	Mileage	Unit Cost (1/4)	
Destination:		Circle One TMC TMMNA Other:				
For PRC Use:	Date Received	Date Shipped	Not Found	Located	Notes	



TQCN DOC#: EVOK107921A		RTS#: 14867-1	RTS Disposition: Forward	TMS QA Dept: QA-Powertrain	Assigned PE: JARBOEM		Distribution Date: 3/21/02
Location: TMS	Source: FPE	Primary Model: Camry	Model Year: 2002	Production Date:	Miles: 2610	VIN: (CONFIRM 17 DIGITS) 4T1BF30K82U [REDACTED]	
Condition Title: Electronic Control ECM Surge					Author: KEVIN PILOTTE		Dealer Code:

Do not type in shaded fields - Input from TQCN attributes:

Problem Area: <input checked="" type="checkbox"/> Base Vehicle <input type="checkbox"/> PPO/DIO			Problem Type: <input checked="" type="checkbox"/> Manufacturing <input type="checkbox"/> Design <input type="checkbox"/> Durability <input type="checkbox"/> New Model			
Optional Approval:	Ref#:	Repair Date: 3/12/02	Dealer Name: Modern Toyota			

Condition Description:

Customer complains of severe engine surge on light to moderate acceleration at operating temperature. Writer was able to duplicate condition by holding engine speed in Park at 3500 RPM for 3 minutes. Engine performed as if it was going into fuel cut. No MIL. Very noticeable up to 60 mph.

Probable Cause:

Short Term Fuel Trim, AF B1 S1, ranged from -16% to +16%; rapidly fluctuating. A/F sensor defective.

Failed Part # 1: 8946733060	Failed Part # 2:	Failed Part # 3:	Part shipped to: / Date: See below	Attachment:
-----------------------------	------------------	------------------	------------------------------------	-------------

Remedy:

Technician replaced A/F sensor B1 S1 to correct condition.



Picture of defective A/F sensor

Delete This Comment & Place Picture #2 here	Delete This Comment & Place Caption #2 here
---	---



A/F Sensor

TOYOTA FIELD TECHNICAL REPORT

CBU

DISTRIBUTOR'S NAME TMS/USA	COUNTRY USA/LA	RTS NO. 14915-1	APPROVAL DATE 3/27/02	REFERENCE	REPORT NO. FPCK108521	Page 1	ATTACHMENTS
VIN/FRAME NO. JTDBF32K420	ENGINE NO.	KM MILES	PRODUCTION DATE	PURCHASE DATE	REPAIR DATE		

MODEL: Camry

SUBJECT: 2002MY Camry (1MZ-FE) Engine "Surging" at Cruise

EARLY WARNING REPORT

INTRODUCTION:

The purpose of this communication is to report and summarize TMS concern with 2002MY Camry (1MZ-FE) Engine Surging at Cruise. TMS has identified an emerging issue with the 2002MY Camry and a "surging" condition that appears most often at steady cruising speeds. Initially this "surging" condition was thought to be directly related to the previously reported issue of A/F Ratio Sensor Failure for 2002MY ES 300 and Camry (1MZ-FE). The FTR document providing technical details for A/F Ratio Sensor Failure and the resulting "surging" condition is FTR #FPZG104521 dated 2/24/02. Vehicles are now being identified that exhibit this "surging" condition with no MIL "ON" and no obvious abnormal operation of the A/F Ratio Sensors.

CONDITION:

Customers and dealership technicians describe a "surging" or "slight misfire" sensation that can be felt mostly when cruising at a steady rate of speed but can also occur under acceleration. The most common scenario is detailed below:

Cruising Condition:

- Engine is at normal operating temperature
- No MIL "ON" or DTC present
- Steady vehicle cruising speed (between 40 – 45mi/h / 64 – 72km/h) on smooth road surface
- Transmission can be in either 3rd or 4th gear
- TCC (Torque Converter Clutch) can be either locked or unlocked
- Disabling the EGR System does not affect the condition

02MY V6 カムリのサージ苦情について、ご報告いたします。引き続き、市場から詳細状況を収集してまいります。添付データを調査・解析いただきますようお願いいたします。 藤原

Acceleration Condition:

- Engine is at normal operating temperature
- No MIL "ON" or DTC present
- Vehicle is under light to moderate acceleration (21 – 30% Throttle Angle) on smooth road surface
- Can be reproduced starting from a stop or moderate acceleration from steady cruising speed

The following TechView snapshots have been captured for each condition described above and are attached with the vehicle information.

Writer <i>Michael Jarboe</i>	SUPERVISOR/DEPT. MANAGER <i>Gary Heine</i>	JAPAN STAFF NAOMITSU KAWAKAMI
-------------------------------------	---	---

DISTRIBUTOR'S NAME TMS/USA	COUNTRY USA/LA	RTS NO. 14915-1	APPROVAL DATE	REFERENCE	REPORT NO. FPCK108521	Page 2
-------------------------------	-------------------	--------------------	---------------	-----------	--------------------------	-----------

TECHVIEW DATA:

VIN	P/D	Miles	Condition
JTDBF32K420	11/01	1,558	Described as "surging" or "erratic hesitation" by customer



'02 Camry Surge.zip'

The attached TechView file above contains 3 separate snapshots:

Snapshot #1 (02 Camry Surge – 02/22/02 01:08) is surge during acceleration from 40 – 60mi/h

Snapshot #2 (02 Camry Surge – 02/22/02 01:10) is surge during steady cruise @ 40 – 42mi/h

Snapshot #3 (02 Camry Surge – 02/22/02 01:12) is also surge during steady cruise @ 39 – 40mi/h

*None of the captured snapshots indicate any malfunction or abnormal operation of the A/F Ratio Sensors. Both sensors had been replaced in an attempt to correct the "surging" condition but had no effect.

In Snapshot #1, during acceleration the FUEL SYS #1 and FUEL SYS #2 are in "OLDRIVE" status instead of "CL" or closed loop status until 2.8 seconds into the Snapshot. This is the only abnormality apparent in the Data List during the "surging" condition. Please see screen capture below:

TechView [02 Camry Surge.evn]

Select

02 Camry Surge.evn

- Real-Time Data List
- Tester Snapshot Data
 - 02 Camry Surge - 02/22/02 01:10
 - 02 Camry Surge - 02/22/02 01:12
- DTC Information
- OBD System Monitors
- Freeze Frame Data
- File Information

INJECTOR	6.2	ms	EGRT GAS	240.8	°F	CYL
IGN ADVANCE	26.0	deg	EGR VALVE POS	2.92	V	CYL
CALC LOAD	29	%	VAPOR PRESS	757	mmHg-a	CYL
MAF	23	gm/s	SHORT FT #1	-0.1	%	CYL
ENGINE SPD	1832	rpm	LONG FT #1	-4.8	%	FC
COOLANT TEMP	186.8	°F	TOTAL FT #1	0.94		
INTAKE AIR	78.8	°F	SHORT FT #2	0.7	%	
THROTTLE POS	22	%	LONG FT #2	-4.8	%	
CTP SW	OFF		TOTAL FT #2	0.96		
VEHICLE SPD	41	MPH	AF FT B1 S1	1.00		
ACCEL POS #1	1.34	V	AF FT B2 S1	1.00		
ACCEL POS #2	2.12	V	FUEL SYS #1	OLDRIVE		
THROTTLE POS #2	3.02	V	FUEL SYS #2	OLDRIVE		
THROTTLE TARGET	1.14	V	FC IDL	OFF		
THROTL OPN DUTY	9	%	FC SIG	ON		
THROTL CLS DUTY	0	%	ELECT LOAD SIG	ON		
THROTTLE MOT	ON		EGR SYSTEM	ON		
+BM	ON		INTAKE CTL VSV1	OFF		
ACCEL IDL POS	OFF		FUEL PUMP / SPD	ON/H		
THROTL IDL POS	OFF		EVAP VSV	ON		
FAIL #1	OFF		SHIFT	4th		
FAIL #2	OFF		SPD(INC)	1650	rpm	
THROTL INITIAL	0.62	V	LOCK UP SOL	ON		
ACCEL LEARN VAL	0.82	V	OVERDRV CUT Sw2	OFF		
THROTTLE MOT	0.6	A	DRIVE	ON		
O2S B1 S2	0.70	V	SOLENOID(SLT)	ON		
O2S B2 S2	0.66	V	AT FLUID TEMP	183.2	°F	
AFS B1 S1	3.29	V	CYL #1	0	%	
AFS B2 S1	3.30	V	CYL #2	0	%	

DISTRIBUTOR'S NAME	COUNTRY	RTS NO.	APPROVAL DATE	REFERENCE	REPORT NO.	Page
TMS/USA	USA/LA	14915-1			FPCK108521	3

REMEDY:

There is no corrective action available at this time.

MARKET SUMMARY:

Due to the early detection and identification of this issue, Warranty Data is not yet available related to this condition. TMS has received 1 Early Warning Report with an additional 5 cases of 2002MY Camry (1MZ-FE) with the "surging" issue outlined above. TMS QAP Product Engineer has discussed and reviewed this condition with the TMC Mr. MIL (Mr. Miura) representative. Mr. MIL has been able to duplicate the "surging" condition on a TMS Internal Fleet Vehicle and is currently reviewing possible causes.

REQUESTS:

TMS requests TMC to investigate this issue to determine the root cause for the "surging" condition. Determine if the A/F Ratio Sensor(s) play any role in the occurrence of this condition. Provide T.I. and Draft TSB.

Distribution List (email notification):

View Access:

Reviewers:

INTRODUCTION:

CONDITION:

CAUSE:

REMEDY:

MARKET SUMMARY:

REQUESTS:

MARKET INFORMATION:

DISTRIBUTOR'S NAME TMS/USA	COUNTRY USA/LA	RTS NO. 14915-1	APPROVAL DATE	REFERENCE	REPORT NO. FPCK108821	Page 2
-------------------------------	-------------------	--------------------	---------------	-----------	--------------------------	-----------

TECHVIEW DATA:

VIN	P/D	Miles	Condition
JTDBF32K420	11/01	1,558	Described as "surging" or "erratic hesitation" by customer



*02 Camry Surge.zip

The attached TechView file above contains 3 separate snapshots:

Snapshot #1 (02 Camry Surge -- 02/22/02 01:08) is surge during acceleration from 40 -- 60mi/h

Snapshot #2 (02 Camry Surge -- 02/22/02 01:10) is surge during steady cruise @ 40 -- 42mi/h

Snapshot #3 (02 Camry Surge -- 02/22/02 01:12) is also surge during steady cruise @ 39 -- 40mi/h

*None of the captured snapshots indicate any malfunction or abnormal operation of the A/F Ratio Sensors. Both sensors had been replaced in an attempt to correct the "surging" condition but had no effect.

In Snapshot #1, during acceleration the FUEL SYS #1 and FUEL SYS #2 are in "OLDRIVE" status instead of "CL" or closed loop status until 2.8 seconds into the Snapshot. This is the only abnormality apparent in the Data List during the "surging" condition. Please see screen capture below.

The screenshot shows the TechView interface with a data list for a 02 Camry Surge. The data list is organized into two columns of parameters. The following table represents the data shown in the screenshot:

Parameter	Value	Units	Parameter	Value	Units	Flag
INJECTOR	6.2	ml	EGRT GAS	240.8	°F	CYL
IGN ADVANCE	28.8	deg	EGR VALVE POS	2.92	V	CYL
CALC LOAD	29	%	VAPOR PRESS	757	mmHg-a	CYL
MAF	23	gm/s	SHORT FT #1	-0.1	%	CYL
ENGINE SPD	1932	rpm	LONG FT #1	-4.8	%	FC
COOLANT TEMP	186.8	°F	TOTAL FT #1	0.94		
INTAKE AIR	79.8	°F	SHORT FT #2	0.7	%	
THROTTLE POS	22	%	LONG FT #2	-4.8	%	
CTP SW	OFF		TOTAL FT #2	0.26		
VEHICLE SPD	41	MPH	AEPT #1 S1	1.00		
ACCEL POS #1	1.34	V	AE FT #2 S1	1.00		
ACCEL POS #2	2.12	V	FUEL SYS #1	OLDRIVE		
THROTTLE POS #2	3.02	V	FUEL SYS #2	OLDRIVE		
THROTTLE TARGET	1.14	V	FC IDL	OFF		
THROTL OPN DUTY	9	%	INC SIG	ON		
THROTL CLS DUTY	0	%	ELECT LOAD SIG	ON		
THROTTLE MOT	ON		EGR SYSTEM	ON		
+BM	ON		INTAKE CTL VSV1	OFF		
ACCEL IDL POS	OFF		FUEL PUMP / SPD	ON/AH		
THROTTL IDL POS	OFF		EVAP VSV	ON		
FAIL #1	OFF		SHIFT	4h		
FAIL #2	OFF		SPD(AC)	1650	rpm	
THROTTL INITIAL	0.62	V	LOCK UP SOL	ON		
ACCEL LEARN VAL	0.62	V	OVERDRV CUT SW2	OFF		
THROTTLE MOT	0.6	A	DRIVE	ON		
O2S B1 S2	0.70	V	SOLENOID(SLT)	ON		
O2S B2 S2	0.66	V	AT FLUID TEMP	183.2	°F	
AFS B1 S1	3.29	V	CYL #1	0	%	
AFS B2 S1	3.30	V	CYL #2	0	%	

TOYOTA FIELD TECHNICAL REPORT

CBU

DISTRIBUTOR'S NAME TMS/USA	COUNTRY USA/LA	RTS NO. 14867-1	APPROVAL DATE 5/20/02	REFERENCE	REPORT NO. FPCK113521	Page 1	ATTACHMENTS
VIN/FRAME NO. N/A	ENGINE NO.	KM MILES	PRODUCTION DATE	PURCHASE DATE	REPAIR DATE		

MODEL: Camry, ES 300

SUBJECT: 2002MY Camry (1MZ-FE) Engine Surging Issue

INTRODUCTION:

The purpose of this report is to inform TMC of:

テキサス州でのお客様苦情車現認結果を、ご報告いたします。
お客様は、「サージ」「シャッター」等の表現を使用されておりますが、本件市場での発生状況を把握していく予定です。

- The results of the TTC / TMS "Go and See" Investigation activity held at GST during the week of 5/6/02
- The current market status / impact of the 1MZ-FE Engine Surging Issue

TMS COMMENTS:

苦情車からのデータを基に、対策検討をお願いいたします。 藤原

As previously communicated via UTA (UTA #UPCK110721 dated 4/24/02) during the week of 5/6/02 TMS and TTC-LA conducted a "Go and See" activity at dealers in the Houston and Longview, TX areas for the 2002MY Camry 1MZ-FE Engine Surging issue. The purpose of the activity was to:

1. Confirm the actual "surge" level using customer complaint vehicles under local area driving and road conditions
2. Determine the potential cause of the "surge" and confirm responsibility for TMC

The two dealers involved with the "Go and See" activity were Fred Haas Toyota in Houston, TX and Toyota of Longview in Longview, TX. Each dealer prepared two confirmed customer complaint vehicles and new dealer in-stock vehicles to utilize during the investigation. The dealer information, vehicles information and the results found at each dealer are outlined below in Chart 1 and 2.

Chart 1: Fred Haas Toyota - Houston, TX (5/7/02)

No.	VIN	P/D	Miles	Grade	Customer Vehicle?
1	4T1BF32K92U	8/01	8,642	XLE	YES - Complaint Vehicle
2	4T1BF32K72U	8/01	11,212	LE	YES - Complaint Vehicle
3	4T1BF32K12U	10/01	7	LE	NO - New Dealer In-Stock

Chart 2: Toyota of Longview - Longview, TX (5/8/02)

No.	VIN	P/D	Miles	Grade	Customer Vehicle?
4	4T1BF32K42U	8/01	12,398	LE	YES - Complaint Vehicle
5	JTDBF32K420	11/01	3,652	XLE	YES - Complaint Vehicle
6	4T1BF32K62U	12/01	117	LE	NO - New Dealer In-Stock



Writer Michael Jarboe	SUPERVISOR/DEPT. MANAGER Gary Heine	JAPAN STAFF NAOMITSU KAWAKAMI
-------------------------------------	---	---

PLEASE DO NOT PLACE TEXT BELOW THIS LINE
FTR-CBU TEMPLATE (ver. 3/99)


DISTRIBUTOR'S NAME TMS/USA	COUNTRY USA/LA	RTS NO. 14867-1	APPROVAL DATE	REFERENCE	REPORT NO. FPCK113521	Page 2
-------------------------------	-------------------	--------------------	---------------	-----------	--------------------------	-----------

TESTING CRITERIA:

All vehicles tested were driven by TMS / TTC engineers and the GST Regional FTS and FPE to provide the best objective evaluation of the "surging" condition. All vehicles were tested and evaluated on flat to slight uphill road profiles (2 ~ 3% grade) with smooth surfaces. Illustrations of the actual test roads are provided below:




All vehicles tested, both customer complaint **and** new dealer in-stock units, exhibited the "surging" condition between 38 ~ 42 mi/h, transmission in 4th gear, L/U "ON" (Lock-Up). Throttle input was 13 ~ 15% with the vehicle maintaining a steady cruise. It was agreed by both TTC and TMS engineers that the "surging" condition experienced on the customer and dealer vehicles was equal to the TMS Internal Fleet Vehicle previously evaluated by TTC, TMS and TMC. Using Vehicle No. 2 described in Chart 1, TTC and TMS engineers installed a Panel A-2 diagnostic tool including the installation of a "G" sensor on the front passenger seat mounting rail. This allowed for the precise measurement of the longitudinal forces that were experienced during the "surging" condition. Measurements were taken during the "surging" condition with L/U coming on at 38 mi/h. The measured frequency was 8hz with the "G" sensor reading a 0.1G force **during** the "surging" condition. The Panel A-2 screen is shown below with the RED line indicating the "G" sensor signal and the GREEN line indicating L/U operation. (L/U "ON" is at this point)



DISTRIBUTOR'S NAME TMS/USA	COUNTRY USA/LA	RTS NO. 14867-1	APPROVAL DATE	REFERENCE	REPORT NO. FPCK113521	Page 3
-------------------------------	-------------------	--------------------	---------------	-----------	--------------------------	-----------

The second test involved changing the shift schedule to move the point at which L/U (Lock-Up) would occur. The L/U point was changed from 38 mi/h to 44 mi/h to evaluate what effect it would have on the "surging" condition. Vehicle No. 2 was then driven and measurements taken. The Panel A-2 diagnostic tool showed that the "G" sensor detected the same 8hz amplitude but the G force had been significantly reduced from 0.1G to 0.04G during the "surging" condition. The Panel A-2 screen is shown below with the RED line indicating the "G" sensor signal and the GREEN line for L/U. (L/U "ON" is at this point)



NOTE: Both TMS / TTC engineers and the GST Regional FTS and FPE agreed that the "surging" condition was eliminated after the change to the shift schedule L/U point.

Several testing conditions were utilized to evaluate what changes that EGR operation, EVAP Purge and the A/F feedback would have on the "surging" condition. No differences were noticed in the "surging" condition with these systems disabled. A summary outlining the specific details of the testing conditions is attached below:



"Go and see
summary.doc"

CAUSE:

The root cause of the "surging" condition remains unknown. However, as previously mentioned, changes made to the shift schedule for L/U (Lock-Up) during the testing / evaluation made the "surging" condition disappear.

REMEDY:

No known remedy exists for the "surging" condition at this time.

DISTRIBUTOR'S NAME	COUNTRY	RTS NO.	APPROVAL DATE	REFERENCE	REPORT NO.	Page
TMS/USA	USA/LA	14867-1			FPCK113521	4

MARKET SUMMARY:

TMS has researched the impact the 1MZ-FE "surging" condition is having in the U.S. market. Due to the specific nature of the "surging" condition and that it is only a **feeling** experienced by the customer, it is difficult to determine the true scope and impact that this issue is currently having. Customers have described the condition many different ways (e.g. surging, shudder, hesitation), therefore it is very difficult to categorize and separate this issue from other potential vehicle concerns.

To better quantify the "surging" issue, an analysis of confirmed field reports and CR Data was performed. As of the date of this report, the number of confirmed "surging" occurrences is summarized below:

- 16 Confirmed Field Reports (includes EWR's, TAS Contacts)
- Reported as a Regional Top Technical Concern for CATD and GST Regions
- The SET, CATD, GST, Los Angeles and Denver Regional Offices have reported customers experiencing the "surging" condition

Associates from TMS and TMMNA are currently involved with a Camry Market Survey activity in the SET Region. During this Market Survey activity, Del Mar Toyota in Florida brought the "surging" issue to the attention of the Market Survey participants. The dealer stated that they have had multiple customer complaints on 2002MY Camry 1MZ-FE for "surging". Additionally, Mr. Andy Kondo, Japan Staff Coordinator for the SET Region and Mr. Hiroshi Yamashita, Coordinator for TMMNA -QD have experienced this "surging" condition using Mr. Kondo's 2002MY Camry Regional Fleet vehicle.

TMS believes that many actual "surging" complaints are hidden due to the customer description of the actual condition. TMS has analyzed TCS and LPS survey returns comparing customer complaints for 2001MY vehicles and 2002MY vehicles. The file attached below provides a detailed summary showing the number of problems per 100 for Camry 1MZ-FE for both "Engine" and "Transmission" have increased significantly.



"TCS vs IQS.xls"

LEXUS (ES 300) MARKET IMPACT:

TMS has also examined the ES 300 for a possible link between the reported Camry 1MZ-FE Engine Surge issue and several reports of a similar condition for the 2002MY ES 300. Using the Lexus R.O. (Repair Order) Database, TMS has reviewed dealership service repair order information and found a significant number of customer complaints that are similar to the current "surging" condition on the 2002MY Camry. Customers and dealers describe a "surge", "studder" or "light shudder" during highway driving at speeds ranging from 40 ~ 55 mi/h. TMS feels that there may be some link between these customer complaints and the identified issue on the Camry. TMS created a Customer Survey for transmission issues related to the 2002MY ES 300. Through this survey, TMS identified customer complaints which describe a "surge", "shock" or "jerking" sensation between 40 ~ 60 mi/h. TMS believes that these customer complaints may be linked to the "surging" issue on the Camry. A summary of the Customer Survey including the customer verbatim comments is contained in the file below.





"02-05-14 ES300 AT Customer Survey.xls"

NOTE: As was confirmed during the TMS / TTC "Go and See" activity, new vehicles from the dealer stock also exhibited the "surging" condition. During diagnosis for issues such as this, it is normal practice for dealer technicians and Regional staff to compare customer complaint vehicles to new vehicles in an effort to determine if a specific condition is "normal" during the vehicle operation. Since both the customer complaint vehicle and the new vehicle act in a similar manner under the same driving conditions, in many cases the customer may be told that the "surging" condition is normal. TMS feels strongly that the actual number of customer complaints is much higher than what is visible via Field Reports and TAS (Technical Assistance Hotline). Since even new vehicles exhibit the "surging" condition, every new Camry has the potential for customer complaints.


DISTRIBUTOR'S NAME TMS/USA	COUNTRY USALA	RTS NO. 14887-1	APPROVAL DATE	REFERENCE	REPORT NO. FPCK113521	Page 2
-------------------------------	------------------	--------------------	---------------	-----------	--------------------------	-----------

TESTING CRITERIA:

All vehicles tested were driven by TMS / TTC engineers and the GST Regional FTS and FPE to provide the best objective evaluation of the "surging" condition. All vehicles were tested and evaluated on flat to slight uphill road profiles (2 ~ 3% grade) with smooth surfaces. Illustrations of the actual test roads are provided below:




All vehicles tested, both customer complaint and new dealer in-stock units, exhibited the "surging" condition between 38 ~ 42 mi/h, transmission in 4th gear, L/U "ON" (Lock-Up). Throttle input was 13 ~ 15% with the vehicle maintaining a steady cruise. It was agreed by both TTC and TMS engineers that the "surging" condition experienced on the customer and dealer vehicles was equal to the TMS Internal Fleet Vehicle previously evaluated by TTC, TMS and TMC. Using Vehicle No. 2 described in Chart 1, TTC and TMS engineers installed a Panel A-2 diagnostic tool including the installation of a "G" sensor on the front passenger seat mounting rail. This allowed for the precise measurement of the longitudinal forces that were experienced during the "surging" condition. Measurements were taken during the "surging" condition with L/U coming on at 38 mi/h. The measured frequency was 8hz with the "G" sensor reading a 0.1G force during the "surging" condition. The Panel A-2 screen is shown below with the RED line indicating the "G" sensor signal and the GREEN line indicating L/U operation. (L/U "ON" is at this point)



DISTRIBUTOR'S NAME TMS/USA	COUNTRY US/USA	RTS NO. 14887-1	APPROVAL DATE	REFERENCE	REPORT NO. FPCK113521	Page 3
-------------------------------	-------------------	--------------------	---------------	-----------	--------------------------	-----------

The second test involved changing the shift schedule to move the point at which L/U (Lock-Up) would occur. The L/U point was changed from 38 mi/h to 44 mi/h to evaluate what effect it would have on the "surging" condition. Vehicle No. 2 was then driven and measurements taken. The Panel A-2 diagnostic tool showed that the "G" sensor detected the same 8hz amplitude but the G force had been significantly reduced from 0.1G to 0.04G during the "surging" condition. The Panel A-2 screen is shown below with the RED line indicating the "G" sensor signal and the GREEN line for L/U. (L/U "ON" is at this point)



NOTE: Both TMS / TTC engineers and the GST Regional FTS and FPE agreed that the "surging" condition was eliminated after the change to the shift schedule L/U point.

Several testing conditions were utilized to evaluate what changes that EGR operation, EVAP Purge and the A/F feedback would have on the "surging" condition. No differences were noticed in the "surging" condition with these systems disabled. A summary outlining the specific details of the testing conditions is attached below:



"Go and see
summary.doc"

CAUSE:

The root cause of the "surging" condition remains unknown. However, as previously mentioned, changes made to the shift schedule for L/U (Lock-Up) during the testing / evaluation made the "surging" condition disappear.

REMEDY:

No known remedy exists for the "surging" condition at this time.

Quality Assurance – Early Warning Report



TQCN DOC#: EJYK115121		RTS#: 14867-1	RTS Disposition: Forward	TMS QA Dept: QA-Powertrain	Assigned PE: JARBOEM		Distribution Date: 6/4/02
Location: TMS-DEN	Source: FTS	Primary Model: Camry	Model Year: 2002	Production Date: 11-2001	Mileage: 3948	VIN: (CONFIRM 17 DIGITS) 4T1BF32K12U [REDACTED]	
Condition Title: Engine Surge at Cruise					Author: JOE LANE		Dealer Code: 43007

Do not type in shaded fields - input from TQCN attributes:

Problem Area: <input checked="" type="checkbox"/> Base Vehicle <input type="checkbox"/> PPO/DIO		Problem Type: <input type="checkbox"/> Manufacturing <input type="checkbox"/> Design <input type="checkbox"/> Durability <input checked="" type="checkbox"/> New Model					
Dealer Name: 43007		Repair Date: 04/23/02	Ref#:	Optional Approval:			
Menlove Toyota							

Condition Description:

Customer States that the vehicle surges/vibrates under light throttle between 35-50 mph on a smooth flat road surface.

Probable Cause:

The condition occurs when the transmission shifts into Lock up. When Lock up disengages the condition stops. I used Active test on the Scan tool to control Lock up operation and found that when Lock up was engaged the vehicle surged/ vibrated and when I disengaged Lock up the surge/vibration stopped. I raised the vehicles front wheels off the ground and ran the vehicle up to 40mph and engaged the Lock up with the Scan tool. I found that the transmission and engine assemblies shook severely when Lock up was engaged. I also noticed that there is no engine mount to help support the engine and transmission assembly on the rear of the subframe. This seems to allow the engine and transmission assemblies to vibrate back and forth excessively during Lock up operation under light throttle, thus causing the surge/vibration condition.

Failed Part # 1: 000000000000	Failed Part # 2:	Failed Part # 3:	Disposition of Failed Parts:
----------------------------------	------------------	------------------	------------------------------

Remedy:

No action taken. Test drove two other like vehicles and they had the same condition. Possible engine and transmission support issue or ECM logic issue?



"02 Camry surge #1.evn"

Place Picture Caption Here

Quality Assurance - Early Warning Report



TQCN DOC#: EJK115421		RTS#: 14867-1	RTS Disposition: Forward	TMS QA Dept: QA-Powertrain	Assigned PE: JARBOEM	Distribution Date: 6/4/02
Location: TMS-DEN	Source: FTS	Primary Model: Camry	Model Year: 2002	Production Date: 10-2001	Mileage: 1881	VIN: (CONFIRM 17 DIGITS) 4T1BF32K02U [REDACTED]
Condition Title: Engine Surge at Cruise				Author: JOE LANE	Dealer Code: 43020	

Do not type in shaded fields - Input from TQCN attributes:

Problem Area: <input checked="" type="checkbox"/> Base Vehicle <input type="checkbox"/> PPO/DIO	Problem Type: <input type="checkbox"/> Manufacturing <input type="checkbox"/> Design <input type="checkbox"/> Durability <input checked="" type="checkbox"/> New Model		
Dealer Name: Mark Miller Toyota-43020	Repair Date: 4/30/02	Ref#:	Optional Approval:

Condition Description:

Customer states that the vehicle surges at 40 mph under light throttle.


Probable Cause:

I used Active test on the Scan tool to control Lock up operation and found that when Lock up was engaged the vehicle surged/vibrated and when I disengaged Lock up the surge/vibration stopped. It seems that the Torque converter becomes out of balance and shakes the engine and transmission assemblies excessively under light throttle. I also noticed that there is no engine mount to help support the engine and transmission assembly on the rear of the subframe. This seems to allow the engine and transmission assemblies to vibrate back and forth excessively during Lock up operation under light throttle. Possible engine and transaxle support issue or ECM logic issue?

Failed Part # 1: 0000000000	Failed Part # 2:	Failed Part # 3:	Disposition of Failed Parts:
-----------------------------	------------------	------------------	------------------------------

Remedy:

No action taken. Compared with another like vehicle and it had the same condition.

 "02 Camry surge #2.evn" Place Pic ture Here	Place Picture Caption Here
Place Picture #2 here	Place Caption #2 here

DISTRIBUTOR'S NAME	COUNTRY	RTS#	APPROVAL DATE	REFERENCE	TQCN REPORT#	Page 1 of 6
TMS/USA	USA/LA	13412-3	6/28/02		FPRG117621	
VIN	ENGINE#	MILES	PRODUCTION DATE	PURCHASE DATE	REPAIR DATE	
JTHBF30G*2*						

MODEL: ES 300, Camry
 SUBJECT: A/F SENSOR AFTER C/M MIL ON/SURGE

INTRODUCTION:

The purpose of this report is to provide five A/F sensors built after the latest counter measure for examination by TMC. TMS has identified 3 2002 ES300 with MIL "ON" or drivability concerns related to A/F sensor failure after latest countermeasure VIN breaks listed in TI-TK1AKA1058218 dated 2/27/02.

対策センサでの再発が懸念されます。
 回収品を調査いただき、原因究明・対策をお願いいたします。 藤原

CONDITION:

- Two Possible complaints of A/F sensor failure
 - o MIL light "ON" with DTC P1155
 - o Customer complaint of surge during steady cruise 30 – 40 mph (48-64 km/hr)
 - Technician noticing erratic voltage changes and sweeping Fuel Trim values

VEHICLE INFORMATION:

- Information on 5 A/F sensors recovered from 3 vehicles is in the chart below

#	VIN	CCR DESCRIPTION	PART NUMBER	DATE CODE	MILEAGE
1	JTHBF30G420	P1155	89467-33060	04D10	192
		P1155	89467-33050	04D05	192
2	JTHBF30G020	SHUDDER / SURGE	89467-33060	02D28	494
		SHUDDER / SURGE	89467-33050	02D28	494
3	JTHBF30G925	SHUDDER / SURGE	89467-33060	03D21	14

- These sensors will be shipped with the report
- Techview file from Vehicle #3 A/F sensor is attached below



TechView2.evn

REMEDY:

- Vehicles were repaired by replacing A/F sensor

WRITER	SUPERVISOR/DEPT. MANAGER	JAPAN STAFF
JOSEPH LETOILE	Gary Heine	NAOMITSU KAWAKAMI

DISTRIBUTOR'S NAME TMS/USA	COUNTRY USA/LA	RTS NO. 13412-3	APPROVAL DATE	TQCN# FPRG117621	Page 2 of 6
-------------------------------	-------------------	--------------------	---------------	---------------------	----------------

Comments:

- TMS was not able to duplicate condition when A/F sensor was installed in Test Vehicle.

REQUESTS:

- Please provide results of examination of A/F sensors via TI format
- Please provide VIN breaks for Toyota Motor Manufacturing Kentucky (TMMK) production vehicles for second countermeasure listed in TI-TK1AK1058218
- Please provide countermeasure information if any changes were made as a result of examination of A/F sensors included with this report

TQCN DOC#: E8NG107131		RTS#: 17992-1	RTS Disposition: Forward	TMS QA Dept: QA-Powertrain	Assigned PE: MALONEYB	Distribution Date: 3/13/03
Location: TMS-LEA	Source: FTS	Primary Model: ES 300	Model Year: 2002	Production Date: 04-2002	Mileage: 9931	VIN: (CONFIRM 17 CHARACTERS) JTHBF30G325 [REDACTED]
Condition Title: Vehicle Surges Under Acceleration - A/F Sensor				Author: Brant Baird	Dealer Code: 61902	

Do not type in shaded fields - Input data from Web page or RDM:

Problem Area: <input checked="" type="checkbox"/> Base Vehicle <input type="checkbox"/> PPO/DIO	Problem Type: <input type="checkbox"/> Manufacturing <input type="checkbox"/> Design <input type="checkbox"/> Durability <input checked="" type="checkbox"/> New Model		
Dealer Name: Len Stoler Lexus	Repair Date: 1/17/03	Ref#: 23450	Optional Approval:

Condition Description:

Customer complains that the vehicle surges when driving up hills or under steady acceleration.

Probable Cause:

When analyzing the Techview data, the B1S1 A/F sensor was reading very erratically as compared to the B2S1 sensor. There were no codes for the sensor although it was operating erratically.

Failed Part # 1: 8946733060	Failed Part # 2:	Failed Part # 3:	Disposition of Failed Parts: Have part / will ship	Parts Shipping Destination: 2113
-----------------------------	------------------	------------------	--	----------------------------------

Remedy:



Replacing the B1S1 A/F sensor corrected the surging condition. Techview file is attached.



Len Stoler ES300 surge1.evn

<div style="border: 1px solid black; padding: 5px;"> <p>1.59 V AFS B1 S1</p> <p>Select [icon]</p> </div> <div style="border: 1px solid black; padding: 5px;"> <p>3.24 V AFS B2 S1</p> <p>Select [icon]</p> </div> <div style="border: 1px solid black; padding: 5px;"> <p>0.11 V O2S B1 S2</p> <p>Select [icon]</p> </div> <div style="border: 1px solid black; padding: 5px;"> <p>0.17 V O2S B2 S2</p> <p>Select [icon]</p> </div>	<p>Techview data</p>
---	----------------------

TQCN DOC#: E8NG107131		RTS#: 17992-1	RTS Disposition: Forward	TMS QA Dept: QA-Powertrain	Assigned PE: MALONEYB		Distribution Date: 3/13/03
Location: TMS-LEA	Source: FTS	Primary Model: ES 300	Model Year: 2002	Production Date: 04-2002	Mileage: 9931	VIN: (CONFIRM 17 CHARACTERS) JTHBF30G325 [REDACTED]	
Condition Title: Vehicle Surges Under Acceleration - A/F Sensor					Author: Brant Baird		Dealer Code: 61902

	<p>A/F sensor PN info</p>
	<p>A/F sensor</p>

TQCN DOC#: E8NG107131		RTS#: 17992-1	RTS Disposition: Forward	TMS QA Dept: QA-Powertrain	Assigned PE: MALONEYB	Distribution Date: 3/13/03
Location: TMS-LEA	Source: FTS	Primary Model: ES 300	Model Year: 2002	Production Date: 04-2002	Mileage: 9931	VIN: (CONFIRM 17 CHARACTERS) JTHBF30G325 [REDACTED]
Condition Title: Vehicle Surges Under Acceleration - A/F Sensor					Author: Brant Baird	Dealer Code: 61902




Parts Recovery Control Sheet


Ship all parts to TMS – Parts Return Center. Do not type in SHADED fields
 If the *Final Destination* field below states "scrap", properly dispose of the part.

Final Destination: 2113

Note: If EWR contains 2 or more VIN's, create a table in the report containing VIN, production date, and mileage

	Failed Part #	Part Description	Qty.	Unit Cost
1	8946733060	SENSOR, AIR FUEL RATIO	1	\$ 52 .00
	Comments:			
2			1	\$ 0 .00
	Comments:			
3			1	\$ 0 .00
	Comments:			
4			1	\$.00
	Comments:			
5			1	\$.00
	Comments:			
6			1	\$.00
	Comments:			
7			1	\$.00
	Comments:			
8			1	\$.00
	Comments:			





TQCN DOC#: E8NG107131A		RTS#: 17992-1	RTS Disposition: Forward	TMS QA Dept: QA-Powertrain	Assigned PE: MALONEYB		Distribution Date: 3/13/03
Location: TMS-LEA	Source: FTS	Primary Model: ES 300	Model Year: 2002	Production Date: 11-2001	Mileage: 20706	VIN: (CONFIRM 17 CHARACTERS) JTHBF30G920	
Condition Title: Vehicle surges when driving up hills - A/F Sensor					Author: Brant Baird	Dealer Code: 61902	

Do not type in shaded fields - Input data from Web page or RDM:

Problem Area: <input checked="" type="checkbox"/> Base Vehicle <input type="checkbox"/> PPO/DIO		Problem Type: <input type="checkbox"/> Manufacturing <input type="checkbox"/> Design <input type="checkbox"/> Durability <input checked="" type="checkbox"/> New Model		
Dealer Name: Len Stoler Lexus	Repair Date: 1/17/03	Ref#: 23449	Optional Approval:	

Condition Description:

Customer complains that the vehicle surges when driving up hills under steady acceleration.

Probable Cause:


When analyzing the Techview data, the B1S1 A/F sensor was reading very erratically as compared to the B2S1 sensor. There were no codes for the sensor although it was operating erratically.

Failed Part # 1: 8946733060	Failed Part # 2:	Failed Part # 3:	Disposition of Failed Parts: Have part / will ship	Parts Shipping Destination: 2113
-----------------------------	------------------	------------------	--	----------------------------------



Remedy:

Replacing the B1S1 A/F sensor corrected the surging condition. Techview file is attached.


Len Stoler ES300 surge2.evn



TQCN DOC#: E8NG107131A		RTS#: 17992-1	RTS Disposition: Forward	TMS QA Dept: QA-Powertrain	Assigned PE: MALONEYB		Distribution Date: 3/13/03
Location: TMS-LEA	Source: FTS	Primary Model: ES 300	Model Year: 2002	Production Date: 11-2001	Mileage: 20706	VIN: (CONFIRM 17 CHARACTERS) JTHBF30G920 [REDACTED]	
Condition Title: Vehicle surges when driving up hills - A/F Sensor					Author: Brant Baird		Dealer Code: 61902

	<p>A/F sensor PN info</p> <p> TOYOTA 89467 -33060 DENSO 0040 11C05 </p>
	<p>A/F sensor</p>

TQCN DOC#: E8NG107131A		RTS#: 17992-1	RTS Disposition: Forward	TMS QA Dept: QA-Powertrain	Assigned PE: MALONEYB		Distribution Date: 3/13/03
Location: TMS-LEA	Source: FTS	Primary Model: ES 300	Model Year: 2002	Production Date: 11-2001	Mileage: 20706	VIN: (CONFIRM 17 CHARACTERS) JTHBF30G920 [REDACTED]	
Condition Title: Vehicle surges when driving up hills - A/F Sensor					Author: Brant Baird		Dealer Code: 61902





Parts Recovery Control Sheet


Ship all parts to TMS – Parts Return Center. Do not type in SHADED fields
If the *Final Destination* field below states "scrap", properly dispose of the part.

Final Destination: 2113

Note: If EWR contains 2 or more VIN's, create a table in the report containing VIN, production date, and mileage

	Failed Part #	Part Description	Qty.	Unit Cost
1	8946733060	SENSOR, AIR FUEL RATIO	1	\$ 51 .00
	Comments:			
2			1	\$ 0 .00
	Comments:			
3			1	\$ 0 .00
	Comments:			
4			1	\$.00
	Comments:			
5			1	\$.00
	Comments:			
6			1	\$.00
	Comments:			
7			1	\$.00
	Comments:			
8			1	\$.00
	Comments:			





TQCN DOC#: E7PK107331		RTS#: 18015-1	RTS Disposition: Forward	TMS QA Dept: QA-Powertrain	Assigned PE: STABAD		Distribution Date: 3/17/03
Location: TMS-LA	Source: FTS	Primary Model: Camry	Model Year: 2003	Production Date: 01-2003	Mileage: 454	VIN: (CONFIRM 17 CHARACTERS) JTDBE32K130 [REDACTED]	
Condition Title: PZEV Camry Fuel Tank Hose					Author: MIKE HOUGHTLING		Dealer Code: 04018

Do not type in shaded fields - Input data from Web page or RDM:

Problem Area: <input checked="" type="checkbox"/> Base Vehicle <input type="checkbox"/> PPO/DIO		Problem Type: <input checked="" type="checkbox"/> Manufacturing <input type="checkbox"/> Design <input type="checkbox"/> Durability <input type="checkbox"/> New Model	
Dealer Name: Claremont Toyota	Repair Date: 03/14/033	Ref#:	Optional Approval:

Condition Description:

- Engine surge at cruise.
- Engine stalling at idle after warm-up.
- Fuel Tank will not fill to full position on Fuel Gauge.

Probable Cause:


- Vapor Hose inside fuel tank is not connected to rear interior Fuel Tank Nipple. (Photo A)
- Liquid fuel is drawn into Vapor Hose flooding EVAP Canister and into Intake Manifold when Purge VSV is cycled ON by ECU. (Photo B)
- No trouble found with Vapor Hose Connector but fitting could not be re-installed to interior Fuel Tank Nipple due to hard to reach location. (Photo C)

Failed Part # 1: 7700106080	Failed Part # 2:	Failed Part # 3:	Disposition of Failed Parts: Special request only	Parts Shipping Destination: N/A
-----------------------------	------------------	------------------	---	---------------------------------

Remedy:

- Fuel Tank Replaced. P/N (77001 – 06080)
- EVAP Canister replaced. P/N (77740 – 06141)
- Fresh Air Filter replaced. P/N (17700 – 0A080)
- Part Numbers are currently not loaded into parts system.

Photo A



Vapor Hose pulled from inside Fuel Tank

Photo B



Liquid Fuel at EVAP VSV

TQCN DOC#: E7PK107331		RTS#: 18015-1	RTS Disposition: Forward	TMS QA Dept: QA-Powertrain	Assigned PE: STABAD		Distribution Date: 3/17/03
Location: TMS-LA	Source: FTS	Primary Model: Camry	Model Year: 2003	Production Date: 01-2003	Mileage: 454	VIN: (CONFIRM 17 CHARACTERS) JTDBE32K130 [REDACTED]	
Condition Title: PZEV Camry Fuel Tank Hose					Author: MIKE HOUGHTLING		Dealer Code: 04018




Photo C
Vapor Hose Connector (No Trouble)

TQCN DOC#: E7PK107331		RTS#: 18015-1	RTS Disposition: Forward	TMS QA Dept: QA-Powertrain	Assigned PE: STABAD	Distribution Date: 3/17/03
Location: TMS-LA	Source: FTS	Primary Model: Camry	Model Year: 2003	Production Date: 01-2003	Mileage: 454	VIN: (CONFIRM 17 CHARACTERS) JTDBE32K130
Condition Title: PZEV Camry Fuel Tank Hose				Author: MIKE HOUGHTLING	Dealer Code: 04018	



Parts Recovery Control Sheet


Ship all parts to TMS – Parts Return Center. Do not type in SHADED fields
If the *Final Destination* field below states "scrap", properly dispose of the part.

Final Destination: N/A

Note: If EWR contains 2 or more VIN's, create a table in the report containing VIN, production date, and mileage

	Failed Part # 1:	Part Description	Qty.	Unit Cost
1	7700106080	TANK SUB-ASSY, FUEL	1	\$ 1.00
	Comments:			
2	Failed Part # 2:	Part Description	Qty.	Unit Cost
	Comments:			
3	Failed Part # 3:	Part Description	Qty.	Unit Cost
	Comments:			
4	Failed Part # 4:	Part Description	Qty.	Unit Cost
	Comments:			
5	Failed Part # 5:	Part Description	Qty.	Unit Cost
	Comments:			
6	Failed Part # 6:	Part Description	Qty.	Unit Cost
	Comments:			
7	Failed Part # 7:	Part Description	Qty.	Unit Cost
	Comments:			
8	Failed Part # 8:	Part Description	Qty.	Unit Cost
	Comments:			





FIELD TECHNICAL REPORT

TQCN DOC# FTR-VJK110831	Affiliate TMS	Dept. QA-Powertrain	Source FPE	Location REG-CHI	Ref 17486-1	Date 4/21/03
Problem Area Base Vehicle	Primary Model Camry	Model Year 2002	Production Date 04-2002	Odometer 23004 mi	VIN (confirm 17 characters): 4T1BF30KX2U [REDACTED]	
Condition Title Surge @ 40-50 MPH with Light Throttle-A/F Sensor						

Do not type in Blue shaded fields - Input data from Web page or RDM:

Repair Date 4/16/03	Optional Ref.	Optional Approval
------------------------	---------------	-------------------

Condition Description

The vehicle exhibited a rhythmic engine surge most noticeable while traveling at 40 – 50 mph and while the engine was at normal operating temperature, the ATM was in 3rd or 4th gear, and at a constant speed and throttle angle. The MIL was not illuminated.

Diagnostic Steps:

Scantool snapshot during the customer complaint condition.


Probable Cause

Erratic output of Bank 1 Sensor 1 A/F Sensor as noted in the attached Techview file.

Part # 1: 8946506060	Part # 2: 1714020070	Part # 3:	Parts Disposition: Have part / will ship	Parts Shipping Destination: TMC
-------------------------	-------------------------	-----------	---	------------------------------------

Repair Process

The A/F Sensor and Bank 1 Exhaust Manifold (due to a seized Bank 1 Sensor 1 A/F Sensor) were replaced which restored normal A/F Sensor output and proper engine operation.



Seized Bank 1 Sensor 1 A/F Sensor causing an engine surge. The Sensor is seized in the Bank 1 Manifold.

Techview snapshot of erratic output of Bank 1 Sensor 1 A/F Sensor.

"4T1BF30KX2U [REDACTED]
3 EG SURGE.evn"

Attachment 1: PRCS

FIELD TECHNICAL REPORT



TQCN DOC# FTR-VJK110831	Affiliate TMS	Dept. QA-Powertrain	Source FPE	Location REG-CHI	Ref 17486-1	Date 4/21/03
Problem Area Base Vehicle	Primary Model Camry	Model Year 2002	Production Date 04-2002	Odometer 23004 mi	VIN (confirm 17 characters): 4T1BF30KX2U [REDACTED]	
Condition Title Surge @ 40-50 MPH with Light Throttle-A/F Sensor						

Attachment 1 : Parts Recovery Control Sheet

Ship all parts to TMS – Parts Return Center. Do not type in SHADED fields
If the **Final Destination** field below is "scrap", properly dispose of the part.

Final Destination: TMC				
Importer: (Applies to TMC Shipments Only)		Deliver to:	住所 :	
North America EDER Gr., Technical Dept. #1 Overseas Customer Service Technical Div. TOYOTA MOTOR CORPORATION Nisshin Education & Training Center 5-210, SAKAE, NISSHIN, AICH, 470-0113 Japan		Attn:	宛先 :	
		Tel:	Tel:	
Note: If this FTR contains more than one VIN, create a table in the report containing VIN, production date, and odometer				FOR CUSTOMS USE: Used Parts Value
1	Part # 1: 8946506060	Part Description SENSOR, OXYGEN	Qty. 1	Used Part Value \$ 19.00
Comments:				
2	Part # 2: 1714020070	Part Description MANIFOLD ASSY, EXHAUST, RH	Qty. 1	Used Part Value \$ 83.00
Comments:				
3	Part # 3:	Part Description	Qty. 0	Used Part Value \$ 0.00
Comments:				
4	Part # 4:	Part Description	Qty.	Used Part Value \$.00
Comments:				
5	Part # 5:	Part Description	Qty.	Used Part Value \$.00
Comments:				
6	Part # 6:	Part Description	Qty.	Used Part Value \$.00
Comments:				
7	Part # 7:	Part Description	Qty.	Used Part Value \$.00
Comments:				
8	Part # 8:	Part Description	Qty.	Used Part Value \$.00
Comments:				

FIELD TECHNICAL REPORT



TQCN DOC# FTR-VGC217431	Affiliate TMS	Dept QA-Powertrain	Source FPE	Location REG-SF	Ref 19176-1	Date 6/23/03
Problem Area Base Vehicle	Primary Model Sienna	Model Year 2004	Production Date 03-2003	Odometer 7936 mi	VIN (confirm 17 characters): 5TDZA22C44S [REDACTED]	
Condition Title TRANSAXLE WOULD NOT ENGAGE REVERSE						

Do not type in Blue shaded fields - Input data from Web page or RDM:

Repair Date 06/23/03	Optional Ref.	Optional Approval
-------------------------	---------------	-------------------

Condition Description

U151E Transaxle would not engage Reverse Gear. Transaxle would engage a forward Gear and drive forward even with Shift Selector in "R" position (Indicators on Shift Selector Assembly and Combination Meter showed "R" Position).

- Transaxle appeared to be in 3rd Gear regardless of Shift Selector position (R, D, 2 and 1).
- Placing Shift selector in "N" Neutral position caused Vehicle to "creep", as if Transaxle was partially engaging a forward Gear.
- Vehicle was a XLE 4X2 model equipped with 3-Power Doors and Tow Hitch. Engine Serial Number was: **3MZ-4021225**. Transaxle Serial Number was: **530327207**.

Diagnostic Steps:

Technician test drove vehicle, confirmed condition, and noted that MIL was illuminated. DTCs P0746 (Pressure Control Solenoid "A" Performance or Stuck off) and P0776 (Pressure Control Solenoid "B" Performance or Stuck off) were found in ECU memory.

- Technician recorded Freeze Frame Data for DTC P0746. Data was as follows:
 Engine Spd: 2,749 RPM FUEL SYS #2: CL
 Coolant Temp: 194° F SHORT FT #1: 0.8%
 Vehicle SPD: 14MPH LONG FT #1: 0.8%
 CALC LOAD: 30.1% SHORT FT #2: 0.0%
 FUEL SYS #1: CL LONG FT #2: 0.0%
- Technician removed Transaxle Oil Pan and determined that an abnormal amount of Clutch Material and metal debris was present in ATF.
- Heavy deposits of debris were also found in ATF Intake Filter Screen.
- Both Magnets located on floor of Oil Pan exhibited large deposits of ferrous metal. ATF, although red in color, exhibited a strong overheated odor.
- No other DTC, Freeze Frame or RAM Data was available from ECU as Battery had been disconnected during diagnosis.

Probable Cause

Specific cause of condition was unknown, although analysis indicated that Transaxle had sustained mechanical damage to internal Gear train components.

- A Gear Train component such as Reverse Clutch (C2) or 1st & Reverse Brake (B2) could have sustained damage due to a mechanical anomaly or assembly error. Metal debris generated by mechanical damage would result in Shift Control malfunctions due to jamming affect on Control Valves in Valve Body and Shift Solenoid Plungers.
- Customer had reportedly driven Vehicle to East Coast and back (round Trip approx. 6,000 miles). No malfunctions were identified until Transaxle-related condition occurred after returning to Petaluma CA area.
- Although Vehicle was equipped with PIO Tow Hitch, unit had not been used.


Part # 1: 3050008010	Part # 2: 3200008010	Part # 3:	Parts Disposition: Special request only	Parts Shipping Destination: TMMWV
-------------------------	-------------------------	-----------	--	--------------------------------------

Repair Process

Transaxle assembly and Torque Converter will be replaced, which should correct condition. Damaged components will be recovered and forwarded to TMS QAP if requested.


FIELD TECHNICAL REPORT

TQCN DOC# FTR-VGC217431	Affiliate TMS	Dept QA-Powertrain	Source FPE	Location REG-SF	Ref 19176-1	Date 6/23/03
Problem Area Base Vehicle	Primary Model Sienna	Model Year 2004	Production Date 03-2003	Odometer 7936 mi	VIN (confirm 17 characters): 5TDZA22C44S [REDACTED]	
Condition Title TRANSAXLE WOULD NOT ENGAGE REVERSE						



Close-up view of U151E Transaxle Oil Pan showing excessive Clutch material and metal debris deposited on floor of Pan.

- Note large deposits of fine ferrous material on both Oil Pan Magnets.
- ATF, although still red in color, exhibited a strong overheated odor.



Close-up view of ATF Intake Filter Screen showing heavy deposits of debris almost completely restricting visible portion of Screen.

FIELD TECHNICAL REPORT



TQCN DOC# FTR-VGC217431	Affiliate TMS	Dept. QA-Powertrain	Source FPE	Location REG-SF	Ref 19176-1	Date 6/23/03
Problem Area Base Vehicle	Primary Model Sienna	Model Year 2004	Production Date 03-2003	Odometer 7936 mi	VIN (confirm 17 characters): 5TDZA22C44S [REDACTED]	
Condition Title TRANSAXLE WOULD NOT ENGAGE REVERSE						

Attachment 1: PRCS

Attachment 1 : Parts Recovery Control Sheet

Ship all parts to TMS – Parts Return Center. Do not type in SHADED fields
If the **Final Destination** field below is "scrap", properly dispose of the part.

Final Destination: TMMWV					
Importer: (Applies to TMC Shipments Only)		Deliver to:	住所 :		
North America EDER Gr., Technical Dept. #1 Overseas Customer Service Technical Div. TOYOTA MOTOR CORPORATION Nisshin Education & Training Center 5-210, SAKAE, NISSHIN, AICH, 470-0113 Japan		Attn:	宛先 :		
		Tel:	Tel :		
Note: If this FTR contains more than one VIN, create a table in the report containing VIN, production date, and odometer					FOR CUSTOMS USE: Used Parts Value
1	Part # 1: 3050008010	Part Description TRANSAXLE ASSY, AUTOMATIC	Qty. 0	Used Part Value \$ 525 .00	
	Comments:				
2	Part # 2: 3200008010	Part Description CONVERTER ASSY, TORQUE	Qty. 0	Used Part Value \$ 113 .00	
	Comments:				
3	Part # 3:	Part Description	Qty. 0	Used Part Value \$ 0 .00	
	Comments:				
4	Part # 4:	Part Description	Qty.	Used Part Value \$.00	
	Comments:				
5	Part # 5:	Part Description	Qty.	Used Part Value \$.00	
	Comments:				
6	Part # 6:	Part Description	Qty.	Used Part Value \$.00	
	Comments:				
7	Part # 7:	Part Description	Qty.	Used Part Value \$.00	
	Comments:				
8	Part # 8:	Part Description	Qty.	Used Part Value \$.00	
	Comments:				

FIELD TECHNICAL REPORT



TQCN DOC# FTR-52R124831	Affiliate TMS	Dept. QA-Powertrain	Source FTS	Location REG-PT	Ref 20108-1	Date 9/19/03
Problem Area Base Vehicle	Primary Model 4Runner	Model Year 2004	Production Date 02-2003	Odometer 903 mi	VIN (confirm 17 characters): JTEBU17R338 [REDACTED]	
Condition Title SEVERE ENGINE SURGE						

Do not type in Blue shaded fields - Input data from Web page or RDM:

Repair Date 8-6-03	Optional Ref.	Optional Approval
-----------------------	---------------	-------------------

Condition Description

The engine surges for the first 10/15 minutes of cold engine operation. It is most noticeable when the throttle is held steady at 35/45 MPH. If the throttle is held wide open the engine will surge and then run cleanly. This started after 200+ miles. As the dealer or this writer could not initially repair the vehicle the dealership purchased the vehicle from the owner. There were no codes set and after warm-up the vehicle operated normally until an overnight cold soak.

Diagnostic Steps:

Test-drove, when cold, by holding throttle steady at 30MPH and observing data parameters; the accelerator sensors held steady but the throttle motor opened and closed. Dealer replaced complete fuel system along with the complete intake system, cam and crank sensor, engine ecu and accelerator pedal. This writer spent 3 days taking data samples and doing pin checks at accelerator pedal, engine ecu and throttle motor with no problems found. Also a compression check, static and running, were completed and all was normal.



Probable Cause

This writer felt that the condition was in the engine wire harness, in the engine compartment, as the condition would go away as the engine warmed up. Just holding the throttle steady for 10 minutes at 2000rpm could do this.

Part # 1: 821213M460	Part # 2:	Part # 3:	Parts Disposition: Have part / will ship	Parts Shipping Destination: TMC
-------------------------	-----------	-----------	---	------------------------------------

Repair Process

The engine wire harness was replaced and the condition was corrected.

 4runner 03 surge Appleway 2.evn	 4runner 03 throttle surge Appleway 1.evn

Attachment 1: PRCS

FIELD TECHNICAL REPORT

TQCN DOC# FTR-52R124831	Affiliate TMS	Dept. QA-Powertrain	Source FTS	Location REG-PT	Ref 20108-1	Date 9/19/03
Problem Area Base Vehicle	Primary Model 4Runner	Model Year 2004	Production Date 02-2003	Odometer 903 mi	VIN (confirm 17 characters): JTEBU17R338 [REDACTED]	
Condition Title SEVERE ENGINE SURGE						

FIELD TECHNICAL REPORT



TQCN DOC# FTR-52R124831	Affiliate TMS	Dept. QA-Powertrain	Source FTS	Location REG-PT	Ref 20108-1	Date 9/19/03
Problem Area Base Vehicle	Primary Model 4Runner	Model Year 2004	Production Date 02-2003	Odometer 903 mi	VIN (confirm 17 characters): JTEBU17R338 [REDACTED]	
Condition Title SEVERE ENGINE SURGE						

Attachment 1 : Parts Recovery Control Sheet

Ship all parts to TMS – Parts Return Center. Do not type in SHADED fields
If the **Final Destination** field below is "scrap", properly dispose of the part.

Final Destination: TMC				
Importer: (Applies to TMC Shipments Only)		Deliver to:	住所 :	
North America EDER Gr., Technical Dept. #1 Overseas Customer Service Technical Div. TOYOTA MOTOR CORPORATION Nisshin Education & Training Center 5-210, SAKAE, NISSHIN, AICH, 470-0113 Japan		Attn:	宛先 :	
		Tel:	Tel:	
Note: If this FTR contains more than one VIN, create a table in the report containing VIN, production date, and odometer				FOR CUSTOMS USE: Used Parts Value
1	Part # 1: 821213M460	Part Description WIRE, ENGINE	Qty. 1	Used Part Value \$ 106 .00
	Comments:			
2	Part # 2:	Part Description	Qty. 0	Used Part Value \$ 0 .00
	Comments:			
3	Part # 3:	Part Description	Qty. 0	Used Part Value \$ 0 .00
	Comments:			
4	Part # 4:	Part Description	Qty.	Used Part Value \$.00
	Comments:			
5	Part # 5:	Part Description	Qty.	Used Part Value \$.00
	Comments:			
6	Part # 6:	Part Description	Qty.	Used Part Value \$.00
	Comments:			
7	Part # 7:	Part Description	Qty.	Used Part Value \$.00
	Comments:			
8	Part # 8:	Part Description	Qty.	Used Part Value \$.00
	Comments:			

FIELD TECHNICAL REPORT



TQCN DOC# FTR-VRR326231D		Affiliate TMS	Dept. QA-Chassis	Source FPE	Location TMS	Ref 20112-1	Date 9/19/03
Problem Area Base Vehicle	Primary Model RX 330	Model Year 2004	Production Date 07-2003	Odometer 593 mi	VIN (confirm 17 characters): JTJGA31U240 [REDACTED]		
Condition Title ABS Actuator							

Do not type in YELLOW shaded fields - Input data from Web page or RDM:

Repair Date 9/18/03	Optional Ref.	Optional Approval
------------------------	---------------	-------------------

Condition Description

Customer states when sitting at a stoplight the brakes gradually release and the vehicle begins to creep forward. The brake pedal must be applied harder to stop the vehicle.

Diagnostic Steps:

1. The vehicle was test-driven and the problem was duplicated. A brake pedal depressor (from the alignment machine tools) was used to hold a consistent pressure on the brake pedal. After the brake pedal was depressed with a constant brake pressure the vehicle began to creep forward after several seconds. This was done several times with the same result.
2. The vehicle was checked for diagnostic trouble codes: None
3. The master cylinder was replaced and had no effect on the condition
4. The ABS actuator was replaced and the problem was eliminated.


Probable Cause

The ABS actuator was bleeding off brake pressure from the calipers and allowing the vehicle to creep forward.

Part # 1: 4405048070	Part # 2:	Part # 3:	Parts Disposition: Have part / will ship	Parts Shipping Destination: TMC
-------------------------	-----------	-----------	---	------------------------------------

Repair Process

Replacing the ABS actuator repaired the vehicle.



Attachment 1: PRCS

FIELD TECHNICAL REPORT



TQCN DOC# FTR-VRR326231D	Affiliate TMS	Dept. QA-Chassis	Source FPE	Location TMS	Ref 20112-1	Date 9/19/03
Problem Area Base Vehicle	Primary Model RX 330	Model Year 2004	Production Date 07-2003	Odometer 593 mi	VIN (confirm 17 characters): JTJGA31U24 [REDACTED]	
Condition Title ABS Actuator						

Attachment 1 : Parts Recovery Control Sheet

VIN [REDACTED]

Ship all parts to TMS – Parts Return Center. Do not type in SHADED fields. If the **Final Destination** field below is "scrap", properly dispose of the part.

TQCN Doc No.



Final Destination: TMC		SETR#:	CQE Eng:	N/A
Importer: (Applies to TMC Shipments Only)		Deliver to:	住所 :	
North America EDER Gr., Technical Dept. #1 Overseas Customer Service Technical Div. TOYOTA MOTOR CORPORATION Nisshin Education & Training Center 5-210, SAKAE, NISSHIN, AICH, 470-0113 Japan		Attn:	宛先 :	
		Tel:	Tel:	
T-STAR				
Note: If this FTR contains more than one VIN, create a table in the report containing VIN, production date, and odometer				FOR CUSTOMS USE: Used Parts Value
Part #	Part Description	Qty.	Used Part Value	
1	4405048070 ACTUATOR ASSY, BRAKE W/FLUID Comments:	1	\$ 368 .00	
2	Part # 2: Part Description Comments:	0	\$ 0 .00	
3	Part # 3: Part Description Comments:	0	\$ 0 .00	
4	Part # 4: Part Description Comments:		\$.00	
5	Part # 5: Part Description Comments:		\$.00	
6	Part # 6: Part Description Comments:		\$.00	
7	Part # 7: Part Description Comments:		\$.00	
8	Part # 8: Part Description Comments:		\$.00	

FIELD TECHNICAL REPORT



TQC# DOC# FTR-JRC236531		Affiliate TMS	Dept. QA-Powertrain	Source FTS	Location REG-CIN	Ref 21270-1	Date 1/12/04
Problem Area Base Vehicle	Primary Model Sienna	Model Year 2004	Production Date 03-2003	Odometer 11664 mi	VIN (confirm 17 characters): 5TDZA22C74S [REDACTED]		
Condition Title Electronic Control Accelerator Pedal Position Sensor							

Do not type in Blue shaded fields - Input data from Web page or RDM:

Repair Date November 12, 2003	Optional Ref.	Optional Approval
----------------------------------	---------------	-------------------

Condition Description

T.M.S. associate states vehicle throttle would not return to idle after accelerating. States the throttle pedal had to be lifted by hand before the engine would return to idle. This is the reported drive cycle prior to the incident; accelerated up hill about 30-40 mph, lift throttle prior to turn, did not decelerate, applied brakes successfully slowing to negotiate turn, put transmission in neutral and engine revved high (did not notice if went to fuel cut), put back into drive and pulled over to side of road, reached down and pulled throttle pedal upward, vehicle went to idle and has not recurred.

Diagnostic Steps:

F.T.S. inspected the vehicle after occurrence. Vehicle drives properly and no codes were stored. Noted the driver's side carpeted floor mat was installed upside down and not clipped in place. Associate does not believe floor mat was interfering with throttle. F.T.S. found sand on floor, probably from recent trip to beach area.


Probable Cause

No probable cause could be determined by Field Technical Specialist.

Part # 1: 7812008020	Part # 2:	Part # 3:	Parts Disposition: Have part / will ship	Parts Shipping Destination: TMMNA
-------------------------	-----------	-----------	---	--------------------------------------


Repair Process

Throttle pedal/sensor assembly recovered for further evaluation only, no fault found to exist.



Attachment 1: PRCS

FIELD TECHNICAL REPORT



TQCN DOC# FTR-JRC236531		Affiliate TMS	Dept. QA-Powertrain	Source FTS	Location REG-CIN	Ref 21270-1	Date 1/12/04
Problem Area Base Vehicle	Primary Model Sienna	Model Year 2004	Production Date 03-2003	Odometer 11664 mi	VIN (confirm 17 characters): 5TDZA22C74S [REDACTED]		
Condition Title Electronic Control Accelerator Pedal Position Sensor							

Attachment 1 : Parts Recovery Control Sheet

Ship all parts to TMS – Parts Return Center. Do not type in SHADED fields
If the **Final Destination** field below is “scrap”, properly dispose of the part.

Final Destination: TMMNA				
Importer: (Applies to TMC Shipments Only)		Deliver to:	住所 :	
North America EDER Gr., Technical Dept. #1 Overseas Customer Service Technical Div. TOYOTA MOTOR CORPORATION Nisshin Education & Training Center 5-210, SAKAE, NISSHIN, AICH, 470-0113 Japan		Attn:	宛先 :	
		Tel:	Tel:	
Note: If this FTR contains more than one VIN, create a table in the report containing VIN, production date, and odometer				FOR CUSTOMS USE: Used Parts Value
1	Part # 1: 7812008020	Part Description ROD ASSY, ACCELERATOR PEDAL	Qty. 1	Used Part Value \$ 5.00
	Comments:			
2	Part # 2:	Part Description	Qty. 0	Used Part Value \$ 0.00
	Comments:			
3	Part # 3:	Part Description	Qty. 0	Used Part Value \$ 0.00
	Comments:			
4	Part # 4:	Part Description	Qty. \$	Used Part Value .00
	Comments:			
5	Part # 5:	Part Description	Qty. \$	Used Part Value .00
	Comments:			
6	Part # 6:	Part Description	Qty. \$	Used Part Value .00
	Comments:			
7	Part # 7:	Part Description	Qty. \$	Used Part Value .00
	Comments:			
8	Part # 8:	Part Description	Qty. \$	Used Part Value .00
	Comments:			

FIELD TECHNICAL REPORT



TQCN DOC# FTR-7QR101241		Affiliate TMS	Dept. QA-Powertrain	Source FTS	Location REG-LA	Ref 20108-1	Date 1/14/04
Problem Area Base Vehicle	Primary Model 4Runner	Model Year 2004	Production Date 05-2003	Odometer 5222 mi	VIN (confirm 17 characters): JTEBU14R330 [REDACTED]		
Condition Title 2003 4Runner V6 Surging							

Do not type in YELLOW shaded fields - Input data from Web page or RDM:

Repair Date 12/30/03	Optional Ref.	Optional Approval
-------------------------	---------------	-------------------

Condition Description

- Customer complaint of vehicle surging especially during cold engine operation.
- F.T.S. verified that surge occurred during cold engine operation.
- Surge would occur during light throttle application while lightly accelerating.
- Once vehicle was warm (approximately 2-3 minutes), condition would cease.

Diagnostic Steps:

- Scan tool data showed no trouble code stored during malfunction.
- Snapshot data (attached below) indicates that throttle position varies greatly with no change in pedal position.
- Ground input to throttle body suspected.
- When brown wire E2 to throttle body was bypassed directly to engine ground, problem was rectified. (See photo below).
- Harness ground splice disassembled for inspection.

Probable Cause

- Splice point E8 suspected as problem.
- Voltage drop was detected as .5 volt at ground splice E8 on sensor wire between E2 terminal on engine E.C.M. and plug T2 terminal #3 on throttle position sensor.
- 4 amp load was applied to circuit during this test.


Part # 1: 821213M460	Part # 2:	Part # 3:	Parts Disposition: Have part / will ship	Parts Shipping Destination: 2107
-------------------------	-----------	-----------	---	-------------------------------------

Repair Process




"snap shot for 4 runner.doc"

Snapshot from scantool.



Part # for wire loom.




Splice point E8.


FIELD TECHNICAL REPORT




TQCN DOC# FTR-7QR101241		Affiliate TMS	Dept. QA-Powertrain	Source FTS	Location REG-LA	Ref 20108-1	Date 1/14/04
Problem Area Base Vehicle	Primary Model 4Runner	Model Year 2004	Production Date 05-2003	Odometer 5222 mi	VIN (confirm 17 characters): JTEBU14R330 [REDACTED]		
Condition Title 2003 4Runner V6 Surging							



Test wire added from throttle body to engine ground.



Splice point cover.



Attachment 1: PRCS

FIELD TECHNICAL REPORT



TQCN DOC# FTR-7QR101241	Affiliate TMS	Dept. QA-Powertrain	Source FTS	Location REG-LA	Ref 20108-1	Date 1/14/04
Problem Area Base Vehicle	Primary Model 4Runner	Model Year 2004	Production Date 05-2003	Odometer 5222 mi	VIN (confirm 17 characters): JTEBU14R330 [REDACTED]	
Condition Title 2003 4Runner V6 Surging						

Attachment 1: Parts Recovery Control Sheet

Do not type in SHADED fields. If the Final Destination field below is "scrap", properly dispose of the part.

Orig Tracking
VIN [REDACTED]
Doc No. [REDACTED]



Final Destination: 2107		SETR#:	CQE Eng:	N/A
Importer: (Applies to TMC Shipments Only)		Deliver to:	住所 :	
North America EDER Gr., Technical Dept. #1 Overseas Customer Service Technical Div. TOYOTA MOTOR CORPORATION Nisshin Education & Training Center 5-210, SAKAE, NISSHIN, AICH, 470-0113 Japan		Attn:	宛先 :	
		Tel:	Tel:	
T-STAR		[REDACTED]		[REDACTED]
Note: If this FTR contains more than one VIN, create a table in the report containing VIN, production date, and odometer				FOR CUSTOMS USE: Used Parts Value
1	Part # 1:	Part Description	Qty.	Used Part Value
	821213M460	WIRE, ENGINE	1	\$ 106 .00
Comments:				
2	Part # 2:	Part Description	Qty.	Used Part Value
			0	\$ 0 .00
Comments:				
3	Part # 3:	Part Description	Qty.	Used Part Value
			0	\$ 0 .00
Comments:				
4	Part # 4:	Part Description	Qty.	Used Part Value
				\$.00
Comments:				
5	Part # 5:	Part Description	Qty.	Used Part Value
				\$.00
Comments:				
6	Part # 6:	Part Description	Qty.	Used Part Value
				\$.00
Comments:				
7	Part # 7:	Part Description	Qty.	Used Part Value
				\$.00
Comments:				
8	Part # 8:	Part Description	Qty.	Used Part Value
				\$.00
Comments:				

FIELD TECHNICAL REPORT

TQCN DOC# FTR-7QK101441A	Affiliate TMS	Dept. QA-Powertrain	Source FTS	Location REG-LA	Ref 21340-1	Date 1/21/04
Problem Area Base Vehicle	Primary Model Camry	Model Year 2004	Production Date 09-2003	Odometer 1087 mi	VIN (confirm 17 characters): 4T1BE32K04U [REDACTED]	
Condition Title Engine Wire Harness Surge Engine Compartment						

Do not type in YELLOW shaded fields - Input data from Web page or RDM:

Repair Date 12/30/03	Optional Ref. 27746	Optional Approval
-------------------------	------------------------	-------------------

Condition Description

- Customer complaint of vehicle surging especially during cold engine operation.
- F.T.S. verified that surge occurred during cold engine operation.
- Surge would occur during light throttle application while lightly accelerating.
- Once vehicle was warm (approximately 2-3 minutes), condition would cease.

Diagnostic Steps:


- Scan tool data showed no trouble code stored during malfunction.
- Snapshot data (attached below) indicates that throttle position varies greatly with no change in pedal position.
- Ground input to throttle body suspected.
- When brown wire E2 to throttle body was bypassed directly to engine ground, problem was rectified. (See photo below).
- Harness ground splice disassembled for inspection.

Probable Cause


- Splice point E8 suspected as problem.
- Voltage drop was detected as .5 volt at ground splice E8 on sensor wire between E2 terminal on engine E.C.M. and plug T2 terminal #3 on throttle position sensor.
- 4 amp load was applied to circuit during this test.

Part # 1: N/A	Part # 2:	Part # 3:	Parts Disposition: No part available	Parts Shipping Destination: N/A
------------------	-----------	-----------	---	------------------------------------


Repair Process



"snap shot for 4 runner.doc" Snapshot from scantool.




Part # for wire loom.



Splice point E8.

FIELD TECHNICAL REPORT



TQCN DOC# FTR-7QK101441A		Affiliate TMS	Dept. QA-Powertrain	Source FTS	Location REG-LA	Ref 21340-1	Date 1/21/04
Problem Area Base Vehicle	Primary Model Camry	Model Year 2004	Production Date 09-2003	Odometer 1087 mi	VIN (confirm 17 characters): 4T1BE32K04U [REDACTED]		
Condition Title Engine Wire Harness Surge Engine Compartment							



Test wire added from throttle body to engine ground.



Splice point cover.



Attachment 1: PRCS

FIELD TECHNICAL REPORT



TQCN DOC# FTR-7QK101441A	Affiliate TMS	Dept. QA-Powertrain	Source FTS	Location REG-LA	Ref 21340-1	Date 1/21/04
Problem Area Base Vehicle	Primary Model Camry	Model Year 2004	Production Date 09-2003	Odometer 1087 mi	VIN (confirm 17 characters): 4T1BE32K04U [REDACTED]	
Condition Title Engine Wire Harness Surge Engine Compartment						

Attachment 1: Parts Recovery Control Sheet

Do not type in SHADED fields. If the **Final Destination** field below is "scrap", properly dispose of the part.

Orig Tracking

VIN

Doc No.



Final Destination: N/A	SETR#:	CQE Eng:	N/A
-------------------------------	--------	----------	-----

Importer: (Applies to TMC Shipments Only) North America EDER Gr., Technical Dept. #1 Overseas Customer Service Technical Div. TOYOTA MOTOR CORPORATION Nisshin Education & Training Center 5-210, SAKAE, NISSHIN, AICH, 470-0113 Japan	Deliver to:	住所:
	Attn:	宛先:
	Tel:	TEL:

T-STAR		
--------	--	--

Note: If this FTR contains more than one VIN, create a table in the report containing VIN, production date, and odometer

FOR CUSTOMS USE:
Used Parts Value

	Part # 1:	Part Description	Qty.	Used Part Value
1	N/A		0	\$ 0.00
	Comments:			
2			0	\$ 0.00
	Comments:			
3			0	\$ 0.00
	Comments:			
4				\$.00
	Comments:			
5				\$.00
	Comments:			
6				\$.00
	Comments:			
7				\$.00
	Comments:			
8				\$.00
	Comments:			

FIELD TECHNICAL REPORT



TQCN DOC# FTR-VLG108941		Affiliate TMS	Dept. QA-Powertrain	Source FPE	Location TMS	Ref 21674-1	Date 3/29/04
Problem Area Base Vehicle	Primary Model ES 330	Model Year 2004	Production Date 09-2003	Odometer 6121 mi	VIN (confirm 17 characters): JTHBA30G3450 [REDACTED]		
Condition Title ATM Hesitation and Jerk							

Do not type in YELLOW shaded fields - Input data from Web page or RDM:

Repair Date 3/29/04	Optional Ref.	Optional Approval
------------------------	---------------	-------------------

Condition Description

Customer complained of vehicle hesitating and jerking when accelerating from a rolling stop.

Diagnostic Steps:

Dealership Technician and FPE drove vehicle on freeway and in residential area around dealership, duplicating 3 distinct conditions during a rolling stop. (See details below)

Probable Cause

Exact cause is unknown. Suspected cause is ECM shifting logic takes too long to decide on which gear and how much throttle to apply during low speed acceleration demand from driver.

Part # 1: N/A	Part # 2:	Part # 3:	Parts Disposition: No part available	Parts Shipping Destination: N/A
------------------	-----------	-----------	---	------------------------------------

Repair Process

No known repair at this time.

REACCELERATING AT 5 TO 10 MPH



PROBLEM DESCRIPTIONS

Decelerating to a stop light, for stopped traffic, or slowing for a turn and reaccelerating before stopping frequently results in the following conditions:

1. Decelerate to 5 mph and lightly reaccelerate – Soft 2nd gear downshift then an abrupt 1st gear downshift.
2. Decelerate to 5 mph and lightly reaccelerate – A single harsh jerk during downshift.
3. Decelerate to 10 mph and lightly accelerate – Free rev to 2,000 rpm then a harsh downshift to 2nd gear.

NOTE: All 3 scenarios were described by customer and duplicated a minimum of 2 times each in a 45 minute test drive by DS and FPE.

Attachment 1: PRCS

FIELD TECHNICAL REPORT



TQCN DOC# FTR-VLG108941	Affiliate TMS	Dept. QA-Powertrain	Source FPE	Location TMS	Ref 21674-1	Date 3/29/04
Problem Area Base Vehicle	Primary Model ES 330	Model Year 2004	Production Date 09-2003	Odometer 6121 mi	VIN (confirm 17 characters): JTHBA30G3450 [REDACTED]	
Condition Title ATM Hesitation and Jerk						

Attachment 1 : Parts Recovery Control Sheet

VIN [REDACTED]

Ship all parts to TMS – Parts Return Center. Do not type in SHADED fields. If the Final Destination field below is "scrap", properly dispose of the part.

TQCN Doc No. [REDACTED]



Final Destination: N/A	SETR#:	CQE Eng:	N/A
------------------------	--------	----------	-----

Importer: (Applies to TMC Shipments Only) North America EDER Gr., Technical Dept. #1 Overseas Customer Service Technical Div. TOYOTA MOTOR CORPORATION Nisshin Education & Training Center 5-210, SAKAE, NISSHIN, AICH, 470-0113 Japan	Deliver to:	住所 :
	Attn:	宛先 :
	Tel:	Tel:

T-STAR	[Barcode]	[Barcode]
--------	-----------	-----------

Note: If this FTR contains more than one VIN, create a table in the report containing VIN, production date, and odometer

FOR CUSTOMS USE:
Used Parts Value

	Part #	Part Description	Qty.	Used Part Value
1	N/A		0	\$ 0.00
Comments:				
2			0	\$ 0.00
Comments:				
3			0	\$ 0.00
Comments:				
4				\$.00
Comments:				
5				\$.00
Comments:				
6				\$.00
Comments:				
7				\$.00
Comments:				
8				\$.00
Comments:				

FIELD TECHNICAL REPORT

TQCN DOC# FTR-VGF209041	Affiliate TMS	Dept. QA-Powertrain	Source FPE	Location REG-SF	Ref 21214-1	Date 3/30/04
Problem Area Base Vehicle	Primary Model LS 430	Model Year 2004	Production Date 09-2003	Odometer 5731 mi	VIN (confirm 17 characters): JTHBN36F640 [REDACTED]	
Condition Title ENGINE LACKS POWER/SURGES-FUEL PUMP MALFUNCTION						

Do not type in YELLOW shaded fields - Input data from Web page or RDM:

Repair Date 03/26/04	Optional Ref.	Optional Approval
-------------------------	---------------	-------------------

Condition Description

Engine lacked power during low speed operation and surged while driving on freeway with Cruise Control set (approx. 65 mph). Condition was very intermittent, but occurred repeatedly during previous 2 weeks before repair date. Engine Serial Number was: 3UZ-0246322.

- Technician was unable to duplicate malfunction.
- Engine performance appeared to be otherwise normal.
- MIL had not illuminated and no DTCs were found in ECM memory.

Affected vehicle was a 2004 LS 430 Ultra Luxury model equipped with 3UZ-FE engine, A761E transmission, and all available factory options.

Diagnostic Steps:

Technician extensively test drove vehicle with customer, but was unable to duplicate lack of power/surging malfunction.

- Technician independently test drove vehicle under city and freeway conditions and could not duplicate reported malfunction, even after accumulating approx. 2 hours of testing.
- However, on one occasion, engine stalled 3 times while driving around dealership at approx. 15 mph after cold start-up. Engine started up immediately after each stalling event.
- Technician examined vehicle and determined that the fuel pump was the most likely cause of condition.

Probable Cause

Analysis indicated that the fuel pump assembly was malfunctioning, causing intermittent lack of engine power, surging, and stalling due to low fuel pressure.

- Fuel inside the fuel tank was clean, but a small amount of foreign material or debris was noted on bottom of the tank.
- Fuel pump inlet screen was clean, and exhibited no sign of foreign material or debris.

Part # 1: 2322050110	Part # 2:	Part # 3:	Parts Disposition: Have part / will ship	Parts Shipping Destination: 2106
-------------------------	-----------	-----------	---	-------------------------------------

Repair Process

Fuel Pump assembly ("Pump Assy, Fuel" PN 23220-50110) was replaced, correcting condition. Malfunctioning OEM unit was recovered, and will be forwarded to TMS QAP with this Report.



Overall view of malfunctioning LS 430 Fuel Pump that had caused intermittent lack of Engine power, surging and stalling due to low fuel pressure.


- Fuel Pump was manufactured by Aisan.
- A yellow-colored paint mark was located on rear of the brown plastic housing.
- No other markings were identified on Fuel Pump assembly.

Note: Fuel pump Connector Receptacle sustained damage when it was accidentally dropped after removal from Vehicle.

FIELD TECHNICAL REPORT



TQCN DOC# FTR-VGF209041	Affiliate TMS	Dept. QA-Powertrain	Source FPE	Location REG-SF	Ref 21214-1	Date 3/30/04
Problem Area Base Vehicle	Primary Model LS 430	Model Year 2004	Production Date 09-2003	Odometer 5731 mi	VIN (confirm 17 characters): JTHBN36F640 [REDACTED]	
Condition Title ENGINE LACKS POWER/SURGES-FUEL PUMP MALFUNCTION						



Close-up photo of fuel tank showing a small accumulation of dirt/debris on floor of tank immediately below fuel pump assembly.

- Debris accumulation was small, and none was found on fuel pump inlet screen assy.
- Debris had not been introduced to the fuel tank when fuel pump was removed, and was identified immediately after Fuel Pump/Sender/Filter assembly was dismounted.

Attachment 1: PRCS

Attachment 1 : Parts Recovery Control Sheet

Ship all parts to TMS – Parts Return Center. Do not type in SHADED fields. If the **Final Destination** field below is "scrap", properly dispose of the part.

VIN [REDACTED]

TQCN Doc No. [REDACTED]



Final Destination: 2106	SETR#:	CQE Eng: N/A
Importer: (Applies to TMC Shipments Only) North America EDER Gr., Technical Dept. #1 Overseas Customer Service Technical Div. TOYOTA MOTOR CORPORATION Nisshin Education & Training Center 5-210, SAKAE, NISSHIN, AICH, 470-0113 Japan	Deliver to: Attn: Tel:	住所 : 宛先 : Tel:
T-STAR	[Barcode]	[Barcode]
Note: If this FTR contains more than one VIN, create a table in the report containing VIN, production date, and odometer		FOR CUSTOMS USE: Used Parts Value
1	Part # 1: 2322050110 Comments:	Part Description PUMP ASSY, FUEL W/FILTER Qty. 1 Used Part Value \$ 44.00
2	Part # 2: Comments:	Part Description Qty. 0 Used Part Value \$ 0.00
3	Part # 3: Comments:	Part Description Qty. 0 Used Part Value \$ 0.00

FIELD TECHNICAL REPORT



TQCN DOC# FTR-VRR313241A		Affiliate TMS	Dept. QA-Chassis	Source FPE	Location REG-LSA	Ref 20446-1	Date 5/12/2004
Problem Area Base Vehicle	Primary Model RX 330	Model Year 2004	Production Date 10-2003	Odometer 6224 mi	VIN (confirm 17 characters): JTJGA31U140 [REDACTED]		
Condition Title BRAKES GRADUALLY RELEASE - ABS ACTUATOR							

Do not type in YELLOW shaded fields - Input data from Web page or RDM:

Repair Date 4/5/04	Optional Ref. 0510043	Optional Approval
-----------------------	--------------------------	-------------------

Condition Description

Customer states when sitting at a stoplight the brakes gradually release and the vehicle begins to creep forward. The brake pedal must be applied harder to stop the vehicle.

Diagnostic Steps:

1. The vehicle was test-driven and the problem was duplicated. A brake pedal depressor (from the alignment machine tools) was used to hold a consistent pressure on the brake pedal. After the brake pedal was depressed with a constant brake pressure the vehicle began to creep forward after several seconds. This was done several times with the same result.
2. The vehicle was checked for diagnostic trouble codes: None
3. The master cylinder and booster assembly were replaced and had no effect on the condition
4. The ABS actuator was replaced and the problem was eliminated.


Probable Cause

Unknown at this time.

Part # 1: 4405048150	Part # 2:	Part # 3:	Parts Disposition: Have part / will ship	Parts Shipping Destination: TMC
-------------------------	-----------	-----------	---	------------------------------------

Repair Process

Replacing the ABS actuator repaired the vehicle.

	<p>TOYOTA 44540-48050 89541-48050 ADVICS 133800-7220 10E521848</p>
---	---

Attachment 1: PRCS

FIELD TECHNICAL REPORT



TQCN DOC# FTR-VRR313241A	Affiliate TMS	Dept. QA-Chassis	Source FPE	Location REG-LSA	Ref 20446-1	Date 5/12/2004
Problem Area Base Vehicle	Primary Model RX 330	Model Year 2004	Production Date 10-2003	Odometer 6224 mi	VIN (confirm 17 characters): JTJGA31U140 [REDACTED]	
Condition Title BRAKES GRADUALLY RELEASE - ABS ACTUATOR						

Attachment 1: Parts Recovery Control Sheet

Do not type in SHADED fields. If the **Final Destination** field below is "scrap", properly dispose of the part.

Orig Tracking

VIN

Doc No.



Final Destination: TMC		SETR#:	CQE Eng:	N/A
Importer: (Applies to TMC Shipments Only)		Deliver to:		住所 :
North America EDER Gr., Technical Dept. #1 Overseas Customer Service Technical Div. TOYOTA MOTOR CORPORATION Nisshin Education & Training Center 5-210, SAKAE, NISSHIN, AICH, 470-0113 Japan		Attn:		宛先 :
		Tel:		Tel:
T-STAR				
Note: If this FTR contains more than one VIN, create a table in the report containing VIN, production date, and odometer				FOR CUSTOMS USE: Used Parts Value
Part #	Part #	Part Description	Qty.	Used Part Value
1	4405048150	ACTUATOR ASSY, BRAKE W/FLUID	1	\$ 367 .00
Comments:				
2			0	\$ 0 .00
Comments:				
3			0	\$ 0 .00
Comments:				
4				\$.00
Comments:				
5				\$.00
Comments:				
6				\$.00
Comments:				
7				\$.00
Comments:				
8				\$.00
Comments:				

FIELD TECHNICAL REPORT



TQCN DOC# FTR-VRR313241		Affiliate TMS	Dept. QA-Chassis	Source FPE	Location REG-LSA	Ref 20446-1	Date 5/12/2004
Problem Area Base Vehicle	Primary Model RX 330	Model Year 2004	Production Date 12-2003	Odometer 684 mi	VIN (confirm 17 characters): JTJGA31U040 [REDACTED]		
Condition Title BRAKES GRADUALLY RELEASE - ABS ACTUATOR							

Do not type in YELLOW shaded fields - Input data from Web page or RDM:

Repair Date 4/13/04	Optional Ref. 0510042	Optional Approval
------------------------	--------------------------	-------------------

Condition Description

Customer states when sitting at a stoplight the brakes gradually release and the vehicle begins to creep forward. The brake pedal must be applied harder to stop the vehicle.

Diagnostic Steps:

1. The vehicle was test-driven and the problem was duplicated. A brake pedal depressor (from the alignment machine tools) was used to hold a consistent pressure on the brake pedal. After the brake pedal was depressed with a constant brake pressure the vehicle began to creep forward after several seconds. This was done several times with the same result.
2. The vehicle was checked for diagnostic trouble codes: None
3. The master cylinder and booster assembly were replaced and had no effect on the condition
4. The ABS actuator was replaced and the problem was eliminated.



Probable Cause

Unknown at this time.

Part # 1: 4405048150	Part # 2:	Part # 3:	Parts Disposition: Have part / will ship	Parts Shipping Destination: TMC
-------------------------	-----------	-----------	---	------------------------------------

Repair Process

Replacing the ABS actuator repaired the vehicle.



Attachment 1: PRCS

FIELD TECHNICAL REPORT



TQCN DOC# FTR-VRR313241	Affiliate TMS	Dept. QA-Chassis	Source FPE	Location REG-LSA	Ref 20446-1	Date 5/12/2004
Problem Area Base Vehicle	Primary Model RX 330	Model Year 2004	Production Date 12-2003	Odometer 684 mi	VIN (confirm 17 characters): JTJGA31U040 [REDACTED]	
Condition Title BRAKES GRADUALLY RELEASE - ABS ACTUATOR						

Attachment 1: Parts Recovery Control Sheet

Do not type in SHADED fields. If the **Final Destination** field below is "scrap", properly dispose of the part.

Orig Tracking

VIN

Doc No.



Final Destination: TMC	SETR#:	CQE Eng:	N/A
Importer: (Applies to TMC Shipments Only) North America EDER Gr., Technical Dept. #1 Overseas Customer Service Technical Div. TOYOTA MOTOR CORPORATION Nisshin Education & Training Center 5-210, SAKAE, NISSHIN, AICH, 470-0113 Japan	Deliver to: Attn: Tel:	住所 : 宛先 : Tel:	

T-STAR



Note: If this FTR contains more than one VIN, create a table in the report containing VIN, production date, and odometer

FOR CUSTOMS USE:
Used Parts Value

	Part #	Part Description	Qty.	Used Part Value
1	4405048150	ACTUATOR ASSY, BRAKE W/FLUID	1	\$ 367 .00
	Comments:			
2			0	\$ 0 .00
	Comments:			
3			0	\$ 0 .00
	Comments:			
4				\$.00
	Comments:			
5				\$.00
	Comments:			
6				\$.00
	Comments:			
7				\$.00
	Comments:			
8				\$.00
	Comments:			

FIELD TECHNICAL REPORT



TQCN DOC# FTR-J0K116041		Affiliate TMS	Dept. QA-Powertrain	Source FTS	Location REG-GST	Ref 22709-1	Date 6/9/2004
Problem Area Base Vehicle	Primary Model Camry	Model Year 2004	Production Date 02-2004	Odometer 1502 mi	VIN (confirm 17 characters): 4T1BE32K54U [REDACTED]		
Condition Title Engine Surge, A/F Sensor Malfunction							

Do not type in YELLOW shaded fields - Input data from Web page or RDM:

Repair Date 05/11/2004	Optional Ref.	Optional Approval
---------------------------	---------------	-------------------

Condition Description

Vehicle surges when driving under light load. No DTC's stored in the ECM.

Diagnostic Steps:

- Inspected fuel pressure. Fuel pressure was 46 psi.
- Inspected operation of mass airflow sensor. Used calculated load per Repair Manual and compared readings, all readings within specifications. Exchanged MAS with known good unit, no change in condition.
- Exchanged ECM with KGU ECM with no change.
- Disconnected air/fuel ratio sensor and problem went away.

Probable Cause


False signal from the air/fuel ratio sensor.

Dealership did not provide Techview file, the type of false signal is not available.

Part # 1: 8946733080	Part # 2:	Part # 3:	Parts Disposition: Have part / will ship	Parts Shipping Destination: TMMNA
-------------------------	-----------	-----------	---	--------------------------------------

Repair Process


Replacing the sensor corrected the concern.



Air/Fuel Ratio Sensor
P/N 89467-33080
Denso 0070
01F27

FIELD TECHNICAL REPORT

TQCN DOC# FTR-J0K116041	Affiliate TMS	Dept. QA-Powertrain	Source FTS	Location REG-GST	Ref 22709-1	Date 6/9/2004
Problem Area Base Vehicle	Primary Model Camry	Model Year 2004	Production Date 02-2004	Odometer 1502 mi	VIN (confirm 17 characters): 4T1BE32K54U [REDACTED]	
Condition Title Engine Surge, A/F Sensor Malfunction						



Attachment 1: PRCS

FIELD TECHNICAL REPORT



TQCN DOC# FTR-JOK116041	Affiliate TMS	Dept. QA-Powertrain	Source FTS	Location REG-GST	Ref 22709-1	Date 6/9/2004
Problem Area Base Vehicle	Primary Model Camry	Model Year 2004	Production Date 02-2004	Odometer 1502 mi	VIN (confirm 17 characters): 4T1BE32K54U [REDACTED]	
Condition Title Engine Surge, A/F Sensor Malfunction						

Attachment 1: Parts Recovery Control Sheet

Do not type in SHADED fields. If the **Final Destination** field below is "scrap", properly dispose of the part.

Orig Tracking

VIN

Doc No.



Final Destination: TMMNA	SETR#:	CQE Eng:	N/A
Importer: (Applies to TMC Shipments Only) North America EDER Gr., Technical Dept. #1 Overseas Customer Service Technical Div. TOYOTA MOTOR CORPORATION Nisshin Education & Training Center 5-210, SAKAE, NISSHIN, AICH, 470-0113 Japan	Deliver to: Attn: Tel:	住所 : 宛先 : Tel:	

T-STAR



Note: If this FTR contains more than one VIN, create a table in the report containing VIN, production date, and odometer

FOR CUSTOMS USE:
Used Parts Value

	Part # 1:	Part Description	Qty.	Used Part Value
1	8946733080	SENSOR, AIR FUEL RATIO	1	\$ 30.00
	Comments:			
2	Part # 2:	Part Description	Qty.	Used Part Value
			0	\$ 0.00
	Comments:			
3	Part # 3:	Part Description	Qty.	Used Part Value
			0	\$ 0.00
	Comments:			
4	Part # 4:	Part Description	Qty.	Used Part Value
				\$.00
	Comments:			
5	Part # 5:	Part Description	Qty.	Used Part Value
				\$.00
	Comments:			
6	Part # 6:	Part Description	Qty.	Used Part Value
				\$.00
	Comments:			
7	Part # 7:	Part Description	Qty.	Used Part Value
				\$.00
	Comments:			
8	Part # 8:	Part Description	Qty.	Used Part Value
				\$.00
	Comments:			

FIELD TECHNICAL REPORT



TQCN DOC# FTR-JCK118141		Affiliate TMS	Dept. QA-Powertrain	Source FTS	Location REG-BOS	Ref 22771-1	Date 6/29/2004
Problem Area Base Vehicle	Primary Model Camry	Model Year 2004	Production Date 04-2004	Odometer 562 mi	VIN (confirm 17 characters): 4T1BF32K24U [REDACTED]		
Condition Title Hesitation on Acceleration							

Do not type in YELLOW shaded fields - Input data from Web page or RDM:

Repair Date 6-23-04	Optional Ref.	Optional Approval
------------------------	---------------	-------------------

Condition Description

Intermittent hesitation, throttle response during up-shift on acceleration after a deceleration. This is usually after a long deceleration, or going around a curve in the road at slow speeds.

Diagnostic Steps:

Dealership installed scan tool to capture condition and could not duplicate condition. Dealership stated they have been able to duplicate condition on one occasion. Customer states that the delay is approximately 2 to 3 seconds long, tech stated more like 1 to 1 and 1/2 second long. The customer also experienced this in a similar vehicle on the dealership lot.

Probable Cause

The customer is feeling the response from the drive by wire response while the transmission is about to change gears. The customer also stated when the vehicle does respond, the vehicle moves strongly forward (as if it has down shifted in response to throttle input)

Part # 1: N/A	Part # 2:	Part # 3:	Parts Disposition: No part available	Parts Shipping Destination: N/A
------------------	-----------	-----------	---	------------------------------------

Repair Process

TSB – TC002-03 was performed TAS case # 041540039

--	--

Attachment 1: PRCS

FIELD TECHNICAL REPORT



TQCN DOC# FTR-JCK118141	Affiliate TMS	Dept. QA-Powertrain	Source FTS	Location REG-BOS	Ref 22771-1	Date 6/29/2004
Problem Area Base Vehicle	Primary Model Camry	Model Year 2004	Production Date 04-2004	Odometer 562 mi	VIN (confirm 17 characters): 4T1BF32K24U [REDACTED]	
Condition Title Hesitation on Acceleration						


Attachment 1: Parts Recovery Control Sheet

Do not type in SHADED fields. If the **Final Destination** field below is "scrap", properly dispose of the part.

Orig Tracking

VIN

Doc No.



Final Destination: N/A	SETR#:	CQE Eng:	N/A
Importer: (Applies to TMC Shipments Only) North America EDER Gr., Technical Dept. #1 Overseas Customer Service Technical Div. TOYOTA MOTOR CORPORATION Nisshin Education & Training Center 5-210, SAKAE, NISSHIN, AICH, 470-0113 Japan	Deliver to: Attn: Tel:	住所 : 宛先 : Tel:	

T-STAR



Note: If this FTR contains more than one VIN, create a table in the report containing VIN, production date, and odometer

FOR CUSTOMS USE:
Used Parts Value

	Part # 1:	Part Description	Qty.	Used Part Value
1	N/A		0	\$ 0.00
	Comments:			
2	Part # 2:	Part Description	Qty.	Used Part Value
			0	\$ 0.00
	Comments:			
3	Part # 3:	Part Description	Qty.	Used Part Value
			0	\$ 0.00
	Comments:			
4	Part # 4:	Part Description	Qty.	Used Part Value
				\$.00
	Comments:			
5	Part # 5:	Part Description	Qty.	Used Part Value
				\$.00
	Comments:			
6	Part # 6:	Part Description	Qty.	Used Part Value
				\$.00
	Comments:			
7	Part # 7:	Part Description	Qty.	Used Part Value
				\$.00
	Comments:			
8	Part # 8:	Part Description	Qty.	Used Part Value
				\$.00
	Comments:			

FIELD TECHNICAL REPORT

TQCN DOC# FTR-8FR318941	Affiliate TMS	Dept. QA-Powertrain	Source FTS	Location REG-LWA	Ref 23066-1	Date 7/8/2004
Problem Area Base Vehicle	Primary Model RX 330	Model Year 2004	Production Date 10-2003	Odometer 5143 mi	VIN (confirm 17 characters): JTJHA31U940 [REDACTED]	
Condition Title RPM Fluctuation at all RPMs, Worse at Idle. Wire Harness						

Do not type in YELLOW shaded fields - Input data from Web page or RDM:

Repair Date 7/2/2004	Optional Ref.	Optional Approval
-------------------------	---------------	-------------------

Condition Description

Surging, approximately 100 RPM every 3 – 5 seconds, noticed primarily at idle, but occurring at all engine speeds. The surging is accompanied by a puffing sound heard in the air filter housing.

Diagnostic Steps:

Prior to FTS involvement dealer technician checked or swapped: Air/fuel ratio sensors, fuel trim, air flow meter, ACIS valve, compression, leak-down, VVTi actuators, ETCSi actuator and TPS, ECM, swapped ignition coils and igniter assemblies.

After FTS involvement the cylinder heads were removed. Valve springs, valve seats, valve guides, lifters and cams were inspected. Electrical and circuit checks included: air flow meter, VVTi oil control valve circuits, VVTi position sensor circuits, NE sensor circuit, ignition system circuits, base timing, throttle control motor and TPS circuits.


Probable Cause

Voltage spike on VTA and VTA2 caused the ECM to turn off the power supply on M+ throttle control motor terminal. See scope shots below:

Part # 1: 822100E010	Part # 2:	Part # 3:	Parts Disposition: Have part / will ship	Parts Shipping Destination: CQEC
-------------------------	-----------	-----------	---	-------------------------------------

Repair Process

Once the relationship between the spikes on VTA and the M+ was found, bypassed VTA and VTA2 wires with external jumper wires. Condition still present. Swapped wiring harness from known good unit and condition was corrected.




KGU - NOT idle
Ch A = M+ Ch B = M-

Picture 1:
Known good unit at normal operating temperature idle. M+ is a steady +B power supply and M- is duty cycled to control idle speed.


FIELD TECHNICAL REPORT

TQCN DOC# FTR-8FR318941		Affiliate TMS	Dept. QA-Powertrain	Source FTS	Location REG-LWA	Ref 23066-1	Date 7/8/2004
Problem Area Base Vehicle	Primary Model RX 330	Model Year 2004	Production Date 10-2003	Odometer 5143 mi	VIN (confirm 17 characters): JTJHA31U940 [REDACTED]		
Condition Title RPM Fluctuation at all RPMs, Worse at Idle. Wire Harness							



JTJHA31U940046786 - NOT idle
Ch A = M+ Ch B = M-

Picture 2:
This is the problem car at normal operating temperature idle.




JTJHA31U940046786 - NOT idle
Ch A = M+ Ch B = VTA

Picture 3:
This is the problem car showing M+ and VTA. Note the spike in VTA and shortly afterward the pattern on M+.


FIELD TECHNICAL REPORT

TQCN DOC# FTR-8FR318941	Affiliate TMS	Dept. QA-Powertrain	Source FTS	Location REG-LWA	Ref 23066-1	Date 7/8/2004
Problem Area Base Vehicle	Primary Model RX 330	Model Year 2004	Production Date 10-2003	Odometer 5143 mi	VIN (confirm 17 characters): JTJHA31U940 [REDACTED]	
Condition Title RPM Fluctuation at all RPMs, Worse at Idle. Wire Harness						



JTJHA31U940046786 - NOT idle
Ch A = M+ Ch B = VTA

Picture 4:
This is the problem car at 100 ms per division.



JTJHA31U 940046786 - NOT idle after
harness replacement.
Ch A = M+ Ch B = VTA

Picture 5:
After wiring harness replacement. Note the absence of spikes on VTA and pattern on M+ compared to Pictures 3 and 4.

Attachment 1: PRCS

FIELD TECHNICAL REPORT



TQCN DOC# FTR-8FR318941	Affiliate TMS	Dept. QA-Powertrain	Source FTS	Location REG-LWA	Ref 23066-1	Date 7/8/2004
Problem Area Base Vehicle	Primary Model RX 330	Model Year 2004	Production Date 10-2003	Odometer 5143 mi	VIN (confirm 17 characters): JTJHA31U940 [REDACTED]	
Condition Title RPM Fluctuation at all RPMs, Worse at Idle. Wire Harness						

Attachment 1: Parts Recovery Control Sheet

Do not type in SHADED fields. If the **Final Destination** field below is "scrap", properly dispose of the part.

Orig Tracking

VIN

Doc No.



Final Destination: CQEC	SETR#:	CQE Eng:	N/A
--------------------------------	--------	----------	-----

Importer: (Applies to TMC Shipments Only) North America EDER Gr., Technical Dept. #1 Overseas Customer Service Technical Div. TOYOTA MOTOR CORPORATION Nisshin Education & Training Center 5-210, SAKAE, NISSHIN, AICH, 470-0113 Japan	Deliver to:	住所 :
	Attn:	宛先 :
	Tel:	TEL :

T-STAR		
--------	--	--

Note: If this FTR contains more than one VIN, create a table in the report containing VIN, production date, and odometer

		FOR CUSTOMS USE: Used Parts Value	
Part #	Part Description	Qty.	Used Part Value
1	822100E010 Comments:	1	\$ 0.00
2	 Comments:	0	\$ 0.00
3	 Comments:	0	\$ 0.00
4	 Comments:		\$.00
5	 Comments:		\$.00
6	 Comments:		\$.00
7	 Comments:		\$.00
8	 Comments:		\$.00

FIELD TECHNICAL REPORT

TQCN DOC# FTR-PW7120141A		Affiliate TMS	Dept. QA-Powertrain	Source PE	Location TMS	Ref 23177-1	Date 7/20/2004
Problem Area Base Vehicle	Primary Model Scion tC	Model Year 2005	Production Date 05/2004	Odometer 2491	VIN (confirm 17 characters): JTKDE167050 [REDACTED]		
Condition Title Performance Surge - When A/C engages							

Do not type in YELLOW shaded fields - Input data from Web page or RDM:

Repair Date	Optional Ref.	Optional Approval
-------------	---------------	-------------------

Condition Description

While driving at highway speeds (above 65 mph) when the A/C compressor engages there is a engine surge or bump that is felt through the floorboard at the drivers feet.

Diagnostic Steps:

While driving at highway speeds if the A/C button is turned on and off, when turned on you can feel the surge/bump.


Probable Cause

Unknown.

Part # 1: N/A	Part # 2:	Part # 3:	Parts Disposition: No part available	Parts Shipping Destination: N/A
------------------	-----------	-----------	---	------------------------------------

Repair Process

No repairs made. This FTR is being written to inform TMC of this condition.

	<p>A/C "ON"</p>
---	-----------------

Attachment 1: PRCS

FIELD TECHNICAL REPORT



TQCN DOC# FTR-PW7120141A		Affiliate TMS	Dept. QA-Powertrain	Source PE	Location TMS	Ref 23177-1	Date 7/20/2004
Problem Area Base Vehicle	Primary Model Scion tC	Model Year 2005	Production Date 05/2004	Odometer 2491	VIN (confirm 17 characters): JTKDE167050 [REDACTED]		
Condition Title Performance Surge - When A/C engages							

Attachment 1: Parts Recovery Control Sheet

Do not type in SHADED fields. If the **Final Destination** field below is "scrap", properly dispose of the part.

Orig Tracking

VIN

Doc No.



Final Destination: N/A	SETR#:	CQE Eng:	N/A
-------------------------------	--------	----------	-----

Importer: (Applies to TMC Shipments Only) North America EDER Gr., Technical Dept. #1 Overseas Customer Service Technical Div. TOYOTA MOTOR CORPORATION Nisshin Education & Training Center 5-210, SAKAE, NISSHIN, AICH, 470-0113 Japan	Deliver to:	住所 :
	Attn:	宛先 :
	Tel:	TEL :

T-STAR		
--------	--	--

Note: If this FTR contains more than one VIN, create a table in the report containing VIN, production date, and odometer

FOR CUSTOMS USE:
Used Parts Value

	Part # 1:	Part Description	Qty.	Used Part Value
1	N/A		1	\$ 0.00
	Comments:			
2			0	\$ 0.00
	Comments:			
3			0	\$ 0.00
	Comments:			
4				\$.00
	Comments:			
5				\$.00
	Comments:			
6				\$.00
	Comments:			
7				\$.00
	Comments:			
8				\$.00
	Comments:			

FIELD TECHNICAL REPORT



TQCN DOC# FTR-VRG122741		Affiliate TMS	Dept. QA-Powertrain	Source FPE	Location REG-LSA	Ref 13898-3	Date 8/16/2004
Problem Area Base Vehicle	Primary Model ES 300	Model Year 2002	Production Date 05-2002	Odometer 18869 mi	VIN (confirm 17 characters): JTHBF30G120 [REDACTED]		
Condition Title Hesitation on Reacceleration (Shift Schedule) After C/M							

Do not type in YELLOW shaded fields - Input data from Web page or RDM:

Repair Date 8/13/04	Optional Ref. 64201	Optional Approval
------------------------	------------------------	-------------------

Condition Description

Customer states when coasting or braking down to less than 15mph, then reaccelerating, a hesitation is felt before the vehicle begins to accelerate.

Note: TSIB TC004-03 was performed on this vehicle on 8/26/03

Customer has complained of shifting on the following repairs:

- 11/6/03 – Jerks when accelerating from a rolling stop
- 2/5/04 – Hesitation
- Present repair – Hesitation on reacceleration

Diagnostic Steps:

The vehicle was driven with the scan tool and a snapshot was taken while duplicating the condition. Only 9 items were selected in user data to maximize the update time of the scan tool. The snapshot was reviewed on Techview and revealed a **3.0 second delay** between when the accelerator pedal position sensor increased and vehicle speed increased (see picture below).

Probable Cause

Transmission / ECM logic concern

Part # 1: N/A	Part # 2:	Part # 3:	Parts Disposition: No part available	Parts Shipping Destination: N/A
------------------	-----------	-----------	---	------------------------------------


Repair Process

No repairs were performed; the vehicle is operating as designed.

FIELD TECHNICAL REPORT



TQCN DOC# FTR-VRG122741		Affiliate TMS	Dept. QA-Powertrain	Source FPE	Location REG-LSA	Ref 13898-3	Date 8/16/2004
Problem Area Base Vehicle	Primary Model ES 300	Model Year 2002	Production Date 05-2002	Odometer 18869 mi	VIN (confirm 17 characters): JTHBF30G120 [REDACTED]		
Condition Title Hesitation on Reacceleration (Shift Schedule) After C/M							



Picture of condition


 C:\Documents and Settings\hennesm\My
Techview file

Attachment 1: PRCS

FIELD TECHNICAL REPORT



TQCN DOC# FTR-VRG122741		Affiliate TMS	Dept. QA-Powertrain	Source FPE	Location REG-LSA	Ref 13898-3	Date 8/16/2004
Problem Area Base Vehicle	Primary Model ES 300	Model Year 2002	Production Date 05-2002	Odometer 18869 mi	VIN (confirm 17 characters): JTHBF30G120 [REDACTED]		
Condition Title Hesitation on Reacceleration (Shift Schedule) After C/M							

Attachment 1: Parts Recovery Control Sheet

Do not type in SHADED fields. If the **Final Destination** field below is "scrap", properly dispose of the part.

Orig Tracking

VIN

Doc No.



Final Destination: N/A		SETR#:	CQE Eng:	N/A
Importer: (Applies to TMC Shipments Only)		Deliver to:		住所:
North America EDER Gr., Technical Dept. #1 Overseas Customer Service Technical Div. TOYOTA MOTOR CORPORATION Nisshin Education & Training Center 5-210, SAKAE, NISSHIN, AICH, 470-0113 Japan		Attn:		宛先:
		Tel:		Tel:
T-STAR				
Note: If this FTR contains more than one VIN, create a table in the report containing VIN, production date, and odometer				FOR CUSTOMS USE: Used Parts Value
1	Part # 1:	Part Description	Qty.	Used Part Value
	N/A		0	\$ 0.00
Comments:				
2	Part # 2:	Part Description	Qty.	Used Part Value
			0	\$ 0.00
Comments:				
3	Part # 3:	Part Description	Qty.	Used Part Value
			0	\$ 0.00
Comments:				
4	Part # 4:	Part Description	Qty.	Used Part Value
				\$.00
Comments:				
5	Part # 5:	Part Description	Qty.	Used Part Value
				\$.00
Comments:				
6	Part # 6:	Part Description	Qty.	Used Part Value
				\$.00
Comments:				
7	Part # 7:	Part Description	Qty.	Used Part Value
				\$.00
Comments:				
8	Part # 8:	Part Description	Qty.	Used Part Value
				\$.00
Comments:				

DEALERSHIP PRODUCT REPORT



TQCN DOC# PR-63103-2174B	Affiliate TMS	Dept. QA-Powertrain	Source MDT/DS	Dealer Code 63103	Ref 23062-1	Date 8/23/2004
Dealer Name LEXUS OF SMITHTOWN		Dealer City ST. JAMES		State NY	Region LEA	
Primary Model RX 330	Model Year 2004	Production Date 10-MAR-04	Odometer 5231 mi	VIN 2T2HA31U04C [REDACTED]		
Condition Title Vehicle Jerks When Accelerating From a Stop (Shift Schedule)						

Repair Date 27-JUL-2004	Optional Ref.	Applicable DTC Code(s)
----------------------------	---------------	------------------------

Condition Description

Customer states vehicle jerks when accelerating after stop.

Diagnostic Steps:

Road tested vehicle.

Probable Cause

ECU logic.

Part # 1: 111111111111	Part # 2:	Part # 3:	Parts Available on Request: No part available	Parts Shipping Destination:
---------------------------	-----------	-----------	--	-----------------------------

Repair Process

none

DEALERSHIP PRODUCT REPORT



TQCN DOC# PR-63103-2174B	Affiliate TMS	Dept. QA-Powertrain	Source MDT/DS	Dealer Code 63103	Ref 23062-1	Date 8/23/2004
Dealer Name LEXUS OF SMITHTOWN		Dealer City ST. JAMES		State NY	Region LEA	
Primary Model RX 330	Model Year 2004	Production Date 10-MAR-04	Odometer 5231 mi	VIN 2T2HA31U04C [REDACTED]		
Condition Title Vehicle Jerks When Accelerating From a Stop (Shift Schedule)						

Attachment 1: Parts Recovery Control Sheet

Orig Tracking

VIN [REDACTED]

Doc No. [REDACTED]

Do not type in SHADED fields. If the Final Destination field below is "scrap", properly dispose of the part.



Final Destination:		SETR#:	CQE Eng:	N/A
Importer: (Applies to TMC Shipments Only)		Deliver to:	住所 :	
North America EDER Gr., Technical Dept. #1 Overseas Customer Service Technical Div. TOYOTA MOTOR CORPORATION Nisshin Education & Training Center 5-210, SAKAE, NISSHIN, AICH, 470-0113 Japan		Attn:	宛先 :	
		Tel:	Tel:	
T-STAR		[REDACTED]		[REDACTED]
Note: If this FTR contains more than one VIN, create a table in the report containing VIN, production date, and odometer				FOR CUSTOMS USE: Used Parts Value
1	Part # 1: 111111111111	Part Description	Qty. 1	Used Part Value \$ 0.00
	Comments:			
2	Part # 2:	Part Description	Qty. 0	Used Part Value \$ 0.00
	Comments:			
3	Part # 3:	Part Description	Qty. 0	Used Part Value \$ 0.00
	Comments:			
4	Part # 4:	Part Description	Qty. \$	Used Part Value .00
	Comments:			
5	Part # 5:	Part Description	Qty. \$	Used Part Value .00
	Comments:			
6	Part # 6:	Part Description	Qty. \$	Used Part Value .00
	Comments:			
7	Part # 7:	Part Description	Qty. \$	Used Part Value .00
	Comments:			

DEALERSHIP PRODUCT REPORT



TQCN DOC# PR-64107-2344B	Affiliate TMS	Dept. QA-Powertrain	Source MDT/DS	Dealer Code 64107	Ref 23708-1	Date 9/7/2004
Dealer Name LEXUS OF MEMPHIS		Dealer City MEMPHIS		State TN	Region LSA	
Primary Model ES 300	Model Year 2002	Production Date 22-JAN-02	Odometer 13733 mi	VIN JTHBF30G925 [REDACTED]		
Condition Title QA-Powertrain: Gas Pedal/Throttle/Floor Mat						

Repair Date 10-AUG-2004	Optional Ref.	Applicable DTC Code(s)
----------------------------	---------------	------------------------

Condition Description

Customer states vehicle accelerated on its own, stepping on brake pedal did not help in slowing it down. Customer was aware of the NHTSA investigation and refuses to drive vehicle.

Diagnostic Steps:

Simply opened driver's door to get in vehicle and immediately saw a possible cause. Then put scan tool on to be sure ECM did not see anything abnormal, no codes in history, pending or current. All data reading normal.



Probable Cause

Customer using a hard molded carpeted floor mat with a smooth rubber bottom, enabling it to slide easily back and forth thus easily covering gas pedal.


Part # 1: N/A	Part # 2:	Part # 3:	Parts Available on Request: No part available	Parts Shipping Destination:
------------------	-----------	-----------	--	-----------------------------

Repair Process

Spoke again with customer to see exactly when it occurred and customer stated that it happened on hard acceleration to pass someone. Also said engine shifted and sounded different, (transmission downshifted). By hand moved floor mat up to see just how it would interfere and it will interfere with accelerator pedal. Explained this to customer showing them the possibility and told them not to drive vehicle with that floor mat.




As shown in the picture the factory mat is still installed below aftermarket floor mat.



Aftermarket floor mat would slide forward and contact accelerator pedal. Pushing on brake pedal hard would cause floor mat to slide forward more.

DEALERSHIP PRODUCT REPORT



TQCN DOC# PR-64107-2344B	Affiliate TMS	Dept. QA-Powertrain	Source MDT/DS	Dealer Code 64107	Ref 23708-1	Date 9/7/2004
Dealer Name LEXUS OF MEMPHIS		Dealer City MEMPHIS		State TN	Region LSA	
Primary Model ES 300	Model Year 2002	Production Date 22-JAN-02	Odometer 13733 mi		VIN JTHBF30G925 [REDACTED]	
Condition Title QA-Powertrain: Gas Pedal/Throttle/Floor Mat						

Attachment 1: Parts Recovery Control Sheet

Do not type in SHADED fields. If the Final Destination field below is "scrap", properly dispose of the part.

Orig Tracking
VIN [REDACTED]
Doc No. [REDACTED]



Final Destination:		SETR#:	CQE Eng:	N/A
Importer: (Applies to TMC Shipments Only)		Deliver to:	住所 :	
North America EDER Gr., Technical Dept. #1 Overseas Customer Service Technical Div. TOYOTA MOTOR CORPORATION Nisshin Education & Training Center 5-210, SAKAE, NISSHIN, AICH, 470-0113 Japan		Attn:	宛先 :	
		Tel:	Tel:	
T-STAR		[Barcode]	[Barcode]	
Note: If this FTR contains more than one VIN, create a table in the report containing VIN, production date, and odometer				FOR CUSTOMS USE: Used Parts Value
1	Part # 1: N/A	Part Description	Qty. 0	Used Part Value \$ 0.00
	Comments:			
2	Part # 2:	Part Description	Qty. 0	Used Part Value \$ 0.00
	Comments:			
3	Part # 3:	Part Description	Qty. 0	Used Part Value \$ 0.00
	Comments:			
4	Part # 4:	Part Description	Qty. \$	Used Part Value .00
	Comments:			
5	Part # 5:	Part Description	Qty. \$	Used Part Value .00
	Comments:			
6	Part # 6:	Part Description	Qty. \$	Used Part Value .00
	Comments:			
7	Part # 7:	Part Description	Qty. \$	Used Part Value .00
	Comments:			

FIELD TECHNICAL REPORT

TQCN DOC# FTR-VQN134341		Affiliate TMS	Dept. QA-Powertrain	Source FPE	Location TMS-LA	Ref 24891-1	Date 12/9/2004
Problem Area Base Vehicle	Primary Model Tacoma	Model Year 2005	Production Date 01-Oct-2004	Odometer 2368 mi	VIN (confirm 17 characters): 5TENX62N25Z [REDACTED]		
Condition Title NON-LINEAR OFF-THROTTLE RESPONSE							

Do not type in YELLOW shaded fields - Input data from Web page or RDM:

Repair Date 08-DEC-2004	Optional Ref.	Optional Approval
----------------------------	---------------	-------------------

Condition Description

Customer complains engine RPM fluctuates or does not drop quickly when throttle is not applied (foot off of gas pedal).

- Customer states engine does RPM not decrease when clutch is disengaged (throttle released) during upshift.
- Customer states engine RPM may increase or decrease while the clutch is disengaged, and the throttle is released.
- Additional customer complaint describes a condition similar to an automatic transmission feeling during deceleration, where engine braking does not slow the vehicle while the throttle is released.

Diagnostic Steps:

FPE test-drove vehicle with the dealer technician.

- Customer complaint of insufficient off-throttle engine braking could not be confirmed.
- Customer complaint of non-linear response during off-throttle was duplicated and recorded in attached Techview file.
- Condition **can be duplicated** by accelerating full throttle (4th gear) to above 4000 RPM, then releasing throttle as clutch pedal is depressed and held down.
- Click on NOTES icon to read explanations of data, as recorded and annotated by FPE.

Probable Cause

Unidentified characteristic of the vehicle.

- No DTC's stored in memory, and no DTC's found in Codes History.
- Customer vehicle drivability and performance consistent with other '05 Tacomas equipped with 2TR engine.

Part # 1: N/A	Part # 2:	Part # 3:	Parts Disposition: No part available	Parts Shipping Destination: N/A
------------------	-----------	-----------	---	------------------------------------

Repair Process

No action taken at this time.



Double-click icon to access Techview file. Click on Notes icon (top of Techview window) to read explanations of driving samples.

FIELD TECHNICAL REPORT



TQCN DOC# FTR-717105551		Affiliate TMS	Dept. QA-Powertrain	Source FTS	Location TMS-NY	Ref 25816-1	Date 2/25/2005
Problem Area Base Vehicle	Primary Model Scion tC	Model Year 2005	Production Date 20-Sep-2004	Odometer 2910 mi	VIN (confirm 17 characters): JTKDE177750 [REDACTED]		
Condition Title Check engine light, engine speed surges/rough idle, DTC P0300, P0301, P0304							

Do not type in YELLOW shaded fields - Input data from Web page or RDM:

Repair Date 28-JAN-2005	Optional Ref.	Optional Approval
-----------------------------------	---------------	-------------------

Condition Description

Customer states that the check engine light is on, engine has rough idle & surges when driving.

Diagnostic Steps:

FTS verified customer concern. Retrieved diagnostic trouble codes P0300, P0301 & P0304 using diagnostic scan tool. Following checks were performed:

- Checked fuel quality & fuel pressure.
- Checked engine timing.
- Checked for any vacuum leaks.
- Compression test.
- Checked spark plugs & wires.
- Performed EFI & checked injectors.
- Checked connections from all vital sensors to the ECM.

All above tests passed. FTS performed test drive using diagnostic scan tool to monitor following data:

- Engine RPM.
- MAF, O2 & A/F sensors
- Long & short fuel trim

Upon test drive FTS found A/F sensor fluctuating between 1.9v & 4.9v when the concern happens. FTS unplugged the A/F sensor & drove vehicle, vehicle acted normally. FTS swapped in known good A/F sensor to verify repair, vehicle operated within manufacturer's specification.

Probable Cause

Failed A/F sensor.


Part # 1: 8946733080	Part # 2:	Part # 3:	Parts Disposition: Have part / will ship	Parts Shipping Destination: 2111
-------------------------	-----------	-----------	---	-------------------------------------

Repair Process



Advised technician to replace A/F sensor.

FIELD TECHNICAL REPORT

TQCN DOC# FTR-717105551	Affiliate TMS	Dept. QA-Powertrain	Source FTS	Location TMS-NY	Ref 25816-1	Date 2/25/2005
Problem Area Base Vehicle	Primary Model Scion tC	Model Year 2005	Production Date 20-Sep-2004	Odometer 2910 mi	VIN (confirm 17 characters): JTKDE177750 [REDACTED]	
Condition Title Check engine light, engine speed surges/rough idle, DTC P0300, P0301, P0304						



Information on A/F sensor:
89467-33080, DENSO0070, 09F07



Attachment 1: PRCS

FIELD TECHNICAL REPORT



TQCN DOC# FTR-717105551		Affiliate TMS	Dept. QA-Powertrain	Source FTS	Location TMS-NY	Ref 25816-1	Date 2/25/2005
Problem Area Base Vehicle	Primary Model Scion tC	Model Year 2005	Production Date 20-Sep-2004	Odometer 2910 mi	VIN (confirm 17 characters): JTKDE177750 [REDACTED]		
Condition Title Check engine light, engine speed surges/rough idle, DTC P0300, P0301, P0304							

Attachment 1: Parts Recovery Control Sheet

Do not type in SHADED fields. If the **Final Destination** field below is "scrap", properly dispose of the part.

Orig Tracking

VIN

Doc No.



Final Destination: 2111		SETR#:	CQE Eng:	N/A
Importer: (Applies to TMC Shipments Only)		Deliver to:		住所:
North America EDER Gr., Technical Dept. #1 Overseas Customer Service Technical Div. TOYOTA MOTOR CORPORATION Nisshin Education & Training Center 5-210, SAKAE, NISSHIN, AICH, 470-0113 Japan		Attn:		宛先:
		Tel:		TEL:
T-STAR				
Note: If this FTR contains more than one VIN, create a table in the report containing VIN, production date, and odometer				FOR CUSTOMS USE: Used Parts Value
1	Part # 1:	Part Description	Qty.	Used Part Value
	8946733080	SENSOR, AIR FUEL RATIO	1	\$ 30.00
Comments:				
2	Part # 2:	Part Description	Qty.	Used Part Value
			0	\$ 0.00
Comments:				
3	Part # 3:	Part Description	Qty.	Used Part Value
			0	\$ 0.00
Comments:				
4	Part # 4:	Part Description	Qty.	Used Part Value
				\$.00
Comments:				
5	Part # 5:	Part Description	Qty.	Used Part Value
				\$.00
Comments:				
6	Part # 6:	Part Description	Qty.	Used Part Value
				\$.00
Comments:				
7	Part # 7:	Part Description	Qty.	Used Part Value
				\$.00
Comments:				
8	Part # 8:	Part Description	Qty.	Used Part Value
				\$.00
Comments:				

DEALERSHIP PRODUCT REPORT



TQCN DOC# PR-61205-0735	Affiliate TMS	Dept. QA-Powertrain	Source MDT/DS	Dealer Code 61205	Ref 26112-1	Date 3/15/2005
Dealer Name LEXUS OF HIGHLAND PARK		Dealer City HIGHLAND PARK		State IL	Region LCA	
Primary Model LS 430	Model Year 2005	Production Date 10-NOV-04	Odometer 1098 mi	VIN JTHBN36F855 [REDACTED]		
Condition Title QA-Powertrain: Automatic Transmission						

Repair Date 03-MAR-2005	Optional Ref.	Applicable DTC Code(s)
-----------------------------------	---------------	------------------------

Condition Description

THERE IS A DELAY WHEN SHIFTING FROM REVERSE TO DRIVE, THEN SHORTLY AFTER THAT YOU'LL FEEL IT ENGAGE WITH A LITTLE JERKING.

Diagnostic Steps:

DID A PRESSURE TEST WITH THE TRANSMISSION PRESSURE GAGE. STALL TEST IN DRIVE WAS 60 PSI. STALL TEST IN REVERSE WAS 95 PSI. BOTH TESTS AT IDLE. STALL TEST IN DRIVE WAS 130 PSI. STALL IN REVERSE WAS 230 PSI. WITH FOOT ON BRAKE, IDLE SPEED YOU COULD SEE ON THE GAGE A DELAY IN PRESSURE FROM REVERSE TO DRIVE AND DRIVE TO REVERSE.


Probable Cause

INTERNAL LEAK DOWN IN TRANSMISSION.

Part # 1: 3500050150	Part # 2: 3200050040	Part # 3:	Parts Available on Request: Yes	Parts Shipping Destination: CQEC
-------------------------	-------------------------	-----------	------------------------------------	-------------------------------------

Repair Process

REPLACE TRANSMISSION ASSEMBLY AND TORQUE CONVERTER



DEALERSHIP PRODUCT REPORT



TQCN DOC# PR-61205-0735	Affiliate TMS	Dept. QA-Powertrain	Source MDT/DS	Dealer Code 61205	Ref 26112-1	Date 3/15/2005
Dealer Name LEXUS OF HIGHLAND PARK		Dealer City HIGHLAND PARK		State IL	Region LCA	
Primary Model LS 430	Model Year 2005	Production Date 10-NOV-04	Odometer 1098 mi	VIN JTHBN36F855 [REDACTED]		
Condition Title QA-Powertrain: Automatic Transmission						

Attachment 1: Parts Recovery Control Sheet

Orig Tracking
VIN [REDACTED]
Doc No. [REDACTED]

Do not type in SHADED fields. If the Final Destination field below is "scrap", properly dispose of the part.



Final Destination: CQEC		SETR#:	CQE Eng:	N/A
Importer: (Applies to TMC Shipments Only)		Deliver to:	住所 :	
North America EDER Gr., Technical Dept. #1 Overseas Customer Service Technical Div. TOYOTA MOTOR CORPORATION Nisshin Education & Training Center 5-210, SAKAE, NISSHIN, AICH, 470-0113 Japan		Attn:	宛先 :	
		Tel:	Tel:	
T-STAR				
Note: If this FTR contains more than one VIN, create a table in the report containing VIN, production date, and odometer				FOR CUSTOMS USE: Used Parts Value
1	Part # 1: 3500050150 Comments:	Part Description TRANSMISSION ASSY	Qty. 1	Used Part Value \$ 834 .00
2	Part # 2: 3200050040 Comments:	Part Description CONVERTER ASSY, TORQUE	Qty. 1	Used Part Value \$ 143 .00
3	Part # 3: Comments:	Part Description	Qty. 0	Used Part Value \$ 0 .00
4	Part # 4: Comments:	Part Description	Qty. \$	Used Part Value .00
5	Part # 5: Comments:	Part Description	Qty. \$	Used Part Value .00
6	Part # 6: Comments:	Part Description	Qty. \$	Used Part Value .00
7	Part # 7: Comments:	Part Description	Qty. \$	Used Part Value .00

TQCN DOC# PR61205-0735	系列会社 TMS	部 QA パワートレ	出所 MDT/D	ディーラー・コード 61205	参考 26112-1	日付 3/15/2005
ディーラー名 ハイランドパークの LEXUS	ディーラー都市 ハイランドパーク	州 IL	地域 LCA			
主要なモデル LS 430	モデルイヤ 2005	生産日 10-11 月-04	オドメータ 1098 の mi	VIN JTHBN36F855	[REDACTED]	
状態タイトル QA パワートレイン: オートマチックトランスミッション						

修理期日 03-3 月-2005	オプションの Ref	適用可能な DTC コード
----------------------------	------------	---------------

状態記述

その直後にリバースからドライブのギアをその後入れる場合、遅れが出ています、感じるでしょう、IT、小さなジャーキングで従事します。

診断のステップ:

T/M 圧力計を備えた圧力試験を行いました。駆動中のスト-ル・テストは 60P.S.I.でした。スト-ル・テストは逆に 95P.S.I.でした。アイドルの両方のテスト。駆動中のスト-ル・テストは 130P.S.I.でした。スト-ルは逆に 230P.S.I.でした。ブレーキ上の足で、ゲージ上で見ることができるアイドル・スピード、運転するべきリバースおよびドライブからリバースまでの圧力の遅れ。


考えられる原因

IN T/M を下った内部漏れ。

部分 1 番: 3500050150	部分 2 番: 3200050040	部分 3 番:	要求のあり次第利 用可能な部品: はい	部品を発送目的地: CQEC
-----------------------	-----------------------	---------	---------------------------	-------------------

修理処理

T/M アッセンブリとトルクコンバータを交換します



TQCN DOC# PR61205-0735	系列会社 TMS	部 QA パワートレ	出所 MDT/D	ディーラー・コード 61205	参考 26112-1	日付 3/15/2005
ディーラー名 ハイランドパークの LEXUS	ディーラー都市 ハイランドパーク	州 IL	地域 LCA			
主要なモデル LS 430	モデルイヤ 2005	生産日 10-11 月-04	オドメータ 1098 の mi	VIN JTHBN36F855		
状態タイトル QA パワートレイン: オートマチックトランスミッション						

アタッチメント 1: 部品回収統制図

Orig ト
ラッキング
グ

VIN

doc No.

SHADED フィールドをタイプインしないでください。下記の最終仕向地フィールドが「切れ端」である場合は、適切にその部分を処分してください。



最終仕向地: CQEC	SETR#:	CQE E/G:	N/A
輸入業者: (TMC出荷だけに当てはまります)	次のものに伝えます:	住所:	
北アメリカEDER Gr、技術的な部#1 海外の顧客サービスの技術的な部 トヨタ自動車CORPORATION Nisshin教育&トレーニング・センター 5-210、SAKAE、NISSHIN、AICH、470-0113 日本	Attn: 電話番号:	宛先: 電話番号:	
T星			
このFTRが1つを越えるVINを含んでいる場合、注釈、VIN、生産日およびオドメータを含んでいる報告の中でテーブルを作成する。			関税使用のために: 使用された部品価値
1	部分 1 番: 3500050150	部分記述 T/M ASSY	量。 1 \$ 834 .00
	コメント:		
2	部分 2 番: 3200050040	部分記述 コンバータ ASSY、トルク	量。 1 \$ 143 .00
	コメント:		
3	部分 3 番:	部分記述	量。 0 \$ 0 .00
	コメント:		
4	部分 4 番:	部分記述	量。 \$.00
	コメント:		
5	部分 5 番:	部分記述	量。 \$.00
	コメント:		
	部分 6 番:	部分記述	量。 使用された部分価値

TQCN DOC# PR61205-0735	系列会社 TMS	部 QA パワートレ	出所 MDT/D	ディーラー・コード 61205	参考 26112-1	日付 3/15/2005
ディーラー名 ハイランドパークの LEXUS	ディーラー都市 ハイランドパーク	州 IL	地域 LCA			
主要なモデル LS 430	モデルイヤ 2005	生産日 10-11 月-04	オドメータ 1098 の mi	VIN JTHBN36F855		
状態タイトル QA パワートレイン: オートマチックトランスミッション						

	部分 6 番:	部分記述	量。	使用された部分価値
6	コメント:			\$.00
	部分 7 番:	部分記述	量。	\$.00
	コメント:			

FIELD TECHNICAL REPORT



TQCN DOC# FTR-JFK107551		Affiliate TMS	Dept. QA-Powertrain	Source FTS	Location TMS-CAT	Ref 26189-1	Date 3/18/2005
Problem Area Base Vehicle	Primary Model Camry	Model Year 2005	Production Date 13-Jan-2005	Odometer 830 mi	VIN (confirm 17 characters): 4T1BE30K35U [REDACTED]		
Condition Title Surge under light throttle							

Do not type in YELLOW shaded fields - Input data from Web page or RDM:

Repair Date 15-MAR-2005	Optional Ref.	Optional Approval
-----------------------------------	---------------	-------------------

Condition Description

Engine surge under light throttle cruise.

Diagnostic Steps:

View engine data list on the scan tool while condition is present. Using active test I locked the A/F sensor value and the condition was eliminated.


Probable Cause

Incorrect signal from B1S1

Part # 1: 8946706030	Part # 2:	Part # 3:	Parts Disposition: Have part / will ship	Parts Shipping Destination: 2111
-------------------------	-----------	-----------	---	-------------------------------------

Repair Process

No replacement part was available, swap part from known good vehicle to confirm repair and order replacement part.
Part # from A/F sensor 89467-06030 Build date 12F03
Part is not ready for recovery until replacement part is received.

 05 be3.evn	Tech view file of event

FIELD TECHNICAL REPORT



TQCN DOC# FTR-JFK107551		Affiliate TMS	Dept. QA-Powertrain	Source FTS	Location TMS-CAT	Ref 26189-1	Date 3/18/2005
Problem Area Base Vehicle	Primary Model Camry	Model Year 2005	Production Date 13-Jan-2005	Odometer 830 mi	VIN (confirm 17 characters): 4T1BE30K35U [REDACTED]		
Condition Title Surge under light throttle							

Attachment 1: PRCS

Attachment 1: Parts Recovery Control Sheet

Do not type in SHADED fields. If the **Final Destination** field below is "scrap", properly dispose of the part.

Orig Tracking
VIN [REDACTED]
Doc No. [REDACTED]



Final Destination: 2111	SETR#:	CQE Eng:	N/A
Importer: (Applies to TMC Shipments Only) Mr. N. Okumura, Chief Expert Quality Div. Warranty Parts Room TOYOTA MOTOR CORPORATION 1 Toyota, Toyota-city, Aichi, 471-8571 Japan	Deliver to: Attn: Tel:	住所: 宛先: Tel:	

T-STAR



Note: If this FTR contains more than one VIN, create a table in the report containing VIN, production date, and odometer

FOR CUSTOMS USE:
Used Parts Value

	Part # 1:	Part Description	Qty.	Used Part Value
1	8946706030	SENSOR, AIR FUEL RATIO	1	\$ 30.00
	Comments:			
2	Part # 2:	Part Description	Qty.	Used Part Value
			0	\$ 0.00
	Comments:			
3	Part # 3:	Part Description	Qty.	Used Part Value
			0	\$ 0.00
	Comments:			
4	Part # 4:	Part Description	Qty.	Used Part Value
				\$.00
	Comments:			
5	Part # 5:	Part Description	Qty.	Used Part Value
				\$.00
	Comments:			
6	Part # 6:	Part Description	Qty.	Used Part Value
				\$.00
	Comments:			
7	Part # 7:	Part Description	Qty.	Used Part Value
				\$.00
	Comments:			
8	Part # 8:	Part Description	Qty.	Used Part Value
				\$.00
	Comments:			

FIELD TECHNICAL REPORT

TQCN DOC# FTR-JFK107551	Affiliate TMS	Dept. QA-Powertrain	Source FTS	Location TMS-CAT	Ref 26189-1	Date 3/18/2005
Problem Area Base Vehicle	Primary Model Camry	Model Year 2005	Production Date 13-Jan-2005	Odometer 830 mi	VIN (confirm 17 characters): 4T1BE30K35U [REDACTED]	
Condition Title Surge under light throttle						

FIELD TECHNICAL REPORT

TQCN DOC# FTR-PEN111751F		Affiliate TMS	Dept. QA-Powertrain	Source PE	Location TMS	Ref 26741-1	Date 4/27/2005
Problem Area Base Vehicle	Primary Model Tacoma	Model Year 2005	Production Date 01/05	Odometer 2040	VIN (confirm 17 characters): 5TEUX42N25Z [REDACTED]		
Condition Title Manual Transmission Rear Seal Leak							

Do not type in YELLOW shaded fields - Input data from Web page or RDM:

Repair Date	Optional Ref.	Optional Approval
-------------	---------------	-------------------

Condition Description

The customer complained that the vehicle would buck while driving and at the same time hear a high pitch whining noise.

Diagnostic Steps:

Technician confirmed customer complaint and isolated noise to manual transmission assembly. Technician checked fluid level and confirmed fluid level to be very low. Continued examining and confirmed that rear transmission extension housing seal was leaking fluid into extension housing and collecting between transfer case and transmission assembly.



Probable Cause

Seal damage

Part # 1: 3303035A50	Part # 2:	Part # 3:	Parts Disposition: Have part / will ship	Parts Shipping Destination: CQEC
-------------------------	-----------	-----------	---	-------------------------------------

Repair Process

Technician replaced transmission assembly (P/N 33030-35A50) to repair vehicle.

	
<p>Transmission Assy (P/N 33030-35A50)</p>	<p>Transmission Serial Number R4Z01076</p>

Attachment 1: PRCS

FIELD TECHNICAL REPORT



TQCN DOC# FTR-PEN111751F		Affiliate TMS	Dept. QA-Powertrain	Source PE	Location TMS	Ref 26741-1	Date 4/27/2005
Problem Area Base Vehicle	Primary Model Tacoma	Model Year 2005	Production Date 01/05	Odometer 2040	VIN (confirm 17 characters): 5TEUX42N25Z [REDACTED]		
Condition Title Manual Transmission Rear Seal Leak							

Attachment 1: Parts Recovery Control Sheet

Orig Tracking
VIN
Doc No.

Do not type in SHADED fields. If the **Final Destination** field below is "scrap", properly dispose of the part.

Final Destination: CQEC		SETR#:	CQE Eng:	N/A
Importer: (Applies to TMC Shipments Only)		Deliver to:		住所 :
Mr. N. Okumura, Chief Expert Quality Div. Warranty Parts Room TOYOTA MOTOR CORPORATION 1 Toyota, Toyota-city, Aichi, 471-8571 Japan		Attn:		宛先 :
		Tel:		TEL :
T-STAR				
Note: If this FTR contains more than one VIN, create a table in the report containing VIN, production date, and odometer				FOR CUSTOMS USE: Used Parts Value
1	Part # 1:	Part Description	Qty.	Used Part Value
	3303035A50	TRANSMISSION UNIT ASSY	1	\$ 309 .00
Comments:				
2	Part # 2:	Part Description	Qty.	Used Part Value
			0	\$ 0 .00
Comments:				
3	Part # 3:	Part Description	Qty.	Used Part Value
			0	\$ 0 .00
Comments:				
4	Part # 4:	Part Description	Qty.	Used Part Value
				\$.00
Comments:				
5	Part # 5:	Part Description	Qty.	Used Part Value
				\$.00
Comments:				
6	Part # 6:	Part Description	Qty.	Used Part Value
				\$.00
Comments:				
7	Part # 7:	Part Description	Qty.	Used Part Value
				\$.00
Comments:				
8	Part # 8:	Part Description	Qty.	Used Part Value
				\$.00
Comments:				

FIELD TECHNICAL REPORT



TQCN DOC# FTR-JAK118851		Affiliate TMS	Dept. QA-Powertrain	Source FTS	Location TMS-BOS	Ref 24078-1	Date 7/9/2005
Problem Area Base Vehicle	Primary Model Camry	Model Year 2004	Production Date 26-Nov-2003	Odometer 22682 mi	VIN (confirm 17 characters): 4T1BF32K74U [REDACTED]		
Condition Title 04 Camry 1MZ-FE engine surge. B1S1 A/F no DTCs							

Do not type in YELLOW shaded fields - Input data from Web page or RDM:

Repair Date 23-JUN-2005	Optional Ref.	Optional Approval
-----------------------------------	---------------	-------------------

Condition Description

Customer stated the vehicle surges intermittently and at intermittent speeds.

Diagnostic Steps:

- FTS inspected this vehicle and confirmed the condition during a test drive with the customer.
- The condition occurred under load while accelerating. The condition was most noticeable at speeds up to ~ 35 MPH. The condition was not present at cruise.
- FTS found the B1S1 Air Fuel Ratio Sensor voltage fluctuating rapidly while the condition occurred (review attached TV file).
- FTS inspected this vehicle's ECM for DTCs with none stored.
- FTS disconnected the B1S1 A/F Sensor which put the vehicle in limp mode and found the condition no longer occurred.
- FTS inspected the wiring associated with the B1S1 A/F Sensor. All inspected wiring and components were found operating as designed.

Probable Cause

B1S1 Air Fuel Ratio Sensor.

Part # 1: 8946733060	Part # 2:	Part # 3:	Parts Disposition: Have part / will ship	Parts Shipping Destination: CQEC
-------------------------	-----------	-----------	---	-------------------------------------

Repair Process

FTS replaced the B1S1 Air Fuel Ratio Sensor.


 [REDACTED] 04 Camry.evn
 TV file with Ram data

Attachment 1: PRCS



FIELD TECHNICAL REPORT



TQCN DOC# FTR-JAK118851		Affiliate TMS	Dept. QA-Powertrain	Source FTS	Location TMS-BOS	Ref 24078-1	Date 7/9/2005
Problem Area Base Vehicle	Primary Model Camry	Model Year 2004	Production Date 26-Nov-2003	Odometer 22682 mi	VIN (confirm 17 characters): 4T1BF32K74U [REDACTED]		
Condition Title 04 Camry 1MZ-FE engine surge. B1S1 A/F no DTCs							

Attachment 1: Parts Recovery Control Sheet

Do not type in SHADED fields. If the **Final Destination** field below is "scrap", properly dispose of the part.

Orig Tracking 
 VIN [REDACTED]
 Doc No. 

Final Destination: CQEC	SETR#:	CQE Eng:	N/A
Importer: (Applies to TMC Shipments Only) North America EDER Gr., Technical Dept. #1 Overseas Customer Service Technical Div. TOYOTA MOTOR CORPORATION Nisshin Education & Training Center 5-210, SAKAE, NISSHIN, AICH, 470-0113 Japan	Deliver to: Attn: Tel:	住所 : 宛先 : Tel:	

T-STAR		
--------	---	---

Note: If this FTR contains more than one VIN, create a table in the report containing VIN, production date, and odometer

			FOR CUSTOMS USE: Used Parts Value	
Part #	Part Description	Qty.	Used Part Value	
1	Part # 1: 8946733060 Comments:	1	\$ 34	.00
2	Part # 2: Comments:	0	\$ 0	.00
3	Part # 3: Comments:	0	\$ 0	.00
4	Part # 4: Comments:		\$.00
5	Part # 5: Comments:		\$.00
6	Part # 6: Comments:		\$.00
7	Part # 7: Comments:		\$.00
8	Part # 8: Comments:		\$.00

DEALERSHIP PRODUCT REPORT



TQCN DOC# PR-62904-3085	Affiliate TMS	Dept. QA-Powertrain	Source MDT/DS	Dealer Code 62904	Ref 23794-2	Date 11/7/2005
Dealer Name LEXUS OF ENGLEWOOD		Dealer City ENGLEWOOD		State NJ	Region LEA	
Primary Model ES 330	Model Year 2005	Production Date 08-APR-05	Odometer 6701 mi	VIN JTHBA30G955 [REDACTED]		
Condition Title Jerk Feeling When Accelerating						

Repair Date 11-NOV-2005	Optional Ref.	Applicable DTC Code(s)
----------------------------	---------------	------------------------

Condition Description

When accelerating there is a jerk feeling when accelerating from a stop.

Diagnostic Steps:

Checked current ID numbers; up-to-date (33360200,53340100).

Probable Cause


Not known

Part # 1: 0000000000	Part # 2:	Part # 3:	Parts Available on Request: No part available	Parts Shipping Destination: CQEC
-------------------------	-----------	-----------	--	-------------------------------------

Repair Process

No repair done.

DEALERSHIP PRODUCT REPORT



TQCN DOC# PR-62904-3085	Affiliate TMS	Dept. QA-Powertrain	Source MDT/DS	Dealer Code 62904	Ref 23794-2	Date 11/7/2005
Dealer Name LEXUS OF ENGLEWOOD		Dealer City ENGLEWOOD		State NJ	Region LEA	
Primary Model ES 330	Model Year 2005	Production Date 08-APR-05	Odometer 6701 mi	VIN JTHBA30G955 [REDACTED]		
Condition Title Jerk Feeling When Accelerating						

Attachment 1: Parts Recovery Control Sheet

Do not type in SHADED fields. If the Final Destination field below is "scrap", properly dispose of the part.

Orig Tracking
VIN [REDACTED]
Doc No. [REDACTED]



Final Destination: CQEC		SETR#:	CQE Eng:	N/A
Importer: (Applies to TMC Shipments Only)		Deliver to:	住所 :	
North America EDER Gr., Technical Dept. #1 Overseas Customer Service Technical Div. TOYOTA MOTOR CORPORATION Nisshin Education & Training Center 5-210, SAKAE, NISSHIN, AICH, 470-0113 Japan		Attn:	宛先 :	
		Tel:	Tel:	
T-STAR				
Note: If this FTR contains more than one VIN, create a table in the report containing VIN, production date, and odometer				FOR CUSTOMS USE: Used Parts Value
1	Part # 1: 0000000000	Part Description	Qty. 0	Used Part Value \$ 0.00
	Comments:			
2	Part # 2:	Part Description	Qty. 0	Used Part Value \$ 0.00
	Comments:			
3	Part # 3:	Part Description	Qty. 0	Used Part Value \$ 0.00
	Comments:			
4	Part # 4:	Part Description	Qty. \$	Used Part Value .00
	Comments:			
5	Part # 5:	Part Description	Qty. \$	Used Part Value .00
	Comments:			
6	Part # 6:	Part Description	Qty. \$	Used Part Value .00
	Comments:			
7	Part # 7:	Part Description	Qty. \$	Used Part Value .00
	Comments:			

DEALERSHIP PRODUCT REPORT



TQCN DOC# PR-64530-0096	Affiliate TMS	Dept. QA-Powertrain	Source MDT/DS	Dealer Code 64530	Ref 29585-2	Date 1/17/2006
Dealer Name CH BARKER'S LX/NWPRT NEWPORT NEWS		Dealer City NEWPORT NEWS		State VA	Region LEA	
Primary Model RX 330	Model Year 2005	Production Date 20-OCT-04	Odometer 15353 mi	VIN 2T2GA31U85C [REDACTED]		
Condition Title Jerking When Accelerating						

Repair Date 09-JAN-2006	Optional Ref.	Applicable DTC Code(s)
----------------------------	---------------	------------------------

Condition Description

Customer states "still jerking when accelerating"

Diagnostic Steps:

Test drive. Transmission hunts for the proper gear at low speeds when on and off the accelerator.


Probable Cause

Part # 1: 8966148470	Part # 2:	Part # 3:	Parts Available on Request: No part available	Parts Shipping Destination: CQEC

Repair Process

No repairs were made. ECU Cals: 34872000 54826000

DEALERSHIP PRODUCT REPORT



TQCN DOC# PR-64530-0096	Affiliate TMS	Dept. QA-Powertrain	Source MDT/DS	Dealer Code 64530	Ref 29585-2	Date 1/17/2006
Dealer Name CH BARKER'S LX/NWPRT		Dealer City NEWPORT NEWS		State VA	Region LEA	
Primary Model RX 330	Model Year 2005	Production Date 20-OCT-04	Odometer 15353 mi	VIN 2T2GA31U85C [REDACTED]		
Condition Title Jerking When Accelerating						

Attachment 1: Parts Recovery Control Sheet

Do not type in SHADED fields. If the Final Destination field below is "scrap", properly dispose of the part.

Orig Tracking
VIN [REDACTED]
Doc No. [REDACTED]



Final Destination: CQEC		SETR#:	CQE Eng:	N/A
Importer: (Applies to TMC Shipments Only)		Deliver to:	住所 :	
North America EDER Gr., Technical Dept. #1 Overseas Customer Service Technical Div. TOYOTA MOTOR CORPORATION Nisshin Education & Training Center 5-210, SAKAE, NISSHIN, AICH, 470-0113 Japan		Attn:	宛先 :	
		Tel:	Tel:	
T-STAR		[Barcode]	[Barcode]	
Note: If this FTR contains more than one VIN, create a table in the report containing VIN, production date, and odometer				FOR CUSTOMS USE: Used Parts Value
1	Part # 1: 8966148470	Part Description COMPUTER, ENGINE CONTROL	Qty. 1	Used Part Value \$ 213.00
	Comments:			
2	Part # 2:	Part Description	Qty. 0	Used Part Value \$ 0.00
	Comments:			
3	Part # 3:	Part Description	Qty. 0	Used Part Value \$ 0.00
	Comments:			
4	Part # 4:	Part Description	Qty. \$	Used Part Value .00
	Comments:			
5	Part # 5:	Part Description	Qty. \$	Used Part Value .00
	Comments:			
6	Part # 6:	Part Description	Qty. \$	Used Part Value .00
	Comments:			
7	Part # 7:	Part Description	Qty. \$	Used Part Value .00
	Comments:			

FIELD TECHNICAL REPORT



TQCN DOC# FTR-VEV101861		Affiliate TMS	Dept. QA-Powertrain	Source FPE	Location TMS-NY	Ref 30995-1	Date 1/18/2006
Problem Area Base Vehicle	Primary Model RAV4	Model Year 2005	Production Date 21-Oct-2005	Odometer 64 mi	VIN (confirm 17 characters): JTEHD20V150 [REDACTED]		
Condition Title RAV4 vehicle surges during acceleration							

Do not type in YELLOW shaded fields - Input data from Web page or RDM:

Repair Date 18-JAN-2006	Optional Ref.	Optional Approval
-----------------------------------	---------------	-------------------

Condition Description

Customer states car surges during acceleration.

Diagnostic Steps:

Technician verified the customer's complaint and took two snapshots during event. The manual trigger was set to 15 seconds (30 sec total). Trigger was hit as soon as surge started. There were no MILs in Pending or History. Mil was off.
Because tech had seen this issue before in previous models, and car has no EGR valve, tech disconnected AF sensor and road tested. Surge was gone. Tech replaced A/F sensor.

Probable Cause

Unknown

Part # 1: 8946742040	Part # 2:	Part # 3:	Parts Disposition: Have part / will ship	Parts Shipping Destination: CQEC
-------------------------	-----------	-----------	---	-------------------------------------

Repair Process

The technician replaced the AF sensor PN 89467-42040 to remedy the condition
Part was shipped UPS for quality evaluation purposes to TMS UPS tracking #
1Z 4X4 15X 06 2165 517 9



Vehicle info.

FIELD TECHNICAL REPORT

TQCN DOC# FTR-VEV101861		Affiliate TMS	Dept. QA-Powertrain	Source FPE	Location TMS-NY	Ref 30995-1	Date 1/18/2006
Problem Area Base Vehicle	Primary Model RAV4	Model Year 2005	Production Date 21-Oct-2005	Odometer 64 mi	VIN (confirm 17 characters): JTEHD20V150 [REDACTED]		
Condition Title RAV4 vehicle surges during acceleration							



Techview file with RAM 7, monitor info and snapshots of event.



Code on AF Sensor is '10G17'

Attachment 1: PRCS

FIELD TECHNICAL REPORT



TQCN DOC# FTR-VEV101861		Affiliate TMS	Dept. QA-Powertrain	Source FPE	Location TMS-NY	Ref 30995-1	Date 1/18/2006
Problem Area Base Vehicle	Primary Model RAV4	Model Year 2005	Production Date 21-Oct-2005	Odometer 64 mi	VIN (confirm 17 characters): JTEHD20V150 [REDACTED]		
Condition Title RAV4 vehicle surges during acceleration							

Attachment 1: Parts Recovery Control Sheet

Do not type in SHADED fields. If the **Final Destination** field below is "scrap", properly dispose of the part.

Orig Tracking

VIN

Doc No.



Final Destination: CQEC	SETR#:	CQE Eng:	N/A
--------------------------------	--------	----------	-----

Importer: (Applies to TMC Shipments Only) Mr. N. Okumura, Chief Expert Quality Div. Warranty Parts Room TOYOTA MOTOR CORPORATION 1 Toyota, Toyota-city, Aichi, 471-8571 Japan	Deliver to:	住所:
	Attn:	宛先:
	Tel:	TEL:

T-STAR		
--------	--	--

Note: If this FTR contains more than one VIN, create a table in the report containing VIN, production date, and odometer

FOR CUSTOMS USE:
Used Parts Value

	Part #	Part Description	Qty.	Used Part Value
1	8946742040	SENSOR, AIR FUEL RATIO	1	\$ 30.00
	Comments:			
2			0	\$ 0.00
	Comments:			
3			0	\$ 0.00
	Comments:			
4				\$.00
	Comments:			
5				\$.00
	Comments:			
6				\$.00
	Comments:			
7				\$.00
	Comments:			
8				\$.00
	Comments:			

FIELD TECHNICAL REPORT

TQCN DOC# FTR-7LN109561		Affiliate TMS	Dept. QA-Powertrain	Source FTS	Location TMS-KC	Ref 32485-1	Date 4/6/2006
Problem Area Base Vehicle	Primary Model Tacoma	Model Year 2005	Production Date 18-Aug-2005	Odometer 3796 mi	VIN (confirm 17 characters): 5TETX22N05Z [REDACTED]		
Condition Title Fast idle hunt/surge after cold start							

Do not type in YELLOW shaded fields - Input data from Web page or RDM:

Repair Date 05-APR-2006	Optional Ref.	Optional Approval
-----------------------------------	---------------	-------------------

Condition Description

Customer complaining of an intermittent hunting/surging fast idle after a cold start.

Diagnostic Steps:

- Technician has verified the customer’s concern. Hard to duplicate unless the ambient temperature is just right and the technician believes that the condition is more prevalent in cooler ambient temperatures.
- The technician describes the condition as the engine acting like it is going into fuel cut because the idle is too high.
- After the engine acts like the fuel has been cut the RPM immediately rebounds back to a fast idle RPM.
- This idle RPM fluctuation may only occur once (as in the attached Techview file) or it may occur several times in succession.
- The technician replaced the Engine ECM at the recommendation of a TAS engineer (TA060860259) but to no avail.


Probable Cause

Unknown at this time.

Part # 1: N/A	Part # 2:	Part # 3:	Parts Disposition: No part available	Parts Shipping Destination: N/A
------------------	-----------	-----------	---	------------------------------------

Repair Process

No successful repairs have been made to this vehicle. Customer very upset with condition. Writer is waiting for revised ECM logic to address situation.



Taco cold start.zip

FIELD TECHNICAL REPORT



TQCN DOC# FTR-7LN109561	Affiliate TMS	Dept. QA-Powertrain	Source FTS	Location TMS-KC	Ref 32485-1	Date 4/6/2006
Problem Area Base Vehicle	Primary Model Tacoma	Model Year 2005	Production Date 18-Aug-2005	Odometer 3796 mi	VIN (confirm 17 characters): 5TETX22N05Z [REDACTED]	
Condition Title Fast idle hunt/surge after cold start						

Attachment 1: PRCS

FIELD TECHNICAL REPORT



TQCN DOC# FTR-7LN109561		Affiliate TMS	Dept. QA-Powertrain	Source FTS	Location TMS-KC	Ref 32485-1	Date 4/6/2006
Problem Area Base Vehicle	Primary Model Tacoma	Model Year 2005	Production Date 18-Aug-2005	Odometer 3796 mi	VIN (confirm 17 characters): 5TETX22N05Z [REDACTED]		
Condition Title Fast idle hunt/surge after cold start							

Attachment 1: Parts Recovery Control Sheet

Do not type in SHADED fields. If the **Final Destination** field below is "scrap", properly dispose of the part.

Orig Tracking

VIN

Doc No.



Final Destination: N/A	SETR#:	CQE Eng:	N/A
-------------------------------	--------	----------	-----

Importer: (Applies to TMC Shipments Only) Mr. N. Okumura, Chief Expert Quality Div. Warranty Parts Room TOYOTA MOTOR CORPORATION 1 Toyota, Toyota-city, Aichi, 471-8571 Japan	Deliver to:	住所 :
	Attn:	宛先 :
	Tel:	TEL :

T-STAR		
--------	--	--

Note: If this FTR contains more than one VIN, create a table in the report containing VIN, production date, and odometer

FOR CUSTOMS USE:
Used Parts Value

	Part # 1:	Part Description	Qty.	Used Part Value
1	N/A		0	\$ 0.00
	Comments:			
2			0	\$ 0.00
	Comments:			
3			0	\$ 0.00
	Comments:			
4				\$.00
	Comments:			
5				\$.00
	Comments:			
6				\$.00
	Comments:			
7				\$.00
	Comments:			
8				\$.00
	Comments:			

FIELD TECHNICAL REPORT



TQCN DOC# FTR-58K110461		Affiliate TMS	Dept. QA-Powertrain	Source FTS	Location TMS-SET	Ref 32715-1	Date 4/18/2006
Problem Area Base Vehicle	Primary Model Camry	Model Year 2007	Production Date 21-Mar-2006	Odometer 291 mi	VIN (confirm 17 characters): 4T1BE46K97U [REDACTED]		
Condition Title Vehicle lunges forward							

Do not type in YELLOW shaded fields - Input data from Web page or RDM:

Repair Date 15-APR-2006	Optional Ref.	Optional Approval
----------------------------	---------------	-------------------

Condition Description

Vehicle lunges forward when coming to a stop

Diagnostic Steps:

- Drove vehicle at 55mph, got vehicle to go into 5th gear, when slowing down and coming to stop, right at 5 mph the vehicle would lunge forward
- Drove vehicle in 4th gear, and when coming to a stop, once the vehicle reached 5mph, vehicle would lunge forward
- Drove vehicle in 3rd gear, and when coming to a stop, when the vehicle reached 5mph, vehicle would lunge forward
- Each of these test were complete with the A/C on and off, no change




Probable Cause

Unknown

Part # 1: 0000000000	Part # 2:	Part # 3:	Parts Disposition: No part available	Parts Shipping Destination: N/A
-------------------------	-----------	-----------	---	------------------------------------

Repair Process

Replaced SLT solenoid. Test drove vehicle, no change. Order transaxle.
Transmission serial # CU008932

 07 Camry 8932 (3).evn
  07 Camry 8932(1).evn
  07 Camry 8932(2).evn

Attachment 1: PRCS

FIELD TECHNICAL REPORT



TQCN DOC# FTR-58K110461		Affiliate TMS	Dept. QA-Powertrain	Source FTS	Location TMS-SET	Ref 32715-1	Date 4/18/2006
Problem Area Base Vehicle	Primary Model Camry	Model Year 2007	Production Date 21-Mar-2006	Odometer 291 mi	VIN (confirm 17 characters): 4T1BE46K97U [REDACTED]		
Condition Title Vehicle luges forward							

Attachment 1: Parts Recovery Control Sheet

Do not type in SHADED fields. If the **Final Destination** field below is "scrap", properly dispose of the part.

Orig Tracking

VIN

Doc No.



Final Destination: N/A	SETR#:	CQE Eng:	N/A
-------------------------------	--------	----------	-----

Importer: (Applies to TMC Shipments Only) North America EDER Gr., Technical Dept. #1 Overseas Customer Service Technical Div. TOYOTA MOTOR CORPORATION Nisshin Education & Training Center 5-210, SAKAE, NISSHIN, AICH, 470-0113 Japan	Deliver to:	住所 :
	Attn:	宛先 :
	Tel:	TEL :

T-STAR		
--------	--	--

Note: If this FTR contains more than one VIN, create a table in the report containing VIN, production date, and odometer

FOR CUSTOMS USE:
Used Parts Value

	Part # 1:	Part Description	Qty.	Used Part Value
1	0000000000		0	\$ 0.00
	Comments:			
2			0	\$ 0.00
	Comments:			
3			0	\$ 0.00
	Comments:			
4				\$.00
	Comments:			
5				\$.00
	Comments:			
6				\$.00
	Comments:			
7				\$.00
	Comments:			
8				\$.00
	Comments:			

FIELD TECHNICAL REPORT



TQCN DOC# FTR-8FX211661	Affiliate TMS	Dept. QA-Powertrain	Source FTS	Location TMS-LWA	Ref 29846-1	Date 4/26/2006
Problem Area Base Vehicle	Primary Model GS 430	Model Year 2006	Production Date 12-Jan-2005	Odometer 3064 mi	VIN (confirm 17 characters): JTHBN96S265 [REDACTED]	
Condition Title Accelerator Pedal						

Do not type in YELLOW shaded fields - Input data from Web page or RDM:

Repair Date 24-APR-2006	Optional Ref.	Optional Approval
-----------------------------------	---------------	-------------------

Condition Description

During the slalom portion of New Model training session the driver reported that the throttle stuck open and he had to apply heavy brake pressure to slow the car.

Diagnostic Steps:

- Inspected the pedal assembly and the mounting point on the vehicle floor.
- During the inspection I was able to remove the pedal assembly from the lower mounting bracket.
- When removing a pedal assembly from a donor car I was not able to remove the pedal assembly from the lower mounting bracket.


Probable Cause

Unknown. Possibly the pedal became separated from the lower mounting bracket and was jammed in the open position.

Part # 1: 7811130130	Part # 2: 7811430100	Part # 3:	Parts Disposition: Have part / will ship	Parts Shipping Destination: 2440
-------------------------	-------------------------	-----------	---	-------------------------------------

Repair Process

Replaced pedal with a service part (78111-30130).





Accelerator Pedal



Accelerator pedal and bracket from donor
JTHBN96S665 [REDACTED]



FIELD TECHNICAL REPORT

TQCN DOC# FTR-8FX211661		Affiliate TMS	Dept. QA-Powertrain	Source FTS	Location TMS-LWA	Ref 29846-1	Date 4/26/2006
Problem Area Base Vehicle	Primary Model GS 430	Model Year 2006	Production Date 12-Jan-2005	Odometer 3064 mi	VIN (confirm 17 characters): JTHBN96S265 [REDACTED]		
Condition Title Accelerator Pedal							



Attachment tabs - pedal from
JTHBN96S265 [REDACTED]

Attachment tabs – new service part



Detail of attachment tab - pedal from
JTHBN96S265 [REDACTED]

Detail of attachment tab - pedal from
JTHBN96S265 [REDACTED]

Attachment 1: PRCS

FIELD TECHNICAL REPORT



TQCN DOC# FTR-8FX211661	Affiliate TMS	Dept. QA-Powertrain	Source FTS	Location TMS-LWA	Ref 29846-1	Date 4/26/2006
Problem Area Base Vehicle	Primary Model GS 430	Model Year 2006	Production Date 12-Jan-2005	Odometer 3064 mi	VIN (confirm 17 characters): JTHBN96S265 [REDACTED]	
Condition Title Accelerator Pedal						

Attachment 1: Parts Recovery Control Sheet

Do not type in SHADED fields. If the Final Destination field below is "scrap", properly dispose of the part.

Orig Tracking
VIN [REDACTED]
Doc No. [REDACTED]



Final Destination: 2440		SETR#:	CQE Eng:	N/A
Importer: (Applies to TMC Shipments Only)		Deliver to:	住所 :	
Mr. N. Okumura, Chief Expert Quality Div. Warranty Parts Room TOYOTA MOTOR CORPORATION 1 Toyota, Toyota-city, Aichi, 471-8571 Japan		Attn:	宛先 :	
		Tel:	Tel:	
T-STAR		[REDACTED]	[REDACTED]	
Note: If this FTR contains more than one VIN, create a table in the report containing VIN, production date, and odometer				FOR CUSTOMS USE: Used Parts Value
1	Part # 1:	Part Description	Qty.	Used Part Value
	7811130130	PEDAL, ACCELERATOR	1	\$ 2.00
Comments:				
2	Part # 2:	Part Description	Qty.	Used Part Value
	7811430100	BRACKET, ACCELERATOR PEDAL SUPPORT	1	\$ 1.00
Comments:				
3	Part # 3:	Part Description	Qty.	Used Part Value
			0	\$ 0.00
Comments:				
4	Part # 4:	Part Description	Qty.	Used Part Value
				\$.00
Comments:				
5	Part # 5:	Part Description	Qty.	Used Part Value
				\$.00
Comments:				
6	Part # 6:	Part Description	Qty.	Used Part Value
				\$.00
Comments:				
7	Part # 7:	Part Description	Qty.	Used Part Value
				\$.00
Comments:				
8	Part # 8:	Part Description	Qty.	Used Part Value
				\$.00
Comments:				

DEALERSHIP PRODUCT REPORT



TQCN DOC# PR-60201-1266	Affiliate TMS	Dept. QA-Powertrain	Source MDT/DS	Dealer Code 60201	Ref 32941-1	Date 5/15/2006
Dealer Name BELL LEXUS		Dealer City PHOENIX		State AZ	Region LWA	
Primary Model LS 430	Model Year 2006	Production Date 30-MAR-06	Odometer 53 mi	VIN JTHBN36F265 [REDACTED]		
Condition Title QA-Body: Trunk Compartment						

Repair Date 29-APR-2006	Optional Ref.	Applicable DTC Code(s)
----------------------------	---------------	------------------------

Condition Description

CUSTOMER STATES THAT AFTER DRIVING VEHICLE 20 MILES ENGINE WILL SURGE AND STALL AT STOPS.

Diagnostic Steps:

NO MIL ON. FOUND RAW FUEL IN VACUUM LINE FROM INTAKE MANIFOLD TO CHARCOAL CANISTER.

Probable Cause

ORVR VALVE IN FUEL TANK FAILED AND CAUSED FUEL TO BE PUSHED INTO CANISTER.


Part # 1: 7700150120	Part # 2:	Part # 3:	Parts Available on Request: Available upon request	Parts Shipping Destination: CQEC
-------------------------	-----------	-----------	---	-------------------------------------

Repair Process

REPLACED FUEL TANK, CHARCOAL CANISTER, AND FILTER FOR CANISTER.

--	--	--

DEALERSHIP PRODUCT REPORT



TQCN DOC# PR-60201-1266	Affiliate TMS	Dept. QA-Powertrain	Source MDT/DS	Dealer Code 60201	Ref 32941-1	Date 5/15/2006
Dealer Name BELL LEXUS		Dealer City PHOENIX		State AZ	Region LWA	
Primary Model LS 430		Model Year 2006	Production Date 30-MAR-06	Odometer 53 mi	VIN JTHBN36F265 [REDACTED]	
Condition Title QA-Body: Trunk Compartment						

Attachment 1: Parts Recovery Control Sheet

Orig Tracking

VIN [REDACTED]

Doc No. [REDACTED]

Do not type in SHADED fields. If the Final Destination field below is "scrap", properly dispose of the part.



Final Destination: CQEC		SETR#:	CQE Eng:	N/A
Importer: (Applies to TMC Shipments Only)		Deliver to:	住所 :	
North America EDER Gr., Technical Dept. #1 Overseas Customer Service Technical Div. TOYOTA MOTOR CORPORATION Nisshin Education & Training Center 5-210, SAKAE, NISSHIN, AICH, 470-0113 Japan		Attn:	宛先 :	
		Tel:	Tel:	
T-STAR		[Barcode]	[Barcode]	
Note: If this FTR contains more than one VIN, create a table in the report containing VIN, production date, and odometer				FOR CUSTOMS USE: Used Parts Value
1	Part # 1: 7700150120	Part Description TANK SUB-ASSY, FUEL	Qty. 1	Used Part Value \$ 78 .00
	Comments:			
2	Part # 2:	Part Description	Qty. 0	Used Part Value \$ 0 .00
	Comments:			
3	Part # 3:	Part Description	Qty. 0	Used Part Value \$ 0 .00
	Comments:			
4	Part # 4:	Part Description	Qty. \$	Used Part Value .00
	Comments:			
5	Part # 5:	Part Description	Qty. \$	Used Part Value .00
	Comments:			
6	Part # 6:	Part Description	Qty. \$	Used Part Value .00
	Comments:			
7	Part # 7:	Part Description	Qty. \$	Used Part Value .00
	Comments:			

DEALERSHIP PRODUCT REPORT



TQCN DOC# PR-62908-1386	Affiliate TMS	Dept. QA-Powertrain	Source MDT/DS	Dealer Code 62908	Ref 30537-1	Date 6/1/2006
Dealer Name WARNOCK LEXUS		Dealer City LIVINGSTON		State NJ	Region LEA	
Primary Model ES 330	Model Year 2006	Production Date 22-NOV-05	Odometer 4484 mi	VIN JTHBA30GX65 [REDACTED]		
Condition Title Harsh Shifts, Shudder During Light Acceleration						

Repair Date 17-MAY-2006	Optional Ref.	Applicable DTC Code(s)
----------------------------	---------------	------------------------

Condition Description

Customer states vehicle is bucking at 20 mph

Diagnostic Steps:

Checked vehicle for trouble codes no codes found.
 Test drove customer vehicle and felt a shudder intermittently at 20 mph during light acceleration and felt a harsh shift intermittently between 35-40mph also during light acceleration.
 Test drove a similar car and felt similar shifting concern.


Probable Cause

Part # 1: 000000000000	Part # 2:	Part # 3:	Parts Available on Request: No part available	Parts Shipping Destination: CQEC
---------------------------	-----------	-----------	--	-------------------------------------

Repair Process

No repair available or attempted at this time.

DEALERSHIP PRODUCT REPORT



TQCN DOC# PR-62908-1386	Affiliate TMS	Dept. QA-Powertrain	Source MDT/DS	Dealer Code 62908	Ref 30537-1	Date 6/1/2006
Dealer Name WARNOCK LEXUS		Dealer City LIVINGSTON		State NJ	Region LEA	
Primary Model ES 330	Model Year 2006	Production Date 22-NOV-05	Odometer 4484 mi	VIN JTHBA30GX65 [REDACTED]		
Condition Title Harsh Shifts, Shudder During Light Acceleration						

Attachment 1: Parts Recovery Control Sheet

Do not type in SHADED fields. If the Final Destination field below is "scrap", properly dispose of the part.

Orig Tracking
VIN [REDACTED]
Doc No. [REDACTED]



Final Destination: CQEC		SETR#:	CQE Eng:	N/A
Importer: (Applies to TMC Shipments Only)		Deliver to:	住所 :	
North America EDER Gr., Technical Dept. #1 Overseas Customer Service Technical Div. TOYOTA MOTOR CORPORATION Nisshin Education & Training Center 5-210, SAKAE, NISSHIN, AICH, 470-0113 Japan		Attn:	宛先 :	
		Tel:	Tel:	
T-STAR				
Note: If this FTR contains more than one VIN, create a table in the report containing VIN, production date, and odometer				FOR CUSTOMS USE: Used Parts Value
1	Part # 1: 000000000000	Part Description	Qty. 0	Used Part Value \$ 0.00
Comments:				
2	Part # 2:	Part Description	Qty. 0	Used Part Value \$ 0.00
Comments:				
3	Part # 3:	Part Description	Qty. 0	Used Part Value \$ 0.00
Comments:				
4	Part # 4:	Part Description	Qty. \$	Used Part Value .00
Comments:				
5	Part # 5:	Part Description	Qty. \$	Used Part Value .00
Comments:				
6	Part # 6:	Part Description	Qty. \$	Used Part Value .00
Comments:				
7	Part # 7:	Part Description	Qty. \$	Used Part Value .00
Comments:				

FIELD TECHNICAL REPORT



TQCN DOC# FTR-9VK117461A	Affiliate TCI	Dept. TCI	Source PE	Location TCI	Ref	Date 6/27/2006
Problem Area Base Vehicle	Primary Model Camry	Model Year 2007	Production Date 01-Mar-2006	Odometer 3259 km	VIN (confirm 17 characters): 4T1BK46K07U [REDACTED]	

Condition Title
Engine Surge during 3-4 upshift

Do not type in YELLOW shaded fields - Input data from Web page or RDM:

Repair Date 22-JUN-2006	Optional Ref.	Optional Approval
-----------------------------------	---------------	-------------------

Condition Description

Engine RPM surges during when the following conditions are met:
 Transmission is shifting from 3rd to 4th gear.
 Vehicle is traveling on a slight uphill road.
 Light throttle is applied.

Diagnostic Steps:

Vehicle had transmission replaced on June 9, 2006 due to internal failure. (Odometer reading was 910 at the time of repair.)
 "MIL" is not on.
 No pending codes in memory.
 New Transmission serial number is 2A06E108878.
 Condition was duplicated and snapshot was taken.
 Snapshot shows that engine revolution increases by 243 rpm for 1 second when transmission is shifting from 3rd to 4th gear and then drops by 550 rpm. (See photo below and compare with techview file)


Probable Cause

Unknown.

Part # 1: 3050033470	Part # 2:	Part # 3:	Parts Disposition: No part available	Parts Shipping Destination: N/A
-------------------------	-----------	-----------	---	------------------------------------

Repair Process



No repair done at this time.



FIELD TECHNICAL REPORT



TQCN DOC# FTR-9VK117461A		Affiliate TCI	Dept. TCI	Source PE	Location TCI	Ref	Date 6/27/2006
Problem Area Base Vehicle	Primary Model Camry	Model Year 2007	Production Date 01-Mar-2006	Odometer 3259 km	VIN (confirm 17 characters): 4T1BK46K07U [REDACTED]		

 C:\Documents and Settings\n	At 17.4 seconds, Transmission upshifts to 4 th gear. Engine RPM goes from 2089 to 2332 (243 rpm increase.) At 18.4 seconds, Engine RPM drops from 2332 to 1782 rpm (550 rpm decrease) See Techview file for details.
 C:\Documents and Settings\n	See video of location where condition happened.

Attachment 1: PRCS

FIELD TECHNICAL REPORT



TQCN DOC# FTR-9VK117461A	Affiliate TCI	Dept. TCI	Source PE	Location TCI	Ref	Date 6/27/2006
Problem Area Base Vehicle	Primary Model Camry	Model Year 2007	Production Date 01-Mar-2006	Odometer 3259 km	VIN (confirm 17 characters): 4T1BK46K07U [REDACTED]	

Attachment 1: Parts Recovery Control Sheet

Do not type in SHADED fields. If the **Final Destination** field below is "scrap", properly dispose of the part.

Orig Tracking

VIN

Doc No.



Final Destination: N/A	SETR#:	CQE Eng: N/A
-------------------------------	---------------	---------------------

Importer: (Applies to TMC Shipments Only) North America EDER Gr., Technical Dept. #1 Overseas Customer Service Technical Div. TOYOTA MOTOR CORPORATION Nisshin Education & Training Center 5-210, SAKAE, NISSHIN, AICH, 470-0113 Japan	Deliver to:	住所:
	Attn:	宛先:
	Tel:	Tel:

T-STAR		
--------	--	--

Note: If this FTR contains more than one VIN, create a table in the report containing VIN, production date, and odometer FOR CUSTOMS USE: Used Parts Value

	Part #	Part Description	Qty.	Used Part Value
1	3050033470 Comments:	TRANSAXLE ASSY, AUTOMATIC	0	\$ 565
2	Part # 2: Comments:	Part Description	0	\$ 0.00
3	Part # 3: Comments:	Part Description	0	\$ 0.00
4	Part # 4: Comments:	Part Description		\$.00
5	Part # 5: Comments:	Part Description		\$.00
6	Part # 6: Comments:	Part Description		\$.00
7	Part # 7: Comments:	Part Description		\$.00
8	Part # 8: Comments:	Part Description		\$.00

DEALERSHIP PRODUCT REPORT



TQCN DOC# PR-60105-2516	Affiliate TMS	Dept. QA-Powertrain	Source MDT/DS	Dealer Code 60105	Ref 35170-1	Date 9/15/2006
Dealer Name TOM WILLIAMS LEXUS		Dealer City IRONDALE		State AL	Region LSA	
Primary Model LS 430	Model Year 2005	Production Date 15-DEC-04	Odometer 16690 mi	VIN JTHBN36FX55 [REDACTED]		
Condition Title ATM(Electrical)ECM Harsh Shift on Acceleration						

Repair Date 08-SEP-2006	Optional Ref.	Applicable DTC Code(s)
-----------------------------------	---------------	------------------------

Condition Description

Customer states there is a slight jerk in the vehicle when accelerating, does not shift throughout gears smoothly.

Diagnostic Steps:

Checked software calibration ID, most current is in vehicle's ECM.

Probable Cause

unknown

Part # 1: 3500050150	Part # 2:	Part # 3:	Parts Available on Request: No part available	Parts Shipping Destination: CQEC
-------------------------	-----------	-----------	--	-------------------------------------

Repair Process

Cleared learned values. Test drove vehicle to help with the ECM relearning.

--	--	--

DEALERSHIP PRODUCT REPORT



TQCN DOC# PR-60105-2516	Affiliate TMS	Dept. QA-Powertrain	Source MDT/DS	Dealer Code 60105	Ref 35170-1	Date 9/15/2006
Dealer Name TOM WILLIAMS LEXUS		Dealer City IRONDALE		State AL	Region LSA	
Primary Model LS 430	Model Year 2005	Production Date 15-DEC-04	Odometer 16690 mi		VIN JTHBN36FX55 [REDACTED]	
Condition Title ATM(Electrical)ECM Harsh Shift on Acceleration						

Attachment 1: Parts Recovery Control Sheet

Do not type in SHADED fields. If the Final Destination field below is "scrap", properly dispose of the part.

Orig Tracking
VIN
Doc No.



Final Destination: CQEC		SETR#:	CQE Eng:	N/A
Importer: (Applies to TMC Shipments Only)		Deliver to:	住所 :	
North America EDER Gr., Technical Dept. #1 Overseas Customer Service Technical Div. TOYOTA MOTOR CORPORATION Nisshin Education & Training Center 5-210, SAKAE, NISSHIN, AICH, 470-0113 Japan		Attn:	宛先 :	
		Tel:	Tel:	
T-STAR				
Note: If this FTR contains more than one VIN, create a table in the report containing VIN, production date, and odometer				FOR CUSTOMS USE: Used Parts Value
1	Part # 1: 3500050150	Part Description TRANSMISSION ASSY	Qty. 1	Used Part Value \$ 954 .00
	Comments:			
2	Part # 2:	Part Description	Qty. 0	Used Part Value \$ 0 .00
	Comments:			
3	Part # 3:	Part Description	Qty. 0	Used Part Value \$ 0 .00
	Comments:			
4	Part # 4:	Part Description	Qty. \$	Used Part Value .00
	Comments:			
5	Part # 5:	Part Description	Qty. \$	Used Part Value .00
	Comments:			
6	Part # 6:	Part Description	Qty. \$	Used Part Value .00
	Comments:			
7	Part # 7:	Part Description	Qty. \$	Used Part Value .00
	Comments:			

TQCN DOC# FTR-PIF335461A		Affiliate TMS	Dept. QA-Powertrain	Source PE	Location TMS	Ref 36701-1	Date 12/22/2006
Problem Area Base Vehicle	Primary Model LS 460	Model Year 2007	Production Date 9/19/06	Odometer 2994	VIN (confirm 17 characters): JTHGL46F75 [REDACTED]		
Condition Title ATM(Electrical)ECM Erratic Shift on Acceleration							

Do not type in YELLOW shaded fields - Input data from Web page or RDM:

Repair Date	Optional Ref.	Optional Approval
-------------	---------------	-------------------

Condition Description

Customer complaint: Transmission hesitates and has a double bump when accelerating from a stop after sitting at a traffic light for more than a few second

Diagnostic Steps:

Technician test drove with customer and confirmed the following conditions are needed to duplicate the condition:

Vehicle is placed in "D" (Drive) and Park Hold Feature is turned "OFF", vehicle is stopped at the traffic light for greater than 45 seconds. Throttle application is made immediately to 50% and there is a hesitation and then bump as vehicle engages a gear

Probable Cause

Electronic transmission control related to shift from 1st to neutral after being stopped for greater than 45 seconds with brake applied

Part # 1: 8953550010	Part # 2:	Part # 3:	Parts Disposition: No part available	Parts Shipping Destination: CQEC
-------------------------	-----------	-----------	---	-------------------------------------

Repair Process

None available

QAP Comment: Information in this report obtained from TAS hotline contact


CHASSIS - AA80E AUTOMATIC TRANSMISSION

CH-39

11. Neutral Control

- Neutral control is used to disengage the transmission from the engine while the vehicle is stopped.
- When the shift lever is in the D position and the vehicle is stopped, the ECT ECU semi-disengages the C₂ clutch and the B₂ brake. This reduces the load on the engine and improves fuel economy while the vehicle is stopped. This control continues if the driver switches the shift lever to the S mode at this time. However, neutral control does not take effect if the vehicle comes to a stop in the S mode.

► Conventional ◀



FIELD TECHNICAL REPORT



TQCN DOC# FTR-PIF335461A	Affiliate TMS	Dept. QA-Powertrain	Source PE	Location TMS	Ref 36701-1	Date 12/22/2006
Problem Area Base Vehicle	Primary Model LS 460	Model Year 2007	Production Date 9/19/06	Odometer 2994	VIN (confirm 17 characters): JTHGL46F75 [REDACTED]	
Condition Title ATM(Electrical)ECM Erratic Shift on Acceleration						

Attachment 1: Parts Recovery Control Sheet

Do not type in SHADED fields. If the **Final Destination** field below is "scrap", properly dispose of the part.

Orig Tracking

VIN

Doc No.



Final Destination: CQEC		SETR#:	CQE Eng:	N/A
Importer: (Applies to TMC Shipments Only)		Deliver to:		住所:
Mr. N. Okumura, Chief Expert Quality Div. Warranty Parts Room TOYOTA MOTOR CORPORATION 1 Toyota, Toyota-city, Aichi, 471-8571 Japan		Attn:		宛先:
		Tel:		TEL:
T-STAR				
Note: If this FTR contains more than one VIN, create a table in the report containing VIN, production date, and odometer				FOR CUSTOMS USE: Used Parts Value
Part #	Part Description	Qty.	Used Part Value	
1	8953550010 COMPUTER, TRANSMISSION CONTROL	1	\$ 126 .00	
Comments:				
2		0	\$ 0 .00	
Comments:				
3		0	\$ 0 .00	
Comments:				
4			\$.00	
Comments:				
5			\$.00	
Comments:				
6			\$.00	
Comments:				
7			\$.00	
Comments:				
8			\$.00	
Comments:				

FIELD TECHNICAL REPORT



TQCN DOC# FTR-VRE601271		Affiliate TMS	Dept. QA-Powertrain	Source FPE	Location TMS-LSA	Ref 37294-1	Date 1/12/2007
Problem Area Base Vehicle	Primary Model IS 350	Model Year 2006	Production Date 14-Jul-2006	Odometer 254 mi	VIN (confirm 17 characters): JTHBE262X62 [REDACTED]		
Condition Title Erratic throttle operation							

Do not type in YELLOW shaded fields - Input data from Web page or RDM:

Repair Date 10-JAN-2007	Optional Ref. 64230 0110071	Optional Approval
----------------------------	--------------------------------	-------------------

Condition Description

Customer states intermittently the vehicle is very sluggish and surges for the first 5 minutes of driving when started cold, and then the vehicle operates properly. This sluggish/surging occurs about 80% of the time driving until the vehicle reaches operating temperature.

When the condition occurs, if the accelerator pedal is completely depressed the engine speed will slowly climb to about 4000rpm and then drop to about 3000rpm. As long as the accelerator pedal is depressed the engine speed will surge up and down around these RPMs.

There is no Diagnostic Trouble Codes present, pending or in history.

Diagnostic Steps:

1. A video was taken of this condition as well as multiple snapshots. These files are attached below.
2. The condition felt like a low fuel pressure concern, so the techstream was used to monitor fuel pressure when the condition occurred. While pressure did decrease slightly the pressure loss is not seem to fit such an immediate drop in engine speed.
3. The techstream was then used to monitor throttle position. When engine speed and throttle position were overlapped in graph mode and zoomed in on, it revealed the throttle position was closing prior to the drop in engine speed (the accelerator position sensor read wide open throttle during this).
4. The throttle body motor resistance was checked - 2.5Ω (spec 0.3 - 100Ω). This measurement was also compared to another vehicle and found to be very similar.
5. The throttle body was swapped to a donor vehicle and then both vehicles were test driven cold. The condition moved to the donor vehicle.

Probable Cause


Internal throttle body concern.

Part # 1: 2203031040	Part # 2:	Part # 3:	Parts Disposition: Have part / will ship	Parts Shipping Destination: CQEC
-------------------------	-----------	-----------	---	-------------------------------------

Repair Process

Replacing the throttle body repaired the vehicle.


TQCN DOC# FTR-VRE601271		Affiliate TMS	Dept. QA-Powertrain	Source FPE	Location TMS-LSA	Ref 37294-1	Date 1/12/2007
Problem Area Base Vehicle	Primary Model IS 350	Model Year 2006	Production Date 14-Jul-2006	Odometer 254 mi	VIN (confirm 17 characters): JTHBE262X62 [REDACTED]		
Condition Title Erratic throttle operation							



IS350 Northside.zip

This is a video of the condition. The vehicle is in neutral with the accelerator pedal completely depressed for the entire snapshot.


(Note: the vehicle in the video is the donor vehicle after the throttle body was swapped to it for diagnostic testing)



2006_IS350_2GR-FSE_JTHBE262X62 [REDACTED] 1-9-2007 11:14:28 AM.zip

Attached is a Techstream file with multiple snapshots taken of the condition. Snapshots "DATA 2" through "DATA 12" are when the surging is occurring. "DATA 13 through DATA 16" are after the vehicle began operating normal again.

Most analysis as done using "DATA 4" since the condition occurring so steadily throughout the entire snapshot.




This is a screen capture out of the snapshot (Data 4). It shown the throttle position decreasing with the accelerator position holding steady (completely depressed). Shortly after the throttle position decreases engine speed follows.

The fuel pressure graph appears to closely follow throttle position as well, although the pressure decrease was not believed to be significant enough to create this condition.

FIELD TECHNICAL REPORT

TQCN DOC# FTR-VRE601271		Affiliate TMS	Dept. QA-Powertrain	Source FPE	Location TMS-LSA	Ref 37294-1	Date 1/12/2007
Problem Area Base Vehicle	Primary Model IS 350	Model Year 2006	Production Date 14-Jul-2006	Odometer 254 mi	VIN (confirm 17 characters): JTHBE262X62 [REDACTED]		
Condition Title Erratic throttle operation							



Throttle body concern



22030-31040
6G04
02393

6H27

Attachment 1: PRCS

FIELD TECHNICAL REPORT



TQCN DOC# FTR-VRE601271		Affiliate TMS	Dept. QA-Powertrain	Source FPE	Location TMS-LSA	Ref 37294-1	Date 1/12/2007
Problem Area Base Vehicle	Primary Model IS 350	Model Year 2006	Production Date 14-Jul-2006	Odometer 254 mi	VIN (confirm 17 characters): JTHBE262X62 [REDACTED]		
Condition Title Erratic throttle operation							

Attachment 1: Parts Recovery Control Sheet

Do not type in SHADED fields. If the **Final Destination** field below is "scrap", properly dispose of the part.

Orig Tracking

VIN

Doc No.



Final Destination: CQEC	SETR#:	CQE Eng:	N/A
Importer: (Applies to TMC Shipments Only) North America EDER Gr., Technical Dept. #1 Overseas Customer Service Technical Div. TOYOTA MOTOR CORPORATION Nisshin Education & Training Center 5-210, SAKAE, NISSHIN, AICH, 470-0113 Japan		Deliver to: Attn: Tel:	住所 : 宛先 : Tel:

T-STAR



Note: If this FTR contains more than one VIN, create a table in the report containing VIN, production date, and odometer

FOR CUSTOMS USE:
Used Parts Value

	Part # 1:	Part Description	Qty.	Used Part Value
1	2203031040	BODY ASSY, THROTTLE W/MOTOR	1	\$ 105 .00
	Comments:			
2	Part # 2:	Part Description	Qty.	Used Part Value
			0	\$ 0 .00
	Comments:			
3	Part # 3:	Part Description	Qty.	Used Part Value
			0	\$ 0 .00
	Comments:			
4	Part # 4:	Part Description	Qty.	Used Part Value
				\$.00
	Comments:			
5	Part # 5:	Part Description	Qty.	Used Part Value
				\$.00
	Comments:			
6	Part # 6:	Part Description	Qty.	Used Part Value
				\$.00
	Comments:			
7	Part # 7:	Part Description	Qty.	Used Part Value
				\$.00
	Comments:			
8	Part # 8:	Part Description	Qty.	Used Part Value
				\$.00
	Comments:			

FIELD TECHNICAL REPORT



TQCN DOC# FTR-78K110171		Affiliate TMS	Dept. QA-Powertrain	Source FTS	Location TMS-NY	Ref 39199-1	Date 4/17/2007
Problem Area Base Vehicle	Primary Model Camry	Model Year 2006	Production Date 26-Sep-2005	Odometer 19777 mi	VIN (confirm 17 characters): 4T1BE32K66U [REDACTED]		
Condition Title A/F Sensor- Surge during light Acceleration							

Do not type in YELLOW shaded fields - Input data from Web page or RDM:

Repair Date 11-APR-2007	Optional Ref.	Optional Approval
----------------------------	---------------	-------------------

Condition Description

Customer states vehicle surges on light to moderate acceleration.

Diagnostic Steps:

Technician verified the customer's complaint.

- Technician used tech stream and found A/F sensor reading 4.99 Volts during surge.
- Technician disconnected A/F sensor and test drove vehicle. Concern was resolved.
- Technician stated A/F sensor appears to be cracked.


Probable Cause

Unknown

Part # 1: 8946706030	Part # 2:	Part # 3:	Parts Disposition: Have part / will ship	Parts Shipping Destination: CQEC
-------------------------	-----------	-----------	---	-------------------------------------

Repair Process

- Technician replaced A/F sensor and test drove concern was resolved.



A/F Sensor P/N 89467-06030

Picture attempts to show the following data:
Toyota 89467-06030
Denso 0350 09G19

FIELD TECHNICAL REPORT



TQCN DOC# FTR-78K110171		Affiliate TMS	Dept. QA-Powertrain	Source FTS	Location TMS-NY	Ref 39199-1	Date 4/17/2007
Problem Area Base Vehicle	Primary Model Camry	Model Year 2006	Production Date 26-Sep-2005	Odometer 19777 mi	VIN (confirm 17 characters): 4T1BE32K66U [REDACTED]		
Condition Title A/F Sensor- Surge during light Acceleration							

Attachment 1: Parts Recovery Control Sheet

Do not type in SHADED fields. If the Final Destination field below is "scrap", properly dispose of the part.

Orig Tracking

VIN [REDACTED]

Doc No. [REDACTED]



Final Destination: CQEC		SETR#:	CQE Eng:	N/A
Importer: (Applies to TMC Shipments Only)		Deliver to:	住所 :	
Mr. N. Okumura, Chief Expert Quality Div. Warranty Parts Room TOYOTA MOTOR CORPORATION 1 Toyota, Toyota-city, Aichi, 471-8571 Japan		Attn:	宛先 :	
		Tel:	Tel:	
T-STAR		[REDACTED]	[REDACTED]	
Note: If this FTR contains more than one VIN, create a table in the report containing VIN, production date, and odometer				FOR CUSTOMS USE: Used Parts Value
1	Part # 1: 8946706030	Part Description SENSOR, AIR FUEL RATIO	Qty. 1	Used Part Value \$ 31 .00
	Comments:			
2	Part # 2:	Part Description	Qty. 0	Used Part Value \$ 0 .00
	Comments:			
3	Part # 3:	Part Description	Qty. 0	Used Part Value \$ 0 .00
	Comments:			
4	Part # 4:	Part Description	Qty. \$	Used Part Value .00
	Comments:			
5	Part # 5:	Part Description	Qty. \$	Used Part Value .00
	Comments:			
6	Part # 6:	Part Description	Qty. \$	Used Part Value .00
	Comments:			
7	Part # 7:	Part Description	Qty. \$	Used Part Value .00
	Comments:			
8	Part # 8:	Part Description	Qty. \$	Used Part Value .00
	Comments:			

FIELD TECHNICAL REPORT



TQCN DOC# FTR-5O1115271	Affiliate TMS	Dept. QA-Powertrain	Source FTS	Location TMS-PT	Ref 40151-1	Date 6/4/2007
Problem Area Base Vehicle	Primary Model Tundra	Model Year 2007	Production Date 06-Feb-2007	Odometer 2791 mi	VIN (confirm 17 characters): 5TBBV58167S [REDACTED]	
Condition Title Driveline Rear Driveshaft Thunk when accelerating from a stop						

Do not type in YELLOW shaded fields - Input data from Web page or RDM:

Repair Date 12-MAY-2007	Optional Ref.	Optional Approval
----------------------------	---------------	-------------------

Condition Description

- The owner complains of a bump in the drivetrain when accelerating from a stop.
- The bump occurs just as the vehicle begins to move.

Diagnostic Steps:

- Operated the vehicle and verified the condition.
- The vehicle had to be stopped aggressively from speeds of about 35mph or higher.
- The condition did not occur with slow gentle stops.
- The sensation is similar to the driveline bump that was present in the '00-'06 MY Tundra.
- This bump is different because it occurs as the vehicle starts to move rather than when the engine idle drops as the A/C compressor cycles off.


Probable Cause

Unknown

Part # 1: 371000C150	Part # 2:	Part # 3:	Parts Disposition: Have part / will ship	Parts Shipping Destination: CQEC
-------------------------	-----------	-----------	---	-------------------------------------

Repair Process

The rear propeller shaft assembly was replaced with one from another comparable vehicle and the condition was corrected. A new replacement part was subsequently installed in the donor vehicle. The VIN from the donor vehicle was: 5TFBV581X7X [REDACTED]



Attachment 1: PRCS

FIELD TECHNICAL REPORT



TQCN DOC# FTR-5O1115271		Affiliate TMS	Dept. QA-Powertrain	Source FTS	Location TMS-PT	Ref 40151-1	Date 6/4/2007
Problem Area Base Vehicle	Primary Model Tundra	Model Year 2007	Production Date 06-Feb-2007	Odometer 2791 mi	VIN (confirm 17 characters): 5TBBV58167S [REDACTED]		
Condition Title Driveline Rear Driveshaft Thunk when accelerating from a stop							

Attachment 1: Parts Recovery Control Sheet

Do not type in SHADED fields. If the **Final Destination** field below is "scrap", properly dispose of the part.

Orig Tracking

VIN

Doc No.



Final Destination: CQEC	SETR#:	CQE Eng:	N/A
Importer: (Applies to TMC Shipments Only) Mr. N. Okumura, Chief Expert Quality Div. Warranty Parts Room TOYOTA MOTOR CORPORATION 1 Toyota, Toyota-city, Aichi, 471-8571 Japan	Deliver to: Attn: Tel:	住所 : 宛先 : Tel:	

T-STAR



Note: If this FTR contains more than one VIN, create a table in the report containing VIN, production date, and odometer

FOR CUSTOMS USE:
Used Parts Value

	Part # 1:	Part Description	Qty.	Used Part Value
1	371000C150	SHAFT ASSY, PROPELLER W/CTR BEARING	1	\$ 224 .00
	Comments:			
2	Part # 2:	Part Description	Qty.	Used Part Value
			0	\$ 0 .00
	Comments:			
3	Part # 3:	Part Description	Qty.	Used Part Value
			0	\$ 0 .00
	Comments:			
4	Part # 4:	Part Description	Qty.	Used Part Value
				\$.00
	Comments:			
5	Part # 5:	Part Description	Qty.	Used Part Value
				\$.00
	Comments:			
6	Part # 6:	Part Description	Qty.	Used Part Value
				\$.00
	Comments:			
7	Part # 7:	Part Description	Qty.	Used Part Value
				\$.00
	Comments:			
8	Part # 8:	Part Description	Qty.	Used Part Value
				\$.00
	Comments:			

DEALERSHIP PRODUCT REPORT



TQCN DOC# PR-62930-1427	Affiliate TMS	Dept. QA-Powertrain	Source MDT/DS	Dealer Code 62930	Ref 36918-1	Date 6/7/2007
Dealer Name RAY CATENA LEXUS/FREEHOLD		Dealer City FREEHOLD		State NJ	Region LEA	
Primary Model ES 350	Model Year 2007	Production Date 28-JUN-06	Odometer 10357 mi	VIN JTHBJ46G772 [REDACTED]		
Condition Title U660E: Shift Flare on Reacceleration						

Repair Date 22-MAY-2007	Optional Ref.	Applicable DTC Code(s)
----------------------------	---------------	------------------------

Condition Description

- Quoting the repair order, Customer states when driving from 35-40 MPH and accelerate lightly, vehicle takes off as if it was floored

Diagnostic Steps:

- Test drive to duplicate 2/3 and or 4/5 shift issue.
- Was able to duplicate 5/4 downshift as in TSB TC005-07.
- After performing TSB there was a noticeable difference in shifting.

Probable Cause

- ECT software

Part # 1: 8953033041	Part # 2:	Part # 3:	Parts Available on Request: No part available	Parts Shipping Destination: CQEC
-------------------------	-----------	-----------	--	-------------------------------------

Repair Process

- Perform TSB TC005-07
- This report created to provide feedback regarding TSIB TC005-07

DEALERSHIP PRODUCT REPORT



TQCN DOC# PR-62930-1427	Affiliate TMS	Dept. QA-Powertrain	Source MDT/DS	Dealer Code 62930	Ref 36918-1	Date 6/7/2007
Dealer Name RAY CATENA LEXUS/FREEHOLD		Dealer City FREEHOLD		State NJ	Region LEA	
Primary Model ES 350	Model Year 2007	Production Date 28-JUN-06	Odometer 10357 mi	VIN JTHBJ46G772 [REDACTED]		
Condition Title U660E: Shift Flare on Reacceleration						

Attachment 1: Parts Recovery Control Sheet

Do not type in SHADED fields. If the Final Destination field below is "scrap", properly dispose of the part.

Orig Tracking
VIN [REDACTED]
Doc No. [REDACTED]



Final Destination: CQEC		SETR#:	CQE Eng:	N/A
Importer: (Applies to TMC Shipments Only)		Deliver to:	住所 :	
North America EDER Gr., Technical Dept. #1 Overseas Customer Service Technical Div. TOYOTA MOTOR CORPORATION Nisshin Education & Training Center 5-210, SAKAE, NISSHIN, AICH, 470-0113 Japan		Attn:	宛先 :	
		Tel:	Tel:	
T-STAR		[Barcode]	[Barcode]	
Note: If this FTR contains more than one VIN, create a table in the report containing VIN, production date, and odometer				FOR CUSTOMS USE: Used Parts Value
1	Part # 1: 8953033041	Part Description COMPUTER ASSY, TRANSMISSION CONTROL	Qty. 1	Used Part Value \$ 88.00
Comments:				
2	Part # 2:	Part Description	Qty. 0	Used Part Value \$ 0.00
Comments:				
3	Part # 3:	Part Description	Qty. 0	Used Part Value \$ 0.00
Comments:				
4	Part # 4:	Part Description	Qty. \$	Used Part Value .00
Comments:				
5	Part # 5:	Part Description	Qty. \$	Used Part Value .00
Comments:				
6	Part # 6:	Part Description	Qty. \$	Used Part Value .00
Comments:				
7	Part # 7:	Part Description	Qty. \$	Used Part Value .00
Comments:				

FIELD TECHNICAL REPORT



TQCN DOC# FTR-JZU225471		Affiliate TMS	Dept. QA-Chassis	Source FTS	Location TMS-CAT	Ref 41024-1	Date 9/12/2007
Problem Area Base Vehicle	Primary Model Highlander	Model Year 2008	Production Date 13-Jun-2007	Odometer 3300 mi	VIN (confirm 17 characters): JTEES42A482 [REDACTED]		
Condition Title MIL Light "ON" Code C1430 - Brake Pedal Load Sensing Switch OFF Malfunction							

Do not type in YELLOW shaded fields - Input data from Web page or RDM:

Repair Date 11-SEP-2008	Optional Ref.	Optional Approval
-----------------------------------	---------------	-------------------

Condition Description

- VSC, ABS, Brake warning lights illuminate immediately after hard brake pedal application, (panic stop maneuver.)
- DTC C1430: Brake Pedal Load Sensing Switch OFF Stuck Malfunction
- DTC C1431: Brake Pedal Load Sensing Switch ON Stuck Malfunction
- Depressing the brake pedal less than a few mm will cause the Brake Assist system to activate and the vehicle to lurch to a stop with little pedal travel, making the vehicle un-driveable.
- Brake malfunction message displayed
- ABS malfunction message displayed
- VSC system malfunction

Diagnostic Steps:

- Visually inspect brake pedal load sensing switch, switch plunger doesn't align with actuator bracket. Please see photos.
- Switch plunger jammed against actuator bracket.
- Bracket appears to be bending or shifting with extreme braking maneuvers.

Probable Cause

Unknown at this time


Part # 1: 4710648060	Part # 2:	Part # 3:	Parts Disposition: Special request only	Parts Shipping Destination: 2750
-------------------------	-----------	-----------	--	-------------------------------------

Repair Process


- Reposition bracket back into place, code immediately changes to stored.
- ABS and VSC lights turn off.
- After repositioning bracket and performing another panic stop maneuver, bracket moves out of position again.
- If repeating another panic stop maneuver, the code immediately reset

FIELD TECHNICAL REPORT


TQCN DOC# FTR-JZU225471		Affiliate TMS	Dept. QA-Chassis	Source FTS	Location TMS-CAT	Ref 41024-1	Date 9/12/2007
Problem Area Base Vehicle	Primary Model Highlander	Model Year 2008	Production Date 13-Jun-2007	Odometer 3300 mi	VIN (confirm 17 characters): JTEES42A482 [REDACTED]		
Condition Title MIL Light "ON" Code C1430 - Brake Pedal Load Sensing Switch OFF Malfunction							




Pedal force switch actuator out of alignment



Warning message



Warning message



Warning message

Attachment 1: PRCS

FIELD TECHNICAL REPORT



TQCN DOC# FTR-JZU225471		Affiliate TMS	Dept. QA-Chassis	Source FTS	Location TMS-CAT	Ref 41024-1	Date 9/12/2007
Problem Area Base Vehicle	Primary Model Highlander	Model Year 2008	Production Date 13-Jun-2007	Odometer 3300 mi	VIN (confirm 17 characters): JTEES42A482 [REDACTED]		
Condition Title MIL Light "ON" Code C1430 - Brake Pedal Load Sensing Switch OFF Malfunction							

Attachment 1: Parts Recovery Control Sheet

Do not type in SHADED fields. If the **Final Destination** field below is "scrap", properly dispose of the part.

Orig Tracking

VIN

Doc No.



Final Destination: 2750		SETR#:	CQE Eng:	N/A
Importer: (Applies to TMC Shipments Only)		Deliver to:		住所 :
Mr. N. Okumura, Chief Expert Quality Div. Warranty Parts Room TOYOTA MOTOR CORPORATION 1 Toyota, Toyota-city, Aichi, 471-8571 Japan		Attn:		宛先 :
		Tel:		Tel :
T-STAR				
Note: If this FTR contains more than one VIN, create a table in the report containing VIN, production date, and odometer				FOR CUSTOMS USE: Used Parts Value
1	Part # 1: 4710648060	Part Description	Qty. 1	Used Part Value \$ 0 .00
	Comments:			

DEALERSHIP PRODUCT REPORT



TQCN DOC# PR-48028-2987	Affiliate TMS	Dept. QA-Powertrain	Source MDT/DS	Dealer Code 48028	Ref 32179-1	Date 10/27/2007
Dealer Name KOLOSSO TOYOTA		Dealer City APPLETON		State WI	Region CHI	
Primary Model Camry	Model Year 2007	Production Date 28-NOV-06	Odometer 5674 mi	VIN JTNBE46K773 [REDACTED]		
Condition Title Shifting Concerns						

Repair Date 25-OCT-2007	Optional Ref.	Applicable DTC Code(s)
----------------------------	---------------	------------------------

Condition Description

- Customer states the vehicle surges on a steady cruise, vehicle is aggressive while in cruise and going up an incline.
- Vehicle also has a harsh down shift into 1st gear before stop.
- The vehicle has all the latest cal updates.

Diagnostic Steps:

1. Perform health check for any updates
2. Check trans fluid level and monitor data while driving during test drive
3. Compared to like vehicle with same engine ECU calibration and vehicle behaved in the same manner.


Probable Cause

- Unknown

Part # 1: 000000000000	Part # 2:	Part # 3:	Parts Available on Request: No part available	Parts Shipping Destination: CQEC
---------------------------	-----------	-----------	--	-------------------------------------


Repair Process

- Technician advised customer that vehicle is operating as designed at this time.



Health Check Information

DEALERSHIP PRODUCT REPORT



TQCN DOC# PR-48028-2987	Affiliate TMS	Dept. QA-Powertrain	Source MDT/DS	Dealer Code 48028	Ref 32179-1	Date 10/27/2007
Dealer Name KOLOSSO TOYOTA		Dealer City APPLETON		State WI	Region CHI	
Primary Model Camry		Model Year 2007	Production Date 28-NOV-06	Odometer 5674 mi	VIN JTNBE46K773 [REDACTED]	
Condition Title Shifting Concerns						

Attachment 1: Parts Recovery Control Sheet

Do not type in SHADED fields. If the Final Destination field below is "scrap", properly dispose of the part.

Orig Tracking
VIN
Doc No.



Final Destination: CQEC		SETR#:	CQE Eng:	N/A
Importer: (Applies to TMC Shipments Only)		Deliver to:	住所 :	
North America EDER Gr., Technical Dept. #1 Overseas Customer Service Technical Div. TOYOTA MOTOR CORPORATION Nisshin Education & Training Center 5-210, SAKAE, NISSHIN, AICH, 470-0113 Japan		Attn:	宛先 :	
		Tel:	Tel:	
T-STAR				
Note: If this FTR contains more than one VIN, create a table in the report containing VIN, production date, and odometer				FOR CUSTOMS USE: Used Parts Value
1	Part # 1: 000000000000	Part Description	Qty. 1	Used Part Value \$ 0.00
	Comments:			
2	Part # 2:	Part Description	Qty. 0	Used Part Value \$ 0.00
	Comments:			
3	Part # 3:	Part Description	Qty. 0	Used Part Value \$ 0.00
	Comments:			
4	Part # 4:	Part Description	Qty. \$	Used Part Value .00
	Comments:			
5	Part # 5:	Part Description	Qty. \$	Used Part Value .00
	Comments:			
6	Part # 6:	Part Description	Qty. \$	Used Part Value .00
	Comments:			
7	Part # 7:	Part Description	Qty. \$	Used Part Value .00
	Comments:			

DEALERSHIP PRODUCT REPORT



TQCN DOC# PR-39052-2717	Affiliate TMS	Dept. QA-Powertrain	Source MDT/DS	Dealer Code 39052	Ref 43491-1	Date 10/30/2007
Dealer Name JIM HUDSON TOYOTA		Dealer City IRMO		State SC	Region SET	
Primary Model Tundra	Model Year 2007	Production Date 30-MAY-07	Odometer 4120 mi	VIN 5TFRT54147X [REDACTED]		
Condition Title Electronic Controls ECM Surge						

Repair Date 22-SEP-2007	Optional Ref.	Applicable DTC Code(s)
-----------------------------------	---------------	------------------------

Condition Description

Customer states that when sitting in drive stopped that vehicle rpm's will surge up to 1,100.

Diagnostic Steps:

Tested engine controls found no codes or any abnormal readings

Probable Cause

--	--	--	--	--


Part # 1: 896610C800	Part # 2:	Part # 3:	Parts Available on Request: No part available	Parts Shipping Destination: CQEC
-------------------------	-----------	-----------	--	-------------------------------------

Repair Process

none at this time -

--	--	--

DEALERSHIP PRODUCT REPORT



TQCN DOC# PR-39052-2717	Affiliate TMS	Dept. QA-Powertrain	Source MDT/DS	Dealer Code 39052	Ref 43491-1	Date 10/30/2007
Dealer Name JIM HUDSON TOYOTA		Dealer City IRMO		State SC	Region SET	
Primary Model Tundra	Model Year 2007	Production Date 30-MAY-07	Odometer 4120 mi	VIN 5TFRT54147X [REDACTED]		
Condition Title Electronic Controls ECM Surge						

Attachment 1: Parts Recovery Control Sheet

Do not type in SHADED fields. If the Final Destination field below is "scrap", properly dispose of the part.

Orig Tracking
VIN [REDACTED]
Doc No. [REDACTED]



Final Destination: CQEC		SETR#:	CQE Eng:	N/A
Importer: (Applies to TMC Shipments Only)		Deliver to:	住所 :	
North America EDER Gr., Technical Dept. #1 Overseas Customer Service Technical Div. TOYOTA MOTOR CORPORATION Nisshin Education & Training Center 5-210, SAKAE, NISSHIN, AICH, 470-0113 Japan		Attn:	宛先 :	
		Tel:	Tel:	
T-STAR				
Note: If this FTR contains more than one VIN, create a table in the report containing VIN, production date, and odometer				FOR CUSTOMS USE: Used Parts Value
1	Part # 1: 896610C800 Comments:	Part Description COMPUTER, ENGINE CONTROL	Qty. 1	Used Part Value \$ 132.00
2	Part # 2: Comments:	Part Description	Qty. 0	Used Part Value \$ 0.00
3	Part # 3: Comments:	Part Description	Qty. 0	Used Part Value \$ 0.00
4	Part # 4: Comments:	Part Description	Qty. \$	Used Part Value .00
5	Part # 5: Comments:	Part Description	Qty. \$	Used Part Value .00
6	Part # 6: Comments:	Part Description	Qty. \$	Used Part Value .00
7	Part # 7: Comments:	Part Description	Qty. \$	Used Part Value .00

FIELD TECHNICAL REPORT

TQCN DOC# FTR-7ZK131071		Affiliate TMS	Dept. QA-Powertrain	Source FTS	Location TMS-NY	Ref 33236-3	Date 11/6/2007
Problem Area Base Vehicle	Primary Model Camry	Model Year 2007	Production Date 12-Jul-2007	Odometer 1435 mi	VIN (confirm 17 characters): 4T1BE46K97U [REDACTED]		
Condition Title Post C/M Hesitation on Acceleration from a Stop and at 35-50MPH							

Do not type in YELLOW shaded fields - Input data from Web page or RDM:

Repair Date 01-NOV-2007	Optional Ref.	Optional Approval
-----------------------------------	---------------	-------------------

Condition Description

- Customer states vehicle does not accelerate when gas pedal is depressed. TSB has already been completed on Oct.3, 2007.
- When traveling 30-40 MPH in the City and attempting to keep up with traffic vehicle will not accelerate when accelerator is depressed up to a ¼ of the way down.
- When traveling a low speeds and attempting to accelerate vehicle will not accelerate when accelerator is depressed up to a ¼ of the way down.
- When continuing to depress throttle pedal past 1/4 of the way vehicle will downshift abruptly and accelerate much faster then expected.
- Customer is afraid to drive vehicle.

Diagnostic Steps:

- FTS inspected and found vehicle had most current calibration file from bulletin EG036-07 previously installed.
- FTS test drove vehicle and noted vehicle operates consistently with other Camry's that the technician has updated with bulleting EG036-07.
- FTS recorded snapshot using tech stream of acceleration events for review.

Probable Cause

- Unknown

Part # 1: N/A	Part # 2:	Part # 3:	Parts Disposition: No part available	Parts Shipping Destination: N/A
------------------	-----------	-----------	---	------------------------------------

Repair Process

- No repairs attempted, vehicle has most current ECU calibration



Techstream Snapshot at 45MPH Accelerating To Keep Up With Traffic

Attachment 1: PRCS

FIELD TECHNICAL REPORT



TQCN DOC# FTR-7ZK131071		Affiliate TMS	Dept. QA-Powertrain	Source FTS	Location TMS-NY	Ref 33236-3	Date 11/6/2007
Problem Area Base Vehicle	Primary Model Camry	Model Year 2007	Production Date 12-Jul-2007	Odometer 1435 mi	VIN (confirm 17 characters): 4T1BE46K97U [REDACTED]		
Condition Title Post C/M Hesitation on Acceleration from a Stop and at 35-50MPH							

Attachment 1: Parts Recovery Control Sheet

Do not type in SHADED fields. If the **Final Destination** field below is "scrap", properly dispose of the part.

Orig Tracking

VIN

Doc No.



Final Destination: N/A	SETR#:	CQE Eng: N/A
-------------------------------	---------------	---------------------

Importer: (Applies to TMC Shipments Only) Mr. N. Okumura, Chief Expert Quality Div. Warranty Parts Room TOYOTA MOTOR CORPORATION 1 Toyota, Toyota-city, Aichi, 471-8571 Japan	Deliver to:	住所 :
	Attn:	宛先 :
	Tel:	TEL :

T-STAR		
--------	--	--

Note: If this FTR contains more than one VIN, create a table in the report containing VIN, production date, and odometer

FOR CUSTOMS USE:
Used Parts Value

	Part # 1:	Part Description	Qty.	Used Part Value
1	N/A		1	\$ 0.00
	Comments:			
2			0	\$ 0.00
	Comments:			
3			0	\$ 0.00
	Comments:			
4				\$.00
	Comments:			
5				\$.00
	Comments:			
6				\$.00
	Comments:			
7				\$.00
	Comments:			
8				\$.00
	Comments:			

DEALERSHIP PRODUCT REPORT



TQCN DOC# TQCN_DPR-080860012	Affiliate TMS	Dept. QAPowertrain	Source MDT/DS	Dealer Code 63105	Ref 80883282	Date 03/28/2008
Dealer Name RALLYE LEXUS		Dealer City GLEN COVE		State NY	Region EAS	
Primary Model ES350	Model Year 2008	Production Date 10-SEP-07	Odometer 4989 mi	VIN JTHBJ46G882 [REDACTED]		
Condition Title U660E: Harsh Downshift when Accelerating from 40 MPH						

Repair Date 3/25/2008	Optional Ref.	Applicable DTC Code(s)
--------------------------	---------------	------------------------

Condition Description

- Customer states at around 40 MPH when reaccelerating the vehicle jerks

Diagnostic Steps:

- Road tested vehicle and confirmed condition, checked fluid level, for dtc's and shift program updates

Probable Cause


- The car is performing the same as other like vehicles. It is the "pause" while the ECM decided what gear to downshift to.

Part # 1: 000000000000	Part # 2:	Part # 3:	Parts Available on Request: No part available	Parts Shipping Destination: CQE
---------------------------	-----------	-----------	--	------------------------------------

Repair Process

- None, vehicle is operating as designed.

DEALERSHIP PRODUCT REPORT



TQCN DOC# TQCN_DPR-080860012	Affiliate TMS	Dept. QAPowertrain	Source MDT/DS	Dealer Code 63105	Ref 80883282	Date 03/28/2008
Dealer Name RALLYE LEXUS		Dealer City GLEN COVE		State NY	Region EAS	
Primary Model ES350		Model Year 2008	Production Date 10-SEP-07	Odometer 4989 mi	VIN JTHBJ46G882 [REDACTED]	
Condition Title U660E: Harsh Downshift when Accelerating from 40 MPH						

Attachment 1: Parts Recovery Control Sheet

Orig Tracking
VIN




Do not type in SHADED fields. If the Final Destination field below is "scrap", properly dispose of the part.

Doc No.



Final Destination:	CQE	SETR#:		CQE Eng:	N/A
Importer: (Applies to TMC Shipments Only)	Deliver to:		住所 :		
Mr. N. Okumura, Chief Expert Quality Div. Warranty Parts Room TOYOTA MOTOR CORPORATION 1 Toyota, Toyota-city, Aichi, 471-8571 Japan	Attn:		宛先 :		
	Tel:		Tel:		
T-STAR					
Note: If this FTR contains more than one VIN, create a table in the report containing VIN, production date, and odometer					FOR CUSTOMS USE: Used Parts Value Each
1	Part # 1: 000000000000	Part Description TEST PART	Qty. 0	Used Part Value Each \$ 0	
	Comments:				
2	Part # 2:	Part Description	Qty.	Used Part Value Each \$	
	Comments:				
3	Part # 3:	Part Description	Qty.	Used Part Value Each \$	
	Comments:				
4	Part # 4:	Part Description	Qty.	Used Part Value Each \$	
	Comments:				
5	Part # 5:	Part Description	Qty.	Used Part Value Each \$	
	Comments:				
6	Part # 6:	Part Description	Qty.	Used Part Value Each \$	
	Comments:				

FIELD TECHNICAL REPORT



TQCN DOC# TQCN_FTR-080910035		Affiliate TMS	Dept. QA Powertrain	Source FTS	Location REG-POR	Ref 80270115	Date 04/04/2008
Problem Area Base Vehicle	Primary Model Camry	Model Year 2005	Production Date 2005-06-17	Odometer 38,515	VIN (confirm 17 characters): JTDBE32K453 [REDACTED]		
Condition Title 2AZ-FE: Vehicle Surges on Acceleration							

Do not type in YELLOW shaded fields - Input data from Web page or RDM:

Repair Date 3/3/2008	Optional Ref.	Optional Approval
-------------------------	---------------	-------------------

Condition Description

- Customer states that there is a surge on moderate to heavy acceleration between 30-50 mph.

Diagnostic Steps:

- Verified customer's complaint during road test.
- Performed health check and no codes were present.
- While driving the vehicle at the time of the concern data list showed no miss fires.
- Readings were within repair manual specifications for the following data parameters:
 - MAF ○ Ignition Timing ○ Fuel Trims
 - RPM ○ Knock ○ TP
 - VVT-i ○ ECT ○ APP
- Found that A/F sensor voltage appeared to be erratic when all other monitors were linear.
- After disconnecting the A/F sensor and driving the vehicle the concern was no longer present.

Probable Cause

- Unknown


Part # 1: 8946733080	Part # 2:	Part # 3:	Parts Disposition: Special request only	Parts Shipping Destination: CQE
-------------------------	-----------	-----------	--	------------------------------------

Repair Process

<p>A/F Sensor voltage compared to downstream O2 sensor voltage at the time of the surge</p>	<p>A/F Sensor 89467-33080</p>

Attachment 1: PRCS

FIELD TECHNICAL REPORT



TQCN DOC# TQCN_FTR-080910035		Affiliate TMS	Dept. QAPowertrain	Source FTS	Location REG-POR	Ref 80270115	Date 04/04/2008
Problem Area Base Vehicle	Primary Model Camry	Model Year 2005	Production Date 2005-06-17	Odometer 38,515	VIN (confirm 17 characters): JTDBE32K453 [REDACTED]		
Condition Title 2AZ-FE: Vehicle Surges on Acceleration							

Attachment 1: **Parts Recovery Control Sheet**

Orig Tracking
VIN
Doc No.



Do not type in SHADED fields. If the Final Destination field below is "scrap", properly dispose of the part.



Final Destination: CQE		SETR#:	CQE Eng:	N/A
Importer: (Applies to TMC Shipments Only)		Deliver to:		住所:
Mr. N. Okumura, Chief Expert Quality Div. Warranty Parts Room TOYOTA MOTOR CORPORATION 1 Toyota, Toyota-city, Aichi, 471-8571 Japan		Attn:		宛先:
		Tel:		Tel:
T-STAR				
Note: If this FTR contains more than one VIN, create a table in the report containing VIN, production date, and odometer				FOR CUSTOMS USE: Used Parts Value
1	Part # 1: 8946733080	Part Description SENSOR, AIR FUEL RATIO	Qty. 1	Used Part Value Each \$ 31.08
	Comments:			
2	Part # 2:	Part Description	Qty.	Used Part Value Each \$
	Comments:			
3	Part # 3:	Part Description	Qty.	Used Part Value Each \$
	Comments:			
4	Part # 4:	Part Description	Qty.	Used Part Value Each \$
	Comments:			
5	Part # 5:	Part Description	Qty.	Used Part Value Each \$
	Comments:			

DEALERSHIP PRODUCT REPORT



TQCN DOC# TQCN_DPR-080890008	Affiliate TMS	Dept. QAPowertrain	Source MDT/DS	Dealer Code 64107	Ref 80953695	Date 04/04/2008
Dealer Name LEXUS OF MEMPHIS		Dealer City MEMPHIS		State TN	Region SOU	
Primary Model LS460	Model Year 2007	Production Date 02-AUG-07	Odometer 6224 mi	VIN JTHGL46F475 [REDACTED]		
Condition Title Customer states vehicle lunge while braking						

Repair Date 3/25/2008	Optional Ref.	Applicable DTC Code(s)
--------------------------	---------------	------------------------

Condition Description

Customer states that when applying the brake at 20-30 mph car will start to brake, then jerk and lunge forward about 5 feet before stopping. Happened 3 times but is intermittent.

Diagnostic Steps:

Drove vehicle to try and verify and duplicate the concern but could not get it to do how customer described. Did feel a slight surge as car slowed down and transmission would downshift, as it did the engine rpm's would raise.

Probable Cause

Unknown

Part # 1: 4405050130	Part # 2: 3500050160	Part # 3:	Parts Available on Request: No part available	Parts Shipping Destination: CQE
-------------------------	-------------------------	-----------	--	------------------------------------

Repair Process

Called and talked with FTS. We checked the transmission fluid level which was good, as well as brake operation. There was a plastic floor mat near accelerator pedal, do not know if this had anything to do with concern or not but fastened it out of the way anyway. Talked with customer, they will keep an eye on issue and let us know.

--	--	--

DEALERSHIP PRODUCT REPORT



TQCN DOC# TQCN_DPR-080890008	Affiliate TMS	Dept. QAPowertrain	Source MDT/DS	Dealer Code 64107	Ref 80953695	Date 04/04/2008
Dealer Name LEXUS OF MEMPHIS		Dealer City MEMPHIS		State TN	Region SOU	
Primary Model LS460	Model Year 2007	Production Date 02-AUG-07	Odometer 6224 mi	VIN JTHGL46F475 [REDACTED]		
Condition Title Customer states vehicle lunge while braking						

Attachment 1: Parts Recovery Control Sheet

Orig Tracking
VIN [REDACTED]

Do not type in SHADED fields. If the Final Destination field below is "scrap", properly dispose of the part.

Doc No. [REDACTED]



Final Destination: CQE	SETR#:	CQE Eng:	N/A
Importer: (Applies to TMC Shipments Only) Mr. N. Okumura, Chief Expert Quality Div. Warranty Parts Room TOYOTA MOTOR CORPORATION 1 Toyota, Toyota-city, Aichi, 471-8571 Japan	Deliver to: Attn: Tel:	住所: 宛先: Tel:	

T-STAR



Note: If this FTR contains more than one VIN, create a table in the report containing VIN, production date, and odometer

FOR CUSTOMS USE: Used Parts Value Each

	Part #	Part Description	Qty.	Used Part Value Each
1	4405050130	ACTUATOR ASSY, BRAKE W/FLUID	1	\$ 276.33
Comments:				
2	3500050160	TRANSMISSION ASSY	1	\$ 1,186.23
Comments:				
3				\$
Comments:				
4				\$
Comments:				
5				\$
Comments:				
6				\$
Comments:				

DEALERSHIP PRODUCT REPORT



TQCN DOC# TQCN_DPR-080990041	Affiliate TMS	Dept. QAPowertrain	Source MDT/DS	Dealer Code 62906	Ref 81054279	Date 04/14/2008
Dealer Name LAWRENCE LEXUS		Dealer City LAWRENCEVILLE		State NJ	Region EAS	
Primary Model ES350	Model Year 2008	Production Date 21-DEC-07	Odometer 2555 mi	VIN JTHBJ46G082 [REDACTED]		
Condition Title U660E: Harsh Downshift on Reacceleration from 30 MPH						

Repair Date 4/8/2008	Optional Ref.	Applicable DTC Code(s)
-------------------------	---------------	------------------------

Condition Description

- When going from 50 to 30 mph and then reaccelerating, transaxle jerks.

Diagnostic Steps:

- No codes stored.
- Inspected transaxle fluid level

Probable Cause

- Fluid level was between 1 to 1.5 quarts low.

Part # 1: 00289ATFWS	Part # 2:	Part # 3:	Parts Available on Request: No part available	Parts Shipping Destination: CQE
-------------------------	-----------	-----------	--	------------------------------------

Repair Process

- Performed fluid procedure and reset ECT memory


DEALERSHIP PRODUCT REPORT



TQCN DOC# TQCN_DPR-080990041	Affiliate TMS	Dept. QAPowertrain	Source MDT/DS	Dealer Code 62906	Ref 81054279	Date 04/14/2008
Dealer Name LAWRENCE LEXUS		Dealer City LAWRENCEVILLE		State NJ	Region EAS	
Primary Model ES350		Model Year 2008	Production Date 21-DEC-07	Odometer 2555 mi	VIN JTHBJ46G082 [REDACTED]	
Condition Title U660E: Harsh Downshift on Reacceleration from 30 MPH						

Attachment 1: Parts Recovery Control Sheet			Orig Tracking VIN	[REDACTED]
Do not type in SHADED fields. If the Final Destination field below is "scrap", properly dispose of the part.			Doc No.	[Barcode]
Final Destination:	CQE	SETR#:	CQE Eng:	N/A
Importer: (Applies to TMC Shipments Only)	Deliver to:		住所 :	
Mr. N. Okumura, Chief Expert Quality Div. Warranty Parts Room TOYOTA MOTOR CORPORATION 1 Toyota, Toyota-city, Aichi, 471-8571 Japan	Attn:		宛先 :	
	Tel:		Tel:	
T-STAR	[Barcode]	[Barcode]	[Barcode]	[Barcode]
Note: If this FTR contains more than one VIN, create a table in the report containing VIN, production date, and odometer				FOR CUSTOMS USE: Used Parts Value Each
1	Part # 1: 00289ATFWS	Part Description WORLD STANDARD AUTOMATIC TRANSMISSION FL	Qty. 2	Used Part Value Each \$ 0.86
	Comments:			
2	Part # 2:	Part Description	Qty.	Used Part Value Each \$
	Comments:			
3	Part # 3:	Part Description	Qty.	Used Part Value Each \$
	Comments:			
4	Part # 4:	Part Description	Qty.	Used Part Value Each \$
	Comments:			
5	Part # 5:	Part Description	Qty.	Used Part Value Each \$
	Comments:			
6	Part # 6:	Part Description	Qty.	Used Part Value Each \$
	Comments:			

DEALERSHIP PRODUCT REPORT



TQCN DOC# TQCN_DPR-082540019	Affiliate TMS	Dept. QAPowertrain	Source MDT/DS	Dealer Code 60404	Ref 80802620	Date 09/16/2008
Dealer Name LEXUS CARLSBAD		Dealer City CARLSBAD		State CA	Region WES	
Primary Model RX330	Model Year 2005	Production Date 27-MAY-05	Odometer 44055 mi	VIN JTJGA31U250 [REDACTED]		
Condition Title Drivability Concerns						

Repair Date 8/19/2008	Optional Ref.	Applicable DTC Code(s)
--------------------------	---------------	------------------------

Condition Description

- Customer states the vehicle jerks and hesitates upon hard acceleration.

Diagnostic Steps:

- Inspected engine control system with Techstream for any malfunctions and found none.
- Road tested and confirmed that vehicle operates as designed.
- Searched TSIB's for related concerns – found TSIB TC005-03

Probable Cause


- Customer driving style and transaxle programming logic.

Part # 1: N/A	Part # 2:	Part # 3:	Parts Available on Request: No part available	Parts Shipping Destination: CQE
------------------	-----------	-----------	--	------------------------------------

Repair Process

- Performed update per TSIB TC005-03.
- The vehicle was delivered to the customer and after they drove the vehicle they feel the repair done was not satisfactory.
- Advised customer that no other repair is available or necessary.
- Customer states they are very unhappy with this condition and states this is not something a Lexus should do.

DEALERSHIP PRODUCT REPORT



TQCN DOC# TQCN_DPR-082540019	Affiliate TMS	Dept. QAPowertrain	Source MDT/DS	Dealer Code 60404	Ref 80802620	Date 09/16/2008
Dealer Name LEXUS CARLSBAD		Dealer City CARLSBAD		State CA	Region WES	
Primary Model RX330		Model Year 2005	Production Date 27-MAY-05	Odometer 44055 mi	VIN JTJGA31U250 [REDACTED]	
Condition Title Drivability Concerns						

Attachment 1: Parts Recovery Control Sheet			Orig Tracking VIN	[REDACTED]
Do not type in SHADED fields. If the Final Destination field below is "scrap", properly dispose of the part.			Doc No.	[Barcode]
Final Destination:	CQE	SETR#:	CQE Eng:	N/A
Importer: (Applies to TMC Shipments Only)	Deliver to:		住所 :	
Mr. N. Okumura, Chief Expert Quality Div. Warranty Parts Room TOYOTA MOTOR CORPORATION 1 Toyota, Toyota-city, Aichi, 471-8571 Japan	Attn:		宛先 :	
	Tel:		Tel:	
T-STAR	[Barcode]	[Barcode]		
Note: If this FTR contains more than one VIN, create a table in the report containing VIN, production date, and odometer				FOR CUSTOMS USE: Used Parts Value Each
1	Part # 1: N/A	Part Description n/a	Qty. 1	Used Part Value Each \$ 0.00
Comments:				
2	Part # 2:	Part Description	Qty.	Used Part Value Each \$
Comments:				
3	Part # 3:	Part Description	Qty.	Used Part Value Each \$
Comments:				
4	Part # 4:	Part Description	Qty.	Used Part Value Each \$
Comments:				
5	Part # 5:	Part Description	Qty.	Used Part Value Each \$
Comments:				
6	Part # 6:	Part Description	Qty.	Used Part Value Each \$
Comments:				

DEALERSHIP PRODUCT REPORT



TQCN DOC# TQCN_DPR-082740007	Affiliate TMS	Dept. QAPowertrain	Source MDT/DS	Dealer Code 60105	Ref 80271890	Date 10/23/2008
Dealer Name TOM WILLIAMS LEXUS		Dealer City IRONDALE		State AL	Region SOU	
Primary Model RX350	Model Year 2008	Production Date 05-DEC-07	Odometer 10029 mi	VIN 2T2GK31U18C [REDACTED]		
Condition Title Hesitation/Harsh Downshift Concern on Reacceleration from Low Vehicle Speed (U151E)						

Repair Date 9/30/2008	Optional Ref.	Applicable DTC Code(s)
--------------------------	---------------	------------------------

Condition Description

- Customer states: "When slowing down to go through a yield sign and then reaccelerate, the vehicle hesitates, jerks and slams into gear."
- Vehicle speed on reacceleration is approximately 5-10 MPH.

Diagnostic Steps:

- Test drove to try to confirm customer concern.

Probable Cause


- Unknown.

Part # 1: N/A	Part # 2:	Part # 3:	Parts Available on Request: No part available	Parts Shipping Destination: CQE
------------------	-----------	-----------	--	------------------------------------

Repair Process

- Normal operation observed during test drive. (no duplication) Information only.

DEALERSHIP PRODUCT REPORT



TQCN DOC# TQCN_DPR-082740007	Affiliate TMS	Dept. QAPowertrain	Source MDT/DS	Dealer Code 60105	Ref 80271890	Date 10/23/2008
Dealer Name TOM WILLIAMS LEXUS		Dealer City IRONDALE		State AL	Region SOU	
Primary Model RX350	Model Year 2008	Production Date 05-DEC-07	Odometer 10029 mi	VIN 2T2GK31U18C [REDACTED]		
Condition Title Hesitation/Harsh Downshift Concern on Reacceleration from Low Vehicle Speed (U151E)						

Attachment 1: Parts Recovery Control Sheet			Orig Tracking VIN	[REDACTED]
Do not type in SHADED fields. If the Final Destination field below is "scrap", properly dispose of the part.			Doc No.	[Barcode]
Final Destination:	CQE	SETR#:	CQE Eng:	N/A
Importer: (Applies to TMC Shipments Only)	Deliver to:		住所 :	
Mr. N. Okumura, Chief Expert Quality Div. Warranty Parts Room TOYOTA MOTOR CORPORATION 1 Toyota, Toyota-city, Aichi, 471-8571 Japan	Attn:		宛先 :	
	Tel:		Tel:	
T-STAR	[Barcode]	[Barcode]		
Note: If this FTR contains more than one VIN, create a table in the report containing VIN, production date, and odometer				FOR CUSTOMS USE: Used Parts Value Each
1	Part # 1: N/A	Part Description n/a	Qty. 1	Used Part Value Each \$ 0.00
Comments:				
2	Part # 2:	Part Description	Qty.	Used Part Value Each \$
Comments:				
3	Part # 3:	Part Description	Qty.	Used Part Value Each \$
Comments:				
4	Part # 4:	Part Description	Qty.	Used Part Value Each \$
Comments:				
5	Part # 5:	Part Description	Qty.	Used Part Value Each \$
Comments:				
6	Part # 6:	Part Description	Qty.	Used Part Value Each \$
Comments:				

DEALERSHIP PRODUCT REPORT



TQCN DOC# TQCN_DPR-082960026	Affiliate TMS	Dept. QAPowertrain	Source MDT/DS	Dealer Code 63408	Ref 82976526	Date 10/23/2008
Dealer Name METRO LEXUS		Dealer City CLEVELAND		State OH	Region CEN	
Primary Model GS350		Model Year 2008	Production Date 30-OCT-07	Odometer 6456 mi	VIN JTHCE96S380 [REDACTED]	
Condition Title Engine Surge						

Repair Date 10/22/2008	Optional Ref.	Applicable DTC Code(s)
---------------------------	---------------	------------------------

Condition Description

Customer states the car will surge forward when stopped. It has happened 4 times to customer and once to his wife.

Diagnostic Steps:

Test drove vehicle and the condition did not present itself. Performed DTC check and no DTCs were present.

Probable Cause

Unknown.

Part # 1: 4711030440	Part # 2:	Part # 3:	Parts Available on Request: No part available	Parts Shipping Destination: CQE
-------------------------	-----------	-----------	--	------------------------------------

Repair Process

No repairs performed.

--	--	--

DEALERSHIP PRODUCT REPORT



TQCN DOC# TQCN_DPR-082960026	Affiliate TMS	Dept. QAPowertrain	Source MDT/DS	Dealer Code 63408	Ref 82976526	Date 10/23/2008
Dealer Name METRO LEXUS		Dealer City CLEVELAND		State OH	Region CEN	
Primary Model GS350		Model Year 2008	Production Date 30-OCT-07	Odometer 6456 mi	VIN JTHCE96S380 [REDACTED]	
Condition Title Engine Surge						

Attachment 1: Parts Recovery Control Sheet

Orig Tracking
VIN [REDACTED]

Do not type in SHADED fields. If the Final Destination field below is "scrap", properly dispose of the part.

Doc No.



Final Destination: CQE	SETR#:	CQE Eng:	N/A
Importer: (Applies to TMC Shipments Only) Mr. N. Okumura, Chief Expert Quality Div. Warranty Parts Room TOYOTA MOTOR CORPORATION 1 Toyota, Toyota-city, Aichi, 471-8571 Japan	Deliver to: Attn: Tel:	住所: 宛先: Tel:	

T-STAR



Note: If this FTR contains more than one VIN, create a table in the report containing VIN, production date, and odometer

FOR CUSTOMS USE: Used Parts Value Each

	Part # 1:	Part Description	Qty.	Used Part Value Each
1	4711030440	SUPPORT ASSY, BRAKE PEDAL	1	\$ 23.72
	Comments:			
2	Part # 2:	Part Description	Qty.	Used Part Value Each
	Comments:			
3	Part # 3:	Part Description	Qty.	Used Part Value Each
	Comments:			
4	Part # 4:	Part Description	Qty.	Used Part Value Each
	Comments:			
5	Part # 5:	Part Description	Qty.	Used Part Value Each
	Comments:			
6	Part # 6:	Part Description	Qty.	Used Part Value Each
	Comments:			

DEALERSHIP PRODUCT REPORT



TQCN DOC# TQCN_DPR-083040051	Affiliate TMS	Dept. QAPowertrain	Source MDT/DS	Dealer Code 61031	Ref 80661670	Date 11/04/2008
Dealer Name NALLEY LEXUS - ROSWELL		Dealer City ROSWELL		State GA	Region SOU	
Primary Model ES350	Model Year 2008	Production Date 15-OCT-07	Odometer 8611 mi	VIN JTHBJ46G382 [REDACTED]		
Condition Title Harsh 3-2 Downshift on Reacceleration (U660E)						

Repair Date 10/30/2008	Optional Ref.	Applicable DTC Code(s)
---------------------------	---------------	------------------------

Condition Description

- The customer states that the transmission jerks while driving in stop and go traffic.

Diagnostic Steps:

- Test drove to verify the condition.
- Test drove with Techstream and recorded a snapshot.
- The transaxle downshifts hard from third to second gear when using moderate throttle at about 16 MPH.
- It is also easier to duplicate with the transaxle temperature below about 100 degrees F.



Probable Cause

- Unknown


Part # 1: N/A	Part # 2:	Part # 3:	Parts Available on Request: No part available	Parts Shipping Destination: CQE
------------------	-----------	-----------	--	------------------------------------

Repair Process

- Compared the customer's car with another 2008 ES 350 with 10,583 miles.
- It felt the same as the customer's car under the same conditions.
- Transaxle serial number: 2A07K102239

 zRDMObjectFile2.zip	 zRDMObjectFile.zip
Customer vehicle	Comparison vehicle
Techstream Snapshot Attachments	

DEALERSHIP PRODUCT REPORT



TQCN DOC# TQCN_DPR-083040051	Affiliate TMS	Dept. QAPowertrain	Source MDT/DS	Dealer Code 61031	Ref 80661670	Date 11/04/2008
Dealer Name NALLEY LEXUS - ROSWELL		Dealer City ROSWELL		State GA	Region SOU	
Primary Model ES350	Model Year 2008	Production Date 15-OCT-07	Odometer 8611 mi	VIN JTHBJ46G382 [REDACTED]		
Condition Title Harsh 3-2 Downshift on Reacceleration (U660E)						

Attachment 1: Parts Recovery Control Sheet			Orig Tracking VIN	[REDACTED]
Do not type in SHADED fields. If the Final Destination field below is "scrap", properly dispose of the part.			Doc No.	[Barcode]
Final Destination:	CQE	SETR#:	CQE Eng:	N/A
Importer: (Applies to TMC Shipments Only)	Deliver to:		住所 :	
Mr. N. Okumura, Chief Expert Quality Div. Warranty Parts Room TOYOTA MOTOR CORPORATION 1 Toyota, Toyota-city, Aichi, 471-8571 Japan	Attn:		宛先 :	
	Tel:		Tel:	
T-STAR	[Barcode]	[Barcode]		
Note: If this FTR contains more than one VIN, create a table in the report containing VIN, production date, and odometer				FOR CUSTOMS USE: Used Parts Value Each
1	Part # 1: N/A	Part Description n/a	Qty. 1	Used Part Value Each \$ 0.00
Comments:				
2	Part # 2:	Part Description	Qty.	Used Part Value Each \$
Comments:				
3	Part # 3:	Part Description	Qty.	Used Part Value Each \$
Comments:				
4	Part # 4:	Part Description	Qty.	Used Part Value Each \$
Comments:				
5	Part # 5:	Part Description	Qty.	Used Part Value Each \$
Comments:				
6	Part # 6:	Part Description	Qty.	Used Part Value Each \$
Comments:				

DEALERSHIP PRODUCT REPORT



TQCN DOC# TQCN_DPR-091140001		Affiliate TMS	Dept. QAElectrical		Dealer Code 60906	Ref 91184816	Date 04/28/2009
Dealer Name LEXUS OF ORLANDO			Dealer City WINTER PARK		State FL	Region SOU	Source TECH
Primary Model GS300			Model Year 2006	Production Date 07-APR-06	Odometer 34626 mi	VIN JTHCH96S360 [REDACTED]	
Part # 1: 883203A310	Part # 2: 884103A290	Part # 3:		Parts Destination: CQE	Parts Available: Available upon request	Repair Date 4/23/2009	
Condition Title HVAC-Engine Idle Surge (A/C Compressor)					Applicable DTC Code(s)		

Condition Description

Idle surges when vehicle stopped. Problem was duplicated

Diagnostic Steps:


Verified idle surge at stop only with A/C on. Low side pressure fluctuating between 29 psi and 42 psi causing idle surge.

Probable Cause

Internal compressor failure.

Repair Process

Replaced A/C compressor and clutch



VIN: JTHCH96S360 [REDACTED] Mile: 34,626 RO# 36504 LEXUS OF ORLANDO

DEALERSHIP PRODUCT REPORT




TQCN DOC# TQCN_DPR-091140001		Condition Title HVAC-Engine Idle Surge (A/C Compressor)			Date 04/28/2009
Primary Model GS300	Model Year 2006	Production Date 07-APR-06	Odometer 34626 mi	VIN JTHCH96S360 [REDACTED]	

Attachment 1: Parts Recovery Control Sheet		Orig Tracking	[REDACTED]
		VIN	
Do not type in SHADED fields. If the Final Destination field below is "scrap", properly dispose of the part.		Doc No.	
Final Destination: CQE	SETR#:	CQE Eng:	
Importer: (Applies to TMC Shipments Only) Mr. N. Okumura, Chief Expert Quality Div. Warranty Parts Room TOYOTA MOTOR CORPORATION 1 Toyota, Toyota-city, Aichi, 471-8571 Japan	Deliver to: Attn: Tel:	住所 : 宛先 : Tel:	

			VALUE FOR CUSTOMS USE:	
	Part # 1:	Part Description	Qty.	Used Part Value Each
1	883203A310	COMPRESSOR ASSY	1	\$ 213.53
	Comments:			
2	884103A290	CLUTCH ASSY, MAGNET	1	\$ 89.51
	Comments:			
3	Part # 3:	Part Description	Qty.	Used Part Value Each
				\$
	Comments:			

FIELD TECHNICAL REPORT



TQCN DOC# TQCN_FTR-091630034		Affiliate TMS		Dept. QAHybrid		Ref 91677367	Date 06/16/2009
Primary Model RX450H		Model Year 2010	Production Date 2009-03-25	Odometer 451	VIN JTJZB1BAXA2 [REDACTED]		Repair Date 6/12/2009
Source FTS	Location AREA-WESTERN	Problem Area Base Vehicle		Parts Destination CQE	DTC		
Part # 1 0000000000	Part # 1 Serial/Date Code		Part # 2	Part # 2 Serial/Date Code		Parts Available No Part(s) Available	
Condition Title Surging at Freeway Speeds							

Condition Description

FTS noted the vehicle exhibits a non rhythmic surge under the following conditions:

- Driving vehicle at 65 to 75 mph on a smooth and flat road.
- Maintaining a constant speed as needed with steady throttle in put.
- The sensation is in frequency with the energy monitor as it changes from “engine drive” to “battery drive” to “battery charge”.
- The sensation is like a slow speed up and slow speed down as the computer changes between “engine, battery, and charge control”.
- The sensation is not present with cruise control set.
- Another description of the condition is like a slow rocking motion.

Diagnostic Steps


FTS has only driven this one vehicle. No other vehicles were available for comparison.

Probable Cause


Unknown.

Repair Process

No repairs performed.



FIELD TECHNICAL REPORT



TQCN DOC# TQCN_FTR-091630034		Condition Title Surging at Freeway Speeds			Date 06/16/2009
Primary Model RX450H	Model Year 2010	Production Date 2009-03-25	Odometer 451	VIN (confirm 17 characters): JTJZB1BAXA2 [REDACTED]	

Orig
Tracking

Attachment 1: Parts Recovery Control Sheet

Do not type in SHADED fields. If the Final Destination field below is "scrap", properly dispose of the part.

VIN

Doc No.



Final Destination: CQE	SETR#:	CQE Eng:	N/A
Importer: (Applies to TMC Shipments Only) Mr. N. Okumura, Chief Expert Quality Div. Warranty Parts Room TOYOTA MOTOR CORPORATION 1 Toyota, Toyota-city, Aichi, 471-8571 Japan	Deliver to: Attn: Tel:	住所: 宛先: Tel:	
T-STAR			
Note: If this FTR contains more than one VIN, create a table in the report containing VIN, production date, and odometer			FOR CUSTOMS USE: Used Parts Value

Part #	Part #	Part Description	Qty.	Used Part Value Each
1	0000000000		1	\$ 0.00
	Serial No. / Date Code		Comments:	
2				\$
	Serial No. / Date Code		Comments:	
3				\$
	Serial No. / Date Code		Comments:	
4				\$
	Serial No. / Date Code		Comments:	
5				\$
	Serial No. / Date Code		Comments:	
6				\$
	Serial No. / Date Code		Comments:	
7				\$
	Serial No. / Date Code		Comments:	

DEALERSHIP PRODUCT REPORT



TQCN DOC# TQCN_DPR-092470009		Affiliate TMS	Dept. QAPowertrain		Dealer Code 60105	Ref 92521987	Date 09/09/2009
Dealer Name TOM WILLIAMS LEXUS			Dealer City IRONDALE		State AL	Region SOU	Source TECH
Primary Model LX470		Model Year 2007	Production Date 09-MAR-07		Odometer 34925 mi	VIN JTJHT00W374 [REDACTED]	
Part # 1: 2322050160	Part # 2:	Part # 3:		Parts Destination: CQE	Parts Available: Available upon request	Repair Date 9/4/2009	
Condition Title Surge at 2200 RPMs - Fuel Pump					Applicable DTC Code(s)		

Condition Description

- Customer states the engine surges, especially going up an incline
- The condition is most noticeable with engine RPM at approximately 2200 rpm

Diagnostic Steps:

- Inspected fuel pressure, observed gauge moving from 2.25 bar to 3.25 bars during surge
- Inspected fuel pump relay control voltage which was correct and constant
- Inspected fuel pump resistor resistance, correct at 1 ohm

Probable Cause

- Unknown

Repair Process

- Replaced fuel pump

DEalersHIP PRODUCT REPORT



TQCN DOC# TQCN_DPR-092470009		Condition Title Surge at 2200 RPMs - Fuel Pump			Date 09/09/2009
Primary Model LX470	Model Year 2007	Production Date 09-MAR-07	Odometer 34925 mi	VIN JTJHT00W374 [REDACTED]	

Attachment 1: Parts Recovery Control Sheet		Orig Tracking	[REDACTED]
Do not type in SHADED fields. If the Final Destination field below is "scrap", properly dispose of the part.		VIN	
		Doc No.	
Final Destination: CQE		SETR#:	CQE Eng:
Importer: (Applies to TMC Shipments Only)	Deliver to:	住所 :	
Mr. N. Okumura, Chief Expert Quality Div. Warranty Parts Room TOYOTA MOTOR CORPORATION 1 Toyota, Toyota-city, Aichi, 471-8571 Japan	Attn:	宛先 :	
	Tel:	Tel:	

				VALUE FOR CUSTOMS USE:
1	Part # 1: 2322050160	Part Description PUMP ASSY, FUEL W/FILTER	Qty. 1	Used Part Value Each \$ 50.94
	Comments:			
2	Part # 2:	Part Description	Qty.	Used Part Value Each \$
	Comments:			
3	Part # 3:	Part Description	Qty.	Used Part Value Each \$
	Comments:			

FIELD TECHNICAL REPORT



TQCN DOC# TQCN_FTR-092740012		Affiliate TMS		Dept. QACHassis		Ref 92753577	Date 10/02/2009
Primary Model Prius		Model Year 2010	Production Date 2009-06-29	Odometer 1255	VIN JTDKN3DU6A0 [REDACTED]	Repair Date 9/29/2009	
Source FTS	Location REG-NY	Problem Area Base Vehicle		Parts Destination CQE	DTC		
Part # 1 N/A	Part # 1 Serial/Date Code		Part # 2		Part # 2 Serial/Date Code		Parts Available Part(s) Available
Condition Title VSC Activates Prematurely When Going Over Bumps And Braking							

Condition Description

Customer states that when driving 15-25 MPH and hitting a bump while braking the vehicle accelerates.

Diagnostic Steps

- FTS inspected customer's vehicle and duplicated condition.
- When driving at low speeds around 15-25 MPH and hitting a bump such as a manhole cover while braking the VSC turns "ON".
- When the VSC turns "ON" while braking it feels as though vehicle is accelerating, but in actuality the vehicle is just not slowing down at the same rate.
- Other like vehicles were compared to customer's vehicle and operated in the same manner.

Probable Cause


Unknown

Repair Process

No repairs made, customer was advised vehicle is operating as designed.

Note: Customer stated that he understands this is how the VSC system is designed to operate, but he feels it is too sensitive. Customer stated while driving in inclement weather he is aware of the road conditions and is prepared for ABS or VSC activation. Customer is not prepared for VSC activation to occur when going over bumps. He feels this not safe and when it occurs and not expected could possibly cause an unsafe condition to occur.

FIELD TECHNICAL REPORT



TQCN DOC# TQCN_FTR-092740012		Condition Title VSC Activates Prematurely When Going Over Bumps And			Date 10/02/2009
Primary Model Prius	Model Year 2010	Production Date 2009-06-29	Odometer 1255	VIN (confirm 17 characters): JTDKN3DU6A0 [REDACTED]	

Orig
Tracking

Attachment 1: Parts Recovery Control Sheet

Do not type in SHADED fields. If the Final Destination field below is "scrap", properly dispose of the part.

VIN


Doc No.



Final Destination: CQE	SETR#:	CQE Eng:	N/A
Importer: (Applies to TMC Shipments Only) Mr. N. Okumura, Chief Expert Quality Div. Warranty Parts Room TOYOTA MOTOR CORPORATION 1 Toyota, Toyota-city, Aichi, 471-8571 Japan	Deliver to: Attn: Tel:	住所: 宛先: Tel:	
T-STAR			
Note: If this FTR contains more than one VIN, create a table in the report containing VIN, production date, and odometer			FOR CUSTOMS USE: Used Parts Value

Part #	Part #	Part Description	Qty.	Used Part Value Each
1	N/A	n/a	1	\$ 0.00
	Serial No. / Date Code		Comments:	
2	Part # 2:	Part Description	Qty.	Used Part Value Each
	Serial No. / Date Code		Comments:	
3	Part # 3:	Part Description	Qty.	Used Part Value Each
	Serial No. / Date Code		Comments:	
4	Part # 4:	Part Description	Qty.	Used Part Value Each
	Serial No. / Date Code		Comments:	
5	Part # 5:	Part Description	Qty.	Used Part Value Each
	Serial No. / Date Code		Comments:	
6	Part # 6:	Part Description	Qty.	Used Part Value Each
	Serial No. / Date Code		Comments:	
7	Part # 7:	Part Description	Qty.	Used Part Value Each
	Serial No. / Date Code		Comments:	

FIELD TECHNICAL REPORT



TQCN DOC# TQCN_FTR-092730016		Affiliate TMS		Dept. QAPowertrain		Ref 92733351	Date 09/30/2009
Primary Model RX350		Model Year 2010	Production Date 2009-08-26	Odometer 82	VIN 2T2ZK1BA1AC [REDACTED]	Repair Date 9/22/2009	
Source PE	Location TMS-PQSS		Problem Area Base Vehicle	Parts Destination CQE	DTC		
Part # 1 305000T010	Part # 1 Serial/Date Code 3A09H111140			Part # 2	Part # 2 Serial/Date Code		Parts Available Manual Part Return
Condition Title Vehicle Jerks When Accelerating From a Stop (U660E)							

Condition Description

Customer states the vehicle is jerking when accelerating from a stop.

Diagnostic Steps

1. Confirmed customer condition
2. Found the condition is not present in reverse or in "S" mode when left in 1st gear
3. Check trans fluid level and condition – OK
4. Reset memory using Techstream
5. Test drove and found the condition is still present
6. Replaced the ECM and test drove – condition is still present
7. Swapped the ECT and test drove – condition is still present

Probable Cause

Unknown

Repair Process

Replaced the transaxle assembly.


Note: Serial #: 3A09H111140



Snap shot of condition occurring.

Note: Flags are recorded immediately following the condition occurring.

FIELD TECHNICAL REPORT



TQCN DOC# TQCN_FTR-092730016		Condition Title Vehicle Jerks When Accelerating From a Stop (U660E)			Date 09/30/2009
Primary Model RX350	Model Year 2010	Production Date 2009-08-26	Odometer 82	VIN (confirm 17 characters): 2T2ZK1BA1AC [REDACTED]	

Orig
Tracking

Attachment 1: Parts Recovery Control Sheet

Do not type in SHADED fields. If the Final Destination field below is "scrap", properly dispose of the part.

VIN


Doc No.



Final Destination: CQE	SETR#:	CQE Eng:	N/A
Importer: (Applies to TMC Shipments Only) Mr. N. Okumura, Chief Expert Quality Div. Warranty Parts Room TOYOTA MOTOR CORPORATION 1 Toyota, Toyota-city, Aichi, 471-8571 Japan	Deliver to: Attn: Tel:	住所: 宛先: Tel:	
T-STAR			
Note: If this FTR contains more than one VIN, create a table in the report containing VIN, production date, and odometer			FOR CUSTOMS USE: Used Parts Value

Part #	Part #	Part Description	Qty.	Used Part Value Each
1	305000T010	TRANSAXLE ASSY, AUTOMATIC	1	\$ 737.63
	Serial No. / Date Code 3A09H111140		Comments:	
2	Part # 2:	Part Description	Qty.	Used Part Value Each
	Serial No. / Date Code		Comments:	
3	Part # 3:	Part Description	Qty.	Used Part Value Each
	Serial No. / Date Code		Comments:	
4	Part # 4:	Part Description	Qty.	Used Part Value Each
	Serial No. / Date Code		Comments:	
5	Part # 5:	Part Description	Qty.	Used Part Value Each
	Serial No. / Date Code		Comments:	
6	Part # 6:	Part Description	Qty.	Used Part Value Each
	Serial No. / Date Code		Comments:	
7	Part # 7:	Part Description	Qty.	Used Part Value Each
	Serial No. / Date Code		Comments:	

FIELD TECHNICAL REPORT



TQCN DOC# TQCN_FTR-092950034		Affiliate TMS		Dept. QAPowertrain		Ref 92160029	Date 10/22/2009
Primary Model Corolla		Model Year 2009	Production Date 2008-09-11	Odometer 10596	VIN 1NXBU40E99Z [REDACTED]	Repair Date 10/14/2009	
Source FTS	Location REG-SF	Problem Area Base Vehicle		Parts Destination CQE	DTC		
Part # 1 7811007011	Part # 1 Serial/Date Code		Part # 2		Part # 2 Serial/Date Code		Parts Available Part(s) Available
Condition Title Engine Intermittent Erratic RPM							

Condition Description

- Customer reports she was just driving. RPM shot up to 7000
- Vehicle jumped forward she had to slam brakes/pull parking brakes
- Vehicle kept going forward. Customer states this happened once. She turn off vehicle then she started car, high idle 9000

Diagnostic Steps

- Tech road tested vehicle and unable to verify customer concern
- Tech performed health check and no DTC's recorded in any system – contacted FTS
- FTS inspected vehicle and confirmed factory floor mats correctly secured and no evidence of stacked mats
- No evidence of outside or foreign interference with pedal assembly
- Depressed pedal by hand and noted return to complete idle position but not as smooth as comparable vehicle

Probable Cause

- Unknown

Repair Process

- Replaced Accel Pedal and Sensor Assembly for recovery and further inspection



Floor Mat Location Upon Inspection





Inspection & Comparison Method

FIELD TECHNICAL REPORT



TQCN DOC# TQCN_FTR-092950034		Condition Title Engine Intermittent Erratic RPM			Date 10/22/2009
Primary Model Corolla	Model Year 2009	Production Date 2008-09-11	Odometer 10596	VIN (confirm 17 characters): 1NXBU40E99Z [REDACTED]	




Sensor Assembly, Accel Pedal
PN 78110-07011

78110-07011
08240A2A X
49999825428
LHD

Toyota
CTS

FIELD TECHNICAL REPORT



TQCN DOC# TQCN_FTR-092950034		Condition Title Engine Intermittent Erratic RPM			Date 10/22/2009
Primary Model Corolla	Model Year 2009	Production Date 2008-09-11	Odometer 10596	VIN (confirm 17 characters): 1NXBU40E99Z [REDACTED]	

Orig
Tracking

Attachment 1: Parts Recovery Control Sheet

Do not type in SHADED fields. If the Final Destination field below is "scrap", properly dispose of the part.

VIN


Doc No.



Final Destination: CQE	SETR#:	CQE Eng:	N/A
Importer: (Applies to TMC Shipments Only) Mr. N. Okumura, Chief Expert Quality Div. Warranty Parts Room TOYOTA MOTOR CORPORATION 1 Toyota, Toyota-city, Aichi, 471-8571 Japan	Deliver to: Attn: Tel:	住所: 宛先: Tel:	
T-STAR			
Note: If this FTR contains more than one VIN, create a table in the report containing VIN, production date, and odometer			FOR CUSTOMS USE: Used Parts Value

Part #	Part #	Part Description	Qty.	Used Part Value Each
1	7811007011	SENSOR ASSY, ACCELERATOR PEDAL	1	\$ 24.55
	Serial No. / Date Code		Comments:	
2				\$
	Serial No. / Date Code		Comments:	
3				\$
	Serial No. / Date Code		Comments:	
4				\$
	Serial No. / Date Code		Comments:	
5				\$
	Serial No. / Date Code		Comments:	
6				\$
	Serial No. / Date Code		Comments:	
7				\$
	Serial No. / Date Code		Comments:	

FIELD TECHNICAL REPORT



TQCN DOC# TQCN_FTR-093100014		Affiliate TMS		Dept. QA Powertrain		Ref 93135912	Date 11/09/2009
Primary Model Camry		Model Year 2009	Production Date 2008-09-29	Odometer 11024	VIN 4T1BE46K49U [REDACTED]	Repair Date 11/2/2009	
Source FTS	Location REG-NY	Problem Area Base Vehicle		Parts Destination 5700	DTC		
Part # 1 111010H011	Part # 1 Serial/Date Code		Part # 2		Part # 2 Serial/Date Code		Parts Available Part(s) Available
Condition Title Engine surge at 1200 RPM (2AZ-FE)							

Condition Description

- Customer States: Engine surging at 1200RPM.

Diagnostic Steps

1. Technician inspected and confirmed customer's concern.
2. No VVT codes, but has pending misfire codes.
3. Noticed that the engine idle was high 750-790rpms.
4. Found condition goes away when OCV is unplugged.
5. Swapped OCV concern did not change.
6. Replaced A/F and O2 sensors, concern did not change.
7. Swapped ECM, fuel pump, MAF, throttle sensor, pedal sensor, cam sensor, crank sensor, coils, from a known good vehicle, concern did not change.
8. Using active test to add fuel, concern did not change.
9. Performed compression test all cylinders 165psi.
10. Performed running compression test, all cylinders 55psi.
11. Removed oil pan, found metal debris in pan.
12. Disassembled short block, no abnormal wear found.
13. Reassembled with new short block, adjusted four tight exhaust valves, Results: concern did not change, engine misfires, and high engine idle corrected.
14. Disabled VVT system, which keeps cam controller locked under all engine running conditions, **condition eliminated**.
15. Removed cylinder head to replace, found oil supply port in OCV passage not machined correctly.

Probable Cause


- Oil supply port in OCV passage not machined correctly

Repair Process

- Technician replaced cylinder head assembly.



Incorrect OCV oil supply port machining in problem cylinder head.




Replacement cylinder head with a considerable larger oil supply port

FIELD TECHNICAL REPORT



TQCN DOC# TQCN_FTR-093100014		Condition Title Engine surge at 1200 RPM (2AZ-FE)			Date 11/09/2009
Primary Model Camry	Model Year 2009	Production Date 2008-09-29	Odometer 11024	VIN (confirm 17 characters): 4T1BE46K49U [REDACTED]	




2AZ cylinder head
OCV port



C:\Documents and
Settings\morint\Desktop

FIELD TECHNICAL REPORT



TQCN DOC# TQCN_FTR-093100014		Condition Title Engine surge at 1200 RPM (2AZ-FE)			Date 11/09/2009
Primary Model Camry	Model Year 2009	Production Date 2008-09-29	Odometer 11024	VIN (confirm 17 characters): 4T1BE46K49U [REDACTED]	

Orig
Tracking

Attachment 1: Parts Recovery Control Sheet

Do not type in SHADED fields. If the Final Destination field below is "scrap", properly dispose of the part.

VIN


Doc No.



Final Destination: 5700	SETR#:	CQE Eng: N/A
Importer: (Applies to TMC Shipments Only) Mr. N. Okumura, Chief Expert Quality Div. Warranty Parts Room TOYOTA MOTOR CORPORATION 1 Toyota, Toyota-city, Aichi, 471-8571 Japan	Deliver to: Attn: Tel:	住所: 宛先: Tel:
T-STAR		
Note: If this FTR contains more than one VIN, create a table in the report containing VIN, production date, and odometer		FOR CUSTOMS USE: Used Parts Value

Part #	Part #	Part Description	Qty.	Used Part Value Each
1	111010H011	HEAD SUB-ASSY, CYLINDER	1	\$ 173.64
	Serial No. / Date Code		Comments:	
2	Part # 2:	Part Description	Qty.	Used Part Value Each
	Serial No. / Date Code		Comments:	
3	Part # 3:	Part Description	Qty.	Used Part Value Each
	Serial No. / Date Code		Comments:	
4	Part # 4:	Part Description	Qty.	Used Part Value Each
	Serial No. / Date Code		Comments:	
5	Part # 5:	Part Description	Qty.	Used Part Value Each
	Serial No. / Date Code		Comments:	
6	Part # 6:	Part Description	Qty.	Used Part Value Each
	Serial No. / Date Code		Comments:	
7	Part # 7:	Part Description	Qty.	Used Part Value Each
	Serial No. / Date Code		Comments:	

FIELD TECHNICAL REPORT



TQCN DOC# TQCN_FTR-093200036		Affiliate TMS		Dept. QACHassis		Ref 92753577	Date 11/16/2009
Primary Model Prius		Model Year 2010	Production Date 2009-06-08	Odometer 4489	VIN JTDKN3DU4A0 [REDACTED]	Repair Date 11/11/2009	
Source FTS	Location REG-NY	Problem Area Base Vehicle		Parts Destination CQE	DTC		
Part # 1 N/A	Part # 1 Serial/Date Code			Part # 2	Part # 2 Serial/Date Code		Parts Available No Part(s) Available
Condition Title Inconsistent brake feel when Going Over Bumps And Braking							

Condition Description

Customer states that when driving 15-25 MPH and hitting a bump while braking the vehicle accelerates.

Diagnostic Steps

- FTS inspected customer's vehicle and duplicated condition.
- When driving at low speeds around 15-25 MPH and hitting a bump such as a manhole cover while braking the VSC turns "ON".
- When the VSC turns "ON" while braking it feels as though vehicle is accelerating, but in actuality the vehicle is just not slowing down at the same rate.
- Other like vehicles were compared to customer's vehicle and operated in the same manner.

Probable Cause


Unknown

Repair Process

No repairs made, customer was advised vehicle is operating as designed.

Note: Customer stated that he understands this is how the VSC system is designed to operate, but he feels it is too sensitive. Customer stated while driving in inclement weather he is aware of the road conditions and is prepared for ABS or VSC activation. Customer is not prepared for VSC activation to occur when going over bumps. He feels this not safe and when it occurs and not expected could possibly cause an unsafe condition to occur.

FIELD TECHNICAL REPORT



TQCN DOC# TQCN_FTR-093200036		Condition Title Inconsistent brake feel when Going Over Bumps And			Date 11/16/2009
Primary Model Prius	Model Year 2010	Production Date 2009-06-08	Odometer 4489	VIN (confirm 17 characters): JTDKN3DU4A0 [REDACTED]	

Orig
Tracking

Attachment 1: Parts Recovery Control Sheet

Do not type in SHADED fields. If the Final Destination field below is "scrap", properly dispose of the part.

VIN

Doc No.



Final Destination: CQE	SETR#:	CQE Eng:	N/A
Importer: (Applies to TMC Shipments Only) Mr. N. Okumura, Chief Expert Quality Div. Warranty Parts Room TOYOTA MOTOR CORPORATION 1 Toyota, Toyota-city, Aichi, 471-8571 Japan	Deliver to: Attn: Tel:	住所: 宛先: Tel:	
T-STAR			
Note: If this FTR contains more than one VIN, create a table in the report containing VIN, production date, and odometer			FOR CUSTOMS USE: Used Parts Value

Part #	Part #	Part Description	Qty.	Used Part Value Each
1	N/A	n/a	1	\$ 0.00
	Serial No. / Date Code		Comments:	
2	Part # 2:	Part Description	Qty.	Used Part Value Each
	Serial No. / Date Code		Comments:	
3	Part # 3:	Part Description	Qty.	Used Part Value Each
	Serial No. / Date Code		Comments:	
4	Part # 4:	Part Description	Qty.	Used Part Value Each
	Serial No. / Date Code		Comments:	
5	Part # 5:	Part Description	Qty.	Used Part Value Each
	Serial No. / Date Code		Comments:	
6	Part # 6:	Part Description	Qty.	Used Part Value Each
	Serial No. / Date Code		Comments:	
7	Part # 7:	Part Description	Qty.	Used Part Value Each
	Serial No. / Date Code		Comments:	

DEALERSHIP PRODUCT REPORT

TQCN DOC# TQCN_DPR-093490050	Affiliate TMS	Dept. QAPowertrain	Dealer Code 64606	Ref 93507939	Date 12/16/2009
Dealer Name LEXUS OF SEATTLE, LLC		Dealer City LYNNWOOD	State WA	Region WES	Source TECH
Primary Model ES350	Model Year 2008	Production Date 26-MAY-08	Odometer 13282 mi	VIN JTHBJ46G982 [REDACTED]	
Part # 1: 7811033020	Part # 2:	Part # 3:	Parts Destination: CQE	Parts Available: No part available	Repair Date 11/27/2009
Condition Title Drivability concern with no floor mat installed			Applicable DTC Code(s)		

Condition Description

- Guest reported vehicle would not slow down in traffic on 11/25/09.
- Guest applied "all force possible with my right foot to the brake pedal, and the car still did not slow down and seemed to be accelerating. Just before I would have struck the car in front of me, I then put the car in neutral, which caused the car to stop accelerating.
- Guest reported vehicle had been driven for approximately 5 minutes from cold start.
- Vehicle was in to the dealer for the floor mat concern on 11/14 and had the floor mat removed.
- Reported concern happened with no floor mat in vehicle.

Diagnostic Steps:


- Electronic system health check revealed no codes stored.
- Verified no floor mat was installed in vehicle at time of inspection.
- Test drove vehicle and verified operation.

Probable Cause

Unknown

Repair Process

No repairs performed.



DEALERSHIP PRODUCT REPORT



TQCN DOC# TQCN_DPR-093490050		Condition Title Drivability concern with no floor mat installed			Date 12/16/2009
Primary Model ES350	Model Year 2008	Production Date 26-MAY-08	Odometer 13282 mi	VIN JTHBJ46G982 [REDACTED]	

Attachment 1: Parts Recovery Control Sheet		Orig Tracking	[REDACTED]
		VIN	
Do not type in SHADED fields. If the Final Destination field below is "scrap", properly dispose of the part.		Doc No.	
Final Destination: CQE		SETR#:	CQE Eng:
Importer: (Applies to TMC Shipments Only)	Deliver to:	住所 :	
Mr. N. Okumura, Chief Expert Quality Div. Warranty Parts Room TOYOTA MOTOR CORPORATION 1 Toyota, Toyota-city, Aichi, 471-8571 Japan	Attn:	宛先 :	
	Tel:	Tel:	

			VALUE FOR CUSTOMS USE:	
	Part # 1:	Part Description	Qty.	Used Part Value Each
1	7811033020	SENSOR ASSY, ACCELERATOR PEDAL	1	\$ 26
	Comments:			
2	Part # 2:	Part Description	Qty.	Used Part Value Each
				\$
	Comments:			
3	Part # 3:	Part Description	Qty.	Used Part Value Each
				\$
	Comments:			

DEALERSHIP PRODUCT REPORT



TQCN DOC# TQCN_DPR-100270042		Affiliate TMS	Dept. QAPowertrain		Dealer Code 04344	Ref	Date
Dealer Name VENTURA TOYOTA			Dealer City VENTURA		State CA	Region LOS	Source TECH
Primary Model Corolla			Model Year 2010	Production Date 18-AUG-09	Odometer 5545 mi	VIN 1NXBU4EE5AZ [REDACTED]	
Part # 1: 000000000000	Part # 2:	Part # 3:		Parts Destination: CQE	Parts Available: No part available		Repair Date 1/25/2010
Condition Title Gas Pedal/Throttle					Applicable DTC Code(s) U100		

Condition Description

CUSTOMER STATES VEHICLE FEELS LIKE IT ACCELERATES ON ITS OWN MOST NOTICEABLE ON SLOW SPEEDS

Diagnostic Steps:

What inspections or diagnostic steps did you perform? Inspect driver side floor mat,health check and diagnostic report, testdrive vehicle with techstream and record data, check for SSC. Inspect accel. pedal for mechanical failure, inspect accel. pedal with techstream per R.M. Inspect trottle body for sticking, inspect idle speed operation with Techstream.

Probable Cause

Unable to duplicate concern, CTS pedal present.

Repair Process

No repair done on this vehicle, contact DSPM/FTS

--	--	--

DEALERSHIP PRODUCT REPORT



TQCN DOC# TQCN_DPR-100270042		Condition Title Gas Pedal/Throttle			Date
Primary Model Corolla	Model Year 2010	Production Date 18-AUG-09	Odometer 5545 mi	VIN 1NXBU4EE5AZ [REDACTED]	

Attachment 1: Parts Recovery Control Sheet		Orig Tracking
		VIN
Do not type in SHADED fields. If the Final Destination field below is "scrap", properly dispose of the part.		Doc No.
Final Destination: CQE	SETR#:	CQE Eng:
Importer: (Applies to TMC Shipments Only) Mr. N. Okumura, Chief Expert Quality Div. Warranty Parts Room TOYOTA MOTOR CORPORATION 1 Toyota, Toyota-city, Aichi, 471-8571 Japan	Deliver to: Attn: Tel:	住所 : 宛先 : Tel:

			VALUE FOR CUSTOMS USE:	
	Part # 1:	Part Description	Qty.	Used Part Value Each
1	000000000000	TEST PART	0	\$ 0
	Comments:			
2	Part # 2:	Part Description	Qty.	Used Part Value Each
				\$
	Comments:			
3	Part # 3:	Part Description	Qty.	Used Part Value Each
				\$
	Comments:			

DEALERSHIP PRODUCT REPORT



TQCN DOC# TQCN_DPR-100270038		Affiliate TMS	Dept. QAPowertrain		Dealer Code 04344	Ref	Date
Dealer Name VENTURA TOYOTA			Dealer City VENTURA		State CA	Region LOS	Source TECH
Primary Model Corolla			Model Year 2010	Production Date 02-OCT-09	Odometer 1979 mi	VIN 1NXBU4EE8AZ [REDACTED]	
Part # 1: 000000000000	Part # 2:	Part # 3:		Parts Destination: CQE	Parts Available: No part available		Repair Date 1/27/2010
Condition Title Gas Pedal/Throttle					Applicable DTC Code(s)		

Condition Description

CUSTOMER STATES CAR KEEPS ON GOING WHILE TRYING TO BRAKE MOST NOTICEABLE AT HIGHER SPEEDS INSPECT AND ADVISE

Diagnostic Steps:

Inspect driver side floor mat,health check and diagnostic report, testdrive vehicle with techstream and record data, check for SSC. Inspect accel. pedal for mechanical failure, inspect accel. pedal with techstream per R.M. Inspect trottle body for sticking, inspect idle speed operation with Techstream. Techstream.

Probable Cause

What likely caused this customer concern? Unable to duplicate concern, CTS pedal present.

Repair Process

Contact DSPM/FTS

DEALERSHIP PRODUCT REPORT



TQCN DOC# TQCN_DPR-100270038		Condition Title Gas Pedal/Throttle			Date
Primary Model Corolla	Model Year 2010	Production Date 02-OCT-09	Odometer 1979 mi	VIN 1NXBU4EE8AZ [REDACTED]	

Attachment 1: Parts Recovery Control Sheet		Orig Tracking
		VIN
Do not type in SHADED fields. If the Final Destination field below is "scrap", properly dispose of the part.		Doc No.
Final Destination: CQE	SETR#:	CQE Eng:
Importer: (Applies to TMC Shipments Only) Mr. N. Okumura, Chief Expert Quality Div. Warranty Parts Room TOYOTA MOTOR CORPORATION 1 Toyota, Toyota-city, Aichi, 471-8571 Japan	Deliver to: Attn: Tel:	住所 : 宛先 : Tel:

			VALUE FOR CUSTOMS USE:	
	Part # 1:	Part Description	Qty.	Used Part Value Each
1	000000000000	TEST PART	0	\$ 0
	Comments:			
2	Part # 2:	Part Description	Qty.	Used Part Value Each
				\$
	Comments:			
3	Part # 3:	Part Description	Qty.	Used Part Value Each
				\$
	Comments:			

DEALERSHIP PRODUCT REPORT



TQCN DOC# TQCN_DPR-100270043		Affiliate TMS	Dept. QAPowertrain		Dealer Code 19026	Ref	Date
Dealer Name KOONS TOYOTA			Dealer City ANNAPOLIS		State MD	Region CAT	Source TECH
Primary Model Camry		Model Year 2010	Production Date 26-MAR-09	Odometer 3442 mi	VIN 4T4BF3EK4AR [REDACTED]		
Part # 1: 8966106J10	Part # 2:	Part # 3:		Parts Destination: CQE	Parts Available: No part available		Repair Date 1/27/2010
Condition Title Gas Pedal/Throttle				Applicable DTC Code(s)			

Condition Description

c/s when accelerating from a stop the car lurches forward

Diagnostic Steps:

road test with owner, scan test. visual inspection of floor mat, cts gas pedal, and throttle body.

Probable Cause

driver error/input. first time with a drive by wire system vehicle.

Repair Process

none.

--	--	--

DEALERSHIP PRODUCT REPORT



TQCN DOC# TQCN_DPR-100270043		Condition Title Gas Pedal/Throttle			Date
Primary Model Camry	Model Year 2010	Production Date 26-MAR-09	Odometer 3442 mi	VIN 4T4BF3EK4AR [REDACTED]	

Attachment 1: Parts Recovery Control Sheet		Orig Tracking	
		VIN	
Do not type in SHADED fields. If the Final Destination field below is "scrap", properly dispose of the part.		Doc No.	
Final Destination: CQE	SETR#:	CQE Eng:	
Importer: (Applies to TMC Shipments Only) Mr. N. Okumura, Chief Expert Quality Div. Warranty Parts Room TOYOTA MOTOR CORPORATION 1 Toyota, Toyota-city, Aichi, 471-8571 Japan	Deliver to: Attn: Tel:	住所 : 宛先 : Tel:	

				VALUE FOR CUSTOMS USE:	
	Part # 1:	Part Description	Qty.	Used Part Value Each	
1	8966106J10	COMPUTER, ENGINE CONTROL	1	\$ 82.8	
	Comments:				
2	Part # 2:	Part Description	Qty.	Used Part Value Each	
	Comments:				
3	Part # 3:	Part Description	Qty.	Used Part Value Each	
	Comments:				

DEALERSHIP PRODUCT REPORT



TQCN DOC# TQCN_DPR-100270049		Affiliate TMS	Dept. QAPowertrain		Dealer Code 04344	Ref	Date
Dealer Name VENTURA TOYOTA			Dealer City VENTURA		State CA	Region LOS	Source TECH
Primary Model Camry			Model Year 2007	Production Date 16-APR-07	Odometer 31875 mi	VIN 4T1BE46K07U [REDACTED]	
Part # 1: 000000000000	Part # 2:	Part # 3:		Parts Destination: CQE	Parts Available: No part available		Repair Date 1/27/2010
Condition Title Gas Pedal/Throttle					Applicable DTC Code(s)		

Condition Description

CUSTOEMR STATES WHEN APPLYING THE GAS PEDAL VEHICLE IS ACCELERATING MORE THAN IT NORMALL;Y WOULD,

Diagnostic Steps:

Inspect driver side floor mat,health check and diagnostic report, testdrive vehicle with techstream and record data, check for SSC. Inspect accel. pedal for mechanical failure, inspect accel. pedal with techstream per R.M. Inspect trottle body for sticking, inspect idle speed operation with Techstream.

Probable Cause

unable to verify condition.

Repair Process

No repair performed. CTS pedal. Contact DSPM/FTS

--	--	--

DEALERSHIP PRODUCT REPORT



TQCN DOC# TQCN_DPR-100270049		Condition Title Gas Pedal/Throttle			Date
Primary Model Camry	Model Year 2007	Production Date 16-APR-07	Odometer 31875 mi	VIN 4T1BE46K07U [REDACTED]	

Attachment 1: Parts Recovery Control Sheet		Orig Tracking
		VIN
Do not type in SHADED fields. If the Final Destination field below is "scrap", properly dispose of the part.		Doc No.
Final Destination: CQE	SETR#:	CQE Eng:
Importer: (Applies to TMC Shipments Only) Mr. N. Okumura, Chief Expert Quality Div. Warranty Parts Room TOYOTA MOTOR CORPORATION 1 Toyota, Toyota-city, Aichi, 471-8571 Japan	Deliver to: Attn: Tel:	住所 : 宛先 : Tel:

			VALUE FOR CUSTOMS USE:	
	Part # 1:	Part Description	Qty.	Used Part Value Each
1	000000000000	TEST PART	0	\$ 0
	Comments:			
2	Part # 2:	Part Description	Qty.	Used Part Value Each
				\$
	Comments:			
3	Part # 3:	Part Description	Qty.	Used Part Value Each
				\$
	Comments:			

DEALERSHIP PRODUCT REPORT



TQCN DOC# TQCN_DPR-100270050		Affiliate TMS	Dept. QAPowertrain		Dealer Code 04344	Ref	Date
Dealer Name VENTURA TOYOTA			Dealer City VENTURA		State CA	Region LOS	Source TECH
Primary Model Camry			Model Year 2010	Production Date 06-JUL-09	Odometer 6672 mi	VIN 4T1BK3EKXAU [REDACTED]	
Part # 1: 000000000000	Part # 2:	Part # 3:		Parts Destination: CQE	Parts Available: No part available	Repair Date 1/27/2010	
Condition Title Gas Pedal/Throttle					Applicable DTC Code(s)		

Condition Description

A CUSTOMER STATES THAT THE VEHICLE ACCELERATED ON ITS OWN WHEN AT A STOP. CUSTOMER STATES THAT WHEN SHE PRESSED THE BRAKE IT WENT ALL THE WAY TO THE FLOOR AND SHE HAD TO TURN OFF THE ENGINE FOR THE VEHICLE TO STOP. INSPECT AND ADVISE.

Diagnostic Steps:

Inspect driver side floor mat,health check and diagnostic report, testdrive vehicle with techstream and record data, check for SSC. Inspect accel. pedal for mechanical failure, inspect accel. pedal with techstream per R.M. Inspect trottle body for sticking, inspect idle speed operation with Techstream.

Probable Cause

Unable to verify concern.

Repair Process

No repair done, Denso pedal, contact DSPM/FTS

--	--	--

DEALERSHIP PRODUCT REPORT



TQCN DOC# TQCN_DPR-100270050		Condition Title Gas Pedal/Throttle			Date
Primary Model Camry	Model Year 2010	Production Date 06-JUL-09	Odometer 6672 mi	VIN 4T1BK3EKXAU [REDACTED]	

Attachment 1: Parts Recovery Control Sheet		Orig Tracking
		VIN
Do not type in SHADED fields. If the Final Destination field below is "scrap", properly dispose of the part.		Doc No.
Final Destination: CQE	SETR#:	CQE Eng:
Importer: (Applies to TMC Shipments Only) Mr. N. Okumura, Chief Expert Quality Div. Warranty Parts Room TOYOTA MOTOR CORPORATION 1 Toyota, Toyota-city, Aichi, 471-8571 Japan	Deliver to: Attn: Tel:	住所 : 宛先 : Tel:

			VALUE FOR CUSTOMS USE:	
	Part # 1:	Part Description	Qty.	Used Part Value Each
1	000000000000	TEST PART	0	\$ 0
	Comments:			
2	Part # 2:	Part Description	Qty.	Used Part Value Each
				\$
	Comments:			
3	Part # 3:	Part Description	Qty.	Used Part Value Each
				\$
	Comments:			

DEALERSHIP PRODUCT REPORT



TQCN DOC# TQCN_DPR-100360007		Affiliate TMS	Dept. QAChassis	Dealer Code 37065	Ref 92753577	Date 02/09/2010
Dealer Name THOMPSON TOYOTA			Dealer City DOYLESTOWN	State PA	Region CAT	Source TECH
Primary Model Prius		Model Year 2010	Production Date 30-JUN-09	Odometer 7692 mi	VIN JTDMK3DU4A0 [REDACTED]	
Part # 1: 000000000000	Part # 2:	Part # 3:	Parts Destination: CQE	Parts Available: Available upon request	Repair Date 2/5/2010	
Condition Title Brake Feel over bumps				Applicable DTC Code(s)		

Condition Description

The customer states car feels like it accelerates on bumpy roads when braking

Diagnostic Steps:

Test-drove the vehicle and could not duplicate the concern.
Performed a health check
Found that there were no codes present

Probable Cause

Unknown

Repair Process


No repair attempted
The vehicle is operating as designed
The customer is unhappy with the feel of the brakes on bumpy roads

--	--	--

DEALERSHIP PRODUCT REPORT




TQCN DOC# TQCN_DPR-100360007		Condition Title Brake Feel over bumps			Date 02/09/2010
Primary Model Prius	Model Year 2010	Production Date 30-JUN-09	Odometer 7692 mi	VIN JTDKN3DU4A0 [REDACTED]	

Attachment 1: Parts Recovery Control Sheet		Orig Tracking	[REDACTED] 
Do not type in SHADED fields. If the Final Destination field below is "scrap", properly dispose of the part.		VIN	
		Doc No.	
Final Destination: CQE		SETR#:	CQE Eng:
Importer: (Applies to TMC Shipments Only)	Deliver to:	住所 :	
Mr. N. Okumura, Chief Expert Quality Div. Warranty Parts Room TOYOTA MOTOR CORPORATION 1 Toyota, Toyota-city, Aichi, 471-8571 Japan	Attn:	宛先 :	
	Tel:	Tel:	

				VALUE FOR CUSTOMS USE:	
	Part # 1:	Part Description	Qty.	Used Part Value Each	
1	000000000000	TEST PART	1	\$ 0	
Comments:					
2	Part # 2:	Part Description	Qty.	Used Part Value Each	
Comments:					
3	Part # 3:	Part Description	Qty.	Used Part Value Each	
Comments:					

FIELD TECHNICAL REPORT



TQCN DOC# TQCN_FTR-100350004		Affiliate GST		Dept. QAPowertrain		Ref 90431573	Date 02/10/2010
Primary Model Corolla		Model Year 2009	Production Date 2008-10-14	Odometer 5989	VIN 1NXBU40E79Z [REDACTED]	Repair Date 1/26/2010	
Source FTS	Location REG-GST	Problem Area Base Vehicle		Parts Destination CQE	DTC		
Part # 1 N/A	Part # 1 Serial/Date Code			Part # 2	Part # 2 Serial/Date Code		Parts Available No Part(s) Available
Condition Title Unintended Acceleration after leaving from a stop							

Condition Description

Customer states while at a stop the engine started to rev and tried to take off. Customer turned off vehicle and restarted. Vehicle continued to rev when running. Turned vehicle off 3rd time and restarted vehicle operated normally after third start.

Diagnostic Steps

- Technician who was inspecting the vehicle had driven it approximately 10-12 minutes.
- 7-8 minutes into the drive the technician was sitting at a stop light. When the stop light changed the tech started to lightly accelerate.
- After traveling 20-30 feet the vehicle exhibited a slight hesitation then began to accelerate on its own.
- Engine speed was estimated to have gone from 1500 rpm to 5500 rpm at the time of the occurrence.
- Vehicle traveling 9-10 mph at time of occurrence. Approximate maximum speed reached was 20 mph prior to accelerator pedal release / brake application.
- Estimated throttle position at the time of the occurrence was 15-20 percent.
- No accessories were on at the time of occurrence.
- The external lights were not on at the time of the occurrence.
- The HVAC system was not in use at time of occurrence.
- DTC U0100 was set in memory, but the technician cleared the DTC prior to duplication and the DTC did not return following duplication
- The technician experienced a problem with the scan tool losing communication with the car at the time of the occurrence. The scan tool in use was a newer unit to the dealer. It is unknown if this was related to the vehicle concern or solely a scan tool concern.

Probable Cause


Unknown

Repair Process

The vehicle was taken back to the dealer and parked after the occurrence. The national office and region office inspected the vehicle. The vehicle was driven extensively on 3 different occasions over 3 different days with the vehicle sitting for 3 days between the second and 3rd driving sessions. The condition experienced by the consumer and the technician was never duplicated. It was decided in the interest of the customer to repurchase the vehicle

--	--

FIELD TECHNICAL REPORT



TQCN DOC# TQCN_FTR-100350004		Condition Title Unintended Acceleration after leaving from a stop			Date 02/10/2010
Primary Model Corolla	Model Year 2009	Production Date 2008-10-14	Odometer 5989	VIN (confirm 17 characters): 1NXBU40E79Z [REDACTED]	

Orig
Tracking

VIN

Doc No.

Attachment 1: Parts Recovery Control Sheet


Do not type in SHADED fields. If the Final Destination field below is "scrap", properly dispose of the part.



Final Destination: CQE	SETR#:	CQE Eng:	N/A
Importer: (Applies to TMC Shipments Only) Mr. N. Okumura, Chief Expert Quality Div. Warranty Parts Room TOYOTA MOTOR CORPORATION 1 Toyota, Toyota-city, Aichi, 471-8571 Japan	Deliver to: Attn: Tel:	住所: 宛先: Tel:	
T-STAR			
Note: If this FTR contains more than one VIN, create a table in the report containing VIN, production date, and odometer			FOR CUSTOMS USE: Used Parts Value

Part #	Part #	Part Description	Qty.	Used Part Value Each
1	N/A	n/a	1	\$ 0.00
	Serial No. / Date Code		Comments:	
2	Part # 2:	Part Description	Qty.	Used Part Value Each
	Serial No. / Date Code		Comments:	
3	Part # 3:	Part Description	Qty.	Used Part Value Each
	Serial No. / Date Code		Comments:	
4	Part # 4:	Part Description	Qty.	Used Part Value Each
	Serial No. / Date Code		Comments:	
5	Part # 5:	Part Description	Qty.	Used Part Value Each
	Serial No. / Date Code		Comments:	
6	Part # 6:	Part Description	Qty.	Used Part Value Each
	Serial No. / Date Code		Comments:	
7	Part # 7:	Part Description	Qty.	Used Part Value Each
	Serial No. / Date Code		Comments:	

DEALERSHIP PRODUCT REPORT



TQCN DOC# TQCN_DPR-100550039		Affiliate TMS	Dept. QACHASSIS		Dealer Code 19061	Ref A0562103	Date 02/25/2010
Dealer Name POHANKA OF SALISBURY			Dealer City SALISBURY		State MD	Region CAT	Source TECH
Primary Model Prius			Model Year 2007	Production Date 23-Nov-06	Odometer 33576 mi	VIN JTDKKB20U277 [REDACTED]	
Part # 1: 8966147160	Part # 2:	Part # 3:		Parts Destination: CQE	Parts Available: No part available		Repair Date 2/23/2010
Condition Title Brake feel on uneven road surface					Applicable DTC Code(s)		

Condition Description

- Customer states that a handful of times, especially on a specific road when applying brakes over a dip in the road, the car feels like it is surging forward instead of stopping
- Customer does not think the ABS is being activated and does not think the VSC is being activated either
- Customer sees a similarity between this situation and the one being reported on the 2010 Prius

Diagnostic Steps:

- Road tested vehicle with customer over a rough surface that customer states they had a problem with
- Customer was unable to duplicate the condition
- Checked ECU programming for the most current version and re-flashed engine ECU to newest software

Probable Cause

Unknown

Repair Process


Engine ECU was re-flashed to newest software version (not for customer complaint issue)

--	--	--

DEALERSHIP PRODUCT REPORT



TQCN DOC# TQCN_DPR-100550039		Condition Title Brake feel on uneven road surface			Date 02/25/2010
Primary Model Prius	Model Year 2007	Production Date 23-Nov-06	Odometer 33576 mi	VIN JTDKB20U277 [REDACTED]	

Attachment 1: Parts Recovery Control Sheet		Orig Tracking	[REDACTED] 
Do not type in SHADED fields. If the Final Destination field below is "scrap", properly dispose of the part.		VIN	
		Doc No.	
Final Destination: CQE		SETR#:	CQE Eng:
Importer: (Applies to TMC Shipments Only)	Deliver to:	住所 :	
Mr. N. Okumura, Chief Expert Quality Div. Warranty Parts Room TOYOTA MOTOR CORPORATION 1 Toyota, Toyota-city, Aichi, 471-8571 Japan	Attn:	宛先 :	
	Tel:	Tel:	

				VALUE FOR CUSTOMS USE:
1	Part # 1:	Part Description	Qty.	Used Part Value Each
	8966147160	COMPUTER, ENGINE CONTROL	1	\$ 113.58
Comments:				
2	Part # 2:	Part Description	Qty.	Used Part Value Each
				\$
Comments:				
3	Part # 3:	Part Description	Qty.	Used Part Value Each
				\$
Comments:				