





Warm-up report 2.0l R4 CR 105 kW in B8 Lim.

Overview of field complaints, ZP7

Page 2-3

· Status of current focuses

Page 4-9

3/26/2008
INFORMATION Redacted PURSUANT TO THE FREEDOM OF **INFORMATION ACT (FOIA), 5 U.S.C. 552(B)(6)**

EA11003EN-01494[1]

Warm-up report 2.0l R4CR 105kW in B8




Overview of field complaints (2007-2008)

Veh. delivered Non-responsive content remo : 6287*

of which: 144 x complaints (14 cases reported outside)

78 x breakdowns

Current focuses EGR 119 x, of which 52 x BD; foreign body damage 17x, of which 12x BD; regulating throttle 10x of which 7x BD; Pleuel bearing thrown 5x of which 4 BD; oil level sensor 4x of which 0 BD



*Updated 1x / week 3/26/2008 EA11003EN-01494[2]

Warm-up report 2.0l R4CR 105kW in B8




Overview of complaints ZP-7 (2007-2008)

Engines delivered: 36653 of which: 123 complaints

7 breakdowns

Focuses of current month: ATL function not OK; ATL noise; oil level sensor function not OK, sensor wheel NW



*Updated 1x / week

EA11003EN-01494[3]

Warm-up report 2.0l R4CR 105kW in B8

Audi R4

Rail pressure too low, pump noise

Problem: Rail pressure too low, pump noise

Cause: Power-train damage of high-pressure fuel pump

(Design fault for all Bosch customers)

Measures

before AHM failures (without effect)


- 1. Click-clack check before delivery, D:05/10/2007
- 2. New switch process between flushing and inspection, D:05/30/2007
- 3. Noise measurement, D:06/18/2007
- 4. Optimization of test bench workflow, D:07/09/2007
- 5. CH assembly with 5° torsion suspension D:07/23/2007
- 6. Extension of high-load inspection point, D:10/01/2007
- 7. Friction coefficient check +/-10°, D:12/13/2007
- 8. Tappet laser scan, D:12/21/2007

Measures after AHM failures:

- 1. Technical elimination measures with dates/persons responsible (for metal spatters in the roller, imperfections with elevations at outer edges of roller, etc.) expected of Bosch. D: 3/27/2008
- 2. Proposed concepts for distortion protection. T:Wk14/2008 (Meeting in WoB with TD).
- 3. Meeting with Bosch in Györ to examine the FFT booth once again and evaluate the recordings together. D:Wk14/2008
- 4. Fuel quality examination for all FFT booths. D:Wk14/2008
- 5. Assess storage concept of TD. D:Wk14/2008

DESIGN FAULT!

This subject is being followed closely in the Group and all activities/measures are being discussed with Bosch during pump technical discussions.



Laufrolle in Rollenschuh (2)

Wk 13/08



Roller in roller support (2)

Camshaft (3)

Nockenwelle (3)

EA11003EN-01494[4]

Non-responsive pages 5-9 removed

 $\stackrel{\text{EA11003EN-01538[0]}}{CP4-XX/1-xx} \ - \ Standard\ pump$

Recommendations for use of Diesel injection systems:

EU4 market and worse:

Use of injection systems with appropriate anti-wear measures after required validation

EU5 market and better:

Use of respective basic injection system for EN590 applications

The decisive factor for assessing the respective country is the minimum required exhaust standard of that country.


Based on the validation results, the use of the RP0 and RP1 (RP1+) anti-wear package and a water separator is recommended in all EU4 markets for the use of Bosch CP4.1 high-pressure fuel pumps.


Non-responsive content removed





CP4-XX/1-xx - Standard pump







RP0: High-pressure plunger

Objective


- → Lower wear of HP plunger
- → Lower internal HP leakage

Measure

- → Optimized C2 layer on HP plunger
- → Reduced play between HP plunger and plunger guidance in cylinder head

Impact

- → Increased robustness against abrasive wear.
- → High hydraulic efficiency, even if low-viscosity fuels are used.









RP1: Roller / roller support

Objective


Improved formation of lubricating film between roller support and roller to reduce the mixed friction proportion for fuels with low viscosity.

Measure

- → Optimized C layer on C2.1 roller support: Reduction of roughness on surface
- → Less play between roller and roller support

Impact

Increase thickness of hydrodynamic lubricating film.







RP1+: Tappet assembly

Objective:

- → Improved lubrication film formation on roller support and roller for reducing mixed friction proportion for fuels with low viscosity such as RP1
- → Increased robustness against wear, reduction of cavitation erosion due to lower tilting in the tappet guide
- → Reduced ticker tendency


Measure:

- → Optimized C-layer roller support C3.1; reduced surface roughness, harder substructure
- → Low roller/roller support play
- → Reduction of radial play of tappet to casing
- → Reduction of axial play on the piston foot

Effect:

- → Increased thickness of the hydrodyn. lubrication film
- → Reduced wear depths and cavitation erosion
- → Reduced impact speed of piston on RS

Affected components








Comparison of roller support layer systems

Schematic diagram of layer structure of friction-reducing anti-wear layer


C2.1 layer (RP1)



Component

- K1 laver
- Transition of K1 adhesive layer
- Adhesive layer 1
- Carbon layer type 1
- Carbon layer type 2


C3 layer, standard



Component

- K1 layer
- K2 layer (thick)
- Adhesive layer 2 (smoother, thinner)

C3.1 layer, RP1+



Component

- K1 layer opti.
- •K2 layer opti.(thinner)
- Adhesive layer 2 (smoother)

- Adhesive layer type 1
- Adhesive layer type 2





OV-b

Task

→ Prevention of vapor bubble formation in the cam space.


Measure

→ Increasing the overflow valve opening pressure.

Effect

→ Increased fuel pressure level in the cam space.

Affected components











CP4-XX/1-xx - Standard pump

Cost for introduction of anti-wear packages:

Unit planning over entire product life	Total Systems	Of which systems without RP0 (AWP)	Of which systems with RP0 (AWP)
2011 - 2016	Non-responsive content remove d	Non-responsive content remove d	Non-responsive content removed
Costs of change for standard pump with RP1+ and RP0	Non-responsive content removed	Non-responsive content removed	Non-responsive content removed
Costs of change for standard pump with RP1+ and elimination of RP0	Non-responsive content removed	Non-responsive content removed	Non-responsive con tent removed

Non-responsive content removed








 $\stackrel{\text{EA11003EN-01538[8]}}{CP4-XX/1-xx} \ - \ Standard\ pump$

Gen1/ 2 Unit planning	Total CR systems	Of which CR systems with RP0 (AWP)	Of which CR systems without RP0 (AWP)				
2011	Non-responsi	Non-respons	Non-responsiv e content rem				
2012	ve content r emoved	ive content removed	oved				
2013							
2014							
2015							
2016							
Total:							
Costs of change for standard pump with RP1+ and RP0	Non-responsive content remo ved	Non-responsive content remo ved	Non-responsive content re moved				
Costs of change for standard pump with RP1+ and elimination of RP0		Non-responsive conte nt removed	Non-responsive content remov ed				

Non-responsive content removed





CP4-XX/1-xx - Standard pump

Dates:

Introduction of CP4.1 anti-wear measures

- Introduction of RP1 anti-wear package and strainer before intake valve in all AWP CP4.1 pump versions completed by Wk 45/2010.
- Comprehensive introduction of RP1+ anti-wear package for all Bosch CP4.1 types planned for 03/2011.

Non-responsive content removed







AUDI AG

Memo to Non-responsive content removed

Subject: V6 TDI deployment scenario for

Coordinated with Messrs. Non-responsive content removed

Due to the critical fuel quality and the associated problems with the HPP4 the back-conversion of the HPP from CP4.2 to CP1H will be developed for the V6 TDI Gen1 engine generation in combination with EU4 application for the following models:

- -Audi Q7
- -VW Touareg
- -Audi C6 CKD
- -VW Phaeton

Timelines and part supply are currently being clarified. Objective: Application dates line in second half of 2011.

As an interim solution4 the Q7 V6 TDI and VW Touareg Gen1 will have the following measures:

- -HPP anti wear package 2
- -SW measures to improve fuel supply during engine start

will be employed in production again starting early 2011.

Signed

Non-responsive content removed

12/14/2010

Copy: Messrs.





EA11003EN-01858[1]

Bills for High-Pressure Fuel Pump CP4.2 Audi V6-TDI

(after setting date in AQUA)

	2008		1st half 2009		Jul 09	Aug 09	Sep 09	Oct 09	Nov 09	WK 49	WK 50	WK 51	WK 52	Total
Non-responsiv e content rem oved	58		118		49	43	80	57	23	0				428
	20		30		11	15	16	6	8	2				108
	30		10		3	5	3	2	0	0				53
	12		8		2	1	1	1	3	0				28
	1		19		9	16	14	9	1	0				69
	0		1		4	1	3	0	1	0				10
	4		6		2	3	0	0	0	0				15
	6		6		2	1	4	1	2	0				22
	7		9	9	1	1	6	4	2	1				31
	2		0		1	1	0	0	0	0				4
	2		6		1	0	1	0	0	0				10
	5	3	2	1	0	1	0	0	0				10	
	1		4		0	0	1	0	0	0				6
	2		0		0	1	0	0	0	0				3
USA	0		0		0	0	1	0	1	0				2
Total	150		220		86	88	131	80	41	3				799

EA11003EN-01858[2]

Bills for High-Pressure Fuel Pump CP4.2 Audi V6-TDI

