

# Quality status of injection components "US07" projects

Q status CP4.1 - 03L 130 755 A - Jetta 1/1

## Cause of failure: pump drivetrain damage

Status of US07 field failures\* total **before measures** (pump DM before 05/15/2008)

- \* At customer: **9** Failures received and confirmed as drivetrain damage, of which **1** warranty case rejected due to corrosion
- \* In testing: **2** failures reported and confirmed as drivetrain damage

Status of US07 field failures\* total **after measures** (pump DM after 05/15/2008)

**No** failures reported

## Other complaints

Complaint	QC number	Vehicle ident. no.	Date of manufacture	Failure date	Mileage	Failure location (0km/field)	Cust. ref. No.	Diagnosis results
Engine will not start.	230002445082	71K99M28802 [redacted]	8/16/2008	1/30/2009	2525	Field	VA 99058	Pump OK according to specification.
Error memory entry	230002460860	3VWRL71K19M0 [redacted]	3/29/2008	2/13/2009	11901	Field	VA 99066	Corrosion and deposits in the pump, no drivetrain damage, no Bosch error
HPP defective	230002465672		11/7/2008	4/6/2009	0	0km/Puebla	1287958	Particles in intake valve

\* Basic data of evaluation coordinated with VW/Audi: VW/Audi NFA [redacted] list (current version from 05/29/2009)

# Quality status of injection components “US07” projects



# Quality status of injection components “US07” projects

non-responsive content removed



# Bosch CP4.1 Claim plausibility check (2.0l TDI BIN5)


- **Listed claims:**
  - MY 2009 = 99 vehicles
  - MY 2010 = 12 vehicles
  
- **Plausibility check:**
  - 12 x double bookings
  - 17 x costs < [REDACTED] (no HPP change)
  - 11 x costs [REDACTED] - [REDACTED] (no injection system change, therefore no HPP drivetrain damage)
  - 71 x costs [REDACTED] - [REDACTED] (⇒ injection system change)
  - ⇒ Large price range for system change implausible!
  
- ⇒ **71 potential, but not yet confirmed, cases of CP4.1 drivetrain damage**
  
- **Diagnosis result (return of 15 high pressure fuel pumps in total):**
  - 1 x no defect
  - 1 x radial shaft seal camshaft leaking
  - 13 x HPP drivetrain damage



# Bosch CP4.1 Claim plausibility check (2.0l TDI BIN5)

## VW CP4.1 Field complaints from USA (0L 130 755A)

CP4.1 Field complaints from USA, status10, 21, 2010



Source IQIS 01.21.2010

**Diesel Systems**

Confidential [redacted] 01/21/2010 | Auswertung USA Triebwerkschäden 21.01.2010.ppt | © Robert Bosch GmbH 2009. All rights reserved, also regarding any disposal, exploitation, reproduction, processing, distribution, as well as for the registration of special industrial property rights.

## Engine development

Engine test center • Drive electronics • Power train management • Diesel engine development • Gearbox development • Petrol engine development





From processor

Tel

Fax

Non-responsive content removed

6/19/2008

## Log

Recipients, see participants

Info: Non-responsive content removed

Host

Participants VW

Non-responsive content removed

Head

Minutes

Organiz.

Date/location 06/12/2008, 12:00 PM - 2:00 PM, Bosch Non-responsive content removed

Topic Review field launch support R4 2.0L CRS3.2 Non-responsive content removed

## Summary

The field deployments to date in the framework of the shared launch support of the R4 2.0L gen.1 were introduced and discussed. A continuation of the collaboration between the VW field launch team and the Bosch Field Competence Team for subsequent launches was agreed upon. In addition, in preparation for future launches, VW- and Bosch-FCT will already receive support with problems in the framework of development and Q verification endurance runs.

## Detailed minutes

### Info in field complaints without reports to FCT (Attachment 1, Page 4)

- Vehicle. ID VWGZZZ5NZ8W : Pump was exchanged in framework of MU exchange campaign, but was OK

### Notes on field deployments in R4, 2l launch (Attachment 1)

- Note on case 5 (Pages 15-16): Workshop will exchange the control unit. If this corrects the fault, the CU will be sent to Bosch for diagnosis through standard channels; feedback to Bosch FCT
- GFF is broken off in workshops in some cases. Reason unclear.

Non-responsive content removed



From processor

Tel

Fax

Non-responsive content removed

6/19/2008

Log

Review field launch support R4 2.0L CRS3.2

Non-responsive content removed

### Further information on improving diagnosis in VW workshops

- Extend guided fault finding to low pressure circuit
- Start GFF from tank
- Check of low pressure circuit and pressure before PRV should be integrated in standard diagnosis => Simple check with potential to prevent expensive incorrect dismantling of turbocharger and high-pressure pump in case of certain PRV defects (for example, Attachment 1, Pages 17-18, case 6). Suitable diagnostic tools (LP case, HP case, return volume measurement device) were introduced by Bosch (Attachment 2)
- Implementation of improvements in GFF are responsibility of VW; already in process according to VW

R:

Non-responsive content removed

### Follow-on launches

- The subsequent launches, particularly with reporting requirements for complaints involving the fuel system (Passat CC, Golf 6-Wk45/08, Scirocco-Wk48/08) were introduced (Attachment 3).
- Continuation of the previous collaboration for subsequent launches was agreed upon.
- Support for the Bosch FCT after the end of the required reporting period was promised for serious complaints.
- Bosch proposed to expand support by VW- and Bosch-FCT for relaunches to test endurance runs and Q assurance endurance runs (particularly CRS2.5). This support should start around 3 months before market launch and serves to establish expertise for the series launch. This suggestion was received positively by VW and will be implemented as needed.

R:

Non-responsive content removed

R:



From processor

Tel

Fax

Non-responsive content removed

6/19/2008

Log

Review field launch support R4 2.0L CRS3.2

Non-responsive content removed

### General

- The VW FAT/Bosch FCT collaboration was assessed very positively by both houses, both individually and as a concept.
- In the case of preliminary examinations of Bosch CR components through field complaints by VW, the participation of Bosch employees is agreed upon in advance
- VW requested that Bosch FCT hold spare parts ready during deployments, to supply the affected workshop in case of bottlenecks in VW spare parts supply.  
Bosch pointed out that eliminating the causes in the supply chain would be more effective. The FCT's task in collaboration with the VW field launch team is to improve diagnosis in the VW workshop.
- VW employees [REDACTED] have already contributed knowledge from the Bosch CRS diagnosis training course in [REDACTED] to the VW GFF
- VW requests that Bosch check whether the CRS diagnosis training course can be held in WOB.  
This is not currently possible due to capacity bottlenecks among the instructors. As a result, synergy effects through interchange with participants from other OEMs (rated very positively by previous participants) would be excluded.
- Series launch US07 (Jetta) in the U.S. will take place without direct support by the VW field launch team.

The next meeting will take place after the end of the mandatory reporting period for the Golf 6 (E2008/A2009) or as needed to discuss new on-site deployments.

Non-responsive content removed

R: Non-responsive content removed

R: Non-responsive content removed



# 1. Review Field Launch Support

## VW-BOSCH for R4 2.0I CRS 3.2



06/12/2008

Non-re sponsi  
ve con tent r  
emove



Non-re spo  
-re sponsi  
ve con ten  
tr emove

## 1. Review Field Launch VW-BOSCH for R4 2.0I CRS 3.2

### Agenda

1. Presentation of FCT activities from Non-responsive content removed and Non-responsive content removed Bosch, VW
2. Discussion of detected optimization options in repair shop diagnostics Bosch, VW
3. Roadmap for further VW launches with mandatory reporting VW
4. Agreement to further cooperation VW, Bosch
  - Field Launch Team, VW and Bosch FCT
  - Series: Non-responsive content removed
  - Non-series, e.g. ER support development, quality validation



# 1. Review Field Launch VW-BOSCH for R4 2.0l CRS 3.2

## Summary of FCT cases for VW R4 engine

- Because of the good start with the R4, there were few field complaints in the period under review.  
6 cases were reported to FCT (in 2 cases the HPP was examined by VW Development and only presented to Bosch in dismantled form).  
3 additional cases are only documented in the Bosch warranty database (IQIS), which means a total of 9 cases are known

- Non-responsive content removed

- Non-responsive content removed

# 1. Review Field Launch VW-BOSCH for R4 2.0l CRS 3.2

R4 field failures up to 06.09.08 (from Bosch warranty system) VW failures

## VW failures

Non-responsive content removed

CP4.1 failures													
QC no.	QC issue date	RB Customer	Customer Material	Material	Date of manufacture	Date/purchase	Date of failure	Mileage KM	VIN	Vehicle model(keyword)	Customer complaint	Decision	Remark:
230001915354	09.01.2008	VW	03L130755	0445010507	10.05.2007	12.07.2007	12.14.2007	14	5N8W01028	5N1143	The O-ring of the MU has sheared off	Bosch's responsibility	No info to FCT
230001933956	01.28.2008	VW	03L130755	0445010507	10.20.2007	12.07.2007	01.04.2008	396	WVGZZZ5NZ8V	5N1242	Mechanical fault	OK according to specification	No info to FCT

## Audi failures

Non-responsive content removed

CP4.1 failures													
QC no.	QC issue date	RB Customer	Customer Material	Material	Date of manufacture	Date/purchase	Date of failure	Mileage KM	VIN	Vehicle model(keyword)	Customer complaint	Decision	Remark:
230001917421	1/10/2008	AUDI	03L130755	0445010507	9/17/2007	12/11/2007	1/4/2008	350	WUZZZ8K48A	8K20QC	Rail pressure not OK	Bosch responsibility	Info to FCT
230001930606	1/23/2008	AUDI	03L130755	0445010507	5/1/2007	12/6/2007	12/13/2007	365	8K08A002485	8K20QC B8	Mechanical fault	Bosch responsibility	Info to FCT
230001992667	3/13/2008	AUDI	03L130755	0445010507	1/18/2007	3/4/2007	3/12/2008	6793	8K69A000578	B8	Leak	Bosch responsibility	Info to FCT
230002070696	4/14/2008	AUDI	03L130277	0445010507	1/11/2008	3/26/2008	3/26/2008	25	WUZZZ8K48	8K20QC	Engine will not start.	Bosch responsibility	Info to FCT
230002125197	5/28/2008	AUDI	03L130755	0445010507	3/12/2008	4/17/2008	5/5/2008	1584	8K18A035821	8K20QC	Preheat light lights up, vehicle stopped	Not classified	Info to FCT



# 1. Review Field Launch VW-BOSCH for R4 2.0I CRS 3.2

## VW R4 field failures (reported to FCT)

No. customer	VIN:	VOT no:	Case date:	QC number:	Location:	Eng. typ	Part:	Remark:
Non-responsive content removed								
2	VW	5NZ8W003205	1558	1/15/2008		R4	CP4.1	Chip in intake valve HPP analysis from VW Development
3	VW	5NZ8W004458	1605	2/21/2008		R4	CP4.1	After replacement of CP4 vehicle OK, HPP analysis at VW Development --> Chip in intake valve (see report)
Non-responsive content removed								

## 1. Review Field Launch VW-BOSCH for R4 2.0l CRS 3.2

Case 1: Non-responsive content removed

Non-responsive content removed



## 1. Review Field Launch VW-BOSCH for R4 2.0l CRS 3.2

### Case 1: Non-responsive content removed

Non-responsive content removed



## 1. Review Field Launch VW-BOSCH for R4 2.0l CRS 3.2

### Case 1: Non-responsive content removed

Non-responsive content removed





## 1. Review Field Launch VW-BOSCH for R4 2.0l CRS 3.2

### Case 2: Non-responsive content removed

#### Vehicle data

Delivery date:	1/4/2008
Chassis number:	5NZ8W003205
MILEAGE:	35 kilometers
Report date WS to TSC:	1/8/2008
Report date to FCT:	1/15/2008
FCT deployed on:	1/16/2007
Involved:	VW <span style="background-color: black; color: white;">Non-responsive content removed</span>

#### Complaint data/ error code

Vehicle stopped while going and would not restart, error code: P0087

Fuel rail/system pressure too low



## 1. Review Field Launch VW-BOSCH for R4 2.0l CRS 3.2

### Case 2: Non-responsive content removed



### Symptoms reason for failure/ cause:

Cause of failure: HPP cannot build up pressure due to particles in intake valve.  
Analysis by VW Development.

Notes: The component causing the problem was clearly determined using the HP case  
The VW GFF for error memory entry “Fuel rail/system pressure too low” could not be carried out because the engine operating temperature (target 50°C; actual <50°C [engine doesn't run]).

## 1. Review Field Launch VW-BOSCH for R4 2.0l CRS 3.2

### Case 3: Non-responsive content removed

#### Vehicle data

Delivery date:	11/15/2007
Chassis number:	5NZ8W004458
MILEAGE:	2,493 kilometers
Report date WS to TSC:	2/20/2008
Report date to FCT.	2/21/2008
Telephone support on:	2/21/2008

No FCT deployment at local level because HPP already replaced before reporting to FCT.

#### Complaint data/ error code

Vehicle stopped and will not start

Error code: none



# 1. Review Field Launch VW-BOSCH for R4 2.0l CRS 3.2

## Case 3: Non-responsive content removed



**Symptom reason for failure/ cause**

Cause of failure: HPP cannot build up pressure due to particles in intake valve. Analysis by VW Development.

Notes: None



## 1. Review Field Launch VW-BOSCH for R4 2.0I CRS 3.2

Case 4: Non-responsive content removed

Non-responsive content removed



## 1. Review Field Launch VW-BOSCH for R4 2.0l CRS 3.2

Case 4: Non-responsive content removed

Non-responsive content removed



## 1. Review Field Launch VW-BOSCH for R4 2.0l CRS 3.2

Case 5: Non-responsive content removed

Non-responsive content removed



## 1. Review Field Launch VW-BOSCH for R4 2.0I CRS 3.2

### Case 5: Non-responsive content removed

Non-responsive content removed





## 1. Review Field Launch VW-BOSCH for R4 2.0l CRS 3.2

### Case 6: Non-responsive content removed

#### Vehicle data

Delivery date:	-
Chassis no.:	3CZ8E232070
Mileage:	218 kilometers
Report date WS to TSC:	5/28/2008
Report date to FCT	5/28/2008
FCT deployed on:	5/29/2008
Involved:	VW <span style="background-color: black; color: white; padding: 2px;">Non-responsive content removed</span>
	RB <span style="background-color: black; color: white; padding: 2px;">Non-responsive content removed</span>

#### Complaint data/ error code

Loss of performance at approx. 2900 rpm, under load.

Error code: Non-responsive content removed

P0088 Fuel rail/system pressure too high



## 1. Review Field Launch VW-BOSCH for R4 2.0l CRS 3.2

### Case 6: Non-responsive content removed

Non-responsive content removed



## 1. Review Field Launch VW-BOSCH for R4 2.0l CRS 3.2

### Conclusions

- Good cooperation with VW in the cases listed
  - Open communication with [REDACTED] and workshop.
- Swift reaction from FCT
  - Max. 1 day to deployment

### Potential for improvement in cooperation

- Earlier consultation with Bosch can help reduce examination and repair time => high level of customer satisfaction
- Incorporate FCT in all cases.
- Submit all damaged parts via RB standard examination channel.



## 1. Review Field Launch VW-BOSCH for R4 2.0l CRS 3.2

### Possible improvements when diagnosing rail pressure errors

Non-responsive content removed

- Examination of the pre-conveyor pumps for pressure and conveying volume.

Non-responsive content removed



## Service tools for Bosch Common Rail Piezo System

Non-responsive content removed

Automotive Aftermarket

1

Non-responsive content removed

01/2008 | © All rights reserved by Robert Bosch GmbH, also with regard to industrial property rights. All usage rights, including copying and distribution, reserved.



**BOSCH**

## Service tools for Bosch Common Rail Piezo System

Non-responsive content removed

Automotive Aftermarket

2

01/2008 | © All rights reserved by Robert Bosch GmbH, also with regard to industrial property rights. All usage rights, including copying and distribution, reserved.



**BOSCH**

## Service tools for Bosch Common Rail Piezo System

Non-responsive content removed

Automotive Aftermarket

3

Non-responsive content removed

01/2008 | © All rights reserved by Robert Bosch GmbH, also with regard to industrial property rights. All usage rights, including copying and distribution, reserved.



**BOSCH**

## Service tools for Bosch Common Rail Piezo System

### Case: Diesel Set 3

- To test pressure build-up of CR pump
- For RDS comparison check

**Bosch order number:  
0 986 613 100**



Automotive Aftermarket

4

Non-responsive content removed

01/2008 | © All rights reserved by Robert Bosch GmbH, also with regard to industrial property rights. All usage rights, including copying and distribution, reserved.



**BOSCH**



## Service tools for Bosch Common Rail Piezo System

### Pressure build-up check

#### ➤ Description

The test unit, consisting of pressure build-up test device and display unit is used to **check the pressure build-up of the high-pressure fuel pump** in common rail (CR) systems. The determined values for the pressure level represent a measure for the pressure build-up capacity of the pump under engine start conditions



#### ➤ How it works

The test device with catch tank is connected directly to the high-pressure connector of the diesel high-pressure fuel pump. To do so, the high-pressure line between pump and rail is detached and the test device is connected to the high-pressure fuel pump through a test line. The engine cannot be started in this condition. While the starter is pressed, the delivered volume is collected in the pressure chamber. The overflow volume flows into the catch tank. The determined pressure value is shown on the corresponding digital display. To protect the pump, the overflow valve is activated when pressure > 500 bar is reached, for pressure relief.



#### ➤ Notes

Adaptation for all widespread CR systems is possible; it could also be used in conventional systems, as well as low-pressure and gasoline systems. \*)

\*) Applicability must be checked individually

Automotive Aftermarket

5

Non-responsive content removed

01/2008 | © All rights reserved by Robert Bosch GmbH, also with regard to industrial property rights. All usage rights, including copying and distribution, reserved.



**BOSCH**

## Service tools for Bosch Common Rail Piezo System

Non-responsive content removed

Automotive Aftermarket

6

Non-responsive content removed

01/2008 | © All rights reserved by Robert Bosch GmbH, also with regard to industrial property rights. All usage rights, including copying and distribution, reserved.



**BOSCH**

## Service tools for Bosch Common Rail Piezo System

Non-responsive content removed



Automotive Aftermarket

7

01/2008 | © All rights reserved by Robert Bosch GmbH, also with regard to industrial property rights. All usage rights, including copying and distribution, reserved.



**BOSCH**

## Service tools for Bosch Common Rail Piezo System

Non-responsive content removed




Automotive Aftermarket



# Deployment dates (ZP4) CR engines in the vehicles

2008

Non-responsive content removed



**KOMPONENTE**

COMPONENT PLANNING







Tiguan improper fueling  
Tiguan shaft seal porous  
Tiguan NTF 6  
Passat NTF 3  
Passat pump drivetrain damage  
Passat t.b.d.  
Jetta pump drivetrain damage 3

Passat NTF 5  
Passat particles IV 3  
Passat pump piston seized 4

**Field complaints 2.0L CR 2008**



**Hall complaint 2, OL CR 2008**







# Bosch CP4.1 Claim plausibility check (2.0l TDI BIN5)

- **Listed claims:**
  - MY 2009 = 99 vehicles
  - MY 2010 = 12 vehicles
  
- **Plausibility check:**
  - 12 x double bookings
  - 17 x costs < [REDACTED] (no HPP change)
  - 11 x costs [REDACTED] - [REDACTED] (no injection system change, therefore no HPP drivetrain damage)
  - 71 x costs [REDACTED] - [REDACTED] (⇒ injection system change)

⇒ Large price range for system change implausible!

⇒ **71 potential, but not yet confirmed, cases of CP4.1 drivetrain damage**
  
- **Diagnosis result (return of 15 high pressure fuel pumps in total):**
  - 1 x no defect
  - 1 x radial shaft seal camshaft leaking
  - 13 x HPP drivetrain damage




# Bosch CP4.1 Claim plausibility check (2.0l TDI BIN5)

## VW CP4.1 field complaints from U.S. (0L 130 755A)

### CP4.1 Field complaints from U.S.

Status 10.21.2010



Source IQIS 01.21.2010

**Diesel Systems**  
Confidential | 01/21/2010 | Auswertung USA Triebwerkschaden 21.01.2010.ppt | © Robert Bosch GmbH 2009. All rights reserved; also regarding any disposal, exploitation, reproduction, processing, distribution, as well as for the registration of special industrial property rights.



## Engine development

Engine Test Center • Drivetrain Electronics • Power train Management • Diesel Engine Development • Gearbox Development • Petrol Engine Development

