


 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.	[REDACTED]										
				Date	12/3/2007										
Department:	Person responsible:	Telephone:	Use	internal											
Non-responsive content removed				external	x										
To:	Non-responsive content removed														
For information:	[REDACTED]														
<b>Pump type:</b> CP4.1S_348_2x5,25_REC_3,3_1,95_MT4,2		<b>Customer:</b> VW	<b>Project:</b> R4 2.0 BIN5	<b>Project / design pattern type</b> C / C2											
<b>Part number (TTNo.):</b> 0445B21060_10		<b>Date of manufacture:</b> 690	<b>Serial number:</b> 4422	<b>Manufacturing plant - line</b> 011M FeP(Feuerbach plant) – M -											
<b>SAP-No.:</b> DS – 154947		<b>Samos no.:</b> 568938	<b>Customer order no.:</b>	<b>Engine/Vehicle number</b> 03LD/17486											
<b>Customer part number</b>		<b>Endurance run type [customer]:</b> Engine trial	<b>Endurance run conditions:</b> Oil dilution + LP full load	<b>DSBFD no.:</b> 18589											
<b>Mileage</b> 995 h		<b>Parts receipt at dept. DS-PC/EDI:</b> 12/03/2007	<b>Process no.</b> 2007-CP4 / 0043	<b>Confidentiality note</b> Confidential											
<b>1 Subject</b> CP4 customer return Oil dilution program + LP full load															
<b>2 Conclusion</b> No significant change of the hydraulic functional values. The wear of the pump is very low.  The pump has passed the <b>endurance run</b>															
<b>3 Results of diagnosis (visual findings)</b>															
<b>3.1 Drive</b> No wear detected			Legend rating stages	OK uncritical Critical	<table border="1"> <tr><td>x</td><td></td><td></td></tr> <tr><td></td><td>x</td><td></td></tr> <tr><td></td><td></td><td>x</td></tr> </table>	x				x				x	
x															
	x														
		x													
<b>3.2 Drivetrain</b> Slight wear observed on the roller crest and tappet body (Figs. 1 and 2)					<table border="1"> <tr><td>x</td><td></td><td></td></tr> <tr><td></td><td>x</td><td></td></tr> </table>	x				x					
x															
	x														
<b>3.3 High pressure</b> Sealing point of intake valve to the stationary seal ring is slightly rusted (Fig. 3)					<table border="1"> <tr><td>x</td><td></td><td></td></tr> </table>	x									
x															
<b>3.4 Bearing</b> Very slight wear visible					<table border="1"> <tr><td>x</td><td></td><td></td></tr> </table>	x									
x															
<b>3.5 Shaft seal</b> Slight recession of the shaft seal (Fig. 4)					<table border="1"> <tr><td></td><td>x</td><td></td></tr> </table>		x								
	x														
<b>3.6 Holes</b> No striking feature					<table border="1"> <tr><td>x</td><td></td><td></td></tr> </table>	x									
x															
<b>3.7 Attached components (Metering Unit, Overflow Valve, Counting Point)</b> No striking feature					<table border="1"> <tr><td>x</td><td></td><td></td></tr> </table>	x									
x															
<b>3.8 Other</b> no					<table border="1"> <tr><td>x</td><td></td><td></td></tr> </table>	x									
x															

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.	[REDACTED]	
				Date	12/3/2007	
Department:	Person responsible:	Telephone:	Use	internal		
Non-responsive content removed				external	x	
To:	Non-responsive content removed					
For information:	[REDACTED]					

#### 4 Hydraulic function

	n[rpm]	p_rail [bar]	I_MU [A]	Delivery rate [l/h] of new part	Delivery rate [l/h] after testing
				11/20/2006	07/26/2007
KL1-S	3375	500	0.4	67.5	67.8
LG	1000	1800	0.4	17.5	17.6
ST	200	200	0.4	3.9	3.9

X		
X		
X		

No significant change of the hydraulic functional values recognizable.

#### 5 Destiny of the parts

Parts will be scrapped during RB 06/2008



Fig. 1: roller crest




Fig. 2 tappet body inside




Fig. 3: Intake valve






Fig. 4: Camshaft\_OilSeal\_System



Tested:	Non-responsive content removed	Telephone:	Non-responsive content removed	Date:	1/17/2008	Signature:	Non-responsive content removed
Department:	[REDACTED]	Telephone:	[REDACTED]	Date:	1/17/2008	Signature:	[REDACTED]
Department:	[REDACTED]	Telephone:	[REDACTED]	Date:	1/28/2008	Signature:	[REDACTED]



EA11003EN-00851[0]

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.											
				Date	3/25/2008										
Department:	Person responsible:	Telephone:		Use	internal										
Non-responsive content removed					external	x									
To:	Non-responsive content removed														
For information:															
<b>Pump type:</b> CP4.1S_348_2x5,25_REC_3,3_1,95_MT4,2		<b>Customer:</b> VW	<b>Project:</b> R4 2.0 EU5	<b>Project / design pattern type</b> D/D											
<b>Part number (TTNo.):</b> 0445B21058		<b>Date of manufacture:</b> 010207	<b>Serial number:</b> 0042	<b>Manufacturing plant - line</b> 0110 FeP – 1											
<b>SAP-No.:</b> DS – 175041		<b>Samos no.:</b> 588430	<b>Customer order no.:</b>	<b>Engine/Vehicle number</b> AU 481-8-8007											
<b>Customer part number</b>	<b>Endurance run type [customer]:</b> Vehicle endurance run	<b>Endurance run conditions:</b> Q verification	<b>DSBFD no.:</b> 20213												
<b>Mileage</b> 100000 km / -miles	<b>Parts receipt at dept. DS-PC/EDI:</b> 11/13/2007	<b>Process no.</b> 2007-CP4_0115	<b>Confidentiality note</b> Confidential												
<b>1. Subject</b>															
CP4 customer returns without complaint Diagnosis after end of endurance run															
<b>2. Conclusion</b>															
No hydraulic modification. No critical wear detected.  The pump has <b>passed</b> the test.															
<b>3. Results of diagnosis (visual findings)</b>															
			Legend rating stages	OK uncritical Critical	<table border="1"> <tr><td>X</td><td></td><td></td></tr> <tr><td></td><td>X</td><td></td></tr> <tr><td></td><td></td><td>X</td></tr> </table>	X				X				X	
X															
	X														
		X													
<b>3.1 Drive</b> No striking feature					<table border="1"> <tr><td>X</td><td></td><td></td></tr> </table>	X									
X															
<b>3.2 Drivetrain</b> Only running marks visible (see roller Fig. 1 and camshaft Fig. 2)					<table border="1"> <tr><td>X</td><td></td><td></td></tr> </table>	X									
X															
<b>3.3 High pressure</b> Slight fretting wear at the intake valve (Fig. 3)					<table border="1"> <tr><td>X</td><td></td><td></td></tr> </table>	X									
X															
<b>3.4 Bearing</b> No striking feature					<table border="1"> <tr><td>X</td><td></td><td></td></tr> </table>	X									
X															
<b>3.5 Shaft seal</b> Slight wearing -in of the shaft seal (depth x width = 9x480 µm) (Figs. 4 and 5)					<table border="1"> <tr><td>X</td><td></td><td></td></tr> </table>	X									
X															
<b>3.6 Holes</b> Only slight cavitation points visible					<table border="1"> <tr><td>X</td><td></td><td></td></tr> </table>	X									
X															
<b>3.7 Attached components (Metering Unit, Overflow Valve, Counting Point)</b> No striking feature					<table border="1"> <tr><td>X</td><td></td><td></td></tr> </table>	X									
X															
<b>3.8 Other</b> No striking feature					<table border="1"> <tr><td>X</td><td></td><td></td></tr> </table>	X									
X															

EA11003EN-00851[1]

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.	[Redacted]	
				Date	3/25/2008	
Department:	Person responsible:	Telephone:	Use	internal		
Non-responsive content removed				external	x	
To:	Non-responsive content removed					
For information:	[Redacted]					

**4. Hydraulic function**

	n[rpm]	p <sub>rail</sub> [bar]	I <sub>MU</sub> [A]	Delivery rate [l/h] of new part 2/6/2007	Delivery rate [l/h] after testing 10/23/2007
ST	200	200	0.4	3.8	3.9
LG	1000	1800	0.4	17.8	17.1
KL1-S	3375	500	0.4	64.7	67.9

x		
x		
x		

No striking feature

**5. Destiny of the parts**

The parts are stored until RB 09/2008



Fig. 1: Roller



Fig. 2: Camshaft




Fig. 3: Intake valve (with fretting wear)





Fig. 4: Running mark of shaft seal on the camshaft





Elevated

Cutting

Fig. 5: Wear measurement of the running mark of the shaft seal




Tested:	Non-responsive content removed	Phone	Non-responsive content removed	Date:	3/31/2008	Signature:	Non-responsive content removed
Department:	[Redacted]	Phone	[Redacted]	Date:	4/10/2008	Signature:	[Redacted]
Department:	[Redacted]	Phone	[Redacted]	Date:	4/11/2008	Signature:	[Redacted]

EA11003EN-00852[0]

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.										
				Date	1/11/2008									
Department:	Person responsible:	Telephone:		Use	internal									
Non-responsive content removed					external <input checked="" type="checkbox"/>									
To:	Non-responsive content removed													
For information:														
<b>Pump type:</b> CP4.1S_348_2x5,25_REC_3,3_1,95_MT4,2	<b>Customer:</b> VW	<b>Project:</b> R4 2.0 BIN5	<b>Project / design pattern type</b> C / C2											
<b>Part number (TTNo.):</b> 0445B21060_10	<b>Date of manufacture:</b> 690	<b>Serial number:</b> 4653	<b>Manufacturing plant - line</b> 011M FeP (Feuerbach plant) – M											
<b>SAP-No.:</b> DS –164754	<b>Samos no.:</b> 0577928	<b>Customer order no.:</b>	<b>Engine/Vehicle number</b> 03LD/17477											
<b>Customer part number</b>	<b>Endurance run type [customer]:</b> Vehicle endurance run	<b>Endurance run conditions:</b> Gear Fatigue Test	<b>DSBFD no.:</b> 19423											
<b>Mileage</b> 118338 km	<b>Parts receipt at dept. DS-PC/EDI:</b> 10/17/2007	<b>Process no.</b> 2007-CP4_0117	<b>Confidentiality note</b> Confidential											
<b>1. Subject</b>														
CP4 customer return GDV-EWP (Ehra variable track for passenger cars); 03LD/17477 Vehicle endurance run														
<b>2. Conclusion</b>														
The residual contamination test of the pump was normal. The pump was seal-tight in the cold test at -25 °C. Slight cavitation erosion was found between intake valve and the stationary seal ring, but is not in the critical range. The pump has <b>passed</b> the test.														
<b>3. Results of diagnosis (visual findings)</b>														
<b>3.1 Drive</b>		Legend rating stages		OK uncritical Critical	<table border="1"> <tr><td>X</td><td></td><td></td></tr> <tr><td></td><td>X</td><td></td></tr> <tr><td></td><td></td><td>X</td></tr> </table>	X				X				X
X														
	X													
		X												
Slight wear visible					<table border="1"> <tr><td>X</td><td></td><td></td></tr> </table>	X								
X														
<b>3.2 Drivetrain</b>					<table border="1"> <tr><td></td><td>X</td><td></td></tr> </table>		X							
	X													
Slight entrainment of the C coating on the roller crest. Alignment mark of the roller on the cam track visible (Fig. 1)														
<b>3.3 High pressure</b>					<table border="1"> <tr><td></td><td>X</td><td></td></tr> </table>		X							
	X													
Moderate fretting wear on the seal seat of the intake valve, but uncritical (Fig. 2)														
<b>3.4 Bearing</b>					<table border="1"> <tr><td>X</td><td></td><td></td></tr> </table>	X								
X														
Slight running marks visible														
<b>3.5 Shaft seal</b>					<table border="1"> <tr><td>X</td><td></td><td></td></tr> </table>	X								
X														
Slight running marks visible														
<b>3.6 Holes</b>					<table border="1"> <tr><td></td><td>X</td><td></td></tr> </table>		X							
	X													
Incipient cavitation erosion in the tappet hole of the housing in non-running area (Fig. 3)														
<b>3.7 Attached components (Metering Unit, Overflow Valve, Counting Point)</b>					<table border="1"> <tr><td>X</td><td></td><td></td></tr> </table>	X								
X														
No striking feature														
<b>3.8 Other</b>					<table border="1"> <tr><td></td><td></td><td></td></tr> </table>									



EA11003EN-00852[1]

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.		
				Date	1/11/2008	
Department:	Person responsible:	Telephone:		Use	internal	
Non-responsive content removed					external	x
To:	Non-responsive content removed					
For information:						

**4. Hydraulic function**

	n[rpm]	p_rail [bar]	I_MU [A]	Delivery rate [l/h] of new part	Delivery rate [l/h] after testing
				10/24/2006	10/24/2007
ST	200	200	0.4	3.9	3.9
LG	1000	1800	0.4	17.6	17.7
KL1-S	3375	500	0.4	67	67.8

x		
x		
x		

No striking feature

**5. Destiny of the parts**

Parts will be stored at RB and scrapped in 06/2008




Figure 1 cam track






Fig. 2 intake valve





Fig. 3 Housing of tappet hole

Tested:	Non-responsive content removed	Phone	Non-responsive content removed	Date:	1/17/2008	Signature:	Non-responsive content removed
Department:		Phone		Date:	1/17/2008	Signature:	
Department:		Phone		Date:	1/28/2008	Signature:	

EA11003EN-00853[0]

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.	[REDACTED]										
				Date	1/11/2008										
Department:	Person responsible:	Telephone:	Use	internal											
Non-responsive content removed				external		x									
To:	Non-responsive content removed														
For information:	[REDACTED]														
<b>Pump type:</b> CP4.1XS_348_2x5,25_REC_3,3_1,95_MT4,2		<b>Customer:</b> VW	<b>Project:</b> R4 2.0 BIN5	<b>Project / design pattern type</b> C / C2											
<b>Part number (TTNo.):</b> 0445B21058_06		<b>Date of manufacture:</b> 689	<b>Serial number:</b> 4888	<b>Manufacturing plant - line</b> 011M FeP (Feuerbach plant) – M -											
<b>SAP-No.:</b> DS -164742		<b>Samos no.:</b> 0577909	<b>Customer order no.:</b>	<b>Engine/Vehicle number</b> 03LA/17301											
<b>Customer part number</b>		<b>Endurance run type [customer]:</b> Q verification	<b>Endurance run conditions:</b> Gear Fatigue Test	<b>DSBFD no.:</b> 19426											
<b>Mileage</b> 120,000 km/- miles		<b>Parts receipt at dept. DS-PC/EDI:</b> 10/17/2007	<b>Process no.</b> 2007-CP4_0118	<b>Confidentiality note</b> Confidential											
Complaint: None.															
<b>1. Subject</b> CP4 customer return Q verification Endurance run end															
<b>2. Conclusion</b> Hydraulic testing points within tolerance for new parts. Only slight wear visible. The pump has <b>passed</b> the test.															
<b>3. Results of diagnosis (visual findings)</b>															
<b>3.1 Drive</b> Only slight running marks		Legend rating stages		OK uncritical Critical	<table border="1"> <tr><td>X</td><td></td><td></td></tr> <tr><td></td><td>X</td><td></td></tr> <tr><td></td><td></td><td>X</td></tr> </table>		X				X				X
X															
	X														
		X													
<b>3.2 Drivetrain</b> Slight wear marks visible					<table border="1"> <tr><td>X</td><td></td><td></td></tr> <tr><td>X</td><td></td><td></td></tr> </table>		X			X					
X															
X															
<b>3.3 High pressure</b> The onset of cavitation erosion on the piston base visible (Fig. 1). Fretting wear on the sealing surface of the intake valve / stationary seal ring visible (Fig. 2)					<table border="1"> <tr><td></td><td>X</td><td></td></tr> </table>			X							
	X														
<b>3.4 Bearing</b> Slight wear marks visible					<table border="1"> <tr><td>X</td><td></td><td></td></tr> </table>		X								
X															
<b>3.5 Shaft seal</b> Shaft seal slipped off the camshaft					<table border="1"> <tr><td>X</td><td></td><td></td></tr> </table>		X								
X															
<b>3.6 Holes</b> The onset of cavitation erosion in tappet hole recognizable					<table border="1"> <tr><td>X</td><td></td><td></td></tr> </table>		X								
X															
<b>3.7 Attached components (Metering Unit, Overflow Valve, Counting Point)</b> Overflow valve screw plug slightly rusted					<table border="1"> <tr><td>X</td><td></td><td></td></tr> </table>		X								
X															
<b>3.8 Other</b>					<table border="1"> <tr><td></td><td></td><td></td></tr> </table>										

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.	[REDACTED]	
				Date	1/11/2008	
Department:	Person responsible:	Telephone:	Use	internal		
Non-responsive content removed				external	<b>x</b>	
To:	Non-responsive content removed					
For information:	Non-responsive content removed					

**4. Hydraulic function**

	n[rpm]	p_rail [bar]	I_MU [A]	Delivery rate [l/h] of new part 9/12/2006	Delivery rate [l/h] after testing 10/24/2007
Starting point	200	200	0.4	3.8	3.9
1000 rpm, p_rated	1000	1800	0.4	17.2	17.2
n_max_p, 500bar	3375	500	0.4	65.0	66.3

<b>x</b>		
<b>x</b>		
<b>x</b>		

OK

**5. Destiny of the parts**

Parts will be stored at RB and scrapped in 06/2008




Fig. 1 High-pressure piston base








Fig. 2 Intake valve sealing surface

Tested:	Non-responsive content removed	Phone	Non-responsive content removed	Date:	1/17/2008	Signature:	Non-responsive content removed
Department:		Phone		Date:	1/17/2008	Signature:	
Department:		Phone		Date:	1/29/2008	Signature:	



EA11003EN-00854[0]

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.											
				Date	3/26/2008										
Department:	Person responsible:	Telephone:		Use	internal										
Non-responsive content removed					external	x									
To:	Non-responsive content removed														
For information:															
Pump type:		Customer:	Project:	Project / design pattern type											
CP4.1xS_348_2x5,25_REC_3,3_1,95_MT4,2		VW	R4 2.0 EU5	D/D											
Part number (TTNo.):		Date of manufacture:	Serial number:	Manufacturing plant - line											
0445B21058		11206	0010	011M FeP (Feuerbach plant) – 1											
SAP-No.:		Samos no.:	Customer order no.:	Engine/Vehicle number											
DS –175042		588432		CAG0000003											
Customer part number		Endurance run type [customer]:	Endurance run conditions:	DSBFD no.:											
		Vehicle endurance run	EW1 KIN	20212											
Mileage		Parts receipt at dept. DS-PC/EDI:	Process no.	Confidentiality note											
95598 km		11/29/2007	2007-CP4_0123	Confidential											
<b>1. Subject</b>															
CP4 customer return Diagnosis after end of endurance run															
<b>2. Conclusion</b>															
Functioning OK Wear uncritical during the running time. The pump has <b>passed</b> the test.															
<b>3. Results of diagnosis (visual findings)</b>															
<b>3.1 Drive</b>		Legend rating stages		<div> <div>OK</div> <div>uncritical</div> <div>Critical</div> </div> <table border="1"> <tr><td>x</td><td></td><td></td></tr> <tr><td></td><td>x</td><td></td></tr> <tr><td></td><td></td><td>x</td></tr> </table>			x				x				x
x															
	x														
		x													
No striking feature				<table border="1"> <tr><td>x</td><td></td><td></td></tr> </table>			x								
x															
<b>3.2 Drivetrain</b>				<table border="1"> <tr><td>x</td><td></td><td></td></tr> </table>			x								
x															
Only slight running marks on roller (Fig. 1) and camshaft (Fig. 2) visible															
<b>3.3 High pressure</b>				<table border="1"> <tr><td></td><td>x</td><td></td></tr> </table>				x							
	x														
Slight fretting wear at the intake valve (Fig. 3)															
<b>3.4 Bearing</b>				<table border="1"> <tr><td>x</td><td></td><td></td></tr> </table>			x								
x															
No striking feature															
<b>3.5 Shaft seal</b>				<table border="1"> <tr><td>x</td><td></td><td></td></tr> </table>			x								
x															
No striking feature															
<b>3.6 Holes</b>				<table border="1"> <tr><td>x</td><td></td><td></td></tr> </table>			x								
x															
No striking feature															
<b>3.7 Attached components (Metering Unit, Overflow Valve, Counting Point)</b>				<table border="1"> <tr><td>x</td><td></td><td></td></tr> </table>			x								
x															
No striking feature															
<b>3.8 Other</b>				<table border="1"> <tr><td>x</td><td></td><td></td></tr> </table>			x								
x															
No striking feature															

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no. [REDACTED]	
				Date 3/26/2008	
Department:	Person responsible:	Telephone:	Use	internal	
Non-responsive content removed				external	<b>x</b>

#### 4. Hydraulic function

	n[rpm]	p <sub>rail</sub> [bar]	I <sub>MU</sub> [A]	Delivery rate [l/h] of new part 10/24/2006	Delivery rate [l/h] after testing 10/24/2007
ST	200	200	0.4	4.2	3.7
LG	1000	1800	0.4	16.7	17.6
KL1-S	3375	500	0.4	67.7	66.4

<b>x</b>		
<b>x</b>		
<b>x</b>		

No striking feature

#### 5. Destiny of the parts

The parts are stored until 09/2008 at RB




Fig. 1 Roller




Fig. 2: Camshaft






Fig. 3 intake valve

Tested:	Non-responsive content removed	Phone	Non-responsive content removed	Date:	3/31/2008	Signature:	Non-responsive content removed
Department:	[REDACTED]	Phone	[REDACTED]	Date:	4/10/2008	Signature:	[REDACTED]
Department:	[REDACTED]	Phone	[REDACTED]	Date:	4/11/2008	Signature:	[REDACTED]

EA11003EN-00855[0]

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.	[REDACTED]													
				Date	3/26/2008													
Department:	Person responsible:	Telephone:		Use	internal													
Non-responsive content removed					external	x												
To:	Non-responsive content removed																	
For information:																		
Pump type:		Customer:	Project:	Project / design pattern type														
CP4.1XS_348_2x5,25_REC_3,3_1,95_MT4,2		VW	R4 2.0 EU5	D/D														
Part number (TTNo.):		Date of manufacture:	Serial number:	Manufacturing plant - line														
0445B21058		201206	0043	0110 FeP - 1														
SAP-No.:		Samos no.:	Customer order no.:	Engine/Vehicle number														
DS -167929		582051		03LAP270028														
Customer part number		Endurance run type [customer]:	Endurance run conditions:	DSBFD no.:														
		Engine endurance run	Polycyclic endurance run	19584														
Mileage		Parts receipt at dept. DS-PC/EDI:	Process no.	Confidentiality note														
718 h		11/29/2007	2007-CP4_0124	Confidential														
<b>1. Subject</b>																		
CP4 customer return Diagnosis after end of endurance run																		
<b>2. Conclusion</b>																		
No change in the hydraulic testing detected. Wear of all parts minimal. The pump has <b>passed</b> the test.																		
<b>3. Results of diagnosis (visual findings)</b>																		
<b>3.1 Drive</b>			Legend rating stages { <table border="1"> <tr> <td>OK</td> <td><div><div>X</div></div></td> <td><div><div></div></div></td> <td><div><div></div></div></td> </tr> <tr> <td>uncritical</td> <td><div><div>X</div></div></td> <td><div><div></div></div></td> <td><div><div></div></div></td> </tr> <tr> <td>Critical</td> <td><div><div></div></div></td> <td><div><div>X</div></div></td> <td><div><div></div></div></td> </tr> </table>	OK	<div><div>X</div></div>	<div><div></div></div>	<div><div></div></div>	uncritical	<div><div>X</div></div>	<div><div></div></div>	<div><div></div></div>	Critical	<div><div></div></div>	<div><div>X</div></div>	<div><div></div></div>			
OK	<div><div>X</div></div>	<div><div></div></div>		<div><div></div></div>														
uncritical	<div><div>X</div></div>	<div><div></div></div>	<div><div></div></div>															
Critical	<div><div></div></div>	<div><div>X</div></div>	<div><div></div></div>															
No striking feature			<table border="1"> <tr> <td><div><div>X</div></div></td> <td><div><div></div></div></td> <td><div><div></div></div></td> </tr> </table>				<div><div>X</div></div>	<div><div></div></div>	<div><div></div></div>									
<div><div>X</div></div>	<div><div></div></div>	<div><div></div></div>																
<b>3.2 Drivetrain</b>																		
In very good condition (see roller Fig. 1 and camshaft Fig. 2)			<table border="1"> <tr> <td><div><div>X</div></div></td> <td><div><div></div></div></td> <td><div><div></div></div></td> </tr> </table>				<div><div>X</div></div>	<div><div></div></div>	<div><div></div></div>									
<div><div>X</div></div>	<div><div></div></div>	<div><div></div></div>																
<b>3.3 High pressure</b>																		
Only running marks on HP piston visible (Fig. 3)			<table border="1"> <tr> <td><div><div>X</div></div></td> <td><div><div></div></div></td> <td><div><div></div></div></td> </tr> </table>				<div><div>X</div></div>	<div><div></div></div>	<div><div></div></div>									
<div><div>X</div></div>	<div><div></div></div>	<div><div></div></div>																
<b>3.4 Bearing</b>																		
No striking feature			<table border="1"> <tr> <td><div><div>X</div></div></td> <td><div><div></div></div></td> <td><div><div></div></div></td> </tr> </table>				<div><div>X</div></div>	<div><div></div></div>	<div><div></div></div>									
<div><div>X</div></div>	<div><div></div></div>	<div><div></div></div>																
<b>3.5 Shaft seal</b>																		
No striking feature			<table border="1"> <tr> <td><div><div>X</div></div></td> <td><div><div></div></div></td> <td><div><div></div></div></td> </tr> </table>				<div><div>X</div></div>	<div><div></div></div>	<div><div></div></div>									
<div><div>X</div></div>	<div><div></div></div>	<div><div></div></div>																
<b>3.6 Holes</b>																		
No striking feature			<table border="1"> <tr> <td><div><div>X</div></div></td> <td><div><div></div></div></td> <td><div><div></div></div></td> </tr> </table>				<div><div>X</div></div>	<div><div></div></div>	<div><div></div></div>									
<div><div>X</div></div>	<div><div></div></div>	<div><div></div></div>																
<b>3.7 Attached components (Metering Unit, Overflow Valve, Counting Point)</b>																		
No striking feature			<table border="1"> <tr> <td><div><div>X</div></div></td> <td><div><div></div></div></td> <td><div><div></div></div></td> </tr> </table>				<div><div>X</div></div>	<div><div></div></div>	<div><div></div></div>									
<div><div>X</div></div>	<div><div></div></div>	<div><div></div></div>																
<b>3.8 Other</b>																		
No striking feature			<table border="1"> <tr> <td><div><div>X</div></div></td> <td><div><div></div></div></td> <td><div><div></div></div></td> </tr> </table>				<div><div>X</div></div>	<div><div></div></div>	<div><div></div></div>									
<div><div>X</div></div>	<div><div></div></div>	<div><div></div></div>																



 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no. [REDACTED]	
				Date 3/26/2008	
Department:	Person responsible:	Telephone:	Use	internal	
Non-responsive content removed				external	<b>x</b>

#### 4. Hydraulic function

	n[rpm]	p <sub>rail</sub> [bar]	I <sub>MU</sub> [A]	Delivery rate [l/h] of new part 12/19/2006	Delivery rate [l/h] after testing 12.07.2007
ST	200	200	0.4	4	3.9
LG	1000	1800	0.4	16.5	17.6
KL1-S	3375	500	0.4	66.9	67.1

<b>x</b>		
<b>x</b>		
<b>x</b>		

No striking feature

#### 5. Destiny of the parts

The parts will be stored at RB until 09/2008



Fig. 1 Roller





Fig. 2: Camshaft



Fig. 3: HP piston

Tested:	Non-responsive content removed	Phone	Non-responsive content removed	Date:	3/31/2008	Signature:	Non-responsive content removed
Department:		Phone		Date:	4/10/2008	Signature:	
Department:		Phone		Date:	4/11/2008	Signature:	

EA11003EN-00856[0]

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.	[REDACTED]	
				Date	1/25/2008	
<b>Department:</b>	<b>Person responsible:</b>	<b>Telephone:</b>		Use	internal	
Non-responsive content removed					external	x
<b>To:</b>	Non-responsive content removed					
<b>For information:</b>						
<b>Pump type:</b>	<b>Customer:</b>	<b>Project:</b>	<b>Project / design pattern type</b>			
CP4.1S_348_2x5,25_REC_3,3_1,95_MT4,2	VW	R4 2.0 EU5	C / C			
<b>Part number (TTNo.):</b>	<b>Date of manufacture:</b>	<b>Serial number:</b>	<b>Manufacturing plant - line</b>			
0445B21058	071206	0011	011M FeP (Feuerbach plant) – M			
<b>SAP-No.:</b>	<b>Samos no.:</b>	<b>Customer order no.:</b>	<b>Engine/Vehicle number</b>			
DS-154940	568932		CAG 0000 050			
<b>Customer part number</b>	<b>Endurance run type [customer]:</b>	<b>Endurance run conditions:</b>	<b>DSBFD no.:</b>			
0	Engine trial	Function	19089			
<b>Mileage</b>	<b>Parts receipt at dept. DS-PC/EDI:</b>	<b>Process no.</b>	<b>Confidentiality note</b>			
826 h	10/18/2007	2007-CP4_0140	Confidential			

**1. Subject**

CP4 customer return  
Findings at the end of endurance run

**2. Conclusion**

The delivery rates after endurance run correspond to the specifications.  
The wear of the components is low.  
The spring plate edge shows uncritical entrainment of the anti-friction paint.

The pump has **passed** the test.

**3. Results of diagnosis (visual findings)**

**3.1 Drive**  
No striking feature

**3.2 Drivetrain**  
Spring plate with isolated anti-friction paint spalling (Figs. 1 and 2)

**3.3 High pressure**  
No striking feature

**3.4 Bearing**  
No striking feature

**3.5 Shaft seal**  
No striking feature

**3.6 Holes**  
No striking feature

**3.7 Attached components (Metering Unit, Overflow Valve, Counting Point)**  
No striking feature

**3.8 Other**  
No striking feature

Legend rating stages

OK

x

uncritical

x

Critical

x

x			
	x		
			x

x			
---	--	--	--

	x		
--	---	--	--

x			
---	--	--	--

x			
---	--	--	--



x			
---	--	--	--

x			
---	--	--	--

--	--	--	--

 <b>BOSCH</b> 	<b>CR pump CP4 - Diagnosis report</b>		Report no.	[REDACTED]	
			Date	1/25/2008	
Department:	Person responsible:	Telephone:	Use	internal	
Non-responsive content removed				external	x

### 3.9 Images of visual findings




Fig. 1: Spring plate, tappet side




Fig. 2: Spring plate, spring side

### 4. Hydraulic function

	n[rpm]	p rail [bar]	I MU [A]	Delivery rate [l/h] of new part	Delivery rate [l/h] after testing
				12/19/2006	7/26/2007
ST	200	200	0.4	4.0	3.9
LG	1000	1800	0.4	16.6	17.3
KL-1	3375	500	0.4	67.0	67.0

x		
x		
x		

TCD (technical customer documentation) testing point LG (1,000 rpm, p<sub>rated</sub> ≥ 15.5 or 15.2 l/h after running time) is met.

No significant fuel-quantity drift compared to delivery measurement.

### 5. Destiny of the parts

The parts are stored until 06/2008 at RB

### 6. Attachments

None

Tested:	Non-responsive content removed	Phone:	Non-responsive content removed	Date:	2/7/2008	Signature:	Non-responsive content removed
Department:		Phone:		Date:	2/7/2008	Signature:	
Department:		Phone:		Date:	2/12/2008	Signature:	



Department:

Person responsible:

Telephone:

Use

internal

external

x

To:

For information:

Non-responsive content removed

<b>Pump type:</b> CP4.1S_348_2x5,25_REC_3,3_1,95_MT4 _2	<b>Customer:</b> VW	<b>Project:</b> R4 2.0 EU5	<b>Project / design pattern type</b> C / C
<b>Part number (TTNo.):</b> 0445B21058_01	<b>Date of manufacture:</b> 683	<b>Serial number:</b> 4396	<b>Manufacturing plant - line</b> 011M FeP (Feuerbach plant) – M -
<b>SAP-No.:</b> DS -154931	<b>Samos no.:</b> 568684	<b>Customer order no.:</b>	<b>Engine/Vehicle number</b> 03LD/16353
<b>Customer part number</b>	<b>Endurance run type [customer]:</b> Engine trial	<b>Endurance run conditions:</b> Cold EGR + POI3	<b>DSBFD no.:</b> 18593
<b>Mileage</b> 1690 h	<b>Parts receipt at dept. DS-PC/EDI:</b> 7/18/2007	<b>Process no.</b> 2007-CP4_0144	<b>Confidentiality note</b> Confidential
<b>VA / ETC no.:</b>	<b>Endurance run type [RB]:</b>		

Complaint:

**1. Subject**

CP4 customer return

Diagnosis of endurance run end without complaint

**2. Conclusion****Function**

- Delivery rates after endurance run without significant fuel-quantity drift in comparison with the new state.

**Components**

- There are abnormal grooves on almost all components and the high number of metallic and non-metallic foreign bodies, especially in the areas in front of the screens or on them.
- On the screens of the metering unit and the overflow valve, copper fibers mixed with predominantly organic particles with proportions of copper, calcium, silicon, magnesium, sulfur and oxygen were detected using EDX / EDS analysis.
- The thread of the camshaft shows damage, caused most likely due to the transport.

**Result**

- The pump has **passed** the test.
- **Massive contamination of the low-pressure system with foreign particles**

**3. Results of diagnosis (visual findings)**

Legend rating stages

OK uncritical Critical	OK			
	uncritical			
	Critical			

**3.1 Drive**

Thread flanks damaged (see Figure 1)

--	--	--

**3.2 Drivetrain**

Tappet body with grooves (see Figure 2), roller's lateral slip off (see Figures 3 to 4)

--	--	--

**3.3 High pressure**Narrow grooves on the piston skirt surface (see Figure 5)  
Particle marks on the piston crown (see Figure 6)

--	--	--

**3.4 Bearing**

Fine grooves in the radial bearing surfaces (see Figure 7 Flange and Fig. 8 Camshaft)

--	--	--

**3.5 Shaft seal**

Slight recession of the shaft seals into the camshaft (see Fig. 9)

--	--	--



BOSCH



## CR pump CP4 - Diagnosis report

Report no.

Date

4/14/2008

Department:

Non-responsive content removed

Person responsible:

Non-responsive content removed

Telephone:

Non-responsive content removed

Use

internal

external

x

## 3.6 Holes

Small metallic particles in the metering unit hole (see Fig. 10)

x

## 3.7 Attached components (Metering Unit, Overflow Valve, Counting Point)

No striking feature

x

## 3.8 Other

Foreign particles on the screen of the metering unit (see Fig. 11) and the overflow valve (see Fig. 12)

For the result of the EDX / EDS analysis of particles, see Appendix

x

## 3.9 Images of visual findings




Fig. 1 Camshaft, thread (damage)




Fig. 2 Tappet body, lateral surface (grooves)




Fig. 3 Roller front surface, housing side




Fig. 4 Tappet body inside, housing side




Fig. 5 High-pressure piston, high-pressure range (groove)




Fig. 6 High-pressure piston, piston crown (particles)





BOSCH



## CR pump CP4 - Diagnosis report

Report no.

Date

4/14/2008

Department:

Non-responsive content removed

Person responsible:

Non-responsive content removed

Telephone:

Non-responsive content removed

Use

internal

external

x




Fig. 7 Flange bearing bushing (grooves)




Fig. 8 Camshaft, flange bearing bushing (grooves)




Fig. 9 Camshaft, moving range of shaft seal




Fig. 10 Housing, metering unit hole (particles)




Fig. 11 Metering unit screen top view and magnification (copper fibers)





Fig. 12 Overflow valve screen top view and magnification (copper fibers)



		<b>CR pump CP4 - Diagnosis report</b>		Report no. <span style="background-color: black; color: black;">[REDACTED]</span>							
				Date 4/14/2008							
<b>Department:</b> Non-responsive content removed	<b>Person responsible:</b> [REDACTED]	<b>Telephone:</b> Non-responsive content removed	Use <table border="1"> <tr> <td>internal</td> <td></td> <td></td> </tr> <tr> <td>external</td> <td>x</td> <td></td> </tr> </table>			internal			external	x	
internal											
external	x										

**4. Hydraulic function**

TCD (technical customer documentation) testing point LG (1,000 rpm, p<sub>rated</sub> ≥ 15.5 or 15.2 l/h after running time) is

	n[rpm]	p <sub>rail</sub> [bar]	I <sub>MU</sub> [A]	Delivery rate [l/h] of new part 3/27/2006	Delivery rate [l/h] after testing 7/26/2007	
Starting point	200	200	0.4	3.8	3.9	x
1000 rpm, p <sub>rated</sub>	1000	1800	0.4	17.1	17.4	x
N <sub>max_p</sub> , 500 bar	3375	500	0.4	67.2	67.2	x

met.

TCD (technical customer documentation) testing point LG (1,000 rpm, p<sub>rated</sub> ≥ 15.5 or 15.2 l/h after running time) is met.

No significant fuel-quantity drift compared to delivery measurement.

**5. Destiny of the parts**

The pump is stored at RB until 06/2008 and then scrapped.

**6. Attachments**

The result of the EDX / EDS analysis of particles (2008-0148)

<b>Tested:</b>	Non-responsive content removed	<b>Phone</b>	Non-responsive content removed	<b>Date:</b>	4/18/2008	<b>Signature:</b>	Non-responsive content removed
<b>Department:</b>		<b>Phone</b>		<b>Date:</b>	4/18/2008	<b>Signature:</b>	
<b>Department:</b>		<b>Phone</b>		<b>Date:</b>	4/23/2008	<b>Signature:</b>	

EA11003EN-00857[4]


Photo report CR /  
ARA  
EDS report

2.008-0148

**BOSCH**

Project: 2008-0148  
Owner: camscan  
Area: Work area 1

Sample: 2008-0148 metering unit  
Type: Specification  
ID:



500 µm

Electron image 1

Magnification: 117 X  
Acceleration voltages (kV): 20.00  
Process time: 6






Photo report CR /  
ARA  
EDS report

2.008-0148

**BOSCH**

Project: 2008-0148  
Owner: camscan  
Area: Work area 1


Sample: 2008-0148 ÜV  
Type: Specification  
ID:





400 µm

Electron image 1





Magnification: 144 X  
Acceleration voltages (kV): 20.00  
Process time: 6




EA11003EN-00858[0]



 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.	[REDACTED]													
				Date	1/28/2008													
Department:	Person responsible:	Telephone:	Use	internal														
Non-responsive content removed		[REDACTED]		external		x												
To:	Non-responsive content removed																	
For information:	[REDACTED]																	
<b>Pump type:</b> CP4.1S_348_2x5,25_REC_3,3_1,95_X		<b>Customer:</b> VW	<b>Project:</b> R4 2.0 EU5	<b>Project / design pattern type</b> C / C2														
<b>Part number (TTNo.):</b> 0445B21058_07		<b>Date of manufacture:</b> 690	<b>Serial number:</b> 4705	<b>Manufacturing plant - line</b> 011M FeP (Feuerbach plant) – M														
<b>SAP-No.:</b> DS -154935		<b>Samos no.:</b> 568692	<b>Customer order no.:</b> 03LA/17772	<b>Engine/Vehicle number</b> 03LA/17772														
<b>Customer part number</b> 03LA/17772		<b>Endurance run type [customer]:</b> CR-engine	<b>Endurance run conditions:</b> IFL	<b>DSBFD no.:</b> 18596														
<b>Mileage</b> 600 h		<b>Parts receipt at dept. DS-PC/EDI:</b> 7/18/2007	<b>Process no.</b> 2007-CP4_0145	<b>Confidentiality note</b> Confidential														
<b>1. Subject</b> CP4 customer return Internal release of endurance run (VW entry)																		
<b>2. Conclusion</b> The pump has <b>passed</b> the test.																		
<b>3. Results of diagnosis (visual findings)</b> <div style="float: right; text-align: right;">       Legend rating stages {       <div style="display: inline-block; vertical-align: middle; margin-right: 5px;">OK</div> <div style="display: inline-block; vertical-align: middle; margin-right: 5px;">uncritical</div> <div style="display: inline-block; vertical-align: middle;">Critical</div> </div> <table style="margin-left: auto; margin-right: 0;"> <tr> <td style="background-color: green; color: white;">X</td> <td></td> <td></td> <td></td> </tr> <tr> <td></td> <td style="background-color: yellow; color: black;">X</td> <td></td> <td></td> </tr> <tr> <td></td> <td></td> <td></td> <td style="background-color: red; color: white;">X</td> </tr> </table>							X					X						X
X																		
	X																	
			X															
<b>3.1 Drive</b> No striking feature				<table style="background-color: green; color: white;"> <tr> <td>X</td> <td></td> <td></td> <td></td> </tr> </table>			X											
X																		
<b>3.2 Drivetrain</b> Very slight running marks recognizable (Example: Fig. 1 camshaft and Fig. 2 roller)				<table style="background-color: green; color: white;"> <tr> <td>X</td> <td></td> <td></td> <td></td> </tr> </table>			X											
X																		
<b>3.3 High pressure</b> Very slight running marks recognizable (Fig. 3 HP piston)				<table style="background-color: green; color: white;"> <tr> <td>X</td> <td></td> <td></td> <td></td> </tr> </table>			X											
X																		
<b>3.4 Bearing</b> No striking feature (Fig. 4 Flange bearing)				<table style="background-color: green; color: white;"> <tr> <td>X</td> <td></td> <td></td> <td></td> </tr> </table>			X											
X																		
<b>3.5 Shaft seal</b> No striking feature				<table style="background-color: green; color: white;"> <tr> <td>X</td> <td></td> <td></td> <td></td> </tr> </table>			X											
X																		
<b>3.6 Holes</b> No striking feature				<table style="background-color: green; color: white;"> <tr> <td>X</td> <td></td> <td></td> <td></td> </tr> </table>			X											
X																		



 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no. <span style="background-color: black; color: black;">[REDACTED]</span>	
				Date 1/28/2008	
Department:	Person responsible:	Telephone:	Use	internal	
Non-responsive content removed				external	x
3.7 Attached components (Metering Unit, Overflow Valve, Counting Point)				x	
No striking feature					
3.8 Other					
<b>4. Hydraulic function</b>					
				Delivery rate [l/h] of new part	Delivery rate [l/h] after testing
	n[rpm]	p <sub>rail</sub> [bar]	I <sub>MU</sub> [A]	11/29/2006	7/26/2007
ST	200	200	0.4	3.9	3.9
LG	1000	1800	0.4	17.4	17.4
KL1-S	3375	500	0.4	66.5	67.4
					x
					x
					x
No striking feature					
<b>5. Destiny of the parts</b>					
The parts will be stored at RB until 08/2008					
					
Fig. 1 Camshaft					
					
Fig. 2: Roller					
					
Fig. 3: HP piston					
					
Fig. 4: Flange bearing					
Tested:	Non-responsive content removed	Phone	Non-responsive content removed	Date:	3/31/2008
Signature:				Signature:	Non-responsive content removed
Department:		Phone		Date:	4/10/2008
Signature:				Signature:	
Department:		Phone		Date:	4/11/2008
Signature:				Signature:	



		<b>CR pump CP4 - Diagnosis report</b>		Report no. Date	2/27/2008												
<b>Department:</b> Non-responsive content removed	<b>Person responsible:</b> Non-responsive content removed	<b>Telephone:</b> Non-responsive content removed	Use	internal external	x												
<b>To:</b> Non-responsive content removed																	
<b>For information:</b> Non-responsive content removed																	
<b>Pump type:</b> CP4.1S_348_2x5,25_REC_3,3_1,95_220	<b>Customer:</b> VW	<b>Project:</b> R4 2.0 EU5	<b>Project / design pattern type</b> C / C2														
<b>Part number (TTNo.):</b> 0445B21058_06	<b>Date of manufacture:</b> 689	<b>Serial number:</b> 4890	<b>Manufacturing plant - line</b> 011M FeP (Feuerbach plant) – M														
<b>SAP-No.:</b> 30-101005-07	<b>Samos no.:</b> 578258	<b>Customer order no.:</b>	<b>Engine/Vehicle number</b> 03LA/17098														
<b>Customer part number</b>	<b>Endurance run type [customer]:</b> Engine endurance run	<b>Endurance run conditions:</b> VW462-7-02224	<b>DSBFD no.:</b> 19419														
<b>Mileage</b> 19940 h	<b>Parts receipt at dept. DS-PC/EDI:</b> 10/22/2007	<b>Process no.</b> 2007-CP4_0148	<b>Confidentiality note</b> Confidential														
<b>VA / ETC no.:</b> DS-164766	<b>Endurance run type [RB]:</b>																
<b>Complaint:</b>																	
<b>1. Subject</b> CP4 customer return Diagnosis of endurance run end without complaint																	
<b>2. Conclusion</b> <b>Function</b> - Delivery rates after endurance run without significant fuel-quantity drift in comparison with the new state. <b>Components</b> - Wear of the components is low and without significant striking features. <b>Result</b> The pump has <b>passed</b> the test.																	
<b>3. Results of diagnosis (visual findings)</b>																	
<b>3.1 Drive</b> No striking feature			Legend rating stages	OK uncritical Critical	<table border="1"> <tr><td>x</td><td></td><td></td></tr> <tr><td></td><td>x</td><td></td></tr> <tr><td></td><td></td><td>x</td></tr> <tr><td>x</td><td></td><td></td></tr> </table>	x				x				x	x		
x																	
	x																
		x															
x																	
<b>3.2 Drivetrain</b> Lateral roller slip off (no picture available)					<table border="1"> <tr><td></td><td>x</td><td></td></tr> </table>		x										
	x																
<b>3.3 High pressure</b> No striking feature					<table border="1"> <tr><td>x</td><td></td><td></td></tr> </table>	x											
x																	
<b>3.4 Bearing</b> No striking feature					<table border="1"> <tr><td>x</td><td></td><td></td></tr> </table>	x											
x																	
<b>3.5 Shaft seal</b> No striking feature					<table border="1"> <tr><td>x</td><td></td><td></td></tr> </table>	x											
x																	
<b>3.6 Holes</b> No striking feature					<table border="1"> <tr><td>x</td><td></td><td></td></tr> </table>	x											
x																	
<b>3.7 Attached components (Metering Unit, Overflow Valve, Counting Point)</b> No striking feature					<table border="1"> <tr><td>x</td><td></td><td></td></tr> </table>	x											
x																	
<b>3.8 Other</b>					<table border="1"> <tr><td>x</td><td></td><td></td></tr> </table>	x											
x																	

EA11003EN-00859[1]  
No striking feature



 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no. <span style="background-color: black; color: black;">[REDACTED]</span>	
				Date 2/27/2008	
Department:	Person responsible:	Telephone:	Use <span style="float: right;">internal <input type="checkbox"/> external <input checked="" type="checkbox"/></span>		
Non-responsive content removed					
<b>4. Hydraulic function</b>					
				Delivery rate [l/h] of new part	Delivery rate [l/h] after testing
	n[rpm]	p_rail [bar]	I_MU [A]	9/12/2006	10/23/2007
Starting point	200	200	0.4	3.9	3.9
1000 rpm, p_rated	1000	1800	0.4	17.1	17
n_max p, 500bar	3375	500	0.4	65.8	66.6
				<div style="background-color: green; width: 15px; height: 15px; display: flex; align-items: center; justify-content: center;">x</div>	<div style="background-color: green; width: 15px; height: 15px; display: flex; align-items: center; justify-content: center;">x</div>
				<div style="background-color: green; width: 15px; height: 15px; display: flex; align-items: center; justify-content: center;">x</div>	<div style="background-color: green; width: 15px; height: 15px; display: flex; align-items: center; justify-content: center;">x</div>
TCD (technical customer documentation) testing point LG (1,000 rpm, p_rated ≥ 15.5 or 15.2 l/h after running time) is met.					
No significant fuel-quantity drift compared to delivery measurement.					
<b>5. Destiny of the parts</b>					
The pump is stored at RB until 06/2008 and then scrapped.					
<b>6. Attachments</b>					
None					
Tested:	Non-responsive content removed	Phone:	Non-responsive content removed	Date:	3/31/2008
Signature:	Non-responsive content removed				
Department:	Non-responsive content removed	Phone:	Non-responsive content removed	Date:	4/10/2008
Signature:	Non-responsive content removed				
Department:	Non-responsive content removed	Phone:	Non-responsive content removed	Date:	4/11/2008
Signature:	Non-responsive content removed				





EA11003EN-00860[0]

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no. <span style="background-color: black; color: black;">[REDACTED]</span>										
				Date 1/22/2008										
Department:	Person responsible:	Telephone:	Use internal external <input checked="" type="checkbox"/>											
Non-responsive content removed														
To:	Non-responsive content removed													
For information:														
<b>Pump type:</b> CP4.1S_348_2x5,25_REC_3,3_1,95_MT4,2		<b>Customer:</b> VW	<b>Project:</b> R4 2.0 EU5	<b>Project / design pattern type</b> C / C										
<b>Part number (TTNo.):</b> 0445B21058		<b>Date of manufacture:</b> 081206	<b>Serial number:</b> 0035	<b>Manufacturing plant - line</b> 011M FeP (Feuerbach plant) – M -										
<b>SAP-No.:</b> DS-164776		<b>Samos no.:</b> 578285	<b>Customer order no.:</b> CBA0000303	<b>Engine/Vehicle number</b> CBA0000 303										
<b>Customer part number</b> CBA0000303		<b>Endurance run type [customer]:</b> CR-engine	<b>Endurance run conditions:</b> GDV;CBA 0000 303	<b>DSBFD no.:</b> 19415										
<b>Mileage</b> 52008 h		<b>Parts receipt at dept. DS-PC/EDI:</b> 10/22/2007	<b>Process no.</b> 2007-CP4_0151	<b>Confidentiality note</b> Confidential										
<b>1. Subject</b> CP4 customer return														
<b>2. Conclusion</b> No striking features detected.														
<b>3. Results of diagnosis (visual findings)</b>														
<b>3.1 Drive</b> No striking feature			Legend rating stages { OK uncritical Critical <table border="1" style="float: right;"> <tr><td>X</td><td></td><td></td></tr> <tr><td></td><td>X</td><td></td></tr> <tr><td></td><td></td><td>X</td></tr> </table>			X				X				X
X														
	X													
		X												
<b>3.2 Drivetrain</b> Very slight running marks visible			<table border="1"> <tr><td>X</td><td></td><td></td></tr> <tr><td>X</td><td></td><td></td></tr> </table>			X			X					
X														
X														
<b>3.3 High pressure</b> Slight wear marks visible			<table border="1"> <tr><td>X</td><td></td><td></td></tr> </table>			X								
X														
<b>3.4 Bearing</b> No striking feature			<table border="1"> <tr><td>X</td><td></td><td></td></tr> </table>			X								
X														
<b>3.5 Shaft seal</b> No striking feature			<table border="1"> <tr><td>X</td><td></td><td></td></tr> </table>			X								
X														
<b>3.6 Holes</b> No striking feature			<table border="1"> <tr><td>X</td><td></td><td></td></tr> </table>			X								
X														
<b>3.7 Attached components (Metering Unit, Overflow Valve, Counting Point)</b> No striking feature			<table border="1"> <tr><td>X</td><td></td><td></td></tr> </table>			X								
X														
<b>4. Destiny of the parts</b> The parts are stored until 07/2008 at RB														
Tested:	Non-responsive content removed	Phone:	Non-responsive content removed	Date:	1/23/2008									
Department:		Phone:		Date:	1/23/2008									
Signature:		Signature:		Signature:										
Department:		Phone:		Date:	1/26/2008									
Signature:		Signature:		Signature:										

EA11003EN-00861[0]

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.	[REDACTED]													
				Date	1/24/2008													
Department:	Person responsible:	Telephone:	internal <input type="checkbox"/> external <input checked="" type="checkbox"/>															
Non-responsive content removed		[REDACTED]		Use														
To:	Non-responsive content removed																	
For information:	[REDACTED]																	
<b>Pump type:</b> CP4.1S_348_2x5,25_REC_3,3_1,95_MT4,2		<b>Customer:</b> VW	<b>Project:</b> R4 2.0 EU5	<b>Project / design pattern type</b> C / C														
<b>Part number (TTNo.):</b> 0445B21058_02		<b>Date of manufacture:</b> 685	<b>Serial number:</b> 4747	<b>Manufacturing plant - line</b> 011M FeP (Feuerbach plant) – M														
<b>SAP-No.:</b> DS -164778		<b>Samos no.:</b> 0578290	<b>Customer order no.:</b>	<b>Engine/Vehicle number</b> 03LD/16369														
<b>Customer part number</b>		<b>Endurance run type [customer]:</b> Engine trial	<b>Endurance run conditions:</b> Function	<b>DSBFD no.:</b> 19414														
<b>Mileage</b> 2056 h		<b>Parts receipt at dept. DS-PC/EDI:</b> 10/22/2007	<b>Process no.</b> 2007-CP4_0152	<b>Confidentiality note</b> Confidential														
<b>1. Subject</b> CP4 customer return Endurance run end																		
<b>2. Conclusion</b> The parts have an incipient wear (2,056 h running time). Anti-friction paint fragments were found in the pump. The pump was mounted before end 06/2006. Between 05/2006 and 06/2006, problem of adhesion occurred during the application of the anti-friction paint on the spring plate. Since then, the process has been improved. Copper particles which do not come from CP4 were also found on overflow valve and the metering unit screen. Risk of nozzle clogging! The origin of the copper should be clarified by the customer, since it is not the first case. The pump has <b>passed</b> the test.																		
<b>3. Results of diagnosis (visual findings)</b>																		
<b>3.1 Drive</b> No striking feature			Legend rating stages { <table border="1"> <tr> <td>OK</td> <td><input checked="" type="checkbox"/></td> <td><input type="checkbox"/></td> <td><input type="checkbox"/></td> </tr> <tr> <td>uncritical</td> <td><input type="checkbox"/></td> <td><input checked="" type="checkbox"/></td> <td><input type="checkbox"/></td> </tr> <tr> <td>Critical</td> <td><input type="checkbox"/></td> <td><input type="checkbox"/></td> <td><input checked="" type="checkbox"/></td> </tr> </table>				OK	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	uncritical	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Critical	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
OK	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>															
uncritical	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>															
Critical	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>															
<b>3.2 Drivetrain</b> Incipient cavitation on the piston base at the roller support (Fig. 1). Anti-friction paint on the spring plate peeled-off (Fig. 2).			<table border="1"> <tr> <td><input checked="" type="checkbox"/></td> <td><input type="checkbox"/></td> <td><input type="checkbox"/></td> </tr> <tr> <td><input type="checkbox"/></td> <td><input checked="" type="checkbox"/></td> <td><input type="checkbox"/></td> </tr> </table>				<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>						
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>																
<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>																
<b>3.3 High pressure</b> Incipient fretting wear at the seal seat of the intake valve (Fig. 3)			<table border="1"> <tr> <td><input type="checkbox"/></td> <td><input checked="" type="checkbox"/></td> <td><input type="checkbox"/></td> </tr> </table>				<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>									
<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>																
<b>3.4 Bearing</b> No striking feature			<table border="1"> <tr> <td><input checked="" type="checkbox"/></td> <td><input type="checkbox"/></td> <td><input type="checkbox"/></td> </tr> </table>				<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>									
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>																
<b>3.5 Shaft seal</b> Incipient wear of the shaft seal on the camshaft (Figure 4)			<table border="1"> <tr> <td><input type="checkbox"/></td> <td><input checked="" type="checkbox"/></td> <td><input type="checkbox"/></td> </tr> </table>				<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>									
<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>																
<b>3.6 Holes</b> Anti-friction paint of the spring plate in the metering unit hole of the housing (Fig. 5)			<table border="1"> <tr> <td><input type="checkbox"/></td> <td><input checked="" type="checkbox"/></td> <td><input type="checkbox"/></td> </tr> </table>				<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>									
<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>																
<b>3.7 Attached components (Metering Unit, Overflow Valve, Counting Point)</b> Anti-friction paint of the spring plate on the metering unit sieve. Copper on overflow valve and metering unit screen			<table border="1"> <tr> <td><input type="checkbox"/></td> <td><input checked="" type="checkbox"/></td> <td><input type="checkbox"/></td> </tr> </table>				<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>									
<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>																
<b>3.8 Other</b>			<table border="1"> <tr> <td><input type="checkbox"/></td> <td><input type="checkbox"/></td> <td><input type="checkbox"/></td> </tr> </table>				<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>									
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>																

 <b>BOSCH</b> 	<b>CR pump CP4 - Diagnosis report</b>		Report no.	[REDACTED]	
			Date	1/24/2008	
Department:	Person responsible:	Telephone:	Use	internal	
Non-responsive content removed				external	x

#### 4. Hydraulic function

	n[rpm]	p_rail [bar]	I_MU [A]	Delivery rate [l/h] of new part 5/10/2006	Delivery rate [l/h] after testing 10/23/2007	
ST	200	200	0.4	3.9	3.9	X
LG-1	1000	1800	0.4	17.4	17.1	X
KL-1S	3375	500	0.4	67.4	67.5	X

No striking feature

#### 5. Destiny of the parts

The parts will be stored at RB until 08/2008




Fig. 1: Roller support




Fig. 2: Spring plate



Fig. 3: Intake valve




Fig. 4: Camshaft




Fig. 5: Metering unit screen








Figure 6: Overflow valve screen

Tested:	Non-responsive content removed	Telephone:	Non-responsive content removed	Date:	1/25/2008	Signature:	Non-responsive content removed
Department:		Telephone:		Date:	1/28/2008	Signature:	
Department:		Telephone:		Date:	1/29/2008	Signature:	





 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.													
				Date	2/27/2008												
<b>Department:</b> Non-responsive content removed	<b>Person responsible:</b> Non-responsive content removed	<b>Telephone:</b> Non-responsive content removed	Use	internal external	x												
<b>To:</b> Non-responsive content removed																	
<b>For information:</b> Non-responsive content removed																	
<b>Pump type:</b> CP4.1S_348_2x5,25_REC_3,3_1,95_MT4,2	<b>Customer:</b> VW	<b>Project:</b> R4 2.0 EU5	<b>Project / design pattern type</b> C / C														
<b>Part number (TTNo.):</b> 0445B21058	<b>Date of manufacture:</b> 010207	<b>Serial number:</b> 0080	<b>Manufacturing plant - line</b> 011M FeP (Feuerbach plant) – M														
<b>SAP-No.:</b> 30-101005-07	<b>Samos no.:</b> 578254	<b>Customer order no.:</b>	<b>Engine/Vehicle number</b> CAG 0000 082														
<b>Customer part number</b>	<b>Endurance run type [customer]:</b> Engine endurance run	<b>Endurance run conditions:</b> Reso-run	<b>DSBFD no.:</b> 19421														
<b>Mileage</b> 209 h	<b>Parts receipt at dept. DS-PC/EDI:</b> 10.22.2007	<b>Process no.</b> 2007-CP4_0153	<b>Confidentiality note</b> Confidential														
<b>VA / ETC no.:</b> DS-164759	<b>Durability test type [RB]:</b>																
<b>Complaint:</b>																	
<b>1. Subject</b> CP4 customer return Findings at the end of endurance run																	
<b>2. Conclusion</b> No back measurement of the function, because a fuel-quantity drift due to the running time is not expected and there is no complaint. Wear of the components is low and without significant striking features. The pump has <b>passed</b> the test.																	
<b>3. Results of diagnosis (visual findings)</b>																	
<b>3.1 Drive</b> No striking feature			Legend rating stages <table border="1"> <tr> <td>OK</td> <td>X</td> <td></td> <td></td> </tr> <tr> <td>uncritical</td> <td></td> <td>X</td> <td></td> </tr> <tr> <td>Critical</td> <td></td> <td></td> <td>X</td> </tr> </table>			OK	X			uncritical		X		Critical			X
OK	X																
uncritical		X															
Critical			X														
<b>3.2 Drivetrain</b> No striking feature			<table border="1"> <tr> <td>X</td> <td></td> <td></td> </tr> <tr> <td>X</td> <td></td> <td></td> </tr> </table>			X			X								
X																	
X																	
<b>3.3 High pressure</b> No striking feature			<table border="1"> <tr> <td>X</td> <td></td> <td></td> </tr> </table>			X											
X																	
<b>3.4 Bearing</b> No striking feature			<table border="1"> <tr> <td>X</td> <td></td> <td></td> </tr> </table>			X											
X																	
<b>3.5 Shaft seal</b> No striking feature			<table border="1"> <tr> <td>X</td> <td></td> <td></td> </tr> </table>			X											
X																	
<b>3.6 Holes</b> No striking feature			<table border="1"> <tr> <td>X</td> <td></td> <td></td> </tr> </table>			X											
X																	
<b>3.7 Attached components (Metering Unit, Overflow Valve, Counting Point)</b> No striking feature			<table border="1"> <tr> <td>X</td> <td></td> <td></td> </tr> </table>			X											
X																	
<b>3.8 Other</b> No striking feature			<table border="1"> <tr> <td></td> <td></td> <td></td> </tr> </table>														

EA11003EN-00862[1]



 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.		[REDACTED]	
				Date		2/27/2008	
Department:	Person responsible:	Telephone:		Use		internal	
Non-responsive content removed		[REDACTED]				external	x
<b>4. Hydraulic function</b>							
				Delivery rate [l/h] of new part	Delivery rate [l/h] after testing		
	n[rpm]	p_rail [bar]	I_MU [A]				
No functional testing due to the short running time and classification in the third diagnosis category.							
<b>5. Destiny of the parts</b>							
The parts are stored at RB until 06/2008 and then scrapped.							
<b>6. Attachments</b>							
None							
Tested:	Non-responsive content removed	Telephone:	Non-responsive content removed	Date:	2/29/2008	Signature:	Non-responsive content removed
Department:	[REDACTED]	Telephone:	[REDACTED]	Date:	3/4/2008	Signature:	[REDACTED]
Department:	[REDACTED]	Telephone:	[REDACTED]	Date:	3/6/2008	Signature:	[REDACTED]

EA11003EN-00863[0]

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.														
				Date	2/27/2008													
Department:	Person responsible:	Telephone:	Use	internal														
Non-responsive content removed				external	x													
To:	Non-responsive content removed																	
For information:																		
<b>Pump type:</b> CP4.1S_348_2x5,25_REC_3,3_1,95_MT4,2		<b>Customer:</b> VW	<b>Project:</b> R4 2.0 EU5	<b>Project / design pattern type</b> C / C														
<b>Part number (TTNo.):</b> 445010507		<b>Date of manufacture:</b> 270407	<b>Serial number:</b> 0008	<b>Manufacturing plant - line</b> 011M FeP (Feuerbach plant) – M														
<b>SAP-No.:</b> 30-101005-07		<b>Samos no.:</b> 577765	<b>Customer order no.:</b>	<b>Engine/Vehicle number</b> CBDP170811														
<b>Customer part number</b>		<b>Endurance run type [customer]:</b> Engine endurance run	<b>Endurance run conditions:</b> ÖVL+PZD	<b>DSBFD no.:</b> 19444														
<b>Mileage</b> 227 h		<b>Parts receipt at dept. DS-PC/EDI:</b> 10/17/2007	<b>Process no.</b> 2007-CP4_0154	<b>Confidentiality note</b> Confidential														
<b>VA / ETC no.:</b> DS-164722		<b>Durability test type [RB]:</b>																
<b>Complaint:</b>																		
<b>1. Subject</b> CP4 customer return Diagnosis of endurance run end without complaint																		
<b>2. Conclusion</b> <b>Function</b> - Delivery rates after endurance run without significant fuel-quantity drift in comparison with the new state. <b>Components</b> - Wear of the components is low and without significant striking features. <b>Result</b> - The pump has <b>passed</b> the endurance run.																		
<b>3. Results of diagnosis (visual findings)</b> <div style="float: right; text-align: right;">           Legend rating stages           <table border="1" style="display: inline-table; vertical-align: middle;"> <tr> <td>OK</td> <td></td> <td></td> <td></td> </tr> <tr> <td>uncritical</td> <td></td> <td></td> <td></td> </tr> <tr> <td>Critical</td> <td></td> <td></td> <td></td> </tr> </table> </div>							OK				uncritical				Critical			
OK																		
uncritical																		
Critical																		
<b>3.1 Drive</b> No striking feature			<table border="1" style="width: 100px;"> <tr><td style="background-color: green;">x</td><td></td><td></td></tr> <tr><td></td><td style="background-color: yellow;">x</td><td></td></tr> <tr><td></td><td></td><td style="background-color: red;">x</td></tr> <tr><td style="background-color: green;">x</td><td></td><td></td></tr> </table>				x				x				x	x		
x																		
	x																	
		x																
x																		
<b>3.2 Drivetrain</b> Lateral roller slip off (no picture available)			<table border="1" style="width: 100px;"> <tr><td></td><td style="background-color: yellow;">x</td><td></td></tr> </table>					x										
	x																	
<b>3.3 High pressure</b> No striking feature			<table border="1" style="width: 100px;"> <tr><td style="background-color: green;">x</td><td></td><td></td></tr> </table>				x											
x																		
<b>3.4 Bearing</b> No striking feature			<table border="1" style="width: 100px;"> <tr><td style="background-color: green;">x</td><td></td><td></td></tr> </table>				x											
x																		
<b>3.5 Shaft seal</b> No striking feature			<table border="1" style="width: 100px;"> <tr><td style="background-color: green;">x</td><td></td><td></td></tr> </table>				x											
x																		
<b>3.6 Holes</b> No striking feature			<table border="1" style="width: 100px;"> <tr><td style="background-color: green;">x</td><td></td><td></td></tr> </table>				x											
x																		
<b>3.7 Attached components (Metering Unit, Overflow Valve, Counting Point)</b> No striking feature			<table border="1" style="width: 100px;"> <tr><td style="background-color: green;">x</td><td></td><td></td></tr> </table>				x											
x																		
<b>3.8 Other</b> No striking feature			<table border="1" style="width: 100px;"> <tr><td style="background-color: green;">x</td><td></td><td></td></tr> </table>				x											
x																		



EA11003EN-00863[1]

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no. <span style="background-color: black; color: black;">[REDACTED]</span>	
				Date 2/27/2008	
Department:	Person responsible:	Telephone:		Use	internal <input type="checkbox"/> external <input checked="" type="checkbox"/>
Non-responsive content removed					

**4. Hydraulic function**

	n[rpm]	p_rail [bar]	I_MU [A]	Delivery rate [l/h] of new part 4/27/2007	Delivery rate [l/h] after testing 10/25/2007
Starting point	200	200	0.4	3.9	4.1
1000 rpm, p_rated	1000	1800	0.4	17.7	17.8
n_max_p, 500bar	3375	500	0.4	67.3	65.9

TCD (technical customer documentation) testing point LG (1,000 rpm, p\_rated ≥ 15.5 or 15.2 l/h after running time) is met.

No significant fuel-quantity drift compared to delivery measurement.

x		
x		
x		

**5. Destiny of the parts**



The pump is stored at RB until 06/2008 and then scrapped.

**6. Attachments**



None

Tested:	Non-responsive content removed	Telephone:	Non-responsive content removed	Date:	3/31/2008	Signature:	Non-responsive content removed
Department:		Telephone:		Date:	4/10/2008	Signature:	
Department:		Telephone:		Date:	4/11/2008	Signature:	

EA11003EN-00864[0]



 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.		
				Date	2/27/2008	
Department:	Person responsible:	Telephone:		Use	internal	
Non-responsive content removed					external	x
To:	Non-responsive content removed					
For information:						
<b>Pump type:</b> CP4.1S_348_2x5,25_REC_3,3_1,95_MT4,2	<b>Customer:</b> VW	<b>Project:</b> R4 2.0 EU5	<b>Project / design pattern type</b> C / C			
<b>Part number (TTNo.):</b> 0445B21058	<b>Date of manufacture:</b> 020207	<b>Serial number:</b> 0028	<b>Manufacturing plant - line</b> 011M FeP (Feuerbach plant) – M			
<b>SAP-No.:</b> 30-101005-07	<b>Samos no.:</b> 577772	<b>Customer order no.:</b>	<b>Engine/Vehicle number</b> 3LAP270109			
<b>Customer part number</b>	<b>Endurance run type [customer]:</b> Engine endurance run	<b>Endurance run conditions:</b> 70h ÖVL+70h PZD	<b>DSBFD no.:</b> 19438			
<b>Mileage</b> 340 h	<b>Parts receipt at dept. DS-PC/EDI:</b> 10/17/2007	<b>Process no.</b> 2007-CP4_0156	<b>Confidentiality note</b> Confidential			
<b>VA / ETC no.:</b> DS-164727	<b>Durability test type [RB]:</b>					
<b>Complaint:</b>						
<b>1. Subject</b> CP4 customer return Findings at the end of endurance run						
<b>2. Conclusion</b> Delivery rates after endurance run or test in accordance with the specifications. Wear of the components is low and without significant striking features.  The pump has <b>passed</b> the endurance run.						
<b>3. Results of diagnosis (visual findings)</b> <div style="float: right; text-align: right;">           Legend rating stages {           <div style="display: inline-block; vertical-align: middle; margin-left: 5px;">             OK uncritical Critical           </div> </div>						
<b>3.1 Drive</b> No striking feature				<div style="display: flex; align-items: center;"> <div style="width: 20px; height: 20px; background-color: green; border: 1px solid black; margin-right: 5px;"></div> <div style="width: 20px; height: 20px; background-color: yellow; border: 1px solid black; margin-right: 5px;"></div> <div style="width: 20px; height: 20px; background-color: red; border: 1px solid black;"></div> </div>		
<b>3.2 Drivetrain</b> Lateral roller slip off (no picture available)				<div style="display: flex; align-items: center;"> <div style="width: 20px; height: 20px; background-color: green; border: 1px solid black; margin-right: 5px;"></div> <div style="width: 20px; height: 20px; background-color: white; border: 1px solid black; margin-right: 5px;"></div> <div style="width: 20px; height: 20px; background-color: white; border: 1px solid black;"></div> </div>		
<b>3.3 High pressure</b> No striking feature				<div style="display: flex; align-items: center;"> <div style="width: 20px; height: 20px; background-color: green; border: 1px solid black; margin-right: 5px;"></div> <div style="width: 20px; height: 20px; background-color: white; border: 1px solid black; margin-right: 5px;"></div> <div style="width: 20px; height: 20px; background-color: white; border: 1px solid black;"></div> </div>		
<b>3.4 Bearing</b> No striking feature				<div style="display: flex; align-items: center;"> <div style="width: 20px; height: 20px; background-color: green; border: 1px solid black; margin-right: 5px;"></div> <div style="width: 20px; height: 20px; background-color: white; border: 1px solid black; margin-right: 5px;"></div> <div style="width: 20px; height: 20px; background-color: white; border: 1px solid black;"></div> </div>		
<b>3.5 Shaft seal</b> No striking feature				<div style="display: flex; align-items: center;"> <div style="width: 20px; height: 20px; background-color: green; border: 1px solid black; margin-right: 5px;"></div> <div style="width: 20px; height: 20px; background-color: white; border: 1px solid black; margin-right: 5px;"></div> <div style="width: 20px; height: 20px; background-color: white; border: 1px solid black;"></div> </div>		
<b>3.6 Holes</b> No striking feature				<div style="display: flex; align-items: center;"> <div style="width: 20px; height: 20px; background-color: green; border: 1px solid black; margin-right: 5px;"></div> <div style="width: 20px; height: 20px; background-color: white; border: 1px solid black; margin-right: 5px;"></div> <div style="width: 20px; height: 20px; background-color: white; border: 1px solid black;"></div> </div>		
<b>3.7 Attached components (Metering Unit, Overflow Valve, Counting Point)</b> No striking feature				<div style="display: flex; align-items: center;"> <div style="width: 20px; height: 20px; background-color: green; border: 1px solid black; margin-right: 5px;"></div> <div style="width: 20px; height: 20px; background-color: white; border: 1px solid black; margin-right: 5px;"></div> <div style="width: 20px; height: 20px; background-color: white; border: 1px solid black;"></div> </div>		
<b>3.8 Other</b> No striking feature				<div style="display: flex; align-items: center;"> <div style="width: 20px; height: 20px; background-color: green; border: 1px solid black; margin-right: 5px;"></div> <div style="width: 20px; height: 20px; background-color: white; border: 1px solid black; margin-right: 5px;"></div> <div style="width: 20px; height: 20px; background-color: white; border: 1px solid black;"></div> </div>		



EA11003EN-00864[1]

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.			
				Date		2/27/2008	
Department:	Person responsible:	Telephone:		Use		internal	
Non-responsive content removed						external	x
<b>4. Hydraulic function</b>							
	n[rpm]	p_rail [bar]	I_MU [A]	Delivery rate [l/h] of new part 2/2/2007	Delivery rate [l/h] after testing 10/25/2007		
Starting point	200	200	0.4	3.9	4.1	x	
1000 rpm, p_rated	1000	1800	0.4	17.6	17.7	x	
n_max_p, 500bar	3375	500	0.4	65.6	66.1	x	
<p>TCD (technical customer documentation) testing point LG (1,000 rpm, p_rated ≥ 15.5 or 15.2 l/h after running time) is met.</p> <p>No significant fuel-quantity drift compared to delivery measurement.</p>							
<b>5. Destiny of the parts</b>							
The pump is stored at RB until 06/2008 and then scrapped.							
<b>6. Attachments</b>							
None							
Tested:	Non-responsive content removed	Telephone:	Non-responsive content removed	Date:	2/29/2008	Signature:	Non-responsive content removed
Department:		Telephone:		Date:	04.03.02008	Signature:	
Department:		Telephone:		Date:	3/6/2008	Signature:	



EA11003EN-00865[0]

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.														
				Date	3/27/2008													
Department:	Person responsible:	Telephone:		Use	internal													
Non-responsive content removed					external	x												
To:	Non-responsive content removed																	
For information:																		
<b>Pump type:</b> CP4.1S_348_2x5,25_REC_3,3_1,95		<b>Customer:</b> VW	<b>Project:</b> R4 2.0 EU5	<b>Project / design pattern type</b> C / C1														
<b>Part number (TTNo.):</b> 0445B21058_02		<b>Date of manufacture:</b> 685	<b>Serial number:</b> 4742	<b>Manufacturing plant - line</b> 011M FeP (Feuerbach plant) – M														
<b>SAP-No.:</b> DS-164746		<b>Samos no.:</b> 577913	<b>Customer order no.:</b>	<b>Engine/Vehicle number</b> 03LA/16870														
<b>Customer part number</b>		<b>Endurance run type [customer]:</b>	<b>Endurance run conditions:</b> CR-engine	<b>DSBFD no.:</b> 19425														
<b>Mileage</b> 70440 h		<b>Parts receipt at dept. DS-PC/EDI:</b> 10/17/2007	<b>Process no.</b> 2007-CP4_0160	<b>Confidentiality note</b> Confidential														
<b>1. Subject</b> CP4 customer returns without complaint Diagnosis after endurance run end Engine testing conditions unknown.																		
<b>2. Conclusion</b> <b>Function</b> Functioning OK Particle accumulation on metering unit screen: Contamination residues of plastic and aluminum alloy. The particles could originate from the pump housing, but this could not be proven through a fault. The origin of the plastic particles could not be determined. The pump has <b>passed</b> the test.																		
<b>3. Results of diagnosis (visual findings)</b> <div style="float: right; text-align: right;">         Legend rating stages         <table border="1" style="display: inline-table; vertical-align: middle;"> <tr> <td>OK</td> <td style="background-color: green; color: white;">x</td> <td></td> <td></td> </tr> <tr> <td>uncritical</td> <td></td> <td style="background-color: yellow; color: black;">x</td> <td></td> </tr> <tr> <td>Critical</td> <td></td> <td></td> <td style="background-color: red; color: white;">x</td> </tr> </table> </div>							OK	x			uncritical		x		Critical			x
OK	x																	
uncritical		x																
Critical			x															
<b>3.1 Drive</b> No striking feature				<table border="1" style="width: 100px;"> <tr><td style="background-color: green; color: white;">x</td><td></td><td></td></tr> <tr><td style="background-color: green; color: white;">x</td><td></td><td></td></tr> </table>			x			x								
x																		
x																		
<b>3.2 Drivetrain</b> Only running marks visible				<table border="1" style="width: 100px;"> <tr><td style="background-color: green; color: white;">x</td><td></td><td></td></tr> <tr><td style="background-color: green; color: white;">x</td><td></td><td></td></tr> </table>			x			x								
x																		
x																		
<b>3.3 High pressure</b> Slight fretting wear at the seal seat of the intake valve (Fig. 1)				<table border="1" style="width: 100px;"> <tr><td style="background-color: green; color: white;">x</td><td></td><td></td></tr> <tr><td style="background-color: green; color: white;">x</td><td></td><td></td></tr> </table>			x			x								
x																		
x																		
<b>3.4 Bearing</b> No striking feature				<table border="1" style="width: 100px;"> <tr><td style="background-color: green; color: white;">x</td><td></td><td></td></tr> <tr><td style="background-color: green; color: white;">x</td><td></td><td></td></tr> </table>			x			x								
x																		
x																		
<b>3.5 Shaft seal</b> Slight recession of shaft seals < 10 µm (Fig. 2)				<table border="1" style="width: 100px;"> <tr><td></td><td style="background-color: yellow; color: black;">x</td><td></td></tr> <tr><td></td><td style="background-color: yellow; color: black;">x</td><td></td></tr> </table>				x			x							
	x																	
	x																	
<b>3.6 Holes</b> No striking feature				<table border="1" style="width: 100px;"> <tr><td style="background-color: green; color: white;">x</td><td></td><td></td></tr> <tr><td style="background-color: green; color: white;">x</td><td></td><td></td></tr> </table>			x			x								
x																		
x																		
<b>3.7 Attached components (Metering Unit, Overflow Valve, Counting Point)</b> Particle collection of contamination residues (origin unknown) and aluminum (possibly from CP4 housing) on the metering unit screen (Fig. 3)				<table border="1" style="width: 100px;"> <tr><td></td><td style="background-color: yellow; color: black;">x</td><td></td></tr> <tr><td></td><td style="background-color: yellow; color: black;">x</td><td></td></tr> </table>				x			x							
	x																	
	x																	
<b>3.8 Other</b> Pump outside slightly rusted (Fig. 2)				<table border="1" style="width: 100px;"> <tr><td></td><td style="background-color: yellow; color: black;">x</td><td></td></tr> <tr><td></td><td style="background-color: yellow; color: black;">x</td><td></td></tr> </table>				x			x							
	x																	
	x																	

 <b>BOSCH</b> 	<b>CR pump CP4 - Diagnosis report</b>		Report no.		
			Date		
Department:	Person responsible:	Telephone:	Use	internal	
Non-responsive content removed				external	x

**4. Hydraulic function**

	n[rpm]	p_rail [bar]	I_MU [A]	New part 5/10/2006	After testing 10/23/2007
Starting point	200	200	0.4	3.9	3.9
1000 rpm, p_rated	1000	1800	0.4	16.9	17.1
n_max_p, 500bar	3375	500	0.4	67.0	66.9

x		
x		
x		

No striking feature

**5. Destiny of the parts**

The parts are stored until 09/2008 at RB



Fig. 1: Intake valve






Fig. 2: Camshaft running surface of shaft seal



Fig. 3: Metering Unit


Tested:	Non-responsive content removed	Phone:	Non-responsive content removed	Date:	4/2/2008	Signature:	Non-responsive content removed
Department:		Phone:		Date:	4/10/2008	Signature:	
Department:		Phone:		Date:	4/11/2008	Signature:	

EA11003EN-00866[0]

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.										
				Date	1/23/2008									
Department:	Person responsible:	Telephone:	Use											
Non-responsive content removed			internal											
			external		x									
To:	Non-responsive content removed													
For information:														
<b>Pump type:</b> CP4.1S_348_2x5,25_REC_3,3_1,95_X	<b>Customer:</b> VW	<b>Project:</b> R4 2.0 EU5	<b>Project / design pattern type</b> C / C											
<b>Part number (TTNo.):</b> 0445B21058_01	<b>Date of manufacture:</b> 684	<b>Serial number:</b> 4555	<b>Manufacturing plant - line</b> 011M FeP (Feuerbach plant)-M -											
<b>SAP-No.:</b> DS-164756	<b>Samos no.:</b> 577931	<b>Customer order no.:</b>	<b>Engine/Vehicle number</b> 03LC/18145											
<b>Customer part number</b>	<b>Endurance run type [customer]:</b> CR-engine	<b>Endurance run conditions:</b> ÖVL+endurance run 1	<b>DSBFD no.:</b> 19422											
<b>Mileage</b> 495 h	<b>Parts receipt at dept. DS-PC/EDI:</b> 10/17/2007	<b>Process no.</b> 2007-CP4_0161	<b>Confidentiality note</b> Confidential											
<b>VA / ETC no.:</b>	<b>Durability test type [RB]:</b>													
<b>Complaint:</b>														
<b>1. Subject</b> CP4 customer return Endurance run end ÖVL+endurance run 1														
<b>2. Conclusion</b> The pump does not show any kind of striking feature. The pump has passed the test.														
<b>3. Results of diagnosis (visual findings)</b> <b>3.1 Drive</b> No striking feature		Legend rating stages	{ OK uncritical Critical	<table border="1"> <tr><td>x</td><td></td><td></td></tr> <tr><td></td><td>x</td><td></td></tr> <tr><td></td><td></td><td>x</td></tr> </table>		x				x				x
x														
	x													
		x												
<b>3.2 Drivetrain</b> No striking feature			<table border="1"> <tr><td>x</td><td></td><td></td></tr> </table>		x									
x														
<b>3.3 High pressure</b> No striking feature			<table border="1"> <tr><td>x</td><td></td><td></td></tr> </table>		x									
x														
<b>3.4 Bearing</b> No striking feature			<table border="1"> <tr><td>x</td><td></td><td></td></tr> </table>		x									
x														
<b>3.5 Shaft seal</b> No striking feature			<table border="1"> <tr><td>x</td><td></td><td></td></tr> </table>		x									
x														
<b>3.6 Holes</b> No striking features			<table border="1"> <tr><td>x</td><td></td><td></td></tr> </table>		x									
x														
<b>3.7 Attached components (metering unit, overflow valve, counting point)</b> No striking features			<table border="1"> <tr><td>x</td><td></td><td></td></tr> </table>		x									
x														
<b>3.8 Other</b>			<table border="1"> <tr><td></td><td></td><td></td></tr> </table>											



EA11003EN-00866[1]

		<b>CR pump CP4 - Diagnosis report</b>		Report no. <span style="background-color: black; color: black;">[REDACTED]</span>	
				Date 5/23/2008	
Department:	Person responsible:	Telephone:	Use		
Non-responsive content removed			internal external <input checked="" type="checkbox"/>		

**4. Hydraulic function**

	n[rpm]	p_rail [bar]	I_MU [A]	New part 4/12/2006	After testing 10/23/2007
Starting point	200	200	0.4	3.9	3.9
1000 rpm, p Rated	1000	1800	0.4	17.4	17.4
n_max_p, 500bar	3375	500	0.4	67.2	67.2

x		
x		
x		

No striking feature



**5. Destiny of the parts**



The parts are stored until 07/2008 at RB

<b>Tested:</b>	Non-responsive content removed	<b>Phone</b>	Non-responsive content removed	<b>Date:</b>	1/25/2008	<b>Signature:</b>	Non-responsive content removed
<b>Department:</b>	<span style="background-color: black; color: black;">[REDACTED]</span>	<b>Phone</b>	<span style="background-color: black; color: black;">[REDACTED]</span>	<b>Date:</b>	1/28/2008	<b>Signature:</b>	<span style="background-color: black; color: black;">[REDACTED]</span>
<b>Department:</b>	<span style="background-color: black; color: black;">[REDACTED]</span>	<b>Phone</b>	<span style="background-color: black; color: black;">[REDACTED]</span>	<b>Date:</b>	1/29/2008	<b>Signature:</b>	<span style="background-color: black; color: black;">[REDACTED]</span>

EA11003EN-00867101

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.										
				Date	2/27/2008									
Department:	Person responsible:	Telephone:	Use <input type="checkbox"/> internal <input checked="" type="checkbox"/> external											
Non-responsive content removed														
To:	Non-responsive content removed													
For information:														
<b>Pump type:</b> CP4.1S_348_2x5,25_REC_3,3_1,8_MT4,2	<b>Customer:</b> VW	<b>Project:</b> R4 2.0 EU5	<b>Project / design pattern type</b> C2 / D1											
<b>Part number (TTNo.):</b> 0445B21058	<b>Date of manufacture:</b> 010207	<b>Serial number:</b> 0117	<b>Manufacturing plant - line</b> 011M FeP (Feuerbach plant)-M -											
<b>SAP-No.:</b> 30-101005-07	<b>Samos no.:</b> 588442	<b>Customer order no.:</b>	<b>Engine/Vehicle number</b> 03LC/18158											
<b>Customer part number</b>	<b>Endurance run type [customer]:</b> Engine endurance run	<b>Endurance run conditions:</b> ÖVL+PZD	<b>DSBFD no.:</b> 20211											
<b>Mileage</b> 594 h	<b>Parts receipt at dept. DS-PC/EDI:</b> 11/29/2007	<b>Process no.</b> 2007-CP4_0163	<b>Confidentiality note</b> Confidential											
<b>VA / ETC no.:</b> DS-175045	<b>Durability test type [RB]:</b>													
<b>Complaint:</b>														
<b>1. Subject</b> CP4 customer return Findings at the end of durability test														
<b>2. Conclusion</b> Delivery rates after endurance run or test in accordance with the specifications. Wear of the components is low and without significant striking features. On the flange front surface, two marks with a diameter of 6 mm can be seen, probably from a puller. The pump has <b>passed</b> the test.														
<b>3. Results of diagnosis (visual findings)</b>		Legend rating stages	OK { uncritical Critical	<table border="1"> <tr><td>x</td><td></td><td></td></tr> <tr><td></td><td>x</td><td></td></tr> <tr><td></td><td></td><td>x</td></tr> </table>		x				x				x
x														
	x													
		x												
<b>3.1 Drive</b> No striking feature				<table border="1"> <tr><td>x</td><td></td><td></td></tr> </table>		x								
x														
<b>3.2 Drivetrain</b> Lateral roller slip-off slightly increased (see Figs. 1 and 2)				<table border="1"> <tr><td></td><td>x</td><td></td></tr> </table>			x							
	x													
<b>3.3 High pressure</b> No striking feature				<table border="1"> <tr><td>x</td><td></td><td></td></tr> </table>		x								
x														
<b>3.4 Bearing</b> No striking feature				<table border="1"> <tr><td>x</td><td></td><td></td></tr> </table>		x								
x														
<b>3.5 Shaft seal</b> No striking feature				<table border="1"> <tr><td>x</td><td></td><td></td></tr> </table>		x								
x														
<b>3.6 Holes</b> No striking features				<table border="1"> <tr><td>x</td><td></td><td></td></tr> </table>		x								
x														
<b>3.7 Attached components (metering unit, overflow valve, counting point)</b> No striking features				<table border="1"> <tr><td>x</td><td></td><td></td></tr> </table>		x								
x														
<b>3.8 Other</b> Marks on flange front surface with 6 mm diameter (see Fig. 3)				<table border="1"> <tr><td>x</td><td></td><td></td></tr> </table>		x								
x														

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.	[REDACTED]	
				Date	2/27/2008	
Department:	Person responsible:	Telephone:	Use	internal	external	
Non-responsive content removed					x	

### 3.9 Images of visual findings




Fig. 1: Tappet body inside, housing side




Fig. 2: Roller front surface, housing side




Fig. 3: Flange front surface

### 4. Hydraulic function

	n[rpm]	p_rail [bar]	I_MU [A]	Delivery rate [l/h] New part	Delivery rate [l/h] after testing
				1/31/2007	12/5/2007
Starting point	200	200	0.4	3.9	3.9
1000 rpm, p Rated	1000	1800	0.4	17.6	17.6
n_max_p, 500bar	3375	500	0.4	66.8	66.6

x		
x		
x		

TCD (technical customer documentation) testing point LG (1,000 rpm, p<sub>rated</sub> ≥ 15.5 or 15.2 l/h after running time) is met.

No significant fuel-quantity drift compared to delivery measurement.

### 5. Destiny of the parts

The pump is stored at RB until 06/2008 and then scrapped.



### 6. Attachments

None

Tested:	Non-responsive content removed	Phone	Non-responsive content removed	Date:	2/29/2008	Signature:	Non-responsive content removed
Department:	Non-responsive content removed	Phone	Non-responsive content removed	Date:	3/4/2008	Signature:	Non-responsive content removed
Department:	Non-responsive content removed	Phone	Non-responsive content removed	Date:	3/6/2008	Signature:	Non-responsive content removed





EA11003EN-00868[0]

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.		
				Date	2/28/2008	
Department:	Person responsible:	Telephone:	Use <input type="checkbox"/> internal <input checked="" type="checkbox"/> external			
Non-responsive content removed						
To:	Non-responsive content removed					
For information:						
<b>Pump type:</b> CP4.1S_348_2x5,25_REC_3,3_1,8_MT4,2		<b>Customer:</b> VW	<b>Project:</b> R4 2.0 EU5	<b>Project / design pattern type</b> C2 / D1		
<b>Part number (TTNo.):</b> 0445B21058	<b>Date of manufacture:</b> 081206	<b>Serial number:</b> 0068	<b>Manufacturing plant - line</b> 011M FeP (Feuerbach plant)-M -			
<b>SAP-No.:</b> 30-101005-07	<b>Samos no.:</b> 588456	<b>Customer order no.:</b>	<b>Engine/Vehicle number</b> 3LAP270051			
<b>Customer part number</b>	<b>Endurance run type [customer]:</b> Engine endurance run	<b>Endurance run conditions:</b> Function	<b>DSBFD no.:</b> 20210			
<b>Mileage</b> 836 h	<b>Parts receipt at dept. DS-PC/EDI:</b> 11/29/2007	<b>Process no.</b> 2007-CP4_0164	<b>Confidentiality note</b> Confidential			
<b>VA / ETC no.:</b>	<b>Durability test type [RB]:</b>					
<b>Complaint:</b>						
<b>1. Subject</b> CP4 customer return Findings at the end of endurance run						
<b>2. Conclusion</b> Delivery rates after endurance run or test in accordance with the specifications. The wear of the components is low. striking features that are uncritical: - metering unit O-ring was slightly cut by slanted mounting or screw-fitting (typical marks). - On the flange front surface, two marks with a diameter of 6 mm can be seen, probably from a puller. The pump has <b>passed</b> the test.						
<b>3. Results of diagnosis (visual findings)</b>			Legend rating stages		OK <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> uncritical <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> Critical <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	
<b>3.1 Drive</b> No striking feature			<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	
<b>3.2 Drivetrain</b> No striking feature			<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	
<b>3.3 High pressure</b> No striking feature			<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	
<b>3.4 Bearing</b> No striking feature			<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	
<b>3.5 Shaft seal</b> No striking feature			<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	
<b>3.6 Holes</b> No striking features			<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	
<b>3.7 Attached components (metering unit, overflow valve, counting point)</b> Metering unit O-ring slightly cut, marks of slanted assembly (see Fig. 2)			<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>	
<b>3.8 Other</b>			<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	

EA11003EN-00868[1]

Marks on flange front surface with 6 mm diameter (see Fig. 3)

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.	
				Date	2/28/2008
Department:	Person responsible:	Telephone:	Use	internal	
Non-responsive content removed			external		x

## 3.9 Images of visual findings




Fig. 1 Metering unit




Fig. 2 Metering unit, detail view O-ring




Fig. 3 Flange front surface

## 4. Hydraulic function

	n[rpm]	p_rail [bar]	I_MU [A]	Delivery rate [l/h] of new part	Delivery rate [l/h] after testing
				2/1/2007	12/5/2007
Starting point	200	200	0.4	3.9	3.7
1000 rpm, p_rated	1000	1800	0.4	17.8	17.7
n_max_p, 500bar	3375	500	0.4	64.8	66.6

x		
x		
x		

TCD (technical customer documentation) testing point LG (1,000 rpm, p\_rated ≥ 15.5 or 15.2 l/h after running time) is met. No significant fuel-quantity drift compared to delivery measurement.

## 5. Destiny of the parts

The pump is stored at RB until 06/2008 and then scrapped.

## 6. Attachments

None



Tested:	Non-responsive content removed	Phone	Non-responsive content removed	Date:	3/29/2008	Signature:	Non-responsive content removed
Department:		Phone		Date:	3/4/2008	Signature:	




EA11003EN-00868[2]



<b>Department:</b>	Non-responsive content removed	<b>Phone</b>	Non-responsive content removed	<b>Date:</b>	3/6/2008	<b>Signature:</b>	Non-responsive content removed
--------------------	--------------------------------	--------------	--------------------------------	--------------	----------	-------------------	--------------------------------









EA11003EN-00869[0]

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.																							
				Date	2/28/2008																						
Department:	Person responsible:	Telephone:		Use	internal																						
Non-responsive content removed			external		x																						
To:	Non-responsive content removed																										
For information:																											
<b>Pump type:</b> CP4.1S_348_2x5,25_REC_3,3_1,8_MT4,2		<b>Customer:</b> VW	<b>Project:</b> R4 2.0 EU5	<b>Project / design pattern type</b> C / C1																							
<b>Part number (TTNo.):</b> 0445B21058_02		<b>Date of manufacture:</b> 686	<b>Serial number:</b> 4007	<b>Manufacturing plant - line</b> 011M FeP (Feuerbach plant)-M -																							
<b>SAP-No.:</b> 30-101005-07		<b>Samos no.:</b> 588456	<b>Customer order no.:</b>	<b>Engine/Vehicle number</b> 03LD/16702																							
<b>Customer part number</b>	<b>Endurance run type [customer]:</b> Engine endurance run	<b>Endurance run conditions:</b> PZD+ÖVL		<b>DSBFD no.:</b> 20204																							
<b>Mileage</b> 485 h	<b>Parts receipt at dept. DS-PC/EDI:</b> 11/29/2007	<b>Process no.</b> 2007-CP4_0165		<b>Confidentiality note</b> Confidential																							
<b>VA / ETC no.:</b> DS-175058		<b>Durability test type [RB]:</b>																									
<b>Complaint:</b>																											
<b>1. Subject</b> CP4 customer return Findings at the end of endurance run																											
<b>2. Conclusion</b> Delivery rates after endurance run or test in accordance with the specifications. The wear of the components is low. The screen of the metering unit is contaminated with foreign particles. The pump has <b>passed</b> the test.																											
<b>3. Results of diagnosis (visual findings)</b> <b>3.1 Drive</b> No striking feature			Legend rating stages { <table border="1"> <tr> <td>OK</td> <td>x</td> <td></td> <td></td> </tr> <tr> <td>uncritical</td> <td></td> <td>x</td> <td></td> </tr> <tr> <td>Critical</td> <td></td> <td></td> <td>x</td> </tr> </table>		OK	x			uncritical		x		Critical			x	<table border="1"> <tr> <td>x</td> <td></td> <td></td> </tr> <tr> <td></td> <td></td> <td></td> </tr> <tr> <td></td> <td></td> <td></td> </tr> </table>		x								
OK	x																										
uncritical		x																									
Critical			x																								
x																											
<b>3.2 Drivetrain</b> No striking feature					<table border="1"> <tr> <td>x</td> <td></td> <td></td> </tr> <tr> <td></td> <td></td> <td></td> </tr> <tr> <td></td> <td></td> <td></td> </tr> </table>		x																				
x																											
<b>3.3 High pressure</b> No striking feature					<table border="1"> <tr> <td>x</td> <td></td> <td></td> </tr> <tr> <td></td> <td></td> <td></td> </tr> <tr> <td></td> <td></td> <td></td> </tr> </table>		x																				
x																											
<b>3.4 Bearing</b> No striking feature					<table border="1"> <tr> <td>x</td> <td></td> <td></td> </tr> <tr> <td></td> <td></td> <td></td> </tr> <tr> <td></td> <td></td> <td></td> </tr> </table>		x																				
x																											
<b>3.5 Shaft seal</b> No striking feature					<table border="1"> <tr> <td>x</td> <td></td> <td></td> </tr> <tr> <td></td> <td></td> <td></td> </tr> <tr> <td></td> <td></td> <td></td> </tr> </table>		x																				
x																											
<b>3.6 Holes</b> No striking features					<table border="1"> <tr> <td>x</td> <td></td> <td></td> </tr> <tr> <td></td> <td></td> <td></td> </tr> <tr> <td></td> <td></td> <td></td> </tr> </table>		x																				
x																											
<b>3.7 Attached components (metering unit, overflow valve, counting point)</b> No striking feature					<table border="1"> <tr> <td>x</td> <td></td> <td></td> </tr> <tr> <td></td> <td></td> <td></td> </tr> <tr> <td></td> <td></td> <td></td> </tr> </table>		x																				
x																											



 <b>BOSCH</b>				<b>CR pump CP4 - Diagnosis report</b>		Report no.	
						Date	2/28/2008
Department:	Person responsible:	Telephone:		Use		internal	
Non-responsive content removed						external	x
<b>3.8 Other</b>						<input checked="" type="checkbox"/>	
Foreign particles on the metering unit screen (see Fig. 1)							
<b>3.9 Images of visual findings</b>							
							
<b>Fig. 1: Metering unit, screen (foreign particles)</b>							
<b>4. Hydraulic function</b>							
				Delivery rate [l/h] of new part	Delivery rate [l/h] after testing		
	n[rpm]	p <sub>rail</sub> [bar]	I <sub>MU</sub> [A]	6/8/2006	12/4/2007		
Starting point	200	200	0.4	3.9	3.9	<input checked="" type="checkbox"/>	
1000 rpm, p <sub>rated</sub>	1000	1800	0.4	17	17.2	<input checked="" type="checkbox"/>	
n <sub>max_p</sub> , 500bar	3375	500	0.4	66.8	66.6	<input checked="" type="checkbox"/>	
TCD (technical customer documentation) testing point LG (1,000 rpm, p <sub>rated</sub> ≥ 15.5 or 15.2 l/h after running time) is met.							
No significant fuel-quantity drift compared to delivery measurement.							
<b>5. Destiny of the parts</b>							
The pump is stored at RB until 06/2008 and then scrapped.							
<b>6. Attachments</b>							
None							
Tested:	Non-responsive content removed	Phone	Non-responsive content removed	Date:	3/29/2008	Signature:	Non-responsive content removed
Department:		Phone		Date:	3/4/2008	Signature:	
Department:		Phone		Date:	3/6/2008	Signature:	

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.													
				Date	2/28/2008												
Department:	Person responsible:	Telephone:	Use														
Non-responsive content removed			internal														
			external		x												
To:	Non-responsive content removed																
For information:																	
<b>Pump type:</b> CP4.1S_348_2x5,25_REC_3,3_1,8_MT4,2		<b>Customer:</b> VW	<b>Project:</b> R4 2.0 EU5	<b>Project / design pattern type</b> C / C													
<b>Part number (TTNo.):</b> 0445B21058_01	<b>Date of manufacture:</b> 685	<b>Serial number:</b> 4734	<b>Manufacturing plant - line</b> 011M FeP (Feuerbach plant)-M -														
<b>SAP-No.:</b> 30-101581-07	<b>Samos no.:</b> 588479	<b>Customer order no.:</b>	<b>Engine/Vehicle number</b> 03LA/16587														
<b>Customer part number</b>	<b>Endurance run type [customer]:</b> Engine endurance run	<b>Endurance run conditions:</b> endurance run 1+ÖVL	<b>DSBFD no.:</b> 20203														
<b>Mileage</b> 450 h	<b>Parts receipt at dept. DS-PC/EDI:</b> 11/29/2007	<b>Process no.</b> 2007-CP4_0166	<b>Confidentiality note</b> Confidential														
<b>VA / ETC no.:</b> DS-175060	<b>Durability test type [RB]:</b>																
<b>Complaint:</b>																	
<b>1. Subject</b> CP4 customer return Diagnosis of endurance run end without complaint																	
<b>2. Conclusion</b> <b>Function</b> - Delivery rates after endurance run without significant fuel-quantity drift in comparison with the new state. <b>Striking features</b> - The pump was disassembled by the customer for self analysis and then reassembled (specification on the pump). The chip along the flange press-in diameter is due to this reassembly. The contamination by foreign particles is also probably due to this or the entry via the low-pressure system upstream to the pump. - The severe corrosion on the cam and the roller outside the running range is due to the presence of free water. - The taper of the camshaft shows significant corrosion. - The existing cavitation erosion suggests insufficient internal pump chamber pressure during operation. <b>Components</b> - The wear of the components is low. <b>Result</b> - The pump has passed the <b>endurance run</b>																	
<b>3. Results of diagnosis (visual findings)</b> <b>3.1 Drive</b> Severe corrosion on the taper (see Fig. 1)			Legend rating stages { <table border="1"> <tr> <td>OK</td> <td></td> <td></td> <td></td> </tr> <tr> <td>uncritical</td> <td>x</td> <td></td> <td></td> </tr> <tr> <td>Critical</td> <td></td> <td></td> <td>x</td> </tr> </table>			OK				uncritical	x			Critical			x
OK																	
uncritical	x																
Critical			x														
<b>3.2 Drivetrain</b> Corrosion of the camshaft (see Fig. 2), roller's lateral slip off (see Figures 3 to 4)			<table border="1"> <tr> <td></td> <td>x</td> <td></td> <td></td> </tr> <tr> <td></td> <td>x</td> <td></td> <td></td> </tr> </table>				x				x						
	x																
	x																
<b>3.3 High pressure</b> Small cavitation erosion area in the HP range (see Fig. 5)z			<table border="1"> <tr> <td></td> <td>x</td> <td></td> <td></td> </tr> </table>				x										
	x																



 <b>BOSCH</b>				<b>CR pump CP4 - Diagnosis report</b>		Report no. <span style="background-color: black; color: black;">[REDACTED]</span>
				Date <b>2/28/2008</b>		
<b>Department:</b> Non-responsive content removed	<b>Person responsible:</b> Non-responsive content removed	<b>Telephone:</b> Non-responsive content removed		<b>Use</b> internal <input type="checkbox"/> external <input checked="" type="checkbox"/>		
<b>To:</b> Non-responsive content removed						
<b>For information:</b> Non-responsive content removed						
<b>3.4 Bearing</b> No striking feature				<input checked="" type="checkbox"/>		
<b>3.5 Shaft seal</b> Slight recession of the shaft seal into the camshaft				<input checked="" type="checkbox"/>		
<b>3.6 Holes</b> Cavitation erosion in the tappet hole outside the moving range of the tappet (see Fig. 6); foreign particles in the metering unit hole (see Fig. 7) and in the overflow valve hole (see Fig. 8)				<input checked="" type="checkbox"/>		
<b>3.7 Attached components (metering unit, overflow valve, counting point)</b> Foreign particles on the screen of the metering unit (see Fig. 9) and the screen of the overflow valve (see Fig. 10)				<input checked="" type="checkbox"/>		
<b>3.8 Other</b> Chip on the press-in diameter due to flange assembly (see Figures 11 and 12)				<input checked="" type="checkbox"/>		
<b>3.9 Images of visual findings</b>						
						
<b>Fig. 1 Camshaft, running range of shaft seal and</b>						
						
<b>Fig. 2 Camshaft, top dead center</b>						
						
<b>Fig. 3 Tappet body inside, housing side</b>						
						
<b>Fig. 4 Roller front surface, housing side</b>						

EA11003EN-00870[2]

 <b>BOSCH</b>			<b>CR pump CP4 - Diagnosis report</b>		Report no. <span style="background-color: black; color: black;">[REDACTED]</span>
				Date <b>2/28/2008</b>	
<b>Department:</b> Non-responsive content removed	<b>Person responsible:</b> Non-responsive content removed	<b>Telephone:</b> Non-responsive content removed		<b>Use</b> internal <input type="checkbox"/> external <input checked="" type="checkbox"/>	
<b>To:</b> Non-responsive content removed					
<b>For information:</b> Non-responsive content removed					




Fig. 5 High-pressure piston, high-pressure




Fig. 6 Tappet hole, top



Fig. 7 Housing, metering unit



Fig. 8 Housing, overflow valve




Fig. 9 metering






Fig. 10 Overflow valve, screen



EA11003EN-00870131

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.	[REDACTED]	
				Date	2/28/2008	
Department:	Person responsible:	Telephone:	Use			
Non-responsive content removed			internal <input type="checkbox"/> external <input checked="" type="checkbox"/>			
To:	Non-responsive content removed					
For information:	[REDACTED]					




Fig. 11 Flange, press-in composite







Fig. 13 Housing, press-in diameter





EA11003EN-00870141

		<b>CR pump CP4 - Diagnosis report</b>		Report no. <span style="background-color: black; color: black;">[REDACTED]</span>																															
				Date 2/28/2008																															
<b>Department:</b> Non-responsive content removed	<b>Person responsible:</b> Non-responsive content removed	<b>Telephone:</b> Non-responsive content removed	<b>Use</b> <table border="1"> <tr> <td>internal</td> <td></td> <td></td> </tr> <tr> <td>external</td> <td>x</td> <td></td> </tr> </table>			internal			external	x																									
internal																																			
external	x																																		
<p><b><u>4. Hydraulic function</u></b></p> <table border="1"> <thead> <tr> <th></th> <th>n[rpm]</th> <th>p_rail [bar]</th> <th>I_MU [A]</th> <th>Delivery rate [l/h] of new part</th> <th>Delivery rate [l/h] after testing</th> </tr> </thead> <tbody> <tr> <td></td> <td></td> <td></td> <td></td> <td>5/8/2006</td> <td>12/4/2007</td> </tr> <tr> <td>Starting point</td> <td>200</td> <td>200</td> <td>0.4</td> <td>3.9</td> <td>3.9</td> </tr> <tr> <td>1000 rpm, p Rated</td> <td>1000</td> <td>1800</td> <td>0.4</td> <td>17.1</td> <td>17.1</td> </tr> <tr> <td>n_max_p, 500bar</td> <td>3375</td> <td>500</td> <td>0.4</td> <td>67.5</td> <td>66.8</td> </tr> </tbody> </table> <p>TCD (technical customer documentation) testing point LG (1,000 rpm, p Rated ≥ 15.5 or 15.2 l/h after running time) is met.</p> <p>No significant fuel-quantity drift compared to delivery measurement.</p>							n[rpm]	p_rail [bar]	I_MU [A]	Delivery rate [l/h] of new part	Delivery rate [l/h] after testing					5/8/2006	12/4/2007	Starting point	200	200	0.4	3.9	3.9	1000 rpm, p Rated	1000	1800	0.4	17.1	17.1	n_max_p, 500bar	3375	500	0.4	67.5	66.8
	n[rpm]	p_rail [bar]	I_MU [A]	Delivery rate [l/h] of new part	Delivery rate [l/h] after testing																														
				5/8/2006	12/4/2007																														
Starting point	200	200	0.4	3.9	3.9																														
1000 rpm, p Rated	1000	1800	0.4	17.1	17.1																														
n_max_p, 500bar	3375	500	0.4	67.5	66.8																														
<p><b><u>5. Destiny of the parts</u></b></p> <p>The pump is stored at RB until 06/2008 and then scrapped.</p>																																			
<p><b><u>6. Attachments</u></b></p> <p>None</p>																																			
<b>Tested:</b> Non-responsive content removed	<b>Phone</b> Non-responsive content removed	<b>Date:</b> 5/13/2008	<b>Signature:</b> Non-responsive content removed																																
<b>Department:</b> Non-responsive content removed	<b>Phone</b> Non-responsive content removed	<b>Date:</b> 5/20/2008	<b>Signature:</b> Non-responsive content removed																																
<b>Department:</b> Non-responsive content removed	<b>Phone</b> Non-responsive content removed	<b>Date:</b> 5/28/2008	<b>Signature:</b> Non-responsive content removed																																

EA11003EN-00871101

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.										
				Date	2/28/2008									
Department:	Person responsible:	Telephone:	Use <input type="checkbox"/> internal <input checked="" type="checkbox"/> external											
Non-responsive content removed														
To:	Non-responsive content removed													
For information:														
<b>Pump type:</b> CP4.1S_348_2x5,25_REC_3,3_1,8_MT4,2		<b>Customer:</b> VW	<b>Project:</b> R4 2.0 BIN5	<b>Project / design pattern type</b> B / B										
<b>Part number (TTNo.):</b> 0445B21058_06		<b>Date of manufacture:</b> 689	<b>Serial number:</b> 4141	<b>Manufacturing plant - line</b> 011M FeP (Feuerbach plant)-M -										
<b>SAP-No.:</b> 30-101005-07		<b>Samos no.:</b> 588471	<b>Customer order no.:</b>	<b>Engine/Vehicle number</b> 03LD/17236; VW 351-780123										
<b>Customer part number</b>	<b>Endurance run type [customer]:</b> Vehicle endurance run	<b>Endurance run conditions:</b> WL1	<b>DSBFD no.:</b> 20216											
<b>Mileage</b> 19825 km	<b>Parts receipt at dept. DS-PC/EDI:</b> 11/29/2007	<b>Process no.</b> 2007-CP4_0169	<b>Confidentiality note</b> Confidential											
<b>VA / ETC no.:</b> DS-175052	<b>Durability test type [RB]:</b>													
<b>Complaint:</b>														
<b>1. Subject</b> CP4 customer return Diagnosis of endurance run end without complaint														
<b>2. Conclusion</b> <b>Function</b> - Delivery rates after endurance run without significant fuel-quantity drift in comparison with the new state. <b>Components</b> - Wear of the components is low and without any striking features. <b>Result</b> - The pump has <b>passed</b> the endurance run.														
<b>3. Results of diagnosis (visual findings)</b>														
			Legend rating stages { <div>           OK            uncritical            Critical         </div>	<table border="1"> <tr><td>x</td><td></td><td></td></tr> <tr><td></td><td>x</td><td></td></tr> <tr><td></td><td></td><td>x</td></tr> </table>		x				x				x
x														
	x													
		x												
<b>3.1 Drive</b> No striking feature			<table border="1"> <tr><td>x</td><td></td><td></td></tr> </table>			x								
x														
<b>3.2 Drivetrain</b> Lateral roller slip-off slightly increased (see Figs. 1 and 2) slight cavitation erosion on the roller support back (see Figs. 3 and 4)			<table border="1"> <tr><td></td><td>x</td><td></td></tr> </table>				x							
	x													
<b>3.3 High pressure</b> No striking feature			<table border="1"> <tr><td>x</td><td></td><td></td></tr> </table>			x								
x														
<b>3.4 Bearing</b> No striking feature			<table border="1"> <tr><td>x</td><td></td><td></td></tr> </table>			x								
x														
<b>3.5 Shaft seal</b> Slight recession of the shaft seals into the camshaft (see Fig. 5)			<table border="1"> <tr><td></td><td>x</td><td></td></tr> </table>				x							
	x													
<b>3.6 Holes</b> No striking features			<table border="1"> <tr><td>x</td><td></td><td></td></tr> </table>			x								
x														

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.		
				Date	2/28/2008	
Department:	Person responsible:	Telephone:		Use	internal	
Non-responsive content removed			external		x	
<b>3.7 Attached components (metering unit, overflow valve, counting point)</b>					<input checked="" type="checkbox"/>	
No striking feature						
<b>3.8 Other</b>					<input checked="" type="checkbox"/>	
No striking feature						


**3.9 Images of visual findings**

Fig. 1 Tappet body inside, flange side




Fig. 2 Roller front surface, flange side




Fig. 3 Roller support, piston base support




Fig. 4 Roller support, piston base support in








Fig. 5 Camshaft, moving range of shaft seal



EA11003EN-00871[2]


 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.			
				Date		2/28/2008	
<b>Department:</b>		<b>Person responsible:</b>		<b>Telephone:</b>		Use <input type="checkbox"/> internal <input checked="" type="checkbox"/> external	
Non-responsive content removed							
<b>4. Hydraulic function</b>							
	n[rpm]	p_rail [bar]	I_MU [A]	Delivery rate [l/h] of new part	Delivery rate [l/h] after testing		
				9/25/2006	12/4/2007		
Starting point	200	200	0.4	3.7	3.9	<input checked="" type="checkbox"/>	
1000 rpm, p Rated	1000	1800	0.4	17	17.7	<input checked="" type="checkbox"/>	
n_max_p, 500bar	3375	500	0.4	67.3	67.2	<input checked="" type="checkbox"/>	
TCD (technical customer documentation) testing point LG (1,000 rpm, p Rated $\geq 15.5$ or 15.2 l/h after running time) is met. No significant fuel-quantity drift compared to delivery measurement.							
<b>5. Destiny of the parts</b>							
The pump is stored at RB until 06/2008 and then scrapped.							
<b>6. Attachments</b>							
None							
<b>Tested:</b>	Non-responsive content removed	<b>Phone</b>	Non-responsive content removed	<b>Date:</b>	3/31/2008	<b>Signature:</b>	Non-responsive content removed
<b>Department:</b>		<b>Phone</b>		<b>Date:</b>	4/10/2008	<b>Signature:</b>	
<b>Department:</b>		<b>Phone</b>		<b>Date:</b>	4/11/2008	<b>Signature:</b>	

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.														
				Date	1/30/2008													
Department:	Person responsible:	Telephone:	Use <input type="checkbox"/> internal <input checked="" type="checkbox"/> external															
Non-responsive content removed																		
To:	Non-responsive content removed																	
For information:																		
<b>Pump type:</b> CP4.1S_348_2x5,25_REC_3,3_1,8_MT4,2	<b>Customer:</b> VW	<b>Project:</b> R4 2.0 EU5	<b>Project / design pattern type</b> C / C2															
<b>Part number (TTNo.):</b> 0445B21058_07	<b>Date of manufacture:</b> 690	<b>Serial number:</b> 4364	<b>Manufacturing plant - line</b> 011M FeP (Feuerbach plant)-M -															
<b>SAP-No.:</b> 30-1015814-07	<b>Samos no.:</b> 588476	<b>Customer order no.:</b>	<b>Engine/Vehicle number</b> 03LB/17818															
<b>Customer part number</b>	<b>Endurance run type [customer]:</b> Vehicle endurance run	<b>Endurance run conditions:</b> Ehra variable track for passenger cars	<b>DSBFD no.:</b> 20205															
<b>Mileage</b> 99850 km	<b>Parts receipt at dept. DS-PC/EDI:</b> 11/29/2007	<b>Process no.</b> 2007-CP4_0172	<b>Confidentiality note</b> Confidential															
<b>VA / ETC no.:</b> DS-175056	<b>Durability test type [RB]:</b>																	
<b>Complaint:</b>																		
<b>1. Subject</b> CP4 customer return Diagnosis of endurance run end without complaint																		
<b>2. Conclusion</b> <b>Function</b> - The pump was dismantled without back measurement for the visual findings. <b>Components</b> - Wear of the components is low and without significant striking features. <b>Result</b> - The pump has <b>passed</b> the endurance run.																		
<b>3. Results of diagnosis (visual findings)</b> <div style="float: right; text-align: right;">         Legend rating stages         <table border="0" style="margin-left: 10px;"> <tr> <td rowspan="3" style="font-size: 2em; vertical-align: middle;">{</td> <td>OK</td> <td style="background-color: green; color: white; text-align: center;">x</td> <td></td> <td></td> </tr> <tr> <td>uncritical</td> <td></td> <td style="background-color: yellow; text-align: center;">x</td> <td></td> </tr> <tr> <td>Critical</td> <td></td> <td></td> <td style="background-color: red; color: white; text-align: center;">x</td> </tr> </table> </div>						{	OK	x			uncritical		x		Critical			x
{	OK	x																
	uncritical		x															
	Critical			x														
<b>3.1 Drive</b> No striking feature <div style="float: right;"> <table border="1" style="background-color: green; color: white; text-align: center;"> <tr><td>x</td><td></td><td></td></tr> </table> </div>						x												
x																		
<b>3.2 Drivetrain</b> Slight lateral roller slip-off (see Figs. 1 and 2) <div style="float: right;"> <table border="1" style="background-color: yellow; text-align: center;"> <tr><td>x</td><td></td><td></td></tr> </table> </div>						x												
x																		
<b>3.3 High pressure</b> No striking feature <div style="float: right;"> <table border="1" style="background-color: green; color: white; text-align: center;"> <tr><td>x</td><td></td><td></td></tr> </table> </div>						x												
x																		
<b>3.4 Bearing</b> No striking feature <div style="float: right;"> <table border="1" style="background-color: green; color: white; text-align: center;"> <tr><td>x</td><td></td><td></td></tr> </table> </div>						x												
x																		
<b>3.5 Shaft seal</b> No striking feature <div style="float: right;"> <table border="1" style="background-color: green; color: white; text-align: center;"> <tr><td>x</td><td></td><td></td></tr> </table> </div>						x												
x																		
<b>3.6 Holes</b> No striking feature <div style="float: right;"> <table border="1" style="background-color: green; color: white; text-align: center;"> <tr><td>x</td><td></td><td></td></tr> </table> </div>						x												
x																		
<b>3.7 Attached components (metering unit, overflow valve, counting point)</b> No striking feature <div style="float: right;"> <table border="1" style="background-color: green; color: white; text-align: center;"> <tr><td>x</td><td></td><td></td></tr> </table> </div>						x												
x																		
<b>3.8 Other</b> No striking feature <div style="float: right;"> <table border="1" style="background-color: green; color: white; text-align: center;"> <tr><td>x</td><td></td><td></td></tr> </table> </div>						x												
x																		


<b>BOSCH</b>		<b>CR pump CP4 - Diagnosis report</b>		Report no. <span style="background-color: black; color: black;">[REDACTED]</span>	
				Date 1/30/2008	
Department:	Person responsible:	Telephone:	Use <span style="float: right;">internal external</span>		
Non-responsive content removed					

### 3.9 Images of visual findings



**Fig. 1** Tappet body inside, housing side



**Fig. 2** Roller front surface, housing side

### 4. Hydraulic function

	n[rpm]	p_rail [bar]	I_MU [A]	Delivery rate [l/h] of new part	Delivery rate [l/h] after testing
Starting point	200	200	0.4	3.9	
1000 rpm, p Rated	1000	1800	0.4	17.1	
n_max_p, 500bar	3375	500	0.4	67.4	


The pump was dismantled without back measurement for the visual findings.

### 5. Destiny of the parts

The pump is stored at RB until 06/2008 and then scrapped.



### 6. Attachments





None



Tested:	Non-responsive content removed	Phone	Non-responsive content removed	Date:	3/31/2008	Signature:	Non-responsive content removed
Department:	Non-responsive content removed	Phone	Non-responsive content removed	Date:	4/10/2008	Signature:	Non-responsive content removed
Department:	Non-responsive content removed	Phone	Non-responsive content removed	Date:	4/23/2008	Signature:	Non-responsive content removed



 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.										
				Date	4/14/2008									
Department:	Person responsible:	Telephone:	Use <input type="checkbox"/> internal <input checked="" type="checkbox"/> external											
Non-responsive content removed														
To:	Non-responsive content removed													
For information:														
<b>Pump type:</b> CP4.1S_348_2x5,25_REC_3,3_1,8_MT4,2		<b>Customer:</b> VW	<b>Project:</b> R4 2.0 EU5	<b>Project / design pattern type</b> C2 / D1										
<b>Part number (TTNo.):</b> 0445B21058	<b>Date of manufacture:</b> 081206	<b>Serial number:</b> 0007	<b>Manufacturing plant - line</b> 011M FeP (Feuerbach plant)-M -											
<b>SAP-No.:</b> 30-1015814-07	<b>Samos no.:</b> 584309	<b>Customer order no.:</b>	<b>Engine/Vehicle number</b> CAG0000011											
<b>Customer part number</b>	<b>Endurance run type [customer]:</b> Vehicle endurance run	<b>Endurance run conditions:</b> Ehra variable track for passenger cars	<b>DSBFD no.:</b> 19791											
<b>Mileage</b> 89000 km	<b>Parts receipt at dept. DS-PC/EDI:</b> 12/20/2007	<b>Process no.</b> 2007-CP4_0173	<b>Confidentiality note</b> Confidential											
<b>VA / ETC no.:</b> DS-170284	<b>Durability test type [RB]:</b>													
<b>Complaint:</b>														
<b>1. Subject</b> CP4 customer return Diagnosis of endurance run end without complaint														
<b>2. Conclusion</b> <b>Function</b> - Delivery rates after endurance run without significant fuel-quantity drift in comparison with the new state. - Cold seal-tightness confirmed up to -25 °C after endurance run <b>Components</b> - Wear of the components is low and without significant striking features. <b>Result</b> - The pump has <b>passed</b> the endurance run.														
<b>3. Results of diagnosis (visual findings)</b>		Legend rating stages		OK uncritical Critical	<table border="1"> <tr><td>x</td><td></td><td></td></tr> <tr><td></td><td>x</td><td></td></tr> <tr><td></td><td></td><td>x</td></tr> </table>	x				x				x
x														
	x													
		x												
<b>3.1 Drive</b> No striking feature					<table border="1"> <tr><td>x</td><td></td><td></td></tr> </table>	x								
x														
<b>3.2 Drivetrain</b> Lateral roller slip-off (see Fig. 1) in the tappet (see Fig. 2)					<table border="1"> <tr><td></td><td>x</td><td></td></tr> </table>		x							
	x													
<b>3.3 High pressure</b> No striking feature					<table border="1"> <tr><td>x</td><td></td><td></td></tr> </table>	x								
x														
<b>3.4 Bearing</b> No striking feature					<table border="1"> <tr><td>x</td><td></td><td></td></tr> </table>	x								
x														
<b>3.5 Shaft seal</b> No striking feature					<table border="1"> <tr><td>x</td><td></td><td></td></tr> </table>	x								
x														
<b>3.6 Holes</b> No striking features					<table border="1"> <tr><td>x</td><td></td><td></td></tr> </table>	x								
x														
<b>3.7 Attached components (metering unit, overflow valve, counting point)</b>					<table border="1"> <tr><td>x</td><td></td><td></td></tr> </table>	x								
x														

 <b>BOSCH</b>				<b>CR pump CP4 - Diagnosis report</b>		Report no. <span style="background-color: black; color: black;">[REDACTED]</span>	
				Date		4/14/2008	
<b>Department:</b>	<b>Person responsible:</b>	<b>Telephone:</b>		<b>Use</b>		internal	<input type="checkbox"/>
Non-responsive content removed				external		<input checked="" type="checkbox"/>	
No striking feature							
<b>3.8 Other</b>						<input checked="" type="checkbox"/>	<input type="checkbox"/>
No striking feature							
<b>3.9 Images of visual findings</b>							
							
<b>Fig. 1 Tappet body inside, housing side</b>				<b>Fig. 2 Roller front surface, housing side</b>			
<b>4. Hydraulic function</b>							
	n[rpm]	p_rail [bar]	I_MU [A]	Delivery rate [l/h] of new part 12/7/2006	Delivery rate [l/h] after testing 12/20/2007	<input checked="" type="checkbox"/>	
Starting point	200	200	0.4	3.9	3.7	<input checked="" type="checkbox"/>	
1000 rpm, p_rated	1000	1800	0.4	16.7	17.7	<input checked="" type="checkbox"/>	
n_max_p, 500bar	3375	500	0.4	67.1	67.2	<input checked="" type="checkbox"/>	
TCD (technical customer documentation) testing point LG (1,000 rpm, p_rated ≥ 15.5 or 15.2 l/h after running time) is met.							
No significant fuel-quantity drift compared to delivery measurement.							
<b>5. Destiny of the parts</b>							
The pump is stored at RB until 06/2008 and then scrapped.							
<b>6. Attachments</b>							
None							
<b>Tested:</b>	Non-responsive content removed	<b>Phone</b>	Non-responsive content removed	<b>Date:</b>	4/28/2008	<b>Signature:</b>	Non-responsive content removed
<b>Department:</b>	[REDACTED]	<b>Phone</b>	[REDACTED]	<b>Date:</b>	4/28/2008	<b>Signature:</b>	[REDACTED]
<b>Department:</b>	[REDACTED]	<b>Phone</b>	[REDACTED]	<b>Date:</b>	5/6/2008	<b>Signature:</b>	[REDACTED]

EA11003EN-00874101

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.	
				Date	2/28/2008
Department:	Person responsible:	Telephone:	Use <input type="checkbox"/> internal <input checked="" type="checkbox"/> external		
Non-responsive content removed					
To:	Non-responsive content removed				
For information:					
<b>Pump type:</b> CP4.1S_348_2x5,25_REC_3,3_1,8_MT4,2	<b>Customer:</b> VW	<b>Project:</b> R4 2.0 EU5	<b>Project / design pattern type</b> D / Series		
<b>Part number (TTNo.):</b> 445010507	<b>Date of manufacture:</b> 290607	<b>Serial number:</b> 0007	<b>Manufacturing plant - line</b> 011M FeP (Feuerbach plant)-M -		
<b>SAP-No.:</b> 30-101005-07	<b>Samos no.:</b> 584310,001	<b>Customer order no.:</b>	<b>Engine/Vehicle number</b> 03LA/270202		
<b>Customer part number</b>	<b>Endurance run type [customer]:</b> Engine endurance run	<b>Endurance run conditions:</b> not known	<b>DSBFD no.:</b> 20042		
<b>Mileage</b> 840 h	<b>Parts receipt at dept. DS-PC/EDI:</b> 12/21/2007	<b>Process no.</b> 2007-CP4_0174	<b>Confidentiality note</b> Confidential		
<b>VA / ETC no.:</b> DS-172513	<b>Durability test type [RB]:</b>				
<b>Complaint:</b>					
<b>1. Subject</b> CP4 customer return Findings at the end of endurance run					
<b>2. Conclusion</b> Delivery rates after endurance run or test in accordance with the specifications. Wear of the components is low and without significant striking features. The feed/return connection shows slight damage due to handling errors. The pump has passed the <b>endurance run</b>					
<b>3. Results of diagnosis (visual findings)</b>		Legend rating stages		OK { uncritical Critical	
<b>3.1 Drive</b> No striking feature				<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	
<b>3.2 Drivetrain</b> No striking feature				<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	
<b>3.3 High pressure</b> No striking feature				<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	
<b>3.4 Bearing</b> No striking feature				<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	
<b>3.5 Shaft seal</b> No striking feature				<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	
<b>3.6 Holes</b> No striking features				<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	
<b>3.7 Attached components (metering unit, overflow valve, counting point)</b> No striking feature				<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	
<b>3.8 Other</b> Feed/return connection faulty (see Figs. 1 and 2)				<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>	




<b>BOSCH</b>		<b>CR pump CP4 - Diagnosis report</b>		Report no. <span style="background-color: black; color: black;">[REDACTED]</span>	
				Date 2/28/2008	


Department:	Person responsible:	Telephone:	Use	internal	
Non-responsive content removed				external	x

### 3.9 Images of visual findings



**Fig. 1 Feed connection**



**Fig. 2 Return connection**

### 4. Hydraulic function

	n[rpm]	p_rail [bar]	I_MU [A]	Delivery rate [l/h] of new part	Delivery rate [l/h] after testing
				6/28/2007	12/21/2007
Starting point	200	200	0.4	3.9	3.9
1000 rpm, p Rated	1000	1800	0.4	17.9	17.7
n_max_p, 500bar	3375	500	0.4	66.1	67.2

x

x

x

TCD (technical customer documentation) testing point LG (1,000 rpm, p Rated ≥ 15.5 or 15.2 l/h after running time) is met.

No significant fuel-quantity drift compared to delivery measurement.

### 5. Destiny of the parts

The pump is stored at RB until 06/2008 and then scrapped.



















### 6. Attachments





None



Tested:	Non-responsive content removed	Phone	Non-responsive content removed	Date:	2/29/2008	Signature:	Non-responsive content removed
Department:	[REDACTED]	Phone	[REDACTED]	Date:	3/4/2008	Signature:	[REDACTED]
Department:	[REDACTED]	Phone	[REDACTED]	Date:	3/6/2008	Signature:	[REDACTED]

EA11003EN-00875[0]



 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.		
				Date	4/4/2008	
Department:	Person responsible:	Telephone:		Use	internal	
Non-responsive content removed			external		x	
To:	Non-responsive content removed					
For information:						
<b>Pump type:</b> CP4.1S_348_2x5,25_REC_3,3_1,95_MT4,2		<b>Customer:</b> VW	<b>Project:</b> R4 2.0 EU5	<b>Project / design pattern type</b> C / C		
<b>Part number (TTNo.):</b> 445010507	<b>Date of manufacture:</b> 110407	<b>Serial number:</b> 0019	<b>Manufacturing plant - line</b> 011M FeP (Feuerbach plant)-M -			
<b>SAP-No.:</b> DS-172525	<b>Samos no.:</b> 054647	<b>Customer order no.:</b> 3LAP270157	<b>Engine/Vehicle number</b> 3LAP270157			
<b>Customer part number</b> 3LAP270157	<b>Endurance run type [customer]:</b>	<b>Endurance run conditions:</b> GDV-Ehra variable track for passenger cars	<b>DSBFD no.:</b> 20044			
<b>Mileage</b> 95210 km	<b>Parts receipt at dept. DS-PC/EDI:</b> 12/21/2007	<b>Process no.</b> 2007-CP4_0176	<b>Confidentiality note</b> Confidential			
<b>1. Subject</b> CP4 customer return Diagnosis after end of endurance run Testing conditions: 95.210km GDV Ehra variable track for passenger cars						
<b>2. Conclusion</b> Cold cell result: leak-tight down to -30 °C. Function: OK The wear of power transmission elements is part of the values that are usual for this service life category.						
<b>3. Results of diagnosis (visual findings)</b>			Legend rating stages		OK uncritical Critical	
<b>3.1 Drive</b> No striking feature						
<b>3.2 Drivetrain</b> Moderate wear of the C coating on the roller crest (Fig. 1). Slight recession of the roller in the tappet body (Fig. 2).						
<b>3.3 High pressure</b> Very low fretting wear of the intake valve, otherwise smooth marks recognizable.						
<b>3.4 Bearing</b> No striking feature						
<b>3.5 Shaft seal</b> No striking feature						
<b>3.6 Holes</b> No striking feature						
<b>3.7 Attached components (metering unit, overflow valve, counting point)</b> No striking feature						
<b>3.8 Other</b>						


 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.	[REDACTED]	
				Date	4/4/2008	
Department:	Person responsible:	Telephone:	Use	internal		
Non-responsive content removed				external	x	
<b>4. Hydraulic function</b>						
	n[rpm]	p_rail [bar]	I_MU [A]	Delivery rate [l/h] of new part	Delivery rate [l/h] after testing	
				4/11/2007	12/21/2007	
Starting point	200	200	0.4	3.9	3.9	<input checked="" type="checkbox"/>
1000 rpm, p_rated	1000	1800	0.4	17.6	17.7	<input checked="" type="checkbox"/>
n_max_p, 500bar	3375	500	0.4	65.4	66.6	<input checked="" type="checkbox"/>
No striking feature.						
<b>5. Destiny of the parts</b>						
The parts will be stored at RB until 10/2008.						
						
Fig. 1: roller crest			Fig. 2: Tappet body			
Tested:	Non-responsive content removed	Phone	Non-responsive content removed	Date:	4/8/2008	Signature:
Department:		Phone		Date:	4/10/2008	Signature:
Department:		Phone		Date:	4/11/2008	Signature:



 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.											
				Date	4/17/2008										
Department:	Person responsible:	Telephone:		Use	internal										
Non-responsive content removed			external			x									
To:	Non-responsive content removed														
For information:															
<b>Pump type:</b> CP4.1S_348_2x5,25_REC_3,3_1,95_MT4,2		<b>Customer:</b> VW	<b>Project:</b> R4 2.0 EU5	<b>Project / design pattern type</b> D / Series											
<b>Part number (TTNo.):</b> 445010507		<b>Date of manufacture:</b> 050607	<b>Serial number:</b> 0404	<b>Manufacturing plant - line</b> 011M FeP (Feuerbach plant)-M -											
<b>SAP-No.:</b> 30-101005-07		<b>Samos no.:</b> 584308	<b>Customer order no.:</b>	<b>Engine/Vehicle number</b> CAH0000111											
<b>Customer part number</b>	<b>Endurance run type [customer]:</b> Engine trial	<b>Endurance run conditions:</b> Reso-run		<b>DSBFD no.:</b> 20041											
<b>Mileage</b> 111 h	<b>Parts receipt at dept. DS-PC/EDI:</b> 12/20/2007	<b>Process no.</b> 2007-CP4_0187		<b>Confidentiality note</b> Confidential											
<b>VA / ETC no.:</b> DS-172511	<b>Endurance run type (RB):</b>	<b>Fuel:</b> EN590													
<b>Complaint:</b>															
<b>1. Subject</b> CP4 customer return Diagnosis of endurance run end without complaint															
<b>2. Conclusion</b> <b>Function</b> - Delivery rates after endurance run without significant fuel-quantity drift in comparison with the new state. - Cold seal-tightness confirmed up to -25 °C after endurance run <b>Components</b> - Smoothing area with grooves in the tappet hole and on the tappet body uncritical. - Wear of the remaining components is low and without significant striking features. <b>Result</b> - The pump has passed the endurance run.															
<b>3. Results of diagnosis (visual findings)</b>				Legend rating stages { OK uncritical Critical											
<b>3.1 Drive</b> No striking feature				<table border="1"> <tr><td>x</td><td></td><td></td></tr> <tr><td></td><td>x</td><td></td></tr> <tr><td></td><td></td><td>x</td></tr> </table>			x				x				x
x															
	x														
		x													
<b>3.2 Drivetrain</b> Smoothing area with grooves on the tappet body (see Fig. 1)				<table border="1"> <tr><td>x</td><td></td><td></td></tr> <tr><td></td><td>x</td><td></td></tr> <tr><td></td><td></td><td></td></tr> </table>			x				x				
x															
	x														
<b>3.3 High pressure</b> No striking feature				<table border="1"> <tr><td>x</td><td></td><td></td></tr> <tr><td></td><td></td><td></td></tr> <tr><td></td><td></td><td></td></tr> </table>			x								
x															
<b>3.4 Bearing</b> No striking feature				<table border="1"> <tr><td>x</td><td></td><td></td></tr> <tr><td></td><td></td><td></td></tr> <tr><td></td><td></td><td></td></tr> </table>			x								
x															
<b>3.5 Shaft seal</b> No striking feature				<table border="1"> <tr><td>x</td><td></td><td></td></tr> <tr><td></td><td></td><td></td></tr> <tr><td></td><td></td><td></td></tr> </table>			x								
x															
<b>3.6 Holes</b> Smoothing area with grooves in the tappet hole (see Fig. 2)				<table border="1"> <tr><td></td><td>x</td><td></td></tr> <tr><td></td><td></td><td></td></tr> <tr><td></td><td></td><td></td></tr> </table>				x							
	x														
<b>3.7 Attached components (metering unit, overflow valve, counting point)</b> No striking feature				<table border="1"> <tr><td>x</td><td></td><td></td></tr> <tr><td></td><td></td><td></td></tr> <tr><td></td><td></td><td></td></tr> </table>			x								
x															
				<table border="1"> <tr><td>x</td><td></td><td></td></tr> <tr><td></td><td></td><td></td></tr> <tr><td></td><td></td><td></td></tr> </table>			x								
x															

EA11003EN-00876[1]

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.					
				Date	4/17/2008				
Department:	Person responsible:	Telephone:	Use <table border="1"> <tr> <td>internal</td> <td></td> </tr> <tr> <td>external</td> <td><b>x</b></td> </tr> </table>			internal		external	<b>x</b>
internal									
external	<b>x</b>								
Non-responsive content removed									
<b>3.8 Other</b> No striking feature									

**3.9 Images of visual findings****Fig. 1 Tappet body, lateral surface****Fig. 2 Housing, tappet hole****4. Hydraulic function**

	n[rpm]	p_rail [bar]	I_MU [A]	Delivery rate [l/h] of new part	Delivery rate [l/h] after testing
				6/5/2007	12/20/2007
Starting point	200	200	0.4	3.9	3.8
1000 rpm, p_rated	1000	1800	0.4	17.8	17.7
n_max_p, 500bar	3375	500	0.4	66.1	66.2

<b>x</b>		
<b>x</b>		
<b>x</b>		

TCD (technical customer documentation) testing point LG (1,000 rpm, p\_rated  $\geq 15.5$  or 15.2 l/h after running time) is met.

No significant fuel-quantity drift compared to delivery measurement.

**5. Destiny of the parts**



The pump is stored at RB until 06/2008 and then scrapped.

**6. Attachments**

None







<b>Tested:</b>	Non-responsive content removed	<b>Phone</b>	Non-responsive content removed	<b>Date:</b>	4/28/2008	<b>Signature:</b>	Non-responsive content removed
<b>Department:</b>		<b>Phone</b>		<b>Date:</b>	4/28/2008	<b>Signature:</b>	
<b>Department:</b>		<b>Phone</b>		<b>Date:</b>	5/6/2008	<b>Signature:</b>	




EA11003EN-00877101

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.	[REDACTED]										
				Date	3/28/2008										
Department:	Person responsible:	Telephone:	Use												
Non-responsive content removed			internal												
			external		x										
To:	Non-responsive content removed														
For information:	[REDACTED]														
<b>Pump type:</b> CP4.1S_348_2x5,25_REC_3,3_1,95_MT4,2		<b>Customer:</b> VW	<b>Project:</b> R4 2.0 EU5	<b>Project / design pattern type</b> C / C2											
<b>Part number (TTNo.):</b> 0445B21058_05	<b>Date of manufacture:</b> 689	<b>Serial number:</b> 4926	<b>Manufacturing plant - line</b> 011M FeP (Feuerbach plant)-M -												
<b>SAP-No.:</b> 30-101005-07	<b>Samos no.:</b> 577901	<b>Customer order no.:</b>	<b>Engine/Vehicle number</b> 03LA/17115 / AU 481-8-110												
<b>Customer part number</b>	<b>Endurance run type [customer]:</b> Vehicle endurance run	<b>Endurance run conditions:</b> Ehra variable track for passenger cars	<b>DSBFD no.:</b> 19435												
<b>Mileage</b> 100000 km	<b>Parts receipt at dept. DS-PC/EDI:</b> 1/11/2008	<b>Process no.</b> 2007-CP4_0248	<b>Confidentiality note</b> Confidential												
<b>VA / ETC no.:</b> DS-164732															
<b>Complaint:</b>															
<b>1. Subject</b> CP4 customer return Diagnosis of endurance run end without complaint															
<b>2. Conclusion</b> <b>Function</b> - Delivery rates after endurance run or test without significant fuel-quantity drift in comparison with the new state (deviation during the first back measurement after reassembly could not be confirmed). - Cold seal-tightness after endurance run or test confirmed up to -30 °C (Leakage during the first measurement on the shaft seal due to contamination in the form of a hair and particles verified through cleaning and retest, camshaft wear measurement normal). <b>Components</b> - Wear of the remaining components is low and without significant striking features. - Damage to the camshaft with respect to its functioning uncritical and probably due to inadequate packaging during return. <b>Result</b> - The pump has passed the endurance run.															
<b>3. Results of diagnosis (visual findings)</b>			Legend rating stages { <div>           OK            uncritical            Critical         </div>		<table border="1"> <tr><td>x</td><td></td><td></td></tr> <tr><td></td><td>x</td><td></td></tr> <tr><td></td><td></td><td>x</td></tr> </table>		x				x				x
x															
	x														
		x													
<b>3.1 Drive</b> Camshaft damaged on the first thread pitch (fault and breakage of the flank, see Figs. 1 and 2)					<table border="1"> <tr><td></td><td>x</td><td></td></tr> </table>			x							
	x														
<b>3.2 Drivetrain</b> No striking feature					<table border="1"> <tr><td>x</td><td></td><td></td></tr> </table>		x								
x															



EA11003EN-00877111

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.							
				Date	3/28/2008						
Department:	Person responsible:	Telephone:	Use <table border="1"> <tr> <td>internal</td> <td></td> <td></td> </tr> <tr> <td>external</td> <td>x</td> <td></td> </tr> </table>			internal			external	x	
internal											
external	x										
Non-responsive content removed											
To:	Non-responsive content removed										
For information:											
<b>3.3 High pressure</b> No striking feature				<input checked="" type="checkbox"/>	<input type="checkbox"/>						
<b>3.4 Bearing</b> No striking feature				<input checked="" type="checkbox"/>	<input type="checkbox"/>						
<b>3.5 Shaft seal</b> Contamination (for hair and particles, see Fig. 3) resulted in a leak in the cold test at -25 °C; pump is seal-tight in bubble test at room temperature (after back measurement and reassembly); wear measurement of shaft seal running range on the camshaft normal (see Figs. 4 and 5)				<input type="checkbox"/>	<input checked="" type="checkbox"/>						
<b>3.6 Holes</b> No striking feature				<input checked="" type="checkbox"/>	<input type="checkbox"/>						
<b>3.7 Attached components (metering unit, overflow valve, counting point)</b> No striking feature				<input checked="" type="checkbox"/>	<input type="checkbox"/>						
<b>3.8 Other</b> No striking feature				<input checked="" type="checkbox"/>	<input type="checkbox"/>						
<b>3.9 Images of visual findings</b>											
											
<b>Fig. 1 Camshaft, thread</b>			<b>Fig. 2 Camshaft, front surface</b>								
											
<b>Fig. 1 Flange, shaft seal sealing lip</b>			<b>Fig. 4: Camshaft, shaft seal running range</b>								

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.					
				Date	3/28/2008				
Department:	Person responsible:	Telephone:	Use <table border="1"> <tr> <td>internal</td> <td></td> </tr> <tr> <td>external</td> <td>x</td> </tr> </table>			internal		external	x
internal									
external	x								
Non-responsive content removed									
To:	Non-responsive content removed								
For information:	Non-responsive content removed								



about 150 µm wide  
about 2.5 µm deep  
Cutting length

Fig. 5: WLI (white-light interferometry) measurement result, camshaft

#### 4. Hydraulic function

	n[rpm]	p_rail [bar]	I_MU [A]	Delivery rate [l/h] of new part 9/15/2006	Delivery rate [l/h] after testing 10/22/2007
Starting point	200	200	0.4	3.9	3.8
1000 rpm, p_rated	1000	1800	0.4	17	16.8
n_max_p, 500bar	3375	500	0.4	65.4	58.8

x		
x		
	x	

TCD testing point LG (1,000 rpm, p\_rated) within tolerance (nominal  $\geq 15.5$  or 15.2 l/h after running time).

Testing point 3,375 rpm / 500 bar / 0.4 A abnormal, that is, outside the known scattering range.

	n[rpm]	p_rail [bar]	I_MU [A]	Delivery rate [l/h] after reassembly 2/22/2008	
Starting point	200	200	0.4	3.9	
1000 rpm, p_rated	1000	1800	0.4	17	
n_max_p, 500bar	3375	500	0.4	66.6	

x		
x		
x		

Delivery rate deviation in the testing point 3,375 rpm / 500 bar / 0.4 A no longer available after reassembly.











#### 5. Destiny of the parts

The pump is stored at RB until 06/2008 and then scrapped.

#### 6. Attachments












None

EA11003EN-00877[3]









 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.			
				Date		3/28/2008	
Department:	Person responsible:	Telephone:		Use		internal	
Non-responsive content removed						external	x
To:	Non-responsive content removed						
For information:							
Tested:	Non-responsive content removed	Phone	Non-responsive content removed	Date:	4/2/2008	Signature:	Non-responsive content removed
Department:		Phone		Date:	4/10/2008	Signature:	
Department:		Phone		Date:	4/11/2008	Signature:	





EA11003EN-00878[0]

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.	
				Date	1/15/2008
Department:	Person responsible:	Telephone:	Use	internal	
Non-responsive content removed				external	x
To:	Non-responsive content removed				
For information:					
<b>Pump type:</b> CP4.1S_348_2x5,25_REC_3,3_1,8_M T4,2	<b>Customer:</b> VW	<b>Project:</b> R4 2.0 EU5	<b>Project / design pattern type</b> C2 / D1		
<b>Part number (TTNo.):</b> 0445B21058	<b>Date of manufacture:</b> 081206	<b>Serial number:</b> 0073	<b>Manufacturing plant - line</b> 011M FeP (Feuerbach plant)-M -		
<b>SAP-No.:</b> DS-164773	<b>Samos no.:</b> 0578260	<b>Customer order no.:</b>	<b>Engine/Vehicle number</b> 3LAP270056		
<b>Customer part number</b>	<b>Endurance run type [customer]:</b> Engine endurance run	<b>Endurance run conditions:</b> GDV-Ehra variable track for passenger cars	<b>DSBFD no.:</b> 19417		
<b>Mileage</b> 98221 km	<b>Parts receipt at dept. DS-PC/EDI:</b> 1/11/2008	<b>Process no.</b> 2007-CP4_0249	<b>Confidentiality note</b> Confidential		
<b>Complaint:</b>					
<b>1. Subject</b> CP4 customer return Endurance run end after gear endurance test					
<b>2. Conclusion</b> No critical wear detected. The pump has passed the test.					
<b>3. Results of diagnosis (visual findings)</b>					
		Legend rating stages	OK uncritical Critical		
<b>3.1 Drive</b>		No striking feature			
<b>3.2 Drivetrain</b>		Slight recession of the spring plate (Fig. 1)			
<b>3.3 High pressure</b>		fretting wear at the sealing surface of the intake valve / stationary seal ring (Fig. 2)			
<b>3.4 Bearing</b>		No striking feature			
<b>3.5 Shaft seal</b>		No striking feature			
<b>3.6 Holes</b>		Slight cavitation erosion in the upper region of the tappet hole (Fig. 3)			
<b>3.7 Attached components (metering unit, overflow valve, counting point)</b>		No striking feature			
<b>3.8 Other</b>					

EA11003EN-00878[1]



 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no. 	
				Date	1/15/2008
<b>Department:</b> Non-responsive content removed		<b>Person responsible:</b> 		<b>Telephone:</b> 	
				Use	internal <input type="checkbox"/> external <input checked="" type="checkbox"/>
<b>4. Destiny of the parts</b>					
The parts will be stored at RB until 07/2008					
					
Fig. 1: Spring plate			Fig. 2: Intake valve		
					
Fig. 3: Tappet hole					
Tested:	Non-responsive content removed	Phone	Non-responsive content removed	Date:	1/17/2008
Department:	Non-responsive content removed	Phone	Non-responsive content removed	Date:	1/17/2008
Department:	Non-responsive content removed	Phone	Non-responsive content removed	Date:	1/28/2008
				Signature:	Non-responsive content removed
				Signature:	Non-responsive content removed
				Signature:	Non-responsive content removed

EA11003EN-00879[0]

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.										
				Date	2/5/2008									
<b>Department:</b>	<b>Person responsible:</b>	<b>Telephone:</b>	Use	internal										
Non-responsive content removed				external	x									
To:	Non-responsive content removed													
For information:														
<b>Pump type:</b> CP4.1S_348_2x5,25_REC_3,3_1,8_M T4,2	<b>Customer:</b> VW	<b>Project:</b> R4 2.0 EU5	<b>Project / design pattern type</b> C2 / D1											
<b>Part number (TTNo.):</b> 0445B21058	<b>Date of manufacture:</b> 081206	<b>Serial number:</b> 0066	<b>Manufacturing plant - line</b> 011M FeP (Feuerbach plant)-M - 01											
<b>SAP-No.:</b> 30-101581-07	<b>Samos no.:</b> 584304	<b>Customer order no.:</b>	<b>Engine/Vehicle number</b> 3LAP270027											
<b>Customer part number</b>	<b>Endurance run type [customer]:</b> Engine endurance run	<b>Endurance run conditions:</b> Polycyclic endurance run (PCR)	<b>DSBFD no.:</b> 19788											
<b>Mileage</b> 914 h	<b>Parts receipt at dept. DS-PC/EDI:</b> 1/11/2008	<b>Process no.</b> 2007-CP4_0253	<b>Confidentiality note</b> Confidential											
<b>VA / ETC no.:</b>	<b>Durability test type [RB]:</b>													
<b>Complaint:</b>														
<b>1. Subject</b> CP4 customer return Findings at the end of endurance run														
<b>2. Conclusion</b> The delivery rates after endurance run correspond to the specifications. Wear of the components is good and does not show any striking features. The pump has <b>passed</b> the test.														
<b>3. Results of diagnosis (visual findings)</b>														
<b>3.1 Drive</b>		Legend rating stages		{ OK uncritical Critical										
No striking feature				<table border="1"> <tr><td>x</td><td></td><td></td></tr> <tr><td></td><td>x</td><td></td></tr> <tr><td></td><td></td><td>x</td></tr> </table>		x				x				x
x														
	x													
		x												
<b>3.2 Drivetrain</b>				<table border="1"> <tr><td>x</td><td></td><td></td></tr> <tr><td>x</td><td></td><td></td></tr> </table>		x			x					
x														
x														
<b>3.3 High pressure</b>				<table border="1"> <tr><td>x</td><td></td><td></td></tr> </table>		x								
x														
No striking feature														
<b>3.4 Bearing</b>				<table border="1"> <tr><td>x</td><td></td><td></td></tr> </table>		x								
x														
No striking feature														
<b>3.5 Shaft seal</b>				<table border="1"> <tr><td>x</td><td></td><td></td></tr> </table>		x								
x														
No striking feature														
<b>3.6 Holes</b>				<table border="1"> <tr><td>x</td><td></td><td></td></tr> </table>		x								
x														
No striking feature														
<b>3.7 Attached components (metering unit, overflow valve, counting point)</b>				<table border="1"> <tr><td>x</td><td></td><td></td></tr> </table>		x								
x														
No striking feature														
<b>3.8 Other</b>				<table border="1"> <tr><td>x</td><td></td><td></td></tr> </table>		x								
x														
No striking feature														



EA11003EN-00879[1]

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no. <span style="background-color: black; color: black;">[REDACTED]</span>	
				Date	2/5/2008
<b>Department:</b>	<b>Person responsible:</b>	<b>Telephone:</b>		Use	<input type="checkbox"/> internal <input checked="" type="checkbox"/> external
Non-responsive content removed		<span style="background-color: black; color: black;">[REDACTED]</span>			

**4. Hydraulic function**

	n[rpm]	p_rail [bar]	I_MU [A]	Delivery rate [l/h] of new part	Delivery rate [l/h] after testing
				2/1/2007	12/11/2007
Starting point	200	200	0.4	3.9	3.8
1000 rpm, p_rated	1000	1800	0.4	17.6	17.6
n_max p, 500bar	3375	500	0.4	66.2	66.9

x		
x		
x		


TCD (technical customer documentation) testing point LG (1,000 rpm, p\_rated ≥ 15.5 or 15.2 l/h after running time) is met.  
 No significant fuel-quantity drift compared to delivery measurement.

**5. Destiny of the parts**  
 The pump is stored at RB until 06/2008 and then scrapped.



  

**6. Attachments**  
 None

Tested:	<span style="background-color: black; color: black;">[REDACTED]</span>	Phone	<span style="background-color: black; color: black;">[REDACTED]</span>	Date:	2/7/2008	Signature:	<span style="background-color: black; color: black;">[REDACTED]</span>
Department:	<span style="background-color: black; color: black;">[REDACTED]</span>	Phone	<span style="background-color: black; color: black;">[REDACTED]</span>	Date:	2/7/2008	Signature:	<span style="background-color: black; color: black;">[REDACTED]</span>
Department:	<span style="background-color: black; color: black;">[REDACTED]</span>	Phone	<span style="background-color: black; color: black;">[REDACTED]</span>	Date:	2/12/2008	Signature:	<span style="background-color: black; color: black;">[REDACTED]</span>

EA11003EN-00880[0]

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.	
				Date	5/28/2008
Department:	Person responsible:	Telephone:	Use	internal	
Non-responsive content removed				external	x
To:	Non-responsive content removed				
For information:	Non-responsive content removed				
<b>Pump type:</b> CP4.2S 644 2x4.85 REC 3.3 1,2		<b>Customer:</b> Audi	<b>Project:</b> W19 EU5	<b>Project / design pattern type</b> C2	
<b>Part number (TTNo.):</b> 0445B20162_05		<b>Date of manufacture:</b> 250706	<b>Serial number:</b> 0008	<b>Manufacturing plant - line</b> 0110 FeP (Feuerbach plant) – 01	
<b>SAP-No.:</b> DS-169128		<b>Samos no.:</b> 582246	<b>Customer order no.:</b>	<b>Engine/Vehicle number</b> 059 D V6N 025	
<b>Customer part number</b>		<b>Endurance run type [customer]:</b> CR-engine	<b>Endurance run conditions:</b> Engine map operation	<b>DSBFD no.:</b> 19695	
<b>Mileage</b> 202 h		<b>Parts receipt at dept. DS-PC/EDI:</b> 11/15/2007	<b>Process no.</b> 2007-CP4_0203	<b>Confidentiality note</b> Confidential	
<b>VA / ETC no.:</b> DS-169128		<b>Durability test type [RB]:</b>	<b>Fuel:</b> EN590		

### 1. Subject

CP4 customer returns **without complaint**  
 Diagnosis after endurance run end  
 202 h engine map operation  
 Engine 059 D V6N 025

### 2. Conclusion

**Function**

- Delivery rates after endurance run or test without significant fuel-quantity drift in comparison with the new state.

**Components**

- Wear of the components is low and without significant striking features.

**Result**

- The pump has passed the **endurance run**

### 3. Results of diagnosis (visual findings)

**3.1 Drive**

No striking feature

**3.2 Drivetrain**

The tappet body has turned around the roller support in the two tappet combinations. Thus, there are 2 or 3 slip-off points of the roller in the tappet body (see 3.10, Figures 1 and 2).

Wear due to lateral roller slip-off is normal.

**3.3 High pressure**

No striking feature

**3.4 Bearing**

No striking feature

**3.5 Shaft seal**

No striking feature

**3.6 Holes**





No striking features

**3.7 Attached components (metering unit, overflow valve, counting point)**

Legend rating stages



OK	x		
uncritical		x	
Critical			x

EA11003EN-00880[1]

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no. [REDACTED]	
				Date 5/28/2008	
Department:	Person responsible:	Telephone:		Use	internal
Non-responsive content removed					external <input checked="" type="checkbox"/>
No striking feature					
<b>3.8 O-rings</b>				<input checked="" type="checkbox"/>	
No striking feature					
<b>3.9 Other</b>				<input checked="" type="checkbox"/>	
No striking feature					
<b>3.10 Images</b>					
					
<b>Fig. 1:</b> Tappet body to the left: Two slip-off points of the roller			<b>Fig. 2:</b> Tappet body to the right: Three slip-off points of the roller		
<b>4. Hydraulic function</b>					
				Delivery rate [l/h] of new part	Delivery rate [l/h] after testing
	n[rpm]	p_rail [bar]	I_MU [A]	7/28/2006	11/29/2007
LG	1000	1800	0.4	30.7	31.3
				<input checked="" type="checkbox"/>	
No significant volumetric efficiency change, the volumetric efficiency is within the tolerance specified in the TCD for new parts.					
<b>5. Destiny of the parts</b>					
The pump will be scrapped at the request of Audi.					
<b>6. Attachments</b>					
None					
Tested:	Non-responsive content removed	Phone:	Non-responsive content removed	Date:	6/27/2008
Signature:		Signature:		Signature:	Non-responsive content removed
Department:		Phone:		Date:	6/30/2008
Signature:		Signature:		Signature:	
Department:		Phone:		Date:	7/9/2008
Signature:		Signature:		Signature:	



EA11003EN-00881[0]

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.	[REDACTED]	
				Date	6/24/2008	
Department:	Person responsible:	Telephone:	Use	internal		
Non-responsive content removed				external		x
To:	Non-responsive content removed					
For information:	[REDACTED]					
<b>Pump type:</b> CP4.2S 644 2x4.85_REC_3,3_1,2		<b>Customer:</b> Audi	<b>Project:</b> W19 EU5	<b>Project / design pattern type</b> D		
<b>Part number (TTNo.):</b> 0445010611		<b>Date of manufacture:</b> 200906	<b>Serial number:</b> 0016	<b>Manufacturing plant - line</b> 0110 FeP (Feuerbach plant) – 01		
<b>SAP-No.:</b> 30-100481-06		<b>Samos no.:</b> 582527	<b>Customer order no.:</b> CP4.2_064	<b>Engine/Vehicle number</b> 059.D EU5 114		
<b>Customer part number</b> CP4.2_064		<b>Endurance run type [customer]:</b>	<b>Endurance run conditions:</b> BOSCH BAT in KST	<b>DSBFD no.:</b> 19803		
<b>Mileage</b> 1670 h		<b>Parts receipt at dept. DS-PC/EDI:</b> 11/23/2007	<b>Process no.</b> 2007-CP4_0216	<b>Confidentiality note</b> Confidential		
<b>VA / ETC no.:</b> DS-170340		<b>Durability test type [RB]:</b>	<b>Fuel:</b> EN590			

### 1. Subject

CP4 customer returns **without complaint**  
 Diagnosis after endurance run end  
 1,670 h Federal Highway Test (BOSCH at KST)  
 Engine 059.D EU5 114

### 2. Conclusion

**Function**

- Delivery rates after endurance run or test without significant fuel-quantity drift in comparison with the new state.
- The cold seal-tightness after endurance run or test has been proven up to -25 °C (KACO shaft seal).

**Components**

- The wear due to cavitation erosion is increased on the roller support (HP piston contact), but uncritical.
- The wear due to cavitation erosion is increased on the high-pressure piston (piston base), but uncritical.
- The wear due to cavitation erosion is increased in the housing (right tappet hole), but uncritical.
- Wear of the remaining components is low and without significant striking features.

**Result**



- The pump has **passed the endurance run**.


### 3. Results of diagnosis (visual findings)

	OK	uncritical	Critical
<b>3.1 Drive</b> No striking feature	x		
<b>3.2 Drivetrain</b> Roller support: Cavitation erosion around the center of the HP piston contact area (see 3.10 Figures 1 and 2)		x	
<b>3.3 High pressure</b> HP piston, piston base: Cavitation erosion at the contact area (see 3.10 Figures 3 and 4)		x	
<b>3.4 Bearing</b> No striking feature	x		
<b>3.5 Shaft seal</b> No striking feature	x		
<b>3.6 Holes</b> Housing, tappet hole to the right: Cavitation erosion (see 3.10, Figure 5)		x	
<b>3.7 Attached components (Metering Unit, Overflow Valve, Counting Point)</b> No striking feature	x		
<b>3.8 O-rings</b> No striking feature	x		
<b>3.9 Other</b> No striking feature	x		


EA11003EN-00881[1]

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.		[Redacted]	
				Date		6/24/2008	
Department:	Person responsible:	Telephone:		Use	internal		
Non-responsive content removed					external		x


**3.10 Images**




**Fig. 1:** Roller support to the left: Cavitation erosion




**Fig. 2:** Roller support to the right: Cavitation erosion



**Fig. 3:** High-pressure piston to the left: Cavitation erosion at the piston base



**Fig. 4:** High-pressure piston to the right: Cavitation erosion at the piston base



**Fig. 5:** Tappet hole to the right: Cavitation erosion

**4. Hydraulic function**

	n[rpm]	p_rail [bar]	I_MU [A]	Delivery rate [l/h] of new part	Delivery rate [l/h] after testing
LG	1000	1800	0.4	30.9	31.6



No significant volumetric efficiency change, the volumetric efficiency is within the tolerance specified in the TCD for new parts.

**5. Destiny of the parts**  
The pump will be scrapped at the request of Audi.

**6. Attachments**  
None


Tested:	Non-responsive content removed	Phone	Non-responsive content removed	Date:	6/27/2008	Signature:	Non-responsive content removed
Department:		Phone		Date:	6/30/2008	Signature:	
Department:		Phone		Date:	7/9/2008	Signature:	



 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.	
				Date	5/13/2008
<b>Department:</b>	<b>Person responsible:</b>	<b>Telephone:</b>	Use	internal	
Non-responsive content removed				external	x
To:	Non-responsive content removed				
For information:					
<b>Pump type:</b> CP4.1S_348_2x5,25_REC_3,3_1,95_MT4,2	<b>Customer:</b> VW	<b>Project:</b> R4 2.0 EU5	<b>Project / design pattern type</b> D / Series		
<b>Part number (TTNo.):</b> 445010507	<b>Date of manufacture:</b> 290607	<b>Serial number:</b> 0008	<b>Manufacturing plant - line</b> 0110 FeP (Feuerbach plant)		
<b>SAP-No.:</b> 30-101005-07	<b>Samos no.:</b> 587811	<b>Customer order no.:</b>	<b>Engine/Vehicle number</b> 03LA270201		
<b>Customer part number</b>	<b>Endurance run type [customer]:</b> Engine endurance run	<b>Endurance run conditions:</b> not known	<b>DSBFD no.:</b> 20178		
<b>Mileage</b> 449 h	<b>Parts receipt at dept. DS-PC/EDI:</b> 1/31/2008	<b>Process no.</b> 2008-CP4_0054	<b>Confidentiality note</b> Confidential		
<b>VA / ETC no.:</b> Ds-174522	<b>Durability test type [RB]:</b>	<b>Fuel:</b>			
<b>Complaint:</b>					
<b>1. Subject</b> CP4 customer return Diagnosis of endurance run end without complaint					
<b>2. Conclusion</b> <b>Function</b> - Delivery rates after endurance run without significant fuel-quantity drift in comparison with the new state. <b>Components</b> - The lateral roller slip-off in the tappet is slightly increased, but still uncritical. - Wear of the remaining components is low and without significant striking features. - On the flange front surface, two marks with a diameter of 6 mm can be seen, probably from a puller. <b>Result</b> - The pump has <b>passed</b> the endurance run.					
<b>3. Results of diagnosis (visual findings)</b>					
<b>3.1 Drive</b>		Legend rating stages { <div>           OK uncritical           <div> <div>x</div> <div></div> <div></div> </div> <div> <div></div> <div>x</div> <div></div> </div> <div> <div></div> <div></div> <div>x</div> </div> </div>		<div> <div>x</div> <div></div> <div></div> </div> <div> <div></div> <div>x</div> <div></div> </div>	
No striking feature					
<b>3.2 Drivetrain</b>					
Lateral roller slip-off (see Fig. 1) in the tappet (see Fig. 2)					
<b>3.3 High pressure</b>					
No striking feature					
<b>3.4 Bearing</b>					
No striking feature					
<b>3.5 Shaft seal</b>					
No striking feature					
<b>3.6 Holes</b>					
No striking feature					
<b>3.7 Attached components (metering unit, overflow valve, counting point)</b>					
No striking feature					
<b>3.8 Other</b>					
Marks on flange front surface with 6 mm diameter (see Fig. 3)					



EA11003EN-00882[1]

		<b>CR pump CP4 - Diagnosis report</b>		Report no. <span style="background-color: black; color: black;">[REDACTED]</span>	
				Date 5/13/2008	
Department: Non-responsive content removed	Person responsible: <span style="background-color: black; color: black;">[REDACTED]</span>	Telephone: <span style="background-color: black; color: black;">[REDACTED]</span>	Use	internal external <input checked="" type="checkbox"/>	

## 3.9 Images of visual findings




Fig. 1 Roller front surface, housing side




Fig. 2 Tappet body inside, housing side




Fig. 3 Flange front surface (damage)

## 4. Hydraulic function

				Delivery rate [l/h] of new part	Delivery rate [l/h] after testing
	n[rpm]	p_rail [bar]	I_MU [A]	6/28/2007	2/11/2008
Starting point	200	200	0.4	3.9	3.8
1000 rpm, p_rated	1000	1800	0.4	17.9	17.9
n_max_p, 500bar	3375	500	0.4	66.2	67.5

x		
x		
x		

TCD (technical customer documentation) testing point LG (1,000 rpm, p\_rated ≥ 15.5 or 15.2 l/h after running time) is met.

No significant fuel-quantity drift compared to delivery measurement.

## 5. Destiny of the parts



The pump is stored at RB until 09/2008 and then scrapped.

## 6. Attachments



None

Tested:	Non-responsive content removed	Phone	Non-responsive content removed	Date:	5/14/2008	Signature:	Non-responsive content removed
Department:	Non-responsive content removed	Phone	Non-responsive content removed	Date:	5/20/2008	Signature:	Non-responsive content removed
Department:	Non-responsive content removed	Phone	Non-responsive content removed	Date:	5/26/2008	Signature:	Non-responsive content removed

EA11003EN-00883[0]

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.														
				Date	6/9/2008													
<b>Department:</b>	<b>Person responsible:</b>	<b>Telephone:</b>		Use	internal													
Non-responsive content removed					external	x												
To:	Non-responsive content removed																	
For information:																		
<b>Pump type:</b>	<b>Customer:</b>	<b>Project:</b>	<b>Project / design pattern type</b>															
CP4.1S_348_2x5,25_REC_3,3_1,95_MT4,2	VW	R4 2.0 EU5	D / Series															
<b>Part number (TTNo.):</b>	<b>Date of manufacture:</b>	<b>Serial number:</b>	<b>Manufacturing plant - line</b>															
445010507	190707	0498	0110 FeP (Feuerbach plant)															
<b>SAP-No.:</b>	<b>Samos no.:</b>	<b>Customer order no.:</b>	<b>Engine/Vehicle number</b>															
30-101005-07	587836		CAG0000171															
<b>Customer part number</b>	<b>Endurance run type [customer]:</b>	<b>Endurance run conditions:</b>	<b>DSBFD no.:</b>															
	Vehicle endurance run	Ehra variable track for passenger cars	20170															
<b>Mileage</b>	<b>Parts receipt at dept. DS-PC/EDI:</b>	<b>Process no.</b>	<b>Confidentiality note</b>															
70994 km	2/1/2008	2008-CP4_0062	Confidential															
<b>VA / ETC no.:</b>	<b>Durability test type [RB]:</b>	<b>Fuel:</b>																
DS-174532																		
<b>Complaint:</b>																		
<b>1. Subject</b> CP4 customer return Diagnosis of endurance run end without complaint																		
<b>2. Conclusion</b> <b>Function</b> - Delivery rates after endurance run without significant fuel-quantity drift in comparison with the new state. - Cold leakage (formation of drops) on the cylinder head screw plug above -30 °C (not tested at -25 °C). Cold seal-tightness proven up to -40 °C at shaft seal, metering unit and housing.  <b>Components</b> - O-ring of the screw plug shows an interior notch in the sealing area towards the screw. The width of the notch of about 190 µm is outside the tolerance of 150 µm. - Wear of the components is low and without significant striking features.  <b>Result</b> - The cold leakage at the screw plug in the cylinder head is due to an unacceptably wide notch of the O-ring. Further analyses and measures carried out through quality assurance of purchased parts. - The pump has <b>conditionally passed</b> the endurance run.																		
<b>3. Results of diagnosis (visual findings)</b>																		
<b>3.1 Drive</b>		No striking feature			Legend rating stages { <table border="1"> <tr> <td>OK</td> <td>x</td> <td></td> <td></td> </tr> <tr> <td>uncritical</td> <td></td> <td>x</td> <td></td> </tr> <tr> <td>Critical</td> <td></td> <td></td> <td>x</td> </tr> </table>		OK	x			uncritical		x		Critical			x
OK	x																	
uncritical		x																
Critical			x															
<b>3.2 Drivetrain</b>		No striking feature			<table border="1"> <tr> <td>x</td> <td></td> <td></td> </tr> </table>		x											
x																		
<b>3.3 High pressure</b>		No striking feature			<table border="1"> <tr> <td>x</td> <td></td> <td></td> </tr> </table>		x											
x																		
<b>3.4 Bearing</b>		No striking feature			<table border="1"> <tr> <td>x</td> <td></td> <td></td> </tr> </table>		x											
x																		
<b>3.5 Shaft seal</b>		No striking feature			<table border="1"> <tr> <td>x</td> <td></td> <td></td> </tr> </table>		x											
x																		


EA11003EN-00883[1]

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.	[REDACTED]	
				Date	6/9/2008	
Department:	Person responsible:	Telephone:	Use	internal		
Non-responsive content removed				external	x	
To:	Non-responsive content removed					
For information:	[REDACTED]					
<b>3.6 Holes</b> No striking feature						<input checked="" type="checkbox"/>
<b>3.7 Attached components (metering unit, overflow valve, counting point)</b> No striking feature						<input checked="" type="checkbox"/>
<b>3.8 Other</b> O-ring screw plug cylinder head slightly twisted and with an inside notch (see Figure 1) WLI measurement of O-ring screw cap cylinder head notch (see Figs. 2 and 3)						<input checked="" type="checkbox"/>

### 3.9 Images of visual findings




Fig. 1 O-ring screw cap cylinder head inside



Notch, elevated image

Fig. 2 WLI (white-light interferometry) measurement of O-ring notch (profile interface)



Notch, width of approximately 190 μm, about 30 μm deep, cutting length

Fig. 3 WLI (white-light interferometry) measurement of O-ring notch, profile interface

### 4. Hydraulic function

				Delivery rate [l/h] of new part	Delivery rate [l/h] after testing
	n[rpm]	p_rail [bar]	I_MU [A]	7/19/2007	2/11/2008
Starting point	200	200	0.4	3.8	3.8
1000 rpm, p_rated	1000	1800	0.4	17.9	17.9
n_max_p, 500bar	3375	500	0.4	65.9	66.5

<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>		



TCD (technical customer documentation) testing point LG (1,000 rpm, p\_rated ≥ 15.5 or 15.2 l/h after running time) is met.  
 No significant fuel-quantity drift compared to delivery measurement.

### 5. Destiny of the parts



The pump is stored at RB until 09/2008 and then scrapped.





EA11003EN-00883[2]

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.		[Redacted]	
				Date		6/9/2008	
<b>Department:</b>		<b>Person responsible:</b>		<b>Telephone:</b>		Use	
Non-responsive content removed		[Redacted]		[Redacted]		internal <input type="checkbox"/> external <input checked="" type="checkbox"/>	
To: Non-responsive content removed For information: [Redacted]							
<b>6. Attachments</b> None							
<b>Tested:</b>	Non-responsive content removed	Phone	Non-responsive content removed	Date:	6/17/2008	Signature:	Non-responsive content removed
<b>Department:</b>	[Redacted]	Phone	[Redacted]	Date:	6/30/2008	Signature:	[Redacted]
<b>Department:</b>	[Redacted]	Phone	[Redacted]	Date:	7/3/2008	Signature:	[Redacted]











EA11003EN-00884101



 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.											
				Date	6/17/2008										
<b>Department:</b>	<b>Person responsible:</b>	<b>Telephone:</b>	Use		internal										
Non-responsive content removed				external	x										
To:	Non-responsive content removed														
For information:															
<b>Pump type:</b> CP4.2S_348_2x5,25_REC_3,3_1,95_MT4,2		<b>Customer:</b> VW	<b>Project:</b> R4 2.0 EU5	<b>Project / design pattern type</b> D / Series											
<b>Part number (TTNo.):</b> 445010507		<b>Date of manufacture:</b> 050607	<b>Serial number:</b> 0328	<b>Manufacturing plant - line</b> 011M FeP (Feuerbach plant)-M - 01											
<b>SAP-No.:</b> 30-101005-01		<b>Samos no.:</b> 590401.001	<b>Customer order no.:</b>	<b>Engine/Vehicle number</b>											
<b>Customer part number</b>	<b>Endurance run type [customer]:</b> Engine endurance run	<b>Endurance run conditions:</b> endurance run 1+ÖVL	<b>DSBFD no.:</b> 20454												
<b>Mileage</b> 279 h	<b>Parts receipt at dept. DS-PC/EDI:</b> 2/26/2008	<b>Process no.</b> 2008-CP4_0175	<b>Confidentiality note</b> Confidential												
<b>VA / ETC no.:</b> DS-176930	<b>Durability test type [RB]:</b>	<b>Fuel:</b> EN590													
<b>Complaint:</b>															
<b>1. Subject</b> CP4 customer return Diagnosis of endurance run end without complaint															
<b>2. Conclusion</b> <b>Function</b> - Delivery rates after endurance run without significant fuel-quantity drift in comparison with the new state. <b>Components</b> - Wear of the components is low and without significant striking features. <b>Result</b> - The pump has <b>passed</b> the endurance run.															
<b>3. Results of diagnosis (visual findings)</b>			Legend rating stages		OK uncritical Critical	<table border="1"> <tr><td>x</td><td></td><td></td></tr> <tr><td></td><td>x</td><td></td></tr> <tr><td></td><td></td><td>x</td></tr> </table>	x				x				x
x															
	x														
		x													
<b>3.1 Drive</b> No striking feature						<table border="1"> <tr><td>x</td><td></td><td></td></tr> </table>	x								
x															
<b>3.2 Drivetrain</b> No striking feature						<table border="1"> <tr><td>x</td><td></td><td></td></tr> </table>	x								
x															
<b>3.3 High pressure</b> No striking feature						<table border="1"> <tr><td>x</td><td></td><td></td></tr> </table>	x								
x															
<b>3.4 Bearing</b> No striking feature						<table border="1"> <tr><td>x</td><td></td><td></td></tr> </table>	x								
x															
<b>3.5 Shaft seal</b> No striking feature						<table border="1"> <tr><td>x</td><td></td><td></td></tr> </table>	x								
x															
<b>3.6 Holes</b> No striking feature						<table border="1"> <tr><td>x</td><td></td><td></td></tr> </table>	x								
x															
<b>3.7 Attached components (metering unit, overflow valve, counting point)</b> No striking feature						<table border="1"> <tr><td>x</td><td></td><td></td></tr> </table>	x								
x															
<b>3.8 Other</b> No striking feature						<table border="1"> <tr><td>x</td><td></td><td></td></tr> </table>	x								
x															

EA11003EN-00884[1]

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no. <span style="background-color: black; color: black;">[REDACTED]</span>	
				Date	6/9/2008
<b>Department:</b> Non-responsive content removed		<b>Person responsible:</b> Non-responsive content removed		<b>Telephone:</b> Non-responsive content removed	
				Use	internal external <input checked="" type="checkbox"/>
<b>4. Hydraulic function</b>					
				Delivery rate [l/h] of new part	Delivery rate [l/h] after testing
	n[rpm]	p_rail [bar]	I_MU [A]	6/5/2007	3/7/2008
Starting point	200	200	0.4	3.9	4.2
1000 rpm, p_rated	1000	1800	0.4	17.5	17.1
n_max_p, 500bar	3375	500	0.4	66.1	65.8
				<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
				<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
				<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
TCD (technical customer documentation) testing point LG (1,000 rpm, p_rated ≥ 15.5 or 15.2 l/h after running time) is met. No significant fuel-quantity drift compared to delivery measurement.					
<b>5. Destiny of the parts</b>					
The pump is stored at RB until 09/2008 and then scrapped.					
<b>6. Attachments</b>					
None					
<b>Tested:</b>	Non-responsive content removed	Phone	Non-responsive content removed	Date:	6/23/2008
<b>Signature:</b>	Non-responsive content removed				
<b>Department:</b>	Non-responsive content removed	Phone	Non-responsive content removed	Date:	6/23/2008
<b>Signature:</b>	Non-responsive content removed				



 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.		
				Date	6/17/2008	
Department:	Person responsible:	Telephone:	Use	internal		
Non-responsive content removed				external	x	
To:	Non-responsive content removed					
For information:						
<b>Pump type:</b> CP4.1S_348_2x5,25_REC_3,3_1,95_MT4,2		<b>Customer:</b> VW	<b>Project:</b> R4 2.0 EU5	<b>Project / design pattern type</b> D / Series		
<b>Part number (TTNo.):</b> 445010507		<b>Date of manufacture:</b> 020507	<b>Serial number:</b> 0272	<b>Manufacturing plant - line</b> 0110 FeP (Feuerbach plant) – 01		
<b>SAP-No.:</b> 30-101005-01		<b>Samos no.:</b> 590270.001	<b>Customer order no.:</b> CAH0000074	<b>Engine/Vehicle number</b> CAH0000074		
<b>Customer part number</b> CAH0000074		<b>Endurance run type [customer]:</b> Vehicle endurance run	<b>Endurance run conditions:</b> GDV-EWP	<b>DSBFD no.:</b> 20469		
<b>Mileage</b> 101956 km		<b>Parts receipt at dept. DS-PC/EDI:</b> 2/26/2008	<b>Process no.</b> 2008-CP4_0181	<b>Confidentiality note</b> Confidential		
<b>VA / ETC no.:</b> DS-176922		<b>Durability test type [RB]:</b>	<b>Fuel:</b> EN590			
<b>Complaint:</b>						
<b>1. Subject</b> CP4 customer return Diagnosis of endurance run end without complaint						
<b>2. Conclusion</b> <b>Function</b> - Delivery rates after endurance run without significant fuel-quantity drift in comparison with the new state. - Cold seal-tightness confirmed up to -30°C after endurance run <b>Components</b> - The slightly asymmetric wear of the intake valve plate and stationary seal ring is still uncritical. - metering unit O-ring slightly cut by oblique assembly (marks in the housing and at the metering unit). The error is known through 0-km complaints at VW and recorded on 8D. - Wear of the remaining components is low and without significant striking features. <b>Result</b> - The pump has passed the endurance run.						
<b>3. Results of diagnosis (visual findings)</b>			Legend rating stages { <div>           OK            uncritical            Critical         </div>			
<b>3.1 Drive</b> No striking feature						
<b>3.2 Drivetrain</b> No striking feature						
<b>3.3 High pressure</b> Fretting wear between intake valve sealing surface (see Fig. 1) and stationary seal ring (see fig. 2)						
<b>3.4 Bearing</b> No striking feature						
<b>3.5 Shaft seal</b> No striking feature						
<b>3.6 Holes</b> Metering unit hole with scrape marks through metering unit assembly (see Figure 3)						
<b>3.7 Attached components (metering unit, overflow valve, counting point)</b> Metering unit magnetic drum with scrape marks (see Fig. 4) and metering unit O-ring cut (see Fig. 5)						

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.	
				Date	6/17/2008
Department:	Person responsible:	Telephone:	Use	internal	
Non-responsive content removed				external	x
<b>3.8 Other</b> No striking feature				x	

## 3.9 Images of visual findings




Fig. 1 Intake valve, sealing area (wear)




Fig. 2 Intake valve stationary seal ring, sealing area (wear)




Fig. 3 Housing, metering unit hole (scrape marks)




Fig. 4 Metering unit, magnetic drum (scrape marks)




Fig. 5 Metering ring, O-ring (sheared off)

## 4. Hydraulic function

				Delivery rate [l/h] of new part	Delivery rate [l/h] after testing
	n[rpm]	p_rail [bar]	I_MU [A]	5/2/2007	3/7/2008
Starting point	200	200	0.4	3.8	4.3
1000 rpm, p_rated	1000	1800	0.4	17.8	17.4
n_max p, 500bar	3375	500	0.4	67.2	65.6

x		
x		
x		



TCD (technical customer documentation) testing point LG (1,000 rpm, p\_rated ≥ 15.5 or 15.2 l/h after running time) is met.

No significant fuel-quantity drift compared to delivery measurement.

## 5. Destiny of the parts



The pump is stored at RB until 09/2008 and then scrapped.

EA11003EN-00885[2]



 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.			
				Date		6/17/2008	
<b>Department:</b>	<b>Person responsible:</b>	<b>Telephone:</b>		Use		internal	
Non-responsive content removed						external	x
<b>6. Attachments</b> None							
<b>Tested:</b>	Non-responsive content removed	Phone	Non-responsive content removed	<b>Date:</b>	6/23/2008	<b>Signature:</b>	Non-responsive content removed
<b>Department:</b>		Phone		<b>Date:</b>	6/23/2008	<b>Signature:</b>	
<b>Department:</b>		Phone		<b>Date:</b>	6/27/2008	<b>Signature:</b>	





EA11003EN-00886[0]

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.	[REDACTED]										
				Date	6/18/2008										
<b>Department:</b>	<b>Person responsible:</b>	<b>Telephone:</b>	Use		internal										
Non-responsive content removed				external	x										
To:	Non-responsive content removed														
For information:															
<b>Pump type:</b>	<b>Customer:</b>	<b>Project:</b>	<b>Project / design pattern type</b>												
CP4.1S_348_2x5,25_REC_3,3_1,95_MT4,2	VW	R4 2.0 EU5	D / Series												
<b>Part number (TTNo.):</b>	<b>Date of manufacture:</b>	<b>Serial number:</b>	<b>Manufacturing plant - line</b>												
445010507	100407	0277	0110 FeP (Feuerbach plant) – 01												
<b>SAP-No.:</b>	<b>Samos no.:</b>	<b>Customer order no.:</b>	<b>Engine/Vehicle number</b>												
30-101005-01	590405.001	CBA0000545	CBA0000545												
<b>Customer part number</b>	<b>Endurance run type [customer]:</b>	<b>Endurance run conditions:</b>	<b>DSBFD no.:</b>												
CBA0000545	Engine endurance run	Vehicle air-conditioning technology - reclaimed refrigerant. DPF	20453												
<b>Mileage</b>	<b>Parts receipt at dept. DS-PC/EDI:</b>	<b>Process no.</b>	<b>Confidentiality note</b>												
1225 h	2/26/2008	2008-CP4_0182	Confidential												
<b>VA / ETC no.:</b>	<b>Durability test type [RB]:</b>	<b>Fuel:</b>													
DS-176931		EN590													
<b>Complaint:</b>															
<b>1. Subject</b>															
CP4 customer return Diagnosis of endurance run end without complaint															
<b>2. Conclusion</b>															
<b>Function</b> - Delivery rates after endurance run without significant fuel-quantity drift in comparison with the new state. - Cold seal-tightness confirmed up to -30°C after endurance run <b>Components</b> - Wear of the components is low and without significant striking features. <b>Result</b> - The pump has <b>passed</b> the endurance run.															
<b>3. Results of diagnosis (visual findings)</b>			Legend rating stages { <div>           OK uncritical Critical         </div>		<table border="1"> <tr><td>x</td><td></td><td></td></tr> <tr><td></td><td>x</td><td></td></tr> <tr><td></td><td></td><td>x</td></tr> </table>		x				x				x
x															
	x														
		x													
<b>3.1 Drive</b>					<table border="1"> <tr><td>x</td><td></td><td></td></tr> <tr><td></td><td></td><td></td></tr> </table>		x								
x															
No striking feature															
<b>3.2 Drivetrain</b>					<table border="1"> <tr><td>x</td><td></td><td></td></tr> <tr><td>x</td><td></td><td></td></tr> </table>		x			x					
x															
x															
No striking feature															
<b>3.3 High pressure</b>					<table border="1"> <tr><td>x</td><td></td><td></td></tr> <tr><td></td><td></td><td></td></tr> </table>		x								
x															
No striking feature															
<b>3.4 Bearing</b>					<table border="1"> <tr><td>x</td><td></td><td></td></tr> <tr><td></td><td></td><td></td></tr> </table>		x								
x															
No striking feature															
<b>3.5 Shaft seal</b>					<table border="1"> <tr><td>x</td><td></td><td></td></tr> <tr><td></td><td></td><td></td></tr> </table>		x								
x															
No striking feature															
<b>3.6 Holes</b>					<table border="1"> <tr><td>x</td><td></td><td></td></tr> <tr><td></td><td></td><td></td></tr> </table>		x								
x															
No striking feature															
<b>3.7 Attached components (metering unit, overflow valve, counting point)</b>					<table border="1"> <tr><td>x</td><td></td><td></td></tr> <tr><td></td><td></td><td></td></tr> </table>		x								
x															
No striking feature															
<b>3.8 Other</b>					<table border="1"> <tr><td>x</td><td></td><td></td></tr> <tr><td></td><td></td><td></td></tr> </table>		x								
x															
No striking feature															

EA11003EN-00886[1]



 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no. <span style="background-color: black; color: black;">[REDACTED]</span>	
				Date	6/18/2008
<b>Department:</b>	<b>Person responsible:</b>	<b>Telephone:</b>		Use	<input type="checkbox"/> internal <input checked="" type="checkbox"/> external
Non-responsive content removed		<span style="background-color: black; color: black;">[REDACTED]</span>			
<b>4. Hydraulic function</b>					
				Delivery rate [l/h] of new part	Delivery rate [l/h] after testing
	n[rpm]	p_rail [bar]	I_MU [A]	4/10/2007	3/7/2008
Starting point	200	200	0.4	3.8	4.3
1000 rpm, p_rated	1000	1800	0.4	17.5	17.2
n_max_p, 500bar	3375	500	0.4	67	65.5
				<input checked="" type="checkbox"/>	<input type="checkbox"/>
				<input checked="" type="checkbox"/>	<input type="checkbox"/>
				<input checked="" type="checkbox"/>	<input type="checkbox"/>
TCD (technical customer documentation) testing point LG (1,000 rpm, p_rated ≥ 15.5 or 15.2 l/h after running time) is met.					
No significant fuel-quantity drift compared to delivery measurement.					
<b>5. Destiny of the parts</b>					
The pump is stored at RB until 09/2008 and then scrapped.					
<b>6. Attachments</b>					
None					
<b>Tested:</b>	Non-responsive content removed	Phone	Non-responsive content removed	Date:	6/23/2008
<b>Signature:</b>	<span style="background-color: black; color: black;">[REDACTED]</span>			<b>Signature:</b>	Non-responsive content removed
<b>Department:</b>	<span style="background-color: black; color: black;">[REDACTED]</span>	Phone	<span style="background-color: black; color: black;">[REDACTED]</span>	Date:	6/23/2008
<b>Signature:</b>	<span style="background-color: black; color: black;">[REDACTED]</span>			<b>Signature:</b>	<span style="background-color: black; color: black;">[REDACTED]</span>



EA11003EN-00887101

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.	[Redacted]										
				Date	6/18/2008										
<b>Department:</b>	<b>Person responsible:</b>	<b>Telephone:</b>		Use	internal										
Non-responsive content removed					external	x									
To:	Non-responsive content removed														
For information:															
<b>Pump type:</b> CP4.1S_348_2x5,25_REC_3,3_1,95_MT4,2	<b>Customer:</b> VW	<b>Project:</b> R4 2.0 EU5	<b>Project / design pattern type</b> D / Series												
<b>Part number (TTNo.):</b> 445010507	<b>Date of manufacture:</b> 050607	<b>Serial number:</b> 0325	<b>Manufacturing plant - line</b> 0110 FeP (Feuerbach plant) – 01												
<b>SAP-No.:</b> 30-101005-01	<b>Samos no.:</b> 590283.001	<b>Customer order no.:</b> CAH0000136	<b>Engine/Vehicle number</b> CAH0000136												
<b>Customer part number</b> CAH0000136	<b>Endurance run type [customer]:</b> Engine endurance run	<b>Endurance run conditions:</b> ÖVL+endurance run 1+ÖVL	<b>DSBFD no.:</b> 20468												
<b>Mileage</b> 440 h	<b>Parts receipt at dept. DS-PC/EDI:</b> 2/26/2008	<b>Process no.</b> 2008-CP4_0187	<b>Confidentiality note</b> Confidential												
<b>VA / ETC no.:</b> DS-176925	<b>Durability test type [RB]:</b>	<b>Fuel:</b> EN590													
<b>Complaint:</b>															
<b>1. Subject</b> CP4 customer return Diagnosis of endurance run end without complaint															
<b>2. Conclusion</b> <b>Function</b> - Delivery rates after endurance run without significant fuel-quantity drift in comparison with the new state. <b>Components</b> - Wear of the components is low and without significant striking features. <b>Result</b> -The pump has passed the durability test.															
<b>3. Results of diagnosis (visual findings)</b> <div style="float: right; text-align: right;">         Legend rating stages {         <div style="display: inline-block; vertical-align: middle; margin-right: 5px;">OK</div> <div style="display: inline-block; vertical-align: middle; margin-right: 5px;">uncritical</div> <div style="display: inline-block; vertical-align: middle;">Critical</div> </div> <table style="float: right; border-collapse: collapse;"> <tr> <td style="border: 1px solid black; width: 20px; height: 20px; text-align: center;">x</td> <td style="border: 1px solid black; width: 20px; height: 20px;"></td> <td style="border: 1px solid black; width: 20px; height: 20px;"></td> </tr> <tr> <td style="border: 1px solid black; width: 20px; height: 20px;"></td> <td style="border: 1px solid black; width: 20px; height: 20px; text-align: center;">x</td> <td style="border: 1px solid black; width: 20px; height: 20px;"></td> </tr> <tr> <td style="border: 1px solid black; width: 20px; height: 20px;"></td> <td style="border: 1px solid black; width: 20px; height: 20px;"></td> <td style="border: 1px solid black; width: 20px; height: 20px; text-align: center;">x</td> </tr> </table>							x				x				x
x															
	x														
		x													
<b>3.1 Drive</b> No striking feature			<table border="1" style="width: 100px; height: 20px;"> <tr> <td style="background-color: green; text-align: center;">x</td> <td></td> <td></td> </tr> </table>				x								
x															
<b>3.2 Drivetrain</b> No striking feature			<table border="1" style="width: 100px; height: 20px;"> <tr> <td style="background-color: green; text-align: center;">x</td> <td></td> <td></td> </tr> </table>				x								
x															
<b>3.3 High pressure</b> No striking feature			<table border="1" style="width: 100px; height: 20px;"> <tr> <td style="background-color: green; text-align: center;">x</td> <td></td> <td></td> </tr> </table>				x								
x															
<b>3.4 Bearing</b> No striking feature			<table border="1" style="width: 100px; height: 20px;"> <tr> <td style="background-color: green; text-align: center;">x</td> <td></td> <td></td> </tr> </table>				x								
x															
<b>3.5 Shaft seal</b> No striking feature			<table border="1" style="width: 100px; height: 20px;"> <tr> <td style="background-color: green; text-align: center;">x</td> <td></td> <td></td> </tr> </table>				x								
x															
<b>3.6 Holes</b> No striking feature			<table border="1" style="width: 100px; height: 20px;"> <tr> <td style="background-color: green; text-align: center;">x</td> <td></td> <td></td> </tr> </table>				x								
x															
<b>3.7 Attached components (metering unit, overflow valve, counting point)</b> No striking feature			<table border="1" style="width: 100px; height: 20px;"> <tr> <td style="background-color: green; text-align: center;">x</td> <td></td> <td></td> </tr> </table>				x								
x															
<b>3.8 Other</b> No striking feature			<table border="1" style="width: 100px; height: 20px;"> <tr> <td style="background-color: green; text-align: center;">x</td> <td></td> <td></td> </tr> </table>				x								
x															





EA11003EN-00887[1]

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no. <span style="background-color: black; color: black;">[REDACTED]</span>	
				Date	6/18/2008
<b>Department:</b>	<b>Person responsible:</b>	<b>Telephone:</b>		Use	<input type="checkbox"/> internal <input checked="" type="checkbox"/> external
Non-responsive content removed		<span style="background-color: black; color: black;">[REDACTED]</span>			
<b>4. Hydraulic function</b>					
				Delivery rate [l/h] of new part	Delivery rate [l/h] after testing
	n[rpm]	p_rail [bar]	I_MU [A]	6/5/2007	3/7/2008
Starting point	200	200	0.4	3.9	4.2
1000 rpm, p_rated	1000	1800	0.4	17.9	17.6
n_max_p, 500bar	3375	500	0.4	66.6	65.9
				<input checked="" type="checkbox"/>	<input type="checkbox"/>
				<input checked="" type="checkbox"/>	<input type="checkbox"/>
				<input checked="" type="checkbox"/>	<input type="checkbox"/>
TCD (technical customer documentation) testing point LG (1,000 rpm, p_rated ≥ 15.5 or 15.2 l/h after running time) is met. No significant fuel-quantity drift compared to delivery measurement.					
<b>5. Destiny of the parts</b>					
The pump is stored at RB until 09/2008 and then scrapped.					
<b>6. Attachments</b>					
None					
<b>Tested:</b>	Non-responsive content removed	Phone	Non-responsive content removed	Date:	6/23/2008
<b>Signature:</b>	<span style="background-color: black; color: black;">[REDACTED]</span>				
<b>Department:</b>	<span style="background-color: black; color: black;">[REDACTED]</span>	Phone	<span style="background-color: black; color: black;">[REDACTED]</span>	Date:	6/23/2008
<b>Signature:</b>	<span style="background-color: black; color: black;">[REDACTED]</span>				



 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.											
				Date	6/18/2008										
<b>Department:</b>	<b>Person responsible:</b>	<b>Telephone:</b>		Use	internal										
Non-responsive content removed					external	x									
<b>To:</b> Non-responsive content removed															
<b>For information:</b> Non-responsive content removed															
<b>Pump type:</b> CP4.1S_348_2x5,25_REC_3,3_1,95_MT4,2		<b>Customer:</b> VW		<b>Project:</b> R4 2.0 EU5		<b>Project / design pattern type</b> D / Series									
<b>Part number (TTNo.):</b> 445010507		<b>Date of manufacture:</b> 230707		<b>Serial number:</b> 0222		<b>Manufacturing plant - line</b> 0110 FeP (Feuerbach plant) – 01									
<b>SAP-No.:</b> 30-101005-01		<b>Samos no.:</b> 590276.001		<b>Customer order no.:</b> CBA0002352		<b>Engine/Vehicle number</b> CBA0002352									
<b>Customer part number</b> CBA0002352		<b>Endurance run type [customer]:</b> Vehicle endurance run		<b>Endurance run conditions:</b> GDV-EWP		<b>DSBFD no.:</b> 20467									
<b>Mileage</b> 44950 km		<b>Parts receipt at dept. DS-PC/EDI:</b> 2/26/2008		<b>Process no.</b> 2008-CP4_0188		<b>Confidentiality note</b> Confidential									
<b>VA / ETC no.:</b> DS-176924		<b>Durability test type [RB]:</b>		<b>Fuel:</b> EN590											
<b>Complaint:</b>															
<b>1. Subject</b> CP4 customer return Diagnosis of endurance run end without complaint															
<b>2. Conclusion</b> <b>Function</b> - Delivery rates after endurance run without significant fuel-quantity drift in comparison with the new state. <b>Components</b> - Wear of the components is low and without significant striking features. <b>Result</b> - The pump has <b>passed</b> the durability test.															
<b>3. Results of diagnosis (visual findings)</b>				Legend rating stages { <div>           OK uncritical Critical         </div>		<table border="1"> <tr><td>x</td><td></td><td></td></tr> <tr><td></td><td>x</td><td></td></tr> <tr><td></td><td></td><td>x</td></tr> </table>	x				x				x
x															
	x														
		x													
<b>3.1 Drive</b> No striking feature						<table border="1"> <tr><td>x</td><td></td><td></td></tr> </table>	x								
x															
<b>3.2 Drivetrain</b> No striking feature						<table border="1"> <tr><td>x</td><td></td><td></td></tr> </table>	x								
x															
<b>3.3 High pressure</b> No striking feature						<table border="1"> <tr><td>x</td><td></td><td></td></tr> </table>	x								
x															
<b>3.4 Bearing</b> No striking feature						<table border="1"> <tr><td>x</td><td></td><td></td></tr> </table>	x								
x															
<b>3.5 Shaft seal</b> No striking feature						<table border="1"> <tr><td>x</td><td></td><td></td></tr> </table>	x								
x															
<b>3.6 Holes</b> No striking feature						<table border="1"> <tr><td>x</td><td></td><td></td></tr> </table>	x								
x															
<b>3.7 Attached components (metering unit, overflow valve, counting point)</b> No striking feature						<table border="1"> <tr><td>x</td><td></td><td></td></tr> </table>	x								
x															
<b>3.8 Other</b> No striking feature						<table border="1"> <tr><td>x</td><td></td><td></td></tr> </table>	x								
x															

EA11003EN-00888[1]

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no. <span style="background-color: black; color: black;">[REDACTED]</span>										
				Date	6/18/2008									
<b>Department:</b>	<b>Person responsible:</b>	<b>Telephone:</b>	Use <span style="float: right;">internal <input type="checkbox"/> external <input checked="" type="checkbox"/></span>											
Non-responsive content removed														
<b>4. Hydraulic function</b>														
				Delivery rate [l/h] of new part	Delivery rate [l/h] after testing									
	n[rpm]	p_rail [bar]	I_MU [A]	7/19/2007	3/7/2008									
Starting point	200	200	0.4	3.8	4.3									
1000 rpm, p_rated	1000	1800	0.4	17.7	17.4									
n_max_p, 500bar	3375	500	0.4	66.8	66.3									
				<table border="1"> <tr><td>x</td><td></td><td></td></tr> <tr><td>x</td><td></td><td></td></tr> <tr><td>x</td><td></td><td></td></tr> </table>		x			x			x		
x														
x														
x														
TCD (technical customer documentation) testing point LG (1,000 rpm, p_rated ≥ 15.5 or 15.2 l/h after running time) is met. No significant fuel-quantity drift compared to delivery measurement.														
<b>5. Destiny of the parts</b>														
The pump is stored at RB until 09/2008 and then scrapped.														
<b>6. Attachments</b>														
None														
<b>Tested:</b>	Non-responsive content removed	Phone	Non-responsive content removed	Date:	6/23/2008									
<b>Signature:</b>				<b>Signature:</b>	Non-responsive content removed									
<b>Department:</b>		Phone		Date:	6/23/2008									
<b>Signature:</b>				<b>Signature:</b>										



EA11003EN-00889[0]

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.		
				Date	7/15/2008	
<b>Department:</b>	<b>Person responsible:</b>	<b>Telephone:</b>	Use		internal	
Non-responsive content removed					external	x
To:	Non-responsive content removed					
For information:						

<b>Pump type:</b> CP4.2S_644_2x4.85_REC_3.3_1.3_R2.0	<b>Customer:</b> AUDI	<b>Project:</b> W19 EU5	<b>Project / design pattern type</b> C / C
<b>Part number (TTNo.):</b> 0445B20197	<b>Date of manufacture:</b> 070227	<b>Serial number:</b> 0081	<b>Manufacturing plant - line</b> 011M FeP (Feuerbach plant)-M -
<b>SAP-No.:</b> 30-100481-06	<b>Samos no.:</b> 593398	<b>Customer order no.:</b>	<b>Engine/Vehicle number</b> 059 D CO2 012
<b>Customer part number</b> CP4.2_081	<b>Endurance run type [customer]:</b> Engine endurance run	<b>Endurance run conditions:</b> Diesel 5	<b>DSBFD no.:</b> 20661
<b>Mileage</b> 530 h	<b>Parts receipt at dept. DS-PC/EDI:</b> 3/19/2008	<b>Process no.</b> 2008-CP4_0255	<b>Confidentiality note</b> Confidential
<b>VA / ETC no.:</b> DS-179387	<b>Durability test type [RB]:</b>	<b>Fuel:</b> EN590	

### 1. Subject

**CP4 customer returns without complaint.**

Diagnosis of pump after endurance run end.

Testing conditions: Engine endurance run "diesel 5", engine 059 D CO2 012

### 2. Conclusion

**Function**

- The volumetric efficiency of the back measurement is OK. There is no significant drift when compared to the new part measurement (for more details, see 4).
- The seal-tightness of the non-return valves (RSV) was analyzed separately and is OK

**Visual findings**

- All components have normal running marks only during the running time (green rating).

**The test was passed.**

### 3. Results of diagnosis (visual findings)

**3.1 Drive**

No striking feature

Legend rating stages

OK



uncritical



Critical

x		
	x	
		x

<b>3.2 Drivetrain</b>	<table border="1" style="border-collapse: collapse;"> <tr><td style="background-color: green;">x</td><td></td><td></td></tr> </table>	x		
x				
No striking feature				
<b>3.3 High pressure</b>	<table border="1" style="border-collapse: collapse;"> <tr><td style="background-color: green;">x</td><td></td><td></td></tr> </table>	x		
x				
No striking feature				
<b>3.4 Bearing</b>	<table border="1" style="border-collapse: collapse;"> <tr><td style="background-color: green;">x</td><td></td><td></td></tr> </table>	x		
x				
No striking feature				
<b>3.5 Shaft seal</b>	<table border="1" style="border-collapse: collapse;"> <tr><td style="background-color: green;">x</td><td></td><td></td></tr> </table>	x		
x				
No striking feature				
<b>3.6 Holes</b>	<table border="1" style="border-collapse: collapse;"> <tr><td style="background-color: green;">x</td><td></td><td></td></tr> </table>	x		
x				
No striking feature				
<b>3.7 Attached components (metering unit, overflow valve, counting point)</b>	<table border="1" style="border-collapse: collapse;"> <tr><td style="background-color: green;">x</td><td></td><td></td></tr> </table>	x		
x				
No striking feature				
<b>3.8 Other</b>	<table border="1" style="border-collapse: collapse;"> <tr><td style="background-color: green;">x</td><td></td><td></td></tr> </table>	x		
x				
No striking feature				

EA11003EN-00889[1]

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no. <span style="background-color: black; color: black;">[REDACTED]</span>	
				Date	7/15/2008
<b>Department:</b>	<b>Person responsible:</b>	<b>Telephone:</b>		Use	<input type="checkbox"/> internal <input checked="" type="checkbox"/> external
Non-responsive content removed		<span style="background-color: black; color: black;">[REDACTED]</span>			
<b>3.9 Other</b> No striking feature					
<b>4. Hydraulic function</b>					
				Delivery rate [l/h] of new part	Delivery rate [l/h] after testing
	n[rpm]	p_rail [bar]	I_MU [A]	2/26/2007	4/7/2008
LG	1000	1800	0.4	31.3	31.8
				<input checked="" type="checkbox"/>	<input type="checkbox"/>
The volumetric efficiency of the back measurement is OK (within TCD nominal value). There is no significant drift when compared to the new part measurement.					
<b>5. Destiny of the parts</b>					
The pump will be scrapped at the request of Audi.					
<b>6. Attachments</b>					
None					
<b>Tested:</b>	Non-responsive content removed	Phone	Non-responsive content removed	Date:	7/21/2008
<b>Signature:</b>	Non-responsive content removed				
<b>Department:</b>		Phone		Date:	7/23/2008
<b>Signature:</b>					

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.		
				Date	7/18/2008	
<b>Department:</b>	<b>Person responsible:</b>	<b>Telephone:</b>		Use	internal	
Non-responsive content removed					external	x
To:	Non-responsive content removed					
For information:						
<b>Pump type:</b> CP4.2S_644_2x4.85_REC_3.3_1.2_MT2.0	<b>Customer:</b> AUDI	<b>Project:</b> W19 EU5	<b>Project / design pattern type</b> Series / D			
<b>Part number (TTNo.):</b> 445010611	<b>Date of manufacture:</b> 171106	<b>Serial number:</b> 0001	<b>Manufacturing plant - line</b> 0110 FeP (Feuerbach plant) – 01			
<b>SAP-No.:</b> 30-100481-06	<b>Samos no.:</b> 593551	<b>Customer order no.:</b>	<b>Engine/Vehicle number</b> CAS 508			
<b>Customer part number</b> CP4.2_078	<b>Endurance run type [customer]:</b> Vehicle endurance run	<b>Endurance run conditions:</b> Q-AL in Q7	<b>DSBFD no.:</b> 20678			
<b>Mileage</b> 65000 km	<b>Parts receipt at dept. DS-PC/EDI:</b> 3/19/2008	<b>Process no.</b> 2008-CP4_0258	<b>Confidentiality note</b> Confidential			
<b>VA / ETC no.:</b> DS-179498		<b>Fuel:</b> EN590				

### 1. Subject

**CP4 customer returns without complaint**  
 Diagnosis of pump after endurance run end.  
 Testing conditions: Vehicle endurance run Q-AL in Audi Q7, engine CAS 000 508

### 2. Conclusion

**Function**  
 - The volumetric efficiency of the back measurement is OK. There is no significant drift when compared to the new part measurement (for more details, see 4).  
 - The metering unit was diagnosed separately for GS-CP/EEC1. Functional and visual findings are OK (see Appendix 6 ZVM 614)

**Visual findings**  
 - All components have normal running marks only during the running time (green rating).  
**The test was passed.**

### 3. Results of diagnosis (visual findings)

Legend rating stages



OK			
uncritical			
Critical			



  

<b>3.1 Drive</b> No striking feature			
<b>3.2 Drivetrain</b> No striking feature			
<b>3.3 High pressure</b> No striking feature			
<b>3.4 Bearing</b> No striking feature			
<b>3.5 Shaft seal</b> No striking feature			
<b>3.6 Holes</b> No striking feature			
<b>3.7 Attached components (metering unit, overflow valve, counting point)</b> No striking features with respect to metering unit see Appendix			
<b>3.8 O-rings</b> No striking feature			



EA11003EN-00890[1]

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no. <span style="background-color: black; color: black;">[REDACTED]</span>	
				Date	7/18/2008
<b>Department:</b>	<b>Person responsible:</b>	<b>Telephone:</b>		Use	<input type="checkbox"/> internal <input checked="" type="checkbox"/> external
Non-responsive content removed					
<b>3.9 Other</b>					
No striking feature					
<b>4. Hydraulic function</b>					
				Delivery rate [l/h] of new part	Delivery rate [l/h] after testing
	n[rpm]	p rail [bar]	I MU [A]	11/17/2006	4/4/2008
LG	1000	1800	0.4	31.4	32
				<input checked="" type="checkbox"/>	<input type="checkbox"/>
The volumetric efficiency of the back measurement is OK (within TCD nominal value). There is no significant drift when compared to the new part measurement.					
<b>5. Destiny of the parts</b>					
The pump will be scrapped at the request of Audi.					
<b>6. Attachments</b>					
Metering unit diagnosis ZVM614					
<b>Tested:</b>	Non-responsive content removed	Phone	Non-responsive content removed	Date:	7/23/2008
<b>Signature:</b>				<b>Signature:</b>	Non-responsive content removed
<b>Department:</b>		Phone		Date:	7/23/2008
<b>Signature:</b>				<b>Signature:</b>	

 <b>BOSCH</b> 	<b>Diagnosis ZVM 614</b>	Waiblingen, 07.01.2008
<b>Metering unit 0928400708 serial no. 53 date of manufacture 69006</b>		

**Customer Audi**

EA11003EN-00890[2]

To  
Cc

Non-responsive content removed

**Pump** 0445010611 **serial no.** 0001 **date of manufacture** 171106**Endurance run diagnosis no.** DNA 2282; ASMUS / SAMOS 0593551; diagnosis no. 20678;  
DS-179498**SAP** 30-100481-01**1. Description****Metering unit complaint:** No**System design** Vehicle**Endurance run type** Q-AL in Q7**Running time** 65000 km**Remark:**

Customer return no. 2008-CP4\_0258.

Project: W19EU5.

The development no. 0928 B01 481 is also printed on the metering unit.

Fuel: EN590.

**2. Diagnosis**

- **Visual findings (external):**

Metering unit housing is contaminated and / or rusted and a piece of plastic injection molding is broken off, both without any impairment of function, see photos. Otherwise, no complaints are externally visible.

- **Function:**

The characteristic curve of the displacement / current measurement looks good.

During the delivery rate / current measurement, all values are within the tolerances.

- **Wear:**

There are no or only slight running marks on the components.

- **Other:**

None.

**3. Result****[X] Passed****[ ] Conditionally passed****[ ] Failed**

The metering unit is functionally OK, delivery rate and displacement measurements yielded positive results. Wear of the components is low.

**4. Corrective actions**

No error.



**5. Other tests (e.g. material analysis. process analysis)**

No further tests are performed.

**6. Destiny of the parts**


Metering unit is returned to the client.

Person responsible:	Non-responsive content removed	
Approval:	Non-responsive content removed	

	<b>BOSCH</b> 	<b>Diagnosis ZVM 614</b>	Waiblingen, 07.01.2008
<b>Metering unit</b> 0928400708 <b>serial no.</b> 53 <b>date of manufacture</b> 69006			

Non-responsive content removed

EA11003EN-00890[3]

**Function:**

Diagnosis values


Delivery rate [l/h]

Current [A]

Testing point [A]	0.8	1.0	1.2	1.4	1.80
Diagnosis values [l/h]	88.93	68.72	47.17	24.86	0.15

**Wear:**

<b>External</b>	1	2	3	4	5	6	7	8	9	10
contamination:					X					
Damage:					X					
Filter contamination		X								
Filter damage		X								
O-ring outside		X								
Seal		X								



<b>internal</b>	1	2	3	4	5	6	7	8	9	10
Tappet housing:		X								
Bearing housing:		X								
Tappet magnetic core:		X								
Bearing magnetic core:		X								
O-ring inside:		X								
Valve piston:		X								

**BOSCH****Diagnosis ZVM 614**


Waiblingen, 07.01.2008

Non-responsive content removed




EA11003EN-00890[4]

Metering unit 0928400708 serial no. 53 date of manufacture 69006



Bearing in the housing



Tappet housing



Tappet magnetic core



Bearing in the magnetic core



Piston





Metering unit housing



Piece of housing broken without impairment of function

EA11003EN-00891[0]

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.											
				Date	12/10/2008										
<b>Department:</b>	<b>Person responsible:</b>	<b>Telephone:</b>		Use	internal										
Non-responsive content removed					external	x									
To:	Non-responsive content removed														
For information:															
<b>Pump type:</b> CP4.1S_348_2x5,25_REC_3,3_1,95_MT4,2	<b>Customer:</b> VW	<b>Project:</b> R4 2.0 EU5	<b>Project / design pattern type</b> D / Series												
<b>Part number (TTNo.):</b> 445010507	<b>Date of manufacture:</b> 190508	<b>Serial number:</b> 0741	<b>Manufacturing plant - line</b> 5150 JhP (Jihlava plant) - 03												
<b>SAP-No.:</b> 30-101005-07	<b>Samos no.:</b> 715206.002	<b>Customer order no.:</b> 731223	<b>Engine/Vehicle number</b> 3VWC781K39M258026												
<b>Customer part number</b> 731223	<b>Endurance run type [customer]:</b> Vehicle endurance run	<b>Endurance run conditions:</b> Summer trip Mexico	<b>DSBFD no.:</b> 22769												
<b>Mileage</b> 13539 km	<b>Parts receipt at dept. DS-PC/EDI:</b> 10/2/2008	<b>Process no.</b> 2008-CP4_0776	<b>Confidentiality note</b> Confidential												
<b>VA / ETC no.:</b> DS-200437	<b>Durability test type [RB]:</b>	<b>Fuel:</b> US Field													
<b>Complaint:</b> Restart after vehicle stop not possible due to error indication in the instrument cluster, but no entry in the control unit. Metering unit dismantled to check drivetrain damage and reassembled.															
<b>1. Subject</b> CP4 customer returns diagnosis before endurance run end <b>with</b> complaint Testing conditions: Summer trip Mexico															
<b>2. Conclusion</b> <b>Function</b> - No function test due to possible drivetrain damage. <b>Components</b> - Drivetrain damage of category I (surfaces almost completely worn). - Particle marks and impressions on almost all of the components due to drivetrain damage. - Metering unit O-ring sheared over half the circumference of disassembly and reassembly of the metering unit on the vehicle. - Unusual deposits at the edge of the flange bearing bushing and in the two low-pressure-sided lubrication grooves of the high pressure piston. - Analysis of the deposit on the flange bearing bushing residues resulting from aging and reaction products of the fuel (see Appendix Report CR / ARA 2008-1206). <b>Result</b> - The analysis results of the reddish sticky deposits reveal the presence of proportions from aging fuel and components from reaction products of fuel components and thus an indication of changes to the fuel properties, which may have a worsening effect on the coefficients of friction of the drivetrain parts. - The damage pattern of the roller support with wear on the C coating in the main load areas (pressure profile) and the indications from the analysis of deposits support the failure hypothesis of an increased mixed friction of the roller in the roller support and as a result of slippage between the roller and cam (stiff roller). This led to the abrasive wear of drivetrain parts and thus failure of the pump. - The pump <b>has failed</b> the durability test.															
<b>3. Results of diagnosis (visual findings)</b> <b>3.1 Drive</b> No striking feature															
			Legend rating stages		{ OK uncritical Critical										
					<table border="1"> <tr> <td>x</td> <td></td> <td></td> </tr> <tr> <td></td> <td>x</td> <td></td> </tr> <tr> <td></td> <td></td> <td>x</td> </tr> </table>		x				x				x
x															
	x														
		x													
					<table border="1"> <tr> <td>x</td> <td></td> <td></td> </tr> </table>		x								
x															



EA11003EN-00891[1]













 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.		
				Date	12/10/2008	
<b>Department:</b>		<b>Person responsible:</b>		<b>Telephone:</b>		
Non-responsive content removed				Use		internal external <input checked="" type="checkbox"/>
To:	DS/CSP2-Fernandes DS-PC/EHC2-Kö, DS/SVW-Bucher, -/Niethammer					
For information:	DS-PC/EHC1-Mr, DS-PC/ED11-PB, DS-PC/EHC2-Gr, DS-PC/EHC1, -/EHC2, -Ak, -/EHP1, -/EHP2, -/EHP-Va, -/ECW W1 -Spr, -/W3-Ls, FeP/COS, -/2, CVIT/ECP21-Stasi, DS-PC/ENJ, -/ENP, -/EHP					
<b>3.2 Drivetrain</b> <div style="float: right;"> <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> </div> <p>Cam with abrasion over the entire running surface and a 90° rotation mark (see Figure 1 and Figure 2); roller with circumferential abrasion and a small and a large 90° wear mark (see Figure 3); US field roller support with C coating wear in the form of pressure profile (see Figure 4); roller support at the contact point of the high-pressure piston with many particle impressions (see Figure 5)</p>						
<b>3.3 High pressure</b> <div style="float: right;"> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> </div> <p>High-pressure piston base with many particle impressions (see Figure 6)          High-pressure piston skirt with many fine grooves or particle marks (see Figure 7)          Deposits in the low-pressure-sided lubrication grooves of the high-pressure piston (see Figure 8)</p>						
<b>3.4 Bearing</b> <div style="float: right;"> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> </div> <p>Radial bearing of the flange (see Figure 9) and housing (see Figure 10) with particle impressions          Bearing area of the camshaft flange-side (see Figure 11) and housing-side (see Figure 12) with particle impressions</p>						
<b>3.5 Shaft seal</b> <div style="float: right;"> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> </div> <p>No striking feature</p>						
<b>3.6 Holes</b> <div style="float: right;"> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> </div> <p>Tappet hole with many particle impressions and drafts (see Figure 13)</p>						
<b>3.7 Attached components (metering unit, overflow valve, counting point)</b> <div style="float: right;"> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> </div> <p>No striking feature</p>						
<b>3.8 O-rings</b> <div style="float: right;"> <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> </div> <p>Metering unit O-ring sheared to an extent of about 180° (see Figure 14)</p>						
<b>3.9 Other</b> <div style="float: right;"> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> </div> <p>Deposits on the front surface of the flange bearing bushing along the shaft seal (see Figure 15)</p>						
<b>3.10 Images of visual findings</b>						
<div style="display: flex; justify-content: space-around;">   </div>						

Fig. 1 Camshaft, BDC (bottom dead center) (wear)

Fig. 2 Camshaft, TDC (top dead center) (wear)











EA11003EN-00891[2]




 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.	[REDACTED]					
				Date	12/10/2008					
<b>Department:</b>		<b>Person responsible:</b>		<b>Telephone:</b>		Use <table border="1"> <tr> <td>internal</td> <td></td> </tr> <tr> <td>external</td> <td>x</td> </tr> </table>	internal		external	x
internal										
external	x									
Non-responsive content removed										
To: DS/CSP2-Fernandes DS-PC/EHC2-Kö, DS/SVW-Bucher, -/Niethammer										
For information: DS-PC/EHC1-Mr, DS-PC/ED11-PB, DS-PC/EHC2-Gr, DS-PC/EHC1, -/EHC2, -Ak, -/EHP1, -/EHP2, -/EHP-Va, -/ECW W1 -Spr, -/W3-Ls, FeP/COS, -/2, CVIT/ECP21-Stasi, DS-PC/ENJ, -/ENP, -/EHP										
										
										
										



EA11003EN-00891[3]

 <b>BOSCH</b>		 <b>CP4</b>		<b>CR pump CP4 - Diagnosis report</b>		Report no. <span style="background-color: black; color: black;">[REDACTED]</span>	
				Date 12/10/2008			
<b>Department:</b> Non-responsive content removed		<b>Person responsible:</b> Non-responsive content removed		<b>Telephone:</b> Non-responsive content removed		Use	
						internal <input type="checkbox"/> external <input checked="" type="checkbox"/>	
<b>To:</b> DS/CSP2-Fernandes DS-PC/EHC2-Kö, DS/SVW-Bucher, -/Niethammer							
<b>For information:</b> DS-PC/EHC1-Mr, DS-PC/ED11-PB, DS-PC/EHC2-Gr, DS-PC/EHC1, -/EHC2, -Ak, -/EHP1, -/EHP2, -/EHP-Va, -/ECW W1 -Spr, -/W3-Ls, FeP/COS, -/2, CVIT/ECP21-Stasi, DS-PC/ENJ, -/ENP, -/EHP							
							
							
							

EA11003EN-00891[4]

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no. <span style="background-color: black; color: black;">[REDACTED]</span>	
				Date 12/10/2008	
<b>Department:</b>		<b>Person responsible:</b>		<b>Telephone:</b>	
Non-responsive content removed				Use <input type="checkbox"/> internal <input checked="" type="checkbox"/> external	
To: DS/CSP2-Fernandes DS-PC/EHC2-Ko, DS/SVW-Bucher, -/Niethammer					
For information: DS-PC/EHC1-Mr, DS-PC/ED11-PB, DS-PC/EHC2-Gr, DS-PC/EHC1, -/EHC2, -Ak, -/EHP1, -/EHP2, -/EHP-Va, -/ECW W1 -Spr, -/W3-Ls, FeP/COS, -/2, CVIT/ECP21-Stasi, DS-PC/ENJ, -/ENP, -/EHP					
					
<b>Fig. 15 Flange, the edge of the bearing bush (deposits)</b>					
<b>4. Hydraulic function</b>					
				Delivery rate [l/h] of new part	Delivery rate [l/h] after testing
	n[rpm]	p_rail [bar]	I_MU [A]		
No functional testing due to the complaint.					
<b>5. Destiny of the parts</b>					
The pump is stored at RB until 03/2009 and then scrapped.					
<b>6. Attachments</b>					
CR/ARA 2008-1206					
Tested:	Non-responsive content removed	Phone	Non-responsive content removed	Date:	12/16/2008
Signature:				Signature:	Non-responsive content removed
Department:		Phone		Date:	12/17/2008
Signature:				Signature:	
Department:		Phone		Date:	12/17/2008
Signature:				Signature:	



EA11003EN-00891[5]



DIN EN ISO 9001: 2000

Version December 2000

This certificate is valid until 2008-12-06

Certificate registration no. 004778 QM

Frankfurt am Main 2005-12-07

**BOSCH**

**CR/ARA Corporate Sector Research and Advance  
Engineering Applied Research 1 - Analytics  
CR / ARA analysis report, analysis number:  
2008-1206**

dated 11.27.2008

Version 1

**Order:** 2008-CP4-0776 Deposit analysis  
of flange bearing bushing / VW  
R4 2.0l EU5 / failure vehicle  
testing Non-responsive content removed / pump  
#190508-0741

**Client:** Non-responsive content removed  
Receipt of samples: 11/3/2008

**Analysis  
coordinator:** Non-responsive content removed

**BOSCH****Analysis report**

Version / supplement 1



EA11003EN-00891[6]

	<b>Analysis no. 2008-1206</b>	<b>Author</b> [redacted]	<b>Date</b> 11/27/2008
--	-------------------------------	-----------------------------	---------------------------

**Client:** [redacted]  
**Site / dept.:** [redacted]  
**Case / carton:**  
**PSP** 30-101005-07  
**element:**  
**c.c.:** [redacted]

**Telephone:** [redacted]  
**Fax:** [redacted]  
**Receipt:** 11/3/2008

**Order:** 2008-CP4-0776 Deposit analysis of flange bearing bushing / VW R4 2.0l EU5 / failure vehicle testing Mexico / pump #190508-0741

**Procedure:** IR / UV / VIS (infrared/ultraviolet/visible) spectrometry, electron microscopy (scanning electron microscope-SEM), EDS / WDS  
**Employee:** [redacted]

**Question:**

Identification and origin of the deposit on the front surface of the flange bearing bushing of a CP4.

**Result:**

The deposit is mainly composed of defined soaps and small amounts of carbonyl compounds (possibly fuel aging products). The observed metal particles were probably entrained by the damage process.

The tin particles found in the deposit may have originated from the detachment of the residue from the bushing (galvanization of the wide band).

**Conclusion:**

The residues are reaction and aging products of the fuel used.

**Person in charge:** [redacted]  
**Tel.:** [redacted]

**Date:** 11/27/2008**Signature:** Signed by [redacted]

CR / ARA is certified according to DIN EN ISO 9001:2000 with conformity assessment according to ISO / TS 16949:2002; reg. no. 004 778 QM, valid until 12.06.2008.

© All rights reserved by Robert Bosch GmbH, including the case of patent applications. We reserve any right to use, such as right to copy and disclose.  
 2211RB14

<b>BOSCH</b> 	<b>Analysis report</b>	Version / supplement 1	[redacted]
--	------------------------	------------------------	------------

EA11003EN-00891[7]




	<b>Analysis no. 2008-1206</b>	Author [REDACTED]	Date 11/27/2008
--	-------------------------------	----------------------	--------------------

**Table of contents**

1. Samples and further information on the order .....	9
2. Detailed results of the methods used .....	10
2.1. Fourier Transform Infrared Spectrometry (FTIR) .....	10
2.2. Scanning Electron Microscopy (SEM) and Energy Dispersive Spectroscopy (EDS) .....	11
3. Appendix .....	12
3.1. Appendix for the Fourier Transform Infrared Spectrometry (FTIR) .....	12
3.2. Appendix to SEM-EDS .....	12



EA11003EN-00891[8]

<b>BOSCH</b>   <b>CR/ARA</b>	<b>Analysis report</b>	Version / supplement 1	
	<b>Analysis no. 2008-1206</b>	Author 	Date 11/27/2008

## 1. Samples and further information on the order

Common rail pump 2008-CP4-0776 with a reddish deposit on the front surface of the flange bearing bushing to the shaft seal.




VW R4 2.0l EU5, pump # 190508-0741. VW EU5 pump for diesel fuel EN590 validated.

Drivetrain failure of the pump (roller / cam due to wear) in summer trials in Mexico after 13,539 km.

Fuel used and the exact running times in Mexico and Germany are not known.

© All rights reserved by Robert Bosch GmbH, including the case of industrial property rights. We reserve any right to use, such as right to copy and disclose.

2211RB14

<b>BOSCH</b>   <b>CR/ARA</b>	<b>Analysis report</b>	Version / supplement 1	
	<b>Analysis no. 2008-1206</b>	Author 	Date 11/27/2008

## 2. Detailed results of the methods used

### 2.1. Fourier Transform Infrared Spectrometry (FTIR)

#### Objective:

Identification of the deposit composition on the flange bearing bushing of CP4.

#### Sample preparation:

The deposit was applied on a sample carrier (potassium bromide disk) and measured, then rinsed with methylene chloride on the sample holder and measured again.

#### Measurement procedure:

The measurements of the deposit was made on the IR (infrared) microscope Equinox-55-1 spectrometer (device SOP OA-G-08-001) from Bruker in transmission mode.

#### Analysis of the measurements:

The obtained IR (infrared) spectra were evaluated using computerized databases, own and commercially available spectral collections.

#### Measuring results:

Hydrocarbons with / and low content of esters and weaker acids adhere to the deposit; they could be isolated by treatment with dichloromethane.

According to the IR spectra, the dichloromethane-insoluble deposit is mainly composed of defined soaps as well as small amounts of carbonyl compounds (esters, weaker acids). The IR (infrared) spectra revealed no evidence of significant entrainment of inorganic components.




#### Assessment:

The deposit is mainly composed of defined soaps and small amounts of carbonyl compounds (possibly fuel aging products).

The fuel used is not known, therefore we cannot accurately classify the carbonyl compounds.

Non-responsive content removed

2211RB14

<b>BOSCH</b>   <b>CR/ARA</b>	<b>Analysis report</b>	Version / supplement 1	
	<b>Analysis no. 2008-1206</b>	Author 	Date 11/27/2008

## ***2.2. Scanning Electron Microscopy (SEM) and Energy Dispersive Spectroscopy (EDS)***

### **Objective:**

Analysis of the composition (elements) of the residue on the front surface of the flange bearing bushing.

### **Sample preparation:**

The residue was removed with a preparation needle and rinsed with petroleum ether.

### **Measurement points:**

The residue was analyzed directly on the preparation needle.

### **Measurement procedure:**

The analysis was carried out using SEM (Scanning Electron Microscopy) (1450 VP, Zeiss) and the coupled EDS (Energy Dispersive Spectroscopy) system (INCA Energy, Oxford Instruments Co.). An accelerating voltage of 20.0 KV was used.

### **Measuring results:**

The preparation needle is made of nickel-plated steel. The first spectrum shows the needle material.




The particles next to the residue consist of iron (Fe), with minor amounts of chromium (Cr), molybdenum (Mo), tungsten (W) and manganese (Mn). In addition, particles of tin (Sn) occur. The residue itself consists mainly of carbon (C) with small amounts of nitrogen (N) and oxygen (O). Within the residue there are tiny particles of iron (Fe) and oxygen (O).

### **Assessment:**

Besides containing various metal particles, the residue is an organic residue (fuel conversion?) with fine iron particles. These very fine iron particles which rapidly oxidize (rust) would be responsible for the (reddish-brown) color.

Non-responsive content removed




<b>BOSCH</b>   <b>CR/ARA</b>	<b>Analysis report</b>	Version / supplement 1	
	<b>Analysis no. 2008-1206</b>	Author 	Date 11/27/2008

### 3. Appendix

#### 3.1. Appendix for the Fourier Transform Infrared Spectrometry (FTIR)

FTIR (Fourier Transform Infrared Spectrometry) spectrum

11/6/2008, 7:57:30 AM

CR CP4 with reddish-brown, CH<sub>2</sub>Cl<sub>2</sub>-insoluble deposit on the front surface of the flange bushing to the shaft seal

2008-1206-1.0

CR CP4 with reddish-brown, CH<sub>2</sub>Cl<sub>2</sub>-insoluble deposit on the front surface of the flange bushing to the shaft seal

2008-1206-1.3

CR CP4 with reddish-brown, CH<sub>2</sub>Cl<sub>2</sub>-insoluble deposit on the front surface of the flange bushing to the shaft seal

2008-1206-1.4

Measuring method: Equinox-I-Mikroskop-Transmission-MCT.XPM

Person responsible: 

ARA no.: 2008-1206-1.0

#### 3.2. Appendix to SEM-EDS

A photo report (Bilder\_2008-1206.pdf) and an EDS report (EDS\_2008-1206.pdf) were created. These will be added to the analysis report separately.

EA11003EN-00891[12]

Photo report CR / ARA


11.10.2008




2.008-1206  
CR\_ARA\_M\_08\_1759  
Overview of flange bearing bushing with detached residues



2.008-1206  
CR\_ARA\_M\_08\_1760  
Residue on preparation needle for analysis







2.008-1206  
CR\_ARA\_VP\_08\_2195  
Residue on preparation needle for analysis



2.008-1206  
CR\_ARA\_VP\_08\_2196  
Residue on preparation needle for analysis

EA11003EN-00891[13]

Photo report CR / ARA EDS report	2.008-1206	 <b>BOSCH</b>	 <p>Spektrum 2</p>
Project: 2.008-1206	Owner: [REDACTED]	Area: Work area 1	<p>Scale range 1091 cts</p> <p>Needle !!</p> <p>Spektrum 2</p>
Sample: Residue on preparation needle	Type: Specification	ID:	


	
<p>Spektrum 2</p> <p>Spektrum 3</p> <p>Spektrum 4</p> <p>Needle !!</p>	<p>Scale range 1091 cts</p> <p>Spektrum 3</p> <p>Spektrum 4</p>
<p>Magnification: 250 X</p> <p>Acceleration voltages (kV): 20.00</p> <p>Process time: 6</p>	



EA11003EN-0089-1[14]

Photo  
2008-1206  
EDS  
report

2008-1206





Project: 2008-1206  
Owner: [REDACTED]  
Area: Work area 2

Scale range 2488 cts

Spektrum 1

Spektrum 2

Sample: Residue on preparation needle  
Type: Specification  
ID:








Spektrum 1  
Spektrum 2  
Spektrum 3  
Spektrum 4


Scale range 2488 cts  
Spektrum 3  
Spektrum 4

Magnification: 500 X  
Acceleration voltages (kV): 15.00  
Process time: 6





EA11003EN-00891[15]

<p>Photo report CR / ARA EDS report</p>	<p>2.008-1206</p>		<div data-bbox="671 81 1201 448"> <p>Spektrum 1</p>  <p>Skalenbereich 1767 cts</p> </div> <div data-bbox="671 448 1201 814"> <p>Spektrum 2</p>  <p>Skalenbereich 1767 cts</p> </div> <div data-bbox="671 814 1201 1181"> <p>Spektrum 3</p>  <p>Skalenbereich 1767 cts</p> </div>
<p>Project: 2.008-1206 Owner: <span style="background-color: black; color: black;">XXXXXXXXXX</span> Area: Work area 3</p>			<p>Scale range 1767 cts Spectrum 1 Spectrum 2</p>
<p>Sample: Residue on preparation needle Type: Specification ID:</p>			<p>Spectrum 3</p>




<p>Spectrum 1 Spectrum 2 Spectrum 3</p>
<p>Magnification: 2299 X Acceleration voltages (kV): 15.00 Process time: 6</p>

		<b>CR pump CP4 - Diagnosis report</b>		Report no. Date	12/15/2008
<b>Department:</b> Non-responsive content removed	<b>Person responsible:</b> Non-responsive content removed	<b>Telephone:</b> Non-responsive content removed	Use	internal external	x
<b>To:</b> Non-responsive content removed					
<b>For information:</b> Non-responsive content removed					
<b>Pump type:</b> CP4.1S_348_2x5,25_REC_3,3_1,95_MT4,2	<b>Customer:</b> VW	<b>Project:</b> R4 2.0 EU5	<b>Project / design pattern type</b> Series / Series		
<b>Part number (TTNo.):</b> 0445B21070	<b>Date of manufacture:</b> 150408	<b>Serial number:</b> 0681	<b>Manufacturing plant - line</b> 0110 FeP – 04		
<b>SAP-No.:</b> 30-101005-02	<b>Samos no.:</b> 718361.002	<b>Customer order no.:</b> 731223	<b>Engine/Vehicle number</b> CBA 655 000260		
<b>Customer part number</b> 731223	<b>Endurance run type [customer]:</b> Vehicle endurance run	<b>Endurance run conditions:</b> VW-Passat PQ46	<b>DSBFD no.:</b> 23034		
<b>VA / ETC no.:</b> DS-202949	<b>Actual mileage</b> 100000 km	<b>Fuel:</b> EN590	<b>Confidentiality note</b> Confidential		
<b>1. Subject</b> CP4 customer return Verification modification package 3 (design package) Diagnosis after endurance run end without complaint					
<b>2. Conclusion</b> <b>Function</b> - Delivery rates after endurance run without significant fuel-quantity drift in comparison with the new state. <b>Components</b> - Wear due to cavitation erosion in the contact area of the high-pressure piston to the roller support occurs only on the roller support back and slightly more pronounced than that of comparable endurance runs. - The groove in the C coating of the roller support was probably caused by a particle - Wear of the remaining components is low and without significant striking features. <b>Change package 3</b> Roller support with C2.1 coating - Features C2.1 coating is not visible over the TTNR of the roller support (6007 = series) and was detected by EDX <i>Roller: C2 tip coating, a second supplier, short design</i> - Front surface without the characteristic groove (see Figure 4 and Figure 5 in Appendix 1). - Length of roller 24.58 mm <i>Camshaft: Omission of shot blasting</i> - Missing shot blasting impressions visible (see Figure 6 and Figure 7 in Appendix 1). <i>spring seat: Omission of anti-friction coating</i> - Front surface of the spring plate without anti-friction paint (see Figure 8 and Figure 9 in Appendix 1). <i>Cylinder head: Non-return valve hemispherical head with red. Play</i> - Hemispherical head with characteristic groove on the surface (see Figure 10 in Appendix 1). <i>Opening pressure lowering non-return valve:</i> - Spring seat with characteristic groove on the surface (see Figure 11 in Appendix 1), opening pressure after the endurance run 1.18 bar. <i>Bearing bushing: Second supplier</i> - Identification recognizable via tappet latching (see Figure 14 in Appendix 1). <i>Metering unit: NC bearing</i> - see metering unit report ZVM 689 (picture on page 3 "bearing in the housing") <b>Result</b> - The components with modification package 3 have a wear rating green. - The pump has passed the endurance run.					



 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.														
				Date	12/15/2008													
Department:	Person responsible:	Telephone:	Use	internal														
Non-responsive content removed				external		x												
<b>3. Results of diagnosis (visual findings)</b>				Legend rating stages: <table border="1"> <tr> <td>OK</td> <td>x</td> <td></td> <td></td> </tr> <tr> <td>uncritical</td> <td></td> <td>x</td> <td></td> </tr> <tr> <td>Critical</td> <td></td> <td></td> <td>x</td> </tr> </table>			OK	x			uncritical		x		Critical			x
OK	x																	
uncritical		x																
Critical			x															
<b>3.1 Drive</b> No striking feature				<table border="1"> <tr> <td>x</td> <td></td> <td></td> </tr> </table>			x											
x																		
<b>3.2 Drivetrain</b> Cavitation erosion on the roller support back on the piston contact point (see Figure 1), but only very low cavitation erosion on the high-pressure piston base (see Figure 2)				<table border="1"> <tr> <td></td> <td>x</td> <td></td> </tr> </table>				x										
	x																	
<b>3.3 High pressure</b> No striking feature				<table border="1"> <tr> <td>x</td> <td></td> <td></td> </tr> </table>			x											
x																		
<b>3.4 Bearing</b> No striking feature				<table border="1"> <tr> <td>x</td> <td></td> <td></td> </tr> </table>			x											
x																		
<b>3.5 Shaft seal</b> No striking feature				<table border="1"> <tr> <td>x</td> <td></td> <td></td> </tr> </table>			x											
x																		
<b>3.6 Holes</b> No striking feature				<table border="1"> <tr> <td>x</td> <td></td> <td></td> </tr> </table>			x											
x																		
<b>3.7 Attached components (Metering Unit, Overflow Valve, Counting Point)</b> No striking feature				<table border="1"> <tr> <td>x</td> <td></td> <td></td> </tr> </table>			x											
x																		
<b>3.8 O-rings</b> No striking feature				<table border="1"> <tr> <td>x</td> <td></td> <td></td> </tr> </table>			x											
x																		
<b>3.9 Other</b> No striking feature				<table border="1"> <tr> <td>x</td> <td></td> <td></td> </tr> </table>			x											
x																		
<b>3.10 Images of visual findings</b>																		
																		
Fig. 1 Roller support, HP piston contact (cavitation)				Fig. 2 HP piston, piston base (very low cavitation)														

EA11003EN-00892[2]

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.			
				Date		12/15/2008	
Department:	Person responsible:		Telephone:		Use		internal
Non-responsive content removed						external	
						x	

**4. Hydraulic function**

	n[rpm]	p_rail [bar]	I_MU [A]	Delivery rate [l/h] of new part 4/16/2008	Delivery rate [l/h] after testing 11/10/2008
Starting point	200	200	0.4	4	4.2
1000 rpm, p_rated	1000	1800	0.4	17.1	17.4
n_max p, 500bar	3375	500	0.4	64.3	66.3

x		
x		
x		

TCD (technical customer documentation) testing point LG (1,000 rpm, p\_rated ≥ 15.5 or 15.2 l/h after running time) is met.

No significant fuel-quantity drift compared to delivery measurement.

**5. Destiny of the parts**

The pump is stored at RB until 12/2010 and then scrapped.

**6. Attachments**

Appendix 1: Images of visual findings

Appendix 2: Metering unit diagnosis report ZMV 688

Tested:	Non-responsive content removed	Phone:	Non-responsive content removed	Date:	12/16/2008	Signature:	Non-responsive content removed
Department:		Phone:		Date:	2/17/2008	Signature:	
Department:		Phone:		Date:	2/17/2008	Signature:	



Fig. 1 Type plate




Fig. 2 Roller support running surface




Fig. 3 Roller support lateral surface




Fig. 4 Roller front surface, flange-side



Fig. 5 Roller front surface, housing-side




Fig. 6 Camshaft running surface BDC (bottom dead center)



**2008-CP4\_0824 Appendix 1: Images of visual findings of modification package 3**

Page 2 of 3



**Fig. 7 Camshaft running surface TDC (top dead center)**



**Fig. 8 Spring plate, spring-sided**




**Fig. 9 Spring plate, tappet-sided**




**Fig. 10 Non-return valve lateral surface (guidance)**



**Fig. 11 Non-return valve spring and non-return valve spring seat**



**Fig. 12 Non-return valve hemispherical head sealing surface**





**Fig. 13** Cylinder head non-return valve sealing surface




**Fig. 14** Flange bearing bushing



**Fig. 15** Housing bearing bushing

 <b>BOSCH</b> 	Diagnosis ZVM 688	Waiblingen, 12.01.2008
<b>Metering unit</b> 0928400706 serial no. 10469 date of manufacture 88404		

Customer VWTo 

Cc

**Pump** **Serial No.** **Date of manufacture**  
**Endurance run diagnosis no.** 2008\_CP4-  
 0824  
**SAP**

**1. Description****Metering unit complaint:** Testing release**System design****Endurance run type****Running time****Remark:**

Fuel:

**2. Diagnosis**

- **Visual findings (external):**

Visual findings externally good. Housing undamaged. Hydraulics and filter clean, undamaged.

- **Function:**

The characteristic curve of the displacement / current measurement is OK.

During the delivery rate / current measurement, all values are within the tolerances.

- **Wear:**

There are no or only slight running marks on the components.

- **Other:**

**3. Result*****[X] Passed******[ ] Conditionally passed******[ ] Failed***


The metering unit is functionally OK, delivery rate and displacement measurements yielded positive results. Wear of the components is low.

**4. Corrective actions**

No error.

**5. Other tests (e.g. material analysis. process analysis)**


No further tests are performed.

**6. Destiny of the parts**Metering unit remains with 

Person responsible:		
Approval:		

Date/Signature




**BOSCH**
**Metering unit 0928400706 serial no. 10469 date of manufacture 88404**
**Function:**


Testing point [A]	0.80	1.00	1.20	1.40	1.80
Diagnosis values [l/h]	136.37	82.95	46.04	20.44	0.33

**Wear:**


<b>External</b>	<b>1</b>	<b>2</b>	<b>3</b>	<b>4</b>	<b>5</b>	<b>6</b>	<b>7</b>	<b>8</b>	<b>9</b>	<b>10</b>
contamination:		x								
Damage:		x								
Filter contamination		x								
Filter damage		x								
O-ring outside		x								
Seal		x								




<b>internal</b>	<b>1</b>	<b>2</b>	<b>3</b>	<b>4</b>	<b>5</b>	<b>6</b>	<b>7</b>	<b>8</b>	<b>9</b>	<b>10</b>
Tappet housing:		x								
Bearing housing:		x								
Tappet magnetic core:		x								
Bearing magnetic core:		x								
O-ring inside:		x								
Valve piston:		x								

	<b>BOSCH</b> CP4	Diagnosis ZVM 688	Waiblingen, 11.27.2008
<b>Metering unit</b> 0928400706 serial no. 10469 date of manufacture 88404			

Bearing in the housing



Tappet housing



Tappet magnetic core




Bearing in the magnetic core








Piston



		<b>CR pump CP4 - Diagnosis report</b>		Report no. Date	12/15/2008
<b>Department:</b> Non-responsive content removed	<b>Person responsible:</b> Non-responsive content removed	<b>Telephone:</b> Non-responsive content removed	Use	internal external	x
<b>To:</b> For information:	Non-responsive content removed				
<b>Pump type:</b> CP4.1S_348_2x5,25_REC_3,3_1,95_MT4,2	<b>Customer:</b> VW	<b>Project:</b> R4 2.0 EU5	<b>Project / design pattern type</b> C1 / C1		
<b>Part number (TTNo.):</b> 0445B21070	<b>Date of manufacture:</b> 150408	<b>Serial number:</b> 0679	<b>Manufacturing plant - line</b> 0110 FeP - 04		
<b>SAP-No.:</b> 30-101005-02	<b>Samos no.:</b> 718361.001	<b>Customer order no.:</b> 731223	<b>Engine/Vehicle number</b> CBA 655 000268		
<b>Customer part number</b> 731223	<b>Endurance run type [customer]:</b> Vehicle endurance run	<b>Endurance run conditions:</b> VW-Passat PQ46	<b>DSBFD no.:</b> 23033		
<b>VA / ETC no.:</b> DS-202948	<b>Actual mileage</b> 10/17/2007	<b>Fuel:</b> EN590	<b>Confidentiality note</b> Confidential		
<b>1. Subject</b> CP4 customer return Verification modification package 3 (design package) Diagnosis after endurance run end without complaint					
<b>2. Conclusion</b> <b>Function</b> - Delivery rates after endurance run without significant fuel-quantity drift in comparison with the new state. <b>Components</b> - Wear due to cavitation erosion in the contact area of the high-pressure piston to the roller support occurs only on the roller support back and slightly more pronounced than that of comparable endurance runs. - The groove in the C coating of the roller support was probably caused by a particle - The metering unit diagnosis did not show any significant striking features (see Appendix CVM 689). - Wear of the remaining components is low and without significant striking features. <b>Change package 3</b> Roller support with C2.1 coating - Features C2.1 coating is not visible over the TTNR of the roller support (6007 = series) and was detected by EDX <i>Roller: C2 tip coating, a second supplier, short design</i> - Front surface without the characteristic groove (see Figure 4 and Figure 5 in Appendix 1). - Length of roller 24.59 mm <i>Camshaft: Omission of shot blasting</i> - Missing shot blasting impressions visible (see Figure 6 and Figure 7 in Appendix 1). <i>spring seat: Omission of anti-friction coating</i> - Front surface of the spring plate without anti-friction paint (see Figure 8 and Figure 9 in Appendix 1). <i>Cylinder head: Non-return valve hemispherical head with red. Play</i> - Hemispherical head with characteristic groove on the surface (see Figure 10 in Appendix 1). <i>Opening pressure lowering non-return valve:</i> - Spring seat with characteristic groove on the surface (see Figure 11 in Appendix 1), opening pressure after the endurance run 1.19 bar. <i>Bearing bushing: Second supplier</i> - Identification recognizable via tappet latching (see Figure 14 in Appendix 1). <i>Metering unit: NC bearing</i> - see metering unit report ZVM 689 (picture on page 3 "bearing in the housing") <b>Result</b> - The components with modification package 3 have a wear rating green. - The pump has passed the endurance run.					



 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.											
				Date	12/15/2008										
Department:	Person responsible:	Telephone:	Use	internal											
Non-responsive content removed				external		x									
<b>3. Results of diagnosis (visual findings)</b>				<div style="display: flex; align-items: center;"> <div style="margin-right: 10px;">             Legend rating stages             <div style="display: flex; flex-direction: column; align-items: center;"> <div>OK</div> <div>uncritical</div> <div>Critical</div> </div> </div> <table border="1"> <tr> <td style="background-color: green;">x</td> <td></td> <td></td> </tr> <tr> <td></td> <td style="background-color: yellow;">x</td> <td></td> </tr> <tr> <td></td> <td></td> <td style="background-color: red;">x</td> </tr> </table> </div>			x				x				x
x															
	x														
		x													
<b>3.1 Drive</b> No striking feature				<table border="1"> <tr> <td style="background-color: green;">x</td> <td></td> <td></td> </tr> </table>			x								
x															
<b>3.2 Drivetrain</b> Cavitation erosion on the roller support back on the piston contact point (see Figure 1), but only very low cavitation erosion on the high-pressure piston base (see Figure 2) Groove in the C coating on the roller support, roller hole (see Figure 3)				<table border="1"> <tr> <td></td> <td style="background-color: yellow;">x</td> <td></td> </tr> </table>				x							
	x														
<b>3.3 High pressure</b> No striking feature				<table border="1"> <tr> <td style="background-color: green;">x</td> <td></td> <td></td> </tr> </table>			x								
x															
<b>3.4 Bearing</b> No striking feature				<table border="1"> <tr> <td style="background-color: green;">x</td> <td></td> <td></td> </tr> </table>			x								
x															
<b>3.5 Shaft seal</b> No striking feature				<table border="1"> <tr> <td style="background-color: green;">x</td> <td></td> <td></td> </tr> </table>			x								
x															
<b>3.6 Holes</b> No striking feature				<table border="1"> <tr> <td style="background-color: green;">x</td> <td></td> <td></td> </tr> </table>			x								
x															
<b>3.7 Attached components (Metering Unit, Overflow Valve, Counting Point)</b> No striking feature				<table border="1"> <tr> <td style="background-color: green;">x</td> <td></td> <td></td> </tr> </table>			x								
x															
<b>3.8 O-rings</b> No striking feature				<table border="1"> <tr> <td style="background-color: green;">x</td> <td></td> <td></td> </tr> </table>			x								
x															
<b>3.9 Other</b> No striking feature				<table border="1"> <tr> <td style="background-color: green;">x</td> <td></td> <td></td> </tr> </table>			x								
x															
<b>3.10 Images of visual findings</b>															
<div style="display: flex; justify-content: space-around;"> <div style="text-align: center;">  <p>Fig. 1 Roller support, HP piston contact (cavitation)</p> </div> <div style="text-align: center;">  <p>Fig. 2 HP piston, piston base (very low cavitation)</p> </div> </div>															

<b>BOSCH</b>		CR pump CP4 - Diagnosis report			Report no.		[REDACTED]																																						
					Date																																								
							03.272008																																						
Department:		Person responsible:		Telephone:		Use		internal																																					
Non-responsive content removed								external		x																																			
																																													
<p>Fig. 3 Roller support, roller hole (particle mark)</p>																																													
4. Hydraulic function																																													
<table border="1" style="width:100%; border-collapse: collapse; text-align: center;"> <thead> <tr> <th></th> <th>n[rpm]</th> <th>p_rail [bar]</th> <th>I_MU [A]</th> <th>Delivery rate [l/h] of new part 4/16/2008</th> <th>Delivery rate [l/h] after testing 11/10/2008</th> <th></th> <th></th> <th></th> </tr> </thead> <tbody> <tr> <td>Starting point</td> <td>200</td> <td>200</td> <td>0.4</td> <td>3.9</td> <td>4.2</td> <td style="background-color: #90EE90;">x</td> <td></td> <td></td> </tr> <tr> <td>1000 rpm, p Rated</td> <td>1000</td> <td>1800</td> <td>0.4</td> <td>16.8</td> <td>17</td> <td style="background-color: #90EE90;">x</td> <td></td> <td></td> </tr> <tr> <td>n_max_p, 500bar</td> <td>3375</td> <td>500</td> <td>0.4</td> <td>65.9</td> <td>65.6</td> <td style="background-color: #90EE90;">x</td> <td></td> <td></td> </tr> </tbody> </table>											n[rpm]	p_rail [bar]	I_MU [A]	Delivery rate [l/h] of new part 4/16/2008	Delivery rate [l/h] after testing 11/10/2008				Starting point	200	200	0.4	3.9	4.2	x			1000 rpm, p Rated	1000	1800	0.4	16.8	17	x			n_max_p, 500bar	3375	500	0.4	65.9	65.6	x		
	n[rpm]	p_rail [bar]	I_MU [A]	Delivery rate [l/h] of new part 4/16/2008	Delivery rate [l/h] after testing 11/10/2008																																								
Starting point	200	200	0.4	3.9	4.2	x																																							
1000 rpm, p Rated	1000	1800	0.4	16.8	17	x																																							
n_max_p, 500bar	3375	500	0.4	65.9	65.6	x																																							
<p>TCD (technical customer documentation) testing point LG (1,000 rpm, p<sub>rated</sub> ≥ 15.5 or 15.2 l/h after running time) is met.</p> <p>No significant fuel-quantity drift compared to delivery measurement.</p>																																													
5. Destiny of the parts																																													
<p>The pump is stored at RB until 12/2010 and then scrapped.</p>																																													
6. Attachments																																													
<p>Appendix 1: Images of visual findings</p> <p>Appendix 2: Metering unit diagnosis report ZMV 689</p>																																													
Tested:		Non-responsive content removed		Phone:		Non-responsive content removed		Date:																																					
								12/16/2008																																					
Signature:								Non-responsive content removed																																					
Department:				Phone:				Date:																																					
								2/17/2008																																					
Signature:								Non-responsive content removed																																					
Department:				Phone:				Date:																																					
								2/17/2008																																					
Signature:								Non-responsive content removed																																					

**2008-CP4\_0823 Appendix 1: Images of visual findings of modification package 3**

Page 1 of 3



Fig. 1 Type plate




Fig. 2 Roller support running surface



Fig. 3 Roller support lateral surface




Fig. 4 Roller front surface, flange-side



Fig. 5 Roller front surface, housing-side




Fig. 6 Camshaft running surface BDC (bottom dead center)





**Fig. 7 Camshaft running surface TDC (top dead center)**




**Fig. 8 Spring plate, tappet-sided**




**Fig. 9 Spring plate, spring-sided**




**Fig. 10 Non-return valve lateral surface (guidance)**




**Fig. 11 Non-return valve spring and non-return valve spring seat**



**Fig. 12 Non-return valve hemispherical head sealing surface**



**Fig. 13** Cylinder head non-return valve sealing surface




**Fig. 14** Flange bearing bushing



**Fig. 15** Housing bearing bushing

EA11003EN-00893[6]

 <b>BOSCH</b> CP4	Diagnosis ZVM 689	12.01.2008
<b>Metering unit</b> 0928400706 serial no. 10469 date of manufacture 88404		

**Customer** VW**To** Non-responsive content removed**Cc**

**Pump**                                      **Serial No. Date of manufacture**  
**Endurance run diagnosis no.** 2008\_CP4-  
 0823  
**SAP**

**1. Description****Metering unit complaint:** Testing release**System design****Endurance run type****Running time****Remark:**

Fuel:

**2. Diagnosis**

- **Visual findings (external):**

Visual findings externally good. Housing undamaged. Hydraulics and filter clean, undamaged.

- **Function:**

The characteristic curve of the displacement / current measurement is OK.

Characteristic curve in the upper delivery rate range slightly above the upper tolerance limit

- **Wear:**

There are no or only slight running marks on the components.

- **Other:**

**3. Result****[X] Passed****[ ] Conditionally passed****[ ] Failed**

The metering unit is functionally OK, delivery rate and displacement measurements yielded positive results. Wear of the components is low.

**4. Corrective actions**

No error.

**5. Other tests (e.g. material analysis. process analysis)**

No further tests are performed.



**6. Destiny of the parts**


Metering unit remains with

Person responsible:	
Approval: 2764	Non-responsive content removed

Date/Signature




	<b>BOSCH</b> 	Diagnosis ZVM 689	11.27.2008
<b>Metering unit 0928400706 serial no. 10469 date of manufacture 88404</b>			

**Function:**



Testing point [A]	0.80	1.00	1.20	1.40	1.80
Diagnosis values [l/h]	137.56	84.91	47.49	21.93	0.23

**Wear:**


<b>External</b>	<b>1</b>	<b>2</b>	<b>3</b>	<b>4</b>	<b>5</b>	<b>6</b>	<b>7</b>	<b>8</b>	<b>9</b>	<b>10</b>
contamination:		x								
Damage:		x								
Filter contamination		x								
Filter damage		x								
Filter damage		x								
Seal		x								



<b>internal</b>	<b>1</b>	<b>2</b>	<b>3</b>	<b>4</b>	<b>5</b>	<b>6</b>	<b>7</b>	<b>8</b>	<b>9</b>	<b>10</b>
Tappet housing:		x								
Bearing housing:		x								
Tappet magnetic core:		x								
Bearing magnetic core:		x								
O-ring inside:		x								
Valve piston:		x								

	<b>BOSCH</b> CP4	Diagnosis ZVM 689	 11.27.2008
<b>Metering unit</b> 0928400706 serial no. 10469 date of manufacture 88404			


Bearing in the housing




Tappet housing



Tappet magnetic core





Bearing in the magnetic core



Piston



EA11003EN-00894[0]

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.	
				Date	6/23/2008
Department:	Person responsible:	Telephone:	Use	internal	
Non-responsive content removed				external	x
To:	Non-responsive content removed				
For information:					
<b>Pump type:</b> CP4.1S_348_2x5,25_REC_3,3_1,95_MT4,2	<b>Customer:</b> VW	<b>Project:</b> R4 2.0 EU5	<b>Project / design pattern type</b> D / Series		
<b>Part number (TTNo.):</b> 0445B21057	<b>Date of manufacture:</b> 050607	<b>Serial number:</b> 0355	<b>Manufacturing plant - line</b> 0110 FeP (Feuerbach plant)		
<b>SAP-No.:</b> 30-101008-01	<b>Samos no.:</b> 594599,001	<b>Customer order no.:</b> 03L 130 755	<b>Engine/Vehicle number</b> CAH0000092		
<b>Customer part number</b> 03L 130 755	<b>Endurance run type [customer]:</b> Vehicle endurance run	<b>Endurance run conditions:</b> not known	<b>DSBFD no.:</b> 20851		
<b>Mileage</b> 27655 km	<b>Parts receipt at dept. DS-PC/EDI:</b> 4/3/2008	<b>Process no.</b> 2008-CP4_0289	<b>Confidentiality note</b> Confidential		
<b>VA / ETC no.:</b> DS-180763	<b>Durability test type [RB]:</b>				

**1. Subject**

CP4 customer return  
Diagnosis of endurance run end without complaint

**2. Conclusion****Function**

- Delivery rates after endurance run without significant fuel-quantity drift in comparison with the new state.










**Components**

- Wear of the components is low and without significant striking features.

**Result**

The pump has **passed** the test.

**3. Results of diagnosis (visual findings)**

Legend rating stages	OK			
	uncritical			
	Critical			

**3.1 Drive**

No striking feature

		
---	---	---

**3.2 Drivetrain**

No striking feature

		
---	---	---

**3.3 High pressure**

No striking feature

		
---	---	---

**3.4 Bearing**

No striking feature

		
---	---	---

**3.5 Shaft seal**

No striking feature

		
---	---	---

**3.6 Holes**

No striking feature

		
---	---	---

**3.7 Attached components (Metering Unit, Overflow Valve, Counting Point)**

No striking feature

		
---	---	---



**3.8 O-rings**

No striking feature



		
---	---	---





EA11003EN-00894[1]

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.		[REDACTED]	
				Date		6/23/2008	
Department:	Person responsible:	Telephone:		Use	internal		
Non-responsive content removed					external		x
<b>3.9 Other</b> <div style="float: right;"> <input checked="" type="checkbox"/> </div>							
No striking feature							
<b>4. Hydraulic function</b>							
				Delivery rate [l/h] of new part	Delivery rate [l/h] after testing		
	n[rpm]	p_rail [bar]	I_MU [A]	6/5/2007	4/16/2008		
Starting point	200	200	0.4	66.7	66.6	<input checked="" type="checkbox"/>	
1000 rpm, p_rated	1000	1800	0.4	17.7	17.6	<input checked="" type="checkbox"/>	
n_max_p, 500bar	3375	500	0.4	3.8	4.3	<input checked="" type="checkbox"/>	
TCD (technical customer documentation) testing point LG (1,000 rpm, p_rated ≥ 15.5 or 15.2 l/h after running time) is met.							
No significant fuel-quantity drift compared to delivery measurement.							
<b>5. Destiny of the parts</b>							
The pump is stored at RB until 09/2008 and then scrapped.							
<b>6. Attachments</b>							
None							
Tested:	Non-responsive content removed	Telephone:	Non-responsive content removed	Date:	6/27/2008	Signature:	Non-responsive content removed
Department		Telephone:		Date:	6/30/2008	Signature:	

EA11003EN-00895[0]

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.														
				Date	6/23/2008													
Department:		Person responsible:	Telephone:	Use	internal													
Non-responsive content removed					external	X												
To:	Non-responsive content removed																	
Cylinder head:																		
Pump type: CP4.1S_348_2x5,25_REC_3,3_1,95_MT4,2		Customer: VW	Project: R4 2.0 EU5	Project / design pattern type D / Series														
Part number (TTNo.): 445010507		Date of manufacture: 190707	Serial number: 0499	Manufacturing plant - line 0110 FeP (Feuerbach plant)														
SAP-No.: 30-101008-01		Samos no.: 594603,001	Customer order no.: 03L 130 755	Engine/Vehicle number CAH0000109														
Customer part number 03L 130 755		Endurance run type [customer]: Engine endurance run	Endurance run conditions: not known	DSBFD no.: 20845														
Mileage 183 h		Parts receipt at dept. DS-PC/EDI: 4/3/2008	Process no. 2008-CP4_0291	Confidentiality note <b>Confidential</b>														
VA / ETC no.: DS-180766		Durability test type [RB]:	Fuel: EN590															
<b>1. Subject</b> CP4 customer returns with complaint Diagnosis of endurance run end without complaint Special feature: Omission of anti-friction coating on spring plate																		
<b>2. Conclusion</b> <b>Function</b> - Delivery rates after endurance run without significant fuel-quantity drift in comparison with the new state. <b>Components</b> - Wear of the components is low and without significant striking features. <b>Result</b> - No effect due to the omission of the anti-friction paint on the spring plate visible, The pump has passed the <b>endurance run</b> .																		
<b>3. Results of diagnosis (visual findings)</b> <div style="float: right; text-align: right;">         Legend rating stages {         <table border="1" style="display: inline-table; vertical-align: middle;"> <tr> <td>OK</td> <td>X</td> <td></td> <td></td> </tr> <tr> <td>Uncritical</td> <td></td> <td>X</td> <td></td> </tr> <tr> <td>Critical</td> <td></td> <td></td> <td>X</td> </tr> </table> </div>							OK	X			Uncritical		X		Critical			X
OK	X																	
Uncritical		X																
Critical			X															
<b>3.1 Drive</b> No striking feature				<table border="1"> <tr><td>X</td><td></td><td></td></tr> <tr><td></td><td></td><td></td></tr> </table>			X											
X																		
<b>3.2 Drivetrain</b> No striking feature				<table border="1"> <tr><td>X</td><td></td><td></td></tr> <tr><td></td><td></td><td></td></tr> </table>			X											
X																		
<b>3.3 High pressure</b> No striking feature				<table border="1"> <tr><td>X</td><td></td><td></td></tr> <tr><td></td><td></td><td></td></tr> </table>			X											
X																		
<b>3.4 Bearing</b> No striking feature				<table border="1"> <tr><td>X</td><td></td><td></td></tr> <tr><td></td><td></td><td></td></tr> </table>			X											
X																		
<b>3.5 Shaft seal</b> No striking feature				<table border="1"> <tr><td>X</td><td></td><td></td></tr> <tr><td></td><td></td><td></td></tr> </table>			X											
X																		
<b>3.6 Holes</b> No striking feature				<table border="1"> <tr><td>X</td><td></td><td></td></tr> <tr><td></td><td></td><td></td></tr> </table>			X											
X																		
<b>3.7 Attached components (Metering Unit, Overflow Valve, Counting Point)</b> No striking feature				<table border="1"> <tr><td>X</td><td></td><td></td></tr> <tr><td></td><td></td><td></td></tr> </table>			X											
X																		

EA11003EN-00895[1]

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no. <span style="background-color: black; color: black;">[REDACTED]</span>							
Department: <span style="background-color: black; color: black;">Non-responsive content removed</span>		Person responsible: <span style="background-color: black; color: black;">[REDACTED]</span>		Date: 6/23/2008							
Telephone: <span style="background-color: black; color: black;">[REDACTED]</span>		Use:		<table border="1"> <tr> <td>internal</td> <td><input type="checkbox"/></td> <td><input type="checkbox"/></td> </tr> <tr> <td>external</td> <td><input checked="" type="checkbox"/></td> <td><input type="checkbox"/></td> </tr> </table>		internal	<input type="checkbox"/>	<input type="checkbox"/>	external	<input checked="" type="checkbox"/>	<input type="checkbox"/>
internal	<input type="checkbox"/>	<input type="checkbox"/>									
external	<input checked="" type="checkbox"/>	<input type="checkbox"/>									

<b>3.8 O-rings</b> No striking feature	<input checked="" type="checkbox"/>	<input type="checkbox"/>
<b>3.9 Other</b> No striking feature	<input checked="" type="checkbox"/>	<input type="checkbox"/>

  
**3.10 Images of visual findings**
  
  




Fig. 1 Sprina plate, tappet side




Fig. 1 Sprina plate, sprina side

  
**Hydraulic function**
  
  

	n[rpm]	p_rail [bar]	I_MU [A]	Delivery rate [l/h] of new part 5/9/2007	Delivery rate [l/h] after testing 6/3/2008
Starting point	200	200	0.4	65.8	65.6
1000 rpm, p_rated	1000	1800	0.4	18.1	17.4
n_max_p, 500bar	3375	500	0.4	3.7	4.1

<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

TCD (technical customer documentation) testing point LG (1,000 rpm, p\_rated ≥ 15.5 or 15.2 l/h after running time) is met.  
No significant fuel-quantity drift compared to delivery measurement.

  
**5. Destiny of the parts**
  
  

The pump is stored at RB until 09/2008 and then scrapped.

  
**6. Appendix**
  
  



None

Tested:	<span style="background-color: black; color: black;">Non-responsive content removed</span>	Phone:	<span style="background-color: black; color: black;">Non-responsive content removed</span>	Date:	6/27/2008	Signature:	<span style="background-color: black; color: black;">Non-responsive content removed</span>
Department:	<span style="background-color: black; color: black;">[REDACTED]</span>	Phone:	<span style="background-color: black; color: black;">[REDACTED]</span>	Date:	6/30/2008	Signature:	<span style="background-color: black; color: black;">[REDACTED]</span>



EA11003EN-00896[0]

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.	[REDACTED]	
				Date	7/9/2008	
Department:		Person responsible:	Telephone:	Use	internal	
Non-responsive content removed					external	X
To: <b>Non-responsive content removed</b> Cylinder head :						
<b>Pump type:</b> CP4.1S_348_2x5,25_REC_3,3_1,95_MT4,2		<b>Customer:</b> VW	<b>Project:</b> R4 2.0 EU5	<b>Project / design pattern type</b> D / Series		
<b>Part number (TTNo.):</b> 445010507		<b>Date of manufacture:</b> 190707	<b>Serial number:</b> 0497	<b>Manufacturing plant - line</b> 0110 FeP (Feuerbach plant)		
<b>SAP-No.:</b> 30-101008-01		<b>Samos no.:</b> 594605,001	<b>Customer order no.:</b> 03L 130 755	<b>Engine/Vehicle number</b> CAH0000170		
<b>Customer part number</b> 03L 130 755		<b>Endurance run type [customer]:</b> Vehicle endurance run	<b>Endurance run conditions:</b> Ehra variable track for passenger cars	<b>DSBFD no.:</b> 20843		
<b>Mileage</b> 74380 km		<b>Parts receipt at dept. DS-PC/EDI:</b> 4/3/2008	<b>Process no.</b> 2008-CP4_0292	<b>Confidentiality note</b> Confidential		
<b>VA / ETC no.:</b> DS-180772		<b>Durability test type [RB]:</b>	<b>Fuel:</b> EN590			

1. Subject

CP4 customer return  
Diagnosis of endurance run end without complaint

2. Conclusion

**Function**

- Delivery rates after endurance run without significant fuel-quantity drift in comparison with the new state.
- Cold seal-tightness confirmed up to -30°C after endurance run

**Components**

- At the metering unit and metering unit hole, marks of an oblique assembly can be recognized. The risk of O-ring damage is confirmed by complaints in the 0-km range and is being pursued using 8D.
- The cavitation erosion in the tappet hole outside the tappet guide is an indication of excessively low pump interior pressure.
- Wear of the remaining components is low and without significant striking features.

**Result**

- The pump has passed the **endurance run**.



3. Results of diagnosis (visual findings)

Legend rating stages
 

OK	X		
Uncritical		X	
Critical			X

3.1 Drive	No striking feature	X		
3.2 Drivetrain	No striking feature	X		
3.3 High pressure	No striking feature	X		
3.4 Bearing	No striking feature	X		
3.5 Shaft seal	No striking feature	X		
3.6 Holes	Metering unit hole with scrape marks through metering unit assembly (see Figure 1)		X	

 <b>BOSCH</b> 	<b>CR pump CP4 - Diagnosis report</b>		Report no.	[REDACTED]	
			Date	7/9/2008	
Department:	Person responsible:	Telephone:	Use	internal	
Non-responsive content removed				external	X

**3.7 Attached components (Metering Unit, Overflow Valve, Counting Point)**

Metering unit magnetic core with external scrape marks through assembly (see Figure 2)

x

**3.8 O-rings**


No striking feature

x

**3.9 Other**

Cavitation erosion in the tappet hole outside the running range of the tappet (see Figure 3)



x

**3.10 Images of visual findings****Fig. 1 Housing, metering unit hole (scrape marks)****Fig. 2 Metering unit, external magnetic core (scrape marks)****Fig. 3 Housing, tappet hole (cavitation)****4. Hydraulic function**

				Delivery rate [l/h] of new part	Delivery rate [l/h] after testing	x		
	n[rpm]	p_rail [bar]	I_MU [A]	7/19/2007	4/14/2008			
Starting point	200	200	0.4	67	64.7	x		
1000 rpm, p_rated	1000	1800	0.4	17.4	17.4	x		
n_max_p, 500bar	3375	500	0.4	3.9	4.2	x		





TCD (technical customer documentation) testing point LG (1,000 rpm, p\_rated ≥ 15.5 or 15.2 l/h after running time) is met.  
No significant fuel-quantity drift compared to delivery measurement.

EA11003EN-00896[2]










 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.	[REDACTED]	
				Date	7/9/2008	
Department:	Person responsible:		Telephone:	Use	internal	
[REDACTED]	[REDACTED]		[REDACTED]		external	X
<p><b><u>5. Destiny of the parts</u></b></p> <p>The pump is stored at RB until 09/2008 and then scrapped.</p> <p><b><u>6. Attachments</u></b></p> <p>None</p>						
Tested:	Non-responsive content removed	Telephone:	Non-responsive content removed	Date:	7/14/2008	Signature:
Department:	[REDACTED]	Telephone:	[REDACTED]	Date:	7/14/2008	Signature:
Department:	[REDACTED]	Telephone:	[REDACTED]	Date:	7/15/2008	Signature:




EA11003EN-00897101

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.															
				Date	8/21/2008														
Department:	Person responsible:	Telephone:		Use	internal														
Non-responsive content removed			external		x														
To:	Non-responsive content removed																		
For information:																			
<b>Pump type:</b> CP4.1S_348_2x5,25_REC_3,3_1,95_MT4,2		<b>Customer:</b> VW	<b>Project:</b> R4 2.0 EU5	<b>Project / design pattern type</b> D / Series															
<b>Part number (TTNo.):</b> 445010507	<b>Date of manufacture:</b> 040607	<b>Serial number:</b> 0279	<b>Manufacturing plant - line</b> 0110 FeP (Feuerbach plant) – 01																
<b>SAP-No.:</b> 30-101005-07	<b>Samos no.:</b> 597416	<b>Customer order no.:</b>	<b>Engine/Vehicle number</b> CAH0000148																
<b>Customer part number</b>	<b>Endurance run type [customer]:</b> Vehicle endurance run	<b>Endurance run conditions:</b> Ehra variable track for passenger cars	<b>DSBFD no.:</b> 19435																
<b>Mileage</b> 47023 km	<b>Parts receipt at dept. DS-PC/EDI:</b> 4/28/2008	<b>Process no.</b> 2008-CP4_0387	<b>Confidentiality note</b> Confidential																
<b>VA / ETC no.:</b> DS-183934																			
<b>1. Subjec</b> CP4 customer return Diagnosis of endurance run end without complaint																			
<b>2. Conclusion</b> <b>Function</b> - Delivery rates after endurance run without significant fuel-quantity drift in comparison with the new state. <b>Components</b> - Wear of the components is low and without significant striking features. <b>Result</b> - The pump has passed the endurance run.																			
<b>3. Results of diagnosis (visual findings)</b> <div style="float: right; text-align: right;">           Legend rating stages           <table style="display: inline-table; vertical-align: middle;"> <tr> <td rowspan="3" style="font-size: 3em; vertical-align: middle;">{</td> <td>OK</td> <td><div><div style="background-color: green; width: 15px; height: 15px; display: flex; align-items: center; justify-content: center;">x</div></div></td> <td><div><div style="background-color: white; width: 15px; height: 15px; display: flex; align-items: center; justify-content: center;">x</div></div></td> <td><div><div style="background-color: white; width: 15px; height: 15px; display: flex; align-items: center; justify-content: center;">x</div></div></td> </tr> <tr> <td>Uncritical</td> <td><div><div style="background-color: yellow; width: 15px; height: 15px; display: flex; align-items: center; justify-content: center;">x</div></div></td> <td><div><div style="background-color: white; width: 15px; height: 15px; display: flex; align-items: center; justify-content: center;">x</div></div></td> <td><div><div style="background-color: red; width: 15px; height: 15px; display: flex; align-items: center; justify-content: center;">x</div></div></td> </tr> <tr> <td>Critical</td> <td><div><div style="background-color: white; width: 15px; height: 15px; display: flex; align-items: center; justify-content: center;">x</div></div></td> <td><div><div style="background-color: white; width: 15px; height: 15px; display: flex; align-items: center; justify-content: center;">x</div></div></td> <td><div><div style="background-color: white; width: 15px; height: 15px; display: flex; align-items: center; justify-content: center;">x</div></div></td> </tr> </table> </div>							{	OK	<div><div style="background-color: green; width: 15px; height: 15px; display: flex; align-items: center; justify-content: center;">x</div></div>	<div><div style="background-color: white; width: 15px; height: 15px; display: flex; align-items: center; justify-content: center;">x</div></div>	<div><div style="background-color: white; width: 15px; height: 15px; display: flex; align-items: center; justify-content: center;">x</div></div>	Uncritical	<div><div style="background-color: yellow; width: 15px; height: 15px; display: flex; align-items: center; justify-content: center;">x</div></div>	<div><div style="background-color: white; width: 15px; height: 15px; display: flex; align-items: center; justify-content: center;">x</div></div>	<div><div style="background-color: red; width: 15px; height: 15px; display: flex; align-items: center; justify-content: center;">x</div></div>	Critical	<div><div style="background-color: white; width: 15px; height: 15px; display: flex; align-items: center; justify-content: center;">x</div></div>	<div><div style="background-color: white; width: 15px; height: 15px; display: flex; align-items: center; justify-content: center;">x</div></div>	<div><div style="background-color: white; width: 15px; height: 15px; display: flex; align-items: center; justify-content: center;">x</div></div>
{	OK	<div><div style="background-color: green; width: 15px; height: 15px; display: flex; align-items: center; justify-content: center;">x</div></div>	<div><div style="background-color: white; width: 15px; height: 15px; display: flex; align-items: center; justify-content: center;">x</div></div>	<div><div style="background-color: white; width: 15px; height: 15px; display: flex; align-items: center; justify-content: center;">x</div></div>															
	Uncritical	<div><div style="background-color: yellow; width: 15px; height: 15px; display: flex; align-items: center; justify-content: center;">x</div></div>	<div><div style="background-color: white; width: 15px; height: 15px; display: flex; align-items: center; justify-content: center;">x</div></div>	<div><div style="background-color: red; width: 15px; height: 15px; display: flex; align-items: center; justify-content: center;">x</div></div>															
	Critical	<div><div style="background-color: white; width: 15px; height: 15px; display: flex; align-items: center; justify-content: center;">x</div></div>	<div><div style="background-color: white; width: 15px; height: 15px; display: flex; align-items: center; justify-content: center;">x</div></div>	<div><div style="background-color: white; width: 15px; height: 15px; display: flex; align-items: center; justify-content: center;">x</div></div>															
<b>3.1 Drive</b> No striking feature <div style="float: right;"> <div><div style="background-color: green; width: 15px; height: 15px; display: flex; align-items: center; justify-content: center;">x</div></div> <div><div style="background-color: white; width: 15px; height: 15px; display: flex; align-items: center; justify-content: center;">x</div></div> <div><div style="background-color: white; width: 15px; height: 15px; display: flex; align-items: center; justify-content: center;">x</div></div> </div>																			
<b>3.2 Drivetrain</b> No striking feature <div style="float: right;"> <div><div style="background-color: green; width: 15px; height: 15px; display: flex; align-items: center; justify-content: center;">x</div></div> <div><div style="background-color: white; width: 15px; height: 15px; display: flex; align-items: center; justify-content: center;">x</div></div> <div><div style="background-color: white; width: 15px; height: 15px; display: flex; align-items: center; justify-content: center;">x</div></div> </div>																			
<b>3.3 High pressure</b> No striking feature <div style="float: right;"> <div><div style="background-color: green; width: 15px; height: 15px; display: flex; align-items: center; justify-content: center;">x</div></div> <div><div style="background-color: white; width: 15px; height: 15px; display: flex; align-items: center; justify-content: center;">x</div></div> <div><div style="background-color: white; width: 15px; height: 15px; display: flex; align-items: center; justify-content: center;">x</div></div> </div>																			
<b>3.4 Bearing</b> No striking feature <div style="float: right;"> <div><div style="background-color: green; width: 15px; height: 15px; display: flex; align-items: center; justify-content: center;">x</div></div> <div><div style="background-color: white; width: 15px; height: 15px; display: flex; align-items: center; justify-content: center;">x</div></div> <div><div style="background-color: white; width: 15px; height: 15px; display: flex; align-items: center; justify-content: center;">x</div></div> </div>																			

EA11003EN-0089711










 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no. 	
				Date 8/21/2008	
Department:	Person responsible:	Telephone:	Use <input type="checkbox"/> internal <input checked="" type="checkbox"/> external		
Non-responsive content removed					
<b>3.5 Shaft seal</b>				<input checked="" type="checkbox"/>	<input type="checkbox"/>
No striking feature					
<b>3.6 Holes</b>				<input checked="" type="checkbox"/>	<input type="checkbox"/>
No striking feature					
<b>3.7 Attached components (metering unit, overflow valve, counting point)</b>				<input checked="" type="checkbox"/>	<input type="checkbox"/>
No striking feature					
<b>3.8 Other</b>				<input checked="" type="checkbox"/>	<input type="checkbox"/>
No striking feature					
<b>3.9 Images of visual findings</b>				<input checked="" type="checkbox"/>	<input type="checkbox"/>
No striking feature					
<b><u>4. Hydraulic function</u></b>					
				Delivery rate [l/h] of new part	Delivery rate [l/h] after testing
	n[rpm]	p_rail [bar]	I_MU [A]	6/4/2007	6/2/2008
Starting point	200	200	0.4	3.9	4.2
1000 rpm, p_rated	1000	1800	0.4	17.9	17.3
n_max_p, 500bar	3375	500	0.4	66.6	66.2
				<input checked="" type="checkbox"/>	<input type="checkbox"/>
				<input checked="" type="checkbox"/>	<input type="checkbox"/>
				<input checked="" type="checkbox"/>	<input type="checkbox"/>
TCD (technical customer documentation) testing point LG (1,000 rpm, p_rated ≥ 15.5 or 15.2 l/h after running time) is met.					
No significant fuel-quantity drift compared to delivery measurement.					
<b><u>5. Destiny of the parts</u></b>					
The pump is stored at RB until 12/2008 and then scrapped.					
<b><u>6. Attachments</u></b>					
None					
<b>Tested:</b>	Non-responsive content removed	<b>Phone:</b>	Non-responsive content removed	<b>Date:</b>	8/21/2008
<b>Signature:</b>		<b>Signature:</b>		<b>Date:</b>	8/21/2008
<b>Department:</b>		<b>Phone:</b>		<b>Date:</b>	8/21/2008
<b>Signature:</b>		<b>Signature:</b>		<b>Date:</b>	8/21/2008

EA11003EN-00898[0]


		<b>CR pump CP4 - Diagnosis report</b>		Report no.	[REDACTED]													
				Date	8/21/2008													
Department:	Person responsible:	Telephone:	Use															
Non-responsive content removed			internal															
			external		x													
To:	Non-responsive content removed																	
For information:																		
<b>Pump type:</b> CP4.1S_348_2x5,25_REC_3,3_1,95_MT4,2		<b>Customer:</b> VW	<b>Project:</b> R4 2.0 EU5	<b>Project / design pattern type</b> D / Series														
<b>Part number (TTNo.):</b> 445010507		<b>Date of manufacture:</b> 251007	<b>Serial number:</b> 0012	<b>Manufacturing plant - line</b> 5150 JhP (Jihlava plant) - 03														
<b>SAP-No.:</b> 30-101005-07		<b>Samos no.:</b> 597419	<b>Customer order no.:</b>	<b>Engine/Vehicle number</b> CBE0000383														
<b>Customer part number</b>	<b>Endurance run type [customer]:</b> Vehicle endurance run	<b>Endurance run conditions:</b> not known		<b>DSBFD no.:</b> 21136														
<b>Mileage</b> 920 h	<b>Parts receipt at dept. DS-PC/EDI:</b> 4/28/2008	<b>Process no.</b> 2008-CP4_0389		<b>Confidentiality note</b> Confidential														
<b>VA / ETC no.:</b> DS-183936																		
<b>1. Subject</b> CP4 customer return Diagnosis of endurance run end without complaint																		
<b>2. Conclusion</b> <b>Function</b> - Delivery rates after endurance run without significant fuel-quantity drift in comparison with the new state. <b>Components</b> - Wear of the components is low and without significant striking features. <b>Result</b> - The pump has passed the endurance run.																		
<b>3. Results of diagnosis (visual findings)</b>			Legend rating stages { <table border="1"> <tr> <td>OK</td> <td>x</td> <td></td> <td></td> </tr> <tr> <td>uncritical</td> <td></td> <td>x</td> <td></td> </tr> <tr> <td>Critical</td> <td></td> <td></td> <td>x</td> </tr> </table>				OK	x			uncritical		x		Critical			x
OK	x																	
uncritical		x																
Critical			x															
<b>3.1 Drive</b> No striking feature			<table border="1"> <tr> <td>x</td> <td></td> <td></td> </tr> </table>				x											
x																		
<b>3.2 Drivetrain</b> No striking feature			<table border="1"> <tr> <td>x</td> <td></td> <td></td> </tr> </table>				x											
x																		
<b>3.3 High pressure</b> No striking feature			<table border="1"> <tr> <td>x</td> <td></td> <td></td> </tr> </table>				x											
x																		
<b>3.4 Bearing</b> No striking feature			<table border="1"> <tr> <td>x</td> <td></td> <td></td> </tr> </table>				x											
x																		
<b>3.5 Shaft seal</b> No striking feature			<table border="1"> <tr> <td>x</td> <td></td> <td></td> </tr> </table>				x											
x																		






EA11003EN-00898[1]

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no. 	
				Date 8/21/2008	
Department:	Person responsible:	Telephone:		Use	<input type="checkbox"/> internal <input checked="" type="checkbox"/> external
Non-responsive content removed					
<b>3.6 Holes</b>				<input checked="" type="checkbox"/>	
No striking feature					
<b>3.7 Attached components (metering unit, overflow valve, counting point)</b>				<input checked="" type="checkbox"/>	
No striking feature					
<b>3.8 O-rings</b>				<input checked="" type="checkbox"/>	
No striking feature					
<b>3.9 Other</b>				<input checked="" type="checkbox"/>	
No striking feature					
<b><u>4. Hydraulic function</u></b>					
				Delivery rate [l/h] of new part	Delivery rate [l/h] after testing
	n[rpm]	p_rail [bar]	I_MU [A]	10/25/2007	6/3/2008
Starting point	200	200	0.4	3.6	4.3
1000 rpm, p_rated	1000	1800	0.4	17.8	17.5
n_max_p, 500bar	3375	500	0.4	66.3	65.8
				<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
				<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
				<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
TCD (technical customer documentation) testing point LG (1,000 rpm, p_rated ≥ 15.5 or 15.2 l/h after running time) is met.					
No significant fuel-quantity drift compared to delivery measurement.					
<b><u>5. Destiny of the parts</u></b>					
The pump is stored at RB until 12/2008 and then scrapped.					
<b><u>6. Attachments</u></b>					
None					
<b>Tested:</b>	Non-responsive content removed	<b>Phone:</b>	Non-responsive content removed	<b>Date:</b>	8/21/2008
<b>Signature:</b>		<b>Signature:</b>		<b>Date:</b>	8/21/2008
<b>Department:</b>		<b>Phone:</b>		<b>Date:</b>	8/21/2008
<b>Signature:</b>		<b>Signature:</b>		<b>Date:</b>	8/21/2008

EA11003EN-00899[0]



		<b>CR pump CP4 - Diagnosis report</b>		Report no.	[REDACTED]										
				Date	8/21/2008										
Department:	Person responsible:	Telephone:		Use	internal										
Non-responsive content removed			external		x										
To:	Non-responsive content removed														
For information:	[REDACTED]														
<b>Pump type:</b> CP4.1S_348_2x5,25_REC_3,3_1,95_MT4,2		<b>Customer:</b> VW	<b>Project:</b> R4 2.0 EU5	<b>Project / design pattern type</b> D / Series											
<b>Part number (TTNo.):</b> 445010507		<b>Date of manufacture:</b> 261007	<b>Serial number:</b> 0784	<b>Manufacturing plant - line</b> 0110 FeP (Feuerbach plant) – 01											
<b>SAP-No.:</b> 30-101005-07		<b>Samos no.:</b> 597421	<b>Customer order no.:</b>	<b>Engine/Vehicle number</b> CBE0000388											
<b>Customer part number</b>	<b>Endurance run type [customer]:</b> Vehicle endurance run	<b>Endurance run conditions:</b> ÖVL + PZD + ÖVL		<b>DSBFD no.:</b> 21137											
<b>Mileage</b> 913 h	<b>Parts receipt at dept. DS-PC/EDI:</b> 4/28/2008	<b>Process no.</b> 2008-CP4_0390		<b>Confidentiality note</b> Confidential											
<b>VA / ETC no.:</b> DS-183937															
<b>1. Subject</b> CP4 customer return Diagnosis of endurance run end without complaint															
<b>2. Conclusion</b> <b>Function</b> - Delivery rates after endurance run without significant fuel-quantity drift in comparison with the new state. <b>Components</b> - Wear of the components is low and without significant striking features. <b>Result</b> - The pump has passed the endurance run.															
<b>3. Results of diagnosis (visual findings)</b>			Legend rating stages		OK uncritical	<table border="1"> <tr><td>x</td><td></td><td></td></tr> <tr><td></td><td>x</td><td></td></tr> <tr><td></td><td></td><td>x</td></tr> </table>	x				x				x
x															
	x														
		x													
<b>3.1 Drive</b> No striking feature					Critical	<table border="1"> <tr><td>x</td><td></td><td></td></tr> </table>	x								
x															
<b>3.2 Drivetrain</b> No striking feature						<table border="1"> <tr><td>x</td><td></td><td></td></tr> </table>	x								
x															
<b>3.3 High pressure</b> No striking feature						<table border="1"> <tr><td>x</td><td></td><td></td></tr> </table>	x								
x															
<b>3.4 Bearing</b> No striking feature						<table border="1"> <tr><td>x</td><td></td><td></td></tr> </table>	x								
x															

EA11003EN-00899[1]

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no. 	
				Date 8/21/2008	
Department:	Person responsible:	Telephone:		Use	<input type="checkbox"/> internal <input checked="" type="checkbox"/> external
Non-responsive content removed					
<b>3.5 Shaft seal</b>				<input checked="" type="checkbox"/>	
No striking feature					
<b>3.6 Holes</b>				<input checked="" type="checkbox"/>	
No striking feature					
<b>3.7 Attached components (metering unit, overflow valve, counting point)</b>				<input checked="" type="checkbox"/>	
No striking feature					
<b>3.8 O-rings</b>				<input checked="" type="checkbox"/>	
No striking feature					
<b>3.9 Other</b>				<input checked="" type="checkbox"/>	
No striking feature					
<b><u>4. Hydraulic function</u></b>					
	n[rpm]	p_rail [bar]	I_MU [A]	Delivery rate [l/h] of new part	Delivery rate [l/h] after testing
				11/26/2007	6/3/2008
Starting point	200	200	0.4	3.7	4.2
1000 rpm, p_rated	1000	1800	0.4	17.6	17.5
n_max_p, 500bar	3375	500	0.4	67.1	66.1
				<input checked="" type="checkbox"/>	
				<input checked="" type="checkbox"/>	
				<input checked="" type="checkbox"/>	
TCD (technical customer documentation) testing point LG (1,000 rpm, p_rated ≥ 15.5 or 15.2 l/h after running time) is met.					
No significant fuel-quantity drift compared to delivery measurement.					
<b><u>5. Destiny of the parts</u></b>					
The pump is stored at RB until 12/2008 and then scrapped.					
<b><u>6. Attachments</u></b>					
None					
Tested:	Non-responsive content removed	Phone:	Non-responsive content removed	Date:	8/21/2008
Signature:				Signature:	Non-responsive content removed
Department:		Phone:		Date:	8/21/2008
Signature:				Signature:	



EA11003EN-00900101

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.	
				Date	7/9/2008
Department:	Person responsible:	Telephone:	Use		
Non-responsive content removed			internal		
			external		x
To:	Non-responsive content removed				
For information:					
<b>Pump type:</b> CP4.1S_348_2x5,25_REC_3,3_1,95_MT4,2	<b>Customer:</b> VW	<b>Project:</b> R4 2.0 EU5	<b>Project / design pattern type</b> D / Series		
<b>Part number (TTNo.):</b> 445010507	<b>Date of manufacture:</b> 011107	<b>Serial number:</b> 0013	<b>Manufacturing plant - line</b> 5150 JhP (Jihlava plant) - 03		
<b>SAP-No.:</b> 30-000335-03	<b>Samos no.:</b> 704745	<b>Customer order no.:</b>	<b>Engine/Vehicle number</b> CBA 655 000653		
<b>Customer part number</b>	<b>Endurance run type [customer]:</b> Vehicle endurance run	<b>Endurance run conditions:</b> not known	<b>DSBFD no.:</b> 21830		
<b>Mileage</b> 50000 km	<b>Parts receipt at dept. DS-PC/EDI:</b> 5/27/2008	<b>Process no.</b> 2008-CP4_0443	<b>Confidentiality note</b> Confidential		
<b>VA / ETC no.:</b> DS-191579	<b>Durability test type [RB]:</b>	<b>Fuel:</b>			

### 1. Subject

CP4 customer return  
Verification of modification package B (omission of the anti-friction paint on the spring plate)

### 2. Conclusion

**Function**  
- Delivery rates after endurance run without significant fuel-quantity drift in comparison with the new state.

**Components**  
- Wear of the spring plate without anti-friction paint is low, as is the wear of the directly adjacent components. An influence of the omission of the anti-friction paint is not visible.  
- The small traces of corrosion on the wear surfaces (low wear) of e.g. intake valve and spring plate are abnormal, but not critical.  
- The discoloration in the radial flange bearings are due to smoothness and incidental fuel deposits. The individual grooves are not critical in their form.  
- Wear of the remaining components is low and without significant striking features.

**Result**  
- The pump has passed the endurance run.

### 3. Results of diagnosis (visual findings)

**3.1 Drive**  
No striking feature

**3.2 Drivetrain**  
Wear of spring plate without anti-friction paint is low (see Figure 1 and Figure 2), but traces of corrosion

**3.3 High pressure**  
Signs of corrosion in the wear area of intake valve (see Figure 3) sealing point to the stationery seal ring  
Signs of corrosion in the wear area of stationery seal ring (see Figure 4) to the intake valve plate

**3.4 Bearing**  
Radial flange bearing with grooved structure and discoloration in the center of the bearing (see Figure 5)

**3.5 Shaft seal**  
No striking feature

**3.6 Holes**  
No striking feature

Legend rating stages

OK

uncritical

Critical

x		
	x	
		x

x		
	x	

	x	
--	---	--








	x	
--	---	--

x		
---	--	--




  

x		
---	--	--

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no. <span style="background-color: black; color: black;">[REDACTED]</span>						
				Date 7/9/2008						
Department:	Person responsible:	Telephone:	Use	<table border="1"> <tr> <td>internal</td> <td></td> <td></td> </tr> <tr> <td>external</td> <td>x</td> <td></td> </tr> </table>	internal			external	x	
internal										
external	x									
Non-responsive content removed										
<b>3.7 Attached components (metering unit, overflow valve, counting point)</b> No striking feature				<table border="1"> <tr> <td>x</td> <td></td> <td></td> </tr> </table>	x					
x										
<b>3.8 O-rings</b> No striking feature				<table border="1"> <tr> <td>x</td> <td></td> <td></td> </tr> </table>	x					
x										
<b>3.9 Other</b> No striking feature				<table border="1"> <tr> <td>x</td> <td></td> <td></td> </tr> </table>	x					
x										
<b>3.10 Images of visual findings</b>										
										
<p>Fig. 1 Spring plate, tappet-side (traces of corrosion)</p>		<p>Fig. 2 Spring plate, spring-side (traces of corrosion)</p>								
										
<p>Fig. 3 Intake valve, sealing area (wear)</p>		<p>Fig. 4 Stationery seal ring, SV direction (traces of corrosion)</p>								
										
<p>Fig. 4 Flange bearing, radial (grooves, discoloration)</p>										





EA11003EN-00900[2]

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no. 	
				Date 7/9/2008	
Department:	Person responsible:	Telephone:	Use <input type="checkbox"/> internal <input checked="" type="checkbox"/> external		
Non-responsive content removed					
<b>4. Hydraulic function</b>					
	n[rpm]	p_rail [bar]	I_MU [A]	Delivery rate [l/h] of new part	Delivery rate [l/h] after testing
				11/1/2007	5/27/2008
Starting point	200	200	0.4	67.5	66
1000 rpm, p_rated	1000	1800	0.4	17.8	17.6
n_max_p, 500bar	3375	500	0.4	3.7	4.1
<div> <div></div> <div></div> <div></div> </div>					
<p>TCD (technical customer documentation) testing point LG (1,000 rpm, p_rated ≥ 15.5 or 15.2 l/h after running time) is met.</p> <p>No significant fuel-quantity drift compared to delivery measurement.</p>					
<b>5. Destiny of the parts</b>					
The pump is stored at RB until 09/2008 and then scrapped.					
<b>6. Attachments</b>					
None					
Tested:	Non-responsive content removed	Phone:	Non-responsive content removed	Date:	7/10/2008
Signature:					
Department:		Phone:		Date:	7/14/2008
Signature:					
Department:		Phone:		Date:	7/15/2008
Signature:					



EA11003EN-00901[0]

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.	[REDACTED]	
				Date	2/20/2009	
Department:		Person responsible:		Telephone:		
Non-responsive content removed						
				Use	internal	
					external	X
To:	Non-responsive content removed					
Cylinder head:	[REDACTED]					
Pump type:		Customer:	Project:	Project / design pattern type		
CP4.1S 348 2x5.25 REC 3.3 1.95 MT4.2		VW	R4 2.0 EU5	D / Series		
Part number (TTNo.):		Date of manufacture:	Serial number:	Manufacturing plant - line		
0445010507		110308	0491	0110 FeP (Feuerbach plant) - 01		
SAP-No.:		Samos no.:	Customer order no.:	Engine/Vehicle number		
30-101005-01		718616	731223	not known		
Customer part number		Endurance run type [customer]:	Endurance run conditions:	DSBFD no.:		
731223		Engine trial	Measurement program (see below)	23076		
VA / ETC no.:		Actual mileage	Fuel:	Confidentiality note		
DS-203337		8 h	Reference diesel CEC RF-06-03	Confidential		
<b>Complaint:</b> Pump does not build up high pressure any longer						
<b>1. Subject</b>  <p>CP4 customer returns with complaint  Pump has been disassembled by the customer and the bearings in the flange and housing were pressed out.  The HP piston seized in the top dead center (TDC) position was dismantled by the customer.</p> <p>Testing conditions: Measuring program A, B, E, 0.4 x F  Reference diesel CEC RF-06-03</p> <p>Description of the measuring program  A: 1 h start-up program  B: Program for reproducibility (5 x 12 points)  C: Long program high pressure fuel pump (HPFP) compression (1 x 1240 points) at Tclosed = 20 °C  D: Long program high pressure fuel pump (HPFP) compression (1 x 1240 points) at Tclosed = 70 °C  E: Shortened program High pressure fuel pump (HPFP) compression (1 x 261 points) at Tclosed = 20°C  F: Shortened program High pressure fuel pump (HPFP) compression (1 x 261 points) at Tclosed = 70 °C</p>						
<b>2. Conclusion</b>  <p><b>Function</b>  - No functional test possible due to complaint reason and irreversible bearing disassembly.</p> <p><b>Components</b></p> <ul style="list-style-type: none"> <li>- The high-pressure piston has seized in the piston bore on the low-pressure side between the first and second lubrication groove. Traces of abrasion from the adhesion region towards the drivetrain are probably caused by the knocking out of the HP piston during disassembly by the customer. This is also suggested by the fact that there are no traces of abrasion visible along the high-pressure side from the main wear area and the HP piston has only traces of abrasion towards the high-pressure range. Traces of abrasion in the piston bore opposite the main wear area do not extend to the respective ends of the piston bore.</li> <li>- The rupture of the spring plate on the inner ring is probably a result of the HP piston seizure. This damage is not forced (see also report CP4_0835 2008). In the documentation accompanying this complaint, there is no indication of a broken spring plate, so that damage is also possible during transport in a disassembled state.</li> </ul> <p><b>Result</b></p> <ul style="list-style-type: none"> <li>- Cause for the seizure of the high-pressure piston in the low pressure area could not be found. The different particle traces cannot be evaluated sufficiently securely with regard to cause and effect due to the forcible disassembly. The operating conditions and the reference fuel do not come under consideration as the cause in terms of specification.</li> <li>- Similar cases of damage with this series pump are known as 0-km complaint with about 3 months older date of manufacture and are documented on the 8D no. 230002262459 (previously 2 failures). Even in these cases, no cause could be determined. Regarding the possible causes and conducted analyses and improvement measures, please refer to these ongoing 8D.</li> <li>- The pump has failed the <b>endurance run</b>.</li> </ul>						

<b style="font-size: 1.2em; margin: 0 10px;">BOSCH</b>		<b>CR pump CP4 - Diagnosis report</b>		Report no.	[REDACTED]	
				Date	2/20/2009	
Department: Non-responsive content removed		Person responsible:		Telephone:		
				Use	internal	
					external	X

<b>3. Results of diagnosis (visual findings)</b>	Legend rating stages { <table style="display: inline-table; vertical-align: middle;"> <tr> <td>OK</td> <td style="background-color: green; width: 20px; height: 15px;"></td> <td style="width: 20px; height: 15px;"></td> <td style="width: 20px; height: 15px;"></td> </tr> <tr> <td>Uncritical</td> <td style="background-color: yellow;"></td> <td style="background-color: orange;"></td> <td style="background-color: red;"></td> </tr> <tr> <td>critical</td> <td style="background-color: red;"></td> <td style="background-color: red;"></td> <td style="background-color: red;"></td> </tr> </table>	OK				Uncritical				critical			
OK													
Uncritical													
critical													

<b>3.1 Drive</b> No striking feature	<table style="width: 100%; text-align: center;"> <tr> <td style="background-color: green; width: 20px; height: 15px;"></td> <td style="width: 20px; height: 15px;"></td> <td style="width: 20px; height: 15px;"></td> </tr> </table>			

<b>3.2 Drivetrain</b> Broken spring plate on the inner ring (entrainment HP piston) at two bars (see Figure 1 and Figure 2)	<table style="width: 100%; text-align: center;"> <tr> <td style="width: 20px; height: 15px;"></td> <td style="width: 20px; height: 15px;"></td> <td style="background-color: red; width: 20px; height: 15px;"></td> </tr> </table>			

<b>3.3 High pressure</b> Cylinder head / piston bore with traces of adhesion and abrasion in the LP range (see Figure 3 and Figure 4) Cylinder head / piston bore opposite side without increased traces of wear (see Figure 5) HP piston with adhesive wear between the 1st and 2nd lubrication groove on the LP side (see Figure 6) SEM (scanning electron microscopy) image of HP piston in the material contrast mode does not show any foreign materials (see Figure 7)	<table style="width: 100%; text-align: center;"> <tr> <td style="width: 20px; height: 15px;"></td> <td style="width: 20px; height: 15px;"></td> <td style="background-color: red; width: 20px; height: 15px;"></td> </tr> </table>			

<b>3.4 Bearing</b> No striking features, the bearings were delivered in the pressed-out state	<table style="width: 100%; text-align: center;"> <tr> <td style="background-color: green; width: 20px; height: 15px;"></td> <td style="width: 20px; height: 15px;"></td> <td style="width: 20px; height: 15px;"></td> </tr> </table>			

<b>3.5 Shaft seal</b> No striking feature	<table style="width: 100%; text-align: center;"> <tr> <td style="background-color: green; width: 20px; height: 15px;"></td> <td style="width: 20px; height: 15px;"></td> <td style="width: 20px; height: 15px;"></td> </tr> </table>			

<b>3.6 Holes</b> No striking feature	<table style="width: 100%; text-align: center;"> <tr> <td style="background-color: green; width: 20px; height: 15px;"></td> <td style="width: 20px; height: 15px;"></td> <td style="width: 20px; height: 15px;"></td> </tr> </table>			

<b>3.7 Attached components (Metering Unit, Overflow Valve, Counting Point)</b> No striking feature	<table style="width: 100%; text-align: center;"> <tr> <td style="background-color: green; width: 20px; height: 15px;"></td> <td style="width: 20px; height: 15px;"></td> <td style="width: 20px; height: 15px;"></td> </tr> </table>			


  

<b>3.8 O-rings</b> No striking feature	<table style="width: 100%; text-align: center;"> <tr> <td style="background-color: green; width: 20px; height: 15px;"></td> <td style="width: 20px; height: 15px;"></td> <td style="width: 20px; height: 15px;"></td> </tr> </table>			


  

<b>3.9 Other</b> No striking feature	<table style="width: 100%; text-align: center;"> <tr> <td style="background-color: green; width: 20px; height: 15px;"></td> <td style="width: 20px; height: 15px;"></td> <td style="width: 20px; height: 15px;"></td> </tr> </table>			


  
**3.10 Images of visual findings**




**Fig. 1 Spring plate, tappet-side**



**Fig. 2 Detail of Figure 1. the**





**Fig. 3 Cylinder head, piston hole (wear)**



**Fig. 4 Detail of Figure 3 (wear)**

EA11003EN-00901[2]

 <b>BOSCH</b> 	<b>CR pump CP4 - Diagnosis report</b>		Report no.	[REDACTED]	
			Date	2/20/2009	
Department:	Person responsible:	Telephone:	Use	internal	
Non-responsive content removed				external	X




Fig. 5 Cylinder head, piston hole opposite side




Fig. 6 HP piston, LP-side (wear)




Fig. 7 HP piston, SEM (scanning electron microscopy material contrast)





Fig. 8 HP piston, SEM (scanning electron microscopy image (wear))

**Hydraulic function**

	n[rpm]	p <sub>rail</sub> [bar]	I <sub>MU</sub> [A]	Delivery rate [l/h] of new part	Delivery rate [l/h] after testing



No functional test possible due to complaint reason and irreversible bearing disassembly.

**6. Destiny of the parts**

The pump is stored at RB until 06/2009 and then scrapped.


**7. Appendix**

8D no. 230002262459 in the version dated October 10 2008

Tested:	Non-responsive content removed	Telephone:	Non-responsive content removed	Date:	2/27/2009	Signature:	Non-responsive content removed
Department:		Telephone:		Date:	2/27/2009	Signature:	
Department:		Telephone:		Date:	3/3/2009	Signature:	



EA11003EN-00901[3]

 <b>BOSCH</b>	<b>8D report</b>				Appendix no.
	Reference no.	BSA000001280-001	Reissue:	19-Sep-08	
	QC no.:	230002245964	Interim report:		
	Q8 No.:	230002262459	Final report:	10-Oct-08	
Header data					
Complaint date:	19-Sep-08	Product:	RADIAL-PISTON PUMP		
8D title:	Q8: piston pump seized	Bosch material no.	0445010507		
Defectiveness:	<b>Bosch responsibility</b>	Bosch manufacturing plant:	Jihlava plant - DS (5150)		
Claim Customer	VOLKSWAGEN AG	Application:			
Delivery customer:	VW	Customer service material no.	03L130755		
Complaint type:	0-km, obstructed	Serial number:	BPT 0958		
Failure location:	From finished vehicle or fleet action	ID no.	IKB 732262		
Goods used	Dispatch: for analysis to RB				
Goods used	<b>For scrapping at RB</b>	Problem number	4814268		
After analysis					
Issued by	Non-responsive content removed	Initiated by:	Non-responsive content removed		
c.c.:					
Customer's clerk:					
Business address:		Telephone:			
		Fax:			
<b>D1 problem-solving team</b> Sponsor: [Redacted]					
Team leader:	Non-responsive content removed		Telephone:	[Redacted]	
E-mail:	Non-responsive content removed		Fax:	[Redacted]	
Business address:					
Team members:	Non-responsive content removed				
<b>D2 Description of problem</b>		Date of manufacture:		12-Jun-08	
Customer complaint:	No rail pressure; (malfunction)				
Bosch description:	(For checking at U-point)				
Self-diagnosis of customer:					
Bosch self-diagnosis:					
Vehicle type:		Mounting location in the vehicle:			
Engine designation:		Vehicle identification no:			
Number of faulty items:	1	Returned qty. to the customer:			
Mileage:		Customer code:			
Date of purchase:		Failure date:	19-Sep-08		
Code no. of co-inspector					
Subsupplier					
Geographic location of the complaint:	Germany, Lower Saxony, VW vehicle plant Emden				
Fault location in the product / module:	Cylinder head (L) piston	U plant:	Plant Jihlava - DS		
Fault type:	seized	Final analysis:	10-Oct-08		
<b>D3 immediate measure (s)</b>					
JhP (Jihlava plant)/QMM2.13					
Due to the fact that the error message of the customer was a functional failure, we have tested the results of the assembly functional test. Result was OK, pump was only once with an OK without interruption result					

EA11003EN-00901[4]

tested. Implementation of the possible actions is possible only after the pump analysis.					
Responsible person	Non-responsive content removed	Implemented on:	19-Sep-08	Effective from:	19-Sep-08
Consent of customer in process or product-changing immediate measure on:				Responsible person	
Should customer-specific 8D requirements be met? Which ones?		No			
<b>D4 root cause analysis</b> Title: Pump piston seized					
<b>Causing process:</b> Exact cause cannot be determined		Others -> cause cannot be determined			
<b>Main cause (s) with proof: How could the fault occur?</b> Bosch Jihlava plant/QMM31 analysis 01 / visual inspection not OK, the black cap is missing on the cylinder head 02 / Check of CL and RL connection OK 03 / Non-return valve nominal depth: 3.6 ± 0.05 mm actual: 3.63 mm OK 04 / Fuel removal OK 05 / Bubble test OK 06 / metering unit test OK, metering unit screen without particles 07/ Axial clearance OK should be: from 0.15 - to 0.30 mm: 0.21mm 08 / Cylinder head disassembly not OK - After the cylinder head disassembly, it was found that pump piston in the cylinder has seized. Further action: Analysis of piston seizure at Bosch Jihlava plant/QMM1.4 Fuel analysis at Bosch Jihlava plant/ HSE  Proof furnished by: Non-responsive content removed Proof furnished on: 04-Sep-08					
<b>Analysis of the wear</b> In the area of seizure, both pump pistons and cylinder heads were so badly damaged that the exact cause of the seizure cannot be clarified. Close to the seizure area, grooves with the residues of aluminum particles, which could have been caused by machining (corundum) or from adjacent parts (flange, housing), were found. A more accurate chemical analysis with respect to the size of the particles is not possible. In the area of seizure, corroded areas were also found. The occurrence of corrosion indicates a high chlorine and oxygen content. There are no burrs in the groove region. Micro-structure and hardness in accordance with the specifications. Proof furnished by: Bosch Jihlava plant/QMM1.4 Proof furnished on: 26-Sep-08					
<b>Analysis of the fuel sample enclosed</b> Fuel analysis: - Percentage of methyl esters: should be: up to 5 vol. % is: 0.5 ± 0.3 vol. OK - Measurement of water content: up to 200 ppm actual: 60±20 ppm OK - Measurement of flash point: Nominal flashpoint: Greater than 55 °C: 58.0 ± 1.4 °C OK - Elementary analysis: Chlorine content: 0 ppm Proof furnished by: Non-responsive content removed Proof furnished on: 26-Sep-08					
<b>JhP (Jihlava plant)/MFH4 Analysis</b> Analysis of the piston seizure was performed with Ishikawa systematics. Five aspects were assessed: 1 - Human 2 - Method 3 - Plant 5 - Material For results of the analysis, please see the end of 8D in the .ppt slides Proof furnished by: Non-responsive content removed Proof furnished on: 05-Nov-08					
<b>Main cause (s) with proof: Why was the fault not discovered?</b> JhP (Jihlava plant)/MFH4 Analysis, QMM2.13, Based on the analysis, three failure hypotheses were defined: 1. Hypothesis: Seizure due to metal chips after shot blasting of the piston lubrication groove at the piston sub-supplier 2. Hypothesis: Seizure due to particles at the piston (grinding residue after piston grinding in the piston lubrication groove) 3. Hypothesis: Mounting of the piston in the cylinder head not OK Proof furnished by: Non-responsive content removed Proof furnished on: 05-Nov-08					

EA11003EN-00901[5]

<b>Reproduction of the error:</b> The error could be reproduced on: The error could not be reproduced.		By:					
<b>D5 Possible corrective action (s) and proof of effectiveness (testing)</b>							
Rotating groove machining				Action against: [Non-responsive content removed]			
Detachment of doublings within the leakage oil groove surface as a consequence of its seizure.							
Corrective actions: Change of the machining of the piston ring groove (new parts) Current status: Piston grooves are rotated Scheduled status: Piston grooves are cut. Detachable doublings or spots occurring in shot blasted grooves (through shot blasting). Proof furnished by: [Non-responsive content removed] Proof furnished on: 16-Jun-08							
Cleanliness				Action against: [Non-responsive content removed]			
Seizure due to particles at the piston (grinding residue after piston grinding in the piston lubrication groove) 1. Increase in the frequency of cleanliness analysis in piston manufacturing 2. Increase in the frequency of cleanliness analysis of the cylinder head 3. 100% visual inspection of the pump pistons after washing, during piston manufacturing 4. Introduction of visual inspection of the piston at DNA (random sample) 5. Change in the working processes for piston manufacturing after grinding the piston 6. Increase in the check of cylinder head blisters in Feuerbach plant and Jihlava plant Proof furnished by: [Non-responsive content removed] Proof furnished on: 04-Nov-08							
Cylinder head and piston assembly				Action against: [Non-responsive content removed]			
Mounting of the piston in the cylinder head: 1. Introduction of the optical sensor for monitoring the correct position of the piston while installing the piston in the cylinder head Proof furnished by: [Non-responsive content removed] Proof furnished on: 04-Nov-08							
<b>D6 Implementation of corrective action (s)</b>							
Customer approval on:				by:			
<b>Implementation of corrective action (s)</b>							
Rotating groove machining				Action against:		[Non-responsive content removed]	
Detachment of doublings within the leakage oil groove surface as a consequence of its seizure.							
Corrective actions: Change of the machining of the piston ring groove (new parts) Current status: Piston grooves are rotated Scheduled status: Piston grooves are cut. Detachable doublings or spots occurring in shot blasted grooves (through shot blasting).							
Responsible person	[Non-responsive content removed]	Implementation scheduled on:	29-Nov-08	Implemented on:	Effective from:		
Cleanliness Corrective action: 1. Increase in the frequency of cleanliness analysis in piston manufacturing Previous status: 1 x per week New status: 1 x per day D: 10.10.2008 Status: Completed 2. Increase in the frequency of cleanliness analysis of the cylinder head Previous status: 1 x per week New status: 3 x per week (Mon, Wed, Fri) D: 06.10.2008 Status: Completed 3. 100% visual inspection of the pump pistons after washing, during piston manufacturing D: 10.10.2008 Status: Completed 4. Introduction of visual inspection of the piston at DNA (random sample 10 units per small load carrier) 12/2008 Status: Completed 5. Change in the working processes for piston manufacturing after grinding the piston D: 10.10.2008 Status: Completed 6. Increase in the check of cylinder head blisters in Feuerbach plant and Jihlava plant D: 22.10.2008 Status: Completed				Action against: [Non-responsive content removed]  D:			
Responsible person	JHP (Jihlava plant)/MFH4	Implementation	22-Oct-08	Implemented on:	22-Oct-08	Effective from:	22-Oct-08



EA11003EN-00901[6]

		scheduled on:				
Cylinder head and piston assembly			Action against: JhP/MFH4 Analyse			
Mounting of the piston in the cylinder head:						
1. Introduction of the optical sensor for monitoring the correct position of the piston while installing the piston in the cylinder head						
T: QC-NR: 230002245964 7.1.008 2 (4)						
Responsible person	JHP (Jihlava plant)/MFH4	Implementation scheduled on:	19-Dec-08	Implemented on:	Effective from:	
<b>Proof of effectiveness for the implemented corrective action (s):</b>						
Rotating groove machining			Action against:	JhP (Jihlava plant)/MFH4 Analysis		
Proof furnished by:			FEP (Feuerbach plant)/PUQ1	Proof furnished on:		
Cleanliness			Action against:	JhP (Jihlava plant)/MFH4 Analysis		
Proof furnished by:			JHP (Jihlava plant)/MFH4	Proof furnished on: Oct 22 2008		
Cylinder head and piston assembly			Action against:	JhP (Jihlava plant)/MFH4 Analysis		
Proof furnished by:			JHP (Jihlava plant)/MFH4	Proof furnished on:		
<b>Cancellation of immediate measure (s)</b>						
Cancellation of immediate measures not implemented.						
by:			JhP (Jihlava plant)/QMM2.13	on: Nov 04 2008		
<b>D7 preventive measure (s) against recurring errors</b>						
<b>Improvement of the Quality Management system (FMEA (Failure Mode and Effects Analysis), procedural instructions, PQP, etc.) Measure</b>						
In Jihlava plant implementation of measures also in assembly module 5, Feuerbach plant management was informed of implemented measures						
Responsible person	Non-responsive content removed	Implementation scheduled on:	06-Nov-08	Implementation completed on:	06-Nov-08	
<b>Acceptance of potential solutions for other processes, products, sites:</b>						
Is this error likely to occur in other processes, products or sites? Yes						
If yes: What other processes, products or sites may be affected?						
If yes, what sites will you inform (e.g. FMEA, Lessons Learned Coordinators)?						
Non-responsive content removed						
If not: Why don't you expect the error to occur in other processes, products or sites?						
<b>D8 final consultation (appreciation, suggestions for improvement)</b>						
Participants:						
Implemented on:						
Results:						
Completion of the report confirmed by:						
Sponsor:	Name:		Date:	Signature:		
P/QMM:	Name:		Date:	Signature:		

Non-responsive content removed

## Jihlava plant/MFH4 pump CP4 - pistons seized



### First influence - human

1.1 Visual inspection: Regular monitoring of cleanliness in piston manufacturing  
D: 10.10.2008 Completed

Status: Cleanliness analysis 1x per week - result OK

1.2. Visual inspection: Increasing frequency of cleanliness check of pistons from once in two weeks to  
daily

D: 10.10.2008 Completed

Result: Measurements in progress - all measurements OK

1.3. Piston fitted incorrectly: Sensor for piston insertion

D: 10.10.2008 in

progress

Status: Sensor ordered, delivery date 12/2008



## Jihlava plant/MFH4 pump CP4 - pistons seized



### First influence - human

1.4. Temperature control too short: Procedural instruction + training for optimal temperature control

D: 10.24.2008 finished

Integrated temperature sensor on pairing the cylinder head system. Pairing process with the parts that are not temperature-controlled is not possible. It is only an infrastructure facility. Procedural instruction and training for optimal temperature control implemented.

1.5. Insertion of piston is not correct: Pattern with piston clamping / piston friction  
Preparation T:  
End 12/2008 in progress

Status: No grinding or clamping pistons available, task in progress

1.6. Incorrect piston class: Test delivery rate - 5 pumps with each piston class

D: 10.10.2008 completed

A cylinder head of class 3 / pistons with classes 1,2,3,4, no seizure detected after functional testing, piston class 5 - fine smoothening visible





## Jihlava plant/MFH4 pump CP4 - pistons seized



### Second influence - method

2.1. Cleanliness: Frequency increase cleanliness check of cylinder head - check capacity and possibilities: 10.06.2008 completed

Analysis of the cleanliness of cylinder head 3x per week (Mon, Wed, Fri)

2.2. Washing, storage, manipulation: Comparison Jihlava plant- Feuerbach plant  
D: 10.10.2008 completed

Washing	Feuerbach plant: High pressure washing system	Jihlava plant: water washing system
Storage	Feuerbach plant: Supermarket / washing frame	Jihlava plant: washing frame in small load carrier, VCI/ (*)
Manipulation	Feuerbach plant: Milkrun	JhP: Milkrun

(\*) Reason: Piston manufacturing in another hall



## Jihlava plant/MFH4 pump CP4 - pistons seized



### Second influence - method

#### 2.3. Washing, storage, manipulation: Limit class pistons - exotic types

D: 10.10.2008 completed

Washing	Feuerbach plant: High pressure washing system	Jihlava plant: water washing system
Storage	Feuerbach plant: Supermarket / washing frame	Jihlava plant: washing frame in small load carrier, VCI/ (*)
Manipulation	Feuerbach plant: Milkrun	JhP: Milkrun

(\*) Reason: Piston manufacturing in another hall

#### 2.4. Pairs of pistons: Comparison Jihlava plant- Feuerbach plant

D: 10.10.2008  
completed

No deviations observed between Feuerbach plant and Jihlava plant. Processes are identical



## Jihlava plant/MFH4 pump CP4 - pistons seized



### Second influence - method

2.5. Rinsing: Check method and medium cleanliness

D: 10.10.2008 completed

Check is done 1x per week according to the specification, result OK

2.6. Incorrect piston class: Readings 4 weeks before the complaints

Check

D: 10.10.2008

completed

Number of pairs about 40,000 pcs., thereof 17 times not OK.





## Jihlava plant/MFH4 pump CP4 - pistons seized



### Third influence - plant

3.1. Grinding, measurement, washing: Check for 300 pistons for grinding residues in piston slot D: 10.10.2008 **completed**

Result: 300 pieces of piston pump checked. No particles or grinding residues found in the piston slot

3.2. Grinding, measurement, washing: Piston hardness - check D: 10.10.2008 **completed**

Check 6 pcs. - result OK

3.3. Grinding, measurement, washing: 100% visual inspection of the pump piston after washing, during piston manufacturing + DNA random inspection D: 10.10.2008 **completed**

100% check during piston manufacturing and random inspection (10 pcs. for each small load carrier) performed on DNA



## Jihlava plant/MFH4 pump CP4 - pistons seized



### Fourth influence environment

- 4.1. Temperature control: Check space for optimal inspection of piston cleanliness  
(Air - blower, etc.) D: 10.10.2008 **Completed**

Place for the inspection spot during piston manufacturing has been changed and adapted.

- 4.2. Shifting - transport: Check in Feuerbach plant and Jihlava plant  
D: 10.10.2008  
**Completed**

Transport of the piston in small load carrier, milk run. Feuerbach plant and Jihlava plant identical

- 4.3. Wash medium: Regularity and results check  
D: 10.10.2008  
**completed**

Check 5 times a week, result OK



## Jihlava plant/MFH4 pump CP4 - pistons seized



### 5. Influence - material

5.1. Geometry, roughness, hardness, temperature: Activities are defined

D: 10.24.2008 finished

Roundness, straightness, roughness has been dimensioned for 25 pcs. of pistons.  
Result OK





EA11003EN-00902[0]

**BOSCH****CR pump CP4 - Diagnosis report**

Report no.

Date

3/31/2009

**Department:****Person responsible:****Telephone:**

Non-responsive content removed

Use

internal

external

x

**Department:****Person responsible:****Telephone:****Confidentiality note**

Confidential

To:

Non-responsive content removed

Cylinder head:

Non-responsive content removed

<b>Pump type:</b> CP4.1S_348_2x5.25_REC_3.3_1.95_MT4.2	<b>Customer:</b> VW	<b>Project:</b> R4 2.0 EU5	<b>Project / design pattern type</b> D / Series
<b>Part number (TTNo.):</b> 0445010507	<b>Date of manufacture:</b> 140508	<b>Serial number:</b> 0400	<b>Manufacturing plant - line</b> 0110 FeP(Feuerbach plant) – 04
<b>SAP-No.:</b> 30-101005-01	<b>Samos no.:</b> 726712	<b>Customer order no.:</b> 731223	<b>Engine / vehicle number</b> CBB000706 / 3C59E102-PQ46
<b>Customer part number</b> 731223	<b>Durability test type [customer]:</b> Vehicle durability test	<b>Durability test conditions:</b> EWP(Ehra variable track for passenger cars)	<b>DSBFD no.:</b> 23775
<b>VA / ETC no.:</b> DS-209813	<b>Actual mileage</b> 79622 km	<b>Fuel:</b> EN590	<b>Nominal pressure [bar]:</b> 1800

**1 Subject**

CP4 customer return

Diagnosis after durability test end Local wear of the inlet coating on the running surface in the roller support, verification of modification package 4 (second source supplier)

Testing conditions: EWP(Ehra variable track for passenger cars)

**2. Conclusion****Function**

- Delivery rates after durability test without significant fuel-quantity drift in comparison with the new state.

**Components**

- The wear of the components is low in general. Only on the running surface of the roller support is low wear to be seen at the run-in layer of the C coating (wear depth 0.29 to 0.43 µm, see Fig. 3.1 and Appendix 1).

**Content of modification package 4-second source supplier**

- Precast camshaft
- Precast tappet body
- Roller support soft part
- High-pressure piston pump precursor
- Precast non-return valve hemispherical head
- Precast non-return valve spring seat
- Precast intake valve plate
- Precast overflow valve carrier
- Blank flange
- Bearing bushing flange and housing

**Result**

- The components of the modification package 4 (second source supplier) have the wear rating green. A correlation between the wear of the roller support C coating and the roller support soft part of the second source supplier is unlikely.
- The pump has passed the durability test.

**3. Results of diagnosis (visual findings)****3.1 Drive**

No striking feature

Legend rating stages

OK

uncritical  
Critical


x			
	x		
			x

**3.2 Drivetrain**

Local wear of the inlet coating on the running surface in the roller support (0.3 to 0.4 µm wear depth)

x			
	x		

EA11003EN 00902[1]

		<b>CR pump CP4 - Diagnosis report</b>		Report no.		
				Date	3/31/2009	
Department:	Person responsible:	Telephone:	Use	internal		
Non-responsive content removed				external	x	
Department:	Person responsible:	Telephone:	Confidentiality note Confidential			

**3.3 High pressure**

No striking feature

x		
---	--	--

**3.4 Bearing**

No striking feature

x		
---	--	--

**3.5 Shaft seal**

No striking feature

x		
---	--	--

**3.6 Holes**

No striking feature

x		
---	--	--

**3.7 Attached components (Metering Unit, Overflow Valve, Counting Point)**

No striking feature

x		
---	--	--

**3.8 O-rings**


No striking feature

x		
---	--	--

**3.9 Other**

No striking feature

x		
---	--	--

**3.10 Images**Appendix 1,  
measurement 1Appendix 1,  
measurement 2**4. Hydraulic function**

	n [rpm]	p <sub>rail</sub> [bar]	I <sub>ZME</sub> [A]	Delivery rate [l/h] of new part 05.14.2008	Delivery rate [l/h] after testing 02.02.2009	
Starting point	200	200	0.4	4.1	4.1	x
1.000 rpm, p <sub>rated</sub>	1000	1800	0.4	16.8	16.9	x
n <sub>max</sub> p <sub>500bar</sub>	3375	500	0.4	65	65.6	x

TCD (technical customer documentation) testing point LG (1,000 rpm, p<sub>rated</sub> ≥ 15.5 or 15.2 l/h after running time) is met.**6. Destiny of parts**

The pump is stored at RB until 12/2010 and then scrapped.


**7. Attachments**

Appendix 1: WLI (white-light interferometry) measurement of the roller support running surface


tested:	Non-responsive content removed	Telephone	Non-responsive content removed	Date:	04.09.2009	Signature:	Non-responsive content removed
Department:		Telephone		Date:	04.21.2009	Signature:	

# Measurement 1



Appendix 1





# Measurement 2







 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.													
				Date	7/16/2009												
Department:	Person responsible:	Telephone:	internal														
Non-responsive content removed			external x														
To:	Non-responsive content removed																
For information:																	
<b>Pump type:</b> CP4.1S_398_2x6_REC_3.3_1.95_MT4.2	<b>Customer:</b> VW	<b>Project:</b> R4 2.0 EU5	<b>Project / design pattern type</b> C / C														
<b>Part number (TTNo.):</b> 0445B21116_06	<b>Date of manufacture:</b> 00890	<b>Serial number:</b> 4631	<b>Manufacturing plant - line</b> 011M FeP (Feuerbach plant)-M														
<b>SAP-No.:</b> 30-101581-07	<b>Samos no.:</b> 742724	<b>Customer order no.:</b>	<b>Engine/Vehicle number</b> 03LL000116														
<b>VA / ETC no.:</b> DS-222364	<b>Endurance run type [customer]:</b> Engine endurance run	<b>Endurance run conditions:</b> Profile PZD	<b>DSBFD no.:</b> 25335														
<b>Mileage</b>	<b>Actual mileage is [h]</b> 697 h	<b>Fuel:</b>	<b>Confidentiality note</b> Confidential														
<h3>1. Subject</h3> <p>CP4 customer returns <b>without complaint</b>  Engine number: 03LL000116, 125 kW, EU5  Mileage: 697 h, Profile PZD</p>																	
<h3>2. Conclusion</h3> <p><b>Function</b>  - Delivery rates after endurance run or test without significant fuel-quantity drift in comparison with the new state.</p> <p><b>Components</b>  - Wear through lateral roller slip-off in the right tappet assembly is increased, but not critical.  - C coating slightly worn on the running surface for roller in the roller support. Not critical.  - Spring plate shows slight indentations at the tappet side, but not critical.  - Wear of the remaining components is low and without significant striking features.</p> <p><b>Result</b>  - The pump has <b>passed the endurance run.</b></p>																	
<h3>3. Results of diagnosis (visual findings)</h3> <div style="display: flex; justify-content: space-between;"> <div> <p><b>3.1 Drive</b></p> <p>No striking feature</p> </div> <div> <p>Legend rating stages</p> <table border="1"> <tr> <td>OK</td> <td><div style="background-color: green; width: 15px; height: 15px; display: flex; align-items: center; justify-content: center;">x</div></td> <td><div style="background-color: yellow; width: 15px; height: 15px; display: flex; align-items: center; justify-content: center;">x</div></td> <td><div style="background-color: red; width: 15px; height: 15px; display: flex; align-items: center; justify-content: center;">x</div></td> </tr> <tr> <td>uncritical</td> <td></td> <td></td> <td></td> </tr> <tr> <td>Critical</td> <td></td> <td></td> <td></td> </tr> </table> </div> </div>						OK	<div style="background-color: green; width: 15px; height: 15px; display: flex; align-items: center; justify-content: center;">x</div>	<div style="background-color: yellow; width: 15px; height: 15px; display: flex; align-items: center; justify-content: center;">x</div>	<div style="background-color: red; width: 15px; height: 15px; display: flex; align-items: center; justify-content: center;">x</div>	uncritical				Critical			
OK	<div style="background-color: green; width: 15px; height: 15px; display: flex; align-items: center; justify-content: center;">x</div>	<div style="background-color: yellow; width: 15px; height: 15px; display: flex; align-items: center; justify-content: center;">x</div>	<div style="background-color: red; width: 15px; height: 15px; display: flex; align-items: center; justify-content: center;">x</div>														
uncritical																	
Critical																	
<p><b>3.2 Drivetrain</b></p> <p>Tappet assembly: Slightly increased lateral roller start-up (see Appendix 1, Figure 1 and 2). Roller support running surface for roller: C coating slightly worn - 0.5 µm depth (see Appendix 1, Figure 3 and 4). Spring plate - indentations in the base material (see Appendix 1, Figure 5).</p>																	
<p><b>3.3 High pressure</b></p> <p>No striking feature</p>																	
<p><b>3.4 Bearing</b></p> <p>No striking feature</p>																	
<p><b>3.5 Shaft seal</b></p> <p>No striking feature</p>																	

EA11003EN-00903[1]

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no. [REDACTED]	
				Date	7/16/2009
<b>Department:</b>	<b>Person responsible:</b>	<b>Telephone:</b>		internal	
Non-responsive content removed				external	x
<b>3.6 Holes</b>					
No striking feature					<input checked="" type="checkbox"/>
<b>3.7 Attached components (metering unit, overflow valve, counting point)</b>					
No striking features, see metering unit report					<input checked="" type="checkbox"/>
<b>3.8 Other</b>					
No striking feature					<input checked="" type="checkbox"/>
<b>3.9 Other</b>					
No striking feature					<input checked="" type="checkbox"/>
<b>4. Hydraulic function</b>					
				Delivery rate [l/h] of new part	Delivery rate [l/h] after testing
	n[rpm]	p_rail [bar]	I_MU [A]	10/22/2008	7/14/2009
LG	1000	1800	0.4	19.91	20.58
					<input checked="" type="checkbox"/>
No significant volumetric efficiency change, the volumetric efficiency is within the tolerance specified in the TCD (technical customer documentation) for new parts.					
<b>5. Destiny of the parts</b>					
The pump will be kept at Jihlava plant after consultation with [REDACTED] and scrapped after six months.					
<b>6. Attachments</b>					
Appendix 1 - Photos					
Appendix 2 - metering unit report UB VW DS-222 364 DNA ZVM20015					
<b>Tested:</b>	Non-responsive content removed	<b>Phone</b>	Non-responsive content removed	<b>Date:</b>	
<b>Department:</b>		<b>Phone</b>		<b>Date:</b>	

EA11003EN-00904101

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.		
				Date	7/14/2009	
<b>Department:</b>	<b>Person responsible:</b>	<b>Telephone:</b>		Use	internal	
Non-responsive content removed					external	x
To:	Non-responsive content removed					
For information:						
<b>Pump type:</b> CP4.1S_398_2x6_REC_3,3_1,95_MT4,2		<b>Customer:</b> VW	<b>Project:</b> R4 2.0 EU5	<b>Project / design pattern type</b> C / C		
<b>Part number (TTNo.):</b> 0445B21116_06		<b>Date of manufacture:</b> 00890	<b>Serial number:</b> 4616	<b>Manufacturing plant - line</b> 011M FeP (Feuerbach plant)-M		
<b>SAP-No.:</b> 30-101581-07		<b>Samos no.:</b> 742718	<b>Customer order no.:</b>	<b>Engine/Vehicle number</b> 03LL000125		
<b>VA / ETC no.:</b> DS-222365		<b>Endurance run type [customer]:</b> Vehicle endurance run	<b>Endurance run conditions:</b> Profile GDV-EWP (Ehra variable track for passenger cars)	<b>DSBFD no.:</b> 25339		
<b>Mileage</b>		<b>Actual mileage is [h]</b> 103504 km	<b>Fuel:</b>	<b>Confidentiality note</b> Confidential		

### 1. Subject

CP4 customer returns **without complaint**  
 Engine number: 03LL000125, 125 kW, EU5  
 Mileage: 103,504 km; Profile GDV EWP

### 2. Conclusion

**Function**  
 - Delivery rates after endurance run or test without significant fuel-quantity drift in comparison with the new state.

**Components**  
 - Wear through lateral roller slip-off in the tappet assembly is increased, but not critical.  
 - Wear of the remaining components is low and without significant striking features.

**Result**  
 - The pump has **passed the endurance run.**

### 3. Results of diagnosis (visual findings)

**3.1 Drive**  
No striking feature

**3.2 Drivetrain**  
Tappet assembly: Slightly increased lateral roller slip-off (see 3.10 Figures 1 and 2)

**3.3 High pressure**  
No striking feature

**3.4 Bearing**  
No striking feature

**3.5 Shaft seal**  
No striking feature

**3.6 Holes**  
No striking feature

**3.7 Attached components (metering unit, overflow valve, counting point)**  
No striking features, see metering unit report

**3.8 O-rings**  
No striking feature

Legend rating stages

OK

uncritical

Critical

x		
	x	
		x

x		
---	--	--

	x	
--	---	--

x		
---	--	--

x		
---	--	--

x		
---	--	--





x		
---	--	--



x		
---	--	--



EA11003EN-00904[1]

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no. <span style="background-color: black; color: black;">[REDACTED]</span>					
				Date	7/14/2009				
<b>Department:</b>		<b>Person responsible:</b>		<b>Telephone:</b>					
Non-responsive content removed		<span style="background-color: black; color: black;">[REDACTED]</span>		Use <table border="1"> <tr> <td>internal</td> <td></td> </tr> <tr> <td>external</td> <td>x</td> </tr> </table>		internal		external	x
internal									
external	x								
<b>3.9 Other</b> No striking feature									
<b>3.10 Images</b>									
									
Fig. 1: Roller - housing-side			Fig. 2: Tappet body - housing-side						
<b>4. Hydraulic function</b>									
				Delivery rate [l/h] of new part	Delivery rate [l/h] after testing				
	n[rpm]	p_rail [bar]	I_MU [A]	10/22/2008	7/13/2009				
LG	1000	1800	0.4	19.99	19.81				
				<span style="background-color: green; color: white;">x</span>					
No significant volumetric efficiency change, the volumetric efficiency is within the tolerance specified in the TCD (technical customer documentation) for new parts.									
<b>5. Destiny of the parts</b>									
The pump remains after consultation with <span style="background-color: black; color: black;">[REDACTED]</span> plant and will be scrapped after 6 months.									
<b>6. Attachments</b>									
Metering unit report UB VW DS-222365 DNA ZVM20016									
<b>Tested:</b>	<span style="background-color: black; color: black;">[REDACTED]</span>	<b>Phone</b>	<span style="background-color: black; color: black;">[REDACTED]</span>	<b>Date:</b>	8/27/2009				
<b>Signature:</b>	<span style="background-color: black; color: black;">[REDACTED]</span>	<b>Signature:</b>	<span style="background-color: black; color: black;">[REDACTED]</span>	<b>Date:</b>	8/27/2009				
<b>Department:</b>	<span style="background-color: black; color: black;">[REDACTED]</span>	<b>Phone</b>	<span style="background-color: black; color: black;">[REDACTED]</span>	<b>Date:</b>	8/27/2009				
<b>Signature:</b>	<span style="background-color: black; color: black;">[REDACTED]</span>	<b>Signature:</b>	<span style="background-color: black; color: black;">[REDACTED]</span>	<b>Date:</b>	8/27/2009				

EA11003EN-00905[0]

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.	
				Date	7/16/2009
<b>Department:</b>	<b>Person responsible:</b>	<b>Telephone:</b>	Use	internal	
Non-responsive content removed				external	x
To: Non-responsive content removed For information:					
<b>Pump type:</b>	<b>Customer:</b>	<b>Project:</b>	<b>Project / design pattern type</b>		
CP4.1S_398_2x6_REC_3.3_1.95_MT4.2	VW	R4 2.0 EU5	D/D		
<b>Part number (TTNo.):</b>	<b>Date of manufacture:</b>	<b>Serial number:</b>	<b>Manufacturing plant - line</b>		
0445B21116_07	141108	0477	5150 JhP (Jihlava plant) -		
<b>SAP-No.:</b>	<b>Samos no.:</b>	<b>Customer order no.:</b>	<b>Engine/Vehicle number</b>		
30-101581-07	742720		03LL000264		
<b>VA / ETC no.:</b>	<b>Endurance run type [customer]:</b>	<b>Endurance run conditions:</b>	<b>DSBFD no.:</b>		
DS-222366	Engine endurance run	Profile endurance run 2+ÖVL	25336		
<b>Mileage</b>	<b>Actual mileage is [h]</b>	<b>Fuel:</b>	<b>Confidentiality note</b>		
	545 h		Confidential		

### 1. Subject

CP4 customer returns **without complaint**  
 Engine no.: 03LL000264, 125 kW, EU5  
 Mileage: 545h, Profile endurance run 2+ÖVL

### 2. Conclusion

**Function**  
 - Delivery rates after endurance run or test without significant fuel-quantity drift in comparison with the new state.

**Components**  
 - Wear through lateral roller slip-off in the tappet assembly is increased, but not critical.  
 - Wear of the remaining components is low and without significant striking features.

**Result**  
 - The pump has **passed the endurance run**.

### 3. Results of diagnosis (visual findings)

**3.1 Drive**  
No striking feature

**3.2 Drivetrain**  
Tappet assembly: Slightly increased lateral roller slip-off (see 3.10 Figures 1 and 2)

**3.3 High pressure**  
No striking feature

**3.4 Bearing**  
No striking feature

**3.5 Shaft seal**  
No striking feature

**3.6 Holes**  
No striking feature

**3.7 Attached components (metering unit, overflow valve, counting point)**  
No striking features, see metering unit report

**3.8 O-rings**  
No striking feature

Legend rating stages {
 

OK

uncritical

Critical

x		
	x	
		x

x		
	x	

x		
---	--	--

x		
---	--	--

x		
---	--	--



  

x		
---	--	--

x		
---	--	--

EA11003EN-00905[1]

 <b>BOSCH</b> 	<b>CR pump CP4 - Diagnosis report</b>		Report no.	
			Date	7/14/2009

<b>Department:</b>	<b>Person responsible:</b>	<b>Telephone:</b>	Use	internal	
Non-responsive content removed				external	<b>x</b>

**3.9 Other**

No striking feature


**3.10 Images**

Fig. 1: Roller - housing-side




Fig. 2: Tappet body - housing-side

**4. Hydraulic function**

				Delivery rate [l/h] of new part	Delivery rate [l/h] after testing
	n[rpm]	p_rail [bar]	I_MU [A]	11/14/2008	7/14/2009
LG	1000	1800	0.4	20.25	20.82

<b>x</b>		
----------	--	--

No significant volumetric efficiency change, the volumetric efficiency is within the tolerance specified in the TCD (technical customer documentation) for new parts.

**5. Destiny of the parts**

The pump remains after consultation with Mr. [redacted] plant and will be scrapped after 6 months.



**6. Attachments**

Metering unit report UB VW DS-222366 DNA ZVM20017.

<b>Tested:</b>	Non-responsive content removed	Phone	Non-responsive content removed	Date:		Signature:	
<b>Department:</b>		Phone		Date:		Signature:	



EA11003EN-00906[0]

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.	[REDACTED]	
				Date	3/15/2010	
<b>Department:</b>	<b>Person responsible:</b>	<b>Telephone:</b>		Use	internal	
Non-responsive content removed					external	x
To:	Non-responsive content removed					
For information:						
<b>Pump type:</b> CP4.1S_448_2x6,75_REC_3,3_1,95_MT4,6	<b>Customer:</b> VW	<b>Project:</b> R4 2,0L EA189_2 EU5	<b>Project / design pattern type</b> B / C			
<b>Part number (TTNo.):</b> 0445B21088	<b>Date of manufacture:</b> 883	<b>Serial number:</b> 4536	<b>Manufacturing plant - line</b> 011M FeP (Feuerbach plant)-M			
<b>SAP-No.:</b> 30-101581-07	<b>Samos no.:</b> 750778	<b>Customer order no.:</b>	<b>Engine/Vehicle number</b> 03LP000051			
<b>MAP-No.</b> DS-227335	<b>Endurance run type [customer]:</b> Vehicle endurance run	<b>Endurance run conditions:</b> Profile EWP (Ehra variable track for passenger cars)	<b>DSBFD no.:</b> 26013			
<b>Desired mileage [km]</b>	<b>Actual mileage is [h]</b> 100000 km	<b>Fuel:</b>	<b>Confidentiality note</b> Confidential			

### 1. Subject

CP4 customer returns **without complaint**  
 Engine number: 03LP000051 SE250-0-0085, emission standard EU5  
 Running time: 100,000 km, Profile of Ehra variable track for passenger cars

### 2. Conclusion

**Function**  
 - Delivery rates after endurance run or test without significant fuel-quantity drift in comparison with the new state.

**Components**  
 - Wear of the components is low and without any striking features.

**Result**  
 - The pump has **passed the endurance run**.

### 3. Results of diagnosis (visual findings)

**3.1 Drive**  
No striking feature

**3.2 Drivetrain**  
No striking feature

**3.3 High pressure**  
No striking feature

**3.4 Bearing**  
No striking feature

**3.5 Shaft seal**  
No striking feature

**3.6 Holes**  
No striking feature

**3.7 Attached components (metering unit, overflow valve, counting point)**  
No striking feature

**3.8 O-rings**  
No striking feature

Legend rating stages

{

OK

uncritical

Critical

x		
	x	
		x

x		
---	--	--

x		
---	--	--

x		
---	--	--

x		
---	--	--

x		
---	--	--












  

x		
---	--	--



  

x		
---	--	--

EA11003EN-00906[1]

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no. 	
				Date	3/15/2010
<b>Department:</b> Non-responsive content removed		<b>Person responsible:</b> 		<b>Telephone:</b> 	
				Use	internal <input type="checkbox"/> external <input checked="" type="checkbox"/>
<b>3.9 Other</b> No striking feature					
<div style="text-align: right;"> <input checked="" type="checkbox"/> </div>					
<b>4. Hydraulic function</b>					
				Delivery rate [l/h] of new part	Delivery rate [l/h] after testing
	n[rpm]	p_rail [bar]	I_MU [A]	4/11/2008	10/8/2009
LG	1000	1800	0.4	19.38	19.93
<div style="text-align: right;"> <input checked="" type="checkbox"/> </div>					
No significant volumetric efficiency change, the volumetric efficiency is within the tolerance specified in the TCD (technical customer documentation) for new parts.					
<b>5. Destiny of the parts</b>					
The pump will be scrapped at the request of VW.					
<b>6. Attachments</b>					
None					
<b>Tested:</b>		Phone		Date:	3/16/2010
<b>Signature:</b>					
<b>Department:</b>		Phone		Date:	3/22/2010
<b>Signature:</b>					

EA11003EN-00908[0]

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.		
				Date	3/15/2010	
<b>Department:</b>	<b>Person responsible:</b>	<b>Telephone:</b>			internal	
Non-responsive content removed				Use	external	x
To:	Non-responsive content removed					
For information:						
<b>Pump type:</b> CP4.1S_398_2x6_REC_3,3_1.95_MT4,2		<b>Customer:</b> VW	<b>Project:</b> R4 2,0L EA189 2 EU5	<b>Project / design pattern type</b> C / C		
<b>Part number (TTNo.):</b> 0445B21116_03		<b>Date of manufacture:</b> 890	<b>Serial number:</b> 4560	<b>Manufacturing plant - line</b> 011M FeP (Feuerbach plant)-M		
<b>SAP-No.:</b> 30-101581-07		<b>Samos no.:</b> 750778	<b>Customer order no.:</b>	<b>Engine/Vehicle number</b> 03LP000051		
<b>MAP-No.</b> DS-227336		<b>Endurance run type [customer]:</b> Vehicle endurance run	<b>Endurance run conditions:</b> Profile EWP (Ehra variable track for passenger cars)	<b>DSBFD no.:</b> 26012		
<b>Mileage</b>		<b>Actual mileage is [h]</b> 100000 km	<b>Fuel:</b>	<b>Confidentiality note</b> Confidential		

### 1. Subject

CP4 customer returns **without complaint**  
 Engine-No.:03LL0000069 103kW, VW 416-0-0075  
 EU5 emission standard, running time: 100,000 km, Profile of Ehra variable track for passenger cars

### 2. Conclusion

**Function**  
 - Delivery rates after endurance run or test without significant fuel-quantity drift in comparison with the new state.

**Components**  
 - Wear of the components is low and without any striking features.

**Result**  
 - The pump has **passed the endurance run**.

### 3. Results of diagnosis (visual findings)

**3.1 Drive**  
No striking feature

**3.2 Drivetrain**  
No striking feature

**3.3 High pressure**  
No striking feature

**3.4 Bearing**  
No striking feature

**3.5 Shaft seal**  
No striking feature

**3.6 Holes**  
No striking feature

**3.7 Attached components (metering unit, overflow valve, counting point)**  
No striking feature

**3.8 O-rings**  
No striking feature

Legend rating stages {

OK

x		
	x	
		x

uncritical

Critical

x		
---	--	--

x		
---	--	--

x		
---	--	--

x		
---	--	--

x		
---	--	--

x		
---	--	--

x		
---	--	--

x		
---	--	--

x		
---	--	--

x		
---	--	--

x		
---	--	--

x		
---	--	--



x		
---	--	--

x		
---	--	--

x		
---	--	--



EA11003EN-00908[1]

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no. <span style="background-color: black; color: black;">[REDACTED]</span>	
				Date	3/15/2010
<b>Department:</b>	<b>Person responsible:</b>	<b>Telephone:</b>		Use	<input type="checkbox"/> internal <input checked="" type="checkbox"/> external
Non-responsive content removed		<span style="background-color: black; color: black;">[REDACTED]</span>			
<b>3.9 Other</b> No striking feature <div style="text-align: right;"> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> </div>					
<b>4. Hydraulic function</b>					
				Delivery rate [l/h] of new part	Delivery rate [l/h] after testing
	n[rpm]	p_rail [bar]	I_MU [A]	10/13/2008	10/8/2009
G	1000	1800	0.4	19.73	19.74
				<input checked="" type="checkbox"/>	<input type="checkbox"/>
No significant volumetric efficiency change, the volumetric efficiency is within the tolerance specified in the TCD (technical customer documentation) for new parts.					
<b>5. Destiny of the parts</b>					
The pump will be scrapped at the request of Audi.					
<b>6. Attachments</b>					
None					
<b>Tested:</b>	Non-responsive content removed	Phone	Non-responsive content removed	Date:	3/16/2010
<b>Signature:</b>	<span style="background-color: black; color: black;">[REDACTED]</span>				
<b>Department:</b>	<span style="background-color: black; color: black;">[REDACTED]</span>	Phone	<span style="background-color: black; color: black;">[REDACTED]</span>	Date:	3/22/2010
<b>Signature:</b>	<span style="background-color: black; color: black;">[REDACTED]</span>				

<b>Pump type:</b> CP4.1S_348_2x5,25_REC_3,3_1,95_MT4,2	<b>Customer:</b> VW	<b>Project:</b> R4 EU5	<b>Project / design pattern type</b> Series / Series
<b>Part number (TTNo.):</b> 0445010507	<b>Date of manufacture:</b> 140508	<b>Serial number:</b> 1158	<b>Manufacturing plant - line</b> 5150 JhP (Jihlava plant) - 03
<b>Actual mileage is [h]</b> 30000 km	<b>Fuel:</b> no information		
<b>SAP-No.:</b> 30-052021-04			<b>Engine/Vehicle number</b> CBBB 01001 / TRUZZZ8J891003028
<b>Customer part number</b> 03L 130 755			<b>Endurance run conditions:</b> Field

**Complaint:** Drivetrain damage

## 1. Subject

CP4 customer returns with complaint from France. (Breakdown) engine no. CBBB 2.0l TDI / 125 kW. (Volkswagen engine installed in an Audi TT Coupe.) Vehicle identification no.: TRUZZZ8J891003028

Pump was disassembled in RB-Jihlava and delivered to the product development.

## 2. Conclusion

## Function

- Due to the drivetrain damage, no functional test was performed.

## Components

- Drivetrain damage category I (global, abrasive wear)
- As a result, particle marks and grooves through particles on most components (bearings, tappet holes, contact area of HP piston and roller support, etc.)
- Due to the progression of damage, detailed analysis on the cam track, the roller support and roller is no longer possible.
- The anti-friction paint on the spring plate is partly entrained or ruptured.

## Result

- Possible damage hypothesis:

Material fatigue and rupture of the roller led probably to the increased slip between roller and cam track (stiff roller) on the tappet assembly in this failure case. Consequently, there was abrasive wear of drivetrain parts and a final turned tappet by 90°. Possible cause for the development of flat spots and stiff rollers for CP4 pumps is the value falling below the minimum viscosity limit:

- Which may have been initiated by wrong fueling, such as kerosene or diesel fuel.
  - By overheating of the diesel fuel.
- Furthermore, flat spots and stiff rollers are also created through:
- Commissioning with air in the drivetrain compartment.
  - C coating defect, fusing in the roller support hole or metal chips on the lateral surface of roller.

- Omission of the anti-friction paint of the spring plate (no suggestions) in the series.
- The pump is to be assessed as on-field failure.

### **3. Results of diagnosis (visual findings)**

### 3.1 Drive

- No significant wear

Legend rating stages { OK  
uncritical  
Critical

X		
	X	
		X



  

X		
---	--	--

### 3.2 Drivetrain

- Camshaft, cam track Abrasive wear in the center of the cam track along the entire circumference of the cam due to the turned tappet (see Appendix 1, Figure 11 to 14)
- Tappet assembly:
  - Roller support, running surface of the roller: C coating is locally entrained (see Appendix 1, Fig. 16)
  - Roller support, HP piston contact surface: Particle indentations (see Appendix 1, Fig. 15)
  - Tappet body / roller support: Tappet body has rotated relative to the roller support (see Appendix 1, Figures 19 and 20).

			X
--	--	--	---



EA11003EN-00909[1]	 <b>BOSCH</b>		 <b>CP4</b>		<b>CR pump CP4 - Diagnosis report</b>		Report no.	
							Date	3/3/2010
<b>Department:</b> Non-responsive content removed		<b>Person responsible:</b> Non-responsive content removed		<b>Telephone:</b> Non-responsive content removed		Use	<input type="checkbox"/> internal <input checked="" type="checkbox"/> external	<input type="checkbox"/> <input checked="" type="checkbox"/> x
								<b>Confidentiality note</b> Confidential
To:		Non-responsive content removed						
For information:		Non-responsive content removed						

- Tappet body lateral surface: Grooves through particle drafts (consequential errors; see Appendix 1, Fig. 18) - Roller, roller surface: Abrasive wear around the entire circumference (see Appendix 1, Figures 9 and 10).				
<b>3.3 High pressure</b> - Running surface of piston high-pressure side (upper 50% of the piston length): Grooves through particles (see Appendix 1, Figure 8) - Piston base: Impressions through particles (see Appendix 1, Figure 7) - Anti-friction paint on the spring plate of the tappet spring is partially entrained, chipped (see Appendix 1, Figures 1 and 2)				<input checked="" type="checkbox"/>
<b>3.4 Bearing</b> - Bearing bush: radially melted (see Appendix 1, Fig. 4)				<input checked="" type="checkbox"/>
<b>3.5 Shaft seal</b> - No significant wear		<input checked="" type="checkbox"/>		
<b>3.6 Holes</b> - Tappet hole top and bottom, grooves and particle indentations (see Appendix 1, Figures 5 and 6)				<input checked="" type="checkbox"/>
<b>3.7 Attached components (Metering Unit, Overflow Valve, Counting Point)</b> - No significant wear		<input checked="" type="checkbox"/>		
<b>3.8 O-rings</b> - No significant wear		<input checked="" type="checkbox"/>		



<b>3.9 Other</b> - Metering unit, particle deposition in the O-ring space (see Appendix 1, Figure 17)				<input checked="" type="checkbox"/>			
<b>4. Hydraulic function</b> Assessment no longer possible							
<b>5. Destiny of the parts</b> The parts are returned to the Quality Assurance.							
<b>6. Attachments</b> Appendix 1 - Photos							
Tested:	Non-responsive content removed	Phone	Non-responsive content removed	Date:	11/16/2010	Signature:	Non-responsive content removed
Department:	Non-responsive content removed	Phone	Non-responsive content removed	Date:	12/21/2010	Signature:	Non-responsive content removed





EA11003EN-00910[0]

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.														
				Date	3/24/2010													
Department:		Person responsible:		Telephone:		Use												
Non-responsive content removed																		
						internal												
						external												
						X												
						Confidentiality note												
						Confidential												
To:	Non-responsive content removed																	
Cylinder head:																		
<b>Pump type:</b>		<b>Customer:</b>		<b>Project:</b>		<b>Project / design pattern type</b>												
CP4.1S_348_2x5,25_REC_3,3_1,95_MT4,2		VW		VW R4 2.0L EU5 CRS3.2 RPU		Series / Series												
<b>Part number (TTNo.):</b>		<b>Date of manufacture:</b>		<b>Serial number:</b>		<b>Manufacturing plant - line</b>												
445010507		161108				5150 JhP (Jihlava plant)												
<b>Actual mileage is [h]</b>		<b>Fuel:</b>				<b>MAP-No.</b>												
50000 km		Others				DS-241774												
<b>SAP-No.:</b>		<b>Samos no.:</b>		<b>Customer order no.:</b>		<b>Engine</b>												
30-101745-50						CDC000534												
<b>Customer part number</b>		<b>DSBFD no.:</b>		<b>Endurance run type [customer]:</b>		<b>Endurance run conditions:</b>												
CR/CP4S1/R35/20		27321		<b>Vehicle endurance run</b>		Argentina endurance run												
<b>1. Subject</b>  CP4 customer returns <b>without complaint</b> Engine no.: CDC000534 (Amarok), emission standard: EU5 Testing conditions: Argentina endurance run Mileage: 50,000km																		
<b>2. Conclusion</b>  <b>Function</b> Delivery rates after durability test without any significant striking features  <b>Components</b> Wear of the components is low. There are no significant striking features seen at the pump.  <b>Result</b> The pump has <b>passed the durability test.</b>																		
<b>3. Results of diagnosis (visual findings)</b>				Legend rating stages <table border="1"> <tr> <td>OK</td> <td>X</td> <td></td> <td></td> </tr> <tr> <td>Uncritical</td> <td></td> <td>X</td> <td></td> </tr> <tr> <td>Critical</td> <td></td> <td></td> <td>X</td> </tr> </table>			OK	X			Uncritical		X		Critical			X
OK	X																	
Uncritical		X																
Critical			X															
<b>3.1 Drive</b>				X														
No significant wear																		
<b>3.2 Drivetrain</b>				X														
No significant wear																		
<b>3.3 High pressure</b>				X														
No significant wear																		
<b>3.4 Bearing</b>				X														
No significant wear																		
<b>3.5 Shaft seal</b>				X														
No significant wear																		
<b>3.6 Holes</b>				X														
No significant wear																		

EA11003EN-00910[1]



 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.																																
				Date	7/9/2008																															
Department:	Person responsible:		Telephone:	Use	internal																															
Non-responsive content removed				external	X																															
<b>3.7 Attached components (Metering Unit, Overflow Valve, Counting Point)</b> No significant wear <table border="1" style="float: right;"> <tr><td>X</td><td></td><td></td></tr> <tr><td></td><td></td><td></td></tr> </table>							X																													
X																																				
<b>3.8 O-rings</b> No significant wear <table border="1" style="float: right;"> <tr><td>X</td><td></td><td></td></tr> <tr><td></td><td></td><td></td></tr> </table>							X																													
X																																				
<b>3.9 Other</b> No significant wear <table border="1" style="float: right;"> <tr><td>X</td><td></td><td></td></tr> <tr><td></td><td></td><td></td></tr> </table>							X																													
X																																				
<b>Hydraulic function</b> The pump function is within specification limits. There is no significant drift in comparison to the delivery measurement																																				
<table border="1"> <tr> <th></th> <th>n[rpm]</th> <th>p_rail [bar]</th> <th>I_MU [A]</th> <th>Delivery rate [l/h] of new part</th> <th>Delivery rate [l/h] after testing</th> </tr> <tr> <td></td> <td></td> <td></td> <td></td> <td>11/16/2008</td> <td>09.03.2010</td> </tr> <tr> <td>ST</td> <td>200</td> <td>200</td> <td>0.4</td> <td>4.1</td> <td>4.1</td> </tr> <tr> <td>LG</td> <td>1000</td> <td>1800</td> <td>0.4</td> <td>17.3</td> <td>17.3</td> </tr> </table>					n[rpm]	p_rail [bar]	I_MU [A]	Delivery rate [l/h] of new part	Delivery rate [l/h] after testing					11/16/2008	09.03.2010	ST	200	200	0.4	4.1	4.1	LG	1000	1800	0.4	17.3	17.3	<table border="1"> <tr><td>X</td><td></td><td></td></tr> <tr><td>X</td><td></td><td></td></tr> </table>			X			X		
	n[rpm]	p_rail [bar]	I_MU [A]	Delivery rate [l/h] of new part	Delivery rate [l/h] after testing																															
				11/16/2008	09.03.2010																															
ST	200	200	0.4	4.1	4.1																															
LG	1000	1800	0.4	17.3	17.3																															
X																																				
X																																				
<b>5 Destiny of the parts</b> The pump will be scrapped at the request of the client.																																				
Tested:	Non-responsive content removed	Telephone:	Non-responsive content removed	Date:	3/24/2010	Signature: Non-responsive content removed																														
Department:		Telephone:		Date:	3/25/2010	Signature: Non-responsive content removed																														

EA11003EN-00911101



 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.													
				Date	3/24/2010												
<b>Department:</b>	<b>Person responsible:</b>	<b>Telephone:</b>	Use														
Non-responsive content removed			internal <input type="checkbox"/> external <input checked="" type="checkbox"/>														
			<b>Confidentiality note</b>														
			Confidential														
To:	Non-responsive content removed																
For information:																	
<b>Pump type:</b>		<b>Customer:</b>	<b>Project:</b>	<b>Project / design pattern type</b>													
CP4.1S_348_2x5,25_REC_3,3_1,95_MT4,2		VW	VW R4 2.0L EU5 CRS3.2 RPU	Series / Series													
<b>Part number (TTNo.):</b>		<b>Date of manufacture:</b>	<b>Serial number:</b>	<b>Manufacturing plant - line</b>													
0445010507		161108		5150 JhP (Jihlava plant)													
<b>Actual mileage is [h]</b>		<b>Fuel:</b>		<b>MAP-No.</b>													
50000 km		Others		DS-241774													
<b>SAP-No.:</b>		<b>Samos no.:</b>	<b>Customer order no.:</b>	<b>Engine/Vehicle number</b>													
30-101745-50		768619		CDC000534													
<b>Customer part number</b>		<b>DSBFD no.:</b>	<b>Endurance run type [customer]:</b>	<b>Endurance run conditions:</b>													
CR/CP4S1/R35/20		27321	Vehicle endurance run	Argentina endurance run													
<b>1. Subject</b>																	
CP4 customer returns <b>without complaint</b> Engine no.: CDC000534 (Amarok), emission standard: EU5 Testing conditions: Argentina endurance run Mileage: 50,000km																	
<b>2. Conclusion</b>																	
<b>Function</b>																	
Delivery rates after endurance run without any significant striking features.																	
<b>Components</b>																	
Wear of the components is low. There are no significant striking features seen at the pump.																	
<b>Result</b>																	
- The pump has <b>passed the endurance run.</b>																	
<b>3. Results of diagnosis (visual findings)</b>			Legend rating stages { <table border="1"> <tr> <td>OK</td> <td><input checked="" type="checkbox"/></td> <td><input type="checkbox"/></td> <td><input type="checkbox"/></td> </tr> <tr> <td>uncritical</td> <td><input type="checkbox"/></td> <td><input checked="" type="checkbox"/></td> <td><input type="checkbox"/></td> </tr> <tr> <td>Critical</td> <td><input type="checkbox"/></td> <td><input type="checkbox"/></td> <td><input checked="" type="checkbox"/></td> </tr> </table>			OK	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	uncritical	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Critical	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
OK	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>														
uncritical	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>														
Critical	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>														
<b>3.1 Drive</b>																	
No significant wear			<table border="1"> <tr> <td><input checked="" type="checkbox"/></td> <td><input type="checkbox"/></td> <td><input type="checkbox"/></td> </tr> </table>			<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>									
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>															
<b>3.2 Drivetrain</b>																	
No significant wear			<table border="1"> <tr> <td><input checked="" type="checkbox"/></td> <td><input type="checkbox"/></td> <td><input type="checkbox"/></td> </tr> </table>			<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>									
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>															
<b>3.3 High pressure</b>																	
No significant wear			<table border="1"> <tr> <td><input checked="" type="checkbox"/></td> <td><input type="checkbox"/></td> <td><input type="checkbox"/></td> </tr> </table>			<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>									
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>															
<b>3.4 Bearing</b>																	
No significant wear			<table border="1"> <tr> <td><input checked="" type="checkbox"/></td> <td><input type="checkbox"/></td> <td><input type="checkbox"/></td> </tr> </table>			<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>									
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>															
<b>3.5 Shaft seal</b>																	
No significant wear			<table border="1"> <tr> <td><input checked="" type="checkbox"/></td> <td><input type="checkbox"/></td> <td><input type="checkbox"/></td> </tr> </table>			<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>									
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>															



EA11003EN-009111[1]

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.			
				Date		3/24/2010	
<b>Department:</b> Non-responsive content removed		<b>Person responsible:</b> Non-responsive content removed		<b>Telephone:</b> Non-responsive content removed		Use <input type="checkbox"/> internal <input checked="" type="checkbox"/> external	
						<b>Confidentiality note</b> Confidential	
<b>3.6 Holes</b> No significant wear						<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	
<b>3.7 Attached components (metering unit, overflow valve, counting point)</b> No significant wear						<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	
<b>3.8 O-rings</b> No significant wear						<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	
<b>3.9 Other</b> No significant wear						<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	
<b>4. Hydraulic function</b> The pump function is within specification limits. There is no significant drift in comparison to the delivery measurement							
				Delivery rate [l/h] of new part	Delivery rate [l/h] after testing		
	n[rpm]	p_rail [bar]	I MU [A]	11/16/2008	3/9/2010		
ST	200	200	0.4	4.1	4.1	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	
LG	1000	1800	0.4	17.3	17.3	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	
<b>5. Destiny of the parts</b> The pump will be scrapped at the request of the client.							
<b>Tested:</b>	Non-responsive content removed	Phone	Non-responsive content removed	Date:	3/24/2010	Signature:	Non-responsive content removed
<b>Department:</b>		Phone		Date:	3/25/2010	Signature:	

EA11003EN-00912[0]

Report no. 7/14/2010		Date		<b>CR pump CP4 diagnosis report</b>		 <b>BOSCH</b> 	
<input type="checkbox"/> internal <input checked="" type="checkbox"/> external		Use		Telephone:		Person responsible:	
Confidentiality note Confidential		Non-responsive content removed		Department:		Non-responsive content removed	
Non-responsive content removed						To: For information:	
Project / design pattern type Series / Series		Project: VW R4 2.0L EU5 CRS3.2 RPU		Customer: VW		Pump type: CP4.1S_348_2x5,25_REC_3,3_1,95_MT4,2	
Manufacturing plant - line 5150 JhP (Jihlava plant) - 03		Serial number: 1383		Date of manufacture: 260109		Part number (TTNo.): 0445010507	
MAP-No. DS-241775				Fuel: Others		Actual mileage is [h] 100000 km	
Engine / vehicle number		Customer order no.: CR/CP4S1/R35/20		Samos no.: 768619		SAP-No.: 30-101745-50	
Endurance run conditions: Argentina returns		Endurance run type [customer]: Vehicle endurance run		DSBFD no.: 27322		Customer part number CR/CP4S1/R35/20	

### 1. Subject

CP4 customer returns **without complaint**  
 Engine no.: CDC000018 (Amarok)  
 Testing conditions: Vehicle endurance testing in Argentina  
 Mileage: 100,000 km, emission standard: EU5

### 2. Conclusion

**Function**  
 Delivery rates after endurance run without any significant striking features

**Components**  
 C coating ruptures on the roller support in allowable size. The C coating ruptures are not due to the endurance run conditions and have no effect on function and service life.  
 The wear of the components is low. There are no significant striking features seen at the pump.

**Result**  
 The pump has **passed** the endurance run.

### 3. Diagnosis Results (visual findings)

Legend rating stages

OK  
 uncritical  
 critical



x		
	x	
		x

<b>3.1 Drive</b> No significant striking features	<div style="display: flex; align-items: center;"> <div style="background-color: green; width: 20px; height: 15px; margin-right: 5px;"></div> <div style="width: 20px; height: 15px; border: 1px solid black; margin-right: 5px;"></div> <div style="width: 20px; height: 15px; border: 1px solid black;"></div> </div>
<b>3.2 Drivetrain</b> C coating ruptures on the roller support in allowable size.	<div style="display: flex; align-items: center;"> <div style="background-color: green; width: 20px; height: 15px; margin-right: 5px;"></div> <div style="width: 20px; height: 15px; border: 1px solid black; margin-right: 5px;"></div> <div style="width: 20px; height: 15px; border: 1px solid black;"></div> </div>
<b>3.3 High pressure</b> No significant striking features	<div style="display: flex; align-items: center;"> <div style="background-color: green; width: 20px; height: 15px; margin-right: 5px;"></div> <div style="width: 20px; height: 15px; border: 1px solid black; margin-right: 5px;"></div> <div style="width: 20px; height: 15px; border: 1px solid black;"></div> </div>
<b>3.4 Bearing</b> No significant striking features	<div style="display: flex; align-items: center;"> <div style="background-color: green; width: 20px; height: 15px; margin-right: 5px;"></div> <div style="width: 20px; height: 15px; border: 1px solid black; margin-right: 5px;"></div> <div style="width: 20px; height: 15px; border: 1px solid black;"></div> </div>
<b>3.5 Shaft seal</b>	

EA11003EN-00912[1]

No significant striking features	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>

<div style="background-color: black; width: 100px; height: 15px; margin-bottom: 5px;"></div> 7/14/2010	Report no. Date	<b>CR pump CP4 diagnosis report</b>		<b>BOSCH</b>						
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 10%; text-align: center;">Use</td> <td style="width: 10%; text-align: center;">intern al</td> <td style="width: 10%; text-align: center;">extern al</td> </tr> <tr> <td style="text-align: center;"><input checked="" type="checkbox"/></td> <td></td> <td></td> </tr> </table>		Use	intern al	extern al	<input checked="" type="checkbox"/>			Telephone: <div style="background-color: black; width: 100%; height: 15px; margin-top: 5px;"></div>	Person responsible: <div style="background-color: black; width: 100%; height: 15px; margin-top: 5px;"></div>	Department: <div style="background-color: black; width: 100%; height: 15px; margin-top: 5px;"></div>
Use	intern al	extern al								
<input checked="" type="checkbox"/>										
<b>Confidentiality note</b> Confidential										
<b>3.6 Holes</b> No significant wear <div style="float: right; text-align: right;"> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> </div>										
<b>3.7 Attached components (Metering Unit, Overflow Valve, Counting Point)</b> No significant wear <div style="float: right; text-align: right;"> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> </div>										
<b>3.8 O-rings</b> No significant wear <div style="float: right; text-align: right;"> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> </div>										
<b>3.9 Other</b> No significant wear <div style="float: right; text-align: right;"> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> </div>										
<b>3.10 Images</b>										
<div style="display: flex; justify-content: space-around; align-items: flex-start;"> <div style="text-align: center;">  <p>Fig. 1: Roller support to the right C coating ruptures ruptures</p> </div> <div style="text-align: center;">  <p>Image 2: Roller support to the right C coating</p> </div> </div>										



EA11003EN-00912[2]

**4. Hydraulic function**

- The pump function is within specification limits. There is no significant drift in comparison to the delivery measurement

Delivery rate [l/h] After testing	Delivery rate [l/h] New part					
3/9/2010	1/26/2009	I_MU [A]	p_rail [bar]	n[rpm]		
17.7	17.6	0.4	200	200	ST	<input type="checkbox"/>
4.3	4.2	0.4	1800	1000	LG	<input checked="" type="checkbox"/>

**5. Destiny of the parts**








The pump will be scrapped at the request of the client.

**6. Attachments**

None

<b>Tested:</b>	Non-responsive content removed	Telephone:	Non-responsive content removed	Date:	7/19/2010	Signature:	Non-responsive content removed
Department:		Telephone:		Date:	7/20/2010	Signature:	

EA11003EN-00913[0]

Report no. 7/14/2010		Date		CR pump CP4 diagnosis report		 <b>BOSCH</b> 	
<input checked="" type="checkbox"/> internal <input type="checkbox"/> external		Use		Telephone:		Person responsible:	
				Non-responsive content removed		Department:	
Confidentiality note Confidential							
Non-responsive content removed						To:	
						For information:	
Project / design pattern type Series / Series		Project: R4 2.0L EU5 RPU		Customer: VW		Pump type: CP4.1S_348_2x5,25_REC_3,3_1,95_MT4,2	
Manufacturing plant - line 5150 JhP (Jihlava plant) - 03		Serial number: 1383		Date of manufacture: 260109		Part number (TTNo.): 0445010507	
MAP-No. DS-241775				Fuel: Others		Actual mileage is [h] 100000 km	
Engine / vehicle number		Customer order no.: CR/CP4S1/R35/20		Samos no.: 768619		SAP-No.: 30-101745-50	
Endurance run conditions: Argentina returns		Endurance run type [customer]: Engine endurance run		DSBFD no.: 27322		Customer part number CR/CP4S1/R35/20	
<h3>1. Subject</h3> <p>CP4 customer returns <b>without complaint</b>          Engine no.: CDC000018 (Amarok)          Testing conditions: Vehicle endurance run in Argentina          Mileage: 100,000 km, emission standard: EU5</p>							
<h3>2. Conclusion</h3> <p><b>Function</b>          Delivery rates after endurance run without any significant striking features</p> <p><b>Components</b>          C coating ruptures on the roller support in allowable size. The C coating ruptures are not due to the endurance run conditions and have no effect on function and durability and service life.          The wear of the components is low. There are no significant striking features seen at the pump.</p> <p><b>Result</b>          The pump has <b>passed</b> the endurance run.</p>							
<h3>3. Diagnosis Results (visual findings)</h3>				Legend rating stages		OK uncritical Critical	
<h4>3.1 Drive</h4> <p>No significant wear</p>							
<h4>3.2 Drivetrain</h4> <p>C coating ruptures on the roller support in allowable size.</p>							
<h4>3.3 High pressure</h4> <p>No significant wear</p>							
<h4>3.4 Bearing</h4> <p>No significant wear</p>							
<h4>3.5 Shaft seal</h4> <p>No significant wear</p>							

EA11003EN-00913[1]

<div style="background-color: black; width: 100px; height: 20px; margin-bottom: 5px;"></div> <div style="border: 1px solid black; padding: 2px;">7/14/2010</div>	Report no. <div style="border: 1px solid black; padding: 2px;">Date</div>	<b>CR pump CP4 diagnosis report</b>	 					
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 10%; text-align: center;">X</td> <td style="width: 10%;">internal</td> <td rowspan="2" style="width: 10%; text-align: center; vertical-align: middle;">Use</td> </tr> <tr> <td></td> <td>external</td> </tr> </table>	X	internal	Use		external	Telephone: <div style="background-color: black; width: 100%; height: 1.2em;"></div>	Person responsible: <div style="background-color: black; width: 100%; height: 1.2em;"></div>	Department: <div style="background-color: black; width: 100%; height: 1.2em;"></div>
X	internal	Use						
	external							
Confidentiality note Confidential								

**3.6 Holes**  
No significant wear

**3.7 Attached components (Metering Unit, Overflow Valve, Counting Point)**  
No significant wear

**3.8 O-rings**  
No significant wear

**3.9 Other**  
No significant wear

**3.10 Images**

Fig. 1: Roller support to the right C coating ruptures

Image 2: Roller support to the right C coating ruptures

		x
		x
		x
		x

**4. Hydraulic function**

The pump function is within specification limits. There is no significant drift in comparison to the delivery measurement

	n[rpm]	p_rail [bar]	I_MU [A]	Delivery rate [l/h] of new part	Delivery rate [l/h] after testing
				1/26/2009	3/9/2010
ST	200	200	0.4	17.6	17.7
LG	1000	1800	0.4	4.2	4.3

		x
		x

**5. Destiny of the parts**



The pump will be scrapped at the request of the client.



EA11003EN-00913[2]

<b>6. Attachments</b> None							
<b>Tested:</b>	Non-responsive content removed	<b>Telephone:</b>	Non-responsive content removed	<b>Date:</b>	7/19/2010	<b>Signature:</b>	Non-responsive content removed
<b>Department:</b>		<b>Telephone:</b>		<b>Date:</b>	7/20/2010	<b>Signature:</b>	

EA11003EN-00914[0]

Report no. 6/29/2010		Date		CR pump CP4 diagnosis report		 <b>BOSCH</b> 	
<input type="checkbox"/> internal <input checked="" type="checkbox"/> external		Use		Telephone:	Person responsible:	Department:	
Confidentiality note Confidential				Non-responsive content removed			
Non-responsive content removed						To: For information:	
Project / design pattern type Series / Series		Project: R4 2.0 EU5		Customer: VW		Pump type: CP4.1S_348_2x5,25_REC_3,3_1,95_MT4,2	
Manufacturing plant - line 5150 JhP (Jihlava plant) - 03		Serial number: 1419		Date of manufacture: 260109		Part number (TTNo.): 0445010507	
MAP-No. DS-243105		Diagnosis no. 3706		Fuel: EN590		Actual mileage is [h] 56551 km	
Engine / vehicle number CDC000047 120 kW BiT (Amarok)		Customer order no.:		Samos no.: 770357		SAP-No.: 30-101745-50	
Endurance run conditions: Emission standard: EU5		Endurance run type [customer]: Vehicle endurance run		DSBFD no.: 27479		Customer part number	

### 1. Subject

CP4 customer return  
Diagnosis after endurance run without complaint

### 2. Conclusion

**Function**  
- Delivery rates after endurance run or test without significant fuel-quantity drift in comparison with the new state.

**Components**  
- Wear corresponds to the service life and the testing conditions.

**Result**  
The pump has **passed** the endurance run.

### 3. Diagnosis Results (visual findings)

**3.1 Drive**  
No significant wear

**3.2 Drivetrain**  
No significant wear

**3.3 High pressure**  
No significant wear

**3.4 Bearing**  
No significant wear

**3.5 Shaft seal**  
No significant wear

**3.6 Holes**  
No significant wear

**3.7 Attached components (Metering Unit, Overflow Valve, Counting Point)**  
No significant wear

Legend rating stages

{

OK

{

uncritical

{

Critical

		x
	x	
x		

		x
--	--	---

		x
--	--	---

		x
--	--	---

		x
--	--	---



  

		x
--	--	---



  

		x
--	--	---



EA11003EN-00914[1]

Report no.		<b>CR pump CP4 diagnosis report</b>				<b>BOSCH</b>			
6/29/2010		Date							
<input type="checkbox"/> internal <input checked="" type="checkbox"/> external		Use		Telephone:		Person responsible:		Department:	
				Non-responsive content removed					
Confidentiality note		Confidential							
<b>3.8 O-rings</b> No significant wear								<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	
<b>3.9 Other</b> No significant wear								<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	
<b>4. Hydraulic function</b>									
				Delivery rate [l/h] of new part		Delivery rate [l/h] after testing			
				1/26/2009		3/24/2010			
	n[rpm]	p_rail [bar]	I_ZME [A]						
Starting point	200	200	0.4	4.1		4.2			
1000 rpm, p_rated	1000	1800	0.4	17.4		17.6		<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	
N_max, p_500bar	3375	500	0.4	64.5		65.7		<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	
TCD (technical customer documentation) testing point LG (1,000 rpm, p_rated ≥ 15.5 or 15.2 l/h after running time) is met.									
<b>5. Destiny of the parts</b>  The pump is stored at RB until 12.2010 and then scrapped.									
<b>6. Attachments</b>  No appendix									
Tested:	Non-responsive content removed		Telephone:	Non-responsive content removed		Date:	7/5/2010	Signature:	Non-responsive content removed
Department:			Telephone:			Date:	7/5/2010	Signature:	





Report no.		CR pump CP4 diagnosis report		 							
6/29/2010		Date									
internal <input checked="" type="checkbox"/> external		Telephone: Non-responsive content removed		Person responsible: Department:							
Confidentiality note Confidential											
Non-responsive content removed				To: For information:							
Project / design pattern type Series / Series Manufacturing plant - line 5150 JhP (Jihlava plant) - 03 MAP-No. DS-243105 Engine / vehicle number CDC000047 120 kW BiT (Amarok) Endurance run conditions: Emission standard: EU5		Project: R4 2.0 EU5 Serial number: 1419 Diagnosis no. 3706 Customer order no.: Endurance run type [customer]: Vehicle endurance run		Customer: VW Date of manufacture: 260109 Fuel: EN590 Samos no.: 770357 DSBFD no.: 27479							
				Pump type: CP4.1S_348_2x5,25_REC_3,3_1,95_MT4,2 Part number (TTNo.): 0445010507 Actual mileage is [h] 56551 km SAP-No.: 30-101745-50 Customer part number							
<b>1. Subject</b> CP4 customer return Diagnosis after endurance run without complaint											
<b>2. Conclusion</b> <b>Function</b> - Delivery rates after endurance run or test without significant fuel-quantity drift in comparison with the new state. <b>Components</b> - Wear corresponds to the service life and the testing conditions. <b>Result</b> - The pump has <b>passed</b> the endurance run.											
<b>3. Diagnosis Results (visual findings)</b> <div style="float: right; text-align: right;">         Legend rating stages         <div style="display: inline-block; vertical-align: middle;"> <div style="border: 1px solid black; width: 20px; height: 20px; background-color: white; margin-bottom: 2px;"></div> <div style="border: 1px solid black; width: 20px; height: 20px; background-color: yellow; margin-bottom: 2px;"></div> <div style="border: 1px solid black; width: 20px; height: 20px; background-color: red;"></div> </div> <div style="display: inline-block; vertical-align: middle; margin-left: 5px;"> <div style="margin-bottom: 5px;">OK uncritical</div> <div>Critical</div> </div> </div> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 33%; text-align: center;">OK uncritical</td> <td style="width: 33%; text-align: center;">Critical</td> <td style="width: 33%;"></td> </tr> <tr> <td style="text-align: center;"> <div style="border: 1px solid black; width: 20px; height: 20px; background-color: white; margin-bottom: 2px;"></div> <div style="border: 1px solid black; width: 20px; height: 20px; background-color: yellow; margin-bottom: 2px;"></div> <div style="border: 1px solid black; width: 20px; height: 20px; background-color: red;"></div> </td> <td style="text-align: center;"> <div style="border: 1px solid black; width: 20px; height: 20px; background-color: white; margin-bottom: 2px;"></div> <div style="border: 1px solid black; width: 20px; height: 20px; background-color: yellow; margin-bottom: 2px;"></div> <div style="border: 1px solid black; width: 20px; height: 20px; background-color: red;"></div> </td> <td style="text-align: center;"> <div style="border: 1px solid black; width: 20px; height: 20px; background-color: white; margin-bottom: 2px;"></div> <div style="border: 1px solid black; width: 20px; height: 20px; background-color: yellow; margin-bottom: 2px;"></div> <div style="border: 1px solid black; width: 20px; height: 20px; background-color: red;"></div> </td> </tr> </table>						OK uncritical	Critical		<div style="border: 1px solid black; width: 20px; height: 20px; background-color: white; margin-bottom: 2px;"></div> <div style="border: 1px solid black; width: 20px; height: 20px; background-color: yellow; margin-bottom: 2px;"></div> <div style="border: 1px solid black; width: 20px; height: 20px; background-color: red;"></div>	<div style="border: 1px solid black; width: 20px; height: 20px; background-color: white; margin-bottom: 2px;"></div> <div style="border: 1px solid black; width: 20px; height: 20px; background-color: yellow; margin-bottom: 2px;"></div> <div style="border: 1px solid black; width: 20px; height: 20px; background-color: red;"></div>	<div style="border: 1px solid black; width: 20px; height: 20px; background-color: white; margin-bottom: 2px;"></div> <div style="border: 1px solid black; width: 20px; height: 20px; background-color: yellow; margin-bottom: 2px;"></div> <div style="border: 1px solid black; width: 20px; height: 20px; background-color: red;"></div>
OK uncritical	Critical										
<div style="border: 1px solid black; width: 20px; height: 20px; background-color: white; margin-bottom: 2px;"></div> <div style="border: 1px solid black; width: 20px; height: 20px; background-color: yellow; margin-bottom: 2px;"></div> <div style="border: 1px solid black; width: 20px; height: 20px; background-color: red;"></div>	<div style="border: 1px solid black; width: 20px; height: 20px; background-color: white; margin-bottom: 2px;"></div> <div style="border: 1px solid black; width: 20px; height: 20px; background-color: yellow; margin-bottom: 2px;"></div> <div style="border: 1px solid black; width: 20px; height: 20px; background-color: red;"></div>	<div style="border: 1px solid black; width: 20px; height: 20px; background-color: white; margin-bottom: 2px;"></div> <div style="border: 1px solid black; width: 20px; height: 20px; background-color: yellow; margin-bottom: 2px;"></div> <div style="border: 1px solid black; width: 20px; height: 20px; background-color: red;"></div>									
<b>3.1 Drive</b> No significant wear			<div style="border: 1px solid black; width: 20px; height: 20px; background-color: white; margin-bottom: 2px;"></div> <div style="border: 1px solid black; width: 20px; height: 20px; background-color: yellow; margin-bottom: 2px;"></div> <div style="border: 1px solid black; width: 20px; height: 20px; background-color: red;"></div>								
<b>3.2 Drivetrain</b> No significant wear			<div style="border: 1px solid black; width: 20px; height: 20px; background-color: white; margin-bottom: 2px;"></div> <div style="border: 1px solid black; width: 20px; height: 20px; background-color: yellow; margin-bottom: 2px;"></div> <div style="border: 1px solid black; width: 20px; height: 20px; background-color: red;"></div>								
<b>3.3 High pressure</b> No significant wear			<div style="border: 1px solid black; width: 20px; height: 20px; background-color: white; margin-bottom: 2px;"></div> <div style="border: 1px solid black; width: 20px; height: 20px; background-color: yellow; margin-bottom: 2px;"></div> <div style="border: 1px solid black; width: 20px; height: 20px; background-color: red;"></div>								
<b>3.4 Bearing</b> No significant wear			<div style="border: 1px solid black; width: 20px; height: 20px; background-color: white; margin-bottom: 2px;"></div> <div style="border: 1px solid black; width: 20px; height: 20px; background-color: yellow; margin-bottom: 2px;"></div> <div style="border: 1px solid black; width: 20px; height: 20px; background-color: red;"></div>								
<b>3.5 Shaft seal</b> No significant wear			<div style="border: 1px solid black; width: 20px; height: 20px; background-color: white; margin-bottom: 2px;"></div> <div style="border: 1px solid black; width: 20px; height: 20px; background-color: yellow; margin-bottom: 2px;"></div> <div style="border: 1px solid black; width: 20px; height: 20px; background-color: red;"></div>								
<b>3.6 Holes</b> No significant wear			<div style="border: 1px solid black; width: 20px; height: 20px; background-color: white; margin-bottom: 2px;"></div> <div style="border: 1px solid black; width: 20px; height: 20px; background-color: yellow; margin-bottom: 2px;"></div> <div style="border: 1px solid black; width: 20px; height: 20px; background-color: red;"></div>								
<b>3.7 Attached components (Metering Unit, Overflow Valve, Counting Point)</b> No significant wear			<div style="border: 1px solid black; width: 20px; height: 20px; background-color: white; margin-bottom: 2px;"></div> <div style="border: 1px solid black; width: 20px; height: 20px; background-color: yellow; margin-bottom: 2px;"></div> <div style="border: 1px solid black; width: 20px; height: 20px; background-color: red;"></div>								





EA11003EN-00915[1]

Report no.		<b>CR pump CP4 - Diagnosis report</b>		 <b>BOSCH</b> 																																								
Date																																												
6/29/2010																																												
Use <input type="checkbox"/> internal <input checked="" type="checkbox"/> external Confidentiality note Confidential		Telephone:	Person responsible:		Department:																																							
		Non-responsive content removed																																										
<b>3.8 O-rings</b> No significant wear <table border="1" style="float: right;"> <tr> <td></td> <td></td> <td style="background-color: green; color: white;">x</td> </tr> </table>								x																																				
		x																																										
<b>3.9 Other</b> No significant wear <table border="1" style="float: right;"> <tr> <td></td> <td></td> <td style="background-color: green; color: white;">x</td> </tr> </table>								x																																				
		x																																										
<b>4. Hydraulic function</b>																																												
<table border="1" style="width: 100%;"> <thead> <tr> <th></th> <th>n[rpm]</th> <th>p_rail [bar]</th> <th>I_MU [A]</th> <th>Delivery rate [l/h] of new part</th> <th>Delivery rate [l/h] after testing</th> </tr> <tr> <th></th> <th></th> <th></th> <th></th> <th>1/26/2009</th> <th>3/24/2010</th> </tr> </thead> <tbody> <tr> <td>Starting point</td> <td>200</td> <td>200</td> <td>0.4</td> <td>4.1</td> <td>4.2</td> </tr> <tr> <td>1000 rpm, p Rated</td> <td>1000</td> <td>1800</td> <td>0.4</td> <td>17.4</td> <td>17.6</td> </tr> <tr> <td>N_max, p_500bar</td> <td>3375</td> <td>500</td> <td>0.4</td> <td>64.5</td> <td>65.7</td> </tr> </tbody> </table> <table border="1" style="float: right;"> <tr> <td></td> <td></td> <td style="background-color: green; color: white;">x</td> </tr> <tr> <td></td> <td></td> <td style="background-color: green; color: white;">x</td> </tr> <tr> <td></td> <td></td> <td style="background-color: green; color: white;">x</td> </tr> </table>							n[rpm]	p_rail [bar]	I_MU [A]	Delivery rate [l/h] of new part	Delivery rate [l/h] after testing					1/26/2009	3/24/2010	Starting point	200	200	0.4	4.1	4.2	1000 rpm, p Rated	1000	1800	0.4	17.4	17.6	N_max, p_500bar	3375	500	0.4	64.5	65.7			x			x			x
	n[rpm]	p_rail [bar]	I_MU [A]	Delivery rate [l/h] of new part	Delivery rate [l/h] after testing																																							
				1/26/2009	3/24/2010																																							
Starting point	200	200	0.4	4.1	4.2																																							
1000 rpm, p Rated	1000	1800	0.4	17.4	17.6																																							
N_max, p_500bar	3375	500	0.4	64.5	65.7																																							
		x																																										
		x																																										
		x																																										
TCD (technical customer documentation) testing point LG (1,000 rpm, p Rated ≥ 15.5 or 15.2 l/h after running time) is met.																																												
<b>5. Destiny of the parts</b>																																												
The pump is stored at RB until 12.2010 and then scrapped.																																												
<b>6. Attachments</b>																																												
No appendix																																												
Tested:	Non-responsive content removed	Telephone:	Non-responsive content removed	Date:	7/5/2010	Signature:	Non-responsive content removed																																					
Department:		Telephone:		Date:	7/5/2010	Signature:																																						

EA11003EN-00916[0]

 <b>BOSCH</b> 		CR pump CP4 - Diagnosis report		Report no.		
				Date	12/2/2010	
Department:	Person responsible:	Telephone:	Use	internal		
Non-responsive content removed			external		X	
Confidentiality note Confidential						
To:	Non-responsive content removed					
Cylinder head:						
Pump type: CP4.1S_348_2x5,25_REC_3,3_1,95_MT4,2		Customer: VW	Project: R4 2.0 EU5	Project / design pattern type D		
Part number (TTNo.): 0445B21116_13		Date of manufacture: 081	Serial number: 4673	Manufacturing plant - line 0110 FeP (Feuerbach plant)		
Mileage 104887 km		Fuel: EN590		MAP-No. DS-251677		
SAP-No.: 30-101008-07		Samos no.: 780995	Customer order no.:	Engine/Vehicle number CFH0126169		
Customer part number 03L 130 755 D		DSBFD no.: 28374	Endurance run type [customer]: Vehicle endurance run	Endurance run conditions: GDV - EWP (Ehra variable track for passenger cars)		
<b>1. Subject</b>  CP4 customer returns <b>without complaint</b> GDV Ehra variable track for passenger cars, vehicle endurance run, service life 104,887 km, testing details are not known. Diagnosis after diagnosis following completion of running time.  Pump with special features (see 6. Appendix 1)						
<b>2. Conclusion</b>  <b>Function</b> - Delivery rates after endurance run without significant fuel-quantity drift in comparison with the new state. The non-return valve (version supplier 2 for spring, supplier 3 for hemispherical head) is thus without any functional striking features.  <b>Components (Special features of modification package):</b> - The roller support (version supplier 2 with material supplier 2) does not show any non-critical run-in traces of the C coating. - No striking features visible on the cylinder head (version supplier 2 for soft stage). - No striking features visible on the spring and the spring plate (both are version supplier 2) of the intake valve. - On the robust flange, uncritical 8 µm deep smoothing of the running surface (see 6. Appendix 2) is visible - axial wear depth up to 100 µm is uncritical. - The O-rings (version supplier 2) does not show any striking features. - Wear of the remaining components is low and without significant striking features.  <b>Result</b> - The pump has passed the endurance run.						
<b>3. Results of diagnosis (visual findings)</b>			Legend rating stages	OK	X	
				Uncritical		X
				Critical		X
<b>3.1 Drive</b> No striking feature				X		
<b>3.2 Drivetrain</b> C coating of roller support with slight, non-critical run-in traces (Fig. 1); no striking features on other drivetrain components				X		



 <b>BOSCH</b> 	<b>CR pump CP4 - Diagnosis report</b>		<b>Report no.</b>		[REDACTED]	
			<b>Date</b>		12/2/2010	
<b>Department:</b>		<b>Person responsible:</b>		<b>Telephone:</b>		<b>Use</b> internal <input type="checkbox"/> external <input checked="" type="checkbox"/>
Non-responsive content removed						
				<b>Confidentiality note</b> Confidential		
<b>3.3 High pressure</b> Cylinder and/or the piston running path do not show any striking features Tappet spring base on the cylinder head light smoothening (Fig. 2) Intake valve base on the cylinder head does not show any striking feature (Fig. 3) Spring and spring plate of the intake valve does not show any striking features, other high-pressure components do not show any striking features					<input checked="" type="checkbox"/>	
<b>3.4 Bearing</b> Robust flange with non-critical run-in traces on the axial bearing (Fig. 4); no striking features on other bearing components					<input checked="" type="checkbox"/>	
<b>3.5 Shaft seal</b> No striking feature					<input checked="" type="checkbox"/>	
<b>3.6 Holes</b> No striking feature					<input checked="" type="checkbox"/>	
<b>3.7 Attached components (Metering Unit, Overflow Valve, Counting Point)</b> No striking feature					<input checked="" type="checkbox"/>	
<b>3.8 O-rings</b> No striking feature					<input checked="" type="checkbox"/>	
<b>3.9 Other</b> No striking feature					<input checked="" type="checkbox"/>	
<b>3.10 Images</b>						
 <p>Fig. 1: Roller support to the right, running surface</p>				 <p>Fig. 2: Cylinder head to the right, tappet spring suspension system</p>		

EA11003EN-00916[2]



 <b>BOSCH</b> 	<b>CR pump CP4 - Diagnosis report</b>		Report no.	[REDACTED]	
			Date	12/2/2010	
Department:	Person responsible:	Telephone:	Use	internal	
Non-responsive content removed				external	X
Confidentiality note Confidential					



Figure 3 cylinder head to the right, SV system





Figure 4: robust flange, axial running surface

**4. Hydraulic function**

	n[rpm]	p_rail [bar]	I_MU [A]	Delivery rate [l/h] New part	Delivery rate [l/h] After testing
				1/28/2010	7/7/2010
ST	200	200	0.4	4.5	4.6
LG	1000	1800	0.4	20.0	20.2



No significant volumetric efficiency change compared to delivery measurement.  
Back measurement is within the TCD for new parts.

**5. Destiny of the parts**

The pump is stored at RB until 06/2011 and then scrapped.


**6. Attachments**

Appendix 1: Sample configuration for special components




Appendix 2: Set of slides for diagnosis of robust flange

Tested:	Non-responsive content removed	Phone:	Non-responsive content removed	Date:	12/6/2010	Signature:	Non-responsive content removed
Department:		Phone:		Date:	12/13/2010	Signature:	

EA11003EN-00917101


		<b>CR pump CP4 - Diagnosis report</b>		Report no.																						
				Date	12/14/2010																					
Department:	Person responsible:	Telephone:	Use <table border="1"> <tr> <td>internal</td> <td></td> </tr> <tr> <td>external</td> <td>x</td> </tr> </table>			internal		external	x																	
internal																										
external	x																									
Non-responsive content removed																										
To:	Non-responsive content removed																									
For information:																										
<table border="1"> <tr> <td><b>Pump type:</b> CP4.1S_398_2x6_REC_3,3_1,95_M T4,2</td> <td><b>Customer:</b> VW</td> <td><b>Project:</b> R4 2.0 EU5</td> <td><b>Project / design pattern type</b> D/D</td> </tr> <tr> <td><b>Part number (TTNo.):</b> 0445B21116_05</td> <td><b>Date of manufacture:</b> 0891</td> <td><b>Serial number:</b> 4839</td> <td><b>Manufacturing plant - line</b> 011M FeP (Feuerbach plant)-M -</td> </tr> <tr> <td><b>Actual mileage is [h]</b> 100000 km</td> <td><b>Fuel:</b> EN590</td> <td></td> <td><b>MAP-No.</b> DS-256645</td> </tr> <tr> <td><b>SAP-No.:</b> 30-101581-07</td> <td><b>Samos no.:</b> 786990</td> <td><b>Customer order no.:</b> PT4839, 000891; engine 03LL000173 or Fa</td> <td><b>Engine/Vehicle number</b> 03LL000173/ VW41600073</td> </tr> <tr> <td><b>Customer part number</b> 03L 130 755 D</td> <td><b>DSBFD no.:</b> 28794</td> <td><b>Endurance run type [customer]:</b> Vehicle trial</td> <td><b>Endurance run conditions:</b> EES</td> </tr> </table>						<b>Pump type:</b> CP4.1S_398_2x6_REC_3,3_1,95_M T4,2	<b>Customer:</b> VW	<b>Project:</b> R4 2.0 EU5	<b>Project / design pattern type</b> D/D	<b>Part number (TTNo.):</b> 0445B21116_05	<b>Date of manufacture:</b> 0891	<b>Serial number:</b> 4839	<b>Manufacturing plant - line</b> 011M FeP (Feuerbach plant)-M -	<b>Actual mileage is [h]</b> 100000 km	<b>Fuel:</b> EN590		<b>MAP-No.</b> DS-256645	<b>SAP-No.:</b> 30-101581-07	<b>Samos no.:</b> 786990	<b>Customer order no.:</b> PT4839, 000891; engine 03LL000173 or Fa	<b>Engine/Vehicle number</b> 03LL000173/ VW41600073	<b>Customer part number</b> 03L 130 755 D	<b>DSBFD no.:</b> 28794	<b>Endurance run type [customer]:</b> Vehicle trial	<b>Endurance run conditions:</b> EES	
<b>Pump type:</b> CP4.1S_398_2x6_REC_3,3_1,95_M T4,2	<b>Customer:</b> VW	<b>Project:</b> R4 2.0 EU5	<b>Project / design pattern type</b> D/D																							
<b>Part number (TTNo.):</b> 0445B21116_05	<b>Date of manufacture:</b> 0891	<b>Serial number:</b> 4839	<b>Manufacturing plant - line</b> 011M FeP (Feuerbach plant)-M -																							
<b>Actual mileage is [h]</b> 100000 km	<b>Fuel:</b> EN590		<b>MAP-No.</b> DS-256645																							
<b>SAP-No.:</b> 30-101581-07	<b>Samos no.:</b> 786990	<b>Customer order no.:</b> PT4839, 000891; engine 03LL000173 or Fa	<b>Engine/Vehicle number</b> 03LL000173/ VW41600073																							
<b>Customer part number</b> 03L 130 755 D	<b>DSBFD no.:</b> 28794	<b>Endurance run type [customer]:</b> Vehicle trial	<b>Endurance run conditions:</b> EES																							
<b>1. Subject</b> CP4 customer returns <b>without complaint</b> . EES (Ehra Start-stop) vehicle endurance run, running time 100000km, <b>110k Start-stops</b> Diagnosis after running time expiry																										
<b>2. Conclusion</b> <b>Function</b> - Delivery rates after endurance run without significant fuel-quantity drift in comparison with the new state. <b>Components</b> - The roller support shows a local rupture of the C3 coating. Because of the maximum wear depth of 0.5 µm in combination with the smaller surface (see 6. Appendix 1), rupture is uncritical. The most likely cause is inhomogeneity in the structure of C3 coating (see also report CP4_0320 2010 in this regard). - Wear of the other components is low and does not show any significant striking features. <b>Result</b> - The pump has <b>passed the endurance run</b> . - It is switched to the optimized C3.1 coating as a corrective action for inhomogeneities in C3 coating.																										
<b>3. Results of diagnosis (visual findings)</b>																										
			Legend rating stages { <table border="1"> <tr> <td>OK</td> <td></td> <td></td> <td></td> </tr> <tr> <td>uncritical</td> <td></td> <td></td> <td></td> </tr> <tr> <td>Critical</td> <td></td> <td></td> <td></td> </tr> </table>	OK				uncritical				Critical				<table border="1"> <tr> <td>x</td> <td></td> <td></td> </tr> <tr> <td></td> <td>x</td> <td></td> </tr> <tr> <td></td> <td></td> <td>x</td> </tr> </table>		x				x				x
OK																										
uncritical																										
Critical																										
x																										
	x																									
		x																								
<b>3.1 Drive</b> No striking feature			<table border="1"> <tr> <td>x</td> <td></td> <td></td> </tr> </table>			x																				
x																										
<b>3.2 Drivetrain</b> Local rupture of C3 coating (Fig. 1, detailed image Figure 2)			<table border="1"> <tr> <td></td> <td>x</td> <td></td> </tr> </table>				x																			
	x																									
<b>3.3 High pressure</b> No striking feature			<table border="1"> <tr> <td>x</td> <td></td> <td></td> </tr> </table>			x																				
x																										
<b>3.4 Bearing</b> No striking feature			<table border="1"> <tr> <td>x</td> <td></td> <td></td> </tr> </table>			x																				
x																										
<b>3.5 Shaft seal</b> No striking feature			<table border="1"> <tr> <td>x</td> <td></td> <td></td> </tr> </table>			x																				
x																										
<b>3.6 Holes</b> No striking feature			<table border="1"> <tr> <td>x</td> <td></td> <td></td> </tr> </table>			x																				
x																										





		<b>CR pump CP4 - Diagnosis report</b>		Report no. <span style="background-color: black; color: black;">[REDACTED]</span>							
				Date 12/14/2010							
<b>Department:</b>	<b>Person responsible:</b>	<b>Telephone:</b>	<b>Use</b> <table border="1"> <tr> <td>internal</td> <td><input type="checkbox"/></td> <td><input type="checkbox"/></td> </tr> <tr> <td>external</td> <td><input checked="" type="checkbox"/></td> <td><input type="checkbox"/></td> </tr> </table>			internal	<input type="checkbox"/>	<input type="checkbox"/>	external	<input checked="" type="checkbox"/>	<input type="checkbox"/>
internal	<input type="checkbox"/>	<input type="checkbox"/>									
external	<input checked="" type="checkbox"/>	<input type="checkbox"/>									
Non-responsive content removed			Confidentiality note Confidential								
<b>3.7 Attached components (metering unit, overflow valve, counting point)</b>				<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>							
No striking feature											
<b>3.8 O-rings</b>				<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>							
No striking feature											
<b>3.9 Other</b>				<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>							
No striking feature											
<b>3.10 Images</b>											
											
Fig. 1: Roller support			Fig. 2: Roller support, detailed rupture								
<b>4. Hydraulic function</b>											
				Delivery rate [l/h] of new part	Delivery rate [l/h] after testing						
	n[rpm]	p_rail [bar]	I_MU [A]	11/18/2008	9/23/2010						
ST	200	200	0.4	4.4	4.5						
LG	1000	1800	0.4	19.9	20.4						
				<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>							
No significant volumetric efficiency change compared to delivery measurement. Back measurement is within the TCD for new parts.											
<b>5. Destiny of the parts</b>											
The pump is stored at RB until 06/2011 and then scrapped.											
<b>6. Attachments</b>											
Appendix 1: WLI (white-light interferometry) measurement of roller support											
<b>Tested:</b>	Non-responsive content removed	<b>Telephone:</b>	Non-responsive content removed	<b>Date:</b>	12/16/2010						
<b>Signature:</b>	Non-responsive content removed	<b>Date:</b>	12/17/2010	<b>Signature:</b>	Non-responsive content removed						
<b>Department:</b>	Non-responsive content removed	<b>Telephone:</b>	Non-responsive content removed	<b>Date:</b>	12/17/2010						
<b>Signature:</b>	Non-responsive content removed	<b>Date:</b>	12/17/2010	<b>Signature:</b>	Non-responsive content removed						

## CP4 - Investigation R4 2,0 EU5/ #891-4839

- **Pump:** D-sample, CP4.1S\_398\_2x6\_REC\_3,3\_1,95\_MT4,2, #891-4839
- **Operating conditions:** Vehicle-Endurance testing, Run time 100000km, Endurance testing-end
- **Investigation:** Roller shoe – start, C-layer, centric



EA11003EN-00918[0]

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.	[REDACTED]	
				Date	2/3/2011	
<b>Department:</b>	<b>Person responsible:</b>	<b>Telephone:</b>		Use	internal	
Non-responsive content removed					external	x
				<b>Confidentiality note</b>		
				Confidential		
To:	Non-responsive content removed					
For information:						
<b>Pump type:</b>		<b>Customer:</b>	<b>Project:</b>	<b>Project / design pattern type</b>		
CP4.1S_398_2x6_REC_3,3_1,95_MT4,2		VW	R4 2.0 EU5	Series / Series		
<b>Part number (TTNo.):</b>		<b>Date of manufacture:</b>	<b>Serial number:</b>	<b>Manufacturing plant - line</b>		
0445010514		260309	0736	736 - 04		
<b>Actual mileage is [h]</b>		<b>Fuel:</b>		<b>MAP-No.</b>		
100023 km		EN590		DS-258419		
<b>SAP-No.:</b>		<b>Samos no.:</b>	<b>Customer order no.:</b>	<b>Engine/Vehicle number</b>		
30-102202-15		789477	731523	CGL0000027 / AU416 -1 1138		
<b>Customer part number</b>		<b>DSBFD no.:</b>	<b>Endurance run type [customer]:</b>	<b>Endurance run conditions:</b>		
03L 130 755 D		28992	Vehicle endurance run	Ehra variable track for passenger cars		

### 1. Subject

CP4 Customer returns **without** complaint  
 Engine no. CGL00000, 125 kW, Euro 5  
 Vehicle no.: AU416 -1 1138  
 Testing conditions: Ehra variable track for passenger cars

### 2. Conclusion

**Function:**  
 The pump function is within the specification limits. There is no significant drift in comparison to the delivery measurement.

**Components**  
 Wear of the components is low and without significant striking features.

**Result**  
 The pump has passed the **endurance run**

### 3. Results of diagnosis (visual findings)

**3.1 Drive**  
No striking feature

**3.2 Drivetrain**  
No striking feature

**3.3 High pressure**  
No striking feature

**3.4 Bearing**  
No striking feature

**3.5 Shaft seal**  
No striking feature

**3.6 Holes**  
No striking feature

Legend rating stages {

- OK
- uncritical
- Critical



x			
	x		
			x



x			
x			
x			
x			
x			
x			





EA11003EN-00918[1]

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.			
				Date		2/3/2011	
<b>Department:</b>	<b>Person responsible:</b>	<b>Telephone:</b>		Use		internal	
Non-responsive content removed						external	x
				<b>Confidentiality note</b>			
				Confidential			
<b>3.7 Attached components (Metering Unit, Overflow Valve, Counting Point)</b>						<input checked="" type="checkbox"/>	
No striking feature							
<b>3.8 O-rings</b>						<input checked="" type="checkbox"/>	
No striking feature							
<b>3.9 Other</b>						<input checked="" type="checkbox"/>	
No striking feature							
<b>3.10 Images</b>							
None							
<b>4. Hydraulic function</b>							
The pump function is within the specification limits. There is no significant drift in comparison to the delivery measurement.							
				Delivery rate [l/h] of new part	Delivery rate [l/h] after testing		
	n[rpm]	p_rail [bar]	I_MU [A]	3/26/2009	10/1/2009		
ST	200	200	0.4	4.6	4.9	<input checked="" type="checkbox"/>	
LG	1000	1800	0.4	20.1	20.6	<input checked="" type="checkbox"/>	
<b>5. Destiny of the parts</b>							
The pump parts remain with Robert Bosch GmbH at the request of the customer							
<b>6. Attachments</b>							
None							
<b>Tested:</b>	Non-responsive content removed	<b>Telephone:</b>	Non-responsive content removed	<b>Date:</b>	2/7/2011	<b>Signature:</b>	Non-responsive content removed
<b>Department</b>		<b>Telephone:</b>		<b>Date:</b>	2/14/2011	<b>Signature:</b>	

EA11003EN-00919[0]



 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.		
				Date	2/3/2011	
Department:	Person responsible:	Telephone:	Use <input type="checkbox"/> internal <input type="checkbox"/> external <input checked="" type="checkbox"/>			
Non-responsive content removed						
			<b>Confidentiality note</b> Confidential			
To:	Non-responsive content removed					
For information:						
<b>Pump type:</b> CP4.1S_398_2x6_REC_3,3_1,95_MT4,2		<b>Customer:</b> VW	<b>Project:</b> R4 2.0 EU5	<b>Project / design pattern type</b> Series / Series		
<b>Part number (TTNo.):</b> 0445010514		<b>Date of manufacture:</b> 260309	<b>Serial number:</b> 0736	<b>Manufacturing plant - line</b> 736 - 04		
<b>Actual mileage is [h]</b> 100023 km		<b>Fuel:</b> EN590	<b>MAP-No.</b> DS-258419			
<b>SAP-No.:</b> 30-102202-15		<b>Samos no.:</b> 789477	<b>Customer order no.:</b> 731523	<b>Engine/Vehicle number</b> CGL0000027 / AU416 -1 1138		
<b>Customer part number</b> 03L 130 755 D		<b>DSBFD no.:</b> 28992	<b>Endurance run type [customer]:</b> Vehicle endurance run	<b>Endurance run conditions:</b> Ehra variable track for passenger cars		
<b>1. Subject</b> CP4 Customer returns <b>without</b> complaint Engine no. CGL00000, 125 kW, Euro 5 Vehicle no.: AU416 -1 1138 Testing conditions: Ehra variable track for passenger cars						
<b>2. Conclusion</b> <b>Function:</b> The pump function is within the specification limits. There is no significant drift in comparison to the delivery measurement. <b>Components</b> Wear of the components is low and without significant striking features. <b>Result</b> The pump has passed the <b>endurance run</b>						
<b>3. Results of diagnosis (visual findings)</b> <div style="float: right; text-align: right;">           Legend rating stages            OK <input checked="" type="checkbox"/>            uncritical <input checked="" type="checkbox"/>            Critical <input checked="" type="checkbox"/> </div>						
<b>3.1 Drive</b> No striking feature			<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>			
<b>3.2 Drivetrain</b> No striking feature			<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>			
<b>3.3 High pressure</b> No striking feature			<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>			
<b>3.4 Bearing</b> No striking feature			<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>			
<b>3.5 Shaft seal</b> No striking feature			<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>			
<b>3.6 Holes</b> No striking feature			<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>			







EA11003EN-00919[1]

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.			
				Date		2/3/2011	
Department:	Person responsible:		Telephone:		Use		internal
Non-responsive content removed						external	
						x	
				<b>Confidentiality note</b> Confidential			
<b>3.7 Attached components (Metering Unit, Overflow Valve, Counting Point)</b> No striking feature						<input checked="" type="checkbox"/>	
<b>3.8 O-rings</b> No striking feature						<input checked="" type="checkbox"/>	
<b>3.9 Other</b> No striking feature						<input checked="" type="checkbox"/>	
<b>3.10 Images</b> None							
<b>4. Hydraulic function</b> The pump function is within the specification limits. There is no significant drift in comparison to the delivery measurement.							
				Delivery rate [l/h] of new part	Delivery rate [l/h] after testing		
	n[rpm]	p_rail [bar]	I_MU [A]	3/26/2009	10/1/2010		
ST	200	200	0.4	4.6	4.9	<input checked="" type="checkbox"/>	
LG	1000	1800	0.4	20.1	20.6	<input checked="" type="checkbox"/>	
<b>5. Destiny of the parts</b> The pump parts remain with Robert Bosch GmbH at the request of the customer							
<b>6. Attachments</b> None							
Tested:	Non-responsive content removed	Telephone:	Non-responsive content removed	Date:	2/7/2011	Signature:	Non-responsive content removed
Department		Telephone:		Date:	2/14/2011	Signature:	





EA11003EN-00920[0]


 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.																	
				Date	2/23/2011																
Department:	Person responsible:	Telephone:	Use		internal																
Non-responsive content removed					external	x															
			<b>Confidentiality note</b>																		
			Confidential																		
To:	Non-responsive content removed																				
For information:																					
<b>Pump type:</b> C P4.1 S_348_2x 5,2 5_R E C_3,3_I, 95_M T4,2		<b>Customer:</b> VW	<b>Project:</b> R4 2.0 EU5	<b>Project / design pattern type</b> Series / Series																	
<b>Part number (TTNo.):</b> 0445010507		<b>Date of manufacture:</b> 150609	<b>Serial number:</b> 0365	<b>Manufacturing plant - line</b> 5150 JhP (Jihlava plant) - 03																	
<b>Actual mileage is [h]</b> 22400 km		<b>Fuel:</b> Others	<b>MAP-No.</b> DS-259908																		
<b>SAP-No.:</b> 30-101745-50		<b>Samos no.:</b> 791254	<b>Customer order no.:</b> VN817-8-0164 (RPU) EU5		<b>Engine/Vehicle number</b>																
<b>Customer part number</b>		<b>DSBFD no.:</b> 29202	<b>Endurance run type [customer]:</b> Vehicle endurance run		<b>Endurance run conditions:</b> Profile Argentina diesel																
<b>1. Subject</b>																					
<p>CP4 Customer returns without complaint          BD 0 445 010 507 HP pump CP4.1,          Design status, date of manufacture: 06.15.2009, SN: BPT0356,          Engine no. VN817-8-0164 (RPU), CDC0000616          EU5 emission standard with Argentina diesel, mileage 22,400 km</p>																					
<b>2. Conclusion</b>																					
<p><b>Function:</b> Pumps were already opened by the customer. Therefore, hydraulic back measurement no longer possible.</p> <p><b>Components:</b>          Drivetrain damage category 1 (global, abrasive wear of roller support and cam track in addition to material fatigue and rupture of the roller), see Figures 1 to 4          As a result, particle marks and grooves through particles on most components (bearings, tappet holes, contact area of HP piston and roller support, etc.), see Figs. 11 to 14          Due to the progression of damage, no detailed analysis on the cam track, roller support and the roller is possible any longer. Argentina-diesel cannot be ruled out as a possible cause of this damage.          Brown discoloration due to fuel on the housing and flange bearing of the camshaft, see Figures 7 and 8; bearing damage as a result of drivetrain damage and overload, see Figures 5 and 6          The high-pressure piston shows waviness and discoloration that can occur during grinding under certain circumstances, see Figures 9 and 10</p> <p><b>Result:</b>          - The pump has failed the endurance run.          The pump is released for EN590 according to TCD (technical customer documentation). The endurance run conditions with Argentina diesel were carried out outside this release.          One possible reason for the deposit formation is air, water in fuel, foam or Argentina diesel fuel.</p>																					
<b>3. Results of diagnosis (visual findings)</b>																					
<b>3.1 Drive</b> No striking feature			Legend rating stages { <table border="1"> <tr> <td>OK</td> <td>x</td> <td></td> <td></td> </tr> <tr> <td>uncritical</td> <td></td> <td>x</td> <td></td> </tr> <tr> <td>Critical</td> <td></td> <td></td> <td>x</td> </tr> </table>		OK	x			uncritical		x		Critical			x	<table border="1"> <tr> <td>x</td> <td></td> <td></td> </tr> </table>		x		
OK	x																				
uncritical		x																			
Critical			x																		
x																					

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.	[REDACTED]	
				Date	2/23/2011	
Department:	Person responsible:	Telephone:	Use	internal		
Non-responsive content removed				external	x	
			<b>Confidentiality note</b> Confidential			
<b>3.2 Drivetrain</b> Drivetrain damage category I (global, abrasive wear)			<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>			
<b>3.3 High pressure</b> Piston base up to 4 mm diameter damaged by particles indentations. High-pressure piston, waviness over the entire piston guidance.			<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>			
<b>3.4 Bearing</b> Bearing damage due to drivetrain damage and overload			<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>			
<b>3.5 Shaft seal</b> No striking feature			<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>			
<b>3.6 Holes</b> As a result of drivetrain damage, particle marks and particles are in the metering hole.			<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>			
<b>3.7 Attached components (metering unit, overflow valve, counting point)</b> As a result of drivetrain damage, there are particles on the MU (metering unit).			<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>			
<b>3.8 O-rings</b> No striking feature			<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>			
<b>3.9 Other</b> No striking feature			<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>			
<b>3.10 Images</b>						
						
<b>Fig. 1: Roller, running surface</b>			<b>Fig. 2: Roller support, running surface</b>			
						
<b>Fig. 3: Camshaft, cam track running surface TDC (top dead center)</b>			<b>Fig. 4: Camshaft, cam track running surface BDC (bottom dead center)</b>			




 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no. <span style="background-color: black; color: black;">[REDACTED]</span>				
				Date 2/23/2011				
Department: Non-responsive content removed	Person responsible: <span style="background-color: black; color: black;">[REDACTED]</span>	Telephone: <span style="background-color: black; color: black;">[REDACTED]</span>	Use <table border="1" style="float: right;"> <tr> <td>internal</td> <td></td> </tr> <tr> <td>external</td> <td>x</td> </tr> </table>		internal		external	x
internal								
external	x							
			<b>Confidentiality note</b> Confidential					


  




**Fig. 5: Housing mount bushing, radial**




**Fig. 6: Housing mount bushing, radial**




**Fig. 7: Camshaft, housing mount radial**




**Fig. 8: Camshaft, flange bearing radial**




**Fig. 9: High-pressure piston, high-pressure side**



**Fig. 10: High-pressure piston, low-pressure side**





**Fig. 11: Roller support, piston system**











**Fig. 12: High-pressure piston, contact surface for roller support**



 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no. [REDACTED]	
				Date 2/23/2011	
Department:	Person responsible:	Telephone:		Use	<input type="checkbox"/> internal <input checked="" type="checkbox"/> external
Non-responsive content removed		[REDACTED]			
				<b>Confidentiality note</b> Confidential	
					
<b>Fig. 13: Metering unit, screen</b>			<b>Fig. 14: Housing, metering unit hole</b>		
<b>4. Hydraulic function</b> The pumps were already opened by the customer. Therefore, hydraulic back measurement no longer possible.					
<b>5. Destiny of the parts</b> The pump parts remain with Robert Bosch GmbH at the request of the customer					
<b>6. Appendix</b> None					
Tested:	Non-responsive content removed	Telephone:	Non-responsive content removed	Date:	2/23/2011
Signature:	[REDACTED]	Signature:	[REDACTED]	Date:	2/23/2011
Department	[REDACTED]	Telephone:	[REDACTED]	Date:	3/2/2011
Signature:	[REDACTED]	Signature:	[REDACTED]	Date:	3/2/2011



EA11003EN-00921[0]

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.	[REDACTED]													
				Date	2/23/2011													
Department:	Person responsible:	Telephone:	Use	internal														
Non-responsive content removed			external		x													
			Confidentiality note															
			Confidential															
To:	Non-responsive content removed																	
For information:	[REDACTED]																	
<b>Pump type:</b> CP4.1S_348_2x5,25_REC_3,3_1,95_MT4,2		<b>Customer:</b> VW		<b>Project:</b> R4 2.0 EU5		<b>Project / design pattern type</b> Series / Series												
<b>Part number (TTNo.):</b> 0445010507		<b>Date of manufacture:</b> 150709		<b>Serial number:</b> 0060		<b>Manufacturing plant - line</b> 5150 JhP (Jihlava plant) - 03												
<b>Actual mileage is [h]</b> 62106 km		<b>Fuel:</b> Others		<b>MAP-No.</b> DS-259910														
<b>SAP-No.:</b> 30-101745-50		<b>Samos no.:</b> 791254		<b>Customer order no.:</b>		<b>Engine/Vehicle number</b> VN817-9-0359 (RPU) EU5,120kW												
<b>Customer part number</b> 03L 130 755		<b>DSBFD no.:</b> 29203		<b>Endurance run type [customer]:</b> Vehicle endurance run		<b>Endurance run conditions:</b> Profile of Ehra variable track for passenger cars with Argentina diesel												
<h3>1. Subject</h3> <p>CP4 Customer returns without complaint          Engine no. VN817-9-0359 (RPU) 120 kW, CDC ..... 630, emission standard: EU5          Mileage: 62,106 km, profile of Ehra variable track for passenger cars with Argentina diesel</p>																		
<h3>2. Conclusion</h3> <p><b>Function:</b> Pumps were already opened by the customer. Therefore, hydraulic back measurement no longer possible.</p> <p><b>Components:</b>          The high-pressure piston shows waviness and discoloration that can occur during grinding under certain circumstances in China. (Rating 4), see Figures 1 and 2          Significant deposits on the right side of the roller support due to fuel. (Rating 5), see Figure 3          Brown discoloration due to fuel on the roller. (Rating 5), see Figure 4          Wear of the other components is low and without significant striking features.</p> <p><b>Result:</b>          The pump has <b>passed the endurance run</b>.          The pump is released for EN590 according to TCD (Technical Customer Documentation). The endurance run conditions with Argentina diesel were outside of this release.          One possible reason for the deposit formation is air, water in fuel, foam or Argentina diesel fuel.</p>																		
<h3>3. Results of diagnosis (visual findings)</h3>				Legend rating stages <table border="1"> <tr> <td>OK</td> <td>x</td> <td></td> <td></td> </tr> <tr> <td>Uncritical</td> <td></td> <td>x</td> <td></td> </tr> <tr> <td>Critical</td> <td></td> <td></td> <td>x</td> </tr> </table>			OK	x			Uncritical		x		Critical			x
OK	x																	
Uncritical		x																
Critical			x															
<h4>3.1 Drive</h4> <p>No striking feature</p>				<table border="1"> <tr> <td>x</td> <td></td> <td></td> </tr> </table>			x											
x																		
<h4>3.2 Drivetrain</h4> <p>Significant deposits on the right side of the roller support due to fuel. (Rating 5), see Figure 3          Brown discoloration due to fuel on the roller. (Rating 5), see Figure 4</p>				<table border="1"> <tr> <td></td> <td>x</td> <td></td> </tr> </table>				x										
	x																	



 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no. <span style="background-color: black; color: black;">[REDACTED]</span>				
				Date 2/23/2011				
Department: Non-responsive content removed	Person responsible: Non-responsive content removed	Telephone: Non-responsive content removed	Use	<table border="1"> <tr> <td>internal</td> <td></td> </tr> <tr> <td>external</td> <td>x</td> </tr> </table>	internal		external	x
internal								
external	x							
			<b>Confidentiality note</b> Confidential					
<b>3.3 High pressure</b> The high-pressure piston shows waviness and discoloration that can occur during grinding under certain circumstances. (Rating 4), see Figures 1 and 2				<table border="1"> <tr> <td></td> <td>x</td> <td></td> </tr> </table>		x		
	x							
<b>3.4 Bearing</b> No striking feature				<table border="1"> <tr> <td>x</td> <td></td> <td></td> </tr> </table>	x			
x								
<b>3.5 Shaft seal</b> No striking feature				<table border="1"> <tr> <td>x</td> <td></td> <td></td> </tr> </table>	x			
x								
<b>3.6 Holes</b> No striking feature				<table border="1"> <tr> <td>x</td> <td></td> <td></td> </tr> </table>	x			
x								
<b>3.7 Attached components (Metering Unit, Overflow Valve, Counting Point)</b> No striking feature				<table border="1"> <tr> <td>x</td> <td></td> <td></td> </tr> </table>	x			
x								
<b>3.8 O-rings</b> No striking feature				<table border="1"> <tr> <td>x</td> <td></td> <td></td> </tr> </table>	x			
x								
<b>3.9 Other</b> No striking feature				<table border="1"> <tr> <td>x</td> <td></td> <td></td> </tr> </table>	x			
x								
<b>3.10 Images</b>								
								
								
<b>Fig. 1: High-pressure piston, high-pressure side (rating 4)</b>		<b>Fig. 2: High-pressure piston, low-pressure side (rating 4)</b>						
<b>Fig. 3: Roller support, running surface (rating 5)</b>		<b>Fig. 4: Roller, running surface (rating 5)</b>						









EA11003EN-00921[2]

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no. <span style="background-color: black; color: black;">[REDACTED]</span>	
				Date 2/23/2011	
Department: Non-responsive content removed	Person responsible: <span style="background-color: black; color: black;">[REDACTED]</span>	Telephone: <span style="background-color: black; color: black;">[REDACTED]</span>	Use	internal external al	<input checked="" type="checkbox"/>
			<b>Confidentiality note</b> Confidential		
<b>4. Hydraulic function</b> Pumps were already opened by the customer. Therefore, hydraulic back measurement no longer possible.					
<b>5. Destiny of the parts</b> The pump parts remain with Robert Bosch GmbH at the request of the customer					
<b>6. Attachments</b> None					
Tested:	Non-responsive content removed	Telephone:	Non-responsive content removed	Date:	2/28/2011
Signature:	Non-responsive content removed				
Department	<span style="background-color: black; color: black;">[REDACTED]</span>	Telephone:	<span style="background-color: black; color: black;">[REDACTED]</span>	Date:	3/1/2011
Signature:	<span style="background-color: black; color: black;">[REDACTED]</span>				

EA11003EN-00922[0]

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.	
				Date	2/23/2011
Department:	Person responsible:	Telephone:	Use	internal	
Non-responsive content removed			external		x
			Confidentiality note Confidential		
To:	Non-responsive content removed				
For information:					
<b>Pump type:</b> CP4.1S_348_2x5,25_REC_3,3_1,95_MT4,2	<b>Customer:</b> VW	<b>Project:</b> R4 2.0 EU5	<b>Project / design pattern type</b> Series / Series		
<b>Part number (TTNo.):</b> 0445010507	<b>Date of manufacture:</b> 150709	<b>Serial number:</b> 0060	<b>Manufacturing plant - line</b> 5150 JhP (Jihlava plant) - 03		
<b>Actual mileage is [h]</b> 62106 km	<b>Fuel:</b> Others		<b>MAP-No.</b> DS-259910		
<b>SAP-No.:</b> 30-101745-50	<b>Samos no.:</b> 791254	<b>Customer order no.:</b>	<b>Engine/Vehicle number</b> VN817-9-0359 (RPU) EU5,120kW		
<b>Customer part number</b> 03L 130 755	<b>DSBFD no.:</b> 29203	<b>Endurance run type [customer]:</b> Vehicle endurance run	<b>Endurance run conditions:</b> Profile of Ehra variable track for passenger cars with Argentina diesel		
<h3>1. Subject</h3> <p>CP4 Customer returns without complaint          Engine no. VN817-9-0359 (RPU) 120 kW, CDC ..... 630, emission standard: EU5          Mileage: 62,106 km, profile of Ehra variable track for passenger cars with Argentina diesel</p>					
<h3>2. Conclusion</h3> <p><b>Function:</b> Pumps were already opened by the customer. Therefore, hydraulic back measurement no longer possible.</p> <p><b>Components:</b>          The high-pressure piston shows waviness and discoloration that can occur during grinding under certain circumstances in China. (Rating 4), see Figures 1 and 2          Significant deposits on the right side of the roller support due to fuel. (Rating 5), see Figure 3          Brown discoloration due to fuel on the roller. (Rating 5), see Figure 4          Wear of the other components is low and without significant striking features.</p> <p><b>Result:</b>          The pump has <b>passed the endurance run</b>.          The pump is released for EN590 according to TCD (Technical Customer Documentation). The endurance run conditions with Argentina diesel were outside of this release.          One possible reason for the deposit formation is air, water in fuel, foam or Argentina diesel fuel.</p>					
<h3>3. Results of diagnosis (visual findings)</h3> <h4>3.1 Drive</h4> <p>No striking feature</p>			<div> <div>OK</div> <div>Uncritical</div> <div>Critical</div> </div> <div> <div>x</div> <div>x</div> <div>x</div> </div>		
<h4>3.2 Drivetrain</h4> <p>Significant deposits on the right side of the roller support due to fuel. (Rating 5), see Figure 3          Brown discoloration due to fuel on the roller. (Rating 5), see Figure 4</p>			<div> <div>x</div> <div>x</div> </div>		

EA11003EN-00922[1]



 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.					
				Date	2/23/2011				
Department: Non-responsive content removed	Person responsible: Non-responsive content removed	Telephone: Non-responsive content removed	Use <table border="1"> <tr> <td>internal</td> <td></td> </tr> <tr> <td>external</td> <td>x</td> </tr> </table>	internal		external	x		
internal									
external	x								
			<b>Confidentiality note</b> Confidential						
<b>3.3 High pressure</b> The high-pressure piston shows waviness and discoloration that can occur during grinding under certain circumstances. (Rating 4), see Figures 1 and 2			<table border="1"> <tr> <td></td> <td>x</td> <td></td> </tr> </table>				x		
	x								
<b>3.4 Bearing</b> No striking feature			<table border="1"> <tr> <td>x</td> <td></td> <td></td> </tr> </table>			x			
x									
<b>3.5 Shaft seal</b> No striking feature			<table border="1"> <tr> <td>x</td> <td></td> <td></td> </tr> </table>			x			
x									
<b>3.6 Holes</b> No striking feature			<table border="1"> <tr> <td>x</td> <td></td> <td></td> </tr> </table>			x			
x									
<b>3.7 Attached components (Metering Unit, Overflow Valve, Counting Point)</b> No striking feature			<table border="1"> <tr> <td>x</td> <td></td> <td></td> </tr> </table>			x			
x									
<b>3.8 O-rings</b> No striking feature			<table border="1"> <tr> <td>x</td> <td></td> <td></td> </tr> </table>			x			
x									
<b>3.9 Other</b> No striking feature			<table border="1"> <tr> <td>x</td> <td></td> <td></td> </tr> </table>			x			
x									
<b>3.10 Images</b>									
									
									
<b>Fig. 1: High-pressure piston, high-pressure side (rating 4)</b>			<b>Fig. 2: High-pressure piston, low-pressure side (rating 4)</b>						
<b>Fig. 3: Roller support, running surface (rating 5)</b>			<b>Fig. 4: Roller, running surface (rating 5)</b>						







EA11003EN-00922[2]

		<b>report</b>		Date	2/23/2011	
Department: Non-responsive content removed	Person responsible:		Telephone:	Use	internal	
					external	x
			Confidentiality note Confidential			
<b>4. Hydraulic function</b> Pumps were already opened by the customer. Therefore, hydraulic back measurement no longer possible.						
<b>5. Destiny of the parts</b> The pump parts remain with Robert Bosch GmbH at the request of the customer						
<b>6. Attachments</b> None						
Tested:	Non-responsive content removed	Telephone:	Non-responsive content removed	Date:	2/28/2011	Signature: Non-responsive content removed
Department		Telephone:		Date:	3/1/2011	Signature:

EA11003EN-00923[0]



 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.														
				Date	3/3/2011													
Department:	Person responsible:	Telephone:	Use															
Non-responsive content removed			internal external <b>x</b>															
			Confidentiality note Confidential															
To:	Non-responsive content removed																	
For information:																		
Pump type:		Customer:	Project:	Project / design pattern type														
CP4.1S_398_2x6_REC_3,3_1,95_MT4,2		VW	R4 2.0 EU5	C / C														
Part number (TTNo.):		Date of manufacture:	Serial number:	Manufacturing plant - line														
0445B21137_05		989	4491	011M FeP (Feuerbach plant)-M -														
Actual mileage is [h]		Fuel:		MAP-No.														
950 h		EN590		DS-260833														
SAP-No.:		Samos no.:	Customer order no.:	Engine/Vehicle number														
30-102939-09		791448	03LT/20819, 103 kW	03LT/20819, 103 kW														
Customer part number		DSBFD no.:	Endurance run type [customer]:	Endurance run conditions:														
03L 130 755 F		29265	Engine endurance run	Profile of ÖVL + PZD + ÖVL														
<b>1. Subject</b>																		
CP4 customer returns <b>without complaint</b> . Engine no. 03LT/20819, 103 kW, emission standard: EU5 Mileage: 950 h with ÖVL + + PZD + ÖVL																		
<b>2. Conclusion</b>																		
<b>Function:</b> The pump function in the specified testing point meets the requirements. In comparison to the delivery measurement, no significant fuel-quantity drift is detectable. <b>Components:</b> Fretting wear on the high-pressure seal of the intake valve and the high-pressure seal in contact with the intake valve. (See 3.10 Figures 1 and 2, rating 4) Fuel deposits on the outer edges of the sealing surfaces of the intake valve and high-pressure seal. (See 3.10 Figures 1 and 2, rating 3) Wear of the other components is low and without significant striking features. <b>Result:</b> The pump has passed the endurance run. Deposit formation is due to fuel. Robert Bosch GmbH requires further information from the customer in this regard.																		
<b>3. Results of diagnosis (visual findings)</b>				Legend rating stages <table border="1"> <tr> <td>OK</td> <td><b>x</b></td> <td></td> <td></td> </tr> <tr> <td>Uncritical</td> <td></td> <td><b>x</b></td> <td></td> </tr> <tr> <td>Critical</td> <td></td> <td></td> <td><b>x</b></td> </tr> </table>			OK	<b>x</b>			Uncritical		<b>x</b>		Critical			<b>x</b>
OK	<b>x</b>																	
Uncritical		<b>x</b>																
Critical			<b>x</b>															
<b>3.1 Drive</b>				<table border="1"> <tr> <td><b>x</b></td> <td></td> <td></td> </tr> </table>			<b>x</b>											
<b>x</b>																		
No striking feature																		
<b>3.2 Drivetrain</b>				<table border="1"> <tr> <td><b>x</b></td> <td></td> <td></td> </tr> </table>			<b>x</b>											
<b>x</b>																		
No striking feature																		
<b>3.3 High pressure x</b>				<table border="1"> <tr> <td></td> <td><b>x</b></td> <td></td> </tr> <tr> <td></td> <td></td> <td></td> </tr> <tr> <td></td> <td></td> <td></td> </tr> <tr> <td></td> <td></td> <td></td> </tr> </table>				<b>x</b>										
	<b>x</b>																	
Fretting wear at the high-pressure seal of the intake valve. (Rating 4, Figure 1).																		
Fretting wear on the high-pressure seal in contact with the intake valve (Rating 4, Figure 2).																		
Fuel deposits on the outer edge of the high-pressure sealing surfaces of the intake valve. (See 3.10 Figures 1 and 2, rating 3)																		
Fuel deposits on the outer edge of the high-pressure seal of the intake valve. (See 3.10 Figures 1 and 2, rating 3)																		

EA11003EN-00923[1]



 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no. <span style="background-color: black; color: black;">[REDACTED]</span>				
				Date 3/3/2011				
Department: <span style="background-color: black; color: black;">Non-responsive content removed</span>	Person responsible: <span style="background-color: black; color: black;">[REDACTED]</span>	Telephone: <span style="background-color: black; color: black;">[REDACTED]</span>	Use <table border="1"> <tr> <td>internal</td> <td></td> </tr> <tr> <td>external</td> <td>x</td> </tr> </table>		internal		external	x
internal								
external	x							
			Confidentiality note Confidential					
<b>3.4 Bearing</b> No striking feature			<input checked="" type="checkbox"/>					
<b>3.5 Shaft seal</b> No striking feature			<input checked="" type="checkbox"/>					
<b>3.6 Holes</b> No striking feature			<input checked="" type="checkbox"/>					
<b>3.7 Attached components (Metering Unit, Overflow Valve, Counting Point)</b> No striking feature			<input checked="" type="checkbox"/>					
<b>3.8 O-rings</b> No striking feature			<input checked="" type="checkbox"/>					
<b>3.9 Other</b> No striking feature			<input checked="" type="checkbox"/>					
<b>3.10 Images</b>								
								
Fig. 1: Intake valve of fretting wear (Rating 4)		Fig. 2: Fretting wear at stationery seal ring (Rating 4)						
<b>4. Hydraulic function</b>								
The pump function in the specified testing point meets the requirements. In comparison to the delivery measurement, no significant fuel-quantity drift is detectable.								
			Delivery rate [l/h] New part	Delivery rate [l/h] After testing				
	n[rpm]	p_rail [bar]	I_MU [A]					
			9/17/2009	11/8/2010				
ST	200	200	0.4	4.4				
LG	1000	1800	0.4	20.4				
				4.5				
				20.5				
				<input checked="" type="checkbox"/>				
				<input checked="" type="checkbox"/>				
<b>5. Destiny of the parts</b> The pump parts remain with Robert Bosch GmbH at the request of the customer								
<b>6. Attachments</b> None								
Tested:	<span style="background-color: black; color: black;">Non-responsive content removed</span>	Telephone:	<span style="background-color: black; color: black;">Non-responsive content removed</span>	Date: 3/10/2011				
Signature:	<span style="background-color: black; color: black;">Non-responsive content removed</span>	Date: 3/10/2011	Signature:	<span style="background-color: black; color: black;">Non-responsive content removed</span>				





EA11003EN-00924[0]

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no. <span style="background-color: black; color: black;">[REDACTED]</span>												
				Date 3/10/2011												
Department: Non-responsive content removed	Person responsible: Non-responsive content removed	Telephone: Non-responsive content removed	Use <table border="1" style="display: inline-table; vertical-align: middle;"> <tr> <td>internal</td> <td></td> </tr> <tr> <td>external</td> <td>x</td> </tr> </table>		internal		external	x								
internal																
external	x															
			<b>Confidentiality note</b> Confidential													
To: For information:	Non-responsive content removed															
<b>Pump type:</b> CP4.1S_398_2x6_REC_3.3_1.95_MT4.2		<b>Customer:</b> VW	<b>Project:</b> R4 2.0 BIN5	<b>Project / design pattern type</b> Series / Series												
<b>Part number (TTNo.):</b> 0445010514		<b>Date of manufacture:</b> 250310	<b>Serial number:</b> 0449	<b>Manufacturing plant - line</b> 5150 JhP (Jihlava plant) -												
<b>Actual mileage is [h]</b> 890 h		<b>Fuel:</b> EN590	<b>MAP-No.</b> DS-265015													
<b>SAP-No.:</b> 30-101933-06		<b>Samos no.:</b> 796025	<b>Customer order no.:</b>	<b>Engine/Vehicle number</b> C3LF / 21493												
<b>Customer part number</b> 03L 130 755 D		<b>DSBFD no.:</b> 29797	<b>Endurance run type [customer]:</b> Engine endurance run	<b>Endurance run conditions:</b> TTHS/SRT												
<b>1. Subject</b> CP4 customer returns without complaint, pump diagnosed Engine no. C3LE/21493 120 kW (Crafter 4 cyl.) Emission standard: EU5, mileage: 890 h, endurance run profile TTHS / SRT																
<b>2. Conclusion</b> <b>Function:</b> The pump function is within the specification limits. There is no significant drift in comparison to the delivery measurement. <b>Components:</b> Wear of the components is low and without significant striking features. <b>Result:</b> The pump has passed the endurance run.																
<b>3. Results of diagnosis (visual findings)</b> <div style="float: right; text-align: right;">         Legend rating stages         <table border="1" style="display: inline-table; vertical-align: middle;"> <tr> <td>OK</td> <td style="background-color: green; color: white;">x</td> <td></td> <td></td> </tr> <tr> <td>Uncritical</td> <td></td> <td style="background-color: yellow; color: black;">x</td> <td></td> </tr> <tr> <td>Critical</td> <td></td> <td></td> <td style="background-color: red; color: white;">x</td> </tr> </table> </div>					OK	x			Uncritical		x		Critical			x
OK	x															
Uncritical		x														
Critical			x													
<b>3.1 Drive</b> No striking feature		<table border="1" style="display: inline-table; vertical-align: middle;"> <tr> <td style="background-color: green; color: white;">x</td> <td></td> <td></td> </tr> </table>			x											
x																
<b>3.2 Drivetrain</b> No striking feature		<table border="1" style="display: inline-table; vertical-align: middle;"> <tr> <td style="background-color: green; color: white;">x</td> <td></td> <td></td> </tr> </table>			x											
x																
<b>3.3 High pressure</b> No striking feature		<table border="1" style="display: inline-table; vertical-align: middle;"> <tr> <td style="background-color: green; color: white;">x</td> <td></td> <td></td> </tr> </table>			x											
x																
<b>3.4 Bearing</b> No striking feature		<table border="1" style="display: inline-table; vertical-align: middle;"> <tr> <td style="background-color: green; color: white;">x</td> <td></td> <td></td> </tr> </table>			x											
x																
<b>3.5 Shaft seal</b> No striking feature		<table border="1" style="display: inline-table; vertical-align: middle;"> <tr> <td style="background-color: green; color: white;">x</td> <td></td> <td></td> </tr> </table>			x											
x																
<b>3.6 Holes</b> No striking feature		<table border="1" style="display: inline-table; vertical-align: middle;"> <tr> <td style="background-color: green; color: white;">x</td> <td></td> <td></td> </tr> </table>			x											
x																

EA11003EN-00924[1]






 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.	[Redacted]	
				Date	3/10/2011	
Department: Non-responsive content removed	Person responsible:	Telephone:		Use	internal	
					external	x
				Confidentiality note Confidential		
<b>3.7 Attached components (metering unit, overflow valve, counting point)</b> No striking feature						<input checked="" type="checkbox"/>
<b>3.8 O-rings</b> No striking feature						<input checked="" type="checkbox"/>
<b>3.9 Other</b> No striking feature						<input checked="" type="checkbox"/>
<b>3.10 Images</b>						
<b>4. Hydraulic function</b> The pump function is within the specification limits. There is no significant drift in comparison to the delivery measurement.						
	n[rpm]	p_rail [bar]	I_MU [A]	Delivery rate [l/h] New part 3/25/2010	Delivery rate [l/h] After testing 11/8/2010	
ST	200	200	0.4	4.6	4.7	<input checked="" type="checkbox"/>
LG	1000	1800	0.4	20.6	20.5	<input checked="" type="checkbox"/>
<b>5. Destiny of the parts</b> The pump parts remain with Robert Bosch GmbH at the request of the customer						
<b>6. Attachments</b> None						
Tested:	Non-responsive content removed	Telephone:	Non-responsive content removed	Date:	3/10/2011	Signature:
Department		Telephone:		Date:	3/10/2010	Signature:

EA11003EN-00925[0]



 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.	[REDACTED]														
				Date	9/22/2011														
Department:	Person responsible:	Telephone:	Use	internal															
Non-responsive content removed			external		x														
			Confidentiality note																
			Confidential																
To:	Non-responsive content removed																		
For information:	[REDACTED]																		
<b>Pump type:</b> CP4.2HS_747_2x5.63_REC_3,3_1,3_MT4,2		<b>Customer:</b> AUDI		<b>Project:</b> W36 2000bar (Q7)		<b>Project / design pattern type</b> D/D													
<b>Part number (TTNo.):</b> 0445B20249_08		<b>Date of manufacture:</b> 990		<b>Serial number:</b> 4011		<b>Manufacturing plant - line</b> 011M FeP (Feuerbach plant)-M													
<b>Actual mileage is [h]</b> 160565 km		<b>Fuel:</b> India EU3				<b>MAP-No.</b> DS-276680													
<b>SAP-No.:</b> 30-101921-06		<b>Samos no.:</b> 813822		<b>Customer order no.:</b>		<b>Engine/Vehicle number</b> 059.H W36 586 / AU641 04046													
<b>Customer part number</b> 059 130 755 AK		<b>DSBFD no.:</b> 31082		<b>Endurance run type [customer]:</b> Vehicle endurance run		<b>Endurance run conditions:</b> 3-zone endurance run (NK6, cool1, hot)													
<b>1. Subject</b> CP4 Customer returns <b>without</b> complaint Diagnosis after endurance run end 160,565 km vehicle durability test Engine no. 059.H W36 586 / Vehicle No.: AU641 04046 Anti-wear package: without Testing country: Germany																			
<b>2. Conclusion</b> <b>Function:</b> - Delivery rates after endurance run or test without significant fuel-quantity drift in comparison with the new state. <b>Components:</b> - The shaft seal on pump side (inside) shows increased wear (see Figure 3). However, this is classified as uncritical. - Both spring plates show smoothening with slight noticeable grooves (see Figures 1 and 2). The wear of the two components is not critical and does not affect the function. - Wear of the other components is low and without significant striking features. <b>Result:</b> - Wear of the shaft seal is increased most likely due to reduced lubricity of the fuel. This indicates a reduced viscosity of the fuel. Maybe, there was a slightly increased proportion of free water or gasoline from the fuel at times. - The pump has passed the <b>endurance run</b>																			
<b>3. Results of diagnosis (visual findings)</b>				Legend rating stages <table border="1"> <tr> <td>OK</td> <td>x</td> <td></td> <td></td> </tr> <tr> <td>Uncritical</td> <td></td> <td>x</td> <td></td> </tr> <tr> <td>Critical</td> <td></td> <td></td> <td>x</td> </tr> </table>				OK	x			Uncritical		x		Critical			x
OK	x																		
Uncritical		x																	
Critical			x																
<b>3.1 Drive</b> No striking feature				<table border="1"> <tr> <td>x</td> <td></td> <td></td> </tr> </table>				x											
x																			
<b>3.2 Drivetrain</b> Spring plate to the left and right: Smoothening with slight noticeable grooves (see Figures 1 and 2).				<table border="1"> <tr> <td></td> <td>x</td> <td></td> </tr> </table>					x										
	x																		
<b>3.3 High pressure</b> No striking feature				<table border="1"> <tr> <td>x</td> <td></td> <td></td> </tr> </table>				x											
x																			
<b>3.4 Bearing</b> No striking feature				<table border="1"> <tr> <td>x</td> <td></td> <td></td> </tr> </table>				x											
x																			



EA11003EN-00925[1]


 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.										
				Date	9/22/2011									
Department:	Person responsible:	Telephone:	Use	internal										
Non-responsive content removed			external		x									
			Confidentiality note											
			Confidential											
<b>3.5 Shaft seal</b>					x									
Shaft seal pump-side: increased wear (see Figure 3).														
<b>3.6 Holes</b>					x									
No striking feature														
<b>3.7 Attached components (Metering Unit, Overflow Valve, Counting Point)</b>					x									
No striking feature														
<b>3.8 O-rings</b>					x									
No striking feature														
<b>3.9 Other</b>					x									
No striking feature														
<b>3.10 Images</b>														
														
Fig. 1: Spring plate to the left, piston system		Figure 2: Spring plate to the right, piston system												
														
Fig. 3: Shaft seal, pump-side														
<b>4. Hydraulic function</b>					<table border="1"> <tr> <td></td> <td></td> <td></td> </tr> <tr> <td>x</td> <td></td> <td></td> </tr> <tr> <td>x</td> <td></td> <td></td> </tr> </table>				x			x		
x														
x														
			Delivery rate [l/h] of new part	Delivery rate [l/h] after testing										
	n[rpm]	p_rail [bar]	I_MU [A]	11/17/2009	3/10/2001									
ST	200	200	0.4	8.5	8.5									
LG	1000	2000	0.4	35.9	36.4									
No significant volumetric efficiency change, the volumetric efficiency is within the tolerance specified in the TCD (technical customer documentation) for new parts.														

EA11003EN-00925[2]


 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no. <span style="background-color: black; color: black;">[REDACTED]</span>					
				Date 9/22/2011					
Department: <span style="background-color: black; color: black;">[REDACTED]</span>		Person responsible: <span style="background-color: black; color: black;">[REDACTED]</span>		Telephone: <span style="background-color: black; color: black;">[REDACTED]</span>					
				Use <table border="1" style="display: inline-table; vertical-align: middle;"> <tr> <td>internal</td> <td><input type="checkbox"/></td> </tr> <tr> <td>external</td> <td><input checked="" type="checkbox"/></td> </tr> </table>		internal	<input type="checkbox"/>	external	<input checked="" type="checkbox"/>
internal	<input type="checkbox"/>								
external	<input checked="" type="checkbox"/>								
				Confidentiality note Confidential					
<b><u>5. Destiny of the parts</u></b>									
The pump will be scrapped at the request of Audi.									
<b><u>6. Attachments</u></b>									
Appendix 1: Diagnosis images of drivetrain									
Tested:	Non-responsive content removed	Telephone:	Non-responsive content removed	Date:					
Signature:									
Department	<span style="background-color: black; color: black;">[REDACTED]</span>	Telephone:	<span style="background-color: black; color: black;">[REDACTED]</span>	Date:					
Signature:									

EA11003EN-00925[3]


## Appendix 1 to process 2011-CP4\_0203




**Fig. 1: Roller support to the left**  
Slight deposit R3




**Fig. 2: Roller support to the right**




**Fig. 3: Roller to the left**  
Faint brown discoloration R3



**Fig. 4: Roller to the right**  
Faint brown discoloration R3





**Fig. 5: Camshaft, running surface US1**



**Fig. 6: Camshaft, running surface LS1**



 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.	
				Date	7/11/2011
Department:	Person responsible:	Telephone:	Use	internal <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> external <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>	
Non-responsive content removed					
			Confidentiality note Confidential		
To:	Non-responsive content removed				
For information:					
Pump type:	Customer:	Project:	Project / design pattern type		
CP4.1S_398_2x6_REC_3,3_1,95_MT4,2	VW	R4 2L EA189 Gen2 BIN5	C / C		
Part number (TTNo.):	Date of manufacture:	Serial number:	Manufacturing plant - line		
0445B21210_01	006	4327	011M FeP (Feuerbach plant)-M -		
Actual mileage is [h]	Fuel:		MAP-No.		
101180 km	North China fuel		DS- 280121		
SAP-No.:	Samos no.:	Customer order no.:	Engine/Vehicle number		
30-104330-20	819666	03L130755 AB	VW316_BW088-0S, 103 kW		
Customer part number	DSBFD no.:	Endurance run type [customer]:	Endurance run conditions:		
731325	31512	Vehicle endurance run	Profile radial run-out North China		

### 1. Subject

CP4 customer returns **without complaint**  
 Diagnosis after endurance run end  
 101180km vehicle durability test  
 Anti-wear package for the roller support: AWP1  
 Anti-wear package for the high-pressure piston: AWP0  
 Engine no. VW316 BW088-0S  
 Testing country:

### 2. Conclusion

**Function:**  
 - The hydraulic delivery rates after endurance run or trial are without significant drift of quantity in comparison with the new state.

**Components:**  
 - The roller support shows a groove due to particle draft (see 3.10, Figure 1).  
 - The spring plate shows noticeable grooves and smoothening over large area (see 3.10, Figure 2).  
 - The above-mentioned striking feature should be classified as uncritical.  
 - The remaining components show normal wear pattern.

**Result:**  
 The pump has **passed the endurance run**.

### 3. Results of diagnosis (visual findings)

**3.1 Drive**  
No striking feature

**3.2 Drivetrain**  
Roller support to the right: Particle draft (see 3.10, Figure 1).

**3.3 High pressure**  
No striking feature

**3.4 Bearing**  
No striking feature

Legend rating stages

OK	<div style="background-color: green; width: 15px; height: 15px; display: flex; align-items: center; justify-content: center;">&gt;</div>	<div style="background-color: white; width: 15px; height: 15px; display: flex; align-items: center; justify-content: center;">&gt;</div>	<div style="background-color: white; width: 15px; height: 15px; display: flex; align-items: center; justify-content: center;">&gt;</div>
Uncritical	<div style="background-color: yellow; width: 15px; height: 15px; display: flex; align-items: center; justify-content: center;">&gt;</div>	<div style="background-color: white; width: 15px; height: 15px; display: flex; align-items: center; justify-content: center;">&gt;</div>	<div style="background-color: white; width: 15px; height: 15px; display: flex; align-items: center; justify-content: center;">&gt;</div>
Critical	<div style="background-color: white; width: 15px; height: 15px; display: flex; align-items: center; justify-content: center;">&gt;</div>	<div style="background-color: white; width: 15px; height: 15px; display: flex; align-items: center; justify-content: center;">&gt;</div>	<div style="background-color: red; width: 15px; height: 15px; display: flex; align-items: center; justify-content: center;">&gt;</div>

>

>

>

x





>

>



>

>

>




 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.	[Redacted]		
				Date	7/11/2011		
Department:	Person responsible:	Telephone:	Use <span style="float: right;">internal <input type="checkbox"/> external <input checked="" type="checkbox"/></span>				
Non-responsive content removed							
			Confidentiality note Confidential				
3.5 Shaft seal			<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>				
No striking feature							
3.6 Holes			<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>				
No striking feature							
3.7 Attached components (Metering Unit, Overflow Valve, Counting Point)			<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>				
No striking feature							
3.8 O-rings			<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>				
No striking feature							
3.9 Other			<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>				
No striking feature							
3.10 Images							
 <p>Particle draft</p>			 <p>Noticeable groove</p>				
Fig. 1: Roller support to the right, running surface			Image 2: Spring plate to the right, piston system				
<b>4. Hydraulic function</b>							
	n[rpm]	p_rail [bar]	I_MU [A]	Delivery rate [l/h] of new part	Delivery rate [l/h] after testing	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	
				6/29/2010	7/5/2011		
LG	1000	1800	0.4	21.0	21.0		
ST	200	2	0.4	4.4	4.4	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	
The volumetric efficiency was checked and is within the tolerance specified in the TCD for new parts.							
<b>5. Destiny of the parts</b>							
The pump will be scrapped at the request of VW.							
<b>6. Attachments</b>							
No appendices.							
Tested:	Non-responsive content removed	Telephone:	Non-responsive content removed	Date:	7/14/2011	Signature:	Non-responsive content removed
Department:		Telephone:		Date:	7/15/2011	Signature:	

EA11003EN-00927[0]



 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.														
				Date	7/12/2011													
Department:	Person responsible:	Telephone:	Use <table border="1"> <tr> <td>internal</td> <td></td> <td></td> </tr> <tr> <td>external</td> <td></td> <td>x</td> </tr> </table>				internal			external		x						
internal																		
external		x																
Non-responsive content removed																		
			<b>Confidentiality note</b> Confidential															
To:	Non-responsive content removed																	
For information:																		
<b>Pump type:</b> CP4.1S_398_2x6_REC_3,3_1,9 5_MT4,2		<b>Customer:</b> VW	<b>Project:</b> R4 2L EA189 Gen2 BIN5	<b>Project / design pattern type</b> C / C														
<b>Part number (TTNo.):</b> 0445B21210_01	<b>Date of manufacture:</b> 006	<b>Serial number:</b> 4331	<b>Manufacturing plant - line</b> 011M FeP (Feuerbach plant)-M -															
<b>Actual mileage</b> 60000 km	<b>Fuel:</b> North China fuel		<b>MAP-No.</b> DS-280122															
<b>SAP-No.:</b> 30-104330-20	<b>Samos no.:</b> 819666	<b>Customer order no.:</b> VW316_BW090-0S	<b>Engine/Vehicle number</b> VW316_BW090-0S, 103 kW															
<b>Customer part number</b> 731325	<b>DSBFD no.:</b> 31513	<b>Endurance run type [customer]:</b> Vehicle endurance run	<b>Endurance run conditions:</b> Profile radial run-out North China															
<b>1. Subject</b> CP4 customer returns <b>without complaint</b> Diagnosis after endurance run end 60,000 km vehicle durability test Anti-wear package for the roller support: AWP1 Anti-wear package for the high-pressure piston: AWP0 Engine no. VW316_BW090-0S Testing country:																		
<b>2. Conclusion</b> <b>Function</b> - The hydraulic delivery rates after endurance run or trial are without significant drift of quantity in comparison with the new state. <b>Components</b> -The spring plate has noticeable grooves and large smoothening (see 3.10, Figure 1). -The above-mentioned striking feature is yet to be classified as <b>uncritical</b> . <b>Result</b> - The pump has <b>passed the endurance run</b> .																		
<b>3. Results of diagnosis (visual findings)</b>			Legend rating stages <table border="1"> <tr> <td>OK</td> <td>x</td> <td></td> <td></td> </tr> <tr> <td>uncritical</td> <td></td> <td>x</td> <td></td> </tr> <tr> <td>Critical</td> <td></td> <td></td> <td>x</td> </tr> </table>				OK	x			uncritical		x		Critical			x
OK	x																	
uncritical		x																
Critical			x															
<b>3.1 Drive</b> No striking feature			<table border="1"> <tr> <td>x</td> <td></td> <td></td> </tr> </table>				x											
x																		
<b>3.2 Drivetrain</b> Noticeable grooves and smoothening over a large area (see 3.10, Figure 1)			<table border="1"> <tr> <td></td> <td>x</td> <td></td> </tr> </table>					x										
	x																	
<b>3.3 High pressure</b> No striking feature			<table border="1"> <tr> <td>x</td> <td></td> <td></td> </tr> </table>				x											
x																		
<b>3.4 Bearing</b> No striking feature			<table border="1"> <tr> <td>x</td> <td></td> <td></td> </tr> </table>				x											
x																		




EA11003EN-00927[1]

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.	[REDACTED]	
				Date	7/12/2011	
Department:	Person responsible:	Telephone:	Use	internal	external	x
Non-responsive content removed						
			<b>Confidentiality note</b> Confidential			
<b>3.5 Shaft seal</b>				<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
No striking feature						
<b>3.6 Holes</b>				<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
No striking feature						
<b>3.7 Attached components (metering unit, overflow valve, counting point)</b>				<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
No striking feature						
<b>3.8 O-rings</b>				<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
No striking feature						
<b>3.9 Other</b>				<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
No striking feature						
<b>3.10 Images</b>						
						
Fig. 1: Spring plate to the right, piston						
<b>4. Hydraulic function</b>						
				Delivery rate [l/h] of new part	Delivery rate [l/h] after testing	
	n[rpm]	p_rail [bar]	I_MU [A]	6/29/2010	7/5/2011	
LG	1000	1800	0.4	21.1	21.2	<input checked="" type="checkbox"/>
ST	200	200	0.4	4.5	4.4	<input checked="" type="checkbox"/>
The volumetric efficiency was checked and is within the tolerance specified in the TCD for new parts.						
<b>5. Destiny of the parts</b>						
The pump will be scrapped at the request of VW.						
<b>6. Attachments</b>						
No appendices.						
Tested:	Non-responsive content removed	Phone	Non-responsive content removed	Date:	7/15/2011	Signature:
Department:	[REDACTED]	Phone	[REDACTED]	Date:	7/15/2011	Signature:

EA11003EN-00928[0]

 <b>BOSCH</b> 		<b>CR pump CP4 - Diagnosis report</b>		Report no.													
				Date	7/12/2011												
Department:	Person responsible:	Telephone:	Use <table border="1"> <tr> <td>internal</td> <td></td> <td></td> </tr> <tr> <td>external</td> <td></td> <td>x</td> </tr> </table>			internal			external		x						
internal																	
external		x															
Non-responsive content removed																	
			<b>Confidentiality note</b> Confidential														
To:	Non-responsive content removed																
For information:																	
<b>Pump type:</b> CP4.1S_398_2x6_REC_3,3_1,9 5_MT4,2		<b>Customer:</b> VW	<b>Project:</b> R4 2L EA189 Gen2 BIN5	<b>Project / design pattern type</b> C / C													
<b>Part number (TTNo.):</b> 0445B21210_01	<b>Date of manufacture:</b> 006	<b>Serial number:</b> 4329	<b>Manufacturing plant - line</b> 011M FeP (Feuerbach plant)- M -														
<b>Actual mileage</b> 101077 km	<b>Fuel:</b> North China fuel		<b>MAP-No.</b> DS-280123														
<b>SAP-No.:</b> 30-104330-20	<b>Samos no.:</b> 819666	<b>Customer order no.:</b> VW316_BW077-0S	<b>Engine/Vehicle number</b> VW316_BW077-0S, 103 kW														
<b>Customer part number</b> 731325	<b>DSBFD no.:</b> 31514	<b>Endurance run type [customer]:</b> Vehicle endurance run	<b>Endurance run conditions:</b> Profile radial run-out North China														
<b>1. Subject</b> CP4 customer returns <b>without complaint</b> Diagnosis after endurance run end 1,01,077km vehicle endurance run Anti-wear package for the roller support: AWP1 Anti-wear package for the high-pressure piston: AWP0 Engine no. VW316_BW077-0S Testing country: North China																	
<b>2. Conclusion</b> <b>Function</b> - The hydraulic delivery rates after endurance run or trial are without significant drift of quantity in comparison with the new state. <b>Components</b> Wear of the components is low and without significant striking features. <b>Result</b> - The pump has <b>passed the endurance run.</b>																	
<b>3. Results of diagnosis (visual findings)</b>			Legend rating stages { <table border="1"> <tr> <td>OK</td> <td>x</td> <td></td> <td></td> </tr> <tr> <td>uncritical</td> <td></td> <td>x</td> <td></td> </tr> <tr> <td>Critical</td> <td></td> <td></td> <td>x</td> </tr> </table>			OK	x			uncritical		x		Critical			x
OK	x																
uncritical		x															
Critical			x														
<b>3.1 Drive</b> No striking feature			<table border="1"> <tr> <td>x</td> <td></td> <td></td> </tr> </table>			x											
x																	
<b>3.2 Drivetrain</b> No striking feature			<table border="1"> <tr> <td>x</td> <td></td> <td></td> </tr> </table>			x											
x																	
<b>3.3 High pressure</b> No striking feature			<table border="1"> <tr> <td>x</td> <td></td> <td></td> </tr> </table>			x											
x																	
<b>3.4 Bearing</b> No striking feature			<table border="1"> <tr> <td>x</td> <td></td> <td></td> </tr> </table>			x											
x																	

EA11003EN-00928[1]

		<b>CR pump CP4 - Diagnosis report</b>		Report no. <span style="background-color: black; color: black;">[REDACTED]</span>							
				Date 7/12/2011							
<b>Department:</b> Non-responsive content removed	<b>Person responsible:</b> Non-responsive content removed	<b>Telephone:</b> Non-responsive content removed	<b>Use</b> <table border="1"> <tr> <td>internal</td> <td><input checked="" type="checkbox"/></td> <td><input type="checkbox"/></td> </tr> <tr> <td>external</td> <td><input type="checkbox"/></td> <td><input checked="" type="checkbox"/></td> </tr> </table>			internal	<input checked="" type="checkbox"/>	<input type="checkbox"/>	external	<input type="checkbox"/>	<input checked="" type="checkbox"/>
internal	<input checked="" type="checkbox"/>	<input type="checkbox"/>									
external	<input type="checkbox"/>	<input checked="" type="checkbox"/>									
			<b>Confidentiality note</b> Confidential								
<b>3.5 Shaft seal</b> No striking feature			<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>								
<b>3.6 Holes</b> No striking feature			<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>								
<b>3.7 Attached components (metering unit, overflow valve, counting point)</b> No striking feature			<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>								
<b>3.8 O-rings</b> No striking feature			<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>								
<b>3.9 Other</b> No striking feature			<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>								
<b>3.10 Images</b>											
<b><u>4. Hydraulic function</u></b>											
				Delivery rate [l/h] of new part	Delivery rate [l/h] after testing						
	n[rpm]	p_rail [bar]	I_MU [A]	6/29/2010	7/5/2011						
LG	1000	1800	0.4	21.1	21.2						
ST	200	200	0.4	4.4	4.4						
				<input checked="" type="checkbox"/>	<input type="checkbox"/>						
				<input checked="" type="checkbox"/>	<input type="checkbox"/>						
The volumetric efficiency was checked and is within the tolerance specified in the TCD for new parts.											
<b><u>5. Destiny of the parts</u></b> The pump will be scrapped at the request of VW.											
<b><u>6. Attachments</u></b> No appendices.											
<b>Tested:</b>	Non-responsive content removed	<b>Phone</b>	Non-responsive content removed	<b>Date:</b>	7/15/2011						
<b>Signature:</b>	Non-responsive content removed										
<b>Department:</b>	Non-responsive content removed	<b>Phone</b>	Non-responsive content removed	<b>Date:</b>	7/15/2011						
<b>Signature:</b>	Non-responsive content removed										



**CP4 – Diagnosis 17858****BOSCH**

From:	Persons responsible	Phone extension	Phone extension	Feuerbach 6/6/2007
Non-responsive content removed				
To:	Non-responsive content removed			
For information:	Non-responsive content removed			

<b>Customer:</b>	VW	<b>IBAS number:</b>	105 225 862
<b>Component:</b>	CP4.1S-348-2X5.25-REC	<b>SaMOS:</b>	0560399
<b>Project:</b>	R4 2.01 Tdi	<b>Customer order / MKV no.:</b>	
<b>Engine / block no.:</b>		<b>Parts receipt at dept. DS-PC/EDI:</b>	5/7/2007
<b>TTNo.:</b>	0 445 B21 058_02	<b>Manufacturing site:</b>	0110 (Feuerbach plant)
<b>DoM:</b>	685	<b>Pattern type:</b>	C
<b>Serial no.:</b>	0044	<b>Running time:</b>	605 h
<b>Add-on parts:</b>	Metering Unit	<b>Complaint:</b>	Endurance run end
<b>Operating conditions:</b>	KRT (customer information)		

**1. Description of problem**

The pump should be diagnosed and assessed according to the durability trial.

**2. Diagnosis result***Leak-tightness:*

The pump was seal-tight in the immersion test (air with 6 bar<sub>rel</sub>, 10 min).

*Function:*

Quantity is within test tolerance for new parts at all testing points. The seal-tightness of the HP valve is OK. No hydraulic defects were found.

*Parts visual findings:*

The drivetrain parts (camshaft, roller, roller support, HP pistons, bearings) are in very good condition. The machining marks on the cam track are still visible. No striking feature present.

**3. Conclusion**

The pump does not show any striking feature in the function and wear. The pump has passed the test.

**4. Destiny of the parts**

The parts are returned to the customer.

Checked by:	Non-responsive content removed	Telephone:	Non-responsive content removed	Date:	6/6/2007	Signature:	Non-responsive content removed
Department		Telephone:		Date:	6/11/2007	Signature:	
E. dept.:		Telephone:		Date:	6/14/2007	Signature:	

Report passed on to the customer: yes

**CP4 – Diagnosis 17846****BOSCH**

From:	Persons responsible	Phone extension	Phone extension	Feuerbach 6/22/2007
Non-responsive content removed				
To:	Non-responsive content removed			
For information:				
				Page 1 of 2 Appendix 0 page (s)

<b>Customer:</b>	VW	<b>IBAS number:</b>	105 225 852
<b>Component:</b>	CP4.1S-348-2X5.25-REC	<b>Samos:</b>	0560377
<b>Project:</b>	R4 2.01 Tdi	<b>Customer order / MKV no.:</b>	
<b>Engine / block no.:</b>	03LD/16351	<b>Parts receipt at dept. DS-PC/EDI:</b>	5/7/2007
<b>TTNo.:</b>	0 445 B21 043_02	<b>Manufacturing site:</b>	0110 (Feuerbach plant)
<b>DoM:</b>	681	<b>Pattern type:</b>	B3.3
<b>Serial no.:</b>	4768	<b>Running time:</b>	950h
<b>Add-on parts:</b>	Metering Unit	<b>Complaint:</b>	Endurance run end
<b>Operating conditions:</b>	Application		

**1. Description of problem**

The pump should be diagnosed and assessed according to the durability trial.

**2. Diagnosis result***Leak-tightness:*

The pump was seal-tight in the immersion test (air with 6 bar<sub>rel</sub>, 10 min).

*Function:*

Quantity is within test tolerance for new parts at all testing points. The seal-tightness of the HP valve is OK. No hydraulic defects were found (see Table 1)

*Parts visual findings:*

The drivetrain parts (camshaft, roller, roller support, HP pistons, bearings) are in very good condition. The machining marks on the cam track are still visible. No striking feature present.

**3. Conclusion**

The pump does not show any striking feature in the function and wear. The pump has passed the test.

**4. Destiny of the parts**

The parts are returned to the customer.

				Delivery measurement	Back measurement
	n[rpm]	p [bar]	iMetering Unit [A]	1/30/2006	5/9/2007
KL1-S	3375	500	0.40	77.9	78.1
LG	1000	1800	0.40	20.4	20.4
ST	200	200	0.40	4.5	4.5

Table 1: Functional test 681-4768

CP4 – Diagnosis 17846



From:	Persons responsible	Phone extension	Phone extension	Feuerbach
Non-responsive content removed				6/22/2007
To:	Non-responsive content removed			
For information:	Non-responsive content removed			
	Fischer			

Checked by:	Non-responsive content removed	Telephone:	Non-responsive content removed	Date:	6/25/2007	Signature:	Non-responsive content removed
Department	Non-responsive content removed	Telephone:	Non-responsive content removed	Date:	6/27/2007	Signature:	Non-responsive content removed
E. dept.:	Non-responsive content removed	Telephone:	Non-responsive content removed	Date:	6/27/2007	Signature:	Non-responsive content removed

Report passed on to the customer: yes



EA11003EN-00931[0]

VOLKSWAGEN



## HPFP - Assessment

Manufacturer	Bosch	Date	26.01.10
Series	CP4.1	Person in charge	
VW - part number	03L130755	Project	RPU
Manufacturer part no.	0445010507	Engine no.	CDC 000002
Serial no. / DoM	BPT 1451 / 260109	Output:	
Drawing no. / pattern		Fuel	
Revision index	0007	Vehicle / test rig	
Plant	515	Running time /	100000 km
Complaints / comments	RPU verification engine		

Component	Assessment		Remark
	OK	Not OK	
<b>housing</b>			
Drive shaft	X		
Roller support	X		
Roller	X		
Tappet hole	X		
HP piston	X		
Spring washer / anti-friction paint coating	X		
Shaft seal / seal-tightness	X		
Corrosion	X		
Bearing	X		
LP ports	X		
HP ports	X		
MU / MU hole	X		
<b>Hydraulic function</b>			
Delivery rate			
Injection pressure			
Drive power			
Seal-tightness under load			
Pressure valves	X		
Overflow valve			
Dirt / chips	X		
<b>Electrical function</b>			
Plug contacts	X		
Metering Unit			
<b>Remarks:</b>			

Non-responsive content removed