
Drivetrain damage VW/Audi CP4.1(-507/508) 0 km and field /FD-KW



Appendix


Status: 9/14/2008

BOSCH Group Confidential

24.09.2008

Page 1

Drivetrain damage VW/Audi CP4.2 (-611/613) 0 km and field /FD-KW




Non-responsive content remove d

Appendix

oved

Status: 9/14/2008

Drivetrain damage CP4.2 VW/Audi



Non-responsive content remove d


Appendix

BOSCH Group Confidential

24.09.2008

Page 1

Failures due to drivetrain damage FD-KW



All, field
All, 0 km
All RB series test bench
Ppm all/WK
10.05 No reuse of tappets if not OK Pressing process
10.05 Click-clack test
23.05 Delta T and Delta Tmax test of test
29.05 Click-clack inspection at the end of the assembly conveyor belt
30.05 New switching procedure between flushing and inspection
18.06 Continuous noise measurement
20.06 Repeat inspection on frictional coefficient test bench dropped
09.07 Optimization of test bench process optimized (n>500 1/min)
23.07 CH assembly with 5 ⁰ torsion
23.07 Dry pressing in of roller shoe
23.07 Uncoated spring plate (BMW)
28.08 Introduction of dwell time in assembly, roller
01.10 Extension of checkpoint heavy load
16.11 Inspection V7.2 (BMW)
13.12 Improved visual inspection, RS
13.12 Frictional coefficient check +/- 10 ⁰
12/21/2007 Tappet check in assembly
1/2/2008 New visual test catalog, RS
1/11/2008 Inspection V7.2 (VW) visual test catalog, RS
Inspection V7.2 (Audi)
7.4 Straightedge test CP4.2 visual inspection catalog, RS
1.5 Cleaning cloth with
1.5 Visual inspection LR for C
1.5 Opt. C coating

Non-responsive content remove d

Appendix

Task force activities to reduce power train failures

- 1. 1) Metalization on roller shoe (RS)
- 1.1) Prevention of metalization

Graphite/boron nitride covering on holders in C layer coating system

Test new system done

2-day production/major test planned
 T. under discussion

If test is positive, introduction planned
 T. under discussion

1.2) Detection of metalization

- Feasibility study for objective measurement processes done
- Two quotations for camera monitoring in progress, major trial under series conditions required for evaluation purposes (avoidance of pseudo scrap)
- Ordering of preferred solution for 1st line in FeP planned by WK 44, implementation then expected by 04.09.
- 2 visual inspections used at present (after finishing or frictional coefficient test)



Task force activities to reduce power train failures

3) Avoidance of C layer removal during washing/ transport, RS New washing/ transport frame

• first 100 done

Complete changeover
 WK 40→WK 42

3.1) Avoidance of C layer removal during pressing, RS in tappet body SK

- Peeling particles of from the C layer on RS are transferred during frictional coefficient measurement and can lead to early damage. The following potential remediation measures are currently being assessed:
 - Optimization of C-layer adhesion
 - Avoiding C-layer
- Draw up a schedule for further procedures

WK39



Task force activities to reduce power train failures

Activities involving transfer of C particles to roller show - further action

1	 Analysis of a rail system set (480) prior to the pressing process →identify peculiarities, observe flow, and take a closer look at anomalies, flow under the microscope 	WK 40
2	. Feasibility assessment of "brushing" rail system surface (after applying C layer)	WK 44
3	. Analysis of the C layer ridge found. Implementation of an FIP section	Wk 43
4	 Change to RS retaining tool when inserting the tappet body →smaller support surface, better coverage 	WK 48



Wk 48

5. Feasibility study for omitting coating on RS surface

4) Avoiding "fusing" on cam roller.

Currently there are two solution approaches being considered:

- a) Improvement of cam roller contact through resilient contact plate
- b) direct alignment of the rollers ("stack of wood") for improved contact
- b) is favored and prioritized; if effect is positive implementation by Wk 48
- Currently there are 2 x straightedge tests used to positive effect, since in the second test no faulty parts were found.

5) Change to construction layout

- Change to layer system, cam roller camber from C3 to C2 (testing W24 D4, VW package 3)
- Improved tight fit for the roller shoe/tappet body press assembly
 R.B. internal testing

WK 43

Replication operation with non-OK rollers

Topic

Confirmation of failure hypothesis for "export countries"

"Drivetrain damage due to combination of stiff cam roller (in this instance, fusing on the cam roller) in combination with country-specific peculiarities (in this instance, fuel)" **through a replication test**

Implementation (0445010**613** instead of 0445010**611** due to C-coated piston to prevent piston seizure) CP4.2 W19 BIN5 with melt on the cam rollers (waste from straightedge test; subsequent frictional value test OK) set up and operated with poorly lubricating fuel GDK650 (HFRR 650 µm).

Result

Drivetrain damage after 35 hours of operation

Note

The **drivetrain** task force carried out several similar tests with EN590, although only one case of drivetrain damage occurred.

Conclusion

Result confirms the **failure hypothesis**. Pumps manufactured prior to the introduction of the straight-edge test (7.04.2008) can--in combination with poor lubricity--experience failures.







Photos after continuous test | Second | Photos | Photos


Development activities to reduce drivetrain failures

(focus on export countries Non-responsive content removed

Failure hypothesis:

Drivetrain damage due to combinations of stiff cam roller (slippage in production prior to introduction of the straightedge test, etc. 1.05.2008) + country-specific special features (fuel, transport, commissioning)

1) KT analysis with key question



- Why is the failure rate in Non-responsive content remo higher than in Non-responsive content removed
- Why is CP4.2 affected more than CP4.1 (production plant, components,...)





2) Investigation in relation to fuels and special fuel features in export markets 2.1) Water

Estimate: Unlikely, but one pump found with visible signs of corrosion

2.1.1) Action: Replication attempt with sloshing water

Result: no drivetrain damage, slight traces of tarnishing in housing

2.1.2) Action: Replication attempt with continual water entry

Result: drivetrain damage

2.1.2) Action: WCF test with 1% water & subsequent continuation with EN590

Result: will be presented 29.09.2009.

2.2) Fuel from Non-responsive content r

Estimation: probably in combination with other influencing factors (influence of special feature of fuel, steroyl glucosides unlikely)

2.2.1) Action: Obtain fuel samples from failure map

Result:

2.2.2) Action: Analysis of fuel from faulty pumps

Result: No striking features to date

Date 10.24.08 Non-responsive content removed

Date ongoing V. Audi,



BOSCH

Diesel systems

Confidential Non-responsive content removed | 9/24/2008 Non-responsive content removed | © Robert Bosch GmbH 2007. All rights reserved, including all use, exploitation, reproduction, processing, distribution and in the case of patent applications

2.3) Fuel from Non responsive content rem

Estimation: probably in combination with other influencing factors 2.3.1) Action: Provocative operation with non-OK Roller & GDK650

Result: Failure after 35 hours with final turned tappet

2.3.2) Action: Continuous replication testing with OK cam roller & GDK650,

but with stiff cam roller (friction testing committee)

Result:

Other continuous tests planned and pumps currently being set up)

2.4) Air in fuel

Assessment: Unlikely

(air found in pump inlet during vehicle measurement (Leasing Q7))

2.4.1) Action: Replication test with high air proportion

Result: no power train damage, but high degree of foam formation 2.4.2) Action: Research with Audi series electric fuel pump & filter

Result: Inline electric fuel pump can take in air via the filter

Recommendation: Verify NDKL layout design with borderline components.

2.4.3) Action: Continuous test with defined air input

Date CW 42 V. Non-responsive content rei

Date CW 41 V.

Continuous testing in combination with 'minimum' belt tension (determined on the

Engine

Diesel systems

Confidential | Non-responsive content removed | 9/24/2008 | Non-responsive content removed | © Robert Bosch GmbH 2007. All rights reserved, including all use, exploitation, reproduction, processing, distribution and in the case of patent applications



V. Audi



2.5) Other special features of fuel

Action: Analysis of fuel deposits

Date 09.29.2008

Result: Only one unusual pump. Rust, products from aging fuel & traces

of chlorine and silicone oxide. The source corrosion medium (probably containing chlorine) could

not be found. Other faulty pumps will be examined.



Diesel systems
Confidential | Non-responsive content removed | 9/24/2008 | Non-responsive content removed © Robert Bosch GmbH 2007. All rights reserved, including all use, exploitation, reproduction, processing, distribution and in the case of patent applications

ENTIRE PAGE CONFIDENTIAL

EA11003EN-00006[0]

tion Failure country Veh. n	o. Part no. Audi/VW F	RB no. QTS-/ AV3 r	o. IQIS no.	OMM3 Tasi pump force	k e Field Sampling		Veh.		veh plant ponsive content re	moved	Engine V6 V6 V6 3	Pump plan	P ML1	ML pump ML2 ML3 M	/L4 FD	FD Re	. Date	Mileson Norwal	Holler right	Additional information Comment / complaint	Cat.	Find to d	Result of frictional	Result of Invisions
of .				in FeP no:	Field Q-AL	plant test t	test. VW A	615 95,716			4 2,7l 3.0l BM 377 18.516 19.344 ?	is PeP Jhi	P ML1	ML2 ML3 M	AL4 Pump	Veh. Da	e Failure/ R		2 pistons only	Comment / complaint	Cat.	Fuel test	coefficient test	Result of findings / comment
si Non-res	03L 130 755 03L130 755	507 AV3 11809:	7 BSA000001209-001	4VW09								FeP	01-0055		20.10.2007			0 Nog.		Rail pressure too high (VW cold test) particles in HPFP Rail pressure too high (VW cold test) particles in HPFP				
conten t remov	03L 130 755	507 2943784	WIA000001838-001	4VW80 210 4VW81 211								FeP FeP FeP	01-0393		05.03.2008 11.03.2008			0 Nog	1 :	Zajos nem tennel nyomást Noise Pressure not OK	1			
ed	03L 130 755 A	507 2949867 508 7	WIA000001840-002 IGH000000105-001	4VW82 212 4VW02 49		×						FeP	01-0456	02-0272	10.03.2008 15.05.2007			0 Nog. 0 Nog.		Noise Pressure not OK Fuel pressure flow increases to about 8 bar after the start within about 15 seconds (maximum shaft brake)	+	£		
Engine CAS Engine CAS Engine CBE	003060 059 130 755 AB 022611 059 130 755 AB 003127 03L 130 755 A	611 2801936 611 2969671 508	WIA000001637-001 WIA000001879-001	4VW09 149 4A13 234 4VW104		X X	x			×	X	FeP FeP	01-0901 01-0078	02-0049	9/28/2007 19:03:2008 30:03:2008			0 Nog- 0 Nog- 0 ?	Nog.	The necessary pressure cannot be established No fuel pressure Breakdowns on roller	1	ОК	ок	Residual fuel in analysis until 12.09
tent remove	059 130 755 AB 059 130 755 AB 059 130 755 AB		WIA000002060-001 0 BSA000001162-001	4A73 4A02 59 4A03 60		X X X	×		No		X X X	FeP FeP	01-0010 01-0416		07.07.2008 14.05.2007 14.05.2007			0 0 Nog	Nog.	High-pressure pump drivetrain damage Particles in injector (delivered in disassembled state)	1	ОК		Flange bearing corrode particles
IUSA GOG-1K59N	059 130 755 AB	611 2799632 611 2814871	WIA000001635-001 WIA000001679-001	4A07 116 4A08 151 4VW77 209	x	X X	X		suffici prior fi CP	ing	x x	FeP FeP FeP FeP	01-0076 01-0068 01-0119		20.09.2007 20.09.2007 20.09.2007 23.08.2007		10.03.20	0 Nog 0 Nog 0 Nog 08 23.927 -	Nog. Nog.	Particles in srigotor (delivered in disassembled state) No CP4.2 conveyed volume Malfunction: proteably twisted tappet Engine will not start. High-pressure pump function Particles in fuel system. malfunction	1 1 1.b.d.			Hypothesis: Ridge on cam roller
8P28100022	5 03L 130 755	507 2973772		4VW87 233	X X		X	x		x	×	FeP FeP	01-0156 01-0626		12.10.2007 30.11.2007		19.03.20	08 15.425 Nog 40.000 Nog 62.300 Nog	-	Rail pressure sporadically not reached Engine died while driving at constant speed	4			metalization on C layer Poor quality fuel!!! W19 tension roller instead of W24
USA AU716 9 80 USA AU716 9 80 USA AU716 9 80	17 059 130 755 AG	613			X		X			×	X	FeP	01-0633 01-0388		30.11.2007 05.06.2008			6.800		Cardown Veh. mileage 69,100 km	1			W19 tension roller instead of W24 No drivetrain damage, UM and OV slove with black particles
Non-8K58A00129 8T68A03880	059 130 755 AG 73 059 130 755 AB 97 059 130 755 AB	613 611 33755/01 611 3014805	IGH000000402-001 IGG000002470-002	4A19 250 4A20 260	X		x x	x	see ab	we X	X X	FeP FeP FeP	01-0900 01-0314 01-0268		22.01.2008 24.05.2007 21.09.2007	13.09.	26.02.20 17,04.20	2.723 Nog. 08 11.027 Nog. 08 7.486 -		Vehicle will not start Engine will not start	1 5			24 tension roller 777
resp 8168A03886	73 059 130 755 AB 060 059 130 755 A	611 3081153 611 3081141 611 3094642	WIA000002702-001 WIA000002031-001 IGE000001961-001	4A19 250 4A20 260 4A29 4A46 4A30 4A44	X X		i i	l x		×	X X X X	FeP FeP FeP	01-0249	02-0641 02-0438	30.10.2008 30.10.2007 29.01.2008 07.05.2008	- 18.12. - 18.12. 22.02.2008 31.03.	2008 09.06.20 2007 11.06.20 2008 09.06.20	08 744 Nog. 08 8.000 Nog. 08 10.561 Nog.	Nog. Nog. Nog.	Electrical fault Non-responsive content rem oved (Mechanical fault	1	OK		WK 29 to Bosch
onsi 8K59N00122	28 059 130 755 AB	611 3105630		4A64 4A58	X X		×	×	x		X X	FeP FeP	0	02-0346 02-0676		28.05.2008 03.07.	2008 04.08.20 2008 5/20/200	08 3.641 Nog. 08 3.470 Nog.	Nog.	Mechanical fault		ОК		
ve c 4L68D05630 onte 8K88N00276	6 059 130 755 AB	611 3102986	IGG000002783-003	4A60 4A66	x		×	×		x	x	FeP	01-0004		22.02.2008 04.12.2007	- 05.05.	0008 7/22/200		Nog.	Non-responsive content removed	2	OK		F
nt r 8K39A0294	059 130 755 AB 059 130 755 AB 059 130 755 AB	611 3127768 611 3127772	IGG000002876-003	4A65 4A76 4A78	X		- X	×	X		X		01-0762 01-0378	02-0905	15.11.2007 17.11.2007 11.02.2008	- 09.01.	27.08.20	08 14.838 Nog.	Nog	Filter + fuel	-	OK		Pump OK
emo\(\frac{41.X8D03988}{41.98D05843}\)			IGG000002876-004 IGG000002876-002 W1H000000324-001	4A79 4A77 4A24 275	X X X		X	X		×	X X	FeP FeP	01-0167	02-0994 02-0447	08.05.2008 17.11.2007 06.03.2008	26.06.	2008 04.08.20	08 2.882 Nog.	Nog.	Fuel	1	OK OK		Engine reflex incorrectly installed
ed 4L58D05843 4L58D04879 4L68D04209	77 059 130 755 AB 17 059 130 755 AB 15 059 130 755 AB 17 059 130 755 AB 17 059 130 755 AB 18 059 130 755 AB 10 059 130 755 AB 11 059 130 755 AB	611 3108206 611 3089357 611 3124575	WIA000002030-001 IGG000002871-001	4A45 4A74 4A75	X X		x			X X	X X X	FeP FeP	01-0062 01-1108	02-0485	16.01.2008 15.01.2008	- 18.04. - 27.03.	2008 30.06.20 2008 25.08.20 2008 25.08.20	08 13.581 Nog. 08 3479 Nog. 08 5.352 Nog.	Nog. Nog. Nog.	WK 37 to Bosch	1	OK.		Tension roller incorrectly installed
8T38A03621 7LZ8D04576 4L18D04110			IGG000002768-004 W1H000000367-001 IGG000002768-003	4A77 4A24 275 4A57 4A45 4A75 4A75 4A53 4A48 4A52 4A31 4A56 4A51 4A56 4A51 4A56	X X		×		x	×	x x	FeP	01-0232 01-0046	12-0026	20.02.2008 17.11.2007 21.11.2007	- 15.07 - 08.02 - 19.02	2008 28.07.20 2008 22.07.20 2008 25.07.20	08 1.044 Nog. 08 n/a Nog. 08 4.961 Nog.	Nog. Nog. Nog.	Fitter + Iuel Particles in Nut Nitre Vehicle will not start WK 37 to Boach Vehicle will not start Engine will not start Vehicle will not start Fitter anylaris proof 20'06-1 Vehicle will not start Fitter anylaris proof 20'06-1 Vehicle will not start Follow-up enging dampe Vehicle will not start Vehicle will not start Vehicle will not start Vehicle will not start Vehicle will not start	1 1	under analysis under analysis		
4L88D04122 4L88D0537 8T58A03625	5 059 130 755 AB 059 130 755 AB 059 130 755 AB	611 3095199 611 3100810 611 3100782	IGE000001962-001 IGG000002768-007 IGG000002768-002	4A31 4A56 4A51	X X X		X X		x	X	X X X	FeP FeP FcP	01-0045 0	02-0303 02-0638	21.11.2007 12.02.2008 26.02.2008	15.01. 01.04. 07.04.	2008 03.07.20 2008 16.07.20 2008 16.07.20	08 20.395 Nog. 08 11.975 Nog. 08 6.566 Nog.	Nog. Nog. Nog.	Fuel analysis report 20'06-1 Vehicle will not start Follow-up engine damage (III	2	OK under analysis	ОК	
8T48A03961 8T48A03961 8T48A03150 4L78D06546	0 059 130 755 AB	611 3100777 611 3100816	IGG000002768-005	4A54	x		X X		X X X		X X	FeP FeP	01-0004 01-0075 01-0595		25.01.2008	- 09.01. - 22.05. - 01.03.	2006 10.07.20 2006 24.07.20 2008 22.07.20	08 14.633 Nog. 06 2.290 Nog. 08 7.774 Nog. 08 1.695 Nog. 08 4.154 Nog.	Nog. Nog. Nog.	Vehicle will not start Vehicle will not start Vehicle will not start	1	under analysis under analysis		
4LX8D0523 4L78D06566	56 059 130 755 AB 58 059 130 755 AB 52 059 130 755 AB 54 059 130 755 AB	611 3104944	IGG000002783-005	4A61 4A59 4A62			l x			x x	X X X	FeP FeP FeP FeP FeP FeP FeP FeP FeP FeP	01-1135	02-1041	19.04.2008 11.02.2008 14.04.2008	- 29.02 - 28.05	2008 07.07.20 2008 09.06.20 2008 11.07.20	08 4.154 Nog. 08 4.496 Nog.	Nog. Nog.	Mechanical fault Electrical fault with fuel test	1			
8K99A06334 8K9BA03273 8T9BA04143	6 059 130 755 AB 12 059 130 755 AB 18 059 130 755 AB	611 3106532	IGG000002804-001	4A63 4A14 235 4A22	x			X X	x		X X	FeP FeP FeP	01-0394	02-0745 02-0752	28.06.2008 03.03.2008 27.03.2008		out 29.07.20	08 12 Gün.	Gün	Engine will not start Vehicle stopped Glow plug system activated while traveling on	1	OK	ОК	Pump OK
8K98N02434 8T68A02211	8 059 130 755 AB 8 059 130 755 AB 95 059 130 755 AB 4 059 130 755 AB	611 3047167	IGG000002610-001	4825							x		01-0372	02-0570	05.04.2008 27.10.2007						1	under analysis OK		
7LZ8D05726 8T78A03071 8T58A03035			WIA000002035-001 IGG000002864-002 IGG000002864-003	4A49 4A47 4A71	X		×		x	×	x	FeP FeP FeP	01-0728		16.01.2008 03.01.2008 18.01.2008			and the second s	10,000	Indowway Vehicle will not start Engine will not start, cardown Dispatch 08.09 Vehicle will not start, but engine turning over	1	under analysis		Corrosion: warrenty rejected
200000000000000000000000000000000000000	55 059 130 755 AB 51 059 130 755 AB 51 059 130 755 AB	Section 1 December 2015	\$2000 TANKS \$2000 AL	4A69	x		×	×	×		×	1 4545.24	01-0008	02-0156	The state of the s	77.02.2008 20.02. 22.04.2008 09.05.	A 80/03 THE STATE OF	06 5.168 08 86 Nog.	III DOMEN	Dispatch 06.09 Engine tailed while driving and will not start. Mechanical healt		under analysis		With fuel test
8K18A0358	21 03L 130 755	507 3016558	IGG000002470-001	4VW93 259			T X	×		Non onsi onte	resp le c	FeP	01-0349		12.03.2008	17.04.	2008 05.05.20	08 1584 -		Glow litement lights up, vehicle stopped and will not restart				Not typical drive-train damage Cause of failure: tappet spring broken
5NZ8W0366 8K48N0062	73 03L 130 755	507 2974476	BSA000001258-001 IGE000001820-001	JhP 4VW86 232	X		X	×		emo	eed .	FeP FeP	O1-0800	03-152	22.01.2008 11.01.2008	- 26.03.	05.05.20	08 25 Nog.		Engine died white driving Non-responsive content removed	2			6,7% RME, not the cause of drivetrain damage
O Dio Control	48 03L 130 755 78 03L 130 755 35 03L 130 755	507 3031672 507 3051740 507 3070039		4VW95 4VW97 274 4VW99	X	\vdash	- X	X X				FeP FeP	01-0261	02-0328	15.03.2008	00.12.2008 08.02. 03.04.2008 04.04.	2008 24.04.20			Engine will not start. Electrical fault	2 2	OK		WK 29 to Bosch
8K88N0222	79 103L 130 755 L.	507 3118777		50000	x x		₩.	1 X					0	02-0341	05.02.2008	15.04.2008 16.04 — 05.04	2008 28.07.20 2008 02.06.20	08 20.422 08 21.921 Nog.		Dispatch 08.09. Pump sent to Bosch 15.09	Ė	OK		with filter (run dry)
Non-8758A03667 8K88N0113	0 059 130 755 AB 059 130 755 AB	611 A5 2,7L TD	not delivered		X X		X		X X		X X	FeP FeP				09.04.	0008 6/2/200	06 434 8 1.462	1					
resp 8K88N0113	15 059 130 755 AB 08 059 130 755 AB 059 130 755 AB	611 A4 2,7L TC	I not delivered I not delivered		X X X		X	x x x			X X X	FeP FeP FeP FeP				28.03. 07.05.	2008 4/24/200 2008 5/20/200 2008 6/10/200	08 2.000 08 850						
onsi 4LX8D0583	00 059 130 755 AB 08 059 130 755 AB 03 059 130 755 AB 05 059 130 755 AB	611 Q7 3.0L TE	not delivered		X X X		v			X X	x x x	FeP FeP				13.05	2008 5/20/200 2008 5/19/200 2008 6/18/200 2008	08 130						
Ve c 71.28004869	60 059 130 755 AB 059 130 755 AB 02 60 130 755 AB	611 VW Toutre 611 VW Toutre 611 VW Toutre	g not delivered g not delivered g not delivered		X X X		X X X			X X X	X X	FeP FeP				07.02. 16.05. 20.12.	2008 2008 2007	10.426 3.386 15.592				l		
onte 71.28004279 71.28007216 71.28004399 nt r 41.98004399	33 059 130 755 AB 16 059 130 755 AB 10 059 130 755 AB 10 059 130 755 AB 12 059 130 755 AB 13 61 130 755 AB 14 130 755 AB 15 059 130 755 AB 16 052 130 755 AB 17 059 130 755 AB 18 059 130 755 AB	611 VW Touare 611 VW Touare 611 Q7 3,0L TD	not delivered not delivered not delivered		X X X X X X X X X X X X X X		X X			X X	X X	FeP FeP FeP FeP FeP FeP FeP FeP FeP FeP	01-1108		15.01.2008	02.06. 04.01.	2008 2008 6/10/200	3.908 12.422 08			E			
emo 8108A04540	48 059 130 755 AB 9 059 130 755 AB	611 Q7 3,0L TE	I requested I not delivered I requested I Part + fuel requested	19	X X		X X		x	X	x x	FeP FeP FeP	01-0429	02-0303	07.07.2008 12.02.2008	30.05. 01.04.	4/25/200 2008 01.09.20 2008 17.07.20	200 08 08 3.324 08 11.975 Nog.	Nog		2			
ed 4LX8D05976 4LX8D05976 4L08D04635	50 059 130 755 AB 4 059 130 755 AB	611 Q7 3.0L TE 611 Q7 3.0L TE	7/30/2008 1		X					×	×				12.02.2000	01,04.	17.01.20	Trail mag.			.5			
4L18D04407 4L18D05841 4L28D04324	7 059 130 755 AB 6 059 130 755 AB 5 059 130 755 AB	611 Q7 3.0L TE 611 Q7 3.0L TE	1		X		X			X X	X X X											E .		
4L78D04322 4L48D05809	059 130 755 AB 059 130 755 AB 059 130 755 AB 059 130 755 AB 059 130 755 AB	611 Q7 3,0L TE 611 Q7 3,0L TE 611 Q7 3,0L TE	1		X X X		X X	×		X X	X X													
4L78D04165 4L58D05100 8K78A02272	059 130 755 AB 12 059 130 755 AB 20 059 130 755 AB	611 Q7 3,0L TE 611 Q7 3,0L TE 611 unknown	30.07.2008		X X X X X X		T Š	x		X	X	FeP	0	02-0310	02.02.2008	05.03.	2006 15,07,20	08 8,706						
8T28A03178 8T58A02633 8T28A01556	059 130 755 AB 050 130 755 AB 050 059 130 755 AB 05	611 A5 2,7L TC 611 A5 2,7L TC 611 A5 2,7L TC	I I failure		x x		i k		x x		X X X X X	FeP									1			5
8T28A01556 7LZ8D05176	6 059 130 755 AB	611	- Committee		1 1		x		x	x	x					7.1		16.471						
	7 059 130 755 AB	611 VW Tourse	not delivered		X X X X		X X			X X X	X X X	FoP FoP FeP				21.8 10.8 4.5	96 28 0							5
7LZ8D07700 7LZ8D07927		611 VW Touare 611 VW Touare	not delivered		X X X X		X X X			X X	X X	FeP FeP				6/20/ 16.07	8008	08 9.438 13.657 2.105						
7LZ9D00126 7LZ9D00148 7LZ8D0792 8K58A00203	12 059 130 755 AB 71 059 130 755 AB	611 VW Touard	g not delivered g not delivered		x x x		X	у	X X X X	X X X	X X X	FeP				29.07. 7/10: 16.07. 21.12.	8008	3.614 2.018			1			
8T48A02870 8T68A02842 8T48A03835	059 130 755 AB 09 059 130 755 AB 059 130 755 AB 059 130 755 AB	611 A5 2,7L TD	1 ?		X X X X X X X X X X X X X X X X X X X		X X		X X X		X X X	FeP FeP				21.12. 15.02. 31.01. 25.06.	2008	1,223 6,062 129						
8T28A02202 4L88D05263 4L98D05410	059 130 755 AB 059 130 755 AB 059 130 755 AB 0 059 130 755 AB 0 059 130 755 AB 0 059 130 755 AB	611 A5 2,7L TD 611 Q7 3,0L TD 611 Q7 3,0L TD	1 9		X X X		×		X	X X	X X X X X X X	FeP FeP	0	02-0784	13.02.2008	29.04. 15.05. 28.03.	2008 2008	129 12.800 1.131 18.691						
41.78004150	2 059 130 755 AB	611 VW Touare	not delivered		X X		×			X X	X X X	FeP FeP				31.12. 08.05. 11.12.	2007 08.08.20 2008 11.06.20 2007 29.07.20 2008 04.08.20	08 26.931 08 4.830 08 20.737						
7LZ8D06738 7LZ8D03873	059 130 755 AB		g Inot delivered		x x		X X			X X	X	EaD				26.12. 13.06.	2007 21.07.20 2008 05.08.20	08 27.137 08 7.914						
7LZ8D06738 7LZ8D03873 7LZ8D04900 7LZ8D04878 7LZ8D07698 7LZ8D06503	059 130 755 AB		not delivered		X											60.43		7.000						
7LZ8D04878			g not delivered g not delivered Part + fuel delivered on 16.09.08		X X		X			X X	X X	FeP FeP FeP	01-0370		28.02.2008	20.05. 20.03.	2008 06.08.20 2008 07.07.20 2008 15.09.20	08 6.550 08 8.006						

Only vehicle failures under testing and in the field

Model	Engine			volume Vehicles SOP - June 08	per mill.	Factor above average in worldwide comparison	Factor above average in comparison,	Remark
Audi Q7	3.01	worldwide	31	19.344	1,6			
			0	5.685				
			5	187	26,7		#DIV/0!	
			12	317	37,9		#DIV/0!	
			3	477	6,3	4	#DIV/0!	
			2	?				1 veh. 2 failures
			2	?				
			2	76			#DIV/0!	N.
			2	2.612	0,8			
		0.41.1104	1			1.50	WD111/6	W40.
		Q-AL USA	2	8	250,0		#DIV/0!	W19 tension roller instead of W24
Audi A4/A5	2.01	worldwide	7	87.660				
			5	24.813				
			1	1.724	0,6		3	
			1	1.225			4	
	2.71	worldwide	34	18.516				
			7	5.899				
			15	243			52	
			7	161	43,5		37	
			4	1.985	2,0			-1
	1		. 1	?				
	3.01		2	?				
	Ü.		. 1					
Audi A3	2.01		1					Poor quality fuel!!!
VW Phaeton	3.01		1	2.807	0,4			Late damage, poor ventilation in 06/07?
VW Touareg	3.01	Free markets	26	13.266				
	j i		1	4.780	0,2			
			6	141	42,6		203	Suspicion of proportion of biodiesel in Brazil
			7	1.112		3	30	
			5	2.437	2,1	1	10	
			5	789	6,3	3	30	
			1	?		7		
		Q-AL USA	1					
VW Tiguan	2.01		1	18.752	0,1			
VW Jetta	2.01	Testing in USA	1					
AudiA4/A5	unknown		3					
ALL CASE I	unknown		1					
Grand total			108					
- Law Law Law Control Law			_			Z-STE		

103

Qty.	Deliveries	Failure rate (per mill.)
29	2295	12,6
27	478	56,5
3	477	6,3
16		Positi
15	62736	0,2

Field total

Trial experience (CR findings; not relevant for approval)

- 6 x 500h with GDK 650µm positive*
- *(1 failure after 490h due to piston seizure; cause: lack of C coating on piston)
- 2 x 100h with GDK 650µm positive
- 1 x 750h@2050 bar with kerosene (jet A1 kerosene F35) positive
- 1 x 500h@2050 bar with kerosene (jet A1 kerosene F35) positive
- 3 x WCF (water contaminated fuel) without AWP -> HP piston seizure
- 2 x WCF (water contaminated fuel) with CP4 with AWP -> drivetrain damage*
- *Not in actual CR after pump breakdown Parts are highly corroded. Note: WCF results are not applicable to the series (1% water content)

Diesel Systems

Confidential | Non-responsive content removed | 07/15/2008 Non-res

Note from Audi:

The CP4 was tested positively and sufficiently in continuous running with EN590-compliant fuels. Trials with "poorer fuel qualities of all kinds" were carried out in a much too narrow scope. In addition, these trials are largely not approval-relevant. The <u>CP4 is not sufficiently robust</u>, even with regard to filling and venting in customer service, engine test and on the vehicle assembly line.

From: Non-responsive content removed

	To:
	CC:
8	
D	ate: 7/28/2010, 2:03:16 PM
	ject: Re: First start times in
Attachme	nts: WG Erststartzeiten aller CR aus .msg
Non-responsive content	
Hello	
D	
Regarding your state	December 1988 for the second of the second o
Non-responsive content remov	tried a while ago, unsuccessfully, to get these start times from FAT
They certainly have	the data
	back then was Non-responsive content remove
The contact percent	back them was
Mr Non-responsive content remo	
A STATE OF THE PARTY OF THE PAR	the proposal as to how to proceed?
Dia you roopona to	the proposal as to new to proceed.
>	
- CA - CA	
>Von: Non-responsive	ve content removed
	The state of the s
>Sent: Friday, M	arch 26, 2010, 10:58 AM
>Sent: Friday, M	The state of the s
>Sent: Friday, M >To: Non-response	arch 26, 2010, 10:58 AM
>Sent: Friday, M >To: Non-response >Cc:	arch 26, 2010, 10:58 AM onsive content removed
>Sent: Friday, M >To: Non-response	arch 26, 2010, 10:58 AM onsive content removed
>Sent: Friday, M >To: Non-responsible Subject: Re: First >	arch 26, 2010, 10:58 AM onsive content removed
>Sent: Friday, M >To: Non-response >Cc: Subject: Re: First	arch 26, 2010, 10:58 AM onsive content removed
>Sent: Friday, M >To: Non-responsible >Cc: Re: First > Hello Mr. ,	arch 26, 2010, 10:58 AM onsive content removed start times in
>Sent: Friday, M >To: Non-responsible Subject: Re: First > Hello Mr. Thank you for taking the street	arch 26, 2010, 10:58 AM onsive content removed start times in ng care of things so quickly.
>Sent: Friday, M >To: Non-responsible Subject: Re: First > Hello Mr.	arch 26, 2010, 10:58 AM onsive content removed start times in ng care of things so quickly. tion Confidential
>Sent: Friday, M >To: >Cc: >Subject: Re: First > >Hello Mr. > >Thank you for takir > Sec: >The average first s	arch 26, 2010, 10:58 AM onsive content removed start times in ng care of things so quickly. tion Confidential tart time of 21 sec. is very critical. This could also include
>Sent: Friday, M >To: >Cc: >Subject: Re: First > >Hello Mr. > >Thank you for takir > >The average first so the vehicles that have to	arch 26, 2010, 10:58 AM onsive content removed start times in ng care of things so quickly. tion Confidential tart time of 21 sec. is very critical. This could also include o start even longer. In this case, preliminary damage
>Sent: Friday, M >To: >Cc: >Subject: Re: First > >Hello Mr. > >Thank you for takir > >The average first s vehicles that have to to the high-pressure	arch 26, 2010, 10:58 AM onsive content removed start times in ng care of things so quickly. tion Confidential tart time of 21 sec. is very critical. This could also include o start even longer. In this case, preliminary damage of fuel pumps cannot be ruled out.
>Sent: Friday, M >To: >Cc: >Subject: Re: First > >Hello Mr. > >Thank you for takir > >The average first s vehicles that have to to the high-pressure >Reasoning: If the v	arch 26, 2010, 10:58 AM onsive content removed start times in ng care of things so quickly. tion Confidential tart time of 21 sec. is very critical. This could also include o start even longer. In this case, preliminary damage
>Sent: Friday, M >To: Non-responsive Subject: Re: First > >Hello Mr. , > Thank you for takin > Sector Secto	arch 26, 2010, 10:58 AM consive content removed start times in ag care of things so quickly. tion Confidential tart time of 21 sec. is very critical. This could also include start even longer. In this case, preliminary damage fuel pumps cannot be ruled out. renting is insufficient, there is nearly no fuel present in the pumps. If with starter rotational speeds in this case, there is a danger that the rollers in the and suffer damage.
>Sent: Friday, M >To: Non-responsive Subject: Re: First > Subject: Re: First > Hello Mr. , > Thank you for takin > Section >The average first some such to the high-pressure pumps will not turn a section section.	start times in arch 26, 2010, 10:58 AM consive content removed start times in arg care of things so quickly. tion Confidential tart time of 21 sec. is very critical. This could also include start even longer. In this case, preliminary damage fuel pumps cannot be ruled out. renting is insufficient, there is nearly no fuel present in the pumps. If with starter rotational speeds in this case, there is a danger that the rollers in the and suffer damage. Confidential
>Sent: Friday, M >To: Non-responsive Subject: Re: First > Subject: Re: First > Hello Mr. , > Thank you for takin > Section >The average first someticles that have to the high-pressure >Reasoning: If the word to turn a section takes place pumps will not turn a section.	arch 26, 2010, 10:58 AM consive content removed start times in ag care of things so quickly. tion Confidential tart time of 21 sec. is very critical. This could also include start even longer. In this case, preliminary damage fuel pumps cannot be ruled out. renting is insufficient, there is nearly no fuel present in the pumps. If with starter rotational speeds in this case, there is a danger that the rollers in the and suffer damage.
>Sent: Friday, M >To: Non-responsive Subject: Re: First > Subject: Re: First > Hello Mr. , > Thank you for takin > Section >The average first some succession takes place pumps will not turn a section some succession some succession	estart times in the start times in the start times in the start times in the start time of 21 sec. is very critical. This could also include the start time of 21 sec. is very critical. This could also include to start even longer. In this case, preliminary damage fuel pumps cannot be ruled out. Therefore is insufficient, there is nearly no fuel present in the pumps. If with starter rotational speeds in this case, there is a danger that the rollers in the and suffer damage. To Confidential Tare 6 - 12 sec. (see attachment).
>Sent: Friday, M >To: Non-responsive Subject: Re: First > Subject: Re: First > Hello Mr. , > Thank you for takin > Section >The average first some vehicles that have to the high-pressure pumps will not turn a section > The start times in > Procedure for how	estart times in the start times in the start times in the start times in the start time of 21 sec. is very critical. This could also include the start time of 21 sec. is very critical. This could also include to start even longer. In this case, preliminary damage fuel pumps cannot be ruled out. Therefore is insufficient, there is nearly no fuel present in the pumps. If with starter rotational speeds in this case, there is a danger that the rollers in the and suffer damage. To Confidential Tare 6 - 12 sec. (see attachment).

>* Please conduct a process analysis soon and compare with I suspect that the

>* Please d the above distribution list; also for vehicles in the field, start times and rate which ones are most endangered.

```
EA11003EN-00114[1]
    vehicles in
                     are not vented sufficiently before the first start and therefore have the
    high start times. We urgently have to match this with the other plants.
    >Please provide information as to your plans for how to proceed.
    >If you are not the person responsible, please forward appropriately.
    >Best regards
    Non-responsive content remove
   Non-responsive content removed
    >www.audi.com
    >
    >Sitz/Domicile: Ingolstadt
    >Court of Registry/Registergericht: Amtsgericht Ingolstadt
    >Commercial Register No./HRB Nr.: 1
    >Chairman of the Supervisory Board/Vorsitzender des Aufsichtsrats: Martin Winterkorn
    >Vorstand/Board of Management: Rupert Stadler (Vorsitzender/Chairman), Ulf Berkenhagen, Michael
    Dick, Frank Dreves, Peter Schwarzenbauer, Axel Strotbek, Werner Widuckel
    >Important note: The above information is automatically added to this e-mail.
    This addition does not constitute a representation that the content of this e-mail is legally relevant
    and/or is intended to be legally binding upon Audi AG.
    >Wichtiger Hinweis: Die vorgenannten Angaben werden jeder E-Mail automatisch hinzugefügt und
    lassen keine Rückschlüsse auf den Rechtscharakter der E-Mail zu.
    >
    >
    >Von: Non-responsive content removed
    >Sent: Friday, March 26, 2010, 9:30 AM
   Non-responsive content removed
    >Subject: Re: First start times in
    Hello colleagues,
    >Here is the requested information:
          Section Confidential
    First start time average: 21s
    Filling quantity :> 14 l
    >Is this information sufficient? Is the data okay or are their problems? What are the times and filling
    quantity in
```

EA11003EN-00114[2]

EA11003EN-00114[3] >With best regards / Mit freundlichen Gruessen Non-responsive content removed >AUDI AG >85045 Ingolstadt Non-responsive content removed >www.audi.com >Sitz/Domicile: Ingolstadt >Court of Registry/Registergericht: Amtsgericht Ingolstadt >Commercial Register No./HRB Nr.: 1 >Chairman of the Supervisory Board/Vorsitzender des Aufsichtsrats: Martin Winterkorn >Vorstand/Board of Management: Rupert Stadler (Vorsitzender/Chairman), Ulf Berkenhagen, Michael Dick, Frank Dreves, Peter Schwarzenbauer, Axel Strotbek, Werner Widuckel >Important note: The above information is automatically added to this e-mail. This addition does not constitute a representation that the content of this e-mail is legally relevant and/or is intended to be legally binding upon Audi AG. >Wichtiger Hinweis: Die vorgenannten Angaben werden jeder E-Mail automatisch hinzugefügt und lassen keine Rückschlüsse auf den Rechtscharakter der E-Mail zu. > >Von: Non-responsive content removed >Sent: Wednesday, March 24, 2010, 11:21 AM >To: Non-responsive content removed >Cc: >Subject: First start times in > >Hello Mr. gave me a tip that you might be able to help me with questions involving production >We have V6 TDIs from (production that have damage to the high-pressure fuel pumps, some after only very short running times (minimum 235 km). >It is possible that the pumps suffered preliminary damage during commissioning of the vehicles if the fuel system is not vented sufficiently during the first start. This is evident in the long first start times. >Specific questions: >* What are the first start times for the V6 TDIs? >* Which fuel quantities are filled for the V6 TDIs at the plant?

EA11003EN-00114[4] > > >Best regards Non-responsive content remo Non-responsive content removed >AUDI AG Non-responsive content removed >www.audi.com

>Sitz/Domicile: Ingolstadt

- >Court of Registry/Registergericht: Amtsgericht Ingolstadt
- >Commercial Register No./HRB Nr.: 1
- >Chairman of the Supervisory Board/Vorsitzender des Aufsichtsrats: Martin Winterkorn
- >Vorstand/Board of Management: Rupert Stadler (Vorsitzender/Chairman), Ulf Berkenhagen, Michael Dick, Frank Dreves, Peter Schwarzenbauer, Axel Strotbek, Werner Widuckel

>Important note: The above information is automatically added to this e-mail.

This addition does not constitute a representation that the content of this e-mail is legally relevant and/or is intended to be legally binding upon Audi AG.

>Wichtiger Hinweis: Die vorgenannten Angaben werden jeder E-Mail automatisch hinzugefügt und lassen keine Rückschlüsse auf den Rechtscharakter der E-Mail zu.

CP4.1

CP4.1

CP4.1

CP4.1

CP4.1

CP4.1

CP4.2

CP4.2

B8

B8

B8

B8

B8

B8

B8

B8 convertible

07-1-4276

07-1-4278

07-1-4279

07-1-4281

07-1-4282

07-1-4285

07-1-4284

R4 TDI, 2.0L-EU5

V6 TDI, 2.7L-EU5

V6 TDI, 3.0L-EU5

B8 engine initial start times - Diesel

06.02.2009

06.02.2009

06.02.2009

06.02.2009

06.02.2009

06.02.2009

06.02.2009

6

8

7

8

8

A14-OG-IBN-Band

A14-OG-IBN-Band

A14-OG-IBN-Band

A14-OG-IBN-Band

A14-OG-IBN-Band

A14-OG-IBN-Band

A14-OG-IBN-Band

> 85 sec

>135 sec

Initial start times, January 15, 2009

initial start times, January 15, 2009											
Veh. class	VIN	Engine type	Vehicle type/data version	Start time [s]	Inspection date	Inspector	Prefilling	Location			
B8	03-5-4151	R4 TDI, 2.0L-EU5	03L 906 022 KA 4235	9	15.01.2009	Non-resp	> 85 sec	A14-OG-IBN-Band			
B8	03-5-4157	R4 TDI, 2.0L-EU5	03L 906 022 MJ 4227	11			> 85 sec	A14-OG-IBN-Band			
B8	03-5-4164	R4 TDI, 2.0L-EU5	03L 906 022 MJ 4227	11	45 04 0000		> 85 sec	A14-OG-IBN-Band			
B8	03-5-4160	R4 TDI, 2.0L-EU5	03L 906 022 MJ 4227	12	15 04 0000		> 85 sec	A14-OG-IBN-Band			
B8	03-5-4167	R4 TDI, 2.0L-EU5	03L 906 022 MJ 4227	12	15.01.2009	cilioved	> 85 sec	A14-OG-IBN-Band			
B8	03-5-4155	R4 TDI, 2.0L-EU5	03L 906 022 MG 4224	12	15.01.2009		> 85 sec	A14-OG-IBN-Band			
B8	03-5-4158	R4 TDI, 2.0L-EU5	03L 906 022 MR 4230	14	15.01.2009		> 85 sec	A14-OG-IBN-Band			
B8	03-5-4162	R4 TDI, 2.0L-EU5	03L 906 022 MP 4233	14	15.01.2009		> 85 sec	A14-OG-IBN-Band			
B8	03-5-4171	R4 TDI, 2.0L-EU5	03L 906 022 MJ 4227	14	15.01.2009		> 85 sec	A14-OG-IBN-Band			
B8	03-5-4178	R4 TDI, 2.0L-EU5	03L 906 022 MJ 4227	14	15.01.2009		> 85 sec	A14-OG-IBN-Band			
B8	03-5-4174	R4 TDI, 2.0L-EU5	03L 906 022 MG 4224	14	15.01.2009		> 85 sec	A14-OG-IBN-Band			
B8	03-5-4176	R4 TDI, 2.0L-EU5	03L 906 022 MG 4224	14	15.01.2009		> 85 sec	A14-OG-IBN-Band			
B8	03-5-4153	V6 TDI, 2.7L-EU5	8K1 907 401 B 0003	9	15.01.2009		>135 sec	A14-OG-IBN-Band			
B8 convertib	48-3-4002	V6 TDI, 3.0L-EU5	8R0 907 401 C 0001	11	15.01.2009		>135 sec	A14-OG-IBN-Band			
B8 convertib	50-2-4002	V6 TDI, 3.0L-EU5	8R0 907 401 C 0001	11	15.01.2009		>135 sec	A14-OG-IBN-Band			
B8 convertib	50-2-4004	V6 TDI, 3.0L-EU5	8K0 907 401 C 0001	12	15.01.2009		>135 sec	A14-OG-IBN-Band			
B8 convertib	50-5-4003	V6 TDI, 3.0L-EU5	8R0 907 401 C 0001	12	15.01.2009		>135 sec	A14-OG-IBN-Band			
L					4.4.5						
	The state of the s				Inspection date			Location			
2		R4 TDI, 2.0L-EU5	03L 906 022 MG 4375				> 85 sec				
B8				8	06.02.2009			A14-OG-IBN-Band			
	07-1-4257	R4 TDI, 2.0L-EU5	03L 906 022 MG 4375	8	06.02.2009 06.02.2009		> 85 sec	A14-OG-IBN-Band			
B8	07-1-4258	R4 TDI, 2.0L-EU5		8	06.02.2009 06.02.2009		> 85 sec > 85 sec	A14-OG-IBN-Band A14-OG-IBN-Band			
B8 B8	07-1-4258 07-1-4261	R4 TDI, 2.0L-EU5 R4 TDI, 2.0L-EU5	03L 906 022 MG 4375	8	06.02.2009		> 85 sec > 85 sec > 85 sec	A14-OG-IBN-Band A14-OG-IBN-Band A14-OG-IBN-Band			
B8 B8 B8	07-1-4258	R4 TDI, 2.0L-EU5 R4 TDI, 2.0L-EU5 R4 TDI, 2.0L-EU5	03L 906 022 MG 4375 03L 906 022 MK 4379	8	06.02.2009 06.02.2009		> 85 sec > 85 sec	A14-OG-IBN-Band A14-OG-IBN-Band			
B8 B8 B8	07-1-4258 07-1-4261 07-1-4262 07-1-4264	R4 TDI, 2.0L-EU5 R4 TDI, 2.0L-EU5 R4 TDI, 2.0L-EU5 R4 TDI, 2.0L-EU5	03L 906 022 MG 4375 03L 906 022 MK 4379 03L 906 022 MJ 4378	8 8 9 7 7	06.02.2009 06.02.2009 06.02.2009		> 85 sec > 85 sec > 85 sec > 85 sec > 85 sec	A14-OG-IBN-Band A14-OG-IBN-Band A14-OG-IBN-Band A14-OG-IBN-Band A14-OG-IBN-Band			
B8 B8 B8 B8 B8	07-1-4258 07-1-4261 07-1-4262 07-1-4264 07-1-4266	R4 TDI, 2.0L-EU5 R4 TDI, 2.0L-EU5 R4 TDI, 2.0L-EU5 R4 TDI, 2.0L-EU5 R4 TDI, 2.0L-EU5	03L 906 022 MG 4375 03L 906 022 MK 4379 03L 906 022 MJ 4378 03L 906 022 NG 4295	8 8 9 7	06.02.2009 06.02.2009 06.02.2009 06.02.2009		> 85 sec > 85 sec > 85 sec > 85 sec > 85 sec > 85 sec > 85 sec	A14-OG-IBN-Band A14-OG-IBN-Band A14-OG-IBN-Band A14-OG-IBN-Band A14-OG-IBN-Band A14-OG-IBN-Band			
B8 B8 B8 B8 B8	07-1-4258 07-1-4261 07-1-4262 07-1-4264	R4 TDI, 2.0L-EU5 R4 TDI, 2.0L-EU5 R4 TDI, 2.0L-EU5 R4 TDI, 2.0L-EU5 R4 TDI, 2.0L-EU5 R4 TDI, 2.0L-EU5	03L 906 022 MG 4375 03L 906 022 MK 4379 03L 906 022 MJ 4378 03L 906 022 NG 4295 03L 906 022 MK 4379	8 8 9 7 7	06.02.2009 06.02.2009 06.02.2009 06.02.2009 06.02.2009		> 85 sec > 85 sec > 85 sec > 85 sec > 85 sec	A14-OG-IBN-Band A14-OG-IBN-Band A14-OG-IBN-Band A14-OG-IBN-Band A14-OG-IBN-Band A14-OG-IBN-Band A14-OG-IBN-Band			
B8 B8 B8 B8 B8	07-1-4258 07-1-4261 07-1-4262 07-1-4264 07-1-4266	R4 TDI, 2.0L-EU5 R4 TDI, 2.0L-EU5 R4 TDI, 2.0L-EU5 R4 TDI, 2.0L-EU5 R4 TDI, 2.0L-EU5	03L 906 022 MG 4375 03L 906 022 MK 4379 03L 906 022 MJ 4378 03L 906 022 NG 4295 03L 906 022 MK 4379 03L 906 022 MK 4379	8 8 9 7 7 7	06.02.2009 06.02.2009 06.02.2009 06.02.2009 06.02.2009 06.02.2009		> 85 sec > 85 sec > 85 sec > 85 sec > 85 sec > 85 sec > 85 sec	A14-OG-IBN-Band A14-OG-IBN-Band A14-OG-IBN-Band A14-OG-IBN-Band A14-OG-IBN-Band A14-OG-IBN-Band			
	B8 B	B8 03-5-4151 B8 03-5-4157 B8 03-5-4164 B8 03-5-4160 B8 03-5-4167 B8 03-5-4155 B8 03-5-4158 B8 03-5-4158 B8 03-5-4162 B8 03-5-4171 B8 03-5-4178 B8 03-5-4176 B8 03-5-4176 B8 03-5-4153 B8 convertit 48-3-4002 B8 convertit 50-2-4004 B8 convertit 50-2-4004 B8 convertit 50-5-4003	B8	B8	B8	B8	B8	B8			

03L 906 022 MK 4379

03L 906 022 MJ 4378

03L 906 022 MM 4377

8K1 907 401 B 0003

C6PA engine initial start times - Diesel

Initial start times, January 15, 2009

HPP type	Veh. class	Veh. name	Engine type	Vehicle type/data version	Start time [s]	Inspection date	Inspector	Prefilling	Location
CP4.1	C6	03-5-2342	R4 TDI, 2.0L-EU5	03L 906 022 FH 3812	7	15.01.2009	Non-respo	> 120 sec	A14-OG-IBN-Band
CP4.1	C6	03-5-2326	R4 TDI, 2.0L-EU5	03L 906 022 SB 3787	7		nsive con	> 120 sec	A14-OG-IBN-Band
CP4.1	C6	03-5-2323	R4 TDI, 2.0L-EU5	03L 906 022 FH 3812	8	15.01.2009	tent remo	> 120 sec	A14-OG-IBN-Band
CP4.1	C6	03-5-2297	R4 TDI, 2.0L-EU5	03L 906 022 FL 3810	9	15.01.2009	ved	> 120 sec	A14-OG-IBN-Band
CP4.1	C6	03-5-2321	R4 TDI, 2.0L-EU5	03L 906 022 FH 3812	9	15.01.2009		> 120 sec	A14-OG-IBN-Band
CP4.1	C6	03-5-2348	R4 TDI, 2.0L-EU5	03L 906 022 FG 3811	9	15.01.2009		> 120 sec	A14-OG-IBN-Band
CP4.1	C6	03-5-2306	R4 TDI, 2.0L-EU5	03L 906 022 SB 3787	10	15.01.2009		> 120 sec	A14-OG-IBN-Band
CP4.1	C6	03-5-2312	R4 TDI, 2.0L-EU5	03L 906 022 FG 3811	10	15.01.2009		> 120 sec	A14-OG-IBN-Band
CP4.1	C6	03-5-2317	R4 TDI, 2.0L-EU5	03L 906 022 SB 3787	10	15.01.2009		> 120 sec	A14-OG-IBN-Band
CP4.1	C6	03-5-2325	R4 TDI, 2.0L-EU5	03L 906 022 FG 3811	10	15.01.2009		> 120 sec	A14-OG-IBN-Band
CP4.1	C6	03-5-2352	R4 TDI, 2.0L-EU5	03L 906 022 SB 3787	10	15.01.2009		> 120 sec	A14-OG-IBN-Band
CP4.1	C6	03-5-2339	R4 TDI, 2.0L-EU5	03L 906 022 FH 3812	11	15.01.2009		> 120 sec	A14-OG-IBN-Band
CP4.1	C6	03-5-2330	R4 TDI, 2.0L-EU5	03L 906 022 SB 3787	11	15.01.2009		> 120 sec	A14-OG-IBN-Band
CP4.1	C6	03-5-2360	R4 TDI, 2.0L-EU5	03L 906 022 FL 3810	11	15.01.2009		> 120 sec	A14-OG-IBN-Band
CP4.1	C6	03-5-2300	R4 TDI, 2.0L-EU5	03L 906 022 SB 3787	12	15.01.2009		> 120 sec	A14-OG-IBN-Band
CP4.1	C6	03-5-2206	R4 TDI, 2.0L-EU5	03L 906 022 SB 3787	12	15.01.2009		> 120 sec	A14-OG-IBN-Band
CP4.2	C6	03-5-2305	V6 TDI, 2.7L-EU5	4F7 910 401 004	7	15.01.2009		> 240 sec	A14-OG-IBN-Band
CP4.2	C6	03-5-2318	V6 TDI, 2.7L-EU5	4F7 910 401 004	7	15.01.2009		> 240 sec	A14-OG-IBN-Band
CP4.2	C6 Allroad	03-5-2295	V6 TDI, 2.7L-EU5	4F7 910 401 F 006	8	15.01.2009		> 240 sec	A14-OG-IBN-Band
CP4.2	C6	03-5-2335	V6 TDI, 2.7L-EU5	4F7 910 401 004	8	15.01.2009		> 240 sec	A14-OG-IBN-Band
CP4.2	C6 Allroad	03-5-2398	V6 TDI, 2.7L-EU5	4F7 910 401 F 006	8	15.01.2009		> 240 sec	A14-OG-IBN-Band
CP4.2	C6	03-5-2302	V6 TDI, 2.7L-EU5	4F7 910 401 F 006	10	15.01.2009		> 240 sec	A14-OG-IBN-Band
CP4.2	C6	03-5-2316	V6 TDI, 2.7L-EU5	4F7 910 401 004	11	15.01.2009		> 240 sec	A14-OG-IBN-Band
CP4.2	C6	03-5-2327	V6 TDI, 2.7L-EU5	4F7 910 401 004	11	15.01.2009		> 240 sec	A14-OG-IBN-Band
CP4.2	C6	03-5-2279	V6 TDI, 2.7L-EU5	4F7 910 401 004	11	15.01.2009		> 240 sec	A14-OG-IBN-Band
CP4.2	C6 Allroad	03-5-2286	V6 TDI, 3.0L-EU5	4F9 910 401 E 007	7	15.01.2009		> 240 sec	A14-OG-IBN-Band
CP4.2	C6	03-5-2291	V6 TDI, 3.0L-EU5	4F9 910 401 Q 005	8	15.01.2009		> 240 sec	A14-OG-IBN-Band
CP4.2	C6	03-5-2367	V6 TDI, 3.0L-EU5	4F2 910 115 K 002	8	15.01.2009		> 240 sec	A14-OG-IBN-Band
CP4.2	C6	03-5-2099	V6 TDI, 3.0L-EU5	4F9 910 401 E 007	8	15.01.2009		> 240 sec	A14-OG-IBN-Band
CP4.2	C6	03-5-2338	V6 TDI, 3.0L-EU5	4F9 910 401 E 007	9	15.01.2009		> 240 sec	A14-OG-IBN-Band
CP4.2	C6	03-5-2329	V6 TDI, 3.0L-EU5	4F9 910 401 E 007	10	15.01.2009		> 240 sec	A14-OG-IBN-Band
CP4.2	C6	03-5-2336	V6 TDI, 3.0L-EU5	4F9 910 401 E 007	10	15.01.2009		> 240 sec	A14-OG-IBN-Band
CP4.2	C6	03-5-2319	V6 TDI, 3.0L-EU5	4F9 910 401 E 007	11	15.01.2009		> 240 sec	A14-OG-IBN-Band

C6PA engine initial start times - Diesel

	Accounts to the control of the contr			5	·				
	Veh. class	Veh. name	Engine type	Vehicle type/data version			spector	Prefilling	Location
CP4.1	C6	07-2-2253	R4 TDI, 2.0L-EU5	03L 906 022 FL 3810	6	06.02.2009 No	on-respo	> 120 sec	A14-OG-IBN-Band
CP4.1	C6	07-2-2256	R4 TDI, 2.0L-EU5	03L 906 022 FG 4397	8	06.02.2009 ns	ive con	> 120 sec	A14-OG-IBN-Band
CP4.1	C6	07-2-2258	R4 TDI, 2.0L-EU5	03L 906 022 FL 3810	6	06.02.2009 ter	nt remo	> 120 sec	A14-OG-IBN-Band
CP4.1	C6	07-2-2260	R4 TDI, 2.0L-EU5	03L 906 022 FH 3812	8	06.02.2009 Ve	d	> 120 sec	A14-OG-IBN-Band
CP4.1	C6	07-2-2267	R4 TDI, 2.0L-EU5	03L 906 022 SB 3787	7	06.02.2009		> 120 sec	A14-OG-IBN-Band
CP4.1	C6	07-2-2274	R4 TDI, 2.0L-EU5	03L 906 022 FG 4397	9	06.02.2009		> 120 sec	A14-OG-IBN-Band
CP4.1	C6	07-2-2275	R4 TDI, 2.0L-EU5	03L 906 022 FG 4397	6	06.02.2009		> 120 sec	A14-OG-IBN-Band
CP4.1	C6	07-2-2279	R4 TDI, 2.0L-EU5	03L 906 022 FG 4397	6	06.02.2009		> 120 sec	A14-OG-IBN-Band
CP4.1	C6	07-2-2282	R4 TDI, 2.0L-EU5	03L 906 022 SB 3787	6	06.02.2009		> 120 sec	A14-OG-IBN-Band
CP4.1	C6	07-2-2186	R4 TDI, 2.0L-EU5	03L 906 022 FL 3810	7	06.02.2009		> 120 sec	A14-OG-IBN-Band
CP4.1	C6	07-2-2288	R4 TDI, 2.0L-EU5	03L 906 022 SB 3787	6	06.02.2009		> 120 sec	A14-OG-IBN-Band
CP4.1	C6	07-2-2301	R4 TDI, 2.0L-EU5	03L 906 022 FG 4397	6	06.02.2009		> 120 sec	A14-OG-IBN-Band
CP4.1	C6	07-2-2304	R4 TDI, 2.0L-EU5	03L 906 022 FH 3812	6	06.02.2009		> 120 sec	A14-OG-IBN-Band
CP4.2	C6	07-2-2249	V6 TDI, 2.7L-EU5	4F7 910 401 004	8	06.02.2009		> 240 sec	A14-OG-IBN-Band
CP4.2	C6	07-2-2101	V6 TDI, 2.7L-EU5	4F7 910 401 004	10	06.02.2009		> 240 sec	A14-OG-IBN-Band
CP4.2	C6	07-2-2252	V6 TDI, 2.7L-EU5	4F7 910 401 F 006	7	06.02.2009		> 240 sec	A14-OG-IBN-Band
CP4.2	C6	07-2-2259	V6 TDI, 2.7L-EU5	4F7 910 401 F 006	11	06.02.2009		> 240 sec	A14-OG-IBN-Band
CP4.2	C6	07-2-2265	V6 TDI, 2.7L-EU5	4F7 910 401 004	8	06.02.2009		> 240 sec	A14-OG-IBN-Band
CP4.2	C6	07-2-2269	V6 TDI, 2.7L-EU5	4F7 910 401 004	8	06.02.2009		> 240 sec	A14-OG-IBN-Band
CP4.2	C6	07-2-2271	V6 TDI, 2.7L-EU5	4F7 910 401 004	6	06.02.2009		> 240 sec	A14-OG-IBN-Band
CP4.2	C6	07-2-2277	V6 TDI, 2.7L-EU5	4F7 910 401 004	7	06.02.2009		> 240 sec	A14-OG-IBN-Band
CP4.2	C6	07-2-2295	V6 TDI, 2.7L-EU5	4F7 910 401 004	8	06.02.2009		> 240 sec	A14-OG-IBN-Band
CP4.2	C6	07-2-2284	V6 TDI, 2.7L-EU5	4F7 910 401 004	9	06.02.2009		> 240 sec	A14-OG-IBN-Band
CP4.2	C6	07-2-2303	V6 TDI, 2.7L-EU5	4F7 910 401 004	9	06.02.2009		> 240 sec	A14-OG-IBN-Band
CP4.2	C6	07-2-2291	V6 TDI, 2.7L-EU5	4F7 910 401 004	7	06.02.2009		> 240 sec	A14-OG-IBN-Band
CP4.2	C6	07-2-2286	V6 TDI, 2.7L-EU5	4F7 910 401 004	7	06.02.2009		> 240 sec	A14-OG-IBN-Band
CP4.2	C6	07-2-2247	V6 TDI, 3.0L-EU5	4F9 910 401 Q 005	8	06.02.2009		> 240 sec	A14-OG-IBN-Band
CP4.2	C6	07-2-2257	V6 TDI, 3.0L-EU5	4F9 910 401 E 007	7	06.02.2009		> 240 sec	A14-OG-IBN-Band
CP4.2	C6	06-4-2174	V6 TDI, 3.0L-EU5	4F9 910 401 E 007	10	06.02.2009		> 240 sec	A14-OG-IBN-Band
CP4.2	C6	07-2-2263	V6 TDI, 3.0L-EU5	4F9 910 401 Q 005	10	06.02.2009		> 240 sec	A14-OG-IBN-Band
CP4.2	C6	07-2-2264	V6 TDI, 3.0L-EU5	4F9 910 401 E 007	10	06.02.2009		> 240 sec	A14-OG-IBN-Band
CP4.2	C6	07-2-2268	V6 TDI, 3.0L-EU5	4F9 910 401 E 007	8	06.02.2009		> 240 sec	A14-OG-IBN-Band
CP4.2	C6	07-2-2276	V6 TDI, 3.0L-EU5	4F9 910 401 E 007	7	06.02.2009		> 240 sec	A14-OG-IBN-Band
CP4.2	C6	07-2-2278	V6 TDI, 3.0L-EU5	4F9 910 401 E 007	9	06.02.2009		> 240 sec	A14-OG-IBN-Band
CP4.2	C6	07-2-2281	V6 TDI, 3.0L-EU5	4F9 910 401 E 007	8	06.02.2009		> 240 sec	A14-OG-IBN-Band
CP4.2	C6	07-2-2283	V6 TDI, 3.0L-EU5	4F9 910 401 E 007	8	06.02.2009		> 240 sec	A14-OG-IBN-Band
CP4.2	C6	07-2-2287	V6 TDI, 3.0L-EU5	4F9 910 401 Q 005	10	06.02.2009		> 240 sec	A14-OG-IBN-Band

ENTIRE PAGE CONFIDENTIAL

EA11003EN-00116[3]

C6PA engine initial start times - Diesel

CP4.2	C6	07-2-2141	V6 TDI, 3.0L-EU5	4F9 910 401 E 007	9			> 240 sec	A14-OG-IBN-Band
CP4.2	C6	07-2-2300	V6 TDI, 3.0L-EU5	4F9 910 401 F 006	6	06.02.2009	e content rem oved	> 240 sec	A14-OG-IBN-Band
CP4.2	C6	07-2-2289	V6 TDI, 3.0L-EU5	4F9 910 401 E 007	6	06.02.2009		> 240 sec	A14-OG-IBN-Band
CP4.2	C6	07-2-2305	V6 TDI, 3.0L-EU5	4F9 910 401 E 007	11	06.02.2009		> 240 sec	A14-OG-IBN-Band

CP4.2 engine measurements, tappet movement about the vertical axis



Task:

Measurements at the W19 CO2 engine: Tappet movement about the vertical axis

Test execution:

- CP4.2 2x4.85mm
- Test sequences:
 - Ramp 1,000 4,500 (5,000) rpm engine speed
 - Engine Start/Stop
 - MVFG Test
- Parameter:
 - Fuel:Diesel (measured density at approx. 30 °C: 828 kg/m³)
 - •Kerosene (measured density at approx. 30°C: 781 kg/m³)
 - Runoff position of the pump in US, LS and in the flanks below 45°

Measuring equipment

- Data acquisition of analog data LTT 186/16
- CP4.2 equipped with instruments:
 - Tappet movement about vertical axis, axial path of camshaft,
 - Shear stress of tappet spring and acceleration at the pump housing
 - US pump
 - Engine speed

Diesel systems



CP4.2 engine measurements, tappet movement about the vertical axis



Sequence and number of measurements:

Fuel	Starts	Ramps	Warm-up	MVEG	Other						
		1000-4500 rpm	20 - 30 min								
Diesel	11	6	2	1	Turning: clockwise / anticlockwise						
Reassembly	Reassembly of cylinder heads for C-coated pistons										
Diesel	2	1	1								
Switching to	kerose	ne (about 45 minu	ites engine run)	3							
Kerosene	7	3	1	1							
Switching to	diesel ((about 45 minutes	engine run)								
Diesel	9		1								
Reassembly	of right c	ylinder head for p_	_element measur	rement							
Diesel	10	2	1		Towing, rotation						
					by hand						

Engine running time with kerosene approximately 1.5 to 2 hours

Diesel systems



CP4.2 engine measurements, tappet movement about the vertical axis



Max. tappet movement about the vertical axis (peak to peak):									
Fuel	Motor starts	rotation	Ramps 100	0-4500 rpm	Other				
	angle [°]		rotationangl	e [°]					
	left cylinder	right cylinder	left cylinder	Right cylinder					
Diesel	1.5	0.4	1.0	0.4					
Reassembly	y of cylinder h	neads for C-c	oated pistons	3					
Diesel	7**	3**	2.4** (0.5)	2.6** (0.4)	** Before start-up				
Switching to	kerosene (a	bout 45 minu	ites engine ru	ın)					
Kerosene	1.2 (6)	1	0.4	0.8	() for last measurement				
Switching to	o diesel (abou	ıt 45 minutes	engine run)						
Diesel	6	1.5	0.4	0.5	Ohi P				
Reassembly	of right cylind	er head for p_	Element measure	ement	7936 VO 2014 ×				
Diesel	6	1	0.4	0.5	0 0 1 19 19 19 19 19 19 19 19 19 19 19 19 1				
**After cylinde	r head assembl	v without spring	n clearance befo	ore					

^{&#}x27;After cylinder head assembly, without spring clearance before start-up () Values m m in brackets at 4500 rpm after start-up

Diesel systems





engine measurements, **CP4.2** tappet movement about the vertical axis



Results:

- Turned tappet >1.5° found only in the start case
- During the last start with kerosene, turned tappet was 6° to the left cylinder
- After replacing oil with diesel, often 6° turned tappet during engine start
- No striking features during engine start-up under load at max. speed

Summary:

- Start case is more critical in terms of turned tappet than rpm ramp-up
- 6° turned tappet only at the 1st stroke of the pump to the left cylinder w thout p EL
- For photo documentation of drivetrain parts of metering pump, see following slides

Further work:

- Evaluation of all measurements
- Evaluation of the measured spring shear stresses
- Evaluation of the measured acceleration signals

Diesel systems

Confidential | Non-responsive content removed



CP4 tests at the engine with diesel / kerosene


Fact


- -> Photo documentation of CP4.2 drivetrain parts after tests for the Audi engine with diesel and kerosene
- -> Turned tappet measurements carried out during start tests.
- -> Significant winding on the roller tappet to the left (about 6°) measured

-> Results:


- -> Light edge support on the cam in cam run-up
- -> Alignment mark in LS
- -> Skewing of the roller in the cam profile recognizable
- -> 2 skid marks on the roller, left roller as well as 2 very fine skid marks on the running surface of the right roller











CP4.2 engine measurements, tappet move- ment about the vertical axis		
Detailing:	Fuel	Slide no.
Engine start prior to rpm ramp-up	Diesel	9 , 10
Engine start after rpm ramp-ups	Diesel	11 , 12
Engine start	Kerosene	13 , 14
Engine start	Diesel	15 - 17
 Engine start pump partly vented, vented with measurement p_El 	Diesel	18 - 24
rpm ramp-up after cylinder head assembly Without clearance ("assembly pre-stressing spring")	Diesel	25
• rpm ramp-up 1000-max. rpm var. load	Diesel	26 - 28
• rpm ramp-up 1000-max. rpm var. load	Kerosene	29 - 30
Diesel systems Confidential Non-responsive content removed 02.08.2010 © All rights reserved by Robe		(a) BOSC














































CP4.2 engine measurements, tappet movement about the vertical axis Tappet angle of rotation at engine start: Detailed start 2, pump filled, run-off to left LS Cylinder AngleOfRotation Start Z1 onBDC after 50rpm 0000 AngleOfRotation_cyl2_Start_Z1_onBDC_after_50rpm_0000_p_El_Start_Z1_onBDC_after_50rpm_0000 TDC cyl1 Start Z1 onBDC after 50rpm 0000 speed stgren Tappet angle of rotation -0.1 of left cylinder Tappet_angle of rotation of right cylinder 0.0 -0.1 400 p_EI 300 200 100 TDC left cylinder of both cams 10^3 rpm 0.8 n_pump 0.6 0.4 45 90 135 180 225 270 315 360 405 450 495 540 585 630 675 720 765 810 855 900 Angle of rotation of pump in degrees Diesel systems 02.08.2010 | @ All rights reserved by Robert Bosch GmbH, also with Confidential | Non-responsive content removed 24 regards to industrial property rights. We reserve any right to use, such as right to copy and disclose











[™]VW-F4_2.0I_low: Notes on initial commissioning

VW-R4 (2.0I_low) EU5 - CRS3.2 -

Notes on initial commissioning of CRS in association with the cold test inspection

12/01/2005



To note during assembly

- → Cleanliness requirements, particularly for supply lines to diesel fuel filter.
- → Installation and service notes.
- → Installation requirements (e.g. tightening torques), also see respective component TCDs and proposal drawings.

Initial filling of injection system

- → All TCD values must be followed!
- → Permissible filling fluid: Diesel fuel compliant DIN EN590, however HFRR ≤ 400µm



Recommendation <u>before</u> venting, initial commissioning, and cold test:

→ Perform electrical check (e.g. CRI3.2: contacting, capacity measurement for low voltages, etc. {Note: pay attention to line lengths and resistances of connectors})

Venting of CR system is performed for

- the low-pressure circuits through the CP4 return,
- the high-pressure part (CP4, rail) through suction or HP valve, through the PCVu in total return.

For cold test commissioning:

→ Activation does not take place through engine electronic control unit → test bench control is needed (Activation of PCVu, MU; CRI3.2 should not inject)



Venting high-pressure fuel pump CP4 (without CP) with predelivery EFP

For CP4:


- → Dry running of the high-pressure fuel pump is not allowed!
- → Minimum filling/pre-pressure of 4.5bar abs must always be ensured through predelivery EFP.
- → max. return pressure 1.8bar abs U* (continuous running ≥1.8bar abs can cause damage to the shaft seal).
- → With a rail pressure of 0bar, the max. drag speed is U* n_{CP}=300U/min.
- → Operation of pump only permitted within pressure limit curve CP4 (Tab.1, Diag. 1).



Table 1:

Pump rotation speed [1/min]	100	1000	2000	3000	4000	4500	5000
Pump rotation speed [1/min]	100	1000	2000	3000	4000	4500	5000
Rail pressure [bar]	300	1800	1800	1800	1800	1800	300

Diagram 1:





1) LP/HP venting:

Continue filling the high-pressure fuel pump at a standstill until no further air bubbles are visible in the CP return or overall return. (transparent inlet and return lines recommended).

Notes: MU flow-free open; PCVu flow-free open; more efficient venting through back pressure-free total return bottom/top Predelivery pressure > 4.5bar_abs.

2) Safe venting of HP part:

Depending on the configuration tolerance of suction/HP valve, possibly already completed in step 1 through EFP admission pressure.

Venting of suction/HP valve of CP4 by turning the high-pressure fuel pump with open (flow-free) PCVu until PCVu return is free of air bubbles.

→ System venting is complete; the system is ready for operation.



For cold test commissioning:

- 3) Measurement of rail pressure fluctuation i.e. test whether correct venting occurred or measurement of air incurred during venting.
- **4)** Test (e.g. test of high-pressure seal) with e.g. 1600bar rail pressure and a pump speed of 1500 1/min. (i=1 \rightarrow $n_{CP} = n_{Engine}$). Proposal: Duration $^{U^*}$ 30sec.



<u>Proposal</u>: Check HP seal in pure PCV operation (due to venting; better through PCVu)

MU test: Function test through temporary closing of MU \rightarrow Monitor pressure range (MU_{TV}=100%; not clocked; continuous flow <1.7±0.1A)

At the end of the cold test, the fuel must remain in the system. To transport the engine, seal the inlet and return connections of the injection system tightly with plugs, since HP and LP system are short-circuited with flow-free PCVu. This is intended to prevent leakage of the system, particularly emptying of the rail.

Note: Filling of leakage rail not supported in cold test; only in first start or hot test. Filling takes place through the control volume of the injectors during injection.



No.	EKP [bar absolute]	CP4- retum pressure [bar absolute]	CP4- Speed rpm	Rail pressure [bar]	Pressure control valve u	Metering unit	Remarks	Min duration [sec.]	Max. duration [sec.]
1	min. 4.5	1.0 – 1.2 max. 1.8 U*	0	-	opened I = 0A	opened I=0A	CP LP/HP venting with electric fuel pump preliminary pressure CP supply: ensuring the fuel lubrication and venting of the overall system until CP return bottom/top pressure control valve u return is free from bubbles	U*	=
2	min. 4.5	1.0 – 1.2 max. 1.8 U*	Start max. 300	0	opened I = 0A	opened I=0A	For reliable venting after intake/HP valve ventilation of the HP Hpart until pressure control valve u return is free from bubbles	U*	
3	min. 4.5	max. 1.8 U*	Start max. 300	Start (250)	controls	opened I=0A	•Ventilation check i.e. measurement of the rail pressure fluctuation •If the start pressure is not achieved with stability after 60 s, cancel the test	To be calculated	≤180 U*
4	min. 4.5	max. 1.8 U*	See Table1	See Table1	controls	opened I=0 0.7A	Leakage test (temperature increase pressure control valve u return)	- 2	30 U*

Proposal: Customer coordination of initial commissioning at vehicle plant with RB. The

variables marked with a U* are currently being defined.

VW has yet to define definitive low-pressure configuration. (Pages 11,12).



Note in case of air intake to the LP system before CP4:


If an air column is delivered to the CP4 (e.g. restart after empty tank, through cutting off CP inlet, after filter change) the CP4 cannot deliver the air column to the rail if the PCVu is closed; no pressure build-up is possible.

In this case, the PCVu must be flow-free, i.e. open; only then can the air column be routed through the CP piston to the rail, and then through the PCVu. If CP4.1 is not critical since it is detectable \rightarrow no pressure build-up possible.

→ SW is available for this purpose in the vehicle U*.




Version 2: CP4.1 + inline EFP before Filter





Version 3: CP4.1 + inline EFP after Filter





EA11003EN-00183[0]

From: Non-responsive content removed

To:

CC:

Date: 5/26/2008 4:40:14 PM

Subject: FW: Abridged minutes for on-site meeting on 23/04/2008, Audi exemplary

measurement of cold and hot test operation for R4, 2.0-lire engine

Attachments: Inbetriebnahme CP4 Audi 100408.pdf

7900875d Zu 000 VW-R4 2.01 Hinweise zur Erstinbetriebnahme von CRS3.2.pdf

EHP2 4144 VN5881 Auswertung Kalttest Tr.pdf

Triebwerkschaden .xls

EHP2 4148 VN5881 Auswertung Hottest Tr.pdf

Dear

I hope that you are feeling much better!

Since your mailbox was full, please find attached once again the minutes from our joint meeting regarding measurements on the R4 2.0-liter cold and hot test in

Mit freundlichem Grüssen /Best Regards

Non-responsive content re moved

Robert Bosch GmbH

Non-responsive content removed

70049 Stuttgart www.bosch.com

Non-responsive content rem oved

Robert Bosch GmbH, registered office: Stuttgart, registration court: local court Stuttgart, HRB 14000

Chairman of the Supervisory Board Hermann Scholl;

Management: Franz Fehrenbach, Siegfried Dais, Bernd Bohr, Wolfgang Chur, Rudolf Colm,

Gerhard Kümmel, Wolfgang Malchow, Peter Marks, Volkmar Denner, Peter Tyroller

From:

responsive content removed

Sent: Wednesday, May 07, 2008 3:15 PM

Non-responsive content removed

Cc:

Non-responsive content removed

Subject: Abridged minutes for on-site meeting on 23/04/2008, Audi Györ, exemplary measurement of cold and hot test operation for R4, 2.0-liter

engine

Abridged minutes for on-site meeting on 23/04/2008, Audi

Exemplary measurement of cold and hot test operation for R4, 2.0-liter engine by Bosch

TN: Aud

Audi: Fröhlich:

Non-responsive content removed

Bosch:

*=temporarily

during the 3rd Audi zero-malfunction-discussion on 10/04/2008, the joint recommendation for next steps to record actual developments in the cold and hot test rigs

Non-responsive content removed

points on initial operation R4, 2.0-liter engine
nsive content removed Hinweise zur Erstinbetriebnahme von CRS3.2.pdf>> Non-responsive content removed

22/04/2008, Bosch arrival 14:30,

Instrumentation of a CR engine in cold test upgrade area

Engine cold test: Engine no. CAG 058018 CP4.1 pump: 04 100 408

BPT 0360

23/04/2008, measures for cold test test rig no. 2, from 08:00

Non-responsive content removed

23/04/2008, 12:45, telecon on results of cold test measurements:

- 1. so far 4 5 cold test measurements taken
- 2. at first glance, cold test operation for normal operation i.O. Detailed analysis measurement data still required.
- 3. Required optimization:

cold-test test programme

1. Initial start cold test operation with PDE programme instead of CR cold test programme;

Test rig interrupted (manually or automatically?);

Analysis: Engine working parts carrier bears CR engine no. card

Mobi data shows CR engine no.

Mobi data cold test test rig shows PDE engine

data (BXE...)

For engine type change (PDE-CR/CR-PDE) mu?? Connector plugs on test rig changed manually. This was forgotten.

Proposed remedy: Connector plug identification prior to start of cold-test test run

- 2. CR test programme also starts with non-inserted DRV connector plugs; since measurement window only checks rail pressure at the end of stage 3. CP4.1 is dragged for at least approx. 20 seconds without rail pressure with high engine speed. Repeat cold test if error not identified. possible. Cable harness identification has not yet been introduced due to cycle time. Proposed remedy: Cable harness identification for DRV and RDS prior to start of
- 3. As far as can be seen, pump supply and return hoses are not fitted correctly to the engine

Pump supply and/or return hose from exhaust gas closing plate with hydraulic cylinder

can be pressure tested. Reappeartest shows slight decrease in supply and return pressure.

Proposed remedy: Measurement/observation of exhaust gas pressure at the start

- 4. Flow rate CP4.1 supply in cold test test rig 3. smaller than Bosch initial operation-specifications v. 135 - 2001/h. Proposed remedy: Installation of larger feed pumps on cold-test test rig 2., 3. and 4. analogue cold-test test rig 1.
- 5. Register termination criteria in target-cold-test-target-process R4 2.0-liter and in the SET synchronize test engineering V Audi: Non-responsive content removed
- 6. Insight into the installation protocol of the three failed engines in in the cold test

ENTIRE PAGE CONFIDENTIAL

 $\begin{array}{c} \textbf{EA11003EN-00183[2]} \\ \textbf{Audi doesh't allow any direct insight into the engine installation protocol during on-} \end{array}$ site meeting.

Please find attached the data provided by Audi (1 engine missing).

<<Triebwerkschaden .xls>>

Summary from detailed analysis of the cold test measurement display:

- Supply level with 100 1/h too low (according to instruction min. 135 1/h); with 135 1/h it's surely much better ventilated and the time until rail pressure formation is minimized
- the CR engine can also be driven in the PDE programme (here the pump does not falter)
- if the DRV connection plug is removed, the entire operation can be run without rail pressure
- whilst the blow-out phase increases return return pressure, i.e. low differential pressure and therefore low blow-out function

Important open points regarding cold test:

- how often can the cold test be repeated before the engine looks striking?
 - (above all if for example it is dragged 3 5 times with DRV removed, then the DRV is inserted and the engine is OK)
- in the current measurements from $\frac{\text{Non-responsive content remov}}{\text{ed}}$ there were no amounts and no faults reproduced
- the CP4.1 pump, with which the cold test operation was measured goes to Bosch for diagnostics/analysis V: DS-PC/EHP T: asap

23/04/2008, measurements for hot test, cabin no. 3, from 14:00

Engine no. CAG 051 535 CP4 pump: 01 070 408

BPT 0620

Used engine in the leak test not OK

Measurements for hot test:

Non-responsive content removed

Summary from detailed analysis of the hot test measurement display:

- for normal operation (pump OK, bonding OK etc), the hot test is carried out without complaint
- if, for example, you remove the DRV you can drag with rail pressure 0 and 1000 1/min as long as you want
- no observation ascertainable, which switches off the test rig in the case of a failure
- how often the hot test can be repeated in the case of a failure is unclear
- compared to the Bosch measurements 1.5 years ago no change found in the hot-test test sequence with removed DRV connection plug

Overall summary:

With correct handling in automatic drive (correct bonding, correct test programme, no other defects)

the cold and hot test operations are OK.

However, the procedure in the case of failure is not defined (max. trail duration without rail pressure, max. acceptable number of

repetitions, etc) and with that, possible damage to the high-pressure fuel pump is conceivable.

Further points for clarification:

Clarification necessary observation of start-up of Audi engines in Audi/VW vehicles so far not carried out

EA11003EN-00183[3]

(R4, 2,01 in A3 Cabrio u. Non-responsive content removed V: Audi, Non-responsive content removed

Mit freundlichem Grüssen /Best Regards

Non-responsive content removed

Robert Bosch GmbH

Non-responsive content removed

70049 Stuttgart

www.bosch.com

Non-responsive content remove

Robert Bosch GmbH, registered office: Stuttgart, registration court: local court Stuttgart, HRB 14000 Chairman of the Supervisory Board: Hermann Scholl;

Management: Franz Fehrenbach, Siegfried Dais, Bernd Bohr, Wolfgang Chur, Rudolf Colm, Gerhard Kümmel, Wolfgang Malchow, Peter Marks, Volkmar Denner, Peter Tyroller

₩₩₩4 2.0I: Notes on initial commissioning of CRS3.2

VW-R4 2.01 EU5

- CRS3.2 -

Notes on initial commissioning of CRS with CP4.1 and predelivery inline EFP in connection with cold test inspection

1/14/2008

Notes:

This slide replaces the slides **14121d_Zu** {12/01/05} and **14150d_Zu** {12/09/05};

14911d Zu {03/14/06} [changes marked in "red"]

6860199d Zu {06/27/06} [changes marked in "blue"]

6870329d Zu {08/02/06} [changes marked in "green"]

6890468d Zu {09/13/06} [changes marked in "pink"]

6900721d_Zu {10/31/06} [changes marked in "light green"]

6900721d Zu {5/14/07} [changes marked in "light blue"] Values marked with U are defined; the "U" indicator was deleted.





EA11003\W+R4_2.0I: Notes on initial commissioning of CRS3.2

To note during assembly:

- → Cleanliness requirements, particularly for supply lines to diesel fuel filter.
- → Installation and service notes.
- → Installation requirements (e.g. tightening torque), also see respective component TCDs and proposal drawings.

Initial filling of injection system

- → All TCD values must be followed!
- → Recommended filling fluid: Diesel fuel compliant DIN EN590, however HFRR ≤ 400µm



WW-R4 2.0I: Notes on initial commissioning of CRS3.2

Test to detect "gross leakage" from fuel system

To detect gross leakage prior to initial commissioning in the cold test inspection, a pneumatic leak test can be performed beforehand.

Background: For safety, health, and cleanliness reasons, the fuel system should be checked for gross assembly errors (such as incorrect screw connections) before it is filled with diesel fuel on the cold test bench.

Pneumatic leak test of the injection system:

The fuel system can be tested with air* in the CP4 inlet with pressure-free total return with a **standing** high-pressure fuel pump with **5bar_rel** for t_{max} <30s.

*Page 17



EA11003₩₩₩74_2.01: Notes on initial commissioning of CRS3.2

Recommendation before venting, initial commissioning, and cold test:

→ Perform electrical check (e.g. CRI3.2: contacting, capacity measurement for low voltages, etc. {Note: pay attention to line lengths and resistances of connectors})

Venting of CR system is performed for

- The low-pressure circuit through the CP4 return
- The high-pressure valve (CP4, rail) through suction or HP valve, through the PCVu in total return.

For cold test commissioning

→Activation does not take place through engine starter → Engine test bench control is needed (Activation of PCVu, MU; CRI3.2 should not inject)



EA11003 WW-F4_2.01: Notes on initial commissioning of CRS3.2

Venting high-pressure fuel pump CP4 (without CP) with predelivery EFP

Note the following conditions when venting the CP4:

- → Dry running of the high-pressure fuel pump is not allowed!
- → Minimum filling/pre-pressure of ≥ 4.5bar_abs must <u>always</u> be ensured through predelivery EFP:
 - → Inlet pressure: 4.5 ≤ p_Inlet [bar_abs] ≤ 7*
 *(not a critical limit, but more is not sensible)
 - → Volume flow > 80 l/h + HP volume demand (Upper limit only restricted by max. inlet pressure)
 - → Differential pressure between CP inlet and return:
 p_{In} p_{Re} ≥ 3.4bar_rel
 - → Max. return pressure ≤ 2.0bar_abs (continuous running >2.0bar_abs may result in damage to shaft seal).



EA11003 WW-R4_2.01: Notes on initial commissioning of CRS3.2

- → At Obar rail pressure max. drag speed is n_{CP}=300...1000rev/min. (RB recommendation n_{CP}=500...1000rev/min.)
 - → An important prerequisite for venting the C4 is that the rail pressure is near zero.
 - → If there is standing pressure in the rail, not even the compression ratio of the elements may be enough to deliver the air.
 - → In this case, the only venting path is through the HP piston guidance in the interior, which can take a long time.
 - If rail pressure is zero, a necessary pressure differential of 3.1 ≤ Δp [bar_rel] ≤ 5.1 over suction and HP valve results.
 - → Since the OV is set to approx. 3.3 bar_rel an EFP without rotating CP4 can only be vented if the tolerance values of the SV/HP valves are minimal.



EA11003₩₩₩R4_2.0I: Notes on initial commissioning of CRS3.2


→ Operation of pump only permitted with **pressure limit curve CP4** (Tab.1, Diag.1).

Table 1: Transmission behavior [engine : pump] i= 1


Pump rotation speed [1/min]	0	100	300	300	1000	2000	3000	4000	4500	5000
Engine rotation speed[1/min]	0	100	300	300	1000	2000	3000	4000	4500	5000
Max. rail pressure [bar]	300	300	633	633	1800	1800	1800	1800	1800	300
Min. rail pressure [bar]	120	120	120	230	230	230	230	230	230	230

Diagram1:

Grenzdruckurven CP4.1 / Pressure limit curves CP4.1



Rail pressure [bar]





EA11003₺₩₩₩74_2.0I: Notes on initial commissioning of CRS3.2

Step 1) LP/HP venting:

Continue filling the high-pressure fuel pump at a standstill until no further air bubbles are visible in the CP return or overall return. (transparent inlet and return lines recommended).

Notes: UM flow-free open; PCVu flow-free open; more efficient venting through back pressure-free total return bottom/top Predelivery pressure >4.5bar_abs

Step 2) Safe venting of HP part:

JDepending on the configuration tolerance of suction/HP valve, possibly already completed in step 1 through EFP admission pressure.

Venting of suction/HP valve of CP4 by turning the high-pressure fuel pump with open (flow-free) PCVu until PCVu return is free of air bubbles.

→ System venting is complete; the system is ready for operation.



EA11003 WW ■ RA _ 2.01: Notes on initial commissioning of CRS3.2

Venting steps in detail:

Step 1) Venting time without revs: 10(...20*)s

(this makes the low-pressure area safe; the high-pressure area is only conditionally vented, depending on the tolerance situation of the SP/HP valves.)

and

Step 2) Venting time at speed(300 ≤ n_{DRAG}[min.-1] ≤ 1000*)
after pre-venting of LP area: = 5 to max. 10s
→ max. allowed pos. of CP4 speed gradient: 400rev/min./s

→ For step 1) + 2) essential: p_Rail=0 bar

Caution: Step 2) with p_{Rail} = 0bar or flow-free PCV is restricted to max. 10s!
 → Danger of pump damage in new condition
 From step 3), p_{Rail} ≥ 230bar is essential!

*RB-recommendation



EA11003 WW ■ R4_2.01: Notes on initial commissioning of CRS3.2

Venting cold test commissioning at engine plant

Step 1) Pre-venting of CP4.1 LP area

```
Q_{lnlet} = 135 – 220 l/h (EFP or test bench supply)
```

Alternative

p_{Inlet} ≥ 4.5 bar_abs (≤ 7 bar_abs); RB recommendation:: 5.0 bar_abs

further increase p_{inlet} increases Q_{Return} by 400 l/(h*bar)

```
p<sub>Inlet</sub> -p<sub>Return</sub> ≥ 3,4 bar_rel [= p<sub>Diff.-CP</sub> at Q<sub>Return</sub> ≥ 80 l/h]
```

```
p<sub>Return</sub> ≤ 1.8...2.0 bar_abs (static)
```

t_{Venting} ≥ 10 sec. (pure CP venting time)

 $n_{Pump} = 0 \text{ min}^{-1} \text{ (pump at standstill [!])}$

p_{Rail} = 0 bar_rel (bel. to p_{Return}), PVCu open, that is, without flow [!]



EA11003EVW=R4_2.0I: Notes on initial commissioning of CRS3.2

Step 2) Final venting CP4.1 HP area

 Q_{inlet} = 135 – 220 l/h (EFP or test bench supply)

Alternative

p_{inlet} ≥ 4.5 bar_abs (≤ 7 bar_abs)

P_{Return} ≤ 1.8...2.0 bar_abs (average pressure)

t_{venting} = 5 to max. 10 sec. [caution: Danger of pump damage in new condition!]

n_{Pump} = 1000 min⁻¹ (→ max allowed pos. of CP4 speed gradient: 400rev/min./s)

p_{Rail} = 0 bar_rel (rel. to p_{Return}), PCVu open, that is, without flow [!]

Times must be determined through trials directly on the ending in the final function test (FFT).

- → System venting is complete; the system is ready for operation.
- → Do not operate further without min. rail pressure [p_{Rail} ≥ 230 bar]
- → Otherwise danger of pump damage in new condition!
- → During the first revving up of the CP4, max. allowed pos. CP4 speed gradient: 400rev/min./s



A11003 WW R4_2.01: Notes on initial commissioning of CRS3.2

Tests for cold test commissioning:

Step 3) Measurement of rail pressure fluctuation i.e. test whether correct venting occurred or measurement of air incurred during venting. [Caution: min. Railpressure p_{Rail} ≥ 230 bar]

Step 4) Test (e.g. test of high pressure seal) → p_{Rail} ≥ 230 bar
 with e.g. 1600bar rail pressure and a pump speed of 1500 1/min. (i=1
 → n_{CP} = n_{Motor}). Proposal: Duration 30 sec.

After step 4), the system can be operated as in the vehicle. When shutting down the engine, the max. allowed neg. CP4 rev gradient is: -1800rev/min./s (the transmission behavior [CP:Motor] must be observed.)



A11003IVW-R4_2.0I: Notes on initial commissioning of CRS3.2

<u>Proposal:</u> Check HP seal in pure PCV operation (due to venting; better through PCVu)

MU test: Function test through temporary closing of MU -> Monitor pressure range (flow max. 1s with 1.7±0.1A; not clocked)

At the end of the cold test, the fuel can remain in the system. It is possible to empty the CP incl. inlet and return lines through blowing out* (e.g. air). [Description Page 15] To transport the engine, seal the inlet and return connections of the injection system tightly with plugs, since HP and LP system are short-circuited with flow-free PCVu. This is intended to prevent leakage of the system, particularly emptying of the rail.

Note: Filling of leakage rail not supported in cold test; only in first start or hot test. Filling takes place through the control volume of the injectors during injection.



A11003 VW • R4_2.01: Notes on initial commissioning of CRS3.2

Venting steps in detail:

No.	EFP [bar_abs]	EFP [bar_rel]	CP4 return - back-pressure [bar_abs]	CP4 speed [rev/min.]	Rail pressure [bar]	PCVu	MU	Remarks:	Min. duration [sec.]	Max. duration [sec.]	Q _{ReC.Max.} [I/h] (Test bench inlet)
1	min. 4.5 RB rec. 5.0	min. 3.5 RB rec. 4.0	1.0 - 1.2 max.2.0 <u>Caution:</u> p _{Inl.} -p _{Ret.} ≥ 3.4bar_rel	0	0	opened I=0A	opened I=0A (allowed max. flow1.7A±0.1 A not clocked max. 1 sec.)	Venting at standstill: CP LP venting with EFP admission pressure CP inlet; ensure fuel lubrication and venting of entire system to CP return bottom/top PCVu return and overall return free of air bubbles	10	Unlim. RB rec. 20	4, 6, 8cyl. 350l/h @ 4.0bar_rel
2	min. 4.5	min. 3.5	1.0 - 1.2 max.2.0	(300) 1000	0	opened <i>I=0A</i>	opened <i>I=0A</i>	For safe venting, from suction/HP valve venting of HP part to PCVu return free of air bubbles	5	10	4, 6, 8cyl. 210l/h @ 3.5bar_rel
3	min. 4.5	min. 3.5	max.2.0	(300) 1000	Start (≥230)	regulate	opened <i>I=0A</i>	Venting check, i.e. measurement of rail pressure fluctuation if, after 10sec., a stable starting pressure is not reached, cancel test	to determine	≤ 180	4, 6, 8cyl. 210l/h @ 3.5bar_rel
4	min. 4.5	min. 3.5	max.2.0	pressure/ speed table 1	pressure/ speed table 1 (≥230)	regulate	opened <i>I=0 0.7A</i>	Leakage check (temperature increase PCVu return)	-11	30	4cyl245I/h, 6cyl260I/h, 8cyl300I/h @ 3.5bar_rel

Note: The following applies to steps 1 through 4: max. allowed pos. CP4 rev gradient:: -1800rev/min./s; max. allowed neg. CP4 rev gradient:: -1800rev/min./s; p_{InI}. - p_{Ret}≥ 3.4bar_rel

Proposal: Customer coordination of initial commissioning at vehicle plant with RB.





WW-R4_2.01: Notes on initial commissioning of CRS3.2

Optional:

Emptying of CP through blowing out* (e.g. air) after cold test commissioning:

 $t_{Blowout} \le 30 \text{ sec.}$ $n_{Pump} = 0 \text{ min.}^{-1} \text{ (pump at standstill)}$

Background: Avoid emptying rail volume through CP and PCV.

p_{Inlet} ≤ 5.0 bar_rel, when PCV is closed, e.g., while under flow during blowout process.

*Page 17



EA11003EVW &R4_2.01: Notes on initial commissioning of CRS3.2

Note in case of air intake to the LP system before CP4:

If an air column is delivered to the CP4 (e.g. restart after empty tank, through cutting off CP inlet, after filter change) the CP4 cannot deliver the air column to the rail if the PCVu is closed; no pressure build-up is possible. In this case, the PCVu must be flow-free, i.e. open; only then can the air column be routed through the CP piston to the rail, and then through the PCVu. If CP4.1 detectable -> No pressure build-up possible.

-> SW is available for this purpose at the Fhz.



EA11003 VW R4_2.01: Notes on initial commissioning of CRS3.2

If air or gases, are used, there is a hazard of contamination and water intake.

The cleanliness requirements with regard to air must be followed:


- → The air supply must be free of water and oil.
- → The use of a 0.3µm filter to separate solid contaminates from compressed air and gases is necessary.

RB recommendation: Series filter connection with 5µm [rough] and 0.3µm filter.




WW-R4 2.01: Notes on initial commissioning of CRS3.2


Common Rail System (CRS3.2 - 1800bar mit CRI3.2, CP4.1 mit Tank- u. Inline-EKP nach Filter) Niederdruckkreis VW R4 2.01 EU5/BIN5 im K-SUV/Jetta





EA11003 VW R4_2.01: Notes on initial commissioning of CRS3.2







CP4.1 Cold Test R4 EU5 Audi Non-responsive control of the control



Task:

- Measure commissioning VW R4 TDI
- Measurements on cold test bench + filling station

Trial execution:

•Location: Audi cold test bench no.2 + filling station

• Pump assembly: Series VW R4

• Measured values: Inlet and return pressure (Kistler sensors 10 cm before pump)

engine speed with pickup on camshaft

Rail pressure from engine RDS

I ZME, I DRV with clamp meter measure

Inlet and return volume with VSE

Speed and inlet pressure parallel from control cabinet

• Measurement process: 1. Fill the pump

2. Engine check program (engine not fired)

Data recording: LTT 186/16ch sampling rate 100 kHz

All results for pressure values in bar rel!



CP4.1 Cold Test R4 EU5 Audi Non-responsive tent removed



Results:

- Inlet volume max. 100 l/h (required 135 -220 l/h)
- Operation of pump with PDE cold test possible (connector on equipment transposed, no check as to whether connected properly)
- PCV connector disconnected, or faulty contact is not detected, therefore full test runs with rail pressure 0 bar. The number of possible repeat attempts is unclear.
- Cold test process with correct check program, intact contacts and required inlet volume is OK
- When the pump is blown out, the OV is not opened (therefore poor blowout effect), high back-pressure (2.5 bar rel) in return


SUMMARY:

- Damage to pump in cold test possible due to overly long dragging with rail pressure 0 bar when PCV connector/RDS is disconnected
- Inlet volume, at 100 l/h, is below the requirements of the commissioning guidelines, if the prescribed values are increased, faster rail pressure build-up possible
- Impact of blow-out function from available measurement not optimal






Pump	CP4.1_348_2x5.25_REC_3.3_1.8	nEngine	var	rpm	done by	
Sample	Pump 04 100 408 BPT 0360	P_Rail	var	bar_rel	date	4/23/2008
testbench	Audi cold test bench no. 2	P_inlet	Approx. 4.0	bar		
	Pump empty, cold test with PDE process	T_Inlet	20	°C		







Pump	CP4.1_348_2x5.25_REC_3.3_1.8	nEngine	var	rpm	done by	
Sample	Pump 04 100 408 BPT 0360	P_Rail	var	bar_rel	date	4/23/2008
testbench	Audi cold test bench no. 2	P_inlet	Approx. 4.0	bar		
,	Cold Test Common Rail Motor	T_Inlet	20	°C	DS/EHP2	





CP4.1 Cold Test R4 EU5 Audi Non-responsive con Pump CP4.1 348 2x5.25 REC 3.3 1.8 nEngine done by var rpm Sample Pump 04 100 408 BPT 0360 P Rail var bar rel date 4/23/2008 Audi cold test bench no. 2 P inlet Approx. 4.0 testbench bar 20 Pump filled, cold test T Inlet °C P ReturnEngine idle Run1 0004 P_InletEngine_idle_Run1_0004 P_RailEngine_idle_Run1_0004 I_UMEngine_idle_Run1_0004 I_PCVEngine_idle_Run1_0004 Q_InlEngine_idle_Run1_0004 Q_RetEngine_idle_Run1_0004 Speed_FamosEngine_idle_Run1_0004 Speed FröhlichEngine idle Run1 0004 Blow out? p Inl 3 2 p Ret 1.5 1.0 0.5 p Rail 2.9 1.0 8.5 2.9 1.0 I UM I PCV 8:5 150 100 50 Q InI t 150 100 Q Ret 50 1500 n_Engine 500 50 10 20 30 40




CP4.1 Cold Test R4 EU5 Audi Non-responsive con Pump CP4.1 348 2x5.25 REC 3.3 1.8 nEngine done by var rpm Sample Pump 04 100 408 BPT 0360 P_Rail var bar rel date 4/23/2008 Audi cold test bench no. 2 P inlet Approx. 4.0 testbench bar 20 Pump not filled, cold test T Inlet °C P_InletEngine_idle_Run1_0005 P_ReturnEngine_idle_Run1_0005 P_RailEngine_idle_Run1_0005 I_UMEngine_idle_Run1_0005 I_PCVEngine_idle_Run1_0005 Q_InlEngine_idle_Run1_0005 Q_RetEngine_idle_Run1_0005 Speed_FröhlichEngine_idle_Run1_0005 Speed FamosEngine idle Run1 0005 p Inl 3 2 p Ret 1.5 1.0 0.5 p Rail 2:5 1.0 8:5 2:5 1.0 8:5 I UM I PCV 150 100 Q Inl 50 150 Q Ret 100 1500 1000 n_Engine 500 10 20 30 40 50 60






Pump	CP4.1_348_2x5.25_REC_3.3_1.8	nEngine	var	rpm	done by	Not expension patriol comment
Sample	Pump 04 100 408 BPT 0360	P_Rail	var	bar_rel	date	4/23/2008
testbench	Audi cold test bench no. 2	P_inlet	Approx. 4.0	bar		
	Pump not filled, cold test, repeat	T_Inlet	20	°C	The constraint transplantment	








Pump	CP4.1_348_2x5.25_REC_3.3_1.8	nEngine	var	rpm	done by	the second or to I more!
Sample	Pump 04 100 408 BPT 0360	P_Rail	var	bar_rel	date	4/23/2008
testbench	Audi cold test bench no. 2	P_inlet	Approx. 4.0	bar		
	Cold test, PCV connector disconnected	T_Inlet	20	°C		








Pump	CP4.1_348_2x5.25_REC_3.3_1.8	nEngine	var	rpm	done by	
Sample	Pump 04 100 408 BPT 0360	P_Rail	var	bar_rel	date	4/23/2008
testbench	Audi cold test bench no. 2	P_inlet	Approx. 4.0	bar		
	Cold test, inlet hose jammed	T_Inlet	20	°C	No. anappe and and built comment	







Pump	CP4.1_348_2x5.25_REC_3.3_1.8	nE	Engine	0	rpm	done by	
Sample	Pump 04 100 408 BPT 0360	Р	_Rail	0	bar_rel	date	4/23/2008
testbench	Audi cold test bench no. 2	P	_inlet	Approx. 4.0	bar		
	Compare inlet pressure measurement	T	_Inlet	20	°C	The department or the Lamburg	








Measurement at filling station:

Measured values:

- p_Inlet
- p_Return
- Q_Inlet
- Q_Return



Pump	CP4.1_348_2x5.25_REC_3.3_1.8	nEngine	0	rpm	done by	
Sample	Pump 04 100 408 BPT 0360	P_Rail	0	bar_rel	date	4/23/2008
testbench	Audi cold test bench no. 2	P_inlet	Approx. 4.0	bar		
	Filling station, pump before cold test	T_Inlet	20	°C		





CP4.1 Hot Test R4 EU5 Audi Non-responsive content removed





Task:

- Measure commissioning VW R4 TDI
- Measurements on the hot test bench

Trial execution:

hot test bench no.3 •Location:

Series VW R4 Pump assembly:

 Measured values: Inlet and return pressure (Kistler sensors 10 cm before pump)

engine speed with pickup on camshaft

Rail pressure from engine RDS

I_ZME, I_DRV with clamp meter measure

Inlet and return volume with VSF

•Measurement process: Engine check program (engine fired)

 Data recording: LTT 186/16ch sampling rate 100 kHz

All results for pressure values in bar rel!

Diesel Systems

Confidential Non-responsive content removed 04/28/08 | @ All rights reserved by Robert Bosch GmbH, including the case of patent applications, All usage rights, including copying and distribution, reserved.



CP4.1 Hot Test R4 EU5 Audiontent removed



Results:

- Inlet volume, at 120-125 l/h, is below commissioning guidelines
- Process with correctly connected sensors OK
- Dragging with rail pressure 0 bar (PCV disconnected) without time limit > 1 min possible
- Test bench does not intervene automatically after 10 s dragging with rail pressure 0, intervention was always made by test bench staff

SUMMARY:

- Damage to a high-pressure fuel pump in hot test possible if PCV is disconnected or has faulty contact
- Number of possibilities to repeat hot test after error occurs does not appear to be limited
- No change in test bench process found compared to measurements 1.5 years ago




Confidential Non-responsive content removed

EA11003EN-00186[2]

CP4.1 Hot Test R4 EU5 Audiontent removed



Pump	CP4.1_348_2x5.25_REC_3.3_1.95	n _{Engine}	var	rpm	done by	De reguerat à come à monet
Sample	Pump 01 070 408 BPT 0620	P_Rail	var	bar_rel	date	4/23/2008
testbench	Audi hot test bench no. 3	P_inlet	Approx. 4.0	bar		
	Pump empty, hot test, 1st measurement	T_Inlet	20	°C	Non-responsive content remov	ed








CP4.1 Hot Test R4 EU5 Audi Non-responsive content removed



testbench	Pump empty, hot test, 2nd measurement	P_inlet T Inlet	Approx. 4.0	oC occurrence of the control of the	Non-responsive content removed	
Sample	Pump 01 070 408 BPT 0620	P_Rail	var	bar_rel	date	4/23/2008
Pump	CP4.1_348_2x5.25_REC_3.3_1.95	n _{Engine}	var	rpm	done by	he and artiful control annual








EA11003EN-00186[4]

CP4.1 Hot Test R4 EU5 Audi Non-responsive content removed



Pump	CP4.1_348_2x5.25_REC_3.3_1.95	n _{Engine}	var	rpm	done by	No response active resmail
Sample	Pump 01 070 408 BPT 0620	P_Rail	var	bar_rel	date	4/23/2008
testbench	Audi hot test bench no. 3	P_inlet	Approx. 4.0	bar		
	Pump empty, hot test, 3rd measurement	T_Inlet	20	°C	Non-responsive content removed	








CP4.1 Hot Test R4 EU5 Audiontent removed



testbench	Audi hot test bench no. 3	P_inlet	Approx. 4.0	bar		
Sample	Pump 01 070 408 BPT 0620	P_Rail	var	bar_rel	date	4/23/2008
Pump	CP4.1_348_2x5.25_REC_3.3_1.95	n _{Engine}	var	rpm	done by	




Diesel Systems



EATTOP4-FG408-04-2009: Kraftstoffkritische Märkte

Confidential - Level 2 Material

Relevance of LLP: Example of Non-responsive content removed



For RoW applications, LLP is a robustness improvement measure

Agenda

recimical opecinications Approval Automobile	Γ. Ζ
Technical Specifications Development MD - & OHW	P. 3
Powertrain damage mechanism (simplified)	Pp. 4, 5

Technical Specifications Approval Automobile

Anti wear package	P. 6
The state of the s	

Approved ruer (ruer properties)	Approved fuel (fuel p	properties)	Pp. 7,8
---------------------------------	-----------------------	-------------	---------

What does "Rest of World" fuel mean P. 9

Improving system robustness P. 10



 D^{2}

Main characteristics CP4 for car applications

Rail pressure 2000bar

Piston diameter / pitch 6.5mm / 6.75mm*

*New piston pitch stages: (6 / 6.5 / 7)mm

Fuels Without AWP: EN590

with AWP: US fuels

Service life 300 000km

Fuel inlet temperature 70°C

Setpoint overflow valve 3.5 bar @ 50l/h



Development main characteristics CP4 for MD & OHW

Rail pressure MD / OHW 2500 / 2000bar

Piston diameter / pitch 6.5mm / **7.5**mm

Fuels with AWP: US fuels

Service life MD / OHW **750 000km** / 10 000h

Fuel inlet temperature 80°C

Setpoint overflow valve 3.5 bar @ 50 l/h

Development focus: Robustness of powertrain (P. 6)



Powertrain damage mechanism (simplified cause-effect relationship) How does powertrain damage occur?

Stiff roller -> Brake plates -> powertrain damage

Cause

 μ _roller-roller support > μ _roller-camshaft

(target: μ_roller-camshaft >> μ_roller-roller support)

Why is μ _roller-roller support too high?

Manufacturing deviations, particularly elevations of the components (uneven rollers; roller support with metal spatters; faults confirmed in challenge experiments).

Manufacturing measures implemented & being implemented (P. 14).



Why is μ _roller-roller support too high?

Insufficient lubricant layer height due to low-viscosity fuels with current component tolerances(contact of roughness peaks). Verification to kinematic viscosity 1.9mm2/s. Challenge experiments with components outside tolerance and overload do not show any striking features.

Note: Failures with fuel contaminated with 1% saltwater

Development measures* to increase robustness of CP4 from this costeffect relationship (P. 6)

*Verification within CP4 MD & OHW platform trials



Development focus @ CP4 for MD & OHW

Increase robustness of powertrain (anti wear package)

1) Optimized roller surface

Parts of potential implemented by prohibiting installation of supplier 2 at Audi.

2) Optimized tappet assembly

Characteristic pressing & friction-optimized tappet implemented in W36 & W37; series implementation possible with customer approval. Other characteristics (tappet play, roller play) will be considered in the development of CP4 MD & OHW.

2) Optimized roller support surface/ in particular roller support coating

Parts of potential implemented for CP22/2 for W37 project.

4) Optimized cam



Verification of approved fuels

without AWP: EN590

@ R.B. Verification with EN590

1) Kinematic viscosity: 2.5mm2/s

2) Lubricity: 460µm

3) Particles:

4) Water: 200mg/kg

@ Customer: Verification in target market with country-typical fuel



Verification of approved fuels with AWP: ASTM 975-05 1D & 2D (US fuels with HFRR 520μm)

@ R.B. Verification with GDK570 (570µm)

1) Kinematic viscosity 1.9mm2/s

2) Lubricity 570µm (approved: 520µm)

3) Particles

4) Water 500mg/kg

Random trials with GDK650, kerosene, gasoline, water, particles.

@ Customer: Verification in target market with country-typical fuel



Approval for Rest of World (RoW) fuels

What does "Rest of World" fuels mean?

1) Kinematic viscosity 1.4mm2/s

2) Lubricity 570 µm

3) Particles Fuel filter

4) Water Water separator

Conclusions

Platform verification needed

Rise in cost of pump if use of anti wear package needed

Approval only possible for specific fuel properties

Thresholds for particles & water must be ensured by filters



CR system robustness improvement with RoW fuels

- Increase inlet pressure level & coolant quantity through opt. EFP control
- Limit load if a "lower" temperature threshold is exceed
- Better filtration (particularly water) of inlet volume

Definition of requirement parameters for the system (such as viscosity, lubricity, water, particles, ...) needed to develop & insure the correct measures.



CP4.2 failure statistics @ VW & Audi (from QMM3)



CP4.1 failure statistics @ VW & Audi (from QMM3)



C4 failure statistics @ all customers (from QMM3)



Production measures (QMM3)



Diesel Systems












Log

Topic



CP4 changes 2008

Bosch introduced the planned changes (design changes) in 2008 in the overview list and in detail.

During the introduction of the individual changes, the following procedure was agreed upon between Audi and Bosch:

CP4 technical discussion (special subject: changes 2008)

- 1) C2.1 coated roller support + C2.1 coated roller crest:
- => with V6 W36/37, introduction FG 27.2.

2) Camshaft omission of bearing peen:

=> introduction with V8 Q7, V8 D4 and V6 W36/37; V6Bin5 not until wider trials, V12 after positive trial of V8

3) Spring seat, omission of anti-friction coating:

=> approval with V6 EU5 package B and transfer for V6 Bin5 and V12, decision for V6Bin5 after coordination with VW, clarify for V12 O Series Wk14

4) Standard calotte for cylinder head

=> Introduction for V6EU5, since introduction was positive for all other types; approved for V6 EU5 effective immediately

5) Piston head, omission of C2 layer:

=> Introduction for V6 Bin5 due to existing documents, decision by Audi after consultation with VW (02/15)

6) UM with NC bearing:

=> Trial with V6 EU5/CO2 package 3 (Wk9) and with V8 Q7, V8 D4, clarify for V12 O Series Wk14 (Non-responsive content rem., 02/15); System CR RB V12 already equipped, start Wk9; V6Bin5 conversion in series,

7) Roller short from second supplier Güntert

=> Approval will take place for V6 EU5 with package B in Wk36; approved immediately for V6 Bin5, verified in PTS and RB continuous running, ISIR for V12, series JhP for VW R4

As part of the meeting, we defined with Audi how the changes can be included in the

Diesel Systems











Log

CP4 technical discussion (special subject: changes 2008)

vehicle trials (see table).

Fahrzeugerprobungen	Änderungen	W26	W19BIN5 0-Serie KW10	W19BIN5 KW15	W19EU5 1800bar CO2 KW10	W19EU5 1800bar CO2 KW15
1. KW 10	ZME NC-Laber	ja*	ja	ja	ja	ja
Paket 3 (Design)	Entfall C-Schicht Kolbensonne	÷	nach Abspr. mit VW	ja	÷	÷
	Entfall Gleitlack Federteller	ja*	nach Abspr. mit VW	ja	ja	ja
2. KW15	wie Paket 3, zusätzlich					
Paket 4	Entfall Kugelstrahlen NM	Übernahme VV24		ja	ja	ja
(Design + Kapa-Steigerungen)	Werksänderungen	Übernahme VV24		ja		ja
Geplante Fahrzeugerprobungs-Sti	ückzahl		50	20	10	10
Geplante Fahrzeugerprobungs-Sti			50**	15+5	5+5	5+5

Table texts:

(Design + Kapa-Steigerungen) = (design + cap. increase)

2. KW15 = 2. Wk15

Änderungen =Changes

Entfall C-Schicht Kolbensonne= Omission of C layer piston head

Entfall Gleitlack Federteller = Omission of antifriction coating on spring seat

Entfall Kugelstrahlen NM = Omission of bearing peen

Fahrzeugerprobungen = Vehicle trials

Geplante Fahrzeugerprobungs-Stückzahl

=Planned vehicle trial units



Geplante Fahrzeugerprobungs-Stückzahl = Planned vehicle trial units

ja = Yes

KW = Wk

nach Absprache mit = after discussion with VW Paket 3 (Design) = Package 3 (Design)

Paket 4 = package 4

Serie = Series

Übernahme W42 = Transfer W24

Werksänderungen = Plant changes

wie Paket 3, zusätzlich = Like package 3, plus

ZME NC-Laber = ZM NC-Laber

* All from Wk14, check O Series

** Preproduction from Wk10, only for



With regard to the changes omission of C layer from piston head and omission of anti-friction coating on spring seat, Audi would like to discuss the situation with VW. A decision is planned by the end of Wk07.

Non-responsive content remove

Agenda:

CP4 changes 2008

Version overview / subject overview

trial Overview





•• P4 technical discussion Audi 02/13/2008

4																					
Customer	Project	Pump	Pressure	Pitch	FP	Cold package	AWP	Approval no. or pattern no.	Batch	Start DL or delivery date	Outlook Roller support C2.1 or C3 opt. instead of C3	Roller: Cone C2.1 layer	Camshaft: Omission of bearing peen, with 1-stage Finnish	spring seat: Omission of anti-friction coating	Cylinder head Standard calotte red. Play (Pressure compensation ridge)	Cylinder head: Piston head w/o C2 (only AWP)	UM: with NC warehouse	Roller: Second supplier Güntert, Short version	Duplication of tools due to capacity increase, Details: see change package A+B	Duplication of tools due to capacity increase, Details: see change package 4	
																					\Box
	V6 EU5/CO2							Series with index		Wk10	-	-	X		X		X	x	-	-	
Audi	V6 EU5/CO2							Series with index		Wk15	-		x	X	X		x	x	-	X	\blacksquare
Audi	V6 Bin5/EU6							Series with index		Wk10	-	-	-	?	X		X	х	-	-	
Audi	V6 Bin5/EU6							Series with index		Wk15	-	ē .	x	x	x	?	x	х	-	X	\boldsymbol{H}
Audi	V12							Series with index		Wk14?	-	-	-	x	X		X	x	-	?	
Audi	V6 EU5/CO2	CP4.2	1800	4.85	EFP	No	No	0 445 010 611	Target state of series		x	X	x	x	X		x	х	x	x	-
Audi	V6 EU5/CO2		_					Series with index	Change package 1	18/1:00	-	-	-	-	-		-	-	-	-	
Audi	V6 EU5/CO2	0040	2000			ED4		Series with index	3 , 3 ,	Wk06			.50	X	. 5	20	*	x	X	-	-
Audi	V6 EU6/Bin5	CP4.2	2000	5.6	EFP	FP1	Yes	0 445 010 613	Target state of series	December	x	x	x	X	X	X	x	X	x	x	
Audi	V6 EU6/Bin5 V6 EU6/Bin5							0 445 B20 169_09		Running A.2008	-	-	-	-	-	-	-	x x	-	-	
Audi	V6 EU6/Bin5			_			-	0 445 B20 169_11a Series no. with index	The second control of the property of the second of the se	Wk48	-	-	-		x	x	x	X	-		-
Audi	V6 EU6/Bin5			_			_	Series no. with index	D sample (ISIR)	(A.2008)	-	-	20		X	?	x	x	-	-	-
0.000	V12	CP4.2	2000	5.6	ZP38	ED1	No	0 445 010 619	Target state of series	(A.2000)	x	x	x	-	x	524	x	x	x	x	-
Audi	V12	CF4.2	2000	5.6	2530	FFI	NO	0 445 B20 200 03	Comp. CR, 2x2000h	Completed	-	-	-		x			x	-	-	-
Audi	V12		_					0 445 B20 200_03		A.2008	-	-			x		x	x		-	-
	V12							Series with index		Wk 04	-	-	•	<u>-</u>	x		<u> </u>	x	_	-	
Audi	V12							Series with index		(A.2008)	-	-	-	x	x		x	x	-	-	
Audi	V8 Q7	CP4.2	2000	5.6	ZP38	FP1	No	0 445 010 620	Target state of series		x	x	x	x	x		x	x	x	x	\blacksquare
Audi	V8 Q7							0 445 B20 172 06	Comp. CR, 4x2000h	Completed	-	-	-	x	x		•	x	-	-	\Box
Audi	V8 Q7							0 445 B20 172_08		A.2008	-	-	x		x		x	x	-	-	
Audi	V8 Q7							0 445 B20 172_09		Wk13	-	-	x	x	x		x	x	-	-	
Audi	V8 Q7							To be determined	D sampl e	Wk20	•	-	x	x	x		x	x	•	-	
Audi	V8 D4	CP4.2	2000	5.6	EFP	FP1	No	To be determined	Target state of series		x	х	x	х	x		х	х	х	х	
Audi	V8 D4							0 445 B20 188_03a	Comp. CR, 2x2000h	A.2008	-	-	x	x	x		x	x	-	-	
Audi	V8 D4	Ĭ.						0 445 B20 188_04	Syst. CR, 2x2000h	A.2008	-	- "	x	x	x		x	x	-	-	
Audi	V8 D4							0 445 B20 188_06		A.2008	-	x	x		x	9	x	x	-	-	
Audi	V8 D4							0 445 B20 188_07		Wk04	-	-	x	x	x	i j	x	х	-	-	
Audi	V8 D4							0 445 B20 188_05		Wk05/08	-	-	x	x	x		x	x	-	- 1	\square
Audi	V8 D4							To be determined	Participation of the Control of the	M.2008	-	-	x	x	x		x	x	-	-	
Audi	V6 W36/37	2000 6			EFP F	P1	No	To be determined	Target state of series		x	x	x	x	x		x	x	x	x	
Audi V	6 W36/W37							0 445 B20 220_01	B sample	A.2008	(x)	(x)	x	x	X		X	х	-	-	





OP4 technical discussion Audi 02/13/2008

Suggestion for how to proceed:

- 1) C2.1 coated roller support + C2.1 coated roller crest:
 - => with V6 W36/37, introduction FG 27.2.
- 2) Camshaft omission of bearing peen:
- => introduction with V8 Q7, V8 D4 and V6 W36/37; V6Bin5 not until wider trials, V12 after positive trial of V8
- 3) Spring seat, omission of anti-friction coating:
- => approval with V6 EU5 package B and transfer for V6 Bin5 and V12, decision for V6Bin5 after consultation with VW, clarify for V12 O Series Wk14 (Non-responsive content removed
- 4) Standard calotte for cylinder head
- => Introduction for V6EU5, since introduction was positive for all other types; approved for V6 EU5 effective immediately
- 5) Piston head, omission of C2 layer:
- => Introduction for V6 Bin5 due to existing documents, decision by Audi after consultation with VW (02/15)
- 6) UM with NC bearing:
- => Trial with V6 EU5/CO2 package 3 (Wk9) and with V8 Q7, V8 D4, clarify for V12 O Series Wk14 (, 02/15); System CR RB V12 already equipped, start Wk9; V6Bin5 conversion in series,
- 7) Roller short from second supplier Güntert
- => Approval will take place for V6 EU5 with package B in Wk36; approved immediately for V6 Bin5, verified in PTS and RB continuous running, ISIR for V12, series JhP for VW R4



EA11003 SR46technical discussion Audi 02/13/2008

Current version overview

Quantity balance	OK	OK	OK	Critical	Critical	OK	OK	OK
Drive	bed round and with the property of a place the care	Long shaft, 1WDF	Long shaft, 2WDF	Long shaft, 1WDF	Long shaft, 1WDF	Long shaft, 2WDF	Short shaft, 1WDF	Short shaft, 1WDF
Cylinder head	1x front, 1x bac	1x front, 1x bac k	2x back	2x front	2x front	2x back	1x back	1x back
Shaft seal	Kaco	Bruss / KP1	Bruss / KP1	Bruss / KP1	Bruss / KP1	Bruss / KP1	Bruss / KP1	Bruss / KP1
AWP	No	AWP1 *)	No	No	No	No	No	AWP1
Cam pitch	4.85	5.6	6	5.6	5.6	5.6	5.25	5.25
n(Pp/Mot) over	4315(5750)	4315(5750)	4315(5750)	5250	5250	4315(5750)	5500	5500 **)
n(Pp/Mot) Pmin.	4125(5500)	4125(5500)	4125(5500)	5000	5000	4125(5500)	5300	5300 **)
n(Pp/Mot) Pmax.	3750(5000)	3750(5000)	3750(5000)	4500	4500	3750(5000)	4500	4500 **)
Rotation direction	Right	Right	Right	Left	Left	Left	Right	Right
Ratio	3/4	3/4	3/4	1	1	3/4	1	1
Pressure	1800	2000	1800/2000	2000	2000	2000	1800	1800
Presupply	EFP	EFP	EFP	EFP	ZP38	ZP38	EFP	EFP
Design	CP4.2 CP4.2	Н	CP4.2H	CP4.2H	CP4.2H	CP4.2H	CP4.1	CP4.1
Type Part No.	611	613	B sample	C sample	620	619	507	
	EU5 / CO2	EU6/Bin5	W36/W37	EU5/ D4	EU5/ Q7	V12 EU5	EU5	Bin5
	Audi V6	Audi V6	Audi V6	Audi V8	Audi V8	Audi	VW R4	VW R4

Open items:

- Commissioning guideline: V6 OK, R4 still open, meeting RB Fröhlich on 01/30
- Bearing strength measurement V6Bin5: Values currently too high, RB open to new measurement with changed config.
- Determination V6 W36/37: Space for bolt indent being clarified
 - *) Warm up with AWP1, omission of AWP1 for EU version planned in PKO measure



©P4 technical discussion Audi 02/13/200

RB components trial CR (1800/2000bar, US fuel GDK 570, EFP version)

Туре	PNR	Vers.	Pump. No	. M status	WDR	cold seal	Pitch	CR progr.					10/01	10/08	10/15	11/12	11/19	11/26	12/03	12/10	12/17		01/07	01/14	01/21	01/28	02/04	02/11	
le n	063_02	AWP1	686-410 6	B1 (C2)	KACO	2	6	PDL_2000	2000	CR pa	assed																		
04.18 US f	063_02	AWP1	686-4107	B1 (C2)	KACO	-	6	PDL_2000	2000	CR pa	assed																		
PF CP4.1S 1800bar, US fuel	060_08	No AWP	690-4592	B1 (C2)	KACO	8	5.25	PDL_2000	2000	CR pa	assed																		
180	060_08	No AWP	690-4594	B1 (C2)	KACO	28	5.25	PDL_2000	2000	CR pa	assed																		
	060_12	AWP1	200207- 0040	C2	Bruss	-40°C OK	5.25	PDL_2000	2001	CR pa	assed																		
10	060_12	AWP1	200207- 0041	C2	Bruss	-40°C OK	5.25	PDL_2000	2001	CR pa	assed																		
S 1800bar, S-Fuel, VW R4 Bin5	060_12	AWP1	200207- 0042	C2	Bruss	-40°C OK	5.25	PDL_2000					1905	2000	CR pas	sed													
CP4.1S 1800bar, US-Fuel, tomer VW R4 Bir	060_12	AWP1	200207- 0043	C2	Bruss	-40°C OK	5.25	PDL_2000	2000	CR pa	assed																		
CP4.18 US customer	060_12	AWP1	200207- 0044	C2	Bruss	-40°C OK	5.25	KDL_500	500	CR pa	assed																		
cns	060_12	AWP1	200207	C2	Bruss	-40°C OK	5.25	KDL_500	500			with rest		S															
Ш	060_12	AWP1	200207	C2	Bruss	*	5.25	KDL_500	549		assed		300																
-	154_07	AWP1	690-4589	B2 (C2)	KACO	-	6	PDL_2000	2000	CR pa	assed																		\neg
2HS, JS fue	154_07	AWP1	690-4590	B2 (C2)	KACO	=	6	PDL_2000	2000	CR pa	assed																		
PF CP4.2HS, 2000bar, US fuel	154_10	AWP1	781-4837	B2 (C2)	Bruss	-40°C OK	6	PDL_2000	2000	CR pa	assed																		\Box
2000	154_10	AWP1	781-4838	B2 (C2)	Bruss	-40°C OK	6	PDL_2000	2000	CR pa	assed																		
	169 08	AWP1	783-4680	C2	Bruss	-40°C OK	5.6	PDL_2000	2000	CR no	ot pass	sed			OK														=
	169 08	_ and accompanied	783-4681	C2	Bruss	-40°C OK	5.6	PDL_2000		CR no	ot pass	ed		IM diag															
	169 09	AWP1	785-426 3	C2	Bruss	-40°C OK	5.6	PDL_2700		Later	ai roile			M diag		1 - /	270	21- 9	1886	1975	2000	Interim	l diagnosi	s 2000h	OK		Р	rojecte	d
CP4.2HS, 2000bar, US fuel EE customer	169 09	AWP1	785-426 4	C2	Bruss	(2000h) -40°C OK	5.6	PDL 2700					ont	inue	run	102	2/0()n -	1886	1975	2000		diagnosi sheared		not OK I	ИU	1115550	rther ru 2/15/200	5535
P4.2 bar, L	169_08	The second of	783-4678	C2	Bruss	(2000h) -40°C OK	5.6	KDL_500	500	CR pa	assed		100000	NAME OF	1000000	1000000	- Contractor		[Darwer	- Mary Section		O fing :	sneared	OII				10,200	
2000]	169 08	2519952000	783-4679	C2	Bruss	-40°C OK	5.6	KDL_500		CR pa		\dashv																	\dashv
	169 09		785-4268	C2	Bruss	To be planned	5.6	PDL_2000									. 200							1153	1222	1388	1555	1720	$\overline{}$
	169 09	2000 CO 100 CO	786-4533	C2	Bruss	To be planned	5.6	PDL_2000			∦ F	Кер	eat	atte	mpt	due	to I	ater	al ro	ller	war	m-u	p_	1153	1157	ZWM	ZWM	ZWM	
	.00_00	_ Y W W W L		9-	D.000		0.0	. 52_2500														Ÿ.		1,00	1.07	02000	(Control of		





OP4 technical discussion Audi 02/13/2008

RB component trial CR (1800/2000bar, EN590, CP version)

		R to achiev																Date					
	PNR		E statu	s Pitch		WDR	cold seal	CP diagnosis			17457/14/2004	08/13	08/20	08/27	3.09	09/10	09/17	10/01	10/08	10/15	11/12	11/19	
· ω	045_01	685-4778	B0.2	6	KDL_1000	KACO	2	OK	1000	CR pas													
C. P	045_01	685-477	B0.2	6	KDL_1000	KACO	*	OK	1000	CR pas	sed												
C P	045_01	685-499	B0.2	6	PDL_2000	KACO	3.5	OK	2000	CR pas	sed												
rm Oba	045_01	685-478	B0.2	6	PDL_2000	KACO	*	OK	2000	CR pas	sed												
Platform CP4.1S 1800bar, ACP, 4500rpm	045_01	685-477	B0.2	6	PDL_2000	KACO	2	OK	2000	CR pas	sed												ī
<u>-</u>	045_01	685-493	B0.2	6	PDL_2000	KACO		OK	2000	CR pas	sed												
	131_03	685-494	B0.2	6	KDL_1000	KACO	5	OK	1000	CR pas	sed												
0 rpm	131_03	685-493	B0.2	6	PDL_2000	KACO	(46)	CP-WDR med. wear	2000		ear throu	ugh ACI	P-WDR,	fretting	of SV se	eal							
Platform CP4.2S 800bar, ACP, 3750rpm	131_03	THE ALL STORY	U-251-20	6	PDL_2000	KACO	*	CP-WDR med. wear	2000	CR pas NW: We	ear thro			fretting	of SV s	eal							
ACP.	131_03			6	KDL_1000	KACO	*	OK	1000	CR pas													
forr r, A		685-494		6	PDL_2000	KACO	×	CP-WDR med. wear	2000	CR pas													
lat		685-494		6	PDL_2000	KACO	*	CP-WDR med. wear	2000	CR pas													
800	170_01	691-485	B1	6	PDL_2000	KACO	-25°C R4	OK	2001	CR pas													
-	170_01	691-485	B1	6	PDL_2000	KACO	-25°C R4	ОК	2001	CR pas due to f					uli to		el (
CP4.2HS, 2000bar ACP, 3750rpm	200_03	785-420	С	5,6	PDL_2000	BRUSS	-40°C R1	Function OK Clutch piece embedded in CP cover			749	913	1079	1172	1336	1503	1668	1966	2000	CR pass UM diag	s ed nosis OK	9) 65	
EE custom CP4. 200 ACP, 3	200_03	785-420	С	5,6	PDL_2000	BRUSS	-40°C R1	Function OK Clutch piece embedded in CP cover			749	913	1079	1172	1336	1503	1668	1966		CR pass UM diag		à	
	172_06	785-425	С	5,6	PDL_2000	BRUSS	-40°C R1	Function OK Clutch piece embedded in CP cover			0	26	130	288	360	490	654	981	1148		1950	2000	CR passed
(V8)	172_06	785-425	С	5,6	PDL_2000	BRUSS	-40°C R1	Function OK Clutch piece embedded in CP cover			0	26	130	288	360	490	654	981	1148	/604	1950	2000	CR passed with restrictions due to tear in UM strainer
omer 2000 500rpn	172_06	785-425	С	5,6	PDL_2000	BRUSS	e.	Function OK Clutch piece embedded in CP cover						322	286	446	614	919	1086	200	1920	2000	CR passed
EE customer (V8) CP4.2HS, 2000bar ACP, 4500rpm	172_06	785-425	С	5,6	PDL_2000	BRUSS	÷	Function OK Clutch piece embedded in CP cover				esign sp te w/o a		1412	286	446	614	919	1086	44	1920	2000	CR passed
CP	172_06	785-425	С	5,6	KDL_500	BRUSS		Function OK Clutch piece embedded in CP cover			J.C. 200	tion coa	990000	7444	398	500	CR pas	sed					
	172_06	785-425	С	5,6	KDL_500	BRUSS	-	Function OK Clutch piece embedded in CP cover						2000	398	500	CR pas	sed					





EA11003 © Rudetechnical discussion Audi 02/13/2008

RB component trial CR (2000bar, EN590, EFP version)

1		Ne	c. CR to ac	hieve B10	target		1,74,3				Special Control				20.00										
	PNR	Pump no.	E status	WDR	cold seal	Pitch	CR progr.			10/01	10/08	10/15	10/22	10/29	***		02/04	02/11	02/18	02/25	03/03	03/10	03/17	03/24	
H ma	051_09	686-01-125	B2H (C2)	KACO	Æ	6	PDL_2000	2000	CR passed																
CP4. r, EF 4800r	051_09	686-01-126	B2H (C2)	KACO	6)	6	PDL_2000	2000	CR passed																
Platform CP4.1H, 2000bar, EFP, EN590, 4800rpm	051_09	686-0127	B2H (C2)	KACO	÷	6	PDL_2000	2000	CR passed																
Plat 20 EN	051_09	686-0128	B2H (C2)	KACO	E.	6	PDL_2000	2000	CR passed																
er,	050_07	690-01-4599	C2H	KACO	-25°C OK	5,25	PDL_2000	2000	CR Passed																
CP4.1HS EE customer, 4800rpm	050_07	690-01-4601	C2H	KACO	-25°C OK	5,25	PDL_2000	2000	CR passed																
CP4 EE cu	050_07	690-01-4603	C2H	KACO	œ	5,25	KDL_500	500	CR passed																
	050_07	690-01-4605	C2H	KACO	*	5,25	KDL_500	500	CR passed																
ar,	133_15	689-4810	B2H (C2)	KACO	590	6	KDL_500	500	CR passed																
2000b 50rpn	133_15	689-4811	B2H (C2)	KACO	*	6	KDL_500	500	CR passed																
2H, 2 0, 37	133_15	687-0243	B2H (C2)	KACO	9	6	PDL_2000	2000	CR passed																
CP4 EN59	133_15	687-0244	B2H (C2)	KACO	ē.	6	PDL_2000	2000	CR passed																
Platform CP4.2H, 2000bar, EFP, EN590, 3750rpm	133_15	689-4808	B2H (C2)	KACO	¥	6	PDL_2000	2000	CR passed with r WDR in CR leakin			vet)													
	133_15	689-4809	B2H (C2)	KACO		6	PDL_2000	2000	CR passed																
CP4.2HS EE customer, 3375rpm	155_06	783-4349	C2	KACO	¥	5,25	PDL_2000			2000	CR pass	sed													
CP4 EE cus	155_06	783-4350	C2	KACO	*	5,25	PDL_2000			2000	CR pass	sed													
CP4.2HS EE customer 4500rpm	188_03	789-4266	C2	BRUSS	To be planned	5,6	PDL_2000									Redesig	n TW	0							
CP4 EE cu	188_03	789-4267	C2	BRUSS	To be planned	5,6	PDL_2000								3	Redesigi	1 TW	0							





©P4 technical discussion Audi 02/13/2008

RB system trial CR (Audi, VW)


уре	PNR	Pump.No	Sample	WDR	cold seal.	Pitch	CR progr.		10/22	10/29	11/05	11/12	11/19	11/26	12/03	12/10	12/17		01/07	01/14 0	1/21	01/28	02/04	02/11	
<u> </u>	508	020507- 0313	С	Bruss		5,25	PDL_2000		233	387	453	600	750	855	997	1113	1250	***	1530	ZWM	ZWM	1654	1818	1948	
US fu	060	130407- 0311	С	Bruss		5,25	PDL_2000	Ī	233	387	453	600	750	855	997	1113	1250		1530	ZWM	ZWM	1654	1818	1948	
CP4.1S 1800bar, US fuel VW R4 Bin5	060	270407- 0001	С	Bruss		5,25	PDL_2000		731	895	1038	1188	1331	1497	1657	1801	1993		2020	CR ende	ed				Г
180	060	250407- 0346	С	Bruss		5,25	PDL_2000		731	895	1038	1188	1331	1497	1657	1801	1993		2020	CR ende	ed				
e c	169_11	788-4959	С	Bruss		5,6	PDL_2000	Г							13	13	13		389	ZWM	461	621	692	837	
CP4.2HS 2000bar, US fuel Audi V6 BIN5	169_11	788-4960	С	Bruss		5,6	PDL_2000	Γ							13	13	13		389	ZWM	461	621	692	837	
CP4. Obar, udi V	169_11	787-4938	С	Bruss		5,6	PDL_2000	Г								Pistor	n head w	design //o C lay					65	197	
	169_11	787-4939	С	Bruss		5,6	PDL_2000											h NC bea					65	197	
2HS EN590 6 EU6	169_11	787-4940	С	Bruss		5,6	PDL_2000									Pistor		design /o C laye	er UM w/	7	21	141	271	379	
CP4.2HS 2000bar, EN590 Audi V6 EU6	169_11	787-4941	С	Bruss		5,6	PDL_2000									NC be AFC	earing sp	oring plat	e w/o	7	21	141	271	379	,
	200_04	787-4727	С	Bruss		5,6	PDL_2000								92	255	420		852	1011	1011	1266	1432	1504	
CP4.2HS 2000bar, EN590 Audi V12 EU5	200_04	787-4728	С	Bruss		5,6	PDL_2000								113	287	399		827	952	999	1151	1314	1506	
CP4.	200_04	787-4730	С	Bruss		5,6	PDL_2000									2-eta		design vith rece	ee LIM				Comr	nissionin	
	200_04	787-4731	С	Bruss		5,6	PDL_2000										bearing		- OW					p. Wk34/2	
CP4.2HS 2000bar, EN590 Audi V8 EU5 ZP			С	Bruss		5,6	PDL_2000																Comr	missionir	
CP4. 2000bar Audi V8			С	Bruss		5,6	PDL_2000																•	p. Wk37/	
			С	Bruss		5,6	PDL_2000																Com	missionii for Wk14	_
ZHS ENE			С	Bruss		5,6	PDL_2000																	p. Wk39/	
CP4.2HS 2000bar, EN590 Audi V8 EU5 EFP			С	Bruss		5,6	PDL_2000																	missionii for Wk36	
200 Auc			С	Bruss		5,6	PDL_2000																	p. Wk51/	





						Ad	ditional pumps	
<u>Endurance</u>				W26	BIN5	BIN5	EU5	EU5
<u>run pumps</u> <u>f. Audi</u>					0-series	Further dev.	1800 bar CO2 KW15	CO2
<u>r. Addr</u>					WK10	dev.	002 1111	WK15
						WK15		
1. WK 10	Pcs.	 Metering unit 	nc-	Yes	Yes	Yes	Yes	Yes
Packet 3		bearing			After verification VW	Yes		
		 No C-layer pis 	ston	Yes	After verification VW	Yes	Yes	Yes
2. WK 15 (?)		sensor						
Packet 4		 " Bonded 		Takeover		Yes	Yes	Yes
		coating of spri	ing seat	W24	Yes	res	703	
	+ factory changes:	As market O misses		_" _		Yes		Yes
	r ractory changes.	As packet 3, plus:						
		No camshaft shotpooning						
		shotpeening						
			>					
		Piece	count		50	20	10	10
				All from	50	15 + 5	5 + 5	5 + 5
				WK14 Check 0-		EK/		
				series	Preliminary	from		
					series	WK10		
				•			•	'

EA11003EN-00276[0]



EA11003EN-00276[1]

Safety considerations for turned tappet CP4.1



Analytical consideration for turned tappet

Safety = loading capability / loading

Loading capability =

Aligning and locking torques about the longitudinal tappet axis

Loading =

Exciting torques about the longitudinal tappet axis

EA11003EN-00276[2]

Safety considerations for turned tappet CP4.1



Influencing variables + loading capability boundary conditions

1. Cam lead

Axial force, roller length, local angle of application of force on cam

Tappet spring torsion

Torsional rigidity of spring, "exciting" turn angle, limited by spring friction at contact surfaces:

Friction coefficient spring seat + axial spring force

 Friction between housing and tappet in the circumferential direction
 Tappet diameter, friction coefficient of tappet housing (circumference), medium angular velocity, transverse force on tappet

4. Fluid friction

Tappet diameter, length, diametral clearance, dynamic viscosity, angular velocity

5. Inertia

Angular acceleration, moment of inertia of tappet assembly




EA11003EN-00276[3]

Safety considerations for turned tappet CP4.1





Considered influencing variables

4 frictional contacts:



Asymmetric surface presses





Diesel systems

Confidential | 06.01.2007 | 06.01.2007 | © All rights reserved by Robert Bosch GmbH, also with regards to industrial property rights. We reserve any right to use, such as right to copy and disclose.



EA11003EN-00276[4]

Safety considerations for turned tappet CP4.1



Safety in all four cases:

	Direction of stroke	Cam and angle	Camshaft first	Load status FM	Remark	Safety
1 Case	Ascending	45	Unity NoWe	Maximum delivery		53.4
2 Case	Ascending	45	Unity NoWe	Zero delivery		6.7
3 Case a	Ascending	45	Unity NoWe	not relevant (suction)	Spring not broken in	3.5
3 Case b	Ascending	45	Unity NoWe	not relevant (suction)	Spring broken in	34.5

EA11003EN-00276[5]

Safety considerations for turned tappet CP4.1



Further work:

- Parameterization
 Safety considerations for all cam angles
- Compare boundary conditions with actual measurements and explain for different operating conditions



EA11003EN-00276[6]

Overview of functional test measurements turned tappet CP4.1



Task:

Measurement of the tappet movement about the vertical axis

Inclusion of different operating conditions and available part types

Test execution:

Pump: CP4.1-348_2x5.25 ZP sand casting housing adapted to EFP

Pump fitting: on pump test bench

Readings:
 Relative rotation of the tappet body in operation, no zero-

measurand output

- Axial path of the camshaft

- Rail pressure, pump speed, ZME current


• Test sequences: - Factory test sequence as in pump manufacturing

- Development test sequence DS/EHP2

- Speed ramps 0-1000 rpm with minimum rail pressure

Parameter variation:
 See following slides

- Only one parameter was changed per test!





EA11003EN-00276[7]

Overview of functional test measurements turned tappet CP4.1



Overview of influences investigated:

1. Operating conditions:

Influence	Operating conditions	Effect on turned tappet	Picture
Engine speed	Starting the pump	Highest turned tappet values reached when the pump starts before alignment via engine speed -Increasing engine speed: Turned tappet is less	Page 11
	>3000 rpm	During first start-up at the factory: Alignment of tappet combination using engine speed level 3,375 rpm	
	Stopping the pump (overrun condition)	No critical increase in the turned tappet when decreasing the speed to 0	
Rail pressure	Starting the pump	After build-up of the minimum rail pressure reduction of the turned tappet	
	Operation	Tendency: Rail pressure is higher, lower turned tappet	
Filling (I-ZME)	Start + operation	No detectable influence	
Inlet pressure	Start	Even with incomplete venting, no impact No effect on start-up without inlet pressure	
	Operation	No influence in the context of the conditions tested	
Back pressure	Start + operation	No detectable influence	



EA11003EN-00276[8]

Overview of functional test measurements turned tappet CP4.1



Overview of influences investigated:

2. Component influences of tappet assembly:

Component	Parameter variation	Effect on turned tappet	Picture
Direction of spring coiling	right	Basic case series	
	left	No effect, the direction of turn LS depends on the spring turn direction	Page 12
Roll	Roll stuck	extreme turned tappets till 30°	Page 13
Roll length	24.9 mm)	not rated yet	
	24.7 mm)	Similar to the series case, basic case also included in all measurements	
	24.5 mm)	not rated yet	



EA11003EN-00276[9]

Overview of functional test measurements turned tappet CP4.1



Overview of influences investigated:

3. Component influences of camshaft / housing

Component	Parameter variation		Picture
Camshaft axial clearance	0.17 mm	Basic case of the metering pump CP4.1	
	0.27 mm	Slight advantages compared to 0.03 mm	
	0.03 mm	see above	
Cam stroke	5.25 mm	The basic case	
	6 mm	No difference from 5.25 mm stroke (in inspections with CP4.2)	
Cylinder head assembly	Wear of screw travel in ZK	No impact of turning the ZK within the screw travel detected following the alignment run. Travel is about ± 1°	



EA11003EN-00276[10]

Overview of functional test measurements turned tappet CP4.1




Influencing factor: Engine speed



During first start-up of the pump, the tappet combination is aligned starting from an engine speed of > 3000 rpm (the pump test is started at 3,375 rpm)

UH_AngleOfRotation_cyl1_seq_material_nmax3375_le_NewInstalled_0000
OH_AngleOfRotation_cyl1_seq_material_nmax3375_le_NewInstalled_0000
UH_axial travel_seq_material_nmax3375_le_NewInstalled_0000
OH_axial travel_seq_material_nmax3375_le_NewInstalled_0000
pump speed_seq_material_nmax3375_le_NewInstalled_0000
Rail pressure_seq_material_nmax3375_le_NewInstalled_0000

Starting after installation procedure same as factory testing n_max = 3375 rpm



Diesel systems

11

Confidential | 6.01.2007 | © All rights reserved by Robert Bosch GmbH, also with regards to industrial property lights. We reserve any right to use such as right to serve and disclose



EA11003EN-00276[11]

Overview of functional test measurements turned tappet CP4.1



Influencing factor: Coiling direction of the spring

Direction of movement of the tappet at US and LS depends on the spring turn direction



0.4

Diesel systems

Confidential | 06.01.2007 |

0.2



0.6

0.8

EA11003EN-00276[12]

Overview of functional test measurements turned tappet CP4.1 Influencing factor: Roller stuck; detail Turned tappets in along US by about 15° and realigns along LS UH_AngleOfRotation_cyll_ramp_0to100_RollerStat_01_0000 BDC_cyl1ramp_0to100_Roller Stat_01_0000 Axial travel_ramp_0to100_RollerStat_01_0000 TDC_cyl1ramp_0to100_RollerStat_01_0000 Pump speed_ramp_0to100_RollerStat_01_0000 First start after installation Rail pressure_ramp_0to100_Roller Stat_01_0000 Turned tappet Cyl1 WITH MANOTON MANOTON TDC **BDC** 400 300 200 100 n_pump 8:3 -0.2 -0.1 -8:9 -200 Axial travel p_Rail 100 --100 26.0 28.0 26.5 27.0 27.5 Diesel systems (A) BOSCH 13 Confidential | 06.01.2007 | © All rights reserved by Robert Bosch GmbH, also

EA11003EN-00276[13]

Overview of functional test measurements turned tappet CP4.1



Summary:

- Turned tappets > 10° were found only with stuck roller
- With stuck roller and turned tappets between 20 and 30°, the tappet combination realigns in the pump combination LS
- When starting the pump, turned tappets up to max. 6° are measured after assembly. These turns are reduced to a maximum of 1.5° after engine speed increase to n = 3,375 rpm or above
- No turned tappets > 3° are found even when the pump starts without rail pressure and at maximum engine speed of 100 rpm

Further work:

- Inspection of turn tendency with stiff rollers (choice of friction coefficient testing and tests with screwdriver bench)
- Further measurements with disc between ZK and upper spring, possibly lubricated
- Evaluate the influencing parameters of roller length
- Draft criteria for the recognition of the alignment process in the factory test
- Instrumentation of a BMW series pump (drawings completed, parts used in manufacturing)

Diesel systems

(A) BOSCH

14

EA11003EN-00313[0]

From:

Non-responsive content removed

To:

CC:

Date: 08.01.2008 15:07:00

Subject: Re: 071117_Corrosion in pumps and injectors / NAR failures

Attachments: 791110 Protokoll CP4 Fachgespräch am 21 11 07 bei

791199 Einsatz Wasserabscheider für US-Markt.pdf

I wish all of you in the distribution list a Happy New Year!

Hello Non-responsive content removed

According to me, the important topic of "Water separator, currently without feedback" is not over yet. The fact that VW has no negative experience with the United States may be because no analyses were made (at least in the QA - see below).

We do not want to resort to the former VP37 analysis of 2002, right?

The Bosch numbers of 10 CoD / 1000 vehicles for a light-commercial vehicle manufacturer are still facts (see minutes of expert meeting on 11.21.07 - page 2, last point, and annex Bosch requirement) To rely on the hope of refueling these light-commercial vehicles at other gas pumps like our Q7 would Be careless in my opinion.

Also the Bosch WCF Test with 300-500 ppm of water content (instead of 1%), specified by you does not help us any further, but only delays the decision.

SECTION CONFIDENTIAL

- * Do you have analyses or concrete reports from VW?
- * What else should we from QA do to convince the TE (or the Company) to finally receive the feedback on water level? (Please do not tell that it's too late now)
- * Please discuss the issue again with Non-responsive content removed and Non-responsive content removed

>With best regards

Non-responsive content removed

>From: Non-responsive content removed

>Sent: Friday, 11.23.07 09:59:00
>To: Non-responsive content removed

>Subject: Re: 071117 Corrosion in pumps and injectors / NAR failures

> >Hello

>Sorry, but no one in the e-mail thread has analyzed US parts.

>Are there by any chance damage parts analyses from the US, for example at VWoA, etc.? (We All agree that there are complaints regarding the injection system)

>Does no one in the Group observe the US market???

>With best regards

Non-responsive content remove

Commercial Register No. /HRB Nr.: 100484

>Chairman of the Supervisory Board: Ferdinand Piëch >Board of Management: Martin Winterkorn (Chairman), Francisco J. Garcia Sanz, Jochem Heizmann, Horst Neumann, Hans Dieter Pötsch >Important note: The above information is automatically added to this e-mail. This addition does not constitute a representation that the content of this e-mail is legally relevant and/or is intended to be legally binding upon Volkswagen Sachsen GmbH. >Important Notice: The above information is automatically added to this e-mail. This addition does not constitute a representation that the content of this e-mail is legally relevant and/or is intended to be legally binding upon VOLKSWAGEN AG. > > Non-responsive content removed >From: >Sent: Thursday, 11.08.07 13:59:00 >To: Non-responsive content removed >Cc: >Subject: 071108 Corrosion in pumps and injectors / NAR failures >Hello >Regarding the issue of corrosion on diesel components, there are no failure figures, as analysis or RB were not performed at our place. >You can certainly obtain data from failed components, but such data are not meaningful with regard to corrosion. >Last in 2002, we analyzed 39 distributor injection pumps from the US market, wherein the main problem here was >the insufficient lubricity of fuel (29 failures) >Two distributor injection pumps were affected by corrosion at that time. >Otherwise, we can make a statement only about the market in We've got figures here. >If you need information, please contact me. >With best regards > >Volkswagen AG Salzgitter Non-responsive content removed V V V V > > >From: Non-responsive content removed >Sent: Wednesday,11.07.07 14:30:00 >To: Non-responsive content removed >Cc: >Subject: Re: Corrosion in pumps and injectors / NAR failures

EA11003EN-00313[2]

>38436 Wolfsburg Non-responsive content removed

```
EA11003EN-00313[4]
    Non-responsive content rem
    >
    >
    >
              Non-responsive content removed
    >From
    >Sent:
              Tuesday,11.06.07 9:52 AM
    >To:
              Non-responsive content removed
    >Cc:
    >Subject: Re: Corrosion in pumps and injectors / NAR failures
    >Hello
              has apparently done it already (see his mail - point 3).
    > I have requested specific statements from Bosch - I will get back to you.
    > < Message: Re: Corrosion in pumps and injectors / NAR failures >>
    >
    >Hello
    >Can VW QA support / confirm the omission of water separation step in the USA?
    >or agree to the facts 1-5 in the Annex?
    >With best regards
    >Non-responsive content rem
    >oved
    >AUDI AG
    >85045 Ingolstadt
    >Non-responsive content remo
    >ved
    >
    >http://www.audi.com
    >
    >
              Non-responsive content removed
    >From:
    >Sent:
               Tuesday,11.06.07 8:06 AM
    >To:
              Non-responsive content removed
    >Cc:
    >Subject: Re: Corrosion in pumps and injectors / NAR failures
    >
    >Hello,
    >I recommend inquiring with Non-responsive content removed
                                                   they have been active for years with TDI in series in
    the USA.
    >Best wishes,
```

EA11003EN-00313[5]

EA11003EN-00313[6]

>The system suppliers strongly recommend to switchover to water separation with indicator in combination! > >With best regards >Non-responsive content rem >oved >AUDI AG >85045 Ingolstadt >Non-responsive content remov >ed >http://www.audi.com >Domicile: Ingolstadt >Court of Registry: District Court of Ingolstadt >Commercial Register No.: 1 >Chairman of the Supervisory Board: Martin Winterkorn >Board of Management: Rupert Stadler (Vorsitzender/Chairman), Ulf Berkenhagen, Michael Dick, Frank Dreves, Axel Strotbek, Ralph Weyler, Werner Widuckel

>Important note: The above information is automatically added to this e-mail.

This addition does not constitute a representation that the content of this e-mail is legally relevant and/or is intended to be legally binding upon Volkswagen Sachsen GmbH.

>Important Notice: The above information is automatically added to this e-mail. This addition does not constitute a representation that the content of this e-mail is legally relevant and/or is intended to be legally binding upon AUDI AG.

Diesel Systems





Persons responsible Non-responsive content removed Tel
Non-responsive content removed

Fax
Non-responsive content remove

November 22, 2007 No. 791110

Protocol

Recipient

TN Audi: Non-responsive content removed

TN RB: Non-responsive content removed

Non-responsive content removed

Invited

Ion-responsive content removed

Participant:

Line:

Non-responsive co ntent removed

Protocol Organis.

Date/venue 21.11.2007, 11:00 - 1:30 p.m.,

, B12, middle meeting room.

Topic CP4 Specialist Meeting

OPL status

The latest outstanding points from the OPL were presented Further points will be added to the OPL from the specialist meetings and from the findings meeting.

Complete overview of RB continuous running tests

Bosch presented the current status of RB's examination of component continuous running tests. A fused flange bearing was found on a CP4.2 platform pump after a continuous running test. The pump is conditionally released. Other investigations are planned.

Two more pumps have passed the continuous running test with restrictions (wear on the shaft seal of the gear pump). It was agreed with Audi that the findings report for the gear pump will be presented.

The V8 pumps have passed the continuous running test without any striking features. There has been no new information from the US continuous running tests since the last specialist meeting. In relation to the smoothing and polished surfaces identified in a visual check on the camshaft. Bosch found that the test bench turns at a much slower speed. Bosch is checking at the moment to see whether a genuine standstill is possible on the test bench.

Bosch presented the latest status on the US VW continuous running tests. 8 pumps run on the test bench and 4 pumps in the vehicles themselves. At present we still lack the results from two vehicle continuous running tests. The worst rating in all other continuous running tests was 4. The rating levels are divided from 1 to 10. Rating 1 is very good. 10 is understood to indicate a total write-off.

It was found that the lubrication of the US fuel ranged from $345\mu m$ to $544\mu m$. This information indicates that the US fuel is better than originally expected, which is confirmed by the long running times of the US vehicles.

There are plans for another set of system continuous running tests with GDK570 at

Non-responsive content remo ved

Non-responsive content remove

Non-responsive content remove

Diesel Systems





Persons responsible Non-responsive content removed Tel

Non-responsive content remove d

Fax

Non-responsive content removed

November 22, 2007 No. 791110

Protocol

CP4 Specialist Meeting

Bosch. In the case of customer VW, the vehicle trial with pump CP4.1 is not yet complete. The pump is currently subject to a conditional release.

Pump failure status Non-responsive content remove

Bosch presented the latest status on the failures due to powertrain damage and reversed tappets. It is clear that the measures are taking effect because the number of failures is decreasing as the production volume rises. Audi wants a regular revision of the customer slides relating to failures.

Bosch also presented the current status in relation to the failure of splintered O-rings in the metering unit. Remedial measures were defined by Bosch and will be presented to the customer separately

Non-responsive content removed

Non-responsive content remo

Volume balance CP4.2H for V8 Non-responsive content rem

Bosch presented the initial situation and the current status from week WK 47. The measurement evaluation shows that Bosch is well within the upper range with 5-8 l/h reserve. Bosch is planning further checks and evaluations of the characteristic curves.

Non-responsive content removed

SECTION CONFIDETIAL

Engine trial CP4.2 with turned tappet

Bosch presented the current status of the engine trial with reversed cam follower. In relation to the damage, Bosch assumes that the torque of the high-pressure fuel pump was too great. Testing of the faulty pump continued on a torque stand and the result was compared with a new pump. In addition, Bosch planned to set up a torque measurement pump with sticking roller and to carry out torque measurements. A separate date is planned for the Dresden failures.

Termin: Ende 2007

Non-responsive content rem oved

Water separator (WA) (Use of WA system)

Audi is currently planning a water separator without filling sensor for use in the USA. Bosch requirement for markets in which fuel quality according to EN590 cannot be assured Bosch requires the use of a water separator with feedback (warning lamp). RB experience in the field in the USA indicates that customers with a water separator and filling sensor have no problems with corrosion, but that in the case of customers without a filling sensor there are

10 cases of damage per 1,000 vehicles.

From Audi's perspective, the wcf test at RB with 1% water is unrealistic and should be repeated with a water proportion of 300 ppm and a maximum of 500 ppm.

SECTION CONFIDETIAL

Non-responsive content remove



EA11003EN-00325[0]

From: Non-responsive content removed

To:

CC:

Date: 11/16/2009

11/16/2009, 10:00:00 AM

Subject: Re: Presentation from CP4 technical discussion

Attachments: 887 1239 water in fuel.pdf

.pdf

Wasserabscheidung im Kraftstoffsystem Aggregatekreis

For your information.

With best wishes



From: Non-responsive content removed

Sent: Friday, November 13, 2009, 4:40 PM

To: Non-responsive content removed

Cc: Subject:

Re: Presentation from CP4 technical discussion

Hello Mr.

I wasn't able to reach you by phone.

Do you mean dissolved water or "mixed" as a water-Diesel emulsion -> formed through free water in the vehicle tank and turbulence through the EFPs?

Dissolved water

- Lubricity and viscocity for dissolved water are comparable to pure Diesel fuel
- Filling station fuel contains water at the limit of solubility, since the tank bottom of the filling station always contains free water.

The proportion of dissolved water is dependent on various parameters (such as temperature, biodiesel).

Free water is created when operating conditions change (for example, operation vs. standstill, ...)

In addition, free water can enter the vehicle's fuel tank through a variety of methods (for example, through the tank ventilation, filling at a filling station that was recently refilled by a tank truck, which whirled up the water on the filling station tank bottom).

We had a expert presentation by Non-responsive content removed - see attachment - page 11/12 illustrates a mechanism of how free water arises in "normal" operation.

confirmed this process in a later presentation (see PPT presentation)

If free water (water droplets) reaches the tribological contact points (roller-cam and roller-roller support), then we - sometimes - have water substance parameters in which the viscosity/lubricity lie outside of what our pump can tolerate.

SECTION CONFIDENTIAL

Our pump was damaged with 500ppm water (approx. 70ppm dissolved, 430 ppm free water). 200 ppm water (70ppm dissolved, 130 ppm free water) did not do any apparent damage to the pump.

As you can see from the CP4 Robustness presentation, additional investigations are planned to

EA11003EN-00325[1]

gain an exact understanding of the influences and damage mechanisms (Page 25, further action).

In addition:

- We will discuss the fuel parameters on the world market on response content removed on 12/8/2009.
- There are activities on your side to assess the future use of a high-value water separator.

Please feel free to contact me if you have any other questions.

Best regards / mit freundlichen Grüßen

Non-responsive content rem

Robert Bosch GmbH

Non-responsive content removed

GERMANY www.bosch.com

Non-responsive content removed

Headquarters: Stuttgart, Court of Registry: Amtsgericht Stuttgart, HRB 14000; Chairman of the Supervisory Board: Hermann Scholl; Management: Franz Fehrenbach, Siegfried Dais; Bernd Bohr, Rudolf Colm, Volkmar Denner, Gerhard Kümmel, Wolfgang Malchow, Peter Marks,

Peter Tyroller; Uwe Raschke

From: Non-responsive content removed

Sent: Friday, November 13, 2009, 12:20 PM

To: Non-responsive content remov Cc: ed

Subject: Re: Presentation from CP4 technical discussion

Hello Non-responsive content removed

Have you examined how the lubricity of the Diesel responds dependent on the water content, for example, according to DIN EN ISO 12156-1?

With best wishes

Non-responsive content removed

AUDI AG

Non-responsive content removed

Domicile/Sitz: Ingolstadt

Court of Registry/Registergericht: Amtsgericht Ingolstadt

Commercial Register No./HRB Nr.: 1

Chairman of the Supervisory Board/Vorsitzender des Aufsichtsrats: Martin Winterkorn

Vorstand/Board of Management: Rupert Stadler (Vorsitzender/Chairman), Ulf Berkenhagen, Michael Dick, Frank Dreves, Peter Schwarzenbauer, Axel Strotbek, Werner Widuckel

Important note: The above information is automatically added to this e-mail. This addition does not constitute a representation that the content of this e-mail is legally relevant and/or is intended to be legally binding upon AUDI AG.

Wichtiger Hinweis: Die vorgenannten Angaben werden jeder E-Mail automatisch hinzugefügt und lassen keine Rückschlüsse auf den Rechtscharakter der E-Mail für AUDI AG zu.

From: Non-responsive content removed

Sent: Thursday, November 12, 2009, 6:13 PM

Non-responsive content removed

Subject: Re: Presentation from CP4 technical discussion

Dear

We have answered Mr. Non-responsive content removed

with regard to your mail.

Please feel free to contact us if you feel the need to discuss the matter further.

Sincerely

Robert Bosch GmbH

Non-responsive content removed

GERMANY www.bosch.com

Non-responsive content removed

Headquarters: Stuttgart, Court of Registry: Amtsgericht Stuttgart, HRB 14000; Chairman of the Supervisory Board: Hermann Scholl; Management: Franz Fehrenbach, Siegfried Dais; Bernd Bohr, Rudolf Colm, Volkmar Denner, Gerhard Kümmel, Wolfgang Malchow, Peter Marks, Peter Tyroller; Uwe Raschke

From: Non-responsive content removed

Sent: Wednesday, November 04, 2009, 7:28 PM

Non-responsive content removed

Subject: Re: Presentation from CP4 technical discussion

.. please provide the evidence for the hydrogen brittleness and stress corrosion cracking (laboratory analysis reports). Or remove the hypotheses - that is, delete them from the presentation!

With best wishes

Non-responsive content removed

From: Non-responsive content removed

Sent: Friday, October 30, 2009, 2:58 PM

Non-responsive content removed

Subject: Re: Presentation from CP4 technical discussion



I see only fatigue damage due to overload from the damage symptoms. Water could possibly reduce lubricity and/or result in earlier mixture friction, thus increasing susceptibility of damage. The idea that water results in hydrogen brittleness and stress corrosion cracking is not apparent in my eyes. We would need firm evidence of this, based on examination of the damage and surface of the break. I don't think this is likely.

On the subject of water induction in Diesel. The Diesel analysis maps worldwide show that in 99% of all cases, we have less than 200 ppm, in most cases not even 100 ppm H20, which does not result in any problems in tests. Is there really a need to harden up against higher water content?

Best wishes,

From:

Non-responsive content removed

Sent:


Friday, October 23, 2009, 10:06 AM

To: Non-responsive content removed

Subject: Re: Presentation from CP4 technical discussion

With best wishes





- > failure types and wear mechanisms caused by water
- why do we get corrosion?
 - anti-corrosive properties of Diesel fuel
 - undissolved water in the FIE, where does it come from?
- > corrosion in the field, what is the main driver?
 - water content compared to the U.S.
 - survey data of anti-corrosive properties and the U.S.
 - effect of corrosive attack and anti-corrosive properties
- wear
- hydrogen wear
- > summary and conclusion
- > the wcf corrosion test



Contents

- failure types and wear mechanisms caused by water
- > why do we get corrosion?
 - anti-corrosive properties of Diesel fuel
 - undissolved water in the FIE, where does it come from?
- > corrosion in the field, what is the main driver?
 - water content compared to the U.S.
 - survey data of anti-corrosive properties
 - effect of corrosive attack and anti-corrosive properties
- → wear
- > hydrogen wear
- > summary and conclusion
- > the wcf corrosion test



(A) BOSCH

Fuel Quality Aspects - Water

Failure types and wear mechanisms caused by water

→ Corrosion

undissolved water combined with insufficient anti-corrosive properties of the fuel leads to corrosion

→ Increased wear

in the presence of water a significant increased wear can be observed

→ Hydrogen wear

certain boundary conditions (depending on material, very high local compression) will lead to hydrogen wear in the presence of water



Contents

- → failure types and wear mechanisms caused by water
- why do we get corrosion?
 - anti-corrosive properties of Diesel fuel
 - undissolved water in the FIE, where does it come from?
- > corrosion in the field, what is the main driver?
 - water content compared to the U.S.
 - survey data of anti-corrosive properties
 and the U.S.
 - effect of corrosive attack and anti-corrosive properties
- → wear
- > hydrogen wear
- > summary and conclusion
- > the wcf corrosion test



(A) BOSCH

Fuel Quality Aspects - Water

Why do we get corrosion?


corrosion inside our FIE has 2 parents

- 1. free (=undissolved) water
- 2. bad anticorrosive properties of Diesel fuel

corrosion can lead to a direct malfunction or to a consecutive failure by rust particles

pump











Anti-corrosive properties of Diesel fuel


- anticorrosive properties of Diesel fuel can be determined and classified by the NACE TM0172 test (we apply NACE_mod with artificial sea water instead of distilled water) alternative standards are ASTM D665, ISO 7120
- → this test method was for a long time used in AAM Survey (unfortunately cancelled in 2008)
- Bosch has introduced this method to some surveys by SGS (e.g. U.S. Diesel & BioDiesel Survey summer 2006 special survey data of the world wide SGS fuel survey, ...)

Confidential

Robert Bosch GmbH 2008. All rights reserved, also regarding any disposal evidential property rights.




BOSCH



Anti-corrosive properties of Diesel fuel

Rating: per NACE TM0172



Fuel Quality Aspects - Water

Undissolved water, where does it come from?

undissolved water can pass the (non-ideal) water separator


or


undissolved water can be "generated inside the system"

- dissolved water passes the water separator at high fuel temperature
- after turning off the engine the water gets undissolved due to cooling down



(A) BOSCH





Undissolved water, where does it come from?

conclusion

- there is water slip even using an ideal water separator
- because of the higher water dissolving power of Biodiesel the water slip by temperature effect is much higher (the higher the Bx portion, the higher the water slip)
- → in addition with Biodiesel(blends) the efficiency of most water separators is dramatically reduced

the risk of having small amounts of undissolved water inside the system is inevitable



BOSCH

Fuel Quality Aspects - Water

- failure types and wear mechanisms caused by water
- > why do we get corrosion?
 - anti-corrosive properties of Diesel fuel
 - undissolved water in the FIE, where does it come from?
- corrosion in the field, what is the main driver?
 - water content compared to the U.S.
 - survey data of anti-corrosive properties
 and the U.S.
 - effect of corrosive attack and anti-corrosive properties
- → wear
- > hydrogen wear
- > summary and conclusion
- > the wcf corrosion test



Corrosion in the field, what is the main driver?

situation

- > the corrosion failure situation varies from market to market
- the U.S. is significantly more affected than


what is the difference in the field situation?


- the water content in fuels ex gas station in the U.S. and the comparable (see following slide)
- but the anticorrosive properties of U.S. fuel are different from fuel


15



(A) BOSCH







Effect of anti corrosive fuel properties in rig test with FIE

Common Rail Injector CRI2.2 1% diluted artificial sea water test duration: 168 h (7 days)

NACE = A

NACE = C

no corrosion even after 1 week in service



valve spring

valve ball seat













CRI destroyed by corrosion after short time

CRI out of spec. after 100h works hardly after 1 week










BOSCH

Fuel Quality Aspects - Water

Why was corrosion not that big issue in the past?

attempt of an answer

- oil lubricated system insert engine oil to the fuel. This improves the anticorrosive properties of the fuel (see next slide)
- oil lubricated systems have less contact with fuel
- fuel temperatures in the tank are lower with non-CR systems, therefore the described "water dissolving effect" is lower
- dissolving power of water was lower due to lower additive concentrations and no BioDiesel blends



Anti-corrosive properties of Diesel fuel

conclusion

- Sooner or later there is undissolved water inside the FIE
- Undissolved water leads to corrosion if the anticorrosive properties of the fuel are bad
- → The occurrence of corrosion depends on the probability of having undissolved water inside the FIE and on the probability distribution of the anti-corrosive properties of the refueling fuel mixture
- → The failure mode and robustness w/r/t corrosion depends on the components. This could be particles, seize up, plugging or fracture.



Corrosion in the field

outlook

- the field situation in the U.S. is tending to get improved by
 - Biodiesel blending leads to improved anti-corrosive properties until it is non-aged
 - U.S. Diesel currently uses higher additive rates due to the switch to ULSD and the consecutive need for lubricity improvement
 - U.S. mineral oil companies switch from acid based lubricity additives to ester based lubricity additives

however

anti-corrosive properties of fuel are not standardized in any fuel standard worldwide





(A) BOSCH

Fuel Quality Aspects - Water

- failure types and wear mechanisms caused by water
- > why do we get corrosion?
 - anti-corrosive properties of Diesel fuel
 - undissolved water in the FIE, where does it come from?
- > corrosion in the field, what is the main driver?
 - water content compared to the U.S.
 - survey data of anti-corrosive properties and the U.S.
 - effect of corrosive attack and anti-corrosive properties
- wear
- > hydrogen wear
- > summary and conclusion
- > the wcf corrosion test







Wear

- water in fuel causes strong wear at highly loaded tribological contacts
- after 30h in service with 1% water we find an immense wear compared to 500h in service without water
- even with a NACE=A fuel (no corrosion at all after 7 days in service with 1% water) we find after 30h higher than doubled wear compared to 500h in service without water
- water is an essential cause for immense wear in the FIE even if the system is not corroding due to excellent anti-corrosive properties of the fuel, water will lead to heavy wear we need a water separator to be sure






Fuel Quality Aspects - Water

- failure types and wear mechanisms caused by water
- > why do we get corrosion?
 - · anti-corrosive properties of Diesel fuel
 - undissolved water in the FIE, where does it come from?
- > corrosion in the field, what is the main driver?
 - water content compared to the U.S.
 - survey data of anti-corrosive properties
 - effect of corrosive attack and anti-corrosive properties
- → wear
- hydrogen wear
- > summary and conclusion
- > the wcf corrosion test



Hydrogen wear

- very high local compression intrudes atomic hydrogen to the steel. By increasing the volume at recombination into H₂ the structure of the steel is demolished (like freezing water)
- experience from rig tests:
 2% distilled water, damage after ca. 70h
 2% sea water, damage after ca. 20h
- could become important again for new roller-cam driven pumps



29

Confidential | | © Robert Boach GmbH 2008: All rights reserved, also regarding any dis



BOSCH

Fuel Quality Aspects - Water

- → failure types and wear mechanisms caused by water
- → why do we get corrosion?
 - anti-corrosive properties of Diesel fuel
 - · undissolved water in the FIE, where does it come from?
- → corrosion in the field, what is the main driver ?
 - water content compared to the U.S.
 - survey data of anti-corrosive properties and the U.S.
 - · effect of corrosive attack and anti-corrosive properties
- → wear
- → hydrogen wear
- > summary and conclusion
- > the wcf corrosion test



Summary and conclusion

- Fuel must be free of undissolved water to prevent the FIE from failure. This is not only due to corrosion, but also due to wear
- Fuel must contain enough anti-corrosion additives to prevent from corrosion. A water separator is necessary but not sufficient.
- The requirements to water separation rise because of increasing BioDiesel shares. Furthermore electric fuel pumps and jet pumps generate more stable emulsions with smaller water droplet size that reduce the separation efficiency.
- Fuel characteristics that influence water separation efficiency (interfacial tension IFT and separability MSEP) are important factors and shall be known market specific (activities just started)



(A) BOSCH

Fuel Quality Aspects - Water

- failure types and wear mechanisms caused by water
- > why do we get corrosion?
 - anti-corrosive properties of Diesel fuel
 - undissolved water in the FIE, where does it come from?
- > corrosion in the field, what is the main driver?
 - water content compared to the U.S.
 - survey data of anti-corrosive properties and the U.S.
 - effect of corrosive attack and anti-corrosive properties
- → wear
- > hydrogen wear
- > summary and conclusion
- the wcf corrosion test



wcf - corrosion test

Water Contaminated Fuel Test for Corrosion

Aim:

robustness analysis of FIE component reliability with respect to water contaminated fuel

Description:

- load-change profile idle, medium and high load
- fuel with medium anti-corrosive properties (NACE=C) and 1% (salty) water
- both indicator test for FIE comparison and release test with runtime targets based on experience

Diesel Systems





wcf - corrosion test

Running Time Target

- based on experience (no field problems known with CRI2)
- until 24 h:

full function of the product within TCD limits is given (within all tolerances)

- → until 72 h:
 - function is given. Significant differences to the TCD field tolerances are allowed, but no shutdown of the engine
 - no sticky or seized up machine elements
- → at test end (168 h):

no failures with severity 10 (in terms of FMEA)









ENTIRE PAGE CONFIDENTIAL






Water separation in the fuel system

EA11003NeCessity - Water separation in the fuel system Classification for critical countries





EA11003 Nec0338fly - Water separation in the fuel system Conditional suitability of current water separator



Premise: for each filling with 70 I fuel + 1 I free water

Vehicle consumption 7 I/100 km

Current water separator (93% acc. specifications from Bosch)

1 I water to 70 I fuel = 17 000 mg/kg

Mileage	Separated water	Water in the HP system
1000 km	0.93	0.07 l
10 000 km	9.3	0.71
30 000 km	27.9	2.1 l

DIN EN 590 limit 200 mg/kg

60 000 km	0.066	0.0051
00 000 KIII		0.0001

Despite the separator, over mileage of 1000 km the amount of water in the HP system exceeds 14 x the "limit" specified by Bosch!

The customer must empty the water reservoir (90 - 200 ml) every 100 - 200 km!

EA11003 Necessity - Water separation in the fuel system Conditional suitability of current water separator





D3 V6 TDI (HN-ZJ 217), part no. fuel filter 057 127 435 E (water reservoir 90 ml)

 Water reservoir in the filter compartment filled with 90 ml (filter paper does not dip into the water) Test:

 5871 km mileage Result:

- 21 ml free water in the filter compartment

D3 V8 TDI (HN-BW 628), part no. fuel filter 057 127 435 E (water reservoir 90 ml)

 Water reservoir in the filter compartment filled with 200 ml (filter paper dips into the water) Test 1:

 1550 km mileage Result 1:

- 47ml free water in the filter compartment

 Vehicle filled with 80 I fuel and + 2 I water Test 2:

 4463 km mileage (without adding more water) Result 2.1:

- 30 ml free water in the filter compartment


 7700 km mileage (without adding more water) Result 2.2:

- No free water in the tank

EA11003 Necessifly - Water separation in the fuel system Technical - physical limits




System-related free water despite separation



EA11003 Necessity - Water separation in the fuel system Technical - physical limits




Water absorption capability in the fuel system



EA11003 Waller Separation in the diesel fuel system



Water separation function



EA 1003 Neccessity - Water separation in the fuel system Technical - physical limits



Water separation with biodiesel

- -Biodiesel can dissolve considerably more water (factor 20) than diesel as per DIN EN 590
- With a biodiesel proportion of >5%, the separation efficiency of a water separator is reduced from 93 to 35%

An efficient, practical water separation is no longer provided in this scenario!

EA 1003 Necessity - Water separation in the fuel system Risk assessment and measures



Decision recommendation

Audi: No use of additional water separators for critical countries!

Volkswagen: Use of existing water separators for critical countries!

- -Establishment of water content up until which the damage-free condition of the HP system is guaranteed.
- Development of a high-performance water separator including sensor system Volkswagen/Audi. Use after proof of effectiveness and renewed damage analysis.
- Set up various series of tests with fuel containing water in the vehicle and components.

Steering committee VW 08.12.09

Strainer in front of intake valve

SECTION CONFIDETIAL

- VW requirement: ≤2 particles(200-400µm) in residual particle test
- Requirement cannot be met with clean practices at present
- RB recommendation: Introduction of sieve in front of intake valve
 - Possible SOP: 04.2010
- Intake valve strainer for pilot customers tested, SOP: 01.2010


Proposal for further procedure:


\rightarrow	Delivery of 2-4 pump samples with intake valve strainers	RB
\rightarrow	Vehicle cold climate tests in climatic chamber	VW
\rightarrow	Validation in winter tests	VW

Validation in winter tests



Steering committee VW 08.12.09








EA11003EN-00515[0]

Status Problems / Measures for CP 4.1 (4-cylinder) Cleanliness Concept CP4.1








Status Problems / Measures for CP 4.1 (4-cylinder) Cleanliness Concept CP4.1: **Summary**

ň.	
Problem	0 km nonstarters
Cause	Particles from pump jam non-return or intake valve => no pressure build-up when starting
Status	15 ppm 0km non-starter with CP4.1
Measures	- Continuous improvement through the identification of particle sources
	in the process chain (splinters map) and the measures derived from this - Introduction of intake valve sieve for USA pumps Optimization of met_ring unit sieve to prevent particle bypass 12,2010
	- Optimization of met ring unit sieve to prevent particle bypass - Development and evaluation of an optimized purging concept. Subsequent decision on the introduction of purging or comprehensive introduction of intake valve sieve. 12.2010 To be introduced in series by end of March 2011
	 Increased cleanliness requirements of new VW standard to be met by end of March 2011 Derogation for CP4.1 will be extended to end of March 2011






Status Problems / Measures for CP 4.1 (4-cylinder) Cleanliness Concept CP4.1: Cleanliness strategy (splinter map)








Status Problems / Measures for CP 4.1 (4-cylinder) Cleanliness Concept CP4.1: Intake valve sieve measure







Status Problems / Measures for CP 4.1 (4-cylinder) Cleanliness Concept CP4.1: **Optimization measure for metering unit sieve**_{Page 5}







ENTIRE PAGE CONFIDENTIAL ENTIRE PAGE CONFIDENTIAL

Pump type: 0 445 010 613 / 059 130 755 BC

IQIS: 230003103863

QMM32: No. 4A970

Pump DoM: 4/26/2010

Ser. no.: 04-0452


Failure reason: Mechanical fault,

Deformed, damaged (as per. customer description)

Results of analysis Standard finding:


- -Packaging OK, protective caps missing, approx. 5 ml fuel sample taken,
- onward and return flow supports visual check OK,
- NRV spring holders offset OK, NRV springs visual check R and L OK,
- deposit at NRV spring holders R and L
- Bubble Test OK.
- NoWe spin test OK,
- metering unit screws torque OK, deposit at metering unit adjustment disc,
- Functional test not OK. -> no excess current quantity,
- Overflow valve (OV) torque OK -> OV dismantled -> OV pistons jammed, OV with deposits,
- pump screw connections torque OK -> Pump dismantled:
- Vacuum test CH R and L OK.
- Deposit at pump parts, see pictures









A11003 CP4 field failure USA with 5649 m





Roller plunger, right






Roller plunger, left



Camshaft, GP



CP4 field failure USA with 5649 m



Excess current piston, strainerside



Excess current piston, lock-side




Excess current piston



Metering unit adjustment disc



Cylinder head, left, housing-side



Camshaft, housing bearing axial








Non-responsive content removed

Situation CW33/11

- > Field action HPP rebuild to anti-wear package 2 underway
 - stopped after 500 of 5,300 vehicles
 - 18,000 of 27,000 have been reequipped
 - 2,100 of 4,100 have been reequipped
 - 1,000 of 1,500 have been reequipped
- > Findings from CP4 Task Force Bosch-Audi are more comprehensive than late 2010
 - Failures / speed fluctuations Gen.1 engine >> Gen.2 and competition
 - Tension roller Gen.1 EU6 engine provides significant improvement
 - Correct position crankshaft/camshaft OP to HPP OP extremely important / toothed belt setting (partially omitted in CD – see Russia trip task force)
- ➤ Recommendation → see last 2 pages




Speed fluctuations V6-TDI engines



Note: Engine speed signal evaluation method is the same for all engine variants.



- High speed fluctuations when starting up the high-pressure fuel pump result in high rotations of the roller in operation.
- Major speed changes in operation of the roller have an impact on the hydrodynamic lubricant layer between roller and roller contact. → Torsional vibrations are an amplification factor for powertrain damage.



Q7 V6TDI Gen1 EU5

- 4294 sold cars
- 12 settlements in MIS12

Q7 V6TDI Gen1 EU6

- 2234 sold cars
- 1 settlement in MIS12
- → EU6 only 1/7 of settlements of EU5

Evaluation period / country:

FD ZP8: 06/2009 to 06/2010

Non-responsive content remove

Improvement from Gen1 EU5 to Gen1 EU6/Bin5 is achieved through different HPP belt tensioner.

V6TDI Gen2 with chain instead of belt drive for high-pressure fuel pump shows another further improvement of drive vibrations. 1 Gen2 powertrain fault known



AQUA rating HPP failures EU5 / EU6 Non-responsive content r and U.S.

Engine	Market	Sold	Random sample MY10+11	Rand. sample MY10	Rand. sample MY11	Failures to 12 MIS MY10 + 11	MY10 12 MIS	MY11 9 MIS
EU6 / Gen.1	Non-respon sive conte	528	274	140	134	0	0	0
EU5 / Gen.1	nt removed	14,813	9,483	5,700	3,783	59+6 units	1.06%	0.37%
EU6 / Gen.1		232	104	66	38	0	0	0
EU5 / Gen.1		2,046	1,411	822	589	5 + 0 units	0.61%	0
BIN5 / Gen.1		7,844	5,816	2,151	3,665	16+5 units	0.74%	0.40%


Summary: In _____, of 274 EU6 vehicles in the random sample, <u>none</u> has failed so far!

If we compare this with the EU5 failures in (MY10 + MY11), the same failure rates in MY10 would equal 1-2 failures in MY10 0-1 failures in MY11.


In some of 104 EU6 vehicles in the random sample, none has failed so far!

If we compare this with the EU5 failures in MY10 (MY10 + MY11), the same failure rates in MY10 would equal 0-1 failures in MY10.

In the **U.S.**, with the standard "stronger" EU6 belt tensioners, there were approx. 30% fewer failures in MY10 than in **EMB**, although the two fuel markets are not comparable.



Results: Speed fluctuation (p-p) pump =f (phasing position), @ 2440 rpm (3250 rpm engine)



Summary:

- . EU 6 tensioning roller in the center leads to approx. 250 rpm less rotation speed oscillations on the pump
- . Setup position 0 or minus 5 teeth found to be best variant
- . Misorientation of the pump at pump change leads to a stronger increase of torsional vibrations under certain conditions.

BOSCH

Vertraulich | | 02-08-2011 | 1918_EHC1 | © Robert Bosch GmbH 2011. Alle Rechte vorbehalten, auch bzgl. jeder Verfügung, Verwertung, Reproduktion, Bearbeitung. Weitergabe sowie für den Fall von Schutzrechtsammeldungen.



Speed variation of pump at approx. 3,300 rev/min engine or 2,500 U/min pump:

W19 with EU5 tension roller measured in **vehicle** / cold:1700 rev/min (2500 +/- 850)

W19 with EU5 tension roller measured in vehicle / hot: 1300 rev/min

W19 with EU6 tension roller measured in **vehicle** / cold:1320 rev/min (-22%)

W19 with EU6 tension roller measured in **vehicle** / hot: 1070 rev/min (-18%)

W36 with chain drive: 440 rev/min

W19 with EU5 tension roller measured on **engine**: 1040 rev/min

W19 with EU6 tension roller measured on **engine**: 800 rev/min (-23%)

W19 with EU5-SR – 3 teeth shifted on **engine**: 2150 rev/min (>> +100%)

W19 with EU6-SR – 2 teeth shifted on **engine**: 1770 rev/min (>> +100%)

- Measurements on vehicle show a similar effect, only approx. +/- 300; max. ca. 2100 rev/min
- Strong temperature influence, that is, cold engine is more critical than hot

Recommendation Non-responsive content removed

Series production

- Conversion of Gen.1 series to Euro 6 tension roller (B8/Q5 not PA; VW D1) underway

→ additional costs of are being negotiated

Normal damage case / repair case in CS

- Installation of stronger belt tensioners for Gen.1 EU5
- Optimization of TPI and repair guide for belt tensioner, installation of HPP / toothed belt, pre-fueling and tank content in coordination with Non-responsive content removed.

OP system

- Introduction of a "red note" in the HPP packaging with important information regarding pump replacement (installation of HPP / toothed belt, fuel prefilling, tank contents) in standard CS languages

Non-responsive content removed English, Non-responsive content removed



Recommendation Non-responsive content removed

- Field action 23G7 Non-responsive content removed
- 1.All vehicles that have not been touched yet, should be converted with changed instructions (**change belt tensioner**, **clear note on HPP OP conversion**)
- 2.Sample inspection on > 25 vehicles per market with executed 23G7 action to see whether setting of HPP OP is correct
- 3. Sample inspection on > 25 mass-produced engines to see whether setting of HPP OP is OK; vehicle GS-2 was configured 180° incorrectly (note: check of CS position position not described in guidelines until 2011)
- 4. Depending on failure rate, "wrong position HPP OP" market-specific
 - Failure < 1-3%

no action


Failure > 1-3%

- \rightarrow
- Carry out new action (see item 5)
- 5.New action to check crankshaft/camshaft/HPP OP (only vehicles with old instructions) and if not OK,
 - install stronger belt tensioner and configure HPP OP or
 - (only configure HPP OT)
- Vehicles outside field action 23G7 Non-responsive content removed
 - Do not carry out any activities / optimized repair in case of damage (see Page 8).

EA11@P4N-R6809t Flange 2009.051, 2009.052

Change number

Product CP4



DS-002 045 748 DS-002 044 074

	n	
Bosch no.	Custo	mer no.
	2nd follow- up	6/15/2010
ew product releases for	<u> </u>	41.0

Ne Audi 0 445 010 611 059 130 755 BB Audi 0 445 010 613 059 130 755 BC Audi 0 445 010 631 059 130 755 AN Audi 0 445 010 632 059 130 755 AK

Change slips [n.n.] for Audi 0 445 010 619

Audi 0 445 010 620 Audi 0 445 010 624

05A 130 755 C 057 130 755 AD 057 130 755 AC

Date


11/26/2009

Presentati on

First

presentatio

EA11@P⊈N-Robust Flange 2009.051, 2009.052



Bosch no. Customer no.

Change	slip	DS-002045748	for

VW	0 445 010 507	03L 130 755
VW	0 445 010 514	03L 130 755 D
VW	0 445 010 526	03L 130 755 L
VW	0 445 010 529	03L 130 755 AC
VW	0 445 010 5xx	03L 130 755 AA

Change slips [n.n.] for

VW	0 445 010 508	03L 130 755 A
VW	0 445 010 520	03L 130 755 J
VW	0 445 010 523	03L 130 755 F
VW	0 445 010 527	03L 130 755 M
VW	0 445 010 5xx	03L 130 755 A



EA11 CP4N Robûlet Flange 2009.051, 2009.052

3. **Description** Introduction of robust flange

3.1 Reason

Increase robustness for Q improvement, improved pump performance (CP4 for 2200/2500bar) require new centering concept. This robustness increase is to be transferred to all CP4s (new standard). Measure to achieve the agreed series prices

3.2 Customer advantage, benefit Increased robustness




EA11 CP4N-R68081 Flange 2009.051, 2009.052


4. Details: Overview of changes

- 4.1 Press assembly in screw level
- 4.2 Screw connection
- 4.3 Cam support surface
- 4.4 Bushing

Series flange




Robust flange





EA11@P4N-R68@≰∦ Flange 2009.051, 2009.052

4.1 Press assembly in screw level



Press assembly to support lateral forces moved to outside to separator level of flange/housing components




EA11@P4N-R6805t Flange 2009.051, 2009.052

Series flange

Support for lateral forces 000 through a) Press assembly "internal" force flow through thin-walled groove (notch radius) Share: ~40% b) Friction coefficient of screw connector Share:~ 60%

Robust flange



Support for lateral forces through


a) Press assembly outside at force level

Share: ~90%

b) Friction coefficient of screw connector

Share ~10%

- Direct support for lateral forces through press assembly, moving proportional force
- -Reduction of assembly tension due to thin-walled groove and notch radius
- Greater pressing area due to larger diameter of press assembly






Robust flange

EA11 CP4N-R650St Flange 2009.051, 2009.052

4.2 Screw connection

Series flange



- Reduction of screw factor possible through changed distribution of force absorption
- Burr formation reduced (CP4 cleanliness initiative)
- Increased stiffness of press assembly through closed screw recesses




EA11 CP4N-R6893 Flange 2009.051, 2009.052

4.3 Cam support surface: Material

Series flange



Robust flange



Cross-grooves for bearing **lubrication**

Support surface and material like pump housing


(Si content: 12.0 – 12.8%)





EA11@P4N-R68@St Flange 2009.051, 2009.052

4.4 Bushing



Force transmission through customer drivetrain dominant, bearing largely loaded on customer side, supporting bearing length unchanged




EA11 ① P4-01 Robust Flange 2009.051, 2009.052

4.5 Process chain

Blank: New production process and supplier

• Flange machining: Flange redesign requires modification of production

process





EA110CF型→ Hothist Flange 2009.051, 2009.052

5. Bosch validation

5.0 Tests

- Extreme pressure tests bushing radial Done

- Extreme pressure tests support surface axial Done

- Press-in test flange Done

- Screw test flange Done

5.1 Function

- Exite bearing simulations Done

EA110CFAN- Flowist Flange 2009.051, 2009.052

5.2 Flange blank (I/II)

Material tests

P-FMEA

No. RPZ > 125

Done

4

- → Assessment of possible faults:
 - Porosity
 - Crack formation

Protective measures:

- 1.) 100% leak test for finished product
- 2.) 100% pressure loss test after "Flange machining". (temporary)
- 3.) In-process sampling (machining) at flange blank supplier



EA110CF41- Hothist Flange 2009.051, 2009.052

5.2 Flange blank (II/II)

EMPB Done

Machining capability Done

2-day production Done

Process audit Done

Degree of fulfillment. 86% (internal RB requirement: 85%)

Post-audit (verify effectiveness of defined measures) Open

5.3 External purchase of flange bushing

No process change for released bushing SNR







EA1100∰4N-0Hotst Flange 2009.051, 2009.052

5.4 Screw



Process audit (result: 91%)

Done

5.5 Flange machining with pressed-in bushing

P-FMEA "Robust flange"

Done



No. RPZ > 125

None



Machining capability

Done

Internal 2-day production

Done

RB internal release Customer fit-in Cmk: 2.7

06/2010

Bushing roundness Cmk: 2.3

Pump fit-in Cmk: 2.3





EA110CFAN- Flowist Flange 2009.051, 2009.052

5.6 Housing machining


P-FMEA "Housing" Done

No. RPZ > 125

Machining capability Done

RB internal release 06/2010

Flange fit-in Cmk: 2.3





EA1100F4N-0F556157 Flange 2009.051, 2009.052

5.7 Product assembly

P-FMEA "Product assembly" Done

No. RPZ > 125 None

2-day production prod. assembly (press flange into housing + screw) Done

RB internal release Done

EA110CP4N- দিউপ্রাজ্য Flange 2009.051, 2009.052

5.8 Endurance / durability testing Boso	5.8	Endurance /	/ durability	testing	Bosc
---	-----	-------------	--------------	---------	------

5.8.1 Pre-trial

2 x 2000h Program CR Done

2 x 2000h Program CR Done

2 x 100h HFRR-QALT with GDK570 Done

1 x 210h t-HALT at nominal pressure Done

5.8.2 Baseline validation

2x150h PER Done

2x2000h System PER Done

2x350T MSS 780h Done

1x350h n-HALT Done

1x3D Vibration Done



EA110CFQ1- Plothist Flange 2009.051, 2009.052

5.8.3 Broad validation

4 x 2000h program CR with GDK 570 Done

Done

4 x 1000h constant CR with GDK 570 Done

2 x 100h HFRR- QALT with GDK 650 Done

2 x 150h p- HALT with GDK 570 Done Done

1 x 3D Vibration test 500h 07/2010

EA110CP型-中心的数据 Flange 2009.051, 2009.052

6. Customer validation: VW 10 x 0 445 B21 116_13 in Wk 4

(2 x GDV, 1 x Veh. CR, 1 x engine CR)

AUDI 7 x 0 445 B20 252_06 in Wk6

1 returned to EHP so far:

- Motor CR (PZD+OVL) 892 h

7. Launch date 08/2010



EA11 ให้อัชนร์เรียลnge – VW Engine Endurance Run

Status: 6/14/2010

Customer return VW R4 2.0L

→ Pump: 0 445 B21 116-13

CP4.1XS-398-2x6-REC-3.3-1.95-MT4.2

Flange version: 0 445 D20 AK6-00 Die-cast,

Bushing w/o friction washer

Continuous run. conditions: Engine CR 892h, engine number 00000070

Audi C/ inline 125 KW EN 590,

Exhaust standard EU5 LL

n_nom = 4500 min-1, p_nom = 1800 bar

Pump durability test
081–4672, VW R4 2.0 EU5 2010-CP4-0426

(DNA 3923)



EA110Rebust@lange – VW Engine Endurance Run

Status: 6/14/2010

Pump:

Fct. OK

SB OK

081 - 4672

Runtime: 892h




View of flange with axial support surface segments



Detailed view of axial support surface segments



View of flange with WDR



Detailed view of support segment






EA110R6bust€ lange – VW Engine Endurance Run


Status: 6/14/2010



View of flange with bushing



Housing fit-in for robust flange



View of flange segments on face

Pump:

081 - 4672

Runtime: 892h

Fct. OK


SB OK



EA110CP4 ជា ក្រី១២ust Flange 2009.051, 2009.052

8. Capacity management


- 8.1 Capacity expansion of blank
 - Capacity expansion for first supplier (B)
 - → Second supplier from E/2011 (C)





EA110CP4 ជា ក្រី១២ust Flange 2009.051, 2009.052

8.2 Planned capacity expansion of flange machining





EA1100∰4N-0Flothist Flange 2009.051, 2009.052

9. Risk: If the defined validation program is completed

successfully, only a low implementation risk

is expected.

10. Alternatives:

EA110℃P4⊶ Robust Flange 2009.051, 2009.052

11. Customer approval:

Appr	oval grante	ed					
	Date	Department	Sign	ature		Remark	
vw							
Audi							
Open items / requirements				Responsib	le	Completion deadline	


Open items / requirements	Responsible	Completion deadline

Status of the SV measures in KVS (design data management system)

- SW measures have been implemented for all VW vehicles (Touareg, Phaeton) with CP4.2-HDPs
 - → Data protection at AUDI
 - → Non-responsive content removed
- No CP4.2-HPPs are installed in other VW vehicles CP4.2 covered!
- In all VW vehicles with inline electric fuel pumps, this lies immediately before the CP4.1-HPP, considerably shorter pressure build-up times versus AUDI fuel supply (assessment complete)
 - → short line, low volume for pressure build-up
 - → Difference at AUDI: 5 x longer line and filter volumes
- Maintenance of the SW measures means a 100% doubling of the data volumes for all VW cars
 - → Measures only implemented where required, e.g. NAR
- from (WK10/2012) the SW package agreed between VW and AUDI which goes far beyond the measures agreed up to now (see Slides 2-8).

Overview:

- Starting volume flow
- Volume flow in the event of a stop and restart
- Volume flow offset depending on the battery voltage
- 4. Negative recuperation recommendation
- 5. Start delay
- 6. Control with initialization (KI15) and in the over-run
- 7. Control after terminal 15 off (pump over-run)





1. Starting volume flow

Non-responsive cont requirement:

- A higher fuel volume flow is needed at the start than supplied by the currently need-based control unit.
- The current Audi solution of applying this volume flow depending on the rotational speed has the disadvantage that the pump with the higher volume current is also controlled when the engine is switched off and no dependency on the temperature of the fuel is indicated.

Agreed solution:

- At the start (query start status which is set approx. 100ms before the starter is turned), an applicable volume flow is specified via an indicator field depending on the rotational speed and injection volume.
- The feeding of the increased volume flow when the engine is switched off is prevented as this would be audibly discernible.
- With an applicable delay time, the volume flow can also optionally be supplied after the engine start.
- Absolute value depending on the fuel temperature as a maximum selection.

2. Volume flow in the event of a stop and restart



requirement:

- At high fuel temperatures, it can be necessary for the pump in the stop phase or when restarting from the stop phase to be operated at a specific volume flow.
- Only one constant volume flow is specified in the current software structure for the event of a stop and restart in each case.

Agreed solution:

- The volume flows should be determined depending on the temperature of the fuel.
- If the volume flow is applied at 0 l/h for low fuel temperatures, the supply can be shut off completely in the stop phase or when restarting.
- Absolute value as a function of the fuel temperature
- Duration as a function of the fuel temperature
- Volume flow in stop phase 30 l/h

3. Volume flow offset depending on the battery voltage



Non-responsive content remov requirement:

• At low voltages, e.g. brought about by recuperation, high rotational speeds may not longer be able to be regulated by the fuel pump unit.

Agreed solution:

- An offset must be defined for the volume flow requirement depending on the injection volume and the
 rotational speed. This offset must be weighted with a factor which is calculated from the fuel temperature and
 injection volume.
- This offset replaces the previous base value.

4. Negative recuperation recommendation (DC-capable)

13th September 2011



requirement:

• At low voltages, high rotation speeds may no longer be able to be regulated by the fuel pump unit. One problem is that a higher fuel volume flow needs to be pumped at a high engine load, while at the same time the voltage through the recuperation is reduced.

Agreed solution:

- The motor control unit already issues a recommendation to lower the voltage above the applicable engine output. This negative recuperation recommendation must be extended such that the voltage is likewise not reduced above a configurable sampling ratio.
- A filter or a debouncing is to be provided in order to prevent a negative recuperation recommendation from being issued with a short-term increase of the sample ratio (positive load step).

Note:

- A negative recuperation recommendations must be agreed with the project.
- · Debouncing via dead time

5. Negative recuperation recommendation (DC-capable)

13th September 2011



Non-responsive content remover requirement:

At high fuel temperatures, it may be necessary to control the fuel pump before starting the engine.

Agreed solution:

- In vehicles with automatic start, the start control is effected by the engine control unit. A delay is already implemented for the start ignition after actuation of the ZAS or ZAT. The existing interface is to be used to delay the start even when control of the fuel pump is required.
- The delay time must be dependent on the fuel temperature.
- The delay of the engine start should only take with the actuation of the ZAS or ZAT when there is a start release (clutch or brake pedal pressed and gear lever on automatic gearbox in position P or N).
- As the pre-glow time tends to be longer than the start delay time for the fuel pump, the timing should be set up so that the start delay also expires for the fuel pump when the pre-glow time ends.

6. Negative recuperation recommendation (DC-capable)

requirement:

• The fuel continues to heat up in the over-run phase of the engine. The high-pressure pump is hot in the start and is not cooled down sufficiently by the hot fuel.

Engine development



Engine test center • Drive electronics • Engine management • Diesel engine development • Vehicle integration drive • Gearbox development • Petrol engine development

Agreed solution:

- To provide sufficient cooling and lubrication to the HPP in the hot start too, the electric fuel pump must also be initialized as of T. 15 ON and/or a door contact. The status must be kept active for an applicable run time depending on the fuel temperature and a volume flow must be issued in accordance with the fuel temperature. The functionality must be able to be deactivated/activated via a switch The functionality must be able to be deactivated/activated when the tank is empty, in the event of faults in the fuel system, and for the production above a configurable kilometer threshold.
- In order to cool down the HPP again, also in the over-run phase, and it must be possible to initialize the electric fuel pump in the over-run phase. In this case, the run time and the fuel volume flow must be configurable according to the temperature. The initialization of the electric fuel pump in the over-run phase must be deactivated depending on the cooling air control (PWM). This functionality must be able to be deactivated/activated via a switch. The functionality must be able to be deactivated when the tank is empty, in the event of faults in the fuel system, and for the production above a configurable kilometer threshold.
 → Over-run for 2 s

7. Negative recuperation recommendation (DC-capable)

Non-responsive content remover requirement

Engine development

Engine test center • Drive electronics • Engine management • Diesel engine development • Vehicle integration drive • Gearbox development • Petrol engine development




- When turning off the engine (terminal 15 OFF), the engine still has an empty running speed at least and it takes up to 1.7 seconds until the engine is actually stationary. In this state, however, the fuel pump was already switched off because the pump goes into the control logic of the terminal 15 status.
- The result is a fall in the fuel pressure in front of the high-pressure pump when the engine/high-pressure pump is turning by itself.

Agreed solution:


• In the event that terminal 15 drops out, the pump is still operated further for an applicable time however not beyond the time when the engine comes to a standstill.



EA11003EN-01544[1]







Further development of C3 layer system for C4 roller support: C3.1

Compare properties C2.1 and C3 in CP4 roller support

			Wear re	sistance		Friction coefficient
Layer	Surface roughness	Damaging effect of layer particles	Vibration stress	Impact stress	Cavitation	
C2.1	Substrate + indi- vidual layer faults	0	0	0	0	+
C3	Substrate + process-linked droplets	٠	+	+	+	0

Non-responsive content removed


© Robert Bosch GmbH 2009. All rights reserved, including all use,

Further development of C3 layer system for C4 roller support: C3.1

Comparison of C2.1 and C3 series version with C3.1


Layer structure

C2.1 layer




- C1 protective layer with constant hardness
- Transition layer
- Adhesive layer 1
- Carbon 1 layer (=C1)
- Carbon 2 layer (=C2)

C3 layer



- C1 protective layer with hardness gradient
- C2 layer
- Adhesive layer 2
- Adhesive layer 1
- Adhesive layer 2

C3.1 layer



- C1 layer with constant hardness
- C2 layer
- Adhesive layer 2



Further development of C3 layer system for C4 roller support: C3.1

Expected properties of C3.1 layer

- Increased wear protection compared to C2.1 thanks to thin "C2" layer for
 - impact stress
 - Vibration/sliding stress
 - Cavitation attack
- Friction properties in "critical" media favorable like C2.1
- → Lower number of droplets compared to C3 through thinner C2 layer
 - Lower risk of droplet outbreaks during operation
- Layer particles less harmful than C3 particles
- Robust adhesiveness like C3
- "C2.1 layer with C3 base as safety reserve"

1. Change no.

DS-002 036 219


[AUDI..611,..619,..620,..624 Eu5]

DS-002 036 221

[AUDI ..613 BIN5]

0 445 010 624

2. Product:



Bosch No. Custo	om	er	no
-----------------	----	----	----

0 445 010 611	[Audi]
0 445 010 613	[Audi]
0 445 010 619	[Audi]
0 445 010 620	[Audi]

[Audi]



3. Description

Introduction of optimized roller tappet

Polished tappet body

Cylindrical press-fit assembly increased pressing dimension


3.1 Base

Improvement and stabilization of the press-fit assembly tappet body / tappet body through: Omission of tolerance restriction Omission of the settling behavior of manganese phosphate coating Increase in pressing force

> Reduction of side roller start-up



4. Details





4.1 Omission of manganese phosphate coating on the tappet body

advatages:


- No tolerance restriction in the press-fit assembly through varying coating thicknesses

Omission of the settling behavior of manganese phosphate over its service life, i.e. the extrusion force of the roller support after continuous running time is about 30 - 40% higher without coating than with coating

Lower coefficient of friction between the tappet body and the housing, thus improved inlet behavior, reduced wear and lower risk of particles


Comparison of tappet body & housing after 2,000 h ensurance run: no difference in the wear pattern





Machining marks still visible after DL






Wear area



Tribology test for determining coefficient of friction




Evaluation:

Lower coefficient of friction with lower scattering at the same time Better wear behavior


= Efficiency & robustness increase

with manganese phosphate



Considerable abrasion

without manganese phosphate



Slight incipient abrasion





5. Validation of Bosch

5.0 Function

Tribology tests

FEM calculations

Conducting trial mounting of roller tappet

Functional tests

settled

settled


settled

5.1. Quality Assurance

FMEA settled pRBFM settled settled

5.2 Durability / continuous runnings

Pump continuous runnings (a total of ≈ 32,000 h) completed







ÄAS DS-002036219, -36221 CP4 roller tappet introduction of optimized press-fit assembly

6. Validation of customer

RB proposal not required

With optimized press-fit assembly at sample pumps delivered to AUDI

8 x CP4 20/2 for W19 Bin5/EU6 ...755AL(February 2009, 0 445 B20 169_20)

239 x CP4 18/2 for W36 D4 ...755AN (0 445 B20 246_x)

207 x CP4 20/2 for W36 Q7 ...755Ak (0 445 B20 249_x)

10 x CP4 20/2 for W37 ...755AP (0 445 B20 252_01 & _02)

19 x CP4 22/2 for W37 ...755AQ (0 445 B20 252_03)

7. Launch date 12.01.2009

8. Risk no risk

9. Alternatives none

10. Remark

Optimized press-fit assembly is in series production at other customers



CR high-pressure fuel pump CP4

Annex 1.1



Agenda, 28/10/2005, VW Presentation CP4


- Platform
- → Design
- Rating
- → Trial
- Drive
- Pump construction for VW, schedule



CR high-pressure fuel pump CP4

Annex 1.2







Characteristics

- Internally supported radial piston pump
- 1 or 2-plunger pump (V90°)
- Multiple cam and roller tappet
- Aluminum housing (no HP duct)
- Steel cylinder heads with integr. HP valve
- 1 or 2 HP lines to rail (1 piece/2 piece)
- Suction-side metering via UM
- EFP and integrated, mechanical presupply pump (CP) possible
- Clockwise/anticlockwise rotation
- Synchronous feeding with 4, 6, 8-cyl.
- Oriented engine-mounted installation














CP4 Platform




Applications:	 PC -, LD-, MD - engines with 3, 4, 5, 6 and 8 cylinder, potential up to 12 cylinder
Platform:	 2 - plunger pump incl. housing flange-Ø = 50 mm, pitch circle-Ø = 105 mm 1 - plunger pump incl. housing
Application parameter:	 pump speedi = 1/2, 3/4, 1/1, 3/2, (2/1) plunger lift plunger-Ø (only pressure amplified FIE)
Options:	mechanical feed pumpUS-fuel



CP4 Modular Concept

Annex 1.6









CP4 Overview - Technical Information CP4.2 (1)

Annex 1.7












CP4 Overview - Technical Information CP4.2 (2)

Annex 1.8








CP4 Overview - Technical Information CP4.2 (3)

Annex 1.9










CP4 Overview - Technical Information CP4.1

Annex 1.10





Diesel Systems




flange

connector




CP4.1 with mech. FP (CP)







Comparison common rail high-pressure fuel pumps Annex 1.12 Non-responsive content removed **CP4.1** Ratio i [-] 6.0 Pitch [mm] Piston diameter 6.5 [mm] [mm³/rev] 398 Feed rate with mech. FP 4,500 (i=1) [rpm] **Engine speed** n_{max} 4,800 (i=1) [rpm] without mech. FP > 80 % Efficiency [-] @ 1000/min, 80 °C with mech. FP 07/2008 **Customer SOP-**09/2006 without mech. FP -Pressure 1,600 [bar] 1,800 2,000 Pressure curve [kg] Weight without mech. FP 3.0 Picture Animation




















Evaluation matrix common rail high-pressure fuel pumps for VW R4 2.0 1 "low"



		Non-responsive content removed	CP4.1	
System pressure	1600 bar		X	
	1800 bar		Χ	
Ratio			1	
max. power 130 kV	V		+	
Emissions package	EU5		+	
	US07		+	
Efficiency			+	
Installation space/package			0	
integr. FP			From 7/2008	
Maturity			0 (43,000 h)	
Availability (adjusted pumps)	Construction stages		Yes	
	Series		Yes	Deadline

^{*} previous series experience: 6 years





CP4 Overview - Performance

Annex 1.16



Technical Data

Drive ratio $0.5 \setminus 0.75 \setminus 1.0$

Max. delivery rates $\leq 90/135/180 \text{ l/h (CP4.2)}$

Max. rated speed 4.500 1/min (w. mech. FP)

High idle 5.000 1/min

Cool- / lubrication quantity typical 50 l/h at rated speed

Pump inlet temperature ≤ 70°C, short time 80° (100h), 90°C (100h)

Inlet pressure 4 ... 6* bar_{rel} with EKP

0.5 ...1.0 bar_{abs} with mech. feed pump

Back flow pressure 0.6 ...1.8 bar_{abs}

*preliminary


CP4 Efficency

Annex 1.17



Comparison CP4-2/995 vs. Non-responsive content removed

Volumetric efficiency @ different inlet temperatures








CP4 efficiency

Annex 1.18



Efficiency comparison: CP4.2 vs. competitor








CP4 - Rail pressure diagram 2 cam lobes

Annex 1.19






Pump speed [rpm]




CP4 - rail pressure diagram (double cams)


















CP4 quality and customer benefits

Annex 1.22



General:

- New generation of CR HP pumps with high pump frequency
- Significantly improved hydraulic efficiency
- lower power losses
- Additional quantity and pressure potential

Drive

- Roller tappet (roll contact) instead of polygon (sliding contact)
- Avoidance of mixed friction allows greater Hertzian stress
- Cam profile optimization allows improved feed rate

High-pressure/low-pressure seal points:

Reduction of high-pressure seal points:

Non-responsive content removed CP4.1: 2 pieces CP4.2: 4 pieces

Reduction of low-pressure seal points:

Non-responsive content removed CP4: 1 locking ball





CP4 trial Annex 1.23



2 standards of testing

Standard tests

(constant load- and programendurance tests)

Long-term testing with practice orientated standard operating conditions in specification

Target: finishing tests without failure B10-design validation




HAL tests

(= Highly Accelerated Lifetime Tests)


operating conditions increased out of specification

Target: forcing failures











Sample complaints CP4

Annex 1.25



Customer failures as at 14/10/05

Pump type	Cause of failure	Sample level	Quantity
CP4.1S	Oldham worn out	B1.1 B3	4 1
CP4.1S	Roller / cam wear, bearing melted	B1.1	1
CP4.1S	Chip in the intake valve seal seat (source: UM flange reworking)	B1.1	1
CP4.2	Oldham broken (dihedron and clutch piece) roller surface fatigue, surface roughness NOK	A1.1	1
CP4.2H	Overflow valve claw plate broken	A1.2	1

Quantity of customer pumps delivered: 350



Sample complaints CP4

Annex 1.26



Failures* as at 14/10/05


Pump type	Customers	Customers	Remark
	CP4.1	CP4.2	
Sample level			
A1	-1-	2 / 10	CP4.1 no A1 sample delivered
B0/B1	6 / 74	0 / 64	Last sand casting versions
B2	-1-	0 / 15	CP4.1 no B2 sample delivered
В3	1 / 100	0 / 87	With customer since WK 20/05

^{*} No. of failures / no. of delivered pumps total: 350 pumps



CP4 status durability test with RB





Optimization point	Solution approaches
Start-up on face of roller on tappet body	 Roller support: Minimization of incorrect positioning roller axis to cam axis Further parameter optimizations * *
Durability of roller / cam drive	Grinding parameter optimization on roller support and cam track * * Improved C coating on roller support **
Durability of flange and housing bearing	 Modified LP circuit * Improved bearing material (PEEK) * Anhebung Grundspiel um 5µm bei beiden Lagern * Diameter of housing bearing 22mm (previously 20mm) * Stiffening of housing / camshaft *
Durability of Oldham coupling	Application upper limit 1,800 bar

^{*} Implemented from C0

^{**} Feasibility in C1 sample

CP4 drive damage



- Main error in internal trials
 - Start-up on face of roller/tappet body
 - Wear roll/cam track
- Main causes
 - Incorrect positioning/angle between roller and cam axis
 - Start-up and locking of roller in tappet body
- Measures
 - Task force to investigate cause of damage and take remedial actions set up
 - Cause of damage understood
 - Immediate measures implemented in CO sample
 - Further measures under investigation, implementation in C1 sample as appropriate



CP4 status durability test with RB

Annex 1.29



Status durability text CP4

Program durability test, 2,000 h

- 1,800 bar (CP4.1/CP4.2) 22 test objects / 3 passed
- 2,000 bar (CP4.1/CP4.2) 5 test objects / 3 passed

Constant durability test (specification limits) 1,000 h

- 1,800 bar (CP4.1/CP4.2) 2 test objects / 2 passed
- 2,000 bar (CP4.1/CP4.2) 3 test objects / 1 passed

HALT * (n-, p-, T-, FL-)

- 1,800 bar (CP4.1/CP4.2) 16 test objects / 10 passed
- 2,000 bar testing in progress

We reserve all rights of disposal such as copying and passing on to third parties.



^{*} HALT = highly accelerated lifetime test

CP4 status durability test with RB

Annex 1.30



Start / stop durability test

1 test object / 1 passed (CP4.2)

1,000 h, 300,000 cycles (50% with pressure maintenance function)

Total running time

• CP4.1 1,800 bar: 43,000 b B sample

• CP4.2 1,800 bar: 25,000 h B sample

• CP4.x 2,000 bar: 8,000 h A sample



CP4 trial

Annex 1.31



Positive highlights of HAL testing with A, B samples:

- → HAL durability test successfully passed up to 2,750 bar
- → HAL durability test successfully passed up to 6,000 rpm
- → First positive HAL results with poor-lubricity fuel

HALT: Highly Accelerated Lifetime Tests)

Objectives:

- high reliability in series production
- utilize CP4 future potential




CP4 drive torque

Annex 1.32



Measurements with EFP version, cone drive





CP4 drive torque

Annex 1.33



Main factor influencing the maximum torque of the pump drive is the pump installation:

- → lowest values with cone direct drive (chain, toothed belt, gear)
- → Increase up to factor 3 with Oldham or loose entrainment drives

Torque measurements:

- → Measurements available with 6, 6.75 and 7.5 mm cam stroke
- → 4.5 and 5.25 mm not yet sampled, will follow later as not critical




CP4 for VW R4

Annex 1.34



Schedule




VW K Concept V1 BStV100 V2 BStV200 PV Pre-series 0 Pilot series

Bosch A A sample B B sample C C sample D D sample E ISIR S RB-SOP

Remark: Order 5 months before delivery










CP4 for VW R4 Annex 1.35

Assessment of VW-spec. characteristics as at 26/10/

Characteristics (differ from pilot application)	Implementation (K: concept engine WK46/05, M: sample delivery, S: series)
Height reduction required to protect pedestrians with 2 corresponding dimensions:	
 Reduction of flange material in mounting bore area from r. 12 mm to r. 9.5 mm UM (radial): Height reduction from 118 mm to 112 mm (based on pump center) 	 → K: not possible due to delivery deadline → M, S: Feasibility through cast modification or reworking being tested (strength test nec. WK46) → K, M: Reduction to 115 mm is being implemented → S: Feasibility of 115 mm being tested → General: < 115 mm not possible (redesign of housing required) ➡ Implementing both maximum requirements might not be necessary, being tested by VW






CP4 for VW R4 Annex 1.36

Assessment of VW-spec. characteristics as at 26/10/

3. HP outlet: Orientation VW-specific 30-90° from the transverse axis	→ K, M, S: 90° (to rear) being implemented as agreed
4. Shaft: Cone with external thread	→ K, M, S: being implemented
5. Housing: Mounting bore with thread instead of through hole	→ K: remains through hole→ M, S: being implemented
6. Direction of rotation: clockwise	 → K, M, S: being implemented → General: Functional effects are being tested

- meeting the space requirement is highly probable, further details to follow (WK46).
- → There are significant differences bet. VW-spec. CP4 and the pilot user.
- The implementation of characteristic 1 determines the sample lead time in particular; delivery category 3 (90 days) still to be scheduled for reworking or cast modification.
- → Pumps for the concept engine in 12/05 will possess all characteristics listed except points 1 and 5.







CP4 - outlook for 4-cyl. engines

Annex 1.37



Pump construction for VW 1.6 1/2.0 1 "low"& "high": HP pumps:

→ RB proposal (synchronous HP feeding):

1.6 1: CP4.1, ratio i=1, cone drive

2.0 1: CP4.1, ratio i=1, cone drive

LP pumps:

→ RB proposal: CP4 in EFP version

pot. combined with engine-mounted

presupply pump

alternative: CP4 with integrated mech. gear pump

(available from 07/2008)

Note: Pump selection based on estimated delivery rate values and other framework conditions, as no official VW values are available

Diesel Systems





DS VMU standard lead times 2 Half-year '05

Annex 1.38

	High-pressure pump						Rail			
	1H	N2	3	3NH	4	N5	WFR	LWR2	LWR3/4	
Cat.1	40	55	40	50	60	70	35	40	50	
Cat.2	50	65	50	65	75	80	45	50	60	
Cat.3	70	95	70	80	90	90	50	60	75	

		CR injector (car)			CR injector (CV)				DENOX	нсі
	2	3.0 3.1	3.2 3.2	3.3	2	3	4.1	4.2	1, 2, car	
Cat.1	35	45	50	50	45	45	75	70	35	35
Cat.2	45	50	60	60	55	55	80	80	45	45
Cat.3	50	55	70	70	70	75	115	90	65	60

Lead time in working days (80 % - completion)
Capacity-related deviations are possible

Definition of contract categories: see page 2



<u> </u>		
Category 1	Repeat order; check drawings and	
	parts lists no technical changes	
Category 2	Variant on existing base; blank or cast	
	available as output component	
Category 3	Redesign; significant deviations from the	
	previous delivery, check installation	
	situation; procurement of new tools and/or	
	output components,	



Cure status AWP (Anti Wear Package), standardization CP4.1

Overview of AWP (Anti Wear Package) sample features (B1)

High-pressure piston: Lateral surface: C coating

Piston base: reduced roughness, C coating

Roller support: Area of contact of the piston base support surface increased and

roughness reduced

Roller: DMO5, finer granularity

Tip: Area of contact increased and roughness reduced

Camshaft: Tolerance restriction of roughness and area of contact of the cam

track

Spring plate: Anti-friction paint coating

Housing - tappet hole: Increased strength through heat treatment

Standardization CP4.1

Bosch scenario: => EU5 first start-up with basic pump

=> US07 first start-up with AWP pump

=> Unit pump from 09.01 (depending on the decision Non-responsive content removed

VW objective: => Unit pump CP4.1 at first start-up US07 from 08.01

Author:

Date: 04.10.2006

File name: AWP (Anti Wear Package) status, Standardized CP4.1

Page:1/1



About AWP B1-pattern characteristics

Tappet hole housing

Increased strength through heat treatment

Spring plate

Anti-friction coating

Roller


DMO5, finer granularity

Roller tip

Area of contact of the surface increased and roughness reduced

Camshaft

Tolerance restriction of roughness and area of contact of the cam track



High-pressure piston

C-coating lateral surface

High-pressure piston


Roughness of piston base reduced and C-coating

Roller support

Area of contact of the surface (piston base support) increased and roughness reduced

Roller support

Roughness reduced





CP4 for VW

Robustness Packages (RPx)

RP0

Task: - Reduce wear and tear (especially avoidance of piston seizure)

Content: - red. C coating on the pump piston

- One-piece carbide coupling (pump with mechanical gear wheel feed pump)

RP1 Task:

- Increasing the load capacity of hydrodynamic lubricating film between the roller / roller support at a lower

viscosity and poorer lubricity

- Reserve robustness for temporary overshooting of specification

Content: - Reduction in the roughness of roller supports, opt. Surface

- Safe prevention of metal chips (process C2)

- Reduction of the roller clearance to the roller support

RP1+ Task: like RP1, additional reduction of wear and cavitation in the tappet hole in conjunction with poorly

lubricating and low-boiling fuels, improved load distribution in the roller support

Content: -like RP1, but C3.1 coating

> -Reduction in the radial clearance of tappet body to housing -Reduction in the axial clearance of piston base to roller support

-Reduced form tolerance of the roller hole in the roller support in conjunction with a radius of 70,000


RP2 task:

- CP4.2: Optimized temperature balance (only for CP4.2 rotating clockwise with EFP)

- change in position of the inlet hole in the powertrain compartment Content:

- robust flange (enlarged overflow cross-section)





EA11003EN-01859[1]

Drivetrain Damage Diesel High-Pressure Fuel Pump CP4.2

Summary of activities:

- Current cases of damage 799 bills worldwide, of which 428 in ___ see Appendix (drivetrain damage in approx. 90% of cases)
- Information from Task Force:
 - Striking features of fuel (FAME acidity) due to increase from approx. 3% to 7% biodiesel in in 2009
 - different from Non-responsive content remov (cam path smoothed, shaft seal worn, etc.)
 - Individual C coating batches feature high failure rates
- Failure hypotheses from Bosch for market:
 - Tribochemical wear: Oxidation of camshaft → Oxide adhesion from cam roller → Smoothing of camshaft → Reduction in frictional coefficient (counter to aim of higher frictional coefficient for cam roller / cams)
 - Deposits from biodiesel: Deposits → Increased frictional coefficient cam roller/roller shoe → cam roller sluggish in roller shoe → slippage between cam roller / cam → Wear + material abrasion
 - Microorganisms in fuel: e.g. algae → Acidity due to metabolic products → Corrosion of am roller + cam shaft → Increased frictional coefficient + Surface damage → Wear + Material fatigue

Other steps:

- Continuation of detailed fuel and damaged pump analysis
- Evaluation of all failure hypotheses / Ishikawa diagram
- Attempt to reproduce damage mechanism on test bench
- Comparison of production parameters CP4.2 (Q recordings) without indication of deviations favoring damage > further analyses for previously unspecified parameters (particularly C coating; component geometries)
- Current status regarding introduction of robustness package (planned SOP July 2010): Production + measurement of individual pump parts First test bench results with critical fuel end January 2010

EA11003EN-01863[0]


Task Force – Anti Wear Packages @ CP4


Non-responsive content removed

- 1) Field situation
- 2) Comparison of injection systems
- 3) (Anti wear package 1 (RP1))
- 4) Anti wear package 2 (RP2)
- Non-responsi ve content r emoved

pump

6) road test pump with RP2








EA11003EN-01863[1]


1) Field situation

Non-responsive content removed





EATIOF4 Task Force Audi, Failures





EATTOTASKOFORCE - CP4

Italy:

- Pumps from 2008/9 suffered preliminary damage in the line early 2009
- Preliminary damage level 20% from analysis of good pumps

Therefore, fuel-related "on-site actions" will only deliver limited findings for further cause analysis, if at all.

Questions:

Why don't the competition have any problems in Why is VW CP4.1 lower than Audi CP4.1?

Measures:

- Back measuring: 25 new presupply pumps 25 low-pressure systems
- Check distribution impact and possible aging statistically for the LP system
- Targeted tests with aged biofuel




EATTOTASKOFOTCE - Anti Wear Packages @ CP4

Examples of **aged fuel** on the intake valve (CP4.1














4VW4VW354 DoM Sep 09 5,358 km

With drivetrain damage











EATTOTASKOFORGE - CP4



- 1. Continued high failure rates, even with 2010 production date
- 2. High rates of repeated failures in certain areas of Non-responsive content?

Questions:

Why do pumps with RP1 measures handle our Q and why do pumps fail so quickly in (300 km)

Why don't any other customers in have problems

Measures:

On-site action needed to understand problem.

Quickly bring RP2 pumps to Non-responsive content in repeat case



EA11003EN-01863[6]

1) Comparison of injection systems

Non-responsive content removed





EATION CP4.2 - FIE


	W19 E (1800 I	70.70.70.70.70.70.70.70.70.70.70.70.70.7		Competition (1800 bar)		Impact on drivetrain damage W19 / competition		
Rotation direction	RL		RL		LL		LL temperature advantage	
Piston diameter [mm]	6.5		6.5		6.5		No influence in the context of exactness of temperature measurement	
Cam stroke [mm]	4.85		5.625		5.25			
Tip circle [mm]	47	47		47				
HP delivery rate [l/h]	81	-	80		78		No impact	
Drive torque [Nm]	min.	max.	min.	max.	min.	max.	Check impact on torque and bending force on W19 temperature compared	
-Engine	-7	30	-25	57	-13	40	to competition W36	
-PB (@ 4500 rpm, 1800 bar)	-8	29	-10	35	-9	33		
Transverse force on camshaft [kN]	0.4	2.4	~0	2.5	1	4		
OV	OV ide	ntical in a	all CP4 E	No impact				
MU	MT 2.0 120 l/h		MT4.2 220 l/h		MT 4.2 220 l/h		No impact, all engines max. 120 l/h at WB	



EA11003EN 0786368 Trayal of cam profiles and torque/forces on the pump


Portrayal chain drive W36/W37

Pump drive W19



EA11003EN 07863[9] trayal of cam profiles and torque/forces on the pump








CP 4.2 Portrayal of cam profiles and torque/forces on the pump

Measurements W19/W36/competition: Cam profile results: 4500 rpm/s, full load mm 6543 5,25 mm competition, fillet Cam pitch 4.85 mm W19, fillet Only 1 cam! mm/s 400 200 C1000 -200 -400 -600 m/s2 200 100 B1000 -100 Nm 60 40 Pump 20 torque -20 0.5 UT /..OT 0.0 Only 1 cam! -0.5 kN 3 2 1



0



270

Turning angle Grad

360

180

225


135

90

45

EA110CSE 4.2 Portrayal of cam profiles and torque/forces on the pump

Measurements W19/W36/competition: Cam profile results: 4500 rpm/s, full load




Confidential Non-responsive content removed



EA11003EN-01863[12]

4) Anti wear package 2 (RP2)

Non-responsive content removed





EATTOTESK FOTCE - Anti Wear Packages @ CP4

Anti wear package 2

Task

Reduce local temperature in right roller support to level of CP4.1 and CP4.2 CCW

Measures

- Opt. arrangement of inlet & return position (exchange inlet/return connections)
- Introduce robust flange (increase overflow profiles)

Result

Reduction of temperature in lubrication gap by 24°C (from 136°C to 111°C @ 80l/h @ 70°C inlet) in Qold

This is the same level as CP4.1

Test of Qold2 endurance runs at R.B. passed

Pumps delivered to Audi for trial


Serial start planned from week 45



Confidential Non-responsive content removed

EA110Task Force – Anti Wear Packages @ CP4

Anti wear package 2



Fuel goes directly to return

CP4.2 EFP cw Audi W19


Fuel is circulated once

CP4.2-EKP cw RP2 for Audi W19



EATTOTESK FOTCE - Anti Wear Packages @ CP4

CP4.2 Audi W19: Roller support temperature as f(coolant/lubricant volume) Robust flange, n=1000 rpm; p_Rail= 2300 bar; T_All=40°C






EATTOTESK FOTCE - Anti Wear Packages @ CP4

Anti wear package RP2

Proof of effectiveness through overload test (150 h with low viscosity)





EA110Task Force - CP4

RP2 impact:

Reduction of temperature on right roller support has 2 effects:

- With lower temperature, lubrication gap has higher reduction
- of deposit formation, up to full prevention
 - Better inflow in lubrication gap
 - Tilting movement of roller in start case enables establishment of hydrodynamics

If flushing quantity is reduced greatly, positive impact of RP2 is overcompensated




Confidential Non-responsive content removed

EA11003EN-01863[18]

4) Diagnosis of Non-responsive content removed pump Non-responsive content removed

Non-responsive content removed







EA1100 PA028 Audi Non-responsive content re


2010-CP4_0644

Failed pump field Non-responsive content delivery date unknown


0 445 010 611; DoM: 100121 BPT 1190; Chg-Index 05; 059 130 755 AH

















EA110Task Force - CP4

Pump shows typical drivetrain damage
Right roller support destroyed first by abrasive wear
Left roller support killed later (turned tappet)

Abrasive wear matches low viscosity in Non-responsive content re

Right roller support: first deal with roller support temperature




EA11003EN-01863[21]

4) Diagnosis Non-responsive content

pump road test with RP2

Non-responsive content removed








EA110CF4.28A336di


2010-CP4_0643 ed Test RP2 with 43,189km W36 0445 B20 321_01; 000005 BPT 4000; ENT 301 181 KL


Slight smoothing tracks



















EA110CP4.28AUdi


2010-CP4_0643 Non-responsive content rem oved Test RP2 with 43,189km W36 0445 B20 321_01; 000005 BPT 4000; ENT 301 181 KL
















EA110Task Force - CP4


Pump with RP2 in very good condition after road test

- 1. Minimal deposits visible in roller support
- 2.Rollers like new
- 3. Slight deposits on spring plate

Summary:

Best result of all road tests with 6 cyl. (6 CRs evaluated)





Product Quality Forum

- "power loss" of high-pressure fuel pump, Touareg V6 TDI

Problem: Powertrain damage to Bosch high-pressure fuel pumps CP4.2

> 2135 cases of damage worldwide in low-quality fuel regions (1,150 in 284 in i





- aged biofuel in conjunction with high proportion of fuel additives

- low fuel viscosity and poor lubricity

Analysis:



- High temp on the right roller support leads to deposits formed from decomposition of the additives
- Deposits impede formation of the lubricant film between roller and roller support
- "Flat spots" cause powertrain damage due to stationary roller of the pump
- Reduction in the frequency of damage by 80% from MY08 to MY10 through measures packages



- Aforementioned fuel properties lead to accelerated component wear
- High temperature on the right roller support leads to further reduction of fuel viscosity
- Abrasive wear due to thin lubricant film between roller and roller supports

Measures:

Robustness package 1 (RP1) Since CW 15/2010

- including C2 instead of C3 coating on roller support; narrowing roller clearance in series for roller support; roller shape optimization
- Increasing lubricant film thickness between roller and roller
- support 8 failures in Non-responsive content removed to date

Robustness package 2 (RP2)


- Reduction in temperature at the right roller support by Opt. Inflow and return lines of the highpressure fuel pump
- No deposit formation and further lubricant film thickness
- Effectiveness proven in Raff test

Series RP 2 starting from CW 45/2010 for all V6 TDI Dates:




Product Quality Forum

- "power loss" of high-pressure fuel pump, Touareg V6 TDI



EA11003EN-02085[0]





Status of Bosch CP4.2 High-Pressure Fuel Pump in V6TDI Wk38/2011

Non-responsive content removed

EA11003EN-02085[1]

Status of Bosch CP4.2 high-pressure fuel pump V6TDI Gen1

Roller support
Roller
Camshaft
DI Gen1

► Complaint:

Drivetrain damage to Bosch CP4.2 high-pressure fuel pump in V6TDI Gen1

Affected models:

B8, C6, Q5, Q7, Touareg, Touareg NF, Cayenne E1

Initial situation/Late 2007: Affected period: Transition from Bosch CP1h high-pressure fuel pump to CP4.2 for V6TDI <u>Gen1</u> Pressure increase from 1600bar to 1800/2000bar - Audi pilot customer for CP4.2

Note: CP1h in V6TDI Gen1 also OK in countries with poor fuel quality

Affected markets:

Countries with poor fuel quality especially Non-responsive content removed

Info: U.S. higher failure rate than

Known cases of damage:

3800 Audi and 2300 VW

Number of units in field:

320,000 Audi and 80,000 VW (esp. Touareg, 10% of which in



Analysis/cause:

Wear due to insufficient lubricating film thickness between roller and roller support

- 1.) Poor production quality at Bosch in MY 2008 and 2009 80% of all cases of damage involve MY 2008 and 2009
- 2.) Lack of robustness of CP4.2 for low-viscosity fuels
- 3.) Coolingof CP4.2dependent on rotational direction/ TCD does not indicate a preferred direction
- 4.) CP4.2 demonstrates insufficient venting behavior
- 5.) Sensitivity of CP4.2 to drive influences (torsional vibrations)

 No information on drive conditions in the TCD

Non-responsive content removed

Aged biodiesel

Low viscosity with high kerosene and gasoline content

EA11003EN-02085[2]

Status of Bosch CP4.2 high-pressure fuel pump V6TDI Gen1

Actions implemented: Measures from package 1&2 Eliminate quality problems in Bosch

productionMP1(Wk30/2008) MP2(Wk30/2009) / After

introduction of MP1 and MP2, failure figures in

n-responsive content removed OK

Anti wear package 1 (RP1) Increase of CP4.2 robustness against low

fuel viscosity (Wk15/2010)

Anti wear package 2 (RP2) Optimized cooling on right CP4.2 runner

(Wk45/2010)

Optimized EFP activation Improved CP4.2 cooling during engine start (early 2011)

Planned measures: Optimized belt tensioner Reduce torsional vibrations on

CP4.2 (only for Gen1 Wk45/2011)

Self-venting CP4.2 Introduction of CP4.2 with optimized

venting capability - for V6TDI Gen1 only Cust

(possible use from Wk45/2012)

Development in field:

