

V2432

Report Numbers: TRC-95-V005

Rear Impact Full-Scale Crash Testing  
for Upgrade of  
FMVSS 301 Test Procedure

Deformable Impactor into Rear of  
1996 Suzuki Sidekick  
at 80 kph with 70% Right Side Overlap  
TRC Test Number: 960314

Prepared by:  
Transportation Research Center Inc.  
10820 State Route 347  
East Liberty, OH 43319



April 11, 1996

Final Report

Prepared for:  
John A. Volpe National Transportation Systems Center  
Vehicle Crashworthiness Division, DTS-74  
Kendall Square  
Cambridge, MA 02142-1093

This Final Test Report was prepared for the U.S. Department of Transportation, National Highway Traffic Safety Administration, under Contract No. DTRS57-95-C-00011.

This publication is distributed by the U. S. Department of Transportation, National Highway Traffic Safety Administration, in the interest of information exchange. The opinions, findings, and conclusions expressed in this publication are those of the author(s) and not necessarily those of the Department of Transportation or the National Highway Traffic Safety Administration. The United States Government assumes no liability for its contents or use thereof. If trade or manufacturers' names or products are mentioned, it is only because they are considered essential to the object of the publication and should not be construed as an endorsement. The United States Government does not endorse products or manufacturers.

Report Prepared By:

Craig A. Markusic, P.E.  
Craig A. Markusic, Senior Project Engineer  
Transportation Research Center Inc.

Date 4/12/96

Report Approved By:

Jeffery W. Sankey  
Jeffery W. Sankey, Manager, Project Operations  
Transportation Research Center Inc.

Date 4/12/96

Final Report Accepted By:

\_\_\_\_\_  
Contracting Officer's Technical Representative (COTR),  
NHTSA, Office of Vehicle Safety Compliance

Date \_\_\_\_\_

<p>1. Report No.  TRC-95-V005</p>	<p>2. Government Accession No.</p>	<p>3. Recipient's Catalog No.</p>	
<p>4. Title and Subtitle Final Report of Deformable Impactor into Rear of 1996 Suzuki Sidekick with 70% Right Side Overlap</p>		<p>5. Report Date April 11, 1996</p>	<p>6. Performing Organization Code TRC</p>
<p>7. Author(s) C. A. Markusic, Senior Project Engineer, TRC</p>		<p>8. Performing Organization Report No. TRC-95-V005</p>	
<p>9. Performing Organization Name and Address Transportation Research Center Inc. 10820 State Route 347 East Liberty, OH 43319</p>		<p>10. Work Unit No. (TRAIS)</p>	<p>11. Contract or Grant No. DTRS57-95-C-00011</p>
<p>12. Sponsoring Agency Name and Address John A. Volpe National Transportation Systems Center Vehicle Crashworthiness Division, DTS-74 Kendall Square Cambridge, MA 02142-1093</p>		<p>13. Type of Report and Period Covered Final Report March - April 1996</p>	
<p>14. Sponsoring Agency Code NEF-30</p>		<p>15. Supplemental Notes</p>	
<p>16. Abstract</p> <p>An 80 kph deformable impactor rear crash test with 70% overlap was conducted on a 1996 Suzuki Sidekick at Transportation Research Center Inc. on March 14, 1996. This test was conducted to determine vehicle and occupant response in the rear 70% right side overlap test mode. The test vehicle's weight was 1370 kg. The impactor's velocity was 81.6 kph. The impactor's weight was 1344 kg. The vehicle's maximum crush was 828 millimeters. The ambient temperature was 17° C.</p> <p>The driver's Head Injury Criteria (HIC) was 389. The driver's chest maximum resultant acceleration with three (3) milliseconds minimum duration was 39.5 g. The driver's chest maximum deflection was 3 mm. The driver's left and right femur maximum axial forces were 2168 N and 1664 N, respectively.</p> <p>The passenger's HIC was 569. The passenger's chest maximum resultant acceleration with three (3) milliseconds minimum duration was 39.7 g. The passenger's chest maximum deflection was 7 mm. The passenger's left and right femur maximum axial forces were 2409 N and 1759 N, respectively.</p>			
<p>17. Key Words  Rear Impact Full Scale Crash Testing for Upgrade of FMVSS 301 Test Procedure</p>		<p>18. Distribution Statement Copies of this report are available from: NHTSA Technical Reference Division Nassif Building, Room 5108 400 Seventh Street, S.W. Washington, DC 20590</p>	
<p>19. Security Classif. (of this report) Unclassified</p>	<p>20. Security Classif. (of this page) Unclassified</p>	<p>21. Number of Pages 244</p>	<p>22. Price</p>


METRIC CONVERSION FACTORS

Approximate Conversions to Metric Measures

Symbol	When You Know	Multiply by	To Find	Symbol
<b>LENGTH</b>				
in	inches	*2.5	centimeters	cm
ft	feet	30	centimeters	m
yd	yards	0.9	meters	km
mi	miles	1.6	kilometers	
<b>AREA</b>				
in <sup>2</sup>	square inches	6.5	square centimeters	cm <sup>2</sup>
ft <sup>2</sup>	square feet	0.09	square meters	m <sup>2</sup>
yd <sup>2</sup>	square yards	0.8	square meters	km <sup>2</sup>
mi <sup>2</sup>	square miles	2.6	square kilometers	ha
	acres	0.4	hectares	
<b>MASS (weight)</b>				
oz	ounces	28	grams	g
lb	pounds	0.45	kilograms	kg
	short tons (2000 lb)	0.9	tonnes	t
<b>VOLUME</b>				
tsp	teaspoons	5	milliliters	ml
Tbsp	tablespoons	15	milliliters	ml
fl oz	fluid ounces	30	milliliters	l
c	cups	0.24	liters	
pt	pints	0.47	liters	
qt	quarts	0.95	liters	
gal	gallons	3.8	liters	l
ft <sup>3</sup>	cubic feet	0.03	cubic meters	m <sup>3</sup>
yd <sup>3</sup>	cubic yards	0.76	cubic meters	m <sup>3</sup>
<b>TEMPERATURE (exact)</b>				
°F	Fahrenheit temperature	5/9 (after subtracting 32)	Celsius temperature	°C

Approximate Conversions from Metric Measures

Symbol	When You Know	Multiply by	To Find	Symbol
<b>LENGTH</b>				
mm	millimeters	0.04	inches	in
cm	centimeters	0.4	inches	in
m	meters	3.3	feet	ft
km	kilometers	1.1	yards	yd
		0.6	miles	mi
<b>AREA</b>				
cm <sup>2</sup>	square centimeters	0.16	square inches	in <sup>2</sup>
m <sup>2</sup>	square meters	1.2	square yards	yd <sup>2</sup>
km <sup>2</sup>	square kilometers	0.4	square miles	mi <sup>2</sup>
ha	hectares (10,000 m <sup>2</sup> )	2.5	acres	
<b>MASS (weight)</b>				
g	grams	0.035	ounces	oz
kg	kilograms	2.2	pounds	lb
t	tonnes (1000 kg)	1.1	short tons	
<b>VOLUME</b>				
ml	milliliters	0.03	fluid ounces	fl oz
l	liters	2.1	pints	pt
l	liters	1.06	quarts	qt
l	liters	0.26	gallons	gal
m <sup>3</sup>	cubic meters	36	cubic feet	ft <sup>3</sup>
m <sup>3</sup>	cubic meters	1.3	cubic yards	yd <sup>3</sup>
<b>TEMPERATURE (exact)</b>				
°C	Celsius temperature	9/5 (then add 32)	Fahrenheit temperature	°F



\*1 in = 2.54 (exactly). For other exact conversions and more detailed tables, see NBS Misc. Publ. 286, Units of Weights and Measures, Price \$2.25, SD Catalog No. C13.1-0-286.



## Table of Contents

<u>Section</u>	<u>Description</u>	<u>Page</u>
1.0	Purpose and Test Procedure	1
2.0	Rear Deformable Barrier Impact Test Summary	5
3.0	FMVSS 301 Data	16
4.0	Vehicle, Moving Deformable Barrier, Occupant, and Camera Measurements	20
Appendix A	Photographs	A-1
Appendix B	Data Plots	B-1
Appendix C	Dummy Calibration Information	C-1
Appendix D	Miscellaneous Test Information	D-1

List of Tables

<u>Number</u>	<u>Description</u>	<u>Page</u>
1	Crash Test Summary	8
2	Test Vehicle Information	10
3	Post-Impact Data	13
4	Dummy Injury Criteria	17
5	Fuel System Data	18
6	FMVSS 301 Post-Impact Test Data	19
7	Impacted Vehicle Measurements	22
8	Vehicle Measurements	23
9	Test Vehicle Rear Profile Data	25
10	Pre- and Post-Test Position of Vehicle Accelerometer Mounting Locations	28
11	Moving Deformable Barrier Face Static Crush	29
12	Dummy Measurement Data for Front Seat Occupants	32
13	Motion Picture Camera Locations	35

List of Figures

<u>Number</u>	<u>Description</u>	<u>Page</u>
1	Impact Velocity Measurement System	14
2	Accident Investigation Division Data	15
3	Pre-test and Post-test Measurement Points	21
4	Vehicle Target Locations	24
5	Vehicle Accelerometer Mounting Locations	27
6	Moving Deformable Barrier Face Crush	30
7	Dummy Measurement Locations for Front Seat Occupants	31
8	Seat Belt Positioning Data	33
9	Camera Positions	34

## List of Photographs

<u>Description</u>	<u>Figure</u>
Pre-Test Front View	A-1
Pre-Test Left Front Three-Quarter View	A-2
Post-Test Left Front Three-Quarter View	A-3
Pre-Test Left Side View	A-4
Post-Test Left Side View	A-5
Pre-Test Left Rear Three-Quarter View	A-6
Post-Test Left Rear Three-Quarter View	A-7
Pre-Test Rear View	A-8
Post-Test Rear View	A-9
Pre-Test Right Rear Three-Quarter View	A-10
Post-Test Right Rear Three-Quarter View	A-11
Pre-Test Right Side View	A-12
Post-Test Right Side View	A-13
Pre-Test Right Front Three-Quarter View	A-14
Post-Test Right Front Three-Quarter View	A-15
Pre-Test Front Underbody View	A-16
Post-Test Front Underbody View	A-17
Pre-Test Right Front Underbody View	A-18
Post-Test Right Front Underbody View	A-19
Pre-Test Rear Underbody View	A-20
Post-Test Rear Underbody View	A-21
Pre-Test Windshield View	A-22
Post-Test Windshield View	A-23
Pre-Test Barrier to Vehicle Alignment Overhead - View 1	A-24
Pre-Test Barrier to Vehicle Alignment Overhead - View 2	A-25
Pre-Test Driver Dummy Position View	A-26
Post-Test Driver Dummy Position View	A-27
Pre-Test Passenger Dummy Position View	A-28
Post-Test Passenger Dummy Position View	A-29

## List of Photographs

<u>Description</u>	<u>Figure</u>
Pre-Test Driver Dummy & Vehicle Interior - View 1	A-30
Post-Test Driver Dummy & Vehicle Interior - View 1	A-31
Pre-Test Driver Dummy & Vehicle Interior - View 2	A-32
Post-Test Driver Dummy & Vehicle Interior - View 2	A-33
Pre-Test Passenger Dummy & Vehicle Interior - View 1	A-34
Post-Test Passenger Dummy & Vehicle Interior - View 1	A-35
Pre-Test Passenger Dummy & Vehicle Interior - View 2	A-36
Post-Test Passenger Dummy & Vehicle Interior - View 2	A-37
Post-Test Driver Dummy Head Contact - View 1	A-38
Post-Test Driver Dummy Head Contact - View 2	A-39
Post-Test Driver Dummy Head Contact - View 3	A-40
Post-Test Passenger Dummy Head Contact - View 1	A-41
Post-Test Passenger Dummy Head Contact - View 2	A-42
Impact Event	A-43
Post-Test Vehicle Fuel System Fluid Spillage	A-44

Section 1.0

**Purpose and Test Procedure**

Purpose

This crash test was conducted to determine vehicle and occupant response in the 80 kph rear impact with 70% right side overlap test mode. The test was performed on a 1996 Suzuki Sidekick 2-door multipurpose passenger vehicle (mpv).

### Test Procedure

This test was conducted per Contract No. DTRS57-95-C-00011, Technical Task Directive No. 1, "Rear Impact Full-Scale Crash Testing for Upgrade of FMVSS 301 Test Procedure."

The test vehicle was instrumented with nine (9) accelerometers to measure longitudinal axis accelerations.

The test vehicle contained two (2) Part 572 E 50th percentile adult male anthropomorphic test devices (dummies). The dummies were positioned in the front outboard designated seating positions according to the dummy placement procedure specified in Appendix C of the Laboratory Test Procedure TP-208-09. Each dummy was restrained by a three-point unibelt.

The deformable impactor was instrumented with five (5) force load cells to measure longitudinal axis forces on the barrier face. The deformable barrier face was positioned 229 mm from ground level.

The impactor's specified velocity range was 80.1 to 81.8 kph.

Both dummies were instrumented with head center of gravity and Position 1, 2, and 3 accelerometers to measure longitudinal, lateral, and vertical accelerations; neck upper and lower 6-axis load cells to measure longitudinal, lateral, and vertical force and moments; chest and pelvis accelerometers to measure longitudinal, lateral, and vertical axis accelerations; and with left and right femur load cells to measure axial forces. Each Part 572 E dummy's instrumentation also included a chest potentiometer to measure longitudinal deflection. The driver dummy's lap and shoulder belt were each instrumented with a load cell.

The seventy-six (76) data channels were digitally sampled at 12,500 samples per second and processed per Sections 11.13 through 11.15 of the Laboratory Test Procedure TP-208-09.

The crash event was recorded by thirteen (13) high-speed motion picture cameras.



The vehicle and occupant data are summarized in Section 2.0. The FMVSS 301 data are presented in Section 3.0. The vehicle, occupant, and camera measurements are presented in Section 4.0. Appendix A contains the still photographic prints. Appendix B contains the dummy and vehicle data plots. Appendix C contains the dummy calibration information. Appendix D contains miscellaneous test information

Section 2.0

Rear Deformable Barrier Impact Test Summary

### Test Results Summary

This 80 kph rear crash test with 70% right side overlap was conducted at TRC on March 14, 1996.

The test vehicle, a 1996 Suzuki Sidekick 2-door mpv, was equipped with airbags and three-point unibelts at the driver's and right front passenger's seating positions. The vehicle's test weight was 1370 kg. The vehicle's maximum static crush was 828 mm.

The driver's HIC was 389. The driver's chest maximum resultant acceleration with three (3) milliseconds minimum duration was 39.5 g. The driver's chest maximum deflection was 3 mm. The driver's left and right femur maximum compressive forces were 2168 N and 1664 N, respectively.

The right front passenger's HIC was 569. The right front passenger's chest maximum resultant acceleration with three (3) milliseconds minimum duration was 39.7 g. The right front passenger's chest maximum deflection was 7 mm. The right front passenger's left and right femur maximum compressive forces were 2409 N and 1759 N, respectively.

A large amount of fuel system spillage occurred at impact and continued for the next thirty minutes immediately following the impact. The static rollover test was not conducted.

Data Acquisition Explanations

The following data channels recorded a questionable data spike at 190 milliseconds:

- NEKZF2 - right front passenger upper neck Z-axis axial force load cell
- NEKYM2 - right front passenger upper neck moment about Y-axis load cell
- NKLXF2 - right front passenger lower neck X-axis shear force load cell
- NKLYF2 - right front passenger lower neck Y-axis shear force load cell
- NKLZF2 - right front passenger lower neck Z-axis axial force load cell
- NKLXM2 - right front passenger lower neck moment about X-axis load cell
- NKLYM2 - right front passenger lower neck moment about Y-axis load cell
- NKLZM2 - right front passenger lower neck moment about Z-axis load cell
- LFMF2 - right front passenger left femur Z-axis axial force load cell
- RFMF2 - right front passenger left femur Z-axis axial force load cell

The rear package shelf X-axis accelerometer, TCRXG, exceeded the data channel's full scale limit at 12 milliseconds.

Table 1 Crash Test Summary

Test type:	80 kph rear impact with 70% right side overlap
Test date:	03/14/96
Test time:	1407
Ambient temperature at impact area:	17° C
Vehicle year/make/ model/body style:	1996/Suzuki/Sidekick/2-door mpv
Vehicle test weight:	1370 kg
Impact angle <sup>1</sup> :	180°
Impact velocity <sup>2</sup> :	
Primary:	81.6 kph
Secondary <sup>3</sup> :	81.6 kph
Maximum static crush:	828 mm
Number of cameras:	
High-speed:	13
Door opening data:	
Left-front:	Difficult
Right-front:	Difficult

<sup>1</sup> With respect to tow track centerline.

<sup>2</sup> Speed trap measurement ( $\pm .08$  kph accuracy)

<sup>3</sup> The secondary light trap failed.

Table 1 Crash Test Summary, Cont'd.

Dummies:	<u>Driver #35</u>	<u>Passenger #34</u>
Type:	Part 572 E	Part 572 E
Location:	Left front	Right front
Restraint:	Airbag/3-point unbelt	3-point unbelt
Number of data channels:	30	30
Front seat data:		
Seat track failure:	None	None
Seat back failure:	Seat back deformed	Seat back deformed
Visible dummy contact points:		
Head:	Head restraint and rear seat back	Head restraint and rear seat back
Chest:	None	None
Abdomen:	None	None
Left knee:	Steering wheel	None
Right knee:	Steering wheel	None

Table 2 Test Vehicle Information

Vehicle year/make/  
model/body style: 1996/Suzuki/Sidekick/2-door mpv  
Color: White  
VIN: 2S3TA02COT6400106  
Engine data:  
Placement: Lateral/transverse  
Cylinders: 4  
Displacement: 1.6 liters  
Transmission data: 5 speed, X manual, \_\_\_ automatic, \_\_\_ overdrive  
Final drive: \_\_\_ fwd, \_\_\_ rwd, X 4wd  
Date vehicle received: 02/29/96  
Odometer reading: 72  
Dealer's name  
and address: Columbus Auto Group, Inc.  
DBA Eastside Suzuki Inc.  
5880 Scarborough Blvd.  
Columbus, OH 43232-4746

Accessories:

Power steering	Yes	Automatic transmission	No
Power brakes	Yes	Automatic speed control	No
Power seats	No	Tilting steering wheel	No
Power windows	No	Telescoping steering wheel	No
Tinted glass	Yes	Air conditioning	No
Radio	No	Anti-skid brake	No
Clock	No	Rear window defroster	No
Power door locks	No		

Certification data from vehicle's label:

Vehicle manufactured by: CAMI-Automotive, Inc.  
Date of manufacture: 07/95  
VIN: 2S3TA02COT6400106  
GVWR: 1499 kg  
GAWR: Front: 710 kg  
Rear: 900 kg

Table 2 Test Vehicle Information, Cont'd.

Size of tires on vehicle: P205/75R15  
Spare tire: P205/75R15  
Type of front seats: Bucket

Tire & capacity data from vehicle's label:

Recommended tire size: P205/75R15

Recommended cold tire pressure:

Front: 160 kPa

Rear: 160 kPa

Designated Seating Capacity:

Front NA

Rear NA

Total NA

Vehicle Capacity Weight: NA

Test vehicle attitudes:

Delivered attitude: LF: 767 mm RF: 770 mm LR: 791 mm RR: 790 mm

Pre-test attitude: LF: 732 mm RF: 736 mm LR: 777 mm RR: 769 mm

Post-test attitude: LF: 731 mm RF: 753 mm LR: 839 mm RR: 1032 mm



Table 2 Test Vehicle Information, Cont'd.

Weight of test vehicle as received (with maximum fluids):

Right front	303 kg	Right rear	253 kg
Left front	298 kg	Left rear	251 kg
Total front weight	601 kg	(54.4% of total vehicle weight)	
Total rear weight	504 kg	(45.6% of total vehicle weight)	
Total delivered weight	1105 kg		

Calculation of test vehicle's target test weight:

RCLW = Rated Cargo and Luggage Weight

UDW = Unloaded Delivered Weight (1105 kg)

VCW<sup>1</sup> = Vehicle Capacity Weight = NA

DSC = Designated Seating Capacity (NA)

RCLW = VCW - 150 (DSC) = 136

Target test weight = UDW + RCLW<sup>1</sup> + (Number of Hybrid III dummies x 76 kg per dummy)

Target test weight = 1105 + 136 + 152 = 1393 kg

Weight of test vehicle with required dummies and 113 kg of cargo weight:

Right front	383 kg	Right rear	294 kg
Left front	391 kg	Left rear	302 kg
Total front weight	774 kg	(56.5% of total vehicle weight)	
Total rear weight	596 kg	(43.5% of total vehicle weight)	
Total test weight	1370 kg	(2.0% over target test weight)	

Weight of ballast secured in vehicle cargo area: 0

Components removed to meet target test weight: None

CG rearward of front wheel centerline: 957 mm

Vehicle Wheelbase: 2200 mm

<sup>1</sup> From vehicle's tire load label.

Table 3 Post-Impact Data

Test number: 960314  
Test date: 03/14/96  
Test time: 1407  
Test type: 80 kph rear impact with 70% right side overlap  
Impact angle: 180°  
Ambient temperature  
at impact area: 17° C  
Temperature in  
occupant compartment: 20° C


Impact velocity:  
Primary: 81.6 kph  
Secondary: 81.6 kph  
Specified range: 78.5 to 81.5 kph

Distance from vehicle to barrier:  
Entering velocity trap: 356 mm  
Exiting velocity trap: 51 mm

Test vehicle static crush:

Overall length of test vehicle:  
Pre-test: L: 3510 mm C: 3558 mm R: 3512 mm  
Post-test: L: 3285 mm C: 3002 mm R: 2668 mm  
Total crush: L: 225 mm C: 556 mm R: 844 mm  
Average crush: 542 mm

Figure 1 Impact Velocity Measurement System



The final vane clears the final emitter/receiver pair 51 millimeters before impact.

The vanes have 305-millimeter spacing.

**Figure 2 Accident Investigation Division Data**

**Test date:** 03/14/96  
**Vehicle year/make/  
model/body style:** 1996/Suzuki/Sidekick/2-door mpv  
**VIN:** 2S3TA02COT6400106  
**Build date:** 07/95  
**Test weight:** 1370 kg  
**Vehicle wheelbase:** 2200 mm  
**Maximum width:** 1630 mm  
**Front overhang:** 676 mm


**Collision Deformation**

**Classification (CDC) Code:** 06BDEW5

**Crush depth  
measurements:**  
 C1: 221 mm  
 C2: 358 mm  
 C3: 463 mm  
 C4: 596 mm  
 C5: 718 mm  
 C6: 828 mm

**Midpoint of damage:** D: Vehicle Longitudinal Centerline

**Length of damaged  
region:** L: 1524 mm



Section 3.0

FMVSS 301 Data

Table 4 Dummy Injury Criteria

Maximum Acceleration

	Head				Chest		
	X	Y	Z	R	X	Y	Z
Driver	54.1 g	15.4 g	-40.8 g	61.0 g	40.3 g	7.5 g	-8.7 g
Passenger	77.8 g	16.0 g	-35.1 g	82.9 g	75.0 g	7.6 g	16.6 g

Maximum Femur Compressive Force

	Left Femur	Right Femur
Driver	2168 N	1664 N
Passenger	2409 N	1759 N

Head Injury Criteria<sup>1</sup>

	HIC	Time t <sub>1</sub>	Time t <sub>2</sub>
Driver	389	78.7 ms	104.6 ms
Passenger	569	72.1 ms	90.2 ms

Head Maximum Resultant Acceleration<sup>2</sup>

	Acceleration	Time t <sub>1</sub>	Time t <sub>2</sub>
Driver	60.4 g	89.4 ms	92.6 ms
Passenger	79.0 g	81.4 ms	84.4 ms

Chest Maximum Resultant Acceleration<sup>2</sup>

	Acceleration	Time t <sub>1</sub>	Time t <sub>2</sub>
Driver	39.5 g	64.0 ms	68.4 ms
Passenger	39.7 g	45.2 ms	48.1 ms

Maximum Chest Deflection

Driver	3 mm
Passenger	7 mm

<sup>1</sup> As defined in FMVSS No. 208

<sup>2</sup> Defined as equal to or exceeding 0.003 sec. duration

Table 5 Fuel System Data

Vehicle year/make/model/body style:	1996/Suzuki/Sidekick/2-door mpv
Fuel system capacity:	42.0 (from owner's manual)
Usable capacity:	41.6 liters (furnished by COTR)
Test volume range:	38.3 liters to 39.1 liters (92-94% of usable)
Actual test volume:	38.7 liters (with entire fuel system filled)
Test fluid type:	Stoddard solvent
Specific gravity:	0.764
Kinematic viscosity:	0.99 centistoke
Test fluid color:	purple
Type of fuel pump:	electric
Does the electric fuel pump operate with ignition switch "on" and the engine not operating.	No
Details of fuel system:	The fuel tank is located behind the rear axle. The fuel filler neck is located on the right side. The fuel lines run along the right side to the front.

Table 6 FMVSS 301 Post-Impact Test Data

Test date: 03/14/96

Vehicle year/make/model/body style: 1996/Suzuki/Sidekick/2-door mpv

Test requirements:

Test vehicle fuel tank filled to 92 to 94% of manufacturer's usable capacity and with electric fuel pump operating (if it will operate without engine operation). Part 572 test dummies located at each front designated seating position.

Test vehicle impact type:

- Frontal (48 kph)
- Oblique (48 kph) with \_\_\_° barrier face first contacting (driver's/passenger's) side
- Rear moving barrier (80 kph)
- Lateral moving barrier (32 kph)

Fuel system fluid spillage measurements:

	<u>Test Results</u>	<u>Maximum Allowable</u>
1. From impact until vehicle motion ceases	See Note <sup>1</sup>	28 g
2. 5-Minute period after vehicle motion ceases	2674 g	140 g
3. Next 25 minutes after 5-minute period	7349 g	28 g/1 min

Fuel system fluid spillage location(s): Fuel tank

<sup>1</sup> A large amount of fuel system fluid occurred from the time of impact until motion ceased.



Section 4.0

Vehicle, Moving Deformable Barrier, Occupant, and Camera Measurements

**Figure 3 Pre-test and Post-test Measurement Points**




Table 7 Impacted Vehicle Measurements

Vehicle year/make/model/body style: 1996/Suzuki/Sidekick/2-door mpv

Test Number: 960314

No.	Type of measurement	Pre-test	Post-test	Diff.
X1	Total length of vehicle at centerline	3558 mm	3002 mm	556 mm
X2	Rear surface of vehicle to front of engine block	503 mm	517 mm	-14 mm
X3	Rear surface of vehicle to firewall	1037 mm	1043 mm	-6 mm
X4	Rear surface of vehicle to upper leading edge of right door	1224 mm	1215 mm	9 mm
X5	Rear surface of vehicle to upper leading edge of left door	1221 mm	1220 mm	1 mm
X6	Rear surface of vehicle to lower leading edge of right door	1248 mm	1247 mm	1 mm
X7	Rear surface of vehicle to lower leading edge of left door	1242 mm	1250 mm	-8 mm
X8	Rear surface of vehicle to upper trailing edge of right door	2373 mm	2359 mm	14 mm
X9	Rear surface of vehicle to upper trailing edge of left door	2369 mm	2365 mm	4 mm
X10	Rear surface of vehicle to lower trailing edge of right door	2287 mm	2283 mm	4 mm
X11	Rear surface of vehicle to lower trailing edge of left door	2282 mm	2282 mm	0 mm
X12	Rear surface of vehicle to bottom of "A" post on right side	1255 mm	1265 mm	-10 mm
X13	Rear surface of vehicle to bottom of "A" post on left side	1259 mm	1260 mm	-1 mm
X14	Rear surface of vehicle to firewall - right side	992 mm	993 mm	-1 mm
X15	Rear surface of vehicle to firewall - left side	991 mm	989 mm	2 mm
X16	Rear surface of vehicle to steering wheel center	1615 mm	1615 mm	0 mm
X17	Center of steering column to "A" post	231 mm	231 mm	0 mm
X18	Center of steering column to headliner	522 mm	531 mm	-9 mm
X19	Rear surface of vehicle to right side of front bumper	3512 mm	2668 mm	844 mm
X20	Rear surface of vehicle to left side of front bumper	3510 mm	3285 mm	225 mm
X21	Length of engine block	420 mm	420 mm	0 mm

Table 8 Vehicle Measurements

No.	Description of Measurement	Pre-Test	Post-Test	Difference
X1	Total Length of Vehicle at Centerline	3558	3002	556
X2	Front Surface of Vehicle to Bottom of "A" Post of Right Side	1255	1265	-10
X3	Front Surface of Vehicle to Bottom of "A" Post of Left Side	1259	1260	-1
X4	Front Surface of Vehicle to Right Side of Rear Bumper	3512	2668	844
X5	Front Surface of Vehicle to Left Side of Rear Bumper	3510	3285	225
X6	Right Front Sill to Ground Plane	244	303	-59
X7	Left Front Sill to Ground Plane	246	294	-48
X8	Right Rear Sill to Ground Plane	273	355	-82
X9	Left Rear Sill to Ground Plane	277	347	-70
X10	Wheelbase of Vehicle - Left Side	2200	2122	78
X11	Width of Vehicle at Maximum Width Point	1630	1738	-108
X12	Front Surface of Vehicle to Engine Target	503	517	-14
X13	Front Surface of Vehicle to Compartment Target	1718	1702	16
X14	Front Surface of Vehicle to Rear Bumper Target	3478	2944	534
X15	Wheelbase of Vehicle - Right Side	2200	1888	312

Figure 4 Vehicle Target Locations




Table 9 Test Vehicle Rear Profile Data

X-axis measurements referenced to a plane 430 millimeters forward of the front bumper support brackets. Y-axis measurements are left and right of the original vehicle centerline. Y-axis measurements (6 points) should divide the width of the car and be clearly indicated on the form. Z-axis (height) measurements are from the ground.



		Pre-Test Profile					
		Vehicle Left			Vehicle Right		
		pt. 1	pt. 2	pt. 3	pt. 4	pt. 5	pt. 6
Bottom of rear bumper	X	3904	3922	3922	3924	3920	3891
	Y	751	455	150	141	480	748
	Z	467	468	462	458	470	462
Top of rear bumper	X	3915	3951	3946	3954	3953	3924
	Y	764	455	148	148	453	752
	Z	644	633	633	633	640	644
Center of trunk	X	3824	3826	3839	3821	3837	3831
	Y	648	456	221	174	423	626
	Z	864	860	845	880	864	869
		Post-Test Profile					
		Vehicle Left			Vehicle Right		
		pt. 1	pt. 2	pt. 3	pt. 4	pt. 5	pt. 6
Bottom of rear bumper	X	3704	3549	3435	3357	3199	3065
	Y	740	448	150	140	480	720
	Z	410	453	482	493	538	580
Top of rear bumper	X	3694	3593	3483	3358	3235	3096
	Y	760	450	145	150	455	753
	Z	595	621	653	677	700	748
Center of trunk	X	3629	3530	3408	3383	3346	3359
	Y	584	383	185	205	430	627
	Z	756	837	962	951	776	702

Table 9 Test Vehicle Rear Profile Data, Cont'd.

		Change					
		Vehicle Left			Vehicle Right		
		pt. 1	pt. 2	pt. 3	pt. 4	pt. 5	pt. 6
Bottom of rear bumper	X	200	373	487	567	721	826
	Y	-11	-7	0	1	0	28
	Z	-57	-15	20	35	68	118
Top of rear bumper	X	221	358	463	596	718	828
	Y	-4	-5	-3	-2	-2	-1
	Z	-49	-12	20	44	60	104
Center of trunk	X	195	296	431	438	491	472
	Y	-64	-73	-36	31	7	1
	Z	-108	-23	117	71	88	167

+X: Rearward from a reference plane 430 mm forward of the vehicle front bumper  
 +Y: Left from vehicle longitudinal centerline  
 +Z: Up from ground

Figure 5 Vehicle Accelerometer Mounting Locations





**Table 10 Pre- and Post-Test Position of Vehicle Accelerometer Mounting Locations**

Accelerometer Description		X, Y, Z Location <sup>1</sup>		
		X	Y	Z
Left front seat outboard mounting rail	Pre	1863 mm	615 mm	438 mm
	Post	1855 mm	615 mm	440 mm
	Change	8 mm	0 mm	2 mm
Right front seat outboard mounting rail	Pre	1852 mm	-615 mm	435 mm
	Post	1841 mm	-615 mm	450 mm
	Change	11 mm	0 mm	15 mm
Left front seat back (mid-point of seat)	Pre	2307 mm	354 mm	980 mm
	Post	2230 mm	354 mm	1150 mm
	Change	77 mm	0 mm	170 mm
Right front seat back (mid-point of seat)	Pre	2308 mm	-354 mm	987 mm
	Post	2200 mm	-354 mm	1100 mm
	Change	108 mm	0 mm	113 mm
Radiator support	Pre	280 mm	-50 mm	878 mm
	Post	270 mm	-50 mm	895 mm
	Change	10 mm	0 mm	17 mm
Top of engine	Pre	607 mm	-12 mm	865 mm
	Post	616 mm	-12 mm	960 mm
	Change	-9 mm	0 mm	95 mm
Left rear wheel axle	Pre	2830 mm	360 mm	320 mm
	Post	2750 mm	395 mm	276 mm
	Change	80 mm	35 mm	-44 mm
Right rear wheel axle	Pre	2836 mm	-395 mm	320 mm
	Post	2640 mm	-395 mm	231 mm
	Change	196 mm	0 mm	-89 mm
Rear package shelf (top of rear seat back)	Pre	3250 mm	0 mm	675 mm
	Post	2797 mm	20 mm	744 mm
	Change	453 mm	20 mm	69 mm

<sup>1</sup> Reference Point: X - vertical plane at front bumper  
 Y - vehicle centerline  
 Z - ground

Table 11 Moving Deformable Barrier Face Static Crush

Location	Height	Zero distance at barrier centerline <sup>1</sup>																
		813	711	610	508	406	305	203	102	0	102	203	305	406	508	610	711	813
Top of face	762	330	335	328	330	330	330	328	326	330	330	331	330	328	327	329	330	330
Mid-face	508	331	331	328	330	330	330	329	326	329	330	329	325	327	326	329	330	330
Bumper	381	248	229	228	229	227	228	226	226	228	228	227	224	225	226	228	228	244

Post-test profile (distance in millimeters from reference plane<sup>2</sup>)

Top of face	762	533	514	500	492	480	464	442	432	433	445	396	358	336	334	334	330	331
Mid-face	508	624	556	549	530	499	475	452	439	404	372	352	329	326	327	327	324	324
Bumper	381	549	495	473	452	428	401	384	386	335	307	282	257	226	197	172	145	142

Static crush (mm)


Top of face	762	203	179	172	162	150	134	114	106	103	115	65	28	8	7	5	0	1
Mid-face	508	293	225	221	200	169	145	123	113	75	42	23	4	-1	1	-2	-6	-6
Bumper	381	301	266	245	223	201	173	158	160	107	79	55	33	1	-29	-56	-83	-102

<sup>1</sup> Column readings are left to right across barrier face from left to right.

<sup>2</sup> Reference plane is the rear surface of the deformable barrier face.

All measurements are in millimeters.


Figure 6 Moving Deformable Barrier Face Crush




Notes: L is pre-test length of contact surface.  
 C1 through C6 are spaced equally apart.  
 CL is moving barrier centerline.

	Pre-test	Post-test	Crush
L	1676 mm		
C1	248 mm	549 mm	301 mm
C2	229 mm	452 mm	223 mm
C3	226 mm	384 mm	158 mm
C4	227 mm	282 mm	55 mm
C5	226 mm	197 mm	-29 mm
C6	244 mm	142 mm	-102 mm
CL	228 mm	335 mm	107 mm

**Figure 7 Dummy Measurement Locations for Front Seat Occupants**



**VERTICAL LONGITUDINAL PLANE**



**VERTICAL TRANSVERSE PLANE**





Table 12 Dummy Measurement Data For Front Seat Occupants

Designation	Type of Measurement	Driver (Serial #35)	Passenger (Serial #34)
WA	Windshield angle	45°	NA
SWA	Steering wheel angle	60°	NA
SCA	Steering column angle	30°	NA
SA	Seat back angle	21°	21°
HZ	Head to roof	248 mm	262 mm
HH	Head to header	544 mm	528 mm
HW	Head to windshield	654 mm	647 mm
HR	Head to side header	218 mm	235 mm
NR	Nose to rim	481 mm	NA
NA	Nose to rim angle	14°	NA
CD	Chest to dash	578 mm	574 mm
CS	Steering wheel to chest	376 mm	NA
RA	Rim to abdomen	215 mm	NA
KDL	Left knee to dash	162 mm	165 mm
KDR	Right knee to dash	163 mm	170 mm
KDA	Outboard knee to dash angle	29°	44°
PA	Pelvic angle	21°	24°
TA	Tibial angle	42°	38°
KK	Knee to knee	304 mm	270 mm
ST <sup>1</sup>	Striker to head	573 mm	585 mm
	Striker to head angle	-78°	-75°
SK <sup>1</sup>	Striker to knee	645 mm	685 mm
	Striker to knee angle	3°	0°
SH <sup>1</sup>	Striker to H-point	255 mm	285 mm
	Striker to H-point angle	20°	11°
SHY	Striker to H-point (Y dir.)	174 mm	170 mm
HS	Head to side window	254 mm	255 mm
HD	H-point to door	117 mm	125 mm
AD	Arm to door	55 mm	68 mm

The seat back angle (SA°) is measured relative to vertical, all other angles are measured relative to horizontal.

Figure 8 Seat Belt Positioning Data



		Driver	Passenger
A	Top surface of aluminum plate to belt upper edge	418 mm	361 mm
B	Top surface of aluminum plate to belt lower edge	364 mm	275 mm
C	Dummy centerline to outer edge of belt at chest flesh top	78 mm	129 mm
D	Dummy centerline to inner edge of belt at chest flesh top	18 mm	68 mm
E	Dummy centerline to intersection of upper torso belt and lap belt	252 mm	255 mm

Figure 9 Camera Positions




Table 13 Motion Picture Camera Locations

Vehicle year/make/model/body style: 1996/Suzuki/Sidekick/2-door mpv

Test number: 960314

Camera Number	View	X	Y	Z	Angle of Inclination <sup>2</sup>	Angle of Rotation <sup>3</sup>	Camera Lens	Film Speed
1	Right side vehicle	7,772 mm	6,934 mm	838 mm	0°	0°	25 mm	995 frames/s
2	Right side overall	813 mm	6,274 mm	1,092 mm	0°	0°	13 mm	1000 frames/s
3	Right MDB	-1,372 mm	10,236 mm	914 mm	0°	0°	25 mm	1000 frames/s
4	Right close-up	305 mm	4,877 mm	1,092 mm	-3°	0°	17 mm	998 frames/s
5	Right front passenger onboard	NA	NA	NA	NA	NA	8 mm	995 frames/s
6	Left side MDB	-787 mm	-10,160 mm	838 mm	0°	0°	25 mm	995 frames/s
7	Left side close-up	432 mm	-7,442 mm	991 mm	-3°	0°	17 mm	1005 frames/s
8	Left side vehicle	2,565 mm	-11,227 mm	1,168 mm	-2°	0°	25 mm	998 frames/s
9	Driver onboard	NA	NA	NA	NA	NA	8 mm	1005 frames/s
10	Underbody vehicle	NA	NA	NA	90°	0°	17 mm	1000 frames/s
11	Overhead	0 mm	0 mm	10,668 mm	90°	0°	13 mm	998 frames/s
12	Left side overall	1,041 mm	-12,675 mm	1,092 mm	0°	0°	13 mm	NA <sup>4</sup> frames/s
13	Seat back view	0 mm	0 mm	10,668 mm	NA	NA	35 mm	815 frames/s

<sup>1</sup> +X: Forward from impact point MDB face

+Y: Rightward from monorail centerline

+Z: Upward from ground level

<sup>2</sup> +Angle of Inclination: Camera lens (upward from horizontal)

<sup>3</sup> +Angle of Rotation: Camera lens toward barrier from line perpendicular to monorail centerline

<sup>4</sup> Camera did not run during test



Appendix A

Photographs




Figure A-1 Pre-Test Front View

A-2

960314



Figure A-2 Pre-Test Left Front Three-Quarter View

A-3

960314



Figure A-3 Post-Test Left Front Three-Quarter View

A-4

960314





Figure A-4 Pre-Test Left Side View

A-5

960314




Figure A-5 Post-Test Left Side View

A-6

960314




Figure A-6 Pre-Test Left Rear Three-Quarter View

A-7

960314






Figure A-7 Post-Test Left Rear Three-Quarter View

A-8

960314






Figure A-8 Pre-Test Rear View

A-9

960314




Figure A-9 Post-Test Rear View

A-10

960314




Figure A-10 Pre-Test Right Rear Three-Quarter View

A-11

960314






Figure A-11 Post-Test Right Rear Three-Quarter View

A-12

960314




Figure A-12 Pre-Test Right Side View

A-13

960314




Figure A-13 Post-Test Right Side View

A-14

960314






Figure A-14 Pre-Test Right Front Three-Quarter View

A-15

960314



Figure A-15 Post-Test Right Front Three-Quarter View

A-16

960314






Figure A-16 Pre-Test Front Underbody View

A-17

960314




Figure A-17 Post-Test Front Underbody View

A-18

960314




Figure A-18 Pre-Test Right Front Underbody View

A-19

960314



Figure A-19 Post-Test Right Front Underbody View

A-20

960314






Figure A-20 Pre-Test Rear Underbody View

A-21

960314



Figure A-21 Post-Test Rear Underbody View

A-22

960314

PRE



Figure A-22 Pre-Test Windshield View

A-23

960314



Figure A-23 Post-Test Windshield View

A-24

960314






Figure A-24 Pre-Test Barrier to Vehicle Alignment Overhead - View 1

A-25

960314




Figure A-25 Pre-Test Barrier to Vehicle Alignment Overhead - View 2

A-26

960314



Figure A-26 Pre-Test Driver Dummy Position View

A-27

960314




Figure A-27 Post-Test Driver Dummy Position View

A-28

960314






Figure A-28 Pre-Test Passenger Dummy Position View

A-29

960314



Figure A-29 Post-Test Passenger Dummy Position View

A-30

960314



Figure A-30 Pre-Test Driver Dummy & Vehicle Interior - View 1

A-31

960314



Figure A-31 Post-Test Driver Dummy & Vehicle Interior - View 1

A-32

960314





Figure A-32 Pre-Test Driver Dummy & Vehicle Interior - View 2

A-33

960314



Figure A-33 Post-Test Driver Dummy & Vehicle Interior - View 2

A-34

960314



Figure A-34 Pre-Test Passenger Dummy & Vehicle Interior - View 1

A-35

960314



Figure A-35 Post-Test Passenger Dummy & Vehicle Interior - View 1

A-36

960314



Figure A-36 Pre-Test Passenger Dummy & Vehicle Interior - View 2

A-37

960314






Figure A-37 Post-Test Passenger Dummy & Vehicle Interior - View 2

A-38

960314




Figure A-38 Post-Test Driver Dummy Head Contact - View 1

A-39

960314




Figure A-39 Post-Test Driver Dummy Head Contact - View 2

A-40

960314






Figure A-40 Post-Test Driver Dummy Head Contact - View 3

A-41

960314




Figure A-41 Post-Test Passenger Dummy Head Contact - View 1

A-42

960314




Figure A-42 Post-Test Passenger Dummy Head Contact - View 2

A-43

960314




Figure A-43 Impact Event

A-44

960314





Figure A-44 Post-Test Vehicle Fuel System Fluid Spillage

A-45


960314

Appendix B

Data Plots

MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
DRIVER HEAD X-AXIS ACCELERATION

FUEL SYSTEM INTEGRITY TEST NUMBER: 960314



CHANNEL: HEDXG1 FILTER: CH. CLASS 1000 PEAK DATA: 54.05 G @ 92.56 MS; -3.55 G @ 229.84 MS


TRC INC.

MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
DRIVER HEAD Y-AXIS ACCELERATION

TEST NUMBER: 960314

FUEL SYSTEM INTEGRITY

TRC INC.




CHANNEL: HEDYG1 FILTER: CH. CLASS 1000

PEAK DATA: 15.37 G @ 92.24 MS; -1.54 G @ 40.80 MS



MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
DRIVER HEAD Z-AXIS ACCELERATION  
FUEL SYSTEM INTEGRITY

TEST NUMBER: 960314




CHANNEL: HEDZG1 FILTER: CH. CLASS 1000 PEAK DATA: 12.63 G @ 65.44 MS; -40.79 G @ 85.52 MS

MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
DRIVER HEAD RESULTANT ACCELERATION

TEST NUMBER: 960314

FUEL SYSTEM INTEGRITY



CHANNEL: HEDRG1 FILTER: CH. CLASS 1000

PEAK DATA: 60.98 G @ 91.76 MS; 0.09 G @ -19.68 MS


960314

B-5

MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
 DRIVER UPPER NECK X-AXIS SHEAR FORCE

TEST NUMBER: 960314


FUEL SYSTEM INTEGRITY



CHANNEL: NEKXF1 FILTER: CH. CLASS 1000  
 PEAK DATA: 138.62 N @ 231.04 MS; -556.74 N @ 94.64 MS

MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
DRIVER UPPER NECK Y-AXIS SHEAR FORCE


FUEL SYSTEM INTEGRITY TEST NUMBER: 960314



CHANNEL: NEKYF1 FILTER: CH. CLASS 1000 PEAK DATA: 47.31 N @ 48.72 MS; -274.30 N @ 95.28 MS

MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
DRIVER UPPER NECK Z-AXIS AXIAL FORCE


FUEL SYSTEM INTEGRITY TEST NUMBER: 960314



CHANNEL: NEKZF1 FILTER: CH. CLASS 1000 PEAK DATA: 1980.00 N @ 86.08 MS; -606.68 N @ 66.56 MS

MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
DRIVER UPPER NECK MOMENT ABOUT X-AXIS

TRC INC. FUEL SYSTEM INTEGRITY TEST NUMBER: 960314




CHANNEL: NEKXMI FILTER: CH, CLASS 600 PEAK DATA: 6.65 N·M @ 125.84 MS; -5.98 N·M @ 185.60 MS

MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
DRIVER UPPER NECK MOMENT ABOUT Y-AXIS

TEST NUMBER: 960314


FUEL SYSTEM INTEGRITY



CHANNEL: NEKYM1 FILTER: CH. CLASS 600 PEAK DATA: 53.86 N.M @ 75.04 MS; -10.17 N.M @ 119.92 MS

MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
 DRIVER UPPER NECK MOMENT ABOUT Z-AXIS

FUEL SYSTEM INTEGRITY TEST NUMBER: 960314



CHANNEL: NEKZM1 FILTER: CH. CLASS 600  
 PEAK DATA: 2.81 N·M @ 218.16 MS; -9.23 N·M @ 110.64 MS

TRC INC.

TORQUE (N·M)

TIME (MS)




MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
DRIVER HEAD POSITION 1 X-AXIS ACCELERATION

TEST NUMBER: 960314

FUEL SYSTEM INTEGRITY

TRC INC.




PEAK DATA: 59.56 G @ 91.52 MS; -3.26 G @ 238.88 MS

CHANNEL: HD1XG1 FILTER: CH. CLASS 1000

MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
DRIVER HEAD POSITION 1 Z-AXIS ACCELERATION

TEST NUMBER: 960314

FUEL SYSTEM INTEGRITY




CHANNEL: HD1ZG1 FILTER: CH. CLASS 1000  
PEAK DATA: 14.42 G @ 66.48 MS; -38.34 G @ 86.00 MS

960314

MOVING DEFORMABLE BARRIER INTO REAR OF A 1986 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
DRIVER HEAD POSITION 2 Y-AXIS ACCELERATION

TRC INC. FUEL SYSTEM INTEGRITY TEST NUMBER: 960314




CHANNEL: HD2YG1 FILTER: CH. CLASS 1000 PEAK DATA: 11.62 G @ 108.00 MS; -1.75 G @ 38.24 MS

MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
DRIVER HEAD POSITION 2 Z-AXIS ACCELERATION

TEST NUMBER: 960314

FUEL SYSTEM INTEGRITY



TRC INC.

CHANNEL: HD27G1 FILTER: CH. CLASS 1000

960314


AS664085

MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
DRIVER HEAD POSITION 3 X-AXIS ACCELERATION

TEST NUMBER: 960314

FUEL SYSTEM INTEGRITY

TRC INC.



CHANNEL: HD3XG1 FILTER: CH. CLASS 1000


PEAK DATA: 84.61 G @ 91.92 MS; -21.56 G @ 72.72 MS

MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
DRIVER HEAD POSITION 3 Y-AXIS ACCELERATION

TEST NUMBER: 960314

FUEL SYSTEM INTEGRITY


TRC INC.



CHANNEL: HD3YG1 FILTER: CH. CLASS 1000  
PEAK DATA: 21.60 G @ 93.60 MS; -2.65 G @ 39.28 MS

MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
DRIVER LOWER NECK X-AXIS SHEAR FORCE

FUEL SYSTEM INTEGRITY TEST NUMBER: 960314




CHANNEL: NKLXF1 FILTER: CH. CLASS 1000 PEAK DATA: 91.07 N @ 237.12 MS; -1768.20 N @ 92.08 MS

MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
DRIVER LOWER NECK Y-AXIS SHEAR FORCE

TEST NUMBER: 960314

FUEL SYSTEM INTEGRITY




CHANNEL: NKLYF1 FILTER: CH. CLASS 1000  
PEAK DATA: 136.84 N @ 74.24 MS; -312.89 N @ 91.60 MS



MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
DRIVER LOWER NECK Z-AXIS AXIAL FORCE

TRC INC. FUEL SYSTEM INTEGRITY TEST NUMBER: 960314




CHANNEL: NKLZF1 FILTER: CH. CLASS 1000 PEAK DATA: 1728.80 N @ 85.68 MS; -654.83 N @ 66.32 MS

MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
DRIVER LOWER NECK MOMENT ABOUT X-AXIS

TEST NUMBER: 960314

FUEL SYSTEM INTEGRITY



PEAK DATA: 49.68 N·M @ 92.08 MS; -9.68 N·M @ 47.36 MS

CHANNEL: NKLXM1 FILTER: CH. CLASS 600


TRC INC.

TORQUE (N·M)

TIME (MS)

MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
DRIVER LOWER NECK MOMENT ABOUT Y-AXIS

FUEL SYSTEM INTEGRITY TEST NUMBER: 960314




CHANNEL: NKLYM1 FILTER: CH. CLASS 600 PEAK DATA: 49.99 N·M @ 65.04 MS; -224.40 N·M @ 89.92 MS

MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
DRIVER LOWER NECK MOMENT ABOUT Z-AXIS

TEST NUMBER: 960314

FUEL SYSTEM INTEGRITY

TRC INC.




PEAK DATA: 8.38 N.M @ 68.88 MS; -19.95 N.M @ 122.88 MS

CHANNEL: NKLZM1 FILTER: CH. CLASS 600

MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
DRIVER CHEST X-AXIS ACCELERATION

TEST NUMBER: 960314

FUEL SYSTEM INTEGRITY



CHANNEL: CSTXG1 FILTER: CH. CLASS 180

PEAK DATA: 40.29 G @ 67.28 MS; -2.01 G @ 299.44 MS

MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
DRIVER CHEST Y-AXIS ACCELERATION

TEST NUMBER: 960314

FUEL SYSTEM INTEGRITY

IRC INC.

60

40

20


0

-20

-40

-60

ACCELERATION (G)



310 280 250 220 190 160 130 100 70 40 10 -20 -40 -60

TIME (MS)

CHANNEL: CSTYGI FILTER: CH. CLASS 180


PEAK DATA: 7.47 G @ 85.12 MS; -3.04 G @ 95.04 MS

960314

AS664095

MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
DRIVER CHEST Z-AXIS ACCELERATION

FUEL SYSTEM INTEGRITY TEST NUMBER: 960314




CHANNEL: CSTZG1 FILTER: CH. CLASS 180 PEAK DATA: 7.44 G @ 66.00 MS; -8.72 G @ 75.36 MS

MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
DRIVER CHEST RESULTANT ACCELERATION

TEST NUMBER: 960314


FUEL SYSTEM INTEGRITY



CHANNEL: CSTRG1 FILTER: CH. CLASS 180 PEAK DATA: 41.14 G @ 67.20 MS; 0.00 G @ -20.00 MS



MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
 DRIVER CHEST DEFLECTION  
 FUEL SYSTEM INTEGRITY




CHANNEL: CSTXD1 FILTER: CH. CLASS 180 PEAK DATA: 3.40 MM @ 69.60 MS; -1.00 MM @ 169.20 MS

MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
DRIVER PELVIS X-AXIS ACCELERATION

TEST NUMBER: 960314

FUEL SYSTEM INTEGRITY

TRC INC.




PEAK DATA: 38.22 G @ 70.08 MS, -2.54 G @ 114.80 MS

CHANNEL: PEVXG1 FILTER: CH. CLASS 1000

MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
DRIVER PELVIS Y-AXIS ACCELERATION

FUEL SYSTEM INTEGRITY TEST NUMBER: 960314




CHANNEL: PEVYG1 FILTER: CH. CLASS 1000 PEAK DATA: 6.32 G @ 73.60 MS; -2.51 G @ 52.08 MS

MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
DRIVER PELVIS Z-AXIS ACCELERATION

TEST NUMBER: 960314

FUEL SYSTEM INTEGRITY

TRC INC.



CHANNEL: PEVZG1 FILTER: CH. CLASS 1000

PEAK DATA: 4.76 G @ 73.84 MS; -7.99 G @ 58.56 MS


MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
DRIVER PELVIS RESULTANT ACCELERATION

TEST NUMBER: 960314

FUEL SYSTEM INTEGRITY

TRC INC.

100



ACCELERATION (G)

-20

10

40

70

100

130

160

190

220

250

280

310


TIME (MS)

CHANNEL: PEVRG1 FILTER: CH. CLASS 1000

PEAK DATA: 38.58 G @ 70.08 MS; 0.07 G @ -20.00 MS

MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
 DRIVER LEFT FEMUR FORCE  
 FUEL SYSTEM INTEGRITY

TEST NUMBER: 960314



CHANNEL: LFMF1 FILTER: CH. CLASS 600  
 PEAK DATA: 32.98 N @ 180.96 MS; -2167.88 N @ 71.84 MS

MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
DRIVER RIGHT FENUR FORCE

TEST NUMBER: 960314

FUEL SYSTEM INTEGRITY

IRC INC.

90

60


30

0

-30

-60

-90



310

280

250

220

190

160

130

100

70

40

10

-20

-50

-80

TIME (MS)

PEAK DATA: 136.61 N @ 236.72 MS; -1663.54 N @ 68.48 MS


FILTER: CH. CLASS 600

CHANNEL: RFMFI

MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
RIGHT FRONT PASSENGER HEAD X-AXIS ACCELERATION

TEST NUMBER: 960314

FUEL SYSTEM INTEGRITY



CHANNEL: HEDXG2 FILTER: CH. CLASS 1000

PEAK DATA: 77.77 G @ 83.36 MS; -8.60 G @ 52.00 MS

TRC INC.


ACCELERATION (G)

TIME (MS)



MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
RIGHT FRONT PASSENGER HEAD Y-AXIS ACCELERATION

TRC INC. FUEL SYSTEM INTEGRITY TEST NUMBER: 960314




CHANNEL: HEDYG2 FILTER: CH. CLASS 1000 PEAK DATA: 16.04 G @ 82.00 MS; -2.54 G @ 154.72 MS

MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
RIGHT FRONT PASSENGER HEAD Z-AXIS ACCELERATION

TEST NUMBER: 960314

FUEL SYSTEM INTEGRITY




CHANNEL: HEDZG2 FILTER: CH. CLASS 1000

PEAK DATA: 24.76 G @ 47.76 MS; -35.13 G @ 74.40 MS

MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
RIGHT FRONT PASSENGER HEAD RESULTANT ACCELERATION

FUEL SYSTEM INTEGRITY TEST NUMBER: 960314




CHANNEL: HEDRG2 FILTER: CH. CLASS 1000 PEAK DATA: 82.89 G @ 83.28 MS; 0.02 G @ -20.00 MS

MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
 RIGHT FRONT PASSENGER UPPER NECK X-AXIS SHEAR FORCE

TEST NUMBER: 960314

FUEL SYSTEM INTEGRITY




CHANNEL: NEKXF2 FILTER: CH. CLASS 1000 PEAK DATA: 294.40 N @ 51.92 MS; -687.34 N @ 68.40 MS

MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
 RIGHT FRONT PASSENGER UPPER NECK Y-AXIS SHEAR FORCE

TEST NUMBER: 960314

FUEL SYSTEM INTEGRITY

TRC INC.



PEAK DATA: 84.28 N @ 151.68 MS; -176.70 N @ 77.60 MS

CHANNEL: NEKYF2 FILTER: CH. CLASS 1000

MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
 RIGHT FRONT PASSENGER UPPER NECK Z-AXIS AXIAL FORCE

TEST NUMBER: 960314

FUEL SYSTEM INTEGRITY

TRC INC.

60

40

20

0

-20

-40

-60

10

40

70

100

130

160

190

220

250

280

310

TIME (MS)

PEAK DATA: 1520.56 N @ 77.04 MS; -704.46 N @ 48.00 MS

CHANNEL: NEKZF2 FILTER: CH. CLASS 1000

See Data Acquisition Explanations;

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.


.

FORCE (N X 10<sup>2</sup>)

MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
RIGHT FRONT PASSENGER UPPER NECK MOMENT ABOUT X-AXIS

TEST NUMBER: 960314

FUEL SYSTEM INTEGRITY




CHANNEL: NEKX12 FILTER: CH. CLASS 600  
PEAK DATA: 10.50 N.M @ 59.76 MS; -8.85 N.M @ 51.20 MS

MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
 RIGHT FRONT PASSENGER UPPER NECK MOMENT ABOUT Y-AXIS

TEST NUMBER: 960314

FUEL SYSTEM INTEGRITY



See Data Acquisition Explanations


CHANNEL: NEYM2 FILTER: CH. CLASS 600 PEAK DATA: 77.45 N·M @ 67.68 MS; -10.82 N·M @ 114.08 MS

TRC INC.



MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
RIGHT FRONT PASSENGER UPPER NECK MOMENT ABOUT Z-AXIS

FUEL SYSTEM INTEGRITY TEST NUMBER: 960314




CHANNEL: NEKZM2 FILTER: CH. CLASS 600

PEAK DATA: 4.81 N.M @ 145.44 MS; -6.06 N.M @ 66.00 MS

MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
RIGHT FRONT PASSENGER HEAD POSITION 1 X-AXIS ACCELERATION

TEST NUMBER: 960314

FUEL SYSTEM INTEGRITY



CHANNEL: HD1XG2 FILTER: CH. CLASS 1000

PEAK DATA: 77.50 G @ 83.04 MS; -7.77 G @ 50.64 MS

TRC INC.

ACCELERATION (G)

-40

-20

0

20

40

60

80

TIME (MS)

10

40

70

100

130

160

190

220


250

280

310

MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
RIGHT FRONT PASSENGER HEAD POSITION 1 Z-AXIS ACCELERATION

FUEL SYSTEM INTEGRITY TEST NUMBER: 960314



CHANNEL: HD1ZG2 FILTER: CH. CLASS 1000

PEAK DATA: 26.18 G @ 47.92 MS; -37.81 G @ 74.56 MS

MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
RIGHT FRONT PASSENGER HEAD POSITION 2 Y-AXIS ACCELERATION

TEST NUMBER: 960314

FUEL SYSTEM INTEGRITY

TRC INC.

60

40

20

0

-20

-40

-60

ACCELERATION (G)

310

280

250

220

190

160

130

100

70

40

10

-20

TIME (MS)


PEAK DATA: 15.24 G @ 83.04 MS; -3.60 G @ 146.96 MS

CHANNEL: HD2YG2 FILTER: CH. CLASS 1000

MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
RIGHT FRONT PASSENGER HEAD POSITION 2 Z-AXIS ACCELERATION

TEST NUMBER: 960314

FUEL\_SYSTEM INTEGRITY



PEAK DATA: 19.40 G @ 63.52 MS; -70.46 G @ 81.60 MS

CHANNEL: HD22G2 FILTER: CH. CLASS 1000

TRC INC.


ACCELERATION (G)

TIME (MS)

MOVING DEFORMABLE BARRIER INTO REAR OF A 1986 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
RIGHT FRONT PASSENGER HEAD POSITION 3 X-AXIS ACCELERATION

TEST NUMBER: 960314

FUEL SYSTEM INTEGRITY




CHANNEL: HD3XG2 FILTER: CH. CLASS 1000 PEAK DATA: 132.06 G @ 82.40 MS; -26.62 G @ 132.06 MS

MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
RIGHT FRONT PASSENGER HEAD POSITION 3 Y-AXIS ACCELERATION

TEST NUMBER: 960314

FUEL SYSTEM INTEGRITY

TRC INC.



CHANNEL: HD3YG2 FILTER: CH. CLASS 1000


PEAK DATA: 21.17 G @ 83.04 MS; -4.75 G @ 51.28 MS

MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
RIGHT FRONT PASSENGER LOWER NECK X-AXIS SHEAR FORCE

TEST NUMBER: 960314

FUEL SYSTEM INTEGRITY

TRC INC.



CHANNEL: NKLXF2 FILTER: CH. CLASS 1000 PEAK DATA: 432.15 N @ 47.28 MS; -1725.15 N @ 77.84 MS



MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
 RIGHT FRONT PASSENGER LOWER NECK Y-AXIS SHEAR FORCE

TEST NUMBER: 960314

FUEL SYSTEM INTEGRITY

TRC INC.

60

40

20

0

-20

-40

-60

FORCE (N X 10<sup>2</sup>)

10

40

70

100

130

150

180

220

250

280

310

TIME (MS)

See Data Acquisition Explanations

CHANNEL: NKLYF2


FILTER: CH. CLASS 1000

PEAK DATA: 855.13 N @ 189.84 MS; -403.94 N @ 75.44 MS

MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
RIGHT FRONT PASSENGER LOWER NECK Z-AXIS AXIAL FORCE

TEST NUMBER: 960314

FUEL SYSTEM INTEGRITY




See Data Acquisition Explanations

CHANNEL: NKLZF2 FILTER: CH. CLASS 1000 PEAK DATA: 2034.18 N @ 74.96 MS; -1370.55 N @ 48.72 MS

MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
 RIGHT FRONT PASSENGER LOWER NECK MOMENT ABOUT X-AXIS

TEST NUMBER: 960314

FUEL SYSTEM INTEGRITY




CHANNEL: NKLXM2 FILTER: CH. CLASS 600  
 PEAK DATA: 35.19 N.M @ 78.96 MS; -24.80 N.M @ 158.64 MS

MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
RIGHT FRONT PASSENGER LOWER NECK MOMENT ABOUT Y-AXIS

TEST NUMBER: 960314

FUEL SYSTEM INTEGRITY

TRC INC.



PEAK DATA: 111.99 N·M @ 48.40 MS; -233.72 N·M @ 74.96 MS


CHANNEL: NKLYM2 FILTER: CH. CLASS 600

MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
RIGHT FRONT PASSENGER LOWER NECK MOMENT ABOUT Z-AXIS

TEST NUMBER: 960314

FUEL SYSTEM INTEGRITY

TRC INC.




PEAK DATA: 2.32 N·M @ 29.36 MS; -41.37 N·M @ 71.04 MS

CHANNEL: NKLZM2 FILTER: CH. CLASS 600

MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
RIGHT FRONT PASSENGER CHEST X-AXIS ACCELERATION

TEST NUMBER: 960314

FUEL SYSTEM INTEGRITY



CHANNEL: CSTXG2 FILTER: CH. CLASS 180

PEAK DATA: 74.95 G @ 46.64 MS; -2.47 G @ 214.32 MS

TRC INC.

ACCELERATION (G)

960314

AS664127


B-57

MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
RIGHT FRONT PASSENGER CHEST Y-AXIS ACCELERATION

TEST NUMBER: 960314

FUEL SYSTEM INTEGRITY

TRC INC.




CHANNEL: CSTYG2 FILTER: CH. CLASS 180

PEAK DATA: 7.63 G @ 45.92 MS; -3.79 G @ 48.80 MS

MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
RIGHT FRONT PASSENGER CHEST Z-AXIS ACCELERATION

TEST NUMBER: 960314

FUEL SYSTEM INTEGRITY




CHANNEL: CSTZG2 FILTER: CH. CLASS 180 PEAK DATA: 16.58 G @ 46.00 MS; -14.07 G @ 57.28 MS



MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
RIGHT FRONT PASSENGER CHEST RESULTANT ACCELERATION

FUEL SYSTEM INTEGRITY TEST NUMBER: 960314




CHANNEL: CSTRG2 FILTER: CH. CLASS 180 PEAK DATA: 76.49 G @ 46.56 MS; 0.00 G @ -3.92 MS

TRC INC.

MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
RIGHT FRONT PASSENGER CHEST DEFLECTION

TEST NUMBER: 960314

FUEL SYSTEM INTEGRITY



PEAK DATA: 7.35 MM @ 51.28 MS; -0.08 MM @ 79.68 MS

CHANNEL: CSTX02 FILTER: CH. CLASS 180


TRC INC.

DISPLACEMENT (MM)

TIME (MS)

MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
RIGHT FRONT PASSENGER PELVIS X-AXIS ACCELERATION

FUEL SYSTEM INTEGRITY TEST NUMBER: 960314




CHANNEL: PEVXG2 FILTER: CH. CLASS 1000 PEAK DATA: 49.32 G @ 59.92 MS; -3.07 G @ 204.40 MS

EA12-005 PRODUCED BY SUZUKI MOTOR CORPORATION

MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
RIGHT FRONT PASSENGER PELVIS Y-AXIS ACCELERATION


TRC INC. FUEL SYSTEM INTEGRITY TEST NUMBER: 960314



CHANNEL: PEVYG2 FILTER: CH. CLASS 1000

MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
RIGHT FRONT PASSENGER PELVIS Z-AXIS ACCELERATION  
FUEL SYSTEM INTEGRITY

TEST NUMBER: 960314




CHANNEL: PEVZG2 FILTER: CH. CLASS 1000  
PEAK DATA: 19.15 G @ 66.88 MS; -22.93 G @ 49.84 MS

1 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
RIGHT FRONT PASSENGER PELYIS RESULTANT ACCELERATION

TEST NUMBER: 960314

FUEL SYSTEM INTEGRITY




CHANNEL: PEVRG2 FILTER: CH. CLASS 1000 PEAK DATA: 46.76 G @ 61.84 MS; 0.11 G @ -20.00 MS

MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
 RIGHT FRONT PASSENGER RIGHT FEMUR FORCE

TEST NUMBER: 950314

FUEL SYSTEM INTEGRITY

TRC INC.



See Data Acquisition Explanations

PEAK DATA: 125.61 N @ 228.72 MS; -1758.60 N @ 79.52 MS


CHANNEL: RFMF2 FILTER: CH. CLASS 600

1. 2. 3. 4. 5. 6. 7. 8. 9. 10. 11. 12. 13. 14. 15. 16. 17. 18. 19. 20. 21. 22. 23. 24. 25. 26. 27. 28. 29. 30. 31. 32. 33. 34. 35. 36. 37. 38. 39. 40. 41. 42. 43. 44. 45. 46. 47. 48. 49. 50. 51. 52. 53. 54. 55. 56. 57. 58. 59. 60. 61. 62. 63. 64. 65. 66. 67. 68. 69. 70. 71. 72. 73. 74. 75. 76. 77. 78. 79. 80. 81. 82. 83. 84. 85. 86. 87. 88. 89. 90. 91. 92. 93. 94. 95. 96. 97. 98. 99. 100.

MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
FRONT SEAT OUTBOARD MOUNTING RAIL X-AXIS ACCELERATION

TEST NUMBER: 960314

FUEL SYSTEM INTEGRITY



PEAK DATA: 34.70 G @ 10.08 MS; -4.21 G @ 44.00 MS

CHANNEL: TLFXG1 FILTER: CH. CLASS 60

TRC INC.

ACCELERATION (G)


TIME (MS)



MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
FRONT SEAT BACK MID X-AXIS ACCELERATION

TEST NUMBER: 960314

FUEL SYSTEM INTEGRITY




CHANNEL: TLFXG2 FILTER: CH. CLASS 60

PEAK DATA: 75.63 G @ 62.96 MS; -20.44 G @ 87.76 MS

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
FRONT SEAT BACK MID X-AXIS ACCELERATION


TRC INC. TEST NUMBER: 960314



CHANNEL: TRFXG2 FILTER: CH. CLASS 60 PEAK DATA: 75.98 G @ 56.96 MS; -21.43 G @ 61.04 MS

MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
 RADIATOR SUPPORT X-AXIS ACCELERATION  
 FUEL SYSTEM INTEGRITY

TEST NUMBER: 960314



PEAK DATA: 24.28 G @ 12.40 MS; -4.91 G @ 6.08 MS

CHANNEL: FFCXG FILTER: CH. CLASS 60


TRC INC.

MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
ENGINE TOP X-AXIS ACCELERATION

TEST NUMBER: 960314

FUEL SYSTEM INTEGRITY

TRC INC.




PEAK DATA: 26.33 G @ 28.16 MS; -8.29 G @ 127.44 MS

CHANNEL: ENGXG FILTER: CH. CLASS 60

MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
REAR WHEEL AXLE X-AXIS ACCELERATION  
FUEL SYSTEM INTEGRITY

TEST NUMBER: 960314




CHANNEL: RAXXG1 FILTER: CH. CLASS 60  
PEAK DATA: 59.65 G @ 30.72 MS; -101.96 G @ 52.40 MS

MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
REAR WHEEL AXLE X-AXIS ACCELERATION

TEST NUMBER: 960314


FUEL SYSTEM INTEGRITY



CHANNEL: RAXXG2 FILTER: CH. CLASS 60  
PEAK DATA: 68.38 G @ 32.32 MS; -103.02 G @ 51.92 MS

MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
PACKAGE SHELF X-AXIS ACCELERATION  
FUEL SYSTEM INTEGRITY

TEST NUMBER: 960314




CHANNEL: TCRXG FILTER: CH. CLASS 60 PEAK DATA: 86.05 G @ 11.68 MS; -59.90 G @ 15.36 MS

MOVING DEFORMABLE BARRIER INTO REAR OF A 1986 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
DRIVER SHOULDER BELT FORCE

TEST NUMBER: 960314

FUEL SYSTEM INTEGRITY



CHANNEL: SHBF1 FILTER: CH. CLASS 60

PEAK DATA: 278.63 N @ 298.88 MS; -19.80 N @ 163.04 MS



MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
DRIVER LAP BELT OUTBOARD FORCE

TEST NUMBER: 960314

FUEL SYSTEM INTEGRITY

IRC INC.

100

80

60

40

20

0

-20

FORCE (N X 10<sup>2</sup>)

130  
TIME (MS)

100

70

40

10

-20

250

280

310

CHANNEL: LBOF1 FILTER: CH. CLASS 60


PEAK DATA: 297.95 N @ 65.92 MS; -34.81 N @ 23.76 MS

MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
BARRIER FRONT TOP LEFT FORCE

TEST NUMBER: 960314

FUEL SYSTEM INTEGRITY

TRC INC.




PEAK DATA: 3.24 N e -20.00 MS, -65208.57 N e 61.44 MS

CHANNEL: BFFXF1 FILTER: CH. CLASS 60

MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
BARRIER FRONT BOTTOM LEFT FORCE  
FUEL SYSTEM INTEGRITY

TEST NUMBER: 960314




CHANNEL: BFFXF2 FILTER: CH. CLASS 60 PEAK DATA: 4379.34 N @ 146.72 MS; -100418.92 N @ 7.12 MS

MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
BARRIER FRONT BOTTOM RIGHT FORCE

TEST NUMBER: 960314

FUEL SYSTEM INTEGRITY


TRC INC.



CHANNEL: BFFXF3 FILTER: CH. CLASS 60 PEAK DATA: 21205.73 N @ 77.52 MS; -35212.18 N @ 7.20 MS

MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
BARRIER FRONT TOP RIGHT FORCE

FUEL SYSTEM INTEGRITY TEST NUMBER: 960314




CHANNEL: BFFXF4 FILTER: CH. CLASS 60

PEAK DATA: 17080.89 N @ 6.96 MS; -29983.09 N @ 60.00 MS

MOVING DEFORMABLE BARRIER INTO REAR OF A 1996 SUZUKI SIDEKICK AT 80 KPH AND 70% OVERLAP  
BARRIER FRONT CENTER FORCE  
FUEL SYSTEM INTEGRITY

TEST NUMBER: 960314



PEAK DATA: 7794.82 N @ 213.68 MS; -65202.52 N @ 8.40 MS

CHANNEL: BFFXF5 FILTER: CH. CLASS 60

TRC INC

Appendix C

Dummy Calibration Information

Pre-Test Calibration

Serial Number 35



TRANSPORTATION RESEARCH CENTER INC.  
 HYBRID III EXTERNAL DIMENSIONS  
 35 VECTOR

11-JUL-95

TRC INC. TEST NO: 35C1ED1 572E SN35 EXT.DIMENSION CAL01

| TEST PARAMETER (DIMEN.)               | SPECIFICATION | TEST RESULTS |
|---------------------------------------|---------------|--------------|
| LOCATION FOR CHEST CIRCUMFERENCE (AA) | 429 - 434 MM  | 432. MM      |
| LOCATION FOR WAIST CIRCUMFERENCE (BB) | 226 - 231 MM  | 229. MM      |
| CHEST CIRCUMFERENCE (Y)               | 970 - 1001 MM | 988. MM      |
| WAIST CIRCUMFERENCE (Z)               | 836 - 866 MM  | 848. MM      |
| CHEST DEPTH (O)                       | 213 - 229 MM  | 218. MM      |
| H-POINT HEIGHT (C)                    | 84 - 89 MM    | 86. MM       |
| H-POINT FROM SEATBACK (D)             | 135 - 140 MM  | 137. MM      |
| SKULL CAP TO BACKLINE (H)             | 41 - 46 MM    | 43. MM       |
| TOTAL SITTING HEIGHT (A)              | 879 - 889 MM  | 886. MM      |
| THIGH CLEARANCE (F)                   | 140 - 155 MM  | 152. MM      |
| BUTTOCK KNEE LENGTH (K)               | 579 - 605 MM  | 602. MM      |
| BUTTOCK POPLITEAL LENGTH (N)          | 452 - 478 MM  | 475. MM      |
| POPLITEAL HEIGHT (L)                  | 429 - 455 MM  | 442. MM      |
| KNEE PIVOT HEIGHT (M)                 | 485 - 500 MM  | 500. MM      |
| FOOT LENGTH (P)                       | 252 - 267 MM  | 254. MM      |
| FOOT BREADTH (W)                      | 91 - 107 MM   | 94. MM       |
| SHOULDER PIVOT FROM BACKLINE (E)      | 84 - 94 MM    | 91. MM       |
| SHOULDER BREADTH (V)                  | 422 - 437 MM  | 427. MM      |
| SHOULDER PIVOT HEIGHT (B)             | 506 - 521 MM  | 511. MM      |
| ELBOW REST HEIGHT (J)                 | 191 - 211 MM  | 203. MM      |
| SHOULDER-ELBOW LENGTH (I)             | 330 - 345 MM  | 343. MM      |
| BACK OF ELBOW TO WRIST PIVOT (G)      | 290 - 305 MM  | 297. MM      |

DUMMY MEETS SPECIFICATIONS

TECHNICIAN Richard DeVos

RUN NUMBER: 071295.1437

TRANSPORTATION RESEARCH CENTER INC.

HEAD DROP TEST

HYBRID III

09-NOV-95

TRC INC.

TEST NO: 35C1HD2

572E SN35 HEAD DROP CAL 01

| TEST PARAMETER                  | SPECIFICATION    | TEST RESULTS |
|---------------------------------|------------------|--------------|
| TEMPERATURE                     | 18.9-25.6 DEG. C | 20.6 DEG. C  |
| RELATIVE HUMIDITY               | 10 - 70 %        | 30.0 %       |
| PEAK RESULTANT ACCELERATION     | 225 - 275 G      | 262.44 G     |
| PEAK LATERAL ACCELERATION       | 15 G MAX         | -9.03 G      |
| IS ACCELERATION CURVE UNIMODAL? | YES              | YES          |

TEST MEETS SPECIFICATIONS

TECHNICIAN Richard LeVan

RUN NUMBER: 110995.1358;1

PART 572-E HYBRID III HEAD CALIBRATION  
HEAD ACCELERATION X AXIS

TRC TEST NUMBER: 35C1HDZ

572E SN35 HEAD DROP CAL 01

RUN NUMBER: 040496.1506;1

75

0

-75


-150

-225

-300

-375

ACCELERATION (G)



TIME (MS X 10<sup>-1</sup>)

PEAK DATA: 2.37 G @ 4.40 MS; -230.10 G @ 1.92 MS

CHANNEL: HEDXG FILTER: CH. CLASS 1000

PART 572-E HYBRID III HEAD CALIBRATION  
HEAD ACCELERATION Y AXIS  
572E SN35 HEAD DROP CAL 01

TRC TEST NUMBER: 35C1H02

RUN NUMBER: 040496.1506;1

225

150

75


0

-75

-150

-225

ACCELERATION (G)




TIME (MS X 10<sup>-1</sup>)

PEAK DATA: 2.20 G @ 4.72 MS; -9.04 G @ 1.92 MS

CHANNEL: HEDYG FILTER: CH. CLASS 1000

PART 572-E HYBRID III HEAD CALIBRATION  
HEAD ACCELERATION Z AXIS


TRC TEST NUMBER: 35C1HD2      572E SN35 HEAD DROP CAL 01      RUN NUMBER: 040496.1506j1



CHANNEL: HEDZG      FILTER: CH. CLASS 1000      PEAK DATA: -0.01 G @ -0.24 MS; -125.90 G @ 1.92 MS

PART 572-E HYBRID III HEAD CALIBRATION  
HEAD RESULTANT ACCELERATION

TRC TEST NUMBER: 35C1HD2      572E SN35 HEAD DROP CAL 01      RUN NUMBER: 040496.1506;1



CHANNEL: HEDRC      FILTER: CH. CLASS 1000      PEAK DATA: 262.45 G @ 1.92 MS; 0.02 G @ -0.32 MS

TRANSPORTATION RESEARCH CENTER INC.

NECK FLEXION TEST - 6 CHANNEL TRANSDUCER

HYBRID III

11-JUL-95

TRC INC. TEST NO: 35C1NF1 572E SN35 NECK FLEXION CAL01

| TEST PARAMETER                                   | SPECIFICATION           | TEST RESULTS |
|--|-------------------------|--------------|
| TEMPERATURE                                      | 20.6-22.2 DEG. C        | 20.6 DEG. C  |
| RELATIVE HUMIDITY                                | 10 - 70 %               | 63.0 %       |
| IMPACT VELOCITY                                  | 6.89 - 7.13 M/S         | 6.99 M/S     |
| PENDULUM<br>DECELERATION                         | 10 MS   22.50 - 27.50 G | 22.98 G      |
|  | 20 MS   17.60 - 22.60 G | 20.12 G      |
|  | 30 MS   12.50 - 18.50 G | 15.08 G      |
| MAX PENDULUM G                                   | 29 G MAX                | 23.77 G      |
| MAX PENDULUM G ABOVE 30 MS                       | 29 G MAX                | 15.03 G      |
| DECELERATION-TIME CURVE<br>DECAY TIME TO 5 G     | 34 - 42 MS              | 37.36 MS     |
| D PLANE  | MAX   64 - 78 DEG.      | 70.37 DEG.   |
| ROTATION   | TIME   57 - 64 MS       | 58.00 MS     |
| MOMENT ABOUT<br>OCCIPITAL<br>CONDYLE             | MAX   88.2 - 108.5 NM   | 96.89 NM     |
|  | TIME   47 - 58 MS       | 50.00 MS     |
| ROTATION ANGLE-TIME CURVE<br>DECAY TIME TO ZERO  | 113 - 128 MS            | 114.48 MS    |
| POSITIVE MOMENT-TIME CURVE<br>DECAY TIME TO ZERO | 97 - 107 MS             | 99.60 MS     |

TEST MEETS SPECIFICATIONS

TECHNICIAN Richard Le Van


RUN NUMBER: 071195.0843;2

PART 572-E HYBRID III NECK FLEXION CALIBRATION  
PENDULUM DECELERATION

TRC TEST NUMBER: 35CINFL

572E SN35 NECK FLEXION CAL01

RUN NUMBER: 040496.1506;2



CHANNEL: PENXG FILTER: CH. CLASS 60

PEAK DATA: 23.78 G @ 8.64 MS; -1.97 G @ 43.76 MS




PART 572-E HYBRID III NECK FLEXION CALIBRATION

ROTATION ABOUT BASE OF NECK

572E SN35 NECK FLEXION CAL01

TRC TEST NUMBER: 35CINF1

RUN NUMBER: 040496.1506;2




CHANNEL: BETA FILTER: CH. CLASS 60 PEAK DATA: 30.01 ° @ 58.24 MS; -19.33 ° @ 167.52 MS

PART 572-E HYBRID III NECK FLEXION CALIBRATION  
ROTATION ABOUT OCCIPITAL CONDYLE

TRC TEST NUMBER: 35CINF1

572E SN35 NECK FLEXION CAL01

RUN NUMBER: 040496.1506;2



CHANNEL: THETA FILTER: CH. CLASS 60

PEAK DATA: 40.37 ° @ 57.76 MS; -30.85 ° @ 169.84 MS


PART 572-E HYBRID III NECK FLEXION CALIBRATION

TOTAL ROTATION

TRC TEST NUMBER: 35C1NF1

572E SN35 NECK FLEXION CAL01

RUN NUMBER: 040496.1506;2



CHANNEL: TOTAN FILTER: CH. CLASS 60 PEAK DATA: 70.38 ° @ 58.00 MS; -50.17 ° @ 169.52 MS


PART 572-E HYBRID III NECK FLEXION CALIBRATION

NECK FORCE X AXIS

TRC TEST NUMBER: 35CINF1

572E SN35 NECK FLEXION CAL01


RUN NUMBER: 040496.1506;2



CHANNEL: NEKXF FILTER: CH. CLASS 60 PEAK DATA: 912.76 N @ 54.56 MS; -205.59 N @ 164.80 MS

PART 572-E HYBRID III NECK FLEXION CALIBRATION  
NECK MOMENT Y AXIS

TRC TEST NUMBER: 35CINF1      572E SN35 NECK FLEXION CAL01      RUN NUMBER: 040496.150612




CHANNEL: NEKYM      FILTER: CH. CLASS 60      PEAK DATA: 80.78 N.M @ 50.00 MS; -33.90 N.M @ 14.24 MS

PART 572-E HYBRID III NECK FLEXION CALIBRATION  
TOTAL MOMENT ABOUT OCCIPITAL CONDYLE

TRC TEST NUMBER: 35CINF1

572E SN35 NECK FLEXION CAL01

RUN NUMBER: 040496.1506;2



CHANNEL: NEKOM FILTER: CH. CLASS 60  
PEAK DATA: 96.89 N·M @ 50.00 MS; -24.77 N·M @ 13.84 MS

TRANSPORTATION RESEARCH CENTER INC.

NECK EXTENSION TEST - 6 CHANNEL TRANSDUCER

HYBRID III

11-JUL-95

TRC INC. TEST NO: 35C1NE1 572E SN35 NECK EXT. CAL01

| TEST PARAMETER                                   | SPECIFICATION           | TEST RESULTS |
|--|-------------------------|--------------|
| TEMPERATURE                                      | 20.6 - 22.2 DEG. C      | 20.6 DEG. C  |
| RELATIVE HUMIDITY                                | 10 - 70 %               | 63.0 %       |
| IMPACT VELOCITY                                  | 5.95 - 6.19 M/S         | 6.00 M/S     |
| PENDULUM<br>DECELERATION                         | 10 MS   17.20 - 21.20 G | 17.48 G      |
|  | 20 MS   14.00 - 19.00 G | 15.59 G      |
|  | 30 MS   11.00 - 16.00 G | 14.31 G      |
| MAX PENDULUM G                                   | 22 G MAX                | 18.20 G      |
| MAX PENDULUM G ABOVE 30 MS                       | 22 G MAX                | 14.27 G      |
| DECELERATION-TIME CURVE<br>DECAY TIME TO 5 G     | 38 - 46 MS              | 39.04 MS     |
| D PLANE  | MAX   81 - 106 DEG.     | 96.12 DEG.   |
| ROTATION   | TIME   72 - 82 MS       | 74.08 MS     |
| MOMENT ABOUT<br>OCCIPITAL<br>CONDYLE             | MIN   -80.0/-52.9 NM    | -65.59 NM    |
|  | TIME   65 - 79 MS       | 69.76 MS     |
| ROTATION ANGLE-TIME CURVE<br>DECAY TIME TO ZERO  | 147 - 174 MS            | 156.00 MS    |
| NEGATIVE MOMENT-TIME CURVE<br>DECAY TIME TO ZERO | 120 - 148 MS            | 134.80 MS    |

TEST MEETS SPECIFICATIONS

TECHNICIAN

*Richard L. Van*


RUN NUMBER: 071195.0855;1

PART 572-E HYBRID III NECK EXTENSION CALIBRATION  
PENDULUM DECELERATION

TRC TEST NUMBER: 35CINE1

572E SN35 NECK EXT. CAL01

RUN NUMBER: 040496.150671



CHANNEL: PENXG FILTER: CH. CLASS 60

PEAK DATA: 18.21 G @ 8.64 MS; -1.91 G @ 45.20 MS




PART 572-E HYBRID III NECK EXTENSION CALIBRATION  
ROTATION ABOUT BASE OF NECK

TRC TEST NUMBER: 35C1NE1

572E SN35 NECK\_EXT. CAL01

RUN NUMBER: 040496.1506;1



CHANNEL: BETA FILTER: CH. CLASS 60


PEAK DATA: 35.65 ° @ 72.64 MS; -12.75 ° @ 197.84 MS

PART 572-E HYBRID III NECK EXTENSION CALIBRATION  
ROTATION ABOUT OCCIPITAL CONDYLE

TRC TEST NUMBER: 35CINE1

572E SN35 NECK EXT. CAL01

RUN NUMBER: 040496.1506;1



CHANNEL: THETA FILTER: CH. CLASS 60  
PEAK DATA: 60.59 ° @ 76.32 MS; -18.87 ° @ 194.56 MS

ANGLE (°)

TIME (MS)

C-20

960314


PART 572-E HYBRID III NECK EXTENSION CALIBRATION

TOTAL ROTATION

TRC TEST NUMBER: 35CINE1

572E SN35 NECK EXT. CAL01

RUN NUMBER: 040496.1506;1



CHANNEL: TOTAN FILTER: CH. CLASS 60 PEAK DATA: 96.13 ° @ 74.08 MS; -31.61 ° @ 195.20 MS


PART 572-E HYBRID III NECK EXTENSION CALIBRATION

NECK FORCE X AXIS

TRC TEST NUMBER: 35CINE1

572E SN35 NECK EXT. CAL01


RUN NUMBER: 040496.1506;1



CHANNEL: NEKXF FILTER: CH. CLASS 60 PEAK DATA: 294.85 N @ 188.88 MS; -605.24 N @ 64.72 MS

PART 572-E HYBRID III NECK EXTENSION CALIBRATION  
 NECK MOMENT Y AXIS

TRC TEST NUMBER: 35CINE1      572E SN35 NECK EXT. CAL01      RUN NUMBER: 040496.1506;1




PEAK DATA: 32.44 N.M @ 177.28 MS; -55.54 N.M @ 69.92 MS

CHANNEL: NEKYM      FILTER: CH. CLASS 60

PART 572-E HYBRID III NECK EXTENSION CALIBRATION  
TOTAL MOMENT ABOUT OCCIPITAL CONDYLE

TRC TEST NUMBER: 35CINE1 RUN NUMBER: 040496.1506;1

572E SN35 NECK EXT. CAL01



CHANNEL: NEKOM FILTER: CH. CLASS 60 PEAK DATA: 36.57 N-M @ 177.68 MS; -65.59 N-M @ 69.76 MS

TRANSPORTATION RESEARCH CENTER INC.

THORAX IMPACT TEST

HYBRID III

11-JUL-95

TRC INC.

TEST NO: 35C1TH1

572E SN35 H.S.THORAX CAL01

| TEST PARAMETER          | HIGH SPEED TEST  | TEST RESULTS |
|-------------------------|------------------|--------------|
|                         | SPECIFICATION    |              |
| TEMPERATURE             | 20.6-22.2 DEG. C | 21.4 DEG. C  |
| RELATIVE HUMIDITY       | 10 - 70 %        | 63.0 %       |
| PENDULUM VELOCITY       | 6.59 - 6.83 M/S  | 6.62 M/S     |
| MAXIMUM DEFLECTION      | 63.5 - 72.6 MM   | 66.7 MM      |
| MAXIMUM RESISTIVE FORCE | 5159 - 5894 N    | 5608. N      |
| INTERNAL HYSTERESIS     | 69% - 85%        | 73.6%        |

TEST MEETS SPECIFICATIONS

TECHNICIAN Richard LeVan


RUN NUMBER: 071195.1433;1

FART 572-E HYBRID III THORAX CALIBRATION  
PENDULUM DECELERATION

TRC TEST NUMBER: 35C1TH1

572E SN35 H.S. THORAX CAL01

RUN NUMBER: 040496.1506;1




CHANNEL: PENXG FILTER: CH. CLASS 180 PEAK DATA: 24.48 G @ 19.52 MS; -0.19 G @ -0.64 MS



PART 572-E HYBRID III THORAX CALIBRATION  
PENDULUM FORCE

TRC TEST NUMBER: 35CITHI      572E SN35 H.S. THORAX CAL01      RUN NUMBER: 040496.1506;1




CHANNEL: PENXF      FILTER: CH. CLASS 180      PEAK DATA: 5608.25 N @ 19.52 MS; -42.97 N @ -0.64 MS

PART 572-E HYBRID III THORAX CALIBRATION  
STERNUM DISPLACEMENT

TRC TEST NUMBER: 35C1TH1

572E SN35 H.S.THORAX CAL01

RUN NUMBER: 040496.1506;1




CHANNEL: CSTXD FILTER: CH. CLASS 180

PEAK DATA: 66.71 MM @ 24.64 MS; -0.05 MM @ 0.96 MS

PART 572-E HYBRID III THORAX CALIBRATION  
 CHEST DISPLACEMENT VS PENDULUM FORCE

TRC TEST NUMBER: 35C1TH1      RUN NUMBER: 040496.1506;1

572E SN35 H.S.THORAX CAL01



CHANNEL: CSTXD      FILTER: CH. CLASS 180  
 PENXF              CH. CLASS 180

PEAK DATA:      66.71 MM @ 24.64 MS;      -0.05 NM @ 0.96 MS  
 5608.25 N @ 19.52 MS;      -42.97 N @ -0.64 MS

TRANSPORTATION RESEARCH CENTER INC.

RIGHT KNEE IMPACT TEST

HYBRID III

11-JUL-95

TRC INC.

TEST NO: 35C1RK1

572E SN35 RIGHT KNEE CAL 01

| TEST PARAMETER                            | SPECIFICATION    | TEST RESULTS |
|---|------------------|--------------|
| TEMPERATURE                               | 18.9-25.6 DEG. C | 20.6 DEG. C  |
| RELATIVE HUMIDITY                         | 10 - 70 %        | 63.0 %       |
| PROBE VELOCITY                            | 2.07 - 2.13 M/S  | 2.10 M/S     |
| PEAK KNEE IMPACT FORCE<br>5.0 KG PENDULUM | 4715 - 5782 N    | 4893.6 N     |

TEST MEETS SPECIFICATIONS

TECHNICIAN Richard LeVan


RUN NUMBER: 071195.1336;3

PART 572-E HYBRID III RIGHT KNEE CALIBRATION  
PENDULUM DECELERATION (5 KC PEND.)

TRC TEST NUMBER: 35CIRK1

572E SN35 RIGHT KNEE CAL 01

RUN NUMBER: 040496.1506.3



CHANNEL: PENXC FILTER: CH. CLASS 600


PEAK DATA: 100.02 G @ 3.12 MS; -0.64 G @ 8.88 MS

PART 572-E HYBRID III RIGHT KNEE CALIBRATION  
PENDULUM FORCE (5 KG PEND.)

TRC TEST NUMBER: 35C1RK1

572E SN35 RIGHT KNEE CAL 01

RUN NUMBER: 040496.1506.3



CHANNEL: PENXF FILTER: CH. CLASS 600

TRANSPORTATION RESEARCH CENTER INC.

LEFT KNEE IMPACT TEST

HYBRID III

11-JUL-95

TRC INC.

TEST NO: 35C1LK1

572E SN35 LEFT KNEE CAL 01

| TEST PARAMETER                            | SPECIFICATION    | TEST RESULTS |
|---|------------------|--------------|
| TEMPERATURE                               | 18.9-25.6 DEG. C | 20.6 DEG. C  |
| RELATIVE HUMIDITY                         | 10 - 70 %        | 63.0 %       |
| PROBE VELOCITY                            | 2.07 - 2.13 M/S  | 2.11 M/S     |
| PEAK KNEE IMPACT FORCE<br>5.0 KG PENDULUM | 4715 - 5782 N    | 4747.9 N     |

TEST MEETS SPECIFICATIONS

TECHNICIAN

*Richard L. Lee*


RUN NUMBER: 071195.1251;2

PART 572-E HYBRID III LEFT KNEE CALIBRATION  
PENDULUM DECELERATION (5 KG PEND.)

TRC TEST NUMBER: 35C1LK1

572E SN35 LEFT KNEE CAL 01

RUN NUMBER: 040496.1506;2



CHANNEL: PENXG FILTER: CH. CLASS 600


PEAK DATA: 97.04 G @ 2.96 MS; -0.87 G @ 8.32 MS



PART 572-E HYBRID III LEFT KNEE CALIBRATION  
PENDULUM FORCE (5 KG PEND.)

TRC TEST NUMBER: 35C1LK1      RUN NUMBER: 040496.1506;2

572E SN35 LEFT KNEE CAL 01



PEAK DATA: 4747.92 N @ 2.96 MS; -42.49 N @ 8.32 MS

CHANNEL: PENXF      FILTER: CH. CLASS 600

**Pre-Test Calibration**

**Serial Number 34**

TRANSPORTATION RESEARCH CENTER INC.  
 HYBRID III EXTERNAL DIMENSIONS  
 34 VECTOR

11-JUL-95

TRC INC. TEST NO: 34C1ED1 572E SN34 EXT.DIMENSION CAL01

| TEST PARAMETER (DIMEN.)               | SPECIFICATION | TEST RESULTS |
|---------------------------------------|---------------|--------------|
| LOCATION FOR CHEST CIRCUMFERENCE (AA) | 429 - 434 MM  | 432. MM      |
| LOCATION FOR WAIST CIRCUMFERENCE (BB) | 226 - 231 MM  | 229. MM      |
| CHEST CIRCUMFERENCE (Y)               | 970 - 1001 MM | 991. MM      |
| WAIST CIRCUMFERENCE (Z)               | 836 - 866 MM  | 856. MM      |
| CHEST DEPTH (O)                       | 213 - 229 MM  | 218. MM      |
| H-POINT HEIGHT (C)                    | 84 - 89 MM    | 86. MM       |
| H-POINT FROM SEATBACK (D)             | 135 - 140 MM  | 137. MM      |
| SKULL CAP TO BACKLINE (H)             | 41 - 46 MM    | 43. MM       |
| TOTAL SITTING HEIGHT (A)              | 879 - 889 MM  | 884. MM      |
| THIGH CLEARANCE (F)                   | 140 - 155 MM  | 155. MM      |
| BUTTOCK KNEE LENGTH (K)               | 579 - 605 MM  | 602. MM      |
| BUTTOCK POPLITEAL LENGTH (N)          | 452 - 478 MM  | 472. MM      |
| POPLITEAL HEIGHT (L)                  | 429 - 455 MM  | 439. MM      |
| KNEE PIVOT HEIGHT (M)                 | 485 - 500 MM  | 498. MM      |
| FOOT LENGTH (P)                       | 252 - 267 MM  | 254. MM      |
| FOOT BREADTH (W)                      | 91 - 107 MM   | 97. MM       |
| SHOULDER PIVOT FROM BACKLINE (E)      | 84 - 94 MM    | 91. MM       |
| SHOULDER BREADTH (V)                  | 422 - 437 MM  | 427. MM      |
| SHOULDER PIVOT HEIGHT (B)             | 506 - 521 MM  | 513. MM      |
| ELBOW REST HEIGHT (J)                 | 191 - 211 MM  | 208. MM      |
| SHOULDER-ELBOW LENGTH (I)             | 330 - 345 MM  | 335. MM      |
| BACK OF ELBOW TO WRIST PIVOT (G)      | 290 - 305 MM  | 295. MM      |

DUMMY MEETS SPECIFICATIONS  
 TECHNICIAN *Richard Le Van*

RUN NUMBER: 071295.1424

TRANSPORTATION RESEARCH CENTER INC.

HEAD DROP TEST

HYBRID III

06-MAR-96

TRC INC.

TEST NO: 34C1HD3

572E SN34 HEAD DROP CAL 01

| TEST PARAMETER                  | SPECIFICATION    | TEST RESULTS |
|---------------------------------|------------------|--------------|
| TEMPERATURE                     | 18.9-25.6 DEG. C | 20.6 DEG. C  |
| RELATIVE HUMIDITY               | 10 - 70 %        | 39.0 %       |
| PEAK RESULTANT ACCELERATION     | 225 - 275 G      | 263.60 G     |
| PEAK LATERAL ACCELERATION       | 15 G MAX         | -8.63 G      |
| IS ACCELERATION CURVE UNIMODAL? | YES              | YES          |

TEST MEETS SPECIFICATIONS

TECHNICIAN Richard L. Van


RUN NUMBER: 030696.1057;1

PART 572-E HYBRID III HEAD CALIBRATION  
HEAD ACCELERATION X AXIS

TRC TEST NUMBER: 34C1H03

572E SN34 HEAD DROP CAL 01


RUN NUMBER: 040496.1528;1



CHANNEL: HEDXG FILTER: CH. CLASS 1000 PEAK DATA: 0.34 G @ -0.08 MS; -229.24 G @ 1.92 MS

PART 572-E HYBRID III HEAD CALIBRATION  
HEAD ACCELERATION Y AXIS

TRC TEST NUMBER: 34CIHQ3      572E SN34 HEAD DROP CAL 01      RUN NUMBER: 040496.1528;1



PEAK DATA: 0.67 G @ 7.76 MS; -8.63 G @ 2.08 MS

CHANNEL: HEDYG      FILTER: CH. CLASS 1000

PART 572-E HYBRID III HEAD CALIBRATION  
HEAD ACCELERATION Z AXIS

TRC TEST NUMBER: 34C1H03

572E SN34 HEAD DROP CAL 01

RUN NUMBER: 040496.1528;1

75

0

-75


-150

-225

-300

-375

ACCELERATION (G)



100  
90  
80  
70  
60  
50  
40  
30  
20  
10  
0

TIME (MS X 10<sup>-1</sup>)

CHANNEL: HEDZG FILTER: CH. CLASS 1000


PEAK DATA: 0.00 G @ -0.32 MS; -130.81 G @ 2.08 MS

PART 572-E HYBRID III HEAD CALIBRATION  
HEAD RESULTANT ACCELERATION

TRC TEST NUMBER: 34CIH03

572E SN34 HEAD DROP CAL 01

RUN NUMBER: 040496.1528;1



CHANNEL: HEDRG FILTER: CH. CLASS 1000

PEAK DATA: 263.61 G @ 2.00 MS; 0.02 G @ -0.24 MS



TRANSPORTATION RESEARCH CENTER INC.

NECK FLEXION TEST - 6 CHANNEL TRANSDUCER

HYBRID III

11-JUL-95

TRC INC. TEST NO: 34C1NF1 572E SN34 NECK FLEXION CAL01

| TEST PARAMETER                                   |       | SPECIFICATION    | TEST RESULTS |
|--|-------|------------------|--------------|
| TEMPERATURE                                      |       | 20.6-22.2 DEG. C | 20.6 DEG. C  |
| RELATIVE HUMIDITY                                |       | 10 - 70 %        | 63.0 %       |
| IMPACT VELOCITY                                  |       | 6.89 - 7.13 M/S  | 6.99 M/S     |
| PENDULUM<br>DECELERATION                         | 10 MS | 22.50 - 27.50 G  | 22.98 G      |
|  | 20 MS | 17.60 - 22.60 G  | 19.34 G      |
|  | 30 MS | 12.50 - 18.50 G  | 14.91 G      |
| MAX PENDULUM G                                   |       | 29 G MAX         | 23.79 G      |
| MAX PENDULUM G ABOVE 30 MS                       |       | 29 G MAX         | 14.89 G      |
| DECELERATION-TIME CURVE<br>DECAY TIME TO 5 G     |       | 34 - 42 MS       | 38.16 MS     |
| D PLANE  | MAX   | 64 - 78 DEG.     | 72.72 DEG.   |
| ROTATION   | TIME  | 57 - 64 MS       | 60.24 MS     |
| MOMENT ABOUT<br>OCCIPITAL<br>CONDYLE             | MAX   | 88.2 - 108.5 NM  | 90.00 NM     |
|  | TIME  | 47 - 58 MS       | 51.60 MS     |
| ROTATION ANGLE-TIME CURVE<br>DECAY TIME TO ZERO  |       | 113 - 128 MS     | 117.76 MS    |
| POSITIVE MOMENT-TIME CURVE<br>DECAY TIME TO ZERO |       | 97 - 107 MS      | 103.44 MS    |

TEST MEETS SPECIFICATIONS

TECHNICIAN Richard LaVan


RUN NUMBER: 071195.1004;1

PART 572-E HYBRID III NECK FLEXION CALIBRATION  
PENDULUM DECELERATION

TRC TEST NUMBER: 34CINF1

572E SN34 NECK FLEXION CAL01

RUN NUMBER: 040496.1528;1



CHANNEL: PENXG FILTER: CH. CLASS 60


PEAK DATA: 23.79 G @ 8.80 MS; -2.85 G @ 44.48 MS

PART 572-E HYBRID III NECK FLEXION CALIBRATION  
ROTATION ABOUT BASE OF NECK

TRC TEST NUMBER: 34CINF1

572E SN34 NECK FLEXION CAL01

RUN NUMBER: 040496.1528.j1




CHANNEL: BETA FILTER: CH. CLASS 60 PEAK DATA: 31.85 ° @ 61.52 MS; -19.92 ° @ 175.76 MS

PART 572-E HYBRID III NECK FLEXION CALIBRATION  
 ROTATION ABOUT OCCIPITAL CONDYLE

TRC TEST NUMBER: 34CINFI

572E SN34 NECK FLEXION CAL01

RUN NUMBER: 040496.1528;1



CHANNEL: THETA FILTER: CH. CLASS 60

PEAK DATA: 40.90 ° @ 59.60 MS; -32.12 ° @ 179.12 MS

PART 572-E HYBRID III NECK FLEXION CALIBRATION

TOTAL ROTATION

IRC TEST NUMBER: 34C1NF1

572E SN34 NECK FLEXION CAL01

RUN NUMBER: 040496.1528;1

120

90

60

30

0

-30

-60

ANGLE (°)

0

20

40

60

80

100

120

140

160

180

200

200

TIME (MS)

PEAK DATA: 72.73 ° @ 60.24 MS; -51.93 ° @ 177.44 MS

CHANNEL: TOTAN


FILTER: CH. CLASS 60

PART 572-E HYBRID III NECK FLEXION CALIBRATION  
NECK FORCE X AXIS

TRC TEST NUMBER: 34CINF1

572E SN34 NECK FLEXION CAL01


RUN NUMBER: 040496.1528;1



CHANNEL: NEKXF FILTER: CH. CLASS 60  
PEAK DATA: 832.72 N @ 46.80 MS; -192.96 N @ 169.52 MS

PART 572-E HYBRID III NECK FLEXION CALIBRATION  
NECK MOMENT Y AXIS

TRC TEST NUMBER: 34CINF1      572E SN34 NECK FLEXION CAL01      RUN NUMBER: 040496.1528;1



PEAK DATA: 75.60 N·M @ 51.52 MS; -37.99 N·M @ 14.32 MS


CHANNEL: NEKYM      FILTER: CH. CLASS 60

PART 572-E HYBRID III NECK FLEXION CALIBRATION  
TOTAL MOMENT ABOUT OCCIPITAL CONDYLE

TRC TEST NUMBER: 34CINF1

572E SN34 NECK FLEXION CAL01

RUN NUMBER: 040496.1528;1



CHANNEL: NEKOM FILTER: CH. CLASS 60

PEAK DATA: 90.00 N-M @ 51.60 MS; -27.68 N-M @ 14.00 MS



TRANSPORTATION RESEARCH CENTER INC.

NECK EXTENSION TEST - 6 CHANNEL TRANSDUCER

HYBRID III

11-JUL-95

TRC INC. TEST NO: 34C1NE1 572E SN34 NECK EXT. CAL01

| TEST PARAMETER                                   | SPECIFICATION           | TEST RESULTS |
|--|-------------------------|--------------|
| TEMPERATURE                                      | 20.6 - 22.2 DEG. C      | 20.6 DEG. C  |
| RELATIVE HUMIDITY                                | 10 - 70 %               | 63.0 %       |
| IMPACT VELOCITY                                  | 5.95 - 6.19 M/S         | 6.05 M/S     |
| PENDULUM<br>DECELERATION                         | 10 MS   17.20 - 21.20 G | 18.10 G      |
|  | 20 MS   14.00 - 19.00 G | 16.16 G      |
|  | 30 MS   11.00 - 16.00 G | 12.32 G      |
| MAX PENDULUM G                                   | 22 G MAX                | 18.73 G      |
| MAX PENDULUM G ABOVE 30 MS                       | 22 G MAX                | 12.28 G      |
| DECELERATION-TIME CURVE<br>DECAY TIME TO 5 G     | 38 - 46 MS              | 39.36 MS     |
| D PLANE  | MAX   81 - 106 DEG.     | 97.53 DEG.   |
| ROTATION   | TIME   72 - 82 MS       | 74.80 MS     |
| MOMENT ABOUT<br>OCCIPITAL<br>CONDYLE             | MIN   -80.0/-52.9 NM    | -71.59 NM    |
|  | TIME   65 - 79 MS       | 69.76 MS     |
| ROTATION ANGLE-TIME CURVE<br>DECAY TIME TO ZERO  | 147 - 174 MS            | 154.56 MS    |
| NEGATIVE MOMENT-TIME CURVE<br>DECAY TIME TO ZERO | 120 - 148 MS            | 142.80 MS    |

TEST MEETS SPECIFICATIONS

TECHNICIAN Richard L. Van

RUN NUMBER: 071195.1058;2

PART 572-E HYBRID III NECK EXTENSION CALIBRATION  
PENDULUM DECELERATION

TRC TEST NUMBER: 34C1NE1

572E SN34 NECK EXT. CAL01

RUN NUMBER: 040496.1528;2

400

320

240

160

80

0

-80

-20

0

20

40

60

80

100

120

140

160

180

200

200

TIME (MS)

PEAK DATA: 18.74 G @ 8.80 MS; -2.54 G @ 46.08 MS

CHANNEL: PENXG

FILTER: CH. CLASS 60

960314

AS664203

EA12-005

PRODUCED BY SUZUKI MOTOR CORPORATION

C-52

ACCELERATION (G X 10<sup>-1</sup>)

0

80

160

240

320

400

400

320

240

160

80

0

-80

-20

0

20

40

60

80

100

120

140

160

180

200

200

TIME (MS)

PEAK DATA: 18.74 G @ 8.80 MS; -2.54 G @ 46.08 MS

CHANNEL: PENXG

FILTER: CH. CLASS 60

960314

AS664203

EA12-005

PRODUCED BY SUZUKI MOTOR CORPORATION

C-52

ACCELERATION (G X 10<sup>-1</sup>)

0

80

160

240

320

400

400

320

240

160

80

0

-80

-20

0

20

40

60

80

100

120

140

160

180

200

200

TIME (MS)

PEAK DATA: 18.74 G @ 8.80 MS; -2.54 G @ 46.08 MS

CHANNEL: PENXG

FILTER: CH. CLASS 60

960314

AS664203

EA12-005

PRODUCED BY SUZUKI MOTOR CORPORATION

C-52

ACCELERATION (G X 10<sup>-1</sup>)

0

80

160

240

320

400

400

320

240

160

80

0

-80

-20

0

20

40

60

80

100

120

140

160

180

200

200

TIME (MS)

PEAK DATA: 18.74 G @ 8.80 MS; -2.54 G @ 46.08 MS

CHANNEL: PENXG

FILTER: CH. CLASS 60

960314

AS664203

EA12-005

PRODUCED BY SUZUKI MOTOR CORPORATION

C-52

ACCELERATION (G X 10<sup>-1</sup>)

0

80

160

240

320

400

400

320

240

160

80

0

-80

-20

0

20

40

60

80

100

120

140

160

180

200

200

TIME (MS)

PEAK DATA: 18.74 G @ 8.80 MS; -2.54 G @ 46.08 MS

CHANNEL: PENXG

FILTER: CH. CLASS 60

960314

AS664203

EA12-005

PRODUCED BY SUZUKI MOTOR CORPORATION

C-52

ACCELERATION (G X 10<sup>-1</sup>)

0

80

160

240

320

400

400

320

240

160

80

0

-80

-20

0

20

40

60

80

100

120

140

160

180

200

200

TIME (MS)

PEAK DATA: 18.74 G @ 8.80 MS; -2.54 G @ 46.08 MS

CHANNEL: PENXG

FILTER: CH. CLASS 60

960314

AS664203

EA12-005

PRODUCED BY SUZUKI MOTOR CORPORATION

C-52

ACCELERATION (G X 10<sup>-1</sup>)

0

80

160

240

320

400

400

320

240

160

80

0

-80

-20

0

20

40

60

80

100

120

140

160

180

200

200

TIME (MS)

PEAK DATA: 18.74 G @ 8.80 MS; -2.54 G @ 46.08 MS

CHANNEL: PENXG

FILTER: CH. CLASS 60

960314

AS664203

EA12-005

PRODUCED BY SUZUKI MOTOR CORPORATION

C-52

ACCELERATION (G X 10<sup>-1</sup>)

0

80

160

240

320

400

400

320

240

160

80

0

-80

-20

0

20

40

60

80

100

120

140

160

180

200

200

TIME (MS)

PEAK DATA: 18.74 G @ 8.80 MS; -2.54 G @ 46.08 MS

CHANNEL: PENXG

FILTER: CH. CLASS 60

960314

AS664203

EA12-005

PRODUCED BY SUZUKI MOTOR CORPORATION

C-52

ACCELERATION (G X 10<sup>-1</sup>)

0

80

160

240

320

400

400

320

240

160

80

0

-80

-20

0

20

40

60

80

100

120

140

160

180

200

200

TIME (MS)

PART 572-E HYBRID III NECK EXTENSION CALIBRATION  
ROTATION ABOUT BASE OF NECK

TRC TEST NUMBER: 34CINE1

572E SN34 NECK EXT. CAL01

RUN NUMBER: 040496.1528;2

120

90

60


30

0

-30

-60

ANGLE (°)



TIME (MS)

80

100

120

140

160

180

200

PEAK DATA: 36.08 ° @ 73.76 MS; -14.89 ° @ 200.00 MS


CHANNEL: BETA FILTER: CH. CLASS 60

PART 572-E HYBRID III NECK EXTENSION CALIBRATION  
ROTATION ABOUT OCCIPITAL CONDYLE

TRC TEST NUMBER: 34CINE1

572E SN34 NECK EXT. CAL01

RUN NUMBER: 040496.1528,2



CHANNEL: THETA FILTER: CH. CLASS 60 PEAK DATA: 61.46 ° @ 75.04 MS; -21.34 ° @ 198.96 MS


PART 572-E HYBRID III NECK EXTENSION CALIBRATION

TOTAL ROTATION

TRC TEST NUMBER: 34CINE1

572E SN34 NECK EXT. CAL01

RUN NUMBER: 040496.1528;2



CHANNEL: TOTAN FILTER: CH. CLASS 60

PEAK DATA: 97.53 ° @ 74.80 MS; -36.22 ° @ 199.60 MS


PART 572-E HYBRID III NECK EXTENSION CALIBRATION

NECK FORCE X AXIS

TRC TEST NUMBER: 34CINE1

572E SN34 NECK EXT. CAL01

RUN NUMBER: 040496.1528;2



CHANNEL: NEKXF FILTER: CH. CLASS 60

PEAK DATA: 242.60 N @ 188.08 MS; -581.96 N @ 65.08 MS


PART 572-E HYBRID III NECK EXTENSION CALIBRATION

NECK MOMENT Y AXIS

TRC TEST NUMBER: 34C1NE1

572E SN34 NECK EXT. CAL01

RUN NUMBER: 040496.1528;2



PEAK DATA: 25.59 N·M @ 177.36 MS; -61.48 N·M @ 69.84 MS


CHANNEL: NEKYM FILTER: CH. CLASS 60

PART 572-E HYBRID III NECK EXTENSION CALIBRATION  
TOTAL MOMENT ABOUT OCCIPITAL CONDYLE

TRC TEST NUMBER: 34CINE1

572E SN34 NECK EXT. CAL01

RUN NUMBER: 040496.1528,2



CHANNEL: NEKOM FILTER: CH. CLASS 60

PEAK DATA: 29.29 N.M @ 178.48 MS; -71.59 N.M @ 69.76 MS



TRANSPORTATION RESEARCH CENTER INC.

THORAX IMPACT TEST

HYBRID III

16-FEB-96

TRC INC.

TEST NO: 34C1TH2

572E SN34 H.S.THORAX CAL01

| TEST PARAMETER          | HIGH SPEED TEST  | TEST RESULTS |
|-------------------------|------------------|--------------|
|                         | SPECIFICATION    |              |
| TEMPERATURE             | 20.6-22.2 DEG. C | 20.8 DEG. C  |
| RELATIVE HUMIDITY       | 10 - 70 %        | 26.0 %       |
| PENDULUM VELOCITY       | 6.59 - 6.83 M/S  | 6.65 M/S     |
| MAXIMUM DEFLECTION      | 63.5 - 72.6 MM   | 68.3 MM      |
| MAXIMUM RESISTIVE FORCE | 5159 - 5894 N    | 5757. N      |
| INTERNAL HYSTERESIS     | 69% - 85%        | 71.1%        |

TEST MEETS SPECIFICATIONS

TECHNICIAN Richard Le Van


RUN NUMBER: 021696.1507;1

PART 572-E HYBRID III THORAX CALIBRATION  
PENDULUM DECELERATION

TRC TEST NUMBER: 34C1TH2

572E SN34 H.S.THORAX CAL01

RUN NUMBER: 040496.1528,1




CHANNEL: PENXC FILTER: CH. CLASS 180 PEAK DATA: 25.13 G @ 20.24 MS; -0.03 G @ 0.08 MS

PART 572-E HYBRID III THORAX CALIBRATION  
PENDULUM FORCE

TRC TEST NUMBER: 34C1TH2

572E SN34 H.S. THORAX CAL01

RUN NUMBER: 040496.1528;1




CHANNEL: PENXF FILTER: CH. CLASS 180 PEAK DATA: 5757.30 N @ 20.24 MS; -6.72 N @ 0.08 MS

PART 572-E HYBRID III THORAX CALIBRATION  
STERNUM DISPLACEMENT

TRC TEST NUMBER: 34C1TH2

572E SN34 H.S.THORAX\_CAL01

RUN NUMBER: 040496.1528;1




CHANNEL: CSTXD FILTER: CH. CLASS 180 PEAK DATA: 68.38 MM @ 25.76 MS; -0.04 MM @ -9.68 MS

PART 572-E HYBRID III THORAX CALIBRATION  
 CHEST DISPLACEMENT VS PENDULUM FORCE

TRC TEST NUMBER: 34C1TH2 RUN NUMBER: 040496.1528;1

572E SN34 H.S.THORAX CAL01



CHANNEL: CSTXD FILTER: CH. CLASS 180  
 PENXF CH. CLASS 180  
 PEAK DATA: 68.38 MM @ 25.76 MS; -0.04 MM @ -9.68 MS  
 5757.30 N @ 20.24 MS; -6.72 N @ 0.08 MS

TRANSPORTATION RESEARCH CENTER INC.

RIGHT KNEE IMPACT TEST

HYBRID III

11-JUL-95

TRC INC.

TEST NO: 34C1RK1

572E SN34 RIGHT KNEE CAL 01

| TEST PARAMETER                            | SPECIFICATION    | TEST RESULTS |
|---|------------------|--------------|
| TEMPERATURE                               | 18.9-25.6 DEG. C | 20.6 DEG. C  |
| RELATIVE HUMIDITY                         | 10 - 70 %        | 63.0 %       |
| PROBE VELOCITY                            | 2.07 - 2.13 M/S  | 2.11 M/S     |
| PEAK KNEE IMPACT FORCE<br>5.0 KG PENDULUM | 4715 - 5782 N    | 5589.1 N     |

TEST MEETS SPECIFICATIONS


TECHNICIAN

*Richard LeVan*

RUN NUMBER: 071195.1244;1

PART 572-E HYBRID III RIGHT KNEE CALIBRATION  
PENDULUM DECELERATION (5 KG PEND.)

TRC TEST NUMBER: 34CIRK1      572E SN34 RIGHT KNEE CAL 01      RUN NUMBER: 040496.1528;1




CHANNEL: PENXG      FILTER: CH. CLASS 600      PEAK DATA: 114.23 G @ 2.64 MS; -0.86 G @ 7.92 MS

PART 572-E HYBRID III RIGHT KNEE CALIBRATION  
 PENDULUM FORCE (5 KG PEND.)

TRC TEST NUMBER: 34C1RK1

572E SN34 RIGHT KNEE CAL 01

RUN NUMBER: 040496.1528;1



PEAK DATA: 5589.18 N @ 2.64 MS; -42.00 N @ 7.92 MS

CHANNEL: PENXF FILTER: CH.. CLASS 600



TRANSPORTATION RESEARCH CENTER INC.

LEFT KNEE IMPACT TEST

HYBRID III

11-JUL-95

TRC INC.

TEST NO: 34C1LK1

572E SN34 LEFT KNEE CAL01

| TEST PARAMETER                            | SPECIFICATION    | TEST RESULTS |
|---|------------------|--------------|
| TEMPERATURE                               | 18.9-25.6 DEG. C | 20.6 DEG. C  |
| RELATIVE HUMIDITY                         | 10 - 70 %        | 63.0 %       |
| PROBE VELOCITY                            | 2.07 - 2.13 M/S  | 2.10 M/S     |
| PEAK KNEE IMPACT FORCE<br>5.0 KG PENDULUM | 4715 - 5782 N    | 5684.2 N     |

TEST MEETS SPECIFICATIONS

TECHNICIAN

*Richard L. ...*

RUN NUMBER: 071195.1240;2


PART 572-E HYBRID III LEFT KNEE CALIBRATION  
 PENDULUM DECELERATION (5 KG PEND.)

TRC TEST NUMBER: 34CILKI

572E SN34 LEFT KNEE CAL01

RUN NUMBER: 040496.1528;2

150



-30

-20

0

40

60

80

100

120

140

160

180

200

TIME (MS X 10<sup>-1</sup>)


CHANNEL: PENXG

FILTER: CH. CLASS 600

PEAK DATA: 116.17 G @ 2.64 MS; -0.84 G @ 7.68 MS

PART 572-E HYBRID III LEFT KNEE CALIBRATION  
 PENDULUM FORCE (5 KG PEND.)

TRC TEST NUMBER: 34CILKI  
 572E SN34 LEFT KNEE CAL01  
 RUN NUMBER: 040496.1528;2



CHANNEL: PENXF FILTER: CH. CLASS 600  
 PEAK DATA: 5684.20 N @ 2.64 MS; -41.11 N @ 7.68 MS

Appendix D

Miscellaneous Test Information

Sign Convention  
NHTSA Data Tape Reference Guide

Accelerometers:

+X: Forward

+Y: Leftward

+Z: Upward

Potentiometers:

+Chest longitudinal deflection: Outward

+Chest lateral deflection: Leftward

+Seat belt displacement: Outward

+Seat belt extension: Elongation

+Knee slider displacement: Distance between femur and tibia

increased

(in relation to a seated dummy)

Load cells:

+Femur force: Tension

+Seat belt force: Tension

+Barrier force: Tension

Neck load cells:

+X force: Head pushed forward

+y force: Head pushed leftward

+Z force: Head pulled upward (tension on neck)

+X moment: Right ear rotating toward right shoulder

+Y moment: Chin rotating toward chest

+Z moment: Chin rotating toward left shoulder

Tibia load cells:

+X force: Tension

+Y force: Tension

+Z force: Tension

+X moment: Bottom of tibia moving leftward

+Y moment: Bottom of tibia moving rearward

Frequency Response Classes  
SAE J211 OCT88

| <u>Typical Test Measurements</u>                    | <u>Channel Class</u> |
|---|----------------------|
| <b>Vehicle Structural Accelerations for use in:</b> |                      |
| Total vehicle comparison                            | 60                   |
| Collision simulation input                          | 60                   |
| Component analysis                                  | 600                  |
| Integration for velocity or displacement            | 180                  |
| <b>Barrier Face Forces</b>                          | 60                   |
| <b>Belt Restraint System Loads</b>                  | 60                   |
| <b>Anthropomorphic Test Device</b>                  |                      |
| Head accelerations (linear and angular)             | 1000                 |
| Neck  |                      |
| Forces  | 1000                 |
| Moments   | 600                  |
| Thorax  |                      |
| Spine accelerations                                 | 180                  |
| Rib accelerations                                   | 1000                 |
| Sternum accelerations                               | 1000                 |
| Deflections   | 180                  |
| Lumbar  |                      |
| Forces  | 1000                 |
| Moments   | 1000                 |
| Pelvis  |                      |
| Accelerations                                       | 1000                 |
| Forces  | 1000                 |
| Moments   | 1000                 |
| Femur/Knee/Tibia/Ankle                              |                      |
| Forces  | 600                  |
| Moments   | 600                  |
| Displacements                                       | 180                  |
| <b>Sled Accelerations</b>                           | 60                   |
| <b>Steering Column Loads</b>                        | 600                  |
| <b>Head form Accelerations</b>                      | 1000                 |



U.S. Department  
of Transportation  
**National Highway  
Traffic Safety  
Administration**

400 Seventh Street, S.W.  
Washington, D.C. 20590

NOV 18 1997

IR 1711

Erika Z. Jones, Esq.  
Mayer, Brown & Platt  
2000 Pennsylvania Ave., N.W.  
Washington, D.C. 20006-1882


Re: CAMI, Inc.

Dear Ms Jones:

By Notice Letter dated March 20, 1997, this office informed CAMI Automotive Inc. of Canada ("CAMI") that the National Highway Traffic Safety Administration's ("NHTSA") Office of Vehicle Safety Compliance ("OVSC") had completed its investigation of the manufacture by CAMI, and importation and sale by General Motors Corporation ("GM") and American Suzuki Motor Corporation ("Suzuki"), of model year ("MY") 1996 Geo Tracker and Suzuki Sidekick motor vehicles that failed to comply with Federal Motor Vehicle Safety Standard No. 301, Fuel System Integrity, 49 CFR 571.301. The results of this investigation initially indicated to us that there was reason to believe that CAMI violated 49 U.S.C. §§ 30112(a) and 30115 in its manufacture and sale of these vehicles. Accordingly, we advised CAMI that NHTSA was considering commencing proceedings that could result in the imposition of a civil penalty against CAMI for violation of sections 30112(a) and 30115, and afforded CAMI an opportunity to submit any mitigating information, data, or arguments relevant to the exercise of reasonable care in this matter and to the imposition of a civil penalty. The letter further advised that, upon receipt and evaluation of CAMI's response, a decision would be made either to suggest that CAMI pay a specified sum in settlement of claims pending against it by NHTSA, or to close the case without such payment.

CAMI responded to our Notice Letter on May 12, 1997, and we asked for further information by letter of May 30, 1997. CAMI provided a response to this letter at a meeting held at the agency on June 13, 1997, which was also attended by representatives of Suzuki and CAMI's Japanese parent, Suzuki Motor Corporation. CAMI provided supplemental information on June 26, 1997, in response to questions asked at the meeting.

**AS 279875**



AUTO SAFETY HOTLINE  
(800) 424-9393  
Wash. D.C. Area (202) 366-0123

The facts of this case indicate that three factors may have contributed to the noncompliance: the orientation of the right rear flange gusset to the fuel tank flange, the spacing of the two spot welds which attach each gusset to the flange on the rear of the fuel tank, and the strengthened fuel tank rear support bracket. The first two factors relate to the fuel tank, and the third relates to the rear support bracket.

The fuel tank was manufactured by CAMI's supplier, Prince Metal Products (PMP). During the investigation, after its initial inspection of OVSC's test vehicle, GM wrote OVSC that "the right rear flange gusset did not appear to be oriented square relative to the tank flange, and the spacing of the gusset spot welds appeared to be too close to the flange attachment hole." Further, GM stated that subsequent inspection of fuel tank samples on hand "revealed variation in both the orientation of the gusset on the flange and the spacing of the two spot welds." (GM letter to NHTSA of August 12, 1996).

In cases where the noncompliance of a motor vehicle with a safety standard results from a problem in a component obtained from an outside, independent supplier, NHTSA pays close attention to the relationship between the manufacturer and the supplier in considering the amount, if any, of civil penalty liability. Among the numerous factors that may be relevant to our assessment are the size and sophistication of the companies, the previous history of the relationship, the complexity of the part in question, the quality control procedures in place at the two companies, the data that the supplier provides the manufacturer, and the basis of the manufacturer's certification.

In this instance, the fuel tank and its gussets are items of motor vehicle equipment that are not complex to manufacture, hence not equipment whose quality would normally be dependent upon continuous monitoring. PMP had been supplying fuel tanks and other equipment to CAMI since 1989, manufacturing them to CAMI's specifications, without apparent deviation. CAMI had never returned a fuel tank to PMP for a departure from specifications. CAMI had provided PMP with quality control guidelines, specifying that there be a visual inspection of 100 percent of the gussets after installation, and that spot weld integrity be verified by conducting a pry test on 100 percent of the gussets after spot welding. CAMI does not contend that PMP failed to inspect the fuel tanks according to CAMI's quality control procedures. The target spot weld locations and parallel gusset orientation were illustrated on the engineering drawings that CAMI provided to PMP, without specifying their tolerances. CAMI contends that this is customary within the industry for drawings of fuel tanks and their attachment components. Finally, it is CAMI's position, as stated at the meeting of June 13, that neither CAMI nor PMP ascribed any particular importance to gusset orientation and spacing prior to this investigation. The agency

AS 279876



possesses insufficient data on industry practice with respect to specifying tolerances for fuel tank attachment components to evaluate CAMI's views on this issue.

The rear support bracket was manufactured by CAMI, which redesigned the bracket for MY 1996 in order to accommodate increased vehicle curb weight. Upon its inspection of NHTSA's test vehicle, GM noted that the post test deformation pattern exhibited by the original bracket in rear impacts was noticeably different than the deformation pattern exhibited in rear impacts with the more robust bracket, leading it to conclude that the strengthening of the bracket coupled with the gusset orientation and spot weld spacing was the root cause of NHTSA's test failure.

Offsetting NHTSA's test failure is the fact that CAMI successfully tested two pre-production MY 1996 vehicles with fuel tanks manufactured by PMP for compliance with Standard No. 301 after it redesigned the fuel tank support bracket. Although CAMI did not test production vehicles for compliance with Standard No. 301, the noncompliance occurred only ten days after the redesigned bracket was introduced into production. While we cannot conclude that testing of production vehicles is never required to establish reasonable care, under the specific circumstances of this case, we are not prepared to conclude that CAMI's failure to conduct such tests amounts to a lack of reasonable care.

Finally, although it is not directly related to the issue of reasonable care, we have viewed favorably the fact that CAMI's two principals, General Motors Corporation and Suzuki Motor Corporation, formally determined the existence of a noncompliance and notified the agency of their determinations only four and five weeks after they became aware of the NHTSA test failure.

On the basis of the foregoing, we have decided to close the file without a penalty.

Sincerely,



Enid Rubenstein  
Acting Assistant Chief Counsel  
for Litigation

AS 279877



U.S. Department  
of Transportation  
National Highway  
Traffic Safety  
Administration

400 Seventh St., S.W.  
Washington, D.C. 20590

JUL 24 1997

Sadayuki Hirano  
Director, Quality Assurance  
CAMI Automotive, Inc.  
P.O. Box 1005  
300 Ingersoll street  
Ingersoll, Ontario,  
Canada N5C 4A6

Re: Confidentiality determination; FMVSS 301

Dear Mr. Hirano:

This responds to your letter, dated July 9, 1997, in which you request confidential treatment for certain information relating to a Federal Motor Vehicle Safety Standard (FMVSS) civil penalty notice. Specifically, CAMI requests confidential treatment for:

- all test reports included in Appendix 2 to its letter of June 13, 1997;
- all materials included in response to question 7 in its letter of June 13, 1997;
- all engineering drawings provided during the meeting between CAMI representatives, Suzuki representatives and NHTSA on June 13, 1997;
- the videotape of certain rear barrier and car-to-car crash tests conducted by Suzuki on the Sidekick Tracker; and
- portions of CAMI's follow-up letter of June 26, 1997.

I have decided to grant confidential treatment for this material under Exemption 4 of the Freedom of Information Act, 5 U.S.C. §552(b)(4).


This grant of confidential treatment is subject to certain conditions since the information was submitted pursuant to a compliance investigation by the agency. The information may be disclosed under the authority of 49 U.S.C. §30167(b) and 49 C.F.R. §512.9(a)(2), if the agency decides the disclosure will assist in carrying out the purposes of the National Traffic and Motor Vehicle Safety Act of 1966, as amended.



AS 279878

The information may also be disclosed under 49 C.F.R. §512.8, based upon newly discovered or changed facts, and you must inform the agency of any changed circumstances which may affect the protection of the information (49 C.F.R. §512.4(I)). Prior to the release of information under 49 C.F.R. §512.8 or §512.9, you would be notified in accordance with the procedure established by our regulations.

Sincerely,



Heidi L. Coleman  
Assistant Chief Counsel  
for General Law

AS 279879



U.S. Department  
of Transportation

National Highway  
Traffic Safety  
Administration

400 Seventh Street, S.W.  
Washington, D.C. 20590

IR 1711

Follow up to  
Civil Penalty Notice Letter

MAY 30 1997


Mr. Sadayuki Hirano  
Director, Quality Assurance  
CAMI Automotive, Inc.  
P.O. Box 1005  
300 Ingersoll Street  
Ingersoll, Ontario  
Canada N5C 4A6

By TELEFAX (519) 425-3100

Dear Mr. Hirano:

Thank you for your letter of May 12, 1997, responding to the agency's civil penalty notice letter of March 20, 1997. After reviewing the information you provided, we would like to ask for certain clarifications.

1. We understand that CAMI Automotive, Inc. ("CAMI") is a joint venture between General Motors Corporation ("GM") and Suzuki Motor Corporation ("Suzuki"). Please quantify the respective interests in CAMI of GM and Suzuki. Please provide a general description of the extent to which GM and Suzuki participate, through the loan of employees or otherwise, in the day to day operations of CAMI. With respect to any such personnel who may have participated in the design, manufacture, or quality control procedures relating to the fuel tanks of 1996-model Suzuki Sidekicks and Geo Trackers ("the vehicles"), please provide the title and a brief job description of each such person.
2. Your letter refers to Certification Tests 75-292 and 76-161. Please provide a complete copy of the documentation of each of these tests, including all data analyses and all still photographs, videotapes, and/or films that may have been taken of such tests.
3. Please provide the name and mailing address of each manufacturer that has supplied CAMI with fuel tanks for the vehicles. Identify the manufacturer that supplied the tank that failed NHTSA's compliance test. Also provide the dates on which each such manufacturer began and ended supplying CAMI with such fuel tanks. If the manufacturer also supplied such fuel tanks for model years of the vehicles other than the 1996 model year, please identify each such model year.
4. We are interested in knowing whether CAMI established a manufacturing tolerance for the placement of the fuel tank gussets, or a manufacturing tolerance for the two spot welds that attached the gusset to the tank (collectively referred to as "tolerances."). If the response is



AUTO SAFETY HOTLINE  
(800) 424-9393  
Wash. D.C. Area (202) 366-0123

AS 279880

affirmative, please state the tolerances. If CAMI did not specify tolerances for either the placement of the fuel tank gussets or the spot welds, please inform us as to your understanding of the industry expectation for such tolerances in this type of manufacturing.

5. Please state also whether CAMI provided the manufacturer of the fuel tank for the vehicles with written or oral instructions regarding the manufacturing tolerances discussed in item 4. If written instructions were given, please provide us with a copy of each such instruction together with the date of such instruction. If oral instructions were given, please provide us with a summary of each such instruction and an estimated date for each time that such instruction was given. Identify the recipient of each written or oral instruction. State whether these instructions, written or oral, differed from those to CAMI's suppliers given the manufacturer(s) identified in response to question 3 above for model years other than 1996. Identify any changes in these instructions and explain the reason for the changes.

6. Please provide a copy of the engineering drawings that CAMI furnished to each supplier of the fuel tank used on the vehicles. If CAMI specified tolerances for the gussets and/or spot welds, please highlight the tolerances on the engineering drawings.

7. Your letter refers to CAMI's "internal standards" and their modification following NHTSA's test. Please provide a copy of CAMI's internal standards and quality control procedures regarding manufacture and inspection of the fuel tank for the vehicles as in effect for the 1995 model year, and at the time NHTSA's 1996 model year test vehicle was manufactured on August 31, 1995. Please also provide a copy of these standards and procedures as modified after CAMI was informed of NHTSA's test result.

8. Please describe any procedure that CAMI followed to ensure that the supplier of the fuel tank for the vehicles was adhering to the specifications of the engineering drawings, or the instructions, written or oral, that CAMI may have given regarding the manufacture of the fuel tank. If these procedures involved written assurances or reports from the supplier, or visits by CAMI personnel to the supplier to inspect fuel tanks, indicate the frequency with which such written assurances, reports, or visits occurred in the year preceding August 31, 1995. State the date of the last such assurance, report, or visit before August 31, 1995.

This letter also confirms that a meeting has been scheduled with representatives of Suzuki at agency headquarters on Monday, June 9, 1997, at 9:30 a.m. The meeting will be held in room 7236, 400 Seventh Street, SW, in Washington, D.C. You or other CAMI representatives may wish to attend. If CAMI wishes to attend, but cannot provide the information we seek by the time of the meeting on June 9, we are willing to reschedule the meeting to provide CAMI sufficient time to respond to this letter.

We are sending this letter by FAX to afford you the maximum time possible for response before June 9. Our FAX number is (202) 366-3820. If you have any questions about the information we are seeking or if CAMI would like to be present at any meeting with Suzuki but cannot respond to this letter by the time of the meeting on June 9, please call Taylor Vinson of this Office (202-366-5263). We are furnishing counsel for Suzuki and GM with copies of this letter.

AS 279881

Sincerely,

/s/

Enid Rubenstein  
Acting Assistant Chief Counsel  
for Litigation

✓ cc: Erika Jones, Esq.  
Stephen Selander, Esq.

AS 279882



U.S. Department  
of Transportation  
National Highway  
Traffic Safety  
Administration

400 Seventh Street, S.W.  
Washington, D.C. 20680

Robert B. Weiss, Esq.  
Honigman Miller Schwartz and Cohn  
2290 First National Building  
Detroit, MI 48228-3583

APR 3 1997

Re: IR 1711 Civil Penalty Notice Letter

Dear Mr. Weiss:

We have received your request, on behalf of CAMI Automotive, Inc. ("CAMI") for an extension until May 11, 1997, of time in which to respond to the agency's Civil Penalty Notice Letter of March 20, 1997.

The reason for your request is that the extension will allow CAMI sufficient time for analysis and review in preparing its response to the Notice Letter.

Because General Motors Corporation rather than CAMI was principally involved during the investigation in this matter, we appreciate the need for CAMI to familiarize itself with the agency file that was enclosed with the Notice Letter, and your request is granted.

Sincerely,

Allan J. Kam  
Acting Assistant Chief Counsel  
for Litigation



ALTO SAFETY HOTLINE  
(800) 424-9163  
Wash. D.C. Area (202) 388-0138

AS 279883



U.S. Department  
of Transportation

National Highway  
Traffic Safety  
Administration

400 Seventh Street, S.W.  
Washington, D.C. 20590

MAR 20 1997

NCC-10 ZTV  
IR 1711  
Civil Penalty Notice Letter

CERTIFIED MAIL -- RETURN RECEIPT REQUESTED

Robert B. Weiss, Esq.  
Honigman, Miller, Schwartz and Cohn  
2290 First National Building  
Detroit, MI 48226

Dear Mr. Weiss:


We understand that CAMI Automotive Inc. of Canada ("CAMI") has designated you its agent under 49 CFR 551.45 to receive correspondence from the National Highway Traffic Safety Administration (NHTSA).

The Office of Vehicle Safety Compliance of NHTSA has completed its investigation of the manufacture by CAMI, and importation and sale by General Motors Corporation ("GM") and American Suzuki Motor Corporation ("Suzuki"), of Geo Tracker and Suzuki Sidekick motor vehicles that failed to comply with Federal Motor Vehicle Safety Standard No. 301, Fuel System Integrity, 49 CFR 571.301. I enclose the agency's public file of this investigation, and, in addition, certain materials that GM submitted subject to a claim of confidentiality, which has been granted. GM has partially waived confidentiality, for the limited purpose of permitting NHTSA to provide the documents to CAMI. These materials are Attachments 5, 6, and 7 to GM's letter to the agency of August 12, 1996.

With the conclusion of this investigation, and GM and Suzuki having commenced their notification and remedy campaigns as required by 49 U.S.C. § 30118 et seq., the file has been forwarded to the Office of Chief Counsel for appropriate civil penalty action.

The results of this investigation indicate to the Office of Chief Counsel that there is reason to believe that CAMI violated 49 U.S.C. §§ 30112(a) and 30115. These sections provide in pertinent part:

Section 30112(a) . . . [a] person may not manufacture for sale . . . any motor vehicle . . . manufactured on or after the date an applicable Federal motor vehicle safety standard prescribed under this chapter takes



AS 279884

AUTO SAFETY HOTLINE  
(800) 424-9393  
Wash. D.C. Area (202) 366-0123



effect unless the vehicle . . . complies with the standard and is covered by a certification issued under section 30115 of this title.

Section 30115 . . . A person may not issue the certificate if, in exercising reasonable care, the person has reason to know the certificate is false and misleading in a material respect. . . .

Section 30165(a) of Title 49 provides that:

A person that violates any of sections 30112, 30115 . . . or a regulation prescribed under those sections is liable to the United States Government for a civil penalty of not more than \$1,000 for each violation. A separate violation occurs for each motor vehicle . . . and for each failure . . . to perform an act required by those sections. The maximum penalty under this subsection for a related series of violations is \$800,000.

Section 30112(b)(2)(A) provides that section 30112(a) does not apply to:

a person establishing that the person had no reason to know, despite exercising reasonable care, that a motor vehicle . . . does not comply with applicable motor vehicle safety standards prescribed under this chapter . . . .

This is to advise you that NHTSA is considering commencing proceedings that could result in the imposition of a civil penalty against CAMI for its violation of sections 30112(a) and 30115. CAMI is hereby afforded an opportunity within 20 calendar days of receipt of this letter to submit to the undersigned any mitigating information, data, or arguments relevant to the exercise of reasonable care in this matter and the imposition of a civil penalty. Upon receipt and evaluation of CAMI's response, a decision will be made either to suggest that CAMI pay a specified sum in settlement of claims pending against it by NHTSA, or to close the case without such payment.

In determining the settlement sum, section 30165(c) requires that "the appropriateness of the penalty or compromise to the size of the business of the person charged and the gravity of the violation" shall be considered. Therefore, CAMI's response should also address these issues.

AS 279885

If you have any questions concerning this matter, you may call Taylor Vinson of this office at (202) 366-5263.

Sincerely,



Enid Rubenstein  
Acting Assistant Chief Counsel  
for Litigation


Enclosure

AS 279886

# MEMO TO FILE

Subject: Action: Technical Investigation Complete/Case  
Transfer to OCC, 1996 Geo Tracker/Suzuki  
Sidekick, FMVSS No. 301

Date: JAN 9 1997

From:   
James A. Jones  
Safety Compliance Engineer

Concurrence: 

To: File IR 1711

## SYNOPSIS

On May 17, 1996, a 1996 model year Geo Tracker 4-door (VIN 2CNBJ1362T6905729) sport utility vehicle was tested to the rear impact requirements of Federal Motor Vehicle Safety Standard (FMVSS) No. 301, "Fuel System Integrity," at Calspan in Buffalo, New York. The vehicle spilled 19.7 oz of stoddard solvent in the 5 minute period immediately following the 29.5 mph rear impact by the moving barrier. It continued to leak at a rate of 1.5 oz/minute for the next 25 minutes. On May 31, 1996, General Motors Corporation (GM) and Suzuki representatives inspected the tested vehicle at Calspan. Subsequently, a information request letter (IR 1711) was sent to GM on June 19, 1996. A response was received on August 12, 1996.

## MANUFACTURER'S RESPONSE

The following is a brief summarization of GM's response to the IR request;

### A. Certification Tests

GM stated that the Tracker is produced by CAMI Automotive Inc., a joint operation between GM and Suzuki Motor Corporation (Suzuki). Suzuki is responsible for performing the necessary certification tests to verify compliance. GM provided data which indicate a number of frontal, oblique, lateral and rear impact tests (including moving deformable barrier tests and vehicle to vehicle rear impact) were performed. Five rear impact tests were conducted at speeds greater than 30 mph (see Attachment 1).

### B. Total Production of affected vehicles

GM/Suzuki identified 18,121, 1996 Geo Tracker 4-door vehicles and 4,325, 1996 Suzuki Sidekick 4-door vehicles produced from August 23, 1995 through June 21, 1996 that have the same fuel system components and design as the vehicle in the NHTSA compliance test.

### C. Production changes made to subject vehicle which may affect conformance to the standard:

GM stated that there were two changes made to the Tracker fuel system design. The first change, effective 8/21/95, involved strengthening of the fuel tank mounting bracket to accommodate an increase in curb weight for 1996 model year vehicles. The second change, effective 6/21/96, involved the corrective action; the installation of new gussets placed between the fuel tank mounting brackets and fuel tank flange. The vehicle tested by NHTSA was produced August 31, 1995 and was subject to the first change.

AS 279887

**D. Manufacturer's Review of the Compliance Test Conduct**

GM/Suzuki reviewed the compliance test, test report and film and concluded that the test was conducted properly. GM/Suzuki representatives confirmed that the fuel system fluid spillage came from a puncture of the fuel tank rear surface by a tank flange reinforcement gusset at the right rear attachment of the tank to the vehicle.

**E. Corrective Action**

On June 21, 1996, CAMI introduced into production, a modified gusset with a rolled, broad angled surface on the side nearest the tank wall to prevent puncture of the tank (see Attachment 2). These new gussets act as reinforcements for the tank's rear flange and will replace the original gussets on both right and left rear tank mounts. In addition, GM stated that CAMI has modified its gusset attachment tooling to assure gusset orientation and spacing of the spot welds during manufacture. GM, also stated that inspection of every gusset has been implemented.

On June 28, 1996, GM initiated a recall and remedy campaign to address all the affected Geo vehicles (Suzuki initiated a recall of Sidekick models on July 2, 1996). The service procedure instructs dealers to add (2) new gussets at the tank rear attachments without removing the original welded gussets (see Attachment 3).

**F. Root Cause - Analysis**

**I. GM's Preliminary Analysis**

GM stated that its inspection at Calspan, on May 31, 1996, helped to focus the investigation which led to the following conclusions;

- a. The forward corner of the tank flange reinforcement (gusset) at the right rear attachment of the tank to the vehicle, punctured the fuel tank rear surface
- b. Impact forces transmitted by the undeformed tank mounting bracket caused localized buckling deformation of the tank flange in the area that should have been covered by the outer portion of the right rear gusset
- c. Localized deformation contributed to partial separation between flange and outer portion of the gussets, thus exposing the outboard forward corner of the gusset which penetrated the tank wall
- d. To a lesser extent, separation was apparent on the left side, as well, but no penetration was evident

**AS 279888**

## II. Root Cause Determination:

- a. Gusset Orientation - GM inspected a number of 1996 Geo Tracker 4-door fuel tanks and found manufacturing variability in the attachment of the gusset to the fuel tank rear flange. Gussets were not aligned square relative to the flange as intended by design (see Attachment 4). Improper orientation or alignment resulted in one end of the gusset being too close to the fuel tank wall.
- b. Gusset Spot Weld Spacing - The gusset is attached to the flange by two spot welds, one on each side of the attachment bolt hole. GM's observations indicate that a shorter spacing between gusset spot welds resulted in more relative separation of the outer portion of the gusset from the flange and allowed more relative movement of the gusset outer portion toward/into the fuel tank wall (see Attachment 5).
- c. Strengthening of the fuel tank rear support bracket - The first change made to the 1996 Geo Tracker fuel system involved strengthening of the support bracket (see Attachment 6). GM noted that the post test deformation pattern exhibited by the original bracket in rear impacts is noticeably different than the deformation pattern exhibited in rear impacts with the more robust bracket (see Attachments 7 & 8). Therefore, GM concluded that strengthening of the bracket, coupled with the gusset problems mentioned above was the root cause of the failure in the NHTSA compliance test.

## REVIEW OF MANUFACTURER'S TEST DATA

### A. Investigative Analysis Tests

GM/Suzuki submitted data from tests performed during its investigative analysis. These tests consist of quasi-static loading tests performed on a number of fuel tanks and full scale rear moving barrier impact tests performed on full production models.

In the static tests, Suzuki varied the following parameters: gusset orientation, gusset spot weld spacing (or pitch) and fuel tank bracket design (see Table 1). Static test C-1 which combined the modified bracket design with the worst case gusset attachment characteristics, yielded results similar to those of the NHTSA compliance test, i.e. partial separation of the gusset outer edge from the tank flange, which in turn, penetrated the fuel tank wall. In test C-2, the nominal gusset orientation configuration yielded no penetration of the gusset into the tank wall. Static tests C-7 and C-8 which combined worst case gusset attachment characteristics with the original bracket design, yielded no penetration as well.

AS 279889

**Table 1 - Quasi-Static Tests**

| Test No. | Fuel Tank Bracket Design | Gusset Orientation | Spot Weld Spacing(Pitch) | Fuel Tank Penetration |
|----------|--------------------------|--------------------|--------------------------|-----------------------|
| C-1      | modified                 | worst case         | narrow-40mm              | yes                   |
| C-2      | modified                 | nominal            | nominal-70mm             | no                    |
| C-7      | original                 | worst case         | narrow-40mm              | no                    |
| C-8      | original                 | worst case         | narrow-40mm              | no                    |

Comparison of post-test photographs show the different deformation patterns exhibited in tests which utilized the modified bracket versus tests which utilized the original bracket. In tests with the original bracket there is buckling and bending (upward) of the fuel tank flange and bending of the bracket itself. Only buckling of the flange (particularly in the area of the outer corners of the gusset) occurs in tests with the modified bracket.

Also, GM/Suzuki submitted data from two full scale FMVSS No. 301 rear impact tests performed on Suzuki vehicles representative of the 1996 Geo Tracker 4-door (see Table 2). The first test utilized the modified bracket design and nominal flange gusset orientation and spot weld spacing based upon the information gathered during fuel tank inspections (see attachments 4 and 5). The second test utilized the original bracket design and worst case gusset orientation and spot weld spacing. The results from these dynamic tests are similar to the results from similarly configured static tests (refer to Table 1 Test Nos. C-2 & C-8).

**Table 2- Dynamic Rear Impact 301 Tests**

| Test No. | Fuel Tank Bracket Design | Gusset Orientation | Spot Weld Spacing(Pitch) | Fuel Tank Penetration |
|----------|--------------------------|--------------------|--------------------------|-----------------------|
| 86-101   | modified                 | nominal            | nominal-70mm             | no                    |
| 86-102   | original                 | worst case         | narrow-40mm              | no                    |

Post-test photographs show expected deformation patterns. In test 86-101, there is very little deformation in the modified (strengthened) bracket. Buckling of the flange at the outer edge of the gusset is evident. In test 86-102, the original bracket is deformed and the tank flange and attached (welded) gusset are bent upward.

These tests substantiate the manufacturer's claim that the combination of off-nominal gusset attachment conditions and modified tank mounting bracket design was the root cause of the fuel spillage.

**AS 279890**

**B. Corrective Action Verification Tests**

For the production fix, CAMI will introduce the new gusset design illustrated in attachment 4. The new gussets have a rolled, broad angled surface on the side nearest the tank wall to prevent puncture of the tank. The new gussets will replace the original gussets (on the bottom side of the flange) at both the left and right side rear fuel tank attachment bolt holes . In addition, CAMI has implemented inspection of each new gusset weld to assure proper orientation and weld spacing (pitch). However, for the recall/remedy, the new gussets will be placed on the opposite side (top side of the flange) of the original gussets. The original gussets welded to the bottom side of the flange remain undisturbed.

- I. Production Change (effective 6-21-96)  
Suzuki performed 2 static tests, 2 dynamic rear impact tests and 1 car to car rear impact test to verify the production change made on 6-21-96 (see Table 4).

**Table 4 - Corrective Action Verification (Production Vehicles)**

| Test No. | Test Type     | Fuel Tank Bracket Design | Gusset Orientation | Spot Weld Spacing(Pitch) | Fuel Spillage |
|----------|---------------|--------------------------|--------------------|--------------------------|---------------|
| C-5      | Static        | modified                 | nominal            | nominal-70mm             | none          |
| C-6      | Static        | modified                 | nominal            | nominal-70mm             | none          |
| 86-122   | RMB -33.6 mph | modified                 | nominal            | nominal-70mm             | none          |
| 86-181   | RMB -30 mph   | modified                 | nominal            | nominal-70mm             | none          |
| 86-253   | C-C -48.8 mph | modified                 | nominal            | nominal-70mm             | none          |

- II. Recall/Remedy  
Suzuki performed 2 static tests, 2 dynamic rear impact tests and 1 car to car rear impact test to verify compliance of the new gusset configuration in the recall/remedy (see Table 5).

**Table 5 - Corrective Action Verification (Recall/Remedy)**

| Test No. | Test Type     | Fuel Tank Bracket Design | Gusset* Orientation   | Spot Weld** Spacing(Pitch) | Fuel Spillage |
|----------|---------------|--------------------------|-----------------------|----------------------------|---------------|
| C-3      | Static        | modified                 | new (nominal)         | narrow-40mm                | none          |
| C-4      | Static        | modified                 |                       | narrow-40mm                | none          |
| 86-121   | RMB -33.6 mph | modified                 | original (worst case) | narrow-40mm                | none          |
| 86-251   | RMB -30 mph   | modified                 |                       | narrow-40mm                | none          |
| 86-202   | C-C - 48 mph  | modified                 |                       | narrow-40mm                | none          |

\* - there are 2 gussets, the new gusset was placed on the top side of the flange with a nominal orientation , the original gusset was welded on the bottom side of the flange using worst case orientation

\*\* - spot weld spacing refers to the original gussets only

**CONCLUSION**

GM has provided the necessary information requested by NHTSA. GM and Suzuki have submitted Part 573 reports of noncompliance (96V-121) and initiated recall and remedy actions.

**AS 279891**

**RECOMMENDATION**

The technical investigation is complete. Last sentence withheld pursuant to 5 USC 552(b)(5)  
#

AS 279892



## ATTACHMENT LIST

- 1 - FMVSS No. 301 Certification Tests
- 2 - Production Fix - Original and Modified Gusset
- 3 - Service Campaign
- 4 - Gusset Orientation
- 5 - Gusset Spot Weld Spacing
- 6 - Original and Modified Fuel Tank Bracket
- 7 - Fuel Tank Deformation with Modified Fuel Tank Bracket
- 8 - Fuel Tank Deformation with Original Fuel Tank Bracket

AS 279893


FMVSS No. 301 Certification Tests  
1996 Tracker 4-door

| Test Config.      | Test No. | Drive | Test Speed(mph) | Test Weight(Kg)* | Test Date | Fuel Spillage |       |          | Remarks               |
|-------------------|----------|-------|-----------------|------------------|-----------|---------------|-------|----------|-----------------------|
|                   |          |       |                 |                  |           | During        | After | Rollover |                       |
| Frontal           | 62-072   | 4WD   | 30.6            | 1489.8           | 02/07/94  | none          | none  | none     |                       |
|                   | 76-091   | 2WD   | 30.2            | 1466.0           | 06/09/95  | none          | none  | none     |                       |
| Oblique Left      | 61-291   | 4WD   | 30.3            | 1489.4           | 01/29/94  | none          | none  | none     |                       |
|                   | 74-112   | 4WD   | 30.2            | 1497.7           | 04/11/95  | none          | none  | none     |                       |
| Oblique Right     | 61-261   | 4WD   | 30.3            | 1493.7           | 01/26/94  | none          | none  | none     |                       |
|                   | 75-121   | 2WD   | 30.1            | 1445.0           | 05/12/95  | none          | none  | none     |                       |
| Side Left         | 62-082   | 4WD   | 20.3            | 1479.8           | 02/08/94  | none          | none  | none     |                       |
| Side Right        | 62-081   | 4WD   | 20.4            | 1478.7           | 02/08/94  | none          | none  | none     |                       |
| Rear              | 63-171   | 4WD   | 34.5            | 1477.5           | 03/17/94  | none          | none  | none     | original tank bracket |
|                   | 75-292   | 4WD   | 33.7            | 1427.8           | 05/29/95  | none          | none  | none     | modified tank bracket |
|                   | 76-161   | 2WD   | 35.0            | 1478.0           | 06/16/95  | none          | none  | none     | modified tank bracket |
|                   | 86-102   | 2WD   | 33.6            | 1422.0           | 06/10/96  | none          | none  | none     | original tank bracket |
|                   | 86-101   | 4WD   | 33.6            | 1472.0           | 06/10/96  | none          | none  | none     | modified tank bracket |
|                   | 5A-181   | 4WD   | 49.4            | 1477.0           | 10/18/93  | none          | none  | none     | original tank bracket |
| Car-to-Car (full) | 77-071   | 4WD   | 49.4            | 1460.0           | 07/01/95  | none          | none  | none     | modified tank bracket |

Note: \* - Test weight includes the weight of two dummies  
Shaded region indicates tests conducted after NHTSA's compliance test failure

AS 279894


# Original Gusset and Modified Gusset



AS 279895


**SERVICE PROCEDURE****Attachment 3**

1. Raise and suitably support vehicle.
2. Support fuel tank with a suitable jack.
3. Slowly remove the two (2) rear fuel tank attachment bolts.
4. Install NEW gussets at each rear attachment locations as shown below.
5. Install rear fuel tank attachment bolts and torque to 35 Nm (26 lb. ft.).
6. Remove fuel tank support jack.
7. Lower vehicle.
8. Install the GM Campaign Identification Label.


**AS 279896**

Location of Fuel Tank Flange Gusset Varies

Attachment 4




GM  
Confidential



AS 279897

Attachment 8

Fuel Tank Deformation With Original Fuel Tank Bracket



AS 279898

Attachments 5, 6, 7 and 9 withheld pursuant to 5 USC 552(b)(4) (See item 7)

AS 279899

MAYER, BROWN & PLATT

2000 PENNSYLVANIA AVENUE, N.W.

WASHINGTON, D.C. 20006-1882

ERIKA Z. JONES  
DIRECT DIAL (202) 778-0642  
ejones@mayerbrown.com

MAIN TELEPHONE  
202-463-2000  
MAIN FAX  
202-861-0473

July 15, 1997

Heidi Lewis Coleman, Esq.  
Assistant Chief Counsel  
National Highway Traffic Safety Administration  
400 Seventh Street, S.W.  
Washington, D.C. 20590

RE: Request for Confidentiality for Certain Documents Provided by CAMI in  
Response to Civil Penalty Notice Letter

Dear Ms. Coleman:

Last week CAMI filed a request for confidentiality of certain documents. The certification in support enclosed with that request was faxed from Japan. The original signed certificate has now arrived, and is enclosed. Please add it to CAMI's package.

We appreciate your courtesy in attending to this matter.

Sincerely,

  
Erika Z. Jones

Enclosure

CHICAGO BERLIN BRUSSELS HOUSTON LONDON LOS ANGELES NEW YORK WASHINGTON  
INDEPENDENT MEXICO CITY CORRESPONDENT: JAUREGUI, NAVARRETE, NADER Y ROJAS  
INDEPENDENT PARIS CORRESPONDENT: LAMBERT ARMENIADES

AS 279900





July 9, 1997

Heidi Lewis Coleman, Esq.  
Assistant Chief Counsel  
National Highway Traffic Safety Administration  
400 Seventh Street, S.W.  
Washington, D.C. 20590

RE: Request for Confidentiality for Certain Documents Provided in Response to  
Civil Penalty Notice Letter

Dear Ms. Coleman:

CAMI recently responded to a letter from the Office of Chief Counsel concerning its consideration of whether to impose a civil penalty related to an FMVSS No. 301 noncompliance in certain MY 1996 Sidekicks/Trackers. The purpose of this letter is to request confidential treatment for certain of the documents and materials provided to the Office in connection with that response. CAMI respectfully requests confidential treatment for the following materials<sup>1/</sup>:

- All Test Reports included in Appendix 2 to its letter of June 13, 1997.
- All materials included in response to question 7 in its letter of June 13, 1997.
- All engineering drawings provided during the meeting between CAMI representatives, Suzuki representatives and NHTSA on June 13, 1997.
- The videotape of certain rear barrier and car-to-car crash tests conducted by Suzuki on the Sidekick/Tracker.
- Portions of CAMI's follow-up letter of June 26, 1997.

A justification for each claim of confidentiality is discussed in turn below.

First, the test reports of certification tests 75-292 and 76-161, as well as test 77-011 (high speed car to car) should be protected from public release. Although CAMI recognizes that NHTSA does not routinely protect manufacturers' certification test reports, an exception

---

<sup>1/</sup> With respect to the first item (test reports), third item (engineering drawings) and fourth item (videotape), these items were provided to NHTSA by CAMI; however, these items are proprietary to Suzuki, one of the CAMI joint venturers. For these items, CAMI respectfully requests confidentiality on behalf of Suzuki.

Heidi Lewis Coleman, Esq.  
July 9, 1997  
Page 2

should be made in this instance, because Suzuki elected to conduct the certification tests at speeds higher than the standard requires. For this reason, the tests served a dual purpose: supporting the certification of compliance with FMVSS No. 301 and providing valuable information to Suzuki and CAMI about the vehicle's performance at speeds higher than required by the standard. With respect to test 77-011, this high speed car-to-car test is a developmental test that is not required by NHTSA regulations. Release of these three test reports would reveal details of Suzuki's internal engineering test procedures beyond those required for FMVSS certification, including procedures developed for evaluating fuel tank integrity. Furthermore, release of the test report of test 77-011 would allow a competitor to duplicate Suzuki's test procedures for high-speed car-to-car testing and would allow a competitor to learn about the vehicle's high-speed crashworthiness, without having to invest in the development of its own procedures or conducting its own reverse engineering, while Suzuki and CAMI would not benefit by obtaining any similar information from its competitors. The test procedures and test results of the three tests are thus entitled to confidential protection. See, e.g., *Worthington Compressors, Inc. v. Costle*, 662 F.2d at 51.

Second, all material provided in response to NHTSA's question 7 in CAMI's letter of June 13, 1997 (Appendices 7-1A, 7-1B, 7-2A, 7-2B, 7-2C, 7-3A, 7-3B, 7-3C, 7-4A, 7-4B, 7-4C, 7-5A and 7-5C) should be protected from public release. These documents identify CAMI's internal standards for parts quality supplied by vendors. These standards are proprietary to CAMI and were developed at CAMI's expense. Release of these standards would permit a competitor to duplicate CAMI's specifications without making the investment ordinarily necessary to develop such standards, while CAMI would obtain no counterpart information from its competitors. The vendor quality specifications should therefore be protected from public release. See *Worthington Compressors, Inc. v. Costle*, 662 F.2d 45, 51 (D.C. Cir. 1981).

Third, the blueprints and drawings provided during the June 13 meeting are entitled to protection pursuant to NHTSA's class determination contained in Appendix B to Part 512.

Fourth, the videotape that includes certification tests 75-292 and 76-161 and high speed car-to-car test 77-011 should be protected from public release. The videotape reveals in detail the precise crush characteristics of the rear of the subject vehicle in barrier and car-to-car testing, all of which were conducted at speeds higher than FMVSS No. 301 requires. These tests are entitled to protection for reasons described in the first justification above, and the videotape illustrating them is likewise protectable.

Fifth, the portions of CAMI's letter of June 26, 1997 that discuss CAMI's processes for evaluating the performance of its suppliers should be protected from public release. Although CAMI initially identified the entire June 26, 1997 letter as confidential, CAMI now

AS 279902

Heidi Lewis Coleman, Esq.  
July 9, 1997  
Page 3

believes that certain portions of that letter could safely be released without causing competitive harm to CAMI. CAMI therefore limits this request for confidential treatment to the matter which has been bracketed in the attached copy. A redacted version of the letter is also attached.

The redacted portions of the June 26, 1997 letter are entitled to protection as confidential business information because they contain a candid discussion of CAMI's various quality control processes by which it evaluates its vendors and the process by which it accepts vendor parts and detects potential vendor part problems during the manufacturing process. These processes are proprietary to CAMI. Release of the description of these processes would permit a competitor to duplicate CAMI's processes without making the investment ordinarily necessary to develop such procedures, while CAMI would obtain no counterpart information from its competitors. The vendor quality specifications should therefore be protected from public release. See *Worthington Compressors, Inc. v. Costle*, 662 F.2d 45, 51 (D.C. Cir. 1981). Furthermore, while every manufacturer presumably has some level of quality control, the exact level of attention a manufacturer pays to different steps in the quality process will differ from company to company. Release of this much detail about CAMI's processes would permit its competitors to know where CAMI is expending resources for supervision of vendor parts and where it is not, to CAMI's competitive detriment. Disclosure of information that would allow a competitor to base future pricing or product revision decisions in such a way as to take advantage of CAMI's costs of quality control is entitled to protection pursuant to 49 C.F.R. Part 512. See, e.g., *Gulf & Western Industries, Inc. v. United States*, 615 F.2d 527, 529-530 and n.6 (D.C. Cir. 1979). Also see *Braintree Elec. Light Dep't. v. Department of Energy*, 494 F.Supp. 287, 290 (D.D.C. 1980)(financial information from which a competitor could "determine another's cost of doing business" would cause "substantial" competitive harm).

Finally, a separate basis exists on which to protect all of the confidential CAMI documents. As these documents were all submitted to NHTSA in voluntary compliance with the agency's letter, and because CAMI does not "customarily release to the public" any of the attached confidential documents, NHTSA should protect the documents. *Critical Mass Energy Project v. Nuclear Regulatory Commission*, 975 F.2d 871, 880 (D.C. Cir. 1992), cert. den. 113 S.Ct. 1579 (1993).

AS 279903

Heidi Lewis Coleman, Esq.  
July 9, 1997  
Page 4

\* \* \*

CAMI has appended to this letter the certification required by your regulations.

Sincerely,

*Sadayuki Hirano*  
Sadayuki Hirano  
Director, Quality Assurance

Attachments

cc: Enid Rubenstein, Esq.  
Acting Assistant Chief Counsel for Litigation

AS 279904



June 26, 1997

PUBLIC VERSION

Enid Rubenstein, Esq.  
Acting Assistant Chief Counsel  
for Litigation  
National Highway Traffic Safety Administration  
400 Seventh Street, S.W.  
Washington, D.C. 20590

Dear Ms. Rubenstein:

Thank you for meeting with us on June 13. In this regard, our letter responds to questions raised at the meeting regarding the reasons why CAMI reasonably had confidence in the quality of parts manufactured by Prince Metal Products (PMP), the fuel tank supplier for the subject vehicles.

PMP is one of several subsidiaries of National Automobile Radiator Manufacturing Company (NARMCO), a major, multiplant supplier of automotive parts to many vehicle manufacturers. NARMCO has been in the automotive parts manufacturing business for more than 50 years, making large stamped panels and welded parts. NARMCO has a particular specialty of manufacturing deep drawn parts, such as oil pans and fuel tanks. Specifically with respect to automotive fuel tanks, NARMCO has been making vehicle fuel tanks for several manufacturers since 1972, either directly or through one of its subsidiaries. In 1988, NARMCO established a new subsidiary, Prince Metal Products (PMP), which manufactures fuel tanks and other stamped and/or welded parts. CAMI has purchased fuel tanks manufactured by PMP since 1989. [

CONFIDENTIAL

] Thus, CAMI was reasonable in relying on the extensive experience of PMP and its parent company, NARMCO, in manufacturing fuel tanks and other automotive parts for several vehicle manufacturers and, specifically, for CAMI.

NARMCO and PMP have quality experience with CAMI that is in line with their competitors in the complex metal parts segment of the automotive parts business. PMP last year obtained QS 9000 certification at the 9001 and 9002 levels and ISO 9002 certification. ISO 9002 is the International Standards Organization's standard for quality systems in manufacturing. Earning QS 9000 and ISO 9002 qualification requires that the manufacturing facility demonstrate to the satisfaction of an outside auditor that it has achieved certain rigorous standards for quality control in the manufacturing process.

Enid Rubenstein, Esq.  
June 26, 1997  
Page 3

ENTIRE  
PAGE  
CONFIDENTIAL

]

AS 279906

Enid Rubenstein, Esq.  
June 26, 1997  
Page 2

ENTIRE  
PAGE  
CONFIDENTIAL

┌

AS 279907

Enid Rubenstein, Esq.  
June 26, 1997  
Page 4

\* \* \*

For all of the above reasons, CAMI believes that it was reasonable to rely on the quality of PMP manufactured parts. We trust this letter has sufficiently answered the questions raised at our June 13 meeting.

Sincerely,

*Sadayuki Hirano* / *kh*

Sadayuki Hirano  
Director, Quality Assurance

AS 279908





CONFIDENTIAL VERSION

June 26, 1997

Enid Rubenstein, Esq.  
Acting Assistant Chief Counsel  
for Litigation  
National Highway Traffic Safety Administration  
400 Seventh Street, S.W.  
Washington, D.C. 20590

Dear Ms. Rubenstein:

Thank you for meeting with us on June 13. In this regard, our letter responds to questions raised at the meeting regarding the reasons why CAMI reasonably had confidence in the quality of parts manufactured by Prince Metal Products (PMP), the fuel tank supplier for the subject vehicles.

PMP is one of several subsidiaries of National Automobile Radiator Manufacturing Company (NARMCO), a major, multiplant supplier of automotive parts to many vehicle manufacturers. NARMCO has been in the automotive parts manufacturing business for more than 50 years, making large stamped panels and welded parts. NARMCO has a particular specialty of manufacturing deep drawn parts, such as oil pans and fuel tanks. Specifically with respect to automotive fuel tanks, NARMCO has been making vehicle fuel tanks for several manufacturers since 1972, either directly or through one of its subsidiaries. In 1988, NARMCO established a new subsidiary, Prince Metal Products (PMP), which manufactures fuel tanks and other stamped and/or welded parts. CAMI has purchased fuel tanks manufactured by PMP since 1989. [At this time, CAMI purchases 24 different parts from PMP, including large stamped panels, fender aprons, fuel inlet boxes, back door hinge reinforcements, bracket suspensions, and other stamped and/or welded parts.] Thus, CAMI was reasonable in relying on the extensive experience of PMP and its parent company, NARMCO, in manufacturing fuel tanks and other automotive parts for several vehicle manufacturers and, specifically, for CAMI.

NARMCO and PMP have quality experience with CAMI that is in line with their competitors in the complex metal parts segment of the automotive parts business. PMP last year obtained QS 9000 certification at the 9001 and 9002 levels and ISO 9002 certification. ISO 9002 is the International Standards Organization's standard for quality systems in manufacturing. Earning QS 9000 and ISO 9002 qualification requires that the manufacturing facility demonstrate to the satisfaction of an outside auditor that it has achieved certain rigorous standards for quality control in the manufacturing process.

Enid Rubenstein, Esq.  
June 26, 1997  
Page 2

ENTIRE  
PAGE  
CONFIDENTIAL

[In CAMI's own experience, PMP over the years has been a reliable supplier of fuel tanks and other automotive parts, and has demonstrated that it has good systems for manufacturing quality components. When CAMI routinely audited PMP (as it does all major suppliers from time to time), CAMI confirmed that PMP has supplier quality systems that rated within the acceptable category of suppliers. Over the years since CAMI has used PMP as a supplier for fuel tanks and other parts, CAMI has considered PMP's performance to be in line with the expected performance from suppliers of major metal parts. That is, the instances of parts needing to be returned to PMP for any reason has been consistent with CAMI's experience with other vendors of complex metal parts.

You specifically asked us to review the circumstances in which fuel tanks were returned to PMP by CAMI as a result of possible flaws in PMP-manufactured fuel tanks discovered by CAMI during the vehicle assembly process. You asked us to report on fuel tanks returned for this reason during the two-year time period immediately preceding, and including, the date of the manufacture of the vehicle tested by NHTSA (September 1, 1993 through August 31, 1995). We have confirmed that there were no instances of fuel tanks returned to PMP by CAMI for reasons attributed to significant problems noted during the vehicle assembly process in that time period. A "significant" problem would have been a departure from specifications; a manufacturing discrepancy introducing problems on the vehicle assembly line (such as misaligned mounting holes); or any issue raising a question of the safe performance of the product in the field. According to CAMI's records, 36 fuel tanks were returned to PMP in the two-year window for minor reasons, out of approximately 141,800 fuel tanks purchased from PMP. Minor reasons for rejecting these tanks included shipping damage, paint damage and malfunctioning electrical connectors. In CAMI's experience with vendors of complex metal parts, this is an acceptable record of return parts.

CAMI has a quality control process known as "Defective Material Corrective Action Reports" (DMCAR's). The DMCAR process documents defective materials identified by CAMI during the vehicle manufacturing process, and requests a plan for a corrective action from the parts vendor. CAMI issues a DMCAR for a single instance of a flaw in a safety-related characteristic; and for non-safety related defects (such as cuts in seat fabrics), a DMCAR is issued if three instances of the defect are observed in an eight-hour shift.

CAMI reviewed the DMCAR's issued for parts manufactured by PMP in the two years preceding the date of the manufacture of the NHTSA-tested vehicle, and confirmed that, during that time period, no DMCAR's were issued for any PMP-manufactured fuel tank, no DMCAR's were issued to PMP for any mislocated welding on any part (including PMP-manufactured parts other than fuel tanks) and no DMCAR's were issued to PMP for misalignment of any welded part (including PMP-manufactured parts other than fuel tank components). 13 DMCAR's were issued to PMP for parts other than fuel tanks, such as rust found in a front body side panel,

AS 279910

Enid Rubenstein, Esq.  
June 26, 1997  
Page 3

ENTIRE  
PAGE  
CONFIDENTIAL

misformed shape in the stamped metal of an inner back panel, and similar defects. None of the 13 DMCAR's issued to PMP in that time period reflected a repeat problem, suggesting that PMP responded promptly to correct even the minor issues that arose. In CAMI's experience, the volume and type of DMCAR's issued to PMP were in line with those issued to other vendors of complex parts.

You also asked that we briefly summarize CAMI's procedure for acceptance of vendor parts and for detecting potential vendor part problems during the vehicle manufacturing process. The first opportunity to observe potential problems with vendor parts is at the receiving department, where vendor parts are accepted by CAMI personnel. Fuel tanks from PMP are delivered by truck on racks, between two and four times per day, depending upon expected vehicle production volumes that day. The receiving department employee will confirm the delivered volume and conduct a cursory visual check for shipping damage.

Assuming no shipping damage is observed, the rack is accepted and held in receiving until needed on the assembly line. At that point, the rack is moved to the assembly line. The assembly worker removes a fuel tank from the rack for each chassis, and bolts the tank to the chassis. At this time, an obvious manufacturing problem in the fuel tank (such as misaligned mounting holes or unpainted shell) would be noted by the assembly worker, and the tank would be rejected.

Once the chassis manufacturing is completed, each chassis receives a visual inspection for such items as security of bolts, presence of all attachment items (such as hoses), security of all attachments, and similar items. This inspection does not include the underbody of the vehicle, but enables verification of appropriate installation of parts visible from the top of the chassis.

After the passenger compartment is added to the completed chassis, the vehicle passes over an inspection pit in which a worker inspects the underbody of each vehicle for visually observable attachment problems. Then, a small amount of fuel is added (approximately 6 liters for the Sidekick/Tracker) and the car is started. It is driven over a second inspection pit, from which the front wheels are aligned. Although this second inspection is not designed to inspect for fuel tank integrity, it provides another opportunity by which fuel leaks can be observed, because the inspection worker in the pit will immediately notice any odor or liquid evidence of fuel leakage.

Each CAMI-built vehicle receives a final inspection. Part of this inspection includes a chassis dynamometer test (up to 70 mph), followed by underbody inspection to confirm vehicle functions. This inspection provides another opportunity to discern any fuel leakage or serious fuel tank attachment problems before the vehicle is shipped. ]

AS 279911

Enid Rubenstein, Esq.  
June 26, 1997  
Page 4

\* \* \*

For all of the above reasons, CAMI believes that it was reasonable to rely on the quality of PMP manufactured parts. We trust this letter has sufficiently answered the questions raised at our June 13 meeting.

Sincerely,

*Sadayuki Hirano* / *kh*


Sadayuki Hirano  
Director, Quality Assurance

AS 279912

Certificate in Support of Request for Confidentiality

I, Sadayuki Hirano, pursuant to the provisions of 49 C.F.R. Part 512, state as follows:

- (1) I am the Director, Quality Assurance and I am authorized by CAMI Automotive Inc. to execute documents on its behalf.
  - (2) The information contained in the documents identified in the attached letter are confidential and proprietary data and were submitted with the claim that it is entitled to confidential treatment under 5 U.S.C. § 552(b)(4).
  - (3) I have personally inquired of the responsible CAMI personnel who have authority in the normal course of business to release the information for which a claim of confidentiality has been made to ascertain whether such information has ever been released outside CAMI.
  - (4) Based upon such inquiries, to the best of my knowledge, information and belief the information for which CAMI has claimed confidential treatment has never been released or become available outside CAMI, except in the normal course of business in dealing with its suppliers, all of whom are asked to protect the confidentiality of the quality control procedures, and expect for ordinary business dealing with CAMI's joint venture partners, Suzuki and General Motors.
  - (5) I make no representations beyond those contained in this certificate and in particular, I make no representations as to whether this information may become available outside CAMI because of unauthorized or inadvertent disclosure except as stated in Paragraph 4.
  - (6) I certify under penalty of perjury that the foregoing is true and correct.
- Executed on this the 8<sup>th</sup> day of July 1997.



Sadayuki Hirano  
Director, Quality Assurance

AS 279913



June 26, 1997

**ENTIRE LETTER IS  
CONFIDENTIAL**

Enid Rubenstein, Esq.  
Acting Assistant Chief Counsel  
for Litigation  
National Highway Traffic Safety Administration  
400 Seventh Street, S.W.  
Washington, D.C. 20590

Dear Ms. Rubenstein:

Thank you for meeting with us on June 13. In this regard, our letter responds to questions raised at the meeting regarding the reasons why CAMI reasonably had confidence in the quality of parts manufactured by Prince Metal Products (PMP), the fuel tank supplier for the subject vehicles.

PMP is one of several subsidiaries of National Automobile Radiator Manufacturing Company (NARMCO), a major, multiplant supplier of automotive parts to many vehicle manufacturers. NARMCO has been in the automotive parts manufacturing business for more than 50 years, making large stamped panels and welded parts. NARMCO has a particular specialty of manufacturing deep drawn parts, such as oil pans and fuel tanks. Specifically with respect to automotive fuel tanks, NARMCO has been making vehicle fuel tanks for several manufacturers since 1972, either directly or through one of its subsidiaries. In 1988, NARMCO established a new subsidiary, Prince Metal Products (PMP), which manufactures fuel tanks and other stamped and/or welded parts. CAMI has purchased fuel tanks manufactured by PMP since 1989. At this time, CAMI purchases 24 different parts from PMP, including large stamped panels, fender aprons, fuel inlet boxes, back door hinge reinforcements, bracket suspensions, and other stamped and/or welded parts. Thus, CAMI was reasonable in relying on the extensive experience of PMP and its parent company, NARMCO, in manufacturing fuel tanks and other automotive parts for several vehicle manufacturers and, specifically, for CAMI.

NARMCO and PMP have quality experience with CAMI that is in line with their competitors in the complex metal parts segment of the automotive parts business. PMP last year obtained QS 9000 certification at the 9001 and 9002 levels and ISO 9002 certification. ISO 9002 is the International Standards Organization's standard for quality systems in manufacturing. Earning QS 9000 and ISO 9002 qualification requires that the manufacturing facility demonstrate to the satisfaction of an outside auditor that it has achieved certain rigorous standards for quality control in the manufacturing process.

Enid Rubenstein, Esq.  
June 26, 1997  
Page 2

In CAMI's own experience, PMP over the years has been a reliable supplier of fuel tanks and other automotive parts, and has demonstrated that it has good systems for manufacturing quality components. When CAMI routinely audited PMP (as it does all major suppliers from time to time), CAMI confirmed that PMP has supplier quality systems that rated within the acceptable category of suppliers. Over the years since CAMI has used PMP as a supplier for fuel tanks and other parts, CAMI has considered PMP's performance to be in line with the expected performance from suppliers of major metal parts. That is, the instances of parts needing to be returned to PMP for any reason has been consistent with CAMI's experience with other vendors of complex metal parts.

You specifically asked us to review the circumstances in which fuel tanks were returned to PMP by CAMI as a result of possible flaws in PMP-manufactured fuel tanks discovered by CAMI during the vehicle assembly process. You asked us to report on fuel tanks returned for this reason during the two-year time period immediately preceding, and including, the date of the manufacture of the vehicle tested by NHTSA (September 1, 1993 through August 31, 1995). We have confirmed that there were no instances of fuel tanks returned to PMP by CAMI for reasons attributed to significant problems noted during the vehicle assembly process in that time period. A "significant" problem would have been a departure from specifications; a manufacturing discrepancy introducing problems on the vehicle assembly line (such as misaligned mounting holes); or any issue raising a question of the safe performance of the product in the field. According to CAMI's records, 36 fuel tanks were returned to PMP in the two-year window for minor reasons, out of approximately 141,800 fuel tanks purchased from PMP. Minor reasons for rejecting these tanks included shipping damage, paint damage and malfunctioning electrical connectors. In CAMI's experience with vendors of complex metal parts, this is an acceptable record of return parts.

CAMI has a quality control process known as "Defective Material Corrective Action Reports" (DMCAR's). The DMCAR process documents defective materials identified by CAMI during the vehicle manufacturing process, and requests a plan for a corrective action from the parts vendor. CAMI issues a DMCAR for a single instance of a flaw in a safety-related characteristic; and for non-safety related defects (such as cuts in seat fabrics), a DMCAR is issued if three instances of the defect are observed in an eight-hour shift.

CAMI reviewed the DMCAR's issued for parts manufactured by PMP in the two years preceding the date of the manufacture of the NHTSA-tested vehicle, and confirmed that, during that time period, no DMCAR's were issued for any PMP-manufactured fuel tank, no DMCAR's were issued to PMP for any mislocated welding on any part (including PMP-manufactured parts other than fuel tanks) and no DMCAR's were issued to PMP for misalignment of any welded part (including PMP-manufactured parts other than fuel tank components). 13 DMCAR's were issued to PMP for parts other than fuel tanks, such as rust found in a front body side panel,

AS 279915

Enid Rubenstein, Esq.  
June 26, 1997  
Page 3

misformed shape in the stamped metal of an inner back panel, and similar defects. None of the 13 DMCAR's issued to PMP in that time period reflected a repeat problem, suggesting that PMP responded promptly to correct even the minor issues that arose. In CAMI's experience, the volume and type of DMCAR's issued to PMP were in line with those issued to other vendors of complex parts.

You also asked that we briefly summarize CAMI's procedure for acceptance of vendor parts and for detecting potential vendor part problems during the vehicle manufacturing process. The first opportunity to observe potential problems with vendor parts is at the receiving department, where vendor parts are accepted by CAMI personnel. Fuel tanks from PMP are delivered by truck on racks, between two and four times per day, depending upon expected vehicle production volumes that day. The receiving department employee will confirm the delivered volume and conduct a cursory visual check for shipping damage.

Assuming no shipping damage is observed, the rack is accepted and held in receiving until needed on the assembly line. At that point, the rack is moved to the assembly line. The assembly worker removes a fuel tank from the rack for each chassis, and bolts the tank to the chassis. At this time, an obvious manufacturing problem in the fuel tank (such as misaligned mounting holes or unpainted shell) would be noted by the assembly worker, and the tank would be rejected.

Once the chassis manufacturing is completed, each chassis receives a visual inspection for such items as security of bolts, presence of all attachment items (such as hoses), security of all attachments, and similar items. This inspection does not include the underbody of the vehicle, but enables verification of appropriate installation of parts visible from the top of the chassis.

After the passenger compartment is added to the completed chassis, the vehicle passes over an inspection pit in which a worker inspects the underbody of each vehicle for visually observable attachment problems. Then, a small amount of fuel is added (approximately 6 liters for the Sidekick/Tracker) and the car is started. It is driven over a second inspection pit, from which the front wheels are aligned. Although this second inspection is not designed to inspect for fuel tank integrity, it provides another opportunity by which fuel leaks can be observed, because the inspection worker in the pit will immediately notice any odor or liquid evidence of fuel leakage.

Each CAMI-built vehicle receives a final inspection. Part of this inspection includes a chassis dynamometer test (up to 70 mph), followed by underbody inspection to confirm vehicle functions. This inspection provides another opportunity to discern any fuel leakage or serious fuel tank attachment problems before the vehicle is shipped.

AS 279916



Enid Rubenstein, Esq.  
June 26, 1997  
Page 4

\* \* \*

For all of the above reasons, CAMI believes that it was reasonable to rely on the quality of PMP manufactured parts. We trust this letter has sufficiently answered the questions raised at our June 13 meeting.

Sincerely,

*Sadayuki Hirano* / *KH*

Sadayuki Hirano  
Director, Quality Assurance

AS 279917



June 13, 1997

Enid Rubenstein  
Acting Assistant Chief Counsel for Litigation  
National Highway Traffic Safety Administration  
400 Seventh Street, S.W.  
Washington, D.C. 20590

Re: NCC-10 ZTV  
IR 1711  
Response to Civil Penalty Notice Letter

Dear Ms. Rubenstein:

CAMI has received your letter of May 30, 1997, regarding follow-up to the civil penalty notice letter of March 20, 1997. The following information is provided in response to your request for clarification. All documents to which this letter refers are attached to this letter, with appendix numbers assigned to correspond to the number of NHTSA's question calling for the document or the number of the response in which the item is discussed. The videotape and drawings to which this letter refers will be provided at the meeting on June 13. Certain items have been marked as Confidential, and supporting justification pursuant to 49 CFR Part 512 will be submitted under separate cover shortly.

1. CAMI Automotive Inc. was established in 1986 at Ingersoll, Ontario, Canada, as a joint venture automotive manufacturing company between General Motors of Canada Limited, Oshawa, Ontario, Canada and Suzuki Motor Corporation, Hamamatsu, Japan. With regard to the respective interest in CAMI, the responsibility is shared equally between General Motors and Suzuki.

The extent of participation in day to day activities is as follows:  
GM and Suzuki have provided their employees at the management level to support production, product and process engineering, quality and other administrative activities at CAMI. Suzuki has also provided technical advisors to assist in quality, production and production engineering.

Suzuki also has design engineering staff at CAMI to support engineering matters.

Design and development of the vehicles manufactured at CAMI is done by Suzuki in Hamamatsu, Japan. CAMI is responsible for manufacturing and production quality of the vehicle.

The following CAMI production and quality positions were filled with GM or Suzuki personnel in 1995-1996:

|            |        |  |
|------------|--------|--|
| Design     | Suzuki | <ul style="list-style-type: none"><li>• Assistant Manager of Suzuki Engineering<br/>Supporting design issues</li></ul>                   |
| Production | GM     | <ul style="list-style-type: none"><li>• Vice President of Production<br/>Responsibility for overall production</li></ul>                 |
|            | GM     | <ul style="list-style-type: none"><li>• Director of Production<br/>Responsibility for production</li></ul>                               |
| Quality    | Suzuki | <ul style="list-style-type: none"><li>• Director of Quality Assurance<br/>Responsibility for Final Vehicle Quality</li></ul>             |
|            | GM     | <ul style="list-style-type: none"><li>• Assistant Director of Quality Assurance</li></ul>  |
|            | Suzuki | <ul style="list-style-type: none"><li>• Manager of Quality Control Parts Inspection<br/>Responsibility for QC - Supplier Parts</li></ul> |

These positions held by Suzuki/GM employees are temporary assignments. Suzuki and GM will determine at a future date when these positions will no longer be held by Suzuki and GM assignees, based on the development of CAMI personnel to fulfill these roles.

2. A copy of the test reports regarding the certification tests 75-292 and 76-161 is attached at Appendix 2. The test report of test 77-011 (high speed car to car) is also attached at Appendix 2. A videotape of all three tests will be provided at the meeting.
3. The name and address of the supplier of the fuel tanks is as follows:

Prince Metal Products Ltd. (PMP)  
2575 Airport Road  
Windsor, Ontario  
Canada, N8W 1Z4

AS 279919

Enid Rubenstein

June 13, 1997

Page 3

Production of 4-door Suzuki Sidekicks began in the 1994 model year, November 1993, and continues to the present time. Initially, these vehicles had fuel tanks supplied by Suzuki, Japan, which were assembled by Okamoto Press Industry Co. Ltd., Hamamatsu, Japan. Prince Metal Products (PMP), one of the manufacturing companies of the National Auto Radiator group, began supplying fuel tanks for the 1995 model year 4-door Suzuki Sidekick, which began production in July 1994. There are no other suppliers of fuel tanks for the 4-door Suzuki Sidekick.

The 4-door GM Tracker was introduced in the 1996 model year, which began production in July 1995 and continues to the present time. PMP supplied fuel tanks for these vehicles and continues to supply fuel tanks to CAMI. There is no other supplier of fuel tanks for the 4-door Tracker produced at CAMI.

4. At the time the vehicle tested by NHTSA was manufactured, CAMI's quality assurance requirements for installation of the fuel tank gussets specified that the gusset installer must "ensure hole alignment and edges line up to mating part." This specification was required to be confirmed by a visual inspection of 100% of the gussets after installation. See CIS (CAMI Inspection Standard), Appendix 7-4A at page 3, line 7B. The CAMI Inspection Standard in effect at that time also specified that spot weld integrity must be verified by conducting a pry test on 100% of the gussets after spot welding. See CIS, Appendix 7-4A at page 3, line 8A. The target spot weld locations and parallel gusset orientation are illustrated on Suzuki's engineering drawing.

CAMI's expectation, based on its experience in the industry, was that spot welds would normally lie within a tolerance of  $\pm 5$  mm from the target location. Based on this experience, Suzuki's successful certification and other testing of fuel tank integrity on the subject vehicles at speeds well above the FMVSS 301 requirements, and the lack of any field incidences suggesting a need for more detailed specifications, CAMI had no reason to believe it was necessary to specify spot weld location or gusset orientation tolerances in detail.

After the NHTSA test results, Suzuki prepared an Engineering Change Notice (ECN), identifying a new gusset design and proposed installation specifications with tolerances, and sent that ECN to CAMI. CAMI then worked with PMP to implement the new gusset design and to specify in more detail the quality assurance requirements for gusset installation. Now, the CAMI inspection standard specifies the following with respect to gusset installation: the spot weld pitch must be  $70 \text{ mm} \pm 5 \text{ mm}$ , the spot weld location to hole offset must be 5.5

AS 279920

mm  $\pm$  4 mm, and the gusset orientation must be parallel to the fuel tank wall within 1.9 mm. (See CAMI's response of May 12 for further explanation of how the parallelism is measured.) The spot weld pitch and offset is verified by comparison with a newly designed template that is also used to guide the welding gun during the spot weld installation process. The gusset orientation is verified by use of a taper rule. The pry test for weld integrity also remains in place. In each case, the inspection standard requires 100% inspection of each gusset after spot welding for compliance with the standard. See Appendix 7-4C at page 7, line 17.

5. At the time the vehicle tested by NHTSA was manufactured, the written materials available to PMP included the Suzuki engineering drawings and the CAMI Inspection Standard. See further discussion in response to Question 4. CAMI does not believe that oral communications took place with PMP on the subject of gusset installation, but is continuing to make inquiries in this regard.

After the NHTSA test results, CAMI worked with PMP to establish more detailed quality assurance requirements for gusset orientation. Initially, in June 1996, Suzuki prepared an Engineering Change Notice (ECN), identifying a new gusset design and proposed installation specifications with tolerances, and sent that ECN to CAMI on June 12, 1996. A copy of this notice, which is provided at Appendix 5-1, was given to PMP on the same day. CAMI and PMP then began to work to implement the new design and evaluate the production capability of the proposed tolerances. To achieve the installation of spot welds within the specified tolerances, PMP developed an installation template to guide the spot welding gun during the installation process. With respect to the proposed tolerance for parallel orientation, CAMI and PMP determined that a tolerance of 1.9 mm was feasible within expected manufacturing variability. Documents reflecting oral communications between CAMI and PMP on this issue are provided at Appendix 5-2 and 5-3.

As identified in response to Question 3, there were no other fuel tank suppliers for the subject vehicles at the time these instructions were developed.

6. The MY 96 original and two subsequent drawings will be provided at the meeting of June 13, 1997.
7. The internal standards referenced in CAMI's May 12 letter are the CAMI Inspection Standards discussed in more detail in response to Question 4.

AS 279921

The CAMI quality control procedures for suppliers in effect for the 1995 model year are attached at Appendix 7-1A. This document is not specific to fuel tanks, but rather governs all supplier parts. This guidance document was revised in minor ways in May 1996. A copy of the document is attached at Appendix 7-1B. Other documents reflecting CAMI's internal standards and quality control procedures include the following:

|                                    | <u>Appendix</u> |
|------------------------------------|-----------------|
| Production Process Operation Sheet | 7-2 A, B, C     |
| Process Flow Diagram               | 7-3 A, B, C     |
| CIS (CAMI Inspection Standard)     | 7-4 A, B, C     |
| Final Parts Approval               | 7-5 A & C       |

Within each appendix, documents in place during the 1994 and 1995 model years are marked 'A'. Documents in use for the 1996 model year at the time of the NHTSA testing are marked 'B'. Documents in use after corrective action was taken for gusset location and welding and also in use for 1997 model year are marked 'C'. Please note that CAMI has not been able to locate the document that would have been attached as Appendix 7-5B but is continuing to search for a copy. Please also note that Appendix 7-1A and B are both confidential documents for which an appropriate Part 512 justification will be submitted under separate cover.

8. The CAMI procedures for assuring supplier conformance with engineering drawings and other instructions prior to August 31, 1995 were based on an annual evaluation, which included on-site audit if necessary, as described in the Supplier Guidelines found at Appendix 7-1A at 13. Also see the other materials provided in response to Question 7, which describe other procedures pertaining specifically to PMP's inspection of fuel tanks. CAMI also communicated with and visited PMP to discuss design change issues for new part installation of P-sensor for 96 MY and other production issues during the year prior to August 31, 1995. CAMI does not believe that there were any problems identified or discussed related to gusset welding during this period, but is continuing to make inquiries in this regard.

AS 279922

Enid Rubenstein  
June 13, 1997  
Page 6

To date, we believe that the last date of contact prior to the above date is August 8, 1995. The following records from the year are attached:

Appendix

|  |     |
|--|-----|
| Fax communication from supplier on May 25, 1995                                      | 8-1 |
| Meeting report on June 1, 1995   | 8-2 |
| Confirmation of trial part submission on June 9, 1995                                | 8-3 |
| Fax communication on June 13, 1995   | 8-4 |
| Fax communication on August 8, 1995  | 8-5 |
| Miscellaneous documents related to product manufacturing dated July to November 1994 | 8-6 |

CAMI is continuing to review its files for additional data pertaining to other contacts with PMP that may have occurred during that year.

I also wish to confirm my presence at a meeting scheduled for June 13, 9:30 a.m. at the NHTSA office. If you have any questions, I will be pleased to discuss these further at that time.

Sincerely,



Sadayuki Hirano  
Director, Quality Assurance

AS 279923





06-19-96

5-2 1/9


### Temporary Temporary (Initial fixture)

#### A) Spot Weld (temporary tolerance relief)

- ①  $70 \pm 5.0$  mm
- ②  $5.5 \pm 4.0$  mm

TOLERANCES FOR A1, 2  
& B TO B6 FINALIZED  
AFTER CAPABILITY STUDY  
(30PC) IS COMPLETED.  
AD.

#### B) Parallelism



CAMI J. Johnson 6/19  
Bentworth 6/19.

AD 96/6-19  
PMP C. Taggart J. Jones

#### C) Lot identification.


- i) Must identify start & finish of (temporary temporary) fixture; Lot date (FAX)
- ii) All these parts painted on filler neck (Blue in color).
- iii) Initial parts tag

#### D) Must have clean break point:



- All old style parts shipped Thursday June 20/96
  - All new style parts shipped after Thurs June 20/96
- \* upon approval from CAMI materials.

utilize pink tag.

AS 279925



TO GORD TAGGR  
5-2 2/9



AS 279926

Company : NARMCO Department: PURCHASED PART  
 Plant : PRINCE METAL PRODUCTS Part # : 30019611  
 Desc : GUSSET Process ID: LOC.BETWEEN SPOTWELDS  
 : LOC. BETWEEN A & B Frequency : 30 PC STUDY

5-2 3/9

Engineering Specifications

Lower: 65.0000 Nominal: 70.0000 Upper: 75.0000 Units: MM

Descriptive Statistics - 1 to 6

Total Samples: 30 Total Subgroups: 6  
 Xbar: 69.8333 Ave Sam/Sub: 5.0000  
 Sbar: 1.4383  
 Cbar: 0.5773 Std Dev (n - 1): 0.5630  
 Rbar: 69.9383 Variance (n - 1): 0.3170  
 Skewness: -0.0373 Coeff. of Skewness: -0.2197  
 Kurtosis: 0.2456 Coeff. of Kurtosis: 2.6156

Control Limit Range 1 - 6: Auto

n = 5 : LCLXbar = 69.0034; Xdbar = 69.8333; UCLXbar = 70.6633  
 LCLR = 0.0000; Rbar = 1.4383; UCLR = 3.0406


| Subgroup: | 1        | 2        | 3        | 4        | 5        |
|-----------|----------|----------|----------|----------|----------|
| Sample :  | 1        | 2        | 3        | 4        | 5        |
|           | 69.5000  | 69.8000  | 69.2000  | 69.4000  | 70.6000  |
|           | 69.2000  | 70.3000  | 70.4500  | 69.1200  | 69.6000  |
|           | 70.0000  | 69.4000  | 69.8300  | 70.4000  | 69.9000  |
|           | 69.5000  | 71.0000  | 70.0000  | 70.1000  | 70.0000  |
|           | 70.1000  | 70.4000  | 69.2000  | 70.2000  | 69.5000  |
| Sum :     | 348.3000 | 350.9000 | 348.6800 | 349.2200 | 348.6000 |
| Average : | 69.6600  | 70.1800  | 69.7360  | 69.8440  | 69.7200  |
| Range :   | 0.9000   | 1.6000   | 1.2500   | 1.2800   | 2.1000   |
| Rate :    |          |          |          |          |          |
| Time :    |          |          |          |          |          |
| Code :    |          |          |          |          |          |

| Subgroup: | 6        |
|-----------|----------|
| Sample :  | 1        |
|           | 69.0000  |
|           | 70.3000  |
|           | 70.0000  |
|           | 70.5000  |
|           | 69.5000  |
| Sum :     | 349.3000 |
| Average : | 69.8600  |
| Range :   | 1.5000   |
| Rate :    |          |
| Time :    |          |
| Code :    |          |

AS 279927

5-2

4/9



AS 279928

Company : NARMCO  
Plant : PRINCE METAL PRODUCTS  
Desc : GUSSET  
LOC. BETWEEN C & D

Department: PURCHASED PART  
Part # : 30019611  
Process ID: LOC.BETWEEN SPOTWELDS  
Frequency : 30 PC STUDY

5-2  
5/9

Engineering Specifications

Lower: 65.0000 Nominal: 70.0000 Upper: 75.0000 Units: MM

Descriptive Statistics - 1 to 6

Total Samples: 30 Total Subgroups: 6

Mean: 70.5433 Ave Sam/Sub: 5.0000

Stdev: 1.2083 Std Dev (n - 1): 0.5557

Var: 0.5083 Variance (n - 1): 0.3088

Skewness: 70.6417 Coeff. of Skewness: -0.1805

Kurtosis: -0.0294 Coeff. of Kurtosis: 2.4741

Control Limit Range 1 - 6: Auto

n = 5 : LCLXbar = 69.8461; Xdbar = 70.5433; UCLXbar = 71.2405  
LCLR = 0.0000; Rbar = 1.2083; UCLR = 2.5544

| Subgroup: | 1        | 2        | 3        | 4        | 5        |
|-----------|----------|----------|----------|----------|----------|
| Sample :  | 1        | 2        | 3        | 4        | 5        |
|           | 70.8000  | 69.8000  | 71.0000  | 69.3000  | 70.8000  |
|           | 2        | 70.1000  | 71.0000  | 70.8000  | 69.8000  |
|           | 3        | 69.8000  | 70.9000  | 70.2000  | 70.5500  |
|           | 4        | 70.5000  | 71.0000  | 70.8000  | 70.8000  |
|           | 5        | 69.8000  | 70.4000  | 70.1000  | 70.2500  |
| Sum :     | 351.0000 | 353.1000 | 352.9000 | 350.7000 | 355.0000 |
| Bar :     | 70.2000  | 70.6200  | 70.5800  | 70.1400  | 71.0000  |
| Range :   | 1.0000   | 1.2000   | 0.9000   | 1.5000   | 1.5000   |

Stdev :  
Time :  
Code :

Subgroup: 6


|          |          |         |         |         |         |
|----------|----------|---------|---------|---------|---------|
| Sample : | 1        | 2       | 3       | 4       | 5       |
|          | 70.4000  | 70.0000 | 71.1500 | 71.1500 | 70.9000 |
| Sum :    | 353.6000 |         |         |         |         |
| Bar :    | 70.7200  |         |         |         |         |
| Range :  | 1.1500   |         |         |         |         |

Stdev :  
Time :  
Code :

AS 279929

5-2

6/9



AS 279930

Company : NARMCO Department: PURCHASED PART  
 Plant : PRINCE METAL PRODUCTS Part # : 30019611  
 Desc : GUSSET Process ID: PARALLELISM  
 Char : PARALLELISM BET A & B Frequency : 30 FC STUDY

5-2  
 7/9

Engineering Specifications

Lower: 0.0000 Nominal: 0.7500 Upper: 1.5000 Units: MM

Descriptive Statistics - 1 to 6

Total Samples: 30 Total Subgroups: 6  
 Xbar: 0.3893 Ave Sam/Sub: 5.0000  
 Rbar: 0.5183  
 Sbar: 0.2040 Std Dev (n - 1): 0.2339  
 Cbar: 0.3650 Variance (n - 1): 0.0547  
 Skewness: 0.0113 Coeff. of Skewness: 0.9289  
 Kurtosis: 0.0121 Coeff. of Kurtosis: 4.3069

Control Limit Range 1 - 6: Auto

n = 5 : LCLXbar = 0.0903; Xbar = 0.3893; UCLXbar = 0.6884  
 LCLR = 0.0000; Rbar = 0.5183; UCLR = 1.0958

| Subgroup: | 1      | 2      | 3      | 4      | 5      |
|-----------|--------|--------|--------|--------|--------|
| Sample :  |        |        |        |        |        |
| 1         | 1.0500 | 0.6000 | 0.3400 | 0.5800 | 0.5800 |
| 2         | 0.3900 | 0.0000 | 0.5200 | 0.3300 | 0.4500 |
| 3         | 0.5500 | 0.3000 | 0.3400 | 0.4000 | 0.9600 |
| 4         | 0.2400 | 0.0600 | 0.5000 | 0.1400 | 0.3700 |
| 5         | 0.2000 | 0.3000 | 0.3000 | 0.3000 | 0.6000 |
| Sum :     | 2.4300 | 1.2600 | 2.0000 | 1.7500 | 2.9600 |
| Average : | 0.4860 | 0.2520 | 0.4000 | 0.3500 | 0.5920 |
| Range :   | 0.8500 | 0.6000 | 0.2200 | 0.4400 | 0.5900 |

ate :  
 me :  
 ode :


Subgroup: 6

|           |        |
|-----------|--------|
| Sample :  |        |
| 1         | 0.4500 |
| 2         | 0.2500 |
| 3         | 0.2000 |
| 4         | 0.0400 |
| 5         | 0.3400 |
| Sum :     | 1.2800 |
| Average : | 0.2560 |
| Range :   | 0.4100 |

ate :  
 me :  
 ode :

AS 279931

5-2  
8/9



AS 279932



Company : NARMCO Department: PURCHASED PART  
 Plant : PRINCE METAL PRODUCTS Part # : 30019611  
 Desc : GUSSET Process ID: PARALLELISM  
 Part : PARALLELISM BET C & D Frequency : 30 PC STUDY

5-2  
 9/8

Engineering Specifications

Lower: 0.0000 Nominal: 0.7500 Upper: 1.5000 Units: MM

Descriptive Statistics - 1 to 6

Total Samples: 30 Total Subgroups: 6  
 dbar: 0.6073 Ave Sam/Sub: 5.0000  
 sbar: 0.8117  
 sbar: 0.3320 Std Dev (n - 1): 0.4182  
 rbar: 0.6100 Variance (n - 1): 0.1749  
 skewness: 0.0514 Coeff. of Skewness: 0.7387  
 kurtosis: 0.1165 Coeff. of Kurtosis: 4.0744

Control Limit Range 1 - 6: Auto

n = 5 : LCLXbar = 0.1390; Xdbar = 0.6073; UCLXbar = 1.0757  
 LCLR = 0.0000; Rbar = 0.8117; UCLR = 1.7159

| Subgroup: | 1 | 2      | 3      | 4      | 5      |        |
|-----------|---|--------|--------|--------|--------|--------|
| Sample :  | 1 | 0.4500 | 1.2000 | 0.1100 | 0.3600 | 0.0000 |
|           | 2 | 1.0000 | 0.7000 | 0.7000 | 0.8900 | 0.2100 |
|           | 3 | 0.6300 | 1.0000 | 0.6000 | 0.8500 | 0.1300 |
|           | 4 | 1.0000 | 0.9600 | 0.0000 | 0.5000 | 0.1900 |
|           | 5 | 0.8500 | 0.8000 | 0.6000 | 0.1100 | 0.5900 |
| um :      |   | 3.9300 | 4.6600 | 2.0100 | 2.7100 | 1.1200 |
| sbar :    |   | 0.7860 | 0.9320 | 0.4020 | 0.5420 | 0.2240 |
| range :   |   | 0.5500 | 0.5000 | 0.7000 | 0.7800 | 0.5900 |

etc :  
 ime :  
 ode :

Subgroup: 6


|          |   |        |
|----------|---|--------|
| Sample : | 1 | 0.3500 |
|          | 2 | 0.1400 |
|          | 3 | 1.8900 |
|          | 4 | 0.8500 |
|          | 5 | 0.5600 |
| um :     |   | 3.7900 |
| sbar :   |   | 0.7580 |
| range :  |   | 1.7500 |

etc :  
 ime :  
 ode :

AS 279933

5-3

1/14



N=148

AS 279934

# FAILURE PREVENTION ANALYSIS PROGRAM

## ATTRIBUTE GAGE STUDY

EXHIBIT QPM 4.20 E

5-3

2/14

ATTRIBUTE GAGE USED Parameters and Stamp

PART NO. 30019611

DATE 6-21-96

OPER. "A" Dm R OPER. "B" CHSR

GUS #1 =  
guessed by  
Miller which  
without stamp

THE STUDY IS CONDUCTED BY TWO OPERATORS USING THE SAME 20 PARTS WHICH WERE SELECTED AT RANDOM AND IDENTIFIED 1 THROUGH 20. EACH OPERATOR GAUGES EACH PART AND ENTERS DATA BELOW.

Test #1  
173-6-001  
Test  
FOR  
Weld  
etc.  
OK To  
Run  
QML

| PART | No Stamp            |                  | WITH Stamp       |           |
|------|---------------------|------------------|------------------|-----------|
|      | OPER. "A" SERIAL #. | OPER. "B" GUS #1 | OPER. "A" GUS #2 | OPER. "B" |
| 1    | 173-6-002           | .06              | 1.00             |           |
| 2    | 173-6-003           | 1.26             | .69              |           |
| 3    | 173-6-004           | .90              | .61              |           |
| 4    | 173-6-005           | .49              | .59              |           |
| 5    | 173-6-006           | .80              | .07              |           |
| 6    | 173-6-007           | .26              | .70              |           |
| 7    | 173-6-008           | .50              | 1.20             |           |
| 8    | 173-6-009           | 1.30             | 1.09             |           |
| 9    | 173-6-010           | 1.00             | 0.30             |           |
| 10   | 173-6-011           | 0.40             | 0.90             |           |
| 11   | 173-6-012           | 0.70             | 1.10             |           |
| 12   | 173-6-013           | 0.70             | 0.60             |           |
| 13   | 173-6-014           | 0.15             | 1.00             |           |
| 14   | 173-6-015           | 0.05             | 0.60             |           |
| 15   | 173-6-016           | 0.30             | 0.15             |           |
| 16   | 173-6-017           | 0.50             | 0.80             |           |
| 17   | 173-6-018           | 0.70             | 0.90             |           |
| 18   | 173-6-019           | 0.60             | 0.90             |           |
| 19   | 173-6-020           | 0.30             | 0.86             | AS 279935 |
| 20   | 173-6-021           | 0.90             | 0.80             |           |

1.2  
2.9  
7.3

THE GAGE IS ACCEPTABLE IF ALL MEASUREMENTS DECISIONS (4 PER PART) AGREE. IF THE MEASUREMENT DECISIONS DO NOT AGREE, AN ACCEPTABLE ALTERNATE MEASUREMENT SYSTEM SHOULD BE USED TO MEASURE THE CHARACTERISTIC.

$\bar{x} = 0.55$

$\bar{y} = 0.75$

$n = 20$

EA12-005 PRODUCED BY SUZUKI MOTOR CORPORATION

FAILURE PREVENTION ANALYSIS PROGRAM

ATTRIBUTE GAGE STUDY

EXHIBIT QPM 4.20 E

ATTRIBUTE GAGE USED PARALLELISM STUDY

PART NO. 30019611

5-3  
3/14

DATE June 21/96

OPER. "A" Don R. OPER. "B" Clair < 1.5 mil

Gage #11  
closed  
to  
Fisher  
one  
without  
stop

THE STUDY IS CONDUCTED BY TWO OPERATORS USING THE SAME 20 PARTS WHICH WERE SELECTED AT RANDOM AND IDENTIFIED 1 THROUGH 20. EACH OPERATOR GAUGES EACH PART AND ENTERS DATA BELOW.

| PART | No Stamp  |           | OPER. "B" |
|------|-----------|-----------|-----------|
|      | OPER. "A" | OPER. "A" |           |
| 1    | 173-6-022 | 0.07      | 0.80      |
| 2    | 173-6-023 | 0.07      | 1.20      |
| 3    | 173-6-024 | 0.70      | 1.30      |
| 4    | 173-6-025 | 0.80      | 1.00      |
| 5    | 173-6-026 | 0.30      | 0.50      |
| 6    | 173-6-027 | 0.16      | 0.70      |
| 7    | 173-6-028 | 0.25      | 0.25      |
| 8    | 173-6-029 | 0.55      | 0.60      |
| 9    | 173-6-030 | 1.00      | 0.50      |
| 10   | 173-6-031 | 0.70      | 0.50      |
| 11   | 173-6-032 | 0.45      | 0.50      |
| 12   | 173-6-033 | 0.40      | 0.75      |
| 13   | 173-6-034 | 0.15      | 0.65      |
| 14   | 173-6-035 | 0.16      | 0.80      |
| 15   | 173-6-036 | 0.55      | 0.65      |
| 16   | 173-6-037 | 0.25      | 0.30      |
| 17   | 173-6-038 | 0.07      | 1.25      |
| 18   | 173-6-039 | 0.90      | 0.30      |
| 19   | 173-6-040 | 0.30      | 1.00      |
| 20   | 173-6-041 | 1.00      | 0.60      |

AS 279936

THE GAGE IS ACCEPTABLE IF ALL MEASUREMENTS DECISIONS (4 PER PART) AGREE. IF THE MEASUREMENT DECISIONS DO NOT AGREE, AN ACCEPTABLE ALTERNATE MEASUREMENT SYSTEM SHOULD BE USED TO MEASURE THE CHARACTERISTIC.

EA12-005  
PRODUCED BY SUZUKI MOTOR CORPORATION

**FAILURE PREVENTION ANALYSIS PROGRAM**

**ATTRIBUTE GAGE STUDY**

**EXHIBIT QPM 4.20 E**

ATTRIBUTE GAGE USED \_\_\_\_\_

PART NO. \_\_\_\_\_

5-3  
4/14

DATE \_\_\_\_\_

OPER. "A" \_\_\_\_\_

OPER. "B" \_\_\_\_\_

THE STUDY IS CONDUCTED BY TWO OPERATORS USING THE SAME 20 PARTS WHICH WERE SELECTED AT RANDOM AND IDENTIFIED 1 THROUGH 20. EACH OPERATOR GAUGES EACH PART AND ENTERS DATA BELOW.

| PART | OPER. "A" | OPER. "B" | OPER. "A" | OPER. "B" |
|------|-----------|-----------|-----------|-----------|
| 1    | 173-6-042 | 0.25      | 1.00      |           |
| 2    | 173-6-043 | 0.30      | 0.70      |           |
| 3    | 173-6-044 | 0.75      | 0.28      |           |
| 4    | 173-6-045 | .80       | .95       |           |
| 5    | 173-6-046 | 0.75      | 0.50      |           |
| 6    | 173-6-047 | .80       | 0.22      |           |
| 7    | 173-6-048 | 0.70      | 0.45      |           |
| 8    | 173-6-049 | 0.23      | 0.33      |           |
| 9    | 173-6-050 | 0.25      | 0.45      |           |
| 10   | 173-6-051 | 0.55      | 0.29      |           |
| 11   | 173-6-052 | 0.58      | 0.42      |           |
| 12   | 173-6-053 | 0.55      | 0.37      |           |
| 13   | 173-6-054 | 0.61      | 0.38      |           |
| 14   | 173-6-055 | 0.24      | 0.29      |           |
| 15   | 173-6-056 | 0.20      | 0.24      |           |
| 16   | 173-6-057 | 0.30      | 0.44      |           |
| 17   | 173-6-058 | 0.30      | 0.20      |           |
| 18   | 173-6-059 | 0.50      | 0.35      |           |
| 19   | 173-6-060 | 0.73      | 0.18      | AS 279937 |
| 20   | 173-6-061 | 0.45      | 0.15      |           |

THE GAGE IS ACCEPTABLE IF ALL MEASUREMENTS DECISIONS (4 PER PART) AGREE. IF THE MEASUREMENT DECISIONS DO NOT AGREE, AN ACCEPTABLE ALTERNATE MEASUREMENT SYSTEM SHOULD BE USED TO MEASURE THE CHARACTERISTIC.

EA12-005  
PRODUCED BY SUZUKI MOTOR CORPORATION

11.29

7-043

# FAILURE PREVENTION ANALYSIS PROGRAM

## ATTRIBUTE GAGE STUDY

EXHIBIT OPM 4.20 E

ATTRIBUTE GAGE USED HAND HELD CHECKING FIXTURE

PART NO. 30018740

5-3

DATE JUNE 19/96

5/14

THE STUDY IS CONDUCTED BY TWO OPERATORS USING THE SAME 20 PARTS WHICH WERE SELECTED AT RANDOM AND IDENTIFIED 1 THROUGH 20. EACH OPERATOR GAUGES EACH PART AND ENTERS DATA BELOW.

| PART | SERIAL NO. | GUSSET WITH STAMP | GUSSET WITH STAMP |           |
|------|------------|-------------------|-------------------|-----------|
| 141  |            | 0.85              | 0.25              |           |
| 142  |            | 0.88              | 0.67              |           |
| 143  | 175-5-05   | 0.82              | 0.20              |           |
| 144  | 172-6-05   | 0.43              | 0.44              |           |
| 145  | 172-6-000  | 0.82              | 0.65              |           |
| 146  | 172-6-06   | 0.12              | 0.21              |           |
| 147  | 172-6-08   | 0.35              | 0.55              |           |
| 148  | 172-6-05   | 0.60              | 0.13              |           |
| 149  | 176-5-070  | 0.13              | 0.98              |           |
| 150  | 172-6-07   | 0.81              | 0.82              |           |
| 151  | 172-6-072  | 0.56              | 0.73              |           |
| 152  | 172-6-073  | 0.50              | 1.02              |           |
| 153  | 173-6-074  | 0.43              | 0.61              |           |
| 154  | 172-6-075  | 0.16              | 0.31              |           |
| 155  | 172-6-077  | 0.21              | 1.12              |           |
| 156  | 172-6-078  | 0.24              | 0.61              |           |
| 157  | 172-6-079  | 0.24              | 0.68              |           |
| 158  | 172-6-080  | 0.24              | 1.03              |           |
| 159  | 172-6-081  | 0.10              | 0.30              |           |
| 160  | 172-6-082  | 0.51              | 0.11              | AS 279938 |

THE GAGE IS ACCEPTABLE IF ALL MEASUREMENTS DECISIONS (4 PER PART) AGREE. IF THE MEASUREMENT DECISIONS DO NOT AGREE, AN ACCEPTABLE ALTERNATE MEASUREMENT SYSTEM SHOULD BE USED TO MEASURE THE CHARACTERISTIC.

FAILURE PREVENTION ANALYSIS PROGRAM

ATTRIBUTE GAGE STUDY

EXHIBIT OPM 420 E

ATTRIBUTE GAGE USED MMM HELIX CHECKING FIXTURE

PART NO. 30018740

5-3  
6/14

DATE JUNE 19/96

THE STUDY IS CONDUCTED BY TWO OPERATORS USING THE SAME 20 PARTS WHICH WERE SELECTED AT RANDOM AND IDENTIFIED 1 THROUGH 20. EACH OPERATOR GAUGES EACH PART AND ENTERS DATA BELOW.

| PART | SERIAL NO. | GUSSET WITH STAMP<br>GO / NOGO | GUSSET W/OUT STAMP<br>GO / NOGO |           |
|------|------------|--------------------------------|---------------------------------|-----------|
| 181  |            |                                |                                 |           |
| 182  |            |                                |                                 |           |
| 183  |            |                                |                                 |           |
| 184  |            | 0.20                           | 1.00                            |           |
| 185  |            | 0.36                           | 0.48                            |           |
| 186  |            | 0.13                           | 0.9                             |           |
| 187  |            | 0.68                           | 1.03                            |           |
| 188  |            | 0.37                           | 0.85                            |           |
| 189  |            | 0.30                           | 0.06                            |           |
| 190  |            | 0.04                           | 0.54                            |           |
| 191  |            | 0.33                           | 0.82                            |           |
| 192  |            | 1.07                           | 1.04                            |           |
| 193  |            | 1.03                           | 1.10                            |           |
| 194  |            | 1.03                           | 1.33                            |           |
| 195  |            | 0.62                           | 1.06                            |           |
| 196  |            | 0.26                           | 0.36                            |           |
| 197  |            | 0.46                           | 0.80                            |           |
| 198  |            | 0.70                           | 1.21                            |           |
| 199  |            | 0.66                           | 0.67                            | AS 279939 |
| 200  |            | 0.20                           | 0.63                            |           |

THE GAGE IS ACCEPTABLE IF ALL MEASUREMENTS DECISIONS (4 PER PART) AGREE. IF THE MEASUREMENT DECISIONS DO NOT AGREE, AN ACCEPTABLE ALTERNATE MEASUREMENT SYSTEM SHOULD BE USED TO MEASURE THE CHARACTERISTIC.

**FAILURE PREVENTION ANALYSIS PROGRAM**

**ATTRIBUTE GAGE STUDY**

**EXHIBIT OPM 4.20 E**

ATTRIBUTE GAGE USED HAND HELD CHECKING FIXTURE

PART NO. 30018740

53  
7/14

DATE JUNE 15/96

THE STUDY IS CONDUCTED BY TWO OPERATORS USING THE SAME 20 PARTS WHICH WERE SELECTED AT RANDOM AND IDENTIFIED 1 THROUGH 20. EACH OPERATOR GAUGES EACH PART AND ENTERS DATA BELOW.

| PART | SERIAL NO. | GUSSET WITH STAMP<br>GO / NOGO | GUSSET W/OIT STAMP<br>GO / NOGO |           |
|------|------------|--------------------------------|---------------------------------|-----------|
| 201  |            |                                |                                 |           |
| 202  |            |                                |                                 |           |
| 203  |            |                                |                                 |           |
| 204  |            | 0.08                           | 0.07                            |           |
| 205  |            |                                |                                 |           |
| 206  |            | 0.75                           | 1.39                            |           |
| 207  |            | 0.54                           | 0.17                            |           |
| 208  |            |                                |                                 |           |
| 209  |            |                                |                                 |           |
| 210  |            |                                |                                 |           |
| 211  |            |                                |                                 |           |
| 212  |            | 1.09                           | 1.58                            |           |
| 213  |            | 0.95                           | 1.36                            |           |
| 214  |            | 0.28                           | 1.01                            |           |
| 215  |            | 0.37                           | 1.34                            |           |
| 216  |            | 0.22                           | 1.20                            |           |
| 217  |            |                                |                                 |           |
| 218  |            | 0.35                           | 1.32                            |           |
| 219  |            | 0.27                           | 0.11                            | AS 279940 |
| 220  |            | 0.12                           | 1.15                            |           |

THE GAGE IS ACCEPTABLE IF ALL MEASUREMENTS DECISIONS (4 PER PART) AGREE. IF THE MEASUREMENT DECISIONS DO NOT AGREE, AN ACCEPTABLE ALTERNATE MEASUREMENT SYSTEM SHOULD BE USED TO MEASURE THE CHARACTERISTIC.



# FAILURE PREVENTION ANALYSIS PROGRAM

## ATTRIBUTE GAGE STUDY

EXHIBIT QPM 4.20 E

ATTRIBUTE GAGE USED HAND HELD CHECKING FIXTURE

PART NO. 30018740

5-3  
8/14

DATE JUNE 19/96

THE STUDY IS CONDUCTED BY TWO OPERATORS USING THE SAME 20 PARTS WHICH WERE SELECTED AT RANDOM AND IDENTIFIED 1 THROUGH 20. EACH OPERATOR GAUGES EACH PART AND ENTERS DATA BELOW.

| PART | SERIAL NO. | GUSSET WITH STAMP |           |
|------|------------|-------------------|-----------|
|      |            | GO / NOGO         | GO / NOGO |
| 281  | 171        | 0.4               | 1.4       |
| 282  | 172        | 0.29              | 1.40      |
| 283  | 173        | 0.23              | 1.40      |
| 284  | 175        | 0.04              | 0.56      |
| 285  | 179        | 0.44              | 1.22      |
| 286  | 130        | 0.34              | 0.55      |
| 287  | 131        | 0.39              | 1.21      |
| 288  | 132        | 0.25              | 1.03      |
| 289  | 133        | 0.05              | 1.08      |
| 290  | 134        | 0.20              | 1.20      |
| 291  | 135        | 0.83              | 1.04      |
| 292  | 136        | 0.37              | 1.23      |
| 293  | 137        | 0.34              | 1.59      |
| 294  | 138        | 0.06              | 0.77      |
| 295  | 139        | 0.58              | 0.11      |
| 296  | 140        | 0.21              | 0.34      |
| 297  | 141        | 0.92              | 0.39      |
| 298  | 142        | 0.05              | 1.18      |
| 299  | 143        | 1.30              | 0.85      |
| 300  | 144        | 0.75              | 0.11      |

AS 279941

THE GAGE IS ACCEPTABLE IF ALL MEASUREMENTS DECISIONS (4 PER PART) AGREE. IF THE MEASUREMENT DECISIONS DO NOT AGREE, AN ACCEPTABLE ALTERNATE MEASUREMENT SYSTEM SHOULD BE USED TO MEASURE THE CHARACTERISTIC.

EA12-005  
PRODUCED BY SUZUKI MOTOR CORPORATION

# FAILURE PREVENTION ANALYSIS PROGRAM

## ATTRIBUTE GAGE STUDY

EXHIBIT QPM/420 E

ATTRIBUTE GAGE USED \_\_\_\_\_

PART NO. 300119611

53  
9119

DATE 6-23-96

OPER. "A" \_\_\_\_\_ OPER. "B" < 1.5 mm

**THE STUDY IS CONDUCTED BY TWO OPERATORS USING THE SAME 20 PARTS WHICH WERE SELECTED AT RANDOM AND IDENTIFIED 1 THROUGH 20. EACH OPERATOR GAUGES EACH PART AND ENTERS DATA BELOW.**

| PART | OPER. "A" | <del>OPER. "B"</del> | <del>OPER. "A"</del> | OPER. "B" |
|------|-----------|----------------------|----------------------|-----------|
| 1    | 173-6-145 | 0.43                 | 0.80                 |           |
| 2    | 173-6-146 | 0.27                 | 1.38                 |           |
| 3    | 173-6-147 | 0.55                 | 1.48                 |           |
| 4    | 173-6-148 | 0.51                 | 1.61                 |           |
| 5    | 173-6-149 | 0.14                 | 0.64                 |           |
| 6    | 173-6-150 | 0.20                 | 0.48                 |           |
| 7    | 173-6-147 | 0.70                 | 0.45                 |           |
| 8    | 174-6-002 | 1.20                 | 0.85                 |           |
| 9    | 174-6-003 | 0.75                 | 1.00                 |           |
| 10   | 174-6-004 | 0.95                 | 0.90                 |           |
| 11   | 174-6-005 | 0.60                 | 0.65                 |           |
| 12   | 174-6-006 | 0.75                 | 0.70                 |           |
| 13   | 174-6-007 | 0.20                 | 1.00                 |           |
| 14   | 174-6-008 | 0.50                 | 0.40                 |           |
| 15   | 174-6-009 | 0.95                 | 0.80                 |           |
| 16   | 174-6-010 | 0.35                 | 0.85                 |           |
| 17   | 174-6-011 | 0.90                 | 0.80                 |           |
| 18   | 174-6-012 | 0.50                 | 1.10                 |           |
| 19   | 174-6-013 | 0.06                 | 0.60                 | AS 279942 |
| 20   | 174-6-014 | 0.35                 | 0.40                 |           |

**THE GAGE IS ACCEPTABLE IF ALL MEASUREMENTS DECISIONS (4 PER PART) AGREE. IF THE MEASUREMENT DECISIONS DO NOT AGREE, AN ACCEPTABLE ALTERNATE MEASUREMENT SYSTEM SHOULD BE USED TO MEASURE THE CHARACTERISTIC.**

EA12-005  
PRODUCED BY SUZUKI MOTOR CORPORATION

**FAILURE PREVENTION ANALYSIS PROGRAM**

**ATTRIBUTE GAGE STUDY**

**EXHIBIT QPM 4.20 E**

ATTRIBUTE GAGE USED \_\_\_\_\_

PART NO. \_\_\_\_\_

5-3  
10/14

DATE \_\_\_\_\_

OPER. "A" \_\_\_\_\_

OPER. "B" \_\_\_\_\_

THE STUDY IS CONDUCTED BY TWO OPERATORS USING THE SAME 20 PARTS WHICH WERE SELECTED AT RANDOM AND IDENTIFIED 1 THROUGH 20.

EACH OPERATOR GAUGES EACH PART AND ENTERS DATA BELOW.

| PART | OPER. "A"<br><i>Scribed</i> | OPER. "B"<br><i>Bus #1</i> | OPER. "A"<br><i>Bus #2</i> | OPER. "B" |
|------|-----------------------------|----------------------------|----------------------------|-----------|
| 1    | 174-6-017                   | 0.80                       | 0.95                       |           |
| 2    | 174-6-018                   | 0.35                       | 1.00                       |           |
| 3    | 174-6-019                   | 0.08                       | 1.00                       |           |
| 4    | 174-6-020                   | 0.10                       | 0.15                       |           |
| 5    | 174-6-021                   | 0.16                       | 0.25                       |           |
| 6    | 194-6-022                   | 0.30                       | 0.85                       |           |
| 7    | 174-6-023                   | 0.06                       | 1.00                       |           |
| 8    | 174-6-024                   | 0.08                       | 1.30                       |           |
| 9    | 174-6-025                   | 0.30                       | 0.70                       |           |
| 10   | 174-6-026                   | 0.25                       | 0.15                       |           |
| 11   | 174-6-027                   | 0.30                       | 1.00                       |           |
| 12   | 174-6-028                   | 0.50                       | 0.70                       |           |
| 13   | 174-6-030                   | 0.40                       | 0.65                       |           |
| 14   | 174-6-029                   | 0.10                       | 0.80                       |           |
| 15   | 174-6-031                   | 0.25                       | 0.90                       |           |
| 16   | 174-6-022                   | 0.05                       | 0.65                       |           |
| 17   | 174-6-033                   | 0.70                       | 0.40                       |           |
| 18   | 174-6-034                   | 0.75                       | 0.65                       |           |
| 19   | 174-6-035                   | 0.65                       | 0.60                       | AS 279943 |
| 20   | 174-6-036                   | 0.65                       | 0.60                       |           |

THE GAGE IS ACCEPTABLE IF ALL MEASUREMENTS DECISIONS (4 PER PART) AGREE. IF THE MEASUREMENT DECISIONS DO NOT AGREE, AN ACCEPTABLE ALTERNATE MEASUREMENT SYSTEM SHOULD BE USED TO MEASURE THE CHARACTERISTIC.

EA12-005  
PRODUCED BY SUZUKI MOTOR CORPORATION

# FAILURE PREVENTION ANALYSIS PROGRAM

## ATTRIBUTE GAGE STUDY

**EXHIBIT QPM 4.20 E**

ATTRIBUTE GAGE USED \_\_\_\_\_

PART NO. \_\_\_\_\_

5-3  
1114

DATE \_\_\_\_\_

JUNE 22 196

OPER. "A" \_\_\_\_\_

OPER. "B" \_\_\_\_\_

← 1.5 mm

**THE STUDY IS CONDUCTED BY TWO OPERATORS USING THE SAME 20 PARTS WHICH WERE SELECTED AT RANDOM AND IDENTIFIED 1 THROUGH 20.**

**EACH OPERATOR GAUGES EACH PART AND ENTERS DATA BELOW.**

| PART | OPER. "A"<br><i>Solid *</i> | OPER. "B"<br><i>Guo * 1</i> | OPER. "A"<br><i>Guo * 2</i> | OPER. "B" |
|------|-----------------------------|-----------------------------|-----------------------------|-----------|
| 1    | 174-6-038                   | 0.25                        | 0.10                        |           |
| 2    | 174-6-040                   | 0.03                        | 0.75                        |           |
| 3    | 174-6-039                   | 0.11                        | 0.85                        |           |
| 4    | 174-6-042                   | 0.79                        | 0.28                        |           |
| 5    | 174-6-043                   | 0.85                        | 0.10                        |           |
| 6    | 174-6-044                   | 0.52                        | 0.12                        |           |
| 7    | 174-6-045                   | 0.42                        | 0.27                        |           |
| 8    | 174-6-046                   | 1.03                        | 0.15                        |           |
| 9    | 174-6-047                   | 1.48                        | 0.21                        |           |
| 10   | 174-6-048                   | 1.47                        | 0.15                        |           |
| 11   | 174-6-049                   | 0.78                        | 0.19                        |           |
| 12   | 174-6-050                   | 0.30                        | 0.13                        |           |
| 13   | 174-6-051                   | 0.49                        | 0.19                        |           |
| 14   | 174-6-052                   | 0.67                        | 0.49                        |           |
| 15   | 174-6-053                   | 0.44                        | 0.14                        |           |
| 16   | 174-6-054                   | 0.45                        | 0.09                        |           |
| 17   | 174-6-055                   | 0.61                        | 0.09                        |           |
| 18   | 174-6-056                   | 0.50                        | 0.14                        |           |
| 19   | 174-6-057                   | 0.69                        | 0.22                        | AS 279944 |
| 20   | 174-6-058                   | 0.10                        | 0.21                        |           |

**THE GAGE IS ACCEPTABLE IF ALL MEASUREMENTS DECISIONS (4 PER PART) AGREE. IF THE MEASUREMENT DECISIONS DO NOT AGREE, AN ACCEPTABLE ALTERNATE MEASUREMENT SYSTEM SHOULD BE USED TO MEASURE THE CHARACTERISTIC.**

$\bar{X} = 0.60$

$\bar{X} = 0.54$

FAILURE PREVENTION ANALYSIS PROGRAM

ATTRIBUTE GAGE STUDY

EXHIBIT QPM 4.20 E

ATTRIBUTE GAGE USED \_\_\_\_\_

PART NO. \_\_\_\_\_

5-3

1-2/14

DATE \_\_\_\_\_

OPER. "A" \_\_\_\_\_

OPER. "B" \_\_\_\_\_

THE STUDY IS CONDUCTED BY TWO OPERATORS USING THE SAME 20 PARTS WHICH WERE SELECTED AT RANDOM AND IDENTIFIED 1 THROUGH 20.

EACH OPERATOR GAUGES EACH PART AND ENTERS DATA BELOW.

| PART | <del>OPER. "A"</del> | OPER. "B" | OPER. "A" | OPER. "B" |
|------|----------------------|-----------|-----------|-----------|
| 1    | 175-6-009            | 0.15      | 0.80      |           |
| 2    | 175-6-007            | 1.00      | 0.16      |           |
| 3    | 175-6-010            | 0.02      | 0.60      |           |
| 4    | 175-6-011            | 0.25      | 0.45      |           |
| 5    | 175-6-012            | 0.40      | 0.75      |           |
| 6    | 175-6-013            | 0.12      | 0.62      |           |
| 7    | 175-6-014            | 0.45      | 0.40      |           |
| 8    | 175-6-015            | 0.45      | 0.10      |           |
| 9    | 175-6-016            | 0.70      | 0.31      |           |
| 10   | 175-6-018            | 0.40      | 0.65      |           |
| 11   | 175-6-019            | 1.20      | 0.86      |           |
| 12   | 175-6-020            | 0.55      | 0.60      |           |
| 13   | 175-6-021            | 0.70      | 0.90      |           |
| 14   | 175-6-023            | 0.30      | 0.23      |           |
| 15   | 175-6-024            | 0.80      | 0.60      |           |
| 16   | 175-6-022            | 0.70      | 0.50      |           |
| 17   | 175-6-024            | 0.65      | 0.40      |           |
| 18   | 175-6-021            | 0.55      | 0.60      |           |
| 19   | 175-6-021            | 0.80      | 0.60      |           |
| 20   | 175-6-026            | 0.40      | 0.90      |           |

AS 279945

THE GAGE IS ACCEPTABLE IF ALL MEASUREMENTS DECISIONS (4 PER PART) AGREE. IF THE MEASUREMENT DECISIONS DO NOT AGREE, AN ACCEPTABLE ALTERNATE MEASUREMENT SYSTEM SHOULD BE USED TO MEASURE THE CHARACTERISTIC.

$\bar{x} = 0.52$

$\bar{y} = 0.51$

$n = 20$

**FAILURE PREVENTION ANALYSIS PROGRAM**

**ATTRIBUTE GAGE STUDY**

**EXHIBIT QPM 4.20 E**

ATTRIBUTE GAGE USED \_\_\_\_\_

PART NO. 30018740 < 15mm

DATE JUNE 22/96 5-3  
13/14

OPER. "A" NO STAMP OPER. "B" STAMP

**THE STUDY IS CONDUCTED BY TWO OPERATORS USING THE SAME 20 PARTS WHICH WERE SELECTED AT RANDOM AND IDENTIFIED 1 THROUGH 20.**

**EACH OPERATOR GAUGES EACH PART AND ENTERS DATA BELOW.**

| PART | NO STAMP    |           | STAMP     |           |
|------|-------------|-----------|-----------|-----------|
|      | OPER. "A" # | OPER. "B" | OPER. "A" | OPER. "B" |
| 1    | 174-6-059   | 0.11      | 0.63      |           |
| 2    | 174-6-060   | 1.22      | 0.22      |           |
| 3    | 174-6-061   | 1.00      | 0.02      |           |
| 4    | 174-6-062   | 0.26      | 0.18      |           |
| 5    | 174-6-063   | 0.23      | 0.37      |           |
| 6    | 174-6-064   | 0.36      | 0.23      |           |
| 7    | 174-6-066   | 1.01      | 0.12      |           |
| 8    | 174-6-067   | 0.63      | 0.40      |           |
| 9    | 174-6-068   | 0.80      | 0.10      |           |
| 10   | 174-6-069   | 0.39      | 0.24      |           |
| 11   | 174-6-070   | 0.37      | 0.28      |           |
| 12   | 174-6-071   | 0.24      | 0.32      |           |
| 13   | 174-6-072   | 0.61      | 0.36      |           |
| 14   | 174-6-073   | 0.08      | 0.58      |           |
| 15   | 174-6-074   | 0.98      | 0.08      |           |
| 16   | 174-6-075   | 0.47      | 0.14      |           |
| 17   | 174-6-076   | 0.85      | 0.30      |           |
| 18   | 174-6-077   | 1.01      | 0.69      |           |
| 19   | 174-6-078   | 0.12      | 0.16      |           |
| 20   | 174-6-079   | 0.89      | 0.70      |           |

AS 279946

**THE GAGE IS ACCEPTABLE IF ALL MEASUREMENTS DECISIONS (4 PER PART) AGREE. IF THE MEASUREMENT DECISIONS DO NOT AGREE, AN ACCEPTABLE ALTERNATE MEASUREMENT SYSTEM SHOULD BE USED TO MEASURE THE CHARACTERISTIC.**

EA12-005  
PRODUCED BY SUZUKI MOTOR CORPORATION

174-6-080 0.06 1.00 0.56 0.22

FAILURE PREVENTION ANALYSIS PROGRAM

ATTRIBUTE GAGE STUDY

EXHIBIT QPM 4.20 E

ATTRIBUTE GAGE USED \_\_\_\_\_

PART NO. \_\_\_\_\_

5-3

14/14

DATE \_\_\_\_\_

OPER. "A" \_\_\_\_\_

OPER. "B" \_\_\_\_\_

THE STUDY IS CONDUCTED BY TWO OPERATORS USING THE SAME 20 PARTS WHICH WERE SELECTED AT RANDOM AND IDENTIFIED 1 THROUGH 20.

EACH OPERATOR GAUGES EACH PART AND ENTERS DATA BELOW.

| PART | <del>OPER. "A"</del> | <del>OPER. "B"</del> | OPER. "A" | OPER. "B" |
|------|----------------------|----------------------|-----------|-----------|
| 1    | 175-6-031            | 0.25                 | 0.60      |           |
| 2    | 175-6-030            | 0.50                 | 0.70      |           |
| 3    | 175-6-032            | 0.40                 | 1.10      |           |
| 4    | 175-6-034            | 0.35                 | 0.80      |           |
| 5    | 175-6-036            | 0.85                 | 0.65      |           |
| 6    | 175-6-038            | 0.70                 | 0.10      |           |
| 7    | 175-6-039            | 0.70                 | 1.30      |           |
| 8    | 175-6-040            | 0.15                 | 0.95      |           |
| 9    | 175-6-041            | 0.10                 | 0.50      |           |
| 10   | 175-6-042            | 0.20                 | 0.20      |           |
| 11   | 175-6-037            | 0.60                 | 1.30      |           |
| 12   | 175-6-033            | 0.40                 | 1.20      |           |
| 13   | 175-6-035            | 0.40                 | 0.90      |           |
| 14   | 175-6-043            | 0.50                 | 1.00      |           |
| 15   | 175-6-044            | 0.25                 | 0.40      |           |
| 16   | 175-6-045            | 1.05                 | 0.60      |           |
| 17   | 175-6-047            | 0.65                 | 0.25      |           |
| 18   | 175-6-046            | 0.25                 | 0.55      |           |
| 19   | 175-6-047            | 0.60                 | 0.15      | AS 279947 |
| 20   | 175-6-040            | 0.05                 | 0.30      |           |

THE GAGE IS ACCEPTABLE IF ALL MEASUREMENTS DECISIONS (4 PER PART) AGREE. IF THE MEASUREMENT DECISIONS DO NOT AGREE, AN ACCEPTABLE ALTERNATE MEASUREMENT SYSTEM SHOULD BE USED TO MEASURE THE CHARACTERISTIC.

$\bar{x} = 0.64$

$\bar{x} = 0.68$

# PART IN PROCESS OPERATION SHEET

7-2-A page 1/2

DATE : 04/15/96

OPERATOR & SAFETY INSTRUCTION : 1 - MUST WEAR SAFETY SHOES, EAR PLUGS, ARM GUARDS, SAFETY GLASSES AND GLOVES

- 2 - CHECK :
- A) WORK AREAS MUST BE FREE OF OIL AND DEBRIS.
  - B) ALL GUARDS IN THEIR PROPER POSITION.
  - C) SELECTOR SWITCHES LOCKED IN PROPER POSITION.
  - D) DIE CLAMPS TIGHT AND FREE OF FOREIGN OBJECTS.
  - E) PRESS AND PALM BUTTON CHECK.

**ACCEPTANCE  
CRITERIA**  
"0 DEFECTS"

COMPANY : CAMI AUTOMOTIVE  
PART NUMBER : 30018740

PART NAME : 4 DOOR GAS TANK ASSEMBLY 96  
BLUEPRINT DATE : CAMI E.C.N.

MACHINE No. :  
ECL. : 77E-1647

OPERATION DESCRIPTION: SPOT WELD GUSSETS 2 P/N 89125-60A00, 1 - P/N 89126-56B00, 1 - P/N 89127-56B00 TO TANK  
(2 SPOT WELDS FOR EACH GUSSET)

- STANDARD RULES :
- 1 - OPERATOR IS RESPONSIBLE FOR PRODUCING QUALITY PARTS IN STATISTICAL CONTROL.
  - 2 - OPERATOR IS RESPONSIBLE FOR COMPLETING CONTROL CHARTS ACCORDING TO THE CONTROL PLAN.
  - 3 - IF PROCESS IS OUT OF STATISTICAL CONTROL, CONDUCT THE FOLLOWING


- A) SHUT PROCESS DOWN.
- B) CONTACT YOUR SUPERVISOR.
- C) WRITE THE PROBLEM AND / OR CAUSE ON THE CONTROL CHARTS.
- D) WRITE CORRECTIVE ACTION ON CONTROL CHART.
- E) SORT PRODUCTION 100 % FROM LAST GOOD CHECK WITHIN BLUEPRINT SPECIFICATION.

\* ALL REPAIRS  
& REWORK SHALL BE  
RE-INSPECTED AS PER  
PART QUALITY PLAN

SCHEMATIC OF OPERATION

OPERATOR TO CHECK

OPERATION #1589126-56B00



1. FILL OUT THE MACHINE LOG AT THE START OF SHIFT.
2. FILL OUT LOT TRACEABILITY.
3. FILL OUT INPROCESS CHECKS AS PER CONTROL PLAN.
4. COMPARE TO MASTER SAMPLE.
5. PRY TEST 100%. ←
6. VISUAL CHECK FOR RUST, MISFORMED, SPLITS, AND BURRS - NONE ALLOWED.

**VERIFY CONTAINERS FOR  
DEBRIS/DAMAGE/LABELS**

4-27-96

ISSUED BY: MINDEE MINOS

PLANT QUALITY MANAGER: *J. Taggart*

REVISION LEVEL : \*1\*  
REASON: NEW PUMP P/N 30018726

**AS 279948**

FILE: OPT-15

ENGINEERING APPROVAL: *[Signature]*

APPROPRIATE D.O. MANAGER: *[Signature]*

PLANT MANAGER: *[Signature]*

EA12-005  
PRODUCED BY SUZUKI MOTOR CORPORATION



# PART IN PROCESS OPERATION SHEET

**7-2-A** page 2/2

DATE : 04/15/96

- OPERATOR & SAFETY INSTRUCTION :**
- 1 - MUST WEAR SAFETY SHDES, EAR PLUGS, ARM GUARDS, SAFETY GLASSES AND GLOVES
  - 2 - CHECK :
    - A) WORK AREAS MUST BE FREE OF OIL AND DEBRIS.
    - B) ALL GUARDS IN THEIR PROPER POSITION.
    - C) SELECTOR SWITCHES LOCKED IN PROPER POSITION.
    - D) DIE CLAMPS TIGHT AND FREE OF-FOREIGN OBJECTS.
    - E) PRESS AND PALM BUTTON CHECK.

**ACCEPTANCE  
CRITERIA  
" 0 DEFECTS "**

COMPANY : CAMI AUTOMOTIVE  
PART NUMBER : 30018740

PART NAME : 4 DOOR GAS TANK ASSEMBLY 96  
BLUEPRINT DATE : CAMI E.C.N.

MACHINE No. :  
ECL. : 77E-1647

**OPERATION DESCRIPTION:** OPERATOR STAMPS JULIAN DATE, YEAR AND NUMBER TANK INTO P/N 89125-60A00 (GUSSET)


- STANDARD RULES :**
- 1 - OPERATOR IS RESPONSIBLE FOR PRODUCING QUALITY PARTS IN STATISTICAL CONTROL.
  - 2 - OPERATOR IS RESPONSIBLE FOR COMPLETING CONTROL CHARTS ACCORDING TO THE CONTROL PLAN.
  - 3 - IF PROCESS IS OUT OF STATISTICAL CONTROL, CONDUCT THE FOLLOWING

- A) SHUT PROCESS DOWN.
- B) CONTACT YOUR SUPERVISOR.
- C) WRITE THE PROBLEM AND / OR CAUSE ON THE CONTROL CHARTS.
- D) WRITE CORRECTIVE ACTION ON CONTROL CHART.
- E) SORT PRODUCTION 100 % FROM LAST GOOD CHECK WITHIN BLUEPRINT SPECIFICATION.

**\* ALL REPAIRS  
& REWORK SHALL BE  
RE-INSPECTED AS PER  
PART QUALITY PLAN**

**SCHEMATIC OF OPERATION**

OPERATION #14



**OPERATOR TO CHECK**

1. FILL OUT THE MACHINE LOG AT THE START OF SHIFT.
2. FILL OUT LOT TRACEABILITY.
3. FILL OUT INPROCESS CHECKS AS PER CONTROL PLAN.
4. COMPARE TO MASTER SAMPLE.
5. FRY TEST 100%. ←
6. VISUAL CHECK FOR RUST, MISFORMED, SPLITS, AND BURRS - NONE ALLOWED.

**VERIFY CONTAINERS FOR  
DEBRIS/DAMAGE/LABELS** 4-27-96

**AS 279949**

ISSUED BY: MINDEE MINOS      PLANT QUALITY MANAGER: *H. Taggart*

REVISION LEVEL : \*1\*  
REASON: NEW PUMP P/N 30018726

FILE: OPT-14

ENGINEERING APPROVAL: *[Signature]*      CORPORATE O.A. MANAGER: *[Signature]*      PLANT MANAGER: *[Signature]*

EA12-005  
PRODUCED BY SUZUKI MOTOR CORPORATION

PART IN PROCESS OPERATION SHEET

7-2-B  
DATE: 01/12/96

1/17

- OPERATOR & SAFETY INSTRUCTION : 1 - MUST WEAR SAFETY SHOES, EAR PLUGS, ARM GUARDS, SAFETY GLASSES AND GLOVES  
 2 - CHECK : A) WORK AREAS MUST BE FREE OF OIL AND DEBRIS.  
 B) ALL GUARDS IN THEIR PROPER POSITION.  
 C) SELECTOR SWITCHES LOCKED IN PROPER POSITION.  
 D) DIE CLAMPS TIGHT AND FREE OF FOREIGN OBJECTS.  
 E) PRESS AND PALM BUTTON CHECK.

ACCEPTANCE  
CRITERIA  
"0 DEFECTS"

COMPANY : CAMI AUTOMOTIVE  
PART NUMBER : 30018268

PART NAME : 4 DOOR GAS TANK ASSEMBLY 96  
BLUEPRINT DATE : CAMI ECH

MACHINE No. :  
ECL. : Y09-1751

OPERATION DESCRIPTION: SPOT WELD 2 BRACKETS P/N 89177-61A00 (4 WELDS), AND 1 P/N 89176-61A00 (2 WELDS) TO OUTER POT P/N 89171-61A00

- STANDARD RULES : 1 - OPERATOR IS RESPONSIBLE FOR PRODUCING QUALITY PARTS IN STATISTICAL CONTROL.  
 2 - OPERATOR IS RESPONSIBLE FOR COMPLETING CONTROL CHARTS ACCORDING TO THE CONTROL PLAN.  
 3 - IF PROCESS IS OUT OF STATISTICAL CONTROL, CONDUCT THE FOLLOWING


- A) SHUT PROCESS DOWN.  
 B) CONTACT YOUR SUPERVISOR.  
 C) WRITE THE PROBLEM AND / OR CAUSE ON THE CONTROL CHARTS.  
 D) WRITE CORRECTIVE ACTION ON CONTROL CHART.  
 E) SORT PRODUCTION 100 % FROM LAST GOOD CHECK WITHIN BLUEPRINT SPECIFICATION.

\* ALL REPAIRS  
& REWORK SHALL BE  
RE-INSPECTED AS PER  
PART QUALITY PLAN

SCHEMATIC OF OPERATION

OPERATOR TO CHECK

89176-61A00



89177-61A00

89177-61A00

1. FILL OUT THE MACHINE LOG AT THE START OF SHIFT.
2. FILL OUT LOT TRACEABILITY.
3. FILL OUT INPROCESS CHECKS AS PER CONTROL PLAN.
4. COMPARE TO MASTER SAMPLE.
5. PRY TEST 100%.
6. VISUAL CHECK FOR RUST, MISFORMED, SPLITS, AND BURRS - NONE ALLOWED.

AS 279950

VERIFY CONTAINERS FOR  
DEBRIS/DAMAGE/LABELS

1-15-96

ISSUED BY: MINDEE MINOS

PLANT QUALITY MANAGER

*J. Legrand*

REVISION LEVEL : "0"  
REASON: INITIAL

FILE: OPT-1

ENGINEERING APPROVAL

*[Signature]*

CORPORATE Q.A. MANAGER

*[Signature]*

PLANT MANAGER

*[Signature]*

CUSTOMER COMPLAINTS TO BE ITEMIZED ON BACK OF SHEET :

EA12-005  
PRODUCED BY SUZUKI MOTOR CORPORATION

**PART**

PART IN PROCESS OPERATION SHEET

T-2-B  
DATE : 01/12/96

2/17

OPERATOR & SAFETY INSTRUCTION : 1 - MUST WEAR SAFETY SHOES, EAR PLUGS, ARM GUARDS, SAFETY GLASSES AND GLOVES

- 2 - CHECK : A) WORK AREAS MUST BE FREE OF OIL AND DEBRIS.  
 B) ALL GUARDS IN THEIR PROPER POSITION.  
 C) SELECTOR SWITCHES LOCKED IN PROPER POSITION.  
 D) DIE CLAMPS TIGHT AND FREE OF FOREIGN OBJECTS.  
 E) PRESS AND PALM BUTTON CHECK.

ACCEPTANCE  
CRITERIA  
"0 DEFECTS"

COMPANY : CAMI AUTOMOTIVE  
PART NUMBER : 30018268

PART NAME : 4 DOOR GAS TANK ASSEMBLY 96  
BLUEPRINT DATE : CAMI ECK

MACHINE No. :  
ECL. : Y09-1731

OPERATION DESCRIPTION: INSTALL INNER CAN P/N 89172-56B00 ONTO MACHINE. WELD OUTER POT P/N 89171-61A00 TO INNER POT - 6 SPOT WELDS 89171-61A00


- STANDARD RULES : 1 - OPERATOR IS RESPONSIBLE FOR PRODUCING QUALITY PARTS IN STATISTICAL CONTROL.  
 2 - OPERATOR IS RESPONSIBLE FOR COMPLETING CONTROL CHARTS ACCORDING TO THE CONTROL PLAN.  
 3 - IF PROCESS IS OUT OF STATISTICAL CONTROL, CONDUCT THE FOLLOWING

- A) SHUT PROCESS DOWN.  
 B) CONTACT YOUR SUPERVISOR.  
 C) WRITE THE PROBLEM AND / OR CAUSE ON THE CONTROL CHARTS.  
 D) WRITE CORRECTIVE ACTION ON CONTROL CHART.  
 E) SORT PRODUCTION 100 % FROM LAST GOOD CHECK WITHIN BLUEPRINT SPECIFICATION.

\* ALL REPAIRS  
& REWORK SHALL BE  
RE-INSPECTED AS PER  
PART QUALITY PLAN

SCHEMATIC OF OPERATION

OPERATOR TO CHECK



1. FILL OUT THE MACHINE LOG AT THE START OF SHIFT.
2. FILL OUT LOT TRACEABILITY.
3. FILL OUT INPROCESS CHECKS AS PER CONTROL PLAN.
4. COMPARE TO MASTER SAMPLE.
5. PRY TEST 100%.
6. VISUAL CHECK FOR RUST, MISFORMED, SPLITS, AND BURRS - NONE ALLOWED.

VERIFY CONTAINERS FOR  
DEBRIS/DAMAGE/LABELS

AS 279951

**A** PART

REVISION LEVEL : "0"  
REASON: INITIAL

ISSUED BY: MINDEE NIKOS

PLANT QUALITY MANAGER: *J. Taggart*

FILE: OPT-2

ENGINEERING APPROVAL *[Signature]*

CORPORATE Q.A. MANAGER *[Signature]*

PLANT MANAGER *[Signature]*

CUSTOMER COMPLAINTS TO BE ITEMIZED ON BACK OF SHEET :

EA12-005  
PRODUCED BY SUZUKI MOTOR CORPORATION

PART IN PROCESS OPERATION SHEET

7-2-B

3/7

DATE : 01/12/96

- OPERATOR & SAFETY INSTRUCTION : 1 - MUST WEAR SAFETY SHOES, EAR PLUGS, ARM GUARDS, SAFETY GLASSES AND GLOVES  
 2 - CHECK : A) WORK AREAS MUST BE FREE OF OIL AND DEBRIS.  
 B) ALL GUARDS IN THEIR PROPER POSITION.  
 C) SELECTOR SWITCHES LOCKED IN PROPER POSITION.  
 D) DIE CLAMPS TIGHT AND FREE OF FOREIGN OBJECTS.  
 E) PRESS AND PALM BUTTON CHECK.

ACCEPTANCE  
 CRITERIA  
 "0 DEFECTS"

COMPANY : CAMI AUTOMOTIVE  
 PART NUMBER : 30018268

PART NAME : 4 DOOR GAS TANK ASSEMBLY 96  
 BLUEPRINT DATE : CAMI ECM

MACHINE No. :  
 ECL. : Y09-1731

OPERATION DESCRIPTION: SPOT WELD P/N 89124-51F00 (LARGE RING) TO P/N 89111-57B30 UPPER HALF) 6 SPOT WELDS


- STANDARD RULES : 1 - OPERATOR IS RESPONSIBLE FOR PRODUCING QUALITY PARTS IN STATISTICAL CONTROL.  
 2 - OPERATOR IS RESPONSIBLE FOR COMPLETING CONTROL CHARTS ACCORDING TO THE CONTROL PLAN.  
 3 - IF PROCESS IS OUT OF STATISTICAL CONTROL, CONDUCT THE FOLLOWING

- A) SHUT PROCESS DOWN.  
 B) CONTACT YOUR SUPERVISOR.  
 C) WRITE THE PROBLEM AND / OR CAUSE ON THE CONTROL CHARTS.  
 D) WRITE CORRECTIVE ACTION ON CONTROL CHART.  
 E) SORT PRODUCTION 100 % FROM LAST GOOD CHECK WITHIN BLUEPRINT SPECIFICATION.

\* ALL REPAIRS  
 & REWORK SHALL BE  
 RE-INSPECTED AS PER  
 PART QUALITY PLAN

SCHEMATIC OF OPERATION

OPERATION #1



OPERATOR TO CHECK

1. FILL OUT THE MACHINE LOG AT THE START OF SHIFT.
2. FILL OUT LOT TRACEABILITY.
3. FILL OUT INPROCESS CHECKS AS PER CONTROL PLAN.
4. COMPARE TO MASTER SAMPLE.
5. PRT TEST 100%.
6. VISUAL CHECK FOR RUST, MISFORMED, SPLITS, AND BURRS - NONE ALLOWED.

VERIFY CONTAINERS FOR

DEBRIS/DAMAGE/LABELS 1-15 96

AS 279952

PART

ISSUED BY: HINDEE KINOS

PLANT QUALITY MANAGER: *[Signature]*

REVISION LEVEL : "0"  
 REASON: INITIAL

FILE: OPT-3

ENGINEERING APPROVAL *[Signature]*

CORPORATE Q.A. MANAGER *[Signature]*

PLANT MANAGER *[Signature]*

CUSTOMER COMPLAINTS TO BE ITEMIZED ON BACK OF SHEET :

EA12-005  
 PRODUCED BY SUZUKI MOTOR CORPORATION

PART IN PROCESS OPERATION SHEET

7-2-B 4/17

DATE : 01/12/96

- OPERATOR & SAFETY INSTRUCTION : 1 - MUST WEAR SAFETY SHOES, EAR PLUGS, ARM GUARDS, SAFETY GLASSES AND GLOVES  
 2 - CHECK : A) WORK AREAS MUST BE FREE OF OIL AND DEBRIS.  
 B) ALL GUARDS IN THEIR PROPER POSITION.  
 C) SELECTOR SWITCHES LOCKED IN PROPER POSITION.  
 D) DIE CLAMPS TIGHT AND FREE OF FOREIGN OBJECTS.  
 E) PRESS AND PALM BUTTON CHECK.

ACCEPTANCE  
 CRITERIA  
 "0 DEFECTS"

COMPANY : CAMI AUTOMOTIVE  
 PART NUMBER : 30018268

PART NAME : 4 DOOR GAS TANK ASSEMBLY 96  
 BLUEPRINT DATE : CAMI ECK

MACHINE No. :  
 ECL. : Y09-1731


OPERATION DESCRIPTION: SPOT WELD P/N 89130-57B20 (BREATHER PIPE) FROM INSIDE OF P/N 89111-57B30 (UPPER HALF) - 2 SPOT WELDS ON THE BRACKET

- STANDARD RULES : 1 - OPERATOR IS RESPONSIBLE FOR PRODUCING QUALITY PARTS IN STATISTICAL CONTROL.  
 2 - OPERATOR IS RESPONSIBLE FOR COMPLETING CONTROL CHARTS ACCORDING TO THE CONTROL PLAN.  
 3 - IF PROCESS IS OUT OF STATISTICAL CONTROL, CONDUCT THE FOLLOWING

- A) SHUT PROCESS DOWN.  
 B) CONTACT YOUR SUPERVISOR.  
 C) WRITE THE PROBLEM AND / OR CAUSE ON THE CONTROL CHARTS.  
 D) WRITE CORRECTIVE ACTION ON CONTROL CHART.  
 E) SORT PRODUCTION 100 % FROM LAST GOOD CHECK WITHIN BLUEPRINT SPECIFICATION.

\* ALL REPAIRS  
 & REWORK SHALL BE  
 RE-INSPECTED AS PER  
 PART QUALITY PLAN

SCHEMATIC OF OPERATION



OPERATOR TO CHECK

1. FILL OUT THE MACHINE LOG AT THE START OF SHIFT.
2. FILL OUT LOT TRACEABILITY.
3. FILL OUT IMPROCESS CHECKS AS PER CONTROL PLAN.
4. COMPARE TO MASTER SAMPLE.
5. PRY TEST 100%.
6. VISUAL CHECK FOR RUST, MISFORMED, SPLITS, AND BURRS - NONE ALLOWED.

AS 279953



REVISION LEVEL : "0"  
 REASON: INITIAL

FILE: OPT-4

ISSUED BY: MINDEE MINOS

PLANT QUALITY MANAGER: *J. Taggart*

ENGINEERING APPROVAL

*[Signature]*

CORPORATE Q.A. MANAGER

*[Signature]*

PLANT MANAGER

*[Signature]*

CUSTOMER COMPLAINTS TO BE ITEMIZED ON BACK OF SHEET :

EA12-005 PRODUCED BY SUZUKI MOTOR CORPORATION

PART IN PROCESS OPERATION SHEET

7-2-B

5/17

DATE : 01/12/96

- OPERATOR & SAFETY INSTRUCTION : 1 - MUST WEAR SAFETY SHOES, EAR PLUGS, ARM GUARDS, SAFETY GLASSES AND GLOVES  
 2 - CHECK : A) WORK AREAS MUST BE FREE OF OIL AND DEBRIS.  
 B) ALL GUARDS IN THEIR PROPER POSITION.  
 C) SELECTOR SWITCHES LOCKED IN PROPER POSITION.  
 D) DIE CLAMPS TIGHT AND FREE OF FOREIGN OBJECTS.  
 E) PRESS AND PALM BUTTON CHECK.

ACCEPTANCE  
 CRITERIA  
 "0 DEFECTS"

COMPANY : CAMI AUTOMOTIVE  
 PART NUMBER : 30018268

PART NAME : 4 DOOR GAS TANK ASSEMBLY 96  
 BLUEPRINT DATE : CAMI ECK

MACHINE No. :  
 ECL. : Y09-1731


OPERATION DESCRIPTION: SPOT WELD P/N 89123-50F00 (MEDIUM RING) TO P/N 89111-57B30 (UPPER HALF) 5 SPOT WELDS

- STANDARD RULES : 1 - OPERATOR IS RESPONSIBLE FOR PRODUCING QUALITY PARTS IN STATISTICAL CONTROL.  
 2 - OPERATOR IS RESPONSIBLE FOR COMPLETING CONTROL CHARTS ACCORDING TO THE CONTROL PLAN.  
 3 - IF PROCESS IS OUT OF STATISTICAL CONTROL, CONDUCT THE FOLLOWING

- A) SHUT PROCESS DOWN.  
 B) CONTACT YOUR SUPERVISOR.  
 C) WRITE THE PROBLEM AND / OR CAUSE ON THE CONTROL CHARTS.  
 D) WRITE CORRECTIVE ACTION ON CONTROL CHART.  
 E) SORT PRODUCTION 100 % FROM LAST GOOD CHECK WITHIN BLUEPRINT SPECIFICATION.

\* ALL REPAIRS  
 & REWORK SHALL BE  
 RE-INSPECTED AS PER  
 PART QUALITY PLAN

SCHEMATIC OF OPERATION



OPERATOR TO CHECK

1. FILL OUT THE MACHINE LOG AT THE START OF SHIFT.
2. FILL OUT LOT TRACEABILITY.
3. FILL OUT INPROCESS CHECKS AS PER CONTROL PLAN.
4. COMPARE TO MASTER SAMPLE.
5. PRT TEST 100%.
6. VISUAL CHECK FOR RUST, MISFORMED, SPLITS, AND BURRS - NONE ALLOWED.

VERIFY CONTAINERS FOR  
 DEBRIS/DAMAGE/LABELS

1-15-96

AS 279954

**A** PART

REVISION LEVEL : "0"  
 REASON: INITIAL

ISSUED BY: HINDEE MINOS

PLANT QUALITY MANAGER: *[Signature]*

FILE: OPT-5

ENGINEERING APPROVAL *[Signature]*

CORPORATE Q.A. MANAGER *[Signature]*

PLANT MANAGER *[Signature]*

CUSTOMER COMPLAINTS TO BE ITEMIZED ON BACK OF SHEET :

EA12-005  
 PRODUCED BY SUZUKI MOTOR CORPORATION

PART IN PROCESS OPERATION SHEET

7-2-B 6/17  
DATE : 01/12/96

- OPERATOR & SAFETY INSTRUCTION : 1 - MUST WEAR SAFETY SHOES, EAR PLUGS, ARM GUARDS, SAFETY GLASSES AND GLOVES  
 2 - CHECK : A) WORK AREAS MUST BE FREE OF OIL AND DEBRIS.  
 B) ALL GUARDS IN THEIR PROPER POSITION.  
 C) SELECTOR SWITCHES LOCKED IN PROPER POSITION.  
 D) DIE CLAMPS TIGHT AND FREE OF FOREIGN OBJECTS.  
 E) PRESS AND PALK BUTTON CHECK.

ACCEPTANCE  
CRITERIA  
"0 DEFECTS"

COMPANY : CAMI AUTOMOTIVE  
PART NUMBER : 30018268

PART NAME : 4 DOOR GAS TANK ASSEMBLY 96  
BLUEPRINT DATE : CAMI ECM

MACHINE No. :  
ECL. : Y09-1731.


OPERATION DESCRIPTION: PROJECTION WELD P/N 89129-66A00 (P-SENSOR RING) TO P/N 89111-57B30 (UPPER HALF) - 4 SPOT WELDS THE BRACKET

- STANDARD RULES : 1 - OPERATOR IS RESPONSIBLE FOR PRODUCING QUALITY PARTS IN STATISTICAL CONTROL.  
 2 - OPERATOR IS RESPONSIBLE FOR COMPLETING CONTROL CHARTS ACCORDING TO THE CONTROL PLAN.  
 3 - IF PROCESS IS OUT OF STATISTICAL CONTROL, CONDUCT THE FOLLOWING

- A) SHUT PROCESS DOWN.  
 B) CONTACT YOUR SUPERVISOR.  
 C) WRITE THE PROBLEM AND / OR CAUSE ON THE CONTROL CHARTS.  
 D) WRITE CORRECTIVE ACTION ON CONTROL CHART.  
 E) SORT PRODUCTION 100 % FROM LAST GOOD CHECK WITHIN BLUEPRINT SPECIFICATION.

\* ALL REPAIRS  
& REWORK SHALL BE  
RE-INSPECTED AS PER  
PART QUALITY PLAN

SCHEMATIC OF OPERATION



OPERATOR TO CHECK

1. FILL OUT THE MACHINE LOG AT THE START OF SHIPT.
2. FILL OUT LOT TRACEABILITY.
3. FILL OUT INPROCESS CHECKS AS PER CONTROL PLAN.
4. COMPARE TO MASTER SAMPLE.
5. PRY TEST 100%.
6. VISUAL CHECK FOR RUST, MISFORMED, SPLITS, AND BURRS - NONE ALLOWED.

AS 279955

**A PART**

VERIFY CONTAINERS FOR

DEBRIS/DAMAGE/LABELS 1-15-96

REVISION LEVEL : "0"  
REASON: INITIAL

ISSUED BY: MINDEE MINOS

PLANT QUALITY MANAGER: *J. Taggart*

FILE: OPT-6

ENGINEERING APPROVAL *[Signature]*

CORPORATE Q.A. MANAGER *[Signature]*

PLANT MANAGER *[Signature]*

CUSTOMER COMPLAINTS TO BE ITENIZED ON BACK OF SHEET :

EA12-005  
PRODUCED BY SUZUKI MOTOR CORPORATION

PART IN PROCESS OPERATION SHEET

7-2-B 7/17  
DATE : 01/12/96

OPERATOR & SAFETY INSTRUCTION : 1 - MUST WEAR SAFETY SHOES, EAR PLUGS, ARM GUARDS, SAFETY GLASSES AND GLOVES  
 2 - CHECK : A) WORK AREAS MUST BE FREE OF OIL AND DEBRIS.  
 B) ALL GUARDS IN THEIR PROPER POSITION.  
 C) SELECTOR SWITCHES LOCKED IN PROPER POSITION.  
 D) DIE CLAMPS TIGHT AND FREE OF FOREIGN OBJECTS.  
 E) PRESS AND PALM BUTTON CHECK.

ACCEPTANCE  
CRITERIA  
"0 DEFECTS"

COMPANY : CAMI AUTOMOTIVE  
PART NUMBER : 30018268

PART NAME : 4 DOOR GAS TANK ASSEMBLY 96  
BLUEPRINT DATE : CAMI ECH

MACHINE No. :  
ECL. : Y09-1731


OPERATION DESCRIPTION: SPOT WELD P/N 89122-56B00 (SMALL RING) TO P/N 89111-57B30 (UPPER HALF) 3 SPOT WELDS

STANDARD RULES : 1 - OPERATOR IS RESPONSIBLE FOR PRODUCING QUALITY PARTS IN STATISTICAL CONTROL.  
 2 - OPERATOR IS RESPONSIBLE FOR COMPLETING CONTROL CHARTS ACCORDING TO THE CONTROL PLAN.  
 3 - IF PROCESS IS OUT OF STATISTICAL CONTROL, CONDUCT THE FOLLOWING

- A) SHUT PROCESS DOWN.
- B) CONTACT YOUR SUPERVISOR.
- C) WRITE THE PROBLEM AND / OR CAUSE ON THE CONTROL CHARTS.
- D) WRITE CORRECTIVE ACTION ON CONTROL CHART.
- E) SORT PRODUCTION 100 % FROM LAST GOOD CHECK WITHIN BLUEPRINT SPECIFICATION.

\* ALL REPAIRS  
& REWORK SHALL BE  
RE-INSPECTED AS PER  
PART QUALITY PLAN

SCHEMATIC OF OPERATION



OPERATOR TO CHECK

1. FILL OUT THE MACHINE LOG AT THE START OF SHIFT.
2. FILL OUT LOT TRACEABILITY.
3. FILL OUT INPROCESS CHECKS AS PER CONTROL PLAN.
4. COMPARE TO MASTER SAMPLE.
5. PRT TEST 100%.
6. VISUAL CHECK FOR RUST, MISFORMED, SPLITS, AND BURRS - NONE ALLOWED.

AS 279956

**A PART**

VERIFY CONTAINERS FOR  
DEBRIS/DAMAGE/LABELS 1-15-96

REVISION LEVEL : "0"  
REASON: INITIAL

ISSUED BY: MINDEE KINOS

PLANT QUALITY MANAGER: *J. Taggart*

FILE: OPT-7

ENGINEERING APPROVAL *[Signature]*

CORPORATE Q.A. MANAGER *[Signature]*

PLANT MANAGER *[Signature]*

CUSTOMER COMPLAINTS TO BE ITEMIZED ON BACK OF SHEET :

EA12-005 PRODUCED BY SUZUKI MOTOR CORPORATION



PART IN PROCESS OPERATION SHEET

7-2-B

8/17

DATE : 01/12/96

- OPERATOR & SAFETY INSTRUCTION : 1 - MUST WEAR SAFETY SHOES, EAR PLUGS, ARM GUARDS, SAFETY GLASSES AND GLOVES  
 2 - CHECK : A) WORK AREAS MUST BE FREE OF OIL AND DEBRIS.  
 B) ALL GUARDS IN THEIR PROPER POSITION.  
 C) SELECTOR SWITCHES LOCKED IN PROPER POSITION.  
 D) DIE CLAMPS TIGHT AND FREE OF FOREIGN OBJECTS.  
 E) PRESS AND PALM BUTTON CHECK.

ACCEPTANCE  
 CRITERIA  
 "0 DEFECTS"

COMPANY : CAMI AUTOMOTIVE  
 PART NUMBER : 30018268

PART NAME : 4 DOOR GAS TANK ASSEMBLY 96  
 BLUEPRINT DATE : CAMI ECR

MACHINE No. :  
 ECL. : Y09-1731

OPERATION DESCRIPTION: OPERATOR INSTALL TANK HALF UPPER P/N 89111-57B30 ON BRAZE TABLE. PROPERLY CLAMPING SIDES DOWN, ROBOT BRAZES AROUND P/N 89130-57B20 (BREATHER PIPE)


- STANDARD RULES : 1 - OPERATOR IS RESPONSIBLE FOR PRODUCING QUALITY PARTS IN STATISTICAL CONTROL.  
 2 - OPERATOR IS RESPONSIBLE FOR COMPLETING CONTROL CHARTS ACCORDING TO THE CONTROL PLAN.  
 3 - IF PROCESS IS OUT OF STATISTICAL CONTROL, CONDUCT THE FOLLOWING

- A) SHUT PROCESS DOWN.  
 B) CONTACT YOUR SUPERVISOR.  
 C) WRITE THE PROBLEM AND / OR CAUSE ON THE CONTROL CHARTS.  
 D) WRITE CORRECTIVE ACTION ON CONTROL CHART.  
 E) SORT PRODUCTION 100 % FROM LAST GOOD CHECK WITHIN BLUEPRINT SPECIFICATION.

\* ALL REPAIRS  
 & REWORK SHALL BE  
 RE-INSPECTED AS PER  
 PART QUALITY PLAN

SCHEMATIC OF OPERATION

OPERATOR TO CHECK



1. FILL OUT THE MACHINE LOG AT THE START OF SHIFT.
2. FILL OUT LOT TRACEABILITY.
3. FILL OUT INPROCESS CHECKS AS PER CONTROL PLAN.
4. COMPARE TO MASTER SAMPLE.
5. PRY TEST 100%.
6. VISUAL CHECK FOR RUST, MISFORMED, SPLITS, AND BURRS - NONE ALLOWED.

AS 279957

VERIFY CONTAINERS FOR  
 DEBRIS/DAMAGE/LABELS 1-15-96

**A** PART

REVISION LEVEL : "0"  
 REASON: INITIAL

ISSUED BY: MINDIE HINOS

PLANT QUALITY MANAGER: *[Signature]*

FILE: OPT-8

ENGINEERING APPROVAL *[Signature]*

CORPORATE Q.A. MANAGER *[Signature]*

PLANT MANAGER *[Signature]*

CUSTOMER COMPLAINTS TO BE ITEMIZED ON BACK OF SHEET :

EA12-005  
 PRODUCED BY SUZUKI MOTOR CORPORATION

PART IN PROCESS OPERATION SHEET

1-2-B 7/17

DATE : 01/12/96

- OPERATOR & SAFETY INSTRUCTION : 1 - MUST WEAR SAFETY SHOES, EAR PLUGS, ARM GUARDS, SAFETY GLASSES AND GLOVES  
 2 - CHECK : A) WORK AREAS MUST BE FREE OF OIL AND DEBRIS.  
 B) ALL GUARDS IN THEIR PROPER POSITION.  
 C) SELECTOR SWITCHES LOCKED IN PROPER POSITION.  
 D) DIE CLAMPS TIGHT AND FREE OF FOREIGN OBJECTS.  
 E) PRESS AND PALM BUTTON CHECK.

ACCEPTANCE  
 CRITERIA  
 "0 DEFECTS"

COMPANY : CAMI AUTOMOTIVE  
 PART NUMBER : 30018268

PART NAME : 4 DOOR GAS TANK ASSEMBLY 96  
 BLUEPRINT DATE : CAMI ECH

MACHINE No. :  
 ECL. : Y09-1731.


OPERATION DESCRIPTION: SPOT WELD 4 P/N 30003200 (LARGE CLAMPS) (1 WELD EACH CLAMP), 1 P/N 30001095 (SMALL CLAMP) (1 WELD), AND 1 P/N 89178-60A00 (VAPOUR SEP BRACKET) TO P/N 89111-57B30 (UPPER HALF) (2 WELDS) \*\* PRY TEST EACH WELD!

- STANDARD RULES : 1 - OPERATOR IS RESPONSIBLE FOR PRODUCING QUALITY PARTS IN STATISTICAL CONTROL.  
 2 - OPERATOR IS RESPONSIBLE FOR COMPLETING CONTROL CHARTS ACCORDING TO THE CONTROL PLAN.  
 3 - IF PROCESS IS OUT OF STATISTICAL CONTROL, CONDUCT THE FOLLOWING

- A) SHUT PROCESS DOWN.  
 B) CONTACT YOUR SUPERVISOR.  
 C) WRITE THE PROBLEM AND / OR CAUSE ON THE CONTROL CHARTS.  
 D) WRITE CORRECTIVE ACTION ON CONTROL CHART.  
 E) SORT PRODUCTION 100 % FROM LAST GOOD CHECK WITHIN BLUEPRINT SPECIFICATION.

\* ALL REPAIRS  
 & REWORK SHALL BE  
 RE-INSPECTED AS PER  
 PART QUALITY PLAN


SCHEMATIC OF OPERATION



OPERATOR TO CHECK

1. FILL OUT THE MACHINE LOG AT THE START OF SHIFT.
2. FILL OUT LOT TRACEABILITY.
3. FILL OUT INPROCESS CHECKS AS PER CONTROL PLAN.
4. COMPARE TO MASTER SAMPLE.
5. PRY TEST 100%.
6. VISUAL CHECK FOR RUST, MISFORMED, SPLITS, AND BURRS - NONE ALLOWED.

AS 279958



REVISION LEVEL : "0"  
 REASON: INITIAL

VERIFY CONTAINERS FOR  
 DEBRIS/DAMAGE/LABELS 1-15-96

ISSUED BY: MINDEE MINOS

PLANT QUALITY MANAGER

FILE: OPT-9

ENGINEERING APPROVAL

CORPORATE Q.A. MANAGER

PLANT MANAGER

CUSTOMER COMPLAINTS TO BE ITEMIZED ON BACK OF SHEET :

EA12-005  
 PRODUCED BY SUZUKI MOTOR CORPORATION

PART IN PROCESS OPERATION SHEET

7-2-B

DATE : 01/12/96

10/17

OPERATOR & SAFETY INSTRUCTION : 1 - MUST WEAR SAFETY SHOES, EAR PLUGS, ARM GUARDS, SAFETY GLASSES AND GLOVES  
 2 - CHECK : A) WORK AREAS MUST BE FREE OF OIL AND DEBRIS.  
 B) ALL GUARDS IN THEIR PROPER POSITION.  
 C) SELECTOR SWITCHES LOCKED IN PROPER POSITION.  
 D) DIE CLAMPS TIGHT AND FREE OF FOREIGN OBJECTS.  
 E) PRESS AND PALM BUTTON CHECK.

ACCEPTANCE  
 CRITERIA  
 "0 DEFECTS"

COMPANY : CAMI AUTOMOTIVE  
 PART NUMBER : 30018268

PART NAME : 4 DOOR GAS TANK ASSEMBLY 96  
 BLUEPRINT DATE : CAMI ECH

MACHINE No. :  
 ECL. : Y09-1731


OPERATION DESCRIPTION: OPERATOR WELDS ASSEMBLED VESSELS (89170-56B00) INTO P/M 89112-56B00 (TANK LOWER) \*\* 6 SPOT WELDS

STANDARD RULES : 1 - OPERATOR IS RESPONSIBLE FOR PRODUCING QUALITY PARTS IN STATISTICAL CONTROL.  
 2 - OPERATOR IS RESPONSIBLE FOR COMPLETING CONTROL CHARTS ACCORDING TO THE CONTROL PLAN.  
 3 - IF PROCESS IS OUT OF STATISTICAL CONTROL, CONDUCT THE FOLLOWING

- A) SHUT PROCESS DOWN.
- B) CONTACT YOUR SUPERVISOR.
- C) WRITE THE PROBLEM AND / OR CAUSE ON THE CONTROL CHARTS.
- D) WRITE CORRECTIVE ACTION ON CONTROL CHART.
- E) SORT PRODUCTION 100 % FROM LAST GOOD CHECK WITHIN BLUEPRINT SPECIFICATION.

\* ALL REPAIRS  
 & REWORK SHALL BE  
 RE-INSPECTED AS PER  
 PART QUALITY PLAN

SCHEMATIC OF OPERATION




OPERATOR TO CHECK

1. FILL OUT THE MACHINE LOG AT THE START OF SHIFT.
2. FILL OUT LOT TRACEABILITY.
3. FILL OUT INPROCESS CHECKS AS PER CONTROL PLAN.
4. COMPARE TO MASTER SAMPLE.
5. PRT TEST 100%.
6. VISUAL CHECK FOR RUST, MISFORMED, SPLITS, AND BURRS - NONE ALLOWED.

AS 279959

VERIFY CONTAINERS FOR  
 DEBRIS/DAMAGE/LABELS 1-15-96



REVISION LEVEL : "0"  
 REASON: INITIAL

ISSUED BY: KINDEE KINGS

PLANT QUALITY MANAGER: *J. Taggart*

FILE: OPT-10

ENGINEERING APPROVAL *[Signature]*

CORPORATE Q.A. MANAGER *[Signature]*

PLANT MANAGER *[Signature]*

CUSTOMER COMPLAINTS TO BE ITEMIZED ON BACK OF SHEET :

EA12-005  
 PRODUCED BY SUZUKI MOTOR CORPORATION

PART IN PROCESS OPERATION SHEET

7-2-B

11/17

DATE : 01/12/96

- OPERATOR & SAFETY INSTRUCTION : 1 - MUST WEAR SAFETY SHOES, EAR PLUGS, ARM GUARDS, SAFETY GLASSES AND GLOVES  
 2 - CHECK : A) WORK AREAS MUST BE FREE OF OIL AND DEBRIS.  
 B) ALL GUARDS IN THEIR PROPER POSITION.  
 C) SELECTOR SWITCHES LOCKED IN PROPER POSITION.  
 D) DIE CLAMPS TIGHT AND FREE OF FOREIGN OBJECTS.  
 E) PRESS AND PALM BUTTON CHECK.

ACCEPTANCE  
 CRITERIA  
 "0 DEFECTS"

COMPANY : CAMI AUTOMOTIVE  
 PART NUMBER : 30018268

PART NAME : 4 DOOR GAS TANK ASSEMBLY 96  
 BLUEPRINT DATE : CAMI ECM


MACHINE No. :  
 ECL. : Y09-1731

OPERATION DESCRIPTION: SPOT WELD P/N 89111-56B30 (TANK UPPER) TO P/N 89112-56B00 TANK LOWER) (4 SPOT WELDS)

- STANDARD RULES : 1 - OPERATOR IS RESPONSIBLE FOR PRODUCING QUALITY PARTS IN STATISTICAL CONTROL.  
 2 - OPERATOR IS RESPONSIBLE FOR COMPLETING CONTROL CHARTS ACCORDING TO THE CONTROL PLAN.  
 3 - IF PROCESS IS OUT OF STATISTICAL CONTROL, CONDUCT THE FOLLOWING
- A) SHUT PROCESS DOWN.  
 B) CONTACT YOUR SUPERVISOR.  
 C) WRITE THE PROBLEM AND / OR CAUSE ON THE CONTROL CHARTS.  
 D) WRITE CORRECTIVE ACTION ON CONTROL CHART.  
 E) SORT PRODUCTION 100 % FROM LAST GOOD CHECK WITHIN BLUEPRINT SPECIFICATION.
- \* ALL REPAIRS & REWORK SHALL BE RE-INSPECTED AS PER PART QUALITY PLAN

SCHEMATIC OF OPERATION

OPERATOR TO CHECK



1. FILL OUT THE MACHINE LOG AT THE START OF SHIFT.
2. FILL OUT LOT TRACEABILITY.
3. FILL OUT INPROCESS CHECKS AS PER CONTROL PLAN.
4. COMPARE TO MASTER SAMPLE.
5. PRY TEST 100%.
6. VISUAL CHECK FOR RUST, MISFORMED, SPLITS, AND BURRS - NONE ALLOWED.

AS 279960

**A PART**

VERIFY CONTAINERS FOR

DEBRIS/DAMAGE/LABELS 1-15-96

REVISION LEVEL : "0"  
 REASON: INITIAL

ISSUED BY: MINDEE KINOS

PLANT QUALITY MANAGER: *[Signature]*

FILE: OPT-11

ENGINEERING APPROVAL *[Signature]*

CORPORATE Q.A. MANAGER *[Signature]*

PLANT MANAGER *[Signature]*

CUSTOMER COMPLAINTS TO BE ITEMIZED ON BACK OF SHEET :

EA12-005  
 PRODUCED BY SUZUKI MOTOR CORPORATION

PART IN PROCESS OPERATION SHEET

7-2-B 12/17  
DATE : 01/12/96

- OPERATOR & SAFETY INSTRUCTION : 1 - MUST WEAR SAFETY SHOES, EAR PLUGS, ARM GUARDS, SAFETY GLASSES AND GLOVES  
 2 - CHECK : A) WORK AREAS MUST BE FREE OF OIL AND DEBRIS.  
 B) ALL GUARDS IN THEIR PROPER POSITION.  
 C) SELECTOR SWITCHES LOCKED IN PROPER POSITION.  
 D) DIE CLAMPS TIGHT AND FREE OF FOREIGN OBJECTS.  
 E) PRESS AND PALM BUTTON CHECK.

ACCEPTANCE  
CRITERIA  
"0 DEFECTS"

COMPANY : CAMI AUTOMOTIVE  
PART NUMBER : 30018268

PART NAME : 4 DOOR GAS TANK ASSEMBLY 96  
BLUEPRINT DATE : CAMI ECM

MACHINE No. :  
ECL. : Y09-1731


OPERATION DESCRIPTION: TANK IS INSTALLED IN SEAM WELDER AND SEAMED ALONG EDGE OF TANK ALL AROUND. SEAM WELD FUSION OF BOTH HALVES. P/N 89111-57B30 (TANK UPPER) AND P/N 89112-56800 (TANK LOWER)

- STANDARD RULES : 1 - OPERATOR IS RESPONSIBLE FOR PRODUCING QUALITY PARTS IN STATISTICAL CONTROL.  
 2 - OPERATOR IS RESPONSIBLE FOR COMPLETING CONTROL CHARTS ACCORDING TO THE CONTROL PLAN.  
 3 - IF PROCESS IS OUT OF STATISTICAL CONTROL, CONDUCT THE FOLLOWING

- A) SHUT PROCESS DOWN.  
 B) CONTACT YOUR SUPERVISOR.  
 C) WRITE THE PROBLEM AND / OR CAUSE ON THE CONTROL CHARTS.  
 D) WRITE CORRECTIVE ACTION ON CONTROL CHART.  
 E) SORT PRODUCTION 100 % FROM LAST GOOD CHECK WITHIN BLUEPRINT SPECIFICATION.

\* ALL REPAIRS  
& REWORK SHALL BE  
RE-INSPECTED AS PER  
PART QUALITY PLAN

SCHEMATIC OF OPERATION




SEAM WELD

OPERATOR TO CHECK

1. FILL OUT THE MACHINE LOG AT THE START OF SHIFT.
2. FILL OUT LOT TRACEABILITY.
3. FILL OUT INPROCESS CHECKS AS PER CONTROL PLAN.
4. COMPARE TO MASTER SAMPLE.
5. PRY TEST 100%.
6. VISUAL CHECK FOR RUST, MISFORMED, SPLITS, AND BURRS - NONE ALLOWED.
7. FILL OUT CIRCLE A REPORT EACH SHIFT

AS 279961

VERIFY CONTAINERS FOR  
DEBRIS/DAMAGE/LABELS 1-15-96



REVISION LEVEL : "0"  
REASON: INITIAL

ISSUED BY: MINDEE KINOS

PLANT QUALITY MANAGER: *J. Taggart*

FILE: OPT-12

ENGINEERING APPROVAL: *[Signature]*

CORPORATE Q.A. MANAGER: *[Signature]*

PLANT MANAGER: *[Signature]*

CUSTOMER COMPLAINTS TO BE ITEMIZED ON BACK OF SHEET :

EA12-005  
PRODUCED BY SUZUKI MOTOR CORPORATION

PART IN PROCESS OPERATION SHEET

7-2-B 13/17  
DATE : 01/12/96

- OPERATOR & SAFETY INSTRUCTION : 1 - MUST WEAR SAFETY SHOES, EAR PLUGS, ARM GUARDS, SAFETY GLASSES AND GLOVES  
 2 - CHECK : A) WORK AREAS MUST BE FREE OF OIL AND DEBRIS.  
 B) ALL GUARDS IN THEIR PROPER POSITION.  
 C) SELECTOR SWITCHES LOCKED IN PROPER POSITION.  
 D) DIE CLAMPS TIGHT AND FREE OF FOREIGN OBJECTS.  
 E) PRESS AND PALM BUTTON CHECK.

ACCEPTANCE  
CRITERIA  
"0 DEFECTS"

COMPANY : CAMI AUTOMOTIVE  
PART NUMBER : 30018268

PART NAME : 4 DOOR GAS TANK ASSEMBLY 96  
BLUEPRINT DATE : CAMI ECK

MACHINE No. :  
ECL. : Y09-1731.


OPERATION DESCRIPTION: OPERATOR STAMPS JULIAN DATE, YEAR AND NUMBER TANK INTO P/N 89125-60A00 (GUSSET)

- STANDARD RULES : 1 - OPERATOR IS RESPONSIBLE FOR PRODUCING QUALITY PARTS IN STATISTICAL CONTROL.  
 2 - OPERATOR IS RESPONSIBLE FOR COMPLETING CONTROL CHARTS ACCORDING TO THE CONTROL PLAN.  
 3 - IF PROCESS IS OUT OF STATISTICAL CONTROL, CONDUCT THE FOLLOWING

- A) SHUT PROCESS DOWN.  
 B) CONTACT YOUR SUPERVISOR.  
 C) WRITE THE PROBLEM AND / OR CAUSE ON THE CONTROL CHARTS.  
 D) WRITE CORRECTIVE ACTION ON CONTROL CHART.  
 E) SORT PRODUCTION 100 % FROM LAST GOOD CHECK WITHIN BLUEPRINT SPECIFICATION.

\* ALL REPAIRS  
& REWORK SHALL BE  
RE-INSPECTED AS PER  
PART QUALITY PLAN

SCHEMATIC OF OPERATION



OPERATOR TO CHECK

1. FILL OUT THE MACHINE LOG AT THE START OF SHIFT.
2. FILL OUT LOT TRACEABILITY.
3. FILL OUT INPROCESS CHECKS AS PER CONTROL PLAN.
4. COMPARE TO MASTER SAMPLE.
5. PRY TEST 100%.
6. VISUAL CHECK FOR RUST, MISFORMED, SPLITS, AND BURRS - NONE ALLOWED.

VERIFY CONTAINERS FOR  
DEBRIS/DAMAGE/LABELS 1-15-96

AS 279962

**A PART**

ISSUED BY: WINDEE MINOS

PLANT QUALITY MANAGER: *P. Taggart*

REVISION LEVEL : "0"  
REASON: INITIAL

FILE: OPT-14

ENGINEERING APPROVAL *[Signature]*

CORPORATE Q.A. MANAGER *[Signature]*

PLANT MANAGER *[Signature]*

CUSTOMER COMPLAINTS TO BE ITENIZED ON BACK OF SHEET :

EA12-005  
PRODUCED BY SUZUKI MOTOR CORPORATION

PART IN PROCESS OPERATION SHEET

7-2-B

14/17

DATE : 01/12/96

- OPERATOR & SAFETY INSTRUCTION : 1 - MUST WEAR SAFETY SHOES, EAR PLUGS, ARM GUARDS, SAFETY GLASSES AND GLOVES  
 2 - CHECK : A) WORK AREAS MUST BE FREE OF OIL AND DEBRIS.  
 B) ALL GUARDS IN THEIR PROPER POSITION.  
 C) SELECTOR SWITCHES LOCKED IN PROPER POSITION.  
 D) DIE CLAMPS TIGHT AND FREE OF FOREIGN OBJECTS.  
 E) PRESS AND PALM BUTTON CHECK.

ACCEPTANCE  
 CRITERIA  
 "0 DEFECTS"

COMPANY : CAMI AUTOMOTIVE  
 PART NUMBER : 30018268

PART NAME : 4 DOOR GAS TANK ASSEMBLY 96  
 BLUEPRINT DATE : CAMI ECM


MACHINE No.:  
 ECL. : Y09-1731.

OPERATION DESCRIPTION: SPOT WELD GUSSETS 2 - P/N 89125-60A00, 1 - P/N 89126-56B00, 1 - P/N 89127-56B00 TO TANK  
 (2 SPOT WELDS FOR EACH GUSSET)

- STANDARD RULES : 1 - OPERATOR IS RESPONSIBLE FOR PRODUCING QUALITY PARTS IN STATISTICAL CONTROL.  
 2 - OPERATOR IS RESPONSIBLE FOR COMPLETING CONTROL CHARTS ACCORDING TO THE CONTROL PLAN.  
 3 - IF PROCESS IS OUT OF STATISTICAL CONTROL, CONDUCT THE FOLLOWING
- A) SHUT PROCESS DOWN.  
 B) CONTACT YOUR SUPERVISOR.  
 C) WRITE THE PROBLEM AND / OR CAUSE ON THE CONTROL CHARTS.  
 D) WRITE CORRECTIVE ACTION ON CONTROL CHART.  
 E) SORT PRODUCTION 100 % FROM LAST GOOD CHECK WITHIN BLUEPRINT SPECIFICATION.

\* ALL REPAIRS  
 & REWORK SHALL BE  
 RE-INSPECTED AS PER  
 PART QUALITY PLAN

SCHEMATIC OF OPERATION



OPERATOR TO CHECK

1. FILL OUT THE MACHINE LOG AT THE START OF SHIFT.
2. FILL OUT LOT TRACEABILITY.
3. FILL OUT INPROCESS CHECKS AS PER CONTROL PLAN.
4. COMPARE TO MASTER SAMPLE.
5. PRT TEST 100%.
6. VISUAL CHECK FOR RUST, MISFORMED, SPLITS, AND BURRS - NONE ALLOWED.

VERIFY CONTAINERS FOR

DEBRIS/DAMAGE/LABELS 1-15-96

ISSUED BY: KINDEE MINOS

PLANT QUALITY MANAGER: *J. Taggart*

REVISION LEVEL : "0"  
 REASON: INITIAL

AS 279963

**A** PART

FILE: OPT-15

ENGINEERING APPROVAL: *[Signature]*

CORPORATE Q.A. MANAGER: *[Signature]*

PLANT MANAGER: *[Signature]*

CUSTOMER COMPLAINTS TO BE ITEMIZED ON BACK OF SHEET :

EA12-005  
 PRODUCED BY SUZUKI MOTOR CORPORATION

PART IN PROCESS OPERATION SHEET

7-2-B 15/17  
DATE : 01/12/96

- OPERATOR & SAFETY INSTRUCTION : 1 - MUST WEAR SAFETY SHOES, EAR PLUGS, ARM GUARDS, SAFETY GLASSES AND GLOVES  
 2 - CHECK : A) WORK AREAS MUST BE FREE OF OIL AND DEBRIS.  
 B) ALL GUARDS IN THEIR PROPER POSITION.  
 C) SELECTOR SWITCHES LOCKED IN PROPER POSITION.  
 D) DIE CLAMPS TIGHT AND FREE OF FOREIGN OBJECTS.  
 E) PRESS AND PALM BUTTON CHECK.

ACCEPTANCE  
CRITERIA  
"0 DEFECTS"

COMPANY : CAMI AUTOMOTIVE  
PART NUMBER : 30018268

PART NAME : 4 DOOR GAS TANK ASSEMBLY 96  
BLUEPRINT DATE : CAMI ECK

MACHINE No. :  
ECL. : Y09-1731

OPERATION DESCRIPTION: OPERATOR INSERTS FUEL INLET PIPE P/N 89121-82000 INTO TANK. MIG ROBOT MIG WELDS ALL AROUND PIPE.


- STANDARD RULES : 1 - OPERATOR IS RESPONSIBLE FOR PRODUCING QUALITY PARTS IN STATISTICAL CONTROL.  
 2 - OPERATOR IS RESPONSIBLE FOR COMPLETING CONTROL CHARTS ACCORDING TO THE CONTROL PLAN.  
 3 - IF PROCESS IS OUT OF STATISTICAL CONTROL, CONDUCT THE FOLLOWING

- A) SHUT PROCESS DOWN.  
 B) CONTACT YOUR SUPERVISOR.  
 C) WRITE THE PROBLEM AND / OR CAUSE ON THE CONTROL CHARTS.  
 D) WRITE CORRECTIVE ACTION ON CONTROL CHART.  
 E) SORT PRODUCTION 100 % FROM LAST GOOD CHECK WITHIN BLUEPRINT SPECIFICATION.

\* ALL REPAIRS  
& REWORK SHALL BE  
RE-INSPECTED AS PER  
PART QUALITY PLAN

SCHEMATIC OF OPERATION

OPERATOR TO CHECK



1. FILL OUT THE MACHINE LOG AT THE START OF SHIFT.
2. FILL OUT LOT TRACEABILITY.
3. FILL OUT INPROCESS CHECKS AS PER CONTROL PLAN.
4. COMPARE TO MASTER SAMPLE.
5. PRY TEST 100%.
6. VISUAL CHECK FOR RUST, MISFORMED, SPLITS, AND BURRS - NONE ALLOWED.

VERIFY CONTAINERS FOR  
DEBRIS/DAMAGE/LABELS 1-15-96

AS 279964

**(A) PART**

REVISION LEVEL : "0"  
REASON: INITIAL

ISSUED BY: KINDEE MINOS

PLANT QUALITY MANAGER: *[Signature]*

FILE: OPT-13

ENGINEERING APPROVAL *[Signature]*

CORPORATE Q.A. MANAGER *[Signature]*

PLANT MANAGER *[Signature]*

CUSTOMER COMPLAINTS TO BE ITEMIZED ON BACK OF SHEET :

EA12-005  
PRODUCED BY SUZUKI MOTOR CORPORATION



PART IN PROCESS OPERATION SHEET

7-2-B

16/17

DATE : 01/12/96

- OPERATOR & SAFETY INSTRUCTION : 1 - MUST WEAR SAFETY SHOES, EAR PLUGS, ARM GUARDS, SAFETY GLASSES AND GLOVES  
 2 - CHECK : A) WORK AREAS MUST BE FREE OF OIL AND DEBRIS.  
 B) ALL GUARDS IN THEIR PROPER POSITION.  
 C) SELECTOR SWITCHES LOCKED IN PROPER POSITION.  
 D) DIE CLAMPS TIGHT AND FREE OF FOREIGN OBJECTS.  
 E) PRESS AND PALM BUTTON CHECK.

ACCEPTANCE  
 CRITERIA  
 "0 DEFECTS"

COMPANY : CAMI AUTOMOTIVE  
 PART NUMBER : 30018268

PART NAME : 4 DOOR GAS TANK ASSEMBLY 96  
 BLUEPRINT DATE : CAMI ECH


MACHINE No. :  
 ECL. : Y09-1731

OPERATION DESCRIPTION: OPERATOR PLACES TANK ON MIG ROBOT FIXTURE. ROBOT MIG WELDS 3 SPOTS ON EACH GUSSET P/N 89126-56B00 AND P/N 89127-56B00

- STANDARD RULES : 1 - OPERATOR IS RESPONSIBLE FOR PRODUCING QUALITY PARTS IN STATISTICAL CONTROL.  
 2 - OPERATOR IS RESPONSIBLE FOR COMPLETING CONTROL CHARTS ACCORDING TO THE CONTROL PLAN.  
 3 - IF PROCESS IS OUT OF STATISTICAL CONTROL, CONDUCT THE FOLLOWING
- A) SHUT PROCESS DOWN.
  - B) CONTACT YOUR SUPERVISOR.
  - C) WRITE THE PROBLEM AND / OR CAUSE ON THE CONTROL CHARTS.
  - D) WRITE CORRECTIVE ACTION ON CONTROL CHART.
  - E) SORT PRODUCTION 100% FROM LAST GOOD CHECK WITHIN BLUEPRINT SPECIFICATION.

\* ALL REPAIRS  
 & REWORK SHALL BE  
 RE-INSPECTED AS PER  
 PART QUALITY PLAN

SCHEMATIC OF OPERATION



OPERATOR TO CHECK

1. FILL OUT THE MACHINE LOG AT THE START OF SHIFT.
2. FILL OUT LOT TRACEABILITY.
3. FILL OUT INPROCESS CHECKS AS PER CONTROL PLAN.
4. COMPARE TO MASTER SAMPLE.
5. PRY TEST 100%.
6. VISUAL CHECK FOR RUST, MISFORMED, SPLITS, AND BURRS - NONE ALLOWED.

AS 279965

VERIFY CONTAINERS FOR  
 DEBRIS/DAMAGE/LABELS 1-15-96

REVISION LEVEL : "0"  
 REASON: INITIAL

**(A) PART**

ISSUED BY: HINDEE MINOS

PLANT QUALITY MANAGER *[Signature]*

FILE: OPT-16

ENGINEERING APPROVAL *[Signature]*

CORPORATE Q.A. MANAGER *[Signature]*

PLANT MANAGER *[Signature]*

CUSTOMER COMPLAINTS TO BE ITEMIZED ON BACK OF SHEET :

EA12-005  
 PRODUCED BY SUZUKI MOTOR CORPORATION

PART IN PROCESS OPERATION SHEET

7-2-B  
DATE : 01/12/96

17/17

- OPERATOR & SAFETY INSTRUCTION : 1 - MUST WEAR SAFETY SHOES, EAR PLUGS, ARM GUARDS, SAFETY GLASSES AND GLOVES  
 2 - CHECK : A) WORK AREAS MUST BE FREE OF OIL AND DEBRIS.  
 B) ALL GUARDS IN THEIR PROPER POSITION.  
 C) SELECTOR SWITCHES LOCKED IN PROPER POSITION.  
 D) DIE CLAMPS TIGHT AND FREE OF FOREIGN OBJECTS.  
 E) PRESS AND PALM BUTTON CHECK.

ACCEPTANCE  
CRITERIA  
"0 DEFECTS"


COMPANY : CAMI AUTOMOTIVE PART NAME : 4 DOOR GAS TANK ASSEMBLY 96 MACHINE No. :  
 PART NUMBER : 30018268 BLUEPRINT DATE : CAMI ECM ECL. : Y09-1731

OPERATION DESCRIPTION: INSTALL P/N 30017817 (SENDING UNIT) (5 SCREWS), P/N 30014333 (FUEL PUMP) (6 SCREWS). AND P/N 30014579 (CUT VALVE) (3 SCREWS) TO TOP OF TANK. \*\*SCREWS P/N 30003198, 30016310 (O-RING) FLAT PLATE (2 SCREWS) AND PROPERLY MASK TANK AS PER CONTROL PLAN FOR LEAK TESTER.

- STANDARD RULES : 1 - OPERATOR IS RESPONSIBLE FOR PRODUCING QUALITY PARTS IN STATISTICAL CONTROL.  
 2 - OPERATOR IS RESPONSIBLE FOR COMPLETING CONTROL CHARTS ACCORDING TO THE CONTROL PLAN.  
 3 - IF PROCESS IS OUT OF STATISTICAL CONTROL, CONDUCT THE FOLLOWING

- A) SHUT PROCESS DOWN.  
 B) CONTACT YOUR SUPERVISOR.  
 C) WRITE THE PROBLEM AND / OR CAUSE ON THE CONTROL CHARTS.  
 D) WRITE CORRECTIVE ACTION ON CONTROL CHART.  
 E) SORT PRODUCTION 100 % FROM LAST GOOD CHECK WITHIN BLUEPRINT SPECIFICATION.

\* ALL REPAIRS & REWORK SHALL BE RE-INSPECTED AS PER PART QUALITY PLAN



OPERATOR TO CHECK

1. FILL OUT THE MACHINE LOG AT THE START OF SHIFT.
2. FILL OUT LOT TRACEABILITY.
3. FILL OUT INPROCESS CHECKS AS PER CONTROL PLAN.
4. COMPARE TO MASTER SAMPLE.
5. PRT TEST 100%.
6. VISUAL CHECK FOR RUST, MISFORMED, SPLITS, AND BURRS - NONE ALLOWED.

AS 279966

**(A) PART**

REVISION LEVEL : "0"  
REASON: INITIAL

ISSUED BY: MINDEE MINOS

PLANT QUALITY MANAGER: *Y. Taggar* 1-15-96

FILE: OPT-17

ENGINEERING APPROVAL *[Signature]* CORPORATE Q.A. MANAGER *[Signature]* PLANT MANAGER *[Signature]*

CUSTOMER COMPLAINTS TO BE ITEMIZED ON BACK OF SHEET :

EA12-005  
PRODUCED BY SUZUKI MOTOR CORPORATION

# PART IN PROCESS OPERATION SHEET

7-2-C page 1/2  
DATE : 03/07/97

- OPERATOR & SAFETY INSTRUCTION : 1 - MUST WEAR SAFETY SHOES, EAR PLUGS, ARM GUARDS, SAFETY GLASSES AND GLOVES  
 2 - CHECK : A) WORK AREAS MUST BE FREE OF OIL AND DEBRIS.  
 B) ALL GUARDS IN THEIR PROPER POSITION.  
 C) SELECTOR SWITCHES LOCKED IN PROPER POSITION.  
 D) DIE CLAMPS TIGHT AND FREE OF FOREIGN OBJECTS.  
 E) PRESS AND PALM BUTTON CHECK.

**ACCEPTANCE  
CRITERIA**  
"0 DEFECTS"

COMPANY : CAMI AUTOMOTIVE  
PART NUMBER : 30019888

PART NAME : 4 DOOR GAS TANK ASSEMBLY  
BLUEPRINT DATE : 06/12/96

MACHINE No. :  
ECL. : 60A-9380


OPERATION DESCRIPTION: SPOT WELD GUSSETS 2 - P/N 30019611 (89125-57B30), 1 - P/N 89126-56B00, 1 - P/N 89127-56B00 TO TANK  
(2 SPOT WELDS FOR EACH GUSSET)

- STANDARD RULES : 1 - PRODUCTION IS RESPONSIBLE FOR PRODUCING QUALITY PARTS IN STATISTICAL CONTROL.  
 2 - PRODUCTION IS RESPONSIBLE FOR COMPLETING CONTROL CHARTS ACCORDING TO THE CONTROL PLAN.  
 3 - IF PROCESS IS OUT OF STATISTICAL CONTROL, CONDUCT THE FOLLOWING

- A) SHUT PROCESS DOWN  
 B) CONTACT YOUR SUPERVISOR.  
 C) WRITE THE PROBLEM AND / OR CAUSE ON THE CONTROL CHARTS.  
 D) WRITE CORRECTIVE ACTION ON CONTROL CHART.  
 E) SORT PRODUCTION 100 % FROM LAST GOOD CHECK WITHIN BLUEPRINT SPECIFICATION.

**& ALL REPAIRS  
& REWORK SHALL BE  
RE-INSPECTED AS PER  
PART QUALITY PLAN**

**SCHEMATIC OF OPERATION**



**OPERATOR TO CHECK**

1. FILL OUT THE MACHINE LOG AT THE START OF SHIFT.
2. FILL OUT LOT TRACEABILITY.
3. FILL OUT INPROCESS CHECKS AS PER CONTROL PLAN.
4. COMPARE TO MASTER SAMPLE.
5. PRY TEST 100%. ←
6. VISUAL CHECK FOR RUST, MISFORMED, SPLITS, AND BURRS - NONE ALLOWED.

A **PART**

**VERIFY CONTAINERS FOR  
DEBRIS/DAMAGE/LABELS** 3-13-97

**AS 279967**

REVISION LEVEL : \*3\*  
REASON: NEW ECL

ISSUED BY: KATHLEEN SCOTT

PLANT QUALITY MANAGER: *[Signature]*

FILE: OPT-15

ENGINEERING APPROVAL: *[Signature]* CORPORATE Q.A. MANAGER: *[Signature]* PLANT MANAGER: *[Signature]*

EA12-005 PRODUCED BY SUZUKI MOTOR CORPORATION

# PART IN PROCESS OPERATION SHEET

7-2-C page 2/2

DATE : 03/07/97

OPERATOR & SAFETY INSTRUCTION : 1 - MUST WEAR SAFETY SHOES, EAR PLUGS, ARM GUARDS, SAFETY GLASSES AND GLOVES

2 - CHECK : A) WORK AREAS MUST BE FREE OF OIL AND DEBRIS.

B) ALL GUARDS IN THEIR PROPER POSITION.

C) SELECTOR SWITCHES LOCKED IN PROPER POSITION.

D) DIE CLAMPS TIGHT AND FREE OF FOREIGN OBJECTS.

E) PRESS AND PALK BUTTON CHECK.

ACCEPTANCE  
CRITERIA  
"0 DEFECTS"

COMPANY : CAMI AUTOMOTIVE  
PART NUMBER : 30019888

PART NAME : 4 DOOR GAS TANK ASSEMBLY  
BLUEPRINT DATE : 06/12/96

MACHINE No. :  
ECL. : 60A-9380

OPERATION DESCRIPTION: OPERATOR STAMPS JULIAN DATE, YEAR AND NUMBER TANK INTO P/N 30019611 (89125-57B30) GUSSET.

STANDARD RULES : 1 - PRODUCTION IS RESPONSIBLE FOR PRODUCING QUALITY PARTS IN STATISTICAL CONTROL.

2 - PRODUCTION IS RESPONSIBLE FOR COMPLETING CONTROL CHARTS ACCORDING TO THE CONTROL PLAN.

3 - IF PROCESS IS OUT OF STATISTICAL CONTROL, CONDUCT THE FOLLOWING

A) SHUT PROCESS DOWN.

B) CONTACT YOUR SUPERVISOR.

C) WRITE THE PROBLEM AND / OR CAUSE ON THE CONTROL CHARTS.

D) WRITE CORRECTIVE ACTION ON CONTROL CHART.


E) SORT PRODUCTION 100 % FROM LAST GOOD CHECK WITHIN BLUEPRINT SPECIFICATION.

\* ALL REPAIRS  
& REWORK SHALL BE  
RE-INSPECTED AS PER  
PART QUALITY PLAN

### SCHEMATIC OF OPERATION

OPERATION #14

30019611  
(89125-57B30)



### OPERATOR TO CHECK

1. FILL OUT THE MACHINE LOG AT THE START OF SHIFT.
2. FILL OUT LOT TRACEABILITY.
3. FILL OUT INPROCESS CHECKS AS PER CONTROL PLAN.
4. COMPARE TO MASTER SAMPLE.
5. PRY TEST 100%.
6. VISUAL CHECK FOR RUST, MISFORMED, SPLITS, AND BURRS - NONE ALLOWED.

A PART

VERIFY CONTAINERS FOR

DEBRIS/DAMAGE/LABELS 3-13-97

AS 279968

REVISION LEVEL : "3"  
REASON: NEW ECL

ISSUED BY: KATHLEEN SCOTT

PLANT QUALITY MANAGER: *[Signature]*

FILE: OPT-14

ENGINEERING APPROVAL: *[Signature]*

CORPORATE Q.A. MANAGER: *[Signature]*

PLANT MANAGER: *[Signature]*

EA12-005 PRODUCED BY SUZUKI MOTOR CORPORATION

7-3-A page 1/4

# The Narmco Group - Process Flow Diagram ACCEPTANCE CRITERIA ZERO DEFECTS

\* ALL REPAIRS & REMORK SHALL BE REINSPECTED AS PER QUALITY PLAN

- Circle - Move ( all steps in the system where the object under study moves from one location to another).
- Triangle - Store ( all steps in the system where the object under study remains at rest, either temporarily or permanently).
- Diamond - Fabrication ( all steps in the system where the object undergoes a change in form, condition or content).
- Square - Inspection ( all steps in the system where the object under study is checked for completeness, quality or quantity).

Plant : PRINCE METAL PRODUCTS LTD.

Part Name : TRUCK FUEL TANK ASSEMBLY

Part Number : 30018740 (89019-57B62)

B/P Date : CAMI E.C.N.

Level : 77E-1647

Customer : CAMI AUTOMOTIVE

Date Submitted : APRIL 22, 1996

REVISION LEVEL: "1" NEW PUMP P/N 30018726

| Step | Fabr. Move Store Insp. | Operation Description  | Affected Control Char.                     | Variation Factor                     |
|------|------------------------|--|--|--------------------------------------|
| 1    | ◆                      | PROJECTION WELD (2) P/N 08315-01059 WELD NUTS 5 MM TO P/N 89178-60A00 BRACKET                | WELD INTEGRITY, WELD SPLASH, OFF LOCATION  | WELDER SCHEDULE PROPERLY MAINTAINED  |
| 2    | ◆                      | SPOT WELD P/N 89176-61A00 & P/N 89177-61A00 BRACKETS TO P/N 89171-61A00 OUTER VESSEL 6 SPOTS | WELD INTEGRITY, WELD SPLASH, OFF LOCATION  | WELDER SCHEDULE PROPERLY MAINTAINED  |
| 3    | ◆                      | SPOT WELD P/N 89172-56B00 INNER VESSEL TO P/N 89171-61A00 OUTER VESSEL 6 SPOTS               | WELD INTEGRITY, WELD SPLASH, OFF LOCATION  | WELDER SCHEDULE PROPERLY MAINTAINED  |
| 4    | ◆                      | SPOT WELD P/N 89124-51F00 (LARGE RING) TO P/N 89111-57B30 (UPPER HALF) (6 SPOTS)             | WELD INTEGRITY, WELD SPLASH, OFF LOCATION  | WELDER SCHEDULE PROPERLY MAINTAINED  |
| 5    | ◆                      | SPOT WELD P/N 89130-57B20 (BREATHHER PIPE) TO P/N 89111-57B30 (UPPER HALF) (2 SPOTS)         | WELD INTEGRITY, WELD SPLASH, OFF LOCATION  | WELDER SCHEDULE PROPERLY MAINTAINED  |
| 6    | ◆                      | SPOT WELD P/N 89123-50F00 (MEDIUM RING) TO P/N 89111-57B30 (UPPER HALF) (5 SPOTS)            | WELD INTEGRITY, WELD SPLASH, OFF LOCATION  | WELDER SCHEDULE PROPERLY MAINTAINED  |
| 7    | ◆                      | SPOT WELD P/N 89129-66A00 (SMALL RING) TO P/N 89111-57B30 (TANK UFFER) (4 SPOTS)             | WELD INTEGRITY, WELD SPLASH, OFF LOCATION  | WELDER SCHEDULE PROPERLY MAINTAINED  |
| 8    | ◆                      | SPOT WELD P/N 89122-56B00 (CUT VALVE RING) TO P/N 89111-57B30 (3 SPOTS)                      | CORRECT TANK NUMBER, YEAR, AND JULIAN DATE | OPERATOR KNOWLEDGE                   |
| 9    | ◆                      | BRAZE WELD AROUND P/N 89130-57B20 (BREATHHER PIPE)   | WELD INTEGRITY, WELD SPLASH, OFF LOCATION  | WELDER SCHEDULE PROPERLY MAINTAINED. |

AS 279969

CORPORATE PLANT MANAGER: *[Signature]* QUALITY MANAGER: *[Signature]*  
 CORPORATE ENGINEERING: *[Signature]* 5/1/96

7-3-A page 2/4

# The Narmco Group - Process Flow Diagram

## ACCEPTANCE CRITERIA ZERO DEFECTS

\* ALL REPAIRS & REWORK SHALL BE REINSPECTED AS PER QUALITY PLAN

- Circle - Move ( all steps in the system where the object under study moves from one location to another).
- Triangle - Store ( all steps in the system where the object under study remains at rest, either temporarily or permanently).
- Diamond - Fabrication ( all steps in the system where the object undergoes a change in form, condition or content).
- Square - Inspection ( all steps in the system where the object under study is checked for completeness, quality or quantity).

Plant : PRINCE METAL PRODUCTS LTD.

Part Name : TRUCK FUEL TANK ASSEMBLY

Part Number : 30018740 (89019-57862)

B/P Date : CAMI E.C.N.

Level : 77E-1647

Customer : CAMI AUTOMOTIVE

Date Submitted : APRIL 22, 1996

REVISION LEVEL: "1" NEW PUMP P/N 30018726

| Step | Fabr. Move Store Insp. | Operation Description   | Affected Control Char.                     | Variation Factor                    |
|------|------------------------|---|--|-------------------------------------|
| 10   | ◇                      | SPOT WELD P/N 89170-56800 (CAN ASSEMBLY) TO P/N 89112-56800 TANK LWR- 6 SPOT WELDS                          | WELD INTEGRITY, WELD SPLASH, OFF LOCATION  | WELDER SCHEDULE PROPERLY MAINTAINED |
| 11   | ◇                      | SPOT WELD (4) P/N 30003200 (LARGE CLAMP) TO P/N 89111-57830 (UPPER HALF) (1 SPOT WELD EACH CLAMP)           | WELD INTEGRITY, WELD SPLASH, OFF LOCATION  | WELDER SCHEDULE PROPERLY MAINTAINED |
| 12   | ◇                      | SPOT WELD (1) P/N 30001095 (SMALL CLAMP) TO P/N 89111-57830 (TANK UPPER) (1 SPOT)                           | WELD INTEGRITY, WELD SPLASH, OFF LOCATION  | WELDER SCHEDULE PROPERLY MAINTAINED |
| 13   | ◇                      | SPOT WELD P/N 89178-60A00 (LARGE BRKT) TO P/N 89111-57830 (UPPER HALF) (2 SPOTS)                            | WELD INTEGRITY, WELD SPLASH, OFF LOCATION  | WELDER SCHEDULE PROPERLY MAINTAINED |
| 14   | ◇                      | SPOT WELD P/N 89111-57830 (UPPER HALF) TO P/N 89112-56800 (LOWER HALF) (4 SPOTS)                            | WELD INTEGRITY, WELD SPLASH, OFF LOCATION  | WELDER SCHEDULE PROPERLY MAINTAINED |
| 15   | ◇                      | SEAM WELD P/N 89111-57830 (UPPER HALF) TO P/N 89112-56800 (LOWER HALF) TOGETHER                             | WELD INTEGRITY, WELD SPLASH, OFF LOCATION  | WELDER SCHEDULE PROPERLY MAINTAINED |
| 16   | ◇                      | MIG WELD P/N 89121-82000 (FUEL INLET PIPE) TO UPPER TANK ASSEMBLY   | WELD INTEGRITY, WELD SPLASH, OFF LOCATION  | WELDER SCHEDULE PROPERLY MAINTAINED |
| 17   | ◇                      | STAMP LOT TRACEABILITY ONTO P/N 89125-60A00 (GUSSET)  | CORRECT TANK NUMBER, YEAR, AND JULIAN DATE | OPERATOR KNOWLEDGE                  |
| 18   | ◇                      | SPOT WELD 2 P/N 89125-60A00, 1 P/N 89126-56800 AND 1 P/N 89127-56800 GUSSETS TO TANK (2 SPOTS EACH GUSSET). | WELD INTEGRITY, WELD SPLASH, OFF LOCATION  | WELDER SCHEDULE PROPERLY MAINTAINED |

AS 279970

CORPORATE MANAGER: *AS 279970*  
 PLANT MANAGER: *AS 279970*  
 QUALITY MANAGER: *AS 279970*

## The Narmco Group - Process Flow Diagram

**ACCEPTANCE CRITERIA**  
**ZERO DEFECTS**

Plant : PRINCE METAL PRODUCTS LTD.  
 Part Name : TRUCK FUEL TANK ASSEMBLY  
 Part Number : 30018740 (89019-57862)  
 B/P Date : CAMI E.C.N.  
 Level : 77E-1647  
 Customer : CAMI AUTOMOTIVE  
 Date Submitted : APRIL 22, 1996

REVISION LEVEL: "1" NEW PUMP P/N 30018726

- \* ALL REPAIRS & REWORK SHALL BE REINSPECTED AS PER QUALITY PLAN
- Circle - Move ( all steps in the system where the object under study moves from one location to another).
  - Triangle - Store ( all steps in the system where the object under study remains at rest, either temporarily or permanently).
  - Diamond - Fabrication ( all steps in the system where the object undergoes a change in form, condition or content).
  - Square - Inspection ( all steps in the system where the object under study is checked for completeness, quality or quantity).

| Step | Fabr. Move Store Insp. | Operation Description   | Affected Control Char.                    | Variation Factor                    |
|------|------------------------|---|---|-------------------------------------|
| 19   | ◆                      | SECURITY M16 P/N 89126-56800 AND P/N 89127-56800 GUSSETS (6) TO TANK ASSEMBLY | WELD INTEGRITY, WELD SPLASH, OFF LOCATION | WELDER SCHEDULE PROPERLY MAINTAINED |
| 20   | ◆                      | ATTACH P/N 30018726 (FUEL PUMP) TO TANK UPPER - 6 30003198 SCREWS             | TORQUE                                    | TORQUE MAINTENANCE GUN              |
| 21   | ◆                      | ATTACH P/N 30017817 (SENDING UNIT) TO TANK UPPER - 5 30003198 SCREWS          | TORQUE                                    | TORQUE MAINTENANCE GUN              |
| 22   | ◆                      | ATTACH P/N 30014579 (CUT VALVE) TO TANK UPPER - 3 30003198 SCREWS             | TORQUE                                    | TORQUE MAINTENANCE GUN              |
| 23   | ◆                      | INSERT "O" RING AND ATTACH P-SENSOR COVER PLATE                               | MISSING COMPONENT                         | OPERATOR KNOWLEDGE                  |
| 24   | ◆                      | INSTALL PROPER MASKING DEVICES AND LEAK TEST                                  | MISSING COMPONENTS                        | OPERATOR KNOWLEDGE                  |
| 25   | ○                      | PLACE TANK ON CONVEYOR TO PAINT LINE  | DENTS                                     | OPERATOR HANDLING                   |
| 26   | ○                      | HANG TANK ON PAINT LINE   | NONE                                      | NONE                                |
| 27   | ◆                      | PAINT   | PAINT THICKNESS                           | PAINT LINE MAINTENANCE              |

Plant Manager: *[Signature]*  
 Corporate Engineering: *[Signature]*  
 Quality Manager: *[Signature]*  
 Prepared By: M. MINDS

Quality Manager: *[Signature]* 4-27-96  
 Page 3 of 4

AS 279971

7-3-A page 4/4 005

**ACCEPTANCE CRITERIA ZERO DEFECTS**

**The Narmco Group - Process Flow Diagram**

\* ALL REPAIRS & REWORK SHALL BE REINSPECTED AS PER QUALITY PLAN

- Circle - Move ( all steps in the system where the object under study moves from one location to another).
- Triangle - Store ( all steps in the system where the object under study remains at rest, either temporarily or permanently).
- Diamond - Fabrication ( all steps in the system where the object undergoes a change in form, condition or content).
- Square - Inspection ( all steps in the system where the object under study is checked for completeness, quality or quantity).

Plant : PRINCE METAL PRODUCTS LTD.

Part Name : TRUCK FUEL TANK ASSEMBLY

Part Number : 30018740 (89019-57B52)

B/P Date : CAMI E.C.N.


Level : 77E-1E47

Customer : CAMI AUTOMOTIVE

Date Submitted : APRIL 22, 1996

REVISION LEVEL: "1" NEW PUMP P/N 3001B726

| Step | Fabr. Move Store Insp. | Operation Description               | Affected Control Char.                 | Variation Factor   |
|------|------------------------|-------------------------------------|--|--------------------|
| 28   | ○                      | REMOVE FROM PAINT LINE              |  |                    |
| 29   | ◇                      | TDF DRESS ASSEMBLY AND RE-LEAK TEST | INCORRECT ASSEMBLY, MISSING COMPONENTS | OPERATOR KNOWLEDGE |
| 30   | □                      | INSPECT AND PACK                    |  |                    |
| 31   | ○                      | MOVE TO SHIPPING DOCK               |  |                    |
| 32   | ○                      | SHIP TO CAMI                        |  |                    |



CORPORATE QUALITY MANAGER: *[Signature]* PLANT MANAGER: *[Signature]* QUALITY MANAGER: *[Signature]*

CORPORATE ENGINEERING: *[Signature]* 5/1/96

AS 279972



# The Narmco Group -

Plant : PRINCE METAL PRODUCTS LTD.

Part Name : TRUCK FUEL TANK ASSEMBLY

Part Number : 30018268 (89019-57861)

B/P Date : CAMI E.C.N.

Level : Y09-1731

Customer : CAMI AUTOMOTIVE

Date Submitted : JANUARY 12, 1996

REVISION LEVEL: "O" INITIAL



## Process Flow Diagram ACCEPTAN CRITERIA ZERO DEFECTS

ALL REPAIRS & REMORK SHALL BE REINSPECTED AS PER QUALITY PLAN

- Circle - Move ( all steps in the system where the object under study moves from one location to another).
- Triangle - Store ( all steps in the system where the object under study remains at rest, either temporarily or permanently).
- Diamond - Fabrication ( all steps in the system where the object undergoes a change in form, condition or content).
- Square - Inspection ( all steps in the system where the object under study is checked for completeness, quality or quantity).

| Step | Fabr. Move Store Insp. | Operation Description  | Affected Control Char.                     | Variation Factor                     |
|------|------------------------|--|--|--------------------------------------|
| 1    | ◆                      | PROJECTION WELD (2) P/N 08315-01059 WELD NUTS 5 MM TO P/N 89178-60A00 BRACKET                | WELD INTEGRITY, WELD SPLASH, OFF LOCATION  | WELDER SCHEDULE PROPERLY MAINTAINED  |
| 2    | ◆                      | SPOT WELD P/N 89176-61A00 & P/N 89177-61A00 BRACKETS TO P/N 89171-61A00 OUTER VESSEL 6 SPOTS | WELD INTEGRITY, WELD SPLASH, OFF LOCATION  | WELDER SCHEDULE PROPERLY MAINTAINED  |
| 3    | ◆                      | SPOT WELD P/N 89172-56B00 INNER VESSEL TO P/N 89171-61A00 OUTER VESSEL 6 SPOTS               | WELD INTEGRITY, WELD SPLASH, OFF LOCATION  | WELDER SCHEDULE PROPERLY MAINTAINED  |
| 4    | ◆                      | SPOT WELD P/N 89124-51F00 (LARGE RING) TO P/N 89111-57B30 (UPPER HALF) (6 SPOTS)             | WELD INTEGRITY, WELD SPLASH, OFF LOCATION  | WELDER SCHEDULE PROPERLY MAINTAINED  |
| 5    | ◆                      | SPOT WELD P/N 89130-57B20 (BREATHER PIPE) TO P/N 89111-57B30 (UPPER HALF) (2 SPOTS)          | WELD INTEGRITY, WELD SPLASH, OFF LOCATION  | WELDER SCHEDULE PROPERLY MAINTAINED  |
| 6    | ◆                      | SPOT WELD P/N 89123-50F00 (MEDIUM RING) TO P/N 89111-57B30 (UPPER HALF) (5 SPOTS)            | WELD INTEGRITY, WELD SPLASH, OFF LOCATION  | WELDER SCHEDULE PROPERLY MAINTAINED  |
| 7    | ◆                      | SPOT WELD P/N 89129-66A00 (SMALL RING) TO P/N 89111-57B30 (TANK UPPER) (4 SPOTS)             | WELD INTEGRITY, WELD SPLASH, OFF LOCATION  | WELDER SCHEDULE PROPERLY MAINTAINED  |
| 8    | ◆                      | SPOT WELD P/N 89122-56B00 (CUT VALVE RING) TO P/N 89111-57B30 (3 SPOTS)                      | CORRECT TANK NUMBER, YEAR, AND JULIAN DATE | OPERATOR KNOWLEDGE                   |
| 9    | ◆                      | BRAZE WELD AROUND P/N 89130-57B20 (BREATHER PIPE)  | WELD INTEGRITY, WELD SPLASH, OFF LOCATION  | WELDER SCHEDULE PROPERLY MAINTAINED. |

7-3-B 1/4

CORPORATE QUALITY MANAGER: *ADP*  
 CORPORATE ENGINEERING: *[Signature]*  
 PLANT MANAGER: *[Signature]*  
 QUALITY MANAGER: *[Signature]* 1-15-96  
 File Name : 268-FLOW  
 Prepare: -y : M. MINDS  
 Page 1 of 4

AS 279973

# The Narmco Group - Process Flow Diagram

ACCEPTAN  
CRITERIA  
ZERO DEFECTS

Plant : PRINCE METAL PRODUCTS LTD.

Part Name : TRUCK FUEL TANK ASSEMBLY

Part Number : 30018268 (89019-57861)

B/P Date : CAMI E.C.N.

Level : Y09-1731

Customer : CAMI AUTOMOTIVE

Date Submitted : JANUARY 12, 1996

REVISION LEVEL: "0" INITIAL

**A PART**

- Circle - Move ( all steps in the system where the object under study moves from one location to another).
- Triangle - Store ( all steps in the system where the object under study remains at rest, either temporarily or permanently).
- Diamond - Fabrication ( all steps in the system where the object undergoes a change in form, condition or content).
- Square - Inspection ( all steps in the system where the object under study is checked for completeness, quality or quantity).

| Step | Fabr. | Move | Store | Insp. | Operation Description  | Affected Control Char.                     | Variation Factor                    |
|------|-------|------|-------|-------|--|--|-------------------------------------|
| 10   | ◇     |      |       |       | SPOT WELD P/N 89170-56800 (CAN ASSEMBLY) TO P/N 89112-56800 TANK LWR- 6 SPOT WELDS                         | WELD INTEGRITY, WELD SPLASH, OFF LOCATION  | WELDER SCHEDULE PROPERLY MAINTAINED |
| 11   | ◇     |      |       |       | SPOT WELD (4) P/N 30003200 (LARGE CLAMP) TO P/N 89111-57830 (UPPER HALF) (1 SPOT WELD EACH CLAMP)          | WELD INTEGRITY, WELD SPLASH, OFF LOCATION  | WELDER SCHEDULE PROPERLY MAINTAINED |
| 12   | ◇     |      |       |       | SPOT WELD (1) P/N 30001095 (SMALL CLAMP) TO P/N 89111-57830 (TANK UPPER) (1 SPOT)                          | WELD INTEGRITY, WELD SPLASH, OFF LOCATION  | WELDER SCHEDULE PROPERLY MAINTAINED |
| 13   | ◇     |      |       |       | SPOT WELD P/N 89178-60A00 (LARGE BRKT) TO P/N 89111-57830 (UPPER HALF) (2 SPOTS)                           | WELD INTEGRITY, WELD SPLASH, OFF LOCATION  | WELDER SCHEDULE PROPERLY MAINTAINED |
| 14   | ◇     |      |       |       | SPOT WELD P/N 89111-57830 (UPPER HALF) TO P/N 89112-56800 (LOWER HALF) (4 SPOTS)                           | WELD INTEGRITY, WELD SPLASH, OFF LOCATION  | WELDER SCHEDULE PROPERLY MAINTAINED |
| 15   | ◇     |      |       |       | SEAM WELD P/N 89111-57830 (UPPER HALF) TO P/N 89112-56800 (LOWER HALF) TOGETHER                            | WELD INTEGRITY, WELD SPLASH, OFF LOCATION  | WELDER SCHEDULE PROPERLY MAINTAINED |
| 16   | ◇     |      |       |       | M16 WELD P/N 89121-82000 (FUEL INLET PIPE) TO UPPER TANK ASSEMBLY  | WELD INTEGRITY, WELD SPLASH, OFF LOCATION  | WELDER SCHEDULE PROPERLY MAINTAINED |
| 17   | ◇     |      |       |       | STAMP LOT TRACEABILITY ONTO P/N 89125-60A00 (GUSSET)   | CORRECT TANK NUMBER, YEAR, AND JULIAN DATE | OPERATOR KNOWLEDGE                  |
| 18   | ◇     |      |       |       | SPOT WELD 2 P/N 89125-60A00, 1 P/N 89126-56800 AND 1 P/N 89127-56800 GUSSETS TO TANK (2 SPOTS EACH GUSSET) | WELD INTEGRITY, WELD SPLASH, OFF LOCATION  | WELDER SCHEDULE PROPERLY MAINTAINED |

CORPORATE QUALITY MANAGER:

*AD Mast*

CORPORATE ENGINEERING:

*[Signature]*

PLANT MANAGER:

*[Signature]*

QUALITY MANAGER:

*[Signature]* 1-15-96

File Name : 268FLOW2

Prepared by : M. MINDS

Page 2 of 4

7-3-B 2/4

AS 279974

# The Narmco Group -

Plant : PRINCE METAL PRODUCTS LTD.

Part Name : TRUCK FUEL TANK ASSEMBLY

Part Number : 30018268 (89019-57861)

B/P Date : CAMI E.C.N.

Level : Y09-1731

Customer : CAMI AUTOMOTIVE

Date Submitted : JANUARY 12, 1996

REVISION LEVEL: "0" INITIAL

**PART**

**Process Flow Diagram ACCEPTAN CRITERI. ZERO DEFECTS**

ALL REPAIRS & REMORK SHALL BE REINSPECTED AS PER QUALITY PLAN

- Circle - Move ( all steps in the system where the object under study moves from one location to another).
- Triangle - Store ( all steps in the system where the object under study remains at rest, either temporarily or permanently).
- Diamond - Fabrication ( all steps in the system where the object undergoes a change in form, condition or content).
- Square - Inspection ( all steps in the system where the object under study is checked for completeness, quality or quantity).

| Step | Fabr. Move Store Insp. | Operation Description   | Affected Control Char.                    | Variation Factor                    |
|------|------------------------|---|---|-------------------------------------|
| 19   | ◆                      | SECURITY MIG P/N 89126-56800 AND P/N 89127-56800 GUSSETS (6) TO TANK ASSEMBLY | WELD INTEGRITY, WELD SPLASH, OFF LOCATION | WELDER SCHEDULE PROPERLY MAINTAINED |
| 20   | ○                      | ATTACH P/N 30014333 (FUEL PUMP) TO TANK UPPER - 6 30003198 SCREWS             | TORQUE                                    | TORQUE MAINTENANCE GUN              |
| 21   | ○                      | ATTACH P/N 30017817 (SENDING UNIT) TO TANK UPPER - 5 30003198 SCREWS          | TORQUE                                    | TORQUE MAINTENANCE GUN              |
| 22   | ○                      | ATTACH P/N 30014579 (CUT VALVE) TO TANK UPPER - 3 30003198 SCREWS             | TORQUE                                    | TORQUE MAINTENANCE GUN              |
| 23   | ○                      | INSERT "O" RING AND ATTACH P-SENSOR COVER PLATE                               | MISSING COMPONENT                         | OPERATOR KNOWLEDGE                  |
| 24   | ○                      | INSTALL PROPER MASKING DEVICES AND LEAK TEST                                  | MISSING COMPONENTS                        | OPERATOR KNOWLEDGE                  |
| 25   | ○                      | PLACE TANK ON CONVEYOR TO PAINT LINE  | DENTS                                     | OPERATOR HANDLING                   |
| 26   | ○                      | HANGS TANK ON PAINT LINE  | NONE                                      | NONE                                |
| 27   | ◆                      | PAINT   | PAINT THICKNESS                           | PAINT LINE MAINTENANCE              |

7-2-B

QUALITY MANAGER: *[Signature]* Tagged 1-15-96  
Page 3 of 4

PLANT MANAGER: *[Signature]*

CORPORATE ENGINEERING: *[Signature]*  
Prepared by: M. MINOS

CORPORATE QUALITY MANAGER: *[Signature]*

File Name : 268FLOW3

AS 279975

The Narmco Group -

Process Flow Diagram ACCEPTAN  
CRITERI  
ZERO DEFECTS

Plant : PRINCE METAL PRODUCTS LTD.

Part Name : TRUCK FUEL TANK ASSEMBLY

Part Number : 30018268 (89019-57861)

B/P Date : CAMI E.C.N.

Level : Y09-1731

Customer : CAMI AUTOMOTIVE


Date Submitted : JANUARY 12, 1996

REVISION LEVEL: "0" INITIAL



- Circle - Move ( all steps in the system where the object under study moves from one location to another).
- Triangle - Store ( all steps in the system where the object under study remains at rest, either temporarily or permanently).
- Diamond - Fabrication ( all steps in the system where the object undergoes a change in form, condition or content).
- Square - Inspection ( all steps in the system where the object under study is checked for completeness, quality or quantity).

| Step | Fabr. Move Store Insp. | Operation Description                 | Affected Control Char.                 | Variation Factor   |
|------|------------------------|---------------------------------------|--|--------------------|
| 28   |                        |                                       |  |                    |
| 29   | ○                      | REMOVE FROM PAINT LINE                |  |                    |
| 30   | ◇                      | TOP DRESS ASSEMBLY AND RE-LEAK TEST   |  |                    |
| 31   | ○                      | INSPECT AND PACK                      |  |                    |
| 32   | ○                      | MOVE TO SHIPPING DOCK<br>SHIP TO CAMI | INCORRECT ASSEMBLY, MISSING COMPONENTS | OPERATOR KNOWLEDGE |



CORPORATE QUALITY MANAGER:

CORPORATE ENGINEERING:

PLANT MANAGER:

QUALITY MANAGER:

File Name : 268FLOW4

Prepareu by : M. MINOS

Page 4 of 4

1-15-96

7-3-B

4/4

7-3-C Page 1/4

**The Narmco Group - Product Flow Diagram ACCEPTANCE CRITERIA ZERO DEFECTS**

\* ALL REPAIRS & REMORK SHALL BE REINSPECTED AS PER QUALITY PLAN

- Circle - Move ( all steps in the system where the object under study moves from one location to another).
- Triangle - Store ( all steps in the system where the object under study remains at rest, either temporarily or permanently).
- Diamond - Fabrication ( all steps in the system where the object undergoes a change in form, condition or content).
- Square - Inspection ( all steps in the system where the object under study is checked for completeness, quality or quantity).



Plant : PRINCE METAL PRODUCTS LTD.

Part Name : TRUCK FUEL TANK ASSEMBLY

Part Number : 30019612 (89019-57863)

B/P Date : CAMI E.C.N.

Level : 56B-2445

Customer : CAMI AUTOMOTIVE

Date Submitted : JUNE 20, 1996

REVISION LEVEL: "2" NEW GUSSET P/N 30019611

| Step | Fabr. | Move | Store | Insp. | Operation Description  | Affected Control Char.                     | Variation Factor                     |
|------|-------|------|-------|-------|--|--|--------------------------------------|
| 1    | ◆     |      |       |       | PROJECTION WELD (2) P/N 08315-01059 WELD NUTS 5 MM TO P/N 89178-60A00 BRACKET                | WELD INTEGRITY, WELD SPLASH, OFF LOCATION  | WELDER SCHEDULE PROPERLY MAINTAINED  |
| 2    | ◆     |      |       |       | SPOT WELD P/N 89176-61A00 & P/N 89177-61A00 BRACKETS TO P/N 89171-61A00 OUTER VESSEL 6 SPOTS | WELD INTEGRITY, WELD SPLASH, OFF LOCATION  | WELDER SCHEDULE PROPERLY MAINTAINED  |
| 3    | ◆     |      |       |       | SPOT WELD P/N 89172-56B00 INNER VESSEL TO P/N 89171-61A00 OUTER VESSEL 6 SPOTS               | WELD INTEGRITY, WELD SPLASH, OFF LOCATION  | WELDER SCHEDULE PROPERLY MAINTAINED  |
| 4    | ◆     |      |       |       | SPOT WELD P/N 89124-51F00 (LARGE RING) TO P/N 89111-57B30 (UPPER HALF) (6 SPOTS)             | WELD INTEGRITY, WELD SPLASH, OFF LOCATION  | WELDER SCHEDULE PROPERLY MAINTAINED  |
| 5    | ◆     |      |       |       | SPOT WELD P/N 89130-57B20 (BREATHING PIPE) TO P/N 89111-57E30 (UPPER HALF) (2 SPOTS)         | WELD INTEGRITY, WELD SPLASH, OFF LOCATION  | WELDER SCHEDULE PROPERLY MAINTAINED  |
| 6    | ◆     |      |       |       | SPOT WELD P/N 89123-50F00 (MEDIUM RING) TO P/N 89111-57B30 (UPPER HALF) (5 SPOTS)            | WELD INTEGRITY, WELD SPLASH, OFF LOCATION  | WELDER SCHEDULE PROPERLY MAINTAINED  |
| 7    | ◆     |      |       |       | SPOT WELD P/N 89129-6E400 (SMALL RING) TO P/N 89111-57B30 (TANK UPPER) (4 SPOTS)             | WELD INTEGRITY, WELD SPLASH, OFF LOCATION  | WELDER SCHEDULE PROPERLY MAINTAINED  |
| 8    | ◆     |      |       |       | SPOT WELD P/N 89122-56B00 (CUT VALVE RING) TO P/N 89111-57B30 (3 SPOTS)                      | CORRECT TANK NUMBER, YEAR, AND JULIAN DATE | OPERATOR KNOWLEDGE                   |
| 9    | ◆     |      |       |       | BRAZE WELD AROUND P/N 89130-57B20 (BREATHING PIPE)   | WELD INTEGRITY, WELD SPLASH, OFF LOCATION  | WELDER SCHEDULE PROPERLY MAINTAINED. |

AS 279977

CORPORATE QUALITY MANAGER: *Bob Mac 96-7-7*  
 CORPORATE ENGINEERING: *Bob Mac 7/1/96*  
 PLANT MANAGER: *Ed Jany*  
 QUALITY MANAGER: *J. Jany 6-29-96*

17-3-C Page 3/4

The Narmco Group - Process Flow Diagram ACCEPTANCE CRITERIA ZERO DEFECTS

\* ALL REPAIRS & PENWORK SHALL BE REINSPECTED AS PER QUALITY PLAN

- Circle - Move ( all steps in the system where the object under study moves from one location to another).
- Triangle - Store ( all steps in the system where the object under study remains at rest, either temporarily or permanently).
- Diamond - Fabrication ( all steps in the system where the object undergoes a change in form, condition or content).
- Square - Inspection ( all steps in the system where the object under study is checked for completeness, quality or quantity).

**A PART**

Plant : PRINCE METAL PRODUCTS LTD.

Part Name : TRUCK FUEL TANK ASSEMBLY

Part Number : 30019612 (89019-57863)

B/P Date : CAMI E.C.N.

Level : 568-2445

Customer : CAMI AUTOMOTIVE

Date Submitted : JUNE 20, 1996

REVISION LEVEL: "2" NEW GUSSET P/N 30019611

| Step | Fabr. Move Store Insp. | Operation Description   | Affected Control Char.                     | Variation Factor                    |
|------|------------------------|---|--|-------------------------------------|
| 10   | ◆                      | SPOT WELD P/N 89170-56800 (CAN ASSEMBLY) TO P/N 89112-56800 TANK LWR- 6 SPOT WELDS                                    | WELD INTEGRITY, WELD SPLASH, OFF LOCATION  | WELDER SCHEDULE PROPERLY MAINTAINED |
| 11   | ◆                      | SPOT WELD (4) P/N 30003200 (LARGE CLAMP) TO P/N 89111-57830 (UPPER HALF) (1 SPOT WELD EACH CLAMP)                     | WELD INTEGRITY, WELD SPLASH, OFF LOCATION  | WELDER SCHEDULE PROPERLY MAINTAINED |
| 12   | ◆                      | SPOT WELD (1) P/N 30001095 (SMALL CLAMP) TO P/N 89111-57830 (TANK UPPER) (1 SPOT)                                     | WELD INTEGRITY, WELD SPLASH, OFF LOCATION  | WELDER SCHEDULE PROPERLY MAINTAINED |
| 13   | ◆                      | SPOT WELD P/N 89178-60A00 (LARGE BRKT) TO P/N 89111-57830 (UPPER HALF) (2 SPOTS)                                      | WELD INTEGRITY, WELD SPLASH, OFF LOCATION  | WELDER SCHEDULE PROPERLY MAINTAINED |
| 14   | ◆                      | SPOT WELD P/N 89111-57830 (UPPER HALF) TO P/N 89112-56800 (LOWER HALF) (4 SPOTS)                                      | WELD INTEGRITY, WELD SPLASH, OFF LOCATION  | WELDER SCHEDULE PROPERLY MAINTAINED |
| 15   | ◆                      | SEAM WELD P/N 89111-57830 (UPPER HALF) TO P/N 89112-56800 (LOWER HALF) TOGETHER                                       | WELD INTEGRITY, WELD SPLASH, OFF LOCATION  | WELDER SCHEDULE PROPERLY MAINTAINED |
| 16   | ◆                      | M15 WELD P/N 89121-82000 (FUEL INLET PIPE) TO UPPER TANK ASSEMBLY   | WELD INTEGRITY, WELD SPLASH, OFF LOCATION  | WELDER SCHEDULE PROPERLY MAINTAINED |
| 17   | ◆                      | STAMP LOT TRACEABILITY ONTO P/N 30019611 (GUSSET)   | CORRECT TANK NUMBER, YEAR, AND JULIAN DATE | OPERATOR KNOWLEDGE                  |
| 18   | ◆                      | SPOT WELD 2 P/N 30019611 (89125-57830), 1 P/N 89126-56800 AND 1 P/N 89127-56800 GUSSETS TO TANK (2 SPOTS EACH GUSSET) | WELD INTEGRITY, WELD SPLASH, OFF LOCATION  | WELDER SCHEDULE PROPERLY MAINTAINED |

AS 279978

CORPORATE QUALITY MANAGER:

1996/06/20 08:27:4

CORPORATE ENGINEERING:

7/4/96

PLANT MANAGER:

*SJ*

QUALITY MANAGER:

*Tagged 6-29-96*

7-3-C Page 3/4

**The Narmco Group - Process Flow Diagram**  
**ACCEPTANCE CRITERIA**  
**ZERO DEFECTS**

\* ALL REPAIRS & REWORK SHALL BE REINSPECTED AS PER QUALITY PLAN

- Circle - Move ( all steps in the system where the object under study moves from one location to another).
- Triangle - Store ( all steps in the system where the object under study remains at rest, either temporarily or permanently).
- Diamond - Fabrication ( all steps in the system where the object undergoes a change in form, condition or content).
- Square - Inspection ( all steps in the system where the object under study is checked for completeness, quality or quantity).



Plant : PRINCE METAL PRODUCTS LTD.

Part Name : TRUCK FUEL TANK ASSEMBLY

Part Number : 30019612 (89019-57863)

R/P Date : CAMI E.C.N.

Level : 568-2445

Customer : CAMI AUTOMOTIVE

Date Submitted : JUNE 20, 1996

REVISION LEVEL: "2" NEW GUSSET P/N 30019611

| Step | Fabr. | Move | Store | Insp. | Operation Description   | Affected Control Char.                    | Variation Factor                    |
|------|-------|------|-------|-------|---|---|-------------------------------------|
| 19   | ◆     |      |       |       | SECURITY MIG P/N 89126-56800 AND P/N 89127-56800 GUSSETS (6) TO TANK ASSEMBLY | WELD INTEGRITY, WELD SPLASH, OFF LOCATION | WELDER SCHEDULE PROPERLY MAINTAINED |
| 20   | ◆     |      |       |       | ATTACH P/N 30018726 (FUEL PUMP) TO TANK UPPER - 6 30003198 SCREWS             | TORQUE                                    | TORQUE MAINTENANCE GUN              |
| 21   | ◆     |      |       |       | ATTACH P/N 30017817 (SENDING UNIT) TO TANK UPPER - 5 30003198 SCREWS          | TORQUE                                    | TORQUE MAINTENANCE GUN              |
| 22   | ◆     |      |       |       | ATTACH P/N 30014579 (CUT VALVE) TO TANK UPPER - 3 30003198 SCREWS             | TORQUE                                    | TORQUE MAINTENANCE GUN              |
| 23   | ◆     |      |       |       | INSERT "O" RING AND ATTACH P-SENSOR COVER PLATE                               | MISSING COMPONENT                         | OPERATOR KNOWLEDGE                  |
| 24   | ◆     |      |       |       | INSTALL PROPER MASKING DEVICES AND LEAK TEST                                  | MISSING COMPONENTS                        | OPERATOR KNOWLEDGE                  |
| 25   | ○     |      |       |       | PLACE TANK ON CONVEYOR TO PAINT LINE  | DENTS                                     | OPERATOR HANDLING                   |
| 26   | ○     |      |       |       | HANG TANK ON PAINT LINE   | NONE                                      | NONE                                |
| 27   | ◆     |      |       |       | PAINT   | PAINT THICKNESS                           | PAINT LINE MAINTENANCE              |

AS 279979

CORPORATE QUALITY MANAGER: *AS 279979* 7/4/96  
 CORPORATE ENGINEERS: *AS 279979*  
 PLANT MANAGER: *AS 279979*  
 QUALITY MANAGER: *AS 279979* 6-28-96  
 Prepared By : M. MINOS  
 Page 3 of 4

7-3-C page 4/4

**The Narmco Group - Process Flow Diagram ACCEPTANCE CRITERIA ZERO DEFECTS**

\* ALL REPAIRS & REMORK SHALL BE REINSPECTED AS PER QUALITY PLAN

- Circle - Move ( all steps in the system where the object under study moves from one location to another).
- Triangle - Store ( all steps in the system where the object under study remains at rest, either temporarily or permanently).
- Diamond - Fabrication ( all steps in the system where the object undergoes a change in form, condition or content).
- Square - Inspection ( all steps in the system where the object under study is checked for completeness, quality or quantity).



Plant : PRINCE METAL PRODUCTS LTD.

Part Name : TRUCK FUEL TANK ASSEMBLY

Part Number : 30019612 (89019-57863)

B/P Date : CAMI E.C.N.

Level : 56B-2445

Customer : CAMI AUTOMOTIVE

Date Submitted : JUNE 20, 1996

REVISION LEVEL: "2" NEW GUSSET P/N 30019611

| Step | Fabr. | Move | Store | Insp. | Operation Description               | Affected Control Char.                 | Variation Factor   |
|------|-------|------|-------|-------|-------------------------------------|--|--------------------|
| 28   |       |      |       |       | REMOVE FROM PAINT LINE              |  |                    |
| 29   |       |      |       |       | TOP DRESS ASSEMBLY AND RE-LEAK TEST |  |                    |
| 30   |       |      |       |       | INSPECT AND PACK                    |  |                    |
| 31   |       |      |       |       | MOVE TO SHIPPING DOCK               |  |                    |
| 32   |       |      |       |       | SHIP TO CAMI                        |  |                    |
|      |       |      |       |       |                                     | INCORRECT ASSEMBLY, MISSING COMPONENTS | OPERATOR KNOWLEDGE |








AS 279980

CORPORATE QUALITY MANAGER: *Bill McNeil* 86-7-4  
 CORPORATE ENGINEERING: *Bill McNeil* 7/4/96  
 PLANT MANAGER: *S. J. Fleming*  
 QUALITY MANAGER: *Off. Taggart* 6-28-96  
 Prepared By : M.-MINDS  
 Page 4 of 4



**Ⓐ PART**






**CIS PART INSPECTION STANDARD (A)**

| PART NUMBER            |  | PART NAME   |  | DATE:   | PROPOSED BY:          | CHECKED BY:            | APPROVED BY:          | DUNS NUMBER |
|------------------------|--|---|--|---|-----------------------|------------------------|-----------------------|-------------|
| 30014813 (89019-57830) |  | TANK SET, FUEL  |  | 03/08/94                                      | GORO TAGGART          | J. Taggart 3/15/94     | S. Amey               | 247650542   |
| NO.                    |  | INSPECTION CHARACTERISTICS  | CRITERIA   | INSPECTION METHOD                             | INSPECTION DIVISION   | QUANTITY AND FREQUENCY | SUPPLIER NAME         |             |
| 1A                     | PROJECTION WELD P/N 89124-85350 TO UPPER HALF OF TANK (6 PLACES)                       |    | 1. EACH PROJECTION MUST PULL PARENT MATERIAL<br>2. PLATE MUST NOT COME LOOSE | 1. HAMMER AND CHISEL DESTRUCTION<br>2. PRY    | AREA MANAGER/OPERATOR | 2/SHIFT                | PRINCE METAL PRODUCTS |             |
| 1B                     | PROJECTION WELD P/N 85121-67010 TO UPPER HALF OF TANK (5 PLACES)                       |    | 1. EACH PROJECTION MUST PULL PARENT MATERIAL<br>2. PLATE MUST NOT COME LOOSE | 1. HAMMER AND CHISEL DESTRUCTION<br>2. PRY    | AREA MANAGER/OPERATOR | 2/SHIFT                | PRINCE METAL PRODUCTS |             |
| 1C                     | SPOT WELD P/N 89187-60400 TO UPPER HALF OF TANK (3 PLACES)                             |    | 1. MUST PULL PARENT MATERIAL<br>2. PART MUST NOT COME LOOSE                  | 1. HAMMER AND CHISEL DESTRUCTION<br>2. PRY    | AREA MANAGER/OPERATOR | 2/SHIFT                | PRINCE METAL PRODUCTS |             |
| 1D                     | SPOT WELD P/N 89130-56801 TO UPPER HALF OF TANK (2 PLACES)                             |    | 1. MUST PULL PARENT MATERIAL<br>2. PART MUST NOT COME LOOSE                  | 1. HAMMER AND CHISEL DESTRUCTION<br>2. PRY    | AREA MANAGER/OPERATOR | 2/SHIFT                | PRINCE METAL PRODUCTS |             |
| 2                      | RAZE P/N 89130-56801 AND P/N 89143-60400 TO UPPER HALF OF TANK                         |   | 1. MUST NOT LEAK<br>2. MUST EXHIBIT CAPILLARY ATTRACTION                     | 1. LEAK TESTER<br>2. CUT, MOUNT, POLISH, ETCH | AREA MANAGER/OPERATOR | 100Z                   | PRINCE METAL PRODUCTS |             |
| 3A                     | SPOT WELD (3) P/N 09405-65302 (30003200) TO UPPER HALF OF TANK (1 SPOT WELD PER CLAMP) |  | 1. MUST PULL PARENT MATERIAL<br>2. PART MUST NOT COME LOOSE                  | 1. HAMMER AND CHISEL DESTRUCTION<br>2. PRY    | AREA MANAGER/OPERATOR | 2/SHIFT                | PRINCE METAL PRODUCTS |             |
| 3B                     | SPOT WELD (1) P/N 09405-65302 (30001095) TO UPPER HALF OF TANK (1 SPOT)                |  | 1. MUST PULL PARENT MATERIAL<br>2. PART MUST NOT COME LOOSE                  | 1. HAMMER AND CHISEL DESTRUCTION<br>2. PRY    | AREA MANAGER/OPERATOR | 2/SHIFT                | PRINCE METAL PRODUCTS |             |
| REASONS FOR REVISION   |  | AUTHORITY   |  | DATE  | CHECKED BY:           | APPROVED BY:           | CAMI B.C.             |             |
|                        |  |   |  |   | my L to 03.22.94      | 3/15/94                |                       |             |

PART NAME: TANK SET

AS 279981

PAGE :

| CIS PART INSPECTION STANDARD (A)      |  |  |   | DATE:                                   | PROPOSED BY:                  | CHECKED BY:                            | APPROVED BY:             |
|---------------------------------------|--|--|---|---|-------------------------------|--|--------------------------|
| PART NUMBER<br>30014813 (89019-57830) |  | PART NAME<br>TANK SET, FUEL  |   | 03/08/94                                | 60RD TAGGART                  | <i>S. Taggart 3/15/94</i>              | <i>[Signature]</i>       |
| INSPECTION CHARACTERISTICS            |  | CRITERIA   |   | MODEL<br>4 DOOR TRUCK                   | ENG CHANGE NUMBER<br>Y19-1315 | SUPPLIER NAME<br>PRINCE METAL PRODUCTS | BUNS NUMBER<br>247650542 |
| NO.                                   | INSPECTION CHARACTERISTICS   | CRITERIA   | INSPECTION METHOD                                       | INSPECTION DIVISION                     | QUANTITY AND FREQUENCY        |  |                          |
| 3C                                    | SPOT WELD P/N 89190-56800 TO UPPER HALF OF TANK (6 PLACES)<br>                        | 1. MUST PULL PARENT MATERIAL<br>2. PART MUST NOT COME LOOSE  | 1. HAMMER AND CHISEL DESTRUCTION<br>2. PRY              | AREA MANAGER/OPERATOR                   | 2/SHIFT                       |  |                          |
| 3D                                    | SPOT WELD P/N 89171-82000 TO UPPER HALF OF TANK (1 PLACE)<br><br>*LOCATION IMPORTANT  | 1. MUST PULL PARENT MATERIAL<br>2. PART MUST NOT COME LOOSE<br>3. DOT SAME SIDE AS FILLER HOLE   | 1. HAMMER AND CHISEL DESTRUCTION<br>2. PRY<br>3. VISUAL | AREA MANAGER/OPERATOR                   | 100Z<br>2/SHIFT               |  |                          |
| 3E                                    | SPOT WELD P/N 89170-60000 TO UPPER HALF OF TANK (2 PLACES)<br><br>*LOCATION IMPORTANT | 1. MUST PULL PARENT MATERIAL<br>2. PART MUST NOT COME LOOSE<br>3. BEND IN PART FITS GROOVE IN WELD FITTURE AND STRAIGHT FLANGE TOWARDS FUEL INLET HOLE | 1. HAMMER AND CHISEL DESTRUCTION<br>2. PRY<br>3. VISUAL | AREA MANAGER/OPERATOR                   | 2/SHIFT<br>100Z<br>100Z       |  |                          |
| 4                                     | SPOT WELD P/N 89170-56800 TO LOWER HALF OF TANK (6 PLACES)<br>                       | 1. MUST PULL PARENT MATERIAL<br>2. PART MUST NOT COME LOOSE  | 1. HAMMER AND CHISEL DESTRUCTION<br>2. PRY              | AREA MANAGER/OPERATOR                   | 2/SHIFT<br>100Z               |  |                          |
| 5A                                    | RIG WELD P/N 89171-82000 360 DEGREES TO UPPER HALF OF TANK<br>                      | 1. MUST NOT LEAK<br>2. 10% PENETRATION   | 1. LEAK TESTER<br>2. CUT, ROUND, POLISH, ETCH           | AREA MANAGER/OPERATOR<br>P.M.P. QUALITY | 100Z<br>1/WEEK                |  |                          |
| 5B                                    | SPOT WELD UPPER AND LOWER HALVES TOGETHER (4 PLACES)(HOLD IN PLACE FOR SEAM WELD)  | MUST PULL PARENT MATERIAL  | HAMMER AND CHISEL DESTRUCTION                           | AREA MANAGER/OPERATOR                   | 2/SHIFT                       |  |                          |
| REASONS FOR REVISION                  |  |  |   | AUTHORITY                               | DATE                          | CHECKED BY:                            | APPROVED BY:             |
|                                       |  |  |   |   |                               |  | <b>CAMI Q.C.</b>         |
|                                       |  |  |   |   |                               |  |                          |
|                                       |  |  |   |   |                               |  |                          |

AS 279982

FILE NO. C12A



7-4-A page 4/6

| CIS PART INSPECTION STANDARD (A)      |   | DATE:  | PROPOSED BY:                       | CHECKED BY:                            | APPROVED BY:                                    |
|---------------------------------------|---|--|------------------------------------|--|---|
| PART NUMBER<br>30014813 (89019-57830) |   | 03/08/94   | GORD TAGSART                       | <i>J. Taggart 3/15/94</i>              | <i>[Signature]</i>                              |
| PART NAME<br>TANK SET, FUEL           |   | MODEL<br>4 DOOR TRUCK  | ENG CHANGE NUMBER<br>Y19-1315      | SUPPLIER NAME<br>PRINCE METAL PRODUCTS | DUNS NUMBER<br>247650542                        |
| NO.                                   | INSPECTION CHARACTERISTICS  | CRITERIA   | INSPECTION METHOD                  | INSPECTION DIVISION                    | QUANTITY AND FREQUENCY                          |
| 9A                                    | ATTACH P/N 30014770 FUEL PUMP ASSY TO TANK ASSY USING (5) P/N 09136-05045 (300003198) | 1. TORQUE 10-15 KG.CM<br>2. MUST NOT LEAK  | 1. TORQUE WRENCH<br>2. LEAK TESTER | PHP QUALITY<br>AREA MANAGER/OPERATOR   | TORQUE VERIFICATION ONCE/VEEK<br>LEAK TEST 100% |
| 9B                                    | ATTACH SENDING UNIT P/N 30000151 TO TANK ASSY USING (5) P/N 09136-05045 (300003198)   | 1. TORQUE 10-15 KG.CM<br>2. MUST NOT LEAK  | 1. TORQUE WRENCH<br>2. LEAK TESTER | PHP QUALITY<br>AREA MANAGER/OPERATOR   | ONCE/VEEK<br>LEAK TEST 100%                     |
| 9C                                    | INSTALL PROPER MASKING DEVICES (HOSES AND CAPS)                                       | MUST BE PRESENT  | VISUAL                             | AREA MANAGER/OPERATOR                  | 100%  |
| 10A                                   | LEAK TEST   | 0.65 KG/CM FOR 30 SECONDS<br>NO BUBBLES ALLOWED  | VISUAL                             | AREA MANAGER/OPERATOR                  | 100%  |
| 10B                                   | MARK WHITE LINE INSIDE FILLER TUBE TO SIGNIFY TANK PASSED LEAK TEST                   | WHITE LINE MUST BE PRESENT   | VISUAL                             | AREA MANAGER/OPERATOR                  | 100%  |
| 10C                                   | MUST PUNCTURE BLACK PUMP CAP  | MUST BE THROUGH  | VISUAL                             | AREA MANAGER/OPERATOR                  | 100%  |
| 11                                    | WANG TANK ON PAINT LINE AND PREPARE WIRES PROPERLY FOR PAINTING                       | WIRES MUST BE INSTALLED IN MASKING DEVICES PROPERLY  | VISUAL                             | AREA MANAGER/OPERATOR                  | 100%  |
| 12                                    | 6 STAGE WASHER<br>CONCENTRATION/TEMPERATURE   | STAGE 1 CONC - .1-.3 ML/60°F<br>2 CONC - 17-22 ML/120-140°F<br>3 CONC - .1-.3 ML/60°F<br>4 CONC - .1-.3 ML/AMBIENT<br>5 CONC - .1 MAX ML/AMBIENT<br>6 CONC - .1 MAX ML/AMBIENT | SEE PROCEDURE SHEET                | LAB                                    | 1/SHIFT   |
| REASONS FOR REVISION                  |   | AUTHORITY  | DATE                               | CHECKED BY:                            | APPROVED BY:                                    |
|                                       |   |  |                                    | <i>[Signature]</i>                     | <i>[Signature]</i>                              |

CAMI Q.C.

FILE NAME: 813-C144



AS 279984

7-4-A page 5/6

**JIS PART INSPECTION STANDARD (A)**

| PART NUMBER            |  | PART NAME   |                          | DATE:                | PROPOSED BY:          | CHECKED BY:              | APPROVED BY:       |
|------------------------|--|---|--------------------------|----------------------|-----------------------|--------------------------|--------------------|
| 30014913 (09019-57830) |  | TANK SET, FUEL  |                          | 03/08/94             | GD0 TAGSART           | <i>J. Taggart 3/5/94</i> | <i>[Signature]</i> |
| NO.                    |  | INSPECTION CHARACTERISTICS                            | CRITERIA                 | INSPECTION METHOD    | INSPECTION DIVISION   | QUANTITY AND FREQUENCY   | DUNS NUMBER        |
| 13                     |  | FINISH INSTALLING MASKING DEVICES                     | COVER NUTS AND HOLES     | VISUAL               | AREA MANAGER/OPERATOR | 100%                     | 247650542          |
| 14                     |  | FLOW RATE OF FLOW COAT CHANNEL                        | 26-30 SECONDS            | VISCOISITY CUP       | AREA MANAGER/OPERATOR | 2/SHIFT                  |                    |
| 15                     |  | NET PRIMER THICKNESS                                  | 10-12 MIL                | NET THICKNESS GAGE   | AREA MANAGER/OPERATOR | 1/SHIFT                  |                    |
| 16                     |  | REMOVE MASKING DEVICES FROM ITEM #13 BEFORE FLOW COAT | MUST BE REMOVED          | VISUAL               | AREA MANAGER/OPERATOR | 100%                     |                    |
| 17                     |  | BAKED PAINT AND PRIMER THICKNESS                      | 200 MIL MINIMUM          | PAINT THICKNESS GAGE | AREA MANAGER/OPERATOR | 1/SHIFT                  |                    |
| 18                     |  | FINISH REMOVING MASKING DEVICES                       | MUST BE REMOVED          | VISUAL               | AREA MANAGER/OPERATOR | 100%                     |                    |
| 19                     |  | WRAP WIRE HARDNESS PROPERLY                           | COMPARE TO MASTER SAMPLE | VISUAL               | AREA MANAGER/OPERATOR | 100%                     |                    |
| 20                     |  | 100% VISUAL INSPECTION                                | COMPARE TO MASTER SAMPLE | VISUAL               | AREA MANAGER/OPERATOR | 100%                     |                    |
| 21                     |  | PACKAGE OF PRODUCT AND ISSUE OF PROPER BAR CODES      | COMPARE TO PROCESS SHEET | VISUAL               | AREA MANAGER/OPERATOR | 100%                     |                    |
|                        |  | <b>PART WEIGHT 9.4 kg</b>                             |                          |                      |                       |                          |                    |
| MARKS                  |  | REASONS FOR REVISION                                  |                          | AUTHORITY            | DATE                  | CHECKED BY:              | APPROVED BY:       |
|                        |  |   |                          |                      |                       |                          | <i>[Signature]</i> |

CAMI B.C.

FILE NAME: 813-C14A


AS 279985

15 PART INSPECTION STANDARD (B)

|        |                |                    |              |                |                           |              |                    |
|--------|----------------|--------------------|--------------|----------------|---------------------------|--------------|--------------------|
| DATE:  | MARCH 12, 1994 | PROPOSED BY:       | GORD TAGGART | CHECKED BY:    | <i>J. Taggart 3/15/94</i> | APPROVED BY: | <i>[Signature]</i> |
| MODEL: | 4 DOOR TRUCK   | ENG CHANGE NUMBER: | Y19-1315     | SUPPLIER NAME: | PRINCE METAL PRODUCTS     | DUNS NUMBER: | 247650542          |

|              |                        |            |                          |
|--------------|------------------------|------------|--------------------------|
| PART NUMBER: | 30014813 (R5019-37830) | PART NAME: | TRUCK FUEL TANK ASSEMBLY |
|--------------|------------------------|------------|--------------------------|

SKETCH



SUPPLIER DATA should be supplied to CAMI on the following items - each lot  
 Items - each lot  
 Items - 1 per month  
 Items - 1 per month  
 Items - 1 per month  
 Inspection data should be reported chronologically so the movement in the process can be predicted.

|       |                      |           |      |             |              |
|-------|----------------------|-----------|------|-------------|--------------|
| INDEX | REASONS FOR REVISION | AUTHORITY | DATE | CHECKED BY: | APPROVED BY: |
|       |                      |           |      |             |              |
|       |                      |           |      |             |              |
|       |                      |           |      |             |              |

**CAMI B.C.**

7-4-A page 6/5

7-4-B 1/12

**C15 PART INSPECTION STANDARD (A)**

| PART NUMBER<br>30018268 (89019-57861) | PART NAME<br>4 DOOR TRUCK TANK FUEL ASSEMBLY   | DATE:<br>JANUARY 11, 1995  | PROPOSED BY:<br>DAA<br>60K2 TAGGART                                     | CHECKED BY:<br>1-15-96<br>G. T. ...  | APPROVED BY:<br>S. J. ...  | DUNS NUMBER<br>247650542   | INSPECTION DIVISION  |  | QUANTITY AND FREQUENCY |
|---------------------------------------|--|--|---|--|--|--|--|--|------------------------|
|                                       |  |  |   |  |  |  | ENG CHANGE NUMBER<br>Y05-1731  | SUPPLIER NAME<br>PRINCE METAL PRODUCTS   |                        |
| NO.                                   | INSPECTION CHARACTERISTICS   | CRITERIA   | INSPECTION METHOD   | RECEIVING INSPECTION   | RECEIVING INSPECTION   | RECEIVING INSPECTION   | RECEIVING INSPECTION   | RECEIVING INSPECTION   | RECEIVING INSPECTION   |
| 1                                     | RECEIVING INSPECTION<br>89111-57830 - GAS TANK UPPER BLANKS<br>(SEE 89111-57830 C15)   | STD-92   | CERTIFICATION   | RECEIVING INSPECTION   | RECEIVING INSPECTION   | RECEIVING INSPECTION   | RECEIVING INSPECTION   | EACH BUNDLE OF BLANKS  |                        |
| 2                                     | 89112-56800 - GAS TANK LOWER BLANKS<br>(SEE 89112-56800 C15)   | STD-92   | CERTIFICATION   | RECEIVING INSPECTION   | RECEIVING INSPECTION   | RECEIVING INSPECTION   | RECEIVING INSPECTION   | EACH BUNDLE OF BLANKS  |                        |
| 3                                     | 89121-82000 - INLET PIPE<br>(PURCHASED FROM SHELBY)<br>A) OUTER DIAMETER OF TUBE<br>B) OVERALL LENGTH<br>C) COATING<br>D) CHEMICAL COMPOSITION OF STEEL              | 42.7 MM +/- 0.2 MM<br>129.0 MM +/- 1.0 MM<br>NF708-C<br>STK11A   | VERMIER/CALIPER<br>SCALE<br>CERTIFICATION<br>CERTIFICATION              | RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION | RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION | RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION | RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION | PER SAMPLING PLAN Q.A.N. 24 (EACH SHIP.)<br>PER SAMPLING PLAN Q.A.N. 24 (EACH SHIP.)<br>PER SAMPLING PLAN Q.A.N. 24 (AS REQUEST.)<br>PER SAMPLING PLAN Q.A.N. 24 (AS REQUEST.) |                        |
| 4                                     | 89122-56800 - PLATE CUT VALVE<br>(PURCHASED FROM ANDTEC)<br>A) PROJECTION HEIGHTS<br>B) THREAD VERIFICATION<br>C) COATING<br>D) CHEMICAL COMPOSITION                 | 1.1 MM +0.2/-0 MM<br>3 PLACES MS<br>NF708-C<br>BASE STEEL - SPHC | MICROMETER<br>MS X 0.8 6H THREAD GAGE<br>CERTIFICATION<br>CERTIFICATION | RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION | RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION | RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION | RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION | PER SAMPLING PLAN Q.A.N. 24 (EACH SHIP.)<br>PER SAMPLING PLAN Q.A.N. 24 (EACH SHIP.)<br>PER SAMPLING PLAN Q.A.N. 24 (AS REQUEST.)<br>PER SAMPLING PLAN Q.A.N. 24 (AS REQUEST.) |                        |
| 5                                     | 89123-50700 - PLATE FUEL PUMP ATTACHMENT<br>(PURCHASED FROM KISSHO-IHAI)<br>A) PROJECTION HEIGHTS<br>B) THREAD VERIFICATION<br>C) COATING<br>D) CHEMICAL COMPOSITION | 1.1 MM +0.2/-0 MM<br>5 PLACES MS<br>NF708-C<br>BASE STEEL SPHC   | MICROMETER<br>MS X 0.8 6H THREAD GAGE<br>CERTIFICATION<br>CERTIFICATION | RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION | RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION | RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION | RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION | PER SAMPLING PLAN Q.A.N. 24 (EACH SHIP.)<br>PER SAMPLING PLAN Q.A.N. 24 (EACH SHIP.)<br>PER SAMPLING PLAN Q.A.N. 24 (AS REQUEST.)<br>PER SAMPLING PLAN Q.A.N. 24 (AS REQUEST.) |                        |
| 6                                     | 89124-51700 - PLATE FUEL PUMP ATTACHMENT<br>(PURCHASED FROM ANDTEC)<br>A) PROJECTION HEIGHTS<br>B) THREAD VERIFICATION<br>C) COATING<br>D) CHEMICAL COMPOSITION      | 1.1 MM +0.2/-0 MM<br>6 PLACES MS<br>NF708-C<br>BASE STEEL SPHC   | MICROMETER<br>MS X 0.8 6H THREAD GAGE<br>CERTIFICATION<br>CERTIFICATION | RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION | RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION | RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION | RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION | PER SAMPLING PLAN Q.A.N. 24 (EACH SHIP.)<br>PER SAMPLING PLAN Q.A.N. 24 (EACH SHIP.)<br>PER SAMPLING PLAN Q.A.N. 24 (AS REQUEST.)<br>PER SAMPLING PLAN Q.A.N. 24 (AS REQUEST.) |                        |

**(A) PART**

REASONS FOR REVISION

AUTHORITY

DATE

CHECKED BY:  
7-15-96  
S. J. ...  
1/13/96

APPROVED BY:  
S. J. ...  
1/13/96

CAMI B.C.





7-4-B 3/12

| CIS PART INSPECTION STANDARD (A) |  |  |                                       |                      |  |                                       |  |  |   |                        |
|----------------------------------|--|--|---------------------------------------|----------------------|--|---------------------------------------|--|--|---|------------------------|
| PART NUMBER                      | PART NAME  | DATE:  | PROPOSED BY:                          | CHECKED BY:          | APPROVED BY:   | DUNS NUMBER                           | INSPECTION DIVISION  |  |   | QUANTITY AND FREQUENCY |
|                                  |  |  |                                       |                      |  |                                       | ENG CHANGE NUMBER  | SUPPLIER NAME  | PRINCE METAL PRODUCTS   |                        |
| NO.                              | INSPECTION CHARACTERISTICS   | CRITERIA   | INSPECTION METHOD                     | MODEL                | INSPECTION DIVISION  | INSPECTION METHOD                     | INSPECTION DIVISION  | INSPECTION METHOD  | INSPECTION DIVISION   |                        |
| 3001B268                         | (B9019-S7861)  | 4 DOOR TRUCK TANK FUEL ASSEMBLY  | JANUARY 12, 1996                      | GORD TAGGART         | DAVID  | 247650542                             | Y09-1731   | PRINCE METAL PRODUCTS  | PRINCE METAL PRODUCTS   |                        |
| 15                               | RECEIVING INSPECTION CONTINUED<br>89176-61A00 - BRACKET<br>(SEE 89176-61A00 CIS)   | ZLC-20/20  | CERTIFICATION                         | 4 DOOR 56 MODEL YEAR | RECEIVING INSPECTION   | CERTIFICATION                         | RECEIVING INSPECTION   | RECEIVING INSPECTION   | EACH COIL   |                        |
| 16                               | 89177-61A00 - BRACKET<br>(SEE 89177-61A00 CIS)   | ZLC-20/20  | CERTIFICATION                         |                      | RECEIVING INSPECTION   | CERTIFICATION                         | RECEIVING INSPECTION   | RECEIVING INSPECTION   | EACH COIL   |                        |
| 17                               | 89178-60A00 - VAPOUR SEP BRKT ASSY PLATED<br>(SEE 89178-60A00 CIS)<br>COATING PERFORMED BY KLINEC  | SPCC-NS<br>M72B-C  | CERTIFICATION<br>CERTIFICATION        |                      | RECEIVING INSPECTION<br>RECEIVING INSPECTION                         | CERTIFICATION<br>CERTIFICATION        | RECEIVING INSPECTION<br>RECEIVING INSPECTION                         | RECEIVING INSPECTION<br>RECEIVING INSPECTION                         | EACH COIL<br>EACH LOT   |                        |
| 18                               | 09105-43303 (30001095)<br>PURCHASED FROM HARNWOOD<br>* PART NOT AS SHOWN ON PART PRINT<br>A) MATERIAL THICKNESS<br>B) BLACK COATING<br>C) CHEMICAL COMPOSITION                     | 0.7 MM +/- 0.04 MM<br>MUST BE PRESENT AND 15.0 TO<br>18.0 MM FROM EDGE OF PART<br>SPCC | MICROMETER<br>VISUAL<br>CERTIFICATION |                      | RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION | MICROMETER<br>VISUAL<br>CERTIFICATION | RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION | RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION | PER SAMPLING PLAN Q.A.N. 24 (AS REQUEST.)<br>PER SAMPLING PLAN Q.A.N. 24 (EACH SHIP.)<br>PER SAMPLING PLAN Q.A.N. 24 (AS REQUEST.)  |                        |
| 19                               | 09405-63303 (30003200) - CLAMP FUEL TANK<br>(PURCHASED FROM HARNWOOD)<br>* PART NOT AS SHOWN ON PART PRINT<br>A) MATERIAL THICKNESS<br>B) BLACK COATING<br>C) CHEMICAL COMPOSITION | 0.7 MM +/- 0.04 MM<br>MUST BE PRESENT AND 15.0 TO<br>18.0 MM FROM EDGE OF PART<br>SPCC | MICROMETER<br>VISUAL<br>CERTIFICATION |                      | RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION | MICROMETER<br>VISUAL<br>CERTIFICATION | RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION | RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION | PER SAMPLING PLAN Q.A.N. 24 (AS REQUEST.)<br>PER SAMPLING PLAN Q.A.N. 24 (AS REQUEST.)<br>PER SAMPLING PLAN Q.A.N. 24 (AS REQUEST.) |                        |
| 20                               | 09405-56000 (30014579) - CUT VALVE<br>(PURCHASED FROM NISSHO IMAT)<br>* PART APPROVED SOURCE   | PART CERTIFICATION FOR ALL<br>TESTS, DIMENSIONS AND MATERIALS                          | CERTIFICATION                         |                      | RECEIVING INSPECTION   | CERTIFICATION                         | RECEIVING INSPECTION   | RECEIVING INSPECTION   | AS REQUESTED  |                        |
| 21                               | 34810-70E10 (30017817) GAUGE ASSY FUEL LEVEL<br>(PURCHASED FROM NISSHO IMAT)<br>* PART APPROVED SOURCE   | PART CERTIFICATION FOR ALL<br>TESTS, DIMENSIONS AND MATERIALS                          | CERTIFICATION                         |                      | RECEIVING INSPECTION   | CERTIFICATION                         | RECEIVING INSPECTION   | RECEIVING INSPECTION   | AS REQUESTED  |                        |
| 22                               | 15100-58B00 (30014333) - PUMP ASSY FUEL<br>(PURCHASED FROM AUTRAMS - CONSIGNMENT)<br>* PART APPROVED SOURCE  | PART CERTIFICATION FOR ALL<br>TESTS, DIMENSIONS AND MATERIALS                          | CERTIFICATION                         |                      | RECEIVING INSPECTION   | CERTIFICATION                         | RECEIVING INSPECTION   | RECEIVING INSPECTION   | AS REQUESTED  |                        |

CHECKED BY: *[Signature]*  
 APPROVED BY: *[Signature]*  
 CAMI B.C.

| MARKS | REASONS FOR REVISION | AUTHORITY | DATE | CHECKED BY: | APPROVED BY: |
|-------|----------------------|-----------|------|-------------|--------------|
|       |                      |           |      |             |              |
|       |                      |           |      |             |              |
|       |                      |           |      |             |              |



AS 279989

CIS PART INSPECTION STANDARD (A)

PROPOSED BY: *PAH*  
 CHECKED BY: *B. Talbani*  
 APPROVED BY: *[Signature]*

DATE: JANUARY 12, 1996  
 6000 TAGGART  
 ENG CHANGE NUMBER: Y09-1731  
 SUPPLIER NAME: PRINCE METAL PRODUCTS  
 DUNS NUMBER: 247650542

PART NUMBER: 30018268 (89019-57861)  
 PART NAME: 4 DOOR TRUCK TANK FUEL ASSEMBLY  
 MODEL: 4 DOOR 96 MODEL YEAR  
 INSPECTION METHOD: INSPECTION DIVISION: QUANTITY AND FREQUENCY

| NO. | INSPECTION CHARACTERISTICS   | CRITERIA  | INSPECTION METHOD  | INSPECTION DIVISION  | QUANTITY AND FREQUENCY   |
|-----|--|---|--|--|--|
| 11  | RECEIVING INSPECTION CONTINUED   |   |  |  |  |
| 23  | 09136-05045 (30003198)-SCREEN FUEL LEVEL GAUGE<br>A) THREAD VERIFICATION<br>B) COATING<br>C) CHEMICAL COMPOSITION<br>D) HEAD HEIGHT<br>E) THREAD AND RECESSED LENGTH   | MS 1 0.8<br>MFC70<br>CH12C<br>3.3 MM +/- 0.15 MM<br>10.0 MM +/- 0.8 MM  | THREADED RING GAGE<br>CERTIFICATION<br>CERTIFICATION<br>VERNIER<br>VERNIER | RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION | PER SAMPLING PLAN Q.A.M. 24 (AS REQUEST.)<br>PER SAMPLING PLAN Q.A.M. 24 (AS REQUEST.)<br>PER SAMPLING PLAN Q.A.M. 24 (AS REQUEST.)<br>PER SAMPLING PLAN Q.A.M. 24 (AS REQUEST.)<br>PER SAMPLING PLAN Q.A.M. 24 (AS REQUEST.)  |
| 24  | RECEIVING INSPECTION TOP DRESS<br>CUSTOMER SUPPLIED MATERIAL<br>A. 30014576 (89411-56800)<br>B. 30014635 (89356-55117-410)<br>C. 30015397 (89356-55113-21010)<br>D. 30016308 (89280-50F00)<br>E. 30018909 (89421-78E40)<br>F. 30016310 (89425-79E00)<br>G. 96057808 (89401-11412)<br>H. 96061880 (89401-11413)<br>I. 30015634 (09402-15.511) | 1. NO VISUAL DEFECTS OR DIRT<br>2. VERIFY QUANTITY<br>3. P/P LOT NUMBER<br>4. OUTSTANDING ORDER # BY BUYER'S DIE DATE<br>5. AFFIX CSR STICKER TO EACH PALLET OF MATERIAL RECEIVED | VISUAL<br>VISUAL<br>ASSIGNED<br>VISUAL<br>VISUAL                           | RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION | PER SAMPLING PLAN Q.A.M. 24 (AS REQUEST.)<br>PER SAMPLING PLAN Q.A.M. 24 (AS REQUEST.)<br>PER SAMPLING PLAN Q.A.M. 24 (AS REQUEST.)<br>PER SAMPLING PLAN Q.A.M. 24 (AS REQUEST.)<br>PER SAMPLING PLAN Q.A.M. 24 (AS REQUEST.)<br>PER SAMPLING PLAN Q.A.M. 24 (AS REQUEST.) |
| 25  | 30000023 - (02142-05083)<br>THREAD VERIFICATION<br>VERIFY QTY<br>IMPRESS INSPECTION  | MS 1 0.8 MM<br>AS INDICATED   | RING GAGE<br>VISUAL  | RECEIVING INSPECTION<br>" " " "  | PER SAMPLING PLAN Q.A.M. 24 (AS REQUEST.)<br>" " " "   |
| 1   | PROJECTION WELD (2) P/N 08315-01059 WELD<br>WTS 5 NR TO P/N 89178-60000 BRACKET  | MUST PULL PARENT MATERIAL<br>NO WELD SPLASH ALLOWED   | PUSH OUT TEST  | AREA MANAGER / OPERATOR  | 2/SHIFT DESTRUCT TEST AND<br>100% PRY TOOL CHECK   |
| 2   | SPOT WELD P/N 89176-61400 & 89177-61400<br>WTS TO P/N 89171-61400 OTR VESSEL (6 SPOTS)   | MUST PULL PARENT MATERIAL   | HAMMER AND CHISEL  | AREA MANAGER / OPERATOR  | 2/SHIFT DESTRUCT TEST AND<br>100% PRY TOOL CHECK   |
| 3   | SPOT WELD P/N 89172-56800 INNER VESSEL TO<br>P/N 89171-61400 OUTER VESSEL 6 SPOTS  | MUST PULL PARENT MATERIAL   | HAMMER AND CHISEL  | AREA MANAGER / OPERATOR  | 2/SHIFT DESTRUCT TEST AND<br>100% PRY TOOL CHECK   |

7-4-B 4/12

MARKS

REASONS FOR REVISION

A PART

AUTHORITY

DATE

CHECKED BY: [Signature]

APPROVED BY: [Signature]

CAMI Q.C.

AS 279990



7-4-B 6/12

CIS PART INSPECTION STANDARD (A)

| NO.                        | PART NUMBER<br>30018268 (89019-57861)   | PART NAME<br>4 DOOR TRUCK TANK FUEL ASSEMBLY   | DATE:<br>JANUARY 12, 1996  | PROPOSED BY:<br>DMM<br>GORD TAGGART  | CHECKED BY:<br><i>C. McCall</i> | APPROVED BY:<br><i>S. J. [Signature]</i> | DUNS NUMBER<br>247650542 | INSPECTION DIVISION           |  | QUANTITY AND FREQUENCY |
|----------------------------|---|--|--|--|---------------------------------|--|--------------------------|-------------------------------|--|------------------------|
|                            |   |  |  |  |                                 |  |                          | ENG CHANGE NUMBER<br>Y09-1731 | SUPPLIER NAME<br>PRINCE METAL PRODUCTS |                        |
| INSPECTION CHARACTERISTICS |   | CRITERIA   | INSPECTION METHOD  | INSPECTION DIVISION  |                                 | QUANTITY AND FREQUENCY                   |                          |                               |  |                        |
| 11                         | INPROCESS INSPECTION CONTINUED<br>SPOT WELD *1* P/N 89405-45303 (30001095)<br>CLIP TO P/N 89111-57830             | 1. SPOT WELD MUST PULL PARENT MATERIAL<br>2. MUST NOT COME LOOSE   | 1. HAMMER AND CHISEL<br>2. PRY   | AREA MANAGER/OPERATOR  |                                 | 2/SHIFT<br>100Z                          |                          |                               |  |                        |
| 12                         | SPOT WELD P/N 89178-60800 TO P/N 89111-57830<br>(2 PLACES)<br>** LOCATION IMPORTANT **                            | 1. EACH SPOT WELD MUST PULL PARENT MATERIAL<br>2. PART MUST NOT COME LOOSE<br>3. STRAIGHT FLANGE ON BRKT TOWARDS FUEL INLET HOLE<br>4. 2-5 MM NUTS MUST BE PRESENT | 1. HAMMER AND CHISEL<br>2. PRY   | AREA MANAGER/OPERATOR  |                                 | 2/SHIFT<br>100Z<br>100Z<br>100Z          |                          |                               |  |                        |
| 13                         | SPOT WELD P/N 89170-56800 TO P/N 89112-56800<br>(6 PLACES)  | 1. EACH SPOT WELD MUST PULL PARENT MATERIAL<br>2. PART MUST NOT COME LOOSE   | 1. HAMMER AND CHISEL<br>2. PRY   | AREA MANAGER/OPERATOR  |                                 | 2/SHIFT<br>100Z                          |                          |                               |  |                        |
| 14                         | SPOT WELD P/N 89111-57830 TO P/N 89112-56800<br>(4 PLACES)  | 1. EACH SPOT WELD MUST PULL PARENT MATERIAL  | 1. HAMMER AND CHISEL   | AREA MANAGER/OPERATOR  |                                 | 2/SHIFT                                  |                          |                               |  |                        |
| 15                         | SEAM WELD P/N 89111-57830 TO P/N 89112-56800  | 1. MUST NOT LEAK<br>2. MUST NOT SEPARATE<br>3. MUST NOT BREAK AT WELD<br>4. SEAM WELD MUST PASS AS CLOSE AS POSSIBLE TO TANK BUT MUST NOT PASS CORNER RADI         | 1. LEAK TESTER<br>2. HAMMER AND CHISEL<br>3. TENSILE TESTER<br>4. VISUAL | AREA MANAGER/OPERATOR<br>AREA MANAGER/OPERATOR<br>AREA MANAGER/OPERATOR<br>AREA MANAGER/OPERATOR |                                 | 100Z<br>EVERY 75 PARTS<br>1/WEEK<br>100Z |                          |                               |  |                        |
| 16                         | STAMP LOT TRACEABILITY ON P/N 89125-60800 AS SHOWN BELOW<br><br>227 5 108<br>L TANK NUMBER<br>YEAR<br>JULIAN DATE | 1. MUST BE PRESENT AND LEGIBLE   | 1. VISUAL  | AREA MANAGER/OPERATOR  |                                 | 100Z                                     |                          |                               |  |                        |

|  |  |           |  |      |  |             |  |              |  |
|--|--|-----------|--|------|--|-------------|--|--------------|--|
| REASONS FOR REVISION   |  | AUTHORITY |  | DATE |  | CHECKED BY: |  | APPROVED BY: |  |
| <div style="border: 2px solid black; padding: 10px; display: inline-block;"> <p style="font-size: 2em; margin: 0;">A PART</p> </div> |  |           |  |      |  |             |  |              |  |
|  |  |           |  |      |  |             |  |              |  |

AS 279992

7-4-B 7/12

| CIS PART INSPECTION STANDARD (A)      |  |  |   |   |                        |               |              |              |           |
|---------------------------------------|--|--|---|---|------------------------|---------------|--------------|--------------|-----------|
| PART NUMBER<br>30018268 (89019-57861) | PART NAME<br>4 DOOR TRUCK TANK FUEL ASSEMBLY   | DATE:  |   | PROPOSED BY:  |                        | CHECKED BY:   |              | APPROVED BY: |           |
|                                       |  | MODEL  | 4 DOOR 96 MODEL YEAR                          | ENG CHANGE NUMBER   | 6092 TAGGART           | SUPPLIER NAME | G. TAGGART   | DUNS NUMBER  | 247650542 |
| NO.                                   | INSPECTION CHARACTERISTICS   | CRITERIA   | INSPECTION METHOD                             | INSPECTION DIVISION   | QUANTITY AND FREQUENCY |               |              |              |           |
| 17                                    | IMPROCESS INSPECTION CONTINUED<br>SPOT WELD *2" P/N 89125-60400 (2 PLACES EACH) TO TANK ASSEMBLY.<br>SPOT WELD P/N 89126-56800 (2 PLACES) TO TANK ASSEMBLY<br>SPOT WELD P/N 89127-56800 (2 PLACES) TO TANK ASSEMBLY  | 1. MUST NOT COME LOOSE<br>1. PNY   | 1. PNY  | AREA MANAGER/OPERATOR   | 100Z                   |               |              |              |           |
| 18                                    | MIG WELD P/N 89121-82000 TO TANK UPPER ASSEMBLY  | 1. MUST NOT LEAK<br>2. 10% PENETRATION   | 1. LEAK TESTER<br>2. CUT, MOUNT, POLISH, ETCH | AREA MANAGER/OPERATOR   | 100Z                   |               |              |              |           |
| 19                                    | MIG FOR SECURITY P/N 89126-56800 AND P/N 89127-56800 TO TANK ASSEMBLY (3 PLACES EACH COMPONENT)  | 1. MUST BE PRESENT AND VISUALLY ACCEPTABLE   | 1. VISUAL                                     | Q.C. LAB LAYOUT   | 1/100Z                 |               |              |              |           |
| 20                                    | ATTACH P/N 15100-58800 (300043233) TO TANK ASSEMBLY USING (6) SCREWS P/N 09136-05045 (30003198)  | 1. TORQUE - 10-15 Kg.cm<br>2. MUST NOT LEAK  | 1. TORQUE WRENCH<br>2. LEAK TESTER            | Q.C. LAB LAYOUT<br>AREA MANAGER/OPERATOR                                | 1/100Z                 |               |              |              |           |
| 21                                    | ATTACH P/N 34810-70E10 (20017817) TO TANK ASSEMBLY USING 5 SCREWS P/N 09136-05045 (30003198)   | 1. TORQUE 10-15 Kg.cm<br>2. MUST NOT LEAK  | 1. TORQUE WRENCH<br>2. LEAK TESTER            | Q.C. LAB LAYOUT<br>AREA MANAGER/OPERATOR                                | 1/100Z                 |               |              |              |           |
| 22                                    | ATTACH P/N 89485-56800 (30004575) TO TANK ASSY USING (3) P/N 09136-05045 (30003198)  | 1. TORQUE 10-15 Kg.cm<br>2. MUST NOT LEAK  | 1. TORQUE WRENCH<br>2. LEAK TESTER            | Q.C. LAB LAYOUT<br>AREA MANAGER/OPERATOR                                | 1/100Z                 |               |              |              |           |
| 23                                    | INSTALL PROPER MASKING DEVICES<br>1. YELLOW CAP ON P/N 89130-57820<br>2. REMOVE SMALL BLACK CAP FROM P/N 30014323 AND PUT ON P/N 30014575<br>3. PLACE *0" RING P/N 30016310 IN SLOTTED GROOVE OF P-SENSOR RING P/N 89129-66800 AND SEAL WITH P-SENSOR PLATE MADE FOR MASKING (2) SCREWS 30003198 | MUST BE PRESENT<br>MUST BE PRESENT<br>MUST BE PRESENT & WATER MUST NOT ENTER TANK ASSY | VISUAL<br>VISUAL<br>VISUAL                    | AREA MANAGER/OPERATOR<br>AREA MANAGER/OPERATOR<br>AREA MANAGER/OPERATOR | 100Z<br>100Z<br>100Z   |               |              |              |           |
| REASONS FOR REVISOR                   |  |  |   |   | AUTHORITY              |               | CAMI Q.C.    |              |           |
| MARKS                                 |  |  |   |   | DATE                   |               | CHECKED BY:  |              |           |
|                                       |  |  |   |   |                        |               | APPROVED BY: |              |           |

**A PART**

AS 279993

# CIS PART INSPECTION STANDARDS

JANUARY 1991  
 ENG CHANGE NUMBER  
 Y09-1731  
 PRINCE METAL PRODUCTS  
 QUANTITY AND FREQUENCY

| NO. | PART NUMBER   | PART NAME                       | CRITERIA  | INSPECTION METHOD  | INSPECTION DIVISION  | QUANTITY AND FREQUENCY                   |
|-----|---|---------------------------------|---|--|--|--|
| 11  | 30018268<br>(85019-57861)<br>INSPECTION CHARACTERISTICS<br>IMPROCESS INSPECTION CONTINUED | 4 DOOR TRUCK TANK FUEL ASSEMBLY | 1. SPOT WELD MUST PULL PARENT MATERIAL<br>2. MUST NOT COME LOOSE  | 1. HAMMER AND CHISEL<br>2. PRY   | AREA MANAGER/OPERATOR  | 2/SHIFT<br>1001                          |
| 12  | SPOT WELD "1" P/N 09405-65303 (30001095)<br>CLIP TO P/N 89111-57830                       | 4 DOOR 98 MODEL YEAR            | 1. EACH SPOT WELD MUST PULL PARENT MATERIAL<br>2. PART MUST NOT COME LOOSE<br>3. STRAIGHT FLANGE ON BRKT TOWARDS FUEL INLET HOLE<br>4. 2-5 TOR NUTS MUST BE PRESENT | 1. HAMMER AND CHISEL<br>2. PRY<br>3. VISUAL<br>4. VISUAL                 | AREA MANAGER/OPERATOR<br>AREA MANAGER/OPERATOR<br>AREA MANAGER/OPERATOR<br>AREA MANAGER/OPERATOR | 1001<br>1001<br>1001<br>2/SHIFT          |
| 13  | SPOT WELD P/N 89170-60000 TO P/N 89112-56800<br>(6 PLACES)                                | 4 DOOR 98 MODEL YEAR            | 1. EACH SPOT WELD MUST PULL PARENT MATERIAL<br>2. PART MUST NOT COME LOOSE  | 1. HAMMER AND CHISEL<br>2. PRY   | AREA MANAGER/OPERATOR<br>AREA MANAGER/OPERATOR   | 1001<br>2/SHIFT                          |
| 14  | SPOT WELD P/N 89111-57830 TO P/N 89112-56800<br>(4 PLACES)                                | 4 DOOR 98 MODEL YEAR            | 1. EACH SPOT WELD MUST PULL PARENT MATERIAL   | 1. HAMMER AND CHISEL   | AREA MANAGER/OPERATOR<br>AREA MANAGER/OPERATOR<br>AREA MANAGER/OPERATOR                          | 1001<br>EVERY 75 PARTS<br>1/WEEK<br>1001 |
| 15  | SEAM WELD P/N 89111-57830 TO P/N 89112-56800  | 4 DOOR 98 MODEL YEAR            | 1. MUST NOT LEAK<br>2. MUST NOT SEPARATE<br>3. MUST NOT BREAK AT WELD<br>4. SEAM WELD MUST PASS AS CLOSE AS POSSIBLE TO TANK BUT MUST NOT PASS CORNER RADIUS        | 1. LEAK TESTER<br>2. HAMMER AND CHISEL<br>3. TENSILE TESTER<br>4. VISUAL | AREA MANAGER/OPERATOR  | 1001                                     |
| 16  | STAMP LOT TRACEABILITY ON P/N 89125-60000 AS SHOWN BELOW                                  | 4 DOOR 98 MODEL YEAR            | 1. MUST BE PRESENT AND LEGIBLE  | 1. VISUAL  | AREA MANAGER/OPERATOR  | 1001                                     |

AS 279992

7-4-B 6/12

7-4-B 7/12

APPROVED BY: CAMI B.C.  
 CHECKED BY: [Signature]  
 DATE: [Blank]

REASONS FOR REVISION  
**A PART**  
 APPROVED BY: [Signature]

FILE: 768-CISS



7-4-B 9/12



| PART NUMBER            |   | PART NAME   |                   | DATE:                 | PROPOSED BY:           | CHECKED BY:   | APPROVED BY: | DUNS NUMBER |
|------------------------|---|---|-------------------|-----------------------|------------------------|---------------|--------------|-------------|
| 30018268 (89019-57861) |   | 4 DOOR TRUCK TANK FUEL ASSEMBLY   |                   | JANUARY 12, 1996      | GORD TAGGART           | E. T. TAGGART | [Signature]  | 247650542   |
| NO.                    | INSPECTION CHARACTERISTICS  | CRITERIA  | INSPECTION METHOD | INSPECTION DIVISION   | QUANTITY AND FREQUENCY |               |              |             |
| 11                     | IMPROCESS INSPECTION CONTINUED  |   |                   |                       |                        |               |              |             |
| 33                     | 100% VISUAL INSPECTION  | COMPARE TO MASTER SAMPLE  | VISUAL            | AREA MANAGER/OPERATOR | 100%                   |               |              |             |
|                        | TOP DRESS   | 20-50 kgf.co  | TORQUE WRENCH     | QA LAB                | 1/ WEEK                |               |              |             |
| 34                     | INSERT CLAMP P/N 30015674 AND HOSE P/N 30014635 ONTO FUEL PUMP  |   |                   |                       |                        |               |              |             |
| 35                     | ENSURE CLAMP (30015674) IS IN PROPER POSITION (REFER TO SAMPLE)   | SCREEN HEAD FACING UP WITH SCREEN SIDE TOWARDS FUEL INLET 3 - B MM FROM END OF HOSE | VISUAL/SCALE      | AREA MANAGER/OPERATOR | 100%                   |               |              |             |
| 36                     | WRAP CLAMPS (30002200) AROUND HOSE (30014635) 2 PLACES (REFER TO SAMPLE)  | 3-6 MM GAP BETWEEN HOSE RETURN AND HOSE TO SEPARATOR TANK                           | VISUAL/SCALE      | AREA MANAGER/OPERATOR | 100%                   |               |              |             |
| 37                     | REMOVE PAINT MASKING PLATE FOR P-SENSOR. ENSURE "O" RING PRESENT AND MARKER CHECK TOP AND BOTTOM OF RING (P/N 30016310) ** ENSURE RING IS CENTERED ** | PAINT FREE  | VISUAL            | AREA MANAGER/OPERATOR | 100%                   |               |              |             |
| 38                     | INSTALL P-SENSOR P/N 3018805 WITH 2 SCREENS P/N 30003198  | 2 - 4 Mm  | TORQUE WRENCH     | QA LAB                | 1/ WEEK                |               |              |             |
| 39                     | CRITICAL: ENSURE THE LONG SIDE OF P-SENSOR IS FACING IN OPPOSITE DIRECTION OF FUEL FILLER NECK  | COMPARE TO MASTER SAMPLE  | VISUAL            | AREA MANAGER/OPERATOR | 100%                   |               |              |             |
| 40                     | DROPPING OF P-SENSOR  | NOT ALLOWED (NOTIFY O.C.)   | VISUAL            | AREA MANAGER/OPERATOR | 100%                   |               |              |             |
| 41                     | INSTALL PRE-ASSEMBLED SUB-ASSEMBLY P/N 268-1 CONSISTS OF: P/N'S 30014576, 36057808, 36061880, 30015397  | COMPARE TO MASTER SAMPLE  | VISUAL            | AREA MANAGER/OPERATOR | 100%                   |               |              |             |
| REASONS FOR REVISION   |   |   |                   | AUTHORITY             | DATE                   | CHECKED BY:   | APPROVED BY: |             |
|                        |   |   |                   |                       |                        |               | CAMI B.C.    |             |

**A PART**





7-4-B 11/12


| CIS PART INSPECTION STANDARD (A)   |  |  |   | DATE:  | PROPOSED BY:   | CHECKED BY:           | APPROVED BY: |
|--|--|--|---|--|--|-----------------------|--------------|
| PART NUMBER  |  | PART NAME  |   | MODEL  | ENG CHANGE NUMBER  | SUPPLIER NAME         | DUNS NUMBER  |
| 30018268 (89019-578611)  |  | 4 DOOR TRUCK TANK FUEL ASSEMBLY  |   | 4 DOOR 96 MODEL YEAR   | Y09-1731   | PRINCE METAL PRODUCTS | 247650542    |
| NO.  | INSPECTION CHARACTERISTICS   | CRITERIA   | INSPECTION METHOD   | INSPECTION DIVISION  | QUANTITY AND FREQUENCY   |                       |              |
| 111  | FINAL INSPECTION<br>A) BAR CODE TAGS<br>B) ALL WELD ARE SECURE<br>C) PAINT ON FILLER NECK AND CONNECTORS<br>D) SCREW PRESENCE<br>E) ALL CLAMPS IN PROPER POSITION AND MARKER CHECKED.<br>F) ENSURE PROPER GAP BETWEEN HOSE SEPARATOR AND FUEL RETURN HOSE<br>G) VISUAL CHARACTERISTICS | MUST MATCH PART IN SHIPPING RACK<br>MUST NOT COME LOOSE<br>NOT ALLOWED<br>MUST HAVE 18<br>MUST HAVE 5<br>MUST HAVE 3 - 6 MM GAP<br>NO BINGS, DENTS, BARE METAL AND MISSING COMPONENTS ALLOWED. | VISUAL<br>PRY<br>VISUAL<br>VISUAL<br>VISUAL<br>VISUAL/SCALE<br>VISUAL | FINAL AUDITOR<br>FINAL AUDITOR<br>FINAL AUDITOR<br>FINAL AUDITOR<br>FINAL AUDITOR<br>FINAL AUDITOR<br>FINAL AUDITOR                  | EACH RACK<br>EACH RACK<br>EACH RACK<br>EACH RACK<br>EACH RACK<br>EACH RACK |                       |              |
| NOTES: AS PER Q.A.M. #11, REFER TO Q.C.I.'S FOR SPECIAL PROCESSES.<br>1. ALL NON-COMFORMING MATERIAL TO BE HANDLED PER Q.A.M.#15.<br>2. ALL BY TEST CONDUCTED PER Q.C.I. #127.<br>3. SEAM WELD PULL TEST CONDUCTED PER Q.C.I. #130<br>4. MIG WELD TESTS CONDUCTED PER Q.C.I.#137<br>5. COLD SPOT WELDS HANDLED PER Q.C.I. #125<br>6. DESTRUCTIVE TEST OF SPOT WELDS CONDUCTED PER Q.C.I. #108<br>7. PINHOLE WELD REPAIR PER Q.C.I. #061<br>8. WELD SPLASH IN THREADS PER Q.C.I. # 062<br>9. PUSH OUT TEST PER Q.C.I. #009<br>10. PAINT SPEC VERIFIED QUARTERLY |  |  |   | AUTHORITY<br>DATE<br>CHECKED BY: <br>APPROVED BY: |  |                       |              |
| REASONS FOR REVISION   |  |  |   | CAMI B.C.  |  |                       |              |
|   |  |  |   | MARKS  |  |                       |              |

AS 279997

7-4-B

12/12

|  |   |  |
|--|---|--|
| <b>CIS PART INSPECTION STANDARD (A)</b>    |   | APPROVED BY: <i>[Signature]</i><br>DUNS NUMBER: 247650542              |
| PART NUMBER: 30018268 (89019-57861)        | DATE: JANUARY 12, 1996<br>MODEL: 4 DOOR 95 MODEL YEAR | CHECKED BY: <i>[Signature]</i><br>SUPPLIER NAME: PRINCE METAL PRODUCTS |
| PART NAME: 4 DOOR TRUCK TANK FUEL ASSEMBLY | ENG CHANGE NUMBER: Y09-1731                           | BORO TAGGART   |
| INSPECTION CHARACTERISTICS                 | CRITERIA  | INSPECTION METHOD  |
|  |   | INSPECTION DIVISION  |
|  |   | QUANTITY AND FREQUENCY   |



A P

| MARKS | REASONS FOR REVISION | AUTHORITY | DATE | CHECKED BY: | APPROVED BY: |
|-------|----------------------|-----------|------|-------------|--------------|
|       |                      |           |      |             |              |
|       |                      |           |      |             |              |
|       |                      |           |      |             |              |
|       |                      |           |      |             |              |

CAMI B.C.

| CIS PART INSPECTION STANDARD (A)                            |   | DATE:   | PROPOSED BY:  | CHECKED BY:  | APPROVED BY:  |
|---|---|---|---|--|---|
| <p><b>A PART</b></p> <p>4 DOOR TRUCK TANK FUEL ASSEMBLY</p> |   | JUNE 20, 1956   | KEVIN ROTH  | <i>[Signature]</i>   | <i>[Signature]</i>  |
| ITEM NUMBER   | WHSE  | MODEL   | ENG CHANGE NUMBER   | SUPPLIER NAME  | DUINS NUMBER  |
| 1-30-3  | (89019-578E4)   | 4 DOOR GAS TANK   | 60A-9380 (CAMI ECH)   | PRINCE METAL PRODUCTS  | 2476S0542   |
| INSPECTION CHARACTERISTICS                                  |   | CRITERIA  | INSPECTION METHOD   | INSPECTION DIVISION  | QUANTITY AND FREQUENCY  |
| 1   | RECEIVING INSPECTION<br>89111-57830 - GAS TANK UPPER BLANKS<br>(SEE 89111-57830 CIS)  | STD-92  | CERTIFICATION   | RECEIVING INSPECTION   | EACH BUNDLE OF BLANKS   |
| 2   | 89112-56800 - GAS TANK LOWER BLANKS<br>(SEE 89112-56800 CIS)  | STD-92  | CERTIFICATION   | RECEIVING INSPECTION   | EACH BUNDLE OF BLANKS   |
| 3   | 89121-82000 - INLET PIPE<br>(PURCHASED FROM SHELBY)<br>A) OUTER DIAMETER OF TUBE<br>B) OVERALL LENGTH<br>C) COATING<br>D) CHEMICAL COMPOSITION OF STEEL<br>E) INSIDE TUBE DIA.              | 42.7 MM +/- 0.5 MM<br>129.0 MM +/- 1.2 MM<br>MF208-C<br>STAINLESS                   | VEFNIER/CAL. REF. SCALE<br>VISUAL/CERTIFICATION<br>VISUAL/CERTIFICATION<br>CHECK VALVE    | RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION | (AS REQUESTED PER P.O.)<br>PER SAMPLING PLAN QPM 4.10.2.2(EACH SHIP.)<br>PER SAMPLING PLAN QPM 4.10.2.2(EACH SHIP.)<br>PER SAMPLING PLAN QPM 4.10.2.2(EACH SHIP.)<br>PER SAMPLING PLAN QPM 4.10.2.2(EACH SHIP.)<br>PER SAMPLING PLAN QPM 4.10.2.2(EACH SHIP.) |
| 4   | 89122-56800 - PLATE CUT VALVE<br>(PURCHASED FROM LAMEX)<br>A) PROJECTION HEIGHTS<br>B) THREAD VERIFICATION<br>C) COATING<br>D) CHEMICAL COMPOSITION<br>E) MAT'L THICKNESS                   | 1.1 MM +/- 0.27-0 MM<br>3 PLACES MS<br>MF208-C<br>BASE STEEL - SFHC<br>3.2 +/- 0.21 | MICROMETER<br>MS X 0.8 EN THREAD GAGE<br>VISUAL / CERTIFICATION<br>VISUAL / CERTIFICATION | RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION | PER SAMPLING PLAN QPM 4.10.2.2(EACH SHIP.)<br>PER SAMPLING PLAN QPM 4.10.2.2(EACH SHIP.)<br>PER SAMPLING PLAN QPM 4.10.2.2(EACH SHIP.)<br>PER SAMPLING PLAN QPM 4.10.2.2(EACH SHIP.)<br>PER SAMPLING PLAN QPM 4.10.2.2(EACH SHIP.)                            |
| 5   | 89123-50F00 - PLATE, FUEL PUMP ATTACHMENT<br>(PURCHASED FROM NISSHO-TWAI)<br>A) PROJECTION HEIGHTS<br>B) THREAD VERIFICATION<br>C) COATING<br>D) CHEMICAL COMPOSITION<br>E) MAT'L THICKNESS | 1.1 MM +/- 0.27-0 MM<br>5 PLACES MS<br>MF208-C<br>BASE STEEL SFHC<br>3.2 +/- 0.21   | MICROMETER<br>MS X 0.8 EN THREAD GAGE<br>VISUAL / CERTIFICATION<br>VISUAL / CERTIFICATION | RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION | PER SAMPLING PLAN QPM 4.10.2.2(EACH SHIP.)<br>PER SAMPLING PLAN QPM 4.10.2.2(EACH SHIP.)<br>PER SAMPLING PLAN QPM 4.10.2.2(EACH SHIP.)<br>PER SAMPLING PLAN QPM 4.10.2.2(EACH SHIP.)<br>PER SAMPLING PLAN QPM 4.10.2.2(EACH SHIP.)                            |
| 6   | 89124-51F00 - PLATE FUEL PUMP ATTACHMENT(LANE)<br>A) PROJECTION HEIGHTS<br>B) THREAD VERIFICATION<br>C) COATING<br>D) CHEMICAL COMPOSITION<br>E) MAT'L THICKNESS                            | 1.1 MM +/- 0.27-0 MM<br>6 PLACES MS<br>MF208-C<br>BASE STEEL SFHC<br>3.2 +/- 0.21   | MICROMETER<br>MS X 0.8 EN THREAD GAGE<br>VISUAL / CERTIFICATION<br>VISUAL / CERTIFICATION | RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION | PER SAMPLING PLAN QPM 4.10.2.2(EACH SHIP.)<br>PER SAMPLING PLAN QPM 4.10.2.2(EACH SHIP.)<br>PER SAMPLING PLAN QPM 4.10.2.2(EACH SHIP.)<br>PER SAMPLING PLAN QPM 4.10.2.2(EACH SHIP.)<br>PER SAMPLING PLAN QPM 4.10.2.2(EACH SHIP.)                            |
| REASONS FOR REVISION  |   | AUTHORITY   | DATE  | CHECKED BY:  | APPROVED BY:  |
| PUMP CHANGE FROM 30014232 TO 30018725                       |   | GORD TAGGART  | 04/22/96  | <i>[Signature]</i>   | <i>[Signature]</i>  |
| NEW BUSSET P/N 30019611                                     |   | GORD TAGGART  | 05/20/96  | <i>[Signature]</i>   | <i>[Signature]</i>  |
| SEAL CHANGE & 1P. SENSOR CHANGE                             |   | GORD TAGGART  | 03/20/96  | <i>[Signature]</i>   | <i>[Signature]</i>  |

CAMI B.C.

AS 279999

| C15 PART INSPECTION STANDARD (A)   |  | DATE:  | PROPOSED BY:   | ORDERED BY:  | APPROVED BY:   | DUNS NUMBER   |
|--|--|--|--|--|--|---|
| PART NAME  |  | JUNE 20, 1996  | LEVIN PGRTH  | J. Taggart 3-13-97   | [Signature]  | 247650542   |
| * 000F TRUCK TANK FUEL ASSEMBLY  |  | MODEL  | ENG CHANGE NUMBER  | SUPPLIER NAME  | QUANTITY AND FREQUENCY   |   |
| * 000F TRUCK TANK FUEL ASSEMBLY  |  | * 000F GAS TANK  | 60A-93B0 (CAMI EFN) 06/12/96   | PRINCE METAL PRODUCTS  | EACH COIL  |   |
| INSPECTION CHARACTERISTICS   | CRITERIA   | INSPECTION METHOD  | INSPECTION DIVISION  | INSPECTION DIVISION  | INSPECTION DIVISION  | QUANTITY AND FREQUENCY  |
| 7 RECEIVING INSPECTION (CONTINUED)<br>30015611 (89125-57830) BUSSET FUEL TANK NO.1   | SCALE - 45/45  | REFER CIS '89125-57B30'  | RECEIVING INSPECTION   | RECEIVING INSPECTION   | RECEIVING INSPECTION   | EACH COIL   |
| 8 89125-56800 - BUSSET FUEL TANK NO.2<br>(SEE 89125-56800 CIS)   | SBAC-45/45   | REFER CIS '89126-56B00'  | RECEIVING INSPECTION   | RECEIVING INSPECTION   | RECEIVING INSPECTION   | EACH COIL   |
| 9 89127-56800 - BUSSET FUEL TANK NO.3<br>(SEE 89127-56800 CIS)   | SBAC-45/45   | REFER CIS '89127-56B00'  | RECEIVING INSPECTION   | RECEIVING INSPECTION   | RECEIVING INSPECTION   | EACH COIL   |
| 10 89129-56800 - PLATE, P-SENSOR ATTACHMENT<br>(PURCHASED FROM LANEX)<br>A) MATERIAL THICKNESS<br>B) PROJECTION HEIGHTS<br>C) THREAD VERIFICATION<br>D) COATING<br>E) CHEMICAL COMPOSITION | 3.2 MM +/- 0.21 MM<br>1.1 MM +/- 0.07-0 MM<br>2 PLACES - MS<br>M70B-C<br>BASE STEEL - SPHC | CERTIFICATION<br>MICROMETER<br>MICROMETER<br>MS X 0.8 SH THREAD GAGE<br>VISUAL / CERTIFICATION<br>VISUAL / CERTIFICATION | RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION | RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION | RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION | PER SAMPLING PLAN QPH 4.10-2.2 (EACH SHIP.)<br>PER SAMPLING PLAN QPH 4.10-2.2 (EACH SHIP.)<br>PER SAMPLING PLAN QPH 4.10-2.2 (EACH SHIP.)<br>PER SAMPLING PLAN QPH 4.10-2.2 (EACH SHIP.)<br>PER SAMPLING PLAN QPH 4.10-2.2 (EACH SHIP.) |
| 11 89120-57820 - PIPE COMP FUEL TANK BREATHER<br>A) OUTER DIAMETER OF TUBE<br>B) OUTER DIAMETER OF END OF TUBE<br>C) COATING<br>D) CHEMICAL COMPOSITION<br>E) WELD INTEGRITY               | 14.0 MM +/- 0.65 MM<br>15.4 MM +/- 0.3 MM<br>M70B-C<br>BASE STEEL - STPM11A<br>P.P.M.      | VERIFY<br>VERNIER<br>CERTIFICATION<br>CERTIFICATION<br>PEY TOOL  | RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION | RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION | RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION | PER SAMPLING PLAN QPH 4.10-2.2 (EACH SHIP.)<br>PER SAMPLING PLAN QPH 4.10-2.2 (EACH SHIP.)<br>PER SAMPLING PLAN QPH 4.10-2.2 (EACH SHIP.)<br>PER SAMPLING PLAN QPH 4.10-2.2 (EACH SHIP.)<br>PER SAMPLING PLAN QPH 4.10-2.2 (EACH SHIP.) |
| 12 89125-56800 - BRACKET FUEL TANK BREATHER<br>(SEE 89135-60A00 CIS)   | SBAC-45/45   | CERTIFICATION  | RECEIVING INSPECTION   | RECEIVING INSPECTION   | RECEIVING INSPECTION   | EACH COIL   |
| 13 89171-61A00 - OUTER POT<br>(SEE 89171-61A00 CIS)  | ZLE-20/20C   | REFER CIS '89135-60A00'  | RECEIVING INSPECTION   | RECEIVING INSPECTION   | RECEIVING INSPECTION   | EACH COIL   |
| 14 89172-56800 - INNER POT<br>(SEE 89172-56800 CIS)  | ZLE-20/20  | REFER CIS '89171-61A00'  | RECEIVING INSPECTION   | RECEIVING INSPECTION   | RECEIVING INSPECTION   | EACH COIL   |
| RESPONSIBLE FOR REVISION   |  | AUTHORITY  |  | CAMI Q.C.  |  |   |
| FORM CHANGE FROM 89014333 TO 20015726  |  | DATE   | CHECKED BY:  | DATE   | APPROVED BY:   |   |
| NEW BUSSET P/N 200*  |  | 06/22/96   |  | 06/22/96   |  |   |
|  |  | 06/22/96   |  | 06/22/96   |  |   |

AS 280000

| CIS PART INSPECTION STANDARD (A) |  | DATE:  | PROPOSED BY:                   | CHECKED BY:                                  | APPROVED BY:           | DUNS NUMBER   |
|----------------------------------|--|--|--------------------------------|--|------------------------|---|
| PART NAME                        |  | JUNE 20, 1996  | LEVIN FORTH                    | <i>H. Jagan 3-13-97</i>                      | <i>J. Mont</i>         | 247650642   |
| ST NUMBER                        | 13688  | MODEL  | ENG CHANGE NUMBER              | SUPPLIER NAME                                |                        |   |
|                                  | 25019-578E4  | 4 DOOR GAS TANK  | 50A-3090 (CAMI ECM) 06/12/96   | PRINCE METAL PRODUCTS                        |                        |   |
| INSPECTION CHARACTERISTICS       |  | CRITERIA   | INSPECTION METHOD              | INSPECTION DIVISION                          | QUANTITY AND FREQUENCY |   |
| RECEIVING INSPECTION CONTINUED   |  |  |                                |  |                        |   |
| 14                               | 89176-61A00 - BRACKET<br>(SEE 89176-61A00 CIS)   | ZLC-20/20<br>REFER CIS 89176-61A00   | CERTIFICATION                  | RECEIVING INSPECTION                         |                        | EACH COIL   |
| 15                               | 89177-61A00 - BRACKET<br>(SEE 89177-61A00 CIS)   | ZLC-20/20<br>REFER CIS 89177-61A00   | CERTIFICATION                  | RECEIVING INSPECTION                         |                        | EACH COIL   |
| 17                               | 89178-60A00 - V4P00R SEP BRKT ASSY PLATED<br>(SEE 89178-60A00 CIS)<br>COATING PERFORMED BY KLINEC  | SPCC-MS<br>REFER CIS 89178-60A00<br>7-4-C  | CERTIFICATION                  | RECEIVING INSPECTION                         |                        | EACH COIL   |
| 18                               | 09405-35302 (30001095) - CLAMP FUEL TANK<br>(PURCHASED FROM MARWOOD)<br>* PART NOT AS SHOWN ON PART PRINT<br>A) MATERIAL THICKNESS<br>B) BLACK COATING | 0.7 MM +/- 0.04 MM<br>(MUST BE PRESENT) 15.0 TO<br>18.0 MM FROM EDGE OF PART<br>MUST HAVE NO COATING | MICROMETER<br>VISUAL AND SCALE | RECEIVING INSPECTION<br>RECEIVING INSPECTION |                        | PER SAMPLING PLAN QPM 4.10.2.2 (AS REQUEST)   |
| 19                               | 09405-65303 (30003200) - CLAMP FUEL TANK<br>(PURCHASED FROM MARWOOD)<br>* PART NOT AS SHOWN ON PART PRINT<br>A) MATERIAL THICKNESS<br>B) BLACK COATING | 0.7 MM +/- 0.04 MM<br>MUST BE PRESENT AND 15.0 TO<br>18.0 MM FROM EDGE OF PART                       | MICROMETER<br>VISUAL           | RECEIVING INSPECTION<br>RECEIVING INSPECTION |                        | PER SAMPLING PLAN QPM 4.10.2.2 (AS REQUEST)<br>PER SAMPLING PLAN QPM 4.10.2.2 (EACH SHIP) |
| 20                               | 59455-5E806 (30014575) - GUT VALVE<br>(PURCHASED BY KISSHO IMAI)<br>* CAMI APPROVED SOURCE   | PART CERTIFICATION FOR ALL<br>TESTS, DIMENSIONS AND MATERIALS  | CERTIFICATION                  | RECEIVING INSPECTION                         |                        | AS REQUESTED  |
| 21                               | 24810-70E25 (30013887) - GAUGE ASSY FUEL LEVEL<br>(PURCHASED FROM KISSHO IMAI)<br>* CAMI APPROVED SOURCE   | PART CERTIFICATION FOR ALL<br>TESTS, DIMENSIONS AND MATERIALS  | CERTIFICATION                  | RECEIVING INSPECTION                         |                        | AS REQUESTED  |
| 22                               | 25019-5E806 (30016726) - PUMP ASSY FUEL<br>(PURCHASED FROM KUTAFMS - CONSIGNMENT)<br>* CAMI APPROVED SOURCE  | PART CERTIFICATION FOR ALL<br>TESTS, DIMENSIONS AND MATERIALS  | CERTIFICATION                  | RECEIVING INSPECTION                         |                        | AS REQUESTED  |

| REVISION | REASON FOR REVISION                   | AUTHORITY    | DATE     | CHECKED BY: | APPROVED BY: |
|----------|---------------------------------------|--------------|----------|-------------|--------------|
| 1        | PUMP CHANGE FROM 25014533 TO 30016726 | EDDF 7438AFT | 04/22/96 |             |              |
| 2        | NEW BUSHET P/N 25019611               | ISDF 7438AFT | 05/20/96 |             |              |
| 3        | NEW COIL 3 191 SENSOR CHANGE          | ISDF 7438AFT | 03/07/97 |             |              |

AS 280001

| CIS PART INSPECTION STANDARD (A)   |  | DATE:   | PROPOSED BY:   | CHECKED BY:   | APPROVED BY:       |
|--|--|---|--|---|--------------------|
|  |  | JUNE 20, 1996   | KEVIN ROATH  | <i>[Signature]</i>  | <i>[Signature]</i> |
| NUMBER   | PART NAME  | MODEL   | ENG CHARGE NUMBER  | SUPPLIER NAME   | DUNS NUMBER        |
| 3596   | 4 DOOR TRUCK TANK FUEL ASSEMBLY  | 4 DOOR GAS TANK   | 60A-9280 (CAMI ECH) 06/12/96   | FRANCE METAL PRODUCTS   | 247650542          |
| INSPECTION CHARACTERISTICS   | CRITERIA   | INSPECTION METHOD   | INSPECTION DIVISION  | QUANTITY AND FREQUENCY  |                    |
| RECEIVING INSPECTION CONTINUED<br>A) THREAD VERIFICATION<br>B) COATING<br>C) CHEMICAL COMPOSITION<br>D) HEAD HEIGHT<br>E) THREAD AND RECESSED LENGTH   | MS X 0.3<br>MFG TO<br>ONI SC<br>3.3 MM +/- 0.15 MM<br>13.0 MM +/- 0.8 MM   | THREADED RING GAUGE<br>CERTIFICATION<br>CERTIFICATION<br>VERNIER<br>VERNIER | RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION                         | PER SAMPLING PLAN OPH 4.10.2.2 (AS REQUEST)<br>PER SAMPLING PLAN OPH 4.10.2.2 (AS REQUEST)<br>PER SAMPLING PLAN OPH 4.10.2.2 (AS REQUEST)<br>PER SAMPLING PLAN OPH 4.10.2.2 (AS REQUEST)  |                    |
| RECEIVING INSPECTION TOP DRESS - (CUSTOMER SUPPLIED MATERIAL)<br>A. 30014576 (89411-56200)<br>B. 30014635 (09356-55117-410)<br>C. 30015397 (09356-55113-21010)<br>D. 30016308 (09280-50760)<br>E. 30018909 (69421-79E10)<br>F. 30016310 (89425-79E00)<br>G. 96057808 (09401-11412)<br>H. 96061880 (05401-11413)<br>I. 30015674 (09402-15511)<br>J. 268-1<br>K. 30014575 (PROTECT)<br>L. M15 WIRE (0.5MM) TYPE MS101 - (FRAMPAIR) | 1. NO VISUAL DEFECTS OF DIFF<br>2. VERIFY QUANTITY<br>3. P/N LOT NUMBER<br>4. OUTSTANDING ORDER # 5)<br>BUYER'S USE DATE<br>5. AFFIX CSM STICKER TO EACH PALLET OF MATERIAL RECEIVED | VISUAL<br>VISUAL<br>DESIGNED<br>VISUAL<br>VISUAL                            | RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION<br>RECEIVING INSPECTION | PER SAMPLING PLAN OPH 4.10.2.2 (AS REQUEST)<br>PER SAMPLING PLAN OPH 4.10.2.2 (AS REQUEST)<br>PER SAMPLING PLAN OPH 4.10.2.2 (AS REQUEST)<br>PER SAMPLING PLAN OPH 4.10.2.2 (AS REQUEST)<br>PER SAMPLING PLAN OPH 4.10.2.2 (AS REQUEST) |                    |
| 30000023 - (02142-05983)<br>THREAD VERIFICATION<br>VERIFY QUANTITY   | MS X 0.8 MM<br>VERIFY QUANTITY   | RING GAUGE<br>VISUAL  | RECEIVING INSPECTION<br>RECEIVING INSPECTION   | PER SAMPLING PLAN OPH 4.10.2.2 (AS REQUEST)<br>PER SAMPLING PLAN OPH 4.10.2.2 (AS REQUEST)  |                    |
| DEFECTLESS INSPECTION 89111-57830<br>89112-57830<br>DEFLECTION WELD (2) P/N 08315-01059 WELD<br>NUTS 5 MM TO P/N 85178-60A00 BRACKET   | SEE CIS FOR IN-PROCESS CONTROLS<br>MUST FULL PARENT MATERIAL<br>NO WELD SPURSE ALLOWED   | APCA MANAGER AND OPERATOR   | APCA MANAGER AND OPERATOR  | 2 PCS PER SHIFT DEFECTIVE TEST AND<br>100% P/FY TOOL CHECK  |                    |
| 89113 WELD P/N 85178-61A00 & 89177-61A30<br>89113 TO 89171-61A00 GUTER VESSEL (6 SPOTS)  | MUST FULL PARENT MATERIAL  | MANAGER AND OPERATOR  | MANAGER AND OPERATOR   | 2 PCS PER SHIFT DEFECTIVE TEST AND<br>100% P/FY TOOL CHECK  |                    |
| 89113 WELD P/N 89178-66B00 INNER VESSEL TO<br>P/N 89171-61A00 GUTER VESSEL (6 SPOTS)   | MUST FULL PARENT MATERIAL  | MANAGER AND OPERATOR  | MANAGER AND OPERATOR   | 2 PCS PER SHIFT DEFECTIVE TEST AND<br>100% P/FY TOOL CHECK  |                    |
| CAMI Q.C.  |  |   |  |   |                    |
| REASONS FOR REVISION   |  | AUTHORITY   | DATE   | CHECKED BY:   | APPROVED BY:       |
| PUMP CHANGE FROM 2001-330 TO 2001971E  |  |   | 06/22/96   |   |                    |
| NEW SUBSET P/N 20019511  |  |   | 06/20/96   |   |                    |
| NEW EXT. 1 P/N SELF-CHARGE   |  |   | 02/07/97   |   |                    |

AS 280002

FORM 359-11-96

| CIS PART INSPECTION STANDARD (A)           |  | DATE:   | PROPOSED BY:                 | CHECKED BY:               | APPROVED BY:                       |
|--|--|---|------------------------------|---------------------------|------------------------------------|
|  |  | JUNE 20, 1996                                     | KEVIN FOATH                  | <i>J. Taggart</i> 3-15-97 | <i>[Signature]</i> 3/14/97 97-3-13 |
| ART NUMBER                                 | DESCRIPTION  | MODEL   | ENG CHANGE NUMBER            | SUPPLIER NAME             | DUNS NUMBER                        |
| 82019-57830                                | 4 DOOR TRUCK TANK FUEL ASSEMBLY  | 4 DOOR GAS TANK                                   | 604-3367 (501 ECH) (6/12/96) | PRINCE METAL PRODUCTS     | 247650542                          |
| INSPECTION CHARACTERISTICS                 | CRITERIA   | INSPECTION METHOD                                 | INSPECTION DIVISION          | QUANTITY AND FREQUENCY    |                                    |
| 4  | IN-PROCESS INSPECTION CONTINUED<br>PROJECTION WELD P/N 89124-51700 TO P/N 89111-57830 (6 PLACES) | 1. HAMMER AND CHISEL<br>2. FRY                    | AREA MANAGER AND OPERATOR    | 2/SHIFT                   |                                    |
| 5  | PROJECTION WELD P/N 89123-50700 TO P/N 89111-57830 (5 PLACES)                                    | 1. HAMMER AND CHISEL<br>2. FRY                    | AREA MANAGER AND OPERATOR    | 2/SHIFT                   | 100%                               |
| 6  | PROJECTION WELD P/N 89122-56800 TO P/N 89111-57830 (3 PLACES)                                    | 1. HAMMER AND CHISEL<br>2. FRY                    | AREA MANAGER AND OPERATOR    | 2/SHIFT                   | 100%                               |
| 7  | PROJECTION WELD P/N 89129-66800 TO P/N 89111-57830 (4 PLACES)                                    | 1. HAMMER AND CHISEL<br>2. FEELER GAUGE<br>3. FRY | AREA MANAGER AND OPERATOR    | 2/SHIFT                   | 100%                               |
| 8  | SPOT WELD P/N 89130-57820 TO P/N 89111-57830 (2 PLACES)  | 1. HAMMER AND CHISEL<br>2. FRY                    | AREA MANAGER AND OPERATOR    | 2/SHIFT                   | 100%                               |
| 9  | SPRUE P/N 89130-57820 TO P/N 89111-57830 (356 DEGREES)   | 1. LEAK TESTER<br>2. 100% INSPECTION, POLISH, ETC | AREA MANAGER AND OPERATOR    | 2/SHIFT                   | 100%<br>ONCE PER WEEK              |
| 10   | SPOT WELD P/N 89405-65503 (30003200) CLIPS TO P/N 89111-57830                                    | 1. HAMMER AND CHISEL                              | AREA MANAGER AND OPERATOR    | 2/SHIFT                   |                                    |
| REASONS FOR REVISION                       |  |   |                              | AUTHORITY                 | CHECKED BY:                        |
| 1. FUEL ASSEMBLY FROM 36014332 TO 36018725 |  |   |                              | 36018725                  | 04/22/96                           |
| 2. NEW GUSSET P/N 20019611                 |  |   |                              | 20019611                  | 05/20/96                           |
| 3. SEC. CHANGE 3 PT SENSOR CHANGE          |  |   |                              | 20019611                  | 03/07/97                           |
|  |  |   |                              |                           | APPROVED BY:                       |
|  |  |   |                              |                           | CAMI B.C.                          |

AS 280003



7-4-C page 6/12

| NUMBER                                | PART NAME  | DATE                            | PROPOSED BY:  | CHECKED BY:  | APPROVED BY:   | DUNS NUMBER  |  | QUANTITY AND FREQUENCY |           |
|---------------------------------------|--|---------------------------------|---|--|--|--|--|------------------------|-----------|
|                                       |  |                                 |   |  |  | ENG CHANGE NUMBER  | SUPPLIER NAME                            |                        |           |
| INSPECTION CHARACTERISTICS            |  | MODEL                           | INSPECTION METHOD   | CRITERIA   | INSPECTION DIVISION  | AREA MANAGER AND OPERATOR  | AREA MANAGER AND OPERATOR                |                        |           |
| 11                                    | SPOT WELD P/N 09405-35303 (39001095)<br>(CLIP TO P/N 85111-57830)                      | 4 DOOR TRUCK TANK FUEL ASSEMBLY | 1. EACH PROJECTION MUST FULL PARENT MATERIAL  | 1. HAMMER AND CHISEL   | AREA MANAGER AND OPERATOR  | AREA MANAGER AND OPERATOR  | 2/SHIFT                                  |                        |           |
| 12                                    | SPOT WELD P/N 89178-40A00 TO P/N 89111-57830<br>(2 PLACES)<br>** LOCATION IMPORTANT ** | 4 DOOR TRUCK TANK FUEL ASSEMBLY | 1. EACH SPOT WELD MUST FULL PARENT MATERIAL<br>2. PART MUST NOT COME LOOSE<br>3. STRAIGHT FLANGE OR BENT TOWARD FUEL INLET HOLE<br>4. 2-5 MM NUTS MUST BE PRESENT PARENT MATERIAL | 1. HAMMER AND CHISEL<br>2. PRY   | AREA MANAGER AND OPERATOR  | AREA MANAGER AND OPERATOR  | 2/SHIFT<br>100%<br>100%<br>100%          |                        |           |
| 13                                    | SPOT WELD P/N 89170-56800 TO P/N 89112-56800<br>(6 PLACES)                             |                                 | 1. EACH SPOT WELD MUST FULL PARENT MATERIAL<br>2. PART MUST NOT COME LOOSE  | 1. HAMMER AND CHISEL<br>2. PRY   | AREA MANAGER AND OPERATOR  | AREA MANAGER AND OPERATOR  | 2/SHIFT<br>100%                          |                        |           |
| 14                                    | SPOT WELD P/N 89111-57830 TO P/N 89112-56800<br>(4 PLACES)                             |                                 | 1. EACH SPOT WELD MUST FULL PARENT MATERIAL   | 1. HAMMER AND CHISEL   | AREA MANAGER AND OPERATOR  | AREA MANAGER AND OPERATOR  | 2/SHIFT                                  |                        |           |
| 15                                    | SEAM WELD P/N 89111-57830 TO P/N 89112-56800<br>(A)                                    |                                 | 1. MUST NOT LEAK<br>2. MUST NOT SEPARATE<br>3. MUST NOT BREAK AT WELD<br>4. SEAM WELD MUST PASS AS CLOSE AS POSSIBLE TO TANK BUT MUST NOT PASS CORNER RADIUS                      | 1. LEAK TESTER<br>2. HAMMER AND CHISEL<br>3. TENSILE TESTER<br>4. VISUAL | AREA MANAGER AND OPERATOR<br>AREA MANAGER AND OPERATOR<br>AREA MANAGER AND OPERATOR<br>AREA MANAGER AND OPERATOR | AREA MANAGER AND OPERATOR<br>AREA MANAGER AND OPERATOR<br>AREA MANAGER AND OPERATOR<br>AREA MANAGER AND OPERATOR | 100%<br>EVERY 75 PARTS<br>1/WEEK<br>100% |                        |           |
| 16                                    | STAMP LOT TRACEABILITY ON P/N 89125-60A00<br>(55 SPOTS BELOW)                          |                                 | 1. MUST BE PRESENT AND LEGIBLE  | 1. VISUAL  | AREA MANAGER AND OPERATOR  | AREA MANAGER AND OPERATOR  | 100%                                     |                        |           |
| REASONS FOR REVISION                  |  | AUTHORITY                       |   | CHECKED BY:  |  | APPROVED BY:   |  | CAMI O.C.              |           |
| PUMP CHANGE FROM 30014555 TO 30018726 |  | DATE                            | 194/20/96   | DATE   | 194/20/96  | DATE   | 194/20/96                                | DATE                   | 194/20/96 |
| NEW SUSSET P/N 30019611               |  | DATE                            | 196/20/96   | DATE   | 196/20/96  | DATE   | 196/20/96                                | DATE                   | 196/20/96 |
| PUMP CHANGE FROM 30014555 TO 30018726 |  | DATE                            | 194/20/96   | DATE   | 194/20/96  | DATE   | 194/20/96                                | DATE                   | 194/20/96 |

AS 280004









| CIS PART INSPECTION STANDARD (A)  |   | DATE:           | PROPOSED BY:                | CHECKED BY:           | APPROVED BY:           |
|---|---|-----------------|-----------------------------|-----------------------|------------------------|
|   |   | JUNE 20, 1996   | KEVIN BOATH                 | <i>J. Taggart</i>     | <i>Kevin Boath</i>     |
| ART NUMBER  | NAME  | MODEL           | ENG CHANGE NUMBER           | SUPPLIER NAME         | DUNS NUMBER            |
| 3019868 (S019-S7864)  | 4 DOOR TRUCK TANK FUEL ASSEMBLY                             | 4 DOOR GAS TANK | 60A-53B (CAMI ESN) 06/12/96 | PRINCE METAL PRODUCTS | 24750542               |
| INSPECTION CHARACTERISTICS  |   | CRITERIA        | INSPECTION METHOD           | INSPECTION DIVISION   | QUANTITY AND FREQUENCY |
| FINAL INSPECTION  |   |                 |                             |                       |                        |
| A) BAR CODE TAGS  | RUST MATCH PART IN SHIPPING RACK                            | VISUAL          | FINAL AUDITOR               |                       | EACH RACK              |
| B) ALL WELDS ARE SECURE   | RUST NOT COME LOOSE   | PSY             | FINAL AUDITOR               |                       | EACH RACK              |
| C) PAINT ON FILLER NECK AND CONNECTORS  | NOT ALLOWED   | VISUAL          | FINAL AUDITOR               |                       | EACH RACK              |
| D) SCREEN PRESENCE  | MUST HAVE 18  | VISUAL          | FINAL AUDITOR               |                       | EACH RACK              |
| E) ALL CLAMPS IN PROPER POSITION AND MARKER CHECKED   | MUST HAVE 5   | VISUAL          | FINAL AUDITOR               |                       | EACH RACK              |
| F) ENSURE PROPER GAP BETWEEN HOSE SEPARATOR AND FUEL RETURN HOSE  | MUST HAVE 3 - 6 MM GAP                                      | VISUAL/SCALE    | FINAL AUDITOR               |                       | EACH RACK              |
| G) VISUAL CHARACTERISTICS   | NO DINGS, DENTS, RAFFI METAL AND MISSING COMPONENTS ALLOWED | VISUAL          | FINAL AUDITOR               |                       | EACH RACK              |
| <p>NOTES: AS PER Q.C.I.#11, REFER TO Q.C.I.#5 FOR SPECIAL PROCESSES.</p> <ol style="list-style-type: none"> <li>1. ALL NON-COMFORMING MATERIAL TO BE HANDLED PER Q.P.M. 4.13</li> <li>2. ALL PRY TEST CONDUCTED PER Q.C.I.#127</li> <li>3. SEAR WELD PULL TEST CONDUCTED PER Q.C.I.#130</li> <li>4. RTG WELD TESTS CONDUCTED PER Q.C.I.#137</li> <li>5. COLD SPOT WELDS HANDLED PER Q.C.I.#125</li> <li>6. DESTRUCTIVE TEST OF SPOT WELDS CONDUCTED PER Q.C.I.#068</li> <li>7. FITTHOLE WELD REPAIR PER Q.C.I.#061</li> <li>8. WELD SPLASH IN THREAD PER Q.C.I.#062</li> <li>9. PUSH OUT TEST PER Q.C.I.#109</li> <li>10. PAINT SPEC VERIFIED QUARTERLY.</li> </ol> |   |                 |                             |                       |                        |
| REASONS FOR REVISION  |   | AUTHORITY       |                             | DATE                  | CHECKED BY:            |
| 1. PART CHANGE FROM 30014233 TO 30018726  |   | 60PE TAGSAPT    |                             | 04/22/96              |                        |
| 2. NEW ACCESSORY N 30014611   |   | 60PD TAGSAPT    |                             | 05/20/96              |                        |
| 3. NEW SOL 1 1/2" SENSOR CHANGE   |   | 60PD TAGSAPT    |                             | 03/07/97              |                        |
| CAMI Q.C.   |   |                 |                             |                       |                        |
|   |   |                 |                             | DATE                  | APPROVED BY:           |

C15 PART INSPECTION STANDARD (A)



PART NAME

13866 4 DOOR TRUCK TANK FUEL ASSEMBLY

DATE: JUNE 20, 1996

PROPOSED BY: KEVIN FORTH

CHECKED BY: J. Pappert 3-13-97

APPROVED BY: [Signature] 3/14/97

MODEL: 4 DOOR GAS TANK

ENG CHARGE NUMBER: 60A-9380 (CAMI ECN) 06/12/96


SUPPLIER NAME: PRINCE METAL PRODUCTS

BUIS NUMBER: 247850542

SUPPLIER DATA should be supplied to CAMI on the items marked. Data is due at CAMI by the 10th day of the following month. Data frequency of checks as follows:

- 1/ (A) Items - each lot
- 2/ (C) Items - each lot
- 3/ (F) Items - 1 per month
- 4/ (X) Items - 1 per month

Inspection data should be formatted chronologically so the movement in the process can be predicted.



7-4-C Page 12/12

| REASONS FOR REVISION                   |  | AUTHORITY    | DATE     | CHECKED BY: | APPROVED BY: |
|--|--|--------------|----------|-------------|--------------|
| PUMP CHANGE FROM 2401-1233 TO 24018726 |  | 60FD TAG54PT | 04/22/96 |             |              |
| NEW SUSSET P/N 20012611                |  | 60FD TAG54PT | 06/20/96 |             |              |
| NEW ECU 2401 SENSOR CHANGE             |  | 60FD TAG54PT | 02/07/97 |             |              |

AS 280010

|   |     |   |           |
|---|-----|---|-----------|
| Engineering Change Level: Y19-1315  |     | SUPPLIER NAME: P.N.P.   |           |
| Part Number: 30014813 (89019-57830)   |     | DUNS #: 247650542   |           |
| Part Classification: A PART   |     | Part Name: TRUCK FUEL TANK ASSEMBLY (4 DOOR)  |           |
| A PART  |     | Functional: <input type="checkbox"/> Functional <input checked="" type="checkbox"/> General |           |
| Manager, Quality Control (Submitted By)   |     | Manager, Sales (Submitted By)   |           |
| Signature: <i>J. Taggart 3-15-94</i>  |     | Signature: <i>Peter Lee</i>   |           |
| Complete the following by referring to Section 2:   |     |   |           |
| 1. CIS/CONTROL PLAN   | YES | NO  | DATE      |
| 2. CANI CORRECTIVE ACTION   | Y   |   | 03/16/94  |
| 3. INSPECTION/PROCESS STANDARDS   | N/A |   | NOT REQ'D |
| 4. Dies/Moulds  | Y   |   | 03/16/94  |
| 5. Jigs/Fixtures  | Y   |   |           |
| 6. Process  | Y   |   |           |
| 7. Facility   | Y   |   |           |
| CANI Decision: <input checked="" type="checkbox"/> Accept <input type="checkbox"/> Reject |     |   |           |
| Date: 03/22/94  |     |   |           |
| Comments: Tank cover + lower KD supplied  |     |   |           |
| Comments:   |     | Quality Control: <i>J.P. 03/22/94</i>   |           |
|   |     | Purchasing: <i>J.P. 03/22/94</i>  |           |

1. Object: is document outlines CANI'S procedure for requesting Final Part Approval". It's purpose is to clarify the Part Approval procedure and the Quality Standards.
2. Scope: Supplier should determine which Part number requires this confirmation procedure. Prior to submission of this document, each product must meet the following conditions:
  1. Product must meet all dimensional and functional quality requirements as specified on prints, BSF's, CIS etc.
  2. All corrective actions requested by CANI for quality improvement must be complete.
  3. Inspection Standards and Process Control Standards are to be complete and submitted to CANI.
  4. Dies, jigs, process and facility are fully prepared for mass production.

- This document shall not be submitted unless all the conditions noted above are satisfied!
3. When to Report: Time to be determined by the supplier. It must be submitted prior to mass production.
  4. How to Report: Complete the attached form and submit the original to Cani.
  5. Send to: Quality Control Department, CANI Automotive, Inc.
  6. Approval: After this document has been submitted to CANI, it will be reviewed in conjunction with results from Joint Inspection and the review of the supplier's production process. A copy will then be returned to the supplier.

Note: Corrective measures shall be taken in consultation between CANI and the supplier to address all quality problems which may occur at CANI and in the market following the Final Part Approval.

Supplier: CANI O.C. Purchasing (Original) Supplier (copy) CANI O.C. (copy)

*h/94*



1. Objective This document outlines CAMI'S procedure for requesting "Final Part Approval". Its purpose is to clarify the Part Approval procedure and the Quality Standards.
2. Scope Supplier should determine which Part number requires this conformation procedure. Prior to submission of this document, each product must meet the following conditions:
  1. Product must meet all dimensional and functional quality requirements as specified on prints, QSP's, CIS etc.
  2. All corrective actions requested by CAMI for quality improvement must be complete.
  3. Inspection Standards and Process Control Standards are to be complete and submitted to CAMI.
  4. Dies, jigs, process and facility are fully prepared for mass production.

- This document shall not be submitted unless all the conditions noted above are satisfied:
3. When to Report Time to be determined by the supplier. It must be submitted prior to mass production.
  4. How to Report Complete the attached form and submit the original to Cami.
  5. Send to Quality Control Department, CAMI Automotive, Inc.
  6. Approval After this document has been submitted to CAMI, it will be reviewed in conjunction with results from Joint Inspection and the review of the supplier's production process. A copy will then be returned to the supplier.

**Note** Corrective measures shall be taken in consultation between CAMI and the supplier to address all quality problems which may occur at CAMI and in the market following the Final Part Approval.

|   |     |                                |      |
|---|-----|--------------------------------|------|
| Engineering Change Level: CAMI ECH 56B-2445   |     | SUPPLIER NAME: P.M.F.          |      |
| Part Number: 30019612 (89019-57863)   |     | DUNS #: 247650542              |      |
| Part Classification: <u>  </u> A Part <u>  </u> E Part <u>  </u> Functional <u>  </u> General <u>  </u> I General |     | Part Name: 4 DR TRUCK GAS TANK |      |
| Signature: <i>J. Toppert</i> 8-15-96  |     | Signature: <i>[Signature]</i>  |      |
| Manager, Quality Control (Submitted By)   |     | Manager, Sales (Submitted By)  |      |
| Complete the following by referring to Section 2:   |     |                                |      |
|   | YES | NO                             | DATE |
| 1. CIS/CONTROL PLAN   | I   |                                |      |
| 2. CAMI CORRECTIVE ACTION   |     |                                |      |
| 3. INSPECTION/PROCESS STANDARDS   |     | I                              |      |
| 4. Dies/Moulds  | I   |                                |      |
| 5. Jigs/Fixtures  |     |                                |      |
| 6. Process  | I   |                                |      |
| 7. Facility   | I   |                                |      |
| CAMI Decision <u>  </u> Accept <u>  </u> Project <u>  </u>  |     | Date: 8/19/96                  |      |
| Comments:   |     |                                |      |
| Quality Control   |     | Purchasing                     |      |
| Signature: <i>[Signature]</i>   |     | Signature: <i>[Signature]</i>  |      |

Supplier to CAMI B.C. to Purchasing (Original) to Supplier (copy)  
 CAMI B.C. (copy) 8/19/96  
*[Handwritten initials]*

THE  
NARMCO  
GROUP

CORPORATE  
OFFICE:

2575 AIRPORT ROAD, WINDSOR, ONTARIO N9W 1Z4 CAN. (519) 969-3350 U.S. (313) 982-3431 TELEFAX (519) 969-0083

TRANSMITTAL COVER SHEET

DATE: 05/25/95

TO: ATTENTION: Mr. Marcus Johnston DEPT./LOC. CCC

FAX NO.: 3130 NO. OF PAGES (INCL. COVER SHEET) (1)

FROM: NAME/DEPT: Peter Angermann DIRECT PHONE: (519) 969-3350

MESSAGE: Dear Marcus...

As per our previous discussion we are ready for your visit to PMP to discuss any and all open issues pertaining to the 2 and 4 door fuel tank "Top Dress" and, more specifically, those issues relevant to the "P" sensor.

Sample topics for discussion as follows:

- what are component requirements for receiving, inspection, certification, etc.
- What are required specifications for the "Top Dress" i.e. torques, alignments etc. (We still do not have assy. drawings).
- 'P' sensor - Test and paint issues. i.e. IF it is not feasible to assemble prior to paint then what are the requirements for assy. and testing after paint. - Can we arrange studies? i.e. full assy & test before paint. - Also... "EVAP II" standards.
- Anything which concerns you.

This will be a casual meeting. Attending will be myself, Mr. Go Taggart, Mr. Steve Fauscy, Ms. Maria Dupuis. It would be greatly appreciated if you could bring us the relevant assembly drawings. So far we are looking at the date of Thursday June 1 1996 @ 10.00 AM @ PMP. If you have a problem with this date please advise and we will adjust accordingly. Thank you Marcus.

DIRECT RESPONSE TO: Any questions please call.

Regards Peter A.

PAINTING • ASSEMBLY NARMCO WELDING • FUEL TANKS  
Associate



PHONE: 519-977-7523  
FAX: 519-977-6686



PHONE: 519-977-5381  
FAX: 519-977-0996

AS 280013

MEETING REPORT

8-2

TOPIC: NARMCO PMP 1996 TANK ASSY

Issued By: M. JOHNSON  
Checked By: [Signature] 12/95  
Approved By: [Signature] 1/95

Issue Date: 06.02  
Meeting Date: 06.01  
Time: 11:00 to 1:00  
Place: PMP

Attendants DAVE ASHMAN, PETER ANGERMAN, STEVE FANNEY, ERIC KAUZS,  
GORD TAGGART, M. JOHNSON

Contents

1. INSTALLATION OF P SENSOR IN YF9 TANK PER Y09-1282.  
NARMCO RESPONSIBILITY/LIABILITY FOR P SENSOR  
P SENSOR IS CONSIGNED THROUGH NISSHO. RESPONSIBILITY FOR DESIGN AND MANUFACTURING OF P SENSOR RESTS WITH CAMI (AS FAR AS THE RELATIONSHIP BETWEEN NARMCO & CAMI IS CONCERNED). NARMCO IS RESPONSIBLE FOR:
  - ① EXAMINING CONTAINERS/CARTONS FOR DAMAGE PRIOR TO TAKING RECEIPT OF SHIPMENT
  - ② HANDLING PARTS WITH PROPER CARE TO PREVENT DAMAGE DURING THE ASSEMBLY PROCESS. IN PARTICULAR, MEASURES NECESSARY TO PREVENT DROPPING OF PARTS AND QUANTITING OF DROPPED PARTS.
  - ③ MANUFACTURING PROCESS CONTROL NECESSARY TO PREVENT DAMAGE/CONTAMINATION OF THE P SENSOR DURING ASSEMBLY AND LEAK TESTING
  - ④ PROVIDING A LEAK FREE, CONTAMINANT FREE, FULL TANK ASSEMBLY TO CAMI.NARMCO IS NOT RESPONSIBLE FOR:
  - ① RECEIVING INSPECTION EXCEPT AS NOTED IN ① ABOVE.
  - ② FUNCTIONAL TESTING OF ANY KIND EXCEPT LEAK FREE CONDITION AFTER SUB ASSEMBLY. NARMCO IS PROHIBITED FROM PERFORMING ELECTRICAL TESTING OF P SENSOR FUNCTION EXCEPT AS MAY BE SPECIFICALLY DIRECTED BY CAMI.
2. P SENSOR IS TO BE INSTALLED AFTER PAINTING FOR SOP 96. IN FUTURE STUDIES MAY BE CONDUCTED TO DETERMINE WHETHER THE P SENSOR COVER WILL ALLOW SENSOR INSTALLATION PRIOR TO PAINTING.  
A LEAK TEST MUST BE PERFORMED AFTER SENSOR INSTALLATION. TEST MAY VERIFY THE ENTIRE ASSEMBLY (FULL IMMERSION) OR ONLY THE P SENSOR AREA. WHICH METHOD IS EMPLOYED MAY BE DECIDED BY NARMCO, SUBJECT TO CAMI

Opinions  
MUCH OF THIS MEETING WAS DEVOTED TO LIABILITY ARISING FROM NARMCO INSTALLATION OF CONSIGNED PARTS.

Circulation: \_\_\_\_\_ Copy To: AS 280014  
PURCHASING

MEETING REPORT

8-2

TOPIC: \_\_\_\_\_

Issued By: \_\_\_\_\_

Issue Date: \_\_\_\_\_

Checked By: \_\_\_\_\_

Meeting Date: \_\_\_\_\_

Approved By: \_\_\_\_\_

Time: \_\_\_\_\_ to \_\_\_\_\_

Place: \_\_\_\_\_

Attendants \_\_\_\_\_

Contents

APPROVAL.

3 DRAWINGS FOR -65A AND -57B10 FUEL TANK SUB ASSEMBLIES PROVIDED.  
WORK ON THIS PROJECT IS NOT SUFFICIENTLY ADVANCED FOR  
SOP 96 START. SSR FOR -65A IS NOT YET APPROVED.

4. CEL HOUSING ASSEMBLY FOR A4LE BUILD OUT IS 06-09. LAST SHIPMENT  
SHOULD BE 06-17. LINES WILL REMAIN INTACT FOR 15-30 DAYS

Opinions

Circulation:

Copy To:

AS 280015

96My J 72-216707 に 7112. (Pc=9 組付け)

1 96My から J 413 の 72-216707 に Pc=9 を付く

その仕入れ元 (PMP) と 責任分担, 検査方法等 に 7112 打ち合せした

PMP の 責任範囲項目

① コーナ, 箱 に キズ, シビレ, 変色, 変形 等

② 箱 から Pc=9 を取り出し, タ:7 に 組み付けられた工程で

Pc=9 を 落とすこと, シビレを 与えること

③ タ:7 の 組付け時 及び リ:7 終了時 に Pc=9 に シビレ

を 与えること

④ 組付け後, リ:7 の 無... こと

PMP の 責任範囲以外項目

① 受け入れ検査 (① 上記以外)

② 機能検査 (Pc=9 の 作動チェック 等)

2. Pc=9 は タ:7 の 塗装後 に 組み付けられた

・ リ:7 終了時, Pc=9 組み付け後, 必ず 実施すること

方法は, フラット同様に リ:7 終了後 OK

以上

THE NARMCO GROUP

8-3

CO... ORATE OFFICE: 2575 AIRPORT ROAD, WINDSOR, ONTARIO N9W 1Z4 CAN. (519) 868-3360 U.S. (313) 643-8418 TELEFAX (519) 868-0069

TRANSMITTAL COVER SHEET

CAREY BARTA

DATE: 6-9-95

TO: ATTENTION: MARCUS JOHNSON DEPT./LOC. P.C. ASSEMBLY

FAX NO.: 1-519-425-3139 NO. OF PAGES (INCL. COVER SHEET) 1

FROM: NAME/DEPT: G. TAGGART DIRECT PHONE:

MESSAGE:

MARCUS.

WE ARE SENDING 2 RACKS OF 12 TANKS EACH OF 2 DOOR AND 4 DOOR FUEL TANKS WITH TOP DRESS. THE 4 DOOR TANKS ARE IN NEW RACK WHICH CAREY NEEDS TO REVIEW. MATERIAL WILL ARRIVE AT DOCK 'J3' AT 7:00 P.M. THIS DATE.

G. Taggart

DIRECT RESPONSE TO:

PAINTING • ASSEMBLY NARMCO WELDING • FUEL TANKS



PHONE: 519-977-7323 FAX: 519-977-6686



PHONE: 519-977-5381 FAX: 519-977-0996

AS 280017

# CAMI Automotive Inc.

Quality Assurance Department

1/2  
8-4 page 1/2

From: M. JONNSTON

Q.C. Fax #: (519) 425-3130

Telephone: (519) 425-3127

Ext.: 4838

Date: 06.13.95

To: GORD TAGGART

Company: PMP

# of pages  
(including cover) 2

Fax #: \_\_\_\_\_

TRIAL SHIPMENT OF SUBASSEMBLED FUEL TANKS.

GENERALLY THE PARTS SHIPPED WERE PRETTY GOOD,  
HOWEVER THERE WAS CONSIDERABLE VARIATION FROM  
TANK TO TANK.

1 ALL CLIPS AND HOSE CLAMPS SHOULD BE MARKED  
RED

2 ALL CLIPS FACE UPWARD. ON SOME TANKS, THE  
SUB ASSEMBLED VALVE ZWAY CHECK AND HOSES WERE  
INSTALLED ON THE TANK WITH THE CLIPS FACING  
DOWN

AS 280018

3. PE COAT ON CLIP 09401-11412 WAS DAMAGED DURING  
ASSEMBLY. SOME OF THESE CLIPS WERE BADLY DISTORTED


3. CAN'T BY ASSEMBLY TOOLS BEING SQUEEZED TOO TIGHT.

4. TIGHTENING TORQUE FOR RETURN HOSE GEAR CLAMP

(SHORT BODY TANK) IS 15N 25 Kgf.cm. CLAMPS SUPPLIED WERE A LITTLE TIGHT.

5. CLAMPING OF RETURN HOSE UNDER SEPARATOR

- MAINTAIN 306mm GAP AS SHOWN



6. UNUSED CLIPS SHOULD BE SET ON THE HOSE

25N 35 mm. SOME ASSEMBLIES HAD CLAMPS ON 60mm OR MORE.



# CAMI Automotive Inc.

Quality Assurance Department

1/2  
8-4 page 1/2

From: M. JONNISON

Q.C. Fax #: (519) 425-3130

Telephone: (519) 425-3127

Ext.: 4838

Date: 06.13.95

To: GORD TAGGART

Company: PMP

# of pages  
(including cover) 2

Fax #: \_\_\_\_\_

TRIAL SHIPMENT OF SUB ASSEMBLED FUEL TANKS.

GENERALLY THE PARTS SHIPPED WERE PRETTY GOOD,  
HOWEVER THERE WAS CONSIDERABLE VARIATION FROM  
TANK TO TANK.

1 ALL CLIPS AND HOSE CLAMPS SHOULD BE MARKED  
RED

2 ALL CLIPS FACE UPWARD. ON SOME TANKS, THE  
SUB ASSEMBLED VALVE ZWAY CHECK AND HOSES WERE  
INSTALLED ON THE TANK WITH THE CLIPS FACING  
DOWN

AS 280020

3. PE COAT ON CLIP 09401-11412 WAS DAMAGED DURING  
ASSEMBLY. SOME OF THESE CLIPS WERE BADLY DISTORTED


3. CONT. BY ASSEMBLY TOOLS BEING SQUEEZED TOO TIGHT.

4. TIGHTENING TORQUE FOR RETURN HOSE GEAR CLAMP

(SHORT BODY TANK) IS 15 ~ 25 kgf/cm. CLAMPS SUPPLIED WERE A LITTLE TIGHT.

5. CLAMPING OF RETURN HOSE UNDER SEPARATOR

- MAINTAIN 306mm GAP AS SHOWN



6. UNUSED CLIPS SHOULD BE SET ON THE HOSE

25 ~ 35 mm. SOME ASSEMBLIES HAD CLAMPS ON 60mm OR MORE.

# CAMI Automotive Inc.

8-5 page 1/1

## Quality Assurance Department

From: M. JOHNSON

Q.C. Fax #: (519) 425-3130

Telephone: (519) \_\_\_\_\_

Ext.: 4838

Date: 08.08 (95) <sup>MB 06.01.97</sup> To: GORD TAGGART

Company: PMP

# of pages (including cover) 1 Fax #: \_\_\_\_\_

FUEL TANK SET J SHORT BODY

LOT 5-2-212

JULY 31

SHIFT 2 CLOCK # 422, 421

M8x1.25 BOLT USED TO SECURE PROTECTION

TO TANK IS LOOSE (TORQUE SPEC 180-280K)

TANKS WITH 421 AND 422 ARE NG.

PLEASE CHECK YOUR STOCK. THIS IS NOT

(A) AND DOES NOT REQUIRE 100% LIMIT

WRENCH CHECK IN PROCESS, HOWEVER, AIR

TOOLS MUST BE CHECKED REGULARLY

*[Signature]* AS 280022

# CAMI Automotive Inc.

## Quality Assurance Department

1/10

8-6

From: M. Jansson

Q.C. Fax #: (519) 425-3130

Telephone: (519) \_\_\_\_\_

Ext.: 4838

Date: 07-27

To: Good Taggart

Company: PMP

# of pages  
(including cover) 1

Fax #: \_\_\_\_\_

In an earlier fax to Peter Angerman  
I described the orientation of the  
Valve Comp Fuel Tank Inlet (89280-50F0)

My description was incorrect - hinge

line should be horizontal, not

vertical as I indicated previously



— HORIZONTAL

PLEASE MODIFY ASSEMBLY INSTRUCTIONS

*my-LD* AS 280023

# CAMI Automotive Inc.

8-6

2/10

## Quality Assurance Department

From: MI JOHNSON -Q.C. Fax #: (519) 425-3130

Telephone: (519) \_\_\_\_\_ Ext.: \_\_\_\_\_


Date: 07-20 To: Peter Angerman

Company: NAMCO

# of pages (including cover) \_\_\_\_\_ Fax #: \_\_\_\_\_


ANSWERS TO YOUR QUESTIONS RE J-4 FUEL TANK SUB

① CLIP IS CORRECT - GEAR CLAMP IS ONLY USED ON 2 DR.

② ORIENTATION  SET VISUALLY

③ P SENSOR ORIENTATION  $\pm 2$  DEGREE IS OK PROVIDED MOUNTING PLATE IS CORRECTLY ORIENTED TO FUEL TANK.

PLEASE KEEP CAMI ADVISED OF P SENSOR LEAK CONDITION.



AS 280024

THE NARMCO GROUP

CORPORATE OFFICE: 2575 AIRPORT ROAD, WINDSOR, ONTARIO N9W 1Z4 CAN. (519) 869-3350 U.S. (513) 862-3432 TELEFAX (519) 869-0063

TRANSMITTAL COVER SHEET

DATE: 07/19/95


TO: ATTENTION: MR MARCUS JOHNSTON DEPT./LOC. QUALITY ASSURANCE!
FAX NO.: (519) 425-3130 NO. OF PAGES (INCL. COVER SHEET) 2
FROM: NAME/DEPT: PETE ANGERMANN DIRECT PHONE: (519) 977-5333

MESSAGE: Re: A DR FUEL TANK "TOP DRESS" (START UP ISSUES - TWEAKING)

MARCUS...

We are just now getting into the actual "top dresses" and testing of the 4 DR tank. We have several questions which need your input. They are as follows:

- 1 FUEL PUMP HOSE CONNECTION - our Cam built sample tank shows the use of a spring clip. On the 2 dr version we are using the TRIDON GEAR CLAMP. Is the spring clamp correct? YES
2 VALVE COMP FUEL TANK - P/N 89280-50 F00 (30016208) is orientation of internal "flap" valves critical. If so what is the correct position?
3 P-SENSOR - The orientation of our connector ring and P-sensor is not quite perpendicular to end of tank or parallel to side of tank. (By about 1 or 2 degrees) Is this acceptable or should it be dead nuts 90°?



DIRECT RESPONSE TO:

PAINTING • ASSEMBLY • NARMCO ASSOCIATE • WELDING • FUEL TANKS

CONTD



PHONE: 519-977-7523 FAX: 519-977-6686



PHONE: 519-977-5381 FAX: 519-977-0096

AS 280025

8-6

4/10

④ Because we mask off the P-SENSOR ring for paint and later mount the P-sensor the ring is not fully coated (and ugly) Should we worry about this and re-touch or is it acceptable as is?

These are the only questions which we have Marcus. We are looking forward to your prompt input,

THANK'S.

Pete

AS 280026

THE NARMCO GROUP

PORTAGE OFFICE: 2578 AIRPORT ROAD, WINDSOR, ONTARIO N9W 1Z4 CAN. (519) 938-3350 U.S. (313) 982-3432 TELEFAX (519) 968-0063

TRANSMITTAL COVER SHEET

DATE: 7/17/95

TO: ATTENTION: Marcus Johnston DEPT./LOC. Quality Control

FAX NO.: 1-519-425-3330 NO. OF PAGES (INCL. COVER SHEET) 3

FROM: NAME/DEPT: Gord Taggart DIRECT PHONE: (519) 977-5333

MESSAGE: Please see attached documents!

DIRECT RESPONSE TO:

PAINTING • ASSEMBLY NARMCO Associate WELDING • FUEL TANKS



PHONE: 519-977-7523 FAX: 519-977-6686



PHONE: 519-977-5361 FAX: 519-977-0996



AS 280027



8-6

6/10

July 17, 1995

RE: 2 DOOR 95 MODEL YEAR GAS TANK

DEAR MARCUS,

Enclosed please find our 2 door top dress component listing for your approval. Without an updated print, we have enclosed the updated GM and Suzuki number provided by Cami. I would be most grateful for your written approval should you agree with our component listing and diagram.

Thank you for your time and effort.

  
Ward Taggart

AS 280028

# TOP DRESSING COMPONENTS 30018475

(86) (7) / 10

F/N 30018475 (89019-65A31) - 2 DOOR FUEL TANK B.P. REFER TO NARMCO PCR DATED 06/05/95 E.C.N. Y09-1831


| NO. | PART #                     | QTY | PARTNAME                               |
|-----|----------------------------|-----|--|
| 1   | 30018475 (89109-65A33)     | 1   | TANK SET FUEL                          |
| 2   | 15810-57B00                | 1   | HOSE COMP FUEL (FILTER INLET -CAMI)    |
| 3   | 96059598 (15864-61A00)     | 1   | HOSE COMP RETURN PIPE TO PUMP          |
| 4   | 96052867 (85451-75100)     | 1   | VALVE 2 WAY CHECK                      |
| 5   | 96059438 (89280-60A00)     | 1   | VALVE COMP FUEL TANK INLET             |
| 6   | 30004113 (89320-60AA0)     | 1   | PROTECTOR COMP, FUEL TANK              |
| 7   | 30000732 (89411-60A01)     | 1   | SEPARATOR FUEL AND EVAPO               |
| 8   | 96061879 (89485-60A00)     | 1   | CLAMP, CHECK VALVE                     |
| 9   | 30000023 (02142-05083)     | 2   | SCREW, FUEL & EVAPO SEPARATOR          |
| 10  | 96053512 (02112-05083)     | 2   | SCREW, CHECK VALVE                     |
| 11  | 30000061 (09354-54115-100) | 1   | HOSE, CHECK VALVE TO TANK EVAPO        |
| 12  | 30014822 (09354-54115-140) | 3   | HOSE                                   |
| 13  | 30000064 (09354-54115-125) | 1   | HOSE, SEPARTATOR TO TANK EVAPO         |
| 14  | 96057808 (09401-11412)     | 2   | CLIP                                   |
| 15  | 96061880 (09401-11413)     | 8   | CLIP                                   |
| 16  | 30015674 (09402-15511)     | 1   | CLAMP FUEL RETURN PIPE                 |
| 17  | 96054836 (09118-08128)     | 1   | BOLT WITH 1 LOCK WASHER & 1 WASHER NUT |
| 18  | 30011183 (08316-20083)     | 1   | NUT                                    |

APPROVED BY: *m.j.t.* 07.26.95

Marcus Johnson  
Camí Specialist

Gord Taggart  
PMP Quality Manager

Steve Fancsy  
PMP Plant Manager



FILE: LISTING

AS 280029

8-6

8

THE NARMCO GROUP

CORPORATE OFFICE: 2575 AIRPORT ROAD, WINDSOR, ONTARIO N8W 1Z4 CAN. (519) 869-3350 U.S. (313) 962-3492 TELEFAX (519) 869-0063

TRANSMITTAL COVER SHEET

DATE: 11-25-94

TO: ATTENTION: MARCUS JOHNSON DEPT./LOC. P.C. ASSY
FAX NO.: 1-425 3130 NO. OF PAGES (INCL. COVER SHEET) 3
FROM: NAME/DEPT: G. TAGGART DIRECT PHONE:

MESSAGE:

MARCUS.

CURRENT 2 DR. FUEL TANK ASSEMBLY UTILIZES A VESSEL ASSY PT. NO. 89170-61A00. A PART LISTING CHANGE COPY ATTACHED HAS BEEN CHANGED TO ALLOW COMMONIZATION WITH 4 DR FUEL TANK VESSEL PT. NO 89170-56B00. WE HAVE INITIATED BUILD OF FUEL TANK ASSEMBLY 30010248 WITH THIS VESSEL. PARTS WILL BE IDENTIFIED WITH A PINK TAG.

[Handwritten signature]

DIRECT RESPONSE TO:

PAINTING • ASSEMBLY NARMCO Associate WELDING • FUEL TANKS



PHONE: 519-977-7523 FAX: 519-977-6686



PHONE: 519-977-5381 FAX: 519-977-0996

AS 280030





8-6 10/04/004

# VA ENGINEERING CHANGE REQUEST

CAMI Automotive Inc. Program Management - ECR - 005 09/24/92 Please PRINT clearly in BLOCK LETTERS.

ECR NO. PROGRAM MANAGEMENT  
ECR -

|   |  |   |   |
|---|--|---|---|
| <b>J/MII/MII</b>  |  | <b>PART NUMBER</b><br>3 0 0 1 0 2 4 8 L/KD<br>8 9 1 0 9 - 6 5 A 3 2 -   | <b>PART NAME</b><br>FUEL TANK ASSEMBLY - 2 DOOR |
| <b>BRIEF DESCRIPTION OF CHANGE</b><br>TO ELIMINATE CURRENT 3 PC ASSEMBLY<br>WITH 2 PC 1995 VESSEL OF 4 DR.  |  | <b>SUPPLIER</b> P.M.P.<br><b>BUYER</b> G. TAGGART<br><b>DATE:</b> 09/20/94  | <b>BUYER</b><br>DATE<br>MANAGER<br>DATE         |
| <b>REASON FOR CHANGE</b><br>1. IMPROVE PERFORMANCE / RELIABILITY<br>2. COST REDUCTION<br>3. COMMODITIZATION / STANDARDIZATION<br>4. OTHERS  |  | <b>COST: US\$ / CONS / YEN</b><br>+/-   | <b>PERVEHICLE</b><br>-----<br>PERVEHICLE        |
| <b>DETAILS OF CHANGE AND DETAILED SKETCH INCLUDING AFFECTED MODELS.</b><br>(PLEASE INCLUDE ADDITIONAL DOCUMENTS SUCH AS DRAWINGS AS REQUIRED)<br>PLEASE WRITE BOTH IN ENGLISH AND JAPANESE. |  | <b>TOOLING / INVESTMENT</b><br>US\$ / CONS / YEN<br>+/-   | <b>REQUESTOR'S REF. NO.</b>                     |
| <b>PRESENT CONDITION</b><br>6 INDIVIDUAL COMPONENTS.  |  | <b>PROPOSED CONDITION</b><br>5 INDIVIDUAL COMPONENTS  |   |
|   |  |   |   |
| <b>PROGRAM MANAGEMENT</b><br>(YES/NO) <input checked="" type="checkbox"/>   |  | <b>Tooling Cost Responsibility</b> <input type="checkbox"/> CAMI <input type="checkbox"/> Suzuki <input type="checkbox"/> CPC <input type="checkbox"/> MCR (YES/NO) |   |
| <b>Adoption</b> YES / NO / EVALUATING   |  | <b>ENG. CHANGE NO.</b>  |   |
| <b>Comments</b>   |  | <b>AS 280032</b>  |   |
| <b>Examiner</b>   |  | <b>Manager</b>  |   |
| <b>Date</b>   |  | <b>Date</b>   |   |

2DR - 89172-61A00

4DR - 89172-56800



May 12, 1997

Enid Rubenstein  
Acting Assistant Chief Counsel for Litigation  
National Highway Traffic Safety Administration  
400 Seventh Street, S.W.  
Washington, D.C. 20590

Re: NCC-10 ZTV  
IR 1711

Dear Ms. Rubenstein:

This letter responds to your Civil Penalty Notice Letter dated March 20, 1997, pertaining to a voluntary recall undertaken in 1996 by Suzuki and General Motors Corporation of certain Sidekick/Tracker models manufactured by CAMI Automotive Inc. (CAMI) (Recall Identification Nos. 96V121 and 96V121.002). The voluntary recall was undertaken in response to an apparent noncompliance with FMVSS 301 observed by NHTSA in a Geo Tracker tested at Calspan for NHTSA on May 17, 1996.

CAMI appreciates this opportunity to explain why it did not, in the exercise of reasonable care, have reason to know that the Sidekick/Tracker model might not comply with FMVSS 301. CAMI therefore submits that, under the circumstances described in this letter, there has been no violation by CAMI of Chapter 301 of Title 49 of the United States Code, and therefore that a civil penalty in this case is not warranted.

As explained in more detail in the August 12, 1996 response of General Motors to NHTSA's information request (IR 1711 JJo), CAMI is a joint operation between Suzuki Motor Corporation (Suzuki) and General Motors Corporation (GM). Suzuki had the responsibility for assuring the compliance of the Sidekick/Tracker with the requirements of all applicable Federal Motor Vehicle Safety standards, including FMVSS 301.

**A. SUZUKI'S CERTIFICATION TESTING WAS EXTENSIVE, AND CAMI REASONABLY RELIED ON IT.**

Suzuki conducted extensive certification testing of the Sidekick/Tracker to evaluate and confirm its compliance with FMVSS 301, including several crash tests at speeds significantly higher than 30 mph. A list of the certification tests and related testing was provided as

Enid Rubenstein  
May 12, 1997  
Page 2

Attachment 1 to the General Motors letter to NHTSA dated August 12, 1996; for your convenience, another copy is attached to this letter as Attachment 1. Suzuki specifically undertook to confirm the continued compliance of the Sidekick/Tracker with FMVSS 301 after upgrading the fuel tank attachment bracket in 1995 to account for the increased curb weight of the vehicle caused by the added weight of newly provided airbag and antilock brake systems. Suzuki confirmed the compliance of the Sidekick/Tracker in two separate certification tests — Test 75-292, conducted at 33.7 mph, and test 76-161, conducted at 35 mph. Suzuki's confidence in the compliance of the Sidekick/Tracker was further assured in Test 77-011<sup>1/</sup>, a high-speed car-to-car test conducted at 49.4 mph, in which the rear of a Sidekick/Tracker equipped with the modified fuel tank attachment bracket was impacted by a heavier vehicle -- a Toyota Crown, which is approximately the size of a General Motors A-Car. There was no fuel tank leakage in the Sidekick in that test, either.

Suzuki provided this information to CAMI, and CAMI relied on this certification testing to form the basis for its certification of compliance with FMVSS 301. We believe that CAMI's reliance on Suzuki's test data was reasonable, both due to the extensiveness of the successful testing and due to Suzuki's excellent record of compliance with FMVSS 301 in the past.

**B. SUZUKI HAD NO REASON TO ANTICIPATE THE NHTSA TEST RESULT.**

To CAMI's knowledge, there has never been an FMVSS 301 test obtaining a noncompliant result on a Sidekick or a Tracker, other than NHTSA's single test. CAMI has confirmed that, throughout Suzuki's fuel tank integrity tests on vehicles intended for production, including tests at speeds incorporating far more energy than required by FMVSS 301, Suzuki never observed fuel tank leakage in a Sidekick/Tracker.

Nor could Suzuki reasonably have predicted the NHTSA result on the basis of the function or location of the gusset that apparently punctured the fuel tank wall in the NHTSA test. The function of the gusset is solely to reinforce the flange at the mounting bolt location. It is permanently welded to the underside of the flange. On a new (off the shelf) fuel tank assembly the gusset does not touch the fuel tank wall at any place. Thus, Suzuki had no reason to consider the potential separate contribution of the gusset to the risk of FMVSS 301 noncompliance. Furthermore, neither Suzuki nor General Motors have received warranty

---

<sup>1/</sup> CAMI wishes to take this opportunity to correct a typographical error in GM's August 12, 1996 submission, which identified this test as "Test 77-071." As a result of this typographical error, NHTSA's public file also refers to this car-to-car test as "Test 77-071," however, it is correctly identified as Test 77-011.

AS 280034

Enid Rubenstein  
May 12, 1997  
Page 3

claims, consumer complaints or lawsuits alleging post-collision fuel tank leakage in the subject vehicles.

**C. IT IS HIGHLY UNLIKELY THAT SUZUKI WOULD HAVE REPLICATED THE NHTSA TEST RESULTS IN ANY REASONABLE AMOUNT OF ADDITIONAL TESTING.**

In the NHTSA test, an unusual confluence of circumstances combined to induce the apparent noncompliance -- first, post-test examination of the vehicle tested by NHTSA confirmed that the right side of the right-hand reinforcement gusset separated from the flange to which it had been attached and the welding pitch was relatively shorter than expected. Second, although the initial orientation of the reinforcement gusset could not be confirmed after the NHTSA test, Suzuki's static testing confirmed that the gusset would have to have been substantially misaligned to have induced the fuel tank wall puncture observed in the NHTSA test.

As noted in subsection B. above, to CAMI's knowledge, neither NHTSA nor Suzuki has replicated the results of the May 17, 1996 NHTSA test. None of Suzuki's extensive certification tests resulted in fuel tank leakage, nor has any collision in the field corroborated the NHTSA results, to our knowledge.

After the NHTSA test, Suzuki and GM promptly began an investigation to determine the probable cause of the fuel tank wall puncture. Based on static bench tests, Suzuki confirmed that the only circumstance in which the post-collision deformation observed in the NHTSA test would result in a gusset-induced puncture of the fuel tank wall was the *combination* of two assembly conditions: significant gusset misalignment and narrow spot weld spacing. Suzuki's static tests showed that fuel tank wall puncture would not have occurred if the gusset had had only *one* of these "off nominal" attributes; the gusset would have to have had *both* a significant off-parallel orientation *and* narrow spacing of spot welds before fuel tank wall puncture would have been induced in the Suzuki static tests.

It may be useful to summarize briefly here the Suzuki static testing conducted as part of the 1996 investigation into the probable cause of the fuel tank wall puncture. At that time, Suzuki conducted static testing in which it simulated the fuel tank wall deformation observed in the NHTSA test vehicle with the gussets oriented in different positions and with different spot weld spacing. As NHTSA's investigative report correctly notes, the only condition in which the static test demonstrated the potential for fuel tank puncture was when the modified fuel tank attachment bracket was installed and when the reinforcement gusset was *both* substantially misaligned *and* when the gusset's spot welds were narrowly spaced. (Suzuki static test C-1). Although the NHTSA investigative report correctly defined the narrow spot weld spacing of the

AS 280035



spot welds as 40 mm apart, it did not define the misalignment of the gusset in test C-1, which was in fact measured at -9 mm. As illustrated on Attachment 4 to the GM letter of August 12, 1996, which is also appended to NHTSA's investigative report, the measurement of misalignment was made in the following manner: first, an imaginary straight line was drawn along the edge of the fuel tank wall from the left side corner of the gusset to the right side corner of the gusset. (As shown on the sketch at the top of Attachment 4, the fuel tank wall curves away from the rear of the vehicle slightly before the right side corner; therefore, the right end of the imaginary straight line does not touch the fuel tank wall at that corner.) Second, the distance from the right side corner of the right-hand reinforcement gusset was measured to the nearest point of the imaginary straight line (point "a"). Third, the distance from the left side corner of the right-hand reinforcement gusset was measured to the nearest point of the imaginary straight line (point "b"). Finally, the distance at "b" was subtracted from the distance at "a". The resulting value is the measurement of misalignment. If the resulting value was zero, the gusset was perfectly parallel to the fuel tank wall. If the resulting value was a positive number, the right side gusset was misaligned, but with the right side corner oriented away from the fuel tank wall -- in other words, a benign misalignment. Even though the left side corner is closer to the fuel tank wall in such a misalignment, this condition does not present a risk of puncture, because of the lack of fuel tank deformation on the in-board side of the gusset resembling the deformation seen on the outboard side in the NHTSA test. If, on the other hand, the resulting value was a negative number, the gusset was misaligned with its right corner toward the fuel tank wall -- which presented the possibility of contact with the fuel tank wall if the misalignment was substantial.

As part of the Suzuki-GM-CAMI investigation following NHTSA's May 17, 1996 test, CAMI conducted a survey of 50 fuel tank assemblies in the condition in which they were received from CAMI's fuel tank assembly vendor. The results of this survey confirmed that the orientation of most reinforcement gussets was perfectly parallel or within less than one millimeter of parallel. (As described above, if the misalignment value is measured to be one mm, this reflects the difference between the right corner and the left corner; however, each corner of the gusset is misaligned by only one-half mm from the parallel position.) Furthermore, the worst gusset orientation observed in these 50 fuel tanks was only -5 mm, substantially less than the -9 mm evaluated in Suzuki in static test C-1.

Suzuki recently conducted additional static testing to evaluate the potential contribution of different gusset misalignment measurements to the risk of fuel tank puncture. These tests were conducted in a manner identical to static test C-1, except that the gusset misalignment measurements were -8 mm, -5 mm, -3 mm and 0 mm. In these recent tests, Suzuki confirmed the results of static test C-1 with the gusset misaligned at -8 mm; that is, there was contact with the fuel tank wall that would likely have induced fuel tank puncture in a collision; however, with the gusset misaligned at -5 mm, there was only slight contact with the fuel tank wall, which

AS 280036

might or might not have induced a puncture in a real-world collision. And, at both -3 mm misalignment and at 0 misalignment (parallel), there was no contact with the fuel tank wall in the static test. Based on these results, Suzuki concludes that the risk of gusset-induced fuel tank puncture is slight with a misalignment at -5 mm, and nonexistent at -3 mm and below.

In the 50-tank survey, *none* of the surveyed tanks exhibited right-side gusset orientation measurements worse than -5 mm, and *only one* of the surveyed fuel tanks exhibited *both* an observed right-side gusset orientation measurement of -5 mm (as noted above, the minus sign indicates a misalignment with the right corner toward the fuel tank wall) *and* a right-side spot weld spacing of 20 mm from the center bolt. It is not clear that even this one "worst-case" tank in the 50-tank survey would have been punctured in a collision. In other words, had Suzuki tested 50 more vehicles containing these 50 fuel tanks, Suzuki would not likely have obtained a noncompliant result.

Thus, Suzuki could not reasonably have anticipated the NHTSA test outcome, without an unreasonable and impracticable number of additional compliance tests, if at all.

#### **D. CAMI'S MANUFACTURING AND QUALITY STANDARDS ARE HIGH.**

CAMI's internal quality standards in effect at the time that the subject Sidekick/Tracker models were manufactured provided that the gusset installation was to be performed by the vendor in such a manner that the edges were "line[d] up to the mating part", and that compliance with that instruction was to be confirmed by a visual inspection of 100% of the fuel tanks. The 50-tank survey confirmed that most gussets were, indeed, aligned parallel to the flange or within 1 mm of parallel. Furthermore, CAMI standards provided that the strength of the spot welds of the gusset was to be confirmed by subjecting 100% of the gussets to a test to confirm attachment.

Nonetheless, the NHTSA test result demonstrated the potential benefits of more specific quality control instructions for gusset installation. CAMI's internal standards now specify that the gusset shall be installed parallel to the flange within a specified maximum tolerance of 1.9 mm, with compliance to be verified by means of a measuring instrument. In addition, CAMI has now added a standard for spot weld location, specifying that the spot welds must be 70 mm apart, within a tolerance of no more than  $\pm 5.0$  mm, with compliance to be verified by means of a measuring instrument. These quality control improvements, coupled with the redesigned gusset described in GM's August 12, 1996 letter to the agency, should substantially reduce or eliminate the already remote chance of a gusset-induced fuel tank wall puncture.

**AS 280037**

Enid Rubenstein  
May 12, 1997  
Page 6

**E. GM AND SUZUKI COOPERATED FULLY WITH NHTSA'S  
INVESTIGATION AND RESPONDED PROMPTLY WITH  
CORRECTIVE ACTION.**

Notwithstanding the companies' surprise at the outcome of the NHTSA test, GM and Suzuki promptly conducted and concluded an inquiry into the probable cause of the NHTSA test result, leading to a decision to conduct a recall to reinforce the flange area within a few weeks of first being notified of the NHTSA test. The companies undertook this prompt recall to assure the safety of its customers, even though the field risk of gusset-induced fuel tank wall puncture is remote. CAMI urges NHTSA to take this prompt cooperation by GM and Suzuki into account in evaluating CAMI's compliance with Chapter 301.

\* \* \*

For reasons explained above, CAMI did not know, nor could it have known in the exercise of reasonable care, that the Sidekick/Tracker tested by NHTSA would fail to comply with FMVSS 301. The combination of circumstances shown to be necessary before the gusset will induce fuel tank wall puncture is extremely rare. Neither Suzuki nor GM had any indication from field collisions of the previously unanticipated contribution of the gusset's welding quality to the risk of fuel tank wall puncture. Under these circumstances, and in light of GM and Suzuki's prompt recall of the subject vehicles, CAMI respectfully submits that no violation of Chapter 301 of Title 49 of the United States Code has taken place and, therefore, that the imposition of any civil penalty in this matter would be unwarranted.

Sincerely,

*Sadayuki Hirano /ej*  
Sadayuki Hirano  
Director, Quality Assurance

AS 280038

Item #4

### RECALL CAMPAIGNS

|  |
|--|
| NAME OF MANUFACTURER : <u>SUZUKI MOTOR CORP.</u>   |
| SUBJECT OF RECALL : <u>EMYSS 301, "FUEL TANK INTEGRITY"</u>                                    |
| RECALL CAMPAIGN NUMBER : <u>96V-121.002</u>  |
| <b>ACTION THAT INFLUENCED RECALL</b>   |
| <b>MANUFACTURED INFLUENCED</b>   |
| ODI INFLUENCED:<br><br>ACTION NO. :<br><br>DED INVESTIGATOR :<br><br>RAD INVESTIGATOR :        |
| OVSC INFLUENCED:<br><br>ACTION NO. : <u>IR-1711</u><br><br>OVSC INVESTIGATOR : <u>J. JONES</u> |

AS 280039



AMERICAN SUZUKI MOTOR CORPORATION

July 2, 1996

Mr. Michael B. Brownlee  
Associate Administrator for Safety Assurance  
National Highway Traffic Safety Administration  
400 7th Street, S.W.  
Washington, D.C. 20590

96V-121,002 (01)

Dear Mr. Brownlee:

The following information is submitted in accordance with the noncompliance reporting regulations in Title 49 of the Code of Federal Regulations, Part 573.

1. Name of Manufacturer and Importers

Manufacturer: CAMI Automotive, Inc.

Importer: American Suzuki Motor Corporation

2. Identification of Vehicles Potentially Involved

1996 model year 4-door Suzuki Sidekick vehicles produced by CAMI Automotive, Inc. from August 1995 through June 1996.

3. Total Number of Vehicles Potentially Involved

4,325

4. Percentage of Vehicles Estimated to Contain the Noncompliance

Unknown

5. Description of Noncompliance

American Suzuki Motor Corporation has decided that certain 1996 model year 4-door Suzuki Sidekick vehicles fail to conform to Federal Motor Vehicle Safety Standard No. 301, "Fuel System Integrity". The fuel tank on these vehicles may become punctured by a fuel tank flange attachment reinforcement (gusset) during certain types of rear end collisions.

6. Chronology of Principal Events

General Motors was contacted by NHTSA in May of 1996 when a Geo Tracker tested by NHTSA did not pass FMVSS 301. An investigation was initiated to determine the cause and extent of the condition.

7. Description of Corrective Action

This information is provided in the attached dealer bulletins.

8. Schedule

Dealer Bulletins have already been mailed. Owner notification letters will be mailed in July 1996.

9. Copy of Notices


Enclosed are copies of the Technical Service Bulletin, Campaign Bulletin, and draft owner notification letter for this campaign.

10. Suzuki Campaign Number

S1

Sincerely,

AMERICAN SUZUKI MOTOR CORPORATION



Kenneth M. Bush  
Regulations Manager  
Government Relations Department

AS 280041

DRAFT

96V-121.  
002 (03)

### IMPORTANT SAFETY RECALL NOTICE

Dear Suzuki Owner:

This notice is sent to you in accordance with provisions of the National Traffic and Motor Vehicle Safety Act.

American Suzuki Motor Corporation has decided that certain 1996 Suzuki 4-Door Sidekick vehicles fail to conform to Federal Motor Vehicle Safety Standard (FMVSS) 301, "Fuel System Integrity". According to our records, you own one of the affected vehicles.

The fuel tank on these affected vehicles may become punctured by a fuel tank flange attachment reinforcement gusset during certain types of rear end collisions. If this were to occur, a punctured fuel tank could allow fuel spillage in excess of the amount prescribed by FMVSS 301. If an ignition source were present, fuel leakage resulting from this puncture could result in a post-crash fire.

To preclude the possibility of this occurring, your Suzuki dealer, at no charge to you, will install two new gussets between the fuel tank and attachment brackets to prevent the reinforcement from puncturing the fuel tank wall.

Please contact your Suzuki dealer to schedule an appointment for this Safety Recall. Instructions have been sent to your dealer and parts are available. The service can be completed in about 30 minutes. Please ask your dealer if additional time will be needed to process your vehicle. When you arrive for your pre-scheduled service, please present this letter to your Suzuki dealer. If you no longer own this vehicle, please complete the enclosed postage-paid reply card and return it to us.

If your dealer does not make the correction within a reasonable period of time, we recommend you contact the American Suzuki Customer Relations Department at (800) 934-0934. If you are still not satisfied that American Suzuki and your dealer have done our best to make the correction within a reasonable period of time, you may wish to write the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street, S.W., Washington DC 20590 or call the toll-free Auto Safety Hotline at (800) 424-9393.

We are sorry for any inconvenience this Safety Recall may cause, but we are certain you understand our interest in your safety and your continued satisfaction with Suzuki products.

AS 280042

DRAFT

NOTICE TO LESSORS

Under Federal law, the lessor of a vehicle who receives this letter must provide a copy of it to the vehicle lessee(s). The lessor must also keep record of the lessee(s) to whom this letter is sent, and the applicable Vehicle Identification Number.

(For the purposes of this notice, a lessor means a person or entity that in the last twelve months prior to the date of this notification has been the owner, as referenced on the vehicle's title, of any five or more leased vehicles. A leased vehicle is a vehicle leased to another person for a term of at least four months.)

Sincerely,

AMERICAN SUZUKI MOTOR CORPORATION

96V-121.

002 (04)

AS 280043