

**INFORMATION Redacted PURSUANT TO THE FREEDOM OF  
INFORMATION ACT (FOIA), 5 U.S.C. 552(B)(6)**

---

**From:** Anderson, Eric (H.)  
**Sent:** Friday, June 17, 2011 10:48 AM  
**To:** Cassata, Joe (J.)  
**Cc:** Napoli, Laura (L.); Estes, Eric (E.E.)  
**Subject:** 1FMHK7B81BG [REDACTED]

Hi Joe:

Please request this gear. I bet you already have. It should go to Eric Estes at WPAC as usual. TR-EE.

Laura and Eric,  
The repairing tech is on vacation until 6/20, so I don't have the full story yet. There's only a U0131 on the claim, but the advisor said there were more codes. A new gear did fix the problem.

Thanks,

Eric Anderson  
PVT Engineer  
Ford Chicago Assembly  
773.646.7236 desk  
773.729.0337 cell  
[eande181@ford.com](mailto:eande181@ford.com)

Server: **AWS Prod**  
Claims loaded through: **16-JUN-2011**

## Claim Detail Report

*Note: All costs are in US dollars*

**Model Year** = 2011; **Claim Key** = 570483

### Vehicle Information

Model Year: 2011

Market Derived: F - FORD

Body/Cab Type: T/WD - 4 DOOR WAGON

Version/Series: T/EF-FORD SERIES

Drive Type: T/A-2 WHL L/H FRONT  
DRIVE

Vehicle Line: T/UB-EXPLORER [11-12]

Warranty Start Date: 27-APR-11

Production Date: 29-MAR-11

### Claim Information

Document Number: 07580203

Repair Date: 13-JUN-  
11

Distance: 1484

TIS: 2

VIN: 1FMHK7B81BG [REDACTED]

**Expense Information**

**Dealer Information:**

Dealer Name MATTHEWS-CURRIE FORD  
COMPANY

Dealer Code: 03591 - \*

Address: 130 N TAMIAMI TRAIL

City: NOKOMIS

State: FL Zip Code: 34275

Country: USA Region Code: NA

Phone: (941)488-6787

Customer Paid Amount: .00

Deductible Amount: .00

Dealer Paid Amount: .00

Labor Cost: 320.13

Misc. Expense Amount: .00

Part Markup Amount: 763.46

Material Cost: 1511.22

Total Cost Gross: 1831.35

Cust.

Concern H22 - STEERING REQUIRES EXTRA OR UNEVEN EFFORT

Code:

Condition 42 - DOES NOT OPERATE PROPERLY

Code:

Technician VERIFY POWER STEERING INOP SELF TEST U01310 PERFORM PPT S  
Comment: FAILED NETWORK TEST PPT AC FOUND PSCM FAILED REPLACE  
STEERING GEAR ASSY PROGRAM WITH AS BUILT DATA CHECK AND  
ADJUST TOE ROAD TEST RETEST PASS

Customer CUSTOMER STATES THE VEH HAS NO POWER STEERING AND THE ADV  
Comment: TRAC LIGHT AND POWER ASSIST LIGHT IS ON..TOW IN

<u>Labor Op Code</u>	<u>Labor Op Description</u>	<u>Labor Op Cost</u>
3504E		20.65
3504E8		10.33
3504E45		30.98
3001A1T	CASTER, CAMBER AND TOE-IN CORRECT	92.94
MT3504		165.23

<b>Causal</b>	<b>Full Part Number</b>			<b>Part</b>	<b>Part</b>	<b>Extended</b>	
<u>Flag</u>	<u>PREF</u>	<u>BASE</u>	<u>SUFF</u>	<u>Description</u>	<u>CPSC</u>	<u>Quantity</u>	<u>Amount</u>
Y	BB5Z	3504	HE	GEAR ASY-STEERING	110101	1	1511.22

DTC Sections:

Mil. Light On =N

<u>Flag</u>	<u>Test Type</u>	<u>Malfunction Cd</u>	<u>Malfunction Cd Description</u>	<u>Monitor Cd</u>	<u>Monitor Cd Description</u>
UNDF		U0131			

Any comments? You can contact

[webmaster](#)

1559

---

**From:** Anderson, Eric (H.)  
**Sent:** Tuesday, August 02, 2011 11:34 AM  
**To:** Cassata, Joe (J.)  
**Cc:** Estes, Eric (E.E.); Napoli, Laura (L.)  
**Subject:** 1FMHK7D87BG [REDACTED] no EPAS no communication

Hi Joe:

Please request this gear to Eric Estes at WPAC, TR EE.

Eric and Laura:

It's one of the no comm gears. I've had a few others like it. Here are my bin comments:

Called dealership. Intermittent EPAS loss. No codes. No communication with gear. New gear fixed problem. Part requested.

Thanks,

Eric Anderson  
PVT Engineer  
Ford Chicago Assembly  
773.646.7236 desk  
773.729.0337 cell  
[eande181@ford.com](mailto:eande181@ford.com)

Server: **AWS Prod**

Claims loaded through: **01-AUG-2011**

## Claim Detail Report

*Note: All costs are in US dollars*

**Model Year** = 2011; **Claim Key** = 751390

### Vehicle Information

Model Year: **2011**

Market Derived: **F - FORD**

Body/Cab Type: **T/WD - 4 DOOR WAGON**

Version/Series: **T/EF-FORD SERIES**

Drive Type: **T/A-2 WHL L/H FRONT  
DRIVE**

Vehicle Line: **T/UB-EXPLORER [11-12]**

Warranty Start Date: **26-MAY-11**

### Claim Information

Document Number: **309187A**

Repair Date: **14-JUL-11**

Distance: **2584**

TIS: **2**

Production Date: 13-MAY-11

VIN: 1FMHK7D87BG [REDACTED]

**Expense Information**

**Dealer Information:**

Dealer Name LAKE ELSINORE FORD

Dealer Code: 06787 - \*

Address: 31500 AUTO CENTER

City: LAKE ELSINORE

State: CA Zip Code: 92530

Country: USA Region Code: NA

Phone: (951)471-4100

Customer Paid Amount: .00

Deductible Amount: .00

Dealer Paid Amount: .00

Labor Cost: 228.55

Misc. Expense Amount: .00

Part Markup Amount: 299.10

Material Cost: 1046.86

Total Cost Gross: 1275.41

Cust.

Concern H22 - STEERING REQUIRES EXTRA OR UNEVEN EFFORT

Code:

Condition

Code: 42 - DOES NOT OPERATE PROPERLY

Technician VERIFIED CONCERN I HAD NO POWER ASSIST I FOUND NO  
Comment: COMMUNICATION WITH STEERING MODULE TALKED TO HOT LINE NO  
KNOWN CONCERNS CK FOR PWR AND GROUND ON CIRCUIT C1463A  
ALL PASS CK FUSE C1617A PASS CK PWR ON C1463B PASS AND GROUND  
PASS REPLACED POWER STEERING CONTROL MODULE ROAD TESTED  
PERFECT ALSO REST FT WHEEL TOE, ALSO NOTE, CAN REFER TO  
ATTACHED WORK SHEET ON RO WITH HOTLINE CONTACT WITH

Customer

Comment: CUSTOMER REPORTS POWER STEERING DOES NOT WORK

<u>Labor Op Code</u>	<u>Labor Op Description</u>	<u>Labor Op Cost</u>
3504E		19.87
3504E8		9.94
3001A1	CASTER, CAMBER AND TOE-IN CORRECT	59.62
3504E45		29.81

3514A STEERING COLUMN ASSEMBLY REMOVE AND 109.31  
 INSTALL

<u>Causal</u>	<u>Full Part Number</u>			<u>Part</u>		<u>Part</u>	<u>Extended</u>
<u>Flag</u>	<u>PREF</u>	<u>BASE</u>	<u>SUFF</u>	<u>Description</u>	<u>CPSC</u>	<u>Quantity</u>	<u>Amount</u>
Y	BB5Z	3504	HE	GEAR ASY-STEERING	110101	1	1046.86

DTC Sections: Mil. Light On =\*

<u>Fla</u>	<u>Test</u>	<u>Malfunction Cd</u>	<u>Malfunction Cd</u>	<u>Monitor</u>	<u>Monitor Cd</u>
<u>g</u>	<u>Type</u>		<u>Description</u>	<u>Cd</u>	<u>Description</u>

Any comments? You can contact

[webmaster](mailto:webmaster)

7730

**From:** Anderson, Eric (H.)  
**Sent:** Monday, June 20, 2011 3:08 PM  
**To:** Cassata, Joe (J.)  
**Cc:** Napoli, Laura (L.); Estes, Eric (E.E.)  
**Subject:** 1FMHK8B8XBG [REDACTED]

Hi Joe:

Please request this gear to Eric Estes.

Laura and Eric,  
This is the gear with no assist, no warning lights and no DTCs.

Server: **AWS Prod**  
Claims loaded through: **17-JUN-2011**

## Claim Detail Report

*Note: All costs are in US dollars*

**Model Year = 2011; Claim Key = 576373**

### Vehicle Information

Model Year: 2011

Market Derived: F - FORD

Body/Cab Type: T/WD - 4 DOOR WAGON

Version/Series: T/EF-FORD SERIES

Drive Type: T/F-4 WHL L/H FULL TIME  
DRIVE

Vehicle Line: T/UB-EXPLORER [11-12]

Warranty Start Date: 28-MAR-11

Production Date: 03-MAR-11

VIN: 1FMHK8B8XBG [REDACTED]

### Claim Information

Document Number: 03134001

Repair Date: 20-MAY-  
11

Distance: 2947

TIS: 2

### Expense Information

#### Dealer Information:

Dealer Name EVERGREEN FORD

Customer Paid Amount: .00

Deductible Amount: .00

Dealer Code: 08305 - *	Dealer Paid Amount: .00
Address: 1500 - 18TH AVE NW	Labor Cost: 647.81
City: ISSAQUAH	Misc. Expense Amount: .00
State: WA Zip Code: 98027	Part Markup Amount: 305.63
Country: USA Region Code: NA	Material Cost: 1069.71
Phone: (425)392-6900	Total Cost Gross: 1717.52

Cust.  
 Concern H22 - STEERING REQUIRES EXTRA OR UNEVEN EFFORT  
 Code:

Condition  
 Code: 42 - DOES NOT OPERATE PROPERLY

Technician REPLACED EPAS ASSEMBLY, PERFORMED PMI PROCESS. CHECKED  
 Comment: AND ADJUSTED TOE. NO LABOR OPS FOR ALIGNMENT CHECK & RACK  
 REPLACEMENT. M TIME FOR EXTENSIVE DIAG.

Customer \*STEERINGS AND SUSP. CUSTOMER STATES POWER STEERING FAILED  
 Comment: TO OPERATE ONCE WHILE DRIVING 35 MPH, DID NOT OPERATE TILL  
 SHUT ENGINE OFF AND RESTA

<u>Labor Op Code</u>	<u>Labor Op Description</u>	<u>Labor Op Cost</u>
3504E		19.63
3504E8		9.82
3504E45		29.45
3504E47		29.45
MT3504E45		215.93
MT3001A		39.26
3001A1T	CASTER, CAMBER AND TOE-IN CORRECT	88.34
MT3504		215.93

Causal	Full Part Number			Part	Part	Extended	
<u>Flag</u>	<u>PREF</u>	<u>BASE</u>	<u>SUFF</u>	<u>Description</u>	<u>CPSC</u>	<u>Quantity</u>	<u>Amount</u>



Y	*	3504	*	GEAR ASY-STEERING	110200	0	.00
N	*	W714710	S439		110200	4	22.85
N	STE	65	*	MOTORCRAFT BATTERY	110101	1	1046.86

**DTC Sections:**

**Mil. Light On =\***

<u>Flag</u>	<u>Test Type</u>	<u>Malfunction Cd</u>	<u>Malfunction Cd Description</u>	<u>Monitor Cd</u>	<u>Monitor Cd Description</u>
-------------	------------------	-----------------------	-----------------------------------	-------------------	-------------------------------

Any comments? You can contact

[webmaster](#)

4843

Eric Anderson  
PVT Engineer  
Ford Chicago Assembly  
773.646.7236 desk  
773.729.0337 cell  
[eande181@ford.com](mailto:eande181@ford.com)

---

**From:** Anderson, Eric (H.)  
**Sent:** Tuesday, July 12, 2011 11:57 AM  
**To:** Cassata, Joe (J.)  
**Cc:** Napoli, Laura (L.); Mrozek, Robert (R.M.); Estes, Eric (E.E.)  
**Subject:** 1FMHK8F81BG [REDACTED] no EPAS

Hi Joe:

Please request this gear to Eric Estes at WPAC. TR EE.

Laura, Rob and Eric,  
This has the usual U3000 codes but a late build date, May 21, 2011. It's still inside our BSAQ, but concerning. The previous latest date was 4/13/2011. Here are my bin comments:

Called dealership. Tech explained gear had no EPAS and power steering fault light on. U3000:49, U3000:48, U3000:96-C8 pulled from gear. New gear fixed problem. Part requested.

Thanks,

Eric Anderson  
PVT Engineer  
Ford Chicago Assembly  
773.646.7236 desk  
773.729.0337 cell  
[eande181@ford.com](mailto:eande181@ford.com)

Server: **AWS Prod**  
Claims loaded through: **11-JUL-2011**

## Claim Detail Report

*Note: All costs are in US dollars*

**Model Year** = 2011; **Claim Key** = 661269

### Vehicle Information

Model Year: **2011**

Market Derived: **F - FORD**

Body/Cab Type: **T/WD - 4 DOOR WAGON**

Version/Series: **T/EF-FORD SERIES**

Drive Type: **T/F-4 WHL L/H FULL TIME DRIVE**

Vehicle Line: **T/UB-EXPLORER [11-12]**

### Claim Information

Document Number: **31773301**

Repair Date: **29-JUN-11**

Distance: **215**

TIS: **1**

Warranty Start Date: 21-JUN-11

Production Date: 21-MAY-11

VIN: 1FMHK8F81BG [REDACTED]

**Expense Information**

**Dealer Information:**

Dealer Name NAPLETON'S PARK RIDGE  
LINCOLN-

Dealer Code: 10565 - \*

Address: 826 TOUHY AVENUE

City: PARK RIDGE

State: IL Zip Code: 60068

Country: USA Region Code: NA

Phone: (847)825-0770

Customer Paid Amount: .00

Deductible Amount: .00

Dealer Paid Amount: .00

Labor Cost: 843.76

Misc. Expense Amount: .00

Part Markup Amount: 542.97

Material Cost: 1628.91

Total Cost Gross: 2472.67

Cust.

Concern H22 - STEERING REQUIRES EXTRA OR UNEVEN EFFORT

Code:

Condition 42 - DOES NOT OPERATE PROPERLY  
Code:

Technician VERIFIED CK FOR CODES U3000 49,U3000 48,U3000 96C8 ALL PRESENT  
Comment: PERFORMED LOAD TEST AND PINPOINT TESTS ALL POWERS AND  
GROUNDS TO STEERING GEAR GOOD FAILURE IN STEERING GEAR  
NECESSARY TO RE REPLD STEERING GEAR AND RESET TOE AND  
ALIGNMENT,UPLOAD PSCM MODULE CONFIG W IDS,PERFORM PMI ON  
PSCM ALIGN FRT

Customer GETTING POWER STEERING ASSIST FAUL MSG AND STEERING IS HARD  
Comment: TO TURN

<u>Labor Op Code</u>	<u>Labor Op Description</u>	<u>Labor Op Cost</u>
3504E		22.20
3504E45		33.31
3504E8		11.10

3504E47							33.31
3001A1T		CASTER, CAMBER AND TOE-IN CORRECT					99.92
MT3504							643.92

<u>Causal</u>	<u>Full Part Number</u>			<u>Part</u>	<u>Part</u>	<u>Extended</u>	
<u>Flag</u>	<u>PREF</u>	<u>BASE</u>	<u>SUFF</u>	<u>Description</u>	<u>CPSC</u>	<u>Quantity</u>	<u>Amount</u>
Y	BB5Z	3504	JE	GEAR ASY-STEERING	110101	1	1628.91

**DTC Sections:**

**Mil. Light On =N**

<u>Fla</u>	<u>Test</u>	<u>Malfunction Cd</u>	<u>Malfunction Cd</u>	<u>Monitor</u>	<u>Monitor Cd</u>
<u>g</u>	<u>Type</u>		<u>Description</u>	<u>Cd</u>	<u>Description</u>
N	UNDF	U3000	CONTROL MODULE	48	HYBRID
	UNDF	49			
	UNDF	96C8			
	UNDF	48			
N	UNDF	U3000	CONTROL MODULE	48	HYBRID
N	UNDF	U3000	CONTROL MODULE	48	HYBRID

Any comments? You can contact

[webmaster](mailto:webmaster)

4514

---

**From:** Anderson, Eric (H.)  
**Sent:** Thursday, June 16, 2011 10:15 AM  
**To:** Napoli, Laura (L.); Estes, Eric (E.E.)  
**Cc:** Cassata, Joe (J.)  
**Subject:** 1FMHK8F85BGA29508 EPAS inop

FYI. Here's another U3000:49. It's within the BSAQ project window. A new gear fixed the problem.

Joe,  
Thanks for requesting it.

Server: **AWS Prod**  
Claims loaded through: **15-JUN-2011**

## Claim Detail Report

*Note: All costs are in US dollars*

**Model Year = 2011; Claim Key = 566418**

### Vehicle Information

Model Year: **2011**

Market Derived: **F - FORD**

Body/Cab Type: **T/WD - 4 DOOR WAGON**

Version/Series: **T/EF-FORD SERIES**

Drive Type: **T/F-4 WHL L/H FULL TIME  
DRIVE**

Vehicle Line: **T/UB-EXPLORER [11-12]**

Warranty Start Date: **26-MAR-11**

Production Date: **04-MAR-11**

VIN: **1FMHK8F85BG** XXXXXXXXXX

### Claim Information

Document Number: **68245502**

Repair Date: **09-JUN-  
11**

Distance: **3003**

TIS: **3**

### Expense Information

#### **Dealer Information:**

Dealer Name **VAN BORTEL FORD, INC.**

Dealer Code: **07590 - \***

Customer Paid Amount: **.00**

Deductible Amount: **.00**

Dealer Paid Amount: **.00**

Address: **71 MARSH RD.** Labor Cost: **244.18**  
 City: **EAST ROCHESTER** Misc. Expense Amount: **.00**  
 State: **NY** Zip Code: **14445** Part Markup Amount: **537.54**  
 Country: **USA** Region Code: **NA** Material Cost: **1623.48**  
 Phone: **(585)924-9525** Total Cost Gross: **1867.66**

Cust.  
 Concern **H22 - STEERING REQUIRES EXTRA OR UNEVEN EFFORT**  
 Code:

Condition  
 Code: **42 - DOES NOT OPERATE PROPERLY**

Technician **MT** TIME FOR UNPUBLISHER LABOR OPERATIONS. DIAG P STEERING  
 nREPLACE BINDING GEAR ASSEMBLY TEST DR TO VERIFY, TEST  
 Comment: PSCM, CODES U2100, U2000 46U3000 49, CK FUSE E, FUSE 89, OK, CK POWER  
 AT MODULE, OK, REPL STEERING RACK ASSEMBLY. CHECK FRONT  
 ALIGNMENT, SET TOE. TEST DRIVE OK. 2012 UNIT, ALL NEW REQUIRED  
 CLAIM IS OK AS IS

Customer **CUSTOMER STATES SHE LOST THE STEERING IN CAR WE DELIVED A**  
 Comment: **STOCK VEHICLE ESCAPE TO HER LAST NITE, AS PER GUY DIAG AND**  
**ADVISE CUSTOMER ASAP THURS**

<u>Labor Op Code</u>	<u>Labor Op Description</u>	<u>Labor Op Cost</u>
3504E		16.28
3504E45		24.42
MT3504		203.48

<u>Causal</u>	<u>Full Part Number</u>			<u>Part</u>	<u>Part</u>	<u>Extended</u>	
<u>Flag</u>	<u>PREF</u>	<u>BASE</u>	<u>SUFF</u>	<u>Description</u>	<u>CPSC</u>	<u>Quantity</u>	<u>Amount</u>
Y	BB5Z	3504	JE	GEAR ASY-STEERING	110101	1	1623.48

**DTC Sections:** **Mil. Light On =N**

<u>Flag</u>	<u>Test Type</u>	<u>Malfunction Cd</u>	<u>Malfunction Cd Description</u>	<u>Monitor Cd</u>	<u>Monitor Cd Description</u>
	UNDF	U2100			
N	UNDF	U3000	CONTROL MODULE	48	HYBRID
N	UNDF	U2000	AUDIO REAR CONTROL UNIT IS NOT RESPONDING	24	CCM VEHICLE

Any comments? You can contact

[webmaster](mailto:webmaster)

227


Eric Anderson  
PVT Engineer  
Ford Chicago Assembly  
773.646.7236 desk  
773.729.0337 cell  
[eande181@ford.com](mailto:eande181@ford.com)

---

**From:** Estes, Eric (E.E.)  
**Sent:** Wednesday, January 04, 2012 12:05 PM  
**To:** Surella, Matthew (M.M.); Snider, Tim (T.O.); Flanagan, Thomas (T.P.); Napoli, Laura (L.)  
**Cc:** 'Anthony Fleenor' (Anthony.Fleenor@TRW.COM); Christopher Woodruff; 'JoseJ Lopez' (JoseJ.Lopez@TRW.COM); Sergio Alvarez (Sergio.Alvarez@TRW.COM)  
**Subject:** 2012 All EPAS Platforms Tyco Relay Claim Count for NA

I thought I sent this before the holiday break, here is the summary of all the warranty, OKM & line returns.  
I have a tab for each platform.

Let me know if you have any questions, thanks



*Eric J Estes*

TRW EPAS Steering Systems  
Quality Specialist  
Hotline ph# 313-317-9358  
Cell ph# 734-560-3493



Case Number	Ford DTCs	TRW Code (Symptom)	Gear Location	Fault found/Root cause	Current Updates	Motor Build Date
UR0090 RUA# 5175	U2011-49	B3A	In eval Tyco	NTF	10/17- B3A repeating PH2 motor relay open contacts. Ship to Tyco 12-7- Tyco found NTF with the relay. SEM on contacts some material found	4/19/2011
UR0126	U3000-72	A30, E30	in process UK	R28 resistor on ECU PCB	12/6-fault following ECU found low resistance on R28 generating incorrect Vbatt readings on ECU. Sergio to ship to UK	
UR0133 RUA# 5164	U2011-49 U3000-96	B3A	in process Tyco		12/13- could duplicate B3A failure in lab. surrogate relay test OK, ribbon cable wiggle test ok, 5amp test done found faulty motor relay. Save for workshop next year.	6/8/2011
UR0137	U2011-49	B3A	in eval MAO		12/9- pulled stored and EFF data shipped to MAO for analysis	9/22/2011
UR0138	U3000-49	B43	in eval MAO		12/9- pulled stored and EFF data shipped to MAO for analysis	5/19/2011
OKM RUA# 5167	U2011-49	B3A	in process Tyco		12/13- could duplicate B3A failure in lab. surrogate relay test OK, ribbon cable wiggle test ok, 5amp test done found faulty motor relay	

4- B3A motor relays

1- B43 Link relay

1- A30 R28 resistor

**6 total relay issues**

Case Number/ RUA	Ford DTCs	TRW Code (Symptom)	Gear Location	Fault found/Root cause	Current Updates	Motor build Date
FR-0551 RUA# 5258	U2011-49	B3A	in eval Tyco	NTF	12/19- Tyco went through complete relay test with NTF	4/10/2011
FR-0554 RUA# 5259	U2011-49	B43	in eval Tyco	Surface contamination	12/19- Tyco has found surface contamination on contact 4. next step to SEM the contacts	6/24/2011
FR-0555	U2011-49	B43	in eval QAO		10/28-pulled EFF & stored data. Shipped to QAO for further testing	5/26/2011
FR-0557	U2011-49	B43	in eval QAO		10/28-pulled EFF & stored data. Shipped to QAO for further testing	4/28/2011
FR-0558	U2011-49	B3A	in eval QAO		10/28-pulled EFF & stored data. Shipped to QAO for further testing	5/3/2011
FR-0559 RUA# 5287	U2011-49	B43	in eval Tyco		11/23- confirmed link relay	5/31/2011
FR-0561	U2011-49	B3A	in eval QAO		11/1-pulled EFF & stored data. Shipped to QAO for further testing	6/22/2011
FR-0562	U2011-49	B3A	in eval QAO		11/4-pulled EFF & stored data. Shipped to QAO for further testing	6/17/2011
FR-0568	U2011-49	B3A	in eval QAO		11/11-pulled EFF & stored data. Shipped to QAO for further testing	5/4/2011
FR-0569	U2011-49	B3A	in eval QAO		11/18-pulled EFF & stored data. Shipped to QAO for further testing	6/1/2011
FR-0570	U3000-49 U3000-96	B43,BB7	in eval QAO		11/18-pulled EFF & stored data. Shipped to QAO for further testing	7/27/2011
FR-0571	U2011-49	B3A	in eval QAO		11/18-pulled EFF & stored data. Shipped to QAO for further testing	6/21/2011
FR-0572	U3000-49 U3000-96	B43	in eval QAO		11/23-pulled EFF & stored data. Shipped to QAO for further testing	6/16/2011

FR-0573	U2011-49	B3A	in process QAO		12/12- pulled EFF & stored data shipped gear to QAO for further analysis	6/15/2011
FR-0575	U2011-49	B3A	in process QAO		12/12- pulled EFF & stored data shipped gear to QAO for further analysis	5/3/2011
FR-0577	U2011-49	B3A	in process QAO		12/12- pulled EFF & stored data shipped gear to QAO for further analysis	6/22/2011
FR-0578	U2011-49	B6B	in process QAO		12/12- pulled EFF & stored data shipped gear to QAO for further analysis	5/21/2011
FR-0579	U3000-49	B43, BB5	in process QAO		12/12- pulled EFF & stored data shipped gear to QAO for further analysis	6/15/2011
FR-0581	U2011-49	B3A	in process QAO		12/12- pulled EFF & stored data shipped gear to QAO for further analysis	5/20/2011
FR-0585	U2011-49 U3000-96	B3A	At WPAC computer issues shipping gears out to MAO		12/19- pulled EFF & stored data shipped gear to QAO for further analysis	7/27/2011
FR-0586	U2011-49	B3A	At WPAC computer issues shipping gears out to MAO		12/19- pulled EFF & stored data shipped gear to QAO for further analysis	7/27/2011
OKM RUA# 5279		B43	In eval Tyco		QAO damaged link relay removing from PFS	
QAO line Bully RUA# 5262		E66	In eval Tyco	damaged ribbon cable due to handling at Anting	11/15/2011	
QAO line Bully RUA# 5253		E66	In eval Tyco	damaged ribbon cable due to handling at Anting	11/15/2011	

QAO line Bully RUA# 5260		E66	In eval Tyco	damaged ribbon cable due to handling at Anting	11/15/2011	
QAO line Bully RUA# 5261		A3A	In eval Tyco	damaged ribbon cable due to handling at Anting	11/15/2011	
QAO line Bully RUA# 5269		A3A	In eval Tyco	damaged ribbon cable due to handling at Anting	11/15/2011	
QAO line Bully RUA# 5270		A3A	In eval Tyco	damaged ribbon cable due to handling at Anting	11/15/2011	

13- B3A Motor relays

8- B43 link relays

3- E66

3- A3A

1- B6B motor relay short

**28 total relay issues**

Item	Quantity	Description	Unit	Price	Total
1	1	Concrete slab (4m x 4m)	m <sup>2</sup>	120	120
2	1	Rebar (Ø16mm)	m	15	15
3	1	Formwork (plywood)	m <sup>2</sup>	80	80
4	1	Gravel (100mm)	m <sup>3</sup>	100	100
5	1	Gravel (200mm)	m <sup>3</sup>	120	120
6	1	Gravel (400mm)	m <sup>3</sup>	150	150
7	1	Gravel (600mm)	m <sup>3</sup>	200	200
8	1	Concrete (C20)	m <sup>3</sup>	250	250
9	1	Labour (1 worker)	day	100	100
10	1	Transport (truck)	hour	50	50
11	1	Construction site fees	fixed	500	500
12	1	Material waste	fixed	20	20
13	1	Labour waste	fixed	10	10
14	1	Transport waste	fixed	5	5
15	1	Insurance	fixed	50	50
16	1	Tax	fixed	50	50
17	1	Profit	fixed	100	100
<b>Total</b>					<b>2025</b>

The yellow box means no specification of TYCO with instruction (100% Check 1952045-1/1952046-1)  
The green box means addition of fabric sorting instruction based on new standard on TYCO work instruction (100% Check 1952045-1/1952046-1)  
The red box means TYCO production Lot after Dec/03-2011



**Last serial number with relay before clean date**

Ford model	Motor serial number	Motor production date	Relay date code
Redacted for Relevance			
D3/U502 48mm	CAG0E287110449	Oct 14, 2011	1136411
U502 58mm	BAF0E335210095	Dec 1, 2011	1132621
Redacted for Relevance			

**First serial number of complete clean relay (no motor later than below has relay before clean date)**


Ford model	Motor serial number	Motor production date
Redacted for Relevance		
D3/U502 48mm	CAG0E287110450	Oct 14, 2011
U502 58mm	BAG0E335210004	Dec 1, 2011
Redacted for Relevance		

---

**From:** Surella, Matthew (M.M.)  
**Sent:** Tuesday, January 24, 2012 12:00 AM  
**To:** Perri, Ron (R.J.)  
**Cc:** Napoli, Laura (L.)  
**Subject:** 6 Panel on relay issues

Ron,  
Here's a first draft of the 6 Panel. I still need to finish some slides tomorrow.

Matthew (Matt) Surella  
Steering EPAS Supervisor / MBB  
313-805-3997







STANDARD REPORTING METHOD  
FOR PROBLEM SOLVING

# 6-PANEL

---

## TRW EPAS Gear Relay Issues

Project Leader: Laura Napoli

Project Champion: Ron Perri/John Tetley

Process Owner: Matt Surella

Organization: PD Chassis Steering

Project Location: PD Dearborn

# 6-PANEL

© 2002-2005, Ford Motor Company



DEFINE VOICE OF THE CUSTOMER

Business Unit: PD Dearborn	Functional area: Chassis Steering	Customer: Vehicle owner
Vehicle program: U502, CD3, C346		Part: EPAS

<p><b>PROJECT CLASSIFICATION:</b></p> <p>BSAQ Item: SAQ201161617-EPAS B3A Motor Relay Contamination</p>	<p><b>TREND CHARTS and BREAKDOWN OF ISSUE:</b></p> <div style="text-align: center;"> <p>Relay %Fall-out</p> <p><b>U502</b></p> <p>10/40,023</p> <p>0.025%</p> <p><b>0.025%</b></p> <p>10 out of 40023</p> </div>	<p>based on warranty teardowns</p>
---	--	--

**VOICE OF THE CUSTOMER:** Some U502, , and  vehicles may exhibit loss of steering assist during a journey including an indicator light on the IP. Assist will return when the key is cycled.


**CTQ STATEMENT (Customer Requirement):**  
EPAS should give driver power steering assist at all times.

**DEFECT DEFINITION for Y (Objective Metric):**  
Within the TRW EPAS electronics, there is a motor relay and a link relay. Failure of the motor relay primarily results in the TRW code B3A and failure of the link relay primarily results in the code B43.

**COST OF POOR QUALITY:**  
Customer dissatisfaction, warranty cost for EPAS claim.

**PROBLEM STATEMENT, SCOPE, AND GOAL**  
Find root causes of relay failures and implement corrective actions to eliminate this issue.  has highest repair rate at 0.35 R/1000 and problem will be scoped to it.

### Relay Code Count



# 6-PANEL

© 2002-2005, Ford Motor Company



DEFINE VOICE OF THE CUSTOMER

← VEHICLE BUILD MONTH

MOTOR BUILD MONTH →

# 6-PANEL

© 2002-2005, Ford Motor Company



DEFINE VOICE OF THE CUSTOMER

← TIME IN SERVICE

Average = 4.54 MIS

MILEAGE →

Average = 7282 Miles

# 6-PANEL

© 2002-2005, Ford Motor Company



DEFINE VOICE OF THE CUSTOMER

## Pie Chart of CD3 Steering Effort Warranty Claims from SOP

This pie chart is based on warranty claim verbatims and shows 15 claims for B3A where tech listed the code.

# 6-PANEL

© 2002-2005, Ford Motor Company



DEFINE VOICE OF THE CUSTOMER


Redacted for Relevance

up  
B3  
B4  
AF  
B6  
B6  
NC  
B2  
B3  
B3  
TC  
BE

# 6-PANEL

© 2002-2005, Ford Motor Company

## Run Chart of Relay Issues by Motor Build



© TRW Automotive Holdings Corp. 2012



# 6-PANEL

© 2002-2005, Ford Motor Company

## Relays Under Analysis

- **44 Relays are currently under analysis**

- **Source**

- 33 from Ford NA
- 11 from Ford of Europe

- **Relay Type**

- 13 link relays
- 31 motor relays

- **Root Causes under investigation**

- Sugar contamination 2
- Mechanical damage 3
- Extra rivet inside relay 1
- Coil terminal not welded 1
- Plastic contamination 1
- Unknown contamination 1
- Scratches on contact 2
- CuS 4
- Initial report NFF 4

- **Relays without initial reports**


- On hold for workshop 10
- In transit 5
- Analysed at TRW 2
- Waiting for initial report 8

Multiple root causes so focus on largest failure mode which is currently CuS contamination.

← Majority of these 10 look to be CuS contamination

# 6-PANEL

© 2002-2005, Ford Motor Company





Example warranty return of relay contacts. Note the corrosion not only in the center of the contact but also on the edge (circled in red).

# 6-PANEL

© 2002-2005, Ford Motor Company


- Contact 4 showed contamination
- EDX analysis of affected area indicated the presence of sulphur and oxygen



Corrosion areas in both center and edge show presence of copper, sulphur and oxygen

# 6-PANEL

© 2002-2005, Ford Motor Company




Analysis of the edge of the contacts shows contamination getting in between the bottom copper layer and the top silver layer. Further analysis by Tyco shows that there is actually a crack between the copper and the silver.

# 6-PANEL

© 2002-2005, Ford Motor Company



ANALYZE  $y=f(x)$




Goal of trials at Tyco was to produce cracks between copper and silver layers. They were successful in doing this using their press in Portugal.

# 6-PANEL

© 2002-2005, Ford Motor Company



ANALYZE  $y=f(x)$



Humidity cycling of the part (40 degrees C, 95% humidity, 16 hours / 13 degrees C, 95% humidity, 8 hours) caused corrosion to develop in the area of the crack. This was repeated on 6 different parts with cracks between copper and silver layers. 20 virgin parts with no cracks were subjected to the same humidity test and none of them showed any signs of this type of corrosion.

## Root Cause Summary

- After the riveting tests, we can conclude that;
  - Rivets where the crack occurs in Doduco process exhibit the contamination.
  - Rivets where the crack is caused by TE's riveting process do not show any signs of contamination.
  - The set-up of the press, where the silver and copper are welded together, is the root cause for possible crack in the rivet.
  - The contamination source is Doduco
  - This contamination has copper and sulphate on its composition as seen in the complained relay.

# 6-PANEL


© 2002-2005, Ford Motor Company



IMPROVE  $y=f(x)$

## Containment Actions at Marion and Queretaro

QAO PUMA RUN CHART



Hot Puma testing at QTO and MAO was increased from 3000 to 4500 relay cycles on 11/17/2011 to try to force a relay failure. A script was implemented on 12/10/2011 which rejects parts that show any LICs for B3A, A3A, and B43.



## Containment Actions at Tyco

- Check 10 rivet per bag (10,000/bag) under a microscope for evidence of cracks at Tyco.
- Scrap first 1000 parts everytime cold weld press starts up at Doduco. It was found that cracks occur when press first starts up.
- Clean feeder tube of any rivets after every set up/tool change after 1000 rivet scrap at Doduco. It was found that set up parts could potentially get into production.
- All actions implemented Aug 5, 2011

## PCA Actions at Tyco

- Investigate going to a solid silver contact rather than bimetal copper/silver

## Next Steps

- ❑ Complete workshop at Tyco Jan 23-25. Both TRW and Ford attending.
- ❑ Complete investigation on solid silver contacts to implement as a possible PCA
- ❑ Root cause and implement corrective actions on the other failure modes making up the relay spike in 2012 MY.

# 6-PANEL

© 2002-2005, Ford Motor Company




DEFINE VOICE OF THE CUSTOMER

BACK-UP SLIDES

# 6-PANEL

© 2002-2005, Ford Motor Company


## Run Chart – Fault Code



# 6-PANEL

© 2002-2005, Ford Motor Company

## Run Chart – Root Cause




# 6-PANEL

© 2002-2005, Ford Motor Company

Relay type (All) Failed at (All)

## Root Causes



---

**From:** Napoli, Laura (L.)  
**Sent:** Thursday, February 16, 2012 3:49 PM  
**To:** Surella, Matthew (M.M.)  
**Subject:** Anting concoat sort

Matt,

Nidec sorted all the completed motors at their and Anting's facilities between 11/11 - 11/27. 30% of that stock was quarantined due to visual presence (using UV light) of conformal coat at the ribbon cable connector. These parts have been scrapped by Nidec, so we were not able to assess how many of these would result in a B9A.

On 11/11, Nidec fixed the conveyor which was the root cause of the concoat contamination. Then from 11/27-12/30, Anting sorted 30% of stock as it was being loaded to the line and found 0 failures.

Regards,

*Laura Napoli*

D3 and U502 EPAS  
Ford Motor Company  
Cube: 2B-G66 PDC  
Phone: 313.323.0634  
Mobile: 313.805.0482

---

**From:** Quis, Rudolf (R.)  
**Sent:** Friday, February 17, 2012 6:40 AM  
**To:** Andy Partridge; Mike Davies; Phil Browne  
**Cc:** Napoli, Laura (L.); Hilprecht, Ulrike (U.)  
**Subject:** AW: AW: AW: AW: AW: TE Ribbon cable action

That's fair.

You know the warranty analysis team can only check for visual damages.  
By this I assume we are still sending relays to TE which do not have an issue and which they will declare as NFF.

As discussed one of my targets is to get rid of the very high numbers of NFF from TE.  
Therefor we will have the brainstorming workshop in the next weeks on diagnostic improvements.

Best regards / Mit freundlichen Gruessen Rudolf Quis Lead System Engineer & PMST leader C1MCA EPAS Chassis  
Steering Ford Werke GmbH  
D-MC/1-C2  
Spessartstrasse  
50725 Cologne-Merkenich  
Germany  
Tel. +49/221/9033868  
Fax. +49/221/9033183  
Ford internal: 87033868  
e-Mail: rquis@ford.com

Ford-Werke GmbH  
Henry-Ford-Straße 1, 50735 Köln  
Sitz der Gesellschaft: Köln  
Registergericht Köln, HRB 54183  
Vorsitzender des Aufsichtsrats: Stephen Odell  
Geschäftsführung: Bernhard Mattes (Vorsitzender), Wolfgang Booms, Dirk Heller, Caspar Hohage, Dr. Hermann H.  
Hollmann, Rainer Ludwig, Rüdiger Minrath, Dr. Wolfgang Schneider

-----Ursprüngliche Nachricht-----  
Von: Andy Partridge [mailto:Andy.Partridge@TRW.COM]  
Gesendet: Freitag, 17. Februar 2012 12:17  
An: Quis, Rudolf (R.); Mike Davies; Phil Browne  
Cc: Napoli, Laura (L.); Hilprecht, Ulrike (U.)  
Betreff: Re: AW: AW: AW: AW: TE Ribbon cable action

Hi Rudi.

Once I have results from our initial jig and I am happy it works, finds faulty cables and is the best way of testing, I shall look into producing some for each of the sites. Hopefully it is good first time.

Regards  
Andy



>>> "Quis, Rudolf (R.)" <rquis@ford.com> 2/17/2012 10:59 am >>>

Sorry misunderstanding,

I am talking about the warranty analysis areas in Schalke, Nove Mesto and Marion, for returned parts only.

Best regards / Mit freundlichen Gruessen Rudolf Quis Lead System Engineer & PMST leader C1MCA EPAS Chassis  
Steering Ford Werke GmbH  
D-MC/1-C2  
Spessartstrasse  
50725 Cologne-Merkenich  
Germany  
Tel. +49/221/9033868  
Fax. +49/221/9033183  
Ford internal: 87033868  
e-Mail: rquis@ford.com

Ford-Werke GmbH  
Henry-Ford-Straße 1, 50735 Köln  
Sitz der Gesellschaft: Köln  
Registergericht Köln, HRB 54183  
Vorsitzender des Aufsichtsrats: Stephen Odell  
Geschäftsführung: Bernhard Mattes (Vorsitzender), Wolfgang Booms, Dirk Heller, Caspar Hohage, Dr. Hermann H.  
Hollmann, Rainer Ludwig, Rüdiger Minrath, Dr. Wolfgang Schneider

-----Ursprüngliche Nachricht-----

Von: Andy Partridge [mailto:Andy.Partridge@TRW.COM]

Gesendet: Freitag, 17. Februar 2012 11:40

An: Quis, Rudolf (R.); Mike Davies; Phil Browne

Cc: Napoli, Laura (L.); Hilprecht, Ulrike (U.)

Betreff: Re: AW: AW: AW: TE Ribbon cable action

Hi Rudi.

It's a test for returning parts. It couldn't be adapted for production.

It's to enable us to diagnose and assess parts here without putting undue strain on the connectors.

Regards

Andy

Quality and Product Support  
TRW Electronic Engineering  
Technical Centre  
Stratford Road  
Shirley  
B90 4GW

Tel: +44 (0)121 627 3143

Mob: +44 (0)7920 134912

>>> "Quis, Rudolf (R.)" <rquis@ford.com> 2/17/2012 10:05 am >>>

By when will this test be finally developed and in place @ Schalke, Nove Mesto and Marion?

Best regards / Mit freundlichen Gruessen Rudolf Quis Lead System Engineer & PMST leader C1MCA EPAS Chassis  
Steering Ford Werke GmbH  
D-MC/1-C2  
Spessartstrasse  
50725 Cologne-Merkenich  
Germany  
Tel. +49/221/9033868  
Fax. +49/221/9033183  
Ford internal: 87033868  
e-Mail: rquis@ford.com

Ford-Werke GmbH  
Henry-Ford-Straße 1, 50735 Köln  
Sitz der Gesellschaft: Köln  
Registergericht Köln, HRB 54183  
Vorsitzender des Aufsichtsrats: Stephen Odell  
Geschäftsführung: Bernhard Mattes (Vorsitzender), Wolfgang Booms, Dirk Heller, Caspar Hohage, Dr. Hermann H.  
Hollmann, Rainer Ludwig, Rüdiger Minrath, Dr. Wolfgang Schneider

-----Ursprüngliche Nachricht-----

Von: Andy Partridge [mailto:Andy.Partridge@TRW.COM]  
Gesendet: Freitag, 17. Februar 2012 09:57  
An: Quis, Rudolf (R.); Mike Davies; Phil Browne  
Cc: Napoli, Laura (L.); Hilprecht, Ulrike (U.)  
Betreff: Re: AW: AW: TE Ribbon cable action

Hi Rudi.

This week we have designed and have been building a ribbon cable test jig to allow us to easily test the ribbon cables in a standard way.

This

will allow us to test all incoming B3a ribbon cables to have confidence that the relay is or is not root cause.

I aim to provide a video once it is completed and in operation.

Regards

Andy

Quality and Product Support  
TRW Electronic Engineering  
Technical Centre  
Stratford Road  
Shirley  
B90 4GW

Tel: +44 (0)121 627 3143

Mob: +44 (0)7920 134912

>>> "Quis, Rudolf (R.)" <rquis@ford.com> 2/17/2012 8:43 am >>>

Thank you very much Andy, you make me happy.  
I asked this to multiple TRW people now since two month without success.

What changed on the warranty analysis procedures now (globally).  
We need to ensure that we do not send relays to TE if the cable is the root cause.  
To detect an intermittent contact, a visual check is not enough.

Best regards / Mit freundlichen Gruessen Rudolf Quis Lead System Engineer & PMST leader C1MCA EPAS Chassis  
Steering Ford Werke GmbH  
D-MC/1-C2  
Spessartstrasse  
50725 Cologne-Merkenich  
Germany  
Tel. +49/221/9033868  
Fax. +49/221/9033183  
Ford internal: 87033868  
e-Mail: rquis@ford.com

Ford-Werke GmbH  
Henry-Ford-Straße 1, 50735 Köln  
Sitz der Gesellschaft: Köln  
Registergericht Köln, HRB 54183  
Vorsitzender des Aufsichtsrats: Stephen Odell  
Geschäftsführung: Bernhard Mattes (Vorsitzender), Wolfgang Booms, Dirk Heller, Caspar Hohage, Dr. Hermann H.  
Hollmann, Rainer Ludwig, Rüdiger Minrath, Dr. Wolfgang Schneider

-----Ursprüngliche Nachricht-----  
Von: Andy Partridge [mailto:Andy.Partridge@TRW.COM]  
Gesendet: Freitag, 17. Februar 2012 09:37  
An: Quis, Rudolf (R.); Mike Davies; Phil Browne  
Cc: Napoli, Laura (L.)  
Betreff: Re: AW: TE Ribbon cable action

Hello Rudi.

An intermittent or loss of signal on pins 10, 11 or pin 12 on the ribbon cable will cause the relay to drop out/lose connectivity. The signals are Motor relay High side, Motor relay low side and Vstar.

We experimented with one of the 3 returned north American units with the "pulled" ribbon cable. We were able to replicate intermittence the same way we can for B9a and then on a bench test running the EPP we were able to replicate a B3a by inducing movement of the cable in the same way that we first proved B9a.

We conclude from this that B3a has been caused and has the potential to be caused by a faulty ribbon cable. I also believe although currently unproven, that a B6b could be caused the same way as it would be relay drop out and immediate pull in under load causing a weld.

Regards  
Andy

Quality and Product Support  
TRW Electronic Engineering  
Technical Centre  
Stratford Road  
Shirley  
B90 4GW

Tel: +44 (0)121 627 3143  
Mob: +44 (0)7920 134912

>>> "Quis, Rudolf (R.)" <rquis@ford.com> 2/16/2012 7:12 pm >>>

Hello Mike,

this proposal is acceptable.

By the way, are you able to share the evidence with me, that the ribbon cable could lead to B3A diagnostic codes.

I asked several people @ TRW to do so since 2 month without success.

You know that I am working together with TE Evora on the relay improvements but ~50% of returned parts are claimed by TE as NFF.

This evidence is required to explain some of the NFF. If there is a proof, we need to apply this during the EPP analysis procedure.

Best regards / Mit freundlichen Gruessen Rudolf Quis Lead System Engineer & PMST leader C1MCA EPAS Chassis  
Steering Ford Werke GmbH  
D-MC/1-C2  
Spessartstrasse  
50725 Cologne-Merkenich  
Germany  
Tel. +49/221/9033868  
Fax. +49/221/9033183  
Ford internal: 87033868  
e-Mail: rquis@ford.com

Ford-Werke GmbH  
Henry-Ford-Straße 1, 50735 Köln  
Sitz der Gesellschaft: Köln  
Registergericht Köln, HRB 54183  
Vorsitzender des Aufsichtsrats: Stephen Odell  
Geschäftsführung: Bernhard Mattes (Vorsitzender), Wolfgang Booms, Dirk Heller, Caspar Hohage, Dr. Hermann H. Hollmann, Rainer Ludwig, Rüdiger Minrath, Dr. Wolfgang Schneider

Von: Mike Davies [mailto:Mike.Davies@TRW.COM]  
Gesendet: Donnerstag, 16. Februar 2012 18:23  
An: Quis, Rudolf (R.); Phil Browne  
Cc: Napoli, Laura (L.); Andy Partridge  
Betreff: TE Ribbon cable action

Hello Rudi

I hope that you are keeping well, wherever you are in the world this week.

As you may recall from the visit to TE in January, we have a list of actions which Laura is tracking in regular calls. One action related to defining key characteristics for the cable assembly, and the action was assigned to you and myself.

I have spoken with Phil Browne and others on this, and the consensus is that we believe that the functional aspects of the cable are the most important.

We would therefore propose that the following are identified as key characteristics.

1. Continuity from one end of the assembly to the other 2. Isolation of adjacent conductors 3. Resistance value of the individual conduction paths

At this point, we are not intending to define specific values for these last two characteristics. We want to ask TE what they can achieve and realistically measure. When they have provided this data, we can check that the system can accommodate these. They can then be added to the drawing.

We do not believe the overall length of the cable assembly needs to be defined as a key characteristic. It already has a suitable tolerance on it, to allow for the cable routing in the system.

Please can you give us your views on this proposal, so that we can progress with TE.

thanks and regards

Mike

Mike Davies  
Senior Manager Supplier Development  
European Steering

TRW Limited Registered in England, No. 872948 Registered Office  
Address: Stratford Road, Solihull B90 4AX


1/23/2012

	Fallout%	Fallout	Total Checked	Good
2012MY U502	0.025%	10	40023	40013
Redacted for Relevance				


2/23/2012

	Fallout%	Fallout	Total Checked	Good
2011MY U502	0.027%	11	40023	40012
Redacted for Relevance				

# Relay %Fall-out



# B3A %Fall-out






---

**From:** Napoli, Laura (L.)  
**Sent:** Tuesday, February 28, 2012 1:55 PM  
**To:** Quis, Rudolf (R.)  
**Cc:** Surella, Matthew (M.M.)  
**Subject:** B3A FNA 6-Panel

Rudi,

Attached is our 6-panel for B3A with FNA implementation dates for solid silver relays. Can you send me information for when you plan to implement in full production on C1? Are all your programs getting massive silver contacts as a running change or is there any program that will be getting the change into any prototype builds? You'll see in our presentation that we will implement on U502 13.5MY PP build before hitting full production in August.



Regards,

*Laura Napoli*

D3 and U502 EPAS  
Ford Motor Company  
Cube: 2B-G66 PDC  
Phone: 313.323.0634  
Mobile: 313.805.0482



STANDARD REPORTING METHOD  
FOR PROBLEM SOLVING

# 6-PANEL

---

## TRW EPAS Gear Relay Issues

Project Leader: Laura Napoli

Project Champion: Ron Perri/John Tetley

Process Owner: Matt Surella

Organization: PD Chassis Steering

Project Location: PD Dearborn

# 6-PANEL

© 2002-2005, Ford Motor Company



DEFINE VOICE OF THE CUSTOMER

Business Unit: PD Dearborn	Functional area: Chassis Steering	Customer: Vehicle owner
Vehicle program: U502, CD3, C346		Part: EPAS

<p><b>PROJECT CLASSIFICATION:</b></p> <p>BSAQ Item: SAQ2012208065 -EPAS B3A Motor Relay Contamination</p>	<p><b>TREND CHARTS and BREAKDOWN OF ISSUE:</b></p> <p style="text-align: center;"><b>Relay %Fall-out</b> <b>U502</b> 10/40,023 0.025% 10 out of 40023 <b>0.025%</b></p>	<p><b>based on warranty teardowns</b></p>
---	---	---

**VOICE OF THE CUSTOMER:** Some U502,  and  vehicles may exhibit loss of steering assist during a journey including an indicator light on the IP. Assist will return when the key is cycled.

**CTQ STATEMENT (Customer Requirement):**  
EPAS should give driver power steering assist at all times.

**DEFECT DEFINITION for Y (Objective Metric):**  
Within the TRW EPAS electronics, there is a motor relay and a link relay. Failure of the motor relay primarily results in the TRW code B3A and failure of the link relay primarily results in the code B43.


**COST OF POOR QUALITY:**  
Customer dissatisfaction, warranty cost for EPAS claim.

**PROBLEM STATEMENT, SCOPE, AND GOAL**  
Find root causes of relay failures and implement corrective actions to eliminate this issue.  has highest repair rate at 0.35 R/1000 and problem will be scoped to it.

# 6-PANEL

© 2002-2005, Ford Motor Company

### Relay Code Count



# 6-PANEL

© 2002-2005, Ford Motor Company




DEFINE VOICE OF THE CUSTOMER

Redacted  
For  
Relevance

# 6-PANEL

© 2002-2005, Ford Motor Company

## Run Chart of Relay Issues by TE Relay Build



# 6-PANEL

© 2002-2005, Ford Motor Company

- **85 Relays are currently under analysis**

- **Source**

- 73 from Ford NA
- 12 from Ford of Europe

as of  
2/24/2012

- **Relay Type**

- 20 link relays
- 65 motor relays

- **Root Causes under investigation**

- Cu S 45
- Mechanical damage 8
- Melted plastic 6
- Plastic contamination 4
- Scratches on Contact 2
- Unknown contamination 2
- Na Cl K 2
- Sugar contamination 2
- Extra Rivet inside Relay 1
- Coil Terminal Not Welded 1


Multiple root causes so focus on largest failure mode which is currently CuS contamination.

- **Relays without initial reports**

- Under analysis 12

# 6-PANEL

© 2002-2005, Ford Motor Company





Example warranty return of relay contacts. Note the corrosion not only in the center of the contact but also on the edge (circled in red).



# 6-PANEL

© 2002-2005, Ford Motor Company

- Contact 4 showed contamination
- EDX analysis of affected area indicated the presence of sulphur and oxygen



Corrosion areas in both center and edge show presence of copper, sulphur and oxygen

# 6-PANEL

© 2002-2005, Ford Motor Company




Analysis of the edge of the contacts shows contamination getting in between the bottom copper layer and the top silver layer. Further analysis by TE shows that there is actually a crack between the copper and the silver.

# 6-PANEL

© 2002-2005, Ford Motor Company



ANALYZE  $y=f(x)$




Goal of trials at TE was to produce cracks between copper and silver layers. They were successful in doing this using their press in Portugal.

# 6-PANEL

© 2002-2005, Ford Motor Company



ANALYZE  $y=f(x)$



Humidity cycling of the part (40 degrees C, 95% humidity, 16 hours / 13 degrees C, 95% humidity, 8 hours) caused corrosion to develop in the area of the crack. This was repeated on 6 different parts with cracks between copper and silver layers created before the Doduco process. 20 parts with cracks created after the Doduco process were subjected to the same humidity test and none of them showed any signs of this type of corrosion.

## Root Cause Summary

- After the riveting tests, we can conclude that;
  - Rivets where the crack occurs in Doduco process exhibit the contamination.
  - Rivets where the crack is caused by TE's riveting process do not show any signs of contamination.
  - The set-up of the press, where the silver and copper are welded together, is the root cause for possible crack in the rivet.
  - The contamination source is Doduco
  - This contamination has copper and sulphate on its composition as seen in the complained relay.

## Containment Actions at TE/Doduco

- Check 10 rivet per bag (10,000/bag) under a microscope for evidence of cracks at TE.
- Scrap first 1000 parts every time cold weld press starts up at Doduco. It was found that cracks occur when press first starts up.
- Clean feeder tube of any rivets after every set up/tool change after 1000 rivet scrap at Doduco. It was found that set up parts could potentially get into production.
- All actions implemented Aug 5, 2011 at TE/Doduco
  - Changes above implemented at assembly plants as follows:  
C346 - 1/9/2012, U502 w/o APA(48mm) - 1/17/2012, U502 w/APA (58mm) - 2/3/2012 low volume production, CD3 - 1/17/2012

## PCA Actions at TE/Doduco

- Investigate going to a solid silver contact rather than bimetal copper/silver
- Investigate new de-burr process at Doduco in order to eliminate contaminates used in current process







# 6-PANEL

© 2002-2005, Ford Motor Company



IMPROVE  $y=f(x)$

## Solid Silver Contact Benefits vs Risk

Benefits	Risks / Issues
CuS failure mode eliminated 	Increased cost (€0.20 to €0.30 per relay) 
Reduced contact resistance at low currents 	Silver rivet into copper base - new material combination for TRW 
Reduced contact resistance at start up 	
Reduced PPMs 	


# 6-PANEL

© 2002-2005, Ford Motor Company



IMPROVE  $y=f(x)$

- ❑ When TRW commenced the Belt Drive project and selected the SPR relay, the TE standard contact type was 'bi-metal'
  - This consists of a copper rivet with a silver contact surface
- ❑ The proposed change is to move to the all silver (massive silver) contact
  - Note that the massive silver contact is now the TE standard contact type for SPR
- ❑ Except for contact forming material types, the process at Doduco is identical for the two contact types





## Next Steps

- Complete workshops at TE. Both TRW and Ford attending.
  - Week 4, 2012 – completed
  - Week 10, 2012 – planned (Frank Hofmann of TRW coordinating)
  
- Complete investigation on solid silver contacts to implement as PCA
  - Solid silver contact implementation plan follows...
  
- Investigate new de-burr process at Doduco as possible PCA
  - Estimated implementation at Ford Assy Plants: Mar, 2013

## Solid Silver Contact Implementation Plan

Action	Owner	Target Date
Life endurance testing and results	TE	10-Feb
Double life test to confirm riveting robustness	TE	10-Feb
Testing to portions of TRW test specification to be conducted	TE	2-Apr
dFMEA review	TE	13-Apr
Manufacture relays with massive silver contacts	TE	17-Feb
Manufacture motors with massive silver contacts	Nidec	16-Mar
Manufacture FOE PFSs with massive silver contacts	Kimball	16-Mar
Manufacture FNA PFSs with massive silver contacts	Anting	18-Mar
Manufacture FOE EPPs with massive silver contacts	Schalke	30-Mar
Manufacture FNA EPPs with massive silver contacts	Anting	18-Mar
EPP Level PV Testing: Tri-Temp Puma Testing (woodpecker)	Shirley	13-Apr
U502 13.5MY Gear Phase 0 with massive silver contacts (to be shipped for <PP> build)	Marion	4-May
SOP at Ford	All	Aug 2012

# 6-PANEL

© 2002-2005, Ford Motor Company



DEFINE VOICE OF THE CUSTOMER

BACK-UP SLIDES








# 6-PANEL

© 2002-2005, Ford Motor Company



IMPROVE  $y=f(x)$

## Ceramic De-Burr Benefits vs Risk

Benefits	Risks / Issues
CuS failure mode eliminated 	New process with no previous experience in Doduco 
Na Mg S failure mode eliminated 	Contamination risk from ceramic chips 
Other potential Doduco failure modes eliminated 	Replacement of ceramic chips at appropriate intervals 
Automatic process 	

# 6-PANEL

© 2002-2005, Ford Motor Company



IMPROVE  $y=f(x)$

- New de-burr machine is now under evaluation at Doduco
  - Different ceramic chip materials are being tried
  - Once the process is defined and approved by TE, TE will start relay tests to confirm it has no detrimental affect on the relay contacts



New De-Burr Machine


# 6-PANEL

© 2002-2005, Ford Motor Company



IMPROVE  $y=f(x)$

## Current Doduco Process Flow




# 6-PANEL

© 2002-2005, Ford Motor Company



IMPROVE  $y=f(x)$

## Doduco Process Flow with New De-Burr



## New De-burr Process Timing

Action	Owner	Target Date
Develop and finalise new de-burr process	Doduco	~ May '12
Relay level validation	TE	June '12
Perform gap level analysis	TE/TRW	July '12
dFMEA review	TE	July '12
Testing to portions of TRW test specification to be conducted	TE	Aug '12
Manufacture relays with new de-burr process	TE	July '12
Manufacture motors with new de-burr process	Nidec	Aug '12
Manufacture PFSs with new de-burr process	Kimball	Aug '12
Manufacture EPPs with new de-burr process	TRW Schalke	Sept '12
EPP Level Puma Testing	TRW Shirley	Nov '12
SOP at Ford	All	Mar '13



# 6-PANEL

© 2002-2005, Ford Motor Company




DEFINE VOICE OF THE CUSTOMER

Redacted  
For  
Relevance

# 6-PANEL

© 2002-2005, Ford Motor Company


## Run Chart – Fault Code



# 6-PANEL

© 2002-2005, Ford Motor Company

## Run Chart – Root Cause




# 6-PANEL

© 2002-2005, Ford Motor Company

Relay type (All) Failed at (All)

## Root Causes



# 6-PANEL


© 2002-2005, Ford Motor Company



IMPROVE  $y=f(x)$

## Containment Actions at Marion and Queretaro

QAO PUMA RUN CHART



Hot Puma testing at QTO and MAO was increased from 3000 to 4500 relay cycles on 11/17/2011 to try to force a relay failure. A script was implemented on 12/10/2011 which rejects parts that show any LICs for B3A, A3A, and B43.

Case Number	Ford DTCs	TRW Code (Symptom)	Component	Gear Location	Current Updates	Miles	VIN	Vehicle Build Date	Gear Build Date	ECU Build Date	EPP Build Date	Eng. Type	Date of Repair	Motor Build Date	other A,B,E codes	LIC's	State	Actual High-low Temp on Claim Date (F)
-------------	-----------	--------------------	-----------	---------------	-----------------	-------	-----	--------------------	-----------------	----------------	----------------	-----------	----------------	------------------	-------------------	-------	-------	--

Redacted for Relevance

Redacted for Relevance

UR0184	U2011-49 U3000-96	B6B	EPP	in process MAO	3/5- pulled EFF & stored data, to ship to QAO for further testing	2673	1FMHK8F89CGA67826	11/7/2011	11/1/2011	9/22/2011	9/23/2011	3.5L wo/APA	2/2/2012	9/1/2011	B6Bx3 C69	none	PA	46-37
UR0200	U2011-49	B6B	EPP	in process MAO	3/9- pulled EFF & stored data, to ship to QAO for further testing	4090	1FMHK8D81CGA46519	10/17/2011	10/8/2011	8/25/2011	8/25/2011	3.5L wo/APA	2/14/2012	6/28/2011	B6Bx5 C69	E12x85 E14x1 E1Ex1 E66x1 B6Bx5	NJ	46-33

2-	U502
12-	CD3
6-	C346
3-	D-Car
23-	Total

3/19/2012


	<b>Fallout%</b>	<b>Fallout</b>	<b>Total Checked</b>	<b>Good</b>
<b>2012MY U502</b>	0.005%	2	40023	40021
Redacted for Relevance				

3/30/2012


	<b>Fallout%</b>	<b>Fallout</b>	<b>Total Checked</b>	<b>Good</b>
<b>2012MY U502</b>	0.003%	3	104,336	104333
Redacted for Relevance				



### B6B %Fall-out



### B6B %Fall-out



---

**From:** Napoli, Laura (L.)  
**Sent:** Friday, January 28, 2011 11:49 AM  
**To:** 'Robert Kostadina'; 'Hemang Mehta'; 'Nick turovich'  
**Cc:** Mrozek, Robert (R.M.); Estes, Eric (E.E.); 'Abe Ghaphery'  
**Subject:** B91 on U502 at CAP

**Importance:** High

Rob, Hemang, Nick,

Please see attached emails with snapshot data and part numbers for the B91 (U3000-61) that occurred last night at CAP on the 2011 U502. This is a non-APA 3.5L TiVCT with a BB53-3200-AG gear with the following SW level:

BB53-14D003-AE

BB53-14D004-AG

This is the R6.2 level with calibration file tuned for rubber mounts and calibrated to turn off the Higher Current Contact Closure Test to resolve the BAO:

Ford needs someone from TRW to go to CAP immediately to test the vehicle before the gear is pulled out of the car. Using the snapshot data, we need you to collect CANape data while driving those conditions to see if you can duplicate.


Eric Anderson is the contact for CAP when you guys arrive. His cell phone is 773-729-0337.

From 26mile:

- Please pull the fishbone we had back in June from our other B91 issue. Rob, can you forward the latest to the team?
- Please confirm that that B91 fix is present in the AE SW.
- Please get Abe Ghaphery involved to help resolve this quickly.

The plant wants to stop ship due to this issue. We need to understand root cause quickly to be able to understand the possibility of this occurring with a customer before we have a fix implemented.

I will be sending a meeting notice to you guys for a 1pm discussion with the plant that I'll need Hemang to support.



Regards,

*Laura Napoli*

U502 EPAS  
Ford Motor Company  
Cube: 2B-G66 PDC  
Phone: 313.323.0634  
Mobile: 313.805.0482

---

**From:** Issa, Ibrahim (I.M.)  
**Sent:** Thursday, January 27, 2011 4:36 PM  
**To:** Napoli, Laura (L.); Anderson, Eric (H.)  
**Cc:** Estes, Eric (E.E.); Jackson, Bradley (B.G.); Logli, Michael (M.A.)  
**Subject:** RE: 2011 U502 Failed Steering Gear  
**Attachments:** BGA22399\_Snapshot.rtf; BGA22399\_HSCAN.rtf; BGA22399\_DIDI Info HS\_CAN.rtf

Laura,

Please see attached files for data taken from BGA22399. The vehicle did not fail for any item during dynamic/static EOL tests. Eric will be interviewing the driver and trying to duplicate the concern in the vehicle. Thanks.

Best Regards,  
Ibrahim Issa

---

**From:** Napoli, Laura (L.)  
**Sent:** Thursday, January 27, 2011 2:53 PM  
**To:** Anderson, Eric (H.); Issa, Ibrahim (I.M.)  
**Cc:** Estes, Eric (E.E.); Jackson, Bradley (B.G.)  
**Subject:** 2011 U502 Failed Steering Gear

Eric,

Please have the Electrical guys pull the snapshot data with the Ford Tool. The following screen shot shows what you need to pull...(Then scroll down below this huge picture for the rest of my questions and shipping location.)

Please ask the technician what he was doing when he lost assist. What was the driving maneuver, etc. Also, please ask him if the car was cold when he went to drive it. Was it in the garage before he took it out for the drive or had it been sitting in the parking lot for a couple hours beforehand? Please also ask him if there were any messages in the message center or lights on in the dash when it happened.

If you can duplicate the issue, I'd like to know what the message in the message center says. Then pull codes and verify you have the U3000-61 again.

Then pull the gear and ship it directly to TRW at the following address:

TRW Automotive East Building  
Attn: John Burnett  
4505 W 26 mile Rd  
Washington, MI 48094

Regards,

*Laura Napoli*

U502 EPAS  
Ford Motor Company  
Cube: 2B-G66 PDC  
Phone: 313.323.0634  
Mobile: 313.805.0482

---

**From:** Anderson, Eric (H.)  
**Sent:** Friday, January 28, 2011 10:21 AM  
**To:** Napoli, Laura (L.)  
**Cc:** Docimo, Tony (A.F.); Cantrell, David (D.D.)  
**Subject:** RE: 2011 U502 Failed Steering Gear

Hi Laura:

I drove BGA22399 again, but could not duplicate the fault. I drove through neighborhoods, on the highway and performed some tight full lock turns. I threw in some key cycle and door opens for good measure too, still no fault.

The original driver said that he began his drive with the vehicle warm, straight off the end of the line. He lost power steering assist while driving straight at about 45mph and braking. He did not report hitting any large potholes or other bumps. The power steering fault message showed up in the message center. After coming to a safe stop, he cycled the key and power steering returned.

My PVT manager is considering going stop ship for this unknown problem. We have not seen a U3000-61 code in any ECB or CQIS claim. Do you have confidence that we are selling vehicles with good EPAS gears?

The gear will be pulled today and sent to John Burnett at TRW.

Thanks,


Eric

---

**From:** Napoli, Laura (L.)  
**Sent:** Thursday, January 27, 2011 2:53 PM  
**To:** Anderson, Eric (H.); Issa, Ibrahim (I.M.)  
**Cc:** Estes, Eric (E.E.); Jackson, Bradley (B.G.)  
**Subject:** 2011 U502 Failed Steering Gear

Eric,

Please have the Electrical guys pull the snapshot data with the Ford Tool. The following screen shot shows what you need to pull...(Then scroll down below this huge picture for the rest of my questions and shipping location.)



Please ask the technician what he was doing when he lost assist. What was the driving maneuver, etc. Also, please ask him if the car was cold when he went to drive it. Was it in the garage before he took it out for the drive or had it been sitting in the parking lot for a couple hours beforehand? Please also ask him if there were any messages in the message center or lights on in the dash when it happened.

If you can duplicate the issue, I'd like to know what the message in the message center says. Then pull codes and verify you have the U3000-61 again.

Then pull the gear and ship it directly to TRW at the following address:

TRW Automotive East Building  
Attn: John Burnett  
4505 W 26 mile Rd  
Washington, MI 48094

Regards,

*Laura Napoli*

U502 EPAS  
Ford Motor Company  
Cube: 2B-G66 PDC  
Phone: 313.323.0634  
Mobile: 313.805.0482

---

**From:** Issa, Ibrahim (I.M.)  
**Sent:** Thursday, January 27, 2011 4:36 PM  
**To:** Napoli, Laura (L.); Anderson, Eric (H.)  
**Cc:** Estes, Eric (E.E.); Jackson, Bradley (B.G.); Logli, Michael (M.A.)  
**Subject:** RE: 2011 U502 Failed Steering Gear  
**Attachments:** BGA22399\_Snapshot.rtf; BGA22399\_HSCAN.rtf; BGA22399\_DIDI Info HS\_CAN.rtf

Laura,

Please see attached files for data taken from BGA22399. The vehicle did not fail for any item during dynamic/static EOL tests. Eric will be interviewing the driver and trying to duplicate the concern in the vehicle. Thanks.

Best Regards,  
Ibrahim Issa

---

**From:** Napoli, Laura (L.)  
**Sent:** Thursday, January 27, 2011 2:53 PM  
**To:** Anderson, Eric (H.); Issa, Ibrahim (I.M.)  
**Cc:** Estes, Eric (E.E.); Jackson, Bradley (B.G.)  
**Subject:** 2011 U502 Failed Steering Gear

Eric,

Please have the Electrical guys pull the snapshot data with the Ford Tool. The following screen shot shows what you need to pull...(Then scroll down below this huge picture for the rest of my questions and shipping location.)

Please ask the technician what he was doing when he lost assist. What was the driving maneuver, etc. Also, please ask him if the car was cold when he went to drive it. Was it in the garage before he took it out for the drive or had it been sitting in the parking lot for a couple hours beforehand? Please also ask him if there were any messages in the message center or lights on in the dash when it happened.

If you can duplicate the issue, I'd like to know what the message in the message center says. Then pull codes and verify you have the U3000-61 again.

Then pull the gear and ship it directly to TRW at the following address:

TRW Automotive East Building  
Attn: John Burnett  
4505 W 26 mile Rd  
Washington, MI 48094

Regards,

*Laura Napoli*

U502 EPAS  
Ford Motor Company  
Cube: 2B-G66 PDC  
Phone: 313.323.0634  
Mobile: 313.805.0482



Date: 2011-01-27 Time: 3:03:23 PM (v3.2.1)

**Please Note:**

The version of the tool you are using is over 6 months old (Released Date: 6/23/2009). Please verify you are using the latest version by visiting the Ford EESE NetCom eRoom.

Request for DiagnosticSessionControl (Service 0x10) -- [ECU ID: 0x730 (PSCM)]  
Session: 0x01 (defaultSession) [SPRMIB = False]  
Positive Response to DiagnosticSessionControl (Service 0x10) -- [ECU ID: 0x738 (PSCM)]  
Session: 0x01 (defaultSession) P2can: 50ms P2\*can: 5000ms  
Request for ReadDTCInformation (Service 0x19) -- [ECU ID: 0x730 (PSCM)]  
SubFunction: 0x04 (reportDTCSnapshotRecordByDTCNumber) [SPRMIB = False]  
DTCMaskRecord: 0xF00061  
DTCSnapshotRecordNumber: 0xFF  
Positive Response to ReadDTCInformation (Service 0x19) -- [ECU ID: 0x738 (PSCM)]  
SubFunction: 0x04 - reportDTCSnapshotRecordByDTCNumber  
-- Assuming only a single DTCSnapshotRecordNumber is being returned  
DTC: 0xF00061 [Control Module - signal calculation failure]  
Status: 0x08  
DTCSnapshotRecordNumber: 0x10  
DTCSnapshotRecordNumberOfIdentifiers: 0x0A  
DID #1: 0x3301 -- Assuming Single DID  
Snapshot Data (Hex): 06 33 02 1E D4 33 06 7F FF 00 00 00 00 00 00 00 00 00 00 33 0C 86 D1 11 7B D1 17 40 D1  
18 FF 91 F4 0C 03 84 F4 0D 00 FD AA 91

Date: 2011-01-27 Time: 2:22:09 PM (v3.2.1)

**Scanning Connection (User Initialized Connection) for ECUs:**

ECU #1 - Communication Established with IPC - Instrument Panel Cluster (IPC) Control Module (0x720) - [GGDS]:  
ECU #2 - Communication Established with SCCM - Steering Column Control Module (0x724) - [GGDS]:  
ECU #3 - Communication Established with BCM - Body Control Module (0x726) - [GGDS]:  
ECU #4 - Communication Established with ACM - Audio Front Control Module (0x727) - [GGDS]:  
ECU #5 - Communication Established with PSCM - Power Steering Control Module (0x730) - [GGDS]:  
ECU #6 - Communication Established with PAM - Parking Assist Control Module (0x736) - [GGDS]:  
ECU #7 - Communication Established with RCM - Restraints Control Module (0x737) - [GGDS]:  
ECU #8 - Communication Established with ABS - Anti-Lock Brake System (ABS) Control Module (0x760) - [GGDS]:  
ECU #9 - Communication Established with OCS - Restraints Occupant Classification System Module (0x765) - [GGDS]:  
ECU #10 - Communication Established with DSP - Audio Digital Signal Processing Module (0x783) - [GGDS]:  
ECU #11 - Communication Established with FLM - Front Lighting Control Module (0x796) - [GGDS]:  
ECU #12 - Communication Established with FCIM - Front Controls Interface Module (0x7A7) - [GGDS]:  
ECU #13 - Communication Established with APIM - Accessory Protocol Interface Module (0x7D0) - [GGDS]:  
ECU #14 - Communication Established with PCM - Powertrain Control Module (0x7E0) - [GGDS]:  
ECU #15 - Communication Established with Unknown ECU (0x7F1) - [Unknown: Assuming CAN GDS]:  
Total Number of Found ECUs: 15

Performing Iteration #1, Step 2

Communicating with IPC - Instrument Panel Cluster (IPC) Control Module (0x720):

**Requesting to Read DTCs:**

Positive Response to ReadDTCInformation (Service 0x19)  
SubFunction: 0x02 - reportDTCTByStatusMask  
DTCStatusAvailabilityMask: 0xFF  
Number of Returned DTCs: 0

Communicating with SCCM - Steering Column Control Module (0x724):

**Requesting to Read DTCs:**

Positive Response to ReadDTCInformation (Service 0x19)  
SubFunction: 0x02 - reportDTCTByStatusMask  
DTCStatusAvailabilityMask: 0xCA  
Number of Returned DTCs: 0

Communicating with BCM - Body Control Module (0x726):

**Requesting to Read DTCs:**

Positive Response to ReadDTCInformation (Service 0x19)  
SubFunction: 0x02 - reportDTCTByStatusMask  
DTCStatusAvailabilityMask: 0xCA  
Number of Returned DTCs: 0

Communicating with ACM - Audio Front Control Module (0x727):

**Requesting to Read DTCs:**

Positive Response to ReadDTCInformation (Service 0x19)  
SubFunction: 0x02 - reportDTCTByStatusMask  
DTCStatusAvailabilityMask: 0xCA  
Number of Returned DTCs: 0

Communicating with PSCM - Power Steering Control Module (0x730):

**Requesting to Read DTCs:**

**Positive Response to ReadDTCInformation (Service 0x19)**  
**SubFunction: 0x02 - reportDTCTByStatusMask**  
**DTCStatusAvailabilityMask: 0xCA**  
**Number of Returned DTCs: 1**  
**DTC #1: 0xF00061 (U3000-61) [Control Module - signal calculation failure]**  
**Status: 0x08**  
**Bit 7 - warningIndicatorRequested: 0**  
**Bit 6 - testNotCompletedThisOperationCycle: 0**  
**Bit 3 - confirmedDTC: 1**  
**Bit 1 - testFailedThisOperationCycle: 0**

Date: 2011-01-27 Time: 2:43:46 PM (v3.2.1)

**Scanning Connection (User Initialized Connection) for ECUs:**

ECU #1 - Communication Established with IPC - Instrument Panel Cluster (IPC) Control Module (0x720) - [GGDS]:  
ECU #2 - Communication Established with SCCM - Steering Column Control Module (0x724) - [GGDS]:  
ECU #3 - Communication Established with BCM - Body Control Module (0x726) - [GGDS]:  
ECU #4 - Communication Established with ACM - Audio Front Control Module (0x727) - [GGDS]:  
ECU #5 - Communication Established with PSCM - Power Steering Control Module (0x730) - [GGDS]:  
ECU #6 - Communication Established with PAM - Parking Assist Control Module (0x736) - [GGDS]:  
ECU #7 - Communication Established with RCM - Restraints Control Module (0x737) - [GGDS]:  
ECU #8 - Communication Established with ABS - Anti-Lock Brake System (ABS) Control Module (0x760) - [GGDS]:  
ECU #9 - Communication Established with OCS - Restraints Occupant Classification System Module (0x765) - [GGDS]:  
ECU #10 - Communication Established with DSP - Audio Digital Signal Processing Module (0x783) - [GGDS]:  
ECU #11 - Communication Established with FLM - Front Lighting Control Module (0x796) - [GGDS]:  
ECU #12 - Communication Established with FCIM - Front Controls Interface Module (0x7A7) - [GGDS]:  
ECU #13 - Communication Established with APIM - Accessory Protocol Interface Module (0x7D0) - [GGDS]:  
ECU #14 - Communication Established with PCM - Powertrain Control Module (0x7E0) - [GGDS]:  
ECU #15 - Communication Established with Unknown ECU (0x7F1) - [Unknown: Assuming CAN GDS]:  
Total Number of Found ECUs: 15

Performing Iteration #1, Step 1

Communicating with IPC - Instrument Panel Cluster (IPC) Control Module (0x720):

**Requesting Standard Identification DIDs:**

[0xD100] Active Diagnostic Session: defaultSession  
[0xF163] Diagnostic Specification Version: GGDS 31810161 Issue 003  
[0xF111] ECU Core Assembly Number: BB5T-14F094-BE  
[0xF113] ECU Delivery Assembly Number: BB5T-10849-GF  
[0xF110] Diagnostic Part Number: DS-BT4T-1A292-AD  
[0xF188] ECU Software Part Number: BT4T-14C026-BS  
[0xF124] ECU Main Calibration Data Number: BT4T-14C088-BN  
[0xF18C] ECU Serial Number: 0017552837411829  
[0xF15F] NOS Generation Tool Version: Vector 0x08070000810002030000  
[0xF166] NOS Message Database #1 Version: 20/January/2010 Version: 09  
[0xF167] NOS Message Database #2 Version: 3/July/2009 Version: 35  
[0xF159] NOS CAN Driver Version Number: 01.26.02

Communicating with SCCM - Steering Column Control Module (0x724):

**Requesting Standard Identification DIDs:**

[0xD100] Active Diagnostic Session: defaultSession  
[0xF163] Diagnostic Specification Version: GGDS 31810161 Issue 003  
[0xF111] ECU Core Assembly Number: BB5T-14F078-BJ  
[0xF113] ECU Delivery Assembly Number: BB5T-3F944-BJ  
[0xF110] Diagnostic Part Number: DS-BC3T-14B522-AC  
[0xF188] ECU Software Part Number: BC3T-14C579-AM  
[0xF15F] NOS Generation Tool Version: Vector 0x08060000910003000000  
[0xF166] NOS Message Database #1 Version: 1/January/2008 Version: 01

Communicating with BCM - Body Control Module (0x726):

**Requesting Standard Identification DIDs:**

[0xD100] Active Diagnostic Session: defaultSession  
[0xF163] Diagnostic Specification Version: GGDS 31810161 Issue 003  
[0xF111] ECU Core Assembly Number: BC3T-14F141-BB  
[0xF113] ECU Delivery Assembly Number: BC3T-14B476-DH  
[0xF110] Diagnostic Part Number: DS-BC3T-14B476-BB  
[0xF188] ECU Software Part Number: BC3T-14C184-BG  
[0xF15F] NOS Generation Tool Version: Vector 0x08060000810110020000  
[0xF166] NOS Message Database #1 Version: 1/January/2008 Version: 01  
[0xF159] NOS CAN Driver Version Number: 05.07.02  
[0xF15A] NOS OSEK Network Management Version Number: 03.75.03  
[0xF15C] NOS Interaction Layer Version Number: 00.00.00  
[0xF15E] NOS Network/Transport Layer Version Number: 03.04.08

[0xF160] NOS Diagnostic Version Number: 05.07.04  
[0xF161] NOS CAN Communication Layer Version Number: 02.09.00

Communicating with ACM - Audio Front Control Module (0x727):

**Requesting Standard Identification DIDs:**

[0xD100] Active Diagnostic Session: defaultSession  
[0xF163] Diagnostic Specification Version: GGDS 31810161 Issue 003  
[0xF111] ECU Core Assembly Number: BB5T-14F188-CB  
[0xF113] ECU Delivery Assembly Number: BB5T-19C107-CS  
[0xF110] Diagnostic Part Number: DS-BB5T-19C107-AB  
[0xF188] ECU Software Part Number: BB5T-14D099-CL  
[0xF124] ECU Main Calibration Data Number: BB5T-14D100-CM  
[0xF125] ECU Calibration Data 2 Number: BB5T-14D100-FL  
[0xF15F] NOS Generation Tool Version: Vector 0x08070000820064010000  
[0xF166] NOS Message Database #1 Version: 2/April/2009 Version: 34  
[0xF159] NOS CAN Driver Version Number: 01.26.02  
[0xF15A] NOS OSEK Network Management Version Number: 00.00.00  
[0xF15C] NOS Interaction Layer Version Number: 05.02.01  
[0xF15D] NOS Network Initialization Version Number: 00.00.00  
[0xF15E] NOS Network/Transport Layer Version Number: 03.04.08  
[0xF160] NOS Diagnostic Version Number: 05.07.05  
[0xF161] NOS CAN Communication Layer Version Number: 02.08.00

Communicating with PSCM - Power Steering Control Module (0x730):

**Requesting Standard Identification DIDs:**

[0xD100] Active Diagnostic Session: defaultSession  
[0xF163] Diagnostic Specification Version: GGDS 31810161 Issue 003  
[0xF111] ECU Core Assembly Number: BB53-14F079-AA  
[0xF113] ECU Delivery Assembly Number: BB53-3F964-BG  
[0xF110] Diagnostic Part Number: DS-BB53-3F964-AC  
[0xF188] ECU Software Part Number: BB53-14D003-AE  
[0xF124] ECU Main Calibration Data Number: BB53-14D004-AG  
[0xF18C] ECU Serial Number: 103341900F300WW  
[0xF15F] NOS Generation Tool Version: Vector 0x08050000610031010000  
[0xF166] NOS Message Database #1 Version: 24/August/2009 Version: 07  
[0xF159] NOS CAN Driver Version Number: 01.03.00  
[0xF15B] NOS Network Management Junior Version Number: 01.19.00  
[0xF15C] NOS Interaction Layer Version Number: 04.06.00  
[0xF15E] NOS Network/Transport Layer Version Number: 02.88.00  
[0xF160] NOS Diagnostic Version Number: 04.02.00  
[0xF161] NOS CAN Communication Layer Version Number: 01.22.00

Communicating with PAM - Parking Assist Control Module (0x736):

**Requesting Standard Identification DIDs:**

[0xD100] Active Diagnostic Session: defaultSession  
[0xF163] Diagnostic Specification Version: GGDS 31810161 Issue 003  
[0xF162] Software Download Specification: SWDL 31808456 Issue 004  
[0xF111] ECU Core Assembly Number: BC3T-14F159-AA  
[0xF113] ECU Delivery Assembly Number: BB5T-15K866-AC  
[0xF112] ECU Assembly Number: BB5T-15K866-AC  
[0xF110] Diagnostic Part Number: DS-AE00-E-12080194  
[0xF188] ECU Software Part Number: BC3T-14C090-AC  
[0xF15F] NOS Generation Tool Version: Vector 0x08050000710061000000  
[0xF166] NOS Message Database #1 Version: 2/October/2008 Version: 06  
[0xF159] NOS CAN Driver Version Number: 05.02.00  
[0xF15B] NOS Network Management Junior Version Number: 01.20.00  
[0xF15C] NOS Interaction Layer Version Number: 04.10.02  
[0xF15E] NOS Network/Transport Layer Version Number: 02.89.04  
[0xF160] NOS Diagnostic Version Number: 05.05.00  
[0xF161] NOS CAN Communication Layer Version Number: 01.32.00

Communicating with RCM - Restraints Control Module (0x737):

**Requesting Standard Identification DIDs:**

[0xD100] Active Diagnostic Session: defaultSession  
[0xF163] Diagnostic Specification Version: GGDS 31810161 Issue 003  
[0xF162] Software Download Specification: SWDL 31808456 Issue 004

[0xF111] ECU Core Assembly Number: BB5T-14F136-AC  
[0xF113] ECU Delivery Assembly Number: BB5T-14B321-AF  
[0xF110] Diagnostic Part Number: DS-BC3T-14B321-AC  
[0xF188] ECU Software Part Number: BB5T-14C028-AC  
[0xF124] ECU Main Calibration Data Number: BB5T-14C098-AF  
[0xF18C] ECU Serial Number: 7103516200000000  
[0xF15F] NOS Generation Tool Version: Vector 0x08050000810049000000  
[0xF166] NOS Message Database #1 Version: 16/April/2010 Version: 07  
[0xF167] NOS Message Database #2 Version: 25/October/2005 Version: 01  
[0xF159] NOS CAN Driver Version Number: 02.02.01  
[0xF15B] NOS Network Management Junior Version Number: 01.23.00  
[0xF15C] NOS Interaction Layer Version Number: 04.10.03  
[0xF15E] NOS Network/Transport Layer Version Number: 03.04.03  
[0xF160] NOS Diagnostic Version Number: 05.06.06  
[0xF161] NOS CAN Communication Layer Version Number: 01.32.00

Communicating with ABS - Anti-Lock Brake System (ABS) Control Module (0x760):

**Requesting Standard Identification DIDs:**

[0xD100] Active Diagnostic Session: defaultSession  
[0xF163] Diagnostic Specification Version: GGDS 31810161 Issue 003  
[0xF162] Software Download Specification: SWDL 31808456 Issue 004  
[0xF111] ECU Core Assembly Number: BB53-14F065-AC  
[0xF113] ECU Delivery Assembly Number: BB53-2C219-AE  
[0xF110] Diagnostic Part Number: DS-BB53-2C219-AC  
[0xF188] ECU Software Part Number: BB53-2D053-AE  
[0xF18C] ECU Serial Number: 0001B510C1900859  
[0xF180] Boot Software Identification: BB53-14C461-AA  
[0xF166] NOS Message Database #1 Version: 5/August/2010 Version: 11

Communicating with OCS - Restraints Occupant Classification System Module (0x765):

**Requesting Standard Identification DIDs:**

[0xD100] Active Diagnostic Session: defaultSession  
[0xF163] Diagnostic Specification Version: GGDS 31810161 Issue 003  
[0xF111] ECU Core Assembly Number: BB53-14F601-AA  
[0xF113] ECU Delivery Assembly Number: BB53-603B16-BE  
[0xF110] Diagnostic Part Number: DS-BB53-603B16-BE  
[0xF188] ECU Software Part Number: BB53-14F595-AD  
[0xF124] ECU Main Calibration Data Number: BB53-14F596-AD  
[0xF18C] ECU Serial Number: 0516283047950342  
[0xF15F] NOS Generation Tool Version: Vector 0x08070000910004000000  
[0xF166] NOS Message Database #1 Version: 5/May/2010 Version: 10  
[0xF159] NOS CAN Driver Version Number: 01.26.02  
[0xF15B] NOS Network Management Junior Version Number: 01.24.00  
[0xF15C] NOS Interaction Layer Version Number: 05.02.01  
[0xF15E] NOS Network/Transport Layer Version Number: 03.04.11  
[0xF160] NOS Diagnostic Version Number: 05.07.13  
[0xF161] NOS CAN Communication Layer Version Number: 02.09.00

Communicating with DSP - Audio Digital Signal Processing Module (0x783):

**Requesting Standard Identification DIDs:**

[0xD100] Active Diagnostic Session: defaultSession  
[0xF163] Diagnostic Specification Version: GGDS 31810161 Issue 003  
[0xF111] ECU Core Assembly Number: BT4T-14F171-BA  
[0xF113] ECU Delivery Assembly Number: BT4T-18B849-DE  
[0xF110] Diagnostic Part Number: DS-BT4T-18B849-AB  
[0xF188] ECU Software Part Number: BT4T-14C589-CH  
[0xF15F] NOS Generation Tool Version: Vector 0x08070000820043020000  
[0xF180] Boot Software Identification: BT4T-14C591-AA  
[0xF166] NOS Message Database #1 Version: 3/July/2009 Version: 35  
[0xF159] NOS CAN Driver Version Number: 01.13.00  
[0xF15B] NOS Network Management Junior Version Number: 01.24.00  
[0xF15C] NOS Interaction Layer Version Number: 04.06.00  
[0xF15E] NOS Network/Transport Layer Version Number: 03.04.03  
[0xF160] NOS Diagnostic Version Number: 05.07.03  
[0xF161] NOS CAN Communication Layer Version Number: 02.08.00  
[0xF170] NOS Bootloader Package Version Number: 05.02.02

[0xF171] NOS Bootloader Main Version Number: 03.11.00  
[0xF172] NOS Bootloader Diagnostic Version Number: 01.31.00  
[0xF173] NOS Bootloader Network/Transport Layer Version Number: 03.02.01  
[0xF174] NOS Bootloader Flash Routines Version Number: 02.09.00  
[0xF175] NOS Bootloader Hardware File Version Number: 01.24.00  
[0xF176] NOS Bootloader API Version Number: 03.21.00  
[0xF177] NOS Bootloader Security Algorithm Version Number: 01.05.00  
[0xF178] NOS Bootloader Flash I/O Version Number: 01.07.00  
[0xF17B] NOS Bootloader Memory I/O Version Number: 01.21.00

Communicating with FLM - Front Lighting Control Module (0x796):

**Requesting Standard Identification DIDs:**

[0xD100] Active Diagnostic Session: defaultSession  
[0xF163] Diagnostic Specification Version: GGDS 31810161 Issue 003  
[0xF162] Software Download Specification: **Unexpected Response**  
[0xF111] ECU Core Assembly Number: BB5T-14F116-AB  
[0xF113] ECU Delivery Assembly Number: BB5T-14C009-AD  
[0xF110] Diagnostic Part Number: DS-BT4T-13D061-AB  
[0xF188] ECU Software Part Number: BT4T-14D411-AE  
[0xF15F] NOS Generation Tool Version: Vector 0x08070000810071000000  
[0xF180] Boot Software Identification: **Unexpected Response**  
[0xF166] NOS Message Database #1 Version: 16/March/2009 Version: 05  
[0xF160] NOS Diagnostic Version Number: 05.07.02  
[0xF161] NOS CAN Communication Layer Version Number: 02.07.00  
[0xF170] NOS Bootloader Package Version Number: **Unexpected Response**  
[0xF171] NOS Bootloader Main Version Number: **Unexpected Response**  
[0xF172] NOS Bootloader Diagnostic Version Number: **Unexpected Response**  
[0xF173] NOS Bootloader Network/Transport Layer Version Number: **Unexpected Response**  
[0xF174] NOS Bootloader Flash Routines Version Number: **Unexpected Response**  
[0xF175] NOS Bootloader Hardware File Version Number: **Unexpected Response**  
[0xF176] NOS Bootloader API Version Number: **Unexpected Response**  
[0xF177] NOS Bootloader Security Algorithm Version Number: **Unexpected Response**  
[0xF178] NOS Bootloader Flash I/O Version Number: **Unexpected Response**  
[0xF17B] NOS Bootloader Memory I/O Version Number: **Unexpected Response**

Communicating with FCIM - Front Controls Interface Module (0x7A7):

**Requesting Standard Identification DIDs:**

[0xD100] Active Diagnostic Session: defaultSession  
[0xF163] Diagnostic Specification Version: GGDS 31810161 Issue 003  
[0xF111] ECU Core Assembly Number: BB5T-14F166-CB  
[0xF113] ECU Delivery Assembly Number: BB5T-18A802-CJ  
[0xF110] Diagnostic Part Number: DSBB5T-18A802-CA  
[0xF188] ECU Software Part Number: BB5T-14D017-BE  
[0xF124] ECU Main Calibration Data Number: BB5T-14D018-CE  
[0xF15F] NOS Generation Tool Version: Vector 0x08070000810042020000  
[0xF166] NOS Message Database #1 Version: 3/July/2009 Version: 35

Communicating with APIM - Accessory Protocol Interface Module (0x7D0):

**Requesting Standard Identification DIDs:**

[0xD100] Active Diagnostic Session: defaultSession  
[0xF163] Diagnostic Specification Version: GGDS 31810161 Issue 003  
[0xF111] ECU Core Assembly Number: BT4T-14F130-BA  
[0xF113] ECU Delivery Assembly Number: BT4T-14D212-AN  
[0xF110] Diagnostic Part Number: DS-BT4T-14D212-BB  
[0xF188] ECU Software Part Number: BT4T-14D205-BD  
[0xF15F] NOS Generation Tool Version: Vector 0x08070000810099020000  
[0xF166] NOS Message Database #1 Version: 19/August/2009 Version: 01  
[0xF167] NOS Message Database #2 Version: 10/July/2009 Version: 01

Communicating with PCM - Powertrain Control Module (0x7E0):

**Requesting Standard Identification DIDs:**

[0xD100] Active Diagnostic Session: defaultSession  
[0xF163] Diagnostic Specification Version: GGDS 31810161 Issue 003  
[0xF111] ECU Core Assembly Number: BT4A-12B684-DA  
[0xF113] ECU Delivery Assembly Number: BB5A-12A650-MH  
[0xF188] ECU Software Part Number: BB5A-14C204-MH

Communicating with Unknown ECU (0x7F1):

**Requesting Standard Identification DIDs:**

[0xD100] Active Diagnostic Session: **Not Supported**

[0xE21X] ECU Part Number: **Not Supported-Not Supported-Not Supported**

[0xE220] ECU Software Version Number: **Not Supported**

[0xE6F3] Diagnostic Specification Version: **Not Supported**

Parallel Query Complete!

Communicating with PAM - Parking Assist Control Module (0x736):

**Requesting to Read DTCs:**

Positive Response to ReadDTCInformation (Service 0x19)  
SubFunction: 0x02 - reportDTCByStatusMask  
DTCStatusAvailabilityMask: 0xFF  
Number of Returned DTCs: 0

Communicating with RCM - Restraints Control Module (0x737):

**Requesting to Read DTCs:**

Positive Response to ReadDTCInformation (Service 0x19)  
SubFunction: 0x02 - reportDTCByStatusMask  
DTCStatusAvailabilityMask: 0xCB  
Number of Returned DTCs: 0

Communicating with ABS - Anti-Lock Brake System (ABS) Control Module (0x760):

**Requesting to Read DTCs:**

Positive Response to ReadDTCInformation (Service 0x19)  
SubFunction: 0x02 - reportDTCByStatusMask  
DTCStatusAvailabilityMask: 0xFB  
Number of Returned DTCs: 0

Communicating with OCS - Restraints Occupant Classification System Module (0x765):

**Requesting to Read DTCs:**

Positive Response to ReadDTCInformation (Service 0x19)  
SubFunction: 0x02 - reportDTCByStatusMask  
DTCStatusAvailabilityMask: 0xFB  
Number of Returned DTCs: 0

Communicating with DSP - Audio Digital Signal Processing Module (0x783):

**Requesting to Read DTCs:**

Positive Response to ReadDTCInformation (Service 0x19)  
SubFunction: 0x02 - reportDTCByStatusMask  
DTCStatusAvailabilityMask: 0xCA  
Number of Returned DTCs: 0

Communicating with FLM - Front Lighting Control Module (0x796):

**Requesting to Read DTCs:**

Positive Response to ReadDTCInformation (Service 0x19)  
SubFunction: 0x02 - reportDTCByStatusMask  
DTCStatusAvailabilityMask: 0xCA  
Number of Returned DTCs: 0

Communicating with FCIM - Front Controls Interface Module (0x7A7):

**Requesting to Read DTCs:**

Positive Response to ReadDTCInformation (Service 0x19)  
SubFunction: 0x02 - reportDTCByStatusMask  
DTCStatusAvailabilityMask: 0xCA  
Number of Returned DTCs: 0

Communicating with APIM - Accessory Protocol Interface Module (0x7D0):

**Requesting to Read DTCs:**

Positive Response to ReadDTCInformation (Service 0x19)  
SubFunction: 0x02 - reportDTCByStatusMask  
DTCStatusAvailabilityMask: 0xCA  
Number of Returned DTCs: 0

Communicating with PCM - Powertrain Control Module (0x7E0):

**Requesting to Read DTCs:**

Positive Response to ReadDTCInformation (Service 0x19)  
SubFunction: 0x02 - reportDTCByStatusMask  
DTCStatusAvailabilityMask: 0xFF  
Number of Returned DTCs: 0

Communicating with Unknown ECU (0x7F1):

**Requesting to Read DTCs (CAN GDS):**



Negative Response to ReadDTCInformation on CAN GDS (Service 0x18)  
Response Code: 0x11 (Service Not Supported)

Parallel Query Complete!



















High Freq Vibration	Target Magnet Check	Hall and Encoder Sensitivity	Motor PCB Integrity	5V_HALL Disturbs	Dyno Test	B4E test software	Teardown	Hot Puma	IC12 Double Start-up	IC12 Regulator Output Fail	Check Motor PCB Clearance	Check Motor PCB solder Joints	Mileage					
													7812					
													1482					
													3274					
													2820					
													7486					
													13					
													14					
													2909					
													9221					
													7743					
													7743					
													1020					

Count of Root Cause




Root Cause

Count of Reference Number




EPP Build Date

Count of Reference Number




ECU Build Date

Count of Reference Number




Count of Reference Number



Root Cause  
Hall Effect - TBC  
Under Analysis  
Reg Power Up  
(blank)

Motor Build Date

Count of Reference Number



Motor PCB Date

Count of Reference Number

0  
1  
2  
3  
4  
5  
6  
7  
8  
9  
A  
B  
C  
D  
E  
F  
G  
H  
I  
J  
K  
L  
M  
N  
O  
P  
Q  
R  
S  
T  
U  
V  
W  
X  
Y  
Z  
[  
\  
]  
^  
\_  
`  
a  
b  
c  
d  
e  
f  
g  
h  
i  
j  
k  
l  
m  
n  
o  
p  
q  
r  
s  
t  
u  
v  
w  
x  
y  
z  
{  
|  
}  
~




- Root Cause
- Hall Effect - TBC
  - Under Analysis
  - Reg Power Up
  - (blank)

C12 Date Code



Count of Reference Number




Main Micro Date Code

<b>ECU</b>	<b>Micro Code</b>	<b>CS Pulse</b>	<b>Double Start</b>
1	XAA0844	Yes	
2		Yes	
3	XAA0944	Yes	
4	XAA0944	No	
5	XAA0944	Yes	
6	XAA0944	Yes	
7		No	
8	XAA0944	Yes	
9	XAO0934	Yes	
10		Yes	

Count of Reference Number

Status by Quantity of Failures



Status

- Closed
- Open

MotorMechanicalVelocity	-766	-857	-670	-5.98438	-6.69531	-5.23438
ColumnTorque	-2369	-2481	-2287	-2.31348	-2.42285	-2.2334
ColumnVelocity	354	397	227	0.345703	0.387695	0.22168
vBatt	3333	3331	3344	13.01953	13.01172	13.0625
FilteredVehicleSpeed	1959	1959	1958	30.60938	30.60938	30.59375
Filt2v5RefVoltage	12403	12403	12403	2498.163	2498.163	2498.163
AssistanceTorqueDemand	-3270	-3682	-2889	-12.7734	-14.3828	-11.2852
FilteredMechanicalVelocity	-766	-857	-670	-5.98438	-6.69531	-5.23438
QAxisCurrent	1468	1702	1275	11.46875	13.29688	9.960938
DriveStageTemperature	4109	4099	4105	41.09	40.99	41.05
TorqueLimit	25000	25000	25000	100	100	100
IgnitionOn	1	1	1	1	1	1
ASP	-6093	-6093	-6184	-6093	-6093	-6184
EcuM__rootState_active	3	3	3	3	3	3
sSystemMode__rootState_active	2	2	2	2	2	2
Padding	1796		0			
AltHallTransitionTime	437971	360001	437971	437971	360001	437971
B92FilteredMotorVelocityError	276	269	270	276	269	270
HallSensor	5	1	5	5	1	5
DiagCommutationCentrePosition	21845	10923	21845	120.0275	60.01648	120.0275
EncoderPositionRegister	1548	1543	1554	1548	1543	1554
MotorElectricalPosition	29912	22254	36795	164.3516	122.2747	202.1703
AltNewHallEvent	0	0	1	0	0	1
AltMotorElectricalVelocity	-1651	-1777	-1609	-1651	-1777	-1609
B92MotorVelocityErrorLimit	1406	1440	1395	1406	1440	1395
AltRotorDirection	-1	-1	-1	-1	-1	-1
AltMotorCommutationState	5	1	5	5	1	5
DistanceTravelled	12571795	12571795				
LifetimeCounter	760329	760329				
AccumulatedColumnMovement	18335	18335				
FastThermalEstTemperatureRise	18	0.18				
ThermalEstTemperatureRise	52	0.52				
VehicleTuneSelector	4	4				
MotorTuneSelector	1	1				
EmulationModeStatus	0	0				
PDCStatus	1	1				
PowerOffDriveStageTemperature	4678	46.78				
CPU_PeakLoadHold	13577	13577				
TorqueReInstatmentFlag	1	1				
IncompletePowerDownTestCount	1	1				
padding	0					
LRE_PositionState	0	0				
PositionExtrapActive	1	1				
EncoderOffset	0	0				
MotorReversal	1	1				

MotorMechanicalVelocity	22	20	18	0.171875	0.15625
ColumnTorque	106	91	96	0.103516	0.088867
ColumnVelocity	-9	-9	-9	-0.00879	-0.00879
vBatt	3305	3305	3309	12.91016	12.91016
FilteredVehicleSpeed	1816	1816	1816	28.375	28.375
Filt2v5RefVoltage	12434	12434	12434	2504.407	2504.407
AssistanceTorqueDemand	4	-55	33	0.015625	-0.21484
FilteredMechanicalVelocity	22	20	18	0.171875	0.15625
QAxisCurrent	-18	11	7	-0.14063	0.085938
DriveStageTemperature	4799	4806	4809	47.99	48.06
TorqueLimit	25000	25000	25000	100	100
IgnitionOn	1	1	1	1	1
ASP	-86	-86	-86	-86	-86
EcuM__rootState_active	3	3	3	3	3
sSystemMode__rootState_active	2	2	2	2	2
Padding	2446		0		
AltHallTransitionTime	57371899	57371899	57371899	57371899	57371899
B92FilteredMotorVelocityError	0	0	0	0	0
HallSensor	2	2	2	2	2
DiagCommutationCentrePosition	54613	54613	54613	300.0714	300.0714
EncoderPositionRegister	65339	65339	65339	65339	65339
MotorElectricalPosition	667	667	65520	3.664835	3.664835
AltNewHallEvent	1	0	0	1	0
AltMotorElectricalVelocity	21	19	18	21	19
B92MotorVelocityErrorLimit	965	965	964	965	965
AltRotorDirection	-1	-1	-1	-1	-1
AltMotorCommutationState	2	2	2	2	2
DistanceTravelled	4538883	4538883			
LifetimeCounter	423415	423415			
AccumulatedColumnMovement	10821	10821			
FastThermalEstTemperatureRise	22	0.22			
ThermalEstTemperatureRise	132	1.32			
VehicleTuneSelector	3	3			
MotorTuneSelector	1	1			
EmulationModeStatus	0	0			
PDCStatus	1	1			
PowerOffDriveStageTemperature	4633	46.33			
CPU_PeakLoadHold	12960	12960			
TorqueRelInstatmentFlag	1	1			
IncompletePowerDownTestCount	1	1			
padding	0				
LRE_PositionState	0	0			
PositionExtrapActive	0	0			
EncoderOffset	0	0			
MotorReversal	0	0			

0.140625  
0.09375  
-0.00879  
12.92578  
28.375  
2504.407  
0.128906  
0.140625  
0.054688  
48.09  
100  
1  
-86  
3  
2

57371899  
0  
2  
300.0714  
65339  
360  
0  
18  
964  
-1  
2

MotorMechanicalVelocity	0	0	0	0	0
ColumnTorque	2015	2140	2273	1.967773	2.089844
ColumnVelocity	0	0	0	0	0
vBatt	3584	3592	3586	14	14.03125
FilteredVehicleSpeed	0	0	0	0	0
Filt2v5RefVoltage	12515	12515	12514	2520.721	2520.721
AssistanceTorqueDemand	3707	4265	4643	14.48047	16.66016
FilteredMechanicalVelocity	0	0	0	0	0
QAxisCurrent	-1683	-1925	-2111	-13.1484	-15.0391
DriveStageTemperature	4661	4657	4660	46.61	46.57
TorqueLimit	25000	25000	25000	100	100
IgnitionOn	1	1	1	1	1
ASP	0	0	0	0	0
EcuM__rootState_active	3	3	3	3	3
sSystemMode__rootState_active	2	2	2	2	2
Padding	4655		0		
AltHallTransitionTime	3959996	3959996	3959996	3959996	3959996
B92FilteredMotorVelocityError	0	0	0	0	0
HallSensor	4	4	4	4	4
DiagCommutationCentrePosition	32768	32768	32768	180.044	180.044
EncoderPositionRegister	2	2	2	2	2
MotorElectricalPosition	49140	49140	49140	270	270
AltNewHallEvent	1	0	0	1	0
AltMotorElectricalVelocity	0	0	0	0	0
B92MotorVelocityErrorLimit	960	960	960	960	960
AltRotorDirection	-1	-1	-1	-1	-1
AltMotorCommutationState	4	4	4	4	4
DistanceTravelled	5268408	5268408			
LifetimeCounter	372483	372483			
AccumulatedColumnMovement	8911	8911			
FastThermalEstTemperatureRise	61	0.61			
ThermalEstTemperatureRise	236	2.36			
VehicleTuneSelector	4	4			
MotorTuneSelector	1	1			
EmulationModeStatus	0	0			
PDCStatus	1	1			
PowerOffDriveStageTemperature	5200	52			
CPU_PeakLoadHold	13540	13540			
TorqueRelInstatmentFlag	1	1			
IncompletePowerDownTestCount	1	1			
padding	0				
LRE_PositionState	0	0			
PositionExtrapActive	0	0			
EncoderOffset	0	0			
MotorReversal	0	0			

0  
2.219727  
0  
14.00781  
0  
2520.52  
18.13672  
0  
-16.4922  
46.6  
100  
1  
0  
3  
2  
  
3959996  
0  
4  
180.044  
2  
270  
0  
0  
960  
-1  
4



MotorMechanicalVelocity	122	94	73	0.953125	0.734375
ColumnTorque	-1426	-1482	-1568	-1.39258	-1.44727
ColumnVelocity	-3	-3	-3	-0.00293	-0.00293
vBatt	3304	3298	3306	12.90625	12.88281
FilteredVehicleSpeed	0	0	0	0	0
Filt2v5RefVoltage	12397	12397	12397	2496.954	2496.954
AssistanceTorqueDemand	-2105	-2408	-2771	-8.22266	-9.40625
FilteredMechanicalVelocity	122	94	73	0.953125	0.734375
QAxisCurrent	1042	1154	1316	8.140625	9.015625
DriveStageTemperature	3140	3140	3137	31.4	31.4
TorqueLimit	25000	25000	25000	100	100
IgnitionOn	1	1	1	1	1
ASP	213	213	213	213	213
EcuM__rootState_active	3	3	3	3	3
sSystemMode__rootState_active	2	2	2	2	2
Padding	2642		0		
AltHallTransitionTime	1373942	1373942	1373942	1373942	1373942
B92FilteredMotorVelocityError	80	78	76	80	78
HallSensor	1	1	1	1	1
DiagCommutationCentrePosition	10923	10923	10923	60.01648	60.01648
EncoderPositionRegister	65405	65406	65406	65405	65406
MotorElectricalPosition	62790	64155	64155	345	352.5
AltNewHallEvent	0	0	0	0	0
AltMotorElectricalVelocity	0	0	0	0	0
B92MotorVelocityErrorLimit	960	960	960	960	960
AltRotorDirection	1	1	1	1	1
AltMotorCommutationState	1	1	1	1	1
DistanceTravelled	2385052	2385052			
LifetimeCounter	308188	308188			
AccumulatedColumnMovement	11188	11188			
FastThermalEstTemperatureRise	5	0.05			
ThermalEstTemperatureRise	90	0.9			
VehicleTuneSelector	3	3			
MotorTuneSelector	1	1			
EmulationModeStatus	0	0			
PDCStatus	1	1			
PowerOffDriveStageTemperature	3171	31.71			
CPU_PeakLoadHold	12847	12847			
TorqueRelInstatmentFlag	1	1			
IncompletePowerDownTestCount	1	1			
padding	0				
LRE_PositionState	0	0			
PositionExtrapActive	0	0			
EncoderOffset	0	0			
MotorReversal	0	0			

0.570313  
-1.53125  
-0.00293  
12.91406  
0  
2496.954  
-10.8242  
0.570313  
10.28125  
31.37  
100  
1  
213  
3  
2  
  
1373942  
76  
1  
60.01648  
65406  
352.5  
0  
0  
960  
1  
1

MotorMechanicalVelocity	0	0	0	0
ColumnTorque	2185	2178	2212	2.133789
ColumnVelocity	0	0	0	0
vBatt	3499	3501	3495	13.66797
FilteredVehicleSpeed	0	0	0	0
Filt2v5RefVoltage	12526	12526	12526	2522.937
AssistanceTorqueDemand	1379	1502	1365	5.386719
FilteredMechanicalVelocity	0	0	0	0
QAxisCurrent	-806	-863	-832	-6.29688
DriveStageTemperature	2530	2530	2521	25.3
TorqueLimit	25000	25000	25000	100
IgnitionOn	1	1	1	1
ASP	0	0	0	0
EcuM__rootState_active	3	3	3	3
sSystemMode__rootState_active	2	2	2	2
AltHallTransitionTime	1469965	1469965	1469965	1469965
B92FilteredMotorVelocityError	0	0	0	0
HallSensor	4	4	4	4
DiagCommutationCentrePosition	32768	32768	32768	180.044
EncoderPositionRegister	65535	65535	0	65535
MotorElectricalPosition	47775	47775	49140	262.5
AltNewHallEvent	0	0	1	0
AltMotorElectricalVelocity	0	0	0	0
B92MotorVelocityErrorLimit	960	960	960	960
AltRotorDirection	-1	-1	-1	-1
AltMotorCommutationState	4	4	4	4
DistanceTravelled	4681441	4681441		
LifetimeCounter	418815	418815		
AccumulatedColumnMovement	16348	16348		
FastThermalEstTemperatureRise	29	0.29		
ThermalEstTemperatureRise	88	0.88		
VehicleTuneSelector	1	1		
MotorTuneSelector	0	0		
EmulationModeStatus	0	0		
PDCStatus	1	1		
PowerOffDriveStageTemperature	4002	40.02		
CPU_PeakLoadHold	13543	13543		
TorqueRelInstatmentFlag	1	1		
IncompletePowerDownTestCount	1	1		
padding	0			
LRE_PositionState	0	0		
PositionExtrapActive	0	0		
EncoderOffset	0	0		
MotorReversal	0	0		

0	0
2.126953	2.160156
0	0
13.67578	13.65234
0	0
2522.937	2522.937
5.867188	5.332031
0	0
-6.74219	-6.5
25.3	25.21
100	100
1	1
0	0
3	3
2	2
1469965	1469965
0	0
4	4
180.044	180.044
65535	0
262.5	270
0	1
0	0
960	960
-1	-1
4	4

MotorMechanicalVelocity	0	0	0	0
ColumnTorque	586	588	589	0.572266
ColumnVelocity	-3	-3	-3	-0.00293
vBatt	3748	3758	3750	14.64063
FilteredVehicleSpeed	0	0	0	0
Filt2v5RefVoltage	12412	12412	12412	2499.976
AssistanceTorqueDemand	3	3	3	0.011719
FilteredMechanicalVelocity	0	0	0	0
QAxisCurrent	5	5	-2	0.039063
DriveStageTemperature	4331	4327	4327	43.31
TorqueLimit	25000	25000	25000	100
IgnitionOn	1	1	1	1
ASP	0	0	0	0
EcuM__rootState_active	3	3	3	3
sSystemMode__rootState_active	2	2	2	2
AltHallTransitionTime	1.57E+09	1.57E+09	1.57E+09	1.57E+09
B92FilteredMotorVelocityError	0	0	0	0
HallSensor	0	0	0	0
DiagCommutationCentrePosition	0	0	0	0
EncoderPositionRegister	63316	63316	63316	63316
MotorElectricalPosition	34109	34109	34109	187.4121
AltNewHallEvent	0	1	0	0
AltMotorElectricalVelocity	0	0	0	0
B92MotorVelocityErrorLimit	960	960	960	960
AltRotorDirection	0	0	0	0
AltMotorCommutationState	0	0	0	0
DistanceTravelled	21789	21789		
LifetimeCounter	6922	6922		
AccumulatedColumnMovement	364	364		
FastThermalEstTemperatureRise	212	2.12		
ThermalEstTemperatureRise	122	1.22		
VehicleTuneSelector	1	1		
MotorTuneSelector	0	0		
EmulationModeStatus	0	0		
PDCStatus	1	1		
PowerOffDriveStageTemperature	4439	44.39		
CPU_PeakLoadHold	13463	13463		
TorqueRelInstatmentFlag	1	1		
IncompletePowerDownTestCount	1	1		
padding	0			
LRE_PositionState	0	0		
PositionExtrapActive	0	0		
EncoderOffset	0	0		
MotorReversal	0	0		

0	0
0.574219	0.575195
-0.00293	-0.00293
14.67969	14.64844
0	0
2499.976	2499.976
0.011719	0.011719
0	0
0.039063	-0.01563
43.27	43.27
100	100
1	1
0	0
3	3
2	2
1.57E+09	1.57E+09
0	0
0	0
0	0
63316	63316
187.4121	187.4121
1	0
0	0
960	960
0	0
0	0

MotorMechanicalVelocity	0	0	0	0
ColumnTorque	2523	1818	2170	2.463867
ColumnVelocity	0	0	0	0
vBatt	3687	3691	3679	14.40234
FilteredVehicleSpeed	50	48	50	0.78125
Filt2v5RefVoltage	12489	12489	12489	2515.485
AssistanceTorqueDemand	2565	1519	1901	10.01953
FilteredMechanicalVelocity	0	0	0	0
QAxisCurrent	-1363	-789	-1012	-10.6484
DriveStageTemperature	2874	2890	2877	28.74
TorqueLimit	25000	25000	25000	100
IgnitionOn	1	1	1	1
ASP	0	0	0	0
EcuM__rootState_active	3	3	3	3
sSystemMode__rootState_active	2	2	2	2
AltHallTransitionTime	6929961	6929961	6929961	6929961
B92FilteredMotorVelocityError	0	0	0	0
HallSensor	2	2	2	2
DiagCommutationCentrePosition	54613	54613	54613	300.0714
EncoderPositionRegister	0	0	0	0
MotorElectricalPosition	4095	4095	4095	22.5
AltNewHallEvent	0	1	0	0
AltMotorElectricalVelocity	0	0	0	0
B92MotorVelocityErrorLimit	960	960	960	960
AltRotorDirection	-1	-1	-1	-1
AltMotorCommutationState	2	2	2	2
DistanceTravelled	20793	20793		
LifetimeCounter	5907	5907		
AccumulatedColumnMovement	1004	1004		
FastThermalEstTemperatureRise	63	0.63		
ThermalEstTemperatureRise	141	1.41		
VehicleTuneSelector	1	1		
MotorTuneSelector	0	0		
EmulationModeStatus	0	0		
PDCStatus	1	1		
PowerOffDriveStageTemperature	2761	27.61		
CPU_PeakLoadHold	13442	13442		
TorqueRelInstatmentFlag	1	1		
IncompletePowerDownTestCount	1	1		
padding	0			
LRE_PositionState	0	0		
PositionExtrapActive	0	0		
EncoderOffset	0	0		
MotorReversal	0	0		

0	0
1.775391	2.119141
0	0
14.41797	14.37109
0.75	0.78125
2515.485	2515.485
5.933594	7.425781
0	0
-6.16406	-7.90625
28.9	28.77
100	100
1	1
0	0
3	3
2	2
6929961	6929961
0	0
2	2
300.0714	300.0714
0	0
22.5	22.5
1	0
0	0
960	960
-1	-1
2	2



MotorMechanicalVelocity	815	630	487	6.367188
ColumnTorque	-2756	-2988	-3536	-2.69141
ColumnVelocity	-95	-22	-6	-0.09277
vBatt	3308	3310	3321	12.92188
FilteredVehicleSpeed	318	318	319	4.96875
Filt2v5RefVoltage	12548	12548	12548	2527.368
AssistanceTorqueDemand	-4441	-5984	-8978	-17.3477
FilteredMechanicalVelocity	815	630	487	6.367188
QAxisCurrent	3154	3879	4876	24.64063
DriveStageTemperature	5675	5669	5675	56.75
TorqueLimit	25000	25000	25000	100
IgnitionOn	1	1	1	1
ASP	0	0	0	0
EcuM__rootState_active	3	3	3	3
sSystemMode__rootState_active	2	2	2	2
AltHallTransitionTime	347999	347999	347999	347999
B92FilteredMotorVelocityError	176	331	323	176
HallSensor	4	4	4	4
DiagCommutationCentrePosition	32768	32768	32768	180.044
EncoderPositionRegister	2005	2005	2006	2005
MotorElectricalPosition	13634	13634	14999	74.91209
AltNewHallEvent	1	0	0	1
AltMotorElectricalVelocity	0	0	0	0
B92MotorVelocityErrorLimit	960	960	960	960
AltRotorDirection	1	1	1	1
AltMotorCommutationState	4	4	4	4

DistanceTravelled	12047049	12047049		
LifetimeCounter	1056744	1056744		
AccumulatedColumnMovement	27303	27303		
FastThermalEstTemperatureRise	18	0.18		
ThermalEstTemperatureRise	40	0.4		
VehicleTuneSelector	1	1		
MotorTuneSelector	0	0		
EmulationModeStatus	0	0		
PDCStatus	1	1		
PowerOffDriveStageTemperature	5648	56.48		
CPU_PeakLoadHold	13551	13551		
TorqueRelInstatmentFlag	1	1		
IncompletePowerDownTestCount	1	1		
padding	0			
LRE_PositionState	0	0		
PositionExtrapActive	1	1		
EncoderOffset	0	0		
MotorReversal	0	0		

4.921875	3.804688
-2.91797	-3.45313
-0.02148	-0.00586
12.92969	12.97266
4.96875	4.984375
2527.368	2527.368
-23.375	-35.0703
4.921875	3.804688
30.30469	38.09375
56.69	56.75
100	100
1	1
0	0
3	3
2	2
347999	347999
331	323
4	4
180.044	180.044
2005	2006
74.91209	82.41209
0	0
0	0
960	960
1	1
4	4

	0	1	2	0	1
MotorMechanicalVelocity	0	0	0	0	0
ColumnTorque	1207	1230	1207	1.178711	1.201172
ColumnVelocity	-3	-3	-3	-0.00293	-0.00293
vBatt	3519	3527	3527	13.74609	13.77734
FilteredVehicleSpeed	3907	3907	3908	61.04688	61.04688
Filt2v5RefVoltage	12471	12471	12470	2511.859	2511.859
AssistanceTorqueDemand	209	303	-51	0.816406	1.183594
FilteredMechanicalVelocity	0	0	0	0	0
QAxisCurrent	-92	-141	30	-0.71875	-1.10156
DriveStageTemperature	4586	4586	4579	45.86	45.86
TorqueLimit	25000	25000	25000	100	100
IgnitionOn	1	1	1	1	1
ASP	100	100	100	1.5625	1.5625
EcuM__rootState_active	3	3	3	3	3
sSystemMode__rootState_active	2	2	2	2	2
AltHallTransitionTime	14694005	14694005	14694005	14694005	14694005
B92FilteredMotorVelocityError	0	0	0	0	0
HallSensor	6	6	6	6	6
DiagCommutationCentrePosition	43691	43691	43691	240.0604	240.0604
EncoderPositionRegister	65440	65440	65440	65440	65440
MotorElectricalPosition	58695	58695	58695	322.5	322.5
				82.43956	82.43956
AltNewHallEvent	0	0	1	0	0
AltMotorElectricalVelocity	0	0	0	0	0
B92MotorVelocityErrorLimit	960	960	960	960	960
AltRotorDirection	-1	-1	-1	-1	-1
AltMotorCommutationState	6	6	6	6	6
DistanceTravelled	6917091				
LifetimeCounter	613650				
AccumulatedColumnMovement	16130				
FastThermalEstTemperatureRise	21				
ThermalEstTemperatureRise	62				
VehicleTuneSelector	2				
MotorTuneSelector	0				
EmulationModeStatus	0				
PDCStatus	1				
PowerOffDriveStageTemperature	4322				
CPU_PeakLoadHold	13384				
TorqueReInstatmentFlag	1				
IncompletePowerDownTestCount	1				
padding	0				
LRE_PositionState	0				
PositionExtrapActive	0				
EncoderOffset	0				
MotorReversal	0				

Journey time to Fault - Fault 1  
Journey time to Fault - Fault 2  
Journey time to Fault - Fault 3

Journey time to Fault - Fault 4  
Journey time to Fault - Fault 5  
Journey time to Fault - Fault 6  
Journey time to Fault - Fault 7  
Journey time to Fault - Fault 8

B9A LICs

?  
?  
?

2  
0  
1.178711  
-0.00293  
13.77734  
61.0625  
2511.658  
-0.19922  
0  
0.234375  
45.79  
100  
1  
1.5625  
3  
2  
14694005  
0  
6  
240.0604  
65440  
322.5  
82.43956  
1  
0  
960  
-1  
6

	0	1	2	0	1
MotorMechanicalVelocity	-4	-7	-5	-0.03125	-0.05469
ColumnTorque	2111	1922	2005	2.061523	1.876953
ColumnVelocity	0	0	0	0	0
vBatt	3503	3505	3501	13.68359	13.69141
FilteredVehicleSpeed	0	0	0	0	0
Filt2v5RefVoltage	12418	12418	12418	2501.184	2501.184
AssistanceTorqueDemand	1382	1045	1176	5.398438	4.082031
FilteredMechanicalVelocity	-4	-7	-5	-0.03125	-0.05469
QAxisCurrent	-747	-604	-663	-5.83594	-4.71875
DriveStageTemperature	5946	5946	5953	59.46	59.46
TorqueLimit	25000	25000	25000	100	100
IgnitionOn	1	1	1	1	1
ASP	-1046	-1052	-1046	-16.3438	-16.4375
EcuM__rootState_active	3	3	3	3	3
sSystemMode__rootState_active	2	2	2	2	2
AltHallTransitionTime	1866095	1866095	1866095	1866095	1866095
B92FilteredMotorVelocityError	0	0	0	0	0
HallSensor	6	6	6	6	6
DiagCommutationCentrePosition	43691	43691	43691	240.0604	240.0604
EncoderPositionRegister	65461	65462	65461	65461	65462
MotorElectricalPosition	57330	58695	57330	315	322.5
AltNewHallEvent	0	0	0	0	0
AltMotorElectricalVelocity	0	0	0	0	0
B92MotorVelocityErrorLimit	960	960	960	960	960
AltRotorDirection	-1	-1	-1	-1	-1
AltMotorCommutationState	6	6	6	6	6
DistanceTravelled	6458112				
LifetimeCounter	527336				
AccumulatedColumnMovement	11993				
FastThermalEstTemperatureRise	12				
ThermalEstTemperatureRise	16				
VehicleTuneSelector	2				
MotorTuneSelector	0				
EmulationModeStatus	0				
PDCStatus	1				
PowerOffDriveStageTemperature	4490				
CPU_PeakLoadHold	13376				
TorqueReInstatmentFlag	1				
IncompletePowerDownTestCount	1				
padding	0				
LRE_PositionState	0				
PositionExtrapActive	0				
EncoderOffset	0				
MotorReversal	0				
Journey time to Fault - Fault 1					
Journey time to Fault - Fault 2					
Journey time to Fault - Fault 3					
Journey time to Fault - Fault 4					

Journey time to Fault - Fault 5  
Journey time to Fault - Fault 6  
Journey time to Fault - Fault 7  
Journey time to Fault - Fault 8

B9A LICs

?  
?  
?

2  
-0.03906  
1.958008  
0  
13.67578  
0  
2501.184  
4.59375  
-0.03906  
-5.17969  
59.53  
100  
1  
-16.3438  
3  
2  
1866095  
0  
6  
240.0604  
65461  
315  
0  
0  
960  
-1  
6



	0	1	2	0	1
MotorMechanicalVelocity	505	390	301	3.945313	3.046875
ColumnTorque	-3145	-3475	-4099	-3.07129	-3.39355
ColumnVelocity	-20	-5	-3	-0.01953	-0.00488
vBatt	3545	3547	3540	13.84766	13.85547
FilteredVehicleSpeed	1139	1138	1138	17.79688	17.78125
Filt2v5RefVoltage	12419	12419	12419	2501.385	2501.385
AssistanceTorqueDemand	-4028	-5903	-8984	-15.7344	-23.0586
FilteredMechanicalVelocity	505	390	301	3.945313	3.046875
QAxisCurrent	2641	3463	4733	20.63281	27.05469
DriveStageTemperature	5391	5397	5387	53.91	53.97
TorqueLimit	25000	25000	25000	100	100
IgnitionOn	1	1	1	1	1
ASP	-6685	-6694	-6715	-104.453	-104.594
EcuM__rootState_active	3	3	3	3	3
sSystemMode__rootState_active	2	2	2	2	2
AltHallTransitionTime	431844	431844	431844	431844	431844
B92FilteredMotorVelocityError	260	254	248	260	254
HallSensor	2	2	2	2	2
DiagCommutationCentrePosition	54613	54613	54613	300.0714	300.0714
EncoderPositionRegister	1190	1190	1191	1190	1190
MotorElectricalPosition	36839	36839	37742	202.4121	202.4121
AltNewHallEvent	0	0	0	0	0
AltMotorElectricalVelocity	0	0	0	0	0
B92MotorVelocityErrorLimit	960	960	960	960	960
AltRotorDirection	1	1	1	1	1
AltMotorCommutationState	2	2	2	2	2
DistanceTravelled	10586896				
LifetimeCounter	602166				
AccumulatedColumnMovement	13285				
FastThermalEstTemperatureRise	2				
ThermalEstTemperatureRise	7				
VehicleTuneSelector	2				
MotorTuneSelector	0				
EmulationModeStatus	0				
PDCStatus	1				
PowerOffDriveStageTemperature	4167				
CPU_PeakLoadHold	13358				
TorqueReInstatmentFlag	1				
IncompletePowerDownTestCount	1				
padding	0				
LRE_PositionState	0				
PositionExtrapActive	1				
EncoderOffset	0				
MotorReversal	0				
Journey time to Fault - Fault 1					
Journey time to Fault - Fault 2					
Journey time to Fault - Fault 3					
Journey time to Fault - Fault 4					

Journey time to Fault - Fault 5  
Journey time to Fault - Fault 6  
Journey time to Fault - Fault 7  
Journey time to Fault - Fault 8

B9A LICs

?  
?  
?

2  
2.351563  
-4.00293  
-0.00293  
13.82813  
17.78125  
2501.385  
-35.0938  
2.351563  
36.97656  
53.87  
100  
1  
-104.922  
3  
2  
431844  
248  
2  
300.0714  
1191  
207.3736  
0  
0  
960  
1  
2

	0	1	2	0	1
MotorMechanicalVelocity	1394	1171	1804	10.89063	9.148438
ColumnTorque	-4871	-6926	-4145	-4.75684	-6.76367
ColumnVelocity	-86	-161	-380	-0.08398	-0.15723
vBatt	3415	3356	3346	13.33984	13.10938
FilteredVehicleSpeed	0	0	0	0	0
Filt2v5RefVoltage	12363	12363	12363	2490.106	2490.106
AssistanceTorqueDemand	-21690	-28672	-16245	-84.7266	-112
FilteredMechanicalVelocity	1394	1171	1804	10.89063	9.148438
QAxisCurrent	12262	13432	10482	95.79688	104.9375
DriveStageTemperature	4128	4142	4132	41.28	41.42
TorqueLimit	25000	25000	25000	100	100
IgnitionOn	1	1	1	1	1
ASP	-17444	-17473	-17425	-272.563	-273.016
EcuM__rootState_active	3	3	3	3	3
sSystemMode__rootState_active	2	2	2	2	2
AltHallTransitionTime	299999	197944	179944	299999	197944
B92FilteredMotorVelocityError	591	763	413	591	763
HallSensor	6	4	4	6	4
DiagCommutationCentrePosition	43691	32768	32768	240.0604	180.044
EncoderPositionRegister	3062	3059	3060	3062	3059
MotorElectricalPosition	17331	14999	14999	95.22527	82.41209
AltNewHallEvent	1	1	1	1	1
AltMotorElectricalVelocity	0	0	0	0	0
B92MotorVelocityErrorLimit	960	960	960	960	960
AltRotorDirection	1	-1	1	1	-1
AltMotorCommutationState	6	4	4	6	4

DistanceTravelled	19063512
LifetimeCounter	1665106
AccumulatedColumnMovement	36558
FastThermalEstTemperatureRise	12
ThermalEstTemperatureRise	17
VehicleTuneSelector	2
MotorTuneSelector	0
EmulationModeStatus	0
PDCStatus	1
PowerOffDriveStageTemperature	3472
CPU_PeakLoadHold	13351
TorqueReInstatmentFlag	1
IncompletePowerDownTestCount	1
padding	0
LRE_PositionState	0
PositionExtrapActive	1
EncoderOffset	0
MotorReversal	0

Journey time to Fault - Fault 1  
Journey time to Fault - Fault 2  
Journey time to Fault - Fault 3  
Journey time to Fault - Fault 4

Journey time to Fault - Fault 5  
Journey time to Fault - Fault 6  
Journey time to Fault - Fault 7  
Journey time to Fault - Fault 8

B9A LICs

?  
?  
?

2  
14.09375  
-4.04785  
-0.37109  
13.07031  
0  
2490.106  
-63.457  
14.09375  
81.89063  
41.32  
100  
1  
-272.266  
3  
2  
179944  
413  
4  
180.044  
3060  
82.41209  
1  
0  
960  
1  
4

				0
MotorMechanicalVelocity	0	0	0	0
ColumnTorque	-51	-43	-48	-0.0498
ColumnVelocity	0	0	0	0
vBatt	3615	3616	3609	14.12109
FilteredVehicleSpeed	0	0	0	0
Filt2v5RefVoltage	12396	12396	12396	2496.753
AssistanceTorqueDemand	-24	-24	0	-0.09375
FilteredMechanicalVelocity	0	0	0	0
QAxisCurrent	24	1	27	0.1875
DriveStageTemperature	2080	2075	2075	20.8
TorqueLimit	25000	25000	25000	100
IgnitionOn	1	1	1	1
ASP	0	0	0	0
EcuM__rootState_active	3	3	3	3
sSystemMode__rootState_active	2	2	2	2
AltHallTransitionTime	1.91E+09	1.91E+09	1.91E+09	1.91E+09
B92FilteredMotorVelocityError	0	0	0	0
HallSensor	3	3	3	3
DiagCommutationCentrePosition	0	0	0	0
EncoderPositionRegister	0	0	0	0
MotorElectricalPosition	49140	49140	49140	270
AltNewHallEvent	0	1	0	0
AltMotorElectricalVelocity	0	0	0	0
B92MotorVelocityErrorLimit	960	960	960	960
AltRotorDirection	1	1	1	1
AltMotorCommutationState	3	3	3	3

DistanceTravelled	6169085	6169085		
LifetimeCounter	557584	557584		
AccumulatedColumnMovement	18426	18426		
FastThermalEstTemperatureRise	14	1.4		
ThermalEstTemperatureRise	38	3.8		
VehicleTuneSelector	2	2		
MotorTuneSelector	0	0		
EmulationModeStatus	0	0		
PDCStatus	1	Not scaled		
PowerOffDriveStageTemperature	4619	46.19		
CPU_PeakLoadHold	13484	Not scaled		
TorqueReInstatmentFlag	1	Not scaled		
IncompletePowerDownTestCount	1	Not scaled		
padding	0	Not scaled		
LRE_PositionState	0	Not scaled		
PositionExtrapActive	0	Not scaled		
EncoderOffset	0	Not scaled		
MotorReversal	0	Not scaled		

1	2
0	0
-0.04199	-0.04688
0	0
14.125	14.09766
0	0
2496.753	2496.753
-0.09375	0
0	0
0.007813	0.210938
20.75	20.75
100	100
1	1
0	0
3	3
2	2
1.91E+09	1.91E+09
0	0
3	3
0	0
0	0
270	270
1	0
0	0
960	960
1	1
3	3



				0
MotorMechanicalVelocity	-92	-154	-119	-0.71875
ColumnTorque	3544	3215	3335	3.460938
ColumnVelocity	0	0	0	0
vBatt	3450	3458	3454	13.47656
FilteredVehicleSpeed	1120	1120	1120	17.5
Filt2v5RefVoltage	12435	12435	12435	2504.608
AssistanceTorqueDemand	5736	4110	4709	22.40625
FilteredMechanicalVelocity	-92	-154	-119	-0.71875
QAxisCurrent	-3117	-2347	-2590	-24.3516
DriveStageTemperature	4020	4027	4027	40.2
TorqueLimit	25000	25000	25000	100
IgnitionOn	1	1	1	1
ASP	0	0	0	0
EcuM__rootState_active	3	3	3	3
sSystemMode__rootState_active	2	2	2	2
AltHallTransitionTime	857876	857876	857876	857876
B92FilteredMotorVelocityError	235	181	241	235
HallSensor	6	6	6	6
DiagCommutationCentrePosition	43691	43691	43691	240.0604
EncoderPositionRegister	60090	60090	60089	60090
MotorElectricalPosition	58695	58695	57330	322.5
AltNewHallEvent	0	1	0	0
AltMotorElectricalVelocity	0	0	0	0
B92MotorVelocityErrorLimit	960	960	960	960
AltRotorDirection	-1	-1	-1	-1
AltMotorCommutationState	6	6	6	6

DistanceTravelled	26313320	26313320	
LifetimeCounter	2105477	2105477	
AccumulatedColumnMovement	63954	63954	
FastThermalEstTemperatureRise	45	0.45	
ThermalEstTemperatureRise	156	1.56	
VehicleTuneSelector	2	2	
MotorTuneSelector	0	0	
EmulationModeStatus	0	0	
PDCStatus	1	1	
PowerOffDriveStageTemperature	3662	36.62	
CPU_PeakLoadHold	13380	13380	
TorqueReInstatmentFlag	1	1	
IncompletePowerDownTestCount	1	1	
padding	0		
LRE_PositionState	0	Not scaled	
PositionExtrapActive	0	Not scaled	
EncoderOffset	0	Not scaled	
MotorReversal	0	Not scaled	

1	2
-1.20313	-0.92969
3.139648	3.256836
0	0
13.50781	13.49219
17.5	17.5
2504.608	2504.608
16.05469	18.39453
-1.20313	-0.92969
-18.3359	-20.2344
40.27	40.27
100	100
1	1
0	0
3	3
2	2
857876	857876
181	241
6	6
240.0604	240.0604
60090	60089
322.5	315
1	0
0	0
960	960
-1	-1
6	6

				0
MotorMechanicalVelocity	-268	-207	-160	-2.09375
ColumnTorque	1787	2050	2251	1.745117
ColumnVelocity	0	0	0	0
vBatt	3634	3625	3619	14.19531
FilteredVehicleSpeed	714	714	712	11.15625
Filt2v5RefVoltage	12397	12397	12397	2496.954
AssistanceTorqueDemand	1551	1957	1926	6.058594
FilteredMechanicalVelocity	-268	-207	-160	-2.09375
QAxisCurrent	-204	-981	-1146	-1.59375
DriveStageTemperature	3669	3676	3669	36.69
TorqueLimit	25000	25000	25000	100
IgnitionOn	1	1	1	1
ASP	-8910	-8901	-8893	-139.219
EcuM__rootState_active	3	3	3	3
sSystemMode__rootState_active	2	2	2	2
AltHallTransitionTime	437904	546107	546107	437904
B92FilteredMotorVelocityError	819	903	985	819
HallSensor	2	6	6	2
DiagCommutationCentrePosition	54613	43691	43691	300.0714
EncoderPositionRegister	1545	1546	1546	1545
MotorElectricalPosition	57330	58695	58695	315
AltNewHallEvent	0	1	0	14.92857
AltMotorElectricalVelocity	0	0	0	0
B92MotorVelocityErrorLimit	960	960	960	960
AltRotorDirection	-1	-1	-1	-1
AltMotorCommutationState	2	6	6	2
				0

DistanceTravelled	31521548	31521548	
LifetimeCounter	2369480	2369480	
AccumulatedColumnMovement	45177	45177	
FastThermalEstTemperatureRise	12	1.2	
ThermalEstTemperatureRise	36	3.6	
VehicleTuneSelector	2	2	
MotorTuneSelector	0	0	
EmulationModeStatus	0	0	
PDCStatus	1	Not scaled	
PowerOffDriveStageTemperature	3555	35.55	
CPU_PeakLoadHold	13451	Not scaled	
TorqueReInstatmentFlag	1	Not scaled	
IncompletePowerDownTestCount	1	Not scaled	
padding	0	Not scaled	
LRE_PositionState	0	Not scaled	
PositionExtrapActive	0	Not scaled	
EncoderOffset	0	Not scaled	
MotorReversal	1	Not scaled	

1	2
-1.61719	-1.25
2.001953	2.198242
0	0
14.16016	14.13672
11.15625	11.125
2496.954	2496.954
7.644531	7.523438
-1.61719	-1.25
-7.66406	-8.95313
36.76	36.69
100	100
1	1
-139.078	-138.953
3	3
2	2
546107	546107
903	985
6	6
240.0604	240.0604
1546	1546
322.5	322.5
82.43956	82.43956
0	0
960	960
-1	-1
6	6
0	0

				0	1
MotorMechanicalVelocity	44	40	42	0.34375	0.3125
ColumnTorque	-764	-800	-737	-0.74609	-0.78125
ColumnVelocity	-23	-23	-23	-0.02246	-0.02246
vBatt	3598	3598	3600	14.05469	14.05469
FilteredVehicleSpeed	3577	3578	3577	55.89063	55.90625
Filt2v5RefVoltage	12379	12379	12379	2493.329	2493.329
AssistanceTorqueDemand	-198	99	205	-0.77344	0.386719
FilteredMechanicalVelocity	44	40	42	0.34375	0.3125
QAxisCurrent	48	-22	-65	0.375	-0.17188
DriveStageTemperature	4678	4671	4668	46.78	46.71
TorqueLimit	25000	25000	25000	100	100
IgnitionOn	1	1	1	1	1
ASP	-44	-44	-44	-0.6875	-0.6875
EcuM__rootState_active	3	3	3	3	3
sSystemMode__rootState_active	2	2	2	2	2
AltHallTransitionTime	35753979	35753979	35753979	35753979	35753979
B92FilteredMotorVelocityError	0	0	0	0	0
HallSensor	6	6	6	6	6
DiagCommutationCentrePosition	43691	43691	43691	240.0604	240.0604
EncoderPositionRegister	139	139	139	139	139
MotorElectricalPosition	54501	54600	54209	299.456	300
AltNewHallEvent	0	0	0	0	0
AltMotorElectricalVelocity	76	76	76	76	76
B92MotorVelocityErrorLimit	980	980	980	980	980
AltRotorDirection	-1	-1	-1	-1	-1
AltMotorCommutationState	6	6	6	6	6
DistanceTravelled	15538746				
LifetimeCounter	1112750				
AccumulatedColumnMovement	17527				
FastThermalEstTemperatureRise	14				
ThermalEstTemperatureRise	48				
VehicleTuneSelector	2				
MotorTuneSelector	0				
EmulationModeStatus	0				
PDCStatus	1				
PowerOffDriveStageTemperature	3026				
CPU_PeakLoadHold	13365				
TorqueReInstatmentFlag	1				
IncompletePowerDownTestCount	1				
padding	0				
LRE_PositionState	0				
PositionExtrapActive	1				
EncoderOffset	0				
MotorReversal	0				

2  
0.328125  
-0.71973  
-0.02246  
14.0625  
55.89063  
2493.329  
0.800781  
0.328125  
-0.50781  
46.68  
100  
1  
-0.6875  
3  
2  
35753979  
0  
6  
240.0604  
139  
297.8516  
0  
76  
980  
-1  
6

				0
MotorMechanicalVelocity	0	0	0	0
ColumnTorque	1233	1223	1227	1.204102
ColumnVelocity	0	0	0	0
vBatt	3526	3532	3530	13.77344
FilteredVehicleSpeed	5	5	5	0.078125
Filt2v5RefVoltage	12399	12399	12399	2497.357
AssistanceTorqueDemand	224	251	224	0.875
FilteredMechanicalVelocity	0	0	0	0
QAxisCurrent	-118	-125	-125	-0.92188
DriveStageTemperature	3580	3580	3583	35.8
TorqueLimit	25000	25000	25000	100
IgnitionOn	1	1	1	1
ASP	0	0	0	0
EcuM__rootState_active	3	3	3	3
sSystemMode__rootState_active	2	2	2	2
AltHallTransitionTime	55098060	55098060	55098060	55098060
B92FilteredMotorVelocityError	0	0	0	0
HallSensor	5	5	5	5
DiagCommutationCentrePosition	21845	21845	21845	120.0275
EncoderPositionRegister	0	0	0	0
MotorElectricalPosition	36855	36855	36855	202.5
AltNewHallEvent	0	0	0	0
AltMotorElectricalVelocity	0	0	0	0
B92MotorVelocityErrorLimit	960	960	960	960
AltRotorDirection	-1	-1	-1	-1
AltMotorCommutationState	5	5	5	5

DistanceTravelled	1211875	1211875		
LifetimeCounter	117063	117063		
AccumulatedColumnMovement	2621	2621		
FastThermalEstTemperatureRise	69	6.9		
ThermalEstTemperatureRise	119	11.9		
VehicleTuneSelector	3	3		
MotorTuneSelector	0	0		
EmulationModeStatus	0	0		
PDCStatus	1	Not scaled		
PowerOffDriveStageTemperature	3771	37.71		
CPU_PeakLoadHold	13385	Not scaled		
TorqueReInstatmentFlag	1	Not scaled		
IncompletePowerDownTestCount	1	Not scaled		
padding	0	Not scaled		
LRE_PositionState	0	Not scaled		
PositionExtrapActive	0	Not scaled		
EncoderOffset	0	Not scaled		
MotorReversal	0	Not scaled		

1	2
0	0
1.194336	1.198242
0	0
13.79688	13.78906
0.078125	0.078125
2497.357	2497.357
0.980469	0.875
0	0
-0.97656	-0.97656
35.8	35.83
100	100
1	1
0	0
3	3
2	2
55098060	55098060
0	0
5	5
120.0275	120.0275
0	0
202.5	202.5
0	0
0	0
960	960
-1	-1
5	5



				0	1
MotorMechanicalVelocity	0	0	0	0	0
ColumnTorque	1395	1359	1331	1.362305	1.327148
ColumnVelocity	0	0	0	0	0
vBatt	3733	3733	3731	14.58203	14.58203
FilteredVehicleSpeed	1400	1400	1400	21.875	21.875
Filt2v5RefVoltage	12382	12382	12382	2493.933	2493.933
AssistanceTorqueDemand	26	52	78	0.101563	0.203125
FilteredMechanicalVelocity	0	0	0	0	0
QAxisCurrent	-20	-20	-37	-0.15625	-0.15625
DriveStageTemperature	3594	3587	3587	35.94	35.87
TorqueLimit	25000	25000	25000	100	100
IgnitionOn	1	1	1	1	1
ASP	65	65	58	1.015625	1.015625
EcuM__rootState_active	3	3	3	3	3
sSystemMode__rootState_active	2	2	2	2	2
AltHallTransitionTime	43746102	43746102	43746102	43746102	43746102
B92FilteredMotorVelocityError	1	1	0	1	1
HallSensor	3	3	3	3	3
DiagCommutationCentrePosition	0	0	0	0	0
EncoderPositionRegister	146	146	146	146	146
MotorElectricalPosition	20475	20475	20475	112.5	112.5
AltNewHallEvent	1	0	0	1	0
AltMotorElectricalVelocity	0	0	0	0	0
B92MotorVelocityErrorLimit	960	960	960	960	960
AltRotorDirection	-1	-1	-1	-1	-1
AltMotorCommutationState	3	3	3	3	3
DistanceTravelled	12842				
LifetimeCounter	2804				
AccumulatedColumnMovement	111				
FastThermalEstTemperatureRise	61				
ThermalEstTemperatureRise	198				
VehicleTuneSelector	3				
MotorTuneSelector	0				
EmulationModeStatus	0				
PDCStatus	1				
PowerOffDriveStageTemperature	3196				
CPU_PeakLoadHold	13457				
TorqueReInstatmentFlag	1				
IncompletePowerDownTestCount	1				
padding	0				
LRE_PositionState	0				
PositionExtrapActive	0				
EncoderOffset	0				
MotorReversal	0				

2  
0  
1.299805  
0  
14.57422  
21.875  
2493.933  
0.304688  
0  
-0.28906  
35.87  
100  
1  
0.90625  
3  
2  
43746102  
0  
3  
0  
146  
112.5  
0  
0  
960  
-1  
3

				0	1
MotorMechanicalVelocity	0	0	0	0	0
ColumnTorque	1761	1840	1719	1.719727	1.796875
ColumnVelocity	0	0	0	0	0
vBatt	3261	3274	3251	12.73828	12.78906
FilteredVehicleSpeed	0	0	0	0	0
Filt2v5RefVoltage	12311	12311	12311	2479.633	2479.633
AssistanceTorqueDemand	1605	1662	1548	6.269531	6.492188
FilteredMechanicalVelocity	0	0	0	0	0
QAxisCurrent	-887	-917	-847	-6.92969	-7.16406
DriveStageTemperature	2591	2583	2578	25.91	25.83
TorqueLimit	1450	1500	1400	5.8	6
IgnitionOn	1	1	1	1	1
ASP	0	0	0	0	0
EcuM__rootState_active	3	3	3	3	3
sSystemMode__rootState_active	2	2	2	2	2
AltHallTransitionTime	2441876	2441876	2441876	2441876	2441876
B92FilteredMotorVelocityError	0	0	0	0	0
HallSensor	2	2	2	2	2
DiagCommutationCentrePosition	54613	54613	54613	300.0714	300.0714
EncoderPositionRegister	2	2	2	2	2
MotorElectricalPosition	4095	4095	4095	22.5	22.5
AltNewHallEvent	0	0	1	0	0
AltMotorElectricalVelocity	0	0	0	0	0
B92MotorVelocityErrorLimit	960	960	960	960	960
AltRotorDirection	-1	-1	-1	-1	-1
AltMotorCommutationState	2	2	2	2	2

2  
0  
1.678711  
0  
12.69922  
0  
2479.633  
6.046875  
0  
-6.61719  
25.78  
5.6  
1  
0  
3  
2  
2441876  
0  
2  
300.0714  
2  
22.5  
1  
0  
960  
-1  
2

MotorMechanicalVelocity	0	0	0	0
ColumnTorque	0	0	0	0
ColumnVelocity	0	0	0	0
vBatt	3055	3053	3050	11.93359
FilteredVehicleSpeed	0	0	0	0
Filt2v5RefVoltage	12331	12331	12331	2483.661
AssistanceTorqueDemand	0	0	0	Not scaled
FilteredMechanicalVelocity	0	0	0	Not scaled
QAxisCurrent	-10	-14	1	-0.07813
DriveStageTemperature	811	811	804	8.11
TorqueLimit	0	0	0	Not scaled
IgnitionOn	1	1	1	1
ASP	0	0	0	Not scaled
EcuM__rootState_active	3	3	3	3
sSystemMode__rootState_active	2	2	2	2
TorquePwmPulseWidth1	0	0	0	0
TorquePwmPulseWidth2	0	0	0	0
TorquePwmPulsePeriod1	0	0	0	0
TorquePwmPulsePeriod2	0	0	0	0
TimeSinceLastEvent1	4754	4770	4786	Not scaled
TimeSinceLastEvent2	4754	4770	4786	Not scaled
AltLowTimeError1	0	0	0	Not scaled
AltLowTimeError2	0	0	0	Not scaled
DistanceTravelled	25302444	25302444		
LifetimeCounter	1640076	1640076		
AccumulatedColumnMovement	37306	37306		
FastThermalEstTemperatureRise	36	3.6		
ThermalEstTemperatureRise	92	9.2		
VehicleTuneSelector	2	2		
MotorTuneSelector	0	0		
EmulationModeStatus	0	0		
PDCStatus	1	Not scaled		
PowerOffDriveStageTemperature	3844	38.44		
CPU_PeakLoadHold	13416	Not scaled		
TorqueReInstatmentFlag	1	Not scaled		
IncompletePowerDownTestCount	1	Not scaled		
padding	0	Not scaled		
empty	5548	Not scaled		

0	0
0	0
0	0
11.92578	11.91406
0	0
2483.661	2483.661
Not scaled	Not scaled
Not scaled	Not scaled
-0.10938	0.007813
8.11	8.04
Not scaled	Not scaled
1	1
Not scaled	Not scaled
3	3
2	2
0	0
0	0
0	0
0	0
Not scaled	Not scaled
Not scaled	Not scaled
Not scaled	Not scaled
Not scaled	Not scaled

	0	1	2	0	1
MotorMechanicalVelocity	0	0	0	0	0
ColumnTorque	-611	-600	-604	-0.59668	-0.58594
ColumnVelocity	-3	-3	-3	-0.00293	-0.00293
vBatt	3588	3580	3584	14.01563	13.98438
FilteredVehicleSpeed	7013	7013	7013	109.5781	109.5781
Filt2v5RefVoltage	12389	12389	12389	2495.343	2495.343
AssistanceTorqueDemand	-169	-148	-168	-0.66016	-0.57813
FilteredMechanicalVelocity	0	0	0	0	0
QAxisCurrent	89	100	89	0.695313	0.78125
DriveStageTemperature	2392	2397	2397	23.92	23.97
TorqueLimit	25000	25000	25000	100	100
IgnitionOn	1	1	1	1	1
ASP	-132	-132	-132	-2.0625	-2.0625
EcuM__rootState_active	3	3	3	3	3
sSystemMode__rootState_active	2	2	2	2	2
AltHallTransitionTime	4.16E+08			4.16E+08	0
B92FilteredMotorVelocityError	0			0	0
HallSensor	6			6	0
DiagCommutationCentrePosition	43691			240.0604	0
EncoderPositionRegister	17			17	0
MotorElectricalPosition	57330			315	0
AltNewHallEvent	0			0	0
AltMotorElectricalVelocity	0			0	0
B92MotorVelocityErrorLimit	960			960	0
AltRotorDirection	-1			-1	0
AltMotorCommutationState	6			6	0
DistanceTravelled	10553441				
LifetimeCounter	589235				
AccumulatedColumnMovement	11847				
FastThermalEstTemperatureRise	0				
ThermalEstTemperatureRise	14				
VehicleTuneSelector	2				
MotorTuneSelector	0				
EmulationModeStatus	0				
PDCStatus	1				
PowerOffDriveStageTemperature	3538				
CPU_PeakLoadHold	13501				
TorqueReInstatmentFlag	1				
IncompletePowerDownTestCount	1				
padding	0				
LRE_PositionState	0				
PositionExtrapActive	0				
EncoderOffset	0				
MotorReversal	0				

2  
0  
-0.58984  
-0.00293  
14  
109.5781  
2495.343  
-0.65625  
0  
0.695313  
23.97  
100  
1  
-2.0625  
3  
2  
0  
0  
0  
0  
0  
0  
0  
0  
0  
0  
0  
0  
0  
0



				0	1
MotorMechanicalVelocity	0	0	0	0	0
ColumnTorque	1908	1933	1960	1.863281	1.887695
ColumnVelocity	0	0	0	0	0
vBatt	3772	3759	3751	14.73438	14.68359
FilteredVehicleSpeed	0	0	0	0	0
Filt2v5RefVoltage	12390	12390	12390	2495.544	2495.544
AssistanceTorqueDemand	783	823	866	3.058594	3.214844
FilteredMechanicalVelocity	0	0	0	0	0
QAxisCurrent	-398	-445	-446	-3.10938	-3.47656
DriveStageTemperature	704	676	683	7.04	6.76
TorqueLimit	25000	25000	25000	100	100
IgnitionOn	1	1	1	1	1
ASP	0	0	0	0	0
EcuM__rootState_active	3	3	3	3	3
sSystemMode__rootState_active	2	2	2	2	2
AltHallTransitionTime	1.58E+08	1.58E+08	1.58E+08	1.58E+08	1.58E+08
B92FilteredMotorVelocityError	0	0	0	0	0
HallSensor	6	6	6	6	6
DiagCommutationCentrePosition	43691	43691	43691	240.0604	240.0604
EncoderPositionRegister	0	0	0	0	0
MotorElectricalPosition	60060	60060	60060	330	330
AltNewHallEvent	0	0	0	0	0
AltMotorElectricalVelocity	0	0	0	0	0
B92MotorVelocityErrorLimit	960	960	960	960	960
AltRotorDirection	-1	-1	-1	-1	-1
AltMotorCommutationState	6	6	6	6	6

2  
0  
1.914063  
0  
14.65234  
0  
2495.544  
3.382813  
0  
-3.48438  
6.83  
100  
1  
0  
3  
2  
1.58E+08  
0  
6  
240.0604  
0  
330  
0  
0  
960  
-1  
6

				0	1
MotorMechanicalVelocity	0	0	0	0	0
ColumnTorque	1637	1638	1638	1.598633	1.599609
ColumnVelocity	0	0	0	0	0
vBatt	3357	3355	3355	13.11328	13.10547
FilteredVehicleSpeed	255	249	255	3.984375	3.890625
Filt2v5RefVoltage	12414	12414	12414	2500.378	2500.378
AssistanceTorqueDemand	586	586	586	2.289063	2.289063
FilteredMechanicalVelocity	0	0	0	0	0
QAxisCurrent	-429	-356	-415	-3.35156	-2.78125
DriveStageTemperature	-593	-575	-585	-5.93	-5.75
TorqueLimit	1050	950	1000	4.2	3.8
IgnitionOn	1	1	1	1	1
ASP	0	0	0	0	0
EcuM__rootState_active	3	3	3	3	3
sSystemMode__rootState_active	2	2	2	2	2
AltHallTransitionTime	1463972	1463972	1463972	1463972	1463972
B92FilteredMotorVelocityError	0	0	0	0	0
HallSensor	6	6	6	6	6
DiagCommutationCentrePosition	43691	43691	43691	240.0604	240.0604
EncoderPositionRegister	0	0	0	0	0
MotorElectricalPosition	60060	60060	60060	330	330
AltNewHallEvent	0	1	0	0	1
AltMotorElectricalVelocity	0	0	0	0	0
B92MotorVelocityErrorLimit	960	960	960	960	960
AltRotorDirection	-1	-1	-1	-1	-1
AltMotorCommutationState	6	6	6	6	6

DistanceTravelled	3150813
LifetimeCounter	249911
AccumulatedColumnMovement	14965
FastThermalEstTemperatureRise	8
ThermalEstTemperatureRise	64
VehicleTuneSelector	2
MotorTuneSelector	0
EmulationModeStatus	0
PDCStatus	1
PowerOffDriveStageTemperature	-564
CPU_PeakLoadHold	13584
TorqueReInstatmentFlag	1
IncompletePowerDownTestCount	1
padding	0
LRE_PositionState	0
PositionExtrapActive	0
EncoderOffset	0
MotorReversal	0

2  
0  
1.599609  
0  
13.10547  
3.984375  
2500.378  
2.289063  
0  
-3.24219  
-5.85  
4  
1  
0  
3  
2  
1463972  
0  
6  
240.0604  
0  
330  
0  
0  
960  
-1  
6

				0
MotorMechanicalVelocity	0	0	0	0
ColumnTorque	-544	-480	-513	-0.53125
ColumnVelocity	0	0	0	0
vBatt	3616	3621	3612	14.125
FilteredVehicleSpeed	0	0	0	0
Filt2v5RefVoltage	12342	12342	12342	2485.876
AssistanceTorqueDemand	-272	-245	-271	-1.0625
FilteredMechanicalVelocity	0	0	0	0
QAxisCurrent	134	122	134	1.046875
DriveStageTemperature	2990	2994	3002	29.9
TorqueLimit	25000	25000	25000	100
IgnitionOn	1	1	1	1
ASP	0	0	0	0
EcuM__rootState_active	3	3	3	3
sSystemMode__rootState_active	2	2	2	2
AltHallTransitionTime	7157869	7157869	7157869	7157869
B92FilteredMotorVelocityError	0	0	0	0
HallSensor	1	1	1	1
DiagCommutationCentrePosition	10923	10923	10923	60.01648
EncoderPositionRegister	0	0	0	0
MotorElectricalPosition	60060	60060	60060	330
AltNewHallEvent	0	1	0	0
AltMotorElectricalVelocity	0	0	0	0
B92MotorVelocityErrorLimit	960	960	960	960
AltRotorDirection	1	1	1	1
AltMotorCommutationState	1	1	1	1
DistanceTravelled	1737930			
LifetimeCounter	159448			
AccumulatedColumnMovement	5414			
FastThermalEstTemperatureRise	21			
ThermalEstTemperatureRise	107			
VehicleTuneSelector	2			
MotorTuneSelector	0			
EmulationModeStatus	0			
PDCStatus	1			
PowerOffDriveStageTemperature	2888			
CPU_PeakLoadHold	13320			
TorqueReInstatmentFlag	1			
IncompletePowerDownTestCount	1			
padding	0			
LRE_PositionState	0			
PositionExtrapActive	0			
EncoderOffset	0			
MotorReversal	0			

1	2
0	0
-0.46875	-0.50098
0	0
14.14453	14.10938
0	0
2485.876	2485.876
-0.95703	-1.05859
0	0
0.953125	1.046875
29.94	30.02
100	100
1	1
0	0
3	3
2	2
7157869	7157869
0	0
1	1
60.01648	60.01648
0	0
330	330
1	0
0	0
960	960
1	1
1	1

MotorMechanicalVelocity	0	0	0	0
vBatt	3188	3186	3186	3186
FilteredVehicleSpeed	6400	6400	6400	6400
Filt2v5RefVoltage	12396	12396	12396	12396
QAxisCurrent	-3571	-3568	-3565	-3571
DriveStageTemperature	2772	2767	2777	2762
IgnitionOn	1	1	1	1
EcuM__rootState_active	2	2	2	2
sSystemMode__rootState_active	1	1	1	1
tune_number	0	0	0	0
top_value	42405	42405	42405	42405
stack_pointer	7767	7767	7767	7767
running_crc	65535	65535	65535	65535
bottom_value	42405	42405	42405	42405
ADCA_0_Reference_Voltage	12389	12386	12386	12389
ADCA_1_Reference_Voltage	12383	12387	12379	12383
ADCB_0_Reference_Voltage	12419	12424	12419	12420
ADCB_1_Reference_Voltage	12370	12366	12370	12362
ExecStarted_MON_SENSOR_TORQUE_MONITOR	255	255	255	255
ExecStarted_MON_ASSIST_TRQ_DEMAND_MONITOR	255	255	255	255
ExecStarted_MON_MOTOR_VELOCITY_MONITOR	255	255	255	255
ExecStarted_MON_RSP_MONITOR	255	255	255	255
ExecStarted_MON_TORQUE_ESTIMATE_MONITOR	255	255	255	255
ExecStarted_MON_CURRENT_CALC_MONITOR	255	255	255	255
ExecStarted_MON_PDC_MONITOR	255	255	255	255
ExecCompleted_MON_SENSOR_TORQUE_MONITOR	255	255	255	255
ExecCompleted_MON_ASSIST_TRQ_DEMAND_MONITOR	255	255	255	255
ExecCompleted_MON_MOTOR_VELOCITY_MONITOR	255	255	255	255
ExecCompleted_MON_RSP_MONITOR	255	255	255	255
ExecCompleted_MON_TORQUE_ESTIMATE_MONITOR	255	255	255	255
ExecCompleted_MON_CURRENT_CALC_MONITOR	255	255	255	255
ExecCompleted_MON_PDC_MONITOR	255	255	255	255
Padding	0	0	0	0
SafetyMicroOperatingMode	2	2	2	2
SafetyMicroStatus	34304	34304	34304	34304
SafetyMicroInhibitFaults	58963	58963	58963	58963
SC_Wdg__rootState_active	2	2	2	2
WdgManagerCurrentConfig	0	0	0	0
theSupervisedEntity0_ActualAliveCount	1	3	1	3
theSupervisedEntity1_ActualAliveCount	0	1	0	1
theSupervisedEntity2_ActualAliveCount	0	1	0	1
theSupervisedEntity3_ActualAliveCount	1	1	1	1
theSupervisedEntity4_ActualAliveCount	0	8	0	8
MotorMechanicalPosition	-5	-5	-5	-5
BridgeEnabled	1	1	1	1
SPUT_LinkVoltage	2832	2829	2826	2822
SPUT_FilteredLinkVoltage	2830	2827	2825	2822
SPUT_LinkRelayClosureRetries	0	0	0	0
Motor_LinkVoltage	2879	2879	2879	2879
Motor_SwitchVoltage	0	0	0	0

Motor_StarVoltage	1464	1464	1464	1464
Motor_Phase1Voltage	1451	1451	1451	1451
Motor_Phase2Voltage	1461	1461	1461	1461
Motor_Phase3Voltage	1461	1461	1461	1461
padding1	0	0	0	0
padding2	0	0	0	0



0	0	0
3188	3186	3186
6400	6400	6400
12396	12396	12396
-3592	-3583	-3555
2768	2771	2762
1	1	1
2	2	2
1	1	1
0	0	0
42405	42405	42405
7767	7767	7767
65535	65535	65535
42405	42405	42405
12385	12385	12390
12379	12383	12383
12420	12428	12428
12370	12370	12370
255	255	255
255	255	255
255	255	255
255	255	255
255	255	255
255	255	255
255	255	255
255	255	255
255	255	255
255	255	255
255	255	255
255	255	255
255	255	255
255	255	255
0	0	0
2	2	2
34304	34304	34304
58963	58963	58963
2	2	2
0	0	0
1	3	3
0	1	1
0	1	1
2	2	1
0	8	8
-5	-5	-5
1	1	1
2819	2815	2833
2819	2816	2833
0	0	0
2879	2879	2879
0	0	0

1464	1464	1464
1451	1451	1451
1461	1461	1461
1461	1461	1461
0	0	0
0	0	0

Parameter	0	1	2
MotorMechanicalVelocity	0	0	0
ColumnTorque	0	0	0
ColumnVelocity	0	0	0
vBatt	2841	2845	2849
FilteredVehicleSpeed	0	0	0
Filt2v5RefVoltage	12428	12428	12428
AssistanceTorqueDemand	0	0	0
FilteredMechanicalVelocity	0	0	0
QAxisCurrent	24	-12	11
DriveStageTemperature	1942	1937	1937
TorqueLimit	0	0	0
IgnitionOn	1	1	1
ASP	0	0	0
EcuM__rootState_active	3	3	3
sSystemMode__rootState_active	2	2	2
TorquePwmPulseWidth1	0	0	0
TorquePwmPulseWidth2	0	0	0
TorquePwmPulsePeriod1	0	0	0
TorquePwmPulsePeriod2	0	0	0
TimeSinceLastEvent1	1874	1890	1906
TimeSinceLastEvent2	1874	1890	1906
AltLowTimeError1	0	0	0
AltLowTimeError2	0	0	0
LifetimeCounter	125146		
AccumulatedColumnMovement	2290		
FastThermalEstTemperatureRise	22		
ThermalEstTemperatureRise	72		
VehicleTuneSelector	2		
MotorTuneSelector	0		
EmulationModeStatus	0		
PDCStatus	1		
PowerOffDriveStageTemperature	2153		
CPU_PeakLoadHold	13533		
TorqueReInstatmentFlag	1		
IncompletePowerDownTestCount	1		
padding	0		
empty	-916		

	0	1	2	0	1
MotorMechanicalVelocity	0	0	0	0	0
ColumnTorque	-740	-791	-689	-0.72266	-0.77246
ColumnVelocity	0	0	0	0	0
vBatt	3296	3292	3303	12.875	12.85938
FilteredVehicleSpeed	0	0	0	0	0
Filt2v5RefVoltage	12431	12432	12431	2503.802	2504.004
AssistanceTorqueDemand	-526	-531	-496	-2.05469	-2.07422
FilteredMechanicalVelocity	0	0	0	0	0
QAxisCurrent	271	283	272	2.117188	2.210938
DriveStageTemperature	370	368	370	3.7	3.68
TorqueLimit	25000	25000	25000	100	100
IgnitionOn	1	1	1	1	1
ASP	0	0	0	0	0
EcuM__rootState_active	3	3	3	3	3
sSystemMode__rootState_active	2	2	2	2	2
AltHallTransitionTime	3210001	3210001	3210001	3210001	3210001
B92FilteredMotorVelocityError	0	0	0	0	0
HallSensor	3	3	3	3	3
DiagCommutationCentrePosition	0	0	0	0	0
EncoderPositionRegister	0	0	0	0	0
MotorElectricalPosition	49140	49140	49140	270	270
AltNewHallEvent	0	0	1	0	0
AltMotorElectricalVelocity	0	0	0	0	0
B92MotorVelocityErrorLimit	960	960	960	960	960
AltRotorDirection	1	1	1	1	1
AltMotorCommutationState	3	3	3	3	3

DistanceTravelled	34063356
LifetimeCounter	1974880
AccumulatedColumnMovement	42402
FastThermalEstTemperatureRise	104
ThermalEstTemperatureRise	94
VehicleTuneSelector	2
MotorTuneSelector	0
EmulationModeStatus	0
PDCStatus	1
PowerOffDriveStageTemperature	811
CPU_PeakLoadHold	13459
TorqueReInstatmentFlag	1
IncompletePowerDownTestCount	1
padding	0
LRE_PositionState	0
PositionExtrapActive	0
EncoderOffset	0
MotorReversal	0

2  
0  
-0.67285  
0  
12.90234  
0  
2503.802  
-1.9375  
0  
2.125  
3.7  
100  
1  
0  
3  
2  
3210001  
0  
3  
0  
0  
270  
1  
0  
960  
1  
3

				0	1
MotorMechanicalVelocity	0	0	0	0	0
ColumnTorque	1729	1864	1598	1.688477	1.820313
ColumnVelocity	0	0	0	0	0
vBatt	3549	3534	3556	13.86328	13.80469
FilteredVehicleSpeed	0	0	0	0	0
Filt2v5RefVoltage	12376	12376	12376	2492.725	2492.725
AssistanceTorqueDemand	1129	1271	995	4.410156	4.964844
FilteredMechanicalVelocity	0	0	0	0	0
QAxisCurrent	-618	-675	-527	-4.82813	-5.27344
DriveStageTemperature	2118	2118	2136	21.18	21.18
TorqueLimit	25000	25000	25000	100	100
IgnitionOn	1	1	1	1	1
ASP	0	0	0	0	0
EcuM__rootState_active	3	3	3	3	3
sSystemMode__rootState_active	2	2	2	2	2
AltHallTransitionTime	2526023	2526023	2526023	2526023	2526023
B92FilteredMotorVelocityError	0	0	0	0	0
HallSensor	2	2	2	2	2
DiagCommutationCentrePosition	54613	54613	54613	300.0714	300.0714
EncoderPositionRegister	65534	65534	65534	65534	65534
MotorElectricalPosition	4095	4095	4095	22.5	22.5
AltNewHallEvent	0	0	0	0	0
AltMotorElectricalVelocity	0	0	0	0	0
B92MotorVelocityErrorLimit	960	960	960	960	960
AltRotorDirection	-1	-1	-1	-1	-1
AltMotorCommutationState	2	2	2	2	2

DistanceTravelled	2650844
LifetimeCounter	187019
AccumulatedColumnMovement	5209
FastThermalEstTemperatureRise	3
ThermalEstTemperatureRise	8
VehicleTuneSelector	2
MotorTuneSelector	0
EmulationModeStatus	0
PDCStatus	1
PowerOffDriveStageTemperature	2322
CPU_PeakLoadHold	13543
TorqueReInstatmentFlag	1
IncompletePowerDownTestCount	1
padding	0
LRE_PositionState	0
PositionExtrapActive	0
EncoderOffset	0
MotorReversal	0

2  
0  
1.560547  
0  
13.89063  
0  
2492.725  
3.886719  
0  
-4.11719  
21.36  
100  
1  
0  
3  
2  
2526023  
0  
2  
300.0714  
65534  
22.5  
0  
0  
960  
-1  
2

				0	1
MotorMechanicalVelocity	0	0	0	0	0
ColumnTorque	2014	2063	1963	1.966797	2.014648
ColumnVelocity	0	0	0	0	0
vBatt	3738	3728	3753	14.60156	14.5625
FilteredVehicleSpeed	40	40	39	0.625	0.625
Filt2v5RefVoltage	12401	12401	12401	2497.76	2497.76
AssistanceTorqueDemand	1111	1197	960	4.339844	4.675781
FilteredMechanicalVelocity	0	0	0	0	0
QAxisCurrent	-567	-629	-508	-4.42969	-4.91406
DriveStageTemperature	-1144	-1144	-1188	-11.44	-11.44
TorqueLimit	25000	25000	25000	100	100
IgnitionOn	1	1	1	1	1
ASP	0	0	0	0	0
EcuM__rootState_active	3	3	3	3	3
sSystemMode__rootState_active	2	2	2	2	2
AltHallTransitionTime	26579958	26579958	26579958	26579958	26579958
B92FilteredMotorVelocityError	0	0	0	0	0
HallSensor	1	1	1	1	1
DiagCommutationCentrePosition	10923	10923	10923	60.01648	60.01648
EncoderPositionRegister	0	0	0	0	0
MotorElectricalPosition	27300	27300	27300	150	150
AltNewHallEvent	0	0	0	89.98352	89.98352
AltMotorElectricalVelocity	0	0	0	0	0
B92MotorVelocityErrorLimit	960	960	960	960	960
AltRotorDirection	-1	-1	-1	-1	-1
AltMotorCommutationState	1	1	1	1	1
				0	0

DistanceTravelled	43283
LifetimeCounter	15219
AccumulatedColumnMovement	1604
FastThermalEstTemperatureRise	72
ThermalEstTemperatureRise	259
VehicleTuneSelector	3
MotorTuneSelector	0
EmulationModeStatus	0
PDCStatus	1
PowerOffDriveStageTemperature	792
CPU_PeakLoadHold	13500
TorqueReInstatmentFlag	1
IncompletePowerDownTestCount	1
padding	0
LRE_PositionState	0
PositionExtrapActive	0
EncoderOffset	0
MotorReversal	0



2  
0  
1.916992  
0  
14.66016  
0.609375  
2497.76  
3.75  
0  
-3.96875  
-11.88  
100  
1  
0  
3  
2  
26579958  
0  
1  
60.01648  
0  
150  
89.98352  
0  
960  
-1  
1  
0

Parameter	0	1	2	0	1
MotorMechanicalVelocity	0	0	0	0	0
ColumnTorque	1531	1335	1431	1.495117	1.303711
ColumnVelocity	0	0	0	0	0
vBatt	3748	3742	3746	14.64063	14.61719
FilteredVehicleSpeed	0	0	0	0	0
Filt2v5RefVoltage	12379	12379	12379	2493.329	2493.329
AssistanceTorqueDemand	1034	888	959	4.039063	3.46875
FilteredMechanicalVelocity	0	0	0	0	0
QAxisCurrent	-539	-471	-515	-4.21094	-3.67969
DriveStageTemperature	-598	-610	-588	-5.98	-6.1
TorqueLimit	25000	25000	25000	100	100
IgnitionOn	1	1	1	1	1
ASP	0	0	0	0	0
EcuM__rootState_active	3	3	3	3	3
sSystemMode__rootState_active	2	2	2	2	2
AltHallTransitionTime	6906003	43385950	6906003	6906003	43385950
B92FilteredMotorVelocityError	0	0	0	0	0
HallSensor	2	2	2	2	2
DiagCommutationCentrePosition	54613	54613	54613	300.0714	300.0714
EncoderPositionRegister	0	0	0	0	0
MotorElectricalPosition	4095	4095	4095	22.5	22.5
AltNewHallEvent	0	0	0	0	0
AltMotorElectricalVelocity	0	0	0	0	0
B92MotorVelocityErrorLimit	960	960	960	960	960
AltRotorDirection	-1	-1	-1	-1	-1
AltMotorCommutationState	2	3	2	2	3

DistanceTravelled	3380111
LifetimeCounter	289130
AccumulatedColumnMovement	6943
FastThermalEstTemperatureRise	25
ThermalEstTemperatureRise	43
VehicleTuneSelector	2
MotorTuneSelector	0
EmulationModeStatus	0
PDCStatus	1
PowerOffDriveStageTemperature	638
CPU_PeakLoadHold	13316
TorqueReInstatmentFlag	1
IncompletePowerDownTestCount	1
padding	0
LRE_PositionState	0
PositionExtrapActive	0
EncoderOffset	0
MotorReversal	0

2  
0  
1.397461  
0  
14.63281  
0  
2493.329  
3.746094  
0  
-4.02344  
-5.88  
100  
1  
0  
3  
2  
6906003  
0  
2  
300.0714  
0  
22.5  
0  
0  
960  
-1  
2

				0	1
MotorMechanicalVelocity	0	0	0	0	0
ColumnTorque	2250	2340	2188	2.197266	2.285156
ColumnVelocity	0	0	0	0	0
vBatt	3394	3394	3394	13.25781	13.25781
FilteredVehicleSpeed	0	0	0	0	0
Filt2v5RefVoltage	12449	12449	12449	2507.428	2507.428
AssistanceTorqueDemand	1661	2000	1405	6.488281	7.8125
FilteredMechanicalVelocity	0	0	0	0	0
QAxisCurrent	-1008	-1176	-816	-7.875	-9.1875
DriveStageTemperature	63	63	56	0.63	0.63
TorqueLimit	25000	25000	25000	100	100
IgnitionOn	1	1	1	1	1
ASP	0	0	0	0	0
EcuM__rootState_active	3	3	3	3	3
sSystemMode__rootState_active	2	2	2	2	2
AltHallTransitionTime	1056065	1056065	1056065	1056065	1056065
B92FilteredMotorVelocityError	0	0	0	0	0
HallSensor	6	6	6	6	6
DiagCommutationCentrePosition	43691	43691	43691	240.0604	240.0604
EncoderPositionRegister	0	0	0	0	0
MotorElectricalPosition	60060	60060	60060	330	330
AltNewHallEvent	0	0	1	89.93956	89.93956
AltMotorElectricalVelocity	0	0	0	0	0
B92MotorVelocityErrorLimit	960	960	960	960	960
AltRotorDirection	-1	-1	-1	-1	-1
AltMotorCommutationState	6	6	6	6	6
DistanceTravelled	14410549				
LifetimeCounter	988449				
AccumulatedColumnMovement	17191				
FastThermalEstTemperatureRise	16				
ThermalEstTemperatureRise	71				
VehicleTuneSelector	2				
MotorTuneSelector	0				
EmulationModeStatus	0				
PDCStatus	1				
PowerOffDriveStageTemperature	71				
CPU_PeakLoadHold	13367				
TorqueReInstatmentFlag	1				
IncompletePowerDownTestCount	1				
padding	0				
LRE_PositionState	0				
PositionExtrapActive	0				
EncoderOffset	0				
MotorReversal	0				

2  
0  
2.136719  
0  
13.25781  
0  
2507.428  
5.488281  
0  
-6.375  
0.56  
100  
1  
0  
3  
2  
1056065  
0  
6  
240.0604  
0  
330  
89.93956  
0  
960  
-1  
6

				0	1
MotorMechanicalVelocity	0	0	0	0	0
ColumnTorque	-1992	-2033	-1957	-1.94531	-1.98535
ColumnVelocity	0	0	0	0	0
vBatt	3354	3349	3358	13.10156	13.08203
FilteredVehicleSpeed	0	0	0	0	0
Filt2v5RefVoltage	12446	12445	12446	2506.824	2506.622
AssistanceTorqueDemand	-1076	-1125	-996	-4.20313	-4.39453
FilteredMechanicalVelocity	0	0	0	0	0
QAxisCurrent	570	616	514	4.453125	4.8125
DriveStageTemperature	924	924	931	9.24	9.24
TorqueLimit	22950	23000	22900	91.8	92
IgnitionOn	1	1	1	1	1
ASP	0	0	0	0	0
EcuM__rootState_active	3	3	3	3	3
sSystemMode__rootState_active	2	2	2	2	2
AltHallTransitionTime	16139957	16139957	16139957	16139957	16139957
B92FilteredMotorVelocityError	0	0	0	0	0
HallSensor	4	4	4	4	4
DiagCommutationCentrePosition	32768	32768	32768	180.044	180.044
EncoderPositionRegister	0	0	0	0	0
MotorElectricalPosition	16380	16380	16380	90	90
AltNewHallEvent	0	0	1	-90.044	-90.044
AltMotorElectricalVelocity	0	0	0	0	0
B92MotorVelocityErrorLimit	960	960	960	960	960
AltRotorDirection	1	1	1	1	1
AltMotorCommutationState	4	4	4	4	4
DistanceTravelled	9967568				
LifetimeCounter	675030				
AccumulatedColumnMovement	14176				
FastThermalEstTemperatureRise	4				
ThermalEstTemperatureRise	26				
VehicleTuneSelector	2				
MotorTuneSelector	0				
EmulationModeStatus	0				
PDCStatus	1				
PowerOffDriveStageTemperature	951				
CPU_PeakLoadHold	13342				
TorqueReInstatmentFlag	1				
IncompletePowerDownTestCount	1				
padding	0				
LRE_PositionState	0				
PositionExtrapActive	0				
EncoderOffset	0				
MotorReversal	0				

2  
0  
-1.91113  
0  
13.11719  
0  
2506.824  
-3.89063  
0  
4.015625  
9.31  
91.6  
1  
0  
3  
2  
16139957  
0  
4  
180.044  
0  
90  
-90.044  
0  
960  
1  
4

				0	1
MotorMechanicalVelocity	0	0	0	0	0
ColumnTorque	4539	5439	3929	4.432617	5.311523
ColumnVelocity	0	0	0	0	0
vBatt	3661	3658	3657	14.30078	14.28906
FilteredVehicleSpeed	0	0	0	0	0
Filt2v5RefVoltage	12392	12392	12392	2495.947	2495.947
AssistanceTorqueDemand	8955	13365	6020	34.98047	52.20703
FilteredMechanicalVelocity	0	0	0	0	0
QAxisCurrent	-5081	-7097	-3485	-39.6953	-55.4453
DriveStageTemperature	2603	2609	2612	26.03	26.09
TorqueLimit	25000	25000	25000	100	100
IgnitionOn	1	1	1	1	1
ASP	0	0	0	0	0
EcuM__rootState_active	3	3	3	3	3
sSystemMode__rootState_active	2	2	2	2	2
AltHallTransitionTime	599956	491907	599956	599956	491907
B92FilteredMotorVelocityError	0	0	0	0	0
HallSensor	1	1	5	1	1
DiagCommutationCentrePosition	21845	10923	21845	120.0275	60.01648
EncoderPositionRegister	0	0	0	0	0
MotorElectricalPosition	36855	36855	36855	202.5	202.5
				82.47253	142.4835
AltNewHallEvent	0	0	0	0	0
AltMotorElectricalVelocity	0	0	0	0	0
B92MotorVelocityErrorLimit	960	960	960	960	960
AltRotorDirection	-1	-1	-1	-1	-1
AltMotorCommutationState	5	1	5	5	1



2  
0  
3.836914  
0  
14.28516  
0  
2495.947  
23.51563  
0  
-27.2266  
26.12  
100  
1  
0  
3  
2  
599956  
0  
5  
120.0275  
0  
202.5  
82.47253  
0  
0  
960  
-1  
5

				0	1
MotorMechanicalVelocity	0	0	0	0	0
ColumnTorque	-1179	-1211	-1241	-1.15137	-1.18262
ColumnVelocity	0	0	0	0	0
vBatt	3708	3710	3710	14.48438	14.49219
FilteredVehicleSpeed	116	117	117	1.8125	1.828125
Filt2v5RefVoltage	12454	12454	12454	2508.435	2508.435
AssistanceTorqueDemand	-516	-546	-522	-2.01563	-2.13281
FilteredMechanicalVelocity	0	0	0	0	0
QAxisCurrent	295	278	312	2.304688	2.171875
DriveStageTemperature	2663	2676	2677	26.63	26.76
TorqueLimit	25000	25000	25000	100	100
IgnitionOn	1	1	1	1	1
ASP	0	0	0	0	0
EcuM__rootState_active	3	3	3	3	3
sSystemMode__rootState_active	2	2	2	2	2
AltHallTransitionTime	3887975	3887975	3887975	3887975	3887975
B92FilteredMotorVelocityError	0	0	0	0	0
HallSensor	2	2	2	2	2
DiagCommutationCentrePosition	54613	54613	54613	300.0714	300.0714
EncoderPositionRegister	0	0	0	0	0
MotorElectricalPosition	36855	36855	36855	202.5	202.5
AltNewHallEvent	1	0	0	1	0
AltMotorElectricalVelocity	0	0	0	0	0
B92MotorVelocityErrorLimit	960	960	960	960	960
AltRotorDirection	1	1	1	1	1
AltMotorCommutationState	2	2	2	2	2

DistanceTravelled	12410
LifetimeCounter	1999
AccumulatedColumnMovement	1005
FastThermalEstTemperatureRise	17
ThermalEstTemperatureRise	575
VehicleTuneSelector	3
MotorTuneSelector	0
EmulationModeStatus	0
PDCStatus	1
PowerOffDriveStageTemperature	3107
CPU_PeakLoadHold	13479
TorqueReInstatmentFlag	1
IncompletePowerDownTestCount	1
padding	0
LRE_PositionState	0
PositionExtrapActive	0
EncoderOffset	0
MotorReversal	0

2  
0  
-1.21191  
0  
14.49219  
1.828125  
2508.435  
-2.03906  
0  
2.4375  
26.77  
100  
1  
0  
3  
2  
3887975  
0  
2  
300.0714  
0  
202.5  
0  
0  
960  
1  
2

				0
MotorMechanicalVelocity	0	0	0	0
ColumnTorque	1783	1903	2045	1.741211
ColumnVelocity	0	0	0	0
vBatt	3768	3754	3743	14.71875
FilteredVehicleSpeed	0	0	0	0
Filt2v5RefVoltage	12429	12429	12429	2503.4
AssistanceTorqueDemand	1155	1276	1492	4.511719
FilteredMechanicalVelocity	0	0	0	0
QAxisCurrent	-636	-702	-928	-4.96875
DriveStageTemperature	5026	5026	5026	50.26
TorqueLimit	25000	25000	25000	100
IgnitionOn	1	1	1	1
ASP	0	0	0	0
EcuM__rootState_active	3	3	3	3
sSystemMode__rootState_active	2	2	2	2
AltHallTransitionTime	1710005	1710005	1710005	1710005
B92FilteredMotorVelocityError	0	0	0	0
HallSensor	2	2	2	2
DiagCommutationCentrePosition	54613	54613	54613	300.0714
EncoderPositionRegister	0	0	0	0
MotorElectricalPosition	4095	4095	4095	22.5
AltNewHallEvent	1	0	0	1
AltMotorElectricalVelocity	0	0	0	0
B92MotorVelocityErrorLimit	960	960	960	960
AltRotorDirection	-1	-1	-1	-1
AltMotorCommutationState	2	2	2	2

DistanceTravelled	19743
LifetimeCounter	5964
AccumulatedColumnMovement	1087
FastThermalEstTemperatureRise	10
ThermalEstTemperatureRise	47
VehicleTuneSelector	2
MotorTuneSelector	0
EmulationModeStatus	0
PDCStatus	1
PowerOffDriveStageTemperature	5419
CPU_PeakLoadHold	13473
TorqueReInstatmentFlag	1
IncompletePowerDownTestCount	1
padding	0
LRE_PositionState	0
PositionExtrapActive	0
EncoderOffset	0
MotorReversal	0

1	2
0	0
1.858398	1.99707
0	0
14.66406	14.62109
0	0
2503.4	2503.4
4.984375	5.828125
0	0
-5.48438	-7.25
50.26	50.26
100	100
1	1
0	0
3	3
2	2
1710005	1710005
0	0
2	2
300.0714	300.0714
0	0
22.5	22.5
0	0
0	0
960	960
-1	-1
2	2

				0
MotorMechanicalVelocity	0	0	0	0
ColumnTorque	-1166	-894	-1030	-1.13867
ColumnVelocity	0	0	0	0
vBatt	3762	3766	3771	14.69531
FilteredVehicleSpeed	0	0	0	0
Filt2v5RefVoltage	12423	12423	12423	2502.191
AssistanceTorqueDemand	-1027	-890	-957	-4.01172
FilteredMechanicalVelocity	0	0	0	0
QAxisCurrent	539	479	515	4.210938
DriveStageTemperature	495	474	481	4.95
TorqueLimit	25000	25000	25000	100
IgnitionOn	1	1	1	1
ASP	0	0	0	0
EcuM__rootState_active	3	3	3	3
sSystemMode__rootState_active	2	2	2	2
AltHallTransitionTime	1.07E+08	1.07E+08	1.07E+08	1.07E+08
B92FilteredMotorVelocityError	0	0	0	0
HallSensor	2	2	2	2
DiagCommutationCentrePosition	54613	54613	54613	300.0714
EncoderPositionRegister	0	0	0	0
MotorElectricalPosition	36855	36855	36855	202.5
AltNewHallEvent	0	0	0	-97.5714
AltMotorElectricalVelocity	0	0	0	0
B92MotorVelocityErrorLimit	960	960	960	960
AltRotorDirection	1	1	1	1
AltMotorCommutationState	2	2	2	2
DistanceTravelled	4697531			
LifetimeCounter	302743			
AccumulatedColumnMovement	7721			
FastThermalEstTemperatureRise	14			
ThermalEstTemperatureRise	74			
VehicleTuneSelector	2			
MotorTuneSelector	0			
EmulationModeStatus	0			
PDCStatus	1			
PowerOffDriveStageTemperature	742			
CPU_PeakLoadHold	13487			
TorqueReInstatmentFlag	1			
IncompletePowerDownTestCount	1			
padding	0			
LRE_PositionState	0			
PositionExtrapActive	0			
EncoderOffset	0			
MotorReversal	0			

1	2
0	0
-0.87305	-1.00586
0	0
14.71094	14.73047
0	0
2502.191	2502.191
-3.47656	-3.73828
0	0
3.742188	4.023438
4.74	4.81
100	100
1	1
0	0
3	3
2	2
1.07E+08	1.07E+08
0	0
2	2
300.0714	300.0714
0	0
202.5	202.5
-97.5714	-97.5714
0	0
960	960
1	1
2	2

				0
MotorMechanicalVelocity	0	0	0	0
ColumnTorque	432	396	446	0.421875
ColumnVelocity	-3	-3	-3	-0.00293
vBatt	3589	3589	3589	14.01953
FilteredVehicleSpeed	4796	4796	4796	74.9375
Filt2v5RefVoltage	12333	12333	12333	2484.064
AssistanceTorqueDemand	-185	-246	-217	-0.72266
FilteredMechanicalVelocity	0	0	0	0
QAxisCurrent	120	120	133	0.9375
DriveStageTemperature	4164	4163	4164	41.64
TorqueLimit	25000	25000	25000	100
IgnitionOn	1	1	1	1
ASP	409	409	409	6.390625
EcuM__rootState_active	3	3	3	3
sSystemMode__rootState_active	2	2	2	2
AltHallTransitionTime	17765938	17765938	17765938	17765938
B92FilteredMotorVelocityError	0	0	0	0
HallSensor	2	2	2	2
DiagCommutationCentrePosition	54613	54613	54613	300.0714
EncoderPositionRegister	2779	2779	2779	2779
MotorElectricalPosition	43680	43680	43680	240
AltNewHallEvent	0	0	0	-60.0714
AltMotorElectricalVelocity	0	0	0	0
B92MotorVelocityErrorLimit	960	960	960	960
AltRotorDirection	1	1	1	1
AltMotorCommutationState	2	2	2	2

DistanceTravelled	1542370
LifetimeCounter	152721
AccumulatedColumnMovement	5966
FastThermalEstTemperatureRise	49
ThermalEstTemperatureRise	319
VehicleTuneSelector	3
MotorTuneSelector	0
EmulationModeStatus	0
PDCStatus	1
PowerOffDriveStageTemperature	4198
CPU_PeakLoadHold	13739
TorqueReInstatmentFlag	1
IncompletePowerDownTestCount	1
padding	0
LRE_PositionState	0
PositionExtrapActive	0
EncoderOffset	0
MotorReversal	0



1	2
0	0
0.386719	0.435547
-0.00293	-0.00293
14.01953	14.01953
74.9375	74.9375
2484.064	2484.064
-0.96094	-0.84766
0	0
0.9375	1.039063
41.63	41.64
100	100
1	1
6.390625	6.390625
3	3
2	2
17765938	17765938
0	0
2	2
300.0714	300.0714
2779	2779
240	240
-60.0714	-60.0714
0	0
960	960
1	1
2	2

				0
MotorMechanicalVelocity	0	0	0	0
ColumnTorque	1095	1095	1095	1.069336
ColumnVelocity	0	0	0	0
vBatt	3320	3323	3324	12.96875
FilteredVehicleSpeed	0	0	0	0
Filt2v5RefVoltage	12349	12349	12349	2487.286
AssistanceTorqueDemand	442	442	442	1.726563
FilteredMechanicalVelocity	0	0	0	0
QAxisCurrent	-217	-217	-217	-1.69531
DriveStageTemperature	2371	2371	2384	23.71
TorqueLimit	25000	25000	25000	100
IgnitionOn	1	1	1	1
ASP	0	0	0	0
EcuM__rootState_active	3	3	3	3
sSystemMode__rootState_active	2	2	2	2
AltHallTransitionTime	2.8E+09	2.8E+09	2.8E+09	2.8E+09
B92FilteredMotorVelocityError	0	0	0	0
HallSensor	6	6	6	6
DiagCommutationCentrePosition	43691	43691	43691	240.0604
EncoderPositionRegister	0	0	0	0
MotorElectricalPosition	27300	27300	27300	150
AltNewHallEvent	0	0	1	0
AltMotorElectricalVelocity	0	0	0	0
B92MotorVelocityErrorLimit	960	960	960	960
AltRotorDirection	1	1	1	1
AltMotorCommutationState	6	6	6	6
DistanceTravelled	1658924			
LifetimeCounter	315516			
AccumulatedColumnMovement	6597			
FastThermalEstTemperatureRise	0			
ThermalEstTemperatureRise	33			
VehicleTuneSelector	3			
MotorTuneSelector	0			
EmulationModeStatus	0			
PDCStatus	1			
PowerOffDriveStageTemperature	-403			
CPU_PeakLoadHold	13948			
TorqueReInstatmentFlag	1			
IncompletePowerDownTestCount	1			
padding	0			
LRE_PositionState	0			
PositionExtrapActive	0			
EncoderOffset	0			
MotorReversal	0			

1	2
0	0
1.069336	1.069336
0	0
12.98047	12.98438
0	0
2487.286	2487.286
1.726563	1.726563
0	0
-1.69531	-1.69531
23.71	23.84
100	100
1	1
0	0
3	3
2	2
2.8E+09	2.8E+09
0	0
6	6
240.0604	240.0604
0	0
150	150
0	1
0	0
960	960
1	1
6	6

				0
MotorMechanicalVelocity	0	0	0	0
ColumnTorque	-1641	-1696	-1738	-1.60254
ColumnVelocity	0	0	0	0
vBatt	3406	3410	3414	13.30469
FilteredVehicleSpeed	0	0	0	0
Filt2v5RefVoltage	12412	12412	12412	2499.976
AssistanceTorqueDemand	-888	-904	-858	-3.46875
FilteredMechanicalVelocity	0	0	0	0
QAxisCurrent	460	472	484	3.59375
DriveStageTemperature	1228	1238	1222	12.28
TorqueLimit	25000	25000	25000	100
IgnitionOn	1	1	1	1
ASP	0	0	0	0
EcuM__rootState_active	3	3	3	3
sSystemMode__rootState_active	2	2	2	2
AltHallTransitionTime	27863959	27863959	27863959	27863959
B92FilteredMotorVelocityError	0	0	0	0
HallSensor	3	3	3	3
DiagCommutationCentrePosition	0	0	0	0
EncoderPositionRegister	0	0	0	0
MotorElectricalPosition	49140	49140	49140	270
AltNewHallEvent	1	0	0	270
AltMotorElectricalVelocity	0	0	0	0
B92MotorVelocityErrorLimit	960	960	960	960
AltRotorDirection	1	1	1	1
AltMotorCommutationState	3	3	3	3
DistanceTravelled	1261631			
LifetimeCounter	165814			
AccumulatedColumnMovement	8208			
FastThermalEstTemperatureRise	42			
ThermalEstTemperatureRise	179			
VehicleTuneSelector	2			
MotorTuneSelector	0			
EmulationModeStatus	0			
PDCStatus	1			
PowerOffDriveStageTemperature	2755			
CPU_PeakLoadHold	13460			
TorqueReInstatmentFlag	1			
IncompletePowerDownTestCount	1			
padding	0			
LRE_PositionState	0			
PositionExtrapActive	0			
EncoderOffset	0			
MotorReversal	0			

1	2
0	0
-1.65625	-1.69727
0	0
13.32031	13.33594
0	0
2499.976	2499.976
-3.53125	-3.35156
0	0
3.6875	3.78125
12.38	12.22
100	100
1	1
0	0
3	3
2	2
27863959	27863959
0	0
3	3
0	0
0	0
270	270
270	270
0	0
960	960
1	1
3	3

				0
MotorMechanicalVelocity	0	0	0	0
ColumnTorque	-1829	-1693	-1763	-1.78613
ColumnVelocity	0	0	0	0
vBatt	3705	3707	3707	14.47266
FilteredVehicleSpeed	38	38	38	0.59375
Filt2v5RefVoltage	12418	12418	12418	2501.184
AssistanceTorqueDemand	-988	-899	-973	-3.85938
FilteredMechanicalVelocity	0	0	0	0
QAxisCurrent	571	488	526	4.460938
DriveStageTemperature	3172	3176	3172	31.72
TorqueLimit	25000	25000	25000	100
IgnitionOn	1	1	1	1
ASP	0	0	0	0
EcuM__rootState_active	3	3	3	3
sSystemMode__rootState_active	2	2	2	2
AltHallTransitionTime	2915888	2915888	2915888	2915888
B92FilteredMotorVelocityError	0	0	0	0
HallSensor	3	3	3	3
DiagCommutationCentrePosition	0	0	0	0
EncoderPositionRegister	0	0	0	0
MotorElectricalPosition	49140	49140	49140	270
AltNewHallEvent	0	1	0	0
AltMotorElectricalVelocity	0	0	0	0
B92MotorVelocityErrorLimit	960	960	960	960
AltRotorDirection	1	1	1	1
AltMotorCommutationState	3	3	3	3
DistanceTravelled	11816			
LifetimeCounter	3282			
AccumulatedColumnMovement	943			
FastThermalEstTemperatureRise	3021			
ThermalEstTemperatureRise	1466			
VehicleTuneSelector	3			
MotorTuneSelector	0			
EmulationModeStatus	0			
PDCStatus	1			
PowerOffDriveStageTemperature	4966			
CPU_PeakLoadHold	13464			
TorqueReInstatmentFlag	1			
IncompletePowerDownTestCount	1			
padding	0			
LRE_PositionState	0			
PositionExtrapActive	0			
EncoderOffset	0			
MotorReversal	0			

1	2
0	0
-1.65332	-1.72168
0	0
14.48047	14.48047
0.59375	0.59375
2501.184	2501.184
-3.51172	-3.80078
0	0
3.8125	4.109375
31.76	31.72
100	100
1	1
0	0
3	3
2	2
2915888	2915888
0	0
3	3
0	0
0	0
270	270
1	0
0	0
960	960
1	1
3	3

				0
MotorMechanicalVelocity	-267	-448	-324	-2.08594
ColumnTorque	2463	2482	2464	2.405273
ColumnVelocity	0	0	0	0
vBatt	3720	3701	3724	14.53125
FilteredVehicleSpeed	157	155	155	2.453125
Filt2v5RefVoltage	12433	12433	12433	2504.205
AssistanceTorqueDemand	3168	3047	3176	12.375
FilteredMechanicalVelocity	-267	-448	-324	-2.08594
QAxisCurrent	-1725	-1666	-1657	-13.4766
DriveStageTemperature	3846	3846	3839	38.46
TorqueLimit	25000	25000	25000	100
IgnitionOn	1	1	1	1
ASP	-2562	-2746	-2653	-40.0313
EcuM__rootState_active	3	3	3	3
sSystemMode__rootState_active	2	2	2	2
AltHallTransitionTime	107973	119994	120002	107973
B92FilteredMotorVelocityError	17697	14581	16178	17697
HallSensor	4	1	2	4
DiagCommutationCentrePosition	43691	10923	54613	240.0604
EncoderPositionRegister	485	516	499	485
MotorElectricalPosition	37440	12933	55253	205.7143
AltNewHallEvent	1	1	1	1
AltMotorElectricalVelocity	0	0	0	0
B92MotorVelocityErrorLimit	960	960	960	960
AltRotorDirection	-1	-1	-1	-1
AltMotorCommutationState	6	5	3	6

DistanceTravelled	11372
LifetimeCounter	2826
AccumulatedColumnMovement	1034
FastThermalEstTemperatureRise	29
ThermalEstTemperatureRise	569
VehicleTuneSelector	2
MotorTuneSelector	0
EmulationModeStatus	0
PDCStatus	1
PowerOffDriveStageTemperature	3647
CPU_PeakLoadHold	13449
TorqueReInstatmentFlag	1
IncompletePowerDownTestCount	1
padding	0
LRE_PositionState	0
PositionExtrapActive	1
EncoderOffset	0
MotorReversal	1



1	2
-3.5	-2.53125
2.423828	2.40625
0	0
14.45703	14.54688
2.421875	2.421875
2504.205	2504.205
11.90234	12.40625
-3.5	-2.53125
-13.0156	-12.9453
38.46	38.39
100	100
1	1
-42.9063	-41.4531
3	3
2	2
119994	120002
14581	16178
1	2
60.01648	300.0714
516	499
71.06044	303.5879
1	1
0	0
960	960
-1	-1
5	3

				0
MotorMechanicalVelocity	-5	-5	-5	-0.03906
ColumnTorque	944	966	977	0.921875
ColumnVelocity	0	0	0	0
vBatt	3670	3677	3674	14.33594
FilteredVehicleSpeed	7837	7837	7837	122.4531
Filt2v5RefVoltage	12411	12411	12411	2499.774
AssistanceTorqueDemand	-116	-116	-115	-0.45313
FilteredMechanicalVelocity	-5	-5	-5	-0.03906
QAxisCurrent	69	60	54	0.539063
DriveStageTemperature	4531	4538	4534	45.31
TorqueLimit	25000	25000	25000	100
IgnitionOn	1	1	1	1
ASP	-29	-29	-29	-0.45313
EcuM__rootState_active	3	3	3	3
sSystemMode__rootState_active	2	2	2	2
AltHallTransitionTime	3179943	3179943	3179943	3179943
B92FilteredMotorVelocityError	0	0	0	0
HallSensor	6	6	6	6
DiagCommutationCentrePosition	43691	43691	43691	240.0604
EncoderPositionRegister	64395	64395	64395	64395
MotorElectricalPosition	32744	32744	32744	179.9121
AltNewHallEvent	0	0	0	0
AltMotorElectricalVelocity	-7	-7	-7	-7
B92MotorVelocityErrorLimit	962	962	962	962
AltRotorDirection	1	1	1	1
AltMotorCommutationState	6	6	6	6

DistanceTravelled	855553
LifetimeCounter	59735
AccumulatedColumnMovement	2650
FastThermalEstTemperatureRise	9
ThermalEstTemperatureRise	41
VehicleTuneSelector	2
MotorTuneSelector	0
EmulationModeStatus	0
PDCStatus	1
PowerOffDriveStageTemperature	2840
CPU_PeakLoadHold	13466
TorqueReInstatmentFlag	1
IncompletePowerDownTestCount	1
padding	0
LRE_PositionState	0
PositionExtrapActive	0
EncoderOffset	0
MotorReversal	0

1	2
-0.03906	-0.03906
0.943359	0.954102
0	0
14.36328	14.35156
122.4531	122.4531
2499.774	2499.774
-0.45313	-0.44922
-0.03906	-0.03906
0.46875	0.421875
45.38	45.34
100	100
1	1
-0.45313	-0.45313
3	3
2	2
3179943	3179943
0	0
6	6
240.0604	240.0604
64395	64395
179.9121	179.9121
0	0
-7	-7
962	962
1	1
6	6

				0
MotorMechanicalVelocity	2287	1767	2492	17.86719
ColumnTorque	-3963	-4689	-3362	-3.87012
ColumnVelocity	-646	-197	-184	-0.63086
vBatt	3671	3673	3715	14.33984
FilteredVehicleSpeed	693	697	693	10.82813
Filt2v5RefVoltage	12396	12396	12396	2496.753
AssistanceTorqueDemand	-9634	-12306	-6673	-37.6328
FilteredMechanicalVelocity	2287	1767	2492	17.86719
QAxisCurrent	5757	7826	2801	44.97656
DriveStageTemperature	2124	2133	2124	21.24
TorqueLimit	25000	25000	25000	100
IgnitionOn	1	1	1	1
ASP	0	0	0	0
EcuM__rootState_active	3	3	3	3
sSystemMode__rootState_active	2	2	2	2
AltHallTransitionTime	162175	161824	150006	162175
B92FilteredMotorVelocityError	5464	5343	5386	5464
HallSensor	4	2	5	4
DiagCommutationCentrePosition	32768	54613	21845	180.044
EncoderPositionRegister	1626	1629	1620	1626
MotorElectricalPosition	19094	24554	11603	104.9121
AltNewHallEvent	1	0	1	1
AltMotorElectricalVelocity	0	0	2011	0
B92MotorVelocityErrorLimit	960	960	1502	960
AltRotorDirection	1	1	1	1
AltMotorCommutationState	4	6	5	4

DistanceTravelled	40719968
LifetimeCounter	3958600
AccumulatedColumnMovement	95429
FastThermalEstTemperatureRise	14
ThermalEstTemperatureRise	40
VehicleTuneSelector	2
MotorTuneSelector	0
EmulationModeStatus	0
PDCStatus	1
PowerOffDriveStageTemperature	5165
CPU_PeakLoadHold	13438
TorqueReInstatmentFlag	1
IncompletePowerDownTestCount	1
padding	0
LRE_PositionState	0
PositionExtrapActive	0
EncoderOffset	0
MotorReversal	0

1	2
13.80469	19.46875
-4.5791	-3.2832
-0.19238	-0.17969
14.34766	14.51172
10.89063	10.82813
2496.753	2496.753
-48.0703	-26.0664
13.80469	19.46875
61.14063	21.88281
21.33	21.24
100	100
1	1
0	0
3	3
2	2
161824	150006
5343	5386
2	5
300.0714	120.0275
1629	1620
134.9121	63.75275
0	1
0	2011
960	1502
1	1
6	5

MotorMechanicalVelocity	0	0	0
ColumnTorque	0	0	0
ColumnVelocity	0	0	0
vBatt	3098	3093	3083
FilteredVehicleSpeed	0	0	0
Filt2v5RefVoltage	12344	12343	12343
AssistanceTorqueDemand	0	0	0
FilteredMechanicalVelocity	0	0	0
QAxisCurrent	-16	-8	-3
DriveStageTemperature	2899	2903	2907
TorqueLimit	0	0	0
IgnitionOn	1	1	1
ASP	0	0	0
EcuM__rootState_active	3	3	3
sSystemMode__rootState_active	2	2	2
TorquePwmPulseWidth1	0	0	0
TorquePwmPulseWidth2	0	0	0
TorquePwmPulsePeriod1	0	0	0
TorquePwmPulsePeriod2	0	0	0
TimeSinceLastEvent1	1714	1730	1747
TimeSinceLastEvent2	1714	1730	1747
AltLowTimeError1	0	0	0
AltLowTimeError2	0	0	0
DistanceTravelled	4090683		
LifetimeCounter	319039		
AccumulatedColumnMovement	9865		
FastThermalEstTemperatureRise	13		
ThermalEstTemperatureRise	21		
VehicleTuneSelector	2		
MotorTuneSelector	0		
EmulationModeStatus	0		
PDCStatus	1		
PowerOffDriveStageTemperature	2887		
CPU_PeakLoadHold	13484		
TorqueReInstatmentFlag	1		
IncompletePowerDownTestCount	1		
padding	0		
empty	27451		

				0
MotorMechanicalVelocity	0	0	0	0
ColumnTorque	4229	4259	4308	4.129883
ColumnVelocity	0	0	0	0
vBatt	3421	3420	3422	13.36328
FilteredVehicleSpeed	4	4	4	0.0625
Filt2v5RefVoltage	12397	12397	12397	2496.954
AssistanceTorqueDemand	13182	13587	13947	51.49219
FilteredMechanicalVelocity	0	0	0	0
QAxisCurrent	-7039	-7206	-7424	-54.9922
DriveStageTemperature	3633	3629	3633	36.33
TorqueLimit	25000	25000	25000	100
IgnitionOn	1	1	1	1
ASP	0	0	0	0
EcuM__rootState_active	3	3	3	3
sSystemMode__rootState_active	2	2	2	2
AltHallTransitionTime	17447895	17447895	17447895	17447895
B92FilteredMotorVelocityError	0	0	0	0
HallSensor	1	1	1	1
DiagCommutationCentrePosition	10923	10923	10923	60.01648
EncoderPositionRegister	65475	65475	65475	65475
MotorElectricalPosition	21840	21840	21840	120
AltNewHallEvent	0	0	0	0
AltMotorElectricalVelocity	0	0	0	0
B92MotorVelocityErrorLimit	960	960	960	960
AltRotorDirection	-1	-1	-1	-1
AltMotorCommutationState	1	1	1	1

DistanceTravelled	4686287
LifetimeCounter	359632
AccumulatedColumnMovement	8458
FastThermalEstTemperatureRise	17
ThermalEstTemperatureRise	23
VehicleTuneSelector	3
MotorTuneSelector	0
EmulationModeStatus	0
PDCStatus	1
PowerOffDriveStageTemperature	3563
CPU_PeakLoadHold	13367
TorqueReInstatmentFlag	1
IncompletePowerDownTestCount	1
padding	0
LRE_PositionState	0
PositionExtrapActive	0
EncoderOffset	0
MotorReversal	0

1	2
0	0
4.15918	4.207031
0	0
13.35938	13.36719
0.0625	0.0625
2496.954	2496.954
53.07422	54.48047
0	0
-56.2969	-58
36.29	36.33
100	100
1	1
0	0
3	3
2	2
17447895	17447895
0	0
1	1
60.01648	60.01648
65475	65475
120	120
0	0
0	0
960	960
-1	-1
1	1



				0
MotorMechanicalVelocity	0	0	0	0
ColumnTorque	1118	1081	1098	1.091797
ColumnVelocity	0	0	0	0
vBatt	3643	3654	3648	14.23047
FilteredVehicleSpeed	0	0	0	0
Filt2v5RefVoltage	12368	12368	12368	2491.113
AssistanceTorqueDemand	377	347	322	1.472656
FilteredMechanicalVelocity	0	0	0	0
QAxisCurrent	-197	-176	-176	-1.53906
DriveStageTemperature	1475	1479	1479	14.75
TorqueLimit	25000	25000	25000	100
IgnitionOn	1	1	1	1
ASP	0	0	0	0
EcuM__rootState_active	3	3	3	3
sSystemMode__rootState_active	2	2	2	2
AltHallTransitionTime	16319923	16319923	16319923	16319923
B92FilteredMotorVelocityError	0	0	0	0
HallSensor	1	1	1	1
DiagCommutationCentrePosition	10923	10923	10923	60.01648
EncoderPositionRegister	2	2	2	2
MotorElectricalPosition	27300	27300	27300	150
AltNewHallEvent	0	0	0	0
AltMotorElectricalVelocity	0	0	0	0
B92MotorVelocityErrorLimit	960	960	960	960
AltRotorDirection	-1	-1	-1	-1
AltMotorCommutationState	1	1	1	1

DistanceTravelled	14094330
LifetimeCounter	1008897
AccumulatedColumnMovement	21800
FastThermalEstTemperatureRise	9
ThermalEstTemperatureRise	110
VehicleTuneSelector	2
MotorTuneSelector	0
EmulationModeStatus	0
PDCStatus	1
PowerOffDriveStageTemperature	3126
CPU_PeakLoadHold	13426
TorqueReInstatmentFlag	1
IncompletePowerDownTestCount	1
padding	0
LRE_PositionState	0
PositionExtrapActive	0
EncoderOffset	0
MotorReversal	0

1	2
0	0
1.055664	1.072266
0	0
14.27344	14.25
0	0
2491.113	2491.113
1.355469	1.257813
0	0
-1.375	-1.375
14.79	14.79
100	100
1	1
0	0
3	3
2	2
16319923	16319923
0	0
1	1
60.01648	60.01648
2	2
150	150
0	0
0	0
960	960
-1	-1
1	1

				0
MotorMechanicalVelocity	436	730	564	3.40625
ColumnTorque	-3434	-2674	-2908	-3.35352
ColumnVelocity	-5	-72	-18	-0.00488
vBatt	3692	3671	3681	14.42188
FilteredVehicleSpeed	100	99	99	1.5625
Filt2v5RefVoltage	12405	12405	12405	2498.566
AssistanceTorqueDemand	-8350	-4538	-5778	-32.6172
FilteredMechanicalVelocity	436	730	564	3.40625
QAxisCurrent	4580	3093	3557	35.78125
DriveStageTemperature	1240	1233	1229	12.4
TorqueLimit	25000	25000	25000	100
IgnitionOn	1	1	1	1
ASP	0	0	0	0
EcuM__rootState_active	3	3	3	3
sSystemMode__rootState_active	2	2	2	2
AltHallTransitionTime	395951	395951	395951	395951
B92FilteredMotorVelocityError	385	261	395	385
HallSensor	2	2	2	2
DiagCommutationCentrePosition	54613	54613	54613	300.0714
EncoderPositionRegister	63971	63971	63972	63971
MotorElectricalPosition	35474	35474	36839	194.9121
AltNewHallEvent	0	1	0	0
AltMotorElectricalVelocity	0	0	0	0
B92MotorVelocityErrorLimit	960	960	960	960
AltRotorDirection	1	1	1	1
AltMotorCommutationState	2	2	2	2

DistanceTravelled	10354575	10354575	
LifetimeCounter	828077	828077	
AccumulatedColumnMovement	32918	32918	
FastThermalEstTemperatureRise	9	0.9	
ThermalEstTemperatureRise	53	5.3	
VehicleTuneSelector	2	2	
MotorTuneSelector	0	0	
EmulationModeStatus	0	0	
PDCStatus	1	Not scaled	
PowerOffDriveStageTemperature	2245	22.45	
CPU_PeakLoadHold	13392	Not scaled	
TorqueReInstatmentFlag	1	Not scaled	
IncompletePowerDownTestCount	1	Not scaled	
padding	0	Not scaled	
LRE_PositionState	0	Not scaled	
PositionExtrapActive	0	Not scaled	
EncoderOffset	0	Not scaled	
MotorReversal	0	Not scaled	

1	2
5.703125	4.40625
-2.61133	-2.83984
-0.07031	-0.01758
14.33984	14.37891
1.546875	1.546875
2498.566	2498.566
-17.7266	-22.5703
5.703125	4.40625
24.16406	27.78906
12.33	12.29
100	100
1	1
0	0
3	3
2	2
395951	395951
261	395
2	2
300.0714	300.0714
63971	63972
194.9121	202.4121
1	0
0	0
960	960
1	1
2	2

MotorMech	0	0	0	0	0	0
ColumnTor	847	782	815	0.827148	0.763672	0.795898
ColumnVel	0	0	0	0	0	0
vBatt	3528	3537	3530	13.78125	13.81641	13.78906
FilteredVel	0	0	0	0	0	0
Filt2v5Ref	12423	12423	12423	2502.191	2502.191	2502.191
Assistance	879	760	819	3.433594	2.96875	3.199219
FilteredMe	0	0	0	0	0	0
QAxisCurre	-415	-340	-370	-3.24219	-2.65625	-2.89063
DriveStage	3740	3743	3743	37.4	37.43	37.43
TorqueLimi	25000	25000	25000	100	100	100
IgnitionOn	1	1	1	1	1	1
ASP	0	0	0	0	0	0
EcuM__roc	3	3	3	3	3	3
sSystemMc	2	2	2	2	2	2
Padding	3734		0			
AltHallTran	26573893	26573893	26573893	26573893	26573893	26573893
B92Filterec	0	0	0	0	0	0
HallSensor	5	5	5	5	5	5
DiagComm	21845	21845	21845	120.0275	120.0275	120.0275
EncoderPo	2	2	2	2	2	2
MotorElect	36855	36855	36855	202.5	202.5	202.5
AltNewHall	0	0	0	0	0	0
AltMotorEl	0	0	0	0	0	0
B92MotorV	960	960	960	960	960	960
AltRotorDir	-1	-1	-1	-1	-1	-1
AltMotorCc	5	5	5	5	5	5
DistanceTr	4191383	4191383				
LifetimeCo	473916	473916				
Accumulate	14186	14186				
FastTherm	0	0				
ThermalEs	19	0.19				
VehicleTun	3	3				
MotorTune	1	1				
EmulationM	0	0				
PDCStatus	1	1				
PowerOffD	6601	66.01				
CPU_Peak	12828	12828				
TorqueReli	1	1				
Incomplete	1	1				
padding	0					
LRE_Positi	0	0				
PositionExl	0	0				
EncoderOf	0	0				
MotorReve	0	0				

MotorMechanicalVelocity	0	0	0	0	0
ColumnTorque	999	918	957	0.975586	0.896484
ColumnVelocity	0	0	0	0	0
vBatt	3606	3598	3600	14.08594	14.05469
FilteredVehicleSpeed	0	0	0	0	0
Filt2v5RefVoltage	12419	12419	12419	2501.385	2501.385
AssistanceTorqueDemand	961	808	847	3.753906	3.15625
FilteredMechanicalVelocity	0	0	0	0	0
QAxisCurrent	-430	-323	-373	-3.35938	-2.52344
DriveStageTemperature	2832	2827	2827	28.32	28.27
TorqueLimit	25000	25000	25000	100	100
IgnitionOn	1	1	1	1	1
ASP	0	0	0	0	0
EcuM__rootState_active	3	3	3	3	3
sSystemMode__rootState_active	2	2	2	2	2
Padding	2819		0		
AltHallTransitionTime	21408100	7.47E+08	21408100	21408100	7.47E+08
B92FilteredMotorVelocityError	0	0	0	0	0
HallSensor	5	5	5	5	5
DiagCommutationCentrePosition	21845	21845	21845	120.0275	120.0275
EncoderPositionRegister	0	0	0	0	0
MotorElectricalPosition	36855	36855	36855	202.5	202.5
AltNewHallEvent	0	0	0	0	0
AltMotorElectricalVelocity	0	0	0	0	0
B92MotorVelocityErrorLimit	960	960	960	960	960
AltRotorDirection	-1	-1	-1	-1	-1
AltMotorCommutationState	5	4	5	5	4
DistanceTravelled	4424043	4424043			
LifetimeCounter	312721	312721			
AccumulatedColumnMovement	8242	8242			
FastThermalEstTemperatureRise	21	0.21			
ThermalEstTemperatureRise	34	0.34			
VehicleTuneSelector	3	3			
MotorTuneSelector	1	1			
EmulationModeStatus	0	0			
PDCStatus	1	1			
PowerOffDriveStageTemperature	5725	57.25			
CPU_PeakLoadHold	12997	12997			
TorqueRelInstatmentFlag	1	1			
IncompletePowerDownTestCount	1	1			
padding	0				
LRE_PositionState	0	0			
PositionExtrapActive	0	0			
EncoderOffset	0	0			
MotorReversal	0	0			

0  
0.93457  
0  
14.0625  
0  
2501.385  
3.308594  
0  
-2.91406  
28.27  
100  
1  
0  
3  
2  
  
21408100  
0  
5  
120.0275  
0  
202.5  
0  
0  
960  
-1  
5

MotorMechanicalVelocity	0	0	0	0	0
ColumnTorque	-693	-697	-702	-0.67676	-0.68066
ColumnVelocity	0	0	0	0	0
vBatt	3521	3503	3524	13.75391	13.68359
FilteredVehicleSpeed	0	0	0	0	0
Filt2v5RefVoltage	12417	12417	12417	2500.983	2500.983
AssistanceTorqueDemand	-586	-703	-645	-2.28906	-2.74609
FilteredMechanicalVelocity	0	0	0	0	0
QAxisCurrent	256	292	301	2	2.28125
DriveStageTemperature	5707	5707	5707	57.07	57.07
TorqueLimit	25000	25000	25000	100	100
IgnitionOn	1	1	1	1	1
ASP	163	163	163	163	163
EcuM__rootState_active	3	3	3	3	3
sSystemMode__rootState_active	2	2	2	2	2
Padding	3906		0		
AltHallTransitionTime	1.32E+08	1.32E+08	1.32E+08	1.32E+08	1.32E+08
B92FilteredMotorVelocityError	0	0	0	0	0
HallSensor	4	4	4	4	4
DiagCommutationCentrePosition	32768	32768	32768	180.044	180.044
EncoderPositionRegister	1731	1731	1731	1731	1731
MotorElectricalPosition	21824	21824	21824	119.9121	119.9121
AltNewHallEvent	0	0	1	0	0
AltMotorElectricalVelocity	0	0	0	0	0
B92MotorVelocityErrorLimit	960	960	960	960	960
AltRotorDirection	1	1	1	1	1
AltMotorCommutationState	4	4	4	4	4
DistanceTravelled	5803677	5803677			
LifetimeCounter	499711	499711			
AccumulatedColumnMovement	12241	12241			
FastThermalEstTemperatureRise	12	0.12			
ThermalEstTemperatureRise	41	0.41			
VehicleTuneSelector	3	3			
MotorTuneSelector	1	1			
EmulationModeStatus	0	0			
PDCStatus	1	1			
PowerOffDriveStageTemperature	5059	50.59			
CPU_PeakLoadHold	12880	12880			
TorqueRelInstatmentFlag	1	1			
IncompletePowerDownTestCount	1	1			
padding	0				
LRE_PositionState	0	0			
PositionExtrapActive	0	0			
EncoderOffset	0	0			
MotorReversal	0	0			



0  
-0.68555  
0  
13.76563  
0  
2500.983  
-2.51953  
0  
2.351563  
57.07  
100  
1  
163  
3  
2  
  
1.32E+08  
0  
4  
180.044  
1731  
119.9121  
1  
0  
960  
1  
4

MotorMechanicalVelocity	0	0	0	0	0
ColumnTorque	-829	-893	-771	-0.80957	-0.87207
ColumnVelocity	0	0	0	0	0
vBatt	3499	3510	3489	13.66797	13.71094
FilteredVehicleSpeed	0	0	0	0	0
Filt2v5RefVoltage	12348	12348	12348	2487.085	2487.085
AssistanceTorqueDemand	-1516	-1637	-1339	-5.92188	-6.39453
FilteredMechanicalVelocity	0	0	0	0	0
QAxisCurrent	715	780	647	5.585938	6.09375
DriveStageTemperature	5022	5019	5016	50.22	50.19
TorqueLimit	25000	25000	25000	100	100
IgnitionOn	1	1	1	1	1
ASP	0	0	0	0	0
EcuM__rootState_active	3	3	3	3	3
sSystemMode__rootState_active	2	2	2	2	2
Padding	5011		0		
AltHallTransitionTime	2567874	2567874	2567874	2567874	2567874
B92FilteredMotorVelocityError	0	0	0	0	0
HallSensor	5	5	5	5	5
DiagCommutationCentrePosition	21845	21845	21845	120.0275	120.0275
EncoderPositionRegister	65535	65535	65535	65535	65535
MotorElectricalPosition	2730	2730	2730	15	15
AltNewHallEvent	0	0	0	0	0
AltMotorElectricalVelocity	0	0	0	0	0
B92MotorVelocityErrorLimit	960	960	960	960	960
AltRotorDirection	1	1	1	1	1
AltMotorCommutationState	5	5	5	5	5
DistanceTravelled	14872198	14872198			
LifetimeCounter	1061205	1061205			
AccumulatedColumnMovement	25712	25712			
FastThermalEstTemperatureRise	19	0.19			
ThermalEstTemperatureRise	31	0.31			
VehicleTuneSelector	4	4			
MotorTuneSelector	1	1			
EmulationModeStatus	0	0			
PDCStatus	1	1			
PowerOffDriveStageTemperature	6569	65.69			
CPU_PeakLoadHold	12932	12932			
TorqueRelInstatmentFlag	1	1			
IncompletePowerDownTestCount	1	1			
padding	0				
LRE_PositionState	0	0			
PositionExtrapActive	0	0			
EncoderOffset	0	0			
MotorReversal	0	0			

0  
-0.75293  
0  
13.62891  
0  
2487.085  
-5.23047  
0  
5.054688  
50.16  
100  
1  
0  
3  
2  
  
2567874  
0  
5  
120.0275  
65535  
15  
0  
0  
960  
1  
5

MotorMechanicalVelocity	0	0	0	0	0
ColumnTorque	588	627	604	0.574219	0.612305
ColumnVelocity	-3	-3	-3	-0.00293	-0.00293
vBatt	3291	3288	3295	12.85547	12.84375
FilteredVehicleSpeed	674	671	674	10.53125	10.48438
Filt2v5RefVoltage	12447	12447	12447	2507.025	2507.025
AssistanceTorqueDemand	257	84	84	1.003906	0.328125
FilteredMechanicalVelocity	0	0	0	0	0
QAxisCurrent	-115	-22	-54	-0.89844	-0.17188
DriveStageTemperature	5888	5892	5898	58.88	58.92
TorqueLimit	25000	25000	25000	100	100
IgnitionOn	1	1	1	1	1
ASP	-22	-45	-22	-22	-45
EcuM__rootState_active	3	3	3	3	3
sSystemMode__rootState_active	2	2	2	2	2
Padding	4272		0		
AltHallTransitionTime	2783903	2783903	2783903	2783903	2783903
B92FilteredMotorVelocityError	0	0	0	0	0
HallSensor	6	6	6	6	6
DiagCommutationCentrePosition	43691	43691	43691	240.0604	240.0604
EncoderPositionRegister	62174	62174	62174	62174	62174
MotorElectricalPosition	58695	58695	58695	322.5	322.5
AltNewHallEvent	0	1	0	0	1
AltMotorElectricalVelocity	0	0	0	0	0
B92MotorVelocityErrorLimit	960	960	960	960	960
AltRotorDirection	-1	-1	-1	-1	-1
AltMotorCommutationState	6	6	6	6	6
DistanceTravelled	22512731	22512731			
LifetimeCounter	1590263	1590263			
AccumulatedColumnMovement	39798	39798			
FastThermalEstTemperatureRise	47	0.47			
ThermalEstTemperatureRise	113	1.13			
VehicleTuneSelector	3	3			
MotorTuneSelector	1	1			
EmulationModeStatus	0	0			
PDCStatus	1	1			
PowerOffDriveStageTemperature	6608	66.08			
CPU_PeakLoadHold	13555	13555			
TorqueRelInstatmentFlag	1	1			
IncompletePowerDownTestCount	1	1			
padding	0				
LRE_PositionState	0	0			
PositionExtrapActive	0	0			
EncoderOffset	0	0			
MotorReversal	0	0			

0  
0.589844  
-0.00293  
12.87109  
10.53125  
2507.025  
0.328125  
0  
-0.42188  
58.98  
100  
1  
-22  
3  
2  
  
2783903  
0  
6  
240.0604  
62174  
322.5  
0  
0  
960  
-1  
6

MotorMechanicalVelocity	1093	1832	1415	8.539063	14.3125
ColumnTorque	2374	2535	2480	2.318359	2.475586
ColumnVelocity	-38	-607	-164	-0.03711	-0.59277
vBatt	3495	3493	3497	13.65234	13.64453
FilteredVehicleSpeed	1738	1735	1735	27.15625	27.10938
Filt2v5RefVoltage	12377	12377	12376	2492.926	2492.926
AssistanceTorqueDemand	1531	2303	1914	5.980469	8.996094
FilteredMechanicalVelocity	1093	1832	1415	8.539063	14.3125
QAxisCurrent	801	-490	337	6.257813	-3.82813
DriveStageTemperature	7022	7029	7029	70.22	70.29
TorqueLimit	25000	25000	25000	100	100
IgnitionOn	1	1	1	1	1
ASP	3504	3759	3759	3504	3759
EcuM__rootState_active	3	3	3	3	3
sSystemMode__rootState_active	2	2	2	2	2
Padding	4961		0		
AltHallTransitionTime	281907	251898	258024	281907	251898
B92FilteredMotorVelocityError	987	618	604	987	618
HallSensor	6	4	4	6	4
DiagCommutationCentrePosition	43691	32768	32768	240.0604	180.044
EncoderPositionRegister	1123	1123	1124	1123	1123
MotorElectricalPosition	19094	19094	20459	104.9121	104.9121
AltNewHallEvent	0	0	0	0	0
AltMotorElectricalVelocity	0	0	0	0	0
B92MotorVelocityErrorLimit	960	960	960	960	960
AltRotorDirection	1	1	1	1	1
AltMotorCommutationState	6	5	4	6	5
DistanceTravelled	6371624	6371624			
LifetimeCounter	660893	660893			
AccumulatedColumnMovement	18919	18919			
FastThermalEstTemperatureRise	17	0.17			
ThermalEstTemperatureRise	79	0.79			
VehicleTuneSelector	3	3			
MotorTuneSelector	1	1			
EmulationModeStatus	0	0			
PDCStatus	1	1			
PowerOffDriveStageTemperature	5464	54.64			
CPU_PeakLoadHold	12919	12919			
TorqueRelInstatmentFlag	1	1			
IncompletePowerDownTestCount	1	1			
padding	0				
LRE_PositionState	0	0			
PositionExtrapActive	0	0			
EncoderOffset	0	0			
MotorReversal	0	0			

11.05469  
2.421875  
-0.16016  
13.66016  
27.10938  
2492.725  
7.476563  
11.05469  
2.632813  
70.29  
100  
1  
3759  
3  
2  
  
258024  
604  
4  
180.044  
1124  
112.4121  
0  
0  
960  
1  
4

MotorMech	-2	-2	-2	-0.01563	-0.01563	-0.01563
ColumnTor	1304	1303	1307	1.273438	1.272461	1.276367
ColumnVel	0	0	0	0	0	0
vBatt	3489	3493	3485	13.62891	13.64453	13.61328
FilteredVel	0	0	0	0	0	0
Filt2v5Ref	12373	12373	12373	2492.12	2492.12	2492.12
Assistance	1921	1921	1921	7.503906	7.503906	7.503906
FilteredMe	-2	-2	-2	-0.01563	-0.01563	-0.01563
QAxisCurre	-870	-858	-878	-6.79688	-6.70313	-6.85938
DriveStage	5178	5178	5182	51.78	51.78	51.82
TorqueLimi	25000	25000	25000	100	100	100
IgnitionOn	1	1	1	1	1	1
ASP	0	0	0	0	0	0
EcuM__roc	3	3	3	3	3	3
sSystemMc	2	2	2	2	2	2
Padding	5171		0			
AltHallTran	26363944	26363944	26363944	26363944	26363944	26363944
B92Filterec	0	0	0	0	0	0
HallSensor	4	4	4	4	4	4
DiagComm	32768	32768	32768	180.044	180.044	180.044
EncoderPo	65519	65519	65519	65519	65519	65519
MotorElect	43680	43680	43680	240	240	240
AltNewHall	0	0	0	0	0	0
AltMotorEl	-3	-3	-3	-3	-3	-3
B92MotorV	961	961	961	961	961	961
AltRotorDir	-1	-1	-1	-1	-1	-1
AltMotorCc	4	4	4	4	4	4
DistanceTr	5456520	5456520				
LifetimeCo	707008	707008				
Accumulate	19052	19052				
FastTherm	20	0.2				
ThermalEs	61	0.61				
VehicleTun	3	3				
MotorTune	1	1				
EmulationM	0	0				
PDCStatus	1	1				
PowerOffD	5361	53.61				
CPU_Peak	12868	12868				
TorqueReli	1	1				
Incomplete	1	1				
padding	0					
LRE_Positi	0	0				
PositionExl	0	0				
EncoderOf	0	0				
MotorReve	0	0				



MotorMechanicalVelocity	0	0	0	0	0
ColumnTorque	1613	1605	1607	1.575195	1.567383
ColumnVelocity	-3	-3	-3	-0.00293	-0.00293
vBatt	3588	3588	3590	14.01563	14.01563
FilteredVehicleSpeed	204	201	204	3.1875	3.140625
Filt2v5RefVoltage	12385	12384	12385	2494.537	2494.336
AssistanceTorqueDemand	2225	2170	2281	8.691406	8.476563
FilteredMechanicalVelocity	0	0	0	0	0
QAxisCurrent	-1016	-985	-1002	-7.9375	-7.69531
DriveStageTemperature	3371	3375	3371	33.71	33.75
TorqueLimit	25000	25000	25000	100	100
IgnitionOn	1	1	1	1	1
ASP	-418	-418	-418	-418	-418
EcuM__rootState_active	3	3	3	3	3
sSystemMode__rootState_active	2	2	2	2	2
Padding	2694		0		
AltHallTransitionTime	34602106	34602106	34602106	34602106	34602106
B92FilteredMotorVelocityError	0	0	0	0	0
HallSensor	3	3	3	3	3
DiagCommutationCentrePosition	0	0	0	0	0
EncoderPositionRegister	254	254	254	254	254
MotorElectricalPosition	20459	20459	20459	112.4121	112.4121
AltNewHallEvent	0	0	0	0	0
AltMotorElectricalVelocity	0	0	0	0	0
B92MotorVelocityErrorLimit	960	960	960	960	960
AltRotorDirection	-1	-1	-1	-1	-1
AltMotorCommutationState	3	3	3	3	3
DistanceTravelled	7834207	7834207			
LifetimeCounter	699860	699860			
AccumulatedColumnMovement	17725	17725			
FastThermalEstTemperatureRise	9	0.09			
ThermalEstTemperatureRise	22	0.22			
VehicleTuneSelector	3	3			
MotorTuneSelector	1	1			
EmulationModeStatus	0	0			
PDCStatus	1	1			
PowerOffDriveStageTemperature	4938	49.38			
CPU_PeakLoadHold	12829	12829			
TorqueRelInstatmentFlag	1	1			
IncompletePowerDownTestCount	1	1			
padding	0				
LRE_PositionState	0	0			
PositionExtrapActive	0	0			
EncoderOffset	0	0			
MotorReversal	0	0			

0  
1.569336  
-0.00293  
14.02344  
3.1875  
2494.537  
8.910156  
0  
-7.82813  
33.71  
100  
1  
-418  
3  
2  
  
34602106  
0  
3  
0  
254  
112.4121  
0  
0  
960  
-1  
3

MotorMech	0	0	0	0	0	0
ColumnTor	380	424	582	0.371094	0.414063	0.568359
ColumnVel	-3	-3	-3	-0.00293	-0.00293	-0.00293
vBatt	3264	3260	3266	12.75	12.73438	12.75781
FilteredVel	5859	5859	5860	91.54688	91.54688	91.5625
Filt2v5Ref	12377	12377	12377	2492.926	2492.926	2492.926
Assistance	-309	-86	271	-1.20703	-0.33594	1.058594
FilteredMe	0	0	0	0	0	0
QAxisCurre	151	79	-47	1.179688	0.617188	-0.36719
DriveStage	6655	6658	6652	66.55	66.58	66.52
TorqueLimi	25000	25000	25000	100	100	100
IgnitionOn	1	1	1	1	1	1
ASP	13	13	18	13	13	18
EcuM__roc	3	3	3	3	3	3
sSystemMc	2	2	2	2	2	2
Padding	4212		0			
AltHallTran	16955997	16955997	16955997	16955997	16955997	16955997
B92Filterec	0	0	0	0	0	0
HallSensor	5	5	5	5	5	5
DiagComm	21845	21845	21845	120.0275	120.0275	120.0275
EncoderPo	65302	65301	65301	65302	65301	65301
MotorElect	9539	8174	8174	52.41209	44.91209	44.91209
AltNewHall	1	0	0	1	0	0
AltMotorEl	0	0	0	0	0	0
B92MotorV	960	960	960	960	960	960
AltRotorDir	1	1	1	1	1	1
AltMotorCc	5	5	5	5	5	5
DistanceTr	10283245	10283245				
LifetimeCo	981339	981339				
Accumulate	30246	30246				
FastTherm	94	0.94				
ThermalEs	388	3.88				
VehicleTun	4	4				
MotorTune	1	1				
EmulationM	0	0				
PDCStatus	1	1				
PowerOffD	4807	48.07				
CPU_Peak	12899	12899				
TorqueReli	1	1				
Incomplete	1	1				
padding	0					
LRE_Positi	0	0				
PositionExl	0	0				
EncoderOf	0	0				
MotorReve	0	0				

MotorMech	482	807	623	3.765625	6.304688	4.867188
ColumnTor	1348	1362	1353	1.316406	1.330078	1.321289
ColumnVel	-10	-173	-40	-0.00977	-0.16895	-0.03906
vBatt	3294	3301	3296	12.86719	12.89453	12.875
FilteredVel	629	628	628	9.828125	9.8125	9.8125
Filt2v5Ref	12449	12449	12449	2507.428	2507.428	2507.428
Assistance	1189	1247	1236	4.644531	4.871094	4.828125
FilteredMe	482	807	623	3.765625	6.304688	4.867188
QAxisCurre	263	-170	180	2.054688	-1.32813	1.40625
DriveStage	5909	5915	5918	59.09	59.15	59.18
TorqueLimi	25000	25000	25000	100	100	100
IgnitionOn	1	1	1	1	1	1
ASP	19333	19333	19333	19333	19333	19333
EcuM__roc	3	3	3	3	3	3
sSystemMc	2	2	2	2	2	2
Padding	4553		0			
AltHallTran	396015	402040	402040	396015	402040	402040
B92Filterec	142	0	0	142	0	0
HallSensor	2	6	6	2	6	6
DiagComm	54613	43691	43691	300.0714	240.0604	240.0604
EncoderPo	61974	61973	61974	61974	61973	61974
MotorElect	31379	30014	30014	172.4121	164.9121	164.9121
AltNewHall	1	1	0	1	1	0
AltMotorEl	0	0	0	0	0	0
B92MotorV	960	960	960	960	960	960
AltRotorDir	1	1	1	1	1	1
AltMotorCc	2	6	6	2	6	6
DistanceTr	8395996	8395996				
LifetimeCo	992239	992239				
Accumulate	29527	29527				
FastTherm	60	0.6				
ThermalEs	94	0.94				
VehicleTun	3	3				
MotorTune	1	1				
EmulationM	0	0				
PDCStatus	1	1				
PowerOffD	5509	55.09				
CPU_Peak	12882	12882				
TorqueReli	1	1				
Incomplete	1	1				
padding	0					
LRE_Positi	0	0				
PositionExl	0	0				
EncoderOf	0	0				
MotorReve	0	0				

MotorMech	476	448	464	3.71875	3.5	3.625
ColumnTor	2315	2282	2301	2.260742	2.228516	2.24707
ColumnVel	-190	-190	-190	-0.18555	-0.18555	-0.18555
vBatt	3626	3620	3622	14.16406	14.14063	14.14844
FilteredVel	1725	1723	1725	26.95313	26.92188	26.95313
Filt2v5Ref	12469	12469	12469	2511.456	2511.456	2511.456
Assistance	1975	2033	1968	7.714844	7.941406	7.6875
FilteredMe	476	448	464	3.71875	3.5	3.625
QAxisCurre	-867	-948	-898	-6.77344	-7.40625	-7.01563
DriveStage	3212	3219	3212	32.12	32.19	32.12
TorqueLimi	25000	25000	25000	100	100	100
IgnitionOn	1	1	1	1	1	1
ASP	3026	3026	3026	3026	3026	3026
EcuM__roc	3	3	3	3	3	3
sSystemMc	2	2	2	2	2	2
Padding	2999		0			
AltHallTran	810001	804000	804000	810001	804000	804000
B92Filterec	83	87	85	83	87	85
HallSensor	2	6	6	2	6	6
DiagComm	54613	43691	43691	300.0714	240.0604	240.0604
EncoderPo	65134	65130	65132	65134	65130	65132
MotorElect	39811	33239	36790	218.7418	182.6319	202.1429
AltNewHall	1	0	0	1	0	0
AltMotorEle	772	775	777	772	775	777
B92MotorV	1168	1169	1169	1168	1169	1169
AltRotorDir	1	1	1	1	1	1
AltMotorCc	2	6	6	2	6	6
DistanceTr	3937673	3937673				
LifetimeCo	401430	401430				
Accumulate	10469	10469				
FastTherm	43	0.43				
ThermalEs	78	0.78				
VehicleTun	4	4				
MotorTune	1	1				
EmulationM	0	0				
PDCStatus	1	1				
PowerOffD	2937	29.37				
CPU_Peak	12840	12840				
TorqueReli	1	1				
Incomplete	1	1				
padding	0					
LRE_Positi	0	0				
PositionExl	1	1				
EncoderOf	0	0				
MotorReve	0	0				

MotorMechanicalVelocity	0	0	0	0	0
ColumnTorque	-2307	-2292	-2298	-2.25293	-2.23828
ColumnVelocity	-3	-3	-3	-0.00293	-0.00293
vBatt	3611	3611	3611	14.10547	14.10547
FilteredVehicleSpeed	5219	5220	5220	81.54688	81.5625
Filt2v5RefVoltage	12384	12384	12384	2494.336	2494.336
AssistanceTorqueDemand	-1115	-1158	-1138	-4.35547	-4.52344
FilteredMechanicalVelocity	0	0	0	0	0
QAxisCurrent	514	559	538	4.015625	4.367188
DriveStageTemperature	4260	4257	4260	42.6	42.57
TorqueLimit	25000	25000	25000	100	100
IgnitionOn	1	1	1	1	1
ASP	-354	-354	-354	-354	-354
EcuM__rootState_active	3	3	3	3	3
sSystemMode__rootState_active	2	2	2	2	2
Padding	2593		0		
AltHallTransitionTime	34398008	34398008	34398008	34398008	34398008
B92FilteredMotorVelocityError	0	2	0	0	2
HallSensor	1	1	1	1	1
DiagCommutationCentrePosition	10923	10923	10923	60.01648	60.01648
EncoderPositionRegister	550	550	550	550	550
MotorElectricalPosition	58695	58695	58695	322.5	322.5
AltNewHallEvent	0	0	0	0	0
AltMotorElectricalVelocity	0	0	0	0	0
B92MotorVelocityErrorLimit	960	960	960	960	960
AltRotorDirection	1	1	1	1	1
AltMotorCommutationState	1	1	1	1	1
DistanceTravelled	5414600	5414600			
LifetimeCounter	459294	459294			
AccumulatedColumnMovement	19493	19493			
FastThermalEstTemperatureRise	20	0.2			
ThermalEstTemperatureRise	46	0.46			
VehicleTuneSelector	3	3			
MotorTuneSelector	1	1			
EmulationModeStatus	0	0			
PDCStatus	1	1			
PowerOffDriveStageTemperature	5409	54.09			
CPU_PeakLoadHold	12968	12968			
TorqueRelInstatmentFlag	1	1			
IncompletePowerDownTestCount	1	1			
padding	0				
LRE_PositionState	0	0			
PositionExtrapActive	0	0			
EncoderOffset	0	0			
MotorReversal	0	0			

0  
-2.24414  
-0.00293  
14.10547  
81.5625  
2494.336  
-4.44531  
0  
4.203125  
42.6  
100  
1  
-354  
3  
2  
  
34398008  
0  
1  
60.01648  
550  
322.5  
0  
0  
960  
1  
1

MotorMech	91	70	54	0.710938	0.546875	0.421875
ColumnTor	-2731	-2842	-2997	-2.66699	-2.77539	-2.92676
ColumnVel	-3	-3	-3	-0.00293	-0.00293	-0.00293
vBatt	3470	3478	3480	13.55469	13.58594	13.59375
FilteredVel	1772	1772	1769	27.6875	27.6875	27.64063
Filt2v5Ref	12322	12322	12322	2481.848	2481.848	2481.848
Assistance	-2783	-3294	-3816	-10.8711	-12.8672	-14.9063
FilteredMe	91	70	54	0.710938	0.546875	0.421875
QAxisCurre	1527	1690	1944	11.92969	13.20313	15.1875
DriveStage	6394	6383	6394	63.94	63.83	63.94
TorqueLimi	25000	25000	25000	100	100	100
IgnitionOn	1	1	1	1	1	1
ASP	-136	-136	-136	-136	-136	-136
EcuM__roc	3	3	3	3	3	3
sSystemMc	2	2	2	2	2	2
Padding	5845		0			
AltHallTran	791913	791913	791913	791913	791913	791913
B92Filterec	399	459	448	399	459	448
HallSensor	1	1	1	1	1	1
DiagComm	10923	10923	10923	60.01648	60.01648	60.01648
EncoderPo	64767	64768	64767	64767	64768	64767
MotorElect	57330	58695	57330	315	322.5	315
AltNewHall	1	0	0	1	0	0
AltMotorEl	0	0	0	0	0	0
B92MotorV	960	960	960	960	960	960
AltRotorDir	1	1	1	1	1	1
AltMotorCc	1	1	1	1	1	1
DistanceTr	2663104	2663104				
LifetimeCo	458541	458541				
Accumulate	14612	14612				
FastTherm	14	0.14				
ThermalEs	49	0.49				
VehicleTun	3	3				
MotorTune	1	1				
EmulationM	0	0				
PDCStatus	1	1				
PowerOffD	6008	60.08				
CPU_Peak	12883	12883				
TorqueReli	1	1				
Incomplete	1	1				
padding	0					
LRE_Positi	0	0				
PositionExl	0	0				
EncoderOf	0	0				
MotorReve	0	0				



MotorMech	126	97	163	0.984375	0.757813	1.273438
ColumnTor	-1472	-1544	-1421	-1.4375	-1.50781	-1.3877
ColumnVel	-3	-3	-4	-0.00293	-0.00293	-0.00391
vBatt	3303	3303	3303	12.90234	12.90234	12.90234
FilteredVel	312	312	312	4.875	4.875	4.875
Filt2v5Ref	12420	12420	12420	2501.587	2501.587	2501.587
Assistance	-1419	-1554	-1257	-5.54297	-6.07031	-4.91016
FilteredMe	126	97	163	0.984375	0.757813	1.273438
QAxisCurre	673	733	676	5.257813	5.726563	5.28125
DriveStage	4109	4109	4105	41.09	41.09	41.05
TorqueLimi	25000	25000	25000	100	100	100
IgnitionOn	1	1	1	1	1	1
ASP	555	509	555	555	509	555
EcuM__roc	3	3	3	3	3	3
sSystemMc	2	2	2	2	2	2
Padding	3433		0			
AltHallTran	1175927	1175927	1175927	1175927	1175927	1175927
B92Filterec	90	88	94	90	88	94
HallSensor	1	1	1	1	1	1
DiagComm	10923	10923	10923	60.01648	60.01648	60.01648
EncoderPo	65402	65403	65401	65402	65403	65401
MotorElect	64155	65088	62790	352.5	357.6264	345
AltNewHall	0	0	0	0	0	0
AltMotorEl	0	0	0	0	0	0
B92MotorV	960	960	960	960	960	960
AltRotorDir	1	1	1	1	1	1
AltMotorCc	1	1	1	1	1	1
DistanceTr	2830895	2830895				
LifetimeCo	283078	283078				
Accumulate	9542	9542				
FastTherm	564	5.64				
ThermalEs	372	3.72				
VehicleTun	4	4				
MotorTune	1	1				
EmulationM	0	0				
PDCStatus	1	1				
PowerOffD	3775	37.75				
CPU_Peak	12956	12956				
TorqueReli	1	1				
Incomplete	1	1				
padding	0					
LRE_Positi	0	0				
PositionExl	1	1				
EncoderOf	0	0				
MotorReve	0	0				

MotorMech	0	0	0	0	0	0
ColumnTor	468	462	437	0.457031	0.451172	0.426758
ColumnVel	-3	-3	-3	-0.00293	-0.00293	-0.00293
vBatt	3319	3311	3323	12.96484	12.93359	12.98047
FilteredVel	3417	3417	3417	53.39063	53.39063	53.39063
Filt2v5Ref	12351	12351	12351	2487.689	2487.689	2487.689
Assistance	299	180	298	1.167969	0.703125	1.164063
FilteredMe	0	0	0	0	0	0
QAxisCurre	-133	-80	-127	-1.03906	-0.625	-0.99219
DriveStage	4949	4949	4953	49.49	49.49	49.53
TorqueLimi	25000	25000	25000	100	100	100
IgnitionOn	1	1	1	1	1	1
ASP	-68	-68	-68	-68	-68	-68
EcuM__roc	3	3	3	3	3	3
sSystemMc	2	2	2	2	2	2
Padding	2762		0			
AltHallTran	1344013	1344013	1344013	1344013	1344013	1344013
B92Filterec	0	0	0	0	0	0
HallSensor	1	1	1	1	1	1
DiagComm	10923	10923	10923	60.01648	60.01648	60.01648
EncoderPo	431	431	431	431	431	431
MotorElect	65520	65520	65520	360	360	360
AltNewHall	0	0	0	0	0	0
AltMotorEl	0	0	0	0	0	0
B92MotorV	960	960	960	960	960	960
AltRotorDir	1	1	1	1	1	1
AltMotorCc	1	1	1	1	1	1
DistanceTr	13852987	13852987				
LifetimeCo	838181	838181				
Accumulate	14055	14055				
FastTherm	37	0.37				
ThermalEs	33	0.33				
VehicleTun	4	4				
MotorTune	1	1				
EmulationM	0	0				
PDCStatus	1	1				
PowerOffD	3832	38.32				
CPU_Peak	12887	12887				
TorqueReli	1	1				
Incomplete	1	1				
padding	0					
LRE_Positi	0	0				
PositionExl	0	0				
EncoderOf	0	0				
MotorReve	0	0				

MotorMech	0	0	8	0	0	0.0625
ColumnTor	360	344	326	0.351563	0.335938	0.318359
ColumnVel	-3	-3	-7	-0.00293	-0.00293	-0.00684
vBatt	3619	3608	3610	14.13672	14.09375	14.10156
FilteredVel	2667	2667	2666	41.67188	41.67188	41.65625
Filt2v5Ref	12487	12487	12487	2515.082	2515.082	2515.082
Assistance	-287	-222	-241	-1.12109	-0.86719	-0.94141
FilteredMe	0	0	8	0	0	0.0625
QAxisCurre	150	103	116	1.171875	0.804688	0.90625
DriveStage	3465	3461	3468	34.65	34.61	34.68
TorqueLimi	25000	25000	25000	100	100	100
IgnitionOn	1	1	1	1	1	1
ASP	366	366	361	366	366	361
EcuM__roc	3	3	3	3	3	3
sSystemMc	2	2	2	2	2	2
AltHallTran	4517877	4517877	4517877	4517877	4517877	4517877
B92Filterec	12	23	21	12	23	21
HallSensor	1	1	1	1	1	1
DiagComm	10923	10923	10923	60.01648	60.01648	60.01648
EncoderPo	687	687	688	687	687	688
MotorElect	60060	60060	61425	330	330	337.5
AltNewHall	1	0	0	1	0	0
AltMotorEl	0	0	96	0	0	96
B92MotorV	960	960	985	960	960	985
AltRotorDir	1	1	1	1	1	1
AltMotorCc	1	1	1	1	1	1

DistanceTr	1232248	1232248
LifetimeCo	150498	150498
Accumulate	7360	7360
FastTherm	65	0.65
ThermalEs	114	1.14
VehicleTun	1	1
MotorTune	0	0
EmulationM	0	0
PDCStatus	1	1
PowerOffD	2483	24.83
CPU_Peak	13477	13477
TorqueReli	1	1
Incomplete	1	1
padding	0	
LRE_Positi	0	0
PositionExl	0	0
EncoderOf	0	0
MotorReve	0	0

MotorMech	0	0	0	0	0	0
ColumnTor	2103	2151	2195	2.053711	2.100586	2.143555
ColumnVel	0	0	0	0	0	0
vBatt	3205	3209	3205	12.51953	12.53516	12.51953
FilteredVel	62	61	61	0.96875	0.953125	0.953125
Filt2v5Ref	12416	12416	12416	2500.781	2500.781	2500.781
Assistance	1256	1345	1434	4.90625	5.253906	5.601563
FilteredMe	0	0	0	0	0	0
QAxisCurre	-677	-712	-762	-5.28906	-5.5625	-5.95313
DriveStage	2773	2779	2774	27.73	27.79	27.74
TorqueLimi	18750	18800	18850	75	75.2	75.4
IgnitionOn	1	1	1	1	1	1
ASP	0	0	0	0	0	0
EcuM__roc	3	3	3	3	3	3
sSystemMc	2	2	2	2	2	2
AltHallTran	9294036	9294036	9294036	9294036	9294036	9294036
B92Filterec	0	0	0	0	0	0
HallSensor	1	1	1	1	1	1
DiagComm	10923	10923	10923	60.01648	60.01648	60.01648
EncoderPo	65534	65534	65534	65534	65534	65534
MotorElect	27300	27300	27300	150	150	150
AltNewHall	0	0	0	0	0	0
AltMotorEl	0	0	0	0	0	0
B92MotorV	960	960	960	960	960	960
AltRotorDir	-1	-1	-1	-1	-1	-1
AltMotorCc	1	1	1	1	1	1

DistanceTr	2918534	2918534
LifetimeCo	323418	323418
Accumulate	13499	13499
FastTherm	32	0.32
ThermalEs	69	0.69
VehicleTun	1	1
MotorTune	0	0
EmulationM	0	0
PDCStatus	1	1
PowerOffD	4090	40.9
CPU_Peak	13488	13488
TorqueReli	1	1
Incomplete	1	1
padding	0	
LRE_Positi	0	0
PositionExl	0	0
EncoderOf	0	0
MotorReve	0	0

MotorMech	-42	-35	-27	-0.32813	-0.27344	-0.21094
ColumnTor	-3020	-3095	-3241	-2.94922	-3.02246	-3.16504
ColumnVel	0	0	0	0	0	0
vBatt	3440	3440	3444	13.4375	13.4375	13.45313
FilteredVel	811	811	813	12.67188	12.67188	12.70313
Filt2v5Ref	12502	12502	12502	2518.103	2518.103	2518.103
Assistance	-3700	-4095	-4717	-14.4531	-15.9961	-18.4258
FilteredMe	-42	-35	-27	-0.32813	-0.27344	-0.21094
QAxisCurre	1897	2161	2368	14.82031	16.88281	18.5
DriveStage	4269	4266	4273	42.69	42.66	42.73
TorqueLimi	25000	25000	25000	100	100	100
IgnitionOn	1	1	1	1	1	1
ASP	-16274	-16268	-16283	-16274	-16268	-16283
EcuM__roc	3	3	3	3	3	3
sSystemMc	2	2	2	2	2	2
AltHallTran	2087946	2087946	2087946	2087946	2087946	2087946
B92Filterec	0	0	0	0	0	0
HallSensor	5	5	5	5	5	5
DiagComm	21845	21845	21845	120.0275	120.0275	120.0275
EncoderPo	2830	2829	2830	2830	2829	2830
MotorElect	36839	35474	36839	202.4121	194.9121	202.4121
AltNewHall	1	0	0	1	0	0
AltMotorEl	0	0	0	0	0	0
B92MotorV	960	960	960	960	960	960
AltRotorDir	-1	-1	-1	-1	-1	-1
AltMotorCc	5	5	5	5	5	5

DistanceTr	29789440	29789440
LifetimeCo	1766476	1766476
Accumulate	36332	36332
FastTherm	14	0.14
ThermalEs	44	0.44
VehicleTun	1	1
MotorTune	0	0
EmulationM	0	0
PDCStatus	1	1
PowerOffD	4212	42.12
CPU_Peak	13568	13568
TorqueReli	1	1
Incomplete	1	1
padding	0	
LRE_Positi	0	0
PositionExl	0	0
EncoderOf	0	0
MotorReve	0	0

MotorMech	0	0	14	0	0	0.109375
ColumnTor	-1410	-1401	-1440	-1.37695	-1.36816	-1.40625
ColumnVel	-3	-3	-16	-0.00293	-0.00293	-0.01563
vBatt	3408	3406	3412	13.3125	13.30469	13.32813
FilteredVel	2788	2788	2788	43.5625	43.5625	43.5625
Filt2v5Ref	12413	12413	12413	2500.177	2500.177	2500.177
Assistance	-357	-212	-359	-1.39453	-0.82813	-1.40234
FilteredMe	0	0	14	0	0	0.109375
QAxisCurre	149	153	176	1.164063	1.195313	1.375
DriveStage	6791	6784	6794	67.91	67.84	67.94
TorqueLimi	25000	25000	25000	100	100	100
IgnitionOn	1	1	1	1	1	1
ASP	-42	-48	-48	-42	-48	-48
EcuM__roc	3	3	3	3	3	3
sSystemMc	2	2	2	2	2	2
AltHallTran	52235934	52235934	52235934	52235934	52235934	52235934
B92Filterec	0	0	0	0	0	0
HallSensor	4	4	4	4	4	4
DiagComm	32768	32768	32768	180.044	180.044	180.044
EncoderPo	62689	62690	62690	62689	62690	62690
MotorElect	16364	17729	17729	89.91209	97.41209	97.41209
AltNewHall	0	0	0	0	0	0
AltMotorEl	0	0	72	0	0	72
B92MotorV	960	960	979	960	960	979
AltRotorDir	1	1	1	1	1	1
AltMotorCc	4	4	4	4	4	4

DistanceTr	8998565	8998565
LifetimeCo	1022664	1022664
Accumulate	37997	37997
FastTherm	254	2.54
ThermalEs	352	3.52
VehicleTun	1	1
MotorTune	0	0
EmulationM	0	0
PDCStatus	1	1
PowerOffD	5291	52.91
CPU_Peak	13546	13546
TorqueReli	1	1
Incomplete	1	1
padding	0	
LRE_Positi	0	0
PositionExl	0	0
EncoderOf	0	0
MotorReve	0	0

MotorMech	-399	-308	-484	-3.11719	-2.40625	-3.78125
ColumnTor	-2330	-2358	-2323	-2.27539	-2.30273	-2.26855
ColumnVel	10	1	35	0.009766	0.000977	0.03418
vBatt	3441	3437	3445	13.44141	13.42578	13.45703
FilteredVel	2004	2006	2004	31.3125	31.34375	31.3125
Filt2v5Ref	12397	12397	12397	2496.954	2496.954	2496.954
Assistance	-916	-1016	-791	-3.57813	-3.96875	-3.08984
FilteredMe	-399	-308	-484	-3.11719	-2.40625	-3.78125
QAxisCurre	11	-76	195	0.085938	-0.59375	1.523438
DriveStage	4779	4779	4772	47.79	47.79	47.72
TorqueLimi	25000	25000	25000	100	100	100
IgnitionOn	1	1	1	1	1	1
ASP	-5071	-5071	-5065	-5071	-5071	-5065
EcuM__roc	3	3	3	3	3	3
sSystemMc	2	2	2	2	2	2
AltHallTran	515917	527927	515917	515917	527927	515917
B92Filterec	213	314	109	213	314	109
HallSensor	6	4	6	6	4	6
DiagComm	43691	32768	43691	240.0604	180.044	240.0604
EncoderPo	932	932	931	932	932	931
MotorElect	58695	58695	57330	322.5	322.5	315
AltNewHall	0	1	1	0	1	1
AltMotorEl	0	0	0	0	0	0
B92MotorV	960	960	960	960	960	960
AltRotorDir	-1	-1	-1	-1	-1	-1
AltMotorCc	6	4	6	6	4	6

DistanceTr	10639777	10639777
LifetimeCo	763666	763666
Accumulate	22093	22093
FastTherm	17	0.17
ThermalEs	52	0.52
VehicleTun	1	1
MotorTune	0	0
EmulationM	0	0
PDCStatus	1	1
PowerOffD	5800	58
CPU_Peak	13530	13530
TorqueReli	1	1
Incomplete	1	1
padding	0	
LRE_Positi	0	0
PositionExl	0	0
EncoderOf	0	0
MotorReve	0	0

MotorMech	0	0	0	0	0	0
ColumnTor	1052	1056	1056	1.027344	1.03125	1.03125
ColumnVel	0	0	0	0	0	0
vBatt	3468	3472	3458	13.54688	13.5625	13.50781
FilteredVel	0	0	0	0	0	0
Filt2v5Ref	12418	12418	12418	2501.184	2501.184	2501.184
Assistance	1011	1011	952	3.949219	3.949219	3.71875
FilteredMe	0	0	0	0	0	0
QAxisCurre	-464	-509	-421	-3.625	-3.97656	-3.28906
DriveStage	5746	5736	5736	57.46	57.36	57.36
TorqueLimi	25000	25000	25000	100	100	100
IgnitionOn	1	1	1	1	1	1
ASP	0	0	0	0	0	0
EcuM__roc	3	3	3	3	3	3
sSystemMc	2	2	2	2	2	2
Padding	5633		0			
AltHallTran	1.03E+08	1.03E+08	1.03E+08	1.03E+08	1.03E+08	1.03E+08
B92Filterec	0	0	0	0	0	0
HallSensor	2	2	2	2	2	2
DiagComm	54613	54613	54613	300.0714	300.0714	300.0714
EncoderPo	2	2	2	2	2	2
MotorElect	4095	4095	4095	22.5	22.5	22.5
AltNewHall	1	0	0	1	0	0
AltMotorEl	0	0	0	0	0	0
B92MotorV	960	960	960	960	960	960
AltRotorDir	-1	-1	-1	-1	-1	-1
AltMotorCc	2	2	2	2	2	2
DistanceTr	10164804	10164804				
LifetimeCo	912037	912037				
Accumulate	19019	19019				
FastTherm	19	0.19				
ThermalEs	63	0.63				
VehicleTun	4	4				
MotorTune	1	1				
EmulationM	0	0				
PDCStatus	1	1				
PowerOffD	6905	69.05				
CPU_Peak	12842	12842				
TorqueReli	1	1				
Incomplete	1	1				
padding	0					
LRE_Positi	0	0				
PositionExl	0	0				
EncoderOf	0	0				
MotorReve	0	0				



MotorMech	0	0	0	0	0	0
ColumnTor	1611	1618	1619	1.573242	1.580078	1.581055
ColumnVel	0	0	0	0	0	0
vBatt	3299	3297	3299	12.88672	12.87891	12.88672
FilteredVel	4806	4806	4806	75.09375	75.09375	75.09375
Filt2v5Ref	12352	12352	12352	2487.891	2487.891	2487.891
Assistance	547	548	571	2.136719	2.140625	2.230469
FilteredMe	0	0	0	0	0	0
QAxisCurre	-246	-255	-255	-1.92188	-1.99219	-1.99219
DriveStage	3750	3753	3753	37.5	37.53	37.53
TorqueLimi	25000	25000	25000	100	100	100
IgnitionOn	1	1	1	1	1	1
ASP	13	18	18	13	18	18
EcuM__roc	3	3	3	3	3	3
sSystemMc	2	2	2	2	2	2
Padding	3409		0			
AltHallTran	8207914	8207914	8207914	8207914	8207914	8207914
B92Filterec	0	0	0	0	0	0
HallSensor	6	6	6	6	6	6
DiagComm	43691	43691	43691	240.0604	240.0604	240.0604
EncoderPo	65426	65426	65426	65426	65426	65426
MotorElect	58695	58695	58695	322.5	322.5	322.5
AltNewHall	0	0	0	0	0	0
AltMotorEl	0	0	0	0	0	0
B92MotorV	960	960	960	960	960	960
AltRotorDir	-1	-1	-1	-1	-1	-1
AltMotorCc	6	6	6	6	6	6
DistanceTr	11988558	11988558				
LifetimeCo	786132	786132				
Accumulate	14972	14972				
FastTherm	16	0.16				
ThermalEs	46	0.46				
VehicleTun	3	3				
MotorTune	1	1				
EmulationM	0	0				
PDCStatus	1	1				
PowerOffD	5822	58.22				
CPU_Peak	12799	12799				
TorqueReli	1	1				
Incomplete	1	1				
padding	0					
LRE_Positi	0	0				
PositionExt	0	0				
EncoderOf	0	0				
MotorReve	0	0				

MotorMech	0	0	0	0	0	0
ColumnTor	1130	1221	1326	1.103516	1.192383	1.294922
ColumnVel	0	0	0	0	0	0
vBatt	3572	3568	3570	13.95313	13.9375	13.94531
FilteredVel	0	0	0	0	0	0
Filt2v5Ref	12402	12402	12402	2497.961	2497.961	2497.961
Assistance	1770	1953	2315	6.914063	7.628906	9.042969
FilteredMe	0	0	0	0	0	0
QAxisCurre	-820	-857	-1031	-6.40625	-6.69531	-8.05469
DriveStage	5814	5814	5814	58.14	58.14	58.14
TorqueLimi	25000	25000	25000	100	100	100
IgnitionOn	1	1	1	1	1	1
ASP	-7491	-7491	-7486	-7491	-7491	-7486
EcuM__roc	3	3	3	3	3	3
sSystemMc	2	2	2	2	2	2
Padding	3088		0			
AltHallTran	3.98E+09	2778118	2778118	3.98E+09	2778118	2778118
B92Filterec	0	0	0	0	0	0
HallSensor	3	3	3	3	3	3
DiagComm	0	0	0	0	0	0
EncoderPo	1446	1447	1446	1446	1447	1446
MotorElect	20459	21824	20459	112.4121	119.9121	112.4121
AltNewHall	0	0	0	0	0	0
AltMotorEl	0	0	0	0	0	0
B92MotorV	960	960	960	960	960	960
AltRotorDir	-1	-1	-1	-1	-1	-1
AltMotorCc	1	3	3	1	3	3
DistanceTr	25535391	25535391				
LifetimeCo	1702577	1702577				
Accumulate	36190	36190				
FastTherm	115	1.15				
ThermalEs	157	1.57				
VehicleTun	3	3				
MotorTune	1	1				
EmulationM	0	0				
PDCStatus	1	1				
PowerOffD	6600	66				
CPU_Peak	13024	13024				
TorqueReli	1	1				
Incomplete	1	1				
padding	0					
LRE_Positi	0	0				
PositionExt	0	0				
EncoderOf	0	0				
MotorReve	0	0				

MotorMech	61	47	79	0.476563	0.367188	0.617188
ColumnTor	-2435	-2569	-2335	-2.37793	-2.50879	-2.28027
ColumnVel	-3	-3	-3	-0.00293	-0.00293	-0.00293
vBatt	3313	3307	3319	12.94141	12.91797	12.96484
FilteredVer	2206	2206	2209	34.46875	34.46875	34.51563
Filt2v5Ref	12434	12434	12434	2504.407	2504.407	2504.407
Assistance	-2493	-2922	-2171	-9.73828	-11.4141	-8.48047
FilteredMer	61	47	79	0.476563	0.367188	0.617188
QAxisCurre	1161	1345	1078	9.070313	10.50781	8.421875
DriveStage	4857	4864	4857	48.57	48.64	48.57
TorqueLimi	25000	25000	25000	100	100	100
IgnitionOn	1	1	1	1	1	1
ASP	-737	-737	-737	-737	-737	-737
EcuM__roc	3	3	3	3	3	3
sSystemMc	2	2	2	2	2	2
Padding	3917		0			
AltHallTran	1235854	1235854	1235854	1235854	1235854	1235854
B92Filterec	87	85	89	87	85	89
HallSensor	1	1	1	1	1	1
DiagComm	10923	10923	10923	60.01648	60.01648	60.01648
EncoderPo	114	115	113	114	115	113
MotorElect	58695	60060	57330	322.5	330	315
AltNewHall	0	0	0	0	0	0
AltMotorEl	0	0	0	0	0	0
B92MotorV	960	960	960	960	960	960
AltRotorDir	1	1	1	1	1	1
AltMotorCc	1	1	1	1	1	1
DistanceTr	10260884	10260884				
LifetimeCo	816674	816674				
Accumulate	18614	18614				
FastTherm	40	0.4				
ThermalEs	79	0.79				
VehicleTun	3	3				
MotorTune	1	1				
EmulationM	0	0				
PDCStatus	1	1				
PowerOffD	6209	62.09				
CPU_Peak	12834	12834				
TorqueReli	1	1				
Incomplete	1	1				
padding	0					
LRE_Positi	0	0				
PositionExt	1	1				
EncoderOf	0	0				
MotorReve	0	0				

MotorMech	648	1086	839	5.0625	8.484375	6.554688
ColumnTor	-2710	-2023	-2213	-2.64648	-1.97559	-2.16113
ColumnVel	-11	-206	-47	-0.01074	-0.20117	-0.0459
vBatt	3569	3558	3569	13.94141	13.89844	13.94141
FilteredVel	280	279	279	4.375	4.359375	4.359375
Filt2v5Ref	12448	12448	12448	2507.227	2507.227	2507.227
Assistance	-8371	-4558	-5739	-32.6992	-17.8047	-22.418
FilteredMer	648	1086	839	5.0625	8.484375	6.554688
QAxisCurre	4088	2787	3574	31.9375	21.77344	27.92188
DriveStage	3167	3171	3174	31.67	31.71	31.74
TorqueLimi	25000	25000	25000	100	100	100
IgnitionOn	1	1	1	1	1	1
ASP	0	0	0	0	0	0
EcuM__roc	3	3	3	3	3	3
sSystemMc	2	2	2	2	2	2
Padding	3145		0			
AltHallTran	348100	311829	348100	348100	311829	348100
B92Filterec	790	495	645	790	495	645
HallSensor	2	6	2	2	6	2
DiagComm	54613	43691	54613	300.0714	240.0604	300.0714
EncoderPo	2532	2532	2531	2532	2532	2531
MotorElect	31379	31379	30014	172.4121	172.4121	164.9121
AltNewHall	0	1	1	0	1	1
AltMotorEk	0	0	0	0	0	0
B92MotorV	960	960	960	960	960	960
AltRotorDir	1	1	1	1	1	1
AltMotorCc	2	6	2	2	6	2
DistanceTr	6710139	6710139				
LifetimeCo	469090	469090				
Accumulate	10734	10734				
FastTherm	18	0.18				
ThermalEs	36	0.36				
VehicleTun	4	4				
MotorTune	1	1				
EmulationM	0	0				
PDCStatus	1	1				
PowerOffD	5291	52.91				
CPU_Peak	12823	12823				
TorqueReli	1	1				
Incomplete	1	1				
padding	0					
LRE_Positi	0	0				
PositionExt	0	0				
EncoderOf	0	0				
MotorReve	0	0				

MotorMech	0	-1	0	0	-0.00781	0
ColumnTor	-255	-285	-266	-0.24902	-0.27832	-0.25977
ColumnVel	0	0	0	0	0	0
vBatt	3595	3595	3591	14.04297	14.04297	14.02734
FilteredVel	3931	3931	3931	61.42188	61.42188	61.42188
Filt2v5Ref	12352	12352	12352	2487.891	2487.891	2487.891
Assistance	328	402	365	1.28125	1.570313	1.425781
FilteredMe	0	-1	0	0	-0.00781	0
QAxisCurre	-139	-180	-172	-1.08594	-1.40625	-1.34375
DriveStage	3685	3682	3678	36.85	36.82	36.78
TorqueLimi	25000	25000	25000	100	100	100
IgnitionOn	1	1	1	1	1	1
ASP	-286	-277	-277	-286	-277	-277
EcuM__roc	3	3	3	3	3	3
sSystemMc	2	2	2	2	2	2
Padding	2910		0			
AltHallTran	3863824	3863824	3863824	3863824	3863824	3863824
B92Filterec	25	14	27	25	14	27
HallSensor	3	3	3	3	3	3
DiagComm	0	0	0	0	0	0
EncoderPo	68	68	68	68	68	68
MotorElect	20475	20475	20475	112.5	112.5	112.5
AltNewHall	0	1	0	0	1	0
AltMotorEl	0	0	0	0	0	0
B92MotorV	960	960	960	960	960	960
AltRotorDir	-1	-1	-1	-1	-1	-1
AltMotorCc	3	3	3	3	3	3
DistanceTr	2941655	2941655				
LifetimeCo	243587	243587				
Accumulat	6105	6105				
FastTherm	14	0.14				
ThermalEs	38	0.38				
VehicleTun	3	3				
MotorTune	1	1				
EmulationM	0	0				
PDCStatus	1	1				
PowerOffD	5885	58.85				
CPU_Peak	12857	12857				
TorqueReli	1	1				
Incomplete	1	1				
padding	0					
LRE_Positi	0	0				
PositionExt	0	0				
EncoderOf	0	0				
MotorReve	0	0				

MotorMech	-596	-460	-356	-4.65625	-3.59375	-2.78125
ColumnTor	2294	2595	3117	2.240234	2.53418	3.043945
ColumnVel	19	3	0	0.018555	0.00293	0
vBatt	3292	3296	3298	12.85938	12.875	12.88281
FilteredVel	1216	1216	1216	19	19	19
Filt2v5Ref	12397	12397	12397	2496.954	2496.954	2496.954
Assistance	4025	5914	8471	15.72266	23.10156	33.08984
FilteredMer	-596	-460	-356	-4.65625	-3.59375	-2.78125
QAxisCurre	-2313	-2898	-3656	-18.0703	-22.6406	-28.5625
DriveStage	5301	5304	5307	53.01	53.04	53.07
TorqueLimi	25000	25000	25000	100	100	100
IgnitionOn	1	1	1	1	1	1
ASP	2088	2088	2088	2088	2088	2088
EcuM__roc	3	3	3	3	3	3
sSystemMc	2	2	2	2	2	2
Padding	3804		0			
AltHallTran	407845	407845	407845	407845	407845	407845
B92Filterec	629	615	601	629	615	601
HallSensor	5	5	5	5	5	5
DiagComm	21845	21845	21845	120.0275	120.0275	120.0275
EncoderPo	65341	65341	65341	65341	65341	65341
MotorElect	40950	40950	40950	225	225	225
AltNewHall	0	0	0	0	0	0
AltMotorEl	0	0	0	0	0	0
B92MotorV	960	960	960	960	960	960
AltRotorDir	-1	-1	-1	-1	-1	-1
AltMotorCc	5	5	5	5	5	5

DistanceTr	15037195	15037195
LifetimeCo	1106531	1106531
Accumulate	26291	26291
FastTherm	18	0.18
ThermalEs	90	0.9
VehicleTun	4	4
MotorTune	1	1
EmulationM	0	0
PDCStatus	1	1
PowerOffD	6035	60.35
CPU_Peak	12829	12829
TorqueReli	1	1
Incomplete	1	1
padding	0	
LRE_Positi	0	0
PositionExt	0	0
EncoderOf	0	0
MotorReve	0	0

MotorMech	87	67	113	0.679688	0.523438	0.882813
ColumnTor	-2775	-2949	-2671	-2.70996	-2.87988	-2.6084
ColumnVel	-3	-3	-4	-0.00293	-0.00293	-0.00391
vBatt	3278	3278	3286	12.80469	12.80469	12.83594
FilteredVel	1395	1395	1394	21.79688	21.79688	21.78125
Filt2v5Ref	12416	12417	12416	2500.781	2500.983	2500.781
Assistance	-4770	-5594	-4218	-18.6328	-21.8516	-16.4766
FilteredMe	87	67	113	0.679688	0.523438	0.882813
QAxisCurre	2214	2601	2021	17.29688	20.32031	15.78906
DriveStage	4405	4405	4416	44.05	44.05	44.16
TorqueLimi	25000	25000	25000	100	100	100
IgnitionOn	1	1	1	1	1	1
ASP	-4601	-4601	-4601	-4601	-4601	-4601
EcuM__roc	3	3	3	3	3	3
sSystemMc	2	2	2	2	2	2
Padding	3402		0			
AltHallTran	1253904	1253904	1253904	1253904	1253904	1253904
B92Filterec	108	104	112	108	104	112
HallSensor	5	5	5	5	5	5
DiagComm	21845	21845	21845	120.0275	120.0275	120.0275
EncoderPo	720	720	719	720	720	719
MotorElect	9539	9539	8174	52.41209	52.41209	44.91209
AltNewHall	0	0	0	0	0	0
AltMotorEl	0	0	0	0	0	0
B92MotorV	960	960	960	960	960	960
AltRotorDir	1	1	1	1	1	1
AltMotorCc	5	5	5	5	5	5
DistanceTr	7728168	7728168				
LifetimeCo	1076230	1076230				
Accumulate	34947	34947				
FastTherm	3	0.03				
ThermalEs	52	0.52				
VehicleTun	3	3				
MotorTune	1	1				
EmulationM	0	0				
PDCStatus	1	1				
PowerOffD	6254	62.54				
CPU_Peak	12946	12946				
TorqueReli	1	1				
Incomplete	1	1				
padding	0					
LRE_Positi	0	0				
PositionExt	0	0				
EncoderOf	0	0				
MotorReve	0	0				

MotorMech	-6	-5	-8	-0.04688	-0.03906	-0.0625
ColumnTor	-484	-481	-477	-0.47266	-0.46973	-0.46582
ColumnVel	0	0	0	0	0	0
vBatt	3285	3283	3278	12.83203	12.82422	12.80469
FilteredVel	1314	1315	1314	20.53125	20.54688	20.53125
Filt2v5Ref	12370	12370	12370	2491.516	2491.516	2491.516
Assistance	-85	23	-85	-0.33203	0.089844	-0.33203
FilteredMe	-6	-5	-8	-0.04688	-0.03906	-0.0625
QAxisCurre	5	-19	9	0.039063	-0.14844	0.070313
DriveStage	5935	5938	5941	59.35	59.38	59.41
TorqueLimi	25000	25000	25000	100	100	100
IgnitionOn	1	1	1	1	1	1
ASP	-901	-914	-901	-901	-914	-901
EcuM__roc	3	3	3	3	3	3
sSystemMc	2	2	2	2	2	2
Padding	3798		0			
AltHallTran	3731849	3731849	3731849	3731849	3731849	3731849
B92Filterec	0	0	0	0	0	0
HallSensor	3	3	3	3	3	3
DiagComm	0	0	0	0	0	0
EncoderPo	262	261	262	262	261	262
MotorElect	14999	13634	14999	82.41209	74.91209	82.41209
AltNewHall	0	0	0	0	0	0
AltMotorEl	0	0	0	0	0	0
B92MotorV	960	960	960	960	960	960
AltRotorDir	-1	-1	-1	-1	-1	-1
AltMotorCc	3	3	3	3	3	3

DistanceTr	15695908	15695908
LifetimeCo	1769250	1769250
Accumulate	42788	42788
FastTherm	4	0.04
ThermalEs	51	0.51
VehicleTun	4	4
MotorTune	1	1
EmulationM	0	0
PDCStatus	1	1
PowerOffD	5842	58.42
CPU_Peak	12901	12901
TorqueReli	1	1
Incomplete	1	1
padding	0	
LRE_Positi	0	0
PositionExt	0	0
EncoderOf	0	0
MotorReve	0	0



MotorMech	-836	-1402	-1083	-6.53125	-10.9531	-8.46094
ColumnTor	4165	2651	3072	4.067383	2.588867	3
ColumnVel	8	194	42	0.007813	0.189453	0.041016
vBatt	3289	3278	3303	12.84766	12.80469	12.90234
FilteredVel	503	501	503	7.859375	7.828125	7.859375
Filt2v5RefV	12381	12381	12381	2493.732	2493.732	2493.732
Assistance	18759	6841	10557	73.27734	26.72266	41.23828
FilteredMer	-836	-1402	-1083	-6.53125	-10.9531	-8.46094
QAxisCurre	-7917	-4863	-5736	-61.8516	-37.9922	-44.8125
DriveStage	5145	5138	5132	51.45	51.38	51.32
TorqueLimi	25000	25000	25000	100	100	100
IgnitionOn	1	1	1	1	1	1
ASP	4519	4300	4519	4519	4300	4519
EcuM__roc	3	3	3	3	3	3
sSystemMc	2	2	2	2	2	2
Padding	4590		0			
AltHallTran	233904	209928	233904	233904	209928	233904
B92Filterec	1100	663	1126	1100	663	1126
HallSensor	5	4	5	5	4	5
DiagComm	21845	32768	21845	120.0275	180.044	120.0275
EncoderPo	64586	64586	64585	64586	64586	64585
MotorElect	47775	47775	46410	262.5	262.5	255
AltNewHall	0	0	0	0	0	0
AltMotorEk	0	0	0	0	0	0
B92MotorV	960	960	960	960	960	960
AltRotorDir	-1	-1	-1	-1	-1	-1
AltMotorCc	5	4	5	5	4	5
DistanceTr	7397349	7397349				
LifetimeCo	661273	661273				
Accumulate	18104	18104				
FastTherm	41	0.41				
ThermalEs	119	1.19				
VehicleTun	3	3				
MotorTune	1	1				
EmulationM	0	0				
PDCStatus	1	1				
PowerOffD	4772	47.72				
CPU_Peak	12824	12824				
TorqueReli	1	1				
Incomplete	1	1				
padding	0					
LRE_Positi	0	0				
PositionExt	0	0				
EncoderOf	0	0				
MotorReve	0	0				

MotorMechanicalVelocity	0	0	0	0	0
ColumnTorque	253	-6	166	0.24707	-0.00586
ColumnVelocity	0	0	0	0	0
vBatt	3581	3575	3571	13.98828	13.96484
FilteredVehicleSpeed	4819	4819	4818	75.29688	75.29688
Filt2v5RefVoltage	12480	12480	12480	2513.672	2513.672
AssistanceTorqueDemand	-138	-544	132	-0.53906	-2.125
FilteredMechanicalVelocity	0	0	0	0	0
QAxisCurrent	26	212	-2	0.203125	1.65625
DriveStageTemperature	4693	4693	4686	46.93	46.93
TorqueLimit	25000	25000	25000	100	100
IgnitionOn	1	1	1	1	1
ASP	31	31	31	31	31
EcuM__rootState_active	3	3	3	3	3
sSystemMode__rootState_active	2	2	2	2	2
Padding	2610		0		
AltHallTransitionTime	15461834	15461834	15461834	15461834	15461834
B92FilteredMotorVelocityError	0	0	0	0	0
HallSensor	5	5	5	5	5
DiagCommutationCentrePosition	21845	21845	21845	120.0275	120.0275
EncoderPositionRegister	40	39	39	40	39
MotorElectricalPosition	9555	8190	8190	52.5	45
AltNewHallEvent	0	0	0	0	0
AltMotorElectricalVelocity	0	0	0	0	0
B92MotorVelocityErrorLimit	960	960	960	960	960
AltRotorDirection	1	1	1	1	1
AltMotorCommutationState	5	5	5	5	5
DistanceTravelled	13920655	13920655			
LifetimeCounter	1087249	1087249			
AccumulatedColumnMovement	26318	26318			
FastThermalEstTemperatureRise	6	0.06			
ThermalEstTemperatureRise	14	0.14			
VehicleTuneSelector	4	4			
MotorTuneSelector	1	1			
EmulationModeStatus	0	0			
PDCStatus	1	1			
PowerOffDriveStageTemperature	4027	40.27			
CPU_PeakLoadHold	12942	12942			
TorqueRelInstatmentFlag	1	1			
IncompletePowerDownTestCount	1	1			
padding	0				
LRE_PositionState	0	0			
PositionExtrapActive	0	0			
EncoderOffset	0	0			
MotorReversal	0	0			

0  
0.162109  
0  
13.94922  
75.28125  
2513.672  
0.515625  
0  
-0.01563  
46.86  
100  
1  
31  
3  
2  
  
15461834  
0  
5  
120.0275  
39  
45  
0  
0  
960  
1  
5

		HALL				Diag comm state				Encoder Posn Reg	
UR0030	U502	5	1	5		120.0275	60.01648	120.0275		1548	1543
UR0045	U502	1	1	1		60.01648	60.01648	60.01648		65405	65406
UR0047	U502	4	4	4		180.044	180.044	180.044		2	2
UR0048	U502	2	2	2		300.0714	300.0714	300.0714		65339	65339

Redacted for Relevance

UR0059	U502	5	5	5		120.0275	120.0275	120.0275		2	2
UR0060	U502	5	5	5		120.0275	120.0275	120.0275		0	0
UR0061	U502	4	4	4		180.044	180.044	180.044		1731	1731
UR0062	U502	5	5	5		120.0275	120.0275	120.0275		65535	65535
UR0063	U502	6	6	6		240.0604	240.0604	240.0604		62174	62174
UR0064	U502	6	4	4		240.0604	180.044	180.044		1123	1123
UR0065	U502										
UR0066	U502	4	4	4		180.044	180.044	180.044		65519	65519
UR0067	U502	3	3	3		0	0	0		254	254
UR0068	U502	5	5	5		120.0275	120.0275	120.0275		65302	65301
UR0069	U502	2	6	6		300.0714	240.0604	240.0604		61974	61973
UR0070	U502	2	6	6		300.0714	240.0604	240.0604		65134	65130
UR0071	U502	1	1	1		60.01648	60.01648	60.01648		550	550
UR0073	U502	1	1	1		60.01648	60.01648	60.01648		64767	64768
UR0075	U502										
UR0076	U502	1	1	1		60.01648	60.01648	60.01648		65402	65403
UR0077	U502	1	1	1		60.01648	60.01648	60.01648		431	431
UR0079	U502										
UR0080	U502										

Redacted for Relevance

UR0081	U502	2	2	2		300.0714	300.0714	300.0714		2	2
UR0082	U502	6	6	6		240.0604	240.0604	240.0604		65426	65426
UP0083	U502	3	3	3		0	0	0		1446	1447
UR0084	U502	1	1	1		60.01648	60.01648	60.01648		114	115
UR0085	U502	2	6	2		300.0714	240.0604	300.0714		2532	2532
UR0087	U502	3	3	3		0	0	0		68	68
UR0088	U502	5	5	5		120.0275	120.0275	120.0275		65341	65341
UR0089	U502	5	5	5		120.0275	120.0275	120.0275		720	720
UR0092	U502	3	3	3		0	0	0		262	261
UR0095	U502	5	4	5		120.0275	180.044	120.0275		64586	64586

UR0096	U502	5	5	5		120.0275	120.0275	120.0275		40	39
--------	------	---	---	---	--	----------	----------	----------	--	----	----

		Motor Elec Position		
1554		164.3516	122.2747	202.1703
65406		345	352.5	352.5
2		270	270	270
65339		3.664835	3.664835	360
2006		74.91209	74.91209	82.41209
0		22.5	22.5	22.5
63316		187.4121	187.4121	187.4121
0		262.5	262.5	270
		52.41209		
		292.5		
		262.5		
		232.5		
		56.16484		
		322.5		
		322.5		
2		202.5	202.5	202.5
0		202.5	202.5	202.5
1731		119.9121	119.9121	119.9121
65535		15	15	15
62174		322.5	322.5	322.5
1124		104.9121	104.9121	112.4121
65519		240	240	240
254		112.4121	112.4121	112.4121
65301		52.41209	44.91209	44.91209
61974		172.4121	164.9121	164.9121
65132		218.7418	182.6319	202.1429
550		322.5	322.5	322.5
64767		315	322.5	315
65401		352.5	357.6264	345
431		360	360	360
688		330	330	337.5
65534		150	150	150
2830		202.4121	194.9121	202.4121
62690		89.91209	97.41209	97.41209
931		322.5	322.5	315
2		22.5	22.5	22.5
65426		322.5	322.5	322.5
1446		112.4121	119.9121	112.4121
113		322.5	330	315
2531		172.4121	172.4121	164.9121
68		112.5	112.5	112.5
65341		225	225	225
719		52.41209	52.41209	44.91209
262		82.41209	74.91209	82.41209
64585		262.5	262.5	255

39		52.5	45	45
----	--	------	----	----

MotorMechanicalVelocity	0	0	0	0	0
ColumnTorque	3133	3433	3727	3.05957	3.352539
ColumnVelocity	0	0	0	0	0
vBatt	3029	3021	3017	11.83203	11.80078
FilteredVehicleSpeed	0	0	0	0	0
Filt2v5RefVoltage	12469	12469	12469	2511.456	2511.456
AssistanceTorqueDemand	9963	11624	13570	38.91797	45.40625
FilteredMechanicalVelocity	0	0	0	0	0
QAxisCurrent	6234	7176	8309	48.70313	56.0625
DriveStageTemperature	1996	1996	1996	19.96	19.96
TorqueLimit	25000	25000	25000	100	100
IgnitionOn	1	1	1	1	1
ASP	-20446	-20446	-20450	-20446	-20446
EcuM__rootState_active	3	3	3	3	3
sSystemMode__rootState_active	2	2	2	2	2
Padding	1		12469		
AltHallTransitionTime	2613265	2613265	2613265	2613265	2613265
B92FilteredMotorVelocityError	0	0	0	0	0
HallSensor	6	6	6	6	6
DiagCommutationCentrePosition	10923	10923	10923	60.01648	60.01648
EncoderPositionRegister	2	1	1	2	1
MotorElectricalPosition	58695	57330	57330	322.5	315
AltNewHallEvent	1	0	0	1	0
AltMotorElectricalVelocity	0	0	0	0	0
B92MotorVelocityErrorLimit	960	960	960	960	960
AltRotorDirection	1	1	1	1	1
AltMotorCommutationState	6	6	6	6	6
DistanceTravelled	12187035	12187035			
LifetimeCounter	767173	767173			
AccumulatedColumnMovement	15994	15994			
FastThermalEstTemperatureRise	50	0.5			
ThermalEstTemperatureRise	503	5.03			
VehicleTuneSelector	18	18			
MotorTuneSelector	1	1			
EmulationModeStatus	0	0			
PDCStatus	1	1			
PowerOffDriveStageTemperature	5355	53.55			
CPU_PeakLoadHold	14671	14671			
TorqueRelInstatmentFlag	1	1			
IncompletePowerDownTestCount	1	1			
SchedulerUnderrunFaultCount	0	Not scaled			
LRE_PositionState	0	0			
PositionExtrapActive	0	0			
EncoderOffset	0	0			
MotorReversal	0	0			



0  
3.639648  
0  
11.78516  
0  
2511.456  
53.00781  
0  
64.91406  
19.96  
100  
1  
-20450  
3  
2  
  
2613265  
0  
6  
60.01648  
1  
315  
0  
0  
960  
1  
6

MotorMech	0	0	0	0	0	0
ColumnTor	-1448	-1482	-1482	-1.41406	-1.44727	-1.44727
ColumnVel	-3	-3	-3	-0.00293	-0.00293	-0.00293
vBatt	3185	3182	3180	12.44141	12.42969	12.42188
FilteredVel	1835	1832	1835	28.67188	28.625	28.67188
Filt2v5Ref	12408	12408	12408	2499.17	2499.17	2499.17
Assistance	-190	-377	-173	-0.74219	-1.47266	-0.67578
FilteredMe	0	0	0	0	0	0
QAxisCurre	-114	-197	-114	-0.89063	-1.53906	-0.89063
DriveStage	5287	5287	5284	52.87	52.87	52.84
TorqueLimi	25000	25000	25000	100	100	100
IgnitionOn	1	1	1	1	1	1
ASP	-50	-50	-50	-50	-50	-50
EcuM__roc	3	3	3	3	3	3
sSystemMc	2	2	2	2	2	2
Padding	1		12407			
AltHallTran	15833944	15833944	39895842	15833944	15833944	39895842
B92Filterec	0	0	0	0	0	0
HallSensor	4	4	4	4	4	4
DiagComm	0	0	0	0	0	0
EncoderPo	61852	61852	61852	61852	61852	61852
MotorElect	20459	20459	20459	112.4121	112.4121	112.4121
AltNewHall	0	0	0	0	0	0
AltMotorEl	0	0	0	0	0	0
B92MotorV	960	960	960	960	960	960
AltRotorDir	-1	-1	-1	-1	-1	-1
AltMotorCc	4	4	6	4	4	6
DistanceTr	11629231	11629231				
LifetimeCo	838719	838719				
Accumulate	18840	18840				
FastTherm	54	0.54				
ThermalEs	378	3.78				
VehicleTun	18	18				
MotorTune	1	1				
EmulationM	0	0				
PDCStatus	1	1				
PowerOffD	6035	60.35				
CPU_Peak	14750	14750				
TorqueReli	1	1				
Incomplete	1	1				
SchedulerL	0	Not scaled				
LRE_Positi	0	0				
PositionExl	0	0				
EncoderOf	0	0				
MotorReve	0	0				

MotorMech	0	0	0	0	0	0
ColumnTor	-1602	-1692	-1777	-1.56445	-1.65234	-1.73535
ColumnVel	0	0	0	0	0	0
vBatt	3514	3502	3494	13.72656	13.67969	13.64844
FilteredVel	0	0	0	0	0	0
Filt2v5Ref	12376	12376	12376	2492.725	2492.725	2492.725
Assistance	-2471	-2677	-2925	-9.65234	-10.457	-11.4258
FilteredMe	0	0	0	0	0	0
QAxisCurre	1120	1229	1318	8.75	9.601563	10.29688
DriveStage	4340	4337	4335	43.4	43.37	43.35
TorqueLimi	25000	25000	25000	100	100	100
IgnitionOn	1	1	1	1	1	1
ASP	0	0	0	0	0	0
EcuM__roc	3	3	3	3	3	3
sSystemMc	2	2	2	2	2	2
Padding	4295		0			
AltHallTran	3299999	3299999	3299999	3299999	3299999	3299999
B92Filterec	0	0	0	0	0	0
HallSensor	1	1	1	1	1	1
DiagComm	10923	10923	10923	60.01648	60.01648	60.01648
EncoderPo	2	2	1	2	2	1
MotorElect	58695	58695	57330	322.5	322.5	315
AltNewHall	0	0	0	0	0	0
AltMotorEl	0	0	0	0	0	0
B92MotorV	960	960	960	960	960	960
AltRotorDir	1	1	1	1	1	1
AltMotorCc	1	1	1	1	1	1
DistanceTr	7400557	7400557				
LifetimeCo	505705	505705				
Accumulate	12403	12403				
FastTherm	31	0.31				
ThermalEs	66	0.66				
VehicleTun	3	3				
MotorTune	1	1				
EmulationM	0	0				
PDCStatus	1	1				
PowerOffD	6552	65.52				
CPU_Peak	13594	13594				
TorqueReli	1	1				
Incomplete	1	1				
padding	0					
LRE_Positi	0	0				
PositionExl	0	0				
EncoderOf	0	0				
MotorReve	0	0				

Reference Number	Platform	Failure Location	RUA	Root Cause	Status	MotorMechanicalVelocity	ColumnTorque	ColumnVelocity	MotorMechanicalVelocity / ColumnVelocity	vBatt	FilteredVehicleSpeed	Flt2VSRVVoltage	AssistanceTorqueDemand	FilteredMechanicalVelocity	QAxisCurrent	DriveStageTemperature	TorqueLimit	IgnitionOn	ASP	ECU_rFootStateActive	sSystemMode_rFootStateActive	AltHallTramsRtnTime	B92FilteredMotorVelocityError	HallSensor	DiagCommutationCentrePosition	EncoderPositionRegister	MotorElectricalPosition	Error	AltNewHallEvent	AltMotorElectricalVelocity	B92MotorVelocityErrorLimit	AltRotorDirection	AltMotorCommutationState	Hall A	Hall B
UR0030	U502	Warranty	4878	Under Analysis	Open	-5.23438	-2.2334	0.22188	#VALUE!	13.06	30.59375	2498.163	-11.2852	-5.23438	9.960938	41.05	100	1	-6184	3	2	437971	270	5	120.0275	1554	202.1703	82.14286	1	-1609	1395	-1	5	1	0
UR0045	U502	Warranty	4998	Under Analysis	Open	0.570313	-1.53125	-0.00293	-23.6123	12.91	0	2496.954	-10.8242	0.570313	10.28125	13.37	100	1	213	3	2	1373942	76	1	60.01648	65406	352.5	292.4835	0	0	960	-1	1	1	0
UR0047	U502	Warranty		Under Analysis	Open	0	2.219727	0	-194.667	14.01	0	2520.52	18.13672	0	-16.4922	46.6	100	1	0	3	2	3959996	0	4	180.044	2	270	89.95604	0	0	960	-1	4	0	0
UR0048	U502	Warranty	5074	Under Analysis	Open	0.140625	-0.09375	-0.00979	#DIV/0!	12.93	28.375	2504.407	0.128902	0.140625	0.054688	48.09	100	1	-86	3	2	57371899	0	2	300.0714	65339	360	59.92857	0	18	964	-1	2	0	1

Redacted for Relevance

UR0059	U502	Warranty		Under Analysis	Open	0	0.795898	0	#DIV/0!	13.78906	0	2502.191	3.199219	0	-2.89063	37.43	100	1	0	3	2	26573893	0	5	120.0275	2	202.5	82.47253	0	0	960	-1	5	1	0	
UR0060	U502	Warranty		Under Analysis	Open	0	0.93457	0	#DIV/0!	14.0625	0	2501.385	3.308594	0	-2.91406	28.27	100	1	0	3	2	21408100	0	5	120.0275	0	202.5	82.47253	0	0	960	-1	5	1	0	
UR0061	U502	Warranty		Under Analysis	Open	0	-0.68555	0	#DIV/0!	13.76563	0	2500.983	-2.51953	0	2.351563	57.07	100	1	163	3	2	1.32E+08	0	4	180.044	1731	119.9121	-60.1319	1	0	960	1	4	0	0	
UR0062	U502	Warranty		Under Analysis	Open	0	-0.75283	0	#DIV/0!	13.62881	0	2487.085	-5.23047	0	5.054688	50.16	100	1	0	3	2	2567874	0	5	120.0275	65535	15	-105.027	0	0	960	-1	5	1	0	
UR0063	U502	Warranty		Under Analysis	Open	0	0.589844	-0.00293	#DIV/0!	12.87109	10.83125	2507.025	0.328125	0	-0.42188	58.98	100	1	-22	3	2	2783903	0	6	240.0604	62174	322.5	82.43956	0	0	960	-1	6	0	1	
UR0064	U502	Warranty		Under Analysis	Open	11.05469	2.421875	-0.16016	0	13.86016	27.10938	2492.725	7.478563	11.05469	2.632813	70.29	100	1	3759	3	2	258024	604	4	180.044	1124	112.4121	-67.6319	0	0	960	1	4	0	0	
UR0065	U502	Warranty		Under Analysis	Open																						0									
UR0066	U502	Warranty		Under Analysis	Open	-0.01563	1.276367	0	#DIV/0!	13.61328	0	2492.12	7.503906	-0.01563	-6.85938	51.82	100	1	0	3	2	26363944	0	4	180.044	65519	240	59.95604	0	-3	961	-1	4	0	0	
UR0067	U502	Warranty		Under Analysis	Open	0	1.589338	-0.00293	#DIV/0!	14.02344	3.1875	2494.537	8.910156	0	-7.82813	33.71	100	1	-418	3	2	34602106	0	3	0	254	112.4121	112.4121	0	0	960	-1	3	1	1	
UR0068	U502	Warranty		Under Analysis	Open	0	0.589339	-0.00293	0	12.75781	91.5625	2492.926	1.058594	0	-0.36719	66.52	100	1	18	3	2	16055997	0	5	120.0275	65301	44.91209	-75.1154	0	0	960	1	5	1	0	
UR0069	U502	Warranty		Under Analysis	Open	4.867188	1.321289	-0.03906	0	12.875	9.8125	2507.428	4.828125	4.867188	1.40625	59.18	100	1	19333	3	2	402040	0	6	240.0604	61974	164.9121	-75.1484	0	0	960	1	6	0	1	
UR0070	U502	Warranty		Under Analysis	Open	3.625	2.24707	-0.18555	-124.6	14.14844	26.95313	2511.456	7.6875	3.625	-7.01563	32.12	100	1	3026	3	2	804000	85	6	240.0604	65132	202.1429	-37.9178	0	777	1169	1	6	0	1	
UR0071	U502	Warranty		Under Analysis	Open	-2.24414	-0.00293	-19.5388	14.10547	81.5625	2494.336	-4.44531	0	4.203125	42.6	100	1	-354	3	2	34398008	0	1	60.01648	590	322.5	262.4835	0	0	960	1	1	1	0		
UR0073	U502	Warranty		Under Analysis	Open	0.421875	-2.92676	-0.00293	0	13.59375	27.64063	2481.848	-14.9063	0.421875	15.1875	63.94	100	1	-136	3	2	791913	448	1	60.01648	64767	315	254.9835	0	0	960	1	1	1	0	
UR0075	U502	Warranty		Under Analysis	Open																															
UR0076	U502	Warranty		Under Analysis	Open	1.273438	-1.3877	-0.00391	#DIV/0!	12.90234	4.875	2501.587	-4.91016	1.273438	5.28125	41.05	100	1	555	3	2	1175927	94	1	60.01648	65401	345	284.9835	0	0	960	1	1	1	0	
UR0077	U502	Warranty		Under Analysis	Open	0	0.426758	-0.00293	-326	12.98047	53.39063	2487.889	1.164063	0	-0.99219	49.53	100	1	-68	3	2	1344013	0	1	60.01648	431	360	299.9835	0	0	960	1	1	1	0	
UR0079	U502	Warranty		Under Analysis	Open																															
UR0080	U502	Warranty		Under Analysis	Open																															

Redacted for Relevance



Motor Build Date	Where Failed	Application Code	Main Calibration Data Number	Tune	Location	Mileage				
17-Sep-10	Warranty	BB53-14D003-BE	BB53-14D004-BG	4	Shirley	7812				
27-Dec-10	Warranty	BB53-14D003-AE	BB53-14D004-AG	3	Shirley	1482				
28-Dec-10	Warranty	BB53-14D003-BE	BB53-14D004-BG	4	26 Mile	3274				
4-Dec-10	Warranty	BB53-14D003-AE	BB53-14D004-AG	3	EDG	2820				
14-Oct-10	Warranty	AESC-14D003-BC	AESC-14D004-BB		Shirley	7486				
10-Sep-10	Warranty	AESC-14D003-BB	AESC-14D004-BB		QAO	13				
9-Feb-11	Warranty	AESC-14D003-BC	AESC-14D004-BB		--> Nidec	14				
22-Dec-10	Warranty	AESC-14D003-BC	AESC-14D004-BB		QAO	2909				
15-Oct-10	Warranty	AESC-14D003-BC	AESC-14D004-BB		QAO	5221				
14-Oct-10	Warranty	AESC-14D003-BC	Comm Error		Shirley	7743				
			AESC-14D004-BB			7743				
20-Feb-11	Warranty	BV6T-14C217-AE	BV6T-14C218-AE	18		1020				
28-Dec-10	Warranty	BB53-14D003-AE	BB53-14D004-AG	3	EDG					
24-Sep-10	Warranty	AESC-14D003-BC	AESC-14D004-BB							
16-Oct-10	Warranty	AESC-14D003-BC	AESC-14D004-BB							
4-Jan-11	Warranty	AESC-14D003-BC	AESC-14D004-BB							
28-Dec-10	Warranty	BB53-14D003-AE								
25-Jan-11	Warranty	BB53-14D003-AE								
27-Dec-10	Warranty	BB53-14D003-AE								
28-Dec-10	Warranty	BB53-14D003-AE								
8-Dec-10	Warranty	BB53-14D003-BE								
24-Dec-10	Warranty	BB53-14D003-AE								
24-Dec-10	Warranty	BB53-14D003-AE								
27-Oct-10	Warranty	BB53-14D003-AE								
23-Dec-10	Warranty	BB53-14D003-AE								
23-Dec-10	Warranty	BB53-14D003-AE								
7-Oct-10	Warranty	BB53-14D003-AE								
28-Dec-10	Warranty	BB53-14D003-AE								
20-Jan-11	Warranty	BB53-14D003-AE								
24-Jan-11	Warranty	BB53-14D003-AE								
27-Dec-10	Warranty	BB53-14D003-AE								
24-Dec-10	Warranty	BB53-14D003-AE								
20-Dec-10	Warranty	AESC-14D003-BC								
23-Nov-10	Warranty	AESC-14D003-BC								
14-Oct-10	Warranty	AESC-14D003-BC								
19-Aug-10	Warranty	AESC-14D003-BA								
17-Oct-10	Warranty	AESC-14D003-BC								

10/14/2011

	Fallout%	Fallout	Total Checked	Good	Date	MAP Start Date
2011MY U502	0.055%	48	87369	87321	8/25/2011	8/30/2011
Redacted for Relevance						


1/6/2012

	Fallout%	Fallout	Total Checked	Good	Date	MAP Start Date
2011MY U502	0.061%	56	92037	91981	8/25/2011	8/30/2011
Redacted for Relevance						

2/20/2012


	Fallout%	Fallout	Total Checked	Good	Date	MAP Start Date
2011MY U502	0.068%	63	92037	91974	8/25/2011	8/30/2011
Redacted for Relevance						

# B9A %Fall-out






# B9A %Fall-out



# B9A %Fall-out



---

**From:** Napoli, Laura (L.)  
**Sent:** Thursday, December 22, 2011 10:25 AM  
**To:** Perri, Ron (R.J.)  
**Cc:** Surella, Matthew (M.M.)  
**Subject:** B9A Fallout at Tyco, Nidec, Anting/Shalke/Nove Mesto

Ron,

I have the most recent numbers for fallout at Tyco, Nidec, and Anting/Shalke/Nove Mesto for the visual inspections they're doing for misalignment and concoat.

Tyco:  
Since Nov 12, Tyco is finding 0 misalignment on ribbon cables at EOL with 5x magnification.

Nidec:  
For batches of ribbon cables that were built before PCAs were put in place at Tyco, Nidec found 22 out of 14,800 with misalignment.  
Since Nov 12, Nidec has 0 fallout at IQ for ribbon cable misalignment when inspected with 5x magnification.  
Nidec inspected 69,122 motor assys that were already built before the ribbon cable visual inspections went into place on Nov 12. They found 638 suspect parts. They x-rayed 42 of them and found 9 to be misaligned. They are going through the rest and visually re-checking them with 30x magnification to find which parts are truly misaligned.  
Since Nov 11, Nidec has been inspecting motor assys at EOL for conformal coat running from the relay. This is the same day they fixed the conveyor. They have 0 fall out for concoat since this date.  
For conformal coat inspections on finished stock, they have quarantined 11k parts. These are parts with any amount of conformal coat at the connector from the relay.

Anting:  
From 11/11-11/21, Anting found 15 out of 25,783 assys with protruding wires (misalignment) and rejected these parts. Anting initially reported that they had 30% fallout for conformal coat at the connector. Since 11/24, they have 0 fallout.

Shalke and Nove Mesto:  
Shalke and Nove Mesto have been inspecting for misalignment since Nov 15 with 0 fallout.

Next Steps:  
TRW is going through each and every return to determine root cause of B9A and B3A/B43.  
There is a study going on between TRW and Nidec with help from Tyco to confirm that conformal coat is the root cause of the high resistance measured on parts that do not have misaligned cables. This is to confirm that there is no other root cause of failure.

Regards,

*Laura Napoli*

D3 and U502 EPAS  
Ford Motor Company  
Cube: 2B-G66 PDC  
Phone: 313.323.0634  
Mobile: 313.805.0482

---

**From:** Napoli, Laura (L.)  
**Sent:** Thursday, December 01, 2011 1:43 PM  
**To:** Perri, Ron (R.J.)  
**Cc:** Surella, Matthew (M.M.)  
**Subject:** B9A Fallout

Ron,

Matt said you wanted to know the part fallout at Tyco, Nidec, and Anting for the con coat and misaligned cable. The info I have right now is the following. I'll have confirmation in tomorrow's 9am meeting.

200/14000 parts were found at Nidec with protruding wires caused by the misalignment. These parts were out of a batch of cables built in Aug 2010 which is before the final PCA was put on the Tyco tooling (9/2/2010).

Nidec has reported that NO concoat parts have been found since the conveyor was fixed.

I need fallout data from Anting and Tyco. I'm not sure if the 1% misalignment and 30% concoat is still accurate at Anting. I'm expecting the 30% concoat fallout to be much lower by now.

Regards,

*Laura Napoli*

D3 and U502 EPAS  
Ford Motor Company  
Cube: 2B-G66 PDC  
Phone: 313.323.0634  
Mobile: 313.805.0482

Reference Number	RUA	Root Cause	Status	MotorMechanicalVelocity	ColumnTorque	ColumnVelocity	MotorMechanicalVelocity / ColumnVelocity	vBatt	FilteredVehicleSpeed	Filt2v5rVfVltgs	AssistanceTorqueDemand	FilteredMechanicalVelocity	QAxisCurrent	DriveStageTemperature	TorqueLimit	IgnitionOn	ASP	EcuM_rootState_active	sSystemMod_rootState_active	HallTransitIonTime	B92FilteredMotorVelocityError	HallSensor	DiagCommutatorPosition	EncoderPositionRegister	MotorElectricPosition	Error
FR0004	2550	Cable Insertion	Open																							
FR0030	2983	Under Analysis	Open	0	1.178710938	-0.002929688	0	13.77734375	61.0625	2511.657715	-0.19921875	0	0.234375	45.79	100	1	1.5625	3	2	14694005	0	6	240.0604396	65440	322.5	82.43956044
FR0033	2983	Under Analysis	Open	-0.0390625	1.958007813	0	#DIV/0!	13.67578125	0	2501.184082	4.59375	-0.0390625	-5.1796875	59.53	100	1	-16.34375	3	2	1866095	0	6	240.0604396	65461	315	74.93956044
FR0054	2983	Under Analysis	Open	2.3515625	-4.002929688	-0.002929688	-802.6686967	13.828125	17.78125	2501.385498	-35.09375	2.3515625	36.9765625	53.87	100	1	-104.921875	3	2	431844	248	2	300.0714286	1191	207.3736264	-92.69780222
FR0065	2983	Under Analysis	Open	14.09375	-4.047851563	-0.37109375	-37.9794731	13.0703125	0	2490.106201	-83.45703125	14.09375	81.890625	41.32	100	1	-272.265625	3	2	179944	413	4	180.043956	3080	82.41208791	-97.63168813
FR0072	3810	Under Analysis	Open	0.328125	-0.719726563	-0.022460938	-14.60889565	14.0625	55.890625	2493.328857	0.80078125	0.328125	-0.5078125	46.68	100	1	-0.6875	3	2	35753979	0	6	240.0604396	139	297.8516484	57.79120879
FR0073	3588	Encoder IC	Contained	0	1.299804688	0	#DIV/0!	14.57421875	21.875	2493.933105	0.3046875	0	-0.2890625	35.87	100	1	0.90625	3	2	43746102	0	3	0	146	112.5	112.5
FR0096	3811	Reg Power Up	Open	0	1.678710938	0	#DIV/0!	12.69921875	0	2479.632568	6.046875	0	-6.6171875	25.78	5.6	1	0	3	2	2441876	0	2	300.0714286	2	22.5	-277.5714286
FR0097	3162	Under Analysis	Open	0	-0.599679688	-0.002929688	0	14.015625	109.578125	2495.343013	-0.66015625	0	0.8953125	23.92	100	1	-2.0625	3	2	416106104	0	6	240.0604396	17	315	74.93956044
FR0108	3551	Reg Power Up	Open	0	1.9140625	0	#DIV/0!	14.65234375	0	2495.544434	3.3828125	0	-3.484375	6.83	100	1	0	3	2	157770003	0	6	240.0604396	0	330	89.93956044
FR0110	3688	Reg Power Up	Open	0	-0.500976563	0	#DIV/0!	14.109375	0	2485.876465	-1.05859375	0	1.046875	30.02	100	1	0	3	2	7157869	0	1	60.01648352	0	330	289.9835165
FR0126	3408	Flux Density - Halls	Contained																							
FR0129	3500	Reg Power Up	Open																							
FR0134	3744	Reg Power Up	Open	0	-0.672851563	0	#DIV/0!	12.90234375	0	2503.80249	-1.9375	0	2.125	3.7	100	1	0	3	2	3210001	0	3	0	0	270	270
FR0141	3445	Motor PCB connector solder	Closed	0	1.560546875	0	#DIV/0!	13.890625	0	2492.724698	3.88671875	0	-4.1171875	21.36	100	1	0	3	2	2526023	0	2	300.0714286	65534	22.5	82.5
FR0146	3446	Motor PCB clearance	Closed	0	1.916992188	0	#DIV/0!	14.69015625	0.609375	2497.78001	3.75	0	-3.98875	-11.88	100	1	0	3	2	28579658	0	1	60.01648352	0	150	89.98351648
AR657700	3680	Reg Power Up	Open	0	3.836914063	0	#DIV/0!	14.28515625	0	2495.947266	23.515625	0	-27.226625	26.12	100	1	0	3	2	599956	0	5	120.0274725	0	202.5	82.47252747
FR0158	3746	Reg Power Up	Open	0	1.397460938	0	#DIV/0!	14.6328125	0	2493.328857	3.74609375	0	-4.0234375	-5.88	100	1	0	3	2	6906003	0	2	300.0714286	0	22.5	-277.5714286
QAO 1	3813	Under Analysis	Open																							
QAO 2	3812	Flux Density - Halls	Contained																							
QAO 3	3812	Flux Density - Halls	Contained																							
FR0174	3745	Reg Power Up	Open	0	2.13671875	0	#DIV/0!	13.2578125	0	2507.427978	5.48828125	0	-6.375	0.56	100	1	0	3	2	1056065	0	6	240.0604396	0	330	89.93956044
FR0177	3753	Reg Power Up	Open	0	-1.911132813	0	#DIV/0!	13.1171875	0	2506.82373	-3.890625	0	4.015625	9.31	91.6	1	0	3	2	16139957	0	4	180.043956	0	90	-90.04395604
AR354559	3681	Reg Power Up	Open	0	-1.211914063	0	#DIV/0!	14.4921875	1.828125	2508.435059	-2.0390625	0	2.4375	26.77	100	1	0	3	2	3887975	0	2	300.0714286	0	202.5	-97.57142857
AR691730	3682	Motor PCB clearance	Closed	0	1.997070313	0	#DIV/0!	14.62109375	0	2503.399658	5.828125	0	-7.25	50.26	100	1	0	3	2	1710005	0	2	300.0714286	0	22.5	-277.5714286
FR0192	3751	Reg Power Up	Open	0	-1.005859375	0	#DIV/0!	14.73046875	0	2502.191162	-3.73028125	0	4.0234375	4.81	100	1	0	3	2	107238913	0	2	300.0714286	0	202.5	-97.57142857
DR0024	3663	Cable Insertion	Open	0	0.435546875	-0.002929688	0	14.01953125	74.9375	2484.063721	-0.84765625	0	1.0390625	41.64	100	1	6.390625	3	2	17765938	0	2	300.0714286	2779	240	-60.07142857
FR0204	3747	Reg Power Up	Open	0	-1.697265625	0	#DIV/0!	13.359375	0	2499.975586	-3.3515625	0	3.78125	12.22	100	1	0	3	2	27863959	0	3	0	0	270	270
AR390291	3752	Reg Power Up	Open	0	-1.721679688	0	#DIV/0!	14.48046875	0.59375	2501.184082	-3.80078125	0	4.109375	31.72	100	1	0	3	2	2915888	0	3	0	0	270	270
AR378362	3752	Reg Power Up	Open	-2.53125	2.40625	0	#DIV/0!	14.546875	2.421875	2504.205322	12.0625	-2.53125	-12.9453125	38.39	100	1	-41.453125	3	2	120002	16178	2	300.0714286	499	303.5879121	3.516483516
DR0004	3545	Reg Power Up	Open	EFF suggests Torque Sensor Power Failure (all Widths and Periods = 0) and fault occurs at Power Up																						
FR0228	3812	Under Analysis	Open	-0.0390625	0.954101563	0	#DIV/0!	14.3515625	122.453125	2499.77417	-0.44921875	-0.0390625	0.421875	45.34	100	1	-0.453125	3	2	3179943	0	6	240.0604396	64395	179.9120879	-60.14835165
FR0234	3781	Reg Power Up	Open	19.46875	-3.283203125	-0.1796875	-108.3478261	14.51171875	10.828125	2496.75293	-26.0640625	19.46875	0.1828125	21.24	100	1	0	3	2	150006	5386	5	120.0274725	1620	63.75274725	-56.27472527
FR0197	3781	Reg Power Up	Open	EFF suggests Torque Sensor Power Failure (all Widths and Periods = 0) and fault occurs at Power Up																						
FR0243	3781	Reg Power Up	Open	0	4.20703125	0	#DIV/0!	13.3671875	0.0625	2496.954346	54.48046875	0	-58	36.33	100	1	0	3	2	17447895	0	1	60.01648352	65475	120	59.98351648
FR0244	3781	Reg Power Up	Open	0	1.072265625	0	#DIV/0!	14.25	0	2491.113261	1.2578125	0	-1.375	14.79	100	1	0	3	2	16319923	0	1	60.01648352	2	150	89.98351648
FR0249	3781	Reg Power Up	Open	4.40625	-2.83984375	-0.017578125	#DIV/0!	14.37890625	1.546875	2498.565674	-22.5703125	4.40625	27.7680625	12.29	100	1	0	3	2	395951	395	2	300.0714286	63972	202.4120879	-97.63956066
FR0109	3781	Reg Power Up	Open	EFF suggests Torque Sensor Power Failure (all Widths and Periods = 0) and fault occurs at Power Up																						
FR0265	3781	Reg Power Up	Open	-1.25	2.198242188	0	#VALUE!	14.13671875	11.125	2496.954346	7.5234375	-1.25	-8.953125	36.69	100	1	-138.953125	3	2	546107	985	6	240.0604396	1546	322.5	82.43956044
FR0266	3781	Reg Power Up	Open	0	-0.046875	0	#DIV/0!	14.09765625	0	2496.75293	0	0	0.2109375	20.75	100	1	0	3	2	1913483962	0	3	0	0	270	270
FR0268	3781	Reg Power Up	Open	0	1.198242188	0	#DIV/0!	13.7890625	0.078125	2497.357178	0.875	0	-0.9785625	35.83	100	1	0	3	2	55098060	0	5	120.0274725	0	202.5	82.47252747

AltNewHall	AltMotorElectricalVelocity	B92MotorVelocityErrorLimit	AltRotorDirection	AltMotorCommutationState	Hall A	Hall B	Hall C	Distance Travelled	Lifetime Counter	Accumulated Column Movement	FastThermalEstimateRise	ThermalEstimateRise	VehicleTemperature	MotorTuneSelector	EmulationModeStatus	PDCStatus	PowerOff DriveStageTemperature	CPU_LoadHold	TorqueInstantFlag	IncompletePowerDownTest Count	padding	LRE_PositionState	PositionExtrapActive	Encoder Offset	MotorReversal	Journey time to Fault - 1 (sec)	Journey time to Fault - 2 (sec)	Journey time to Fault - 3 (sec)	Journey time to Fault - 4 (sec)	Journey time to Fault - 5 (sec)	Journey time to Fault - 6 (sec)	Journey time to Fault - 7 (sec)	Journey time to Fault - 8 (sec)	Average number of journeys between faults	Primary Code		
1	0	960	-1	6	0	1	1	6917091	613650	16130	0.21	0.62	2	0	0	1	4322	13384	1	1	0	0	0	0	317	810	-	-	-	-	-	-	122	B9A			
0	0	960	-1	6	0	1	1	6458112	527336	11993	0.12	0.16	2	0	0	1	4490	13376	1	1	0	0	0	0	1288	2645	-	3	3	1760	-	-	4.6	B9A			
0	0	960	1	2	0	1	0	10586896	602166	13285	0.02	0.07	2	0	0	1	4167	13358	1	1	0	0	1	0	1981	840	609	1564	3663	-	-	-	27.5	B9A			
1	0	960	1	4	0	0	1	19063512	1665106	36358	0.12	0.17	2	0	0	1	3472	13351	1	1	0	0	1	0	923	911	12	-	-	-	-	-	1	B9A			
0	76	980	-1	6	0	1	1	15538746	1112750	17527	0.14	0.48	2	0	0	1	3026	13365	1	1	0	0	1	0	1	3120	1256	547	7	3	1724	-	-	46	B9A		
0	0	960	-1	3	1	1	0	12842	2804	111	0.61	1.98	3	0	0	1	3196	13457	1	1	0	0	0	0	0	361	3757	-	-	-	-	-	-	5	B9A		
1	0	960	-1	2	0	1	0	7894725	549108	11408	0.19	0.68	3	0	0	1	4437	13395	1	1	0	0	0	0	1.8	0.9	0.7	0.6	16	1.3	606	-	-	36	B9A		
0	0	960	-1	6	0	1	1	10553441	589235	11847	0	0.14	2	0	0	1	3538	13501	1	1	0	0	0	0	540	24	-	-	-	-	-	-	-	1	B9A		
0	0	960	-1	6	0	1	1	15635	5261	200	1.83	3.08	2	0	0	1	492	13442	1	1	0	0	0	0	166	17	9	10	10	-	-	-	-	31	B9A		
0	0	960	-1	6	0	1	0	1737930	159448	5414	21	107	2	0	0	1	2888	13320	1	1	0	0	0	0	12	5.6	8.4	8	-	-	-	-	-	140	B9A		
0	0	960	-1	1	1	0	0	2695	920	1305	11.36	28.56	2	0	0	1	2745	13544	1	1	0	0	0	0	192	-	-	-	-	-	-	-	-	6	B4E		
								1834092	125146	2290	0.22	0.72	2	0	0	1	2153	13533	1	1	0	0	0	0	1.8	2.1	-	-	-	-	-	-	-	3	BdX		
1	0	960	1	3	1	1	0	34063356	1974880	42402	1.04	0.94	2	0	0	1	811	13459	1	1	0	0	0	0	3.4	-	-	-	-	-	-	-	-	10	B9A		
0	0	960	-1	2	0	1	0	2650844	167019	5208	0.03	0.08	2	0	0	1	2322	13543	1	1	0	0	0	0	12	6	28	-	-	-	-	-	-	-	1	B9A	
89.98351648	0	960	-1	1	1	0	0	43283	15219	1604	0.72	2.59	3	0	0	1	792	13500	1	1	0	0	0	0	15	1	12	2	-	-	-	-	-	2	B9A		
0	0	960	-1	5	1	0	1	14251	1948	738	0.09	3.37	3	0	0	1	2833	13466	1	1	0	0	0	0	4.5	-	-	-	-	-	-	-	-	-	-	B9A	
0	0	960	-1	2	0	1	0	3380111	289130	6943	0.25	0.43	2	0	0	1	638	13316	1	1	0	0	0	0	33	-	-	-	-	-	-	-	-	-	-	B9A	
																																					B4E
																																					B4E
89.93956044	0	960	-1	6	0	1	1	14410549	988449	17191	1.6	0.71	2	0	0	1	71	13367	1	1	0	0	0	0	4.5	8	28	8.5	-	-	-	-	-	-	130	B9A	
-90.04395604	0	960	1	4	0	0	1	9967568	675030	14176	0.04	0.26	2	0	0	1	951	13342	1	1	0	0	0	0	2.5	-	-	-	-	-	-	-	-	-	-	B9A	
0	0	960	1	2	0	1	0	12410	1999	1005	17	575	3	0	0	1	3107	13479	1	1	0	0	0	0	28	-	-	-	-	-	-	-	-	-	-	B9A	
0	0	960	-1	2	0	1	0	19743	5964	1087	0.1	0.47	2	0	0	1	5419	13473	1	1	0	0	0	0	9	8	1.5	-	-	-	-	-	-	-	1	B9A	
-97.97142857	0	960	1	2	0	1	0	4697531	302743	7721	0.14	0.74	2	0	0	1	742	13467	1	1	0	0	0	0	2.5	-	-	-	-	-	-	-	-	-	-	B9A	
-60.07142857	0	960	1	2	0	1	0	1542370	152721	5966	0.49	3.19	3	0	0	1	4198	13738	1	1	0	0	0	0	174	589	-	-	-	-	-	-	-	-	2	B9A	
270	0	960	1	3	1	1	0	1261631	165814	8208	0.42	1.79	2	0	0	1	2755	13460	1	1	0	0	0	0	4	29	-	-	-	-	-	-	-	-	9	B9A	
0	0	960	1	3	1	1	0	11816	3282	943	30.21	14.66	3	0	0	1	4966	13464	1	1	0	0	0	0	45	-	-	-	-	-	-	-	-	-	-	B9A	
0	0	960	-1	3	1	1	0	11372	2826	1034	0.29	5.69	2	0	0	1	3647	13449	1	1	0	0	1	0	0.2	-	-	-	-	-	-	-	-	-	-	23	B9Z
								789133	47129	1382	0.15	0.2	3	0	0	1	1740	13524	1	1	0	0	0	0	0.2	0.2	0.2	0.2	0.2	0.2	-	-	-	-	-	-	BdX
0	-7	962	1	6	0	1	1	855553	59735	2650	0.09	0.41	2	0	0	1	2840	13466	1	1	0	0	0	0	2123	-	-	-	-	-	-	-	-	-	-	B9A	
1	2011	1502	1	5	1	0	1	40719668	3958600	95429	0.14	0.4	2	0	0	1	5165	13438	1	1	0	0	0	0	38	3.3	1025	-	-	-	-	-	-	-	1	B9A	
								4090683	319039	9865	0.13	0.21	2	0	0	1	2887	13484	1	1	0	0	0	0	0.8	0.8	0.8	0.8	0.8	0.8	0.8	0.8	0.8	0.8	0.8	3	BdX
0	0	960	-1	1	1	0	0	4686287	359632	8458	0.17	0.23	3	0	0	1	3563	13367	1	1	0	0	0	0	200	3.6	842	-	-	-	-	-	-	-	95	B9A	
0	0	960	-1	1	1	0	0	14094330	1008897	21800	0.09	1.1	2	0	0	1	3128	13426	1	1	0	0	0	0	667	22	-	-	-	-	-	-	-	-	-	18	B9A
0	0	960	1	2	0	1	0	10384575	828077	32918	0.09	5.3	2	0	0	1	2245	13392	1	1	0	0	0	0	18	1.6	7	4	10	-	-	-	-	-	-	4	B9A
								25302448	1640076	37306	0.36	0.92	2	0	0	1	3844	13416	1	1	0	0	0	0	1.2	-	-	-	-	-	-	-	-	-	-	-	BdX
82.43956044	0	960	-1	6	0	1	1	31521548	2369480	45177	0.12	0.36	2	0	0	1	3555	13451	1	1	0	0	0	0	72	11	1232	1693	21	4	10	-	-	-	6	B9A	
0	0	960	1	3	1	1	0	6169085	557584	18426	0.14	0.38	2	0	0	1	4619	13484	1	1	0	0	0	0	32	-	-	-	-	-	-	-	-	-	-	B9A	
0	0	960	-1	5	1	0	1	1211875	117063	2621	0.69	1.19	3	0	0	1	3771	13385	1	1	0	0	0	0	7	-	-	-	-	-	-	-	-	-	-	B9A	



27-Jul-08	27-Jul-08	27-Jul-08	27-Jul-08			27-Mar-08
28-Jul-08	28-Jul-08	28-Jul-08	28-Jul-08			28-Mar-08
29-Jul-08	29-Jul-08	29-Jul-08	29-Jul-08			29-Mar-08
30-Jul-08	30-Jul-08	30-Jul-08	30-Jul-08			30-Mar-08
31-Jul-08	31-Jul-08	31-Jul-08	31-Jul-08			31-Mar-08
1-Aug-08	1-Aug-08	1-Aug-08	1-Aug-08			1-Apr-08
2-Aug-08	2-Aug-08	2-Aug-08	2-Aug-08			2-Apr-08
3-Aug-08	3-Aug-08	3-Aug-08	3-Aug-08			3-Apr-08
4-Aug-08	4-Aug-08	4-Aug-08	4-Aug-08			4-Apr-08
5-Aug-08	5-Aug-08	5-Aug-08	5-Aug-08			5-Apr-08
6-Aug-08	6-Aug-08	6-Aug-08	6-Aug-08			6-Apr-08
7-Aug-08	7-Aug-08	7-Aug-08	7-Aug-08			7-Apr-08
8-Aug-08	8-Aug-08	8-Aug-08	8-Aug-08			8-Apr-08
9-Aug-08	9-Aug-08	9-Aug-08	9-Aug-08			9-Apr-08
10-Aug-08	10-Aug-08	10-Aug-08	10-Aug-08			10-Apr-08
11-Aug-08	11-Aug-08	11-Aug-08	11-Aug-08			11-Apr-08
12-Aug-08	12-Aug-08	12-Aug-08	12-Aug-08			12-Apr-08
13-Aug-08	13-Aug-08	13-Aug-08	13-Aug-08			13-Apr-08
14-Aug-08	14-Aug-08	14-Aug-08	14-Aug-08			14-Apr-08
15-Aug-08	15-Aug-08	15-Aug-08	15-Aug-08			15-Apr-08
16-Aug-08	16-Aug-08	16-Aug-08	16-Aug-08			16-Apr-08
17-Aug-08	17-Aug-08	17-Aug-08	17-Aug-08			17-Apr-08
18-Aug-08	18-Aug-08	18-Aug-08	18-Aug-08			18-Apr-08
19-Aug-08	19-Aug-08	19-Aug-08	19-Aug-08			19-Apr-08
20-Aug-08	20-Aug-08	20-Aug-08	20-Aug-08			20-Apr-08
21-Aug-08	21-Aug-08	21-Aug-08	21-Aug-08			21-Apr-08
22-Aug-08	22-Aug-08	22-Aug-08	22-Aug-08			22-Apr-08
23-Aug-08	23-Aug-08	23-Aug-08	23-Aug-08			23-Apr-08
24-Aug-08	24-Aug-08	24-Aug-08	24-Aug-08			24-Apr-08
25-Aug-08	25-Aug-08	25-Aug-08	25-Aug-08			25-Apr-08
26-Aug-08	26-Aug-08	26-Aug-08	26-Aug-08			26-Apr-08
27-Aug-08	27-Aug-08	27-Aug-08	27-Aug-08			27-Apr-08
28-Aug-08	28-Aug-08	28-Aug-08	28-Aug-08			28-Apr-08
29-Aug-08	29-Aug-08	29-Aug-08	29-Aug-08			29-Apr-08
30-Aug-08	30-Aug-08	30-Aug-08	30-Aug-08			30-Apr-08
31-Aug-08	31-Aug-08	31-Aug-08	31-Aug-08			1-May-08
1-Sep-08	1-Sep-08	1-Sep-08	1-Sep-08			2-May-08
2-Sep-08	2-Sep-08	2-Sep-08	2-Sep-08			3-May-08
3-Sep-08	3-Sep-08	3-Sep-08	3-Sep-08			4-May-08
4-Sep-08	4-Sep-08	4-Sep-08	4-Sep-08			5-May-08
5-Sep-08	5-Sep-08	5-Sep-08	5-Sep-08			6-May-08
6-Sep-08	6-Sep-08	6-Sep-08	6-Sep-08			7-May-08
7-Sep-08	7-Sep-08	7-Sep-08	7-Sep-08			8-May-08
8-Sep-08	8-Sep-08	8-Sep-08	8-Sep-08			9-May-08
9-Sep-08	9-Sep-08	9-Sep-08	9-Sep-08			10-May-08
10-Sep-08	10-Sep-08	10-Sep-08	10-Sep-08			11-May-08
11-Sep-08	11-Sep-08	11-Sep-08	11-Sep-08			12-May-08
12-Sep-08	12-Sep-08	12-Sep-08	12-Sep-08			13-May-08
13-Sep-08	13-Sep-08	13-Sep-08	13-Sep-08			14-May-08
14-Sep-08	14-Sep-08	14-Sep-08	14-Sep-08			15-May-08
15-Sep-08	15-Sep-08	15-Sep-08	15-Sep-08			16-May-08
16-Sep-08	16-Sep-08	16-Sep-08	16-Sep-08			17-May-08
17-Sep-08	17-Sep-08	17-Sep-08	17-Sep-08			18-May-08
18-Sep-08	18-Sep-08	18-Sep-08	18-Sep-08			19-May-08
19-Sep-08	19-Sep-08	19-Sep-08	19-Sep-08			20-May-08
20-Sep-08	20-Sep-08	20-Sep-08	20-Sep-08			21-May-08
21-Sep-08	21-Sep-08	21-Sep-08	21-Sep-08			22-May-08
22-Sep-08	22-Sep-08	22-Sep-08	22-Sep-08			23-May-08
23-Sep-08	23-Sep-08	23-Sep-08	23-Sep-08			24-May-08
24-Sep-08	24-Sep-08	24-Sep-08	24-Sep-08			25-May-08
25-Sep-08	25-Sep-08	25-Sep-08	25-Sep-08			26-May-08
26-Sep-08	26-Sep-08	26-Sep-08	26-Sep-08			27-May-08
27-Sep-08	27-Sep-08	27-Sep-08	27-Sep-08			28-May-08
28-Sep-08	28-Sep-08	28-Sep-08	28-Sep-08			29-May-08
29-Sep-08	29-Sep-08	29-Sep-08	29-Sep-08			30-May-08
30-Sep-08	30-Sep-08	30-Sep-08	30-Sep-08			31-May-08
1-Oct-08	1-Oct-08	1-Oct-08	1-Oct-08			1-Jun-08
2-Oct-08	2-Oct-08	2-Oct-08	2-Oct-08			2-Jun-08
3-Oct-08	3-Oct-08	3-Oct-08	3-Oct-08			3-Jun-08
4-Oct-08	4-Oct-08	4-Oct-08	4-Oct-08			4-Jun-08
5-Oct-08	5-Oct-08	5-Oct-08	5-Oct-08			5-Jun-08
6-Oct-08	6-Oct-08	6-Oct-08	6-Oct-08			6-Jun-08
7-Oct-08	7-Oct-08	7-Oct-08	7-Oct-08			7-Jun-08
8-Oct-08	8-Oct-08	8-Oct-08	8-Oct-08			8-Jun-08
9-Oct-08	9-Oct-08	9-Oct-08	9-Oct-08			9-Jun-08

836 0836  
837 0837  
838 0838  
839 0839  
840 0840  
841 0841  
842 0842  
843 0843  
844 0844  
845 0845  
846 0846  
847 0847  
848 0848  
849 0849  
850 0850  
851 0851  
852 0852  
901 0901  
902 0902  
903 0903  
904 0904  
905 0905  
906 0906  
907 0907  
908 0908  
909 0909  
910 0910  
911 0911  
912 0912  
913 0913  
914 0914  
915 0915  
916 0916  
917 0917  
918 0918  
919 0919  
920 0920  
921 0921  
922 0922  
923 0923  
924 0924  
925 0925  
926 0926  
927 0927  
928 0928  
929 0929  
930 0930  
931 0931  
932 0932  
933 0933  
934 0934  
935 0935  
936 0936  
937 0937  
938 0938  
939 0939  
940 0940  
941 0941  
942 0942  
943 0943  
944 0944  
945 0945  
946 0946  
947 0947  
948 0948  
949 0949  
950 0950  
951 0951  
952 0952



10-Oct-08	10-Oct-08	10-Oct-08	10-Oct-08		10-Jun-08
11-Oct-08	11-Oct-08	11-Oct-08	11-Oct-08		11-Jun-08
12-Oct-08	12-Oct-08	12-Oct-08	12-Oct-08		12-Jun-08
13-Oct-08	13-Oct-08	13-Oct-08	13-Oct-08		13-Jun-08
14-Oct-08	14-Oct-08	14-Oct-08	14-Oct-08		14-Jun-08
15-Oct-08	15-Oct-08	15-Oct-08	15-Oct-08		15-Jun-08
16-Oct-08	16-Oct-08	16-Oct-08	16-Oct-08		16-Jun-08
17-Oct-08	17-Oct-08	17-Oct-08	17-Oct-08		17-Jun-08
18-Oct-08	18-Oct-08	18-Oct-08	18-Oct-08		18-Jun-08
19-Oct-08	19-Oct-08	19-Oct-08	19-Oct-08		19-Jun-08
20-Oct-08	20-Oct-08	20-Oct-08	20-Oct-08		20-Jun-08
21-Oct-08	21-Oct-08	21-Oct-08	21-Oct-08		21-Jun-08
22-Oct-08	22-Oct-08	22-Oct-08	22-Oct-08		22-Jun-08
23-Oct-08	23-Oct-08	23-Oct-08	23-Oct-08		23-Jun-08
24-Oct-08	24-Oct-08	24-Oct-08	24-Oct-08		24-Jun-08
25-Oct-08	25-Oct-08	25-Oct-08	25-Oct-08		25-Jun-08
26-Oct-08	26-Oct-08	26-Oct-08	26-Oct-08		26-Jun-08
27-Oct-08	27-Oct-08	27-Oct-08	27-Oct-08		27-Jun-08
28-Oct-08	28-Oct-08	28-Oct-08	28-Oct-08		28-Jun-08
29-Oct-08	29-Oct-08	29-Oct-08	29-Oct-08		29-Jun-08
30-Oct-08	30-Oct-08	30-Oct-08	30-Oct-08		30-Jun-08
31-Oct-08	31-Oct-08	31-Oct-08	31-Oct-08		1-Jul-08
1-Nov-08	1-Nov-08	1-Nov-08	1-Nov-08		2-Jul-08
2-Nov-08	2-Nov-08	2-Nov-08	2-Nov-08		3-Jul-08
3-Nov-08	3-Nov-08	3-Nov-08	3-Nov-08		4-Jul-08
4-Nov-08	4-Nov-08	4-Nov-08	4-Nov-08		5-Jul-08
5-Nov-08	5-Nov-08	5-Nov-08	5-Nov-08		6-Jul-08
6-Nov-08	6-Nov-08	6-Nov-08	6-Nov-08		7-Jul-08
7-Nov-08	7-Nov-08	7-Nov-08	7-Nov-08		8-Jul-08
8-Nov-08	8-Nov-08	8-Nov-08	8-Nov-08		9-Jul-08
9-Nov-08	9-Nov-08	9-Nov-08	9-Nov-08		10-Jul-08
10-Nov-08	10-Nov-08	10-Nov-08	10-Nov-08		11-Jul-08
11-Nov-08	11-Nov-08	11-Nov-08	11-Nov-08		12-Jul-08
12-Nov-08	12-Nov-08	12-Nov-08	12-Nov-08		13-Jul-08
13-Nov-08	13-Nov-08	13-Nov-08	13-Nov-08		14-Jul-08
14-Nov-08	14-Nov-08	14-Nov-08	14-Nov-08		15-Jul-08
15-Nov-08	15-Nov-08	15-Nov-08	15-Nov-08		16-Jul-08
16-Nov-08	16-Nov-08	16-Nov-08	16-Nov-08		17-Jul-08
17-Nov-08	17-Nov-08	17-Nov-08	17-Nov-08		18-Jul-08
18-Nov-08	18-Nov-08	18-Nov-08	18-Nov-08		19-Jul-08
19-Nov-08	19-Nov-08	19-Nov-08	19-Nov-08		20-Jul-08
20-Nov-08	20-Nov-08	20-Nov-08	20-Nov-08		21-Jul-08
21-Nov-08	21-Nov-08	21-Nov-08	21-Nov-08		22-Jul-08
22-Nov-08	22-Nov-08	22-Nov-08	22-Nov-08		23-Jul-08
23-Nov-08	23-Nov-08	23-Nov-08	23-Nov-08		24-Jul-08
24-Nov-08	24-Nov-08	24-Nov-08	24-Nov-08		25-Jul-08
25-Nov-08	25-Nov-08	25-Nov-08	25-Nov-08		26-Jul-08
26-Nov-08	26-Nov-08	26-Nov-08	26-Nov-08		27-Jul-08
27-Nov-08	27-Nov-08	27-Nov-08	27-Nov-08		28-Jul-08
28-Nov-08	28-Nov-08	28-Nov-08	28-Nov-08		29-Jul-08
29-Nov-08	29-Nov-08	29-Nov-08	29-Nov-08		30-Jul-08
30-Nov-08	30-Nov-08	30-Nov-08	30-Nov-08		31-Jul-08
1-Dec-08	1-Dec-08	1-Dec-08	1-Dec-08		1-Aug-08
2-Dec-08	2-Dec-08	2-Dec-08	2-Dec-08		2-Aug-08
3-Dec-08	3-Dec-08	3-Dec-08	3-Dec-08		3-Aug-08
4-Dec-08	4-Dec-08	4-Dec-08	4-Dec-08		4-Aug-08
5-Dec-08	5-Dec-08	5-Dec-08	5-Dec-08		5-Aug-08
6-Dec-08	6-Dec-08	6-Dec-08	6-Dec-08		6-Aug-08
7-Dec-08	7-Dec-08	7-Dec-08	7-Dec-08		7-Aug-08
8-Dec-08	8-Dec-08	8-Dec-08	8-Dec-08		8-Aug-08
9-Dec-08	9-Dec-08	9-Dec-08	9-Dec-08		9-Aug-08
10-Dec-08	10-Dec-08	10-Dec-08	10-Dec-08		10-Aug-08
11-Dec-08	11-Dec-08	11-Dec-08	11-Dec-08		11-Aug-08
12-Dec-08	12-Dec-08	12-Dec-08	12-Dec-08		12-Aug-08
13-Dec-08	13-Dec-08	13-Dec-08	13-Dec-08		13-Aug-08
14-Dec-08	14-Dec-08	14-Dec-08	14-Dec-08		14-Aug-08
15-Dec-08	15-Dec-08	15-Dec-08	15-Dec-08		15-Aug-08
16-Dec-08	16-Dec-08	16-Dec-08	16-Dec-08		16-Aug-08
17-Dec-08	17-Dec-08	17-Dec-08	17-Dec-08		17-Aug-08
18-Dec-08	18-Dec-08	18-Dec-08	18-Dec-08		18-Aug-08
19-Dec-08	19-Dec-08	19-Dec-08	19-Dec-08		19-Aug-08
20-Dec-08	20-Dec-08	20-Dec-08	20-Dec-08		20-Aug-08
21-Dec-08	21-Dec-08	21-Dec-08	21-Dec-08		21-Aug-08
22-Dec-08	22-Dec-08	22-Dec-08	22-Dec-08		22-Aug-08
23-Dec-08	23-Dec-08	23-Dec-08	23-Dec-08		23-Aug-08

24-Dec-08	24-Dec-08	24-Dec-08	24-Dec-08			24-Aug-08
25-Dec-08	25-Dec-08	25-Dec-08	25-Dec-08			25-Aug-08
26-Dec-08	26-Dec-08	26-Dec-08	26-Dec-08			26-Aug-08
27-Dec-08	27-Dec-08	27-Dec-08	27-Dec-08			27-Aug-08
28-Dec-08	28-Dec-08	28-Dec-08	28-Dec-08			28-Aug-08
29-Dec-08	29-Dec-08	29-Dec-08	29-Dec-08			29-Aug-08
30-Dec-08	30-Dec-08	30-Dec-08	30-Dec-08			30-Aug-08
31-Dec-08	31-Dec-08	31-Dec-08	31-Dec-08			31-Aug-08
1-Jan-09	1-Jan-09	1-Jan-09	1-Jan-09			1-Sep-08
2-Jan-09	2-Jan-09	2-Jan-09	2-Jan-09			2-Sep-08
3-Jan-09	3-Jan-09	3-Jan-09	3-Jan-09			3-Sep-08
4-Jan-09	4-Jan-09	4-Jan-09	4-Jan-09			4-Sep-08
5-Jan-09	5-Jan-09	5-Jan-09	5-Jan-09			5-Sep-08
6-Jan-09	6-Jan-09	6-Jan-09	6-Jan-09			6-Sep-08
7-Jan-09	7-Jan-09	7-Jan-09	7-Jan-09			7-Sep-08
8-Jan-09	8-Jan-09	8-Jan-09	8-Jan-09			8-Sep-08
9-Jan-09	9-Jan-09	9-Jan-09	9-Jan-09			9-Sep-08
10-Jan-09	10-Jan-09	10-Jan-09	10-Jan-09			10-Sep-08
11-Jan-09	11-Jan-09	11-Jan-09	11-Jan-09			11-Sep-08
12-Jan-09	12-Jan-09	12-Jan-09	12-Jan-09			12-Sep-08
13-Jan-09	13-Jan-09	13-Jan-09	13-Jan-09			13-Sep-08
14-Jan-09	14-Jan-09	14-Jan-09	14-Jan-09			14-Sep-08
15-Jan-09	15-Jan-09	15-Jan-09	15-Jan-09			15-Sep-08
16-Jan-09	16-Jan-09	16-Jan-09	16-Jan-09			16-Sep-08
17-Jan-09	17-Jan-09	17-Jan-09	17-Jan-09			17-Sep-08
18-Jan-09	18-Jan-09	18-Jan-09	18-Jan-09			18-Sep-08
19-Jan-09	19-Jan-09	19-Jan-09	19-Jan-09			19-Sep-08
20-Jan-09	20-Jan-09	20-Jan-09	20-Jan-09			20-Sep-08
21-Jan-09	21-Jan-09	21-Jan-09	21-Jan-09			21-Sep-08
22-Jan-09	22-Jan-09	22-Jan-09	22-Jan-09			22-Sep-08
23-Jan-09	23-Jan-09	23-Jan-09	23-Jan-09			23-Sep-08
24-Jan-09	24-Jan-09	24-Jan-09	24-Jan-09			24-Sep-08
25-Jan-09	25-Jan-09	25-Jan-09	25-Jan-09			25-Sep-08
26-Jan-09	26-Jan-09	26-Jan-09	26-Jan-09			26-Sep-08
27-Jan-09	27-Jan-09	27-Jan-09	27-Jan-09			27-Sep-08
28-Jan-09	28-Jan-09	28-Jan-09	28-Jan-09			28-Sep-08
29-Jan-09	29-Jan-09	29-Jan-09	29-Jan-09			29-Sep-08
30-Jan-09	30-Jan-09	30-Jan-09	30-Jan-09			30-Sep-08
31-Jan-09	31-Jan-09	31-Jan-09	31-Jan-09			1-Oct-08
1-Feb-09	1-Feb-09	1-Feb-09	1-Feb-09			2-Oct-08
2-Feb-09	2-Feb-09	2-Feb-09	2-Feb-09			3-Oct-08
3-Feb-09	3-Feb-09	3-Feb-09	3-Feb-09			4-Oct-08
4-Feb-09	4-Feb-09	4-Feb-09	4-Feb-09			5-Oct-08
5-Feb-09	5-Feb-09	5-Feb-09	5-Feb-09			6-Oct-08
6-Feb-09	6-Feb-09	6-Feb-09	6-Feb-09			7-Oct-08
7-Feb-09	7-Feb-09	7-Feb-09	7-Feb-09			8-Oct-08
8-Feb-09	8-Feb-09	8-Feb-09	8-Feb-09			9-Oct-08
9-Feb-09	9-Feb-09	9-Feb-09	9-Feb-09			10-Oct-08
10-Feb-09	10-Feb-09	10-Feb-09	10-Feb-09			11-Oct-08
11-Feb-09	11-Feb-09	11-Feb-09	11-Feb-09			12-Oct-08
12-Feb-09	12-Feb-09	12-Feb-09	12-Feb-09			13-Oct-08
13-Feb-09	13-Feb-09	13-Feb-09	13-Feb-09			14-Oct-08
14-Feb-09	14-Feb-09	14-Feb-09	14-Feb-09			15-Oct-08
15-Feb-09	15-Feb-09	15-Feb-09	15-Feb-09			16-Oct-08
16-Feb-09	16-Feb-09	16-Feb-09	16-Feb-09			17-Oct-08
17-Feb-09	17-Feb-09	17-Feb-09	17-Feb-09			18-Oct-08
18-Feb-09	18-Feb-09	18-Feb-09	18-Feb-09			19-Oct-08
19-Feb-09	19-Feb-09	19-Feb-09	19-Feb-09			20-Oct-08
20-Feb-09	20-Feb-09	20-Feb-09	20-Feb-09			21-Oct-08
21-Feb-09	21-Feb-09	21-Feb-09	21-Feb-09			22-Oct-08
22-Feb-09	22-Feb-09	22-Feb-09	22-Feb-09			23-Oct-08
23-Feb-09	23-Feb-09	23-Feb-09	23-Feb-09			24-Oct-08
24-Feb-09	24-Feb-09	24-Feb-09	24-Feb-09			25-Oct-08
25-Feb-09	25-Feb-09	25-Feb-09	25-Feb-09			26-Oct-08
26-Feb-09	26-Feb-09	26-Feb-09	26-Feb-09			27-Oct-08
27-Feb-09	27-Feb-09	27-Feb-09	27-Feb-09			28-Oct-08
28-Feb-09	28-Feb-09	28-Feb-09	28-Feb-09			29-Oct-08
1-Mar-09	1-Mar-09	1-Mar-09	1-Mar-09			30-Oct-08
2-Mar-09	2-Mar-09	2-Mar-09	2-Mar-09			31-Oct-08
3-Mar-09	3-Mar-09	3-Mar-09	3-Mar-09			1-Nov-08
4-Mar-09	4-Mar-09	4-Mar-09	4-Mar-09			2-Nov-08
5-Mar-09	5-Mar-09	5-Mar-09	5-Mar-09			3-Nov-08
6-Mar-09	6-Mar-09	6-Mar-09	6-Mar-09			4-Nov-08
7-Mar-09	7-Mar-09	7-Mar-09	7-Mar-09			5-Nov-08
8-Mar-09	8-Mar-09	8-Mar-09	8-Mar-09			6-Nov-08

9-Mar-09	9-Mar-09	9-Mar-09	9-Mar-09			7-Nov-08
10-Mar-09	10-Mar-09	10-Mar-09	10-Mar-09			8-Nov-08
11-Mar-09	11-Mar-09	11-Mar-09	11-Mar-09			9-Nov-08
12-Mar-09	12-Mar-09	12-Mar-09	12-Mar-09			10-Nov-08
13-Mar-09	13-Mar-09	13-Mar-09	13-Mar-09			11-Nov-08
14-Mar-09	14-Mar-09	14-Mar-09	14-Mar-09			12-Nov-08
15-Mar-09	15-Mar-09	15-Mar-09	15-Mar-09			13-Nov-08
16-Mar-09	16-Mar-09	16-Mar-09	16-Mar-09			14-Nov-08
17-Mar-09	17-Mar-09	17-Mar-09	17-Mar-09			15-Nov-08
18-Mar-09	18-Mar-09	18-Mar-09	18-Mar-09			16-Nov-08
19-Mar-09	19-Mar-09	19-Mar-09	19-Mar-09			17-Nov-08
20-Mar-09	20-Mar-09	20-Mar-09	20-Mar-09			18-Nov-08
21-Mar-09	21-Mar-09	21-Mar-09	21-Mar-09			19-Nov-08
22-Mar-09	22-Mar-09	22-Mar-09	22-Mar-09			20-Nov-08
23-Mar-09	23-Mar-09	23-Mar-09	23-Mar-09			21-Nov-08
24-Mar-09	24-Mar-09	24-Mar-09	24-Mar-09			22-Nov-08
25-Mar-09	25-Mar-09	25-Mar-09	25-Mar-09			23-Nov-08
26-Mar-09	26-Mar-09	26-Mar-09	26-Mar-09			24-Nov-08
27-Mar-09	27-Mar-09	27-Mar-09	27-Mar-09			25-Nov-08
28-Mar-09	28-Mar-09	28-Mar-09	28-Mar-09			26-Nov-08
29-Mar-09	29-Mar-09	29-Mar-09	29-Mar-09			27-Nov-08
30-Mar-09	30-Mar-09	30-Mar-09	30-Mar-09			28-Nov-08
31-Mar-09	31-Mar-09	31-Mar-09	31-Mar-09			29-Nov-08
1-Apr-09	1-Apr-09	1-Apr-09	1-Apr-09			30-Nov-08
2-Apr-09	2-Apr-09	2-Apr-09	2-Apr-09			1-Dec-08
3-Apr-09	3-Apr-09	3-Apr-09	3-Apr-09			2-Dec-08
4-Apr-09	4-Apr-09	4-Apr-09	4-Apr-09			3-Dec-08
5-Apr-09	5-Apr-09	5-Apr-09	5-Apr-09			4-Dec-08
6-Apr-09	6-Apr-09	6-Apr-09	6-Apr-09			5-Dec-08
7-Apr-09	7-Apr-09	7-Apr-09	7-Apr-09			6-Dec-08
8-Apr-09	8-Apr-09	8-Apr-09	8-Apr-09			7-Dec-08
9-Apr-09	9-Apr-09	9-Apr-09	9-Apr-09			8-Dec-08
10-Apr-09	10-Apr-09	10-Apr-09	10-Apr-09			9-Dec-08
11-Apr-09	11-Apr-09	11-Apr-09	11-Apr-09			10-Dec-08
12-Apr-09	12-Apr-09	12-Apr-09	12-Apr-09			11-Dec-08
13-Apr-09	13-Apr-09	13-Apr-09	13-Apr-09			12-Dec-08
14-Apr-09	14-Apr-09	14-Apr-09	14-Apr-09			13-Dec-08
15-Apr-09	15-Apr-09	15-Apr-09	15-Apr-09			14-Dec-08
16-Apr-09	16-Apr-09	16-Apr-09	16-Apr-09			15-Dec-08
17-Apr-09	17-Apr-09	17-Apr-09	17-Apr-09			16-Dec-08
18-Apr-09	18-Apr-09	18-Apr-09	18-Apr-09			17-Dec-08
19-Apr-09	19-Apr-09	19-Apr-09	19-Apr-09			18-Dec-08
20-Apr-09	20-Apr-09	20-Apr-09	20-Apr-09			19-Dec-08
21-Apr-09	21-Apr-09	21-Apr-09	21-Apr-09			20-Dec-08
22-Apr-09	22-Apr-09	22-Apr-09	22-Apr-09			21-Dec-08
23-Apr-09	23-Apr-09	23-Apr-09	23-Apr-09			22-Dec-08
24-Apr-09	24-Apr-09	24-Apr-09	24-Apr-09			23-Dec-08
25-Apr-09	25-Apr-09	25-Apr-09	25-Apr-09			24-Dec-08
26-Apr-09	26-Apr-09	26-Apr-09	26-Apr-09			25-Dec-08
27-Apr-09	27-Apr-09	27-Apr-09	27-Apr-09			26-Dec-08
28-Apr-09	28-Apr-09	28-Apr-09	28-Apr-09			27-Dec-08
29-Apr-09	29-Apr-09	29-Apr-09	29-Apr-09			28-Dec-08
30-Apr-09	30-Apr-09	30-Apr-09	30-Apr-09			29-Dec-08
1-May-09	1-May-09	1-May-09	1-May-09			30-Dec-08
2-May-09	2-May-09	2-May-09	2-May-09			31-Dec-08
3-May-09	3-May-09	3-May-09	3-May-09			1-Jan-09
4-May-09	4-May-09	4-May-09	4-May-09			2-Jan-09
5-May-09	5-May-09	5-May-09	5-May-09			3-Jan-09
6-May-09	6-May-09	6-May-09	6-May-09			4-Jan-09
7-May-09	7-May-09	7-May-09	7-May-09			5-Jan-09
8-May-09	8-May-09	8-May-09	8-May-09			6-Jan-09
9-May-09	9-May-09	9-May-09	9-May-09			7-Jan-09
10-May-09	10-May-09	10-May-09	10-May-09			8-Jan-09
11-May-09	11-May-09	11-May-09	11-May-09			9-Jan-09
12-May-09	12-May-09	12-May-09	12-May-09			10-Jan-09
13-May-09	13-May-09	13-May-09	13-May-09			11-Jan-09
14-May-09	14-May-09	14-May-09	14-May-09			12-Jan-09
15-May-09	15-May-09	15-May-09	15-May-09			13-Jan-09
16-May-09	16-May-09	16-May-09	16-May-09			14-Jan-09
17-May-09	17-May-09	17-May-09	17-May-09			15-Jan-09
18-May-09	18-May-09	18-May-09	18-May-09			16-Jan-09
19-May-09	19-May-09	19-May-09	19-May-09			17-Jan-09
20-May-09	20-May-09	20-May-09	20-May-09			18-Jan-09
21-May-09	21-May-09	21-May-09	21-May-09			19-Jan-09
22-May-09	22-May-09	22-May-09	22-May-09			20-Jan-09

23-May-09	23-May-09	23-May-09	23-May-09			21-Jan-09
24-May-09	24-May-09	24-May-09	24-May-09			22-Jan-09
25-May-09	25-May-09	25-May-09	25-May-09			23-Jan-09
26-May-09	26-May-09	26-May-09	26-May-09			24-Jan-09
27-May-09	27-May-09	27-May-09	27-May-09			25-Jan-09
28-May-09	28-May-09	28-May-09	28-May-09			26-Jan-09
29-May-09	29-May-09	29-May-09	29-May-09			27-Jan-09
30-May-09	30-May-09	30-May-09	30-May-09			28-Jan-09
31-May-09	31-May-09	31-May-09	31-May-09			29-Jan-09
1-Jun-09	1-Jun-09	1-Jun-09	1-Jun-09			30-Jan-09
2-Jun-09	2-Jun-09	2-Jun-09	2-Jun-09			31-Jan-09
3-Jun-09	3-Jun-09	3-Jun-09	3-Jun-09			1-Feb-09
4-Jun-09	4-Jun-09	4-Jun-09	4-Jun-09			2-Feb-09
5-Jun-09	5-Jun-09	5-Jun-09	5-Jun-09			3-Feb-09
6-Jun-09	6-Jun-09	6-Jun-09	6-Jun-09			4-Feb-09
7-Jun-09	7-Jun-09	7-Jun-09	7-Jun-09			5-Feb-09
8-Jun-09	8-Jun-09	8-Jun-09	8-Jun-09			6-Feb-09
9-Jun-09	9-Jun-09	9-Jun-09	9-Jun-09			7-Feb-09
10-Jun-09	10-Jun-09	10-Jun-09	10-Jun-09			8-Feb-09
11-Jun-09	11-Jun-09	11-Jun-09	11-Jun-09			9-Feb-09
12-Jun-09	12-Jun-09	12-Jun-09	12-Jun-09			10-Feb-09
13-Jun-09	13-Jun-09	13-Jun-09	13-Jun-09			11-Feb-09
14-Jun-09	14-Jun-09	14-Jun-09	14-Jun-09			12-Feb-09
15-Jun-09	15-Jun-09	15-Jun-09	15-Jun-09			13-Feb-09
16-Jun-09	16-Jun-09	16-Jun-09	16-Jun-09			14-Feb-09
17-Jun-09	17-Jun-09	17-Jun-09	17-Jun-09			15-Feb-09
18-Jun-09	18-Jun-09	18-Jun-09	18-Jun-09			16-Feb-09
19-Jun-09	19-Jun-09	19-Jun-09	19-Jun-09			17-Feb-09
20-Jun-09	20-Jun-09	20-Jun-09	20-Jun-09			18-Feb-09
21-Jun-09	21-Jun-09	21-Jun-09	21-Jun-09			19-Feb-09
22-Jun-09	22-Jun-09	22-Jun-09	22-Jun-09			20-Feb-09
23-Jun-09	23-Jun-09	23-Jun-09	23-Jun-09			21-Feb-09
24-Jun-09	24-Jun-09	24-Jun-09	24-Jun-09			22-Feb-09
25-Jun-09	25-Jun-09	25-Jun-09	25-Jun-09			23-Feb-09
26-Jun-09	26-Jun-09	26-Jun-09	26-Jun-09			24-Feb-09
27-Jun-09	27-Jun-09	27-Jun-09	27-Jun-09			25-Feb-09
28-Jun-09	28-Jun-09	28-Jun-09	28-Jun-09			26-Feb-09
29-Jun-09	29-Jun-09	29-Jun-09	29-Jun-09			27-Feb-09
30-Jun-09	30-Jun-09	30-Jun-09	30-Jun-09			28-Feb-09
1-Jul-09	1-Jul-09	1-Jul-09	1-Jul-09			1-Mar-09
2-Jul-09	2-Jul-09	2-Jul-09	2-Jul-09			2-Mar-09
3-Jul-09	3-Jul-09	3-Jul-09	3-Jul-09			3-Mar-09
4-Jul-09	4-Jul-09	4-Jul-09	4-Jul-09			4-Mar-09
5-Jul-09	5-Jul-09	5-Jul-09	5-Jul-09			5-Mar-09
6-Jul-09	6-Jul-09	6-Jul-09	6-Jul-09			6-Mar-09
7-Jul-09	7-Jul-09	7-Jul-09	7-Jul-09			7-Mar-09
8-Jul-09	8-Jul-09	8-Jul-09	8-Jul-09			8-Mar-09
9-Jul-09	9-Jul-09	9-Jul-09	9-Jul-09			9-Mar-09
10-Jul-09	10-Jul-09	10-Jul-09	10-Jul-09			10-Mar-09
11-Jul-09	11-Jul-09	11-Jul-09	11-Jul-09			11-Mar-09
12-Jul-09	12-Jul-09	12-Jul-09	12-Jul-09			12-Mar-09
13-Jul-09	13-Jul-09	13-Jul-09	13-Jul-09			13-Mar-09
14-Jul-09	14-Jul-09	14-Jul-09	14-Jul-09			14-Mar-09
15-Jul-09	15-Jul-09	15-Jul-09	15-Jul-09			15-Mar-09
16-Jul-09	16-Jul-09	16-Jul-09	16-Jul-09			16-Mar-09
17-Jul-09	17-Jul-09	17-Jul-09	17-Jul-09			17-Mar-09
18-Jul-09	18-Jul-09	18-Jul-09	18-Jul-09			18-Mar-09
19-Jul-09	19-Jul-09	19-Jul-09	19-Jul-09			19-Mar-09
20-Jul-09	20-Jul-09	20-Jul-09	20-Jul-09			20-Mar-09
21-Jul-09	21-Jul-09	21-Jul-09	21-Jul-09			21-Mar-09
22-Jul-09	22-Jul-09	22-Jul-09	22-Jul-09			22-Mar-09
23-Jul-09	23-Jul-09	23-Jul-09	23-Jul-09			23-Mar-09
24-Jul-09	24-Jul-09	24-Jul-09	24-Jul-09			24-Mar-09
25-Jul-09	25-Jul-09	25-Jul-09	25-Jul-09			25-Mar-09
26-Jul-09	26-Jul-09	26-Jul-09	26-Jul-09			26-Mar-09
27-Jul-09	27-Jul-09	27-Jul-09	27-Jul-09			27-Mar-09
28-Jul-09	28-Jul-09	28-Jul-09	28-Jul-09			28-Mar-09
29-Jul-09	29-Jul-09	29-Jul-09	29-Jul-09			29-Mar-09
30-Jul-09	30-Jul-09	30-Jul-09	30-Jul-09			30-Mar-09
31-Jul-09	31-Jul-09	31-Jul-09	31-Jul-09			31-Mar-09
1-Aug-09	1-Aug-09	1-Aug-09	1-Aug-09			1-Apr-09
2-Aug-09	2-Aug-09	2-Aug-09	2-Aug-09			2-Apr-09
3-Aug-09	3-Aug-09	3-Aug-09	3-Aug-09			3-Apr-09
4-Aug-09	4-Aug-09	4-Aug-09	4-Aug-09			4-Apr-09
5-Aug-09	5-Aug-09	5-Aug-09	5-Aug-09			5-Apr-09

6-Aug-09	6-Aug-09	6-Aug-09	6-Aug-09		6-Apr-09
7-Aug-09	7-Aug-09	7-Aug-09	7-Aug-09		7-Apr-09
8-Aug-09	8-Aug-09	8-Aug-09	8-Aug-09		8-Apr-09
9-Aug-09	9-Aug-09	9-Aug-09	9-Aug-09		9-Apr-09
10-Aug-09	10-Aug-09	10-Aug-09	10-Aug-09		10-Apr-09
11-Aug-09	11-Aug-09	11-Aug-09	11-Aug-09		11-Apr-09
12-Aug-09	12-Aug-09	12-Aug-09	12-Aug-09		12-Apr-09
13-Aug-09	13-Aug-09	13-Aug-09	13-Aug-09		13-Apr-09
14-Aug-09	14-Aug-09	14-Aug-09	14-Aug-09		14-Apr-09
15-Aug-09	15-Aug-09	15-Aug-09	15-Aug-09		15-Apr-09
16-Aug-09	16-Aug-09	16-Aug-09	16-Aug-09		16-Apr-09
17-Aug-09	17-Aug-09	17-Aug-09	17-Aug-09		17-Apr-09
18-Aug-09	18-Aug-09	18-Aug-09	18-Aug-09		18-Apr-09
19-Aug-09	19-Aug-09	19-Aug-09	19-Aug-09		19-Apr-09
20-Aug-09	20-Aug-09	20-Aug-09	20-Aug-09		20-Apr-09
21-Aug-09	21-Aug-09	21-Aug-09	21-Aug-09		21-Apr-09
22-Aug-09	22-Aug-09	22-Aug-09	22-Aug-09		22-Apr-09
23-Aug-09	23-Aug-09	23-Aug-09	23-Aug-09		23-Apr-09
24-Aug-09	24-Aug-09	24-Aug-09	24-Aug-09		24-Apr-09
25-Aug-09	25-Aug-09	25-Aug-09	25-Aug-09		25-Apr-09
26-Aug-09	26-Aug-09	26-Aug-09	26-Aug-09		26-Apr-09
27-Aug-09	27-Aug-09	27-Aug-09	27-Aug-09		27-Apr-09
28-Aug-09	28-Aug-09	28-Aug-09	28-Aug-09		28-Apr-09
29-Aug-09	29-Aug-09	29-Aug-09	29-Aug-09		29-Apr-09
30-Aug-09	30-Aug-09	30-Aug-09	30-Aug-09		30-Apr-09
31-Aug-09	31-Aug-09	31-Aug-09	31-Aug-09		1-May-09
1-Sep-09	1-Sep-09	1-Sep-09	1-Sep-09		2-May-09
2-Sep-09	2-Sep-09	2-Sep-09	2-Sep-09		3-May-09
3-Sep-09	3-Sep-09	3-Sep-09	3-Sep-09		4-May-09
4-Sep-09	4-Sep-09	4-Sep-09	4-Sep-09		5-May-09
5-Sep-09	5-Sep-09	5-Sep-09	5-Sep-09		6-May-09
6-Sep-09	6-Sep-09	6-Sep-09	6-Sep-09		7-May-09
7-Sep-09	7-Sep-09	7-Sep-09	7-Sep-09		8-May-09
8-Sep-09	8-Sep-09	8-Sep-09	8-Sep-09		9-May-09
9-Sep-09	9-Sep-09	9-Sep-09	9-Sep-09		10-May-09
10-Sep-09	10-Sep-09	10-Sep-09	10-Sep-09		11-May-09
11-Sep-09	11-Sep-09	11-Sep-09	11-Sep-09		12-May-09
12-Sep-09	12-Sep-09	12-Sep-09	12-Sep-09		13-May-09
13-Sep-09	13-Sep-09	13-Sep-09	13-Sep-09		14-May-09
14-Sep-09	14-Sep-09	14-Sep-09	14-Sep-09		15-May-09
15-Sep-09	15-Sep-09	15-Sep-09	15-Sep-09		16-May-09
16-Sep-09	16-Sep-09	16-Sep-09	16-Sep-09		17-May-09
17-Sep-09	17-Sep-09	17-Sep-09	17-Sep-09		18-May-09
18-Sep-09	18-Sep-09	18-Sep-09	18-Sep-09		19-May-09
19-Sep-09	19-Sep-09	19-Sep-09	19-Sep-09		20-May-09
20-Sep-09	20-Sep-09	20-Sep-09	20-Sep-09		21-May-09
21-Sep-09	21-Sep-09	21-Sep-09	21-Sep-09		22-May-09
22-Sep-09	22-Sep-09	22-Sep-09	22-Sep-09		23-May-09
23-Sep-09	23-Sep-09	23-Sep-09	23-Sep-09		24-May-09
24-Sep-09	24-Sep-09	24-Sep-09	24-Sep-09		25-May-09
25-Sep-09	25-Sep-09	25-Sep-09	25-Sep-09		26-May-09
26-Sep-09	26-Sep-09	26-Sep-09	26-Sep-09		27-May-09
27-Sep-09	27-Sep-09	27-Sep-09	27-Sep-09		28-May-09
28-Sep-09	28-Sep-09	28-Sep-09	28-Sep-09		29-May-09
29-Sep-09	29-Sep-09	29-Sep-09	29-Sep-09		30-May-09
30-Sep-09	30-Sep-09	30-Sep-09	30-Sep-09		31-May-09
1-Oct-09	1-Oct-09	1-Oct-09	1-Oct-09		1-Jun-09
2-Oct-09	2-Oct-09	2-Oct-09	2-Oct-09		2-Jun-09
3-Oct-09	3-Oct-09	3-Oct-09	3-Oct-09		3-Jun-09
4-Oct-09	4-Oct-09	4-Oct-09	4-Oct-09		4-Jun-09
5-Oct-09	5-Oct-09	5-Oct-09	5-Oct-09		5-Jun-09
6-Oct-09	6-Oct-09	6-Oct-09	6-Oct-09		6-Jun-09
7-Oct-09	7-Oct-09	7-Oct-09	7-Oct-09		7-Jun-09
8-Oct-09	8-Oct-09	8-Oct-09	8-Oct-09		8-Jun-09
9-Oct-09	9-Oct-09	9-Oct-09	9-Oct-09		9-Jun-09
10-Oct-09	10-Oct-09	10-Oct-09	10-Oct-09		10-Jun-09
11-Oct-09	11-Oct-09	11-Oct-09	11-Oct-09		11-Jun-09
12-Oct-09	12-Oct-09	12-Oct-09	12-Oct-09		12-Jun-09
13-Oct-09	13-Oct-09	13-Oct-09	13-Oct-09		13-Jun-09
14-Oct-09	14-Oct-09	14-Oct-09	14-Oct-09		14-Jun-09
15-Oct-09	15-Oct-09	15-Oct-09	15-Oct-09		15-Jun-09
16-Oct-09	16-Oct-09	16-Oct-09	16-Oct-09		16-Jun-09
17-Oct-09	17-Oct-09	17-Oct-09	17-Oct-09		17-Jun-09
18-Oct-09	18-Oct-09	18-Oct-09	18-Oct-09		18-Jun-09
19-Oct-09	19-Oct-09	19-Oct-09	19-Oct-09		19-Jun-09

20-Oct-09	20-Oct-09	20-Oct-09	20-Oct-09			20-Jun-09
21-Oct-09	21-Oct-09	21-Oct-09	21-Oct-09			21-Jun-09
22-Oct-09	22-Oct-09	22-Oct-09	22-Oct-09			22-Jun-09
23-Oct-09	23-Oct-09	23-Oct-09	23-Oct-09			23-Jun-09
24-Oct-09	24-Oct-09	24-Oct-09	24-Oct-09			24-Jun-09
25-Oct-09	25-Oct-09	25-Oct-09	25-Oct-09			25-Jun-09
26-Oct-09	26-Oct-09	26-Oct-09	26-Oct-09			26-Jun-09
27-Oct-09	27-Oct-09	27-Oct-09	27-Oct-09			27-Jun-09
28-Oct-09	28-Oct-09	28-Oct-09	28-Oct-09			28-Jun-09
29-Oct-09	29-Oct-09	29-Oct-09	29-Oct-09			29-Jun-09
30-Oct-09	30-Oct-09	30-Oct-09	30-Oct-09			30-Jun-09
31-Oct-09	31-Oct-09	31-Oct-09	31-Oct-09			1-Jul-09
1-Nov-09	1-Nov-09	1-Nov-09	1-Nov-09			2-Jul-09
2-Nov-09	2-Nov-09	2-Nov-09	2-Nov-09			3-Jul-09
3-Nov-09	3-Nov-09	3-Nov-09	3-Nov-09			4-Jul-09
4-Nov-09	4-Nov-09	4-Nov-09	4-Nov-09			5-Jul-09
5-Nov-09	5-Nov-09	5-Nov-09	5-Nov-09			6-Jul-09
6-Nov-09	6-Nov-09	6-Nov-09	6-Nov-09			7-Jul-09
7-Nov-09	7-Nov-09	7-Nov-09	7-Nov-09			8-Jul-09
8-Nov-09	8-Nov-09	8-Nov-09	8-Nov-09			9-Jul-09
9-Nov-09	9-Nov-09	9-Nov-09	9-Nov-09			10-Jul-09
10-Nov-09	10-Nov-09	10-Nov-09	10-Nov-09			11-Jul-09
11-Nov-09	11-Nov-09	11-Nov-09	11-Nov-09			12-Jul-09
12-Nov-09	12-Nov-09	12-Nov-09	12-Nov-09			13-Jul-09
13-Nov-09	13-Nov-09	13-Nov-09	13-Nov-09			14-Jul-09
14-Nov-09	14-Nov-09	14-Nov-09	14-Nov-09			15-Jul-09
15-Nov-09	15-Nov-09	15-Nov-09	15-Nov-09			16-Jul-09
16-Nov-09	16-Nov-09	16-Nov-09	16-Nov-09			17-Jul-09
17-Nov-09	17-Nov-09	17-Nov-09	17-Nov-09			18-Jul-09
18-Nov-09	18-Nov-09	18-Nov-09	18-Nov-09			19-Jul-09
19-Nov-09	19-Nov-09	19-Nov-09	19-Nov-09			20-Jul-09
20-Nov-09	20-Nov-09	20-Nov-09	20-Nov-09			21-Jul-09
21-Nov-09	21-Nov-09	21-Nov-09	21-Nov-09			22-Jul-09
22-Nov-09	22-Nov-09	22-Nov-09	22-Nov-09			23-Jul-09
23-Nov-09	23-Nov-09	23-Nov-09	23-Nov-09			24-Jul-09
24-Nov-09	24-Nov-09	24-Nov-09	24-Nov-09			25-Jul-09
25-Nov-09	25-Nov-09	25-Nov-09	25-Nov-09			26-Jul-09
26-Nov-09	26-Nov-09	26-Nov-09	26-Nov-09			27-Jul-09
27-Nov-09	27-Nov-09	27-Nov-09	27-Nov-09			28-Jul-09
28-Nov-09	28-Nov-09	28-Nov-09	28-Nov-09			29-Jul-09
29-Nov-09	29-Nov-09	29-Nov-09	29-Nov-09			30-Jul-09
30-Nov-09	30-Nov-09	30-Nov-09	30-Nov-09			31-Jul-09
1-Dec-09	1-Dec-09	1-Dec-09	1-Dec-09			1-Aug-09
2-Dec-09	2-Dec-09	2-Dec-09	2-Dec-09			2-Aug-09
3-Dec-09	3-Dec-09	3-Dec-09	3-Dec-09			3-Aug-09
4-Dec-09	4-Dec-09	4-Dec-09	4-Dec-09			4-Aug-09
5-Dec-09	5-Dec-09	5-Dec-09	5-Dec-09			5-Aug-09
6-Dec-09	6-Dec-09	6-Dec-09	6-Dec-09			6-Aug-09
7-Dec-09	7-Dec-09	7-Dec-09	7-Dec-09			7-Aug-09
8-Dec-09	8-Dec-09	8-Dec-09	8-Dec-09			8-Aug-09
9-Dec-09	9-Dec-09	9-Dec-09	9-Dec-09			9-Aug-09
10-Dec-09	10-Dec-09	10-Dec-09	10-Dec-09			10-Aug-09
11-Dec-09	11-Dec-09	11-Dec-09	11-Dec-09			11-Aug-09
12-Dec-09	12-Dec-09	12-Dec-09	12-Dec-09			12-Aug-09
13-Dec-09	13-Dec-09	13-Dec-09	13-Dec-09			13-Aug-09
14-Dec-09	14-Dec-09	14-Dec-09	14-Dec-09			14-Aug-09
15-Dec-09	15-Dec-09	15-Dec-09	15-Dec-09			15-Aug-09
16-Dec-09	16-Dec-09	16-Dec-09	16-Dec-09			16-Aug-09
17-Dec-09	17-Dec-09	17-Dec-09	17-Dec-09			17-Aug-09
18-Dec-09	18-Dec-09	18-Dec-09	18-Dec-09			18-Aug-09
19-Dec-09	19-Dec-09	19-Dec-09	19-Dec-09			19-Aug-09
20-Dec-09	20-Dec-09	20-Dec-09	20-Dec-09			20-Aug-09
21-Dec-09	21-Dec-09	21-Dec-09	21-Dec-09			21-Aug-09
22-Dec-09	22-Dec-09	22-Dec-09	22-Dec-09			22-Aug-09
23-Dec-09	23-Dec-09	23-Dec-09	23-Dec-09			23-Aug-09
24-Dec-09	24-Dec-09	24-Dec-09	24-Dec-09			24-Aug-09
25-Dec-09	25-Dec-09	25-Dec-09	25-Dec-09			25-Aug-09
26-Dec-09	26-Dec-09	26-Dec-09	26-Dec-09			26-Aug-09
27-Dec-09	27-Dec-09	27-Dec-09	27-Dec-09			27-Aug-09
28-Dec-09	28-Dec-09	28-Dec-09	28-Dec-09			28-Aug-09
29-Dec-09	29-Dec-09	29-Dec-09	29-Dec-09			29-Aug-09
30-Dec-09	30-Dec-09	30-Dec-09	30-Dec-09			30-Aug-09
31-Dec-09	31-Dec-09	31-Dec-09	31-Dec-09			31-Aug-09
1-Jan-10	1-Jan-10	1-Jan-10	1-Jan-10			1-Sep-09
2-Jan-10	2-Jan-10	2-Jan-10	2-Jan-10			2-Sep-09

3-Jan-10	3-Jan-10	3-Jan-10	3-Jan-10			3-Sep-09
4-Jan-10	4-Jan-10	4-Jan-10	4-Jan-10			4-Sep-09
5-Jan-10	5-Jan-10	5-Jan-10	5-Jan-10			5-Sep-09
6-Jan-10	6-Jan-10	6-Jan-10	6-Jan-10			6-Sep-09
7-Jan-10	7-Jan-10	7-Jan-10	7-Jan-10			7-Sep-09
8-Jan-10	8-Jan-10	8-Jan-10	8-Jan-10			8-Sep-09
9-Jan-10	9-Jan-10	9-Jan-10	9-Jan-10			9-Sep-09
10-Jan-10	10-Jan-10	10-Jan-10	10-Jan-10			10-Sep-09
11-Jan-10	11-Jan-10	11-Jan-10	11-Jan-10			11-Sep-09
12-Jan-10	12-Jan-10	12-Jan-10	12-Jan-10			12-Sep-09
13-Jan-10	13-Jan-10	13-Jan-10	13-Jan-10			13-Sep-09
14-Jan-10	14-Jan-10	14-Jan-10	14-Jan-10			14-Sep-09
15-Jan-10	15-Jan-10	15-Jan-10	15-Jan-10			15-Sep-09
16-Jan-10	16-Jan-10	16-Jan-10	16-Jan-10			16-Sep-09
17-Jan-10	17-Jan-10	17-Jan-10	17-Jan-10			17-Sep-09
18-Jan-10	18-Jan-10	18-Jan-10	18-Jan-10			18-Sep-09
19-Jan-10	19-Jan-10	19-Jan-10	19-Jan-10			19-Sep-09
20-Jan-10	20-Jan-10	20-Jan-10	20-Jan-10			20-Sep-09
21-Jan-10	21-Jan-10	21-Jan-10	21-Jan-10			21-Sep-09
22-Jan-10	22-Jan-10	22-Jan-10	22-Jan-10			22-Sep-09
23-Jan-10	23-Jan-10	23-Jan-10	23-Jan-10			23-Sep-09
24-Jan-10	24-Jan-10	24-Jan-10	24-Jan-10			24-Sep-09
25-Jan-10	25-Jan-10	25-Jan-10	25-Jan-10			25-Sep-09
26-Jan-10	26-Jan-10	26-Jan-10	26-Jan-10			26-Sep-09
27-Jan-10	27-Jan-10	27-Jan-10	27-Jan-10			27-Sep-09
28-Jan-10	28-Jan-10	28-Jan-10	28-Jan-10			28-Sep-09
29-Jan-10	29-Jan-10	29-Jan-10	29-Jan-10			29-Sep-09
30-Jan-10	30-Jan-10	30-Jan-10	30-Jan-10			30-Sep-09
31-Jan-10	31-Jan-10	31-Jan-10	31-Jan-10			1-Oct-09
1-Feb-10	1-Feb-10	1-Feb-10	1-Feb-10			2-Oct-09
2-Feb-10	2-Feb-10	2-Feb-10	2-Feb-10			3-Oct-09
3-Feb-10	3-Feb-10	3-Feb-10	3-Feb-10			4-Oct-09
4-Feb-10	4-Feb-10	4-Feb-10	4-Feb-10			5-Oct-09
5-Feb-10	5-Feb-10	5-Feb-10	5-Feb-10			6-Oct-09
6-Feb-10	6-Feb-10	6-Feb-10	6-Feb-10			7-Oct-09
7-Feb-10	7-Feb-10	7-Feb-10	7-Feb-10			8-Oct-09
8-Feb-10	8-Feb-10	8-Feb-10	8-Feb-10			9-Oct-09
9-Feb-10	9-Feb-10	9-Feb-10	9-Feb-10			10-Oct-09
10-Feb-10	10-Feb-10	10-Feb-10	10-Feb-10			11-Oct-09
11-Feb-10	11-Feb-10	11-Feb-10	11-Feb-10			12-Oct-09
12-Feb-10	12-Feb-10	12-Feb-10	12-Feb-10			13-Oct-09
13-Feb-10	13-Feb-10	13-Feb-10	13-Feb-10			14-Oct-09
14-Feb-10	14-Feb-10	14-Feb-10	14-Feb-10			15-Oct-09
15-Feb-10	15-Feb-10	15-Feb-10	15-Feb-10			16-Oct-09
16-Feb-10	16-Feb-10	16-Feb-10	16-Feb-10			17-Oct-09
17-Feb-10	17-Feb-10	17-Feb-10	17-Feb-10			18-Oct-09
18-Feb-10	18-Feb-10	18-Feb-10	18-Feb-10			19-Oct-09
19-Feb-10	19-Feb-10	19-Feb-10	19-Feb-10			20-Oct-09
20-Feb-10	20-Feb-10	20-Feb-10	20-Feb-10			21-Oct-09
21-Feb-10	21-Feb-10	21-Feb-10	21-Feb-10			22-Oct-09
22-Feb-10	22-Feb-10	22-Feb-10	22-Feb-10			23-Oct-09
23-Feb-10	23-Feb-10	23-Feb-10	23-Feb-10			24-Oct-09
24-Feb-10	24-Feb-10	24-Feb-10	24-Feb-10			25-Oct-09
25-Feb-10	25-Feb-10	25-Feb-10	25-Feb-10			26-Oct-09
26-Feb-10	26-Feb-10	26-Feb-10	26-Feb-10			27-Oct-09
27-Feb-10	27-Feb-10	27-Feb-10	27-Feb-10			28-Oct-09
28-Feb-10	28-Feb-10	28-Feb-10	28-Feb-10			29-Oct-09
1-Mar-10	1-Mar-10	1-Mar-10	1-Mar-10			30-Oct-09
2-Mar-10	2-Mar-10	2-Mar-10	2-Mar-10			
3-Mar-10	3-Mar-10	3-Mar-10	3-Mar-10			
4-Mar-10	4-Mar-10	4-Mar-10	4-Mar-10			
5-Mar-10	5-Mar-10	5-Mar-10	5-Mar-10			
6-Mar-10	6-Mar-10	6-Mar-10	6-Mar-10			
7-Mar-10	7-Mar-10	7-Mar-10	7-Mar-10			
8-Mar-10	8-Mar-10	8-Mar-10	8-Mar-10			
9-Mar-10	9-Mar-10	9-Mar-10	9-Mar-10			
10-Mar-10	10-Mar-10	10-Mar-10	10-Mar-10			
11-Mar-10	11-Mar-10	11-Mar-10	11-Mar-10			
12-Mar-10	12-Mar-10	12-Mar-10	12-Mar-10			
13-Mar-10	13-Mar-10	13-Mar-10	13-Mar-10			
14-Mar-10	14-Mar-10	14-Mar-10	14-Mar-10			
15-Mar-10	15-Mar-10	15-Mar-10	15-Mar-10			
16-Mar-10	16-Mar-10	16-Mar-10	16-Mar-10			
17-Mar-10	17-Mar-10	17-Mar-10	17-Mar-10			
18-Mar-10	18-Mar-10	18-Mar-10	18-Mar-10			

19-Mar-10	19-Mar-10	19-Mar-10	19-Mar-10
20-Mar-10	20-Mar-10	20-Mar-10	20-Mar-10
21-Mar-10	21-Mar-10	21-Mar-10	21-Mar-10
22-Mar-10	22-Mar-10	22-Mar-10	22-Mar-10
23-Mar-10	23-Mar-10	23-Mar-10	23-Mar-10
24-Mar-10	24-Mar-10	24-Mar-10	24-Mar-10
25-Mar-10	25-Mar-10	25-Mar-10	25-Mar-10
26-Mar-10	26-Mar-10	26-Mar-10	26-Mar-10
27-Mar-10	27-Mar-10	27-Mar-10	27-Mar-10
28-Mar-10	28-Mar-10	28-Mar-10	28-Mar-10
29-Mar-10	29-Mar-10	29-Mar-10	29-Mar-10
30-Mar-10	30-Mar-10	30-Mar-10	30-Mar-10
31-Mar-10	31-Mar-10	31-Mar-10	31-Mar-10



Check  
Motor  
PCB  
solder  
Joints

✓
✓
FAIL
✓

---

**From:** Anthony Fleenor <Anthony.Fleenor@TRW.COM>  
**Sent:** Monday, April 02, 2012 9:58 AM  
**To:** Surella, Matthew (M.M.)  
**Cc:** Estes, Eric (E.E.); Napoli, Laura (L.); Andy Partridge; Salim Semssar  
**Subject:** B9A Mileage for U502

Matt,

Looking in AWS for C200D (B9A) I see an average mileage of 7,932.

Minimum of 1,695  
Maximum of 25,878

76% are under 10,000 but that may just be due to the "newness" of the vehicle line and not many have reached higher miles.


I have all the claims in a file so if you think of other information you need just let me know.

Tony Fleenor  
TRW Steering Warranty  
423-272-4221

---

**From:** Estes, Eric (E.E.)  
**Sent:** Wednesday, December 07, 2011 1:08 PM  
**To:** Napoli, Laura (L.)  
**Cc:** Surella, Matthew (M.M.)  
**Subject:** B9A root cause /ribbon cable dates list

Have added updated ribbon cable dates and some new root cause analysis.



*Eric J Estes*

TRW EPAS Steering Systems  
Quality Specialist  
Hotline ph# 313-317-9358  
Cell ph# [REDACTED]

Case Number	U502 B9A EPP s/n	Motor Build date	Ribbon Cable Date	Root Cause	Location	still need analysis	other codes set
UR0030	102881920F30188	2010-09-17		torn down	motors grp-UK		
UR0045	110291919G30475	2010-12-27		under analysis	UK?	X	
UR0047	110441920G30308	2010-12-28		torn down	Tyco		
UR0048	103601919G30367	2010-12-04		conformal coat	Nidec		
UR0058	110271919G31290	2010-12-28		under analysis	motors grp-UK	X	
UR0059	110291919G31227	2010-12-28	2010-11-15	misalignment	Tyco		
UR0060	110771919J30898	2011-01-25	2010-11-16	misalignment	Tyco		
UR0061	110291919G30593	2010-12-27	2010-11-16	conformal coat	UK		
UR0062	110291919G30862	2010-12-28	2010-11-17	conformal coat	UK		
UR0063	103631920G30133	2010-12-06	2010-10-25	conformal coat	UK		
UR0064	110261919G30786	2010-12-24	2010-11-17	misalignment	Tyco		
UR0065	103591919G30091	2010-12-24	2010-10-12	conformal coat	UK		
UR0066	103171919F30938	2010-10-27		under analysis	Micronis to UK?	X	
UR0067	110151919G31298	2010-12-13		under analysis	Micronis to UK?	X	
UR0068	110151919G30515	2010-12-23		under analysis	Micronis to UK?	X	
UR0069	103031919F30506	2010-10-07		under analysis	Micronis to UK?	X	
UR0070	110281919G30095	2010-12-28	2010-11-26	misalignment	UK		
UR0071	110621919J30710	2011-01-20	2010-12-02	conformal coat	MAO		
UR0073	110761919J31074	2011-01-24		conformal coat	MAO		
UR0075	110451919G30577	2010-12-30	2010-11-16	conformal coat	MAO		
UR0076	110291919G30300	2010-12-27	2010-11-16	misalignment	MAO		
UR0077	110071919G30749	2010-12-24	2010-11-16	conformal coat	MAO		
UR0079	110481919G30125	2010-12-30	2010-11-16	misalignment	MAO		
UR0080	110491919J30546	2010-12-30		conformal coat	MAO		
UR0081	110151919G30544	2010-12-23	2010-11-08	conformal coat	MAO		
UR0082	110071919G30887	2010-12-24	2010-11-08	conformal coat	MAO		
UR0083	103181919F31151	2010-10-27	2010-09-13	conformal coat	MAO		
UR0084	103601919G30305	2010-12-04		conformal coat	MAO		
UR0085	103381919G30931	2010-11-08		conformal coat	MAO		
UR0086	110631920J30819	2011-01-03	2010-11-16	conformal coat	MAO		
UR0087	110291919G30215	2011-12-27	2010-11-16	misalignment	MAO		
UR0088	103521919G31407	2010-11-11	2010-09-07	conformal coat	MAO		
UR0089	110141919G30775	2011-12-23	2010-11-08	conformal coat	MAO		
UR0092	103561919G30991	2010-11-12		conformal coat	MAO		
UR0095	110271919G30664	2010-12-25	2010-11-15	misalignment	MAO		

cannot test

cannot test

UR0096	110631919J30050	2011-01-20		remove from vehicle	Gary Smith in-vehicle test		B92
UR0098	103521919G31407	2010-11-11		conformal coat	MAO		
UR0099	103451919G30811	2010-11-10	2010-09-07	conformal coat	MAO		
UR0100	110901919J35745	2011-02-12	2010-12-14	conformal coat	MAO		
UR0101	110761919J30756	2011-01-24	2010-12-06	conformal coat	MAO		
UR0103	110281919G31045	2011-12-27		under analysis	MAO	X	
UR0104	110151919G30511	2011-12-23		conformal coat	MAO		
UR0105	110421919G30598	2011-12-29	2010-11-17	conformal coat	MAO		
UR0108	110081919G30406	2011-12-24	2010-11-08	conformal coat	MAO		
UR0109	103031919F30809	2010-10-25	2010-09-02	conformal coat	MAO		
UR0111	110151919G30342	2010-12-23	2010-11-08	conformal coat	MAO		
UR0113	110161919G30045	2011-12-23		conformal coat	MAO		
UR0114	110261919G30136	2010-12-27		conformal coat	MAO		
UR0115	110291919G30096	2010-12-27		conformal coat	MAO		
UR0116	103381919G30367	2010-10-27		remove from vehicle	Matt Surella's in-vehicle test		
UR0117	110281919G30762	2011-12-28	2010-11-15	misalignment	MAO		BD0-BD3
UR0118	110671920J30011	2011-01-02		under analysis	Allegro	X	
UR0119	110071919G30999	2010-12-24		under analysis	Allegro	X	
UR0120	110911919J35411	2011-02-15	2010-12-21	misalignment	MAO		
UR0123	111051919J35133	2011-03-14		under analysis	Allegro	X	
UR0124	110901919J36048	2011-02-14		under analysis	Allegro	X	

31- con coat  
10- misalignment  
11- under analysis  
2- torn down  
2-in-vehicle

Case Number	CD3 B9A EPP s/n	Motor Build date	Ribbon Cable Date	root cause	Location	Still need analysis	other codes set
FR-0493	102792002C30419	2010-10-14	2010-09-02	conformal coat	UK		
FR-0496	102792002C30419			regulator PU	QAO		
FR-0512	110662002D35100	2011-02-09		hall effect	Micronas		
FR-0518	110242002D30163	2010-12-22	2010-11-16	misalignment	QAO		
FR-0525	103062002D30239	2010-10-15		conformal coat	QAO		
FR-0532	103062002D31029	2010-10-14		conformal coat	UK		
FR-0533	111022002D35025	2011-03-17		under analysis	QAO	X	NO B9A(B38,B4E)
FR-0534	110322002D35261	2011-01-08		under analysis	UK		lost EPP
FR-0535	102912002C30375	2010-09-24	2010-08-30	conformal coat	QAO		
FR-0536	103152002D31020	2010-10-16		conformal coat	UK		
FR-0537	110252002D30179	2011-01-04	2010-11-22	misalignment	Tyco		
FR-0538	110232002D30097	2010-12-20		under analysis	UK	X	Find Gear
FR-0539	103482002D30282	2010-11-23	2010-10-10	conformal coat	QAO		
FR-0543	103072002D30992	2010-10-14		conformal coat	26mile		
FR-0544	102472002B30653	2010-08-19		conformal coat	26mile		
FR-0545	103212002D30532	2010-10-17		conformal coat	26mile		
FR-0546	103412002D30674	2010-11-04	2010-09-16	conformal coat	QAO		
FR-0547	110672002D30526	2011-02-09	2010-12-13	misalignment	QAO		
FR-0548	103192002D30082	2010-10-15	2010-09-05	conformal coat	QAO		
FR-0549	103192002D30791	2010-10-15	2010-09-03	conformal coat	QAO		
FR0552	103052002D30193	2010-10-13	2010-09-01	conformal coat	QAO		
FR0553	111292002D36263	2011-04-10	2010-09-01	conformal coat	26mile		2012 m/y
FR0567	111612002D31167	2011-05-23			in eval QAO	X	2012 m/y

14- Con. Coat  
3- misalignment  
1- hall effect  
1- Reg. power up  
4-under analysis

Case Number	C346 B9A EPP s/n	Motor Build date	Ribbon Cable Date	Root Cause	location
CR0075	110761923D36352	2011-02-20		misalignment	in process MAO
CR0088	110061923D35205	2010-11-18		conformal coat-testing at Tyco	in eval Tyco
CR0093	110551923D35104	2011-01-25	2010-11-29	misalignment	26mile
CR0112	110141923D35643	2010-11-19	2010-09-29	misalignment	MAO
CR0136	110571923D35913	2011-02-09		misalignment	UK
C1-Europe				misalignment	Tyco
0km CL180760			2010-10-12	misalignment	MAO

Laura's vehicle test

was CR0090 has duplicate so I changed the CR#

5-misalignment  
1- con coat  
1- under analysis


UR0045

	Time to failure
Warranty Unit - 1	128
Warranty Unit - 2	72
Warranty Unit - 3	78
Warranty Unit - 4	104
Warranty Unit - 5	106
Golden Unit - 1	60
Golden Unit - 2	60
Golden Unit - 3	81
Golden Unit - 4	78
Golden Unit - 5	60

	Warranty Unit - 1	Warranty Unit - 2	Warranty Unit - 3	Warranty Unit - 4	Warranty Unit - 5	Golden Unit - 1	Golden Unit - 2	Golden Unit - 3	Golden Unit - 4	Golden Unit - 5
Time to failure	128	72	78	104	106	60	60	81	78	60




Time to failure



---

**From:** Pienta, Alan (A.)  
**Sent:** Wednesday, November 02, 2011 9:41 AM  
**To:** Rossi, Roberto (R.A.)  
**Subject:** B9a trace  
**Attachments:** b9a failure.doc



---

**From:** Anderson, Eric (H.)  
**Sent:** Thursday, March 24, 2011 11:05 AM  
**To:** Napoli, Laura (L.)  
**Subject:** BGA27421 power steering inop

Hi Laura:

FYI. Steering failed right after customer took delivery, of course. This is #8 for EPAS inop in general and #4 for U\*\*\*\* codes. The build date is still within our BSAQ dates. The gear has been requested and will go to TRW in Washington, MI. Have TRW, Tyco or Dudoco reported a confident clean date? Are they building with the new software you mentioned?

Thanks,

Eric Anderson  
PVT Engineer  
Ford Chicago Assembly  
773.646.7236 desk  
773.729.0337 cell  
[eande181@ford.com](mailto:eande181@ford.com)

Server: **AWS Prod**  
Claims loaded through: **23-MAR-2011**

## Claim Detail Report

*Note: All costs are in US dollars*

**Model Year** = 2011; **Claim Key** = 308468

### Vehicle Information

Model Year: 2011

Market Derived: F - FORD

Body/Cab Type: T/WD - 4 DOOR WAGON

Version/Series: T/EF-FORD SERIES

Drive Type: T/F-4 WHL L/H FULL TIME  
DRIVE

Vehicle Line: T/UB-EXPLORER [11-12]

Warranty Start Date: 08-MAR-11

Production Date: 16-FEB-11

VIN: 1FMHK8F85BG [REDACTED]

### Claim Information

Document Number: 234129A

Repair Date: 09-MAR-11

Distance: 115

TIS: 1

**Expense Information**

**Dealer Information:**

Dealer Name CREST FORD FLAT ROCK,  
INC.

Dealer Code: 00807 - \*

Address: 22675 GIBRALTAR RD

City: FLAT ROCK

State: MI Zip Code: 48134

Country: USA Region Code: NA

Phone: (734)782-2400

Customer Paid Amount: .00

Deductible Amount: .00

Dealer Paid Amount: .00

Labor Cost: 340.62

Misc. Expense Amount: .00

Part Markup Amount: 293.04

Material Cost: 1025.64

Total Cost Gross: 1366.26

Cust.

Concern N58 - STEERING NOISY

Code:

Condition 42 - DOES NOT OPERATE PROPERLY  
Code:

Technician PERFORM EPAS DIAG AQUIRED DTC U3000:69, PERFORM DRIVE  
nCYCLE,PERFORM PINPOINT TESTS, MT MECHANICAL TIME NECESSARY  
Comment: TO REPLACE EPAS STEERING GEAR, PERFORM PMI, CK ALIGNMENT  
AND SET TOE

Customer PWR STEERING HAS NO PWR ASSIST MESSAGE CENTER READS PWR  
Comment: STEERING FAULT INSP AND ADV

<u>Labor Op Code</u>	<u>Labor Op Description</u>	<u>Labor Op Cost</u>
3504E		17.93
3504E8		8.96
3504E45		26.89
3504E46		8.96
3001A1	CASTER, CAMBER AND TOE-IN CORRECT	53.78
MT3504		224.10

<b>Causal</b>	<b>Full Part Number</b>			<b>Part</b>	<b>Part</b>	<b>Extended</b>	
<u>Flag</u>	<u>PREF</u>	<u>BASE</u>	<u>SUFF</u>	<u>Description</u>	<u>CPSC</u>	<u>Quantity</u>	<u>Amount</u>
Y	BB5Z	3504	CE	GEAR ASY-STEERING	110101	1	1025.64

DTC Sections:

Mil. Light On =\*

<u>Flag</u>	<u>Test</u>	<u>Malfunction Cd</u>	<u>Malfunction Cd</u>	<u>Monitor</u>	<u>Monitor Cd</u>
<u>g</u>	<u>Type</u>		<u>Description</u>	<u>Cd</u>	<u>Description</u>

Any comments? You can contact

[webmaster](mailto:webmaster)

815

---

**From:** Anderson, Eric (H.)  
**Sent:** Tuesday, June 21, 2011 12:52 PM  
**To:** Napoli, Laura (L.); Estes, Eric (E.E.); Mrozek, Robert (R.M.)  
**Subject:** CQIS Report BFTAQ006

Hi Laura, Eric and Rob:

Check out this CQIS. It's got the same code as the car that's gone through two gears here in the plant. U3000:96-C8. Could the gear get too much current and be damaged by a faulty electrical system?

**Attachments :** 0

**Report# :** BFTAQ006 NHL **Received:** 06/20/2011

**CCRG/EPRC:** **Reviewed Status:** **Date:**

**Vehicle:** 2011,EXPLORER 4X2 (U502),4 DOOR **Build Date:** 05/10/2011  
,MP,1FMHK7F87BGA66103

**Odometer :** 1,410 M **Engine:** 3.5L CYCLO **Calibration**  
:

**Transmission:** 6F50 **Axle:** **A/C:** YES

**Dealer:** USA 04927 J.C. Lewis Ford **Phone#:** (912) 925-2678

**City:** Savannah **State:** Georgia **Country :** USA

**Originator:** AARON MOORE

**Symptom:** 3 03 1 55 CHASS.,STRG/HANDLING ,FUNCTION,LOSS OF STRG

**Status:**

**VFG:** V89 RIDE & HANDLING

**Additional Symptom:** U3000:96

**Fix:** **Causal Component :** --

**Condition Code:**

**Hotliner:** CBISHO41 **Phone:** 313 317-9359 **Regn Cd:** S1 Atlanta

**Engineering:** **Phone:** **TAR:**

**Dlr Contact:** AARON MOORE **Phone:** 000 000-0000 **Title Cde:** T

**DTCs:**

KOEO:

KOEC:

KOER:

**Comments :**

REPAIR 06/20/2011 09:27AM CHRIS BISHOP MSS - FCSD - TECH SVC HOTLINE

WEB FORM DATA - CONCERN: POWER STEERING IS INOP NO POWER STEERING AND

SERVICE ADVANCE TRACK AND POWER ASST FAULT LIGHTS ON AND ABS LIGHT ON

AT ALL TIMES DIAGNOSTICS: PERFORMED PINPOINT FOR CODES U3000:96-C8

PSCM U3000:96-C8 PARTS REPLACED.: NONE TECH QUESTION: PINPOINT

SAYS TO REPLACE PSCM RACK GEAR ASSY MOD. PINPOINT TEST C-1.HAS THERE

BEEN ANY OTHER CONCERNS ON THIS OR SSMS TSBS OR HAS THE REPLACEMENT OF

THE PSCM. WERE YOU ABLE TO VERIFY THE CONCERN? YES IS THERE AN

APPROPRIATE PINPOINT TEST IN THE WSM FOR THIS CONCERN? YES WAS THE

PINPOINT TEST FOLLOWED? YES

**RECOMM 06/20/2011 09:27AM CHRIS BISHOP MSS - FCSD - TECH SVC HOTLINE**

IF THE U3000:96 DTC IS RETURNING AS A CMDTC AFTER BEING CLEARED, THE

EPAS SHOULD BE REPLACED. PLEASE VERIFY THAT THERE ARE NO POWER OR

GROUND ISSUES TO THE EPAS MODULE. RECOMMEND LOAD TESTING POWER/GROUND

IN ADDITION TO INSPECTING THE CONNECTOR TERMINALS (PINS)



AND VERIFY

THERE ARE NO FIT CONCERNS AT THE EPAS MODEL. IF THIS IS OK,  
REPLACE

THE EPAS.

Eric Anderson  
PVT Engineer  
Ford Chicago Assembly  
773.646.7236 desk  
773.729.0337 cell  
[eande181@ford.com](mailto:eande181@ford.com)

---

**From:** Napoli, Laura (L.)  
**Sent:** Monday, March 07, 2011 3:06 PM  
**To:** Michael Fontana; 'Simon Malsbury'; 'Geoff Jacks'; Andy Partridge; Robert Kostadina; Nick turovich; 'Greg Austin'; 'Gregory Sheets'; 'Phil Browne'  
**Cc:** Mrozek, Robert (R.M.); Snider, Tim (T.O.); Diez, Timothy (T.P.); Kingstrom, Mark (M.D.); Bahena, Miguel (Mike.)  
**Subject:** Data on Management Lease B3A Vehicle  
**Importance:** High  
**Attachments:** BG [REDACTED]\_Taras.ppt; BG [REDACTED]\_Taras.PAR

Team,

We have another B3A on a U502 management lease car. This one happened on Friday and I pulled the data out of the vehicle in Dearborn this afternoon. Driver lost assist one time on Friday morning. They will be taking their vehicle in for a gear swap in the management garage. Eric Estes will expedite the replacement and pickup of this gear to get it to 26mi as soon as possible.

Attached is the data. A few points...

1. VIN is BG [REDACTED] Eric, please send ECU and EPP serial numbers so we can get relay build date ASAP.
2. This vehicle had 36 E66's present in the LIC data. There was only one that lead to a B3A.
3. I don't want any more contacts built at Doduco until an ICA is in place!



BG [REDACTED]\_Taras.ppt BG [REDACTED]\_Taras.PAR

Regards,

*Laura Napoli*

U502 EPAS  
Ford Motor Company  
Cube: 2B-G66 PDC  
Phone: 313.323.0634  
Mobile: 313.805.0482

BG

3/7/2011

1: Fault Store Data    2: LICS    3: SafetMicro    4: Maintainece Data    5: Control Pannel    6: Part Numbers/Traceability    7: Calibration Data    8: CAN Signals

[1] A Co...  
02h 21 N/A 326313  
02h 0 N/A 693625  
02h 255 N/A 781209  
02h 3 N/A 6729  
02h 35 N/A 3905  
02h 0 N/A 104849  
02h 46 N/A 196073  
02h 0 N/A 234385

[2] A Jo...  
21 N/A 326313  
0 N/A 693625  
255 N/A 781209  
3 N/A 6729  
35 N/A 3905  
0 N/A 104849  
46 N/A 196073  
0 N/A 234385

[3] A Times...  
326313  
693625  
781209  
6729  
3905  
104849  
196073  
234385

[4] Level A Fault Store  
TRW\_FaultStore.itsFaultStores.[0].Las 2 N/A  
TRW\_FaultStore.itsFaultStores.[0].Nun 10 N/A

[7] BC C...  
02h 0 N/A 693625  
02h 255 N/A 781209  
3Ah 27 N/A 19333  
02h 35 N/A 3905  
02h 0 N/A 104849  
02h 46 N/A 196073  
02h 0 N/A 234385  
02h 21 N/A 326313

[6] BC J...  
0 N/A 693625  
255 N/A 781209  
27 N/A 19333  
35 N/A 3905  
0 N/A 104849  
46 N/A 196073  
0 N/A 234385  
21 N/A 326313

[8] BC Time...  
693625  
781209  
19333  
3905  
104849  
196073  
234385  
326313

[5] Level BC Fault Store  
TRW\_FaultStore.itsFaultStores.[1].Las 2 N/A  
TRW\_FaultStore.itsFaultStores.[1].Nun 10 N/A

[9] E Co...  
66h 3 N/A 580  
66h 1 N/A 582  
66h 1 N/A 587  
66h 7 N/A 584  
66h 1 N/A 586  
66h 3 N/A 579  
66h 0 N/A 582  
12h 1 N/A 32260

[10] E J...  
3 N/A 580  
1 N/A 582  
1 N/A 587  
7 N/A 584  
1 N/A 586  
3 N/A 579  
0 N/A 582  
1 N/A 32260

[11] E Time...  
580  
582  
587  
584  
586  
579  
582  
32260

[12] Level E Fault Store  
TRW\_FaultStore.itsFaultStores.[2].Las 0 N/A  
TRW\_FaultStore.itsFaultStores.[2].Nur 64 N/A

[14] Numeric  
sSystemMode.rootState\_a NormalOperation N/A  
EcuM.rootState\_active MotorDriveOn N/A  
VehicleTuneID\_NVV VEHICLE\_TUNE\_3 N/A  
MotorTuneID\_NVV MOTOR\_TUNE\_2 N/A  
BuildVersion FNU5-B2-AMBBB

1	0
0	00h
1	00h
2	24h
3	00h
4	3Ah
5	0Bh
6	01h
7	00h
8	03h
9	01h
10	03h
11	01h
12	ECh
13	00h
14	96h
15	2Ch
16	1Ah
17	00h
18	94h
19	77h
20	03h
21	00h
22	D7h
23	21h
24	00h
25	00h
26	6Ah

# LICS—36 E66!

A0D.PSU_STUCK_ON_FAULT.I	0	▽	AA8.PULL_DRIFT_COMPEI	0	▽	B23.BOTTOM_FET_OPEN_CIRCUIT	0	▽	B92.INTEG_CHECK_MOTOR_VE	0	▽	BEE.MOTOR_TUNE_DATA_CRC_FAI	0
A0E.CAN_ENGINE_SPEED_INV	0	▽	AB0.CAN_HEV_READY_AB	0	▽	B24.TOP_FET_THREE_OPEN_CIRCI	0	▽	B93.INTEG_CHECK_RSP_FAULT	0	▽	BEF.DEV_TUNE_DATA_CRC_FAULT.	0
A0F.CAN_HARDWARE_NOT_R	0	▽	AB1.HFAC_SPD_GRADIENT	0	▽	B25.LNK_CAP_CHARGING_TOO_SI	0	▽	B95.INTEG_CHECK_TORQUE_E!	0	▽	BFA.TUNE_COMPATIBILITY_FAULT.I	0
A11.CAN_BUS_ERROR_FAULT	0	▽	AB2.HFAC_TRQ_GRADIENT	0	▽	B31.LINK_RELAY_SHORT_CIRCUIT	0	▽	B97.INTEG_CHECK_CURRENT_C	0	▽	BFC.EEPROM_INCOMPATIBLE_FAI	0
A12.CAN_CHARGING_SYSTEM	0	▽	AB3.HFAC_SPD_OUT_OF	0	▽	B32.LINK_VOLTAGE_WILL_NOT_S	0	▽	B9A.HALL_ENCODER_REFEREN	0	▽	BFD.HARDWARE_INCOMPATIBLE_F.	0
A13.CAN_CHR_SYS_STUCK_F	0	▽	AB4.HFAC_TRQ_OUT_OF	0	▽	B38.MOTOR_POSITION_SENSOR_I	0	▽	B9B.I_SENSE_STATIC_ZERO_O	0	▽	C41.MON_TRIP_LATCH_NOT_HOLD	0
A14.CAN_STR_WHL_OFST_S	0	▽	ABC.HFAC_GAIN_BELOW	0	▽	B39.UNABLE_TO_READ_HALL_ST/	0	▽	B9E.LOAD_DUMP_TIMEOUT_EX	0	▽	C69.LEVEL_B_LATCHED_FAULT.LIC	1
A15.CAN_VEHICLE_SPEED_IN	0	▽	AE5.CAN_VEH_SPD_STUC	0	▽	B3A.MOTOR_STAR_POINT_VOLTA	19	▽	B9F.INTEG_CHECK_MONITOR_E	0	▽	CFE.EOLT_EPS_OUT_OF_SPEC_FAI	0
A16.CAN_MUTE_FAULT.LIC	0	▽	AE6.CAN_ENG_SPD_STUC	0	▽	B40.MON_PASSIVE_CTRL_TIMEOU	0	▽	BA4.SAFETY_CIRCUIT_TRIPPED	0	▽	CFE.EOLT_EPS_OUT_OF_SPEC_FAI	0
A17.CAN_ENGINE_SPEED_AB:	0	▽	AE7.COLUMN_TORQUE_C	0	▽	B42.MON_PASSIVE_TRIP_TIMEOU	0	▽	BA5.SAFETY_CIRCUIT_COMMS.	0	▽	CFF.EOLT_NOT_PASSED_FAULT.LIC	0
A18.CAN_VEHICLE_SPEED_AE	0	▽	AE8.NVM_TRQ_REINST_BI	0	▽	B43.LINK_VOLTAGE_FAULT.LIC	0	▽	BA6.LINK_RELAY_HIGH_SIDE_D	0	▽	E08.LOW_PWM_SUSPEND_EVENT.	0
A19.INVALID_RSP_COUNTER	0	▽	AF0.VEHICLE_TYPE_SELE	0	▽	B45.INT_WATCHDOG_RESET_FAI	0	▽	BA7.BRIDGE_NOT_DISABLED_D	0	▽	E09.LOAD_DUMP_EVENT.LIC	0
A1A.LOW_BATTERY_VOLTAGE	0	▽	AF1.FRICTION_DETECTION	0	▽	B47.ASIC_COMMS_POWER_UP_F/	0	▽	BA9.MOTOR_I_SENSE_DYNAMI	0	▽	E10.SUPPLY_LOW_VOLTAGE_TRQ	0
A1B.ECU_CALIB_DATA_CRC_I	0	▽	AF2.FRICTION_DETECTION	0	▽	B4A.UNEXPECTED_INTERRUPT_FA	0	▽	BAA.I_SENSE_STATIC_POSITIV	0	▽	E12.OVER_USE_TORQUE_LIMIT_AF	18
A1C.MAINTENANCE_DATA_CR	0	▽	AF3.EOLT_DATA_CRC_FAI	0	▽	B4E.MOTOR_POSITION_SENSOR_I	0	▽	BAB.I_SENSE_STATIC_NEGATN	0	▽	E14.ENGINE_STALLED_TORQUE_LII	0
A1E.VEHICLE_TUNE_DATA_CF	0	▽	AF4.TRACEABILITY_NUMS.	0	▽	B4F.LINK_RELAY_LOW_SIDE_DISA	0	▽	BAC.MOTOR_I_SENSE_DYNAMI	0	▽	E1A.LOW_BATTERY_VOLTAGE_EVE	0
A1F.TUNE_PLAUSIBILITY_FAU	0	▽	AF6.VEHICLE_TUNE_SELEI	0	▽	B51.STACK_FAULT.LIC	0	▽	BAD.MOTOR_I_SENSE_DYNAMI	0	▽	E1E.CURRENT_LIMIT_THERMAL_EV	0
A21.HIGH_BATTERY_VOLTAGE	0	▽	AF7.VEHICLE_TUNE_SELEI	0	▽	B53.RAM_CONTINUOUS_TEST_FAI	0	▽	BAE.I_SENSE_STATIC_COMMO	0	▽	E21.HIGH_BATTERY_VOLTAGE_EVE	0
A26.DEFAULT_DRIVE_STAGE	0	▽	A05.ANC_GATEWAY_LINK	0	▽	B55.PORT_REGISTERS_FAULT.LIC	0	▽	BAF.MOTOR_I_SENSE_DYNAMI	0	▽	E22.MICRO_LOW_VOLTAGE_FAULT	0
A28.ANGLE_OFFSET_INVALID	0	▽	A14.CAN_BRAKE_SENSOR	0	▽	B56.FAST_ROM_CHECK_FAULT.LIC	0	▽	BB5.MOTOR_PHASE_VOLTAGE	0	▽	E26.DRIVE_STAGE_TEMP_EVENT.LI	0
A29.INVALID_ASP_COUNTER	0	▽	A1D.TPMS_COUNTER_CRI	0	▽	B5F.MON_PASSIVE_RE_CTRL_TIM	0	▽	BB6.MOTOR_PHASE_VOLTAGE	0	▽	E2E.INCOMPLETE_POWER_DOWN	0
A2A.CAN_ANGLE_OFFSET_AB	0	▽	A20.CAN_VEH_YAW_RATE	0	▽	B60.ADC_REFERENCE_VOLTAGE_F	0	▽	BB7.MOTOR_PHASE_VOLTAGE	0	▽	E30.LINK_RELAY_OPEN_CIRCUIT_E	0
A2E.INCOMPLETE_POWER_D	0	▽	A34.CAN_VEH_YAW_RATE	0	▽	B61.PROC_CORE_TEST_FAULT.LIC	0	▽	BB8.MOTOR_PHASE_VOLTAGE	0	▽	E4C.THERM_EST_TEMP_EVENT.LIC	0
A30.LINK_RELAY_OPEN_CIRC	0	▽	A35.CAN_VEH_YAW_RATE	0	▽	B64.LNK_CAP_CHARGING_TOO_F/	0	▽	BB9.MOTOR_PHASE_VOLTAGE	0	▽	E4D.FAST_THERM_EST_TEMP_EVE	0
A33.BRIDGE_ENABLE_SENSE	0	▽	A36.CAN_ABS_STABILITY	0	▽	B6B.MOTOR_RELAY_SHORT_CIRC	0	▽	BBA.MOTOR_PHASE_VOLTAGE	0	▽	E62.ASIC_RAM_EVENT.LIC	0
A3B.MCU_TEMPERATURE_FAI	0	▽	A37.CAN_DESIRED_TORQI	0	▽	B6C.RAM_POWER_UP_TEST_FAI	0	▽	BBB.BRIDGE_NOT_DISABLED_I	0	▽	E78.NVM_RESEEDED_EVENT.LIC	0
A3C.NVM_TEMPORARY_DATA	0	▽	A3A.MOTOR_A_STAR_PO	0	▽	B6F.MON_ACTIVE_CTRL_TIMEOUT	0	▽	BC1.BRIDGE_NOT_DISABLED_T	0	▽	E90.HIGH_PWM_SUSPEND_EVENT.	0
A3D.NVM_DEM_BLOCK_CRC	0	▽	A3E.NVM_FEATURE_SW_C	0	▽	B70.MON_ACTIVE_TRIP_TIMEOUT	0	▽	BC2.SAFETY_CIRCUIT_PROG_S	0	▽	EDF.EXCESSIVE_COLUMN_VELOCIT	0
A49.FLASH_ACCESS_VIOLATI	0	▽	A3F.NVM_TIRE_ID_CRC_B	0	▽	B71.SOFTWARE_OVERRUN_FAULT	0	▽	BC4.LINK_RELAY_LOW_SIDE_I	0	▽	EF5.NO_VEH_TUNE_SELECTED_FAI	0
A62.ASIC_COMMUNICATIONS	0	▽	A44.PLATFORM_TUNE_DA	0	▽	B7A.PUT_MOTOR_PHASE_VOLTAC	0	▽	BC5.LINK_RELAY_HIGH_SIDE_D	0	▽	EF9.VEHICLE_TYPE_SELECTOR_CO	0
A65.BATT_LOSS_ON_LAST_J	0	▽	AC3.CAN_WHL_SPD_STUI	0	▽	B7B.PUT_MOTOR_PHASE_VOLTAC	0	▽	BC6.BRIDGE_NOT_ENABLED_DI	0	▽	F6A.FRICTION_DETECTED_ON_LAS	0
A66.MOTOR_RELAY_OPEN_CI	0	▽	AC8.CAN_WHL_SPD_INVA	0	▽	B7C.PUT_MOTOR_PHASE_VOLTAC	0	▽	BC7.BRIDGE_NOT_ENABLED_M	0	▽	A5C.INTEG_CHECK_ARB_LIM_FAI	0
A77.NVM_COMPATIBILITY_ID	0	▽	ACA.CAN_RSP_INVALID_F	0	▽	B7D.PUT_MOTOR_PHASE_VOLTAC	0	▽	BD0.TAS_RAW_TORQUE_1_RA	0	▽	A63.LA_CAMERA_HANDS_OFF_RES	0
B9C.CALIBRATION_INTEGRITY	0	▽	ACB.CAN_ANC_WHL_SPD	0	▽	B7E.PUT_MOTOR_PHASE_VOLTAC	0	▽	BD1.TAS_RAW_TORQUE_2_RA	0	▽	A67.LA_LDW_NEUTRALITY_FAULT.I	0
BA0.MOTOR_RELAY_CONTACT	0	▽	ACC.ANC_NIBBLE_CONTR	0	▽	B7F.PUT_MOTOR_PHASE_VOLTAG	0	▽	BD2.TAS_RAW_TORQUE_FREQ	0	▽	A73.EAC_STATE_FLT_RAISED_FAI	0
BEB.INVALID_MOTOR_TUNE_:	0	▽	ACD.ANC_MONITOR_COM	0	▽	B86.ROM_CONTINUOUS_CSUM_FA	0	▽	BD3.TAS_RAW_TORQUE_FREQ	0	▽	A74.EAC_STATE_FLT_LATCHED_FA	2
E11.SUPPLY_HIGH_VOLTAGE	0	▽	ACE.CAN_LANE_ASSIST_I	0	▽	B8F.REF_TUNE_DATA_INTEG_REM	0	▽	BD4.TAS_TORQUE_CROSSCHE	0	▽	A76.EAC_FAULT_LATCHED_FAULT.I	0
E1D.HARD_RST_RQST_REPR	0	▽	ACF.CAN_LANE_ASSIST_I	0	▽	B90.INTEG_CHECK_SENSOR_TORC	0	▽	B68.LA_LDW_LIMIT_FAULT.LIC	0	▽	A75.EAC_ACTIVE_ILLEGAL_STATE	0
EE0.DSR_HANDSHAKE_EVENT	0	▽	AD5.CAN_STR_WHEEL_AI	0	▽	A8C.CAN_BRK_SEN_DATA_STUCK	0	▽	B6D.PU_TAS_RAW_TORQUE_1	0	▽	A8A.CAN_VEH_LAT_ACCL_ABOVE	0
E98.POWERDOWN_DEICE_AB	0	▽	AD6.CAN_AUTOPARK_CM	0	▽	A8D.CAN_VEH_LAT_ACCL_ABSEN	0	▽	B6E.PU_TAS_RAW_TORQUE_2	0	▽	A8B.REF_TUNE_DATA_INTEGRITY_F	0
E66.MOTOR_RELAY_OPEN_CI	36	▽	AD7.CAN_WHL_SPD_ABS	0	▽	AA1.MOTOR_RELAY_CONTACT_TE	0	▽	B87.INTEG_CHECK_PU_SENSO!	0	▽	AA2.MOTOR_RELAY_CONTACT_TE!	0
												AA3.MOTOR_RELAY_CONTACT_RE!	0

# Ford DTC Info

Positive Response to ReadDTCInformation (Service 0x19) -- [ECU ID: 0x738 (PSCM)]

SubFunction: 0x02 - reportDTCByStatusMask

DTCStatusAvailabilityMask: 0xCA

Number of Returned DTCs: 1

DTC #1: 0xE01149 (U2011-49) [Motor - internal electronic failure]

Status: 0x08

Bit 7 - warningIndicatorRequested: 0

Bit 6 - testNotCompletedThisOperationCycle: 0

Bit 3 - confirmedDTC: 1

Bit 1 - testFailedThisOperationCycle: 0

# Veh Config Info

Positive Response to ReadDataByIdentifier (Service 0x22) -- [ECU ID: 0x738 (PSCM)] -- Assuming Single DID

DataIdentifier: 0xDE00    Data Size: 2 byte(s)

Data (Hex): 03 03

```
CANape PAR V3.1: FNU5-B2-AMBBB.a21 1 0 ccp
;
;
;
; Taras U502 with B3A and E66
ALT_COMP_EAC_INPUT_LIMIT_MAP [INT(16),(1,7)] 1152 ; 1152
: 1088 ; 1088
: 1024 ; 1024
: 1024 ; 1024
: 1024 ; 1024
: 512 ; 512
: 0 ; 0
ALT_COMP_EAC_INPUT_VSPD_MAP [INT(16),(1,7)] 0 ; 0
: 96 ; 96
: 192 ; 192
: 480 ; 480
: 768 ; 768
: 800 ; 800
: 832 ; 832
ASP_VALID_MULT_CHANGE_RATE [UINT(16)] 26 ; 9.92
ATF2_A0 [UINT(16)] 16384 ; 16384
ATF2_A1_MAP [UINT(16),(1,5)] 27301 ; 1.67
: 27293 ; 1.67
: 27285 ; 1.67
: 27285 ; 1.67
: 27277 ; 1.66
ATF2_A1_MAP_VTD [UINT(16),(1,5)] 27301 ; 27301
: 27293 ; 27293
: 27285 ; 27285
: 27285 ; 27285
: 27277 ; 27277
ATF2_A2_MAP [UINT(16),(1,5)] 10939 ; 0.67
: 10933 ; 0.67
: 10928 ; 0.67
: 10928 ; 0.67
: 10923 ; 0.67
ATF2_A2_MAP_VTD [UINT(16),(1,5)] 10939 ; 10939
: 10933 ; 10933
: 10928 ; 10928
: 10928 ; 10928
: 10923 ; 10923
ATF2_B0_MAP [UINT(16),(1,5)] 14025 ; 0.86
: 15774 ; 0.96
: 17522 ; 1.07
: 17522 ; 1.07
: 19270 ; 1.18
ATF2_B0_MAP_VTD [UINT(16),(1,5)] 14025 ; 14025
: 15774 ; 15774
: 17522 ; 17522
: 17522 ; 17522
: 19270 ; 19270
ATF2_B1_MAP [UINT(16),(1,5)] 26950 ; 1.64
: 30311 ; 1.85
: 33670 ; 2.06
: 33670 ; 2.06
: 37028 ; 2.26
ATF2_B1_MAP_VTD [UINT(16),(1,5)] 26950 ; 26950
: 30311 ; 30311
: 33670 ; 33670
: 33670 ; 33670
: 37028 ; 37028
ATF2_B2_MAP [UINT(16),(1,5)] 12947 ; 0.79
```



```

: 14561 ; 0.89
: 16175 ; 0.99
: 16175 ; 0.99
: 17788 ; 1.09
ATF2_B2_MAP_VTD [UINT(16),(1,5)] 12947 ; 12947
: 14561 ; 14561
: 16175 ; 16175
: 16175 ; 16175
: 17788 ; 17788
ATF2_VEHICLE_SPEED_MAP_VTD [UINT(8),(1,5)] 0 ; 0
: 5 ; 5
: 10 ; 10
: 15 ; 15
: 20 ; 20
ATF2_VehicleSpeed_Map [UINT(8),(1,5)] 0 ; 0
: 5 ; 5
: 10 ; 10
: 15 ; 15
: 20 ; 20
AltCompEAC_LimitMapBrkpts [INT(16),(1,7)] 0 ; 0
: 96 ; 96
: 192 ; 192
: 480 ; 480
: 768 ; 768
: 800 ; 800
: 832 ; 832
AltCompEAC_LimitMapData [INT(16),(1,7)] 1152 ; 1152
: 1088 ; 1088
: 1024 ; 1024
: 1024 ; 1024
: 1024 ; 1024
: 512 ; 512
: 0 ; 0
BATT_CUR_FILT_COEF [UINT(16)] 16384 ; 1
BLENDING_FILTER_FREQ_MAP [UINT(8),(1,12)] 80 ; 8
: 88 ; 8.8
: 98 ; 9.8
: 110 ; 11
: 123 ; 12.3
: 130 ; 13
: 135 ; 13.5
: 136 ; 13.6
: 137 ; 13.7
: 138 ; 13.8
: 138 ; 13.8
: 138 ; 13.8
BLENDING_FILTER_FREQ_MAP_VTD [UINT(8),(1,12)] 80 ; 8
: 88 ; 8.8
: 98 ; 9.8
: 110 ; 11
: 123 ; 12.3
: 130 ; 13
: 135 ; 13.5
: 136 ; 13.6
: 137 ; 13.7
: 138 ; 13.8
: 138 ; 13.8
: 138 ; 13.8
BUS_CLAMPING_THRESHOLD_HIGH_SQRD [UINT(16)] 607 ; 0.59
BUS_CLAMPING_THRESHOLD_LOW_SQRD [UINT(16)] 576 ; 0.56
CAN_STUCK_BITS_TIME_THRESH_APV [UINT(16)] 2000 ; 2000
CCP_Enable [UINT(8)] 1 ; 1
CCP_RequestedSAPPVehicleMode [UINT(32)] 0 ; 0

```

BGA02812\_Taras.PAR

```

CCP_Requested_Maintenance_Mode [UINT(32)] 0 ; 0
CHARGING_SYS_CHG_FLT_TIME_VTD [UINT(16)] 500 ; 500
COMP_EAC_A1_VTD [UINT(16)] 13650 ; 13650
COMP_EAC_A2_VTD [UINT(16)] 5470 ; 5470
COMP_EAC_B0_VTD [UINT(16)] 7013 ; 7013
COMP_EAC_B1_VTD [UINT(16)] 13475 ; 13475
COMP_EAC_B2_VTD [UINT(16)] 6474 ; 6474
COMP_EAC_BOOST_GAIN_VTD [INT(16)] 160 ; 20
COMP_EAC_INPUT_LIMIT_MAP [UINT(16),(1,4)] 1152 ; 1152
: 1024 ; 1024
: 1024 ; 1024
: 0 ; 0
COMP_EAC_INPUT_VSPD_MAP [UINT(8),(1,4)] 0 ; 0
: 3 ; 3
: 12 ; 12
: 13 ; 13
COMP_EAC_MODE_IN_TIME_VTD [UINT(16)] 200 ; 0.2
COMP_EAC_MODE_OUT_TIME_VTD [UINT(16)] 200 ; 0.2
COMP_EAC_OFF_CVEL_THRESH [UINT(16)] 5120 ; 5
COMP_EAC_OFF_TRQ_THRESH_PTD [UINT(16)] 5120 ; 5
COMP_EAC_OFF_VSPD_THRESH_PTD [UINT(16)] 768 ; 12
COMP_EAC_ON_CVEL_THRESH_PTD [UINT(16)] 102 ; 0.1
COMP_EAC_ON_TRQ_THRESH_PTD [UINT(16)] 3072 ; 3
COMP_EAC_ON_VSPD_THRESH_PTD [UINT(16)] 768 ; 12
COMP_EAC_TRQ_FILTER_FREQ_VTD [UINT(16)] 640 ; 2.5
CURRENT_INTEGRAL_GAIN [UINT(16)] 35 ; 42.72
CURRENT_PROPORTIONAL_GAIN [UINT(16)] 1409 ; 0.17
CURRENT_SHAPING_DISABLE_THRESH [INT(16)] 0 ; 0
CURRENT_SHAPING_ENABLE_THRESH [INT(16)] 0 ; 0
ClearEFFData [UINT(32)] 0 ; 0
ClearTRWFaults [UINT(32)] 0 ; 0
D0_DAMPING_TORQUE_DEADBAND_VTD [INT(16)] 0 ; 0
D1Q_DAMPING_TRQ_GAIN_MAP [UINT(8),(1,12)] 18 ; 1.8
: 18 ; 1.8
: 19 ; 1.9
: 20 ; 2
: 21 ; 2.1
: 22 ; 2.2
: 24 ; 2.4
: 26 ; 2.6
: 29 ; 2.9
: 32 ; 3.2
: 35 ; 3.5
: 37 ; 3.7
D1Q_DAMPING_TRQ_GAIN_MAP_VTD [UINT(8),(1,12)] 18 ; 1.8
: 18 ; 1.8
: 19 ; 1.9
: 20 ; 2
: 21 ; 2.1
: 22 ; 2.2
: 24 ; 2.4
: 26 ; 2.6
: 29 ; 2.9
: 32 ; 3.2
: 35 ; 3.5
: 37 ; 3.7
D1_DAMPING_TRQ_GAIN_MAP [UINT(8),(1,12)] 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 7 ; 0.7
: 17 ; 1.7
: 39 ; 3.9

```

```

: 64 ; 6.4
: 91 ; 9.1
: 116 ; 11.6
: 139 ; 13.9
: 156 ; 15.6
D1_DAMPING_TRQ_GAIN_MAP_VTD [UINT(8),(1,12)] 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 7 ; 0.7
: 17 ; 1.7
: 39 ; 3.9
: 64 ; 6.4
: 91 ; 9.1
: 116 ; 11.6
: 139 ; 13.9
: 156 ; 15.6
D2_DAMPING_TRQ_MAX_MAP [UINT(8),(1,12)] 85 ; 8.5
: 85 ; 8.5
: 85 ; 8.5
: 86 ; 8.6
: 88 ; 8.8
: 90 ; 9
: 94 ; 9.4
: 97 ; 9.7
: 100 ; 10
: 102 ; 10.2
: 103 ; 10.3
: 103 ; 10.3
D2_DAMPING_TRQ_MAX_MAP_VTD [UINT(8),(1,12)] 85 ; 8.5
: 85 ; 8.5
: 85 ; 8.5
: 86 ; 8.6
: 88 ; 8.8
: 90 ; 9
: 94 ; 9.4
: 97 ; 9.7
: 100 ; 10
: 102 ; 10.2
: 103 ; 10.3
: 103 ; 10.3
D3_DMP_TRQ_MULT_LWR_THRESH_VTD [UINT(16)] 819 ; 0.8
D4_DMP_TRQ_MULT_UPR_THRESH_VTD [UINT(16)] 3277 ; 3.2
D5_DMP_TRQ_MULT_FILT_FREQ_VTD [UINT(8)] 200 ; 20
D6_DMP_TRQ_DIFF_FLT_FREQ_VTD [UINT(8)] 255 ; 25.5
D7_DMP_TRQ_DIFF_MULT_LWR_THRESH [UINT(8)] 250 ; 250
D8_DMP_TRQ_DIFF_MULT_UPR_THRESH [UINT(8)] 255 ; 255
DECOUPLING_GAIN [UINT(16)] 0 ; 0
DEFAULT_DRIVE_STAGE_TEMP [INT(16)] 13000 ; 130
DEFAULT_MOTOR_CURRENT_A_RIPPLE [INT(16)] 192 ; 1.5
DEFAULT_MOTOR_CURRENT_C_RIPPLE [INT(16)] 346 ; 2.7
DEF_VEHICLE_SPEED [UINT(16)] 6400 ; 100
DEF_VSPD_IN_USE_MUL_CHNG_RATE [UINT(16)] 131 ; 49.97
DM_ACTIVE_PRECHARGE_SAFE_V_DROP [INT(16)] 3840 ; 15
DM_ADC_REF_VOLTAGE_MAX_RAW_INPUT [INT(16)] 14100 ; 2.84
DM_ADC_REF_VOLTAGE_MIN_RAW_INPUT [INT(16)] 10774 ; 2.17
DM_ASIC_MIN_BRIDGE_CLAMP_BAT_V [INT(16)] 5990 ; 23.4
DM_ASIC_WORKAROUND_PULSE_TIME [UINT(16)] 50 ; 5
DM_BATTERY_MAX_OVER_V_DURATION [UINT(32)] 3900000 ; 3900000
DM_BATTERY_MAX_V [INT(16)] 6144 ; 24
DM_BATTERY_MIN_V [INT(16)] 2304 ; 9
DM_BATTERY_NORMAL_V [INT(16)] 2304 ; 9
DM_BATTERY_V_CHECK_TIME [UINT(16)] 10 ; 10

```

BGA02812\_Taras.PAR

DM\_CAP\_TST\_CHARGE\_FAST\_COEFF [UINT(16)] 703 ; 0.043  
DM\_CAP\_TST\_CHARGE\_SLOW\_COEFF [UINT(16)] 176 ; 0.011  
DM\_CAP\_TST\_CHRG\_FST\_COEF\_PREP2C [UINT(16)] 676 ; 0.041  
DM\_CAP\_TST\_CHRG\_SLO\_COEF\_PREP2C [UINT(16)] 169 ; 0.01  
DM\_CAP\_TST\_CURVE\_FIT\_TOLERANCE\_V [INT(16)] 128 ; 0.5  
DM\_CAP\_TST\_FULL\_CHRG\_BAT\_V\_DROP [INT(16)] 282 ; 1.1  
DM\_CAP\_TST\_MAX\_VLINK\_CHARGE\_TIME [UINT(16)] 240 ; 240  
DM\_CAP\_TST\_MAX\_VLINK\_PCNT\_OF\_BAT [INT(16)] 11469 ; 70.001  
DM\_CAP\_TST\_STOP\_CLOSE\_V\_HEADROOM [INT(16)] 192 ; 0.75  
DM\_FET\_MAX\_UNLOADED\_BOT\_V\_DROP [INT(16)] 128 ; 0.5  
DM\_FET\_MAX\_UNLOADED\_OFF\_V\_DROP [INT(16)] 512 ; 2  
DM\_FET\_MAX\_UNLOADED\_TOP\_V\_DROP [INT(16)] 384 ; 1.5  
DM\_FET\_OFF\_PHASE\_V\_NOM\_BIAS\_PCNT [INT(16)] 8864 ; 54.102  
DM\_FET\_TST\_MAX\_PHASE\_V\_TST\_COUNT [UINT(16)] 40 ; 40  
DM\_FET\_TST\_MAX\_VLINK\_PAUSE\_COUNT [UINT(16)] 200 ; 200  
DM\_FET\_TST\_MIN\_INTER\_STATE\_V\_GAP [INT(16)] 64 ; 0.25  
DM\_FET\_TST\_MIN\_PHASES\_BAD\_COUNT [UINT(16)] 10 ; 10  
DM\_FET\_TST\_MIN\_PHASES\_OK\_COUNT [UINT(16)] 8 ; 8  
DM\_GATE\_DRV\_MAX\_SUPPLY\_ERR\_TIME [UINT(16)] 115 ; 115  
DM\_GATE\_DRV\_SUPPLY\_MAX\_ERR [INT(16)] 640 ; 2.5  
DM\_GATE\_DRV\_SUPPLY\_MIN\_VBATT [INT(16)] 3200 ; 12.5  
DM\_I\_SENSE\_RT\_MAX\_CM\_I\_SHIFT [INT(16)] 675 ; 675  
DM\_I\_SENSE\_RT\_MAX\_SIGNAL\_DIFF [INT(16)] 100 ; 100  
DM\_I\_SENSE\_RT\_MAX\_TEST\_CURRENT [INT(16)] 13200 ; 13200  
DM\_I\_SENSE\_RT\_MIN\_NEG\_I\_SHIFT [INT(16)] 1295 ; 1295  
DM\_I\_SENSE\_RT\_MIN\_POS\_I\_SHIFT [INT(16)] 1245 ; 1245  
DM\_I\_SENSE\_RT\_MIN\_TEST\_CURRENT [INT(16)] 76 ; 76  
DM\_I\_SENSE\_SPUT\_I\_SETTLING\_TIME [UINT(16)] 60 ; 6  
DM\_I\_SENSE\_SPUT\_MAX\_CM\_I\_SHIFT [UINT(16)] 620 ; 620  
DM\_I\_SENSE\_SPUT\_MAX\_TEST\_COUNT [UINT(16)] 10 ; 10  
DM\_I\_SENSE\_SPUT\_MIN\_NEG\_I\_SHIFT [UINT(16)] 3160 ; 3160  
DM\_I\_SENSE\_SPUT\_MIN\_POS\_I\_SHIFT [UINT(16)] 3160 ; 3160  
DM\_I\_SENSE\_SPUT\_OFFSET\_MAX\_ERROR [UINT(16)] 3006 ; 3006  
DM\_I\_SENSE\_SPUT\_OFFSET\_NOMINAL [UINT(16)] 14669 ; 14669  
DM\_LNK\_CONTACT\_MAX\_CLOSED\_V\_DROP [INT(16)] 230 ; 0.9  
DM\_LNK\_CONTACT\_MAX\_TEST\_TIME [UINT(16)] 7000 ; 7000  
DM\_LNK\_CONTACT\_NUM\_DELTA\_V\_DIFFS [UINT(16)] 4 ; 4  
DM\_LNK\_CONTACT\_OPEN\_DELTA\_V\_DROP [INT(16)] 128 ; 0.5  
DM\_LNK\_CONTACT\_PRE\_CLOSE\_V\_DROP [INT(16)] 845 ; 3.3  
DM\_LNK\_RLY\_CLS\_MAX\_RETRIES [UINT(16)] 4 ; 4  
DM\_LNK\_RLY\_CLS\_TEST\_CONF\_OPN\_CNT [UINT(16)] 95 ; 95  
DM\_LNK\_RLY\_CLS\_TEST\_MAX\_COUNT [UINT(16)] 140 ; 140  
DM\_LNK\_RLY\_DISABL\_CHG\_MAX\_RISE\_V [INT(16)] 256 ; 1  
DM\_LNK\_RLY\_OPEN\_MAX\_TEST\_COUNT [UINT(16)] 15 ; 15  
DM\_LNK\_RLY\_OPN\_TEST\_MAX\_COUNT [UINT(16)] 5000 ; 5000  
DM\_LNK\_RLY\_RETEST\_OPENING\_TIME [UINT(16)] 100 ; 100  
DM\_LNK\_RLY\_RE\_OPN\_CONF\_OPN\_CNT [UINT(16)] 5 ; 5  
DM\_LNK\_RLY\_RE\_OPN\_EXTD\_VBAT\_DROP [INT(16)] 51 ; 0.2  
DM\_LNK\_RLY\_RE\_OPN\_EXTEND\_COUNT [UINT(16)] 20 ; 20  
DM\_LNK\_RLY\_RE\_OPN\_EXTEND\_MAX\_CNT [UINT(16)] 200 ; 200  
DM\_LNK\_RLY\_RE\_OPN\_MAX\_COUNT [UINT(16)] 35 ; 35  
DM\_LOAD\_DUMP\_MAX\_DETECT\_ERR\_TIME [UINT(16)] 25 ; 100  
DM\_LOAD\_DUMP\_TIME\_LIMIT [UINT(16)] 100 ; 400  
DM\_MON\_MAX\_ACTIVE\_TRIP\_TIME [UINT(16)] 30 ; 30  
DM\_MON\_MAX\_INIT\_CONTROL\_TIME [UINT(16)] 30 ; 30  
DM\_MON\_MAX\_INIT\_BRDG\_ENABLE\_TIME [UINT(16)] 4 ; 4  
DM\_MON\_MAX\_PASSIVE\_TRIP\_TIME [UINT(16)] 30 ; 30  
DM\_MON\_MAX\_PWR\_DOWN\_TRIP\_RETESTS [UINT(16)] 3 ; 3  
DM\_MON\_MAX\_RE\_CONTROL\_TIME [UINT(16)] 30 ; 30  
DM\_MON\_MAX\_TRIP\_BRDG\_DISABL\_TIME [UINT(16)] 4 ; 4  
DM\_MTR\_RLY\_CLEAN\_MAX\_TEMPERATURE [INT(16)] 0 ; 0  
DM\_MTR\_RLY\_CLS\_MAX\_RETRIES [UINT(16)] 4 ; 4  
DM\_MTR\_RLY\_CLS\_TEST\_CNF\_CLS\_CNT [UINT(16)] 20 ; 20

BGA02812\_Taras.PAR

```

DM_MTR_RLY_CLS_TEST_MAX_COUNT [UINT(16)] 150 ; 150
DM_MTR_RLY_MAX_FET_3_OFF_COUNT [UINT(16)] 4 ; 4
DM_MTR_RLY_OPN_TEST_CNF_OPN_CNT [UINT(16)] 20 ; 20
DM_MTR_RLY_OPN_TEST_MAX_COUNT [UINT(16)] 100 ; 100
DM_MTR_RLY_PWM_DISCHRG_VLNK_PCNT [INT(16)] 3277 ; 20.001
DM_MTR_RLY_RETEST_OPENING_TIME [UINT(16)] 100 ; 100
DM_PHASE_3_BACK_EMF_ADJUST_PCNT [INT(16)] 3758 ; 22.937
DM_RELAY_CLEAN_CYCLE_TIME [UINT(16),(1,8)] 50 ; 50
: 50 ; 50
: 50 ; 50
: 50 ; 50
: 50 ; 50
: 50 ; 50
: 50 ; 50
: 50 ; 50
DM_RELAY_CLEAN_DURATION [UINT(16),(1,8)] 3000 ; 3000
: 1000 ; 1000
: 500 ; 500
: 500 ; 500
: 1500 ; 1500
: 1000 ; 1000
: 500 ; 500
: 500 ; 500
DM_RELAY_CLOSURE_TIMING [UINT(16),(1,9)] 110 ; 110
: 88 ; 88
: 60 ; 60
: 47 ; 47
: 39 ; 39
: 34 ; 34
: 30 ; 30
: 27 ; 27
: 25 ; 25
DM_SPDT_PAUSE_TEST_INDEFINITELY [INT(16)] 0 ; 0
DM_SPUT_PAUSE_TEST_INDEFINITELY [INT(16)] 0 ; 0
DM_SPUT_RESUME_HIGH_BATTERY_V [INT(16)] 4096 ; 16
DM_SPUT_RESUME_HIGH_LINK_V [INT(16)] 4096 ; 16
DM_SPUT_RESUME_LOW_BATTERY_V [INT(16)] 2816 ; 11
DM_SPUT_SUSPEND_HIGH_BATTERY_V [INT(16)] 4352 ; 17
DM_SPUT_SUSPEND_HIGH_LINK_V [INT(16)] 4352 ; 17
DM_SPUT_SUSPEND_LOW_BATTERY_V [INT(16)] 2560 ; 10
DM_SUSPEND_DE_GLITCH_TIME [UINT(16)] 2 ; 2
DRIVE_STAGE_TEMP_FALL_RATE [INT(16)] -4096 ; -0.5
DRIVE_STAGE_TEMP_LOWER_LIMIT [INT(16)] -5000 ; -50
DRIVE_STAGE_TEMP_RISE_RATE [INT(16)] 6390 ; 0.78
DRIVE_STAGE_TEMP_UPPER_LIMIT [INT(16)] 15500 ; 155
DRIVE_STAGE_VOLTAGE_FILTER_CONST [UINT(16)] 2730 ; 85.31
DevTune.AltPWM_Period [UINT(16)] 3760 ; 470
DevTune.AltTRQ_TimeThreshold [UINT(16)] 461 ; 57.63
DevTune.BATTERY_VOLTAGE_CHECK_TIME [UINT(16)] 100 ; 100
DevTune.CAN_STUCK_BITS_TIME_THRESH [UINT(16)] 2000 ; 2000
DevTune.DEF_VSPD_IN_USE_MUL_CHNG_RATE [UINT(16)] 131 ; 49.97
DevTune.DEMAND_PHASE_CURRENT [UINT(16)] 512 ; 4
DevTune.DM_ActivePrechargeSafeVDrop [INT(16)] 3840 ; 15
DevTune.DM_AdcRefVoltageMaxRawInput [INT(16)] 14100 ; 2.84
DevTune.DM_AdcRefVoltageMinRawInput [INT(16)] 10774 ; 2.17
DevTune.DM_AsicMinBridgeClampBatV [INT(16)] 5990 ; 23.4
DevTune.DM_AsicWorkaroundPulseTime [UINT(16)] 50 ; 5
DevTune.DM_BatteryMaxV [INT(16)] 6144 ; 24
DevTune.DM_BatteryMaxoverVDuration [UINT(32)] 3900000 ; 3900000
DevTune.DM_BatteryMinV [INT(16)] 2304 ; 9
DevTune.DM_BatteryNormalV [INT(16)] 2304 ; 9
DevTune.DM_BatteryVCheckTime [UINT(16)] 10 ; 10
DevTune.DM_CapTstChargeFastCoeff [UINT(16)] 703 ; 0.043

```

BGA02812\_Taras.PAR

```

DevTune.DM_CapTstChargeSlowCoeff [UINT(16)] 176 ; 0.011
DevTune.DM_CapTstChrgFastCoeff_PreP2c [UINT(16)] 676 ; 0.041
DevTune.DM_CapTstChrgSlowCoeff_PreP2c [UINT(16)] 169 ; 0.01
DevTune.DM_CapTstCurveFitToleranceV [INT(16)] 128 ; 0.5
DevTune.DM_CapTstFullChrgBatVDrop [INT(16)] 282 ; 1.1
DevTune.DM_CapTstMaxVlnkChargeTime [UINT(16)] 240 ; 240
DevTune.DM_CapTstMaxVlnkPcntOfBat [INT(16)] 11469 ; 70.001
DevTune.DM_CapTstStopCloseVHeadroom [INT(16)] 192 ; 0.75
DevTune.DM_FetMaxUnloadedBotVDrop [INT(16)] 128 ; 0.5
DevTune.DM_FetMaxUnloadedOffVDrop [INT(16)] 512 ; 2
DevTune.DM_FetMaxUnloadedTopVDrop [INT(16)] 384 ; 1.5
DevTune.DM_FetOffPhaseVNomBiasPcnt [INT(16)] 8864 ; 54.102
DevTune.DM_FetTstMaxPhaseVTstCount [UINT(16)] 40 ; 40
DevTune.DM_FetTstMaxVlnkPauseCount [UINT(16)] 200 ; 200
DevTune.DM_FetTstMinInterStateVGap [INT(16)] 64 ; 0.25
DevTune.DM_FetTstMinPhasesBadCount [UINT(16)] 10 ; 10
DevTune.DM_FetTstMinPhasesOkCount [UINT(16)] 8 ; 8
DevTune.DM_GateDrvMaxSupplyErrTime [UINT(16)] 115 ; 115
DevTune.DM_GateDrvSupplyMaxErr [INT(16)] 640 ; 2.5
DevTune.DM_GateDrvSupplyMinVBatt [INT(16)] 3200 ; 12.5
DevTune.DM_ISenseRtMaxCmIShift [INT(16)] 675 ; 675
DevTune.DM_ISenseRtMaxCrosscheckError [INT(16)] 100 ; 100
DevTune.DM_ISenseRtMaxTestCurrent [INT(16)] 13200 ; 13200
DevTune.DM_ISenseRtMinNegIShift [INT(16)] 1295 ; 1295
DevTune.DM_ISenseRtMinPosIShift [INT(16)] 1245 ; 1245
DevTune.DM_ISenseRtMinTestCurrent [INT(16)] 76 ; 76
DevTune.DM_ISenseSputISettlingTime [UINT(16)] 60 ; 6
DevTune.DM_ISenseSputMaxCmIShift [UINT(16)] 620 ; 620
DevTune.DM_ISenseSputMaxTestCount [UINT(16)] 10 ; 10
DevTune.DM_ISenseSputMinNegIShift [UINT(16)] 3160 ; 3160
DevTune.DM_ISenseSputMinPosIShift [UINT(16)] 3160 ; 3160
DevTune.DM_ISenseSputOffsetMaxError [UINT(16)] 3006 ; 3006
DevTune.DM_ISenseSputOffsetNominal [UINT(16)] 14669 ; 14669
DevTune.DM_LnkContactMaxClosedVDrop [INT(16)] 230 ; 0.9
DevTune.DM_LnkContactMaxTestTime [UINT(16)] 7000 ; 7000
DevTune.DM_LnkContactNumDeltaVDiffs [UINT(16)] 4 ; 4
DevTune.DM_LnkContactOpenDeltaVDrop [INT(16)] 128 ; 0.5
DevTune.DM_LnkContactPreCloseVDrop [INT(16)] 845 ; 3.3
DevTune.DM_LnkRlyClsMaxRetries [UINT(16)] 4 ; 4
DevTune.DM_LnkRlyClsTestConfOpnCnt [UINT(16)] 95 ; 95
DevTune.DM_LnkRlyClsTestMaxCount [UINT(16)] 140 ; 140
DevTune.DM_LnkRlyDisablChgMaxRiseV [INT(16)] 256 ; 1
DevTune.DM_LnkRlyDisablChgSenseTime [UINT(16)] 15 ; 15
DevTune.DM_LnkRlyOpnTestMaxCount [UINT(16)] 5000 ; 5000
DevTune.DM_LnkRlyReOpenConfOpnCnt [UINT(16)] 5 ; 5
DevTune.DM_LnkRlyReOpenExtendCount [UINT(16)] 20 ; 20
DevTune.DM_LnkRlyReOpenExtendMaxCount [UINT(16)] 200 ; 200
DevTune.DM_LnkRlyReOpenExtendVbatDrop [INT(16)] 51 ; 0.2
DevTune.DM_LnkRlyReOpenMaxCount [UINT(16)] 35 ; 35
DevTune.DM_LnkRlyRetestOpeningTime [UINT(16)] 100 ; 100
DevTune.DM_LoadDumpMaxDetectErrTime [UINT(16)] 25 ; 100
DevTune.DM_LoadDumpTimeLimit [UINT(16)] 100 ; 400
DevTune.DM_MaxIncompletePowerDownTests [UINT(8)] 24 ; 24
DevTune.DM_MonMaxActiveTripTime [UINT(16)] 30 ; 30
DevTune.DM_MonMaxInitBrdgEnableTime [UINT(16)] 4 ; 4
DevTune.DM_MonMaxInitialControlTime [UINT(16)] 30 ; 30
DevTune.DM_MonMaxPassiveTripTime [UINT(16)] 30 ; 30
DevTune.DM_MonMaxPwrDownTripRetests [UINT(16)] 3 ; 3
DevTune.DM_MonMaxReControlTime [UINT(16)] 30 ; 30
DevTune.DM_MonMaxTripBrdgDisablTime [UINT(16)] 4 ; 4
DevTune.DM_MtrRlyCleanMaxTemperature [INT(16)] 0 ; 0
DevTune.DM_MtrRlyClsMaxRetries [UINT(16)] 4 ; 4
DevTune.DM_MtrRlyClsTstCnfClsCnt [UINT(16)] 20 ; 20

```

BGA02812\_Taras.PAR

```

DevTune.DM_MtrRlyClsTstMaxCount [UINT(16)] 150 ; 150
DevTune.DM_MtrRlyMaxFet3OffCount [UINT(16)] 4 ; 4
DevTune.DM_MtrRlyOpnTstCnfOpnCnt [UINT(16)] 20 ; 20
DevTune.DM_MtrRlyOpnTstMaxCount [UINT(16)] 100 ; 100
DevTune.DM_MtrRlyPwmDischrgVlnkPcnt [INT(16)] 3277 ; 20.001
DevTune.DM_MtrRlyRetestOpeningTime [UINT(16)] 100 ; 100
DevTune.DM_Phase3BackEmfAdjustPcnt [INT(16)] 3758 ; 22.937
DevTune.DM_RelayCleanCycleTime [UINT(16),(1,8)] 50 ; 50
: 50 ; 50
: 50 ; 50
: 50 ; 50
: 50 ; 50
: 50 ; 50
: 50 ; 50
: 50 ; 50
: 50 ; 50
DevTune.DM_RelayCleanDuration [UINT(16),(1,8)] 3000 ; 3000
: 1000 ; 1000
: 500 ; 500
: 500 ; 500
: 1500 ; 1500
: 1000 ; 1000
: 500 ; 500
: 500 ; 500
DevTune.DM_RelayClosureTiming [UINT(16),(1,9)] 110 ; 110
: 88 ; 88
: 60 ; 60
: 47 ; 47
: 39 ; 39
: 34 ; 34
: 30 ; 30
: 27 ; 27
: 25 ; 25
DevTune.DM_SpdtPauseTestIndefinitely [INT(16)] 0 ; 0
DevTune.DM_SputPauseTestIndefinitely [INT(16)] 0 ; 0
DevTune.DM_SputResumeHighBatteryV [INT(16)] 4096 ; 16
DevTune.DM_SputResumeHighLinkV [INT(16)] 4096 ; 16
DevTune.DM_SputResumeLowBatteryV [INT(16)] 2816 ; 11
DevTune.DM_SputSuspendDeGlitchTime [UINT(16)] 2 ; 2
DevTune.DM_SputSuspendHighBatteryV [INT(16)] 4352 ; 17
DevTune.DM_SputSuspendHighLinkV [INT(16)] 4352 ; 17
DevTune.DM_SputSuspendLowBatteryV [INT(16)] 2560 ; 10
DevTune.DefaultDriveStageTemp [INT(16)] 13000 ; 130
DevTune.DriveStageTempFallRate [INT(16)] -4096 ; -0.5
DevTune.DriveStageTempLowerLimit [INT(16)] -5000 ; -50
DevTune.DriveStageTempRiseRate [INT(16)] 6390 ; 0.78
DevTune.DriveStageTempUpperLimit [INT(16)] 15500 ; 155
DevTune.DriveStageVoltageFilterConst [UINT(16)] 2730 ; 85.31
DevTune.ENG_STOP_HELD_DELAY_THRESH [UINT(16)] 15000 ; 300
DevTune.EncoderExtrapDisableElecVel [UINT(16)] 19 ; 0.15
DevTune.EncoderExtrapEnabledElecVel [UINT(16)] 40 ; 0.31
DevTune.FAST_IGNITION_OFF_DETECTION_TIME [UINT(16)] 30 ; 30
DevTune.HFAC_GAIN_MAP_SPD_GRAD_CNG_LIMIT [UINT(16)] 100 ; 10
DevTune.HFAC_GAIN_MAP_TRQ_GRAD_CNG_LIMIT [UINT(16)] 20 ; 20
DevTune.HFAC_LIMIT_LINE_GRADIENT [INT(8)] -1 ; -0.1
DevTune.HFAC_LIMIT_LINE_OFFSET [UINT(8)] 128 ; 128
DevTune.HFAC_ON_CENTRE_TRQ_CHANGE_LIMIT [INT(8)] -4 ; -2
DevTune.HFAC_ON_CENTRE_TRQ_LIMIT [UINT(8)] 20 ; 2
DevTune.HIGH_BATTERY_VLT_EVENT_DURATION [UINT(32)] 600000 ; 600000
DevTune.HIGH_BATTERY_VLT_EVENT_THRESHOLD [INT(16)] 5120 ; 20
DevTune.HallSensorPlacementAccuracy [UINT(16)] 432 ; 27
DevTune.IGNITION_DETECTION_TIME [UINT(16)] 109 ; 109
DevTune.IGNITION_IMMINEENT_TIME [UINT(16)] 30 ; 30
DevTune.LAT_ACCELERATION_LIMIT [UINT(16)] 24000 ; 15

```

BGA02812\_Taras.PAR

```

DevTune.LOW_BATTERY_VLT_EVENT_DURATION [UINT(16)] 50 ; 50
DevTune.LOW_BATTERY_VLT_EVENT_THRESHOLD [INT(16)] 2560 ; 10
DevTune.MAX_CAN_READ_COL_TORQUE_ERROR [UINT(8)] 64 ; 0.06
DevTune.MAX_DTCT_TORSION_BAR_DEFLECTION [INT(16)] 128 ; 4
DevTune.MAX_HALL_ENCODER_POSITION_ERROR [INT(16)] 9649 ; 53
DevTune.MAX_VEHICLE_LAT [UINT(16)] 7000 ; 40
DevTune.MAX_VEH_SPD_ERROR_RECOVERY_RATE [UINT(16)] 1280 ; 1250
DevTune.MIN_BATTERY_VOLTAGE [INT(16)] 2304 ; 9
DevTune.MaxCAN_ReadbackRSP_Error [UINT(8)] 69 ; 13.8
DevTune.MaxHallPeriod [UINT(16)] 278 ; 1.09
DevTune.MotorElecAccelSignFuncVellimit [UINT(8)] 37 ; 37
DevTune.MotorPowerupCurrentFilterConst [UINT(16)] 16384 ; 512
DevTune.MotorRippleCurrentFilterConst [UINT(16)] 16 ; 0.5
DevTune.MotorTorqueDemandErrorLimit [UINT(8)] 20 ; 0.16
DevTune.MotorVelExtrapolationConst [UINT(16)] 4096 ; 128
DevTune.MotorVelocityEstimateErrorLimit [UINT(8)] 15 ; 15
DevTune.MotorVelocityFilterConstant [UINT(16)] 1024 ; 32
DevTune.MotorZeroCurrentFilterConst [UINT(16)] 202 ; 6.31
DevTune.NORMAL_BATTERY_VOLTAGE [INT(16)] 2560 ; 10
DevTune.NO_TORQUE_LOWER_SUP_VOLT_DEMAND [INT(16)] 2406 ; 9.4
DevTune.OVER_USE_COLUMN_VEL_THRESHOLD [UINT(16)] 307 ; 0.3
DevTune.OVER_USE_INITIATION_TIME [UINT(16)] 25 ; 0.5
DevTune.OVER_USE_LOWER_TORQUE_THRESHOLD [UINT(16)] 2048 ; 2
DevTune.OVER_USE_TORQUE_LIMIT_VALUE [UINT(16)] 2500 ; 10
DevTune.OVER_USE_TRQ_LIM_DOWN_SLEW_RATE [UINT(8)] 30 ; 30
DevTune.OVER_USE_TRQ_LIM_UP_SLEW_RATE [UINT(8)] 100 ; 100
DevTune.OVER_USE_UPPER_TORQUE_THRESHOLD [UINT(16)] 5120 ; 5
DevTune.PDC_ASP_VALID_MULT_CHANGE_RATE [UINT(16)] 26 ; 9.92
DevTune.PDC_REPAIR_DETECTION_TIME [UINT(16)] 1000 ; 1
DevTune.PDC_SUPPRESSION_MULT_CHANGE_RATE [UINT(16)] 131 ; 49.97
DevTune.PDC_TYPE_THRESHOLD [UINT(16)] 1000 ; 500
DevTune.PD_DE_ICE_BATTERY_VOLTAGE_THRESH [INT(16)] 3020 ; 11.8
DevTune.PHASE_CURRENT_TEST_THRESHOLD [UINT(16)] 192 ; 1.5
DevTune.PWMS_High_Bat_Reinst_Delay [UINT(16)] 0 ; 0
DevTune.PWMS_High_Diag_Reinst_Delay [UINT(16)] 9 ; 9
DevTune.PWMS_Low_Bat_Reinst_Delay [UINT(16)] 0 ; 0
DevTune.PWMS_Low_Diag_Reinst_Delay [UINT(16)] 9 ; 9
DevTune.RELAY_POWERDOWN_CAN_CHECK_TIME [UINT(16)] 48 ; 48
DevTune.RELAY_POWERDOWN_CURRENT [INT(16)] 7936 ; 62
DevTune.RELAY_POWERDOWN_DS_TEMP [INT(16)] 5000 ; 50
DevTune.RELAY_POWERDOWN_F_THRM_EST_TEMP [INT(16)] 5000 ; 50
DevTune.RELAY_POWERDOWN_MAX_ENC_CHANGE [INT(16)] 1 ; 1
DevTune.RELAY_POWERDOWN_RAMP_DOWN_TIME [UINT(16)] 1000 ; 1000
DevTune.RELAY_POWERDOWN_RAMP_TIME [UINT(16)] 1000 ; 1000
DevTune.RELAY_POWERDOWN_THERM_EST_TEMP [INT(16)] 5000 ; 50
DevTune.RELAY_POWERDOWN_TIME [UINT(16)] 3000 ; 3000
DevTune.RELAY_TEMPERATURE_PD [INT(16)] 0 ; 0
DevTune.RSP_ErrorLimit [UINT(8)] 50 ; 5
DevTune.SC_FI_COL_VEL_CUT_OF_FREQC_ACD [UINT(16)] 22476 ; 0.69
DevTune.STRAIGHT_AHEAD_CONFIDENCE_LEVEL [INT(16)] 800 ; 25
DevTune.SwitchedVoltageFilterConst [UINT(16)] 2730 ; 5
DevTune.TAS_TorqueCrosscheckThreshold [UINT(16)] 25 ; 2.5
DevTune.TAS_TorqueDutyOffset [UINT(16)] 1000 ; 50
DevTune.TAS_TorqueDutyRange [UINT(16)] 1500 ; 75
DevTune.TAS_TorqueRange [UINT(16)] 400 ; 20
DevTune.TORQUE_LIMIT_DOWN_SLEW_RATE [UINT(8)] 50 ; 50
DevTune.TORQUE_LIMIT_UP_SLEW_RATE [UINT(8)] 50 ; 50
DevTune.TRW_EOL_TRQ_LIMIT_DOWN_SLEW_RATE [UINT(8)] 100 ; 100
DevTune.TRW_EOL_TRQ_LIMIT_UP_SLEW_RATE [UINT(8)] 100 ; 100
DevTune.VEHICLE_ACCEL_LIMIT [INT(16)] 1024 ; 1000
DevTune.VEHICLE_DECEL_LIMIT [INT(16)] -2368 ; -2312.5
DevTune.VEHICLE_MOVING_DETECTION_DELAY [UINT(16)] 60 ; 60
DevTuneTB.SaveRAM_Copy [UINT(16)] 0 ; FALSE

```



```

EACAbsoluteAngleSelector [UINT(16)] 0 ; EAC_ANGLE_SELECTED
EAC_ABSOLUTE_ANGLE_SELECTOR [UINT(8)] 0 ; 0
EAC_CM3_MVS_VTD [UINT(16)] 192 ; 3
EAC_CM3_SWSp_VTD [UINT(16)] 51 ; 0.05
EAC_CM3_SWT_VTD [UINT(16)] 1024 ; 1
EAC_CM3_dSWA_VTD [UINT(16)] 455 ; 10
EAC_CM5_MVS_VTD [UINT(16)] 704 ; 11
EAC_CM5_SWSp_VTD [UINT(16)] 5120 ; 5
EAC_CM5_SWT_VTD [UINT(16)] 3581 ; 3.5
EAC_CM5_dSWA_VTD [UINT(16)] 5461 ; 119.99
EAC_FAULT_RECOVERY_A_PTD [UINT(8)] 0 ; 0
EAC_FAULT_RECOVERY_B_PTD [UINT(8)] 0 ; 0
EAC_FAULT_RECOVERY_C_PTD [UINT(8)] 0 ; 0
EAC_FAULT_RECOVERY_D_PTD [UINT(8)] 2 ; 2
EAC_FAULT_RECOVERY_E_PTD [UINT(8)] 0 ; 0
EAC_FAULT_RECOVERY_F_PTD [UINT(8)] 0 ; 0
EAC_FAULT_RECOVERY_G_PTD [UINT(8)] 0 ; 0
EAC_FAULT_RECOVERY_H_PTD [UINT(8)] 0 ; 0
EAC_Filt_Freq_PTD [UINT(16)] 768 ; 3
EAC_Filt_Freq_Pos_PTD [UINT(16)] 19200 ; 75
EAC_GD_VTD [UINT(16)] 15360 ; 15
EAC_GF_VTD [UINT(16)] 1024 ; 1
EAC_ING_VTD [UINT(16)] 1311 ; 0.02
EAC_KD_VTD [UINT(16)] 9830 ; 1.2
EAC_KI_VTD [UINT(16)] 0 ; 0
EAC_KP_VTD [UINT(16)] 12800 ; 100
EAC_LIC_COUNTER [INT(16)] 0 ; 0
EAC_MAX_INTEGRAL_TRQ_VTD [INT(32)] 532676608 ; 127
EAC_MAX_PROPORTIONAL_TRQ_VTD [INT(32)] 33292288 ; 127
EAC_MAX_VELOCITY_ERROR_PTD [UINT(16)] 40960 ; 40
EAC_Max_Available_Current_PTD [UINT(8)] 100 ; 100
EAC_TORQUE_LIMIT_PTD [INT(16)] 1295 ; 5.08
EAC_T_ACTIVATE_LIMIT_PTD [INT(16)] 100 ; 100
EAC_T_SAPP_in_VTD [INT(16)] 500 ; 0.5
EAC_T_SAPP_out_VTD [INT(16)] 200 ; 0.2
EAL_SWA_LIMIT_VTD [UINT(16)] 21825 ; 479.55
EAL_SWA_MARGIN_VTD [UINT(16)] 227 ; 4.99
EAL_T_PTD [UINT(16)] 2000 ; 2000
ECU_Calib.BatteryVoltageGain [UINT(16)] 32336 ; 0.98682
ECU_Calib.BatteryVoltageOffset [INT(16)] 206 ; 206
ECU_Calib.CurrentSenseAveGain [UINT(16)] 32886 ; 1.0036
ECU_Calib.CurrentSenseAveOffset [INT(16)] 46 ; 46
ECU_Calib.CurrentSenseGain [INT(16)] 8765 ; 1.06995
ECU_Calib.CurrentSenseGainADCA [UINT(16)] 32915 ; 1.00449
ECU_Calib.CurrentSenseGainADCB [UINT(16)] 32931 ; 1.00497
ECU_Calib.CurrentSenseOffsetADCA [INT(16)] 38 ; 38
ECU_Calib.CurrentSenseOffsetADCB [INT(16)] 5 ; 5
ECU_Calib.External5VoltGain [UINT(16)] 32768 ; 1
ECU_Calib.External5VoltOffset [INT(16)] 0 ; 0
ECU_Calib.FET_TemperatureGain [UINT(16)] 32768 ; 1
ECU_Calib.FET_TemperatureOffset [INT(16)] 0 ; 0
ECU_Calib.LinkRelayVoltageGain [UINT(16)] 33107 ; 1.01035
ECU_Calib.LinkRelayVoltageOffset [INT(16)] -29 ; -29
ECU_Calib.MotorStarVoltageGain [UINT(16)] 33046 ; 1.00848
ECU_Calib.MotorStarVoltageOffset [INT(16)] -37 ; -37
ECU_Calib.PhaseVoltage1Gain [UINT(16)] 32964 ; 1.00598
ECU_Calib.PhaseVoltage1Offset [INT(16)] -25 ; -25
ECU_Calib.PhaseVoltage2Gain [UINT(16)] 33075 ; 1.00937
ECU_Calib.PhaseVoltage2Offset [INT(16)] -132 ; -132
ECU_Calib.PhaseVoltage3Gain [UINT(16)] 33011 ; 1.00742
ECU_Calib.PhaseVoltage3Offset [INT(16)] -39 ; -39
ECU_Calib.Reference2V5GainADCA [UINT(16)] 32768 ; 1
ECU_Calib.Reference2V5GainADCB [UINT(16)] 32768 ; 1

```

BGA02812\_Taras.PAR

```

ECU_Calib.Reference2V5OffsetADCA [INT(16)] 0 ; 0
ECU_Calib.Reference2V5OffsetADCB [INT(16)] 0 ; 0
ECU_Calib.SwitchVoltageGain [UINT(16)] 32391 ; 0.98849
ECU_Calib.SwitchVoltageOffset [INT(16)] 152 ; 152
ECU_Calib.TorqueSense1Gain [UINT(16)] 32768 ; 1
ECU_Calib.TorqueSense1Offset [INT(16)] 0 ; 0
ECU_Calib.TorqueSense2Gain [UINT(16)] 32768 ; 1
ECU_Calib.TorqueSense2Offset [INT(16)] 0 ; 0
ECU_CalibTB.SaveRAM_Copy [UINT(16)] 0 ; FALSE
ECU_Delivery_Assembly_Number [UINT(8),(1,24)] 66 ; 66
: 66 ; 66
: 53 ; 53
: 51 ; 51
: 45 ; 45
: 51 ; 51
: 70 ; 70
: 57 ; 57
: 54 ; 54
: 52 ; 52
: 45 ; 45
: 66 ; 66
: 71 ; 71
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
ECU_EOLT_Reject_Code [UINT(8)] 0 ; 0
ECU_EOL_TEST_PASSED [UINT(8)] 85 ; 85
ENCODER_EXTRAP_DISABLED_ELEC_VEL [UINT(16)] 19 ; 0.15
ENCODER_EXTRAP_ENABLED_ELEC_VEL [UINT(16)] 40 ; 0.31
ENGINE_STOPPED_HELD_DELAY_VTD [UINT(16)] 0 ; 0
ENGINE_STOPPED_HELD_TORQUE_VTD [UINT(8)] 0 ; 0
ENG_SPEED_CRANKING_RPM [UINT(16)] 1200 ; 300
ENG_SPEED_CRANKING_RPM_VTD [UINT(16)] 1200 ; 1200
ENG_SPEED_RUNNING_RPM [UINT(16)] 2000 ; 500
ENG_SPEED_RUNNING_VTD [UINT(16)] 2000 ; 2000
ENG_STALLED_INITIATION_TIME_VTD [UINT(16)] 0 ; 0
ENG_STATUS_CHG_FLT_TIME_VTD [UINT(16)] 50 ; 50
ENG_STL_TRQ_LMT_DN_SLEW_RATE_VTD [UINT(8)] 30 ; 30
ENG_STL_TRQ_LMT_UP_SLEW_RATE_VTD [UINT(8)] 100 ; 100
ENG_STOP_HELD_DELAY_THRESH [UINT(16)] 15000 ; 300
EPP_EOLT_Reject_Code [UINT(8)] 0 ; 0
EPP_EOL_TEST_PASSED [UINT(8)] 85 ; 85
EPP_Traceability [UINT(8),(1,15)] 49 ; 49
: 48 ; 48
: 50 ; 50
: 53 ; 53
: 57 ; 57
: 49 ; 49
: 57 ; 57
: 49 ; 49
: 57 ; 57
: 68 ; 68
: 51 ; 51
: 48 ; 48
: 48 ; 48

```

BGA02812\_Taras.PAR

```
: 49 ; 49
: 53 ; 53
EPS_EOLT_Function_Test_Indicator [UINT(8)] 0 ; 0
EPS_EOLT_Reject_Code [UINT(8)] 0 ; 0
EPS_EOLT_Test_Status [UINT(8)] 128 ; 128
EPS_to_ECC_Comms_Indicator [UINT(8)] 1 ; 1
FAST_THERMAL_EST_COOLING_RES [UINT(16)] 512 ; 2
FAST_THERMAL_EST_HEATING_RES [UINT(16)] 22118 ; 10.8
FAST_THERMAL_EST_THERMAL_CAP [UINT(16)] 12800 ; 50
FP_FRICTION_BOUND_AXIS [UINT(16),(1,2)] 0 ; 0
: 3000 ; 3000
FP_FRICTION_BOUND_AXIS_VTD [UINT(16),(1,2)] 0 ; 0
: 3000 ; 3000
FP_LAT_ACCEL_2_LOAD_MAP [UINT(16),(1,2)] 6195 ; 774.38
: 5200 ; 650
FP_LAT_ACCEL_2_LOAD_MAP_VTD [UINT(16),(1,2)] 6195 ; 774.38
: 5200 ; 650
FP_UPPER_FRICTION_BOUND [UINT(16),(1,2)] 950 ; 950
: 950 ; 950
FP_UPPER_FRICTION_BOUND_VTD [UINT(16),(1,2)] 950 ; 950
: 950 ; 950
FP_VSPD_GAIN [UINT(16),(1,2)] 1352 ; 1.32
: 1147 ; 1.12
FP_VSPD_GAIN_MAP [UINT(8),(1,2)] 45 ; 45
: 75 ; 75
FP_VSPD_GAIN_MAP_VTD [UINT(8),(1,2)] 45 ; 45
: 75 ; 75
FP_VSPD_GAIN_VTD [UINT(16),(1,2)] 1352 ; 1.32
: 1147 ; 1.12
FP_VSPD_LAT_MAP [UINT(8),(1,2)] 50 ; 50
: 120 ; 120
FP_VSPD_LAT_MAP_VTD [UINT(8),(1,2)] 50 ; 50
: 120 ; 120
Gear_Hardware_Part_Number [UINT(8),(1,24)] 66 ; 66
: 66 ; 66
: 53 ; 53
: 51 ; 51
: 45 ; 45
: 51 ; 51
: 50 ; 50
: 48 ; 48
: 48 ; 48
: 45 ; 45
: 66 ; 66
: 71 ; 71
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
HALL_SENSOR_INIT_ERROR_TIMEOUT [UINT(16)] 100 ; 100
HFAC_GAIN_MAP [UINT(8),(12,10)] 109 ; 54.5
: 116 ; 58
: 119 ; 59.5
: 121 ; 60.5
: 123 ; 61.5
```

BGA02812\_Taras.PAR

: 127 ; 63.5  
: 132 ; 66  
: 135 ; 67.5  
: 139 ; 69.5  
: 144 ; 72  
: 83 ; 41.5  
: 90 ; 45  
: 93 ; 46.5  
: 95 ; 47.5  
: 97 ; 48.5  
: 101 ; 50.5  
: 106 ; 53  
: 109 ; 54.5  
: 113 ; 56.5  
: 118 ; 59  
: 72 ; 36  
: 79 ; 39.5  
: 82 ; 41  
: 84 ; 42  
: 86 ; 43  
: 90 ; 45  
: 95 ; 47.5  
: 98 ; 49  
: 102 ; 51  
: 107 ; 53.5  
: 60 ; 30  
: 67 ; 33.5  
: 70 ; 35  
: 72 ; 36  
: 74 ; 37  
: 78 ; 39  
: 83 ; 41.5  
: 86 ; 43  
: 90 ; 45  
: 95 ; 47.5  
: 52 ; 26  
: 59 ; 29.5  
: 62 ; 31  
: 64 ; 32  
: 66 ; 33  
: 70 ; 35  
: 75 ; 37.5  
: 78 ; 39  
: 82 ; 41  
: 87 ; 43.5  
: 45 ; 22.5  
: 52 ; 26  
: 55 ; 27.5  
: 57 ; 28.5  
: 59 ; 29.5  
: 63 ; 31.5  
: 68 ; 34  
: 71 ; 35.5  
: 75 ; 37.5  
: 80 ; 40  
: 40 ; 20  
: 47 ; 23.5  
: 50 ; 25  
: 52 ; 26  
: 54 ; 27  
: 58 ; 29  
: 63 ; 31.5  
: 66 ; 33

BGA02812\_Taras.PAR

```
: 70 ; 35
: 75 ; 37.5
: 33 ; 16.5
: 40 ; 20
: 43 ; 21.5
: 45 ; 22.5
: 47 ; 23.5
: 51 ; 25.5
: 56 ; 28
: 59 ; 29.5
: 63 ; 31.5
: 70 ; 35
: 31 ; 15.5
: 38 ; 19
: 41 ; 20.5
: 43 ; 21.5
: 45 ; 22.5
: 49 ; 24.5
: 54 ; 27
: 57 ; 28.5
: 61 ; 30.5
: 68 ; 34
: 30 ; 15
: 37 ; 18.5
: 40 ; 20
: 42 ; 21
: 44 ; 22
: 48 ; 24
: 53 ; 26.5
: 56 ; 28
: 60 ; 30
: 65 ; 32.5
: 29 ; 14.5
: 36 ; 18
: 39 ; 19.5
: 41 ; 20.5
: 43 ; 21.5
: 47 ; 23.5
: 52 ; 26
: 55 ; 27.5
: 59 ; 29.5
: 64 ; 32
: 28 ; 14
: 35 ; 17.5
: 38 ; 19
: 40 ; 20
: 42 ; 21
: 46 ; 23
: 51 ; 25.5
: 54 ; 27
: 58 ; 29
: 63 ; 31.5
HFAC_GAIN_MAP_SPD_GRAD_CNG_LIMIT [UINT(16)] 100 ; 10
HFAC_GAIN_MAP_TRQ_GRAD_CNG_LIMIT [UINT(16)] 20 ; 20
HFAC_GAIN_MAP_Transposed [UINT(8),(10,12)] 109 ; 54.5
: 83 ; 41.5
: 72 ; 36
: 60 ; 30
: 52 ; 26
: 45 ; 22.5
: 40 ; 20
: 33 ; 16.5
: 31 ; 15.5
```

BGA02812\_Taras.PAR

: 30 ; 15  
: 29 ; 14.5  
: 28 ; 14  
: 116 ; 58  
: 90 ; 45  
: 79 ; 39.5  
: 67 ; 33.5  
: 59 ; 29.5  
: 52 ; 26  
: 47 ; 23.5  
: 40 ; 20  
: 38 ; 19  
: 37 ; 18.5  
: 36 ; 18  
: 35 ; 17.5  
: 119 ; 59.5  
: 93 ; 46.5  
: 82 ; 41  
: 70 ; 35  
: 62 ; 31  
: 55 ; 27.5  
: 50 ; 25  
: 43 ; 21.5  
: 41 ; 20.5  
: 40 ; 20  
: 39 ; 19.5  
: 38 ; 19  
: 121 ; 60.5  
: 95 ; 47.5  
: 84 ; 42  
: 72 ; 36  
: 64 ; 32  
: 57 ; 28.5  
: 52 ; 26  
: 45 ; 22.5  
: 43 ; 21.5  
: 42 ; 21  
: 41 ; 20.5  
: 40 ; 20  
: 123 ; 61.5  
: 97 ; 48.5  
: 86 ; 43  
: 74 ; 37  
: 66 ; 33  
: 59 ; 29.5  
: 54 ; 27  
: 47 ; 23.5  
: 45 ; 22.5  
: 44 ; 22  
: 43 ; 21.5  
: 42 ; 21  
: 127 ; 63.5  
: 101 ; 50.5  
: 90 ; 45  
: 78 ; 39  
: 70 ; 35  
: 63 ; 31.5  
: 58 ; 29  
: 51 ; 25.5  
: 49 ; 24.5  
: 48 ; 24  
: 47 ; 23.5  
: 46 ; 23

BGA02812\_Taras.PAR

```
: 132 ; 66
: 106 ; 53
: 95 ; 47.5
: 83 ; 41.5
: 75 ; 37.5
: 68 ; 34
: 63 ; 31.5
: 56 ; 28
: 54 ; 27
: 53 ; 26.5
: 52 ; 26
: 51 ; 25.5
: 135 ; 67.5
: 109 ; 54.5
: 98 ; 49
: 86 ; 43
: 78 ; 39
: 71 ; 35.5
: 66 ; 33
: 59 ; 29.5
: 57 ; 28.5
: 56 ; 28
: 55 ; 27.5
: 54 ; 27
: 139 ; 69.5
: 113 ; 56.5
: 102 ; 51
: 90 ; 45
: 82 ; 41
: 75 ; 37.5
: 70 ; 35
: 63 ; 31.5
: 61 ; 30.5
: 60 ; 30
: 59 ; 29.5
: 58 ; 29
: 144 ; 72
: 118 ; 59
: 107 ; 53.5
: 95 ; 47.5
: 87 ; 43.5
: 80 ; 40
: 75 ; 37.5
: 70 ; 35
: 68 ; 34
: 65 ; 32.5
: 64 ; 32
: 63 ; 31.5
HFAC_GAIN_MAP_VTD [UINT(8),(1,120)] 109 ; 54.5
: 116 ; 58
: 119 ; 59.5
: 121 ; 60.5
: 123 ; 61.5
: 127 ; 63.5
: 132 ; 66
: 135 ; 67.5
: 139 ; 69.5
: 144 ; 72
: 83 ; 41.5
: 90 ; 45
: 93 ; 46.5
: 95 ; 47.5
: 97 ; 48.5
```

BGA02812\_Taras.PAR

: 101 ; 50.5  
: 106 ; 53  
: 109 ; 54.5  
: 113 ; 56.5  
: 118 ; 59  
: 72 ; 36  
: 79 ; 39.5  
: 82 ; 41  
: 84 ; 42  
: 86 ; 43  
: 90 ; 45  
: 95 ; 47.5  
: 98 ; 49  
: 102 ; 51  
: 107 ; 53.5  
: 60 ; 30  
: 67 ; 33.5  
: 70 ; 35  
: 72 ; 36  
: 74 ; 37  
: 78 ; 39  
: 83 ; 41.5  
: 86 ; 43  
: 90 ; 45  
: 95 ; 47.5  
: 52 ; 26  
: 59 ; 29.5  
: 62 ; 31  
: 64 ; 32  
: 66 ; 33  
: 70 ; 35  
: 75 ; 37.5  
: 78 ; 39  
: 82 ; 41  
: 87 ; 43.5  
: 45 ; 22.5  
: 52 ; 26  
: 55 ; 27.5  
: 57 ; 28.5  
: 59 ; 29.5  
: 63 ; 31.5  
: 68 ; 34  
: 71 ; 35.5  
: 75 ; 37.5  
: 80 ; 40  
: 40 ; 20  
: 47 ; 23.5  
: 50 ; 25  
: 52 ; 26  
: 54 ; 27  
: 58 ; 29  
: 63 ; 31.5  
: 66 ; 33  
: 70 ; 35  
: 75 ; 37.5  
: 33 ; 16.5  
: 40 ; 20  
: 43 ; 21.5  
: 45 ; 22.5  
: 47 ; 23.5  
: 51 ; 25.5  
: 56 ; 28  
: 59 ; 29.5



BGA02812\_Taras.PAR

```
: 63 ; 31.5
: 70 ; 35
: 31 ; 15.5
: 38 ; 19
: 41 ; 20.5
: 43 ; 21.5
: 45 ; 22.5
: 49 ; 24.5
: 54 ; 27
: 57 ; 28.5
: 61 ; 30.5
: 68 ; 34
: 30 ; 15
: 37 ; 18.5
: 40 ; 20
: 42 ; 21
: 44 ; 22
: 48 ; 24
: 53 ; 26.5
: 56 ; 28
: 60 ; 30
: 65 ; 32.5
: 29 ; 14.5
: 36 ; 18
: 39 ; 19.5
: 41 ; 20.5
: 43 ; 21.5
: 47 ; 23.5
: 52 ; 26
: 55 ; 27.5
: 59 ; 29.5
: 64 ; 32
: 28 ; 14
: 35 ; 17.5
: 38 ; 19
: 40 ; 20
: 42 ; 21
: 46 ; 23
: 51 ; 25.5
: 54 ; 27
: 58 ; 29
: 63 ; 31.5
HFAC_LIMIT_LINE_GRADIENT [INT(8)] -1 ; -0.1
HFAC_LIMIT_LINE_OFFSET [UINT(8)] 128 ; 128
HFAC_ON_CENTRE_TRQ_CHANGE_LIMIT [INT(8)] -4 ; -2
HFAC_ON_CENTRE_TRQ_LIMIT [UINT(8)] 20 ; 2
HFAC_SPD_BRKPNT_MAP [UINT(8),(1,12)] 0 ; 0
: 8 ; 8
: 15 ; 15
: 25 ; 25
: 35 ; 35
: 45 ; 45
: 60 ; 60
: 75 ; 75
: 95 ; 95
: 120 ; 120
: 150 ; 150
: 190 ; 190
HFAC_SPD_BRKPNT_MAP_VTD [UINT(8),(1,12)] 0 ; 0
: 8 ; 8
: 15 ; 15
: 25 ; 25
: 35 ; 35
```

BGA02812\_Taras.PAR

```
: 45 ; 45
: 60 ; 60
: 75 ; 75
: 95 ; 95
: 120 ; 120
: 150 ; 150
: 190 ; 190
HFAC_TRQ_BRKPNT_MAP [UINT(8),(1,10)] 0 ; 0
: 5 ; 0.5
: 10 ; 1
: 15 ; 1.5
: 20 ; 2
: 25 ; 2.5
: 30 ; 3
: 35 ; 3.5
: 45 ; 4.5
: 60 ; 6
HFAC_TRQ_BRKPNT_MAP_VTD [UINT(8),(1,10)] 0 ; 0
: 5 ; 0.5
: 10 ; 1
: 15 ; 1.5
: 20 ; 2
: 25 ; 2.5
: 30 ; 3
: 35 ; 3.5
: 45 ; 4.5
: 60 ; 6
HSD0_COLUMN_VELOCITY_MAP_VTD [INT(16),(1,12)] 2253 ; 2.2
: 2765 ; 2.7
: 3277 ; 3.2
: 3789 ; 3.7
: 4301 ; 4.2
: 4813 ; 4.7
: 5325 ; 5.2
: 5837 ; 5.7
: 5837 ; 5.7
: 5837 ; 5.7
: 5837 ; 5.7
: 5837 ; 5.7
HSD0_Column_Velocity_Map [INT(16),(1,12)] 2253 ; 2.2
: 2765 ; 2.7
: 3277 ; 3.2
: 3789 ; 3.7
: 4301 ; 4.2
: 4813 ; 4.7
: 5325 ; 5.2
: 5837 ; 5.7
: 5837 ; 5.7
: 5837 ; 5.7
: 5837 ; 5.7
: 5837 ; 5.7
HSD1_DAMPING_TORQUE_GAIN_MAP_VTD [INT(16),(1,12)] 100 ; 100
: 75 ; 75
: 50 ; 50
: 25 ; 25
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
```

```

HSD1_Damping_Torque_Gain_Map [INT(16),(1,12)] 100 ; 100
: 75 ; 75
: 50 ; 50
: 25 ; 25
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
HSD2_MAX_HIGH_SPEED_DAMPING_VTD [UINT(8),(1,12)] 106 ; 106
: 106 ; 106
: 106 ; 106
: 106 ; 106
: 106 ; 106
: 106 ; 106
: 106 ; 106
: 106 ; 106
: 106 ; 106
: 106 ; 106
: 106 ; 106
: 106 ; 106
: 106 ; 106
HSD2_Max_High_Speed_Damping [UINT(8),(1,12)] 106 ; 106
: 106 ; 106
: 106 ; 106
: 106 ; 106
: 106 ; 106
: 106 ; 106
: 106 ; 106
: 106 ; 106
: 106 ; 106
: 106 ; 106
: 106 ; 106
: 106 ; 106
: 106 ; 106
MANUFACTURING_RESET [UINT(32)] 0 ; 0
MAXIMUM_ASSISTANCE_TORQUE_MTD [UINT(8)] 250 ; 125
MAXIMUM_BATTERY_CURRENT [INT(16)] 15360 ; 120
MAX_CAN_READ_COL_TORQUE_ERROR [UINT(8)] 64 ; 0.06
MAX_DRIVE_STAGE_TEMP [INT(16)] 15000 ; 150
MAX_DTCT_TORSION_BAR_DEFLECTION [INT(16)] 128 ; 4
MAX_HALL_ENCODER_POSITION_ERROR [INT(16)] 9649 ; 53
MAX_INCOMPLETE_POWER_DOWN_TESTS [UINT(8)] 24 ; 24
MAX_MODULATION_DEPTH [UINT(16)] 1178 ; 1.15
MAX_THERMAL_ESTIMATOR_TEMP [INT(16)] 19000 ; 190
MOTOR_RIPPLE_I_FILTER_CONST [UINT(16)] 16 ; 0.5
MOTOR_STALLED_THRESHOLD [UINT(16)] 42 ; 0.33
MOTOR_TORQUE_CONSTANT [INT(16)] 959 ; 0.06
MOTOR_TORQUE_CONSTANT_TRIM [INT(16)] 0 ; 0
MOTOR_VELOCITY_FILTER_CONSTANT [UINT(16)] 1024 ; 32
MOTOR_VEL_EXTRAPOLATION_CONST [UINT(16)] 4096 ; 128
MOTOR_ZERO_CURRENT_FILTER_CONST [UINT(16)] 202 ; 6.31
MotorTune.BusClampingThresholdHighSquared [UINT(16)] 607 ; 0.59
MotorTune.BusClampingThresholdLowSquared [UINT(16)] 576 ; 0.56
MotorTune.CurrentIntegralGain [UINT(16)] 35 ; 42.72
MotorTune.CurrentProportionalGain [UINT(16)] 1409 ; 0.17
MotorTune.CurrentShapeA18MapData [INT(16),(1,31)] 56 ; 0.44
: 56 ; 0.44
: 56 ; 0.44
: 56 ; 0.44
: 45 ; 0.35
: 34 ; 0.27

```

BGA02812\_Taras.PAR

```
: 20 ; 0.16
: 6 ; 0.05
: -11 ; -0.09
: -28 ; -0.22
: -24 ; -0.19
: -19 ; -0.15
: -14 ; -0.11
: -9 ; -0.07
: -5 ; -0.04
: 0 ; 0
: 6 ; 0.05
: 11 ; 0.09
: 17 ; 0.13
: 23 ; 0.18
: 29 ; 0.23
: 34 ; 0.27
: 15 ; 0.12
: -4 ; -0.03
: -20 ; -0.16
: -35 ; -0.27
: -48 ; -0.38
: -60 ; -0.47
: -60 ; -0.47
: -60 ; -0.47
: -60 ; -0.47
MotorTune.CurrentShapeB18MapData [INT(16),(1,31)] -24 ; -0.19
: -24 ; -0.19
: -24 ; -0.19
: -24 ; -0.19
: -25 ; -0.2
: -26 ; -0.2
: -24 ; -0.19
: -21 ; -0.16
: -15 ; -0.12
: -9 ; -0.07
: -8 ; -0.06
: -6 ; -0.05
: -5 ; -0.04
: -3 ; -0.02
: -2 ; -0.02
: 0 ; 0
: -3 ; -0.02
: -5 ; -0.04
: -7 ; -0.05
: -9 ; -0.07
: -12 ; -0.09
: -14 ; -0.11
: -22 ; -0.17
: -29 ; -0.23
: -33 ; -0.26
: -37 ; -0.29
: -38 ; -0.3
: -39 ; -0.3
: -39 ; -0.3
: -39 ; -0.3
: -39 ; -0.3
MotorTune.CurrentShapingDisableThreshold [INT(16)] 0 ; 0
MotorTune.CurrentShapingEnableThreshold [INT(16)] 0 ; 0
MotorTune.DecouplingGain [UINT(16)] 0 ; 0
MotorTune.DefaultMotorCurrentARipple [INT(16)] 192 ; 1.5
MotorTune.DefaultMotorCurrentCRipple [INT(16)] 346 ; 2.7
MotorTune.DrvStgTempMotI_LimMapBrkpts [INT(16),(1,4)] -4000 ; -40
: 13000 ; 130
```

BGA02812\_Taras.PAR

```
: 15000 ; 150
: 16000 ; 160
MotorTune.DrvStgTempMotI_LimMapData [INT(16),(1,4)] 15360 ; 120
: 15360 ; 120
: 0 ; 0
: 0 ; 0
MotorTune.FastThermalEstCoolingRes [UINT(16)] 512 ; 2
MotorTune.FastThermalEstHeatingRes [UINT(16)] 22118 ; 10.8
MotorTune.FastThermalEstI_LimMapBrkpts [INT(16),(1,4)] -4000 ; -40
: 15000 ; 150
: 17000 ; 170
: 30000 ; 300
MotorTune.FastThermalEstI_LimMapData [INT(16),(1,4)] 15360 ; 120
: 15360 ; 120
: 0 ; 0
: 0 ; 0
MotorTune.FastThermalEstThermalCap [UINT(16)] 12800 ; 50
MotorTune.HallSensorInitErrorTimeout [UINT(16)] 100 ; 100
MotorTune.MPS_POWERDOWN_DE_ICE_FILT_CONST [UINT(16)] 3000 ; 3000
MotorTune.MaxDriveStageTemp [INT(16)] 15000 ; 150
MotorTune.MaxFastThermalEstimatorTemp [INT(16)] 17000 ; 170
MotorTune.MaxModulationDepth [UINT(16)] 1178 ; 1.15
MotorTune.MaxMotorPhaseCurrentLowerMapData [INT(16),(1,30)] 14592 ; 114
: 14592 ; 114
: 14592 ; 114
: 14080 ; 110
: 13184 ; 103
: 12544 ; 98
: 12032 ; 94
: 11904 ; 93
: 11904 ; 93
: 11904 ; 93
: 11904 ; 93
: 11904 ; 93
: 11776 ; 92
: 11648 ; 91
: 11648 ; 91
: 11776 ; 92
: 11776 ; 92
: 11776 ; 92
: 11776 ; 92
: 11904 ; 93
: 11904 ; 93
: 11904 ; 93
: 12032 ; 94
: 12032 ; 94
: 12032 ; 94
: 12032 ; 94
: 12160 ; 95
: 12288 ; 96
: 12288 ; 96
: 12288 ; 96
: 12288 ; 96
: 12288 ; 96
: 12288 ; 96
: 12288 ; 96
MotorTune.MaxMotorPhaseCurrentUpperMapData [INT(16),(1,30)] 14592 ; 114
: 14592 ; 114
: 14592 ; 114
: 14080 ; 110
: 13184 ; 103
: 12544 ; 98
: 12032 ; 94
: 11392 ; 89
: 10880 ; 85
: 10368 ; 81
: 9728 ; 76
```

BGA02812\_Taras.PAR

```

: 9216 ; 72
: 8832 ; 69
: 8576 ; 67
: 8448 ; 66
: 8448 ; 66
: 8448 ; 66
: 8448 ; 66
: 8448 ; 66
: 8576 ; 67
: 8704 ; 68
: 8832 ; 69
: 8960 ; 70
: 9216 ; 72
: 9344 ; 73
: 9344 ; 73
: 9344 ; 73
: 9344 ; 73
: 9344 ; 73
: 9344 ; 73
MotorTune.MaxThermalEstimatorTemp [INT(16)] 19000 ; 190
MotorTune.MaximumAssistanceTorqueDemand [UINT(8)] 250 ; 125
MotorTune.MaximumBatteryCurrent [INT(16)] 15360 ; 120
MotorTune.MotorStalledThreshold [UINT(16)] 42 ; 0.33
MotorTune.MotorTorqueConstant [INT(16)] 959 ; 0.06
MotorTune.MotorTorqueConstantTrim [INT(16)] 0 ; 0
MotorTune.NumPhaseVoltageTestFailures [UINT(8)] 19 ; 19
MotorTune.NumStarPointTestFailures [UINT(8)] 19 ; 19
MotorTune.PD_DE_ICE_MPS_PHASE_ALLOWANCE [UINT(16)] 5461 ; 30
MotorTune.PU_MTR_RLY_TEST_MPS_PHASE_ALL [UINT(16)] 182 ; 1
MotorTune.PhaseAdvanceLowerMapData [INT(16),(1,30)] 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 1638 ; 9
: 3095 ; 17
: 4551 ; 25
: 5825 ; 32
: 6918 ; 38
: 7828 ; 43
: 8556 ; 47
: 9102 ; 50
: 9648 ; 53
: 10195 ; 56
: 10741 ; 59
: 11105 ; 61
: 11469 ; 63
: 11833 ; 65
: 12197 ; 67
: 12561 ; 69
: 12743 ; 70
: 12925 ; 71
: 13107 ; 72
: 13107 ; 72
: 13107 ; 72
: 13107 ; 72
: 13107 ; 72
: 13107 ; 72
MotorTune.PhaseAdvanceUpperMapData [INT(16),(1,30)] 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0

```

```

: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 728 ; 4
: 1820 ; 10
: 2913 ; 16
: 4005 ; 22
: 5097 ; 28
: 6008 ; 33
: 6918 ; 38
: 7646 ; 42
: 8374 ; 46
: 8920 ; 49
: 9648 ; 53
: 10377 ; 57
: 10923 ; 60
: 11287 ; 62
: 11651 ; 64
: 12015 ; 66
: 12015 ; 66
: 12015 ; 66
: 12015 ; 66
: 12015 ; 66
: 12015 ; 66
MotorTune.PhaseVoltageThresholdHigh [INT(16)] 886 ; 3.46
MotorTune.PhaseVoltageThresholdLow [INT(16)] 253 ; 0.99
MotorTune.RotatingMotorRMSPowerFraction [UINT(16)] 32 ; 0.25
MotorTune.SectorHysteresis [UINT(16)] 210 ; 0.07
MotorTune.StarPointVoltA1MaxError [INT(16)] 908 ; 3.55
MotorTune.StarPointVoltC1MaxError [INT(16)] 908 ; 3.55
MotorTune.StarPointVoltSumMaxError [INT(16)] 908 ; 3.55
MotorTune.SvmSectorHysteresisHigh [UINT(16)] 50 ; 0.05
MotorTune.SvmSectorHysteresisLow [UINT(16)] 15 ; 0.01
MotorTune.SvmSectorPositionHysteresis [UINT(16)] 910 ; 5
MotorTune.ThermalEstCoolingRes [UINT(16)] 7680 ; 30
MotorTune.ThermalEstHeatingRes [UINT(16)] 2048 ; 1
MotorTune.ThermalEstInitFracMapBrkpts [INT(16),(1,4)] -7000 ; -70
: -3500 ; -35
: -800 ; -8
: 1000 ; 10
MotorTune.ThermalEstThermalCap [UINT(16)] 6144 ; 24
MotorTune.ThermalEstimatorI_LimMapBrkpts [INT(16),(1,4)] -4000 ; -40
: 16000 ; 160
: 19000 ; 190
: 30000 ; 300
MotorTune.ThermalEstimatorI_LimMapData [INT(16),(1,4)] 15360 ; 120
: 15360 ; 120
: 0 ; 0
: 0 ; 0
MotorTuneID_NVCopy [UINT(16)] 1 ; 1
MotorTuneID_NVV [UINT(16)] 1 ; MOTOR_TUNE_2
MotorTuneTB.SaveRAM_Copy [UINT(16)] 0 ; FALSE
MotorTraceability [UINT(8),(1,15)] 66 ; 66
: 65 ; 65
: 70 ; 70
: 48 ; 48
: 68 ; 68
: 50 ; 50
: 52 ; 52
: 50 ; 50
: 50 ; 50

```

BGA02812\_Taras.PAR

```
: 49 ; 49
: 48 ; 48
: 52 ; 52
: 50 ; 50
: 48 ; 48
: 0 ; 0
NUM_PHASE_VOLTAGE_TEST_FAILURES [UINT(8)] 19 ; 19
NUM_STAR_POINT_TEST_FAILURES [UINT(8)] 19 ; 19
NvM.EraseNVM [UINT(32)] 0 ; 0
NvM.ForceReSeedNVM [UINT(32)] 0 ; 0
OVER_USE_COLUMN_VEL_THRESHOLD [UINT(16)] 307 ; 0.3
OVER_USE_INITIATION_TIME [UINT(16)] 25 ; 0.5
OVER_USE_LOWER_TORQUE_THRESHOLD [UINT(16)] 2048 ; 2
OVER_USE_TORQUE_LIMIT_VALUE [UINT(16)] 2500 ; 10
OVER_USE_TRQ_LIM_DOWN_SLEW_RATE [UINT(8)] 30 ; 30
OVER_USE_TRQ_LIM_UP_SLEW_RATE [UINT(8)] 100 ; 100
OVER_USE_UPPER_TORQUE_THRESHOLD [UINT(16)] 5120 ; 5
P0 [UINT(8),(1,12)] 1 ; 0.05
: 2 ; 0.1
: 3 ; 0.15
: 4 ; 0.2
: 5 ; 0.25
: 7 ; 0.35
: 9 ; 0.45
: 11 ; 0.55
: 13 ; 0.65
: 14 ; 0.7
: 15 ; 0.75
: 16 ; 0.8
P0_BOOST_CURVE_Q1_START_MAP_VTD [UINT(8),(1,12)] 1 ; 0.05
: 2 ; 0.1
: 3 ; 0.15
: 4 ; 0.2
: 5 ; 0.25
: 7 ; 0.35
: 9 ; 0.45
: 11 ; 0.55
: 13 ; 0.65
: 14 ; 0.7
: 15 ; 0.75
: 16 ; 0.8
P1 [UINT(8),(1,12)] 18 ; 0.9
: 24 ; 1.2
: 25 ; 1.25
: 25 ; 1.25
: 25 ; 1.25
: 24 ; 1.2
: 23 ; 1.15
: 22 ; 1.1
: 21 ; 1.05
: 20 ; 1
: 20 ; 1
: 20 ; 1
P1_BOOST_CURVE_Q1_WIDTH_MAP_VTD [UINT(8),(1,12)] 18 ; 0.9
: 24 ; 1.2
: 25 ; 1.25
: 25 ; 1.25
: 25 ; 1.25
: 24 ; 1.2
: 23 ; 1.15
: 22 ; 1.1
: 21 ; 1.05
: 20 ; 1
```



BGA02812\_Taras.PAR

```
: 20 ; 1
: 20 ; 1
P2 [UINT(8),(1,12)] 180 ; 9
: 130 ; 6.5
: 96 ; 4.8
: 82 ; 4.1
: 77 ; 3.85
: 75 ; 3.75
: 74 ; 3.7
: 73 ; 3.65
: 73 ; 3.65
: 72 ; 3.6
: 71 ; 3.55
: 70 ; 3.5
P2_BOOST_CURVE_Q1_GAIN_MAP_VTD [UINT(8),(1,12)] 180 ; 9
: 130 ; 6.5
: 96 ; 4.8
: 82 ; 4.1
: 77 ; 3.85
: 75 ; 3.75
: 74 ; 3.7
: 73 ; 3.65
: 73 ; 3.65
: 72 ; 3.6
: 71 ; 3.55
: 70 ; 3.5
P3 [UINT(8),(1,12)] 20 ; 1
: 27 ; 1.35
: 29 ; 1.45
: 30 ; 1.5
: 31 ; 1.55
: 32 ; 1.6
: 33 ; 1.65
: 34 ; 1.7
: 35 ; 1.75
: 36 ; 1.8
: 37 ; 1.85
: 38 ; 1.9
P3_BOOST_CURVE_Q2_START_MAP_VTD [UINT(8),(1,12)] 20 ; 1
: 27 ; 1.35
: 29 ; 1.45
: 30 ; 1.5
: 31 ; 1.55
: 32 ; 1.6
: 33 ; 1.65
: 34 ; 1.7
: 35 ; 1.75
: 36 ; 1.8
: 37 ; 1.85
: 38 ; 1.9
P4 [UINT(8),(1,12)] 20 ; 1
: 22 ; 1.1
: 25 ; 1.25
: 29 ; 1.45
: 34 ; 1.7
: 40 ; 2
: 48 ; 2.4
: 56 ; 2.8
: 63 ; 3.15
: 70 ; 3.5
: 77 ; 3.85
: 81 ; 4.05
P4_BOOST_CURVE_Q2_WIDTH_MAP_VTD [UINT(8),(1,12)] 20 ; 1
```

```

: 22 ; 1.1
: 25 ; 1.25
: 29 ; 1.45
: 34 ; 1.7
: 40 ; 2
: 48 ; 2.4
: 56 ; 2.8
: 63 ; 3.15
: 70 ; 3.5
: 77 ; 3.85
: 81 ; 4.05
P5 [UINT(8),(1,12)] 179 ; 35.8
: 176 ; 35.2
: 169 ; 33.8
: 160 ; 32
: 151 ; 30.2
: 140 ; 28
: 123 ; 24.6
: 105 ; 21
: 85 ; 17
: 73 ; 14.6
: 67 ; 13.4
: 62 ; 12.4
P5_BOOST_CURVE_Q2_GAIN_MAP_VTD [UINT(8),(1,12)] 179 ; 35.8
: 176 ; 35.2
: 169 ; 33.8
: 160 ; 32
: 151 ; 30.2
: 140 ; 28
: 123 ; 24.6
: 105 ; 21
: 85 ; 17
: 73 ; 14.6
: 67 ; 13.4
: 62 ; 12.4
PD [UINT(8),(1,12)] 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 3 ; 0.03
: 11 ; 0.11
: 17 ; 0.17
: 23 ; 0.23
: 27 ; 0.27
: 28 ; 0.28
: 28 ; 0.28
PDC_COLUMN_TORQUE_FILT_FREQ [UINT(16)] 37 ; 0.07
PDC_COL_ANGLE_MAX_VTD [UINT(16)] 228 ; 5.01
PDC_COL_TRQ_MAX_VTD [UINT(8)] 80 ; 2.5
PDC_COL_TRQ_MIN_VTD [UINT(8)] 26 ; 0.2
PDC_ColumnTorqueFrequency [UINT(16)] 37 ; 2.98
PDC_LIMIT [UINT(8)] 48 ; 1.5
PDC_MAX_RATE_LIMIT [INT(32)] 262 ; 1
PDC_TIMER [UINT(16)] 500 ; 2
PDC_TIME_CONSTANT_VTD [UINT(16)] 60 ; 30
PDC_USE_LAST_JOURNEY_VTD [UINT(8)] 0 ; 0
PDC_VSPD_HIGHER_GAIN_THRESHOLD [UINT(16)] 2600 ; 40
PDC_VSPD_LOWER_GAIN [UINT(16)] 0 ; 0
PDC_VSPD_LOWER_GAIN_THRESHOLD [UINT(16)] 640 ; 10
PDC_VSPD_MAX [INT(16)] 12800 ; 200
PDC_VSPD_MIN [INT(16)] 2560 ; 40
PDC_VSPD_ZERO_GAIN_THRESHOLD [UINT(16)] 192 ; 3

```

```

PD_BOOST_CURVE_GAIN_D_MAP_VTD [UINT(8),(1,12)] 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 3 ; 0.03
: 11 ; 0.11
: 17 ; 0.17
: 23 ; 0.23
: 27 ; 0.27
: 28 ; 0.28
: 28 ; 0.28
PHASE_VOLTAGE_THRESHOLD_HIGH [INT(16)] 886 ; 3.46
PHASE_VOLTAGE_THRESHOLD_LOW [INT(16)] 253 ; 0.99
PartNumbersDataROM.VM_EcuSoftwareNumber [UINT(8),(1,24)] 66 ; 66
: 66 ; 66
: 53 ; 53
: 51 ; 51
: 45 ; 45
: 49 ; 49
: 52 ; 52
: 68 ; 68
: 48 ; 48
: 48 ; 48
: 51 ; 51
: 45 ; 45
: 65 ; 65
: 69 ; 69
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
Peak_CPU_LoadOtherStates [UINT(16)] 12380 ; 77.38
PlatformTune.BATT_CURRENT_FILTER_COEF_PTD [UINT(16)] 16384 ; 1
PlatformTune.COMP_EAC_INPUT_LIMIT_MAP [UINT(16),(1,4)] 1152 ; 1152
: 1024 ; 1024
: 1024 ; 1024
: 0 ; 0
PlatformTune.COMP_EAC_INPUT_VSPD_MAP [UINT(8),(1,4)] 0 ; 0
: 3 ; 3
: 12 ; 12
: 13 ; 13
PlatformTune.COMP_EAC_OFF_CVEL_THRESH [UINT(16)] 5120 ; 5
PlatformTune.COMP_EAC_OFF_TRQ_THRESH_PTD [UINT(16)] 5120 ; 5
PlatformTune.COMP_EAC_OFF_VSPD_THRESH_PTD [UINT(16)] 768 ; 12
PlatformTune.COMP_EAC_ON_CVEL_THRESH_PTD [UINT(16)] 102 ; 0.1
PlatformTune.COMP_EAC_ON_TRQ_THRESH_PTD [UINT(16)] 3072 ; 3
PlatformTune.COMP_EAC_ON_VSPD_THRESH_PTD [UINT(16)] 768 ; 12
PlatformTune.EAC_CM5_SWSp [UINT(16)] 5120 ; 5
PlatformTune.EAC_FAULT_RECOVERY_A_PTD [UINT(8)] 0 ; 0
PlatformTune.EAC_FAULT_RECOVERY_B_PTD [UINT(8)] 0 ; 0
PlatformTune.EAC_FAULT_RECOVERY_C_PTD [UINT(8)] 0 ; 0
PlatformTune.EAC_FAULT_RECOVERY_D_PTD [UINT(8)] 2 ; 2
PlatformTune.EAC_FAULT_RECOVERY_E_PTD [UINT(8)] 0 ; 0
PlatformTune.EAC_FAULT_RECOVERY_F_PTD [UINT(8)] 0 ; 0
PlatformTune.EAC_FAULT_RECOVERY_G_PTD [UINT(8)] 0 ; 0
PlatformTune.EAC_FAULT_RECOVERY_H_PTD [UINT(8)] 0 ; 0

```

```

                                BGA02812_Taras.PAR
PlatformTune.EAC_Filt_Freq_PTD [UINT(16)] 768 ; 3
PlatformTune.EAC_Filt_Freq_Pos_PTD [UINT(16)] 19200 ; 75
PlatformTune.EAC_MAX_VELOCITY_ERROR_PTD [UINT(16)] 40960 ; 40
PlatformTune.EAC_Max_Available_Current_PTD [UINT(8)] 100 ; 100
PlatformTune.EAC_TORQUE_LIMIT_PTD [INT(16)] 1295 ; 5.08
PlatformTune.EAC_T_ACTIVATE_LIMIT_PTD [INT(16)] 100 ; 100
PlatformTune.EAL_T_PTD [UINT(16)] 2000 ; 2000
PlatformTune.TIRE_CIRCUMFERENCE_PTD [UINT(32),(1,12)] 70411878 ; 70411878
: 70041600 ; 70041600
: 70411878 ; 70411878
: 70411878 ; 70411878
: 71257292 ; 71257292
: 70411878 ; 70411878
: 70411878 ; 70411878
: 70411878 ; 70411878
: 70411878 ; 70411878
: 70411878 ; 70411878
: 70411878 ; 70411878
: 70411878 ; 70411878
: 70411878 ; 70411878
PlatformTuneTB.SaverAM_Copy [UINT(16)] 0 ; FALSE
Power_Stage_Traceability [UINT(8),(1,15)] 49 ; 49
: 48 ; 48
: 50 ; 50
: 53 ; 53
: 54 ; 54
: 49 ; 49
: 56 ; 56
: 48 ; 48
: 55 ; 55
: 66 ; 66
: 51 ; 51
: 48 ; 48
: 48 ; 48
: 49 ; 49
: 70 ; 70
REVERSE_GEAR_ENGAGED [UINT(8)] 0 ; NO_SIGNAL_SELECTED
ReprogRequest [UINT(32)] 305419896 ; NO_REPROG_REQUEST
SAPPFeatureEnabled [UINT(16)] 1 ; ENABLED
SAPP_FEATURE_ENABLED_MASTER [UINT(8)] 1 ; 1
SECTOR_HYSTERESIS [UINT(16)] 210 ; 0.07
SLOW_REINST_TRQ_LIM_UP_SLEW_RATE [UINT(16)] 30 ; 30
STAR_POINT_VOLT_A1_MAX_ERROR [INT(16)] 908 ; 3.55
STAR_POINT_VOLT_C1_MAX_ERROR [INT(16)] 908 ; 3.55
STAR_POINT_VOLT_SUM_MAX_ERROR [INT(16)] 908 ; 3.55
STRAIGHT_AHEAD_CONFIDENCE_LEVEL [INT(16)] 800 ; 25
SVM_SECTOR_HYSTERESIS [UINT(16)] 910 ; 5
SVM_SECTOR_HYSTERESIS_HIGH [UINT(16)] 50 ; 0.05
SVM_SECTOR_HYSTERESIS_LOW [UINT(16)] 15 ; 0.01
SaveNVM_CCP_BLOCK [UINT(16)] 0 ; FALSE
SaveNVM_COMPATIBILITY_ID_A_BLOCK [UINT(16)] 0 ; FALSE
SaveNVM_COMPATIBILITY_ID_B_BLOCK [UINT(16)] 0 ; FALSE
SaveNVM_COMPATIBILITY_ID_C_BLOCK [UINT(16)] 0 ; FALSE
SaveNVM_CONFIGURATION_ID_BLOCK [UINT(16)] 0 ; FALSE
SaveNVM_DEM_BLOCK [UINT(16)] 0 ; FALSE
SaveNVM_ECU_CALIB_BLOCK [UINT(16)] 0 ; FALSE
SaveNVM_EFF_BLOCK [UINT(16)] 0 ; FALSE
SaveNVM_END_OF_LINE_DATA_BLOCK [UINT(16)] 0 ; FALSE
SaveNVM_FEATURE_SWITCH_BLOCK [UINT(16)] 0 ; FALSE
SaveNVM_FREEZE_FRAMES_BLOCK [UINT(16)] 0 ; FALSE
SaveNVM_FRICTION_DETECTION_BLOCK [UINT(16)] 0 ; FALSE
SaveNVM_MAINTENANCE_DATA_BLOCK [UINT(16)] 0 ; FALSE
SaveNVM_MOTOR_TUNE_ID_BLOCK [UINT(16)] 0 ; FALSE
SaveNVM_MULTI_BLOCK [UINT(16)] 1 ; TRUE

```

SaveNVM\_PART\_NUMBERS\_BLOCK [UINT(16)] 0 ; FALSE  
SaveNVM\_PDC\_BLOCK [UINT(16)] 1 ; TRUE  
SaveNVM\_QUICK\_PWR\_DN\_DATA\_BLOCK [UINT(16)] 0 ; FALSE  
SaveNVM\_SAPP\_BLOCK [UINT(16)] 1 ; TRUE  
SaveNVM\_SIZE\_DETECT\_BLOCK [UINT(16)] 0 ; FALSE  
SaveNVM\_SYS\_CALIB\_BLOCK [UINT(16)] 0 ; FALSE  
SaveNVM\_TEMPORARY\_DATA\_BLOCK [UINT(16)] 0 ; FALSE  
SaveNVM\_TIRE\_CIRCUMFERENCE\_BLOCK [UINT(16)] 0 ; FALSE  
SaveNVM\_TM\_BLOCK [UINT(16)] 0 ; FALSE  
SaveNVM\_TRACEABILITY\_NUMBERS\_BLOCK [UINT(16)] 0 ; FALSE  
SaveNVM\_TRQ\_REINST\_BLOCK [UINT(16)] 0 ; FALSE  
SaveNVM\_TRW\_FAULTS\_BLOCK [UINT(16)] 0 ; FALSE  
SaveNVM\_VEHICLE\_ID\_BLOCK [UINT(16)] 0 ; FALSE  
SaveNVM\_VEHICLE\_TUNE\_ID\_BLOCK [UINT(16)] 0 ; FALSE  
SwitchedVoltageFilterConst [UINT(16)] 2730 ; 5  
SysCalib.InverseBallNutBeltEfficiency [UINT(16)] 38552 ; 1.18  
SysCalibTB.SaverAM\_Copy [UINT(16)] 0 ; FALSE  
THERMAL\_EST\_COOLING\_RES [UINT(16)] 7680 ; 30  
THERMAL\_EST\_HEATING\_RES [UINT(16)] 2048 ; 1  
THERMAL\_EST\_THERMAL\_CAP [UINT(16)] 6144 ; 24  
TIRE\_CIRCUMFERENCE\_TABLE [UINT(32),(1,12)] 70411878 ; 70411878  
: 70041600 ; 70041600  
: 70411878 ; 70411878  
: 70411878 ; 70411878  
: 71257292 ; 71257292  
: 70411878 ; 70411878  
: 70411878 ; 70411878  
: 70411878 ; 70411878  
: 70411878 ; 70411878  
: 70411878 ; 70411878  
: 70411878 ; 70411878  
: 70411878 ; 70411878  
: 70411878 ; 70411878  
TM\_NVV.EmuRequestFlag\_NVV [UINT(32)] 0 ; EMULATION\_MODE\_NOT\_REQUESTED  
TM\_NVV.ProductComplete\_NVV [UINT(32)] 0 ; 0  
TORQUE\_DAMPING\_TRQ\_GAIN\_MAP [UINT(8),(1,12)] 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
TORQUE\_DAMPING\_TRQ\_GAIN\_MAP\_VTD [UINT(8),(1,12)] 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
TORQUE\_LIMIT\_DOWN\_SLEW\_RATE [UINT(8)] 50 ; 50  
TORQUE\_LIMIT\_UP\_SLEW\_RATE [UINT(8)] 50 ; 50  
TRQ\_DAMPING\_TRQ\_FILTER\_FREQ\_VTD [UINT(8)] 6 ; 6  
TRQ\_DAMPING\_TRQ\_LWR\_THRESH\_VTD [UINT(16)] 1024 ; 1  
TRQ\_DAMPING\_TRQ\_UPR\_THRESH\_VTD [UINT(16)] 2048 ; 2

```

BGA02812_Taras.PAR
TRQ_DAMPING_TRQ_UPR_TRQ_MULT_VTD [UINT(16)] 60 ; 0.24
TRW_EOL_TRQ_LIMIT_DOWN_SLEW_RATE [UINT(8)] 100 ; 100
TRW_EOL_TRQ_LIMIT_UP_SLEW_RATE [UINT(8)] 100 ; 100
TRW_FaultStore.ClearTRWFaults [UINT(32)] 0 ; 0
UPDATE_EOLT_DATA [UINT(32)] 0 ; 0
UPDATE_TRACEABILITY_NUMBERS [UINT(32)] 0 ; 0
UpdateMotorTuneID [UINT(16)] 0 ; FALSE
UpdateVehicleTuneID [UINT(16)] 0 ; FALSE
VEHICLE_MOVING_THRESHOLD [UINT(16)] 173 ; 2.7
VEHICLE_SPEED_BREAKPOINTS_VTD [UINT(8),(1,12)] 0 ; 0
: 8 ; 8
: 15 ; 15
: 25 ; 25
: 35 ; 35
: 45 ; 45
: 60 ; 60
: 75 ; 75
: 95 ; 95
: 120 ; 120
: 150 ; 150
: 190 ; 190
VM_EcuSoftwareNumber [UINT(8),(1,24)] 66 ; 66
: 66 ; 66
: 53 ; 53
: 51 ; 51
: 45 ; 45
: 49 ; 49
: 52 ; 52
: 68 ; 68
: 48 ; 48
: 48 ; 48
: 51 ; 51
: 45 ; 45
: 65 ; 65
: 69 ; 69
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
vehicleSpeed [UINT(8),(1,12)] 0 ; 0
: 8 ; 8
: 15 ; 15
: 25 ; 25
: 35 ; 35
: 45 ; 45
: 60 ; 60
: 75 ; 75
: 95 ; 95
: 120 ; 120
: 150 ; 150
: 190 ; 190
VehicleTune.ATF2_A0_VTD [UINT(16)] 16384 ; 16384
VehicleTune.ATF2_A1_MAP_VTD [UINT(16),(1,5)] 27301 ; 27301
: 27293 ; 27293
: 27285 ; 27285
: 27285 ; 27285
: 27277 ; 27277

```

BGA02812\_Taras.PAR

```

VehicleTune.ATF2_A2_MAP_VTD [UINT(16),(1,5)] 10939 ; 10939
: 10933 ; 10933
: 10928 ; 10928
: 10928 ; 10928
: 10923 ; 10923
VehicleTune.ATF2_B0_MAP_VTD [UINT(16),(1,5)] 14025 ; 14025
: 15774 ; 15774
: 17522 ; 17522
: 17522 ; 17522
: 19270 ; 19270
VehicleTune.ATF2_B1_MAP_VTD [UINT(16),(1,5)] 26950 ; 26950
: 30311 ; 30311
: 33670 ; 33670
: 33670 ; 33670
: 37028 ; 37028
VehicleTune.ATF2_B2_MAP_VTD [UINT(16),(1,5)] 12947 ; 12947
: 14561 ; 14561
: 16175 ; 16175
: 16175 ; 16175
: 17788 ; 17788
VehicleTune.ATF2_VEHICLE_SPEED_MAP_VTD [UINT(8),(1,5)] 0 ; 0
: 5 ; 5
: 10 ; 10
: 15 ; 15
: 20 ; 20
VehicleTune.BLENDING_FILTER_FREQ_MAP_VTD [UINT(8),(1,12)] 80 ; 8
: 88 ; 8.8
: 98 ; 9.8
: 110 ; 11
: 123 ; 12.3
: 130 ; 13
: 135 ; 13.5
: 136 ; 13.6
: 137 ; 13.7
: 138 ; 13.8
: 138 ; 13.8
: 138 ; 13.8
VehicleTune.CHARGING_SYS_CHG_FLT_TIME [UINT(16)] 500 ; 500
VehicleTune.COMP_EAC_A1_VTD [UINT(16)] 13650 ; 13650
VehicleTune.COMP_EAC_A2_VTD [UINT(16)] 5470 ; 5470
VehicleTune.COMP_EAC_B0_VTD [UINT(16)] 7013 ; 7013
VehicleTune.COMP_EAC_B1_VTD [UINT(16)] 13475 ; 13475
VehicleTune.COMP_EAC_B2_VTD [UINT(16)] 6474 ; 6474
VehicleTune.COMP_EAC_BOOST_GAIN_VTD [INT(16)] 160 ; 20
VehicleTune.COMP_EAC_MODE_IN_TIME_VTD [UINT(16)] 200 ; 0.2
VehicleTune.COMP_EAC_MODE_OUT_TIME_VTD [UINT(16)] 200 ; 0.2
VehicleTune.COMP_EAC_TRQ_FILTER_FREQ_VTD [UINT(16)] 640 ; 2.5
VehicleTune.D0_DAMPING_TORQUE_DEADBAND_VTD [INT(16)] 0 ; 0
VehicleTune.D1Q_DAMPING_TRQ_GAIN_MAP_VTD [UINT(8),(1,12)] 18 ; 1.8
: 18 ; 1.8
: 19 ; 1.9
: 20 ; 2
: 21 ; 2.1
: 22 ; 2.2
: 24 ; 2.4
: 26 ; 2.6
: 29 ; 2.9
: 32 ; 3.2
: 35 ; 3.5
: 37 ; 3.7
VehicleTune.D1_DAMPING_TRQ_GAIN_MAP_VTD [UINT(8),(1,12)] 0 ; 0
: 0 ; 0
: 0 ; 0

```

BGA02812\_Taras.PAR

```

: 0 ; 0
: 7 ; 0.7
: 17 ; 1.7
: 39 ; 3.9
: 64 ; 6.4
: 91 ; 9.1
: 116 ; 11.6
: 139 ; 13.9
: 156 ; 15.6
VehicleTune.D2_DAMPING_TRQ_MAX_MAP_VTD [UINT(8),(1,12)] 85 ; 8.5
: 85 ; 8.5
: 85 ; 8.5
: 86 ; 8.6
: 88 ; 8.8
: 90 ; 9
: 94 ; 9.4
: 97 ; 9.7
: 100 ; 10
: 102 ; 10.2
: 103 ; 10.3
: 103 ; 10.3
VehicleTune.D3_DMP_TRQ_MULT_LWR_THRESH_VTD [UINT(16)] 819 ; 0.8
VehicleTune.D4_DMP_TRQ_MULT_UPR_THRESH_VTD [UINT(16)] 3277 ; 3.2
VehicleTune.D5_DMP_TRQ_MULT_FILT_FREQ_VTD [UINT(8)] 200 ; 20
VehicleTune.D6_DMP_TRQ_DIFF_FLT_FREQ_VTD [UINT(8)] 255 ; 25.5
VehicleTune.D7_DMP_TRQ_DIFF_MULT_LWR_THRESH [UINT(8)] 250 ; 250
VehicleTune.D8_DMP_TRQ_DIFF_MULT_UPR_THRESH [UINT(8)] 255 ; 255
VehicleTune.DEF_VEHICLE_SPEED [UINT(16)] 6400 ; 50
VehicleTune.EAC_CM3_MVS_VTD [UINT(16)] 192 ; 3
VehicleTune.EAC_CM3_SWSp_VTD [UINT(16)] 51 ; 0.05
VehicleTune.EAC_CM3_SWT_VTD [UINT(16)] 1024 ; 1
VehicleTune.EAC_CM3_dSWA_VTD [UINT(16)] 455 ; 10
VehicleTune.EAC_CM5_MVS_VTD [UINT(16)] 704 ; 11
VehicleTune.EAC_CM5_SWT_VTD [UINT(16)] 3581 ; 3.5
VehicleTune.EAC_CM5_dSWA_VTD [UINT(16)] 5461 ; 119.99
VehicleTune.EAC_GD_VTD [UINT(16)] 15360 ; 15
VehicleTune.EAC_GF_VTD [UINT(16)] 1024 ; 1
VehicleTune.EAC_ING_VTD [UINT(16)] 1311 ; 0.02
VehicleTune.EAC_KD_VTD [UINT(16)] 9830 ; 1.2
VehicleTune.EAC_KI_VTD [UINT(16)] 0 ; 0
VehicleTune.EAC_KP_VTD [UINT(16)] 12800 ; 100
VehicleTune.EAC_MAX_INTEGRAL_TRQ_VTD [INT(32)] 532676608 ; 127
VehicleTune.EAC_MAX_PROPORTIONAL_TRQ_VTD [INT(32)] 33292288 ; 127
VehicleTune.EAC_T_SAPP_in_VTD [INT(16)] 500 ; 0.5
VehicleTune.EAC_T_SAPP_out_VTD [INT(16)] 200 ; 0.2
VehicleTune.EAL_SWA_LIMIT_VTD [UINT(16)] 21825 ; 479.55
VehicleTune.EAL_SWA_MARGIN_VTD [UINT(16)] 227 ; 4.99
VehicleTune.ENGINE_STOPPED_HELD_DELAY_VTD [UINT(16)] 0 ; 0
VehicleTune.ENGINE_STOPPED_HELD_TORQUE_VTD [UINT(8)] 0 ; 0
VehicleTune.ENG_SPEED_CRANKING_RPM [UINT(16)] 1200 ; 1200
VehicleTune.ENG_SPEED_RUNNING_RPM [UINT(16)] 2000 ; 2000
VehicleTune.ENG_STALLED_INITIATION_TIME_VTD [UINT(16)] 0 ; 0
VehicleTune.ENG_STATUS_CHG_FLT_TIME [UINT(16)] 50 ; 50
VehicleTune.ENG_STL_TRQ_LMT_DN_SLEW_RATE_VTD [UINT(8)] 30 ; 30
VehicleTune.ENG_STL_TRQ_LMT_UP_SLEW_RATE_VTD [UINT(8)] 100 ; 100
VehicleTune.FP_ACCEL_CUTOFF_VTD [UINT(16)] 1024 ; 1
VehicleTune.FP_ACCEL_FILTER_BETA_VTD [UINT(16)] 9911 ; 0.6049
VehicleTune.FP_COLUMN_TORQUE_MAX_VTD [UINT(16)] 2048 ; 8
VehicleTune.FP_DRIVESTAGE_TEMP_FAULT_TIME [UINT(16)] 30000 ; 600
VehicleTune.FP_FRICTION_BOUND_AXIS_VTD [UINT(16),(1,2)] 0 ; 0
: 3000 ; 3000
VehicleTune.FP_HIGH_SPEED_CUTOFF_VTD [UINT(16)] 1000 ; 125
VehicleTune.FP_LAT_ACCEL_2_LOAD_MAP_VTD [UINT(16),(1,2)] 6195 ; 774.38

```



BGA02812\_Taras.PAR

```

: 5200 ; 650
VehicleTune.FP_LAT_ACCEL_CUTOFF_VTD [UINT(16)] 448 ; 1.75
VehicleTune.FP_LAT_ACCEL_ERROR_VTD [UINT(16)] 800 ; 0.5
VehicleTune.FP_LAT_ACC_FILTER_BETA_VTD [UINT(16)] 14449 ; 0.8819
VehicleTune.FP_LOAD_MEAS_FILTER_BETA_VTD [UINT(16)] 15581 ; 0.951
VehicleTune.FP_LOAD_PRED_FILTER_BETA_VTD [UINT(16)] 15581 ; 0.951
VehicleTune.FP_LOW_SPEED_CUTOFF_VTD [UINT(16)] 360 ; 45
VehicleTune.FP_MINTEMP_VTD [INT(16)] 0 ; 0
VehicleTune.FP_MIN_STABLE_TIME_VTD [UINT(16)] 50 ; 50
VehicleTune.FP_ONE_OVER_PINION_VTD [UINT(16)] 14588 ; 113.9688
VehicleTune.FP_PDC_GAIN_VTD [UINT(16)] 256 ; 1
VehicleTune.FP_SW_VEL_CUTOFF_VTD [UINT(16)] 600 ; 75
VehicleTune.FP_SW_VEL_FILTER_BETA_VTD [UINT(16)] 5995 ; 0.3659
VehicleTune.FP_UPPER_FRICTION_BOUND_VTD [UINT(16),(1,2)] 950 ; 950
: 950 ; 950
VehicleTune.FP_UP_DOWN_COUNTER_THRESHOLD_VTD [UINT(16)] 15 ; 15
VehicleTune.FP_UP_DOWN_LIMIT_VTD [UINT(16)] 200 ; 200
VehicleTune.FP_VSPD_GAIN_MAP_VTD [UINT(8),(1,2)] 45 ; 45
: 75 ; 75
VehicleTune.FP_VSPD_GAIN_VTD [UINT(16),(1,2)] 1352 ; 1.32
: 1147 ; 1.12
VehicleTune.FP_VSPD_LAT_MAP_VTD [UINT(8),(1,2)] 50 ; 50
: 120 ; 120
VehicleTune.FRICTION_THRESHOLD_VTD [UINT(16)] 4 ; 4
VehicleTune.HFAC_GAIN_MAP_VTD [UINT(8),(1,120)] 109 ; 54.5
: 116 ; 58
: 119 ; 59.5
: 121 ; 60.5
: 123 ; 61.5
: 127 ; 63.5
: 132 ; 66
: 135 ; 67.5
: 139 ; 69.5
: 144 ; 72
: 83 ; 41.5
: 90 ; 45
: 93 ; 46.5
: 95 ; 47.5
: 97 ; 48.5
: 101 ; 50.5
: 106 ; 53
: 109 ; 54.5
: 113 ; 56.5
: 118 ; 59
: 72 ; 36
: 79 ; 39.5
: 82 ; 41
: 84 ; 42
: 86 ; 43
: 90 ; 45
: 95 ; 47.5
: 98 ; 49
: 102 ; 51
: 107 ; 53.5
: 60 ; 30
: 67 ; 33.5
: 70 ; 35
: 72 ; 36
: 74 ; 37
: 78 ; 39
: 83 ; 41.5
: 86 ; 43
: 90 ; 45

```

BGA02812\_Taras.PAR

: 95 ; 47.5  
: 52 ; 26  
: 59 ; 29.5  
: 62 ; 31  
: 64 ; 32  
: 66 ; 33  
: 70 ; 35  
: 75 ; 37.5  
: 78 ; 39  
: 82 ; 41  
: 87 ; 43.5  
: 45 ; 22.5  
: 52 ; 26  
: 55 ; 27.5  
: 57 ; 28.5  
: 59 ; 29.5  
: 63 ; 31.5  
: 68 ; 34  
: 71 ; 35.5  
: 75 ; 37.5  
: 80 ; 40  
: 40 ; 20  
: 47 ; 23.5  
: 50 ; 25  
: 52 ; 26  
: 54 ; 27  
: 58 ; 29  
: 63 ; 31.5  
: 66 ; 33  
: 70 ; 35  
: 75 ; 37.5  
: 33 ; 16.5  
: 40 ; 20  
: 43 ; 21.5  
: 45 ; 22.5  
: 47 ; 23.5  
: 51 ; 25.5  
: 56 ; 28  
: 59 ; 29.5  
: 63 ; 31.5  
: 70 ; 35  
: 31 ; 15.5  
: 38 ; 19  
: 41 ; 20.5  
: 43 ; 21.5  
: 45 ; 22.5  
: 49 ; 24.5  
: 54 ; 27  
: 57 ; 28.5  
: 61 ; 30.5  
: 68 ; 34  
: 30 ; 15  
: 37 ; 18.5  
: 40 ; 20  
: 42 ; 21  
: 44 ; 22  
: 48 ; 24  
: 53 ; 26.5  
: 56 ; 28  
: 60 ; 30  
: 65 ; 32.5  
: 29 ; 14.5  
: 36 ; 18

BGA02812\_Taras.PAR

: 39 ; 19.5  
: 41 ; 20.5  
: 43 ; 21.5  
: 47 ; 23.5  
: 52 ; 26  
: 55 ; 27.5  
: 59 ; 29.5  
: 64 ; 32  
: 28 ; 14  
: 35 ; 17.5  
: 38 ; 19  
: 40 ; 20  
: 42 ; 21  
: 46 ; 23  
: 51 ; 25.5  
: 54 ; 27  
: 58 ; 29  
: 63 ; 31.5

VehicleTune.HFAC\_SPD\_BRKPNT\_MAP\_VTD [UINT(8),(1,12)] 0 ; 0

: 8 ; 8  
: 15 ; 15  
: 25 ; 25  
: 35 ; 35  
: 45 ; 45  
: 60 ; 60  
: 75 ; 75  
: 95 ; 95  
: 120 ; 120  
: 150 ; 150  
: 190 ; 190

VehicleTune.HFAC\_TRQ\_BRKPNT\_MAP\_VTD [UINT(8),(1,10)] 0 ; 0

: 5 ; 0.5  
: 10 ; 1  
: 15 ; 1.5  
: 20 ; 2  
: 25 ; 2.5  
: 30 ; 3  
: 35 ; 3.5  
: 45 ; 4.5  
: 60 ; 6

VehicleTune.HSD0\_COLUMN\_VELOCITY\_MAP\_VTD [INT(16),(1,12)] 2253 ; 2.2

: 2765 ; 2.7  
: 3277 ; 3.2  
: 3789 ; 3.7  
: 4301 ; 4.2  
: 4813 ; 4.7  
: 5325 ; 5.2  
: 5837 ; 5.7  
: 5837 ; 5.7  
: 5837 ; 5.7  
: 5837 ; 5.7  
: 5837 ; 5.7

VehicleTune.HSD1\_DAMPING\_TORQUE\_GAIN\_MAP\_VTD [INT(16),(1,12)] 100 ; 100

: 75 ; 75  
: 50 ; 50  
: 25 ; 25  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0

BGA02812\_Taras.PAR

```
: 0 ; 0
VehicleTune.HSD2_MAX_HIGH_SPEED_DAMPING_VTD [UINT(8),(1,12)] 106 ; 106
: 106 ; 106
: 106 ; 106
: 106 ; 106
: 106 ; 106
: 106 ; 106
: 106 ; 106
: 106 ; 106
: 106 ; 106
: 106 ; 106
: 106 ; 106
: 106 ; 106
: 106 ; 106
VehicleTune.NOMINAL_TIRE_PRESSURE_VTD [UINT(16)] 0 ; 0
VehicleTune.ONE_MIN_EXP_FP_THERM_FILTER_TC_VTD [INT(32)] 58 ; 58
VehicleTune.P0_BOOST_CURVE_Q1_START_MAP_VTD [UINT(8),(1,12)] 1 ; 0.05
: 2 ; 0.1
: 3 ; 0.15
: 4 ; 0.2
: 5 ; 0.25
: 7 ; 0.35
: 9 ; 0.45
: 11 ; 0.55
: 13 ; 0.65
: 14 ; 0.7
: 15 ; 0.75
: 16 ; 0.8
VehicleTune.P1_BOOST_CURVE_Q1_WIDTH_MAP_VTD [UINT(8),(1,12)] 18 ; 0.9
: 24 ; 1.2
: 25 ; 1.25
: 25 ; 1.25
: 25 ; 1.25
: 24 ; 1.2
: 23 ; 1.15
: 22 ; 1.1
: 21 ; 1.05
: 20 ; 1
: 20 ; 1
: 20 ; 1
VehicleTune.P2_BOOST_CURVE_Q1_GAIN_MAP_VTD [UINT(8),(1,12)] 180 ; 9
: 130 ; 6.5
: 96 ; 4.8
: 82 ; 4.1
: 77 ; 3.85
: 75 ; 3.75
: 74 ; 3.7
: 73 ; 3.65
: 73 ; 3.65
: 72 ; 3.6
: 71 ; 3.55
: 70 ; 3.5
VehicleTune.P3_BOOST_CURVE_Q2_START_MAP_VTD [UINT(8),(1,12)] 20 ; 1
: 27 ; 1.35
: 29 ; 1.45
: 30 ; 1.5
: 31 ; 1.55
: 32 ; 1.6
: 33 ; 1.65
: 34 ; 1.7
: 35 ; 1.75
: 36 ; 1.8
: 37 ; 1.85
: 38 ; 1.9
```

BGA02812\_Taras.PAR

```

VehicleTune.P4_BOOST_CURVE_Q2_WIDTH_MAP_VTD [UINT(8),(1,12)] 20 ; 1
: 22 ; 1.1
: 25 ; 1.25
: 29 ; 1.45
: 34 ; 1.7
: 40 ; 2
: 48 ; 2.4
: 56 ; 2.8
: 63 ; 3.15
: 70 ; 3.5
: 77 ; 3.85
: 81 ; 4.05
VehicleTune.P5_BOOST_CURVE_Q2_GAIN_MAP_VTD [UINT(8),(1,12)] 179 ; 35.8
: 176 ; 35.2
: 169 ; 33.8
: 160 ; 32
: 151 ; 30.2
: 140 ; 28
: 123 ; 24.6
: 105 ; 21
: 85 ; 17
: 73 ; 14.6
: 67 ; 13.4
: 62 ; 12.4
VehicleTune.PDC_COL_ANGLE_MAX_VTD [UINT(16)] 228 ; 5.01
VehicleTune.PDC_COL_TRQ_MAX_VTD [UINT(8)] 80 ; 2.5
VehicleTune.PDC_COL_TRQ_MIN_VTD [UINT(8)] 26 ; 0.2
VehicleTune.PDC_ColumnTorqueFrequency [UINT(16)] 37 ; 0.07
VehicleTune.PDC_LIMIT [UINT(8)] 48 ; 1.5
VehicleTune.PDC_MaxRateLimit [INT(32)] 262 ; 1
VehicleTune.PDC_REPAIR_LOWER_THRESHOLD [UINT(8)] 16 ; 0.5
VehicleTune.PDC_REPAIR_UPPER_THRESHOLD [UINT(8)] 3 ; 0.09
VehicleTune.PDC_TIMER [UINT(16)] 500 ; 2
VehicleTune.PDC_TIME_CONSTANT_VTD [UINT(16)] 60 ; 30
VehicleTune.PDC_VSPD_HIGHER_GAIN_THRESHOLD [UINT(16)] 2600 ; 40
VehicleTune.PDC_VSPD_LOWER_GAIN [UINT(16)] 0 ; 0
VehicleTune.PDC_VSPD_LOWER_GAIN_THRESHOLD [UINT(16)] 640 ; 10
VehicleTune.PDC_VSPD_MAX [INT(16)] 12800 ; 200
VehicleTune.PDC_VSPD_MIN [INT(16)] 2560 ; 40
VehicleTune.PDC_VSPD_ZERO_GAIN_THRESHOLD [UINT(16)] 192 ; 3
VehicleTune.PD_BOOST_CURVE_GAIN_D_MAP_VTD [UINT(8),(1,12)] 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 3 ; 0.03
: 11 ; 0.11
: 17 ; 0.17
: 23 ; 0.23
: 27 ; 0.27
: 28 ; 0.28
: 28 ; 0.28
VehicleTune.SLOW_REINST_TRQ_LIM_UP_SLEW_RATE [UINT(16)] 30 ; 30
VehicleTune.SLOW_TRQ_REINST_ENG_RUN_CHK_TIME [UINT(16)] 50 ; 50
VehicleTune.SLOW_TRQ_REINST_LIMIT_THRESH [UINT(8)] 5 ; 5
VehicleTune.SQRT_FP_UNDER_STEER_COEF_VTD [UINT(16)] 16 ; 0.0625
VehicleTune.TIRE_PRESSURE_TOLERANCE [UINT(8)] 0 ; 0
VehicleTune.TORQUE_DAMPING_TRQ_GAIN_MAP_VTD [UINT(8),(1,12)] 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0

```

BGA02812\_Taras.PAR

```

: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
VehicleTune.TRQ_DAMPING_TRQ_FILTER_FREQ_VTD [UINT(8)] 6 ; 6
VehicleTune.TRQ_DAMPING_TRQ_LWR_THRESH_VTD [UINT(16)] 1024 ; 1
VehicleTune.TRQ_DAMPING_TRQ_UPR_THRESH_VTD [UINT(16)] 2048 ; 2
VehicleTune.TRQ_DAMPING_TRQ_UPR_TRQ_MULT_VTD [UINT(16)] 60 ; 0.24
VehicleTune.USE_LAST_JOURNEY_PDC_VTD [UINT(8)] 0 ; 0
VehicleTune.VEHICLE_MOVING_THRESHOLD [UINT(16)] 173 ; 1.35
VehicleTune.VEHICLE_SPEED_BREAKPOINTS_VTD [UINT(8),(1,12)] 0 ; 0
: 8 ; 8
: 15 ; 15
: 25 ; 25
: 35 ; 35
: 45 ; 45
: 60 ; 60
: 75 ; 75
: 95 ; 95
: 120 ; 120
: 150 ; 150
: 190 ; 190
VehicleTune.WHEEL_BASE_VTD [UINT(16)] 6130 ; 2.993
VehicleTuneID_NVCopy [UINT(16)] 3 ; 3
VehicleTuneID_NVV [UINT(16)] 3 ; VEHICLE_TUNE_3
VehicleTuneTB.SaveRAM_Copy [UINT(16)] 0 ; FALSE
reverseGearSignalSelected [UINT(8)] 0 ; NO_SIGNAL_SELECTED
sAssistanceController.NVM_Data.PDC_Initial_Torque_Value [INT(32)] 0 ; 0
sAssistanceController.NVM_Data.Pdc_Enabled [UINT(8)] 1 ; 1
SEAC_AssistMode.EAC_NVM_Data.EAC_ABSOLUTE_ANGLE_SELECTOR [UINT(8)] 0 ; 0
SEAC_AssistMode.EAC_NVM_Data.EAC_LIC_COUNTER [INT(16)] 0 ; 0
SEAC_AssistMode.EAC_NVM_Data.REVERSE_GEAR_SELECTED [UINT(8)] 0 ; NO_SIGNAL_SELECTED
SEAC_AssistMode.EAC_NVM_Data.SAPP_FEATURE_ENABLED_MASTER [UINT(8)] 1 ; 1
SEAC_PositionFilter.EACAbsoluteAngleSelector [UINT(16)] 0 ; EAC_ANGLE_SELECTED
SEFF_Buffer [UINT(8),(1312,1)] 0 ; 0
: 0 ; 0
: 36 ; 36
: 0 ; 0
: 58 ; 58
: 11 ; 11
: 1 ; 1
: 0 ; 0
: 3 ; 3
: 1 ; 1
: 3 ; 3
: 1 ; 1
: 236 ; 236
: 0 ; 0
: 150 ; 150
: 44 ; 44
: 26 ; 26
: 0 ; 0
: 148 ; 148
: 119 ; 119
: 3 ; 3
: 0 ; 0
: 215 ; 215
: 33 ; 33
: 0 ; 0
: 0 ; 0
: 106 ; 106

```

: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 129 ; 129  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 3 ; 3  
: 0 ; 0  
: 1 ; 1  
: 0 ; 0  
: 0 ; 0  
: 1 ; 1  
: 0 ; 0  
: 48 ; 48  
: 6 ; 6  
: 83 ; 83  
: 50 ; 50  
: 1 ; 1  
: 1 ; 1  
: 0 ; 0  
: 0 ; 0  
: 150 ; 150  
: 44 ; 44  
: 23 ; 23  
: 0 ; 0  
: 26 ; 26  
: 0 ; 0  
: 97 ; 97  
: 71 ; 71  
: 0 ; 0  
: 0 ; 0  
: 215 ; 215  
: 33 ; 33  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 1 ; 1  
: 3 ; 3  
: 0 ; 0  
: 231 ; 231  
: 9 ; 9  
: 196 ; 196  
: 248 ; 248  
: 188 ; 188  
: 252 ; 252  
: 88 ; 88  
: 14 ; 14  
: 87 ; 87  
: 1 ; 1  
: 142 ; 142  
: 48 ; 48  
: 179 ; 179  
: 231 ; 231  
: 231 ; 231  
: 9 ; 9  
: 182 ; 182  
: 12 ; 12  
: 43 ; 43  
: 5 ; 5  
: 168 ; 168  
: 97 ; 97

: 1 ; 1  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 3 ; 3  
: 0 ; 0  
: 2 ; 2  
: 0 ; 0  
: 31 ; 31  
: 5 ; 5  
: 169 ; 169  
: 9 ; 9  
: 65 ; 65  
: 248 ; 248  
: 203 ; 203  
: 252 ; 252  
: 92 ; 92  
: 14 ; 14  
: 87 ; 87  
: 1 ; 1  
: 142 ; 142  
: 48 ; 48  
: 156 ; 156  
: 232 ; 232  
: 169 ; 169  
: 9 ; 9  
: 148 ; 148  
: 255 ; 255  
: 49 ; 49  
: 5 ; 5  
: 168 ; 168  
: 97 ; 97  
: 1 ; 1  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 3 ; 3  
: 0 ; 0  
: 2 ; 2  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 75 ; 75  
: 9 ; 9  
: 166 ; 166  
: 247 ; 247  
: 242 ; 242  
: 252 ; 252  
: 119 ; 119  
: 14 ; 14  
: 87 ; 87  
: 1 ; 1  
: 142 ; 142  
: 48 ; 48  
: 51 ; 51  
: 230 ; 230  
: 75 ; 75  
: 9 ; 9  
: 228 ; 228  
: 11 ; 11  
: 54 ; 54  
: 5 ; 5  
: 168 ; 168



```
: 97 ; 97
: 1 ; 1
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 3 ; 3
: 0 ; 0
: 2 ; 2
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 254 ; 254
: 13 ; 13
: 1 ; 1
: 0 ; 0
: 4 ; 4
: 0 ; 0
: 4 ; 4
: 0 ; 0
: 0 ; 0
: 134 ; 134
: 2 ; 2
: 0 ; 0
: 133 ; 133
: 14 ; 14
: 1 ; 1
: 0 ; 0
: 4 ; 4
: 0 ; 0
: 4 ; 4
: 0 ; 0
: 0 ; 0
: 134 ; 134
: 2 ; 2
: 0 ; 0
: 162 ; 162
: 14 ; 14
: 1 ; 1
: 0 ; 0
: 4 ; 4
: 0 ; 0
: 4 ; 4
: 0 ; 0
: 0 ; 0
: 134 ; 134
: 2 ; 2
: 0 ; 0
: 196 ; 196
: 0 ; 0
: 185 ; 185
: 14 ; 14
: 254 ; 254
: 13 ; 13
: 3 ; 3
: 0 ; 0
: 246 ; 246
: 13 ; 13
: 244 ; 244
: 13 ; 13
: 114 ; 114
: 10 ; 10
: 37 ; 37
: 10 ; 10
```







```
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 1 ; 1
: 13 ; 13
: 36 ; 36
: 77 ; 77
: 18 ; 18
: 78 ; 78
: 127 ; 127
: 255 ; 255
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 1 ; 1
: 0 ; 0
: 110 ; 110
: 144 ; 144
: 53 ; 53
: 0 ; 0
: 219 ; 219
: 1 ; 1
: 43 ; 43
: 5 ; 5
: 58 ; 58
: 2 ; 2
: 255 ; 255
: 200 ; 200
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 3 ; 3
: 255 ; 255
: 200 ; 200
: 0 ; 0
: 0 ; 0
: 0 ; 0
```



```
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 30 ; 30
: 120 ; 120
: 127 ; 127
: 255 ; 255
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 127 ; 127
: 118 ; 118
: 44 ; 44
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 2 ; 2
: 0 ; 0
: 10 ; 10
: 0 ; 0
: 2 ; 2
: 21 ; 21
: 0 ; 0
: 0 ; 0
: 169 ; 169
: 250 ; 250
: 4 ; 4
: 0 ; 0
: 2 ; 2
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 121 ; 121
: 149 ; 149
: 10 ; 10
: 0 ; 0
: 2 ; 2
: 255 ; 255
: 0 ; 0
: 0 ; 0
: 153 ; 153
: 235 ; 235
: 11 ; 11
: 0 ; 0
: 2 ; 2
: 3 ; 3
```

: 0 ; 0  
: 0 ; 0  
: 73 ; 73  
: 26 ; 26  
: 0 ; 0  
: 0 ; 0  
: 2 ; 2  
: 35 ; 35  
: 0 ; 0  
: 0 ; 0  
: 65 ; 65  
: 15 ; 15  
: 0 ; 0  
: 0 ; 0  
: 2 ; 2  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 145 ; 145  
: 153 ; 153  
: 1 ; 1  
: 0 ; 0  
: 2 ; 2  
: 46 ; 46  
: 0 ; 0  
: 0 ; 0  
: 233 ; 233  
: 253 ; 253  
: 2 ; 2  
: 0 ; 0  
: 2 ; 2  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 145 ; 145  
: 147 ; 147  
: 3 ; 3  
: 0 ; 0  
: 2 ; 2  
: 0 ; 0  
: 10 ; 10  
: 0 ; 0  
: 2 ; 2  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 121 ; 121  
: 149 ; 149  
: 10 ; 10  
: 0 ; 0  
: 2 ; 2  
: 255 ; 255  
: 0 ; 0  
: 0 ; 0  
: 153 ; 153  
: 235 ; 235  
: 11 ; 11  
: 0 ; 0  
: 58 ; 58  
: 27 ; 27  
: 0 ; 0  
: 0 ; 0  
: 133 ; 133



: 75 ; 75  
: 0 ; 0  
: 0 ; 0  
: 2 ; 2  
: 35 ; 35  
: 0 ; 0  
: 0 ; 0  
: 65 ; 65  
: 15 ; 15  
: 0 ; 0  
: 0 ; 0  
: 2 ; 2  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 145 ; 145  
: 153 ; 153  
: 1 ; 1  
: 0 ; 0  
: 2 ; 2  
: 46 ; 46  
: 0 ; 0  
: 0 ; 0  
: 233 ; 233  
: 253 ; 253  
: 2 ; 2  
: 0 ; 0  
: 2 ; 2  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 145 ; 145  
: 147 ; 147  
: 3 ; 3  
: 0 ; 0  
: 2 ; 2  
: 21 ; 21  
: 0 ; 0  
: 0 ; 0  
: 169 ; 169  
: 250 ; 250  
: 4 ; 4  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 64 ; 64  
: 0 ; 0  
: 102 ; 102  
: 3 ; 3  
: 0 ; 0  
: 0 ; 0  
: 68 ; 68  
: 2 ; 2  
: 0 ; 0  
: 0 ; 0  
: 102 ; 102  
: 1 ; 1  
: 0 ; 0  
: 0 ; 0  
: 70 ; 70  
: 2 ; 2  
: 0 ; 0  
: 0 ; 0

```
: 102 ; 102
: 1 ; 1
: 0 ; 0
: 0 ; 0
: 75 ; 75
: 2 ; 2
: 0 ; 0
: 0 ; 0
: 102 ; 102
: 7 ; 7
: 0 ; 0
: 0 ; 0
: 72 ; 72
: 2 ; 2
: 0 ; 0
: 0 ; 0
: 102 ; 102
: 1 ; 1
: 0 ; 0
: 0 ; 0
: 74 ; 74
: 2 ; 2
: 0 ; 0
: 0 ; 0
: 102 ; 102
: 3 ; 3
: 0 ; 0
: 0 ; 0
: 67 ; 67
: 2 ; 2
: 0 ; 0
: 0 ; 0
: 102 ; 102
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 70 ; 70
: 2 ; 2
: 0 ; 0
: 0 ; 0
: 18 ; 18
: 1 ; 1
: 0 ; 0
: 0 ; 0
: 4 ; 4
: 126 ; 126
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 16 ; 16
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
```

```
: 0 ; 0
: 00 ; 00
: 00 ; 00
: 00 ; 00
: 00 ; 00
: 00 ; 00
: 00 ; 00
: 00 ; 00
: 00 ; 00
: 00 ; 00
: 00 ; 00
: 00 ; 00
: 00 ; 00
: 00 ; 00
: 00 ; 00
: 00 ; 00
: 00 ; 00
: 00 ; 00
: 00 ; 00
: 00 ; 00
: 00 ; 00
: 00 ; 00
: 00 ; 00
: 00 ; 00
: 16 ; 16
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 16 ; 16
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 16 ; 16
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 16 ; 16
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 16 ; 16
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 16 ; 16
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
```













```
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 128 ; 128
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 16 ; 16
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 16 ; 16
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 1 ; 1
: 0 ; 0
: 0 ; 0
: 16 ; 16
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
```



```
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 16 ; 16
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 16 ; 16
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
sEFF_Manager.ClearEFFData [UINT(32)] 0 ; 0
sEndOfLineData.NVM_Data.EcuEoltTestPassed [UINT(8)] 85 ; 85
sEndOfLineData.NVM_Data.EcuEoltRejectCode [UINT(8)] 0 ; 0
sEndOfLineData.NVM_Data.EppEoltTestPassed [UINT(8)] 85 ; 85
sEndOfLineData.NVM_Data.EppEoltRejectCode [UINT(8)] 0 ; 0
sEndOfLineData.NVM_Data.EpsEoltFunctionTestIndicator [UINT(8)] 0 ; 0
sEndOfLineData.NVM_Data.EpsEoltRejectCode [UINT(8)] 0 ; 0
sEndOfLineData.NVM_Data.EpsEoltTestStatus [UINT(8)] 128 ; 128
sEndOfLineData.NVM_Data.EpsToEccCommsIndicator [UINT(8)] 1 ; 1
sEndOfLineData.NVM_Data.SpareBytes [UINT(8),(1,2)] 0 ; 0
: 0 ; 0
sEndOfLineData.UpdateNVM_Request [UINT(32)] 0 ; 0
sFeatureSwitch.CCP_RequestedSAPPVehicleMode [UINT(32)] 0 ; 0
sFeatureSwitch.TRWModeEnableSAPPStatus_NVV [UINT(16)] 0 ; DISABLED
sManufacturingServices.ManufacturingResetRequest [UINT(32)] 0 ; 0
sMotorCurrentDemand.CurrentControlTestModeActive [UINT(16)] 0 ; FALSE
sMotorCurrentDemand.TestCurrentDemand [INT(16)] 0 ; 0
sMotorPositionSensor.ElectricalPositionOffset [INT(16)] 0 ; 0
sPartNumbers.NVM_Data.ecuDeliveryAssemblyNumber [UINT(8),(1,24)] 66 ; 66
: 66 ; 66
: 53 ; 53
: 51 ; 51
: 45 ; 45
: 51 ; 51
: 70 ; 70
: 57 ; 57
: 54 ; 54
: 52 ; 52
: 45 ; 45
: 66 ; 66
: 71 ; 71
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
```

BGA02812\_Taras.PAR

```
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
sPartNumbers.NVM_Data.gearHardwarePartNumber [UINT(8),(1,24)] 66 ; 66
: 66 ; 66
: 53 ; 53
: 51 ; 51
: 45 ; 45
: 51 ; 51
: 50 ; 50
: 48 ; 48
: 48 ; 48
: 45 ; 45
: 66 ; 66
: 71 ; 71
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
sSystemMode.CCP_RequestedMaintenanceMode [UINT(32)] 0 ; 0
STM.SaveTuneDataRequestFlag [UINT(16)] 0 ; CANCEL
sTaskController.CPU_PeakLoad [UINT(16)] 12380 ; 77.38
sTemporaryDataManager.NVM_Data.ccpEnable [UINT(8)] 1 ; 1
sTraceabilityNumbers.NVM_Data.EppTraceabilityNumber [UINT(8),(1,15)] 49 ; 49
: 48 ; 48
: 50 ; 50
: 53 ; 53
: 57 ; 57
: 49 ; 49
: 57 ; 57
: 49 ; 49
: 57 ; 57
: 68 ; 68
: 51 ; 51
: 48 ; 48
: 48 ; 48
: 49 ; 49
: 53 ; 53
sTraceabilityNumbers.NVM_Data.MotorTraceabilityNumber [UINT(8),(1,15)] 66 ; 66
: 65 ; 65
: 70 ; 70
: 48 ; 48
: 68 ; 68
: 50 ; 50
: 52 ; 52
: 50 ; 50
: 50 ; 50
: 49 ; 49
: 48 ; 48
: 52 ; 52
: 50 ; 50
: 48 ; 48
: 0 ; 0
sTraceabilityNumbers.NVM_Data.PaddingByte [UINT(8)] 0 ; 0
```

sTraceabilityNumbers.NVM\_Data.PowerStageTraceabilityNumber [UINT(8),(1,15)] 49 ;  
49

: 48 ; 48  
: 50 ; 50  
: 53 ; 53  
: 54 ; 54  
: 49 ; 49  
: 56 ; 56  
: 48 ; 48  
: 55 ; 55  
: 66 ; 66  
: 51 ; 51  
: 48 ; 48  
: 48 ; 48  
: 49 ; 49  
: 70 ; 70

sTraceabilityNumbers.UpdateNVM\_Request [UINT(32)] 0 ; 0

xDevTune [UINT(8),(1,548)] 244 ; 244

: 209 ; 209  
: 0 ; 0  
: 0 ; 0  
: 7 ; 7  
: 48 ; 48  
: 5 ; 5  
: 48 ; 48  
: 42 ; 42  
: 34 ; 34  
: 208 ; 208  
: 7 ; 7  
: 20 ; 20  
: 55 ; 55  
: 22 ; 22  
: 42 ; 42  
: 102 ; 102  
: 23 ; 23  
: 0 ; 0  
: 0 ; 0  
: 96 ; 96  
: 130 ; 130  
: 59 ; 59  
: 0 ; 0  
: 0 ; 0  
: 24 ; 24  
: 0 ; 0  
: 9 ; 9  
: 0 ; 0  
: 9 ; 9  
: 10 ; 10  
: 0 ; 0  
: 115 ; 115  
: 0 ; 0  
: 128 ; 128  
: 2 ; 2  
: 128 ; 128  
: 12 ; 12  
: 163 ; 163  
: 2 ; 2  
: 100 ; 100  
: 0 ; 0  
: 144 ; 144  
: 51 ; 51  
: 15 ; 15  
: 5 ; 5

: 221 ; 221  
: 4 ; 4  
: 76 ; 76  
: 0 ; 0  
: 25 ; 25  
: 0 ; 0  
: 100 ; 100  
: 0 ; 0  
: 128 ; 128  
: 0 ; 0  
: 200 ; 200  
: 50 ; 50  
: 0 ; 0  
: 240 ; 240  
: 246 ; 246  
: 24 ; 24  
: 120 ; 120  
: 236 ; 236  
: 140 ; 140  
: 60 ; 60  
: 170 ; 170  
: 10 ; 10  
: 16 ; 16  
: 0 ; 0  
: 202 ; 202  
: 0 ; 0  
: 19 ; 19  
: 0 ; 0  
: 40 ; 40  
: 0 ; 0  
: 0 ; 0  
: 16 ; 16  
: 0 ; 0  
: 4 ; 4  
: 144 ; 144  
: 1 ; 1  
: 220 ; 220  
: 5 ; 5  
: 232 ; 232  
: 3 ; 3  
: 25 ; 25  
: 0 ; 0  
: 109 ; 109  
: 0 ; 0  
: 30 ; 30  
: 0 ; 0  
: 30 ; 30  
: 0 ; 0  
: 32 ; 32  
: 28 ; 28  
: 0 ; 0  
: 9 ; 9  
: 0 ; 0  
: 10 ; 10  
: 0 ; 0  
: 20 ; 20  
: 0 ; 0  
: 0 ; 0  
: 192 ; 192  
: 39 ; 39  
: 9 ; 9  
: 0 ; 0  
: 0 ; 0

: 10 ; 10  
: 50 ; 50  
: 0 ; 0  
: 100 ; 100  
: 0 ; 0  
: 0 ; 0  
: 5 ; 5  
: 0 ; 0  
: 4 ; 4  
: 192 ; 192  
: 246 ; 246  
: 60 ; 60  
: 0 ; 0  
: 204 ; 204  
: 87 ; 87  
: 152 ; 152  
: 58 ; 58  
: 51 ; 51  
: 1 ; 1  
: 25 ; 25  
: 0 ; 0  
: 0 ; 0  
: 8 ; 8  
: 0 ; 0  
: 20 ; 20  
: 30 ; 30  
: 100 ; 100  
: 196 ; 196  
: 9 ; 9  
: 50 ; 50  
: 50 ; 50  
: 100 ; 100  
: 100 ; 100  
: 176 ; 176  
: 14 ; 14  
: 205 ; 205  
: 1 ; 1  
: 69 ; 69  
: 50 ; 50  
: 0 ; 0  
: 4 ; 4  
: 96 ; 96  
: 240 ; 240  
: 212 ; 212  
: 48 ; 48  
: 136 ; 136  
: 19 ; 19  
: 140 ; 140  
: 0 ; 0  
: 0 ; 0  
: 50 ; 50  
: 154 ; 154  
: 0 ; 0  
: 192 ; 192  
: 0 ; 0  
: 90 ; 90  
: 1 ; 1  
: 155 ; 155  
: 1 ; 1  
: 0 ; 0  
: 15 ; 15  
: 50 ; 50  
: 0 ; 0

: 191 ; 191  
: 2 ; 2  
: 176 ; 176  
: 0 ; 0  
: 164 ; 164  
: 2 ; 2  
: 169 ; 169  
: 0 ; 0  
: 128 ; 128  
: 0 ; 0  
: 26 ; 26  
: 1 ; 1  
: 240 ; 240  
: 0 ; 0  
: 205 ; 205  
: 44 ; 44  
: 192 ; 192  
: 0 ; 0  
: 128 ; 128  
: 0 ; 0  
: 0 ; 0  
: 2 ; 2  
: 128 ; 128  
: 1 ; 1  
: 160 ; 160  
: 34 ; 34  
: 40 ; 40  
: 0 ; 0  
: 200 ; 200  
: 0 ; 0  
: 64 ; 64  
: 0 ; 0  
: 10 ; 10  
: 0 ; 0  
: 8 ; 8  
: 0 ; 0  
: 60 ; 60  
: 0 ; 0  
: 108 ; 108  
: 2 ; 2  
: 10 ; 10  
: 0 ; 0  
: 88 ; 88  
: 12 ; 12  
: 88 ; 88  
: 12 ; 12  
: 190 ; 190  
: 11 ; 11  
: 77 ; 77  
: 57 ; 57  
: 230 ; 230  
: 0 ; 0  
: 88 ; 88  
: 27 ; 27  
: 4 ; 4  
: 0 ; 0  
: 128 ; 128  
: 0 ; 0  
: 77 ; 77  
: 3 ; 3  
: 4 ; 4  
: 0 ; 0  
: 95 ; 95



: 0 ; 0  
: 140 ; 140  
: 0 ; 0  
: 0 ; 0  
: 1 ; 1  
: 15 ; 15  
: 0 ; 0  
: 136 ; 136  
: 19 ; 19  
: 5 ; 5  
: 0 ; 0  
: 20 ; 20  
: 0 ; 0  
: 200 ; 200  
: 0 ; 0  
: 51 ; 51  
: 0 ; 0  
: 35 ; 35  
: 0 ; 0  
: 100 ; 100  
: 0 ; 0  
: 30 ; 30  
: 0 ; 0  
: 4 ; 4  
: 0 ; 0  
: 30 ; 30  
: 0 ; 0  
: 30 ; 30  
: 0 ; 0  
: 3 ; 3  
: 0 ; 0  
: 30 ; 30  
: 0 ; 0  
: 4 ; 4  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 4 ; 4  
: 0 ; 0  
: 20 ; 20  
: 0 ; 0  
: 150 ; 150  
: 0 ; 0  
: 128 ; 128  
: 2 ; 2  
: 4 ; 4  
: 0 ; 0  
: 20 ; 20  
: 0 ; 0  
: 100 ; 100  
: 0 ; 0  
: 205 ; 205  
: 12 ; 12  
: 100 ; 100  
: 0 ; 0  
: 174 ; 174  
: 14 ; 14  
: 50 ; 50  
: 0 ; 0  
: 50 ; 50  
: 0 ; 0  
: 50 ; 50  
: 0 ; 0

: 50 ; 50  
: 0 ; 0  
: 50 ; 50  
: 0 ; 0  
: 50 ; 50  
: 0 ; 0  
: 50 ; 50  
: 0 ; 0  
: 50 ; 50  
: 0 ; 0  
: 184 ; 184  
: 11 ; 11  
: 232 ; 232  
: 3 ; 3  
: 244 ; 244  
: 1 ; 1  
: 244 ; 244  
: 1 ; 1  
: 220 ; 220  
: 5 ; 5  
: 232 ; 232  
: 3 ; 3  
: 244 ; 244  
: 1 ; 1  
: 244 ; 244  
: 1 ; 1  
: 110 ; 110  
: 0 ; 0  
: 88 ; 88  
: 0 ; 0  
: 60 ; 60  
: 0 ; 0  
: 47 ; 47  
: 0 ; 0  
: 39 ; 39  
: 0 ; 0  
: 34 ; 34  
: 0 ; 0  
: 30 ; 30  
: 0 ; 0  
: 27 ; 27  
: 0 ; 0  
: 25 ; 25  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 16 ; 16  
: 0 ; 0  
: 16 ; 16  
: 0 ; 0  
: 11 ; 11  
: 2 ; 2  
: 0 ; 0  
: 0 ; 0  
: 17 ; 17  
: 0 ; 0  
: 17 ; 17  
: 0 ; 0  
: 10 ; 10  
: 20 ; 20

: 37 ; 37  
: 22 ; 22  
: 1 ; 1  
: 176 ; 176  
: 1 ; 1  
: 15 ; 15  
: 0 ; 0  
: 131 ; 131  
: 0 ; 0  
: 128 ; 128  
: 21 ; 21  
: 32 ; 32  
: 3 ; 3  
: 0 ; 0  
: 0 ; 0  
: 9 ; 9  
: 0 ; 0  
: 9 ; 9  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 9 ; 9  
: 0 ; 0  
: 0 ; 0  
: 6 ; 6  
: 0 ; 0  
: 24 ; 24  
: 255 ; 255  
: 107 ; 107  
: 176 ; 176  
: 227 ; 227  
: 124 ; 124  
: 57 ; 57  
: 21 ; 21  
: 0 ; 0  
: 18 ; 18  
: 100 ; 100  
: 20 ; 20  
: 20 ; 20  
: 100 ; 100  
: 52 ; 52  
: 100 ; 100  
: 100 ; 100  
: 0 ; 0  
: 20 ; 20  
: 0 ; 0  
: 255 ; 255  
: 128 ; 128  
: 252 ; 252  
: 0 ; 0  
: 20 ; 20  
: 0 ; 0  
: 144 ; 144  
: 1 ; 1  
: 128 ; 128  
: 21 ; 21  
: 177 ; 177  
: 37 ; 37  
: 170 ; 170  
: 10 ; 10  
: 232 ; 232  
: 3 ; 3

: 26 ; 26  
: 0 ; 0  
: 64 ; 64  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 184 ; 184  
: 11 ; 11  
: 0 ; 0  
: 31 ; 31  
: 102 ; 102  
: 9 ; 9  
: 165 ; 165  
: 165 ; 165  
: 204 ; 204  
: 11 ; 11  
: 232 ; 232  
: 3 ; 3  
: 232 ; 232  
: 3 ; 3  
: 48 ; 48  
: 0 ; 0  
: 192 ; 192  
: 93 ; 93  
: 88 ; 88  
: 27 ; 27  
: 1 ; 1  
: 0 ; 0  
: 0 ; 0  
: 3 ; 3  
: 183 ; 183  
: 1 ; 1  
: 0 ; 0  
: 4 ; 4  
: 10 ; 10  
: 0 ; 0  
: 136 ; 136  
: 19 ; 19  
: 136 ; 136  
: 19 ; 19  
: 136 ; 136  
: 19 ; 19  
: 50 ; 50  
: 0 ; 0  
: 0 ; 0  
: 10 ; 10  
: 25 ; 25  
: 50 ; 50  
: 50 ; 50  
: 0 ; 0  
: 128 ; 128  
: 2 ; 2  
: 128 ; 128  
: 2 ; 2  
: 128 ; 128  
: 2 ; 2  
: 0 ; 0  
: 1 ; 1  
: 0 ; 0  
: 1 ; 1  
: 131 ; 131  
: 0 ; 0  
: 232 ; 232

```
: 3 ; 3
: 120 ; 120
: 236 ; 236
: 0 ; 0
: 0 ; 0
: 232 ; 232
: 3 ; 3
: 64 ; 64
: 31 ; 31
: 16 ; 16
: 39 ; 39
: 4 ; 4
: 41 ; 41
: 248 ; 248
: 42 ; 42
: 32 ; 32
: 78 ; 78
: 205 ; 205
: 9 ; 9
: 205 ; 205
: 9 ; 9
: 154 ; 154
: 11 ; 11
: 154 ; 154
: 11 ; 11
: 154 ; 154
: 11 ; 11
: 154 ; 154
: 11 ; 11
: 102 ; 102
: 10 ; 10
: 102 ; 102
: 10 ; 10
: 205 ; 205
: 9 ; 9
: 205 ; 205
: 9 ; 9
: 154 ; 154
: 11 ; 11
: 154 ; 154
: 11 ; 11
: 154 ; 154
: 11 ; 11
: 154 ; 154
: 11 ; 11
: 102 ; 102
: 10 ; 10
: 102 ; 102
: 10 ; 10
: 0 ; 0
: 64 ; 64
: 0 ; 0
: 2 ; 2
: 192 ; 192
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 3 ; 3
: 0 ; 0
: 0 ; 0
: 0 ; 0
xMotorTune [UINT(8),(1,532)] 236 ; 236
: 27 ; 27
```

: 1 ; 1  
: 0 ; 0  
: 7 ; 7  
: 48 ; 48  
: 0 ; 0  
: 2 ; 2  
: 0 ; 0  
: 30 ; 30  
: 102 ; 102  
: 86 ; 86  
: 0 ; 0  
: 8 ; 8  
: 0 ; 0  
: 50 ; 50  
: 0 ; 0  
: 24 ; 24  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 60 ; 60  
: 191 ; 191  
: 3 ; 3  
: 0 ; 0  
: 0 ; 0  
: 35 ; 35  
: 0 ; 0  
: 129 ; 129  
: 5 ; 5  
: 0 ; 0  
: 0 ; 0  
: 154 ; 154  
: 4 ; 4  
: 95 ; 95  
: 2 ; 2  
: 64 ; 64  
: 2 ; 2  
: 50 ; 50  
: 0 ; 0  
: 15 ; 15  
: 0 ; 0  
: 142 ; 142  
: 3 ; 3  
: 192 ; 192  
: 0 ; 0  
: 90 ; 90  
: 1 ; 1  
: 56 ; 56  
: 74 ; 74  
: 104 ; 104  
: 66 ; 66  
: 118 ; 118  
: 3 ; 3  
: 253 ; 253  
: 0 ; 0  
: 96 ; 96  
: 240 ; 240  
: 200 ; 200  
: 50 ; 50  
: 152 ; 152  
: 58 ; 58  
: 128 ; 128

: 62 ; 62  
: 0 ; 0  
: 60 ; 60  
: 0 ; 0  
: 60 ; 60  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 96 ; 96  
: 240 ; 240  
: 128 ; 128  
: 62 ; 62  
: 56 ; 56  
: 74 ; 74  
: 48 ; 48  
: 117 ; 117  
: 0 ; 0  
: 60 ; 60  
: 0 ; 0  
: 60 ; 60  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 96 ; 96  
: 240 ; 240  
: 152 ; 152  
: 58 ; 58  
: 104 ; 104  
: 66 ; 66  
: 48 ; 48  
: 117 ; 117  
: 0 ; 0  
: 60 ; 60  
: 0 ; 0  
: 60 ; 60  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 128 ; 128  
: 2 ; 2  
: 213 ; 213  
: 0 ; 0  
: 29 ; 29  
: 0 ; 0  
: 0 ; 0  
: 57 ; 57  
: 0 ; 0  
: 57 ; 57  
: 0 ; 0  
: 57 ; 57  
: 0 ; 0  
: 55 ; 55  
: 128 ; 128  
: 51 ; 51  
: 0 ; 0  
: 49 ; 49  
: 0 ; 0  
: 47 ; 47  
: 128 ; 128  
: 44 ; 44

: 128 ; 128  
: 42 ; 42  
: 128 ; 128  
: 40 ; 40  
: 0 ; 0  
: 38 ; 38  
: 0 ; 0  
: 36 ; 36  
: 128 ; 128  
: 34 ; 34  
: 128 ; 128  
: 33 ; 33  
: 0 ; 0  
: 33 ; 33  
: 0 ; 0  
: 33 ; 33  
: 0 ; 0  
: 33 ; 33  
: 0 ; 0  
: 33 ; 33  
: 128 ; 128  
: 33 ; 33  
: 0 ; 0  
: 34 ; 34  
: 128 ; 128  
: 34 ; 34  
: 0 ; 0  
: 35 ; 35  
: 0 ; 0  
: 36 ; 36  
: 128 ; 128  
: 36 ; 36  
: 128 ; 128  
: 36 ; 36  
: 128 ; 128  
: 36 ; 36  
: 128 ; 128  
: 36 ; 36  
: 128 ; 128  
: 36 ; 36  
: 128 ; 128  
: 36 ; 36  
: 0 ; 0  
: 57 ; 57  
: 0 ; 0  
: 57 ; 57  
: 0 ; 0  
: 57 ; 57  
: 0 ; 0  
: 55 ; 55  
: 128 ; 128  
: 51 ; 51  
: 0 ; 0  
: 49 ; 49  
: 0 ; 0  
: 47 ; 47  
: 128 ; 128  
: 46 ; 46  
: 128 ; 128  
: 46 ; 46  
: 128 ; 128



: 46 ; 46  
: 128 ; 128  
: 46 ; 46  
: 0 ; 0  
: 46 ; 46  
: 128 ; 128  
: 45 ; 45  
: 128 ; 128  
: 45 ; 45  
: 0 ; 0  
: 46 ; 46  
: 0 ; 0  
: 46 ; 46  
: 0 ; 0  
: 46 ; 46  
: 128 ; 128  
: 46 ; 46  
: 128 ; 128  
: 46 ; 46  
: 128 ; 128  
: 46 ; 46  
: 0 ; 0  
: 47 ; 47  
: 0 ; 0  
: 47 ; 47  
: 0 ; 0  
: 47 ; 47  
: 128 ; 128  
: 47 ; 47  
: 0 ; 0  
: 48 ; 48  
: 0 ; 0  
: 48 ; 48  
: 0 ; 0  
: 48 ; 48  
: 0 ; 0  
: 48 ; 48  
: 0 ; 0  
: 48 ; 48  
: 0 ; 0  
: 48 ; 48  
: 0 ; 0  
: 181 ; 181  
: 0 ; 0  
: 5 ; 5  
: 30 ; 30  
: 0 ; 0  
: 56 ; 56  
: 0 ; 0  
: 56 ; 56  
: 0 ; 0  
: 56 ; 56  
: 0 ; 0  
: 56 ; 56  
: 0 ; 0  
: 45 ; 45  
: 0 ; 0  
: 34 ; 34  
: 0 ; 0  
: 20 ; 20  
: 0 ; 0  
: 6 ; 6  
: 0 ; 0

BGA02812\_Taras.PAR

: 245 ; 245  
: 255 ; 255  
: 228 ; 228  
: 255 ; 255  
: 232 ; 232  
: 255 ; 255  
: 237 ; 237  
: 255 ; 255  
: 242 ; 242  
: 255 ; 255  
: 247 ; 247  
: 255 ; 255  
: 251 ; 251  
: 255 ; 255  
: 0 ; 0  
: 0 ; 0  
: 6 ; 6  
: 0 ; 0  
: 11 ; 11  
: 0 ; 0  
: 17 ; 17  
: 0 ; 0  
: 23 ; 23  
: 0 ; 0  
: 29 ; 29  
: 0 ; 0  
: 34 ; 34  
: 0 ; 0  
: 15 ; 15  
: 0 ; 0  
: 252 ; 252  
: 255 ; 255  
: 236 ; 236  
: 255 ; 255  
: 221 ; 221  
: 255 ; 255  
: 208 ; 208  
: 255 ; 255  
: 196 ; 196  
: 255 ; 255  
: 196 ; 196  
: 255 ; 255  
: 196 ; 196  
: 255 ; 255  
: 196 ; 196  
: 255 ; 255  
: 232 ; 232  
: 255 ; 255  
: 232 ; 232  
: 255 ; 255  
: 232 ; 232  
: 255 ; 255  
: 232 ; 232  
: 255 ; 255  
: 232 ; 232  
: 255 ; 255  
: 231 ; 231  
: 255 ; 255  
: 230 ; 230  
: 255 ; 255  
: 232 ; 232  
: 255 ; 255  
: 235 ; 235  
: 255 ; 255  
: 241 ; 241

BGA02812\_Taras.PAR

: 255 ; 255  
: 247 ; 247  
: 255 ; 255  
: 248 ; 248  
: 255 ; 255  
: 250 ; 250  
: 255 ; 255  
: 251 ; 251  
: 255 ; 255  
: 253 ; 253  
: 255 ; 255  
: 254 ; 254  
: 255 ; 255  
: 0 ; 0  
: 0 ; 0  
: 253 ; 253  
: 255 ; 255  
: 251 ; 251  
: 255 ; 255  
: 249 ; 249  
: 255 ; 255  
: 247 ; 247  
: 255 ; 255  
: 244 ; 244  
: 255 ; 255  
: 242 ; 242  
: 255 ; 255  
: 234 ; 234  
: 255 ; 255  
: 227 ; 227  
: 255 ; 255  
: 223 ; 223  
: 255 ; 255  
: 219 ; 219  
: 255 ; 255  
: 218 ; 218  
: 255 ; 255  
: 217 ; 217  
: 255 ; 255  
: 217 ; 217  
: 255 ; 255  
: 217 ; 217  
: 255 ; 255  
: 217 ; 217  
: 255 ; 255  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 102 ; 102  
: 6 ; 6  
: 23 ; 23  
: 12 ; 12  
: 199 ; 199  
: 17 ; 17

: 193 ; 193  
: 22 ; 22  
: 6 ; 6  
: 27 ; 27  
: 148 ; 148  
: 30 ; 30  
: 108 ; 108  
: 33 ; 33  
: 142 ; 142  
: 35 ; 35  
: 176 ; 176  
: 37 ; 37  
: 211 ; 211  
: 39 ; 39  
: 245 ; 245  
: 41 ; 41  
: 97 ; 97  
: 43 ; 43  
: 205 ; 205  
: 44 ; 44  
: 57 ; 57  
: 46 ; 46  
: 165 ; 165  
: 47 ; 47  
: 17 ; 17  
: 49 ; 49  
: 199 ; 199  
: 49 ; 49  
: 125 ; 125  
: 50 ; 50  
: 51 ; 51  
: 51 ; 51  
: 51 ; 51  
: 51 ; 51  
: 51 ; 51  
: 51 ; 51  
: 51 ; 51  
: 51 ; 51  
: 51 ; 51  
: 51 ; 51  
: 51 ; 51  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 216 ; 216  
: 2 ; 2  
: 28 ; 28

: 7 ; 7  
: 97 ; 97  
: 11 ; 11  
: 165 ; 165  
: 15 ; 15  
: 233 ; 233  
: 19 ; 19  
: 120 ; 120  
: 23 ; 23  
: 6 ; 6  
: 27 ; 27  
: 222 ; 222  
: 29 ; 29  
: 182 ; 182  
: 32 ; 32  
: 216 ; 216  
: 34 ; 34  
: 176 ; 176  
: 37 ; 37  
: 137 ; 137  
: 40 ; 40  
: 171 ; 171  
: 42 ; 42  
: 23 ; 23  
: 44 ; 44  
: 131 ; 131  
: 45 ; 45  
: 239 ; 239  
: 46 ; 46  
: 239 ; 239  
: 46 ; 46  
: 239 ; 239  
: 46 ; 46  
: 239 ; 239  
: 46 ; 46  
: 239 ; 239  
: 46 ; 46  
: 239 ; 239  
: 46 ; 46  
: 179 ; 179  
: 11 ; 11  
: 128 ; 128  
: 13 ; 13  
: 210 ; 210  
: 0 ; 0  
: 168 ; 168  
: 228 ; 228  
: 84 ; 84  
: 242 ; 242  
: 224 ; 224  
: 252 ; 252  
: 232 ; 232  
: 3 ; 3  
: 5 ; 5  
: 0 ; 0  
: 20 ; 20  
: 0 ; 0  
: 100 ; 100  
: 0 ; 0  
: 100 ; 100  
: 0 ; 0  
: 192 ; 192  
: 254 ; 254

```
: 192 ; 192
: 1 ; 1
: 100 ; 100
: 0 ; 0
: 32 ; 32
: 0 ; 0
: 42 ; 42
: 0 ; 0
: 19 ; 19
: 19 ; 19
: 140 ; 140
: 3 ; 3
: 152 ; 152
: 58 ; 58
: 140 ; 140
: 3 ; 3
: 140 ; 140
: 3 ; 3
: 85 ; 85
: 21 ; 21
: 184 ; 184
: 11 ; 11
: 250 ; 250
: 0 ; 0
: 182 ; 182
: 0 ; 0
xPlatformTune [UINT(8),(1,108)] 76 ; 76
: 157 ; 157
: 0 ; 0
: 0 ; 0
: 1 ; 1
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 102 ; 102
: 102 ; 102
: 50 ; 50
: 4 ; 4
: 0 ; 0
: 192 ; 192
: 44 ; 44
: 4 ; 4
: 102 ; 102
: 102 ; 102
: 50 ; 50
: 4 ; 4
: 102 ; 102
: 102 ; 102
: 50 ; 50
: 4 ; 4
: 204 ; 204
: 76 ; 76
: 63 ; 63
: 4 ; 4
: 102 ; 102
: 102 ; 102
: 50 ; 50
: 4 ; 4
: 102 ; 102
: 102 ; 102
: 50 ; 50
: 4 ; 4
: 102 ; 102
```

: 102 ; 102  
: 50 ; 50  
: 4 ; 4  
: 102 ; 102  
: 102 ; 102  
: 50 ; 50  
: 4 ; 4  
: 102 ; 102  
: 102 ; 102  
: 50 ; 50  
: 4 ; 4  
: 102 ; 102  
: 102 ; 102  
: 50 ; 50  
: 4 ; 4  
: 102 ; 102  
: 102 ; 102  
: 50 ; 50  
: 4 ; 4  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 2 ; 2  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 20 ; 20  
: 0 ; 0  
: 20 ; 20  
: 0 ; 0  
: 3 ; 3  
: 102 ; 102  
: 0 ; 0  
: 0 ; 0  
: 12 ; 12  
: 0 ; 0  
: 3 ; 3  
: 0 ; 0  
: 3 ; 3  
: 12 ; 12  
: 13 ; 13  
: 128 ; 128  
: 4 ; 4  
: 0 ; 0  
: 4 ; 4  
: 0 ; 0  
: 4 ; 4  
: 0 ; 0  
: 0 ; 0  
: 100 ; 100  
: 0 ; 0  
: 0 ; 0  
: 160 ; 160  
: 15 ; 15  
: 5 ; 5  
: 0 ; 0  
: 3 ; 3  
: 0 ; 0  
: 75 ; 75  
: 75 ; 75  
: 100 ; 100

```
: 208 ; 208
: 7 ; 7
: 0 ; 0
: 20 ; 20
: 0 ; 0
: 64 ; 64
: 0 ; 0
: 0 ; 0
xVehicleTune [UINT(8),(1,648)] 196 ; 196
: 234 ; 234
: 3 ; 3
: 0 ; 0
: 1 ; 1
: 0 ; 0
: 176 ; 176
: 4 ; 4
: 208 ; 208
: 7 ; 7
: 50 ; 50
: 0 ; 0
: 244 ; 244
: 1 ; 1
: 80 ; 80
: 88 ; 88
: 98 ; 98
: 110 ; 110
: 123 ; 123
: 130 ; 130
: 135 ; 135
: 136 ; 136
: 137 ; 137
: 138 ; 138
: 138 ; 138
: 138 ; 138
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 0 ; 0
: 7 ; 7
: 17 ; 17
: 39 ; 39
: 64 ; 64
: 91 ; 91
: 116 ; 116
: 139 ; 139
: 156 ; 156
: 18 ; 18
: 18 ; 18
: 19 ; 19
: 20 ; 20
: 21 ; 21
: 22 ; 22
: 24 ; 24
: 26 ; 26
: 29 ; 29
: 32 ; 32
: 35 ; 35
: 37 ; 37
: 85 ; 85
: 85 ; 85
: 85 ; 85
```



: 86 ; 86  
: 88 ; 88  
: 90 ; 90  
: 94 ; 94  
: 97 ; 97  
: 100 ; 100  
: 102 ; 102  
: 103 ; 103  
: 103 ; 103  
: 51 ; 51  
: 3 ; 3  
: 205 ; 205  
: 12 ; 12  
: 200 ; 200  
: 255 ; 255  
: 250 ; 250  
: 255 ; 255  
: 0 ; 0  
: 0 ; 0  
: 30 ; 30  
: 100 ; 100  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 8 ; 8  
: 15 ; 15  
: 25 ; 25  
: 35 ; 35  
: 45 ; 45  
: 60 ; 60  
: 75 ; 75  
: 95 ; 95  
: 120 ; 120  
: 150 ; 150  
: 190 ; 190  
: 0 ; 0  
: 5 ; 5  
: 10 ; 10  
: 15 ; 15  
: 20 ; 20  
: 25 ; 25  
: 30 ; 30  
: 35 ; 35  
: 45 ; 45  
: 60 ; 60  
: 109 ; 109  
: 116 ; 116  
: 119 ; 119  
: 121 ; 121  
: 123 ; 123  
: 127 ; 127  
: 132 ; 132  
: 135 ; 135  
: 139 ; 139  
: 144 ; 144  
: 83 ; 83  
: 90 ; 90  
: 93 ; 93  
: 95 ; 95  
: 97 ; 97  
: 101 ; 101

: 106 ; 106  
: 109 ; 109  
: 113 ; 113  
: 118 ; 118  
: 72 ; 72  
: 79 ; 79  
: 82 ; 82  
: 84 ; 84  
: 86 ; 86  
: 90 ; 90  
: 95 ; 95  
: 98 ; 98  
: 102 ; 102  
: 107 ; 107  
: 60 ; 60  
: 67 ; 67  
: 70 ; 70  
: 72 ; 72  
: 74 ; 74  
: 78 ; 78  
: 83 ; 83  
: 86 ; 86  
: 90 ; 90  
: 95 ; 95  
: 52 ; 52  
: 59 ; 59  
: 62 ; 62  
: 64 ; 64  
: 66 ; 66  
: 70 ; 70  
: 75 ; 75  
: 78 ; 78  
: 82 ; 82  
: 87 ; 87  
: 45 ; 45  
: 52 ; 52  
: 55 ; 55  
: 57 ; 57  
: 59 ; 59  
: 63 ; 63  
: 68 ; 68  
: 71 ; 71  
: 75 ; 75  
: 80 ; 80  
: 40 ; 40  
: 47 ; 47  
: 50 ; 50  
: 52 ; 52  
: 54 ; 54  
: 58 ; 58  
: 63 ; 63  
: 66 ; 66  
: 70 ; 70  
: 75 ; 75  
: 33 ; 33  
: 40 ; 40  
: 43 ; 43  
: 45 ; 45  
: 47 ; 47  
: 51 ; 51  
: 56 ; 56  
: 59 ; 59  
: 63 ; 63

: 70 ; 70  
: 31 ; 31  
: 38 ; 38  
: 41 ; 41  
: 43 ; 43  
: 45 ; 45  
: 49 ; 49  
: 54 ; 54  
: 57 ; 57  
: 61 ; 61  
: 68 ; 68  
: 30 ; 30  
: 37 ; 37  
: 40 ; 40  
: 42 ; 42  
: 44 ; 44  
: 48 ; 48  
: 53 ; 53  
: 56 ; 56  
: 60 ; 60  
: 65 ; 65  
: 29 ; 29  
: 36 ; 36  
: 39 ; 39  
: 41 ; 41  
: 43 ; 43  
: 47 ; 47  
: 52 ; 52  
: 55 ; 55  
: 59 ; 59  
: 64 ; 64  
: 28 ; 28  
: 35 ; 35  
: 38 ; 38  
: 40 ; 40  
: 42 ; 42  
: 46 ; 46  
: 51 ; 51  
: 54 ; 54  
: 58 ; 58  
: 63 ; 63  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 3 ; 3  
: 11 ; 11  
: 17 ; 17  
: 23 ; 23  
: 27 ; 27  
: 28 ; 28  
: 28 ; 28  
: 1 ; 1  
: 2 ; 2  
: 3 ; 3  
: 4 ; 4  
: 5 ; 5  
: 7 ; 7  
: 9 ; 9  
: 11 ; 11  
: 13 ; 13  
: 14 ; 14

: 15 ; 15  
: 16 ; 16  
: 18 ; 18  
: 24 ; 24  
: 25 ; 25  
: 25 ; 25  
: 25 ; 25  
: 24 ; 24  
: 23 ; 23  
: 22 ; 22  
: 21 ; 21  
: 20 ; 20  
: 20 ; 20  
: 20 ; 20  
: 180 ; 180  
: 130 ; 130  
: 96 ; 96  
: 82 ; 82  
: 77 ; 77  
: 75 ; 75  
: 74 ; 74  
: 73 ; 73  
: 73 ; 73  
: 72 ; 72  
: 71 ; 71  
: 70 ; 70  
: 20 ; 20  
: 27 ; 27  
: 29 ; 29  
: 30 ; 30  
: 31 ; 31  
: 32 ; 32  
: 33 ; 33  
: 34 ; 34  
: 35 ; 35  
: 36 ; 36  
: 37 ; 37  
: 38 ; 38  
: 20 ; 20  
: 22 ; 22  
: 25 ; 25  
: 29 ; 29  
: 34 ; 34  
: 40 ; 40  
: 48 ; 48  
: 56 ; 56  
: 63 ; 63  
: 70 ; 70  
: 77 ; 77  
: 81 ; 81  
: 179 ; 179  
: 176 ; 176  
: 169 ; 169  
: 160 ; 160  
: 151 ; 151  
: 140 ; 140  
: 123 ; 123  
: 105 ; 105  
: 85 ; 85  
: 73 ; 73  
: 67 ; 67  
: 62 ; 62  
: 30 ; 30

: 0 ; 0  
: 0 ; 0  
: 4 ; 4  
: 0 ; 0  
: 8 ; 8  
: 6 ; 6  
: 0 ; 0  
: 60 ; 60  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 8 ; 8  
: 15 ; 15  
: 25 ; 25  
: 35 ; 35  
: 45 ; 45  
: 60 ; 60  
: 75 ; 75  
: 95 ; 95  
: 120 ; 120  
: 150 ; 150  
: 190 ; 190  
: 0 ; 0  
: 25 ; 25  
: 170 ; 170  
: 1 ; 1  
: 173 ; 173  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 50 ; 50  
: 0 ; 0  
: 5 ; 5  
: 0 ; 0  
: 165 ; 165  
: 106 ; 106  
: 157 ; 157  
: 106 ; 106  
: 149 ; 149  
: 106 ; 106  
: 149 ; 149  
: 106 ; 106  
: 141 ; 141  
: 106 ; 106  
: 187 ; 187  
: 42 ; 42  
: 181 ; 181  
: 42 ; 42  
: 176 ; 176  
: 42 ; 42

: 176 ; 176  
: 42 ; 42  
: 171 ; 171  
: 42 ; 42  
: 201 ; 201  
: 54 ; 54  
: 158 ; 158  
: 61 ; 61  
: 114 ; 114  
: 68 ; 68  
: 114 ; 114  
: 68 ; 68  
: 70 ; 70  
: 75 ; 75  
: 70 ; 70  
: 105 ; 105  
: 103 ; 103  
: 118 ; 118  
: 134 ; 134  
: 131 ; 131  
: 134 ; 134  
: 131 ; 131  
: 164 ; 164  
: 144 ; 144  
: 147 ; 147  
: 50 ; 50  
: 225 ; 225  
: 56 ; 56  
: 47 ; 47  
: 63 ; 63  
: 47 ; 47  
: 63 ; 63  
: 124 ; 124  
: 69 ; 69  
: 0 ; 0  
: 5 ; 5  
: 10 ; 10  
: 15 ; 15  
: 20 ; 20  
: 0 ; 0  
: 2 ; 2  
: 10 ; 10  
: 15 ; 15  
: 25 ; 25  
: 32 ; 32  
: 35 ; 35  
: 40 ; 40  
: 60 ; 60  
: 0 ; 0  
: 64 ; 64  
: 0 ; 0  
: 8 ; 8  
: 228 ; 228  
: 0 ; 0  
: 80 ; 80  
: 26 ; 26  
: 60 ; 60  
: 0 ; 0  
: 37 ; 37  
: 0 ; 0  
: 48 ; 48  
: 0 ; 0  
: 6 ; 6

: 1 ; 1  
: 0 ; 0  
: 0 ; 0  
: 244 ; 244  
: 1 ; 1  
: 40 ; 40  
: 10 ; 10  
: 0 ; 0  
: 0 ; 0  
: 128 ; 128  
: 2 ; 2  
: 0 ; 0  
: 50 ; 50  
: 0 ; 0  
: 10 ; 10  
: 192 ; 192  
: 0 ; 0  
: 3 ; 3  
: 16 ; 16  
: 183 ; 183  
: 38 ; 38  
: 107 ; 107  
: 23 ; 23  
: 0 ; 0  
: 1 ; 1  
: 0 ; 0  
: 4 ; 4  
: 232 ; 232  
: 3 ; 3  
: 104 ; 104  
: 1 ; 1  
: 88 ; 88  
: 2 ; 2  
: 192 ; 192  
: 1 ; 1  
: 50 ; 50  
: 0 ; 0  
: 221 ; 221  
: 60 ; 60  
: 221 ; 221  
: 60 ; 60  
: 200 ; 200  
: 0 ; 0  
: 15 ; 15  
: 0 ; 0  
: 4 ; 4  
: 0 ; 0  
: 242 ; 242  
: 23 ; 23  
: 130 ; 130  
: 0 ; 0  
: 252 ; 252  
: 56 ; 56  
: 0 ; 0  
: 8 ; 8  
: 16 ; 16  
: 0 ; 0  
: 50 ; 50  
: 120 ; 120  
: 51 ; 51  
: 24 ; 24  
: 80 ; 80  
: 20 ; 20

: 45 ; 45  
: 75 ; 75  
: 72 ; 72  
: 5 ; 5  
: 123 ; 123  
: 4 ; 4  
: 0 ; 0  
: 0 ; 0  
: 184 ; 184  
: 11 ; 11  
: 182 ; 182  
: 3 ; 3  
: 182 ; 182  
: 3 ; 3  
: 0 ; 0  
: 0 ; 0  
: 58 ; 58  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 48 ; 48  
: 117 ; 117  
: 0 ; 0  
: 0 ; 0  
: 205 ; 205  
: 8 ; 8  
: 205 ; 205  
: 10 ; 10  
: 205 ; 205  
: 12 ; 12  
: 205 ; 205  
: 14 ; 14  
: 205 ; 205  
: 16 ; 16  
: 205 ; 205  
: 18 ; 18  
: 205 ; 205  
: 20 ; 20  
: 205 ; 205  
: 22 ; 22  
: 205 ; 205  
: 22 ; 22  
: 205 ; 205  
: 22 ; 22  
: 205 ; 205  
: 22 ; 22  
: 205 ; 205  
: 22 ; 22  
: 100 ; 100  
: 0 ; 0  
: 75 ; 75  
: 0 ; 0  
: 50 ; 50  
: 0 ; 0  
: 25 ; 25  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0



: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 106 ; 106  
: 106 ; 106  
: 106 ; 106  
: 106 ; 106  
: 106 ; 106  
: 106 ; 106  
: 106 ; 106  
: 106 ; 106  
: 106 ; 106  
: 106 ; 106  
: 106 ; 106  
: 106 ; 106  
: 32 ; 32  
: 3 ; 3  
: 113 ; 113  
: 56 ; 56  
: 31 ; 31  
: 5 ; 5  
: 0 ; 0  
: 4 ; 4  
: 102 ; 102  
: 38 ; 38  
: 0 ; 0  
: 0 ; 0  
: 252 ; 252  
: 1 ; 1  
: 0 ; 0  
: 0 ; 0  
: 192 ; 192  
: 31 ; 31  
: 192 ; 192  
: 0 ; 0  
: 0 ; 0  
: 4 ; 4  
: 199 ; 199  
: 1 ; 1  
: 51 ; 51  
: 0 ; 0  
: 192 ; 192  
: 2 ; 2  
: 253 ; 253  
: 13 ; 13  
: 85 ; 85  
: 21 ; 21  
: 227 ; 227  
: 0 ; 0  
: 65 ; 65  
: 85 ; 85  
: 244 ; 244  
: 1 ; 1  
: 200 ; 200  
: 0 ; 0

BGA02812\_Taras.PAR

: 200 ; 200  
: 0 ; 0  
: 200 ; 200  
: 0 ; 0  
: 128 ; 128  
: 2 ; 2  
: 160 ; 160  
: 0 ; 0  
: 0 ; 0  
: 50 ; 50  
: 0 ; 0  
: 0 ; 0  
: 0 ; 0  
: 60 ; 60  
: 82 ; 82  
: 53 ; 53  
: 94 ; 94  
: 21 ; 21  
: 101 ; 101  
: 27 ; 27  
: 163 ; 163  
: 52 ; 52  
: 74 ; 74  
: 25 ; 25  
: 0 ; 0  
: 0 ; 0

---

**From:** Napoli, Laura (L.)  
**Sent:** Tuesday, June 14, 2011 12:16 PM  
**To:** Estes, Eric (E.E.)  
**Subject:** FW: 1FMHK8D81BG [REDACTED]

Can you look this VIN up and see if the U3000-49 snapshot data is in the system?

---

**From:** Anderson, Eric (H.)  
**Sent:** Tuesday, June 14, 2011 11:55 AM  
**To:** Cassata, Joe (J.)  
**Cc:** Logli, Michael (M.A.); Docimo, Tony (A.F.); Napoli, Laura (L.); Mrozek, Robert (R.M.); Annadi, Hari (H.); Estes, Eric (E.E.)  
**Subject:** 1FMHK8D81BG [REDACTED]

Hi Joe:

Please request this steering gear from the dealership. It should go to Eric Estes at WPAC, TR-EE.

Steering and Electrical teams,

I'm rebinning this claim to Electrical after talking to the repairing technician. He never did manage to repair the vehicle. It was eventually bought back. Here are my notes and bin comments from our conversation:

Called dealership. Multiple fault lights in IP. Service manual initially directed tech to replace rack because of U3000:49 code. Unit never lost steering assist. Unknown if problem with rack. New gear did not fix problem. Something dropping HS CAN network. Fault lights still come on. Intermittent problem, hard to isolate because of interdependent modules required to test drive vehicle. Technician's best guess is wire chafe or short somewhere in network. Technician could short HS CAN network on purpose and produce same codes. Unit never repaired, bought back by FoMoCo. Codes are U0001, U0100, U0131, U0140, U0420, C1B00:29-68, C1B00:86-28, U0140:00-28, U0121, U0212, U0155, U0423, U0554, U0138, U0151, U0159, U0553, U0534, P193P, P260F, U0415, U3000:49.

Laura Napoli is looking into the possibility of inducing a U3000:49 without losing steering assist.

Electrical team,  
Any guesses?

Thanks,

Eric Anderson  
PVT Engineer  
Ford Chicago Assembly  
773.646.7236 desk  
773.729.0337 cell  
[eande181@ford.com](mailto:eande181@ford.com)

Server: **AWS Prod**  
Claims loaded through: **13-JUN-2011**

## Claim Detail Report

*Note: All costs are in US dollars*

**Model Year** = 2011; **Claim Key** = 549026

**Vehicle Information**

Model Year: 2011

Market Derived: F - FORD

Body/Cab Type: T/WD - 4 DOOR WAGON

Version/Series: T/EF-FORD SERIES

Drive Type: T/F-4 WHL L/H FULL TIME DRIVE

Vehicle Line: T/UB-EXPLORER [11-12]

Warranty Start Date: 19-MAR-11

Production Date: 07-MAR-11

VIN: 1FMHK8D81B [REDACTED]

**Claim Information**

Document Number: 01309051

Repair Date: 15-APR-11

Distance: 1343

TIS: 1

**Expense Information**

**Dealer Information:**

Dealer Name: WALDORF FORD, INC.

Dealer Code: 00149 - \*

Address: 2440 CRAIN HIGHWAY

City: WALDORF

State: MD Zip Code: 20601

Country: USA Region Code: NA

Phone: (301)843-2400

Customer Paid Amount: .00

Deductible Amount: .00

Dealer Paid Amount: .00

Labor Cost: 678.96

Misc. Expense Amount: .00

Part Markup Amount: 292.57

Material Cost: 1024.00

Total Cost Gross: 1702.96

Cust.

Concern: E29 - CHECK ENGINE LIGHT TROUBLE

Code:

Condition: 42 - DOES NOT OPERATE PROPERLY

Code:

Technician: IC, CENTER CONSOLD, & FRONT DIAPLAY. DISCONNECTING ALL  
Comment: MODULES ON HS CAN NETWORK TO PP CONSERN W FEILD SERVICE  
ENGINEER. WIGGLE TESTED VERIUS HARNESS & INSP HS CAN NET  
WORK JOINT CONNECTORS. PROBLEM BECAME VERY INTERMITTANT &

WAS UNABLE TO ISOLATE CONSERN WITH ENGINEER. CHECKED & CLEANED GROUNDS G100,G101,G103. CHECK PCM,IC, BCM FOR UPDATES & RECALIBRATED. VEHI LCE WAS NOT REPAIRED & BOUGHT BACK B

Customer Comment: CUSTOMER STS SERVICE ENGINE SOON LIGHT IS ON DASH

<u>Labor Op Code</u>	<u>Labor Op Description</u>	<u>Labor Op Cost</u>
3504E		19.68
3504E8		9.84
3504E45		29.52
3504E47		29.52
MTDIAG		590.40

<u>Causal Flag</u>	<u>Full Part Number</u>	<u>Part Description</u>	<u>Part CPSC</u>	<u>Part Quantity</u>	<u>Extended Amount</u>
Y	BB5Z 3504 BE	GEAR ASY-STEERING	110101	1	1024.00

DTC Sections: Mil. Light On = Y

<u>Flag</u>	<u>Test Type</u>	<u>Malfunction Cd</u>	<u>Malfunction Cd Description</u>	<u>Monitor Cd</u>	<u>Monitor Cd Description</u>
	KOEC	P123D			
Y	KOEC	P260F	EVAPORATIVE SYSTEM MONITORING PROCESSOR PERFORMANCE	21	CCM MODULE
N	KOEO	PASS	SYSTEM PASS	27	NO-FAULT CODES
N	KOER	PASS	SYSTEM PASS	27	NO-FAULT CODES

Any comments? You can contact

*webmaster*

3354

---

**From:** Napoli, Laura (L.)  
**Sent:** Thursday, June 16, 2011 10:48 AM  
**To:** Estes, Eric (E.E.)  
**Subject:** FW: 1FMHK8F85BG [REDACTED] EPAS inop

How the hell did a U2100 (A5B, AF5) get in this gear? Is something happening to the gear due to electrical surges or shorts causing it to lose its configuration? We need to try and duplicate this because that's a big deal if gears are losing their configs.

---

**From:** Anderson, Eric (H.)  
**Sent:** Thursday, June 16, 2011 10:15 AM  
**To:** Napoli, Laura (L.); Estes, Eric (E.E.)  
**Cc:** Cassata, Joe (J.)  
**Subject:** 1FMHK8F85BG [REDACTED] EPAS inop

FYI. Here's another U3000:49. It's within the BSAQ project window. A new gear fixed the problem.

Joe,  
Thanks for requesting it.

Server: **AWS Prod**  
Claims loaded through: **15-JUN-2011**

## Claim Detail Report

*Note: All costs are in US dollars*

**Model Year** = 2011; **Claim Key** = 566418

### Vehicle Information

Model Year: 2011

Market Derived: F - FORD

Body/Cab Type: T/WD - 4 DOOR WAGON

Version/Series: T/EF-FORD SERIES

Drive Type: T/F-4 WHL L/H FULL TIME  
DRIVE

Vehicle Line: T/UB-EXPLORER [11-12]

Warranty Start Date: 26-MAR-11

Production Date: 04-MAR-11

VIN: 1FMHK8F85BG [REDACTED]

### Claim Information

Document Number: 68245502

Repair Date: 09-JUN-  
11

Distance: 3003

TIS: 3

**Expense Information**

**Dealer Information:**

<u>Dealer Name</u> VAN BORTEL FORD, INC.	Customer Paid Amount:	.00
Dealer Code: 07590 - *	Deductible Amount:	.00
Address: 71 MARSH RD.	Dealer Paid Amount:	.00
City: EAST ROCHESTER	Labor Cost:	244.18
State: NY Zip Code: 14445	Misc. Expense Amount:	.00
Country: USA Region Code: NA	Part Markup Amount:	537.54
Phone: (585)924-9525	Material Cost:	1623.48
	Total Cost Gross:	1867.66

Cust.  
 Concern H22 - STEERING REQUIRES EXTRA OR UNEVEN EFFORT  
 Code:

Condition  
 Code: 42 - DOES NOT OPERATE PROPERLY

Technician MT TMIME FOR UNPUBLISHER LABOR OPERATIONS. DIAG P STEERING  
 nREPLACE BINDING GEAR ASSEMBLY TEST DR TO VERIFY,TEST  
 Comment: PSCM, CODES U2100, U2000 46U3000 49, CK FUSE E, FUSE 89, OK, CK POWER  
 AT MODULE, OK, REPL STEERING RACK ASSEMBLY. CHECK FRONT  
 ALIGNMENT, SET TOE. TEST DRIVE OK. 2012 UNIT, ALL NEW REQUIRED  
 CLAIM IS OK AS IS

Customer CUSTOMER STATES SHE LOST THE STEERING IN CAR WE DELIVED A  
 Comment: STOCK VEHICLE ESCAPE TO HER LAST NITE, AS PER GUY DIAG AND  
 ADVISE CUSTOMER ASAP THURS

<u>Labor Op Code</u>	<u>Labor Op Description</u>	<u>Labor Op Cost</u>
3504E		16.28
3504E45		24.42
MT3504		203.48

<u>Causal</u>	<u>Full Part Number</u>	<u>Part</u>	<u>Part</u>	<u>Extended</u>
<u>Flag</u>	<u>PREF</u> <u>BASE</u> <u>SUFF</u>	<u>Description</u>	<u>CPSC</u> <u>Quantity</u>	<u>Amount</u>



Y BB5Z 3504 JE GEAR ASY-STEERING 110101 1 1623.48

**DTC Sections:**

**Mil. Light On =N**

<u>Flag</u>	<u>Test Type</u>	<u>Malfunction Cd</u>	<u>Malfunction Cd Description</u>	<u>Monitor Cd</u>	<u>Monitor Cd Description</u>
	UNDF	U2100			
N	UNDF	U3000	CONTROL MODULE	48	HYBRID
N	UNDF	U2000	AUDIO REAR CONTROL UNIT IS NOT RESPONDING	24	CCM VEHICLE

Any comments? You can contact

[webmaster](mailto:webmaster)

227

Eric Anderson  
PVT Engineer  
Ford Chicago Assembly  
773.646.7236 desk  
773.729.0337 cell  
[eande181@ford.com](mailto:eande181@ford.com)

---

**From:** Mrozek, Robert (R.M.)  
**Sent:** Friday, January 14, 2011 8:44 AM  
**To:** Napoli, Laura (L.)  
**Subject:** FW: 2011 Exp - BG [REDACTED] - Loss of power steering, lamp on, 18 mi, BD 12/16/10

**Importance:** High

Please get intimately involved in this issue and push it for root cause. Thanks!

*Rob Mrozek*

Electric Power Steering Supervisor  
C346N/CD3/D3/D4/U502/Police/Limo Programs  
Ford Motor Company  
Phone: (313) 805-5947  
e-mail: rmrozek@ford.com

---

**From:** Jackson, Bradley (B.G.)  
**Sent:** Thursday, January 13, 2011 5:17 PM  
**To:** Estes, Eric (E.E.)  
**Cc:** Mrozek, Robert (R.M.)  
**Subject:** RE: 2011 Exp - BG [REDACTED] - Loss of power steering, lamp on, 18 mi, BD 12/16/10

Eric, I know exactly how the system works. I use it everyday. I also know how to circumvent the process to make things happen quickly when needed. We can send parts directly to the dealer, the dealer receives the part and replaces old, and sends out the old part under my FedEx account number at the same time. When the dealer puts the claim into the system, he just claims the labor....since we supplied the part.

U502 is under a microscope right now and we are being required to report out to senior mgmt on every single claim and CQIS report coming in every day. The longer it takes for analysis, the more energy is going to be wrapped around the issue.

Brad

---

**From:** Estes, Eric (E.E.)  
**Sent:** Thursday, January 13, 2011 3:57 PM  
**To:** Jackson, Bradley (B.G.)  
**Cc:** Mrozek, Robert (R.M.)  
**Subject:** RE: 2011 Exp - BG [REDACTED] - Loss of power steering, lamp on, 18 mi, BD 12/16/10

Bradley welcome to the new parts return system at Ford WPAC.

Here is the time line after the claim at the dealer is totally closed. The claim is not send by UPS until it show's up on the PEAR's register then add 3-5 days to WPAC. Not much of a hot process return system but this is how the new system works since July 2010. It will take 2-3 weeks for parts to return under the normal parts return system.

Here is an example:

Monday night Claim Paid

Tuesday morning visible in AWS

Tuesday/Wednesday submit request for part

Wednesday night PEARS 700Tag generates

Thursday morning Tag shows up on Dealers PEARS Register

*Eric J Estes*

TRW EPAS Steering Systems  
Quality Specialist  
Hotline ph# 313-317-9358  
Cell ph# 734-560-3493

---

**From:** Jackson, Bradley (B.G.)  
**Sent:** Thursday, January 13, 2011 4:17 PM  
**To:** Estes, Eric (E.E.)  
**Cc:** Mrozek, Robert (R.M.)  
**Subject:** RE: 2011 Exp - BG [REDACTED] - Loss of power steering, lamp on, 18 mi, BD 12/16/10

Eric, there doesn't seem to be much urgency to get this gear back. We are being pushed very hard for every CQIS report coming in. Would you rather me ship a gear directly out of ZF tonight? I have 1.5 hours that I could get a gear into FedEx tonight. How do we make this happen sooner rather than later?

Brad

---

**From:** Estes, Eric (E.E.)  
**Sent:** Thursday, January 13, 2011 3:03 PM  
**To:** Jackson, Bradley (B.G.)  
**Subject:** RE: 2011 Exp - BGA10846 - Loss of power steering, lamp on, 18 mi, BD 12/16/10

No I will call the dealer on Monday and make sure the RO paperwork is filled out properly and closed so we can get the gear back hopefully by the end of next week.

Eric

---

**From:** Jackson, Bradley (B.G.)  
**Sent:** Thursday, January 13, 2011 3:53 PM  
**To:** Estes, Eric (E.E.)  
**Subject:** RE: 2011 Exp - BG [REDACTED] - Loss of power steering, lamp on, 18 mi, BD 12/16/10

Eric, is getting the replacement gear going to hold up getting the suspect gear back for analysis?

Brad

---

**From:** Estes, Eric (E.E.)  
**Sent:** Thursday, January 13, 2011 2:39 PM  
**To:** Jackson, Bradley (B.G.); 'Gregory Sheets'; Mrozek, Robert (R.M.); Snider, Tim (T.O.)

**Cc:** Napoli, Laura (L.); 'Anthony Fleenor'; 'Michael Fontana'; 'Pat Messer'; 'Sergio Alvarez'; 'Simon Malsbury'  
**Subject:** RE: 2011 Exp - BG [REDACTED] - Loss of power steering, lamp on, 18 mi, BD 12/16/10

Talked to the part manager and the dealer is open till 2pm on Saturday so hopefully the delivery will get their before then, if not it will be delivered on Monday.  
Dealer probably will not do the job till Monday anyway.

*Eric J Estes*

TRW EPAS Steering Systems  
Quality Specialist  
Hotline ph# 313-317-9358  
Cell ph# 734-560-3493

---

**From:** Jackson, Bradley (B.G.)  
**Sent:** Thursday, January 13, 2011 2:15 PM  
**To:** 'Gregory Sheets'; Estes, Eric (E.E.); Mrozek, Robert (R.M.); Snider, Tim (T.O.)  
**Cc:** Napoli, Laura (L.); Anthony Fleenor; Michael Fontana; Pat Messer; Sergio Alvarez; Simon Malsbury  
**Subject:** RE: 2011 Exp - BG [REDACTED] - Loss of power steering, lamp on, 18 mi, BD 12/16/10

Why can't it leave tonight and be at the dealership tomorrow? Some Michigan dealerships aren't even open on Saturdays.

Brad

---

**From:** Gregory Sheets [mailto:Gregory.Sheets@TRW.COM]  
**Sent:** Thursday, January 13, 2011 1:13 PM  
**To:** Estes, Eric (E.E.); Mrozek, Robert (R.M.); Snider, Tim (T.O.)  
**Cc:** Jackson, Bradley (B.G.); Napoli, Laura (L.); Anthony Fleenor; Michael Fontana; Pat Messer; Sergio Alvarez; Simon Malsbury  
**Subject:** RE: 2011 Exp - BG [REDACTED] - Loss of power steering, lamp on, 18 mi, BD 12/16/10

The replacement gear will leave TRW Marion on Friday, via FEDEX for a Saturday delivery at the dealership.

Greg Sheets  
Quality Manager  
TRW Automotive  
Marion Assembly Operations  
276-783-1284

>>> "Estes, Eric (E.E.)" <eestes@ford.com> 1/13/2011 12:02 PM >>>  
That's the one we need, can that be direct shipped?

Eric

**From:** Gregory Sheets [mailto:Gregory.Sheets@TRW.COM]  
**Sent:** Thursday, January 13, 2011 11:59 AM  
**To:** Estes, Eric (E.E.); Mrozek, Robert (R.M.); Snider, Tim (T.O.)  
**Cc:** Jackson, Bradley (B.G.); Napoli, Laura (L.); Anthony Fleenor; Michael Fontana; Simon Malsbury  
**Subject:** RE: 2011 Exp - BG [REDACTED] - Loss of power steering, lamp on, 18 mi, BD 12/16/10

The current service gear part number is up to the BG level.

BB53-3504-BG (3.5 TiVct)

Will this work for this vehicle?

Greg Sheets  
Quality Manager  
TRW Automotive  
Marion Assembly Operations  
276-783-1284

>>> "Estes, Eric (E.E.)" <eestes@ford.com> 1/13/2011 11:23 AM >>>

Greg is their any way we can get an EPAS gear direct shipped to the address below, Ford part# BB5Z-3504-BE (wo/APA 3.5L)

Atten: Clay Berry (PM)  
BROWN MOTORS INC  
Dealer Address: 2170 NORTH U.S. 31  
PETOSKEY MI 49770  
Dealer Main Phone: 231-439-3673

---

**From:** Mrozek, Robert (R.M.)  
**Sent:** Thursday, January 13, 2011 11:13 AM  
**To:** Estes, Eric (E.E.); Snider, Tim (T.O.); 'Corrine Schraffenberger'; Koszegi, Martin (M.)  
**Cc:** Jackson, Bradley (B.G.); Napoli, Laura (L.); 'Malsbury, Simon'; 'Michael Fontana'  
**Subject:** RE: 2011 Exp - BG [REDACTED] - Loss of power steering, lamp on, 18 mi, BD 12/16/10

Can we send him a gear straight from Marion?

*Rob Mrozek*

Electric Power Steering Supervisor  
C346N/CD3/D3/D4/U502/Police/Limo Programs  
Ford Motor Company  
Phone: (313) 805-5947  
e-mail: rmrozek@ford.com

---

**From:** Estes, Eric (E.E.)  
**Sent:** Thursday, January 13, 2011 10:37 AM  
**To:** Snider, Tim (T.O.); Corrine Schraffenberger; Koszegi, Martin (M.)  
**Cc:** Jackson, Bradley (B.G.); Mrozek, Robert (R.M.); Napoli, Laura (L.); Malsbury, Simon; 'Michael Fontana'  
**Subject:** RE: 2011 Exp - BG [REDACTED] - Loss of power steering, lamp on, 18 mi, BD 12/16/10

Just talked to the tech he will go back through Interactive diagnosis and he has a B3A motor relay code. The code is intermittent but this code reset right after start-up and vehicle was in a hot soak. This Explorer is a stock unit at the dealer, its not a sold unit but customers are looking to road test this new vehicle.

Corrine/ Martin this EPAS gear BB5Z- 3504-BE is on back order do we know when we will have stock?

I need to get this dealer a gear as soon as possible, can we direct ship them a gear? P&A code 09618

Atten: Clay Berry (PM)

Dealer Address: BROWN MOTORS INC  
2170 NORTH U.S. 31  
PETOSKEY MI 49770  
Dealer Main Phone: 231-439-3673

Let me know thanks

*Eric J Estes*

TRW EPAS Steering Systems  
Quality Specialist  
Hotline ph# 313-317-9358  
Cell ph# 734-560-3493

---

**From:** Snider, Tim (T.O.)  
**Sent:** Thursday, January 13, 2011 9:46 AM  
**To:** Estes, Eric (E.E.)  
**Cc:** Jackson, Bradley (B.G.); Mrozek, Robert (R.M.); Napoli, Laura (L.)  
**Subject:** RE: 2011 Exp - BG [REDACTED] - Loss of power steering, lamp on, 18 mi, BD 12/16/10

Eric,

Probably a good time to discuss this, do you have a hot request in place for all US U502 EPAS warranty gears??

Regards,  
Tim Snider (tsnider1@ford.com)  
**CD3/C489 Steering Engineering**  
**Ford Motor Company**  
Cell 313-805-3201  
2B-L18 Product Development Center  
Dearborn, MI 48124 USA

---

**From:** Estes, Eric (E.E.)  
**Sent:** Thursday, January 13, 2011 9:44 AM  
**To:** Mrozek, Robert (R.M.); Napoli, Laura (L.)  
**Cc:** Jackson, Bradley (B.G.); Snider, Tim (T.O.)  
**Subject:** RE: 2011 Exp - BG [REDACTED] - Loss of power steering, lamp on, 18 mi, BD 12/16/10

I will hot process the gear back to WPAC

Eric

---

**From:** Mrozek, Robert (R.M.)  
**Sent:** Thursday, January 13, 2011 9:43 AM  
**To:** Napoli, Laura (L.); Estes, Eric (E.E.)  
**Cc:** Jackson, Bradley (B.G.); Snider, Tim (T.O.)  
**Subject:** RE: 2011 Exp - BG [REDACTED] Loss of power steering, lamp on, 18 mi, BD 12/16/10

Thanks Tim. I would expect the same. But we need to get the part to TRW for asap analysis.

*Rob Mrozek*

Electric Power Steering Supervisor  
C346N/CD3/D3/D4/U502/Police/Limo Programs  
Ford Motor Company  
Phone: (313) 805-5947  
e-mail: rmrozek@ford.com

---

**From:** Snider, Tim (T.O.)  
**Sent:** Thursday, January 13, 2011 9:41 AM  
**To:** Mrozek, Robert (R.M.); Jackson, Bradley (B.G.); Napoli, Laura (L.); Estes, Eric (E.E.)  
**Subject:** RE: 2011 Exp - BG [REDACTED] - Loss of power steering, lamp on, 18 mi, BD 12/16/10

Just some background, on CD3 DTC 2011-49 is usually a reverse fitted capacitor, raised rivet, offset bridge, plastic contamination, or B6B relay.

Regards,  
Tim Snider (tsnider1@ford.com)  
**CD3/C489 Steering Engineering**  
**Ford Motor Company**  
Cell 313-805-3201  
2B-L18 Product Development Center  
Dearborn, MI 48124 USA

---

**From:** Mrozek, Robert (R.M.)  
**Sent:** Thursday, January 13, 2011 9:28 AM  
**To:** Jackson, Bradley (B.G.); Napoli, Laura (L.); Estes, Eric (E.E.)  
**Cc:** Snider, Tim (T.O.); Mrozek, Robert (R.M.)  
**Subject:** FW: 2011 Exp - BG [REDACTED] - Loss of power steering, lamp on, 18 mi, BD 12/16/10  
**Importance:** High

Brad - Damn it! I should have shut my mouth yesterday.

Laura - Please dig into this asap.

Eric - What can you tell us about the codes or any other info on this gear?

*Rob Mrozek*

Electric Power Steering Supervisor  
C346N/CD3/D3/D4/U502/Police/Limo Programs  
Ford Motor Company  
Phone: (313) 805-5947  
e-mail: rmrozek@ford.com

---

**From:** Saleh, Salim (S.A.)  
**Sent:** Thursday, January 13, 2011 9:24 AM  
**To:** Napoli, Laura (L.); Pasquarella, Michael (M.S.); Mrozek, Robert (R.M.)  
**Subject:** FW: 2011 Exp - BG [REDACTED] - Loss of power steering, lamp on, 18 mi, BD 12/16/10

fyi..

**Salim Saleh**

U502 Explorer  
Chassis PMT Leader  
Phone: (313)805-2451 Fax: (313)322-0744  
ssaleh@ford.com Cubicle: 2B-L37  
<http://vm7.dearborn.ford.com/cgi/textpage>

---

**From:** Buelow, Steve (S.E.)  
**Sent:** Thursday, January 13, 2011 9:22 AM  
**To:** Adamczyk, David (D.W.); Bollwahn, Bryce (B.A.); Centlivre, James (J.C.); Cittadino, Lisa (L.C.); Collins, Kevin (K.E.); Gagnier, Kathryn (K.A.); Gilewski, David (D.); Gubing, William (Bill.); Hays, Andy (A.R.); Henker, Scott (S.); Holland, James (J.P.); Lubin Henney, Michele (MLH.); Lysik, Kevin (K.M.); Mann, Mickey (N.S.); McClain, Shawn (S.M.); Pogorzelski, John (J.M.); Rodgers, Chuck (.); Saleh, Salim (S.A.); Sellers, Gary (G.T.); Simkus, Walter (W.A.); Smith, Scott (S.A.); Sokolowski, Todd (T.M.); Thornsberry, Joel (J.A.); Willis, Mark (M.E.); Wong, Vicki (V.A.); Abrams, Donald (D.); Acuna, Aaron (A.A.); Allman, Jan (J.E.); Bell, Tim (.); Bergeron, Matthew (M.C.); Bisaga, Richard (R.); Boykin, George (G.); Boykins, Michael (M.); Bustamante, Chris (C.T.); Cantrell, David (D.D.); Ciotti, Steven (S.R.); Davis, Charlene (C.); Devine, Robert (R.M.); Docimo, Tony (A.F.); Elting, Tim (T.H.); Ferguson, Hugh (H.); Gagnier, Scott (S.W.); Greenwell, R (R.); Guyton, MzJenny (J.); Hernandez, Thomas (T.); Herron, Micheal (M.C.); Inglis, Steve (S.D.); Iqbal, Khurram (K.); Jones, Frederick (F.L.); Little, Janie (J.); Martin, Kenneth (K.A.); Matlock, Douglas (D.); McElroy, Darin (D.L.); McKernan, Patrick (P.J.); Miller, Melinda (M.S.); Moore, Chikynda (D.); Moses, Barry (B.A.); Moskwa, Larry (L.M.); Perkins, John (J.E.); Pesch, Vincent (V.J.); Rutovic, Nick (N.); Sarkisian, Mark (Z.); Talbott, Larry (J.L.); Turner, Bridgette (B.); Turner, Patrice (P.T.); Vandergroef, Cornelius (C.); Washington, Kellie (K.S.); Wertman, David Brian (D.B.); Westbrook, Dori (D.); Williams, Erik (E.C.); Williams, Gregory (G.M.); Williams, TRACE (S.); Wyatt, Kimberly (K.D.); Zroback, David (D.P.); Evans, Kayekethia (K.); Gibson, Renelda (R.); Lakomek, Scott (S.); Ornelas, Demetrio (D.); Ratliff, Kathy (K.); Stonewall, Wendy (M.); Svetich, Chris (C.); Anderson, Eric (H.); Berzeri, Marcello (M.); Chamberlain, Steve (J.); Edwards, Monty (M.R.); Farmer, Marty (M.F.); Feder, Andrew (A.); Gerrard, Ryan (R.P.); Iannotti, Jason (JRI.); Ickes, Walt (W.D.); Imperati, Daniel (D.); Issa, Ibrahim (I.M.); Jackson, Bradley (B.G.); Logli, Michael (M.A.); Morgan, Anthony (A.); Olsson, Paul (P.C.); Polaski, Mike (M.S.); Porter, Alan (A.T.); Rapiz, Noreen (N.G.); Siddiqui, Saif (S.S.); Sluis, Jim (JS.); Smith, Erin (E.); Sridhara, Raghu (R.); Trygar, Mike (M.); Vargo, Rebecca (R.L.); Widrick, Brad (B.A.); Young, Richard (R.C.); Yu,



Eric (E.); Buelow, Steve (S.E.)

**Subject:** FW: 2011 Exp - BG [REDACTED] - Loss of power steering, lamp on, 18 mi, BD 12/16/10

**-The Customer Defines Quality-**

*Steve Buelow - Ford Motor Company*

FCSD Program Manager-  
Taurus/Taurus SHO/Lincoln MKS/Explorer  
Chicago Assembly PVT Office, COE  
773-646-7495 DialNet 686-7495  
Cell 313-805-8334 sbuelow@ford.com

"You miss 100 percent of the shots you never take." - Wayne Gretzky

---

**From:** SBUELOW@ford.com [mailto:SBUELOW@ford.com]  
**Sent:** Thursday, January 13, 2011 8:15 AM  
**To:** Buelow, Steve (S.E.)  
**Subject:** 2011 Exp - BG [REDACTED] - Loss of power steering, lamp on, 18 mi, BD 12/16/10

**Attachments :** 0

<b>Report# :</b>	BALEI002 NHL	<b>Received:</b>	01/12/2011
<b>CCRG/EPRC:</b>		<b>Date:</b>	
<b>Vehicle:</b>	2011,EXPLORER 4X4 (U502),4 DOOR ,MP,1FMHK8D83BG [REDACTED]	<b>Build Date:</b>	12/16/2010
<b>Odometer :</b>	18 M	<b>Engine:</b>	3.5L CYCLO
<b>Transmission:</b>	6F55	<b>Axle:</b>	
<b>Dealer:</b>	USA 09618 Brown Motors, Inc.	<b>Calibration:</b>	BUB1ST0A
<b>City:</b>	Petoskey	<b>A/C:</b>	YES
<b>Originator:</b>	JIM MILBRANDT	<b>Phone#:</b>	(231!!) 439- 9604
<b>Symptom:</b>	3 03 1 50 CHASS.,STRG/HANDLING ,FUNCTION,HIGH EFFORT	<b>Country :</b>	USA
<b>Status:</b>			
<b>VFG:</b>	V87 STEERING		
<b>Additional Symptom:</b>	LOSS OF POWER STEERING		
<b>Fix:</b>	<b>Causal Component :</b>		
<b>Condition Code:</b>			

**Hotliner:** DMU!! RRA86

**Phone:** 313 248-8233

**Regn Cd:** G2 Detroit

**Engineering:**

**Phone:**

**TAR:**

**Dlr Contact:** JIM MILBRANDT

**Phone:** 231 439-3673

**Title Cde:** T

**DTCs:**

KOEO:U0253 U2011

KOEC:

KOER:

**Comments**

:

**REPAIR** 01/12/2011 02:45PM DOUGLAS MURRAY MSS - FCSD - TECH SVC HOTLINE  
WEB FORM DATA - CONCERN: CUSTOMER STATES WHEN ON TEST DRIVE THE  
POWER  
STEERING QUIT AND A RED INDICATOR LIGHT CAME ONE. DIAGNOSTICS:  
PERFORMED IDS TESTS U0253:00-28 IPC U2011:49-08 PSCM IN MEMORY  
PARTS REPLACED:: NONE TECH QUESTION: ANY REPORTS FOR THIS  
CONCERN? WERE YOU ABLE TO VERIFY THE CONCERN? NO IS THERE AN  
APPROPRIATE PINPOINT TEST IN THE WSM FOR THIS CONCERN? WAS THE  
PINPOINT TEST FOLLOWED?

**RECOMM** 01/12/2011 02:45PM DOUGLAS MURRAY MSS - FCSD - TECH SVC HOTLINE  
JIM, IT IS RECOMMENDED TO GO TO THE WSM SECTION 211-00/DIAGNOSIS  
AND TESTING/DTC AND SYMPTOM CHARTS/INTERACTIVE DIAGNOSTICS AND GO  
TO  
THE INTERACTIVE DIAGNOSTICS SECTION. FROM THERE, GO TO THE DTC LIST  
AND LOOK UP U2011. THIS IS A MOTOR CODE AND THERE ARE 2 DIFFERENT PPT  
TESTS DEPENDING ON WHICH BITMAP CODE YOU HAVE. THIS CODE INDICATES  
THAT THE PSCM HAS SEEN A MOTOR ISSUE AND WILL SHUT DOWN THE POWER  
ASSIST FUNCTION. PLEASE TRY TO DUPLICATE THE CONCERN AND IF CODE  
U2011 SETS, PERFORM THE APPROPRIATE CHART. THERE ARE NO COMMON  
TRENDS FOR THIS CONCERN. THANK YOU.

---

**From:** Mrozek, Robert (R.M.)  
**Sent:** Thursday, January 13, 2011 9:49 AM  
**To:** Napoli, Laura (L.)  
**Subject:** FW: 2011 Exp - BG [REDACTED] - Loss of power steering, lamp on, 18 mi, BD 12/16/10

*Rob Mrozek*

Electric Power Steering Supervisor  
C346N/CD3/D3/D4/U502/Police/Limo Programs  
Ford Motor Company  
Phone: (313) 805-5947  
e-mail: rmrozek@ford.com

---

**From:** Estes, Eric (E.E.)  
**Sent:** Thursday, January 13, 2011 9:49 AM  
**To:** Mrozek, Robert (R.M.)  
**Cc:** Snider, Tim (T.O.)  
**Subject:** RE: 2011 Exp - BG [REDACTED] - Loss of power steering, lamp on, 18 mi, BD 12/16/10

I looked at Interactive diagnosis and cannot tell if the tech cleared the code and the code reset look below

**Year = MY11**  
**Model = U502**  
**Engine =**  
**VIN = 1FMHK8D83BG [REDACTED]**  
**IDS Version = Not Available**

---

**Start: Wed Jan 12 15:50:58 EST 2011**

---

Menu Selection: DTC U2011 (PSCM) - Motor

---

☐ B: DTCs C1B00, C200B, C200C, C200D, U2011, U2200 and U3000: Steering Angle Sensor, Steering Shaft Torque Sensor 1, Steering Shaft Torque Sensor 2, Motor and Control Module - Failure or Erratic

Normal Operation

The power steering control module (PSCM) monitors various inputs and outputs of the electronic power assist steering (EPAS) system in order to keep the system operating at peak capacity. Information provided by sensors (steering torque, vehicle speed, vehicle travel distance, etc.) are all compared to programmed and learned information. Likewise, outputs like the motor and steering rack (travel) are tested against programmed and learned information.

Note:

If a damaged bellows boot(s) was discovered during Inspection and Verification and this pinpoint test DOES NOT lead to the installation of a new EPAS gear or bellows boot(s), then go to Pinpoint Test K to address the damaged boot(s) before returning the vehicle to the customer.

---

☐ B1: CHECK FOR PREVIOUSLY SET DTCS

- Go to KNOWN CONCERNS.

Check for DTCs listed in the section: System Related CMDTCs cleared since initial read.

- Are any of the following DTCs present?

PSCM DTCs C1B00:2F, C1B00:62, C200B:2F, C200B:61, C200B:62, U2011:49, U2011:61, U2200:54, U3000:41, U3000:46, U3000:49.

Yes

Go to B2.

No

Go to B2.

---

**Exit: Wed Jan 12 15:51:44 EST 2011**

---

**From:** Mrozek, Robert (R.M.)

**Sent:** Thursday, January 13, 2011 9:45 AM

**To:** Estes, Eric (E.E.)

**Subject:** RE: 2011 Exp - BG [REDACTED] - Loss of power steering, lamp on, 18 mi, BD 12/16/10

Is there anything else you can find from the available on-line systems? Please compile all you can. Thanks Eric.

*Rob Mrozek*

Electric Power Steering Supervisor  
C346N/CD3/D3/D4/U502/Police/Limo Programs  
Ford Motor Company  
Phone: (313) 805-5947  
e-mail: rmrozek@ford.com

---

**From:** Estes, Eric (E.E.)

**Sent:** Thursday, January 13, 2011 9:43 AM

**To:** Mrozek, Robert (R.M.); Jackson, Bradley (B.G.); Napoli, Laura (L.)

**Cc:** Snider, Tim (T.O.)

**Subject:** RE: 2011 Exp - BG [REDACTED] - Loss of power steering, lamp on, 18 mi, BD 12/16/10

This is a B3A or B6B code most likely, but it also could be a BB5-BB9 code which is a motor phase voltage high or low fault

Eric

---

**From:** Mrozek, Robert (R.M.)

**Sent:** Thursday, January 13, 2011 9:28 AM

**To:** Jackson, Bradley (B.G.); Napoli, Laura (L.); Estes, Eric (E.E.)

**Cc:** Snider, Tim (T.O.); Mrozek, Robert (R.M.)

**Subject:** FW: 2011 Exp - BG [REDACTED] - Loss of power steering, lamp on, 18 mi, BD 12/16/10

**Importance:** High

Brad - Damn it! I should have shut my mouth yesterday.

Laura - Please dig into this asap.

Eric - What can you tell us about the codes or any other info on this gear?

*Rob Mrozek*

Electric Power Steering Supervisor  
C346N/CD3/D3/D4/U502/Police/Limo Programs  
Ford Motor Company  
Phone: (313) 805-5947  
e-mail: rmrozek@ford.com

---

**From:** Saleh, Salim (S.A.)  
**Sent:** Thursday, January 13, 2011 9:24 AM  
**To:** Napoli, Laura (L.); Pasquarella, Michael (M.S.); Mrozek, Robert (R.M.)  
**Subject:** FW: 2011 Exp - BG [REDACTED] - Loss of power steering, lamp on, 18 mi, BD 12/16/10

fyi..

**Salim Saleh**

U502 Explorer  
Chassis PMT Leader  
Phone: (313)805-2451 Fax: (313)322-0744  
ssaleh@ford.com Cubicle: 2B-L37  
<http://vm7.dearborn.ford.com/cgi/textpage>

---

**From:** Buelow, Steve (S.E.)  
**Sent:** Thursday, January 13, 2011 9:22 AM  
**To:** Adamczyk, David (D.W.); Bollwahn, Bryce (B.A.); Centlivre, James (J.C.); Cittadino, Lisa (L.C.); Collins, Kevin (K.E.); Gagnier, Kathryn (K.A.); Gilewski, David (D.); Gubing, William (Bill.); Hays, Andy (A.R.); Henker, Scott (S.); Holland, James (J.P.); Lubin Henney, Michele (MLH.); Lysik, Kevin (K.M.); Mann, Mickey (N.S.); McClain, Shawn (S.M.); Pogorzelski, John (J.M.); Rodgers, Chuck (.); Saleh, Salim (S.A.); Sellers, Gary (G.T.); Simkus, Walter (W.A.); Smith, Scott (S.A.); Sokolowski, Todd (T.M.); Thornsberry, Joel (J.A.); Willis, Mark (M.E.); Wong, Vicki (V.A.); Abrams, Donald (D.); Acuna, Aaron (A.A.); Allman, Jan (J.E.); Bell, Tim (.); Bergeron, Matthew (M.C.); Bisaga, Richard (R.); Boykin, George (G.); Boykins, Michael (M.); Bustamante, Chris (C.T.); Cantrell, David (D.D.); Ciotti, Steven (S.R.); Davis, Charlene (C.); Devine, Robert (R.M.); Docimo, Tony (A.F.); Elting, Tim (T.H.); Ferguson, Hugh (H.); Gagnier, Scott (S.W.); Greenwell, R (R.); Guyton, MzJenny (J.); Hernandez, Thomas (T.); Herron, Micheal (M.C.); Inglis, Steve (S.D.); Iqbal, Khurram (K.); Jones, Frederick (F.L.); Little, Janie (J.); Martin, Kenneth (K.A.); Matlock, Douglas (D.); McElroy, Darin (D.L.); McKernan, Patrick (P.J.); Miller, Melinda (M.S.); Moore, Chikynda (D.); Moses, Barry (B.A.); Moskwa, Larry (L.M.); Perkins, John (J.E.); Pesch, Vincent (V.J.); Rutovic, Nick (N.); Sarkisian, Mark (Z.); Talbott, Larry (J.L.); Turner, Bridgette (B.); Turner, Patrice (P.T.); Vandergroef, Cornelius (C.); Washington, Kellie (K.S.); Wertman, David Brian (D.B.); Westbrook, Dori (D.); Williams, Erik (E.C.); Williams, Gregory (G.M.); Williams, TRACE (S.); Wyatt, Kimberly (K.D.); Zroback, David (D.P.); Evans, Kayekethia (K.); Gibson, Renelda (R.); Lakomek, Scott (S.); Ornelas, Demetrio (D.); Ratliff, Kathy (K.); Stonewall, Wendy (M.); Svetich, Chris (C.); Anderson, Eric (H.); Berzeri, Marcello (M.); Chamberlain, Steve (J.); Edwards, Monty (M.R.); Farmer, Marty (M.F.); Feder, Andrew (A.); Gerrard, Ryan (R.P.); Iannotti, Jason (JRI.); Ickes, Walt (W.D.); Imperati, Daniel (D.); Issa, Ibrahim (I.M.); Jackson, Bradley (B.G.); Logli, Michael (M.A.); Morgan, Anthony (A.); Olsson,

Paul (P.C.); Polaski, Mike (M.S.); Porter, Alan (A.T.); Rapiz, Noreen (N.G.); Siddiqui, Saif (S.S.); Sluis, Jim (JS.); Smith, Erin (E.); Sridhara, Raghu (R.); Trygar, Mike (M.); Vargo, Rebecca (R.L.); Widrick, Brad (B.A.); Young, Richard (R.C.); Yu, Eric (E.); Buelow, Steve (S.E.)

**Subject:** FW: 2011 Exp - BG [REDACTED] - Loss of power steering, lamp on, 18 mi, BD 12/16/10

**-The Customer Defines Quality-**

*Steve Buelow - Ford Motor Company*

FCSD Program Manager-  
Taurus/Taurus SHO/Lincoln MKS/Explorer  
Chicago Assembly PVT Office, COE  
773-646-7495 DialNet 686-7495  
Cell 313-805-8334 sbuelow@ford.com

"You miss 100 percent of the shots you never take." - Wayne Gretzky

---

**From:** SBUELOW@ford.com [mailto:SBUELOW@ford.com]  
**Sent:** Thursday, January 13, 2011 8:15 AM  
**To:** Buelow, Steve (S.E.)  
**Subject:** 2011 Exp - BG [REDACTED] - Loss of power steering, lamp on, 18 mi, BD 12/16/10

**Attachments :** 0

<b>Report# :</b>	BALEI002 NHL	<b>Received:</b>	01/12/2011
<b>CCRG/EPRC:</b>		<b>Date:</b>	
<b>Vehicle:</b>	2011,EXPLORER 4X4 (U502),4 DOOR ,MP,1FMHK8D83BG [REDACTED]	<b>Build Date:</b>	12/16/2010
<b>Odometer :</b>	18 M	<b>Engine:</b>	3.5L CYCLO
<b>Transmission:</b>	6F55	<b>Axle:</b>	
<b>Dealer:</b>	USA 09618 Brown Motors, Inc.	<b>Calibration:</b>	BUB1ST0A
<b>City:</b>	Petoskey	<b>A/C:</b>	YES
<b>Originator:</b>	JIM MILBRANDT	<b>Phone#:</b>	(231!!) 439- 9604
<b>Symptom:</b>	3 03 1 50 CHASS.,STRG/HANDLING ,FUNCTION,HIGH EFFORT	<b>Country :</b>	USA
<b>Status:</b>			
<b>VFG:</b>	V87 STEERING		
<b>Additional Symptom:</b>	LOSS OF POWER STEERING		
<b>Fix:</b>	<b>Causal Component :</b>		
<b>Condition Code:</b>			

**Hotliner:** DMU!! RRA86

**Phone:** 313 248-8233

**Regn Cd:** G2 Detroit

**Engineering:**

**Phone:**

**TAR:**

**Dlr Contact:** JIM MILBRANDT

**Phone:** 231 439-3673

**Title Cde:** T

**DTCs:**

KOEO:U0253 U2011

KOEC:

KOER:

**Comments**

:

**REPAIR** 01/12/2011 02:45PM DOUGLAS MURRAY MSS - FCSD - TECH SVC HOTLINE  
WEB FORM DATA - CONCERN: CUSTOMER STATES WHEN ON TEST DRIVE THE  
POWER

STEERING QUIT AND A RED INDICATOR LIGHT CAME ONE. DIAGNOSTICS:  
PERFORMED IDS TESTS U0253:00-28 IPC U2011:49-08 PSCM IN MEMORY  
PARTS REPLACED:: NONE TECH QUESTION: ANY REPORTS FOR THIS  
CONCERN? WERE YOU ABLE TO VERIFY THE CONCERN? NO IS THERE AN  
APPROPRIATE PINPOINT TEST IN THE WSM FOR THIS CONCERN? WAS THE  
PINPOINT TEST FOLLOWED?

**RECOMM** 01/12/2011 02:45PM DOUGLAS MURRAY MSS - FCSD - TECH SVC HOTLINE  
JIM, IT IS RECOMMENDED TO GO TO THE WSM SECTION 211-00/DIAGNOSIS  
AND TESTING/DTC AND SYMPTOM CHARTS/INTERACTIVE DIAGNOSTICS AND GO  
TO

THE INTERACTIVE DIAGNOSTICS SECTION. FROM THERE, GO TO THE DTC LIST  
AND LOOK UP U2011. THIS IS A MOTOR CODE AND THERE ARE 2 DIFFERENT PPT  
TESTS DEPENDING ON WHICH BITMAP CODE YOU HAVE. THIS CODE INDICATES  
THAT THE PSCM HAS SEEN A MOTOR ISSUE AND WILL SHUT DOWN THE POWER  
ASSIST FUNCTION. PLEASE TRY TO DUPLICATE THE CONCERN AND IF CODE  
U2011 SETS, PERFORM THE APPROPRIATE CHART. THERE ARE NO COMMON  
TRENDS FOR THIS CONCERN. THANK YOU.

---

**From:** Napoli, Laura (L.)  
**Sent:** Saturday, January 15, 2011 12:23 PM  
**To:** Anderson, Eric (H.); Jackson, Bradley (B.G.)  
**Subject:** FW: 2011 Exp - BG [REDACTED] - Loss of power steering, lamp on, 18 mi, BD 12/16/10

**Importance:** High

Eric,  
Not sure if Brad already forwarded you the chain of emails on this claim. Brad has been pushing TRW to get this gear back quickly. The fault code points to a motor relay failure. We need to test the gear to verify.

Brad,  
Did you get an answer from Eric Estes on Fri to your suggestion of using your FedEx account to get the gear back more quickly than following the parts return process? I didn't see any notes on Fri, and didn't get a chance to call Eric directly.

Regards,

*Laura Napoli*

U502 EPAS  
Ford Motor Company  
Cube: 2B-G66 PDC  
Phone: 313.323.0634  
Mobile: 313.805.0482

---

**From:** Jackson, Bradley (B.G.)  
**Sent:** Thursday, January 13, 2011 5:17 PM  
**To:** Estes, Eric (E.E.)  
**Cc:** Mrozek, Robert (R.M.)  
**Subject:** RE: 2011 Exp - BG [REDACTED] - Loss of power steering, lamp on, 18 mi, BD 12/16/10

Eric, I know exactly how the system works. I use it everyday. I also know how to circumvent the process to make things happen quickly when needed. We can send parts directly to the dealer, the dealer receives the part and replaces old, and sends out the old part under my FedEx account number at the same time. When the dealer puts the claim into the system, he just claims the labor....since we supplied the part.

U502 is under a microscope right now and we are being required to report out to senior mgmt on every single claim and CQIS report coming in every day. The longer it takes for analysis, the more energy is going to be wrapped around the issue.

Brad

---

**From:** Estes, Eric (E.E.)  
**Sent:** Thursday, January 13, 2011 3:57 PM  
**To:** Jackson, Bradley (B.G.)  
**Cc:** Mrozek, Robert (R.M.)  
**Subject:** RE: 2011 Exp - BG [REDACTED] - Loss of power steering, lamp on, 18 mi, BD 12/16/10



Bradley welcome to the new parts return system at Ford WPAC.

Here is the time line after the claim at the dealer is totally closed. The claim is not send by UPS until it show's up on the PEAR's register then add 3-5 days to WPAC. Not much of a hot process return system but this is how the new system works since July 2010. It will take 2-3 weeks for parts to return under the normal parts return system.

Here is an example:

Monday night Claim Paid

Tuesday morning visible in AWS

Tuesday/Wednesday submit request for part

Wednesday night PEARS 700Tag generates

Thursday morning Tag shows up on Dealers PEARS Register

*Eric J Estes*

TRW EPAS Steering Systems  
Quality Specialist  
Hotline ph# 313-317-9358  
Cell ph# 734-560-3493

---

**From:** Jackson, Bradley (B.G.)  
**Sent:** Thursday, January 13, 2011 4:17 PM  
**To:** Estes, Eric (E.E.)  
**Cc:** Mrozek, Robert (R.M.)  
**Subject:** RE: 2011 Exp - BG [REDACTED] - Loss of power steering, lamp on, 18 mi, BD 12/16/10

Eric, there doesn't seem to be much urgency to get this gear back. We are being pushed very hard for every CQIS report coming in. Would you rather me ship a gear directly out of ZF tonight? I have 1.5 hours that I could get a gear into FedEx tonight. How do we make this happen sooner rather than later?

Brad

---

**From:** Estes, Eric (E.E.)  
**Sent:** Thursday, January 13, 2011 3:03 PM  
**To:** Jackson, Bradley (B.G.)  
**Subject:** RE: 2011 Exp - BG [REDACTED] - Loss of power steering, lamp on, 18 mi, BD 12/16/10

No I will call the dealer on Monday and make sure the RO paperwork is filled out properly and closed so we can get the gear back hopefully by the end of next week.

Eric

---

**From:** Jackson, Bradley (B.G.)  
**Sent:** Thursday, January 13, 2011 3:53 PM  
**To:** Estes, Eric (E.E.)  
**Subject:** RE: 2011 Exp - BG [REDACTED] - Loss of power steering, lamp on, 18 mi, BD 12/16/10

Eric, is getting the replacement gear going to hold up getting the suspect gear back for analysis?

Brad

---

**From:** Estes, Eric (E.E.)  
**Sent:** Thursday, January 13, 2011 2:39 PM  
**To:** Jackson, Bradley (B.G.); 'Gregory Sheets'; Mrozek, Robert (R.M.); Snider, Tim (T.O.)  
**Cc:** Napoli, Laura (L.); 'Anthony Fleenor'; 'Michael Fontana'; 'Pat Messer'; 'Sergio Alvarez'; 'Simon Malsbury'  
**Subject:** RE: 2011 Exp - BG [REDACTED] - Loss of power steering, lamp on, 18 mi, BD 12/16/10

Talked to the part manager and the dealer is open till 2pm on Saturday so hopefully the delivery will get their before then, if not it will be delivered on Monday.  
Dealer probably will not do the job till Monday anyway.

*Eric J Estes*

TRW EPAS Steering Systems  
Quality Specialist  
Hotline ph# 313-317-9358  
Cell ph# 734-560-3493

---

**From:** Jackson, Bradley (B.G.)  
**Sent:** Thursday, January 13, 2011 2:15 PM  
**To:** 'Gregory Sheets'; Estes, Eric (E.E.); Mrozek, Robert (R.M.); Snider, Tim (T.O.)  
**Cc:** Napoli, Laura (L.); Anthony Fleenor; Michael Fontana; Pat Messer; Sergio Alvarez; Simon Malsbury  
**Subject:** RE: 2011 Exp - BG [REDACTED] - Loss of power steering, lamp on, 18 mi, BD 12/16/10

Why can't it leave tonight and be at the dealership tomorrow? Some Michigan dealerships aren't even open on Saturdays.

Brad

---

**From:** Gregory Sheets [mailto:Gregory.Sheets@TRW.COM]  
**Sent:** Thursday, January 13, 2011 1:13 PM  
**To:** Estes, Eric (E.E.); Mrozek, Robert (R.M.); Snider, Tim (T.O.)  
**Cc:** Jackson, Bradley (B.G.); Napoli, Laura (L.); Anthony Fleenor; Michael Fontana; Pat Messer; Sergio Alvarez; Simon Malsbury  
**Subject:** RE: 2011 Exp - BG [REDACTED] - Loss of power steering, lamp on, 18 mi, BD 12/16/10

The replacement gear will leave TRW Marion on Friday, via FEDEX for a Saturday delivery at the dealership.

Greg Sheets  
Quality Manager  
TRW Automotive  
Marion Assembly Operations  
276-783-1284

>>> "Estes, Eric (E.E.)" <eestes@ford.com> 1/13/2011 12:02 PM >>>  
That's the one we need, can that be direct shipped?

Eric

---

**From:** Gregory Sheets [mailto:Gregory.Sheets@TRW.COM]  
**Sent:** Thursday, January 13, 2011 11:59 AM  
**To:** Estes, Eric (E.E.); Mrozek, Robert (R.M.); Snider, Tim (T.O.)  
**Cc:** Jackson, Bradley (B.G.); Napoli, Laura (L.); Anthony Fleenor; Michael Fontana; Simon Malsbury  
**Subject:** RE: 2011 Exp - BG [REDACTED] - Loss of power steering, lamp on, 18 mi, BD 12/16/10

The current service gear part number is up to the BG level.

BB53-3504-BG (3.5 TiVct)

Will this work for this vehicle?

Greg Sheets  
Quality Manager  
TRW Automotive  
Marion Assembly Operations  
276-783-1284

>>> "Estes, Eric (E.E.)" <eestes@ford.com> 1/13/2011 11:23 AM >>>  
Greg is their any way we can get an EPAS gear direct shipped to the address below, Ford part# BB5Z-3504-BE (wo/APA 3.5L)

Atten: Clay Berry (PM)  
BROWN MOTORS INC  
Dealer Address: 2170 NORTH U.S. 31  
PETOSKEY MI 49770  
Dealer Main Phone: 231-439-3673

---

**From:** Mrozek, Robert (R.M.)  
**Sent:** Thursday, January 13, 2011 11:13 AM  
**To:** Estes, Eric (E.E.); Snider, Tim (T.O.); 'Corrine Schraffenberger'; Koszegi, Martin (M.)  
**Cc:** Jackson, Bradley (B.G.); Napoli, Laura (L.); 'Malsbury, Simon'; 'Michael Fontana'  
**Subject:** RE: 2011 Exp - BGA10846 - Loss of power steering, lamp on, 18 mi, BD 12/16/10

Can we send him a gear straight from Marion?

*Rob Mrozek*

Electric Power Steering Supervisor  
C346N/CD3/D3/D4/U502/Police/Limo Programs  
Ford Motor Company  
Phone: (313) 805-5947  
e-mail: rmrozek@ford.com

---

**From:** Estes, Eric (E.E.)  
**Sent:** Thursday, January 13, 2011 10:37 AM  
**To:** Snider, Tim (T.O.); Corrine Schraffenberger; Koszegi, Martin (M.)  
**Cc:** Jackson, Bradley (B.G.); Mrozek, Robert (R.M.); Napoli, Laura (L.); Malsbury, Simon; 'Michael Fontana'  
**Subject:** RE: 2011 Exp - BG [REDACTED] - Loss of power steering, lamp on, 18 mi, BD 12/16/10

Just talked to the tech he will go back through Interactive diagnosis and he has a B3A motor relay code. The code is intermittent but this code reset right after start-up and vehicle was in a hot soak. This Explorer is a stock unit at the dealer, its not a sold unit but customers are looking to road test this new vehicle.

Corrine/ Martin this EPAS gear BB5Z- 3504-BE is on back order do we know when we will have stock?

I need to get this dealer a gear as soon as possible, can we direct ship them a gear? P&A code 09618

Atten: Clay Berry (PM)

Dealer Address: BROWN MOTORS INC  
2170 NORTH U.S. 31  
PETOSKEY MI 49770  
Dealer Main Phone: 231-439-3673

Let me know thanks

*Eric J Estes*

TRW EPAS Steering Systems  
Quality Specialist  
Hotline ph# 313-317-9358  
Cell ph# 734-560-3493

---

**From:** Snider, Tim (T.O.)  
**Sent:** Thursday, January 13, 2011 9:46 AM  
**To:** Estes, Eric (E.E.)  
**Cc:** Jackson, Bradley (B.G.); Mrozek, Robert (R.M.); Napoli, Laura (L.)  
**Subject:** RE: 2011 Exp - BG [REDACTED] - Loss of power steering, lamp on, 18 mi, BD 12/16/10

Eric,

Probably a good time to discuss this, do you have a hot request in place for all US U502 EPAS warranty gears??

Regards,  
Tim Snider (tsnider1@ford.com)  
**CD3/C489 Steering Engineering**  
**Ford Motor Company**  
Cell 313-805-3201  
2B-L18 Product Development Center  
Dearborn, MI 48124 USA

---

**From:** Estes, Eric (E.E.)  
**Sent:** Thursday, January 13, 2011 9:44 AM  
**To:** Mrozek, Robert (R.M.); Napoli, Laura (L.)  
**Cc:** Jackson, Bradley (B.G.); Snider, Tim (T.O.)  
**Subject:** RE: 2011 Exp - BG [REDACTED] - Loss of power steering, lamp on, 18 mi, BD 12/16/10

I will not process the gear back to WPAC

Eric

---

**From:** Mrozek, Robert (R.M.)  
**Sent:** Thursday, January 13, 2011 9:43 AM  
**To:** Napoli, Laura (L.); Estes, Eric (E.E.)  
**Cc:** Jackson, Bradley (B.G.); Snider, Tim (T.O.)  
**Subject:** RE: 2011 Exp - BG [REDACTED] - Loss of power steering, lamp on, 18 mi, BD 12/16/10

Thanks Tim. I would expect the same. But we need to get the part to TRW for asap analysis.

*Rob Mrozek*

Electric Power Steering Supervisor  
C346N/CD3/D3/D4/U502/Police/Limo Programs  
Ford Motor Company  
Phone: (313) 805-5947  
e-mail: rmrozek@ford.com

---

**From:** Snider, Tim (T.O.)  
**Sent:** Thursday, January 13, 2011 9:41 AM  
**To:** Mrozek, Robert (R.M.); Jackson, Bradley (B.G.); Napoli, Laura (L.); Estes, Eric (E.E.)  
**Subject:** RE: 2011 Exp - BG [REDACTED] - Loss of power steering, lamp on, 18 mi, BD 12/16/10

Just some background, on CD3 DTC 2011-49 is usually a reverse fitted capacitor, raised rivet, offset bridge, plastic contamination, or B6B relay.

Regards,  
Tim Snider (tsnider1@ford.com)  
**CD3/C489 Steering Engineering**  
**Ford Motor Company**  
Cell 313-805-3201  
2B-L18 Product Development Center  
Dearborn, MI 48124 USA

**From:** Mrozek, Robert (R.M.)  
**Sent:** Thursday, January 13, 2011 9:28 AM  
**To:** Jackson, Bradley (B.G.); Napoli, Laura (L.); Estes, Eric (E.E.)  
**Cc:** Snider, Tim (T.O.); Mrozek, Robert (R.M.)  
**Subject:** FW: 2011 Exp - BG [REDACTED] - Loss of power steering, lamp on, 18 mi, BD 12/16/10  
**Importance:** High

Brad - Damn it! I should have shut my mouth yesterday.

Laura - Please dig into this asap.

Eric - What can you tell us about the codes or any other info on this gear?

*Rob Mrozek*

Electric Power Steering Supervisor  
C346N/CD3/D3/D4/U502/Police/Limo Programs  
Ford Motor Company  
Phone: (313) 805-5947  
e-mail: rmrozek@ford.com

---

**From:** Saleh, Salim (S.A.)  
**Sent:** Thursday, January 13, 2011 9:24 AM  
**To:** Napoli, Laura (L.); Pasquarella, Michael (M.S.); Mrozek, Robert (R.M.)  
**Subject:** FW: 2011 Exp - BG [REDACTED] - Loss of power steering, lamp on, 18 mi, BD 12/16/10

fyi..

**Salim Saleh**

U502 Explorer  
Chassis PMT Leader  
Phone: (313)805-2451 Fax: (313)322-0744  
ssaleh@ford.com Cubicle: 2B-L37  
<http://vm7.dearborn.ford.com/cgi/textpage>

---

**From:** Buelow, Steve (S.E.)  
**Sent:** Thursday, January 13, 2011 9:22 AM  
**To:** Adamczyk, David (D.W.); Bollwahn, Bryce (B.A.); Centlivre, James (J.C.); Cittadino, Lisa (L.C.); Collins, Kevin (K.E.); Gagnier, Kathryn (K.A.); Gilewski, David (D.); Gubing, William (Bill.); Hays, Andy (A.R.); Henker, Scott (S.); Holland, James (J.P.); Lubin Henney, Michele (MLH.); Lysik, Kevin (K.M.); Mann, Mickey (N.S.); McClain, Shawn (S.M.); Pogorzelski, John (J.M.); Rodgers, Chuck (.); Saleh, Salim (S.A.); Sellers, Gary (G.T.); Simkus, Walter (W.A.); Smith, Scott (S.A.); Sokolowski, Todd (T.M.); Thornsberry, Joel (J.A.); Willis, Mark (M.E.); Wong, Vicki (V.A.); Abrams, Donald (D.); Acuna, Aaron (A.A.); Allman, Jan (J.E.); Bell, Tim (.); Bergeron, Matthew (M.C.); Bisaga, Richard (R.); Boykin, George (G.); Boykins, Michael (M.); Bustamante, Chris (C.T.); Cantrell, David (D.D.); Ciotti, Steven (S.R.); Davis, Charlene (C.); Devine, Robert (R.M.); Docimo, Tony (A.F.); Elting, Tim (T.H.); Ferguson, Hugh (H.); Gagnier, Scott (S.W.); Greenwell, R (R.); Guyton, MzJenny (J.); Hernandez, Thomas (T.); Herron, Micheal (M.C.); Inglis, Steve (S.D.); Iqbal, Khurram (K.); Jones, Frederick (F.L.); Little, Janie (J.); Martin, Kenneth (K.A.); Matlock, Douglas (D.); McElroy, Darin (D.L.); McKernan, Patrick (P.J.); Miller, Melinda (M.S.); Moore, Chikynda (D.); Moses, Barry (B.A.); Moskwa, Larry (L.M.); Perkins, John

(J.E.); Pesch, Vincent (V.J.); Rutovic, Nick (N.); Sarkisian, Mark (Z.); Talbott, Larry (J.L.); Turner, Bridgette (B.); Turner, Patrice (P.T.); Vandergroef, Cornelius (C.); Washington, Kellie (K.S.); Wertman, David Brian (D.B.); Westbrook, Dori (D.); Williams, Erik (E.C.); Williams, Gregory (G.M.); Williams, TRACE (S.); Wyatt, Kimberly (K.D.); Zroback, David (D.P.); Evans, Kayekethia (K.); Gibson, Renelda (R.); Lakomek, Scott (S.); Ornelas, Demetrio (D.); Ratliff, Kathy (K.); Stonewall, Wendy (M.); Svetich, Chris (C.); Anderson, Eric (H.); Berzeri, Marcello (M.); Chamberlain, Steve (J.); Edwards, Monty (M.R.); Farmer, Marty (M.F.); Feder, Andrew (A.); Gerrard, Ryan (R.P.); Iannotti, Jason (JRI.); Ickes, Walt (W.D.); Imperati, Daniel (D.); Issa, Ibrahim (I.M.); Jackson, Bradley (B.G.); Logli, Michael (M.A.); Morgan, Anthony (A.); Olsson, Paul (P.C.); Polaski, Mike (M.S.); Porter, Alan (A.T.); Rapiz, Noreen (N.G.); Siddiqui, Saif (S.S.); Sluis, Jim (JS.); Smith, Erin (E.); Sridhara, Raghu (R.); Trygar, Mike (M.); Vargo, Rebecca (R.L.); Widrick, Brad (B.A.); Young, Richard (R.C.); Yu, Eric (E.); Buelow, Steve (S.E.)

**Subject:** FW: 2011 Exp - BG [REDACTED] - Loss of power steering, lamp on, 18 mi, BD 12/16/10

**-The Customer Defines Quality-**

*Steve Buelow - Ford Motor Company*

FCSD Program Manager-  
Taurus/Taurus SHO/Lincoln MKS/Explorer  
Chicago Assembly PVT Office, COE  
773-646-7495 DialNet 686-7495  
Cell 313-805-8334 sbuelow@ford.com

"You miss 100 percent of the shots you never take." - Wayne Gretzky

---

**From:** SBUELOW@ford.com [mailto:SBUELOW@ford.com]  
**Sent:** Thursday, January 13, 2011 8:15 AM  
**To:** Buelow, Steve (S.E.)  
**Subject:** 2011 Exp - BG [REDACTED] - Loss of power steering, lamp on, 18 mi, BD 12/16/10

Attachments : 0

<b>Report# :</b>	BALEI002 NHL	<b>Received:</b>	01/12/2011
<b>CCRG/EPRC:</b>		<b>Date:</b>	
<b>Vehicle:</b>	2011,EXPLORER 4X4 (U502),4 DOOR ,MP,1FMHK8D83BG [REDACTED]	<b>Build Date:</b>	12/16/2010
<b>Odometer :</b>	18 M	<b>Engine:</b>	3.5L CYCLO
<b>Transmission:</b>	6F55	<b>Axle:</b>	
<b>Dealer:</b>	USA 09618 Brown Motors, Inc.	<b>Calibration:</b>	BUB1ST0A
<b>City:</b>	Petoskey	<b>A/C:</b>	YES
<b>Originator:</b>	JIM MILBRANDT	<b>Phone#:</b>	(231! ! ) 439- 9604
<b>Symptom:</b>	3 03 1 50 CHASS.,STRG/HANDLING ,FUNCTION,HIGH EFFORT	<b>Country :</b>	USA

**Status:**

**VFG:** V87 STEERING

**Additional Symptom:** LOSS OF POWER STEERING

**Fix:** Causal Component :

**Condition Code:**

**Hotliner:** DMU! ! RRA86

**Phone:** 313 248-8233

**Regn Cd:** G2 Detroit

**Engineering:**

**Phone:**

**TAR:**

**Dlr Contact:** JIM MILBRANDT

**Phone:** 231 439-3673

**Title Cde:** T

**DTCs:**

KOEO:U0253 U2011

KOEC:

KOER:

**Comments**

:

**REPAIR** 01/12/2011 02:45PM DOUGLAS MURRAY MSS - FCSD - TECH SVC HOTLINE  
WEB FORM DATA - CONCERN: CUSTOMER STATES WHEN ON TEST DRIVE THE  
POWER

STEERING QUIT AND A RED INDICATOR LIGHT CAME ONE. DIAGNOSTICS:  
PERFORMED IDS TESTS U0253:00-28 IPC U2011:49-08 PSCM IN MEMORY  
PARTS REPLACED:: NONE TECH QUESTION: ANY REPORTS FOR THIS  
CONCERN? WERE YOU ABLE TO VERIFY THE CONCERN? NO IS THERE AN  
APPROPRIATE PINPOINT TEST IN THE WSM FOR THIS CONCERN? WAS THE  
PINPOINT TEST FOLLOWED?

**RECOMM** 01/12/2011 02:45PM DOUGLAS MURRAY MSS - FCSD - TECH SVC HOTLINE  
JIM, IT IS RECOMMENDED TO GO TO THE WSM SECTION 211-00/DIAGNOSIS  
AND TESTING/DTC AND SYMPTOM CHARTS/INTERACTIVE DIAGNOSTICS AND GO  
TO

THE INTERACTIVE DIAGNOSTICS SECTION. FROM THERE, GO TO THE DTC LIST  
AND LOOK UP U2011. THIS IS A MOTOR CODE AND THERE ARE 2 DIFFERENT PPT  
TESTS DEPENDING ON WHICH BITMAP CODE YOU HAVE. THIS CODE INDICATES  
THAT THE PSCM HAS SEEN A MOTOR ISSUE AND WILL SHUT DOWN THE POWER  
ASSIST FUNCTION. PLEASE TRY TO DUPLICATE THE CONCERN AND IF CODE  
U2011 SETS, PERFORM THE APPROPRIATE CHART. THERE ARE NO COMMON  
TRENDS FOR THIS CONCERN. THANK YOU.



---

**From:** Jackson, Bradley (B.G.)  
**Sent:** Thursday, February 03, 2011 3:22 PM  
**To:** Napoli, Laura (L.); Mrozek, Robert (R.M.); Rossi, Roberto (R.A.); Buelow, Steve (S.E.)  
**Cc:** Docimo, Tony (A.F.)  
**Subject:** FW: 2011 Exp - BG [REDACTED] - Traction control fault, C1B00, U0121, U0126, 3 mi, BD 1/13/11

I confirmed with this dealer that the root cause of this CQIS report was the spread terminal issue on C139. This vehicle did go through evac/fill machine #3. The tech stated he had a second vehicle with the same codes on the lot today. He will call me back with the VIN so I can check that this unit went through #3 as well just to ensure this is a spread terminal eligible vehicle.

Brad

---

**From:** Buelow, Steve (S.E.)  
**Sent:** Thursday, February 03, 2011 10:18 AM  
**To:** Adamczyk, David (D.W.); Bollwahn, Bryce (B.A.); Centlivre, James (J.C.); Cheatham, Sandy (.); Cittadino, Lisa (L.C.); Collins, Kevin (K.E.); Gagnier, Kathryn (K.A.); Gilewski, David (D.); Gubing, William (Bill.); Hays, Andy (A.R.); Henker, Scott (S.); Lubin Henney, Michele (MLH.); Lysik, Kevin (K.M.); Mann, Mickey (N.S.); McClain, Shawn (S.M.); Pogorzelski, John (J.M.); Rodgers, Chuck (.); Saleh, Salim (S.A.); Sellers, Gary (G.T.); Shaukat, Nadeem (N.S.); Simkus, Walter (W.A.); Smith, Scott (S.A.); Sokolowski, Todd (T.M.); Thornsberry, Joel (J.A.); Willis, Mark (M.E.); Wong, Vicki (V.A.); Abrams, Donald (D.); Acuna, Aaron (A.A.); Allman, Jan (J.E.); Bell, Tim (.); Bergeron, Matthew (M.C.); Bisaga, Richard (R.); Boykin, George (G.); Boykins, Michael (M.); Bustamante, Chris (C.T.); Cantrell, David (D.D.); Ciotti, Steven (S.R.); Davis, Charlene (C.); Devine, Robert (R.M.); Docimo, Tony (A.F.); Elting, Tim (T.H.); Ferguson, Hugh (H.); Gagnier, Scott (S.W.); Greenwell, R (R.); Guyton, MzJenny (J.); Hernandez, Thomas (T.); Herron, Micheal (M.C.); Inglis, Steve (S.D.); Iqbal, Khurram (K.); Jones, Frederick (F.L.); Little, Janie (J.); Martin, Kenneth (K.A.); Matlock, Douglas (D.); McElroy, Darin (D.L.); McKernan, Patrick (P.J.); Miller, Melinda (M.S.); Moore, Chikynda (D.); Moses, Barry (B.A.); Moskwa, Larry (L.M.); Perkins, John (J.E.); Pesch, Vincent (V.J.); Rutovic, Nick (N.); Sarkisian, Mark (Z.); Smith, Eugenia (E.R.); Talbott, Larry (J.L.); Turner, Bridgette (B.); Turner, Patrice (P.T.); Vandergroef, Cornelius (C.); Washington, Kellie (K.S.); Wertman, David Brian (D.B.); Westbrook, Dori (D.); Williams, Erik (E.C.); Williams, Gregory (G.M.); Wyatt, Kimberly (K.D.); Zroback, David (D.P.); Armstrong, Miya (M.); Evans, Kayekethia (K.); Gibson, Renelda (R.); Lakomek, Scott (S.); Ornelas, Demetrio (D.); Ratliff, Kathy (K.); Stonewall, Wendy (M.); Svetich, Chris (C.); Torian, Jason (J.B.); Anderson, Eric (H.); Berzeri, Marcello (M.); Chamberlain, Steve (J.); Edwards, Monty (M.R.); Farmer, Marty (M.F.); Feder, Andrew (A.); Gerrard, Ryan (R.P.); Iannotti, Jason (JRI.); Ickes, Walt (W.D.); Imperati, Daniel (D.); Issa, Ibrahim (I.M.); Jackson, Bradley (B.G.); Logli, Michael (M.A.); Morgan, Anthony (A.); Olsson, Paul (P.C.); Polaski, Mike (M.S.); Porter, Alan (A.T.); Rapiz, Noreen (N.G.); Siddiqui, Saif (S.S.); Sluis, Jim (JS.); Smith, Erin (E.); Sridhara, Raghu (R.); Trygar, Mike (M.); Vargo, Rebecca (R.L.); Widrick, Brad (B.A.); Young, Richard (R.C.); Yu, Eric (E.); Buelow, Steve (S.E.)  
**Subject:** FW: 2011 Exp - BGA12929 - Traction control fault, C1B00, U0121, U0126, 3 mi, BD 1/13/11

**-The Customer Defines Quality-**

*Steve Buelow - Ford Motor Company*

FCSD Program Manager-  
Taurus/Taurus SHO/Lincoln MKS/Explorer  
Chicago Assembly PVT Office, COE  
773-646-7495 DialNet 686-7495  
Cell 313-805-8334 sbuelow@ford.com

"You miss 100 percent of the shots you never take." - Wayne Gretzky

---

**From:** SBUELOW@ford.com [mailto:SBUELOW@ford.com]

**Sent:** Thursday, February 03, 2011 8:40 AM

**To:** Buelow, Steve (S.E.)

**Subject:** 2011 Exp - BG [REDACTED] - Traction control fault, C1B00, U0121, U0126, 3 mi, BD 1/13/11

**Attachments :** 0

**Report# :** BBAA9020 NHL **Received:** 02/01/2011  
**CCRG/EPRC:** **Reviewed Status:** **Date:**  
**Vehicle:** 2011,EXPLORER 4X4 (U502),4 DOOR **Build Date:** 01/13/2011  
,MP,1FMHK8F8XBG [REDACTED]  
**Odometer :** 3 M **Engine:** 3.5L **Calibration:** BUB1ST0A  
CYCLO  
**Transmission:** 6F55 **Axle:** **A/C:** YES  
**Dealer:** CAN B2412 Desjardins Ford Ltee **Phone#:** (514)! ! 332-3850  
**City:** St Laurent **Province** Quebec **Country :** CAN  
**Originator:** MICHEL LALONDE  
**Symptom:** 3 01 A 04 CHASS.,SERVICE BRAKE ,INDICATOR,T/C LIGHT  
**Status:**  
**VFG:** V21 BRAKING  
**Additional Symptom:** TRAC LIGHT C1B00 U0121 U0126  
**Fix:** **Causal Component :**  
**Condition Code:**

**Hotliner:** T! ! FUMEROL **Phone:** 000 317-9383 **Regn Cd:** 02 02 FCSD REGION-CANADA

**Engineering:** **Phone:** **TAR:**

**Dlr Contact:** MICHEL LALONDE **Phone:** 514 332-3850 **Title Cde:** T

**DTCs:**

KOEO:C1B00 U0121 U0126 U0150 U0428

KOEC:

KOER:

**Comments**

:

REPAIR 02/01/2011 04:03PM TOM FUMEROLA MSS - FCSD - TECH SVC HOTLINE  
WEB FORM DATA - CONCERN: TRACTION LIGHT ON DIAGNOSTICS:

KOEO PARTS REPLACED:: NONE TECH QUESTION: EVERY CODE IS IN MEMORY ONLY...WHEN I CHECK THE PIDS I HAVE TWO IDENTICAL PIDS SW\_ANGLE....ONE SAYS 0 DEGREE AND THE OTHER ONE SAYS -223 DEGREE WHEN

THE STEERING IS CENTERED...DO YOU HAVE ANYTHING ON THAT ISSUE ??? THANKS WERE YOU ABLE TO VERIFY THE CONCERN? IS THERE AN APPROPRIATE PINPOINT TEST IN THE WSM FOR THIS CONCERN? WAS THE PINPOINT TEST FOLLOWED?

**RECOMM 02/01/2011 04:03PM TOM FUMEROLA MSS - FCSD - TECH SVC HOTLINE**

MICHEL, PERFORM A PIN DRAG TEST ON C139 PINS 24 AND 25. THERE HAVE BEEN SOME REPORTS OF SPREAD TERMINALS CAUSING AN INTERMITTENT NETWORK

FAULT WITH THE U-CODES YOU ARE SEEING. IT IS RECOMMENDED TO BYPASS C139 BY SPLICING AND SHRINK TUBING THE CIRCUITS. ISM 11-01-018 HS-CAN LOSS OF COMMUNICATION, C1B00

**REPAIR 02/01/2011 04:20PM JOSEPH REDDMANN MSS - FCSD - TECH SVC HOTLINE**

TECHNICIAN REPLY: WHEN YOU SAYS BYPASS C139 DO YOU MEAN ONLY CIRCUIT

24 AND 25 OR THE HOLE CONNECTOR ??

**RECOMM 02/01/2011 04:20PM JOSEPH REDDMANN MSS - FCSD - TECH SVC HOTLINE**

MICHEL, THERE IS NO NEED TO BY-PASS THE ENTIRE CONNECTOR. WE RECOMMEND THAT YOU BY-PASS TERMINALS 24 AND 25 ONLY. IF YOU WOULD LIKE ANY ADDITIONAL INFORMATION OR ASSISTANCE, PLEASE UPDATE THIS FORM

IN THE SPACE PROVIDED BELOW.

---

**From:** Perri, Ron (R.J.)  
**Sent:** Sunday, May 22, 2011 11:30 PM  
**To:** Mrozek, Robert (R.M.); Pascarella, Michael (M.); Napoli, Laura (L.); Annadi, Hari (H.)  
**Cc:** Menz, Kenneth (K.C.)  
**Subject:** FW: 2011 Exp - BG [REDACTED] - Loss of power steering, trac light on, 1921 mi, BD 2/18/11

Ron Perri  
Manager, Chassis - EPAS and Upper Steering, Systems & Core  
2B-F77, Product Development Center  
cell 313-805-0680  
rperri@ford.com

---

**From:** Cantrell, David (D.D.)  
**Sent:** Friday, May 20, 2011 6:41 PM  
**To:** Chamberlain, Steve (J.); Anderson, Eric (H.)  
**Cc:** Docimo, Tony (A.F.); Buelow, Steve (S.E.); Perri, Ron (R.J.); Annadi, Hari (H.)  
**Subject:** RE: 2011 Exp - BG [REDACTED] - Loss of power steering, trac light on, 1921 mi, BD 2/18/11

Eric,

This is a good find on the electrical ground wire--may be a systemic issue. Please make sure you are working with Hari and Ron on this, as they are investigating also. Thanks.

Regards,  
**D. David Cantrell, Jr.**  
Chicago Assembly PVT Manager  
Taurus / MKS / Explorer Programs  
Ford Motor Company  
*Ford-UofM Lead Recruiter*  
Ford Cell Ph: 313-805-8324  
Chicago Assembly Plant – PVT Office  
[dcantrel@ford.com](mailto:dcantrel@ford.com)

---

**From:** Chamberlain, Steve (J.)  
**Sent:** Friday, May 20, 2011 4:40 PM  
**To:** Anderson, Eric (H.)  
**Cc:** Docimo, Tony (A.F.); Buelow, Steve (S.E.); Cantrell, David (D.D.)  
**Subject:** RE: 2011 Exp - BG [REDACTED] - Loss of power steering, trac light on, 1921 mi, BD 2/18/11

Hi Eric,

I called the technician on BG [REDACTED] 6 to get a better understanding of what is going on. He was already gone for the day. I will call back Monday.

Thanks,

**Steve Chamberlain**

PVT Electrical/Wiring Harnesses

Chicago Assembly Plant

Ford Motor Company

**ONE FORD • ONE TEAM • ONE PLAN • ONE GOAL**

---

**From:** Anderson, Eric (H.)

**Sent:** Friday, May 20, 2011 4:26 PM

**To:** Cantrell, David (D.D.); Chamberlain, Steve (J.)

**Cc:** Docimo, Tony (A.F.); Buelow, Steve (S.E.)

**Subject:** RE: 2011 Exp - BG [REDACTED] - Loss of power steering, trac light on, 1921 mi, BD 2/18/11

Hi David:

I'm not sure if this is a new issue, but am working with Electrical to determine if root cause is here at the plant, the supplier or elsewhere. I was able to talk to the tech for the EPAS inop BG [REDACTED] CQIS. The tech followed the SSM and hotline's directions and eventually found ground circuit GD108 would not carry a load. This is the ground circuit that goes to the gear. The tech overlaid a new wire from the fender ground to the PSCM connector. This fixed the problem. The tech did not mention any damaged parts to the wire loom.

Steve,

Have you ever had any supplier problems with this loom? Have you had any problems with pinched wires elsewhere recently?

I did a process walk this afternoon, but did not see anything out of the ordinary.

Thanks,

Eric

---

**From:** Cantrell, David (D.D.)

**Sent:** Friday, May 20, 2011 3:51 PM

**To:** Anderson, Eric (H.)

**Cc:** Docimo, Tony (A.F.); Buelow, Steve (S.E.)

**Subject:** RE: 2011 Exp - BG [REDACTED] - Loss of power steering, trac light on, 1921 mi, BD 2/18/11

Eric,

We've had several claims recently for loss of power steering---is this open? What is root cause and corrective actions? Thanks.

Regards,

**D. David Cantrell, Jr.**

Chicago Assembly PVT Manager

Taurus / MKS / Explorer Programs

Ford Motor Company

*Ford-UofM Lead Recruiter*

Ford Cell Ph: 313-805-8324

Chicago Assembly Plant – PVT Office

[dcantrel@ford.com](mailto:dcantrel@ford.com)

---

**From:** Buelow, Steve (S.E.)

**Sent:** Friday, May 20, 2011 11:08 AM

**To:** Adamczyk, David (D.W.); Bollwahn, Bryce (B.A.); Centlivre, James (J.C.); Cheatham, Sandy (.); Cittadino, Lisa (L.C.); Collins, Kevin (K.E.); Gagnier, Kathryn (K.A.); Gilewski, David (D.); Gillanders, Eric (E.S.) (egilland@ford.com); Gray, Carl (C.L.); Gubing, William (Bill.); Hays, Andy (A.R.) (ahays@ford.com); Krochmalny, Kevin (K.); Mann, Mickey (N.S.); McClain, Shawn (S.M.); Pogorzelski, John (J.M.); Rodgers, Chuck (.); Saleh, Salim (S.A.); Sellers, Gary (G.T.); Shaukat, Nadeem (N.S.); Simkus, Walter (W.A.) (wsimkus1@ford.com); Sokolowski, Todd (T.M.); Thornsberry, Joel (J.A.); Willis, Mark (M.E.); Wong, Vicki (V.A.); Acuna, Aaron (A.A.); Allman, Jan (J.E.) (jallman@ford.com); Bell, Tim (.); Bergeron, Matthew (M.C.); Bisaga, Richard (R.); Boykin, George (G.); Boykins, Michael (M.); Bustamante, Chris (C.T.); Cantrell, David (D.D.); Carter, Tracy (T.); Ciotti, Steven (S.R.); Davis, Charlene (C.); Devine, Robert (R.M.); Docimo, Tony (A.F.) (adocimo@ford.com); Ferguson, Hugh (H.) (hferguso@ford.com); Gagnier, Scott (S.W.); Greenwell, R (R.); Guyton, MzJenny (J.); Hernandez, Thomas (T.); Herron, Micheal (M.C.); Inglis, Steve (S.D.) (singlis@ford.com); Iqbal, Khurram (K.); Jones, Frederick (F.L.); Little, Janie (J.); Martin, Kenneth (K.A.) (kmartin@ford.com); Matlock, Douglas (D.); McElroy, Darin (D.L.); McKernan, Patrick (P.J.); Miller, Melinda (M.S.); Moore, Chikynda (D.); Moskwa, Larry (L.M.) (lmoskwa@ford.com); Perkins, John (J.E.); Russell, David (D.A.); Rutovic, N (N.) (nrutovic@ford.com); Sarkisian, Mark (M.) (msarkisi@ford.com); Talbott, Larry (J.L.); Turner, Bridgette (B.); Turner, Patrice (P.T.); Vandergroef, Cornelius (C.); Washington, Kellie (K.S.); Wertman, David Brian (D.B.) (dwertman@ford.com); Westbrook, Dori (D.); Williams, Erik (E.C.); Williams, Gregory (G.M.); Wyatt, Kimberly (K.D.); Zroback, David (D.P.); Armstrong, Miya (M.); Buerger, Robert (R.G.); Evans, Kayekethia (K.); Gibson, Renelda (R.); Lakomek, Scott (S.); Napier, S (S.); Ornelas, Demetrio (D.); Ratliff, Kathy (K.); Scheldberg, Gary (G.D.); Stonewall, Wendy (M.); Svetich, Chris (C.); Torian, Jason (J.B.); Anderson, Eric (H.); Berzeri, Marcello (M.) (mberzeri@ford.com); Cassata, Joe (J.); Chamberlain, Steve (J.); Edwards, Monty (M.R.); Farmer, Marty (M.F.); Feder, Andrew (A.); Gerrard, Ryan (R.P.) (rgerrard@ford.com); Iannotti, Jason (JRI.) (jiannott@ford.com); Ickes, Walt (W.D.); Issa, Ibrahim (I.M.); Jackson, Bradley (B.G.); Logli, Michael (M.A.); Morgan, Anthony (A.); Olsson, Paul (P.C.) (polssso21@ford.com); Polaski, Mike (M.S.); Porter, Alan (A.T.); Rapiz, Noreen (N.G.); Santilli, Rennie (R.); Smith, Erin (E.); Sridhara, Raghu (R.); Trygar, Mike (M.) (mtrygar@ford.com); Vargo, Rebecca (R.L.); Widrick, Brad (B.A.) (bwidrick@ford.com); Young, Richard (R.C.) (ryoung27@ford.com); Yu, Eric (E.); Buelow, Steve (S.E.)

**Subject:** FW: 2011 Exp - BGA27891 - Loss of power steering, trac light on, 1921 mi, BD 2/18/11

**-The Customer Defines Quality-**

*Steve Buelow - Ford Motor Company*

FCSD Program Manager-

Taurus/Taurus SHO/Lincoln MKS/Explorer

Chicago Assembly PVT Office, COE

773-646-7495 DialNet 686-7495

Cell 773-726-0808 sbuelow@ford.com

"Quality means doing it right when no one is looking." - Henry Ford

**From:** SBUELOW@ford.com [mailto:SBUELOW@ford.com]  
**Sent:** Friday, May 20, 2011 9:53 AM  
**To:** Buelow, Steve (S.E.)  
**Subject:** 2011 Exp - BG [REDACTED] - Loss of power steering, trac light on, 1921 mi, BD 2/18/11

**Attachments :** 0

**Report# :** BESEA011 NHL  
**CCRG/EPRC:** **Reviewed Status:**  
**Vehicle:** 2011,EXPLORER 4X4 (U502),4 DOOR  
,MP,1FMHK8F89BG [REDACTED] **Build Date:** 02/18/2011  
**Odometer :** 1,921 M **Engine:** 3.5L  
CYCLO **Calibration:** BUB1SN0A  
**Transmission:** 6F50 **Axle:** **A/C:** YES  
**Dealer:** USA 03926 Park Ford Lincoln Mercury Inc. **Phone#:** (845) 628-8800  
**City:** Mahopac **State:** New York **Country :** USA  
**Originator:** JOSEPH MAURO  
**Symptom:** 3 03 1 50 CHASS.,STRG/HANDLING ,FUNCTION,HIGH EFFORT  
**Status:**  
**VFG:** V87 STEERING  
**Additional Symptom:** HIGH STEERING EFFORT  
**Fix:** **Causal Component :**  
**Condition Code:**

**Hotliner:** MABELA3 **Phone:** 000 248-9263 **Regn Cd:** N1 New York  
**Engineering:** **Phone:** **TAR:**  
**Dlr Contact:** JOSEPH MAURO **Phone:** 000 000-0000 **Title Cde:** T

**DTCs:**  
KOEO:  
KOEC:C1B00 U0422 U0131  
KOER:

**Comments**  
:  
REPAIR 05/19/2011 05:04PM MATT ABELA MSS - FCSD - TECH SVC HOTLINE  
WEB FORM DATA - CONCERN: TERRAIN MANAGEMENT FAULT LIGHT CAME ON,  
LOST  
POWER STEERING DIAGNOSTICS: U0131,C1B00,U0422. FOUND SSM 21737.

PARTS REPLACED:: NONE TECH QUESTION: FOUND SSM 21737. VEHICLE IS PAST BUILD DATE SPECIFIED IN SSM. SHOULD SSM BE FOLLOWED OR NOT. WERE YOU ABLE TO VERIFY THE CONCERN? YES IS THERE AN APPROPRIATE PINPOINT TEST IN THE WSM FOR THIS CONCERN? WAS THE PINPOINT TEST FOLLOWED?

**RECOMM 05/19/2011 05:04PM MATT ABELA MSS - FCSD - TECH SVC HOTLINE**

JOE, YOU SHOULD NOT SEE THE SAME CONDITION AS EXPERIENCED IN SSM 21737 ON THIS VEHICLE; HOWEVER THE DIAGNOSTIC IN THAT SSM IS VALID AND YOU CAN CERTAINLY USE IT AS A GUIDE FOR DIAGNOSING THIS VEHICLE. PLEASE NOTE WE HAVE SEEN A FEW INSTANCES OF SIMILAR CONCERNS CAUSED BY THE STABILITY CONTROL SENSOR CLUSTER IN THE RCM SENDING FALSE YAW RATE INFORMATION TO THE ABS MODULE. SINCE YAW RATE

AND STEERING WHEEL ANGLE SHOULD DIRECTLY CORRELATE WITH ONE ANOTHER,

WE SUSPECT THAT THE C1B00 DTC IS SETTING FALSELY DUE TO THE ABS MODULE

NOT SEEING CORRELATION BETWEEN THE TWO INPUTS. TO DETERMINE THE CAUSE OF THE CONCERN, PLACE THE VEHICLE ON A LEVELED ALIGNMENT RACK AND MONITOR THE YAW AND ROLL RATE AS WELL AS THE LATERAL AND LONGITUDINAL ACCELERATION PID'S IN THE ABS MODULE. ALL PID'S SHOULD READ AT OR NEAR ZERO WITH MINIMAL FLUCTUATION. COMPARE ANY SUSPECT PID

READING TO A LIKE VEHICLE. IF A FAULTY PID READING IS PRESENT ON THE CUSTOMER'S VEHICLE, REPLACE THE RCM, AND RE EVALUATE THE CONCERN.



---

**From:** Perri, Ron (R.J.)  
**Sent:** Thursday, May 19, 2011 3:04 PM  
**To:** Mrozek, Robert (R.M.); Napoli, Laura (L.); Pascarella, Michael (M.)  
**Cc:** Menz, Kenneth (K.C.)  
**Subject:** FW: 2011 Exp - BG [REDACTED] - Loss of steering assist, 256 mi, BD 5/3/11

Please get into. Get part back, etc.  
Thanks.

Ron Perri  
Manager, Chassis - EPAS and Upper Steering, Systems & Core  
2B-F77, Product Development Center  
cell 313-805-0680  
rperri@ford.com

---

**From:** Menz, Kenneth (K.C.)  
**Sent:** Thursday, May 19, 2011 1:14 PM  
**To:** Perri, Ron (R.J.)  
**Subject:** FW: 2011 Exp - BG [REDACTED] - Loss of steering assist, 256 mi, BD 5/3/11

Ron - Bill Gubing just sent this over; 2 warranty claims in 1 day for EPAS loss of assist. How shall I respond? I am not aware of any warranty spike for EPAS on U502 nor aware of any recent quality issues.

**Kenneth C. Menz**

Chassis Integration Mgr for  
Med/Large Family & CUV  
313-805-3156  
PDC 2B-G80

---

**From:** Gubing, William (Bill.)  
**Sent:** Thursday, May 19, 2011 11:59 AM  
**To:** Menz, Kenneth (K.C.)  
**Subject:** FW: 2011 Exp - BG [REDACTED] - Loss of steering assist, 256 mi, BD 5/3/11

2 of these in the same day hit warranty. And ideas?

Thanks

Bill

---

**From:** Buelow, Steve (S.E.)

**Sent:** Thursday, May 19, 2011 11:42 AM

**To:** Adamczyk, David (D.W.); Bollwahn, Bryce (B.A.); Centlivre, James (J.C.); Cheatham, Sandy (.); Cittadino, Lisa (L.C.); Collins, Kevin (K.E.); Gagnier, Kathryn (K.A.); Gilewski, David (D.); Gillanders, Eric (E.S.); Gray, Carl (C.L.); Gubing, William (Bill.); Hays, Andy (A.R.); Krochmalny, Kevin (K.); Mann, Mickey (N.S.); McClain, Shawn (S.M.); Pogorzelski, John (J.M.); Rodgers, Chuck (.); Saleh, Salim (S.A.); Sellers, Gary (G.T.); Shaukat, Nadeem (N.S.); Simkus, Walter (W.A.); Sokolowski, Todd (T.M.); Thornsberry, Joel (J.A.); Willis, Mark (M.E.); Wong, Vicki (V.A.); Acuna, Aaron (A.A.); Allman, Jan (J.E.); Bell, Tim (.); Bergeron, Matthew (M.C.); Bisaga, Richard (R.); Boykin, George (G.); Boykins, Michael (M.); Bustamante, Chris (C.T.); Cantrell, David (D.D.); Carter, Tracy (T.); Ciotti, Steven (S.R.); Davis, Charlene (C.); Devine, Robert (R.M.); Docimo, Tony (A.F.); Ferguson, Hugh (H.); Gagnier, Scott (S.W.); Greenwell, R (R.); Guyton, MzJenny (J.); Hernandez, Thomas (T.); Herron, Micheal (M.C.); Inglis, Steve (S.D.); Iqbal, Khurram (K.); Jones, Frederick (F.L.); Little, Janie (J.); Martin, Kenneth (K.A.); Matlock, Douglas (D.); McElroy, Darin (D.L.); McKernan, Patrick (P.J.); Miller, Melinda (M.S.); Moore, Chikynda (D.); Moskwa, Larry (L.M.); Perkins, John (J.E.); Russell, David (D.A.); Rutovic, Nick (N.); Sarkisian, Mark (Z.); Talbott, Larry (J.L.); Turner, Bridgette (B.); Turner, Patrice (P.T.); Vandergroef, Cornelius (C.); Washington, Kellie (K.S.); Wertman, David Brian (D.B.); Westbrook, Dori (D.); Williams, Erik (E.C.); Williams, Gregory (G.M.); Wyatt, Kimberly (K.D.); Zroback, David (D.P.); Armstrong, Miya (M.); Buerger, Robert (R.G.); Evans, Kayekethia (K.); Gibson, Renelda (R.); Lakomek, Scott (S.); Napier, S (S.); Ornelas, Demetrio (D.); Ratliff, Kathy (K.); Scheldberg, Gary (G.D.); Stonewall, Wendy (M.); Svetich, Chris (C.); Torian, Jason (J.B.); Anderson, Eric (H.); Berzeri, Marcello (M.); Cassata, Joe (J.); Chamberlain, Steve (J.); Edwards, Monty (M.R.); Farmer, Marty (M.F.); Feder, Andrew (A.); Gerrard, Ryan (R.P.); Iannotti, Jason (J.R.I.); Ickes, Walt (W.D.); Issa, Ibrahim (I.M.); Jackson, Bradley (B.G.); Logli, Michael (M.A.); Morgan, Anthony (A.); Olsson, Paul (P.C.); Polaski, Mike (M.S.); Porter, Alan (A.T.); Rapiz, Noreen (N.G.); Santilli, Rennie (R.); Smith, Erin (E.); Sridhara, Raghu (R.); Trygar, Mike (M.); Vargo, Rebecca (R.L.); Widrick, Brad (B.A.); Young, Richard (R.C.); Yu, Eric (E.); Buelow, Steve (S.E.)

**Subject:** FW: 2011 Exp - BGA61636 - Loss of steering assist, 256 mi, BD 5/3/11

**-The Customer Defines Quality-**

*Steve Buelow - Ford Motor Company*

FCSD Program Manager-

Taurus/Taurus SHO/Lincoln MKS/Explorer

Chicago Assembly PVT Office, COE

773-646-7495 DialNet 686-7495

Cell 773-726-0808 sbuelow@ford.com

"Quality means doing it right when no one is looking." - Henry Ford

---

**From:** SBUELOW@ford.com [mailto:SBUELOW@ford.com]

**Sent:** Thursday, May 19, 2011 9:26 AM

**To:** Buelow, Steve (S.E.)

**Subject:** 2011 Exp - BG[REDACTED] - Loss of steering assist, 256 mi, BD 5/3/11

**Attachments :** 0

**Report# :** BERDT010 NHL

**Received:** 05/18/2011

**CCRG/EPRC:** **Reviewed Status:** **Date:**  
**Vehicle:** 2011,EXPLORER 4X4 (U502),4 DOOR **Build Date:** 05/03/2011  
,MP,1FMHK8F89BG [REDACTED]  
**Odometer :** 256 M **Engine:** 3.5L **Calibration:**  
CYCLO  
**Transmission:** 6F55 **Axle:** **A/C:** YES  
**Dealer:** USA 00838 Lynch Ford-Mt. Vernon, Inc. **Phone#:** (319) 895-  
8500  
**City:** Mount Vernon **State:** Iowa **Country :** USA  
**Originator:** CHAD HONKOMP  
**Symptom:** 6 98 2 98 DRVABL,INDICATOR,CHECK ENGINE,MIL ONLY  
**Status:**  
**VFG:** V29 CHECK ENGINE LIGHT  
**Additional Symptom:** LOSS OF ASSIST U0131  
**Fix:** **Causal Component :**  
**Condition Code:**

**Hotliner:** FSHEPHE2 **Phone:** 000 317-6305 **Regn Cd:** G1 Chicago  
**Engineering:** **Phone:** **TAR:**  
**Dlr Contact:** CHAD HONKOMP **Phone:** 319 895-8500 **Title Cde:** T

**DTCs:**  
KOE0:U0131  
KOE0:  
KOE0:

**Comments**  
:

**REPAIR** 05/18/2011 06:43PM FRED SHEPHERD MSS - FCSD - TECH SVC HOTLINE  
WEB FORM DATA - CONCERN: POWER STERRING IS ACTING ERRATTIC DURING  
PARKING GARAGE DRIVING. DIAGNOSTICS: ROADTEST FOR CONERNS , NOT  
PRESENT , CHECK DTCS CONT U0131 PSCM KOEO- PASS PARTS REPLACED::  
NONE TECH QUESTION: WSM IS INCOMPLETE. CHEKCING FOR REPORTS OR  
KNOWN CONCERNS. ANY FURTHER DIAG?

**RECOMM** 05/18/2011 06:43PM FRED SHEPHERD MSS - FCSD - TECH SVC HOTLINE  
HI CHAD. WE ARE NOT AWARE OF ANY COMMON TRENDS OR CONCERNS FOR  
THIS  
ISSUE OTHER THEN SSM 21737. PLEASE DUPLICATE THE CONCERN PRIOR TO ANY  
REPAIR AND WHEN PRESENT, REFER TO THE SSM AND CHECK FOR CONCERNS AT  
C139 AND REPAIR AS NEEDED. IF OK, LOAD TEST ALL PSCM POWERS AND  
GROUNDS AND REPAIR IF NECESSARY AND RETEST. IF YOU NEED ADDITIONAL  
ASSISTANCE, PLEASE LET US KNOW. THANKS. SSM 21737 CODES C1B00,

U0131, U0100, U0001, U0121, AND/OR U0151- CLEAR CODES AND WIGGLE TEST CONNECTER C139. IFCODES RETURN, BYPASS C139 FOR CIRCUITS VDB04 AND VDB05 USING THE SOLDER AND SHRINK TUBING METHOD FOUND IN SECTION 5 OF THE WIRING DIAGRAMS.

---

**From:** Napoli, Laura (L.)  
**Sent:** Wednesday, June 01, 2011 11:18 AM  
**To:** 'apienta@yahoo.com'  
**Subject:** FW: 2011 Exp - BG [REDACTED] - Loss of steering assist, 256 mi, BD 5/3/11

**Importance:** High

---

**From:** Anderson, Eric (H.)  
**Sent:** Friday, May 20, 2011 2:15 PM  
**To:** Logli, Michael (M.A.); Issa, Ibrahim (I.M.); Chamberlain, Steve (J.); Jackson, Marcell (M.)  
**Cc:** Docimo, Tony (A.F.); Jackson, Bradley (B.G.); Estes, Eric (E.E.); Napoli, Laura (L.)  
**Subject:** FW: 2011 Exp - BG [REDACTED] - Loss of steering assist, 256 mi, BD 5/3/11  
**Importance:** High

Hi Electrical Team:

I called this dealership about a recently built U502 that lost assist. The tech explained that he eventually found circuit GD108 would not carry a load. He then overlaid GD108 from the fender attachment point to the PSCM connector with a new wire. EPAS returned and has been working properly.

Do you think we could be pinching this wire somewhere in our process? Have you ever had supplier quality problems with this wire loom?

Thanks,

Eric

---

**From:** Buelow, Steve (S.E.)  
**Sent:** Thursday, May 19, 2011 10:42 AM  
**To:** Adamczyk, David (D.W.); Bollwahn, Bryce (B.A.); Centlivre, James (J.C.); Cheatham, Sandy (.); Cittadino, Lisa (L.C.); Collins, Kevin (K.E.); Gagnier, Kathryn (K.A.); Gilewski, David (D.); Gillanders, Eric (E.S.); Gray, Carl (C.L.); Gubing, William (Bill.); Hays, Andy (A.R.); Krochmalny, Kevin (K.); Mann, Mickey (N.S.); McClain, Shawn (S.M.); Pogorzelski, John (J.M.); Rodgers, Chuck (.); Saleh, Salim (S.A.); Sellers, Gary (G.T.); Shaukat, Nadeem (N.S.); Simkus, Walter (W.A.); Sokolowski, Todd (T.M.); Thornsberry, Joel (J.A.); Willis, Mark (M.E.); Wong, Vicki (V.A.); Acuna, Aaron (A.A.); Allman, Jan (J.E.); Bell, Tim (.); Bergeron, Matthew (M.C.); Bisaga, Richard (R.); Boykin, George (G.); Boykins, Michael (M.); Bustamante, Chris (C.T.); Cantrell, David (D.D.); Carter, Tracy (T.); Ciotti, Steven (S.R.); Davis, Charlene (C.); Devine, Robert (R.M.); Docimo, Tony (A.F.); Ferguson, Hugh (H.); Gagnier, Scott (S.W.); Greenwell, R (R.); Guyton, MzJenny (J.); Hernandez, Thomas (T.); Herron, Micheal (M.C.); Inglis, Steve (S.D.); Iqbal, Khurram (K.); Jones, Frederick (F.L.); Little, Janie (J.); Martin, Kenneth (K.A.); Matlock, Douglas (D.); McElroy, Darin (D.L.); McKernan, Patrick (P.J.); Miller, Melinda (M.S.); Moore, Chikynda (D.); Moskwa, Larry (L.M.); Perkins, John (J.E.); Russell, David (D.A.); Rutovic, Nick (N.); Sarkisian, Mark (Z.); Talbott, Larry (J.L.); Turner, Bridgette (B.); Turner, Patrice (P.T.); Vandergroef, Cornelius (C.); Washington, Kellie (K.S.); Wertman, David Brian (D.B.); Westbrook, Dori (D.); Williams, Erik (E.C.); Williams, Gregory (G.M.); Wyatt, Kimberly (K.D.); Zroback, David (D.P.); Armstrong, Miya (M.); Buerger, Robert (R.G.); Evans, Kayekethia (K.); Gibson, Renelda (R.); Lakomek, Scott (S.); Napier, S (S.); Ornelas, Demetrio (D.); Ratliff, Kathy (K.); Scheldberg, Gary (G.D.); Stonewall, Wendy (M.); Svetich, Chris (C.); Torian, Jason (J.B.); Anderson, Eric (H.); Berzeri, Marcello (M.); Cassata, Joe (J.); Chamberlain, Steve (J.); Edwards, Monty (M.R.); Farmer, Marty (M.F.); Feder, Andrew (A.); Gerrard, Ryan (R.P.); Iannotti, Jason (J.R.I.); Ickes, Walt (W.D.); Issa, Ibrahim (I.M.); Jackson, Bradley (B.G.); Logli, Michael (M.A.); Morgan, Anthony (A.); Olsson, Paul (P.C.); Polaski, Mike (M.S.); Porter, Alan (A.T.); Rapiz, Noreen (N.G.); Santilli, Rennie (R.); Smith, Erin (E.); Sridhara, Raghu (R.); Trygar, Mike (M.); Vargo, Rebecca (R.L.); Widrick, Brad (B.A.);

Young, Richard (R.C.); Yu, Eric (E.); Buelow, Steve (S.E.)

**Subject:** FW: 2011 Exp - BG [REDACTED] - Loss of steering assist, 256 mi, BD 5/3/11

**-The Customer Defines Quality-**

*Steve Buelow - Ford Motor Company*

FCSD Program Manager-  
Taurus/Taurus SHO/Lincoln MKS/Explorer  
Chicago Assembly PVT Office, COE  
773-646-7495 DialNet 686-7495  
Cell 773-726-0808 sbuelow@ford.com

"Quality means doing it right when no one is looking." - Henry Ford

---

**From:** SBUELOW@ford.com [mailto:SBUELOW@ford.com]  
**Sent:** Thursday, May 19, 2011 9:26 AM  
**To:** Buelow, Steve (S.E.)  
**Subject:** 2011 Exp - BG [REDACTED] - Loss of steering assist, 256 mi, BD 5/3/11

**Attachments :** 0

<b>Report# :</b>	BERDT010 NHL	<b>Received:</b>	05/18/2011
<b>CCRG/EPRC:</b>		<b>Date:</b>	
<b>Vehicle:</b>	2011,EXPLORER 4X4 (U502),4 DOOR ,MP,1FMHK8F89BG [REDACTED]	<b>Build Date:</b>	05/03/2011
<b>Odometer :</b>	256 M	<b>Engine:</b>	3.5L CYCLO
<b>Transmission:</b>	6F55	<b>Axle:</b>	
<b>Dealer:</b>	USA 00838 Lynch Ford-Mt. Vernon, Inc.	<b>A/C:</b>	YES
<b>City:</b>	Mount Vernon	<b>Phone#:</b>	(319) 895- 8500
<b>Originator:</b>	CHAD HONKOMP	<b>Country :</b>	USA
<b>Symptom:</b>	6 98 2 98 DRVABL,INDICATOR,CHECK ENGINE,MIL ONLY		
<b>Status:</b>			
<b>VFG:</b>	V29 CHECK ENGINE LIGHT		
<b>Additional Symptom:</b>	LOSS OF ASSIST U0131		
<b>Fix:</b>	<b>Causal Component :</b>		
<b>Condition Code:</b>			

**Hotliner:** FSHEPHE2

**Phone:** 000 317-6305

**Regn Cd:** G1 Chicago

**Engineering:**

**Phone:**

**TAR:**

**Dlr Contact:** CHAD HONKOMP

**Phone:** 319 895-8500

**Title Cde:** T

**DTCs:**

KOEO:U0131

KOEC:

KOER:

**Comments**

:

**REPAIR** 05/18/2011 06:43PM FRED SHEPHERD MSS - FCSD - TECH SVC HOTLINE  
WEB FORM DATA - CONCERN: POWER STERRING IS ACTING ERRATTIC DURING  
PARKING GARAGE DRIVING. DIAGNOSTICS: ROADTEST FOR CONERNS , NOT  
PRESENT , CHECK DTCS CONT U0131 PSCM KOEO- PASS PARTS REPLACED::  
NONE TECH QUESTION: WSM IS INCOMPLETE. CHEKCING FOR REPORTS OR  
KNOWN CONCERNS. ANY FURTHER DIAG?

**RECOMM** 05/18/2011 06:43PM FRED SHEPHERD MSS - FCSD - TECH SVC HOTLINE  
HI CHAD. WE ARE NOT AWARE OF ANY COMMON TRENDS OR CONCERNS FOR  
THIS  
ISSUE OTHER THEN SSM 21737. PLEASE DUPLICATE THE CONCERN PRIOR TO ANY  
REPAIR AND WHEN PRESENT, REFER TO THE SSM AND CHECK FOR CONCERNS AT  
C139 AND REPAIR AS NEEDED. IF OK, LOAD TEST ALL PSCM POWERS AND  
GROUNDS AND REPAIR IF NECESSARY AND RETEST. IF YOU NEED ADDITIONAL  
ASSISTANCE, PLEASE LET US KNOW. THANKS. SSM 21737 CODES C1B00,  
U0131, U0100, U0001, U0121, AND/OR U0151- CLEAR CODES AND WIGGLE TEST  
CONNECTER C139. IFCODES RETURN, BYPASS C139 FOR CIRCUITS VDB04 AND  
VDB05 USING THE SOLDER AND SHRINK TUBING METHOD FOUND IN SECTION 5  
OF  
THE WIRING DIAGRAMS.

---

**From:** Napoli, Laura (L.)  
**Sent:** Wednesday, October 12, 2011 10:27 AM  
**To:** Flanagan, Thomas (T.P.)  
**Cc:** Surella, Matthew (M.M.)  
**Subject:** FW: 2011 EXP/[REDACTED] CHASSIS - Report Summary(s) from a GCQIS Query Disposition

The one you showed me this morning is Israel.

---

**From:** Jackson, Bradley (B.G.)  
**Sent:** Wednesday, October 12, 2011 10:06 AM  
**To:** Napoli, Laura (L.); Estes, Eric (E.E.)  
**Cc:** Annadi, Hari (H.); Mrozek, Robert (R.M.)  
**Subject:** FW: 2011 EXP/[REDACTED] CHASSIS - Report Summary(s) from a GCQIS Query Disposition

Look how latent a B9A can be. 10K miles? And we are now shipping B9A's internationally. The 2nd report is in Israel.

Brad

<b>Report# :</b>	BJKAN009 NHL	<b>Received:</b>	10/11/2011
<b>CCRG/EPRC:</b>		<b>Reviewed Status:</b>	<b>Date:</b>
<b>Vehicle:</b>	2011,EXPLORER 4X4 (U502) ,XLT ,4 DOOR ,MPV ,1FMHK8D86BG [REDACTED]	<b>Build Date:</b>	03/20/2011
<b>Odometer :</b>	10,258 M	<b>Engine:</b>	3.5L CYCLO
<b>Transmission:</b>	6F50	<b>Axle:</b>	<b>Calibration:</b> BUB1SN0A
<b>Dealer:</b>	USA 03605 Sunshine Ford-Lincoln, Inc.	<b>Phone#:</b>	(845) 561-3900
<b>City:</b>	Newburgh	<b>State:</b>	New York
<b>Country :</b>			USA
<b>Originator:</b>	BRIAN WARREN		
<b>Symptom:</b>	6 62 4 28 SP/ST/RD,STEER/STER WHL,PERFORMANCE,EXCESS EFFORT		
<b>Status:</b>			
<b>VFG:</b>	V87 STEERING		
<b>Additional Symptom:</b>	STEERING FAULT		
<b>Fix:</b>	<b>Causal Component :</b>	--	
<b>Condition Code:</b>			

**Hotliner:** JREDDMAN                      **Phone:** 000 248-9292                      **Regn Cd:** N1 New York

**Engineering:**                                      **Phone:**                                      **TAR:**

**Dlr Contact:** BRIAN WARREN                      **Phone:** 000 000-0000                      **Title Cde:** T



**DTCs:**

KOEO:C1B00:86 C200D:49

KOEC:

KOER:

**Comments**

:

REPAIR 10/11/2011 01:30PM JOSEPH REDDMANN MSS - FCSD - TECH SVC HOTLINE  
WEB FORM DATA - CONCERN:C/S STEERING LOCKED UP, ALMOST CAUSED  
COLLISION. DIAGNOSTICS: CK. DTCS,ROAD TEST, PERFORMED PINPOINT  
TESTS PARTS REPLACED:NONE TECH QUESTION:CONCERN WAS NOT VERFIED,  
AFTER PERFORMING PINPOINT TEST B3 NO DTCS WERE RECORDED. DUE TO THE  
NATURE OF THIS CONCERN PLEASE ADVISE.

**RECOMM 10/11/2011 01:30PM JOSEPH REDDMANN MSS - FCSD - TECH SVC HOTLINE**  
BRIAN, BASED ON THE DESCRIPTION OF THE CONCERN, THE DTCS THAT ARE  
PRESENT AND PRIOR HOTLINE REPORTS, WE RECOMMEND THAT YOU REPLACE  
THE  
STEERING RACK AND RE-EVALUATE THE CONCERN. IF YOU NEED ANY  
ADDITIONAL ASSISTANCE, PLEASE UPDATE THIS FORM IN THE SPACE  
PROVIDED. ISM 11-08-019 LOSS OF POWER STEERING ASSIST WITH C200D IN  
PSCM

**Attachments : 0**

<b>Report# :</b>	BJKCJ008 NHL	<b>Received:</b>	10/11/2011
<b>CCRG/EPRC:</b>		<b>Reviewed Status:</b>	<b>Date:</b>
<b>Vehicle:</b>	2011,EXPLORER 4X4 (U502) ,LIMITED,4 DOOR ,MPV ,1FMHK8F81BG [REDACTED]	<b>Build Date:</b>	04/13/2011
<b>Odometer :</b>	2,316 M	<b>Engine:</b>	3.5L CYCLO
<b>Transmission:</b>	6F50	<b>Axle:</b>	<b>Calibration:</b>
<b>Dealer:</b>	ISR W0B34 Delek Motors Ltd.	<b>A/C:</b>	YES
<b>City:</b>	Nir Zvi	<b>Phone#:</b>	
<b>Originator:</b>	ASAF ARVIV	<b>Country :</b>	ISR
<b>Symptom:</b>	6 62 4 39 SP/ST/RD,STEER/STER WHL,PERFORMANCE,INTERMITTENT		
<b>Status:</b>			
<b>VFG:</b>	V87 STEERING		
<b>Additional Symptom:</b>	LACKS ASSIST ON U-TURN		
<b>Fix:</b>	<b>Causal Component :</b>	--	

**Condition Code:**

**Hotliner:** GBARTOS

**Phone:** 313 317-6301

**Regn Cd:** 9B FCSD REGION 9B

**Engineering:**

**Phone:**

**TAR:**

**Dlr Contact:** ASAF ARVIV

**Phone:** 000 000-0000

**Title Cde:** T

**DTCs:**

KOEO:

KOEC:C200D

KOER:

**Comments**

:

**REPAIR** 10/11/2011 10:37AM GREG BARTOS MSS - FCSD - TECH SVC HOTLINE  
 WEB FORM DATA - CONCERN:SUDDENLY DURING U-TURN DRIVING, THE STEERING BECAME VERY HARD, AND STEERING MULFUNCTION LIGHT SET ON ON IC. CYCLING  
 THE IGNITION ELIMINATE THE CONCERN. THERE WAS ANOTHER EVENT LATER ON.  
 THE ENGINE ALMOST STALLED AS THE EVENT OCCUR. DIAGNOSTICS: WE PREFORMED DIAGNOSTICS ACCORDING TO WSM AND IDS DTCS. C200D TROUBLESHOOTING COMPLETED WITH THE CONCLUSION THAT THE VEHICLE SHOULD BE DELIVERED TO CUSTOMER IF NO WE HAVE NOT SCSEED TO DUPLICATE THE CONCERN. U3003 INDICATE HIGH VOLTAGE CONCERN AND TROUBLE SHOOTING HAS NOT IDENTIFIED ANY CONCERN. LONG TEST DRIVE HAS NOT DUPLICATE THE CONCERN PARTS REPLACED:NONE YET TECH QUESTION:WE AFFRAID TO DELIVER THE VEHICLE BACK TO CUSTOMER. IT IS A BRAND NEW VEHICLE AND ANY FAULTS CAN AFFEC US BADLY. PLEASE REVIEW THE INFORMATION AND ADVICE IF YOU CAN UNDERSTAND THE ROOT CAUSE OF THE CONCERN. MANY THANKS!

**RECOMM** 10/11/2011 10:37AM GREG BARTOS MSS - FCSD - TECH SVC HOTLINE  
 ASAF, SINCE DTC C200D HAS BEEN SET, IT WILL BE NECESSARY TO REPLACE THE EPAS GEAR. ENGINEERING HAS CONFIRMED THAT DTC C200D HAS BEEN SET DUE TO AN INTERNAL FAULT WITH THE EPAS GEAR WHICH REQUIRES GEAR REPLACEMENT. REPLACE THE EPAS GEAR AND RE-EVALUATE THE CONCERN. -----  
 ----- ISM 11-08-019 LOSS OF POWER STEERING ASSIST WITH C200D IN PSCM

Attachments : 0

**Report# :** BJKAJ015 NHL **Received:** 10/11/2011  
**CCRG/EPRC:** **Reviewed Status:** **Date:**  
**Vehicle:** 2012,EXPLORER 4X2 (U502) ,LIMITED,4 DOOR ,MPV **Build Date:** 08/18/2011  
,1FMHK7F80CG [REDACTED]  
**Odometer :** 1,192 M **Engine:** 3.5L **Calibration:** CUB1SN0A  
CYCLO  
**Transmission:** 6F50 **Axle:** **A/C:** YES  
**Dealer:** USA 08223 Link Ford & RV-Minong LLC **Phone#:** (715) 466-  
2222  
**City:** Minong **State:** Wisconsin **Country :** USA  
**Originator:** ANDREW DURST  
**Symptom:** 6 62 4 28 SP/ST/RD,STEER/STER WHL,PERFORMANCE,EXCESS EFFORT  
**Status:**  
**VFG:** V87 STEERING  
**Additional Symptom:** U0131 IN IC AND ABS  
**Fix:** **Causal Component :** --  
**Condition Code:**

**Hotliner:** MDREWYOU **Phone:** 000 317-9369 **Regn Cd:** G5 Twin Cities  
**Engineering:** **Phone:** **TAR:**  
**Dlr Contact:** ANDREW DURST **Phone:** 000 000-0000 **Title Cde:** T

**DTCs:**

KOEO:U0131 C1B00:29 U0415

KOEC:

KOER:

**Comments**

:

REPAIR 10/11/2011 02:15PM MICHAEL DREWYOU MSS - FCSD - TECH SVC HOTLINE  
WEB FORM DATA - CONCERN:CUSTOMER STATES THE POWER STEERING IS  
INTERMITTENTLY INOPERATIVE, WARNING LIGHTS COME ON WHEN  
INOPERATIVE. DIAGNOSTICS: PERFORMED SELF TESTS FOR PSCM, SCCM, ABS,  
AND IPC. AT THE TIME OF INITIAL TESTING, EPAS SYSTEM WAS OPERATING  
NORMALLY. AFTER A 15 MILE TEST DRIVE, PULLING ONTO HIGHWAY,  
ADVANCETRAC WARNING AND ABS LIGHTS CAME ON AND POWER ASSIST QUIT  
WORKING. UPON RETURN TO THE SHOP, SCAN SHOWED NO RESPONSE FROM  
PSCM ON  
THE NETWORK, PSCM FAILED NETWORK TEST, PPT ADVISED TO REPLACE PSCM.

HOWEVER, AFTER SHUTTING VEHICLE OFF AND SITTING FOR 15 MINUTES, WARNING LIGHTS ARE OFF AND EPAS IS WORKING NORMALLY AGAIN.  
INSPECTED

ALL CONNECTORS, ALL APPEAR TO BE OKAY (ON STEERING GEAR, ABS MODULE, DLC). PARTS REPLACED:NONE AT THIS TIME TECH QUESTION:DIAGNOSTICS ADVISE TO REPLACE THE PSCM (STEERING GEAR ASSEMBLY). LOOKING FOR ANY INFORMATION ABOUT THIS CONCERN. WHEN PSCM FAILED THE NETWORK TEST, ALL

POWERS, GROUNDS, AND NETWORK CONNECTIONS (TO DLC) TESTED NORMAL, LOAD

TESTS OKAY. ANY HELP APPRECIATED.

**RECOMM 10/11/2011 02:15PM MICHAEL DREWYOU MSS - FCSD - TECH SVC HOTLINE**

ANDREW, RECOMMEND CHECKING POWERS AND GROUND TO THE PSCM WHEN THE

CONCERN IS PRESENT. ALSO RECOMMEND VERIFYING PIN FITS USING A FLEX PROBE AT THE PCSM AND VERIFY THE COMMUNICATION CIRCUITS TO THE PCSM. INSPECT THE HARNESS FOR ANY CHEFFING.

---

**From:** Jackson, Bradley (B.G.)  
**Sent:** Thursday, September 01, 2011 8:16 AM  
**To:** Napoli, Laura (L.); Estes, Eric (E.E.); Buelow, Steve (S.E.)  
**Cc:** Mrozek, Robert (R.M.); Fumerola, Tom (T.)  
**Subject:** FW: 2011 EXP/[REDACTED] CHASSIS - Report Summary(s) from a GCQIS Query Disposition

Laura / Eric, a C200D gear below

Steve, our new message to the Hotliners should have directed Jonathan below to advise replacing the gear. Is our ISM active?

Brad

---

<b>Report# :</b>	BH5CN008 NHL	<b>Received:</b>	08/31/2011
<b>CCRG/EPRC:</b>		<b>Date:</b>	
<b>Vehicle:</b>	2011,EXPLORER 4X2 (U502) ,XLT ,4 DOOR ,MPV ,1FMHK7D80BG [REDACTED]	<b>Build Date:</b>	05/05/2011
<b>Odometer :</b>	2,454 M	<b>Engine:</b>	3.5L CYCLO
<b>Transmission:</b>	6F55	<b>Axle:</b>	
<b>Dealer:</b>	USA 07761 Orchid Isle Auto Center	<b>Calibration:</b>	BUB1ST0A
<b>City:</b>	Hilo	<b>A/C:</b>	YES
<b>State:</b>	Hawaii	<b>Phone#:</b>	(808) 935- 1191
<b>Country :</b>	USA		
<b>Originator:</b>	SCOTT NAKASONE		
<b>Symptom:</b>	6 62 4 39 SP/ST/RD,STEER/STER WHL,PERFORMANCE,INTERMITTENT		
<b>Status:</b>			
<b>VFG:</b>	V87 STEERING		
<b>Additional Symptom:</b>	STEERING HARD TRACTION LIGHT		
<b>Fix:</b>	<b>Causal Component :</b>	--	
<b>Condition Code:</b>			
<b>Hotliner:</b>	JSAVOY1	<b>Phone:</b>	313 317-9352
		<b>Regn Cd:</b>	W1 Los Angeles
<b>Engineering:</b>		<b>Phone:</b>	
		<b>TAR:</b>	
<b>Dlr Contact:</b>	MARK NISHIOKA	<b>Phone:</b>	808 326-5655
		<b>Title Cde:</b>	T

**DTCs:**  
KOEO:C1B00 C200D  
KOEC:  
KOER:

**Comments**

:

**REPAIR** 08/31/2011 07:23PM JONATHAN SAVOY MSS - FCSD - TECH SVC HOTLINE  
WEB FORM DATA - CONCERN: CUST STATES ADVANCE TRAC LIGHT CAME ON  
LOST  
POWERSTEERING DIAGNOSTICS: PULLED CODES . RAN OASIS FOUND TSB PER  
CODE #11-6-12. TRIED TO PEFORM UPDATE ON SCCM AND IT SAYS THERE IS NO  
UPDATE FOR SCCM PARTS REPLACED:: NONE TECH QUESTION: IS THERE ANY  
OTHER KNOWN REPAIR FOR THIS CONCERN.

**RECOMM** 08/31/2011 07:23PM JONATHAN SAVOY MSS - FCSD - TECH SVC HOTLINE  
SCOTT, PLEASE CONFIRM THAT THE IDS IS UPDATED TO THE LATEST VERSION  
74.04A PRIOR TO PERFORMING THE UPDATE. IF THE IDS IS NOT UPDATED, IT  
MAY NOT HAVE CALIBRATIONS THEREFORE IT WILL SHOW NO UPDATES FOR  
THE  
VEHICLE. IF THERE ARE NO UPDATES FOR THE VEHICLE, IT IS POSSIBLE  
THAT THE STEERING RACK IS CAUSING THIS CONCERN. IN ORDER TO HELP  
ISOLATE THE ROOT CAUSE OF THIS CONCERN, DUPLICATED THE CONCERN THEN  
PERFORM THE INTERACTIVE DIAGNOSTICS.

---

**From:** Jackson, Bradley (B.G.)  
**Sent:** Friday, August 26, 2011 9:48 AM  
**To:** Napoli, Laura (L.); Mrozek, Robert (R.M.); Fumerola, Tom (T.)  
**Cc:** Buelow, Steve (S.E.)  
**Subject:** FW: 2011 EXP/ [REDACTED] CHASSIS - Report Summary(s) from a GCQIS Query Disposition

2 more U502 C200D CQIS calls today.....fyi.

Tom, do you have an ETA on service message that will direct the dealer to replace the steering gear whenever they see a C200D DTC on U502?

Brad

<b>Report# :</b>	BHYEO003 NHL	<b>Received:</b>	08/25/2011
<b>CCRG/EPRC:</b>		<b>Date:</b>	
<b>Vehicle:</b>	2011,EXPLORER 4X2 (U502) ,XLT ,4 DOOR ,MPV ,1FMHK7D88BG [REDACTED]	<b>Build Date:</b>	04/05/2011
<b>Odometer :</b>	6,008 M	<b>Engine:</b>	3.5L CYCLO
<b>Transmission:</b>	6F50	<b>Calibration:</b>	BUB1SN0A
<b>Dealer:</b>	USA 04910 Cook-Whitehead Ford	<b>A/C:</b>	YES
<b>City:</b>	Panama City	<b>Phone#:</b>	(850) 784- 0400
<b>Originator:</b>	WILLIAM MARLEY	<b>State:</b>	Florida
<b>Symptom:</b>	6 62 4 28 SP/ST/RD,STEER/STER WHL,PERFORMANCE,EXCESS EFFORT	<b>Country :</b>	USA
<b>Status:</b>			
<b>VFG:</b>	V87 STEERING		
<b>Additional Symptom:</b>	C200D		
<b>Fix:</b>	<b>Causal Component :</b>		--
<b>Condition Code:</b>			
<b>Hotliner:</b>	BWRIGH77	<b>Phone:</b>	313 317-7040
<b>Engineering:</b>		<b>Regn Cd:</b>	S3 Orlando
<b>Dlr Contact:</b>	WILLIAM MARLEY	<b>Phone:</b>	000 000-0000
		<b>TAR:</b>	
		<b>Title Cde:</b>	T

**DTCs:**  
KOEO:C1B00 C200D  
KOEC:  
KOER:

**Comments**

REPAIR 08/25/2011 02:28PM BRANDON WRIGHT MSS - FCSD - TECH SVC HOTLINE  
 WEB FORM DATA - CONCERN: ADVANCE TRACK LIGHT CAME ON AND COULD NOT  
 STEER WHEN WAS ON. HAD TO TURN CAR OFF FOR IT TO RESTART. DIAGNOSTICS: SCANNED FOR CODES. FOUND CODE C1B00:86 IN THE  
 ABS MODULE AND C200D:49 IN THE PSCM . PARTS REPLACED::  
 NONE. TECH QUESTION: SEEKING ANY KNOWN CAUSES FOR THIS CONCERN IN  
 YOUR DATA BASE. ALL CODES SEEM TO LEAD ME BACK TO THE SCCM BUT NO  
 CODES PRESENT BUT WHEN I GO TO DATA LOGGER THE STEERING ANGLE  
 READINGS  
 DO NOT MATCH. THANKS FOR THE HELP.

**RECOMM 08/25/2011 02:28PM BRANDON WRIGHT MSS - FCSD - TECH SVC HOTLINE**  
 WILLIAM, IF YOU HAVE NOT DONE SO ALREADY, RECOMMEND TO VERIFY THE  
 INTEGRITY OF THE POWER AND GROUND CIRCUITS TO THE PSCM BY VOLTAGE  
 DROP  
 TESTING THEM. IF THE VOLTAGE DROP EXCEEDS .2V, REPAIR THE CIRCUIT AS  
 NECESSARY. IF NO CIRCUITRY CONCERNS ARE FOUND, IT IS RECOMMENDED TO  
 REFER TO THE ONLINE WORKSHOP MANUAL SECTION 211-00 INTERACTIVE  
 DIAGNOSTICS AND PERFORM DIAGNOSTIC ROUTINE B TO DIAGNOSE THIS  
 CONCERN.

<b>Report# :</b>	BHYAW014 NHL	<b>Received:</b>	08/25/2011
<b>CCRG/EPRC:</b>		<b>Reviewed Status:</b>	<b>Date:</b>
<b>Vehicle:</b>	2011,EXPLORER 4X4 (U502) ,LIMITED,4 DOOR ,MPV ,1FMHK8F88BG [REDACTED]	<b>Build Date:</b>	02/18/2011
<b>Odometer :</b>	8,411 M	<b>Engine:</b>	3.5L CYCLO
<b>Transmission:</b>	6F50	<b>Axle:</b>	<b>Calibration:</b> BUB1SN0A
<b>Dealer:</b>	USA 08199 Dave Sinclair Ford, Inc.	<b>Phone#:</b>	(314) 892- 2600
<b>City:</b>	St Louis	<b>State:</b>	Missouri
<b>Originator:</b>	MIKE CRITES	<b>Country :</b>	USA
<b>Symptom:</b>	6 62 4 39 SP/ST/RD,STEER/STER WHL,PERFORMANCE,INTERMITTENT		
<b>Status:</b>			
<b>VFG:</b>	V87 STEERING		
<b>Additional Symptom:</b>	LACK OF ASSIST		
<b>Fix:</b>	<b>Causal Component :</b>	--	
<b>Condition Code:</b>			

**Hotliner:** MHINDERE                      **Phone:** 000 337-9292                      **Regn Cd:** C4 Kansas City  
**Engineering:**                                      **Phone:**                                      **TAR:**



**Dlr Contact:** MIKE CRITES

**Phone:** 314 892-2600

**Title Cde:** T

**DTCs:**

KOEO:

KOEC:C1B00 C200D

KOER:

**Comments**

:

**REPAIR** 08/25/2011 11:45AM MICHAEL HINDERER MSS - FCSD - TECH SVC HOTLINE  
WEB FORM DATA - CONCERN: EPAS INOP AT TIMES AND MESSAGE CENTER  
READS  
SERVICE TERRAIN MGT SYSTEM DIAGNOSTICS: CHECKED OASIS FOUND TSB  
11-06-12 FOR SSCM RECAL HAS LATEST CALIB CHECKED FOR CODES HAS  
C1B00-68 ABS AND C200D:49-08PSCM CHECKED PSCM WIRING AND CONNECTORS  
NO  
ISSUE S FOUND PARTS REPLACED:: NONE TECH QUESTION: I CANNOT  
FIND C1B00:86-68 WHAT MAY BE CAUSING THIS CONCERN ;

**RECOMM** 08/25/2011 11:45AM MICHAEL HINDERER MSS - FCSD - TECH SVC HOTLINE  
MICHAEL, RECOMMEND TO LOAD TEST AND VOLTAGE DROP POWER AND  
GROUND AT  
THE PSCM. ALSO CLOSELY INSPECT PINFIT AND CONNECTION AT THE PSCM. IF  
ALL OK, RECOMMEND TO REPLACE THE STEERING GEAR ASSEMBLY AND  
RETEST.

---

**From:** Napoli, Laura (L.)  
**Sent:** Thursday, July 14, 2011 9:19 AM  
**To:** Estes, Eric (E.E.)  
**Subject:** FW: 2011 EXP/[REDACTED] CHASSIS - Report Summary(s) from a GCQIS Query Disposition

We have another C200D...

---

**From:** SBUELOW [mailto:SBUELOW]  
**Sent:** Wednesday, July 13, 2011 2:34 AM  
**To:** L NAPOLI  
**Subject:** 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

This email contains 13 report summary(s).

---

**Attachments :** 0

<b>Report# :</b>	BGLCF008 NHL	<b>Received:</b>	07/12/2011
<b>CCRG/EPRC:</b>		<b>Reviewed Status:</b>	<b>Date:</b>
<b>Vehicle:</b>	2011,EXPLORER 4X2 (U502),4 DOOR ,MP,1FMHK7D86BG [REDACTED]	<b>Build Date:</b>	04/25/2011
<b>Odometer :</b>	4,885 M	<b>Engine:</b>	3.5L CYCLO
<b>Transmission:</b>	6F50	<b>Axle:</b>	<b>Calibration:</b>
<b>Dealer:</b>	USA 04962 World Ford-Pensacola	<b>A/C:</b>	YES
<b>City:</b>	Pensacola	<b>State:</b>	Florida
<b>Originator:</b>	DIANNE TUMINO	<b>Phone#:</b>	(850) 479- 1311
<b>Symptom:</b>	6 62 4 39 SP/ST/RD,STEER/STER WHL,PERFORMANCE,INTERMITTENT		
<b>Status:</b>			
<b>VFG:</b>	V87 STEERING		
<b>Additional Symptom:</b>	STEERING HARD C1B00 C200D		
<b>Fix:</b>	<b>Causal Component :</b>	--	
<b>Condition Code:</b>			

<b>Hotliner:</b> DKNAPP7	<b>Phone:</b> 000 317-6316	<b>Regn Cd:</b> S3 Orlando
<b>Engineering:</b>	<b>Phone:</b>	<b>TAR:</b>
<b>Dlr Contact:</b> DIANNE TUMINO	<b>Phone:</b> 000 000-0000	<b>Title Cde:</b> WA

**DTCs:**

KOEO:C1B00 C200D

KOEC:

KOER:

**Comments**

:

**REPAIR** 07/12/2011 02:03PM DAVID KNAPP MSS - FCSD - TECH SVC HOTLINE  
WEB FORM DATA - CONCERN: C/S THAT HIS WIFE WAS DRIVING DOWN THE ROAD AND A STEERING FAILURE LIGHT CAME ON THEN STEERING WHEEL LOCKED UP. DIAGNOSTICS: USED IDS AND INTERACTIVE DIAGNOSTICS, RETRIEVED CODES AND FOLLOWED PIN POINT PROCEDURES, VERIFIED ELECTRICAL CONNECTIONS AND WIRING LOOKS OK, NO VISIBLE DAMAGE TO STEERING SYSTEM. PARTS REPLACED:: NONE TECH QUESTION: HAD CODES C1B00:86-28, C200D:49-08, WENT THROUGH PIN POINT TESTS AND ENDED UP AT CLEAR CODE AND RETURN TRUCK TO CUSTOMER, THEN DROVE IT 15 MILES WITH LOTS OF SIDE ROAD TURNING MANUEVERS AND DIDNT DUPLICATE CONCERN. LOOKING FOR ANY KNOWN CONCERNS OR FURTHER THINGS I CAN CHECK DUE TO THE LIABILITY IF THIS CONDITION OCCURS AGAIN AND CUST HAS ACCIDENT OR SOMETHING BAD HAPPENS. NOT COMFORTABLE RETURNING CAR WITHOUT CHECKING WITH YOU GUYS DUE TO THE SAFETY NATURE OF THEIR CONCERN. THANKS.

**RECOMM** 07/12/2011 02:03PM DAVID KNAPP MSS - FCSD - TECH SVC HOTLINE  
DIANNE, WE WOULD SUGGEST YOU USE <>  
HREF='HTTP://WWW.VREP.FORDTECHSERVICE.DEALERCONNECTION.COM/VDIRS/SSM/SSM.ASP?SSM=21737' TARGET='\_BLANK'>SSM 21737 TO ADDRESS THIS  
CONDITION.

---

---

**From:** Napoli, Laura (L.)  
**Sent:** Thursday, June 30, 2011 9:00 AM  
**To:** Estes, Eric (E.E.)  
**Subject:** FW: 2011 EXP/[REDACTED] CHASSIS - Report Summary(s) from a GCQIS Query Disposition

Another B9A and one F00049-48 which is an A0B. Haven't seen one of those yet. There's also a C69 which we obviously don't know what is causing that.

---

**From:** SBUELOW [mailto:SBUELOW]  
**Sent:** Thursday, June 30, 2011 4:53 AM  
**To:** LNAPOLI  
**Subject:** 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

This email contains 10 report summary(s).

<b>Report# :</b>	BF3AJ001 NHL	<b>Received:</b>	06/29/2011
<b>CCRG/EPRC:</b>		<b>Reviewed Status:</b>	<b>Date:</b>
<b>Vehicle:</b>	2011,EXPLORER 4X2 (U502),4 DOOR ,MP,1FMHK7F84BG [REDACTED]	<b>Build Date:</b>	04/13/2011
<b>Odometer :</b>	2,359 M	<b>Engine:</b>	3.5L CYCLO
<b>Transmission:</b>	6F50	<b>Axle:</b>	<b>Calibration:</b>
<b>Dealer:</b>	USA 01597 Santa Margarita Ford	<b>A/C:</b>	YES
<b>City:</b>	Rancho Santa Mar	<b>State:</b>	California
<b>Originator:</b>	OMAR TRIANA	<b>Phone#:</b>	(949) 888-4348
<b>Symptom:</b>	3 03 1 50 CHASS.,STRG/HANDLING ,FUNCTION,HIGH EFFORT	<b>Country :</b>	USA
<b>Status:</b>			
<b>VFG:</b>	V87 STEERING		
<b>Additional Symptom:</b>	INTERM LOSS OF P/S ASSIST		
<b>Fix:</b>	<b>Causal Component :</b>		--
<b>Condition Code:</b>			
<b>Hotliner:</b>	RHAIST1	<b>Phone:</b>	313 317-9342
<b>Engineering:</b>		<b>Regn Cd:</b>	W1 Los Angeles
<b>Dlr Contact:</b>	OMAR TRIANA	<b>Phone:</b>	000 000-0000
		<b>TAR:</b>	
		<b>Title Cde:</b>	T

**DTCs:**  
KOEO:C200D:49  
KOEC:

KOER:

**Comments**

:

REPAIR 06/29/2011 07:39AM RICK HAIST MSS - FCSD - TECH SVC HOTLINE  
WEB FORM DATA - CONCERN: VEHICLE AT TIMES POWER STEERING LOSS ON  
TURNS AND AT DASH READ POWER STEERING FAILURE DIAGNOSTICS:  
PERFORMED PINPOINT TEST B1 B2 B3/ . INSPECTED EPAS GEAR BOOST FOR  
DAMAGE , NO PROBLEMS FOUND/ INSPECTED WIRE HARNNES AND THREE  
CONNECTORS , NO PROBLEMS FOUND/ TEST DRIVE FOR RETURNING DTCS,  
PASSED  
BUT VEHICLE WAS PARKING FOR TWO HOURS , REROAD TEST WHEN BACKING UP  
AND TURN THE STEERING WHEEL TO THE RIGHT LOOS POWER STEERING AND AT  
DASH READING P/S FAILURE. DTC C200D:49 AGEN PARTS REPLACED::  
NONE TECH QUESTION: SO DTC C200D:49 RETURN ACCORDING WITH THE WORK  
SHOP MANUAL I HAVE TO REPLACE THE EPAS GEAR? YOU KNOW OTHER  
VEHICLES  
FOR THE SAME CONCERN.?I DID THE WIGGLE TEST STILL THE SAME WERE  
YOU ABLE TO VERIFY THE CONCERN? YES IS THERE AN APPROPRIATE  
PINPOINT TEST IN THE WSM FOR THIS CONCERN? YES WAS THE PINPOINT  
TEST FOLLOWED? YES

RECOMM 06/29/2011 07:39AM RICK HAIST MSS - FCSD - TECH SVC HOTLINE  
OMAR, BASED ON THE CONCERN SYMPTOMS AND THE C200D:49 DC RETURNING  
IN  
THE PSCM MODULE AFTER CLEARING IT AND ROAD TESTING THE VEHICLE, WE  
WOULD RECOMMEND REPLACEMENT OF THE EPAS STEERING GEAR ASSEMBLY  
PER  
PINPOINT TEST "B" IN SECTION 211-00 OF THE ONLINE WSM. -THERE  
WERE NO PAST REPORTS ON LIKE VEHICLES WITH THIS TYPE OF CONCERN AND  
A  
C200D:49 DTC BEING SET.

---

Attachments : 0

<b>Report# :</b>	BF3FM006 NHL	<b>Received:</b>	06/29/2011
<b>CCRG/EPRC:</b>		<b>Date:</b>	
<b>Vehicle:</b>	2011,EXPLORER 4X4 (U502),4 DOOR ,MP,1FMHK8F81BG [REDACTED]	<b>Build Date:</b>	05/21/2011
<b>Odometer :</b>	215 M	<b>Engine:</b>	3.5L CYCLO
<b>Transmission:</b>	6F55	<b>Axle:</b>	
		<b>Calibration:</b>	
		<b>A/C:</b>	YES

**Dealer:** USA 10565 Napleton's Park Ridge Lincoln- **Phone#:** (847) 825-0770  
**City:** Park Ridge **State:** Illinois **Country :** USA  
**Originator:** BROCK KENSKI  
**Symptom:** 3 03 1 50 CHASS.,STRG/HANDLING ,FUNCTION,HIGH EFFORT  
**Status:**  
**VFG:** V87 STEERING  
**Additional Symptom:** POWER ASSIST FAULT U3000  
**Fix:** **Causal Component :** --  
**Condition Code:**

**Hotliner:** BWRIGH77 **Phone:** 313 317-7040 **Regn Cd:** G1 Chicago  
**Engineering:** **Phone:** **TAR:**  
**Dlr Contact:** BROCK KENSKI **Phone:** 847 825-0770 **Title Cde:** T

**DTCs:**

KOEO:U3000:96-C8 U3000:49-48

KOEC:

KOER:

**Comments**

:

**REPAIR** 06/29/2011 04:21PM BRANDON WRIGHT MSS - FCSD - TECH SVC HOTLINE  
WEB FORM DATA - CONCERN: GETTING POWER STEERING ASSIST FAULT MSG  
AND  
HARD TO TURN DIAGNOSTICS: U 3000 49-48 PSCM AND U3000 96-C8.  
PINPOINT TEST AND STATES REFLASH PSCM SOFTWARE PARTS REPLACED::  
NONE TECH QUESTION: TRIED TO REFLASH THE PSCM MODULE BUT NO OPTION  
TO REFLASH AT ALL WERE YOU ABLE TO VERIFY THE CONCERN? YES IS  
THERE AN APPROPRIATE PINPOINT TEST IN THE WSM FOR THIS CONCERN?  
YES WAS THE PINPOINT TEST FOLLOWED? YES

**RECOMM** 06/29/2011 04:21PM BRANDON WRIGHT MSS - FCSD - TECH SVC HOTLINE  
BROCK, ACCORDING TO THE INTERACTIVE DIAGNOSTIC ROUTINE C,  
REPLACEMENT  
OF THE PSCM IS REQUIRED. RECOMMEND TO CHECK THE PSCM CONNECTOR FOR  
PROPER PIN FIT, CORROSION OR PUSHED OUT PINS. IF NO CONNECTOR  
CONCERNS  
ARE FOUND, REPLACE THE PSCM AND RE-EVALUATE THE CONCERN. IF FURTHER  
ASSISTANCE IS REQUIRED, PLEASE UPDATE THE FORM WITH YOUR LATEST  
RESULTS.

---

**From:** Napoli, Laura (L.)  
**Sent:** Friday, April 29, 2011 8:54 AM  
**To:** Estes, Eric (E.E.); 'Greg Austin'  
**Subject:** FW: 2011 EXP/[REDACTED] CHASSIS - Report Summary(s) from a GCQIS Query Disposition

TS failure in warranty on U502. Let's hope this TS was built before the visual inspection...assuming it's a bent finger.

---

**From:** SBUELOW [mailto:SBUELOW]  
**Sent:** Friday, April 29, 2011 5:01 AM  
**To:** LNAPOLI  
**Subject:** 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

---

**Attachments :** 0

<b>Report# :</b>	BD2BP002 NHL	<b>Received:</b>	04/28/2011
<b>CCRG/EPRC:</b>		<b>Reviewed Status:</b>	<b>Date:</b>
<b>Vehicle:</b>	2011,EXPLORER 4X4 (U502),4 DOOR ,MP,1FMHK8F80BG [REDACTED]	<b>Build Date:</b>	02/04/2011
<b>Odometer :</b>	13 M	<b>Engine:</b>	3.5L CYCLO
<b>Transmission:</b>	6F55	<b>Axle:</b>	<b>Calibration:</b> BUB1ST0A
<b>Dealer:</b>	USA 02058 Beechmont Ford Inc	<b>Phone#:</b>	(513) 752- 7474
<b>City:</b>	Cincinnati	<b>State:</b>	Ohio
<b>Originator:</b>	SHANE JONES	<b>Country :</b>	USA
<b>Symptom:</b>	3 03 0 00 CHASS.,STRG/HANDLING ,OTHER-CODE NA,OTHER-CODE NA		
<b>Status:</b>			
<b>VFG:</b>	V89 RIDE & HANDLING		
<b>Additional Symptom:</b>	MULTIPLE CODES		
<b>Fix:</b>	<b>Causal Component :</b>	--	
<b>Condition Code:</b>			
<b>Hotliner:</b> JELLERH2	<b>Phone:</b> 313 317-9374	<b>Regn Cd:</b> G3 Cincinnati	
<b>Engineering:</b>	<b>Phone:</b>	<b>TAR:</b>	
<b>Dlr Contact:</b> SHANE JONES	<b>Phone:</b> 513 752-7474	<b>Title Cde:</b> T	

**DTCs:**

KOEO:U3000:96-C8 C200B:2F-48 C200B:61-48 C200B:62-48

KOEC:

KOER:

**Comments :**

**REPAIR** 04/28/2011 09:08AM JAMES ELLERHOLZ MSS - FCSD - TECH SVC HOTLINE  
WEB FORM DATA - CONCERN: NO POWER STEERING DIAGNOSTICS: IDS TESTED  
AND GOT DTC U3000:96-C8 C200B:2F-48 C200B:61-48 C200B:62-48 THE  
U3000:96-C8 WOULD NOT CLEAR PINPOINT TEST SHOWED TO REPLACE THE  
STEERING GEAR PARTS REPLACED:: NONE TECH QUESTION: BEING A LOW  
MILE VEH I WANTED TO SEE IF THERE WERE ANY KNOWN CONCERNS WERE  
YOU ABLE TO VERIFY THE CONCERN? YES IS THERE AN APPROPRIATE  
PINPOINT TEST IN THE WSM FOR THIS CONCERN? YES WAS THE PINPOINT  
TEST FOLLOWED? YES

**RECOMM** 04/28/2011 09:08AM JAMES ELLERHOLZ MSS - FCSD - TECH SVC HOTLINE  
SHANE, WE DO NOT HAVE ANY TRENDS OR SIMILAR CONCERNS. IF THE WIRING  
AND ALL CONNECTORS ARE IN GOOD SHAPE, WE RECOMMEND REPLACE THE  
STEERING GEAR AS INSTRUCTED.

---

---

---



**From:** Jackson, Bradley (B.G.)  
**Sent:** Friday, April 22, 2011 12:22 PM  
**To:** Buelow, Steve (S.E.); Millard, Lyle (L.); Brucker, Eric (.); Napoli, Laura (L.)  
**Cc:** Docimo, Tony (A.F.); McAllister, Derek (D.)  
**Subject:** FW: 2011 EXP/[REDACTED] CHASSIS - Report Summary(s) from a GCQIS Query Disposition

Steve / Lyle, the 2011 Explorer in the hotline report below is not a candidate for SSM 21737 based on vehicle build date. SSM 21737 is only valid on units built prior to 24 January 2011.

Laura / Eric, based on the lost communication codes below, do you have any recommendations for this dealer to help diagnosis?

The only thing I could suggest is that the dealer monitor steering angle signal from the PSCM and the yaw/roll signal from the RCM while replicating the customer concern.

Brad Jackson

<b>Report# :</b>	BDUB5007 NHL	<b>Received:</b>	04/21/2011
<b>CCRG/EPRC:</b>		<b>Date:</b>	
<b>Vehicle:</b>	2011,EXPLORER 4X2 (U502),4 DOOR ,MP,1FMHK7D84BG [REDACTED]	<b>Build Date:</b>	03/24/2011
<b>Odometer :</b>	164 M	<b>Engine:</b>	3.5L CYCLO
<b>Transmission:</b>	6F50	<b>Axle:</b>	
<b>Dealer:</b>	USA 05662 Crossroads Ford Lincoln, Inc.	<b>Calibration:</b>	
<b>City:</b>	Frankfort	<b>A/C:</b>	YES
<b>State:</b>	Kentucky	<b>Phone#:</b>	(502) 695-1990
<b>Country :</b>	USA	<b>Phone#:</b>	
<b>Originator:</b>	MARTY MITCHAM	<b>Country :</b>	USA
<b>Symptom:</b>	3 01 A 04 CHASS.,SERVICE BRAKE ,INDICATOR,T/C LIGHT		
<b>Status:</b>			
<b>VFG:</b>	V21 BRAKING		
<b>Additional Symptom:</b>	TRAC LIGHT ON/NO ASSIST INT		
<b>Fix:</b>	<b>Causal Component :</b>	--	
<b>Condition Code:</b>			
<b>Hotliner:</b>	LMILLA11	<b>Phone:</b>	313 317-9130
<b>Engineering:</b>		<b>Regn Cd:</b>	G3 Cincinnati
<b>Phone:</b>		<b>TAR:</b>	
<b>Dlr Contact:</b>	MARTY MITCHAM	<b>Phone:</b>	502 695-1990
		<b>Title Cde:</b>	T

**DTCs:**  
**KOEO:**  
**KOEC:**

KOER:

**Comments**

:

**REPAIR** 04/21/2011 10:08AM LYLE MILLARD MSS - FCSD - TECH SVC HOTLINE  
WEB FORM DATA - CONCERN: CUSTOMER SAYS WHILE LEAVING A RESTURANT  
YESTERDAY, HE HAD NO POWER STEERING ALL THE WAY HOME. ALSO THE TRAC  
CONTROL LIGHT CAME ON TWICE AND WENT OFF. EVERY THING OK THIS  
MORNING DIAGNOSTICS: IDS DIAG. PSCM-PINPOINT TEST B. CHECKED  
CONNECTIONS AT GEAR-OK CODES C1B00:86-28 ABS, U0182:87-0A BCM,  
U0212:87-0A BCM, U0253:00-28 IPC, C200D:49-08 PSCM ALL OK AT THIS  
TIME PARTS REPLACED:: NONE TECH QUESTION: ANY KNOWN  
CONCERNS WERE YOU ABLE TO VERIFY THE CONCERN? NO IS THERE AN  
APPROPRIATE PINPOINT TEST IN THE WSM FOR THIS CONCERN? YES WAS THE  
PINPOINT TEST FOLLOWED? YES

**RECOMM** 04/21/2011 10:08AM LYLE MILLARD MSS - FCSD - TECH SVC HOTLINE  
MARTY, PLEASE ENSURE THAT THE CONCERN CAN BE VERIFIED BEFORE ANY  
REPAIRS ARE TO BE PERFORMED. IF THE CONCERN CAN BE DUPLICATED AND  
VERIFIED, THIS CONCERN CAN BE ADDRESSED BY CONSULTING SSM  
21737. THIS SSM ADDRESSES COMMUNICATION ISSUES THAT WOULD SET THESE  
CODES. DTC U0253 DOES NOT PERTAIN TO THE CONCERN AND SHOULD BE  
DISREGARDED. IF COMMUNICATION IS RESTORED PLEASE RETEST, AND  
EVALUATE. SSM 21737 CODES C1B00, U0131, U0100, U0001, U0121,  
AND/OR U0151- CLEAR CODES AND WIGGLE TEST CONNECTER C139. IFCODES  
RETURN, BYPASS C139 FOR CIRCUITS VDB04 AND VDB05 USING THE SOLDER AND  
SHRINK TUBING METHOD FOUND IN SECTION 5 OF THE WIRING DIAGRAMS.

---

---

**From:** Napoli, Laura (L.)  
**Sent:** Friday, April 01, 2011 9:34 AM  
**To:** Estes, Eric (E.E.); Anderson, Eric (H.)  
**Subject:** FW: 2011 EXP, [REDACTED] CHASSIS - Report Summary(s) from a GCQIS Query Disposition

2 wiring issues below causing loss of assist. Did either of you talk to these dealers already? If not, I'll call to make sure they don't pull the gears. Please let me know.

---

**From:** SBUELOW [mailto:SBUELOW]  
**Sent:** Friday, April 01, 2011 4:47 AM  
**To:** LNAPOLI  
**Subject:** 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

**Report# :** BC5AL007 NHL  
**CCRG/EPRC:** **Reviewed Status:**  
**Vehicle:** 2011,EXPLORER 4X4 (U502),4 DOOR  
,MP,1FMHK8F82BG [REDACTED] **Build Date:** 02/23/2011  
**Odometer :** 13 M **Engine:** 3.5L  
CYCLO **Calibration:** BUB1ST0A  
**Transmission:** 6F55 **Axle:** **A/C:** YES  
**Dealer:** USA 00978 Capital Ford, Inc. **Phone#:** (919) 790-4700  
**City:** Raleigh **State:** North Caroli **Country :** USA  
**Originator:** RYAN WALLACE  
**Symptom:** 3 03 1 50 CHASS.,STRG/HANDLING ,FUNCTION,HIGH EFFORT  
**Status:**  
**VFG:** V87 STEERING  
**Additional Symptom:** NO POWER STEERING ASSIST  
**Fix:** **Causal Component :** --  
**Condition Code:**

**Hotliner:** WHOUST13 **Phone:** 313 317-7044 **Regn Cd:** S2 Charlotte  
**Engineering:** **Phone:** **TAR:**  
**Dlr Contact:** RYAN WALLACE **Phone:** 000 000-0000 **Title Cde:** T

**DTCs:**  
KOEO:  
KOEC:

KOER:

**Comments**

:

**REPAIR** 03/31/2011 12:22PM WILLIE HOUSTON MSS - FCSD - TECH SVC HOTLINE  
WEB FORM DATA - CONCERN: POWER STEERING INOP DIAGNOSTICS: NETWORK  
TEST NO COMMUNICATION WITH PSCM, PINPIONT TEST AC1-12VOLTS AT C1463A  
PIN 3, PINPIONT AC2- .2 OHMS C1463B PIN2, PINPIONT TEST AC3- C1463A  
PIN 1 TO DLC PIN6 1.2 OHMS, C1463A PIN 2 TO DLC PIN14 1 OHM, PINPIONT  
TEST AC4 NO PUSHED OUT PINS OR CORROSION OR BENT OR DAMAGED  
PINS PARTS REPLACED:: STEERING GEAR TECH QUESTION: ANY KNOWN  
PROBLEMS WITH REPROGRAM OR COMMUNICATION WITH THE PSCM, ANY  
OTHER  
PINPIONT TEST? WERE YOU ABLE TO VERIFY THE CONCERN? YES IS  
THERE AN APPROPRIATE PINPOINT TEST IN THE WSM FOR THIS CONCERN?  
YES WAS THE PINPOINT TEST FOLLOWED? YES

**RECOMM** 03/31/2011 12:22PM WILLIE HOUSTON MSS - FCSD - TECH SVC HOTLINE  
RYAN, THE EPAS SYSTEM THAT THIS VEHICLE HAS IS TOTALLY SELF  
CONTAINED. THE GEAR REQUIRES POWER AND GROUND AND NETWORK  
CIRCUITS FOR  
COMMUNICATION. IF THE EPAS GEAR HAS BEEN REPLACED, AND THERE IS NO  
ASSIST OR COMMUNICATION WITH THE MODULE, LOAD TEST THE POWERS AND  
GROUNDS TO THE EPAS USING A HEADLAMP BULB TO VERIFY THAT THEY ARE  
CAPABLE OF CARRYING SUFFICIENT AMPERAGE AND PERFORM WIGGLE TESTS  
DURING THIS LOAD TEST. IF OKAY, VERIFY THAT THE NETWORK VOLTAGES AT  
THE PSCM CONNECTOR CORRESPOND WITH THE VOLTAGES AT PINS 6 AND 14 OF  
THE DLC WITH THE VEHICLE IN A KOEO STATE. CLOSELY INSPECT FOR  
LOOSE/DAMAGE OR OTHER PINFIT ISSUES AT THE PSCM AND BJB. REFERENCE  
PAGE 43-1 OF THE ONLINE EVTMM FOR CIRCUIT DETAILS.

---

**Attachments : 0**

<b>Report# :</b>	BC5EH004 NHL	<b>Received:</b>	03/31/2011
<b>CCRG/EPRC:</b>		<b>Date:</b>	
<b>Vehicle:</b>	2011,EXPLORER 4X2 (U502),4 DOOR ,MP,1FMHK7F86BG [REDACTED]	<b>Build Date:</b>	03/02/2011
<b>Odometer :</b>	33 M	<b>Engine:</b>	3.5L CYCLO
		<b>Calibration:</b>	

**Transmission:** 6F55                      **Axle:**    **A/C:** YES  
**Dealer:** USA 02561 Sewell Ford, Inc.    **Phone#:** (432) 498-0421  
**City:** Odessa                      **State:** Texas                      **Country :** USA  
**Originator:** STEFAN DROUI  
**Symptom:** 3 03 1 50 CHASS.,STRG/HANDLING ,FUNCTION,HIGH EFFORT  
**Status:**  
**VFG:** V87 STEERING  
**Additional Symptom:** LOSS OF ASSIST  
**Fix:**                      **Causal Component :** --  
**Condition Code:**

**Hotliner:** IWRIGH24                      **Phone:** 313 317-4284                      **Regn Cd:** C1 Dallas  
**Engineering:**    **Phone:**    **TAR:**  
**Dlr Contact:** STEFAN DROUI                      **Phone:** 432 432-3320                      **Title Cde:** T

**DTCs:**  
 KOEO:C1B00:29 C1B00:41 U0131  
 KOEC:  
 KOER:

**Comments**  
:

**REPAIR** 03/31/2011 03:28PM IAN WRIGHT MSS - FCSD - TECH SVC HOTLINE  
 WEB FORM DATA - CONCERN: LOST ALL POWER STEERING ,TOWED IN,POWER STEERING NOW. ADVANCE TRACK LIGHT ON ABS LIGHT ON DIAGNOSTICS: IDS TEST,MONITERED PIDS STEERING ANGLE PI WAS 49150.95. INSPECTED CONNECTIONS ON EPAS,ABS MODULE,SJB,BJB ALL OK,INSPECTED GRONDS PARTS REPLACED:: NO PARTS REPLACED TECH QUESTION: POWER STEERING LOCKED,ADVANCED TRACK LIGHT ON,SOMETIMES STEERING FUNCTIONS,OTHER TIMES IT DOESNT,CANT COMMUNICATE WITH PSCM AT TIMES,OTHER TIMES CAN. CODES C1B00:29-68 AND C1B00:41-68. CANNOT FIND CORRECT PIN POINT TEST. I FEEL LIKE IT IS THE PSCM,EPAS RAC-N-PINION. DO HAVE ANY REPAIR IDEAS NOT SURE WHERE TO GO.

**RECOMM** 03/31/2011 03:28PM IAN WRIGHT MSS - FCSD - TECH SVC HOTLINE  
 STEFAN, THE READING OF THE STEERING ANGLE SENSOR IS NORMAL. THE STEERING ANGLE SENSOR LEARNS A ZERO POINT AFTER DRIVING STRAIGHT. REFER TO <>  
 HREF='HTTP://WWW.VREP.FORDTECHSERVICE.DEALERCONNECTION.COM/VDIRS/SSM/SSM.ASP?SSM=21737' TARGET='\_BLANK'>SSM 21737 TO ADDRESS THE FAULTS PRESENT. SSM 21737 CODES C1B00, U0131, U0100, U0001, U0121, AND/OR U0151- CLEAR CODES AND WIGGLE TEST CONNECTER C139. IFCODES RETURN,

BYPASS C139 FOR CIRCUITS VDB04 AND VDB05 USING THE SOLDER AND SHRINK TUBING METHOD FOUND IN SECTION 5 OF THE WIRING DIAGRAMS.

---

---

**From:** Napoli, Laura (L.)  
**Sent:** Tuesday, February 15, 2011 3:04 PM  
**To:** Diez, Timothy (T.P.)  
**Subject:** FW: 2011 EXP/[REDACTED] CHASSIS - Report Summary(s) from a GCQIS Query Disposition

Just noticed you weren't on my response.

And to answer your question from yesterday, 48mm motor is used on 2.0L, 58mm is used on 3.5L.

---

**From:** Napoli, Laura (L.)  
**Sent:** Tuesday, February 15, 2011 3:04 PM  
**To:** Jackson, Bradley (B.G.); Mrozek, Robert (R.M.); Rossi, Roberto (R.A.)  
**Cc:** Anderson, Eric (H.)  
**Subject:** RE: 2011 EXP/[REDACTED] CHASSIS - Report Summary(s) from a GCQIS Query Disposition

There was a C69 in the fault store. So we need snapshot data on the gear if they haven't tried clearing the Ford DTCs. Either way, a C69 due to 3 or more B-level faults would mean the gear is locked out and service directs them to pull the gear. We need to get it back to know exactly what happened to the gear due to the disconnected connector.

---

**From:** Jackson, Bradley (B.G.)  
**Sent:** Tuesday, February 15, 2011 7:59 AM  
**To:** Napoli, Laura (L.); Mrozek, Robert (R.M.); Rossi, Roberto (R.A.)  
**Cc:** Anderson, Eric (H.)  
**Subject:** FW: 2011 EXP/[REDACTED] CHASSIS - Report Summary(s) from a GCQIS Query Disposition

Any clues about the first report from Maryland? If a loose connector was found and re-connected, any ideas on why there would still be no assist?

Also, have a look at the 3rd report from North Carolina.

Brad

This email contains 3 report summary(s).

<b>Report# :</b>	BBLAA025 NHL	<b>Received:</b>	02/12/2011
<b>CCRG/EPRC:</b>		<b>Date:</b>	
<b>Vehicle:</b>	2011,EXPLORER 4X4 (U502),4 DOOR ,MP,1FMHK8F8XBG [REDACTED]	<b>Build Date:</b>	01/20/2011
<b>Odometer :</b>	303 M	<b>Engine:</b>	3.5L
		<b>Calibration:</b>	BUB1ST0A

CYCLO

**Transmission:** 6F55                      **Axle:**    **A/C:** YES  
**Dealer:** USA 00089 Koons Ford of Annapolis, Inc.                      **Phone#:** (410) 266-3087  
**City:** Annapolis                      **State:** Maryland                      **Country :** USA  
**Originator:** JAMES MORELAND  
**Symptom:** 3 03 1 55 CHASS.,STRG/HANDLING ,FUNCTION,LOSS OF STRG  
**Status:**  
**VFG:** V89 RIDE & HANDLING  
**Additional Symptom:** U3000:96  
**Fix:**                      **Causal Component :** --  
**Condition Code:**

**Hotliner:** CBISHO41                      **Phone:** 313 317-9359                      **Regn Cd:** N4 Washington

**Engineering:**    **Phone:**    **TAR:**

**Dlr Contact:** JAMES MORELAND    **Phone:** 410 266-3087    **Title Cde:** T

**DTCs:**

KOEO:U3000:96  
 KOEC:  
 KOER:

**Comments**

**:**  
**REPAIR** 02/12/2011 01:58PM CHRIS BISHOP MSS - FCSD - TECH SVC HOTLINE  
 WEB FORM DATA - CONCERN: NO POWER STEERING DIAGNOSTICS: SELF TEST VISUAL INSPECTION FOUND CONNECTOR ON GEAR DISCONNECTED PARTS REPLACED:: NONE TECH QUESTION: CODE U3000 96 LEADS TO REPLACEMENT OF EPAS GEAR W/NO PINPOINT TESTS IS THIS CORRECT, VEHICLE WAS DX TO OUR DEALER SAID P/S WENT OUT IN OUR PARKING LOT, TESTED AND FOUND CONNECTOR 1453A DISCONNECTED. PLUGGED BACK IN BUT NO P/S AND CODE AND  
 MESSAGE CENTER WILL NOT CLEAR OUT. WERE YOU ABLE TO VERIFY THE CONCERN? YES IS THERE AN APPROPRIATE PINPOINT TEST IN THE WSM FOR THIS CONCERN? YES WAS THE PINPOINT TEST FOLLOWED? YES

**RECOMM** 02/12/2011 01:58PM CHRIS BISHOP MSS - FCSD - TECH SVC HOTLINE  
 JAMES, YOU ARE CORRECT. IF THE U3000:96 IS PRESENT AS A HARD FAULT THEN STEERING GEAR REPLACEMENT IS REQUIRED. THIS CODE INDICATES THAT THE ELECTRONIC STEERING GEAR HAS EXPERIENCED AN INTERNAL FAULT. RECOMMEND REPLACING THE GEAR AS NEEDED THEN RETESTING FOR NORMAL OPERATION.



---

**Attachments : 2**

**Report# :** BBNEY164 NHLDIG--or-- HD 201100413212 **Received:** 02/14/2011  
**CCRG/EPRC:** **Reviewed Status:** **Date:**  
**Vehicle:** 2011,TAURUS,SEL ,SEDAN ,1FAHP2HW0BG [REDACTED] **Build Date:** 01/26/2011  
**Odometer :** 1,396 M **Engine:** DURATEC **Calibration:**  
35  
**Transmission:** 6F50 **Axle:** 2.77 RATIO **A/C:** YES  
**Dealer:** USA 02393 Kowalski Ford **Phone#:** (440) 933-3291  
**City:** Avon Lake **State:** Ohio **Country :** USA  
**Originator:** chastity christman  
**Symptom:** 3 06 7 04 CHASS.,TIRES/WHEELS,APPEARANCE,PEELING  
**Status:**  
**VFG:** V88 TIRES  
**Additional Symptom:** Processed  
**Fix:** **Causal Component :** --  
**Condition Code:**  
**Region Code:** G4 **Region Name:** Pittsburgh

**DTCs:**

KOEO:

KOEC:

KOER:

**Comments :**

**CONCER** 02/14/2011 12:38PM  
drivers front rim is discolored, can only see it at certain angles,  
recommend replacing rim

**RECOMM** 02/14/2011 12:38PM

Please perform the ssm 21548 for the wheel concern. This appears to have a film on the wheel as mentioned in the ssm and will remove if cleaned as the ssm states. No need for an approval code. Thanks Sean  
contact id: 104364134

Please click on the link below to view the attachments associated with this report

[https://www.gcqis.dealerconnection.com/gcqis/asp/DIViewAttachment\\_Mainx.asp?ReportNumber=BBNEY164](https://www.gcqis.dealerconnection.com/gcqis/asp/DIViewAttachment_Mainx.asp?ReportNumber=BBNEY164)

---

**Attachments :** 0

**Report# :** BBND7002 NHL  
**CCRG/EPRC:** **Reviewed Status:**  
**Vehicle:** 2011,EXPLORER 4X2 (U502),4 DOOR  
,MP,1FMHK7B86BG [REDACTED] **Build Date:** 01/20/2011  
**Odometer :** 519 M **Engine:** 3.5L  
CYCLO **Calibration:** BUB1NN0A  
**Transmission:** 6F50 **Axle:** **A/C:** YES  
**Dealer:** USA 09151 Huntersville Ford **Phone#:** (704) 875-  
6547  
**City:** Huntersville **State:** North  
Caroli **Country :** USA  
**Originator:** TIM BARRON  
**Symptom:** 3 03 1 50 CHASS.,STRG/HANDLING ,FUNCTION,HIGH EFFORT  
**Status:**  
**VFG:** V87 STEERING  
**Additional  
Symptom:** INTERMIT NO STR ASSIST  
**Fix:** **Causal Component :** --  
**Condition Code:**

**Hotliner:** JTAYL466 **Phone:** 000 000-0000 **Regn Cd:** S2 Charlotte  
**Engineering:** **Phone:** **TAR:**  
**Dlr Contact:** TIM BARRON **Phone:** 704 400-9384 **Title Cde:** T

**DTCs:**  
KOEO:U0131  
KOEC:  
KOER:

**Comments**  
:

REPAIR 02/14/2011 04:13PM JASON TAYLOR MSS - FCSD - TECH SVC HOTLINE  
THE CUSTOMER STATES THAT INTERMITTENTLY THERE IS NO STEERING ASSIST.  
THE TECH HAS ONLY BEEN ABLE TO DUPLICATE THIS CONCERN ONCE. THE TECH  
STATES THAT HE LET THE VEHICLE IDLE FOR TWENTY MINUTES IN HIS BAY AND  
WHEN HE RETURNED THE CONCERN WAS PRESENT. THE PSCM DOES FAIL THE  
NETWORK TEST. THERE ARE CODES U0131 IN THE ABS AND IC MODULES. WHEN  
THE VEHICLE CAME IN THERE WAS A CONTINUOUS CODE U3000 IN THE PSCM,  
BUT  
THAT CODE CLEARED AND DID NOT RETURN.

**RECOMM 02/14/2011 04:13PM JASON TAYLOR MSS - FCSD - TECH SVC HOTLINE**

TIM, SUGGEST INSPECTING THE VEHICLE FOR ANY AFTER MARKET EQUIPMENT. IF THERE IS ANY AFTER MARKET EQUIPMENT PRESENT THEN REMOVE IT FROM THE

VEHICLE. IF THERE IS NO AFTER MARKET EQUIPMENT PRESENT AND THE PSCM IS NOT COMMUNICATING, THEN SUGGEST PERFORMING A LOAD TEST ON THE POWER

AND GROUND TO THE PSCM. IF THE POWER AND GROUND PROVE OUT THEN CHECK

THE COMMUNICATION CIRCUITS BETWEEN THE PSCM AND DLC FOR ANY OPEN OR

HIGH RESISTANCE ISSUES. INSPECT THE PIN FITS AT THE PSCM FOR ANY LOOSE OR DAMAGED PINS.

---

---

**From:** Napoli, Laura (L.)  
**Sent:** Saturday, January 29, 2011 1:47 PM  
**To:** Greg Austin; Gregory Sheets; 'Pat Messer'  
**Cc:** Estes, Eric (E.E.); Mrozek, Robert (R.M.)  
**Subject:** FW: 2011 EXP/[REDACTED] CHASSIS - Report Summary(s) from a GCQIS Query Disposition

**Importance:** High

Greg,

The part number for the gear I need is BB53-3200-BE. The dealership is open today until 4. Tomorrow the sales department is there from 1-5, so if the gear can be driven to the dealership tomorrow, the sales department can receive it and get it to the service area so they can begin pulling the gear first thing in the morning. Please let me know how Marion can support expediting this gear.

The dealership is:

I-77 Ford  
HC80 Box 71B  
(on Route 21 exit 132)  
Ripley, WV 25271  
(304) 372-2480  
<http://i77fordmercury.dealerconnection.com/?lang=en>

Regards,

*Laura Napoli*

U502 EPAS  
Ford Motor Company  
Cube: 2B-G66 PDC  
Phone: 313.323.0634  
Mobile: 313.805.0482

---

**From:** Jackson, Bradley (B.G.)  
**Sent:** Saturday, January 29, 2011 12:36 PM  
**To:** Anderson, Eric (H.); Napoli, Laura (L.); Mrozek, Robert (R.M.)  
**Subject:** FW: 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

note p/s inop claim from w. virginia dealer below.....1st report.

brad

---

**From:** SBUELOW [mailto:SBUELOW]  
**Sent:** Saturday, January 29, 2011 11:29 AM  
**To:** BJACKSON  
**Subject:** 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

This email contains 2 report summary(s).

**Attachments :** 0

**Report# :** BA2AK005 NHL **Received:** 01/28/2011  
**CCRG/EPRC:** **Reviewed Status:** **Date:**  
**Vehicle:** 2011,EXPLORER 4X4 (U502),4 DOOR **Build Date:** 01/12/2011  
,MP,1FMHK8D83BG [REDACTED]  
**Odometer :** 12 M **Engine:** 3.5L **Calibration:** BUB1ST0A  
CYCLO  
**Transmission:** 6F55 **Axle:** **A/C:** YES  
**Dealer:** USA 02071 I77 Ford Mercury **Phone#:** (304) 372-2480  
**City:** Ripley **State:** West **Country :** USA  
Virgini  
**Originator:** JOHNATHAN FRYE  
**Symptom:** 3 03 1 50 CHASS.,STRG/HANDLING ,FUNCTION,HIGH EFFORT  
**Status:**  
**VFG:** V87 STEERING  
**Additional Symptom:** POWER STEERING INOP  
**Fix:** **Causal Component :** --  
**Condition Code:**

**Hotliner:** IWRIGH24 **Phone:** 313 317-4284 **Regn Cd:** G3 Cincinnati  
**Engineering:** **Phone:** **TAR:**  
**Dlr Contact:** JOHNATHAN FRYE **Phone:** 304 372-3673 **Title Cde:** SM

**DTCs:**  
KOEO:U3000  
KOEC:  
KOER:

**Comments**  
:

**REPAIR** 01/28/2011 08:35AM IAN WRIGHT MSS - FCSD - TECH SVC HOTLINE  
WEB FORM DATA - CONCERN: POWER STEERING IS INOP DIAGNOSTICS: KOEO  
KOER PINPOINT TEST C1 PARTS REPLACED:: NO AT THIS TIME TECH  
QUESTION: ANY KNOWN CONCERNS WITH STEERING RACK WERE YOU ABLE TO  
VERIFY THE CONCERN? YES IS THERE AN APPROPRIATE PINPOINT TEST IN  
THE WSM FOR THIS CONCERN? YES WAS THE PINPOINT TEST FOLLOWED? YES  
**RECOMM** 01/28/2011 08:35AM IAN WRIGHT MSS - FCSD - TECH SVC HOTLINE  
JONATHAN. INSPECT CONNECTOR PIN FITS TO THE PSCM. WE HAVE SEEN SOME  
CONCERNS DUE TO SPREAD PINS AT CONNECTOR C139. INSPECT THIS

CONNECTION

USING A FLEX PROBE AND REPAIR/REPLACE ANY LOOSE PINS. PERFORM THE INTERACTIVE DIAGNOSTICS FOR FURTHER ASSISTANCE DIAGNOSING THIS CONCERN. TO PERFORM THE DIAGNOSTICS. CONNECT IDS TO VEHICLE AND GO TO THE PTS WEB PAGE. OPEN THE ONLINE WORKSHOP MANUAL OPEN SECTION 211-00 AND SELECT DTC CHART INTERACTIVE DIAGNOSTICS.

---

**Attachments : 0**

**Report# :** BA2AL015 NHL **Received:** 01/28/2011  
**CCRG/EPRC:** **Reviewed Status:** **Date:**  
**Vehicle:** 2011,EXPLORER 4X4 (U502),4 DOOR **Build Date:** 11/19/2010  
,MP,1FMHK8F89BG [REDACTED]  
**Odometer :** 1,331 M **Engine:** 3.5L **Calibration:** BUB1ST0A  
CYCLO  
**Transmission:** 6F55 **Axle:** **A/C:** YES  
**Dealer:** USA 09568 Stivers Ford Lincoln Mercury **Phone#:** (515) 987-3697  
**City:** Waukee **State:** Iowa **Country :** USA  
**Originator:** AARON KING  
**Symptom:** 3 01 A 01 CHASS.,SERVICE BRAKE ,INDICATOR,RED ONLY  
**Status:**  
**VFG:** V21 BRAKING  
**Additional Symptom:** BRAKE LIGHT SPEED CONTROL INOP  
**Fix:** **Causal Component :** --  
**Condition Code:**  
**Hotliner:** NGARCI32 **Phone:** 313 248-8202 **Regn Cd:** C4 Kansas City  
**Engineering:** **Phone:** **TAR:**  
**Dlr Contact:** AARON KING **Phone:** 000 000-0000 **Title Cde:** T

**DTCs:**  
KOEO:C0040  
KOEC:  
KOER:

**Comments**  
:

**REPAIR** 01/28/2011 01:18PM NOEL GARCIA MSS - FCSD - TECH SVC HOTLINE  
WEB FORM DATA - CONCERN: CRUISE INOP / BRAKE LIGHTS STAY  
ON DIAGNOSTICS: RAN OASIS, SELF TESTED PARTS REPLACED::  
NONE TECH QUESTION: SEEMS LIKE THERE IS ALOT OF MOVEMENT IN BRAKE  
PEDAL, HAVE ANY REPORTS ON THIS? WERE YOU ABLE TO VERIFY THE  
CONCERN? YES IS THERE AN APPROPRIATE PINPOINT TEST IN THE WSM FOR  
THIS CONCERN? WAS THE PINPOINT TEST FOLLOWED?

**RECOMM** 01/28/2011 01:18PM NOEL GARCIA MSS - FCSD - TECH SVC HOTLINE  
HELLO AARON, THE TECHNICAL HOTLINE HAS NOT SEEN ANY SIMILAR REPORTS  
FOR ISSUES WITH BRAKE PEDAL MOVEMENT. IT IS RECOMMENDED TO COMPARE  
THE BRAKE PEDAL MOVEMENT TO ANOTHER SIMILAR VEHICLE TO VERIFY IF  
THIS  
IS A NORMAL CHARACTERISTIC. IT IS RECOMMENDED TO FOLLOW DIAGNOSTIC  
ROUTINE E IN SECTION 06 OF THE WORKSHOP MANUAL TO BEGIN  
DIAGNOSIS. THANK YOU.

---

---

**From:** Jackson, Bradley (B.G.)  
**Sent:** Saturday, April 21, 2012 12:06 PM  
**To:** Napoli, Laura (L.); Flanagan, Thomas (T.P.); Surella, Matthew (M.M.)  
**Cc:** Estes, Eric (E.E.); Farmer, Marty (M.F.)  
**Subject:** FW: 2011 EXP/[redacted] CHASSIS - Report Summary(s) from a GCQIS Query Disposition

Note [redacted] EPAS concern in first report below.

Also, you get a feel for what is in the field by seeing the other C200D reports below. This is just from today's CQIS download.

Brad

This email contains 9 report summary(s).

Redacted for Relevance



Redacted for Relevance

Attachments : 0

---

<b>Report# :</b>	CDTEI003 NHL	<b>Received:</b>	04/20/2012
<b>CCRG/EPRC:</b>		<b>Date:</b>	
<b>Vehicle:</b>	2011,EXPLORER 4X4 (U502) ,LIMITED,4 DOOR ,MPV ,1FMHK8F88BG [REDACTED]	<b>Build Date:</b>	04/04/2011
<b>Odometer :</b>	5,096 M	<b>Engine:</b>	3.5L CYCLO
<b>Transmission:</b>	6F55	<b>Axle:</b>	
<b>Dealer:</b>	USA 00429 Townsend Ford	<b>Calibration:</b>	BUB1ST0A
<b>City:</b>	Tuscaloosa	<b>A/C:</b>	YES
<b>Originator:</b>	TECHNICIAN	<b>Phone#:</b>	(205) 752- 0401
<b>Symptom:</b>	6 62 4 39 SP/ST/RD,STEER/STER WHL,PERFORMANCE,INTERMITTENT		
<b>Status:</b>			

VFG: V87 STEERING  
Additional Symptom: LOSS OF STEERING ASSIST  
Fix: Causal Component : --  
Condition Code:

Hotliner: TWATERS Phone: 313 317-9366 Regn Cd: S1 Atlanta  
Engineering: Phone: TAR:  
Dlr Contact: Phone: Title Cde: T

DTCs:  
KOEO:  
KOEC:  
KOER:

**Comments**

:  
REPAIR 04/20/2012 02:33PM TROY WATERS MSS - FCSD - TECH SVC HOTLINE  
WEB FORM DATA - CONCERN:AT TIMES CAR WILL LOOSE POWER STEERING, CAN  
PULL OVER, TURN CAR OFF AND WHEN START IT BACK THE STEERING IS  
FINE DIAGNOSTICS: USED IDS, CHECKED AND HAD NO CODES FOR ELECTRIC  
STEER. PARTS REPLACED:NONE TECH QUESTION:HAVE YOU SEEN THIS  
PROBLEM WITH ANY OTHER EXPLORERS. DO YOU KNOW WHAT ELSE I CAN  
CHECK.  
THANKS  
RECOMM 04/20/2012 02:33PM TROY WATERS MSS - FCSD - TECH SVC HOTLINE  
IF THE CONCERN CAN BE DUPLICATED PLEASE PREFORM THE ON DEMAND TEST  
OF  
THE ABS AND PSCM TO BE SURE THERE ARE NO COMMUNICATION CODES  
STATING A  
COMMUNICATION LOSS. IF DTCS ARE RETRIEVED PLEASE PREFORM THE  
INTERACTIVE DIAGNOSIS LOCATED IN THE WORKSHOP MANUAL 211-00 AND  
DIAGNOSE ACCORDINGLY. IF NO DTCS ARE FOUND AND AND THE CONCERN IS  
PRESENT, VERIFY THE POWER AND GROUNDS TO PSCM. IF THESE CIRCUITS  
PROVE  
OUT REPLACE THE STEERING GEAR AND RETEST FOR CORRECT OPERATION.  
ADD-ON 04/20/2012 02:33PM TROY WATERS MSS - FCSD - TECH SVC HOTLINE  
( CONSULTED KIRK HENDERSON )

---

Attachments : 0

Report# : CDTFB001 NHL Received: 04/20/2012

**CCRG/EPRC:** **Reviewed Status:** **Date:**  
**Vehicle:** 2011,EXPLORER 4X4 (U502) ,XLT ,4 DOOR ,MPV **Build Date:** 04/12/2011  
,1FMHK8D87BG [REDACTED]  
**Odometer :** 14,093 M **Engine:** 3.5L **Calibration:** BUB1SN0A  
CYCLO  
**Transmission:** 6F50 **Axle:** **A/C:** YES  
**Dealer:** USA 03717 Crown Ford, Inc. **Phone#:** (516) 599-0600  
**City:** Lynbrook **State:** New York **Country :** USA  
York  
**Originator:** MARK DASCHER  
**Symptom:** 6 62 4 28 SP/ST/RD,STEER/STER WHL,PERFORMANCE,EXCESS EFFORT  
**Status:**  
**VFG:** V87 STEERING  
**Additional Symptom:** C200D  
**Fix:** **Causal Component :** --  
**Condition Code:**

**Hotliner:** BWRIGH77 **Phone:** 313 317-7040 **Regn Cd:** N1 New York  
**Engineering:** **Phone:** **TAR:**  
**Dlr Contact:** MARK DASCHER **Phone:** 000 000-0000 **Title Cde:** T

**DTCs:**  
KOEO:C1B00 C200D:49  
KOEC:  
KOER:

**Comments**  
:

**REPAIR** 04/20/2012 03:52PM BRANDON WRIGHT MSS - FCSD - TECH SVC HOTLINE  
WEB FORM DATA - CONCERN:CUSTOMER STATES WHILE DRIVING LOST  
STEERING  
NEEDED TO TURN OFF AND RESTART TO GET STEERING BACK HAPPENED A FEW  
TIMES. CUSTOMER ALSO STATES THAT WHILE DRIVING IN MESSAGE CENTER OIL  
PRESSURE OIL CAME ON DIAGNOSTICS: SCANNED FOR CODES AND RAN OASIS  
CONCERNS PARTS REPLACED:NONE TECH QUESTION:THE CONCERN IS NOT  
PRESENT AT THIS TIME. HAVE YOU HEARD OF THIS CONDITION BEFORE, AND  
SHOULD I JUST GO AHEAD AND REPLACE THE EPAS RACK  
**RECOMM** 04/20/2012 03:52PM BRANDON WRIGHT MSS - FCSD - TECH SVC HOTLINE  
MARK, YOU ARE CORRECT TO BELIEVE THAT PSCM REPLACEMENT WILL  
RESOLVE  
THIS CONCERN. PRIOR TO REPLACEMENT OF THE PSCM, RECOMMEND TO VERIFY  
POWER AND GROUND BY LOAD TEST AS WELL AS INSPECT THE PSCM

CONNECTOR

FOR PROPER PIN FIT OR PUSHED OUT PINS USING FLEX PROBES. IF NO CIRCUIT OR CONNECTOR FAULTS ARE FOUND, REPLACE THE PSCM AND RETEST.

Attachments : 0

<b>Report# :</b>	CDTEE003 NHL	<b>Received:</b>	04/20/2012
<b>CCRG/EPRC:</b>		<b>Date:</b>	
<b>Vehicle:</b>	2011,EXPLORER 4X2 (U502) ,LIMITED,4 DOOR ,MPV ,1FMHK7F88BG [REDACTED]	<b>Build Date:</b>	03/31/2011
<b>Odometer :</b>	17,819 M	<b>Engine:</b>	3.5L CYCLO
<b>Transmission:</b>	6F55	<b>Axle:</b>	
<b>Dealer:</b>	USA 04888 Santa Fe Ford, Inc.	<b>Calibration:</b>	BUB1ST0A
<b>City:</b>	Alachua	<b>A/C:</b>	YES
<b>State:</b>	Florida	<b>Phone#:</b>	(386) 462- 2802
<b>Country :</b>	USA	<b>Originator:</b>	KEVIN SHICK
<b>Symptom:</b>	6 62 4 39 SP/ST/RD,STEER/STER WHL,PERFORMANCE,INTERMITTENT		
<b>Status:</b>			
<b>VFG:</b>	V87 STEERING		
<b>Additional Symptom:</b>	LOSS OF ASSIST AND C200D:49		
<b>Fix:</b>	<b>Causal Component :</b>	--	
<b>Condition Code:</b>			
<b>Hotliner:</b>	JWIBERG5	<b>Phone:</b>	313 317-6313
<b>Engineering:</b>		<b>Regn Cd:</b>	S3 Orlando
<b>Dlr Contact:</b>	KEVIN SHICK	<b>Phone:</b>	000 000-0000
		<b>TAR:</b>	
		<b>Title Cde:</b>	T

**DTCs:**

KOEO:  
KOEC:  
KOER:

**Comments**

REPAIR 04/20/2012 02:21PM JAMES WIBERG MSS - FCSD - TECH SVC HOTLINE  
 WEB FORM DATA - CONCERN:CUST COMPLAIT OF NO POWER STEERING  
 INTERMITTANTLY. DIAGNOSTICS: EEC TESTS, C-200D ONLY DTC. PERF  
 P.P.TEST B IN STEERING SECTION. PASSES TESTS DID NOT DUPLICATE CONCERN  
 ON ROAD TESTS, DTC DID NOT RESET YET. PARTS REPLACED:NONE

YET TECH QUESTION:CUST HAS BEEN IN THREE TIMES FOR THIS CONCERN( FRONT END TECH HAS BEEN WORKING ON IT), AND HAS NOT FIXED PROBLEM.I HAVE CLEARED DTCS AND I AM PLANNING ON DRIVING UNTIL I GET IT TO ACT UP. I AM WONDERING IF THERE HAVE BEEN ANY SIMILAR REPORTS OF THIS CONCERN?

**RECOMM 04/20/2012 02:21PM JAMES WIBERG MSS - FCSD - TECH SVC HOTLINE**

KEVIN, THE HOTLINE HAS SEEN SEVERAL REPORTS OF THIS CONDITION WITH 2011 EXPLORERS WHERE THE EPAS LOOSES ASSIST INTERMITTENTLY AND SET A C200D IN THE PSCM. THIS CONDITION IS CAUSED BY A MALFUNCTIONING EPAS GEAR. RECOMMEND TESTING POWER AND GROUND INPUTS TO THE EPAS GEAR AND

INSPECTING CONNECTIONS TO EPAS FOR THE PRESENCE OF CORROSION OR POOR PIN FIT,IF FOUND CORRECT THESE ISSUES FIRST. IF NO CONNECTION ISSUES ARE FOUND AND ALL INPUTS ARE GOOD, REPLACE THE EPAS GEAR AND RE-EVALUATE THE CUSTOMERS CONCERN. ISM 11-08-019 LOSS OF POWER STEERING ASSIST WITH C200D IN PSCM

---

Redacted for Relevance

Redacted for Relevance

Attachments : 0

---

<b>Report# :</b>	CDTEG008 NHL	<b>Received:</b>	04/20/2012
<b>CCRG/EPRC:</b>		<b>Reviewed Status:</b>	<b>Date:</b>
<b>Vehicle:</b>	2012,EXPLORER 4X2 (U502) ,XLT ,4 DOOR ,MPV ,1FMHK7D8XCG [REDACTED]	<b>Build Date:</b>	09/20/2011
<b>Odometer :</b>	8,586 M	<b>Engine:</b>	3.5L CYCLO
<b>Transmission:</b>	6F55	<b>Axle:</b>	<b>Calibration:</b> CUB1ST0A
<b>Dealer:</b>	USA 06684 Riggins Motor Company	<b>A/C:</b>	YES
<b>City:</b>	Poquoson	<b>Phone#:</b>	(757) 868- 6777
<b>Originator:</b>	LARRY GRAHAM	<b>State:</b>	Virginia
<b>Symptom:</b>	6 62 0 00 SP/ST/RD,STEER/STER WHL,UNKNOWN,UNKNOWN		
<b>Status:</b>			
<b>VFG:</b>	V89 RIDE & HANDLING		

**Additional Symptom:** LOSS OF ASSIST

**Fix:** Causal Component : --

**Condition Code:**

**Hotliner:** JBOALES                      **Phone:** 000 317-9341                      **Regn Cd:** N4 Washington

**Engineering:**    **Phone:**    **TAR:**

**Dlr Contact:** LARRY GRAHAM                      **Phone:** 000 000-0000                      **Title Cde:** T

**DTCs:**

KOEO:C200D:49 C1B00:86

KOEC:

KOER:

**Comments**

:

**REPAIR**    04/20/2012 03:30PM JEFFREY BOALES MSS - FCSD - TECH SVC HOTLINE  
WEB FORM DATA - CONCERN:CUSTOMER STATES THAT WHILE DRIVING AROUND  
25  
MPH , LOST POWER STEERING AND POWER STEERING FAULT LIGHT CAME ON  
AND  
SERVICE ADVANCE TRAC LIGHT CAME ON. DIAGNOSTICS: RETRIEVED DTCS  
C200D-49 AND C1B00-86. PER FORMED PINPOINT TEST B IN WSM MANUAL FOR  
EPAS SYSTEM. TEST RESULTS CONCLUDED THAT EPAS ASSEMBLY WAS AT  
FAULT. PARTS REPLACED:NONE TECH QUESTION:CUSTOMER REFUSES TO  
DRIVE THE VEHICLE AT THIS POINT...BASED ON OUR TEST FINDINGS THAT THE  
EPAS (3504) ASSY IS AT FAULT. ARE WE CORRECT TO ASSUME THAT WE NEED TO  
REPLACE THIS UNIT ASSY? HAVE THERE BEEN ANY OTHER REPORTS OF THIS  
CONCERN? CUSTOMER STATES HE FOUND A VEHICLE IN CALIFORNIA THAT HAD  
THE  
SAME CONCERN, BUT COULD NOT FIND ANY TEST RESULTS TO BACK  
REPLACEMENT  
OF ANY PARTS). WE HAVE PROVIDED THE CUSTOMER A LOANER VEHICLE. WE  
WOULD APPRECIATE INPUT REGARDING THIS CONCERN.

**RECOMM** 04/20/2012 03:30PM JEFFREY BOALES MSS - FCSD - TECH SVC HOTLINE  
LARRY, BASED ON THE C200D DTC, YOU ARE CORRECT IN BELIEVING THE  
STEERING GEAR IS AT FAULT. IT IS RECOMMENDED THAT YOU REPLACE THE  
EPAS  
STEERING GEAR AT THIS TIME. THERE ARE MULTIPLE REPORTS OF A STEERING  
GEAR FAILURE CAUSING THIS CONCERN AND THE C200D DTC. ONCE REPLACED,  
RE-EVALUATE THE CONCERN.ISM 11-08-019 LOSS OF POWER STEERING ASSIST  
WITH C200D IN PSCM

Attachments : 0

**Report# :** CDTEG011 NHL **Received:** 04/20/2012  
**CCRG/EPRC:** **Reviewed Status:** **Date:**  
**Vehicle:** 2012,EXPLORER 4X2 (U502) ,XLT ,4 DOOR ,MPV **Build Date:** 08/01/2011  
,1FMHK7D8XCG [REDACTED]  
**Odometer :** 7,503 M **Engine:** 3.5L **Calibration:** CUB1ST0A  
CYCLO  
**Transmission:** 6F55 **Axle:** **A/C:** YES  
**Dealer:** USA 06633 Cavalier Ford Lincoln **Phone#:** (757) 424-  
1111  
**City:** Chesapeake **State:** Virginia **Country :** USA  
**Originator:** STEVE BEASLEY  
**Symptom:** 6 62 3 81 SP/ST/RD,STEER/STER WHL,FEEL/WAN/PULL,RIGHT  
**Status:**  
**VFG:** V87 STEERING  
**Additional Symptom:** TORQUE STEER  
**Fix:** **Causal Component :** --  
**Condition Code:**  
**Hotliner:** JBOALES **Phone:** 000 317-9341 **Regn Cd:** N4 Washington  
**Engineering:** **Phone:** **TAR:**  
**Dlr Contact:** STEVE BEASLEY **Phone:** 000 000-0000 **Title Cde:** T

**DTCs:**

KOEO:

KOEC:

KOER:

**Comments**

:

**REPAIR** 04/20/2012 04:05PM JEFFREY BOALES MSS - FCSD - TECH SVC HOTLINE  
WEB FORM DATA - CONCERN:VEHICLE HAS TORQUE STERRING CONDITION .  
PULLS  
TO RIGHT UNDER MODERATE AND HEAVY ACCELAERATION DIAGNOSTICS:  
VISUAL  
INSP FOR DAMAGE . TIRE PRESSURES OK . NO DAMGE . PRESSURES OK.  
INTERMEDIATE AXLE SUPPORT OK . ENGINE MOUNTS OK , FRAME TO BODY  
MOUNTS  
OK . PARTS REPLACED:NONE TECH QUESTION:ARE THERE ANY KNOWN  
CONCERNS FOR THIS CONDITION IN THIS MODEL . UPDATED MOUNTS ?  
**RECOMM** 04/20/2012 04:05PM JEFFREY BOALES MSS - FCSD - TECH SVC HOTLINE



STEVE, THERE ARE NO UPDATED MOUNTS FOR THIS VEHICLE TO RESOLVE THIS ISSUE. HOWEVER, THERE HAVE BEEN REPORTS OF TORQUE STEER ON THIS VEHICLE. BEGIN BY PERFORMING THE POWERTRAIN/DRIVETRAIN MOUNT NEUTRALIZATION PROCEDURE. THIS PROCEDURE IS FOUND IN SECTION 303-00 OF THE ONLINE WSM. NEXT PERFORM PINPOINT TEST A IN SECTION 204-00 OF THE ONLINE WSM. PERFORM STEPS A1-A4. THIS IS FOR A STEADY STATE DRIFT/PULL CONCERN, BUT ALSO HELPS DIAGNOSE TORQUE STEER ISSUES. MEASURE THE FRONT SUSPENSION ALIGNMENT, ESPECIALLY FRONT CROSS CAMBER (LEFT MINUS RIGHT). IF THE FRONT CROSS CAMBER IS GREATER THAN +.3 DEGREES, ROTATE THE R/F UPPER STRUT MOUNT SO CHANGE THE ADJUSTMENT. THE FINAL CROSS CAMBER SHOULD BE NO LESS THAN -.3 DEGREES. REGARDLESS OF FRONT CROSS CAMBER, ADJUST THE FRONT TOES NEXT. ONCE THE FRONT TOES HAS BEEN ADJUSTED, TEST DRIVE THE VEHICLE.-----ISM 11-11-008 2011-2012 EXPLORER TORQUE STEER

**Attachments :** 0

<b>Report# :</b>	CDTB4015 NHL	<b>Received:</b>	04/20/2012
<b>CCRG/EPRC:</b>		<b>Reviewed Status:</b>	<b>Date:</b>
<b>Vehicle:</b>	2012,EXPLORER 4X2 (U502) ,XLT ,4 DOOR ,MPV ,1FMHK7D95CG [REDACTED]	<b>Build Date:</b>	09/21/2011
<b>Odometer :</b>	6,751 M	<b>Engine:</b>	2.0L GTDI
<b>Transmission:</b>	6SP 6F MID	<b>Axle:</b>	
<b>Dealer:</b>	USA 03381 Marysville Ford	<b>Calibration:</b>	CUB1F40A
<b>City:</b>	Marysville	<b>A/C:</b>	YES
<b>Originator:</b>	CHRIS WILLIAMSON	<b>State:</b>	Washington
<b>Symptom:</b>	6 62 4 28 SP/ST/RD,STEER/STER WHL,PERFORMANCE,EXCESS EFFORT	<b>Country :</b>	USA
<b>Status:</b>		<b>Phone#:</b>	(360) 659-4000
<b>VFG:</b>	V87 STEERING		
<b>Additional Symptom:</b>	LOSS OF ASSIST C200D		
<b>Fix:</b>	<b>Causal Component :</b>		--
<b>Condition Code:</b>			
<b>Hotliner:</b>	JBOALES	<b>Phone:</b>	000 317-9341
<b>Engineering:</b>		<b>Regn Cd:</b>	W5 Seattle
<b>Dlr Contact:</b>	CHRIS WILLIAMSON	<b>Phone:</b>	000 000-0000
		<b>TAR:</b>	
		<b>Title Cde:</b>	T

**DTCs:**

KOEO:C200D C1B00 U0131

KOEC:

KOER:

**Comments**

:

**REPAIR** 04/20/2012 12:13PM JEFFREY BOALES MSS - FCSD - TECH SVC HOTLINE  
WEB FORM DATA - CONCERN:CUSTOMER STATES POWER ASSIST WARNING AND  
LOOSES POWER STEERING ASSIST CUSTOMER STATED IT IS UNSAFE TO DRIVE  
WHEN THIS HAPPENS. DIAGNOSTICS: RAN PINPOINT TESTS FOR CODES PASSES  
AT THIS TIME. PARTS REPLACED:NOTHING YET TECH QUESTION:LOOKING  
FOR ANY KNOWN CONCERNS AT THIS TIME.

**RECOMM** 04/20/2012 12:13PM JEFFREY BOALES MSS - FCSD - TECH SVC HOTLINE  
CHRIS, THE C200D DTC INDICATES A STEERING GEAR FAULT. IT IS  
RECOMMENDED THAT YOU PLACE THE PSCM/EPAS STEERING GEAR AT THIS  
TIME.  
CLEAR THE DTCS AND RE-EVALUATE THE CONCERN. ISM 11-08-019 LOSS OF  
POWER STEERING ASSIST WITH C200D IN PSCM

---

Redacted for Relevance

Redacted for Relevance

---

**From:** Surella, Matthew (M.M.)  
**Sent:** Tuesday, July 10, 2012 9:09 AM  
**To:** Napoli, Laura (L.); Perri, Ron (R.J.)  
**Cc:** Pasquarella, Michael (M.S.)  
**Subject:** FW: Explorer EPAS/ABS Engineering Review at Discovery Ford

Laura,

I forgot to mention yesterday that Transport Canada has identified a complaint vehicle in Burlington, Ontario. The proposal from yesterday's meeting was to send an ABS engineer and an EPAS engineer to this dealership in Canada (4 hour drive). Can you check the code and let us know the details? Ron can then engage the ABS folks once he has a little more info.

Matthew (Matt) Surella  
Steering EPAS Supervisor / MBB  
313-805-3997

---

**From:** Williams, Trevor (T.G.)  
**Sent:** Monday, July 09, 2012 2:01 PM  
**To:** Surella, Matthew (M.M.)  
**Cc:** Setili, Frank (F.E.); Matckars, Vic (V.A.); Hotrum, Erin (E.M.)  
**Subject:** Explorer EPAS/ABS Engineering Review at Discovery Ford

Matt:

Vic Matckars, Ford Canada Technical Service Specialist (FCSD) is the contact for an engineering review of the Transport Canada compliant vehicle that is at Discovery Ford, in Burlington, Ontario.  
CDIS ID: VMATCKAR Ford net phone#: 9-1-853-1575

The customer has been in a rental vehicle since last Thursday so please prioritize the visit.

The engineers should be cautioned to state that the purpose of their visit to Canada is to attend a meeting related to a Transport Canada defect investigation. Canada Border Service Agency has been known to deny entry to US employees who's response indicates he/she is working in Canada.

Copy of the CQIS hotline report is attached.



Report Summary  
for the CQIS Re...

Thanks

*Trevor G. Williams*  
Manager, Vehicle Safety  
Environment, Energy & Vehicle Safety  
Ford of Canada

Canadian Head Quarters Bldg, Office 625  
(905) 845-2511, ext 1145  
Dial net: 9-1-853-1145  
[twillia4@ford.com](mailto:twillia4@ford.com)

---

**From:** Napoli, Laura (L.)  
**Sent:** Saturday, January 29, 2011 4:58 PM  
**To:** Jackson, Bradley (B.G.); Anderson, Eric (H.)  
**Cc:** Mrozek, Robert (R.M.)  
**Subject:** FW: FW: 2011 EXP/[REDACTED] CHASSIS - Report Summary(s) from a GCQIS Query Disposition

The gear will be delivered to the dealership Sunday at 1. Sales is open from 1-5 and can receive the gear. I'll call them tomorrow to let them know it's coming.

Then I'll call the service manager Mon to see when he can get the gear to 26 mile.

---

**From:** Pat Messer [mailto:Pat.Messer@TRW.COM]  
**Sent:** Saturday, January 29, 2011 4:53 PM  
**To:** Napoli, Laura (L.); Greg Austin; Gregory Sheets  
**Cc:** Estes, Eric (E.E.); Mrozek, Robert (R.M.)  
**Subject:** Re: FW: 2011 EXP/[REDACTED] CHASSIS - Report Summary(s) from a GCQIS Query Disposition

Laura,

We have contracted a courier to deliver this gear to the dealership listed by 1:00 p.m. tomorrow. We will be sending a BB53-3200-BG gear as this is current revision level.

If there are any issues with this, please let us know.

Thank you,

Pat Messer  
Plant Manager  
TRW - Marion Plant  
Office: 276-783-1261  
Cell: 276-759-9120  
e-mail: pat.messer@trw.com

>>> "Napoli, Laura (L.)" <lnapoli@ford.com> 1/29/2011 1:47 PM >>>  
Greg,

The part number for the gear I need is BB53-3200-BE. The dealership is open today until 4. Tomorrow the sales department is there from 1-5, so if the gear can be driven to the dealership tomorrow, the sales department can receive it and get it to the service area so they can begin pulling the gear first thing in the morning. Please let me know how Marion can support expediting this gear.

The dealership is:

I-77 Ford  
HC80 Box 71B

(on Route 21 exit 132)  
Ripley, WV 25271  
(304) 372-2480  
<http://i77fordmercury.dealerconnection.com/?lang=en>

Regards,

*Laura Napoli*

U502 EPAS  
Ford Motor Company  
Cube: 2B-G66 PDC  
Phone: 313.323.0634  
Mobile: 313.805.0482

---

**From:** Jackson, Bradley (B.G.)  
**Sent:** Saturday, January 29, 2011 12:36 PM  
**To:** Anderson, Eric (H.); Napoli, Laura (L.); Mrozek, Robert (R.M.)  
**Subject:** FW: 2011 EXP/[REDACTED] CHASSIS - Report Summary(s) from a GCQIS Query Disposition

[note p/s inop claim from w. virginia dealer below.....1st report.](#)

brad

---

**From:** SBUELOW [mailto:SBUELOW]  
**Sent:** Saturday, January 29, 2011 11:29 AM  
**To:** BJACKSON  
**Subject:** 2011 EXP/[REDACTED] CHASSIS - Report Summary(s) from a GCQIS Query Disposition

This email contains 2 report summary(s).

**Attachments :** 0

<b>Report# :</b>	BA2AK005 NHL	<b>Received:</b>	01/28/2011
<b>CCRG/EPRC:</b>		<b>Date:</b>	
<b>Vehicle:</b>	2011,EXPLORER 4X4 (U502),4 DOOR ,MP,1FMHK8D83BG [REDACTED]	<b>Build Date:</b>	01/12/2011
<b>Odometer :</b>	12 M	<b>Engine:</b>	3.5L CYCLO
<b>Transmission:</b>	6F55	<b>Axle:</b>	
<b>Dealer:</b>	USA 02071 I77 Ford Mercury	<b>Calibration:</b>	BUB1ST0A
<b>City:</b>	Ripley	<b>A/C:</b>	YES
<b>State:</b>		<b>Phone#:</b>	(304) 372- 2480
<b>Originator:</b>	JOHNATHAN FRYE	<b>Country :</b>	USA
<b>Symptom:</b>	3 03 1 50 CHASS.,STRG/HANDLING ,FUNCTION,HIGH EFFORT		
<b>Status:</b>			
<b>VFG:</b>	V87 STEERING		
<b>Additional</b>	POWER STEERING INOP		

**Symptom:**

**Fix:** Causal Component : --

**Condition Code:**

**Hotliner:** IWRIGH24 **Phone:** 313 317-4284 **Regn Cd:** G3 Cincinnati

**Engineering:** **Phone:** **TAR:**

**Dlr Contact:** JOHNATHAN FRYE **Phone:** 304 372-3673 **Title Cde:** SM

**DTCs:**

KOEO:U3000

KOEC:

KOER:

**Comments**

:

**REPAIR** 01/28/2011 08:35AM IAN WRIGHT MSS - FCSD - TECH SVC HOTLINE  
WEB FORM DATA - CONCERN: POWER STEERING IS INOP DIAGNOSTICS: KOEO  
KOER PINPOINT TEST C1 PARTS REPLACED:: NO AT THIS TIME TECH  
QUESTION: ANY KNOWN CONCERNS WITH STEERING RACK WERE YOU ABLE TO  
VERIFY THE CONCERN? YES IS THERE AN APPROPRIATE PINPOINT TEST IN  
THE WSM FOR THIS CONCERN? YES WAS THE PINPOINT TEST FOLLOWED? YES

**RECOMM** 01/28/2011 08:35AM IAN WRIGHT MSS - FCSD - TECH SVC HOTLINE  
JONATHAN. INSPECT CONNECTOR PIN FITS TO THE PSCM. WE HAVE SEEN SOME  
CONCERNS DUE TO SPREAD PINS AT CONNECTOR C139. INSPECT THIS  
CONNECTION  
USING A FLEX PROBE AND REPAIR/REPLACE ANY LOOSE PINS. PERFORM THE  
INTERACTIVE DIAGNOSTICS FOR FURTHER ASSISTANCE DIAGNOSING THIS  
CONCERN. TO PERFORM THE DIAGNOSTICS. CONNECT IDS TO VEHICLE AND GO  
TO  
THE PTS WEB PAGE. OPEN THE ONLINE WORKSHOP MANUAL OPEN SECTION 211-  
00  
AND SELECT DTC CHART INTERACTIVE DIAGNOSTICS.

**Attachments : 0**

<b>Report# :</b>	BA2AL015 NHL	<b>Received:</b>	01/28/2011
<b>CCRG/EPRC:</b>		<b>Date:</b>	
<b>Vehicle:</b>	2011,EXPLORER 4X4 (U502),4 DOOR ,MP,1FMHK8F89BG [REDACTED]	<b>Build Date:</b>	11/19/2010
<b>Odometer :</b>	1,331 M	<b>Engine:</b>	3.5L CYCLO
<b>Transmission:</b>	6F55	<b>Axle:</b>	<b>Calibration:</b> BUB1ST0A
			<b>A/C:</b> YES



**Dealer:** USA 09568 Stivers Ford Lincoln Mercury **Phone#:** (515) 987-3697  
**City:** Waukee **State:** Iowa **Country :** USA  
**Originator:** AARON KING  
**Symptom:** 3 01 A 01 CHASS.,SERVICE BRAKE ,INDICATOR,RED ONLY  
**Status:**  
**VFG:** V21 BRAKING  
**Additional Symptom:** BRAKE LIGHT SPEED CONTROL INOP  
**Fix:** **Causal Component :** --  
**Condition Code:**

**Hotliner:** NGARCI32 **Phone:** 313 248-8202 **Regn Cd:** C4 Kansas City

**Engineering:** **Phone:** **TAR:**

**Dlr Contact:** AARON KING **Phone:** 000 000-0000 **Title Cde:** T

**DTCs:**

KOEO:C0040

KOEC:

KOER:

**Comments**

:

**REPAIR** 01/28/2011 01:18PM NOEL GARCIA MSS - FCSD - TECH SVC HOTLINE  
WEB FORM DATA - CONCERN: CRUISE INOP / BRAKE LIGHTS STAY  
ON DIAGNOSTICS: RAN OASIS, SELF TESTED PARTS REPLACED::  
NONE TECH QUESTION: SEEMS LIKE THERE IS ALOT OF MOVEMENT IN BRAKE  
PEDAL, HAVE ANY REPORTS ON THIS? WERE YOU ABLE TO VERIFY THE  
CONCERN? YES IS THERE AN APPROPRIATE PINPOINT TEST IN THE WSM FOR  
THIS CONCERN? WAS THE PINPOINT TEST FOLLOWED?

**RECOMM** 01/28/2011 01:18PM NOEL GARCIA MSS - FCSD - TECH SVC HOTLINE  
HELLO AARON, THE TECHNICAL HOTLINE HAS NOT SEEN ANY SIMILAR REPORTS  
FOR ISSUES WITH BRAKE PEDAL MOVEMENT. IT IS RECOMMENDED TO COMPARE  
THE BRAKE PEDAL MOVEMENT TO ANOTHER SIMILAR VEHICLE TO VERIFY IF  
THIS  
IS A NORMAL CHARACTERISTIC. IT IS RECOMMENDED TO FOLLOW DIAGNOSTIC  
ROUTINE E IN SECTION 06 OF THE WORKSHOP MANUAL TO BEGIN  
DIAGNOSIS. THANK YOU.

---

**From:** Napoli, Laura (L.)  
**Sent:** Tuesday, May 24, 2011 11:34 AM  
**To:** Estes, Eric (E.E.)  
**Subject:** FW: STEERING V87 ALL 09-10 - Report Summary(s) from a GCQIS Query Disposition

Good summary from Eric Anderson on our recent claims...

---

**From:** Anderson, Eric (H.)  
**Sent:** Tuesday, May 24, 2011 10:50 AM  
**To:** Buelow, Steve (S.E.)  
**Cc:** Napoli, Laura (L.)  
**Subject:** FW: STEERING V87 ALL 09-10 - Report Summary(s) from a GCQIS Query Disposition

Hi Steve:

FYI. V87 is working on all the ECB and CQIS for EPAS. Here's an update on the recently received CQIS claims:

BGA36413 build date 3/3/11 no DTC codes, wiring problem probable  
BGA27891 build date 2/18/11 C1B00, U0131 indicate wiring problem  
BGA61636 build date 5/3/11 U0131 and tech interview indicate wiring problem  
BGA64725 build date 5/9/11 C1B00 and U0131 codes indicate wiring problem  
BGA15758 build date 1/19/11 C200D is a known and cut-off internal EPAS problem

Thanks,

Eric

---

**From:** Napoli, Laura (L.)  
**Sent:** Tuesday, May 24, 2011 9:40 AM  
**To:** Annadi, Hari (H.); Mrozek, Robert (R.M.)  
**Cc:** Anderson, Eric (H.); Estes, Eric (E.E.)  
**Subject:** RE: STEERING V87 ALL 09-10 - Report Summary(s) from a GCQIS Query Disposition

Eric A,

Can you please make sure Steve is aware that we're working on all EPAS claims and the new findings is that we have a new wiring problem?

---

**From:** Annadi, Hari (H.)  
**Sent:** Tuesday, May 24, 2011 7:54 AM  
**To:** Mrozek, Robert (R.M.); Napoli, Laura (L.)  
**Cc:** Anderson, Eric (H.); Estes, Eric (E.E.)  
**Subject:** RE: STEERING V87 ALL 09-10 - Report Summary(s) from a GCQIS Query Disposition

Steve Beulow.

Pl read stapled note. Thanks.

**From:** Mrozek, Robert (R.M.)  
**Sent:** Tuesday, May 24, 2011 7:47 AM  
**To:** Annadi, Hari (H.); Napoli, Laura (L.)  
**Cc:** Anderson, Eric (H.); Estes, Eric (E.E.)  
**Subject:** RE: STEERING V87 ALL 09-10 - Report Summary(s) from a GCQIS Query Disposition

Who is the plant FCSD person?

*Rob Mrozek*

Electric Power Steering Supervisor  
CD3/D3/D4/U502/Police/Limo EPAS Programs +  
Active Front Steering Applications Engineering  
Ford Motor Company  
Phone: (313) 805-5947  
e-mail: rmrozek@ford.com

---

**From:** Annadi, Hari (H.)  
**Sent:** Tuesday, May 24, 2011 7:45 AM  
**To:** Mrozek, Robert (R.M.); Napoli, Laura (L.)  
**Cc:** Anderson, Eric (H.); Estes, Eric (E.E.)  
**Subject:** RE: STEERING V87 ALL 09-10 - Report Summary(s) from a GCQIS Query Disposition

Understood. I did have a conversation with Laura about this yesterday. We need to communicate this to the FCSD rep in the plant so he does not open an Emerging concern with Chassis as the lead function. I am sure your team will be supporting Electrical to root cause.

---

**From:** Mrozek, Robert (R.M.)  
**Sent:** Tuesday, May 24, 2011 7:40 AM  
**To:** Annadi, Hari (H.); Napoli, Laura (L.)  
**Cc:** Anderson, Eric (H.); Estes, Eric (E.E.)  
**Subject:** RE: STEERING V87 ALL 09-10 - Report Summary(s) from a GCQIS Query Disposition

We get all these CQIS reports. Intermittent is typically an electrical issue and not related to EPAS. We design EPAS not to deliver assist intermittently. Due to severity of intermittent assist, we will completely pull assist. So this is likely a wiring/connection/grounding issue.

Laura is working with PVT on this one.

*Rob Mrozek*

Electric Power Steering Supervisor  
CD3/D3/D4/U502/Police/Limo EPAS Programs +  
Active Front Steering Applications Engineering  
Ford Motor Company  
Phone: (313) 805-5947  
e-mail: rmrozek@ford.com

---

**From:** Annadi, Hari (H.)  
**Sent:** Tuesday, May 24, 2011 7:34 AM  
**To:** Napoli, Laura (L.); Mrozek, Robert (R.M.)  
**Subject:** FW: STEERING V87 ALL 09-10 - Report Summary(s) from a GCQIS Query Disposition

[CQIS for intermittent loss of assist.](#)

---

**Attachments :** 0

**Report# :** BETBK025 NHL **Received:** 05/20/2011  
**CCRG/EPRC:** **Reviewed Status:** **Date:**  
**Vehicle:** 2011,EXPLORER 4X4 (U502),4 DOOR **Build Date:** 03/03/2011  
,MP,1FMHK8B8XBG [REDACTED]  
**Odometer :** 2,947 M **Engine:** 3.5L **Calibration:**  
CYCLO  
**Transmission:** 6F50 **Axle:** **A/C:** YES  
**Dealer:** USA 08305 Evergreen Ford **Phone#:** (425) 392-6900  
**City:** Issaquah **State:** Washington **Country :** USA  
**Originator:** JASON DESCHAMBAULT  
**Symptom:** 3 03 1 50 CHASS.,STRG/HANDLING ,FUNCTION,HIGH EFFORT  
**Status:**  
**VFG:** V87 STEERING  
**Additional Symptom:** INT. LOSS OF STEERING  
**Fix:** **Causal Component :** --  
**Condition Code:**

**Hotliner:** MHINDERE **Phone:** 000 337-9292 **Regn Cd:** W5 Seattle  
**Engineering:** **Phone:** **TAR:**  
**Dlr Contact:** JASON DESCHAMBAULT **Phone:** 425 392-6900 **Title Cde:** T

**DTCs:**  
KOEO:  
KOEC:  
KOER:

**Comments**

**:**  
REPAIR 05/20/2011 03:11PM MICHAEL HINDERER MSS - FCSD - TECH SVC HOTLINE  
WEB FORM DATA - CONCERN: CUSTOMER LOST STEERING ASSIST AT 35 MPH,  
DIDNT RETURN UNTILL ENGINE SHUT OFF AND RETSTARTED. DIAGNOSTICS:

CHECKED OASIS, CHECKED FOR DTCS PASS. PARTS REPLACED:: NONE TECH QUESTION: ROAD TESTED, UNABLE TO VERIFY CONCERN. ANY KNOWN CONCERNS? WERE YOU ABLE TO VERIFY THE CONCERN? NO IS THERE AN APPROPRIATE PINPOINT TEST IN THE WSM FOR THIS CONCERN? YES WAS THE PINPOINT TEST FOLLOWED? NO

**RECOMM 05/20/2011 03:11PM MICHAEL HINDERER MSS - FCSD - TECH SVC HOTLINE**  
JASON, TO ACTIVATE THE EPAS SYSTEM, A 12-VOLT HOT AT ALL TIMES AND A 12-VOLT IGNITION/RUN INPUT TO THE PSCM IS REQUIRED. THE PSCM THEN MONITORS THE HS-CAN TO DETERMINE IF THE VEHICLE IS OPERATING IN A MANNER CAPABLE OF SUPPORTING THE EPAS SYSTEM. THE PSCM USES INPUTS FROM VARIOUS MODULES OVER THE HS-CAN, THE STEERING TORQUE SENSOR AND THE MOTOR TO DETERMINE THE AMOUNT OR LEVEL OF ASSIST PROVIDED BY THE EPAS SYSTEM. INSPECT PINFIT AND CONNECTION AT THE PSCM. VERIFY THERE ARE NO CONCERNS WITH A LOSS OF POWER TO THE PSCM. GIVEN THE CONCERN IS INTERMITTENT, A CONNECTION CONCERN IS POSSIBLE.

---

---

**From:** Jackson, Bradley (B.G.)  
**Sent:** Monday, August 22, 2011 9:26 AM  
**To:** Estes, Eric (E.E.); Napoli, Laura (L.)  
**Cc:** Buelow, Steve (S.E.); Mrozek, Robert (R.M.)  
**Subject:** FW: Steering wheel lock up - 2011 Explorer

Per CQIS report below, there is a Ford employee's vehicle that has a C200D flagged on a 23 February 2011 build. This may be a good opportunity to see customer's vehicle before gear replacement. Also note the dealer states the employee will not take the U502 back because of this condition.

Brad

---

**From:** Buelow, Steve (S.E.)  
**Sent:** Monday, August 22, 2011 8:18 AM  
**To:** Jackson, Bradley (B.G.)  
**Subject:** FW: Steering wheel lock up - 2011 Explorer

Per our brief discussion.



Report Summary  
for the C200D Re...

**-The Customer Defines Quality-**

*Steve Buelow - Ford Motor Company*

FCSD Program Manager-  
Taurus/Taurus SHO/Lincoln MKS/Explorer  
Chicago Assembly PVT Office, COE  
773-646-7495 DialNet 686-7495  
Cell 773-726-0808 [sbuelow@ford.com](mailto:sbuelow@ford.com)

"Quality means doing it right when no one is looking." - Henry Ford

---

**From:** Buckman, Lynne (L.A.)  
**Sent:** Monday, August 22, 2011 7:48 AM  
**To:** Buelow, Steve (S.E.)  
**Cc:** Buckman, Lynne (L.A.)  
**Subject:** Steering wheel lock up - 2011 Explorer

Hi Steve

Here is the VIN # 1FMHK8D89BG [REDACTED] for the vehicle we discussed this morning.

Thanks

Lynne

PRIVILEGED AND CONFIDENTIAL

*Lynne Buckman*  
*Executive Liaison - CCGO*  
*Phone - 313-845-6232*  
*Fax - 866-626-8586*  
[lbuckman@ford.com](mailto:lbuckman@ford.com)

**From:** Buelow, Steve (S.E.)  
**Sent:** Monday, August 22, 2011 9:10 AM  
**To:** Buelow, Steve (S.E.)  
**Subject:** Report Summary for the CQIS Report#BHPD7005

**Attachments :** 0

**Report# :** BHPD7005 NHL  
**CCRG/EPRC:** **Reviewed Status:**  
**Vehicle:** 2011,EXPLORER 4X4 (U502) ,XLT ,4 DOOR ,MPV  
,1FMHK8D89BG [REDACTED] **Build Date:** 02/23/2011  
**Odometer :** 9,708 M **Engine:** 3.5L  
CYCLO **Calibration:** BUB1ST0A  
**Transmission:** 6F55 **Axle:** **A/C:** YES  
**Dealer:** USA 02890 Russ Milne Ford, Inc. **Phone#:** (586) 948-7700  
**City:** Macomb **State:** Michigan **Country :** USA  
**Originator:** JOHN BARBIAN  
**Symptom:** 2 27 2 68 AID/INFO,WNG IND/MESS/C,ADV TRAC,STAYS ON  
**Status:**  
**VFG:** V21 BRAKING  
**Additional Symptom:** ABS AND T/C LIGHTS ON  
**Fix:** **Causal Component :**  
**Condition Code:**

**Hotliner:** MABELA3 **Phone:** 000 248-9263 **Regn Cd:** G2 Detroit  
**Engineering:** **Phone:** **TAR:**  
**Dlr Contact:** JOHN BARBIAN **Phone:** 586 948-2572 **Title Cde:** SF

**DTCs:**

KOEO:C1B00:86-28 C200D:49-08

KOEC:

KOER:

**Comments**

:

REPAIR 08/16/2011 12:22PM MATT ABELA MSS - FCSD - TECH SVC HOTLINE  
WEB FORM DATA - CONCERN: ABS LIGHT AND TRAC CONTROL LIGHT CAME ON  
WHILE DRIVING AND STEERING WOULD NOT TURN ONLY WOULD TURN MAYBE  
20



DEGREES ALSO MESSAGE CENTER CAME UP WITH WARNING FOR 4X4  
SYSTEM DIAGNOSTICS: RETRIEVED CODES C1B00 86-28 ABS & C200D 49-08  
PSCM PARTS REPLACED:: NONE YET TECH QUESTION: FOLLOWED  
PINPOINT TEST PERFORMED TEST B3 TEST DRIVE AND RECHECKED NO CODES  
RETURNED PER PPT RETURN VEHICLE TO CUST. CUST VERY WORRIED ABOUT  
CONCERN STATED WAS UNABLE TO STEER VEHICLE BUT APPROX 20 DEG EITHER  
WAY WE COULD NOT DUPLICATE THIS COMPLAINT ARE THERE ANY OTHER  
KNOWN  
CONCERNS OR SUGGESTIONS OTHER THAN RETURNING VEHICLE BACK TO  
OWNER  
THANKS JOHN

**RECOMM 08/16/2011 12:22PM MATT ABELA MSS - FCSD - TECH SVC HOTLINE**

JOHN, IF YOU HAVE PERFORMED THE DRIVE CYCLE IN PINPOINT TEST B, STEP  
B3, AND THE CONCERN HAS NOT RECURRED, THIS SET OF DTC'S AND SYMPTOM  
MAY HAVE OCCURRED DUE TO IMPACT WITH A LARGE POTHOLE OR A CURB.  
LOOK

FOR POSSIBLE RASH ON THE SIDEWALLS OF THE RIMS AND OR TIRES. IF NO  
CONCERNS ARE NOTED AND IF PINPOINT TEST B HAS PASSED, NO FURTHER  
SERVICE ACTION IS ADVISED - PLEASE RELEASE THE VEHICLE TO YOUR  
CUSTOMER.

**REPAIR 08/16/2011 05:26PM IONET PUSTA MSS - FCSD - TECH SVC HOTLINE**

TECHNICIAN REPLY: CUST WILL NOT ACCEPT VEHICLE BACK IN CURRENT  
CONDITION WILL NOT RETUR RENTAL CAR HE WORKS AT FOMOCO & DOES NOT  
ACCEPT DIAGNOSIS ANY SUGGESTIONS

**RECOMM 08/16/2011 05:26PM IONET PUSTA MSS - FCSD - TECH SVC HOTLINE**

HELLO JOHN, TO BETTER ASSIST YOU ON THIS WARRANTY RELATED QUESTION,  
THE TECHNICAL SERVICE HOTLINE RECOMMENDS THAT YOU REFER TO THE  
DEALERSHIP WARRANTY ADMINISTRATOR, THE WARRANTY AND POLICY  
MANUAL, OR

YOU MAY CONTACT THE WARRANTY ASSISTANCE CENTER DIRECTLY AT  
1-800-423-8851, FOR ADDITIONAL ASSISTANCE WITH THE CUSTOMER HANDLING.

---

**From:** Keinath, Wayne (W.)  
**Sent:** Friday, April 13, 2012 9:41 AM  
**To:** Flanagan, Thomas (T.P.)  
**Subject:** FW: U502 EPAS gear C200D with 15 February 2012 build date

Tom:

Since you mentioned you were replacing Laura, I thought you should see this claims and request. Thanks.

Regards:

*Wayne Keinath*

**CAP VE/Chass/Elec PVT Supervisor**  
(773) 646-7372 or (313) 805-3771  
Fax (773) 646-7377

---

**From:** Jackson, Bradley (B.G.)  
**Sent:** Friday, April 13, 2012 8:38 AM  
**To:** Napoli, Laura (L.); Estes, Eric (E.E.); Cassata, Joe (J.)  
**Cc:** Surella, Matthew (M.M.); Farmer, Marty (M.F.); Keinath, Wayne (W.)  
**Subject:** U502 EPAS gear C200D with 15 February 2012 build date

Laura / Eric, hope somebody jumps on this 2013MY U502 gear. I did submit PEARS 190861 just to be safe. If you have already requested, then that's fine too.

Joe, please have the dealer ship this out quickly. This one is hot.

## Claim Detail Report

### Vehicle Information

Model Year: 2013 Document Number: 01254501  
Market Derived: F - FORD Repair Date: 03-APR-2012  
Body/Cab Type: T/WD - 4 DOOR WAGON Distance: 1264  
Version/Series: T/EF-FORD SERIES TIS: 1  
Drive Type: T/F-4 WHL L/H FULL TIME DRIVE AWS Load Date: 12-APR-2012  
Vehicle Line: T/UB-EXPLORER [11-13]  
Warranty Start Date: 30-MAR-2012  
Production Date: 15-FEB-2012  
VIN: 1FM5K8F80DG [REDACTED]

### Claim Information

### Expense Information

### Dealer Information

Customer Paid Amount: .00  
Dealer Name: COUNTRYSIDE FORD OF CLEARWATER Deductible Amount: .00  
Dealer Code: 08183 - \* Dealer Paid Amount: .00  
Address: 24825 U.S. HWY 19 NORTH Labor Cost: 202.00  
City: CLEARWATER Misc. Expense Amount: .00  
State: FL Zip Code: 33763 Part Markup Amount: .00

Country: USA Region Code: NA Material Cost: 1696.25  
 Phone: (727)793-6222 Total Cost Gross: 1898.25

Cust. Concern Code: C50 - OTHER STEERING/HANDLING AND RIDE TROUBLES  
 Condition Code: 42 - DOES NOT OPERATE PROPERLY  
 Technician Comment: VERIFIED COMPLAINT.PREFORMED SELF TEST ON  
 PSCM.DTCU3000 96,C200D 49.PREFORMED PINPOINT TEST C .TEST RESULTS REPLACE  
 STEERING GEAR.INSTALLED NEW EPAS STEERING GEAR AS PER WSM.MEASURE AND  
 RESET ALGINMENT ANGLES TO SPECS.RECHECKED OK  
 Customer Comment: CUST STATES THAT POWER STEERING IS NOT ASSISTING...

<u>Labor Op Code</u>	<u>Labor Op Description</u>	<u>Labor Op Cost</u>
3504A	STEERING GEAR ASSEMBLY REMOVE AND INSTALL OR REPLACE	146.91
3001A	CASTER, CAMBER, TOE-IN CHECK	36.73
3001A6F	TOE-IN CORRECT	18.36

<u>Causal Flag</u>	<u>Full Part Number</u>	<u>Part</u>	<u>Part Description</u>	<u>Part CPSC</u>	<u>Extended Quantity</u>	<u>Amount</u>
Y	DB5Z 3504 CE	CE	GEAR ASY-STEERING	110101	1	1696.25

<u>DTC Sections:</u>		<u>Mil. Light On =</u>		<u>N</u>	
<u>Flag</u>	<u>Test Type</u>	<u>Malfunction Cd</u>	<u>Malfunction Cd Description</u>	<u>Monitor Cd</u>	<u>Monitor Cd</u>
N	KOEO	U3000	CONTROL MODULE	48	HYBRID

Regards,  
*Brad Jackson*  
 Chassis Resident Engineer  
 Chicago Assembly Plant  
 Ford Motor Company  
 Phone: +1.313.805.4798  
[bjackson@ford.com](mailto:bjackson@ford.com)

---

**From:** Napoli, Laura (L.)  
**Sent:** Thursday, February 24, 2011 8:55 AM  
**To:** 'Rob Kostadina'; 'Jim Loria'; 'Shafqat Bhatti'  
**Subject:** FW: UR0003(BD0,BD2,BD4)- Bent torque sensor finger

Keep this in mind from U502 2011 warranty when analyzing the  gear that was picked up last night. May be the same root cause...?

---

**From:** Estes, Eric (E.E.)  
**Sent:** Wednesday, February 23, 2011 12:50 PM  
**To:** Napoli, Laura (L.); Mrozek, Robert (R.M.); Snider, Tim (T.O.); Bahena, Miguel (Mike.)  
**Subject:** UR0003(BD0,BD2,BD4)- Bent torque sensor finger

We have found one bent torque sensor finger similar to the other  returns(see attached pic's)

IPA should arrive at Rogersville today for analysis.


At this time Rogersville sent two people to inspect 3,500 IPA's in stock at the Marion Plant before assembly and Rogersville they are inspecting 5K IPA's before shipping to Marion. At this time have not found any bent fingers at this time.

Apparently all IPA's for U502 use line 2 and now Rogersville is trying to find the cause of the bent finger at this time since we are making all the changes to line 1 for a bent finger since all the  bent finger returns came off line 1 and this is the first bent finger that came off of line 2.

The EOL operator at Rogersville was the only one inspecting for bent fingers on line 2 and missed this one.

So the containment at this time is 100% offline inspection at Rogersville and 100% inspection at Marion before assembly into the gear.

Should have more updates on the corrective action by Friday.




Let me know if you have any questions, thanks

*Eric J Estes*

TRW EPAS Steering Systems  
Quality Specialist  
Hotline ph# 313-317-9358  
Cell ph# 734-560-3493





---

**From:** Anderson, Eric (H.)  
**Sent:** Thursday, January 13, 2011 10:27 AM  
**To:** Bahena, Miguel (Mike.)  
**Subject:** FW: 2011 Exp - BGA10846 - Loss of power steering, lamp on, 18 mi, BD 12/16/10

Hi Mike:

CAP just received this CQIS claim about an inoperative EPAS gear. Do you have any idea what could be wrong with it based on the hotline conversation below?

Thanks,

Eric Anderson

---

**From:** Buelow, Steve (S.E.)  
**Sent:** Thursday, January 13, 2011 8:22 AM  
**To:** Adamczyk, David (D.W.); Bollwahn, Bryce (B.A.); Centlivre, James (J.C.); Cittadino, Lisa (L.C.); Collins, Kevin (K.E.); Gagnier, Kathryn (K.A.); Gilewski, David (D.); Gubing, William (Bill.); Hays, Andy (A.R.); Henker, Scott (S.); Holland, James (J.P.); Lubin Henney, Michele (MLH.); Lysik, Kevin (K.M.); Mann, Mickey (N.S.); McClain, Shawn (S.M.); Pogorzelski, John (J.M.); Rodgers, Chuck (.); Saleh, Salim (S.A.); Sellers, Gary (G.T.); Simkus, Walter (W.A.); Smith, Scott (S.A.); Sokolowski, Todd (T.M.); Thornsberry, Joel (J.A.); Willis, Mark (M.E.); Wong, Vicki (V.A.); Abrams, Donald (D.); Acuna, Aaron (A.A.); Allman, Jan (J.E.); Bell, Tim (.); Bergeron, Matthew (M.C.); Bisaga, Richard (R.); Boykin, George (G.); Boykins, Michael (M.); Bustamante, Chris (C.T.); Cantrell, David (D.D.); Ciotti, Steven (S.R.); Davis, Charlene (C.); Devine, Robert (R.M.); Docimo, Tony (A.F.); Elting, Tim (T.H.); Ferguson, Hugh (H.); Gagnier, Scott (S.W.); Greenwell, R (R.); Guyton, MzJenny (J.); Hernandez, Thomas (T.); Herron, Micheal (M.C.); Inglis, Steve (S.D.); Iqbal, Khurram (K.); Jones, Frederick (F.L.); Little, Janie (J.); Martin, Kenneth (K.A.); Matlock, Douglas (D.); McElroy, Darin (D.L.); McKernan, Patrick (P.J.); Miller, Melinda (M.S.); Moore, Chikynda (D.); Moses, Barry (B.A.); Moskwa, Larry (L.M.); Perkins, John (J.E.); Pesch, Vincent (V.J.); Rutovic, Nick (N.); Sarkisian, Mark (Z.); Talbott, Larry (J.L.); Turner, Bridgette (B.); Turner, Patrice (P.T.); Vandergroef, Cornelius (C.); Washington, Kellie (K.S.); Wertman, David Brian (D.B.); Westbrook, Dori (D.); Williams, Erik (E.C.); Williams, Gregory (G.M.); Williams, TRACE (S.); Wyatt, Kimberly (K.D.); Zroback, David (D.P.); Evans, Kayekethia (K.); Gibson, Renelda (R.); Lakomek, Scott (S.); Ornelas, Demetrio (D.); Ratliff, Kathy (K.); Stonewall, Wendy (M.); Svetich, Chris (C.); Anderson, Eric (H.); Berzeri, Marcello (M.); Chamberlain, Steve (J.); Edwards, Monty (M.R.); Farmer, Marty (M.F.); Feder, Andrew (A.); Gerrard, Ryan (R.P.); Iannotti, Jason (JRI.); Ickes, Walt (W.D.); Imperati, Daniel (D.); Issa, Ibrahim (I.M.); Jackson, Bradley (B.G.); Logli, Michael (M.A.); Morgan, Anthony (A.); Olsson, Paul (P.C.); Polaski, Mike (M.S.); Porter, Alan (A.T.); Rapiz, Noreen (N.G.); Siddiqui, Saif (S.S.); Sluis, Jim (JS.); Smith, Erin (E.); Sridhara, Raghu (R.); Trygar, Mike (M.); Vargo, Rebecca (R.L.); Widrick, Brad (B.A.); Young, Richard (R.C.); Yu, Eric (E.); Buelow, Steve (S.E.)  
**Subject:** FW: 2011 Exp - BGA10846 - Loss of power steering, lamp on, 18 mi, BD 12/16/10

**-The Customer Defines Quality-**

*Steve Buelow - Ford Motor Company*

FCSD Program Manager-  
Taurus/Taurus SHO/Lincoln MKS/Explorer  
Chicago Assembly PVT Office, COE  
773-646-7495 DialNet 686-7495  
Cell 313-805-8334 sbuelow@ford.com

"You miss 100 percent of the shots you never take." - Wayne Gretzky

---

**From:** SBUELOW@ford.com [mailto:SBUELOW@ford.com]  
**Sent:** Thursday, January 13, 2011 8:15 AM  
**To:** Buelow, Steve (S.E.)  
**Subject:** 2011 Exp - BG [REDACTED] - Loss of power steering, lamp on, 18 mi, BD 12/16/10

**Attachments :** 0

**Report# :** BALEI002 NHL **Received:** 01/12/2011  
**CCRG/EPRC:** **Reviewed Status:** **Date:**  
**Vehicle:** 2011,EXPLORER 4X4 (U502),4 DOOR **Build Date:** 12/16/2010  
,MP,1FMHK8D83BG [REDACTED]  
**Odometer :** 18 M **Engine:** 3.5L **Calibration:** BUB1ST0A  
CYCLO  
**Transmission:** 6F55 **Axle:** **A/C:** YES  
**Dealer:** USA 09618 Brown Motors, Inc. **Phone#:** (231!!) 439-9604  
**City:** Petoskey **State:** Michigan **Country :** USA  
**Originator:** JIM MILBRANDT  
**Symptom:** 3 03 1 50 CHASS.,STRG/HANDLING ,FUNCTION,HIGH EFFORT  
**Status:**  
**VFG:** V87 STEERING  
**Additional Symptom:** LOSS OF POWER STEERING  
**Fix:** **Causal Component :**  
**Condition Code:**

**Hotliner:** DMU!! RRA86 **Phone:** 313 248-8233 **Regn Cd:** G2 Detroit  
**Engineering:** **Phone:** **TAR:**  
**Dlr Contact:** JIM MILBRANDT **Phone:** 231 439-3673 **Title Cde:** T

**DTCs:**

KOEO:U0253 U2011  
KOEC:  
KOER:

**Comments**

**:**  
REPAIR 01/12/2011 02:45PM DOUGLAS MURRAY MSS - FCSD - TECH SVC HOTLINE  
WEB FORM DATA - CONCERN: CUSTOMER STATES WHEN ON TEST DRIVE THE  
POWER



STEERING QUIT AND A RED INDICATOR LIGHT CAME ONE. DIAGNOSTICS:  
PERFORMED IDS TESTS U0253:00-28 IPC U2011:49-08 PSCM IN MEMORY  
PARTS REPLACED:: NONE TECH QUESTION: ANY REPORTS FOR THIS  
CONCERN? WERE YOU ABLE TO VERIFY THE CONCERN? NO IS THERE AN  
APPROPRIATE PINPOINT TEST IN THE WSM FOR THIS CONCERN? WAS THE  
PINPOINT TEST FOLLOWED?

**RECOMM 01/12/2011 02:45PM DOUGLAS MURRAY MSS - FCSD - TECH SVC HOTLINE**  
JIM, IT IS RECOMMENDED TO GO TO THE WSM SECTION 211-00/DIAGNOSIS  
AND TESTING/DTC AND SYMPTOM CHARTS/INTERACTIVE DIAGNOSTICS AND GO  
TO  
THE INTERACTIVE DIAGNOSTICS SECTION. FROM THERE, GO TO THE DTC LIST  
AND LOOK UP U2011. THIS IS A MOTOR CODE AND THERE ARE 2 DIFFERENT PPT  
TESTS DEPENDING ON WHICH BITMAP CODE YOU HAVE. THIS CODE INDICATES  
THAT THE PSCM HAS SEEN A MOTOR ISSUE AND WILL SHUT DOWN THE POWER  
ASSIST FUNCTION. PLEASE TRY TO DUPLICATE THE CONCERN AND IF CODE  
U2011 SETS, PERFORM THE APPROPRIATE CHART. THERE ARE NO COMMON  
TRENDS FOR THIS CONCERN. THANK YOU.

**From:** Flanagan, Thomas (T.P.)  
**Sent:** Thursday, July 19, 2012 7:18 AM  
**To:** Surella, Matthew (M.M.)  
**Cc:** Estes, Eric (E.E.)  
**Subject:** FW: 2011 EXP/[REDACTED] CHASSIS - Report Summary(s) from a GCQIS Query Disposition

Matt,

4 C200D U502's yesterday.

Tom Flanagan  
Ford Motor Company  
CD3, D3 EPAS Steering Engineering  
PDC 2B-K24  
(313) 845-4062  
Cell (313) 815-6885

**From:** SBUELOW  
**Sent:** Thursday, July 19, 2012 2:49 AM  
**To:** TFLANAG1  
**Subject:** 2011 EXP/[REDACTED] CHASSIS - Report Summary(s) from a GCQIS Query Disposition

This email contains 11 report summary(s).

**Attachments :** 0

<b>Report# :</b>	CGRD1005 NHL	<b>Received:</b>	07/18/2012
<b>CCRG/EPRC:</b>		<b>Date:</b>	
<b>Vehicle:</b>	2011,EXPLORER 4X4 (U502) ,LIMITED,4 DOOR ,MPV ,1FMHK8F82BG [REDACTED]	<b>Build Date:</b>	04/25/2011
<b>Odometer :</b>	21,939 M	<b>Engine:</b>	3.5L CYCLO
<b>Transmission:</b>	6F55	<b>A/C:</b>	YES
<b>Dealer:</b>	USA 00693 Romano Ford	<b>Phone#:</b>	(315) 637-4668
<b>City:</b>	Fayetteville	<b>State:</b>	New York
<b>Originator:</b>	WARREN JONES	<b>Country :</b>	USA
<b>Symptom:</b>	6 62 4 39 SP/ST/RD,STEER/STER WHL,PERFORMANCE,INTERMITTENT		
<b>Status:</b>			
<b>VFG:</b>	V87 STEERING		
<b>Additional Symptom:</b>	C200D49		
<b>Fix:</b>	<b>Causal Component :</b>	--	
<b>Condition Code:</b>			

**Hotliner:** NHARRIER

**Phone:** 313 317-9290

**Regn Cd:** N1 New York

**Engineering:**

**Phone:**

**TAR:**

**Dlr Contact:** WARREN JONES

**Phone:** 315 637-4668

**Title Cde:** T

**DTCs:**

KOEO:C1B00:85 C200D:49

KOEC:

KOER:

**Comments**

:

**REPAIR** 07/18/2012 10:55AM NATHAN HARRIER MSS - FCSD - TECH SVC HOTLINE  
WEB FORM DATA - CONCERN:LOSS OF STEARING ASSIST DIAGNOSTICS:  
MONITORED PIDS DTCS PARTS REPLACED:REPLACES SCCM/ANGLE SENSOR TOOK  
CARE OF 1 CODE TECH QUESTION:STILL GETTING C200D BOOK SAYS TO  
REPLACE STEARING GEAR?

**RECOMM** 07/18/2012 10:55AM NATHAN HARRIER MSS - FCSD - TECH SVC HOTLINE  
WARREN, BASED ON DTC C220D-49 SUSPECT A EPASS RACK CAUSING THIS  
CONCERN. PLEASE ENSURE THAT NO BATTERY OR CHARGING SYSTEM FAULTS  
EXISTS AS THIS CAN CAUSE A LACK OF ASSISTS. IF A CHARGING OR BATTERY  
ISSUE EXISTS FURTHER DIAGNOSE USING SECTION 414-00 IN THE ONLINE  
WORKSHOP MANUAL. IF NO BATTERY OR CHARGING SYSTEM FAULTS EXISTS  
REPLACE THE EPASS RACK (PSCM) PER WORKSHOP MANUAL SECTION 211-00 IN  
THE ONLINE WORKSHOP MANUAL AND REEVALUATE THE CONCERN. IF FURTHER  
ASSISTANCE IS NEEDED FEEL FREE TO CONTACT US AGAIN. THANK  
YOU =====  
ISM 11-08-019 LOSS OF POWER STEERING ASSIST WITH C200D IN PSCM

**Attachments : 0**

<b>Report# :</b>	CGRD9008 NHL	<b>Received:</b>	07/18/2012
<b>CCRG/EPRC:</b>		<b>Date:</b>	
<b>Vehicle:</b>	2012,EXPLORER 4X2 (U502) ,XLT ,4 DOOR ,MPV ,1FMHK7D83CG [REDACTED]	<b>Build Date:</b>	10/14/2011
<b>Odometer :</b>	12,391 M	<b>Engine:</b>	3.5L CYCLO
<b>Transmission:</b>	6F50	<b>Axle:</b>	
<b>Dealer:</b>	USA 00025 Preston Ford Lincoln	<b>Calibration:</b>	CUB1SN0A
		<b>A/C:</b>	YES
		<b>Phone#:</b>	(410) 673- 7171

**City:** Hurlock **State:** Maryland **Country :** USA  
**Originator:** ROB LYNCH  
**Symptom:** 6 62 4 38 SP/ST/RD,STEER/STER WHL,PERFORMANCE,INOPERATIVE  
**Status:**  
**VFG:** V87 STEERING  
**Additional Symptom:** C200D  
**Fix:** **Causal Component :** --  
**Condition Code:**

**Hotliner:** BWRIGH77 **Phone:** 313 317-7040 **Regn Cd:** N4 Washington  
**Engineering:** **Phone:** **TAR:**  
**Dlr Contact:** ROB LYNCH **Phone:** 410 673-7171 **Title Cde:** T

**DTCs:**  
KOEO:C200D:49 C1B00:86  
KOEC:  
KOER:

**Comments**

**:**  
**REPAIR** 07/18/2012 11:48AM BRANDON WRIGHT MSS - FCSD - TECH SVC HOTLINE  
WEB FORM DATA - CONCERN:CUSTOMER STATED VEHICLE LOST STEERING AND SERVICE TRAC LAMP CAME ON WORKING NOW BUT HAD CODES C1B00:86 IN ABS MODULE PINPOINT TEST REFERS YOU TO GO TO PSCM AND FIX ANY CODES THERE  
PSCM HAS CODE C200D:49 THERE IS NO TEST STATES TO REPLACE STEERING GEAR ASSEMBLY DIAGNOSTICS: WROTE IT IN VEHICLE CONCERN AREA  
SERVICE MANAGER WANTED ME TO CONTACT TECHNICAL SUPPORT BECAUSE CUSTOMER HAS BEEN ONLINE AND READ ABOUT THIS BEING A CONCERN WITH MULTIPLE VEHICLES AND WANTS TO MAKE SURE EVERY EFFORT IS MADE TO PROPERLY FIX THIS VEHICLE IS THERE ANY UPDATED REPAIRS PARTS REPLACED:NONE TECH QUESTION:SERVICE MANUAL STATES REPLACE STEERING GEAR IS THERE ANY THING ELSE THAT SHOULD BE DONE OR ANY UPDATED PARTS  
**RECOMM** 07/18/2012 11:48AM BRANDON WRIGHT MSS - FCSD - TECH SVC HOTLINE  
ROBERT, YOU ARE CORRECT THAT PSCM (STEERING GEAR) REPLACEMENT IS NECESSARY TO RESOLVE THIS CONCERN. ENGINEERING HAS DETERMINED THAT THE PSCM IS THE CAUSE OF THIS CONCERN AND REPLACE IS NECESSARY WITH THESE DTCS AND SYMPTOM. PLEASE CONTINUE WITH REPLACEMENT OF THE PSCM AT THIS

TIME.

---

**Attachments :** 0

**Report# :** CGRGP010 NHL **Received:** 07/18/2012  
**CCRG/EPRC:** S **Reviewed Status:** **Date:** 07/18/2012  
**Vehicle:** 2012,EXPLORER 4X2 (U502) ,LIMITED,4 DOOR ,MPV **Build Date:** 09/12/2011  
,1FMHK7F80CG [REDACTED]  
**Odometer :** 14,615 M **Engine:** 3.5L **Calibration:** CUB1SN0A  
CYCLO  
**Transmission:** 6F50 **Axle:** **A/C:** YES  
**Dealer:** USA 02750 Avis Ford, Inc. **Phone#:** (800) 358-  
2778  
**City:** Southfield **State:** Michigan **Country :** USA  
**Originator:** SHAWN ALDRICH  
**Symptom:** 6 60 3 40 SP/ST/RD,STOPPING,PEDAL,LONG TRAVEL  
**Status:**  
**VFG:** V21 BRAKING  
**Additional Symptom:** BRAKE PEDAL DROPS TO FLOOR  
**Fix:** **Causal Component :** --  
**Condition Code:**

**Hotliner:** WWHITT1 **Phone:** 313 317-6304 **Regn Cd:** G2 Detroit  
**Engineering:** **Phone:** **TAR:**  
**Dlr Contact:** SHAWN ALDRICH **Phone:** 000 000-0000 **Title Cde:** T

**DTCs:**  
KOEO:  
KOEC:  
KOER:

**Comments**

**:**  
REPAIR 07/18/2012 05:20PM WESLEY WHITTINGTON MSS - FCSD - TECH SVC HOTLINE  
WEB FORM DATA - CONCERN:WHILE CREEPING AT IDLE FOOT RESTING ON THE  
BRAKE PEDAL WITH VERY LITTLE BRAKE APPLIED, PEDAL WILL FALL TO THE  
FLOOR AND UNABLE TO STOP THE VEHICLE ONCE THIS OCCURS. UNLESS YOU  
TAKE  
YOUR FOOT OFF THE PEDAL AND REAPPLY THE BRAKES. DIAGNOSTICS: CHECK

FOR LEAKS NONE. NOT LOW ON FLUID. VEHICLE STOPS FINE AT HIGH SPEEDS, PROBLEM ONLY HAPPENS WHILE CREEPING AT A LIGHT, HEAVY TRAFFIC, IN PRAKING LOTS. UNDER 5 MPH. PARTS REPLACED:NONE. TECH QUESTION:ANY KNOWN ISSUES AND/OR AREAS TO CHECK FOR POSSABLE CAUSES.

**RECOMM 07/18/2012 05:20PM WESLEY WHITTINGTON MSS - FCSD - TECH SVC HOTLINE**  
 SHAWN, IT IS RECOMMENDED TO ATTEMPT TO DUPLICATE THE CONCERN WHILE THE VEHICLE IS STATIONARY BY SLOWLY APPLYING THE BRAKE PEDAL. ONCE WITH THE ENGINE RUNNING AND AGAIN WITH THE ENGINE OFF AND THE BOOSTER RELIEVED OF THE VACUUM. IF THE CONCERN CAN BE DUPLICATE WITH THE ENGINE OFF AND BOOSTER WITH NO VACUUM, SUSPECT A MASTER CYLINDER BYPASS ISSUE. AT THIS POINT DISCONNECT THE MASTER CYLINDER OUTPUT LINES AND PLUG THE PORTS ON THE MASTER CYLINDER. APPLY FIRM BRAKE PRESSURE AND MONITOR FOR A DROPPING PEDAL. IF THE PEDAL FEELS FIRM PERFORM THE SAME TEST ON THE HCU AND MONITOR FOR A DROP IN PEDAL. IF THE PEDAL DROPS SUSPECT A HCU BYPASS CONDITION. BRAKE BOOSTER AND MASTER CYLINDER COMPONENT TESTS CAN BE FOUND IN SECTION 206-00.

**Attachments : 5**

<b>Report# :</b>	CGRBR004 NHL	<b>Received:</b>	07/18/2012
<b>CCRG/EPRC:</b>		<b>Date:</b>	
<b>Vehicle:</b>	2011,EXPLORER 4X2 (U502) ,XLT ,4 DOOR ,MPV ,1FMHK7D87BG [REDACTED]	<b>Build Date:</b>	06/07/2011
<b>Odometer :</b>	12,196 M	<b>Engine:</b>	3.5L CYCLO
<b>Transmission:</b>	6F50	<b>Axle:</b>	
<b>Dealer:</b>	USA 03990 Morris Ford, Inc.	<b>Calibration:</b>	BUB1SN0A
<b>City:</b>	Burnt Hills	<b>A/C:</b>	YES
<b>Originator:</b>	MATTHEW GURDINEER	<b>Phone#:</b>	(518) 399- 9188
<b>Symptom:</b>	6 62 2 03 SP/ST/RD,STEER/STER WHL,APPEAR/CLEAR,APPEARANCE		
<b>Status:</b>			
<b>VFG:</b>	V89 RIDE & HANDLING		
<b>Additional Symptom:</b>	STEERIGN WHEEL SWITCHES LOOSE		
<b>Fix:</b>	<b>Causal Component :</b>	--	
<b>Condition Code:</b>			

**Hotliner:** GSTAVROP

**Phone:** 000 317-4877

**Regn Cd:** N1 New York

**Engineering:**

**Phone:**

**TAR:**

**Dlr Contact:** MATTHEW GURDINEER

**Phone:** 000 000-0000

**Title Cde:** T

**DTCs:**

KOEO:

KOEC:

KOER:

**Comments**

:

**REPAIR 07/18/2012 09:07AM GEORGE STAVROPOULUS MSS - FCSD - TECH SVC HOTLINE**  
 DATA FROM PRIOR APPROVAL REQUEST FORM: PLEASE DESCRIBE CUSTOMERS CONCERN.CUSTOMER STATES STEERING WHEEL BUTTONS ON RIGHT SIDE FELL INSIDE STEERING WHEEL WHAT IS THE INTENDED REPAIR, LIST ALL COMPONENTS NEEDED FOR REPAIR?REPLACEMENT PROVIDE ANY ADDITIONAL DETAILS NECESSARY.  
 PLEASE INCLUDE ANY AVAILABLE TECHNICAL INFORMATION THAT YOU BELIEVE WILL HELP PROCESS YOUR PRIOR APPROVAL REQUEST.NONE REPAIR ESTIMATE - LABOR: REPAIR ESTIMATE - TOTAL: VEHICLE/COMPONENT ABUSE: MODIFICATIONS: LACK OF MAINTENANCE: RO#: 287525RO DATE:2012-07-18WARRANTY TYPE:NEW VEHICLE WARRANTY SPW MILEAGE: SPW INSTALL DATE:

**RECOMM 07/18/2012 09:07AM GEORGE STAVROPOULUS MSS - FCSD - TECH SVC HOTLINE**  
 MATT,  
 WITH COMMENTS PROVIDED IT'S NOT CLEAR WHAT NEEDS REPLACEMENT? STEERING WHEEL SWITCHES ARE AVAILABLE FOR THIS STEERING WHEEL AND DO NOT REQUIRE OUR PRIOR APPROVALS. IF STEERING WHEEL NEEDS REPLACEMENT PLEASE CLARIFY WHY?  
 SWITCH PART NUMBERS ARE  
 BT4Z-9C888-AB LEFT SIDE / BT4Z-9C888-CA RIGHT SIDE

FUTURE

CLAIM SUBMISSIONS SHOULD INCLUDE IMAGES THAT ARE RIGHT SIDE UP. PROVIDING IMAGES RIGHT SIDE UP WILL HELP IMPROVE HANDLING TIME AND REDUCE CLARIFICATIONS.

PLEASE REFER TO THE 2012 INTERIOR / EXTERIOR PRIOR APPROVAL PROGRAM COVERED COMPONENT LIST AND BEST PRACTICE INSTRUCTIONS ON PRIOR APPROVAL SUBMISSIONS SUBMISSIONS.

<="" td="">

HREF=HTTP://WWW.FMCDEALER.DEALERCONNECTION.COM/SITES/FORD\_LM/EDC/JUL2012/DOCUMENTS/IEPA%20BEST%20PRACTICE\_FINAL.PDF TARGET=\_BLANK>FCSD TECHNICAL SERVICE HOTLINE 2012 INTERIOR / EXTERIOR PRIOR APPROVAL PROGRAM REQUEST AND IMAGE SUBMISSION BEST PRACTICE JOB AID

<="" td="">

HREF=HTTP://WWW.FMCDEALER.DEALERCONNECTION.COM/SITES/FORD\_LM/EDC/JUL2012/DOCUMENTS/UPDATED%20US%202012%20IEPA%20COVERED%20COMPONENTS\_JULY\_%0FINAL.PDF TARGET=\_BLANK> U.S. DEALERS - 2012 INTERIOR/EXTERIOR PRIOR APPROVAL PROGRAM COMPONENT LIST

DIPA PRIOR APPROVAL  
NOT NECESSARY

**REPAIR 07/18/2012 01:26PM GEORGE STAVROPOULUS MSS - FCSD - TECH SVC HOTLINE**  
TABS FOR RIGHT SIDE SWITCHES ON SILVER COVER BROKEN

**RECOMM 07/18/2012 01:26PM GEORGE STAVROPOULUS MSS - FCSD - TECH SVC HOTLINE**  
MATT,  
THANK YOU FOR THE DIAGNOSTIC INFORMATION.  
BASED ON

INFORMATION AND IMAGES PROVIDED, CLAIM REQUEST IS APPROVED TO REPLACE THE STEERING WHEEL (PART #:3600 STEERING WHEEL ASSY) TO CORRECT LOOSE SWITCHES DUE TO BROKEN MOUNT TABS WITHIN STEERING WHEEL. DIPA APPROVED APPROVAL CODE: PAAYS

**REPAIR 07/18/2012 02:51PM GARY BUSH MSS - FCSD - TECH SVC HOTLINE**  
THANK YOU SORRY ABOUT THE PICTURES BEING UPSIDE DOWN, MY IPHONE FLIPPED THEM OVER.

**RECOMM 07/18/2012 02:51PM GARY BUSH MSS - FCSD - TECH SVC HOTLINE**  
YOU ARE WELCOME. IMAGES ARE CLEAR SO WE WERE ABLE TO WORK WITH THEM.  
DIPA APPROVED APPROVAL CODE: PAAYS

Please click on the link below to view the attachments associated with this report

[https://www.gcqis.dealerconnection.com/gcqis/asp/DIViewAttachment\\_Mainx.asp?ReportNumber=CGRBR004](https://www.gcqis.dealerconnection.com/gcqis/asp/DIViewAttachment_Mainx.asp?ReportNumber=CGRBR004)

Redacted for Relevance



Redacted for Relevance

Redacted for Relevance

Attachments : 0

<b>Report# :</b>	CGRB8002 NHL	<b>Received:</b>	07/18/2012
<b>CCRG/EPRC:</b>		<b>Date:</b>	
<b>Vehicle:</b>	2012,EXPLORER 4X4 (U502) ,XLT ,4 DOOR ,MPV ,1FMHK8D84CG [REDACTED]	<b>Build Date:</b>	10/27/2011
<b>Odometer :</b>	9,235 M	<b>Engine:</b>	3.5L CYCLO
<b>Transmission:</b>	6F55	<b>Axle:</b>	
		<b>Calibration:</b>	CUB1ST0A
		<b>A/C:</b>	YES

**Dealer:** USA 07392 Salem Ford **Phone#:** (603) 898-9766  
**City:** Salem **State:** New Hampshir **Country :** USA  
**Originator:** ERIC DEBISZ  
**Symptom:** 6 62 4 39 SP/ST/RD,STEER/STER WHL,PERFORMANCE,INTERMITTENT  
**Status:**  
**VFG:** V87 STEERING  
**Additional Symptom:** LACK OF ASSIST C200D  
**Fix:** **Causal Component :** --  
**Condition Code:**

**Hotliner:** WWHITT11 **Phone:** 313 317-6304 **Regn Cd:** N2 Boston  
**Engineering:** **Phone:** **TAR:**  
**Dlr Contact:** ERIC DEBISZ **Phone:** 000 000-0000 **Title Cde:** T

**DTCs:**  
KOEO:C200D:49  
KOEC:  
KOER:

**Comments**

**:**  
**REPAIR** 07/18/2012 08:55AM WESLEY WHITTINGTON MSS - FCSD - TECH SVC HOTLINE  
WEB FORM DATA - CONCERN:CUSTOMER STATES TAKING A RIGHT HAND TURN LOST  
POWER STEERING. TURNED VEHICLE OFF AND RESTARTED AND THE STEERING WAS  
FINE. DIAGNOSTICS: INSPECTION, ROAD TEST, EEC TEST, OASIS PARTS  
REPLACED:NONE TECH QUESTION:PERFORMED DIAG WITH THE INTERACTIVE  
WORKSHOP MANUAL TESTING. MANUAL STATES THE ACTION TO BE PERFORMED  
FOR  
THIS CODE IN TO REPLACE THE RACK? IS THIS CORRECT, THERE IS NOTHING TO  
DO BUT TO REPLACE THE RACK? JUST WANT TO MAKE SURE BEFORE I ORDER  
THE  
RACK. I COULD NOT DUPLICATE CONCERN ON MY ROAD TEST. INSPECTED AND  
FOUND NO CHAFT WIRING OR DAMAGE TO THE VEHICLE OR RACK IN ANY WAY.  
**RECOMM** 07/18/2012 08:55AM WESLEY WHITTINGTON MSS - FCSD - TECH SVC HOTLINE  
ERIC, ERIC, WITH THE CODE THAT IS SET IT IS RECOMMENDED TO  
REPLACE THE EPAS STEERING GEAR. ENGINEERING HAS DETERMINED THE ROOT  
CAUSE FOR THIS CONCERN AND HAS UPDATED THE NEW GEARS. ISM

11-08-019 LOSS OF POWER STEERING ASSIST WITH C200D IN PSCM SSM 22383  
THE WORKSHOP MANUAL SECTION 211-00A HAS BEEN UPDATED WITH REVISED  
DIAGNOSIS FOR POWER STEERING CONTROL MODULE DTCS U2011:49 AND C200D

**REPAIR 07/18/2012 09:24AM MATTHEW BERELS MSS - FCSD - TECH SVC HOTLINE**  
THANK YOU!

**RECOMM 07/18/2012 09:24AM MATTHEW BERELS MSS - FCSD - TECH SVC HOTLINE**  
ERIC, YOU'RE WELCOME. IF EPAS STEERING GEAR REPLACEMENT RESOLVES  
THIS CONCERN, PLEASE COMPLETE THE ONLINE SURVEY WITH THE FIX  
INFORMATION. IF FURTHER ASSISTANCE IS NEEDED, PLEASE FEEL FREE TO  
CONTACT THE HOTLINE. THANK YOU.

---

**Attachments : 0**

**Report# :** CGRD1007 NHL **Received:** 07/18/2012  
**CCRG/EPRC:** **Reviewed Status:** **Date:**  
**Vehicle:** 2012,EXPLORER 4X4 (U502) ,BASE ,4 DOOR ,MPV **Build Date:** 08/10/2011  
,1FMHK8B8XCG [REDACTED]  
**Odometer :** 8,816 M **Engine:** 3.5L **Calibration:** CUB1SN0A  
CYCLO  
**Transmission:** 6F50 **Axle:** **A/C:** YES  
**Dealer:** BHS F0A62 Friendly Ford **Phone#:**  
**City:** Nassau **Country :** BHS  
**Originator:** ANTON SMITH  
**Symptom:** 6 62 4 38 SP/ST/RD,STEER/STER WHL,PERFORMANCE,INOPERATIVE  
**Status:**  
**VFG:** V87 STEERING  
**Additional Symptom:** LOSS OF ASSIST  
**Fix:** **Causal Component :** --  
**Condition Code:**

**Hotliner:** ASIMS38 **Phone:** 313 317-9367 **Regn Cd:** 9A FCSD REGION- 9A

**Engineering:** **Phone:** **TAR:**

**Dlr Contact:** ANTON SMITH **Phone:** 242 356-7100 **Title Cde:** T

**DTCs:**

**KOEO:**

KOEC:B00A0:63 C1B00:86 C200D:49 U3000:96 U3003:16

**KOER:**

**Comments**

**REPAIR** 07/18/2012 10:57AM AARON SIMS MSS - FCSD - TECH SVC HOTLINE  
 WEB FORM DATA - CONCERN:STEERING WHEEL IS STIFF, THERE IS NO POWER STEERING ASSIT WHILE DRIVING. THE POWER STEERING ASSIT LIGHT IS ON, ADVANCE TRAC LIGHT AND AIRBAG LIGHT IS ON. DIAGNOSTICS: A VISIUAL INSPECTION IS DONE TO SEE IF THERE WAS ANY DAMAGE WIRES NONE SEEN. CHECKED FUSES ,(OK). FOLLOWED THE PINPOINT TEST. PARTS REPLACED:NO PARTS WAS REPLACED. TECH QUESTION:ACCORDING TO THE DTC CHART FOR DTC CODE U3000 , IT SAYS TO DIAGNOSE OTHER DTCS AND IF THERE IS NO OTHER DTC ORESENT TO REPLACE THE RFA MODULE. SO I WENT AND CLEARED THE CODES TO SEE IF THEIR IS A HARD CODE IN THE SYSTEM AND ONLY THE U3000 WAS PRESENT. SO AS A RESULT I WENT TO INSPECT THE RFA MODULE TO SEE IF THERE WAS ANY DAMAGE WIRES OR ANY OBVIOUS PROBLEM. SO I FOLLOWED THE REMOVAL PROCEDURE BUT COULD NOT LOCATE THE MODULE. WANTED TO KNOW IF I AM FOLLOWING THE RIGHT DIAGNOSTIC PROCEDURE AND IF THIS PATICULAR VEHICLE IS EQUIPED WITH A RFA MODULE.

**RECOMM** 07/18/2012 10:57AM AARON SIMS MSS - FCSD - TECH SVC HOTLINE  
 ANTON, WITH THIS CONCERN, IF THE U3000:96 CODE IS PRESENT IN THE PSCM VERIFY CONNECTORS AT PSCM ARE SEATED CORRECTLY AND NOT DAMAGED. IF THESE ARE GOOD SUSPECT A FAULTY STEERING GEAR CAUSING THE CONCERN. WHEN FOLLOWING THE U3000:96 DTC BEING STORED IN THE PSCM AS OUTLINED IN INTERACTIVE DIAGNOSTICS IN SECTION 211-00 THIS IS THE DIRECTION IT LEADS. SINCE THIS VEHICLE IS NOT EQUIPPED WITH IA KEYS(PUSH BUTTON START) THIS VEHICLE WILL NOT HAVE AN RFA MODULE. IF DTC U3003:16 IS PRESENT IN THE RCM RECOMMEND REVIEWING DIAGNOSTIC ROUTINE Y IN SECTION 501-20 OF THE ONLINE WSM.

**Attachments : 0**

<b>Report# :</b>	CGRCP001 NHL	<b>Received:</b>	07/18/2012
<b>CCRG/EPRC:</b>	<b>Reviewed Status:</b>	<b>Date:</b>	
<b>Vehicle:</b>	2011,EXPLORER 4X2 (U502) ,LIMITED,4 DOOR ,MPV ,1FMHK7F84BG [REDACTED]	<b>Build Date:</b>	02/11/2011

**Odometer :** 26,757 M      **Engine:** 3.5L CYCLO      **Calibration:** BUB1ST0A  
**Transmission:** 6F55      **Axle:**      **A/C:** YES  
**Dealer:** USA 04893 Midway Ford      **Phone#:** (305) 266-4357  
**City:** Miami      **State:** Florida      **Country :** USA  
**Originator:** ELIEZER ZEQUEIRA  
**Symptom:** 6 62 2 03 SP/ST/RD,STEER/STER WHL,APPEAR/CLEAR,APPEARANCE  
**Status:**  
**VFG:** V89 RIDE & HANDLING  
**Additional Symptom:** REARVIEW CAMERA GUIDELINES  
**Fix:** **Causal Component :** --  
**Condition Code:**

**Hotliner:** JWIBERG5      **Phone:** 313 317-6313      **Regn Cd:** S4 Miami  
**Engineering:**      **Phone:**      **TAR:**  
**Dlr Contact:** ELIEZER ZEQUEIRA      **Phone:** 305 266-3000      **Title Cde:** T

**DTCs:**  
 KOEO:  
 KOEC:  
 KOER:

**Comments**

:  
**REPAIR** 07/18/2012 09:13AM JAMES WIBERG MSS - FCSD - TECH SVC HOTLINE  
 WEB FORM DATA - CONCERN:REAR VIEW CAMARA NOT ALIGMING  
 STRAIGHT DIAGNOSTICS: RADIO TECNICIAN CHECK RADIO AND IS OK// NO  
 CODES PARTS REPLACED:RACK&PINION TECH QUESTION:COSTOMER  
 COMPLEING THE AFTER RACK WAS REPLACE THE LINE ON THE RADIO DONT  
 MASH  
 THE DIRECTION OF THE VEHICLE OR THE STEERING WHEEL// I CHECK RACK AND  
 TIE RODS ARE CENTER IN BOTH SIDE// I NEED TO KNOW: THIS LINE ARE  
 CONTROL BY THE RACK OR SOMETING ELSE IN THE STEERING COLUM// IF IS IN  
 THE STEERING COLUM I CAN ROTATE STEERING WHEEL 360 DEGREE AND WILL  
 BY  
 OK// IF IS ON, DO I HAVE TO REPLACE THE RACK AGAIN?// OR I CAN  
 REPROGRAM A MODULE?  
**RECOMM** 07/18/2012 09:13AM JAMES WIBERG MSS - FCSD - TECH SVC HOTLINE  
 ELIECER, THE FIXED GUIDELINES THAT ARE DISPLAYED WHEN THE VEHICLE  
 IS IN REVERSE ARE CONTROLLED BY THE STEERING WHEEL ROTATION SENSOR.

IF  
 THE STEERING WHEEL WAS MOVED WHEN REPLACING THE STEERING GEAR,  
 DAMAGE  
 MAY HAVE OCCURRED TO THE SWR SENSOR WHICH IS WHY THE GUIDELINES  
 ARE  
 READING INCORRECTLY. SUGGEST THAT YOU REMOVE THE STEERING WHEEL  
 AND  
 CLOCKSPrING AND INSPECT THE SWR SENSOR FOR DAMAGE OR INCORRECT  
 MOUNTING AND REPLACE/REINSTALL AS NEEDED PER ONLINE WORKSHOP  
 MANUAL  
 PROCEDURES.

**Attachments :** 0

<b>Report# :</b>	CGRGB014 NHL	<b>Received:</b>	07/18/2012
<b>CCRG/EPRC:</b>	<b>Reviewed Status:</b>	<b>Date:</b>	
<b>Vehicle:</b>	2011,TAURUS ,FWD ,LIMITED,SEDAN ,1FAHP2FW4BG [REDACTED]	<b>Build Date:</b>	05/02/2011
<b>Odometer :</b>	9,886 M	<b>Engine:</b>	DURATEC 35
<b>Transmission:</b>	6F50	<b>Axle:</b>	3.16 RATIO
<b>Dealer:</b>	USA 02968 Tyler Ford, LTD	<b>Calibration:</b>	BPH1FT0A
<b>City:</b>	Tyler	<b>A/C:</b>	YES
<b>Originator:</b>	JOSHUA STAPLES	<b>Phone#:</b>	(903) 597- 9331
<b>Symptom:</b>	6 62 3 00 SP/ST/RD,STEER/STER WHL,FEEL/WAN/PULL,UNKNOWN		
<b>Status:</b>			
<b>VFG:</b>	V87 STEERING		
<b>Additional Symptom:</b>	PULL TO RIGHT ON HARD ACCEL		
<b>Fix:</b>	<b>Causal Component :</b>	--	
<b>Condition Code:</b>			

<b>Hotliner:</b> JBOALES	<b>Phone:</b> 000 317-9341	<b>Regn Cd:</b> C1 Dallas
<b>Engineering:</b>	<b>Phone:</b>	<b>TAR:</b>
<b>Dlr Contact:</b> JOSHUA STAPLES	<b>Phone:</b> 000 000-0000	<b>Title Cde:</b> T

**DTCs:**  
 KOEO:  
 KOEC:

KOER:

**Comments**

:

**REPAIR** 07/18/2012 06:25PM JEFFREY BOALES MSS - FCSD - TECH SVC HOTLINE  
WEB FORM DATA - CONCERN:PULLS HARD TO THE RIGHT UNDER  
ACCELERATION DIAGNOSTICS: TEST DROVE TO VERIFY CONCERN, INSPECTED  
ALL SUSPENSION, CHECKED ALIGNMENT. ALIGNMENT IS ON THE MONEY WITH  
ONE  
EXCEPTION. FRONT CASTER IS SLIGHTLY OUT OF SPECS ON THE HIGH SIDE BUT  
THE CASTER SPLIT IS GOOD. PARTS REPLACED:NONE TECH  
QUESTION:WITH NO CASTER ADJUSTMENT IS THERE ANYTHING I CAN DO OR  
SHOULD THE -.04 CASTER SPLIT BE OK AT THIS TIME?

**RECOMM** 07/18/2012 06:25PM JEFFREY BOALES MSS - FCSD - TECH SVC HOTLINE  
JOSHUA, A SLIGHTLY OUT OF SPECIFICATION CASTER SPLIT WILL NOT CAUSE  
THE VEHICLE TO PULL ON ACCELERATION LIKE THIS. IT IS RECOMMENDED THAT  
YOU BEGIN BY COMPARING THE OPERATION TO A LIKE UNIT WITH THE EXACT  
SAME POWERTRAIN ON THE SAME ROAD. THERE HAVE BEEN MULTIPLE  
INSTANCES  
WHERE TORQUE STEER UNDER HARD ACCELERATION HAS BEEN FOUND TO BE  
NORMAL. IF THE OPERATION OF THE LIKE UNIT IS SIMILAR, NO REPAIRS ARE  
RECOMMENDED. ATTEMPTING TO ALTER A NORMAL CHARACTERISTIC WILL  
LEAD TO  
A REPEAT ISSUE. VERIFY THAT THE CUSTOMER IS NOT REMOVING THEIR  
HANDS FROM THE WHEEL. PULLING WITH HANDS REMOVED FROM THE WHEEL IS  
NORMAL UNDER ANY CONDITION. THIS IS NOT A VALID TEST. DISCONNECT  
THE ABS MODULE TO ENDURE THE IS NO TRACTION CONTROL EVENT CAUSING  
THE  
PULL. IF THE ISSUE IS GONE, THIS IS TRACTION CONTROL RELATED. MONITOR  
THE YAW, LAT, SWA, AND WSS PIDS USING THE IDS. THE PIDS MUST BE  
MONITORED WHEN THE CONCERN ACTUALLY OCCURS. IF ANY PID READS  
ERRATICALLY OR DROPS OUT, SUSPECT THIS IS THE CAUSE OF THE CONCERN.

---

Redacted for Relevance



Redacted for Relevance

Redacted for Relevance

Redacted for Relevance

---

**From:** Napoli, Laura (L.)  
**Sent:** Tuesday, October 25, 2011 3:46 PM  
**To:** Moody, Sandra (S.L.); Perri, Ron (R.J.); Surella, Matthew (M.M.); Dukkipati, Srinu (S.); Brezee, Shane (S.B.)  
**Subject:** FW: 2011 U502 B9A Buy Back vehicle

TRW has a potential buy back. Good news is that it is at a rental company, so we are not holding up a customer. The gear is locked out, so there is no way of knowing if the failure is a hard failure. There's no reason to buy the car back if it is a hard failure because the gear will not be testable. TRW is going out to the dealer tomorrow in San Fran to pull codes and verify if the gear has a complete failure or just a temporary lock out. They will also take data and try to duplicate the failure.

If it is a permanent failure, we should not buy back the car, but just have the gear returned.  
If it's not a permanent failure and they duplicate it while taking data, we may not need to buy the car back.  
If neither of the above happens, this would be a good buy back car and we should move quickly.

On another note, I have a couple responses from the 6-sigma study of management lease cars that would be potential cars to test instead of buying one back. I should have more info on that this week.

Regards,

*Laura Napoli*

D3 and U502 EPAS  
Ford Motor Company  
Cube: 2B-G66 PDC  
Phone: 313.323.0634  
Mobile: 313.805.0482

---

**From:** Estes, Eric (E.E.)  
**Sent:** Tuesday, October 25, 2011 1:30 PM  
**To:** Napoli, Laura (L.)  
**Cc:** Salim Semssar; Anthony.Fleenor@TRW.COM; John Burnett  
**Subject:** FW: 2011 U502 B9A Buy Back vehicle

John Burnett is all set to arrive at Future Ford tomorrow afternoon to pull the data on the 2011 Explorer then clearing the data to see if the B9A code resets.

I did let the service manager know our intentions of buying back the vehicle if it fits our criteria.

The dealer information is below: Tracy is the Service Manager that I talked to.

FUTURE FORD OF CLOVIS  
920 West Shaw Avenue, Clovis, CA 93612

- Call Us Now: (866) 875-7137

# Eric J Estes

TRW EPAS Steering Systems  
Quality Specialist  
Hotline ph# 313-317-9358  
Cell ph# 734-560-3493

---

**From:** Estes, Eric (E.E.)  
**Sent:** Tuesday, October 25, 2011 11:37 AM  
**To:** Napoli, Laura (L.)  
**Subject:** 2011 U502 B9A Buy Back vehicle

Laura I found this vehicle in Clovis, California and this vehicle is a AVIS RAC so it might be easy to buy back, the problem with this vehicle is that it set B9A three times then set U3000-96(C69) not the exact issues with the other B9A returns but we can get the tech to perform the proper snap shot data below and look at the freeze frame data for the B9A.

Let me know the tech will not replace the gear until I call him back.

**Year = MY11**  
**Model = U502**  
**Engine = 3.5L**  
**VIN = 1FMHK8D87BG** [REDACTED]  
**IDS Version = 73.03A (IDS-73.03A)**

**PCM = BB5A-14C204-NJ**  
**ABS = BB53-2C219-AF**  
**ACM = BB5T-19C107-BS**  
**APIM = BT4T-14D212-BM**  
**ATCM = N\A**  
**BCM = BC3T-14B476-DH**  
**C-CM = N\A**  
**CLM = N\A**  
**DCSM = N\A**  
**DSM = N\A**  
**DSP = N\A**  
**FCDIM = N\A**  
**FCIM = N\A**  
**FLM = N\A**  
**GPSM = N\A**  
**HSWM = N\A**  
**HUD = N\A**  
**HVAC = BB5T-18C612-BG**

IPC = BB5T-10849-GG  
 LTM = N/A  
 OCSM = N/A  
 PAM = BB5T-15K866-AC  
 PSCM = BB53-3F964-BG  
 RCM = BB5T-14B321-AF  
 RFA = N/A  
 RLCM-A = N/A  
 SCCM = BB5T-3F944-AJ  
 SOD-L = N/A  
 SOD-R = N/A  
 TPM = N/A

▣ Current DTCs {retrieved 19 October 2011 15:14:25}

DTC	Snap Shot Data	Source
-----	----------------	--------

▣ Historic DTCs {retrieved 19 October 2011 15:14:25}

DTC	Snap Shot Data	Source
-----	----------------	--------

▣ DTCs cleared since initial read:

DTC	Snap Shot Data	Source
U0402:68	N/A	<a href="#">ABS</a>
C1B00:86	N/A	<a href="#">ABS</a>
(ABS)	N/A	<a href="#">ABS</a>
P1285:00	N/A	<a href="#">PCM</a>
P1299:00	N/A	<a href="#">PCM</a>
U3000:96	N/A	<a href="#">PSCM</a>
C200D:49	N/A	<a href="#">PSCM</a>


*Eric J Estes*

TRW EPAS Steering Systems  
 Quality Specialist  
 Hotline ph# 313-317-9358  
 Cell ph# 734-560-3493

**From:** Perri, Ron (R.J.)  
**Sent:** Thursday, January 05, 2012 3:25 PM  
**To:** Surella, Matthew (M.M.)  
**Subject:** FW: B9A Fallout at Tyco, Nidec, Anting/Shalke/Nove Mesto

**Attachments:** Picture (Metafile)

Please update this....



Ron Perri  
Manager, Chassis - EPAS and Upper Steering, Systems & Core  
2B-F77, Product Development Center  
cell 313-805-0680  
rperri@ford.com

---

**From:** Napoli, Laura (L.)  
**Sent:** Thursday, December 22, 2011 10:25 AM  
**To:** Perri, Ron (R.J.)  
**Cc:** Surella, Matthew (M.M.)  
**Subject:** B9A Fallout at Tyco, Nidec, Anting/Shalke/Nove Mesto

Ron,

I have the most recent numbers for fallout at Tyco, Nidec, and Anting/Shalke/Nove Mesto for the visual inspections they're doing for misalignment and concoat.

Tyco:  
Since Nov 12, Tyco is finding 0 misalignment on ribbon cables at EOL with 5x magnification.

Nidec:  
For batches of ribbon cables that were built before PCAs were put in place at Tyco, Nidec found 22 out of 14,800 with

misalignment.

Since Nov 12, Nidec has 0 fallout at IQ for ribbon cable misalignment when inspected with 5x magnification.

Nidec inspected 69,122 motor assys that were already built before the ribbon cable visual inspections went into place on Nov 12. They found 638 suspect parts. They x-rayed 42 of them and found 9 to be misaligned. They are going through the rest and visually re-checking them with 30x magnification to find which parts are truly misaligned.

Since Nov 11, Nidec has been inspecting motor assys at EOL for conformal coat running from the relay. This is the same day they fixed the conveyor. They have 0 fall out for concoat since this date.

For conformal coat inspections on finished stock, they have quarantined 11k parts. These are parts with any amount of conformal coat at the connector from the relay.

Anting:

From 11/11-11/21, Anting found 15 out of 25,783 assys with protruding wires (misalignment) and rejected these parts. Anting initially reported that they had 30% fallout for conformal coat at the connector. Since 11/24, they have 0 fallout.

Shalke and Nove Mesto:

Shalke and Nove Mesto have been inspecting for misalignment since Nov 15 with 0 fallout.

Next Steps:

TRW is going through each and every return to determine root cause of B9A and B3A/B43.

There is a study going on between TRW and Nidec with help from Tyco to confirm that conformal coat is the root cause of the high resistance measured on parts that do not have misaligned cables. This is to confirm that there is no other root cause of failure.

Regards,

*Laura Napoli*

D3 and U502 EPAS

Ford Motor Company

Cube: 2B-G66 PDC

Phone: 313.323.0634

Mobile: 313.805.0482



---

**From:** Diez, Timothy (T.P.)  
**Sent:** Wednesday, February 16, 2011 3:00 PM  
**To:** Rossi, Roberto (R.A.)  
**Subject:** FW: Explorers with inoperative steering

Please read below...

Sincerely,  
Tim Diez  
Ford Electric Power Steering, EESE  
313-805-1060; Fax: 313-317-4387  
e-mail: [tdiez@ford.com](mailto:tdiez@ford.com)  
cube 3C071, Building 5

---

**From:** Anderson, Eric (H.)  
**Sent:** Wednesday, February 16, 2011 2:58 PM  
**To:** Napoli, Laura (L.); Estes, Eric (E.E.); 'Michael Fontana'; 'Simon Malsbury'; 'Robert Kostadina'; 'Hemang Mehta'; 'Nick turovich'; Mrozek, Robert (R.M.); Diez, Timothy (T.P.); 'Geoff Jacks'; 'Phil Browne'; 'Michele Marion'; 'Jim Loria'; 'Don Blandino-contr'; 'Engelbert Lu'; 'Mathew Alder'  
**Cc:** Docimo, Tony (A.F.); Cantrell, David (D.D.)  
**Subject:** RE: Explorers with inoperative steering

Hi All:

Please see the latest power steering inoperative claim. It is the fifth suspected internal gear fault known to CAP. The list to date is:

BGA14928: U3000:96  
BGA10846: U0253:00-28, U2011:49-08  
BGA14928: U3000:96  
BGA22399: U3000:61 discovered in plant  
BGA18724: C200B:2F

CAP is working toward 50R per 1000 units for the Explorer as a whole vehicle. Five inverted delta parts that stop functioning within weeks of vehicle launch is unacceptable. What is TRW doing to fix these problems? What can CAP do to detect faulty gears before our customers experience steering assist loss? Please explain your fixes as soon as possible.

Thanks,

Eric

**Attachments :** 0

<b>Report# :</b>	BBLAA025 NHL	<b>Received:</b>	02/12/2011
<b>CCRG/EPRC:</b>	<b>Reviewed Status:</b>	<b>Date:</b>	
<b>Vehicle:</b>	2011,EXPLORER 4X4 (U502),4 DOOR ,MP,1FMHK8F8XBG [REDACTED]	<b>Build Date:</b>	01/20/2011
<b>Odometer :</b>	303 M	<b>Engine:</b>	3.5L CYCLO
		<b>Calibration</b>	BUB1ST0A
		:	

**Transmission:** 6F55      **Axle:**      **A/C:** YES  
**Dealer:** USA 00089 Koons Ford of Annapolis, Inc.      **Phone#:** (410) 266-3087  
**City:** Annapolis      **State:** Maryland      **Country :** USA  
**Originator:** JAMES MORELAND  
**Symptom:** 3 03 1 55 CHASS.,STRG/HANDLING ,FUNCTION,LOSS OF STRG  
**Status:**  
**VFG:** V89 RIDE & HANDLING  
**Additional Symptom:** U3000:96  
**Fix:**      **Causal Component :**  
**Condition Code:**

**Hotliner:** C10 BISHO41      **Phone:** 313 317-9359      **Regn Cd:** N4 Washington  
**Engineering:**      **Phone:**      **TAR:**  
**Dlr Contact:** JAMES MORELAND      **Phone:** 410 266-3087      **Title Cde:** T

**DTCs:**

KOEO:U3000:96

KOEC:

KOER:

**Comments :**

REPAIR 02/12/2011 01:58PM CHRIS BISHOP MSS - FCSD - TECH SVC HOTLINE

WEB FORM DATA - CONCERN: NO POWER STEERING DIAGNOSTICS:  
SELF TEST

VISUAL INSPECTION FOUND CONNECTOR ON GEAR DISCONNECTED  
PARTS

REPLACED:: NONE TECH QUESTION: CODE U3000 96 LEADS TO  
REPLACEMENT

OF EPAS GEAR W/NO PINPOINT TESTS IS THIS CORRECT, VEHICLE WAS  
DX TO

OUR DEALER SAID P/S WENT OUT IN OUR PARKING LOT, TESTED AND  
FOUND

CONNECTOR 1453A DISCONNECTED. PLUGGED BACK IN BUT NO P/S  
AND CODE AND

MESSAGE CENTER WILL NOT CLEAR OUT. WERE YOU ABLE TO VERIFY  
THE

CONCERN? YES IS THERE AN APPROPRIATE PINPOINT TEST IN THE  
WSM FOR

THIS CONCERN? YES WAS THE PINPOINT TEST FOLLOWED? YES

**RECOMM 02/12/2011 01:58PM CHRIS BISHOP MSS - FCSD - TECH SVC HOTLINE**

JAMES, YOU ARE CORRECT. IF THE U3000:96 IS PRESENT AS A HARD  
FAULT

THEN STEERING GEAR REPLACEMENT IS REQUIRED. THIS CODE  
INDICATES THAT

THE ELECTRONIC STEERING GEAR HAS EXPERIENCED AN INTERNAL  
FAULT.

RECOMMEND REPLACING THE GEAR AS NEEDED THEN RETESTING  
FOR NORMAL

OPERATION.

---

**From:** Napoli, Laura (L.)  
**Sent:** Wednesday, February 09, 2011 3:23 PM  
**To:** Anderson, Eric (H.); Estes, Eric (E.E.); 'Michael Fontana'; 'Simon Malsbury'; 'Robert Kostadina'; 'Hemang Mehta'; 'Nick turovich'; Mrozek, Robert (R.M.); Diez, Timothy (T.P.); 'Geoff Jacks'; 'Phil Browne'; 'Michele Marion'; 'Jim Loria'; 'Don Blandino-contr'; 'Engelbert Lu'; 'Mathew Alder'  
**Subject:** RE: Explorers with inoperative steering

[Please see my comments below...](#)

---

**From:** Anderson, Eric (H.)  
**Sent:** Wednesday, February 09, 2011 4:14 PM  
**To:** Estes, Eric (E.E.); 'Michael Fontana'; 'Simon Malsbury'; 'Robert Kostadina'; 'Hemang Mehta'; 'Nick turovich'; Mrozek, Robert (R.M.); Diez, Timothy (T.P.); Napoli, Laura (L.); 'Geoff Jacks'; 'Phil Browne'; 'Michele Marion'; 'Jim Loria'; 'Don Blandino-contr'; 'Engelbert Lu'; 'Mathew Alder'  
**Subject:** Explorers with inoperative steering

Hi All:

Please give me an update on root cause for these U502 units that experienced steering assist loss, if you have one. If the part has yet to be returned for analysis and root cause is unknown, please note it.

BGA10846: Petoskey, MI. Inoperative because of contamination in B3A motor relay.  
B3A caused by contamination on motor relay. Source of contamination at Tyco unknown.

BGA14928: Ripley, WV. Root cause unknown.  
B3A. Part shipped to Tyco but not yet received. Cause of B3A will be known by COB tomorrow once relay is analyzed by Tyco.

BGA22399: Chicago Assembly Plant. Gear hand carried to TRW for analysis. Root cause unknown.  
B91. Unable to duplicate. Root cause not yet known. Suspect gear was installed into a 2011 U502 and TRW is trying to duplicate issue before HW is sent out for analysis.

BGA18724: Dixon, CA. Intermittently inoperative. Root cause unknown.  
BD2 & BD4. Torque Sensor Faults. Gear not yet returned to TRW. Root cause unknown.

Thanks,

Eric Anderson  
PVT Engineer  
Ford Chicago Assembly  
773.646.7236 desk  
773.729.0337 cell  
eande181@ford.com


---

**From:** Surella, Matthew (M.M.)  
**Sent:** Friday, June 15, 2012 12:22 AM  
**To:** Perri, Ron (R.J.)  
**Cc:** Napoli, Laura (L.)  
**Subject:** FW: U502/D3 "New" Clean dates

Ron,  
Wayne Keinath called me yesterday about the assignment below. Somehow the PVT at CAP got asked to provide Bennie a summary of TRW EPAS issues. I told Wayne that Chassis has our own meetings with Bennie but Wayne was still wondering if I could send him a summary document.

I updated our summary file for both ribbon cable and relay issues and attached it below. We still do not have all the new clean dates for the copper sulfur relay issues but Laura is actively working on this. Please take a look at the file and send it to Wayne if you think this is appropriate. He wanted something by the end of the week and I will let him know that it is in your hands. Thanks.

Matthew (Matt) Surella  
Steering EPAS Supervisor / MBB  
313-805-3997



---

**From:** Farmer, Marty (M.F.)  
**Sent:** Monday, June 11, 2012 11:11 AM  
**To:** Surella, Matthew (M.M.)  
**Cc:** Keinath, Wayne (W.); Brown, Jude (J.); Szalay, Michael (M.A.)  
**Subject:** FW: U502/D3 "New" Clean dates

Matt,

Apparently Bennie Fowler is asking for a summary of TRW EPAS issues for all vehicle lines along with "new" clean points and why we have broken containment.

Can this be provided to us today?

**Marty Farmer** CHICAGO ASSEMBLY PLANT | CHASSIS PVT | FORD MOTOR COMPANY | [mfarmer2@ford.com](mailto:mfarmer2@ford.com)  
| 313.805.5605

---

**From:** Napoli, Laura (L.)  
**Sent:** Wednesday, June 06, 2012 1:04 PM  
**To:** Farmer, Marty (M.F.)  
**Cc:** Brown, Jude (J.); Surella, Matthew (M.M.)  
**Subject:** RE: U502/D3 "New" Clean dates

Here are the clean dates for CAP programs for CuS on relays and misaligned ribbon cables...

CuS fix on motor and link relays:

- D3 Base: 5/11/2012
- D3 Police: 2/10/2012
- U502 48mm: 2/10/2012
- U502 58mm: 2/23/2012

Ribbon Cable Misalignment:

- D3 Base: 8/16/2012
- D3 Police: 8/16/2012
- U502 48mm: 6/30/2012
- U502 58mm: 8/8/2012

For D3 Base CuS relay fix, I need to confirm with China. This is what Mexico gave me but it seems too far out compared to D3 Police. And for ribbon cable misalignment, the dates are based on 100% clean stock. Need to know from China what percentage of current stock is clean. We know U502 is already shipping a mix of parts before and after the clean date. Not sure what the ratio is. It's the best I have for you now. If they ask why each program is so different, you should tell them that high volume (like U502 48mm) gets clean quicker because they build more often. The lower volume programs get built in large batches and stored until requested by TRW. For example, for U502 58mm, Nidec only builds once every 1-2 months based on the orders. Therefore they're holding old stock and not using it at TRW until now.

Regards,

*Laura Napoli*

D3 and U502 EPAS  
Ford Motor Company  
Cube: 2B-G66 PDC  
Phone: 313.323.0634  
Mobile: 313.805.0482

---

**From:** Farmer, Marty (M.F.)  
**Sent:** Wednesday, June 06, 2012 9:55 AM  
**To:** Napoli, Laura (L.)  
**Cc:** Brown, Jude (J.)  
**Subject:** U502/D3 "New" Clean dates

Laura,

Please send Jude and I clean dates for the misaligned ribbon cable and relay contamination.

**Marty Farmer** CHICAGO ASSEMBLY PLANT | CHASSIS PVT | FORD MOTOR COMPANY | [mfarmer2@ford.com](mailto:mfarmer2@ford.com)  
| 313.805.5605

# TRW EPAS Gear Quality Issues

## TRW EPAS Gear Containment Actions for H22 CCC - B9A warranty

**A. Root cause** - PCB ribbon cable header assembly quality and conformal coat location on PCB quality

**B. Corrective Actions**

At Tier 1 - TRW

- Modify Puma script to reject for B9A LIC's - implemented 11/11 - gears arrived at CAP ~Monday 11/21
- 100% sort cable for protruding wire strands with magnification at Novo Mesto and Schalke - implemented 11/14 – gears arrived Saar louis, Valencia ~Monday 11/21
- 100% sort cable for conformal coat contamination w/ UV light at Novo Mesto and Schalke - implemented 11/16 - gears arrived Saar louis, Valencia ~Wednesday 11/23

At Tier 2 – Anting - China

- 100% sort cable for conformal coat contamination w/ UV light - implemented 11/10 – arrived at TRW-MAO, TRW-QTO 01/10/2012
- Modify EOLT program to reject for B9A LIC's - implemented 11/11
- Modify Puma script to reject for B9A LIC's - implemented 11/11
- 100% sort cable for protruding wire strands with magnification - implemented 11/16

At Tier 3 – Nidec - China

- 100% sort cable for conformal coat contamination w/ UV light - implemented 11/11
- 100% sort cable for protruding wire strands with magnification - implemented 11/14
- **Conveyor angle corrected for conformal coat running from relay - implemented 11/11, – arrived at Assembly Plants 01/30/2012**

At Tier 4 – Tyco - Germany

- 100% sort cable for protruding wire strands with magnification - implemented 11/14
- Added calibrated set-up block for header to ribbon cable assembly - implemented 11/25
- Increase frequency of set-up teardown cross-section to verify set-up ribbon cable assembly alignment - implemented 11/17
- **Ribbon cable header assembly wedge adjusted 9/6, started cross sectioning parts and added visual inspection for misalignment 11/17, added set up gages 11/25, implemented blade change every 50,000 cuts 12/2 – arrived at Assembly Plants as follows:**

Platform	EPP ( out of motor clean date: Mar.22=F082 )		EPP ( within motor clean date:Mar.22=F082 )		Anting EPP clean date	last ship date of Anting with motor build date prior to F082	Parts arrive at MAO/QAO	Parts arrive at Ford Assy Plant
	Qty	Anting EPP build period	Qty	Anting EPP build period				
Redacted for Relevance								
U502 48	10,447	Mar.27~May.11.2012	12,099	Apr.10~May.17.2012	May.12.2012	May 17, 2012	June 27, 2012	June 30, 2012
U502 58	4,245	Apr.1~May.22.2012	0	to be confirmed	May.22.2012	June 24, 2012	August 5, 2012	August 8, 2012
Redacted for Relevance								

Estimates. These programs subject to undetermined amount of time sitting in China warehouse.

**C. Standard Bill of Process Globally** => C1, U502, D2/D3/D4, [redacted] TRW EPAS ribbon cables are supplied from Tier 4: Tyco-Germany; C1, U502, D2/D3/D4, [redacted] TRW EPAS conformal coat processed at same Tier 3: Nidec-China

**D. Warranty and Assembly Plant Fall-out Status**

N.A. Warranty pre-containment: 2011 U502: 63/92037, [redacted]; 8/142773; Post containment: Zero.

Redacted for Relevance

Redacted for Relevance

**Warranty and Assembly Plant Fall-out Status**

N.A. Warranty pre-containment: 2012 U502: 11/40023, ; Post containment: Zero.



Steering Products Center		8D Corrective & Preventive Action Form				TRW			
Report #'s / Reference #'s				Date Opened:	02/22/11	Platform(s)	Team Leader:	Angie Caudill	
QCCAR#	N/A	NCT/ QR#	N/A	Revised Date:		All IPA	QRQC Rank:	A	
				Time:	7:59 AM				
CS#	N/A	WAR#	UR0003	TRW Person Entering Complaint:		Plant(s)	Clean Date:		
						Rogersville / Marion	02/23/11		
Customer:	Ford	Contact:	Bobby Sandhu	Customer DM#		TRW Part #:	80SA1G1		
Customer Plant:	MAO	Phone:	276-783-1116	Referral #		Customer Part #:	A0025456		
(1a) Team Name: IPA corrective action team				(1b) Team Members: Misty Christian, Todd Williams, Angie Caudill, Carl Craig and Andy Ausband					
P U R P O S E	(2a) Customer's Description of Problem:  IPA assembly with bent rotor finger			(2b) Expert's Description of Problem:  Defective IPA assembly was a warranty return with one bent rotor vane. Vane was touching the PCB. Build date of IPA was 01/14/2011			Repeat Issue?	Yes	
	Inspection Report#		Met Lab Report#						
	Func. Test Report#		Eng. Test Report#						
	dFMEA Reviewed?		PFMEA Reviewed?		Severity				
<b>Click Go To Containment Worksheet To Enter Data</b>									
A C T I O N	(3a) Implementation of Interim Containment Actions:			(3b) How are Containment Measures Effectiveness Verified?					
	<u>Containment Action</u>		<u>Date Checked</u>						
	1	External Customer (See Above)	02/23/11	1					
	2	Interdivisional TRW (See Above)	02/23/11	2					
	3	TRW (See Above)	02/23/11	3					
4	Supplier (See Above)	02/23/11	4						
(3c) Interim Actions prior to identifying Root Cause: (List actions, primes, dates, etc.) <span style="float: right;">(T) = Times Changed</span>									
	<u>Action</u>	<u>Prime:</u>	<u>Status</u>	<u>Target Date</u>	<u>New Date</u>	<u>T</u>	<u>Completed Date</u>		
1	Post / implement quality alert on Prodel lines one and two to inform operators there has been an additional requirement of a 100% visual off line inspection added. Alert must also mandate that the inspection be performed by someone other than the Prodel operator. IPA assemblies will be certified to the customer for this condition and marked with a blue dot on the rotor	A. Caudill	Quality alert posted. 100% off-line visual inspection is in place.	2/22/2011			2/22/2011		
2	Create and implement procedure on Prodel lines one and two for 100% visual off line inspection for bent rotor vanes	A. Caudill	Procedure is completed and has been implemented	2/22/2011			2/22/2011		
3	Verify that the 100% on-line mistake proof check for bent rotors is functioning correctly	A. Caudill	Red masters are functioning correctly. Verification that lines one and two will reject a bent rotor	2/22/2011			2/22/2011		
4	Perform analysis on returned part	A. Caudill	One rotor vane was bent. There was no witness mark present on top of the vane. Historically, we have seen two methods of bending the rotor vanes. (1) impact (witness mark will be visible) (2) steady force over time	2/28/2011					

Steering Products Center		8D Corrective & Preventive Action Form				TRW	
5	Through the established check points (Rog on-line MP, Rog EOL, Rog. off-line and MAO), we are trying to isolate where the defect occurred	A. Caudill			TBD		
<b>Click Go To 3L Root Cause Analysis To Enter Data</b>							
<b>(4a) Define the Root Cause (3L ) (Root Cause)</b>				<b>(4b) How was the Root Cause Verified?</b>			
		<b>Cause:</b>	<b>Date Identified:</b>			<b>Duplicated? (Yes/No)</b>	
C A U S E	1	<b>Primary:</b> Root cause still under investigation.		1			
	2	<b>Secondary:</b>		2			
<b>Cause &amp; Effect Done? (Y/N)</b>			<b>Timeline Done? (Y/N)</b>		<b>DOE Done? (Y/N)</b>		

Steering Products Center		8D Corrective & Preventive Action Form				TRW	
<b>(5) Implementation of Permanent Corrective Actions: (List actions, primes, dates, etc.)</b>							<small>(T) = Times Changed</small>
<u>Action</u>	<u>Prime:</u>	<u>Status</u>	<u>Target Date</u>	<u>New Date</u>	<u>T</u>	<u>Completed Date</u>	
1	Creation of electrical PM to verify correct alignment of axis on station B3 (sensor weld). Ensures part does not make contact and damage rotor	A. Caudill	PM has been added to the system (read across from line 1 issue)	1/6/2011		1/6/2011	
2	Creation of tech PM to verify correct clamp jaw position on station B3 (sensor weld)	A. Caudill	PM has been added to the system (read across from line 1 issue)	1/6/2011		1/6/2011	
3	Addition of a 100% visual EOL check for bent rotors to the operator's standard work. Parts to be verified prior to packaging	A. Caudill	100% visual EOL check has been added to the operator's standard work (read across from line 1 issue)	2/22/2011		1/6/2011	
4	Investigate the possibility of reducing the contact area of gap set tooling depending on the results of the tool design stack-up	T. Williams	Timing includes design, fabrication and installation of tooling	3/21/2011			
5							
6							
7							
<b>Mistake proofing Required? (Y/N)</b>			<b>Explain:</b>				
<b>(6) Verify Effectiveness of Actions:</b>							
	<b>Verified:</b> (List How verified and Who verified)					<b>Verified Date:</b>	
1							
2							
3							
4							
5							
6							
7							



A  
C  
T  
I  
O  
N

V  
E  
R  
I  
F  
Y






Steering Products Center	8D Corrective & Preventive Action Form						TRW
A C T I O N	(7) Control Plan to Prevent Recurrence (List actions, primes, dates, etc.) <span style="float: right;">(T) = Times Changed</span>						
	Action	Prime:	Status	Target Date	New Date	T	Completed Date
	1						
	2						
	3						
	4						
	5						
Expected Verification Time Period:		Days	Date:				
G L O B A L	(8) How will the Global System be Modified to Prevent Similar Events within the Business? <span style="float: right;">(T) = Times Changed</span>						
	Action	Prime:	Status	Target Date	New Date	T	Completed Date
	1						
	2						
	3						
dFMEA Updated? (Y/N)		pFMEA Updated? (Y/N)					
Detection# Changed from:		to:	Occurrence# changed from:	to:			
<b>APPROVE PLAN</b>							
S I G N A T U R E S	Quality Engineer: _____			Date: _____			
	Quality Manager: _____			Date: _____			
	<b>CLOSURE</b>						
	Supplier Quality Manager: _____			Date: _____			
	Quality Specialist or SDE: _____			Date: _____			
Quality Manager: _____			Date: _____				
Director of Quality: _____			Date: _____				
Other(s): _____			Date: _____				
Cause: (Place "X" where applicable)		Systemic:	Design:	Process:	Operator:	Supplier:	Customer or Dealer
If Systemic Breakdown is Evident, List Applicable ISO/TS 16949 Element(s) and Clause(s).		Element:	Element:	Element:			

## New problem in TE 12way cable assy

TE date code 1563245-1A 14/12/11 (Dec 14th, 2011)



- 1 Cutting point No.1 (blue) is different from other lines
- 2 Other line insulation protruded
- 3 Strand of No.1 (blue) damaged and protruded
- 4 Misalignment



B9A

10-5-11

REDACTED FOR RELEVANCE

<sup>U502</sup>  
- OF ~~55~~ B9A'S, 31 HAD ELECTRICAL ISSUES w/ TOUCH SCREEN NAV... <sup>SYWC</sup>

REDACTED FOR RELEVANCE

AP/LN/GJ/EE/MSURZLA/T. FLANAGAN  
BRAD JACKSON  
CHRIS WOODRUFF  
GUILLERMO, PEPE

B9A FOLLOW UP FRIDAY 10:00

10-7-11

REDACTED FOR RELEVANCE

U502 NEW B92 CODE ON NEW B9A UR0096 SHIPPING TO MARION, VA.  
TO TRY TO REPEAT ISSUE UNDER TEST.

95SEC → B92 → B9A → B9A → C69

REDACTED FOR RELEVANCE

TUESDAY SYSTEMS PAT @ TLW

10/18/11

REDACTED FOR RELEVANCE

6000 AVG 4502 MILES TO FAILURE. (B9A)

REDACTED FOR RELEVANCE



MONDAY WARRANTY MEETING (ESTES)

10/31/11

REDACTED FOR RELEVANCE

U502 - RON COLLINS HI TEMP DRIVER ISSUES FISHBONE REQ'D.

B9A

EFF DATA @ 25°C - 28°C NOT ALL @ HIGH TEMPS

20°C - 70°C TOTAL RANGE (FROM MICRO.)

HALL EFFECT HARD FAILURE - @ TEMP BIASED REGION OF CHIP.

- ANDY TO INVESTIGATE ED INDICATED EXHAUST AS POSSIBLE FAILURE MODE

113 C200B'S REPORTED ON U502 NOT ALL RETURNED.  
OUT OF IDS.

"EMC" IS ONE AREA NOT CLOSED OUT YET.

- MY FORD TOUCH IMPACT ON HEAT

REDACTED FOR RELEVANCE

MONDAY WARRANTY RETURN MTG

8/23/12

VEIL  
JUNE BLD

REDACTED FOR RELEVANCE

U502.

5-6 GEARS REC'D FROM FIELD EVERY DAY.

SERGIO OUT ON VACATION 3 WEEKS:

TOM  
FLANAGAN

NOV. CLAIMS NOT LOOKED AT & NO DATA LISTED.

CERIE SAID RESOURCES FOCUSED ON B9A + B3A RQMY.

JOHN BURNETT SENT TO HELP SERGIO

QAO POMA RUN CHART • 11/17/11 FIX @ QAO

B3A/A3A/B43  
NEW  
SCRIPT  
IMPLEMENT

11/4 B6B

B51

11/7 B43

1/5 B43

1/11 B9A

PRIOR TO 11/17 LIC COULD

REJECT

B9A, B43, B3A, A3A 1

4-5 LIC  
TO SET FAULT

• 12/1/11 2ND LIC CHECK ADD.

JIM  
PARKER

MICHELLE & SOFTWARE TEAM CONFIRMED MORE THAN

1 LICR REQ'D. TO GET FAULT + REJECT. (3) B9A (4)

-WEDNESDAY-  
2-22-12

REDACTED FOR RELEVANCE

EMERGING  
ISSUE

B6B

2010 INITIAL SAW THESE  
FAILURES

PCS MOTOR CLEARANCE  
ISSUE.

→ US02 NEVER HAD THESE BEFORE.

REDACTED FOR RELEVANCE

SERGIO COULD NOT DUPLICATE

- welding of contacts can be caused by opening under load.

REDACTED FOR RELEVANCE

SALEEM SEMSAR / GEOFF / AP / MSURELLA / TSIDER.

MONDAY WARRANTY REVIEW.

4-30-12

C346

• B45 LINK RELAY - MOTOR BUILD DATE 9-17-12.

• SERGIO: B3A - 10 SUSPECT 4 TO UK

B6B - 5 TO UK.

REDACTED FOR  
RELEVANCE

# MELTED RELAY BASE RELAYS (4) US02

PER MIKE DAVIES - PLAN TO THERMOCOUPLE RELAYS TO  
DETERMINE ROOT CAUSE OF WELDING @ NIDEC.

TE TO SEND RELAYS PRIOR TO APPLYING SEALANT TO RELAYS.

TIG WELDING PROCESS USED. HAVE NOT BEEN ABLE LINK

B3A TO WELDING PROCESS.

THERE ARE 3 WELDING MACHINES IN EACH (2) LINES  
AT NIDEC.

PER GEOFF: 1ST MELTED BASE WAS A B6B.

10 EU & 10 NA MELTED BASE FAILURES (1) B6B, (1) B97, B3A

NEW: \* BUILDING & HAD A B97 RELAY FAILURE, SIMON SENT  
RELAY TO UK <sup>- PHIL BROWNE.</sup> (WAS USED ON PV TESTING)

\* RECENT BENT FINGER ISSUES ATTRIBUTED TO DOWNGAGE  
ISSUE WHERE TOP PARTS WERE SLID ACROSS LOWER  
PARTS BENDING FINGERS. @ ROGERSVILLE

MONDAY 8:30 WARRANTY MEETING  
(ERIC ESTES)

~~10/3/11~~  
10/3/11

U502

B9A SET ONCE @ CHARLSTON S. CAROLINA  
ERIC { BARRY MOSES NOTIFIED OF B9A ISSUE  
(DON ABRAHAMS @ FORD GARAGE (MGT.)

REDACTED FOR RELEVANCE

REDACTED FOR RELEVANCE

(2) U502 } RUNNING TRIP TEMP  
ON FOR 1 MONTH - NOBA DIRECTION

ANTINA HAS 2 EPP LINES NEED TO CONFIRM 1 OR 2 ABOVE  
SACTA'S - NO INFO AVAILABLE YET  
12/25 - 12/28 NOTHING ABNORMAL @ NIDEC.

10/4/11

REDACTED FOR RELEVANCE

CANOPY DATA BOX.

MGT. GARAGE. REQUEST FOR B9A OR LOSS OF ASSIST

GJ/LN TORN DOWN 1 UNIT - 2ND IN PROCESS.

TD - SEND ALL COMPONENTS BACK TO SUPPLIERS FOR ANALYSIS

DAVE RUTKOWSKI CHASSIS SPECIALIST

GEOFF JACKS TRYING TO EXCLUDE SOFTWARE PROBLEM.

ROUNDING ERROR FOUND + CONVINCED NOT VEHICLE FAULT.

U502 - BULLETIN SAYS SWAP GEAR ON 1ST FAULT [CGG LOCK OUT  
CANNOT CLEAR CODES

JOHN BURNETT

MONDAY WARRANTY MTG (ESTES)

9-19-11

U502 B9A

8 SENT TO MARION FROM WARRANTY FRIDAY 9-16-11.

67 @WARRANTY ETR  
TO CHRIS WOODRUF. GEOF JACKS TO SUPPLY TEST PROG

REDACTED FOR RELEVANCE

• ALL PROGRAMS HAVE THE 53° LIMIT INCORPORATED  
IN PRODUCTION NOW REDACTED U502

• GEOF HAS SW VERSIONS & DATES

WORKPLAN: B9A GEOF JACKS

- DISCUSS MOTOR CONTROL w/SPECIALIST FROM MOTOR
- MEASURED FLUX DENSITY BUT NO HYSTERESIS TEST  
NEED TO CONDUCT THIS ON TORN DOWN UNIT.
- RUN ON DYNO TEST w/MODIFIED SW
- BENCH TEST w/SMALL MOVEMENTS NOT ROUND + ROUND
- SYNCHRONIZATION OCCURS w/(1) MOTOR REVOLUTION  
WHAT CAN VIDECON DO TO HELP? LN

ON SEMME ASIC ISSUE

PSD MASK - PARTS APRIL 2012 EST. BEFORE PARTS GET INTO PLANT

---

**From:** Estes, Eric (E.E.)  
**Sent:** Tuesday, June 14, 2011 3:07 PM  
**To:** Anderson, Eric (H.); Napoli, Laura (L.)  
**Cc:** Mrozek, Robert (R.M.)  
**Subject:** RE: 1FMHK7B80BG [REDACTED] please request gear

Heavy load testing at the 2-pin batt. & grd. is needed for this issue, we have found main BJB main battery feed issues and C1617A connector issues at the BJB.

Also need to load test ignition feed, this is not in the workshop manual but this load test is where we have found all our wiring issues on U502, normally hotline advises to perform this operation if CQIS report is used.

I will check the gear for issues when it returns

Eric

---

**From:** Anderson, Eric (H.)  
**Sent:** Tuesday, June 14, 2011 2:33 PM  
**To:** Napoli, Laura (L.)  
**Cc:** Estes, Eric (E.E.); Mrozek, Robert (R.M.)  
**Subject:** RE: 1FMHK7B80BG [REDACTED] please request gear

The tech did say he performed all the electrical tests the workshop manual and hotline directed him too. Looking up U0131 and C1B00:29 in the workshop manual both eventually lead techs to replace the gear after following electrical test steps AC1, AC2, AC3 and AC4. We'll have to see if there's anything new to learn from the gear when it's returned. Is there anything like this on REDACTED FOR

VERIFY NO POWER STEERING AND ADVANCE TRAC LIGHT ON. CHECK FOR CODES NO COMM WITH PSCM, ABS U0131, C1B00, IPC U0131. CHECK OASIS FOR SSM OR TSB NONE FOUND. CHECK UNDERHOOD FUSE OK. FOLLOW PINPOINT TESTS AC1 CHECK FOR VOLTAGE TO PSCM 12 VOLTS OK. AC2 CHECK GROUND WIRE 2 OHMS OK. AC3 CHECK HS CAN CIRCUITS ALL OK. AC4 CHECK CONNECTORS ALL OK. VERIFY ALL CONNECTORS ARE TIGHT AND WIGGLE TEST ALL OK. RE

---

**From:** Napoli, Laura (L.)  
**Sent:** Tuesday, June 14, 2011 12:48 PM  
**To:** Anderson, Eric (H.); Cassata, Joe (J.)  
**Cc:** Estes, Eric (E.E.); Mrozek, Robert (R.M.)  
**Subject:** RE: 1FMHK7B80BG [REDACTED] please request gear

Why are they pulling gears? Are they being instructed to do so? There's a lot on the electrical side to check before pulling a gear besides the fuse. There are no EPAS codes so I don't see why they pulled the gear. New gear fixing the problem doesn't mean it won't come back if the whole electrical system wasn't checked.

---

**From:** Anderson, Eric (H.)  
**Sent:** Tuesday, June 14, 2011 1:09 PM  
**To:** Cassata, Joe (J.)  
**Cc:** Napoli, Laura (L.); Estes, Eric (E.E.)  
**Subject:** 1FMHK7B80BG [REDACTED] please request gear

Hi Joe:

Here's another one today. Please request it to Eric Estes at WPAC, TR-EE.

Laura and Eric,

Here are my notes from my conversation with the tech. Any news on a communication problem in gears?

Called dealership. Tech pulled U0131:00-AB, C1B00:29-68, U0131:00-2F. Customer lost assist at ignition, would not return with multiple key cycles. Tech pulled and reinserted steering fuse, assist returned briefly. Assist lost again a few hours later. Could not be regained with fuse pull method. New gear fixed problem. Part requested.

Thanks,

Eric Anderson  
PVT Engineer  
Ford Chicago Assembly  
773.646.7236 desk  
773.729.0337 cell  
eande181@ford.com

Server: **AWS Prod**  
Claims loaded through: **13-JUN-2011**

## Claim Detail Report

*Note: All costs are in US dollars*

**Model Year** = 2011; **Claim Key** = 556186

### Vehicle Information

Model Year: 2011

Market Derived: F - FORD

Body/Cab Type: T/WD - 4 DOOR WAGON

Version/Series: T/EF-FORD SERIES

Drive Type: T/A-2 WHL L/H FRONT  
DRIVE

Vehicle Line: T/UB-EXPLORER [11-12]

Warranty Start Date: 25-MAY-11

Production Date: 18-APR-11

VIN: 1FMHK7B80BG [REDACTED]

### Claim Information

Document Number: 04137001

Repair Date: 04-JUN-11

Distance: 872

TIS: 1

### Dealer Information:

Dealer Name NEW BRIGHTON FORD,  
INC.

Dealer Code: 08452 - \*

### Expense Information

Customer Paid Amount: .00

Deductible Amount: .00

Dealer Paid Amount: .00



Address: 1100 SILVER LAKE ROAD Labor Cost: 284.15  
 City: NEW BRIGHTON Misc. Expense Amount: .00  
 State: MN Zip Code: 55112 Part Markup Amount: 299.10  
 Country: USA Region Code: NA Material Cost: 1046.86  
 Phone: (651)633-9010 Total Cost Gross: 1331.01

Cust.  
 Concern: H22 - STEERING REQUIRES EXTRA OR UNEVEN EFFORT  
 Code:

Condition: 42 - DOES NOT OPERATE PROPERLY  
 Code:

Technician Comment: VERIFY NO POWER STEERING AND ADVANCE TRAC LIGHT ON. CHECK FOR CODES NO COMM WITH PSCM, ABS U0131, C1B00, IPC U0131. CHECK OASIS FOR SSM OR TSB NONE FOUND. CHECK UNDERHOOD FUSE OK. FOLLOW PINPOINT TESTS AC1 CHECK FOR VOLTAGE TO PSCM 12 VOLTS OK. AC2 CHECK GROUND WIRE 2 OHMS OK. AC3 CHECK HS CAN CIRCUITS ALL OK. AC4 CHECK CONNECTORS ALL OK. VERIFY ALL CONNECTORS ARE TIGHT AND WIGGLE TEST ALL OK. RE

Customer Comment: STEERING & SUSPENSIO CUSTOMER STATES THE POWER STEERING IS INOP

<u>Labor Op Code</u>	<u>Labor Op Description</u>	<u>Labor Op Cost</u>
12651D	BODY / CHASSIS / ELECTRIAL (BCE) TEST	21.05
12651D45		31.57
12651DX1	EXTRA TIME TO REPEAT FINAL QUICK TEST	10.52
3001A1T	CASTER, CAMBER AND TOE-IN CORRECT	94.72
MTPROGRAM		31.57
MT3504		94.72

<u>Causal Flag</u>	<u>Full Part Number</u>	<u>Part Description</u>	<u>Part CPSC</u>	<u>Part Quantity</u>	<u>Extended Amount</u>
Y	BB5Z 3504 HE	GEAR ASY-STEERING	110101	1	1046.86

**DTC Sections:**

**Mil. Light On =\***

<u>Flag</u>	<u>Test Type</u>	<u>Malfunction Cd</u>	<u>Malfunction Cd Description</u>	<u>Monitor Cd</u>	<u>Monitor Cd Description</u>
CHAS		C1B00			
UNDF		U0131			

Any comments? You can contact

<< OLE Object: Picture (Metafile) >> [webmaster](#)

3508

---

**From:** Mrozek, Robert (R.M.)  
**Sent:** Monday, March 28, 2011 2:16 PM  
**To:** Napoli, Laura (L.)  
**Subject:** RE: 1FMHK8F83BG [REDACTED] p/s inop

This is a warranty claim and not a 0km claim.

*Rob Mrozek*

Electric Power Steering Supervisor  
CD3/D3/D4/U502/Police/Limo EPAS Programs +  
Active Front Steering Applications Engineering  
Ford Motor Company  
Phone: (313) 805-5947  
e-mail: [rmrozek@ford.com](mailto:rmrozek@ford.com)

---

**From:** Napoli, Laura (L.)  
**Sent:** Monday, March 28, 2011 1:11 PM  
**To:** Anderson, Eric (H.); Mrozek, Robert (R.M.)  
**Cc:** Estes, Eric (E.E.); ruckerlimosine@comcast.net  
**Subject:** RE: 1FMHK8F83BG [REDACTED] p/s inop

Did you contact James Rucker about this gear? From this point on, I'd like to follow the normal process for all failed gears. QR TRW, contact James to pick up the gear, and he will send it to 26mile or Marion, depending on the failure.

---

**From:** Anderson, Eric (H.)  
**Sent:** Monday, March 28, 2011 12:13 PM  
**To:** Napoli, Laura (L.); Mrozek, Robert (R.M.)  
**Cc:** Estes, Eric (E.E.)  
**Subject:** 1FMHK8F83BG [REDACTED] p/s inop

Hi Laura and Rob:

FYI. Another B3A power steering inop claim. Part has been requested to go to John Burnett at TRW.

Server: **AWS Prod**  
Claims loaded through: **25-MAR-2011**

## Claim Detail Report

*Note: All costs are in US dollars*

**Model Year** = 2011; **Claim Key** = 315373

### Vehicle Information

Model Year: 2011

### Claim Information

Document Number: 431545A

Market Derived: F - FORD  
 Repair Date: 22-MAR-11  
 Body/Cab Type: T/WD - 4 DOOR WAGON  
 Distance: 1425  
 Version/Series: T/EF-FORD SERIES  
 TIS: 3  
 Drive Type: T/F-4 WHL L/H FULL TIME DRIVE  
 Vehicle Line: T/UB-EXPLORER [11-12]  
 Warranty Start Date: 03-JAN-11  
 Production Date: 22-NOV-10  
 VIN: 1FMHK8F83BG [REDACTED]

**Expense Information**

**Dealer Information:**

<u>Dealer Name</u> BEECHMONT FORD INC	Customer Paid Amount: .00
Dealer Code: 02058 - *	Deductible Amount: .00
Address: 600 OHIO PIKE	Dealer Paid Amount: .00
City: CINCINNATI	Labor Cost: 217.57
State: OH Zip Code: 452452118	Misc. Expense Amount: .00
Country: USA Region Code: NA	Part Markup Amount: 293.04
Phone: (513)752-6611	Material Cost: 1025.64
	Total Cost Gross: 1243.21

Cust.  
 Concern H22 - STEERING REQUIRES EXTRA OR UNEVEN EFFORT  
 Code:

Condition 42 - DOES NOT OPERATE PROPERLY  
 Code:

Technician TEST DROVE VEH AND HAD NO POWER STEERING IDS TESTED AND GOT  
 Comment: DTC U2011:49 48 U2011:61 48 U3000:96 C8 CONTACTED HOT LINE AND  
 THEY RECOMMENDED TO REPLACED THE PSCM REPLACED THE PSCM  
 RACK ASY PERFORMED PMI AND PERFORMED ALIGNMENT TEST  
 DROVE VEH AND NORMAL OPERATION

Customer THE POWER STEERING ASST. FAULT IS ON AND VEHICLE IS VERY  
 Comment: TOUGH TO STEER HAS HAPPEND OTHER TIMES THIS IS THE SECOND

TIME ITS IN FOR THIS

<u>Labor Op Code</u>	<u>Labor Op Description</u>	<u>Labor Op Cost</u>
3504E		16.12
3504E45		24.17
3504E8		8.06
3504E46		8.06
MT3504		161.16

<u>Causal</u>	<u>Full Part Number</u>			<u>Part</u>	<u>Part</u>	<u>Extended</u>	
<u>Flag</u>	<u>PREF</u>	<u>BASE</u>	<u>SUFF</u>	<u>Description</u>	<u>CPSC</u>	<u>Quantity</u>	
						<u>Amount</u>	
Y	BB5Z	3504	CE	GEAR ASY-STEERING	110101	1	1025.64

DTC Sections:

Mil. Light On =\*

<u>Fla</u>	<u>Test</u>	<u>Malfunction Cd</u>	<u>Malfunction Cd</u>	<u>Monitor</u>	<u>Monitor Cd</u>
<u>g</u>	<u>Type</u>		<u>Description</u>	<u>Cd</u>	<u>Description</u>

Any comments? You can contact

<< OLE Object: Picture (Metafile) >> [webmaster](#)

1112

Ford Chicago Assembly  
773.646.7236 desk  
773.729.0337 cell  
[eande181@ford.com](mailto:eande181@ford.com)

---

**From:** Anderson, Eric (H.)  
**Sent:** Monday, March 28, 2011 2:14 PM  
**To:** Napoli, Laura (L.)  
**Subject:** RE: 1FMHK8F83BG [REDACTED] p/s inop

Hi Laura:

I did not contact James Rucker about this failed gear. This is a warranty claim, so I only get it after the part has been replaced. Unfortunately, snapshot data is not available with most warranty claims. I have put in a hot part request for the gear. It will be sent to John Burnett.

For gears that become inoperative in the plant with known DTC codes (U2011, U3000, C200B, C200C), I've started using the normal incoming quality process with James.

Thanks,

Eric

---

**From:** Napoli, Laura (L.)  
**Sent:** Monday, March 28, 2011 12:11 PM  
**To:** Anderson, Eric (H.); Mrozek, Robert (R.M.)  
**Cc:** Estes, Eric (E.E.); ruckerlimosine@comcast.net  
**Subject:** RE: 1FMHK8F83BG [REDACTED] p/s inop

Did you contact James Rucker about this gear? From this point on, I'd like to follow the normal process for all failed gears. QR TRW, contact James to pick up the gear, and he will send it to 26mile or Marion, depending on the failure.

---

**From:** Anderson, Eric (H.)  
**Sent:** Monday, March 28, 2011 12:13 PM  
**To:** Napoli, Laura (L.); Mrozek, Robert (R.M.)  
**Cc:** Estes, Eric (E.E.)  
**Subject:** 1FMHK8F83BG [REDACTED] p/s inop

Hi Laura and Rob:

FYI. Another B3A power steering inop claim. Part has been requested to go to John Burnett at TRW.

Server: **AWS Prod**

Claims loaded through: **25-MAR-2011**

## Claim Detail Report

*Note: All costs are in US dollars*

**Model Year** = 2011; **Claim Key** = 315373

### Vehicle Information

Model Year: 2011

### Claim Information

Document Number: 431545A

Market Derived: F - FORD  
 Repair Date: 22-MAR-11  
 Body/Cab Type: T/WD - 4 DOOR WAGON  
 Distance: 1425  
 Version/Series: T/EF-FORD SERIES  
 TIS: 3  
 Drive Type: T/F-4 WHL L/H FULL TIME DRIVE  
 Vehicle Line: T/UB-EXPLORER [11-12]  
 Warranty Start Date: 03-JAN-11  
 Production Date: 22-NOV-10  
 VIN: 1FMHK8F83BG [REDACTED]

**Expense Information**

**Dealer Information:**

<u>Dealer Name</u> BEECHMONT FORD INC	Customer Paid Amount:	.00
Dealer Code: 02058 - *	Deductible Amount:	.00
Address: 600 OHIO PIKE	Dealer Paid Amount:	.00
City: CINCINNATI	Labor Cost:	217.57
State: OH Zip Code: 452452118	Misc. Expense Amount:	.00
Country: USA Region Code: NA	Part Markup Amount:	293.04
Phone: (513)752-6611	Material Cost:	1025.64
	Total Cost Gross:	1243.21

Cust.  
 Concern H22 - STEERING REQUIRES EXTRA OR UNEVEN EFFORT  
 Code:

Condition 42 - DOES NOT OPERATE PROPERLY  
 Code:

Technician TEST DROVE VEH AND HAD NO POWER STEERING IDS TESTED AND GOT  
 Comment: DTC U2011:49 48 U2011:61 48 U3000:96 C8 CONTACTED HOT LINE AND  
 THEY RECOMMENDED TO REPLACED THE PSCM REPLACED THE PSCM  
 RACK ASY PERFORMED PMI AND PERFORMED ALIGNMENT TEST  
 DROVE VEH AND NORMAL OPERATION

Customer THE POWER STEERING ASST. FAULT IS ON AND VEHICLE IS VERY  
 Comment: TOUGH TO STEER HAS HAPPEND OTHER TIMES THIS IS THE SECOND



TIME ITS IN FOR THIS

<u>Labor Op Code</u>	<u>Labor Op Description</u>	<u>Labor Op Cost</u>
3504E		16.12
3504E45		24.17
3504E8		8.06
3504E46		8.06
MT3504		161.16

<u>Causal Flag</u>	<u>Full Part Number</u>			<u>Part Description</u>	<u>Part CPSC</u>	<u>Part Quantity</u>	<u>Extended Amount</u>
	<u>PREF</u>	<u>BASE</u>	<u>SUFF</u>				
Y	BB5Z	3504	CE	GEAR ASY-STEERING	110101	1	1025.64

DTC Sections:

Mil. Light On =\*

<u>Flag</u>	<u>Test Type</u>	<u>Malfunction Cd</u>	<u>Malfunction Cd Description</u>	<u>Monitor Cd</u>	<u>Monitor Cd Description</u>
-------------	------------------	-----------------------	-----------------------------------	-------------------	-------------------------------

Any comments? You can contact

<< OLE Object: Picture (Metafile) >> [webmaster](#)

1112

Ford Chicago Assembly  
773.646.7236 desk  
773.729.0337 cell  
[eande181@ford.com](mailto:eande181@ford.com)

---

**From:** Napoli, Laura (L.)  
**Sent:** Monday, March 28, 2011 1:34 PM  
**To:** Anderson, Eric (H.); Mrozek, Robert (R.M.)  
**Cc:** Estes, Eric (E.E.)  
**Subject:** RE: 1FMHK8F83BG [REDACTED] p/s inop

Did you take snapshot data? How do you know it's B3A? Please send snapshot data if you have it.

---

**From:** Anderson, Eric (H.)  
**Sent:** Monday, March 28, 2011 12:13 PM  
**To:** Napoli, Laura (L.); Mrozek, Robert (R.M.)  
**Cc:** Estes, Eric (E.E.)  
**Subject:** 1FMHK8F83BGA02503 p/s inop

Hi Laura and Rob:

FYI. Another B3A power steering inop claim. Part has been requested to go to John Burnett at TRW.

Server: **AWS Prod**

Claims loaded through: **25-MAR-2011**

## Claim Detail Report

*Note: All costs are in US dollars*

**Model Year** = 2011; **Claim Key** = 315373

### Vehicle Information

Model Year: 2011

Market Derived: F - FORD

Body/Cab Type: T/WD - 4 DOOR WAGON

Version/Series: T/EF-FORD SERIES

Drive Type: T/F-4 WHL L/H FULL TIME  
DRIVE

Vehicle Line: T/UB-EXPLORER [11-12]

Warranty Start Date: 03-JAN-11

Production Date: 22-NOV-10

VIN: 1FMHK8F83BG [REDACTED]

### Claim Information

Document Number: 431545A

Repair Date: 22-MAR-11

Distance: 1425

TIS: 3

### Expense Information

**Dealer Information:**

<u>Dealer Name</u> BEECHMONT FORD INC	Customer Paid Amount:	.00
Dealer Code: 02058 - *	Deductible Amount:	.00
Address: 600 OHIO PIKE	Dealer Paid Amount:	.00
City: CINCINNATI	Labor Cost:	217.57
State: OH Zip Code: 452452118	Misc. Expense Amount:	.00
Country: USA Region Code: NA	Part Markup Amount:	293.04
Phone: (513)752-6611	Material Cost:	1025.64
	Total Cost Gross:	1243.21

Cust.  
 Concern **H22 - STEERING REQUIRES EXTRA OR UNEVEN EFFORT**  
 Code:

Condition  
 Code: **42 - DOES NOT OPERATE PROPERLY**

Technician TEST DROVE VEH AND HAD NO POWER STEERING IDS TESTED AND GOT  
 Comment: DTC U2011:49 48 U2011:61 48 U3000:96 C8 CONTACTED HOT LINE AND  
 THEY RECOMMENDED TO REPLACED THE PSCM REPLACED THE PSCM  
 RACK ASY PERFORMED PMI AND PERFORMED ALIGNMENT TEST  
 DROVE VEH AND NORMAL OPERATION

Customer THE POWER STEERING ASST. FAULT IS ON AND VEHICLE IS VERY  
 Comment: TOUGH TO STEER HAS HAPPEND OTHER TIMES THIS IS THE SECOND  
 TIME ITS IN FOR THIS

<u>Labor Op Code</u>	<u>Labor Op Description</u>	<u>Labor Op Cost</u>
3504E		16.12
3504E45		24.17
3504E8		8.06
3504E46		8.06
MT3504		161.16

Causal	Full Part Number	Part	Part	Extended
--------	------------------	------	------	----------

<u>Flag</u>	<u>PREF</u>	<u>BASE</u>	<u>SUFF</u>	<u>Description</u>	<u>CPSC</u>	<u>Quantity</u>	<u>Amount</u>
Y	BB5Z	3504	CE	GEAR ASY-STEERING	110101	1	1025.64

DTC Sections:

Mil. Light On =\*

<u>Flag</u>	<u>Test Type</u>	<u>Malfunction Cd</u>	<u>Malfunction Cd Description</u>	<u>Monitor Cd</u>	<u>Monitor Cd Description</u>
-------------	------------------	-----------------------	-----------------------------------	-------------------	-------------------------------

Any comments? You can contact

<< OLE Object: Picture (Metafile) >> [webmaster](mailto:webmaster)

1112


Eric Anderson  
PVT Engineer  
Ford Chicago Assembly  
773.646.7236 desk  
773.729.0337 cell  
[eande181@ford.com](mailto:eande181@ford.com)

---

**From:** Estes, Eric (E.E.)  
**Sent:** Monday, July 25, 2011 12:20 PM  
**To:** Anderson, Eric (H.); Napoli, Laura (L.)  
**Cc:** Mrozek, Robert (R.M.)  
**Subject:** RE: 1FMHK8F85BGA61262 EPAS inop

Most EPAS gear returns will have a U3000 code, U3000-96 codes sets with most of the relay or all other electronic failure codes that set three times within three ignition cycles and most internal electronic failure's are U3000-49. Most of the internal U3000-49 codes are separate electronic failures(see the attached warranty chart).

Here is the latest U502 warranty paynter-pareto chart



Eric

---

**From:** Anderson, Eric (H.)  
**Sent:** Monday, July 25, 2011 11:53 AM  
**To:** Napoli, Laura (L.)  
**Cc:** Estes, Eric (E.E.); Mrozek, Robert (R.M.)  
**Subject:** RE: 1FMHK8F85BGA61262 EPAS inop

Do we have a root cause for U3000 codes then? I just got another one today. Should I open a new project and make it red red?

---

**From:** Napoli, Laura (L.)  
**Sent:** Monday, July 25, 2011 10:49 AM  
**To:** Anderson, Eric (H.); Cassata, Joe (J.)  
**Cc:** Estes, Eric (E.E.); Mrozek, Robert (R.M.)  
**Subject:** RE: 1FMHK8F85BGA61262 EPAS inop

Eric,

These are not B3A gears. U2011-49 is the B3A DTC with a PCA date of 7/11. We received 2 B3A gears recently which had build dates of last year.

---

**From:** Anderson, Eric (H.)  
**Sent:** Tuesday, July 19, 2011 10:23 AM  
**To:** Cassata, Joe (J.)  
**Cc:** Estes, Eric (E.E.); Napoli, Laura (L.); Mrozek, Robert (R.M.)  
**Subject:** 1FMHK8F85BGA61262 EPAS inop

Hi Joe:

Please request this gear to Eric Estes at WPAC, TR EE.

Eric, Laura and Rob,  
These U3000 faulted gears continue to come. This unit was built 5/2/11. Do you still have confidence in the July 11 PCA date?

Thanks,

Eric Anderson  
PVT Engineer  
Ford Chicago Assembly  
773.646.7236 desk  
773.729.0337 cell  
[eande181@ford.com](mailto:eande181@ford.com)

Server: **AWS Prod**

Claims loaded through: **18-JUL-2011**

## Claim Detail Report

*Note: All costs are in US dollars*

**Model Year = 2011; Claim Key = 687210**

### Vehicle Information

Model Year: **2011**

Market Derived: **F - FORD**

Body/Cab Type: **T/WD - 4 DOOR WAGON**

Version/Series: **T/EF-FORD SERIES**

Drive Type: **T/F-4 WHL L/H FULL TIME  
DRIVE**

Vehicle Line: **T/UB-EXPLORER [11-12]**

Warranty Start Date: **23-MAY-11**

Production Date: **02-MAY-11**

VIN: **1FMHK8F85BG** XXXXXXXXXX

### **Dealer Information:**

Dealer Name **CHARLES GABUS FORD**

Dealer Code: **03334 - \***

Address: **4545 MERLE HAY RD**

City: **DES MOINES**

### Claim Information

Document Number: **515439A**

Repair Date: **11-JUL-  
11**

Distance: **4666**

TIS: **2**

### Expense Information

Customer Paid Amount: **.00**

Deductible Amount: **.00**

Dealer Paid Amount: **.00**

Labor Cost: **406.23**

Misc. Expense Amount: **.00**

State: **IA** Zip Code: **50310** Part Markup Amount: **434.38**  
 Country: **USA** Region Code: **NA** Material Cost: **1520.32**  
 Phone: **(515)270-0707** Total Cost Gross: **1926.55**

Cust.  
 Concern **H22 - STEERING REQUIRES EXTRA OR UNEVEN EFFORT**  
 Code:

Condition **42 - DOES NOT OPERATE PROPERLY**  
 Code:

Technician **VERIFY CONCERN HOOK UP IDS AND RUN SELF TESTS PULLED CODES**  
 Comment: **U3000:49 8A PSCM AND U3000:96 C8 PSCM RUN PIN POINT TESTS**  
**INTERNAL FAULT REPLACE PSCM ORDERED PARTS REPLACE PS RACK**  
**OR PSCM VERIFY REPAIR AND ALIGN FRONT END SET TOE**

Customer **CUSTOMER STATES THAT THE POWER STEERING QUIT WORKING**  
 Comment: **BARELY ABLE TO STEER INSPECT AND ADVISE**

<u>Labor Op Code</u>	<u>Labor Op Description</u>	<u>Labor Op Cost</u>
3504E		17.66
3504E45		26.49
3504E8		8.83
MT3504A		309.09
MT3001A		44.16

<u>Causal</u>	<u>Full Part Number</u>			<u>Part</u>	<u>Part</u>	<u>Extended</u>	
<u>Flag</u>	<u>PREF</u>	<u>BASE</u>	<u>SUFF</u>	<u>Description</u>	<u>CPSC</u>	<u>Quantity</u>	<u>Amount</u>
Y	BB5Z	3504	JE	GEAR ASY-STEERING	110101	1	1520.32

DTC Sections: **Mil. Light On =N**

<u>Fla</u>	<u>Test</u>	<u>Malfunction Cd</u>	<u>Malfunction Cd</u>	<u>Monitor</u>	<u>Monitor Cd</u>
<u>g</u>	<u>Type</u>		<u>Description</u>	<u>Cd</u>	<u>Description</u>



Any comments? You can contact

<< OLE Object: Picture (Metafile) >> [webmaster](#)

9452

Case Number	Ford DTCs	TRW Code (Symptom)	Component	Gear Location	Current Updates	Issue Status	Gear location	Report State	Verbatim	Assigned To	Root Cause	P&A Code/ Dealer Name/ Dealer State	Miles	Snap Shot Data (if known)	TRW Fault (fault store codes)	VIN	Vehicle Build Date	Gear Build Date	ECU Build Date	EPP Build Date	Eng. Type	Date of Repair	Model Year	Date	Part ETA	
OKM BGA41610	C200B-62	BD4	TS	CAP												1FMHK8F81BGA	3/16/2011				3.5L w/APA	3/16/2011				
OKM BGA30310	No Assist	?		CAP	no returned part from CAP																3.5L w/APA					
UR0003	C200B-2F C200B-62	BD0,BD2, BD4	TS	In Eval (MAO)	5/23- made decision to keep 400% inspection in place for PCA. But to follow through on the parts req. so if we do find a bent finger to order parts for reflection gage on station 50.	2/4- seen interactive diagnosis for the codes and the dealer ordered an EPAS gear. Put hot process request to be returned to WPAC. 2/9- dealer will ship out part once 700 tag is assigned, should be tomorrow. Then part should arrive at WPAC by Monday 2/14. 4/6- need to discuss next week the poke yokes designed at station 50 to check for bent veins/fingers on the torque sensor. Andrew Bradley will join in the discussion to assist Marion to find a reasonable PCA. QAO will also be involved with the discussion. 5/3- have parts request in for TS check at station 50 on one line at MAO. Update timing chart for implementation. 5/10- sent the timing plan and needs to update with PPAP and production timing					07955 Ron Dupratt Ford	15			1FMHK8D87BC	1/24/2011	1/17/2011	11/16/2010	11/22/2010	3.5L wo/APA	2/2/2011					
UR0004	U3000-96	EF5		In Eval (26mile)	5/2- NTF with the testing on this gear at 26mile. UK testing another similar NV ram issue, NTF with that unit at this time. I will keep in pending to see if we get any other returns.	2/21- 700 tag should generate today, hoping to get the gear back to WPAC for initial analysis. 2/22- dealer ordered wrong steering gear, now waiting for new part with AP feature to be sent through the Ford parts			CHECK THE P S JUST WENT OUT WENT TO TEST DRIVE VEHICLE AND COULD NOT GET IT TO TURN AT ALL REALLY. PULLED VEHICLE INTO STALL. PULLED CODES HAD U3000:96. PULLED OASIS NO TSB, NO SSM. DID SOME PIN POINT TEST, AND EEG TEST. SENT HOTLINE INFO.			00089 Koons Ford	303			1FMHK8F8XBC	1/20/2011	1/19/2011	12/1/2010	12/4/2010	3.5L w/APA	2/12/2011				
UR0007	loud growl noise gear hard to turn		NVH	At CAP, unknown location	5/3- found out the gear was shipped to CAP unknown who has the gear at this time.	3/3- talked to tech states vehicle is hard to turn the wheel even on the hoist, no boot damage only code tech states he had U0253 which is not a PSCM code advise tech to call back with more			WEB FORM DATA - CONCERN: STEERING ASSIST IS INOP, LOUD GROWLING NOISE WHEN ATTEMPTING TO TURN THE STEERING WHEEL DIAGNOSTICS: VISUAL INSPECTION IS OK, NO VISIBLE SIGNS OF CAUSE, GROWLING NOISE			08398 Don Aadsen Ford	18			1FMHK8F86BC	1/31/2011				3.5L wo/APA	3/2/2011				



Case Number	Ford DTCs	TRW Code (Symptom)	Component	Gear Location	Current Updates	Issue Status	Gear location	Report State	Verbatim	Assigned To	Root Cause	P&A Code/ Dealer Name/ Dealer State	Miles	Snap Shot Data (if known)	TRW Fault (fault store codes)	VIN	Vehicle Build Date	Gear Build Date	ECU Build Date	EPP Build Date	Eng. Type	Date of Repair	Model Year	Date	Part ETA		
OKM BGA59863	steering noise on full left stop		NVH	In Eval (26mile)	5/9- mark on the ITR that indicates the ITR over articulated, the gear was dropped or impacted before assembly in the vehicle. Maron.ZF or MAP the gear could be dropped. No marks on the EPAS housing. Unknown source at this time.	5/2- shipped direct to 26mile over articulated. 5/4- found right side tie rod bent, cannot find out how this happens, waiting for Ford to instruct next steps.							34			BC											
UR0001 RUA# 4308	U2011-49	B3A	EPP	In Eval (Tyco)	3/9- have implemented some containment actions. Starting today Tyco will heat treat(150deg for 1.5hrs) 100% of the rivets from Doduco to reduce contact resistance. 3/2 start shipping rivets weekly to U of Madrid for SEMEDX analysis. Sorting of Ford stoc	2/21- waiting on Duduco line audit information and also looking to get Tyco's presentation to send to Ford. Still at this time no new information on where the contamination came from. 3/9- have implemented some containment actions. Starting today Tyco will					09618 Brown Motors	18				1FMHK8D83B	12/16/2010				3.5L w/APA	1/12/2011					
UR0002 (UR0008) RUA# 4384	U2011-49 U3000-96	B3A	EPP	In Eval (Tyco)	3/9- have implemented some containment actions. Starting today Tyco will heat treat(150deg for 1.5hrs) 100% of the rivets from Doduco to reduce contact resistance. 3/2 start shipping rivets weekly to U of Madrid for SEMEDX analysis. Sorting of Ford stoc	2/21- waiting on Duduco line audit information and also looking to get Tyco's presentation to send to Ford. Still at this time no new information on where the contamination came from. 3/9- have implemented some containment actions. Starting today Tyco will					02071 I-77 Ford	10				1FMHK8D83B	1/12/2011		11/11/2010	11/13/2010	3.5L w/APA	1/28/2011					
UR0005 RUA# 4498	U2011-49	B3A	EPP	In Eval (Tyco)	3/16- confirmed Mag.sulfur sodium contamination, same as UR1 & UR2, here are the changes that are being made at Doduco before the next batch build that will be supervised by Tyco & TRW. Contaminants such as bucket washing and new sulphur bath to be implem	3/3- pulled snap shot data that has B3A, gear now in process to 26mile for analysis. 3/4- will arrive at 26mile this afternoon for analysis. Will hook up surrogate relay over the weekend if no codes set will remove the relay and ship to Tyco for test when					Ford Management Lease Car- Chicago	1700				1FMHK8F88B	11/22/2010	11/14/2010	9/21/2010	9/24/2010	3.5L w/APA	3/1/2011					
UR0006 RUA# 4529	U2011-49	B3A	EPP	In Eval (Tyco)	5/4- Tyco confirmed this as a Mg.Na.S failure.	3/7- customer will drop off vehicle at VSC garage for replacement as soon as MAO gear arrives at the VSC center. I will pick-up the gear after					Ford PDC Fleet vehicle- Taras Palczynsk	2010				1FMHK7D89B	11/16/2010	11/9/2010	9/13/2010	9/16/2010	3.5L w/APA	3/7/2011					
UR0010 RUA# 4585	U2011-49	B3A	EPP	In Eval (Tyco)	5/4- Tyco confirmed this as a Mg.Na.S failure.	4/1- picked up gear from WHQ VSC garage, pulled EFF and stored data. 4/4 John Burnett will install surrogate relay and test ambient if testing passes will remove relay and ship to					lease management vehicle WHQ VSC	1838				1FMHK8F89B	11/18/2010	11/14/2010	9/21/2010	9/24/2010	3.5L w/APA	3/29/2010					
UR0011 RUA# 4621	U2011-49	B3A	EPP	At Dealer	5/4- Tyco confirmed this as a Mg.Na.S failure.	3/30- checked interactive diagnostic's intermittent B3A sets to ship gear back to 26mile for analysis.					04331 Brondes Ford					1FMHK7F87B	2/24/2011				3.5L w/APA	3/28/2011					
UR0012 RUA# 4596	U2011-49 U2011-61 U3000-96	B3A, B95	EPP	In Eval (Tyco)	5/4- Tyco confirmed this as a Mg.Na.S failure.	4/1- shipped from the dealer to CAP then to 26mile for testing, install surrogate relay test with					02058 Beechmo nt Ford	1425				1FMHK8F83B	11/22/2010										
UR0013 RUA# 4601	U2011-49	B3A	EPP	In Eval (26mile)	5/4- Tyco confirmed this as a Mg.Na.S failure.	4/8- Arrived at 26mile for testing, will not make the workshop will install surrogate relay and test 4/13- done testing with the surrogate relay will ship relay to					00807 Crest Ford	115				1FMHK8F85B	2/16/2011				3.5L w/APA	3/9/2011					
UR0014 RUA# 4618	U2011-49 U3000-96	B3A	EPP	In Eval (26mile)	5/4- Tyco confirmed this as a Mg.Na.S failure.	4/11- pulled fault store and EFF data, shipped gear to 26mile for further testing 4/13- testing with surrogate relay if passes will ship out relay to UK					03820 Landers Ford	3096				1FMHK8F8XB	11/3/2010				3.5L w/APA	3/5/2011					
UR0015 RUA# 4619	U2011-49 U3000-96	B3A	EPP	In Eval (26mile)	5/4- Tyco confirmed this as a Mg.Na.S failure.	4/11- pulled fault store and EFF data, shipped gear to 26mile for further testing 4/13- testing with surrogate					00807 Crest Ford	1356				1FMHK7B87B	11/16/2010				3.5L w/APA	2/25/2011					
UR0016	TC lamp on	no codes		Ship to 26mile for storage	4/26- pulled stored data from gear no codes stored in gear, check CQIS data and found the RCM fixed the vehicle. Cannot chargeback the gear to the dealer because hotline advised to change						02761 Southgate Ford	249				1FMHK7D82B	3/8/2011	3/3/2011			3.5L w/APA	3/30/2011					
UR0017	TC lamp on	no codes		Ship to 26mile for storage	4/29- pulled stored data from gear no codes stored in gear, check CQIS data and found the RCM fixed the vehicle. Cannot chargeback the gear to the dealer because hotline advised to change				CUST REPORTS T/C LIGHT STAYING ON. TECH VERIFIED THIS CONCERN SELF TEST CODE C-1B00-64 FROM ABS MODULE. TECH REPORTS NO CODES FROM RCM. TECH REPORTS REPLACED THE STEERING RACK PER NHL RECOMMENDATION. TECH REPORTS VEHICLE STILL HAS T/C LIGHT ON CONCERN. RECONTACTED NHL WAS INFORMED TO REPLACE THE RCM. TECH REPLACED THE RCM REPORTS NORMAL T/C LIGHT FUNCTION NO RETURN CODES. TECH IS NOW SEEKING APPROVAL CODE FOR RCM REPAIR					02731 Atchinson Ford	111				1FMHK8D89B	3/4/2011	3/1/2011		3.5L w/APA	3/31/2011			

UR0018	TC lamp on	no codes		at 26mile storage	5/12- pulled stored data from gear no codes stored in gear, check CQIS data and found the RCM fixed the vehicle. Cannot changeback the gear to the dealer because hotline advised to change					WEB FORM DATA - CONCERN: ADVANCE TRAC LIGHT ON DIAGNOSTICS: RUN OASIS NO TBSBS FOUND ROADTEST VEH PARTS REPLACED: NONE TECH QUESTION: THIS IS A NEW VEH WITH ABS DTC C1B00:64-68 IN MEMORY. I CLEARED THE DTC WENT APPROX 1 MILE HIT THE BRAKES TRACTION CONTROL ACTIVATED AND LAMP CAME BACK ON. SAME DTC SET AGAIN ANY KNOWN CONCERNS, REPAIRS OR SUGGESTIONS BEFORE I START WITH NORMAL DIAGNOSTICS? WERE YOU ABLE TO VERIFY THE CONCERN? YES IS THERE AN APPROPRIATE PINPOINT TEST IN THE WSM FOR THIS CONCERN? YES WAS THE PINPOINT TEST FOLLOWED? NO TECHNICIAN REPLY: OK I CHECKED PIN FIT AT ABS MODULE ALL TEST OK. DID FIND I CAN GET FALSE ACTIVATION GOING STRAIGHT ALSO MONITORED PID FOUND THAT STEERING WHEEL ANGLE SENSOR READS AROUND -20 DEG WITH STEERING WHEEL STRAIGHT AT TIMES. COULD THIS CAUSE THE FALSE ACTIVATION ISSUE? AFTER REPLACING SCCM RETESTED CONCERN STILL PRESENT PERFORMED FURTHER TESTING FOUND THAT ELECTRICAL SCHEMATIC ONLY SHOWS STEER WHEEL ANGLE IN SCCM I FOUND THAT VEH WITHOUT PARK ASSIST THE ANGLE IS INSIDE THE PSCM DUE TO THAT WE REPLACED THE PSCM STILL INT CONCERN WITHIN 1 MILE TRAC CONTROL WILL FALSE ACTIVATE AND FLASH. NO DTC'S I REALLY HAVE A FEELING THIS	05646 Crown Ford	30	1FMHK7D85B	3/8/2011					3.5L wo/APA	4/6/2011
UR0022	Int. No Assist	no codes		at WPAC	5/20- pulled data no ford codes or TRW codes checked hotline CQIS claim and found electrical connection issue with the wiring (UNKNOWN SOURCE) EPAS Gear did not fix symptom. this vehicle set ABS codes U0131, C1B00 & U0253					WEB FORM DATA - CONCERN: NO POWER STEERING ASSIST DIAGNOSTICS: INSPECTED THE STEERING GEAR AND CONNECTOR AND FOUND OK. RAN THE SELF TEST AND THE POWER STEERING MODULE PASSED. THE ABS MODULE HAD CODES C1B00 AND U0131. FOUND THE STEERING ASSIST STARTED WORKING MOMENTARILY AFTER THE SELF TESTS AND THE STOPPED WORKING. MONITORED THE STEERING ANGLE PID AND FOUND IT DOES NOT MATCH THE ACTUAL STEERING ANGLE. TECHNICIAN REPLY: I REPLACED THE STEERING GEAR AND MODULE ASSEMBLY. ON THE 3RD TRIP THE STEERING HAD NO ASSIST FOR 10 MINUTES AND CODES U0131 C1B00 U0253 SET. THE STEERING ASSIST THEN CAME BACK. INSPECTED THE CONNECTORS AND WIGGLE TESTED THE WIRING TO THE GEAR TECH PERFORMED \$400 WORTH OF WIRING REPAIR TO THE PSCM. UNKNOWN WHERE THE	07737 Serramonte Ford	611	1FMHK8D89B	2/15/2011	2/7/2011			3.5L wo/APA	3/23/2011	
UR0020 RUA# 4743	U2011-49	B3A	EPP	In Eval Tyco	6/23- Contamination - confirmed as Mg,Na,S at Tyco	5/16- CAP shipped gear direct to 26mile, performed level 1 analysis shipped to MAO for level 3				05126 Gary Crossley Ford	4475	1FMHK8F808B	11/5/2010	10/22/2010			3.5L w/APA	4/18/2011		
UR0024 RUA# 4827	U2011-49	B3A	EPP	In Eval Tyco	6/23- Tyco confirmed Mg,S,Na contamination week 35 relay build was in the 3rd batch- Aug 26th.-Sept. 7th	5/25- surrogate relay test, raise RUA ship to UK for week 24 workshop				06081 San Francisco Ford	14	1FMHK8D818B	3/8/2011	3/2/2011	12/27/2010		3.5L wo/APA	4/28/2011		
UR0026 RUA# 4809	U2011-49 U3000-96	B3A	EPP	In Eval Tyco	6/23- Tyco confirmed Mg,S,Na contamination, week 25 relay build was in the 1st contact batch- June 13th.-June 20th.	5/26- pulled stored & EFF data shipped to MAO for further testing, motor build date 8/30/2011				02694 Dean Sellers	3754	1FMHK8F8XB	11/22/2010	11/11/2010	9/13/2010	9/16/2010	3.5L wo/APA	5/13/2011		
UR0028	rubbing noise while turning at stop	no codes	NVH	in process MAO	6/10- No problem found EOL EDF/NVH testing. Did find a couple of impact marks on the OBH & EPP. Unsure what the tech moved or changed during gear replacement to fix noise. NPF- unknown cause	6/6- no codes in fault store, did not notice any noise turning input shaft back & forth from center. Shipped to MAO for EDF/NVH testing				20636 Schultz Ford	5475	1FMHK8D8XB	1/20/2011	1/6/2011	9/27/2010	10/7/2010	3.5L wo/APA	5/18/2011		
UR0029	TC Lamp on	no codes		At WPAC	6/10- pulled stored and EFF data, no ford codes or TRW codes that would cause the TC lamp to come on.	5/9- TECH TO CHECK PIDS FOR ERRATIC OPERATION WHEN THIS INTERMITTENT TC LAMP CAME ON, REPLACED THE EPAS GEAR SAME SYMPTOMS OCCUR				08868 John C. Stewart & Son	17	1FMHK8D83B	3/8/2011	3/2/2011	1/5/2011	1/13/2011	3.5L wo/APA	5/6/2011		



Case Number	Ford DTCs	TRW Code (Symptom)	Component	Gear Location	Current Updates	Issue Status	Gear location	Report State	Verbatim	Assigned To	Root Cause	P&A Code/ Dealer Name/ Dealer State	Miles	Snap Shot Data (if known)	TRW Fault (fault store codes)	VIN	Vehicle Build Date	Gear Build Date	ECU Build Date	EPP Build Date	Eng. Type	Date of Repair	Model Year	Date	Part ETA	
OKM BGA41610	C200B-62	BD4	TS	CAP												1FMHK8F81BGA	3/16/2011				3.5L w/APA	3/16/2011				
OKM BGA30310	No Assist	?		CAP	no returned part from CAP																3.5L w/APA					
UR0003	C200B-2F C200B-62	BD0,BD2, BD4	TS	In Eval (MAO)	5/23- made decision to keep 400% inspection in place for PCA. But to follow through on the parts req. so if we do find a bent finger to order parts for reflection gage on station 50.	2/4- seen interactive diagnosis for the codes and the dealer ordered an EPAS gear. Put hot process request to be returned to WPAC. 2/9- dealer will ship out part once 700 tag is assigned, should be tomorrow. Then part should arrive at WPAC by Monday 2/14. 4/6- need to discuss next week the poke yokes designed at station 50 to check for bent veins/fingers on the torque sensor. Andrew Bradley will join in the discussion to assist Marion to find a reasonable PCA. QAO will also be involved with the discussion. 5/3- have parts request in for TS check at station 50 on one line at MAO. Update timing chart for implementation. 5/10- sent the timing plan and needs to update with PPAP and production timing					07955 Ron Dupratt Ford	15			1FMHK8D87BC	1/24/2011	1/17/2011	11/16/2010	11/22/2010		3.5L wo/APA	2/2/2011				
UR0004	U3000-96	EF5		In Eval (26mile)	5/2- NTF with the testing on this gear at 26mile. UK testing another similar NV ram issue, NTF with that unit at this time. I will keep in pending to see if we get any other returns.	2/21- 700 tag should generate today, hoping to get the gear back to WPAC for initial analysis. 2/22- dealer ordered wrong steering gear, now waiting for new part with AP feature to be sent through the Ford parts			CHECK THE P S JUST WENT OUT WENT TO TEST DRIVE VEHICLE AND COULD NOT GET IT TO TURN AT ALL REALLY. PULLED VEHICLE INTO STALL. PULLED CODES HAD U3000:96. PULLED OASIS NO TSB, NO SSM. DID SOME PIN POINT TEST, AND EEG TEST. SENT HOTLINE INFO.			00089 Koons Ford	303			1FMHK8E8XBC	1/20/2011	1/19/2011	12/1/2010	12/4/2010		3.5L w/APA	2/12/2011			
UR0007	loud growl noise gear hard to turn		NVH	At CAP, unknown location	5/3- found out the gear was shipped to CAP unknown who has the gear at this time.	3/3- talked to tech states vehicle is hard to turn the wheel even on the hoist, no boot damage only code tech states he had U0253 which is not a PSCM code advise tech to call back with more			WEB FORM DATA - CONCERN: STEERING ASSIST IS INOP, LOUD GROWLING NOISE WHEN ATTEMPTING TO TURN THE STEERING WHEEL DIAGNOSTICS: VISUAL INSPECTION IS OK, NO VISIBLE SIGNS OF CAUSE, GROWLING NOISE			08398 Don Aadsen Ford	18			1FMHK8E86BC	1/31/2011					3.5L wo/APA	3/2/2011			





Case Number	Ford DTCs	TRW Code (Symptom)	Component	Gear Location	Current Updates	Issue Status	Gear location	Report State	Verbatim	Assigned To	Root Cause	P&A Code/ Dealer Name/ Dealer State	Miles	Snap Shot Data (if known)	TRW Fault (fault store codes)	VIN	Vehicle Build Date	Gear Build Date	ECU Build Date	EPP Build Date	Eng. Type	Date of Repair	Model Year	Date	Part ETA	
OKM BGA59863	steering noise on full left stop		NVH	In Eval (26mile)	5/9- mark on the ITR that indicates the ITR over articulated, the gear was dropped or impacted before assembly in the vehicle. Marlon.ZF or MAP the gear could be dropped. No marks on the EPAS housing. Unknown source at this time.	5/2- shipped direct to 26mile over articulated. 5/4- found right side tie rod bent, cannot find out how this happens, waiting for Ford to instruct next steps.							34			BC										
UR0001 RUA# 4308	U2011-49	B3A	EPP	In Eval (Tyco)	3/9- have implemented some containment actions. Starting today Tyco will heat treat(150deg for 1.5hrs) 100% of the rivets from Doduco to reduce contact resistance. 3/2 start shipping rivets weekly to U of Madrid for SEMEDX analysis. Sorting of Ford stoc	2/21- waiting on Duduco line audit information and also looking to get Tyco's presentation to send to Ford. Still at this time no new information on where the contamination came from. 3/9- have implemented some containment actions. Starting today Tyco will					09618 Brown Motors	18				1FMHK8D83B	12/16/2010				3.5L w/APA	1/12/2011				
UR0002 (UR0008) RUA# 4384	U2011-49 U3000-96	B3A	EPP	In Eval (Tyco)	3/9- have implemented some containment actions. Starting today Tyco will heat treat(150deg for 1.5hrs) 100% of the rivets from Doduco to reduce contact resistance. 3/2 start shipping rivets weekly to U of Madrid for SEMEDX analysis. Sorting of Ford stoc	2/21- waiting on Duduco line audit information and also looking to get Tyco's presentation to send to Ford. Still at this time no new information on where the contamination came from. 3/9- have implemented some containment actions. Starting today Tyco will					02071 I-77 Ford	10				1FMHK8D83B	1/12/2011		11/11/2010	11/13/2010	3.5L w/APA	1/28/2011				
UR0005 RUA# 4498	U2011-49	B3A	EPP	In Eval (Tyco)	3/16- confirmed Mag.sulfur sodium contamination, same as UR1 & UR2, here are the changes that are being made at Doduco before the next batch build that will be supervised by Tyco & TRW. Contaminants such as bucket washing and new sulphur bath to be implem	3/3- pulled snap shot data that has B3A, gear now in process to 26mile for analysis. 3/4- will arrive at 26mile this afternoon for analysis. Will hook up surrogate relay over the weekend if no codes set will remove the relay and ship to Tyco for test when					Ford Management Lease Car- Chicago	1700				1FMHK8F88B	11/22/2010	11/14/2010	9/21/2010	9/24/2010	3.5L w/APA	3/1/2011				
UR0006 RUA# 4529	U2011-49	B3A	EPP	In Eval (Tyco)	5/4- Tyco confirmed this as a Mg.Na.S failure.	3/7- customer will drop off vehicle at VSC garage for replacement as soon as MAO gear arrives at the VSC center. I will pick-up the gear after					Ford PDC Fleet vehicle- Taras Palczynski	2010				1FMHK7D89B	11/16/2010	11/9/2010	9/13/2010	9/16/2010	3.5L w/APA	3/7/2011				
UR0010 RUA# 4585	U2011-49	B3A	EPP	In Eval (Tyco)	5/4- Tyco confirmed this as a Mg.Na.S failure.	4/1- picked up gear from WHQ VSC garage, pulled EFF and stored data. 4/4 John Burnett will install surrogate relay and test ambient if testing passes will remove relay and ship to					lease management vehicle WHQ VSC	1838				1FMHK8F89B	11/18/2010	11/14/2010	9/21/2010	9/24/2010	3.5L w/APA	3/29/2010				
UR0011 RUA# 4621	U2011-49	B3A	EPP	At Dealer	5/4- Tyco confirmed this as a Mg.Na.S failure.	3/30- checked interactive diagnostic's intermittent B3A sets to ship gear back to 26mile for analysis.					04331 Brondes Ford					1FMHK7F87B	2/24/2011				3.5L w/APA	3/28/2011				
UR0012 RUA# 4596	U2011-49 U2011-61 U3000-96	B3A, B95	EPP	In Eval (Tyco)	5/4- Tyco confirmed this as a Mg.Na.S failure.	4/1- shipped from the dealer to CAP then to 26mile for testing, install surrogate relay test with					02058 Beechmo nt Ford	1425				1FMHK8F83B	11/22/2010									
UR0013 RUA# 4601	U2011-49	B3A	EPP	In Eval (26mile)	5/4- Tyco confirmed this as a Mg.Na.S failure.	4/8- Arrived at 26mile for testing, will not make the workshop will install surrogate relay and test 4/13- done testing with the surrogate relay will ship relay to					00807 Crest Ford	115				1FMHK8F85B	2/16/2011				3.5L w/APA	3/9/2011				
UR0014 RUA# 4618	U2011-49 U3000-96	B3A	EPP	In Eval (26mile)	5/4- Tyco confirmed this as a Mg.Na.S failure.	4/11- pulled fault store and EFF data, shipped gear to 26mile for further testing 4/13- testing with surrogate relay if passes will ship out relay to UK					03820 Landers Ford	3096				1FMHK8F8XB	11/13/2010				3.5L w/APA	3/5/2011				
UR0015 RUA# 4619	U2011-49 U3000-96	B3A	EPP	In Eval (26mile)	5/4- Tyco confirmed this as a Mg.Na.S failure.	4/11- pulled fault store and EFF data, shipped gear to 26mile for further testing 4/13- testing with surrogate					00807 Crest Ford	1356				1FMHK7B87BGA02763	11/16/2010				3.5L w/APA	2/25/2011				
UR0016	TC lamp on	no codes		Ship to 26mile for storage	4/26- pulled stored data from gear no codes stored in gear, check CQIS data and found the RCM fixed the vehicle. Cannot chargeback the gear to the dealer because hotline advised to change						02761 Southgate Ford	249				1FMHK7D82BG	3/8/2011	3/3/2011			3.5L w/APA	3/30/2011				
UR0017	TC lamp on	no codes		Ship to 26mile for storage	4/29- pulled stored data from gear no codes stored in gear, check CQIS data and found the RCM fixed the vehicle. Cannot chargeback the gear to the dealer because hotline advised to change				CUST REPORTS T/C LIGHT STAYING ON. TECH VERIFIED THIS CONCERN SELF TEST CODE C-1B00-64 FROM ABS MODULE. TECH REPORTS NO CODES FROM RCM. TECH REPORTS REPLACED THE STEERING RACK PER NHL RECOMMENDATION. TECH REPORTS VEHICLE STILL HAS T/C LIGHT ON CONCERN. RECONTACTED NHL WAS INFORMED TO REPLACE THE RCM. TECH REPLACED THE RCM REPORTS NORMAL T/C LIGHT FUNCTION NO RETURN CODES. TECH IS NOW SEEKING APPROVAL CODE FOR RCM REPLACEMENT		02731 Atchinson Ford	111				1FMHK8D89B	3/4/2011	3/1/2011			3.5L w/APA	3/31/2011				

UR0018	TC lamp on	no codes		at 26mile storage	5/12- pulled stored data from gear no codes stored in gear, check CQIS data and found the RCM fixed the vehicle. Cannot changeback the gear to the dealer because hotline advised to change			WEB FORM DATA - CONCERN: ADVANCE TRAC LIGHT ON DIAGNOSTICS: RUN OASIS NO TBSBS FOUND ROADTEST VEH PARTS REPLACED: NONE TECH QUESTION: THIS IS A NEW VEH WITH ABS DTC C1B00:64-68 IN MEMORY. I CLEARED THE DTC WENT APPROX 1 MILE HIT THE BRAKES TRACTION CONTROL ACTIVATED AND LAMP CAME BACK ON. SAME DTC SET AGAIN ANY KNOWN CONCERNS, REPAIRS OR SUGGESTIONS BEFORE I START WITH NORMAL DIAGNOSTICS? WERE YOU ABLE TO VERIFY THE CONCERN? YES IS THERE AN APPROPRIATE PINPOINT TEST IN THE WSM FOR THIS CONCERN? YES WAS THE PINPOINT TEST FOLLOWED? NO TECHNICIAN REPLY: OK I CHECKED PIN FIT AT ABS MODULE ALL TEST OK. DID FIND I CAN GET FALSE ACTIVATION GOING STRAIGHT ALSO MONITORED PID FOUND THAT STEERING WHEEL ANGLE SENSOR READS AROUND -20 DEG WITH STEERING WHEEL STRAIGHT AT TIMES. COULD THIS CAUSE THE FALSE ACTIVATION ISSUE? AFTER REPLACING SCCM RETESTED CONCERN STILL PRESENT PERFORMED FURTHER TESTING FOUND THAT ELECTRICAL SCHEMATIC ONLY SHOWS STEER WHEEL ANGLE IN SCCM I FOUND THAT VEH WITHOUT PARK ASSIST THE ANGLE IS INSIDE THE PSCM DUE TO THAT WE REPLACED THE PSCM STILL INT CONCERN WITHIN 1 MILE TRAC CONTROL WILL FALSE ACTIVATE AND FLASH. NO DTC'S I REALLY HAVE A FEELING THIS	05646 Crown Ford	30	1FMHK7D85B	3/8/2011					3.5L wo/APA	4/6/2011
UR0022	Int. No Assist	no codes		at WPAC	5/20- pulled data no ford codes or TRW codes checked hotline CQIS claim and found electrical connection issue with the wiring (UNKNOWN SOURCE) EPAS Gear did not fix symptom. this vehicle set ABS codes U0131, C1B00 & U0253			WEB FORM DATA - CONCERN: NO POWER STEERING ASSIST DIAGNOSTICS: INSPECTED THE STEERING GEAR AND CONNECTOR AND FOUND OK. RAN THE SELF TEST AND THE POWER STEERING MODULE PASSED. THE ABS MODULE HAD CODES C1B00 AND U0131. FOUND THE STEERING ASSIST STARTED WORKING MOMENTARILY AFTER THE SELF TESTS AND THE STOPPED WORKING. MONITORED THE STEERING ANGLE PID AND FOUND IT DOES NOT MATCH THE ACTUAL STEERING ANGLE. TECHNICIAN REPLY: I REPLACED THE STEERING GEAR AND MODULE ASSEMBLY. ON THE 3RD TRIP THE STEERING HAD NO ASSIST FOR 10 MINUTES AND CODES U0131 C1B00 U0253 SET. THE STEERING ASSIST THEN CAME BACK. INSPECTED THE CONNECTORS AND WIGGLE TESTED THE WIRING TO THE GEAR TECH PERFORMED \$400 WORTH OF WIRING REPAIR TO THE PSCM. UNKNOWN WHERE THE	07737 Searnate Ford	611	1FMHK8D89B	2/15/2011	2/7/2011			3.5L wo/APA	3/23/2011	
UR0020 RUA# 4743	U2011-49	B3A	EPP	In Eval Tyco	6/23- Contamination - confirmed as Mg,Na,S at Tyco	5/16- CAP shipped gear direct to 26mile, performed level 1 analysis shipped to MAO for level 3			05126 Gary Crossley Ford	4475	1FMHK8F808B	11/5/2010	10/22/2010			3.5L w/APA	4/18/2011	
UR0024 RUA# 4827	U2011-49	B3A	EPP	In Eval Tyco	6/23- Tyco confirmed Mg,S,Na contamination week 35 relay build was in the 3rd batch- Aug 26th -Sept. 7th	5/25- surrogate relay test, raise RUA ship to UK for week 24 workshop			06081 San Francisco Ford	14	1FMHK8D81B	3/8/2011	3/2/2011	12/27/2010		3.5L wo/APA	4/28/2011	
UR0026 RUA# 4809	U2011-49 U3000-96	B3A	EPP	In Eval Tyco	6/23- Tyco confirmed Mg,S,Na contamination, week 25 relay build was in the 1st contact batch- June 13th -June 20th.	5/26- pulled stored & EFF data shipped to MAO for further testing, motor build date 8/30/2011	6/9- shipped relay out to Tyco for relay workshop next week.		02694 Dean Sellers	3754	1FMHK8F8XB	11/22/2010	11/11/2010	9/13/2010	9/16/2010	3.5L wo/APA	5/13/2011	
UR0028	rubbing noise while turning at stop	no codes	NVH	in process MAO	6/10- No problem found EOL EDF/NVH testing. Did find a couple of impact marks on the OBH & EPP. Unsure what the tech moved or changed during gear replacement to fix noise. NPF- unknown cause	6/6- no codes in fault store, did not notice any noise turning input shaft back & forth from center. Shipped to MAO for EDF/NVH testing			20636 Schultz Ford	5475	1FMHK8D8XB	1/20/2011	1/6/2011	9/27/2010	10/7/2010	3.5L wo/APA	5/18/2011	
UR0029	TC Lamp on	no codes		At WPAC	6/10- pulled stored and EFF data, no ford codes or TRW codes that would cause the TC lamp to come on.	5/9- TECH TO CHECK PIDS FOR ERRATIC OPERATION WHEN THIS INTERMITTENT TC LAMP CAME ON, REPLACED THE EPAS GEAR SAME SYMPTOMS OCCUR	05/19/2011 02:45PM ERIC TESTES MSS - TSO - DIGITAL IMAGE WITH A CONTACTED DEALER FOUND OUT THE YAW SIGNAL WAS STUCK ON 0 ALL THE TIME DURING ROAD TEST. DEALER REPLACED THE RCM AFTER 20 MILES OF ROAD TEST NO TC LAMP ON. TC ACTIVATION OR ABS CODES. VEHICLE FIXED AT THIS TIME. TO RELEASE BACK TO CUSTOMER	08868 John C. Stewart & Son	17	1FMHK8D83B	3/8/2011	3/2/2011	1/5/2011	1/13/2011	3.5L wo/APA	5/6/2011		

OKM BGA:39357 RJA# 4531	U2011-49 U2011-61 U3000-49 U3000-96	BSA	EPP	In Eval (Tyco)	5/4- Tyco confirmed this as a Mg,Na,S failure.	3/15- pulled Ford codes unknown what the TRW codes are at this time, to pull CANape codes and ship to 26mie for analysis. 3/21- tri-temp ignition cycled for 36 hrs with no A3A's, E66's or B3A's, relay still in the chamber. 3/23- gear shipped out to UK to 4/18- under analysis at Tyco, on the contamination suspect list this unit has been tri-temp tested over 36hrs.													
-------------------------------	--	-----	-----	-------------------	--	---	--	--	--	--	--	--	--	--	--	--	--	--	--

1FM#K8D81B

3/14/2011				3.5L wo/APA	3/2/2011			
-----------	--	--	--	----------------	----------	--	--	--

---

**From:** Napoli, Laura (L.)  
**Sent:** Monday, July 25, 2011 12:03 PM  
**To:** Anderson, Eric (H.)  
**Cc:** Estes, Eric (E.E.); Mrozek, Robert (R.M.)  
**Subject:** RE: 1FMHK8F85BG [REDACTED] EPAS inop

U3000-49 is a code that encompasses MANY root causes. As we get the gears back, we group them based on the failure (TRW code). Do not open another project and make it red. Please see Eric Estes' spreadsheet for our open issues. You are welcome to call into our Monday 9am meetings where we go through U502 returns.

---

**From:** Anderson, Eric (H.)  
**Sent:** Monday, July 25, 2011 11:53 AM  
**To:** Napoli, Laura (L.)  
**Cc:** Estes, Eric (E.E.); Mrozek, Robert (R.M.)  
**Subject:** RE: 1FMHK8F85BGA61262 EPAS inop

Do we have a root cause for U3000 codes then? I just got another one today. Should I open a new project and make it red red?

---

**From:** Napoli, Laura (L.)  
**Sent:** Monday, July 25, 2011 10:49 AM  
**To:** Anderson, Eric (H.); Cassata, Joe (J.)  
**Cc:** Estes, Eric (E.E.); Mrozek, Robert (R.M.)  
**Subject:** RE: 1FMHK8F85BG [REDACTED] EPAS inop

Eric,

These are not B3A gears. U2011-49 is the B3A DTC with a PCA date of 7/11. We received 2 B3A gears recently which had build dates of last year.

---

**From:** Anderson, Eric (H.)  
**Sent:** Tuesday, July 19, 2011 10:23 AM  
**To:** Cassata, Joe (J.)  
**Cc:** Estes, Eric (E.E.); Napoli, Laura (L.); Mrozek, Robert (R.M.)  
**Subject:** 1FMHK8F85BG [REDACTED] EPAS inop

Hi Joe:

Please request this gear to Eric Estes at WPAC, TR EE.

Eric, Laura and Rob,  
These U3000 faulted gears continue to come. This unit was built 5/2/11. Do you still have confidence in the July 11 PCA date?

Thanks,

Eric Anderson  
PVT Engineer  
Ford Chicago Assembly  
773.646.7236 desk  
773.729.0337 cell  
[eande181@ford.com](mailto:eande181@ford.com)

# Claim Detail Report

Note: All costs are in US dollars

Model Year = 2011; Claim Key = 687210

## Vehicle Information

Model Year: 2011

Market Derived: F - FORD

Body/Cab Type: T/WD - 4 DOOR WAGON

Version/Series: T/EF-FORD SERIES

Drive Type: T/F-4 WHL L/H FULL TIME  
DRIVE

Vehicle Line: T/UB-EXPLORER [11-12]

Warranty Start Date: 23-MAY-11

Production Date: 02-MAY-11

VIN: 1FMHK8F85BG [REDACTED]

## Dealer Information:

Dealer Name: CHARLES GABUS FORD

Dealer Code: 03334 - \*

Address: 4545 MERLE HAY RD

City: DES MOINES

State: IA Zip Code: 50310

Country: USA Region Code: NA

Phone: (515)270-0707

## Claim Information

Document Number: 515439A

Repair Date: 11-JUL-11

Distance: 4666

TIS: 2

## Expense Information

Customer Paid Amount: .00

Deductible Amount: .00

Dealer Paid Amount: .00

Labor Cost: 406.23

Misc. Expense Amount: .00

Part Markup Amount: 434.38

Material Cost: 1520.32

Total Cost Gross: 1926.55

Cust.  
 Concern **H22 - STEERING REQUIRES EXTRA OR UNEVEN EFFORT**  
 Code:

Condition **42 - DOES NOT OPERATE PROPERLY**  
 Code:

Technician VERIFY CONCERN HOOK UP IDS AND RUN SELF TESTS PULLED CODES  
 Comment: U3000:49 8A PSCM AND U3000:96 C8 PSCM RUN PIN POINT TESTS  
 INTERNAL FAULT REPLACE PSCM ORDERED PARTS REPLACE PS RACK  
 OR PSCM VERIFY REPAIR AND ALIGN FRONT END SET TOE

Customer CUSTOMER STATES THAT THE POWER STEERING QUIT WORKING  
 Comment: BARELY ABLE TO STEER INSPECT AND ADVISE

<u>Labor Op Code</u>	<u>Labor Op Description</u>	<u>Labor Op Cost</u>
3504E		17.66
3504E45		26.49
3504E8		8.83
MT3504A		309.09
MT3001A		44.16

<u>Causal</u>	<u>Full Part Number</u>			<u>Part</u>	<u>Part</u>	<u>Extended</u>	
<u>Flag</u>	<u>PREF</u>	<u>BASE</u>	<u>SUFF</u>	<u>Description</u>	<u>CPSC</u>	<u>Quantity</u>	<u>Amount</u>
Y	BB5Z	3504	JE	GEAR ASY-STEERING	110101	1	1520.32

DTC Sections: **Mil. Light On =N**

<u>Fla</u>	<u>Test</u>	<u>Malfunction Cd</u>	<u>Malfunction Cd</u>	<u>Monitor</u>	<u>Monitor Cd</u>
<u>g</u>	<u>Type</u>		<u>Description</u>	<u>Cd</u>	<u>Description</u>
N	UNDF	U3000	CONTROL MODULE	48	HYBRID

Any comments? You can contact

<< OLE Object: Picture (Metafile) >> [webmaster](mailto:webmaster)



---

**From:** Estes, Eric (E.E.)  
**Sent:** Wednesday, January 26, 2011 5:00 PM  
**To:** Napoli, Laura (L.); Jackson, Bradley (B.G.); Anderson, Eric (H.); Bahena, Miguel (Mike.); Pasquarella, Michael (M.S.)  
**Cc:** Snider, Tim (T.O.)  
**Subject:** RE: 2011 Exp - BG [REDACTED] - Power steering fault, codes, 289 mi, BD 11/22/10

No DTC's collected on interactive diagnosis. I called the tech and he never saw any lamps on or no assist, starting the vehicle up from the write up area, he cleared the codes performed the parking lot road test and road tested the vehicle did not have any problems. the customer was waiting for the vehicle and has been driving it since last thursday with no problem at this time.

Eric

---

**From:** Napoli, Laura (L.)  
**Sent:** Wednesday, January 26, 2011 4:45 PM  
**To:** Jackson, Bradley (B.G.); Anderson, Eric (H.); Bahena, Miguel (Mike.); Pasquarella, Michael (M.S.); Estes, Eric (E.E.)  
**Cc:** Snider, Tim (T.O.)  
**Subject:** RE: 2011 Exp - BG [REDACTED] - Power steering fault, codes, 289 mi, BD 11/22/10

Brad,  
You are right. I only read Eric's list and overlooked the U2011:49-08. Disregard my last comments.

Eric Estes, can you try to find the snapshot data in IDS and see if there are any EPAS codes for this one linking to the POWER STEERING ASSIST FAULT?

---

**From:** Jackson, Bradley (B.G.)  
**Sent:** Wednesday, January 26, 2011 4:41 PM  
**To:** Napoli, Laura (L.); Anderson, Eric (H.); Bahena, Miguel (Mike.); Pasquarella, Michael (M.S.); Estes, Eric (E.E.)  
**Subject:** RE: 2011 Exp - BG [REDACTED] - Power steering fault, codes, 289 mi, BD 11/22/10

Laura, are we certain? I have not seen these codes on the spread terminal stop ship we had. The codes that were repeating on vehicles with the spread terminal were C1B00, U0131, and U0001.

Brad

---

**From:** Napoli, Laura (L.)  
**Sent:** Wednesday, January 26, 2011 2:51 PM  
**To:** Anderson, Eric (H.); Bahena, Miguel (Mike.); Pasquarella, Michael (M.S.); Estes, Eric (E.E.)  
**Cc:** Jackson, Bradley (B.G.)  
**Subject:** RE: 2011 Exp - BGA02503 - Power steering fault, codes, 289 mi, BD 11/22/10

The wiring issue at CAP will cause these codes.

---

**From:** Anderson, Eric (H.)  
**Sent:** Wednesday, January 26, 2011 11:27 AM  
**To:** Bahena, Miguel (Mike.); Pasquarella, Michael (M.S.); Napoli, Laura (L.); Estes, Eric (E.E.)  
**Subject:** FW: 2011 Exp - BG [REDACTED] - Power steering fault, codes, 289 mi, BD 11/22/10



Hi All:

I translated these error codes from this CQIS claim. Do you know what might cause them together? We currently have a stop ship on the C139 connector for spread terminals on circuit 24.

U0121= lost communication with ABS  
U0159= lost communication with active park assist module A  
U2011= module transmitted invalid data  
U0126= lost communication with steering angle sensor  
U0428= invalid data from steering angle sensor

Thanks,

Eric

---

**From:** Buelow, Steve (S.E.)

**Sent:** Friday, January 21, 2011 10:40 AM

**To:** Adamczyk, David (D.W.); Bollwahn, Bryce (B.A.); Centlivre, James (J.C.); Cheatham, Sandy (.); Cittadino, Lisa (L.C.); Collins, Kevin (K.E.); Gagnier, Kathryn (K.A.); Gilewski, David (D.); Gubing, William (Bill.); Hays, Andy (A.R.); Henker, Scott (S.); Lubin Henney, Michele (MLH.); Lysik, Kevin (K.M.); Mann, Mickey (N.S.); McClain, Shawn (S.M.); Pogorzelski, John (J.M.); Rodgers, Chuck (.); Saleh, Salim (S.A.); Sellers, Gary (G.T.); Shaukat, Nadeem (N.S.); Simkus, Walter (W.A.); Smith, Scott (S.A.); Sokolowski, Todd (T.M.); Thornsberry, Joel (J.A.); Willis, Mark (M.E.); Wong, Vicki (V.A.); Abrams, Donald (D.); Acuna, Aaron (A.A.); Allman, Jan (J.E.); Bell, Tim (.); Bergeron, Matthew (M.C.); Bisaga, Richard (R.); Boykin, George (G.); Boykins, Michael (M.); Bustamante, Chris (C.T.); Cantrell, David (D.D.); Ciotti, Steven (S.R.); Davis, Charlene (C.); Devine, Robert (R.M.); Docimo, Tony (A.F.); Elting, Tim (T.H.); Ferguson, Hugh (H.); Gagnier, Scott (S.W.); Greenwell, R (R.); Guyton, MzJenny (J.); Hernandez, Thomas (T.); Herron, Micheal (M.C.); Inglis, Steve (S.D.); Iqbal, Khurram (K.); Jones, Frederick (F.L.); Little, Janie (J.); Martin, Kenneth (K.A.); Matlock, Douglas (D.); McElroy, Darin (D.L.); McKernan, Patrick (P.J.); Miller, Melinda (M.S.); Moore, Chikynda (D.); Moses, Barry (B.A.); Moskwa, Larry (L.M.); Perkins, John (J.E.); Pesch, Vincent (V.J.); Rutovic, Nick (N.); Sarkisian, Mark (Z.); Talbott, Larry (J.L.); Turner, Bridgette (B.); Turner, Patrice (P.T.); Vandergroef, Cornelius (C.); Washington, Kellie (K.S.); Wertman, David Brian (D.B.); Westbrook, Dori (D.); Williams, Erik (E.C.); Williams, Gregory (G.M.); Williams, TRACE (S.); Wyatt, Kimberly (K.D.); Zroback, David (D.P.); Evans, Kayekethia (K.); Gibson, Renelda (R.); Lakomek, Scott (S.); Ornelas, Demetrio (D.); Ratliff, Kathy (K.); Stonewall, Wendy (M.); Svetich, Chris (C.); Anderson, Eric (H.); Berzeri, Marcello (M.); Chamberlain, Steve (J.); Edwards, Monty (M.R.); Farmer, Marty (M.F.); Feder, Andrew (A.); Gerrard, Ryan (R.P.); Iannotti, Jason (J.R.I.); Ickes, Walt (W.D.); Imperati, Daniel (D.); Issa, Ibrahim (I.M.); Jackson, Bradley (B.G.); Logli, Michael (M.A.); Morgan, Anthony (A.); Olsson, Paul (P.C.); Polaski, Mike (M.S.); Porter, Alan (A.T.); Rapiz, Noreen (N.G.); Siddiqui, Saif (S.S.); Sluis, Jim (J.S.); Smith, Erin (E.); Sridhara, Raghu (R.); Trygar, Mike (M.); Vargo, Rebecca (R.L.); Widrick, Brad (B.A.); Young, Richard (R.C.); Yu, Eric (E.); Buelow, Steve (S.E.)

**Subject:** FW: 2011 Exp - BG [REDACTED] - Power steering fault, codes, 289 mi, BD 11/22/10

**-The Customer Defines Quality-**

*Steve Buelow - Ford Motor Company*

FCSD Program Manager-

Taurus/Taurus SHO/Lincoln MKS/Explorer

Chicago Assembly PVT Office, COE

773-646-7495 DialNet 686-7495

Cell 313-805-8334 sbuelow@ford.com

"You miss 100 percent of the shots you never take." - Wayne Gretzky

**From:** SBUELOW@ford.com [mailto:SBUELOW@ford.com]  
**Sent:** Friday, January 21, 2011 10:07 AM  
**To:** Buelow, Steve (S.E.)  
**Subject:** 2011 Exp - BG [REDACTED] - power steering fault, codes, 289 mi, BD 11/22/10

**Attachments :** 0

**Report# :** BATDZ004 NHL  
**CCRG/EPRC:** **Reviewed Status:**  
**Vehicle:** 2011,EXPLORER 4X4 (U502),4 DOOR  
,MP,1FMHK8F83BG [REDACTED]  
**Odometer :** 289 M **Engine:** 3.5L  
CYCLO **Calibration:** BUB1ST0A  
**Transmission:** 6F55 **Axle:** **A/C:** YES  
**Dealer:** USA 02058 BEECHMONT FORD INC **Phone#:** (51!!3) 752-7474  
**City:** Cincinnati **State:** Ohio **Country :** USA  
**Originator:** SHANE JONES  
**Symptom:** 3 03 A 99 CHASS.,STRG/HANDLING ,STEERING WHEEL ,NOT LISTED  
**Status:**  
**VFG:** V87 STEERING  
**Additional Symptom:** STEERING HARD INTERMITTENT  
**Fix:** **Causal Component :**  
**Condition Code:**

**Hotliner:** JSAV!! OY1 **Phone:** 313 317-9352 **Regn Cd:** G3 Cincinnati  
**Engineering:** **Phone:** **TAR:**  
**Dlr Contact:** SHANE JONES **Phone:** 513 752-7474 **Title Cde:** T

**DTCs:**  
KOEO:U0121 U2011:49-08 U0126 U0159 U0428  
KOEC:  
KOER:

**Comments**  
:

REPAIR 01/20/2011 02:47PM JONATHAN SAVOY MSS - FCSD - TECH SVC HOTLINE  
WEB FORM DATA - CONCERN: CUST STATES THAT THE MESSAGE CENTER HAD A  
MESSAGE THAT SAID POWER STEERING ASSIST FAULT AND THE STEERING WAS  
VERY HARD DIAGNOSTICS: TEST DROVE VEH AND NORMAL OPERATION AT THIS

TIME 0 WARNINGS IN THE MESSAGE CENTER IDS TESTED AND FOLLOWED  
PINPOINT TEST PER WORK SHOP MANUAL AND IT LED ME TO THE CONSERN IS  
NOT PRESENT AND TO RETURN THE VEH BACK TO THE CUST DTC  
U2011:49-08,U0121,U0126,U0159,U0428 THE WORK SHOP MANUAL TOLD ME TO  
CLEAR THE DTC AND TEST DRIVE VEH AND RETEST I CLEARD THE DTC AND THE  
SYSTEM PASSED PARTS REPLACED:: NONE TECH QUESTION: ANY KNOWN  
CONSERNS SHOULD I RETURN THE VEH TO THE CUST WERE YOU ABLE TO  
VERIFY THE CONCERN? NO IS THERE AN APPROPRIATE PINPOINT TEST IN THE  
WSM FOR THIS CONCERN? YES WAS THE PINPOINT TEST FOLLOWED? YES

**RECOMM 01/20/2011 02:47PM JONATHAN SAVOY MSS - FCSD - TECH SVC HOTLINE**

SHANE, THIS CONCERN IS LIKELY CAUSED BY A LOOSE CONNECTION WITHIN  
THE MAIN ENGINE OR BODY WIRING HARNESS. THIS WOULD RESULT IN  
INTERMITTENT COMMUNICATION CODES AND POSSIBLE INOPERATIVE  
ACCESSORIES.

IN ORDER TO HELP ISOLATE THE ROOT CAUSE OF THIS CONCERN, PLEASE  
START THE VEHICLE AND WIGGLE TEST THE MAIN ENGINE AND BODY WIRING  
HARNESS. THIS MAY HELP TO INDUCE THE CONCERN. PLEASE ALSO INSPECT FOR  
LOOSE OR UNSEATED CONNECTORS. THE HOTLINE HAS NOT SEEN TRENDS OF  
THIS CONCERN AT THIS TIME. IF THE CONCERN CANNOT BE DUPLICATED, NO  
REPAIRS SHOULD BE PERFORMED. IF ADDITIONAL ASSISTANCE IS NEEDED,  
PLEASE UPDATE YOUR FORM WITH ANY ADDITIONAL DETAILS OF THIS  
CONCERN.

---

**From:** Napoli, Laura (L.)  
**Sent:** Monday, June 13, 2011 12:10 PM  
**To:** Jackson, Bradley (B.G.); Mrozek, Robert (R.M.); Anderson, Eric (H.)  
**Subject:** RE: 2011 Exp - BG [REDACTED] - Loss of steering assist, fuse 89 blown, 4506 mi, BD 12/1/10

Why are they being told to replace the gear??? There are no EPAS codes.

---

**From:** Jackson, Bradley (B.G.)  
**Sent:** Friday, June 10, 2011 8:22 AM  
**To:** Napoli, Laura (L.); Mrozek, Robert (R.M.)  
**Subject:** FW: 2011 Exp - BG [REDACTED] - Loss of steering assist, fuse 89 blown, 4506 mi, BD 12/1/10

[Interesting way to lose EPAS. fyi.](#)

brad

---

**From:** Buelow, Steve (S.E.)  
**Sent:** Thursday, June 09, 2011 8:21 PM  
**To:** Adamczyk, David (D.W.); Bollwahn, Bryce (B.A.); Centlivre, James (J.C.); Cheatham, Sandy (.); Cittadino, Lisa (L.C.); Collins, Kevin (K.E.); Gagnier, Kathryn (K.A.); Gilewski, David (D.); Gillanders, Eric (E.S.); Gubing, William (Bill.); Hays, Andy (A.R.); Krochmalny, Kevin (K.); Mann, Mickey (N.S.); McClain, Shawn (S.M.); Pogorzelski, John (J.M.); Rodgers, Chuck (.); Saleh, Salim (S.A.); Sellers, Gary (G.T.); Shaukat, Nadeem (N.S.); Simkus, Walter (W.A.); Sokolowski, Todd (T.M.); Thornsberry, Joel (J.A.); Willis, Mark (M.E.); Wong, Vicki (V.A.); Acuna, Aaron (A.A.); Allman, Jan (J.E.); Bell, Tim (.); Bergeron, Matthew (M.C.); Bisaga, Richard (R.); Boykin, George (G.); Boykins, Michael (M.); Bustamante, Chris (C.T.); Cantrell, David (D.D.); Carter, Tracy (T.); Chones, Marvin (M.); Ciotti, Steven (S.R.); Davis, Charlene (C.); Devine, Robert (R.M.); Docimo, Tony (A.F.); Ferguson, Hugh (H.); Gagnier, Scott (S.W.); Greenwell, R (R.); Guyton, MzJenny (J.); Hernandez, Thomas (T.); Herron, Micheal (M.C.); Inglis, Steve (S.D.); Iqbal, Khurram (K.); Jones, Frederick (F.L.); Little, Janie (J.); Lux, Tracie (T.L.); Martin, Kenneth (K.A.); Matlock, Douglas (D.); McElroy, Darin (D.L.); McKernan, Patrick (P.J.); Miller, Melinda (M.S.); Moore, Chikynda (D.); Moskwa, Larry (L.M.); Perkins, John (J.E.); Russell, David (D.A.); Rutovic, Nick (N.); Sarkisian, Mark (Z.); Talbott, Larry (J.L.); Turner, Bridgette (B.); Turner, Patrice (P.T.); Vandergroef, Cornelius (C.); Washington, Kellie (K.S.); Wertman, David Brian (D.B.); Westbrook, Dori (D.); Williams, Erik (E.C.); Williams, Gregory (G.M.); Wyatt, Kimberly (K.D.); Zroback, David (D.P.); Armstrong, Miya (M.); Buerger, Robert (R.G.); Evans, Kayekethia (K.); Gibson, Renelda (R.); Lakomek, Scott (S.); Napier, S (S.); Ornelas, Demetrio (D.); Ratliff, Kathy (K.); Scheldberg, Gary (G.D.); Stonewall, Wendy (M.); Svetich, Chris (C.); Torian, Jason (J.B.); Anderson, Eric (H.); Berzeri, Marcello (M.); Cassata, Joe (J.); Chamberlain, Steve (J.); Edwards, Monty (M.R.); Farmer, Marty (M.F.); Feder, Andrew (A.); Gerrard, Ryan (R.P.); Iannotti, Jason (JRI.); Ickes, Walt (W.D.); Issa, Ibrahim (I.M.); Jackson, Bradley (B.G.); Logli, Michael (M.A.); Morgan, Anthony (A.); Olsson, Paul (P.C.); Polaski, Mike (M.S.); Porter, Alan (A.T.); Rapiz, Noreen (N.G.); Santilli, Rennie (R.); Smith, Erin (E.); Sridhara, Raghu (R.); Trygar, Mike (M.); Vargo, Rebecca (R.L.); Widrick, Brad (B.A.); Young, Richard (R.C.); Yu, Eric (E.); Buelow, Steve (S.E.)  
**Subject:** FW: 2011 Exp - BG [REDACTED] - Loss of steering assist, fuse 89 blown, 4506 mi, BD 12/1/10

**-The Customer Defines Quality-**

*Steve Buelow - Ford Motor Company*

FCSD Program Manager-  
Taurus/Taurus SHO/Lincoln MKS/Explorer

Chicago Assembly PVT Office, COE  
773-646-7495 DialNet 686-7495  
Cell 773-726-0808 sbuelow@ford.com

"Quality means doing it right when no one is looking." - Henry Ford

---

**From:** SBUELOW@ford.com [mailto:SBUELOW@ford.com]  
**Sent:** Thursday, June 09, 2011 8:17 PM  
**To:** Buelow, Steve (S.E.)  
**Subject:** 2011 Exp - BG [REDACTED] - Loss of steering assist, fuse 89 blown, 4506 mi, BD 12/1/10

**Attachments :** 0

**Report# :** BFIA Y027 NHL **Received:** 06/09/2011  
**CCRG/EPRC:** **Reviewed Status:** **Date:**  
**Vehicle:** 2011,EXPLORER 4X4 (U502),4 DOOR **Build Date:** 12/01/2010  
,MP,1FMHK8D80BG [REDACTED]  
**Odometer :** 4,506 M **Engine:** 3.5L **Calibration:** BUB1SN0A  
CYCLO  
**Transmission:** 6F50 **Axle:** **A/C:** YES  
**Dealer:** USA 00615 DeLacy Ford, Inc. **Phone#:** (716) 668-1200  
**City:** Elma **State:** New York **Country :** USA  
**Originator:** MIKE MONTOUR  
**Symptom:** 3 03 1 50 CHASS.,STRG/HANDLING ,FUNCTION,HIGH EFFORT  
**Status:**  
**VFG:** V87 STEERING  
**Additional Symptom:** LOSS OF ASSIST F89 OPEN  
**Fix:** **Causal Component :**  
**Condition Code:**

**Hotliner:** FSHEPHE2 **Phone:** 000 317-6305 **Regn Cd:** G4 Pittsburgh  
**Engineering:** **Phone:** **TAR:**  
**Dlr Contact:** MIKE MONTOUR **Phone:** 000 000-0000 **Title Cde:** T

**DTCs:**  
KOEO:  
KOEC:  
KOER:

**Comments**

:

**REPAIR** 06/09/2011 04:12PM FRED SHEPHERD MSS - FCSD - TECH SVC HOTLINE  
WEB FORM DATA - CONCERN: NO POWER STEERING, TRAC LIGHT ON, NO BLWER  
OPERATION. DIAGNOSTICS: SELF TEST, CODES U0131, U0253. CHECKED  
CONNECTOR C139- GOOD. FOUND FUSE F89- 5 AMP IN BJB BLOWN. REPLACED  
FUSE, ALL GOOD. UNABLE TO FIND ROOT CAUSE FOR FUSE TO BLOW. PARTS  
REPLACED:: #F89 FUSE TECH QUESTION: KNOWN CONCERNS. WERE YOU  
ABLE TO VERIFY THE CONCERN? YES IS THERE AN APPROPRIATE PINPOINT  
TEST IN THE WSM FOR THIS CONCERN? NO WAS THE PINPOINT TEST  
FOLLOWED? NO

**RECOMM** 06/09/2011 04:12PM FRED SHEPHERD MSS - FCSD - TECH SVC HOTLINE  
HI MIKE. WE ARE NOT AWARE OF ANY COMMON TRENDS OR CONCERNS FOR  
THIS  
ISSUE OTHER THEN WHAT IS ADDRESSED IN SSM 21737. PLEASE BE SURE THERE  
ARE NO AFTERMARKET SYSTEMS OR COMPONENTS INSTALLED AND IF SO,  
REMOVE  
THEM PRIOR TO DIAGNOSIS. BASED ON THE DESCRIPTION, IF THERE ARE NO  
CIRCUIT SHORTS OR CONNECTION ISSUES, I WOULD SUSPECT AN INTERNAL  
PSCM  
CONCERN. TO CONFIRM THIS, I WOULD ISOLATE THE BLOWER MOTOR RELAY  
PORTION OF CIRCUIT CBB89 FROM S123 AND ATTEMPT TO DUPLICATE THE  
CONCERN. IF THE FUSE OPENS, REPLACE THE PSCM. IF THE CONCERN IS  
RESOLVED, SUSPECT A BLOWER ISSUE. TRACE AND REPAIR AS NEEDED. IF  
YOU NEED ADDITIONAL ASSISTANCE, PLEASE LET US KNOW. THANKS. SSM  
21737 CODES C1B00, U0131, U0100, U0001, U0121, AND/OR U0151- CLEAR  
CODES AND WIGGLE TEST CONNECTER C139. IFCODES RETURN, BYPASS C139 FOR  
CIRCUITS VDB04 AND VDB05 USING THE SOLDER AND SHRINK TUBING METHOD  
FOUND IN SECTION 5 OF THE WIRING DIAGRAMS.

---

**From:** Napoli, Laura (L.)  
**Sent:** Wednesday, June 15, 2011 2:03 PM  
**To:** Buelow, Steve (S.E.); Anderson, Eric (H.); Mrozek, Robert (R.M.); Annadi, Hari (H.); Cassata, Joe (J.)  
**Cc:** Perri, Ron (R.J.)  
**Subject:** RE: 2011 Exp - BG [REDACTED] - No steering assist, 5016 mi, BD 12/2/10

Steve,

We already looked this vehicle up and saw that there is a B3A code for this vehicle (motor relay failure). There is an open BSAQ in the system for this failure mode (relay contamination: [SAQ2011161617](#)). Once we get the part back through the warranty system, we can investigate if this part was built before or after the PCA's went into place at the Tier 4.

Regards,

*Laura Napoli*

U502 EPAS  
Ford Motor Company  
Cube: 2B-G66 PDC  
Phone: 313.323.0634  
Mobile: 313.805.0482

---

**From:** Buelow, Steve (S.E.)  
**Sent:** Wednesday, June 15, 2011 1:27 PM  
**To:** Annadi, Hari (H.); Napoli, Laura (L.); Mrozek, Robert (R.M.); Adamczyk, David (D.W.); Bollwahn, Bryce (B.A.); Centlivre, James (J.C.); Cheatham, Sandy (.); Cittadino, Lisa (L.C.); Collins, Kevin (K.E.); Gagnier, Kathryn (K.A.); Gilewski, David (D.); Gillanders, Eric (E.S.); Gubing, William (Bill.); Hays, Andy (A.R.); Krochmalny, Kevin (K.); Mann, Mickey (N.S.); McClain, Shawn (S.M.); Pogorzelski, John (J.M.); Rodgers, Chuck (.); Saleh, Salim (S.A.); Sellers, Gary (G.T.); Shaukat, Nadeem (N.S.); Simkus, Walter (W.A.); Sokolowski, Todd (T.M.); Thornsberry, Joel (J.A.); Willis, Mark (M.E.); Wong, Vicki (V.A.); Acuna, Aaron (A.A.); Allman, Jan (J.E.); Bell, Tim (.); Bergeron, Matthew (M.C.); Bisaga, Richard (R.); Boykin, George (G.); Boykins, Michael (M.); Bustamante, Chris (C.T.); Cantrell, David (D.D.); Carter, Tracy (T.); Chones, Marvin (M.); Ciotti, Steven (S.R.); Davis, Charlene (C.); Devine, Robert (R.M.); Docimo, Tony (A.F.); Ferguson, Hugh (H.); Gagnier, Scott (S.W.); Greenwell, R (R.); Guyton, MzJenny (J.); Hernandez, Thomas (T.); Herron, Micheal (M.C.); Inglis, Steve (S.D.); Iqbal, Khurram (K.); Jones, Frederick (F.L.); Little, Janie (J.); Lux, Tracie (T.L.); Martin, Kenneth (K.A.); Matlock, Douglas (D.); McElroy, Darin (D.L.); McKernan, Patrick (P.J.); Miller, Melinda (M.S.); Moore, Chikynda (D.); Moskwa, Larry (L.M.); Perkins, John (J.E.); Russell, David (D.A.); Rutovic, Nick (N.); Sarkisian, Mark (Z.); Talbott, Larry (J.L.); Turner, Bridgette (B.); Turner, Patrice (P.T.); Vandergroef, Cornelius (C.); Washington, Kellie (K.S.); Wertman, David Brian (D.B.); Westbrook, Dori (D.); Williams, Erik (E.C.); Williams, Gregory (G.M.); Wyatt, Kimberly (K.D.); Zroback, David (D.P.); Armstrong, Miya (M.); Buerger, Robert (R.G.); Evans, Kayekethia (K.); Gibson, Renelda (R.); Lakomek, Scott (S.); Napier, S (S.); Ornelas, Demetrio (D.); Ratliff, Kathy (K.); Scheldberg, Gary (G.D.); Stonewall, Wendy (M.); Svetich, Chris (C.); Torian, Jason (J.B.); Anderson, Eric (H.); Berzeri, Marcello (M.); Cassata, Joe (J.); Chamberlain, Steve (J.); Edwards, Monty (M.R.); Farmer, Marty (M.F.); Feder, Andrew (A.); Gerrard, Ryan (R.P.); Iannotti, Jason (JRI.); Ickes, Walt (W.D.); Issa, Ibrahim (I.M.); Jackson, Bradley (B.G.); Logli, Michael (M.A.); Morgan, Anthony (A.); Olsson, Paul (P.C.); Polaski, Mike (M.S.); Porter, Alan (A.T.); Rapiz, Noreen (N.G.); Santilli, Rennie (R.); Smith, Erin (E.); Sridhara, Raghu (R.); Trygar, Mike (M.); Vargo, Rebecca (R.L.); Widrick, Brad (B.A.); Young, Richard (R.C.); Yu, Eric (E.); Buelow, Steve (S.E.)  
**Subject:** FW: 2011 Exp - B [REDACTED] - No steering assist, 5016 mi, BD 12/2/10

**-The Customer Defines Quality-**

*Steve Buelow - Ford Motor Company*

FCSD Program Manager-  
Taurus/Taurus SHO/Lincoln MKS/Explorer  
Chicago Assembly PVT Office, COE  
773-646-7495 DialNet 686-7495  
Cell 773-726-0808 sbuelow@ford.com

"Quality means doing it right when no one is looking." - Henry Ford

---

**From:** SBUELOW@ford.com [mailto:SBUELOW@ford.com]  
**Sent:** Wednesday, June 15, 2011 12:07 PM  
**To:** Buelow, Steve (S.E.)  
**Subject:** 2011 Exp - BG [REDACTED] - No steering assist, 5016 mi, BD 12/2/10

**Attachments :** 0

<b>Report# :</b>	BFNC5004 NHL	<b>Received:</b>	06/14/2011
<b>CCRG/EPRC:</b>		<b>Date:</b>	
<b>Vehicle:</b>	2011,EXPLORER 4X4 (U502),4 DOOR ,MP,1FMHK8B88BG [REDACTED]	<b>Build Date:</b>	12/02/2010
<b>Odometer :</b>	5,016 M	<b>Engine:</b>	3.5L CYCLO
<b>Transmission:</b>	6F55	<b>Calibration:</b>	BUB1ST0A
<b>Dealer:</b>	USA 02199 Bob Gillingham Ford, Inc.	<b>A/C:</b>	YES
<b>City:</b>	Parma	<b>Phone#:</b>	(216) 398- 1300
<b>Originator:</b>	DINO MICELI	<b>State:</b>	Ohio
<b>Symptom:</b>	3 03 1 50 CHASS.,STRG/HANDLING ,FUNCTION,HIGH EFFORT	<b>Country :</b>	USA
<b>Status:</b>			
<b>VFG:</b>	V87 STEERING		
<b>Additional Symptom:</b>	NO STEERING ASSIST		
<b>Fix:</b>	<b>Causal Component :</b>		
<b>Condition Code:</b>			
<b>Hotliner:</b> JTAYL466	<b>Phone:</b> 000 000-0000	<b>Regn Cd:</b> G4 Pittsburgh	
<b>Engineering:</b>	<b>Phone:</b>	<b>TAR:</b>	



**Dlr Contact:** DINO MICELI

**Phone:** 216 398-1300

**Title Cde:** T

**DTCs:**

KOEO:C1B00 U3000 U2011

KOEC:

KOER:

**Comments**

:

**REPAIR** 06/14/2011 12:25PM JASON TAYLOR MSS - FCSD - TECH SVC HOTLINE  
WEB FORM DATA - CONCERN: NO POWER STEERING DIAGNOSTICS: VISUAL,  
PINPOINT TEST B. LEAD TO RWEPLACED RACK PARTS REPLACED::  
NONE TECH QUESTION: PINPOINT TEST LEAD TO REPLACE RACK. NEVER HAD U  
CHECK POWERS AND GROUNDS TO RACK JUST VISUAL ON WIRES AND  
CONNECTORS.  
ANY KNOWN CONCERNS. ALSO SHOULD SSM 21737 BE PERFORMED. WERE YOU  
ABLE TO VERIFY THE CONCERN? YES IS THERE AN APPROPRIATE PINPOINT  
TEST IN THE WSM FOR THIS CONCERN? YES WAS THE PINPOINT TEST  
FOLLOWED? YES

**RECOMM** 06/14/2011 12:25PM JASON TAYLOR MSS - FCSD - TECH SVC HOTLINE  
DINO, THE SSM 21737 IS ADDRESSING AN INTERMITTENT COMMUNICATION  
CONCERN WITH THE PSCM AND IS SPECIFIC TO THE CODES LISTED IN THE SSM.  
THIS VEHICLE DOES FALL WITHIN THE BUILD DATE OF THE SSM SO I WOULD  
SUGGEST INSPECTING THESE PINS FOR ANY LOOSENESS OR DAMAGE. IF ANY PIN  
FIT ISSUES ARE FOUND, THEN I WOULD SUGGEST PERFORMING THE SSM 21737.  
IF NO PIN FIT ISSUES ARE FOUND OR THE CONCERN IS STILL PRESENT AFTER  
PERFORMING THE SSM, THEN SUGGEST PERFORMING A LOAD TEST ON THE  
POWER  
AND GROUND TO PSCM. IF THE POWERS AND GROUND CIRCUITS PROVE OUT,  
THEN  
SUGGEST REPLACING THE RACK FOR THIS CONCERN. SSM 21737 CODES C1B00,  
U0131, U0100, U0001, U0121, AND/OR U0151- CLEAR CODES AND WIGGLE TEST  
CONNECTER C139. IFCODES RETURN, BYPASS C139 FOR CIRCUITS VDB04 AND  
VDB05 USING THE SOLDER AND SHRINK TUBING METHOD FOUND IN SECTION 5  
OF  
THE WIRING DIAGRAMS.

---

**From:** Estes, Eric (E.E.)  
**Sent:** Thursday, January 13, 2011 9:49 AM  
**To:** Mrozek, Robert (R.M.)  
**Cc:** Snider, Tim (T.O.)  
**Subject:** RE: 2011 Exp - BG [REDACTED] - Loss of power steering, lamp on, 18 mi, BD 12/16/10

I looked at Interactive diagnosis and cannot tell if the tech cleared the code and the code reset look below

**Year = MY11**  
**Model = U502**  
**Engine =**  
**VIN = 1FMHK8D83BG [REDACTED]**  
**IDS Version = Not Available**

---

**Start: Wed Jan 12 15:50:58 EST 2011**

---

Menu Selection: DTC U2011 (PSCM) - Motor

---

B: DTCs C1B00, C200B, C200C, C200D, U2011, U2200 and U3000: Steering Angle Sensor, Steering Shaft Torque Sensor 1, Steering Shaft Torque Sensor 2, Motor and Control Module - Failure or Erratic

Normal Operation

The power steering control module (PSCM) monitors various inputs and outputs of the electronic power assist steering (EPAS) system in order to keep the system operating at peak capacity. Information provided by sensors (steering torque, vehicle speed, vehicle travel distance, etc.) are all compared to programmed and learned information. Likewise, outputs like the motor and steering rack (travel) are tested against programmed and learned information.

Note:

If a damaged bellows boot(s) was discovered during Inspection and Verification and this pinpoint test DOES NOT lead to the installation of a new EPAS gear or bellows boot(s), then go to Pinpoint Test K to address the damaged boot(s) before returning the vehicle to the customer.

---

B1: CHECK FOR PREVIOUSLY SET DTCS

- Go to KNOWN CONCERNS.

Check for DTCs listed in the section: System Related CMDTCS cleared since initial read.

- Are any of the following DTCs present?

PSCM DTCs C1B00:2F, C1B00:62, C200B:2F, C200B:61, C200B:62, U2011:49, U2011:61, U2200:54, U3000:41, U3000:46, U3000:49.

Yes  
Go to B2.

No  
Go to B2.

---

**Exit: Wed Jan 12 15:51:44 EST 2011**

---

**From:** Mrozek, Robert (R.M.)  
**Sent:** Thursday, January 13, 2011 9:45 AM  
**To:** Estes, Eric (E.E.)  
**Subject:** RE: 2011 Exp - BG [REDACTED] - Loss of power steering, lamp on, 18 mi, BD 12/16/10

Is there anything else you can find from the available on-line systems? Please compile all you can. Thanks Eric.

*Rob Mrozek*

Electric Power Steering Supervisor  
C346N/CD3/D3/D4/U502/Police/Limo Programs  
Ford Motor Company  
Phone: (313) 805-5947  
e-mail: rmrozek@ford.com

---

**From:** Estes, Eric (E.E.)  
**Sent:** Thursday, January 13, 2011 9:43 AM  
**To:** Mrozek, Robert (R.M.); Jackson, Bradley (B.G.); Napoli, Laura (L.)  
**Cc:** Snider, Tim (T.O.)  
**Subject:** RE: 2011 Exp - BG [REDACTED] - Loss of power steering, lamp on, 18 mi, BD 12/16/10

This is a B3A or B6B code most likely, but it also could be a BB5-BB9 code which is a motor phase voltage high or low fault

Eric

---

**From:** Mrozek, Robert (R.M.)  
**Sent:** Thursday, January 13, 2011 9:28 AM  
**To:** Jackson, Bradley (B.G.); Napoli, Laura (L.); Estes, Eric (E.E.)  
**Cc:** Snider, Tim (T.O.); Mrozek, Robert (R.M.)  
**Subject:** FW: 2011 Exp - BG [REDACTED] - Loss of power steering, lamp on, 18 mi, BD 12/16/10  
**Importance:** High

Brad - Damn it! I should have shut my mouth yesterday.

Laura - Please dig into this asap.

Eric - What can you tell us about the codes or any other info on this gear?

*Rob Mrozek*

Electric Power Steering Supervisor  
C346N/CD3/D3/D4/U502/Police/Limo Programs  
Ford Motor Company  
Phone: (313) 805-5947  
e-mail: rmrozek@ford.com

---

**From:** Saleh, Salim (S.A.)  
**Sent:** Thursday, January 13, 2011 9:24 AM  
**To:** Napoli, Laura (L.); Pasquarella, Michael (M.S.); Mrozek, Robert (R.M.)  
**Subject:** FW: 2011 Exp - BG [REDACTED] - Loss of power steering, lamp on, 18 mi, BD 12/16/10

fyi..

**Salim Saleh**

U502 Explorer  
Chassis PMT Leader  
Phone: (313)805-2451 Fax: (313)322-0744  
ssaleh@ford.com Cubicle: 2B-L37  
<http://vm7.dearborn.ford.com/cgi/textpage>

---

**From:** Buelow, Steve (S.E.)  
**Sent:** Thursday, January 13, 2011 9:22 AM  
**To:** Adamczyk, David (D.W.); Bollwahn, Bryce (B.A.); Centlivre, James (J.C.); Cittadino, Lisa (L.C.); Collins, Kevin (K.E.); Gagnier, Kathryn (K.A.); Gilewski, David (D.); Gubing, William (Bill.); Hays, Andy (A.R.); Henker, Scott (S.); Holland, James (J.P.); Lubin Henney, Michele (MLH.); Lysik, Kevin (K.M.); Mann, Mickey (N.S.); McClain, Shawn (S.M.); Pogorzelski, John (J.M.); Rodgers, Chuck (.); Saleh, Salim (S.A.); Sellers, Gary (G.T.); Simkus, Walter (W.A.); Smith, Scott (S.A.); Sokolowski, Todd (T.M.); Thornsberry, Joel (J.A.); Willis, Mark (M.E.); Wong, Vicki (V.A.); Abrams, Donald (D.); Acuna, Aaron (A.A.); Allman, Jan (J.E.); Bell, Tim (.); Bergeron, Matthew (M.C.); Bisaga, Richard (R.); Boykin, George (G.); Boykins, Michael (M.); Bustamante, Chris (C.T.); Cantrell, David (D.D.); Ciotti, Steven (S.R.); Davis, Charlene (C.); Devine, Robert (R.M.); Docimo, Tony (A.F.); Elting, Tim (T.H.); Ferguson, Hugh (H.); Gagnier, Scott (S.W.); Greenwell, R (R.); Guyton, MzJenny (J.); Hernandez, Thomas (T.); Herron, Micheal (M.C.); Inglis, Steve (S.D.); Iqbal, Khurram (K.); Jones, Frederick (F.L.); Little, Janie (J.); Martin, Kenneth (K.A.); Matlock, Douglas (D.); McElroy, Darin (D.L.); McKernan, Patrick (P.J.); Miller, Melinda (M.S.); Moore, Chikynda (D.); Moses, Barry (B.A.); Moskwa, Larry (L.M.); Perkins, John (J.E.); Pesch, Vincent (V.J.); Rutovic, Nick (N.); Sarkisian, Mark (Z.); Talbott, Larry (J.L.); Turner, Bridgette (B.); Turner, Patrice (P.T.); Vandergroef, Cornelius (C.); Washington, Kellie (K.S.); Wertman, David Brian (D.B.); Westbrook, Dori (D.); Williams, Erik (E.C.); Williams, Gregory (G.M.); Williams, TRACE (S.); Wyatt, Kimberly (K.D.); Zroback, David (D.P.); Evans, Kayekethia (K.); Gibson, Renelda (R.); Lakomek, Scott (S.); Ornelas, Demetrio (D.); Ratliff, Kathy (K.); Stonewall, Wendy (M.); Svetich, Chris (C.); Anderson, Eric (H.); Berzeri, Marcello (M.); Chamberlain, Steve (J.); Edwards, Monty (M.R.); Farmer, Marty (M.F.); Feder, Andrew (A.); Gerrard, Ryan (R.P.); Iannotti, Jason (JRI.); Ickes, Walt (W.D.); Imperati, Daniel (D.); Issa, Ibrahim (I.M.); Jackson, Bradley (B.G.); Logli, Michael (M.A.); Morgan, Anthony (A.); Olsson, Paul (P.C.); Polaski, Mike (M.S.); Porter, Alan (A.T.); Rapiz, Noreen (N.G.); Siddiqui, Saif (S.S.); Sluis, Jim (JS.); Smith, Erin (E.); Sridhara, Raghu (R.); Trygar, Mike (M.); Vargo, Rebecca (R.L.); Widrick, Brad (B.A.); Young, Richard (R.C.); Yu, Eric (E.); Buelow, Steve (S.E.)  
**Subject:** FW: 2011 Exp - BG [REDACTED] - Loss of power steering, lamp on, 18 mi, BD 12/16/10

**-The Customer Defines Quality-**

*Steve Buelow - Ford Motor Company*

FCSD Program Manager-  
Taurus/Taurus SHO/Lincoln MKS/Explorer  
Chicago Assembly PVT Office, COE  
773-646-7495 DialNet 686-7495  
Cell 313-805-8334 sbuelow@ford.com

"You miss 100 percent of the shots you never take." - Wayne Gretzky

---

**From:** SBUELOW@ford.com [mailto:SBUELOW@ford.com]  
**Sent:** Thursday, January 13, 2011 8:15 AM  
**To:** Buelow, Steve (S.E.)  
**Subject:** 2011 Exp - BG [REDACTED] - Loss of power steering, lamp on, 18 mi, BD 12/16/10

**Attachments :** 0

**Report# :** BALEI002 NHL **Received:** 01/12/2011  
**CCRG/EPRC:** **Reviewed Status:** **Date:**  
**Vehicle:** 2011,EXPLORER 4X4 (U502),4 DOOR **Build Date:** 12/16/2010  
,MP,1FMHK8D83BG [REDACTED]  
**Odometer :** 18 M **Engine:** 3.5L **Calibration:** BUB1ST0A  
CYCLO  
**Transmission:** 6F55 **Axle:** **A/C:** YES  
**Dealer:** USA 09618 Brown Motors, Inc. **Phone#:** (231!!) 439-9604  
**City:** Petoskey **State:** Michigan **Country :** USA  
**Originator:** JIM MILBRANDT  
**Symptom:** 3 03 1 50 CHASS.,STRG/HANDLING ,FUNCTION,HIGH EFFORT  
**Status:**  
**VFG:** V87 STEERING  
**Additional Symptom:** LOSS OF POWER STEERING  
**Fix:** **Causal Component :**  
**Condition Code:**

**Hotliner:** DMU!! RRA86 **Phone:** 313 248-8233 **Regn Cd:** G2 Detroit  
**Engineering:** **Phone:** **TAR:**  
**Dlr Contact:** JIM MILBRANDT **Phone:** 231 439-3673 **Title Cde:** T

**DTCs:**

KOEO:U0253 U2011  
KOEC:  
KOER:

**Comments**

**:**  
REPAIR 01/12/2011 02:45PM DOUGLAS MURRAY MSS - FCSD - TECH SVC HOTLINE  
WEB FORM DATA - CONCERN: CUSTOMER STATES WHEN ON TEST DRIVE THE  
POWER

STEERING QUIT AND A RED INDICATOR LIGHT CAME ONE. DIAGNOSTICS:  
PERFORMED IDS TESTS U0253:00-28 IPC U2011:49-08 PSCM IN MEMORY  
PARTS REPLACED:: NONE TECH QUESTION: ANY REPORTS FOR THIS  
CONCERN? WERE YOU ABLE TO VERIFY THE CONCERN? NO IS THERE AN  
APPROPRIATE PINPOINT TEST IN THE WSM FOR THIS CONCERN? WAS THE  
PINPOINT TEST FOLLOWED?

**RECOMM** 01/12/2011 02:45PM DOUGLAS MURRAY MSS - FCSD - TECH SVC HOTLINE  
JIM, IT IS RECOMMENDED TO GO TO THE WSM SECTION 211-00/DIAGNOSIS  
AND TESTING/DTC AND SYMPTOM CHARTS/INTERACTIVE DIAGNOSTICS AND GO  
TO  
THE INTERACTIVE DIAGNOSTICS SECTION. FROM THERE, GO TO THE DTC LIST  
AND LOOK UP U2011. THIS IS A MOTOR CODE AND THERE ARE 2 DIFFERENT PPT  
TESTS DEPENDING ON WHICH BITMAP CODE YOU HAVE. THIS CODE INDICATES  
THAT THE PSCM HAS SEEN A MOTOR ISSUE AND WILL SHUT DOWN THE POWER  
ASSIST FUNCTION. PLEASE TRY TO DUPLICATE THE CONCERN AND IF CODE  
U2011 SETS, PERFORM THE APPROPRIATE CHART. THERE ARE NO COMMON  
TRENDS FOR THIS CONCERN. THANK YOU.

---

**From:** Napoli, Laura (L.)  
**Sent:** Monday, January 31, 2011 3:13 PM  
**To:** Saleh, Salim (S.A.); Mrozek, Robert (R.M.)  
**Subject:** RE: 2011 Exp - BG [REDACTED] - Power steering inop, 12 mi, BD 1/12/11

Thanks Salim. We got this one handled over the weekend. The gear is on it's way to TRW today.

---

**From:** Saleh, Salim (S.A.)  
**Sent:** Monday, January 31, 2011 2:21 PM  
**To:** Mrozek, Robert (R.M.); Napoli, Laura (L.)  
**Subject:** FW: 2011 Exp - BG [REDACTED] - Power steering inop, 12 mi, BD 1/12/11

FYI..

### **Salim Saleh**

U502 Explorer

Chassis PMT Leader

Phone: (313)805-2451

ssaleh@ford.com

<http://vm7.dearborn.ford.com/cgi/textpage>

Fax: (313)322-0744

Cubicle: 2B-L37

---

**From:** Buelow, Steve (S.E.)  
**Sent:** Monday, January 31, 2011 1:42 PM  
**To:** Adamczyk, David (D.W.); Bollwahn, Bryce (B.A.); Centlivre, James (J.C.); Cheatham, Sandy (.); Cittadino, Lisa (L.C.); Collins, Kevin (K.E.); Gagnier, Kathryn (K.A.); Gilewski, David (D.); Gubing, William (Bill.); Hays, Andy (A.R.); Henker, Scott (S.); Lubin Henney, Michele (MLH.); Lysik, Kevin (K.M.); Mann, Mickey (N.S.); McClain, Shawn (S.M.); Pogorzelski, John (J.M.); Rodgers, Chuck (.); Saleh, Salim (S.A.); Sellers, Gary (G.T.); Shaukat, Nadeem (N.S.); Simkus, Walter (W.A.); Smith, Scott (S.A.); Sokolowski, Todd (T.M.); Thornsberry, Joel (J.A.); Willis, Mark (M.E.); Wong, Vicki (V.A.); Abrams, Donald (D.); Acuna, Aaron (A.A.); Allman, Jan (J.E.); Bell, Tim (.); Bergeron, Matthew (M.C.); Bisaga, Richard (R.); Boykin, George (G.); Boykins, Michael (M.); Bustamante, Chris (C.T.); Cantrell, David (D.D.); Ciotti, Steven (S.R.); Davis, Charlene (C.); Devine, Robert (R.M.); Docimo, Tony (A.F.); Elting, Tim (T.H.); Ferguson, Hugh (H.); Gagnier, Scott (S.W.); Greenwell, R (R.); Guyton, MzJenny (J.); Hernandez, Thomas (T.); Herron, Micheal (M.C.); Inglis, Steve (S.D.); Iqbal, Khurram (K.); Jones, Frederick (F.L.); Little, Janie (J.); Martin, Kenneth (K.A.); Matlock, Douglas (D.); McElroy, Darin (D.L.); McKernan, Patrick (P.J.); Miller, Melinda (M.S.); Moore, Chikynda (D.); Moses, Barry (B.A.); Moskwa, Larry (L.M.); Perkins, John (J.E.); Pesch, Vincent (V.J.); Rutovic, Nick (N.); Sarkisian, Mark (Z.); Smith, Eugenia (E.R.); Talbott, Larry (J.L.); Turner, Bridgette (B.); Turner, Patrice (P.T.); Vandergroef, Cornelius (C.); Washington, Kellie (K.S.); Wertman, David Brian (D.B.); Westbrook, Dori (D.); Williams, Erik (E.C.); Williams, Gregory (G.M.); Williams, TRACE (S.); Wyatt, Kimberly (K.D.); Zroback, David (D.P.); Evans, Kayekethia (K.); Gibson, Renelda (R.); Lakomek, Scott (S.); Ornelas, Demetrio (D.); Ratliff, Kathy (K.); Stonewall, Wendy (M.); Svetich, Chris (C.); Anderson, Eric (H.); Berzeri, Marcello (M.); Chamberlain, Steve (J.); Edwards, Monty (M.R.); Farmer, Marty (M.F.); Feder, Andrew (A.); Gerrard, Ryan (R.P.); Iannotti, Jason (JRI.); Ickes, Walt (W.D.); Imperati, Daniel (D.); Issa, Ibrahim (I.M.); Jackson, Bradley (B.G.); Logli, Michael (M.A.); Morgan, Anthony (A.); Olsson, Paul (P.C.); Polaski, Mike (M.S.); Porter, Alan (A.T.); Rapiz, Noreen (N.G.); Siddiqui, Saif (S.S.); Sluis, Jim (JS.); Smith, Erin (E.); Sridhara, Raghu (R.); Trygar, Mike (M.); Vargo, Rebecca (R.L.); Widrick, Brad (B.A.); Young, Richard (R.C.); Yu, Eric (E.); Buelow, Steve (S.E.)  
**Subject:** FW: 2011 Exp - BG [REDACTED] - Power steering inop, 12 mi, BD 1/12/11

**-The Customer Defines Quality-**

*Steve Buelow - Ford Motor Company*

FCSD Program Manager-  
Taurus/Taurus SHO/Lincoln MKS/Explorer  
Chicago Assembly PVT Office, COE  
773-646-7495 DialNet 686-7495  
Cell 313-805-8334 sbuelow@ford.com

"You miss 100 percent of the shots you never take." - Wayne Gretzky

---

**From:** SBUELOW@ford.com [mailto:SBUELOW@ford.com]  
**Sent:** Monday, January 31, 2011 10:18 AM  
**To:** Buelow, Steve (S.E.)  
**Subject:** 2011 Exp - BG [REDACTED] - Power steering inop, 12 mi, BD 1/12/11

**Attachments :** 0

<b>Report# :</b>	BA2AK005 NHL	<b>Received:</b>	01/28/2011
<b>CCRG/EPRC:</b>		<b>Date:</b>	
<b>Vehicle:</b>	2011,EXPLORER 4X4 (U502),4 DOOR ,MP,1FMHK8D83BG [REDACTED]	<b>Build Date:</b>	01/12/2011
<b>Odometer :</b>	12 M	<b>Engine:</b>	3.5L CYCLO
<b>Transmission:</b>	6F55	<b>Axle:</b>	
<b>Dealer:</b>	USA 02071 I77 Ford Mercury	<b>Calibration:</b>	BUB1ST0A
<b>City:</b>	Ripley	<b>A/C:</b>	YES
<b>State:</b>		<b>Phone#:</b>	(304! ! ) 372- 2480
<b>Originator:</b>	JOHNATHAN FRYE	<b>Country :</b>	USA
<b>Symptom:</b>	3 03 1 50 CHASS.,STRG/HANDLING ,FUNCTION,HIGH EFFORT		
<b>Status:</b>			
<b>VFG:</b>	V87 STEERING		
<b>Additional Symptom:</b>	POWER STEERING INOP		
<b>Fix:</b>	<b>Causal Component :</b>		
<b>Condition Code:</b>			

**Hotliner:** I ! ! WRIGH24

**Phone:** 313 317-4284

**Regn Cd:** G3 Cincinnati

**Engineering:**

**Phone:**

**TAR:**



**Dlr Contact:** JOHNATHAN FRYE

**Phone:** 304 372-3673

**Title Cde:** SM

**DTCs:**

KOEO:U3000

KOEC:

KOER:

**Comments**

:

**REPAIR** 01/28/2011 08:35AM IAN WRIGHT MSS - FCSD - TECH SVC HOTLINE  
WEB FORM DATA - CONCERN: POWER STEERING IS INOP DIAGNOSTICS: KOEO  
KOER PINPOINT TEST C1 PARTS REPLACED:: NO AT THIS TIME TECH  
QUESTION: ANY KNOWN CONCERNS WITH STEERING RACK WERE YOU ABLE TO  
VERIFY THE CONCERN? YES IS THERE AN APPROPRIATE PINPOINT TEST IN  
THE WSM FOR THIS CONCERN? YES WAS THE PINPOINT TEST FOLLOWED? YES

**RECOMM** 01/28/2011 08:35AM IAN WRIGHT MSS - FCSD - TECH SVC HOTLINE  
JONATHAN. INSPECT CONNECTOR PIN FITS TO THE PSCM. WE HAVE SEEN SOME  
CONCERNS DUE TO SPREAD PINS AT CONNECTOR C139. INSPECT THIS  
CONNECTION  
USING A FLEX PROBE AND REPAIR/REPLACE ANY LOOSE PINS. PERFORM THE  
INTERACTIVE DIAGNOSTICS FOR FURTHER ASSISTANCE DIAGNOSING THIS  
CONCERN. TO PERFORM THE DIAGNOSTICS. CONNECT IDS TO VEHICLE AND GO  
TO  
THE PTS WEB PAGE. OPEN THE ONLINE WORKSHOP MANUAL OPEN SECTION 211-  
00  
AND SELECT DTC CHART INTERACTIVE DIAGNOSTICS.

---

**From:** Napoli, Laura (L.)  
**Sent:** Monday, January 31, 2011 3:15 PM  
**To:** Mrozek, Robert (R.M.); Estes, Eric (E.E.)  
**Subject:** RE: 2011 Exp - BG [REDACTED] - Power steering inop, 12 mi, BD 1/12/11

No. Same C69 in West Virginia.

---

**From:** Mrozek, Robert (R.M.)  
**Sent:** Monday, January 31, 2011 3:08 PM  
**To:** Estes, Eric (E.E.)  
**Cc:** Napoli, Laura (L.)  
**Subject:** FW: 2011 Exp - BG [REDACTED] - Power steering inop, 12 mi, BD 1/12/11

Is this a new one?

*Rob Mrozek*

Electric Power Steering Supervisor  
CD3/D3/D4/U502/Police/Limo EPAS Programs +  
Active Front Steering Applications Engineering  
Ford Motor Company  
Phone: (313) 805-5947  
e-mail: rmrozek@ford.com

---

**From:** Saleh, Salim (S.A.)  
**Sent:** Monday, January 31, 2011 2:21 PM  
**To:** Mrozek, Robert (R.M.); Napoli, Laura (L.)  
**Subject:** FW: 2011 Exp - BG [REDACTED] - Power steering inop, 12 mi, BD 1/12/11

FYI..

**Salim Saleh**

U502 Explorer  
Chassis PMT Leader  
Phone: (313)805-2451 Fax: (313)322-0744  
ssaleh@ford.com Cubicle: 2B-L37  
<http://vm7.dearborn.ford.com/cgi/textpage>

---

**From:** Buelow, Steve (S.E.)  
**Sent:** Monday, January 31, 2011 1:42 PM  
**To:** Adamczyk, David (D.W.); Bollwahn, Bryce (B.A.); Centlivre, James (J.C.); Cheatham, Sandy (.); Cittadino, Lisa (L.C.); Collins, Kevin (K.E.); Gagnier, Kathryn (K.A.); Gilewski, David (D.); Gubing, William (Bill.); Hays, Andy (A.R.); Henker,

Scott (S.); Lubin Henney, Michele (MLH.); Lysik, Kevin (K.M.); Mann, Mickey (N.S.); McClain, Shawn (S.M.); Pogorzelski, John (J.M.); Rodgers, Chuck (.); Saleh, Salim (S.A.); Sellers, Gary (G.T.); Shaukat, Nadeem (N.S.); Simkus, Walter (W.A.); Smith, Scott (S.A.); Sokolowski, Todd (T.M.); Thornsberry, Joel (J.A.); Willis, Mark (M.E.); Wong, Vicki (V.A.); Abrams, Donald (D.); Acuna, Aaron (A.A.); Allman, Jan (J.E.); Bell, Tim (.); Bergeron, Matthew (M.C.); Bisaga, Richard (R.); Boykin, George (G.); Boykins, Michael (M.); Bustamante, Chris (C.T.); Cantrell, David (D.D.); Ciotti, Steven (S.R.); Davis, Charlene (C.); Devine, Robert (R.M.); Docimo, Tony (A.F.); Elting, Tim (T.H.); Ferguson, Hugh (H.); Gagnier, Scott (S.W.); Greenwell, R (R.); Guyton, MzJenny (J.); Hernandez, Thomas (T.); Herron, Micheal (M.C.); Inglis, Steve (S.D.); Iqbal, Khurram (K.); Jones, Frederick (F.L.); Little, Janie (J.); Martin, Kenneth (K.A.); Matlock, Douglas (D.); McElroy, Darin (D.L.); McKernan, Patrick (P.J.); Miller, Melinda (M.S.); Moore, Chikynda (D.); Moses, Barry (B.A.); Moskwa, Larry (L.M.); Perkins, John (J.E.); Pesch, Vincent (V.J.); Rutovic, Nick (N.); Sarkisian, Mark (Z.); Smith, Eugenia (E.R.); Talbott, Larry (J.L.); Turner, Bridgette (B.); Turner, Patrice (P.T.); Vandergroef, Cornelius (C.); Washington, Kellie (K.S.); Wertman, David Brian (D.B.); Westbrook, Dori (D.); Williams, Erik (E.C.); Williams, Gregory (G.M.); Williams, TRACE (S.); Wyatt, Kimberly (K.D.); Zroback, David (D.P.); Evans, Kayekethia (K.); Gibson, Renelda (R.); Lakomek, Scott (S.); Ornelas, Demetrio (D.); Ratliff, Kathy (K.); Stonewall, Wendy (M.); Svetich, Chris (C.); Anderson, Eric (H.); Berzeri, Marcello (M.); Chamberlain, Steve (J.); Edwards, Monty (M.R.); Farmer, Marty (M.F.); Feder, Andrew (A.); Gerrard, Ryan (R.P.); Iannotti, Jason (JRI.); Ickes, Walt (W.D.); Imperati, Daniel (D.); Issa, Ibrahim (I.M.); Jackson, Bradley (B.G.); Logli, Michael (M.A.); Morgan, Anthony (A.); Olsson, Paul (P.C.); Polaski, Mike (M.S.); Porter, Alan (A.T.); Rapiz, Noreen (N.G.); Siddiqui, Saif (S.S.); Sluis, Jim (JS.); Smith, Erin (E.); Sridhara, Raghu (R.); Trygar, Mike (M.); Vargo, Rebecca (R.L.); Widrick, Brad (B.A.); Young, Richard (R.C.); Yu, Eric (E.); Buelow, Steve (S.E.)

**Subject:** FW: 2011 Exp - BG [REDACTED] - Power steering inop, 12 mi, BD 1/12/11

**-The Customer Defines Quality-**

*Steve Buelow - Ford Motor Company*

FCSD Program Manager-  
Taurus/Taurus SHO/Lincoln MKS/Explorer  
Chicago Assembly PVT Office, COE  
773-646-7495 DialNet 686-7495  
Cell 313-805-8334 sbuelow@ford.com

"You miss 100 percent of the shots you never take." - Wayne Gretzky

---

**From:** SBUELOW@ford.com [mailto:SBUELOW@ford.com]  
**Sent:** Monday, January 31, 2011 10:18 AM  
**To:** Buelow, Steve (S.E.)  
**Subject:** 2011 Exp - BG [REDACTED] - Power steering inop, 12 mi, BD 1/12/11

**Attachments :** 0

<b>Report# :</b>	BA2AK005 NHL	<b>Received:</b>	01/28/2011
<b>CCRG/EPRC:</b>		<b>Date:</b>	
<b>Vehicle:</b>	2011,EXPLORER 4X4 (U502),4 DOOR ,MP,1FMHK8D83BG [REDACTED]	<b>Build Date:</b>	01/12/2011
<b>Odometer :</b>	12 M	<b>Engine:</b>	3.5L CYCLO
		<b>Calibration:</b>	BUB1ST0A

**Transmission:** 6F55                      **Axle:**    **A/C:** YES  
**Dealer:** USA 02071 I77 Ford Mercury    **Phone#:** (304! ! ) 372-2480  
**City:** Ripley                      **State:**    West Virginia                      **Country :** USA  
**Originator:** JOHNATHAN FRYE  
**Symptom:** 3 03 1 50 CHASS.,STRG/HANDLING ,FUNCTION,HIGH EFFORT  
**Status:**  
**VFG:** V87 STEERING  
**Additional Symptom:** POWER STEERING INOP  
**Fix:**                      **Causal Component :**  
**Condition Code:**

**Hotliner:** I ! ! WRIGH24                      **Phone:** 313 317-4284                      **Regn Cd:** G3 Cincinnati  
**Engineering:**    **Phone:**    **TAR:**  
**Dlr Contact:** JOHNATHAN FRYE                      **Phone:** 304 372-3673                      **Title Cde:** SM

**DTCs:**  
KOEO:U3000  
KOEC:  
KOER:

**Comments**

**:**  
**REPAIR** 01/28/2011 08:35AM IAN WRIGHT MSS - FCSD - TECH SVC HOTLINE  
WEB FORM DATA - CONCERN: POWER STEERING IS INOP DIAGNOSTICS: KOEO  
KOER PINPOINT TEST C1 PARTS REPLACED:: NO AT THIS TIME TECH  
QUESTION: ANY KNOWN CONCERNS WITH STEERING RACK WERE YOU ABLE TO  
VERIFY THE CONCERN? YES IS THERE AN APPROPRIATE PINPOINT TEST IN  
THE WSM FOR THIS CONCERN? YES WAS THE PINPOINT TEST FOLLOWED? YES  
**RECOMM** 01/28/2011 08:35AM IAN WRIGHT MSS - FCSD - TECH SVC HOTLINE  
JONATHAN. INSPECT CONNECTOR PIN FITS TO THE PSCM. WE HAVE SEEN SOME  
CONCERNS DUE TO SPREAD PINS AT CONNECTOR C139. INSPECT THIS  
CONNECTION  
USING A FLEX PROBE AND REPAIR/REPLACE ANY LOOSE PINS. PERFORM THE  
INTERACTIVE DIAGNOSTICS FOR FURTHER ASSISTANCE DIAGNOSING THIS  
CONCERN. TO PERFORM THE DIAGNOSTICS. CONNECT IDS TO VEHICLE AND GO  
TO  
THE PTS WEB PAGE. OPEN THE ONLINE WORKSHOP MANUAL OPEN SECTION 211-  
00  
AND SELECT DTC CHART INTERACTIVE DIAGNOSTICS.

---

**From:** Anderson, Eric (H.)  
**Sent:** Wednesday, March 09, 2011 4:54 PM  
**To:** Napoli, Laura (L.)  
**Subject:** RE: 2011 Exp - BG [REDACTED] - No steering assist, noisy, 18 mi, BD 1/31/11

Hi Laura:

This claim came through ECB today. I had the gear sent to John Burnett at TRW. The tech was only able to pull the one U0253 code. His interactive diagnostics tool would not work with the gear.

Thanks,

Eric

---

**From:** Napoli, Laura (L.)  
**Sent:** Monday, March 07, 2011 9:41 AM  
**To:** Napoli, Laura (L.); Anderson, Eric (H.)  
**Subject:** RE: 2011 Exp - BG [REDACTED] - No steering assist, noisy, 18 mi, BD 1/31/11

Sorry, you didn't call on this. It was Eric Estes.

Eric Estes called last week and is trying to get EPAS codes and more info to understand the "growl". Trying to understand if there was a boot leak causing contamination.

---

**From:** Napoli, Laura (L.)  
**Sent:** Monday, March 07, 2011 10:39 AM  
**To:** Anderson, Eric (H.)  
**Subject:** RE: 2011 Exp - BG [REDACTED] - No steering assist, noisy, 18 mi, BD 1/31/11

You already called them once, right? Just see if you can ask questions to understand the "growl" and if it's rack noise or actually motor. And need codes. I think you already asked for this.

---

**From:** Anderson, Eric (H.)  
**Sent:** Monday, March 07, 2011 10:19 AM  
**To:** Napoli, Laura (L.)  
**Subject:** FW: 2011 Exp - BG [REDACTED] - No steering assist, noisy, 18 mi, BD 1/31/11

FYI. I'll give the dealer a call today to get more of the story. This car did not go over the problem brake fill connector.

Thanks,

Eric

---

**From:** Buelow, Steve (S.E.)  
**Sent:** Thursday, March 03, 2011 3:43 PM  
**To:** Adamczyk, David (D.W.); Bollwahn, Bryce (B.A.); Centlivre, James (J.C.); Cheatham, Sandy (.); Cittadino, Lisa (L.C.); Collins, Kevin (K.E.); Gagnier, Kathryn (K.A.); Gilewski, David (D.); Gray, Carl (C.L.); Gubing, William (Bill.); Hays, Andy

(A.R.); Krochmalny, Kevin (K.); Lysik, Kevin (K.M.); Mann, Mickey (N.S.); McClain, Shawn (S.M.); Pogorzelski, John (J.M.); Rodgers, Chuck (.); Saleh, Salim (S.A.); Sellers, Gary (G.T.); Shaukat, Nadeem (N.S.); Simkus, Walter (W.A.); Sokolowski, Todd (T.M.); Thornsberry, Joel (J.A.); Willis, Mark (M.E.); Wong, Vicki (V.A.); Acuna, Aaron (A.A.); Allman, Jan (J.E.); Bell, Tim (.); Bergeron, Matthew (M.C.); Bisaga, Richard (R.); Boykin, George (G.); Boykins, Michael (M.); Bustamante, Chris (C.T.); Cantrell, David (D.D.); Ciotti, Steven (S.R.); Davis, Charlene (C.); Devine, Robert (R.M.); Docimo, Tony (A.F.); Elting, Tim (T.H.); Ferguson, Hugh (H.); Gagnier, Scott (S.W.); Greenwell, R (R.); Guyton, MzJenny (J.); Hernandez, Thomas (T.); Herron, Micheal (M.C.); Inglis, Steve (S.D.); Iqbal, Khurram (K.); Jones, Frederick (F.L.); Little, Janie (J.); Martin, Kenneth (K.A.); Matlock, Douglas (D.); McElroy, Darin (D.L.); McKernan, Patrick (P.J.); Miller, Melinda (M.S.); Moore, Chikynda (D.); Moskwa, Larry (L.M.); Perkins, John (J.E.); Pesch, Vincent (V.J.); Russell, David (D.A.); Rutovic, Nick (N.); Sarkisian, Mark (Z.); Smith, Eugenia (E.R.); Talbott, Larry (J.L.); Turner, Bridgette (B.); Turner, Patrice (P.T.); Vandergroef, Cornelius (C.); Washington, Kellie (K.S.); Wertman, David Brian (D.B.); Westbrook, Dori (D.); Williams, Erik (E.C.); Williams, Gregory (G.M.); Wyatt, Kimberly (K.D.); Zroback, David (D.P.); Armstrong, Miya (M.); Buerger, Robert (R.G.); Evans, Kayekethia (K.); Gibson, Renelda (R.); Lakomek, Scott (S.); Ornelas, Demetrio (D.); Ratliff, Kathy (K.); Scheldberg, Gary (G.D.); Stonewall, Wendy (M.); Svetich, Chris (C.); Torian, Jason (J.B.); Anderson, Eric (H.); Berzeri, Marcello (M.); Chamberlain, Steve (J.); Edwards, Monty (M.R.); Farmer, Marty (M.F.); Feder, Andrew (A.); Gerrard, Ryan (R.P.); Iannotti, Jason (JRI.); Ickes, Walt (W.D.); Imperati, Daniel (D.); Issa, Ibrahim (I.M.); Jackson, Bradley (B.G.); Logli, Michael (M.A.); Morgan, Anthony (A.); Olsson, Paul (P.C.); Polaski, Mike (M.S.); Porter, Alan (A.T.); Rapiz, Noreen (N.G.); Santilli, Rennie (R.); Sluis, Jim (JS.); Smith, Erin (E.); Sridhara, Raghu (R.); Trygar, Mike (M.); Vargo, Rebecca (R.L.); Widrick, Brad (B.A.); Young, Richard (R.C.); Yu, Eric (E.); Buelow, Steve (S.E.)

**Subject:** FW: 2011 Exp - BG [REDACTED] - No steering assist, noisy, 18 mi, BD 1/31/11

**-The Customer Defines Quality-**

*Steve Buelow - Ford Motor Company*

FCSD Program Manager-  
Taurus/Taurus SHO/Lincoln MKS/Explorer  
Chicago Assembly PVT Office, COE  
773-646-7495 DialNet 686-7495  
Cell 313-805-8334 sbuelow@ford.com

"You miss 100 percent of the shots you never take." - Wayne Gretzky

---

**From:** SBUELOW@ford.com [mailto:SBUELOW@ford.com]  
**Sent:** Thursday, March 03, 2011 12:39 PM  
**To:** Buelow, Steve (S.E.)  
**Subject:** 2011 Exp - BG [REDACTED] - No steering assist, noisy, 18 mi, BD 1/31/11

**Attachments :** 0

<b>Report# :</b>	BCBAW023 NHL	<b>Received:</b>	03/02/2011
<b>CCRG/EPRC:</b>		<b>Date:</b>	
<b>Vehicle:</b>	2011,EXPLORER 4X4 (U502),4 DOOR ,MP,1FMHK8F86BG [REDACTED]	<b>Build Date:</b>	01/31/2011
<b>Odometer :</b>	18 M	<b>Engine:</b>	3.5L CYCLO
		<b>Calibration:</b>	BUB1ST0A

**Transmission:** 6F55                      **Axle:**    **A/C:** YES  
**Dealer:** USA 08398 Don Aadsen Ford    **Phone#:** (406! ! ) 676-4400  
**City:** Ronan                      **State:** Montana                      **Country :** USA  
**Originator:** KEN LOZEAU  
**Symptom:** 3 03 1 50 CHASS.,STRG/HANDLING ,FUNCTION,HIGH EFFORT  
**Status:**  
**VFG:** V87 STEERING  
**Additional Symptom:** LACK OF ASSIST, GROWL NOISE  
**Fix:**                      **Causal Component :**  
**Condition Code:**

**Hotliner:** TFUMER!! OL                      **Phone:** 000 317-9383                      **Regn Cd:** W5 Seattle  
**Engineering:**    **Phone:**    **TAR:**  
**Dlr Contact:** KEN LOZEAU                      **Phone:** 406 676-4420                      **Title Cde:** T

**DTCs:**  
KOEO:U0253  
KOEC:  
KOER:

**Comments**  
:

**REPAIR** 03/02/2011 04:10PM TOM FUMEROLA MSS - FCSD - TECH SVC HOTLINE  
WEB FORM DATA - CONCERN: STEERING ASSIST IS INOP, LOUD GROWLING NOISE  
WHEN ATTEMPTING TO TURN THE STEERING WHEEL DIAGNOSTICS: VISUAL  
INSPECTION IS OK, NO VISIBLE SIGNS OF CAUSE, GROWLING NOISE APPEARS TO  
BE COMING FROM ELECTRIC MOTOR ON STEERING RACK. HOOKED UP IDS AND  
RETRIEVED CONT CODE U0253, TRACTION CONTROL LIGHT IS ON PARTS  
REPLACED.: NONE TECH QUESTION: ANY DIAG ASSISTANCE WOULD BE GREATLY  
APPRECIATED, POWER STEERING WORKED NORMAL UNTIL IT WAS DRIVEN INTO  
WASH BAY THEN QUIT WORKING WERE YOU ABLE TO VERIFY THE CONCERN?  
YES IS THERE AN APPROPRIATE PINPOINT TEST IN THE WSM FOR THIS  
CONCERN? NO WAS THE PINPOINT TEST FOLLOWED? NO

**RECOMM** 03/02/2011 04:10PM TOM FUMEROLA MSS - FCSD - TECH SVC HOTLINE  
KENNETH, IT IS RECOMMENDED TO PERFORM THE INTERACTIVE VEHICLE  
DIAGNOSTICS AVAILABLE THROUGH THE ONLINE WORKSHOP MANUAL 211-00,  
DTC  
AND SYMPTOM CHART. THIS WILL AID IN DIAGNOSING THE SYSTEM. SINCE THE  
MOTOR IS MAKING NOISE THERE MAY BE AN INTERNAL FAULT. SERVICE AS  
NEEDED.

---

**From:** Napoli, Laura (L.)  
**Sent:** Thursday, March 31, 2011 9:02 AM  
**To:** Anderson, Eric (H.); Estes, Eric (E.E.); Jackson, Bradley (B.G.); Issa, Ibrahim (I.M.); Logli, Michael (M.A.)  
**Subject:** RE: 2011 Exp - BG [REDACTED] - Loss of steering assist, 611 mi, BD 2/15/11

Eric Estes,

Please contact this dealer and make sure they understand they are NOT to change the gear without performing the pinout and wiggle tests.

Thanks.

---

**From:** Anderson, Eric (H.)  
**Sent:** Wednesday, March 30, 2011 6:09 PM  
**To:** Napoli, Laura (L.); Estes, Eric (E.E.); Jackson, Bradley (B.G.); Issa, Ibrahim (I.M.); Logli, Michael (M.A.)  
**Subject:** RE: 2011 Exp - BG [REDACTED] - Loss of steering assist, 611 mi, BD 2/15/11

Hi All:

I called the dealership this afternoon and spoke to the repair technician. He explained that this unit is for a local rental car branch and that a new steering gear has been ordered but not installed. He is available to talk tomorrow to figure out if this is an EPAS gear problem or a wiring problem.

Thanks,

Eric

---

**From:** Anderson, Eric (H.)  
**Sent:** Wednesday, March 30, 2011 9:34 AM  
**To:** Napoli, Laura (L.); Estes, Eric (E.E.); Jackson, Bradley (B.G.); Issa, Ibrahim (I.M.); Logli, Michael (M.A.)  
**Subject:** FW: 2011 Exp - BG [REDACTED] - Loss of steering assist, 611 mi, BD 2/15/11

Hi All:

We were talking about this CQIS last week. Is there an update? There weren't any EPAS specific codes and the problem started to look like wiring (the gear wasn't getting any power).

Thanks,

Eric

---

**From:** Docimo, Tony (A.F.)  
**Sent:** Tuesday, March 29, 2011 9:29 PM  
**To:** Anderson, Eric (H.)  
**Subject:** FW: 2011 Exp - BG [REDACTED] - Loss of steering assist, 611 mi, BD 2/15/11

Any more info on this?



---

**From:** Buelow, Steve (S.E.)

**Sent:** Thursday, March 24, 2011 10:26 AM

**To:** Adamczyk, David (D.W.); Bollwahn, Bryce (B.A.); Centlivre, James (J.C.); Cheatham, Sandy (.); Cittadino, Lisa (L.C.); Collins, Kevin (K.E.); Gagnier, Kathryn (K.A.); Gilewski, David (D.); Gillanders, Eric (E.S.); Gray, Carl (C.L.); Gubing, William (Bill.); Hays, Andy (A.R.); Krochmalny, Kevin (K.); Mann, Mickey (N.S.); McClain, Shawn (S.M.); Pogorzelski, John (J.M.); Rodgers, Chuck (.); Saleh, Salim (S.A.); Sellers, Gary (G.T.); Shaukat, Nadeem (N.S.); Simkus, Walter (W.A.); Sokolowski, Todd (T.M.); Thornsberry, Joel (J.A.); Willis, Mark (M.E.); Wong, Vicki (V.A.); Acuna, Aaron (A.A.); Allman, Jan (J.E.); Bell, Tim (.); Bergeron, Matthew (M.C.); Bisaga, Richard (R.); Boykin, George (G.); Boykins, Michael (M.); Bustamante, Chris (C.T.); Cantrell, David (D.D.); Ciotti, Steven (S.R.); Davis, Charlene (C.); Devine, Robert (R.M.); Docimo, Tony (A.F.); Ferguson, Hugh (H.); Gagnier, Scott (S.W.); Greenwell, R (R.); Guyton, MzJenny (J.); Hernandez, Thomas (T.); Herron, Micheal (M.C.); Inglis, Steve (S.D.); Iqbal, Khurram (K.); Jones, Frederick (F.L.); Little, Janie (J.); Martin, Kenneth (K.A.); Matlock, Douglas (D.); McElroy, Darin (D.L.); McKernan, Patrick (P.J.); Miller, Melinda (M.S.); Moore, Chikynda (D.); Moskwa, Larry (L.M.); Perkins, John (J.E.); Pesch, Vincent (V.J.); Russell, David (D.A.); Rutovic, Nick (N.); Sarkisian, Mark (Z.); Talbott, Larry (J.L.); Turner, Bridgette (B.); Turner, Patrice (P.T.); Vandergroef, Cornelius (C.); Washington, Kellie (K.S.); Wertman, David Brian (D.B.); Westbrook, Dori (D.); Williams, Erik (E.C.); Williams, Gregory (G.M.); Wyatt, Kimberly (K.D.); Zroback, David (D.P.); Armstrong, Miya (M.); Buerger, Robert (R.G.); Evans, Kayekethia (K.); Gibson, Renelda (R.); Lakomek, Scott (S.); Napier, S (S.); Ornelas, Demetrio (D.); Ratliff, Kathy (K.); Scheldberg, Gary (G.D.); Stonewall, Wendy (M.); Svetich, Chris (C.); Torian, Jason (J.B.); Anderson, Eric (H.); Berzeri, Marcello (M.); Chamberlain, Steve (J.); Edwards, Monty (M.R.); Farmer, Marty (M.F.); Feder, Andrew (A.); Gerrard, Ryan (R.P.); Iannotti, Jason (JRI.); Ickes, Walt (W.D.); Imperati, Daniel (D.); Issa, Ibrahim (I.M.); Jackson, Bradley (B.G.); Logli, Michael (M.A.); Morgan, Anthony (A.); Olsson, Paul (P.C.); Polaski, Mike (M.S.); Porter, Alan (A.T.); Rapis, Noreen (N.G.); Santilli, Rennie (R.); Sluis, Jim (JS.); Smith, Erin (E.); Sridhara, Raghu (R.); Trygar, Mike (M.); Vargo, Rebecca (R.L.); Widrick, Brad (B.A.); Young, Richard (R.C.); Yu, Eric (E.); Buelow, Steve (S.E.)

**Subject:** FW: 2011 Exp - BG [REDACTED] - Loss of steering assist, 611 mi, BD 2/15/11

**-The Customer Defines Quality-**

*Steve Buelow - Ford Motor Company*

FCSD Program Manager-

Taurus/Taurus SHO/Lincoln MKS/Explorer

Chicago Assembly PVT Office, COE

773-646-7495 DialNet 686-7495

Cell 313-805-8334 sbuelow@ford.com

"Quality means doing it right when no one is looking." - Henry Ford

---

**From:** SBUELOW@ford.com [mailto:SBUELOW@ford.com]

**Sent:** Thursday, March 24, 2011 9:37 AM

**To:** Buelow, Steve (S.E.)

**Subject:** 2011 Exp - BG [REDACTED] - Loss of steering assist, 611 mi, BD 2/15/11

**Attachments :** 0

**Report# :** BCWFW001 NHL

**Received:** 03/23/2011

**CCRG/EPRC:** **Reviewed Status:** **Date:**  
**Vehicle:** 2011,EXPLORER 4X4 (U502),4 DOOR **Build Date:** 02/15/2011  
,MP,1FMHK8D89BG [REDACTED]  
**Odometer :** 611 M **Engine:** 3.5L **Calibration:** BUB1SN0A  
CYCLO  
**Transmission:** 6F50 **Axle:** **A/C:** YES  
**Dealer:** USA 07737 Serramonte Ford, Inc. **Phone#:** (650) 301-7065  
**City:** Colma **State:** California **Country :** USA  
**Originator:** OMAR NAVARRO  
**Symptom:** 3 03 0 00 CHASS.,STRG/HANDLING ,OTHER-CODE NA,OTHER-CODE NA  
**Status:**  
**VFG:** V89 RIDE & HANDLING  
**Additional Symptom:** LOSS OF STEERING ASSIST  
**Fix:** **Causal Component :**  
**Condition Code:**

**Hotliner:** MHINDERE **Phone:** 313 337-9292 **Regn Cd:** W2 San Francisco

**Engineering:** **Phone:** **TAR:**

**Dlr Contact:** OMAR NAVARRO **Phone:** 650 577-0577 **Title Cde:** T

**DTCs:**

KOEO:

KOEC:C1B00 U0131

KOER:

**Comments**

:

REPAIR 03/23/2011 06:19PM MICHAEL HINDERER MSS - FCSD - TECH SVC HOTLINE  
WEB FORM DATA - CONCERN: NO POWER STEERING ASSIST DIAGNOSTICS:  
INSPECTED THE STEERING GEAR AND CONNECTOR AND FOUND OK. RAN THE  
SELF  
TEST AND THE POWER STEERING MODULE PASSED. THE ABS MODULE HAD  
CODES  
C1B00 AND U0131. FOUND THE STEERING ASSIT STARTED WORKING  
MOMENTARELY  
AFTER THE SELF TES AND THE STOPED WORKING. MONITORED THE STEERING  
ANGLE PID AND FOUND IT DOES NOT MATCH THE ACTUAL STEERING ANGLE.  
PARTS REPLACED:: NONE TECH QUESTION: DOES THE STEERING GEAR  
ASSEMBLY NEED TO HAVE APPROVAL FOR REPLACEMENT WERE YOU ABLE TO  
VERIFY THE CONCERN? YES IS THERE AN APPROPRIATE PINPOINT TEST IN  
THE WSM FOR THIS CONCERN? YES WAS THE PINPOINT TEST FOLLOWED? YES

**RECOMM 03/23/2011 06:19PM MICHAEL HINDERER MSS - FCSD - TECH SVC HOTLINE**

TO BETTER ASSIST YOU ON THIS WARRANTY RELATED QUESTION, THE  
TECHNICAL  
SERVICE HOTLINE RECOMMENDS THAT YOU REFER TO THE DEALERSHIP  
WARRANTY  
ADMINISTRATOR, THE WARRANTY AND POLICY MANUAL, OR YOU MAY  
CONTACT THE  
WARRANTY ASSISTANCE CENTER DIRECTLY AT 1-800-423-8851

---

**From:** Napoli, Laura (L.)  
**Sent:** Monday, May 23, 2011 2:03 PM  
**To:** Annadi, Hari (H.); Perri, Ron (R.J.); Mrozek, Robert (R.M.); Pascarella, Michael (M.)  
**Subject:** RE: 2011 Exp - BG [REDACTED] - Loss of steering assist, 2947 mi, BD 3/3/11

No. The gear was not changed out on this one. It sounds like a wiring issue to me. PVT said they lost assist and it came back on the next key cycle with no DTC's. There's a new wiring issue popping up that the PVT is investigating with the electrical team. We need to start directing dealers to look for this wiring problem when they have no communication with the gear or intermittent assist with no EPAS DTC's.

---

**From:** Annadi, Hari (H.)  
**Sent:** Monday, May 23, 2011 12:12 PM  
**To:** Perri, Ron (R.J.); Mrozek, Robert (R.M.); Pascarella, Michael (M.); Napoli, Laura (L.)  
**Subject:** RE: 2011 Exp - BG [REDACTED] - Loss of steering assist, 2947 mi, BD 3/3/11

[Do we have any of these parts back?](#)

---

**From:** Perri, Ron (R.J.)  
**Sent:** Monday, May 23, 2011 10:12 AM  
**To:** Annadi, Hari (H.); Mrozek, Robert (R.M.); Pascarella, Michael (M.); Napoli, Laura (L.)  
**Subject:** FW: 2011 Exp - BG [REDACTED] - Loss of steering assist, 2947 mi, BD 3/3/11

[This concern is being added to the emerging issues list](#)

Ron Perri  
Manager, Chassis - EPAS and Upper Steering, Systems & Core  
2B-F77, Product Development Center  
cell 313-805-0680  
rperri@ford.com

---

**From:** Gubing, William (Bill.)  
**Sent:** Monday, May 23, 2011 10:10 AM  
**To:** Menz, Kenneth (K.C.); Perri, Ron (R.J.)  
**Subject:** FW: 2011 Exp - BG [REDACTED] - Loss of steering assist, 2947 mi, BD 3/3/11

FYI

Bill

---

**From:** Buelow, Steve (S.E.)  
**Sent:** Monday, May 23, 2011 10:02 AM

**To:** Adamczyk, David (D.W.); Bollwahn, Bryce (B.A.); Centlivre, James (J.C.); Cheatham, Sandy (.); Cittadino, Lisa (L.C.); Collins, Kevin (K.E.); Gagnier, Kathryn (K.A.); Gilewski, David (D.); Gillanders, Eric (E.S.); Gray, Carl (C.L.); Gubing, William (Bill.); Hays, Andy (A.R.); Krochmalny, Kevin (K.); Mann, Mickey (N.S.); McClain, Shawn (S.M.); Pogorzelski, John (J.M.); Rodgers, Chuck (.); Saleh, Salim (S.A.); Sellers, Gary (G.T.); Shaukat, Nadeem (N.S.); Simkus, Walter (W.A.); Sokolowski, Todd (T.M.); Thornsberry, Joel (J.A.); Willis, Mark (M.E.); Wong, Vicki (V.A.); Acuna, Aaron (A.A.); Allman, Jan (J.E.); Bell, Tim (.); Bergeron, Matthew (M.C.); Bisaga, Richard (R.); Boykin, George (G.); Boykins, Michael (M.); Bustamante, Chris (C.T.); Cantrell, David (D.D.); Carter, Tracy (T.); Ciotti, Steven (S.R.); Davis, Charlene (C.); Devine, Robert (R.M.); Docimo, Tony (A.F.); Ferguson, Hugh (H.); Gagnier, Scott (S.W.); Greenwell, R (R.); Guyton, MzJenny (J.); Hernandez, Thomas (T.); Herron, Micheal (M.C.); Inglis, Steve (S.D.); Iqbal, Khurram (K.); Jones, Frederick (F.L.); Little, Janie (J.); Martin, Kenneth (K.A.); Matlock, Douglas (D.); McElroy, Darin (D.L.); McKernan, Patrick (P.J.); Miller, Melinda (M.S.); Moore, Chikynda (D.); Moskwa, Larry (L.M.); Perkins, John (J.E.); Russell, David (D.A.); Rutovic, Nick (N.); Sarkisian, Mark (Z.); Talbott, Larry (J.L.); Turner, Bridgette (B.); Turner, Patrice (P.T.); Vandergroef, Cornelius (C.); Washington, Kellie (K.S.); Wertman, David Brian (D.B.); Westbrook, Dori (D.); Williams, Erik (E.C.); Williams, Gregory (G.M.); Wyatt, Kimberly (K.D.); Zroback, David (D.P.); Armstrong, Miya (M.); Buerger, Robert (R.G.); Evans, Kayekethia (K.); Gibson, Renelda (R.); Lakomek, Scott (S.); Napier, S (S.); Ornelas, Demetrio (D.); Ratliff, Kathy (K.); Scheldberg, Gary (G.D.); Stonewall, Wendy (M.); Svetich, Chris (C.); Torian, Jason (J.B.); Anderson, Eric (H.); Berzeri, Marcello (M.); Cassata, Joe (J.); Chamberlain, Steve (J.); Edwards, Monty (M.R.); Farmer, Marty (M.F.); Feder, Andrew (A.); Gerrard, Ryan (R.P.); Iannotti, Jason (JRI.); Ickes, Walt (W.D.); Issa, Ibrahim (I.M.); Jackson, Bradley (B.G.); Logli, Michael (M.A.); Morgan, Anthony (A.); Olsson, Paul (P.C.); Polaski, Mike (M.S.); Porter, Alan (A.T.); Rapiz, Noreen (N.G.); Santilli, Rennie (R.); Smith, Erin (E.); Sridhara, Raghu (R.); Trygar, Mike (M.); Vargo, Rebecca (R.L.); Widrick, Brad (B.A.); Young, Richard (R.C.); Yu, Eric (E.); Buelow, Steve (S.E.)

**Subject:** FW: 2011 Exp - BG [REDACTED] - Loss of steering assist, 2947 mi, BD 3/3/11

This is the 5th report in the last 3 weeks. This concern is being added to the emerging issues list.

**-The Customer Defines Quality-**

*Steve Buelow - Ford Motor Company*

FCSD Program Manager-  
Taurus/Taurus SHO/Lincoln MKS/Explorer  
Chicago Assembly PVT Office, COE  
773-646-7495 DialNet 686-7495  
Cell 773-726-0808 sbuelow@ford.com

"Quality means doing it right when no one is looking." - Henry Ford

---

**From:** SBUELOW@ford.com [mailto:SBUELOW@ford.com]  
**Sent:** Monday, May 23, 2011 8:59 AM  
**To:** Buelow, Steve (S.E.)  
**Subject:** 2011 Exp - BG [REDACTED] - Loss of steering assist, 2947 mi, BD 3/3/11

**Attachments :** 0

<b>Report# :</b>	BETBK025 NHL	<b>Received:</b>	05/20/2011
<b>CCRG/EPRC:</b>		<b>Date:</b>	
<b>Vehicle:</b>	2011,EXPLORER 4X4 (U502),4 DOOR ,MP,1FMHK8B8XBG [REDACTED]	<b>Build Date:</b>	03/03/2011

**Odometer :** 2,947 M      **Engine:** 3.5L CYCLO      **Calibration:**  
**Transmission:** 6F50      **Axle:**      **A/C:** YES  
**Dealer:** USA 08305 Evergreen Ford      **Phone#:** (425) 392-6900  
**City:** Issaquah      **State:** Washington      **Country :** USA  
**Originator:** JASON DESCHAMBAULT  
**Symptom:** 3 03 1 50 CHASS.,STRG/HANDLING ,FUNCTION,HIGH EFFORT  
**Status:**  
**VFG:** V87 STEERING  
**Additional Symptom:** INT. LOSS OF STEERING  
**Fix:**      **Causal Component :**  
**Condition Code:**

**Hotliner:** MHINDERE      **Phone:** 000 337-9292      **Regn Cd:** W5 Seattle  
**Engineering:**      **Phone:**      **TAR:**  
**Dlr Contact:** JASON DESCHAMBAULT      **Phone:** 425 392-6900      **Title Cde:** T

**DTCs:**  
 KOEO:  
 KOEC:  
 KOER:

**Comments**

:  
**REPAIR** 05/20/2011 03:11PM MICHAEL HINDERER MSS - FCSD - TECH SVC HOTLINE  
 WEB FORM DATA - CONCERN: CUSTOMER LOST STEERING ASSIST AT 35 MPH,  
 DIDNT RETURN UNTILL ENGINE SHUT OFF AND RETSTARTED. DIAGNOSTICS:  
 CHECKED OASIS, CHECKED FOR DTCS PASS. PARTS REPLACED:: NONE TECH  
 QUESTION: ROAD TESTED, UNABLE TO VERIFY CONCERN. ANY KNOWN  
 CONCERNS? WERE YOU ABLE TO VERIFY THE CONCERN? NO IS THERE AN  
 APPROPRIATE PINPOINT TEST IN THE WSM FOR THIS CONCERN? YES WAS THE  
 PINPOINT TEST FOLLOWED? NO  
**RECOMM** 05/20/2011 03:11PM MICHAEL HINDERER MSS - FCSD - TECH SVC HOTLINE  
 JASON, TO ACTIVATE THE EPAS SYSTEM, A 12-VOLT HOT AT ALL TIMES AND A  
 12-VOLT IGNITION/RUN INPUT TO THE PSCM IS REQUIRED. THE PSCM THEN  
 MONITORS THE HS-CAN TO DETERMINE IF THE VEHICLE IS OPERATING IN A  
 MANNER CAPABLE OF SUPPORTING THE EPAS SYSTEM. THE PSCM USES INPUTS  
 FROM VARIOUS MODULES OVER THE HS-CAN, THE STEERING TORQUE SENSOR  
 AND  
 THE MOTOR TO DETERMINE THE AMOUNT OR LEVEL OF ASSIST PROVIDED BY  
 THE

EPAS SYSTEM. INSPECT PINFIT AND CONNECTION AT THE PSCM. VERIFY THERE ARE NO CONCERNS WITH A LOSS OF POWER TO THE PSCM. GIVEN THE CONCERN IS INTERMITTENT, A CONNECTION CONCERN IS POSSIBLE.

---

**From:** Napoli, Laura (L.)  
**Sent:** Wednesday, May 04, 2011 12:44 PM  
**To:** Anderson, Eric (H.); Docimo, Tony (A.F.)  
**Cc:** Jackson, Bradley (B.G.); Mrozek, Robert (R.M.)  
**Subject:** RE: 2011 Exp - BG [REDACTED] - No power steering, traction fault lmap on, 164 mi, BD 3/24/11

Sorry Eric and Tony. I misunderstood which issues you've had in CAP, so I would like to reword my statement below...

It's still correct that -- No. The C200D has nothing to do with the torque sensor. This is a motor fault.

To further add, in warranty, we saw one vehicle last week with a C200D-49 motor fault. The dealer cleared codes and returned the vehicle to the customer since they could not duplicate the failure. Since we don't have the part back, we cannot investigate this failure. If the customer has a repeat fault, and brings the car back in, then we can start to investigate the C200D-49. I thought you said you had a 0km at CAP with C200D-49, but you did not have that fault. Therefore, there are no gears for us to use to investigate this fault at this time.

Regarding ICA or PCA per Tony's question below...no, there is no ICA or PCA in place for C200D-49 per the reasoning above. There is an ICA in place for C200B and C200C which are the torque sensor faults that you have gotten in CAP on one vehicle. We are replacing the ICA with a PCA which is currently being developed at the TRW assy facility.

I hope this clears things up.

Regards,

*Laura Napoli*

U502 EPAS  
Ford Motor Company  
Cube: 2B-G66 PDC  
Phone: 313.323.0634  
Mobile: 313.805.0482

---

**From:** Napoli, Laura (L.)  
**Sent:** Tuesday, May 03, 2011 10:59 AM  
**To:** Anderson, Eric (H.)  
**Cc:** Docimo, Tony (A.F.); Jackson, Bradley (B.G.); Mrozek, Robert (R.M.)  
**Subject:** RE: 2011 Exp - BG [REDACTED] - No power steering, traction fault lmap on, 164 mi, BD 3/24/11

No. This has nothing to do with the torque sensor. This is a motor fault. At this point there are no U502 warranty issues with this fault code. No ICA or PCA is in place since there was only one claim and the gear has not been changed out. We would need the gear back to do an analysis of what the specific TRW code is for this one C200D claim. We can analyze the 0km gear that was found yesterday, but that is not necessarily the same issue that happened in warranty, so it cannot be used to specifically analyze this warranty claim below.

---

**From:** Anderson, Eric (H.)  
**Sent:** Tuesday, May 03, 2011 10:20 AM



**To:** Napoli, Laura (L.)  
**Cc:** Docimo, Tony (A.F.); Jackson, Bradley (B.G.)  
**Subject:** RE: 2011 Exp - BGA42179 - No power steering, traction fault lmap on, 164 mi, BD 3/24/11

Hi Laura:

Would I be correct in adding C200D code claims to *SAQ2011167053 D3/U502 EPAS defective torque sensor (C200B, C200C codes)*? Does C200D indicate the same root cause as C200B and C200C?

Thanks,

Eric

---

**From:** Docimo, Tony (A.F.)  
**Sent:** Monday, May 02, 2011 6:58 PM  
**To:** Napoli, Laura (L.); Jackson, Bradley (B.G.); Anderson, Eric (H.)  
**Subject:** RE: 2011 Exp - BG [REDACTED] - No power steering, traction fault lmap on, 164 mi, BD 3/24/11  
**Importance:** High

Do we have an ICA or PCA plan for this C200D DTC?

---

**From:** Napoli, Laura (L.)  
**Sent:** Monday, May 02, 2011 8:55 AM  
**To:** Jackson, Bradley (B.G.); Docimo, Tony (A.F.)  
**Cc:** Anderson, Eric (H.)  
**Subject:** RE: 2011 Exp - BG [REDACTED] - No power steering, traction fault lmap on, 164 mi, BD 3/24/11

Yes. C200D is a gear HW DTC. Service is to clear codes and try to duplicate. If they cannot duplicate, they return to customer. If they do duplicate, they replace gear. If they return to customer and customer brings it back a second time, they immediately replace gear.

This dealer cleared codes and returned to customer same day.

---

**From:** Jackson, Bradley (B.G.)  
**Sent:** Saturday, April 30, 2011 5:40 AM  
**To:** Docimo, Tony (A.F.); Napoli, Laura (L.)  
**Cc:** Anderson, Eric (H.)  
**Subject:** RE: 2011 Exp - BG [REDACTED] - No power steering, traction fault lmap on, 164 mi, BD 3/24/11

Tony, not sure. The C200D might be pointing to the gear.

Laura, any insight on this CQIS report?

Brad

---

**From:** Docimo, Tony (A.F.)  
**Sent:** Friday, April 29, 2011 5:31 PM  
**To:** Jackson, Bradley (B.G.); Anderson, Eric (H.)  
**Subject:** FW: 2011 Exp - BG [REDACTED] - No power steering, traction fault lmap on, 164 mi, BD 3/24/11

Any ideas on this?

---

**From:** Buelow, Steve (S.E.)

**Sent:** Monday, April 25, 2011 3:15 PM

**To:** Adamczyk, David (D.W.); Bollwahn, Bryce (B.A.); Centlivre, James (J.C.); Cheatham, Sandy (.); Cittadino, Lisa (L.C.); Collins, Kevin (K.E.); Gagnier, Kathryn (K.A.); Gilewski, David (D.); Gillanders, Eric (E.S.); Gray, Carl (C.L.); Gubing, William (Bill.); Hays, Andy (A.R.); Krochmalny, Kevin (K.); Mann, Mickey (N.S.); McClain, Shawn (S.M.); Pogorzelski, John (J.M.); Rodgers, Chuck (.); Saleh, Salim (S.A.); Sellers, Gary (G.T.); Shaukat, Nadeem (N.S.); Simkus, Walter (W.A.); Sokolowski, Todd (T.M.); Thornsberry, Joel (J.A.); Willis, Mark (M.E.); Wong, Vicki (V.A.); Acuna, Aaron (A.A.); Allman, Jan (J.E.); Bell, Tim (.); Bergeron, Matthew (M.C.); Bisaga, Richard (R.); Boykin, George (G.); Boykins, Michael (M.); Bustamante, Chris (C.T.); Cantrell, David (D.D.); Ciotti, Steven (S.R.); Davis, Charlene (C.); Devine, Robert (R.M.); Docimo, Tony (A.F.); Ferguson, Hugh (H.); Gagnier, Scott (S.W.); Greenwell, R (R.); Guyton, MzJenny (J.); Hernandez, Thomas (T.); Herron, Micheal (M.C.); Inglis, Steve (S.D.); Iqbal, Khurram (K.); Jones, Frederick (F.L.); Little, Janie (J.); Martin, Kenneth (K.A.); Matlock, Douglas (D.); McElroy, Darin (D.L.); McKernan, Patrick (P.J.); Miller, Melinda (M.S.); Moore, Chikynda (D.); Moskwa, Larry (L.M.); Perkins, John (J.E.); Pesch, Vincent (V.J.); Russell, David (D.A.); Rutovic, Nick (N.); Sarkisian, Mark (Z.); Talbott, Larry (J.L.); Turner, Bridgette (B.); Turner, Patrice (P.T.); Vandergroef, Cornelius (C.); Washington, Kellie (K.S.); Wertman, David Brian (D.B.); Westbrook, Dori (D.); Williams, Erik (E.C.); Williams, Gregory (G.M.); Wyatt, Kimberly (K.D.); Zroback, David (D.P.); Armstrong, Miya (M.); Buerger, Robert (R.G.); Evans, Kayekethia (K.); Gibson, Renelda (R.); Lakomek, Scott (S.); Napier, S (S.); Ornelas, Demetrio (D.); Ratliff, Kathy (K.); Scheldberg, Gary (G.D.); Stonewall, Wendy (M.); Svetich, Chris (C.); Torian, Jason (J.B.); Anderson, Eric (H.); Berzeri, Marcello (M.); Cassata, Joe (J.); Chamberlain, Steve (J.); Edwards, Monty (M.R.); Farmer, Marty (M.F.); Feder, Andrew (A.); Gerrard, Ryan (R.P.); Iannotti, Jason (JRI.); Ickes, Walt (W.D.); Issa, Ibrahim (I.M.); Jackson, Bradley (B.G.); Logli, Michael (M.A.); Morgan, Anthony (A.); Olsson, Paul (P.C.); Polaski, Mike (M.S.); Porter, Alan (A.T.); Rapis, Noreen (N.G.); Santilli, Rennie (R.); Smith, Erin (E.); Sridhara, Raghu (R.); Trygar, Mike (M.); Vargo, Rebecca (R.L.); Widrick, Brad (B.A.); Young, Richard (R.C.); Yu, Eric (E.); Buelow, Steve (S.E.)

**Subject:** FW: 2011 Exp - BG [REDACTED] - No power steering, traction fault lmap on, 164 mi, BD 3/24/11

**-The Customer Defines Quality-**

*Steve Buelow - Ford Motor Company*

FCSD Program Manager-

Taurus/Taurus SHO/Lincoln MKS/Explorer

Chicago Assembly PVT Office, COE

773-646-7495 DialNet 686-7495

Cell 313-805-8334 sbuelow@ford.com

"Quality means doing it right when no one is looking." - Henry Ford

---

**From:** SBUELOW@ford.com [mailto:SBUELOW@ford.com]

**Sent:** Monday, April 25, 2011 10:32 AM

**To:** Buelow, Steve (S.E.)

**Subject:** 2011 Exp - BG [REDACTED] - No power steering, traction fault lmap on, 164 mi, BD 3/24/11

**Attachments :** 0

**Report# :** BDUB5007 NHL

**Received:** 04/21/2011

**CCRG/EPRC:** **Reviewed Status:** **Date:**  
**Vehicle:** 2011,EXPLORER 4X2 (U502),4 DOOR **Build Date:** 03/24/2011  
,MP,1FMHK7D84BG [REDACTED]  
**Odometer :** 164 M **Engine:** 3.5L **Calibration:**  
CYCLO  
**Transmission:** 6F50 **Axle:** **A/C:** YES  
**Dealer:** USA 05662 Crossroads Ford Lincoln, Inc. **Phone#:** (502) 695-  
1990  
**City:** Frankfort **State:** Kentucky **Country :** USA  
**Originator:** MARTY MITCHAM  
**Symptom:** 3 01 A 04 CHASS.,SERVICE BRAKE ,INDICATOR,T/C LIGHT  
**Status:**  
**VFG:** V21 BRAKING  
**Additional Symptom:** TRAC LIGHT ON/NO ASSIST INT  
**Fix:** **Causal Component :**  
**Condition Code:**

**Hotliner:** LMILLA11 **Phone:** 313 317-9130 **Regn Cd:** G3 Cincinnati  
**Engineering:** **Phone:** **TAR:**  
**Dlr Contact:** MARTY MITCHAM **Phone:** 502 695-1990 **Title Cde:** T

**DTCs:**  
KOEO:  
KOEC:  
KOER:

**Comments**

:  
**REPAIR** 04/21/2011 10:08AM LYLE MILLARD MSS - FCSD - TECH SVC HOTLINE  
WEB FORM DATA - CONCERN: CUSTOMER SAYS WHILE LEAVING A RESTURANT  
YESTERDAY, HE HAD NO POWER STEERING ALL THE WAY HOME. ALSO THE TRAC  
CONTROL LIGHT CAME ON TWICE AND WENT OFF. EVERY THING OK THIS  
MORNING DIAGNOSTICS: IDS DIAG. PSCM-PINPOINT TEST B. CHECKED  
CONNECTIONS AT GEAR-OK CODES C1B00:86-28 ABS, U0182:87-0A BCM,  
U0212:87-0A BCM, U0253:00-28 IPC, C200D:49-08 PSCM ALL OK AT THIS  
TIME PARTS REPLACED:: NONE TECH QUESTION: ANY KNOWN  
CONCERNS WERE YOU ABLE TO VERIFY THE CONCERN? NO IS THERE AN  
APPROPRIATE PINPOINT TEST IN THE WSM FOR THIS CONCERN? YES WAS THE  
PINPOINT TEST FOLLOWED? YES

**RECOMM** 04/21/2011 10:08AM LYLE MILLARD MSS - FCSD - TECH SVC HOTLINE  
MARTY, PLEASE ENSURE THAT THE CONCERN CAN BE VERIFIED BEFORE ANY  
REPAIRS ARE TO BE PERFORMED. IF THE CONCERN CAN BE DUPLICATED AND

VERIFIED, THIS CONCERN CAN BE ADDRESSED BY CONSULTING SSM 21737. THIS SSM ADDRESSES COMMUNICATION ISSUES THAT WOULD SET THESE CODES. DTC U0253 DOES NOT PERTAIN TO THE CONCERN AND SHOULD BE DISREGARDED. IF COMMUNICATION IS RESTORED PLEASE RETEST, AND EVALUATE. SSM 21737 CODES C1B00, U0131, U0100, U0001, U0121, AND/OR U0151- CLEAR CODES AND WIGGLE TEST CONNECTER C139. IF CODES RETURN, BYPASS C139 FOR CIRCUITS VDB04 AND VDB05 USING THE SOLDER AND SHRINK TUBING METHOD FOUND IN SECTION 5 OF THE WIRING DIAGRAMS.

---

**From:** Napoli, Laura (L.)  
**Sent:** Thursday, June 02, 2011 4:31 PM  
**To:** Anderson, Eric (H.); Estes, Eric (E.E.)  
**Subject:** RE: 2011 Exp - BG [REDACTED] - Lost power steering assist while driving, 540 mi, BD 3/29/11

We'll need to discuss in detail in our Mon warranty mtg. I need to get the background on what was done.

---

**From:** Anderson, Eric (H.)  
**Sent:** Thursday, June 02, 2011 10:30 AM  
**To:** Napoli, Laura (L.); Estes, Eric (E.E.)  
**Subject:** FW: 2011 Exp - BG [REDACTED] - Lost power steering assist while driving, 540 mi, BD 3/29/11

Hi Laura and Eric:

C200D is a known issue, but do we have a fix for it?

Thanks,

Eric

---

**From:** Buelow, Steve (S.E.)  
**Sent:** Thursday, June 02, 2011 9:23 AM  
**To:** Adamczyk, David (D.W.); Bollwahn, Bryce (B.A.); Centlivre, James (J.C.); Cheatham, Sandy (.); Cittadino, Lisa (L.C.); Collins, Kevin (K.E.); Gagnier, Kathryn (K.A.); Gilewski, David (D.); Gillanders, Eric (E.S.); Gray, Carl (C.L.); Gubing, William (Bill.); Hays, Andy (A.R.); Krochmalny, Kevin (K.); Mann, Mickey (N.S.); McClain, Shawn (S.M.); Pogorzelski, John (J.M.); Rodgers, Chuck (.); Saleh, Salim (S.A.); Sellers, Gary (G.T.); Shaukat, Nadeem (N.S.); Simkus, Walter (W.A.); Sokolowski, Todd (T.M.); Thornsberry, Joel (J.A.); Willis, Mark (M.E.); Wong, Vicki (V.A.); Acuna, Aaron (A.A.); Allman, Jan (J.E.); Bell, Tim (.); Bergeron, Matthew (M.C.); Bisaga, Richard (R.); Boykin, George (G.); Boykins, Michael (M.); Bustamante, Chris (C.T.); Cantrell, David (D.D.); Carter, Tracy (T.); Chones, Marvin (M.); Ciotti, Steven (S.R.); Davis, Charlene (C.); Devine, Robert (R.M.); Docimo, Tony (A.F.); Ferguson, Hugh (H.); Gagnier, Scott (S.W.); Greenwell, R (R.); Guyton, MzJenny (J.); Hernandez, Thomas (T.); Herron, Micheal (M.C.); Inglis, Steve (S.D.); Iqbal, Khurram (K.); Jones, Frederick (F.L.); Little, Janie (J.); Lux, Tracie (T.L.); Martin, Kenneth (K.A.); Matlock, Douglas (D.); McElroy, Darin (D.L.); McKernan, Patrick (P.J.); Miller, Melinda (M.S.); Moore, Chikynda (D.); Moskwa, Larry (L.M.); Perkins, John (J.E.); Russell, David (D.A.); Rutovic, Nick (N.); Sarkisian, Mark (Z.); Talbott, Larry (J.L.); Turner, Bridgette (B.); Turner, Patrice (P.T.); Vandergroef, Cornelius (C.); Washington, Kellie (K.S.); Wertman, David Brian (D.B.); Westbrook, Dori (D.); Williams, Erik (E.C.); Williams, Gregory (G.M.); Wyatt, Kimberly (K.D.); Zroback, David (D.P.); Armstrong, Miya (M.); Buerger, Robert (R.G.); Evans, Kayekethia (K.); Gibson, Renelda (R.); Lakomek, Scott (S.); Napier, S (S.); Ornelas, Demetrio (D.); Ratliff, Kathy (K.); Scheldberg, Gary (G.D.); Stonewall, Wendy (M.); Svetich, Chris (C.); Torian, Jason (J.B.); Anderson, Eric (H.); Berzeri, Marcello (M.); Cassata, Joe (J.); Chamberlain, Steve (J.); Edwards, Monty (M.R.); Farmer, Marty (M.F.); Feder, Andrew (A.); Gerrard, Ryan (R.P.); Iannotti, Jason (JRI.); Ickes, Walt (W.D.); Issa, Ibrahim (I.M.); Jackson, Bradley (B.G.); Logli, Michael (M.A.); Morgan, Anthony (A.); Olsson, Paul (P.C.); Polaski, Mike (M.S.); Porter, Alan (A.T.); Rapiz, Noreen (N.G.); Santilli, Rennie (R.); Smith, Erin (E.); Sridhara, Raghu (R.); Trygar, Mike (M.); Vargo, Rebecca (R.L.); Widrick, Brad (B.A.); Young, Richard (R.C.); Yu, Eric (E.); Buelow, Steve (S.E.)  
**Subject:** FW: 2011 Exp - BG [REDACTED] - Lost power steering assist while driving, 540 mi, BD 3/29/11

**-The Customer Defines Quality-**

*Steve Buelow - Ford Motor Company*

FCSD Program Manager-  
Taurus/Taurus SHO/Lincoln MKS/Explorer  
Chicago Assembly PVT Office, COE  
773-646-7495 DialNet 686-7495  
Cell 773-726-0808 sbuelow@ford.com

"Quality means doing it right when no one is looking." - Henry Ford

---

**From:** SBUELOW@ford.com [mailto:SBUELOW@ford.com]  
**Sent:** Thursday, June 02, 2011 8:44 AM  
**To:** Buelow, Steve (S.E.)  
**Subject:** 2011 Exp - BG [REDACTED] - Lost power steering assist while driving, 540 mi, BD 3/29/11

**Attachments :** 0

**Report# :** BFADJ010 NHL **Received:** 06/01/2011  
**CCRG/EPRC:** **Reviewed Status:** **Date:**  
**Vehicle:** 2011,EXPLORER 4X2 (U502),4 DOOR **Build Date:** 03/29/2011  
,MP,1FMHK7F82BG [REDACTED]  
**Odometer :** 540 M **Engine:** 3.5L **Calibration:**  
CYCLO  
**Transmission:** 6F55 **Axle:** **A/C:** YES  
**Dealer:** USA 08556 Ford and Lincoln of Bellevue **Phone#:** (877) 374-3931  
**City:** Bellevue **State:** Washington **Country :** USA  
**Originator:** HOWARD WOLF  
**Symptom:** 3 03 1 50 CHASS.,STRG/HANDLING ,FUNCTION,HIGH EFFORT  
**Status:**  
**VFG:** V87 STEERING  
**Additional Symptom:** POWER ASSIST INOP  
**Fix:** **Causal Component :**  
**Condition Code:**

**Hotliner:** BWRIGH77 **Phone:** 313 317-7040 **Regn Cd:** W5 Seattle  
**Engineering:** **Phone:** **TAR:**  
**Dlr Contact:** HOWARD WOLF **Phone:** 425 454-2454 **Title Cde:** T

**DTCs:**  
KOEO:C200D  
KOEC:

KOER:

**Comments**

:

**REPAIR** 06/01/2011 03:28PM BRANDON WRIGHT MSS - FCSD - TECH SVC HOTLINE  
WEB FORM DATA - CONCERN: CUSTOMER STATES THAT WHILE DRIVING  
STEERING  
GOT STIFF AND HAD NO ASSIST POWER STEERING FAULT DISPLAYED IN  
MESSAGE  
CENTER DIAGNOSTICS: ROADTEST VERIFIED CONCERN C200D IS THE CODE  
WHEN DOING THE PINPOINT TEST IT HAS ME CLEAR THEN TURN LKOCK TO LOCK  
A  
FEW TIMES THEN RETEST IT WILL BE OK THEN NSAYS TO RELEASE TO  
CUSTOMER  
BUT IF I GO DRIVE FOR ALITTLE BIT IT WILL LOOSE ALL POWER  
ASSIST PARTS REPLACED:: NONE TECH QUESTION: ANY LIKE CONCERNS OR  
DAIG HELP TO TRACK DOWN THIS PROBLEM ALL CONNECTORS LOOK GOOD AND  
EVERYTHING WILL PASS THEN DRIVE AND IT WILL FAIL AGAIN WERE YOU  
ABLE TO VERIFY THE CONCERN? YES IS THERE AN APPROPRIATE PINPOINT  
TEST IN THE WSM FOR THIS CONCERN? YES WAS THE PINPOINT TEST  
FOLLOWED? YES

**RECOMM** 06/01/2011 03:28PM BRANDON WRIGHT MSS - FCSD - TECH SVC HOTLINE  
HOWARD, IF YOU HAVE NOT DONE SO ALREADY, REFER TO THE ONLINE  
WORKSHOP  
MANUAL SECTION 211-00 AND ENTER INTERACTIVE DIAGNOSTICS AND PERFORM  
DIAGNOSTIC ROUTINE B TO DIAGNOSE DTC C200D. PLEASE REVIEW DIAGNOSTIC  
ROUTINE I ALSO TO VERIFY IF IT CORRESPONDS WITH THE PRESENT CONCERN.  
IF FURTHER ASSISTANCE IS REQUIRED, PLEASE UPDATE THE FORM WITH YOUR  
LATEST RESULTS.

---

**From:** Napoli, Laura (L.)  
**Sent:** Friday, May 20, 2011 8:26 AM  
**To:** Perri, Ron (R.J.); Mrozek, Robert (R.M.); Pascarella, Michael (M.)  
**Cc:** Menz, Kenneth (K.C.); Surella, Matthew (M.M.)  
**Subject:** RE: 2011 Exp - BG [REDACTED] - Loss of steering assist, 256 mi, BD 5/3/11

Ron,

We are actively following up on all claims and getting gears back.

The process we follow for EPAS claims is to get gears back from dealers through the warranty 700 tag process and have them analyzed at 26mile or Marion. We also contact dealers that we see in CQIS who either seem to need help or who are being told to change a gear unnecessarily. Eric Estes is the TRW warranty lead who sits at the Ford Diagnostic Service Center (DSC1) and has been working on the Ford programs since the beginning of CD3. He builds paretos for each program and follows up with dealers and the WHQ garage for claims that need our immediate attention. He's also in direct contact with the PVT as necessary.

Please let me know if you'd like more detail or have any suggestions on our current process.

Regards,

*Laura Napoli*

U502 EPAS  
Ford Motor Company  
Cube: 2B-G66 PDC  
Phone: 313.323.0634  
Mobile: 313.805.0482

---

**From:** Perri, Ron (R.J.)  
**Sent:** Thursday, May 19, 2011 3:04 PM  
**To:** Mrozek, Robert (R.M.); Napoli, Laura (L.); Pascarella, Michael (M.)  
**Cc:** Menz, Kenneth (K.C.)  
**Subject:** FW: 2011 Exp - BG [REDACTED] - Loss of steering assist, 256 mi, BD 5/3/11

Please get into. Get part back, etc.  
Thanks.

Ron Perri  
Manager, Chassis - EPAS and Upper Steering, Systems & Core  
2B-F77, Product Development Center  
cell 313-805-0680  
rperri@ford.com



**From:** Menz, Kenneth (K.C.)  
**Sent:** Thursday, May 19, 2011 1:14 PM  
**To:** Perri, Ron (R.J.)  
**Subject:** FW: 2011 Exp - BG [REDACTED] - Loss of steering assist, 256 mi, BD 5/3/11

Ron - Bill Gubing just sent this over; 2 warranty claims in 1 day for EPAS loss of assist. How shall I respond? I am not aware of any warranty spike for EPAS on U502 nor aware of any recent quality issues.

## **Kenneth C. Menz**

Chassis Integration Mgr for  
Med/Large Family & CUV  
313-805-3156  
PDC 2B-G80

---

**From:** Gubing, William (Bill.)  
**Sent:** Thursday, May 19, 2011 11:59 AM  
**To:** Menz, Kenneth (K.C.)  
**Subject:** FW: 2011 Exp - BG [REDACTED] - Loss of steering assist, 256 mi, BD 5/3/11

2 of these in the same day hit warranty. And ideas?

Thanks

Bill

---

**From:** Buelow, Steve (S.E.)  
**Sent:** Thursday, May 19, 2011 11:42 AM  
**To:** Adamczyk, David (D.W.); Bollwahn, Bryce (B.A.); Centlivre, James (J.C.); Cheatham, Sandy (.); Cittadino, Lisa (L.C.); Collins, Kevin (K.E.); Gagnier, Kathryn (K.A.); Gilewski, David (D.); Gillanders, Eric (E.S.); Gray, Carl (C.L.); Gubing, William (Bill.); Hays, Andy (A.R.); Krochmalny, Kevin (K.); Mann, Mickey (N.S.); McClain, Shawn (S.M.); Pogorzelski, John (J.M.); Rodgers, Chuck (.); Saleh, Salim (S.A.); Sellers, Gary (G.T.); Shaukat, Nadeem (N.S.); Simkus, Walter (W.A.); Sokolowski, Todd (T.M.); Thornsberry, Joel (J.A.); Willis, Mark (M.E.); Wong, Vicki (V.A.); Acuna, Aaron (A.A.); Allman, Jan (J.E.); Bell, Tim (.); Bergeron, Matthew (M.C.); Bisaga, Richard (R.); Boykin, George (G.); Boykins, Michael (M.); Bustamante, Chris (C.T.); Cantrell, David (D.D.); Carter, Tracy (T.); Ciotti, Steven (S.R.); Davis, Charlene (C.); Devine, Robert (R.M.); Docimo, Tony (A.F.); Ferguson, Hugh (H.); Gagnier, Scott (S.W.); Greenwell, R (R.); Guyton, MzJenny (J.); Hernandez, Thomas (T.); Herron, Micheal (M.C.); Inglis, Steve (S.D.); Iqbal, Khurram (K.); Jones, Frederick (F.L.); Little, Janie (J.); Martin, Kenneth (K.A.); Matlock, Douglas (D.); McElroy, Darin (D.L.); McKernan, Patrick (P.J.); Miller, Melinda (M.S.); Moore, Chikynda (D.); Moskwa, Larry (L.M.); Perkins, John (J.E.); Russell, David (D.A.); Rutovic, Nick (N.); Sarkisian, Mark (Z.); Talbott, Larry (J.L.); Turner, Bridgette (B.); Turner, Patrice (P.T.); Vandergroef, Cornelius (C.); Washington, Kellie (K.S.); Wertman, David Brian (D.B.); Westbrook, Dori (D.); Williams, Erik (E.C.); Williams, Gregory (G.M.); Wyatt, Kimberly (K.D.); Zroback, David (D.P.); Armstrong, Miya (M.); Buerger, Robert (R.G.); Evans, Kayekethia (K.); Gibson, Renelda (R.); Lakomek, Scott (S.); Napier, S (S.); Ornelas, Demetrio (D.); Ratliff, Kathy (K.); Scheldberg, Gary (G.D.); Stonewall, Wendy (M.); Svetich, Chris (C.); Torian, Jason (J.B.); Anderson, Eric (H.); Berzeri, Marcello (M.); Cassata, Joe (J.); Chamberlain, Steve (J.); Edwards, Monty (M.R.); Farmer, Marty (M.F.); Feder, Andrew (A.); Gerrard, Ryan (R.P.); Iannotti, Jason (JRI.); Ickes, Walt (W.D.); Issa, Ibrahim (I.M.); Jackson, Bradley (B.G.); Logli, Michael (M.A.); Morgan, Anthony (A.); Olsson, Paul (P.C.); Polaski, Mike (M.S.); Porter, Alan (A.T.); Rapiz, Noreen (N.G.); Santilli, Rennie (R.); Smith, Erin (E.); Sridhara, Raghu (R.); Trygar, Mike (M.); Vargo, Rebecca (R.L.); Widrick, Brad (B.A.);

Young, Richard (R.C.); Yu, Eric (E.); Buelow, Steve (S.E.)

**Subject:** FW: 2011 Exp - BG [REDACTED] - Loss of steering assist, 256 mi, BD 5/3/11

**-The Customer Defines Quality-**

*Steve Buelow - Ford Motor Company*

FCSD Program Manager-  
Taurus/Taurus SHO/Lincoln MKS/Explorer  
Chicago Assembly PVT Office, COE  
773-646-7495 DialNet 686-7495  
Cell 773-726-0808 sbuelow@ford.com

"Quality means doing it right when no one is looking." - Henry Ford

---

**From:** SBUELOW@ford.com [mailto:SBUELOW@ford.com]  
**Sent:** Thursday, May 19, 2011 9:26 AM  
**To:** Buelow, Steve (S.E.)  
**Subject:** 2011 Exp - BG [REDACTED] - Loss of steering assist, 256 mi, BD 5/3/11

**Attachments :** 0

<b>Report# :</b>	BERDT010 NHL	<b>Received:</b>	05/18/2011
<b>CCRG/EPRC:</b>		<b>Date:</b>	
<b>Vehicle:</b>	2011,EXPLORER 4X4 (U502),4 DOOR ,MP,1FMHK8F89BG [REDACTED]	<b>Build Date:</b>	05/03/2011
<b>Odometer :</b>	256 M	<b>Engine:</b>	3.5L CYCLO
<b>Transmission:</b>	6F55	<b>Axle:</b>	
<b>Dealer:</b>	USA 00838 Lynch Ford-Mt. Vernon, Inc.	<b>A/C:</b>	YES
<b>City:</b>	Mount Vernon	<b>Phone#:</b>	(319) 895- 8500
<b>Originator:</b>	CHAD HONKOMP	<b>Country :</b>	USA
<b>Symptom:</b>	6 98 2 98 DRVABL,INDICATOR,CHECK ENGINE,MIL ONLY		
<b>Status:</b>			
<b>VFG:</b>	V29 CHECK ENGINE LIGHT		
<b>Additional Symptom:</b>	LOSS OF ASSIST U0131		
<b>Fix:</b>	<b>Causal Component :</b>		
<b>Condition Code:</b>			

**Hotliner:** FSHEPHE2

**Phone:** 000 317-6305

**Regn Cd:** G1 Chicago

**Engineering:**

**Phone:**

**TAR:**

**Dlr Contact:** CHAD HONKOMP

**Phone:** 319 895-8500

**Title Cde:** T

**DTCs:**

KOEO:U0131

KOEC:

KOER:

**Comments**

:

**REPAIR** 05/18/2011 06:43PM FRED SHEPHERD MSS - FCSD - TECH SVC HOTLINE  
WEB FORM DATA - CONCERN: POWER STERRING IS ACTING ERRATTIC DURING  
PARKING GARAGE DRIVING. DIAGNOSTICS: ROADTEST FOR CONERNS , NOT  
PRESENT , CHECK DTCS CONT U0131 PSCM KOEO- PASS PARTS REPLACED::  
NONE TECH QUESTION: WSM IS INCOMPLETE. CHEKCING FOR REPORTS OR  
KNOWN CONCERNS. ANY FURTHER DIAG?

**RECOMM** 05/18/2011 06:43PM FRED SHEPHERD MSS - FCSD - TECH SVC HOTLINE  
HI CHAD. WE ARE NOT AWARE OF ANY COMMON TRENDS OR CONCERNS FOR  
THIS  
ISSUE OTHER THEN SSM 21737. PLEASE DUPLICATE THE CONCERN PRIOR TO ANY  
REPAIR AND WHEN PRESENT, REFER TO THE SSM AND CHECK FOR CONCERNS AT  
C139 AND REPAIR AS NEEDED. IF OK, LOAD TEST ALL PSCM POWERS AND  
GROUNDS AND REPAIR IF NECESSARY AND RETEST. IF YOU NEED ADDITIONAL  
ASSISTANCE, PLEASE LET US KNOW. THANKS. SSM 21737 CODES C1B00,  
U0131, U0100, U0001, U0121, AND/OR U0151- CLEAR CODES AND WIGGLE TEST  
CONNECTER C139. IFCODES RETURN, BYPASS C139 FOR CIRCUITS VDB04 AND  
VDB05 USING THE SOLDER AND SHRINK TUBING METHOD FOUND IN SECTION 5  
OF  
THE WIRING DIAGRAMS.

---

**From:** Napoli, Laura (L.)  
**Sent:** Wednesday, May 25, 2011 10:01 AM  
**To:** Anderson, Eric (H.)  
**Subject:** RE: 2011 Exp - BG [REDACTED] - Loss of steering assist, 3 mi, BD 5/9/11

Ok, thanks for trying. It'll be interesting to know if a new gear fixes the problem.

---

**From:** Anderson, Eric (H.)  
**Sent:** Tuesday, May 24, 2011 6:10 PM  
**To:** Napoli, Laura (L.)  
**Subject:** FW: 2011 Exp - BG [REDACTED] - Loss of steering assist, 3 mi, BD 5/9/11

Hi Laura:

I called this tech again. He said he followed the DTC symptom chart to look at section 418-00 but was not able to solve the communication/no assist problem. I told him I could not authorize a gear swap and to work with hotline for the rest of the repair.

Looks like we're getting this gear back. We'll just have to wait to find out what the real problem is.

Thanks,

Eric

---

**From:** Buelow, Steve (S.E.)  
**Sent:** Friday, May 20, 2011 11:07 AM  
**To:** Adamczyk, David (D.W.); Bollwahn, Bryce (B.A.); Centlivre, James (J.C.); Cheatham, Sandy (.); Cittadino, Lisa (L.C.); Collins, Kevin (K.E.); Gagnier, Kathryn (K.A.); Gilewski, David (D.); Gillanders, Eric (E.S.); Gray, Carl (C.L.); Gubing, William (Bill.); Hays, Andy (A.R.); Krochmalny, Kevin (K.); Mann, Mickey (N.S.); McClain, Shawn (S.M.); Pogorzelski, John (J.M.); Rodgers, Chuck (.); Saleh, Salim (S.A.); Sellers, Gary (G.T.); Shaukat, Nadeem (N.S.); Simkus, Walter (W.A.); Sokolowski, Todd (T.M.); Thornsberry, Joel (J.A.); Willis, Mark (M.E.); Wong, Vicki (V.A.); Acuna, Aaron (A.A.); Allman, Jan (J.E.); Bell, Tim (.); Bergeron, Matthew (M.C.); Bisaga, Richard (R.); Boykin, George (G.); Boykins, Michael (M.); Bustamante, Chris (C.T.); Cantrell, David (D.D.); Carter, Tracy (T.); Ciotti, Steven (S.R.); Davis, Charlene (C.); Devine, Robert (R.M.); Docimo, Tony (A.F.); Ferguson, Hugh (H.); Gagnier, Scott (S.W.); Greenwell, R (R.); Guyton, MzJenny (J.); Hernandez, Thomas (T.); Herron, Micheal (M.C.); Inglis, Steve (S.D.); Iqbal, Khurram (K.); Jones, Frederick (F.L.); Little, Janie (J.); Martin, Kenneth (K.A.); Matlock, Douglas (D.); McElroy, Darin (D.L.); McKernan, Patrick (P.J.); Miller, Melinda (M.S.); Moore, Chikynda (D.); Moskwa, Larry (L.M.); Perkins, John (J.E.); Russell, David (D.A.); Rutovic, Nick (N.); Sarkisian, Mark (Z.); Talbott, Larry (J.L.); Turner, Bridgette (B.); Turner, Patrice (P.T.); Vandergroef, Cornelius (C.); Washington, Kellie (K.S.); Wertman, David Brian (D.B.); Westbrook, Dori (D.); Williams, Erik (E.C.); Williams, Gregory (G.M.); Wyatt, Kimberly (K.D.); Zroback, David (D.P.); Armstrong, Miya (M.); Buerger, Robert (R.G.); Evans, Kayekethia (K.); Gibson, Renelda (R.); Lakomek, Scott (S.); Napier, S (S.); Ornelas, Demetrio (D.); Ratliff, Kathy (K.); Scheldberg, Gary (G.D.); Stonewall, Wendy (M.); Svetich, Chris (C.); Torian, Jason (J.B.); Anderson, Eric (H.); Berzeri, Marcello (M.); Cassata, Joe (J.); Chamberlain, Steve (J.); Edwards, Monty (M.R.); Farmer, Marty (M.F.); Feder, Andrew (A.); Gerrard, Ryan (R.P.); Iannotti, Jason (JRI.); Ickes, Walt (W.D.); Issa, Ibrahim (I.M.); Jackson, Bradley (B.G.); Logli, Michael (M.A.); Morgan, Anthony (A.); Olsson, Paul (P.C.); Polaski, Mike (M.S.); Porter, Alan (A.T.); Rapiz, Noreen (N.G.); Santilli, Rennie (R.); Smith, Erin (E.); Sridhara, Raghu (R.); Trygar, Mike (M.); Vargo, Rebecca (R.L.); Widrick, Brad (B.A.); Young, Richard (R.C.); Yu, Eric (E.); Buelow, Steve (S.E.)  
**Subject:** FW: 2011 Exp - BG [REDACTED] - Loss of steering assist, 3 mi, BD 5/9/11

**-The Customer Defines Quality-**

*Steve Buelow - Ford Motor Company*

FCSD Program Manager-  
Taurus/Taurus SHO/Lincoln MKS/Explorer  
Chicago Assembly PVT Office, COE  
773-646-7495 DialNet 686-7495  
Cell 773-726-0808 sbuelow@ford.com

"Quality means doing it right when no one is looking." - Henry Ford

---

**From:** SBUELOW@ford.com [mailto:SBUELOW@ford.com]  
**Sent:** Friday, May 20, 2011 9:52 AM  
**To:** Buelow, Steve (S.E.)  
**Subject:** 2011 Exp - BG [REDACTED] - Loss of steering assist, 3 mi, BD 5/9/11

**Attachments :** 0

<b>Report# :</b>	BESD7009 NHL	<b>Received:</b>	05/19/2011
<b>CCRG/EPRC:</b>		<b>Date:</b>	
<b>Vehicle:</b>	2011,EXPLORER 4X2 (U502),4 DOOR ,MP,1FMHK7D85BG [REDACTED]	<b>Build Date:</b>	05/09/2011
<b>Odometer :</b>	3 M	<b>Engine:</b>	3.5L CYCLO
<b>Transmission:</b>	6F50	<b>Axle:</b>	
<b>Dealer:</b>	USA 02459 Sam Pack's Five Star Ford	<b>Calibration:</b>	
<b>City:</b>	Carrollton	<b>A/C:</b>	YES
<b>Originator:</b>	BRIAN MCKEVITT	<b>Phone#:</b>	(972) 242- 6415
<b>Symptom:</b>	3 03 1 50 CHASS.,STRG/HANDLING ,FUNCTION,HIGH EFFORT	<b>Country :</b>	USA
<b>Status:</b>			
<b>VFG:</b>	V87 STEERING		
<b>Additional Symptom:</b>	NO STEERING ASSIST		
<b>Fix:</b>	<b>Causal Component :</b>		
<b>Condition Code:</b>			

**Hotliner:** JTAYL466

**Phone:** 000 000-0000

**Regn Cd:** C1 Dallas

**Engineering:**

**Phone:**

**TAR:**

**Dlr Contact:** BRIAN MCKEVITT

**Phone:** 972 446-5000

**Title Cde:** T

**DTCs:**

KOEO:C1B00:86 C1B00:41 U0131:00

KOEC:

KOER:

**Comments**

:

**REPAIR** 05/19/2011 04:27PM JASON TAYLOR MSS - FCSD - TECH SVC HOTLINE  
WEB FORM DATA - CONCERN: VEHICLE HAS NO STEERING  
ASSIST DIAGNOSTICS: SELF TEST NO COMUNICATION WITH PSCM. ABS MODULE  
STORED CODES CONTINUOUS: C1B00:86-68, C1B00:41-68, U0131:00-AB. TESTED  
BOTH POWERS TO PSCM: PIN 1 C1463B 12.6V, PIN 3 C1463A 12.6V. TESTED  
GROUND PIN 2 C1463B .8 OHMS CONTINUITY TO GROUND. TESTED HIGH SPEED  
CAN CIRCUITS FROM DLC TO PSCM BOTH .8 OHMS. CONNECTOR PINS AND PINS AT  
PSCM APPER IN CORRECT LOCATION NOT PUSHED OUT AND ARE IN GOOD  
CONDITION. RECONNECTED AND TESTED CONCERN STILL PRESENT PARTS  
REPLACED.: NONE TECH QUESTION: LOOKING FOR KNOWN CONCERNS BEFORE  
REPLACING PSCM GEAR ASSEMBLY

**RECOMM 05/19/2011 04:27PM JASON TAYLOR MSS - FCSD - TECH SVC HOTLINE**

BRIAN, SUGGEST YOU USE <>  
HREF='HTTP://WWW.VREP.FORDTECHSERVICE.DEALERCONNECTION.COM/VDIRS/SSM/S  
SM.ASP?SSM=21737' TARGET='\_BLANK'>SSM 21737 TO ADDRESS THIS  
CONDITION. SSM 21737 CODES C1B00, U0131, U0100, U0001, U0121, AND/OR  
U0151- CLEAR CODES AND WIGGLE TEST CONNECTER C139. IFCODES RETURN,  
BYPASS C139 FOR CIRCUITS VDB04 AND VDB05 USING THE SOLDER AND SHRINK  
TUBING METHOD FOUND IN SECTION 5 OF THE WIRING DIAGRAMS.

**REPAIR 05/19/2011 06:39PM JOSEPH REDDMANN MSS - FCSD - TECH SVC HOTLINE**

TECHNICIAN REPLY: WIGGLE TESTED NO CHANGE IN CONDITION INSPECTED PIN  
FIT APPEARED OK. BYPASSED CONNECTOR AND HARD WIRED CIRCUITS PER SSM.  
NO CHANGED IN CONCERN. STILL NO COMUNICATION WITH PSCM WHEN ATEMPTING  
A SELF TEST. THE PSCM DOES PASS THE NETWORK TEST

**RECOMM 05/19/2011 06:39PM JOSEPH REDDMANN MSS - FCSD - TECH SVC HOTLINE**

BRIAN, IF THE PSCM PASSES NETWORK BUT FAILS SELF TEST, CHECK ALL  
POWER AND GROUND TO THE MODULE. IF ALL APPEARS GOOD, REPLACE THE PSCM  
AND RE-EVALUATE THE CONCERN. IF YOU WOULD LIKE ANY ADDITIONAL  
INFORMATION OR ASSISTANCE, PLEASE UPDATE THIS FORM IN THE SPACE  
PROVIDED BELOW.

---

**From:** Napoli, Laura (L.)  
**Sent:** Tuesday, August 02, 2011 1:51 PM  
**To:** Anderson, Eric (H.); Pasquarella, Michael (M.S.); 'Gregory Sheets'  
**Subject:** RE: 2011 Exp - BG [REDACTED] - Loss of power steering assist, 829 mi, BD 6/17/11

The TS failures we've gotten back are not related to Bent Finger.

Eric E, can you confirm if we have this one back yet? I know we had 2 that were Hella electrical issues.

---

**From:** Anderson, Eric (H.)  
**Sent:** Tuesday, August 02, 2011 12:43 PM  
**To:** Napoli, Laura (L.); Pasquarella, Michael (M.S.); Gregory Sheets  
**Subject:** FW: 2011 Exp - BG [REDACTED] - Loss of power steering assist, 829 mi, BD 6/17/11

Hi Laura, Mike and Greg:

This is a C200B/ C200C torque sensor CQIS claim for a unit built 6/17/2011. According to the BSAQ project, the problem is supposed to have been permanently fixed on 5/12/2011. Could this unit have received an older gear? What is the pipeline between Marion and ZF Chicago?

Mike,  
Will the finger ring improvement solve this problem? Please remind me when that change became permanent.

Thanks,

Eric

---

**From:** Buelow, Steve (S.E.)  
**Sent:** Tuesday, August 02, 2011 10:40 AM  
**To:** Adamczyk, David (D.W.); Bollwahn, Bryce (B.A.); Centlivre, James (J.C.); Cheatham, Sandy (.); Cittadino, Lisa (L.C.); Collins, Kevin (K.E.); Gagnier, Kathryn (K.A.); Gilewski, David (D.); Gillanders, Eric (E.S.); Gubing, William (Bill.); Hays, Andy (A.R.); Krochmalny, Kevin (K.); Mann, Mickey (N.S.); McClain, Shawn (S.M.); Pogorzelski, John (J.M.); Rodgers, Chuck (.); Saleh, Salim (S.A.); Sellers, Gary (G.T.); Shaukat, Nadeem (N.S.); Simkus, Walter (W.A.); Sokolowski, Todd (T.M.); Thornsberry, Joel (J.A.); Willis, Mark (M.E.); Wong, Vicki (V.A.); Acuna, Aaron (A.A.); Allman, Jan (J.E.); Bell, Tim (.); Bergeron, Matthew (M.C.); Bisaga, Richard (R.); Boykin, George (G.); Boykins, Michael (M.); Bustamante, Chris (C.T.); Cantrell, David (D.D.); Carter, Tracy (T.); Chones, Marvin (M.); Ciotti, Steven (S.R.); Davis, Charlene (C.); Devine, Robert (R.M.); Docimo, Tony (A.F.); Ferguson, Hugh (H.); Gagnier, Scott (S.W.); Greenwell, R (R.); Guyton, MzJenny (J.); Hernandez, Thomas (T.); Herron, Micheal (M.C.); Inglis, Steve (S.D.); Iqbal, Khurram (K.); Jones, Frederick (F.L.); Little, Janie (J.); Lux, Tracie (T.L.); Martin, Kenneth (K.A.); Matlock, Douglas (D.); McElroy, Darin (D.L.); McKernan, Patrick (P.J.); Miller, Melinda (M.S.); Moore, Chikynda (D.); Moskwa, Larry (L.M.); Perkins, John (J.E.); Rutovic, Nick (N.); Sarkisian, Mark (Z.); Talbott, Larry (J.L.); Turner, Bridgette (B.); Turner, Patrice (P.T.); Vandergroef, Cornelius (C.); Washington, Kellie (K.S.); Wertman, David Brian (D.B.); Westbrook, Dori (D.); Williams, Erik (E.C.); Williams, Gregory (G.M.); Wyatt, Kimberly (K.D.); Zroback, David (D.P.); Armstrong, Miya (M.); Buerger, Robert (R.G.); Evans, Kayekethia (K.); Gibson, Renelda (R.); Lakomek, Scott (S.); Napier, S (S.); Ornelas, Demetrio (D.); Ratliff, Kathy (K.); Scheldberg, Gary (G.D.); Stonewall, Wendy (M.); Svetich, Chris (C.); Torian, Jason (J.B.); Anderson, Eric (H.); Baldwin, Mark (M.E.); Berzeri, Marcello (M.); Cassata, Joe (J.); Chamberlain, Stephen (J.); Edwards, Monty (M.R.); Farmer, Marty (M.F.); Feder, Andrew (A.); Gerrard, Ryan (R.P.); Ickes, Walt (W.D.); Issa, Ibrahim (I.M.); Jackson, Bradley (B.G.); Logli, Michael (M.A.); Olsson, Paul (P.C.); Polaski, Mike (M.S.); Porter, Alan (A.T.); Rapiz, Noreen (N.G.); Santilli, Rennie (R.); Sridhara, Raghu (R.); Trygar, Mike (M.); Urbina, Christopher (C.); Widrick, Brad (B.A.); Young, Richard (R.C.); Yu, Eric (E.);

Buelow, Steve (S.E.)

**Subject:** FW: 2011 Exp - BG [REDACTED] - Loss of power steering assist, 829 mi, BD 6/17/11

**-The Customer Defines Quality-**

*Steve Buelow - Ford Motor Company*

FCSD Program Manager-  
Taurus/Taurus SHO/Lincoln MKS/Explorer  
Chicago Assembly PVT Office, COE  
773-646-7495 DialNet 686-7495  
Cell 773-726-0808 sbuelow@ford.com

"Quality means doing it right when no one is looking." - Henry Ford

---

**From:** SBUELOW@ford.com [mailto:SBUELOW@ford.com]  
**Sent:** Tuesday, August 02, 2011 8:57 AM  
**To:** Buelow, Steve (S.E.)  
**Subject:** 2011 Exp - BG [REDACTED] - Loss of power steering assist, 829 mi, BD 6/17/11

**Attachments :** 0

<b>Report# :</b>	BHACJ011 NHL	<b>Received:</b>	08/01/2011
<b>CCRG/EPRC:</b>		<b>Date:</b>	
<b>Vehicle:</b>	2011,EXPLORER 4X2 (U502),4 DOOR ,MP,1FMHK7B88BG [REDACTED]	<b>Build Date:</b>	06/17/2011
<b>Odometer :</b>	829 M	<b>Engine:</b>	3.5L CYCLO
<b>Transmission:</b>	6F55	<b>Axle:</b>	
<b>Dealer:</b>	USA 07868 Lilliston Ford Mercury	<b>Calibration:</b>	
<b>City:</b>	Kingsland	<b>A/C:</b>	YES
<b>Originator:</b>	TERRY STATON	<b>Phone#:</b>	(912) 510- 3673
<b>Symptom:</b>	2 27 Z 00 AID/INFO,WNG IND/MESS/C,NOT LISTED,UNKNOWN	<b>Country :</b>	USA
<b>Status:</b>			
<b>VFG:</b>	V83 INSTRUMENTATION FUNCTION		
<b>Additional Symptom:</b>	EPAS INOP		
<b>Fix:</b>	<b>Causal Component :</b>		
<b>Condition Code:</b>			

**Hotliner:** APINKER3

**Phone:** 000 317-7066

**Regn Cd:** S3 Orlando



**Engineering:**

**Phone:**

**TAR:**

**Dlr Contact:** TERRY STATON

**Phone:** 000 000-0000

**Title Cde:** OT

**DTCs:**

KOEO:

KOEC:C200C C200B

KOER:

**Comments**

:

**REPAIR** 08/01/2011 02:53PM ADAM PINKERTON MSS - FCSD - TECH SVC HOTLINE  
 WEB FORM DATA - CONCERN: NO POWER STEERING ASST., MESSAGE CENTER HAS  
 P/S LIGHT ON DIAGNOSTICS: CHECK WIRING AND CONNECTOR OK, HOOK UP  
 IDS. CHECK FOR CODES, PARTS REPLACED:: N/A TECH QUESTION: I DID  
 THE PPT.B-3, AFTER DRIVING , RE CHECK FOR CODES NONE, BUT WHAT SHOULD  
 BE DONE NEXT?, ARE THERE ANY KNOWN PROBLEMS WITH THIS SYSTEM?

**RECOMM** 08/01/2011 02:53PM ADAM PINKERTON MSS - FCSD - TECH SVC HOTLINE  
 TERRY, THERE ARE NO COMMON TRENDS OR SIMILAR REPORTS OF THIS  
 CONCERN. IT IS RECOMMENDED TO FOLLOW PINPOINT TEST I FROM SECTION  
 211-00 OF THE ON-LINE WSM UNDER INTERACTIVE DIAGNOSTICS. THIS PINPOINT  
 TEST WILL HELP ISOLATE THE CAUSE OF THIS CONCERN.

---

**From:** Napoli, Laura (L.)  
**Sent:** Monday, July 11, 2011 3:46 PM  
**To:** Rochna, Jeffery (J.P.); Carter, James (J.W.)  
**Subject:** RE: 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

Yeah, that's fine. No point if you guys are almost done.

James,  
What's the plan for 2013 TT build? Any updates already scheduled once the cars hit DEMS, etc?

---

**From:** Rochna, Jeffery (J.P.)  
**Sent:** Monday, July 11, 2011 3:43 PM  
**To:** Napoli, Laura (L.)  
**Cc:** Sims, Steven (S.W.); Carter, James (J.W.)  
**Subject:** RE: 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

Laura,

The two vehicles are fixed. Both wiring issues.

We only have 4 more vehicles that need to be updated w/ PUMA. I know you said new EPAS software is now available, but can you or supplier re-flash the EPAS? Not sure if it is worth updating PUMA for the last 4 vehicles. Thanks.

-----  
Regards,  
Jeff Rochna  
2011 U502 E/E Systems  
Phone: (313) 805-4155  
E-mail: jrochna@ford.com, PDC Cube 2H-E35  
-----

---

**From:** Napoli, Laura (L.)  
**Sent:** Monday, July 11, 2011 2:17 PM  
**To:** Rochna, Jeffery (J.P.); Sims, Steven (S.W.); Carter, James (J.W.)  
**Subject:** FW: 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

See warranty list below for EPAS no comm troubleshooting...

---

**From:** Anderson, Eric (H.)  
**Sent:** Wednesday, June 15, 2011 11:18 AM  
**To:** Napoli, Laura (L.); Estes, Eric (E.E.)  
**Subject:** RE: 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

Hi Laura and Eric:

By my count, the Diagnostic Routine S for DTC U0131 in the SSM covers all but one of the recently learned electrical issues:

GD108 circuit	covered
VDB04 circuit	covered
VDB05 circuit	covered
Fuse #89	covered
Pushed out connectors	covered
C139 connector	covered
Battery junction box fasteners	NOT COVERED

Adding the BJB fastener check could go right before or after the fuse #89 check.

Maybe it takes practice to read the workshop manuals. I found it very confusing. I'm not surprised techs call hotline to solve issues.

Thanks,

Eric

---

**From:** Napoli, Laura (L.)  
**Sent:** Wednesday, June 15, 2011 9:08 AM  
**To:** Estes, Eric (E.E.); Anderson, Eric (H.)  
**Subject:** RE: 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

Eric E found that this has a B3A and a C69. The service manual tells these guys to change out a gear with these codes. Not sure why FSCD is instructing them to do all these electrical checks for a C69. We're paying them to do all these checks for no reason.

---

**From:** Napoli, Laura (L.)  
**Sent:** Wednesday, June 15, 2011 9:30 AM  
**To:** Estes, Eric (E.E.); Anderson, Eric (H.)  
**Subject:** FW: 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

Eric E, can you call the dealer to see if there are any codes in this gear? None are reported.

Eric A, does the SSM cover all the recently learned electrical issues?

---

**From:** SBUELOW [mailto:SBUELOW]  
**Sent:** Wednesday, June 15, 2011 4:55 AM  
**To:** LNAPOLI  
**Subject:** 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

This email contains 5 report summary(s).

---

**Attachments :** 0

**Report# :** BFNC5004 NHL

**Received:** 06/14/2011

**CCRG/EPRC:** **Reviewed Status:** **Date:**  
**Vehicle:** 2011,EXPLORER 4X4 (U502),4 DOOR **Build Date:** 12/02/2010  
,MP,1FMHK8B88BG [REDACTED]  
**Odometer :** 5,016 M **Engine:** 3.5L **Calibration:** BUB1ST0A  
CYCLO  
**Transmission:** 6F55 **Axle:** **A/C:** YES  
**Dealer:** USA 02199 Bob Gillingham Ford, Inc. **Phone#:** (216) 398-  
1300  
**City:** Parma **State:** Ohio **Country :** USA  
**Originator:** DINO MICELI  
**Symptom:** 3 03 1 50 CHASS.,STRG/HANDLING ,FUNCTION,HIGH EFFORT  
**Status:**  
**VFG:** V87 STEERING  
**Additional Symptom:** NO STEERING ASSIST  
**Fix:** **Causal Component :** --  
**Condition Code:**

**Hotliner:** JTAYL466 **Phone:** 000 000-0000 **Regn Cd:** G4 Pittsburgh  
**Engineering:** **Phone:** **TAR:**  
**Dlr Contact:** DINO MICELI **Phone:** 216 398-1300 **Title Cde:** T

**DTCs:**  
KOE0:C1B00 U3000 U2011  
KOE0:  
KOE0:

**Comments**  
:

**REPAIR** 06/14/2011 12:25PM JASON TAYLOR MSS - FCSD - TECH SVC HOTLINE  
WEB FORM DATA - CONCERN: NO POWER STEERING DIAGNOSTICS: VISUAL,  
PINPOINT TEST B. LEAD TO RWEPLACED RACK PARTS REPLACED::  
NONE TECH QUESTION: PINPOINT TEST LEAD TO REPLACE RACK. NEVER HAD U  
CHECK POWERS AND GROUNDS TO RACK JUST VISUAL ON WIRES AND  
CONNECTORS.  
ANY KNOWN CONCERNS. ALSO SHOULD SSM 21737 BE PERFORMED. WERE YOU  
ABLE TO VERIFY THE CONCERN? YES IS THERE AN APPROPRIATE PINPOINT  
TEST IN THE WSM FOR THIS CONCERN? YES WAS THE PINPOINT TEST  
FOLLOWED? YES  
**RECOMM** 06/14/2011 12:25PM JASON TAYLOR MSS - FCSD - TECH SVC HOTLINE  
DINO, THE SSM 21737 IS ADDRESSING AN INTERMITTENT COMMUNICATION  
CONCERN WITH THE PSCM AND IS SPECIFIC TO THE CODES LISTED IN THE SSM.  
THIS VEHICLE DOES FALL WITHIN THE BUILD DATE OF THE SSM SO I WOULD

SUGGEST INSPECTING THESE PINS FOR ANY LOOSENESS OR DAMAGE. IF ANY PIN FIT ISSUES ARE FOUND, THEN I WOULD SUGGEST PERFORMING THE SSM 21737. IF NO PIN FIT ISSUES ARE FOUND OR THE CONCERN IS STILL PRESENT AFTER PERFORMING THE SSM, THEN SUGGEST PERFORMING A LOAD TEST ON THE POWER AND GROUND TO PSCM. IF THE POWERS AND GROUND CIRCUITS PROVE OUT, THEN SUGGEST REPLACING THE RACK FOR THIS CONCERN. SSM 21737 CODES C1B00, U0131, U0100, U0001, U0121, AND/OR U0151- CLEAR CODES AND WIGGLE TEST CONNECTER C139. IF CODES RETURN, BYPASS C139 FOR CIRCUITS VDB04 AND VDB05 USING THE SOLDER AND SHRINK TUBING METHOD FOUND IN SECTION 5 OF THE WIRING DIAGRAMS.

---

**From:** Napoli, Laura (L.)  
**Sent:** Thursday, June 09, 2011 1:18 PM  
**To:** Estes, Eric (E.E.); Anderson, Eric (H.)  
**Cc:** Mrozek, Robert (R.M.)  
**Subject:** RE: 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

Thank you Eric E!!

---

**From:** Estes, Eric (E.E.)  
**Sent:** Thursday, June 09, 2011 11:53 AM  
**To:** Napoli, Laura (L.); Anderson, Eric (H.)  
**Subject:** RE: 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

Talked to the tech below and this loss of assist would always occur in low speed parking lot maneuvers similar to the Focus issue and had him check the HC BJB main feed and the 100a fuse connections and the tech found the main battery feed loose to high current battery junction box, he tightened the nut 1 1/2 turns to torque it properly, road test now the vehicle is fixed.

Eric

---

**From:** Napoli, Laura (L.)  
**Sent:** Thursday, June 09, 2011 8:40 AM  
**To:** Anderson, Eric (H.); Estes, Eric (E.E.)  
**Subject:** FW: 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

Can one of you follow up with this dealer and make sure they are running all the electrical checks and have them look for any of our newly known issues? There are no codes from EPAS and it seems to be intermittent. Sounds like a wiring issue again...

---

**From:** SBUELOW [mailto:SBUELOW]  
**Sent:** Thursday, June 09, 2011 4:33 AM  
**To:** LNAPOLI  
**Subject:** 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

This email contains 7 report summary(s).

**Attachments :** 0

<b>Report# :</b>	BFHBT004 NHL	<b>Received:</b>	06/08/2011		
<b>CCRG/EPRC:</b>	S	<b>Reviewed Status:</b>	06/08/2011		
<b>Vehicle:</b>	2011,EXPLORER 4X2 (U502),4 DOOR ,MP,1FMHK7B84BG [REDACTED]	<b>Build Date:</b>	03/03/2011		
<b>Odometer :</b>	6,672 M	<b>Engine:</b>	3.5L CYCLO	<b>Calibration:</b>	
<b>Transmission:</b>	6F50	<b>Axle:</b>		<b>A/C:</b>	YES

**Dealer:** USA 05017 Friendly Ford, Inc. **Phone#:** (417) 883-4330  
**City:** Springfield **State:** Missouri **Country :** USA  
**Originator:** JEFFREY WHILES  
**Symptom:** 3 03 1 55 CHASS.,STRG/HANDLING ,FUNCTION,LOSS OF STRG  
**Status:**  
**VFG:** V89 RIDE & HANDLING  
**Additional Symptom:** TRAC LIGHT AND LOSS OF ASSIST  
**Fix:** **Causal Component :** --  
**Condition Code:**

**Hotliner:** DWEST90 **Phone:** 313 248-9291 **Regn Cd:** C4 Kansas City  
**Engineering:** **Phone:** **TAR:**  
**Dlr Contact:** JEFFREY WHILES **Phone:** 417 883-4330 **Title Cde:** SW

**DTCs:**  
KOEO:C1B00:86  
KOEC:  
KOER:

**Comments**

:  
REPAIR 06/08/2011 10:02AM DEVIN WEST MSS - FCSD - TECH SVC HOTLINE  
WEB FORM DATA - CONCERN: C/S STEERING WILL LOCK AND LOOSE ELT ASSIST,  
TRAC LIGHTS COME ON AND HAS MESSAGE COME UP IN MESSAGE  
CENTER. DIAGNOSTICS: UNABLE TO VERIFY CONCERN, CUST HAS BROUGHT IN  
TWICE FOR CONCERN PARTS REPLACED:: NONE TECH QUESTION: ANY  
KNOWN WERE YOU ABLE TO VERIFY THE CONCERN? NO IS THERE AN  
APPROPRIATE PINPOINT TEST IN THE WSM FOR THIS CONCERN? NO WAS THE  
PINPOINT TEST FOLLOWED? NO

**RECOMM 06/08/2011 10:02AM DEVIN WEST MSS - FCSD - TECH SVC HOTLINE**  
JEFFREY, MORE INFORMATION WILL BE NEEDED TO EFFECTIVELY ASSIST YOU.  
RECOMMEND TO RUN ALL CMDTCS BEFORE CONTINUING TO ENSURE THAT NO  
MODULES ARE SETTING CODES. TALK TO THE CUSTOMER TO DETERMINE WHAT  
THE  
MESSAGE ACTUALLY SAID AND ASK IF THE FAULT OCCURS UNDER ANY  
SPECIFIC  
DRIVING CONDITIONS OR IF IT IS AFFECTED BY THE WEATHER CONDITIONS.  
UPDATE THE FORM OR CONTACT THE TECHNICAL HOTLINE BY TELEPHONE WITH  
AS  
MUCH DETAIL AS POSSIBLE SO THAT WE CAN ASSIST YOU WITH THIS REQUEST.  
THANK YOU.

**REPAIR 06/08/2011 05:50PM ALEXANDER ROGERS MSS - FCSD - TECH SVC HOTLINE**  
TECHNICIAN REPLY: CODES RETRIEVED LAST TIME IN C1B0086-68 AND  
C1B0086-28, ITS BEEN AFTERNOON WHEN SHE IS LEAVING WORK 90+ DEGREES.  
PARKING LOT SPEEDS

**RECOMM 06/08/2011 05:50PM ALEXANDER ROGERS MSS - FCSD - TECH SVC HOTLINE**  
JEFFREY, STEERING ANGLE ON THIS VEHICLE IS CALCULATED BY THE PSCM  
AND SENT TO THE ABS MODULE VIA HS CAN. A LOSS OF HS CAN  
COMMUNICATION  
OR AN INTERNAL PSCM/STEERING RACK FAULT IS LIKELY TO BE THE CAUSE OF  
THIS CONCERN. WE WOULD RECOMMEND ALLOWING THE VEHICLE TO SIT IN  
HOT AMBIENT TEMPERATURES AND ATTEMPTING TO DUPLICATE A DTC. IF AN  
ON  
DEMAND CODE CAN BE DUPLICATED, NOTE IF ANY DTC'S SET IN THE PSCM, AND  
REFER TO THE EPAS INTERACTIVE DIAGNOSTICS IN WORKSHOP MANUAL  
SECTION  
211-00 TO ADDRESS ANY NOTED CODES. IF NO DTC'S ARE PRESENT IN THE  
PSCM, DIAGNOSE THE CONCERN BY SYMPTOM USING THE LACK OF ASSIST OR  
INCONSISTENT ASSIST TEST IN THE INTERACTIVE DIAGNOSTICS' SYMPTOM  
CHART.

---



---

**From:** Estes, Eric (E.E.)  
**Sent:** Tuesday, June 07, 2011 11:54 AM  
**To:** Napoli, Laura (L.)  
**Subject:** RE: 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

Looking at interactive diagnosis I do see a PSCM code U2011-61 which is a motor signal calculation fault most likely a B92 but could also have other codes associated with a B95.

Eric

---

**From:** Napoli, Laura (L.)  
**Sent:** Tuesday, June 07, 2011 8:35 AM  
**To:** Estes, Eric (E.E.)  
**Subject:** FW: 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

Another loss of assist for U502. It was a C69, so there's nothing we can do til we get the gear back.

---

**From:** SBUELOW [mailto:SBUELOW]  
**Sent:** Tuesday, June 07, 2011 8:31 AM  
**To:** LNAPOLI  
**Subject:** 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

This email contains 4 report summary(s).

**Attachments :** 0

REDACTED FOR RELEVANCE

REDACTED FOR RELEVANCE

REDACTED FOR RELEVANCE

**Report# :** BFFDK013 NHL  
**CCRG/EPRC:** **Reviewed Status:**  
**Vehicle:** 2011,EXPLORER 4X2 (U502),4 DOOR  
,MP,1FMHK7D80BG [REDACTED]  
**Odometer :** 2,707 M **Engine:** 3.5L  
CYCLO **Calibration:** BUB1SN0A  
**Transmission:** 6F50 **Axle:** **A/C:** YES  
**Dealer:** USA 00210 Sunny King Ford **Phone#:** (256) 831-5300  
**City:** Anniston **State:** Alabama **Country :** USA  
**Originator:** JAMIE FORD  
**Symptom:** 3 03 1 50 CHASS.,STRG/HANDLING ,FUNCTION,HIGH EFFORT  
**Status:**  
**VFG:** V87 STEERING  
**Additional Symptom:** HIGH STEERING EFFORT  
**Fix:** **Causal Component :** --  
**Condition Code:**

**Hotliner:** JELLERH2 **Phone:** 313 317-9374 **Regn Cd:** S1 Atlanta  
**Engineering:** **Phone:** **TAR:**  
**Dlr Contact:** JAMIE FORD **Phone:** 256 831-5300 **Title Cde:** T

**DTCs:**  
KOEO:U3000:96  
KOEC:  
KOER:

**Comments**

:

**REPAIR** 06/06/2011 02:34PM JAMES ELLERHOLZ MSS - FCSD - TECH SVC HOTLINE  
WEB FORM DATA - CONCERN: POWERSTEERING HARD TO TURN DIAGNOSTICS:  
CK. CODES AND VERIFY CONCERN PARTS REPLACED:: CLOCKSPrING TECH  
QUESTION: ALL CODES FOR SCCM WENT AWAY AFTER CLOKSPRING  
REPLACEMENT

NOW HAVE CODE FOR PSCM CODE IS U3000:96-C8 NEED HELP IN DIAG

**RECOMM** 06/06/2011 02:34PM JAMES ELLERHOLZ MSS - FCSD - TECH SVC HOTLINE

JAMIE, BE SURE THAT THE CORRECT CLOCK SPRING WAS INSTALLED. THE  
INTERACTIVE DIAGNOSIS IN THE WORK SHOP MANUAL WILL NEED TO BE  
FOLLOWED

BASED ON THE CODE IN THIS FORM. THE DIAGNOSIS CAN BE FOUND IN THE  
WORK

SHOP MANUAL SECTION 211-00 AND CLICK ON THE DTC AND SYMPTOM CHART  
AND

THE INTERACTIVE DIAGNOSIS WILL BE ON THE RIGHT SIDE OF THE PAGE.

FOLLOW THE DIAGNOSIS AS INSTRUCTED AND REPAIR AS THE TEST INDICATES.

**REPAIR** 06/06/2011 03:32PM ALEXANDER ROGERS MSS - FCSD - TECH SVC HOTLINE

TECHNICIAN REPLY: PERFORMED TEST PER WORKSHOP MANUAL- TEST  
INDICATES

STEERING GEAR.

**RECOMM** 06/06/2011 03:32PM ALEXANDER ROGERS MSS - FCSD - TECH SVC HOTLINE

JAMIE, DTC U3000:96 IS LIKELY TO INDICATE AN INTERNAL PSCM FAULT.

THE PSCM IS SERVICED WITH THE STEERING GEAR. PLEASE REPLACE THE  
STEERING GEAR AS NEEDED TO ADDRESS THIS CONDITION.

---

REDACTED FOR RELEVANCE

REDACTED FOR RELEVANCE

---

REDACTED FOR RELEVANCE

REDACTED FOR RELEVANCE

---

**From:** Estes, Eric (E.E.)  
**Sent:** Thursday, June 02, 2011 10:43 AM  
**To:** Napoli, Laura (L.); Mrozek, Robert (R.M.)  
**Cc:** Snider, Tim (T.O.); Kingstrom, Mark (M.D.)  
**Subject:** RE: 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

REDACTED FOR RELEVANCE

Eric

---

**From:** Napoli, Laura (L.)  
**Sent:** Thursday, June 02, 2011 9:47 AM  
**To:** Estes, Eric (E.E.); Mrozek, Robert (R.M.)  
**Cc:** Snider, Tim (T.O.); Kingstrom, Mark (M.D.)  
**Subject:** RE: 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

Thanks Eric. Looks like we're going to need to follow up on where we're at with B9A since this is emerging again on U502

REDACTED FOR RELEVANCE

---

**From:** Estes, Eric (E.E.)  
**Sent:** Thursday, June 02, 2011 9:35 AM  
**To:** Mrozek, Robert (R.M.)  
**Cc:** Napoli, Laura (L.)  
**Subject:** RE: 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

The U502 claim below VIN# 1FMHK7D8XBG [REDACTED] with the intermittent C200D(B9A) code I have seen 2-3 times( see interactive attachment), not sure what is causing this B9A issue will need to get the gear back and hopefully be able to duplicate the issue. With an intermittent condition it will be hard to reset this code. The claim from yesterday(s below also looking at interactive diagnosis had an intermittent C200B not sure if the dealer replaced the gear.

REDACTED FOR

REDACTED FOR RELEVANCE



REDACTED FOR RELEVANCE

---

**From:** Mrozek, Robert (R.M.)  
**Sent:** Thursday, June 02, 2011 8:11 AM  
**To:** Estes, Eric (E.E.)

**Cc:** Napoli, Laura (L.)

**Subject:** FW: 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

Please catch up with these dealers to see if there is something new going on. Let me know what you find out. Thank you.

*Rob Mrozek*

Electric Power Steering Supervisor  
CD3/D3/D4/U502/Police/Limo EPAS Programs +  
Active Front Steering Applications Engineering  
Ford Motor Company  
Phone: (313) 805-5947  
e-mail: rmrozek@ford.com

---

**From:** SBUELOW [mailto:SBUELOW]

**Sent:** Thursday, June 02, 2011 4:56 AM

**To:** RMROZEK

**Subject:** 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

This email contains 6 report summary(s).

**Attachments :** 0

REDACTED FOR RELEVANCE

REDACTED FOR RELEVANCE

REDACTED FOR RELEVANCE

---

REDACTED FOR RELEVANCE

REDACTED FOR RELEVANCE

REDACTED FOR RELEVANCE

REDACTED FOR RELEVANCE

Attachments : 0

**Report# :** BFABO004 NHL **Received:** 06/01/2011  
**CCRG/EPRC:** **Reviewed Status:** **Date:**  
**Vehicle:** 2011,EXPLORER 4X2 (U502),4 DOOR **Build Date:** 12/08/2010  
,MP,1FMHK7D8XBG [REDACTED]  
**Odometer :** 4,625 M **Engine:** 3.5L **Calibration:** BUB1ST0A  
CYCLO  
**Transmission:** 6F55 **Axle:** **A/C:** YES  
**Dealer:** USA 04161 Eddie Yaklin Ford Lincoln Merc **Phone#:** (361) 592-2661  
**City:** Kingsville **State:** Texas **Country :** USA  
**Originator:** NATHAN CINOLLO  
**Symptom:** 3 03 1 50 CHASS.,STRG/HANDLING ,FUNCTION,HIGH EFFORT  
**Status:**  
**VFG:** V87 STEERING  
**Additional Symptom:** HIGH EFFORT  
**Fix:** **Causal Component :** --

**Condition Code:**

**Hotliner:** MABELA3 **Phone:** 000 248-9263 **Regn Cd:** C2 Houston  
**Engineering:** **Phone:** **TAR:**  
**Dlr Contact:** NATHAN CINOLLO **Phone:** 000 000-0000 **Title Cde:** T

**DTCs:**

KOEO:  
KOEC:C1B00 U3000:96 U0291  
KOER:

**Comments**

:  
REPAIR 06/01/2011 09:51AM MATT ABELA MSS - FCSD - TECH SVC HOTLINE  
WEB FORM DATA - CONCERN: POWER STERRING INOP DIAGNOSTICS:  
NONE PARTS REPLACED.: NONE TECH QUESTION: PINPOINT TEST C1 ASKS  
IF CODE U3000.96 IS PRESENT AND IF SO REPLACED EPAS, I DO HAVE THIS  
CODE PRESENT BUT IT IS AND MEMORY CODE NOT ON DEMAND BUT POWER

STERRING ASSIST INACTIVE MESSAGE ALWAYS ON, DO I REPALCE EPAS IF THE CODE IS IN MEMORY .[ WERE YOU ABLE TO VERIFY THE CONCERN? YES IS THERE AN APPROPRIATE PINPOINT TEST IN THE WSM FOR THIS CONCERN? YES WAS THE PINPOINT TEST FOLLOWED? YES

**RECOMM 06/01/2011 09:51AM MATT ABELA MSS - FCSD - TECH SVC HOTLINE**

NATHAN, IF THE U3000:96 IS RETURNING CMDTC AFTER BEING CLEARED, THE EPAS SHOULD BE REPLACED. PLEASE ENSURE POWER AND GROUND TO THE EPAS MODULE CAN CARRY A LOAD AND THAT THERE ARE NO TERMINAL (PIN) FIT CONCERNS AT THE EPAS. IF THIS IS OK, REPLACE THE EPAS.

---

**Attachments : 0**

**Report# :** BFADJ010 NHL **Received:** 06/01/2011  
**CCRG/EPRC:** **Reviewed Status:** **Date:**  
**Vehicle:** 2011,EXPLORER 4X2 (U502),4 DOOR **Build Date:** 03/29/2011  
,MP,1FMHK7F82BG [REDACTED]  
**Odometer :** 540 M **Engine:** 3.5L **Calibration:**  
CYCLO  
**Transmission:** 6F55 **Axle:** **A/C:** YES  
**Dealer:** USA 08556 Ford and Lincoln of Bellevue **Phone#:** (877) 374-3931  
**City:** Bellevue **State:** Washington **Country :** USA  
**Originator:** HOWARD WOLF  
**Symptom:** 3 03 1 50 CHASS.,STRG/HANDLING ,FUNCTION,HIGH EFFORT  
**Status:**  
**VFG:** V87 STEERING  
**Additional Symptom:** POWER ASSIST INOP  
**Fix:** **Causal Component :** --

**Condition Code:**

**Hotliner:** BWRIGH77 **Phone:** 313 317-7040 **Regn Cd:** W5 Seattle  
**Engineering:** **Phone:** **TAR:**  
**Dlr Contact:** HOWARD WOLF **Phone:** 425 454-2454 **Title Cde:** T

**DTCs:**

KOEO:C200D

KOEC:

KOER:

**Comments**



:

REPAIR 06/01/2011 03:28PM BRANDON WRIGHT MSS - FCSD - TECH SVC HOTLINE  
WEB FORM DATA - CONCERN: CUSTOMER STATES THAT WHILE DRIVING  
STEERING  
GOT STIFF AND HAD NO ASSIST POWER STEERING FAULT DISPLAYED IN  
MESSAGE  
CENTER DIAGNOSTICS: ROADTEST VERIFIED CONCERN C200D IS THE CODE  
WHEN DOING THE PINPOINT TEST IT HAS ME CLEAR THEN TURN LKOCK TO LOCK  
A  
FEW TIMES THEN RETEST IT WILL BE OK THEN NSAYS TO RELEASE TO  
CUSTOMER  
BUT IF I GO DRIVE FOR ALITTLE BIT IT WILL LOOSE ALL POWER  
ASSIST PARTS REPLACED:: NONE TECH QUESTION: ANY LIKE CONCERNS OR  
DAIG HELP TO TRACK DOWN THIS PROBLEM ALL CONNECTORS LOOK GOOD AND  
EVERYTHING WILL PASS THEN DRIVE AND IT WILL FAIL AGAIN WERE YOU  
ABLE TO VERIFY THE CONCERN? YES IS THERE AN APPROPRIATE PINPOINT  
TEST IN THE WSM FOR THIS CONCERN? YES WAS THE PINPOINT TEST  
FOLLOWED? YES

RECOMM 06/01/2011 03:28PM BRANDON WRIGHT MSS - FCSD - TECH SVC HOTLINE  
HOWARD, IF YOU HAVE NOT DONE SO ALREADY, REFER TO THE ONLINE  
WORKSHOP  
MANUAL SECTION 211-00 AND ENTER INTERACTIVE DIAGNOSTICS AND PERFORM  
DIAGNOSTIC ROUTINE B TO DIAGNOSE DTC C200D. PLEASE REVIEW DIAGNOSTIC  
ROUTINE I ALSO TO VERIFY IF IT CORRESPONDS WITH THE PRESENT CONCERN.  
IF FURTHER ASSISTANCE IS REQUIRED, PLEASE UPDATE THE FORM WITH YOUR  
LATEST RESULTS.

---

REDACTED FOR RELEVANCE

REDACTED FOR RELEVANCE

---

**From:** Anderson, Eric (H.)  
**Sent:** Monday, April 04, 2011 6:07 PM  
**To:** Jackson, Bradley (B.G.); Sridhara, Raghu (R.); Napoli, Laura (L.)  
**Subject:** RE: 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

What would it take to reverse the connector? The female side would become male and we could use pogo test pins like  
**REDACTED** How much would this design and tooling change cost? Is it worth it?

---

**From:** Jackson, Bradley (B.G.)  
**Sent:** Monday, April 04, 2011 3:52 PM  
**To:** Estes, Eric (E.E.); Janiunas, Vince (V.J.); Buelow, Steve (S.E.); Anderson, Eric (H.); 'James Rucker'  
**Cc:** Napoli, Laura (L.); Sridhara, Raghu (R.)  
**Subject:** RE: 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

**REDACTED FOR RELEVANCE**

Brad

---

**From:** Estes, Eric (E.E.)  
**Sent:** Monday, April 04, 2011 3:42 PM  
**To:** Janiunas, Vince (V.J.); Jackson, Bradley (B.G.); Buelow, Steve (S.E.); Anderson, Eric (H.); 'James Rucker'  
**Cc:** Napoli, Laura (L.)  
**Subject:** RE: 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

**REDACTED FOR RELEVANCE**

<b>Report# :</b>	BC5EH004 NHL	<b>Received:</b>	03/31/2011
<b>CCRG/EPRC:</b>		<b>Reviewed Status:</b>	<b>Date:</b>
<b>Vehicle:</b>	2011,EXPLORER 4X2 (U502),4 DOOR ,MP,1FMHK7F86BG [REDACTED]	<b>Build Date:</b>	03/02/2011
<b>Odometer :</b>	33 M	<b>Engine:</b>	3.5L CYCLO
<b>Transmission:</b>	6F55	<b>Axle:</b>	<b>Calibration:</b>
<b>Dealer:</b>	USA 02561 Sewell Ford, Inc.	<b>A/C:</b>	YES
		<b>Phone#:</b>	(432) 498- 0421

**City:** Odessa **State:** Texas **Country :** USA

**Originator:** STEFAN DROUI

**Symptom:** 3 03 1 50 CHASS.,STRG/HANDLING ,FUNCTION,HIGH EFFORT

**Status:**

**VFG:** V87 STEERING

**Additional Symptom:** LOSS OF ASSIST

**Fix:** **Causal Component :** --

**Condition Code:**

**Hotliner:** IWRIGH24

**Phone:** 313 317-4284

**Regn Cd:** C1 Dallas

**Engineering:**

**Phone:**

**TAR:**

**Dlr Contact:** STEFAN DROUI

**Phone:** 432 432-3320

**Title Cde:** T

**DTCs:**

KOEO:C1B00:29 C1B00:41 U0131

KOEC:

KOER:

**Comments**

:

**REPAIR** 03/31/2011 03:28PM IAN WRIGHT MSS - FCSD - TECH SVC HOTLINE  
WEB FORM DATA - CONCERN: LOST ALL POWER STEERING ,TOWED IN,POWER STEERING NOW. ADVANCE TRACK LIGHT ON ABS LIGHT ON DIAGNOSTICS: IDS TEST,MONITERED PIDS STEERING ANGLE PI WAS 49150.95. INSPECTED CONNECTIONS ON EPAS,ABS MODULE,SJB,BJB ALL OK,INSPECTED GRONDS PARTS REPLACED:: NO PARTS REPLACED TECH QUESTION: POWER STEERING LOCKED,ADVANCED TRACK LIGHT ON,SOMETIMES STEERING FUNCTIONS,OTHER TIMES IT DOESNT,CANT COMMUNICATE WITH PSCM AT TIMES,OTHER TIMES CAN. CODES C1B00:29-68 AND C1B00:41-68. CANNOT FIND CORRECT PIN POINT TEST. I FEEL LIKE IT IS THE PSCM,EPAS RAC-N-PINION. DO HAVE ANY REPAIR IDEAS NOT SURE WHERE TO GO.

**RECOMM** 03/31/2011 03:28PM IAN WRIGHT MSS - FCSD - TECH SVC HOTLINE

STEFAN, THE READING OF THE STEERING ANGLE SENSOR IS NORMAL. THE STEERING ANGLE SENSOR LEARNS A ZERO POINT AFTER DRIVING STRAIGHT. REFER TO <>

HREF='HTTP://WWW.VREP.FORDTECHSERVICE.DEALERCONNECTION.COM/VDIRS/SSM/SSM.ASP?SSM=21737' TARGET='\_BLANK'>SSM 21737 TO ADDRESS THE FAULTS PRESENT. SSM 21737 CODES C1B00, U0131, U0100, U0001, U0121, AND/OR U0151- CLEAR CODES AND WIGGLE TEST CONNECTER C139. IFCODES RETURN, BYPASS C139 FOR CIRCUITS VDB04 AND VDB05 USING THE SOLDER AND SHRINK TUBING METHOD FOUND IN SECTION 5 OF THE WIRING DIAGRAMS.

---

*Eric J Estes*

TRW EPAS Steering Systems  
Quality Specialist  
Hotline ph# 313-317-9358  
Cell ph# 734-560-3493

---

---

**From:** Estes, Eric (E.E.)  
**Sent:** Friday, April 01, 2011 12:52 PM  
**To:** Janiunas, Vince (V.J.); Jackson, Bradley (B.G.); Buelow, Steve (S.E.)  
**Subject:** FW: 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

FYI- 2011 U502 BJB poor connection at C1617A causing no assist and no communication to PSCM. New issue first one at this time. See note below

Vince I did add the comments to the CQIS report.

*Eric J Estes*

TRW EPAS Steering Systems  
Quality Specialist  
Hotline ph# 313-317-9358  
Cell ph# 734-560-3493

---

**From:** Napoli, Laura (L.)  
**Sent:** Friday, April 01, 2011 11:09 AM  
**To:** Estes, Eric (E.E.); Anderson, Eric (H.); Mrozek, Robert (R.M.)  
**Cc:** 'James Rucker'  
**Subject:** RE: 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

Thanks Eric. Too bad we didn't catch them before they changed it. I'm working with ABS service manual updates now. Not sure what direction those guys have since the ABS service manual isn't posted in our system yet.

---

**From:** Estes, Eric (E.E.)  
**Sent:** Friday, April 01, 2011 11:07 AM

To: Napoli, Laura (L.); Anderson, Eric (H.); Mrozek, Robert (R.M.)

Cc: James Rucker

Subject: RE: 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition


This gear at Capital Ford below has no communication the tech already replaced the gear and it did not fix the issue. Tech did load test the power & ground at the 2-pin and had 12volts, not sure if he performed that properly like the hotline suggested. tech found a poor connection to the 100amp fuse in the high current BJB C1617A pin 1(see below). Tech told me he thought it was corroded but it was more burn't like it was arcing and had some greenish color to the terminal. tech cleaned and tighten the blade of the terminal to fix this no communication issue.

Connector Viewer - 2011 Explorer - C1617A - Windows Internet Explorer

Back Forward C1617A

Connector:	Description	Color	Harness	Base Part #	Service Pi
C1617A	HIGH CURRENT BATTERY JUNCTION BOX (BJB)		14B060	part# N/A	Not Availa

Pin	Circuit	Gauge	Circuit Function
1	SBF05 (GY-RD)	08	FUSE - E (HIGH CURRENT BATTERY JUNCTION BOX)



The diagram shows a rectangular high current battery junction box (BJB) with a handle on top. A terminal labeled '1' is shown on the right side of the box. The terminal is connected to a wire that runs through a fuse holder. The fuse holder is labeled '1' and is connected to a circuit labeled 'SBF05 (GY-RD)'. The gauge is '08'. The circuit function is 'FUSE - E (HIGH CURRENT BATTERY JUNCTION BOX)'.

Eric

---

**From:** Napoli, Laura (L.)  
**Sent:** Friday, April 01, 2011 9:34 AM  
**To:** Estes, Eric (E.E.); Anderson, Eric (H.)  
**Subject:** FW: 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

2 wiring issues below causing loss of assist. Did either of you talk to these dealers already? If not, I'll call to make sure they don't pull the gears. Please let me know.

---

**From:** SBUELOW [mailto:SBUELOW]  
**Sent:** Friday, April 01, 2011 4:47 AM  
**To:** LNAPOLI  
**Subject:** 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

<b>Report# :</b>	BC5AL007 NHL	<b>Received:</b>	03/31/2011
<b>CCRG/EPRC:</b>		<b>Reviewed Status:</b>	<b>Date:</b>
<b>Vehicle:</b>	2011,EXPLORER 4X4 (U502),4 DOOR ,MP,1FMHK8F82BG [REDACTED]	<b>Build Date:</b>	02/23/2011
<b>Odometer :</b>	13 M	<b>Engine:</b>	3.5L CYCLO
<b>Transmission:</b>	6F55	<b>Axle:</b>	<b>Calibration:</b> BUB1ST0A
<b>Dealer:</b>	USA 00978 Capital Ford, Inc.	<b>Phone#:</b>	(919) 790- 4700
<b>City:</b>	Raleigh	<b>State:</b>	North Caroli
<b>Originator:</b>	RYAN WALLACE	<b>Country :</b>	USA
<b>Symptom:</b>	3 03 1 50 CHASS.,STRG/HANDLING ,FUNCTION,HIGH EFFORT		
<b>Status:</b>			
<b>VFG:</b>	V87 STEERING		
<b>Additional Symptom:</b>	NO POWER STEERING ASSIST		
<b>Fix:</b>	<b>Causal Component :</b>	--	
<b>Condition Code:</b>			

<b>Hotliner:</b> WHOUST13	<b>Phone:</b> 313 317-7044	<b>Regn Cd:</b> S2 Charlotte
<b>Engineering:</b>	<b>Phone:</b>	<b>TAR:</b>
<b>Dlr Contact:</b> RYAN WALLACE	<b>Phone:</b> 000 000-0000	<b>Title Cde:</b> T

**DTCs:**  
**KOEO:**

KOEC:

KOER:

**Comments**

:

**REPAIR** 03/31/2011 12:22PM WILLIE HOUSTON MSS - FCSD - TECH SVC HOTLINE  
WEB FORM DATA - CONCERN: POWER STEERING INOP DIAGNOSTICS: NETWORK  
TEST NO COMMUNICATION WITH PSCM, PINPOINT TEST AC1-12VOLTS AT C1463A  
PIN 3, PINPOINT AC2- .2 OHMS C1463B PIN2, PINPOINT TEST AC3- C1463A  
PIN 1 TO DLC PIN6 1.2 OHMS, C1463A PIN 2 TO DLC PIN14 1 OHM, PINPOINT  
TEST AC4 NO PUSHED OUT PINS OR CORROSION OR BENT OR DAMAGED  
PINS PARTS REPLACED:: STEERING GEAR TECH QUESTION: ANY KNOWN  
PROBLEMS WITH REPROGRAM OR COMMUNICATION WITH THE PSCM, ANY  
OTHER  
PINPOINT TEST? WERE YOU ABLE TO VERIFY THE CONCERN? YES IS  
THERE AN APPROPRIATE PINPOINT TEST IN THE WSM FOR THIS CONCERN?  
YES WAS THE PINPOINT TEST FOLLOWED? YES

**RECOMM** 03/31/2011 12:22PM WILLIE HOUSTON MSS - FCSD - TECH SVC HOTLINE  
RYAN, THE EPAS SYSTEM THAT THIS VEHICLE HAS IS TOTALLY SELF  
CONTAINED. THE GEAR REQUIRES POWER AND GROUND AND NETWORK  
CIRCUITS FOR  
COMMUNICATION. IF THE EPAS GEAR HAS BEEN REPLACED, AND THERE IS NO  
ASSIST OR COMMUNICATION WITH THE MODULE, LOAD TEST THE POWERS AND  
GROUNDS TO THE EPAS USING A HEADLAMP BULB TO VERIFY THAT THEY ARE  
CAPABLE OF CARRYING SUFFICIENT AMPERAGE AND PERFORM WIGGLE TESTS  
DURING THIS LOAD TEST. IF OKAY, VERIFY THAT THE NETWORK VOLTAGES AT  
THE PSCM CONNECTOR CORRESPOND WITH THE VOLTAGES AT PINS 6 AND 14 OF  
THE DLC WITH THE VEHICLE IN A KOEO STATE. CLOSELY INSPECT FOR  
LOOSE/DAMAGE OR OTHER PINFIT ISSUES AT THE PSCM AND BJB. REFERENCE  
PAGE 43-1 OF THE ONLINE EVTMM FOR CIRCUIT DETAILS.

---

**Attachments : 0**

<b>Report# :</b>	BC5EH004 NHL	<b>Received:</b>	03/31/2011
<b>CCRG/EPRC:</b>		<b>Date:</b>	
<b>Vehicle:</b>	2011,EXPLORER 4X2 (U502),4 DOOR ,MP,1FMHK7F86BG [REDACTED]	<b>Build Date:</b>	03/02/2011
<b>Odometer :</b>	33 M	<b>Engine:</b>	3.5L
		<b>Calibration:</b>	



CYCLO

**Transmission:** 6F55                      **Axle:**    **A/C:** YES  
**Dealer:** USA 02561 Sewell Ford, Inc.    **Phone#:** (432) 498-0421  
**City:** Odessa                      **State:** Texas                      **Country :** USA  
**Originator:** STEFAN DROUI  
**Symptom:** 3 03 1 50 CHASS.,STRG/HANDLING ,FUNCTION,HIGH EFFORT  
**Status:**  
**VFG:** V87 STEERING  
**Additional Symptom:** LOSS OF ASSIST  
**Fix:**                      **Causal Component :** --  
**Condition Code:**

**Hotliner:** IWRIGH24                      **Phone:** 313 317-4284                      **Regn Cd:** C1 Dallas  
**Engineering:**    **Phone:**    **TAR:**  
**Dlr Contact:** STEFAN DROUI                      **Phone:** 432 432-3320                      **Title Cde:** T

**DTCs:**

KOEO:C1B00:29 C1B00:41 U0131  
KOEC:  
KOER:

**Comments**

:

**REPAIR** 03/31/2011 03:28PM IAN WRIGHT MSS - FCSD - TECH SVC HOTLINE  
WEB FORM DATA - CONCERN: LOST ALL POWER STEERING ,TOWED IN,POWER STEERING NOW. ADVANCE TRACK LIGHT ON ABS LIGHT ON DIAGNOSTICS: IDS TEST,MONITERED PIDS STEERING ANGLE PI WAS 49150.95. INSPECTED CONNECTIONS ON EPAS,ABS MODULE,SJB,BJB ALL OK,INSPECTED GRONDS PARTS REPLACED:: NO PARTS REPLACED TECH QUESTION: POWER STEERING LOCKED,ADVANCED TRACK LIGHT ON,SOMETIMES STEERING FUNCTIONS,OTHER TIMES IT DOESNT,CANT COMMUNICATE WITH PSCM AT TIMES,OTHER TIMES CAN. CODES C1B00:29-68 AND C1B00:41-68. CANNOT FIND CORRECT PIN POINT TEST. I FEEL LIKE IT IS THE PSCM,EPAS RAC-N-PINION. DO HAVE ANY REPAIR IDEAS NOT SURE WHERE TO GO.

**RECOMM** 03/31/2011 03:28PM IAN WRIGHT MSS - FCSD - TECH SVC HOTLINE

STEFAN, THE READING OF THE STEERING ANGLE SENSOR IS NORMAL. THE STEERING ANGLE SENSOR LEARNS A ZERO POINT AFTER DRIVING STRAIGHT. REFER TO <>

HREF='HTTP://WWW.VREP.FORDTECHSERVICE.DEALERCONNECTION.COM/VDIRS/SSM/SM.ASP?SSM=21737' TARGET='\_BLANK'>SSM 21737 TO ADDRESS THE FAULTS PRESENT. SSM 21737 CODES C1B00, U0131, U0100, U0001, U0121, AND/OR

U0151- CLEAR CODES AND WIGGLE TEST CONNECTER C139. IFCODES RETURN,  
BYPASS C139 FOR CIRCUITS VDB04 AND VDB05 USING THE SOLDER AND SHRINK  
TUBING METHOD FOUND IN SECTION 5 OF THE WIRING DIAGRAMS.

---

---

**From:** Estes, Eric (E.E.)  
**Sent:** Friday, April 01, 2011 11:19 AM  
**To:** Mrozek, Robert (R.M.); Napoli, Laura (L.); Anderson, Eric (H.)  
**Cc:** 'James Rucker'  
**Subject:** RE: 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

the load test is not suggested in the manual only a voltage check of 12v, so we cannot charge the dealer back but the wiring connector should be the causal repair not the steering gear so we should not get nicked on warranty.

Eric

---

**From:** Mrozek, Robert (R.M.)  
**Sent:** Friday, April 01, 2011 11:15 AM  
**To:** Napoli, Laura (L.); Estes, Eric (E.E.); Anderson, Eric (H.)  
**Cc:** 'James Rucker'  
**Subject:** RE: 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

Did the dealer follow the diagnostics? Can we charge them back on this claim?

*Rob Mrozek*

Electric Power Steering Supervisor  
CD3/D3/D4/U502/Police/Limo EPAS Programs +  
Active Front Steering Applications Engineering  
Ford Motor Company  
Phone: (313) 805-5947  
e-mail: rmrozek@ford.com

---

**From:** Napoli, Laura (L.)  
**Sent:** Friday, April 01, 2011 11:09 AM  
**To:** Estes, Eric (E.E.); Anderson, Eric (H.); Mrozek, Robert (R.M.)  
**Cc:** 'James Rucker'  
**Subject:** RE: 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

Thanks Eric. Too bad we didn't catch them before they changed it. I'm working with ABS service manual updates now. Not sure what direction those guys have since the ABS service manual isn't posted in our system yet.

---

**From:** Estes, Eric (E.E.)  
**Sent:** Friday, April 01, 2011 11:07 AM  
**To:** Napoli, Laura (L.); Anderson, Eric (H.); Mrozek, Robert (R.M.)  
**Cc:** James Rucker  
**Subject:** RE: 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

This gear at Capital Ford below has no communication the tech already replaced the gear and it did not fix the issue. Tech did load test the power & ground at the 2-pin and had 12volts, not sure if he performed that properly like the hotline suggested. tech found a poor connection to the 100amp fuse in the high current BJB C1617A pin 1(see below). Tech told me he thought it was corroded but it was more burn't like it was arcing and had some greenish color to the terminal. tech cleaned and tighten the blade of the terminal to fix this no communication issue.


Connector Viewer - 2011 Explorer - C1617A - Windows Internet Explorer

Back Forward C1617A

<b>Connector:</b> <b>C1617A</b>	<b>Description</b> HIGH CURRENT BATTERY JUNCTION BOX (BJB)	<b>Color</b>	<b>Harness</b> 14B060	<b>Base Part #</b> part# N/A	<b>Service Pi</b> Not Availa
------------------------------------	---	--------------	--------------------------	---------------------------------	---------------------------------

Pin	Circuit	Gauge	Circuit Function
1	SBF05 (GY- RD)	08	FUSE - E (HIGH CURRENT BATTERY JUNCTION BOX)

The diagram shows a rectangular high current battery junction box (BJB) with a handle on top. A terminal labeled '1' is shown on the right side of the box. The terminal is a blade-style terminal that fits into a socket on the box. The box has a cutout on the left side, possibly for a fuse or another terminal.

---

**From:** Napoli, Laura (L.)  
**Sent:** Friday, April 01, 2011 9:34 AM  
**To:** Estes, Eric (E.E.); Anderson, Eric (H.)  
**Subject:** FW: 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

2 wiring issues below causing loss of assist. Did either of you talk to these dealers already? If not, I'll call to make sure they don't pull the gears. Please let me know.

---

**From:** SBUELOW [mailto:SBUELOW]  
**Sent:** Friday, April 01, 2011 4:47 AM  
**To:** LNAPOLI  
**Subject:** 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

**Report# :** BC5AL007 NHL  
**CCRG/EPRC:** **Reviewed Status:**  
**Vehicle:** 2011,EXPLORER 4X4 (U502),4 DOOR  
,MP,1FMHK8F82BG [REDACTED] **Build Date:** 02/23/2011  
**Odometer :** 13 M **Engine:** 3.5L  
CYCLO **Calibration:** BUB1ST0A  
**Transmission:** 6F55 **Axle:** **A/C:** YES  
**Dealer:** USA 00978 Capital Ford, Inc. **Phone#:** (919) 790-4700  
**City:** Raleigh **State:** North Caroli **Country :** USA  
**Originator:** RYAN WALLACE  
**Symptom:** 3 03 1 50 CHASS.,STRG/HANDLING ,FUNCTION,HIGH EFFORT  
**Status:**  
**VFG:** V87 STEERING  
**Additional Symptom:** NO POWER STEERING ASSIST  
**Fix:** **Causal Component :** --  
**Condition Code:**

**Hotliner:** WHOUST13 **Phone:** 313 317-7044 **Regn Cd:** S2 Charlotte  
**Engineering:** **Phone:** **TAR:**  
**Dlr Contact:** RYAN WALLACE **Phone:** 000 000-0000 **Title Cde:** T

**DTCs:**  
**KOEO:**  
**KOEC:**  
**KOER:**  
**Comments**

REPAIR 03/31/2011 12:22PM WILLIE HOUSTON MSS - FCSD - TECH SVC HOTLINE  
 WEB FORM DATA - CONCERN: POWER STEERING INOP DIAGNOSTICS: NETWORK  
 TEST NO COMMUNICATION WITH PSCM, PINPIONT TEST AC1-12VOLTS AT C1463A  
 PIN 3, PINPIONT AC2- .2 OHMS C1463B PIN2, PINPIONT TEST AC3- C1463A  
 PIN 1 TO DLC PIN6 1.2 OHMS, C1463A PIN 2 TO DLC PIN14 1 OHM, PINPIONT  
 TEST AC4 NO PUSHED OUT PINS OR CORROSION OR BENT OR DAMAGED  
 PINS PARTS REPLACED:: STEERING GEAR TECH QUESTION: ANY KNOWN  
 PROBLEMS WITH REPROGRAM OR COMMUNICATION WITH THE PSCM, ANY  
 OTHER  
 PINPIONT TEST? WERE YOU ABLE TO VERIFY THE CONCERN? YES IS  
 THERE AN APPROPRIATE PINPOINT TEST IN THE WSM FOR THIS CONCERN?  
 YES WAS THE PINPOINT TEST FOLLOWED? YES

RECOMM 03/31/2011 12:22PM WILLIE HOUSTON MSS - FCSD - TECH SVC HOTLINE  
 RYAN, THE EPAS SYSTEM THAT THIS VEHICLE HAS IS TOTALLY SELF  
 CONTAINED. THE GEAR REQUIRES POWER AND GROUND AND NETWORK  
 CIRCUITS FOR  
 COMMUNICATION. IF THE EPAS GEAR HAS BEEN REPLACED, AND THERE IS NO  
 ASSIST OR COMMUNICATION WITH THE MODULE, LOAD TEST THE POWERS AND  
 GROUNDS TO THE EPAS USING A HEADLAMP BULB TO VERIFY THAT THEY ARE  
 CAPABLE OF CARRYING SUFFICIENT AMPERAGE AND PERFORM WIGGLE TESTS  
 DURING THIS LOAD TEST. IF OKAY, VERIFY THAT THE NETWORK VOLTAGES AT  
 THE PSCM CONNECTOR CORRESPOND WITH THE VOLTAGES AT PINS 6 AND 14 OF  
 THE DLC WITH THE VEHICLE IN A KOEO STATE. CLOSELY INSPECT FOR  
 LOOSE/DAMAGE OR OTHER PINFIT ISSUES AT THE PSCM AND BJB. REFERENCE  
 PAGE 43-1 OF THE ONLINE EVTMM FOR CIRCUIT DETAILS.

Attachments : 0

<b>Report# :</b>	BC5EH004 NHL	<b>Received:</b>	03/31/2011
<b>CCRG/EPRC:</b>		<b>Date:</b>	
<b>Vehicle:</b>	2011,EXPLORER 4X2 (U502),4 DOOR ,MP,1FMHK7F86BG [REDACTED]	<b>Build Date:</b>	03/02/2011
<b>Odometer :</b>	33 M	<b>Engine:</b>	3.5L CYCLO
<b>Transmission:</b>	6F55	<b>Axle:</b>	
<b>Dealer:</b>	USA 02561 Sewell Ford, Inc.	<b>Calibration:</b>	
		<b>A/C:</b>	YES
		<b>Phone#:</b>	(432) 498-

City: Odessa State: Texas Country : USA 0421  
Originator: STEFAN DROUI  
Symptom: 3 03 1 50 CHASS.,STRG/HANDLING ,FUNCTION,HIGH EFFORT  
Status:  
VFG: V87 STEERING  
Additional Symptom: LOSS OF ASSIST  
Fix: Causal Component : --  
Condition Code:

Hotliner: IWRIGH24 Phone: 313 317-4284 Regn Cd: C1 Dallas  
Engineering: Phone: TAR:  
Dlr Contact: STEFAN DROUI Phone: 432 432-3320 Title Cde: T

**DTCs:**

KOEO:C1B00:29 C1B00:41 U0131  
KOEC:  
KOER:

**Comments**

:

REPAIR 03/31/2011 03:28PM IAN WRIGHT MSS - FCSD - TECH SVC HOTLINE  
WEB FORM DATA - CONCERN: LOST ALL POWER STEERING ,TOWED IN,POWER  
STEERING NOW. ADVANCE TRACK LIGHT ON ABS LIGHT ON DIAGNOSTICS: IDS  
TEST,MONITERED PIDS STEERING ANGLE PI WAS 49150.95. INSPECTED  
CONNECTIONS ON EPAS,ABS MODULE,SJB,BJB ALL OK,INSPECTED GRONDS  
PARTS REPLACED:: NO PARTS REPLACED TECH QUESTION: POWER  
STEERING LOCKED,ADVANCED TRACK LIGHT ON,SOMETIMES STEERING  
FUNCTIONS,OTHER TIMES IT DOESNT,CANT COMMUNICATE WITH PSCM AT  
TIMES,OTHER TIMES CAN. CODES C1B00:29-68 AND C1B00:41-68. CANNOT FIND  
CORRECT PIN POINT TEST. I FEEL LIKE IT IS THE PSCM,EPAS RAC-N-PINION.  
DO HAVE ANY REPAIR IDEAS NOT SURE WHERE TO GO.

**RECOMM 03/31/2011 03:28PM IAN WRIGHT MSS - FCSD - TECH SVC HOTLINE**

STEFAN, THE READING OF THE STEERING ANGLE SENSOR IS NORMAL. THE  
STEERING ANGLE SENSOR LEARNS A ZERO POINT AFTER DRIVING STRAIGHT.  
REFER TO <>

HREF='HTTP://WWW.VREP.FORDTECHSERVICE.DEALERCONNECTION.COM/VDIRS/SSM/  
SM.ASP?SSM=21737' TARGET='\_BLANK'>SSM 21737 TO ADDRESS THE FAULTS  
PRESENT. SSM 21737 CODES C1B00, U0131, U0100, U0001, U0121, AND/OR  
U0151- CLEAR CODES AND WIGGLE TEST CONNECTER C139. IFCODES RETURN,  
BYPASS C139 FOR CIRCUITS VDB04 AND VDB05 USING THE SOLDER AND SHRINK  
TUBING METHOD FOUND IN SECTION 5 OF THE WIRING DIAGRAMS.





---

**From:** Napoli, Laura (L.)  
**Sent:** Thursday, March 24, 2011 10:11 AM  
**To:** Jackson, Bradley (B.G.); Logli, Michael (M.A.); Issa, Ibrahim (I.M.); Estes, Eric (E.E.)  
**Cc:** Anderson, Eric (H.); Mrozek, Robert (R.M.); Docimo, Tony (A.F.)  
**Subject:** RE: 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

The question would be whether the veh has an SCCM or not. If it's not Autopark, it has no SCCM, so then I'd direct them to the pinout/wiggle test. The only codes they show are referring to the relative steering angle. There's no reason that you'd lose assist for those DTC's.

Eric Estes, can you get snapshot data from the dealer on the C1B00?

---

**From:** Jackson, Bradley (B.G.)  
**Sent:** Thursday, March 24, 2011 7:49 AM  
**To:** Logli, Michael (M.A.); Issa, Ibrahim (I.M.)  
**Cc:** Anderson, Eric (H.); Napoli, Laura (L.); Mrozek, Robert (R.M.); Docimo, Tony (A.F.)  
**Subject:** FW: 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

Mike / Ibrahim, i am out of the office this morning. Can you contact the dealer and see if this is SCCM related before they swap the gear?

Brad

---

**From:** SBUELOW [mailto:SBUELOW]  
**Sent:** Thursday, March 24, 2011 2:37 AM  
**To:** BJACKSON  
**Subject:** 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

This email contains 3 report summary(s).

**Attachments :** 0

<b>Report# :</b>	BCWFW001 NHL	<b>Received:</b>	03/23/2011
<b>CCRG/EPRC:</b>	<b>Reviewed Status:</b>	<b>Date:</b>	
<b>Vehicle:</b>	2011,EXPLORER 4X4 (U502),4 DOOR ,MP,1FMHK8D89BG [REDACTED]	<b>Build Date:</b>	02/15/2011
<b>Odometer :</b>	611 M	<b>Engine:</b>	3.5L CYCLO
<b>Transmission:</b>	6F50	<b>Axle:</b>	<b>Calibration:</b> BUB1SN0A
<b>Dealer:</b>	USA 07737 Serramonte Ford, Inc.	<b>Phone#:</b>	(650) 301- 7065
<b>City:</b>	Colma	<b>State:</b>	California
<b>Originator:</b>	OMAR NAVARRO	<b>Country :</b>	USA
<b>Symptom:</b>	3 03 0 00 CHASS.,STRG/HANDLING ,OTHER-CODE NA,OTHER-CODE NA		

**Status:**

**VFG:** V89 RIDE & HANDLING

**Additional Symptom:** LOSS OF STEERING ASSIST

**Fix:** Causal Component : --

**Condition Code:**

**Hotliner:** MHINDERE                      **Phone:** 313 337-9292                      **Regn Cd:** W2 San Francisco

**Engineering:**    **Phone:**    **TAR:**

**Dlr Contact:** OMAR NAVARRO    **Phone:** 650 577-0577    **Title Cde:** T

**DTCs:**

KOEO:

KOEC:C1B00 U0131

KOER:

**Comments**

:

REPAIR 03/23/2011 06:19PM MICHAEL HINDERER MSS - FCSD - TECH SVC HOTLINE  
WEB FORM DATA - CONCERN: NO POWER STEERING ASSIST DIAGNOSTICS:  
INSPECTED THE STEERING GEAR AND CONNECTOR AND FOUND OK. RAN THE  
SELF  
TEST AND THE POWER STEERING MODULE PASSED. THE ABS MODULE HAD  
CODES  
C1B00 AND U0131. FOUND THE STEERING ASSIT STARTED WORKING  
MOMENTARELY  
AFTER THE SELF TES AND THE STOPED WORKING. MONITORED THE STEERING  
ANGLE PID AND FOUND IT DOES NOT MATCH THE ACTUAL STEERING ANGLE.  
PARTS REPLACED:: NONE TECH QUESTION: DOES THE STEERING GEAR  
ASSEMBLY NEED TO HAVE APPROVAL FOR REPLACEMENT WERE YOU ABLE TO  
VERIFY THE CONCERN? YES IS THERE AN APPROPRIATE PINPOINT TEST IN  
THE WSM FOR THIS CONCERN? YES WAS THE PINPOINT TEST FOLLOWED? YES

**RECOMM 03/23/2011 06:19PM MICHAEL HINDERER MSS - FCSD - TECH SVC HOTLINE**

TO BETTER ASSIST YOU ON THIS WARRANTY RELATED QUESTION, THE  
TECHNICAL  
SERVICE HOTLINE RECOMMENDS THAT YOU REFER TO THE DEALERSHIP  
WARRANTY  
ADMINISTRATOR, THE WARRANTY AND POLICY MANUAL, OR YOU MAY  
CONTACT THE  
WARRANTY ASSISTANCE CENTER DIRECTLY AT 1-800-423-8851

---

**From:** Estes, Eric (E.E.)  
**Sent:** Thursday, March 03, 2011 1:48 PM  
**To:** Mrozek, Robert (R.M.); Napoli, Laura (L.); Pasquarella, Michael (M.S.)  
**Cc:** Anderson, Eric (H.); jason.johnson; Gregory Sheets; 'Greg Austin'; Sergio Alvarez; anthony.fleenor@trw.com  
**Subject:** RE: 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

Called the dealer tech and Ken is going to get more code/vehicle information, the code he pulled U0253 is not our code so he will re-check for any PSCM codes, does sound like a friction issue steering very hard to turn at all times, even on a hoist. Tech states he did not see any holes/slices in the boot. Also advised to check the PS message center for a PS message. TC lamp & TC active lamps on all the time and symptom never goes away and code(s) will not clear.

Will let you know as soon as the tech calls back.

Eric

---

**From:** Mrozek, Robert (R.M.)  
**Sent:** Thursday, March 03, 2011 9:07 AM  
**To:** Napoli, Laura (L.); Pasquarella, Michael (M.S.); Estes, Eric (E.E.)  
**Cc:** Anderson, Eric (H.); Mrozek, Robert (R.M.)  
**Subject:** FW: 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

Laura/Mike/Eric E -

See U502 call. Sounds like corrosion in the gear due to a leak somewhere. Please call the dealer to see if they can inspect corrosion in the gear by removing the boots and looking at the rack. It normally is a boot puncture the leads to this type of call. But if it is something else, we need to know asap. Also see if friction detection went off or not. The noise is a good customer indicator as well.

*Rob Mrozek*

Electric Power Steering Supervisor  
CD3/D3/D4/U502/Police/Limo EPAS Programs +  
Active Front Steering Applications Engineering  
Ford Motor Company  
Phone: (313) 805-5947  
e-mail: [rmrozek@ford.com](mailto:rmrozek@ford.com)

**Attachments :** 0

<b>Report# :</b>	BCBAW023 NHL	<b>Received:</b>	03/02/2011
<b>CCRG/EPRC:</b>	<b>Reviewed Status:</b>	<b>Date:</b>	
<b>Vehicle:</b>	2011,EXPLORER 4X4 (U502),4 DOOR ,MP,1FMHK8F86BG [REDACTED]	<b>Build Date:</b>	01/31/2011

**Odometer :** 18 M                      **Engine:** 3.5L CYCLO                      **Calibration:** BUB1ST0A  
**Transmission:** 6F55                      **Axle:**                      **A/C:** YES  
**Dealer:** USA 08398 Don Aadsen Ford                      **Phone#:** (406) 676-4400  
**City:** Ronan                      **State:** Montana                      **Country :** USA  
**Originator:** KEN LOZEAU  
**Symptom:** 3 03 1 50 CHASS.,STRG/HANDLING ,FUNCTION,HIGH EFFORT  
**Status:**  
**VFG:** V87 STEERING  
**Additional Symptom:** LACK OF ASSIST, GROWL NOISE  
**Fix:**                      **Causal Component :** --  
**Condition Code:**

**Hotliner:** TFUMEROL                      **Phone:** 000 317-9383                      **Regn Cd:** W5 Seattle  
**Engineering:**                      **Phone:**                      **TAR:**  
**Dlr Contact:** KEN LOZEAU                      **Phone:** 406 676-4420                      **Title Cde:** T

**DTCs:**  
 KOEO:U0253  
 KOEC:  
 KOER:

**Comments**

:  
**REPAIR** 03/02/2011 04:10PM TOM FUMEROLA MSS - FCSD - TECH SVC HOTLINE  
 WEB FORM DATA - CONCERN: STEERING ASSIST IS INOP, LOUD GROWLING NOISE  
 WHEN ATTEMPTING TO TURN THE STEERING WHEEL DIAGNOSTICS: VISUAL  
 INSPECTION IS OK, NO VISIBLE SIGNS OF CAUSE, GROWLING NOISE APPEARS TO  
 BE COMING FROM ELECTRIC MOTOR ON STEERING RACK. HOOKED UP IDS AND  
 RETRIEVED CONT CODE U0253, TRACTION CONTROL LIGHT IS ON PARTS  
 REPLACED:: NONE TECH QUESTION: ANY DIAG ASSISTANCE WOULD BE GREATLY  
 APPRECIATED, POWER STEERING WORKED NORMAL UNTIL IT WAS DRIVEN INTO  
 WASH BAY THEN QUIT WORKING WERE YOU ABLE TO VERIFY THE CONCERN?  
 YES IS THERE AN APPROPRIATE PINPOINT TEST IN THE WSM FOR THIS  
 CONCERN? NO WAS THE PINPOINT TEST FOLLOWED? NO  
**RECOMM** 03/02/2011 04:10PM TOM FUMEROLA MSS - FCSD - TECH SVC HOTLINE  
 KENNETH, IT IS RECOMMENDED TO PERFORM THE INTERACTIVE VEHICLE  
 DIAGNOSTICS AVAILABLE THROUGH THE ONLINE WORKSHOP MANUAL 211-00,  
 DTC  
 AND SYMPTOM CHART. THIS WILL AID IN DIAGNOSING THE SYSTEM. SINCE THE  
 MOTOR IS MAKING NOISE THERE MAY BE AN INTERNAL FAULT. SERVICE AS

NEEDED.

---

**From:** Napoli, Laura (L.)  
**Sent:** Tuesday, March 01, 2011 11:23 AM  
**To:** Mrozek, Robert (R.M.)  
**Subject:** RE: 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

We now have 2 gears that came from Warranty. They both show up in CQIS, so that's what CAP will see. There's a 3rd one out of NMPDC on a 2013 gear, but CAP won't see that one. But I think it only takes 2 for them to start yelling. And now we have 2.

---

**From:** Mrozek, Robert (R.M.)  
**Sent:** Tuesday, March 01, 2011 10:44 AM  
**To:** Napoli, Laura (L.)  
**Subject:** RE: 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

what do you mean by "2 out of CAP"?

*Rob Mrozek*

Electric Power Steering Supervisor  
CD3/D3/D4/U502/Police/Limo EPAS Programs +  
Active Front Steering Applications Engineering  
Ford Motor Company  
Phone: (313) 805-5947  
e-mail: rmrozek@ford.com

---

**From:** Napoli, Laura (L.)  
**Sent:** Tuesday, March 01, 2011 10:38 AM  
**To:** Estes, Eric (E.E.)  
**Cc:** Mrozek, Robert (R.M.)  
**Subject:** RE: 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

Thanks for jumping on this one. I've alerted the 26mile team (since I'm here) to make them aware that this now means we have 2 out of CAP and I expect lots of attention from PVT.

Can we get the EPP number from the dealer off the sticker so we can trace the IPA build date quickly? Just ask him to read you the first number below the barcode on the EPP cover sticker.

What's UR0004 from Virginia? Is that the C69 with the disconnected power connector?

---

**From:** Estes, Eric (E.E.)  
**Sent:** Tuesday, March 01, 2011 9:00 AM  
**To:** Napoli, Laura (L.)

**Cc:** Mrozek, Robert (R.M.)

**Subject:** RE: 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

Already put in a hot process request yesterday for this gear, also still waiting on gear UR0004 to comeback from Virginia. That gear in Quebec did not have any snap shot data from interactive diagnostic's because dealer cleared the codes prior to diagnostic's but it does list a U3000-96 code in history data, so as soon as FCSD gets these auto park gears available we should get some gears back for analysis.

Eric

---

**From:** Napoli, Laura (L.)

**Sent:** Tuesday, March 01, 2011 8:19 AM

**To:** Estes, Eric (E.E.)

**Cc:** Mrozek, Robert (R.M.)

**Subject:** FW: 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

See TS loss of assist claim. It's in French, but please see if you can call the dealer and get this gear back quickly. Or at least let's get the EPP number from them so we can get the info to Rogersville and understand IPA build date.

---

**From:** SBUELOW [mailto:SBUELOW]

**Sent:** Tuesday, March 01, 2011 3:36 AM

**To:** LNAPOLI

**Subject:** 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

This email contains 10 report summary(s).

REDACTED FOR RELEVANCE

REDACTED FOR RELEVANCE



REDACTED FOR RELEVANCE

REDACTED FOR RELEVANCE

REDACTED FOR RELEVANCE

REDACTED FOR RELEVANCE

I/S

REDACTED FOR RELEVANCE

REDACTED FOR RELEVANCE

KOEO:  
KOEC:  
KOER:

**Comments**

: REDACTED FOR RELEVANCE

R

R

---

**Attachments : 0**

<b>Report# :</b>	BB2AO007 NHL	<b>Received:</b>	02/28/2011
<b>CCRG/EPRC:</b>		<b>Date:</b>	
<b>Vehicle:</b>	2011,EXPLORER 4X4 (U502),4 DOOR ,MP,1FMHK8F82BG [REDACTED]	<b>Build Date:</b>	11/30/2010
<b>Odometer :</b>	2,294 M	<b>Engine:</b>	3.5L CYCLO
<b>Transmission:</b>	6F55	<b>Axle:</b>	
<b>Dealer:</b>	CAN B2515 Jacques Olivier Ford Inc.	<b>Calibration:</b>	BUB1ST0A
<b>City:</b>	St-Hubert	<b>A/C:</b>	YES
<b>Originator:</b>	VINCENT ROY	<b>Phone#:</b>	(450) 445- 3673
<b>Symptom:</b>	3 03 1 50 CHASS.,STRG/HANDLING ,FUNCTION,HIGH EFFORT		
<b>Status:</b>			
<b>VFG:</b>	V87 STEERING	<b>Country :</b>	CAN
<b>Additional Symptom:</b>	LACK OF ASSIST		
<b>Fix:</b>	<b>Causal Component :</b>		--

**Condition Code:**

**Hotliner:** MGIRARD1      **Phone:** 313 317-7064      **Regn Cd:** 02 02 FCSD REGION-CANADA

**Engineering:**      **Phone:**      **TAR:**

**Dlr Contact:** VINCENT ROY      **Phone:** 514 927-6404      **Title Cde:** T

**DTCs:**

KOEO:

KOEC:C200B C200C

KOER:

**Comments**

:

**REPAIR**    02/28/2011 11:34AM MARIO GIRARD MSS - FCSD - TECH SVC HOTLINE  
WEB FORM DATA - CONCERN: PAS DASSISTANCE  
SERVODIRECTION. DIAGNOSTICS: CMDTC C200B ET C200C PRESENT EFFACE  
CODES.LES CODES NE REVIENNENT PAS MAIS LE POWER STEERING NE  
FONCTIONNE  
PAS.VERIFIE FUSES ET CONNEXIONS OK.FAIT PINPOINT TESTS.VERIFIE EN PIDS  
LA POSITION DU VOLANT PID SW ANGLE EST TOUJOURS A 5553.5 DEGRES.NE  
PEUT POURSUIVRE LE DIAGNOSTIQUE PARCEQUE EFFACE CODES. PARTS  
REPLACED:: AUCUNE TECH QUESTION: Y A T IL DES SUGGESTIONS DE  
DIAGNOSTIQUE

**RECOMM** 02/28/2011 11:34AM MARIO GIRARD MSS - FCSD - TECH SVC HOTLINE  
VINCENT LE PROBLME EST INTERNE AU SYSTM DE DIRECTION , REMPLACE LE  
EPAS ASSEMBLE

---

REDACTED FOR RELEVANCE

REDACTED FOR RELEVANCE

**Attachments : 0**



REDACTED FOR RELEVANCE

REDACTED FOR RELEVANCE

**Attachments : 0**

REDACTED FOR RELEVANCE

REDACTED FOR RELEVANCE

---

**From:** Anderson, Eric (H.)  
**Sent:** Wednesday, February 16, 2011 3:39 PM  
**To:** Napoli, Laura (L.); Snider, Tim (T.O.); Mrozek, Robert (R.M.)  
**Cc:** Estes, Eric (E.E.); Diez, Timothy (T.P.); Rossi, Roberto (R.A.)  
**Subject:** RE: 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

BGA17285 had all the classic pin fit issue codes: C1B00, U0131.

BGA17032 only had U3000:96

---

**From:** Napoli, Laura (L.)  
**Sent:** Wednesday, February 16, 2011 2:31 PM  
**To:** Snider, Tim (T.O.); Mrozek, Robert (R.M.)  
**Cc:** Estes, Eric (E.E.); Anderson, Eric (H.); Diez, Timothy (T.P.); Rossi, Roberto (R.A.)  
**Subject:** RE: 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

This has a C69 which means the gear is locked out and must be replaced due to at least 3 B level faults which I'm sure were caused by the loose connector.

Last one sounds like the pinout issue. Only code shown is the ABS lost comm with PSCM code. Need to know if there are more.

---

**From:** Snider, Tim (T.O.)  
**Sent:** Wednesday, February 16, 2011 3:19 PM  
**To:** Mrozek, Robert (R.M.)  
**Cc:** Estes, Eric (E.E.); Anderson, Eric (H.); Napoli, Laura (L.); Diez, Timothy (T.P.); Rossi, Roberto (R.A.)  
**Subject:** RE: 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

First one could be an issue besides the loose connector, and the third one could be a loose / damaged EPAS or ABS connector or loose / damaged EPAS or battery ground.

Regards,  
Tim Snider (tsnider1@ford.com)  
**CD3/C489 Steering Engineering**  
**Ford Motor Company**  
Cell 313-805-3201  
2B-L18 Product Development Center  
Dearborn, MI 48124 USA

---

**From:** Mrozek, Robert (R.M.)  
**Sent:** Tuesday, February 15, 2011 9:49 AM  
**To:** Snider, Tim (T.O.)  
**Subject:** FW: 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

Any thoughts?

*Rob Mrozek*

Electric Power Steering Supervisor  
CD3/D3/D4/U502/Police/Limo EPAS Programs +  
Active Front Steering Applications Engineering  
Ford Motor Company  
Phone: (313) 805-5947  
e-mail: rmrozek@ford.com

---

**From:** Jackson, Bradley (B.G.)  
**Sent:** Tuesday, February 15, 2011 7:59 AM  
**To:** Napoli, Laura (L.); Mrozek, Robert (R.M.); Rossi, Roberto (R.A.)  
**Cc:** Anderson, Eric (H.)  
**Subject:** FW: 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

Any clues about the first report from Maryland? If a loose connector was found and re-connected, any ideas on why there would still be no assist?

Also, have a look at the 3rd report from North Carolina.

Brad

This email contains 3 report summary(s).

<b>Report# :</b>	BBLAA025 NHL	<b>Received:</b>	02/12/2011
<b>CCRG/EPRC:</b>		<b>Date:</b>	
<b>Vehicle:</b>	2011,EXPLORER 4X4 (U502),4 DOOR ,MP,1FMHK8F8XBG [REDACTED]	<b>Build Date:</b>	01/20/2011
<b>Odometer :</b>	303 M	<b>Engine:</b>	3.5L CYCLO
<b>Transmission:</b>	6F55	<b>Axle:</b>	
<b>Dealer:</b>	USA 00089 Koons Ford of Annapolis, Inc.	<b>Calibration:</b>	BUB1ST0A
<b>City:</b>	Annapolis	<b>A/C:</b>	YES
<b>Originator:</b>	JAMES MORELAND	<b>Phone#:</b>	(410) 266- 3087
<b>Symptom:</b>	3 03 1 55 CHASS.,STRG/HANDLING ,FUNCTION,LOSS OF STRG	<b>Country :</b>	USA
<b>Status:</b>			
<b>VFG:</b>	V89 RIDE & HANDLING		
<b>Additional Symptom:</b>	U3000:96		

**Fix:** Causal Component : --

**Condition Code:**

**Hotliner:** CBISHO41                      **Phone:** 313 317-9359                      **Regn Cd:** N4 Washington

**Engineering:**                                      **Phone:**                                      **TAR:**

**Dlr Contact:** JAMES MORELAND                      **Phone:** 410 266-3087                      **Title Cde:** T

**DTCs:**

KOEO:U3000:96

KOEC:

KOER:

**Comments**

:

**REPAIR** 02/12/2011 01:58PM CHRIS BISHOP MSS - FCSD - TECH SVC HOTLINE  
WEB FORM DATA - CONCERN: NO POWER STEERING DIAGNOSTICS: SELF TEST  
VISUAL INSPECTION FOUND CONNECTOR ON GEAR DISCONNECTED PARTS  
REPLACED:: NONE TECH QUESTION: CODE U3000 96 LEADS TO REPLACEMENT  
OF EPAS GEAR W/NO PINPOINT TESTS IS THIS CORRECT, VEHICLE WAS DX TO  
OUR DEALER SAID P/S WENT OUT IN OUR PARKING LOT, TESTED AND FOUND  
CONNECTOR 1453A DISCONNECTED. PLUGGED BACK IN BUT NO P/S AND CODE  
AND  
MESSAGE CENTER WILL NOT CLEAR OUT. WERE YOU ABLE TO VERIFY THE  
CONCERN? YES IS THERE AN APPROPRIATE PINPOINT TEST IN THE WSM FOR  
THIS CONCERN? YES WAS THE PINPOINT TEST FOLLOWED? YES

**RECOMM** 02/12/2011 01:58PM CHRIS BISHOP MSS - FCSD - TECH SVC HOTLINE  
JAMES, YOU ARE CORRECT. IF THE U3000:96 IS PRESENT AS A HARD FAULT  
THEN STEERING GEAR REPLACEMENT IS REQUIRED. THIS CODE INDICATES THAT  
THE ELECTRONIC STEERING GEAR HAS EXPERIENCED AN INTERNAL FAULT.  
RECOMMEND REPLACING THE GEAR AS NEEDED THEN RETESTING FOR NORMAL  
OPERATION.

---

REDACTED FOR RELEVANCE

REDACTED FOR RELEVANCE

Attachments : 0

<b>Report# :</b>	BBND7002 NHL	<b>Received:</b>	02/14/2011
<b>CCRG/EPRC:</b>		<b>Date:</b>	
<b>Vehicle:</b>	2011,EXPLORER 4X2 (U502),4 DOOR ,MP,1FMHK7B86BG [REDACTED]	<b>Build Date:</b>	01/20/2011
<b>Odometer :</b>	519 M	<b>Engine:</b>	3.5L CYCLO
<b>Transmission:</b>	6F50	<b>Axle:</b>	
<b>Dealer:</b>	USA 09151 Huntersville Ford	<b>Calibration:</b>	BUB1NN0A
<b>City:</b>	Huntersville	<b>A/C:</b>	YES
		<b>Phone#:</b>	(704) 875- 6547
		<b>State:</b>	North
		<b>Country :</b>	USA



**Originator:** TIM BARRON  
**Symptom:** 3 03 1 50 CHASS.,STRG/HANDLING ,FUNCTION,HIGH EFFORT  
**Status:**  
**VFG:** V87 STEERING  
**Additional Symptom:** INTERMIT NO STR ASSIST  
**Fix:** **Causal Component :** --  
**Condition Code:**

**Hotliner:** JTAYL466                      **Phone:** 000 000-0000                      **Regn Cd:** S2 Charlotte  
**Engineering:**    **Phone:**    **TAR:**  
**Dlr Contact:** TIM BARRON                      **Phone:** 704 400-9384                      **Title Cde:** T

**DTCs:**  
 KOEO:U0131  
 KOEC:  
 KOER:

**Comments**  
 :

**REPAIR** 02/14/2011 04:13PM JASON TAYLOR MSS - FCSD - TECH SVC HOTLINE  
 THE CUSTOMER STATES THAT INTERMITTENTLY THERE IS NO STEERING ASSIST. THE TECH HAS ONLY BEEN ABLE TO DUPLICATE THIS CONCERN ONCE. THE TECH STATES THAT HE LET THE VEHICLE IDLE FOR TWENTY MINUTES IN HIS BAY AND WHEN HE RETURNED THE CONCERN WAS PRESENT. THE PSCM DOES FAIL THE NETWORK TEST. THERE ARE CODES U0131 IN THE ABS AND IC MODULES. WHEN THE VEHICLE CAME IN THERE WAS A CONTINUOUS CODE U3000 IN THE PSCM, BUT THAT CODE CLEARED AND DID NOT RETURN.

**RECOMM** 02/14/2011 04:13PM JASON TAYLOR MSS - FCSD - TECH SVC HOTLINE  
 TIM, SUGGEST INSPECTING THE VEHICLE FOR ANY AFTER MARKET EQUIPMENT. IF THERE IS ANY AFTER MARKET EQUIPMENT PRESENT THEN REMOVE IT FROM THE VEHICLE. IF THERE IS NO AFTER MARKET EQUIPMENT PRESENT AND THE PSCM IS NOT COMMUNICATING, THEN SUGGEST PERFORMING A LOAD TEST ON THE POWER AND GROUND TO THE PSCM. IF THE POWER AND GROUND PROVE OUT THEN CHECK THE COMMUNICATION CIRCUITS BETWEEN THE PSCM AND DLC FOR ANY OPEN OR HIGH RESISTANCE ISSUES. INSPECT THE PIN FITS AT THE PSCM FOR ANY LOOSE OR DAMAGED PINS.



---

**From:** Anderson, Eric (H.)  
**Sent:** Monday, January 31, 2011 2:09 PM  
**To:** Napoli, Laura (L.); Jackson, Bradley (B.G.); Mrozek, Robert (R.M.); Estes, Eric (E.E.); 'Michael Fontana'; 'Robert Kostadina'; 'Hemang Mehta'; 'Nick turovich'  
**Subject:** RE: 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

Hi All:

CAP needs to better understand this inoperative power steering claim from West Virginia. What is a U3000-96 code and how does it occur? A fishbone explaining the failure parameters would be helpful.

Thanks,

Eric

---

**From:** Napoli, Laura (L.)  
**Sent:** Monday, January 31, 2011 7:57 AM  
**To:** Anderson, Eric (H.); Jackson, Bradley (B.G.); Mrozek, Robert (R.M.); Estes, Eric (E.E.)  
**Subject:** RE: 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

The gear is being pulled today and they hope to get it overnighted today as well. I will let 26mile know once we have a tracking number.

---

**From:** Anderson, Eric (H.)  
**Sent:** Saturday, January 29, 2011 1:09 PM  
**To:** Jackson, Bradley (B.G.); Napoli, Laura (L.); Mrozek, Robert (R.M.); Estes, Eric (E.E.)  
**Subject:** RE: 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

Hi All:

The dealership did attempt to clear the codes but the problem persists. A service tech is attempting to get the snapshot data for us. I asked them to please hold on to the gear and explained that Eric Estes will be calling them to arrange shipping the faulty gear and receiving a new one.

Eric,  
Could you please arrange for this dealership to get a new gear and send the faulty one to

TRW Automotive East Building  
Attn: John Burnett  
4505 W 26 mile Rd  
Washington, MI 48094

Thank you everyone!

Eric

**From:** Jackson, Bradley (B.G.)  
**Sent:** Saturday, January 29, 2011 11:36 AM  
**To:** Anderson, Eric (H.); Napoli, Laura (L.); Mrozek, Robert (R.M.)  
**Subject:** FW: 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

[note p/s inop claim from w. virginia dealer below.....1st report.](#)

brad

---

**From:** SBUELOW [mailto:SBUELOW]  
**Sent:** Saturday, January 29, 2011 11:29 AM  
**To:** BJACKSON  
**Subject:** 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

This email contains 2 report summary(s).

**Attachments :** 0

<b>Report# :</b>	BA2AK005 NHL	<b>Received:</b>	01/28/2011
<b>CCRG/EPRC:</b>		<b>Date:</b>	
<b>Vehicle:</b>	2011,EXPLORER 4X4 (U502),4 DOOR ,MP,1FMHK8D83BG [REDACTED]	<b>Build Date:</b>	01/12/2011
<b>Odometer :</b>	12 M	<b>Engine:</b>	3.5L CYCLO
<b>Transmission:</b>	6F55	<b>Axle:</b>	
<b>Dealer:</b>	USA 02071 I77 Ford Mercury	<b>Calibration:</b>	BUB1ST0A
<b>City:</b>	Ripley	<b>A/C:</b>	YES
<b>State:</b>		<b>Phone#:</b>	(304) 372- 2480
<b>Originator:</b>	JOHNATHAN FRYE	<b>Country :</b>	USA
<b>Symptom:</b>	3 03 1 50 CHASS.,STRG/HANDLING ,FUNCTION,HIGH EFFORT		
<b>Status:</b>			
<b>VFG:</b>	V87 STEERING		
<b>Additional Symptom:</b>	POWER STEERING INOP		
<b>Fix:</b>	<b>Causal Component :</b>	--	

**Condition Code:**

<b>Hotliner:</b> IWRIGH24	<b>Phone:</b> 313 317-4284	<b>Regn Cd:</b> G3 Cincinnati
<b>Engineering:</b>	<b>Phone:</b>	<b>TAR:</b>
<b>Dlr Contact:</b> JOHNATHAN FRYE	<b>Phone:</b> 304 372-3673	<b>Title Cde:</b> SM

**DTCs:**  
KOEO:U3000  
KOEC:  
KOER:

**Comments**

:

**REPAIR** 01/28/2011 08:35AM IAN WRIGHT MSS - FCSD - TECH SVC HOTLINE  
WEB FORM DATA - CONCERN: POWER STEERING IS INOP DIAGNOSTICS: KOEO  
KOER PINPOINT TEST C1 PARTS REPLACED:: NO AT THIS TIME TECH  
QUESTION: ANY KNOWN CONCERNS WITH STEERING RACK WERE YOU ABLE TO  
VERIFY THE CONCERN? YES IS THERE AN APPROPRIATE PINPOINT TEST IN  
THE WSM FOR THIS CONCERN? YES WAS THE PINPOINT TEST FOLLOWED? YES

**RECOMM** 01/28/2011 08:35AM IAN WRIGHT MSS - FCSD - TECH SVC HOTLINE  
JONATHAN. INSPECT CONNECTOR PIN FITS TO THE PSCM. WE HAVE SEEN SOME  
CONCERNS DUE TO SPREAD PINS AT CONNECTOR C139. INSPECT THIS  
CONNECTION  
USING A FLEX PROBE AND REPAIR/REPLACE ANY LOOSE PINS. PERFORM THE  
INTERACTIVE DIAGNOSTICS FOR FURTHER ASSISTANCE DIAGNOSING THIS  
CONCERN. TO PERFORM THE DIAGNOSTICS. CONNECT IDS TO VEHICLE AND GO  
TO  
THE PTS WEB PAGE. OPEN THE ONLINE WORKSHOP MANUAL OPEN SECTION 211-  
00  
AND SELECT DTC CHART INTERACTIVE DIAGNOSTICS.

---

**Attachments : 0**

REDACTED FOR RELEVANCE

**Engineering:**

**Phone:**

**TAD:**

REDACTED FOR RELEVANCE

---

**From:** Napoli, Laura (L.)  
**Sent:** Monday, January 31, 2011 8:57 AM  
**To:** Anderson, Eric (H.); Jackson, Bradley (B.G.); Mrozek, Robert (R.M.); Estes, Eric (E.E.)  
**Subject:** RE: 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

The gear is being pulled today and they hope to get it overnighted today as well. I will let 26mile know once we have a tracking number.

---

**From:** Anderson, Eric (H.)  
**Sent:** Saturday, January 29, 2011 1:09 PM  
**To:** Jackson, Bradley (B.G.); Napoli, Laura (L.); Mrozek, Robert (R.M.); Estes, Eric (E.E.)  
**Subject:** RE: 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

Hi All:

The dealership did attempt to clear the codes but the problem persists. A service tech is attempting to get the snapshot data for us. I asked them to please hold on to the gear and explained that Eric Estes will be calling them to arrange shipping the faulty gear and receiving a new one.

Eric,  
Could you please arrange for this dealership to get a new gear and send the faulty one to

TRW Automotive East Building  
Attn: John Burnett  
4505 W 26 mile Rd  
Washington, MI 48094

Thank you everyone!

Eric

---

**From:** Jackson, Bradley (B.G.)  
**Sent:** Saturday, January 29, 2011 11:36 AM  
**To:** Anderson, Eric (H.); Napoli, Laura (L.); Mrozek, Robert (R.M.)  
**Subject:** FW: 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

[note p/s inop claim from w. virginia dealer below.....1st report.](#)

[brad](#)

---

**From:** SBUELOW [mailto:SBUELOW]  
**Sent:** Saturday, January 29, 2011 11:29 AM  
**To:** BJACKSON  
**Subject:** 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

This email contains 2 report summary(s).

**Attachments :** 0

**Report# :** BA2AK005 NHL **Received:** 01/28/2011  
**CCRG/EPRC:** **Reviewed Status:** **Date:**  
**Vehicle:** 2011,EXPLORER 4X4 (U502),4 DOOR **Build Date:** 01/12/2011  
,MP,1FMHK8D83BG [REDACTED]  
**Odometer :** 12 M **Engine:** 3.5L **Calibration:** BUB1ST0A  
CYCLO  
**Transmission:** 6F55 **Axle:** **A/C:** YES  
**Dealer:** USA 02071 I77 Ford Mercury **Phone#:** (304) 372-2480  
**City:** Ripley **State:** West **Country :** USA  
Virgini  
**Originator:** JOHNATHAN FRYE  
**Symptom:** 3 03 1 50 CHASS.,STRG/HANDLING ,FUNCTION,HIGH EFFORT  
**Status:**  
**VFG:** V87 STEERING  
**Additional Symptom:** POWER STEERING INOP  
**Fix:** **Causal Component :** --  
**Condition Code:**

**Hotliner:** IWRIGH24 **Phone:** 313 317-4284 **Regn Cd:** G3 Cincinnati  
**Engineering:** **Phone:** **TAR:**  
**Dlr Contact:** JOHNATHAN FRYE **Phone:** 304 372-3673 **Title Cde:** SM

**DTCs:**

KOEO:U3000  
KOEC:  
KOER:

**Comments**

**:**  
**REPAIR** 01/28/2011 08:35AM IAN WRIGHT MSS - FCSD - TECH SVC HOTLINE  
WEB FORM DATA - CONCERN: POWER STEERING IS INOP DIAGNOSTICS: KOEO  
KOER PINPOINT TEST C1 PARTS REPLACED:: NO AT THIS TIME TECH  
QUESTION: ANY KNOWN CONCERNS WITH STEERING RACK WERE YOU ABLE TO  
VERIFY THE CONCERN? YES IS THERE AN APPROPRIATE PINPOINT TEST IN  
THE WSM FOR THIS CONCERN? YES WAS THE PINPOINT TEST FOLLOWED? YES  
**RECOMM** 01/28/2011 08:35AM IAN WRIGHT MSS - FCSD - TECH SVC HOTLINE  
JONATHAN. INSPECT CONNECTOR PIN FITS TO THE PSCM. WE HAVE SEEN SOME  
CONCERNS DUE TO SPREAD PINS AT CONNECTOR C139. INSPECT THIS



CONNECTION


USING A FLEX PROBE AND REPAIR/REPLACE ANY LOOSE PINS. PERFORM THE INTERACTIVE DIAGNOSTICS FOR FURTHER ASSISTANCE DIAGNOSING THIS CONCERN. TO PERFORM THE DIAGNOSTICS. CONNECT IDS TO VEHICLE AND GO TO THE PTS WEB PAGE. OPEN THE ONLINE WORKSHOP MANUAL OPEN SECTION 211-00 AND SELECT DTC CHART INTERACTIVE DIAGNOSTICS.

---

**Attachments : 0**

REDACTED FOR RELEVANCE

REDACTED FOR RELEVANCE



---

**From:** Anderson, Eric (H.)  
**Sent:** Saturday, January 29, 2011 1:09 PM  
**To:** Jackson, Bradley (B.G.); Napoli, Laura (L.); Mrozek, Robert (R.M.); Estes, Eric (E.E.)  
**Subject:** RE: 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

Hi All:

The dealership did attempt to clear the codes but the problem persists. A service tech is attempting to get the snapshot data for us. I asked them to please hold on to the gear and explained that Eric Estes will be calling them to arrange shipping the faulty gear and receiving a new one.

Eric,  
Could you please arrange for this dealership to get a new gear and send the faulty one to

TRW Automotive East Building  
Attn: John Burnett  
4505 W 26 mile Rd  
Washington, MI 48094

Thank you everyone!

Eric

---

**From:** Jackson, Bradley (B.G.)  
**Sent:** Saturday, January 29, 2011 11:36 AM  
**To:** Anderson, Eric (H.); Napoli, Laura (L.); Mrozek, Robert (R.M.)  
**Subject:** FW: 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

note p/s inop claim from w. virginia dealer below.....1st report.

brad

---

**From:** SBUELOW [mailto:SBUELOW]  
**Sent:** Saturday, January 29, 2011 11:29 AM  
**To:** BJACKSON  
**Subject:** 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

This email contains 2 report summary(s).

**Attachments :** 0

<b>Report# :</b>	BA2AK005 NHL	<b>Received:</b>	01/28/2011
<b>CCRG/EPRC:</b>	<b>Reviewed Status:</b>	<b>Date:</b>	
<b>Vehicle:</b>	2011,EXPLORER 4X4 (U502),4 DOOR ,MP,1FMHK8D83BG [REDACTED]	<b>Build Date:</b>	01/12/2011
<b>Odometer :</b>	12 M	<b>Engine:</b>	3.5L CYCLO
<b>Transmission:</b>	6F55	<b>Axle:</b>	<b>Calibration:</b> BUB1ST0A
			<b>A/C:</b> YES

**Dealer:** USA 02071 I77 Ford Mercury **Phone#:** (304) 372-2480  
**City:** Ripley **State:** West Virginia **Country :** USA  
**Originator:** JOHNATHAN FRYE  
**Symptom:** 3 03 1 50 CHASS.,STRG/HANDLING ,FUNCTION,HIGH EFFORT  
**Status:**  
**VFG:** V87 STEERING  
**Additional Symptom:** POWER STEERING INOP  
**Fix:** **Causal Component :** --  
**Condition Code:**

**Hotliner:** IWRIGH24 **Phone:** 313 317-4284 **Regn Cd:** G3 Cincinnati

**Engineering:** **Phone:** **TAR:**

**Dlr Contact:** JOHNATHAN FRYE **Phone:** 304 372-3673 **Title Cde:** SM

**DTCs:**  
KOEO:U3000  
KOEC:  
KOER:

**Comments**

:

**REPAIR** 01/28/2011 08:35AM IAN WRIGHT MSS - FCSD - TECH SVC HOTLINE  
WEB FORM DATA - CONCERN: POWER STEERING IS INOP DIAGNOSTICS: KOEO  
KOER PINPOINT TEST C1 PARTS REPLACED:: NO AT THIS TIME TECH  
QUESTION: ANY KNOWN CONCERNS WITH STEERING RACK WERE YOU ABLE TO  
VERIFY THE CONCERN? YES IS THERE AN APPROPRIATE PINPOINT TEST IN  
THE WSM FOR THIS CONCERN? YES WAS THE PINPOINT TEST FOLLOWED? YES

**RECOMM** 01/28/2011 08:35AM IAN WRIGHT MSS - FCSD - TECH SVC HOTLINE  
JONATHAN. INSPECT CONNECTOR PIN FITS TO THE PSCM. WE HAVE SEEN SOME  
CONCERNS DUE TO SPREAD PINS AT CONNECTOR C139. INSPECT THIS  
CONNECTION  
USING A FLEX PROBE AND REPAIR/REPLACE ANY LOOSE PINS. PERFORM THE  
INTERACTIVE DIAGNOSTICS FOR FURTHER ASSISTANCE DIAGNOSING THIS  
CONCERN. TO PERFORM THE DIAGNOSTICS. CONNECT IDS TO VEHICLE AND GO  
TO  
THE PTS WEB PAGE. OPEN THE ONLINE WORKSHOP MANUAL OPEN SECTION 211-  
00  
AND SELECT DTC CHART INTERACTIVE DIAGNOSTICS.

**Attachments : 0**

REDACTED FOR RELEVANCE

REDACTED FOR RELEVANCE

## Printable View

Year = MY11

Model = U502

Engine = 3.5L

VIN = 1FMHK8D87BG

IDS Version = Not Available

 Current DTCs {retrieved 02 February 2011 11:14:34}

DTC	Snap Shot Data	Source
C1B00:86	N/A	<a href="#">ABS</a>
C200B:62	0A33010E330221E03306003B0000000000000000330C94D1118FD1173DD118FFADF40C01E4F40D14FDAAD4	<a href="#">PSCM</a>

 Historic DTCs {retrieved 02 February 2011 11:14:34}

DTC	Snap Shot Data	Source
U0402:68	N/A	<a href="#">ABS</a>
U0253:00	N/A	<a href="#">IC</a>

 DTCs cleared since initial read:

DTC	Snap Shot Data	Source
(ABS)	N/A	<a href="#">ABS</a>
Pass	N/A	<a href="#">ACM</a>
Pass	N/A	<a href="#">APIM</a>
Pass	N/A	<a href="#">ATCM</a>
Pass	N/A	<a href="#">FCIM</a>
Pass	N/A	<a href="#">FLM</a>
Pass	N/A	<a href="#">GPSM</a>
Pass	N/A	<a href="#">HVAC</a>
Pass	N/A	<a href="#">PAM</a>
Pass	N/A	<a href="#">PCM</a>
C200B:2F	0A330103330223203306004A00000000000000000000330C94D1118DD11742D118FF8DF40C03F6F40D0FFDAAD2	<a href="#">PSCM</a>
Pass	N/A	<a href="#">RCM</a>
Pass	N/A	<a href="#">SCCM</a>
Pass	N/A	<a href="#">TPM</a>

Start: Wed Feb 2 10:43:46 EST 2011

## Menu Selection: Inspection and Verification

 IV1: VISUAL INSPECTION

- Verify the customer concern.
- Visually inspect the electronic power assist steering (EPAS) system for obvious signs of mechanical or electrical damage.  
**NOTE:** When inspecting the bellows boots make sure to use a strong light source and an inspection mirror.

## VISUAL INSPECTION CHART

Mechanical	Electrical
Binding or misaligned steering column.	High-current battery junction box (BJB) fuse E (100A), attached to the battery positive terminal
Loose steering column shaft bolts.	Battery Junction Box (BJB) fuse 89 (5A)
Steering column shaft couplings/U-joints	Wiring, terminals or connectors.
Steering gear	
Steering gear bellows boots	
Inner tie rod ends	
Outer tie rod ends	
Tire pressure	

Tires

- Is an obvious cause for an observed or reported concern found?

No

Go to Known Concerns

undefined: undefined

## DTC C200B:2F (PSCM) - Steering Shaft Torque Sensor 1: Signal Erratic

- ▣ B: DTCs C1B00, C200B, C200C, C200D, U2011, U2200 and U3000: Steering Angle Sensor, Steering Shaft Torque Sensor 1, Steering Shaft Torque Sensor 2, Motor and Control Module - Failure or Erratic  
**Normal Operation**

The power steering control module (PSCM) monitors various inputs and outputs of the electronic power assist steering (EPAS) system in order to keep the system operating at peak capacity. Information provided by sensors (steering torque, vehicle speed, vehicle travel distance, etc.) are all compared to programmed and learned information. Likewise, outputs like the motor and steering rack (travel) are tested against programmed and learned information.

**Note:**

If a damaged bellows boot(s) was discovered during Inspection and Verification and this pinpoint test DOES NOT lead to the installation of a new EPAS gear or bellows boot(s), then go to Pinpoint Test K to address the damaged boot(s) before returning the vehicle to the customer.

- ▣ B1: CHECK FOR PREVIOUSLY SET DTCS

- Go to KNOWN CONCERNS.  
Check for DTCs listed in the section: System Related CMDTCs cleared since initial read.
- **Are any of the following DTCs present?**  
**PSCM DTCs C1B00:2F, C1B00:62, C200B:2F, C200B:61, C200B:62, U2011:49, U2011:61, U2200:54, U3000:41, U3000:46, U3000:49.**

Yes

Go to B2.

- ▣ B2: INSPECT EPAS GEAR WIRING HARNESS

- With the vehicle in NEUTRAL, position it on a hoist. Refer to Section 100-02.
- Ignition OFF.
- Thoroughly inspect the wire harness along the top of the EPAS gear for cuts, breaks and pinched wires.
- Disconnect all 3 EPAS gear electrical connectors and inspect them for corrosion, pushed-out pins, bent pins and spread terminals.
- **Is the wire harness undamaged and are all 3 connectors in good condition?**

Yes

CONNECT all 3 EPAS gear electrical connectors.

Go to B3.

- ▣ B3: TEST DRIVE TO CHECK FOR RETURNING DTCS. - Fault outcome

NOTE: Always drive the vehicle in a safe manner according to driving conditions and obey all traffic laws.

- Clear the PSCM DTCs. **Complete**
- Cycle the ignition to OFF and then back to RUN.
- Test drive the vehicle in the following manner:
  - With the engine running/ready, stop the vehicle on an unsealed concrete or asphalt surface (in order to provide adequate friction for a thorough test).
  - With the vehicle in gear and the brakes applied, turn the steering wheel lock-to-lock.
  - Return the steering wheel to the center position and move the vehicle forward approximately 32 cm (1 ft).
  - With the vehicle in gear and the brakes applied, turn the steering wheel lock-to-lock.
  - Return the steering wheel to the center position and move the vehicle forward approximately 32 cm (1 ft).
  - With the vehicle in gear and the brakes applied, turn the steering wheel lock-to-lock.
  - The test drive is complete.
- Press Read Vehicle Information button to retrieve DTC s from the vehicle. NOTE: DTCs may be displayed from previous diagnostic actions.



**Vehicle Information:**

VIN 1FMHK8D87BG [REDACTED]

**System Related CMDTCs Active {retrieved 02 February 2011 11:14:34}**

DTC	Description	Type	Source	Status
C200B:2F	Steering Shaft Torque Sensor 1 : Signal Erratic	KOEC	PSCM	Historic
C200B:62	Steering Shaft Torque Sensor 1 : Signal Compare Failure	KOEC	PSCM	Current
C200B:62	Steering Shaft Torque Sensor 1 : Signal Compare Failure	ODDTCs	PSCM	Unknown

**System Related CMDTCs cleared since initial read:**

- Does DTC C1B00:62, C200B:2F, C200B:61, C200C:2F, C200D:49, U2011:49, U2011:61, U3000:41, U3000:46 and/or U3000:49 return?

**Yes****INSTALL a new EPAS gear.  
Refer to Section 211-02.**

Exit: Wed Feb 2 11:18:57 EST 2011

---

**From:** Mrozek, Robert (R.M.)  
**Sent:** Friday, January 21, 2011 1:45 PM  
**To:** Estes, Eric (E.E.)  
**Cc:** Napoli, Laura (L.); Bahena, Miguel (Mike.)  
**Subject:** RE: 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

3 and 4 sound like electrical issues to me.....when interior lights go on an off and low batt voltage come up then you gotta believe it is not an EPAS issue. Right?

*Rob Mrozek*

Electric Power Steering Supervisor  
CD3/D3/D4/U502/Police/Limo EPAS Programs +  
Active Front Steering Applications Engineering  
Ford Motor Company  
Phone: (313) 805-5947  
e-mail: rmrozek@ford.com

---

**From:** Estes, Eric (E.E.)  
**Sent:** Friday, January 21, 2011 10:14 AM  
**To:** Napoli, Laura (L.)  
**Cc:** Mrozek, Robert (R.M.)  
**Subject:** RE: 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

Talked to all tech's for all three No Com gears they will replace EPAS gears. I have two int. no com's similar with Bradley's plant vehicle road test and I have one No Com that is their all the time

Laura see if we can install one of the int. No Com's for on-vehicle testing and we will take the other two in for analysis at 26-mile.

The attachment is my updated warranty tracking report with the new U502 gears, and I added the tech comments.

Laura did you talk to Brad and find out about the U502 B3A if you wanted to wait for the Tyco relay workshop in Feb?

Let me know

Eric

---

**From:** Napoli, Laura (L.)  
**Sent:** Friday, January 21, 2011 9:28 AM  
**To:** Estes, Eric (E.E.)  
**Subject:** FW: 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

Eric,

Can you verify that none of these codes indicate that the rack should be pulled? Thanks!

I'm off today, so call my cell if you need me...313-805-0482

---

**From:** SBUELOW [mailto:SBUELOW]

**Sent:** Friday, January 21, 2011 4:46 AM

**To:** LNAPOLI

**Subject:** 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

REDACTED FOR RELEVANCE

Attachments : 0

**Report# :** BATDZ004 NHL **Received:** 01/20/2011  
**CCRG/EPRC:** **Reviewed Status:** **Date:**  
**Vehicle:** 2011,EXPLORER 4X4 (U502),4 DOOR **Build Date:** 11/22/2010  
,MP,1FMHK8F83BG [REDACTED]  
**Odometer :** 289 M **Engine:** 3.5L **Calibration:** BUB1ST0A  
CYCLO  
**Transmission:** 6F55 **Axle:** **A/C:** YES  
**Dealer:** USA 02058 BEECHMONT FORD INC **Phone#:** (513) 752-  
7474  
**City:** Cincinnati **State:** Ohio **Country :** USA  
**Originator:** SHANE JONES  
**Symptom:** 3 03 A 99 CHASS.,STRG/HANDLING ,STEERING WHEEL ,NOT LISTED  
**Status:**  
**VFG:** V87 STEERING  
**Additional Symptom:** STEERING HARD INTERMITTENT  
**Fix:** **Causal Component :** --  
**Condition Code:**

**Hotliner:** JSAVOY1 **Phone:** 313 317-9352 **Regn Cd:** G3 Cincinnati  
**Engineering:** **Phone:** **TAR:**  
**Dlr Contact:** SHANE JONES **Phone:** 513 752-7474 **Title Cde:** T

**DTCs:**  
KOE0:U0121 U2011:49-08 U0126 U0159 U0428  
KOE0:  
KOE0:

**Comments**  
:

REPAIR 01/20/2011 02:47PM JONATHAN SAVOY MSS - FCSD - TECH SVC HOTLINE  
WEB FORM DATA - CONCERN: CUST STATES THAT THE MESSAGE CENTER HAD A  
MESSAGE THAT SAID POWER STEERING ASSIST FAULT AND THE STEERING WAS  
VERY HARD DIAGNOSTICS: TEST DROVE VEH AND NORMAL OPERATION AT THIS

TIME 0 WARNINGS IN THE MESSAGE CENTER IDS TESTED AND FOLLOWED  
PINPOINT TEST PER WORK SHOP MANUAL AND IT LED ME TO THE CONSERN IS  
NOT PRESENT AND TO RETURN THE VEH BACK TO THE CUST DTC  
U2011:49-08,U0121,U0126,U0159,U0428 THE WORK SHOP MANUAL TOLD ME TO  
CLEAR THE DTC AND TEST DRIVE VEH AND RETEST I CLEARD THE DTC AND THE  
SYSTEM PASSED PARTS REPLACED:: NONE TECH QUESTION: ANY KNOWN  
CONSERNS SHOULD I RETURN THE VEH TO THE CUST WERE YOU ABLE TO  
VERIFY THE CONCERN? NO IS THERE AN APPROPRIATE PINPOINT TEST IN THE  
WSM FOR THIS CONCERN? YES WAS THE PINPOINT TEST FOLLOWED? YES

**RECOMM 01/20/2011 02:47PM JONATHAN SAVOY MSS - FCSD - TECH SVC HOTLINE**

SHANE, THIS CONCERN IS LIKELY CAUSED BY A LOOSE CONNECTION WITHIN  
THE MAIN ENGINE OR BODY WIRING HARNESS. THIS WOULD RESULT IN  
INTERMITTENT COMMUNICATION CODES AND POSSIBLE INOPERATIVE  
ACCESSORIES.

IN ORDER TO HELP ISOLATE THE ROOT CAUSE OF THIS CONCERN, PLEASE  
START THE VEHICLE AND WIGGLE TEST THE MAIN ENGINE AND BODY WIRING  
HARNESS. THIS MAY HELP TO INDUCE THE CONCERN. PLEASE ALSO INSPECT FOR  
LOOSE OR UNSEATED CONNECTORS. THE HOTLINE HAS NOT SEEN TRENDS OF  
THIS CONCERN AT THIS TIME. IF THE CONCERN CANNOT BE DUPLICATED, NO  
REPAIRS SHOULD BE PERFORMED. IF ADDITIONAL ASSISTANCE IS NEEDED,  
PLEASE UPDATE YOUR FORM WITH ANY ADDITIONAL DETAILS OF THIS  
CONCERN.

---

REDACTED FOR RELEVANCE

REDACTED FOR RELEVANCE

---

**Attachments : 0**

REDACTED FOR RELEVANCE

**Dlr Contact:** JAMES BUCHANAN

**Phone:** 000 000-0000

**Title Cde:** T

REDACTED FOR RELEVANCE

---

---

**From:** Estes, Eric (E.E.)  
**Sent:** Friday, January 21, 2011 12:46 PM  
**To:** Mrozek, Robert (R.M.); Jackson, Bradley (B.G.); Napoli, Laura (L.); 'Michael Fontana'; Diez, Timothy (T.P.)  
**Cc:** Pasquarella, Michael (M.S.); Bahena, Miguel (Mike.); 'John Burnett'  
**Subject:** RE: 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

Mike any way you can do that relay testing Geoff wanted you to do before Mike takes the EPP in for xray?

Eric

---

**From:** Mrozek, Robert (R.M.)  
**Sent:** Friday, January 21, 2011 12:39 PM  
**To:** Estes, Eric (E.E.); Jackson, Bradley (B.G.); Napoli, Laura (L.); 'Michael Fontana'; Diez, Timothy (T.P.)  
**Cc:** Pasquarella, Michael (M.S.); Bahena, Miguel (Mike.)  
**Subject:** RE: 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition  
**Importance:** High

Eric -

Please talk to Brad about how to expedite these parts back to us. Also, since the intermittent code maps to an A19 or A29, A19 might be related to a missing soft stop. Please have Fontana run the ANY gear without soft stops and see if that code is raised. Even check with the dealer to see if he can test the gear or car for equal travel left to right. We had a missing soft stop issue at MP1.

B3A  
Please be prepared to have the EPP analysis by Monday at our weekly meeting even if it means someone needs to work on it tomorrow.

*Rob Mrozek*

Electric Power Steering Supervisor  
CD3/D3/D4/U502/Police/Limo EPAS Programs +  
Active Front Steering Applications Engineering  
Ford Motor Company  
Phone: (313) 805-5947  
e-mail: rmrozek@ford.com

---

**From:** Estes, Eric (E.E.)  
**Sent:** Friday, January 21, 2011 11:02 AM  
**To:** Mrozek, Robert (R.M.); Jackson, Bradley (B.G.); Napoli, Laura (L.)  
**Cc:** Pasquarella, Michael (M.S.)  
**Subject:** RE: 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

Rob all three of the No Com's will be returned, I cannot say 100% that the gear is the issue. most of the testing has been confirmed by the book and some have load tested the circuits. it is possible it could be a ground or ign. feed but I have one hard No Com that will be returned and two intermittent No Com similar to Brad's road test description at the plant.



I'm giving Blood to the Red Cross and will return in one hour

Eric

---

**From:** Mrozek, Robert (R.M.)  
**Sent:** Friday, January 21, 2011 10:50 AM  
**To:** Jackson, Bradley (B.G.); Estes, Eric (E.E.); Napoli, Laura (L.)  
**Cc:** Pasquarella, Michael (M.S.)  
**Subject:** RE: 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

We had a similar launch issue and it was a bad ground of the wire to the EPAS.

*Rob Mrozek*

Electric Power Steering Supervisor  
CD3/D3/D4/U502/Police/Limo EPAS Programs +  
Active Front Steering Applications Engineering  
Ford Motor Company  
Phone: (313) 805-5947  
e-mail: rmrozek@ford.com

---

**From:** Jackson, Bradley (B.G.)  
**Sent:** Friday, January 21, 2011 10:47 AM  
**To:** Mrozek, Robert (R.M.); Estes, Eric (E.E.); Napoli, Laura (L.)  
**Cc:** Pasquarella, Michael (M.S.)  
**Subject:** RE: 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

Rob, I agree. If the word gets out that gear replacements are fixing the concern, we are in trouble. Need to deep dive these gears when they come back.

Just an fyi to this team, my M10 from 2 weeks ago was found to be a NPF....even though there were stored DTC's and was reproducible after several key off/key on cycles. That being said, we now have another vehicle with the exact same tell tale signs of terrain mgmt inop and traction control inop here at CAP that was found in a FCPA audit. This vehicle has stored DTC's and is now not showing the faults either. We are going to be deep diving this vehicle at some point today to try to root cause. I want to start with wiring connection to gear and work backwards. Something is happening intermittently and we need to figure this out.

Please call with any questions.

Brad

---

**From:** Mrozek, Robert (R.M.)  
**Sent:** Friday, January 21, 2011 9:27 AM  
**To:** Estes, Eric (E.E.); Napoli, Laura (L.)  
**Cc:** Pasquarella, Michael (M.S.); Jackson, Bradley (B.G.)  
**Subject:** RE: 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition  
**Importance:** High

- 1) Why are we replacing these gears? How do you know it is not a wiring issue? Do not replace an intermittent gear until we know 100% for sure it is not wiring. Are these dealers nearby where we can go there to look?
- 2) WARNING: The world will shit a brick with 4 EPAS claims on U502 and our lives will be hell. ALL these gears need root cause within 48 hours or less.

*Rob Mrozek*

Electric Power Steering Supervisor  
CD3/D3/D4/U502/Police/Limo EPAS Programs +  
Active Front Steering Applications Engineering  
Ford Motor Company  
Phone: (313) 805-5947  
e-mail: rmrozek@ford.com

---

**From:** Estes, Eric (E.E.)  
**Sent:** Friday, January 21, 2011 10:14 AM  
**To:** Napoli, Laura (L.)  
**Cc:** Mrozek, Robert (R.M.)  
**Subject:** RE: 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

Talked to all tech's for all three No Com gears they will replace EPAS gears. I have two int. no com's similar with Bradley's plant vehicle road test and I have one No Com that is their all the time

Laura see if we can install one of the int. No Com's for on-vehicle testing and we will take the other two in for analysis at 26-mile.

The attachment is my updated warranty tracking report with the new U502 gears, and I added the tech comments.

Laura did you talk to Brad and find out about the U502 B3A if you wanted to wait for the Tyco relay workshop in Feb?

Let me know

Eric

---

**From:** Napoli, Laura (L.)  
**Sent:** Friday, January 21, 2011 9:28 AM  
**To:** Estes, Eric (E.E.)  
**Subject:** FW: 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

Eric,

Can you verify that none of these codes indicate that the rack should be pulled? Thanks!

I'm off today, so call my cell if you need me...313-805-0482

---

**From:** SBUELOW [mailto:SBUELOW]

**Sent:** Friday, January 21, 2011 4:46 AM

**To:** LNAPOLI

**Subject:** 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

REDACTED FOR RELEVANCE

Attachments : 0

**Report# :** BATDZ004 NHL **Received:** 01/20/2011  
**CCRG/EPRC:** **Reviewed Status:** **Date:**  
**Vehicle:** 2011,EXPLORER 4X4 (U502),4 DOOR **Build Date:** 11/22/2010  
,MP,1FMHK8F83BG [REDACTED]  
**Odometer :** 289 M **Engine:** 3.5L **Calibration:** BUB1ST0A  
CYCLO  
**Transmission:** 6F55 **Axle:** **A/C:** YES  
**Dealer:** USA 02058 BEECHMONT FORD INC **Phone#:** (513) 752-7474  
**City:** Cincinnati **State:** Ohio **Country :** USA  
**Originator:** SHANE JONES  
**Symptom:** 3 03 A 99 CHASS.,STRG/HANDLING ,STEERING WHEEL ,NOT LISTED  
**Status:**  
**VFG:** V87 STEERING  
**Additional Symptom:** STEERING HARD INTERMITTENT  
**Fix:** **Causal Component :** --  
**Condition Code:**

**Hotliner:** JSAVOY1 **Phone:** 313 317-9352 **Regn Cd:** G3 Cincinnati  
**Engineering:** **Phone:** **TAR:**  
**Dlr Contact:** SHANE JONES **Phone:** 513 752-7474 **Title Cde:** T

**DTCs:**

KOEO:U0121 U2011:49-08 U0126 U0159 U0428  
KOEC:  
KOER:

**Comments**

:  
REPAIR 01/20/2011 02:47PM JONATHAN SAVOY MSS - FCSD - TECH SVC HOTLINE  
WEB FORM DATA - CONCERN: CUST STATES THAT THE MESSAGE CENTER HAD A  
MESSAGE THAT SAID POWER STEERING ASSIST FAULT AND THE STEERING WAS  
VERY HARD DIAGNOSTICS: TEST DROVE VEH AND NORMAL OPERATION AT THIS  
TIME 0 WARNINGS IN THE MESSAGE CENTER IDS TESTED AND FOLLOWED  
PINPOINT TEST PER WORK SHOP MANUAL AND IT LED ME TO THE CONSERN IS  
NOT PRESENT AND TO RETURN THE VEH BACK TO THE CUST DTC  
U2011:49-08,U0121,U0126,U0159,U0428 THE WORK SHOP MANUAL TOLD ME TO  
CLEAR THE DTC AND TEST DRIVE VEH AND RETEST I CLEARD THE DTC AND THE

SYSTEM PASSED PARTS REPLACED:: NONE TECH QUESTION: ANY KNOWN  
CONSERNS SHOULD I RETURN THE VEH TO THE CUST WERE YOU ABLE TO  
VERIFY THE CONCERN? NO IS THERE AN APPROPRIATE PINPOINT TEST IN THE  
WSM FOR THIS CONCERN? YES WAS THE PINPOINT TEST FOLLOWED? YES

**RECOMM 01/20/2011 02:47PM JONATHAN SAVOY MSS - FCSD - TECH SVC HOTLINE**

SHANE, THIS CONCERN IS LIKELY CAUSED BY A LOOSE CONNECTION WITHIN  
THE MAIN ENGINE OR BODY WIRING HARNESS. THIS WOULD RESULT IN  
INTERMITTENT COMMUNICATION CODES AND POSSIBLE INOPERATIVE  
ACCESSORIES.

IN ORDER TO HELP ISOLATE THE ROOT CAUSE OF THIS CONCERN, PLEASE  
START THE VEHICLE AND WIGGLE TEST THE MAIN ENGINE AND BODY WIRING  
HARNESS. THIS MAY HELP TO INDUCE THE CONCERN. PLEASE ALSO INSPECT FOR  
LOOSE OR UNSEATED CONNECTORS. THE HOTLINE HAS NOT SEEN TRENDS OF  
THIS CONCERN AT THIS TIME. IF THE CONCERN CANNOT BE DUPLICATED, NO  
REPAIRS SHOULD BE PERFORMED. IF ADDITIONAL ASSISTANCE IS NEEDED,  
PLEASE UPDATE YOUR FORM WITH ANY ADDITIONAL DETAILS OF THIS  
CONCERN.

---

REDACTED FOR RELEVANCE

REDACTED FOR RELEVANCE

REDACTED FOR RELEVANCE

REDACTED FOR RELEVANCE

---

**From:** Napoli, Laura (L.)  
**Sent:** Tuesday, April 17, 2012 5:49 PM  
**To:** Flanagan, Thomas (T.P.)  
**Subject:** RE: 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

We need to know the gear part number for the U3000-61. We fixed B91 with our R7 SW which went in last Nov/Dec for MP1. That part number was DG13-3D070-AF. We'll see when we get the gear back. I'd be shocked if it didn't have this level SW in it because we flashed most of the fleet with this update.

---

**From:** Flanagan, Thomas (T.P.)  
**Sent:** Monday, April 16, 2012 9:34 AM  
**To:** Napoli, Laura (L.)  
**Subject:** FW: 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

Tom Flanagan  
Ford Motor Company  
CD3, D3 EPAS Steering Engineering  
PDC 2B-K24  
(313) 845-4062  
Cell (313) 815-6885

**From:** SBUELOW  
**Sent:** Saturday, April 14, 2012 8:30 AM  
**To:** TFLANAG1  
**Subject:** 2011 EXP/TAU/MKS CHASSIS - Report Summary(s) from a GCQIS Query Disposition

This email contains 6 report summary(s).

**Attachments :** 0

REDACTED FOR RELEVANCE



REDACTED FOR RELEVANCE

**Attachments :** 0

<b>Report# :</b>	CDMDT020 NHL	<b>Received:</b>	04/13/2012
<b>CCRG/EPRC:</b>		<b>Date:</b>	
<b>Vehicle:</b>	2011,EXPLORER 4X4 (U502) ,LIMITED,4 DOOR ,MPV ,1FMHK8F87BG [REDACTED]	<b>Build Date:</b>	03/30/2011
<b>Odometer :</b>	28,272 M	<b>Engine:</b>	3.5L CYCLO
<b>Transmission:</b>	6F55	<b>Axle:</b>	
		<b>Calibration:</b>	BUB1ST0A
		<b>A/C:</b>	YES

**Dealer:** USA 02707 Brighton Ford, Inc. **Phone#:** (810) 227-1171  
**City:** Brighton **State:** Michigan **Country :** USA  
**Originator:** WALTER GAWEL  
**Symptom:** 2 27 2 68 AID/INFO,WNG IND/MESS/C,ADV TRAC,STAYS ON  
**Status:**  
**VFG:** V21 BRAKING  
**Additional Symptom:** TRAC AND HILL ASSIST ON START  
**Fix:** **Causal Component :** --  
**Condition Code:**

**Hotliner:** IWRIGH24 **Phone:** 313 317-4284 **Regn Cd:** G2 Detroit  
**Engineering:** **Phone:** **TAR:**  
**Dlr Contact:** WALTER GAWEL **Phone:** 000 000-0000 **Title Cde:** T

**DTCs:**  
 KOEO:  
 KOEC:  
 KOER:

**Comments**

:  
**REPAIR** 04/13/2012 04:14PM IAN WRIGHT MSS - FCSD - TECH SVC HOTLINE  
 WEB FORM DATA - CONCERN:HILL DESENT AND STABILTIY WARNING LIGHTS ARE  
 ON. DIAGNOSTICS: PERFORM IDS CHECK AND CLEAR CODES AND NO CODES FOUND. PERFORM NETWORK TEST AND PASSES. PARTS REPLACED:NONE TECH QUESTION:VEHICLE CAME BACK WITH THE HILL DESENT AND STABILTY LIGHTS ON. JUST HAD THE SYNC UPDATE PERFORMED. THE WARNING LIGHTS COME ON FOR ABOUT 30SECONDS AFTER STARTING VEHICLE AND THEN THEY GO OFF. SHUT VEHICLE OFF AND THE LIGHTS COME BACK ON. IS THIS RELATED TO THE SYNC REFLASH OR IS THERE SOMETHING ELSE GOING ON. CUST STATES WAS NOT HAPPENING BEFORE SERVICE WAS PERFORM.  
**RECOMM** 04/13/2012 04:14PM IAN WRIGHT MSS - FCSD - TECH SVC HOTLINE  
 WALTER, THIS IS NOT LIKELY RELATED TO THE MYTOUCH UPDATE. COMPARE THIS TO A LIKE VEHICLE TO ENSURE THAT THIS IS NOT NORMAL INDICATOR PROVE-OUT. IF A LIKE VEHICLE HAS THE SAME CONDITION NO FURTHER REPAIRS SHOULD BE MADE. IF THIS DOES NOT COMPARE TO A LIKE VEHICLE, PERFORM A ON DEMAND SELF TEST OF THE IC AND ABS MODULE TO ENSURE NO FAULTS ARE SET. IF NO DTCS ARE SET THIS MAY BE DUE TO LOW

CRANKING VOLTAGE. MONITOR CRANKING VOLTAGE. IF IT IS BELOW 11 VOLTS REPLACE/RECHARGE THE BATTERY AS NEEDED.

**REPAIR 04/13/2012 04:53PM FRED SHEPHERD MSS - FCSD - TECH SVC HOTLINE**

ALL READY PERFORM SELFTEST ON SAID MODULES AND PASSED. AFTER PUTTING

IN THIS REPORT I WAITED ABOUT 10MINS AND WENT TO RESTART VEHICLE AND CONCERN CORRECTED IT SELF. ROAD TEST AND SHUT ENGINE OFF AND RESTARTED

10 DIIFERENT TIMES AND IS FINE NOW. CUST WAS WAITING AND TOOK VEHICLE WHILE I WS WAITING FOR A RESPONSE FROM HOTLINE.

**RECOMM 04/13/2012 04:53PM FRED SHEPHERD MSS - FCSD - TECH SVC HOTLINE**

THANKS FOR THE UPDATE WALT. IF THE VEHICLE RETURNS WITH THIS ISSUE, I WOULD RECOMMEND TO VERIFY THERE IS NO LOSS OF MODULE COMMUNICATION.

VERIFY ALL ABS POWERS AND GROUNDS. ROAD TEST THE VEHICLE AND ATTEMPT

TO DUPLICATE THE CONCERN. MONITOR THE WSS, SWA, LAT, YAW AND ROLL PIDS

AND CHECK FOR POSSIBLE INCORRECT OR ERRATIC READINGS AND SERVICE AS NEEDED.

---

REDACTED FOR RELEVANCE

REDACTED FOR RELEVANCE

REDACTED FOR RELEVANCE

REDACTED FOR RELEVANCE

REDACTED FOR RELEVANCE

Attachments : 0

**Report# :** CDMFP003 NHL **Received:** 04/13/2012  
**CCRG/EPRC:** **Reviewed Status:** **Date:**  
**Vehicle:** 2011,EXPLORER 4X2 (U502) ,LIMITED,4 DOOR ,MPV **Build Date:** 03/14/2011  
,1FMHK7F86BG [REDACTED]  
**Odometer :** 12,404 M **Engine:** 3.5L CYCLO **Calibration:** BUB1ST0A  
**Transmission:** 6F55 **Axle:** **A/C:** YES  
**Dealer:** USA 08686 Courtesy Ford Lincoln **Phone#:** (337) 332-2145  
**City:** Breaux Bridge **State:** Louisiana **Country :** USA  
**Originator:** SHERILL LATIOLAIS  
**Symptom:** 6 62 4 28 SP/ST/RD,STEER/STER WHL,PERFORMANCE,EXCESS EFFORT  
**Status:**  
**VFG:** V87 STEERING  
**Additional Symptom:** HIGH EFFORT, TRAC LIGHT  
**Fix:** **Causal Component :** --  
**Condition Code:**

**Hotliner:** AROGER59 **Phone:** 000 317-9295 **Regn Cd:** C3 Memphis  
**Engineering:** **Phone:** **TAR:**  
**Dlr Contact:** SHERILL LATIOLAIS **Phone:** 000 000-0000 **Title Cde:** OT

**DTCs:**

KOEO:C1B00:86 C200D:49

KOEC:

KOER:

**Comments**

:

**REPAIR** 04/13/2012 05:51PM ALEXANDER ROGERS MSS - FCSD - TECH SVC HOTLINE  
WEB FORM DATA - CONCERN:CUST SAID THAT SHE LOST POWER STEERING AND  
TRACTION CONTROL LIGHT CAME ON DIAGNOSTICS: CK FOR DTC,S AND CK ALL  
RELATED CONNECTIONS PARTS REPLACED:NONE TECH QUESTION:ANY KNOWN  
CONCERNS,

**RECOMM** 04/13/2012 05:51PM ALEXANDER ROGERS MSS - FCSD - TECH SVC HOTLINE  
SHERRILL, IF DTC C200D:49 IS PRESENT IN THE PSCM, AN INTERNAL  
STEERING RACK FAULT IS PRESENT, AND THE RACK SHOULD BE REPLACED. A  
STEERING RACK FAULT IS LIKELY TO HAVE CAUSED THE ILLUMINATED



ADVANCE

TRAC LIGHT AS WELL AS THE HIGH STEERING EFFORT. THE PSCM THAT IS SERVICED WITH THE STEERING RACK DETERMINES STEERING WHEEL ANGLE. THE

STEERING RACK FAULT THAT CAUSED DTC C200D:49 TO SET LIKELY CAUSED DTC C1B00:86 TO SET IN THE ABS MODULE. PLEASE REPLACE THE VEHICLE'S STEERING RACK, AND RE EVALUATE BOTH CONCERNS. ISM 11-08-019 LOSS OF POWER STEERING ASSIST WITH C200D IN PSCM

---

---

**From:** Estes, Eric (E.E.)  
**Sent:** Wednesday, February 09, 2011 12:47 PM  
**To:** Anderson, Eric (H.); 'Michael Fontana'; 'Simon Malsbury'; 'Robert Kostadina'; 'Hemang Mehta'; 'Nick turovich'; Mrozek, Robert (R.M.); Diez, Timothy (T.P.); Napoli, Laura (L.); 'Geoff Jacks'; 'Phil Browne'; 'Michele Marion'; Jim Loria; Don Blandino-contr; Engelbert Lu; Mathew Alder  
**Subject:** RE: BG [REDACTED] power steering intermittently inoperative

This is the third U502 warranty return on have on my warranty chart with torque sensor codes(BD2 & BD4), I put in a hot request last week for this return, still no 700 tag on this part today, if the claim is closed we should have a 700 tag tomorrow and I have the part overnighted to WPAC where I will perform the level 1 diagnosis and then ship to 26mile for further analysis.

See interactive diagnosis below



*Eric J Estes*

TRW EPAS Steering Systems  
Quality Specialist  
Hotline ph# 313-317-9358  
Cell ph# 734-560-3493

---

**From:** Anderson, Eric (H.)  
**Sent:** Wednesday, February 09, 2011 12:15 PM  
**To:** 'Michael Fontana'; 'Simon Malsbury'; 'Robert Kostadina'; 'Hemang Mehta'; 'Nick turovich'; Estes, Eric (E.E.); Mrozek, Robert (R.M.); Diez, Timothy (T.P.); Napoli, Laura (L.); 'Geoff Jacks'; 'Phil Browne'; 'Michele Marion'  
**Subject:** BG [REDACTED] power steering intermittently inoperative

Hi All:

Please see the ECB claim below. I am collecting more information from the dealer. So far, his story is:

Power steering became inoperative while maneuvering vehicle during slow speed turns in dealer lot. Key cycling would sometimes bring power steering back for 30 seconds to a minute, then steering would become inoperative.

A day after symptoms started, power steering worked fine. Vehicle was driven into repair garage with full assist. These codes were pulled, cleared and returned:

C1B00  
U0253-00  
C200B  
2F  
C200B-62

The traction control light turned on.

The dealership has a bumpy parking lot and has experienced temperature swings from mid 30's to high 50's lately.

I will request the gear back.

Server: **AWS Prod**

Claims loaded through: **08-FEB-2011**

## Claim Detail Report

*Note: All costs are in US dollars*

**Model Year** = 2011; **Claim Key** = 214167

### Vehicle Information

Model Year: 2011

Market Derived: F - FORD

Body/Cab Type: T/WD - 4 DOOR WAGON

Version/Series: T/EF-FORD SERIES

Drive Type: T/F-4 WHL L/H FULL TIME  
DRIVE

Vehicle Line: T/UB-EXPLORER [2011]

Warranty Start Date:

Production Date: 24-JAN-11

VIN: 1FMHK8D87BG [REDACTED]

### **Dealer Information:**

Dealer Name RON DUPRATT FORD

Dealer Code: 07955 - \*

Address: 1320 N FIRST ST

City: DIXON

State: CA Zip Code: 95620

Country: USA Region Code: NA

Phone: (707)678-5555

### Claim Information

Document Number: 168057A

Repair Date: 02-FEB-11

Distance: 15

TIS: -1

### Expense Information

Customer Paid Amount: .00

Deductible Amount: .00

Dealer Paid Amount: .00

Labor Cost: 608.85

Misc. Expense Amount: .00

Part Markup Amount: 292.57

Material Cost: 1024.00

Total Cost Gross: 1632.85

Cust.  
 Concern **H22 - STEERING REQUIRES EXTRA OR UNEVEN EFFORT**  
 Code:

Condition  
 Code: **42 - DOES NOT OPERATE PROPERLY**

Technician 15 (381) RELACED EPAS GEAR SYSTEM, WAS NOT ABLE TO INHALE  
 Comment: PSCM, SO PERFORMED AS BUILT DATA ON PSCM. CHECKED  
 ALIGNMENT FOUND TOE TO BE OUT OF SPECS ADJUSTED TOE AND  
 TEST DROVE VEHICLE VEHICLE DRIVES STRAIGN AND POWER  
 STEERING ASSIST OPERATES PROPERLY. NO CODES PRESENT AT THIS  
 TIME.

Customer FOUND DURING DEMO DRIVE, P S LOST ASST. TRACTION CONTROL  
 Comment: LIGHT CAME ON. CONCERN CORRECTED AFTER DRIVING 2 MILES

<u>Labor Op Code</u>	<u>Labor Op Description</u>	<u>Labor Op Cost</u>
3504E		22.14
3504E45		33.21
3504E47		33.21
MT3504		387.45
MT3001		66.42
3504E8		11.07
MTPSCM		55.35

<u>Causal</u>	<u>Full Part Number</u>			<u>Part</u>	<u>Part</u>	<u>Extended</u>	
<u>Flag</u>	<u>PREF</u>	<u>BASE</u>	<u>SUFF</u>	<u>Description</u>	<u>CPSC</u>	<u>Quantity</u>	<u>Amount</u>
Y	BB5Z	3504	BE	GEAR ASY-STEERING	110101	1	1024.00

DTC Sections: **Mil. Light On =\***

<u>Fla</u>	<u>Test</u>	<u>Malfunction Cd</u>	<u>Malfunction Cd</u>	<u>Monitor</u>	<u>Monitor Cd</u>
<u>g</u>	<u>Type</u>		<u>Description</u>	<u>Cd</u>	<u>Description</u>

Any comments? You can contact  
<< OLE Object: Picture (Metafile) >> [webmaster](#)  
36845

Thanks,

Eric Anderson  
PVT Engineer  
Ford Chicago Assembly  
773.646.7236 desk  
773.729.0337 cell  
[eande181@ford.com](mailto:eande181@ford.com)

## Printable View

Year = MY11

Model = U502

Engine = 3.5L

VIN = 1FMHK8D87BG [REDACTED]

IDS Version = Not Available

 Current DTCs {retrieved 02 February 2011 11:14:34}

DTC	Snap Shot Data	Source
C1B00:86	N/A	<a href="#">ABS</a>
C200B:62	0A33010E330221E03306003B000000000000000000330C94D1118FD1173DD118FFADF40C01E4F40D14FDAAD4	<a href="#">PSCM</a>

 Historic DTCs {retrieved 02 February 2011 11:14:34}

DTC	Snap Shot Data	Source
U0402:68	N/A	<a href="#">ABS</a>
U0253:00	N/A	<a href="#">IC</a>

 DTCs cleared since initial read:

DTC	Snap Shot Data	Source
(ABS)	N/A	<a href="#">ABS</a>
Pass	N/A	<a href="#">ACM</a>
Pass	N/A	<a href="#">APIM</a>
Pass	N/A	<a href="#">ATCM</a>
Pass	N/A	<a href="#">FCIM</a>
Pass	N/A	<a href="#">FLM</a>
Pass	N/A	<a href="#">GPSM</a>
Pass	N/A	<a href="#">HVAC</a>
Pass	N/A	<a href="#">PAM</a>
Pass	N/A	<a href="#">PCM</a>
C200B:2F	0A330103330223203306004A00000000000000000000330C94D1118DD11742D118FF8DF40C03F6F40D0FFDAAD2	<a href="#">PSCM</a>
Pass	N/A	<a href="#">RCM</a>
Pass	N/A	<a href="#">SCCM</a>
Pass	N/A	<a href="#">TPM</a>

Start: Wed Feb 2 10:43:46 EST 2011

## Menu Selection: Inspection and Verification

 IV1: VISUAL INSPECTION

- Verify the customer concern.
- Visually inspect the electronic power assist steering (EPAS) system for obvious signs of mechanical or electrical damage.  
**NOTE:** When inspecting the bellows boots make sure to use a strong light source and an inspection mirror.

## VISUAL INSPECTION CHART

Mechanical	Electrical
Binding or misaligned steering column.	High-current battery junction box (BJB) fuse E (100A), attached to the battery positive terminal
Loose steering column shaft bolts.	Battery Junction Box (BJB) fuse 89 (5A)
Steering column shaft couplings/U-joints	Wiring, terminals or connectors.
Steering gear	
Steering gear bellows boots	
Inner tie rod ends	
Outer tie rod ends	
Tire pressure	

Tires

- Is an obvious cause for an observed or reported concern found?

No

Go to Known Concerns

undefined: undefined

## DTC C200B:2F (PSCM) - Steering Shaft Torque Sensor 1: Signal Erratic

- ▣ B: DTCs C1B00, C200B, C200C, C200D, U2011, U2200 and U3000: Steering Angle Sensor, Steering Shaft Torque Sensor 1, Steering Shaft Torque Sensor 2, Motor and Control Module - Failure or Erratic  
**Normal Operation**

The power steering control module (PSCM) monitors various inputs and outputs of the electronic power assist steering (EPAS) system in order to keep the system operating at peak capacity. Information provided by sensors (steering torque, vehicle speed, vehicle travel distance, etc.) are all compared to programmed and learned information. Likewise, outputs like the motor and steering rack (travel) are tested against programmed and learned information.

**Note:**

If a damaged bellows boot(s) was discovered during Inspection and Verification and this pinpoint test DOES NOT lead to the installation of a new EPAS gear or bellows boot(s), then go to Pinpoint Test K to address the damaged boot(s) before returning the vehicle to the customer.

- ▣ B1: CHECK FOR PREVIOUSLY SET DTCS

- Go to KNOWN CONCERNS.  
Check for DTCs listed in the section: System Related CMDTCs cleared since initial read.
- **Are any of the following DTCs present?**  
**PSCM DTCs C1B00:2F, C1B00:62, C200B:2F, C200B:61, C200B:62, U2011:49, U2011:61, U2200:54, U3000:41, U3000:46, U3000:49.**

Yes

Go to B2.

- ▣ B2: INSPECT EPAS GEAR WIRING HARNESS

- With the vehicle in NEUTRAL, position it on a hoist. Refer to Section 100-02.
- Ignition OFF.
- Thoroughly inspect the wire harness along the top of the EPAS gear for cuts, breaks and pinched wires.
- Disconnect all 3 EPAS gear electrical connectors and inspect them for corrosion, pushed-out pins, bent pins and spread terminals.
- **Is the wire harness undamaged and are all 3 connectors in good condition?**

Yes

CONNECT all 3 EPAS gear electrical connectors.

Go to B3.

- ▣ B3: TEST DRIVE TO CHECK FOR RETURNING DTCS. - Fault outcome

NOTE: Always drive the vehicle in a safe manner according to driving conditions and obey all traffic laws.

- Clear the PSCM DTCs. **Complete**
- Cycle the ignition to OFF and then back to RUN.
- Test drive the vehicle in the following manner:
  - With the engine running/ready, stop the vehicle on an unsealed concrete or asphalt surface (in order to provide adequate friction for a thorough test).
  - With the vehicle in gear and the brakes applied, turn the steering wheel lock-to-lock.
  - Return the steering wheel to the center position and move the vehicle forward approximately 32 cm (1 ft).
  - With the vehicle in gear and the brakes applied, turn the steering wheel lock-to-lock.
  - Return the steering wheel to the center position and move the vehicle forward approximately 32 cm (1 ft).
  - With the vehicle in gear and the brakes applied, turn the steering wheel lock-to-lock.
  - The test drive is complete.
- Press Read Vehicle Information button to retrieve DTC s from the vehicle. NOTE: DTCs may be displayed from previous diagnostic actions.

**Vehicle Information:**

VIN 1FMHK8D87BG [REDACTED]

**System Related CMDTCs Active {retrieved 02 February 2011 11:14:34}**

DTC	Description	Type	Source	Status
C200B:2F	Steering Shaft Torque Sensor 1 : Signal Erratic	KOEC	PSCM	Historic
C200B:62	Steering Shaft Torque Sensor 1 : Signal Compare Failure	KOEC	PSCM	Current
C200B:62	Steering Shaft Torque Sensor 1 : Signal Compare Failure	ODDTCs	PSCM	Unknown

**System Related CMDTCs cleared since initial read:**

- Does DTC C1B00:62, C200B:2F, C200B:61, C200C:2F, C200D:49, U2011:49, U2011:61, U3000:41, U3000:46 and/or U3000:49 return?

**Yes****INSTALL a new EPAS gear.  
Refer to Section 211-02.**

Exit: Wed Feb 2 11:18:57 EST 2011



---

**From:** Napoli, Laura (L.)  
**Sent:** Friday, February 18, 2011 10:35 AM  
**To:** Estes, Eric (E.E.)  
**Subject:** RE: BG [REDACTED] power steering intermittently inoperative

What's the status on this gear?

---

**From:** Estes, Eric (E.E.)  
**Sent:** Thursday, February 10, 2011 1:06 PM  
**To:** Anderson, Eric (H.)  
**Cc:** Napoli, Laura (L.)  
**Subject:** RE: BG [REDACTED] power steering intermittently inoperative

Eric just called Ron Dupratt Ford today and found out the dealer closed the repair order yesterday, so we should have a 700 tag generated tomorrow.  
So we should have the gear back to WPAC by this Monday or Tuesday.

*Eric J Estes*

TRW EPAS Steering Systems  
Quality Specialist  
Hotline ph# 313-317-9358  
Cell ph# 734-560-3493

---

**From:** Anderson, Eric (H.)  
**Sent:** Wednesday, February 09, 2011 12:52 PM  
**To:** Estes, Eric (E.E.)  
**Subject:** RE: BG [REDACTED] power steering intermittently inoperative

Hi Eric:

I just requested this to go back to John Burnett at TRW. Should I edit the request to go to you?

Thanks,

Eric

---

**From:** Estes, Eric (E.E.)  
**Sent:** Wednesday, February 09, 2011 11:47 AM  
**To:** Anderson, Eric (H.); 'Michael Fontana'; 'Simon Malsbury'; 'Robert Kostadina'; 'Hemang Mehta'; 'Nick turovich'; Mrozek, Robert (R.M.); Diez, Timothy (T.P.); Napoli, Laura (L.); 'Geoff Jacks'; 'Phil Browne'; 'Michele Marion'; Jim Loria; Don Blandino-contr; Engelbert Lu; Mathew Alder  
**Subject:** RE: BG [REDACTED] power steering intermittently inoperative

This is the third U502 warranty return on have on my warranty chart with torque sensor codes(BD2 & BD4), I put in a hot request last week for this return, still no 700 tag on this part today, if the claim is closed we should have a 700 tag tomorrow and I have the part overnighted to WPAC where I will perform the level 1 diagnosis and then ship to 26mile for further analysis.

See interactive diagnosis below

<< File: UR0003 interactive diag.pdf >>

*Eric J Estes*

TRW EPAS Steering Systems  
Quality Specialist  
Hotline ph# 313-317-9358  
Cell ph# 734-560-3493

---

**From:** Anderson, Eric (H.)  
**Sent:** Wednesday, February 09, 2011 12:15 PM  
**To:** 'Michael Fontana'; 'Simon Malsbury'; 'Robert Kostadina'; 'Hemang Mehta'; 'Nick turovich'; Estes, Eric (E.E.); Mrozek, Robert (R.M.); Diez, Timothy (T.P.); Napoli, Laura (L.); 'Geoff Jacks'; 'Phil Browne'; 'Michele Marion'  
**Subject:** BC [REDACTED] power steering intermittently inoperative

Hi All:

Please see the ECB claim below. I am collecting more information from the dealer. So far, his story is:

Power steering became inoperative while maneuvering vehicle during slow speed turns in dealer lot. Key cycling would sometimes bring power steering back for 30 seconds to a minute, then steering would become inoperative.

A day after symptoms started, power steering worked fine. Vehicle was driven into repair garage with full assist. These codes were pulled, cleared and returned:

C1B00  
U0253-00  
C200B  
2F  
C200B-62

The traction control light turned on.

The dealership has a bumpy parking lot and has experienced temperature swings from mid 30's to high 50's lately.

I will request the gear back.

Server: **AWS Prod**

Claims loaded through: **08-FEB-2011**

## Claim Detail Report

*Note: All costs are in US dollars*

**Model Year** = 2011; **Claim Key** = 214167

### Vehicle Information

Model Year: 2011

Market Derived: F - FORD

Body/Cab Type: T/WD - 4 DOOR WAGON

Version/Series: T/EF-FORD SERIES

### Claim Information

Document Number: 168057A

Repair Date: 02-FEB-11

Distance: 15

TIS: -1

Drive Type: T/F-4 WHL L/H FULL TIME  
DRIVE

Vehicle Line: T/UB-EXPLORER [2011]

Warranty Start Date:

Production Date: 24-JAN-11

VIN: 1FMHK8D87BG [REDACTED]

**Expense Information**

**Dealer Information:**

Dealer Name RON DUPRATT FORD

Dealer Code: 07955 - \*

Address: 1320 N FIRST ST

City: DIXON

State: CA Zip Code: 95620

Country: USA Region Code: NA

Phone: (707)678-5555

Customer Paid Amount: .00

Deductible Amount: .00

Dealer Paid Amount: .00

Labor Cost: 608.85

Misc. Expense Amount: .00

Part Markup Amount: 292.57

Material Cost: 1024.00

Total Cost Gross: 1632.85

Cust.

Concern H22 - STEERING REQUIRES EXTRA OR UNEVEN EFFORT

Code:

Condition

Code: 42 - DOES NOT OPERATE PROPERLY

Technician 15 (381) RELACED EPAS GEAR SYSTEM, WAS NOT ABLE TO INHALE  
Comment: PSCM, SO PERFORMED AS BUILT DATA ON PSCM. CHECKED  
ALIGNMENT FOUND TOE TO BE OUT OF SPECS ADJUSTED TOE AND  
TEST DROVE VEHICLE VEHICLE DRIVES STRAIGN AND POWER  
STEERING ASSIST OPERATES PROPERLY. NO CODES PRESENT AT THIS  
TIME.

Customer FOUND DURING DEMO DRIVE, P S LOST ASST. TRACTION CONTOL  
Comment: LIGHT CAME ON. CONCERN CORRECTED AFTER DRIVING 2 MILES

<u>Labor Op Code</u>	<u>Labor Op Description</u>	<u>Labor Op Cost</u>
3504E		22.14

3504E45	33.21
3504E47	33.21
MT3504	387.45
MT3001	66.42
3504E8	11.07
MTPSCM	55.35

<b>Causal</b>	<b>Full Part Number</b>			<b>Part</b>	<b>Part</b>	<b>Extended</b>	
<b><u>Flag</u></b>	<b><u>PREF</u></b>	<b><u>BASE</u></b>	<b><u>SUFF</u></b>	<b><u>Description</u></b>	<b><u>CPSC</u></b>	<b><u>Quantity</u></b>	<b><u>Amount</u></b>
Y	BB5Z	3504	BE	GEAR ASY-STEERING	110101	1	1024.00

DTC Sections:

Mil. Light On =\*

<b><u>Flag</u></b>	<b><u>Test</u></b>	<b><u>Malfunction Cd</u></b>	<b><u>Malfunction Cd</u></b>	<b><u>Monitor</u></b>	<b><u>Monitor Cd</u></b>
<b><u>g</u></b>	<b><u>Type</u></b>		<b><u>Description</u></b>	<b><u>Cd</u></b>	<b><u>Description</u></b>

Any comments? You can contact

<< OLE Object: Picture (Metafile) >> [webmaster](mailto:webmaster)

36845

Thanks,

Eric Anderson  
PVT Engineer  
Ford Chicago Assembly  
773.646.7236 desk

773.729.0337 cell  
eande181@ford.com

---

**From:** Napoli, Laura (L.)  
**Sent:** Thursday, March 17, 2011 3:44 PM  
**To:** Anderson, Eric (H.); Mrozek, Robert (R.M.)  
**Subject:** RE: BG [REDACTED] EPAS inop

Anyway you can get snapshot data for the U3000-49?

---

**From:** Anderson, Eric (H.)  
**Sent:** Thursday, March 17, 2011 3:27 PM  
**To:** Mrozek, Robert (R.M.); Napoli, Laura (L.)  
**Subject:** BG [REDACTED] EPAS inop

Hi Rob and Laura:

FYI. Another EPAS with an internal fault. U3000:49-48, U3000:96-C8 and U2011:49-48 present. The technician was friendly and helpful. Gear has been requested to go to John Burnett at TRW.

Server: **AWS Prod**  
Claims loaded through: **16-MAR-2011**

## Claim Detail Report

*Note: All costs are in US dollars*

**Model Year = 2011; Claim Key = 293056**

### Vehicle Information

Model Year: **2011**

Market Derived: **F - FORD**

Body/Cab Type: **T/WD - 4 DOOR WAGON**

Version/Series: **T/EF-FORD SERIES**

Drive Type: **T/F-4 WHL L/H FULL TIME  
DRIVE**

Vehicle Line: **T/UB-EXPLORER [11-12]**

Warranty Start Date:

Production Date: **16-FEB-11**

VIN: **1FMHK8D80BG [REDACTED]**

### Claim Information

Document Number: **012123A**

Repair Date: **08-MAR-11**

Distance: **5**

TIS: **-1**

### Expense Information

**Dealer Information:**

<u>Dealer Name</u> PERFORMANCE FORD	Customer Paid Amount:	.00
Dealer Code: 07530 - *	Deductible Amount:	.00
Address: 906 ROUTE 10 WEST	Dealer Paid Amount:	.00
City: RANDOLPH	Labor Cost:	405.69
State: NJ Zip Code: 07869	Misc. Expense Amount:	.00
Country: USA Region Code: NA	Part Markup Amount:	476.89
Phone: (973)927-6700	Material Cost:	1208.32
	Total Cost Gross:	1614.01

Cust. Concern Code: C50 - OTHER STEERING/HANDLING AND RIDE TROUBLES

Condition Code: 42 - DOES NOT OPERATE PROPERLY

Technician INSPECTED, FOUND NO POWER STEERING. HOOK UP IDS, U2011.PP  
 Comment: TEST IN SHOP MANUAL. REPLACED RACK AND PINION. MT NO LOPS  
 AVAILABLE

Customer UPON PERFORMING VEHICLE PREP FOR DELIVERY FOUND PWR  
 Comment: STEERING ASSIST FAILURE ON DISPLAY

<u>Labor Op Code</u>	<u>Labor Op Description</u>	<u>Labor Op Cost</u>
3504E		21.35
3504E8		10.68
3504E45		32.03
3504E47		32.03
MT3504		213.52
3001A1T	CASTER, CAMBER AND TOE-IN CORRECT	96.08

<u>Causal</u>	<u>Full Part Number</u>	<u>Part</u>	<u>Part</u>	<u>Extended</u>
<u>Flag</u>	<u>PREF</u> <u>BASE</u> <u>SUFF</u>	<u>Description</u>	<u>CPSC</u> <u>Quantity</u>	<u>Amount</u>

Y BB5Z 3504 BE GEAR ASY-STEERING 110101 1 1208.32

**DTC Sections:**

**Mil. Light On =N**

<u>Flag</u>	<u>Test Type</u>	<u>Malfunction Cd</u>	<u>Malfunction Cd Description</u>	<u>Monitor Cd</u>	<u>Monitor Cd Description</u>
N	UNDF	U2011	MODULE TRANSMITTED INVALID DATA (NON SCP)	24	CCM VEHICLE

Any comments? You can contact

<< OLE Object: Picture (Metafile) >> [webmaster](#)

22982

Eric Anderson  
PVT Engineer  
Ford Chicago Assembly  
773.646.7236 desk  
773.729.0337 cell  
[eande181@ford.com](mailto:eande181@ford.com)



---

**From:** Estes, Eric (E.E.)  
**Sent:** Thursday, March 17, 2011 3:54 PM  
**To:** Mrozek, Robert (R.M.)  
**Cc:** Napoli, Laura (L.); Anderson, Eric (H.)  
**Subject:** RE: BG [REDACTED] EPAS inop

I was just going to call this dealer to get the gear back, I will talk to the tech

That's Mr. Estes to you Rob

Eric

---

**From:** Mrozek, Robert (R.M.)  
**Sent:** Thursday, March 17, 2011 3:51 PM  
**To:** Estes, Eric (E.E.)  
**Cc:** Napoli, Laura (L.); Anderson, Eric (H.)  
**Subject:** FW: BG [REDACTED] EPAS inop

ESTES - What can you find out?

*Rob Mrozek*

Electric Power Steering Supervisor  
CD3/D3/D4/U502/Police/Limo EPAS Programs +  
Active Front Steering Applications Engineering  
Ford Motor Company  
Phone: (313) 805-5947  
e-mail: [rmrozek@ford.com](mailto:rmrozek@ford.com)

---

**From:** Anderson, Eric (H.)  
**Sent:** Thursday, March 17, 2011 3:27 PM  
**To:** Mrozek, Robert (R.M.); Napoli, Laura (L.)  
**Subject:** BG [REDACTED] EPAS inop

Hi Rob and Laura:

FYI. Another EPAS with an internal fault. U3000:49-48, U3000:96-C8 and U2011:49-48 present. The technician was friendly and helpful. Gear has been requested to go to John Burnett at TRW.

Server: **AWS Prod**  
Claims loaded through: **16-MAR-2011**

## Claim Detail Report

*Note: All costs are in US dollars*

**Model Year = 2011; Claim Key = 293056**

### Vehicle Information

### Claim Information

Model Year:2011

Document Number:012123A

Market Derived:F - FORD

Repair Date:08-MAR-11

Body/Cab Type:T/WD - 4 DOOR WAGON

Distance:5

Version/Series:T/EF-FORD SERIES

TIS:-1

Drive Type:T/F-4 WHL L/H FULL TIME DRIVE

Vehicle Line:T/UB-EXPLORER [11-12]

Warranty Start Date:

Production Date:16-FEB-11

VIN:1FMHK8D80BG [REDACTED]

**Expense Information**

**Dealer Information:**

Dealer NamePERFORMANCE FORD

Dealer Code:07530 - \*

Address:906 ROUTE 10 WEST

City:RANDOLPH

State:NJ Zip Code:07869

Country:USA Region Code: NA

Phone:(973)927-6700

Customer Paid Amount: .00

Deductible Amount: .00

Dealer Paid Amount: .00

Labor Cost: 405.69

Misc. Expense Amount: .00

Part Markup Amount: 476.89

Material Cost: 1208.32

Total Cost Gross: 1614.01

Cust. Concern Code: C50 - OTHER STEERING/HANDLING AND RIDE TROUBLES

Condition Code: 42 - DOES NOT OPERATE PROPERLY

TechnicianINSPECTED,FOUND NO POWER STEERING. HOOK UP IDS,U2011.PP  
Comment:TEST IN SHOP MANUAL.REPLACED RACK AND PINION. MT NO LOPS  
AVAILABLE

CustomerUPON PERFORMING VEHICLE PREP FOR DELIVERY FOUND PWR  
Comment:STEERING ASSIST FAILURE ON DISPLAY

<u>Labor Op Code</u>	<u>Labor Op Description</u>	<u>Labor Op Cost</u>
3504E		21.35
3504E8		10.68
3504E45		32.03
3504E47		32.03
MT3504		213.52
3001A1T	CASTER, CAMBER AND TOE-IN CORRECT	96.08

<u>Causal Flag</u>	<u>Full Part Number</u>			<u>Part Description</u>	<u>Part CPSC</u>	<u>Part Quantity</u>	<u>Extended Amount</u>
	<u>PREF</u>	<u>BASE</u>	<u>SUFF</u>				
Y	BB5Z	3504	BE	GEAR ASY-STEERING	110101	1	1208.32

**DTC Sections:** Mil. Light On =N

<u>Flag</u>	<u>Test Type</u>	<u>Malfunction Cd</u>	<u>Malfunction Cd Description</u>	<u>Monitor Cd</u>	<u>Monitor Cd Description</u>
N	UNDF	U2011	MODULE TRANSMITTED INVALID DATA (NON SCP)	24	CCM VEHICLE

Any comments? You can contact  
 << OLE Object: Picture (Metafile) >> [webmaster](mailto:webmaster)  
 22982

Eric Anderson  
 PVT Engineer  
 Ford Chicago Assembly  
 773.646.7236 desk  
 773.729.0337 cell  
[eande181@ford.com](mailto:eande181@ford.com)

---

**From:** Napoli, Laura (L.)  
**Sent:** Friday, February 18, 2011 10:34 AM  
**To:** Mrozek, Robert (R.M.)  
**Subject:** RE: Explorers with inoperative steering

Will do. It bothers me that Eric is sending these notes out and including his management. I think he's just trying to put the pressure on TRW, and I don't want to reply to that and defend TRW. So I'm going to call him to discuss these notes with him. He has been invited to the B91 meetings. I can update him weekly on our warranty meetings.

---

**From:** Mrozek, Robert (R.M.)  
**Sent:** Wednesday, February 16, 2011 3:38 PM  
**To:** Napoli, Laura (L.)  
**Subject:** RE: Explorers with inoperative steering  
**Importance:** High

We need to figure out how to contain these type of notes by communicating to the PVT of what we are doing to fix these issues. You need to lead this please. Let's talk when you get back.

*Rob Mrozek*

Electric Power Steering Supervisor  
CD3/D3/D4/U502/Police/Limo EPAS Programs +  
Active Front Steering Applications Engineering  
Ford Motor Company  
Phone: (313) 805-5947  
e-mail: rmrozek@ford.com

---

**From:** Anderson, Eric (H.)  
**Sent:** Wednesday, February 16, 2011 2:58 PM  
**To:** Napoli, Laura (L.); Estes, Eric (E.E.); 'Michael Fontana'; 'Simon Malsbury'; 'Robert Kostadina'; 'Hemang Mehta'; 'Nick turovich'; Mrozek, Robert (R.M.); Diez, Timothy (T.P.); 'Geoff Jacks'; 'Phil Browne'; 'Michele Marion'; 'Jim Loria'; 'Don Blandino-contr'; 'Engelbert Lu'; 'Mathew Alder'  
**Cc:** Docimo, Tony (A.F.); Cantrell, David (D.D.)  
**Subject:** RE: Explorers with inoperative steering

Hi All:

Please see the latest power steering inoperative claim. It is the fifth suspected internal gear fault known to CAP. The list to date is:

BGA14928: U3000:96  
BGA10846: U0253:00-28, U2011:49-08  
BGA14928: U3000:96  
BGA22399: U3000:61 discovered in plant  
BGA18724: C200B:2F

CAP is working toward 50R per 1000 units for the Explorer as a whole vehicle. Five inverted delta parts that stop functioning within weeks of vehicle launch is unacceptable. What is TRW doing to fix these problems? What can CAP do to detect faulty gears before our customers experience steering assist loss? Please explain your fixes as soon as possible.

Thanks,

Eric

**Attachments : 0**

**Report# :** BBLAA025 NHL **Received:** 02/12/2011  
**CCRG/EPRC:** **Reviewed Status:** **Date:**  
**Vehicle:** 2011,EXPLORER 4X4 (U502),4 DOOR **Build Date:**01/20/2011  
,MP,1FMHK8F8XBG [REDACTED]  
**Odometer :** 303 M **Engine:** 3.5L CYCLO **Calibration** BUB1ST0A  
**:**  
**Transmission:** 6F55 **Axle:** **A/C:** YES  
**Dealer:** USA 00089 Koons Ford of Annapolis, Inc. **Phone#:** (410) 266-3087  
**City:** Annapolis **State:** Maryland **Country :** USA  
**Originator:** JAMES MORELAND  
**Symptom:** 3 03 1 55 CHASS.,STRG/HANDLING ,FUNCTION,LOSS OF STRG  
**Status:**  
**VFG:** V89 RIDE & HANDLING  
**Additional Symptom:** U3000:96  
**Fix:** **Causal Component :**  
**Condition Code:**

**Hotliner:** C ! BISHO41 **Phone:** 313 317-9359 **Regn Cd:** N4 Washington  
**Engineering:** **Phone:** **TAR:**  
**Dlr Contact:** JAMES MORELAND **Phone:** 410 266-3087 **Title Cde:** T

**DTCs:**  
KOEO:U3000:96  
KOEC:  
KOER:

**Comments :**

REPAIR 02/12/2011 01:58PM CHRIS BISHOP MSS - FCSD - TECH SVC HOTLINE

WEB FORM DATA - CONCERN: NO POWER STEERING DIAGNOSTICS:  
SELF TEST

VISUAL INSPECTION FOUND CONNECTOR ON GEAR DISCONNECTED  
PARTS

REPLACED:: NONE TECH QUESTION: CODE U3000 96 LEADS TO  
REPLACEMENT

OF EPAS GEAR W/NO PINPOINT TESTS IS THIS CORRECT, VEHICLE WAS  
DX TO

OUR DEALER SAID P/S WENT OUT IN OUR PARKING LOT, TESTED AND  
FOUND

CONNECTOR 1453A DISCONNECTED. PLUGGED BACK IN BUT NO P/S  
AND CODE AND

MESSAGE CENTER WILL NOT CLEAR OUT. WERE YOU ABLE TO VERIFY  
THE

CONCERN? YES IS THERE AN APPROPRIATE PINPOINT TEST IN THE  
WSM FOR

THIS CONCERN? YES WAS THE PINPOINT TEST FOLLOWED? YES

**RECOMM 02/12/2011 01:58PM CHRIS BISHOP MSS - FCSD - TECH SVC HOTLINE**

JAMES, YOU ARE CORRECT. IF THE U3000:96 IS PRESENT AS A HARD  
FAULT

THEN STEERING GEAR REPLACEMENT IS REQUIRED. THIS CODE  
INDICATES THAT

THE ELECTRONIC STEERING GEAR HAS EXPERIENCED AN INTERNAL  
FAULT.

RECOMMEND REPLACING THE GEAR AS NEEDED THEN RETESTING  
FOR NORMAL

OPERATION.

---

**From:** Napoli, Laura (L.)  
**Sent:** Wednesday, February 09, 2011 3:23 PM  
**To:** Anderson, Eric (H.); Estes, Eric (E.E.); 'Michael Fontana'; 'Simon Malsbury'; 'Robert Kostadina'; 'Hemang Mehta'; 'Nick turovich';  
Mrozek, Robert (R.M.); Diez, Timothy (T.P.); 'Geoff Jacks'; 'Phil Browne'; 'Michele Marion'; 'Jim Loria'; 'Don Blandino-contr';  
'Engelbert Lu'; 'Mathew Alder'  
**Subject:** RE: Explorers with inoperative steering

Please see my comments below...

---

**From:** Anderson, Eric (H.)  
**Sent:** Wednesday, February 09, 2011 4:14 PM  
**To:** Estes, Eric (E.E.); 'Michael Fontana'; 'Simon Malsbury'; 'Robert Kostadina'; 'Hemang Mehta'; 'Nick turovich'; Mrozek, Robert (R.M.); Diez, Timothy (T.P.); Napoli, Laura (L.); 'Geoff Jacks'; 'Phil Browne'; 'Michele Marion'; 'Jim Loria'; 'Don Blandino-contr'; 'Engelbert Lu'; 'Mathew Alder'  
**Subject:** Explorers with inoperative steering

Hi All:

Please give me an update on root cause for these U502 units that experienced steering assist loss, if you have one. If the part has yet to be returned for analysis and root cause is unknown, please note it.

BG [REDACTED]: Petoskey, MI. Inoperative because of contamination in B3A motor relay.  
B3A caused by contamination on motor relay. Source of contamination at Tyco unknown.

BG [REDACTED]: Ripley, WV. Root cause unknown.  
B3A. Part shipped to Tyco but not yet received. Cause of B3A will be known by COB tomorrow once relay is analyzed by Tyco.

BG [REDACTED] Chicago Assembly Plant. Gear hand carried to TRW for analysis. Root cause unknown.  
B91. Unable to duplicate. Root cause not yet known. Suspect gear was installed into a 2011 U502 and TRW is trying to duplicate issue before HW is sent out for analysis.

BG [REDACTED] Dixon, CA. Intermittently inoperative. Root cause unknown.  
BD2 & BD4. Torque Sensor Faults. Gear not yet returned to TRW. Root cause unknown.

Thanks,

Eric Anderson  
PVT Engineer  
Ford Chicago Assembly  
773.646.7236 desk  
773.729.0337 cell  
eande181@ford.com

---

**From:** Napoli, Laura (L.)  
**Sent:** Thursday, March 10, 2011 2:26 PM  
**To:** 'Michael Fontana'; Estes, Eric (E.E.); John Burnett; Robert Kostadina  
**Subject:** RE: FW: 2011 Explorer Management Lease Vehicle

Loss of assist twice when he started his car in the morning.

-----Original Message-----

From: Michael Fontana [mailto:Michael.Fontana@TRW.COM]  
Sent: Thursday, March 10, 2011 2:22 PM  
To: Estes, Eric (E.E.); Napoli, Laura (L.); John Burnett; Robert Kostadina  
Subject: RE: FW: 2011 Explorer Management Lease Vehicle

Not sure. Why was this vehicle initially suspected for a PSCM issue if there were no DTCs?

>>> "Napoli, Laura (L.)" <[lnapoli@ford.com](mailto:lnapoli@ford.com)> 3/10/2011 2:10 PM >>>

Data on Doug's car with 2 B3A's and 2 E66's. Confused as to how he had 2 B3A's in the fault store and no Ford DTCs. See powerpoint...

-----Original Message-----

From: Napoli, Laura (L.)  
Sent: Thursday, March 10, 2011 12:35 PM  
To: 'Michael Fontana'; Estes, Eric (E.E.); John Burnett; Robert Kostadina  
Subject: RE: FW: 2011 Explorer Management Lease Vehicle

How many E66 did he have?

-----Original Message-----

From: Michael Fontana [mailto:Michael.Fontana@TRW.COM]  
Sent: Thursday, March 10, 2011 10:02 AM  
To: Estes, Eric (E.E.); Napoli, Laura (L.); John Burnett; Robert Kostadina  
Subject: Re: FW: 2011 Explorer Management Lease Vehicle

Laura,

I checked out Steve Baker's U502 vehicle this morning and confirmed that there were (x3) B3a. There is no C69 because there were many journey's between the two. Please let the team know if you choose to change out this gear.

Best Regards,

Michael Fontana  
Product Engineer - TRW Electronics  
Electric Power Steering  
C: (586) 337-6343



D: (586) 232-8533

>>> "Napoli, Laura (L.)" <[lnapoli@ford.com](mailto:lnapoli@ford.com)> 3/9/2011 1:42 PM >>>

Mike, Rob, John,

I have a loss of assist vehicle in the management lease fleet that's with the vehicle owner in Sterling Heights (Mound and 17mi). It has assist now, but is a suspect B3A. I'd like to know what codes are inside the gear. Can one of you go to Sterling Axle and visit Steve Baker to pull codes out of his vehicle this week? I don't want to have to wait til I go up there on Tuesday.

Please let me know who can go and when. His contact info and hours are below.

> \_\_\_\_\_  
> From: Baker, Steven (S.W.)  
> Sent: Wednesday, March 09, 2011 12:01 PM  
> To: Napoli, Laura (L.)  
> Subject: RE: 2011 Explorer Management Lease Vehicle

>  
> I am here every day, 6am - 4:30pm (at the earliest). Just give me a  
> little heads up and I will be available.

>  
> Steve Baker  
> Production Control Team Manager  
> Sterling Axle Plant  
> (586) 826-5290

>  
>  
> \_\_\_\_\_  
> From: Napoli, Laura (L.)  
> Sent: Wednesday, March 09, 2011 12:00 PM  
> To: Baker, Steven (S.W.)  
> Subject: RE: 2011 Explorer Management Lease Vehicle

>  
> Are you ok with me sending someone from TRW out there this week? Do  
> any days/times not work for you?

>  
>  
> \_\_\_\_\_  
> From: Baker, Steven (S.W.)  
> Sent: Wednesday, March 09, 2011 9:57 AM  
> To: Napoli, Laura (L.)  
> Subject: RE: 2011 Explorer Management Lease Vehicle

>  
> Not a problem.  
>  
> My cell is (248) 885-0391. Just let me know when you are close and  
> I'll be ready.  
>  
> Steve Baker

> Production Control Team Manager  
> Sterling Axle Plant  
> (586) 826-5290  
>  
>  
> \_\_\_\_\_  
> From: Napoli, Laura (L.)  
> Sent: Wednesday, March 09, 2011 9:29 AM  
> To: Baker, Steven (S.W.)  
> Subject: 2011 Explorer Management Lease Vehicle

>  
> Steve,  
>  
> I am the EPAS engineer for the 2011 Explorer. I was reading the 1MIS  
> verbatims and see that you experienced a loss of assist on your new  
> Explorer. Would you be available on Tuesday next week for me to come  
> by and pull data off of your steering gear? It would take about  
> 10min. I'll be up in the Sterling Heights area on Tuesday driving up  
> Mound to 26mile. If there's a time that works for you, I can make it  
> work with my drive.

>  
>  
> Regards,  
>  
> Laura Napoli  
> U502 EPAS  
> Ford Motor Company  
> Cube: 2B-G66 PDC  
> Phone: 313.323.0634  
> Mobile: 313.805.0482  
>

---

**From:** Annadi, Hari (H.)  
**Sent:** Tuesday, May 24, 2011 7:54 AM  
**To:** Mrozek, Robert (R.M.); Napoli, Laura (L.)  
**Cc:** Anderson, Eric (H.); Estes, Eric (E.E.)  
**Subject:** RE: STEERING V87 ALL 09-10 - Report Summary(s) from a GCQIS Query Disposition  
**Attachments:** RE: 2011 Exp - BG [REDACTED] - Loss of steering assist, 2947 mi, BD 3/3/11

Steve Beulow.

PI read stapled note. Thanks.

---

**From:** Mrozek, Robert (R.M.)  
**Sent:** Tuesday, May 24, 2011 7:47 AM  
**To:** Annadi, Hari (H.); Napoli, Laura (L.)  
**Cc:** Anderson, Eric (H.); Estes, Eric (E.E.)  
**Subject:** RE: STEERING V87 ALL 09-10 - Report Summary(s) from a GCQIS Query Disposition

Who is the plant FCSD person?

*Rob Mrozek*

Electric Power Steering Supervisor  
CD3/D3/D4/U502/Police/Limo EPAS Programs +  
Active Front Steering Applications Engineering  
Ford Motor Company  
Phone: (313) 805-5947  
e-mail: [rmrozek@ford.com](mailto:rmrozek@ford.com)

---

**From:** Annadi, Hari (H.)  
**Sent:** Tuesday, May 24, 2011 7:45 AM  
**To:** Mrozek, Robert (R.M.); Napoli, Laura (L.)  
**Cc:** Anderson, Eric (H.); Estes, Eric (E.E.)  
**Subject:** RE: STEERING V87 ALL 09-10 - Report Summary(s) from a GCQIS Query Disposition

Understood. I did have a conversation with Laura about this yesterday. We need to communicate this to the FCSD rep in the plant so he does not open an Emerging concern with Chassis as the lead function. I am sure your team will be supporting Electrical to root cause.

---

**From:** Mrozek, Robert (R.M.)  
**Sent:** Tuesday, May 24, 2011 7:40 AM  
**To:** Annadi, Hari (H.); Napoli, Laura (L.)  
**Cc:** Anderson, Eric (H.); Estes, Eric (E.E.)  
**Subject:** RE: STEERING V87 ALL 09-10 - Report Summary(s) from a GCQIS Query Disposition

We get all these CQIS reports. Intermittent is typically an electrical issue and not related to EPAS. We design EPAS not to deliver assist intermittently. Due to severity of intermittent assist, we will completely pull assist. So this is likely a wiring/connection/grounding issue.

Laura is working with PVT on this one.

*Rob Mrozek*

Electric Power Steering Supervisor  
CD3/D3/D4/U502/Police/Limo EPAS Programs +  
Active Front Steering Applications Engineering  
Ford Motor Company  
Phone: (313) 805-5947  
e-mail: [rmrozek@ford.com](mailto:rmrozek@ford.com)

---

**From:** Annadi, Hari (H.)  
**Sent:** Tuesday, May 24, 2011 7:34 AM  
**To:** Napoli, Laura (L.); Mrozek, Robert (R.M.)  
**Subject:** FW: STEERING V87 ALL 09-10 - Report Summary(s) from a GCQIS Query Disposition

CQIS for intermittent loss of assist.

---

**Attachments :** 0

<b>Report# :</b>	BETBK025 NHL	<b>Received:</b>	05/20/2011
<b>CCRG/EPRC:</b>		<b>Reviewed Status:</b>	<b>Date:</b>
<b>Vehicle:</b>	2011,EXPLORER 4X4 (U502),4 DOOR ,MP,1FMHK8B8XBG [REDACTED]	<b>Build Date:</b>	03/03/2011
<b>Odometer :</b>	2,947 M	<b>Engine:</b>	3.5L CYCLO
<b>Transmission:</b>	6F50	<b>Axle:</b>	<b>Calibration:</b>
<b>Dealer:</b>	USA 08305 Evergreen Ford	<b>Phone#:</b>	YES (425) 392-6900
<b>City:</b>	Issaquah	<b>State:</b>	Washington
<b>Originator:</b>	JASON DESCHAMBAULT	<b>Country :</b>	USA
<b>Symptom:</b>	3 03 1 50 CHASS.,STRG/HANDLING ,FUNCTION,HIGH EFFORT		
<b>Status:</b>			
<b>VFG:</b>	V87 STEERING		
<b>Additional Symptom:</b>	INT. LOSS OF STEERING		
<b>Fix:</b>	<b>Causal Component :</b>	--	
<b>Condition Code:</b>			

**Hotliner:** MHINDERE

**Phone:** 000 337-9292

**Regn Cd:** W5 Seattle

**Engineering:**

**Phone:**

**TAR:**

**Dlr Contact:** JASON DESCHAMBAULT

**Phone:** 425 392-6900

**Title Cde:** T

**DTCs:**

KOEO:

KOEC:

KOER:

**Comments**

:

**REPAIR** 05/20/2011 03:11PM MICHAEL HINDERER MSS - FCSD - TECH SVC HOTLINE  
WEB FORM DATA - CONCERN: CUSTOMER LOST STEERING ASSIST AT 35 MPH,  
DIDNT RETURN UNTILL ENGINE SHUT OFF AND RETSTARTED. DIAGNOSTICS:  
CHECKED OASIS, CHECKED FOR DTCS PASS. PARTS REPLACED:: NONE TECH  
QUESTION: ROAD TESTED, UNABLE TO VERIFY CONCERN. ANY KNOWN  
CONCERNS? WERE YOU ABLE TO VERIFY THE CONCERN? NO IS THERE AN  
APPROPRIATE PINPOINT TEST IN THE WSM FOR THIS CONCERN? YES WAS THE  
PINPOINT TEST FOLLOWED? NO

**RECOMM** 05/20/2011 03:11PM MICHAEL HINDERER MSS - FCSD - TECH SVC HOTLINE  
JASON, TO ACTIVATE THE EPAS SYSTEM, A 12-VOLT HOT AT ALL TIMES AND A  
12-VOLT IGNITION/RUN INPUT TO THE PSCM IS REQUIRED. THE PSCM THEN  
MONITORS THE HS-CAN TO DETERMINE IF THE VEHICLE IS OPERATING IN A  
MANNER CAPABLE OF SUPPORTING THE EPAS SYSTEM. THE PSCM USES INPUTS  
FROM VARIOUS MODULES OVER THE HS-CAN, THE STEERING TORQUE SENSOR  
AND  
THE MOTOR TO DETERMINE THE AMOUNT OR LEVEL OF ASSIST PROVIDED BY  
THE  
EPAS SYSTEM. INSPECT PINFIT AND CONNECTION AT THE PSCM. VERIFY  
THERE ARE NO CONCERNS WITH A LOSS OF POWER TO THE PSCM. GIVEN THE  
CONCERN IS INTERMITTENT, A CONNECTION CONCERN IS POSSIBLE.

---

---

**From:** Perri, Ron (R.J.)  
**Sent:** Monday, May 23, 2011 3:19 PM  
**To:** Napoli, Laura (L.); Annadi, Hari (H.); Mrozek, Robert (R.M.); Pascarella, Michael (M.)  
**Subject:** RE: 2011 Exp - BG [REDACTED] - Loss of steering assist, 2947 mi, BD 3/3/11

[Hari, should a SSM be communicated to reduce incorrect gear replacements?](#)  
[Thanks.](#)

Ron Perri  
Manager, Chassis - EPAS and Upper Steering, Systems & Core  
2B-F77, Product Development Center  
cell 313-805-0680  
rperri@ford.com

---

**From:** Napoli, Laura (L.)  
**Sent:** Monday, May 23, 2011 2:03 PM  
**To:** Annadi, Hari (H.); Perri, Ron (R.J.); Mrozek, Robert (R.M.); Pascarella, Michael (M.)  
**Subject:** RE: 2011 Exp - BG [REDACTED] - Loss of steering assist, 2947 mi, BD 3/3/11

No. The gear was not changed out on this one. It sounds like a wiring issue to me. PVT said they lost assist and it came back on the next key cycle with no DTC's. There's a new wiring issue popping up that the PVT is investigating with the electrical team. We need to start directing dealers to look for this wiring problem when they have no communication with the gear or intermittent assist with no EPAS DTC's.

---

**From:** Annadi, Hari (H.)  
**Sent:** Monday, May 23, 2011 12:12 PM  
**To:** Perri, Ron (R.J.); Mrozek, Robert (R.M.); Pascarella, Michael (M.); Napoli, Laura (L.)  
**Subject:** RE: 2011 Exp - BG [REDACTED] - Loss of steering assist, 2947 mi, BD 3/3/11

[Do we have any of these parts back?](#)

---

**From:** Perri, Ron (R.J.)  
**Sent:** Monday, May 23, 2011 10:12 AM  
**To:** Annadi, Hari (H.); Mrozek, Robert (R.M.); Pascarella, Michael (M.); Napoli, Laura (L.)  
**Subject:** FW: 2011 Exp - BG [REDACTED] - Loss of steering assist, 2947 mi, BD 3/3/11

[This concern is being added to the emerging issues list](#)

Ron Perri  
Manager, Chassis - EPAS and Upper Steering, Systems & Core  
2B-F77, Product Development Center  
cell 313-805-0680

---

**From:** Gubing, William (Bill.)  
**Sent:** Monday, May 23, 2011 10:10 AM  
**To:** Menz, Kenneth (K.C.); Perri, Ron (R.J.)  
**Subject:** FW: 2011 Exp - BG [REDACTED] - Loss of steering assist, 2947 mi, BD 3/3/11

FYI

Bill

---

**From:** Buelow, Steve (S.E.)  
**Sent:** Monday, May 23, 2011 10:02 AM  
**To:** Adamczyk, David (D.W.); Bollwahn, Bryce (B.A.); Centlivre, James (J.C.); Cheatham, Sandy (.); Cittadino, Lisa (L.C.); Collins, Kevin (K.E.); Gagnier, Kathryn (K.A.); Gilewski, David (D.); Gillanders, Eric (E.S.); Gray, Carl (C.L.); Gubing, William (Bill.); Hays, Andy (A.R.); Krochmalny, Kevin (K.); Mann, Mickey (N.S.); McClain, Shawn (S.M.); Pogorzelski, John (J.M.); Rodgers, Chuck (.); Saleh, Salim (S.A.); Sellers, Gary (G.T.); Shaukat, Nadeem (N.S.); Simkus, Walter (W.A.); Sokolowski, Todd (T.M.); Thornsberry, Joel (J.A.); Willis, Mark (M.E.); Wong, Vicki (V.A.); Acuna, Aaron (A.A.); Allman, Jan (J.E.); Bell, Tim (.); Bergeron, Matthew (M.C.); Bisaga, Richard (R.); Boykin, George (G.); Boykins, Michael (M.); Bustamante, Chris (C.T.); Cantrell, David (D.D.); Carter, Tracy (T.); Ciotti, Steven (S.R.); Davis, Charlene (C.); Devine, Robert (R.M.); Docimo, Tony (A.F.); Ferguson, Hugh (H.); Gagnier, Scott (S.W.); Greenwell, R (R.); Guyton, MzJenny (J.); Hernandez, Thomas (T.); Herron, Micheal (M.C.); Inglis, Steve (S.D.); Iqbal, Khurram (K.); Jones, Frederick (F.L.); Little, Janie (J.); Martin, Kenneth (K.A.); Matlock, Douglas (D.); McElroy, Darin (D.L.); McKernan, Patrick (P.J.); Miller, Melinda (M.S.); Moore, Chikynda (D.); Moskwa, Larry (L.M.); Perkins, John (J.E.); Russell, David (D.A.); Rutovic, Nick (N.); Sarkisian, Mark (Z.); Talbott, Larry (J.L.); Turner, Bridgette (B.); Turner, Patrice (P.T.); Vandergroef, Cornelius (C.); Washington, Kellie (K.S.); Wertman, David Brian (D.B.); Westbrook, Dori (D.); Williams, Erik (E.C.); Williams, Gregory (G.M.); Wyatt, Kimberly (K.D.); Zroback, David (D.P.); Armstrong, Miya (M.); Buerger, Robert (R.G.); Evans, Kayekethia (K.); Gibson, Renelda (R.); Lakomek, Scott (S.); Napier, S (S.); Ornelas, Demetrio (D.); Ratliff, Kathy (K.); Scheldberg, Gary (G.D.); Stonewall, Wendy (M.); Svetich, Chris (C.); Torian, Jason (J.B.); Anderson, Eric (H.); Berzeri, Marcello (M.); Cassata, Joe (J.); Chamberlain, Steve (J.); Edwards, Monty (M.R.); Farmer, Marty (M.F.); Feder, Andrew (A.); Gerrard, Ryan (R.P.); Iannotti, Jason (J.R.I.); Ickes, Walt (W.D.); Issa, Ibrahim (I.M.); Jackson, Bradley (B.G.); Logli, Michael (M.A.); Morgan, Anthony (A.); Olsson, Paul (P.C.); Polaski, Mike (M.S.); Porter, Alan (A.T.); Rapiz, Noreen (N.G.); Santilli, Rennie (R.); Smith, Erin (E.); Sridhara, Raghu (R.); Trygar, Mike (M.); Vargo, Rebecca (R.L.); Widrick, Brad (B.A.); Young, Richard (R.C.); Yu, Eric (E.); Buelow, Steve (S.E.)  
**Subject:** FW: 2011 Exp - BG [REDACTED] - Loss of steering assist, 2947 mi, BD 3/3/11

This is the 5th report in the last 3 weeks. This concern is being added to the emerging issues list.

**-The Customer Defines Quality-**

*Steve Buelow - Ford Motor Company*

FCSD Program Manager-  
Taurus/Taurus SHO/Lincoln MKS/Explorer  
Chicago Assembly PVT Office, COE  
773-646-7495 DialNet 686-7495  
Cell 773-726-0808 sbuelow@ford.com

"Quality means doing it right when no one is looking." - Henry Ford

**From:** SBUELOW@ford.com [mailto:SBUELOW@ford.com]  
**Sent:** Monday, May 23, 2011 8:59 AM  
**To:** Buelow, Steve (S.E.)  
**Subject:** 2011 Exp - BG [REDACTED] - Loss of steering assist, 2947 mi, BD 3/3/11

**Attachments :** 0

**Report# :** BETBK025 NHL  
**CCRG/EPRC:** **Reviewed Status:**  
**Vehicle:** 2011,EXPLORER 4X4 (U502),4 DOOR  
,MP,1FMHK8B8XBG [REDACTED] **Build Date:** 03/03/2011  
**Odometer :** 2,947 M **Engine:** 3.5L  
CYCLO **Calibration:**  
**Transmission:** 6F50 **Axle:** **A/C:** YES  
**Dealer:** USA 08305 Evergreen Ford **Phone#:** (425) 392-  
6900  
**City:** Issaquah **State:** Washington **Country :** USA  
**Originator:** JASON DESCHAMBAULT  
**Symptom:** 3 03 1 50 CHASS.,STRG/HANDLING ,FUNCTION,HIGH EFFORT  
**Status:**  
**VFG:** V87 STEERING  
**Additional Symptom:** INT. LOSS OF STEERING  
**Fix:** **Causal Component :**  
**Condition Code:**

**Hotliner:** MHINDERE **Phone:** 000 337-9292 **Regn Cd:** W5 Seattle  
**Engineering:** **Phone:** **TAR:**  
**Dlr Contact:** JASON DESCHAMBAULT **Phone:** 425 392-6900 **Title Cde:** T

**DTCs:**  
KOEO:  
KOEC:  
KOER:

**Comments**

:  
REPAIR 05/20/2011 03:11PM MICHAEL HINDERER MSS - FCSD - TECH SVC HOTLINE  
WEB FORM DATA - CONCERN: CUSTOMER LOST STEERING ASSIST AT 35 MPH,  
DIDNT RETURN UNTILL ENGINE SHUT OFF AND RETSTARTED. DIAGNOSTICS:  
CHECKED OASIS, CHECKED FOR DTCS PASS. PARTS REPLACED:: NONE TECH



QUESTION: ROAD TESTED, UNABLE TO VERIFY CONCERN. ANY KNOWN CONCERNS? WERE YOU ABLE TO VERIFY THE CONCERN? NO IS THERE AN APPROPRIATE PINPOINT TEST IN THE WSM FOR THIS CONCERN? YES WAS THE PINPOINT TEST FOLLOWED? NO

**RECOMM 05/20/2011 03:11PM MICHAEL HINDERER MSS - FCSD - TECH SVC HOTLINE**

JASON, TO ACTIVATE THE EPAS SYSTEM, A 12-VOLT HOT AT ALL TIMES AND A 12-VOLT IGNITION/RUN INPUT TO THE PSCM IS REQUIRED. THE PSCM THEN MONITORS THE HS-CAN TO DETERMINE IF THE VEHICLE IS OPERATING IN A MANNER CAPABLE OF SUPPORTING THE EPAS SYSTEM. THE PSCM USES INPUTS FROM VARIOUS MODULES OVER THE HS-CAN, THE STEERING TORQUE SENSOR AND

THE MOTOR TO DETERMINE THE AMOUNT OR LEVEL OF ASSIST PROVIDED BY THE

EPAS SYSTEM. INSPECT PINFIT AND CONNECTION AT THE PSCM. VERIFY THERE ARE NO CONCERNS WITH A LOSS OF POWER TO THE PSCM. GIVEN THE CONCERN IS INTERMITTENT, A CONNECTION CONCERN IS POSSIBLE.

---

**From:** Napoli, Laura (L.)  
**Sent:** Thursday, March 17, 2011 10:23 AM  
**To:** Mrozek, Robert (R.M.)  
**Subject:** RE: U502 TS Warranty Bent Rotor

Ok, I'll talk to them about it. and I agree...the gage would haev to be at Marion because there's no evidence at this time that the bent finger is coming out of Rogersville. I'll talk to Greg Austin to come up with something at the station.

We are setting up the rabbit now to verify that visual inspection catches it.

---

**From:** Mrozek, Robert (R.M.)  
**Sent:** Thursday, March 17, 2011 10:19 AM  
**To:** Napoli, Laura (L.)  
**Subject:** RE: U502 TS Warranty Bent Rotor

Good progress still a few open items. Need PCA that is not visual inspection. Some type of gage at MAO for bent finger would be acceptable.

*Rob Mrozek*

Electric Power Steering Supervisor  
CD3/D3/D4/U502/Police/Limo EPAS Programs +  
Active Front Steering Applications Engineering  
Ford Motor Company  
Phone: (313) 805-5947  
e-mail: rmrozek@ford.com

---

**From:** Napoli, Laura (L.)  
**Sent:** Thursday, March 17, 2011 9:59 AM  
**To:** Mrozek, Robert (R.M.)  
**Subject:** FW: U502 TS Warranty Bent Rotor

Updated TS 8D and answer on if it's possible for a bent finger to pass the MP tooling station with the half moon tooling design. Answer is basically no. Looks like gap is smaller than width of finger. See below...

---

**From:** Angie Caudill [mailto:Angie.Caudill@TRW.COM]  
**Sent:** Thursday, March 17, 2011 9:45 AM  
**To:** Ausband, Andy; Austin, Greg; Craig, Carl; Estes, Eric (E.E.); Fleenor, Anthony; Napoli, Laura (L.); Williams, Todd  
**Subject:** RE: U502 TS Warranty Bent Rotor

Laura,  
The requested action was added to the 8D. Please find it attached below.

1. Is it possible to rotate the part in a way that the bent finger is located in the gap of the half moon and a bad part would pass?

Yes, but it would take a specially bent vane (in the shape of an "L") for this to happen.

Are you saying the half moon closes so the only way a finger can be bent and pass the MP tooling station is if the finger is bent so it is vertical and sits inside the ID of the tool parallel to the shaft? Yes, the only way that a bent finger could actually fit into the gap of the half moon is to be bent so that it is vertical and sitting inside the ID of the tool. Please see the pictures below. We will take a look at the tooling and see if we can reduce the gap to eliminate this possibility.



Thanks,  
Angie

>>> "Napoli, Laura (L.)" <lnapoli@ford.com> 3/16/2011 3:37 PM >>>  
Angie,

Please add the following action to the 8D...

Rogersville to meet with MAO quality team at Marion plant to investigate possible source of bent finger at full MAO facility. This will include incoming IPAs once a shipment is received all the way until IPA is assembled into gear and TS cover is secured. This should be the same type of deep dive already done at Rogersville.

Also, regarding my first question from yesterday...

1. Is it possible to rotate the part in a way that the bent finger is located in the gap of the half moon and a bad part would pass?

Yes, but it would take a specially bent vane (in the shape of an "L") for this to happen.

Are you saying the half moon closes so the only way a finger can be bent and pass the MP tooling station is if the finger is bent so it is vertical and sits inside the ID of the tool parallel to the shaft?

Thanks Angie.

---

**From:** Angie Caudill [mailto:Angie.Caudill@TRW.COM]

**Sent:** Wednesday, March 16, 2011 12:50 PM

**To:** Estes, Eric (E.E.); Napoli, Laura (L.); Andy Ausband; Anthony Fleenor; Carl Craig; Greg Austin; Todd Williams

**Subject:** RE: U502 TS Warranty Bent Rotor

All,  
Please find attached the latest 8D updated with actions from today's meeting. Please let me know if there are any corrections required.

Thank you,

Angie Caudill  
TRW Pinion and IPA Department Quality Engineer  
423.272.4118 (Office)

>>> "Napoli, Laura (L.)" <lnapoli@ford.com> 3/15/2011 8:47 AM >>>  
Angie,

Need the following questions answered in the 10am meeting tomorrow...

1. Is it possible to rotate the part in a way that the bent finger is located in the gap of the half moon and a bad part would pass?
2. I see that the bent finger is near the weld spot on the picture you sent. Is this true in all parts?
3. Can you see a bent rotor when setting the gap measurement during assy? I'm assuming no. Why not?
4. Can we build a rabbit and run it through Marion to see if the visual inspectors catch it? We can discuss details on how to do this tomorrow.

Regards,

*Laura Napoli*

U502 EPAS  
Ford Motor Company  
Cube: 2B-G66 PDC  
Phone: 313.323.0634  
Mobile: 313.805.0482

---

**From:** Angie Caudill [mailto:Angie.Caudill@TRW.COM]  
**Sent:** Wednesday, March 09, 2011 9:47 AM  
**To:** Napoli, Laura (L.); Todd Williams  
**Cc:** Estes, Eric (E.E.); Andy Ausband; Carl Craig; Greg Austin  
**Subject:** RE: U502 TS Warranty Bent Rotor

Todd,  
Can you please answer Laura's question?

Thanks,  
Angie

>>> "Napoli, Laura (L.)" <lnapoli@ford.com> 3/9/2011 9:11 AM >>>  
Angie,

Is it possible to rotate the part in a way that the bent finger is located in the gap of the half moon and a bad part would pass?

---

**From:** Angie Caudill [mailto:Angie.Caudill@TRW.COM]  
**Sent:** Wednesday, March 09, 2011 9:01 AM

**To:** Napoli, Laura (L.)  
**Cc:** Estes, Eric (E.E.); Greg Austin  
**Subject:** Re: U502 TS Warranty Bent Rotor

Laura,  
Please find the requested 8D attached. Both failed IPA's were rejected on our pre assembly MP check.

Thank you,

Angie Caudill  
TRW Pinion and IPA Department Quality Engineer  
423.272.4118 (Office)

>>> "Napoli, Laura (L.)" <lnapoli@ford.com> 3/8/2011 4:08 PM >>>

Angie,

1. Can you send me an updated 8D?
  2. What are the results at Rogersville from running the failed IPA's on the attached poke-yoke tool?
- <<Line 1.JPG>>

Regards,

*Laura Napoli*

U502 EPAS  
Ford Motor Company  
Cube: 2B-G66 PDC  
Phone: 313.323.0634  
Mobile: 313.805.0482

---

**From:** Napoli, Laura (L.)  
**Sent:** Wednesday, September 14, 2011 5:16 PM  
**To:** Pienta, Alan (A.)  
**Subject:** RE: U502 with C200B/C200C

Welcome to EPAS :)

---

**From:** Pienta, Alan (A.)  
**Sent:** Thursday, September 01, 2011 1:55 PM  
**To:** Napoli, Laura (L.)  
**Subject:** RE: U502 with C200B/C200C

Thanks Laura, I forgot you sent that to me. Why is everything so complex?  
Al

---

**From:** Napoli, Laura (L.)  
**Sent:** Thursday, September 01, 2011 11:26 AM  
**To:** Pienta, Alan (A.); Diez, Timothy (T.P.)  
**Subject:** RE: U502 with C200B/C200C

You have to find C200B and C200C in the Part 2 I sent you. That will give you the hex version so you can use the spreadsheet to find the TRW code.

C200B is probably BD0 and/or BD2 and possibly a BD4.  
C200C is probably BD1 and/or BD3.

---

**From:** Pienta, Alan (A.)  
**Sent:** Thursday, September 01, 2011 11:04 AM  
**To:** Diez, Timothy (T.P.); Napoli, Laura (L.)  
**Subject:** FW: U502 with C200B/C200C

Tim, Laura,  
If you have the fault code descriptions, please send them to me. In my opinion, the grease would potentially make a better connection if someone had probed and spread the terminals during diagnosis.  
Al

---

**From:** Napoli, Laura (L.)  
**Sent:** Thursday, September 01, 2011 9:23 AM  
**To:** 'Jim Loria'; Pienta, Alan (A.); Michael Fontana; Simon Malsbury; Engelbert Lu; joel.rabideau@trw.com; Diez, Timothy (T.P.)  
**Cc:** Mrozek, Robert (R.M.); Estes, Eric (E.E.)  
**Subject:** FW: U502 with C200B/C200C

TRW TS Team,

We have a car in warranty that had C200B and C200C TS Faults. The dealer unplugged ALL 3 connectors and put dielectric grease on the pins and said it fixed the issue. This is not in the service procedure. Do you have any concerns that they did this, or do you think the car will just come back with another TS fault and we can replace the gear then?

Regards,

*Laura Napoli*  
D3 and U502 EPAS  
Ford Motor Company

Cube: 2B-G66 PDC  
Phone: 313.323.0634  
Mobile: 313.805.0482

---

**From:** Jackson, Bradley (B.G.)  
**Sent:** Thursday, September 01, 2011 8:43 AM  
**To:** Napoli, Laura (L.); Estes, Eric (E.E.)  
**Cc:** Mrozek, Robert (R.M.); Logli, Michael (M.A.); Brucker, Eric (.)  
**Subject:** U502 with C200B/C200C

Laura / Eric E., what is the C200B/C DTC? This dealer is claiming they put di-electric grease in the connector to the gear and fixed this problem. This does not sound correct.

## Claim Detail Report

**Model Year = 2011; Claim Key = 918856**

### Vehicle Information

### Claim Information

Model Year: **2011** Document Number: **00410801**  
Market Derived: **F - FORD** Repair Date: **24-AUG-11**  
Body/Cab Type: **T/WD - 4 DOOR WAGON** Distance: **1619**  
Version/Series: **T/EF-FORD SERIES** TIS: **2**  
Drive Type: **T/A-2 WHL L/H FRONT DRIVE**  
Vehicle Line: **T/UB-EXPLORER [11-12]**  
Warranty Start Date: **16-JUL-11**  
Production Date: **17-JUN-11**  
VIN: **1FMHK7B88BG** [REDACTED]

### Expense Information

#### **Dealer Information:**

Customer Paid Amount: **.00**  
**Dealer Name** **DUVAL FORD** Deductible Amount: **.00**  
**Dealer Code:** **04863 - \*** Dealer Paid Amount: **.00**  
**Address:** **1616 CASSAT AVE** Labor Cost: **87.66**  
**City:** **JACKSONVILLE** Misc. Expense Amount: **.00**  
**State:** **FL** Zip Code: **32210** Part Markup Amount: **.00**  
**Country:** **USA** Region Code: **NA** Material Cost: **.00**  
**Phone:** **(904)387-6541** Total Cost Gross: **87.66**

---

Cust. Concern Code: **H39 - TRACTION CONTROL/ADVANCE TRAC WARNING LIGHT TRBLS**  
Condition Code: **28 - OPEN CIRCUIT**  
Technician Comment: **VERIFY CONCERN,PERFORM SELF TEST TO ABS & PSCM, RECEIVE U0001:88,C1BOO:86,C200B:62,C200C:2F,PERFORM PINPOINT B PER INTERACTIVE DYNAMICS,FOUND HIGH RESISTANCE IN ELECTRONIC STEERING GEAR CONNECTORS,INSTALL DIELECTRIC GREASE IN ALL 3 CONNECTORS,PER FORM TEST DRIVE TO VERIFY DTC'S DID NOT RETURN, OPERATING AS DESIGNED. CC 42 1621**  
Customer Comment: **SVC ADVANCE TRAC & PWR STEERING ASSIST FAULT COMES ON INTERMITTANTLY WHILE DRIVING. WHEN THIS OCCURS, POWER STEERING IS INOP...ADVISE**

---

<u>Labor Op Code</u>	<u>Labor Op Description</u>	<u>Labor Op Cost</u>
MTWIRING		87.66

---

<u>Causal</u>	<u>Full Part Number</u>	<u>Part</u>	<u>Part</u>	<u>Extended</u>	<u>Quantity</u>	<u>Amount</u>
<u>Flag</u>	<u>PREF</u>	<u>BASE</u>	<u>SUFF</u>	<u>Description</u>	<u>CPSC</u>	
Y	*	14401	*	WIRE ASY MAIN LOOM	180102	0 .00

Regards,

*Brad Jackson*

Chassis Resident Engineer  
 Chicago Assembly Plant  
 Ford Motor Company  
 Phone: +1.313.805.4798  
[bjackson@ford.com](mailto:bjackson@ford.com)



---

**From:** Napoli, Laura (L.)  
**Sent:** Friday, April 01, 2011 9:36 AM  
**To:** Estes, Eric (E.E.); Mrozek, Robert (R.M.)  
**Cc:** Anderson, Eric (H.); Diez, Timothy (T.P.)  
**Subject:** RE: 2011 EXP/[REDACTED] CHASSIS - Report Summary(s) from a GCQIS Query Disposition

They're definitely wiring issues. Seems like these are all of a sudden popping up again. We need to make sure they don't pull the gears on these, and should get information from them once they find out the electrical problem to see if we have another build issue.

---

**From:** Estes, Eric (E.E.)  
**Sent:** Friday, April 01, 2011 9:00 AM  
**To:** Mrozek, Robert (R.M.)  
**Cc:** Napoli, Laura (L.); Anderson, Eric (H.); Diez, Timothy (T.P.)  
**Subject:** RE: 2011 EXP/[REDACTED] CHASSIS - Report Summary(s) from a GCQIS Query Disposition

I will check these out as soon as I get out of our internal meeting, thanks

Eric

---

**From:** Mrozek, Robert (R.M.)  
**Sent:** Friday, April 01, 2011 8:58 AM  
**To:** Estes, Eric (E.E.)  
**Cc:** Napoli, Laura (L.); Anderson, Eric (H.); Mrozek, Robert (R.M.); Diez, Timothy (T.P.)  
**Subject:** FW: 2011 EXP/[REDACTED] CHASSIS - Report Summary(s) from a GCQIS Query Disposition

Mr. Estes -

Can you check with these please to see if you can offer some guidance? There are two Explorer EPAS concerns in the list. Let us know what you find?

*Rob Mrozek*

Electric Power Steering Supervisor  
CD3/D3/D4/U502/Police/Limo EPAS Programs +  
Active Front Steering Applications Engineering  
Ford Motor Company  
Phone: (313) 805-5947  
e-mail: rmrozek@ford.com

---

**From:** SBUELOW [mailto:SBUELOW]  
**Sent:** Friday, April 01, 2011 4:47 AM

**To:** RMROZEK

**Subject:** 2011 EXP/[REDACTED] CHASSIS - Report Summary(s) from a GCQIS Query Disposition

This email contains 6 report summary(s).

Redacted for Relevance

**Attachments : 2**

**Report# :** BC5E5524 NHLDIG--or-- HD 201100431245 **Received:** 03/31/2011  
**CCRG/EPRC:** **Reviewed Status:** **Date:**  
**Vehicle:** 2011,EXPLORER 4X4 (U502),4 DOOR **Build Date:** 12/07/2010  
,MP,1FMHK8D86BG [REDACTED]  
**Odometer :** 9,579 M **Engine:** 3.5L **Calibration:** BUB1ST0A  
CYCLO  
**Transmission:** 6F55 **Axle:** **A/C:** YES  
**Dealer:** USA 02848 Holman Ford Lincoln Mercury - **Phone#:** (856) 728-7800  
**City:** Turnersville **State:** New Jersey **Country :** USA  
**Originator:** Rob Barbarino  
**Symptom:** 3 03 A 01 CHASS.,STRG/HANDLING ,STEERING WHEEL ,APPEARANCE  
**Status:**  
**VFG:** V71 I.P. & COUNSOL FUNCTION  
**Additional Symptom:** Processed  
**Fix:** **Causal Component :** --  
**Condition Code:**  
**Region Code:** N3 **Region Name:** Philadelphia

**DTCs:**  
KOE0:  
KOE1:  
KOE2:

**Comments :**

CONCER 03/31/2011 11:05AM  
cust sts steering is loose. tech verified and found that steering wheel just needs to be tighten. nut came loose. thanks, rob

**RECOMM 03/31/2011 11:05AM**

No parts are being replaced no need for DI approval code. Thanks Sean  
contact id: 104468995

Please click on the link below to view the attachments associated with this report

[https://www.gcqis.dealerconnection.com/gcqis/asp/DIVViewAttachment\\_Mainx.asp?ReportNumber=BC5E5524](https://www.gcqis.dealerconnection.com/gcqis/asp/DIVViewAttachment_Mainx.asp?ReportNumber=BC5E5524)

**Attachments : 0**

<b>Report# :</b>	BC5AL007 NHL	<b>Received:</b>	03/31/2011
<b>CCRG/EPRC:</b>		<b>Date:</b>	
<b>Vehicle:</b>	2011,EXPLORER 4X4 (U502),4 DOOR ,MP,1FMHK8F82BG [REDACTED]	<b>Build Date:</b>	02/23/2011
<b>Odometer :</b>	13 M	<b>Engine:</b>	3.5L CYCLO
<b>Transmission:</b>	6F55	<b>Axle:</b>	
<b>Dealer:</b>	USA 00978 Capital Ford, Inc.	<b>Calibration:</b>	BUB1ST0A
<b>City:</b>	Raleigh	<b>State:</b>	North Caroli
<b>Originator:</b>	RYAN WALLACE	<b>Phone#:</b>	(919) 790- 4700
<b>Symptom:</b>	3 03 1 50 CHASS.,STRG/HANDLING ,FUNCTION,HIGH EFFORT		
<b>Status:</b>			
<b>VFG:</b>	V87 STEERING		
<b>Additional Symptom:</b>	NO POWER STEERING ASSIST		
<b>Fix:</b>	<b>Causal Component :</b>	--	
<b>Condition Code:</b>			

<b>Hotliner:</b> WHOUST13	<b>Phone:</b> 313 317-7044	<b>Regn Cd:</b> S2 Charlotte
<b>Engineering:</b>	<b>Phone:</b>	<b>TAR:</b>
<b>Dlr Contact:</b> RYAN WALLACE	<b>Phone:</b> 000 000-0000	<b>Title Cde:</b> T

**DTCs:**  
 KOEO:  
 KOEC:  
 KOER:

**Comments**  
:

REPAIR 03/31/2011 12:22PM WILLIE HOUSTON MSS - FCSD - TECH SVC HOTLINE  
WEB FORM DATA - CONCERN: POWER STEERING INOP DIAGNOSTICS: NETWORK

TEST NO COMMUNICATION WITH PSCM, PINPOINT TEST AC1-12VOLTS AT C1463A PIN 3, PINPOINT AC2- .2 OHMS C1463B PIN2, PINPOINT TEST AC3- C1463A PIN 1 TO DLC PIN6 1.2 OHMS, C1463A PIN 2 TO DLC PIN14 1 OHM, PINPOINT TEST AC4 NO PUSHED OUT PINS OR CORROSION OR BENT OR DAMAGED PINS PARTS REPLACED:: STEERING GEAR TECH QUESTION: ANY KNOWN PROBLEMS WITH REPROGRAM OR COMMUNICATION WITH THE PSCM, ANY OTHER

PINPOINT TEST? WERE YOU ABLE TO VERIFY THE CONCERN? YES IS THERE AN APPROPRIATE PINPOINT TEST IN THE WSM FOR THIS CONCERN? YES WAS THE PINPOINT TEST FOLLOWED? YES

**RECOMM 03/31/2011 12:22PM WILLIE HOUSTON MSS - FCSD - TECH SVC HOTLINE**

RYAN, THE EPAS SYSTEM THAT THIS VEHICLE HAS IS TOTALLY SELF CONTAINED. THE GEAR REQUIRES POWER AND GROUND AND NETWORK CIRCUITS FOR

COMMUNICATION. IF THE EPAS GEAR HAS BEEN REPLACED, AND THERE IS NO ASSIST OR COMMUNICATION WITH THE MODULE, LOAD TEST THE POWERS AND GROUNDS TO THE EPAS USING A HEADLAMP BULB TO VERIFY THAT THEY ARE CAPABLE OF CARRYING SUFFICIENT AMPERAGE AND PERFORM WIGGLE TESTS DURING THIS LOAD TEST. IF OKAY, VERIFY THAT THE NETWORK VOLTAGES AT THE PSCM CONNECTOR CORRESPOND WITH THE VOLTAGES AT PINS 6 AND 14 OF THE DLC WITH THE VEHICLE IN A KOEO STATE. CLOSELY INSPECT FOR LOOSE/DAMAGE OR OTHER PINFIT ISSUES AT THE PSCM AND BJB. REFERENCE PAGE 43-1 OF THE ONLINE EVTMM FOR CIRCUIT DETAILS.

---

Redacted for Relevance

Redacted for Relevance

**Attachments :** 0

**Report# :** BC5E3001 NHL

**CCRG/EPRC:** **Reviewed Status:**

**Vehicle:** 2011,EXPLORER 4X2 (U502),4 DOOR  
,MP,1FMHK7F88BG [REDACTED]

**Received:** 03/31/2011

**Date:**

**Build Date:** 02/22/2011

**Odometer :** 401 M                      **Engine:** 3.5L  
CYCLO                      **Calibration:** BUB1SN0A  
**Transmission:** 6F50                      **Axle:**                      **A/C:** YES  
**Dealer:** USA 05739 Ted Russell Ford Lincoln Mercu                      **Phone#:** (865) 693-  
7707  
**City:** Knoxville                      **State:** Tennessee                      **Country :** USA  
**Originator:** SAM NELSON  
**Symptom:** 3 01 A 03 CHASS.,SERVICE BRAKE ,INDICATOR,RED/AMBER ONLY  
**Status:**  
**VFG:** V21 BRAKING  
**Additional Symptom:** RED & YELLOW BRAKE & T/C LIGHT  
**Fix:**                      **Causal Component :** --  
**Condition Code:**

**Hotliner:** GBARTOS                      **Phone:** 313 317-6301                      **Regn Cd:** S1 Atlanta  
**Engineering:**                      **Phone:**                      **TAR:**  
**Dlr Contact:** SAM NELSON                      **Phone:** 000 000-0000                      **Title Cde:** T

**DTCs:**

KOEO:  
KOEC:C0020:12 C0020:13 U0131  
KOER:

**Comments**

:  
**REPAIR**    03/31/2011 04:45PM GREG BARTOS MSS - FCSD - TECH SVC HOTLINE  
WEB FORM DATA - CONCERN: RED BRAKE LIGHT ON , YELLOW BRAKE LIGHT ON ,  
TRAC LIGHT ON AND TRACK LIGHT OFF IS ON . DIAGNOSTICS: EEC TEST  
HAS C0020:12-AB, C0020:13-AB,U0131:00-AB CODES CLEAR CODES AND RETEST  
ABS PASS OD, PASS CON., BUT STILL HAS ALL LIGHTS ON ON THE DASH?  
PARTS REPLACED:: NONE TECH QUESTION: C0020:12 PINPOINT TEST  
SAID FAILED INTERNALLY, IN HCU TO REPLACE? C0020:13 COULD BE IN ECU  
MODULE DO I REPLACE BOTH? I DO HAVE COMP. WITH THE MODULE? WERE  
YOU ABLE TO VERIFY THE CONCERN? YES IS THERE AN APPROPRIATE  
PINPOINT TEST IN THE WSM FOR THIS CONCERN? YES WAS THE PINPOINT  
TEST FOLLOWED? YES  
**RECOMM**    03/31/2011 04:45PM GREG BARTOS MSS - FCSD - TECH SVC HOTLINE  
SAM, IT IS RECOMMENDED TO REPLACE BOTH THE HCU AND ABS MODULE FOR  
THE  
C0020 DTCS THAT HAVE BEEN SET ON THIS VEHICLE. ALSO REFERENCE TO  
SSM 21737 TO ADDRESS THE U0131 DTC THAT HAS BEEN SET. CLEAR THE DTCS  
AND WIGGLE TEST C139 AND VERIFY IF THE U0131 DTC

RETURNS. -----

----- REPORT #: BAKFD002 REPLACE ABS ECU SSM 21737 CODES C1B00,  
U0131, U0100, U0001, U0121, AND/OR U0151- CLEAR CODES AND WIGGLE TEST  
CONNECTER C139. IFCODES RETURN, BYPASS C139 FOR CIRCUITS VDB04 AND  
VDB05 USING THE SOLDER AND SHRINK TUBING METHOD FOUND IN SECTION 5  
OF  
THE WIRING DIAGRAMS.

Attachments : 0

**Report# :** BC5EH004 NHL **Received:** 03/31/2011  
**CCRG/EPRC:** **Reviewed Status:** **Date:**  
**Vehicle:** 2011,EXPLORER 4X2 (U502),4 DOOR **Build Date:** 03/02/2011  
,MP,1FMHK7F86BG [REDACTED]  
**Odometer :** 33 M **Engine:** 3.5L **Calibration:**  
CYCLO  
**Transmission:** 6F55 **Axle:** **A/C:** YES  
**Dealer:** USA 02561 Sewell Ford, Inc. **Phone#:** (432) 498-  
0421  
**City:** Odessa **State:** Texas **Country :** USA  
**Originator:** STEFAN DROUI  
**Symptom:** 3 03 1 50 CHASS.,STRG/HANDLING ,FUNCTION,HIGH EFFORT  
**Status:**  
**VFG:** V87 STEERING  
**Additional Symptom:** LOSS OF ASSIST  
**Fix:** **Causal Component :** --  
**Condition Code:**

**Hotliner:** IWRIGH24 **Phone:** 313 317-4284 **Regn Cd:** C1 Dallas  
**Engineering:** **Phone:** **TAR:**  
**Dlr Contact:** STEFAN DROUI **Phone:** 432 432-3320 **Title Cde:** T

**DTCs:**  
KOE0:C1B00:29 C1B00:41 U0131  
KOE0:  
KOE0:

**Comments**

:  
REPAIR 03/31/2011 03:28PM IAN WRIGHT MSS - FCSD - TECH SVC HOTLINE



WEB FORM DATA - CONCERN: LOST ALL POWER STEERING ,TOWED IN,POWER STEERING NOW. ADVANCE TRACK LIGHT ON ABS LIGHT ON DIAGNOSTICS: IDS TEST,MONITERED PIDS STEERING ANGLE PI WAS 49150.95. INSPECTED CONNECTIONS ON EPAS,ABS MODULE,SJB,BJB ALL OK,INSPECTED GRONDS PARTS REPLACED:: NO PARTS REPLACED TECH QUESTION: POWER STEERING LOCKED,ADVANCED TRACK LIGHT ON,SOMETIMES STEERING FUNCTIONS,OTHER TIMES IT DOESNT,CANT COMMUNICATE WITH PSCM AT TIMES,OTHER TIMES CAN. CODES C1B00:29-68 AND C1B00:41-68. CANNOT FIND CORRECT PIN POINT TEST. I FEEL LIKE IT IS THE PSCM,EPAS RAC-N-PINION. DO HAVE ANY REPAIR IDEAS NOT SURE WHERE TO GO.

**RECOMM 03/31/2011 03:28PM IAN WRIGHT MSS - FCSD - TECH SVC HOTLINE**

STEFAN, THE READING OF THE STEERING ANGLE SENSOR IS NORMAL. THE STEERING ANGLE SENSOR LEARNS A ZERO POINT AFTER DRIVING STRAIGHT. REFER TO <>

HREF='HTTP://WWW.VREP.FORDTECHSERVICE.DEALERCONNECTION.COM/VDIRS/SSM/SSM.ASP?SSM=21737' TARGET='\_BLANK'>SSM 21737 TO ADDRESS THE FAULTS PRESENT. SSM 21737 CODES C1B00, U0131, U0100, U0001, U0121, AND/OR U0151- CLEAR CODES AND WIGGLE TEST CONNECTER C139. IFCODES RETURN, BYPASS C139 FOR CIRCUITS VDB04 AND VDB05 USING THE SOLDER AND SHRINK TUBING METHOD FOUND IN SECTION 5 OF THE WIRING DIAGRAMS.

---

---

**From:** Bahena, Miguel (Mike.)  
**Sent:** Friday, January 21, 2011 6:01 PM  
**To:** Mrozek, Robert (R.M.); Estes, Eric (E.E.); Jackson, Bradley (B.G.); Napoli, Laura (L.); 'Michael Fontana'; Diez, Timothy (T.P.)  
**Cc:** Pasquarella, Michael (M.S.)  
**Subject:** RE: 2011 EXP/[REDACTED] CHASSIS - Report Summary(s) from a GCQIS Query Disposition

Eric,

UR002 and UR003 technician comments indicate that Service Power Steering Now was in the cluster. This text would be associated with the friction detection fault.

Also how do you know these are No comms? Is it based on technicians telling you? I would expect CAN communication is working if cluster messages are being displayed. Make sure the techs follow workshop manual procedure 418 pinpoint D if it is truly a no com.

Sincerely,

**Mike Bahena**  
**D3 Electric Power Steering Systems**  
**Ford Motor Co.**  
Ph: (313) 805-3680  
mbahena1@ford.com

---

**From:** Mrozek, Robert (R.M.)  
**Sent:** Friday, January 21, 2011 12:39 PM  
**To:** Estes, Eric (E.E.); Jackson, Bradley (B.G.); Napoli, Laura (L.); 'Michael Fontana'; Diez, Timothy (T.P.)  
**Cc:** Pasquarella, Michael (M.S.); Bahena, Miguel (Mike.)  
**Subject:** RE: 2011 EXP/[REDACTED] CHASSIS - Report Summary(s) from a GCQIS Query Disposition  
**Importance:** High

Eric -

Please talk to Brad about how to expedite these parts back to us. Also, since the intermittent code maps to an A19 or A29, A19 might be related to a missing soft stop. Please have Fontana run the ANY gear without soft stops and see if that code is raised. Even check with the dealer to see if he can test the gear or car for equal travel left to right. We had a missing soft stop issue at MP1.

B3A  
Please be prepared to have the EPP analysis by Monday at our weekly meeting even if it means someone needs to work on it tomorrow.

*Rob Mrozek*

Electric Power Steering Supervisor  
CD3/D3/D4/U502/Police/Limo EPAS Programs +  
Active Front Steering Applications Engineering  
Ford Motor Company

Phone: (313) 805-5947  
e-mail: rmrozek@ford.com

---

**From:** Estes, Eric (E.E.)  
**Sent:** Friday, January 21, 2011 11:02 AM  
**To:** Mrozek, Robert (R.M.); Jackson, Bradley (B.G.); Napoli, Laura (L.)  
**Cc:** Pasquarella, Michael (M.S.)  
**Subject:** RE: 2011 EXP/[REDACTED] CHASSIS - Report Summary(s) from a GCQIS Query Disposition

Rob all three of the No Com's will be returned, I cannot say 100% that the gear is the issue. most of the testing has been confirmed by the book and some have load tested the circuits. it is possible it could be a ground or ign. feed but I have one hard No Com that will be returned and two intermittent No Com similar to Brad's road test description at the plant.

I'm giving Blood to the Red Cross and will return in one hour

Eric

---

**From:** Mrozek, Robert (R.M.)  
**Sent:** Friday, January 21, 2011 10:50 AM  
**To:** Jackson, Bradley (B.G.); Estes, Eric (E.E.); Napoli, Laura (L.)  
**Cc:** Pasquarella, Michael (M.S.)  
**Subject:** RE: 2011 EXP/[REDACTED] CHASSIS - Report Summary(s) from a GCQIS Query Disposition

We had a similar launch issue and it was a bad ground of the wire to the EPAS.

*Rob Mrozek*

Electric Power Steering Supervisor  
CD3/D3/D4/U502/Police/Limo EPAS Programs +  
Active Front Steering Applications Engineering  
Ford Motor Company  
Phone: (313) 805-5947  
e-mail: rmrozek@ford.com

---

**From:** Jackson, Bradley (B.G.)  
**Sent:** Friday, January 21, 2011 10:47 AM  
**To:** Mrozek, Robert (R.M.); Estes, Eric (E.E.); Napoli, Laura (L.)  
**Cc:** Pasquarella, Michael (M.S.)  
**Subject:** RE: 2011 EXP/[REDACTED] CHASSIS - Report Summary(s) from a GCQIS Query Disposition

Rob, I agree. If the word gets out that gear replacements are fixing the concern, we are in trouble. Need to deep dive these gears when they come back.

Just an fyi to this team, my M10 from 2 weeks ago was found to be a NPF....even though there were stored DTC's and was reproducible after several key off/key on cycles. That being said, we now have another vehicle with the exact same tell tale signs of terrain mgmt inop and traction control inop here at CAP that was found in a FCPA audit. This vehicle has

stored DTC's and is now not showing the faults either. We are going to be deep diving this vehicle at some point today to try to root cause. I want to start with wiring connection to gear and work backwards. Something is happening intermittently and we need to figure this out.

Please call with any questions.

Brad

---

**From:** Mrozek, Robert (R.M.)  
**Sent:** Friday, January 21, 2011 9:27 AM  
**To:** Estes, Eric (E.E.); Napoli, Laura (L.)  
**Cc:** Pasquarella, Michael (M.S.); Jackson, Bradley (B.G.)  
**Subject:** RE: 2011 EXP/[REDACTED] CHASSIS - Report Summary(s) from a GCQIS Query Disposition  
**Importance:** High

- 1) Why are we replacing these gears? How do you know it is not a wiring issue? Do not replace an intermittent gear until we know 100% for sure it is not wiring. Are these dealers nearby where we can go there to look?
- 2) WARNING: The world will shit a brick with 4 EPAS claims on U502 and our lives will be hell. ALL these gears need root cause within 48 hours or less.

*Rob Mrozek*

Electric Power Steering Supervisor  
CD3/D3/D4/U502/Police/Limo EPAS Programs +  
Active Front Steering Applications Engineering  
Ford Motor Company  
Phone: (313) 805-5947  
e-mail: rmrozek@ford.com

---

**From:** Estes, Eric (E.E.)  
**Sent:** Friday, January 21, 2011 10:14 AM  
**To:** Napoli, Laura (L.)  
**Cc:** Mrozek, Robert (R.M.)  
**Subject:** RE: 2011 EXP/[REDACTED] CHASSIS - Report Summary(s) from a GCQIS Query Disposition

Talked to all tech's for all three No Com gears they will replace EPAS gears. I have two int. no com's similar with Bradley's plant vehicle road test and I have one No Com that is their all the time

Laura see if we can install one of the int. No Com's for on-vehicle testing and we will take the other two in for analysis at 26-mile.

The attachment is my updated warranty tracking report with the new U502 gears, and I added the tech comments.

Laura did you talk to Brad and find out about the U502 B3A if you wanted to wait for the Tyco relay workshop in Feb?

Let me know

Eric

---

**From:** Napoli, Laura (L.)  
**Sent:** Friday, January 21, 2011 9:28 AM  
**To:** Estes, Eric (E.E.)  
**Subject:** FW: 2011 EXP/[REDACTED] CHASSIS - Report Summary(s) from a GCQIS Query Disposition

Eric,

Can you verify that none of these codes indicate that the rack should be pulled? Thanks!

I'm off today, so call my cell if you need me...313-805-0482

---

**From:** SBUELOW [mailto:SBUELOW]  
**Sent:** Friday, January 21, 2011 4:46 AM  
**To:** LNAPOLI  
**Subject:** 2011 EXP/[REDACTED] CHASSIS - Report Summary(s) from a GCQIS Query Disposition

This email contains 4 report summary(s).

Redacted for Relevance

Redacted for Relevance

**Attachments :** 0

**Report# :** BATDZ004 NHL **Received:** 01/20/2011  
**CCRG/EPRC:** **Reviewed Status:** **Date:**  
**Vehicle:** 2011,EXPLORER 4X4 (U502),4 DOOR **Build Date:** 11/22/2010  
,MP,1FMHK8F83BG [REDACTED]  
**Odometer :** 289 M **Engine:** 3.5L **Calibration:** BUB1ST0A  
CYCLO  
**Transmission:** 6F55 **Axle:** **A/C:** YES  
**Dealer:** USA 02058 BEECHMONT FORD INC **Phone#:** (513) 752-7474  
**City:** Cincinnati **State:** Ohio **Country :** USA  
**Originator:** SHANE JONES  
**Symptom:** 3 03 A 99 CHASS.,STRG/HANDLING ,STEERING WHEEL ,NOT LISTED  
**Status:**  
**VFG:** V87 STEERING  
**Additional Symptom:** STEERING HARD INTERMITTENT  
**Fix:** **Causal Component :** --  
**Condition Code:**  
**Hotliner:** JSAVOY1 **Phone:** 313 317-9352 **Regn Cd:** G3 Cincinnati  
**Engineering:** **Phone:** **TAR:**  
**Dlr Contact:** SHANE JONES **Phone:** 513 752-7474 **Title Cde:** T

**DTCs:**

KOEO:U0121 U2011:49-08 U0126 U0159 U0428

KOEC:

KOER:

**Comments**

:

**REPAIR** 01/20/2011 02:47PM JONATHAN SAVOY MSS - FCSD - TECH SVC HOTLINE  
WEB FORM DATA - CONCERN: CUST STATES THAT THE MESSAGE CENTER HAD A MESSAGE THAT SAID POWER STEERING ASSIST FAULT AND THE STEERING WAS VERY HARD  
DIAGNOSTICS: TEST DROVE VEH AND NORMAL OPERATION AT THIS TIME 0 WARNINGS IN THE MESSAGE CENTER IDS TESTED AND FOLLOWED PINPOINT TEST PER WORK SHOP MANUAL AND IT LED ME TO THE CONSERN IS NOT PRESENT AND TO RETURN THE VEH BACK TO THE CUST DTC U2011:49-08,U0121,U0126,U0159,U0428 THE WORK SHOP MANUAL TOLD ME TO CLEAR THE DTC AND TEST DRIVE VEH AND RETEST I CLEARD THE DTC AND THE SYSTEM PASSED PARTS REPLACED:: NONE TECH QUESTION: ANY KNOWN CONSERNS SHOULD I RETURN THE VEH TO THE CUST WERE YOU ABLE TO VERIFY THE CONCERN? NO IS THERE AN APPROPRIATE PINPOINT TEST IN THE WSM FOR THIS CONCERN? YES WAS THE PINPOINT TEST FOLLOWED? YES

**RECOMM** 01/20/2011 02:47PM JONATHAN SAVOY MSS - FCSD - TECH SVC HOTLINE  
SHANE, THIS CONCERN IS LIKELY CAUSED BY A LOOSE CONNECTION WITHIN THE MAIN ENGINE OR BODY WIRING HARNESS. THIS WOULD RESULT IN INTERMITTENT COMMUNICATION CODES AND POSSIBLE INOPERATIVE ACCESSORIES.  
IN ORDER TO HELP ISOLATE THE ROOT CAUSE OF THIS CONCERN, PLEASE START THE VEHICLE AND WIGGLE TEST THE MAIN ENGINE AND BODY WIRING HARNESS. THIS MAY HELP TO INDUCE THE CONCERN. PLEASE ALSO INSPECT FOR LOOSE OR UNSEATED CONNECTORS. THE HOTLINE HAS NOT SEEN TRENDS OF THIS CONCERN AT THIS TIME. IF THE CONCERN CANNOT BE DUPLICATED, NO REPAIRS SHOULD BE PERFORMED. IF ADDITIONAL ASSISTANCE IS NEEDED, PLEASE UPDATE YOUR FORM WITH ANY ADDITIONAL DETAILS OF THIS CONCERN.

---

Redacted for Relevance

**Attachments :** 0

<b>Report# :</b>	BATBL002 NHL	<b>Received:</b>	01/20/2011
<b>CCRG/EPRC:</b>	<b>Reviewed Status:</b>	<b>Date:</b>	
<b>Vehicle:</b>	2011,EXPLORER 4X4 (U502),4 DOOR ,MP,1FMHK8F89BG [REDACTED]	<b>Build Date:</b>	12/13/2010
<b>Odometer :</b>	51 M	<b>Engine:</b>	3.5L CYCLO
<b>Transmission:</b>	6F50	<b>Axle:</b>	
<b>Dealer:</b>	USA 04963 BRANDON FORD	<b>Calibration:</b>	BUB1SN0A
<b>City:</b>	Tampa	<b>A/C:</b>	YES
<b>Originator:</b>	JAMES BUCHANAN	<b>Phone#:</b>	(813) 246- 3673
<b>Symptom:</b>	3 03 4 54 CHASS.,STRG/HANDLING ,NOISE,WHEN TURNING	<b>Country :</b>	USA
<b>Status:</b>			
<b>VFG:</b>	V87 STEERING		
<b>Additional</b>	RT FRONT STRUT BEARING NOISE		





---

**From:** Estes, Eric (E.E.)  
**Sent:** Thursday, October 27, 2011 9:42 AM  
**To:** Napoli, Laura (L.); Brezee, Shane (S.B.)  
**Cc:** Dukkipati, Srini (S.); Flanagan, Thomas (T.P.); Surella, Matthew (M.M.)  
**Subject:** RE: 2011 U502 B9A Buy Back vehicle

Laura this vehicle is ready for buy back, John did clear the B9A code and no codes reset after a short road test. Apparently this vehicle was towed into the dealer for an in/op cooling fan issue and the tech notice the power steering was not working. John has all the data on the vehicle and sent to Geoff and Sergio to pull the EFF data.

This was a strange B9A setting because it looks like it only had one B9A that tripped then set C69 so not sure what happened with the fault store.

Let me know if you need more vehicle information before John comes back today, thanks

Eric

---

**From:** Napoli, Laura (L.)  
**Sent:** Tuesday, October 25, 2011 4:56 PM  
**To:** Brezee, Shane (S.B.); Estes, Eric (E.E.)  
**Cc:** Dukkipati, Srini (S.)  
**Subject:** RE: 2011 U502 B9A Buy Back vehicle

Eric,

Please reply to all with the VIN of this potential buy back vehicle. Thanks!

---

**From:** Brezee, Shane (S.B.)  
**Sent:** Tuesday, October 25, 2011 3:49 PM  
**To:** Napoli, Laura (L.)  
**Cc:** Dukkipati, Srini (S.)  
**Subject:** RE: 2011 U502 B9A Buy Back vehicle

If you can get us the VIN we can start the paperwork ahead of any decision.

*Regards,*  
*Shane B. Brezee*

**PD Quality Supervisor**  
**Steering, Wheels & Tires**  
Ford Motor Company  
2BJ70 PDC 20901 Oakwood Blvd, Dearborn, MI 48124  
 PH: (313) 805-8590  
 e-mail : [sbrezee@ford.com](mailto:sbrezee@ford.com)

---

**From:** Napoli, Laura (L.)  
**Sent:** Tuesday, October 25, 2011 3:46 PM  
**To:** Moody, Sandra (S.L.); Perri, Ron (R.J.); Surella, Matthew (M.M.); Dukkipati, Srini (S.); Brezee, Shane (S.B.)  
**Subject:** FW: 2011 U502 B9A Buy Back vehicle

TRW has a potential buy back. Good news is that it is at a rental company, so we are not holding up a customer. The gear is locked out, so there is no way of knowing if the failure is a hard failure. There's no reason to buy the car back if it is a hard failure because the gear will not be testable. TRW is going out to the dealer tomorrow in San Fran to pull codes and verify if the gear has a complete failure or just a temporary lock out. They will also take data and try to duplicate the failure.

If it is a permanent failure, we should not buy back the car, but just have the gear returned.  
If it's not a permanent failure and they duplicate it while taking data, we may not need to buy the car back.  
If neither of the above happens, this would be a good buy back car and we should move quickly.

On another note, I have a couple responses from the 6-sigma study of management lease cars that would be potential cars to test instead of buying one back. I should have more info on that this week.

Regards,

*Laura Napoli*

D3 and U502 EPAS  
Ford Motor Company  
Cube: 2B-G66 PDC  
Phone: 313.323.0634  
Mobile: 313.805.0482

---

**From:** Estes, Eric (E.E.)  
**Sent:** Tuesday, October 25, 2011 1:30 PM  
**To:** Napoli, Laura (L.)  
**Cc:** Salim Semssar; Anthony.Fleenor@TRW.COM; John Burnett  
**Subject:** FW: 2011 U502 B9A Buy Back vehicle

John Burnett is all set to arrive at Future Ford tomorrow afternoon to pull the data on the 2011 Explorer then clearing the data to see if the B9A code resets.

I did let the service manager know our intentions of buying back the vehicle if it fits our criteria.

The dealer information is below: Tracy is the Service Manager that I talked to.

FUTURE FORD OF CLOVIS  
920 West Shaw Avenue, Clovis, CA 93612

- Call Us Now: (866) 875-7137

*Eric J Estes*

TRW EPAS Steering Systems  
Quality Specialist  
Hotline ph# 313-317-9358  
Cell ph# 734-560-3493

---

**From:** Estes, Eric (E.E.)  
**Sent:** Tuesday, October 25, 2011 11:37 AM  
**To:** Napoli, Laura (L.)  
**Subject:** 2011 U502 B9A Buy Back vehicle

Laura I found this vehicle in Clovis, California and this vehicle is a AVIS RAC so it might be easy to buy back, the problem with this vehicle is that it set B9A three times then set U3000-96(C69) not the exact issues with the other B9A returns but we can get the tech to perform the proper snap shot data below and look at the freeze frame data for the B9A.

Let me know the tech will not replace the gear until I call him back.

**Year = MY11**  
**Model = U502**  
**Engine = 3.5L**  
**VIN = 1FMHK8D87BG** [REDACTED]  
**IDS Version = 73.03A (IDS-73.03A)**

**PCM = BB5A-14C204-NJ**  
**ABS = BB53-2C219-AF**  
**ACM = BB5T-19C107-BS**  
**APIM = BT4T-14D212-BM**  
**ATCM = N\A**  
**BCM = BC3T-14B476-DH**  
**C-CM = N\A**  
**CLM = N\A**  
**DCSM = N\A**  
**DSM = N\A**  
**DSP = N\A**  
**FCDIM = N\A**  
**FCIM = N\A**  
**FLM = N\A**  
**GPSM = N\A**  
**HSWM = N\A**  
**HUD = N\A**  
**HVAC = BB5T-18C612-BG**  
**IPC = BB5T-10849-GG**  
**LTM = N\A**  
**OCSM = N\A**  
**PAM = BB5T-15K866-AC**  
**PSCM = BB53-3F964-BG**  
**RCM = BB5T-14B321-AF**  
**RFA = N\A**  
**RLCM-A = N\A**  
**SCCM = BB5T-3F944-AJ**  
**SOD-L = N\A**

SOD-R = N/A

TPM = N/A

**Current DTCs {retrieved 19 October 2011 15:14:25}**

DTC	Snap Shot Data	Source
-----	----------------	--------

**Historic DTCs {retrieved 19 October 2011 15:14:25}**

DTC	Snap Shot Data	Source
-----	----------------	--------

**DTCs cleared since initial read:**

DTC	Snap Shot Data	Source
U0402:68	N/A	<a href="#">ABS</a>
C1B00:86	N/A	<a href="#">ABS</a>
(ABS)	N/A	<a href="#">ABS</a>
P1285:00	N/A	<a href="#">PCM</a>
P1299:00	N/A	<a href="#">PCM</a>
U3000:96	N/A	<a href="#">PSCM</a>
C200D:49	N/A	<a href="#">PSCM</a>

*Eric J Estes*

TRW EPAS Steering Systems

Quality Specialist

Hotline ph# 313-317-9358

Cell ph# 734-560-3493

---

**From:** Schondorf, Steven (S.)  
**Sent:** Wednesday, August 11, 2010 4:54 PM  
**To:** Diez, Timothy (T.P.)  
**Subject:** RE: 2011MY U502 TRW Rack EPAS Loss of Assist Issue

Ok. Thanks.

---

**From:** Diez, Timothy (T.P.)  
**Sent:** Wednesday, August 11, 2010 3:47 PM  
**To:** Schondorf, Steven (S.); Rossi, Roberto (R.A.)  
**Subject:** 2011MY U502 TRW Rack EPAS Loss of Assist Issue

Steve, Rob,

This note pertains to the 2011MY U502 TRW Rack EPAS Loss of Assist Issue discovered at CAP this week. The wiring team has determined the root cause to be a crimp issue. The EPAS ground wire is crimped to the same eyelet as the vehicle ground wire. That eyelet is then fastened to sheet metal.


The harness is being removed from the vehicle for further analysis, and an 8D is forthcoming.

Please let me know if you have any additional questions.

Sincerely,  
Tim Diez  
Ford Electric Power Steering, EESE  
313-805-1060; Fax: 313-317-4387  
e-mail: [tdiez@ford.com](mailto:tdiez@ford.com)  
cube 3C071, Building 5

**From:** Surella, Matthew (M.M.)  
**Sent:** Friday, January 06, 2012 1:00 PM  
**To:** Perri, Ron (R.J.)  
**Subject:** RE: B9A Fallout at Tyco, Nidec, Anting/Shalke/Nove Mesto

Here's the update:



Matthew (Matt) Surella  
Steering EPAS Supervisor / MBB  
313-805-3997

---

**From:** Perri, Ron (R.J.)  
**Sent:** Thursday, January 05, 2012 3:25 PM  
**To:** Surella, Matthew (M.M.)  
**Subject:** FW: B9A Fallout at Tyco, Nidec, Anting/Shalke/Nove Mesto

Please update this....

<< OLE Object: Picture (Metafile) >>

Ron Perri  
Manager, Chassis - EPAS and Upper Steering, Systems & Core  
2B-F77, Product Development Center  
cell 313-805-0680  
[rperri@ford.com](mailto:rperri@ford.com)

---

**From:** Napoli, Laura (L.)  
**Sent:** Thursday, December 22, 2011 10:25 AM  
**To:** Perri, Ron (R.J.)

**Cc:** Surella, Matthew (M.M.)  
**Subject:** B9A Fallout at Tyco, Nidec, Anting/Shalke/Nove Mesto

Ron,

I have the most recent numbers for fallout at Tyco, Nidec, and Anting/Shalke/Nove Mesto for the visual inspections they're doing for misalignment and concoat.

Tyco:

Since Nov 12, Tyco is finding 0 misalignment on ribbon cables at EOL with 5x magnification.

Nidec:

For batches of ribbon cables that were built before PCAs were put in place at Tyco, Nidec found 22 out of 14,800 with misalignment.

Since Nov 12, Nidec has 0 fallout at IQ for ribbon cable misalignment when inspected with 5x magnification.

Nidec inspected 69,122 motor assys that were already built before the ribbon cable visual inspections went into place on Nov 12. They found 638 suspect parts. They x-rayed 42 of them and found 9 to be misaligned. They are going through the rest and visually re-checking them with 30x magnification to find which parts are truly misaligned.

Since Nov 11, Nidec has been inspecting motor assys at EOL for conformal coat running from the relay. This is the same day they fixed the conveyor. They have 0 fall out for concoat since this date.

For conformal coat inspections on finished stock, they have quarantined 11k parts. These are parts with any amount of conformal coat at the connector from the relay.

Anting:

From 11/11-11/21, Anting found 15 out of 25,783 assys with protruding wires (misalignment) and rejected these parts. Anting initially reported that they had 30% fallout for conformal coat at the connector. Since 11/24, they have 0 fallout.

Shalke and Nove Mesto:

Shalke and Nove Mesto have been inspecting for misalignment since Nov 15 with 0 fallout.

Next Steps:

TRW is going through each and every return to determine root cause of B9A and B3A/B43.

There is a study going on between TRW and Nidec with help from Tyco to confirm that conformal coat is the root cause of the high resistance measured on parts that do not have misaligned cables. This is to confirm that there is no other root cause of failure.

Regards,

*Laura Napoli*

D3 and U502 EPAS  
Ford Motor Company  
Cube: 2B-G66 PDC  
Phone: 313.323.0634  
Mobile: 313.805.0482



---

**From:** Napoli, Laura (L.)  
**Sent:** Thursday, October 13, 2011 5:00 PM  
**To:** Estes, Eric (E.E.)  
**Cc:** Surella, Matthew (M.M.); Perri, Ron (R.J.)  
**Subject:** RE: Buyback U502 Vehicle with B9A

Eric, thanks for getting me in touch with the FCSD rep. He contacted me and told me that all Engineering Buy Backs need to go through DST. Since this could take a while, Ron Perri agreed that we can let this car go. So I called Jeff and told him to replace the gear on this car and give it back to the customer. Once we get the DST process in place, I will let you know to start your search again. Hopefully in the meantime we will find a Ford employee or Management Lease car we can use instead.

Please keep your search going for cars that are repeatable and let me know if you find one. At the very least, we still want to send John out to take data on any vehicle with a repeatable B9A.

---

**From:** Estes, Eric (E.E.)  
**Sent:** Thursday, October 13, 2011 4:11 PM  
**To:** Napoli, Laura (L.)  
**Cc:** Surella, Matthew (M.M.)  
**Subject:** Buyback U502 Vehicle with B9A  
**Importance:** High

Laura I talked to Jeff the service manager at this dealer to hold the vehicle, this problem only happened once to the customer and the dealer could not duplicate the code after clearing. Good chance the customer would release this vehicle since they state they almost got into an accident with the steering locked up

Let me know

Eric

Top of Form

---

Vehicle:	2011,EXPLORER 4X4 (U502) ,XLT ,4 DOOR ,MPV ,1FMHK8D86BG [REDACTED]	Build Date:	03/20/2011		
Odometer :	10,258 M	Engine:	3.5L CYCLO	Calibration:	BUB1SN0A
Transmission:	6F50	Axle:		A/C:	YES
Dealer:	USA 03605 Sunshine Ford-Lincoln, Inc.	Phone#:	(845) 561-3900		
City:	Newburgh	State:	New York	Country :	USA
Originator:	BRIAN WARREN				
Symptom:	6 62 4 28 SP/ST/RD,STEER/STER WHL,PERFORMANCE,EXCESS EFFORT				
Status:					
VFG:	V87 STEERING				
Additional Symptom:	STEERING FAULT				
Fix:	Causal Component :				

Condition Code:

Hotliner: JREDDMAN

Phone: 000 248-9292

Regn Cd: N1 New York

Engineering:

Phone:

TAR:

Dlr Contact: BRIAN WARREN

Phone: 000 000-0000

Title Cde: T

---

Bottom of Form

**KOEO:** C1B00:86 C200D:49

**KOEC:**

**KOER:**

Comments:

REPAIR 10/11/2011 01:30PM JOSEPH REDDMANN MSS - FCSD - TECH SVC HOTLINE  
WEB FORM DATA - CONCERN:C/S STEERING LOCKED UP, ALMOST CAUSED  
COLLISION. DIAGNOSTICS: CK. DTCS,ROAD TEST, PERFORMED PINPOINT  
TESTS PARTS REPLACED:NONE TECH QUESTION:CONCERN WAS NOT VERFIED,  
AFTER PERFORMING PINPOINT TEST B3 NO DTCS WERE RECORDED. DUE TO THE  
NATURE OF THIS CONCERN PLEASE ADVISE.

RECOMM 10/11/2011 01:30PM JOSEPH REDDMANN MSS - FCSD - TECH SVC HOTLINE  
BRIAN, BASED ON THE DESCRIPTION OF THE CONCERN, THE DTCS THAT ARE  
PRESENT AND PRIOR HOTLINE REPORTS, WE RECOMMEND THAT YOU REPLACE THE  
STEERING RACK AND RE-EVALUATE THE CONCERN. IF YOU NEED ANY  
ADDITIONAL ASSISTANCE, PLEASE UPDATE THIS FORM IN THE SPACE  
PROVIDED. ISM 11-08-019 LOSS OF POWER STEERING ASSIST WITH C200D IN  
PSCM

---

Bottom of Form

*Eric J Estes*

TRW EPAS Steering Systems

Quality Specialist

Hotline ph# 313-317-9358

Cell ph# 734-560-3493

---

**From:** Napoli, Laura (L.)  
**Sent:** Wednesday, November 30, 2011 11:47 AM  
**To:** Surella, Matthew (M.M.); Perri, Ron (R.J.)  
**Subject:** RE: Pareto for B9A confirmed root causes

**Attachments:** B9A serial numbers all belt drive 11-30-11.xlsx

I've added the quantity of parts under analysis to the Pareto...



B9A serial numbers  
all belt dr...

---

**From:** Napoli, Laura (L.)  
**Sent:** Wednesday, November 30, 2011 11:43 AM  
**To:** Surella, Matthew (M.M.); Perri, Ron (R.J.)  
**Subject:** Pareto for B9A confirmed root causes

Attached is the updated spreadsheet for B9A root cause analysis on each warranty return. I've created an updated Pareto for all confirmed and removed the ones still under analysis.

<< File: B9A serial numbers all belt drive 11-30-11.xlsx >>

There have been NO B9A failures at any assy plant. I'm waiting for the updated data on the total number of parts returned to update what you have in the 6-panel. The only recent failure is 1 for . I'll send that over once I have it done.

Regards,

*Laura Napoli*

D3 and U502 EPAS  
Ford Motor Company  
Cube: 2B-G66 PDC  
Phone: 313.323.0634  
Mobile: 313.805.0482


Case Number	U502 B9A EPP s/n	Motor Build date	Ribbon Cable Date	Root Cause
UR0048	103601919G30367	2010-12-04		conformal coat
UR0059	110291919G31227	2010-12-28	2010-11-15	misalignment
UR0060	110771919J30898	2011-01-25	2010-11-16	misalignment
UR0061	110291919G30593	2010-12-27	2010-11-16	conformal coat
UR0062	110291919G30862	2010-12-28	2010-11-17	conformal coat
UR0063	103631920G30133	2010-12-06	2010-10-25	conformal coat
UR0064	110261919G30786	2010-12-24	2010-11-17	misalignment
UR0065	103591919G30091	2010-12-24	2010-10-12	conformal coat
UR0070	110281919G30095	2010-12-28	2010-11-26	misalignment
UR0071	110621919J30710	2011-01-20		conformal coat
UR0073	110761919J31074	2011-01-24		conformal coat
UR0075	110451919G30577	2010-12-30		conformal coat
UR0076	110291919G30300	2010-12-27	2010-11-16	misalignment
UR0077	110071919G30749	2010-12-24		conformal coat
UR0079	110481919G30125	2010-12-30	2010-11-16	misalignment
UR0080	110491919J30546	2010-12-30		conformal coat
UR0081	110151919G30544	2010-12-23		conformal coat
UR0082	110071919G30887	2010-12-24		conformal coat
UR0083	103181919F31151	2010-10-27		conformal coat
UR0084	103601919G30305	2010-12-04		conformal coat
UR0085	103381919G30931	2010-11-08		conformal coat
UR0086	110631920J30819	2011-01-03		conformal coat
UR0087	110291919G30215	2011-12-27	2010-11-16	misalignment
UR0088	103521919G31407	2010-11-11		conformal coat
UR0089	110141919G30775	2011-12-23		conformal coat
UR0092	103561919G30991	2010-11-12		conformal coat
UR0095	110271919G30664	2010-12-25	2010-11-15	misalignment
UR0098	103521919G31407	2010-11-11		conformal coat
UR0099	103451919G30811	2010-11-10		conformal coat
UR0100	110901919J35745	2011-02-12		conformal coat
UR0101	110761919J30756	2011-01-24		conformal coat
UR0104	110151919G30511	2011-12-23		conformal coat
UR0105	110421919G30598	2011-12-29		conformal coat
UR0108	110081919G30406	2011-12-24		conformal coat
UR0109	103031919F30809	2010-10-25		conformal coat
UR0111	110151919G30342	2010-12-23		conformal coat
UR0113	110161919G30045	2011-12-23		conformal coat
UR0114	110261919G30136	2010-12-27		conformal coat
UR0115	110291919G30096	2010-12-27		conformal coat
UR0117	110281919G30762	2011-12-28	2010-11-15	misalignment
UR0120	110911919J35411	2011-02-15	2010-12-21	misalignment

Redacted for Relevance

Redacted for Relevance

	U502	Redacted
con coat	31	for
misalignment	10	Relevance
hall effect	0	
Reg. Pwr Up	0	
under analysis	15	

### B9A Root Causes



Redacted for Relevance



Redacted for Relevance

Redacted for Relevance

---

**From:** Anthony Fleenor <Anthony.Fleenor@TRW.COM>  
**Sent:** Friday, May 04, 2012 9:57 AM  
**To:** Jawed, Afaq (.)  
**Cc:** Estes, Eric (E.E.); Andrew Ellison; Bobby Supel; Salim Semssar  
**Subject:** RE: RE: 12 04 Warranty Review Ford Only.pptx  
**Attachments:** BSAQ Status rev3.xlsx

Per your request to change any issue that is awaiting a design change to "Design".

As I explained, some of these were initially a quality processing issue but we found that a design change would help to prevent it from occurring again, such as the silver contact and the piston ring damage.

>>> "Jawed, Afaq (.)" <[ajawed@ford.com](mailto:ajawed@ford.com)> 5/4/2012 9:46 AM >>>

Please call me at 313-805-2381. Thanks

*Afaq Jawed*

*STA, Ford Chassis Commodity*

*Phone: 313 805 2381 (Work/Cell)*

*Cube; C156 Fairlane Business Park II,*

*17425 Federal Drive Allen Park MI 48101, USA*

*E-mail; [ajawed@ford.com](mailto:ajawed@ford.com)*

*Text Pager: <http://messaging.sprintpcs.com>*

---

**From:** Anthony Fleenor [mailto:Anthony.Fleenor@TRW.COM]  
**Sent:** Friday, May 04, 2012 9:32 AM  
**To:** Jawed, Afaq (.)  
**Cc:** Estes, Eric (E.E.); Andrew Ellison; Bobby Supel  
**Subject:** RE: RE: 12 04 Warranty Review Ford Only.pptx

Hello AJ,

Please see attached.

Sorry, I did not answer your first question in the response.

It means that I am waiting for information from Ford PD regarding the status of closure but, so far, the containment dates are clean which means we do not have a part returned confirmed with that issue after the containment date was established.

>>> "Jawed, Afaq (.)" <[ajawed@ford.com](mailto:ajawed@ford.com)> 5/3/2012 9:55 PM >>>

Hi Tony;

What does it means by " Waiting response-but no current containment or PCA dates have been broken". Please explain.

Further I need to know the containment actions as summary, the next step. I would like to know how many issues are related to design and or quality. Thanks

*Afaq Jawed*

*STA, Ford Chassis Commodity*

*Phone: 313 805 2381 (Work/Cell)*

*Cube; C156 Fairlane Business Park II,*

*17425 Federal Drive Allen Park MI 48101, USA*

*E-mail; [ajawed@ford.com](mailto:ajawed@ford.com)*

*Text Pager: <http://messaging.sprintpcs.com>*

---

**From:** Anthony Fleenor [mailto:[Anthony.Fleenor@TRW.COM](mailto:Anthony.Fleenor@TRW.COM)]

**Sent:** Thursday, May 03, 2012 3:55 PM

**To:** Jawed, Afaq (.); Bobby Supel

**Subject:** Fwd: RE: 12 04 Warranty Review Ford Only.pptx

Please see attached for what we have to date relative to the BSAQ's we discussed.

>>> "Jawed, Afaq (.)" <[ajawed@ford.com](mailto:ajawed@ford.com)> 4/26/2012 10:33 AM >>>

Please review the attached file, and the following; Let me know the correct number of issues open and please get it closed if you feel it should be closed. Thanks

*Afaq Jawed*

*STA, Ford Chassis Commodity*

*Phone: 313 805 2381 (Work/Cell)*

*Cube; C156 Fairlane Business Park II,*

*17425 Federal Drive Allen Park MI 48101, USA*

*E-mail; [ajawed@ford.com](mailto:ajawed@ford.com)*

*Text Pager: <http://messaging.sprintpcs.com>*

Redacted for Relevance

Open	Open	SP	SP	Chicago	EXPLORER (NA-CAP)	Chassis	FNVCC	T210R	TRW INC
Open	Open	SP	SP	Chicago	EXPLORER (NA-CAP)	Chassis	FNVCC	T210R	TRW INC

---

**From:** Anthony Fleenor [mailto:Anthony.Fleenor@TRW.COM]  
**Sent:** Wednesday, April 25, 2012 6:52 AM  
**To:** Jawed, Afaq (.); Flanagan, Thomas (T.P.)  
**Cc:** Estes, Eric (E.E.); Salim Semssar  
**Subject:** 12 04 Warranty Review Ford Only.pptx

A.J., Tom,

Attached is the file we reviewed yesterday in Rogersville.

It was a pleasure to meet both of you.

Tony Fleenor  
TRW Steering Warranty  
423-272-4221

TRW Steering Open BSAQ Status

BSAQ	Veh	Concern Title	Author	Active	Type	Status	Open Date	ICA Date	PCA Date	Description	ICA/PCA Summary	Status/What is needed to close(from Ford PD)?	Quality/Design
Redacted for Relevance													
SAQ2011187769	U502	EPAS gears with C2000 DTC (B9A)-ribbon misalignment	BJACKSON	Y	CHRONIC	TWO	17-Aug-11	12-Jan-12		Loss of assist due to ribbon cable cutting misalignment causing wire protrusion	1.400% inspection. 2. New tooling to reduce clearance around part when cutting ribbon cable.	No containment broken but we are rebuilding ribbon cable tools at Tyco so remain open and monitor until that is complete	Quality
SAQ2012206614	U502	EPAS gears with C2000 DTC (B9A)-conformal coating	MFARMER2	Y	CHRONIC	CMR	17-Aug-11		26-Dec-11	Loss of assist due to conformal coating on PCB running over onto contacts, circuits	200% UV light inspection at supplier for conformal coat running over.	per plant PVT: "the subject BSAQ project is already in "complete monitor" mode. This is where a project stays, when no further actions are going to be done." Based on this, PD has said we could consider it closed.	Quality
SAQ2012208065	U502	EPAS B3A and B43 relay failures	MFARMER2	Y	CHRONIC	TWO	1-Jun-11	17-Jan-12	Sep-12	Loss of assist due to CuS contamination of relay contacts (bi-metal) in cracks	Scrap 1" 1,000 pieces at each machine stop. Inspect 1" ten pieces under microscope for cracks. Change to solid silver contacts and implement deburr process	Although no containment is broken to date, we will keep open until silver relay is implemented in Aug 2012 since that is the permanent corrective action	Design
SAQ2012214003	U22X	Steering Rack Defective Piston Ring	SGARRE16	Y	CHRONIC	CMR	1-Nov-11	28-Feb-12	Oct-12	Piston ring damage due to overstretching, sling issues and snagging the piston ring at assembly	Additional operator training, improved assy tools, increased dwell time at assy and improved scrap/reject handling implemented. Investigating a design change to the piston ring/piston material/dimensions to ease assy.	Keep open until design change is implemented planned for Oct 2012	Design

Rows 3, 4 and 7 are the same issue

---

**From:** Napoli, Laura (L.)  
**Sent:** Wednesday, June 06, 2012 2:04 PM  
**To:** Farmer, Marty (M.F.)  
**Cc:** Brown, Jude (J.); Surella, Matthew (M.M.)  
**Subject:** RE: U502/[redacted]"New" Clean dates

Here are the clean dates for CAP programs for CuS on relays and misaligned ribbon cables...

CuS fix on motor and link relays:

- [redacted]
- [redacted]
- U502 48mm: 2/10/2012
- U502 58mm: 2/23/2012

Ribbon Cable Misalignment:

- [redacted]
- [redacted]
- U502 48mm: 6/30/2012
- U502 58mm: 8/8/2012

[redacted]

[redacted] We know U502 is already shipping a mix of parts before and after the clean date. Not sure what the ratio is. It's the best I have for you now. If they ask why each program is so different, you should tell them that high volume (like U502 48mm) gets clean quicker because they build more often. The lower volume programs get built in large batches and stored until requested by TRW. For example, for U502 58mm, Nidec only builds once every 1-2 months based on the orders. Therefore they're holding old stock and not using it at TRW until now.

Regards,

*Laura Napoli*

D3 and U502 EPAS  
Ford Motor Company  
Cube: 2B-G66 PDC  
Phone: 313.323.0634  
Mobile: 313.805.0482

---

**From:** Farmer, Marty (M.F.)  
**Sent:** Wednesday, June 06, 2012 9:55 AM  
**To:** Napoli, Laura (L.)  
**Cc:** Brown, Jude (J.)  
**Subject:** U502/[redacted]"New" Clean dates

Laura,

Please send Jude and I clean dates for the misaligned ribbon cable and relay contamination.





---

**From:** Napoli, Laura (L.)  
**Sent:** Tuesday, February 08, 2011 2:57 PM  
**To:** 'Andy Partridge'; Bahena, Miguel (Mike.); Snider, Tim (T.O.)  
**Cc:** Estes, Eric (E.E.); Mrozek, Robert (R.M.); Rossi, Roberto (R.A.); Diez, Timothy (T.P.); Geoff Jacks; Michael Fontana  
**Subject:** RE: UR-0001 B3A Motor Relay Contamination Pictures

Thanks Andy. Please send an update later today with the material analysis on the first relay.

Another request for you that we can discuss on Wed:  
Can you start putting together the finished relay wash audit results from the period that the two failed U502 relays were built (include build month +\ - 2mo)? I know the 1st relay was Aug 3, 2010. Once we confirm the failure mode of the 2nd relay, we'll need that build date along with it's wash audit data assuming contamination is found. Please include the results from the quarterly contamination wash audit over the last year.

Regards,

Laura Napoli  
U502 EPAS  
Ford Motor Company  
Cube: 2B-G66 PDC  
Phone: 313.323.0634  
Mobile: 313.805.0482

-----Original Message-----

From: Andy Partridge [mailto:Andy.Partridge@TRW.COM]  
Sent: Tuesday, February 08, 2011 4:30 AM  
To: Napoli, Laura (L.); Bahena, Miguel (Mike.); Snider, Tim (T.O.)  
Cc: Estes, Eric (E.E.); Mrozek, Robert (R.M.); Rossi, Roberto (R.A.); Diez, Timothy (T.P.); Geoff Jacks; Michael Fontana  
Subject: RE: UR-0001 B3A Motor Relay Contamination Pictures

Hello Laura.

Tyco have carried out 2 actions:

1) The dampers of the ruler that removes the coil bodies from the axis of the winding machine, occasionally creates burrs, a new concept to stabilize the movement of the ruler was studied. (Module 2). Implemented :10-12-2010

2) Implement a preventive maintenance plan for all critical points in production line related with possible origin of particles. 07-01-2011

I will verify both of these actions and we shall have a fresh eyes approach to contamination on the line during the audit today.

The first B3A is now back in the UK and will undergo EDX analysis to confirm the composition of the contamination. Tyco do not currently believe this is plastic contamination. I will confirm as soon as we have some results.

I believe the second B3A has arrived in Portugal and is due at the plant late today. We shall start analysis as soon as it gets here.

I will send an update on the workshop at around 9pm UK time

Regards  
Andy

>>> "Napoli, Laura (L.)" 02/04/11 9:18 PM >>>  
Andy,

Since we've had issues with plastic in the past, can you get Tyco to immediately review that process with you and get actions in place for interim containment we can put in place first thing Monday?

Please let me know when the U502 part has confirmation on the type of contaminant. There is a second U502 part at 26mile that is being x-rayed with a B3A if you are not aware. If no problem is found in the x-ray, the part needs immediate analysis for contamination.

Regards,

Laura Napoli  
U502 EPAS  
Ford Motor Company  
Cube: 2B-G66 PDC  
Phone: 313.323.0634  
Mobile: 313.805.0482

-----Original Message-----

From: Andy Partridge [mailto:Andy.Partridge@TRW.COM]  
Sent: Friday, February 04, 2011 9:15 AM  
To: Bahena, Miguel (Mike.); Snider, Tim (T.O.)  
Cc: Estes, Eric (E.E.); Napoli, Laura (L.); Mrozek, Robert (R.M.); Rossi, Roberto (R.A.); Diez, Timothy (T.P.); Geoff Jacks; Michael Fontana  
Subject: RE: UR-0001 B3A Motor Relay Contamination Pictures

Hi Mike.

Tyco did not indicate what the contamination was or where they thought it had come from. The contamination is small so we believe that EDX analysis is the best way to find the composition of it. I shall do a thorough line walk audit looking at any causes of contamination and looking at their containments on Tuesday.

Regards  
Andy

>>> "Bahena, Miguel (Mike.)" 02/04/11 1:19 PM >>>  
Andy,

Any indication if the contamination is plastic or do we need to wait and see what the SEM/EDX analysis shows.

Sincerely,

Mike Bahena  
D3 Electric Power Steering Systems  
Ford Motor Co.  
Ph: (313) 805-3680  
mbahenal@ford.com

-----Original Message-----

From: Andy Partridge [mailto:Andy.Partridge@TRW.COM]  
Sent: Friday, February 04, 2011 4:02 AM  
To: Snider, Tim (T.O.)

Cc: Estes, Eric (E.E.); Napoli, Laura (L.); Bahena, Miguel (Mike.);  
Mrozek, Robert (R.M.); Rossi, Roberto (R.A.); Diez, Timothy (T.P.);  
Geoff Jacks; Michael Fontana  
Subject: Re: UR-0001 B3A Motor Relay Contamination Pictures

Hello Tim.

Please find enclosed the report from Tyco as requested. The circular  
mark on contact 3 is from the rivetting machine and is not an issue that

would cause this failure.

In discussion with Tyco we have decided that it will be quicker to  
return this relay to TRW for SEM and EDX analysis rather than utilise  
the laboratory in Germany. Assuming we receive the relay by Tuesday, we  
shall be able to report back the composition of the contamination in the

call on Wednesday.

If you need any further information, I'm available at Tyco via e-mail or  
on my mobile number listed below.

Regards  
Andy

Quality and Product Support  
TRW Electronic Engineering  
Technical Centre  
Stratford Road  
Shirley  
B90 4GW

Tel: +44 (0)121 627 3143  
Mob: +44 (0)7920 134912

>>> "Snider, Tim (T.O.)" 2/3/2011 7:54 pm >>>  
Andy,

Please forward the pictures of the UR-0001 motor relay contamination you  
showed Wednesday. Thanks.

Regards,  
Tim Snider (tsnider1@ford.com)  
CD3/C489 Steering Engineering  
Ford Motor Company  
Cell 313-805-3201  
2B-L18 Product Development Center  
Dearborn, MI 48124 USA

**From:** [Surella, Matthew \(M.M.\)](#)  
**To:** [Flanagan, Thomas \(T.P.\)](#)  
**Subject:** RE: Ford Explorer IN: 1FMHK8F83CGA06603 Kms: 17005 - Steering gets hard intermittently  
**Date:** Friday, March 23, 2012 8:35:51 AM

---

C200D (B9A) was not completely clean until January. Eric's chart shows 1/16 but in Bennie F meetings we have been using 1/30 so please use 1/30 as clean date. This is the date for clean parts starting to be used at Fusion assembly plant (HSAP). This is the same date we are using for U502 in Chicago and  in MAP. I don't know where they got November???

Please see typo in your note below. 1/17 is clean date for B3A on Fusion. Thanks.

Matthew (Matt) Surella  
Steering EPAS Supervisor / MBB  
313-805-3997

---

**From:** Flanagan, Thomas (T.P.)  
**Sent:** Friday, March 23, 2012 7:40 AM  
**To:** Surella, Matthew (M.M.)  
**Subject:** FW: Ford Explorer IN: 1FMHK8F83CGA06603 Kms: 17005 - Steering gets hard intermittently

Matt,

See note below.

I do not want to respond until I have a good understanding. Laura is out today. Do you know what the clean dates and corrective actions were for the C200D and B3A issues? I know the clean date for B3A is 11/17/11. The email below shows C200D. There were 2, 2012 U502 units.

Tom Flanagan  
Ford Motor Company  
CD3, D3 EPAS Steering Engineering  
PDC 2B-K24  
(313) 845-4062  
Cell (313) 815-6885

---

**From:** Robinson, Mark (.)  
**Sent:** Thursday, March 22, 2012 12:20 PM  
**To:** Flanagan, Thomas (T.P.)  
**Cc:** Allie, Abdul (A.D.)  
**Subject:** FW: Ford Explorer IN: 1FMHK8F83CGA06603 Kms: 17005 - Steering gets hard intermittently

Hi Thomas,

I need your help. You may have this information at your fingertips. Can you tell if the EPAS ribbon cable concern on the Fusion is linked to the Explorer U502? This concern I believe was resolved at the end of Nov. 2011 for the Fusion vehicle line. We are seeing concerns on the Explorer U502 EPAS hard to turn intermittently.

---

**From:** Allie, Abdul (A.D.)  
**Sent:** Thursday, March 22, 2012 10:57 AM  
**To:** Dallalah, Ziyad (Z.F.); Mueller, John (F.); Robinson, Mark (.)  
**Cc:** Hansen, Thayne (T.); Noel, Chris (C.R.)  
**Subject:** FW: Ford Explorer IN: 1FMHK8F83CG [REDACTED] Kms: 17005 - Steering gets hard intermittently

I checked NA data base and no EPAS concern is listed for the U502. Mark will need to check GCQIS for further analysis.

I was able to locate similar concern (submit in AEQ) on the [REDACTED] in NA which was closed on March 20, 2012. But will need to confirm.

REDACTED FOR RELEVANCE

---

**From:** Dallalah, Ziyad (Z.F.)  
**Sent:** Thursday, March 22, 2012 10:32 AM  
**To:** Mueller, John (F.); Allie, Abdul (A.D.)  
**Cc:** Hansen, Thayne (T.); Noel, Chris (C.R.)  
**Subject:** RE: Ford Explorer IN: 1FMHK8F83CG [REDACTED] Kms: 17005 - Steering gets hard intermittently

Abdul

Details on UAE vehicle:

The Loss of assist happened under the following conditions:

- 1) Turning inside a parking lot (garage)
- 2) U-turn

Upon engine shut down and restart by customer the issue went away and returned.

Regards,

Ziyad Dallalah "Z"

Ford Motor Company

Product Development & Vehicle Engineering

Middle East (Levant & Gulf) Markets

**UAE MoBile: +971-50-4543647**

Email: [zdallala@ford.com](mailto:zdallala@ford.com)

---

**From:** Mueller, John (F.)  
**Sent:** Thursday, March 22, 2012 6:11 PM  
**To:** Allie, Abdul (A.D.)  
**Cc:** Dallalah, Ziyad (Z.F.); Hansen, Thayne (T.); Noel, Chris (C.R.)  
**Subject:** FW: Ford Explorer IN: 1FMHK8F83CG [REDACTED] Kms: 17005 - Steering gets hard intermittently

Abdul

We have two 2012 Explorers in the region where the steering system loses power assist. The one below is from Altayer and second is Qatar. In both cases the powersteering lost assist. Can you look into this to see if this is a known issue in the U.S. We need to include this in our Monday meeting as part of our escalation process.

I will provide the second vehicle with its details shortly once I receive them from Qatar

*Regards*

*John Mueller*

*Technical Service Operations Manager*

*Service Engineering Operations*

*Ford Middle East*

*Mobile: 971 50 640 4053*

---

**From:** Noel, Chris (C.R.)  
**Sent:** 22 March 2012 15:05  
**To:** Mueller, John (F.)  
**Subject:** FW: Ford Explorer IN: 1FMHK8F83CG [REDACTED] Kms: 17005 - Steering gets hard intermittently

Please investigate and let me know if this is a wider concern

---

**From:** Ravindran S [mailto:sravindran@altayer-motors.com]  
**Sent:** Thursday, March 22, 2012 2:52 PM  
**To:** Noel, Chris (C.R.)  
**Cc:** Viji Baby  
**Subject:** Ford Explorer VIN: 1FMHK8F83CG [REDACTED] Kms: 17005 - Steering gets hard intermittently

Hi Chris,

We had checked the subject vehicle and the details are as below:-

**Customer complaint:** Steering wheel got extremely hard as if it got locked and making it difficult to steer. Power steering system fault message appeared in the Message Center. The problem occurred 9 days back and again it appeared yesterday.

**Diagnosis:** Power Steering fluid level and quality are ok.

There were 2 DTCs in Continuous memory.

1<sup>st</sup> DTC – C200D-49-08-PSCM – Motor rotation angle sensor failure

2<sup>nd</sup> DTC – C1A02-23-08-ATCM – Rotor encode start in intermediate position

We did the pin point test and could not find any abnormalities. As per the last step in pin point test we have to test the vehicle and check for codes again. If the code appears again the rack has to be replaced. In this case there is no code after test drive. The matter was discussed with Mr. John Mueller also. Since the problem has appeared 2 times to the customer, the possibility of getting the problem again is high. Being a safety related issue, we do not want to take any chance and John Mueller also recommended replacement of the rack. As of now, rack assly is not available in PDC. We do not have any vehicle for cannibalization. Request your assistance in getting the part faster.

Regards

Ravindran S  
Area Service Manager

**Al Tayer Motors**

PO Box 7310, Dubai,UAE

Tel: +971 4 3037704

Fax: +971 4 3401924

[sravindran@altayer-motors.com](mailto:sravindran@altayer-motors.com)


[www.altayermotors.com](http://www.altayermotors.com)

---


**Disclaimer:**

This message, together with any attachments, is confidential, is intended only for the use of the addressee(s) and may contain information which is covered by legal, professional or other privilege. If you are not the intended recipient, any copying, distribution or use of this email or its attachments, or of the information contained therein, is strictly prohibited; please destroy this email and its attachments and notify us immediately.

Any opinions expressed, implied, or presented are solely those of the author and do not necessarily represent those of the Al Tayer Group.









---

**From:** Annadi, Hari (H.)  
**Sent:** Wednesday, August 24, 2011 6:17 PM  
**To:** Napoli, Laura (L.); Mrozek, Robert (R.M.); Perri, Ron (R.J.)  
**Cc:** Flanagan, Thomas (T.P.); Jackson, Bradley (B.G.)  
**Subject:** RE: U502 C200D (B9A)

Thanks for the update Laura.

Ron - This item is RED for the form 4 and will come up at the PDQR tomorrow.

---

**From:** Napoli, Laura (L.)  
**Sent:** Wednesday, August 24, 2011 4:12 PM  
**To:** Mrozek, Robert (R.M.); Annadi, Hari (H.)  
**Cc:** Flanagan, Thomas (T.P.)  
**Subject:** U502 C200D (B9A)

Hari, Rob,

The C200D-49 Ford DTC is a TRW B9A Fault Code. We have 5 gears that have been returned to the WPRC that are in TRW's hands and are being tested on the Marion, 26mile, and UK test stands. There are more parts out there that haven't been shipped back since the gears were on back order. I expect to get approx 5 more once the release issue with Service is cleared up. CAP knows the exact total since Brad Jackson has been tracking the ECB claims.

TRW was never able to duplicate the first B9A failure. We tried in every possible way at Marion and in the UK and it would not trip. We then tore down the HW and measured individual components and found nothing wrong with the part.

There is a second gear on the test stand at 26mile which has been repeatedly duplicated. The B9A will trip when Vehicle Tune 4 (3.5L AWD) is selected with the J1+90 SW. They then switched the Veh Tune to the TRW End Of Line Veh Tune and the B9A did not trip. They also tested this EPP with old  SW and could not get the B9A to trip with either Veh Tune 4 or EOL Tune.

They think that the B9A is linked to SW and/or Calibration. They just don't know what in the SW or Cal is causing it to trip. All they know right now is that the Hall Effect and the Encoder are getting out of sync. An offset emerges and starts to creep which moves the standard diagnostic towards the threshold.

I have 26mile running the EPP with J1 SW to all 4 Veh Tunes and J1+90 SW with the other 3 they didn't run yet. Eric Estes is tracking the claims to see if all are 3.5L AWD vehicles and to see if they all have J1+90 SW on them. I've also asked TRW if there is a standard offset we can enter into the Cal file as an ICA and they said no. The offset is usually low and increases on occasion.

I will have more on Monday from 26mile and Wed from the UK.

Regards,

*Laura Napoli*

D3 and U502 EPAS  
Ford Motor Company  
Cube: 2B-G66 PDC  
Phone: 313.323.0634  
Mobile: 313.805.0482



# U502 EPAS TGW's

Laura Napoli

Rob Mrozek

5/2/2011

# U502 V87 TGW's

Count of VIN			Production Year		Production Month	Grand Total
Model	VFG	Checkbox	2010	2011		
EXPLORER	V87-STEERING	H21A -Steering - Response - Too quick/sensitive	1	1	1	3
		H22B -Steering - Effort - Too soft/light			1	1
		H50 -STEERING GEAR/PUMP TRBLS **		1		1
		N58 -STEERING - UNUSUAL NOISE - WHILE TURNING			1	1
V87-STEERING Total			1	2	3	6
EXPLORER Total			1	2	3	6
Grand Total			1	2	3	6

Checkbox	VIN	Model Yea	Plant	Model	VerbEnglish
H50 -STEERING GEAR/PUMP TRBLS **	1FMHK8D87BG [REDACTED]	2011	CHICAGO	EXPLORER	Power steering warning light came on, then steering went out
H21A -Steering - Response - Too quick/sensitive	1FMHK7B8XBG [REDACTED]	2011	CHICAGO	EXPLORER	Every car I have owned has been a Ford. have had 3 Explorers in the past and I am still getting used to the sensitive steering. When I speed up and change lanes the vehicle has a tendency to swerve a bit. Nothing major, just not used to the steering yet
H21A -Steering - Response - Too quick/sensitive	1FMHK7F85BG [REDACTED]	2011	CHICAGO	EXPLORER	Does not seem to hug the road.
N58 -STEERING - UNUSUAL NOISE - WHILE TURNING	1FMHK8F84BG [REDACTED]	2011	CHICAGO	EXPLORER	
H21A -Steering - Response - Too quick/sensitive	1FMHK8F84BG [REDACTED]	2011	CHICAGO	EXPLORER	Unexplainable going in for service. After/during kick start steering is very wobbly and erratic. Almost uncontrollable.
H22B -Steering - Effort - Too soft/light	1FMHK8F84BG [REDACTED]	2011	CHICAGO	EXPLORER	Unexplainable going in for service. After/during kick start steering is very wobbly and erratic. Almost uncontrollable.

**Note: These vehicles have not been brought to dealers for service.**



# H50 – Steering Gear/Pump Troubles

“Power steering warning light came on, then steering went out.”

- Loss of Assist is the safe-state for EPAS when the electronics are suspected to be faulty.

**There are 3 general root causes for loss of assist:**

- 1) **EPP or TS HW Failure:** ECU, PFS, Motor, and TS HW failures set a B-level fault. POWER STEERING FAULT appears in the msg center and assist is removed. DTC will be stored. On the next key cycle, if the issue does not return, assist will return and the message will go away. If the HW failure is still present, B-level code will continue to be raised and gear will eventually lock out, removing assist permanently.  
Current known EPP and TS faults:
  - Relay Icing: SW robustness action implemented 4/4/2011 (Veh sold in Fenton, MI on 12/30/10.)
  - B3A: motor relay contamination (contamination improvements in place)
  - BD0-BD4: Torque Sensor bent finger (400% visual inspection in place)
- 2) **SW monitor faults:** SW Monitors track torque loop calculations by running similar calculations as the main torque loop. If the monitor calculation differs by more than the allowable value from the main calculation, a B-level fault will raise, POWER STEERING FAULT appears in msg center, and assist will be removed. Once the key is cycled, assist will return and the message will go away. DTC will be stored.
- 3) **High Friction:** If the Friction Detection Algorithm senses high friction in the rack, SERVICE POWER STEERING appears in msg center and assist efforts increase. On the next key cycle, SERVICE POWER STEERING NOW appears in msg center and assist is removed until codes are cleared. DTC will be stored.



# V87 Claims related to Ride and Handling

H21A—Steering Response too quick/sensitive

H22B—Steering Efforts too soft/light

- “After/during kick start steering is very wobbly and erratic. Almost uncontrollable.”
  - This complaint is related to torque steer which is inherent to the Explorer and is seen in Veh Dyn CQIS claims binned to V89 (H28). Torque steer is a function of front suspension geometry, half shaft angles, and CG. Core Veh Dyn is working closely with CAP VE PVT on all torque steer claims. 2013MY U502 is getting the benefit of TSC (torque steer compensation) which will improve the number of these claims, but does not eliminate the issue.

H21A—Steering Response too quick/sensitive

- “I have had 3 Explorers in the past and I am still getting used to the sensitive steering. When I speed up and change lanes the vehicle has a tendency to swerve a bit. Nothing major, just not used to the steering yet.”
  - Could be experiencing torque steer. Driver seems to be getting familiar with sensitivity of the vehicle and EPAS steering feel.
- “Does not seem to hug the road”
  - Veh Dyn/Chassis Systems issue. Vehicle initially released with rubber mounts. TRW started shipping all gears with urethane mounts on April 4th. Solid mounts planned for 2013.5MY which will help Veh Dyn achieve the finest level of tuning.

---

**From:** Jackson, Bradley (B.G.)  
**Sent:** Thursday, September 15, 2011 10:19 AM  
**To:** Napoli, Laura (L.); Estes, Eric (E.E.); Flanagan, Thomas (T.P.)  
**Cc:** Surella, Matthew (M.M.); Mrozek, Robert (R.M.)  
**Subject:** U502 gears replaced 20110914 for C200D

Here are the gears that were replaced yesterday (14 September) at dealers. 4 of the 5 were C200D DTC. 1 gear I am going to guess will come back as a NPF, as it looks like the vehicle had a wiring issue (BGA72610). Attached are the IDS files confirming the (4) C200D calls.



At what point will we have enough gears returned back from the field for analysis that we can stop asking for them?

Brad

---

**From:** Jackson, Bradley (B.G.)  
**Sent:** Wednesday, September 14, 2011 9:24 AM  
**To:** Napoli, Laura (L.); Estes, Eric (E.E.); Flanagan, Thomas (T.P.)  
**Cc:** Surella, Matthew (M.M.); Mrozek, Robert (R.M.)  
**Subject:** RE: U502 gears replaced 20110913 for C200D

Here are the gears that were replaced yesterday. 3 claims for C200D, along with IDS session files on 2 of the 3 vehicles. The third vehicle did not have a valid session.

<< File: U502 gears replaced 20110914.csv >> << File: 1FMHK7F84BG[REDACTED].pdf >> << File: 1FMHK7D85BG[REDACTED].pdf >>

---

**From:** Jackson, Bradley (B.G.)  
**Sent:** Tuesday, September 13, 2011 9:48 AM  
**To:** Napoli, Laura (L.); Estes, Eric (E.E.); Flanagan, Thomas (T.P.)  
**Cc:** Surella, Matthew (M.M.); Mrozek, Robert (R.M.)  
**Subject:** U502 gears replaced 20110913 for C200D

There were four U502 gears replaced yesterday alone for C200D DTC. These gears are being requested back to Eric.

<< File: U502 gears replaced 20110913.csv >>

Brad

---

**From:** Jackson, Bradley (B.G.)  
**Sent:** Tuesday, September 13, 2011 9:45 AM  
**To:** Napoli, Laura (L.); Estes, Eric (E.E.); Flanagan, Thomas (T.P.)  
**Cc:** Surella, Matthew (M.M.); Mrozek, Robert (R.M.)  
**Subject:** U502 gear replaced 20110913



This U502 gear was replaced for the C1B00/U0131 DTC codes, but I have a feeling this may come back as a NPF. PEARS 144028 was submitted this morning for this gear. Also attached is the IDS session file which points to a host of electrical codes being set.

# Claim Detail Report

**Vehicle Information**

**Claim Information**

Model Year: 2011 Document Number: 311425A  
 Market Derived: F - FORD Repair Date: 24-AUG-11  
 Body/Cab Type: T/WD - 4 DOOR WAGON Distance: 85  
 Version/Series: T/EF-FORD SERIES TIS: 1  
 Drive Type: T/F-4 WHL L/H FULL TIME DRIVE  
 Vehicle Line: T/UB-EXPLORER [11-12]  
 Warranty Start Date: 01-AUG-11  
 Production Date: 12-JUL-11  
 VIN: 1FMHK8D83BG [REDACTED]

**Expense Information**

**Dealer Information:**

Customer Paid Amount: .00  
Dealer Name MATHEWS FORD SANDUSKY, INC. Deductible Amount: .00  
 Dealer Code: 02265 - \* Dealer Paid Amount: .00  
 Address: 610 EAST PERKINS AVENUE Labor Cost: 327.13  
 City: SANDUSKY Misc. Expense Amount: .00  
 State: OH Zip Code:44870 Part Markup Amount: 299.10  
 Country: USA Region Code: NA Material Cost: 1046.86  
 Phone: (419)626-4721 Total Cost Gross: 1373.99

Cust. Concern Code: H39 - TRACTION CONTROL/ADVANCE TRAC WARNING LIGHT TRBLS  
 Condition Code: 42 - DOES NOT OPERATE PROPERLY  
 Technician Comment: PERFORM ROAD TEST, PERFORM SELF TEST ON ABS, OR TRAC CONTROL, CODES U0131.00 AND C1B00.29. PERFORM DIAG ON LINE PER MANUAL, SENDS ME TO STEERING GEARING, PERFORM NETWORK TEST, WILL NOT COMMUNICATE, PERFORM DIAG FURTER, ORDER STEERING GEAR, TRY TO DOWN LOAD INFO, WILL NOT, CONTACT HOT LINE, DID NOT HAVE NEW GEAR PLUGED IN ALL THE WAY, MY MISTAKE, DOWN LOAD INFO, NOW FINE, CLEAR  
 Customer Comment: ADVANCE TRAC LIGHT IS ON

<u>Labor Op Code</u>	<u>Labor Op Description</u>	<u>Labor Op Cost</u>
3504E	16.78	
3504E8	8.39	
3504E45	25.16	
MT3504	251.64	
3504E47	25.16	

Causal	Full Part Number	Part	Part	Extended
--------	------------------	------	------	----------

<u>Flag</u>	<u>PREF</u>	<u>BASE</u>	<u>SUFF</u>	<u>Description</u>	<u>CPSC</u>	<u>Quantity</u>	<u>Amount</u>
Y	BB5Z	3504	HE	GEAR ASY-STEERING	110101	1	1046.86

---

**DTC Sections:**

<u>Flag</u>	<u>Test Type</u>	<u>Malfunction Cd</u>	<u>Malfunction Cd Description</u>	<u>Mil. Light On =</u>	<u>Monitor Cd</u>	<u>Monitor Cd</u>
	CHAS	C1B0029				Y
	UNDF	U013100				

Regards,

*Brad Jackson*

Chassis Resident Engineer  
 Chicago Assembly Plant  
 Ford Motor Company  
 Phone: +1.313.805.4798  
[bjackson@ford.com](mailto:bjackson@ford.com)

Model Yea	Part Num	FPart Num	IPart Num	SVIN	Repair Dea	Vehicle Ty	Vehicle Lir	Plant Descr	Repair Dea	Repair Dea	Repair Dea	Country	Re	ECB	Flag	Claim Key	Part Num	FPart Num	EVehicle Lir	Part Quanti	Material C	Customer C	Technician	TIS	Production Date
2011	BB5Z	3504	HE	1FMHK7D84BC	11325	T	T/UB	CHICAGO DORAL LI	786	8450900	USA	N			1054999	BB5Z-350	GEAR AS'EXPLORE	1	1046.86	CUSTOMER	VERIFY	C	5	7-Apr-11	
2011	BB5Z	3504	HE	1FMHK7D88BC	4910	T	T/UB	CHICAGO COOK-WI	850	7840400	USA	N			1052642	BB5Z-350	GEAR AS'EXPLORE	1	997.01	ADVANCE	HAD	COD	4	5-Apr-11	
2011	BB5Z	3504	HE	1FMHK8B88BC	8190	T	T/UB	CHICAGO ALL AME	201	2624900	USA	N			1054060	BB5Z-350	GEAR AS'EXPLORE	1	1325.78	CUSTOMER	VERIFY	C	5	9-Mar-11	
2011	BB5Z	3504	HE	1FMHK8F8XBC	2645	T	T/UB	CHICAGO PRICE-GN	636	3569000	USA	N			1051500	BB5Z-350	GEAR AS'EXPLORE	1	1046.86	CUSTOMER	TA	VERIFIED	5	12-Apr-11	
2011	BB5Z	3504	HE	1FMHK7D86BC	4450	T	T/UB	CHICAGO RODRIGU	956	6892452	USA	N			1052345	BB5Z-350	GEAR AS'EXPLORE	1	1046.86	POWER S'	UNIT	CAN	4	21-May-11	

Load Date	Mileage	Repair Date	Warranty Start / Transaction	VFG	Customer Concern Code
14-Sep-11	7027	25-Aug-11	27-Apr-11	2 V21	H39
14-Sep-11	6008	25-Aug-11	30-Apr-11	2 V21	H39
14-Sep-11	11798	18-Aug-11	31-Mar-11	2 V87	H22
14-Sep-11	4583	2-Sep-11	28-Apr-11	1 V87	H22
14-Sep-11	6288	13-Sep-11	14-Jun-11	1 V87	H22



# One Warranty Reporting Solution

Details for Session File Number 17282262

Report Created: 09/15/2011

## Session Header Information

Session Open Date 2011/09/08  
 Session Upload Date 2011/09/09 09:33:22  
 Dealer GEO Sales Code USA  
 Dealer PA Code 02645  
 Dealer Sub Code  
 Previous Version of Session File .  
 Odometer Reading 4583 miles

## Module List

<u>Module Name</u>	<u>Software Part Number</u>	<u>Responded</u>
ABS - Antilock braking system	BB53-2C219-AF	Yes
ACM - Audio Control Module	BB5T-19C107-CS	Yes
APIM - Accessory Protocol Interface Module	BT4T-14D212-BS	Yes
ATCM - All Terrain Control Module	????	Yes
BdyCM - Body Control Module	BC3T-14B476-DH	Yes
C-CM - Cruise-Control Module	????	No
CLM - Column Lock Module	????	No
DCSM - Driver/Dual Climate-Control Seat Module	BU5T_14B663_AB	Yes
DSM - Driver's Seat Module	BB5T_14C708_AE	Yes
DSP - (Audio) Digital Signal Processing Module	BT4T-18B849-DE	Yes
FCDIM - Front Control/Display Interface Module	????	No
FCIM - Front Controls Interface Module	????	Yes
FLM - Front Lighting Control Module	????	Yes
GPSM - Global Positioning System Module	????	Yes
HSWM - Heated Steering Wheel Module	????	No
HUD - Head Up Display	????	No
HVAC - Heating Ventilation Air Conditioning	BB5T-18C612-CH	Yes
IPC - Instrument Panel Control Module	BB5T-10849-GH	Yes
LTM - Liftgate/Trunk Module	BB5T_14B673_AK	Yes
OCS - Occupant Classification System Module	????	Yes
PAM - Parking Aid Module	BB5T-15K866-AC	Yes
PCM - Powertrain Control Module	BB5AMJ	Yes
PSCM - Power Steering Control Module	BB53-3F964-BJ	Yes
RCM - Restraint Control Module	BB5T-14B321-AH	Yes
RFA - Remote Function Actuator	BB5T-19G481-AL	Yes
RLCMA - Rear Lighting Control Module A	????	No
SCCM - Steering Column Control Module	BB5T-3F944-BJ	Yes
SODL - Side Obstacle Detection Control Module - Left	????	No
SODR - Side Obstacle Detection Control Module - Right	????	No
TPM - Tire Pressure Monitor	????	Yes

## DTC Codes Present

<u>Type</u>	<u>Module</u>	<u>DTC Code</u>	<u>DTC Version</u>	<u>DTC Description</u>	<u>Status Byte</u>	<u>Failure Byte</u>	<u>Failure Byte Desc</u>
CONTINUOUS DTC	ABS	C1B00	GGDS	Steering angle sensor	.	86	Signal Invalid
CONTINUOUS DTC	ABS	U0131	GGDS	Lost Communication With %h(PSCM)	.	00	No Additional Failure Type information for this DTC
CONTINUOUS DTC	IPC	U0253	GGDS	Lost Communication With Accessory Protocol Interface Module	.	00	No Additional Failure Type information for this DTC
CONTINUOUS DTC	PSCM	C200D	GGDS	Motor Rotation Angle Sensor	.	49	Internal Electronic Failure
Self Test - UNKNOWN	ABS	C1B00	GGDS	Steering angle sensor	<a href="#">68</a>	86	Signal Invalid
Self Test - UNKNOWN	ABS	U0131	GGDS	Lost Communication With	<a href="#">60</a>	00	No Additional Failure Type

## DTC Codes Present

Type	Module	DTC Code	DTC Version	DTC Description	Status Byte	Failure Byte	Failure Byte Desc
Self Test - UNKNOWN	IPC	U0253	GGDS	%%h(PSCM) Lost Communication With Accessory Protocol Interface Module	<a href="#">28</a>	00	information for this DTC No Additional Failure Type information for this DTC

## Freeze Frame (IDS Classic only)

Type	DTC	Parameter	Value	Description
------	-----	-----------	-------	-------------

## Mode 6 Test Results (IDS Classic only)

Timestamp	Description	Test	Component	Limits	Value
-----------	-------------	------	-----------	--------	-------

## PID Results in IDS Classic Self Test

Logical Address	Value	PID Description
-----------------	-------	-----------------

## Technician Selected Symptoms (ETIS IDS only)

Symptom

## Diagnosed Modules / Components (ETIS IDS only)

Component	RVC	WCC	Diagnosed Method
-----------	-----	-----	------------------

## Vehicle Information

VIN 1FMHK8F8XBG [REDACTED]  
Model Year 2011  
Vehicle Line EXPLORER  
Engine 3.5L V6 CYCLONE TIVCT  
Engine Trace Number E1600 080411L1304012211S 344 CA  
Transmission 6 SPD AUTO TRANS 6F  
Transmission Trace Number A4931 0604111096186438BA8P 7000 NB 38  
Build Date 2011/04/12  
Warranty Start Date 2011/04/28  
Production Plant CHICAGO PLANT BUILD

## Vehicle WERS Feature Codes

SE EF - FORD SERIES  
AC G - DUAL ZONE AUTO TEMP CONTROL AC  
DR F - 4 WHL L/H FULL TIME DRIVE  
CA WD - 4 DOOR WAGON

[Links to Other Session Files for this VIN](#)

## Vehicle Investigation Links

[Warranty Claim \(AWS\)](#)

[GCQIS Reports](#)

[OWS Find a Vehicle Homepage](#)

[Native Session file Viewer](#)

[Additional Vehicle Information from SAVE](#)



# One Warranty Reporting Solution

Details for Session File Number 16863531

Report Created: 09/15/2011

## Session Header Information

Session Open Date 2011/08/24  
 Session Upload Date 2011/08/26 11:51:37  
 Dealer GEO Sales Code USA  
 Dealer PA Code 09497  
 Dealer Sub Code  
 Previous Version of Session File .  
 Odometer Reading 7018 miles

## Module List

<u>Module Name</u>	<u>Software Part Number</u>	<u>Responded</u>
ABS - Antilock braking system	BB53-2C219-AF	Yes
ACM - Audio Control Module	BB5T-19C107-BS	Yes
APIM - Accessory Protocol Interface Module	BT4T-14D212-BS	Yes
ATCM - All Terrain Control Module	????	No
BdyCM - Body Control Module	BC3T-14B476-DH	Yes
C-CM - Cruise-Control Module	????	No
CLM - Column Lock Module	????	No
DCSM - Driver/Dual Climate-Control Seat Module	????	No
DSM - Driver's Seat Module	????	No
DSP - (Audio) Digital Signal Processing Module	????	No
FCDIM - Front Control/Display Interface Module	????	No
FCIM - Front Controls Interface Module	????	Yes
FLM - Front Lighting Control Module	????	Yes
GPSM - Global Positioning System Module	????	Yes
HSWM - Heated Steering Wheel Module	????	No
HUD - Head Up Display	????	No
HVAC - Heating Ventilation Air Conditioning	BB5T-18C612-BH	Yes
IPC - Instrument Panel Control Module	BB5T-10849-GH	Yes
LTM - Liftgate/Trunk Module	????	No
OCS - Occupant Classification System Module	????	Yes
PAM - Parking Aid Module	BB5T-15K866-AC	Yes
PCM - Powertrain Control Module	BB5AMJ	Yes
PSCM - Power Steering Control Module	BB53-3F964-BJ	Yes
RCM - Restraint Control Module	BB5T-14B321-AH	Yes
RFA - Remote Function Actuator	????	No
RLCMA - Rear Lighting Control Module A	????	No
SCCM - Steering Column Control Module	BB5T-3F944-AJ	Yes
SODL - Side Obstacle Detection Control Module - Left	????	No
SODR - Side Obstacle Detection Control Module - Right	????	No
TPM - Tire Pressure Monitor	????	Yes

## DTC Codes Present

<u>Type</u>	<u>Module</u>	<u>DTC Code</u>	<u>DTC Version</u>	<u>DTC Description</u>	<u>Status Byte</u>	<u>Failure Byte</u>	<u>Failure Byte Desc</u>
CONTINUOUS DTC	ABS	C1B00	GGDS	Steering angle sensor	.	86	Signal Invalid
CONTINUOUS DTC	PSCM	C200D	GGDS	Motor Rotation Angle Sensor	.	49	Internal Electronic Failure
Self Test - UNKNOWN	ABS	C1B00	GGDS	Steering angle sensor	<u>28</u>	86	Signal Invalid
Self Test - UNKNOWN	PSCM	C200D	GGDS	Motor Rotation Angle Sensor	<u>08</u>	49	Internal Electronic Failure

### Freeze Frame (IDS Classic only)

<u>Type</u>	<u>DTC</u>	<u>Parameter</u>	<u>Value</u>	<u>Description</u>
Snapshot	C200D:49-08	RPM	74RPM RPM	Revolutions per minute
Snapshot	C200D:49-08	VS	0MPH MPH	Vehicle Speed

### Mode 6 Test Results (IDS Classic only)

<u>Timestamp</u>	<u>Description</u>	<u>Test</u>	<u>Component</u>	<u>Limits</u>	<u>Value</u>
------------------	--------------------	-------------	------------------	---------------	--------------

### PID Results in IDS Classic Self Test

<u>Logical Address</u>	<u>Value</u>	<u>PID Description</u>
------------------------	--------------	------------------------

### Technician Selected Symptoms (ETIS IDS only)

Symptom

### Diagnosed Modules / Components (ETIS IDS only)

<u>Component</u>	<u>RVC</u>	<u>WCC</u>	<u>Diagnosed Method</u>
------------------	------------	------------	-------------------------

### Vehicle Information

VIN 1FMHK7D84BG [REDACTED]  
Model Year 2011  
Vehicle Line EXPLORER  
Engine 3.5L V6 CYCLONE TIVCT  
Engine Trace Number E1600 040411L1304000231S 344 CA  
Transmission 6 SPD AUTO TRANS 6F  
Transmission Trace Number A4931 0504111095163434BA8P 7000 MB 34  
Build Date 2011/04/07  
Warranty Start Date 2011/04/25  
Production Plant CHICAGO PLANT BUILD

### Vehicle WERS Feature Codes

DR A - 2 WHL L/H FRONT DRIVE  
SE EF - FORD SERIES  
AC G - DUAL ZONE AUTO TEMP CONTROL AC  
CA WD - 4 DOOR WAGON

### [Links to Other Session Files for this VIN](#)

### Vehicle Investigation Links

[Warranty Claim \(AWS\)](#)

[GCQIS Reports](#)

[OWS Find a Vehicle Homepage](#)

[Native Session file Viewer](#)

[Additional Vehicle Information from SAVE](#)





# One Warranty Reporting Solution

Details for Session File Number 17170205

Report Created: 09/15/2011

## Session Header Information

Session Open Date 2011/07/11  
 Session Upload Date 2011/09/08 01:54:46  
 Dealer GEO Sales Code USA  
 Dealer PA Code FACT1  
 Dealer Sub Code  
 Previous Version of Session File .  
 Odometer Reading 2911 miles

## Module List

<u>Module Name</u>	<u>Software Part Number</u>	<u>Responded</u>
ABS - Antilock braking system	BB53-2C219-AF	Yes
ACM - Audio Control Module	BB5T-19C107-BS	Yes
APIM - Accessory Protocol Interface Module	BT4T-14D212-BS	Yes
ATCM - All Terrain Control Module	????	No
BdyCM - Body Control Module	BC3T-14B476-DH	Yes
C-CM - Cruise-Control Module	????	No
CLM - Column Lock Module	????	No
DCSM - Driver/Dual Climate-Control Seat Module	????	No
DSM - Driver's Seat Module	????	No
DSP - (Audio) Digital Signal Processing Module	????	No
FCDIM - Front Control/Display Interface Module	????	No
FCIM - Front Controls Interface Module	????	Yes
FLM - Front Lighting Control Module	????	Yes
GPMS - Global Positioning System Module	????	Yes
HSWM - Heated Steering Wheel Module	????	No
HUD - Head Up Display	????	No
HVAC - Heating Ventilation Air Conditioning	BB5T-18C612-BH	Yes
IPC - Instrument Panel Control Module	BB5T-10849-GH	Yes
LTM - Liftgate/Trunk Module	????	No
OCS - Occupant Classification System Module	????	Yes
PAM - Parking Aid Module	BB5T-15K866-AC	Yes
PCM - Powertrain Control Module	BB5AMJ	Yes
PSCM - Power Steering Control Module	BB53-3F964-BJ	Yes
RCM - Restraint Control Module	BB5T-14B321-AH	Yes
RFA - Remote Function Actuator	????	No
RLCMA - Rear Lighting Control Module A	????	No
SCCM - Steering Column Control Module	BB5T-3F944-FC	Yes
SODL - Side Obstacle Detection Control Module - Left	CT43-14C689-CA	Yes
SODR - Side Obstacle Detection Control Module - Right	CT43-14C689-CA	Yes
TPM - Tire Pressure Monitor	????	Yes

## DTC Codes Present

<u>Type</u>	<u>Module</u>	<u>DTC Code</u>	<u>DTC Version</u>	<u>DTC Description</u>	<u>Status Byte</u>	<u>Failure Byte</u>	<u>Failure Byte Desc</u>
CONTINUOUS DTC	ABS	U0131	GGDS	Lost Communication With %h(PSCM)	.	00	No Additional Failure Type information for this DTC
CONTINUOUS DTC	ACM	U0253	GGDS	Lost Communication With Accessory Protocol Interface Module	.	00	No Additional Failure Type information for this DTC
CONTINUOUS DTC	ACM	U0257	GGDS	Lost Communication With Front Controls / Display Interface Module	.	00	No Additional Failure Type information for this DTC
CONTINUOUS DTC	FCIM	U0257	GGDS	Lost Communication With	.	00	No Additional Failure Type

**DTC Codes Present**

Type	Module	DTC Code	DTC Version	DTC Description	Status Byte	Failure Byte	Failure Byte Desc
				Front Controls / Display Interface Module			information for this DTC
CONTINUOUS DTC	IPC	U0253	GGDS	Lost Communication With Accessory Protocol Interface Module	.	00	No Additional Failure Type information for this DTC
Self Test - UNKNOWN	ABS	U0131	GGDS	Lost Communication With %%(PSCM)	<u>AB</u>	00	No Additional Failure Type information for this DTC
Self Test - UNKNOWN	ACM	U0253	GGDS	Lost Communication With Accessory Protocol Interface Module	<u>0A</u>	00	No Additional Failure Type information for this DTC
Self Test - UNKNOWN	ACM	U0257	GGDS	Lost Communication With Front Controls / Display Interface Module	<u>0A</u>	00	No Additional Failure Type information for this DTC
Self Test - UNKNOWN	FCIM	U0257	GGDS	Lost Communication With Front Controls / Display Interface Module	<u>08</u>	00	No Additional Failure Type information for this DTC
Self Test - UNKNOWN	IPC	U0253	GGDS	Lost Communication With Accessory Protocol Interface Module	<u>2E</u>	00	No Additional Failure Type information for this DTC

**Freeze Frame (IDS Classic only)**

Type	DTC	Parameter	Value	Description
------	-----	-----------	-------	-------------

**Mode 6 Test Results (IDS Classic only)**

Timestamp	Description	Test	Component	Limits	Value
-----------	-------------	------	-----------	--------	-------

**PID Results in IDS Classic Self Test**

Logical Address	Value	PID Description
16D3	0RPM	Engine (RPM) At Time Of Misfire
16D4	0%	Engine Load At Time Of Misfire
16D7	00:00	Engine Off Soak Time Prior to Misfire
16D8	00:00	Engine Running Time At Time Of Misfire
16DC	1	Number Of Trips Since The Time Of Misfire

**Technician Selected Symptoms (ETIS IDS only)**

Symptom

**Diagnosed Modules / Components (ETIS IDS only)**

Component	RVC	WCC	Diagnosed Method
-----------	-----	-----	------------------

**Vehicle Information**

VIN	1FMHK7D86BG [REDACTED]
Model Year	2011
Vehicle Line	EXPLORER
Engine	3.5L V6 CYCLONE TIVCT
Engine Trace Number	E1600 160511L1304015621S 344 CA
Transmission	6 SPD AUTO TRANS 6F
Transmission Trace Number	A4931 1805111138161934BA8P 7000 MB 34
Build Date	2011/05/21
Warranty Start Date	2011/06/14
Production Plant	CHICAGO PLANT BUILD

#### Vehicle WERS Feature Codes

DR A - 2 WHL L/H FRONT DRIVE  
SE EF - FORD SERIES  
AC G - DUAL ZONE AUTO TEMP CONTROL AC  
CA WD - 4 DOOR WAGON

[Links to Other Session Files for this VIN](#)

#### Vehicle Investigation Links

[Warranty Claim \(AWS\)](#)

[GCQIS Reports](#)

[OWS Find a Vehicle Homepage](#)

[Native Session file Viewer](#)

[Additional Vehicle Information from SAVE](#)



# One Warranty Reporting Solution

Details for Session File Number 16346534

Report Created: 09/15/2011

## Session Header Information

Session Open Date .  
 Session Upload Date 2011/08/05 01:48:01  
 Dealer GEO Sales Code .  
 Dealer PA Code .  
 Dealer Sub Code .  
 Previous Version of Session File .  
 Odometer Reading 4692 miles

## Module List

<u>Module Name</u>	<u>Software Part Number</u>	<u>Responded</u>
ABS - ANTILOCK BRAKE SYSTEM (PRIORITY 7)	.	.
APIM - TEST - APIM (NO PRIORITY)	.	.
IC - INSTRUMENT CLUSTER (PRIORITY 10)	.	.
OCS - Occupant Classification System Module	.	.
PAM - Parking Aid Module	.	.
PCM,ECM - POWERTRAIN CONTROL MODULE, ENGINE CONTROL MODULE (PRIORITY 3)	.	.
RCM - RESTRAINT CONTROL MODULE (PRIORITY 1)	.	.
SPDJB - SMART POWER DISTRIBUTION JUNCTION BOX (PRIORITY 6)	.	.
TPMS - TIRE PRESSURE MONITOR SYSTEM (PRIORITY 5)	.	.
UNKNOWN SYNC MODULE ADDRESS	.	.

## DTC Codes Present

<u>Type</u>	<u>Module</u>	<u>DTC Code</u>	<u>DTC Version</u>	<u>DTC Description</u>	<u>Status Byte</u>	<u>Failure Byte</u>	<u>Failure Byte Desc</u>
Self Test - CONTINUOUS DTC	ABS	C1B00	GGDS	Steering angle sensor	20	86	Signal Invalid

## Freeze Frame (IDS Classic only)

<u>Type</u>	<u>DTC</u>	<u>Parameter</u>	<u>Value</u>	<u>Description</u>
-------------	------------	------------------	--------------	--------------------

## Mode 6 Test Results (IDS Classic only)

<u>Timestamp</u>	<u>Description</u>	<u>Test</u>	<u>Component</u>	<u>Limits</u>	<u>Value</u>
------------------	--------------------	-------------	------------------	---------------	--------------

## PID Results in IDS Classic Self Test

<u>Logical Address</u>	<u>Value</u>	<u>PID Description</u>
------------------------	--------------	------------------------

## Technician Selected Symptoms (ETIS IDS only)

<u>Symptom</u>
----------------

## Diagnosed Modules / Components (ETIS IDS only)

<u>Component</u>	<u>RVC</u>	<u>WCC</u>	<u>Diagnosed Method</u>
------------------	------------	------------	-------------------------

**Vehicle Information**

VIN	1FMHK7D88BG [REDACTED]
Model Year	2011
Vehicle Line	EXPLORER
Engine	3.5L V6 CYCLONE TIVCT
Engine Trace Number	E1600 300311L1302016231S 344 BA
Transmission	6 SPD AUTO TRANS 6F
Transmission Trace Number	A4931 0104111091181734BA8P 7000 MB 34
Build Date	2011/04/05
Warranty Start Date	2011/04/30
Production Plant	CHICAGO PLANT BUILD

**Vehicle WERS Feature Codes**

DR A - 2 WHL L/H FRONT DRIVE  
SE EF - FORD SERIES  
AC G - DUAL ZONE AUTO TEMP CONTROL AC  
CA WD - 4 DOOR WAGON

**[Links to Other Session Files for this VIN](#)****Vehicle Investigation Links**

[Warranty Claim \(AWS\)](#)

[GCQIS Reports](#)

[OWS Find a Vehicle Homepage](#)

[Additional Vehicle Information from SAVE](#)



# One Warranty Reporting Solution

Details for Session File Number 16692403

Report Created: 09/15/2011

## Session Header Information

Session Open Date 2011/08/18  
 Session Upload Date 2011/08/29 13:57:09  
 Dealer GEO Sales Code USA  
 Dealer PA Code 08190  
 Dealer Sub Code  
 Previous Version of Session File .  
 Odometer Reading 11799 miles

## Module List

Module Name	Software Part Number	Responded
ABS - Antilock braking system	BB53-2C219-AF	Yes
ACM - Audio Control Module	BB5T-19C107-BS	Yes
APIM - Accessory Protocol Interface Module	????	No
ATCM - All Terrain Control Module	????	Yes
BdyCM - Body Control Module	BC3T-14B476-DH	Yes
C-CM - Cruise-Control Module	????	No
CLM - Column Lock Module	????	No
DCSM - Driver/Dual Climate-Control Seat Module	????	No
DSM - Driver's Seat Module	????	No
DSP - (Audio) Digital Signal Processing Module	????	No
FCDIM - Front Control/Display Interface Module	BB5T-19C116-CJ	Yes
FCIM - Front Controls Interface Module	????	Yes
FLM - Front Lighting Control Module	????	Yes
GPSM - Global Positioning System Module	????	No
HSWM - Heated Steering Wheel Module	????	No
HUD - Head Up Display	????	No
HVAC - Heating Ventilation Air Conditioning	BB5T-19980-AG	Yes
IPC - Instrument Panel Control Module	BB5T-10849-EF	Yes
LTM - Liftgate/Trunk Module	????	No
OCS - Occupant Classification System Module	????	Yes
PAM - Parking Aid Module	????	No
PCM - Powertrain Control Module	BB5ANJ	Yes
PSCM - Power Steering Control Module	BB53-3F964-BG	Yes
RCM - Restraint Control Module	BB5T-14B321-AF	Yes
RFA - Remote Function Actuator	????	No
RLCMA - Rear Lighting Control Module A	????	No
SCCM - Steering Column Control Module	BB5T-3F944-AJ	Yes
SODL - Side Obstacle Detection Control Module - Left	????	No
SODR - Side Obstacle Detection Control Module - Right	????	No
TPM - Tire Pressure Monitor	????	Yes

## DTC Codes Present

Type	Module	DTC Code	DTC Version	DTC Description	Status Byte	Failure Byte	Failure Byte Desc
CONTINUOUS DTC	ABS	C1B00	GGDS	Steering angle sensor	.	86	Signal Invalid
CONTINUOUS DTC	PSCM	C200D	GGDS	Motor Rotation Angle Sensor	.	49	Internal Electronic Failure
Self Test - UNKNOWN	ABS	C1B00	GGDS	Steering angle sensor	<u>20</u>	86	Signal Invalid
Self Test - UNKNOWN	PSCM	C200D	GGDS	Motor Rotation Angle Sensor	<u>08</u>	49	Internal Electronic Failure
Self Test - KOEO TEST	PSCM	U0415	GGDS	Invalid Data Received From %h(ABS) Control Module	.	00	No Additional Failure Type information for this DTC
Self Test - UNKNOWN	PSCM	U0415	GGDS	Invalid Data Received From %h(ABS) Control Module	<u>08</u>	00	No Additional Failure Type information for this DTC
Self Test - UNKNOWN	PSCM	U0415	GGDS	Invalid Data Received From	<u>0A</u>	00	No Additional Failure Type

## DTC Codes Present

<u>Type</u>	<u>Module</u>	<u>DTC Code</u>	<u>DTC Version</u>	<u>DTC Description</u>	<u>Status Byte</u>	<u>Failure Byte</u>	<u>Failure Byte Desc</u>
				%%h(ABS) Control Module			information for this DTC

## Freeze Frame (IDS Classic only)

<u>Type</u>	<u>DTC</u>	<u>Parameter</u>	<u>Value</u>	<u>Description</u>
Snapshot	C200D:49-08	RPM	127RPM RPM	Revolutions per minute
Snapshot	C200D:49-08	VS	0MPH MPH	Vehicle Speed
Snapshot	U0415:00-08	RPM	83.25RPM RPM	Revolutions per minute
Snapshot	U0415:00-08	VS	0MPH MPH	Vehicle Speed

## Mode 6 Test Results (IDS Classic only)

<u>Timestamp</u>	<u>Description</u>	<u>Test</u>	<u>Component</u>	<u>Limits</u>	<u>Value</u>
------------------	--------------------	-------------	------------------	---------------	--------------

## PID Results in IDS Classic Self Test

<u>Logical Address</u>	<u>Value</u>	<u>PID Description</u>
------------------------	--------------	------------------------

## Technician Selected Symptoms (ETIS IDS only)

Symptom

## Diagnosed Modules / Components (ETIS IDS only)

<u>Component</u>	<u>RVC</u>	<u>WCC</u>	<u>Diagnosed Method</u>
------------------	------------	------------	-------------------------

## Vehicle Information

VIN 1FMHK8B88BG [REDACTED]  
Model Year 2011  
Vehicle Line EXPLORER  
Engine 3.5L V6 CYCLONE TIVCT  
Engine Trace Number E1600 050311L1301004431S 342 BA  
Transmission 6 SPD AUTO TRANS 6F55  
Transmission Trace Number A4921 0103111060010211BA5P 7000 RC 11  
Build Date 2011/03/09  
Warranty Start Date 2011/03/31  
Production Plant CHICAGO PLANT BUILD

## Vehicle WERS Feature Codes

SE EF - FORD SERIES  
AC B - MANUAL AIR CONDITIONER  
DR F - 4 WHL L/H FULL TIME DRIVE  
CA WD - 4 DOOR WAGON

## [Links to Other Session Files for this VIN](#)

## Vehicle Investigation Links

[Warranty Claim \(AWS\)](#)

[GCQIS Reports](#)

[OWS Find a Vehicle Homepage](#)

[Native Session file Viewer](#)  
[Additional Vehicle Information from SAVE](#)



---

**From:** Perri, Ron (R.J.)  
**Sent:** Tuesday, November 15, 2011 11:29 AM  
**To:** Collins, Ron (R.J.)  
**Subject:** RE: U502 steering update  
**Importance:** High

Yes, as far as we know, TYCO, ribbon cable supplier, is same Globally for

REDACTED  
FOR  
RELEVANCE

Ron Perri  
Manager, Chassis - EPAS and Upper Steering, Systems & Core  
2B-F77, Product Development Center  
cell 313-805-0680  
rperri@ford.com

---

**From:** Collins, Ron (R.J.)  
**Sent:** Tuesday, November 15, 2011 7:17 AM  
**To:** Perri, Ron (R.J.)  
**Subject:** FW: U502 steering update

FYI. Have we done the same for Europe (ribbon cable actions)?

Ron Collins  
Chief Engineer, North American Chassis Engineering  
Ford Motor Company  
email: rcollin4@ford.com

---

**From:** Jammoul, Ali (A.)  
**Sent:** Saturday, November 12, 2011 5:38 PM  
**To:** Collins, Ron (R.J.)  
**Cc:** Tetley, John (J.K.)  
**Subject:** Re: U502 steering update

Ron,

Very good progress. Please make sure this is reflected in the six panel for the Bennie review and ask TRW to contain for the European C1 production immediately. Thanks.

Ali Jammoul  
Director  
Global Chassis Engineering

---

**From:** Collins, Ron (R.J.)  
**Sent:** Saturday, November 12, 2011 11:03 AM  
**To:** Fisher, Marcy (M.J.)  
**Cc:** Jammoul, Ali (A.); Pittel, Kimberly (K.L.)  
**Subject:** RE: U502 steering update

Update:

We've found root cause on the encoder failures, both associated with the ribbon cable.

1. Conformal coating insulating strand from pins, through capillary action. Containment 11/11/11: Parts are 100% checked for this issue by UV light (coating glows, and if present on strand ends, cable is scrapped).
2. Misalignment of connector on ribbon cable, allowing intermittent connection. Containment 11/11/11: 100% sort for misalignment. Bad parts scrapped.

These issues account for 8 failures of 8 analyzed returned parts. 3 more to tear down.

Thanks

Ron Collins  
Chief Engineer, North American Chassis Engineering  
Ford Motor Company  
email: rcollin4@ford.com

---

**From:** Collins, Ron (R.J.)  
**Sent:** Wednesday, November 09, 2011 7:30 PM  
**To:** Fisher, Marcy (M.J.)  
**Cc:** Jammoul, Ali (A.); Pittel, Kimberly (K.L.)  
**Subject:** RE: U502 steering update

Marcy:

To answer your question, Micronas (Hall supplier) was found to be in good condition. The summary of investigation is as follows:

- Failed part build date: 9/17/2010
- Exhaust system is controlled during weekly preventive maintenance
- Exhaust system is cleaned during monthly preventive maintenance
- **New manometers introduced in WW03/2011 for improved particle detection.**
  - As part of the Micronas Continuous Improvement Plan at Wafer Fab, our Defect Engineering Team is performing further measures like particle monitoring, material analysis, source estimation and action definition on an ongoing basis.
  - Micronas reports 0.12ppm on hall sensors to all customers

The bottom line here: Micronas has installed new particle detection equipment since the failed part was built. Further, the Hall failure appears to be a flier...the other failed units' fault have been isolated to the encoder rather

than the Hall.

Thanks

Ron Collins  
Chief Engineer, North American Chassis Engineering  
Ford Motor Company  
email: rcollin4@ford.com

---

**From:** Fisher, Marcy (M.J.)  
**Sent:** Wednesday, November 09, 2011 11:53 AM  
**To:** Collins, Ron (R.J.)  
**Cc:** Jammoul, Ali (A.); Pittel, Kimberly (K.L.)  
**Subject:** RE: U502 steering update

Ron, Thanks for the update. Please keep me in the loop on progress on the encoder signal root cause. Also, regarding the contamination, did they find something that they weren't doing regarding PM and/or find the potential cause of the contamination? I'm just trying to gain confidence that something has been improved to ensure the contamination is really cut-off. Thanks

---

**From:** Collins, Ron (R.J.)  
**Sent:** Wednesday, November 09, 2011 9:15 AM  
**To:** Fisher, Marcy (M.J.)  
**Cc:** Jammoul, Ali (A.); Pittel, Kimberly (K.L.)  
**Subject:** U502 steering update

Marcy:

Per your request, here is our latest status with the B9A fault code issue:

1) encoder - 2 vehicles now intermittently exhibit B9A related to encoder signal (Laura's focus and a Fusion at TRW-26 mile).

Allegro (encoder supplier) has received 4 suspect encoders from TRW-Marion (not necessarily in failed state).

Working to get an encoder to fail, keep it at that state, and have Allegro analyze it.

2) ribbon cable - TRW developing method to check ribbon cable resistance in-vehicle. 1st check the Fusion, then Laura's car. This looks less likely root cause now that both vehicles have shown failure in encoder.

3) hall effects => one sensor found with hard fault due to contamination. Supplier in Europe has been visited and PM has been verified to ensure no further contamination.

We know why we are getting B9A (encoder signal failure). We are working now to understand why that signal is failing intermittently. That is step one above: get the suspect sensors instrumented in lab and get them to fail so we can determine root cause.

Thanks

Ron Collins  
Chief Engineer, North American Chassis Engineering  
Ford Motor Company  
email: rcollin4@ford.com

---

**From:** Pienta, Alan (A.)  
**Sent:** Friday, September 02, 2011 5:35 PM  
**To:** Napoli, Laura (L.); 'Jim Loria'; 'Michael Fontana'; 'Simon Malsbury'; Engelbert Lu; 'joel.rabideau@trw.com'  
**Cc:** Mrozek, Robert (R.M.); Estes, Eric (E.E.); Diez, Timothy (T.P.); Rossi, Roberto (R.A.)  
**Subject:** RE: U502 with C200B/C200C

Team,  
Upon investigation, the dealership informed me that the di-electric grease solution lasted 24 hours and the unit was returned to the dealership with the same customer complaint. Furthermore, the dealership technician stated that upon visual inspection, he could find nothing wrong with the wire harness connectors or terminals. When questioned about the utilization of di-electric grease, the technician stated that he has experienced positive results in intermittent electrical connections by the insertion of di-electric grease.

The unit has just had a new rack installed as of 5:00 pm, September 2, 2011.

Alan Pienta  
EPAS Electronics Engineer

---

**From:** Napoli, Laura (L.)  
**Sent:** Thursday, September 01, 2011 9:23 AM  
**To:** 'Jim Loria'; Pienta, Alan (A.); Michael Fontana; Simon Malsbury; Engelbert Lu; joel.rabideau@trw.com; Diez, Timothy (T.P.)  
**Cc:** Mrozek, Robert (R.M.); Estes, Eric (E.E.)  
**Subject:** FW: U502 with C200B/C200C

TRW TS Team,

We have a car in warranty that had C200B and C200C TS Faults. The dealer unplugged ALL 3 connectors and put di-electric grease on the pins and said it fixed the issue. This is not in the service procedure. Do you have any concerns that they did this, or do you think the car will just come back with another TS fault and we can replace the gear then?

Regards,

*Laura Napoli*

D3 and U502 EPAS  
Ford Motor Company  
Cube: 2B-G66 PDC  
Phone: 313.323.0634  
Mobile: 313.805.0482

---

**From:** Jackson, Bradley (B.G.)  
**Sent:** Thursday, September 01, 2011 8:43 AM  
**To:** Napoli, Laura (L.); Estes, Eric (E.E.)  
**Cc:** Mrozek, Robert (R.M.); Logli, Michael (M.A.); Brucker, Eric (.)  
**Subject:** U502 with C200B/C200C

Laura / Eric E., what is the C200B/C DTC? This dealer is claiming they put di-electric grease in the connector to the gear and fixed this problem. This does not sound correct.

## Claim Detail Report

Model Year = 2011; Claim Key = 918856

**Vehicle Information**

**Claim Information**

Model Year: 2011 Document Number: 00410801  
Market Derived: F - FORD Repair Date: 24-AUG-11  
Body/Cab Type: T/WD - 4 DOOR WAGON Distance: 1619  
Version/Series: T/EF-FORD SERIES TIS: 2  
Drive Type: T/A-2 WHL L/H FRONT DRIVE  
Vehicle Line: T/UB-EXPLORER [11-12]  
Warranty Start Date: 16-JUL-11  
Production Date: 17-JUN-11  
VIN: 1FMHK7B88BG [REDACTED]

**Expense Information**

**Dealer Information:**

Customer Paid Amount: .00  
Dealer Name DUVAL FORD Deductible Amount: .00  
Dealer Code: 04863 - \* Dealer Paid Amount: .00  
Address: 1616 CASSAT AVE Labor Cost: 87.66  
City: JACKSONVILLE Misc. Expense Amount: .00  
State: FL Zip Code: 32210 Part Markup Amount: .00  
Country: USA Region Code: NA Material Cost: .00  
Phone: (904)387-6541 Total Cost Gross: 87.66

Cust. Concern Code: H39 - TRACTION CONTROL/ADVANCE TRAC WARNING LIGHT TRBLS  
Condition Code: 28 - OPEN CIRCUIT  
Technician Comment: VERIFY CONCERN,PERFORM SELF TEST TO ABS & PSCM, RECEIVE U0001:88,C1BOO:86,C200B:62,C200C:2F,PERFORM PINPOINT B PER INTERACTIVE DYNAMICS,FOUND HIGH RESISTANCE IN ELECTRONIC STEERING GEAR CONNECTORS,INSTALL DIELECTRIC GREASE IN ALL 3 CONNECTORS,PER FORM TEST DRIVE TO VERIFY DTC'S DID NOT RETURN, OPERATING AS DESIGNED. CC 42 1621  
Customer Comment: SVC ADVANCE TRAC & PWR STEERING ASSIST FAULT COMES ON INTERMITTANTLY WHILE DRIVING. WHEN THIS OCCURS, POWER STEERING IS INOP...ADVISE

**Labor Op Code**      **Labor Op Description**      **Labor Op Cost**  
MTWIRING    87.66

<u>Causal Flag</u>	<u>PREF</u>	<u>BASE</u>	<u>SUFF</u>	<u>Part Description</u>	<u>Part CPSC</u>	<u>Extended Quantity</u>	<u>Amount</u>
Y	*	14401	*	WIRE ASY MAIN LOOM	180102	0	.00

Regards,  
*Brad Jackson*  
Chassis Resident Engineer  
Chicago Assembly Plant  
Ford Motor Company  
Phone: +1.313.805.4798  
bjackson@ford.com