

PE13-018

FORD

8-23-2013

APPENDIX G

Engineering Review

1

AND

2 PAGE 166

PE13-018

FORD

8-23-2013

APPENDIX G

Engineering Review

1

From: Ronzi, Bill (W.C.)
Sent: Monday, June 17, 2013 2:33 PM
To: Andersen, Erik (E.); Kramer, Michael (M.T.); Madej, Jeanette (J.); Sparks, Douglas (D.S.); Russo, Scott (S.)
Subject: 13/14MY Direction -- RE: 2013 CAC Misfire Meeting

I suspect that the 13/14MY QSF will be opening very soon so I was going to schedule a short meeting to discuss.

Rather than a separate meeting, can we use the first 15 minutes of your Tuesday 2pm meeting to focus on 13/14MY potential solutions? In order to fully address customer drivability concerns, the avoidance of FMEM may need to be goal vs only misfire count reductions.

PS – Would be helpful to have the existing results summarized (could show data for both cells). Can we review that summary on Tuesday? Something like this:

	Misfire	FMEM	# Cylinders	TASE	Towing	Top
Hardware Configuration	Counts	(Y/N)	FMEM	IAT	Derate?	Water T
11/12MY (no blocker)						
11/12MY (top blocker)						
13MY PCA CAC						
13MY PCA CAC (bottom blocker)						

Note: Due to test/test & vehicle/vehicle variability, misfire counts accurate to +/- TBD.

Thanks,
 Bill

-----Original Appointment-----

From: Andersen, Erik (E.)
Sent: Friday, February 08, 2013 2:14 PM
To: Andersen, Erik (E.); Ronzi, Bill (W.C.); Giunta, Michael (M.J.); Huang, Larry (L.); Allan, Valerie (V.J.); Madej, Jeanette (J.); Raver, Jon (J.A.); Ladd, John (J.R.); Dumler, Jeff (J.D.); Rollins, Scott (S.); Rollinger, John (J.E.); Devries, Jason (J.E.); Yamada, Shuya Shark (S.Y.); Norman, Kristofor (K.R.); Styles, Daniel (D.J.); Shaikh, F Zafar (.); Abarham, Mehdi (M.); Glugla, Chris (C.P.); Usman, Mohammad (M.); Shaw, Nathanael (N.); Wade, Robert (R.A.); Baldwin, Damien (D.K.); Bishop, Chris (C.B.); Garrett, David (D.P.); Rackmil, Chuck (C.I.); Hall, Brent (A.); Sowards, John (J.); Toutanji, Mohamad (M.); Wenzel, Todd (T.L.); Widmann, Carl (C.A.); Sparks, Douglas (D.S.); Gardner, Greg (G.D.); Gallo, Joseph (J.J.); Robbins, John (J.R.); Keough, Shane (S.T.); Michela, Mike (M.); Schoeneman, Christian (C.B.); Zhang, Yi (Y.); Dame, Andrew (A.C.); Perini, Rob (R.M.); Stewart, LaMar (M.L.); Zhao, Yonglu (Y.); Vostal, Pat (P.T.); Valluri, Siddharth (S.); Beck, Jim (J.G.); Smith, Craig (C.A.)
Cc: Russo, Scott (S.); Cragel, Daniel (D.M.)
Subject: FW: 2013 CAC Misfire Meeting
When: Tuesday, June 18, 2013 2:00 PM-3:00 PM (UTC-05:00) Eastern Time (US & Canada).
Where: 23G26

-----Original Appointment-----

From: Andersen, Erik (E.)
Sent: Thursday, December 13, 2012 11:14 AM

From: Ronzi, Bill (W.C.)
Sent: Tuesday, March 12, 2013 6:30 PM
To: Dobbs, Dan (K.D.); Nowaczyk, Rick (R.J.)
Cc: Ricks, Kevin (K.J.); Sparks, Douglas (D.S.); Andersen, Erik (E.)
Subject: 13MY CAC Replacement

Rick/Dan,

We need the SSM out... Good example below.

Can you call the dealer on this one to discuss the repair? It appears the vehicle had a P0430 catalyst code but instead of replacing the LH catalyst they replaced the CAC, per the TSB, even though it was built outside the TSB dates (already had new CAC). That means the customer will likely be back very soon with another P0430 and got \$300 worth of new CAC parts that won't help.

YR	VIN	PLANT	MODEL	TRIM	ENGINE	TRANS	DRIVE	ASSY PLAN	PROD DATE	WARRANTY START DATE	
2013	1FTFW1ETXDK		#	T/F6	F/B/A/E	T/KW	T/C3	AJ	26-Oct-12	17-Dec-12	

Bill
William C. Ronzi
PTI Quality Supervisor
(313) 805-6140 cell & pgr

From: Osepchook, William (W.R.)
Sent: Wednesday, January 04, 2012 9:04 AM
To: Stawiecki, Bob (R.)
Cc: Cockerill, Al (C.A.); Donahue, Francis (Fran.); Bonell, Paul (P.S.); Mazuchowski, James (J.A.); Harmon, Derek (D.M.); Graham, David (D.L.)
Subject: 2011 F-150 EcoBoost 1FTFX1ET5B [REDACTED] Misfire

Hi Bob,

I will be shipping six spark plugs and a 7T4Z-19A095-A ground strap.

Reference GCQIS report BF3GB001

Per conversation; below are the instructions for recommended repairs on this vehicle:

1. Scan for DTC's and list current drivability issues.
2. Check G105 Ground (Rear of driver side cylinder head) torque per attached instructions. (M-time)
 - A) Can you loosen G105 bolt using only finger pressure?
 - B) Attempt to torque bolt to 10 Nm (7lb/ft). Was the torque set correctly?
3. Install spark plugs. Set gap to 0.8mm +/- 0.05mm (Labor Op 12405AT)
4. Install ground strap per attached instructions. (M-time)



Ground Strap.pdf

Thanks for the help.
Let me know if there are any questions.

William Osepchook

LGDEE

Large Gas & Diesel Engine Engineering

V-Engine Service Engineer

313-805-9191

wosepcho@ford.com

F-150 Service Ground Strap Instructions (Left/Driver side Rear of Engine)

Attach 7T4Z-19A095-A wire to G105 ground and crank position sensor heat shield lower bolt. Use a tie strap to secure wire to transmission shift cable. (Keep existing G105 ground eyelet in same position)



1. G105 Ground

Install eyelet behind the stud. Torque to 10Nm (7 lb/ft) then rotate an additional 45 degrees

2. Crank position sensor heat shield lower bolt

Torque to 11Nm (8 lb/ft)

3. Attach tie strap

Secure wire to transmission shift cable (Cable not shown)

From: Oyafuso, Kevin (K.G.)
Sent: Monday, August 15, 2011 5:46 PM
To: Sims, Ivan (I.D.); McCoy, Jim (D.); Rutkowski, Brian (B.); Dusa, Daniel (D.V.); Donahue, Francis (Fran.); Morrow, Bill (N.W.); Baskins, Robert (R.S.); Whitehead, Joseph (J.P.); Smith, Craig (C.A.); Wagers, Sue (S.K.); Fischer, Troy (T.A.)
Cc: Dixon, Mark (M.R.); Avery, Kevin (K.); Hamilton, Steven (S.C.); Nowaczyk, Rick (R.J.); Reno, George (G.L.); Elkins, Donly (D.); Cockerill, Al (C.A.)
Subject: 2011 P415 GTDI P0306 at York Ford, Maine (Houlton); 1FTFX1ET1BF [REDACTED]
Attachments: 2011 P415 gtdi misfire York Ford.zip

here is the data from the P415 GTDI in Maine - Customer was able to repeat misfire condition with the ADR2 installed.

Regards,
Kevin Oyafuso
Ford Motor Company
PD / Powertrain Integration Management - C&C Quality
Vehicle Operations General Office (VOGO)
17000 Oakwood Blvd, Allen Park, MI 48101
6-Sigma Garage, Office 4B
(313) 805-4908 (koyafuso@ford.com)

From: Avery, Kevin (K.)
Sent: Thursday, July 28, 2011 12:29 PM
To: Oyafuso, Kevin (K.G.)
Subject: 2011 F-150 Ecoboost misfire

Kevin,

Heads up that the coils and plugs have not repaired this vehicle. Ritchie did say that he sent the parts back last week as requested. Did you have further insight beyond the secondary ignition?

Kevin Avery

Field Service Engineer, Boston Region
(774) 285-9143
Fax: 866-736-6011

Rotunda: Your Single Source for Service Department & Equipment Needs

Just because you don't see it in the Rotunda catalog doesn't mean we don't sell it!

This e-mail and any attachments is intended only for the use of the person or persons addressed hereto and may contain legally privileged and/or confidential information. If you are not the intended recipient of this e-mail, you are hereby notified that any dissemination, distribution or copying of this e-mail, and any attachments, is strictly prohibited. If you have received this e-mail in error, please notify me via return e-mail and permanently delete the original and any copy of any e-mail and any printout.

From: KAVERY3@ford.com [mailto:KAVERY3@ford.com]
Sent: Thursday, July 28, 2011 12:22 PM
To: Avery, Kevin (K.)
Subject: Report Summary for the CQIS Report#BCWAN004

Attachments : 0

Report# : BCWAN004 NHL **Received:** 03/23/2011
CCRG/EPRC: **Reviewed Status:** **Date:**
Vehicle: 2011,F150 4X4,SUP CAB,STYSD **Build Date:** 02/15/2011
,1FTFX1ET1BF [REDACTED]
Odometer : 1,847 M **Engine:** 3.5L-GTDI **Calibration:**
Transmission: 6R80E **Axle:** 3800F3.31C **A/C:** YES
Dealer: USA 08849 York Ford Sales **Phone#:** (207) 532-2928
City: Houlton **State:** Maine **Country :** USA
Originator: RITCHIE LYNDS
Symptom: 5 51 9 02 DRV PERF,IDLE QUALITY,ROUGH,ALWAYS
Status:
VFG: V40 GOOD IDLE QUALITY
Additional Symptom: PREMATURE CATALYST FAILURE
Fix: **Causal Component :**
Condition Code:

Hotliner: ABOUGHAN **Phone:** 000 317-6308 **Regn Cd:** N2 Boston

Engineering: **Phone:** **TAR:** 0-30

Dlr Contact: RITCHIE LYNDS **Phone:** 207 532-2928 **Title Cde:** T

DTCs:

KOEO:

KOEC:P0430

KOER:

Comments

:

REPAIR 03/23/2011 08:03AM ALEX BOUGHAN MSS - FCSD - TECH SVC HOTLINE
WEB FORM DATA - CONCERN: OWNER SAYS MISSES AT TIMES, LACK OF
POWER DIAGNOSTICS: ROAD TESTED AND CHECKED FOR CODES PARTS
REPLACED:: NONE TECH QUESTION: NO CODES NOTHING IN MODE 6 A KNOWNS
ON THESE FOR LACK OF POWER PLEASE LIST ANY PERTINENT PID DATA
PLEASE LIST ANY VEHICLE MODIFICATIONS, OR TYPE NONE. NONE

RECOMM 03/23/2011 08:03AM ALEX BOUGHAN MSS - FCSD - TECH SVC HOTLINE
RITCHIE, BASED ON THE INFORMATION PROVIDED, THE CUSTOMER STATES THAT
A
MISFIRE AND LACK OF POWER IS PRESENT, THE CONCERN CAN NOT BE
DUPLICATED AT THE DEALER LEVEL. GATHER MORE DETAILED INFORMATION

FROM

THE CUSTOMER. DUPLICATE CONCERN AND PROCEED WITH NORMAL DIAGNOSTICS AS

NECESSARY. REFER TO SECTION 3 OF THE PC/ED FOR A LIST OF POSSIBLE CAUSES BY SYMPTOM. REFER TO SECTION 6 OF THE PC/ED FOR A LIST OF PIDS TO MONITOR BY SYMPTOM. DOCUMENT ANY AFTERMARKET COMPONENT OR ANY

DAMAGE ON THE VEHICLE. FOR AN INTERMITTENT MISS/LACK OF POWER CONCERN,

THERE ARE NO COMMON CONCERNS IN THE HOTLINE DATA BASE TO INFORM YOU

OF. PLEASE CONTACT THE HOTLINE BY PHONE, USING THE CONTACT ID IN RED AT THE TOP OF THE PAGE, IF FURTHER TECHNICAL ASSISTANCE IS NEEDED ON THIS CONCERN.

REPAIR

03/23/2011 08:47AM LAWRENCE NEWSOM MSS - FCSD - TECH SVC HOTLINE

CUSTOMER HAS ALSO COMPLAINED OF POOR FUEL ECONOMY. UABLE TO VERIFY THE

CUSTOMERS COMPLAINTS. EEC PASSES, MODE 6 DATA SHOWS NO MISFIRE COUNTS

PRESENT. PERFORMED A IDS FUEL ECONOMY TEST WHICH SHOWS USAGE WAS IN SPEC.

RECOMM

03/23/2011 08:47AM LAWRENCE NEWSOM MSS - FCSD - TECH SVC HOTLINE

RITCHIE, ADVISE TO CONTINUE TO ATTEMPT TO DUPLICATE THE CONCERN.

ATTEMPT TO OBTAIN MORE INFORMATION FROM THE CUSTOMER ON WHEN THE CONCERN OCCURS COLD OR HOT ENGINE OPERATION, AT IDLE OR UNDER HEAVY

ACCELERATION. INSTALL A VDR TO ATTEMPT TO GET A POSSIBLE RECORDING OF

THE ALLEGED CONCERN.

ADD-ON

04/01/2011 11:59AM JORDAN DODDS MSS - FCSD - TECH SVC HOTLINE

THE DEALER WAS CONTACTED TO DISCUSS THIS VEHICLES CONCERN (SPOKE WITH

CARLENE). HOWEVER, THE TECHNICIAN WAS UNAVAILABLE AND WILL NOT RETURN

UNTIL MONDAY (4/4/11)

ADD-ON

04/01/2011 01:41PM ALEX BOUGHAN MSS - FCSD - TECH SVC HOTLINE

PLEASE HAVE THE TECH MONITOR THE SHORT TERM FUEL TRIMS, LONG TERM FUEL

TRIMS, BARO, FRP (ACTUAL AND DESIRED) AND OBTAIN FUEL SAMPLE FOR VISUAL INSPECTION.

AUDIT

07/02/2011 11:05AM

SYMPTOM 6 14 5 93 CHANGED TO 5 54 2 02 BY CS012093

REPAIR

07/12/2011 03:32PM CASEY WAGONER MSS - FCSD - TECH SVC HOTLINE

WEB FORM DATA - CONCERN: SES LIGHT MISSING, DIAGNOSTICS: ROAD TESTED PIN POINT, PARTS REPLACED:: NONE TECH QUESTION: KNOWNS

RECOMM 07/12/2011 03:32PM CASEY WAGONER MSS - FCSD - TECH SVC HOTLINE
RITCHIE, THE P0430 INDICATES THAT CATALYST FAILURE HAS OCCURRED. THIS CONCERN OF PREMATURE CATALYST FAILURE IS CURRENTLY UNDER ENGINEERING INVESTIGATION. BEFORE CLEARING ANY CODES OR DATA, PLEASE USE IDS TO VIEW MODE 6 DATA AND CLICK ON THE BLUE LINED BUTTON IN THE UPPER RIGHT HAND CORNER OF THE SCREEN. PLEASE THEN CLICK ON "LOG DATA." THIS WILL STORE MODE 6 DATA TO THE VEHICLE SESSION. PLEASE THEN HOLD THE VEHICLE SESSION AND THEN OPEN THE PREVIOUS SESSIONS SCREEN. HIGHLIGHT THE VEHICLE SESSION FOR THIS VEHICLE AND CLICK ON THE BUTTON WITH THE PICTURE OF THREE COMPUTERS AT THE RIGHT OF THE SCREEN. AS LONG AS YOU HAVE A GOOD INTERNET CONNECTION, THIS WILL SEND THE VEHICLE INTO THE HOTLINE FOR ENGINEERING REVIEW. PLEASE THEN PROCEED WITH REPLACEMENT OF THE AFFECTED CATALYST, RESET KAM, AND RETEST THE VEHICLE.

AUDIT 07/12/2011 03:32PM CASEY WAGONER MSS - FCSD - TECH SVC HOTLINE
SYMPTOM 5, 54, 2, 02 CHANGED TO 5, 51, 9, 02 BY CWAGONE1

REPAIR 07/12/2011 04:04PM TONY ROMANO MSS - FCSD - TECH SVC HOTLINE
RITCHIE CALLED TO ADVISE HE HAS FOUND THE NUMBER 6 PLUG'S CENTER ELECTRODE HAS BROKEN AND IT IS SLIDING DOWN TO COVER THE CENTER ELECTRODE.

RECOMM 07/12/2011 04:04PM TONY ROMANO MSS - FCSD - TECH SVC HOTLINE
THANKED RITCHIE FOR THE UPDATE AND ADVISED HIM TO RETEST FOR ANY CONCERNS AFTER THE CATALYST IS REPLACED. ESCALATION TO AN FSE CONTACT MAY OR MAY NOT BE NEEDED.

REPAIR 07/13/2011 02:05PM JACK STRAMER MSS - FCSD - TECH SVC HOTLINE
RITCHIE STATES THAT THE PLUG AND BANK 2 CATALYST WERE REPLACED AND VEHICLE SEEMED TO RUN GOOD. VEHICLE WAS RELEASED TO CUSTOMER AND CUSTOMER CALLED DEALER BACK STATING THE MIL CAME BACK ON AND THE TRUCK IS MISSING AGAIN. TRUCK IS NOT AT THE DEALER AT THIS TIME. TECH IS LOOKING FOR ESCALATION OR FSE.

RECOMM 07/13/2011 02:05PM JACK STRAMER MSS - FCSD - TECH SVC HOTLINE
ADVISED RITCHIE TO HAVE CUSTOMER BRING TRUCK TO DEALER. ALSO ADVISED THAT WE HAVE ESCALATED THIS CONCERN FOR ADDITIONAL REVIEW. A REPRESENTATIVE SHOULD CONTACT YOU BY PHONE OR THROUGH THIS

HOTLINE

ASSISTANCE REQUEST WITHIN ONE (1) BUSINESS DAY WITH ADDITIONAL INFORMATION OR RECOMMENDATIONS TO ASSIST IN THE RESOLUTION OF THIS VEHICLE CONCERN.

ADD-ON 07/13/2011 02:05PM JACK STRAMER MSS - FCSD - TECH SVC HOTLINE

ESCALATED DUE TO # OF CONTACTS TO HOTLINE FOR CONCERN AND FACT THAT CUSTOMER HAS OPEN CUDL SEEKING BUY-BACK

REPAIR 07/13/2011 03:55PM JORDAN DODDS MSS - FCSD - TECH SVC HOTLINE

AN OBC HAS BEEN PLACED TO THE DEALER TO DISCUSS THIS CONCERN IN GREATER DETAIL. RITCHIE (TECHNICIAN) HAS STATED THAT THE VEHICLE PREVIOUSLY EXHIBITED A MISFIRE CONCERN. UPON ARRIVAL OF THE VEHICLE, NO MISFIRES WERE PRESENT IN MODE 6 IN ADDITION TO POWER BALANCE. THE VEHICLE WAS RELEASED AND RETURNED WITH A MISFIRE ON CYLINDER NUMBER 6

AND A FAULTY SPARK PLUG WAS IDENTIFIED. THE INSULATION ON THE PLUG FAILED THUS DROPPING DOWN AND COVERING THE CENTER ELECTRODE. THE SPARK

PLUG HAS BEEN REPLACED AND THE VEHICLE RAN FAN AT THAT TIME. HOWEVER,

THE VEHICLE RETURNED WITH THE MIL LIGHT (P0430) WAS ON. THE CATALYST HAS BEEN REPLACED AND THE VEHICLE WAS RELEASED AGAIN. THE CUSTOMER CALLED THE DEALER AND HAS STATED THAT THE VEHICLE CONTINUES TO MISFIRE. THE VEHICLE IS CURRENTLY NOT AT THE DEALER. A CUDL CASE IS CURRENTLY OPEN INDICATING A POTENTIAL CASE OF BUY BACK/LEMON LAW.

TAR 07/13/2011 03:55PM JORDAN DODDS MSS - FCSD - TECH SVC HOTLINE

A TAR HAS BEEN OPENED AT THE REQUEST OF THE HOTLINE DUE TO A DOCUMENTED CUDL CASE. THE CUSTOMER HAS REQUESTED THAT THE VEHICLE BE

BOUGHT BACK. THIS VEHICLE EXHIBITS AN INTERMITTENT MISFIRE CONDITION. THE NUMBER SIX SPARK PLUG HAS BEEN REPLACED DUE TO A FAILED INSULATOR

WHICH HAS DROPPED DOWN THUS COVERING THE ELECTRODE. THE VEHICLE WAS

RELEASED WITH NO DRIVE-ABILITY CONCERNS AND RETURNED WITH DTC P0430. THE CATALYST HAS BEEN REPLACED AND THE CONDITION WAS RE-EVALUATED. THE

TRUCK DID NOT EXHIBIT ANY CONCERNS AND THE VEHICLE WAS RELEASED AGAIN.

HOWEVER, THE CUSTOMER CONTACTED THE DEALER STATING THAT THE MIL IS ON

AND THE TRUCK CONTINUES TO MISFIRE. THE VEHICLE IS CURRENTLY NOT AT THE DEALER. THE TECHNICAL HOTLINE SUSPECTS THIS CONCERN MAY BE A RESULT OF A LOOSE GROUND (G105) OR A FUEL PRESSURE/QUALITY RELATED

CONCERN. PLEASE ASSIST THE DEALER WITH DETERMINING ROOT CAUSE OF THIS
CONDITION. ESTIMATED NUMBER OF REPAIR ATTEMPTS: 3 ESTIMATED DAYS
OUT
OF SERVICE: 10

RECOMM 07/13/2011 03:55PM JORDAN DODDS MSS - FCSD - TECH SVC HOTLINE
RITCHIE, WE'VE REFERRED THIS CONCERN TO THE FIELD SERVICE ENGINEER
(FSE) IN YOUR MARKET AREA. THE FSE SHOULD CONTACT YOU OR DEALERSHIP
MANAGEMENT (SERVICE MANAGER OR SERVICE DIRECTOR) WITHIN ONE (1)
BUSINESS DAY. IF THE FSE DOES NOT CONTACT YOU DIRECTLY, PLEASE
CONSULT
WITH DEALERSHIP MANAGEMENT TO DISCUSS FURTHER RECOMMENDATIONS
AND
STEPS TO ASSIST IN THE RESOLUTION OF THIS VEHICLE CONCERN.

REPAIR 07/13/2011 04:27PM RICHARD MAILLOUX MSS - FCSD - TECH SVC HOTLINE
THE TECHNICIAN IS REQUESTING JORDAN FOR ADDITIONAL INFORMATION.

RECOMM 07/13/2011 04:27PM RICHARD MAILLOUX MSS - FCSD - TECH SVC HOTLINE
RITCHIE, A TECHNICAL SERVICE HOTLINE REPRESENTATIVE WILL BE
CONTACTING YOU SHORTLY.

REPAIR 07/13/2011 04:37PM JORDAN DODDS MSS - FCSD - TECH SVC HOTLINE
AN OBC HAS BEEN PLACED TO RITCHIE VIA HIS CELL PHONE NUMBER [REDACTED]
[REDACTED] RITCHIE WAS UNAVAILABLE DURING THE TIME OF THE CALL.

RECOMM 07/13/2011 04:37PM JORDAN DODDS MSS - FCSD - TECH SVC HOTLINE
RITCHIE, PLEASE CONTACT THE HOTLINE BY PHONE AT YOUR EARLIEST
CONVENIENCE.

REPAIR 07/13/2011 04:53PM JORDAN DODDS MSS - FCSD - TECH SVC HOTLINE
AN OBC HAS BEEN PLACED TO RITCHIE.

RECOMM 07/13/2011 04:53PM JORDAN DODDS MSS - FCSD - TECH SVC HOTLINE
RITCHIE HAS STATED THAT THE VEHICLE WILL ARRIVE IN THE MORNING AND
THE
CONCERN IS WORSE WITH AN INCREASE IN ENGINE TEMPERATURE.

ADD-ON 07/13/2011 04:53PM JORDAN DODDS MSS - FCSD - TECH SVC HOTLINE
NOTE TO FSE: THE VEHICLE WILL ARRIVE AT THE DEALER IN THE MORNING ON
THE DAY OF JULY 14, 2011. ADDITIONALLY, THE TECHNICIAN HAS STATED THAT
THE VEHICLES CONCERN IS MORE PROMINENT WITH AN INCREASE IN ENGINE
TEMPERATURE.

ADD-ON 07/14/2011 11:20AM KEVIN AVERY(FSE) MSS - FCSD - REG - BOSTON
I SPOKE WITH RICHIE YESTERDAY BEFORE THE TAR WAS FILED AS HE WAS
SEEKING ANY INFORMATION I MAY HAVE, I ADVISED THAT IF THE CUSTOMER IS
ALLEGING A RECURRENCE OF THE SAME ISSUE TO LOOK AT MODE 6 AGAIN TO
CONFIRM IF A MISFIRE WAS DETECTED. I ADVISED POSSIBLE STICKING VALVE
CONCERN OR INJECTOR.

ADD-ON 07/18/2011 10:58AM KEVIN OYAFUSO PD - PRODUCT DEVELOPMENT
SPOKE WITH RITCHIE, TECHNICIAN, REQUESTED SESSION DATA AND VERIFY G105 IS TIGHT. RITCHIE CALLED BACK AND SAID GROUND WAS TIGHT AND COULD NOT TIGHTEN IT MORE THAN A 1/8 TURN. ENGINE WAS NOT MISFIRING AT THE TIME. CUSTOMER HAD CONCERNS OF ENGINE RUNNING ROUGH SINCE MARCH 23, WITH 1100 MILES, TECH COULD NOT FIND ANY MISFIRES DURING THIS TIME. VEHICLE NOW HAS ABOUT 11000 MILES ON AND CAME IN FOR MIL ON, STILLS SAYS ENGINE RUNS ROUGH - NEED CLARIFICATION IF THIS IS DURING ACCEL TOO , VEHICLE HAS CAMPER ON THE BACK, NOT SURE IF USED WITH TRAILER, GETS WORSE WHEN ITS HOTTER (LONGER HE DRIVES). S UPERCAB 4X4 S
EEMS WORSE WHEN WET, M
ISFIRE TEST - NO CONCERS AT PARK, BRAKE TORQUE, NO MIS DURING POWER B ALANCE M
ODE 6: O2 STORAGE CAPACITY =.36;1, .32;1 RESULTS SHOW CAT MONITOR I S OK NOW(AFTER CAT REPLACEMENT) R
EL COMP: ALL CYLINDERS AT 0% M
ODE 9: PCM ID INDICATES AT R11= KGCH0C5.H32. REFLASHED LAST THURSDAY (7/14/11). D
ATALOGER SNAPSHOT RECORDED: M
FF_TRIP=3 M
FF_RPM=628 M
FF_VS=0 M
FFLOAD 16% M
FF_RUN=4:15 M
FF_SOAK=11:00 K
NK_CNTR_CYL=0 K
NK_CNTR=WAS AT 49 BEFORE #6 PLUG SWAP R
EQUESTED RITCHIE TO HOLD ON TO #6 PLUG AND CAT, THEN REPLACE ALL 6 P LUGS AND IGNITION COILS. ENGINEERING WILL REQUEST ALL PARTS BACK V IA HOT PROCESS FOR ANALYSIS. MAKE SURE ALL PLUGS AND COILS ARE L ABELED WITH ORIGINAL CYLINDER NUMBER.


ADD-ON 07/28/2011 11:07AM KEVIN AVERY(FSE) MSS - FCSD - REG - BOSTON
RECEIVED VOICE MAIL FROM TECH YESTERDAY, CALLED TECH TODAY AND WAS TOLD HE WAS AT LUNCH, LEFT MESSAGE FOR TECH TO CALL ME.

ADD-ON 07/28/2011 12:21PM KEVIN AVERY(FSE) MSS - FCSD - REG - BOSTON
SPOKE WITH SF RITCHIE WHO STATES HE REPLACED ALL 6 COILS AND PLUGS AND
CUSTOMER STATES STILL HAS THE CONCERN, VEHICLE IS NOT AT THE DEALERSHIP CURRENTLY. SF STATES HE SENT THE COILS AND PLUGS BACK LAST WEEK.

From: Hepburn, Mitch (M.)
Sent: Monday, November 07, 2011 9:54 AM
To: Gernant, Tim (T.R.); Garrett, David (D.P.); Whitehead, Joseph (J.P.); Smith, Craig (C.A.); Wagers, Sue (S.K.); Sims, Ivan (I.D.); Cockerill, Al (C.A.); De Coste, Bill (W.J.)
Cc: Graham, Daniel (D.B.); 'Christopher White'
Subject: 3.5 CAL. MISFIRE

Here is the latest over the weekend on the 4- 3.5L mis. Calibration units. CKD00034 is back on drives after getting ABS module replaced In Denver.

Chris White I need paperwork on this sent to me please for the repair with mileage and dealership and all.



Mitch Hepburn
Roush Industries
Vehicle Coordinator
U377-2012
VN127-2012
C346-2012.25 BEV
mhepbur1@ford.com
Cell - 734-748-5728

From: Hepburn, Mitch (M.)
Sent: Tuesday, November 08, 2011 9:44 AM
To: De Coste, Bill (W.J.); Gernant, Tim (T.R.); Garrett, David (D.P.); Whitehead, Joseph (J.P.); Smith, Craig (C.A.); Cockerill, Al (C.A.); Wagers, Sue (S.K.); Sims, Ivan (I.D.); Mazuchowski, James (J.A.)
Cc: Tatro, James (J.E.); Graham, Daniel (D.B.)
Subject: 3.5L calibration

CF [REDACTED] had a misfire detected late last night file was sent out this morning at 6.00am, here is the latest from drive yesterday all units ok except c [REDACTED] need next steps from team after reading the data please David. Thanks Mitch



Mitch Hepburn
Roush Industries
Vehicle Coordinator
U377-2012
VN127-2012
C346-2012.25 BEV
mhepbur1@ford.com
Cell - 734-748-5728

From: Wodzisz, Ken (K.R.)
Sent: Tuesday, April 19, 2011 2:30 PM
To: Reddy, Srikanth (S.C.); Smith, Craig (C.A.)
Cc: Shiposh, Melissa (M.A.); Fodera, Jas (J.J.)
Subject: 3.5L Cat melt

Sri/Craig,

We got our first 3.5L warranty return (LH cat). The front face of brick shows clear signs of overtemp (spider lines). The vehicle was exhibiting misfire codes.

Do you want to do anything with this cat?

There is not much value in tearing it down on my end.

Ken Wodzisz

BoF and Mustang Exhaust Supervisor
Ford Bldg 2 (2-3K02) MD 1232
Ph: (313) 805-3355

From: Wagner, Glen (G.C.)
Sent: Friday, January 11, 2013 4:54 PM
To: Dobbs, Dan (K.D.)
Cc: Nowaczyk, Rick (R.J.); Oyafuso, Kevin (K.G.)
Subject: 3.5L F150 CAC

How are we handling customers that continue to have CAC condensation miss-fire issue after the vehicle has the latest fixes installed?

Glen Wagner
FCSD Commodity Program Manager, Fuel / Exhaust / Air Induction / Cooling / Controls / Calibration / Gas Engine
Phone 313 32-26768

From: Whitehead, Joseph (J.P.)
Sent: Wednesday, October 12, 2011 8:48 AM
To: Peters, Robin (R.S.); Mills, Linda (L.S.); Michela, Mike (M.); Sullivan, Todd (T.E.)
Cc: Smith, Craig (C.A.); Garrett, David (D.P.); Whitehead, Joseph (J.P.)
Subject: 3.5L P415 Emergency Releases

Importance: High

All,
New calibrations will be released for 3.5L P415 for misfire detection and mitigation. Service calcs will be released for 2011.5 and running change calcs for 2012.

Your help is needed to support this effort.

Robin,

1. Could you please add Craig and I to the **Cert Review** agenda on Oct 19?
2. Could you please schedule an **emergency release** meeting for Thursday Oct 20?

Linda,

Could you please provide two new **whitepaper numbers** for the following:

1. 2011.5 3.5L P415 R12 Service Fix
2. 2012 3.5L P415 R08 Running Change.

Need these numbers by Friday Oct 14.

Mike,

Could you please supply **concern number** by Friday to support these releases?

Todd,

1. Could you please release the KGCH2 & KGCP2 **prelim** strategies by Friday morning Oct 14?
2. **Final** strategies by Tuesday morning Oct 18?

Thanks,

Joe Whitehead
3.5L GTDI P415 Calibration
jwhiteh4@ford.com
313 805-5481

From: Norman, Kristofor (K.R.)
Sent: Monday, January 23, 2012 11:38 AM
To: Norman, Kristofor (K.R.); Gardner, Greg (G.D.); McCoy, Jim (D.); Saad, Thomas (T.J.); Nester, Darren (D.); Kramer, Michael (M.T.); Ladd, John (J.R.); Madej, Jeanette (J.); Allan, Valerie (V.J.); Baldwin, Damien (D.K.); Emery, Jim (J.M.); Bollman, Wes (W.); Lyon, Peter (P.M.); Dumler, Jeff (J.D.); Yamada, Shuya Shark (S.Y.); Sparks, Douglas (D.S.); Fabien, Phil (P.A.); Smith, Craig (C.A.); Nault, Ben (B.D.); Pierce, Michael (M.A.); Sims, Ivan (I.D.); Morrow, Bill (N.W.); Donahue, Francis (Fran.); Cockerill, Al (C.A.); Fried, Marcus (M.W.); Devries, Jason (J.E.); Whitehead, Joseph (J.P.); Krygowski, Richard (R.J.); Cowher, Terry (T.); Hargreaves, Gregory (G.J.); Garrett, David (D.P.); Sullivan, Todd (T.E.); Imarisio, Valerio (V.); Zott, Brian (B.R.); Mancini, Michael (M.A.); Pawlak, Greg (G.J.); Ahmed, Masood (M.); Dixon, Mark (M.R.); Wilson, David (D.G.); Dusa, Daniel (D.V.); Wagers, Sue (S.K.); Zimlich, Mary (M.); Mingo, Paul (P.C.); Rollinger, John (J.E.); Huberts, Garlan (G.); Baskins, Robert (R.S.); Michela, Mike (M.); Zhou, Jay (J.); Lehto, Scott (S.A.); Mazuchowski, James (J.A.); Hammoud, Mazen (M.); Boerger, Jim (J.G.); Merrell, Robert (R.J.); Stanley, Daniel (D.J.); Ronzi, Bill (W.C.); Palepu, Padmalaya (P.); Stefanski, John (J.C.); Russ, Stephen (S.G.); Glugla, Chris (C.P.); McDonagh, Scot (S.M.); Ricks, Kevin (K.J.); Dobbs, Dan (K.D.); Nowaczyk, Rick (R.J.); Ducklow, Corey (C.S.); Bailey, Owen (O.R.); Mohan, Robert (R.); Yamada, Shuya Shark (S.Y.); Madej, Jeanette (J.); Andersen, Erik (E.); Huang, Larry (L.)
Subject: 1/23 D35 Misfire Meeting 3pm Audio and Webex in meeting notice.

- 1) Review CAC Benchmark Info - Ladd/Huang/Anderson/Palm
- 2) Upcoming Testing Plans, PT Dyno and DTF - Glugla/Mandjack/Palm/McCoy
- 3) Hardware fabrication progress from last meeting - All/below

Regards,

Kristofor Norman
Manager, Engine Performance Development
Global Engine Engineering
knorman1@ford.com
313-390-7855

From: Norman, Kristofor (K.R.)
Sent: Thursday, January 19, 2012 1:43 PM
To: Norman, Kristofor (K.R.); Gardner, Greg (G.D.); McCoy, Jim (D.); Saad, Thomas (T.J.); Nester, Darren (D.); Kramer, Michael (M.T.); Ladd, John (J.R.); Madej, Jeanette (J.); Allan, Valerie (V.J.); Baldwin, Damien (D.K.); Emery, Jim (J.M.); Bollman, Wes (W.); Lyon, Peter (P.M.); Dumler, Jeff (J.D.); Yamada, Shuya Shark (S.Y.); Sparks, Douglas (D.S.); Fabien, Phil (P.A.); Smith, Craig (C.A.); Nault, Ben (B.D.); Pierce, Michael (M.A.); Sims, Ivan (I.D.); Morrow, Bill (N.W.); Donahue, Francis (Fran.); Cockerill, Al (C.A.); Fried, Marcus (M.W.); Devries, Jason (J.E.); Whitehead, Joseph (J.P.); Krygowski, Richard (R.J.); Cowher, Terry (T.); Hargreaves, Gregory (G.J.); Garrett, David (D.P.); Sullivan, Todd (T.E.); Imarisio, Valerio (V.); Zott, Brian (B.R.); Mancini, Michael (M.A.); Pawlak, Greg (G.J.); Ahmed, Masood (M.); Dixon, Mark (M.R.); Wilson, David (D.G.); Dusa, Daniel (D.V.); Wagers, Sue (S.K.); Zimlich, Mary (M.); Mingo, Paul (P.C.); Rollinger, John (J.E.); Huberts, Garlan (G.); Baskins, Robert (R.S.); Michela, Mike (M.); Zhou, Jay (J.); Lehto, Scott (S.A.); Mazuchowski, James (J.A.); Hammoud, Mazen (M.); Boerger, Jim (J.G.); Merrell, Robert (R.J.); Stanley, Daniel (D.J.); Ronzi, Bill (W.C.); Palepu, Padmalaya (P.); Stefanski, John (J.C.); Russ, Stephen (S.G.); Glugla, Chris (C.P.); McDonagh, Scot (S.M.); Ricks, Kevin (K.J.); Dobbs, Dan (K.D.); Nowaczyk, Rick (R.J.); Ducklow, Corey (C.S.); Bailey, Owen (O.R.); Mohan, Robert (R.); Norman, Kristofor (K.R.); Yamada, Shuya Shark (S.Y.)
Subject: 1/19 D35 Misfire Meeting Minutes

Reviewed DTF and PT Dyno Testing - . Confirmed process to make sufficient condensate in conditions of around 30 min. Even worse at higher temps. Separator/reservoir concepts in HP AIS did not prevent misfire. A static test indicated that the CAC can hold 23 oz of water.

PT cooling, Palm, will work to develop a bench test for flow/condensate through the CAC/AIS/Manifold at dyno basement or PFSL.

Concepts to be fabricated for testing:

Manifold Runners in a Box - Cockerill

Manifold End Reservoir/Absorber - Cockerill

Build a CAC end tank perforated separator/lith part - Cockerill

Orient CAC for down flow connection - McCoy desired to run at DTF on Monday

Develop an improved HP AIS can separator, better location(s) - Palm

Procure from supplier reduced turbulator/louver tubes CAC - Palm

Develop an ideal HP AIS trap design - Russ/Norman/Yamada

TIMING is ASAP on all.

Regards,

Kristofor Norman

Manager, Engine Performance Development

Global Engine Engineering

knorman1@ford.com

313-390-7855

From: Norman, Kristofor (K.R.)
Sent: Thursday, January 19, 2012 8:05 AM
To: Gardner, Greg (G.D.); McCoy, Jim (D.); Saad, Thomas (T.J.); Nester, Darren (D.); Bld-1 13F040 (20); Kramer, Michael (M.T.); Ladd, John (J.R.); Madej, Jeanette (J.); Allan, Valerie (V.J.); Baldwin, Damien (D.K.); Emery, Jim (J.M.); Bollman, Wes (W.); Lyon, Peter (P.M.); Dumler, Jeff (J.D.); Yamada, Shuya Shark (S.Y.); Sparks, Douglas (D.S.); Fabien, Phil (P.A.); Smith, Craig (C.A.); Nault, Ben (B.D.); Pierce, Michael (M.A.); Sims, Ivan (I.D.); Morrow, Bill (N.W.); Donahue, Francis (Fran.); Cockerill, Al (C.A.); Fried, Marcus (M.W.); Devries, Jason (J.E.); Whitehead, Joseph (J.P.); Krygowski, Richard (R.J.); Cowher, Terry (T.); Hargreaves, Gregory (G.J.); Garrett, David (D.P.); Sullivan, Todd (T.E.); Imarisio, Valerio (V.); Zott, Brian (B.R.); Mancini, Michael (M.A.); Pawlak, Greg (G.J.); Ahmed, Masood (M.); Dixon, Mark (M.R.); Wilson, David (D.G.); Dusa, Daniel (D.V.); Wagers, Sue (S.K.); Zimlich, Mary (M.); Mingo, Paul (P.C.); Rollinger, John (J.E.); Huberts, Garlan (G.); Baskins, Robert (R.S.); Michela, Mike (M.); Zhou, Jay (J.); Lehto, Scott (S.A.); Mazuchowski, James (J.A.); Hammoud, Mazen (M.); Boerger, Jim (J.G.); Merrell, Robert (R.J.); Stanley, Daniel (D.J.); Ronzi, Bill (W.C.); Palepu, Padmalaya (P.); Stefanski, John (J.C.); Russ, Stephen (S.G.); Glugla, Chris (C.P.); McDonagh, Scot (S.M.); Ricks, Kevin (K.J.); Dobbs, Dan (K.D.); Nowaczyk, Rick (R.J.); Ducklow, Corey (C.S.); Bailey, Owen (O.R.); Mohan, Robert (R.)
Subject: 1/19 D35 Misfire Meeting Agenda

12pm 13F040 Audio and Webex in Mtg Notice

- 1) Review latest DTF/PT Dyno test results - Glugla/Mandjack
- 2) Determine next steps for potential fixes, testing required - All
PT Cooling, please bring in CAC cutaways/drawings
- 3) How to proceed with IP

Regards,

Kristofor Norman

Manager, Engine Performance Development

Global Engine Engineering

knorman1@ford.com

313-390-7855

From: Kramer, Michael (M.T.)
Sent: Tuesday, May 14, 2013 9:12 AM
To: Corey SMALL <corey.small@valeo.com> (corey.small@valeo.com); Satish NADELLA; Kramer, Michael (M.T.); ying.tang@valeo.com; Guillermo GUADARRAMA; Blas-Fernando GUTIERREZ; Tyler, Jim (J.S.); Huang, Larry (L.); Joseph LUMETTA; Larry ENGEL
Cc: Alcaraz andrade, Alejandro (M.); Tyler, Jim (J.S.); Kramer, Michael (M.T.)
Subject: A couple open Valeo items

A) On track for 5/16 or sooner for the following data sheets with original J1 CAC internals (these are the ones that were first run with the wrong CAC internals):

- 1) Externally block bottom 7 tubes / 8 fins
- 2) Externally block bottom 4 tubes / 5 fins
- 3) Externally block bottom 7 tubes / 8 fins .25% of the length across the CAC from the inlet side and the bottom 3 tubes / 4 fins the remainder of the length ("L" laying on its side).

B) Status of P415 CAC corrosion testing with 7 tube / 8 fin lower blocker.

Mike Kramer
RWD PT Cooling Supv.
Six Sigma Black Belt
Cell Phone: (313) 805-0190
Text Page: mkramer1
Page from outside Ford. External email: mkramer1@ford.com

From: Oyafuso, Kevin (K.G.)
Sent: Wednesday, May 16, 2012 12:04 PM
To: McCoy, Jim (D.)
Cc: Whitehead, Joseph (J.P.); Smith, Craig (C.A.); Devries, Jason (J.E.); Cockerill, Al (C.A.); Yamada, Shuya Shark (S.Y.); Dixon, Mark (M.R.)
Subject: ADR2 FILES FROM MAINE BUYBACK A82092 WITH MODIFIED CAC AND R12.2 SERVICE FIX

p415 gtdi cac mod
r12_2 5_16_2...

Here are the files from the VOCF drive with the latest service release and modified CAC - driver did comment on mis-feeling/surge (he calls it rapid fluttering) with wot and cruise- I didn't see any evidence of misfire (during wot) or cbv cycling (with cruise control)but please look at these files and let me know if you see something unusual. Data is from the Maine buyback with a 5000lb trailer. It was raining this morning but it stopped by 6:30am. Driver made me a copy of his comments and I will send it out when I can get to a scanner.

Regards,
Kevin Oyafuso
Ford Motor Company
PD / Powertrain Integration Management - C&C Quality
(313) 805-4908

From: Nowaczyk, Rick (R.J.)
Sent: Wednesday, November 14, 2012 9:35 AM
To: Triplette, Wesley (.)
Subject: Buyback Case - CAC Part Request

Importance: High

Wes,

Has the dealer ordered the CAC under Emergency Order? If not, please have them order the part under Emergency Order and give me their P/A number. I will see if we can get them bumped a head of the line for these CAC backorders.

Regards,
Rick Nowaczyk
FCSD Product Concern Engineer
F-150, Freestar/Monterey, Ford GT, Th!nk
E-mail: rnowaczy@ford.com
Diagnostic Service Center-I, Allen Park
PH# 313-322-7251

From: Tyler, Jim (J.S.)
Sent: Thursday, February 16, 2012 3:23 PM
To: Grabowski, Joseph (J.)
Cc: Meyer, Robert (R.H.); Andersen, Erik (E.); Hayes, Kenneth (K.J.); Huang, Larry (L.)
Subject: CAC Air Deflector revision to block top 6 P415 CAC tubes BL34-19E672-AA

Joe, please make a CAD proposal using the current P415 CAC deflector BL34-19E672-AA to incorporate a front side panel that blocks the first 6 upper tubes of the core. The front section should be located with 9mm clearance from the core face and can use rubber bumpers like used on the fan shrouds to isolate vibration contact with the headers.

Please call me on Friday morning to go over details by phone. This is to support very high priority CAC water condensation vehicle issues.

Jim Tyler
T1/P552 Cooling
313-805-2565 Bld-2 23P25

SECTION 303-12 Intake Air Distribution and Filtering

CONTENTS	PAGE
GENERAL PROCEDURES	
Charge Air Cooler (CAC) Cleaning	303-12-2
Charge Air Cooler (CAC) Cleaning	303-12-2

GENERAL PROCEDURES**Charge Air Cooler (CAC) Cleaning****Material**

Item	Specification
Metal Brake Parts Cleaner PM-4-A or PM-4-B (US); CPM-4 (Canada)	—

Charge Air Cooler (CAC) Cleaning

1. Remove the Charge Air Cooler (CAC). For additional information, refer to Charge Air Cooler in this section.

2. **NOTICE:**

Do not use a high-pressure power washer to clean the Charge Air Cooler (CAC) or the CAC may be damaged.

NOTE:

Drain all contaminants such as coolant, fuel and oil prior to cleaning the Charge Air Cooler (CAC).

NOTE:

Thoroughly clean the joint clamp areas as well as the turbocharger connections and the engine connection using metal brake parts cleaner.

Lay the CAC flat with the inlet and outlet ports pointing up.

3. **NOTE:**

Plug or cap the CAC openings prior to agitating.

Add an appropriate amount of commercially available detergent cleaner such as Simple Green® Pro HD, or equivalent, to the CAC. Follow the manufacturer's directions for cleaning. Fill the CAC to 40% of its volume with water.

4. Raise one end of the CAC and agitate it by hand for at least 5 minutes.

5. Raise the opposite end of the CAC and agitate it by hand for at least 5 minutes.

6. Drain the CAC.

7. Flush the CAC thoroughly with clean water.

8. Repeat Steps 1 through 6 until no contaminants are found in the flush water.

9. Allow the CAC to air dry.

10. **NOTE:**

The following leak test steps must be performed prior to installing the CAC.

NOTE:

Use a commercially available kit, such as the SPX/OTC Charged Air Cooler Tester No. 5039, or equivalent.

Install the commercially available CAC cooler tester on the CAC following the manufacturer's installation instructions.

- Tighten the clamps to 5 Nm (44 lb-in).

11.

**WARNING:**

Never exceed the specified pressure. Excessive pressure may cause the test adapter to blow off or may damage the charge air cooler (CAC). Failure to follow this instruction may result in serious personal injury.

Slowly apply air pressure to 150 kPa (22 psi).

12. Let the CAC stand for a few minutes and note any loss in pressure.

- Release the air pressure.

13. Repeat Steps 11 and 12 as many times as necessary to verify the readings. The reading is considered verified when 3 consecutive tests show approximately the same pressure drop.

- If the pressure loss exceeds 20 kPa (3 psi) per minute, install a new CAC. For additional information, refer to Charge Air Cooler in this section.

From: Ridolfi, Dominic (D.R.)
Sent: Monday, November 05, 2012 1:26 PM
To: Abercrombie, Robert (R.); Barrett, Dale (D.); Chatfield, David (D.); Dowdy, Jonathon (J.); Fenning, Brett (B.); Ferret, Shawn (S.); French, Sean (S.P.); Gammon, Charles (C.); Girard, Mario (y.); Graham, Brian (B.); Hebert, Adam (A.); Higgs, Justin (J.); Houston, Willie (W.); Jacobs, Phil (P.); Johnson, Seth (S.); Kvenvold, Derek (D.); Mason, Nicholas (N.G.); Massey, Stephen (S.); McEntee, Alec (A.); Meers, Brian (B.); Messina, Matthew (M.); Ridolfi, Dominic (D.R.); Romano, Tony (T.); Samson, Jean (J.); Sanders, Kevin (K.); Schmidt, Matthew (M.); Schober, Michael (M.); Sheahan, Karen (K.); Singleton, Sylvain (S.); Smith, Walter (W.A.); Stendardo, David (D.)
Subject: CAC Condensation

Team,

With 2013 F-150s hitting the street, and the service part CAC from TSB 12-10-19 being installed across the country, we've been able to gauge our responses moving forward in regards to CAC condensation on F-150 GTDI. Far and away the most important point regarding this topic is the following:

We are going to see water develop in the CAC during normal operation, regardless which CAC is installed on the vehicle.

Moving forward, **this means that our previous recommendation to check the air inlet and throttle body for water tracking/marks is invalid and should no longer be used.** A normally operating vehicle can still show signs of water tracking to the throttle plate, and exhibit no drivability concerns – therefore using the old recommendation of checking for this in order to verify a CAC condensation misfire is invalid and will lead to the misfire still being present after the CAC is replaced.

This is not to say we are never to recommend CAC replacement. We will still be contacted with clear CAC condensation misfires, but more likely, we will be contacted by a tech looking for clarification. With the recommendation to check for water staining no longer an option, the best way to respond to this type of contact is to fully identify the symptoms of a CAC misfire.

The following will be review for most, and some of these things will seem obvious – however all of these symptoms below were lifted directly from GCQIS reports where we recommended replacing the CAC...

A CAC misfire will:

- Cause a bank two misfire
- Occur during WOT acceleration, after extended highway driving
- Require road testing, often extended, to duplicate
- Can set a P0430

A CAC misfire will not:

- Cause a bank one misfire
- Set circuit codes
- Set a P0420
- Cause low compression on a cylinder
- Be present at startup, P0316
- Be present at idle
- Create a dead miss, or misfire/concern that can be duplicated at will, every time
- Cause a vibration present at all times or at all times when driving
- Cause a misfire/stumble/surge during steady cruise

- Be duplicated in the service bay

There is no doubt that we will get plenty of first contacts in to the Hotline where, prior to any communication is started with us, the vehicle has already had an unsuccessful CAC replacement. There isn't anything we can do about the TSB being performed before they contact us, outside of providing information as to what this updated CAC typically will fix, and continuing to assist the technician with normal diagnostics.

What we can do is, once contact is opened on these vehicles, advise the technician clearly and properly on the nature of the CAC condensation miss. We made quite a few of these trucks and it's likely every tech that asks us a question on one of these will deal with another one somewhere down the line. It's important we use the symptoms of the concern to accurately ID these contacts as CAC misfire, or normal diag.

If there are any questions as to a possible CAC miss, or a contact where we could be dealing with more than one concern, please come talk to Bob or myself about it.

Dominic Ridolfi

3.0/3.5/3.7/GTDI Subject Matter Expert

Ford Technical Hotline

Diagnostic Service Center 1

1700 Fairlane Dr. Allen Park, MI 48101

(313) 248-8241

From: Whitehead, Joseph (J.P.)
Sent: Wednesday, May 22, 2013 2:30 PM
To: Leisenring, Kenneth (K.C.); Smith, Craig (C.A.); Strylo, Tom (T.M.)
Cc: Whitehead, Joseph (J.P.)
Subject: CAC Demo Trucks

Ken and Craig,

Two 3.5L GTDI P415 vehicles are available for CAC condensate ingestion demonstrations.

1. Crew cab 4X2 3.15 RAR, 294W942, has a 8,000 lb. trailer connected and is parked behind APTL. The max GCWR for this configuration is 15,700 lbs. The rough weight of this truck & trailer is 14,000 lbs.
2. Crew cab 4X4 3.73 RAR, 579W103, w/o trailer is parked @ TEE spot #15.

Suggested drive route for truck w/ trailer:

1. APTL to Melvindale ice rink parking lot. WOP accel on Enterprise for base performance feel w/o misfire.
2. Add 6 oz. water to CAC @ ice rink.
3. WOP ingestion accel on Enterprise.
4. Return to APTL.
5. Probably 10 minutes total time.

These vehicles are immediately available upon your request. The trailer has been borrowed until next Friday, May 31.

Tom,
Really appreciate your help setting up the truck.

Thanks,

Joe Whitehead
3.5L GTDI P415 Calibration
jwhiteh4@ford.com
313 805-5481

From: Nowaczyk, Rick (R.J.)
Sent: Monday, October 22, 2012 2:16 PM
To: White, Eric (E.)
Cc: Nowaczyk, Rick (R.J.)
Subject: CAC Emergency Order P/A Codes

Importance: High

Eric,

Here are the current dealers that need CAC's ASAP to prevent a buyback that should have Emergency orders placed in the system.

04182
09685
01423
03781
04924
05677
02865
04735
02739

Regards,
Rick Nowaczyk
FCSD Product Concern Engineer
F-150, Freestar/Monterey, Ford GT, Th!nk
E-mail: rnowaczy@ford.com
Diagnostic Service Center-I, Allen Park
PH# 313-322-7251

From: Dobbs, Dan (K.D.)
Sent: Wednesday, February 20, 2013 10:40 AM
To: Ricks, Kevin (K.J.); Norton, John (J.K.)
Cc: Nowaczyk, Rick (R.J.)
Subject: CAC Overview
Attachments: CAC Overview.docx

Please find attached a summary of the 3.5L GTDI Misfire Concern.

If I can clarify or answer any additional questions, please let me know.

3.5L Ecoboost - Charge Air Cooler Related Misfire Overview:

In certain locations in the U.S. and Canada, the 3.5L "Ecoboost" engine may develop excessive condensation in the Charge Air Cooler (CAC) as a normal part of operation. The primary locations are near high humidity zones, or areas that are experiencing extended rainy periods. At this time of the year, we are seeing the typical conditions in:

- SouthEast U.S. (East Texas, LA, AL,MS,FL,GA)
- Northwest U.S (WA,OR)
- Canada (Manitoba,Ontario, Newfoundland)

We released TSB 12-10-19 on October 30th 2012. The TSB provides a repair procedure that may include replacing the CAC (BL3Z-6K775-B) with one that has been revised to reduce the condensation condition. There is no other performance benefit from installing the revised CAC.

We presently have ~ 4,300 CAC's on backorder. The CAC part has been on backorder since November 2012. The supplier is running at maximum to maintain production volumes and meet service demand. **NOTE:** *The service part is unique for 2011 and 2012 units, and the 2013 part is not backward compatible to previous model years.*

We are currently prioritizing orders where the CRC has open cases with the trucks noted as "out of service"." Dealers who need the revised CAC (and do not have a unit "out of service") are best served to enter an Emergency Order to PS&L to get in line for the parts as they become available.

Published Articles to Dealers

- **SSM 22192 (released 1-24-12, deactivated 2-20-12)**
 - Highlighted that the Misfire condition is under investigation
 - Do not replace Ignition parts to try and correct the concern
- **TSB 12-2-10 (released 2-15-12)**
 - Units built on of before 2-7-12
 - Revised calibration for multiple issues
 - Included an updated FMEM to protect Catalyst
- **SSM 22225 (released 2-21-12, deactivated 6-7-12)**
 - Referred Dealers to use TSB 12-2-10 for a broader spectrum of issues than the TSB stated
- **TSB 12-6-4 (released 6-7-12, superceded elements of 12-2-10)**
 - Add deflector to the CAC for units builds before 5/24/12
 - Reflash for FMEM and other items
 - For units with P0430 replace the LH Catalyst
- **TSB 12-10-19 (released 10-30-12, superceded TSB 12-6-4)**
 - Units built before 9-18-12 (KCAP 9-17-12) with the described symptoms (loss of power, and specific DTC's)
 - Applicable units will receive a revised Charge Air Cooler (CAC)
 - Dealer will transfer the previously installed air deflector to the new CAC
 - Units not previously flashed under TSB 12-6-4 will be reflashed
 - If code P0430 is present they will replace the LH Catalyst

Technical Points:

1. The misfire condition can and often will damage the Left Hand Catalyst.
2. The amount of condensation required to induce the concern can be as low as ~ 8 oz.
3. The condensation will purge only under heavy acceleration (at or near WOT), the air volume has to break the surface tension of the condensation to get it into the airflow.
4. The flow of condensation in the airflow will impact cylinder #6 first, and then can impact Cylinders #5 and #4.
5. Dyno testing has shown that the condensation can be fully purged after ~ 2-3 WOT cycles.
6. Owners may or may not have stored DTC's from this condition.
7. Owners may also have no record of the misfire event in "freeze frame or Mode 6" memory.
8. We have 19 cases of the repeat misfire concerns after the revised CAC was installed – issue is in emerging status at 76% of QSF threshold.

Reference and Observation Points:


1. The CAC is used in Turbocharged and Supercharged applications to cool the air before it enters the engine. The process of cooling the air will always create some condensation. In this case, the condensation can collect over time and cause the noted concern. The revised CAC pulls the condensation through at a higher rate than the previous CAC (reducing buildup of condensation). Preventing a large build-up of condensation will reduce the chance for the condition to occur.
2. Owners outside of the high humidity areas will have a low chance of experiencing the issue. If it does occur, the condition will likely be gone by the time they arrive at the Dealership (condensation purges under heavy acceleration). The concern will also have a very slight chance of repeating.
3. The ingestion of CAC related condensation will not harm the engine. We have no cases where engine damage from condensation has been proven.
4. The vehicles that have experienced the misfire concern are driveable and should not be taken out of service. However, Dealers have the authority to do so if in their judgement there is a concern. Some owners have refused to take the units while they wait on parts, and these should be reported to the CRC to get on the "out of service list".
5. The issue has been noted on several Public Websites, and some owners are insisting on the revised part. As stated above, if owners in dry areas do not have a CAC condensation related misfire concern -they will see no performance gain by installing the revised CAC.
6. Some Dealers are not following the TSB, and are adding the revised CAC for other issues. The CAC related concern will only occur under heavy acceleration with excessive condensation present in the CAC. Light throttle surge, rough idle, or buck jerk on tip-in throttle are not related this issue. We have other TSB's in place or in process to address these concerns.
7. This issue will not impact fuel economy concerns. If there is a concern, most owners will have a "Service Engine Soon" lamp illuminated. Light throttle cruise mode at legal Highway speeds is not impacted by this concern.
8. Owners need to have the vehicle inspected by their local Dealer to assess the concern, and to see if the TSB 12-10-19 actually applies. There are other engine conditions including bad spark plugs, fuel supply, or ignition coils that can mimick the condition.
9. We have published multiple TSB's on this issue including revised calibrations to assist with diagnosis and operation. Dealers are likely frustrated with us, and are sometimes defaulting to adding the revised CAC as a result of multiple attempts to correct the concern.

From: Cockerill, Al (C.A.)
Sent: Tuesday, March 13, 2012 11:31 AM
To: Kurt@qualitymetalcraft.com
Cc: Ladd, John (J.R.); Kramer, Michael (M.T.); Madej, Jeanette (J.)
Subject: Charge Air Cooler Stamping


Importance: High

Kurt,

Your company did some work for us on engine lift eye stampings during the launch of the 2011 F150. I am in need of assistance again for a very simple stamping to be sent to a company in Mexico called Valeo. The part I am looking for is to block off part of our Charge Air Cooler, crude picture below. What I am thinking is a single aluminum stamping that will cover the inlets. The yellow part is the single stamping. Timing is critical and we are looking for your assistance. Please contact me.



1 Part Yellow
covers 21 tubes



The spirit, the will to win, and the will to excel are the things that endure. These qualities are so much more important than the events that occur. The harder you work, the harder it is to surrender.

Vince Lombardi

Al Cockerill
RWD V6 Engine System Supervisor
313-805-2333 C
313-845-0475 O

From: Cockerill, Al (C.A.)
Sent: Monday, June 06, 2011 4:19 PM
To: Hamilton, Steven (S.C.); Gorgol, Kevin (K.); Osepchok, William (W.R.); Reno, George (G.L.); Matera, Steve (S.L.); Mazuchowski, James (J.A.); Donahue, Francis (Fran.); Mazuchowski, James (J.A.)
Subject: Customer Bring Back Investigation.xls

All, per our conversation today, the list attached are the Candidates to bring the customer back in for a G105 review. Kevin & Steve, please let me know which one you want to go after. The one the I highlighted is the repeat return for G105 and then a catalyst.



© 2011 Microsoft Corporation
All rights reserved. Microsoft, the Microsoft Dynamics logo, and the Microsoft Dynamics logo are either registered trademarks or trademarks of Microsoft Corporation in the United States and/or other countries.

PROBABLE / SUSPECT ROOT CAUSE	GCQIS REPORT	VIN	DEALERSHIP	STATE / PROVINCE
COP	N/A	1FTFX1ET0B	DONLEY FORD OF SHELBY	OH
COP	N/A	1FTFW1ET7B	HILLER FORD INC	WI
COP	N/A	1FTFW1ET3B	DON HINDS FORD INC	IN
COP	N/A	1FTFW1CT1B	BILLY HOWELL FORD LINCOLN-MERC	GA
COP	N/A	1FTFW1ET8B	SOUND FORD, INC.	WA
DIAG - MISFIRE	N/A	1FTFW1ET7B	TOM HOLZER FORD, INC.	MI
DIAG - MISFIRE	BCWAN004	1FTFX1ET1B	YORK FORD SALES	ME
DIAG - MISFIRE	N/A	1FTFW1ET3B	DRUM HILL FORD INC	MA
DIAG - MISFIRE	N/A	1FTFW1ET5B	OROVILLE FORD LINCOLN MERCURY	CA
DIAG - MISFIRE	N/A	1FTFW1ET4B	STEVE MARSH FORD	TN
DIAG - MISFIRE	N/A	1FTFW1ET5B	ECKENROD FORD LINCOLN OF CULLM	AL
DIAG - MISFIRE	N/A	1FTFW1CT7B	LONG-LEWIS FORD LINCOLN	AL
DIAG - MISFIRE	BDKBE020	1FTFX1ET2B	FREEWAY FORD	MN
DIAG - MISFIRE	N/A	1FTFX1ET4B	CASKINETTE'S LOFINK MOTOR CO.	NY
DIAG - MISFIRE	N/A	1FTFW1ET0B	JIM O'NEAL FORD, INC.	IN
DIAG - MISFIRE	N/A	1FTFW1ET9B	COTRAC FORD LINCOLN SALES INC.	ON
DIAG - MISFIRE	N/A	1FTFW1ET3B	EINSPAHR AUTO PLAZA, INC.	SD
DIAG - MISFIRE	N/A	1FTFW1ETXB	KENTWOOD FORD SALES, INC.	AB
DIAG - MISFIRE	N/A	1FTFX1ET4B	VAN CLEVE FORD, INC.	WA
DIAG - MISFIRE	N/A	1FTFW1ET2B	WESTLIE MOTOR COMPANY	ND
DIAG - MISFIRE	BDUCN006	1FTFW1ET6B	ARCHIE COCHRANE MOTORS, INC.	MT
DIAG - MISFIRE	BDYA4019	1FTFW1ET6B	MILLS FORD OF WILLMAR	MN
DIAG - MISFIRE	N/A	1FTFW1ET0B	TENVOORDE FORD, INC.	MN
DIAG - MISFIRE	BDTAW017	1FTFW1ET4B	SIOUX CITY FORD LINCOLN MERCUR	IA
DIAG - MISFIRE	N/A	1FTFW1ET5B	BOURGEOIS MOTORS LIMITED	ON
DIAG - MISFIRE	N/A	1FTFW1ET1B	FRIENDLY FORD, INC.	MI
DIAG - MISFIRE	N/A	1FTFW1ET3B	RUXER FORD LINCOLN, INC.	IN
DIAG - MISFIRE	BEEAQ015	1FTFW1ET0B	HOFFMAN FORD, INC.	CT
DIAG - MISFIRE	N/A	1FTFW1ET9B	RUXER FORD LINCOLN, INC.	IN
DIAG - MISFIRE	N/A	1FTFX1ET3B	PLAMONDON AUTOS INC.	QC
DIAG - MISFIRE	N/A	1FTFX1ET9B	BOUCHARD FORD	QC
DIAG - MISFIRE	N/A	1FTFW1ET6B	REINEKE LINCOLN, INC.	OH
DIAG - MISFIRE	N/A	1FTFW1ET0B	JOHN MEEGAN FORD, INC.	PA
DIAG - MISFIRE	N/A	1FTFW1ET2B	KEN STILLWELL FORD	MI
DIAG - MISFIRE	N/A	1FTFW1ET4B	ERIC VON SCHLEDORN FORD	WI

Primary Short
Primary Short
Primary Short
Driver Short
Driver Short

DIAG - MISFIRE	N/A	1FTFW1ETXBK	SAYVILLE FORD	NY
DIAG - MISFIRE	N/A	1FTFW1CT9BF	JOHNSON SEWELL FORD LINCOLN	TX
DIAG - MISFIRE	BEQBQ004	1FTFW1ET8BF	ASHE COUNTY FORD, INC.	NC
DIAG - MISFIRE	BETCA005	1FTFX1CT8BK	GARY CROSSLEY FORD, INC.	MO
DIAG - MISFIRE	BEXDD011	1FTFX1ET4BF	DARLING'S BANGOR FORD	ME
DIAG - MISFIRE	N/A	1FTFW1ET5BF	D.K. FORD SALES LTD.	AB
DIAG - MISFIRE	N/A	1FTFW1ET2BF	COTRAC FORD LINCOLN SALES INC.	ON
DIAG - MISFIRE	N/A	1FTFW1ET1BF	JOE HALL FORD LINCOLN MERCURY	ID
DIAG - MISFIRE	BEP2001	1FTFW1ET2BK	GAYLORD FORD LINC-MERC, INC.	MI
DIAG - MISFIRE	N/A	1FTFW1ET6BF	SUNRISE FORD SALES LTD	BC
DIAG - MISFIRE	N/A	1FTFW1ET9BF	MAX PLATT FORD-LINCOLN, INC.	IN
CATALYTIC CONVERTER	BCHDP012	1FTFW1ET4BF	HAAG FORD SALES, INC.	IN
CATALYTIC CONVERTER	BDEBG011	1FTFW1ET2BF	CAPITAL FORD, INC.	NC
CATALYTIC CONVERTER	N/A	1FTFW1ETXBF	JEDDELOH, INC.	IA
CATALYTIC CONVERTER	N/A	1FTFW1ET5BF	CAPITAL FORD, INC.	NC
CATALYTIC CONVERTER	BDIAD012	1FTFW1ET9BF	BILLINGSLEY FORD LINCOLN MERCU	OK
CATALYTIC CONVERTER	BDLBS007	1FTFW1ET5BF	MIDDLEKAUFF FORD LINCOLN	ID
CATALYTIC CONVERTER	BDSAW011	1FTFW1ETXBF	JACQUES OLIVIER FORD INC.	QC
CATALYTIC CONVERTER	BDZCX005	1FTFW1CTXBF	HOLLINGSWORTH RICHARDS FORD	LA
CATALYTIC CONVERTER	N/A	1FTFW1ET9BF	RUXER FORD LINCOLN, INC.	IN
CATALYTIC CONVERTER	N/A	1FTFW1ET2BF	OAKRIDGE FORD SALES (1981) LTD	ON
CATALYTIC CONVERTER	N/A	1FTFW1ET7BF	A&B FORD SALES LTD	ON
CATALYTIC CONVERTER	BEBA3046	1FTFW1ET2BF	SIOUX FALLS FORD LINCOLN MERCU	SD
CATALYTIC CONVERTER	BECBN005	1FTFW1ET8BF	BARIL FORD LINCOLN INC.	QC
CATALYTIC CONVERTER	BEDCG011	1FTFW1ET9BF	BOB SWOPE FORD, INC.	KY
CATALYTIC CONVERTER	BDZCM016	1FTFX1ET0BF	EXPRESSWAY FORD	IN
CATALYTIC CONVERTER	N/A	1FTFW1ET1BF	BOB HURLEY FORD	OK
CATALYTIC CONVERTER	N/A	1FTFW1ETXBF	NORTHWAY FORD LINCOLN LTD.	ON
CATALYTIC CONVERTER	BCVCS014	1FTFW1ET0BF	MONTGOMERY FORD SALES LIMITED	ON
CATALYTIC CONVERTER	BETDJ009	1FTFX1ET1BF	TUBBS & SONS FORD SALES, INC.	KS
CATALYTIC CONVERTER	BD2CP010	1FTFW1ET5BF	D-PATRICK, INC.	IN
CATALYTIC CONVERTER	BC2DW002	1FTFW1ET1BF	ELKINS FORDLAND	WV
CATALYTIC CONVERTER	N/A	1FTFW1ET3BF	MIKE MURPHY FORD INC	IL
CATALYTIC CONVERTER	BETCA010	1FTFW1ET9BF	WATERTOWN FORD	SD
CATALYTIC CONVERTER	N/A	1FTFW1ET0BF	MILNES FORD, INC.	MI

From: Ricks, Kevin (K.J.)
Sent: Thursday, February 14, 2013 7:58 AM
To: Dobbs, Dan (K.D.); Nowaczyk, Rick (R.J.)
Subject: data CAC

Dan, you had some preliminary findings from the data. Large orders from Canada, etc. What is the current status of the data findings? I guess no meeting yesterday. Maybe we should see who the top ordering dealers? I wonder which % are ordered emergency or unit down.

Kevin Ricks

Manager - Truck Service Engineering
FCSD - Service Engineering Operations
KRICKS@Ford.com
313-323-6574

From: Osepchook, William (W.R.)
Sent: Thursday, January 26, 2012 6:55 AM
To: Cockerill, Al (C.A.)
Subject: EcoBoost In The Rain

Importance: High

Interesting.....Appears the steam is coming off the CAC.

<http://www.f150forum.com/f70/ecoboost-engine-steams-rain-90407/>



FORUMS

PHOTOS

MEMBERS

TECH TOOLS

MARKETPLACE



Search...

Search

Ford F150 Forum - Community of Ford Truck Fans
> Late Model F150s > 2009 - Present Ford F150 >
2011+ Engines

Sign in using an external account

User Name

Password

Ecoboost engine steams in the rain?

[Register](#)

[Register](#)

[Garage](#)

[Photos](#)

[FAQ](#)


[Community](#)

[Calendar](#)

[Today's Posts](#)

[Search](#)

[Store](#)



Welcome to F150 Forum!



Welcome to **F150 Forum**,

You are currently viewing our limited access to view most of our features. By joining our community you will have full access to post topics, communicate privately with other members (PM), respond to polls, upload your own photos and access special features. Registration is quick and easy. [Join our community today](#)

POST REPLY

Like

0

Send

0

Tweet

0



Thread Tools

04-11-2011, 05:54 PM

Ecoboost engine steams in the rain?

Junior Member

Join Date: Mar 2011
Posts: 14
Mentioned: 0
Post(s)
Thanks: 0
Thanked 0
Times in 0
Posts
[Feedback](#)
Score: 0
reviews

Just trying to find out if this is a common problem or isolated incident or two.....apparently are reporting significant amounts of steam coming from their engines when it rains pedestrians have thought their trucks were on fire.....just ordered my EB a coupe be cool and may be a deal breaker for my Pacific Northwest climate.....anyone? If issue.....

You Tube



OFF

04-11-2011, 06:18 PM

[Redacted]
Sr NCO



Join Date: Feb 2011
Location: The Woodlands, TX
Posts: 225
Mentioned: 0 Post(s)
Thanks: 1
Thanked 1 Time in 1 Post
Feedback Score: 0 reviews

OFF



When hot things get wet, they will steam in the cold. I don't see the i and when they are not running they are not pulling the air through th somewhere.

I just don't see the issue.....

04-11-2011, 07:44 PM

[Redacted]
Senior Member

Join Date: Mar 2011
Posts: 465
Mentioned: 0 Post(s)
Thanks: 0
Thanked 2 Times in 2 Posts
Feedback Score: 0 reviews

OFF



Quote:

Originally Posted by [Redacted]
When hot things get wet, they will steam in the cold. I don't see i electric fans and when they are not running they are not pulling t steam has to go somewhere.

I just don't see the issue.....

I have electric fans and my truck does not do that.....

04-11-2011, 07:48 PM

[Redacted]
Senior Member

Join Date: Feb 2011
Location: Superior, WI
Posts: 685
Mentioned: 0 Post(s)
Thanks: 0
Thanked 9 Times in 5 Posts
Feedback Score: 0 reviews



I've been following and trying to figure it out on the other forum - It trucks without skid plates. Mine has skid plates, and will steam just like in the video - if the CAC way that sprays water directly through the front, but never in normal puddle.

No one answered my question on the other site on if non-skid plate e from the front of the CAC to the front of the skid plate under the engi keeping the water out of mine

OFF

04-11-2011, 08:12 PM

Junior Member

Join Date: Mar 2011
 Posts: 14
 Mentioned: 0 Post(s)
 Thanks: 0
 Thanked 0 Times in 0 Posts
 Feedback Score: 0 reviews

OFF



Hopefully that's the case as I ordered mine with skid plates.....not but for the occasional [hunting trip](#) the extra protection at a low cost is hitting face on whether the "bug screen" that I usually put on my truck would prevent this also.....surely there must be an easy fix.....

04-11-2011, 09:17 PM

Senior Member

Join Date: Mar 2011
 Posts: 696
 Mentioned: 0 Post(s)
 Thanks: 0
 Thanked 2 Times in 2 Posts
 Feedback Score: 0 reviews

OFF



Do the ones with the steam have a lower grill in place of the open space

As stated above, every engine gets stinking hot, and if it gets water on it while driving through heavy rain or behind someone throwing water up in the lower section, could be water getting into the compartment through the grill

My theory is through elimination.....water gets into engine compartment on other engines that don't do this except for one thing, they have an open grill. It must be the one thing that is different.... let's see if [logic works](#) :P

Last edited by [REDACTED] 04-11-2011 at 09:25 PM. Reason: corrected spelling I notice

04-11-2011, 10:21 PM

Senior Member

Join Date: Feb 2011
 Location: Superior, WI
 Posts: 685
 Mentioned: 0 Post(s)
 Thanks: 0
 Thanked 9 Times in 5 Posts
 Feedback Score: 0 reviews

OFF



No it really seems to be the skid plates keeping the water out - mine has skid plates and has never steamed in normal use

The thing that's steaming appears to be the charge air cooler, which is behind the radiators

04-11-2011, 10:28 PM

Senior Member

Join Date: Mar 2011
 Posts: 696
 Mentioned: 0 Post(s)
 Thanks: 0



Quote:

Originally Posted by [REDACTED] [↩](#)
No it really seems to be the skid plates keeping the water out - mine has skid plates and has never steamed in normal use

Thanked 2 Times in 2 Posts
Feedback Score: 0 reviews

*The thing that's steaming appears to be the charge air cooler, wh
other radiators*

But that would mean that all the other engines, that dont steam, corr
As far as it coming from the coolers, that reenforces my theory

OFF

04-11-2011, 10:57 PM



Got Boost?



Join Date: Mar 2011
Posts: 36
Mentioned: 0 Post(s)
Thanks: 0
Thanked 0 Times in 0 Posts
Feedback Score: 0 reviews

OFF



This happens with my FST snowmobiles after a long run at idle the hc
inter-cooler and when water hits it there is much steam generated.

I have not had it happen with my EB but could certainly see it happer

If it bothers you keep moving forward 🙄



2011 Black F150 FX4 SuperCrew EcoBoost w/FX Luxur
System. MODS: BFG AT T/A KO's, OEM Hood Protector, Carriage Wor
w/powerlock, Pop & Lock pwr lock, EZ Down, Bedrug, Steel Works All

04-12-2011, 12:41 AM



Senior Member

Join Date: Feb 2011
Location: SO.CA.
Posts: 163
Mentioned: 0 Post(s)
Thanks: 0
Thanked 1 Time in 1 Post
Feedback Score: 0 reviews

OFF



My guess is water getting on the intercooler and causing the steam. I

04-12-2011, 12:41 AM





This Page Cannot Be Displayed

Based on your corporate access policies, this web site

([REDACTED] 2Fecoboost-engine-steams-rain-90407%2F&r=&view=) has been blocked because it has been determined by Web Reputation Filters to be a security threat to your computer or the corporate network. This web site has been associated with malware/spyware.

Threat Type: adware
Threat Reason: Domain reported and verified

Like 0 Send

0 Tweet 0



POST REPLY



« [Previous Thread](#) | [Next Thread](#) »

Posting Rules

- You **may not** post new threads
- You **may not** post replies
- You **may not** post attachments
- You **may not** edit your posts

- [BB code](#) is **On**
- [Smilies](#) are **On**
- [\[IMG\]](#) code is **On**
- HTML code is **Off**
- [Trackbacks](#) are **Off**
- [Pingbacks](#) are **Off**
- [Refbacs](#) are **Off**

[Forum Rules](#)

Similar Threads

Thread	Thread Starter	Forum
Ecoboost engine	mtamor1	2009 - Present Ford F150
Engine quites when driving in rain	RR2115	2004 - 2008 Ford F150
I have engine problems in the rain. Any suggestions?	fordalltheyway	2004 - 2008 Ford F150
Windshield steams up - bad heater core?	FirstFordTruck	1997 - 2003 Ford F150

Similar Threads

[A lot of rain now engine misfiring](#)

andrewk

2004 - 2008 Ford F150



5 Cheap Ways to get Better Mileage



F-150 Mistakes 458 Italia for Boulder; Rolls Over it Anyway



EcoBoost Blowup: The Sad Tale Of GhostintheMach(F-150 Ecoboost



Hottest Celebrity Beach Bodies (People.com)



5 Really, Really Fast Ford F-150s

Recommended by

All times are GMT -4. The time now is 03:00 PM.

-- F150Forum.com - New Header

[Advertise](#) - [Contact Us](#) - [Ford F150 Forum](#) - [Terms of Service](#) -

Powered by vBulletin® Version 3.8.7
Copyright ©2000 - 2013, vBulletin Solutions, Inc.
SEO by [vBSEO](#) 3.5.2

Copyright © 2006 - 2011 F150forum.com

This site is in no way affiliated with the Ford Motor Company.

Our Network: [Ford F150 Forum](#) | [Jeep Cherokee Forum](#)

Garage Plus [vBulletin Plugins](#) by Drive Thru Online, Inc.



Kramer, Michael (M.T.)

From: Ng, Paul (P.K.)
Sent: Monday, July 23, 2012 4:25 PM
To: Nowaczyk, Rick (R.J.); McDonagh, Scot (S.M.)
Cc: Dixon, Mark (M.R.); Kramer, Michael (M.T.); Steslicki, Michael (M.E.)
Subject: RE: 2012 F-150 3.5l GTDI Continued aft Misfire TSB (CQIS Report#CGJCV013)
Attachments: TSB 12-6-4.xls

Mr. Nowaczyk,

The breakdown of the 580 TSB 12-6-4 claims:

- P0299 only 15
- P0430 only 88
- Misfire only 112
- Other DTCs than Above 11
- Combinations of the Above 17
- No DTC 337
- Total 580



Paul K. Ng
Ford Motor Company
Powertrain Engineering
313-805-5766
png@ford.com

From: Nowaczyk, Rick (R.J.)
Sent: Thursday, July 19, 2012 1:17 PM
To: Ng, Paul (P.K.); McDonagh, Scot (S.M.)
Cc: Dixon, Mark (M.R.); Kramer, Michael (M.T.); Steslicki, Michael (M.E.)
Subject: RE: 2012 F-150 3.5l GTDI Continued aft Misfire TSB (CQIS Report#CGJCV013)

The only thing is this TSB doesn't address just the misfire issue. The TSB also address another failure mode for the surge at cruise, which is not part of the water ingestion concern from the CAC. Of the 580 VIN's how many were for misfire and/or P0430/P0299 only? I don't think it's a clean 90% effectiveness calculation.

From: Ng, Paul (P.K.)
Sent: Thursday, July 19, 2012 11:44 AM
To: McDonagh, Scot (S.M.)
Cc: Dixon, Mark (M.R.); Kramer, Michael (M.T.); Steslicki, Michael (M.E.); Nowaczyk, Rick (R.J.)
Subject: RE: 2012 F-150 3.5l GTDI Continued aft Misfire TSB (CQIS Report#CGJCV013)

Scot,

There are 580 VINs as of yesterday that have went through TSB 12-6-4. 57 of the VINs have subsequent repairs to fix similar symptoms (CCCs and/or DTCs). The calculated effective for the TSB is 90% provided that the repeat repairs were valid.

Paul

From: McDonagh, Scot (S.M.)
Sent: Wednesday, July 18, 2012 12:56 PM
To: Ng, Paul (P.K.)
Cc: Dixon, Mark (M.R.); Kramer, Michael (M.T.); Steslicki, Michael (M.E.); Nowaczyk, Rick (R.J.)
Subject: FW: 2012 F-150 3.5l GTDI Continued aft Misfire TSB (CQIS Report#CGJCV013)

How many AWS claims to date for TSB 12-06-04 ? Original estimate was 60% effective repair rate for CAC Deflector. Would like to know % based on TSB usage with 12 vehicles unresolved. Thanks

OPERATION	DESCRIPTION	TIME
120604A	2011-2012 F-150 3.5L GTDI: Check DTCs, Install CAC Air Deflector Plate if Necessary And Reprogram The PCM (Do Not Use With Any Other Labor Operations)	0.5 Hr.
120604B	2011-2012 F-150 3.5L GTDI: Check DTCs, Replace The Left Catalytic Converter, Install CAC Air Deflector Plate if Necessary And Reprogram The PCM (Do Not Use With Any Other Labor Operations)	1.0 Hr.

Scot G. McDonagh
PT Quality Engineering
Phone: (313)337-8091
smcdonag@ford.com

From: Nowaczyk, Rick (R.J.)
Sent: Wednesday, July 18, 2012 12:12 PM
To: McDonagh, Scot (S.M.)
Subject: RE: 2012 F-150 3.5l GTDI Continued aft Misfire TSB (CQIS Report#CGJCV013)

Looks like...
7 reports for vehicle built after the cutoff date
4-5 reports for vehicles still having the concern after the TSB was performed.
11-12 Total...

From: McDonagh, Scot (S.M.)
Sent: Wednesday, July 18, 2012 10:59 AM
To: Nowaczyk, Rick (R.J.)
Subject: RE: 2012 F-150 3.5l GTDI Continued aft Misfire TSB (CQIS Report#CGJCV013)

What is total count for vehicles not fixed with Deflector ?

Scot G. McDonagh
PT Quality Engineering
Phone: (313)337-8091
smcdonag@ford.com

From: Nowaczyk, Rick (R.J.)
Sent: Wednesday, July 18, 2012 10:20 AM
To: Madej, Jeanette (J.); McDonagh, Scot (S.M.); Kramer, Michael (M.T.); Ladd, John (J.R.); Sowards, John (J.)
Cc: Chatfield, David (D.); Ricks, Kevin (K.J.); Dobbs, Dan (K.D.); Oyafuso, Kevin (K.G.); Smith, Craig (C.A.); Dixon, Mark (M.R.); Sparks, Douglas (D.S.); Mazuchowski, James (J.A.); Nowaczyk, Rick (R.J.)
Subject: RE: 2012 F-150 3.5l GTDI Continued aft Misfire TSB (CQIS Report#CGJCV013)
Importance: High

Jeanette,
Any updates on this per your comment below?

From: Madej, Jeanette (J.)
Sent: Friday, July 13, 2012 2:57 PM
To: McDonagh, Scot (S.M.); Nowaczyk, Rick (R.J.); Kramer, Michael (M.T.); Ladd, John (J.R.); Sowards, John (J.)
Cc: Chatfield, David (D.); Ricks, Kevin (K.J.); Dobbs, Dan (K.D.); Oyafuso, Kevin (K.G.); Smith, Craig (C.A.); Dixon, Mark (M.R.); Sparks, Douglas (D.S.); Mazuchowski, James (J.A.)
Subject: RE: 2012 F-150 3.5l GTDI Continued aft Misfire TSB (CQIS Report#CGJCV013)

We will discuss on Monday and get back to you

From: McDonagh, Scot (S.M.)
Sent: Wednesday, July 11, 2012 7:53 AM
To: Nowaczyk, Rick (R.J.); Kramer, Michael (M.T.); Ladd, John (J.R.); Sowards, John (J.)
Cc: Chatfield, David (D.); Ricks, Kevin (K.J.); Dobbs, Dan (K.D.); Oyafuso, Kevin (K.G.); Smith, Craig (C.A.); Dixon, Mark (M.R.); Madej, Jeanette (J.); Sparks, Douglas (D.S.); Mazuchowski, James (J.A.)
Subject: RE: 2012 F-150 3.5l GTDI Continued aft Misfire TSB (CQIS Report#CGJCV013)

Thanks Rick- It is my understanding the Deflector is ICA for CAC condensate Misfire. Will ask PT Cooling for update on PCA Service proposals.

Scot G. McDonagh
PT Quality Engineering
Phone: (313)337-8091
smcdonag@ford.com

From: Nowaczyk, Rick (R.J.)
Sent: Tuesday, July 10, 2012 4:42 PM
To: McDonagh, Scot (S.M.); Oyafuso, Kevin (K.G.); Smith, Craig (C.A.); McDonagh, Scot (S.M.); Dixon, Mark (M.R.)
Cc: Chatfield, David (D.); Ricks, Kevin (K.J.); Dobbs, Dan (K.D.); Nowaczyk, Rick (R.J.)
Subject: 2012 F-150 3.5l GTDI Continued aft Misfire TSB (CQIS Report#CGJCV013)
Importance: High

Powertrain Team,
Here is another case were the dealer performed the TSB for the misfire and the customer still experienced the condition when raining. The issue in this case this customer appears to have purchased 13 trucks for their company. If this TSB is going to be the final fix, we may need to look at communication to the field that if condition are right this concern may still occur.

Thanks....

From: DCHATFIE@ford.com [mailto:DCHATFIE@ford.com]

Sent: Tuesday, July 10, 2012 4:05 PM

To: Nowaczyk, Rick (R.J.)

Cc: Chatfield, David (D.)

Subject: Report Summary for the CQIS Report#CGJCV013

2012 misfire under load, tsb performed. Location Memphis, Tn.

Attachments : 0

Report# :	CGJCV013 NHL	Received:	07/10/2012
CCRG/EPRC:		Date:	
Vehicle:	2012,F150 4X4 ,F150 ,SUP CRW,STYSD ,1FTFW1ET0CF [REDACTED]	Build Date:	01/21/2012
Odometer :	8,386 M	Engine:	3.5L-GTDI
Transmission:	6R80E	Axle:	3.73 LOCK
Dealer:	USA 06422 Butch Oustalet, Inc.	Calibration:	CF613C0A
City:	Gulfport	A/C:	YES
State:	Mississippi	Phone#:	(228) 863-5525
Country :	USA		
Originator:	BEN PRIESTER		
Symptom:	5 50 2 39 DRV PERF,RUNS ROUGH,ACCEL,INTERMITTENT		
Status:			
VFG:	V52 DRIVEABILITY		
Additional Symptom:	BUCKS AND JERKS WHEN RAINING		
Fix:	Causal Component :		
Condition Code:			

Hotliner: DCHATFIE

Phone: 313 317-6315

Regn Cd: C3 Memphis

Engineering:

Phone:

TAR:

Dlr Contact: BEN PRIESTER

Phone: 000 000-0000

Title Cde: OT

DTCs:

KOEO:

KOEC:

KOER:

Comments

:

REPAIR 07/10/2012 03:58PM DAVID CHATFIELD MSS - FCSD - TECH SVC HOTLINE
WEB FORM DATA - CONCERN:CUST WAS DRIVING HIS TRUCK IN THE RAIN AND
IT

STARTED BUCKING AND JERKING DIAGNOSTICS: RUN DIAGNOSIS NO CODES WE HAXE ALREADY DONE TSB 12-6-4 LAST REPAI PARTS REPLACED:NONE TECH QUESTION:THIS TRUCK CONTINUES TO HAVE PROBLEM WHEN DRIVING IN THE RAIN. HAVE HAD IN THE SHOP 3 TIMES BEFORE. DONT KNOW WERE TO GO WITH IT. THIS CUST OWN A COMPANY THAT BOUGHT 13 TRUCKS FROM US LAST YEAR AND I VE GOT TO FIND A SOLUTION. ARE THER ANY LATER UPDATES OR SUGGESTIONS FOR THIS

RECOMM 07/10/2012 03:58PM DAVID CHATFIELD MSS - FCSD - TECH SVC HOTLINE

BEN, DUE TO THE EFFICIENCY OF THE CHARGE AIR COOLER, THERE MAY BE SOME CONDITIONS WHERE SOME CONDENSATION BUILDS IN THE CAC, EVEN WITH

THE CAC SHIELD IN PLACE AND IS INJECTED INTO THE ENGINE. VERY WET OR EXTREMELY HUMID CONDITIONS MAY ENHANCE THIS CONCERN. THE SHIELD WAS

DESIGNED TO HELP WITH LESS CONDENSATION BUILD UP, BUT DUE TO HUMID CONDITIONS AND COMPRESSED AIR IN THE CAC, THIS WILL NOT TOTALLY ELIMINATE THE CONDENSATION FROM FORMING UNDER THESE CONDITIONS. AT THIS TIME, IF WATER HAS BEEN VERIFIED IN THE CAC, AIS AND AROUND THE THROTTLE BODY, CLEAN THE WATER AS BEST AS POSSIBLE AND INFORM THE CUSTOMER OF THE DESIGN OF THE SYSTEM AND THE POSSIBLY OF CONDENSATION

BUILD-UP UNDER THESE CONDITIONS.

From: Hepburn, Mitch (M.)
Sent: Friday, October 28, 2011 10:54 AM
To: Smith, Craig (C.A.)
Subject: RE: Emailing: CFA00017 10-27-11 PM .XML

Thanks Craig.

-----Original Message-----

From: Smith, Craig (C.A.)
Sent: Friday, October 28, 2011 10:16 AM
To: Tatro, James (J.E.); De Coste, Bill (W.J.); Hepburn, Mitch (M.); Garrett, David (D.P.); Whitehead, Joseph (J.P.); Nickerson, Kurt (K.H.)
Cc: Graham, Daniel (D.B.); Muntz, Nicole (N.); Sims, Ivan (I.D.); Cockerill, Al (C.A.); Mazuchowski, James (J.A.); Pierce, Michael (M.A.); Gernant, Tim (T.R.); Baskins, Robert (R.S.); Pierce, Michael (M.A.)
Subject: RE: Emailing: CFA00017 10-27-11 PM .XML

I interviewed the driver and he indicated the following:

- 1) Started shift at ~4pm.
- 2) Vehicle was warm at engine start
- 3) Idled for 10 minutes while waiting for lead driver
- 4) Drove ~1 mile from garage to I-94 entrance ramp
- 5) While accelerating onto I-94 entrance ramp @ approximately 40mph, vehicle exhibited loss of power and flashing MIL
- 6) Pulled to side of road and let vehicle idle while he called garage for further instructions
- 7) Misfire & flashing MIL cleared up while idling on the side of the road
- 8) Driver thinks he may have pressed the VDR trigger while at side of the road (can't locate the file?)
- 9) Resumed route with no further incidents throughout the rest of his shift.

Based upon this description, the drivability symptoms and PCM codes are consistent with the bank 2 misfire issue that's currently being investigated by the team.

Thanks,
Craig Smith
Supervisor - Engine Calibration
3.5L TIVCT GTDI & 3.5L IVCT GTDI Powerpacks
Phone: (313) 805-6345
TEE Bldg cube 1AD08

-----Original Message-----

From: Tatro, James (J.E.)
Sent: Friday, October 28, 2011 9:56 AM

To: Smith, Craig (C.A.); De Coste, Bill (W.J.); Hepburn, Mitch (M.); Garrett, David (D.P.); Whitehead, Joseph (J.P.); Nickerson, Kurt (K.H.)
Cc: Graham, Daniel (D.B.); Muntz, Nicole (N.); Sims, Ivan (I.D.); Cockerill, Al (C.A.); Mazuchowski, James (J.A.); Pierce, Michael (M.A.); Gernant, Tim (T.R.); Baskins, Robert (R.S.); Graham, Daniel (D.B.)
Subject: RE: Emailing: CFA00017 10-27-11 PM .XML

Craig, drivers name is [REDACTED] his number is [REDACTED]

>James Tatro
>VoCF Vehicle Coordinator
>C346 2012, D47X 2012, U22X 2012
>VoCF Matrix Manager P415 2012
>734-679-9183
>jtatro@ford.com
>

-----Original Message-----

From: Smith, Craig (C.A.)
Sent: Friday, October 28, 2011 9:51 AM
To: De Coste, Bill (W.J.); Hepburn, Mitch (M.); Garrett, David (D.P.); Whitehead, Joseph (J.P.); Tatro, James (J.E.); Nickerson, Kurt (K.H.)
Cc: Graham, Daniel (D.B.); Muntz, Nicole (N.); Sims, Ivan (I.D.); Cockerill, Al (C.A.); Mazuchowski, James (J.A.); Pierce, Michael (M.A.); Gernant, Tim (T.R.); Baskins, Robert (R.S.)
Subject: RE: Emailing: CFA00017 10-27-11 PM .XML

We reviewed the VDR file that was associated with these misfire codes on CFA00017.

Unfortunately, the VDR data that we found didn't show us anything. My guess is that the file was generated during a restart, immediately after the event that generated the codes. We didn't see any other pertinent file on the Qualifier web site for this vehicle.

See attached email that includes a screen capture of the VDR data. Note the no misfires (totnummis = 0) were present.

Can we interview the driver to understand what drivability symptoms were exhibited?

Per my prior note, this vehicle did have a history of misfire soft failures prior to R08 being installed.

Tim,

Do you see any other data on the Qualifier website for this vehicle that we may have missed?

Thanks,
Craig Smith
Supervisor - Engine Calibration
3.5L TIVCT GTDI & 3.5L IVCT GTDI Powerpacks
Phone: (313) 805-6345
TEE Bldg cube 1AD08

-----Original Message-----

From: De Coste, Bill (W.J.)
Sent: Friday, October 28, 2011 7:22 AM
To: Hepburn, Mitch (M.); Garrett, David (D.P.); Whitehead, Joseph (J.P.); Smith, Craig (C.A.); Tatro, James (J.E.); Nickerson, Kurt (K.H.)
Cc: Graham, Daniel (D.B.); Muntz, Nicole (N.)
Subject: RE: Emailing: CFA00017 10-27-11 PM .XML

Get the 3.5L misfire guys over to Livonia this morning to look at the truck.

-----Original Message-----

From: Hepburn, Mitch (M.)
Sent: Friday, October 28, 2011 7:20 AM
To: De Coste, Bill (W.J.); Garrett, David (D.P.); Whitehead, Joseph (J.P.); Smith, Craig (C.A.); Tatro, James (J.E.); Nickerson, Kurt (K.H.)
Cc: Graham, Daniel (D.B.); Muntz, Nicole (N.)
Subject: FW: Emailing: CFA00017 10-27-11 PM .XML

Bill, UNIT CFA00017 Codes show Misfires detected from drive last night, This is the unit Kurt picked up this morning and it is at Livonia having trans. Swapped picked up at 5.30am by Kurt, Need next steps on this unit. Thanks Mitch

Codes attached.

-----Original Message-----

From: Ross, Timothy (T.G.)
Sent: Friday, October 28, 2011 7:08 AM
To: Hepburn, Mitch (M.); Tatro, James (J.E.)
Subject: Emailing: CFA00017 10-27-11 PM .XML

The message is ready to be sent with the following file or link attachments:

CFA00017 10-27-11 PM .XML

Note: To protect against computer viruses, e-mail programs may prevent sending or receiving certain types of file attachments. Check your e-mail security settings to determine how attachments are handled.

Emissions Defect Information Report (EDIR)

* = required field

Report / Manufacturer Information

New EDIR Correct / Update EDIR *

Manufacturers must submit EDIRs within 15 working days after an emission-related defect is found.

EPA EDIR Number *

Manufacturer EDIR Number *

Form Version Number *

Additional email address

Defect Information

Problem category *
 Oxygen Sensor
 Secondary Air System
 Selective Catalytic Reduction System
Turbocharger/Supercharger

Defect description *
 Some 2011 through 2013 model year F150 Trucks with 3.5L engines may experience driveability concerns related to condensation accumulated in the charge air cooler. Vehicles operated in high humidity conditions may have water condensation build up in the charge air cooler. This water can be ingested by the engine and result in temporary misfire and/or slow burn conditions.

Defect identification source / method *
 (CTRL + Click to select multiple value(s))
 Investigation based on warranty claims
 In-Use Testing (According to CAP 2000)
Investigation based on customer feedback
 Manufacturer Internal Testing
 Manufacturer Technical/Data Analysis

Address(es) of plants *
 Dearborn Truck Plant
 3001 Miller Road
 Dearborn, MI 48121
 Kansas City Assembly Plant
 U.S. Highway #69
 Claycomo, MO 64199

Evaluation of the emissions impact when the vehicle / engine exhibits the defect *
 If an affected vehicle experiences misfire conditions, the Failure Mode Effects Management (FMEM) system will disable fuel injectors on up to two cylinders and limit the air/fuel ratio to a constant value. This FMEM will only remain active while misfire conditions are detected. It is estimated that exhaust emissions may be affected while the misfire FMEM system is active.

Are there any available emissions data that relates to the defect? * Yes No

Emissions Defect Information Report (EDIR)

* = required field

Does the defect cause or result in On-Board Diagnostic Malfunction Indicator Lamp illumination? * Yes No

Describe any drivability problems which a defective vehicle/engine would exhibit *

Customers driving affected vehicles will experience rough and noisy operating conditions.

Description of anticipated manufacturer follow up *

In February, 2012 Ford put a revised misfire monitor calibration into production. This calibration was designed to mitigate misfire induced catalyst damage. In September, 2012 Ford implemented a revised charge air cooler, including an external shield, to minimize condensation build up in high humidity conditions. Technical Service Bulletins (12-2-10, 12-6-4, 12-10-19 and 12-11-15) were issued to help technicians diagnose and correct the condition. No further follow

Type of related documents to be submitted to the Verify Document Module * (CTRL + Click to select multiple value(s))

No Related Documents to Submit
Available Emissions Data
Repair Instructions
Technical Service Bulletin
Other (Specify in 'Notes' field)

Number of related documents to be submitted to Verify Document Module *

0

Notes

-Estimated values for Production Volumes and Vehicles Identified are based on Ford production and aggregate service data.

-Ford does not, by filing this report, make a determination of an emissions defect subject to Sections 207 of the Clean Air Act (42 U.S.C. § 7541), as amended, or Section 43204 of the California Health and Safety Code, or a safety defect subject to 49 U.S.C. § 30118.

Validate Form

* = required field

**Emissions Defect Information Report (EDIR)
Affected Vehicles / Engines Description**

Add Test Group / Engine Family

Test Group / Engine Family Information				Delete Test Group / Engine Family
Test Group / Engine Family *	Certified Sales Area *	Total Production Volume Count *	Potential Number Affected *	Actual Number Identified *
BFMXT03.54EP	50-State (CA+177 States+FED)	26,982	26,982	459
Add Vehicle / Engine				
Vehicle / Engine Information				
Make *	Model / Calibration *	Model Year *	Displacement (Liters) *	
Ford	F150	2011	3.5	Delete This Vehicle / Engine

Test Group / Engine Family Information				Delete Test Group / Engine Family
Test Group / Engine Family *	Certified Sales Area *	Total Production Volume Count *	Potential Number Affected *	Actual Number Identified *
CFMXT03.54EP	50-State (CA+177 States+FED)	31,692	31,692	539
Add Vehicle / Engine				
Vehicle / Engine Information				
Make *	Model / Calibration *	Model Year *	Displacement (Liters) *	
Ford	F150	2012	3.5	Delete This Vehicle / Engine

Test Group / Engine Family Information				Delete Test Group / Engine Family
Test Group / Engine Family *	Certified Sales Area *	Total Production Volume Count *	Potential Number Affected *	Actual Number Identified *
CFMXT03.54DX	50-State (CA+177 States+FED)	108,358	108,358	1,842
Add Vehicle / Engine				
Vehicle / Engine Information				
Make *	Model / Calibration *	Model Year *	Displacement (Liters) *	
Ford	F150	2012	3.5	Delete This Vehicle / Engine

* = required field

Emissions Defect Information Report (EDIR) Affected Vehicles / Engines Description

Validate Form

Add Test Group / Engine Family

Test Group / Engine Family Information				Delete Test Group / Engine Family
Test Group / Engine Family *	Certified Sales Area *	Total Production Volume Count *	Potential Number Affected *	Actual Number Identified *
DFMXT03.54DX	50-State (CA+177 States+FED)	11,335	11,335	193
Vehicle / Engine Information				
Make *	Model / Calibration *	Model Year *	Displacement (Liters) *	Delete This Vehicle / Engine
Ford	F150	2013	3.5	

**Emissions Defect Information Report (EDIR)
Help Section****General****Validate Form Button**

Clicking this button will check to see if the form is valid and identify any form errors for correction. Failure to submit a valid form means you have not met reporting requirements and the system will reject the form.

Report Information**New EDIR or Correct / Update EDIR**

If you are submitting this EDIR for the first time, you should select "New EDIR". If you are updating or correcting a previously submitted EDIR, you should select "Correct / Update EDIR". If you select "Correct / Update EDIR", you must enter the number of the original EDIR that you are correcting / updating and the reason that you are correcting or updating the EDIR.

EPA EDIR Number

You must enter a number for the EDIR. If you are submitting a new EDIR, the number should be exactly four digits and must contain zeroes for numbers with fewer than four significant digits (e.g., "0007"). If you are submitting a corrected / updated EDIR, you must enter a two-digit revision number (e.g., "04").

Manufacturer EDIR Number

You may enter information, up to 20 characters into this field, it is designed to allow manufacturers to internally track their defect reports. If you are using your own internal number for EDIR Purposes, you may enter it here. Otherwise, enter the EPA EDIR number here.

Form version number

You must enter a two digit form version number. If you are submitting a corrected or updated EDIR, increment the number of the previous submitted EDIR. The number should be exactly 2 digits and must contain zeroes for numbers with fewer than two significant digits (e.g., "01").

Reason for correction / update

If you selected "Correct/Update EDIR", you must enter the reason that you are correcting or updating the EDIR. If you are submitting the EDIR for the first time, you should select "New EDIR". (4000 Character Limit)

Additional email address

You may enter an additional e-mail that can be used in notifications or communications concerning this report. The primary e-mail used for notifications or communications will be the one provided during the Verify registration process.

Problem category

Even if there are multiple problems identified in the EDIR, you must select only one category identifying the primary problem. For example, if an exhaust gas recirculation (EGR) valve problem is defective and, subsequently, an On-Board Diagnostic (OBD) malfunction indicator lamp (MIL) is illuminated for an EGR fault, the problem category should identify the EGR components as defective, not the OBD system. In contrast, if an OBD MIL is being erroneously illuminated for EGR valves that are not defective and the OBD programming is being corrected, then the problem category should identify the OBD system as defective.

Defect description

Clearly identify the device, system, assembly or software that has the defect, what the defect is, and to the extent known at the time, the cause of the defect. (4000 Character Limit)

Emissions Defect Information Report (EDIR) Help Section

Defect identification source / method

Select one or more sources/methods from this list used to determine that a defect(s) was present in the class/category of vehicles/engines in the EDIR.

Address of plants

Enter the address of the plant(s) at which the defective vehicles or engines were produced. (4000 Character Limit)

Evaluation of the emissions impact when the vehicle / engine exhibits the defect

Describe any emissions impact when the defect(s) is present and how the emissions impact was evaluated(e.g., emissions testing, or engineering analysis). (4000 Character Limit)

Are there any available emissions data that relates to the defect?

This field is used to indicate whether or not emissions data related the defect is available. If you select "Yes", you should also send any supporting documentation to the Verify Document Module along with the EDIR.

Does the defect cause or result in On-Board Diagnostic Malfunction Indicator Lamp illumination?

This field is used to indicate whether or not the defect(s) identified in the EDIR causes or results in illumination of the On-Board Diagnostic (OBD) Malfunction Indicator Lamp (MIL).

Describe any drivability problems which a defective vehicle/engine would exhibit

Describe any drivability problems that a vehicle or engine might exhibit or an owner might experience when the defect is present on the vehicle/engine. (4000 Character Limit)

Description of anticipated manufacturer follow up

Describe any follow-up that you anticipate will be performed to rectify/correct the defect indicated in the EDIR. (4000 Character Limit)

Type of related documents to be submitted to the Verify Document Module

If you are submitting documents related or supporting the EDIR to the Verify Document Module, you can use this list to identify one or more of these documents that you are submitting. If you are submitting documents containing confidential business information (CBI) you should select "Other (Specify in 'Notes' field)" and indicate in the "Notes" field that a CBI document is being submitted separately (e.g., "CBI attached in separate document.").

Number of related documents to be submitted to Verify Document Module

Enter the number of documents you will be submitting to the Verify Document Module. Since some documents may be combined, it is helpful to know how many related documents that accompany an EDIR should be retrieved from the Verify Document Module.

Notes

Use this field to enter any notes and/or comments. In addition, there are particular fields that require you to enter notes when certain options are selected and this field should be used for this that purpose. (4000 Character Limit)

**Emissions Defect Information Report (EDIR)
Help Section****Affected Vehicles / Engines Description****Test Group / Engine Family**

Enter the test group or engine family of the affected vehicle(s) or engine(s). [Example: 9EPAX04.23A1]

Certified Sales Area

Select the appropriate certified sales area for the applicable test group or engine family. For vehicles that were certified to exhaust emission standards for California and Section 177 states, select the "CA+177 States" option. For vehicles that were certified to exhaust emission standards for states other than California and Section 177 states, select the "FED" option. For vehicles that were certified to exhaust emission standards for California and Section 177 states and states other than California and Section 177 states, select the "50-State" option.

Total Production Volume Count

Enter the total production volume of the test group or engine family. If this test group/engine family is still in production, enter the total production volume to date. However, this number should be updated with the final production volume when it is available. If this test group or engine family production has been completed, enter the final production volume.

Potential Number Affected

Enter the number of vehicles or engines produced that may have the defect described in the EDIR. This number may be different than the total production volume count only if a subset of the total production volume is potentially affected. Conversely, this number may be the same if all of the total production volume is potentially affected.

Actual Number Identified

Enter the actual number of defects described in the EDIR on the affected vehicles or engines. This number may be different than the potential number affected only if a subset of the vehicles or engines have exhibited the defect or it has been determined that they will exhibit the defect described in the EDIR. Conversely, this number may be the same as the potential number affected if all of the vehicles or engines have exhibited the defect or it has been determined that they will exhibit the defect described in the EDIR.

Make

Enter the specific make (i.e., name plate) for the affected vehicle(s) or engine(s). [Example: Buick, Lexus, Mercury]

Model / Calibration

Enter the model or calibration name that the manufacturer has designated for the vehicle or the calibration for the engine that is identified in the defect report.

Model Year

Enter the model year of the affected vehicle(s) or engine(s). [Example: 2001]

Displacement (liters)

Enter the engine displacement for the affected vehicle(s) or engine(s) in liters. [Example: 4.23] Note: The displacement will be shown without trailing zeroes. However, they will be captured when uploaded (e.g., 4.0 will be displayed as 4 on the form, but will be uploaded as 4.00).

Emissions Defect Information Report (EDIR)
Help Section**Vehicle Information Page Buttons**

Add Test Group / Engine Family - This button is used if a report covers multiple Test Groups / Engine Families. Clicking this button creates additional Test Group / Engine Family tables at the end of the "Affected Vehicles / Engines Description" section. Each additional Test Group / Engine Family table will have a row to add Vehicle / Engine Information. Additional rows can be added if this Test Group / Engine Family covers multiple Vehicles / Engines (see instructions below for adding rows to the Vehicle / Engine Information section).

Delete Test Group / Engine Family - This button is used for deleting a Test Group / Engine Family Table. Clicking this button in a Test Group / Engine Family table will delete that Test Group / Engine Family table, and all associated Vehicle/Engine Information, only.

Add Vehicle / Engine - This button is used if a Test Group / Engine Family covers multiple Vehicles / Engines. Clicking this button in a Test Group / Engine Family table will add a new row to the bottom of the Vehicle / Engine Information section in that Test Group / Engine Family table only.

Delete Vehicle / Engine - This button is used for deleting a specific row of Vehicle / Engine Information in a Test Group / Engine Family table. Clicking the button at the end of a row will delete the a Vehicle / Engine information for just that row.

From: Wilson, Marie (M.)
Sent: Monday, November 12, 2012 3:51 PM
To: Sparks, Douglas (D.S.); Cockerill, Al (C.A.); Dixon, Mark (M.R.); Kramer, Michael (M.T.); Madej, Jeanette (J.); Harrison, Michael (M.J.); Smith, Craig (C.A.); Dixon, Mark (M.R.); Ronzi, Bill (W.C.)
Cc: McClenaghan, Dave (D.); Oswalt, Greg (G.G.)
Subject: RE: Emission Problem Review Committee Fact Sheet Request - 11EPRC20 - 2011 F150 3.5L Charge Air Cooler

Mike K. will you have an PERC fact sheet for meeting review on 11-15? Please advise.



Marie Wilson
Ford Motor Company
Vehicle Environmental Engineering
Homologation & Compliance
Phone: 313-248-2404 MWILSO18@FORD.COM

From: Sparks, Douglas (D.S.)
Sent: Monday, October 29, 2012 1:39 PM
To: Wilson, Marie (M.); Cockerill, Al (C.A.); Dixon, Mark (M.R.); Kramer, Michael (M.T.); Madej, Jeanette (J.); Harrison, Michael (M.J.); Smith, Craig (C.A.); Dixon, Mark (M.R.); Ronzi, Bill (W.C.)
Subject: RE: Emission Problem Review Committee Fact Sheet Request - 11EPRC20 - 2011 F150 3.5L Charge Air Cooler

Marie,
The CAC D&R is Mike Kramer. However, after quickly reviewing the Fact Sheet it appears the Calibration Team will need to help complete this document.

Mazen/Craig,
Please work with Mike Kramer and help populate the EPRC fact Sheet.

Mark/Bill,
Please ensure Mike has the correct warranty data for this document.

Thank you,

Douglas S. Sparks
P/T Quality and PVT Manager FNA
P/T Integration and Program Management (PTIM)
dsparks3@ford.com 313-805-6096

Administrative Assistant: Tina Tessadri
tessadr 313 594-1115

From: Wilson, Marie (M.)
Sent: Monday, October 29, 2012 12:53 PM
To: Cockerill, Al (C.A.); Sparks, Douglas (D.S.); Dixon, Mark (M.R.)
Subject: RE: Emission Problem Review Committee Fact Sheet Request - 11EPRC20 - 2011 F150 3.5L Charge Air Cooler

Who owns D&R for the CAC?

Marie Wilson
Ford Motor Company
Vehicle Environmental Engineering
Homologation & Compliance
Phone: 313-248-2404 MWILSON18@FORD.COM

From: Cockerill, Al (C.A.)
Sent: Monday, October 29, 2012 11:57 AM
To: Sparks, Douglas (D.S.); Dixon, Mark (M.R.)
Cc: Wilson, Marie (M.)
Subject: FW: Emission Problem Review Committee Fact Sheet Request - 11EPRC20 - 2011 F150 3.5L Charge Air Cooler

Doug, Mark,
Attached is the form that Marie is referring to. I do not feel that I am the correct person to be completing this.
How do suggest we handle this?
<< File: FAF03-170-1.doc >>

The spirit, the will to win, and the will to excel are the things that endure. These qualities are so much more important than the events that occur. The harder you work, the harder it is to surrender.
Vince Lombardi

Al Cockerill
RWD V6 Engine System Supervisor
313-805-2333 C
313-843-0475 O

From: Wilson, Marie (M.)
Sent: Monday, October 15, 2012 1:58 PM
To: Cockerill, Al (C.A.); Smith, Craig (C.A.)
Cc: Mazuchowski, James (J.A.); Oberski, Christopher (C.); Oswald, Greg (G.G.); McClenaghan, Dave (D.)
Subject: Emission Problem Review Committee Fact Sheet Request - 11EPRC20 - 2011 F150 3.5L Charge Air Cooler

Al, per our discussions (and attached e-mail), please prepare an EPRC fact sheet for the subject concern.
<< Message: RE: Charge Air Cooler - 2011 P415 >> << Message: RE: P415 3.5L Catalyst replacement 2011MY, 2012MY >>

Please prepare an Environmental Problem Review Committee (EPRC) Fact sheet for *Some 2011 F150 rucks with 3.5L GTDI engines may experience misfire conditions due to condensation build up in the charge air cooler*, per the instructions below.

- Obtain EPRC fact sheet at <https://www.tc2.ford.com/ts/VEE/certification/default.aspx> (the fact sheet link is listed under "Reporting Compliance Sites" low on the left side of the page)
- Fill out both pages of the fact sheet as completely as possible. (NOTE: Please use Vehicle Line names like "Fusion" rather than Vehicle line codes like "CD338" in all sections referring to vehicles affected.)
- 11EPRC20 has been assigned to this item. Place this number in the Form Header.
- To facilitate an efficient review of the topic in EPRC, the CCM group will set up a fact sheet review meeting by the Friday before your scheduled EPRC presentation. Please plan to support this meeting. It will improve the quality of the EPRC meeting review and reduce your follow up requirements.
- Please send the completed fact sheet draft to me by close of business on the Monday prior to your scheduled EPRC meeting. (No paper copies are necessary for the meeting.)
- Please plan to present this item in the 11-15-12 EPRC meeting at 10:00 AM. Presentations should be made by LL6 or above employees with support from any employees required. Presentations should also be made in person (not via call in.) Please provide CDS id's for the appropriate meeting notice.

EPRC Background:

The Environmental Problem Review Committee is chaired by Vehicle Environmental Engineering. It has members from The Automotive Safety Office, Critical Concern Review Group (CCRG), Critical Concern Manager (CCM), The Ford Customer Service Division (FCSD) - Recall Group, The Office of the General Council (OGC) Global Product Development and Vehicle Operations – GRC Manager. It's mission is to review all Production Vehicle/Engine Environmental Compliance related issues to determine the correct course of action for the company. Support from the organizations and individuals who have firsthand knowledge of environmental compliance related issues is critical to the committee's success.


Thanks in advance for your cooperation and support. Please feel free to contact me with any questions.

Marie Wilson
 Ford Motor Company
 Vehicle Environmental Engineering
 Homologation & Compliance
 Phone: 313-248-2404 MWILSO18@FORD.COM

From: Wilson, Marie (M.)
Sent: Wednesday, October 31, 2012 10:03 AM
To: Bush, Janet (J.K.); Witzcak, Rich (R.A.); Cockerill, Al (C.A.); Ronzi, Bill (W.C.); Kramer, Michael (M.T.)
Subject: CAC follow up

Follow up from our meeting yesterday.

I do find CAC 6K775 in the parts coverage directory including California 7/70 warranty coverage. See attached.



I reviewed the Emissions application and still consider this part described. I am confirming with our certification engineers who normally provides this feedback to EPRC. See:

https://www.tc2.ford.com/ts/VEE/certification/applications/Applications%20%202011%20MY%20%20Confidential/CBI_BFMXT03.54EP_APP_FIN_R00.pdf

Search by the words Charge Air Cooled (not the part number) you will find reference to the CAC in two places.

Also, there is a new TSB on its way out now that I believe is related. Is it? If so, we should include 2013 MY in the fact sheet.



Marie Wilson
Ford Motor Company
Vehicle Environmental Engineering
Homologation & Compliance
Phone: 313-248-2404 MWILSO18@FORD.COM

2011 MODEL 7/70 DEFECT WARRANTY COVERAGE

2011 California Passenger Cars, Light Duty Trucks, including Hybrid vehicles in PA., OR. & WA.
(Vehicles 14000 GVWR or less)

Part Name	Part Number(s)	Engine Size/Vehicle Line																										
		1.6L Fiesta	2.0L Focus	2.0L Transit/Connect	2.0L Explorer	2.3L Ranger	2.5L Fusion	2.5L Mylar	2.5L Fusion-Hybrid	2.5L Mylar-Hybrid	2.5L MKZ-hybrid	2.5L Escape	2.5L Mariner	2.5L Escape-Hybrid	2.5L Mariner-Hybrid	3.0L Fusion	3.0L Mylar	3.0L Escape	3.0L Mariner	3.5L Fusion	3.5L MKZ	3.5L Flex	3.5L Taurus	3.5L MKS	3.5L MKT	3.5L Edge	3.5L Explorer	3.5L F150
ABS Module	2C219																											
Catalytic Converter	5E212, 5E213, 5230(7), 5G232, 5F250, 5H270	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X
Exhaust Converter Intermediate Pipe	5G274															X	X											
Diesel Particulate Filter	5H270																											
Diesel Exhaust Fluid Tank Assembly	5J228																											
Cam Timing Assembly	6256	X														X	X	X	X	X	X					X	X	X
Variable Camshaft Timing Kit	6A257																			X	X	X	X	X	X	X	X	
Venable Camshaft Timing Housing (Right)	6C260															X	X			X	X	X	X	X	X	X	X	
Variable Camshaft Timing Housing (Left)	6C261															X	X			X	X	X	X	X	X	X	X	
Variable Camshaft Timing Solenoid	6M280																											X
Variable Camshaft Timing Assembly	6C525																						X				X	
Turbocharger	6K662				X																							X
Charge Air Cooler	6K775				X																							X
Transmission Turbine Shaft Speed Sensor	7M101				X	X																					X	
Transmission Output Shaft Speed Sensor	7H103																											
Transmission Intermediate Speed Sensor	7M183					X																						
Transmission Range Sensor	7F293						X	X								X	X			X	X							
Transmission Control Module	7Z389				X																X	X	X	X	X	X	X	X
Transmission Solenoid Assembly	7A100(8), 7G391						X	X				X	X							(3)	(3)	X	X	X	X	X	X	X
Fuel Tank	9002	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X
Fuel Tank Shield	9A031, 9A032																					X	X					
Fuel Filler Pipe	9034			X																								
Fuel Supply Manifold Assembly	9C280	X																			X	X	X	X				
Fuel Delivery Module	9H307	X			X																	X	X			X	X	X
Fuel Pump Assembly	9350				X																	(4)	(4)					X
Turbocharger Control Solenoid	9K378				X																							X
Intake Manifold	9424												X	X								X	X	X	X			X
Exhaust Manifold (Right-Hand)	9430																				X	X	X	X	X	X	X	X
Exhaust Manifold (Left-Hand)	9431																				X	X	X	X	X	X	X	X
Exhaust Manifold Gasket	9448															X	X									X	X	X
EGR Cooler	9F464																											
EGR Tube to Manifold Connector	9F485															X	X											
Emission Vacuum Connector	9E498																											
Fuel Injector	9E527, 9F593																					(4)	(4)	(4)	(4)			
High Pressure Fuel Pump	9A543																											
Throttle Body Spacer	9A586																											
Fuel Vapor Storage Canister	9D653																											
Fuel Injector Fuel Supply Manifold	9F792																		X	X		X	X					X
Fuel Injector Wiring Harness	9C930				X																							X
High Voltage Traction Battery	10B759								X	X	X				X	X												
High Voltage Battery Pack Sensing Module	10B830								X	X	X																	
Instrument Cluster (5)	10E49			X		X	X	X	X	X					X	X					X						X	X
Powertrain Control Wiring Harness	12A561			X		X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X
Engine Control Wiring Harness	12B637				X																							
Powertrain Engine Control Unit (ECU)	12A850	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X
Engine Control Sensor Wiring Assembly	12A690																											
Main Body Wiring Harness (6)	14A005		X	X		X	X	X	X	X					X	X					X	X						
Dash Panel & Headlamp Junction Wiring Assembly (6)	14290	X		X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X
Main Wiring Assembly (6)	14401				X																							X
Rear Lamp Wiring Assembly (6)	14405										X	X	X	X		X	X											X

- (1) for F-Super-duty 4x4 Manual Shift on the Fly (MSOF) Transfer Case Vehicles only
- (2) for 4x4 only
- (3) Trans Solenoid Assy requires replacement of Trans Valve/Control Assy
- (4) for EcoBoost Engine only
- (5) for Service Engine Soon / Malfunction Indicator Light (MIL) functionality concerns only
- (6) for MIL Illumination only
- (7) for Flex, Taurus, MKS & MKT w/ 3.5L GTDI only
- (8) for 3.5L Fusion & MKZ and 5.4L Expedition & Navigator only

Note: Parts were selected for 7/70 Defect Coverage on the basis of their estimated replacement cost at the time the California Air Resources Board certified the vehicle for sale in California.

3.5L GTDI—INTERMITTENT STUMBLE/MISFIRE ON ACCELERATION FROM HIGHWAY CRUISE IN HUMID OR DAMP CONDITIONS— BUILT ON OR BEFORE 9/18/2012	Concern Tracking# 069-2012-1953
---	--

FORD:
2013 F-150

ISSUE

Some 2013 F-150 vehicles built on or before 9/18/2012 and equipped with a 3.5L gasoline turbocharged direct injection (GTDI) Ecoboost engine may exhibit an intermittent stumble and/or misfire on hard acceleration after an extended drive at highway speeds during high humid or damp conditions. This could result in a steady or flashing malfunction indicator lamp (MIL) with diagnostic trouble codes (DTCs) primarily for misfire P0300, P0304, P0305, P0306. DTC P0430 may also be present.

ACTION

Follow the Service Procedure steps to correct the condition.

SERVICE PROCEDURE

Ensure all hard fault powertrain DTCs are addressed prior to performing this service procedure.

1. Check for DTC P0430. Is DTC P0430 present?
 - a. Yes - Replace the left hand catalytic converter. Refer to Workshop Manual (WSM), Section 309-00. Proceed to Step 2.
 - b. No - Proceed to Step 2.
2. Install a new Charge Air Cooler (CAC) and the original air deflector plate and shield using new retaining pushpins. Refer WSM, Section 303-12.

PART NUMBER	PART NAME
DL3Z-6K775-B	CAC
W711281-S300	Push Pin (2 Req)
BL3Z-5E212-E	Catalytic Converter Assembly
W520514-S440	Nuts (2 Req)

WARRANTY STATUS: Eligible Under Provisions Of New Vehicle Limited Warranty Coverage And Emissions Warranty Coverage
Warranty/ESP coverage limits/policies/prior approvals are not altered by a TSB. Warranty/ESP coverage limits are determined by the identified causal part and verified using the OASIS part coverage tool.

OPERATION	DESCRIPTION	TIME
0691253A	2013 F-150 3.5L DOHC GTDI: Check DTCs, Replace The Charge Air Cooler Assembly Includes Time To Transfer Turbocharger Exhaust Inlet and CAC Shield (Do Not Use With Any Other Labor Operations)	0.9 Hr,
0691253B	2013 F-150 3.5L DOHC GTDI: Check DTCs, Replace The Charge Air Cooler Assembly And The Left Hand Catalyst Converter Includes Time To Transfer Turbocharger Exhaust Inlet and CAC Shield (Do Not Use With Any Other Labor Operations)	1.2 Hrs.

NOTE: The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford or Lincoln dealership to determine whether the Bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supercede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.

Concern Tracking# 069-2012-1953 (Continued)

DEALER CODING

BASIC PART NO.


5E212
6K775 (OPERATION A)

CONDITION
CODE
12
(OPERATION
B)
42

OASIS CODES: 2*****
, 227***
, 227Q**
, 227Q30
, 227Q68
, 5*****
, 550***
, 5502**
, 550234
, 550239
, 5503**
, 550339
, 554***
, 5542**
, 554234
, 554239
, 554299
, 5543**
, 554334
, 554339
, 554399
, 557***
, 5572**
, 557234
, 557239
, 5573**
, 557334
, 557339
, 558***
, 5582**
, 558234
, 558239
, 5583**
, 558334
, 558339
, 600000
, 606000
, 606000
, 609000
, 609500
, 609600
, 610000
, 610500
, 610600
, 611000
, 611500
, 612000
, 612500
, 612600
, 614000
, 614500
, 614600
, 623000
, 698298

From: Wilson, Marie (M.)
Sent: Tuesday, May 14, 2013 12:59 PM
To: Christensen, Kris (K.S.); Fuher, Michael (M.J.); King, Lamar (L.L.); Edie, Mark (M.D.); Johnston, Dennis (D.T.); Londy, George (G.L.); McClenaghan, Dave (D.); Oswald, Greg (G.G.); Parks, James (J.); Wickenheiser, Francis (F.J.); Cadagin, Ed (E.J.); Welch, Sharon (S.L.); Kinnie, Yvonne (Y.C.); Goebel, Ken (K.M.); Mills, Linda (L.S.); Tuneff, Mark (M.S.); Fagerman, Todd (T.M.); Khan, Mohammad (T.); Patel, Bharat (B.J.); Spencer, Beth (B.); Schiltges, Dave (D.); Holzheuer, Bill (W.P.); Condron, Brian (B.G.); Woodring, Christopher (C.A.); Hanshaw, Jamie (J.C.); Lenox, James (J.M.); Gomes, Enio (D.); Selthofer, Adam (A.)
Subject: EPRC Meeting Agenda - 16 May 2013

Attached please find the subject meeting agenda.



Marie Wilson
Ford Motor Company
Vehicle Environmental Engineering
Homologation & Compliance
Phone: 313-248-2404 MWILSO18@FORD.COM

**EPRC MEETING AGENDA FOR
May 16, 2013
WHQ 2AW**

Cluster	Time	EPRC #	Concern	Open Assignment(s)	Activity
Announcements	10 00				
	10 05		14D/FRC/DPAC Updates	08EPRC29 - Easy Fuel 13EPRC07 - 2.0L P0030 11EPRC19 - 6.7L OBD 12EPRC21 - Can Tire	CCM's

Redacted for Relevance

PU/Med Duty/Lg SUV	11 15	11EPRC20	Some 2011 F150 trucks with 3.5L GTDI engines may experience misfire conditions due to condensation build up in the charge air cooler.	To close with signed fact sheet	PTO VEE-CE
--------------------	-------	----------	---	---------------------------------	---------------

Redacted for Relevance

From: Nowaczyk, Rick (R.J.) [mowaczy@ford.com]
Sent: Monday, February 04, 2013 1:01 PM
To: McDonagh, Scot (S.M.); Oyafuso, Kevin (K.G.); Selthofer, Adam (A.); Dixon, Mark (M.R.); Hughes, Scott (S.R.)
Cc: Dobbs, Dan (K.D.); Nowaczyk, Rick (R.J.); Shekleton, James (J.)
Subject: **Escalated Case** 2012 F-150 CAC Misfire TAR REOPENED AT SAYBROOK FORD, INC. 08844--USA Phone : (860) 388-3572 FOR MUNCASTER , DAVID ON 2012 F150 4X4 ,F150 ,SUP CRW,STYSD VIN : 1FTFW1ET7CF [REDACTED] GCQIS : CJBB6001

Importance: High

Engineering Team,

Here is a 2012 F-150 3.5L with what appears to be a continued CAC Misfire after the latest updates. The FSE (James Shekleton is CC: on the note) looking for further digestion. Dealer has not been able to replicate the concern. Customer does state the concern only happens after an extended cruise at highway speed then go to WOT vehicle losses power mode 6 data shows #5 cylinder.

What are the next steps, should we have the FSE get some VDR data?

From: Shekleton, James (J.)
Sent: Monday, February 04, 2013 11:26 AM
To: Nowaczyk, Rick (R.J.)
Cc: Raboin, Matt (M.)
Subject: FW: TAR REOPENED AT SAYBROOK FORD, INC. 08844--USA Phone : (860) 388-3572 FOR MUNCASTER , DAVID ON 2012 F150 4X4 ,F150 ,SUP CRW,STYSD VIN : 1FTFW1ET7CF [REDACTED] GCQIS : CJBB6001

Rick,

I left you a voicemail regarding this TAR and concern on this 2012 F 150. I was reviewing the "Emerging Detailed Reports" and "Emerging Reports >75% of QSF Threshold" that Jason Kahn sends out. Line 20 of the Truck and SUV tab in the "Emerging Detailed Reports" is where I have some questions.

There are no DTCs set in this truck and mode six data shows one misfire on cylinder 6.

At your earliest convenience, please call me regarding this concern. Thank you.

Jim Shekleton

Field Service Engineer
Ford Customer Service Division
Boston Region
Mobile: (201) 788-7004
Fax: 1-888-410-2801
Email: jsheklet@ford.com

This e-mail and any attachments is intended only for the use of the person or persons addressed hereto and may contain legally privileged and/or confidential information. If you are not the intended recipient of this e-mail, you are hereby notified that any dissemination, distribution or copying of this e-mail, and any attachments, is strictly prohibited. If you have received this e-mail in error, please notify me via return e-mail and permanently delete the original and any copy of any e-mail and any printout.

From: CQIS, Help (.)

Sent: Monday, February 04, 2013 9:44 AM

To: Jakob, Diana (D.); Paff, Curtis (C.L.); Shekleton, James (J.); Avery, Kevin (K.); Raboin, Matt (M.); Stawiecki, Bob (R.); Todisco, Ronald (R.J.); Atkinson, Bill (B.W.); Wynn, David (D.); Yurowski, Daniel (D.E.); Clark, John (J.J.); Manning, Justin (J.E.); Tomaso, James (J.C.); Krawczyk, Kevin (R.); Palmer, Ken (L.); Peters, Paul (P.); Koulakjian, Robert (J.)
Cc: Barrett, Dale (D.); Barrett, Dale (D.); Harmon, Derek (D.M.); Stendardo, David (D.); Mceachern, Matthew (M.); Johnson, Seth (S.); Houston, Willie (W.)

Subject: TAR REOPENED AT SAYBROOK FORD, INC. 08844--USA Phone : (860) 388-3572 FOR MUNCASTER , DAVID ON 2012 F150 4X4 ,F150 ,SUP CRW,STYSD VIN : 1FTFW1ET7CF [REDACTED] GCQIS : CJBB6001

A request for technical assistance has been REOPENED for :

MUNCASTER , DAVID T
08844--USA Name : SAYBROOK FORD, INC

By : US-TECHNICAL SERVICE HOTLINE

Unit Down :

The dealer requires additional assistance to resolve a concern on :
2012 F150 4X4 ,F150 ,SUP CRW,STYSD
VIN : 1FTFW1ET7CF [REDACTED]

It is filed under GCQIS report number : CJBB6001

Following TECH ASSIST REFERRAL procedure, the dealership has been notified that someone from the Region will contact them in the near future. This letter is notification of the referral. The report will be in GCQIS for your review.

https://www.gcqis.dealerconnect.com/gcqis/asp/WBRES_RptSummaryUpdMain.asp?rptnbr=CJBB6001

THANK YOU , FROM THE US-TECHNICAL SERVICE HOTLINE

Attachments : 0

Report# :	CJBB6001 NHL	Received:	10/02/2012
CCRG/EPRC:		Date:	
Vehicle:	2012,F150 4X4 ,F150 ,SUP CRW,STYSD ,1FTFW1ET7CF [REDACTED]	Reviewed Status:	
Odometer :	19,142 M	Build Date:	02/21/2012
Transmission:	6R80E	Engine:	3.5L-GTDI
		Axle:	3800F3.31C
		Calibration:	CF613K0A
		A/C:	YES

Dealer: USA 08844 Saybrook Ford, Inc. **Phone#:** (860) 388-3572
City: Old Saybrook **State:** Connecticut **Country :** USA
Originator: BRANDON RYAN
Symptom: 5 54 2 39 DRV PERF,LACK/LOSS PWR ,ACCEL,INTERMITTENT
Status:
VFG: V52 DRIVEABILITY
Additional Symptom: RUNS ROUGH PASSING
Fix:Y **Causal Component :** COOLER ASSY -- RPL
Condition Code:

Hotliner: PJACOB45 **Phone:** 000 000-0000 **Regn Cd:** N2 Boston
Engineering: **Phone:** **TAR:** OPEN
Dlr Contact: **Phone:** **Title Cde:** T

REPAIR 10/02/2012 09:04AM PHIL JACOBS MSS - FCSD - TECH SV! C ! HOTLINE
 WEB FORM DATA - CONCERN:CUSTOMER COMPLAINING ABOUT ACCELERATING ON HIGHWAY TO PASS AND LOSING ALL POWER WITH LITTLE TO NO THROTTLE RESPONSE, HAS TO PULL OVER, SHUT ENGINE OFF AND RESTART AND THEN IS FINE. HAPPENED TO HIM TWICE LAST WEEK. I HAVENT BEEN ABLE TO DUPLICATE YET. DIAGNOSTICS: ALREADY PERFORMED TSB#12-06-04. REPLACED LEFT SIDE CAT, REPROGRAM TO LATEST LEVEL AND INSTALL CAC SHIELD. DID THIS TSB A COUPLE OF WEEKS AGO. WHEN TRUCK CAME BACK TODAY, RESCANNED AND HAS NO CODES. PARTS REPLACED:LEFT SIDE CAT, INSTALL CAC SHIELD AND REPROGRAM. TECH QUESTION:ANY OTHER FIXES FOR THIS CONCERN

RECOMM 10/02/2012 09:04AM PHIL JACOBS MSS - FCSD - TECH SVC HOTLINE
 BRANDON, VERIFY WITH THE CUSTOMER IF THE CONCERN TYPICALLY OCCURS ON RAINY OR HUMID DAYS. IF THIS IS THE CASE, INSPECT THE THROTTLE BODY AND THE CAC SYSTEM FOR SIGNS OF WATER SPOTS. DUE TO THE EFFICIENCY OF THE CHARGE AIR COOLER, THERE MAY BE SOME CONDITIONS WHERE SOME CONDENSATION BUILDS IN THE CAC, DUE TO HUMID AIR BEING COMPRESSED BY THE TURBOCHARGERS AND THEN COOLED BY THE CAC. WHEN THE HUMID/COMPRESSED AIR IS COOLED BY THE CAC, IT CAUSES THE WATER GRAINS TO SEPARATE FROM THE AIR AND COLLECT ON THE CAC FINS. THE WATER IS THEN DRAWN INTO THE ENGINE, TYPICALLY RESULTING IN A BANK 2 MISFIRE.

ENGINEERING IS CURRENTLY DEVELOPING A REPAIR FOR THIS CONCERN THAT

SHOULD BE AVAILABLE DURING THE 4TH QUARTER OF THIS YEAR. IF THE CUSTOMER STATES THAT THE CONCERN WILL OCCUR UNDER ANY WEATHER CONDITIONS AND SIGNS OF WATER WERE NOT FOUND IN THE THROTTLE BODY OR

CAC SYSTEM, ATTEMPT TO DUPLICATE THE CONCERN WHILE MONITORING THE

FOLLOWING PID'S TO HELP DETERMINE THE CAUSE OF THE CONCERN; APP(%), BARO(PRESS), CHT(TEMP), CYL_(1-6)_ACCL, EQ_RAT11 (RATIO), EQ_RATIO21 (RATIO), FRP (PRESS), FRP_DSD, GEAR, KNK_CNTR_CYL (1-6),

KNK_RATE_LRND, LOAD, LONGFT1, LONGFT2, MAI P(! PRESS), NUM_MISFIRE, OCTADJ_R_LRND, O2S11_CUR, O2S21_CUR, RPM, RUNTM, SHRTFT1, SHRTFT2, TQ_CNTRL, TR, VPWR, VREF, VSS. IF THE MISFIRES CAN BE ISOLATED TO A SPECIFIC CYLINDER, SWAP THE IGNITION COILS AND THE SPARK PLUGS WITH

KNOWN GOOD CYLINDERS AND RETEST. REPLACE THE AFFECTED IGNITION COMPONENTS IF THE MISFIRE FOLLOWS THE COMPONENT. IF THE CONCERN STILL

PERSIST AFTER IGNITION COIL SWAP AND COMPRESSION TESTS DO NOT INDICATE

A CONCERN, REPLACE THE INJECTOR FOR THE MISFIRING CYLINDER(S).

REPAIR

10/02/2012 12:20PM DAVID STENDARDO MSS - FCSD - TECH SVC HOTLINE
REMOVED CAC TUBE FROM THROTTLE BODY TO COOLER, FOUND WATER INTRUSION

IN TUBE AND COOLER. I KNOW ENGINEERING IS WORKING ON A FIX FOR THIS BUT WHAT SHOULD WE DO IN THE MEAN TIME. REPLACE COOLER FOR NOW? CUSTOMER IS NOT TO HAPPY AS IS.

RECOMM

10/02/2012 12:20PM DAVID STENDARDO MSS - FCSD - TECH SVC HOTLINE

BRANDO, NO SERVICE ACTIONS SHOULD BE PERFORMED AT THIS TIME, AS A REPLACEMENT CAC WILL RESULT IN THE SAME CONCERN DUE TO THE REPLACEMENT

PART BEING EXACTLY THE SAME. AT THIS POINT, THE ONLY PROCEDURE TO BE

PERFORMED WOULD BE CLEANING OF THE CAC AS PER SECTION 303-12 INTAKE AIR DISTRIBUTION AND FILTERING / CHARGE AIR COOLER (CAC) CLEANING IN THE ONLINE WSM. KEEP IN MIND THAT THIS IS NOT A REPAIR FOR THE CONCERN AT HAND, JUST A CLEANING OF ANY WATER OR OIL SLUDGE BUILD UP.

REPAIR

10/10/2012 03:23PM DALE BARRETT MSS - FCSD - TECH SVC HOTLINE
SPOKE TO FSE TOLD TO MONITOR AND RECORD ETC ACTUAL AND ETC DESIRED

FOUND UNDER HEAVY ACCEL DIFFERENCE WAS @ 4 DEGRESS WAS TOLD THAT
1

COULD TRY A THROTTLE BODY BUT WILL NOT FIX CONCERN. DID RECHECK
INTERCOOLER AGAIN DEFFINELY WATER IN INTERCOOLER AND WATER
SIGNS IN

CAC TUBES. CUSTOMER DOES DRIVE MOSTLY HIGHWAY MILES.

!!

RECOMM

10/10/2012 03:23PM DALE BARRETT MSS - FCSD - TECH SVC HOTLINE

BRANDON, THE FORD TECHNICAL HOTLINE HAS REVIEWED YOUR REQUEST
AND HAS

DETERMINED THAT IT IS NECESSARY TO DISCUSS THIS MATTER VERBALLY
OVER

THE TELEPHONE. YOU WILL BE CONTACTED SHORTLY BY A FORD TECHNICAL
HOTLINE REPRESENTATIVE.

REPAIR

10/10/2012 03:34PM DALE BARRETT MSS - FCSD - TECH SVC HOTLINE

AN OUT BOUND CALL WAS PLACED TO THE DEALER; SPOKE TO SERVICE
STEVEN

MOSSBERG. THE CUSTOMER IS UPSET WITH THE VEHICLE PERFORMANCE
(HESITATION ON ACCELERATION). VEHICLE IS PRESENTLY AT THE DEALER,
OUT

OF SERVICE FOR 17 DAYS.

RECOMM

10/10/2012 03:34PM DALE BARRETT MSS - FCSD - TECH SVC HOTLINE

STEVEN, TECHNICAL ASSISTANCE HAS BEEN REQUESTED BY THE HOTLINE
FOR

THIS VEHICLE. THE FSE IN YOUR AREA SHOULD CONTACT THE DEALER
MANAGEMENT (SERVICE MANAGER OR SERVICE DIRECTOR) WITHIN 1
BUSINESS DAY

TO DISCUSS AND ASSIST IN THE RESOLUTION OF THIS VEHICLE CONCERN.

TAR

10/10/2012 03:34PM DALE BARRETT MSS - FCSD - TECH SVC HOTLINE

NOTE TO FSE: TECHNICAL ASSISTANCE HAS BEEN REQUESTED BY THE
HOTLINE

FOR THIS VEHICLE DUE TO THE DAYS OUT OF SERVICE AND LACK OF
PROGRESS

IN REPAIRING A HESITATION ON ACCELERATION AFTER A HIGHWAY CRUISE,
WATER HAS BEEN FOUND IN THE CAC, THE CAC DEFLECTOR IS INSTALLED,
PCM

AT THE LATEST LEVEL. THE VEHICLE HAS AN OPEN CUDL REQUESTING BUY
BACK.

PLEASE ASSIST THE TECHNICIAN IN RESOLVING THE VEHICLE

CONCERN. ESTIMATED NUMBER OF REPAIR ATTEMPTS: 3 ESTIMATED NUMBER
OF

DAYS OUT OF SERVICE: 17

ADD-ON

10/19/2012 11:15AM ROBERT STAWIECKI(FSE MSS - FCSD - REG - BOSTON

VERIFIED COMPLAINT AND ADVISED CUSTOMER TO PERFORM OCCAISONAL

HARD

ACCELS AFTER LONG CRUISE. CUSTOMER IS UNWILLING TO DRIVE BECAUSE HE

SAYS HE FEARS FOR HIS SAFETY.HAD TECH REPLACE THROTTLE BODY BECAUSE

RECORDING SHOWED 4 DEGREE VARIANCE FROM ACTUAL VS. DESIRED. MODIFIED

CAC WITH WICK INSTALLED IN BASE TO TRY TO REMOVE WATER FROM IT. DEALER

WILL ADVISE ME IF SUCCESSFUL.

ADD-ON 11/09/2012 09:20AM ROBERT STAWIECKI(FSE MSS - FCSD - REG - BOSTON SCHEDULED FOR 11/14

ADD-ON 12/11/2012 11:35AM ROBERT STAWIECKI(FSE MSS - FCSD - REG - BOSTON CAC REPLACED. CUSTOMER REPORTS NO PROBLEMS

AUDIT 12/11/2012 11:35AM ROBERT STAWIECKI(FSE MSS - FCSD - REG - BOSTON TECH ASSIST REFERRAL HAS BEEN CLOSED

REPAIR 02/01/2013 10:17AM MATTHEW MESSINA MSS - FCSD - TECH SVC HOTLINE WEB FORM DATA - CONCERN: HESITATION, BUCKING, LACK OF POWER ON ACCELERATION MAINLY AFTER CRUISE THAN ACCELERATE AND AFTER IT RAINS DIAGNOSTICS: HOOK -UP IDS AND SCAN, NO CODES. MODE 6 DATA SHOWED #6 WITH ONLY 1 COUNT FOR LAST 10 DRIVE CYCLES PARTS REPLACED: PERFORM TSB# 12-10-19. INSTALLED NEW CAC, DEFLECTOR PLATE AND REPROGRAM PCM. ALSO REPLACED #6 COIL AND PLUG. REPLACED ETB PER

ENGINEER FROM PREVIOUS REPAIR. TECH QUESTION: ANY NEW FIXES FOR THIS CONCERN OR ANOTHER ROUTE TO TAKE?

RECOMM 02/01/2013 10:17AM MATTHEW MESSINA MSS - FCSD - TECH SVC HOTLINE DAVID, SINCE THE TSB 12-10-19 HAS ALREADY BEEN COMPLETED, AND THIS CONDITION CONTINUES, PLEASE INSPECT THE FUEL QUALITY OF THIS VEHICLE.

POOR FUEL QUALITY CAN INDUCE RUNNING MISFIRE RELATED ISSUES. IF THE FUEL SAMPLE INDICATES ANY ISSUES, PLEASE COMPLETELY DRAIN THE FUEL TANK. FILL THE VEHICLE WITH KNOWN GOOD FRESH FUEL, AND REEVALUATE.

IF NO FUEL QUALITY ISSUES ARE DISCOVERED, PLEASE INSPECT THE THROTTLE INLET PRESSURE (TIP) SENSOR FOR ANY CONCERNS. A CONTAMINATED

TIP SENSOR CAN INDUCE THIS CONDITION. IF A LIKE UNIT IS AVAILABLE, PLEASE SWAP THE TIP SENSOR WITH A KNOWN GOOD UNIT, AND REEVALUATE.

ADDITIONALLY, WE HAVE ESCALATED THIS CONCERN TO THE TECHNICAL SERVICE HOTLINE'S ESCALATED HANDLING TEAM FOR ADDITIONAL

REVIEW. A
SERVICE ENGINEER FROM THIS TEAM WILL CONTACT YOU BY PHONE OR
THROUGH
THIS HOTLINE ASSISTANCE REQUEST WITHIN ONE (1) BUSINESS DAY TO
PROVIDE
ADDITIONAL INFORMATION AND/OR RECOMMENDATIONS TO ASSIST IN THE
RESOLUTION OF THE CUSTOMER'S CONCERN. OUR TEAM AT THE HOTLINE
WILL
CONTINUE TO WORK WITH YOU AND YOUR DEALERSHIP TO HELP GET THE
CONCERN
RESOLVED AND THE VEHICLE BACK TO THE CUSTOMER IN A TIMELY MANNER.
IF
WE HAVE EXHAUSTED ALL OF OUR RESOURCES AND ARE STILL UNABLE TO
RESOLVE
THE CUSTOMER'S CONCERN THROUGH THESE ADDITIONAL STEPS, THE
HOTLINE
WILL ALERT YOUR FIELD SERVICE ENGINEER BY OPENING A TECHNICAL
ASSISTANCE REQUEST. PLEASE BE PREPARED TO DISCUSS ALL DIAGNOSTICS
PERFORMED AND TEST RESULTS WITH THE TECHNICAL SERVICE HOTLINE
SERVICE
ENGINEER IN MORE DETAIL. THANK YOU IN ADVANCE.

ESCLHD

02/01/2013 10:17AM MATTHEW MESSINA MSS - FCSD - TECH SVC HOTLINE
106074185 CONCERN RE-ESCALATED DUE TO PAST FSE INVOLVEMENT. THE
RUNNING ROUGH IN HUMID (RAINING) CONDITION CONTINUES. TSB 12-10-19
HAS
BEEN COMPLETED.

AUDIT

02/01/2013 10:17AM MATTHEW MESSINA MSS - FCSD - TECH SVC HOTLINE
ODOMETER 9531 M CHANGED TO 19142 M BY MMESSIN4

REPAIR

02/04/2013 09:39AM DALE BARRETT MSS - FCSD - TECH! S! VC HOTLINE
AN OUT BOUND CALL WAS PLACED TO THE DEALER; SPOKE TO TECHNICIAN
DAVID
MUNCASTER. THE TECHNICIAN HAS NOT DUPLICATED THE CONCERN.
CUSTOMER
STATES AFTER STEADY STATE CRUISE IN RAINY CONDITIONS FOR EXTENDED
PERIODS OF TIME THE VEHICLE WILL LOSE POWER ON HARD ACCELERATION.
THE
LOST POWER EVENT WILL NOT RE-OCCUR UNTIL THE VEHICLE IS DRIVEN
AGAIN
AT A STEADY STATE CRUISE. VEHICLE HAS THE LATEST UPDATED CAC AND
PCM
SOFTWARE. !!

TAR

02/04/2013 09:39AM DALE BARRETT MSS - FCSD - TECH SVC HOTLINE
NOTE TO FSE: TECHNICAL ASSISTANCE IS BEING REQUESTED BY THE HOTLINE

DUE TO THE DAYS OUT OF SERVICE AND LACK OF PROGRESS IN REPAIRING A
LOSES POWER CONCERN. CUSTOMER STATES AFTER STEADY STATE CRUISE IN
RAINY CONDITIONS FOR EXTENDED PERIODS OF TIME THE VEHICLE WILL
LOSE

POWER ON HARD ACCELERATION. THE LOST POWER EVENT WILL NOT RE-
OCCUR

UNTIL THE VEHICLE IS DRIVEN AGAIN AT A STEADY STATE CRUISE. VEHICLE
HAS THE LATEST UPDATED CAC AND PCM SOFTWARE. THE VEHICLE WAS
TECH

ASSISTED FOR THIS ISSUE 10/10 12. PLEASE ASSIST THE TECHNICIAN IN
RESOLVING THE VEHICLE CONCERN. ESTIMATED NUMBER OF DAYS OUT OF
SERVICE: 18 ESTIMATED NUMBER OF REPAIR ATTEMPTS: 4

RECOMM

02/04/2013 09:39AM DALE BARRETT MSS - FCSD - TECH SVC HOTLINE

DAVID, TECHNICAL ASSISTANCE HAS BEEN REQUESTED FOR THIS VEHICLE BY
THE TECHNICAL HOTLINE. THE FSE IN YOUR AREA WILL CONTACT THE
SERVICE MANAGER OR SERVICE DIRECTOR WITHIN 1 BUSINESS DAY TO ASSIST
IN

REPAIRING THE VEHICLE CONCERN.

ADD-ON

02/04/2013 09:44AM DALE BARRETT MSS - FCSD - TECH SVC HOTLINE

RE-OPENING TAR

AUDIT

02/04/2013 09:44AM DALE BARRETT MSS - FCSD - TECH SVC HOTLINE

TECH ASSIST REFERRAL HAS BEEN REOPENED

This email was generated by the server ECCWS686

From: Kramer, Michael (M.T.)
Sent: Tuesday, June 04, 2013 7:11 AM
To: Ronzi, Bill (W.C.)
Cc: Alcaraz andrade, Alejandro (M.); Andersen, Erik (E.); Tyler, Jim (J.S.); Kramer, Michael (M.T.)
Subject: External 7 tube / 8 fin blocker '11 & 12 MY P415 Only TSB

Bill. Are you starting the draft of the subject in anticipation of successful corrosion test completion?

- Need to include a cleaning procedure to ensure blocker sticks.
- Also need to ensure the existing top 6 tube external blocker is not used with the 7 tube / 8 fin stick-on blocker.
- Any further discussions with FCSD on how to prevent installing the 7 tube / 8 fin stick-on blocker on a PCA CAC?

Mike Kramer
RWD PT Cooling Supv.
Six Sigma Black Belt
Cell Phone: (313) 805-0190
Text Page: mkramer1
Page from outside Ford. External email: mkramer1@ford.com

From: Nowaczyk, Rick (R.J.)
Sent: Tuesday, February 14, 2012 2:40 PM
To: Mazuchowski, James (J.A.); Hammoud, Mazen (M.); Norman, Kristofor (K.R.); Baum, Joe (J.M.); Smith, Craig (C.A.); Baltusis, Paul (P.A.); Sims, Ivan (I.D.); Cockerill, Al (C.A.); Gernant, Tim (T.R.); Graham, David (D.L.); McDonagh, Scot (S.M.); Dobbs, Dan (K.D.); Ricks, Kevin (K.J.); Sparks, Douglas (D.S.); Wright, Robin (R.A.); Norton, John (J.K.); Stephens, Craig (C.); McNamara, Patrick (P.S.); Gardner, Greg (G.D.); Osepchook, William (W.R.)
Subject: F-150 3.5L GTDI PCM reflash has gone to FINAL as 12-2-10 (enUSA)
Importance: High

Team Members,

TSB 12-2-10 for 3.5L GTDI reflash is now released to the field.

I will be submitting the SSM for approval today with the article # 12-2-10 included in the message.

Thanks

-----Original Message-----

From: Siplus, G (G.)
Sent: Tuesday, February 14, 2012 2:17 PM
To: Nowaczyk, Rick (R.J.)
Subject: 069-2012-1106 has gone to FINAL as 12-2-10 (enUSA)
Importance: High

English TSB Article 12-2-10 has been released for publication

The following Technical Service Bulletin (TSB) article has been moved from collaboration and is now final.

Dealers may view this article on the next business day via OASIS and fmcdealer.com (<http://www.fmcdealer.dealerconnection.com>).

Company personnel may view it at:
<http://www.protechnician.com/>.

Concern Tracking Number: 069-2012-1106

TSB Article Number: 12-2-10

Description: 3.5L GTDI Calibration Update - Various Issues - Built On Or Before 2/7/2012.

Vehicles: F-150

If this message should not have been sent to this address please forward it to gsiplus@ford.com.

Subject: F-150 CAC

Start: Mon 5/20/2013 11:00 AM
End: Mon 5/20/2013 12:00 PM
Show Time As: Tentative

Recurrence: (none)

Meeting Status: Not yet responded

Organizer: Britton, Eric (E.J.)
Required Attendees: Fronckowiak, Todd (T.M.); Oswald, Greg (G.G.); Ott, David (D.J.); Kramer, Michael (M.T.); Smith, Craig (C.A.); Whitehead, Joseph (J.P.); Ronzi, Bill (W.C.); Andersen, Erik (E.)

Please forward this meeting notice to anyone else who may want to attend.

Reason: NHTSA has raised several questions regarding this warranty issue and the TSB. They have also requested to drive a vehicle under the subject conditions.

Objective (Agenda):
Discuss NHTSA questions (projected rate of occurrence, worst case, etc.)
Begin planning the NHTSA test drive in Dearborn
TSB's status

Eric Britton invites you to an online meeting using WebEx.

WebEx meeting information

Meeting Number: 712 830 639
Meeting Link: <https://ford.webex.com/ford/j.php?J=712830639>
Meeting Password: This meeting does not require a password.

Audio conference information

To receive a call back, provide your phone number when you join the meeting, or call the number below and enter the access code.

US Toll Free Number: +1-888-628-3668

FordNet 248-3668 / Toll: +1-313-248-3668

Global call-in numbers: <https://ford.webex.com/ford/globalcallin.php?serviceType=MC&ED=201672582&tollFree=1>

Toll-free dialing restrictions: http://www.webex.com/pdf/tollfree_restrictions.pdf

Access code XXXXXXXXXX

MC06

<http://www.webex.com>

From: Christoff, Donald (D.A.)
Sent: Wednesday, October 10, 2012 8:55 AM
To: Nowaczyk, Rick (R.J.)
Cc: Johnson, Jim (J.S.)
Subject: F-150 CAC

Good Morning Rick,

I have a few of our FSEs now saying that the new CAC are being shipped if the dealer puts in an order. I know you said that we were trying to get some "*feed stock*" of the parts before the release of the TSB, is this going to delay the release?

Don Christoff

Technical Operations Coordinator
Southeast (Atlanta, Orlando & Miami Regions)
Phone 407- 467-5007 Email - dchrist2@ford.com

Subject: F-150 CAC
Location: Teleconference

Start: Tue 6/25/2013 12:00 PM
End: Tue 6/25/2013 12:30 PM
Show Time As: Tentative

Recurrence: (none)

Meeting Status: Not yet responded

Organizer: Britton, Eric (E.J.)
Required Attendees: Ott, David (D.J.); Kramer, Michael (M.T.); Andersen, Erik (E.)

Let me know if this time works. There are no assignments for this meeting. I want to understand what tests were done in the wind tunnel. What data was recorded. What format is it in. How difficult would it be to produce the data. When could we do a data review.

Eric Britton invites you to an online meeting using WebEx.

WebEx meeting information

Meeting Number: 710 389 217
Meeting Link: <https://ford.webex.com/ford/j.php?J=710389217>
Meeting Password: This meeting does not require a password.

This meeting may include the option for video. The recording of meetings is prohibited. For company policies on using video click here:
<https://comm.sp.ford.com/sites/digitalworker/Pages/HowiWorkItem.aspx?UCTitle=to%20use%20Video&UCID=&Page=2&Section=2.001>

Audio conference information

To receive a call back, provide your phone number when you join the meeting, or call the number below and enter the access code.
US Toll Free Number: +1-888-628-3668
FordNet 248-3668 / Toll: +1-313-248-3668
Global call-in numbers: <https://ford.webex.com/ford/globalcallin.php?serviceType=MC&ED=236875992&tollFree=1>
Toll-free dialing restrictions: http://www.webex.com/pdf/tollfree_restrictions.pdf

Access code:710 389 217

MC06

<http://www.webex.com>

From: Lehmkuhl, David (D.B.)
Sent: Tuesday, February 08, 2011 12:42 PM
To: Kuehn, Dave (D.E.); Collareno, Philip (P A.); Wood, Jeffery (J.C.); Hoskins, Anthony (A.L.); Kuehn, Dave (D.E.); Green, Ann (A.D.); DiMarco, Jackie Marshal (J.M.); Wishnousky, Dale (D.S.)
Cc: Reid, Patricia (P.B.); Cowell, William (W.E.); Rothmann, Rich (R.P.); Carrier, Jeffrey (J.J.); Ickes, Bill (B.K.); Vahratian, Adam (A.J.); Galas, Dean (C.K.); Ufford, Donald (D.A.); Manzano, Deborah (D.); Lowe, Walter (W.E.); Edmonds, Mark (M.); Barthelemy, Bruno (B.); Keller, Mark (M.E.); Medley, Steven (S.D.); Katinas, Dana (D.J.); Taylor, James (J.D.); Thornton, George (G.A.); Ernat, Mike (M.G.); Rothmann, Rich (R.P.); Kiselis, Michael (M.S.); Bushey, David (D.R.); Stoltz, Jeffery (J.A.); Rothmann, Rich (R.P.); Sovoda, Richard (R.P.); Bresky, Aaron (A.); Arbitter, Daniel (D.S.); Kosztowny, Brian (B.P.); McCarthy, Mark (M.W.); Stoltz, Jeffery (J.A.); Opaleski, Edward (E.J.); Medley, Steven (S.D.); Coleman, Al (A.); Miller, Brian (B.J.); Lehmkuhl, David (D.B.)
Subject: F150 DTP and KCAP Stop Ship Status Updates / Tuesday update

This week's update (#s as of noon):

[Stop Ship #2892: F150 3.5L suspect misfire during cold weather](#)

- Robustness calibration proposal for R10 to reflash units after proveout.
- Team reviewing proposal for accelerated calibration proveout (discussion at 1 pm)
- On hold at DTP: 2236

Redacted for Relevancy

Redacted for Relevancy

Thanks,
Dave Lehmkuhl
PVT Manager F150 / DTP / KCAP
(313) 805-2751

From: Levine, Michael (M.)
Sent: Tuesday, October 23, 2012 3:10 PM
To: Scott, Douglas (D.W.); Sarkar, Raj (R.); Collareno, Philip (P.A.); DiMarco, Jackie Marshal (J.M.); Mazuchowski, James (J.A.); Lehmkuhl, David (D.B.); Smith, Craig (C.A.)
Subject: F-150 EcoBoost CAC condensation Q&A
Attachments: EcoBoost CAC TSB QA FINAL.docx

Team,

Here's our Q&A to address the engine shudder issue some F-150 EcoBoost owners may encounter in humid conditions.

Thanks very much for all of your help.

Thanks,

- Mike

Mike Levine
Ford Motor Company Truck Communications Manager
313.323.6854 office
313.806.1741 mobile
310.776.5018 google voice
mlevine5@ford.com email



F-150 EcoBoost Power and Shudder Issues in High Humidity

Situation: Some F-150 EcoBoost owners operating their truck in conditions of high humidity or during rain have reported instances of engine shudder, misfire and power loss, particularly when towing or at wide open throttle. The issue occurs when the charge-air-cooler (CAC) allows moisture to form. This condensed water can enter the engine, causing the misfire. In certain cases, the engine may enter into protective "limp" home mode. In response, Ford has implemented corrective actions that prevent recurrence of these issues.

Main Messages:

- To address this issue, all F-150 EcoBoost trucks built since Sept 18, 2012 are fitted with a new, redesigned charge-air-cooler.
 - From October 29, customers with an engine affected by this issue will be able to take their pickup to a dealer to receive a redesigned charge-air-cooler installed free of charge.
 - No instances of accidents or incidents involving this issue have been reported.
-

Q. Is Ford having engine misfire problems with F-150 EcoBoost?

A. Some F-150 customers with EcoBoost engines may experience engine shudder or misfire during conditions of high humidity and hot weather. The issue occurs when the charge-air-cooler (CAC) allows moisture to form. In some instances, this condensed water could enter the engine, causing a misfire. In certain cases, the engine may enter into its protective "limp home" mode.

Q. How many units are affected?

A. This condition affects some trucks in areas with high humidity or in similar environmental conditions.

Q. Is there a permanent fix for this condition? What is it?

A. All F-150 EcoBoost trucks built since Sept 18, 2012 have been fitted with a redesigned charge-air-cooler that prevents moisture buildup. From October 29, 2012, owners of earlier F-150 EcoBoost trucks affected by this issue will be able to receive the same charge-air-cooler installed free of charge by a dealer.

Q. How reliable are F-150 EcoBoost engines?

A. EcoBoost has excellent reliability, at 99.8% to date. EcoBoost is a huge success running over 40 percent of F-150 retail volume or more than 200,000 sales since its launch in February 2011.

###

Contact(s): Mike Levine
313-323-6854
mlevine5@ford.com

Go to <http://media.ford.com> for news releases and high-resolution photographs.

From: Stawiecki, Bob (R.)
Sent: Friday, January 06, 2012 11:16 AM
To: Oyafuso, Kevin (K.G.); Osepchook, William (W.R.)
Cc: Atkinson, Bill (B.W.); Todisco, Ronald (R.J.)
Subject: F150 inspection
Attachments: IMG00318-20120106-0951.jpg; IMG00317-20120106-0948.jpg;
IMG00316-20120106-0944.jpg; IMG00315-20120106-0943.jpg;
IMG00313-20120106-0914.jpg

Importance: High

Gentlemen, spark plugs have been installed and ground strap as well. Attached are photos of inspection re; #6 misfire 3.5 GTDI. I don't have Photoshop editor so I can't draw arrows on the pics but I'll try to describe in detail.

Image 318 is viewed looking down into airbox for air filter. Your right hand side shows water intrusion witness marks from intake snout which is pointed to inner fender well.

Image 313 is view from under driver's side of cab looking up at front of fender well area. In the middle of screen you will note a gap between fender skirt and front fender extension. It initially looks like it was broken off but examination shows that the contour mimics it's facing piece so it appears to be designed like this. Gap is approximately 1 ¼ " at it's widest point. There is evidence of substantial water spray up behind apron.

Image 315 is viewing into the bottom of CAC discharge port. Note water and oil puddling.

Image 317 is graduated beaker with CAC contents. Measured fluid is just over ¼ ounce

Image 316 is CAC discharge tube disconnected from CAC and residual oil.


The technician is removing the driver's side cam cover so that I can inspect ventilation baffle.

The dealer is requesting that I take whatever measures necessary to prevent a reoccurrence because customer has run out of patience and threatening buyback. Unless you have objections I intend to do the following;

Fabricated material to close or substantially reduce gap in fender area near airbox.
Inspect oil baffle in cam cover and drill a bleed hole as necessary.











Emissions Defect Information Report (EDIR)

* = required field

Report / Manufacturer Information

New EDIR Correct / Update EDIR *

Manufacturers must submit EDIRs within 15 working days after an emission-related defect is found.

EPA EDIR Number *

Manufacturer EDIR Number *

Form Version Number *

Additional email address

Defect Information

Problem category *
 Oxygen Sensor
 Secondary Air System
 Selective Catalytic Reduction System
Turbocharger/Supercharger

Defect description *
 Some 2011 through 2013 model year F150 Trucks with 3.5L engines may experience driveability concerns related condensation accumulated in the charge air cooler. Vehicles operated in high humidity conditions may have water condensation build up in the charge air cooler. This water can be ingested by the engine and result in temporary misfire and or slow burn conditions.

Defect identification source / method *
 (CTRL + Click to select multiple value(s))
Investigation based on warranty claims
 In-Use Testing (According to CAP 2000)
 Investigation based on customer feedback
 Manufacturer Internal Testing
 Manufacturer Technical/Data Analysis

Address(es) of plants *
 Dearborn Truck Plant
 3001 Miller Road
 Dearborn, MI 48121
 Kansas City Assembly Plant
 U.S. Highway #69
 Claycomo, MO 64199

Evaluation of the emissions impact when the vehicle / engine exhibits the defect *
 If an affected vehicle experiences misfire conditions, the Failure Mode Effects Management (FMEM) system will disable fuel injectors on up to two cylinders and limit the air/fuel ratio to a constant value. This FMEM will only remain active while misfire conditions are detected. It is estimated that exhaust emissions may be affected while the misfire FMEM system is active.

Are there any available emissions data that relates to the defect? * Yes No

Emissions Defect Information Report (EDIR)

* = required field

Does the defect cause or result in On-Board Diagnostic Malfunction Indicator Lamp illumination? * Yes No

Describe any drivability problems which a defective vehicle/engine would exhibit *

Customers driving affected vehicles will experience rough and noisy operating conditions.

Description of anticipated manufacturer follow up *

In February, 2012 Ford put a revised misfire monitor calibration into production. This calibration was designed to mitigate misfire induced catalyst damage. In September, 2012 Ford implemented a revised charge air cooler, including an external shield, to minimize condensation build up in high humidity conditions. Technical Service Bulletins (12-2-10, 12-6-4, 12-10-19 and 12-11-15) were issued to help technicians diagnose and correct the condition.

Type of related documents to be submitted to the Verify Document Module * (CTRL + Click to select multiple value(s))

- No Related Documents to Submit
- Available Emissions Data
- Repair Instructions
- Technical Service Bulletin
- Other (Specify in 'Notes' field)

Number of related documents to be submitted to Verify Document Module *

0

Notes

-Estimated values for Production Volumes and Vehicles Identified are based on Ford production and aggregate service data.

-Ford does not, by filing this report, make a determination of an emissions defect subject to Sections 207 of the Clean Air Act (42 U.S.C. § 7541), as amended, or Section 43204 of the California Health and Safety Code, or a safety defect subject to 49 U.S.C. § 30118.

* = required field

**Emissions Defect Information Report (EDIR)
Affected Vehicles / Engines Description**

Validate Form

Add Test Group / Engine Family

Test Group / Engine Family Information				Delete Test Group / Engine Family
Test Group / Engine Family *	Certified Sales Area *	Total Production Volume Count *	Potential Number Affected *	Actual Number Identified *
BFMXT03.54EP	50-State (CA+177 States+FED)	26,982	26,982	459
Add Vehicle / Engine				
Vehicle / Engine Information				
Make *	Model / Calibration *	Model Year *	Displacement (Liters) *	
Ford	F150	2011	3.5	Delete This Vehicle / Engine

Test Group / Engine Family Information				Delete Test Group / Engine Family
Test Group / Engine Family *	Certified Sales Area *	Total Production Volume Count *	Potential Number Affected *	Actual Number Identified *
CFMXT03.54EP	50-State (CA+177 States+FED)	31,692	31,692	539
Add Vehicle / Engine				
Vehicle / Engine Information				
Make *	Model / Calibration *	Model Year *	Displacement (Liters) *	
Ford	F150	2012	3.5	Delete This Vehicle / Engine

Test Group / Engine Family Information				Delete Test Group / Engine Family
Test Group / Engine Family *	Certified Sales Area *	Total Production Volume Count *	Potential Number Affected *	Actual Number Identified *
CFMXT03.54DX	50-State (CA+177 States+FED)	108,358	108,358	1,842
Add Vehicle / Engine				
Vehicle / Engine Information				
Make *	Model / Calibration *	Model Year *	Displacement (Liters) *	
Ford	F150	2012	3.5	Delete This Vehicle / Engine

* = required field

Emissions Defect Information Report (EDIR) Affected Vehicles / Engines Description

Validate Form

Add Test Group / Engine Family

Test Group / Engine Family Information				Delete Test Group / Engine Family
Test Group / Engine Family *	Certified Sales Area *	Total Production Volume Count *	Potential Number Affected *	Actual Number Identified *
DFMXT03.54DX	50-State (CA+177 States+FED)	11,335	11,335	193
Vehicle / Engine Information				
Make *	Model / Calibration *	Model Year *	Displacement (Liters) *	Delete This Vehicle / Engine
Ford	F150	2013	3.5	

Emissions Defect Information Report (EDIR)
Help Section

General

Validate Form Button

Clicking this button will check to see if the form is valid and identify any form errors for correction. Failure to submit a valid form means you have not met reporting requirements and the system will reject the form.

Report Information

New EDIR or Correct / Update EDIR

If you are submitting this EDIR for the first time, you should select "New EDIR". If you are updating or correcting a previously submitted EDIR, you should select "Correct / Update EDIR". If you select "Correct / Update EDIR", you must enter the number of the original EDIR that you are correcting / updating and the reason that you are correcting or updating the EDIR.

EPA EDIR Number

You must enter a number for the EDIR. If you are submitting a new EDIR, the number should be exactly four digits and must contain zeroes for numbers with fewer than four significant digits (e.g., "0007"). If you are submitting a corrected / updated EDIR, you must enter a two-digit revision number (e.g., "04").

Manufacturer EDIR Number

You may enter information, up to 20 characters into this field, it is designed to allow manufacturers to internally track their defect reports. If you are using your own internal number for EDIR Purposes, you may enter it here. Otherwise, enter the EPA EDIR number here.

Form version number

You must enter a two digit form version number. If you are submitting a corrected or updated EDIR, increment the number of the previous submitted EDIR. The number should be exactly 2 digits and must contain zeroes for numbers with fewer than two significant digits (e.g., "01").

Reason for correction / update

If you selected "Correct/Update EDIR", you must enter the reason that you are correcting or updating the EDIR. If you are submitting the EDIR for the first time, you should select "New EDIR". (4000 Character Limit)

Additional email address

You may enter an additional e-mail that can be used in notifications or communications concerning this report. The primary e-mail used for notifications or communications will be the one provided during the Verify registration process.

Problem category

Even if there are multiple problems identified in the EDIR, you must select only one category identifying the primary problem. For example, if an exhaust gas recirculation (EGR) valve problem is defective and, subsequently, an On-Board Diagnostic (OBD) malfunction indicator lamp (MIL) is illuminated for an EGR fault, the problem category should identify the EGR components as defective, not the OBD system. In contrast, if an OBD MIL is being erroneously illuminated for EGR valves that are not defective and the OBD programming is being corrected, then the problem category should identify the OBD system as defective.

Defect description

Clearly identify the device, system, assembly or software that has the defect, what the defect is, and to the extent known at the time, the cause of the defect. (4000 Character Limit)

**Emissions Defect Information Report (EDIR)
Help Section****Defect identification source / method**

Select one or more sources/methods from this list used to determine that a defect(s) was present in the class/category of vehicles/engines in the EDIR.

Address of plants

Enter the address of the plant(s) at which the defective vehicles or engines were produced. (4000 Character Limit)

Evaluation of the emissions impact when the vehicle / engine exhibits the defect

Describe any emissions impact when the defect(s) is present and how the emissions impact was evaluated(e.g., emissions testing, or engineering analysis). (4000 Character Limit)

Are there any available emissions data that relates to the defect?

This field is used to indicate whether or not emissions data related the defect is available. If you select "Yes", you should also send any supporting documentation to the Verify Document Module along with the EDIR.

Does the defect cause or result in On-Board Diagnostic Malfunction Indicator Lamp illumination?

This field is used to indicate whether or not the defect(s) identified in the EDIR causes or results in illumination of the On-Board Diagnostic (OBD) Malfunction Indicator Lamp (MIL).

Describe any drivability problems which a defective vehicle/engine would exhibit

Describe any drivability problems that a vehicle or engine might exhibit or an owner might experience when the defect is present on the vehicle/engine. (4000 Character Limit)

Description of anticipated manufacturer follow up

Describe any follow-up that you anticipate will be performed to rectify/correct the defect indicated in the EDIR. (4000 Character Limit)

Type of related documents to be submitted to the Verify Document Module

If you are submitting documents related or supporting the EDIR to the Verify Document Module, you can use this list to identify one or more of these documents that you are submitting. If you are submitting documents containing confidential business information (CBI) you should select "Other (Specify in 'Notes' field)" and indicate in the "Notes" field that a CBI document is being submitted separately (e.g., "CBI attached in separate document.").

Number of related documents to be submitted to Verify Document Module

Enter the number of documents you will be submitting to the Verify Document Module. Since some documents may be combined, it is helpful to know how many related documents that accompany an EDIR should be retrieved from the Verify Document Module.

Notes

Use this field to enter any notes and/or comments. In addition, there are particular fields that require you to enter notes when certain options are selected and this field should be used for this that purpose. (4000 Character Limit)

**Emissions Defect Information Report (EDIR)
Help Section****Affected Vehicles / Engines Description****Test Group / Engine Family**

Enter the test group or engine family of the affected vehicle(s) or engine(s). [Example: 9EPAX04.23A1]

Certified Sales Area

Select the appropriate certified sales area for the applicable test group or engine family. For vehicles that were certified to exhaust emission standards for California and Section 177 states, select the "CA+177 States" option. For vehicles that were certified to exhaust emission standards for states other than California and Section 177 states, select the "FED" option. For vehicles that were certified to exhaust emission standards for California and Section 177 states and states other than California and Section 177 states, select the "50-State" option.

Total Production Volume Count

Enter the total production volume of the test group or engine family. If this test group/engine family is still in production, enter the total production volume to date. However, this number should be updated with the final production volume when it is available. If this test group or engine family production has been completed, enter the final production volume.

Potential Number Affected

Enter the number of vehicles or engines produced that may have the defect described in the EDIR. This number may be different than the total production volume count only if a subset of the total production volume is potentially affected. Conversely, this number may be the same if all of the total production volume is potentially affected.

Actual Number Identified

Enter the actual number of defects described in the EDIR on the affected vehicles or engines. This number may be different than the potential number affected only if a subset of the vehicles or engines have exhibited the defect or it has been determined that they will exhibit the defect described in the EDIR. Conversely, this number may be the same as the potential number affected if all of the vehicles or engines have exhibited the defect or it has been determined that they will exhibit the defect described in the EDIR.

Make

Enter the specific make (i.e., name plate) for the affected vehicle(s) or engine(s). [Example: Buick, Lexus, Mercury]

Model / Calibration

Enter the model or calibration name that the manufacturer has designated for the vehicle or the calibration for the engine that is identified in the defect report.

Model Year

Enter the model year of the affected vehicle(s) or engine(s). [Example: 2001]

Displacement (liters)

Enter the engine displacement for the affected vehicle(s) or engine(s) in liters. [Example: 4.23] Note: The displacement will be shown without trailing zeroes. However, they will be captured when uploaded (e.g., 4.0 will be displayed as 4 on the form, but will be uploaded as 4.00).

**Emissions Defect Information Report (EDIR)
Help Section****Vehicle Information Page Buttons**

Add Test Group / Engine Family - This button is used if a report covers multiple Test Groups / Engine Families. Clicking this button creates additional Test Group / Engine Family tables at the end of the "Affected Vehicles / Engines Description" section. Each additional Test Group / Engine Family table will have a row to add Vehicle / Engine Information. Additional rows can be added if this Test Group / Engine Family covers multiple Vehicles / Engines (see instructions below for adding rows to the Vehicle / Engine Information section).

Delete Test Group / Engine Family - This button is used for deleting a Test Group / Engine Family Table. Clicking this button in a Test Group / Engine Family table will delete that Test Group / Engine Family table, and all associated Vehicle/Engine Information, only.

Add Vehicle / Engine - This button is used if a Test Group / Engine Family covers multiple Vehicles / Engines. Clicking this button in a Test Group / Engine Family table will add a new row to the bottom of the Vehicle / Engine Information section in that Test Group / Engine Family table only.

Delete Vehicle / Engine - This button is used for deleting a specific row of Vehicle / Engine Information in a Test Group / Engine Family table. Clicking the button at the end of a row will delete the a Vehicle / Engine information for just that row.

From: Kramer, Michael (M.T.)
Sent: Wednesday, September 26, 2012 6:53 AM
To: Russo, Scott (S.); Madej, Jeanette (J.); Andersen, Erik (E.)
Subject: FW: **Update on** 1 of the 12 New CAC install under engineering evaluation from Down in Florida (VIN# 1FTFW1ET6BF[REDACTED])

Additional feedback from FSE on P415 PCA CAC that did not resolve concern.

Mike Kramer
RWD PT Cooling Supv.
Six Sigma Black Belt
Cell Phone: (313) 805-0190
Text Page: mkramer1
[Page from outside Ford](#), External email: mkramer1@ford.com

From: Kramer, Michael (M.T.)
Sent: Wednesday, September 26, 2012 6:52 AM
To: Hall, Christopher (C.)
Cc: Kramer, Michael (M.T.)
Subject: RE: **Update on** 1 of the 12 New CAC install under engineering evaluation from Down in Florida (VIN# 1FTFW1ET6BF[REDACTED])

Thx. How long does he cruise at 75 mph? Is he towing (trailer weight?) during this time?

In our testing for the CAC related misfire, it has been difficult to get it to occur when not raining. It is not impossible, just much more likely to happen when raining ("super-cooling" effect of the rain on the CAC).

If you can get some pictures of the truck (overall, front end, CAC, etc.) that would also be helpful.

Mike Kramer
RWD PT Cooling Supv.
Six Sigma Black Belt
Cell Phone: (313) 805-0190
Text Page: mkramer1
[Page from outside Ford](#), External email: mkramer1@ford.com

From: Hall, Christopher (C.)
Sent: Tuesday, September 25, 2012 10:13 PM
To: Kramer, Michael (M.T.)
Subject: RE: **Update on** 1 of the 12 New CAC install under engineering evaluation from Down in Florida (VIN# 1FTFW1ET6BF[REDACTED])

I am inspecting this vehicle tomorrow morning and will have the IDS session. I spoke with the customer today and he works 12 hour shifts and if it is 70 degrees early in the morning and he set the cruise at 75 mph when he gets off the interstate and gives it the gas it will miss and bog down for approximately 30 seconds unless he lets off the gas. It is not raining when this happens. If he drives it when it is 90 degrees there is no problem according to him. It does have the blocker plate and the pcm is at the latest level.

Regards,

Chris Hall

Field Service Engineer
Ford Customer Service Division
Orlando Region
cell-727-643-9285

"Fix it right every time with Rotunda!"

<< OLE Object: Picture (Device Independent Bitmap) >>

From: Kramer, Michael (M.T.)
Sent: Tuesday, September 25, 2012 2:16 PM
To: Hall, Christopher (C.)
Cc: Kramer, Michael (M.T.)
Subject: FW: **Update on** 1 of the 12 New CAC install under engineering evaluation from Down in Florida (VIN# 1FTFW1ET6BF[REDACTED])
Importance: High

In addition to Rick's request to verify the external blocker plate is also installed, does the misfire condition only happen when raining?

Mike Kramer
RWD PT Cooling Supv.
Six Sigma Black Belt
Cell Phone: (313) 805-0190
Text Page: mkramer1
[Page from outside Ford](mailto:mkramer1@ford.com), External email: mkramer1@ford.com

From: Nowaczyk, Rick (R.J.)
Sent: Tuesday, September 25, 2012 10:52 AM
To: Sparks, Douglas (D.S.); Kramer, Michael (M.T.); Tyler, Jim (J.S.); McDonagh, Scot (S.M.)
Cc: Hall, Christopher (C.); Nowaczyk, Rick (R.J.); Dobbs, Dan (K.D.)
Subject: **Update on** 1 of the 12 New CAC install under engineering evaluation from Down in Florida (VIN# 1FTFW1ET6BF[REDACTED])
Importance: High

Engineering Team,

The FSE (Chris Hall) left me a voice mail message this morning indicating that one of the vehicle's he installed the new CAC experience a repeat misfire/stumble from moisture in the CAC. The customer did state that it seem to be a little better with the new CAC, but he was still getting the concern to happen. This customer drives over 100 miles a day to and from work. I have attached the GCQIS report for this vehicle.

Is there anything the FSE should do or look for on this vehicle?

Chris, can you confirm that the deflector plate was installed on the new CAC when the repair was made?

<< Message: Report Summary for the CQIS Report#CHNB9001 >>

Regards,
Rick Nowaczyk
FCSD Product Concern Engineer

F-150, Freestar/Monterey, Ford GT, Th!nk
E-mail: rnowaczy@ford.com
Diagnostic Service Center-I, Allen Park
PH# 313-322-7251

[Do not add or change anything below this line. The information in this section may be replaced with your meeting details after you click Send.]

WebEx Meeting Information

Meeting Number: 710 469 451

Meeting Password: This meeting does not require a password.

Meeting Link: <https://ford.webex.com/ford/j.php?J=710469451>

This meeting may include the option for video. The recording of meetings is prohibited. For company policies on using video click here:

<https://comm.sp.ford.com/sites/digitalworker/Pages/HowiWorkItem.aspx?UCTitle=to%20use%20Video&UCID=&Page=2&Section=2.001>

Audio conference information

To receive a call back, provide your phone number when you join the meeting, or call the number below and enter the access code.

US Toll Free Number: +1-888-628-3668

FordNet 248-3668 / Toll: +1-313-248-3668

Global call-in numbers: <https://ford.webex.com/ford/globalcallin.php?serviceType=MC&ED=236384877&tollFree=1>

Toll-free dialing restrictions: http://www.webex.com/pdf/tollfree_restrictions.pdf

Access code:710 469 451

MC12

<http://www.webex.com>

From: Nowaczyk, Rick (R.J.)
Sent: Thursday, January 10, 2013 4:04 PM
To: McDonagh, Scot (S.M.); Kramer, Michael (M.T.); Dixon, Mark (M.R.); Oyafuso, Kevin (K.G.); Selthofer, Adam (A.)
Cc: Dobbs, Dan (K.D.); Ricks, Kevin (K.J.); Smith, Craig (C.A.); Whitehead, Joseph (J.P.)
Subject: FW: '13 F-150 B2 CAC Misfire - CQIS Report#CK2EB014

Importance: High

Powertrain Team,

Here is another 2013MY CAC misfire with the new CAC. The concern acts up for the customer after driving on the highway for extended periods (2-4 hours) in raining/damp conditions. Stumble on acceleration and setting bank 2 misfire codes. This customer was traded out of their 2011 3.5L GTDI for the CAC misfire into this 2013 MY truck having the same concern.

From: Ridolfi, Dominic (D.R.)
Sent: Thursday, January 10, 2013 3:33 PM
To: Nowaczyk, Rick (R.J.)
Subject: '13 F-150 B2 Miss - CQIS Report#CK2EB014

From: Ridolfi, Dominic (D.R.)
Sent: Thursday, January 10, 2013 3:32 PM
To: Ridolfi, Dominic (D.R.)
Subject: OBC - '13 F-150 B2 Miss - CQIS Report#CK2EB014

Attachments : 0

Report# :	CK2EB014 NHL	Received:	11/28/2012
CCRG/EPRC:		Date:	
Vehicle:	2013,F150 4X4 ,F150 ,SUP CRW.STYSD ,1FTFW1ET8DF [REDACTED]	Build Date:	10/24/2012
Odometer :	4,207 M	Engine:	3.5L-GTDI
Transmission:	6R80E	Axle:	
Dealer:	USA 00469 Bondy's Ford Lincoln	A/C:	YES
City:	Dothan	State:	Alabama
Originator:	MARTY FORSTER	Phone#:	(334) 792-5171
Symptom:	5 50 2 39 DRV PERF,RUNS ROUGH,ACCEL,INTERMITTENT		
Status:			
VFG:	V52 DRIVEABILITY		
Additional Symptom:	STUMBLE ON ACCEL		

ACTUAL IS DROPPING LOWER THAN DESIRED, THIS INDICATES A FUEL DELIVERY CONCERN. MONITOR TIP VOLTAGE FOR A SAW-TOOTHED PATTERN, INDICATING A POSSIBLE TIP SENSOR OR TIP SENSOR CIRCUIT CONCERN. WITH THE CONCERN PRESENT MONITOR FUEL TRIMS FOR A LEAN/RICH CONDITION. PLEASE UPDATE THIS FORM WITH THE ABOVE INFORMATION, THANK YOU.

REPAIR 11/28/2012 07:46PM TONY ROMANO MSS - FCSD - TECH SVC HOTLINE
ON HVBOM IT SHOWS A DL3Z-6K775-A THIS IS THE SAME CAC AS THE DL3Z-6K775-B IN THE TSB?

RECOMM 11/28/2012 07:46PM TONY ROMANO MSS - FCSD - TECH SVC HOTLINE
MARTY, THE HOTLINE HAS LIMITED PART LOOK UP CAPABILTY, THE BEST PLACE TO CHECK PART NUMBERS WOULD BE PACO. PLEASE DIRECT YOUR QUESTION ON THIS PARTS ISSUE TO THE PARTS ASSISTANCE CENTER. SELECT PACO (PARTS ASSISTANCE CENTER ONLINE) UNDER PARTS & SERVICE TAB ON FMCDEALER.

REPAIR 01/07/2013 11:28AM DEREK KVENVOLD MSS - FCSD - TECH SVC HOTLINE
DESCRIPTION OF VEHICLE CONCERN: CS ENGINE HESITATES AND STUMBLES UNDER ACCEL WHILE DRIVING IN WET CONDITIONS DIAGNOSTICS ALREADY COMPLETED: CK CODES HAS MIFIRE CODES PARTS REPLACED: NONE MADE HOTLINE CONTACT ON LAST VISIT WITH NO REPAIR SUGGESTION TECH'S QUESTION: IS THERE ANY NEW INFOR OUT ON 2013 ON THE HESTATION OR STUMBLE WHILE DRIVING IN THE RAIN FOR A PERIOD OF TIME THEN ACCELL? IT HAS HAPPENED TWO TIMES SINCE THE LAST CONTACT. DTC: P0300 MODULE: PCM DTC: P0304 MODULE: PCM DTC: P0305 MODULE: PCM DTC: P0306 MODULE: PCM

RECOMM 01/07/2013 11:28AM DEREK KVENVOLD MSS - FCSD - TECH SVC HOTLINE
MARTY, THERE IS NO ADDITIONAL INFORMATION FOR THIS CONCERN ON THIS BUILD DATE VEHICLE. THIS REPORT WILL BE FORWARDED ON FOR ADDITIONAL REVIEW. AFTER ADDITIONAL RESEARCH CAN BE PERFORMED, YOU WILL BE CONTACTED BY PHONE WITHIN 1 BUSINESS DAY.

ADD-ON 01/07/2013 11:28AM DEREK KVENVOLD MSS - FCSD - TECH SVC HOTLINE
CONSULTED ROBERT ABERCROMBIE ON THIS CONTACT. ROBERT OR DOMINIC WILL PERFORM ADDITIONAL RESEARCH AND CONTACT THE DEALER BY PHONE.

AUDIT 01/07/2013 11:28AM DEREK KVENVOLD MSS - FCSD - TECH SVC HOTLINE
ODOMETER 600 M CHANGED TO 4207 M BY DKVENVOL

REPAIR 01/08/2013 06:46PM DOMINIC RIDOLFI MSS - FCSD - TECH SVC HOTLINE
MARTY, AN ATTEMPT WAS MADE TO REACH YOU AT THE DEALER HOWEVER IT WAS INDICATED YOU HAD LEFT FOR THE DAY.

- RECOMM 01/08/2013 06:46PM DOMINIC RIDOLFI MSS - FCSD - TECH SVC HOTLINE**
A REPRESENTATIVE FROM THE HOTLINE WILL CONTACT YOUR DEALER BY PHONE
TOMORROW.
- REPAIR 01/09/2013 05:19PM DOMINIC RIDOLFI MSS - FCSD - TECH SVC HOTLINE**
ATTEMPTED TO CONTACT MARTY AGAIN, UNABLE.
- RECOMM 01/09/2013 05:19PM DOMINIC RIDOLFI MSS - FCSD - TECH SVC HOTLINE**
MARTY, WE WILL CALL BACK TOMORROW AM.
- REPAIR 01/10/2013 03:31PM DOMINIC RIDOLFI MSS - FCSD - TECH SVC HOTLINE**
CALLED MARTY TO DISCUSS VEHICLE CONCERN. DEALER HAS NOT BEEN ABLE TO
DUPLICATE CONCERN DUE TO SPECIFIC CONDITIONS THAT NEED TO BE PRESENT FOR CONCERN TO OCCUR. THE CUSTOMER DESCRIPTION OF THE CONCERN WAS DISCUSSED AT LENGTH WITH MARTY AND IS AS FOLLOWS: CONCERN IS VERY INTERMITTENT IN NATURE AND IS DEPENDENT ON WEATHER. CONCERN CAN ONLY
BE DUPLICATED WHEN CUSTOMER DRIVES VEHICLE FOR EXTENDED PERIODS OF TIME "2-4 HOURS" IN RAINY CONDITIONS. AFTER EXTENDED DRIVING ON HIGHWAY DURING RAIN, CUSTOMER WILL ATTEMPT TO PASS ANOTHER VEHICLE.
WHEN ATTEMPTING TO PASS, THE VEHICLE WILL LOSE POWER/STUMBLE, SETTING
THE BANK TWO P030X DTCS. THE VEHICLE IS CURRENTLY NOT AT THE DEALERSHIP, IT HAS BEEN RETURNED TO THE CUSTOMER SO THE CUSTOMER IS ABLE TO DRIVE HIS VEHICLE WHILE THE DEALER DETERMINES A DIRECTION FOR
THIS CONCERN.
- RECOMM 01/10/2013 03:31PM DOMINIC RIDOLFI MSS - FCSD - TECH SVC HOTLINE**
MARTY, THANK YOU FOR THIS INFORMATION. A REPRESENTATIVE FROM THE HOTLINE WILL CONTACT YOU BY PHONE WITHIN ONE (1) BUSINESS DAY TO DISCUSS THIS ISSUE.
- ADD-ON 01/10/2013 03:31PM DOMINIC RIDOLFI MSS - FCSD - TECH SVC HOTLINE**
MARTY FORSTER (SHOP FOREMAN) CELL PHONE: (229) 220-6804

From: Smith, Craig (C.A.)
Sent: Thursday, January 10, 2013 1:27 PM
To: Leisenring, Kenneth (K.C.)
Subject: FW: '13 F-150 B2 CAC Misfire - CQIS Report#CK2EB014

Importance: High

Ken,

We seeing misfires/customer complaints on some F150 3.5L GTDI's with the PCA CAC. While the occurrence rate may be less with the PCA CAC (need data analysis to confirm), I believe that FCSD is now carrying this in the emerging deck based upon the complaints that are still coming into the dealerships.

Thanks,
Craig Smith
Supervisor - Engine Calibration
3.5L TIVCT GTDI & 3.5L IVCT GTDI Powerpacks
Phone: (313) 805-6345
TEE Bldg cube 1AD08

From: Nowaczyk, Rick (R.J.)
Sent: Thursday, January 10, 2013 4:04 PM
To: McDonagh, Scot (S.M.); Kramer, Michael (M.T.); Dixon, Mark (M.R.); Oyafuso, Kevin (K.G.); Selthofer, Adam (A.)
Cc: Dobbs, Dan (K.D.); Ricks, Kevin (K.J.); Smith, Craig (C.A.); Whitehead, Joseph (J.P.)
Subject: FW: '13 F-150 B2 CAC Misfire - CQIS Report#CK2EB014
Importance: High

Powertrain Team,

Here is another 2013MY CAC misfire with the new CAC. The concern acts up for the customer after driving on the highway for extended periods (2-4 hours) in raining/damp conditions. Stumble on acceleration and setting bank 2 misfire codes. This customer was traded out of their 2011 3.5L GTDI for the CAC misfire into this 2013 MY truck having the same concern.

From: Ridolfi, Dominic (D.R.)
Sent: Thursday, January 10, 2013 3:33 PM
To: Nowaczyk, Rick (R.J.)
Subject: '13 F-150 B2 Miss - CQIS Report#CK2EB014

From: Ridolfi, Dominic (D.R.)
Sent: Thursday, January 10, 2013 3:32 PM
To: Ridolfi, Dominic (D.R.)
Subject: OBC - '13 F-150 B2 Miss - CQIS Report#CK2EB014

Attachments : 0

Report# : CK2EB014 NHL
CCRG/EPRC: **Reviewed Status:**
Vehicle: 2013,F150 4X4 ,F150 ,SUP CRW,STYS

Received: 11/28/2012
Date:
Build Date: 10/24/2012

,1FTFW1ET8DF [REDACTED]

Odometer : 4,207 M **Engine:** 3.5L-GTDI **Calibration:**

Transmission: 6R80E **Axle:** **A/C:** YES

Dealer: USA 00469 Bondy's Ford Lincoln **Phone#:** (334) 792-5171

City: Dothan **State:** Alabama **Country :** USA

Originator: MARTY FORSTER

Symptom: 5 50 2 39 DRV PERF,RUNS ROUGH,ACCEL,INTERMITTENT

Status:

VFG: V52 DRIVEABILITY

Additional Symptom: STUMBLE ON ACCEL

Fix: **Causal Component :**

Condition Code:

Hotliner: DRIDOLF2 **Phone:** 313 248-8241 **Regn Cd:** S1 Atlanta

Engineering: **Phone:** **TAR:**

Dlr Contact: MARTY FORSTER **Phone:** 334 792-5171 **Title Cde:** T

DTCs:
KOEO:
KOEC:
KOER:

Comments

:

REPAIR 11/28/2012 05:42PM DOMINIC RIDOLFI MSS - FCSD - TECH SVC HOTLINE
 WEB FORM DATA - CONCERN:CS WHILE DRIVING IN THE RAIN AND ACCELARATES
 THE TRUCK WILL STUMBLE AND CK ENGINE LIGHT FLASHES DIAGNOSTICS: CK OASIS AND FOUND TSB 12-11-15 PARTS REPLACED:NONE TECH
 QUESTION:THE BUILD DATE IS NOT WITHIN THE TSB BUT HAS SAME CONCERN SHOULD I USE THE TSB ON THIS TRUCK AND REPLACE THE CAC?

RECOMM 11/28/2012 05:42PM DOMINIC RIDOLFI MSS - FCSD - TECH SVC HOTLINE
 MARTY, IT WOULD NOT BE RECOMMENDED TO PERFORM TSB 12-11-15 ON THIS VEHICLE. THIS VEHICLE IS EQUIPPED WITH THE CAC LISTED IN THE TSB FROM THE FACTORY, SO PERFORMING THIS TSB WOULD HAVE NO EFFECT ON THE VEHICLE. PLEASE NOTE IF YOU HAVE BEEN ABLE TO DUPLICATE THIS

CONCERN. IF NOT ALREADY DONE, SCAN ALL MODULES FOR DTCS AND UPDATE THIS FORM WITH ANY RETURNED. IF YOU ARE ABLE TO DUPLICATE THIS CONCERN, PLEASE MAKE A RECORDING OF THE EVENT FEATURING THE FOLLOWING

PIDS: APP(%), BARO(PRESS), CHT(TEMP), CYL_(1-6)_ACCL, EQ_RAT11 (RATIO), EQ_RATIO21 (RATIO), FRP (PRESS), FRP_DSD, GEAR, KNK_CNTR_CYL (1-6), KNK_RATE_LRND, LOAD, LONGFT1, LONGFT2, MAP(PRESS), NUM_MISFIRE, OCTADJ_R_LRND, O2S11_CUR, O2S21_CUR, RPM, RUNTM, SHRTFT1, SHRTFT2, TIP VOLTAGE, TIP_PRS-BOOST, TQ_CNTRL, TR, VPWR, VREF, VSS. MONITOR THE CYLINDER ACCELERATION PIDS FOR MISFIRE INFORMATION. READINGS NEAR -1 ON THE HISTOGRAM INDICATE A DETECTED MISFIRE. VERIFY THAT, WITH THE CONCERN PRESENT, FRP ACTUAL IS MATCHING FRP DESIRED CLOSELY. IF FRP ACTUAL IS DROPPING LOWER THAN DESIRED, THIS INDICATES A FUEL DELIVERY CONCERN. MONITOR TIP VOLTAGE FOR A SAW-TOOTHED PATTERN, INDICATING A POSSIBLE TIP SENSOR OR TIP SENSOR CIRCUIT CONCERN. WITH THE CONCERN PRESENT MONITOR FUEL TRIMS FOR A LEAN/RICH CONDITION. PLEASE UPDATE THIS FORM WITH THE ABOVE INFORMATION, THANK YOU.

REPAIR 11/28/2012 07:46PM TONY ROMANO MSS - FCSD - TECH SVC HOTLINE
ON HVBOM IT SHOWS A DL3Z-6K775-A THIS IS THE SAME CAC AS THE DL3Z-6K775-B IN THE TSB?

RECOMM 11/28/2012 07:46PM TONY ROMANO MSS - FCSD - TECH SVC HOTLINE
MARTY, THE HOTLINE HAS LIMITED PART LOOK UP CAPABILITY, THE BEST PLACE TO CHECK PART NUMBERS WOULD BE PACO. PLEASE DIRECT YOUR QUESTION ON THIS PARTS ISSUE TO THE PARTS ASSISTANCE CENTER. SELECT PACO (PARTS ASSISTANCE CENTER ONLINE) UNDER PARTS & SERVICE TAB ON FMCDEALER.

REPAIR 01/07/2013 11:28AM DEREK KVENVOLD MSS - FCSD - TECH SVC HOTLINE
DESCRIPTION OF VEHICLE CONCERN: CS ENGINE HESITATES AND STUMBLES UNDER ACCEL WHILE DRIVING IN WET CONDITIONS DIAGNOSTICS ALREADY COMPLETED: CK CODES HAS MIFIRE CODES PARTS REPLACED: NONE MADE HOTLINE CONTACT ON LAST VISIT WITH NO REPAIR SUGGESTION TECH'S QUESTION: IS THERE ANY NEW INFOR OUT ON 2013 ON THE HESTATION OR STUMBLE WHILE DRIVING IN THE RAIN FOR A PERIOD OF TIME THEN ACCELL? IT HAS HAPPENED TWO TIMES SINCE THE LAST CONTACT. DTC: P0300 MODULE: PCM DTC: P0304 MODULE: PCM DTC: P0305 MODULE: PCM DTC: P0306 MODULE: PCM

RECOMM 01/07/2013 11:28AM DEREK KVENVOLD MSS - FCSD - TECH SVC HOTLINE
MARTY, THERE IS NO ADDITIONAL INFORMATION FOR THIS CONCERN ON THIS

BUILD DATE VEHICLE. THIS REPORT WILL BE FORWARDED ON FOR ADDITIONAL REVIEW. AFTER ADDITIONAL RESEARCH CAN BE PERFORMED, YOU WILL BE CONTACTED BY PHONE WITHIN 1 BUSINESS DAY.

- ADD-ON** 01/07/2013 11:28AM DEREK KVENVOLD MSS - FCSD - TECH SVC HOTLINE
CONSULTED ROBERT ABERCROMBIE ON THIS CONTACT. ROBERT OR DOMINIC WILL
PERFORM ADDITIONAL RESEARCH AND CONTACT THE DEALER BY PHONE.
- AUDIT** 01/07/2013 11:28AM DEREK KVENVOLD MSS - FCSD - TECH SVC HOTLINE
ODOMETER 600 M CHANGED TO 4207 M BY DKVENVOL
- REPAIR** 01/08/2013 06:46PM DOMINIC RIDOLFI MSS - FCSD - TECH SVC HOTLINE
MARTY, AN ATTEMPT WAS MADE TO REACH YOU AT THE DEALER HOWEVER IT WAS
INDICATED YOU HAD LEFT FOR THE DAY.
- RECOMM** 01/08/2013 06:46PM DOMINIC RIDOLFI MSS - FCSD - TECH SVC HOTLINE
A REPRESENTATIVE FROM THE HOTLINE WILL CONTACT YOUR DEALER BY
PHONE
TOMORROW.
- REPAIR** 01/09/2013 05:19PM DOMINIC RIDOLFI MSS - FCSD - TECH SVC HOTLINE
ATTEMPTED TO CONTACT MARTY AGAIN, UNABLE.
- RECOMM** 01/09/2013 05:19PM DOMINIC RIDOLFI MSS - FCSD - TECH SVC HOTLINE
MARTY, WE WILL CALL BACK TOMORROW AM.
- REPAIR** 01/10/2013 03:31PM DOMINIC RIDOLFI MSS - FCSD - TECH SVC HOTLINE
CALLED MARTY TO DISCUSS VEHICLE CONCERN. DEALER HAS NOT BEEN ABLE TO
DUPLICATE CONCERN DUE TO SPECIFIC CONDITIONS THAT NEED TO BE PRESENT
FOR CONCERN TO OCCUR. THE CUSTOMER DESCRIPTION OF THE CONCERN WAS
DISCUSSED AT LENGTH WITH MARTY AND IS AS FOLLOWS: CONCERN IS VERY
INTERMITTENT IN NATURE AND IS DEPENDENT ON WEATHER. CONCERN CAN
ONLY
BE DUPLICATED WHEN CUSTOMER DRIVES VEHICLE FOR EXTENDED PERIODS OF
TIME "2-4 HOURS" IN RAINY CONDITIONS. AFTER EXTENDED DRIVING ON
HIGHWAY DURING RAIN, CUSTOMER WILL ATTEMPT TO PASS ANOTHER
VEHICLE.
WHEN ATTEMPTING TO PASS, THE VEHICLE WILL LOSE POWER/STUMBLE,
SETTING
THE BANK TWO P030X DTCS. THE VEHICLE IS CURRENTLY NOT AT THE
DEALERSHIP, IT HAS BEEN RETURNED TO THE CUSTOMER SO THE CUSTOMER IS
ABLE TO DRIVE HIS VEHICLE WHILE THE DEALER DETERMINES A DIRECTION
FOR
THIS CONCERN.
- RECOMM** 01/10/2013 03:31PM DOMINIC RIDOLFI MSS - FCSD - TECH SVC HOTLINE

MARTY, THANK YOU FOR THIS INFORMATION. A REPRESENTATIVE FROM THE HOTLINE WILL CONTACT YOU BY PHONE WITHIN ONE (1) BUSINESS DAY TO DISCUSS THIS ISSUE.

ADD-ON 01/10/2013 03:31PM DOMINIC RIDOLFI MSS - FCSD - TECH SVC HOTLINE
MARTY FORSTER (SHOP FOREMAN) CELL PHONE: (229) 220-6804

From: Andersen, Erik (E.)
Sent: Thursday, May 02, 2013 11:57 AM
To: Widmann, Carl (C.A.)
Subject: FW: 2011 P415 w/ 7 tube blocker

FYI....we are quickly progressing a plan for the bottom 7-tube blocker. Latest test data indicates we deliver equivalent or better performance than the PCA setup on the 2011 / 12 my CAC's.

Next steps are to repeat the exercise on the 2013 and beyond. I think Erik is aligned based on my earlier conversations with him, but wanted to make sure you were aware there are additional workstreams that we need to manage.

We have engaged the supplier, but given the angle of the CAC the DV isn't as straight forward. We are working through that now.

Erik Andersen
Core P/T Cooling
eanderse@ford.com
313-805-2966

From: Andersen, Erik (E.)
Sent: Thursday, May 02, 2013 10:56 AM
To: Weber, Erik (E.M.)
Subject: RE: 2011 P415 w/ 7 tube blocker

Can we repeat this same exercise with the latest CAC minus the internal blockers? My guess is that it should perform similarly, maybe slightly worse than the original CAC from an MCT perspective.

Erik Andersen
Core P/T Cooling
eanderse@ford.com
313-805-2966

From: Weber, Erik (E.M.)
Sent: Wednesday, April 24, 2013 9:20 AM
To: Andersen, Erik (E.); Kramer, Michael (M.T.); Tyler, Jim (J.S.)
Cc: Widmann, Carl (C.A.)
Subject: RE: 2011 P415 w/ 7 tube blocker

I installed the original 2013 CAC into TASE's workhorse P415, 566w329. In doing so, I discovered that the compressor bypass valve assembly we have on that truck still has a sterolith prototype housing. Functionally it should be okay though. The vehicle is all ready to go for Thursday's test slot.

Erik M. Weber

Ford Motor Company
TASE - FNA VE
P552 Thermal & Cooling
313.805.4349

<< OLE Object: Picture (Device Independent Bitmap) >>

From: Andersen, Erik (E.)
Sent: Tuesday, April 23, 2013 3:16 PM
To: Weber, Erik (E.M.); Kramer, Michael (M.T.); Tyler, Jim (J.S.)
Cc: Widmann, Carl (C.A.)
Subject: RE: 2011 P415 w/ 7 tube blocker

Thanks Erik!

I will set some time for us to get together tomorrow to talk about a test plan. I think it will involve variants of the external block with and without the latest grill insert proposal.

We can provide different external blocker configurations.

Erik Andersen
Core P/T Cooling
eanderse@ford.com
313-805-2966

From: Weber, Erik (E.M.)
Sent: Tuesday, April 23, 2013 1:46 PM
To: Kramer, Michael (M.T.); Tyler, Jim (J.S.)
Cc: Widmann, Carl (C.A.); Andersen, Erik (E.)
Subject: RE: 2011 P415 w/ 7 tube blocker

Looks like I will be able to swap the CACs myself over at the wind tunnel. We're on the schedule for Thursday morning.

Jim, do you still need to examine the CAC before I install it? I will be bringing it over to the WT around 2:15 this afternoon. You're welcome to join me in the "busted knuckles garage" while I wrench on this thing...

Erik M. Weber

Ford Motor Company
TASE - FNA VE
P552 Thermal & Cooling
313.805.4349

<< OLE Object: Picture (Device Independent Bitmap) >>

From: Kramer, Michael (M.T.)
Sent: Tuesday, April 23, 2013 9:28 AM
To: Tyler, Jim (J.S.)
Cc: Widmann, Carl (C.A.); Andersen, Erik (E.); Weber, Erik (E.M.)
Subject: RE: 2011 P415 w/ 7 tube blocker

Jim, please take a look at this CAC. High priority and visibility on testing an original J1 CAC with an external lower tube blocker.

If any doubt not the right part then need to get the right one. Do you have any original level (J1) CACs on hand?

Mike Kramer
RWD PT Cooling Supv.
Six Sigma Black Belt
Cell Phone: (313) 805-0190
Text Page: mkramer1
[Page from outside Ford](mailto:mkramer1@ford.com), External email: mkramer1@ford.com

From: Andersen, Erik (E.)
Sent: Tuesday, April 23, 2013 8:26 AM
To: Weber, Erik (E.M.); Kramer, Michael (M.T.)
Cc: Widmann, Carl (C.A.)
Subject: RE: 2011 P415 w/ 7 tube blocker

Mike,

Can you please have someone confirm it is the correct level CAC? We need to ensure we have the right config.

It should be the 14 cell, internal louvered CAC.

Erik Andersen
Core P/T Cooling
eanderse@ford.com
313-805-2966

From: Weber, Erik (E.M.)
Sent: Tuesday, April 23, 2013 7:36 AM
To: Andersen, Erik (E.); Kramer, Michael (M.T.)

Cc: Widmann, Carl (C.A.)
Subject: RE: 2011 P415 w/ 7 tube blocker

I located a non-PCA 2013 CAC in the VEMC parts crib yesterday. I need to extract it from the pellet it's on and get it over to the wind tunnel. I believe the CAC can be swapped out on site; there aren't that many connections.

Erik M. Weber

Ford Motor Company
TASE - FNA VE
P552 Thermal & Cooling
313.805.4349

<< OLE Object: Picture (Device Independent Bitmap) >>

From: Andersen, Erik (E.)
Sent: Monday, April 22, 2013 4:44 PM
To: Weber, Erik (E.M.); Kramer, Michael (M.T.)
Subject: RE: 2011 P415 w/ 7 tube blocker
Importance: High

Erik,

We just met with Julie and need to get priority to test this ASAP. I've got a call into Carl for whatever help is needed to get this run. Essentially what I'd be looking for is how much lower blocker you can tolerate from an MCT perspective on the original CAC. Whatever configuration you come up with, I'd go test for condensate. At the same time, we could give the configuration to Valeo to assess various proposals to deliver equivalent performance.

Can you please get the request out for tunnel time? Honestly, Julie is looking for a test to be completed this week.

Erik Andersen
Core P/T Cooling
eanderse@ford.com
313-805-2966

From: Weber, Erik (E.M.)
Sent: Wednesday, April 17, 2013 10:41 AM
To: Andersen, Erik (E.); Kramer, Michael (M.T.)
Subject: RE: 2011 P415 w/ 7 tube blocker

Not exactly sure. The schedule is booked solid for a few weeks, but cancellations always happen. Plus, we might be able to pull rank and bump a less critical test.

Erik M. Weber

Ford Motor Company
TASE - FNA VE
P552 Thermal & Cooling
313.805.4349

<< OLE Object: Picture (Device Independent Bitmap) >>

From: Andersen, Erik (E.)
Sent: Wednesday, April 17, 2013 10:12 AM
To: Kramer, Michael (M.T.); Weber, Erik (E.M.)
Subject: RE: 2011 P415 w/ 7 tube blocker

When do you think it could be run?

Erik Andersen
Core P/T Cooling
eanderse@ford.com
313-805-2966

From: Kramer, Michael (M.T.)
Sent: Wednesday, April 17, 2013 8:51 AM
To: Weber, Erik (E.M.)
Cc: Andersen, Erik (E.)
Subject: RE: 2011 P415 w/ 7 tube blocker

Great. This could be a potential high value service fix and is getting some attention

Mike Kramer
RWD PT Cooling Supv.
Six Sigma Black Belt
Cell Phone: (313) 805-0190
Text Page: mkramer1
[Page from outside Ford, External email: mkramer1@ford.com](mailto:mkramer1@ford.com)

From: Weber, Erik (E.M.)
Sent: Wednesday, April 17, 2013 8:48 AM
To: Kramer, Michael (M.T.)

Cc: Andersen, Erik (E.)
Subject: RE: 2011 P415 w/ 7 tube blocker

I think I still have the original non-PCA 2013 CAC, fully instrumented. Let me check my storage crib and see if it's readily available...

Erik M. Weber

Ford Motor Company
TASE - FNA VE
P552 Thermal & Cooling
313.805.4349

<< OLE Object: Picture (Device Independent Bitmap) >>

From: Kramer, Michael (M.T.)
Sent: Wednesday, April 17, 2013 8:04 AM
To: Weber, Erik (E.M.)
Cc: Andersen, Erik (E.); Kramer, Michael (M.T.)
Subject: FW: 2011 P415 w/ 7 tube blocker

Erik, can you squeeze this in near term? It is an interesting idea.

Mike Kramer
RWD PT Cooling Supv.
Six Sigma Black Belt
Cell Phone: (313) 805-0190
Text Page: mkramer1
[Page from outside Ford](mailto:mkramer1@ford.com), External email: mkramer1@ford.com

From: Andersen, Erik (E.)
Sent: Tuesday, April 16, 2013 7:26 PM
To: Widmann, Carl (C.A.)
Cc: Kramer, Michael (M.T.)
Subject: 2011 P415 w/ 7 tube blocker

Carl,

Would it be possible to run a P415 with the original 2011MY CAC and 7-tube external blocker to understand the impact to MCT? It has the higher fin density, internal louvers, and no internal blocker. It should perform much better than the PCA CAC and blocker from an MCT perspective. We need to understand if it is a feasible, better solution versus the CAC replacements we are doing today.

We have a vehicle you could use, but it would need to be instrumented for your needs.

Please let me know. We are meeting with Robert Brown tomorrow and will be going through next steps with him.

Thanks,

Erik Andersen
Core P/T Cooling
eanderse@ford.com
313-805-2966

From: Smith, Craig (C.A.)
Sent: Friday, October 28, 2011 8:45 AM
To: May, David (D.A.); Moore, Brian (B.M.)
Subject: FW: 3.5 Mis

Just to keep you guys informed regarding the 12MY P415 GTDI R08 VOCF testing.....

Thanks,

Craig Smith
Supervisor - Engine Calibration
3.5L TIVCT GTDI & 3.5L IVCT GTDI Powerpacks
Phone: (313) 805-6345
TEE Bldg cube 1AD08

From: Smith, Craig (C.A.)
Sent: Friday, October 28, 2011 8:42 AM
To: Hepburn, Mitch (M.); Gernant, Tim (T.R.); Garrett, David (D.P.); Whitehead, Joseph (J.P.); Graham, Daniel (D.B.); De Coste, Bill (W.J.); Lehmkuhl, David (D.B.)
Cc: Tatro, James (J.E.); Sims, Ivan (I.D.); Cockerill, Al (C.A.); Mazuchowski, James (J.A.)
Subject: RE: 3.5 Mis

Digging into this issue a little further, per DEMS driver feedback contained in AIMS 3192618, this vehicle (CKD00034) had also experienced a similar issue on 9/14 @8:00pm (*before R08*).

See driver comment "DC 77921" in the link below

<https://web.aim.ford.com/owa.cgi/FrameSet.Main?psRD=2011.09.12.06.52.27&psIssueID=3192618>

Two independent reviews of the latest VDR data captured w/R08 indicated that the system reacted quickly and appropriately to the misfire that occurred on 10/26.



Microsoft Word 2007: 3192618.docx
Microsoft Word 2007: 3192618.docx

The cross functional misfire investigation team also reviewed the VDR data in detail yesterday and came to the same conclusion.

Thanks,

Craig Smith
Supervisor - Engine Calibration
3.5L TIVCT GTDI & 3.5L IVCT GTDI Powerpacks
Phone: (313) 805-6345
TEE Bldg cube 1AD08

From: Hepburn, Mitch (M.)
Sent: Thursday, October 27, 2011 1:43 PM
To: Gernant, Tim (T.R.); Garrett, David (D.P.); Whitehead, Joseph (J.P.); Smith, Craig (C.A.); Graham, Daniel (D.B.); De Coste, Bill (W.J.)
Cc: Tatro, James (J.E.)
Subject: 3.5 Mis

Here is the latest, CKD00034 Grounded in Denver, Chris white (Denver) is working with powertrain. The other three units seem to be fine.

<< File: 3 5L MIS Daily Report 10-26-2011.xls >>

Mitch Hepburn
Roush Industries
Vehicle Coordinator
U377-2012
VN127-2012
C346-2012.25 BEV
mhepbur1@ford.com
Cell - 734-748-5728

From: Baskins, Robert (R.S.)
Sent: Friday, October 28, 2011 7:18 AM
To: Gernant, Tim (T.R.); Smith, Craig (C.A.); Pawlak, Greg (G.J.)
Cc: Baskins, Robert (R.S.)
Subject: RE: Issue Alert: 1FTFW1ET0CK [REDACTED] CK [REDACTED] P0306(Cylinder 6 Misfire Detected), 3.5L ECO / P415 / ATX

After looking at the data, this does look like a bank misfire from the monitor signals. The misfire counts after the "mis_pb_norm" signals faded on bank 2 would have come from the PC-rev signal. So, the Monitor changes all appear to have worked as intended here.

Bob Baskins

PT Control Design Sr. Engineer – Gasoline Ignition Subsystem
Global Powertrain Control Systems Engineering
Powertrain Controls & Calibration Engineering
Ford Motor Company / Building #2 / Cube 22M35
E-mail: rbaskins@ford.com
Mob: (313) 805-7023
ONE FORD: ONE Plan - ONE Team - ONE Goal

From: Gernant, Tim (T.R.)
Sent: Wednesday, October 26, 2011 1:42 PM
To: Smith, Craig (C.A.); Pawlak, Greg (G.J.); Baskins, Robert (R.S.)
Subject: FW: Issue Alert: 1FTFW1ET0CK [REDACTED] / CK [REDACTED], P0306(Cylinder 6 Misfire Detected), 3.5L ECO / P415 / ATX

Head's up! I have not reviewed the data yet. It looks like we set 3 DTC's.

Tim Gernant

OBD Calibration Technical Expert
Powertrain Feature Calibration
TEE 1AE33 - Ph: (313) 805-4962
<mailto:tgernant@ford.com>

From: qualifier@control-tec.com [<mailto:qualifier@control-tec.com>]
Sent: Wednesday, October 26, 2011 1:38 PM
Subject: Issue Alert: 1FTFW1ET0CK [REDACTED] CK [REDACTED] P0306(Cylinder 6 Misfire Detected), 3.5L ECO / P415 / ATX

Hello,

The following trigger was detected by Qualifier on vehicle 1FTFW1ET0CK [REDACTED] CK [REDACTED] and 3.5L ECO / P415 / ATX:

Event Name : P0306 - Cylinder 6 Misfire Detected
Event ID : [8696](#)
Module: E8
Occurred on: 2011-10-26 17:19:43
Location : Brush, CO



Datafile : [1FTFW1ET0CK \[REDACTED\] DTC---Active-or-Pending_2011-10-26_17-19-43.csv.zip](#)

Manage your issue alert settings [here](#).

Thank you,

The Qualifier Team at Control-Tec



999 Republic Dr. Suite 100, Allen Park, MI 48101 www.control-tec.com

This e-mail, and any attachments, is intended solely for use by the addressee(s) named above. It may contain confidential or proprietary information of Control-Tec LLC, its subsidiaries, affiliates or business partners. If you are not the intended recipient of this e-mail or are an unauthorized recipient of the information, you are hereby notified that any dissemination, distribution or copying of this e-mail or any attachments, is strictly prohibited. If you have received this e-mail in error, please immediately notify the sender by reply e-mail and permanently delete the original and any copies or printouts.

Computer viruses can be transmitted via email. The recipient should check this e-mail and any attachments for the presence of viruses. Control-Tec LLC accepts no liability for any damage caused by any virus transmitted by this e-mail.

Purpose:

Follow-up assignment from 10/17 PDQR re: GTDI misfire ICA and implementation options.

Agenda:

- 1) What are the current MP1/MP2 2012 M.Y. dates ?
- 2) Discuss options of containing the vehicles and reflash to catch all vehicles prior to shipment.
- 3) What are the Oct/Nov (2012 M.Y.) weekly volumes (GTDI)?
- 4) Next steps.

From: Fronckowiak, Todd (T.M.)
Sent: Thursday, May 16, 2013 9:27 AM
To: Britton, Eric (E.J.)
Subject: FW: 3.5-liter

What we already knew and what I told Mark (P/T Communications) yesterday.

Best Regards,
Todd Fronckowiak
Assistant Director
Global Automotive Safety and Compliance
Automotive Safety Office
Ford Motor Company
Phone: (313) 337-6777 | Cell: (734) 837-9409

-----Original Message-----

From: Schirmer, Mark (M.)
Sent: Wednesday, May 15, 2013 6:04 PM
To: Fronckowiak, Todd (T.M.); Kenner, Steve (S.M.); Felker, Kelli (K.F.)
Subject: 3.5-liter

FYI -- no commonality between the F150 issue and the SHO issue.
mhs

-----Original Message-----

From: Mazuchowski, James (J.A.)
Sent: Wednesday, May 15, 2013 5:52 PM
To: Schirmer, Mark (M.)
Cc: Madej, Jeanette (J.)
Subject: RE: Per my voicemail...

Mark, new CAC was implemented on the F-150 on 9/2012.

FWD 3.5L Ecoboost doesn't have the problem. Different CAC design, different vehicle installation, underhood airflow, how hard we work the vehicle and engine, different speed and load operating points, etc..

Jim Mazuchowski
Manager, V6 Engine Programs
GEE; 313-337-9935
Help me raise \$\$ to fight Multiple Sclerosis - 2013 Bike MS
http://main.nationalmssociety.org/site/TR/Bike/MIGBikeEvents?px=4458825&pg=personal&fr_id=19330

-----Original Message-----

From: Schirmer, Mark (M.)
Sent: Wednesday, May 15, 2013 4:55 PM
To: Mazuchowski, James (J.A.)
Subject: Per my voicemail...

Quick question related to the 3.5Ecoboost. Hot media story right now - we are trying to damp down.

The CAC issue with the F-150. Understand that has been handled. Does that issue also cover the FWD versions of the 3.5-Liter. Same fix? Has that been implemented?

Let me know ASAP, please.

Mark H. Schirmer
Global Product Communications Manager
Ford Motor Company
Cell: 313-354-4962
www.ford.com

From: Whitehead, Joseph (J.P.)
Sent: Monday, March 26, 2012 6:43 AM
To: Smith, Craig (C.A.); Syrylo, Tom (T.M.); Lisi, Paul (P.); Pierce, Michael (M.A.); Devries, Jason (J.E.)
Subject: FW: Al and Kevin's end plates

Pictures of the latest CAC condensate "fix", blocking plates on the hot & cold ends of the CAC core.

Thanks,

Joe Whitehead
3.5L GTDI P415 Calibration
jwhiteh4@ford.com
313 805-5481

From: Yamada, Shuya Shark (S.Y.)
Sent: Friday, March 23, 2012 3:51 PM
To: Whitehead, Joseph (J.P.)
Subject: FW: Al and Kevin's end plates



IMG_1098.JPG



IMG_1101.JPG



IMG_1100.JPG



IMG_1099.JPG



IMG_1103.JPG



IMG_1102.JPG

Shown here is 32mm opening but Al made 27 and 30mm versions as well.

Let's see how good of a seal we can make to minimize the flow to the outer tubes.

Shark.














From: Yamada, Shuya Shark (S.Y.)
Sent: Tuesday, October 23, 2012 11:10 AM
To: Kramer, Michael (M.T.); Andersen, Erik (E.); Ladd, John (J.R.); Sowards, John (J.); Norman, Kristofor (K.R.); Glugla, Chris (C.P.); Whitehead, Joseph (J.P.); Giunta, Michael (M.J.); Shaikh, F Zafar (.); Abarham, Mehdi (M.); Styles, Daniel (D.J.)
Subject: FW: CAC Coating - Nano Pattern w/ Oil Film

Misfire Team,

Joe Whitehead found this interesting coating that helps to move the condensate on the surface. It sounds better than Teflon. Was the CAC surface coating that we tested in March similar to this?

It may be a "futuristic" but perhaps we could study the prototype CAC on the bench for stripping effectiveness and heat transfer.

May be Dupont could coat one of our CAC cores for us.

Shark.

From: Glugla, Chris (C.P.)
Sent: Tuesday, October 23, 2012 9:30 AM
To: Yamada, Shuya Shark (S.Y.)
Subject: FW: CAC Coating - Nano Pattern w/ Oil Film

How about this coating?

Chris Glugla
Technical Expert Advanced Controls Implementation
Powertrain Controls Research and Development
Research and Innovation Center
2101 Village Road
Dearborn, MI. 48121
Cube 1625.g
Phone: (313) 322-4692
Ford Cell: (313) 269-4471
Fax: (313)-2487857
MD: 2036
email: cglugla@ford.com

From: Whitehead, Joseph (J.P.)
Sent: Tuesday, October 23, 2012 9:14 AM
To: Glugla, Chris (C.P.); Smith, Craig (C.A.)

Cc: Whitehead, Joseph (J.P.)
Subject: CAC Coating - Nano Pattern w/ Oil Film

http://www.pddnet.com/news/2012/10/better-way-shed-water?et_cid=2909559&et_rid=45614493&linkid=http%3a%2f%2fwww.pddnet.com%2fnews%2f2012%2f10%2fbetter-way-shed-water

Joe Whitehead
3.5L GTDI P415 Calibration
jwhiteh4@ford.com
313 805-5481

From: Ladd, John (J.R.)
Sent: Tuesday, January 08, 2013 1:46 PM
To: Kramer, Michael (M.T.); Tyler, Jim (J.S.); Hayes, Kenneth (K.J.)
Subject: FW: CAC Freezing follow-up FW: Report Summary for the CQIS Report#DAGDQ021
Attachments: DSCF2525.JPG.JPG; DSCF2523.JPG; DSCF2520.JPG

Warranty.

From: Mohan, Robert (R.)
Sent: Tuesday, January 08, 2013 12:25 PM
To: Ladd, John (J.R.)
Subject: FW: CAC Freezing follow-up FW: Report Summary for the CQIS Report#DAGDQ021

John
Are you getting these reports?

Robert Mohan
Air Induction Systems
Supervisor
313-805-9810
rmohan@ford.com

From: Galas, Dean (C.K.)
Sent: Tuesday, January 08, 2013 11:35 AM
To: Sparks, Douglas (D.S.); Schaffer, Scott (S.A.); Mohan, Robert (R.); Dixon, Mark (M.R.)
Cc: Saad, Thomas (T.J.); Galas, Dean (C.K.); Miller, Brian (B.J.)
Subject: CAC Freezing follow-up FW: Report Summary for the CQIS Report#DAGDQ021

The following notes and attached photos are in response to a follow-up to my conversation with Dan Dobbs, P415 FCSD resident engineer. The Canadian FSE's were already discussing the freezing concern.

The pictures are from an old level CAC.

Live Long and Prosper

C. K. (Dean) Galas

P/T Resident Engineer
Dearborn Truck Plant
313-337-9583 Dialnet 337-9583
cell phone 734-652-7907 dgalas@ford.com

From: Dobbs, Dan (K.D.)
Sent: Tuesday, January 08, 2013 10:37 AM
To: Galas, Dean (C.K.); Jabbour, Paul (P.)
Subject: FW: Report Summary for the CQIS Report#DAGDQ021

Ice in CAC from Canada

From: Davis, Craig (C.B.)
Sent: Tuesday, January 08, 2013 10:22 AM

To: Dobbs, Dan (K.D.)
Subject: RE: Report Summary for the CQIS Report#DAGDQ021

Dan, found an email with photos of ice in the CAC this vehicle still had the original level CAC.

1FTFW1ET0CF [REDACTED]
30,951 KM

From: Davis, Craig (C.B.)
Sent: Tuesday, January 08, 2013 10:05 AM
To: Dobbs, Dan (K.D.)
Subject: RE: Report Summary for the CQIS Report#DAGDQ021

Dan, we had a conference call with the Canadian FSEs yesterday, I had talked to them about a couple of issues relating to the CAC

- freeze up, on both levels of the CAC (pre and post TSB repairs)
- repeat issues following TSB 12-10-19 (CQIS Folder # 130002120000)

Looking at areas that would increase moisture/condensation, drive cycles, remote start use, fuel quality, distance of drive and air filter status

As I hear back I will advise you

From: Dobbs, Dan (K.D.)
Sent: Tuesday, January 08, 2013 9:49 AM
To: Davis, Craig (C.B.)
Subject: Report Summary for the CQIS Report#DAGDQ021

Craig. We are interested in these concern. Can you advise your FSE's to let me know if they hear of any. We will watch the Hotline reports like usual. But, we thought the FSE's might be engaged indirectly.

Attachments : 0

Report# :	DAGDQ021 NHL	Received:	01/07/2013
CCRG/EPRC:		Date:	
Vehicle:	2012,F150 4X4 ,F150 ,SUP CRW,STYSD .1FTFW1ET3CF [REDACTED]	Build Date:	04/12/2012
Odometer :	11,465 M	Engine:	3.5L-GTDI
Transmission:	6R80E	Calibration:	CF613C0A
Dealer:	CAN A6040 Universal Ford Lincoln Sales L.	A/C:	YES
City:	Calgary	Phone#:	(403) 291-2800
Originator:	BRENT MAY	Province:	Alberta
Symptom:	5 52 2 39 DRV PERF,STALLS/QUITS,ACCEL,INTERMITTENT	Country :	CAN
Status:			

VFG: V52 DRIVEABILITY
Additional Symptom: WATER IN CAC, SUSPECTS ICING
Fix: Causal Component :
Condition Code:

Hotliner: TROMANO7 **Phone:** 313 337-9132 **Regn Cd:** 06 06 FCSD REGION-CANADA

Engineering: **Phone:** **TAR:**
Dlr Contact: BRENT MAY **Phone:** 000 000-0000 **Title Cde:** T

DTCs:
KOEO:
KOEC:P2101 P2111 P0316
KOER:

Comments

:
REPAIR 01/07/2013 07:53PM TONY ROMANO MSS - FCSD - TECH SVC HOTLINE
WEB FORM DATA - CONCERN: CUSTOMER REPORTED THAT THE TRUCK STALLED AT A LIGHT AND WAS HARD TO RESTART. ONCE RESTATED, MOVED IT TO A PARKING LOT AND LEFT FOR 3 HOURS AND AFTER THAT TIME RESTARTED AND RAN OK. DIAGNOSTICS: EEC TESTED AND FOUND MEMORY FAULTS, CHECKED OASIS TWO DIFFERNT WAYS AND FOUND THE TSB 12-10-19, BUT THE CODES RECEIVED DIDNT MATCH THE ONES IN THE TSB. SUSPECTED THE CAC AS THERE WAS NO SHIELD ON IT. REMOVED THE CAC AND FOUND ABOUT 2 OUNCES OF WATER. PARTS REPLACED: NONE AS YET TECH QUESTION: FROM THE AMOUNT OF WATER IN THE CAC, I SUSPECT THE ROOT CAUSE OF THE ISSUE IS THE CAC AND THE SHIELD/PCM UPDATE. I SUSPECT THAT YOU WILL REQUIRE ME TO PERFORM THE TSB FIRST, DOES THIS TSB APPLY TO THIS CONCERN? I SUSPECT THAT THE WATER MAY HAVE GOT TAKEN INTO THE THROTTLE BODY, CAUSING IT TO FREEZE AND BIND IT UP. AS FOR THE P0316, IF THERE WAS ENOUGH INGESTED, IT MAY HAVE CAUSE THE MISFIRE ON START UP.....HOW CLOSE AM I? SHOULD I BE LOOKING ELSEWARE?
RECOMM 01/07/2013 07:53PM TONY ROMANO MSS - FCSD - TECH SVC HOTLINE
BRENT, IT IS POSSIBLE WATER FROZE ON THE THROTTLE AREA, RECOMMEND PERFORMING THE TSB AND RE-EVALUATING THE CONCERN. WITH THE SYMPTOMS AND CODES RECEIVED YOU MAY BE CORRECT ABOUT THE ICING.







From: Whitehead, Joseph (J.P.)
Sent: Friday, May 17, 2013 7:35 AM
To: Baskins, Robert (R.S.)
Cc: Smith, Craig (C.A.)
Subject: FW: CAC Misfire - FMEM Demonstration

Bob,
Thanks much for the flashing light background note.

Joe Whitehead
3.5L GTDI P415 Calibration
jwhite4@ford.com
313 805-5481

From: Baskins, Robert (R.S.)
Sent: Friday, May 17, 2013 5:54 AM
To: Whitehead, Joseph (J.P.); Gernant, Tim (T.R.)
Subject: RE: CAC Misfire - FMEM Demonstration

Joe,

I can't think of a way to do this with poking. Give me a call to discuss.

The PPT document in the attached note describes the rationale for disabling the flashing MIL.



2013 My 3.5L GTDI
P415 Misfire...

Bob Baskins
PT Control Design Sr. Engineer – Gasoline Ignition Subsystem
Global Powertrain Control Systems Engineering
Mob: (313) 805-7023

From: Whitehead, Joseph (J.P.)
Sent: Thursday, May 16, 2013 4:36 PM
To: Baskins, Robert (R.S.); Gernant, Tim (T.R.)
Cc: Whitehead, Joseph (J.P.)
Subject: CAC Misfire - FMEM Demonstration
Importance: High

Bob and Tim,
Ken Leisenring has requested a demonstration of the CAC misfire FMEM action tomorrow. He has asked for this demonstration to be activated by a calibration change which simulates what happens with an actual water ingestion event.

What parameter(s) can be poked to enable FMEM (injector cutouts and load limiting)?

Also, do you recall the rational for disabling the flashing MIL on a CAC type misfire?

Thanks,

Joe Whitehead
3.5L GTDI P415 Calibration
jwhite4@ford.com
313 805-5481

From: Dumler, Jeff (J.D.)
Sent: Tuesday, January 10, 2012 8:02 AM
To: Sims, Ivan (I.D.); Fabien, Phil (P.A.)
Cc: Baldwin, Damien (D.K.); Wagers, Sue (S.K.); Kramer, Michael (M.T.)
Subject: FW: CAC_Condensation_workplan_V4.xls

Ivan,

Just passing along an SEA paper that was published last year by Ying Tang at Valeo. "The Condensation within a CAC - Thermodynamics Analysis" provides insight, science, and criteria for how condensate develops within a CAC tube.



SAE Paper: The
Condensation wit..

Jeff Dumler
PTIM 6-Sigma Master Black Belt
Ford Motor Company
Location: Bldg-2, 24B31
Phone: 313-805-3996

The Condensation within a CAC - Thermodynamics Analysis

2011-01-1168

Published
04/12/2011Ying Tang
Valeo

Copyright © 2011 SAE International

doi:10.4271/2011-01-1168

ABSTRACT

With more emphasis on developing a better fuel-economic vehicle, applications of charged air cooler (CAC) in turbo charged gas and diesel engine plays an increasing critical role in both aspects of reduction of engine intake manifold temperature level and increase of intake air density. However, there is a limitation on how far charged air can be cooled when it starts to condensate within the charged air cooler (CAC).

In this paper, starting from basic thermodynamics principles, a thermal flow model is developed and explains the physical reasons for the condensation generation inside charged air cooler (CAC) tubes.

INTRODUCTION

Since late 1990, under high level of public pressures and opinions for producing more fuel efficiency and less emission vehicle, application of a charged air cooler (CAC) was become more common and having critical importance on both gas turbo charged engine powered and diesel engine powered vehicles. Especially in diesel engine powered heavy duty pickup truck, by further pushing the engine power level and being compliant with fuel economy and emission requirements, the charged air, taken from ambient environment, is needed to be compressed by turbo-compressor system to a new higher level of pressure and temperature, and then, charged air is also needed to maximize cooling down its temperature while minimizing its pressure loss. To meet such a challenge, a better and high level thermal effectiveness CAC shall be selected and installed.

For any installed component in today's vehicle, the high level functional performance, such as thermal flow characteristics,

is only a requirement partially satisfied the overall specifications. Other requirements such as durability-performances under all driving profile environments are also needed to be fulfilled. Therefore, the CAC design is not only focused on typical maximum power and maximum torque operational points but also for less challenged vehicle operating conditions. To applied in all the described vehicle operating environments, however, condensation may occurred with this high level thermal effectiveness CAC, which may lead to potential corrosion issue if the condensation's acid level is not properly controlled, especially when driving in coastal area [1,2,3]. And this may also lead to potential engine misfire if a high level accumulation of condensation existed at engine entrance location if a non-ideal CAC flow path design is used.

In this technical paper, the physical reason for the generation of condensation was presented. And also, all pertinent formulas were derived from basic principles of thermodynamics and fluid flow. Additionally, some examples related to vehicle operations were presented to illustrate the theory. Finally, discussions and comments on the range of the condensation theory and its applications were also provided.

THEORY AND EXAMPLE

Any CAC or air to air heat exchanger will experience the condensation phenomena when the heat exchanger core is exposed to cold air flow environment. Typically, when contacted with cold tube wall or less cold internal tabulator wall (or inside tube fin), the moist air flow inside CAC tube will condensate. This condensation will form as water pond like mainly located in bottom tubes of CAC. However, in this paper, the above mechanism of condensation generation is not the main focus point of discussion.

During the operation (or testing) of a high thermal effectiveness CAC in diesel engines, a high amount of condensation is typically observed. One of the possibilities of the origin of this condensation is that might have been generated inside of the tube air space and away from tube wall and/or tube turbulator wall. This means that even without consideration of cold solid surface, the moist air under high pressure and low temperature can condense within airflow stream itself, mainly inside of end portion of CAC tubes.

To analyze this problem, based on the moist air thermodynamics principals, the environments of condensation generation as second mechanism can be regarded as same as when the condensation happens under high level pressure, low charged air flow rates and low average temperature of charged air, in which any high level thermal effectiveness CAC will create the lowest possible CAC outlet charged air temperatures.

Following charged air flow path, for a typical constant amount of moist air being drawn directly from ambient, the total air pressure of this inlet point can be expressed as the combination of water vapor and dry air portions [4]:

$$P_{atm} = P_a + P_v = P_v + \frac{0.622}{\omega} P_v = \left(1 + \frac{0.622}{\omega}\right) P_v \quad (1)$$

Here, the ω is the humidity ratio of the ambient air [4].

When considering the turbo-compressor system's compressor action, the pressure p_e and temperature T_e at the compressor outlet will be increased and can be expressed as follows, by taking into account the effect of losses within the compressor system:

$$\frac{P_e}{P_{atm}} = \pi \quad (2)$$

$$\begin{aligned} \frac{T_e}{T_{atm}} &= 1 + \frac{1}{T_{atm}} \frac{T_{es} - T_{atm}}{\eta_{comp}} = 1 + \frac{1}{\eta_{comp}} \left[\left(\frac{P_{atm}}{P_e} \right)^{\frac{1-k}{k}} - 1 \right] \\ &= 1 + \frac{\pi^{\frac{k-1}{k}} - 1}{\eta_{comp}} \end{aligned} \quad (3)$$

Where T_{es} is isotropic process temperature and η_{comp} is compressor efficiency.

Then, as the charged air passing through a charged air cooler (CAC), its charged air outlet temperature T_m and pressure p_m are further reduced with heat transfer (Q) out to outside air stream:

$$\frac{P_m}{P_{atm}} = \frac{P_e}{P_{atm}} \frac{P_m}{P_e} = \pi \left(1 - \frac{\Delta p_{cac}}{P_e} \right) = \pi - \frac{\Delta p_{cac}}{P_{atm}} \quad (4)$$

$$\frac{T_m}{T_{atm}} = \frac{T_e}{T_{atm}} - \frac{\dot{Q}}{C_p \dot{m}_{cac} T_{atm}} = 1 + \frac{\pi^{\frac{k-1}{k}} - 1}{\eta_{comp}} - \frac{\dot{Q}}{C_p \dot{m}_{cac} T_{atm}} \quad (5)$$

Then, the charged air cooler outlet vapor partial pressure p_{vm} of moist content can be expressed as the ratio of itself over atmospheric pressure as follows:

$$\frac{P_{vm}}{P_{atm}} = \frac{\pi - \frac{\Delta p_{cac}}{P_{atm}}}{1 + \frac{0.622}{\omega}} \quad (6)$$

As in most cases, the assumption can be applied for gas volume is much larger than liquid one. Along the moist air saturated curve, the typical saturated water vapor pressure and its saturated temperature can be expressed as [4]:

$$\frac{dp_v}{dT} = \frac{h_{fg}}{T v_{fg}} \approx \frac{h_{fg}}{T v_g} = \frac{h_{fg}}{RT^2} P_v \quad (7)$$

$$\left(\frac{P_{vm}}{P_v} \right)_{sat} = e^{-\frac{h_{fg}}{RT_m} \left(1 - \frac{T_m}{T_{atm}} \right)} \quad (8)$$

By combining equations (1), (5), (8) and definition of relative humidity of air ϕ_v , the non-dimensional partial moist air pressure at charged air cooler (CAC) outlet (or manifold inlet if the minor pressure drops of manifold itself can be ignored) can be expressed as:

$$\frac{(p_{vm})_{sat}}{P_{atm}} = \frac{(p_{vm})_{sat}}{P_v} \frac{P_v}{P_{atm}} \left(\frac{P_{vm}}{P_v} \right)_{sat} = \frac{(p_{vm})_{sat}}{P_v} \frac{P_v}{P_{atm}} e^{-\frac{h_{fg}}{RT_{atm}} \frac{T_{atm}}{T_m} \left(1 - \frac{T_m}{T_{atm}} \right)}$$

$$(9)$$

$$\frac{(p_{vm})_{sat}}{P_{atm}} = \frac{1}{\phi_v} \left(1 + \frac{0.622}{\omega} \right)^{-1} \exp \left[-\frac{h_{fg}}{RT_{atm}} \left(1 + \frac{\pi^{\frac{k-1}{k}} - 1}{\eta_{comp}} - \frac{\dot{Q}}{C_p \dot{m}_{cac} T_{atm}} \right)^{-1} - 1 \right]$$

$$(10)$$

Based on equations (6) and (10), the final state of charged air relative humidity level at the engine intake manifold can be expressed as:

$$\phi_m = \frac{P_{vm}}{P_{atm}} \frac{P_{atm}}{(p_{vm})_{sat}} = \phi_v \left(\pi - \frac{\Delta p_{cac}}{P_{atm}} \right) \exp \left[-\frac{h_{fg}}{RT_{atm}} \left(1 - \frac{1}{1 - \left(\frac{\dot{Q}}{C_p \dot{m}_{cac} T_{atm}} - \frac{\pi^{\frac{k-1}{k}} - 1}{\eta_{comp}} \right)} \right) \right]$$

$$(11)$$

Based on equation (11), the criteria of condensation can be established when the relative humidity level of the engine intake manifold is equal to 100% ($\phi_m = 100\%$). If the condensation criterion is written as ambient air relative humidity level and compressor pressures increase ratio, the condensation characteristic related to this turbo-compressor-CAC system and can be expressed as:

$$\frac{1}{\phi_v \pi} = \left(1 - \frac{\Delta p_{cac}}{\pi P_{atm}} \right) \exp \left[-\frac{h_{fg}}{RT_{atm}} \left(1 - \frac{1}{1 - \left(\frac{\dot{Q}}{C_p \dot{m}_{cac} T_{atm}} - \frac{\pi^{\frac{k-1}{k}} - 1}{\eta_{comp}} \right)} \right) \right]$$

$$= \text{factor (system)}$$

$$(12)$$

In the following Figure-1, the calculations of the criteria curves of condensation were based on a typical charge air cooler (CAC) internal pressure drop assumed to be at 100 mbar, and when the charged air of the engine manifold temperatures (T_f) are at 20, 25 and 30 degree C. Of which, the $T_f = 20$ degree C condition corresponds to the “ideal” thermal performance CAC with its manifold temperature (T_f) equals to ambient air temperature. For these charged air temperatures of engine manifold, if the vehicle charge air booster system operates above the areas of the respective plotted curves, then the condensation will occur inside the later section of charge air cooler tubes.




Figure 1. The criteria for an exemplified charge air system, including turbo-compressor-CAC at 20 degree C ambient

In the Figure-2, the similar calculations were conducted for higher ambient temperature: 30 degree C. Here, with the same assumption on charge air cooler (CAC) internal

pressure drop, the plots curves below were for the charged air of the engine manifold temperatures (T_f) are at 30, 35 and 40 degree C levels.




Figure 2. The criteria for an exemplified charge air system, including turbo-compressor-CAC at 30 degree C ambient

All the analysis presented here had been carried out without taking into account the extensive design and operation features of the turbo-compressor-CAC, and therefore minor errors may be generated.

If a charge air cooler providing its maximum theoretical thermal performance, the final state or the engine manifold charge air temperature will be closed to that of the ambient air temperature. Then, the only lower order terms of exponent expression in the equation (11) should be maintained and its limitation value will be close to 1.0. The equation (11) may be then simplified as follows:

$$\begin{aligned} \phi_m &\approx \phi_v \left(\pi - \frac{\Delta p_{cac}}{P_{atm}} \right) \\ \left[1 + \frac{h_{fg}}{RT_{atm}} \left(\frac{\dot{Q}}{C_p \dot{m}_{cac} T_{atm}} - \frac{\pi^{\frac{k-1}{k}} - 1}{\eta_{comp}} \right) \right] \\ &\approx \phi_v \left(\pi - \frac{\Delta p_{cac}}{P_{atm}} \right) \end{aligned} \quad (13)$$

And its respective criteria of condensation expression can be shown as:

$$\begin{aligned} \frac{1}{\phi_v \pi} &\approx \left(1 - \frac{\Delta p_{cac}}{\pi p_{atm}} \right) \\ \left[1 + \frac{h_{fg}}{RT_{atm}} \left(\frac{\dot{Q}}{C_p \dot{m}_{cac} T_{atm}} - \frac{\pi^{\frac{k-1}{k}} - 1}{\eta_{comp}} \right) \right] \\ &\approx \left(1 - \frac{\Delta p_{cac}}{\pi p_{atm}} \right) \end{aligned} \quad (14)$$

$$\phi_v \left(\pi - \frac{\Delta p_{cac}}{P_{atm}} \right) = \phi_v \pi^* \approx 1 \quad (15)$$

Here, π^* is defined as effective pressure boost ratio for this entire turbo-compressor-CAC system.

Even the equation (15) here only represents the ideal situation. However, it is obvious that the condensation inside of CAC tubes will occur more easily for the high boost diesel engine system with a high level thermal effectiveness CAC. And also as indicated, the condensation phenomenon occurs when the product of ambient air relative humidity level and the effective booster pressure ratio of the entire turbo-compressor-CAC system is closed to 1.0.

In reality, the saturation transform surface between vapor phase and fluid phase of moist air is a curvature surface instead of flat one. The pressure at fluid side surface of r_f size water droplet is larger than gas phase side, and is balanced by this droplet surface tension as follow [5,6,7,8]:

$$p_f - p_v = \frac{2\sigma}{r_f} \quad (16)$$

The Kelvin-Helmholtz equation, which is reflected the curvature surface influence, may be applied here [6,7,8]:

$$\frac{p_v}{p_v^{eq}} = \exp \left(\frac{2}{r_f \rho_f} \frac{\sigma}{R T} \right) \quad (17)$$

Then, the equation (7) can be modified as the following for the curvature surface of phase transform of moist:

$$\frac{p_{vm}}{p_v} = \left(\frac{p_{vm}^{eq}}{p_v^{eq}} \right)_{sat} e^{\frac{2}{r_f \rho_f R} \left(\frac{\sigma_{vm}}{T_m} - \frac{\sigma_v}{T_{atm}} \right)} = \exp \left[-\frac{h_{fg}}{RT_m} \left(1 - \frac{T_m}{T_{atm}} \right) + \frac{2}{r_f \rho_f R} \left(\frac{\sigma_{vm}}{T_m} - \frac{\sigma_v}{T_{atm}} \right) \right] \quad (18)$$

Typically, unless water droplet size is smaller than $10^{-8}m$, the second term of above is always being ignored [6]. Also, due to pressure balancing and heat transfer impacts, not all the water droplet can be developed within charged airflow stream, smaller than a stable (critical) size one will be evaporated [6].

CONCLUSIONS

Based on the derivations and analysis on examples, the author is drawing the conclusions as the following:

- 1). Condensation within charged air away from cold solid wall surfaces is very possible for high level compressed and cooled turbo-compressor-CAC system, such as in heavy duty pickup diesel vehicle.
- 2). The product of relative humidity of ambient air and vehicle turbo-compressor-CAC system effective boost pressure ratio can be applied as the judgmental factor regarding the described condensation phenomena.
- 3). From the condensation viewpoint, the questions may be posed as how far can charged air be cooled and compressed without dehumidification of the intake air and what is the limitation of charged air cooler (CAC) design for any high level compressed system, if such limitation is existed.
- 4). Normally, for any moist or condensation droplet size, the variations or corrections on the pressure due to the curvature phase transformation surface between fluid and vapor could be ignored.

Of course to fully simulate the physical phenominal of condensation, both mechanisms-the condensation on the cold surfaces of charged air cooler (CAC) tubes and volumetrically (or spatial) condensed within the charged air stream should be counted and applied at same time.

REFERENCES

1. Zaldivar, Jose Garcia, Exhaust Gas Condensates Corrosion Evaluation on Low Pressure EGR, ACAC and WCAC Aluminum brazed heat Exchangers, 6th International Congress Aluminum Brazing, May 2010
2. Morozl, S., Bourgoïn, G., Luján, J. M., Pla, B., A 2.0 litre Diesel Engine with Low Pressure Exhaust Gas Recirculation

and Advanced Cooling Systems, SAE The Diesel Engine Conference, May 2008, Rouen

3. Zaldivar, Jose Garcia, The Role of Different Parameters on the Corrosion Of Aluminum Heat Exchangers By Exhaust Gases Condensates, 14TH Annual Invitational Aluminum Brazing Seminar, October, 2010, Novi, Michigan U.S.A.
4. Fundamentals-ASHRAE Handbook, 1997
5. Pai, Shih-I, Luo, Shijun, Theoretical and Computational Dynamics of a Compressible Flow, Springer, 1991
6. Moore, M J, Two-Phase Steam Flow in Turbines and Separators: Theory, Instrumentation, Engineering, Hemisphere Pub. Corp., 1976
7. Hewitt, Geoffrey Frederick, Hall-Taylor, N. S., Annular Two-phase Flow, Pergamon Press, 1970
8. Rowlinson, J. S. and Widom, B., Molecular Theory of Capillarity, Dover Publications, 2003

CONTACT INFORMATION

Ying Tang

Valeo Engine Cooling, Inc.

4100, North Atlantic Boulevard, Auburn Hill, MI USA 48326

ying.tang@valeo.com

ACKNOWLEDGMENTS

The author would like to acknowledge and thank Mr. Refki Elbourini (Meggitt Defense Systems, Inc.) for his constant suggestions, advices and writing revisions of this paper. And the author would like also express sincerely thanks to Dr. Jose-Zaldivar Garcia (Valeo Engine Cooling, Inc) and to Mr. Robert H. Meyer (FORD Motor P/T Cooling) for the highly inspired and valuable discussions on the topics related to the impacts of condensation inside of charged air cooler.

DEFINITIONS/ABBREVIATIONS

C_p	Heat Capacity at constant pressure
C_v	Heat Capacity at constant volume
k	C_p/C_v
h	Enthalpy
\dot{m}	Mass flow rate

Q'
Heat transfer rate

R
Gas constant, specific for each gas

r
Radius

p
Pressure

T
Temperature

π
Pressure Ratio

σ
Surface Tension

ϕ
Relative Humidity

v
Volume

ω
Humidity Ratio

η
Efficiency

SUBSCRIPT

a
Air

atm
Ambient

cac
Charged Air Cooler

comp
Compressor

E
At compressor outlet state

Es
Isotropic Process

M
Final state, Engine manifold intake

Fg
Change for phase transition

G
Gas phase

sat
Saturation

V
Vapor phase

vm
Vapor phase at final state

SUPERSCRIPT

Eq
Equilibrium

Additional term or entire

The Engineering Meetings Board has approved this paper for publication. It has successfully completed SAE's peer review process under the supervision of the session organizer. This process requires a minimum of three (3) reviews by industry experts.

All rights reserved. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, without the prior written permission of SAE.

ISSN 0148-7191

Positions and opinions advanced in this paper are those of the author(s) and not necessarily those of SAE. The author is solely responsible for the content of the paper.

SAE Customer Service:

Tel: 877-606-7323 (inside USA and Canada)

Tel: 724-776-4970 (outside USA)

Fax: 724-776-0790

Email: CustomerService@sae.org

SAE Web Address: <http://www.sae.org>

Printed in USA

SAEInternational

PE13-018

FORD

8-23-2013

APPENDIX G

Engineering Review

2

From: Ladd, John (J.R.)
Sent: Monday, April 16, 2012 12:34 PM
To: Tyler, Jim (J.S.)
Cc: Kramer, Michael (M.T.)
Subject: FW: Charge Air Cooler - 2011 P415

Jim, is the CAC an emission's item?

Regards,
John Ladd
Supervisor - Cooling Development Engineering
Ph: (313) 62-16626 Cell: (313) 805-4627
Fax: (313) 317-9241

From: Wilson, Marie (M.)
Sent: Monday, April 16, 2012 12:29 PM
To: Ladd, John (J.R.); Behnke, David (D.P.)
Cc: Cockerill, Al (C.A.); Howard, Steven (S.M.); Lundy, George (G.L.); Walkowicz, Erin (E.A.)
Subject: RE: Charge Air Cooler - 2011 P415

The reason that I started this chain below has nothing to do with emission warranty (which is Dave's responsibility). My concern is for EPA defect reporting which requires reporting on all components "described" in the emission certification application. I reviewed the application and found CAC described. If you would like further confirmation you should work with the application engineer for P415.

Marie Wilson
Ford Motor Company
Vehicle Environmental Engineering
Homologation & Compliance
Phone: 313-248-2404 Fax: 313-594-0338
MWILSO18@FORD.COM

From: Ladd, John (J.R.)
Sent: Monday, April 16, 2012 11:17 AM
To: Behnke, David (D.P.)
Cc: Cockerill, Al (C.A.); Wilson, Marie (M.); Howard, Steven (S.M.); Lundy, George (G.L.); Walkowicz, Erin (E.A.)
Subject: RE: Charge Air Cooler - 2011 P415

David, is the subject CAC a regulatory item?

Regards,
John Ladd
Supervisor - Cooling Development Engineering
Ph: (313) 62-16626 Cell: (313) 805-4627
Fax: (313) 317-9241

From: Walkowicz, Erin (E.A.)
Sent: Monday, April 16, 2012 10:56 AM
To: Ladd, John (J.R.); Behnke, David (D.P.)
Cc: Cockerill, Al (C.A.); Wilson, Marie (M.); Howard, Steven (S.M.); Lony, George (G.L.)
Subject: RE: Charge Air Cooler - 2011 P415

John,

2012 MY is the last EWPR that I was responsible for. Dave Behnke is your new contact for current EWPR status of CAC components. From my records of 12 MY, 6K775 was listed as an "X" for the 3.5L GTDI P415 program (which means it was NOT covered for emissions warranty). However, I do not have access to the most recent information. I believe that the RFR was the only GTDI program that was covered for the 12 MY (though again, that may have changed).

Per Steve Howard, 6K775 is not listed in the Certification reportable parts list for 13 MY (and 12 MY as well, I believe).

Dave – please confirm if my direction above is incorrect for EWPR for the Charge Air Cooler.

Erin Walkowicz

Evaporative and Advanced Certification
Allen Park Test Laboratory (APTL) 3BH13
Work Cell (313) 805-6656
Text page: <http://vm7.dearborn.ford.com/cgi/textpage?PAGETO=EWALKOW2>

From: Ladd, John (J.R.)
Sent: Monday, April 16, 2012 8:48 AM
To: Walkowicz, Erin (E.A.)
Cc: Cockerill, Al (C.A.)
Subject: FW: Charge Air Cooler - 2011 P415

Erin, please confirm P415 3.5L GTDI CAC is a regulatory item. Thanks.

Regards,
John Ladd
Supervisor - Cooling Development Engineering
Ph: (313) 62-16626 Cell: (313) 805-4627
Fax: (313) 317-9241

From: Cockerill, Al (C.A.)
Sent: Sunday, April 15, 2012 8:10 PM
To: Ladd, John (J.R.); Mazuchowski, James (J.A.); Madej, Jeanette (J.)
Cc: Wilson, Marie (M.)
Subject: FW: Charge Air Cooler - 2011 P415

FYI this is about compliance reporting to EPA and CARB. John, I thought the CAC was listed as an emissions item. Is it listed as an intercooler and not a charge air cooler?

The spirit, the will to win, and the will to excel are the things that endure. These qualities are so much more important than the events that occur. The harder you work, the harder it is to surrender.

Vince Lombardi

Al Cockerill
RWD V6 Engine System Supervisor

From: Wilson, Marie (M.)
Sent: Tuesday, April 10, 2012 1:00 PM
To: Cockerill, Al (C.A.)
Subject: Charge Air Cooler - 2011 P415

Confirming our discussion today: I did find the charge air cooler described in our emission certification documents. Therefore we should plan to follow up on this item when we have enough information on root cause/corrective actions to determine whether or not a defect exists. I set a reminder for follow up on this note for 6-12-12. Please feel free to contact me any time prior to that date. Otherwise we can circle back and assess the situation at that time. Thanks.


Marie Wilson
Ford Motor Company
Vehicle Environmental Engineering
Homologation & Compliance
Phone: 313-248-2404 Fax: 313-594-0338
MWILSO18@FORD.COM

From: Allan, Valerie (V.J.)
Sent: Wednesday, May 16, 2012 2:52 PM
To: Madej, Jeanette (J.)
Cc: Kramer, Michael (M.T.)
Subject: FW: DENSO CAC Condensate Solutions

Here's the final word from DENSO on misfires due to condensate.

Valerie J. Allan
Ford Motor Company
Powertrain Cooling Heat Exchangers
313-805-4421
vallan@ford.com

From: [ROB BRINKER@denso-diam.com](mailto:ROB_BRINKER@denso-diam.com) [[mailto:ROB BRINKER@denso-diam.com](mailto:ROB_BRINKER@denso-diam.com)]
Sent: Tuesday, May 15, 2012 4:19 PM
To: Allan, Valerie (V.J.)
Subject: DENSO CAC Condensate Solutions


I have confirmed that through out all regions within DENSO the approach is a good defense as opposed to additional management main stream designs for dealing with high humidity situations in CAC systems. Special care is taken to size the outlets to maximize velocity and minimize any area where water could collect. In applications where that is not possible we have worked, with or proposed solutions, that either shut off front end air flow to minimize cooling when not required or bypass CAC within the ducting to prevent cooling and condensing of water in high humidity low cooling need conditions. Additionally we have a design solution for water ingestion from the intake perspective that can be seen in the link to the patent that could be adapted to a CAC, however it is what I would consider a somewhat exotic solution and would need a containment system as opposed to a duck bill drain. Please review and let me know if you have further questions or need for DN on CAC applications.

<http://www.google.com/patents/US20090241515>

Best regards,
Robert Brinker
DENSO International America, Inc.
Telephone (248) 372 - 8807
Cell Phone (248) 763 - 3623

The information contained in and transmitted with this Email may be privileged, proprietary, confidential and protected from disclosure. No privilege is hereby intended to be waived. This Email is intended only for the person to whom it is addressed. If you are not the intended recipient/addressee, any use of the Email and/or its contents, including, but not limited to, dissemination, distribution or copying is strictly prohibited and may be unlawful, and you must not take any action in reliance on it. If you receive this Email in error, please immediately notify the sender and delete the original message and any copies of it from your computer system. We deny any liability for damages resulting from the use of this Email by the unintended recipient, including the recipient in error.

From: Glugla, Chris (C.P.)
Sent: Wednesday, October 12, 2011 8:54 AM
To: Smith, Craig (C.A.); Sims, Ivan (I.D.)
Subject: FW: DTF time extension

I can call in - but would it be more meaningful to have a manager type?

Chris Glugla
Technical Expert Advanced Controls Implementation
Powertrain Controls Research and Development
Research and Innovation Center
2101 Village Road
Dearborn, MI. 48121
Cube 1625.t
Phone: (313) 322-4692
Fax: (313)-2487857
MD: 2036
email: cglugla@ford.com

From: Doyle, Bob (R.J.)
Sent: Wednesday, October 12, 2011 8:51 AM
To: Smith, Craig (C.A.); Hammoud, Mazen (M.); Baum, Joe (J.M.); Payne, Dave (D.L.)
Cc: Sims, Ivan (I.D.); 'Dominski, Joe M'; Glugla, Chris (C.P.); Mazuchowski, James (J.A.); Shimon, Richard (R.L.)
Subject: RE: DTF time extension

Can Richard or Chris attend our scheduling meeting today 9:00? We can figure out our option and develop a plan for containment during that meeting.

Joe D.
Please forward the conference call details to Richard and Chris.

Thanks

From: Smith, Craig (C.A.)
Sent: Wednesday, October 12, 2011 8:46 AM
To: Hammoud, Mazen (M.); Baum, Joe (J.M.); Payne, Dave (D.L.); Doyle, Bob (R.J.)
Cc: Sims, Ivan (I.D.); Dominski, Joe M; Glugla, Chris (C.P.); Mazuchowski, James (J.A.); Shimon, Richard (R.L.)
Subject: RE: DTF time extension

Dave/Bob,

The P415 misfire team requires additional DTF test time as part of our ongoing root cause investigation. Details of our DTF needs are contained within Chris Glugla's note below. The DTF appears to be booked throughout the end of the month per Joe Dominski's note below. Given the other Job1 release pressures on the DTF, we may require additional DTF resources and/or help with crossfunctional prioritization, etc. to secure the requested time. Can you please assist in helping us acquire the requested time?

Joe/Mazen,

In follow-up to Friday's PTIM discussion, we'll likely need help with DTF priority for the P415 GTDI misfire work.

Thanks,
Craig Smith
Supervisor - Engine Calibration
3.5L TIVCT GTDI & 3.5L IVCT GTDI Powerpacks
Phone: (313) 805-6345
TEE Bldg cube 1AD08

From: Dominski, Joe M [<mailto:Joe.Dominski@jacobs.com>]
Sent: Wednesday, October 12, 2011 7:19 AM
To: Glugla, Chris (C.P.)
Cc: Smith, Craig (C.A.); Sims, Ivan (I.D.)
Subject: RE: DTF time extension

We are booked with CD4 and B515 testing and I don't have openings to meet your timing. I don't have a Monday or Tuesday or much of anything open until the week of 10/31.

Joe Dominski
Wind Tunnel Scheduler
313-294-6105

From: Glugla, Chris (C.P.) [<mailto:cglugla@ford.com>]
Sent: Tuesday, October 11, 2011 3:21 PM
To: Dominski, Joe M
Cc: Smith, Craig (C.A.); Sims, Ivan (I.D.)
Subject: DTF time extension
Importance: High

We have been working off TR ab3559 vehicle 566w331 to resolve a Production QSF service action

We need to secure Monday and Tuesday Day shift 8hr blocks for the next 4 weeks beginning 10/17. (no soak, no altitude - just elevated temperatures, and road load + grade + trailer tow loading capability) These dates / times are need to allow critical engineering test support, data analysis, and upper management report out.

After week 3 we will then need to review our progress and potentially secure additional time. The team is prepare to escalate this to the highest management position needed to support this critical f150 misfire warranty issue.

Can you please provide the time we need to perform critical root cause testing.

Chris Glugla
Technical Expert Advanced Controls Implementation
Powertrain Controls Research and Development
Research and Innovation Center
2101 Village Road
Dearborn, MI. 48121
Cube 1625.t
Phone: (313) 322-4692
Fax: (313)-2487857

MD: 2036

email: cglugla@ford.com

NOTICE - This communication may contain confidential and privileged information that is for the sole use of the intended recipient. Any viewing, copying or distribution of, or reliance on this message by unintended recipients is strictly prohibited. If you have received this message in error, please notify us immediately by replying to the message and deleting it from your computer.

From: Andersen, Erik (E.)
Sent: Wednesday, May 08, 2013 6:28 PM
To: Widmann, Carl (C.A.)
Subject: FW: Eco Boost

Info...background on the pressure we're getting.

Erik Andersen
Core P/T Cooling
eanderse@ford.com
313-805-2966

From: Sparks, Douglas (D.S.)
Sent: Wednesday, May 08, 2013 5:01 PM
To: Ricks, Kevin (K.J.); Gardner, Greg (G.D.)
Cc: Kramer, Michael (M.T.); McCoy, Julie (.); Dobbs, Dan (K.D.); Norton, John (J.K.); Madej, Jeanette (J.); Andersen, Erik (E.); Ronzi, Bill (W.C.)
Subject: RE: Eco Boost

Rick,
Our testing priority was to lower the cost of the current Misfire fix. As you know the CAC replacements are driving our WS performance. We tested the 11-12MY F150 with the new lower shield and it proved equal to/better performance than our current 13MY PCA CAC. The team is aggressively completing the DV (retention, system interaction...) of this new shield and is kicking off tooling this week (so the parts are ready when DV is complete). I need to get back with you on DV timing, but the parts will be available before testing is completed. We would like to follow a similar process as we did on the PCA CAC release, and work with FSE to expedite parts into the high humidity regions.

The Team is now testing the new shield on the PCA CAC to further improve its field performance. First level of testing was to aggressive (shield to large blocked to much air flow) and failed for MCT (manifold charge temperature) being too high. The next step is for additional testing with smaller shields that meet the MCT with the new PCA production CAC. This testing will begin next week and should be finished within two weeks. All DV work for shield retention on 11-12MY CAC will apply to the 13MY + CAC.

Please call if you want to discuss further.

Thank you,

Douglas S. Sparks
P/T Quality and PVT Manager FNA
P/T Integration and Program Management (PTIM)
dsparks3@ford.com 313-805-6096

Administrative Assistant: Tina Tessadri
ttessadr 313 594-1115

From: Ricks, Kevin (K.J.)
Sent: Wednesday, May 08, 2013 2:51 PM
To: Sparks, Douglas (D.S.); Gardner, Greg (G.D.)

Cc: Kramer, Michael (M.T.); McCoy, Julie (.); Dobbs, Dan (K.D.); Norton, John (J.K.)

Subject: FW: Eco Boost

Where are we on the progress of this fix, we still have a fair number of customers waiting for the final fix. We have been tracking this concern as a non-QSF but customers and the dealers in most affected areas are eager to get this behind us and have been contacting us repeatedly.

From: Farabee, Todd (T.)

Sent: Wednesday, May 08, 2013 2:40 PM

To: Ricks, Kevin (K.J.); Johnson, Jim (J.S.)

Cc: Uvaydova, Kristina (K.); McClung, Shannon (S.T.); Christoff, Donald (D.A.); Brisson, Richard (R.S.)

Subject: FW: Eco Boost

Kevin & Jim,

Steve Everett is looking for an update from us on the EcoBoost blocker plate fix. Do we have any news to report & can you help answer/respond to his below inquiry?

Sincerely,



Todd G. Farabee • Parts & Service Operations Manager • Orlando Region • Ford Motor Company

tfarabee@ford.com • ph: (425) 241-4704 • fx: (866) 397-3443

From: Steve Everett [<mailto:theboss@langdaleford.com>]

Sent: Wednesday, May 08, 2013 2:23 PM

To: Farabee, Todd (T.)

Cc: Jack Howell; Jack Strayhorn

Subject: Re: Eco Boost

Hey Todd,

You can read this email string to familiarize yourself with this customer's issue or you may recall. This customer has a newer Eco Boost F-150 with the supposedly 'New' part installed but continues to have issues while driving in the rain.

You and I talked on the phone about this issue and you said they were testing another new part and that maybe we could field test it on my customer's truck. He is more than willing and so am I. The problem is not going away and I feel we are headed towards another "Lemon Law" case that neither you or I want to see.

I would appreciate an update on the potential fix for this problem and also the possibility of using my customer to beta test the new part.

Thanks, Steve Everett

----- Original Message -----

From: [Farabee, Todd \(T.\)](mailto:Farabee, Todd (T.))

To: [McClung, Shannon \(S.T.\)](mailto:McClung, Shannon (S.T.))

Cc: 'theboss@langdaleford.com'; [Uvaydova, Kristina \(K.\)](mailto:Uvaydova, Kristina (K.)); [Johnson, Jim \(J.S.\)](mailto:Johnson, Jim (J.S.)); [Christoff, Donald \(D.A.\)](mailto:Christoff, Donald (D.A.)); [Brisson, Richard \(R.S.\)](mailto:Brisson, Richard (R.S.))

Sent: Thursday, April 04, 2013 2:36 PM

Subject: Fw: Eco Boost

Shannon,

Can you please reach out to [REDACTED], to see what we can do to assist with these customer concerns? Thanks.

Sincerely,

Todd G. Farabee
Parts & Service Operations Manager
Orlando Region
Ford Motor Company
cell ph: (425) 241-4704
fx: (866) 397-3443
tfarabee@ford.com

Sent via Blackberry device.

From: Steve Everett [<mailto:theboss@langdaleford.com>]
Sent: Thursday, April 04, 2013 01:53 PM
To: Brisson, Richard (R.S.); Farabee, Todd (T.)
Subject: Eco Boost

Good Afternoon Gentleman,

I hate to burden you with a problem but at this point, I'm not sure what to do.

As you know, we have had a major issue with some F-150 Pick Ups equipped with the 3.5 liter Eco Boost engine. When it rains water is getting into the induction system and the engines either hesitate on acceleration, will not operate over a certain speed or will quit altogether. We all know that it's not occurring on every Eco Boost truck but when it does it is really a problem. I and some of my staff have had several Eco Boost equipped trucks as demos and personally I have never had an issue. We have probably 6-8 customers who we are working with at this time and most of them are simply waiting on the replacement parts that are supposed to take care of the problem, by the way, these parts are on backorder. I have also had one very good customer who we traded back his truck for a V-8 and I had to give him full price for the Eco Boost or lose his business altogether. I also had one other customer that I tried to trade with but he ended up seeking Lemon Law and Ford bought his truck back without a fight.

Now I have a new problem.....A good customer who recently purchased a new Eco Boost equipped F-150 complained of the same problem and when we checked it out, it has the new part already installed that is supposed to fix the concern. Apparently this unit was recently built and is equipped with the new part. Hot Line said there was nothing else we could do and they would take it under advisement. The upset customer called Ford Motor Co. and the person who handled the case told the customer that they were aware of the concern and were working towards a correction and in the meantime, not to drive it in the rain. What kind of answer was that? Now my customer wants to know what I am going to do about his truck. He is a good customer and his wife (who drives a year old Expedition) manages a local Credit Union that finances a lot of vehicles for customers of Langdale Ford.

I do a lot of things at the dealership level to take care of my customers that you all never know about. We pay for repairs that Ford will not, provide rentals when Ford will not and even trade or repurchase vehicles to keep our good customers happy. The problem here is that even if I elect to trade back with the customer I have a truck that I cannot resell.

I am proud and excited to be a Ford Dealer and I love our new products and think our quality has improved tremendously. My concern is that when we have a legitimate problem, Ford does not acknowledge the concern and take appropriate steps to address it. The concern with the Eco Boost has gotten around the community and a few of my customers are hesitant to give it a try. In fact, we are seeing the V-8's start to gain a little traction in recent months. We have a good thing going with the Eco Boost story but we must address these concerns before they become headlines.

I would appreciate some guidance on how to proceed with this particular customer at this time.

Thanks for your time.....Steve Everett, Langdale Ford

No virus found in this message.

Checked by AVG - www.avg.com

Version: 2012.0.2240 / Virus Database: 2641/5724 - Release Date: 04/04/13

From: Madej, Jeanette (J.)
Sent: Tuesday, October 23, 2012 11:05 AM
To: Kramer, Michael (M.T.); Andersen, Erik (E.)
Subject: FW: EcoBoost condensation articles

Jeanette Madej
Global Cooling Systems Manager
Phone: 313-805-0189

-----Original Message-----

From: Smith, Craig (C.A.)
Sent: Tuesday, October 23, 2012 3:42 PM
To: Mazuchowski, James (J.A.); DiMarco, Jackie Marshal (J.M.); Levine, Michael (M.); Gernant, Tim (T.R.)
Cc: Sparks, Douglas (D.S.); Sarkar, Raj (R.); Lapine, Marc (M.J.); Bell, Brian (B.D.); Piechocki, Dawn (D.M.); Dobbs, Dan (K.D.); Madej, Jeanette (J.); Russo, Scott (S.); Norman, Kristofor (K.R.); Baltusis, Paul (P.A.); Hammoud, Mazen (M.)
Subject: RE: EcoBoost condensation articles

Jim,

The misfire-related strategy and calibration changes included the following:

1. Improved misfire detection robustness during multi-cylinder misfire events.
2. Added engine load limiting during misfire FMEM to reduce the probability of component damage.
3. Disabled the flashing MIL when the misfire event occurred in the high rpm/high load operating region that's associated with CAC-condensate-induced misfire events.
4. Minimized the amount of time that's required to clear the FMEM action once the misfire event is no longer present.

Tim,

Anything else to add?

Thanks,
Craig Smith
Supervisor - Engine Calibration
3.5L TIVCT GTDI & 3.5L IVCT GTDI Powerpacks
Phone: (313) 805-6345
TEE Bldg cube 1AD08

-----Original Message-----

From: Mazuchowski, James (J.A.)

Sent: Tuesday, October 23, 2012 7:49 AM

To: DiMarco, Jackie Marshal (J.M.); Levine, Michael (M.); Smith, Craig (C.A.)

Cc: Sparks, Douglas (D.S.); Sarkar, Raj (R.); Lapine, Marc (M.J.); Bell, Brian (B.D.); Piechocki, Dawn (D.M.); Dobbs, Dan (K.D.); Madej, Jeanette (J.); Russo, Scott (S.); Norman, Kristofor (K.R.)

Subject: RE: EcoBoost condensation articles

Deflector shield was an interim fix that reduced the CAC condensate build-up [the amount of water in the CAC]. Testing validated no degradation to vehicle cooling or vehicle performance as a result of the deflector shield add.

Revised CAC is the PCA that also 1) reduces the amount of CAC condensate build-up within the CAC and 2) modifies the air flow thru the CAC which enables regular & consistent stripping away of the condensate build-up.

Again vehicle cooling and vehicle performance not affected with the revised CAC. Our estimation is PCA approx 98% effective, the guy in high humidity, raining, towing a trailer may still have a problem.

Craig Smith could provide the details around the 1st item revised calibration {TSB 12-2-10}.

Jim Mazuchowski

Manager, New V6 Engine Programs

V-Engine Eng'r; 33-79935

-----Original Message-----

From: DiMarco, Jackie Marshal (J.M.)

Sent: Monday, October 22, 2012 9:10 PM

To: Levine, Michael (M.); Mazuchowski, James (J.A.)

Cc: Sparks, Douglas (D.S.); Sarkar, Raj (R.); Lapine, Marc (M.J.); Bell, Brian (B.D.); Piechocki, Dawn (D.M.); Dobbs, Dan (K.D.)

Subject: FW: EcoBoost condensation articles

Importance: High

Mike, see below for TSB details. The relevant details here are that the 6/7/12 TSB offered an improvement but not a full fix. Customers experiencing the issue will be able to get a replacement CAC shortly for a full fix (targeting 10/29/12). All units built after 9/18/12 already have that fix. Our field data, although its early, has indicated no concerns from the field since the new CAC's went online 9/18/12.

I want to be careful that we don't send a bunch of customers unnecessarily to dealers for the fix and run out of service parts/cause a needless warranty spike - please temper the words.

Jim, please provide the technical detail discussed earlier - Mike needs to get ahead of this ASAP.

-----Original Message-----

From: Dobbs, Dan (K.D.)

Sent: Monday, October 22, 2012 11:06 AM

To: DiMarco, Jackie Marshal (J.M.)

Cc: Mazuchowski, James (J.A.); Sparks, Douglas (D.S.); Ricks, Kevin (K.J.); Nowaczyk, Rick (R.J.)

Subject: RE: EcoBoost condensation articles

Jackie, Here you go. We are trying to get the latest TSB out by 10-29-12 (parts inventory is being procured)

TSB 12-2-10 (released 2-15-12)

- * Units built on or before 2-7-12
- * Revised calibration for multiple issues
- * Included an updated FMEM to protect Catalyst

SSM 22225 (released 2-21-12, deactivated 6-7-12)

- * Referred Dealers to use TSB 12-2-10 for a broader spectrum of issues than the TSB addressed

TSB 12-6-4 (released 6-7-12, superceded elements of 12-2-10)

- * Add deflector for units built before 5/24/12
- * Reflash for FMEM and other items
- * For units with P0430 replace the LH Catalyst

New TSB (Yet to be numbered eta = as soon as parts meet launch threshold)

- * Units built before 9-18-12 (KCAP 9-17-12) with the described symptoms (loss of power, and specific DTC's)
- * Applicable units will receive a revised Charge Air Cooler (CAC)
- * Dealer will transfer the previously installed deflector to the new CAC
- * Units not previously flashed under TSB 12-6-4 will be reflashed
- * If code P0430 is present they will replace the LH Catalyst
- * NOTE: We are adding another TSB to handle the few weeks of 2013 production before the revised CAC went in.

From: DiMarco, Jackie Marshal (J.M.)
Sent: Monday, October 22, 2012 10:26 AM
To: Mazuchowski, James (J.A.); Sparks, Douglas (D.S.); Dobbs, Dan (K.D.)
Cc: Levine, Michael (M.); Bell, Brian (B.D.); Scott, Douglas (D.W.); Sarkar, Raj (R.); Lapine, Marc (M.J.); Piechocki, Dawn (D.M.)
Subject: RE: EcoBoost condensation articles

Dan, please summarize latest TSB's regarding 3.5L misfire.

Doug, Jim, can you help with a high level technical description of the improvements we've implemented for misfire? Thanks.

From: Levine, Michael (M.)
Sent: Monday, October 22, 2012 10:05 AM
To: Bell, Brian (B.D.); Scott, Douglas (D.W.); Sarkar, Raj (R.); Lapine, Marc (M.J.); DiMarco, Jackie Marshal (J.M.); Piechocki, Dawn (D.M.)
Subject: RE: EcoBoost condensation articles

Can you please remind me of what the fix is? I'll create a Q&A.

From: Bell, Brian (B.D.)
Sent: Monday, October 22, 2012 10:04 AM
To: Scott, Douglas (D.W.); Sarkar, Raj (R.); Lapine, Marc (M.J.); Levine, Michael (M.); DiMarco, Jackie Marshal (J.M.); Piechocki, Dawn (D.M.)
Subject: EcoBoost condensation articles

FYI - TundraHeadquarters.com posted an article on Oct 18th talking about the condensation issues EcoBoost is having in high humidity areas.

<http://www.tundraheadquarters.com/blog/2012/10/18/ford-f-150-problems-shuddering-power-loss-limp-mode/>

Autospies.com picked up the article over the weekend:

<http://www.autospies.com/news/EcoBoost-F150-Owners-Experiencing-Engine-Problems-Shudder-Stalling-and-Loss-of-Power-73001>

I spoke to Jackie and the fix is in place and is shipping on vehicles now.

Brian

From: Ladd, John (J.R.)
Sent: Monday, April 30, 2012 7:44 AM
To: Kramer, Michael (M.T.); Tyler, Jim (J.S.)
Subject: FW: Emailing: 2013 P415 CAC Condensation Study 20120228.ppt

You guys have this covered?

>Regards,
>John Ladd
>Supervisor - Cooling Development Engineering
>Ph: (313) 62-16626 Cell: (313) 805-4627
>Fax: (313) 317-9241

-----Original Message-----

From: Mazuchowski, James (J.A.)
Sent: Monday, April 30, 2012 7:41 AM
To: Ladd, John (J.R.); Weber, Erik (E.M.)
Cc: Moore, Brian (B.M.); May, David (D.A.); Cockerill, Al (C.A.)
Subject: RE: Emailing: 2013 P415 CAC Condensation Study 20120228.ppt

John, as you work thru this approval on current production 2012 MY, pls make sure you take into account updating 2013 MY P415's. We are just building <TT> vehicles now. Need to make sure we're compatible there as well unless there is a different solution in that timeframe?

Jim Mazuchowski
Manager, New V6 Engine Programs
V-Engine Eng'r; 33-79935

Help me raise \$\$ to fight Multiple Sclerosis

http://main.nationalmssociety.org/site/TR?px=4458825&pg=personal&fr_id=15101&et=GLWrHQdMhjKES SjoqyZpAA..&s_tafId=172675

-----Original Message-----

From: Ladd, John (J.R.)
Sent: Monday, April 30, 2012 7:30 AM
To: Weber, Erik (E.M.)
Cc: Kramer, Michael (M.T.); Rodgers, Thomas (T.A.); Palm, Jim (J.R.); Norman, Kristofor (K.R.); Mazuchowski, James (J.A.); Madej, Jeanette (J.); Lewis, Jeffrey (J.E.)
Subject: RE: Emailing: 2013 P415 CAC Condensation Study 20120228.ppt

The misfire team is looking for a TSE declaration for acceptability of the 6 tube blocker panel across the top of the CAC. You have forwarded me the results, but there isn't any clear statement of acceptability.

PT Cooling is moving forward with the release of the top row blocker panel with mid-May incorporation into production. Your input is required. Thanks.

>Regards,
>John Ladd
>Supervisor - Cooling Development Engineering

>Ph: (313) 62-16626 Cell: (313) 805-4627

>Fax: (313) 317-9241

-----Original Message-----

From: Weber, Erik (E.M.)

Sent: Monday, April 23, 2012 10:18 AM

To: Ladd, John (J.R.)

Subject: Emailing: 2013 P415 CAC Condensation Study 20120228.ppt

Your message is ready to be sent with the following file or link attachments:

2013 P415 CAC Condensation Study 20120228.ppt

Note: To protect against computer viruses, e-mail programs may prevent sending or receiving certain types of file attachments. Check your e-mail security settings to determine how attachments are handled.

From: Smith, Craig (C.A.)
Sent: Wednesday, August 01, 2012 9:47 AM
To: Hammoud, Mazen (M.); Baum, Joe (J.M.); Devries, Jason (J.E.); Whitehead, Joseph (J.P.); Dobson, Kevin (K.E.); Ducklow, Corey (C.S.); Pierce, Michael (M.A.)
Subject: FW: F-150 3.5I GTDI Continued Misfire Aft TSB is at Emerging Level
Importance: High

Unfortunately, It does not look like the P415 GTDI CAC tube blocker plate ICA was very successful at mitigating condensate misfires. Per FCSD's note below, the condensate misfire issue is back as an emerging concern and could quickly escalate to QSF. A vast majority of our V52, as well as a significant portion of our V40 & V29 TGWs, are associated with misfires due to CAC condensation. To my knowledge, there are no longer plans to investigate grill shutters on P415 so hopefully the revised CAC design that's going into production this September will be a more effective fix.

Thanks,
Craig Smith
Supervisor - Engine Calibration
3.5L TIVCT GTDI & 3.5L IVCT GTDI Powerpacks
Phone: (313) 805-6345
TEE Bldg cube 1AD08

From: McDonagh, Scot (S.M.)
Sent: Wednesday, August 01, 2012 9:36 AM
To: Sparks, Douglas (D.S.); Madej, Jeanette (J.); Mazuchowski, James (J.A.); Dixon, Mark (M.R.); Smith, Craig (C.A.)
Subject: FW: F-150 3.5I GTDI Continued Misfire Aft TSB is at Emerging Level
Importance: High

INFO



Scot G. McDonagh
PT Quality Engineering
Phone: (313)337-8091
smcdonag@ford.com

From: Nowaczyk, Rick (R.J.)
Sent: Wednesday, August 01, 2012 8:58 AM
To: McDonagh, Scot (S.M.)
Cc: Dobbs, Dan (K.D.)
Subject: F-150 3.5I GTDI Continued Misfire Aft TSB is at Emerging Level
Importance: High

Scot,

Not good news. The F-150 3.5L GTDI continued misfire in damp/humid condition after TSB 12-6-4 has reached Emerging Level now (two units are being bought back). In addition, I have a folder for unit's built from production with the misfire under the same conditions which is also at Emerging level. I think our plan is to open an Emerging concern on the TSB side and add the reports for units built the deflector still having a concern. However, this could move to QSF quickly combining the two folders.

Regards,
Rick Nowaczyk
FCSD Product Concern Engineer
F-150, Freestar/Monterey, Ford GT, Th!nk
E-mail: rnowaczy@ford.com
Diagnostic Service Center-I, Allen Park
PH# 313-322-7251

Subject: P415 Misfire CAC Release
Location: Teleconference: x13673 Passcode: 21340179#

Start: Fri 8/3/2012 9:00 AM
End: Fri 8/3/2012 9:30 AM

Recurrence: (none)

Meeting Status: Meeting organizer

Organizer: McDonagh, Scot (S.M.)
Required Attendees: Kramer, Michael (M.T.); Dixon, Mark (M.R.) (mdixon@ford.com); Wagner, Glen (G.C.); Nowaczyk, Rick (R.J.); Dobbs, Dan (K.D.); Tyler, Jim (J.S.)

Please join the Powertrain Quality Team to discuss Production & Service release of new P415 3.5L GTDI Charge Air Cooler. Thanks



RE: 2012 P415 3.5L GTDI CAC Release
08/03/2012 09:00 AM

Scot G. McDonagh
PT Quality Engineering
Phone: (313)337-8091
smcdonag@ford.com

From: McDonagh, Scot (S.M.)
Sent: Tuesday, July 31, 2012 12:00 PM
To: Kramer, Michael (M.T.); Tyler, Jim (J.S.)
Cc: Nowaczyk, Rick (R.J.); Dobbs, Dan (K.D.); Wagner, Glen (G.C.)
Subject: RE: 2012 F-150 3.5I GTDI Continued aft Misfire TSB (CQIS Report#CGJCV013)

I will set up a meeting with FCSD for next week to discuss plan for PCA CAC service release

Scot G. McDonagh
PT Quality Engineering
Phone: (313)337-8091
smcdonag@ford.com

From: Kramer, Michael (M.T.)
Sent: Tuesday, July 31, 2012 10:17 AM
To: McDonagh, Scot (S.M.)
Cc: Tyler, Jim (J.S.)
Subject: FW: 2012 F-150 3.5I GTDI Continued aft Misfire TSB (CQIS Report#CGJCV013)

Note request for review of CAC 6 tube blocker shield to ensure clarity. We should also begin discussions on the TSB/s for the revised CAC PCA. When?

Mike Kramer
RWD PT Cooling Supv.
Six Sigma Black Belt
Cell Phone: (313) 805-0190
Text Page: mkramer1
Page from outside Ford, External email: mkramer1@ford.com

From: Madej, Jeanette (J.)
Sent: Tuesday, July 31, 2012 10:08 AM
To: Gardner, Greg (G.D.); Sparks, Douglas (D.S.)
Cc: Kramer, Michael (M.T.)
Subject: RE: 2012 F-150 3.5I GTDI Continued aft Misfire TSB (CQIS Report#CGJCV013)

I think we should review and make sure it's ok

Jeanette Madej
Global Cooling Systems Manager
Phone: 313-805-0189

From: Gardner, Greg (G.D.)
Sent: Monday, July 23, 2012 12:44 PM
To: McDonagh, Scot (S.M.); Sparks, Douglas (D.S.); Madej, Jeanette (J.); Mazuchowski, James (J.A.); Ricks, Kevin (K.J.); Mazuchowski, James (J.A.); Norman, Kristofor (K.R.)
Subject: RE: 2012 F-150 3.5I GTDI Continued aft Misfire TSB (CQIS Report#CGJCV013)

I had some time today and reviewed a portion of the repeat claims in this file ... I looked at 23 of the repeat claims and noted the following:

1. 7 of the 23 repeats or 30% did not have the TSB properly performed, 3 of the 6 had a P0430 code present at initial service and even though the TSB states to replace the catalyst the dealer did not complete a catalyst

repair. Of these three, two of them did not get a CAC shield on the first visit ... one vehicle had shield installed on the second visit, one has never had the shield installed. Of the other four claims, one was a surge complaint, recal was done per TSB but no CAC shield was installed, another has been in to dealer twice and been reflashed but no CAC shield has been installed, one did not get the TSB performed even though the codes pointed to the TSB, and the last one did not get the shield installed on either visit but did set a P0430 between first and second visit and ended up with a new CAC.

- Of the remaining claims in the 23 repeats, 5 were actual misfire repeats where the TSB was completed correctly and the vehicle had a subsequent claim for misfire and the remainder were repeats for non misfire related concerns, second claims for part installation when the shield was not available on the first visit, or two claims on the first day for unrelated issues

Based on this data, the effectiveness of the misfire fix looks very good but I am somewhat concerned with the number of vehicles that are not getting the TSB properly performed. Do we need to review the TSB and make sure that it is written clearly enough? Is it possible to bold the section on replacing the catalyst if a P0430 claim is present? Also, is there some automated way in the warranty system to identify when a 120604A or 120604B labor op occurs on a pre-containment vehicle (i.e. built before May 17, 2012) but no catalyst shield or push-pin parts show up on the claim?

Not Repeats	TSB Improper		
1		Line 8 and 9	(Claims occurred on same day, one for misfire fix, one for coil replacement) (Dealer did not follow TSB ... there was a P0430 code and they installed)
1	1	Lines 11 and 12	(Not a steady state misfire claim, surge complaint and then misfire)
1	1	Lines 21 and 22	(Two separate claims, one for misfire, one for surge on the same day)
1		Lines 25 and 26	(Misfire TSB performed, issue was not steady state misfire, dealer replaced coil)
1		Lines 37 and 38	(Claims occurred on same day, one claim entered for misfire TSB performed)
1		Lines 50 and 51	(One claim for ordering parts, one claim for installing parts)
1		Lines 57 and 58	(First claim was NPF, second claim cylinder #2 coil was replaced)
1		Lines 66 and 67	(Complaint was shudder up hill, final repair was to repair front pump)
1		Lines 72 and 73	(Two complaints on same day, first was surge, TSB performed, second was misfire)
1	1	Lines 94 and 95	(TSB not performed properly, vehicle had P0430 and cat not replaced)
1	1	Lines 96 and 97	(TSB performed, follow-up visit to replace fouled plug and coil)
1		Lines 132 and 133	(Two claims on same day, one for misfire, one for reported fuel economy)
1		Lines 134 and 135	(TSB not performed properly, P0430 code and cat not replaced)
1	1	Lines 136 and 137	(TSB not performed properly, no CAC shield installed, vehicle had misfire)
0	1	Lines 143 and 144	(TSB not performed even though SSM points to misfire TSB based on codes)
0	1	Lines 155 and 156	(Two claims on same day, one for surge and one for crank issue)
1		Lines 168 and 169	(Two claims on same day, one for misfire fix, one for coil replacement)
1		Lines 170 and 171	(First claim for misfire, second claim was for poor fuel economy)
1		Lines 225 and 226	(Two claims for misfire at same dealer, PCM reprogrammed but no shield)
1	1	Lines 227 and 228	(Two claims for misfire at same dealer, PCM reprogrammed but no shield)
18	7		
	Summary	Claims	205
		Repeat Claims	23
		Repeats and TSB Not Followed	7
		Effectiveness	97%
		Effectiveness if TSB Properly Followed	98%

Gregory D. Gardner

Global Powertrain Quality Manager

Building 2, Mail Drop 1213
Cell: 313-805-8999 Desk: 734-523-5377

From: McDonagh, Scot (S.M.)
Sent: Thursday, July 19, 2012 11:50 AM
To: Sparks, Douglas (D.S.); Gardner, Greg (G.D.); Madej, Jeanette (J.); Mazuchowski, James (J.A.); Ricks, Kevin (K.J.)
Subject: FW: 2012 F-150 3.5I GTDI Continued aft Misfire TSB (CQIS Report#CGJCV013)

INFO

[Scot G. McDonagh](#)
PT Quality Engineering
Phone: (313)337-8091
smcdonag@ford.com

From: Ng, Paul (P.K.)
Sent: Thursday, July 19, 2012 11:44 AM
To: McDonagh, Scot (S.M.)
Cc: Dixon, Mark (M.R.); Kramer, Michael (M.T.); Steslicki, Michael (M.E.); Nowaczyk, Rick (R.J.)
Subject: RE: 2012 F-150 3.5I GTDI Continued aft Misfire TSB (CQIS Report#CGJCV013)

Scot,

There are 580 VINs as of yesterday that have went through TSB 12-6-4. 57 of the VINs have subsequent repairs to fix similar symptoms (CCCs and/or DTCs). The calculated effective for the TSB is 90% provided that the repeat repairs were valid.

Paul

From: McDonagh, Scot (S.M.)
Sent: Wednesday, July 18, 2012 12:56 PM
To: Ng, Paul (P.K.)
Cc: Dixon, Mark (M.R.); Kramer, Michael (M.T.); Steslicki, Michael (M.E.); Nowaczyk, Rick (R.J.)
Subject: FW: 2012 F-150 3.5I GTDI Continued aft Misfire TSB (CQIS Report#CGJCV013)

How many AWS claims to date for TSB 12-06-04 ? Original estimate was 60% effective repair rate for CAC Deflector. Would like to know % based on TSB usage with 12 vehicles unresolved. Thanks

OPERATION	DESCRIPTION	TIME
120604A	2011-2012 F-150 3.5L GTDI: Check DTCs, Install CAC Air Deflector Plate if Necessary And Reprogram The PCM (Do Not Use With Any Other Labor Operations)	0.5 Hr.
120604B	2011-2012 F-150 3.5L GTDI: Check DTCs, Replace The Left Catalytic Converter, Install CAC Air Deflector Plate if Necessary And Reprogram The PCM (Do Not Use With Any Other Labor Operations)	1.0 Hr.

[Scot G. McDonagh](#)
PT Quality Engineering
Phone: (313)337-8091
smcdonag@ford.com

From: Nowaczyk, Rick (R.J.)
Sent: Wednesday, July 18, 2012 12:12 PM
To: McDonagh, Scot (S.M.)
Subject: RE: 2012 F-150 3.5l GTDI Continued aft Misfire TSB (CQIS Report#CGJCV013)

Looks like...

7 reports for vehicle built after the cutoff date

4-5 reports for vehicles still having the concern after the TSB was performed.

11-12 Total...

From: McDonagh, Scot (S.M.)
Sent: Wednesday, July 18, 2012 10:59 AM
To: Nowaczyk, Rick (R.J.)
Subject: RE: 2012 F-150 3.5l GTDI Continued aft Misfire TSB (CQIS Report#CGJCV013)

What is total count for vehicles not fixed with Deflector ?

[Scot G. McDonagh](#)
PT Quality Engineering
Phone: (313)337-8091
smcdonag@ford.com

From: Nowaczyk, Rick (R.J.)
Sent: Wednesday, July 18, 2012 10:20 AM
To: Madej, Jeanette (J.); McDonagh, Scot (S.M.); Kramer, Michael (M.T.); Ladd, John (J.R.); Sowards, John (J.)
Cc: Chatfield, David (D.); Ricks, Kevin (K.J.); Dobbs, Dan (K.D.); Oyafuso, Kevin (K.G.); Smith, Craig (C.A.); Dixon, Mark (M.R.); Sparks, Douglas (D.S.); Mazuchowski, James (J.A.); Nowaczyk, Rick (R.J.)
Subject: RE: 2012 F-150 3.5l GTDI Continued aft Misfire TSB (CQIS Report#CGJCV013)
Importance: High

Jeanette,
Any updates on this per your comment below?

From: Madej, Jeanette (J.)
Sent: Friday, July 13, 2012 2:57 PM
To: McDonagh, Scot (S.M.); Nowaczyk, Rick (R.J.); Kramer, Michael (M.T.); Ladd, John (J.R.); Sowards, John (J.)
Cc: Chatfield, David (D.); Ricks, Kevin (K.J.); Dobbs, Dan (K.D.); Oyafuso, Kevin (K.G.); Smith, Craig (C.A.); Dixon, Mark (M.R.); Sparks, Douglas (D.S.); Mazuchowski, James (J.A.)
Subject: RE: 2012 F-150 3.5l GTDI Continued aft Misfire TSB (CQIS Report#CGJCV013)

We will discuss on Monday and get back to you

From: McDonagh, Scot (S.M.)
Sent: Wednesday, July 11, 2012 7:53 AM
To: Nowaczyk, Rick (R.J.); Kramer, Michael (M.T.); Ladd, John (J.R.); Sowards, John (J.)
Cc: Chatfield, David (D.); Ricks, Kevin (K.J.); Dobbs, Dan (K.D.); Oyafuso, Kevin (K.G.); Smith, Craig (C.A.); Dixon, Mark (M.R.); Madej, Jeanette (J.); Sparks, Douglas (D.S.); Mazuchowski, James (J.A.)
Subject: RE: 2012 F-150 3.5l GTDI Continued aft Misfire TSB (CQIS Report#CGJCV013)

Thanks Rick- It is my understanding the Deflector is ICA for CAC condensate Misfire. Will ask PT Cooling for update on PCA Service proposals.

Scot G. McDonagh
PT Quality Engineering
Phone: (313)337-8091
smcdonag@ford.com

From: Nowaczyk, Rick (R.J.)
Sent: Tuesday, July 10, 2012 4:42 PM
To: McDonagh, Scot (S.M.); Oyafuso, Kevin (K.G.); Smith, Craig (C.A.); McDonagh, Scot (S.M.); Dixon, Mark (M.R.)
Cc: Chatfield, David (D.); Ricks, Kevin (K.J.); Dobbs, Dan (K.D.); Nowaczyk, Rick (R.J.)
Subject: 2012 F-150 3.5l GTDI Continued aft Misfire TSB (CQIS Report#CGJCV013)
Importance: High

Powertrain Team,
Here is another case were the dealer performed the TSB for the misfire and the customer still experienced the condition when raining. The issue in this case this customer appears to have purchased 13 trucks for their company. If this TSB is going to be the final fix, we may need to look at communication to the field that if condition are right this concern may still occur.

Thanks....

From: DCHATFIE@ford.com [mailto:DCHATFIE@ford.com]
Sent: Tuesday, July 10, 2012 4:05 PM
To: Nowaczyk, Rick (R.J.)
Cc: Chatfield, David (D.)
Subject: Report Summary for the CQIS Report#CGJCV013

2012 misfire under load, tsb performed. Loaction Memphis, Tn.

Attachments : 0

Report# :	CGJCV013 NHL	Received:	07/10/2012
CCRG/EPRC:		Date:	
Vehicle:	2012,F150 4X4 ,F150 ,SUP CRW,STYSD ,1FTFW1ET0CF [REDACTED]	Build Date:	01/21/2012
Odometer :	8,386 M	Engine:	3.5L-GTDI
Transmission:	6R80E	Calibration:	CF613C0A
		A/C:	YES
Dealer:	USA 06422 Butch Oustalet, Inc.	Phone#:	(228) 863-5525
City:	Gulfport	State:	Mississippi
		Country :	USA
Originator:	BEN PRIESTER		
Symptom:	5 50 2 39 DRV PERF,RUNS ROUGH,ACCEL,INTERMITTENT		
Status:			
VFG:	V52 DRIVEABILITY		
Additional Symptom:	BUCKS AND JERKS WHEN RAINING		

Fix: Causal Component :

Condition Code:

Hotliner: DCHATFIE

Phone: 313 317-6315

Regn Cd: C3 Memphis

Engineering:

Phone:

TAR:

Dlr Contact: BEN PRIESTER

Phone: 000 000-0000

Title Cde: OT

DTCs:

KOEO:

KOEC:

KOER:

Comments

:

REPAIR 07/10/2012 03:58PM DAVID CHATFIELD MSS - FCSD - TECH SVC HOTLINE
WEB FORM DATA - CONCERN:CUST WAS DRIVING HIS TRUCK IN THE RAIN AND IT
STARTED BUCKING AND JERKING DIAGNOSTICS: RUN DIAGNOSIS NO CODES WE
HAXE ALREADY DONE TSB 12-6-4 LAST REPAI PARTS REPLACED:NONE TECH
QUESTION:THIS TRUCK CONTINUES TO HAVE PROBLEM WHEN DRIVING IN THE
RAIN. HAVE HAD IN THE SHOP 3 TIMES BEFORE. DONT KNOW WERE TO GO WITH
IT. THIS CUST OWN A COMPANY THAT BOUGHT 13 TRUCKS FROM US LAST YEAR
AND I VE GOT TO FIND A SOLUTION. ARE THER ANY LATER UPDATES OR
SUGGESTIONS FOR THIS

RECOMM 07/10/2012 03:58PM DAVID CHATFIELD MSS - FCSD - TECH SVC HOTLINE
BEN, DUE TO THE EFFICIENCY OF THE CHARGE AIR COOLER, THERE MAY BE
SOME CONDITIONS WHERE SOME CONDENSATION BUILDS IN THE CAC, EVEN
WITH
THE CAC SHIELD IN PLACE AND IS INJECTED INTO THE ENGINE. VERY WET OR
EXTREMELY HUMID CONDITIONS MAY ENHANCE THIS CONCERN. THE SHIELD
WAS
DESIGNED TO HELP WITH LESS CONDENSATION BUILD UP, BUT DUE TO HUMID
CONDITIONS AND COMPRESSED AIR IN THE CAC, THIS WILL NOT TOTALLY
ELIMINATE THE CONDENSATION FROM FORMING UNDER THESE CONDITIONS. AT
THIS TIME, IF WATER HAS BEEN VERIFIED IN THE CAC, AIS AND AROUND THE
THROTTLE BODY, CLEAN THE WATER AS BEST AS POSSIBLE AND INFORM THE
CUSTOMER OF THE DESIGN OF THE SYSTEM AND THE POSSIBLY OF
CONDENSATION
BUILD-UP UNDER THESE CONDITIONS.

FORD:

2011-2012 F-150

ISSUE

Some 2011-2012 F-150 vehicles built on or before 5/24/2012 and equipped with a 3.5L gasoline turbocharged direct injection (GTDI) Ecoboost engine exhibit a steady or flashing malfunction indicator lamp (MIL) with various diagnostic trouble codes (DTC) and drivability concerns.

ACTION

Follow the Service Procedure steps to correct the condition.

SERVICE PROCEDURE

The calibration update contains improvement actions and enhancements to address the following conditions:

- Intermittent stumble and/or misfire on hard acceleration after an extended drive at highway speeds being more noticeable during humid or damp conditions.
- Intermittent engine surge during moderate to light loads at cruise.
- Powertrain control module (PCM) Misfire DTC P030x.
- PCM DTC P0430 and/or P0299.

NOTE

INSURE ALL HARD FAULT POWERTRAIN DTCS ARE ADDRESSED PRIOR TO PERFORMING THE CALIBRATION UPDATE.

1. Check for DTC P0430. Is DTC P0430 present?
 - a. Yes - Replace the left bank catalytic converter assembly. Refer to Workshop Manual (WSM), Section 309-00. Proceed to Step 2.
 - b. No - Proceed to Step 2.
2. Is the Charge Air Cooler (CAC) equipped with an air deflector plate? (Figure 1A)




Figure 1 - Article 12-6-4

- a. Yes - Proceed to Step 4.
- b. No - Proceed to Step 3.
3. Install CAC air deflector plate with two new push pins. (Figure 1B) Proceed to step 4.
4. Reprogram the PCM to the latest calibration using IDS release 79.02A or higher. This new calibration is not included in the 2012.5 DVD. Calibration files may also be obtained at www.motorcraft.com.

NOTE

PLEASE ADVISE THE CUSTOMER THAT THIS VEHICLE IS EQUIPPED WITH AN ADAPTIVE TRANSMISSION SHIFT STRATEGY WHICH ALLOWS THE VEHICLE'S COMPUTER TO LEARN THE TRANSMISSION'S UNIQUE PARAMETERS AND IMPROVE SHIFT QUALITY. WHEN THE ADAPTIVE STRATEGY IS RESET, THE COMPUTER WILL BEGIN A RE-LEARNING PROCESS. THIS RE-LEARNING PROCESS MAY RESULT IN FIRMER THAN NORMAL UPSHIFTS AND DOWNSHIFTS FOR SEVERAL DAYS.

NOTE: The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford or Lincoln dealership to determine whether the Bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supersede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.

TSB 12-6-4 (Continued)

PART NUMBER	PART NAME
BL3Z-5E212-E	Catalytic Converter Assembly
W520514-S440	Nuts (2 Req)
CL3Z-19E672-A	Deflector Plate
W711281-S300	Push Pin (2 Req)

120604B 2011-2012 F-150 3.5L 1.0 Hr.
 GTDI: Check DTCs,
 Replace The Left Catalytic
 Converter, Install CAC Air
 Deflector Plate if
 Necessary And Reprogram
 The PCM (Do Not Use
 With Any Other Labor
 Operations)

WARRANTY STATUS: Eligible Under Provisions Of
 New Vehicle Limited
 Warranty Coverage And
 Emissions Warranty
 Coverage
 Warranty/ESP coverage
 limits/policies/prior approvals
 are not altered by a TSB.
 Warranty/ESP coverage
 limits are determined by the
 identified causal part and
 verified using the OASIS
 part coverage tool.

DEALER CODING

BASIC PART NO.
 5E212 (OPERATION B)
 6K775 (OPERATION A)

CONDITION
 CODE
 12
 42

OPERATION	DESCRIPTION	TIME
120604A	2011-2012 F-150 3.5L GTDI: Check DTCs, Install CAC Air Deflector Plate if Necessary And Reprogram The PCM (Do Not Use With Any Other Labor Operations)	0.5 Hr.

From: McDonagh, Scot (S.M.)
Sent: Tuesday, September 04, 2012 12:00 PM
To: Dixon, Mark (M.R.); Ronzi, Bill (W.C.); Smith, Craig (C.A.); Oyafuso, Kevin (K.G.); McCoy, Jim (D.)
Subject: FW: F-150 EcoBoost - Olliver

We are installing 27mm PCA CACs in (2) P415 GTDI customer vehicles at buy back status

Scot G. McDonagh
PT Quality Engineering
Phone: (313)337-8091
smcdonag@ford.com

From: Nowaczyk, Rick (R.J.)
Sent: Friday, August 31, 2012 3:20 PM
To: Tyler, Jim (J.S.); Ricks, Kevin (K.J.); Kramer, Michael (M.T.); McDonagh, Scot (S.M.); Hanson, Chris (C.)
Cc: Arledge, Lynn (L.); Sparks, Douglas (D.S.); Dobbs, Dan (K.D.)
Subject: RE: F-150 EcoBoost - Olliver

Yes, thanks Jim.

The two CAC assemblies are shipping out FedEx this afternoon. Thanks again to everyone for all their help.

From: Tyler, Jim (J.S.)
Sent: Friday, August 31, 2012 3:16 PM
To: Nowaczyk, Rick (R.J.); Ricks, Kevin (K.J.); Kramer, Michael (M.T.); McDonagh, Scot (S.M.); Hanson, Chris (C.)
Cc: Arledge, Lynn (L.); Sparks, Douglas (D.S.); Dobbs, Dan (K.D.)
Subject: RE: F-150 EcoBoost - Olliver

Note to all...Rick received two BL34-9L440-AE PCA CACs at 2:20pm today.

Sent with Good (www.good.com)
Jim Tyler
T1/P552 Cooling
313-805-2565

-----Original Message-----

From: Nowaczyk, Rick (R.J.)
Sent: Friday, August 31, 2012 01:10 PM Eastern Standard Time
To: Tyler, Jim (J.S.); Ricks, Kevin (K.J.); Kramer, Michael (M.T.); McDonagh, Scot (S.M.); Hanson, Chris (C.)
Cc: Arledge, Lynn (L.); Sparks, Douglas (D.S.); Dobbs, Dan (K.D.)
Subject: RE: F-150 EcoBoost - Olliver

Jim,

Left you a voice mail message. If you can bring them over that would be great. I am vacation for Tuesday, but will be back Wednesday.

From: Tyler, Jim (J.S.)
Sent: Friday, August 31, 2012 10:34 AM
To: Nowaczyk, Rick (R.J.); Ricks, Kevin (K.J.); Kramer, Michael (M.T.); McDonagh, Scot (S.M.); Hanson, Chris (C.)
Cc: Arledge, Lynn (L.); Sparks, Douglas (D.S.); Dobbs, Dan (K.D.)
Subject: RE: F-150 EcoBoost - Olliver

Rick, two BL34-9L440-AE service CACs arrived at Bld-1 this morning. Currently the parts are being released from the shipping dock to my desk. Are you available around 11-11:15? I can bring them to you.

Jim Tyler
T1/P552 Cooling
313-805-2565 Bld-2 23P25

From: Nowaczyk, Rick (R.J.)
Sent: Thursday, August 30, 2012 12:35 PM
To: Ricks, Kevin (K.J.); Kramer, Michael (M.T.); McDonagh, Scot (S.M.); Hanson, Chris (C.)
Cc: Arledge, Lynn (L.); Sparks, Douglas (D.S.); Tyler, Jim (J.S.); Dobbs, Dan (K.D.)
Subject: RE: F-150 EcoBoost - Olliver

Yes, Jim Tyler please work with me on these. I just spoke to the FSE (Chris Hall) on this vehicle to let him know we are getting a CAC for this customer. I will be shipping this one directly to the FSE and he can carry it into the dealer once they schedule the customer in for the repair. Thanks everyone for all their help on this one.

From: Ricks, Kevin (K.J.)
Sent: Thursday, August 30, 2012 12:17 PM
To: Nowaczyk, Rick (R.J.); Kramer, Michael (M.T.); McDonagh, Scot (S.M.); Hanson, Chris (C.)
Cc: Arledge, Lynn (L.); Sparks, Douglas (D.S.); Tyler, Jim (J.S.); Dobbs, Dan (K.D.)
Subject: RE: F-150 EcoBoost - Olliver

Rick is FCSD lead for coordination of repairs / availability.

From: Nowaczyk, Rick (R.J.)
Sent: Thursday, August 30, 2012 11:58 AM
To: Kramer, Michael (M.T.); Ricks, Kevin (K.J.); McDonagh, Scot (S.M.); Hanson, Chris (C.)
Cc: Arledge, Lynn (L.); Sparks, Douglas (D.S.); Tyler, Jim (J.S.)
Subject: RE: F-150 EcoBoost - Olliver

We need to make this one customer listed below a top priority and get a CAC for this customer ASAP. From my understanding Shannon has been able to hold off her customer for a little while longer. I have attached the GCQIS report for this vehicle.

Chris Hanson, do you know who the FSE is that handles dealer P/A 04991.

From: Kramer, Michael (M.T.)
Sent: Thursday, August 30, 2012 11:23 AM
To: Ricks, Kevin (K.J.); McDonagh, Scot (S.M.)
Cc: Arledge, Lynn (L.); Sparks, Douglas (D.S.); Tyler, Jim (J.S.); Nowaczyk, Rick (R.J.)
Subject: RE: F-150 EcoBoost - Olliver

We are following up on an unfilled order. This would satisfy attached and Rick's previous request. Parts by mid-next week should be reasonable, however, need to confirm delivery date.

Mike Kramer
RWD PT Cooling Supv.

Six Sigma Black Belt

Cell Phone: (313) 805-0190

Text Page: mkramer1

Page from outside Ford, External email: mkramer1@ford.com

From: Ricks, Kevin (K.J.)
Sent: Thursday, August 30, 2012 11:09 AM
To: McDonagh, Scot (S.M.); Kramer, Michael (M.T.)
Cc: Arledge, Lynn (L.); Sparks, Douglas (D.S.)
Subject: FW: F-150 EcoBoost - Olliver
Importance: High

Scot, high visibility customer, can we get a new CAC?

From: Berardi, Michael (M.A.)
Sent: Thursday, August 30, 2012 9:40 AM
To: Arledge, Lynn (L.)
Cc: Ricks, Kevin (K.J.)
Subject: RE: F-150 EcoBoost - Olliver
Importance: High

Kevin, When can we get a cooler for this customer? Can we pull one ahead?

Mike Berardi
Director - Service Engineering Operations
Ford Customer Service Division
Administrative Assistant - Sandy Schwartzenberger (38468)
Phone - (313) 323-8467
Fax - (313) 845-2580

Share the Ford Story at www.TheFordStory.com
Save Paper - Do not print this email unless absolutely necessary

From: Arledge, Lynn (L.)
Sent: Wednesday, August 29, 2012 3:49 PM
To: Berardi, Michael (M.A.); Scott, Douglas (D.W.)
Subject: FW: F-150 EcoBoost - Olliver

Mike,

I've been speaking with the customer below. He has retained an attorney, but is still willing to work with Ford if we can resolve this issue. Do you have an approximate date in September for the new cooler?

Thanks,

Privileged and Confidential

Lynn Arledge
Senior Executive Representative
Ford Executive Offices - CCGO
Ford Motor Company

(313) 845-5808
Email: larledge@ford.com

From: Sloan, Jeffrey (J.)
Sent: Wednesday, August 22, 2012 6:36 PM
To: Tansil-Marshall, Robin (R.)
Cc: Berardi, Michael (M.A.)
Subject: FW: F-150 EcoBoost

Robin,

Please provide this additional information to the EL Agent.

Not certain we need to do an RAV if it can be fixed. Please send Mile and I a closing report.

Thank you

Sent with Good (www.good.com)

-----Original Message-----

From: Berardi, Michael (M.A.)
Sent: Wednesday, August 22, 2012 05:12 PM Eastern Standard Time
To: Czubay, Kenneth (M.); Scott, Douglas (D.W.); Sloan, Jeffrey (J.)
Subject: RE: F-150 EcoBoost

We have a Technical Service Bulletin (TSB) on an engine misfire in high humidity areas or during the rain. The TSB involves a new calibration and a deflector for the cooler and fixes most of the concerns. There are some instances where this will not repair it completely in certain geographic areas, and engineering is working on a new cooler which should be available in September. I suggest we expedite the part for the customer as soon as it is available.

Jeff – Question – Would we lose money on a trade assist if the customer paid the difference (A to A) and mileage? I would assume the truck should bring a decent buck at auction, but you're the expert.

Mike Berardi
Director - Service Engineering Operations
Ford Customer Service Division
Administrative Assistant - Sandy Schwartzenberger (38468)
Phone - (313) 323-8467
Fax - (313) 845-2580

Share the Ford Story at www.TheFordStory.com
Save Paper - Do not print this email unless absolutely necessary

From: Czubay, Kenneth (M.)
Sent: Tuesday, August 21, 2012 9:15 AM
To: Sloan, Jeffrey (J.)
Cc: Berardi, Michael (M.A.); Scott, Douglas (D.W.)
Subject: FW: F-150 EcoBoost

Hi Jeff

I have not seen another note about this issue. Mike/Doug ??? thanks ken

Kenneth M Czubay
Vice President
US Marketing, Sales and Service

Go Ford !!

From: Mulally, Alan (A.R.)
Sent: Tuesday, August 21, 2012 5:32 AM
To: Czubay, Kenneth (M.)
Subject: FW: F-150 EcoBoost

From: [REDACTED]
Sent: Monday, August 20, 2012 6:21 PM
To: Mulally, Alan (A.R.)
Subject: F-150 EcoBoost

Mr. Mulally

Would be very surprise if you even are the one that reads this, but as I am sure you know you have a problem with your F-150 EcoBoost intercooler that engineering is not coming up with a fix they are trying but are not succeeding.

Mine is really bad and came close a couple of times to a very bad accident, and I have tried to work it out with customer service(which has been very nice) but they say Ford will not trade me for a V8.

I am not asking for my money back and moving to a Chevy, I am asking for to be moved into the same truck but a V8 or give me a trade in allowance for what I paid and I will buy a V8 or a Raptor.

Now we are a Ford Family

[REDACTED] 011 FX4
[REDACTED] 2012 Ford Fusion
[REDACTED] daughter Grad school 2012 Focus
[REDACTED] son Naval Officer 2012 Escape

as you see we are a Ford family please give this some consideration

My truck Vin number is 1FTFX1ET4BF [REDACTED]

[REDACTED]

Please if you are not going to respond or help do not send back to customer service

From: Smith, Craig (C.A.)
Sent: Friday, February 01, 2013 11:36 AM
To: Leisenring, Kenneth (K.C.)
Subject: FW: F150 GTDI AIS Water Ingestion
Signed By: csmith24@ford.com

Ken,

Please see note below. It looks like the CAC team isn't planning any additional actions for the P415 misfire QSF that's nearly upon us. I'd be surprised if water ingestion was a significant factor for misfire based upon our DTF experience. If it's not, then I'm not sure what's left in the tank for potential solutions short of AGS. Adding AGS will require participation from a broad cross-section of teams and agreement to add non-trivial cost to the vehicle. As such, if we plan to proceed down this path then direction will need to come from a high enough level to quickly get everyone aligned and moving forward.

Thanks,
Craig Smith
Supervisor - Engine Calibration
3.5L TIVCT GTDI & 3.5L IVCT GTDI Powerpacks
Phone: (313) 805-6345
TEE Bldg cube 1AD08

-----Original Message-----

From: Hughes, Scott (S.R.)
Sent: Friday, February 01, 2013 9:10 AM
To: Smith, Craig (C.A.); Whitehead, Joseph (J.P.)
Subject: FW: F150 GTDI AIS Water Ingestion

-----Original Message-----

From: McDonagh, Scot (S.M.)
Sent: Friday, February 01, 2013 8:53 AM
To: Sparks, Douglas (D.S.); Dixon, Mark (M.R.); Oyafuso, Kevin (K.G.);
Hughes, Scott (S.R.); Dumler, Jeff (J.D.)
Subject: FW: F150 GTDI AIS Water Ingestion

I gave John Sowards our 13MY P415 GTDI test vehicle for AIS video experiment. Jeanette advised there are no further actions planned with CAC to address upcoming Misfire QSF.

Scot G. McDonagh
PT Quality Engineering

Phone: (313)337-8091
smcdonag@ford.com

-----Original Message-----

From: Sowards, John (J.)
Sent: Friday, February 01, 2013 8:17 AM
To: Ronzi, Bill (W.C.); Andersen, Erik (E.); Madej, Jeanette (J.); Russo, Scott (S.); Hermann, Erik (E.H.)
Cc: McDonagh, Scot (S.M.); Ladd, John (J.R.)
Subject: RE: F150 GTDI AIS Water Ingestion

I would not consider the filter saturated but it was damp and in similar condition as was seen during the **RFR** stop ship water ingestion/CAC condensate investigation. I believe during WOT, enough air mass goes through the filter to strip most of the water collected leaving the filter damp to the touch.

During the **RFR** testing, we would weigh the filters to try and put a number on the amount of water ingested but found that an unreliable measurable based on video of the CAC inlet. In other words - we would see a large amount of water ingested at the CAC inlet but the weight of the filter would not correspond.

There was a small amount of puddling at the bottom of the airbox as well as witness marks from previous standing water.

I had attempted to run back to back testing with the fenderwell gap taped and un-taped but could not make a taped run in the time we had with the vehicle.

I agree that further testing should be done to determine the effects but suspect it isn't a large contributor to CAC condensate misfire.

I can make arrangements with the Video Imaging folks at EVB to have a camera installed in the clean and/or dirty side of the airbox. I believe we'll have more time with the vehicle I received from Scot McD to perform back to back testing. Standing by for further instructions.

-----Original Message-----

From: Ronzi, Bill (W.C.)
Sent: Thursday, January 31, 2013 4:45 PM
To: Andersen, Erik (E.); Madej, Jeanette (J.); Russo, Scott (S.); Hermann, Erik (E.H.); Sowards, John (J.)
Subject: RE: F150 GTDI AIS Water Ingestion

We'll put it on the agenda for next week then. I can give Julie a brief

update tomorrow if she asks.

I just looked at the video from John Sowards. Appears to be some droplets but it's difficult to see much beyond that. Do you know if the air filter was saturated following the drive?

If pulling any significant water through the AIS, I'd expect the filter to be saturated and there to be water standing in the bottom of the air box.

I'd suggest that we re-run the test next week, if we can get some wet roads, or run at DPG if the sprinklers aren't shut down for winter.

Bill

-----Original Message-----

From: Andersen, Erik (E.)

Sent: Thursday, January 31, 2013 4:05 PM

To: Ronzi, Bill (W.C.); Madej, Jeanette (J.); Russo, Scott (S.); Hermann, Erik (E.H.)

Subject: RE: F150 GTDI AIS Water Ingestion

I don't think we will have much information tomorrow. Is it possible to do it next week? We should have more to talk about.

Erik Andersen
Core P/T Cooling
eanderse@ford.com
313-805-2966

-----Original Message-----

From: Ronzi, Bill (W.C.)

Sent: Thursday, January 31, 2013 1:47 PM

To: Madej, Jeanette (J.); Russo, Scott (S.); Andersen, Erik (E.); Hermann, Erik (E.H.)

Subject: F150 GTDI AIS Water Ingestion

Importance: High

Julie would like to discuss the plan to test the above and ID possible improvements. She'd like to discuss in her Friday FQR.

Could we discuss for 5-10 minutes tomorrow or is that too soon?

Bill
William C. Ronzi

PTI Quality Supervisor
(313) 805-6140 cell & pgr

From: Cockerill, Al (C.A.)
Sent: Tuesday, January 22, 2013 11:40 AM
To: Kramer, Michael (M.T.); Madej, Jeanette (J.); Norman, Kristofor (K.R.); Osepchok, William (W.R.)
Subject: FW: F150 Water in CAC concern - Management lease vehicle 1FTFW1ET1DF [REDACTED]

FYI, and confused

The spirit, the will to win, and the will to excel are the things that endure. These qualities are so much more important than the events that occur. The harder you work, the harder it is to surrender.

Vince Lombardi

Al Cockerill
RWD V6 Engine System Supervisor
313-805-2333 C
313-845-0475 O

From: Parnell, Bill (W.)
Sent: Tuesday, January 22, 2013 10:18 AM
To: Cockerill, Al (C.A.); Mazuchowski, James (J.A.)
Subject: FW: F150 Water in CAC concern - Management lease vehicle 1FTFW1ET1DF [REDACTED]

FYI on my 2013 F150. If the dealer didn't have the two CAC side by side they might not have noticed this and fitted a new "bad" CAC.

From: Parnell, Bill (W.)
Sent: Tuesday, January 22, 2013 10:14 AM
To: Hughes, Scott (S.R.)
Cc: Galas, Dean (C.K.)
Subject: RE: F150 Water in CAC concern - Management lease vehicle 1FTFW1ET1DF [REDACTED]

Hi Scott. Yes Dean did send me one down and it's a good thing he did. The dealer had called me on Thursday last week to tell me the one they had ordered had arrived. I had my truck scheduled for it to be fitted today. I gave them the one that Dean had sent and told them to use it for the next customer so that they wouldn't have to wait. Turns out when they opened the box the special order one they had been sent was the old level! So they are now fitting the one Dean sent. We should probably have someone in FCSD look into why we are still sending out the old level part, I would've expected we would have scrapped out all the old level parts we have, no?

I told the dealer about the erratic shifting when using cruise control and asked them to flash the PCM with the latest cal.

Thanks.

From: Hughes, Scott (S.R.)
Sent: Saturday, January 19, 2013 8:16 AM
To: Parnell, Bill (W.)
Subject: RE: F150 Water in CAC concern - Management lease vehicle 1FTFW1ET1DF [REDACTED]

I heard that Dean Galas sent a CAC down to you. I'm hoping that you can still install it. Would like to hear if it improves your issues.

Thinking about mycanic, if something goes wrong, your truck would be dead. I think it would be best if you got the "latest" cal at dealership. Tell them you have a trans concern. If you are in Dearborn, I'd be happy to flash it for you.

From: Parnell, Bill (W.)
Sent: Monday, January 14, 2013 4:44 PM
To: Hughes, Scott (S.R.)
Subject: RE: F150 Water in CAC concern - Management lease vehicle 1FTFW1ET1DF [REDACTED]

I've never used a mycanic, I'd be happy to give it a go if you've time to talk me through it.

Thanks

From: Hughes, Scott (S.R.)
Sent: Monday, January 14, 2013 4:22 PM
To: Parnell, Bill (W.)
Subject: RE: F150 Water in CAC concern - Management lease vehicle 1FTFW1ET1DF [REDACTED]

Bill –

I just talked to the trans calibrator. Oddly enough, there was a change made after your truck was built to cruise control. I think I heard that your cal will give it 2 sec to get to set speed. If not there, it will downshift. New cal is 10 sec or more. This new cal is certified and in the plant, but I don't think it is at dealer yet.

Have you ever used a mycanic? I could send you one and you could reflash your truck. Or when your cac comes in, you could ask for latest cal as well.

Let me know what you'd like to do.

From: Parnell, Bill (W.)
Sent: Monday, January 14, 2013 12:26 PM
To: Hughes, Scott (S.R.)
Subject: RE: F150 Water in CAC concern - Management lease vehicle 1FTFW1ET1DF [REDACTED]

Thanks for trying Scott. I took a long drive to Canada this weekend, with the roads wet with melting snow it happened again. Kinda apprehensive to floor the throttle at all now. I do have another powertrain calibration question/issue. Why when the engine has such a huge fat torque curve does the transmission insist on kicking down from 6th to 5th gear when I hit resume on the cruise control at 65MPH to get the truck back up to 70MPH ? This was on flat ground with a light load on board (3 people and their gear) Seems like it would waste fuel and the noise is just annoying.

Thanks again.

From: Hughes, Scott (S.R.)
Sent: Friday, January 11, 2013 2:56 PM
To: Parnell, Bill (W.)
Subject: FW: F150 Water in CAC concern - Management lease vehicle 1FTFW1ET1DF [REDACTED]

Bill –

I guess your dealer had the latest info. No spare parts in Dearborn. When you do eventually get your new CAC, I would be very curious to know your opinion on the effectiveness. Thanks.

Sorry I couldn't help.

Scott

From: Dobbs, Dan (K.D.)
Sent: Wednesday, January 09, 2013 2:32 PM
To: Hughes, Scott (S.R.)
Subject: RE: F150 Water in CAC concern - Management lease vehicle 1FTFW1ET1DF [REDACTED]

Sorry we are > 2,000 CAC's on backorder. We don't have anything here at DTP that would fit, or that I can weasel.

His Dealer will have to emergency order and get in line. We are getting like 400 a week from Valeo. Messy.

Good news is that we are now having CAC's freeze internally in Canada. Air flows funny around an ice ball plugging the outlet. I bet you can Cal that out....grin... ! Physics are a pain sometimes.

Overall, the revised CAC has made a good positive dent as best we can tell. Weather shifted in Southeast Gulf area so we won't be certain until Spring and Late Summer. We have a few leakers in Washington State and Oregon, it's hard to be certain with COP issues popping at times.

We appreciate what you are doing with the TGW driveability items.

From: Hughes, Scott (S.R.)
Sent: Wednesday, January 09, 2013 2:23 PM
To: Dobbs, Dan (K.D.)
Subject: FW: F150 Water in CAC concern - Management lease vehicle 1FTFW1ET1DF [REDACTED]

Dan –

Below is a Ford employee that works out of Cleveland. He is very in tune with his CAC issue, but has been put on hold by the dealer in getting the part put in his vehicle. I was hoping that there may be a part in Dearborn that we could get to Bill's dealer a little quicker. Bill had promised that he would provide feedback on the effectiveness of his fix. Dealer info is below.

Please let me know if this is possible. Thanks.

Also – what is your take on the effectiveness of the new CAC? As good as advertised?

Scott

From: Parnell, Bill (W.)
Sent: Wednesday, January 09, 2013 1:56 PM
To: Hughes, Scott (S.R.)
Subject: F150 Water in CAC concern - Management lease vehicle 1FTFW1ET1DF [REDACTED]

Hi Scott, as we discussed I had previously taken my truck to Liberty Ford in Brunswick. The service writer I was dealing there was Jay (sorry don't know his last name). The truck was in there on 1-3-13, they had advised I needed the new CAC and that the parts would be on back order for 3 – 4 weeks.

Dealer Address is

Liberty Ford
3101 Center Road
Brunswick
OH 44212

Tel: 330-225-9141

Thanks for your help.

Bill Parnell
Ford Motor Company
T: 313 283 2646

From: Alcaraz andrade, Alejandro (M.)
Sent: Wednesday, June 26, 2013 9:44 AM
To: Kramer, Michael (M.T.)
Subject: FW: FW: Surface prep question

Mike,

No issue with cleaning the CAC with alcohol, but I think we should specify that dealers must make sure CAC is dry before installation

Thank you

-----Original Message-----

From: Stein, James (J.R.)
Sent: Wednesday, June 26, 2013 09:00 AM Eastern Standard Time
To: Alcaraz andrade, Alejandro (M.)
Subject: Re: FW: Surface prep question

Hi Alejandro,

No this is not an issue.

Thank you,

>>> "Alcaraz andrade, Alejandro (M.)" <malcara2@ford.com> 6/26/2013 8:57 AM >>>

For the service blocker, DL34 3G4610 AA, previous to the installation we would like to clean the CAC is there any known concern with the 3M adhesive if we do so with alcohol?

Thanks

From: Kramer, Michael (M.T.)
Sent: miércoles, 26 de junio de 2013 06:58 a.m.
To: Alcaraz andrade, Alejandro (M.)
Cc: Kramer, Michael (M.T.)
Subject: FW: Surface prep question

Please also have Creative Foam check with 3M to see if there are any concerns with using an alcohol wipe for cleaning the surface prior to sticking the blocker to it.

Mike Kramer

RWD PT Cooling Supv.

Six Sigma Black Belt

Cell Phone: (313) 805-0190

Text Page: mkramer1

Page from outside Ford, External email: mkramer1@ford.com

From: Kramer, Michael (M.T.)
Sent: Wednesday, June 26, 2013 7:57 AM
To: Blas-Fernando GUTIERREZ (blas-fernando.cutierrez@valeo.com); Tyler, Jim (J.S.)
Cc: Reaume, Alan (A.C.); Alcaraz andrade, Alejandro (M.); Kramer, Michael (M.T.)
Subject: FW: Surface prep question

Please provide name and details of the paint used on the P415 CAC

Mike Kramer
RWD PT Cooling Supv.
Six Sigma Black Belt
Cell Phone: (313) 805-0190
Text Page: mkramer1
Page from outside Ford, External email: mkramer1@ford.com

From: Reaume, Alan (A.C.)
Sent: Wednesday, June 26, 2013 7:35 AM
To: Kramer, Michael (M.T.); Kowalski, George (G.S.); Romano, Ron (R.)
Cc: Alcaraz andrade, Alejandro (M.); Dobbs, Dan (K.D.); Ronzi, Bill (W.C.)
Subject: RE: Surface prep question

Mike, The paint specification is not attached, the two methods below are for paint adhesion. If you can give us the paint trade name or specification, we can evaluate the cleaner, but generally any fully cured paint will not be affected by an alcohol wipe. I would recommend using iso-propyl alcohol to remove oily residue.

Thanks,

Alan Reaume
Engine Materials Engineering
Engine Non-Metals Technical Expert
phone/fax 313 337-2879
20000 Rotunda, Cube 12B038
Dearborn MI, 48121-2053

From: Kramer, Michael (M.T.)
Sent: Tuesday, June 25, 2013 3:54 PM
To: Reaume, Alan (A.C.); Kowalski, George (G.S.); Romano, Ron (R.)
Cc: Kramer, Michael (M.T.); Alcaraz andrade, Alejandro (M.); Dobbs, Dan (K.D.); Ronzi, Bill (W.C.)
Subject: Surface prep question

We have an aluminum charge air cooler painted per the following spec:

<< OLE Object: Picture (Device Independent Bitmap) >>

Want to add a surface cleaning procedure to a TSB to clean a portion of the face prior to adding a stick-on blocker shield.

Would denatured alcohol be a suitable cleaner/degreaser that would not remove the paint? Other cleaner/degreaser?

Mike Kramer
RWD PT Cooling Supv.
Six Sigma Black Belt
Cell Phone: (313) 805-0190
Text Page: mkramer1
Page from outside Ford, External email: mkramer1@ford.com

This transmission may contain information that is privileged, proprietary, confidential and/or exempt from disclosure under applicable law. If you are not the intended recipient, you are hereby notified that any disclosure, copying, distribution, or use of the information contained herein (including any reliance thereon) is **STRICTLY PROHIBITED**. If you received this transmission in error, please immediately contact the sender and destroy the material in its entirety, whether in electronic or hard copy format. Thank you.

From: Sims, Ivan (I.D.)
Sent: Thursday, January 05, 2012 8:22 AM
To: Kramer, Michael (M.T.)
Subject: FW: GM patent describing CAC condensate leading to misfire

Importance: High

Per our discussion...

IVAN D. SIMS

Hardware/Controls Interface Section
Component Design C Department, GEE
Phone: 313-805-9971

From: Glugla, Chris (C.P.)
Sent: Wednesday, January 04, 2012 2:57 PM
To: Mancini, Michael (M.A.); Mazuchowski, James (J.A.); Russ, Stephen (S.G.); Sims, Ivan (I.D.); Smith, Craig (C.A.); Mandjack, Michael (M.P.); Morrow, Bill (N.W.); Norman, Kristofor (K.R.); Boerger, Jim (J.G.); Tallio, Kevin (K.V.); McCoy, Jim (D.); Fabien, Phil (P.A.); Fought, Matthew (M.S.); Cockerill, Al (C.A.)
Subject: GM patent describing CAC condensate leading to misfire
Importance: High

From GM patent 20110107760



US20110107760(A
1).pdf

BACKGROUND OF INVENTION

The present invention relates generally to turbocharger systems used with internal combustion engines in vehicles, and more particularly to intercooler assemblies used with turbocharger systems in vehicles.

Many high output turbocharged engines used in vehicles employ a base boost at relatively low engine speeds, such as during steady state highway driving. This base boost is essentially an always-on turbo boost and helps reduce turbo lag, which is a common complaint for older turbocharged engines on vehicles. A high level of base boost, together with a high thermal efficiency charge-air-cooler (CAC) heat exchanger (i.e., an intercooler), can cause condensation to form inside the CAC. This condensation typically occurs during steady state driving when ambient conditions are warm with humidity levels near one hundred percent. Such a condition may occur for an automotive vehicle during steady state highway driving in the rain.

The concern with forming this condensation occurs when a significant amount of condensate has been generated during steady state driving, and the vehicle operator subsequently performs a hard acceleration of the vehicle. The collected condensate can be ingested into the engine at too high of a rate, causing engine misfire. If the misfire is severe enough, the vehicle's engine control module may light the "service engine soon" light, which is undesirable. Moreover, the driver may also notice poor vehicle performance or rough acceleration, which are also undesirable.

One way to minimize the condensate collection is by employing a turbocharger system that provides a very low base boost. However, this increases the undesirable turbo-lag that base boost is meant to minimize in the first

place. Another possibility to deal with the condensate is to use engine vacuum to extract condensate, but this may create powertrain integration concerns. Also, another way is to allow the condensate to leak to atmosphere; however, this may be undesirable when attempting to meet certain vehicle emissions requirements.

Another possible solution is to create an integrated condensate trap, as is shown in FIG. 1. In this turbocharger system **10**, a pair of integrated condensate trap tubes **12** are built into the bottom of an intercooler heat exchanger **14**. As air passes from an inlet tube **16** at a first end of the heat exchanger **14** to an outlet tube **18** at a second end of the heat exchanger, excess condensate that is formed in the heat exchanger **14** is stored in the integral trap tubes **12**. For example, for a vehicle traveling at steady state highway speeds during a rain storm, the condensate may be produced in the intercooler heat exchanger **14** at a rate of about two hundred milliliters of water per hour, but the engine may only be able to handle ingesting water at a rate of about sixty milliliters of water per hour from the intercooler heat exchanger before engine misfire is detected. Thus, with the condensate trap tubes **12**, the vehicle may only be able to travel for a relatively limited time before the ingestion rate of the condensate is high enough to cause a misfire.

Chris Glugla
Technical Expert Advanced Controls Implementation
Powertrain Controls Research and Development
Research and Innovation Center
2101 Village Road
Dearborn, MI. 48121
Cube 1625.t
Phone: (313) 322-4692
Fax: (313)-2487857
MD: 2036
email: cglugla@ford.com



(19) **United States**

(12) **Patent Application Publication**
Quinn et al.

(10) **Pub. No.: US 2011/0107760 A1**

(43) **Pub. Date: May 12, 2011**

(54) **INTERCOOLER HAVING CONDENSATE RESERVOIR**

Publication Classification

(51) **Int. Cl.**
F02B 29/04 (2006.01)
(52) **U.S. Cl.** 60/599
(57) **ABSTRACT**


(75) **Inventors:** **Richard D. Quinn**, Clarkston, MI (US); **Brandon S. Helton**, Hartland, MI (US); **Kenneth J. Murphy**, Carleton, MI (US); **Tuan A. Tran**, Dearborn Heights, MI (US); **Lawrence E. Walla**, Washington, MI (US)

(73) **Assignee:** **GM GLOBAL TECHNOLOGY OPERATIONS, INC.**, DETROIT, MI (US)

(21) **Appl. No.:** 12/617,010

(22) **Filed:** Nov. 12, 2009

An engine air intake system for a vehicle having an internal combustion engine may include a turbocharger; a CAC heat exchanger having an inlet end for receiving compressed intake air from the turbocharger and an outlet end; a remote condensate reservoir spaced from the CAC heat exchanger, for storing condensate therein; a condensate drain tube extending from the outlet end to the remote condensate reservoir to allow condensate produced in the CAC heat exchanger to flow into the remote condensate reservoir; an air duct connecting the outlet end to the engine to direct air flow from the outlet end to the engine; and a reservoir outlet hose connected to the remote condensate reservoir at a first end and connected to the air duct at a second end to allow condensate evaporating from the remote condensate reservoir to flow through the reservoir outlet hose into the air duct.






Fig. 1
(Prior Art)




Fig. 3




Fig. 2




Fig. 4




Fig. 5

INTERCOOLER HAVING CONDENSATE RESERVOIR

BACKGROUND OF INVENTION

[0001] The present invention relates generally to turbocharger systems used with internal combustion engines in vehicles, and more particularly to intercooler assemblies used with turbocharger systems in vehicles.

[0002] Many high output turbocharged engines used in vehicles employ a base boost at relatively low engine speeds, such as during steady state highway driving. This base boost is essentially an always-on turbo boost and helps reduce turbo lag, which is a common complaint for older turbocharged engines on vehicles. A high level of base boost, together with a high thermal efficiency charge-air-cooler (CAC) heat exchanger (i.e., an intercooler), can cause condensation to form inside the CAC. This condensation typically occurs during steady state driving when ambient conditions are warm with humidity levels near one hundred percent. Such a condition may occur for an automotive vehicle during steady state highway driving in the rain.

[0003] The concern with forming this condensation occurs when a significant amount of condensate has been generated during steady state driving, and the vehicle operator subsequently performs a hard acceleration of the vehicle. The collected condensate can be ingested into the engine at too high of a rate, causing engine misfire. If the misfire is severe enough, the vehicle's engine control module may light the "service engine soon" light, which is undesirable. Moreover, the driver may also notice poor vehicle performance or rough acceleration, which are also undesirable.

[0004] One way to minimize the condensate collection is by employing a turbocharger system that provides a very low base boost. However, this increases the undesirable turbo-lag that base boost is meant to minimize in the first place. Another possibility to deal with the condensate is to use engine vacuum to extract condensate, but this may create powertrain integration concerns. Also, another way is to allow the condensate to leak to atmosphere; however, this may be undesirable when attempting to meet certain vehicle emissions requirements.

[0005] Another possible solution is to create an integrated condensate trap, as is shown in FIG. 1. In this turbocharger system 10, a pair of integrated condensate trap tubes 12 are built into the bottom of an intercooler heat exchanger 14. As air passes from an inlet tube 16 at a first end of the heat exchanger 14 to an outlet tube 18 at a second end of the heat exchanger, excess condensate that is formed in the heat exchanger 14 is stored in the integral trap tubes 12. For example, for a vehicle traveling at steady state highway speeds during a rain storm, the condensate may be produced in the intercooler heat exchanger 14 at a rate of about two hundred milliliters of water per hour, but the engine may only be able to handle ingesting water at a rate of about sixty milliliters of water per hour from the intercooler heat exchanger before engine misfire is detected. Thus, with the condensate trap tubes 12, the vehicle may only be able to travel for a relatively limited time before the ingestion rate of the condensate is high enough to cause a misfire.

SUMMARY OF INVENTION

[0006] An embodiment contemplates an engine air intake system for a vehicle having an internal combustion engine.

The engine air intake system may include a turbocharger; a charge-air-cooler (CAC) heat exchanger having an inlet end that receives compressed intake air from the turbocharger and an outlet end; a remote condensate reservoir spaced from the CAC heat exchanger that stores condensate; a condensate drain tube extending from the outlet end to the remote condensate reservoir to allow condensate produced in the CAC heat exchanger to flow into the remote condensate reservoir; an air duct connecting the outlet end to the engine to direct air flow from the outlet end to the engine; and a reservoir outlet hose connected to the top surface of the remote condensate reservoir at a first end and connected to the air duct at a second end to allow condensate evaporating from the remote condensate reservoir to be drawn through the reservoir outlet hose into the air duct.

[0007] An embodiment contemplates an engine air intake system for a vehicle having an internal combustion engine. The engine air intake system may include a turbocharger; a CAC heat exchanger having an inlet end for receiving compressed intake air from the turbocharger and an outlet end; a remote condensate reservoir spaced from the CAC heat exchanger, for storing condensate therein; a condensate drain tube extending from the outlet end to the remote condensate reservoir having a first end connected to the outlet end and a second end connected to the remote condensate reservoir at an elevation that is lower than the first end of the condensate drain tube to allow condensate produced in the CAC heat exchanger to flow into the remote condensate reservoir; an air duct connecting the outlet end to the engine to direct air flow from the outlet end to the engine; and a reservoir outlet hose connected to the remote condensate reservoir at a first end and connected to the air duct at a second end and configured to allow condensate evaporating from the remote condensate reservoir to flow through the reservoir outlet hose into the air duct.

[0008] An advantage of an embodiment is that a remote coolant reservoir allows for improved intercooler performance, especially when operating the vehicle in wet conditions. The condensate can be stored and fed into the engine in a controlled rate while still allowing for maximum charge-air-cooler heat exchanger effectiveness within the packaging space allowed for the heat exchanger by allowing for maximizing the frontal area in the CAC heat exchanger. Maximizing the frontal area in this way reduces the air flow restriction and reduces the pressure drop, which leads to the improved overall cooling of the charge air. This may allow for improved horsepower and torque output from the engine. Moreover, the remote coolant reservoir allows for more flexibility in the size and shape of the reservoir to provide the desired storage capacity for the condensate without reducing the cooling effectiveness of the charge air cooler heat exchanger and while providing more packaging flexibility in locating the reservoir.

[0009] Another advantage of an embodiment is that the remote condensate reservoir allows the vehicle to travel for longer periods of time without ingestion of condensate in the engine creating a significant engine misfire concern, even with an intercooled, high base boost turbocharger system. The ingestion of the condensate into the engine may be maintained at desired controlled rates, with the relatively higher pressure at a condensate drain tube and the relatively lower pressure at an intake duct connector causing a flow through the remote condensate reservoir that will draw condensate into the air stream.

[0010] Another advantage of an embodiment is that the condensate does not have to be released to atmosphere, thus avoiding concerns with vehicle emissions requirements.

[0011] Still another advantage of an embodiment is that the condensate reservoir, condensate drain tube and reservoir outlet hose do not require any moving parts, thus reducing concerns with reliability and making the assembly simple to fabricate and assemble and easy to service.

BRIEF DESCRIPTION OF DRAWINGS

[0012] FIG. 1 is a perspective view of a prior art intercooler heat exchanger.

[0013] FIG. 2 is a schematic, plan view of an engine and turbocharger system for a vehicle.

[0014] FIG. 3 is a perspective view of a portion of the turbocharger system.

[0015] FIG. 4 is a perspective view of a portion of the turbocharger system.

[0016] FIG. 5 is another perspective view of a portion of the turbocharger system.

DETAILED DESCRIPTION

[0017] FIGS. 2-5 illustrate portions of an engine 20 and engine air intake system 22 that is employed with a vehicle. The engine air intake system 22 includes a turbocharger system 24 that compresses and cools intake air before being delivered to the engine 20. The engine 20 connects to an exhaust pipe 26 leading to a turbocharger 28 that is driven by the flow of exhaust gas from the pipe 26. An exhaust outlet of the turbocharger 28 directs air into a vehicle exhaust pipe 30. Intake air is directed through an air cleaner 32 to the turbocharger 28, which directs the charged air into an intercooler inlet tube 34.

[0018] The intercooler inlet tube 34 directs compressed air into an intake end 36 of a charge-air-cooler (CAC) heat exchanger 38 that cools the charged air. The CAC heat exchanger 38 may include mounting brackets 39 for mounting the heat exchanger in a condenser, radiator, fan module. An outlet end 40 of the CAC heat exchanger 38 directs the compressed, cooled air into an intercooler air outlet tube 42, which is connected to and directs the air into an engine air intake duct 44. The engine air intake duct 44 directs the air into the engine 20.

[0019] The outlet end 40 also connects to a condensate drain tube 46 that leads to a remote condensate reservoir 48 that is spaced from the CAC heat exchanger 38. A support bracket 50 may mount to the reservoir 48 to vehicle body structure to support the reservoir 48 in the vehicle. The reservoir 48 is preferably packaged in the vehicle such that the condensate drain tube 46 is level or lower at the reservoir end than the end connected to the heat exchanger 38. Accordingly, the height the condensate has to travel up the drain tube 46 is minimized or eliminated. The condensate drain tube 46 should have a large enough inside diameter to allow condensate to easily flow from the heat exchanger 38 into the reservoir 48 under conditions that cause a high rate of condensate production, such as under a hard acceleration.

[0020] Extending from the top 52 of the reservoir 48 is a reservoir outlet hose 54. The reservoir outlet hose 54 connects to an intake duct connector 56, which is mounted to the engine air intake duct 44. The reservoir outlet hose 54 has a significantly smaller inner diameter than the engine air intake duct 44 in order to limit the amount of condensate relative to the

volume of the air flowing into the engine 20. The significant size difference may be as much as an order of magnitude different, with the smaller diameter being one-tenth or less of the larger diameter, thus making the flow area difference even greater. The air flowing through the engine air intake duct 44 may possibly create somewhat of a venturi effect as it flows past the intake duct connector 56, thus drawing the air and condensate mixture from the reservoir outlet hose 54. The difference in pressure between the air in the condensate drain tube 46 and the air in the intake duct connector 56 will cause an air flow through the remote condensate reservoir 48, which will draw some of the condensate into the air stream. Consequently, this reservoir assembly is an active system that operates continuously as the engine is on—rather than a passive system—assuring that the condensate will be drawn into the engine at a desirable controlled rate.

[0021] Portions of the condensate drain tube 46 and reservoir outlet hose 54 are preferably made of silicone. The silicone material is preferred in order to avoid swelling and cracking from exposure to oil from the turbocharger unit that may occur with other materials. The silicone also provides the ability to expand should the condensate freeze in cold weather.

[0022] During operation of the vehicle in high humidity conditions, such as driving on a highway during a rain storm, condensate that forms in the CAC heat exchanger 38 and collects at the bottom of the heat exchanger 38 is drawn into the remote condensate reservoir 48 through the condensate drain tube 46. The reservoir outlet hose 54 is attached to the top 52 of the reservoir 48, which allows the incoming mix of condensate and air to separate. The excess condensate produced while driving under the high humidity conditions will be stored in the reservoir 48.

[0023] Then, when the vehicle is operated under driving conditions with lower humidity, the condensate evaporates into the air flowing through the remote condensate reservoir 48, with this air drawn from the reservoir 48 through the reservoir outlet hose 54 into the engine air intake duct 44 and into the engine 20. The vacuum in the engine air intake duct 44 may possibly employ a venturi effect to draw the air/condensate mixture through the reservoir outlet hose 54. The inside diameter of the reservoir outlet hose 54, being much smaller than the inside diameter of the engine air intake duct 44 assures that the amount of condensate in the incoming air to the engine 20 will minimize the chance of the condensate causing an engine misfire. The particular difference in diameters may be determined for particular combinations of specific engines and turbocharger systems to assure that the condensate is ingested at a controlled rate below that which may cause misfires. The intake duct connector 56 connects to the engine air intake duct 44 close to the intake of the engine 20 to take advantage of the pressure differential in order to draw the evaporated condensate through the reservoir outlet hose 54.

[0024] While certain embodiments of the present invention have been described in detail, those familiar with the art to which this invention relates will recognize various alternative designs and embodiments for practicing the invention as defined by the following claims.

What is claimed is:

1. An engine air intake system for a vehicle having an internal combustion engine comprising:

- a turbocharger;
 - a CAC heat exchanger having an inlet end configured to receive compressed intake air from the turbocharger and an outlet end;
 - a remote condensate reservoir mounted in the vehicle spaced from the CAC heat exchanger, configured to store condensate therein, and having a top surface;
 - a condensate drain tube extending from the outlet end to the remote condensate reservoir configured to allow condensate produced in the CAC heat exchanger to flow into the remote condensate reservoir;
 - an air duct connecting the outlet end to the engine and configured to direct air flow from the outlet end to the engine; and
 - a reservoir outlet hose connected to the top surface of the remote condensate reservoir at a first end and connected to the air duct at a second end and configured to allow condensate evaporating from the remote condensate reservoir to be drawn through the reservoir outlet hose into the air duct.
2. The engine air intake system of claim 1 wherein the condensate drain tube has a first end connected to the outlet end and a second end connected to the remote condensate reservoir at an elevation that is lower than the first end of the condensate drain tube.
 3. The engine air intake system of claim 1 wherein the reservoir outlet hose has an inside diameter that is at least an order of magnitude smaller than an inside diameter of the air duct.
 4. The engine air intake system of claim 1 wherein at least a portion of the condensate drain tube is made of silicone.
 5. The engine air intake system of claim 1 wherein at least a portion of the reservoir outlet hose is made of silicone.
 6. The engine air intake system of claim 1 wherein the condensate drain tube connects to a side of the remote condensate reservoir at an elevation below the top surface of the remote condensate reservoir.
 7. An engine air intake system for a vehicle having an internal combustion engine comprising:

- a turbocharger;
 - a CAC heat exchanger having an inlet end configured to receive compressed intake air from the turbocharger and an outlet end;
 - a remote condensate reservoir spaced from the CAC heat exchanger, configured to store condensate therein;
 - a condensate drain tube extending from the outlet end to the remote condensate reservoir having a first end connected to the outlet end and a second end connected to the remote condensate reservoir at an elevation that is lower than the first end of the condensate drain tube to allow condensate produced in the CAC heat exchanger to flow into the remote condensate reservoir;
 - an air duct connecting the outlet end to the engine and configured to direct air flow from the outlet end to the engine; and
 - a reservoir outlet hose connected to the remote condensate reservoir at a first end and connected to the air duct at a second end and configured to allow condensate evaporating from the remote condensate reservoir to flow through the reservoir outlet hose into the air duct.
8. The engine air intake system of claim 7 wherein the reservoir outlet hose has an inside diameter that is at least an order of magnitude smaller than an inside diameter of the air duct.
 9. The engine air intake system of claim 8 wherein the remote condensate reservoir has a top surface and the first end of the reservoir outlet hose is connected to the top surface of the remote condensate reservoir.
 10. The engine air intake system of claim 9 wherein the condensate drain tube connects to a side of the remote condensate reservoir at an elevation below the top surface of the remote condensate reservoir.
 11. The engine air intake system of claim 7 including a pair of heat exchanger brackets secured to the CAC heat exchanger and configured to mount the CAC heat exchanger to vehicle structure, and a reservoir bracket secured to the remote condensate reservoir and configured to secure the remote condensate bracket to the vehicle structure.

* * * * *

From: Andersen, Erik (E.)
Sent: Tuesday, February 26, 2013 6:17 PM
To: Devries, Jason (J.E.)
Subject: FW: Heads-up - 13MY F150 GTDI CAC Misfire 80% QSF Threshold

we don't have any room on the CAC. This is going to get a lot more attention once it hits the QSF threshold, as if it isn't already.

So, what else can we do in the calibration? Do we need to start talking more seriously about shift schedules?

Erik Andersen
Core P/T Cooling
eanderse@ford.com
313-805-2966

From: Sparks, Douglas (D.S.)
Sent: Tuesday, February 26, 2013 12:31 PM
To: McCoy, Julie (.); Madej, Jeanette (J.); Ronzi, Bill (W.C.); Andersen, Erik (E.); Renwick, Rick (R.J.); Wright, Robin (R.A.); Beltramo, Joel (J.J.); Mazuchowski, James (J.A.); Crudo, Frank (F.J.); Baum, Joe (J.M.); Leisenring, Kenneth (K.C.); Smith, Craig (C.A.)
Subject: Heads-up - 13MY F150 GTDI CAC Misfire 80% QSF Threshold

Team,
FYI - the F150 3.5L GTDI is on the emerging QSF list; is currently 80% of QSF threshold (20 calls into the hot line for help post revised CAC). We will continue to monitor and keep you posted. However, at this rate there will be another QSF for CAC induced misfire.

Eric,
What is the testing status of controlling system pressure with CBV and or waste gate? Has there been any progress on H2O contribution from the AIS ?

Thank you,

Douglas S. Sparks
P/T Quality and PVT Manager FNA
P/T Integration and Program Management (PTIM)
dsparks3@ford.com 313-805-6096

Administrative Assistant: Tina Tessadri
ttessadr 313 594-1115

From: Madej, Jeanette (J.)
Sent: Friday, February 17, 2012 11:02 AM
To: Kramer, Michael (M.T.); Ladd, John (J.R.)
Subject: Fw: Kick off tooling for P415 misfire fixes

Pls see we need timing for both

From: Mazuchowski, James (J.A.)
Sent: Friday, February 17, 2012 10:40 AM
To: Hermann, Erik (E.H.); McCoy, Julie (.)
Cc: Madej, Jeanette (J.)
Subject: RE: Kick off tooling for P415 misfire fixes

Erik, the 1000 pc number was for a service fix and an estimate on my part. You need to assume for both service and production based on yesterday's direction.

Jim Mazuchowski
Manager, New V6 Engine Programs
V-Engine Eng'r; 33-79935

From: Hermann, Erik (E.H.)
Sent: Thursday, February 16, 2012 2:46 PM
To: McCoy, Julie (.)
Cc: Madej, Jeanette (J.); Mazuchowski, James (J.A.)
Subject: RE: Kick off tooling for P415 misfire fixes

There is not yet a feasible design to tool. I reviewed the concept earlier this week and agreed assumptions that we think would be feasible but the team is still working on creating the design. The CAC duct change is not minor. A feasible version is a totally new tooled duct with a completely different manufacturing approach.

Request was low volume (~1000 parts) so our assumption is aluminum tooling using a fast local shop similar to what we did for the C520 turbo whine resonators. Timing will be similar at 10-12 weeks from now to customer usable parts.

Erik Hermann
Manager - PTI Global Air Intake Systems
313-323-8715
Share the Ford Story at www.TheFordStory.com
<< OLE Object: Picture (Metafile) >>

From: McCoy, Julie (.)
Sent: Thursday, February 16, 2012 2:22 PM
To: Madej, Jeanette (J.); Hermann, Erik (E.H.); Mazuchowski, James (J.A.)
Subject: Kick off tooling for P415 misfire fixes
Importance: High

Jeanette/Erik, need you to kick off the highest confidence tooling for the P415 misfire fixes TODAY. Per Joe, he will help elevate with the suppliers in next week's quality meeting if timing is not expedited or to your expectations. Please make sure that this is done before you leave for the day and let me know if you have any questions. Suggest that you very closely scrub the timing and ensure that the suppliers have the proper sense of urgency. Please let me know if any help is needed, many thanks.

Julie McCoy

Chief Engineer, Powertrain Installations (PTI)

jmccoy, 313-805-6374

Administrative assistant: Angie Perkins x47391

From: Kramer, Michael (M.T.)
Sent: Monday, April 08, 2013 4:03 PM
To: Sowards, John (J.); Huang, Larry (L.)
Cc: Andersen, Erik (E.)
Subject: FW: LATE SCHEDULE CHANGE - Tuesday 7:30am

Importance: High

Per our discussions today.

Mike Kramer
RWD PT Cooling Supv.
Six Sigma Black Belt
Cell Phone: (313) 805-0190
Text Page: mkramer1
Page from outside Ford, External email: mkramer1@ford.com

From: Weber, Erik (E.M.)
Sent: Monday, April 08, 2013 3:23 PM
To: Sarkozi, Gerald (G.); Rohrhoff, Bob (J.)
Cc: Weber, Erik (E.M.); Kramer, Michael (M.T.)
Subject: LATE SCHEDULE CHANGE - Tuesday 7:30am
Importance: High

Gerry,

I need to make a late schedule change.

Please replace 294w448 AD5834 with 566w329 AD1260. Vehicle is on-site already.

This change is required to support and emerging 2014 P415 late content change related to on-going CAC condensation field issues and a new bumper grill insert.

Erik M. Weber
Ford Motor Company
TASE - FNA VE
P552 Thermal & Cooling
313.805.4349



From: Kramer, Michael (M.T.)
Sent: Monday, September 17, 2012 11:42 AM
To: Ladd, John (J.R.); Tyler, Jim (J.S.)
Cc: Weber, Erik (E.M.); Kramer, Michael (M.T.)
Subject: FW: Meeting Forward Notification: Lower Grille (bumper design)

The P415 program is continuing to investigate a grill cover in the lower bumper opening due to appearance concerns of the CAC showing through.

Jim. Erik needs a PCA CAC next week for his cooling evaluation of the latest grill cover proposal.

John. We should also consider evaluating from a CAC condensation standpoint.

Mike Kramer
RWD PT Cooling Supv.
Six Sigma Black Belt
Cell Phone: (313) 805-0190
Text Page: mkramer1
Page from outside Ford, External email: mkramer1@ford.com

From: Massara, Michael (M.G.)
Sent: Monday, September 17, 2012 11:27 AM
To: Sullivan, Raymond (R.)
Cc: Harris, Wilding (W.G.); Rodgers, Thomas (T.A.); Weber, Erik (E.M.); Palm, Jim (J.R.); Kramer, Michael (M.T.); Kasper, Kenneth (K.T.); DiMarco, Jackie Marshal (J.M.)
Subject: RE: Meeting Forward Notification: Lower Grille (bumper design)

Ray, please verify when the SLA will be available. Eric told me that once he knows this info, he will compose the test request. He is optimistic the testing can happen next week. Thanks

From: Weber, Erik (E.M.)
Sent: Monday, September 17, 2012 11:14 AM
To: Massara, Michael (M.G.); Sullivan, Raymond (R.)
Cc: Harris, Wilding (W.G.); Rodgers, Thomas (T.A.)
Subject: RE: Meeting Forward Notification: Lower Grille (bumper design)

Michael,

Yes, I'm sure we can accommodate a test of this grill proposal very soon. Based on previous test information, I believe this proposal will be acceptable.

There was a separate request of our group to accommodate a CAC condensation water spray test for P415 the week of 9/24. Beyond the requested timing, I'm not really certain what that request entails, but I would suggest piggybacking onto that request in the interest of DV efficiency.

Erik M. Weber

Ford Motor Company
TASE - FNA VE
P415 / U22x Thermal & Cooling
313.805.4349

<< OLE Object: Picture (Device Independent Bitmap) >>

From: Massara, Michael (M.G.)
Sent: Monday, September 17, 2012 10:03 AM
To: Sullivan, Raymond (R.); Weber, Erik (E.M.)
Subject: RE: Meeting Forward Notification: Lower Grille (bumper design)

On that note Eric, are there any plans for getting analytical and empirical (wind tunnel) testing done on this design?

From: Sullivan, Raymond (R.)
Sent: Monday, September 17, 2012 9:38 AM
To: Weber, Erik (E.M.)
Cc: Massara, Michael (M.G.)
Subject: FW: Meeting Forward Notification: Lower Grille (bumper design)

Erik,
Sorry I could not remember if I sent this to you already for a preview of the latest proposal from the studio. I should have a sterolith part in a couple of days. There is a lot of interest in getting a cooling evaluation as soon as possible (of course).

<< File: bumper.stp >>

From: LaMontagne, Trevor (T.)
Sent: Wednesday, September 05, 2012 2:16 PM
To: Massara, Michael (M.G.); Sullivan, Raymond (R.)
Subject: RE: Meeting Forward Notification: Lower Grille (bumper design)

I reviewed w Sean Tant ,the design manager and he made some changes...

<< OLE Object: Picture (Device Independent Bitmap) >>

From: Massara, Michael (M.G.)
Sent: Wednesday, September 05, 2012 12:11 PM
To: LaMontagne, Trevor (T.); Sullivan, Raymond (R.)
Subject: RE: Meeting Forward Notification: Lower Grille (bumper design)

Thanks Trevor. Ray, if you are satisfied w/the geometric detail, let's get a surface to Weber for assessment.

From: LaMontagne, Trevor (T.)
Sent: Wednesday, September 05, 2012 11:41 AM
To: Massara, Michael (M.G.); Sullivan, Raymond (R.)
Subject: RE: Meeting Forward Notification: Lower Grille (bumper design)

I have a proposal ready for review. Let me know if you want the file shared somewhere or a meeting to review...
<< OLE Object: Picture (Device Independent Bitmap) >>

From: Massara, Michael (M.G.)
Sent: Wednesday, September 05, 2012 9:51 AM
To: Sullivan, Raymond (R.); LaMontagne, Trevor (T.)
Subject: RE: Meeting Forward Notification: Lower Grille (bumper design)

Thanks guys, please keep me in the loop where you are on this and guesstimate timing when we can get a basic a-surface to TASE for assessment. Again, this isn't artwork at this point, just some basic design to determine whether it's viable and worth going forward.

From: Sullivan, Raymond (R.)
Sent: Wednesday, September 05, 2012 7:06 AM
To: LaMontagne, Trevor (T.)
Cc: Massara, Michael (M.G.)
Subject: RE: Meeting Forward Notification: Lower Grille (bumper design)

Trevor,
Sorry I have been out of the office and just returned today. Let me know a good time for you and we can get together to look at the lower bumper grille proposal. Thank you.

From: Massara, Michael (M.G.)
Sent: Tuesday, September 04, 2012 1:22 PM
To: LaMontagne, Trevor (T.)
Cc: Sullivan, Raymond (R.)
Subject: RE: Meeting Forward Notification: Lower Grille (bumper design)

Ray, please get with and line up Trevor on the design. I will most likely be out this and next week. Thanks

From: LaMontagne, Trevor (T.)
Sent: Tuesday, September 04, 2012 12:22 PM
To: Massara, Michael (M.G.)
Cc: Sullivan, Raymond (R.)
Subject: RE: Meeting Forward Notification: Lower Grille (bumper design)

I have not heard from anyone on this issue yet.

From: Massara, Michael (M.G.)
Sent: Tuesday, September 04, 2012 12:17 PM
To: LaMontagne, Trevor (T.)
Cc: Sullivan, Raymond (R.)
Subject: RE: Meeting Forward Notification: Lower Grille (bumper design)

Have you and Ray gotten together on this?

-----Original Appointment-----

From: Microsoft Outlook **On Behalf Of** LaMontagne, Trevor (T.)
Sent: Tuesday, September 04, 2012 10:45 AM
To: Massara, Michael (M.G.)
Subject: Meeting Forward Notification: Lower Grille (bumper design)
When: Friday, August 31, 2012 9:00 AM-9:30 AM (UTC-05:00) Eastern Time (US & Canada).
Where:

Your meeting was forwarded

LaMontagne, Trevor (T.) has forwarded your meeting request to additional recipients.

Meeting

Lower Grille (bumper design)

Meeting Time

Friday, 31 August 2012 09:00-09:30.

Recipients

Lacelle, Michael (M.G.)

All times listed are in the following time zone: (UTC-05:00) Eastern Time (US & Canada)

Sent by Microsoft Exchange Server 2010

From: Kramer, Michael (M.T.)
Sent: Monday, May 07, 2012 12:00 PM
To: Marowelli, Bart (B.); Tejada, Angelito (A.S.); DiMarco, Jackie Marshal (J.M.); Sparks, Douglas (D.S.); Massara, Michael (M.G.); Sirgedas, Vitas (V.J.)
Cc: Kramer, Michael (M.T.); Tyler, Jim (J.S.); Madej, Jeanette (J.)
Subject: FW: misfire ICA's

Team, please do not reject either of the recently approved P415 misfire related WERS concerns.

C12559877 actions are being implemented next week.

C12559964. Further refinements of these actions are being evaluated in the wind tunnel this Friday (5/11/12). Given the urgency around addressing the misfire concern, concern authorization was done in parallel with notice release being held until the wind tunnel testing is complete.

Mike Kramer
RWD PT Cooling Supv.
Six Sigma Black Belt
Cell Phone: (313) 805-0190
Text Page: mkramer1
[Page from outside Ford](mailto:mkramer1@ford.com), External email: mkramer1@ford.com

From: Madej, Jeanette (J.)
Sent: Monday, May 07, 2012 11:44 AM
To: Kramer, Michael (M.T.)
Subject: FW: misfire ICA's

They keep missing you

Jeanette Madej
Global Cooling Systems Manager
Phone: 313-805-0189

From: Marowelli, Bart (B.)
Sent: Monday, May 07, 2012 11:28 AM
To: Tejada, Angelito (A.S.); DiMarco, Jackie Marshal (J.M.); Sparks, Douglas (D.S.); Madej, Jeanette (J.); Tyler, Jim (J.S.); Massara, Michael (M.G.); Sirgedas, Vitas (V.J.)
Subject: RE: misfire ICA's

Based on this we are not building them in TT. From Doug's note it looks like we should be rejecting that CR

Doug can you please confirm we should reject the Louver change C12559964

~BART MAROWELLI
Cell: (313) 805-6600
bmarowel@ford.com

From: Tejada, Angelito (A.S.)

Sent: Monday, May 07, 2012 11:26 AM

To: Marowell, Bart (B.); DiMarco, Jackie Marshal (J.M.); Sparks, Douglas (D.S.); Madej, Jeanette (J.); Tyler, Jim (J.S.); Massara, Michael (M.G.); Sirgedas, Vitas (V.J.)

Subject: RE: misfire ICA's

Team, For TT we are building our trucks with the CAC cover/shield. We do not have the louver fins change. Jim was going to provide the timeline on when we can have parts with louver fins change and asses proper VOCF proveout plan.

Lito Tejada

New Model Program

CDS: ATEJADA@FORD.COM

Cell: (313) 805-6585

Dearborn Truck Land Line - 313-337-8538

From: Marowell, Bart (B.)

Sent: Monday, May 07, 2012 10:08 AM

To: Tejada, Angelito (A.S.)

Subject: FW: misfire ICA's

We may need to put a pin in this change

~BART MAROWELLI

Cell: (313) 805-6600

bmarowel@ford.com

From: Sirgedas, Vitas (V.J.)

Sent: Monday, May 07, 2012 8:20 AM

To: DiMarco, Jackie Marshal (J.M.); Sparks, Douglas (D.S.)

Cc: Madej, Jeanette (J.); Tyler, Jim (J.S.); Marowell, Bart (B.); Massara, Michael (M.G.)

Subject: RE: misfire ICA's

Plan I have is that TT builds were going to be updated through Approved On-Site Mod Alert A12562506. (captures intent of C12559877/C12559964)

I have no information that either C12559877 nor C12559964 Approved CR's need to be rejected...

From: DiMarco, Jackie Marshal (J.M.)

Sent: Monday, May 07, 2012 7:54 AM

To: Sirgedas, Vitas (V.J.); Sparks, Douglas (D.S.)

Cc: Madej, Jeanette (J.)

Subject: RE: misfire ICA's

OK, what is in our TT's that we started building today?

Do we need to reject this CR?

From: Sirgedas, Vitas (V.J.)
Sent: Monday, May 07, 2012 7:53 AM
To: DiMarco, Jackie Marshal (J.M.); Sparks, Douglas (D.S.)
Cc: Madej, Jeanette (J.)
Subject: RE: misfire ICA's

Status of 2 CR's in this note:

C12559877 (add CAC front face cover) – Authorized and Released for 2012 P415 PJ1 Running Change
C12559964 (CAC tube plate revision) – Authorized, but not yet released for 2012 P415 PJ1 Running Change and as flow-thru for 2013 P415 J1...

From: DiMarco, Jackie Marshal (J.M.)
Sent: Sunday, May 06, 2012 7:25 PM
To: Sparks, Douglas (D.S.)
Cc: Madej, Jeanette (J.); Sirgedas, Vitas (V.J.)
Subject: RE: misfire ICA's

Has the CR been rejected?

From: Sparks, Douglas (D.S.)
Sent: Thursday, May 03, 2012 2:07 PM
To: DiMarco, Jackie Marshal (J.M.)
Cc: Madej, Jeanette (J.)
Subject: RE: misfire ICA's

Jackie,

It is not planned at this time. The increased velocity theory did not net measurable benefit (did not work). Based on current test results I do not think this will get to production.

Thank you,

Douglas S. Sparks

P/T Quality and PVT Manager FNA
P/T Integration and Program Management (PTIM)
dsparks3@ford.com 313-805-6096

Administrative Assistant: Tina Tessadri
ttessadr 313 594-1115

From: DiMarco, Jackie Marshal (J.M.)
Sent: Thursday, May 03, 2012 2:00 PM
To: Sparks, Douglas (D.S.)
Subject: RE: misfire ICA's

Thanks, that's C12559877. But what about the CAC internal tube cover we released on C12559964?

From: Sparks, Douglas (D.S.)
Sent: Thursday, May 03, 2012 11:22 AM
To: DiMarco, Jackie Marshal (J.M.); Madej, Jeanette (J.)
Subject: RE: misfire ICA's

Jackie,
The ICA is the shield only, please see attached file:
<< File: April 17th Misfire Update_v2.pptx >>

At this time ICA is only the shield. We do have a misfire cal update that allows FMEM to be active below 15% fuel level (currently does not run below 15% fuel level).

Thank you,

Thank you,

Douglas S. Sparks

P/T Quality and PVT Manager FNA
P/T Integration and Program Management (PTIM)
dsparks3@ford.com 313-805-6096

Administrative Assistant: Tina Tessadri
ttessadr 313 594-1115

From: DiMarco, Jackie Marshal (J.M.)
Sent: Thursday, May 03, 2012 11:07 AM
To: Sparks, Douglas (D.S.); Madej, Jeanette (J.)
Subject: misfire ICA's

Doug or Jeanette, Phil Collareno requested some screen shots of the 2 actions (air deflector and drain tube) so that he can better understand the strategy. Can you help?

Jackie Marshall Di Marco
Chief Engineer - F150/Expedition/Navigator
Mobile: 313-805-3346

From: Dobbs, Dan (K.D.)
Sent: Monday, April 09, 2012 10:31 AM
To: Osepchook, William (W.R.)
Subject: FW: Misfire Tech Posting

-----Original Message-----

From: Dobbs, Dan (K.D.)
Sent: Monday, April 09, 2012 10:30 AM
To: Dobbs, Dan (K.D.)
Subject: RE: Misfire Tech Posting

Okay I pulled the claims and they made no mention of any mods.

Brian Jay is the FSE, and he will handle the Dealer.

-----Original Message-----

From: Dobbs, Dan (K.D.)
Sent: Monday, April 09, 2012 10:23 AM
To: Osepchook, William (W.R.)
Subject: RE: Misfire Tech Posting

Okay - FSE not a part of the fix.

I have to look at the reports for this store.

From: Osepchook, William (W.R.)
Sent: Monday, April 09, 2012 9:57 AM
To: Dobbs, Dan (K.D.)
Subject: Misfire Tech Posting

Hi Dan,

Per conversation please read tech posting. Concern is; what is the fix.

<< File: <http://www.db.fmcdealer.dealerconnection.pdf> >>

PATRICK WALTON
Tipton Ford, Inc.
Nacogdoches, TX
(936) 564-7337

William Osepchook
GEE
Global Engine Engineering
V-Engine Service Engineer
313-805-9191
wosepcho@ford.com

From: Martin, Thomas (T.C.)
Sent: Tuesday, February 14, 2012 3:41 PM
To: Smith, Craig (C.A.)
Cc: Devries, Jason (J.E.); Whitehead, Joseph (J.P.)
Subject: FW: New Emerging Concern - 2011 F-150 MIL DTC P0299 3.5L GTDI


Importance: High

Jason looked this over and we both agree that the fault appears due to misfire FMEM, resulting in P0299 underboost code. Jason/Joe have previously proven this can happen with the flashing MIL, ending in P0299 code. I believe we need to somehow attach this concern to the CAC condensation issue?

From: Nowaczyk, Rick (R.J.)
Sent: Tuesday, February 14, 2012 11:05 AM
To: Dixon, Mark (M.R.); Oyafuso, Kevin (K.G.); Selthofer, Adam (A.); Cockerill, Al (C.A.); Martin, Thomas (T.C.); Osepchook, William (W.R.)
Cc: McDonagh, Scot (S.M.); Dobbs, Dan (K.D.)
Subject: New Emerging Concern - 2011 F-150 MIL DTC P0299 3.5L GTDI
Importance: High

Engineering Team,

We have a New Emerging Concern for 2011 F-150 MIL DTC P0299 3.5L GTDI for low boost. This issue is ramping up quickly in Concern Management based on GCQIS report volume coming into the Tech Hotline.



Regards,
Rick Nowaczyk
FCSD Product Concern Engineer
F-150, Freestar/Monterey, Ford GT, Th!nk
E-mail: rnowaczy@ford.com
Diagnostic Service Center-I, Allen Park
PH# 313-322-7251

RUN DATE:02/14/2012

FORD CUSTOMER SERVICE DIVISION

PAGE: 1

SERVICE, WARRANTY, AND FINANCIAL SYSTEMS DEPARTMENT

CS0115F1 13:20 102111

COMMON QUALITY INDICATOR SYSTEM

TEP20

CQIS Concern Folder

Folder: 110008200000 2 11 V29/E29 3.5 P0299

Status (T,A,C): A ACCEPT/DEFINITE Status Date: 07/06/2011

Follow-up Date: 12/31/9999

Owner: RNOWACZY

Index Points:

Part Nbr: - -

YTD Part Sales: 150

Part Desc:

Backorder:

Resp Person:

Total Reports: 6

Resp Phone: () -

Folder Comments

Date

Comments

09/19/2011

INTERIM ISM MESSAGE RELEASED WASTE GATE
ADJUSTMENT. WSM UPDATED PLANNED

Rpt#: CBGBX007 NHL Rpt: 02/07/2012 Odom: 23,564 M
 Vehicle: 2011 F150 4X4 ,F150 ,SUP CRW,STYSD
 Vin:1FTFW1ET4BF [REDACTED] Bld: 05/04/2011
 Engine: 3.5L-GTDI Calb: BF613C0A Trans: 6R80E Axle: 3800F3.55L A/C: YES
 Dealer ID:USA 00341 Billy Howell Ford Lincoln, Inc Phone:(770) 887-2311
 State: Georgia City: Cumming Orig/Caller: AARON DYKES
 Symptom: 2 27 Q 00 AID/INFO,WNG IND/MESS/C,ENGINE IMAGE,UNKNOWN
 Addl Sym: P0299 Attchmnts: 0
 Fix: Caus. Comp: -- Condition Code:
 KOEO:
 KOEO:
 KOEC:
 KOEC:
 KOER:
 KOER:
 Hotliner: AHUFFMA4 Phone: 313 248-8050 Dist Cd: S1 Atlanta
 Engineering: Phone: TAR:
 Dlr Contact: AARON DYKES Phone: 770 887-2311 Title Cde: T

----- C O M M E N T S -----

Type	Comments
REPAIR	WEB FORM DATA - CONCERN:WHILE PULLING A TRAILER STARTED TO ACCEL TO PASS ENGINE STARTED CUTTING OUT MIL CAME ON, PULLED OVER, RESTARTED ALL OK DIAGNOSTICS: CHECKED FOR CODES, TEST DROVE CND CONDITION, PERFORMED SMPKE TEST ON CAC TUBES AND TURBOS. NO LEAKS. WATCHED ALL TURBO PIDS NO FAULTS OR UNDER BOOST CONDITIONS. WASTE GATE VALVES OPERATING AS DESIGNED. CLEARED CODES DID NOT RETURN ON TEST DRIVES PARTS REPLACED:NONE AT THIS TIME TECH QUESTION:HAS THIS ISSUE BEEN SEEN, PERHAPS A STICKING BYPASS VALVE OR WASTEGATE VALVE.
RECOMM	02/07/2012 10:22AM ALEXANDER HUFFMAN MSS - FCSD - TECH SVC HOTLINE AARON, IF NOT ALREADY PERFORMED RECOMMEND TO FOLLOW PINPOINT TEST HN. RECOMMEND TO ALSO LOAD TEST (WITH THE WASTEGATE REGULATING VALVE SOLENOID AND THE PCM UNPLUGGED ELECTRICALLY) THE TURBOCHARGER WASTEGATE REGULATING VALVE SOLENOID CIRCUITS CE328 AND CBK03. WHILE LOAD TESTING THE CIRCUITS, RECOMMEND TO PERFORM A WIGGLER TEST AND A VOLTAGE DROP TEST. THERE SHOULD BE NO MORE THAN .2V DROP PRESENT ON THE CIRCUIT/S. IF A CIRCUIT CONCERN IS PRESENT, RECOMMEND TO OVERLAY THE AFFECTED CIRCUIT/S FROM PIN TO PIN USING NEW PINS. PAST REPORTS HAVE SHOWN THAT THIS SOLENOID IS THE CAUSE FOR THIS CONCERN.

Rpt#: CBFBE018 NHL Rpt: 02/06/2012 Odom: 7,025 M
 Vehicle: 2011 F150 4X4 ,F150 ,SUP CAB,STYSD
 Vin:1FTFX1ETXBF [REDACTED] Bld: 07/31/2011
 Engine: 3.5L-GTDI Calb: BF613C0A Trans: 6R80E Axle: 3800F3.73L A/C: YES
 Dealer ID:CAN B6274 Heartland Ford Sales Inc. Phone:(780) 998-5450
 Province Alberta City: Fort Saskatchewan Orig/Caller: SEAN, MCILROY
 Symptom: 2 27 Q 68 AID/INFO,WNG IND/MESS/C,ENGINE IMAGE,STAYS ON
 Addl Sym: P0299 Attchmnts: 0
 Fix: Caus. Comp: -- Condition Code:
 KOEO: P0299
 KOEO:
 KOEC:
 KOEC:
 KOER:
 KOER:
 Hotliner: SFERRET Phone: 313 317-9124 Dist Cd: 06 06 FCSD REGION-CANADA
 Engineering: Phone: TAR:
 Dlr Contact: SEAN, MCILROY Phone: 000 000-0000 Title Cde: T

----- C O M M E N T S -----

Type	Comments
REPAIR	WEB FORM DATA - CONCERN:ENGINE LITE ON-NO DRIVEABILITY CONCERNS MENTIONED DIAGNOSTICS: RETRIEVE P0299:00-EC-PCM IN MEMORY-INSPECTED CAC TUBES ETC- NOTHING OBVIOUS NO SMOKE MACHINE AVAILABLE PARTS REPLACED:NONE HERE TECH QUESTION:ANY KNOWN CONCERNS
RECOMM	SEAN, IF A SMOKE MACHINE IS NOT AVAILABLE THE CAC TUBES CAN BE PRESSURIZED WITH UP TO 15 PSI OF REGULATED SHOP AIR AND SUSPECT AREAS SPRAYED WITH SOAPY WATER. VERIFY THE TIP, MAP, AND BARO PIDS READ THE SAME VALUE WITH KOEO. IF NOT, SUSPECT A BIASED SENSOR IS CAUSING THIS DTC TO SET. CARRY OUT PIN POINT TEST HN IN THE PC/ED TO ISOLATE THE CAUSE OF THE P0299. IF THE PIN POINT TEST RESULTS ARE INCONCLUSIVE, HOTLINE DATA INDICATES AN INTERMITTENTLY STICKING WASTEGATE SOLENOID IS THE MOST COMMON CAUSE OF THIS CONCERN.

Rpt#: BLPCJ004 NHL Rpt: 12/16/2011 Odom: 19,931 M
 Vehicle: 2011 F150 4X4 ,F150 ,SUP CRW,STYSD
 Vin:1FTFW1ET0BF [REDACTED] Bld: 03/17/2011
 Engine: 3.5L-GTDI Calb: BF613C0A Trans: 6R80E Axle: 3800F3.73L A/C: YES
 Dealer ID:CAN B2531 Fecteau Ford Inc. Phone:(418) 459-3431
 Province Quebec City: La Guadeloupe Orig/Caller: ERIC LAPIERRE
 Symptom: 2 27 Q 30 AID/INFO,WNG IND/MESS/C,ENGINE IMAGE,FLASHES
 Addl Sym: MIL ON Attchmnts: 0
 Fix: Caus. Comp: -- Condition Code:
 KOEO:
 KOEO:
 KOEC: P0299
 KOEC:
 KOER:
 KOER:
 Hotliner: MGIRARD1 Phone: 313 317-7064 Dist Cd: 02 02 FCSD REGION-CANADA
 Engineering: Phone: TAR:
 Dlr Contact: ERIC LAPIERRE Phone: 418 459-3431 Title Cde: T

----- C O M M E N T S -----

Type	Comments
REPAIR	WEB FORM DATA - CONCERN:MOTEUR LUMIÈRE CHECK ENGINE LIGHT ET FLASH,QUAND ELLE FLASH CLIENT ENTEND COMME DES DÉTONATION ET A DES RATÉ, ET MANQUE DE PUISSANCE,QUAND LA LUMIÈRE ARRETE DE DE FLASHER LE MOTEUR PLUS DANOMALIE.FAITE É DEUX REPRISES. DIAGNOSTICS: PRISE CODE,P0299 EN MÈMOIRE . OASIS SSM#21872.CONTROLE DÉTAILLÉ, HN1-HN2-HN19 ET HN20 RIEN TROUVER.JAI 3 CLIENT AVEC MOTEUR ECOBOOST QUI ONT DES PLAINTES SEMBLABLE ET MEME CODE ET INCAPABLE DE REPRODUIRE SYMPTOME. PARTS REPLACED:NONE TECH QUESTION:AVEZ-VOUS EU DES PLAINTES DE CE GENRE.
RECOMM	ERIC VÉRIFIE POUR MAUVAIS CONTACTE AU G105 , ET FAIT UNE INSPECTION DES BOUGIES , AUSSI VÉRIFIE L'OPÉRATION DES COILS POUR LES BOUGIES

Rpt#: BLPCP010 NHL Rpt: 12/16/2011 Odom: 11,533 M
 Vehicle: 2011 F150 4X2 ,F150 ,SUP CAB,STYSD
 Vin:1FTFX1CTXBF Bld: 08/23/2011
 Engine: 3.5L-GTDI Calb: BF613G0A Trans: 6R80E Axle: 3800F3.55L A/C: YES
 Dealer ID:USA 05539 Sunrise Ford Phone:(909) 822-4401
 State: California City: Fontana Orig/Caller: JOSE MORENO
 Symptom: 2 27 Q 68 AID/INFO,WNG IND/MESS/C,ENGINE IMAGE,STAYS ON
 Addl Sym: P0299 UNDER LOAD CEL FLASHES Attchmnts: 0
 Fix: Caus. Comp: -- Condition Code:
 KOEO:
 KOEO:
 KOEC: P0299
 KOEC:
 KOER:
 KOER:
 Hotliner: MMESSIN4 Phone: 313 322-5105 Dist Cd: W1 Los Angeles
 Engineering: Phone: TAR:
 Dlr Contact: JOSE MORENO Phone: 000 000-0000 Title Cde: T

----- C O M M E N T S -----

Type	Comments
REPAIR	WEB FORM DATA - CONCERN:CHECK ENGINE LIGHT COMES ON WHILE GOIN UP HILLS , LIGHT ALSO FLASHES DIAGNOSTICS: TEST EEC SYSTEM CODE PO299 RUN OASIS FOUND MESSAGE 21872 PERF SMOKE TEST TO CHECK AIR INTAKE HOSES NO LEAKS FOUND, PARTS REPLACED:NONE TECH QUESTION:ANY KNOWN ISSUES WITH THIS VEHICLE? PROBLEM ONLY OCCURS WHEN GOIND UP HILLS ENGINE LIGHT WITH START TO FLASH AND THEN REMAINS SOLID, PO299 WAS ONLY CODE FOUND IN SYSTEM.
RECOMM	12/16/2011 02:52PM MATTHEW MESSINA MSS - FCSD - TECH SVC HOTLINE JOSE, WHEN SMOKE TESTING THE CAC SYSTEM, PLEASE INDUCE 15 PSI OF REGULATED SHOP AIR PRESSURE INTO THE HOSES. THIS AIR PRESSURE WILL SIMULATE A BOOST EVENT, AND HELP LOCATE A SMALL LEAK. PLEASE REPAIR OR REPLACE AS NECESSARY.7 USING IDS, MAP AND TIP_PRS-BOOST WILL MATCH KOEO AT 14.7 PSI (AT SEAL LEVEL). IF MAP SENSOR IS READING LOW, SUSPECT A MAP SENSOR CONCERN IS PRESENT. PLEASE ALSO MEASURE THE EXHAUST BACK PRESSURE OF THIS VEHICLE FOR BOTH BANKS. PLEASE USE ROTUNDA TOOL 309-D002 FOR EXHAUST BACK PRESSURE TESTING. EXHAUST BACK PRESSURE SHOULD NOT EXCEED 3 PSI IN BAY (AFTER 3-4 WOT SNAPS) AND 8 PSI UNDER A HIGH LOAD DRIVING EVENT. IF EXCESSIVE EXHAUST BACK PRESSURE IS DISCOVERED, PLEASE REPLACE THE CATALYST AND RETEST FOR THIS CONCERN.
REPAIR	12/29/2011 03:01PM ADAM HEBERT MSS - FCSD - TECH SVC HOTLINE JOSE STATED THAT WHILE VIEWING THE DATALOGGER THE BANK 2 UEGO WENT DOWN TO .9 EQ_RAT WHILE BANK 1 REMAINED AT 14.7 WHEN THE VEHICLE WAS RUNNING ROUGH. THERE ARE 5 COUNTS ON CYLINDER 4 AND 10 COUNTS ON CYLINDER 5.
RECOMM	12/29/2011 03:01PM ADAM HEBERT MSS - FCSD - TECH SVC HOTLINE JOSE, RECOMMEND TO FIRST PERFORM AN EXHAUST BACKPRESSURE TEST. IF EXCESSIVE BACKPRESSURE IS IDENTIFIED, RECOMMEND TO REPLACE THE CATALYST THEN RE-EVALUATE. IF BACKPRESSURE PROVES OUT OK, RECOMMEND TO APPLY A SUITABLE LOAD WHILE VOLTAGE DROPPING THE UEGO CIRCUITS. NO MORE THAN .2V SHOULD BE DROPPED ON ANY ONE CIRCUIT. IF NO CIRCUIT ISSUES ARE FOUND, PLEASE REPLACE THE BANK 2 UEGO SENSOR THEN RETEST.
AUDIT	12/29/2011 03:01PM ADAM HEBERT MSS - FCSD - TECH SVC HOTLINE

REPAIR ODOMETER 8860 M CHANGED TO 11533 M BY AHEBERT8
12/29/2011 06:03PM ROBERT GARY MSS - FCSD - TECH SVC HOTLINE

Rpt#: BLBBI013 NHL Rpt: 12/02/2011 Odom: 6,581 M
 Vehicle: 2011 F150 4X4 ,F150 ,SUP CRW,STYSD
 Vin:1FTFW1ET1BF Bld: 09/02/2011
 Engine: 3.5L-GTDI Calb: BF613C0A Trans: 6R80E Axle: 3.73 LOCK A/C: YES
 Dealer ID:USA 04036 All American Ford of Kingston, Phone:(845) 338-7800
 State: New York City: Kingston Orig/Caller: BRYAN WOLFF
 Symptom: 2 27 Q 68 AID/INFO,WNG IND/MESS/C,ENGINE IMAGE,STAYS ON
 Addl Sym: P0299 Attchmnts: 0
 Fix: Caus. Comp: -- Condition Code:
 KOEO: P0299
 KOEO:
 KOEC:
 KOEC:
 KOER:
 KOER:
 Hotliner: RCUSHIO1 Phone: Dist Cd: N1 New York
 Engineering: Phone: TAR:
 Dlr Contact: BRYAN WOLFF Phone: 000 000-0000 Title Cde: OT

----- C O M M E N T S -----

Type	Comments
REPAIR	WEB FORM DATA - CONCERN:CUSTOMER STATES UNDER LOAD CHECK ENGINE LIGHT FLASHES. DIAGNOSTICS: CKD FOR CODES FOUND P0299 LOW BOOST DETECTED. CKD AS PER SSM 21872 CKD FOR CAC AIR LEAKS USED SOAPY WATER AND POWER BRAKED VEHICLE TO BUILD BOOST AND NONE FOUND. ROAD TESTED VEHICLE AND MONITORED BOOST ACTUAL AND DESIRED AND THEY FOLLOWED EACH OTHER CLOSELY. PARTS REPLACED:NONE TECH QUESTION:ARE THERE ANY KNOW ISSUES RELATED TO THIS CODE AND OR PROBLEMS WITH THE CAC KNOW? IF NOT WHAT DIRECTION SHOULD I TAKE?
RECOMM	12/02/2011 04:31PM RCUSHIO1 BRYAN, THERE ARE NO COMMON CONCERNS BEING TRACKED FOR THIS CONCERN AT THE HOTLINE. PLEASE INSPECT FOR ANY AFTERMARKET PERFORMANCE COMPONENTS, AS THERE HAVE BEEN REPORTS OF NON-STOCK AIR INLET COMPONENTS CREATING TURBULENT AIR FLOW THROUGH THE MAF. ALSO ENSURE THE AIR FILTER BOX IS SECURE, SEALED AND THERE ARE NO CRACKS, AS THIS CAN ALSO CREATE A TURBULENT AIR FLOW THROUGH THE MAF. SUGGEST MONITORING THE MAP, TIP AND BARO PIODS IN THE IDS KOEO, SINCE THERE IS NO PRESSURE CHANGE AT THIS POINT ALL THREE SHOULD READ APPROXIMATELY 14.7, THIS WILL VALIDATE THEIR STARTING POINT. IF ANY DO NOT, IT WOULD INDICATE A SENSOR IS CAUSING THE CONCERN. A RESTRICTED EXHAUST MAY CONTRIBUTE TO A LOW BOOST CONCERN, SUGGEST PERFORMING AN EXHAUST BACK PRESSURE TEST. INSTALL THE GAUGE IN THE O2 BUNG AND GIVE THE THROTTLE 3-4 WOT SNAPS AND THE PRESSURE SHOULD NOT EXCEED 3PSIAND WHILE DRIVING IT SHOULD NOT EXCEED 8 PSI. THIS WOULD INDICATE A RESTRICTED CATALYTIC CONVERTER.
REPAIR	12/07/2011 04:07PM DAVID CHATFIELD MSS - FCSD - TECH SVC HOTLINE TOOK FOR A ROAD TESTED AND ENGINE LIGHT CAME BACK ON HAD P0430 CAT CODE. RAN THROUGH PPT AND CAT BAD. REMOVED AND FOUND DEBRIS IN MIDDLE SECTION OF CAT. REPLACED CAT ON BANK 2 AND ROAD TESTED OK.
RECOMM	12/07/2011 04:07PM DAVID CHATFIELD MSS - FCSD - TECH SVC HOTLINE BRYAN, THANK YOU FOR PROVIDING US WITH YOUR FEEDBACK ON WHAT FIXED THE VEHICLE CONCERN. PLEASE FILL OUT THE SURVEY TO HELP US MONITOR COMMON TRENDS AND EMERGING CONCERNS. THANKS AGAIN FOR YOUR RESPONSE.

Rpt#: BK2BH011 NHL Rpt: 11/28/2011 Odom: 2,436 M
 Vehicle: 2011 F150 4X4 ,F150 ,SUP CRW,STYSD
 Vin:1FTFW1ET6BK Bld: 07/15/2011
 Engine: 3.5L-GTDI Calb: BF613C0A Trans: 6R80E Axle: 3.73 LOCK A/C: YES
 Dealer ID:USA 09201 Landers Ford Phone:(501) 315-4700
 State: Arkansas City: Benton Orig/Caller: LARRY BROWN
 Symptom: 5 57 2 39 DRV PERF,HESITATES/STUM,ACCEL,INTERMITTENT
 Addl Sym: P0299 Attchmnts: 0
 Fix: Caus. Comp: -- Condition Code:
 KOEO:
 KOEO:
 KOEC: P0299
 KOEC:
 KOER:
 KOER:
 Hotliner: DRIDOLF2 Phone: 000 248-8241 Dist Cd: C3 Memphis
 Engineering: Phone: TAR:
 Dlr Contact: LARRY BROWN Phone: 000 000-0000 Title Cde: T

----- C O M M E N T S -----

Type	Comments
REPAIR	<p>WEB FORM DATA - CONCERN:TICKET= ENGINE LIGHT ON,FLUTTERING AND VIBRATING WHEN ACCEL RATING TO PASS SOME ONE,,, WRITE UP SHEET VEHICLE VIBRATING BAD AT TIMES,ENGINE LIGHT FLASHING WHEN THIS HAPPENS,FUEL MILEAGE DROPPED WHEN THIS STARTED DIAGNOSTICS: LAST WEEK SOME ELSE CKED IT, HAD ALL PASS CODES,CUST DROVE IT, IT HAPPEN AGAIN, I GOT THIS MORNING, KOEC P0299, ALL OTHERS PASS,WENT THRU PPT HN, FOUND NO PROBLEMS, TESTDROVE HAVE NOT VERFIED CONCERN, BUT AVE MILEAGE WAS 7.3 WHEN I STARTED, IT WAS 8.8 WHEN I GOT BACK TO THE SHOP, THATS WHEN I SEEN THE WRITE-UP SHEET, I SURE THERES A PROBLEM,BUT I DO NOT SEE A TURBO OR CAC CONCERN,BUT SEEING FUEL MILAGE? PARTS REPLACED:NONE TECH QUESTION:I DO MOSTLY DIESEL,UNTIL WE DO NOT HAVE ANY, DO THESE HAVE ANY INJ OR FUEL PUMP CONCERNS OR WIRING THAT WILL NOT SET A CODE? IVE SEEN P0299 IN DIESELS, BUT IT WAS ANOTHER SYSTEM THAT CAUSED BOOST CODE.</p>
RECOMM	<p>11/28/2011 11:34AM DOMINIC RIDOLFI MSS - FCSD - TECH SVC HOTLINE LARRY, -FIRST, WE SHOULD TAKE A FUEL SAMPLE AND CHECK FOR BOTH POOR QUALITY FUEL AS WELL AS PRESENCE OF E85. TO CHECK FOR E85 CONTENT IN THE FUEL, RECOMMEND PERFORMING A WATER TEST. USING A CLEAR BOTTLE, FILL IT HALFWAY WITH WATER, MARK THE LINE, ADD THE SAME AMOUNT OF FUEL FROM THE VEHICLE, MIX TOGETHER, AND ALLOW TO SEPARATE. THE ETHANOL WILL COMBINE WITH THE WATER INCREASING THE WATER LEVEL. AN INCREASE OF WATER LEVEL UP TO 10% IS NORMAL GASOLINE. ANY MORE THAN 10% IS AN E85 MIX. IF AN E85 MIX IS EVIDENT, RECOMMEND DRAINING THE FUEL TANK COMPLETELY, DRY IT OUT, ADD KNOWN GOOD FUEL, CLEAR KAM, AND RETEST. -NEXT, PLEASE INSPECT G105. THIS IS THE GROUND FOR THE BANK TWO IGNITION COILS AND IS LOCATED ON THE BACK OF THE BANK TWO CYLINDER HEAD. 1. ARE YOU ABLE TO LOOSEN THE G105 BOLT USING ONLY FINGER PRESSURE? 2. IF YOU ARE NOT ABLE TO LOOSEN G105 WITH YOUR FINGERS, CAN IT BE TIGHTENED USING ONLY A SOCKET AND A SIX-EIGHT INCH 3/8 DRIVE EXTENSION? (NO RATCHET) 3. PLEASE ENSURE G105 IS CLEANED AND TORQUED TO 10 NM + 45 DEGREES. -THIS CONCERN IS CURRENTLY UNDER INVESTIGATION AND YOUR RESPONSES ARE IMPORTANT AND APPRECIATED. PLEASE UPDATE THIS FORM WITH YOUR FINDINGS REGARDING THE ABOVE TESTS AS WELL AS ANY ADDITIONAL QUESTIONS YOU MAY HAVE, THANK YOU. -THE P0299 MAY</p>

BE CAUSED BY THE MISFIRE, OR THE MISFIRE MAY BE CAUSED BY THE P0299.
PLEASE PERFORM THE ABOVE TESTS AND RE-EVALUATE FOR THE P0299. IF THE

Rpt#: BK2BH011 NHL

Rpt: 11/28/2011

----- C O M M E N T S -----

Type	Comments
	CONCERN IS STILL PRESENT WITH P0299, CONDUCT A CAREFUL INSPECTION OF ALL CAC TUBING. SEE SSM 21872. CHECK THE BANK ONE TURBO (TURBO A) WASTEGATE ROD FOR A LOCKING CLIP THAT FITS OVER THE LOCK NUTS. CHECK FOR DAMAGE/TAMPERING TO THIS ROD. -THIS CODE MAY ALSO BE CAUSED BY EXCESSIVE BACKPRESSURE ON THE BANK IN QUESTION. CHECK BACKPRESSURE AT THE UPSTREAM O2 PORT, USING AN EXHAUST BACKPRESSURE TESTER. AFTER 3-4 WOT SNAPS IN THE STALL BACKPRESSURE SHOULD REMAIN UNDER 3 PSI, OR UNDER 8 PSI DURING WOT ACCELERATION UNDER LOAD. -THE P0299, WHEN NOT CAUSED BY A MISFIRE, IS TYPICALLY CAUSED BY LOOSE OR DAMAGED CAC TUBING. ISM 11-11-021 3.5L GTDI MISFIRE BANK TWO CYLINDERS 4,5,6
REPAIR	11/28/2011 03:18PM SHAWN FERRET MSS - FCSD - TECH SVC HOTLINE FUEL WAS AT 10%, G105 BOLT WAS TIGHT
RECOMM	11/28/2011 03:18PM SHAWN FERRET MSS - FCSD - TECH SVC HOTLINE LARRY, THANK YOU FOR THE RESPONSE ABOUT G105. PLEASE CONTINUE WITH THE RECOMMENDED BACK PRESSURE AND CAC TUBE CHECKS FOR THE P0299 CODE. WITH KOEO THE PIDS FOR TIP, MAP, AND BARO SHOULD ALL READ APPROXIMATELY THE SAME, IF NOT, SUSPECT A BIASED SENSOR OR FAULTY CIRCUIT IS CAUSING THIS DTC. MONITOR FRP AND FRP_DSD DURING THE MISFIRE CONCERN AND VERIFY THEY REMAIN VERY CLOSE TO EACH OTHER AT ALL TIMES. MONITOR LOW SIDE FUEL PRESSURE WITH A MECHANICAL GAUGE AND CONFIRM IT IS BETWEEN 62-75 PSI DURING THE CONCERN.
REPAIR	11/28/2011 05:53PM ALEC MCENTEE MSS - FCSD - TECH SVC HOTLINE I DROVE IT MORE AND STILL HAVENT VERFIED, WE HAVE ANOTHER TRUCK WITH SAME CONCERN, FIRST BOTH HAVE ALMOST A FULL TANK OF FUEL, COMING OFF THE FULL MARK, WE HAVENT VERFIED IT YET. IF IT ONLY HAPPEN AT FULL TANK, EVAP.??, BUT THE SECOND GUY SAID HE COULD SHUT THE TRUCK OFF AND RESTART IT RAN FINE UNTIL IT HAPPEN AGAIN, SA JUST CAME IN SAID THEY HAVE 2 MORE TO BE COMING IN, WHEN ACC. SHUTTERS NO POWER AT TIMES, FUEL MILEAGE DROPS OUT.
RECOMM	11/28/2011 05:53PM ALEC MCENTEE MSS - FCSD - TECH SVC HOTLINE LARRY, -RECOMMEND TO DIAGNOSE THE TRUCKS SEPARATELY, FROM THE DESCRIPTION THERE COULD BE TWO DIFFERENT VEHICLE CONCERNS CAUSING THE SAME DTC ON TWO DIFFERENT VEHICLES. -IN REGARDS TO THE VEHICLE LISTED, TO DIAGNOSE THE DTC LISTED, FIRST OBTAIN MAP AND TCBP PID READINGS KOEO, KOER AT IDLE AND DURING A WOT ACCELERATION (WHILE DRIVING THIS VEHICLE, NOT STATIONARY). * MAP AND TIP_PRS-BOOST WILL MATCH KOEO. THE WILL READ ATMOSPHERIC PRESSURE (14.7 PSI AT SEA LEVEL). * THE TIP_PRS-BOOST WILL STILL READ ATMOSPHERIC PRESSURE KOER BUT THE MAP PID WILL READ ABOUT 4.7 PSI, ASSUMING 20 HG (EVERY 2 HG EQUALS 1 PSI SO 20 HG EQUALS 10 PSI, TAKE 10 PSI AWAY FROM THE KOEO READING AND THIS IS HOW THE 4.7 PSI READING IS DETERMINED). -IF NOT ALREADY PERFORMED SMOKE TEST THE CAC LINES AND THE INTAKE. -IN REGARDS TO THE OTHER VEHICLE, IF THE CONCERN ONLY OCCURS AFTER THE CUSTOMER RE-FUELS THE VEHICLE OR WHEN THERE IS A FULL TANK OF FUEL, FOR TESTING PURPOSES BLOCK OFF THE EVAP SYSTEM. IF THE ISSUE IS NO LONGER PRESENT INSPECT THE EVAP CHARCOAL CANISTER FOR RAW FUEL (TYPICALLY RAW FUEL IN THE EVAP SYSTEM IS CAUSED BY THE CUSTOMER OVER

Rpt#: BK2BH011 NHL

Rpt: 11/28/2011

----- C O M M E N T S -----

Type	Comments
	RE-FUELING THE VEHICLE). IF THERE IS RAW FUEL IN THE EVAP SYSTEM AND THE CUSTOMER IS NOT OVER RE-FUELING THE VEHICLE, REPLACE THE CANISTER PURGE VALVE (LOCATED IN THE ENGINE COMPARTMENT). FOR FURTHER ASSISTANCE WITH THE OTHER VEHICLE, PLEASE SUMMIT A WEB REQUEST FORM FOR THAT VEHICLE VIN#.

From: Oyafuso, Kevin (K.G.)
Sent: Tuesday, November 27, 2012 8:12 AM
To: Nowaczyk, Rick (R.J.); Gernant, Tim (T.R.)
Cc: Massey, Stephen (S.); Dixon, Mark (M.R.); McDonagh, Scot (S.M.); Smith, Craig (C.A.); Whitehead, Joseph (J.P.)
Subject: FW: P-415 3.5L GTDI MISFIRE - Report Summary(s) from a GCQIS Query Disposition
Signed By: koyafuso@ford.com

Tim,
Take a look at the first CQIS report in this note. The improved CAC to mitigate condensation is on back order but there is at least one customer that ended up with a suspect CAT, most likely due to misfiring. I think our recommendation should be to NOT change the CAT until the new CAC is available. This would prevent possible damage to the new CAT if the new CAC was not installed (tech could still install shield and calibration). Any recommendation on your side?

Regards,
Kevin Oyafuso
Ford Motor Company - North America Engineering
PD / Powertrain Integration Management - C&C Quality
Vehicle Operations General Office (VOGO)
17000 Oakwood, Allen Park, MI , 48101
6-Sigma Garage, Office 4B
Phone (313) 805-4908 (koyafuso@ford.com)

From: Nowaczyk, Rick (R.J.)
Sent: Tuesday, November 27, 2012 4:44 AM
To: Oyafuso, Kevin (K.G.)
Subject: P-415 3.5L GTDI MISFIRE - Report Summary(s) from a GCQIS Query Disposition

This email contains 5 report summary(s).

Attachments : 0

Report# :	CKZC5003 NHL	Received:	11/26/2012
CCRG/EPRC:		Date:	
Vehicle:	2012,F150 4X4 ,F150 ,SUP CRW,STYSD ,1FTFW1ET5CK [REDACTED]	Build Date:	02/27/2012
Odometer :	15,065 M	Engine:	3.5L-GTDI
Transmission:	6R80E	Axle:	3.73 LOCK
Dealer:	CAN A3258 Cabot Ford Lincoln Sales Limit	Calibration:	CF613C0A
City:	St Johns	A/C:	YES
Originator:	TREVOR BUTT	Phone#:	(709) 722-8877
Symptom:	5 57 2 39 DRV PERF,HESITATES/STUM,ACCEL,INTERMITTENT		
Status:			
VFG:	V52 DRIVEABILITY		

Report# : CKZD6019 NHL **Received:** 11/26/2012
CCRG/EPRC: **Reviewed Status:** **Date:**
Vehicle: 2012,F150 4X4 ,F150 ,SUP CRW,STYSD **Build Date:** 02/17/2012
,1FTFW1ET6CF [REDACTED]
Odometer : 20,771 M **Engine:** 3.5L- **Calibration:** CF613C0A
GTDI
Transmission: 6R80E **Axle:** 3.73 **A/C:** YES
LOCK
Dealer: CAN B6251 Vegreville Ford Sales & Servic **Phone#:** (780) 632-
2060
City: Vegreville **Province** Alberta **Country :** CAN
Originator: ED NEUDORF
Symptom: 5 54 2 39 DRV PERF,LACK/LOSS PWR ,ACCEL,INTERMITTENT
Status:
VFG: V52 DRIVEABILITY
Additional Symptom: LIMP MODE
Fix: **Causal Component :** --
Condition Code:

Hotliner: BFENNIN1 **Phone:** 313 317-7071 **Regn Cd:** 06 06 FCSD REGION-CANADA

Engineering: **Phone:** **TAR:**
Dlr Contact: ED NEUDORF **Phone:** 000 000-0000 **Title Cde:** T

DTCs:
KOE0:
KOE1:
KOE2:

Comments

:
REPAIR 11/26/2012 06:42PM BRETT FENNING MSS - FCSD - TECH SVC HOTLINE
WEB FORM DATA - CONCERN:VEHICLE WILL LOSE POWER GO INTO LIMP MODE
AND
CHECK ENGINE LIGHT TURNS ON. VEHICLE IS SHUT OFF AND RESTARTED CHECK
ENGINE LIGHT OFF. COMES INTO DEALER WITH NO CODE. CANT RECREATE AT
DEALER. DIAGNOSTICS: HAS HAD TSB 12-10-19 DONE. PARTS
REPLACED:NONE TECH QUESTION:JUST LOOKING FOR SOME FURTHER INFO ON
IF A CONCERN LIKE THIS HAS HAPPEND BEFORE. IS GETTING CUSOTMER TO
DRIVE MONITOR AND BRING IN WITH CHECK ENGINE LIGH ON TO HAVE ATLEAST
A
CODE PRESENT.

RECOMM 11/26/2012 06:42PM BRETT FENNING MSS - FCSD - TECH SVC HOTLINE

ED, THE CONCERN MUST BE DUPLICATED BEFORE ANY REPAIRS ARE ATTEMPTED. IF THE CONCERN CANNOT BE DUPLICATED, RECOMMEND YOU INSTALL

A VDR (IF AVAILABLE) TO CAPTURE A RECORDING OF THE EVENT. THE DATABASE INDICATES THAT AN INTERMITTENT ELECTRONIC THROTTLE BODY (ETB)

FAULT AS THE MOST LIKELY CAUSE OF THIS CONCERN, WITH NO DTC'S PRESENT. THE PCM WILL NOT SET AN ETB DTC UNTIL AN ERROR IN EXCESS OF 6 DEGREES FOR 400MS HAS OCCURRED. AN ETB RELATED DRIVABILITY CONCERN CAN START

TO OCCUR WHEN ERROR EXCEEDS 3 DEGREES AND OCCURRENCE THAT EXCEEDS 200MS. ENSURE THAT THE VEHICLES AIR FILTER IS NOT CONTAMINATED AND IS AN OEM STYLE FILTER. AFTER MARKET OR CONTAMINATED AIR FILTERS CAN CAUSE TURBULENT AIR FLOW ACROSS THE MAF, CAUSING SKEWED READINGS. ALSO

INSPECT THE AIR FILTER HOUSING AND AIR INTAKE SYSTEM FOR PROPER SEALING AND ENSURE NO LEAKS ARE PRESENT. MONITOR MAF_V AND TP2. MAF_V SHOULD BE APPROXIMATELY .7-.9 VOLTS AT IDLE AND SHOULD REMAIN FAIRLY CLOSE TO TP2 THROUGHOUT THE RPM RANGE. IF A CONCERN IS VERIFIED

AND THE AIR FILTER AND AIR INTAKE SYSTEM ARE OPERATING PROPERLY, REPLACE THE MAF SENSOR AND RETEST. IF THE MAF AND AIR INTAKE SYSTEM ARE OPERATING PROPERLY, MONITOR ETB PID'S TO VALIDATE PROPER ETB OPERATION. WHILE ROAD TESTING WITH THE IDS DATALOGGER, MONITOR ETB PID'S ETC_ACT AND ETC_DSD. IDEALLY THESE PID'S SHOULD REMAIN FAIRLY CLOSE (0-1 DEGREES) UNDER STEADY STATE CRUISE, IDLING CONDITIONS AND DURING THE CUSTOMERS CONCERN (IF IT CAN BE DUPLICATED). IF A VARIANCE OF 3 DEGREES OR GREATER IS OBSERVED WITH SMOOTH APP SENSOR INPUT, THIS

WOULD INDICATE AN ETB INTERNAL FAULT. IF VERIFIED, REPLACE THE ETB, RESET KAM AND RE-EVALUATE.

REPAIR 11/26/2012 07:43PM DOMINIC RIDOLFI MSS - FCSD - TECH SVC HOTLINE

DESCRIPTION OF VEHICLE CONCERN: AT HIWAY SPEED, THE WRENCH LIGHT WILL

COME ON AND SPEED IS LIMITED TO 90 KPM, THIS HAS HAPPENED 4 TIMES, GOES AWAY ON ITS OWN AFTER BEING SHUTOFF FOR SOME TIME DIAGNOSTICS ALREADY COMPLETED: SCANNED FOR CODES, NONE, RUNS FINE BY THE TIME THE

CUSTOMER GETS HERE PARTS REPLACED: NONE TECH'S QUESTION: ANY HELP? CUSTOMER IS BECOMING FRUSTRATED, THE ISSUE HAS OCCURED 4 TIMES, 3 TIMES WHEN EMPTY, 1 TIME WHILE PULLING A TRAILER

RECOMM 11/26/2012 07:43PM DOMINIC RIDOLFI MSS - FCSD - TECH SVC HOTLINE

BRIAN, THIS CONCERN WILL LIKELY HAVE TO BE DUPLICATED IN ORDER TO PROPERLY DIAGNOSE. INSTALLATION OF THE FLIGHT RECORDER, OR A POSSIBLE ROAD TEST WITH THE CUSTOMER DRIVING, MAY BE USEFUL IN THIS TYPE OF SITUATION. WITH THE CONCERN PRESENT, MONITOR ETC ACTUAL VS. DESIRED PIDS FOR A DIFFERENCE OF OVER THREE DEGREES. THIS WOULD INDICATE AN INTERNAL ETB FAILURE, REQUIRING ETB REPLACEMENT. MONITOR FUEL TRIMS FOR A LEAN/RICH CONDITION, AND MODE 6/CYLINDER ACCELERATION PIDS FOR ANY MISFIRE DATA. ENSURE THAT FRP ACTUAL IS FOLLOWING FRP DESIRED WITH THE CONCERN PRESENT.

Attachments : 0

Report# : CKZCS001 NHL **Received:** 11/26/2012
CCRG/EPRC: **Reviewed Status:** **Date:**
Vehicle: 2012,F150 4X4 ,F150 ,SUP CAB,STYSD **Build Date:** 07/19/2012
,1FTFX1ET5CFC [REDACTED]
Odometer : 12,154 M **Engine:** 3.5L-GTDI **Calibration:** CF613C0A
Transmission: 6R80E **Axle:** **A/C:** YES
Dealer: USA 05668 Dempewolf Ford **Phone#:** (270) 827-3566
City: Henderson **State:** Kentucky **Country :** USA
Originator: RICK SMITHHART
Symptom: 5 57 2 39 DRV PERF,HESITATES/STUM,ACCEL,INTERMITTENT
Status:
VFG: V52 DRIVEABILITY
Additional Symptom: STUMBLE ON ACCEL
Fix: **Causal Component :** --
Condition Code:

Hotliner: BFENNIN1 **Phone:** 313 317-7071 **Regn Cd:** G3 Cincinnati
Engineering: **Phone:** **TAR:**
Dlr Contact: RICK SMITHHART **Phone:** 270 827-3566 **Title Cde:** T

DTCs:
KOEO:
KOEC:
KOER:

Comments

REPAIR 11/26/2012 01:22PM BRETT FENNING MSS - FCSD - TECH SVC HOTLINE
 WEB FORM DATA - CONCERN:CUST STATES STUMBLE/MISSFIRE ON ACCELERATION
 DIAGNOSTICS: SCAN NO CODES THIS VISIT PARTS REPLACED:LEFT CAT
 LAST VISIT TECH QUESTION:I HAVE TSB 12-11-15 FROM OASIS BROADCAST
 MESSAGES BUT WHEN I RUN VIN ON OASSIS TSB IS NOT UNDER VIN CHECK BUILD
 DATE 12 JULY 2012 WITH BUILD DATE ON OR BEFORE 9/18/2012 PER TSB DO I
 STILL USE TSB EVEN THOUGH TSB NOT ON OASSIS UNDER VIN THANKS

RECOMM 11/26/2012 01:22PM BRETT FENNING MSS - FCSD - TECH SVC HOTLINE
 RICK, TSB 12-11-15 APPLIES TO 2013 F150 3.5L GTDIS BUILT ON OR
 BEFORE 9/18/2012, THIS IS WHY THE TSB DOES NOT SHOW UP ON OASIS FOR
 THIS VIN (2012 F150 3.5L GTDI). PLEASE REVIEW AND PERFORM <="" td="">
 HREF='HTTP://WWW.FORDTECHSERVICE.DEALERCONNECTION.COM/VDIRS/SPUBS/ANUM
 Q.ASP?FLAVOR=DEALERS&SZARTICLE=12-10-19' TARGET='_BLANK'>TSB 12-10-19
 TO ADDRESS THIS CONCERN.

Attachments : 0

Report# :	CKZC4017 NHL	Received:	11/26/2012
CCRG/EPRC:		Date:	
Vehicle:	2012,F150 4X4 ,F150 ,SUP CRW,STYSD ,1FTFW1ET8CF [REDACTED]	Build Date:	05/02/2012
Odometer :	7,349 M	Engine:	3.5L- GTDI
Transmission:	6R80E	Axle:	3.73 LOCK
Dealer:	USA 08518 Robberson Ford Sales, Inc.	Calibration:	CF613K0A
City:	Bend	A/C:	YES
Originator:	DAVID TUCKER	Phone#:	(541) 382- 4521
Symptom:	5 57 2 39 DRV PERF,HESITATES/STUM,ACCEL,INTERMITTENT	Country :	USA
Status:			
VFG:	V52 DRIVEABILITY		
Additional Symptom:	JERK UPHILL/TRAC LIGHT		
Fix:	Causal Component :		--
Condition Code:			

Hotliner: KMART171

Phone: 313 317-9381

Regn Cd: W5 Seattle

Engineering:**Phone:****TAR:****Dlr Contact:** DAVID TUCKER**Phone:** 541 388-2054**Title Cde:** T**DTCs:**

KOEO:C2807 U0401

KOEC:

KOER:

Comments

:

REPAIR 11/26/2012 06:21PM KEVIN MARTIN MSS - FCSD - TECH SVC HOTLINE
 WEB FORM DATA - CONCERN:CLIMBING HILL WITH NO TRAILER, VEHICLE JOLTED
 AND TRAC CONTROL LIGHT CAME ON DIAGNOSTICS: SELF TEST ALL MODULES. PPT A1 TBC CODE C2807 PARTS REPLACED:NONE TECH QUESTION:ACCORDING TO PPT A1 IF VEHICLE DOES NOT HAVE TRAILER FAULT MESSAGE WITHOUT TRAILER HOOKED UP FAULT IS IN TRAILER. NO TRAILER ON VEHICLE NOW, NO TRAILER ON VEHICLE DURING CONCERN. C2807 IS ONLY CODE IN ANY MODULES EXCEPT THE U0401. AND WOULD THAT EVEN CAUSE A JOLT FEELING AND TRAC CONTROL LIGHT? ONLY HAPPEND ONE TIME. PULLED OVER AND SHUT OFF AND RESTARTED AND HAS BEEN FINE. WHAT DO YOU RECOMMEND?

RECOMM 11/26/2012 06:21PM KEVIN MARTIN MSS - FCSD - TECH SVC HOTLINE
 DAVID, THE CONCERN THAT CAUSED THE C2807 SHOULD NOT HAVE RESULTED IN THE STUMBLE WITH NO TRAILER CONNECTED. PER PINPOINT TEST A1, IT IS UNCLEAR IF A FAULT MESSAGE IS PRESENT AT THIS TIME. IF IT IS NOT, WE DO STILL KNOW THAT THE DTC WAS NOT CAUSED BY A TRAILER, THEREFORE THE TEST CAN BE PERFORMED PROCEEDING WITH A2. THE CIRCUITS CAN BE LOAD TESTED WHILE WIGGLING THE WIRES IF NECESSARY. IT WILL LIKELY BE NECESSARY TO DUPLICATE THE STUMBLE CONCERN IN ORDER TO FULLY DIAGNOSE.
 ATTEMPT TO ALSO CAPTURE A RECORDING OF THE EVENT. CHECK FOR ANY LEAKS OR RESTRICTIONS IN THE INTAKE. PERFORM A HIGH PRESSURE FUEL SYSTEM INJECTOR TEST. IF THE CONCERN CANNOT BE DUPLICATED THEN NO FURTHER DIAGNOSTICS ARE RECOMMENDED AT THIS TIME. THANK YOU.

REPAIR 11/26/2012 08:03PM JAMES KOLTZ MSS - FCSD - TECH SVC HOTLINE
 WEB FORM DATA - CONCERN:VEHICLE JOLTED WHILE CLIMBING HILL AND TRAC CONTROL LIGHT CAME ON DIAGNOSTICS: SELF TESTED ALL MODULES. CODE C2807 IN ABS MODULE PARTS REPLACED:NONE TECH QUESTION:PPT FOR TBC CODE C2807 SAYS TO CHECK FOR TBC MESSAGE WITHOUT TRAILER

CONNECTED. NO TRAILER, NO MESSAGE. VEHICLE DID NOT HAVE TRAILER ON IT DURING CONCERN EITHER. ONLY HAPPENED ONCE. COULD THIS CODE EVEN CAUSE

THE JOLT THE CUSTOMER FELT? WHAT DO YOU RECOMMEND?

RECOMM 11/26/2012 08:03PM JAMES KOLTZ MSS - FCSD - TECH SVC HOTLINE

HI BRIAN, A FAULT WITH THE TBC MODULE WOULD NOT BE ABLE TO TRACTION CONTROL LIGHT ON. IF THE TRACTION CONTROL LIGHT WAS ON TO INDICATE A FAULT, A CODE WOULD BE PRESENT IN THE ABS MODULE INDICATING A DIAGNOSTIC DIRECTION. IF THERE ARE NO CODES, SUSPECT THAT THE LIGHT WAS FLASHING DUE TO A TRACTION CONTROL EVENT AT THE TIME. THIS WOULD

ALSO EXPLAIN THE HAPTIC FEEDBACK AS DESCRIBED BY THE CUSTOMER. PLEASE

REFER THE CUSTOMER TO THE OPERATION OF THE SYSTEM AS DESCRIBED STARTING ON PAGE 293 OF THE NEWEST EDITION OF THE OWNER'S MANUAL ONLINE.

Attachments : 0

Report# :	CKZD6008 NHL	Received:	11/26/2012		
CCRG/EPRC:		Date:			
Vehicle:	2012,F150 4X4 ,F150 ,SUP CRW,STYSD ,1FTFW1ETXCK [REDACTED]	Build Date:	02/02/2012		
Odometer :	12,503 M	Engine:	3.5L- GTDI	Calibration:	CF613C0A
Transmission:	6R80E	Axle:	3.73 LOCK	A/C:	YES
Dealer:	CAN B3230 Highland Ford Sales Limited		Phone#:	(902) 752- 8243	
City:	Westville	Province	Nova Scotia	Country :	CAN
Originator:	ROSS DAGENAIS				
Symptom:	5 57 2 39 DRV PERF,HESITATES/STUM,ACCEL,INTERMITTENT				
Status:					
VFG:	V52 DRIVEABILITY				
Additional Symptom:	MIL ON/LACK OF POWER				
Fix:	Causal Component :	--			
Condition Code:					

Hotliner: BFENNIN1

Phone: 313 317-7071

Regn Cd: 03 03 FCSD REGION-CANADA

Engineering:

Phone:

TAR:

Dlr Contact: ROSS DAGENAIS

Phone: 000 000-0000

Title Cde: T

DTCs:

KOEO:

KOEC:

KOER:

Comments

:

REPAIR 11/26/2012 04:01PM BRETT FENNING MSS - FCSD - TECH SVC HOTLINE
 WEB FORM DATA - CONCERN:CUSTOMER COMPLAINS OF ENGINE LIGHT ON AND
 RUNNING ROUGH AND LACKS POWER DIAGNOSTICS: IDS TEST P0430 RELEVANT
 TO TSB12-10-19 PARTS REPLACED:NONE TECH QUESTION:THE NEW CAC IS
 NOT AVAILIBLE AT THIS TIME (NO STOCK) DO YOU RECOMEND REPLACING THE
 CATALYST AT THIS TIME<="" td="">
 REPLACE THE CAC AND CAT AT THE SAME TIME ,ASSUMING THE CAC IS THE
 CAUSAL FOR PREMATURE CATALYS FAILURE DUE TO MISFIRE
 CONCERN.....PLEASE ADVISE

RECOMM 11/26/2012 04:01PM BRETT FENNING MSS - FCSD - TECH SVC HOTLINE
 ROSS, IT IS NOT RECOMMENDED TO REPLACE THE CATALYST CONVERTER UNTIL
 THE CAC IS INSTALLED. RECOMMEND TO EMERGENCY ORDER THE NEW CAC AT
 THIS
 TIME. ONCE THE NEW CAC IS RECEIVED IT IS RECOMMENDED TO PERFORM TSB
 12-10-19 AND REPLACE THE CATALYST CONVERTER. PLEASE DO NOT UPDATE
 THE
 PCM UNTIL THE NEW CAC IS READY TO INSTALL.

From: Andersen, Erik (E.)
Sent: Wednesday, February 06, 2013 7:16 PM
To: Sowards, John (J.); Huang, Larry (L.)
Subject: FW: P415 CBV

FYI...my goal is to be there for this testing as well. What time do you think it will start? Right now it is slated to be the second run after the baseline.

Erik Andersen
Core P/T Cooling
eanderse@ford.com
313-805-2966

From: Devries, Jason (J.E.)
Sent: Wednesday, February 06, 2013 2:52 PM
To: Andersen, Erik (E.)
Subject: RE: P415 CBV

Erik,

I have managed to get PT-diag setup to have the capability to open the CBV. Let me know when you are ready to do this on Friday and I will come down to DTF to get it setup to run that way.

Jason DeVries

Calibration Commodity Technical Specialist
GTDI, I4, and V6 Powertrains
Phone: 313-805-1035
e-mail: jdevrie4@ford.com

From: Andersen, Erik (E.)
Sent: Monday, February 04, 2013 7:22 PM
To: Devries, Jason (J.E.)
Subject: RE: P415 CBV

I'd like to run the whole 60 minutes to see how it does. Analytical data suggest that if I drop the pressure even 2" I cut the formation rate in half.

Erik Andersen
Core P/T Cooling
eanderse@ford.com
313-805-2966

From: Devries, Jason (J.E.)
Sent: Monday, February 04, 2013 7:18 PM

To: Andersen, Erik (E.)
Subject: RE: P415 CBV

I will attempt to try it in one of our vehicles, I will also have to talk to the hardware guys to see how the hardware will handle it. I have been told in the past that with the electric valves the electronics will overheat if they stay in an energized state for a long period of time, I think it is more a long term durability thing, but I still want to ask. Do you want to run a whole 60 min. test or do you just want to open it during the cruise to see how much the pressure drops?

Jason DeVries

Calibration Commodity Technical Specialist
GTDI, I4, and V6 Powertrains
Phone: 313-805-1035
e-mail: jdevrie4@ford.com

From: Andersen, Erik (E.)
Sent: Monday, February 04, 2013 6:17 PM
To: Devries, Jason (J.E.)
Subject: RE: P415 CBV

That would make it so much easier.

Erik Andersen
Core P/T Cooling
eanderse@ford.com
313-805-2966

From: Devries, Jason (J.E.)
Sent: Monday, February 04, 2013 5:03 PM
To: Andersen, Erik (E.)
Subject: RE: P415 CBV

If it is a 2013 then it is an electric CBV so we should just be able to command it open. I think we can do it will PT-diag but we will have to try it.

Jason DeVries

Calibration Commodity Technical Specialist
GTDI, I4, and V6 Powertrains
Phone: 313-805-1035
e-mail: jdevrie4@ford.com

From: Andersen, Erik (E.)
Sent: Monday, February 04, 2013 4:57 PM
To: Devries, Jason (J.E.)
Subject: RE: P415 CBV

It's a 2013.

Is this something you can check on one of your vehicles? If we need to figure out a vacuum source we can work on that now.

Erik Andersen
Core P/T Cooling
eanderse@ford.com
313-805-2966

From: Devries, Jason (J.E.)
Sent: Monday, February 04, 2013 4:55 PM
To: Andersen, Erik (E.)
Subject: RE: P415 CBV

What level of P415 do you have: 2011, 2012, or 2013? We can come up with a way to make it be open, but it will likely require an external vacuum source since even if we command it open we might run out of vacuum to hold it open during the cruise.

Jason DeVries

Calibration Commodity Technical Specialist
GTDI, I4, and V6 Powertrains
Phone: 313-805-1035
e-mail: jdevrie4@ford.com

From: Andersen, Erik (E.)
Sent: Monday, February 04, 2013 4:33 PM
To: Devries, Jason (J.E.)
Subject: P415 CBV

Jason,

We are going to be running a P415 this Friday to baseline it against our latest test. I would like to run one with CBV open to reduce the pressure in the CAC. Are you guys able to put in a development PCM and force it open or somehow poke it in with PTDiag? I believe we ran this on one of the 2.0L before and saw a 2" difference in CAC pressure. The P415 has a huge hole, wondering if we can get a little more and see how it does.

What do you think?

Erik Andersen
Core P/T Cooling
eanderse@ford.com
313-805-2966

From: Huang, Larry (L.)
Sent: Monday, January 30, 2012 1:49 PM
To: Andersen, Erik (E.)
Subject: FW: P415 D35 GTDI Misfire Audio 742 280 62

FYI. Status of coating.

Regards,

Larry Huang
Global Cooling/Heat Exchangers
Phone/Text Message: 313-805-2617
E-mail: lhuang3@ford.com
Building #2-3M29, Mail Drop: 1215

From: Tyler, Jim (J.S.)
Sent: Monday, January 30, 2012 1:24 PM
To: Huang, Larry (L.)
Subject: RE: P415 D35 GTDI Misfire Audio 742 280 62

Last week I sent an inquiry note to SLP Mexico engineering contacts (Blas, Guillermo, and Eduardo) and Joe Lumetta for feedback if they know of any surfactant. No response yet.

Jim Tyler
T1/P552 Cooling
313-805-2565 Bld-2 23P25

From: Huang, Larry (L.)
Sent: Monday, January 30, 2012 11:49 AM
To: Tyler, Jim (J.S.)
Subject: RE: P415 D35 GTDI Misfire Audio 742 280 62

Jim,
Did you get a chance to talk to Valeo to see if they can apply the coating for evaporator to our CAC, just a prototype for our testing? Thanks.

Regards,

Larry Huang
Global Cooling/Heat Exchangers
Phone/Text Message: 313-805-2617
E-mail: lhuang3@ford.com
Building #2-3M29, Mail Drop: 1215

From: Huang, Larry (L.)
Sent: Friday, January 27, 2012 12:47 PM
To: Ladd, John (J.R.); Allan, Valerie (V.J.); Andersen, Erik (E.)
Cc: Tyler, Jim (J.S.)
Subject: FW: P415 D35 GTDI Misfire Audio 742 280 62

Please see the feedback from the person that the team recommended to contact.

It's unlikely we can find a "Implement-Ready" coating material (as well as manufacturing process) to resolve the issue in a short time of period. As matter of a fact, the coating that make water hard to "stick" on the surface will enhance the condensation (changing the "film condensation" to "droplets condensation". We can't say without the testing, if the coating is a resolution.

I suggest:

While we continue investigating the "coating" resolution, we may want to test the idea first: asking Valeo to apply surfactant (for evaporator) onto CAC with their existing process, and testing it. If the result is favorable, then we work 1) with the coating material supplier find right coating material, 2) with Valeo to introduce the "coating process" into the current CAC production line. Thanks.

Regards,

Larry Huang

Global Cooling/Heat Exchangers

Phone/Text Message: 313-805-2617

E-mail: lhuang3@ford.com

Building #2-3M29, Mail Drop: 1215

From: Bolyard, Jay (John.)
Sent: Friday, January 27, 2012 12:31 PM
To: Huang, Larry (L.)
Subject: RE: P415 D35 GTDI Misfire Audio 742 280 62

Applied to aluminum piston.

The skirt coating is for wear, scuff and friction reduction in oil flood environment - piston to cylinder bore
The piston pin bore coating is for scuff elimination also in oil flood environment.

Neither has anything to do with water. But - surface tension of water on the surface of one or the other may be reduced vs. on parent aluminum... I do not know.

Best Regards,
Jay Bolyard
Piston & Conn Rod Assy Technical Expert
Tel: (313)805-9465, Building #1, 12G003

From: Huang, Larry (L.)
Sent: Friday, January 27, 2012 12:20 PM
To: Bolyard, Jay (John.)
Subject: RE: P415 D35 GTDI Misfire Audio 742 280 62

Hi Jay,

Thank you very much for the feedback.

The coatings you mentioned were not for reducing the condensated water to "stick" on the surface? Were the coating on steel or on aluminum? Thanks.

Regards,

Larry Huang

Global Cooling/Heat Exchangers

Phone/Text Message: 313-805-2617

E-mail: lhuang3@ford.com

Building #2-3M29, Mail Drop: 1215

From: Bolyard, Jay (John.)
Sent: Friday, January 27, 2012 11:32 AM
To: Huang, Larry (L.)
Subject: RE: P415 D35 GTDI Misfire Audio 742 280 62

Hello Larry - I apologize that I am running crazy with a stop ship and also traveling for business out of the country starting tomorrow.

There are two potential coatings - one is the skirt coating with is a Dow D10 coating screen printed and cured on the skirt surface. The other is a Manganese Phosphate bath for the pin bore as a solid film lubricant. I can't really imagine how either would prevent condensation on a surface?

Best Regards,
Jay Bolyard
Piston & Conn Rod Assy Technical Expert
Tel: (313)805-9465, Building #1, 12G003

From: Huang, Larry (L.)
Sent: Thursday, January 26, 2012 1:54 PM
To: Bolyard, Jay (John.)
Cc: Ladd, John (J.R.); Allan, Valerie (V.J.); Andersen, Erik (E.)
Subject: RE: P415 D35 GTDI Misfire Audio 742 280 62

Hi, Jay,

We are having "misfiring issue" on P415. A possible root cause is that the condensed water is held inside the turbulator (walls and) channels, and was suddenly pushed out into the engine through AIS ducts when WOT suddenly. The team came up an idea: coating a layer of material on the turbulator surface to reduce the capability of aluminum surface to hold water. The team recommend me to contact to you to know if the coating on the piston can serve this purpose. Would you please share us your coating application on the piston, and provide us the input on the possibility of applying it on a CAC. Thank you very much.

Regards,

Larry Huang
Global Cooling/Heat Exchangers
Phone/Text Message: 313-805-2617
E-mail: lhuang3@ford.com
Building #2-3M29, Mail Drop: 1215

From: Norman, Kristofor (K.R.)
Sent: Thursday, November 17, 2011 4:29 PM
To: Norman, Kristofor (K.R.); Fabien, Phil (P.A.); Smith, Craig (C.A.); Nault, Ben (B.D.); Pierce, Michael (M.A.); Sims, Ivan (I.D.); Morrow, Bill (N.W.); Donahue, Francis (Fran.); Cockerill, Al (C.A.); Fried, Marcus (M.W.); Devries, Jason (J.E.); Whitehead, Joseph (J.P.); Krygowski, Richard (R.J.); Cowher, Terry (T.); Hargreaves, Gregory (G.J.); Garrett, David (D.P.); Sullivan, Todd (T.E.); Imarisio, Valerio (V.); Zott, Brian (B.R.); Mancini, Michael (M.A.); Pawlak, Greg (G.J.); Ahmed, Masood (M.); Dixon, Mark (M.R.); Wilson, David (D.G.); Dusa, Daniel (D.V.); Wagers, Sue (S.K.); Zimlich, Mary (M.); Mingo, Paul (P.C.); Rollinger, John (J.E.); Huberts, Garlan (G.); Baskins, Robert (R.S.); Michela, Mike (M.); Zhou, Jay (J.); Lehto, Scott (S.A.); Mazuchowski, James (J.A.); Hammoud, Mazen (M.); Boerger, Jim (J.G.); Merrell, Robert (R.J.); Stanley, Daniel (D.J.); Ronzi, Bill (W.C.); Palepu, Padmalaya (P.); Stefanski, John (J.C.); Russ, Stephen (S.G.); Glugla, Chris (C.P.); McDonagh, Scot (S.M.); Ricks, Kevin (K.J.); Dobbs, Dan (K.D.); Nowaczyk, Rick (R.J.); Ducklow, Corey (C.S.); Bailey, Owen (O.R.); Gardner, Greg (G.D.); McCoy, Jim (D.); Saad, Thomas (T.J.); Nester, Darren (D.); Bld-1 13F040 (20); Kramer, Michael (M.T.); Ladd, John (J.R.); Madej, Jeanette (J.); Allan, Valerie (V.J.); Yamada, Shuya Shark (S.Y.); Mohan, Robert (R.); Huang, Larry (L.); Andersen, Erik (E.); Bishop, Chris (C.B.); Hermann, Erik (E.H.); Stec, Randall (A.)
Cc: Baldwin, Damien (D.K.); Emery, Jim (J.M.); Bollman, Wes (W.); Lyon, Peter (P.M.); Dumler, Jeff (J.D.); Sparks, Douglas (D.S.); Schaffer, Scott (S.A.); McGearry, David (D.B.)
Subject: P415 D35 GTDI Misfire Audio 742 280 62
When: Thursday, January 26, 2012 12:00 PM-1:00 PM (GMT-05:00) Eastern Time (US & Canada).
Where: Bld-1 13F040 (20)

From: Andersen, Erik (E.)
Sent: Monday, March 04, 2013 7:42 PM
To: Garrett, David (D.P.); Smith, Craig (C.A.); Devries, Jason (J.E.); Norman, Kristofor (K.R.)
Subject: FW: P415 GTDI Misfire - CAC Moisture
Signed By: eanderse@ford.com

Sensitivity: Private

Guys,

This issue continues to plague us. Is there any merit in retesting any of these? Given that we have less than 18 months of production, I think we could probably rule some of them out. However, is there anything that could be done as a "service only" type corrective action?

I tend to shy away from anything that would involve active controls of any form. Seems it would be a service nightmare. However, I'm open to any feedback you have.

We can discuss further tomorrow at the misfire meeting, but you can see this is starting to get some high level attention.

Thanks,

Erik Andersen
Core P/T Cooling
eanderse@ford.com
313-805-2966

From: Ronzi, Bill (W.C.)
Sent: Monday, March 04, 2013 5:12 PM
To: Andersen, Erik (E.)
Subject: RE: P415 GTDI Misfire - CAC Moisture
Sensitivity: Private

Erik, Can you do an initial sort by re-wording, adding, or deleting items below? We can then provide that preliminary list to Bob Fascetti for his discussions with Mike Berardi with the intent being to show Mike that the team is engaged enough to send the SSM right away.

Bill

From: Ronzi, Bill (W.C.)
Sent: Monday, March 04, 2013 4:25 PM
To: Kramer, Michael (M.T.); Sparks, Douglas (D.S.); Madej, Jeanette (J.); Russo, Scott (S.); Andersen, Erik (E.)
Subject: RE: P415 GTDI Misfire - CAC Moisture
Sensitivity: Private

Erik, Have any of these alternatives been tested along with the latest and greatest CAC and blocker (ie. would be service only - no production).

Test in Conjunction with New CAC & Deflector	Test Results	Tooling	Service Only Variab
--	--------------	---------	---------------------

			Cost
Incremental blocker plate			
Small weep drain (engine off only)			
Centrifugal collector			
CAC bypass duct			
Foam filter cold duct insert			
SS screen insert(s) - similar to old maf screens			
TB gasket splitter/diverter (better distribution of water)			
Honey comb trap at bottom of CAC end tank			
VW TSB valve			

-----Original Message-----

From: Ronzi, Bill (W.C.)

Sent: Monday, March 04, 2013 1:53 PM

To: Kramer, Michael (M.T.); McCoy, Julie (.); Sparks, Douglas (D.S.); Madej, Jeanette (J.); Russo, Scott (S.); Andersen, Erik (E.)

Subject: RE: P415 GTDI Misfire - CAC Moisture

Sensitivity: Private

I'm checking on the Berardi meeting timing. I believe the intention was tomorrow. We need to convince FCSD that the appropriate work is happening so that they'll release the SSM telling dealers not to replace new CAC's.

We'll probably need a short list of Cooling and/or Engine potential "service only" actions under consideration that could provide further directional improvement.

Let's discuss at 4:30 for a few minutes if possible.

Thanks,
Bill

-----Original Message-----

From: Kramer, Michael (M.T.)

Sent: Monday, March 04, 2013 1:35 PM

To: Ronzi, Bill (W.C.); McCoy, Julie (.); Sparks, Douglas (D.S.); Madej, Jeanette (J.); Russo, Scott (S.); Andersen, Erik (E.)

Subject: RE: P415 GTDI Misfire - CAC Moisture

Sensitivity: Private

Clarification. The Berardi meeting is 3/26.

>Mike Kramer
>RWD PT Cooling Supv.
>Six Sigma Black Belt
>Cell Phone: (313) 805-0190
>Text Page: mkramer1
>Page from outside Ford, External email: mkramer1@ford.com

-----Original Message-----

From: Ronzi, Bill (W.C.)

Sent: Monday, March 04, 2013 11:50 AM

To: McCoy, Julie (.); Sparks, Douglas (D.S.); Kramer, Michael (M.T.); Madej, Jeanette (J.); Russo, Scott (S.); Andersen, Erik (E.)
Subject: RE: P415 GTDI Misfire - CAC Moisture
Importance: High
Sensitivity: Private

I believe the Tuesday Mike Berardi meeting is about our plan to address the emerging QSF (repeats with new CAC's).

The 11MY/12MY TSB has been revised to require misfire codes or misfire freeze frame data before replacing CAC's (this was released Friday).

We also have an SSM ready to go out that advises dealers to not replace latest level CAC's with the same part (no added benefit).

FCSD does not want to release that SSM until we have agreement on how to handle the emerging QSF.

I've scheduled a 4:30 meeting today to discuss further.

Bill

-----Original Appointment-----

From: Schwartzenberger, Sandra (S.) On Behalf Of Berardi, Michael (M.A.)
Sent: Monday, March 04, 2013 10:58 AM
To: Fascetti, Robert (R.J.); McCoy, Julie (.); Sparks, Douglas (D.S.); Harrison, Michael (M.J.); Dobbs, Dan (K.D.); Norton, John (J.K.); Kramer, Michael (M.T.); Nowaczyk, Rick (R.J.); McDonagh, Scot (S.M.); Dixon, Mark (M.R.); Ronzi, Bill (W.C.); Ricks, Kevin (K.J.)
Subject: P415 GTDI Misfire - CAC Moisture
When: Tuesday, March 26, 2013 2:00 PM-2:30 PM (UTC-05:00) Eastern Time (US & Canada).
Where: Audio
Sensitivity: Private

Michael Berardi invites you to an Audio Only Personal Conference Meeting.

Audio conference information

US Toll Free Number: +1-888-628-3668
FordNet 248-3668 / Toll: +1-313-248-3668
FordNet 248-3668 / Toll*: +1-313-248-3668
Global call-in numbers:
<https://ford.webex.com/ford/globalcallin.php?serviceType=MC&ED=195382697&tollFree=1>
Toll-free dialing restrictions:
http://www.webex.com/pdf/tollfree_restrictions.pdf

Attendee access code: 222 358 99

* FordNet 248-3668 / Toll should only be used if the primary number does not work.

Use information below only if directed to by the host

Optional WebEx Link: <https://ford.webex.com/mc>
Meeting Number: 716 466 518
Meeting Password: 22235899

MC08

<http://www.webex.com>

From: Osepchook, William (W.R.)
Sent: Wednesday, October 17, 2012 12:43 PM
To: Nowaczyk, Rick (R.J.)
Subject: FW: P415 Misfire QSF Closure

See Bill Ronzi input below.

-----Original Message-----

From: Ronzi, Bill (W.C.)
Sent: Friday, October 12, 2012 12:07 PM
To: McDonagh, Scot (S.M.); Nowaczyk, Rick (R.J.); Dobbs, Dan (K.D.); Osepchook, William (W.R.); Schiltges, Dave (D.); Selthofer, Adam (A.); White, Eric (E.); Kramer, Michael (M.T.); Wagner, Glen (G.C.)
Cc: Sparks, Douglas (D.S.); Ricks, Kevin (K.J.); Madej, Jeanette (J.); Dixon, Mark (M.R.)
Subject: RE: P415 Misfire QSF Closure

Rick/Dan/Glen,

I'm concerned that the verbiage is too loose, essentially only requiring drivability concerns to get the new CAC. When we scoped the plan for this TSB, and discussed a potential for a Prior Approval program, I believe we agreed that either a left bank misfire or catalyst DTC would be a requirement for getting a new CAC. We had then planned to check for one of those two DTC's within the TCA process.

Bill
William C. Ronzi
PTI Quality Supervisor
(313) 805-6140 cell & pgr

-----Original Appointment-----

From: McDonagh, Scot (S.M.)
Sent: Wednesday, October 10, 2012 11:37 AM
To: McDonagh, Scot (S.M.); Nowaczyk, Rick (R.J.); Dobbs, Dan (K.D.); Osepchook, William (W.R.); Schiltges, Dave (D.); Selthofer, Adam (A.); Ronzi, Bill (W.C.); White, Eric (E.); Kramer, Michael (M.T.)
Cc: Sparks, Douglas (D.S.); Ricks, Kevin (K.J.); Madej, Jeanette (J.); Dixon, Mark (M.R.)
Subject: P415 Misfire QSF Closure
When: Friday, October 12, 2012 11:00 AM-11:30 AM (UTC-05:00) Eastern Time (US & Canada).
Where: Teleconference: x13673 Passcode: 21340179#

Please join the Powertrain Quality Team to discuss QSF Service closure plan.

1) Final content for 2011-2012MY and 2013MY TSB releases- Team Input

2) Confirmation from PS&L that Valeo will provide 2,000 2011-2012MY and 250 2013MY 6K775 CACs by ~10/22/12(PT Management request)- Eric White

Scot G. McDonagh
PT Quality Engineering
Phone: (313)337-8091
smcdonag@ford.com

Scot McDonagh invites you to an online meeting using WebEx.

WebEx meeting information

Meeting Number: 710 284 606
Meeting Link: <https://ford.webex.com/ford/j.php?J=710284606>
Meeting Password: This meeting does not require a password.

Audio conference information

To receive a call back, provide your phone number when you join the meeting, or call the number below and enter the access code.

US Toll Free Number: +1-888-628-3668
FordNet 248-3668 / Toll: +1-313-248-3668

Global call-in numbers:

<https://ford.webex.com/ford/globalcallin.php?serviceType=MC&ED=185682342&tolIFree=1>

Toll-free dialing restrictions:

http://www.webex.com/pdf/tollfree_restrictions.pdf

Access code:710 284 606

MC06

<http://www.webex.com>

From: Kramer, Michael (M.T.)
Sent: Monday, June 17, 2013 1:58 PM
To: Weber, Erik (E.M.)
Cc: Andersen, Erik (E.); Sowards, John (J.); Huang, Larry (L.); Kramer, Michael (M.T.); Tyler, Jim (J.S.)
Subject: FW: P415 VPAT Meeting Assignments - 6/14

We are doing the condensation test with a J1 CAC, 7T8F stick-on blocker, and lower bumper grill insert this Friday (6/21). Also doing some other blocker configs in conjunction with J1 CAC and lower bumper grill insert to investigate potential alternative service action that would address both the aesthetic and condensate concerns.

Mike Kramer
RWD PT Cooling Supv.

Six Sigma Black Belt
Cell Phone: (313) 805-0190
Text Page: mkramer1
Page from outside Ford, External email: mkramer1@ford.com

From: Leonardi, Scott (S.A.)
Sent: Monday, June 17, 2013 11:14 AM
To: Crawford, Gerald (F.); Demmith, David (D.J.); Roberts, Paul (P.W.); Michaels, Victor (J.); Kramer, Michael (M.T.); Weber, Erik (E.M.); Maynard, Roger (R.W.); DiTullio, Marc (M.J.); Cutting, Janice (J.M.); Dobbs, Dan (K.D.); Ricks, Kevin (K.J.)
Cc: Mocio, James (J.W.); Frantzeskakis, Petros (Peter.); Leonardi, Scott (S.A.)
Subject: P415 VPAT Meeting Assignments - 6/14

Team,

Below are the assignments from Friday's P415 VPAT. Please review and provide feedback / required info per the comments.

If there are issues with the assignment or uncertain about what is requested please contact me to discuss

.....
.....

NVH Shield Discussion

F/UP: Crawford - Provide parts to NVH week of 8/17 for testing
F/UP: Roberts - Provide Off Road Assessment to team on latest proposal

CAC Blocker Discussion

F/UP: Kramer / Weber - Verify no adverse issues with C/C CAC combined with Bumper Grill and Stick on Blocker
F/UP: Michaels - Get stick on blocker from PT for water fording to verify no issues
VE recommend approval of the blocker for service contingent upon passing 6/21 TASE testing and Water Fording (CR12695680)

Myanmar Fuel Concerns

F/UP: Maynard - Work with J. Cutting and team to verify data and fuel info for next VPAT

Torque Converter Bearing

VE recommends approval of the change for P415

Scott A. Leonardi

F150 Vehicle Engineering

Vehicle Integration Engineer

PDC 1J-F46

☎ 313.805.2747 (Cell)

"The information contained herein is FORD PROPRIETARY information and may include FORD CONFIDENTIAL information as defined in Ford's Global Information Standard II. Reproduction of this document, disclosure of the information, or use for any purpose other than the conduct of business with Ford is expressly prohibited"

From: Alcaraz andrade, Alejandro (M.)
Sent: Wednesday, May 15, 2013 1:26 PM
To: Raver, Jon (J.A.); Allan, Valerie (V.J.); Huang, Larry (L.)
Cc: Kramer, Michael (M.T.)
Subject: FW: Picture of two P415 parts on their way to Greensburg for SWAAT test
Attachments: P415 with grill side blocker SWAAT test parts..doc

Hi,

We are running the SWAAT test and the Cyclic corrosion test on the P415 CAC (DL34 9L440 DA) for these tests we added the bottom sticky blocker. We requested Valeo to cover 7tubes and 8 fins, but they installed the blocker lower than it should be and it covers 7 tubes 7 fins(as shown in the pictures attached). I believe not covering the 8th fin row would not have a significant impact on the test results. Can we continue the test or should we make them change the blocker? Last option requires new blockers and new CACs.

Thanks

Manuel Alejandro Alcaraz Andrade
PTI Cooling System D&R Engineer
Product Development FoM
T + 313 782 2580 USA
T + 52 1 55 35229780 Mexico
Ford: + 52 55 11033489 Mexico
malcara2@ford.com

From: Joseph LUMETTA [<mailto:joseph.lumetta@valeo.com>]
Sent: miércoles, 15 de mayo de 2013 12:05 p.m.
To: Alcaraz andrade, Alejandro (M.)
Cc: Carl HILDINGER; Corey SMALL
Subject: Picture of two P415 parts on their way to Greensburg for SWAAT test

Hello Alejandro

It turns out I was able to get a quick photo of the P415 parts on their way to Carl Hildinger at Valeo Greensburg prior to SWAAT testing.

look to attachment

Have a great day

Joseph Lumetta
joseph.lumetta@valeo.com
office phone 248-209-8237
fax 248-209-8282
cell 248-709-4710

This e-mail message is intended only for the use of the intended recipient(s).
The information contained therein may be confidential or privileged,
and its disclosure or reproduction is strictly prohibited.
If you are not the intended recipient, please return it immediately to its sender
at the above address and destroy it.





20130515_113234.jpg
Type: JPG File
Size: 1.16 MB
Dimension: 2048 x 1232 pixels

From: Smith, Craig (C.A.)
Sent: Monday, June 11, 2012 11:31 AM
To: Hammoud, Mazen (M.)
Subject: FW: Pilot Downshifting 6-4-2 only when the bucket is full, Update.

Mazen,

The latest approach being investigated by EPD is a delay in downshifts depending upon the status of a TBD CAC condensate model. Please see my comments below. I think that this would like to D42 as well as shift response TGW.

Thanks,

Craig Smith
Supervisor - Engine Calibration
3.5L TIVCT GTDI & 3.5L IVCT GTDI Powerpacks
Phone: (313) 805-6345
TEE Bldg cube 1AD08

From: Smith, Craig (C.A.)
Sent: Monday, June 11, 2012 10:47 AM
To: Cockerill, Al (C.A.)
Cc: Jungbluth, Karl (K.); LaVoie, Vince (V.P.); Devries, Jason (J.E.)
Subject: RE: Pilot Downshifting 6-4-2 only when the bucket is full, Update.

Al,

Yes, I indicated that this would not be acceptable at the last meeting. I can see the following issues.

- 1) lack of downshift complaints (Trans Calibration TGW)
- 2) lack of power complaints (D42 Engine Calibration TGW)
- 3) inconsistent behavior, sometimes get a 6-2 immediately, sometimes it's a 6-4 following by a 4-2 after a few seconds. (Trans Calibration TGW)

Vince/Karl,

Your thoughts regarding the viability of variable shift response as a function of an inferred condensate model?

Thanks,

Craig Smith
Supervisor - Engine Calibration
3.5L TIVCT GTDI & 3.5L IVCT GTDI Powerpacks
Phone: (313) 805-6345
TEE Bldg cube 1AD08

From: Cockerill, Al (C.A.)
Sent: Monday, June 11, 2012 10:32 AM
To: Smith, Craig (C.A.)
Subject: FW: Pilot Downshifting 6-4-2 only when the bucket is full, Update.

FYI,
I know you guys own drivability. Are you aware of this action?

The spirit, the will to win, and the will to excel are the things that endure. These qualities are so much more important than the events that occur. The harder you work, the harder it is to surrender.

Vince Lombardi

Al Cockerill
RWD V6 Engine System Supervisor
313-805-2333 C
313-845-0475 O

From: Yamada, Shuya Shark (S.Y.)

Sent: Monday, June 11, 2012 10:12 AM

To: Norman, Kristofor (K.R.); Glugla, Chris (C.P.); Ladd, John (J.R.); Kramer, Michael (M.T.); Palm, Jim (J.R.); Sowards, John (J.); Cockerill, Al (C.A.); Mazuchowski, James (J.A.)

Subject: Pilot Downshifting 6-4-2 only when the bucket is full, Update.

Team,

Here's my update for today.

I can't make today's Misfire Meeting but I have face to face meeting at Livonia with Karl Jungbluth 6R80 Supervisor and Philip Wiethe TS regarding the feasibility of Pilot Downshifting 6-4-2 only when the CAC bucket is full.

Full Bucket = Amount of condensate build up to cause misfire during steady state, plus 6-2 downshift at DTF tests.

The new high velocity CAC holds 80% less water than the production CAC so the idea is to pre-cleans the CAC in 2 seconds at 4th gear 23lb/min before we hit it with 2nd gear 36lb/min if customer manage to fill the bucket with gentle driving and no trailer.

If the RFR CAC has similar characteristics as P415 high velocity CAC, the same pre-cleansing strategy should work on RFR as well when the bucket is full.

Once we get the blessing from Karl and Philip, we will start testing this strategy.

Shark.

From: Tyler, Jim (J.S.)
Sent: Tuesday, August 14, 2012 10:16 PM
To: Kramer, Michael (M.T.)
Subject: FW: PVP&R.
Attachments: PVP&R CAC P415 NEW CAC eCBV Ford Hystorical changes.pdf

CAC misfire change PV proposal for review and approval.

Sent with Good (www.good.com)
Jim Tyler
T1/P552 Cooling
313-805-2565

-----Original Message-----

From: Guillermo GUADARRAMA [guillermo.guadarrama@valeo.com]
Sent: Monday, August 13, 2012 06:04 PM Eastern Standard Time
To: Tyler, Jim (J.S.)
Cc: David CASTILLO
Subject: PVP&R.

Jim,

I am attaching the revised PVP&R for the plastic cover, please review it and send it me back signed, if possible, if not please send me the corrections to re-submit and get the signature.

In this PVP&R is also included another PVP&R for the capacity increase (Crimping machine added) and validation of alternative furnace.

Regards/Saludos,

Guillermo Guadarrama
Valeo Engine Cooling, SLP
Eje 130 Esq. C.F.E.
CP 78395 AP 6-082
San Luis Potosi, Mexico
Tel: +52 (444) 826-66-00, Ext. 6229
mail: guillermo.guadarrama@valeo.com

This e-mail message is intended only for the use of the intended recipient(s).
The information contained therein may be confidential or privileged,
and its disclosure or reproduction is strictly prohibited.
If you are not the intended recipient, please return it immediately to its sender
at the above address and destroy it.

From: Dobbs, Dan (K.D.)
Sent: Wednesday, April 11, 2012 12:48 PM
To: Osepchook, William (W.R.)
Cc: Ricks, Kevin (K.J.); Nowaczyk, Rick (R.J.)
Subject: FW: RE: Misfire Tech Posting
Attachments: <http://www.db.fmcdealer.dealerconnection.pdf>

Okay see what you think I built on your approach.

We do appreciate your patience on this issue. Engineering is aware and working on the issue. There is no approved field service procedure available at this time. Any attempts to modify the Charge Air Cooler or associated Air Intake components will create other driveability concerns. Additionally, modifications will create a non-reimbursable warranty repair if the modified component is replaced. Continue to monitor OASIS for further updates.

Kevin, FYI we have a country cousin Technician who was passing along a purported fix via the message boards and feeding his fellow Techs. This is a posting that Bill and I would like to make to stop the flow of bad information. Your thoughts?

From: Osepchook, William (W.R.)
Sent: Wednesday, April 11, 2012 12:17 PM
To: Dobbs, Dan (K.D.)
Cc: Cockerill, Al (C.A.); Nowaczyk, Rick (R.J.)
Subject: RE: Misfire Tech Posting

Hi Dan,

Please review. This is how I would like to respond to the tech posting. Attached is the tech post. Please add to if you think it is necessary.

Unauthorized Modification of the F-150 Ecoboost Charge Air Cooler system for condensation could effect emissions; it could also lead to Lack of performance, drivability issues, DTCs, and possibly component failures.

William Osepchook
GEE
Global Engine Engineering
V-Engine Service Engineer
313-805-9191
wosepcho@ford.com

[Discussion Boards](#) [Parts & Service Discussion Board](#) [Tech-to-Tech](#) **2012 Ecoboost F-150 intermittent miss**

[Send an email to webmaster](#)

Search Discussion Board:

[View Most Recent Message](#) [Refresh](#) [Open Discussion Boards in a New Window](#)

Search →

Author	Topic: 2012 Ecoboost F-150 intermittent miss	Email Topic	Print Topic
▶ DEKE HOFFMAN Tri Motor Sales, Inc. Oak Harbor, OH (419) 898-2931	I have one that came in with a miss complaint ONCE (for about 10 seconds) after a long highway cruise. Had p0306 in CM but hadn't done it since. I inspected the basics and swapped the plug to #5 incase it did it again. It did it again 6K miles later. No DTC's and no misfires in Mode 6. I thought I saw a few other people posting about this and that engineering was "investigating" Anyone else seen this or heard anything else about it??		
			March 26, 2012 02:59:23 PM
▶ Ben Ramsey Mooresville Ford Mooresville, NC (704) 664-1300	I heard this had to do with condensation from the CAC. TSB 12-2-10 would be the first thing I would do. Our FSE was here and we were discussing it and he said something to the effect the CAC was too efficient causing condensation inside make it miss. This was mainly noticeable on highway cruise decel.		
			March 26, 2012 03:51:25 PM
▶ Mike Schindler Dempewolf Ford Henderson, KY (270) 827-3566	In a few days a p0430 will rear its ugly head Ive put a few cats in left bank. Starts out as a high speed miss and kills the cat,I think its the water in the cac		
			March 26, 2012 05:01:39 PM
▶ FRANK SIMS O'Daniel Ford, Inc. New Haven, IN (260) 748-6200	had engineers here for a couple days they had me change the vacuum harness on top the engine from the turbos along with all plugs and left hand cat. the miss went away but still had the reprogram issues that ford didnt have out at the time so they bought the vehicle back. at that time also there was no moisture in the cac like there has been reported now, also we replaced all the side 2 ign. coils. hope this helps		
			March 27, 2012 08:23:24 AM
▶ Mike Schindler Dempewolf Ford Henderson, KY (270) 827-3566	Ihave replaced the cat on one 2 times in 12k miles and it had new program in it		
			March 27, 2012 10:15:39 AM
▶ DEKE HOFFMAN Tri Motor Sales, Inc. Oak Harbor, OH (419) 898-2931	This one has 11K and I personally know the customer. It has only done this twice so far. I will ask more questions knowing what I know from you gus now and see if I can determine if this is whats happening. The first time he did say it was on a decel after a long highway cruise. That I do know. I'll post back if I find out anything definate. Thanks for the good replies		
			March 28, 2012 12:37:57 PM
▶ PATRICK WALTON Tipton Ford, Inc. Nacogdoches, TX (936) 564-7337	Have had the same discussion with our FSE. Have put on 2 drivers side cats so far (2 different trucks) The first one sound exactly like yours Deke. Shoot me an email address and I can give you the fix that we came up with. Havent seen either truck back except for maint. so far.		
			March 28, 2012 08:26:48 PM
▶ MICHAEL CARTA Rainbow Ford, LLC La Follette, TN (423) 562-2251	Ask your customer if it was raining at any point during his long highway cruise. We had an 11 f150 Ecoboost w/ similar problem. Problem occured with customer on interstate while raining. We had the truck for a few days. Couldn't duplicate on road tests until it started raining heavy on one of the road tests. Drove again next day same route, speed, etc but dry outside w/ no problem. Started to rain later in the day, took truck out and duplicated again. Had some engineers involved with the cat converter and coil replacements but customer decided to take the truck back to selling dealer in FL to deal with the problem. Haven't heard anything since.		
			March 28, 2012 10:07:58 PM
▶ Gary Gearner Crossroads Ford Lincoln of San Sanford, NC (919) 775-2221	Have had a couple here with that issue. Last one we found that there was oil in the turbo. Found PCV valve stuck open allowing oil to get to the turbo and CAC. Had to clean the CAC and also found water in the CAC with oil from the PCV valve stuck open. Cleaned the turbo and the CAC tubes as well. Water in the CAC is definitely from the condensation issue. Vehicle still had issues after the repair and reprogram. Ended up going to RAV.		

- March 29, 2012 12:19:31 PM
- ▶ **DEKE HOFFMAN**
Tri Motor Sales, Inc.
Oak Harbor, OH
(419) 898-2931
- Partick, I'd appreciate any info horspla65@hotmail.com
- March 29, 2012 04:31:18 PM
- ▶ **JAMIE HACK**
Don Franklin Ford, Inc.
Columbia, KY
(270) 384-3016
- patrick me to ive got 2 of them here my email is jhack71@googlemail.com
- March 29, 2012 04:58:10 PM
- ▶ **STEVEN CLINE**
Ford Country of Lewisville
Lewisville, TX
(972) 221-2900
- Patrick, isnt this the discussion board for things like you have found? i bet we would all like to know what you guys come up with down there.
just my 0.02 thx
- March 29, 2012 05:41:09 PM
- ▶ **DEKE HOFFMAN**
Tri Motor Sales, Inc.
Oak Harbor, OH
(419) 898-2931
- Steven, actually its not, but we just do it sometimes. I'm suspecting he used some knowledge and experience and came up with something on his own, not from the book. In Fords world, if its not in the book, its not possible, which is dead wrong. Having said that, maybe he doesn't want to put it all out there. Just sayin
- March 30, 2012 08:33:40 AM
- ▶ **kyle rosen**
Cox Motor Sales, Inc.
New Richmond, WI
(715) 246-2561
- Patrick send it my way please!! hoheisel1@yahoo.com
- March 30, 2012 03:29:51 PM
- ▶ **Rick Barlau**
North Star Ford
Duluth, MN
(218) 727-3673
- Patrick send to smtech46@yahoo.com
- April 2, 2012 04:31:38 PM
- ▶ **James Strothers**
New Holland Ford
New Holland, PA
(717) 354-4901
- patrick send to jstrothers@newhollandauto.com
- April 4, 2012 09:39:37 AM
- ▶ **Joshua Loney**
Kayser Ford Stoughton
Stoughton, WI
(608) 873-5621
- patrick can i get an email to thanks loneyj2@gmail.com
- April 4, 2012 10:42:24 AM
- ▶ **james northam**
Hertrich Ford of Pocomoke
Pocomoke City, MD
(410) 957-3333
- well while you are at it please send me one to thanks for your time doug290@earthlink.net
- April 4, 2012 10:51:35 AM
- ▶ **MARVIN BITSILLY**
Gurley Motor Company
Gallup, NM
(505) 722-6621
- i need all the help i can get.please send it my way. mnbitsilly@hotmail.com
- April 4, 2012 11:27:32 AM
- ▶ **DONALD REIK JR**
Mullinax Ford East
Wickliffe, OH
(440) 585-8000
- djreik@yahoo.com
- April 4, 2012 12:22:00 PM
- ▶ **Daniel Toronski**
Leith Lincoln
Raleigh, NC
(919) 872-9500
- please send me one? thanks for your time and input. dtoronski@nc.rr.com
- April 4, 2012 02:29:21 PM
- ▶ **Vernie Newton**
Olathe Ford Lincoln
Olathe, KS
(913) 782-0881
- Me too please. carslayer11@yahoo.com Thanks.
- April 4, 2012 03:25:28 PM
- ▶ **John Lewis**
Classic Ford Lincoln of Columb
Columbia, SC
(803) 779-5977
- one more please streetglider79@gmail.com
- April 4, 2012 04:13:15 PM
- ▶ **Eric Wiedeman**
Courtesy Ford Lincoln Sales, I
Norfolk, NE
(402) 371-9350
- send one my way if u get a chance. thanks. fritow1234@yahoo.com
- April 4, 2012 05:33:44 PM
- ▶ **JEFFREY NEUHAUS**

- Ed Koehn Ford of Wayland, Inc.
Wayland, MI
(269) 792-2205
ADD ME PLEASE fordisking2003@yahoo.com Thanks
April 5, 2012 02:22:50 PM
- ▶ **GARY STUTZ**
Moon Township Ford
Moon Township, PA
(412) 264-2360
Send me 1 too gstutz1@verizon.net thanks
April 5, 2012 03:13:45 PM
- ▶ **JOSEPH POWERS**
Alan Jay Ford Lincoln
Sebring, FL
(863) 385-0144
I hate to do this,but I could use it too joemama@strato.net
April 6, 2012 02:45:42 PM
- ▶ **THOMAS NEHL**
Freese Motors, Inc.
Monticello, IA
(319) 465-3541
just got the ticket on one t-nehl@hotmail.com THANK YOU
April 6, 2012 04:45:50 PM
- ▶ **MICHAEL CARTA**
Rainbow Ford, LLC
La Follette, TN
(423) 562-2251
Send one our way please!! michaelbcarta@yahoo.com THANKS!!!
April 6, 2012 04:57:07 PM

[Return to top of page](#)[Refresh](#)

From: Cockerill, Al (C.A.)
Sent: Thursday, June 02, 2011 3:55 PM
To: Osepchook, William (W.R.); Gorgol, Kevin (K.)
Cc: Reno, George (G.L.)
Subject: FW: Report Summary for the CQIS Report#BEIA4008

Guy's, I would like to put a SSM out for any 3.5L Tivct GTDI vehicle that experiences lack of power, mis-fire, P0340 code, to inspect ground on the rear of the LH head

The spirit, the will to win, and the will to excel are the things that endure. These qualities are so much more important than the events that occur. The harder you work, the harder it is to surrender.

Vince Lombardi

Al Cockerill
RWD V6 Engine System Supervisor
313-805-2333 C
313-845-0475 O

From: Steslicki, Michael (M.E.)
Sent: Thursday, June 02, 2011 12:40 PM
To: Crudo, Frank (F.J.); Dixon, Mark (M.R.); Oyafuso, Kevin (K.G.); Cockerill, Al (C.A.); Reno, George (G.L.); Merrell, Robert (R.J.); Smith, Craig (C.A.); Sims, Ivan (I.D.); Parnell, Bill (W.)
Cc: Davis, Craig (C.B.)
Subject: FW: Report Summary for the CQIS Report#BEIA4008

Thanks Craig!

FYI - this is from a GCQIS report from about a month ago for a P415 GTDI with codes P0300, P0305, P0306, P0430. Craig is sending me the parts. Please note the last comment about the ground G105 being loose.

Mike Steslicki
Quality Analyst
Ford Motor Company
Large Gas & Diesel Engine Engineering
(313) 805-9888

From: Davis, Craig (C.B.)
Sent: Thursday, June 02, 2011 11:16 AM
To: Steslicki, Michael (M.E.)
Subject: RE: Report Summary for the CQIS Report#BEIA4008

Mike, just followed up with the dealer (rather has one of our French people re-contact the dealer)

- All stored DTCs...P0300, P0305, P0306, P0430
- Freeze Frame and Mode 6 Data...sent into Hotline
- Check ST and LT Fuel Trims for inference on whether E-85 is used (GTDI is not an FFV application) or other fuel issue...E85 not used, name brand fuels used 87 octane
- Replace all Bank 2 coils and plugs (assuming P430)...replaced Bank COPs, Cat and spark plugs returned to Warranty Parts Evaluation to be forwarded to engineering
- Replace catalyst
- Get any customer information on misfires (tactile misfire or reports of flashing MIL) and fuel use....travelling on the highway when the CEL came on
- Get fuel sample if any indication of E85 use
- Resistance Check on Bank 2 Coil Ground (G105) ...Ground bolt in back of head was loose, took two complete turns to tighten

Hope this helps

From: Davis, Craig (C.B.)
Sent: Thursday, May 12, 2011 2:28 PM
To: Steslicki, Michael (M.E.)
Subject: RE: Report Summary for the CQIS Report#BEIA4008

Michael, dealer has been contacted and advised to perform these additional tests/parts replacement and to forward to our Part return Centre for forwarding to you.

I have updated the GCQIS report

From: Steslicki, Michael (M.E.)
Sent: Wednesday, May 11, 2011 3:00 PM
To: Davis, Craig (C.B.)
Subject: FW: Report Summary for the CQIS Report#BEIA4008

Craig, please call this dealer and have him replace the bank 2 catalytic converter, COP's, and spark plugs. Please request the parts and then ship them to me.

Please see the attached note for what we'd like to get from the dealer for this vehicle.

-
- All stored DTCs
 - Freeze Frame and Mode 6 Data
 - Check ST and LT Fuel Trims for inference on whether E-85 is used (GTDI is not an FFV application) or other fuel issue
 - Replace all Bank 2 coils and plugs (assuming P430)

- Replace catalyst
- Get any customer information on misfires (tactile misfire or reports of flashing MIL) and fuel use.
- Get fuel sample if any indication of E85 use
- Resistance Check on Bank 2 Coil Ground (G105)

From: MSTESLIC@ford.com [mailto:MSTESLIC@ford.com]
Sent: Wednesday, May 11, 2011 2:59 PM
To: Steslicki, Michael (M.E.)
Subject: Report Summary for the CQIS Report#BEIA4008

Attachments : 0

Report# :	BEIA4008 NHL	Received:	05/09/2011
CCRG/EPRC:		Reviewed Status:	Date:
Vehicle:	2011,F150 4X4,SUP CRW,STYSD ,1FTFW1ET6BF [REDACTED]	Build Date:	04/14/2011
Odometer :	561 M	Engine:	3.5L-GTDI Calibration:
Transmission:	6R80E	Axle:	3800F3.73L A/C: YES
Dealer:	CAN B2515 Jacques Olivier Ford Inc.	Phone#:	(450) 445-3673
City:	St-Hubert	Province	Quebec
Originator:	RONALD PROULX	Country :	CAN
Symptom:	6 98 2 98 DRVABL,INDICATOR,CHECK ENGINE,MIL ONLY		
Status:			
VFG:	V29 CHECK ENGINE LIGHT		
Additional Symptom:	P0430, P0300, P0305, P0306		
Fix:	Causal Component :		
Condition Code:			

Hotliner: SLAMOND1 **Phone:** 313 317-9296 **Regn Cd:** 02 02 FCSD REGION-CANADA

Engineering: **Phone:** **TAR:**

Dlr Contact: RONALD PROULX **Phone:** 450 445-3673 **Title Cde:** T

DTCs:

KOEO:

KOEC:P0430 P0300 P0305 P0306

KOER:

Comments

:

REPAIR 05/09/2011 03:14PM SEBASTIEN LAMONDE MSS - FCSD - TECH SVC HOTLINE
WEB FORM DATA - CONCERN: LUMIERE CHECK ENGINE RESTE
ALLUME DIAGNOSTICS: VERIFIER PLAINTE CONFIRMER, IDS TEST PCM CMDTC
P0300,P0305,P0306,P0430 CATALYSEUR BANK 2 DEFECT CONFIRMER AVEC IDS,
KOE0 KOER P1000 PARTS REPLACED:: NONE TECH QUESTION: EXISTIL
AUTRE PLAINTE A SE SUJET POUR PROBLEME AVEC CATALYSEUR SELON UN
CONFRERE DE TRAVAIL QUI A SUIVIE UN COUR CHEZ FORD A LAVAL , IL Y A UN
PROBLEME AVEC LES CATALYSEURS F150 ECOBOOST

RECOMM 05/09/2011 03:14PM SEBASTIEN LAMONDE MSS - FCSD - TECH SVC HOTLINE
SALUT RONALD, NOUS RECEVONS DES CONTACTS SIMILAIRES DE TEMPS À
AUTRE
MAIS, CE N'EST PAS TOUJOURS LA MÊME CHOSE QUI EST À LA SOURCE DU
SYMPTÔME. BASÉ SUR L'INFORMATION QUE TU NOUS DONNE, NOUS TE
RECOMMANDONS DE REMPLACER LE CATALYSEUR SUR LA RANGÉ DEUX ET
RÉÉVALUE. TU DOIS DÉTERMINER S'IL Y A UNE CONDITION RICHE OU PAUVRE.
VÉRIFIE LE 'MODE 6 DATA' POUR DE L'INFORMATION SUR LES RATÉS DE
CYLINDRE POUR POSSIBLEMENT ISOLER UN CYLINDRE EN PARTICULIER. VÉRIFIE
LA QUALITÉ ET LA PRESSION D'ESSENCE. LE CODE DE DIAGNOSTIQUE P0300
EST SOUVENT DU À UNE MAUVAISE QUALITÉ D'ESSENCE... EST CE QU'IL Y A
UNE CONSOMMATION D'HUILE OU DE LIQUIDE DE REFROIDISSEMENT? IL EST
POSSIBLE QU'UN INJECTEUR COULE...

From: Graham, David (D.L.)
Sent: Monday, December 19, 2011 3:22 PM
To: Osepchook, William (W.R.); Cockerill, Al (C.A.); Donahue, Francis (Fran.)
Subject: FW: Service Spark Plug for 3.5L TIVCT GTDI Warranty

Presume we will have a PPAP with multiple deviations for ES tests and such. That would be transparent to FCSD

Dave Graham

Sent with Good (www.good.com)

-----Original Message-----

From: Donahue, Francis (Fran.)
Sent: Monday, December 19, 2011 02:26 PM Eastern Standard Time
To: Ricks, Kevin (K.J.); Boerger, Jim (J.G.)
Cc: Nowaczyk, Rick (R.J.); Mazuchowski, James (J.A.); Dobbs, Dan (K.D.); Bonell, Paul (P.S.); Donahue, Francis (Fran.); Graham, David (D.L.)
Subject: RE: Service Spark Plug for 3.5L TIVCT GTDI Warranty

Kevin, Jim:

Below are your questions/answers.

- WERS concern number: **C12503644.**
- Concern Status in WERS: **The WERS Concern has gone to WERS Notice.**
- When does the part go into production at the engine plant? **09Feb2012**
- When does the plug go into production at the assembly plant? **Estimated 16Feb2012 assuming historical 1 week difference between Engine Build Date and Vehicle Build Date.**

Paul Bonell will start the WERS Alert but we can wait until 03 Jan 2012 to put the details together. David Graham in Engine can help us with the Service Alert protocol/approval also. Delaying this until 03 Jan will not impact NGK's actions. They are building spark plugs – The discussion around the Alert is really about where the first shipment goes.

Thanks for your support. +Fran

Revel In Virtue

Francis "Fran" Donahue

Supervisor - Ignition Systems

Ford Motor Company

fdonahue@ford.com 313 622-6482

From: Ricks, Kevin (K.J.)
Sent: Monday, December 19, 2011 9:18 AM
To: Boerger, Jim (J.G.)
Cc: Donahue, Francis (Fran.); Nowaczyk, Rick (R.J.); Mazuchowski, James (J.A.); Dobbs, Dan (K.D.)
Subject: RE: Service Spark Plug for 3.5L TIVCT GTDI Warranty

I am supportive Jim and I will help pursue. Be aware we have great difficulty getting service parts released under an alert, they have to be very specific and will need to include rate and flow for service parts. We know we will get hit hard for demand as soon as the part is available to dealers. We will need some issue specific meetings but to start, can you advise:

- WERS concern number
- Concern Status in WERS
- When does the part go into production at the engine plant?
- When does the plug go into production at the assembly plant?

From: Boerger, Jim (J.G.)
Sent: Friday, December 16, 2011 4:23 PM
To: Ricks, Kevin (K.J.)
Cc: Donahue, Francis (Fran.)
Subject: FW: Service Spark Plug for 3.5L TIVCT GTDI Warranty
Importance: High

Hi Kevin ...

We were not able to connect via phone today - I am supportive of an urgent service action for 3.5L EcoBoost to provide a more robust spark plug produced from production tooling (but prior to full PPAP documentation). Let's discuss on Monday, but if "yes" is a straight forward response, pls reply via e-mail - thanks, Jim

Jim Boerger

Manager - Component Design C Department

Global Engine Engineering

Dearborn - Building 1 - Room 12B092

E-mail jboerger@ford.com - Tel: (313) 805 8536

ONE FORD: ONE Plan - ONE Team - ONE Goal

Share the Ford story at <http://www.thefordstory.com>

From: Donahue, Francis (Fran.)

Sent: Friday, December 16, 2011 4:11 PM

To: Boerger, Jim (J.G.)

Cc: Donahue, Francis (Fran.)

Subject: Service Spark Plug for 3.5L TIVCT GTDI Warranty

Jim:

NGK is scheduled to support Production with the new spark plug (stepped center electrode and smaller gap) on 09 Feb 2012. It would be beneficial to bring the spark plug into Service earlier than 09 Feb prior to NGK completing PPAP. Can we bring those spark plugs into Service under WERS Alert for this action while the PPAP paperwork catches up? This action could gain us 5-8 days in the 8 week timing plan.

Thanks +Fran

Revel In Virtue

Francis "Fran" Donahue

Supervisor - Ignition Systems

Ford Motor Company

fdonahue@ford.com 313 622-6482

From: Osepchook, William (W.R.)
Sent: Friday, November 02, 2012 7:48 AM
To: Cockerill, Al (C.A.)
Subject: FW: TSB 12-10-19 F150 GTDI - CAC Backorder

Do you have a CAC in your back pocket?

From: Osepchook, William (W.R.)
Sent: Friday, November 02, 2012 6:29 AM
To: Schiltges, Dave (D.); Selthofer, Adam (A.)
Subject: FW: TSB 12-10-19 F150 GTDI - CAC Backorder

Oh boy did I call that one.....and I gave them the benefit of the doubt....Nov 12.

From: Ridolfi, Dominic (D.R.)
Sent: Thursday, November 01, 2012 4:12 PM
To: Osepchook, William (W.R.)
Subject: FW: TSB 12-10-19 F150 GTDI - CAC Backorder

You were close...

From: Ridolfi, Dominic (D.R.)
Sent: Thursday, November 01, 2012 4:06 PM
To: Abercrombie, Robert (R.); Barrett, Dale (D.); Chatfield, David (D.); Dowdy, Jonathon (J.); Fenning, Brett (B.); Ferret, Shawn (S.); French, Sean (S.P.); Gammon, Charles (C.); Girard, Mario (y.); Graham, Brian (B.); Hebert, Adam (A.); Higgs, Justin (J.); Houston, Willie (W.); Jacobs, Phil (P.); Johnson, Seth (S.); Kvenvold, Derek (D.); Mason, Nicholas (N.G.); Massey, Stephen (S.); McEntee, Alec (A.); Meers, Brian (B.); Messina, Matthew (M.); Ridolfi, Dominic (D.R.); Romano, Tony (T.); Samson, Jean (J.); Sanders, Kevin (K.); Schmidt, Matthew (M.); Schober, Michael (M.); Sheahan, Karen (K.); Singleton, Sylvain (S.); Smith, Walter (W.A.); Stendardo, David (D.)
Subject: TSB 12-10-19 F150 GTDI - CAC Backorder

Team,

The CAC for TSB 12-10-19 (BL3Z- 6K775-B) is on national backorder.

Please direct dealers to emergency order the part. If they have additional part questions refer them to PACO.

The TSB should not be performed without the CAC – don't flash the PCM unless you've also got the part ready to put in.

Any questions come see Bob or I.

Dominic Ridolfi

3.0/3.5/3.7/GTDI Subject Matter Expert
Ford Technical Hotline
Diagnostic Service Center 1
1700 Fairlane Dr. Allen Park, MI 48101
(313) 248-8241

From: Whitehead, Joseph (J.P.)
Sent: Tuesday, April 10, 2012 2:14 PM
To: Cockerill, Al (C.A.)
Cc: Smith, Craig (C.A.); Ladd, John (J.R.); Palm, Jim (J.R.); Yamada, Shuya Shark (S.Y.); Krygowski, Richard (R.J.)
Subject: FW: UNTITLED.PPT

Al,
Built a blocking plate from corrugated plastic found @ TEE. It's available for testing this Friday.



0 290 ; 23hac-464.0006

Thanks,

Joe Whitehead
3.5L GTDI P415 Calibration
jwhiteh4@ford.com
313 805-5481

From: Cockerill, Al (C.A.)
Sent: Monday, April 09, 2012 12:10 PM
To: Ladd, John (J.R.); Yamada, Shuya Shark (S.Y.); Palm, Jim (J.R.); Whitehead, Joseph (J.P.); Kramer, Michael (M.T.)
Subject: UNTITLED.PPT

Can someone make a blocking plate that is easy to remove and evaluate it effectiveness?



0 290 ; 23hac-464.0006

Eager Beaver
Lawn Care & Landscaping



**Free
Estimates**

313999-4817



Inset plate that
mounts to holes
already available



From: Smith, Craig (C.A.)
Sent: Monday, May 13, 2013 8:06 AM
To: Leisenring, Kenneth (K.C.)
Subject: FW: UPDATE 1. Emission Problem Review Committee Fact Sheet Request - 11EPRC20 - 2011 F150 3.5L Charge Air Cooler

Ken,

Just wanted you to know that we demo'd the CAC condensate misfire for the Government Investigations team by artificially inducing misfire via adding water in the CAC. Apparently they are meeting with NTHSA today or tomorrow and wanted to personally experience the issue.

Thanks,

Craig Smith
Supervisor - Engine Calibration
3.5L TIVCT GTDI & 3.5L IVCT GTDI Powerpacks
Phone: (313) 805-6345
TEE Bldg cube 1AD08

From: Britton, Eric (E.J.)
Sent: Friday, May 10, 2013 3:39 PM
To: Whitehead, Joseph (J.P.)
Cc: Smith, Craig (C.A.)
Subject: RE: UPDATE 1. Emission Problem Review Committee Fact Sheet Request - 11EPRC20 - 2011 F150 3.5L Charge Air Cooler

Thanks for pulling this off on such short notice Joe!

Eric Britton
Government Investigations
Tel. 313-323-2966
Fax: 313-594-2268

From: Smith, Craig (C.A.)
Sent: Thursday, May 09, 2013 11:28 AM
To: Britton, Eric (E.J.); Kramer, Michael (M.T.); Whitehead, Joseph (J.P.)
Subject: RE: UPDATE 1. Emission Problem Review Committee Fact Sheet Request - 11EPRC20 - 2011 F150 3.5L Charge Air Cooler

Joe,

Eric wants his management to experience misfire FMEM. Please call (323-2966) him today and arrange a time to set up a quick demo.

The plan will be to disable injectors to emulate the issue during a passing maneuver. As I explained to Eric, the field issues can range from 1 to 3 cylinders misfiring but FMEM (injector disablement) is only active on up to 2 based upon the

strategies current capability. The 3rd cylinder, however, may not be making significant torque due to the misfire though FMEM action (injector disablement) isn't being taken.

Thanks,

Craig Smith
Supervisor - Engine Calibration
3.5L TIVCT GTDI & 3.5L IVCT GTDI Powerpacks
Phone: (313) 805-6345
TEE Bldg cube 1AD08

From: Britton, Eric (E.J.)
Sent: Thursday, May 09, 2013 10:58 AM
To: Smith, Craig (C.A.); Kramer, Michael (M.T.)
Subject: RE: UPDATE 1. Emission Problem Review Committee Fact Sheet Request - 11EPRC20 - 2011 F150 3.5L Charge Air Cooler

Friday or Monday would be best. We have to call NHTSA by COB Monday to discuss. I think we just need to discuss what is needed to set this up, who can help, and how to get priority if necessary. Thanks!

Eric Britton

Government Investigations
Tel. 313-323-2966
Fax: 313-594-2268

From: Smith, Craig (C.A.)
Sent: Thursday, May 09, 2013 10:54 AM
To: Britton, Eric (E.J.); Kramer, Michael (M.T.)
Subject: RE: UPDATE 1. Emission Problem Review Committee Fact Sheet Request - 11EPRC20 - 2011 F150 3.5L Charge Air Cooler

I can't set up a demo with a vehicle in the next ½ hour.

Thanks,

Craig Smith
Supervisor - Engine Calibration
3.5L TIVCT GTDI & 3.5L IVCT GTDI Powerpacks
Phone: (313) 805-6345
TEE Bldg cube 1AD08

From: Britton, Eric (E.J.)
Sent: Thursday, May 09, 2013 10:11 AM
To: Smith, Craig (C.A.); Kramer, Michael (M.T.)
Subject: RE: UPDATE 1. Emission Problem Review Committee Fact Sheet Request - 11EPRC20 - 2011 F150 3.5L Charge Air Cooler

We need to drive a vehicle and experience this symptom. Do you guys have access to a vehicle?

Eric Britton

Government Investigations

Tel. 313-323-2966

Fax: 313-594-2268

From: Smith, Craig (C.A.)

Sent: Thursday, May 09, 2013 10:08 AM

To: Britton, Eric (E.J.); Kramer, Michael (M.T.)

Subject: RE: UPDATE 1. Emission Problem Review Committee Fact Sheet Request - 11EPRC20 - 2011 F150 3.5L Charge Air Cooler

Besides describing how to recreate the problem, what else do you wish to discuss? This will drive who else, if anyone, needs to be invited.

Thanks,

Craig Smith

Supervisor - Engine Calibration

3.5L TIVCT GTDI & 3.5L IVCT GTDI Powerpacks

Phone: (313) 805-6345

TEE Bldg cube 1AD08

From: Britton, Eric (E.J.)

Sent: Thursday, May 09, 2013 9:50 AM

To: Smith, Craig (C.A.); Kramer, Michael (M.T.)

Subject: RE: UPDATE 1. Emission Problem Review Committee Fact Sheet Request - 11EPRC20 - 2011 F150 3.5L Charge Air Cooler

Is there anyone else I should invite?

Eric Britton

Government Investigations

Tel. 313-323-2966

Fax: 313-594-2268

From: Smith, Craig (C.A.)

Sent: Thursday, May 09, 2013 8:45 AM

To: Britton, Eric (E.J.); Kramer, Michael (M.T.)

Subject: RE: UPDATE 1. Emission Problem Review Committee Fact Sheet Request - 11EPRC20 - 2011 F150 3.5L Charge Air Cooler

I'm available 11-1130am this morning. You can simulate the problem by:

- Removing the air intake tube at the engine throttle plate.

- Pouring 6 oz's of water down the air intake tube such that it accumulates in the CAC.
- Reconnect the air intake tube to the engine throttle plate.
- Starting the engine and gently accelerating to approximately 50mph.
- Perform a quick wide-open-pedal acceleration to force a downshift from 6th to 2nd gear.

Thanks,

Craig Smith

Supervisor - Engine Calibration

3.5L TIVCT GTDI & 3.5L IVCT GTDI Powerpacks

Phone: (313) 805-6345

TEE Bldg cube 1AD08

-----Original Message-----

From: Britton, Eric (E.J.)

Sent: Thursday, May 09, 2013 8:32 AM

To: Kramer, Michael (M.T.); Smith, Craig (C.A.)

Subject: FW: UPDATE 1. Emission Problem Review Committee Fact Sheet Request - 11EPRC20 - 2011 F150 3.5L Charge Air Cooler

Craig, we may need your help. We need to drive a vehicle that exhibits the symptoms in this TSB. Maybe the FMEM mode can be induced through the PCM? Are you available for a short phone call this morning?

Mike, what time is best for you?

Eric Britton

Government Investigations

Tel. 313-323-2966

Fax: 313-594-2268

-----Original Message-----

From: Britton, Eric (E.J.)

Sent: Wednesday, May 08, 2013 3:22 PM

To: Kramer, Michael (M.T.)

Subject: RE: UPDATE 1. Emission Problem Review Committee Fact Sheet Request - 11EPRC20 - 2011 F150 3.5L Charge Air Cooler

Thanks! Mike can this FMEM condition be induced on a vehicle drive?

Eric Britton

Government Investigations

Tel. 313-323-2966

Fax: 313-594-2268

-----Original Message-----

From: Kramer, Michael (M.T.)

Sent: Wednesday, May 08, 2013 2:05 PM

To: Britton, Eric (E.J.)

Subject: FW: UPDATE 1. Emission Problem Review Committee Fact Sheet Request - 11EPRC20 - 2011 F150 3.5L Charge Air Cooler

>Mike Kramer

>RWD PT Cooling Supv.

>Six Sigma Black Belt

>Cell Phone: (313) 805-0190

>Text Page: mkramer1

>Page from outside Ford, External email: mkramer1@ford.com

-----Original Message-----

From: Kramer, Michael (M.T.)

Sent: Monday, May 06, 2013 10:07 AM

To: Fagerman, Todd (T.M.)

Cc: Wilson, Marie (M.); Spencer, Beth (B.); Madej, Jeanette (J.); Russo, Scott (S.)

Subject: RE: UPDATE 1. Emission Problem Review Committee Fact Sheet Request - 11EPRC20 - 2011 F150 3.5L Charge Air Cooler

Here it is

>Mike Kramer

>RWD PT Cooling Supv.

>Six Sigma Black Belt

>Cell Phone: (313) 805-0190

>Text Page: mkramer1

>Page from outside Ford, External email: mkramer1@ford.com

-----Original Message-----

From: Madej, Jeanette (J.)

Sent: Monday, May 06, 2013 9:59 AM

To: Fagerman, Todd (T.M.); Kramer, Michael (M.T.)

Cc: Wilson, Marie (M.); Spencer, Beth (B.)

Subject: Re: UPDATE 1. Emission Problem Review Committee Fact Sheet Request - 11EPRC20 - 2011 F150 3.5L Charge Air Cooler

Ill follow up with Mike

----- Original Message -----

From: Fagerman, Todd (T.M.)

Sent: Monday, May 06, 2013 09:57 AM Eastern Standard Time

To: Kramer, Michael (M.T.); Madej, Jeanette (J.)

Cc: Wilson, Marie (M.); Spencer, Beth (B.)

Subject: RE: UPDATE 1. Emission Problem Review Committee Fact Sheet Request - 11EPRC20 - 2011 F150 3.5L Charge Air Cooler

Mike/Jeanette,

I don't believe we received this on Friday as promised. Status?

As indicted in the notes below, we need to close this document out w/ signatures ASAP. Who are you waiting on? I will engage directly with them.

Regards,
Todd Fagerman
Manager, Car and Truck Certification
Sustainability, Environment and Safety Engineering
(313) 59-40680
email: tfagerma@ford.com

-----Original Message-----

From: Kramer, Michael (M.T.)
Sent: Thursday, May 02, 2013 12:41 PM
To: Spencer, Beth (B.)
Cc: Madej, Jeanette (J.); Wilson, Marie (M.); Russo, Scott (S.); Fagerman, Todd (T.M.); Kramer, Michael (M.T.)
Subject: RE: UPDATE 1. Emission Problem Review Committee Fact Sheet Request - 11EPRC20 - 2011 F150 3.5L Charge Air Cooler

Asking for Raj's help for a signature on an EPRC document really??

Document signoff will be complete by tomorrow.

>Mike Kramer
>RWD PT Cooling Supv.
>Six Sigma Black Belt
>Cell Phone: (313) 805-0190
>Text Page: mkramer1
>Page from outside Ford, External email: mkramer1@ford.com

-----Original Message-----

From: Spencer, Beth (B.)
Sent: Thursday, May 02, 2013 11:49 AM
To: Kramer, Michael (M.T.)
Cc: Madej, Jeanette (J.); Wilson, Marie (M.); Russo, Scott (S.); Fagerman, Todd (T.M.)
Subject: RE: UPDATE 1. Emission Problem Review Committee Fact Sheet Request - 11EPRC20 - 2011 F150 3.5L Charge Air Cooler

Thanks for the update, Mike. We have to provide a signed copy of this fact sheet to Robert Brown next Tuesday, and he offered to call Raj Nair if necessary. We asked him to give us more time, so maybe if you could provide the name of who in the calibration team needs to sign, we can follow up with them and prevent it from being elevated that far. Thanks.

Beth Spencer
Sustainability, Environment & Safety Engineering Ford Motor Company bspencer@ford.com
(313) 33-72635

-----Original Message-----

From: Kramer, Michael (M.T.)
Sent: Monday, April 29, 2013 8:31 AM

To: Spencer, Beth (B.)
Cc: Madej, Jeanette (J.); Wilson, Marie (M.); Russo, Scott (S.); Kramer, Michael (M.T.)
Subject: RE: UPDATE 1. Emission Problem Review Committee Fact Sheet Request - 11EPRC20 - 2011 F150 3.5L Charge Air Cooler

Update. PT Cooling has signed off the Fact Sheet. Out for Calibration signoff. I will follow-up later today.

>Mike Kramer
>RWD PT Cooling Supv.
>Six Sigma Black Belt
>Cell Phone: (313) 805-0190
>Text Page: mkramer1
>Page from outside Ford, External email: mkramer1@ford.com

-----Original Message-----

From: Spencer, Beth (B.)
Sent: Tuesday, April 23, 2013 1:07 PM
To: Kramer, Michael (M.T.)
Cc: Madej, Jeanette (J.); Wilson, Marie (M.); Russo, Scott (S.)
Subject: RE: UPDATE 1. Emission Problem Review Committee Fact Sheet Request - 11EPRC20 - 2011 F150 3.5L Charge Air Cooler

Mike,

We just found out that we're being asked to review the status of this issue with our VP, Robert Brown, next Tuesday. Since this is earlier than the completion date we agreed on, I thought I would let you know and give you the opportunity to finish getting the signatures on your fact sheet by Monday so we can report it as complete when we talk to Robert.

If this isn't possible, we'll assume you're still on track to submit them by COB Wednesday to support the May 2 EPRC.

Thanks!

Beth Spencer
Sustainability, Environment & Safety Engineering Ford Motor Company bspencer@ford.com
(313) 33-72635

-----Original Message-----

From: Kramer, Michael (M.T.)
Sent: Tuesday, April 16, 2013 11:34 AM
To: Spencer, Beth (B.)
Cc: Madej, Jeanette (J.); Wilson, Marie (M.); Russo, Scott (S.); Kramer, Michael (M.T.)
Subject: RE: UPDATE 1. Emission Problem Review Committee Fact Sheet Request - 11EPRC20 - 2011 F150 3.5L Charge Air Cooler

yes

>Mike Kramer
>RWD PT Cooling Supv.
>Six Sigma Black Belt
>Cell Phone: (313) 805-0190
>Text Page: mkramer1
>Page from outside Ford, External email: mkramer1@ford.com

-----Original Message-----

From: Spencer, Beth (B.)

Sent: Tuesday, April 16, 2013 11:23 AM

To: Kramer, Michael (M.T.)

Cc: Madej, Jeanette (J.); Wilson, Marie (M.); Russo, Scott (S.)

Subject: RE: UPDATE 1. Emission Problem Review Committee Fact Sheet Request - 11EPRC20 - 2011 F150 3.5L Charge Air Cooler

OK; then would it be possible to complete for our next meeting, which would be May 2?

Beth Spencer

Sustainability, Environment & Safety Engineering Ford Motor Company bspencer@ford.com

(313) 33-72635

-----Original Message-----

From: Kramer, Michael (M.T.)

Sent: Tuesday, April 16, 2013 11:22 AM

To: Spencer, Beth (B.)

Cc: Madej, Jeanette (J.); Wilson, Marie (M.); Russo, Scott (S.); Kramer, Michael (M.T.)

Subject: RE: UPDATE 1. Emission Problem Review Committee Fact Sheet Request - 11EPRC20 - 2011 F150 3.5L Charge Air Cooler

I will follow-up on the signatures, however, will not be able to complete by tomorrow.

>Mike Kramer

>RWD PT Cooling Supv.

>Six Sigma Black Belt

>Cell Phone: (313) 805-0190

>Text Page: mkramer1

>Page from outside Ford, External email: mkramer1@ford.com

-----Original Message-----

From: Russo, Scott (S.)

Sent: Tuesday, April 16, 2013 11:17 AM

To: Spencer, Beth (B.); Kramer, Michael (M.T.)

Cc: Madej, Jeanette (J.); Wilson, Marie (M.)

Subject: RE: UPDATE 1. Emission Problem Review Committee Fact Sheet Request - 11EPRC20 - 2011 F150 3.5L Charge Air Cooler

Who's signature are we missing?

Scott Russo

Ford Motor Company

PT Cooling Applications Manager

srusso2@ford.com

Phone: 313-805-3059

Page: 3138053059@vtext.com

From: Spencer, Beth (B.)

Sent: Tuesday, April 16, 2013 11:14 AM
To: Russo, Scott (S.); Kramer, Michael (M.T.)
Cc: Madej, Jeanette (J.); Wilson, Marie (M.)
Subject: FW: UPDATE 1. Emission Problem Review Committee Fact Sheet Request
- 11EPRC20 - 2011 F150 3.5L Charge Air Cooler

Hello, Mike and Scott,

I'm the new Chair of the EPRC, and Marie and I were just reviewing the open agenda items. It looks like your item has been open for some time for clerical updates and signatures. We need to officially close this item at our next meeting and require your updates and signatures by COB tomorrow.

Each week it remains open, it involves resources on our part to continue to track it.

Please let me know if you have any questions. Thanks!

Beth Spencer

Sustainability, Environment & Safety Engineering Ford Motor Company bspencer@ford.com

(313) 33-72635

From: Wilson, Marie (M.)
Sent: Monday, March 18, 2013 9:32 AM
To: Kramer, Michael (M.T.); Russo, Scott (S.)
Cc: McClenaghan, Dave (D.)
Subject: RE: UPDATE 1. Emission Problem Review Committee Fact Sheet Request
- 11EPRC20 - 2011 F150 3.5L Charge Air Cooler

Another reminder. I would like to close this item on the EPRC agenda.

Please provide the signed fact sheet. Thank you.

Marie Wilson
Ford Motor Company
Vehicle Environmental Engineering
Homologation & Compliance
Phone: 313-248-2404 MWILSO18@FORD.COM

From: Wilson, Marie (M.)
Sent: Monday, February 18, 2013 11:06 AM
To: Kramer, Michael (M.T.)
Cc: McClenaghan, Dave (D.)
Subject: RE: UPDATE 1. Emission Problem Review Committee Fact Sheet Request
- 11EPRC20 - 2011 F150 3.5L Charge Air Cooler

Reminder: Please complete fact sheet revisions (per review meeting) and have the paper signed. Then, please scan and send the completed copy.

We can close this item in EPRC on Thursday with the completed fact sheet.

Thank you.

Marie Wilson
Ford Motor Company
Vehicle Environmental Engineering
Homologation & Compliance
Phone: 313-248-2404 MWILSO18@FORD.COM

From: Kramer, Michael (M.T.)
Sent: Wednesday, November 28, 2012 3:29 PM
To: Wilson, Marie (M.)
Cc: Oswalt, Greg (G.G.); McClenaghan, Dean (D.C.); Russo, Scott (S.); Madej, Jeanette (J.); Sparks, Douglas (D.S.); Fuher, Michael (M.J.); Leisenring, Kenneth (K.C.); McClenaghan, Dave (D.); Smith, Craig (C.A.); Ronzi, Bill (W.C.); Dixon, Mark (M.R.); Andersen, Erik (E.); Tyler, Jim (J.S.); Kramer, Michael (M.T.)
Subject: RE: UPDATE 1. Emission Problem Review Committee Fact Sheet Request - 11EPRC20 - 2011 F150 3.5L Charge Air Cooler

Updated per your feedback.

<< File: P415 CAC EPRC Fact Sheet_11282012.doc >>

Mike Kramer
RWD PT Cooling Supv.
Six Sigma Black Belt
Cell Phone: (313) 805-0190
Text Page: mkramer1
Page from outside Ford
<https://text.vzw.com/customer_site/jsp/messaging_lo.jsp> , External email:
mkramer1@ford.com

From: Kramer, Michael (M.T.)
Sent: Wednesday, November 28, 2012 8:14 AM
To: Wilson, Marie (M.)
Cc: Oswalt, Greg (G.G.); McClenaghan, Dean (D.C.); Russo, Scott (S.); Madej, Jeanette (J.); Sparks, Douglas (D.S.); Fuher, Michael (M.J.); Leisenring, Kenneth (K.C.); McClenaghan, Dave (D.); Smith, Craig (C.A.); Kramer, Michael (M.T.); Ronzi, Bill (W.C.); Dixon, Mark (M.R.); Andersen, Erik (E.); Tyler, Jim (J.S.)
Subject: RE: Emission Problem Review Committee Fact Sheet Request - 11EPRC20 - 2011 F150 3.5L Charge Air Cooler

Here is the consolidated Fact Sheet (mine and Craig's input) with all updates received as of 8:00 am this morning to support tomorrow's EPRC meeting. The document has been reviewed by both Managers (Scott and Ken).

<< File: P415 CAC EPRC Fact Sheet_11282012.doc >>

Mike Kramer
RWD PT Cooling Supv.
Six Sigma Black Belt
Cell Phone: (313) 805-0190
Text Page: mkramer1
Page from outside Ford
<https://text.vzw.com/customer_site/jsp/messaging_lo.jsp> , External email:
mkramer1@ford.com

From: Wilson, Marie (M.)
Sent: Tuesday, November 27, 2012 1:21 PM
To: Smith, Craig (C.A.); Kramer, Michael (M.T.)
Cc: McClenaghan, Dean (D.C.); Oswald, Greg (G.G.); Russo, Scott (S.); Madej, Jeanette (J.); Sparks, Douglas (D.S.); Fuher, Michael (M.J.); Leisenring, Kenneth (K.C.); McClenaghan, Dave (D.)
Subject: RE: Emission Problem Review Committee Fact Sheet Request - 11EPRC20 - 2011 F150 3.5L Charge Air Cooler

Thanks, Craig! Nice work.

I only have one recommendation. I believe that the OBD system functions as designed/intended even when there is misfire related to the CAC. If that is true, then the OBD section can be populated with "none".

Please send the updated copy to Mike so that he can consolidate for Thursday's meeting.

Thanks again for supporting.

Marie Wilson
Ford Motor Company
Vehicle Environmental Engineering
Homologation & Compliance
Phone: 313-248-2404 MWILSO18@FORD.COM

From: Smith, Craig (C.A.)
Sent: Tuesday, November 27, 2012 12:31 PM
To: Wilson, Marie (M.); Kramer, Michael (M.T.)
Cc: McClenaghan, Dean (D.C.); Oswald, Greg (G.G.); Russo, Scott (S.); Madej, Jeanette (J.); Sparks, Douglas (D.S.); Fuher, Michael (M.J.); Leisenring, Kenneth (K.C.)
Subject: RE: Emission Problem Review Committee Fact Sheet Request - 11EPRC20 - 2011 F150 3.5L Charge Air Cooler

Marie,

I don't have permission to access the link below but Mike provided a copy.

Mike,

Here is a draft of section 2 that I completed and reviewed with Ken.

<< File: FAF03-170-1 CAC Condensate Misfire Section 2 CSMITH24 112712.doc
>>

Please let me know if you have any questions.

Thanks,
Craig Smith
Supervisor - Engine Calibration
3.5L TIVCT GTDI & 3.5L IVCT GTDI Powerpacks
Phone: (313) 805-6345
TEE Bldg cube 1AD08

From: Wilson, Marie (M.)
Sent: Tuesday, November 27, 2012 10:56 AM
To: Kramer, Michael (M.T.)
Cc: Smith, Craig (C.A.); McClenaghan, Dean (D.C.); Oswald, Greg (G.G.);
Russo, Scott (S.); Madej, Jeanette (J.); Sparks, Douglas (D.S.); Fuher,
Michael (M.J.)
Subject: RE: Emission Problem Review Committee Fact Sheet Request - 11EPRC20
- 2011 F150 3.5L Charge Air Cooler
Importance: High

We've been pushing the pause button on this one (for one reason or another) since last winter. I am not inclined to push it out further as my agenda is booked until January.

Mike and Craig, please send me your sections by 2PM tomorrow. I will review and recommend changes so that you can make updates prior to the EPRC meeting.

Thank you.

Marie Wilson
Ford Motor Company
Vehicle Environmental Engineering
Homologation & Compliance
Phone: 313-248-2404 MWILSO18@FORD.COM

From: Kramer, Michael (M.T.)
Sent: Tuesday, November 27, 2012 10:43 AM
To: Wilson, Marie (M.)
Cc: Smith, Craig (C.A.); McClenaghan, Dean (D.C.); Oswald, Greg (G.G.);

Kramer, Michael (M.T.)

Subject: RE: Emission Problem Review Committee Fact Sheet Request - 11EPRC20
- 2011 F150 3.5L Charge Air Cooler

I got a call today from Dean expressing a want/need to have a pre-review prior to this Thursday's EPRC. Apparently, this desire was included in some previous emails, however, I did not pick up on it nor have I seen any related meeting notices (I only have the Thur. EPRC on my calendar).

Bottom line is I can just make it for Thursday. I left a voicemail for Craig to check his status, however, anticipate he is in similar situation as myself.

Is there an opportunity to reschedule the EPRC for this item to enable Dean to schedule a pre-review?

Mike Kramer

RWD PT Cooling Supv.

Six Sigma Black Belt

Cell Phone: (313) 805-0190

Text Page: mkramer1

Page from outside Ford

<https://text.vzw.com/customer_site/jsp/messaging_lo.jsp> , External email:
mkramer1@ford.com

From: Wilson, Marie (M.)

Sent: Tuesday, November 27, 2012 8:49 AM

To: Smith, Craig (C.A.)

Cc: Kramer, Michael (M.T.)

Subject: FW: Emission Problem Review Committee Fact Sheet Request - 11EPRC20
- 2011 F150 3.5L Charge Air Cooler

Craig, per your voicemail, see the link at the bottom of this chain for a blank fact sheet. Please collaborate with Mike Kramer to complete.
Thanks.

Marie Wilson

Ford Motor Company

Vehicle Environmental Engineering

Homologation & Compliance

Phone: 313-248-2404 MWILSO18@FORD.COM

From: Kramer, Michael (M.T.)

Sent: Wednesday, November 14, 2012 4:49 PM

To: Wilson, Marie (M.)

Subject: FW: Emission Problem Review Committee Fact Sheet Request - 11EPRC20
- 2011 F150 3.5L Charge Air Cooler

Can this item be covered between 10 and 11 on 11/29? I have a hard rock conflict at 11:00.

Mike Kramer
RWD PT Cooling Supv.
Six Sigma Black Belt
Cell Phone: (313) 805-0190
Text Page: mkramer1
Page from outside Ford
<https://text.vzw.com/customer_site/jsp/messaging_lo.jsp> , External email:
mkramer1@ford.com

From: Kramer, Michael (M.T.)
Sent: Wednesday, November 14, 2012 4:45 PM
To: Wilson, Marie (M.)
Cc: McClenaghan, Dave (D.); Oswald, Greg (G.G.); Fuher, Michael (M.J.); Sparks, Douglas (D.S.); Cockerill, Al (C.A.); Dixon, Mark (M.R.); Madej, Jeanette (J.); Harrison, Michael (M.J.); Smith, Craig (C.A.); Dixon, Mark (M.R.); Ronzi, Bill (W.C.); Russo, Scott (S.); Kramer, Michael (M.T.)
Subject: RE: Emission Problem Review Committee Fact Sheet Request - 11EPRC20 - 2011 F150 3.5L Charge Air Cooler

PT Cooling will have section 1 complete to support the 11/29 meeting. Will need the Calibration team (Craig Smith?) to handle section 2.

We can consolidate section 2 from the Calibration team into our document if needed.

Mike Kramer
RWD PT Cooling Supv.
Six Sigma Black Belt
Cell Phone: (313) 805-0190
Text Page: mkramer1
Page from outside Ford
<https://text.vzw.com/customer_site/jsp/messaging_lo.jsp> , External email:
mkramer1@ford.com

From: Wilson, Marie (M.)
Sent: Wednesday, November 14, 2012 4:18 PM
To: Sparks, Douglas (D.S.); Cockerill, Al (C.A.); Dixon, Mark (M.R.); Kramer, Michael (M.T.); Madej, Jeanette (J.); Harrison, Michael (M.J.); Smith, Craig (C.A.); Dixon, Mark (M.R.); Ronzi, Bill (W.C.); Russo, Scott (S.)
Cc: McClenaghan, Dave (D.); Oswald, Greg (G.G.); Fuher, Michael (M.J.)
Subject: RE: Emission Problem Review Committee Fact Sheet Request - 11EPRC20 - 2011 F150 3.5L Charge Air Cooler

I have added this item to the 11-29 EPRC agenda and sent the meeting notice to Mike Kramer. Thanks.

Marie Wilson
Ford Motor Company
Vehicle Environmental Engineering
Homologation & Compliance
Phone: 313-248-2404 MWILSO18@FORD.COM

From: Wilson, Marie (M.)
Sent: Monday, November 12, 2012 3:51 PM
To: Sparks, Douglas (D.S.); Cockerill, Al (C.A.); Dixon, Mark (M.R.); Kramer, Michael (M.T.); Madej, Jeanette (J.); Harrison, Michael (M.J.); Smith, Craig (C.A.); Dixon, Mark (M.R.); Ronzi, Bill (W.C.)
Cc: McClenaghan, Dave (D.); Oswald, Greg (G.G.)
Subject: RE: Emission Problem Review Committee Fact Sheet Request - 11EPRC20 - 2011 F150 3.5L Charge Air Cooler

Mike K. will you have an PERC fact sheet for meeting review on 11-15?
Please advise.

<< Message: CAC follow up >>

Marie Wilson
Ford Motor Company
Vehicle Environmental Engineering
Homologation & Compliance
Phone: 313-248-2404 MWILSO18@FORD.COM

From: Sparks, Douglas (D.S.)
Sent: Monday, October 29, 2012 1:39 PM
To: Wilson, Marie (M.); Cockerill, Al (C.A.); Dixon, Mark (M.R.); Kramer, Michael (M.T.); Madej, Jeanette (J.); Harrison, Michael (M.J.); Smith, Craig (C.A.); Dixon, Mark (M.R.); Ronzi, Bill (W.C.)
Subject: RE: Emission Problem Review Committee Fact Sheet Request - 11EPRC20 - 2011 F150 3.5L Charge Air Cooler

Marie,
The CAC D&R is Mike Kramer. However, after quickly reviewing the Fact Sheet it appears the Calibration Team will need to help complete this document.

Mazen/Craig,
Please work with Mike Kramer and help populate the EPRC fact Sheet.

Mark/Bill,

Please ensure Mike has the correct warranty data for this document.

Thank you,

Douglas S. Sparks
P/T Quality and PVT Manager FNA
P/T Integration and Program Management (PTIM)
dsparks3@ford.com 313-805-6096

Administrative Assistant: Tina Tessadri
ttessadr 313 594-1115

From: Wilson, Marie (M.)
Sent: Monday, October 29, 2012 12:53 PM
To: Cockerill, Al (C.A.); Sparks, Douglas (D.S.); Dixon, Mark (M.R.)
Subject: RE: Emission Problem Review Committee Fact Sheet Request - 11EPRC20
- 2011 F150 3.5L Charge Air Cooler

Who owns D&R for the CAC?

Marie Wilson
Ford Motor Company
Vehicle Environmental Engineering
Homologation & Compliance
Phone: 313-248-2404 MWILSO18@FORD.COM

From: Cockerill, Al (C.A.)
Sent: Monday, October 29, 2012 11:57 AM
To: Sparks, Douglas (D.S.); Dixon, Mark (M.R.)
Cc: Wilson, Marie (M.)
Subject: FW: Emission Problem Review Committee Fact Sheet Request - 11EPRC20
- 2011 F150 3.5L Charge Air Cooler

Doug, Mark,
Attached is the form that Marie is referring to. I do not feel that I am
the correct person to be completing this. How do suggest we handle this?
<< File: FAF03-170-1.doc >>

The spirit, the will to win, and the will to excel are the things
that endure. These qualities are so much more important than the events that
occur. The harder you work, the harder it is to surrender.

Vince Lombardi
Al Cockerill
RWD V6 Engine System Supervisor
313-805-2333 C
313-845-0475 O

From: Wilson, Marie (M.)
Sent: Monday, October 15, 2012 1:58 PM
To: Cockerill, Al (C.A.); Smith, Craig (C.A.)
Cc: Mazuchowski, James (J.A.); Oberski, Christopher (C.); Oswalt, Greg (G.G.); McClenaghan, Dave (D.)
Subject: Emission Problem Review Committee Fact Sheet Request - 11EPRC20 - 2011 F150 3.5L Charge Air Cooler

Al, per our discussions (and attached e-mail), please prepare an EPRC fact sheet for the subject concern.

<< Message: RE: Charge Air Cooler - 2011 P415 >> << Message: RE: P415 3.5L Catalyst replacement 2011MY, 2012MY >>

Please prepare an Environmental Problem Review Committee (EPRC) Fact sheet for Some 2011 F150 rucks with 3.5L GTDI engines may experience misfire conditions due to condensation build up in the charge air cooler, per the instructions below.

. Obtain EPRC fact sheet at
<https://www.tc2.ford.com/ts/VEE/certification/default.aspx>
<<https://www.tc2.ford.com/ts/VEE/certification/default.aspx%20%20>> (the fact sheet link is listed under "Reporting Compliance Sites" low on the left side of the page)

. Fill out both pages of the fact sheet as completely as possible.
(NOTE: Please use Vehicle Line names like "Fusion" rather than Vehicle line codes like "CD338" in all sections referring to vehicles affected.)

. 11EPRC20 has been assigned to this item. Place this number in the Form Header.

. To facilitate an efficient review of the topic in EPRC, the CCM group will set up a fact sheet review meeting by the Friday before your scheduled EPRC presentation. Please plan to support this meeting. It will improve the quality of the EPRC meeting review and reduce your follow up requirements.

. Please send the completed fact sheet draft to me by close of business on the Monday prior to your scheduled EPRC meeting. (No paper copies are necessary for the meeting.)

. Please plan to present this item in the 11-15-12 EPRC meeting at 10:00 AM. Presentations should be made by LL6 or above employees with support from any employees required. Presentations should also be made in person (not via call in.) Please provide CDS id's for the appropriate meeting notice.

EPRC Background:

The Environmental Problem Review Committee is chaired by Vehicle Environmental Engineering. It has members from The Automotive Safety Office, Critical Concern Review Group (CCRG), Critical Concern Manager (CCM), The Ford Customer Service Division (FCSD) - Recall Group, The Office of the General Council (OGC)' Global Product Development and Vehicle Operations - GRC Manager. Its mission is to review all Production Vehicle/Engine Environmental Compliance related issues to determine the correct course of action for the company. Support from the organizations and individuals who have firsthand knowledge of environmental compliance related issues is critical to the committee's success.

Thanks in advance for your cooperation and support. Please feel free to contact me with any questions.

Marie Wilson
Ford Motor Company
Vehicle Environmental Engineering
Homologation & Compliance
Phone: 313-248-2404 MWILSO18@FORD.COM

From: Whitehead, Joseph (J.P.)
Sent: Wednesday, April 18, 2012 1:53 PM
To: Smith, Craig (C.A.); Devries, Jason (J.E.); Yamada, Shuya Shark (S.Y.); Strylo, Tom (T.M.); Lisi, Paul (P.)
Subject: FW: Variable CAC

From: Palm, Jim (J.R.)
Sent: Wednesday, April 18, 2012 10:06 AM
To: Ladd, John (J.R.); Madej, Jeanette (J.); Tyler, Jim (J.S.); Norman, Kristofor (K.R.); Whitehead, Joseph (J.P.); Cockerill, Al (C.A.)
Cc: Germek, Rick (R.J.); Bishop, Chris (C.B.)
Subject: Variable CAC

This is the boost actuated hot side variable CAC which Rick Germek and I have been working on as a possible PCA action. We plan on evaluating it for misfire this Friday in the WT. During low boost levels as encountered at cruise conditions it blocks air flow and condensation in the top 12 tubes of the CAC and greatly increases flow velocities in the lower 9 tubes thereby stripping water droplets out of the tubes. During WOT operation high boost levels fully open the flapper valve allowing flow through all 21 tubes thereby not hurting thermal efficiency..





From: Ricks, Kevin (K.J.)
Sent: Tuesday, March 12, 2013 7:42 PM
To: Dobbs, Dan (K.D.); Nowaczyk, Rick (R.J.)
Subject: FW: 13MY CAC Replacement

Let's discuss in the am.

From: Ronzi, Bill (W.C.)
Sent: Tuesday, March 12, 2013 6:30 PM
To: Dobbs, Dan (K.D.); Nowaczyk, Rick (R.J.)
Cc: Ricks, Kevin (K.J.); Sparks, Douglas (D.S.); Andersen, Erik (E.)
Subject: 13MY CAC Replacement

Rick/Dan,

We need the SSM out... Good example below.

Can you call the dealer on this one to discuss the repair? It appears the vehicle had a P0430 catalyst code but instead of replacing the LH catalyst they replaced the CAC, per the TSB, even though it was built outside the TSB dates (already had new CAC). That means the customer will likely be back very soon with another P0430 and got \$300 worth of new CAC parts that won't help.

DEL	VIN	VEHICLE #	ENGINE	TRANS	ASSY PLAN	PROD DATE	WARRANTY START DATE	DEALERSHIP	PART NUMBER			
2013	1FTFW1ETXDK	#	T/F6	F/B/A/E	T/KW	T/C3	AJ	26-Oct-12	17-Dec-12	D-PATRICK, INC.	172# F0L3	6K775

Bill

William C. on
PTI Quality Supervisor
(313) 805-6140 cell & pgr

From: Ladd, John (J.R.)
Sent: Monday, June 04, 2012 10:10 AM
To: Kramer, Michael (M.T.)
Cc: Madej, Jeanette (J.)
Subject: FW: 13MY P415 DEMS MISFIRE: FW: CT-Alert: DFA00029 (3.5L ECO / P415 / ATX) triggered P0300 @ 2012-06-01 21:19:02 GMT

If the TASE test proves adequate cooling performance, need to prioritize getting half the DEMs fleet updated. That is if VO lets us put parts on the trucks...

Regards,
John Ladd
Supervisor - Cooling Development Engineering
Ph: (313) 62-16626 Cell: (313) 805-4627
Fax: (313) 317-9241

From: Smith, Craig (C.A.)
Sent: Monday, June 04, 2012 10:02 AM
To: Tatro, James (J.E.)
Cc: Hammoud, Mazen (M.); Madej, Jeanette (J.); Devries, Jason (J.E.); Whitehead, Joseph (J.P.); Ladd, John (J.R.); Kramer, Michael (M.T.); Yamada, Shuya Shark (S.Y.); Cockerill, Al (C.A.); Gernant, Tim (T.R.); Liebert, Mike (M.D.); VanHouten, Andrew (A.S.); Norman, Kristofor (K.R.); Cowher, Terry (T.); Dixon, Mark (M.R.)
Subject: 13MY P415 DEMS MISFIRE: FW: CT-Alert: DFA00029 (3.5L ECO / P415 / ATX) triggered P0300 @ 2012-06-01 21:19:02 GMT

James,

I reviewed the VDR data from Friday evening's misfire event on DFA00029 (13MY P415 GTDI DEMS vehicle). The event was a high load misfire on bank 2 where cylinders 4,5, and 6 were involved. Given the rainy, highly- humid conditions, I believe this event to be the classic condensate-induced misfire. Please disposition this issue accordingly.

My understanding is that the CAC 6-tube blocker plate was installed on all 13MY P415 GTDI DEMS units. Can you please confirm that this vehicle had the plate in place.


Thanks,
Craig Smith
Supervisor - Engine Calibration
3.5L TIVCT GTDI & 3.5L IVCT GTDI Powerpacks
Phone: (313) 805-6345
TEE Bldg cube 1AD08

From: notifications@control-tec.com [mailto:notifications@control-tec.com]
Sent: Friday, June 01, 2012 7:13 PM
Subject: CT-Alert: DFA00029 (3.5L ECO / P415 / ATX) triggered P0300 @ 2012-06-01 21:19:02 GMT

CONTROLTEC

QUALIFIER


Issue [P0300 - Random Misfire Detected](#) (Status: Open)

Vehicle 1F1T1CT5D1A000 (3.5L ECO / P415 / ATX)
DTC Details Module: E8 Type: Pending
Module HW/SW DL3A-1B684-AA DL3A-14C04-CB
Trigger Time 2011-06-01 11:10:00 GMT
PCM Calibration GCT1GA.03
Logger S/W 1.1.186
Data Files 
Assignee one

Location: Jackson, MI



Occurrence History



Comment History

No Comments

Notification Info

Name Notification -- Fault type: DTC Mail type: Hard Mail Subsystem: All --
 (automatically migrated) (created on 2011-08-18 10:01:04.0) [Manage Notifications](#)

From: Kelly, Jim (J.)
Sent: Thursday, October 04, 2012 2:14 PM
To: Nowaczyk, Rick (R.J.)
Subject: FW: 20088667-Request Saved

Pick:

I have another one that I closed the TA on. That truck is also sitting at the dealer he wouldn't pick it up needs CAC. Should I reopen the TA and escalate that one too

Jim Kelly

Field Service Engineer - Philadelphia Region

Ford Motor Company

jkelly@ford.com

phone: 203-488-3401 toll-free fax: 866-355-5008

From: tfosys@ford.com [mailto:tfosys@ford.com]
Sent: Thursday, October 04, 2012 1:59 PM
To: Nowaczyk, Rick (R.J.); Kelly, Jim (J.)
Subject: 20088667-Request Saved

This is an auto generated e-mail from Technical Field Operations Assignment Management System, Please do not reply.

Please click [here](#) to access this request

Additional Comments

Request Details

Additions and/or changes made to the request are highlighted in red.

Tracking Number	20088667
Status	Assigned
Currently assigned to	RNOWACZY
Request Type	Escalated FSE Support Request (from FSE to CSE)
Request Source	Field Service Engineer

If Other request source, please explain

Primary contact	[REDACTED]
Primary contact's phone number	[REDACTED]
Primary contact's email address	[REDACTED]
Technician Name	
Technician certified in relevant speciality	
Dealership Name	GEO. M. YOCUM, INC.
P&A Code	01300
Facing Region (SDR separate from Contact Regions)	N3 - PHILADELPHIA
Geographic Region (SDR combined with Contact Region)	N3 - PHILADELPHIA
FCSD Sales Zone	A02
FCSD Technical Zone	T02
VIN	1FTFX1ET7CF [REDACTED]
Vehicle year/model	
Vehicle mileage	9,134
Repair Order (R.O) #	N/A
Customer Name	
Vehicle Down?	Yes
GCQIS Report #	CHGBC001
TAR Open?	Yes
CuDL Case #	
Priority	High
Request description	5 57 2 34,DRVLIN,HESITATES/STUMBLE,ACCELERATION,HOT AFTER TSB/P0304 P0305 This vehicle exhibits symptoms, evidence and DTCs consistent with water in charge air cooler(CAC). Customer has left vehicle at dealer and will not take it. Customer has open CUDL and is threatening legal action and buy back (RAV). I am requesting further engineering or customer handling information indicating the direction we should take at a local level given the circumstances. ---Updated By--- JKELLY22--09/13/2012 03:04:14 PM-- Please assign to Rick Nowaczyk (RNOWACZY) ---Updated By---BCAINES--09/13/2012 03:47:38 PM--
GCQIS Comments	08/07/2012 08:09AM PHIL JACOBS MSS - FCSD - TECH SVC HOTLINE; WEB FORM DATA - CONCERN:AFTER LONG HIGHWAY CRUISE,THEN ATTEMPTING TO PASS THE TRUCK WILL BOG OUT THEN BUCK, STUMBLE THEN RECOVER AND ACCELLERATE NORMALLY. DIAGNOSTICS: ROAD TESTED OVER 20 MILES FELT

NOTHING. PERFORMED SELF TEST , RECIEVED P0304,P0305 .
CHECK OASIS,
FOUND AND PERFORMED TSB 12-06-04. TRUCK WAS THEN DRIVEN
OVER 75 MILES
BEFORE GIVEN BACK. CUSTOMER CALLED 3 DAYS LATER SAYS
TRUCK STILL HAS
SAME PROBLEM.

PARTS REPLACED:NONE

TECH QUESTION:IS ANYTHING
ELSE KNOWN ABOUT THIS PROBLEM? CUSTOMERS COMPLAINT
MATCHES TSB PRETTY
CLOSELY. BUT APPARENTLY DID NOT FIX IT.

08/07/2012 08:09AM PHIL JACOBS MSS - FCSD - TECH SVC HOTLINE;

[REDACTED],
DUE TO THE EFFICIENCY OF THE CHARGE AIR COOLER, THERE
MAY BE
SOME CONDITIONS WHERE SOME CONDENSATION BUILDS IN THE
CAC, EVEN WITH
THE CAC SHIELD IN PLACE. VERY WET OR EXTREMELY HUMID
CONDITIONS MAY
ENHANCE THIS CONCERN. THE SHIELD WAS DESIGNED TO HELP
WITH LESS
CONDENSATION BUILD UP, BUT DUE TO HUMID AIR BEING
COMPRESSED BY THE
TURBOCHARGERS AND THEN COOLED BY THE CAC, THIS WILL
NOT TOTALLY
ELIMINATE THE CONDENSATION FROM FORMING UNDER THESE
CONDITIONS. WHEN
THE HUMID/COMPRESSED AIR IS COOLED BY THE CAC, IT
CAUSES THE WATER
GRAINS TO SEPARATE FROM THE AIR AND COLLECT ON THE CAC
FINS. AT THIS
TIME, IF WATER HAS BEEN VERIFIED IN THE CAC, AIS AND
AROUND THE
THROTTLE PLATE, CLEAN THE WATER AS BEST AS POSSIBLE AND

INFORM THE
CUSTOMER OF THE DESIGN OF THE SYSTEM AND THE POSSIBLY
OF CONDENSATION
BUILD-UP UNDER THESE CONDITIONS.

IF ABLE TO DUPLICATE THE CONCERN
WITH CONTINUED ROAD TESTS AND/OR THE P0304/P0305 DTC'S
HAVE RETURNED,
RECOMMEND TO SWAP THE #4 AND #5 IGNITION COILS AND
SPARK PLUGS WITH
KNOWN GOOD CYLINDERS, THEN RETEST(RELEASE THE VEHICLE
TO THE CUSTOMER
FOR TESTING PURPOSES IF THE CONCERN CANNOT BE
DUPLICATED).

IF THE
DTC'S DO NOT FOLLOW THE SWAP, REPLACE THE #4 AND #5 FUEL
INJECTORS.

09/12/2012 09:43AM STEPHEN MASSEY MSS - FCSD - TECH SVC
HOTLINE;
WEB FORM DATA -
CONCERN:TRUCK WILL LOSS POWER WHEN YOU ATTEMPT TO
ACCEL ON HIGHWAY AFTER DRING .

DIAGNOSTICS: PERFROM TSB 12-6-4
INSTALL DEFLECTOR PLATE AND CLEAN OUT COOLER. THEN
CAME BACK IN WE
CAME IN AND DRAIN COOLER .INFORMED CUSTOMER OF ISSUE
WITH PROBLEM AND
THAT FORD IS TRYING TO FIND A FIX.

PARTS REPLACED:CL3Z-19E672A
W711281S300

TECH QUESTION:TRUCK IS BACK IN WITH SAME ISSUE AND
CUSTOMER WANT FORD TO BUY TRUCK BACK.THERE IS A
MESSAGE ON PARTS

&SERVICE DISCUSSION BOARD FROM WEBMASTER FROM
GLOBAL ENGINE
ENGINEERING TEAM.THAT ENGINEERING IS AWARE AND
WORKING ON THE ISSUE.
THERE IS NO FIELD SERVICE PROCEDURE AVAILABLE AT THIS
TIME.ANY
ATTEMPTS TO MODIFY THE CHARGE AIR COOLER OR AIR INTAKE
COMPONENTS WILL
CREATE OTHER DRIVABILITY CONCERNS.CONTINUE TO MONITOR
OASIS FOR FURTHER
UPDATES.CUSTOMER DOES NOT WANT HIS TRUCK BACK TILL WE
FIX THE
ISSUE.WHAT DO I DO.

09/12/2012 09:43AM STEPHEN MASSEY MSS - FCSD - TECH SVC
HOTLINE;
DAVID,
WE HAVE ESCALATED THIS CONCERN FOR ADDITIONAL
REVIEW. A
REPRESENTATIVE SHOULD CONTACT YOU BY PHONE OR
THROUGH THIS HOTLINE
ASSISTANCE REQUEST WITHIN ONE (1) BUSINESS DAY WITH
ADDITIONAL
INFORMATION OR RECOMMENDATIONS TO ASSIST IN THE
RESOLUTION OF THIS
VEHICLE CONCERN.

09/12/2012 09:43AM STEPHEN MASSEY MSS - FCSD - TECH SVC
HOTLINE;
CONSULTED WILLIE HOUSTON
NOTE TO EH TEAM MEMBER: THIS CONCERN IS
BEING ESCALATED DUE TO MULTIPLE INCIDENTS OF THE SAME
CONCERN. THE
CUSTOMER REFUSING TO TAKE VEHICLE UNTIL THE CONCERN
HAS BEEN FIXED.
THERE IS AN OPEN CUDL WHICH MENTIONS THE CUSTOMER IS
CONSIDERING
HIRING AN ATTORNEY.

09/12/2012 11:58AM DALE BARRETT MSS - FCSD - TECH SVC
HOTLINE;
AN OUT BOUND CALL WAS PLACED TO THE DEALER; SPOKE TO
SERVICE MANAGER
DAVE LESSOR. THE VEHICLE WILL SET MISFIRE FAULTS P0304,
P0305 AND
P0306 DURING ACCELERATION AFTER A LONG FREEWAY CRUISE.
THE CUSTOMER
REFUSED TO ACCEPT THE VEHICLE BACK UNTIL REPAIRED.

09/12/2012 11:58AM DALE BARRETT MSS - FCSD - TECH SVC
HOTLINE;
DAVE,
TECHNICAL ASSISTANCE HAS BEEN REQUESTED BY THE
HOTLINE FOR THIS
VEHICLE. THE FSE IN YOUR AREA SHOULD CONTACT THE
DEALER MANAGEMENT
(SERVICE MANAGER OR SERVICE DIRECTOR) WITHIN 1 BUSINESS
DAY TO DISCUSS
AND ASSIST IN THE RESOLUTION OF THIS VEHICLE CONCERN.

09/12/2012 11:58AM DALE BARRETT MSS - FCSD - TECH SVC
HOTLINE;
NOTE TO FSE: TECHNICAL ASSISTANCE HAS BEEN REQUESTED
BY THE HOTLINE
FOR THIS VEHICLE DUE TO LACK OF PROGRESS IN REPAIRING AN
ENGINE
MISFIRE CONCERN. THE VEHICLE WILL SET MISFIRE FAULTS
P0304, P0305 AND
P0306 DURING ACCELERATION AFTER A LONG FREEWAY CRUISE.
THE CUSTOMER
REFUSED TO ACCEPT THE VEHICLE BACK UNTIL REPAIRED. THE
VEHICLE HAS AN
OPEN CUDL, CUSTOMER IS PREPARED TO SEEK BUY BACK.
PLEASE ASSIST THE
TECHNICIAN IN RESOLVING THE VEHICLE CONCERN.
ESTIMATED NUMBER OF

REPAIR ATTEMPTS: 3

ESTIMATED NUMBER OF DAYS OUT OF SERVICE: 4

09/13/2012 07:18AM JIM KELLY (FSE) MSS - FCSD - REG - PHILADELPH;
CONTACTED DEALER VIA E-MAIL 12:13 PM 9/12/2012. CALLED DEALER AT 4:55PM AND SM WAS GONE FOR THE DAY. WILL FOLLOW UP TODAY. THIS IS A KNOWN CONCERN (CAC OVER EFFICIENT - CONDENSES WATER AFTER LONG CRUISE)WITH A SERVICE FIX SCHEDULED FOR MID OCTOBER 2012 ACCORDING TO AEQ TRACKER.

09/13/2012 2:56PM JIM KELLY (FSE) MSS - FCSD - REG - PHILADELPH;
REMOVED CAC TUBE HOSES AT BOTH ENDS AND FOUND WATER AT BOTTOM AND WATER STAINS AT TOP. KNOWN CONCERN, ENGINEERING EXPECTS NEW DESIGN CAC AVAILABILITY FOR SERVICE 10/5/2012.

09/17/2012 2:54PM JIM KELLY (FSE) MSS - FCSD - REG - PHILADELPH;
ESCALATED ASSISTANCE REQUEST TO PCE RNOWACZY 9/13/2012. RESPONSE VIA PHONE THIS DATE 2:20 PM STATES THERE ARE NO NEW DESIGN CHARGE AIR COOLERS (CAC) AVAILABLE FOR SERVICE AT THE PRESENT TIME. THEY HOPE TO HAVE A BETTER IDEA OF AVAILABILITY DATE BY MID-OCTOBER.

09/20/2012 06:45AM JIM KELLY (FSE) MSS - FCSD - REG - PHILADELPH;
ALERTED MY MANAGEMENT, PSOM AND ZM TO THE SITUATION VIA PHONE AND E-MAIL 9/18/2012 9:04 AM.

FSE Comments

Initial Contact Date

Person Contacted

Dealership visit planned?

Visit date, if planned

Did Visit Occur?

Concern Summary for Technical Assistance Contact Report

Inspection Comments for Technical Assistance Contact Report

Primary Root cause for Technical Assistance Contact Report

Other Root Causes

Please explain if "Other" is root cause

FSE requesting new design CAC for this vehicle. Timing plan for New CAC to be available for service is mid to late October. ---Updated By--- RNOWACZY--09/13/2012 04:42:21 PM-- FSE to make sure that the dealer has an Emergency order in the parts system under part# BL3Z- 6K775-B. Working with PS&L to have a CAC drop shipped from the packager to the dealer for this vehicle. Also make sure dealer swaps over the defector to the new CAC with two new push pins. ---Updated By---RNOWACZY--10/04/2012 01:58:41 PM--

Recommendation for Technical Assistance Contact Report

Missing tools/equipment(if identified)

Missing tools/equipment ordered during visit?

Total hours spent on request

0.0

Created by

JKELLY22

Created date

09/13/2012 03:04:15 PM EST

Last Revised by

RNOWACZY

Last revised date

10/04/2012 01:58:42 PM EST

This e-mail notification has been generated by: RNOWACZY

Thank you..

From: Hamilton, Steven (S.C.)
Sent: Thursday, August 18, 2011 8:14 AM
To: Nowaczyk, Rick (R.J.)
Subject: FW: 2011 MY 3.5L GTDI P415 Misfire Daily AWS Claims (8/2/11)

FYI.....

Best regards,

Steve Hamilton

FCSD Service Engineering Operations
F-150 PVT Program Manager
(313)390-7750

From: Hamilton, Steven (S.C.)
Sent: Thursday, August 18, 2011 8:14 AM
To: Hamilton, Steven (S.C.); Cockerill, Al (C.A.); Reno, George (G.L.); Mazuchowski, James (J.A.)
Cc: Sims, Ivan (I.D.); Dixon, Mark (M.R.); Sparks, Douglas (D.S.); Donahue, Francis (Fran.); McCoy, Jim (D.); Oyafuso, Kevin (K.G.); Ricks, Kevin (K.J.); Lehmkuhl, David (D.B.); Galas, Dean (C.K.); Gorgol, Kevin (K.)
Subject: RE: 2011 MY 3.5L GTDI P415 Misfire Daily AWS Claims (8/2/11)

FYI....QSF has been opened this morning. It will show up in AEQ tomorrow.

Best regards,

Steve Hamilton

FCSD Service Engineering Operations
F-150 PVT Program Manager
(313)390-7750

From: Hamilton, Steven (S.C.)
Sent: Tuesday, August 09, 2011 12:20 PM
To: Cockerill, Al (C.A.); Reno, George (G.L.); Mazuchowski, James (J.A.)
Cc: Sims, Ivan (I.D.); Dixon, Mark (M.R.); Sparks, Douglas (D.S.); Donahue, Francis (Fran.); McCoy, Jim (D.); Oyafuso, Kevin (K.G.); Ricks, Kevin (K.J.); Lehmkuhl, David (D.B.); Galas, Dean (C.K.); Gorgol, Kevin (K.)
Subject: FW: 2011 MY 3.5L GTDI P415 Misfire Daily AWS Claims (8/2/11)

Team,

FCSD needs to open a QSF on F-150 3.5L misfire due to report count. The QSF will open on Aug 17 so that the team is given plenty of notice. Your continued cooperation with this issue and root cause identification is much appreciated.

Best regards,

Steve Hamilton

FCSD Service Engineering Operations
F-150 PVT Program Manager
(313)390-7750

From: Gorgol, Kevin (K.)
Sent: Tuesday, August 09, 2011 12:13 PM
To: McDonagh, Scot (S.M.); Ricks, Kevin (K.J.); Hamilton, Steven (S.C.)
Subject: RE: 2011 MY 3.5L GTDI P415 Misfire Daily AWS Claims (8/2/11)

QSF to open Aug 17th.

Kevin Gorgol
Field Service Engineer
Philadelphia Region
703-595-7263

From: McDonagh, Scot (S.M.)
Sent: Tuesday, August 09, 2011 11:54 AM
To: Cockerill, Al (C.A.); Reno, George (G.L.); Mazuchowski, James (J.A.)
Cc: Steslicki, Michael (M.E.); Dixon, Mark (M.R.); Sparks, Douglas (D.S.); Sims, Ivan (I.D.); Donahue, Francis (Fran.); McCoy, Jim (D.); Oyafuso, Kevin (K.G.)
Subject: RE: 2011 MY 3.5L GTDI P415 Misfire Daily AWS Claims (8/2/11)
Importance: High

FCSD has the Emerging Concern at RED status due to undetermined root cause. (2) more CQIS reports and FCSD will open the QSF. When the QSF is opened we have 68 days to release a Service fix(TSB) and 90 Days to close the QSF for Production.

Quality Team: F-150 Status: Emerging Open Date: 22/Jun/2011 VIN Count: 36 Threshold: 38 % of Threshold: 95% Function: Powertrain Days Open: 48 PCE: << OLE Object: Picture (Metafile) >> Last Updated: 4/Aug/2011 12:54:24 PM

F-150	2011-2011	06920110034-3.5L MISFIRE ON ACCEL w/o DTCs	PO CCOCKER W I - GRENO - SHAMILT3	CC:3.5L Misfire occurring without DTCs setting. MIL flashing with Catalyst Damage occurring resulting in lack of power on loaded acceleration. CA:TBD. SC:TBD. PC:TBD. ST:Aug/3: Report count increasing, no root cause identified. FAV and parts analysis on going are. Red due to help needed by engineering as QSF threshold is pending with no root cause. Service Red Due to: Other Production Red Due to:Other	Jun/22/2011	44	3	38	36	95%	TBD RED	TBD RED
-------	-----------	--	-----------------------------------	--	-------------	----	---	----	----	-----	---------	---------

PE13-018 000325

Scot G. McDonagh
PT Quality Engineering
Phone: (313)337-8091
smcdonag@ford.com

From: Cockerill, Al (C.A.)
Sent: Tuesday, August 09, 2011 11:42 AM
To: Hamilton, Steven (S.C.); McDonagh, Scot (S.M.); Reno, George (G.L.)
Cc: Steslicki, Michael (M.E.); Dixon, Mark (M.R.); Gorgol, Kevin (K.)
Subject: RE: 2011 MY 3.5L GTDI P415 Misfire Daily AWS Claims (8/2/11)

So what happens when it turns red?

The spirit, the will to win, and the will to excel are the things that endure. These qualities are so much more important than the events that occur. The harder you work, the harder it is to surrender.

Vince Lombardi

Al Cockerill
RWD V6 Engine System Supervisor
313-805-2333 C
313-845-0475 O

From: Hamilton, Steven (S.C.)
Sent: Tuesday, August 09, 2011 7:47 AM
To: Cockerill, Al (C.A.); McDonagh, Scot (S.M.); Reno, George (G.L.)
Cc: Steslicki, Michael (M.E.); Dixon, Mark (M.R.); Gorgol, Kevin (K.)
Subject: RE: 2011 MY 3.5L GTDI P415 Misfire Daily AWS Claims (8/2/11)

Al,

This is probably too late since the item is already RED but we are close to QSF threshold and still don't have a good understanding of root cause. We appreciate the team's support and will continue to support the team in root cause identification with CQIS reports, FAV's, etc.

Best regards,

Steve Hamilton

FCSD Service Engineering Operations
F-150 PVT Program Manager
(313)390-7750

From: Cockerill, Al (C.A.)
Sent: Tuesday, August 02, 2011 1:34 PM
To: McDonagh, Scot (S.M.); Reno, George (G.L.); Hamilton, Steven (S.C.)

PE13-018 000326

Cc: Steslicki, Michael (M.E.); Dixon, Mark (M.R.)
Subject: RE: 2011 MY 3.5L GTDI P415 Misfire Daily AWS Claims (8/2/11)

As you all know, there is a team fully dedicated to this multi-faceted issue. At this time work streams are in place but we can not define a resolution date with ICA's and PCA's in place. Steve, what can be done to keep this from going red?

The spirit, the will to win, and the will to excel are the things that endure. These qualities are so much more important than the events that occur. The harder you work, the harder it is to surrender.
 Vince Lombardi

Al Cockerill
 RWD V6 Engine System Supervisor
 313-805-2333 C
 313-845-0475 O

From: McDonagh, Scot (S.M.)
Sent: Tuesday, August 02, 2011 7:58 AM
To: Cockerill, Al (C.A.); Reno, George (G.L.)
Cc: Steslicki, Michael (M.E.); Dixon, Mark (M.R.)
Subject: RE: 2011 MY 3.5L GTDI P415 Misfire Daily AWS Claims (8/2/11)

Do we have an action plan to close the Emerging Concern at 84% QSF threshold ?

F-150	2011-2011	06920110034-3.5L MISFIRE ON ACCEL w/o DTCs	PO CCOCKER W I - GRENO - SHAMILT3	CC: 3.5L Misfire occurring without DTCs setting. MIL flashing with Catalyst Damage occurring resulting in lack of power on loaded acceleration. CA: TBD. SC: TBD. PC: TBD. ST: Jul/26: FAV roles resulting in dealer information obtained by engineering. Root cause Identification still occurring.	22/Jun/2011	40	3	38	32	84%	TBD GREEN	TBD GREEN
-------	-----------	--	-----------------------------------	---	-------------	----	---	----	----	-----	-----------	-----------

Scot G. McDonagh
 PT Quality Engineering
 Phone: (313)337-8091
smcdonag@ford.com

From: Steslicki, Michael (M.E.)
Sent: Tuesday, August 02, 2011 7:53 AM
To: Ahmed, Masood (M.); Bailey, Owen (O.R.); Boerger, Jim (J.G.); Boughan, Alex (A.B.); Cervenak, Neil (N.J.); Cockerill, Al (C.A.); Crudo, Frank (F.J.); Dame, Andrew (A.C.); Dixon, Mark (M.R.); Dodds, Jordan (J.); Donahue, Francis (Fran.); Early, Curt (C.G.); Fodera, Jas (J.J.); Galas, Dean (C.K.); Gorgol, Kevin (K.); Hamilton, Steven (S.C.); Heck, Kevin (K.C.); Holland, Del (D.); Holmes, Douglas (D.A.); Klomp, Karl (K.R.); Langley, Scott (C.S.); Mazuchowski, James (J.A.); McDonagh, Scot (S.M.); Merrell, Robert (R.J.); Miller, Brian (B.J.); Moore, Andrew (R.); Morrow, Bill (N.W.); Nevels, Laurence (L.); Osepchook, William (W.R.); Oyafuso, Kevin (K.G.); Parnell, Bill (W.); Reno, George (G.L.); Ronzi, Bill (W.C.); Ruppert, Dave (D.R.); Saad, Thomas (T.J.); Siddall, Stephen (S.); Sims, Ivan (I.D.); Skurko, Jennifer (J.J.); Smith, Craig (C.A.); Sparks, Douglas (D.S.); Stanley, Daniel (D.J.); Treusch, Christopher (C.J.); Wodzisz, Ken (K.R.); Zimlich, Mary (M.)
Subject: 2011 MY 3.5L GTDI P415 Misfire Daily AWS Claims (8/2/11)

PE13-018 000327

Six new claims today

(3) COP

(1) Spark Plug

(1) Diag - Misfire

(1) Catalytic Converter

<< File: 2011 MY 3.5L GTDI P415 Misfire Claims.xls >>

Mike Steslicki

Quality Analyst

Ford Motor Company

Large Gas & Diesel Engine Engineering

(313) 805-9888

From: Madej, Jeanette (J.)
Sent: Thursday, June 28, 2012 3:56 PM
To: Kramer, Michael (M.T.)
Subject: Fw: 2012 F-150 3.5L GTDI (Built After TSB Cutoff) Misfire P0304/P0306 CQIS Report#CF1CG014

From: McDonagh, Scot (S.M.)
Sent: Thursday, June 28, 2012 12:04 PM
To: Sparks, Douglas (D.S.); Mazuchowski, James (J.A.); Madej, Jeanette (J.)
Subject: FW: 2012 F-150 3.5L GTDI (Built After TSB Cutoff) Misfire P0304/P0306 CQIS Report#CF1CG014

INFO

[Scot G. McDonagh](#)
PT Quality Engineering
Phone: (313)337-8091
smcdonag@ford.com

From: Smith, Craig (C.A.)
Sent: Thursday, June 28, 2012 11:36 AM
To: Nowaczyk, Rick (R.J.); Oyafuso, Kevin (K.G.); McDonagh, Scot (S.M.); Dixon, Mark (M.R.); Ladd, John (J.R.); Devries, Jason (J.E.); Whitehead, Joseph (J.P.); Kramer, Michael (M.T.); VanHouten, Andrew (A.S.)
Cc: Dobbs, Dan (K.D.); Ricks, Kevin (K.J.); Hammoud, Mazen (M.)
Subject: RE: 2012 F-150 3.5L GTDI (Built After TSB Cutoff) Misfire P0304/P0306 CQIS Report#CF1CG014

[This appears to be the same condensate ingestion misfire problem even though the blocker plate was installed.](#)

Thanks,
Craig Smith
Supervisor - Engine Calibration
3.5L TIVCT GTDI & 3.5L IVCT GTDI Powerpacks
Phone: (313) 805-6345
TEE Bldg cube 1AD08

From: Nowaczyk, Rick (R.J.)
Sent: Thursday, June 28, 2012 11:23 AM
To: Oyafuso, Kevin (K.G.); Smith, Craig (C.A.); McDonagh, Scot (S.M.); Dixon, Mark (M.R.)
Cc: Dobbs, Dan (K.D.); Ricks, Kevin (K.J.); Nowaczyk, Rick (R.J.)
Subject: 2012 F-150 3.5L GTDI (Built After TSB Cutoff) Misfire P0304/P0306 CQIS Report#CF1CG014

Powertrain Engineering,

Tech Hotline received a call today on a 2012 F-150 3.5L GTDI built outside the production cutoff with intermittent misfire DTC P0304/P0306. There was evidence of water in the CAC and CAC tubes. No signs of water ingestion through the air filter box.

Suggestions?

From: Chatfield, David (D.)
Sent: Thursday, June 28, 2012 11:11 AM
To: Nowaczyk, Rick (R.J.)
Subject: water in CAC CQIS Report#CF1CG014

Rick,

As per our conversation, 2012 P415 low miles, water in CAC/ETB. Vehicle location is Tarpon Springs, Florida. This was the area that was affected by T.S. Debbie, high humidity and wet conditions for 7+ days.

Thanks,

David Chatfield

*Service Engineer - Gas Engine
3.0/3.5/3.7/GTDI Subject Matter Expert
Diagnostic Service Center I
1700 Fairlane Dr. Allen Park, MI 48101
DCHATFIE@FORD.COM
(313) 317-7056*

From: TROMANO7@ford.com [mailto:TROMANO7@ford.com]
Sent: Thursday, June 28, 2012 10:54 AM
To: Chatfield, David (D.)
Subject: water in CAC CQIS Report#CF1CG014

105529673

Attachments : 0

Report# :	CF1CG014 NHL	Received:	06/27/2012
CCRG/EPRC:		Date:	
Vehicle:	2012,F150 4X2 ,F150 ,SUP CRW,STYSD ,1FTVW1CT5CK [REDACTED]	Build Date:	06/04/2012
Odometer :	998 M	Calibration:	
Transmission:	6R80E	A/C:	YES
Dealer:	USA 04970 Karl Flammer Ford, Inc.	Phone#:	(727) 934-8675
City:	Tarpon Springs	State:	Florida
Originator:	ERIC BITTNER	Country :	USA
Symptom:	5 50 2 39 DRV PERF,RUNS ROUGH,ACCEL,INTERMITTENT		
Status:			
VFG:	V52 DRIVEABILITY		
Additional Symptom:	INTERMITTANT MISFIRES		
Fix:	Causal Component :		
Condition Code:			

Hotliner: SFRENC20

Phone: 313 248-8007

Regn Cd: S3 Orlando

Engineering:

Phone:

TAR:

Dlr Contact: ERIC BITTNER

Phone: 000 000-0000

Title Cde: T

DTCs:

KOEO:P0304 P0306

KOEC:

KOER:

Comments

:

REPAIR 06/27/2012 03:26PM SEAN FRENCH MSS - FCSD - TECH SVC HOTLINE
WEB FORM DATA - CONCERN: CUSTOMER STATES WHEN ACCELERATING TRUCK MISFIRES AND LACKS POWER. HAPPENED WHEN PULLING ONTO INTERSTATE. WAS GOING 60 AND ENGINE WAS AT 3000 RPM. DIAGNOSTICS: SELF TEST. PARTS REPLACED: NONE TECH QUESTION: CAN NOT DUPLICATE CONCERN. CUSTOMER SAID THIS HAS HAPPENED A FEW TIMES. TRUCK WAS IN A FEW DAYS AGO AND I PERFORMED A MISFIRE MONITOR CORRECTION AND DID A VISUAL INSPECTION. HAVE THERE BEEN ANY ISSUES WITH THIS. THE CODES WERE SET FROM LAST VISIT BUT DID NOT SET ANY CODES THIS TIME.

RECOMM 06/27/2012 03:26PM SEAN FRENCH MSS - FCSD - TECH SVC HOTLINE
ERIC, IF THE CONCERN IS DIFFICULT TO DUPLICATE, RECOMMEND SPEAKING WITH THE CUSTOMER REGARDING THE TIMING AND ANY UNIQUE CONDITIONS PRESENT FOR THE MISFIRES TO OCCUR. ONCE THE CONCERN HAS BEEN DUPLICATED, RECOMMEND SWAPPING SPARK PLUGS AND IGNITION COILS WITH KNOWN GOOD CYLINDERS AND MONITOR FOR CHANGE. IF THE MISFIRES FOLLOW THE SWAPPED COMPONENTS, RECOMMEND REPLACING THE SUSPECT COMPONENTS AT THIS TIME AND REEVALUATE THE CONCERN. IF COMPONENT SWAPPING DOES NOT INDICATE A FAULT, RECOMMEND MONITORING FUEL TRIMS AT IDLE BY MONITORING PIDS: LONG_FT AND SHRT_FT WITH THE IDS DATA LOGGER. IF MORE THAN 10% TOTAL FUEL CORRECTION IS PRESENT AT IDLE AND GRADUALLY IMPROVES AS RPMS INCREASE, THIS WOULD INDICATE THE PRESENCE OF VACUUM LEAKS. IF A VACUUM LEAK CONCERN IS PRESENT; RECOMMEND SMOKE TESTING THE INTAKE SYSTEM AND MONITOR FOR LEAKAGE AND MAKE REPAIRS AS NECESSARY. IF SMOKE TESTING DOES NOT INDICATE ANY FAULTS, RECOMMEND CAPPING OFF VACUUM SOURCES AND MONITOR FUEL TRIMS FOR CHANGE. IF FUEL TRIMS IMPROVE WITH VACUUM LINES CAPPED OFF, RECOMMEND RE INSTALLING VACUUM LINES ONE AT A TIME UNTIL THE ORIGIN OF THE LEAK IS IDENTIFIED

AND REPAIR AS NECESSARY. IF NO VACUUM LEAKS ARE PRESENT, RECOMMEND PERFORMING AN IDS FUEL INJECTOR FLOW TEST. IF AN INJECTOR FAILS THE TEST, RECOMMEND REPLACING THE SUSPECT INJECTOR AS PER THE INSTRUCTIONS LISTED IN THE WSM SECTION: 303-04A --> REMOVAL AND INSTALLATION --> FUEL RAIL. IF NO FUEL INJECTOR FAULTS ARE IDENTIFIED, RECOMMEND INSPECTING A FUEL SAMPLE FOR SIGNS OF POOR QUALITY. IF SIGNS OF DISCOLORATION OR DEBRIS/SEDIMENT ARE IDENTIFIED, RECOMMEND DRAINING AND STEAM CLEANING THE FUEL TANK (IF NECESSARY), CLEAR OUT THE FUEL RAILS/LINES WITH SHOP AIR AND REFUEL WITH A KNOWN GOOD FUEL SOURCE. IF FUEL QUALITY IS OK, MISFIRES CAN ALSO OCCUR DUE TO EXCESSIVE ETHANOL CONTENT DUE TO THIS VEHICLE NOT BEING FLEX FUEL CAPABLE. TO TEST FOR ETHANOL: FILL A CLEAR CONTAINER HALF WAY WITH FUEL AND HALF WAY WITH WATER AND ALLOW 5 MINUTES FOR THE ETHANOL TO SEPARATE INTO THE WATER CONTENT. THE OVERALL LEVEL INCREASE OF WATER INDICATES THE PERCENTAGE OF ETHANOL PRESENT WITHIN THE TANK. IF MORE THAN 10% ETHANOL IS PRESENT, DRAIN THE TANK AND REFUEL WITH A KNOWN GOOD FUEL SOURCE.

REPAIR 06/28/2012 09:47AM DALE BARRETT MSS - FCSD - TECH SVC HOTLINE

I REMOVED CAC HOSE AT THE THROTTLE BODY AND SAW SIGNIFICANT WATER STAINING ON THROTTLE BODY. REMOVED CAC HOSE FROM COOLER AND LOOKED IN HOSE AND IT APPEARS TO HAVE DRIED UP WATER RUNS THROUGH IT.

RECOMM 06/28/2012 09:47AM DALE BARRETT MSS - FCSD - TECH SVC HOTLINE

ERIC, A AIR DEFLECTOR HAS BEEN ADDED TO THE CAC TO PREVENT CONDENSATION IN THE CAC. WITH THE VEHICLE BUILD DATE OF 6-4-2012 RECOMMEND REFERRING TO TSB 12-6-4 (REFERENCE ONLY) FOR ILLUSTRATION OF PROPER CAC AIR DEFLECTOR PLATE INSTALLATION. INSPECT THE AIR FILTER HOUSING FOR WATER INTRUSION.

REPAIR 06/28/2012 10:52AM TONY ROMANO MSS - FCSD - TECH SVC HOTLINE

AIR DEFLECTOR WAS INSTALLED CORRECTLY. DONT SEE ANY DAMAGE TO CHARGE AIR COOLER. INSPECTED AIR FILTER AND WAS DRY.

RECOMM 06/28/2012 10:52AM TONY ROMANO MSS - FCSD - TECH SVC HOTLINE

ERIC, IF NOT YET PERFORMED INSPECT THE AIR INTAKE FROM THE FILTER CASE TO ENGINE TO ENSURE NO WATER WAS TAKEN IN THROUGH THE AIR FILTER CASE EVEN THOUGH THE FILTER WAS DRY. IF ANY WATER WAS PRESENT IN THE SYSTEM CLEAR AS MUCH AS POSSIBLE AND RETEST. IF THE CONCERN IS NOT PRESENT NOW, INSPECT THE SPARK PLUGS FOR ANY CONCERNS AND RELEASE THE VEHICLE. WITH THE HEAVY RAINS IN THE AREA AND THE HIGH EFFICIENCY OF THE INTERCOOLER THE CONDENSATION MAY HAVE BUILT UP EVEN WITH THE ADDED AIR DEFLECTOR. PLEASE HAVE THE CUSTOMER MONITOR THE VEHICLE FOR ANY MORE CONCERNS.

From: McDonagh, Scot (S.M.)
Sent: Wednesday, October 24, 2012 8:24 AM
To: Hughes, Scott (S.R.); Smith, Craig (C.A.); Whitehead, Joseph (J.P.)
Subject: FW: 2012 F-150 3.5L GTDI Repeat Misfire at Highway Speeds (VIN: 1FTFW1ET1CF[REDACTED])
Importance: High

INFO

Scot G. McDonagh
PT Quality Engineering
Phone: (313)337-8091
smcdonag@ford.com

From: Nowaczyk, Rick (R.J.)
Sent: Wednesday, October 24, 2012 7:55 AM
To: Oyafuso, Kevin (K.G.); Corning, Dan (D.C.)
Cc: Nowaczyk, Rick (R.J.); Dixon, Mark (M.R.); Sparks, Douglas (D.S.); McDonagh, Scot (S.M.)
Subject: FW: 2012 F-150 3.5L GTDI Repeat Misfire at Highway Speeds (VIN: 1FTFW1ET1CF[REDACTED])
Importance: High

Kevin,

FSE (Dan Corning) has a Escalated Field case for repeat misfire at highway speeds. The FSE had the dealer install the new CAC, which I believe resolved one of the symptoms for the misfire. However, it appears the customer may be experiencing the surge at light throttle 6th gear going up hills.

Dan, do you have any IDS recordings you can send Kevin?

From:
Sent: Wednesday, October 24, 2012 7:03 AM
To: Nowaczyk, Rick (R.J.)
Subject: 2012 F-150 VIN: 1FTFW1ET1CF[REDACTED] - FLoF

Rick,

This unit has an Escalated FSE Support TFOAM. It has continued problems with an intermittent random miss after the new CAC was installed. no DTCs. Any additional ideas you may have would be appreciated.

Thanks,
Dan Corning
Ford Motor Company
Field Service Engineer
(615) 579-1032

From: Corning, Dan (D.C.)
Sent: Wednesday, October 24, 2012 12:21 AM
To: Corning, Dan (D.C.)
Subject: Report Summary for the CQIS Report#CGTB5003

Attachments : 0

Report# : CGTB5003 NHL **Received:** 07/20/2012
CCRG/EPRC: **Reviewed Status:** **Date:**
Vehicle: 2012,F150 4X4 ,F150 ,SUP CRW,STYSD ,1FTFW1ET1CF [REDACTED] **Build Date:** 01/09/2012
Odometer : 11,736 M **Engine:** 3.5L-GTDI **Calibration:** CF613C0A
Transmission: 6R80E **Axle:** 3800F3.31C **A/C:** YES
Dealer: USA 06004 Ford Lincoln of Franklin **Phone#:** (615) 794-4585
City: Franklin **State:** Tennessee **Country :** USA
Originator: PHILLIP RITER
Symptom: 5 50 2 39 DRV PERF,RUNS ROUGH,ACCEL,INTERMITTENT
Status:
VFG: V52 DRIVEABILITY
Additional Symptom: RUNS ROUGH
Fix:Y **Causal Component :** THROTTLE BODY AND MOTOR ASY -- RPL
Condition Code:

Hotliner: BGRAHA43 **Phone:** 313 248-8050 **Regn Cd:** C3 Memphis
Engineering: **Phone:** **TAR:** 0-30
Dlr Contact: PHILLIP RITER **Phone:** 000 000-0000 **Title Cde:** OT

DTCs:
KOEO:
KOEC:
KOER:

Comments

:

REPAIR 07/20/2012 10:19AM BRIAN GRAHAM MSS - FCSD - TECH SVC HOTLINE
WEB FORM DATA - CONCERN:VEHICLE HAS A MISS AT HIGHWAY SPEEDS ON LIGHT
ACCEL GOING UP HILLS DIAGNOSTICS: #3 MISFIRE ON ROAD TEST-SWAP #3
COILS,MISFIRE CHANGED CYLINDERS.REPLACE #3 COIL AND ROAD
TESTED,INTERMINENT RANDOM MISFIRE BUT NOT AS EXTREME AS AN IGNITION
MISFIRE,MONITORED MODE 6 DATA-0 MISFIRES,REMOVED CAC TUBES AND
INSPECTED FOR WATER OR CONDENSATION-NONE PRESENT,PERFORMED TSB
12-06-04.CONCERN STILL PRESENT. PARTS REPLACED:#COIL COIL,PCM

REPROGRAM TECH QUESTION:ANY KNOWN CONCERNS

RECOMM 07/20/2012 10:19AM BRIAN GRAHAM MSS - FCSD - TECH SVC HOTLINE

PHILLIP, WITH THE MISFIRE BEING RANDOM, SUGGEST TO TAKE A FUEL SAMPLE AND CHECK FOR ANY CONTAMINATION IN THE FUEL. SUGGEST TO PERFORM A FUEL PRESSURE TEST WITH A MECHANICAL PRESSURE GAUGE AND VERIFY PROPER LOW SIDE FUEL PRESSURE. NORMAL LOW SIDE PRESSURE FOR THIS VEHICLE IS 62-73 PSI. COMPARE FRP_ACT WITH FRP_DSD DURING CONCERN. IF THE LOW SIDE PRESSURE IS LOW, A CONCERN WITH THE LOW SIDE PUMP IS SUSPECTED. IF THE CONCERN IS ON THE HIGH PRESSURE SIDE, THE HIGH PRESSURE PUMP IS SUSPECTED. VERIFY THE MISFIRE PROFILE HAS RE-LEARNED. THE MLP_LRND PID SHOULD INDICATE IT HAS. IF NOT CHECK THE IDS FOR THE RELEARN AUTOMATED PROCEDURE PER SSM 21703. NO REPORTS ARE IN OUR DATA BASE FOR THIS CONCERN.

REPAIR 07/24/2012 10:52AM DAVID CHATFIELD MSS - FCSD - TECH SVC HOTLINE

CHECKED FUEL QUALITY-OK,CHECKED ETHANOL CONTENT-10%,MPLRND-YES,LOW PRESSURE FUEL READING-55 TO 70 IDLE WITH RAPID FLUCTUATION,64 PSI AT 1500RPM,HIGH PRESSURE 214,FRP DSD 207.WHATS NEXT?COULD WE STILL HAVE CALIBRATION ISSUES FOR ENGINEERING TO INVESTIGATE?MISFIRE TEST DETECTS NO MISFIRES AT THIS TIME

RECOMM 07/24/2012 10:52AM DAVID CHATFIELD MSS - FCSD - TECH SVC HOTLINE

PHILLIP, IF THE INTERPRETED MISFIRE OCCURS IN A HIGH TRANSMISSION GEAR (6TH) UNDER A HEAVY LOAD WITH A DOWNSHIFT, THIS CONDITION MAY WELL BE A NORMAL CHARACTERISTIC. AT THIS TIME, PLEASE USE THE IDS AND COMMAND THE TORQUE CONVERTER UNLOCKED DURING THE EVENT. IF THE CONCERN IS ALLEVIATED, THEN THE CONDITION IS MOST LIKELY NORMAL. IT WOULD BE RECOMMENDED TO COMPARE TO A LIKE VEHICLE WITH LIKE MILEAGE DURING THE CONDITION TO DETERMINE IF THE CONCERN IS A NORMAL OPERATING CHARACTERISTIC. IF THE CONCERN IS VERIFIED TO A LIKE VEHICLE TO BE ABNORMAL, IT IS RECOMMENDED TO MONITOR THE FOLLOWING PID`S APP(%), BARO(PRESS), CHT(TEMP), CYL_(1-6)_ACCL, EQ_RAT11 (RATIO), EQ_RATIO21 (RATIO), FRP (PRESS), FRP_DSD, GEAR, KNK_CNTR_CYL (1-6), KNK_RATE_LRND, LOAD, LONGFT1, LONGFT2, MAP(PRESS), NUM_MISFIRE, OCTADJ_R_LRND, O2S11_CUR, O2S21_CUR, RPM, RUNTM, SHRTFT1, SHRTFT2, TQ_CNTRL, TR, VPWR, VREF, VSS TO SEE IF A FAULT CAN BE VERIFIED. PLEASE FEEL FREE TO UPDATE THIS REPORT WITH THE UPDATED PID INFORMATION IF THE CONCERN CAN BE DUPLICATED.

REPAIR 07/25/2012 01:16PM SHAWN FERRET MSS - FCSD - TECH SVC HOTLINE

RUDY VICE CALLED AND STATED THE VEHICLE HAS A MISFIRE/BUCKING/JERKING THAT OCCURS UNDER MODERATE LOAD IN 6TH, 5TH, AND 3RD GEAR. SEVERAL

RECORDINGS WERE TAKEN OF THE CONCERN. FUEL TRIMS ARE OK. THE ISSUE OCCURS AROUND 1800 RPM. CYLINDER 5 WILL DROP UP TO 75% ON POWER BALANCE DURING THE CONCERN. THE ISSUE ONLY HAPPENS WITH THE TORQUE CONVERTER LOCKED. FRP ALWAYS MATCHES FRP_DSD.

RECOMM 07/25/2012 01:16PM SHAWN FERRET MSS - FCSD - TECH SVC HOTLINE

RUDY, RECOMMEND TO SWAP CYLINDER 5 COIL AND PLUG TO KNOWN GOOD CYLINDERS ON BANK 1 AND SEE IF THE MISFIRE CHANGES ON POWER BALANCE. PERFORM A HIGH PRESSURE FUEL SYSTEM TEST USING THE IDS TO VALIDATE THE INJECTORS ARE WORKING PROPERLY. REVIEW THE RECORDINGS AND MONITOR TCC_SLIP_ACT AND TCC_SLIP_DSD, ALONG WITH RPM COMPARED TO TSS TO SEE IF THE TORQUE CONVERTER IS MOMENTARILY SLIPPING DURING THE ISSUE. MONITOR THE WASTEGATE AND BYPASS VALVE PIDS TO DETERMINE IF THE BUCKING IS CONSISTENT WITH A CHANGE IN STATE.

REPAIR 08/09/2012 04:40PM ROBERT ABERCROMBIE MSS - FCSD - TECH SVC HOTLINE

RUDY MADE RECORDINGS OF THIS CONCERN AND NOTED THE FUEL TRIMS ARE -9 TO 10%. HE PERFORMED A FUEL SYSTEM TEST AND MONITORED THE FRP AND DESIRED AS THEY WERE THE SAME AT CRUISE. HE NOTED AT STEADY ACCELERATION CYLINDER ONE OR TWO AT A TIME WOULD SHOW A CONCERN IN CYLINDER CONTRIBUTION. HE ALSO NOTED A FLUCTUATION IN THE WAST GATE SOLENOIDS.

RECOMM 08/09/2012 04:40PM ROBERT ABERCROMBIE MSS - FCSD - TECH SVC HOTLINE

RUDY, RECOMMEND TO MONITOR THE MAP AND YIP_PRS_BOOST PID. LOOK FOR A SPIKE OR DIP IN THIS PID. IF NOTED THIS CAN AFFECT THE WAST GATE SOLENOIDS AND CAUSE MISFIRES. REPLACE THE TIP SENSOR AND RE EVALUATE.

REPAIR 08/14/2012 09:55AM DAVID CHATFIELD MSS - FCSD - TECH SVC HOTLINE

RUDY CALLED TO DISCUSS THE SURGE CONCERN IN GREATER DETAIL. HE STATED THAT HE CONFIRMED A V-SHAPE DIP IN TIP ON THE ROAD TEST. HE INSTALLED A TIP SENSOR FORM A DONOR VEHICLE OFF OF THE LOT AND RE EVALUTE. HE STATED AT FIRST THE CONCERN WAS GONE, BUT AFTER MULTIPLE ROAD TEST THE CONCERN HAS RE APPEARED. AT THE TIME OF THE CONCERN, THE TIP WITH DROP, MAP WILL BE STEADY, WASTE GATE WILL FLUCTUATE BETWEEN 25-55%, LOAD IS BETWEEN 70-90. THE CONCERN HAPPENS DURING LIGHT TIP-IN LIGHT LOAD SLIGHT GRADE AT APPROXIMATELY 65 MPH IN 6TH GEAR.

RECOMM 08/14/2012 09:55AM DAVID CHATFIELD MSS - FCSD - TECH SVC HOTLINE

RUDY, AS PER OUR DISCUSSION, PLEASE NAVIGATE TO THE AIR MANAGEMENT SELECT OF DATALOGGER AND MONITOR ETC_ACT AND ETC_DSD. PLEASE ENSURE THAT DURING THE CONCERN THESE PID DO NOT VARY MORE THAN 3 DEGREES. IF THERE IS A DISCREPANCY IN THESE PIDS DURING THE CONCERN, INSTALL A KNOWN GOOD ETB AND RE EVALUTE. ADDITIONALLY, WE HAVE ESCALATED THIS CONCERN FOR ADDITIONAL REVIEW. A REPRESENTATIVE SHOULD CONTACT YOU BY

PHONE OR THROUGH THIS HOTLINE ASSISTANCE REQUEST WITHIN ONE (1) BUSINESS DAY WITH ADDITIONAL INFORMATION OR RECOMMENDATIONS TO ASSIST IN THE RESOLUTION OF THIS VEHICLE CONCERN.

ESCLHD 08/14/2012 09:55AM DAVID CHATFIELD MSS - FCSD - TECH SVC HOTLINE

NOTE TO EH TEAM: THIS VEHICLE IS BEING ESCALATED DUE TO LACK OF PROGRESS AND DOWN TIME IN EXCESS OF 27 DAYS. VEHICLE HAS HAD PREVIOUS REPAIR (TSB 12-6-4) IN JULY FOR A LIKE CONCERN.

REPAIR 08/15/2012 10:35AM WILLIE HOUSTON MSS - FCSD - TECH SVC HOTLINE

AN OBC WAS MADE TO THE DEALER TO DISCUSS THIS CONCERN WITH RUDY. HE WAS NOT AVAILABLE FOR THE TELEPHONE CALL. I SPOKE TO TRACY WHO STATED THAT THE VEHICLE HAS BEEN AT THE DEALER FOR 27 DAYS AND THIS IS THE SECOND REPAIR ATTEMPT.

RECOMM 08/15/2012 10:35AM WILLIE HOUSTON MSS - FCSD - TECH SVC HOTLINE

TRACY, DUE TO THE EXCESSIVE DOWNTIME, WE'VE REFERRED THIS CONCERN TO THE FIELD SERVICE ENGINEER (FSE) IN YOUR MARKET AREA. THE FSE SHOULD CONTACT YOU OR DEALERSHIP MANAGEMENT (SERVICE MANAGER OR SERVICE DIRECTOR) WITHIN ONE (1) BUSINESS DAY. IF THE FSE DOES NOT CONTACT YOU DIRECTLY, PLEASE CONSULT WITH DEALERSHIP MANAGEMENT TO DISCUSS FURTHER RECOMMENDATIONS AND STEPS TO ASSIST IN THE RESOLUTION OF THIS VEHICLE CONCERN.

TAR 08/15/2012 10:35AM WILLIE HOUSTON MSS - FCSD - TECH SVC HOTLINE

NOTE TO FSE: WE ARE REQUESTING TECHNICAL ASSISTANCE ON THIS VEHICLE DUE TO EXCESSIVE DOWNTIME. THE VEHICLE CAME TO THE DEALER FOR A SURGE AT CRUISE UNDER LIGHT TIP IN. THE TECHNICIAN HAS REPLACED A COIL PACK AND PERFORMED TSB 12-06-04 WITH NO CHANGE TO THE CONCERN. HE HAS NOTED A DOWNWARD SPIKE IN TIP-BOOST WHEN THE CONCERN OCCURS AND WAS INSTRUCTED TO MONITOR ETB_ACT AND ETB_DSD PIDS DURING THE CONCERN. UPON ESCALATION CONTACT HE WAS UNAVAILABLE FOR THE PHONE CALL. ESTIMATED NUMBER OF REPAIR ATTEMPTS: 2 ESTIMATED NUMBER OF DAYS OUT OF SERVICE: 27

ADD-ON 08/16/2012 11:00AM DAN CORNING(FSE) MSS - FCSD - REG - MEMPHIS

FSE WENT TO THE DEALERSHIP 8/15/12 AND TEST DROVE THE UNIT. VERIFIED CONCERN. SYMPTOM: DURING A WARM ENGINE CRUISE AT 60+ MPH IN 6TH GEAR WITH TORQUE CONVERTER LOCKED. ACCELERATE LIGHTLY TO LOAD DRIVELINE WITHOUT DOWNSHIFTING. INTERMITTENTLY, THE ENGINE WILL SURGE AND MISS.

ADD-ON 08/16/2012 11:06AM DAN CORNING(FSE) MSS - FCSD - REG - MEMPHIS

USED IDS TO MONITOR ECT-ACT VS ETC-DSD. THE TWO PIDS WERE NORMALLY WITHIN 3 DEGREES OF ONE ANOTHER BUT OBSERVED MOMENTARY WIDE VARIANCE WHILE ENGINE MISS OCCURRED. (30 DEGREE VARIATION) AT THE SAME TIME, TIP-PRS BECOMES RAGGED DURING ENGINE MISS.

ADD-ON 08/16/2012 11:22AM DAN CORNING(FSE) MSS - FCSD - REG - MEMPHIS
 TO DATE, THE DEALERSHIP HAS REPLACED THE THROTTLE BODY OFF A DONOR UNIT (THE ONE THEY PULLED FROM A DONOR UNIT WASN'T THE SAME P/N), TIP SENSOR, ALL SPARK PLUGS AND ALL COILS. RECOMMENDATION: I REQUESTED THE DEALERSHIP RESEARCH THE CORRECT THROTTLE BODY PART NUMBER IF THE ONE THEY INSTALLED WAS INCORRECT, INSTALL THE CORRECT ONE. ALSO, I ASKED THEM TO CHECK EXHAUST BACKPRESSURE ON BOTH BANKS DUE TO AN UNUSUAL "HISS" NOISE I HEARD ON LIGHT ACCEL.

REPAIR 08/16/2012 03:16PM ROBERT ABERCROMBIE MSS - FCSD - TECH SVC HOTLINE
 FSE: DAN CORNING CALLED IN TO DISCUSS THE CONCERN IN FURTHER DETAIL. HE HAS THE TECH PERFORMING AN EXHAUST BACK PRESSURE TEST. THE AC TSB WAS ALREADY PERFORMED AND DURING THE CONCERN THE AMBIENT TEMP WAS HOT AND DRY.

RECOMM 08/16/2012 03:16PM ROBERT ABERCROMBIE MSS - FCSD - TECH SVC HOTLINE
 IF THE CONCERN CAN BE DUPLICATED DURING A ROAD TEST ON A REGULAR BASIS, THEN IT IS MOST LIKELY NOT A CONDENSATION CONCERN. IT IS RECOMMENDED TO MONITOR THE FOLLOWING PID'S APP(%), BARO(PRESS), CHT(TEMP), CYL_(1-6)_ACCL, EQ_RAT11 (RATIO), EQ_RATIO21 (RATIO), FRP (PRESS), FRP_DSD, GEAR, KNK_CNTR_CYL (1-6), KNK_RATE_LRND, LOAD, LONGFT1, LONGFT2, MAP(PRESS), NUM_MISFIRE, OCTADJ_R_LRND, O2S11_CUR, O2S21_CUR, RPM, RUNTM, SHRTFT1, SHRTFT2, TIP_PRS-BOOST, TQ_CNTRL, TR, VPWR, VREF, VSS.

ADD-ON 08/28/2012 03:32PM DAN CORNING(FSE) MSS - FCSD - REG - MEMPHIS
 DEALERSHIP REPLACED TIP SENSOR AND THROTTLE BODY. EXTENSIVE TEST DRIVE VERIFIED CONCERN RESOLVED.

AUDIT 08/28/2012 03:32PM DAN CORNING(FSE) MSS - FCSD - REG - MEMPHIS
 TECH ASSIST REFERRAL HAS BEEN CLOSED

ADD-ON 10/05/2012 09:35AM JIM BROUSE(STI) MSS - FCSD - REG - MEMPHIS
 JIM BROUSE WENT TO THE DEALERSHIP 10.4.12 YESTERDAY AFTERNOON AND SAT WITH THE SERVICE MANAGER AND SUCCESSFULLY PUT IN AN EMERGENCY PARTS ORDER.
 THANKS

REPAIR 10/16/2012 06:11PM DAVID STENDARDO MSS - FCSD - TECH SVC HOTLINE
 TECH CALLING IN AFTER THE UPDATED CAC (FOBL3Z-6K775-B) WAS INSTALLED AND THE CONCERN OF RANDOM MISFIRING WAS STILL PRESENT UNDER MODERATE LOADS. WHEN MONITORING THE POWER BALANCE, IT WAS NOTED THAT THE TRUCK WILL MISFIRE ON #6, THEN #1, THEN #3. THERE ARE NO DTC'S SETTING AT THIS TIME. THE TECH INSPECTED THE THROTTLE PLATE AND THERE WERE NO SIGNS OF WATER PRESENT.

TAR 10/16/2012 06:11PM DAVID STENDARDO MSS - FCSD - TECH SVC HOTLINE

****NOTE TO FSE: I AM REQUESTING TECHNICAL ASSISTANCE ON THIS VEHICLE DUE TO A RECURRING MISFIRE/BUCK/JERK SENSATION AFTER THE UPDATED CAC WAS INSTALLED AND CUSTOMER SEEKING BUY BACK IN CUDL** PLEASE VERIFY ABOVE DIAGNOSTICS AND REPAIRS PERFORMED. TECH REPLACED THE CAC WITH FOBL3Z-6K775-B AS DIRECTED BY ENGINEERING AND THE CONCERN WAS SAID TO BE STILL PRESENT WITH NO DTC'S SETTING. THE CONCERN WAS SAID TO HAVE IMPROVED BY ABOUT 75%, BUT STILL THERE NONE THE LESS. THE SHOP FOREMAN IS CONCERNED WITH BUYBACK AS WELL THE CUSTOMER BEING IN CONTACT THE CRC. WHEN MONITORING POWER BALANCE, IT WAS SAID THAT THE MISFIRE WILL START ON #6, THEN #1, THEN #3. THE THROTTLE PLATE DOES NOT SHOW ANY MOISTURE STAINING. REVIEW THE CONCERN WITH THE TECHNICIAN AFTER THE MOST RECENT DIRECTED REPAIR WITH AN UPDATED PART AND PROVIDE AN APPROPRIATE DIRECTION BASED ON FINDINGS. REPAIR ATTEMPTS: 2 ESTIMATE OF TOTAL DAYS OUT OF SERVICE: 45(TECH DIESEL CERTIFIED)**

RECOMM 10/16/2012 06:11PM DAVID STENDARDO MSS - FCSD - TECH SVC HOTLINE
ADVISED TECH THAT THERE WERE PAST FSE INVOLVEMENT AND WITH THE MENTION OF BUY BACK IN CUDL, THE FSE WILL NEED TO BE INVOLVED AGAIN TO ASSIST WITH THIS CONCERN.

****WE'VE REFERRED THIS CONCERN TO THE FIELD SERVICE ENGINEER (FSE) IN YOUR MARKET AREA. THE FSE SHOULD CONTACT YOU OR DEALERSHIP MANAGEMENT (SERVICE MANAGER OR SERVICE DIRECTOR) WITHIN ONE (1) BUSINESS DAY. IF FSE DOES NOT CONTACT YOU DIRECTLY, PLEASE CONSULT WITH DEALERSHIP MANAGEMENT TO DISCUSS FURTHER RECOMMENDATIONS AND STEPS TO ASSIST IN THE RESOLUTION OF THIS VEHICLE CONCERN.****

AUDIT 10/16/2012 06:11PM DAVID STENDARDO MSS - FCSD - TECH SVC HOTLINE
TECH ASSIST REFERRAL HAS BEEN REOPENED

REPAIR 10/18/2012 11:51AM BRETT FENNING MSS - FCSD - TECH SVC HOTLINE
DAN(FSE) RECEIVED UPDATED CHARGE AIR COOLER AND WAS IDENTICAL TO ORIGINAL CHARGE AIR COOLER. VEHICLE WAS STILL MISFIRING WITH THE UPDATED CHARGE COOLER INSTALLED. WAS LOOKING TO CONTACT RICK NOAWACZYK
IN REGARDS TO THE CONCERN.

RECOMM 10/18/2012 11:51AM BRETT FENNING MSS - FCSD - TECH SVC HOTLINE
DAN, RICK NOWACZYK CAN BE REACHED AT (313)322-7251.

ADD-ON 10/19/2012 12:01PM DAN CORNING(FSE) MSS - FCSD - REG - MEMPHIS
WORKED WITH JIM BROUSE (STI) YESTERDAY TO TRY AND DIAG THE CONCERN. THE NEW CAC HAS BEEN INSTALLED WITH NO IMPROVEMENT. THE ENGINE HAS A RANDOM MISS ON ACCELERATION. SOMETIMES THE CONCERN DOES NOT HAPPEN AT ALL, SOMETIMES THE ENGINE MISS IS BAD ENOUGH THAT IT'S DIFFICULT TO

ACCELERATE THE VEHICLE. THE DEALERSHIP HAS ALREADY REPLACED ALL SPARK PLUGS AND COILS AND PERFORMED THE HIGH PRESSURE FUEL SYSTEM TEST MULTIPLE TIMES (PASSES EVERY TIME) AND HAS PERFORMED EVERY TEST (AND MORE) SEEN ABOVE. JIM BROUSE AND I TEST DROVE THE UNIT WHILE MONITORING DATALOGGER. AFTER A COUPLE HOURS OF DRIVING, THE CONCERN BEGAN TO HAPPEN FREQUENTLY. EVEN WHEN THE ENGINE BEGAN MISSING CONSTANTLY, THERE WAS NO DTC SET. OTHER THAN THE ENGINE GOING A BIT LEAN, NO ROOT CAUSE WAS VERIFIED. CALLED PVT RICK NOWACZYK TO REVIEW.

ADD-ON 10/19/2012 12:02PM DAN CORNING(FSE) MSS - FCSD - REG - MEMPHIS

AT THIS POINT, NO CLEAR DIAGNOSIS HAS BEEN IDENTIFIED.

From: Smith, Craig (C.A.)
Sent: Monday, January 07, 2013 10:51 AM
To: Ladd, John (J.R.); Whitehead, Joseph (J.P.); Leisenring, Kenneth (K.C.); Hughes, Scott (S.R.); VanHouten, Andrew (A.S.); Devries, Jason (J.E.); Cockerill, Al (C.A.)
Subject: FW: 2012 F150 3.5L - Poor Power Turbo noise
Attachments: Report Summary for the CQIS Report#CIQBO008 (7.87 KB); Report Summary for the CQIS Report#CLSCD008 (5.37 KB)

FCSD emerging issue: Getting CQIS calls about loss of power after CAC TSB performed. See two attached sample reports.

Thanks,
Craig Smith
Supervisor - Engine Calibration
3.5L TIVCT GTDI & 3.5L IVCT GTDI Powerpacks
Phone: (313) 805-6345
TEE Bldg cube 1AD08

-----Original Message-----

From: Davis, Craig (C.B.) [mailto:cdavis6@ford.com]
Sent: Monday, January 07, 2013 9:28 AM
To: McDonagh, Scot (S.M.); Merrell, Robert (R.J.)
Subject: RE: 2012 F150 3.5L - Poor Power Turbo noise

Gentlemen, new emerging issue, following TSB 12-10-19 (updated CAC) dealer reporting same issue (miss power loss etc.) see attached emails

I am having the FSE work with the dealer to gather more details on drive cycles, and filter status

From: McDonagh, Scot (S.M.)
Sent: Monday, December 10, 2012 10:51 AM
To: Merrell, Robert (R.J.); Davis, Craig (C.B.)
Subject: RE: 2012 F150 3.5L - Poor Power Turbo noise

Agreed- I was not expecting R/1000 on F-150 W/O 3.5L to be worse than 3.5L GTDI

Scot G. McDonagh
PT Quality Engineering
Phone: (313)337-8091
smcdonag@ford.com

From: Merrell, Robert (R.J.)
Sent: Monday, December 10, 2012 10:39 AM
To: Davis, Craig (C.B.); McDonagh, Scot (S.M.)
Subject: RE: 2012 F150 3.5L - Poor Power Turbo noise

Nothing really obvious, it's much lower than the gas engines.
But let's examine some parts.
<< File: F150_8A080.xlsx >>

From: Davis, Craig (C.B.)
Sent: Monday, December 10, 2012 8:47 AM
To: McDonagh, Scot (S.M.); Merrell, Robert (R.J.)
Subject: RE: 2012 F150 3.5L - Poor Power Turbo noise

I agree

My other concern - Is the potential for this to occur on any and all of our turbocharged engines? To allow dirt bypass once the filter becomes restricted (due to the higher AIS vacuum seen with turbos)?

Or is this related more to the Air Box design and we might see this on F150 3.7L and 5.0L as they use the exact air box as the 3.5L does

From: McDonagh, Scot (S.M.)
Sent: Monday, December 10, 2012 8:41 AM
To: Davis, Craig (C.B.); Merrell, Robert (R.J.)
Subject: RE: 2012 F150 3.5L - Poor Power Turbo noise

If we ever really apply "Lessons Learned" we will be unemployed :-)

Scot G. McDonagh
PT Quality Engineering
Phone: (313)337-8091
smcdonag@ford.com

From: Davis, Craig (C.B.)
Sent: Monday, December 10, 2012 8:39 AM
To: Merrell, Robert (R.J.)
Cc: McDonagh, Scot (S.M.)
Subject: RE: 2012 F150 3.5L - Poor Power Turbo noise

You been around as long as Scot has ..

From: Merrell, Robert (R.J.)
Sent: Monday, December 10, 2012 8:39 AM
To: Davis, Craig (C.B.)
Cc: McDonagh, Scot (S.M.)
Subject: RE: 2012 F150 3.5L - Poor Power Turbo noise

You guys are walking history books.

From: Davis, Craig (C.B.)
Sent: Monday, December 10, 2012 8:36 AM
To: McDonagh, Scot (S.M.); Merrell, Robert (R.J.); Mohan, Robert (R.); Ronzi, Bill (W.C.)
Cc: Dixon, Mark (M.R.); Tiernan, Chris (C.D.); Oyafuso, Kevin (K.G.)
Subject: RE: 2012 F150 3.5L - Poor Power Turbo noise

Robert, no I don't have any pieces as the air box was never requested (even though the dealer had it as the causal part)

All, Scot I agree with this possibility - the 7.3L had a revised air cleaner assembly developed see attached Ford of Canada released the attached bulletin advising the dealers of the changes made

<< File: Document.pdf.pdf >>

From: McDonagh, Scot (S.M.)
Sent: Monday, December 10, 2012 8:27 AM
To: Merrell, Robert (R.J.); Mohan, Robert (R.); Ronzi, Bill (W.C.)
Cc: Dixon, Mark (M.R.); Davis, Craig (C.B.); Tiernan, Chris (C.D.); Oyafuso, Kevin (K.G.)
Subject: RE: 2012 F150 3.5L - Poor Power Turbo noise

Thanks- Does P415 GTDI Airbox have a mechanism inside the Airbox to prevent the filter from buckling when plugged ? This scenario reminds me of 1998.5-2002MY P131 7.3L Diesel Turbo failures.

Scot G. McDonagh
PT Quality Engineering
Phone: (313)337-8091
smcdonag@ford.com

From: Merrell, Robert (R.J.)
Sent: Monday, December 10, 2012 8:16 AM
To: McDonagh, Scot (S.M.); Mohan, Robert (R.); Ronzi, Bill (W.C.)
Cc: Dixon, Mark (M.R.); Davis, Craig (C.B.); Tiernan, Chris (C.D.); Oyafuso, Kevin (K.G.)
Subject: RE: 2012 F150 3.5L - Poor Power Turbo noise

Request is in.

Craig have anything you can send me asap.

From: McDonagh, Scot (S.M.)
Sent: Friday, December 07, 2012 3:14 PM
To: Mohan, Robert (R.); Ronzi, Bill (W.C.); Merrell, Robert (R.J.)
Cc: Dixon, Mark (M.R.); Davis, Craig (C.B.); Tiernan, Chris (C.D.); Oyafuso, Kevin (K.G.)
Subject: FW: 2012 F150 3.5L - Poor Power Turbo noise

Should we kick off a WPAC request to have 8A080 AIS Assemblies returned for 12-13MY P415 GTDI ?

224756 <http://www.wpac.ford.com/wprc/tools/req_detail.asp?REQNUM=224756>
DTP1-01 9/13/2012 12/12/2012 9/13/2012 10:07:12 PM UPS
Overnight ACTIVE QUALITY REVIEW: LEVEL 5 DS TRUCK 2012
ALL BL3Z 8A080 B A 1/Year FORD MOTOR COMPANY
PVT DEPARTMENT GATE 6/GENERAL STORE 3001 MILLER RD,DEARBORN,
MI-48120 NON-QUARTERBACK

Scot G. McDonagh
PT Quality Engineering
Phone: (313)337-8091
smcdonag@ford.com

From: Davis, Craig (C.B.)
Sent: Thursday, December 06, 2012 1:36 PM
To: McDonagh, Scot (S.M.)
Subject: RE: 2012 F150 3.5L - Poor Power Turbo noise

Scot, dealer has sent in photos from another unit showing dirt bypassing the filter - no other issues aside from the Check Engine light on for MAF, but you can see the traces of dirt in the upper air box cover

These trucks are not sitting, 1FTFX1ET7CK [REDACTED] this was put into service January 10 2012 and has 71,000+km

Dealer has been asked to input GCR

<< File: DSCN0095.JPG.JPG >> << File: DSCN0092.JPG.JPG >> << File: DSCN0091.JPG.JPG >> << File: DSCN0090.JPG.JPG >> << File: DSCN0089.JPG.JPG >> << File: DSCN0088.JPG.JPG >> << File: DSCN0087.JPG.JPG >> << File: DSCN0086.JPG.JPG >> << File: DSCN0098.JPG.JPG >>

From: Davis, Craig (C.B.)
Sent: Thursday, November 29, 2012 11:57 AM
To: McDonagh, Scot (S.M.)
Subject: RE: 2012 F150 3.5L - Poor Power Turbo noise

Just checked the parts listing, the BL3Z 8A080 B is used on all 2011 and newer F150 3.7L/3.5L/5.0L, so I re-ran AWS no difference to the 3.5L count, showed 5 reports for 5.0L and nothing for the 3.7L

The 6.2L uses the BL3Z 8A080 A level part

So the question is, are the other part sales retail, due to the housing breaking during routine service for the air filter? Is there in fact an issue with the housing?

From: Davis, Craig (C.B.)
Sent: Thursday, November 29, 2012 9:12 AM
To: McDonagh, Scot (S.M.)
Subject: 2012 F150 3.5L - Poor Power Turbo noise

Scot, here is an interesting one

2012 F150 - 1FTFX1ET9CF [REDACTED]
In service = January 25 2012
Last repair = September 26 2012 at 56,643 km Customer complaint Poor Power and Turbos noisy
Dealer codes to the air box/coolant bottle (assembly) BL3Z 8A080 B for poor sealing causing the failure

Question
- have you been made aware of any issue relating to the air box/air box sealing?

I have ran AWS and only 2 repairs, both for coolant leak
AWS against 2010 - 2012 F150 with the 3.5L and causal part "8A080" and full part number "BL3Z 8A080 B"

Canadian Part Sales shows a different story

Calendar year	2011	SYTD
BL3Z 8A080 B	31	95

The photos of the turbos show the real story

<< File: Webb's Ford Turbo #1 .JPG >> << File: Webb's Ford Turbo # 2 .JPG >>
>> << File: Webb's Ford .JPG >>

<< File: Normal Turbo .JPG >>

Let me know your thoughts

This e-mail and any attachments is intended only for the use of the person or persons addressed hereto and may contain legally privileged and/or

confidential information. If you are not the intended recipient of this e-mail, you are hereby notified that any dissemination, distribution or copying of this e-mail, and any attachments, is strictly prohibited. If you have received this e-mail in error, please notify me via return e-mail and permanently delete the original and any copy of any e-mail and any printout.

Craig Davis (cdavis6@ford.com)
Technical Service Support
(905) 845-2511 ext 1488 Dial net 853-1488
Fax (905) 845 9447
Ford of Canada
Mail Drop C.H.Q.402 Room 420A

Accelerate Growth Through Customer Satisfaction and Loyalty

From: Pitre, Rejean (R.J.) <rpite4@ford.com>
Sent: Monday, January 07, 2013 9:13 AM
To: Davis, Craig (C.B.)
Cc: Pitre, Rejean (R.J.)
Subject: Report Summary for the CQIS Report#CLSCD008

hi craig, any insight on the ecoboost hesitation after the CAC has been replaced with the updated one i have this one and another from Avalon that i will send the file to you next. thanks in advance

Attachments : 0

Report# : CLSCD008 NHL Received: 12/19/2012
CCRG/EPRC: Reviewed Status: Date:
Vehicle: 2012,F150 4X4 ,F150 ,SUP CRW,STYSD ,1FTFW1ET6CK [REDACTED]
Build Date: 03/21/2012
Odometer : 8,441 K Engine: 3.5L-GTDI Calibration:
CF613COA
Transmission: 6R80E Axle: 3.73 LOCK A/C: YES
Dealer: CAN B3805 Downey Ford Sales Ltd Phone#: (506) 633-2200

City: Saint John Province New Brunswick Country : CAN

Originator: BURT KELLY
Symptom: 5 54 2 39 DRV PERF,LACK/LOSS PWR ,ACCEL,INTERMITTENT
Status:
VFG: V52 DRIVEABILITY
Additional Symptom: MISS ON BANK2
Fix: Causal Component :
Condition Code:

Hotliner: TROMANO7 Phone: 313 337-9132 Regn Cd: 03 03 FCSD
REGION-CANADA

Engineering: Phone: TAR: 0-30

Dlr Contact: BURT KELLY Phone: 506 654-0448 Title Cde: SF

DTCs:
KOEO:
KOEC:P0304 P0305 P0306
KOER:

Comments :
REPAIR 12/19/2012 01:29PM TONY ROMANO MSS - FCSD - TECH SVC HOTLINE
WEB FORM DATA - CONCERN: LOSS OF POWER ENGINE LIGHT ON ACCELL. ON
WET
DAYS DIAGNOSTICS: VERIFY CUST. CONCERN PERFROM EEC. TEST HAD CODES

P0304,P0305,P0306 CHECK ING. SYSTEM REPLACE # 4,5,6 PLUGS FOULED
FROM PREVIOUS MISSFIRES ROADTEST OK AT THIS TIME. TRUCK COME BACK HAD
MISSFIRE CODE P0304 TRY NEW COIL ROADTEST POWER BAQLANCE TEST TURCK
IN HAS MISSFIRE ON#4 AND #6 CYLINDERS. REMOVE CAC AND CHECK HAD WATER
IT AGAIN FOREMAN IS CONTACTING HOTLINE. PARTS REPLACED: REPLACE #
DONE, 4,5,6 PLUGS FOULED FROM PREVIOUS MISSFIRES TSB 12-10-19 HAS BEEN
ALSO A NEW INTERCOOLER AND A SECOND CONVERTER.ROAD TESTED TRUCK
YESTERDAY AND IT FELL ON ITS FACE .REMOVED INNERCOOLER AN FOUND WATE
RIN IT APROX 1/2 CUP AFTER ROAD TEST. TECH QUESTION: HAS THERE BEEN
ANY OTHER REPORTS OF WATER IN THE INNER COOLER AFTER THE INNNER
COOLER HAS BEEN REPLACED? AND IF SO WHAT NOW? CUSTOMER REFUSES TO TAKE
TRUCK BACK.

RECOMM 12/19/2012 01:29PM TONY ROMANO MSS - FCSD - TECH SVC HOTLINE
BURT, THE FORD TECHNICAL HOTLINE HAS REVIEWED YOUR REQUEST AND HAS
DETERMINED THAT IT IS NECESSARY TO DISCUSS THIS MATTER VERBALLY OVER
THE TELEPHONE. YOU WILL BE CONTACTED SHORTLY BY A FORD TECHNICAL
HOTLINE REPRESENTATIVE.

REPAIR 12/19/2012 02:23PM TONY ROMANO MSS - FCSD - TECH SVC HOTLINE
CAN CALLED THE DEALERSHIP TO DISCUSS THE CONCERN IN MORE DETAIL. THE CAC
WAS UPDATED AND THE VEHICLE IS ON ITS 3RD CATALYST. THE MISFIRING
BE DUPLICATED EASILY WHEN THE WEATHER IS WET OR DAMP OUT. THEY HAVE
HAS SUCCESS WITH OTHER VEHICLES WITH THE NEW CAC BUT THIS TRUCK IS
NOT RESOLVED.

RECOMM 12/19/2012 02:23PM TONY ROMANO MSS - FCSD - TECH SVC HOTLINE
BE SPOKE WITH BURT THE SHOP FOREMAN AND ADVISED HIM THE CONCERN WOULD
ESCALATED.

ESCLHD 12/19/2012 02:23PM TONY ROMANO MSS - FCSD - TECH SVC HOTLINE
RETURNED NOTE TO ESCALATION TEAM : ESCALATED DUE TO THE OPEN CUDL AND
COMPONENTS ALREADY REPLACED. PER INFORMATION THE VEHICLE HAS
TO THE DEALER 6-7 TIMES SINCE NEW JUST OVER 3 MONTHS. DISCUSSED THE

CONCERN WITH MR. RIDOLFI. THE VEHICLE IS IN THE PROCESS OF A
CANADIAN
RAV AND BURT REPORTS THE CUSTOMER IS IN ANOTHER VEHICLE AT THIS
TIME.
REPAIR 12/20/2012 03:46PM DAVID STENDARDO MSS - FCSD - TECH SVC HOTLINE

****REVIEWED BY THE ESCALATION TEAM**** CONTACTED DEALER THROUGH
OUTBOUND CALL AND SPOKE WITH SERVICING TECHNICIAN BURT KELLY. TECH

A
MENTIONED THAT THE TRUCK IS COMMERCIAL USE AND IS DRIVEN ABOUT 80KM
DAY IN THE HIGHWAY. THE CAC HAS BEEN REPLACED WITH THE UPDATED
VERSION
AS PER TSB 12-10-19 WITH NO CHANGE. THE CAC WAS LATER REMOVED AND IT
WAS SAID THAT THERE WAS ABOUT 1 CUP OF WATER REMOVED. THE PLUGS ON
THE
L/S AS WELL AS BOTH CATALYSTS HAVE BEEN REPLACED WITH NO CHANGE.

RECOMM 12/20/2012 03:46PM DAVID STENDARDO MSS - FCSD - TECH SVC HOTLINE

ADVISED TECH TO CLOSELY INSPECT THE AIR FILTER HOUSING FOR PROPER
SEALING AS WELL AS THE AIR FILTER FOR ANY SIGNS OF
SATURATION.

****WE'VE REFERRED THIS CONCERN TO THE FIELD SERVICE
ENGINEER (FSE) IN YOUR MARKET AREA. THE FSE SHOULD CONTACT YOU OR
DEALERSHIP MANAGEMENT (SERVICE MANAGER OR SERVICE DIRECTOR) WITHIN
ONE
(1) BUSINESS DAY. IF FSE DOES NOT CONTACT YOU DIRECTLY, PLEASE
CONSULT
WITH DEALERSHIP MANAGEMENT TO DISCUSS FURTHER RECOMMENDATIONS AND
STEPS TO ASSIST IN THE RESOLUTION OF THIS VEHICLE CONCERN.****

TAR 12/20/2012 03:46PM DAVID STENDARDO MSS - FCSD - TECH SVC HOTLINE

****NOTE TO FSE: I AM REQUESTING TECHNICAL ASSISTANCE ON THIS VEHICLE
DUE TO A RECURRING MISFIRE CONCERN DURING HUMID OPERATION AFTER
SEVERAL DIRECTED REPAIR ATTEMPTS.**** PLEASE VERIFY ABOVE DIAGNOSTICS
AND REPAIRS PERFORMED. VEHICLE BROUGHT TO THE DEALER FOR POWER LOSS
ON
ACCELERATION. DEALER VERIFIED THE CONCERN WITH MISFIRE DTC'S PRESENT
THE
FOR THE L/S. TSB 12-06-04 WAS PERFORMED AS OUTLINED AND RETURNED.
TO
TECH HAS ALSO REPLACED PLUGS AND ONE COIL IN THE AFFECTED BANK DUE

THE
WAS
WAS
OF
AND

FOULING. THE CUSTOMER BROUGHT THE VEHICLE BACK WITH THE MIL ON AND
DEALER THEN PERFORMED 12-06-04 AGAIN FOR A P0430 AND THE CATALYST
REPLACED. THE VEHICLE THEN RETURNED AGAIN WITH THE MIL ON AND A LOSS
OF POWER. THE TECH THEN PERFORMED TSB 12-10-19 AND THE UPDATED CAC
INSTALLED AND THE PCM REPROGRAMMED. THE CUSTOMER BROUGHT THE TRUCK
BACK AGAIN FOR THE SAME CONCERN AND THE TECH HAS FOUND ABOUT 1 CUP
WATER IN THE CAC WHEN DRAINED. REVIEW THE CONCERN WITH THE DEALER
AND VERIFY ALL FINDINGS OF CONDENSATION BUILD UP AFTER DIRECTED REPAIRS
HAVE BEEN PERFORMED. PROVIDE ANY ADDITIONAL INSPECTION OR TESTING AS
NEEDED AS WELL AS AN APPROPRIATE REPAIR DIRECTION BASED ON
FINDINGS. REPAIR ATTEMPTS: 3 ESTIMATE OF TOTAL DAYS OUT OF SERVICE:

5(TECH CERTIFIED)

CUDL CASE #503403182

From: Pitre, Rejean (R.J.) <rpitre4@ford.com>
Sent: Monday, January 07, 2013 9:14 AM
To: Davis, Craig (C.B.)
Cc: Pitre, Rejean (R.J.)
Subject: Report Summary for the CQIS Report#CIQBO008

here is the other case. they have not yet reproduced it. on this unit.

Attachments : 0

Report# : CIQBO008 NHL Received: 09/17/2012
CCRG/EPRC: Reviewed Status: Date:
Vehicle: 2012,F150 4X4 ,F150 ,SUP CRW,STYSD ,1FTFW1ET7CF [REDACTED]
Build Date: 01/26/2012
Odometer : 16,450 K Engine: 3.5L-GTDI Calibration:
CF613CON
Transmission: 6R80E Axle: 3.73 LOCK A/C: YES
Dealer: CAN B3303 Avalon Ford Sales 1996 Limited Phone#: (709)
754-7500
City: St Johns Province Newfoundland Country : CAN

Originator: SCOTT GAULTON
Symptom: 5 50 2 39 DRV PERF,RUNS ROUGH,ACCEL,INTERMITTENT
Status:
VFG: V52 DRIVEABILITY
Additional Symptom: HESITATION ON ACCEL
Fix: Causal Component :
Condition Code:

Hotliner: SMASSE16 Phone: 313 317-4491 Regn Cd: 03 03 FCSD
REGION-CANADA

Engineering: Phone: TAR: 0-30

Dlr Contact: SCOTT GAULTON Phone: 709 722-6600 Title Cde: SF

DTCs:
KOEO:
KOEC:
KOER:

Comments :
REPAIR 09/17/2012 10:43AM STEPHEN MASSEY MSS - FCSD - TECH SVC HOTLINE

WEB FORM DATA - CONCERN:HESITATES ,STUMBLES, LACK OF POWER ,MISS ON

ACCELERATION ON HIGHWAY. DIAGNOSTICS: VEHICLE OPPEARATING OK AT

THIS TIME NO CODES ,NO MIL LIGHT ON,THE ONLY MESSAGES FOUND ON OASIS

THAT FIT THE CUSTOMERS SYMPTOMS WERE FOR TSB 12-6-4 WHICH WAS COMPLETED AT ANOTHER DEALER JULY 13 2012, PARTS REPLACED:NOTHING

AT THIS TIME. TSB 12-6-4 ALREADY COMPLETED AT ANOTHER DEALER. TECH

QUESTION:THIS TSB 12-6-4 DOESNT SEEM TO BE FIXING THE VARIOUS PERFORMANCE ISSUES WITH THE 3.5 ECO BOOST F-150S ALOT THAT HAVE BEEN

WITH DONE HERE AND OTHER DEALERS AROUND US HAVE CUSTOMERS COMING BACK

SAME ISUES MISSFIRES HESITATING STUMBLE ,FALLING ON ITS FACE ON

HIGHWAY ACCELLERATION TO PASS WITH OR WITHOUT LOAD SAME WITH A FEW

THAT WERE BUILT AFTER 5/24/2012 THAT HAVE HAD THIS DONE FROM THE

FACTORY, ARE THERE ANY FIXES FOR THIS ISSUE IN THE WORKS,EXCESSIVE

MOISTURE BUILD UP IN CAC. CUSTOMERS ARE GETTING HARDER TO DEAL WITH

OVER THESE PERFORMANCE ISSUES AND TELL US UNSAFE WHEN TRYING TO PASS

ON HIGHWAY. ANY HELP MUCH APPRECIATED.

RECOMM 09/17/2012 10:43AM STEPHEN MASSEY MSS - FCSD - TECH SVC HOTLINE

SCOTT, PLEASE INSPECT THE CAC TUBING AND THROTTLE PLATE FOR SIGNS OF

WATER/ WATER SPOTS. IF WATER SPOTS ARE NOT FOUND, RECOMMEND TO CONTINUE WITH NORMAL DIAGNOSTICS. RECOMMEND TO MONITOR THE FOLLOWING

PIDS DURING THE CONCERN TO DETERMINE WHAT COMPONENT OR SYSTEM MAY BE

CAUSING THIS CONCERN: APP(%), BARO(PRESS), CHT(TEMP),

CYL_(1-6)_ACCL,

EQ_RAT11 (RATIO), EQ_RATIO21 (RATIO), FRP (PRESS), FRP_DSD, GEAR,

KNK_CNTR_CYL (1-6), KNK_RATE_LRND, LOAD, LONGFT1, LONGFT2,

MAP(PRESS),

NUM_MISFIRE, OCTADJ_R_LRND, O2S11_CUR, O2S21_CUR, RPM, RUNTM,

SHRTFT1,

SHRTFT2, TQ_CNTRL, TR, VPWR, VREF, VSS. IF THE MISFIRE CAN BE

ISOLATED

TO A PARTICULAR CYLINDER, RECOMMEND TO SWAP THE IGNITION COMPONENTS

FROM THE SUSPECT CYLINDER WITH A KNOWN GOOD CYLINDER. IF THE MISFIRE

FOLLOWS THE COMPONENT SWAP, REPLACE THE SUSPECT COMPONENTS AND RE-EVALUATE THE CONCERN. IF THE CONCERN CANNOT BE ISOLATED TO A

PARTICULAR CYLINDER, RECOMMEND TO PERFORM A HIGH PRESSURE FUEL SYSTEM TEST. IF THE TEST PASSES, PERFORM A MANUAL COMPRESSION TEST AND COMPARE YOUR RESULTS TO A SEVERAL CYLINDERS. IF COMPRESSION IS FOUND TO BE LOW, PLEASE PERFORM A CYLINDER LEAK DOWN TEST TO DETERMINE WHERE THE LOSS OF COMPRESSION IS OCCURRING. IF WATER/ WATER SPOTS ARE FOUND ON THE THROTTLE PLATE OR IN THE CAC TUBING, SUSPECT CONDENSATION IN THE CAC IS THE CAUSE. DUE TO THE EFFICIENCY OF THE CHARGE AIR COOLER, THERE MAY BE SOME CONDITIONS WHERE SOME CONDENSATION BUILDS IN THE CAC, EVEN WITH THE CAC SHIELD IN PLACE. VERY WET OR EXTREMELY HUMID CONDITIONS MAY ENHANCE THIS CONCERN. THE SHIELD WAS DESIGNED TO HELP WITH LESS CONDENSATION BUILD UP, BUT DUE TO HUMID AIR BEING COMPRESSED BY THE TURBOCHARGERS AND THEN COOLED BY THE CAC, THIS WILL NOT TOTALLY ELIMINATE THE CONDENSATION FROM FORMING UNDER THESE CONDITIONS. WHEN THE HUMID/COMPRESSED AIR IS COOLED BY THE CAC, IT CAUSES THE WATER GRAINS TO SEPARATE FROM THE AIR AND COLLECT ON THE CAC FINS. AT THIS TIME, IF WATER HAS BEEN VERIFIED IN THE CAC, AIS AND AROUND THE THROTTLE PLATE, CLEAN THE WATER AS BEST AS POSSIBLE AND INFORM THE CUSTOMER OF THE DESIGN OF THE SYSTEM AND THE POSSIBLY OF CONDENSATION BUILD-UP UNDER THESE CONDITIONS. ENGINEERING IS CURRENTLY INVESTIGATING THIS CONCERN, AND FIX INFORMATION IS BEING PREPARED. A RELEASE DATE FOR THE FIX INFORMATION HAS NOT YET BEEN DETERMINED.

REPAIR 12/05/2012 09:06AM PHIL JACOBS MSS - FCSD - TECH SVC HOTLINE
AS DESCRIPTION OF VEHICLE CONCERN: CUSTOMER COMPLAINS OF SAME CONCERN
TSB 12-10-19, RAN TEST AND NO CODES, UNABLE TO REPRODUCE CONCERN.
DIAGNOSTICS ALREADY COMPLETED: RAN OASIS, RAN TEST AND NO CODES.
PARTS REPLACED: NONE TECH'S QUESTION: ANY KNOWNS OTHER THAN TSB
12-10-19

RECOMM 12/05/2012 09:06AM PHIL JACOBS MSS - FCSD - TECH SVC HOTLINE
DWAYNE, RECOMMEND TO CONTINUE TO ATTEMPT TO DUPLICATE THE CONCERN(OR
INSTALL A VDR/VCM II) WHILE MONITORING THE FOLLOWING PID'S TO HELP
DETERMINE THE CAUSE OF THE CONCERN; APP(%), BARO(PRESS), CHT(TEMP),
CYL_(1-6)_ACCL, EQ_RAT11 (RATIO), EQ_RATIO21 (RATIO), FRP (PRESS),
FRP_DSD, GEAR, KNK_CNTR_CYL (1-6), KNK_RATE_LRND, LOAD, LONGFT1,
LONGFT2, MAP(PRESS), NUM_MISFIRE, OCTADJ_R_LRND, O2S11_CUR,
O2S21_CUR,
RPM, RUNTM, SHRTFT1, SHRTFT2, TQ_CNTRL, TR, VPWR, VREF, VSS. IF
THE MISFIRES CAN BE ISOLATED TO A SPECIFIC CYLINDER, SWAP THE
IGNITION
COILS AND THE SPARK PLUGS WITH KNOWN GOOD CYLINDERS AND RETEST.
REPLACE THE AFFECTED IGNITION COMPONENTS IF THE MISFIRE FOLLOWS THE
COMPONENT. IF THE CONCERN STILL PERSIST AFTER IGNITION COIL SWAP AND
FOR
COMPRESSION TESTS DO NOT INDICATE A CONCERN, REPLACE THE INJECTOR
THE MISFIRING CYLINDER(S). WE HAVE ESCALATED THIS CONCERN TO THE
TECHNICAL SERVICE HOTLINE'S ESCALATED HANDLING TEAM FOR ADDITIONAL
REVIEW. A SERVICE ENGINEER FROM THIS TEAM WILL CONTACT YOU BY PHONE
OR
THROUGH THIS HOTLINE ASSISTANCE REQUEST WITHIN ONE (1) BUSINESS DAY
TO
PROVIDE ADDITIONAL INFORMATION AND/OR RECOMMENDATIONS TO ASSIST IN
THE
RESOLUTION OF THE CUSTOMER'S CONCERN. OUR TEAM AT THE HOTLINE WILL
CONCERN
CONTINUE TO WORK WITH YOU AND YOUR DEALERSHIP TO HELP GET THE
RESOLVED AND BACK TO THE CUSTOMER IN A TIMELY MANNER. IF WE HAVE
EXHAUSTED ALL OF OUR RESOURCES AND ARE STILL UNABLE TO RESOLVE THE
CUSTOMER'S CONCERN THROUGH THESE ADDITIONAL STEPS WITH YOU, THE
HOTLINE WILL ALERT YOUR FIELD SERVICE ENGINEER BY OPENING A
TECHNICAL
ASSISTANCE REQUEST. PLEASE BE PREPARED TO DISCUSS ALL DIAGNOSTICS
PERFORMED AND TEST RESULTS WITH THE TECHNICAL SERVICE HOTLINE
SERVICE
ENGINEER IN MORE DETAIL. THANK YOU IN ADVANCE.

ESCLHD 12/05/2012 09:06AM PHIL JACOBS MSS - FCSD - TECH SVC HOTLINE
NOTE TO EH: THIS HAS BEEN ESCALATED DUE TO THE OPEN CUDL REQUESTING
BUY BACK. TSB 12-10-19 HAS BEEN FORMED AND THE CUSTOMER STATES THAT
THE SAME CONCERN IS STILL PRESENT. CONSULTED DALE BARRETT. CONTACT
ID 105940388.

ADD-ON 12/05/2012 09:07AM PHIL JACOBS MSS - FCSD - TECH SVC HOTLINE
FORWARD TO ESCALATION TEAM.

REPAIR 12/06/2012 09:31AM WILLIE HOUSTON MSS - FCSD - TECH SVC HOTLINE

AN OBC WAS MADE TO THE DEALER TO DISCUSS THIS CONCERN WITH DWAYNE
RUSSELL. HE WAS NOT AVAILABLE FOR THE PHONE CALL HOWEVER I SPOKE TO
SHAUN GILLIS. HE STATES THAT THE VEHICLE IS NOT AT THE DEALER. TSB
12-10-19 WAS PERFORMED ON 10/30 AND THE CUSTOMER REPORTS THAT THE
CONCERN IS STILL PRESENT. HE HAS DRIVEN AT HIGHWAY SPEEDS OF
APPROXIMATELY 80-100 KPH FOR APPROXIMATELY 50 KM AND WHEN ATTEMPTING
TO PASS THE MIL STARTS TO FLASH AND THE VEHICLE LOOSES POWER. THIS
OCCURS MOST COMMONLY IN EXTREMELY WET CONDITIONS. THE CUSTOMER LIVES
ON THE COAST OF THE ATLANTIC OCEAN.

RECOMM 12/06/2012 09:31AM WILLIE HOUSTON MSS - FCSD - TECH SVC HOTLINE

DWAYNE, DUE TO THE CUDL COMMENTS AND REPEAT REPAIR, WE'VE REFERRED
THIS CONCERN TO THE FIELD SERVICE ENGINEER (FSE) IN YOUR MARKET
AREA.
THE FSE SHOULD CONTACT YOU OR DEALERSHIP MANAGEMENT (SERVICE MANAGER
OR SERVICE DIRECTOR) WITHIN ONE (3) BUSINESS DAYS. IF THE FSE DOES
NOT CONTACT YOU DIRECTLY, PLEASE CONSULT WITH DEALERSHIP MANAGEMENT TO
DISCUSS FURTHER RECOMMENDATIONS AND STEPS TO ASSIST IN THE
RESOLUTION
OF THIS VEHICLE CONCERN.

ESCLHD 12/06/2012 09:31AM WILLIE HOUSTON MSS - FCSD - TECH SVC HOTLINE

TAR TO BE OPENED ON 12/10/12
TAR 12/10/2012 08:57AM WILLIE HOUSTON MSS - FCSD - TECH SVC HOTLINE

NOTE TO FSE: WE ARE REQUESTING TECHNICAL ASSISTANCE ON THIS VEHICLE
DUE TO REPEAT REPAIR AND CUSTOMER REQUESTING BUY BACK. THE VEHICLE

CAME TO THE DEALER BECAUSE OF A LOSS OF POWER AND FLASHING MIL LIGHT.

THE CONCERN IS CONSISTENT WITH THE CONDITION DESCRIBED IN TSB
12-10-19

HOWEVER THE TSB HAS BEEN PERFORMED AND THE CONCERN IS STILL PRESENT.

THE VEHICLE IS NOT AT THE DEALER. ESTIMATED NUMBER OF REPAIR ATTEMPTS:

4 ESTIMATED NUMBER OF DAYS OUT OF SERVICE: 5

ADD-ON 12/10/2012 10:32PM REJEAN PITRE(FSE) MSS - FOC - CAN FIELD OPERAT

CALLLED DEALER THIS MORNING LEFT A MESSAGE WITH SERVICE MANAGER TO

CALL FSE AT 506-543-5850

From: Kramer, Michael (M.T.)
Sent: Tuesday, May 14, 2013 9:12 AM
To: Andersen, Erik (E.)
Subject: FW: A couple open Valeo items

Forgot to cc you

Mike Kramer
RWD PT Cooling Supv.
Six Sigma Black Belt
Cell Phone: (313) 805-0190
Text Page: mkramer1
[Page from outside Ford](mailto:mkramer1@ford.com), External email: mkramer1@ford.com

From: Kramer, Michael (M.T.)
Sent: Tuesday, May 14, 2013 9:12 AM
To: Corey SMALL <corey.small@valeo.com> (corey.small@valeo.com); Satish NADELLA; Kramer, Michael (M.T.); ying.tang@valeo.com; Guillermo GUADARRAMA; Blas-Fernando GUTIERREZ; Tyler, Jim (J.S.); Huang, Larry (L.); Joseph LUMETTA; Larry ENGEL
Cc: Alcaraz andrade, Alejandro (M.); Tyler, Jim (J.S.); Kramer, Michael (M.T.)
Subject: A couple open Valeo items

A) On track for 5/16 or sooner for the following data sheets with original J1 CAC internals (these are the ones that were first run with the wrong CAC internals):

- 1) Externally block bottom 7 tubes / 8 fins
- 2) Externally block bottom 4 tubes / 5 fins
- 3) Externally block bottom 7 tubes / 8 fins 25% of the length across the CAC from the inlet side and the bottom 3 tubes / 4 fins the remainder of the length ("L" laying on its side).

B) Status of P415 CAC corrosion testing with 7 tube / 8 fin lower blocker.

Mike Kramer
RWD PT Cooling Supv.
Six Sigma Black Belt
Cell Phone: (313) 805-0190
Text Page: mkramer1
[Page from outside Ford](mailto:mkramer1@ford.com), External email: mkramer1@ford.com

From: McDonagh, Scot (S.M.)
Sent: Thursday, October 18, 2012 11:55 AM
To: Fodera, Jas (J.J.)
Cc: Dixon, Mark (M.R.); Oyafuso, Kevin (K.G.); Nowaczyk, Rick (R.J.); Dobbs, Dan (K.D.)
Subject: FW: Customer Feedback on New CAC's Installed

Importance: High

Will the (2) Convertors replaced on enclosed P415 GTDI be routed back to you for analysis ?

1FTFX1ET8CK [REDACTED] - FSE Chris Hall



Report Summary for the 00000 Re...
Report Summary for the 00000 Re...

Scot G. McDonagh
PT Quality Engineering
Phone: (313)337-8091
smcdonag@ford.com

From: Nowaczyk, Rick (R.J.)
Sent: Thursday, October 18, 2012 9:16 AM
To: Sparks, Douglas (D.S.)
Cc: Oyafuso, Kevin (K.G.); McDonagh, Scot (S.M.); Kramer, Michael (M.T.); Dixon, Mark (M.R.); Dobbs, Dan (K.D.); Ricks, Kevin (K.J.)
Subject: FW: Customer Feedback on New CAC's Installed
Importance: High

Doug,

Unfortunately, we were not able to save this one from going buyback as part of the 12 CAC installed in the field. The dealer installed the new CAC and then the vehicle came back with P0430, so the dealer then installed a new CAT Conv. on 10/3. The vehicle returned again on 10/9 with a repeat P0430 DTC. Currently, the vehicle seems to be performing well.

From: Hall, Christopher (C.)
Sent: Thursday, October 18, 2012 8:25 AM
To: Nowaczyk, Rick (R.J.); Powers, Kurtis (K.S.)
Cc: Johnson, Jim (J.S.); Christoff, Donald (D.A.); Dripps, David (D.S.); Hammer, Richard (R.M.)
Subject: RE: Customer Feedback on New CAC's Installed

Rick,

Below is the reply on received from my dealer and the vin in question;

Chris,

The new CAC installed on 9/28 (ro 35366) . The vehicle returned with a code 430 and p0301 on 10/3 after 125 miles ro (35447) . Per hotline we replace the left hand cat conv. and cylinder #1 coil. The vehicle returned on 10/9 after 64 miles with a p0430 (ro 35744) and was traded in at that time . We cleared the code and have driven over 350 miles so far without a fault.

If you have any other questions, don't hesitate to call me.

Mark J. Anderson
Nick Nicholas Ford

Regards,

Chris Hall

Field Service Engineer
Ford Customer Service Division
Orlando Region
cell-727-643-9285

"Fix it right every time with Rotunda!"



From: Nowaczyk, Rick (R.J.)

Sent: Wednesday, October 17, 2012 4:59 PM

To: Powers, Kurtis (K.S.)

Cc: Johnson, Jim (J.S.); Christoff, Donald (D.A.); Dripps, David (D.S.); Hammer, Richard (R.M.); Hall, Christopher (C.)

Subject: RE: Customer Feedback on New CAC's Installed

Ok, thank you. I will give the feedback to engineering.

From: Powers, Kurtis (K.S.)

Sent: Wednesday, October 17, 2012 4:20 PM

To: Nowaczyk, Rick (R.J.)

Cc: Johnson, Jim (J.S.); Christoff, Donald (D.A.); Dripps, David (D.S.); Hammer, Richard (R.M.); Hall, Christopher (C.)

Subject: RE: Customer Feedback on New CAC's Installed

Hi Rick,

1FTFW1ET0CF [REDACTED] is still doing good, no issues with a misfire. The customer does state he feels like he has lost a little power at the top end (high way speeds) and also stated that his fuel economy has decreased a little.

Regards,

Kurtis Powers
Field Service Engineer, Miami Region
(313) 805-0087

<< OLE Object: Picture (Device Independent Bitmap) >>

From: Nowaczyk, Rick (R.J.)
Sent: Wednesday, October 17, 2012 4:11 PM
To: Powers, Kurtis (K.S.); Dripps, David (D.S.); Hammer, Richard (R.M.); Hall, Christopher (C.)
Cc: Johnson, Jim (J.S.); Christoff, Donald (D.A.)
Subject: Customer Feedback on New CAC's Installed
Importance: High

Field Team,

Any feedback from the customers on the following VIN#?

1FTFW1ET9CFE [REDACTED] - FSE Rick Hammer
1FTFW1ET4BF [REDACTED] - FSE Rick Hammer
1FTFX1ET8CK [REDACTED] - FSE Chris Hall
1FTFW1ET9CK [REDACTED] - FSE Dave Dripps
1FTFW1ET0CF [REDACTED] - FSE Kurtis Powers

Regards,
Rick Nowaczyk
FCSD Product Concern Engineer
F-150, Freestar/Monterey, Ford GT, Th!nk
E-mail: rnwaczy@ford.com
Diagnostic Service Center-I, Allen Park
PH# 313-322-7251

From: McDonagh, Scot (S.M.)
Sent: Thursday, October 18, 2012 11:54 AM
To: McDonagh, Scot (S.M.)
Subject: Report Summary for the CQIS Report#CJBCT002

Attachments : 0

Report# :	CJBCT002 NHL	Received:	10/02/2012
CCRG/EPRC:	Reviewed Status:	Date:	
Vehicle:	2012,F150 4X4 ,F150 ,SUP CAB,STYSD ,1FTFX1ET8CK [REDACTED]	Build Date:	02/24/2012
Odometer :	34,328 M	Engine:	3.5L-GTDI
Transmission:	6R80E	Axle:	
Dealer:	USA 01200 Nick Nicholas Ford, Inc.	Calibration:	CF613C0A
City:	Inverness	A/C:	YES
Originator:	JOHN HYDE	Phone#:	(352) 726-1231
Symptom:	2 27 Q 30 AID/INFO,WNG IND/MESS/C,ENGINE IMAGE,FLASHES		
Status:			
VFG:	V29 CHECK ENGINE LIGHT		
Additional Symptom:	P0301, P0430		
Fix:	Causal Component :	COIL ASY-IGNITION -- RPL	
Condition Code:			
Hotliner:	AHEBERT8	Phone:	313 317-9379
		Regn Cd:	S3 Orlando
Engineering:		Phone:	
		TAR:	
Dlr Contact:	JOHN HYDE	Phone:	352 726-1231
		Title Cde:	T

DTCs:
KOEO:P0301 P0430
KOEC:
KOER:

Comments :
REPAIR 10/02/2012 09:45AM ADAM HEBERT MSS - FCSD - TECH SVC HOTLINE
WEB FORM DATA - CONCERN:VEHICLE HAS CHECK ENGINE LIGHT, FLASHES ON
HARD ACCEL, MISSFIRING ON #1 CYLINDER. DIAGNOSTICS: CHECK CODES
ROAD TEST PULL AND INSPECT #1 SPARK PLUG, LOOKS A LITTLE DARK BUT NOT

BAD. PARTS REPLACED:NONE TODAY. BUT HAS HAD TSB 12-06-04, DONE 06-09-12 AT 15192MILES. LEFT CATALYTIC CONVERTER REPLACED 06-26-12 AT 18719MILES. LEFT CATALYTIC CONVERTER REPLACED 07-30-12 AT28754MILES. CHARGE AIR COOLER REPLACED 08-28-12 AT 34113 MILES. CAC WAS BROUGHT TO US BY CHRIS HALL OUR FIELD SERVICE ENGINEER. HE TOLD US A TSB WAS COMING OUT SOON BUT GOT US THE PART EARLY. TECH QUESTION:WHAT AM I GOING TO DO WITH THIS TRUCK. JUST SO YOU KNOW MOST OF THIS CUSTOMERS DRIVING IS INTERSTATE DRIVING AND HE RUNS TRUCK VERY HARD.

RECOMM 10/02/2012 09:45AM ADAM HEBERT MSS - FCSD - TECH SVC HOTLINE

JOHN, IF THE P0430 IS CURRENTLY PRESENT, THE CATALYST WILL REQUIRE REPLACEMENT AGAIN. DUE TO THIS CONCERN BEING PRESENT ON BANK 1 SUSPECT THAT THIS CURRENT CONCERN IS NOT RELATED TO THE CHARGE AIR COOLER OR MOISTURE BUILDUP AS MOISTURE TYPICALLY AFFECTS BANK 2 DUE TO THE INTAKE DYNAMICS. IT WOULD BE RECOMMENDED TO SWAP THE NUMBER 1 INJECTOR, SPARK PLUG AND COIL WITH ANOTHER GOOD KNOWN CYLINDER THEN RE-EVALUATE.

REPAIR 10/02/2012 10:40AM JIM MITCHELL MSS - FCSD - TECH SVC HOTLINE

DATA FROM PRIOR APPROVAL REQUEST FORM: PLEASE DESCRIBE CUSTOMERS CONCERN.HAS MISSFIRE ON 1 CYLINDER UNDER HEAVY LOAD. DESCRIBE DIAGNOSTIC PROCEDURES COMPLETED AND THE RESULTS. BE SURE TO NOTE ANY PINPOINT OR OTHER DIAGNOSTIC TESTS COMPLETED. INCOMPLETE DIAGNOSIS WILL PROLONG THE PRIOR APPROVAL PROCESS, SO BE SURE TO INCLUDE ALL TEST RESULTS.RUN NORMAL DIAGNOSTICS, EEC TEST INJECTOR FLOW TEST POWERBALANCE ROAD TEST,SHOWS MISSFIRE 1. MOVE 1 COIL ON PLUG TO 2 .2 TO1 MISSFIRE MOVES FROM 1 TO 2. PLEASE LIST PART THAT WAS ROOT CAUSE OF FAILURE:12029 COP. LIST MAJOR COMPONENTS NEEDED FOR REPAIR:NONE PROVIDE ANY ADDITIONAL DETAILS NECESSARY. PLEASE INCLUDE ANY TECHNICAL INFORMATION THAT YOU FEEL WILL HELP THE HOTLINE PROCESS YOUR PRIOR APPROVAL REQUESTNONE REPAIR ESTIMATE - LABOR: REPAIR ESTIMATE - TOTAL: VEHICLE/COMPONENT ABUSE: MODIFICATIONS: LACK OF MAINTENANCE: RO#: 35447RO DATE:2012-10-02WARRANTY TYPE:NEW VEHICLE WARRANTY SPW MILEAGE: SPW INSTALL DATE:

RECOMM 10/02/2012 10:40AM JIM MITCHELL MSS - FCSD - TECH SVC HOTLINE

JOHN SWAPPED COIL,MISS FOLLOWED. THE DEALER IS APPROVED TO REPLACE THE #1 COIL ON PLUG (COP). PLEASE REFERENCE THE ONLINE WORKSHOP MANUAL FOR INSTALLATION INFORMATION.

From: McDonagh, Scot (S.M.)
Sent: Thursday, October 18, 2012 11:54 AM
To: McDonagh, Scot (S.M.)
Subject: Report Summary for the CQIS Report#CIRBB005

Attachments : 0

Report# :	CIRBB005 FCSDFS	Received:	09/18/2012
CCRG/EPRC:		Date:	
Vehicle:	2012,F150 4X4 ,F150 ,SUP CAB,STYSD ,1FTFX1ET8CK [REDACTED]	Build Date:	02/24/2012
Odometer :	30,000 M	Engine:	3.5L- GTDI
Transmission:	6R80E	Axle:	
Dealer:	USA 01200 Nick Nicholas Ford, Inc.	Calibration:	CF613C0A
City:	Inverness	A/C:	YES
State:	Florida	Phone#:	(352) 726- 1231
Country :	USA	Country :	USA
Originator:	MIKE BAKER		
Symptom:	5 50 2 39 DRV PERF,RUNS ROUGH,ACCEL,INTERMITTENT		
Status:			
VFG:	V52 DRIVEABILITY		
Additional Symptom:	AFTER DRIVING IN RAIN		
Fix:	Causal Component :		
Condition Code:			
Region Code:	S3	Region Name:	Orlando

DTCs:
KOE0:
KOE1:
KOE2:

Comments :
OWNER 09/18/2012 01:42PM CHRIS HALL(FSE) MSS - FCSD - REG - ORLANDO
CHRIS,WE HAVE A LOCAL FLEET WITH SEVERAL ECOBOOST F-150'S AND ALL HAVE HAD CHECK ENGINE LIGHT AND PERFORMANCE ISSUES. IF YOU COULD PLEASE LOOK AT THE HISTORY ON THIS ONE IN PARTICULAR. IT IS DRIVEN BY ONE OF THE BOSSES AND IS DRIVEN HARD. NOT OVERLOADED BUT HARD.
1FTFX1ET8CK [REDACTED].JUST WANT TO KNOW WHAT YOU THINK WE MAY NEED TO DO NEXT. CUSTOMER TALKING LEMON LAW. THANKS,MIKE BAKER NICK NICHOLAS

FORD PARTS AND SERVICE DIRECTOR

ADD-ON 09/18/2012 01:42PM CHRIS HALL(FSE) MSS - FCSD - REG - ORLANDO
CONTACTED PCE AND HE IS IN PROCESS OF SHIPPING A CAC TO RESOLVE
CUSTOMER CONCERN.PLEASE SEE AWS FOR WARRANTY HISTORY.

ADD-ON 10/08/2012 06:55AM CHRIS HALL(FSE) MSS - FCSD - REG - ORLANDO
DELIVERED CAC TO DEALER ON 9/24 AND IT WAS INSTALLED SHORTLY AFTER.

ADD-ON 10/18/2012 08:58AM CHRIS HALL(FSE) MSS - FCSD - REG - ORLANDO
CONTACTED DEALER REQUESTING STATUS ON VEHICLE SINCE NEW CAC INSTALLED
AND RECEIVED THIS REPLY; CHRIS, THE NEW CAC INSTALLED ON 9/28 (RO
35366) . THE VEHICLE RETURNED WITH A CODE 430 AND P0301 ON 10/3 AFTER
125 MILES RO (35447) . PER HOTLINE WE REPLACE THE LEFT HAND CAT
CONV. AND CYLINDER #1 COIL. THE VEHICLE RETURNED ON 10/9 AFTER 64
MILES WITH A P0430 (RO 35744) AND WAS TRADED IN AT THAT TIME . WE
CLEARED THE CODE AND HAVE DRIVEN OVER 350 MILES SO FAR WITHOUT A
FAULT. IF YOU HAVE ANY OTHER QUESTIONS, DON'T HESITATE TO CALL ME.
MARK J. ANDERSON

From: McDonagh, Scot (S.M.)
Sent: Wednesday, April 17, 2013 7:41 AM
To: Ricks, Kevin (K.J.); Nowaczyk, Rick (R.J.); Dobbs, Dan (K.D.)
Subject: FW: Engineering visit to Fla for misfire

Stay tuned

Scot G. McDonagh
PT Quality Engineering
Phone: (313)337-8091
smcdonag@ford.com

From: Ronzi, Bill (W.C.)
Sent: Tuesday, April 16, 2013 4:09 PM
To: McDonagh, Scot (S.M.)
Cc: Dixon, Mark (M.R.)
Subject: FW: Engineering visit to Fla for misfire

Scot, Let's hold off on meeting with FCSD on service parts until sometime next week. We want to complete Friday's tunnel testing and also get some TASE MCT feedback before talking about service samples.

Thx
Bill

From: Madej, Jeanette (J.)
Sent: Tuesday, April 16, 2013 1:10 PM
To: Dobbs, Dan (K.D.); Russo, Scott (S.); Kramer, Michael (M.T.); Nowaczyk, Rick (R.J.); McDonagh, Scot (S.M.)
Cc: Ricks, Kevin (K.J.); Sparks, Douglas (D.S.); Dixon, Mark (M.R.); Ronzi, Bill (W.C.); Sowards, John (J.); Andersen, Erik (E.)
Subject: RE: Engineering visit to Fla for misfire

Scott McDonagh is going to get us together.

Jeanette Madej

Global Cooling Manager

313-805-0189

From: Dobbs, Dan (K.D.)
Sent: Tuesday, April 16, 2013 1:08 PM
To: Russo, Scott (S.); Kramer, Michael (M.T.); Nowaczyk, Rick (R.J.); McDonagh, Scot (S.M.)
Cc: Ricks, Kevin (K.J.); Sparks, Douglas (D.S.); Dixon, Mark (M.R.); Ronzi, Bill (W.C.); Madej, Jeanette (J.); Sowards, John (J.); Andersen, Erik (E.)
Subject: RE: Engineering visit to Fla for misfire

Thanks All. We will wait for your update on effectiveness and timing. However due to the market weather conditions, this location may provide the best real-world opportunity to validate.

From: Russo, Scott (S.)
Sent: Tuesday, April 16, 2013 1:02 PM
To: Kramer, Michael (M.T.); Nowaczyk, Rick (R.J.); Dobbs, Dan (K.D.); McDonagh, Scot (S.M.)
Cc: Ricks, Kevin (K.J.); Sparks, Douglas (D.S.); Dixon, Mark (M.R.); Ronzi, Bill (W.C.); Madej, Jeanette (J.); Sowards, John (J.); Andersen, Erik (E.)
Subject: RE: Engineering visit to Fla for misfire

While I support a trip if this investigation will help us learn something new about customer duty cycle, the revised blocker is not a turnkey solution yet at this point in time. Implementing this blocker on this vehicle (before all validation/verification is complete) may just trade one problem for another.

Scott Russo
Ford Motor Company
PT Cooling Applications Manager
srusso2@ford.com
Phone: 313-805-3059
Page: [3138053059@vtext.com](tel:3138053059@vtext.com)

-----Original Message-----

From: Kramer, Michael (M.T.)
Sent: Tuesday, April 16, 2013 12:41 PM
To: Nowaczyk, Rick (R.J.); Dobbs, Dan (K.D.); McDonagh, Scot (S.M.)
Cc: Ricks, Kevin (K.J.); Sparks, Douglas (D.S.); Dixon, Mark (M.R.); Ronzi, Bill (W.C.); Madej, Jeanette (J.); Sowards, John (J.); Andersen, Erik (E.); Kramer, Michael (M.T.); Russo, Scott (S.)
Subject: RE: Engineering visit to Fla for misfire

Unfortunately, test data does not support ability to do a field assessment.

>Mike Kramer
>RWD PT Cooling Supv.
>Six Sigma Black Belt
>Cell Phone: (313) 805-0190
>Text Page: mkramer1
>Page from outside Ford, External email: mkramer1@ford.com

-----Original Message-----

From: Andersen, Erik (E.)
Sent: Tuesday, April 16, 2013 12:38 PM
To: Nowaczyk, Rick (R.J.); Dobbs, Dan (K.D.); McDonagh, Scot (S.M.); Madej, Jeanette (J.); Sowards, John (J.)
Cc: Ricks, Kevin (K.J.); Sparks, Douglas (D.S.); Dixon, Mark (M.R.); Ronzi, Bill (W.C.); Kramer, Michael (M.T.)
Subject: RE: Engineering visit to Fla for misfire

Hold on....We should discuss before any customer vehicles are updated.
There are a number of engineering issues that we are still sorting through.

Bill,

If you can set up some time that would be helpful.

Erik Andersen
Core P/T Cooling
eanderse@ford.com
313-805-2966

-----Original Message-----

From: Nowaczyk, Rick (R.J.)
Sent: Tuesday, April 16, 2013 12:35 PM
To: Dobbs, Dan (K.D.); McDonagh, Scot (S.M.); Madej, Jeanette (J.);
Andersen, Erik (E.); Sowards, John (J.)
Cc: Ricks, Kevin (K.J.); Sparks, Douglas (D.S.); Dixon, Mark (M.R.); Ronzi,
Bill (W.C.)
Subject: RE: Engineering visit to Fla for misfire

I agree with Dan. It's shouldn't be a problem.

-----Original Message-----

From: Dobbs, Dan (K.D.)
Sent: Tuesday, April 16, 2013 12:24 PM
To: McDonagh, Scot (S.M.); Madej, Jeanette (J.); Andersen, Erik (E.);
Sowards, John (J.)
Cc: Nowaczyk, Rick (R.J.); Ricks, Kevin (K.J.); Sparks, Douglas (D.S.);
Dixon, Mark (M.R.); Ronzi, Bill (W.C.)
Subject: RE: Engineering visit to Fla for misfire

I do not see a problem.

From: McDonagh, Scot (S.M.)
Sent: Tuesday, April 16, 2013 12:17 PM
To: Madej, Jeanette (J.); Andersen, Erik (E.); Sowards, John (J.)
Cc: Nowaczyk, Rick (R.J.); Ricks, Kevin (K.J.); Sparks, Douglas (D.S.);
Dobbs, Dan (K.D.); Dixon, Mark (M.R.); Ronzi, Bill (W.C.)
Subject: RE: Engineering visit to Fla for misfire
Importance: High

Can we trial Creative Foam/3M bottom CAC blocker on customer vehicles in parallel with DTF testing ?

<< Message: FW: 3.5 L Engine CEL on Hesitates >>

Scot G. McDonagh
PT Quality Engineering
Phone: (313)337-8091
smcdonag@ford.com

From: Ricks, Kevin (K.J.)
Sent: Friday, April 05, 2013 10:31 AM

To: Sparks, Douglas (D.S.); Dobbs, Dan (K.D.); Dixon, Mark (M.R.)

Cc: Nowaczyk, Rick (R.J.); McDonagh, Scot (S.M.)

Subject: Engineering visit to Fla for misfire

Doug, we would like to request an engineering visit to a couple critical customer vehicles in coordination with our TSOM Jim Johnson in Florida. This could accomplish a couple objectives, real world feedback on the new proposed blocker and partially to show goodwill to dealers in the area. Perhaps we could get a couple blockers to try out. We can coordinate.

Kevin Ricks

Manager - Truck Service Engineering

FCSD - Service Engineering Operations

KRICKS@Ford.com

313-323-6574

From: Johnson, Jim (J.S.)
Sent: Wednesday, October 10, 2012 10:18 AM
To: Nowaczyk, Rick (R.J.)
Cc: Dobbs, Dan (K.D.)
Subject: FW: F-150 CAC

FYI – Two more dealers ordered parts

From: Dripps, David (D.S.)
Sent: Wednesday, October 10, 2012 12:02 AM
To: Christoff, Donald (D.A.); Kuffel, Adam (A.B.); Hall, Christopher (C.); Gibula, Jeff (J.P.); Carey, John (J.P.); McCall, Kris (K.J.); McClung, Shannon (S.T.); Powers, Kurtis (K.S.); Hammer, Richard (R.M.); Jackson, Robert (R.P.); Kocher, Michael (M.); Sonnen, Stuart (S.J.); Triplette, Wesley (.)
Cc: Johnson, Jim (J.S.)
Subject: RE: F-150 CAC

They're shipping now. I had two dealers pressing me for one and I had them order it emergency last week and both got them this morning. Part number: BL3Z- 6K775-B.

David S. Dripps
Field Service Engineer
Atlanta, Georgia
Southeast Region
678-358-8458

From: Dobbs, Dan (K.D.)
Sent: Friday, February 01, 2013 2:39 PM
To: Nowaczyk, Rick (R.J.)
Subject: FW: F150 GTDI CAC Misfire Emerging QSF

Here you go skippy – now you’re in the big time.... Again.

From: Ronzi, Bill (W.C.)
Sent: Friday, February 01, 2013 2:28 PM
To: Dobbs, Dan (K.D.)
Subject: F150 GTDI CAC Misfire Emerging QSF

Dan, Are you the keeper of the file for the above? If so, can you send me the VINS that are currently included?

Thanks,

Bill

William C. Ronzi
PTI Quality Supervisor
(313) 805-6140 cell & pgr

From: Hamilton, Steven (S.C.)
Sent: Monday, September 12, 2011 12:36 PM
To: Dobbs, Dan (K.D.); Nowaczyk, Rick (R.J.)
Subject: FW: Misfire Status

Not sure if I sent this last week.

Best regards,

Steve Hamilton

FCSD Service Engineering Operations
F-150 PVT Program Manager
(313)390-7750

From: Cockerill, Al (C.A.)
Sent: Thursday, September 08, 2011 8:48 AM
To: Hamilton, Steven (S.C.)
Subject: FW: Misfire Status

The spirit, the will to win, and the will to excel are the things that endure. These qualities are so much more important than the events that occur. The harder you work, the harder it is to surrender.
Vince Lombardi

Al Cockerill
RWD V6 Engine System Supervisor
313-805-2333 C
313-845-0475 O

From: Cockerill, Al (C.A.)
Sent: Thursday, September 08, 2011 8:46 AM
To: Saad, Thomas (T.J.); Galas, Dean (C.K.); Sims, Ivan (I.D.); Mazuchowski, James (J.A.)
Subject: Misfire Status

Tom,

Per our conversation, I will not be able to provide an update for the PRT at 9:30. The team is meeting with the PT Chiefs today at 11:30 to discuss next steps based on our findings from vehicle testing at DTF.

The status at this time is as follows:

1. Warranty trends continue to show a significant decrease. No significant change since the review with Bennie.
2. We have confirmed the an entire bank needs to be misfiring before catalyst damage occurs
3. We have confirmed that if a cylinder is misfiring and FMEM action is not taken, then the misfire will propagate and cause the other cylinders on that bank to misfire
4. We have multiple COP warranty items that have been addressed with ICA's and PCA's in place
5. There is a COP item, (Primary Layer Short or PLS), which we can not confirm as a supplier quality issue or a result of electrical damage in vehicle.
6. We have been able to replicate the misfire drive cycle at DTF with a PLS coil and thus we are discussing next steps with the PT Chief today.

The spirit, the will to win, and the will to excel are the things that endure. These qualities are so much more important than the events that occur. The harder you work, the harder it is to surrender.
Vince Lombardi

Al Cockerill
RWD V6 Engine System Supervisor
313-805-2333 C

From: Hamilton, Steven (S.C.)
Sent: Tuesday, October 11, 2011 2:18 PM
To: Nowaczyk, Rick (R.J.)
Cc: Garrett, David (D.P.); McDonagh, Scot (S.M.)
Subject: FW: P415 3.5L GTDI MisFire QSF

Rick,

Is this the correct QSF tracking number?

Thanks.

Best regards,

Steve Hamilton

FCSD Service Engineering Operations
Diesel Commodity Manager
(313)390-7750

From: Cervenán, Neil (N.J.)
Sent: Tuesday, October 11, 2011 2:16 PM
To: Hamilton, Steven (S.C.)
Cc: Garrett, David (D.P.); McDonagh, Scot (S.M.)
Subject: P415 3.5L GTDI MisFire QSF

Steve,

PCSE wants to add the official QSF tracking number for P415 3.5L GTDI Misfire to a WERS concern.

Please verify the following number in bold, that I've copied from the weekly QSF report, is correct:

06920110034-3.5L MISFIRE ON ACCEL w/o DTCs

Thanks,

Neil Cervenán Phone: 313-805-7036
ncervena@ford.com Bldg #2 24Q34

From: Ricks, Kevin (K.J.)
Sent: Thursday, February 28, 2013 12:53 PM
To: Holzheuer, Bill (W.P.)
Cc: Dobbs, Dan (K.D.); Nowaczyk, Rick (R.J.)
Subject: FW: P415 GTDI Misfire - CAC moisture

Unbelievable.

From: Norton, John (J.K.)
Sent: Thursday, February 28, 2013 12:48 PM
To: Ricks, Kevin (K.J.)
Cc: Dwan, Patrick (P.J.); Klump, Robert (R.F.)
Subject: FW: P415 GTDI Misfire - CAC moisture

FYI... If the revised TSB has not gone, please hold until we have a response from Bob Facetti.

Regards,

John Norton

Global Chief Engineer
Customer Service Engineering
Ford Customer Service Division
Phone: (313) 322-9454
Email: jnorton@ford.com

From: Berardi, Michael (M.A.)
Sent: Thursday, February 28, 2013 12:43 PM
To: Fascetti, Robert (R.J.)
Cc: Norton, John (J.K.)
Subject: FW: P415 GTDI Misfire - CAC moisture

Bob, We should probably get our teams together to see if we may have a concern on our hands (oh by the way – hope your vacation was a good one and you actually got to slow down a little!) on the CAC TSB that we are getting ready to re-publish. Looks like we have some reports where the CAC has been replaced and the concern is still present. Either the dealer didn't diagnose it correctly, or something else is happening. Before we re-publish the TSB, is your team aware that we have these potential repeat repairs out there?

Mike Berardi
Director - Service Engineering Operations
Ford Customer Service Division
Administrative Assistant - Sandy Schwartzenberger (38468)
Phone - (313) 323-8467
Fax - (313) 845-2580

Share the Ford Story at www.TheFordStory.com
Save Paper - Do not print this email unless absolutely necessary

From: Norton, John (J.K.)
Sent: Thursday, February 28, 2013 12:31 PM
To: Berardi, Michael (M.A.); Ricks, Kevin (K.J.)
Subject: RE: P415 GTDI Misfire - CAC moisture

ike,

We have reached the SF threshold for reports where the new CAC has been installed and customers are still having the problem. The new CAC is a significant improvement, but it does not appear that it is fixed. The thought would be to meet with powertrain management to determine if further actions are necessary or even possible before we open another SF. Are you in agreement with this approach?

Regards,

John Norton

Global Chief Engineer
Customer Service Engineering
Ford Customer Service Division
Phone: (313) 322-9454
Email: jnorton@ford.com

From: Ricks, Kevin (K.J.)
Sent: Thursday, February 28, 2013 11:48 AM
To: Norton, John (J.K.); Berardi, Michael (M.A.)
Subject: FW: P415 GTDI Misfire - CAC moisture
Importance: High

Part of our strategy of putting out the TSB with improved diagnostics was to open our emerging concern on this concern for those cases that still have issues after the latest and greatest hardware and software revisions. Before we open a QSF, I want to make sure all parties are overtly aware. I will call a brief teleconference with us, PT Sparks, Baum, McCoy, Fascetti, can you suggest other key stake holders?

From: Nowaczyk, Rick (R.J.)
Sent: Thursday, February 28, 2013 9:08 AM
To: Ronzi, Bill (W.C.); McDonagh, Scot (S.M.)
Cc: Dobbs, Dan (K.D.); Nowaczyk, Rick (R.J.)
Subject: RE: P415 GTDI Misfire - CAC moisture

I went through some more 2011-2012 GCQIS reports and we have reached the QSF threshold of 25. I will be e-mailing the updated GCQIS folder when the system has downloaded the reports to the server.

We will not be flipping this to QSF just yet. Kevin Ricks wants to have a discussion with John Norton and Mike Berardi first. Thanks

From: Ronzi, Bill (W.C.)
Sent: Wednesday, February 27, 2013 9:43 AM
To: McDonagh, Scot (S.M.); Nowaczyk, Rick (R.J.)
Cc: Dobbs, Dan (K.D.); Dixon, Mark (M.R.)
Subject: RE: P415 GTDI Misfire - CAC moisture

Rick, Would like to get the updated VIN list when you have a chance.

From: McDonagh, Scot (S.M.)
Sent: Wednesday, February 27, 2013 7:20 AM
To: Ronzi, Bill (W.C.); Nowaczyk, Rick (R.J.)
Cc: Dobbs, Dan (K.D.); Dixon, Mark (M.R.)
Subject: RE: P415 GTDI Misfire - CAC moisture

(20) Reports not including 11-12MY

Concern Title:

Quality Team: F-□□□

Status: Emerging **Open** **VIN Count: 20** **Threshold:** □□ % of **Threshold:** □□□
Date: □□□□an□□□□ 

Function: □owertrain **Days Open:** □□

PCE: **Last Updated:** □□Feb□□□□ □□□□□□A□

Functional Champion: □□CC□Y **Engineering Contact:**
□□□A□E□□

Scot G. McDonagh
PT Quality Engineering
Phone: (313)337-8091
smcdonag@ford.com

-----Original Message-----

From: Ronzi, Bill (W.C.)
Sent: Tuesday, February 26, 2013 4:51 PM
To: Nowaczyk, Rick (R.J.); McDonagh, Scot (S.M.)
Cc: Dobbs, Dan (K.D.)
Subject: RE: P415 GTDI Misfire - CAC moisture

Rick, Can you provide an update when you have a chance? I believe we're up to 18 now?

Thx
Bill Ronzi

-----Original Message-----

From: Nowaczyk, Rick (R.J.)
Sent: Monday, February 04, 2013 1:09 PM
To: McDonagh, Scot (S.M.); Ronzi, Bill (W.C.)
Cc: Dobbs, Dan (K.D.)
Subject: RE: P415 GTDI Misfire - CAC moisture
Importance: High

Sorry for the delay...GCQIS was not cooperating last Friday.

-----Original Message-----

From: McDonagh, Scot (S.M.)

Sent: Monday, February 04, 2013 11:54 AM
To: Ronzi, Bill (W.C.); Dobbs, Dan (K.D.)
Cc: Nowaczyk, Rick (R.J.)
Subject: RE: P415 GTDI Misfire - CAC moisture

I asked Rick to provide latest folder with (14) CQIS Reports

Scot G. McDonagh
PT Quality Engineering
Phone: (313)337-8091
smcdonag@ford.com

-----Original Message-----

From: Ronzi, Bill (W.C.)
Sent: Monday, February 04, 2013 11:48 AM
To: McDonagh, Scot (S.M.); Dobbs, Dan (K.D.)
Subject: RE: P415 GTDI Misfire - CAC moisture

Scot, Were you able to find the emerging QSF folder VINS? I shot Dan a note on Friday but not sure if he's the right guy for this one.

Bill

From: Dixon, Mark (M.R.)
Sent: Monday, February 04, 2013 11:18 AM
To: Leisenring, Kenneth (K.C.); Cervenán, Neil (N.J.); Ronzi, Bill (W.C.)
Cc: McDonagh, Scot (S.M.); Smith, Craig (C.A.)
Subject: RE: P415 GTDI Misfire - CAC moisture

Ken, yes, we have 1 and 2 MIS data. Meant to include you on attached email.

Neil, lets plan to update Joe on this tomorrow. Bill, any information on a service fix as this is heading for QSF levels.

<< Message: RE: 2013 MY 3.5L GTDI P415 Misfire Daily AWS Claims (Post 9/18/12 Vehicle Build Date) - (1/22/13) >>

From: Leisenring, Kenneth (K.C.)
Sent: Monday, February 04, 2013 10:08 AM
To: Dixon, Mark (M.R.); Cervenán, Neil (N.J.)
Cc: McDonagh, Scot (S.M.); Smith, Craig (C.A.)
Subject: RE: P415 GTDI Misfire - CAC moisture

Did we ever get an R/1000 estimate for before and after the CAC PCA? This should come into Joe Baum's FQR tomorrow as well.

Thanks.

Ken Leisenring
Manager, Powertrain Calibration
Cell: (313) 805-5459
kleisenr@ford.com

From: Dixon, Mark (M.R.)
Sent: Tuesday, January 22, 2013 4:33 PM
To: Leisenring, Kenneth (K.C.); Cervenán, Neil (N.J.); Smith, Craig (C.A.)
Cc: McDonagh, Scot (S.M.)
Subject: RE: P415 GTDI Misfire - CAC moisture

Mike Kramer is the cooling supervisor we need to invite. I asked Paul Ng to take the latest misfire claims file for vehicles with the new CAC (post 9/18 production) and calculate the R/1000 improvement. Should have a 1 and 2 MIS number to compare against the old CAC data.

From: Leisenring, Kenneth (K.C.)
Sent: Tuesday, January 22, 2013 3:38 PM
To: Cervenán, Neil (N.J.); Smith, Craig (C.A.)
Cc: Dixon, Mark (M.R.); McDonagh, Scot (S.M.)
Subject: RE: P415 GTDI Misfire - CAC moisture

Who did you invite the previous 20 times this issue was reviewed in the FQR and it was allegedly solved? I'd like to hear what they have to say.

On a serious note, I think Craig Smith knows who is currently leading this investigation for the Cooling team.

Ken Leisenring
Manager, Powertrain Calibration
Cell: (313) 805-5459 - note: back to old number
kleisenr@ford.com

From: Cervenán, Neil (N.J.)
Sent: Tuesday, January 22, 2013 3:36 PM
To: Leisenring, Kenneth (K.C.)
Cc: Dixon, Mark (M.R.); McDonagh, Scot (S.M.)
Subject: P415 GTDI Misfire - CAC moisture

Ken,

The P415 GTDI issue for 'continued moisture in CAC & misfire after CAC update' is an emerging issue @ 48% QSF threshold.

Who from the PTI Cooling team should I invite to the FQR to present their status to Joe?

Thanks,

Neil Cervenak 313-805-7036
ncervena@ford.com Bldg #2 24Q34