

RQ13-002

GM

8/16/2013

Q8A

2012 Camaro-Cruze-Verano-
Sonic airbag connector-20 Jan
13 NHTSA

Shorting Bar within the Driver's Airbag Connector



**Model Year: 2012 Cruze, Verano, Camaro, and Sonic
4,101 vehicles**

ETQ N120261

Condition: Some 2012 Cruze, Verano, Camaro, and Sonic vehicles have a driver's side airbag connector shorting bar that may have been damaged during assembly of the airbag.


Effect of the Condition: A vehicle in this condition may set diagnostic trouble code B0013 (secondary stage inflator). The Sensing and Diagnostic Module (SDM) will request the instrument cluster to illuminate the AIRBAG indicator. If a crash event occurs the the SDM will attempt deployment, but, if the shorting bar is in contact with the airbag terminals, the airbag will not deploy.

Technical Root Cause: During the retainer seating process the shorting bars were not fully retracted to prevent contact with the airbag terminals.

Responsibility: Takata

Potential Field Action Category: Safety


Potential Field Remedy: Replace the clock spring.



Primary and Secondary Stage Inflator Connectors


Primary Stage
Inflator Connector
(sets DTC B0012)

Secondary Stage
Inflator Connector
(sets DTC B0013)




2012 Female and Male Connectors

Female Connector




Front

Actuator Finger



Side

CPA*



Back

Male Connector



Terminals




Shorting Bar Clip



Assembled Connector

*Connector Position Assurance

X-Rays of Assembled Male and Female Connector Shorting Bar Retracted




Male Connector - Retracting the Shorting Bar

Front of Male Connector




Shorting Bar Engaged




Actuator Finger Inserted

Shorting Bar Retracted


Back of Shorting Bar Clip




CPA Engaged



*X-Rays of Assembled Male and Female Connector
Shorting Bar Damaged*



X-Rays of Assembled Male and Female Connector Shorting Bar Damaged



Shorting Bar within the Driver's Airbag Connector



**Model Year: 2012 Cruze, Verano, and Sonic
3,922**

ETQ N120261

Condition: Some 2012 Cruze, Verano, and Sonic vehicles have a driver's side airbag connector shorting bar that may have been damaged during assembly of the airbag.


Effect of the Condition: A vehicle in this condition may set diagnostic trouble code B0012 (primary stage inflator). The Sensing and Diagnostic Module (SDM) will request the instrument cluster to illuminate the AIRBAG indicator. If a crash event occurs the the SDM will attempt deployment, but, if the shorting bar is in contact with the airbag terminals, the airbag will not deploy.

Technical Root Cause: During the retainer seating process the shorting bars were not fully retracted to prevent contact with the airbag terminals.

Responsibility: Takata

Potential Field Action Category: Safety

Potential Field Remedy: Inspect the connection or replace the clock spring or the driver's side airbag.




Shorting Bar

Conversation with the NHTSA

- Did the issue start in April 12
- Infant mortality


2011/2012 Camaro, Cruze, Sonic, and Verano Airbag Filtered Warranty IPTV vs Month of Build




Subject of
further analysis

Subject of
field action


2011/2012 Camaro, Cruze, Sonic, and Verano Airbag Filtered Warranty IPTV vs Month of Build



2011/2012 Camaro, Cruze, Sonic, and Verano Airbag Filtered Warranty IPTV vs Month of Build



2012 Camaro, Cruze, Sonic, Verano Airbag Filtered Warranty Cumulative IPTV for Inflator Build Dates 3 and 7 Dec 11




Shorting Bar


Conversation with the NHTSA

- Did the issue start in April 12
- Infant mortality


2011/2012 Camaro, Cruze, Sonic, and Verano Airbag Filtered Warranty IPTV vs Month of Build




2012 Cruze, Sonic, Verano Airbag Filtered Warranty Cumulative IPTV for Vehicle Build Dates 8 - 21 Jun



2012 Cruze, Sonic, Verano Airbag Filtered Warranty Cumulative IPTV for Select Inflator Build Dates



2011/2012 Camaro, Cruze, Sonic, and Verano Airbag Filtered Warranty IPTV vs Month of Build



Shorting Bar Population

	Model Year	Number Involved
US		
Verano	2012	409
Camaro	2012	429
Cruze	2012	1,981
Sonic	2012	1,077
Total		3,487
GM CANADA		
Verano	2012	33
Camaro	2012	4
Cruze	2012	36
Sonic	2012	132
Total		205
Total GM		4,101

RQ13-002

GM

8/16/2013

Q8A

Pictures of Damaged Parts


2012 Chevrolet Cruze, Verano, and Sonic

Pictures of Damaged Parts




2012 Chevrolet Cruze, Verano, and Sonic

Pictures of Damaged Parts



Witness marks on shorting bars



Note how the shorting bars are bent in to the page

RQ13-002

GM

8/16/2013

Q8A

Q_08_2012 2013 Cruze and
Verano Warranty Summary
with 5 phase 29OCT12 Rev. 1-p

2012 Buick Verano and Chevrolet Cruze Driver Airbag & Clockspring Quality Issues

Craig Zinser – Infotainment and Controls Global BOM Leader
David Silvestri – Switches and Controls GSSLT Lead
Lenore Kolhoff – CEA EGM

Douglas Houlihan – Safety Components Global BOM Leader
George Helou – Safety Components GSSLT Lead
Lisa Amin – SW & DAB EGM


October 31st, 2012

WORLD'S BEST VEHICLES





{ * } Indicates GM Confidential Business Information Redacted



(Back to Summary)



WORLD'S BEST VEHICLES





Airbag Light On

Root Cause:

- Bent DAB inflator shorting clips due to damage to installation tool.
- Supplier quality spill at inflator facility.

Containment:

- Quality Spill Start: Approx. 01AP12
- GM notified: 12JN12
- Clean Break point: 22JN12. Replaced shorting clips.


Corrective Action

- Replaced shorting clip installation tool.



Supplier
Quality
Spill

(Back to Summary)



WORLD'S BEST VEHICLES






BACK UP

WORLD'S BEST VEHICLES



2011-2012 Cruze and Verano Clockspring and Airbag Trend Chart




WORLD'S BEST VEHICLES





2009-2013 All GMNA Vehicles Clockspring Trend Chart




WORLD'S BEST VEHICLES







Safety Suppliers Manufacturing Footprints



Autoliv: 
 Seatbelts: Tijuana & Toluca Mexico
 Airbags: Ogden, Utah & Queretaro, Mexico
 Steering Wheels: Matamoros, Mexico
 Inflator: **Brigham, Utah**
 Cushion: Queretaro, Mexico

TRW: 
 Seatbelts: Reynosa, Mexico
 Airbags: Chihuahua, Mexico
 Steering Wheels: Chihuahua, Mexico
 Inflator: Meza, Arizona

KSS: 
 Seatbelts: Valle Hermoso, Mexico
 Airbags: Knoxville, Tennessee
 Steering Wheels: Valle Hermoso, Mexico
 Inflator: Valle Hermoso, Mexico
 Cushion: Juarez, Mexico

Takata: 
 Seatbelts: Acuna, Mexico
 Airbags: Acuna, Mexico
 Steering Wheels: Monterrey, Mexico
 Inflator: Monclova, Mexico
 Airbag cover & Cushion: Monclova, Mexico

TGNA: 
 Airbags: Perryville, Missouri
 Steering Wheels: Perryville, Missouri
 Inflator: Purchased (ARC)



RQ13-002

GM

8/16/2013

Q8A

Q_08_2012 Cruze and Verano
Warranty 29OCT12-p

Airbag Light On

Root Cause:

- Bent DAB inflator shorting clips due to damage to installation tool.
- Supplier quality spill at inflator facility.

Containment:


- Quality Spill Start: Approx. 01AP12
- GM notified: 12JN12
- Clean Break point: 22JN12. Replaced shorting clips.

Corrective Action

- Replaced shorting clip installation tool on 16JN12.



Supplier
Quality
Spill



WORLD'S BEST VEHICLES

RQ13-002

GM

8/16/2013

Q8A

Interior Tech

Symposium_GSSLT Restraints

Breakout Session

(Materials)_06DEC2012 rev-p

Driver Airbag Light On 2012 Cruze, Verano, Sonic & Volt



Shorting Bar within the Driver's Airbag Connector



Model Year: 2012 Cruze, Verano, and Sonic
3,922 plus recently sold vehicles
Cost Estimate: TBD

ETQ N120261

Condition: Some 2012 Cruze, Verano, and Sonic vehicles have a driver's side airbag connector shorting bar that may have been damaged during assembly of the airbag.

Effect of the Condition: A vehicle in this condition may set diagnostic trouble code B0012 (primary stage inflator). The Sensing and Diagnostic Module (SDM) will request the instrument cluster to illuminate the AIRBAG indicator. If a crash event occurs the the SDM will attempt deployment, but, if the shorting bar is in contact with the airbag terminals, the airbag will not deploy.


Technical Root Cause: During the retainer seating process the shorting bars were not fully retracted to prevent contact with the airbag terminals.

Responsibility: Takata


Projected Frequency: TBD IPTV

Potential Field Action Category: Safety


Potential Field Remedy: Inspect the connection or replace the clock spring or the driver's side airbag.




2012 Chevrolet Cruze, Verano, and Sonic Male Connector - Retracting the Shorting Bar



2012 Chevrolet Cruze, Verano, and Sonic X-Rays of Assembled Male and Female Connector Shorting Bar Retracted



2012 Chevrolet Cruze, Verano, and Sonic X-Rays of Assembled Male and Female Connector Shorting Bar Damaged



RQ13-002

GM

8/16/2013

Q8A

Cruze,+Verano,+and+Sonic+air
bag+connector+-
+22+Oct+12+FPET-p

Shorting Bar within the Driver's Airbag Connector



Model Year: 2012 Cruze, Verano, and Sonic
3,922 plus recently sold vehicles
Cost Estimate: TBD

ETQ N120261

Condition: Some 2012 Cruze, Verano, and Sonic vehicles have a driver's side airbag connector shorting bar that may have been damaged during assembly of the airbag.

Effect of the Condition: A vehicle in this condition may set diagnostic trouble code B0012 (primary stage inflator). The Sensing and Diagnostic Module (SDM) will request the instrument cluster to illuminate the AIRBAG indicator. If a crash event occurs the the SDM will attempt deployment, but, if the shorting bar is in contact with the airbag terminals, the airbag will not deploy.


Technical Root Cause: During the retainer seating process the shorting bars were not fully retracted to prevent contact with the airbag terminals.

Responsibility: Takata


Projected Frequency: TBD IPTV

Potential Field Action Category: Safety

Potential Field Remedy: Inspect the connection or replace the clock spring or the driver's side airbag.




2012 Chevrolet Cruze, Verano, and Sonic Female and Male Connectors




*Connector Position Assurance

2012 Chevrolet Cruze, Verano, and Sonic X-Rays of Assembled Male and Female Connector Shorting Bar Retracted





2012 Chevrolet Cruze, Verano, and Sonic Male Connector - Retracting the Shorting Bar




2012 Chevrolet Cruze, Verano, and Sonic Root Cause


The length of the Push Tab was measured using a microscope. The push tab length of the primary chamber shorting clip insertion tool was shorter than the secondary chamber shorting clip insertion tool.




*2012 Chevrolet Cruze, Verano, and Sonic
X-Rays of Assembled Male and Female Connector
Shorting Bar Damaged*




*2012 Chevrolet Cruze, Verano, and Sonic
X-Rays of Assembled Male and Female Connector
Shorting Bar Damaged*




Cruze Airbag Light On by Day of Build




Verano Airbag Light On by Day of Build




Sonic Airbag Light On by Day of Build



Camaro Airbag Light On by Day of Build



Airbag Light On by Day of Build 3 Months of Exposure



2012 Chevrolet Cruze, Verano, and Sonic Options

Vehicle	11 Jun 12 - 21 Jun 12	Jun 2012 at Dealer
Cruze Population	10,511	2,989
Verano Population	1,475	310
Sonic Population	2,534	623
Total Population	14,520	3,922
Airbag Cost	{ ** }	{ ** }
Clockspring cost	{ ** }	{ ** }
Inspect Cost	{ ** }	{ ** }

RQ13-002

GM

8/16/2013

Q8A

Cruze Warranty Summary

10302012

2013 Cruze Warranty

- 29 unique VINS have roll coil (C8800) or air bag (C8835) claims
 - 8 VINS with air bag (C8835) labor op
 - 21 VINS with roll coil (C8800) labor op
 - 13 of 29 VINS had LPO Cruise Control Installed *prior* to Roll Coil/Air Bag labor op
 - 12 of 13 claims 10 miles or less (exception of 1 claim at 29 miles)
 - 2 of 29 VINS had LPO installed *after* Roll Coil/Air Bag labor op
 - No repeat dealers (all unique)
 - Accessory Cruze RPO RXZ Penetration of 7% according to PPC
- Accessory Install Procedure provided to engineering for review
- Accessory Install Procedure to be performed on-vehicle with engineering (coil and air bag) to review procedure and identify any issues
- Contacting dealers with recent claims in an effort to understand issues/concerns with procedure

WORLD'S BEST VEHICLES

RQ13-002

GM

8/16/2013

Q8A

Driver Airbag Check - TIS-p

{ * } Indicates GM Confidential Business Information Redacted

{ * }

{ * }



Signature Block				Date:	Name:	Change Description:
Shift		Team Leader	Group Leader			
1	Sign Date					
2	Sign Date					
3	Sign Date					


RQ13-002

GM

8/16/2013

Q8B

2458853-AA Amphenol

Distribution: to: cc: Herr Annecke Herr Dullin Herr Beck, Till Herr Plappert Herr Schmid Herr Schuster Herr Treanor	Author S. Schulz	Date September 22, 2009
	Approved by 	Order no. PA 09/099
	Test object Airbag AK2 Retainer C252 14B002 XXX 2 EP200400423	

Task

Qualifying test for **Design Verification** of Airbag retainers with AK2 interface

1. Summary

Presented were Airbag retainers AK2 C252 14B002 XXX 2, manually assembled in insulator rings of types AK2 codes I, II and III, for Design Verification. The retainers C252 14B002 X0X 2 and shorting clips were subjected to selected tests acc. to the qualifying matrix of Amphenol specification N50 252 0015 Rev.02.

The test samples meet the specified requirements of all test lots.

O.K.


2. Used documents

Working Committee Test Guideline of the German Automotive Industry. Edition 1, April 1996
 Specification Retainer AK2 Amphenol Tuchel Electronics N 50 252 0015 Rev.02

Drawings:
 Retainer C252 14B002 X0X 2 Rev.02
 Shorting clip N 02 072 0014 100
 Shorting clip on strip N 02 072 0014 102
 Insulator ring C252 H09 X0X E2

3. Test samples

46 Airbag AK_2 retainers, coding I, black: C252 14B002 101 2
 46 Airbag AK_2 retainers, coding II, light green: C252 14B002 205 2
 46 Airbag AK_2 retainers, coding III, yellow: C252 14B002 306 2
 All test samples without date code, production location Heilbronn



4. Tests (Test groups)

- PG 0: Receiving inspection (electrical resistances $R_{D \text{ contact}}$ and $R_{D \text{ bulk}}$)
- PG 1: Dimensions
- PG 2: Surface analysis
- PG 5: Electrical characteristics
- PG 11: Mechanical characteristics (contact normal force, service life / mating cycles)
- PG 17: Dynamic stress (Vibration covered with temperature change)
- PG 19: Environmental simulation (Temperature shock, dry heat, damp heat cyclic)
- PG 21: Long term temperature storage

5. Results

PG 0: Receiving inspection

No.	Test	Requirement	Result	Remark
E 0.1	Visual inspection DIN IEC 512 P.2	No mech. defects on housing; no corrosion or damage on contact surfaces; no crushes	No deviations	O.K.
E 0.2	Shorting resistance in contact area of firing pellet Test groups PG11 and PG19 DIN IEC 512 P.2	$R_D < 100 \text{ m}\Omega$	min 45,76 mΩ max 48,22 mΩ avg 46,96 mΩ	O.K.
E 0.2	Shorting resistance in contact area of firing pellet Test groups PG 2, 5, 17, 21 DIN IEC 512 P.2	$R_D < 100 \text{ m}\Omega$	min 40,26 mΩ max 44,10 mΩ avg 41,66 mΩ	OK.
E 0.2	Path resistance (Bulk) DIN IEC 512 P.2	$R_B < 40 \text{ m}\Omega$	min 37,01 mΩ max 39,73 mΩ avg 38,56 mΩ	O.K.

PG 1: Dimensions:

No.	Test	Requirement	Result	Remark
E 0.1	Visual inspection DIN IEC 512 P.2	No mech. defects on housing; no corrosion or damage on contact surfaces	No deviations	O.K.
E 1.1	Dimensions	Dimensions conform to release drawing	Dim. within tolerances, see First Sample Test Report Shorting clip 0065-02/08 Ins.ring I 0070-03/08 Ins.ring II 0071-03/08 Ins.ring III 0072-03/08	O.K.

PG 2: Surface analysis of contacts:

Only contacts of Test groups PG 11-1 and PG 19:

No.	Test	Requirement	Result	Remark
E 2.1.2	Layer structure of shorting clip N 02 072 0011 102 Test groups PG 11-1 and PG19	Area (1): Ni > 5 µm	Ni thickness: min 6,42 µm max 7,67 µm avg. 6,91 µm	O.K.

PG 11-1: Mechanical characteristics / Service life

(3 x 5 Test samples)

No.	Test	Requirement	Result	Remark
E 0.1	Visual inspection 15 test samples DIN IEC 512 P.2	No mech. defects on insulator ring; no corrosion or damage on contact surfaces	No deviations	O.K.
E 11.1	Contact normal force	Determination of contact normal force in new state, deflection of clip in new state in firing pellet; Specified: F > 40 cN	F _N : min 101 cN max 128 cN avg. 119 cN	O.K.
	Life cycle test: Operation of shorting clip	20 x mating and locking of an Airbag connector	Accomplished	O.K.
E 11.1	Contact normal force	Determination of contact normal force Specified: F > 40 cN	F _N : min 90 cN max 102 cN avg. 95 cN	O.K.
E 0.2	Shorting resistance in contact area of firing pellet DIN IEC 512 P.2	R _D ≤ 100 mΩ	R _D : min 48,68 mΩ max 52,52 mΩ avg. 50,17 mΩ	O.K.

PG 11-2: Mechanical characteristics acc. to N50 252 0015 Rev.01

E 0.1	Visual inspection 15 new test samples DIN IEC 512 P.2	No mech. defects on insulator ring; no corrosion or damage on contact surfaces	No deviations	O.K.
E 11.2	Retention force of shorting clip in insulator ring	Determination of retention force of clip in insulator ring in new state at RT: F > 10 N	F _N : min: 87,4 N max: 106,7 N avg. 98,6 N	O.K.

E 0.1	Visual inspection 15 new test samples DIN IEC 512 P.2	No mech. defects on insulator ring; no corrosion or damage on contact surfaces	No deviations	O.K.
E 11.3	Retention force of insulator ring in ignitor carrier	Determination of retention force of retainer in ignitor carrier (Type L) in new state at room temperature: F > 20 N	F _N : min 44,3 N max 64,9 N avg. 54,1 N	O.K.

PG 12: Electrical characteristics:

No.	Test	Requirement	Result	Remark
E 0.1	Visual inspection DIN IEC 512 P.2	No mech. defects on insulator ring; no corrosion or damage on contact surfaces	No deviations	O.K.
E 1.1	Derating 3 test samples	Current carrying capacity of shorting clip	Will be measured with other plating acc. to new specification	
	Dielectric strength 30 test samples from test group PG 19 DIN IEC 512-2 test 4a	No flash over at 1000 V _{DC} to pins of firing pellet under connector position assurance	No flash over at 1000 V _{DC}	O.K.

PG 17: Dynamic stress acc. to N50 252 0015 Rev.01

3x5 test samples

No.	Test	Requirement	Result	Remark
E 0.1	Visual inspection DIN IEC 512 P.2	No mech. defects on insulator ring; no corrosion or damage on contact surfaces	No deviations	O.K.
E 0.2	Contact resistance in contact area DIN IEC 512 P.2	$R_D \leq 100 \text{ m}\Omega$	min 40,735 m Ω max 42,578 m Ω avg. 41,687 m Ω	O.K.
E 11.1	Contact normal force	Determination of contact normal force in new state, deflection of clip as mounted in firing pellet; Specified: $F > 40 \text{ cN}$	F_N : min 61,8 cN max 91,7 cN avg. 79,8 cN	O.K.
B 17.1	Sinus oscillation covered with temperature change acc. test group B19.2 DIN IEC 512-4, test 6d	Sinus oscillation 15...1000 Hz: 5 g acc. test group B17.1 max. temperature: 100°C 24 h per spatial axis	Accomplished at Amphenol Tuchel Electronics, mated with Airbag_AK2 cable assemblies	O.K.
B 17.3	Mechanical shocks	30g, 6 ms 1000 shocks per axis and direction, total: 6000 shocks	Accomplished at Amphenol Tuchel Electronics, mated with Airbag_AK2 connectors	O.K.
E 0.2	Contact resistance in contact area DIN IEC 512 P.2	$R_D \leq 100 \text{ m}\Omega$	min 42,67 m Ω max 77,80 m Ω avg. 47,14 m Ω	O.K.
E 11.1	Contact normal force	Contact normal force after dynamic stress $F > 40 \text{ cN}$	F_N : min 40,7 cN max 66,2 cN avg. 50,3 cN	O.K.
E 0.1	Visual inspection DIN IEC 512 P.2	No mech. defects on insulator ring; no corrosion or damage on contact surfaces	No deviations	O.K.

PG 19: Environmental simulation acc. to Working Committee Test Guideline

(Group 1: 3 x 5 pcs. unmated, Group 2: 3 x 5 pcs. mated with AK2 connector)



No.	Test	Requirement	Result	Remark
E 0.1	Visual inspection DIN IEC 512 P.2	No mech. defects on insulator ring; no corrosion or damage on contact surfaces	No deviations	O.K.
E 0.2	Contact resistance in contact area Group 1 and 2 DIN IEC 512 P.2	$R_D \leq 100 \text{ m}\Omega$	min 45,76 mΩ max 48,22 mΩ avg. 46,96 mΩ	O.K.
		Separation of Group 1	Accomplished	O.K.
B19.1	Rapid change of temperature DIN IEC 60068-2-14, Na	$T_U = -40^\circ\text{C}$, 15 minutes, $T_O = +90^\circ\text{C}$, 15 minutes 144 cycles Duration: 3 days	Accomplished at AMPHENOL TUCHEL Electronics GmbH	O.K.
E 02	Contact resistance in contact area Group 2 only DIN IEC 512 P.2	$R_D \leq 100 \text{ m}\Omega$ Group 2 only	min 47,34 mΩ max 52,04 mΩ avg. 50,12 mΩ	O.K.
B19.3	Dry heat DIN EN 60068-2-2, Ba	Temperature: $T = 90^\circ\text{C}$ Duration: 120 hrs.	Accomplished at AMPHENOL TUCHEL Electronics GmbH	O.K.
E 0.2	Contact resistance in contact area Group 2 only DIN IEC 512 P.2	$R_D \leq 100 \text{ m}\Omega$ Group 2 only	min 51,31 mΩ max 60,05 mΩ avg. 54,46 mΩ	O.K.
E 0.1	Visual inspection DIN IEC 512 P.2	No mech. defects on insulator ring; no corrosion or damage on contact surfaces	No deviations	O.K.
B 19.5	Damp heat, cyclic DIN IEC 68068-2-30, Var. 2	95% rel. hum. $+25^\circ\text{C} / +55^\circ\text{C}$ 10 cycles Duration: 10 days	Accomplished at AMPHENOL TUCHEL Electronics GmbH	O.K.
		Mating with Group 1	Accomplished	O.K.
E 0.1	Visual inspection DIN IEC 512 P.2	No mech. defects on insulator ring; no corrosion or damage on contact surfaces	No deviations	O.K.
E 0.2	Contact resistance in contact area Group 1 and 2 DIN IEC 512 P.2	$R_D \leq 100 \text{ m}\Omega$ Group 1 and 2, after environmental simulation	Group 1: min 45,92 mΩ max 49,43 mΩ avg. 47,52 mΩ Group 2: min 49,42 mΩ max 62,20 mΩ avg. 55,27 mΩ	O.K. O.K.

Continuation **PG 19: Environmental simulation**

No.	Test	Requirement	Result	Remark
E 0.3	Dielectric strength at 1000 V _{DC}	No flash over at 1000 V _{DC}	No flash over	O.K.
E 11.1	Contact normal force	Contact normal force Group 1 and 2, after environmental simulation	Group 1 min 100 cN max 129cN avg. 113 cN	O. K.
		F > 40 cN	Group 2 min 46 cN max 71 cN avg. 55 cN	O.K.

PG 21 Long term temperature storage

No.	Test	Requirement	Result	Remark
E 0.1	Visual inspection DIN IEC 512 P.2	No mech. defects on insulator ring; no corrosion or damage on contact surfaces	No deviations	O.K.
B21.1	Dry heat	Long term temperature storage T = 120°C Duration: 1000 hrs.	Accomplished at AMPHENOL TUCHEL Electronics GmbH	O.K.
	Storage	Storage at room temperature Duration: 7 days	Accomplished at AMPHENOL TUCHEL Electronics GmbH	O.K.
E 0.1	Visual inspection DIN IEC 512 P.2	No mech. defects on insulator ring; no corrosion or damage on contact surfaces	No deviations, no cracks, no delaminations, see photographs below:	O.K.



S. Schulz
QA Laboratory

RQ13-002

GM

8/16/2013

Q8B

601554

Global Quality Tracking System

Problem Reporting and Resolution

PRR Number 601554

Issuing Plant LORDSTOWN ASSEMBLY

Status Closed

Supplier:823761820 INDUSTRIAS IRVIN DE MEXICO SA DE CV KM 7 CARR PRESA LA AMISTAD COL PARQUE INDUSTRIAL LA AMISTAD CIUDAD ACUNA,CZ,26238,MX	Contact: Hector Falcon Phone Number: 830 703 7253 Title: cust serv quality Email: hecto.falcon@takata.com Address:
---	--

Customer: Mauro R Jadue	Issue Date: 18-Jun-2012
Contact No: +1 330 553 6062	Time: 09:44:51 AM
Internal Destination:	PRR Type: Quality
Phase: Production	Primary N/C: Electrical
Station: Not Applicable	Secondary N/C: Inoperative
Supplier Initiated: N	Vehicle/PWT/Component Impact: Not Applicable
Direct Run Rate: N	Plant Impact: Not Applicable
Email Address for Notification: mauro.jadue@gm.com	Major Disruption: Plant Disruption
Ship From Duns#:	Initiator Role Code: 1LD0MJ
Ship From Duns Name:	Internal Indicator: false
DDW / Read Across Required : N	Approver Role Code: 1LD0MJ
	Repeated PRR Number Issued: N

Supplier Contacted: N

Person Contacted Reason Supplier Not Contacted



Problem Information

Material Identification													
Locati on	Line Item	Part Number	DLS/P LS	Part Descripti	Misc 1	Misc 2	SI D	Carri er	PRT S	Date Shipp	Quantit y	Quanti ty	Quanti ty N/C

Code	Date		Location	Code	Entered	Suspected	Checked	
01LD	18-JUN-2012	95214734	AIRBAG ASM-STRG WHL		18-JUN-2012	1	1	1

Problem Description

Driver air bag has damaged internal shorting bar.
This causes DTC code to be set (B0012 OE)
GM Lordstown requests containment and a breakpoint of certified material to be provided to our ESEP provider, PTI. The

Note: The latest revised Drill Deep & Wide (DDW) found on GM Supplypower (Quality folder=> Current Quality) must be

Please provide federal express tracking account number for return shipment of suspect parts.

"Please update this PRR today with the conforming material date which should be no later than within 48 hrs of the original date of this PRR. If you cannot meet this date please email the originator of this PRR with an explanation."

Dan Heck
PTIQCS

Quality Liaison - GM Lordstown
Cell - 812-447-1130
Cell - 330-353-6899 off shift
Nextel - 136*53468*1
Fax - 330-824-7576
E-Mail - dheck@ptiqcs.com

Initial Response

Material Disposition	
In Plant: Not Applicable	In Transit: Not Applicable
Compliance Measurement Method	
1.-Communicate issue to all involved personel (FRancisco fuentes) 2.-Create and post a quality alert at process area (Francisco Fuentes) 3.-Sort material in warehosue and house. Certified material will be identified with a green dot 1/4 inch diameter placed on Takata initiated production with certified inflators - upon process improvements at inflator mfg facility. Takata materials is working with Gm to expedite certified material. Upon priorities provided by the team.	
Containment Action	

1.-Communicate issue to all involved personel (FRancisco fuentes)
 2.-Create and post a quality alert at process area (Francisco Fuentes)
 3.-Sort material in w arehosue and house. Certified material w ill be identified w ith a green dot 1/4 inch diameter placed on
 Takata initiated production w ith certified inflators - upon process improvements at inflator mfg facility.
 Takata materials is w orking w ith Gm to expedite certified material. Upon priorities provided by the team.

Conforming Material Date: 20-Jun-2012

Problem Identification

Caused By Sub Tier Supplier : N

GM Directed Buy Indicator : N	Supplier's Duns Number :
-------------------------------	--------------------------

GM Component Part Number :	Supplier Part Description :
----------------------------	-----------------------------

Root Cause

Supplier: Shorting clip installation into inflator results in dmgaged or misaligned placement of shorting bar.
 Escape: On 6/14/2012 damage to underside of shorting bars were observed in returned parts that correlated with the a
 Primary stage shorting clip installation tool does not match secondary shorting clip installation tool dimensionally (0.3mm c
 Escape: Shortingclip installation tooling not covered by normal equipment preventative maintenance plan. As a result toc
 Overall system interface and stack-up betw een multiple vendor supplied components do not provide adequate clearanc

QSB Status: CF Certified - Expires : 15-Dec-2013

QSB Failure
 Mode :

Failure Cause - Prevent: Other - Please Specify Details in Root Cause Memo Field	Failure Cause - Predict: Other - Please Specify Details in Root Cause Memo Field	Failure Cause - Protect: Other - Please Specify Details in Root Cause Memo Field
--	--	--

Corrective Action

1.-Redesign improved shorting clip insertion tool according to shorting clip supplier's recommendation to guarantee corre
 2.-Include short clip insertion tooling preventive maintenance plan to inspect condition and dimensional validation of the tr
 3.-Implement next generation Molex body side connector to improve robustness of AK2 system and shorting bar retracti
 4.-Investigate removing shorting bar from design of record to eliminate chance of low airbag resistance.

FMEA Changes Complete Date: 29-Jun-2012	Process Control Plan Changes Complete Date: 29-Jun-2012
Corrective Action Implementation Date: 12-Jul-2012	

Implementation

Implementation
<p>Install redesigned shorting clip installation tool from D5-1 above on all PSDI-Xlines 7/12/2012 Update tooling preventative maintenance schedule and QA documents to include shorting clip installation tools per D5-2 ; Implement next generation molex body side connector per D5-3 above. MY13 breakpoint</p>

Evaluate
<p>Validation of actions upon complete of actions.</p>

Institutionalized
<p>Communicate global read across to all Takata inflator manufacturing locations and product lines.</p>

DDW/Read Across Completed : N

DDW Comment
<p></p>

Cost Recovery Information

Cost Recovery Detail											
Locati on Code	Curren cy	CR Line Item Create Date	Departm ent To Credit	Financ e Recove ry	Man Hours Request ed	Downti me Minutes	Numb er of Units Impact ed	Additio nal Costs	Negotiat ed Total Cost	Total Cost Request ed	Approv ed By
01LD	USD	19-JUL-2012	01LDE1		2840	0	1	0	0	156200	

Reason for Cost Recovery

Recovery hours per attached excel file.

Cost Recovery Status

Response Pending

Supplier Response to Cost Recovery

Customer Comments

Status : Closed

Approval Date : 24-Jul-2012

Approver Name : tzl576 - Mauro R Jadue

Comments

Supplier corrected tooling. Confirmed certified material received.
24 July 2012 Mauro Jadue

Last updated on 27-Jun-13



RQ13-002

GM

8/16/2013

Q8B

602022

Global Quality Tracking System

Problem Reporting and Resolution

PRR Number 602022

Issuing Plant ORION ASSEMBLY

Status Closed

Supplier:823761820 INDUSTRIAS IRVIN DE MEXICO SA DE CV KM 7 CARR PRESA LA AMISTAD COL PARQUE INDUSTRIAL LA AMISTAD CIUDAD ACUNA,CZ,26238,MX	Contact: Hector Falcon Phone Number: 8307037170 Title: Quality eng Email: hector.falcon@takata.com Address:
---	---

Customer: Mark E Wenzlick	Issue Date: 19-Jun-2012
Contact No: 248-377-5272	Time: 12:13:03 PM
Internal Destination:	PRR Type: Customer Satisfaction
Phase: Production	Primary N/C: Miscellaneous
Station: Production Line	Secondary N/C: Other
Supplier Initiated: N	Vehicle/PWT/Component Impact: Not Applicable
Direct Run Rate: N	Plant Impact: Not Applicable
Email Address for Notification:	Major Disruption: Not Applicable
Ship From Duns#:	Initiator Role Code: 1OR0MW
Ship From Duns Name:	Internal Indicator: false
DDW / Read Across Required : N	Approver Role Code: 1OR0MW
	Repeated PRR Number Issued: N

Supplier Contacted: N

Person Contacted Reason Supplier Not Contacted



Problem Information

Material Identification													
Locati on	Line Item	Part Number	DLS/P LS	Part Descripti	Misc 1	Misc 2	SI D	Carri er	PRT S	Date Shipp	Quantit y	Quanti ty	Quanti ty N/C

Code	Date		on				Code	ed	Suspected	Checked	
01OR	19-JUN-2012	95181997	MODULE ASM-AIRBAG STRG WHL <USE 1A2R 006					19-JUN-2012	1	1	1
01OR	19-JUN-2012	20986955	MODULE ASM-INFL RST STRG WHL					19-JUN-2012	1	1	1
01OR	19-JUN-2012	20986956	MODULE ASM-INFL RST STRG WHL					19-JUN-2012	1	1	1

Problem Description

This customer satisfaction PRR is to cover the cost related to all of Orion Assemblies activities for PRR 601554 written b

The cost recovery will be updated when the inspection and repair process is completed.

Total cost of yard sort, remove and replace airbags is completed.

Initial Response

Material Disposition

In Plant: Not Applicable In Transit: Not Applicable

Compliance Measurement Method

- 1.-Communicate issue to all involved personel (FRancisco fuentes)
- 2.-Create and post a quality alert at process area (Francisco Fuentes)
- 3.-Sort material in warehosue and house. Certified material will be identified with a green dot 1/8 inch diameter placed on Takata initiated production with certified inflators - upon process improvements at inflator mfg facility. Takata materials is working with Gm to expedite certified material. Upon priorities provided by the team.

Containment Action

1.-Communicate issue to all involved personel (FRancisco fuentes)
 2.-Create and post a quality alert at process area (Francisco Fuentes)
 3.-Sort material in w arehosue and house. Certified material w ill be identified w ith a green dot 1/4 inch diameter placed on
 Takata initiated production w ith certified inflators - upon process improvements at inflator mfg facility.
 Takata materials is w orking w ith Gm to expedite certified material. Upon priorities provided by the team.

Conforming Material Date: 21-Jun-2012

Problem Identification

Caused By Sub Tier Supplier : N	
GM Directed Buy Indicator : N	Supplier's Duns Number :
GM Component Part Number :	Supplier Part Description :

Root Cause

Supplier: Shorting clip installation into inflator results in dmgaged or misaligned placement of shorting bar.
 Escape: On 6/14/2012 damage to underside of shorting bars were observed in returned parts that correlated with the a
 Primary stage shorting clip installation tool does not match secondary shorting clip installation tool dimensionally (0.3mm c
 Escape: Shortingclip installation tooling not covered by normal equipment preventative maintenance plan. As a result toc
 Overall system interface and stack-up betw een multiple vendor supplied components do not provide adequate clearanc

QSB Status: CF	Certified - Expires : 15-Dec-2013	
QSB Failure Mode :		
Failure Cause - Prevent: Other - Please Specify Details in Root Cause Memo Field	Failure Cause - Predict: Other - Please Specify Details in Root Cause Memo Field	Failure Cause - Protect: Other - Please Specify Details in Root Cause Memo Field

Corrective Action

1.-Redesign improved shorting clip insertion tool according to shorting clip supplier's recommendation to guarantee corre
 2.-Include short clip insertion tooling preventive maintenance plan to inspect condition and dimensional validation of the tr
 3.-Implement next generation Molex body side connector to improve robustness of AK2 system and shorting bar retracti
 4.-Investigate removing shorting bar from design of record to eliminate chance of low airbag resistance.

FMEA Changes Complete Date: 29-Jun-2012	Process Control Plan Changes Complete Date: 29-Jun-2012
Corrective Action Implementation Date: 12-Jul-2012	

Implementation

Implementation

Install redesigned shorting clip installation tool from D5-1 above on all PSDI-Xlines 7/12/2012
 Update tooling preventative maintenance schedule and QA documents to include shorting clip installation tools per D5-2 ;
 Implement next generation moxex body side connector per D5-3 above. MY13 breakpoint

Evaluate

Validation of actions upon complete of actions.

Institutionalized

Communicate global read across to all Takata inflator manufacturing locations and product lines.

DDW/Read Across Completed : N

DDW Comment

Cost Recovery Information

Cost Recovery Detail											
Locati on Code	Curren cy	CR Line Item Create Date	Departm ent To Credit	Financ e Recove ry	Man Hours Requested	Downti me Minutes	Numb er of Units Impact ed	Additio nal Costs	Negotiat ed Total Cost	Total Cost Requested	Approv ed By
01OR	USD	16-JUL-2012			0	0	0	38676	0	38676	

Reason for Cost Recovery

Problem Solving_____	\$0
Event Management_____	\$0
Dow ntime_____	\$0
In-plant w ork by GM_____	\$9,350
Shipping yard_____	\$29,326
External support_____	\$0
Misc_____	\$0
Explanation for misc.:	
Total_____	\$38,676

Cost break dow n

\$ 12,856 AWC yard cost
\$ 16,470 Rousch inspection and rew ork in the yard
40 Hours 2 QEs monitoring the w ork
50 Hours repair of vehicles in the plant
80 Hours 2 operators do line inspection

Cost Recovery Status

Approved

Supplier Response to Cost Recovery

Customer Comments

Status : Closed

Approval Date :

Approver Name : -

Comments

Last updated on 27-Jun-13



RQ13-002

GM

8/16/2013

Q8B


8D - 2012 GM DAB Inflator
with marks on shorting bar 7-
20-12

G8D Report

Title 2012 GM DAB Airbag Light On – Low Resistance	Date Opened 06/15/2012	Last Updated 07/20/12
Product/Process Information Inflator: TK PSDI-X PN 2448636-AB Shorting clip: Amphenol PN 2458853-AA MIO: Production line F.	Organization Information TKH (North America) / MIO (Monclova Inflators Operation)	
DØ Symptom(s) During vehicle assembly process, line operators at Lordstown identified intermittent electrical connection with the primary (code 2, stage 1). Vehicle found with fault code (low resistance stage 1 – primary) resulting in an airbag light on.		

DØ Emergency Response Action(s) TKH-MIO: Validate assembly process controls to guarantee good parts for customer. TKH-MIO: Validate all stock of Inflators to assure no marks on shorting bar.	% Effective 100 100	Date Implemented 06/15/12 06/15/12
---	--------------------------------------	---

D1 Team TAKATA: Don Sztaba, Tim Kmiec, Will Chavez, Mike Done, Tony Rivera, Bob Phillion, Jeff Deevey, Carlos Iruegas, Mario Ramos, Jesus Flores, Rodolfo Rodriguez, Luis Briones, Guillermo Apud, Jaime Villarreal, Dagoberto Gutierrez, Luis Dominguez, Rodolfo Gaytan, David Villarreal, Omar Gaytan, Francisco Contreras, Jack Vaughn GM: Lisa Amin, Karen May, Pradeep Singh, Phil Stasevich, Jay Kelly, George Helou, Steve Drop Molex: Dave Koehler FCI: Mike Matusik, Terry Herfurth	D2 Problem Problem Statement: On 06/12/12 there were 15 consecutive GM driver airbag modules at Lordstown plant with electrical intermittence due to short circuit condition between inflator initiator pin and shorting bar on the primary stage.	
---	---	--

D3 Interim Containment Action(s) 1. RED-X team was assembled at TKH lead by Pradeep Singh to evaluate BOB/WOW. The team worked with BOB/WOW samples from Lordstown and Orion. Investigation into the body side connector / shorting clip / the team concluded the shorting clip (code2) was the RED-X.	% Effective 100	Date Implemented 06/14/12
		
2. TKH MIO - Validate no marks on Shorting bar during assembly process (10 pieces each hour)	100	06/15/12
3. TKH MIO – Replaced the primary stage installation tool with a revised tool matching the secondary stage dimensional and design intent.	100	06/16/12
4. TKH MIO - Validate shorting bar retraction reference dimension (>2.50mm) between shorting clip base and shorting clip bar when shorting clip is placed on tool. (1 at beginning each shift / 1 at change over)	100	06/16/12
5. TKH Acuna – Raw material 100% sort, insert connector, press for 15sec and verify resistance value spec 1.7 – 2.3 ohms, each inflator is marked with a blue line.	100	06/18/12
6. TKH Acuna – In line verification 100% - no connector only probes and resistance checks range 1.7 to 2.3 ohms – a green dot is places on protective film (emblem) on top of cover.	100	06/18/12
7. TKH Acuna – Finished goods off line random audit 10% - same process as raw material sort activity, a number 2 is marked on retainer side upon inspection.	100	06/18/12
8. Inventory produced from April 18 th to May 23 rd was reviewed for witness marks on shorting bar. No damage or marks seen on shorting bars.	100	06/21/12

D4 Root Cause(s)		% Contribution	
		6/27	7/17
1.	One or more incoming components or sub-assemblies was not to print or specification Verification: All materials, components verified and within specifications.	0%	0%*
2.	Shorting clip installation into inflator results in damaged or misaligned placement of shorting bar. Escape: On 06/14/12 damage to underside of shorting bars were observed in returned parts that correlated with the Airbag Light on condition. Examination of the manufacturing process found that shorting bar was not fully retracted during insertion process resulting in interference/contact between initiator pins and shorting bar. Additional comparisons were made to secondary stage (no reported issues) and a 0.3 mm shorter difference in tab length was detected in the insertion tool itself.	40%	0%
3.	Primary stage shorting clip installation tool does not match secondary shorting clip installation tool dimensionally (0.3 mm difference in tab length). Escape: On or approximately May 25 th , the primary shorting clip installation tooling was repaired by plant maintenance changing the effect work point of the tool. This event was not covered by normal equipment preventative maintenance plan. As a result tooling validation (dimensional/visual inspection) not defined at preventive maintenance or at QA assurance routines.	20%	60%
4.	Overall system interface and stack-up between multiple vendor supplied components do not provide adequate clearance in all combinations (Molex, FCI, Amphenol) between the shorting bar and initiator pins when the body side connectors are installed in vehicle position. * awaiting measurement data from Molex and capability study of electrical connection.	40%	40%*
D5 Chosen Permanent Corrective Action(s)		% Effective	
		6/27	7/17
1.	N/A	-	-
2.	Redesign improved shorting clip insertion tool according to shorting clip supplier's recommendation to guarantee correct shorting bar retraction and no damage during installation.	40%	100%
3.	Include short clip insertion tooling on the tooling preventative maintenance plan to inspect condition and dimensional validation of the tool. Frequency to define tool life will be confirmed by tooling lay out every 15 days. Include on QA check sheet dimensional validation for shorting bar retraction distance (one piece) and no marks condition on shorting bar (5 pieces). (Beginning of shift and change over). A) To keep shorting clip insertion tool, according to print the following actions will be taken: *Define special dimensions on tool. *Develop procedure. *Make shorting clip insertion tool spare parts. B) *Implement next generation Molex body side connector to improve robustness of AK2 system and shorting bar retraction by the CPA.	30%	100%
4.	Investigate removing shorting bar from design of record to eliminate chance of low airbag resistance. Update: On QRDCP meeting on Wed 27 th , GM agreed to re-visit the possibility of removing the shorting bar feature from the shorting clip. The decision will come from GM Electrical team, the Safety team does support moving in this direction.	30%	30%
		100%	100%

<p>D6 Implemented Permanent Corrective Action(s)</p> <ol style="list-style-type: none"> 1. N/A 2. Install redesigned shorting clip installation tool from D5-2 above on all PSDI-X lines. Based upon the FCI recommended insertion tool design (5.4 +/- 0.2 mm critical dimension), the tool was tested and found to be capable for inserting the shorting clip with damage. 3. Update tooling preventative maintenance schedule and QA documents to include shorting clip installation tools per D5-3 above. <p>3A) Implement new procedure to validate specific insertion tool dimensions before start of production.</p> <ol style="list-style-type: none"> 4. Implement next generation Molex body side connector per D5-3 above. 	<p>Date Implemented</p> <p>N/A</p> <p>Complete</p> <p>Complete</p> <p>Complete</p> <p>MY13 Breakpoint</p>	
<p>D7 Prevent Actions</p> <ol style="list-style-type: none"> 1. Update D/PFMEA and PQCT to include the shorting clip insertion failure mode. 2. Communicate global read across to all Takata inflator manufacturing locations and product lines. A meeting was held with Takata Germany to inform and assure this problem will not happen. Meeting held on 7/6. 3. Implement layered audits in order to assure all actions have been completed. 	<p>Date Implemented</p> <p>Complete</p> <p>07/20/12</p> <p>Completed</p>	
<p>D7 Systemic Prevent Recommendations</p> <ol style="list-style-type: none"> 1. Specify OEM approved and validated connector and shorting clip combinations to reduce variability. 2. Utilize shorting clip supplier approved installation tools and/or tooling drawings for future programs and verify again when supplier changes occur. 	<p>Responsibility</p> <p>GM</p> <p>TAKATA</p>	
<p>D8 Team and Individual Recognition</p>	<p>Date Closed</p>	<p>Reported By</p>

RQ13-002

GM

8/16/2013

Q8B

Public ER-0522-031

**Potential Failure Mode And Effects Analysis (Design FMEA)
ER-0522 Rev 03 DFMEA PSDI-X Inflator Family with AIB**

Eight Pages Submitted To The Office Of Chief Counsel With A Request For Confidential Treatment

RQ13-002

GM

8/16/2013

Q8B

Public PFMEA Linea F SU GM

DELTA

Confidential Excel Workbook Submitted To The Office Of Chief Counsel With A Request For
Confidential Treatment

RQ13-002

GM

8/16/2013

Q8C

2012 Camaro, Cruze, Verano,

Sonic airbag connector - 15

Aug 13 FPERC

Shorting Bar within the Driver's Airbag Connector



**Model Year: 2012 Cruze, Verano, Camaro, and Sonic
8,023 vehicles**

ETQ N120261
RQ13002

Condition: Some 2012 Cruze, Verano, Camaro, and Sonic vehicles have a driver's side airbag connector shorting bar that may have been damaged during assembly of the airbag.


Effect of the Condition: A vehicle in this condition may set diagnostic trouble code B0012 (primary stage inflator) or B0013 (secondary stage inflator). The Sensing and Diagnostic Module (SDM) will request the instrument cluster to illuminate the AIRBAG indicator. If a crash event occurs the the SDM will attempt deployment, but, if the shorting bar is in contact with the airbag terminals, the airbag will not deploy.

Technical Root Cause: During the retainer seating process the shorting bars were not fully retracted to prevent contact with the airbag terminals.

Responsibility: Takata

Potential Field Action Category: Safety


Potential Field Remedy: Replace the clockspring.



Primary and Secondary Stage Inflator Connectors


Primary Stage
Inflator Connector
(sets DTC B0012)

Secondary Stage
Inflator Connector
(sets DTC B0013)




2012 Female and Male Connectors

Female Connector




Front

Actuator Finger



Side

CPA*



Back

Male Connector



Terminals




Shorting Bar Clip



Assembled Connector

*Connector Position Assurance

X-Rays of Assembled Male and Female Connector Shorting Bar Retracted




Male Connector - Retracting the Shorting Bar

Front of Male Connector




Shorting Bar Engaged




Actuator Finger Inserted

Shorting Bar Retracted


Back of Shorting Bar Clip



CPA Engaged




X-Rays of Assembled Male and Female Connector Shorting Bar Damaged




Movement in this damaged connector could short the associated airbag stage.


X-Rays of Assembled Male and Female Connector Shorting Bar Damaged



2012 Camaro, Cruze, Sonic, and Verano Airbag Filtered Warranty IPTV vs Day of Inflator Build




2012 Camaro, Cruze, Sonic, and Verano Airbag Filtered Warranty Cumulative IPTV for N120261 Inflator Build Dates



The RQ13002 investigation found that the warranty rate for this issue is dropping. **So addressing those vehicles at dealerships and with less than 30 days of exposure was the correct action.**


2012 Camaro, Cruze, Sonic, and Verano Airbag Filtered Warranty Incremental IPTV for N120261 Inflator Build Dates

The RQ13002 investigation found that the warranty rate for this issue is dropping. **So addressing those vehicles at dealerships and with less than 30 days of exposure was the correct action.**




2012 Camaro, Cruze, Sonic, and Verano Airbag Filtered Warranty IPTV vs Month of Vehicle Build

NHTSA RQ13002 defined the subjects vehicles as 2012 MY Camaro, Cruze, Sonic and Verano. This chart is the cumulative warranty responsive to RQ13002 vs. month of vehicle build for all subject vehicles.




2012 Camaro, Cruze, Sonic, and Verano Airbag Filtered Warranty IPTV vs Month of Vehicle Build After Removal of 12 Days

This chart is the cumulative warranty responsive to RQ13002 vs. month of vehicle build for subject vehicles after the 12 inflator build days addressed by the 2 field actions are removed.



2012 Camaro, Cruze, Sonic, and Verano Airbag Filtered Warranty IPTV vs Month of Vehicle Build at 12 Months Exposure



Shorting Bar Issue

Summary from the Response

- *The circumstances of the shorting bar issue, and the recent warranty data, show the risk to motor vehicle safety for the subject vehicles to be very low for the following reasons.*
 - Warranty data show that the recalls targeted the appropriate vehicle population. This is demonstrated by the low warranty rate which is seen in the non-recalled vehicles
 - For the first recall, 12V522, which included some vehicles built in April, May and June of 2012, the issue occurred very early in the vehicle's service. In fact, many of the vehicles were repaired before they were delivered to customers. In addition, since the recall, there has been a low rate of warranty for the subject condition (0.5 IPTV) for non-recalled vehicles manufactured in these months. The rate of claims has declined over time.
 - For the second recall, 13V023, which involved vehicles built in December 2011 and January 2012, GM recalled all vehicles built with inflators from the two suspect inflator build days. Since the recall, there has been a low rate of warranty claims for the subject condition (0.4 IPTV) for non-recalled vehicles manufactured in these months. The rate of claims has declined over time.
 - Since the recalls, the warranty rate for the subject condition in the non-recalled subject vehicles is only 0.2 IPTV for the entire 2012 Model Year.

Shorting Bar Issue

Summary from the Response

- *Continued*

- If the shorting bar contacts the terminal in the connector, the airbag warning light will illuminate. The warning light is an overt signal to the operator that the airbag needs to be serviced. The light remains on in front of the operator to warn the operator of the condition.
- For most of the subject vehicles, a “SERVICE AIRBAG” message will appear in the Driver Information Center (DIC).
- The OnStar vehicle diagnostic report, which is a monthly email communication from OnStar, will remind the vehicle owner that the airbag warning light is on and that the vehicle needs to be serviced. On Star service is provided at no charge for the first six months of vehicle ownership.
- The subject vehicles are under warranty. There is no reason for a vehicle owner to hesitate to bring the vehicle in for service when the airbag light is illuminated.
- NHTSA did not send any VOQ’s related to this issue to GM. GM conducted a search for VOQ’s and found none.
- There have been no reported crashes or injuries related to this condition.
- Of the GM reports which GM sent with its partial response on August 2, 2013, which occurred at a low rate of 0.5 IPTV, it should be noted that over half of these could not be definitively attributed to the shorting bar issue. Some of these reports are likely to have involved an airbag light illuminating with no impact on airbag performance.

- *Therefore, the risk to motor vehicle safety in the subject vehicles which were not recalled is extremely low.*

RQ13-002

GM

8/16/2013

Q10

Public Production Line F



Controls and Poka-yokes

The following slides show up controls and Pokayoke from Line Line F PSDI-X.

30 Pages Submitted To The Office Of Chief Counsel With A Request For Confidential Treatment

RQ13-002

GM

8/16/2013

Q11

Public CP Linea F SU PSDI-X
GM Delta GSV Rev 20D

Confidential Excel Workbook Submitted To The Office Of Chief Counsel With A Request For
Confidential Treatment

RQ13-002

GM

8/16/2013

Q11

Public CP Linea V SU PSDI-X

GM Delta GSV Rev 4B

Confidential Excel Workbook Submitted To The Office Of Chief Counsel With A Request For
Confidential Treatment

RQ13-002

GM

8/16/2013

Q11

Public GM Intermittent issue


PSDI-X update 10 26 12



TAKATA



PSDI-X GM 2448636-AB
Intermittent Issue





Root Cause (Snake chart point 2)

Examination of the manufacturing process found that the shorting bar was not fully retracted during insertion process resulting in interference/contact between initiator pins and shorting bar. Additional comparisons were made to secondary stage (no reported issues) and a 0.3 mm shorter difference in tab (simulated cpa) length was detected in the insertion tool itself.



On approximately May 25th, the primary shorting clip installation tooling was detected to be damaged and repaired by plant maintenance changing the effect work point of the tool. This tool was not covered by normal equipment preventative maintenance plan, so no documentation was kept.

On June 16th the primary stage installation tool was replaced with a dimensional revised tool. This new tool matched the secondary stage tool for dimensional and design intent.

Insertion Tool	Dimension	Drawing	Dimensional
PSDI-X 130-08-0 Green SC		0.255 (6.47 mm)	0.236 (5.99 mm)
PSDI-X 130-09-0 Yellow SC	Tab Length	0.255 (6.47 mm)	0.250 (6.38 mm)
Insertion Tool	Dimension	Drawing	Dimensional
PSDI-X 130-08-0 Green SC	Tab Length	0.255 (6.47 mm)	0.250 (6.35 mm)

6-16-12
Replacement tool

Nine Pages Submitted To The Office Of Chief Counsel With A Request For Confidential Treatment