



U.S. Department  
of Transportation

**National Highway  
Traffic Safety  
Administration**

# ODI RESUME

**Investigation:** PE 14-004  
**Date Opened:** 01/31/2014  
**Investigator:** Michael Lee  
**Approver:** Frank Borris  
**Subject:** Inadvertent Side Air Bag Deployment

**Date Closed:** 07/29/2014  
**Reviewer:** Scott Yon

## MANUFACTURER & PRODUCT INFORMATION

**Manufacturer:** Honda (American Honda Motor Co.)  
**Products:** 2008 Honda Accord 4-door  
**Population:** 335,195

**Problem Description:** The side curtain air bag and seat-mounted torso air bag can inadvertently deploy when the vehicle's door is shut.

## FAILURE REPORT SUMMARY

	ODI	Manufacturer	Total
<b>Complaints:</b>	37	237	274
<b>Crashes/Fires:</b>	0	0	0
<b>Injury Incidents:</b>	5	9	14
<b>Number of Injuries:</b>	5	9	14
<b>Fatality Incidents:</b>	0	0	0
<b>Other*:</b>	0	133	133

\*Description of Other: Warranty claims

## ACTION / SUMMARY INFORMATION

**Action:** This Preliminary Evaluation has been upgraded to an Engineering Analysis (EA14-004).

### Summary:

ODI has identified 293 incidents of alleged inadvertent deployment of the side air bags in model year (MY) 2008 Honda Accord 4-door vehicles. This total represents all incidents reported to both ODI and Honda including those from Honda's warranty system (note: the total shown above eliminates all duplicative reports to ODI and Honda). This investigation has revealed that when the driver or front passenger door is shut, the driver-side or passenger-side side curtain air bag can deploy, and in some cases, the side seat-mounted torso air bag can deploy as well. Fourteen people allegedly suffered injuries caused by the deploying air bags.

In June 2008, near the end of MY 2008 Accord 4-door production, Honda changed the crash parameter for door closing force, which is embedded in the electronic control unit's software code, in order to reduce the incidents of the inadvertent side air bag deployments. More specifically, the software design change was made on June 5, 2008 for the Accords built in the U.S. and on June 30, 2008 for those built in Japan. ODI found the number of the inadvertent deployment incidents declined significantly for the vehicles with the new crash parameter setting, i.e., the late-built MY 2008 vehicles and all MY 2009 vehicles. Honda reported the Accord 2-door model utilizes a different software/crash parameter than the subject 4-door model.

This Preliminary Evaluation has been upgraded to an Engineering Analysis (EA14-004) to determine, among other things, the risk of air bag deployment injuries to vehicle users in vulnerable positions.

The ODI reports cited above can be reviewed online at <http://www-odi.nhtsa.dot.gov/owners/SearchNHTSAID> under the following identification numbers: 10232206, 10235294, 10255323, 10268158, 10268191, 10269514, 10276755,

10279446, 10280675, 10308292, 10319979, 10342520, 10353536, 10408925, 10436506, 10447151, 10458732,  
10468196, 10468200, 10493407, 10494971, 10522291, 10524389, 10543092, 10544473, 10545258, 10547591,  
10554073, 10563629, 10565311, 10565423, 10576518, 10579241, 10584501, 10585442, 10606937, 10608973.