

PE14-032

HNDA

12-19-2014

Q8 REDACTED

QIS REDACTED

QSM REDACTED PAGE 20

ACTUAL PLACE VISIT
REPORT REDACTED PG 38

GQM REDQACTED PAGE 58

PE14-032

HNDA

12-19-2014


Q8 REDACTED

QIS_REDACTED

Q8-10 - TH2WE2011 060

Engine Cut - Engine Will Not

Idle_English_REDACTED



PE14-032

HNDA

12-19-2014


Q8 REDACTED

QIS_REDACTED

Q8-10 - TH2WE2011 060

Engine Cut - Engine Will not

Idle_Thai_REDACTED



0110
(
12

PE14-032

HNDA

12-19-2014


Q8 REDACTED

QIS_REDACTED

Q8-11 - TH2WE2011 085

Insufficient valve clearance
causes engine to cut out with
clutch

disengaged_English_REDACT
ED



PE14-032

HNDA

12-19-2014


Q8 REDACTED

QIS_REDACTED

Q8-11 - TH2WE2011 085

Insufficient valve clearance
causes engine to cut out with
clutch

disengaged_Thai_REDACTED



PE14-032

HNDA

12-19-2014

Q8 REDACTED

QIS_REDACTED

Q8-12 - TH2WE2012 047


Insufficient Valve Clearances

Caused Engine Stall While

Riding, After

Countermeasure_Thai_English_

REDACTED



PE14-032

HNDA

12-19-2014

Q8 REDACTED

QIS_REDACTED


Q8-13 - TH2WE2012 066

Ground bolt at regulatorrectifier

loose engine cuts out after

CM_Thai_English_REDACTE

D



PE14-032

HNDA

12-19-2014


Q8 REDACTED

QIS_REDACTED

Q8-14 - TH2WE2012 091

Engine stall While

Riding_English_REDACTED



PE14-032

HNDA

12-19-2014


Q8-14 - TH2WE2012 091

Engine Stalls While

Riding_Thai_REDACTED

V 12

(b) (5)



PE14-032

HNDA

12-19-2014

Q8 REDACTED

QIS_REDACTED


Q8-9 - TH2WE2011 034

Ground Bolt Crossthreaded

Engine

Cuts_Thai_English_REDACTE

D



PE14-032

HNDA

12-19-2014

Q8 REDACTED

Actual place visit

report_REDACTED

Q8-1 - Report CBR250R

Genba(US)

visit_English_REDACTED

CBR250R

Actual Place Visit Report

1.Purpose: Confirmation of claim at Genba

2.Location: USA (Connecticut or HRA-O depend on the situation)

3.Participant

①Mr. Kenji Kakuda (ASH A-QIC)

②Mr. Yoshiaki Nakajima (HRA-O)

③Mr. Jeremy Hoerning/ Masashi Yahata (AH-Service)

4.Confirmation Items

① Reproduce the Engine stall symptom




② ECU-data Logging and Record


③ Unit check

(Compression, valve timing, valve clearance, spark plug, plug cap, fuel pump, etc.)

5.Schedule (plan)

2012/03/13~2012/03/16

11 (Sun)	12 (Mon)	13 (Tue)	14 (Wed)	15 (Thur)	16 (Fri)
	 In	Check ed items ③ ①	Check items ① ②	Sum mtg. 	 Out




Visit to DLR
LIBBY'S MOTOWORLD
60 PRINTERSLN, NEW HAVEN, CT
06519-1812
TEL (203) 772-1112

▪ Tappet C/L




▪ Valve Timing was normal




▪ Plug Cap did not have any cracks or damage

▪ grounding wire condition was normal

▪ Result of Leak Test is



back and forth)





A running test was performed on the same road as the complaint. The outside temp. is about 58F~64F, with a distance of about 5.2miles up and downhill with traffic lights. The running test was performed with about 60 miles following the same steps as described in the allegation. The engine stall was not able to be recreated.



Test Place : Hardfolk
Test in front of the dealers
shop , clear, dry
Outside temp. 14°C~17°C

Not to able get the distance between the actual place and the customer's home, and because of the need to keep the engine cool, decided to perform a running test on a private road near the dealer.



Engine Stall – Not Found




Perform test with the same condition – 3 times.



◆The next direction to analysis (from now onward)

Team estimated the causes of engine stall to be from 2 reasons. However, the team can't judge if the cause of problem occurred from individual or several problems. After this, Thai Honda will analyze the cause of low compression pressure in the engine head. In addition to lower idle, it will be compared with the mass prod. of other models. A-QIC will be the one who requests HRS-T, HGA, MQID to analyze the cause of this problem

- Used motorcycle will be sent to Thai Honda



CBR250R (US) : Visiting an actual place Result : Customer feedback information

- Purchase date 23 Aug.
- 1st inspection at dealer on Sept. 27 and customer complained that the engine stalled



The result of 1st inspection → adjusted the tappet clearance (no data, but found stuck)
After adjustment, dealer did not verify the symptom

Oil replacement on 1st inspection ⇒ GN4 of 10W-40 (Genuine product of AH)

- 6 Oct. – User took MC to dealer
- 7 Oct. – Informed to dealer that engine stall happened again
⇒ Dealer did not check the tappet clearance
Dealer conducted simulation test, but the symptom did not reoccur.
- 7-12 Oct. – Customer took MC to DLR again, and confirmed with DLR that the symptom occurred only one time.
- 27 Oct. – Mr. Jeremy of AH-Service conducted the simulation running test with the customer information, but the symptom did not reoccur. The DLR request to customer to check the condition a little more
- 8 Nov. – Mr. Jeremy of AH-Service borrowed the affected vehicle for testing and conducted running test (cold start) 4 times, the symptom did not reoccur and the affected vehicle was not adjusted.
- Then customer took the affected vehicle to DLR and recorded a video and uploaded it to YouTube (Out side air temperature when taken the video is 40-50F (4.4-10°C)).

PE14-032

HNDA

12-19-2014

Q8 REDACTED

Actual place visit
report_REDACTED

Q8-1 - Report CBR250R

Genba(US)

visit_Japanese_REDACTED

CBR250R



1.Purpose: Confirmation of claimed unit at Genba

2.Location: USA (Connecticut or HRA-O depend on the situation)

3.Participant

①Mr. Kenji Kakuda (ASH A-QIC)

②Mr. Yoshiaki Nakajima (HRA-O)

③Mr. Jeremy Hoerning/ Masashi Yahata (AH-Sv.)

4.Confirmation Items

① Reproduce the Engine stall symptom




② ECU-data Logging and Record


③ Unit check

(Compression, valve timing, valve clearance, spark plug, plug cap, fuel pump, etc.)

5.Schedule (plan)

2012/03/13~2012/03/16




11 (Sun)	12 (Mon)	13 (Tue)	14 (Wed)	15 (Thur)	16 (Fri)
	 In	Check ed items ③ ①	Check items ① ②	Sum mtg. 	 Out



°C/°F






LIBBY'S MOTOWORLD
60 PRINTERSLN, NEW HAVEN, CT
06519-1812
TEL (203) 772-1112








[Redacted text block]









PE14-032

HNDA

12-19-2014

Q8 REDACTED

QSM_REDACTED

ENGLISH

JAPANESE PAGE 79

PE14-032

HNDA

12-19-2014

Q8 REDACTED

QSM_REDACTED

ENGLISH

Q8-15 - QSM 71th Report&

Minute Meeting



20111130_English_REDACTE

D

71st QSM progress report


71st QSM progress report

30 . Nov. 11

No	Theme	Detail	Future development	PIC	Due date
4	Engine stall NG Plug cap leak CBR250R TH Rank A Manufacturer : NGK 2CSO2011118 <Analysis request projects> 	<ul style="list-style-type: none"> ·Engine stall while riding, replace IG coil and Plug cap and then symptom disappear ·Occurred at TH, KOR, EU, JPN 10 items ·First analysis result is normally in size and material quality. ·Finished meeting with NGK(28/Jun) ·The root cause is coming from plug cap specification toughness shortages and TH assembly during oblique mounting, there is a countermeasure already. ·Test current receiving of Plug cap and no trouble found. ·Already issue TH QID (TH2WE2011 060) 	Countermeasure is revise specification and special follow up	A-QIC Kakuda	30/Nov. 

71st QSM progress report

71st QSM progress report



PE14-032

HNDA

12-19-2014

Q8 REDACTED

QSM_REDACTED

ENGLISH

Q8-16 - QSM 77th Report&

Minute Meeting

20120229_English_REDACTE

D

77th QSM progress report

29. Feb. 12


No	Theme	Detail	Future development	PIC	Due date
----	-------	--------	--------------------	-----	----------



77th QSM progress report

29. Feb. 12

No.	Theme	Detail	Future	PIC	Due date
-----	-------	--------	--------	-----	----------



77th QSM progress report

29. Feb. 12

No	Theme	Detail	Future	PIC	Due
----	-------	--------	--------	-----	-----




77th QSM progress report

29. Feb. 12



Future


Due




PAGE CONTAINS BUSINESS CONFIDENTIAL INFORMATION
77th QSM progress report

29. Feb. 12

No	Theme	Detail	Future development	PIC	Due date
10	Engine stall when riding KYJA CBR250R TH, Rank B M11THM054 (29/Nov/2011) 	<ul style="list-style-type: none"> · Occurred in USA market Engine stall when riding (MLHMC4117B5003360) · Adjusting tappet C/L within STD. but symptom not improve without known cause of problem · Information meeting with AH on 15/Feb 	<ul style="list-style-type: none"> · Buy back the affected vehicle · Identifying the root cause of a problem 	Kakuda	9/Mar 



77st QSM Minute note



10. Engine stall when riding CBR250R(KYJA)

- understanding of report
- Please quick preparation of plan and Identifying the root cause of a problem ASAP.

PE14-032

HNDA

12-19-2014

Q8 REDACTED

QSM_REDACTED

ENGLISH

Q8-17 - QSM 78th Report&

Minute Meeting

20120314_English_REDACTE

D

ENTIRE PAGE CONTAINS BUSINESS CONFIDENTIAL INFORMATION
78st QSM Progress Report

14. Mar. 12

No	Theme	Detail	Future development	PIC	Due date
----	-------	--------	--------------------	-----	----------

78st QSM Progress Report

14. Mar. 12

No	Theme	Detail	Future development	PIC	Due date
[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]
[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]
[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]

ENTIRE PAGE CONTAINS BUSINESS CONFIDENTIAL INFORMATION
78st QSM Progress Report

14. Mar. 12

No	Theme	Detail	Future development	PIC	Due
		<p>Meeting with PDI 20th Feb 2012 10th Rank A Water Museum India 20th Feb 2012 10:30-12:00 12th Mar 2012</p> <p>Meeting to follow up with PDI Collect PDI document</p>	<p>Meeting with PDI 21st Mar 2012</p>	<p>Kawato</p>	
	<p>Engine can't be started. Non working fuel pump STEP2 KAWATO Water 10 1st Rank B 24th Mar 2012 12 Mar 2012</p>	<p>While PDI found that engine is not working 120 cases found in Thailand Fuel Pressure Lower than standard 25MPa (100PSI)</p>	<p>Conclude the current situation 14-20 Mar Meeting with PDI 19-20 Mar</p>	<p>Kawato</p>	



ENTIRE PAGE CONTAINS BUSINESS CONFIDENTIAL INFORMATION
78st QSM Progress Report

14. Mar. 12

No	Theme	Detail	Future development	PIC	Due date
	<p>Eng Oil leak TMX155 FPL Rank B 2HP1201020 23 Aug 2011</p>	<p>In Philippines we found the problem of fuel leak from engine and the problem was solved by changing the fuel pump. In 2011, Change of fuel pump was approved.</p> <p>Case: HP Analysis results, the engine department and the Assembly had found the problem of fuel leak. The structure was approved from DMC.</p> <p>HP repeating results: Fuel: The other engine used 20000 litres. Consumption: Using the same amount of fuel, the engine in mass production.</p>			
	<p>FR Wheel damage KWP-SCV110 FMSI Rank A Maker: SCW 2HMS12012081-00-01 12 Feb 2012</p>	<p>Discussed in India. The front wheel was damaged during the test. Working situation: Working with the wheel for the test. Working with the test: Part found: SC Part and 2 other prepared wheel of making process and the only 1 wheel for the test. Part: Working with the working process of the test. Working with the test: Part found: SC Part</p>	<p>Check situation</p>	<p>Kanako</p>	<p>12 Feb 2012</p>

78st QSM Progress Report

14. Mar. 12

No	Theme	Detail	Future development	PIC	Due date
11	Engine Stall KYJA CBR250R TH, Rank B M11THM054 (29/Nov/2011) 	<ul style="list-style-type: none"> ·Occurred in USA market Engine stall when riding (MLHMC4117B5003360) Information Meeting with AH on 9 Mar. ·Analysis conduct at actual place(13~14 Mar.) ① The symptom not reoccurred ② Pug cap, ground bolt not found abnormality, TP/CL within STD. ③Compression : values less than STD base on OM 	<ul style="list-style-type: none"> ·Logging the data of ECU of the affected vehicle ·Identify Occurred mechanism 	Kakuda	28/Mar 

78st QSM Minute Note

14. Mar. 12

Attendance: Hosono AOP, HRST, Fukamachi OF, TH, NMC, Nishida NG, A-DIC, Tokita SM, Nakada Co, Kishida AGO, Mr. Prater, Mr. Uhen, Miss Fujita
Mr. Place, TH, NMC, QSM, etc.

1. Idle round speed up PCX(KWNA)

- Understand the report
- Please close QIS

2. Noise unusual tensionary lift can't operated CBR250R(KYJA)

- Understand the report

3. ECM Performance NG(Step4)Wave110 (KWWM) ON110B(KVBV)

- Understand the report
- Please monitor market situation
- PR development information of STEP4

4. The break PAD was easy to damaged (Fr. break) Air Blade(KVGS)

- Understand the report
- Review result of temporary countermeasure with HRST/NISSIN
- Informed countermeasure and Pad Brake usage to RVN service

5. Plated rust shift pedal damage meter crack defect AHL model (CD70, CG125)

- Understand the report
- Consider with AHL for QAY, TH will participate as well
- Mechanism has deterioration, please make countermeasure

6. Fuel Pump NG KYJA CBR250R

- Understand the report
- Check abnormality in production process of TH
- After sell this product to the market, please check for abnormality
- Please prevent production process of related part and pump that easy to understand

78st QSM Minute Note

14. Mar. 12

Attendance: Hosono AOP, HPS1, Fukamachi OF, TH-100, Yamaguchi MO, A-DIC, Takita DM, Nakada EO, Kaneko AOB
Mr. Present: Mr. Ueha, Miss Fujita

7. Final shaft damage KWP SOV110

Understand the report.

8. Eng. startup failure - fuel pump malfunction (STEP4) KWWM Wave110

Understand the report.

For fuel pump (Step4), please summarize the occurrence and analysis situation of Fuel Pump (Step4) STEP4, how to handle related parts, please coordinate with the WH, TH.

9. Eng. Oil leaks TMX155

Understand the report.

10. RR wheel damage KWP SOV110

Understand the report.

Monitor Market Continuously.

11.Engine stall KYJA CBR250R

Approval

12. Abnormal sound happen when start engine KWB AFP110

Understand the report.

13. Abnormal sound at muffler KYL Wave125

Understand the report.

When analysis result is issued, please report.

PE14-032

HNDA

12-19-2014

Q8 REDACTED

QSM_REDACTED

ENGLISH

Q8-18 - QSM 79th Report&

Minute Meeting

20120418_English_REDACTE

D

79st QSM Progress Report

18. Apr. 12

No	Theme	Detail	Future development	PIC	Due date
[Redacted content]					

79st QSM Progress Report


18. Apr. 12

No	Theme	Detail	Future development	PIC	Due date
----	-------	--------	--------------------	-----	----------

79st QSM Progress Report



18. Apr. 12

No	Theme	Detail	Future	PIC	Due
----	-------	--------	--------	-----	-----



79st QSM Progress Report


18. Apr. 12

No	Theme	Detail	Future development	PIC	Due date
7	Engine Stall when riding KYJA CBR250R TH, RankB M11THM054 (29/Nov/2011) 	Occurred in USA market Engine stall when riding (MLHMC4117B5003360) ・Analysis conduct at actual place(13~14 Mar.) ① The symptom not reoccurred ② Pug cap, ground bolt not found abnormality , TP/CL within STD. ③Compression : values less than STD base on OM ・Wait for the affected vehicle occurred in USA market ・Under investigation the affected vehicle that occurred in KOR market ・MQAD and AQSC already info. Meeting on 6/Apr.	・Identify Occurred mechanism	Kakuda	30/Apr. 

79st QSM Progress Report

18. Apr. 12

No	Theme	Detail	Future development	PIC	Due date
----	-------	--------	--------------------	-----	----------




79st QSM Progress Report

18. Apr. 12

No	Theme	Detail	Future development	PIC	Due date
----	-------	--------	--------------------	-----	----------

79st QSM Minute Note

18. Apr. 12



7. Engine Stall when riding CBR250R(KYJA)

- All understanding of report
- Please summary occurrence situation soon
- Please judgment of necessity by team for sold out of vehicle

PE14-032

HNDA

12-19-2014

Q8 REDACTED

QSM_REDACTED

ENGLISH

Q8-19 - QSM 80th Report&

Minute Meeting


20120425_English_REDACTE

D

80th QSM Progress Report

25. Apr. 12


No	Theme	Detail	Future development	PIC	Due date
----	-------	--------	--------------------	-----	----------





80th QSM Progress Report

25. Apr. 12

No	推進テーマ	内容	今後の展開	担当	完了 予定日
----	-------	----	-------	----	-----------




80th QSM Progress Report

No	Theme	Detail	Future development	PIC	Due date
7	Engine stall when riding KYJA CBR250R TH, RankB M11THM054 (29/Nov/2011) 	Occurred in USA market Engine stall when riding (MLHMC4117B5003360) ・Analysis conduct at actual place(13~14 Mar.) ① The symptom not reoccurred ② Pug cap, ground bolt not found abnormality , TP/CL within STD. ③ Compression : values less than STD base on OM ・Under investigation the affected vehicle that occurred in KOR market ・MQAD and AQSC already info. Meeting on 6/Apr. ・Under shipment the affected vehicle that occurred in USA to JPN (23/Apr. ~) ・Under investigation the affected vehicle occurred USA	・Identify Occurred mechanism	Kakuda	30/Apr. 

80th QSM Progress Report

25. Apr. 12


No	Theme	Detail	Future development	PIC	Due date
----	-------	--------	--------------------	-----	----------



80th QSM Progress Report


25. Apr. 12

No	Theme	Detail	Future development	PIC	Due date
----	-------	--------	--------------------	-----	----------



80th QSM Minute Note

25. Apr. 12



80th QSM Minute Note

25. Apr. 12

7. Engine stall when riding CBR250R(KYJA)

- All understanding of report
- Please summary occurrence situation soon
- Please judgment of necessity by team for sold out of vehicle

PE14-032

HNDA

12-19-2014

Q8 REDACTED

QSM_REDACTED

ENGLISH

Q8-20 - QSM 81th Report&

Minute Meeting


20120509_English_REDACTE

D

81th QSM Progress Report

9. May. 12


No	Theme	Detail	Future development	PIC	Due date
----	-------	--------	--------------------	-----	----------



81th QSM Progress Report



9. May. 12

No	Theme	Detail	Future development	PIC	Due date
----	-------	--------	--------------------	-----	----------



81th QSM Progress Report


9. May. 12

No	Theme	Detail	Future development	PIC	Due date
7	<p>Engine stall when riding KYJA CBR250R TH, Rank B M11THM054 (29/Nov/2011)</p> 	<p>Occurred in USA market Engine stall when riding (MLHMC4117B5003360)</p> <ul style="list-style-type: none"> ·Analysis conduct at actual place(13~14 Mar.) ① The symptom not reoccurred ② Pug cap, ground bolt not found abnormality , TP/CL within STD. ③Compression : values less than STD base on OM <ul style="list-style-type: none"> ·Under investigation the affected vehicle that occurred in KOR market ·MQAD and AQSC already info. Meeting on 6/Apr. ·Under investigation the affected vehicle occurred in USA to JPN (23/Apr.~) 	<ul style="list-style-type: none"> ·Identify Occurred mechanism 	Kakuda	<p>30/May.</p> 

81th QSM Progress Report

9. May. 12


No	Theme	Detail	Future development	PIC	Due date
----	-------	--------	--------------------	-----	----------



81th QSM Progress Report

9. May. 12


No	Theme	Detail	Future development	PIC	Due date
----	-------	--------	--------------------	-----	----------



81th QSM Progress Report


9. May. 12

No	Theme	Detail	Future development	PIC	Due date
----	-------	--------	--------------------	-----	----------




81st QSM Minute Note

9. May. 12




7. Engine Stall when riding CBR250R(KYJA)

- All understanding of report



81st QSM Minute Note

9. May. 12



PE14-032

HNDA

12-19-2014

Q8 REDACTED

QSM_REDACTED

ENGLISH

Q8-21 - QSM 82th Report&

Minute Meeting


20120523_English_REDACTE

D

82th QSM Progress Report

23. May. 12


No	Theme	Detail	Future development	PIC	Due date
----	-------	--------	--------------------	-----	----------



82th QSM Progress Report



23. May. 12


No	Theme	Detail	Future development	PIC	Due date
----	-------	--------	--------------------	-----	----------



PAGE CONTAINS CONFIDENTIAL BUSINESS INFORMATION
82th QSM Progress Report

23. May. 12


No	Theme	Detail	Future development	PIC	Due date
7	Engine stall when riding KYJA CBR250R TH, Rank B M11THM054 (29/Nov/2011) 	<ul style="list-style-type: none"> · Occurred in USA market Engine stall when riding (MLHMC4117B5003360) · Analysis conduct at actual place(13~14 Mar.) ① The symptom not reoccurred ② Pug cap, ground bolt not found abnormality , TP/CL within STD. ③ Compression : values less than STD base on OM · Under investigation the affected vehicle that occurred in KOR market · MQAD and AQSC already info. meeting on 6/Apr. · Under shipment the affected vehicle that occurred in USA to JPN (23/Apr.~) 	<ul style="list-style-type: none"> · Identify Occurred mechanism 	Kakuda	30/May. 



ENTIRE PAGE CONTAINS CONFIDENTIAL BUSINESS INFORMATION
82th QSM Progress Report

23. May. 12


No	Theme	Detail	Future development	PIC	Due date
----	-------	--------	--------------------	-----	----------



ENTIRE PAGE CONTAINS CONFIDENTIAL BUSINESS INFORMATION
82th QSM Progress Report

23. May. 12


No	Theme	Detail	Future development	PIC	Due date
----	-------	--------	--------------------	-----	----------



ENTIRE PAGE CONTAINS CONFIDENTIAL BUSINESS INFORMATION
82th QSM Progress Report


23. May. 12

No	Theme	Detail	Future development	PIC	Due date
----	-------	--------	--------------------	-----	----------



7. Engine Stall when riding CBR250R(KYJA)

- Understanding of report
- Please summary the final report soon



PE14-032

HNDA

12-19-2014

Q8 REDACTED

QSM_REDACTED

ENGLISH

Q8-22 - QSM 83th Report&

Minute Meeting


20120620_English_REDACTE

D

83rd QSM Progress Report

20. Jun. 12


No	Theme	Detail	Future development	PIC	Due date
----	-------	--------	--------------------	-----	----------



--	--	--	--	--	--

83rd QSM Progress Report

20. Jun. 12


No	Theme	Detail	Future development	PIC	Due date
5	<p>Engine stall when riding CBR250R(KYJA) TH, Rank B M11THM054 (29/Nov/2011)</p> <p style="color: blue; text-decoration: underline;"><Analysis request issue</p> 	<p>Occurred in USA market Engine stall when riding (MLHMC4117B5003360)</p> <p>·Analysis conduct at actual place(13~14 Mar.)</p> <p>① The symptom not reoccurred ② Pug cap, ground bolt not found abnormality , TP/CL within STD. ③Compression : values less than STD base on OM Asia & Oceania information exchange Mtg.on19Jun. Cause of symptom is FI program</p>	<ul style="list-style-type: none"> •C/M , changing FI Program with KZZ •Theme up to GQM Meeting 	Kakuda	30/Jul.



83rd QSM Progress Report

20. Jun. 12


No	Theme	Detail	Future development	PIC	Due date
----	-------	--------	--------------------	-----	----------



83rd QSM Progress Report

20. Jun. 12


No	Theme	Detail	Future development	PIC	Due
----	-------	--------	--------------------	-----	-----



83rd QSM Progress Report

20. Jun. 12

No	Theme	Detail	Future development	PIC	Due
----	-------	--------	--------------------	-----	-----




--	--	--	--	--	--

83rd QSM Progress Report

20. Jun. 12


No	Theme	Detail	Future development	PIC	Due
----	-------	--------	--------------------	-----	-----



83rd QSM Progress Report

20. Jun. 12

No	Theme	Detail	Future	PIC	Due
----	-------	--------	--------	-----	-----



83st QSM Progress Minute Note


20.June. 12

5. Engine Stall when riding CBR250R(KYJA)

- All understanding of report
- Please closely contact with JPN side


83st QSM Progress Minute Note

20. June. 12



83st QSM Progress Minute Note

20. June. 12



PE14-032

HNDA

12-19-2014

Q8 REDACTED

QSM_REDACTED

ENGLISH

Q8-23 - QSM 84th Report&

Minute Meeting

20120627_English_REDACTE

D



84st QSM Progress Report

27.Jun. 12

No	Theme	Detail	Future development	PIC	Due date
----	-------	--------	--------------------	-----	----------

84st QSM Progress Report


27.Jun. 12

No	Theme	Detail	Future development	PIC	Due date
4	<p>Engine stall when riding CBR250R(KYJA) TH, Rank B M11THM054 (29/Nov/2011)</p> <p><Analysis request issue></p> 	<p>·Occurred in USA market Engine stall when riding (MLHMC4117B5003360) ·Analysis conduct at actual place(13~14 Mar.) ① The symptom not reoccurred ② Pug cap, ground bolt not found abnormality , TP/CL within STD. ③Compression : values less than STD base on OM ·ATAI Information Exchange Meeting on19Jun, The symptom caused by FI Program ·GQM_Q on 26Jun.)</p>	<p>·C/M , changing FI Program with KZZ</p>	<p>Kakuda</p> <p>elapsed days</p>	<p>30/Jun</p>  <p>210</p>

84st QSM Progress Report

27.Jun. 12

No	Theme	Detail	Future development	PIC	Due date
----	-------	--------	--------------------	-----	----------



84st QSM Progress Report

27.Jun. 12


No	Theme	Detail	Future development	PIC	Due date
----	-------	--------	--------------------	-----	----------

--	--	--	--	--	--

84st QSM Progress Report

27.Jun. 12


No	Theme	Detail	Future development	PIC	Due date
----	-------	--------	--------------------	-----	----------



4. Engine stall when riding CBR250R(KYJA)

- Understanding of report
- Please report with GQM meeting by TV

84st QSM Minute note



PE14-032

HNDA

12-19-2014

Q8 REDACTED

QSM_REDACTED

JAPANESE

Q8-15 - QSM 71th Report&

Minute Meeting

20111130_Japanese_REDACT
ED

[REDACTED]

No	[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]
----	------------	------------	------------	------------	------------

[REDACTED]







No	[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]
----	------------	------------	------------	------------	------------

7	[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]
---	------------	------------	------------	------------	------------




No					
----	--	--	--	--	--






4. 







PE14-032

HNDA

12-19-2014

Q8 REDACTED

QSM_REDACTED

JAPANESE

Q8-16 - QSM 77th Report&

Minute Meeting

20120229_Japanese_REDACT
ED


No	[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]
----	------------	------------	------------	------------	------------

[REDACTED]



No.										
-----	--	--	--	--	--	--	--	--	--	--


A large, solid black rectangular redaction box covering the majority of the page's content. On the left side of this redacted area, there are several white L-shaped brackets indicating a list or table structure. A small white number '7' is visible on the left edge of the redacted area, approximately halfway down the page.




No					
----	--	--	--	--	--





7





No	[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]
----	------------	------------	------------	------------	------------



7





[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

PE14-032

HNDA

12-19-2014

Q8 REDACTED

QSM_REDACTED

JAPANESE

Q8-17 - QSM 78th Report&

Minute Meeting

20120314_Japanese_REDACT
ED

[REDACTED]

[REDACTED]

[REDACTED]


[REDACTED]

[REDACTED]

[REDACTED]

14. [REDACTED] 21

No



[REDACTED]

[REDACTED]

No	[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]
----	------------	------------	------------	------------	------------

[REDACTED]

7


[REDACTED]

No	[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]
----	------------	------------	------------	------------	------------



[REDACTED]







No					
----	--	--	--	--	--



7







PE14-032

HNDA

12-19-2014

Q8 REDACTED

QSM_REDACTED

JAPANESE

Q8-Q8-18 - QSM 79th Report &
Minute Meeting

20120418_Japanese_REDACT
ED

[REDACTED]

No	[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]
----	------------	------------	------------	------------	------------

[REDACTED]

7



[REDACTED]


18. Apr. 12




No	[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]
----	------------	------------	------------	------------	------------

[REDACTED]

7







PE14-032

HNDA

12-19-2014


Q8 REDACTED

QSM_REDACTED

JAPANESE



Q8-19 - QSM 80th Report &
Minute Meeting



20120425_Japanese_REDACT
ED



ENTIRE PAGE CONT

ESS INFORMATION





PE14-032

HNDA

12-19-2014

Q8 REDACTED

QSM_REDACTED


JAPANESE


Q8-20 - QSM 81th Report&


Minute Meeting


20120509_Japanese_REDACT
ED


















- 7. [REDACTED]
[REDACTED]





PE14-032

HNDA

12-19-2014

Q8 REDACTED

QSM_REDACTED

JAPANESE


Q8-21 - QSM 82th Report&


Minute Meeting


20120523_Japanese_REDACT
ED

ENTIRE PAGE CONTAINS CONFIDENTIAL BUSINESS INFORMATION




















PE14-032

HNDA

12-19-2014

Q8 REDACTED

QSM_REDACTED


JAPANESE

Q8-22 - QSM 83th Report&

Minute Meeting


20120620_Japanese_REDACT
ED

ENTIRE PAGE CONTAINS CONFIDENTIAL BUSINESS INFORMATION




ENTIRE PAGE CONTAINS CONFIDENTIAL BUSINESS INFORMATION









ENTIRE PAGE CONTAINS CONFIDENTIAL BUSINESS INFORMATION



ENTIRE PAGE CONTAINS CONFIDENTIAL BUSINESS INFORMATION





ENTIRE PAGE CONTAINS



FORMATION

20. June. 12

[REDACTED]

[REDACTED]

[REDACTED]

PE14-032

HNDA

12-19-2014

Q8 REDACTED

QSM_REDACTED


JAPANESE

Q8-23 - QSM 84th Report&

Minute Meeting

20120627_Japanese_REDACT
ED







(b) (5) - ACP, (b) (5) - DPP

	(b) (5) - ACP, (b) (5) - DPP				
--	------------------------------	--	--	--	--

ENTIRE PAGE CONTAINS CONFIDENTIAL BUSINESS INFORMATION




ENTIRE PAGE CONTAINS CONFIDENTIAL BUSINESS INFORMATION

[REDACTED]

[REDACTED]

[REDACTED]



PE14-032

HNDA

12-19-2014

Q8 REDACTED

GQM_REDACTED

ENGLISH

JAPANESE PAGE 115

PE14-032

HNDA


12-19-2014

Q8 REDACTED

GQM_REDACTED

Q8-2 - 516th GQM

report_English_REDACTED



<Contents>

- 1. Previous Pointing out
- 2. Complained of ev
- 3. Number of occur
- 4. Analysis result
- 5. Countermeasures
- 6. Proposal
- 7. Deployment schedule



QIS:TH2WE2011085

2012.6.26
516th GQM QP,Q1 Report

2、3 Complained of events & Number of occurrences

Vehicle		CBR250R MC41 XXXXXXXXXX
Occurrence Situation Summary		Problem is happening intermittently, will occur within 10 minutes after the engine is started. At a reduced speed and happens only when you are off the clutch. Number of revolutions that have cut the clutch is low 3000r / m, is high and 8000r / m.
QIC		QIC:M11THM 054-00 <small>QIC Form Identification: M11THM 054-00 Date: 1.1.11</small>
Occ. No.		USA:1、Korea:1
Unit Sales		USA:7187、Korea:335 Whole of the World;27,670(28countries)
Occurrence ratio		USA:0.01%、Korea:0.30% Whole of the World:0.01%
Mileage		USA:425mile(684km)、Korea:546km

4. Analysis Result

Specification of Problem Vehicle

		CBR250R (MC41 [REDACTED])															
		SPEC	L	R													
Tp,Cl (mm)	IN	0.16±0.03	0.18	0.18													
	EX	0.27±0.03	0.26	0.26													
Valve Timing		<table border="1"> <tr> <td>IN</td> <td>20</td> <td>0</td> <td>EX</td> </tr> <tr> <td>(8.60)</td> <td>35</td> <td>40</td> <td>(8.30)</td> </tr> </table>	IN	20	0	EX	(8.60)	35	40	(8.30)	<table border="1"> <tr> <td>21.5</td> <td>3</td> </tr> <tr> <td>(8.45)</td> <td>30.5</td> </tr> <tr> <td>40</td> <td>(8.14)</td> </tr> </table>	21.5	3	(8.45)	30.5	40	(8.14)
IN	20	0	EX														
(8.60)	35	40	(8.30)														
21.5	3																
(8.45)	30.5																
40	(8.14)																
Compression Ratio		10.7±0.2	10.63														
COMP (kPa)		1300	1294														
IDLE Speed(r/min)		1400±100	1400														
IDLE PB(kPa)/Gair(g/sec)		Less than 72kpa /0.90	69.1/0.91														
ENG OIL Volume		Upper level(1.8L)															
Plug Cap		Nothing abnormal															
Plug condition																	
Connecting Earth																	



There is a slight shift of Valve Timing in CBR250R, but Vehicle abnormality can not be seen without the items in problem both [REDACTED] and CBR250R.

4. Analysis Result

Problem Vehicle (Reproduction, Engine Stall Temp. Range)

CBR250R (MC41

TW:23~85°C
 Gear Position : 6th
 Clutch disengage
 at 70~90km/h
 (7,000r/min)
 Temperature: 10°C
 0.5sec/div




	T.Water : less than 40°C, T.Oil : less than 25°C	T.Water : 40~82°C, T. Oil : 25~60°C	T.Water : Over 85°C, T.Oil : Over 60°C
Eng Stall	No	Yes	No
A/F	10.5	unkown (may be less than 10.5)	13


CBR Engine Stall occurs both at the same time the clutch disengage to coasting with the throttle fully closed from the Engine high speed range.

- The idling Speed drops below 1450r / min in the warm-up process, A/F becomes rich, occur engine Speed drop and engine stall.
- Engine stall has occurred in the Range in the middle of completion of the warm-up of the Oil Temperature 25 ~ 60 °C.

4. Analysis Result



4. Analysis Result



4. Analysis Result

Occurrence Mechanism

Poor Rich A/F toughness of Low Speed/Load range

① Simultaneous operation Throttle Off / Disengage Clutch at High Speed/Load Range



② Correction control amount Shortage

③ High Friction At Low Oil Temperature

④ Engine Speed goes down under 1,000 r/min

⑤ Worsening Combustion by Over Rich (A/F less than 10.5)

Coasting Engine Stall



7. Schedule

Item	Responsible	Schedule	
		June	July
GQM Promotion Plan	QAD	26 ▽ Q-planning/Q1	9 16 ▽ ▽ Q2 Q-End
Reproduction Test	QAD	▼ ▼ 11 15	
Cause investigation	HGA QAD	CBR US Buy-Back	Analysis
Countermeasure		▼ ▼	▼ ▼
Effect confirmation		▽ ▽	▽ ▽
Negative confirmation		▽ ▽	▽ ▽
Occurrence prediction	Service QAD		▽ ▽
Final event			▽ ▽
Market corresponding			▽ ▽

END

PE14-032

HNDA


12-19-2014

Q8 REDACTED

GQM_REDACTED

Q8-3 - 518th GQM

report_English_REDACTED



<Contents>

- 1. Previous Pointi
- 2. Complained of
- 3. Number of occu
- 4. Analysis result
- 5. Countermeasures
- 6. Proposal
- 7. Deployment schedule



QIS:TH2WE2011085


2012.7.9
518thGQM
Q1-1st Report

1. Previous pointed out

<Previous GQM Q-Planning> (2012.6.26)

Pointed Out Item	Correspondence
<ul style="list-style-type: none">▪ Scrutinize the situation of occurrence number.▪ Review occurrence mechanism.	<p>⇒P 3</p> <p>⇒P 8</p>

2、3 Complained of events & Number of occurrences

Vehicle	[REDACTED]			CBR250R MC41	[REDACTED]	
Occurrence Situation Summary	[REDACTED]			Problem is happening intermittently, will occur within 10 minutes after the engine is started. At a reduced speed and happens only when you are off the clutch. Number of revolutions that have cut the clutch is low 3000r / m, is high and 8000r / m.		
QIC	[REDACTED]			QIC:M11THM 054-00、M12THM 009-00 		
Occ. Country	[REDACTED]			USA	KOREA	Whole World
Occ. / TTL Sales	[REDACTED]			2 /7187	9/335	27,670
Occurrence Ratio	[REDACTED]			0.03%	2.7%	0.04%
Mileage (km)	[REDACTED]			USA:425mile(684)、882、KOREA:546		

4. Analysis Result

Specification of Problem Vehicle



		CBR250R (MC41																			
		SPEC	L	R																	
Tp,Cl (mm)	IN	0.16±0.03	0.18	0.18																	
	EX	0.27±0.03	0.26	0.26																	
Valve Timing		<table border="1"> <tr> <td>IN</td> <td>20</td> <td>0</td> <td>EX</td> </tr> <tr> <td></td> <td>35</td> <td>40</td> <td></td> </tr> <tr> <td></td> <td>(8.60)</td> <td>(8.30)</td> <td></td> </tr> </table>	IN	20	0	EX		35	40			(8.60)	(8.30)		<table border="1"> <tr> <td>21.5</td> <td>3</td> </tr> <tr> <td>30.5</td> <td>40</td> </tr> <tr> <td>(8.45)</td> <td>(8.14)</td> </tr> </table>	21.5	3	30.5	40	(8.45)	(8.14)
IN	20	0	EX																		
	35	40																			
	(8.60)	(8.30)																			
21.5	3																				
30.5	40																				
(8.45)	(8.14)																				
Compression Ratio		10.7±0.2	10.63																		
COMP (kPa)		1300	1294																		
IDLE Speed(r/min)		1400±100	1400																		
IDLE PB(kPa)/Gair(g/sec)		Less than 72kpa/0.90	69.1/0.91																		
ENG OIL Volume		Upper (1.8L)																			
Plug Cap		Nothing abnormal																			
Plug condition																					
Connecting Ground																					

There is a slight shift of Valve Timing both [redacted] and CBR250R. Vehicle abnormality can not be seen without the items in problem both [redacted] and CBR250R.

4. Analysis Result Problem Vehicle (Reproduction, Engine Stall Temp. Range) 5/10

CBR250R (MC41)

TW:23~85°C
 Gear Position : 6th
 Speed : Clutch disengage at 70~90km/h (7,000r/min)
 Temperature : 10°C
 0.5sec/div




	T.Water: less than 40°C, T.Oil: less than 25°C	T.Water: 40~82°C, T. Oil: 25~60°C	T.Water: Over 85°C, T.Oil: Over 60°C
Eng Stall	No	Yes	No
A/F	10.5	unkown (may be less than 10.5)	13

- Engine Stall occurs at the same time the clutch disengage to coasting with the throttle fully closed from the Engine high speed range.
- No occurrence of engine stall in a state the clutch engage.
- Restart after engine stall is easy.
- The idling Speed drops below 1450r / min in the warm-up process, A/F becomes rich, occur engine Speed drop and engine stall.
- Engine stall has occurred in the middle of completion of the warm-up of in the Range the Oil Temperature 25 ~ 60 °C.

4. Analysis Result

CBR250R Eng. Parts replace, Tightening Torque change 6/10
(Chassis)




CBR250R Replace; Cylinder·Piston·Head·Cam shaft Result (Test Vehicle: US Buy Back)

No	Head	Cam Shaft	Cylinder	Piston	←Other	Eng. Speed Drop	Eng. Stall	A/F	NOTES
①	M/P	←	←	←	M/P	7/10	3/10	11.3	Eng. Stall
②	T/P	←	←	←	Develop	3/10	0/10	11.8	Not Eng. Stall
③	T/P	←	←	←	M/P	4/10	0/10	11.7	Not Eng. Stall after replace Head, Camshaft, Cylinder, Piston
④	T/P	←	M/P	←	M/P	5/10	0/10	11.3	No effect Cylinder and Piston⇒Head & Camshaft Effect
⑤	M/P	T/P	M/P	←	M/P	7/10	2/10	11.3	Head Effect

CBR250R Tightening Torque change Result (Head, Camshaft, Cylinder, Piston⇒M/P)

No	Head Tightening Torque (51N·m±3N·m)	Eng. Speed Drop	Eng. Stall	A/F	Results and Notes
①	60.5	7/10	3/10	11.3	Eng. Stall
⑦	40	9/10	0/10	11.3	Do not stall Lowering the tightening torque
⑧	51	8/10	1/10	11.3	To stall If you increase the tightening torque



• Engine Speed Drop and Engine Stall level changes by tightening torque of the cylinder head. Head Distortion can be considered as a probable cause.



4. Analysis Result

Ability confirmation of valve seating failure

1. Head leakage quantity measurement

CBR250R Development (sand mold)							
Only HEAD		steady flow jig		トルク: 51N.m		ENG Assy(51N.m)	
kPa	c,3/min	kPa	c,3/min	kPa	c,3/min	kPa	c,3/min
11.78	254	10.52	206			7.13	74
20.01	436	19.99	395			10.89	129
50.03	1128	50.01	1025			20.03	237

CBR250R US Buy Back (M/P)							
Only HEAD		steady flow jig		トルク: 51N.m		ENG Assy(51N.m)	
kPa	c,3/min	kPa	c,3/min	kPa	c,3/min	kPa	c,3/min
10.51	4	10.99	24	7.39	90	7.94	175
20.86	9	21.02	53	10.26	114	10.86	231
50.24	21	50.04	139	20.11	236	20.09	434

▪ Development (sand mold) head is bad alone leakage quantity, leakage quantity is reduced by tightening.

▪ US Buy Back and Fukui vehicles (M/P) head leak amount is increasing by tightening.

Head leak amount difference need further analysis.


- Head stiffness
- The initial distortion
- Ground-effect of valve etc.

Only Head

▪ leakage quantity measurement of mounting the steady flow jig.

▪ leakage quantity measurement of ENG Assy.


ENG Assy




4. Analysis Result

FTA

· Before Warm-up complete
· Clutch disengage
Engine Stall in Coasting





7. Schedule

Item	Responsible	Schedule			
		June	July		
GQM Promotion Plan	QAD	26 ▼ Q-Planning/Q1	9 ▽ Q2	16 ▽ Q-End	
GQM Amendment		26 ▼ Q-Planning	9 ▽ Q1-1st	16 ▽ Q1-2nd	30 ▽ Q1~Q-End
Reproduction Test	QAD	11 ▼	15 ▼		
Cause investigation (HEAD distortion)	HGA QAD	Comparison of CBR US Buy Back Eng. and Development Eng.			
Countermeasure		▼		▽	
Effect confirmation		▼		▽	
Negative confirmation		▼		▽	
Occurrence prediction	Service QAD			▽	▽
Final event				▽	▽
Market corresponding				▽	▽

Countermeasure / Direction
 • HEAD distortion

END

PE14-032

HNDA


12-19-2014

Q8 REDACTED

GQM_REDACTED

Q8-4 - 519th GQM

report_English_REDACTED



QIC.NO



<Contents>

- 1. Previous Point
- 2. Complained of
- 3. Number of occ
- 4. Analysis result
- 5. Countermeasures
- 6. Proposal
- 7. Deployment schedule



QIC.NO : M11THM 054-00
 M12THM 009-00
 2HKO2012001-00

2012.7.16
 519thGQM
 Q1-2nd Report

1. Previous pointed out

<Previous GQM Q1-1st> (2012.7.9)

Pointed Out Item	Correspondence
1. Also confirm the occurrence from the customer phase information and Tech line information, scrutinize occurrence number / incidence.	⇒P 3~6
2. Summarized to organize it as the difference between CBR and [REDACTED] is seen in the analysis and Occurrence mechanism.	⇒Review Implementation of materials
3. Although the full extent of the cause has not been elucidated, because to respond to urgent market need, next time, show the proposed countermeasures.	⇒P 10

2、3 Complained of events &
Number of occurrences




2、3 Complained of events & Number of occurrences

CBR250R QIC, Wty, TL,CR Scrutiny

Item	Unit of Occured	QIC Number
Engine Stall	11	3
Grand Failure	3	2
Noise Cap Broken	11	11
Valve Clearance Failure	59	22
After Valve Clearance Adjust	2	2
Others	16	16
Grand Total	102	56

What led to the stall for reasons other than Grand Failure, Noise Cap Broken, Valve Clearance Failure is 11 units / QIC 3 items.



After 3 items Countermeasure, 1 unit occurred Eng. Stall in Japan.

There are 5 units of GQM Eng. Stall complained appeared in the USA CR 177 items and TL 66 items .

Date	YM	CR	TL	QIC	Model	Mile	Complaint
2012/5/21	2011	○			CBR250R	2000	After Eng. Warm Up 1 to 2 minutes, disengage clutch and Shift Down Gear, Stall occurred.
2012/7/6	2012	○			CBR250RA	?	Shift Gear into 1st then Eng. Stall, Eng. Speed was 1000 or 1100 r/min.
2012/4/30	2011		○		CBR250R	2800	When Stop the motorcycle with disengage clutch, Stall occurred.
2012/3/7	2011		○	M11THM054-00	CBR250R	450	Buy Back
2012/4/19	2011		○		CBR250R	7785	After 5 to 15minutes running. When Eng. during cold. 3 times Stall occurred. Restart possible.
2012/5/22	2012		○		CBR250R	572	Stall occurred during warm up. Restart possible. After Warm Up is no problem. Ignition is good.

2、3 Complained of events & Number of occurrences

CBR250R Internet Investigation (USA)

Google™ Custom Search Search

Page 1 of 15 1 2 3 11 > Last

Threads in Forum : CBR250 Problems and Issues Forum Tools Search this Forum

Thread / Thread Starter	Rating	Last Post	Replies	Views
My CBR250's engine turns off when Downshifting!!! (1 2 3 ... Last Page) CBR250newOWNER	★★★★★	Today 09:13 AM by cbrku	665	42,106
Unforced Stalling (1 2 3 ... Last Page) CBRNewbie		Today 12:59 PM by rrages	36	3,036
Cold Stall on first start...Help! (1 2 3) Mike323		Yesterday 05:14 PM by TX_Di	25	679
Engine shuts off on first start (1 2 3 ... Last Page) cbrlocal		07-08-2012 05:14 AM by Wynne G Oldman	45	1,988
stalling on cold start up (1 2) mrfunktastic		05-30-2012 02:34 PM by prittner	11	533
Engine stall on cold/first start rich3389		05-26-2012 06:17 PM by cbrlocal	9	321
Engine shuts off when idling after restart. (2012 CBR250R) Rusty Shackelford		05-04-2012 06:58 AM by Streetsville CBR_Guy	9	496
Sometimes: engine stalls when downshifting to 1 while holding clutch (1 2 3 ... Last Page) p4i1		04-09-2012 07:49 PM by jasinner	73	7,463

2、3 Complained of events & Number of occurrences

Vehicle		CBR250R MC41
Occurrence Situation Summary		Problem is happening intermittently, will occur within 10 minutes after the engine is started. At a reduced speed and happens only when you are off the clutch. Number of revolutions that have cut the clutch is low 3000r / m, is high and 8000r / m.
QIC		M11THM 054-00 M12THM 009-00 2HKO2012001-00

Country		Japan	USA	Korea	Whole World
Occ. No./ Eng. Stall Complaint [Unit]	QIC	0 / 20	2 / 34	9 / 18	11 / 102
	Wty.	1 / 195	0 / 16	9 / 25	10 / 313
	TL	0 / 198	4 / 177	—	4 / 400
	CR	0 / 17	2 / 66	—	2 / 85
Occ. No.[Unit]		1	7	9	17
Sales Units (end of June) [Unit]		6,917	8,459	335	30,777
Occurrence Ratio[%]		0.01	0.08	2.69	0.06

4. Analysis Result

Specification of Problem Vehicle

No Change Previous Report

		CBR250R (MC41 [REDACTED])																									
		SPEC	L R																								
Tp,Cl (mm)	IN	0.16±0.03	0.18 0.18																								
	EX	0.27±0.03	0.26 0.26																								
Valve Timing		<table border="1"> <tr> <td>IN</td> <td>20</td> <td>0</td> <td>EX</td> </tr> <tr> <td colspan="2">_____</td> <td colspan="2">_____</td> </tr> <tr> <td>(8.60)</td> <td>35</td> <td>40</td> <td>(8.30)</td> </tr> </table>	IN	20	0	EX	_____		_____		(8.60)	35	40	(8.30)	<table border="1"> <tr> <td>IN</td> <td>21.5</td> <td>3</td> <td>EX</td> </tr> <tr> <td colspan="2">_____</td> <td colspan="2">_____</td> </tr> <tr> <td>(8.45)</td> <td>30.5</td> <td>40</td> <td>(8.14)</td> </tr> </table>	IN	21.5	3	EX	_____		_____		(8.45)	30.5	40	(8.14)
IN	20	0	EX																								
_____		_____																									
(8.60)	35	40	(8.30)																								
IN	21.5	3	EX																								
_____		_____																									
(8.45)	30.5	40	(8.14)																								
Compression Ratio		10.7±0.2	10.63																								
COMP (kPa)		1300	1294																								
IDLE Speed(r/min)		1400±100	1400																								
IDLE PB(kPa)/Gair(g/sec)		Less than 72kpa/0.90	69.1/0.91																								
ENG OIL Volume		Upper (1.8L)																									
Plug Cap		Nothing abnormal																									
Plug condition																											
Connecting Ground																											

There is a slight shift of Valve Timing both [REDACTED] and CBR250R.

Vehicle abnormality can not be seen without the items in problem both [REDACTED] and CBR250R.

4. Analysis Result


Problem Vehicle (Reproduction, Engine Stall Temp. Range)

CBR250R (MC41 [REDACTED])

23~85°C

100km/h/7.000r/min

10°C



No

1,020r/min (A/F11.2)

Yes (A/F less than 10.8)

870r/min (A/F 10.8)

No

1,300r/min (A/F 11.5)

- Both [REDACTED] and CBR, Engine Stall occurs after few seconds the clutch disengage to coasting with Throttle fully closed from Engine high speed range.
- No occurrence of engine stall in a state the clutch engage, and restart after engine stall is easy.
- In the process of the warm-up (In the Range Oil Temp. 25 ~ 60 °C), the idling Speed drops below setting, A/F becomes rich and Engine stall has occurred .

Reproduction Result

Eng. Stall Temp. Range

4. Analysis Result


Comparison Head tightening torque

Comparison Data
PB Map at Eng. Speed 1,000r/min

CRF250L Cange FI Mapping (Left)

CBR250R Changing Head tightening torque (Right side)


CBR250R (MC41)



Stall	No	No	Yes	Unconfirmed (Plan)	Yes
Eng. Speed after dropping	900r/min	1,050r/min	980r/min		970r/min
A/F	11.1	11.2	11.2		11.2
Leakage Volume cm ³ /min (@20kPa)	236	79(New HEAD)	434	1,564	1,700
Head tightening torque	40N·m Ref.	48N·m Upper Tolerance	51N·m Setting	35KN (Axial Force Buy Back) ⇒56N·m	60.5N·m (Ave.) EX 58.7 61.1 69.3 52.8


- There is specifications difference (fuel pressure, bore diameter, the intake and exhaust System), it is not possible numerical comparison.
- CRF, the engine stall does not occur when Lean fuel setting under Idle Speed
- Amount of leakage is changed by the Head Tightening Torque, CBR Stall becomes not occur.

4. Analysis Result



4. Analysis Result

Occurrence mechanism (estimated)



5. Countermeasure

countermeasure for Engine Stall




Content		CBR250R		
ENG		Change	Content	Effect
Parts and Tightening Torque Change		①Cylinder Head ②Stud Bolt ③、④Cylinder/Head Gasket ⑤Nut ⑥Washer ⑦Tightening Torque	New ↑ ↑ ↑ ↑ 51N·m →48N·m	Improve distortion of cylinder Head and Eng. Assy. Leakage by Tightening Torque Excessive
		/		

- CRF: ENG Parts & ECU Data Change
 - CBR: ENG Parts Change
- To the countermeasure specification the above correspondence.

5. Countermeasure


Before

After



Both [redacted] and CBR, the introduction of countermeasure specification, is no longer the occurrence of engine stall


5. Countermaesure



Item		CBR250R
------	--	---------

ENG Parts
Tightening
Torque Change

• No change to performance only the parts are changed
• Tightening torque is also no problem a correspondence by setting width.



CBR not negative measures specification for each

7. Schedule

Item	Responsible	Schedule			
		June	July		August
GQM Promotion Plan	QAD	26 ▼ Q-p/Q1	9 ▼ Q2	16 ▽ Q-e	
GQM Amendment		26 ▼ Q-p	9 ▼ Q1-1st	16 ▽ Q1-2nd	31 ▽ Q1~Q-e
Reproduction Test	QAD	11 ▼	15 ▼		
Cause investigation (HEAD distortion)	HGA QAD	M/P Mold Head Confirm (Reration of Tightening Torque and Axial Force)			
Countermeasure		▼	→		▽
Effect confirmation		▼	→		▽
Negative confirmation		▼	→		▽
Occurrence prediction	Service QAD		▽		▽
Final event			▽		▽
Market corresponding			▽		▽

END

PE14-032

HNDA


12-19-2014

Q8 REDACTED

GQM_REDACTED

Q8-5 - 520th GQM

report_English_REDACTED



QIC.NO

<Contents>

- 1. Previous Pointin
- 2. Complained of e
- 3. Number of occur
- 4. Analysis result
- 5. Countermeasures
- 6. Proposal
- 7. Deployment schedule



QIC.NO : M11THM 054-00
 M12THM 009-00
 2HKO2012001-00

2012.7.31
 520th GQM
 Q1~Qend Report

1. Previous pointed out

<Previous GQM Q1-2nd> (2012.7.16)

Pointed Out Item	Correspondence
1. Summarize the occurrence mechanism did on assess the true cause.	⇒P 9
2. Consider the necessity of the corresponding did on understanding the ability of the Head Tightening Torque in mass production line.	⇒P 7、14
3. I understand about the measures release of drawing.	⇒7/20 (Fri) Release of drawing completion

2、3 Complained of events & Number of occurrences

Vehicle	[REDACTED]			CBR250R MC4 [REDACTED]				
Occurrence Situation Summary				Problem is happening intermittently, will occur within 10 minutes after the engine is started. At a reduced speed and happens only when you are off the clutch. Number of revolutions that have cut the clutch is low 3000r / m, is high and 8000r / m.				
QIC				M11THM 054-00 M12THM 009-00 2HKO2012001-00				
Country		[REDACTED]			JAPAN	USA	KOREA	Whole World
Occ. No./ Eng. Stall Complaint [Unit]	QIC				0 / 20	2 / 34	9 / 18	11 / 102
	Wty.				1 / 195	0 / 16	9 / 25	10 / 313
	TL				0 / 198	4 / 177	—	4 / 400
	CR				0 / 17	2 / 66	—	2 / 85
Occ. No.[Unit]		1	7	9※	17			
Sales (end of June) [Unit]		6,917	8,459	335	30,777			
Occurrence Ratio[%]		0.01	0.08	2.69	0.06			
Plans to sell country		No unreleased countries.						

※No subsequent recurrence information with the launch of winter

4. Analysis Result

		BR250R (MC41 [REDACTED])	
		SPEC	L R
Tp,Cl (mm)	IN	0.16±0.03	0.18 0.18
	EX	0.27±0.03	0.26 0.26
Valve Timing		IN 20 0 EX 21.5 3 EX ----- (.60) 35 40(8.30) (8.45) 30.5 40(8.14)	
Compression Ratio		10.7±0.2	10.63
COMP (kPa)		1300	1294
IDLE Speed(r/min)		1400±100	1400
IDLE PB(kPa)/Gair(g/sec)		Less than 72kpa/0.90	69.1/0.91
ENG OIL Volume		Upper (1.8L)	
Plug Cap			
Plug condition		Nothing abnormal	
Connecting Ground			

There is a slight shift of Valve Timing, but Vehicle abnormality can not be seen without the items in problem.

4. Analysis Result

Problem Vehicle

(Reproduction, Engine Stall Temp. Range)

No changes from Previous Report

Reproduction Result


Eng. Stall temp. Range

CBR250R (MC41 [REDACTED])

23~85°C

100km/h/7.000r/min

10°C



No

1,020r/min (A/F11.2)

Yes (A/F less than 10.8)

870r/min (A/F 10.8)




No

1,300r/min (A/F 11.5)

- Both [REDACTED] and CBR, Engine Stall occurs after few seconds the clutch disengage to coasting with Throttle fully closed from Engine high speed range.
- No occurrence of engine stall in a state the clutch engage, and restart after engine stall is easy.
- In the process of the warm-up (In the Range Oil Temp. 25 ~ 60 °C), the idling Speed drops below setting, A/F becomes rich and Engine stall has occurred .


4. Analysis Result Fuel setting lean/ Comparison Head tightening torque

Item
Comparison Data (PB Map at Eng. Speed 1,000r/min)



Eng. Stall	BuyBack	No ○	—	Yes ×	—	Yes ×
	New	—	No ○	—	No ○	No ○
Eng. Speed	BuyBack	900r/min 11.1	—	980r/min 11.2	—	970r/min 11.2
er dropping	New	—	1,050r/min 11.2	—	1,230r/min 11.8	1,160r/min 11.8
leakage volume (m ³ /min @20kPa)	BuyBack	236	—	434	—	1,700
	New	—	79	—	580	610
Head tightening torque		40N·m	48N·m	51N·m	54N·m	60.5N·m (Ave.)
						EX 58.7 61.1
						IN 69.3 52.8
	Ref.		Under Tolerance	Setting	Upper Tolerance	Buy Back




CBR250R Changing Head tightening torque (Right)



There is specifications difference (fuel pressure, bore diameter, the intake and exhaust System), it is not possible numerical comparison,

- CBR250R leak amount is reduced and not stall occurs Lowering the tightening torque of the head attached clamping by Overspecified.
- CBR250R is stalling does not occur in the exchange to the new head.

4. Analysis Result Valve Leakage amount ~ Head tightening Axial Force




CAE analysis results
Valve Seat Leakage occurs deformed by with Head Tightening Axial Force

CAE Conditions: Axial Force 37.7kN


• Axial Force of more than aim at the Development has occurred within the Set Torque Range due to the difference of how Tightening.
 ⇒ Mass Production Management Techniques to achieve, including separate adjustment change of setting torque to be the axial force of the aim.

4. Analysis Result

· Before Warm-up complete
· Clutch disengage
Engine Stall in Coasting



4. Analysis Result




5. Countermeasure

Content	[Redacted]	CBR250R		
[Redacted]		[Redacted]		
[Redacted]				
ENG Parts and Tightening Torque Change	[Redacted]	Change	Content	Effect
	[Redacted]	①Cylinder Head ②Stud Bolt ③、④Cylinder/Head Gasket ⑤Nut ⑥Washer ⑦Tightening Torque	New ↑ ↑ ↑ ↑ 51N·m →48N·m	Improve distortion of cylinder Head and Eng. Assy. Leakage by Tightening Torque Excessive


• CBR : ENG Parts Change
To the countermeasure specification the above correspondence.

5. Countermeasure

Before



After




Both [redacted] and CBR, the introduction of countermeasure specification, is no longer the occurrence of engine stall

5. Countermeasure

Negative Confirmation



Item		CBR250R
ENG Parts Tightening Torque Change	<ul style="list-style-type: none">• No change to performance only the parts are changed• Tightening torque is also no problem a correspondence by setting width.	




CBR not negative measures specification for each

6. Proposal

CBR250R

■ Weibull: user (N = 17) released one year 9 months



• $M = 0.4596$
Early Type

Year	Occ. Ratio (%)	Occ. No.
1	0.0659	20
2	0.0906	28
3	0.1092	34
4	0.1246	38
5	0.1381	42
6	0.1501	46
7	0.1611	50
8	0.1713	53
9	0.1809	56
10	0.1899	58

• CBR250R: Incidence of after two years is 0.09%, and the occurrence number expected to be 28 units.

6. Proposal

Market corresponding proposal
The final event confirmation

PAGE CONTAINS 14/15
BUSINESS CONFIDENTIAL
INFORMATION

Market corresponding [REDACTED] CBR250R; the general claims handling

Corresponding contents (1)ENG Parts Exchange ▪ Tightening to the specified torque [REDACTED]
CBR250R)

[REDACTED]

『Reason』

Market Complain 「To stall when disengage the clutch closes the throttle during deceleration」

Reproducible 「To stall when hold long disengage clutch」 「At the Cold, it is not nearly occur」

results Only occurs in the process of warm-up, clutch disengage from Engine high speed range.

It is in the event that limited conditions and rare usability are combined to occurs.

Final event ■ Case of the continued Engine Stall while disengage the clutch.

Change of slowdown feeling, rapid deceleration, disturbance of body behavior does not occur, can be restarted in starter switch.

■ Case of engage clutch while Engine Stall.

Engine restart by rear wheel drive. Behavior unexpected vehicle does not occur.

◆ During stalling, lighting equipment is functioning, enables the detection of the following vehicle.

Among the usual convenient, functional inhibition is not occur.

Market incidence It considered early type. Incidence is low [REDACTED] / CBR250R:0.06%)

7. Schedule

Item	Responsible	Schedule			
		June	July		August
GQM Promotion Plan	QAD	26 ▼ Qp/Q1	9 ▼ Q2	16 ▼ Qe	
GQM Amendment		26 ▼ Qp	9 ▼ Q1-1次	16 ▼ Q1-2次	31 ▼ Q1~Qe
Reproduction Test	QAD	11 ▼	15 ▼		
Cause investigation (HEAD distortion)	HGA QAD	M/P Mold Head Confirm (Reration of Tightening Torque and Axial Force)			
Countermeasure		▼	▼		
Effect confirmation		▼	▼		
Negative confirmation		▼	▼		
Occurrence prediction	Service QAD		▼		
Final event			▼		
Market corresponding			▼		▼ Create a head replacement work manual
CRF250L USA W/H rewrite	TH		JAPAN Vr. Rewrite verification	26 ▼	27 ▼ Plan (about 2,000) ▼

During the adjustment

END

PE14-032

HNDA

12-19-2014

Q8 REDACTED

GQM_REDACTED

Q8-6 - 523th GQM

report_English_REDACTED



QIC.NO



<Contents>

- 1. Previous Pointing
- 2. Complained of ev
- 3. Number of occur
- 4. Analysis result
- 5. Countermeasures
- 6. Proposal
- 7. Deployment schedule



QIC.NO : M11THM 054-00
 M12THM 009-00
 2HKO2012001-00

2012.8.20
 523th GQM
 Qend 2nd Report

1. Previous pointed out

<Previous GQM Q1-Qend> (2012.7.31)

Pointed Out Item	Correspondence
1. With respect to the axial force target value of the specification on the upper and lower limit, determine the tools and torque setting value in the market.	⇒P15
2. In Impact Wrench / QL Wrench in the TH, to clarify the relationship between the Tightening Torque and Axial Force, determine the tightening in procedure line.	⇒Will report Next Qend-3rd
3. Reflection of the permanent plan for the next model, and please to reflect the consolidation of the base model in Schedule.	⇒P16

2、3 Complained of events & Number of occurrences

Vehicle		CBR250R MC41 [REDACTED]
Occurrence Situation Summary		Problem is happening intermittently, will occur within 10 minutes after the engine is started. At a reduced speed and happens only when you are off the clutch. Number of revolutions that have cut the clutch is low 3000r / m, is high and 8000r / m.
QIC		M11THM 054-00 M12THM 009-00 2HKO2012001-00

Country		JAPAN	USA	KOREA	Whole World
Occ. No./ Eng. Stall Complaint [Unit]	QIC	0 / 20	2 / 34	9 / 18	11 / 102
	Wty.	1 / 195	0 / 16	9 / 25	10 / 313
	TL	0 / 198	4 / 177	—	4 / 400
	CR	0 / 17	2 / 66	—	2 / 85
Occ. No.[Unit]		1	7	9※	17
Sales (end of June) [Unit]		6,917	8,459	335	30,777
Occurrence Ratio[%]		0.01	0.08	2.69	0.06
Plans to sell country		No unreleased countries.			

※No subsequent recurrence information with the launch of winter

4. Analysis Result

Specification of Problem Vehicle

No changes from Previous Report

			CBR250R (MC41 XXXXXXXXXX)																															
			SPEC	L	R																													
Tp,Cl (mm)	IN		0.16±0.03	0.18	0.18																													
	EX		0.27±0.03	0.26	0.26																													
Valve Timing			<table style="border-collapse: collapse; margin: auto;"> <tr> <td style="text-align: right;">IN</td> <td style="text-align: center;">20</td> <td style="border-left: 1px solid black; border-right: 1px solid black; width: 20px;"></td> <td style="text-align: center;">0</td> <td style="text-align: left;">EX</td> </tr> <tr> <td colspan="2" style="border-top: 1px solid black;"></td> <td colspan="2" style="border-top: 1px solid black;"></td> <td></td> </tr> <tr> <td style="text-align: right;">(8.60)</td> <td style="text-align: center;">35</td> <td style="border-left: 1px solid black; border-right: 1px solid black;"></td> <td style="text-align: center;">40</td> <td style="text-align: left;">(8.30)</td> </tr> </table>	IN	20		0	EX						(8.60)	35		40	(8.30)	<table style="border-collapse: collapse; margin: auto;"> <tr> <td style="text-align: right;">IN</td> <td style="text-align: center;">21.5</td> <td style="border-left: 1px solid black; border-right: 1px solid black; width: 20px;"></td> <td style="text-align: center;">3</td> <td style="text-align: left;">EX</td> </tr> <tr> <td colspan="2" style="border-top: 1px solid black;"></td> <td colspan="2" style="border-top: 1px solid black;"></td> <td></td> </tr> <tr> <td style="text-align: right;">(8.45)</td> <td style="text-align: center;">30.5</td> <td style="border-left: 1px solid black; border-right: 1px solid black;"></td> <td style="text-align: center;">40</td> <td style="text-align: left;">(8.14)</td> </tr> </table>	IN	21.5		3	EX						(8.45)	30.5		40	(8.14)
IN	20			0	EX																													
(8.60)	35			40	(8.30)																													
IN	21.5			3	EX																													
(8.45)	30.5			40	(8.14)																													
Compression Ratio			10.7±0.2	10.63																														
COMP (kPa)		1300	1294																															
IDLE Speed(r/min)		1400±100	1400																															
IDLE PB(kPa)/Gair(g/sec)		Less than 72kpa/0.90	69.1/0.91																															
ENG OIL Volume		Upper (1.8L)																																
Plug Cap		Nothing abnormal																																
Plug condition																																		
Connecting Ground																																		

There is a slight shift of Valve Timing, but Vehicle abnormality can not be seen without the items in problem.

4. Analysis Result

Problem Vehicle
(Reproduction, Engine Stall Temp. Range)

No changes from
Previous Report

Reproduction Result


Eng. Stall Temp. Range

CBR250R (MC41 [REDACTED])

23~85°C

100km/h/7.000r/min

10°C



No

1,020r/min (A/F11.2)

Yes (A/F less than 10.8)


870r/min (A/F 10.8)

No

1,300r/min (A/F 11.5)

- Engine Stall occurs after few seconds the clutch disengage to coasting with Throttle fully closed from Engine high speed range.
- No occurrence of engine stall in a state the clutch engage, and restart after engine stall is easy.
- In the process of the warm-up (In the Range Oil Temp. 25 ~ 60 °C), the idling Speed drops below setting, A/F becomes rich and Engine stall has occurred .

4. Analysis Result Fuel adjustment lean/ Comparison Head tightening torque



	BuyBack	No	—	Yes	—	Yes									
	Eng. Stall	○	—	×	—	×									
	New	—	○	—	○	○									
	BuyBack	900r/min 11.1	—	980r/min 11.2	—	970r/min 11.2									
	New	—	1,050r/min 11.2	—	1,230r/min 11.8	1,160r/min 11.8									
	A/F	—	—	—	—	—									
CBR250R Changing Head tightening torque (Right)	BuyBack	236	—	434	—	1,700									
	New	—	79	—	580	610									
	Ref.	40N·m	Under Tolerance	Setting	Upper Tolerance	Buy Back									
	Head tightening torque	40N·m	48N·m	51N·m	54N·m	60.5N·m (Ave.)									
						<table border="1"> <tr> <td></td> <td>L</td> <td>R</td> </tr> <tr> <td>EX</td> <td>58.7</td> <td>61.1</td> </tr> <tr> <td>IN</td> <td>69.3</td> <td>52.8</td> </tr> </table>		L	R	EX	58.7	61.1	IN	69.3	52.8
	L	R													
EX	58.7	61.1													
IN	69.3	52.8													


There is specifications difference (fuel pressure, bore diameter, the intake and exhaust System), it is not possible numerical comparison.

- CBR250R is Engine stall does not occur Lowering the tightening torque of the actual item to 40N·m
- CBR250R is stalling does not occur in the exchange to the new head.



Since with the aim of fastening axial force can not be obtained, component reuse of nut bolts is not allowed

4. Analysis Result CBR250R Factory line Tightening Torque Check Result

After with oil pulse wrench tighten (n=20 Unit)






After with QL Wrench tighten (n=20 Unit)



4. Analysis Result Valve Leakage amount ~ Head tightening Axial Force

No changes from Previous Report



CAE analysis results
Valve Seat Leakage occurs deformed by with Head Tightening Axial Force

CAE Conditions: Axial Force 37.7kN


• Axial Force of more than aim at the Development has occurred within the Set Torque Range due to the difference of how Tightening.
 ⇒ Mass Production Management Techniques to achieve, including separate adjustment change of setting torque to be the axial force of the aim.

4. Analysis Result

FTA

No changes from Previous Report

· Before Warm-up complete
· Clutch disengage
Engine Stall in Coasting



4. Analysis Result

Occurrence Mechanism (Draft)

██████████ CBR250R <Common Factor >

Axial force had been over the target when tightened in line with drawings torque.

Cylinder Head
Spec. over in Tightening Torque
(Confirm result re-tightening by Buyback)

Valve leakage increase by Valve Seat Distortion

In the warm-up process from High Load/Speed Range
'Throttle complete close and Clutch disengage'
Concurrent operations

(Tightening Torque 51N·m±3)

		CBR250R	
		L	R
E	██████████	58.7	61.1
I	██████████	69.3	52.8

Engine Speed drops below the Idle Speed by Valve Leakage

Poor combustion

Engine Stall




CBR250R
Market incidence
0.06%(Whole World)
Reproduction test incidence : 40%


5. Countermeasure


Content

CBR250R



	Item	Change	Effect
(2) ENG Parts and Tightening Torque Change	1-①Cylinder Head	新品	Improve distortion of cylinder Head and Eng. Assy. Leakage by Tightening Torque Excessive
	②Stud Bolt	↑	
	③Cylinder Gasket	↑	
	④Head Gasket	↑	
	⑤Nut	↑	
	⑥Washer	↑	
	2 Tightening Torque	51N·m	






 CBR(2)ENG Parts Change
 To the above combination correspond to the countermeasures specifications of both models.

5. Countermeasure


Effect of countermeasure

No changes from Previous Report

Before



After




Both [redacted] and CBR, the introduction of countermeasure specification, is no longer the occurrence of engine stall.

5. Countermeasure

Negative Confirmation

No changes from Previous Report

Item	[Redacted]	CBR250R
[Redacted]		
ENG Parts Tightening Torque Change	• No change to performance only the parts are changed	


[Redacted] CBR not negative measures specification for each

6. Proposal

Occurrence Prediction

CBR250R

■ Weibull: user (N = 17) released one year 9 months




• M = 0.4596
Early Type

• CBR250R : Incidence of after two years is 0.09%, and the occurrence number expected to be 28 units.

6. Proposal Details


Market Action	Handle as Normal Warranty Claim for both [REDACTED] and CBR250
C/M Detail	(1)Replacement of the specified Engine parts (only head comp can be reused after valve seat correction) and clamping by the designated torque of15N・m (for [REDACTED] CBR250R)



『Reasons』

Customer Contention	<p>“Engine stall occurs when I close a throttle during slowdown with clutch off.”</p> <p>“Engine stall occurs when a clutch is pulled for a while.”, “It is unlikely to occur in in cold condition.”</p>
Recurrence test results	<p>It occurs only in the condition from high rev with clutch pulled in warm-up process.</p> <p>The phenomenon occurs only when a limited condition and a rare operation are put together.</p>
Definitive phenomenon	<ul style="list-style-type: none"> ■ Even if engine stall condition with clutch pulled was continued,, Change of slowdown feeling, rapid deceleration, and body behavior disturbance will not occur, and by pushing starter switch engine can be restarted. ■ If a driver engaged clutch durinh engine stall,, Engine will be restarted by rear wheel traction. On this occasion no unpredictable body behavior will occur. <p>◆Light device functions during engine stall. Detection from following car is possible.</p> <p>In ordinary driving, no functional defect occurs.</p>
Market incidence	Seems to be early occur type and has low incidence. C [REDACTED] CBR250R (Whole World):0.06%

7. Schedule

Item	Responsible	Schedule						'13	
		June	July			August	Sep.	Oct.	Sep.
GQM Promotion Plan	QAD	26 ▼ Qp	9 ▼ Q1-1st	16 ▼ Q1-2nd	31 ▼ Qe1st	20 ▼ Qe2nd	27 ▼ Qe3rd		
Reproduction Test	QAD	11 ▼	15 ▼						
Cause investigation	HGA	Rerotation of Tightening Torque and Axial Force							
Countermeasure	QAD	▼	▼	▼	▼	Tightening torque setting examination HGA to TH business trip			
Effect and Negative confirmation		▼	▼						
Occurrence prediction Final event	Service	Rewrite Design Change							
Market corresponding	QAD		▼			▼			
CBR250R Toughness improvement study	HGA							Applied mass production in the next model	

END

PE14-032

HNDA

12-19-2014

Q8 REDACTED

GQM_REDACTED


Q8-7 - 524th GQM

report_English_REDACTED

11~12M [REDACTED] CBR250R(MC41) Engine stalling during drive with clutch pulled in for a while.

<Index>

1. Instruction of last meeting
2. Customer Content
3. Number of claims
4. Analysis results
5. Countermeasure detail
6. Proposal detail
7. Proceeding schedule



QIC.NO : M11THM 054-00
M12THM 009-00
M12THM 009-01
2HKO2012001-00

2012/ Aug./27
No.524th GQM
Q-Complete Report

1. Instruction of last meeting

<Last GQM Q Comp.-2nd> (2012/Aug/20)

Instruction contents	Reply
<p>1. According to verified results of torque/axial power in TH factory, report about measures of market action/factory line in the next GQM.</p>	<p>⇒P14</p>
<p>2. As for stock control instruction associated with a drawing issue of design change, clarify the contents of measures in abroad.</p>	<div data-bbox="961 743 1976 939" style="border: 1px solid black; padding: 5px;"> <p>Application Request, Supplement to Mfg., HS & HB</p> <p>To SS: Please apply rewriting method to warehouse stocks.</p> <p>To HS: please revise and issue part List</p> <p>To HB: please integrate into new parts</p> </div> <p>Coordinate the contents in a information share meeting. Instruct the measures of Japan and USA by “Mass Production Spec Notice” according to the above notes.</p>

2、3 Customer Contention, Number of claims

Model		CBR250R MC41 [REDACTED]			
Summary of occurrence situation		Problem occurred intermittently within 10 min. after engine start. It occurred only when MC was decelerating and a clutch pulled in. The engine rev speeds when a clutch was pulled in were at the lowest of 3000rpm and the highest of 8000rpm.			
QIC		M11THM 054-00 M12THM 009-00 M12THM 009-01 2HKO2012001-00			
Occur. Country		Japan	USA	Korea	Whole World
No. of Claims/ No. of claims for Engine stop [no. of Units]	QIC	0 / 20	3 / 35	9 / 18	12 / 103
	Wty.	1 / 195	0 / 16	9 / 25	10 / 313
	TL	0 / 198	4 / 177	—	4 / 400
	CR	0 / 17	2 / 66	—	2 / 85
No. of Claims [No. of unit]		1	8	9※	18
No. of sales (at the end of Jun)[no. of unit]		6,917	8,459	335	30,777
Ocurrence rate [%]		0.01	0.09	2.69	0.06
Planned sales Country		No planned sales country			

※claims were alleged in winter, and no additional claim after that.

4. Analysis Results

Verification results of Specification conformance of actual vehicle

		CBR250R (MC41 [REDACTED])																	
		SPEC	L	R															
Tp,Cl (mm)	IN	0.16±0.03	0.18	0.18															
	EX	0.27±0.03	0.26	0.26															
Valve timing*		<table border="1"> <tr> <td>IN</td> <td>20</td> <td>0</td> <td>EX</td> </tr> <tr> <td>(8.60)</td> <td>35</td> <td>40</td> <td>(8.30)</td> </tr> </table>	IN	20	0	EX	(8.60)	35	40	(8.30)	<table border="1"> <tr> <td>IN</td> <td>21.5</td> <td>3</td> <td>EX</td> </tr> <tr> <td>(8.45)</td> <td>30.5</td> <td>40</td> <td>(8.14)</td> </tr> </table>	IN	21.5	3	EX	(8.45)	30.5	40	(8.14)
IN	20	0	EX																
(8.60)	35	40	(8.30)																
IN	21.5	3	EX																
(8.45)	30.5	40	(8.14)																
Compression ratio		10.7±0.2	10.63																
COMP (kPa)		1300	1294																
IDLE 回転数(r/min)		1400±100	1400																
IDLE PB(kPa)/Gair(g/sec)		Below 72kpa /0.90	69.1/0.91																
ENG OIL vol		Upper level (1.8L)																	
Plug Cap		No abnormalities																	
Plug burning																			
Ground connection																			

[REDACTED] and CBR250R have small deviation of valve timing, but it is not a cause of the occurrence.


[REDACTED] and CBR250R have no other problem to inspect, no abnormalities are seen in the vehicles.

4. Analysis Results

Actual Vehicle verification results (Reproductive test, in the range of temp. where a engine rev stop occurs.

Reproductive test results


Temp. range of occur.



- Engine stop occurs during inertia run 2-3 seconds after clutch is pulled in with throttle fully closed from a high engine rev situation.
- Engine stop doesn't occur under the situation with clutch engaged. Even if the engine stop occurs, it is easy to restart engine.
- Engine rev decreases less than setting idol rev in warm-up process (oil temp is 25~65°C), and A/F becomes rich, and engine stall occurs.

4. Analysis Results

Comparison for A/F ratio lean control and Head comp tightening Torque



CBR250R Tightening Torque changing (Right table)	Engine stall	Actual Unit	Not occur	—	Occur	—	Occur				
		New Unit	—	Not occur	—	Not occur	Not occur				
	rpm at stall	Actual Unit	900r/min 11.1	—	980r/min 11.2	—	970r/min 11.2				
	A/F	New Unit	—	1,050r/min 11.2	—	1,230r/min 11.8	1,160r/min 11.8				
	ak amount engine sy	Actual Unit	236	—	434	—	1,700				
	3/min 20kPa)	New unit	—	79	—	580	610				
Tightening torque		For reference	40N·m	lower limit tolerance	48N·m	Set value	51N·m	Upper limit tolerance	54N·m	Outcome of Actual Unit	60.5N·m (Ave.)
										L	R
										EX 58.7	61.1
										IN 69.3	52.8

·It can not be compared numerically because of the difference of specifications (Fuel pressure, Bore diameter, Intake & Exhaust sys.)

·CBR250R will not occur engine stall after the tightening torque of Actual unit is released to 40N·m.


·CBR250R will not occur engine stall after the engine head is replaced to new one.

Used parts such as nut and bolt can not reuse because aimed clamping axial power is not be gotten.


4. Analysis Results

CBR250R Verification results of clamping torque in factory line.


After clamping with oil pulse wrench (n=20units)




After QL clamping(n=20 units)



Unit	kgf·m	N·m
Max. std.	5.5	54
Cent. std.	5.2	51
Min. std.	4.9	48






Ave. of clamping torque in line (N: 5 units)



Actual line verification shows that clamping torque data are all in standard.

4. Analysis Results

Correlation between valve air leakage, head clamping axial power




- The axial power which does not cause engine stall is under 38.6 kN.
- Clamping of TH(Impact & QL) may surpass axial power limit for leakage.
 - Variation of axial power by impact wrench clamping.
 - Overstroke by QL wrench clamping

4. Analysis Result


FTA

· In Warm-up process
· Clutch disengage
Engine Stall during Coasting



4. Analysis Results

Mechanism of Occurrence




5. Countermeasure Details



Market action proposal C/M contents

content

CBR250R



(2)
Engine
Part
replacem
ent




• CBR250R: (2) Engine parts replacement
Countermeasure for both models will be the combinations mentioned above.


5. Countermeasure Details

Proposed market action, Confirmation of the measures effect

Before C/M



After C/M



No engine stall occurs by means of countermeasures for both [redacted] and CBR250R.

5. Countermeasure Details


Proposed market action, Confirmation of negative effect

[Redacted]

content

[Redacted]

CBR250R



Engine part replacement

Only part modification. No performance affected.

No negative effect from modification was confirmed for both [Redacted] and CBR250R

5. Countermeasure

Clamping according to demanded axis power


Head comp clamping in TH line



Change the set torque for impact wrench: 51 → 33 N·m
 Change a QL wrench: adopt a over less type wrench (set torque is 51 N·m, no change)

It was confirmed that axial power comes in target range by changing the setting

Head comp clamping in measures





Impact wrench is not available.
 Set torque is 51 N·m instructed in Service Manual. No change.

It was confirmed that no engine stall occurs at the upper limit torque by hand clamping.

- Impossible to use impact wrench because of its variation.
- Wearout parts, such as stud bolt, washer, nut, Cylinder gasket, and head gasket, will be replaced to new one.

6. Proposal

Occurrence Prediction



• CBR250R : Incidence of after two years is 0.09%, and the occurrence number expected to be 28 units.

6. Proposal Details

Proposal of Market Action, Definitive phenomenon

Market Action	Handle as Normal Warranty Claim for both [REDACTED] and CBR250
C/M Detail	(1)Replacement of the specified Engine parts (only head comp can be reused after valve seat correction) and clamping by the designated torque of45N·m (for [REDACTED] CBR250R)



『Reasons』

Customer Contention	<p>“Engine stall occurs when I close a throttle during slowdown with clutch off.”</p> <p>“Engine stall occurs when a clutch is pulled for a while.”, “It is unlikely to occur in in cold condition.”</p>
Recurrence test results	<p>It occurs only in the condition from high rev with clutch pulled in warm-up process.</p> <p>The phenomenon occurs only when a limited condition and a rare operation are put together.</p>
Definitive phenomenon	<ul style="list-style-type: none"> ■ Even if engine stall condition with clutch pulled was continued,, Change of slowdown feeling, rapid deceleration, and body behavior disturbance will not occur, and by pushing starter switch engine can be restarted. ■ If a driver engaged clutch durinh engine stall,, Engine will be restarted by rear wheel traction. On this occasion no unpredictable body behavior will occur. ◆ Light device functions during engine stall. Detection from following car is possible. <p>In ordinary driving, no functional defect occurs.</p>
Market incidence	Seems to be early occur type and has low incidence. [REDACTED] CBR250R (Whole World):0.06%

7. Schedule

Item	Div. in charge	Schedule						' 13		
		Jun	Jul			Aug.		Sep	Oct	Sep
GQM promote	MQAD	26 ▼ Q-P	9 ▼ Q1-1st	16 ▼ Q1-2nd	31 ▼ Q-C1st	20 ▼ Q-C2nd	27 ▼ Q-C3rd	10 ▼ Q-C		
Recurrence test	MQAD	11 ▼	15 ▼							
Cause Analysis	HGA MQAD	Verification of correlation between clamping torque and axial power ▼			Clamping torque setting study HGA business trip to TH factory		C/M clamping method Apply to TH factory			
Countermeasure Study		▼			▼		▼			
Verification of Effectiveness/ Negative		▼			▼		▼			
Occurrence prediction Definitive phenomenon Discussion for market action	Service MQAD		▼							
CBR250 Study for toughness up	HGA		Clamping torque change (51→45N·m) · verification of negative factor				14 ▼	MP Design Change		

END

PE14-032

HNDA

12-19-2014

Q8 REDACTED

GQM_REDACTED

Q8-8 - 525th GQM

report_English_REDACTED

11~12M [REDACTED] CBR250R(MC41) Engine stalling during drive with clutch pulled in for a while.



- 1. Instruction of meeting
- 2. Customer Concern
- 3. Number of claims
- 4. Analysis results
- 5. Countermeasure detail
- 6. Proposal detail
- 7. Proceeding schedule



QIC.NO : M11THM 054-00
M12THM 009-00
M12THM 009-01
2HKO2012001-00

2012/ Sep./10
No.525th GQM
Q-Complete Report

1. Instruction of last meeting

<Last GQM Q Comp.-3rd> (2012/ Aug./27)

Instruction contents	Reply
<p>1. Prepare the data; as for the impact wrench used for the affected parts in TH, the new one of oil pulse method can provide a stable torque/axis power, while the torque/axis power of the conventional one may be changed by clamping time.</p>	<p>As for impact wrench, the one of oil pulse method have been used for a long time.</p>
<p>2. The excessive torque by the overstroke in the QL wrench clamping process had been confirmed in TH, so it should be clearly shown in Market Action instruction that the QL Wrench clamping shall be performed slowly enough. (P8, P14)</p>	<p>⇒P14</p>
<p>3. The value of impact wrench torque was set down to 33N·m as C/M. Describe its suitability of the value by means of axial force. (P14)</p>	<p>⇒P13</p>
<p>4. Prepare the data; The dispersion of axial force of mass production ($\pm 3\sigma$) will be settled in the targeted value ($\pm 3\sigma$) at development design by this C/M. (P14)</p>	<p>⇒P13</p>

2,3 Customer Contention, Number of claims

Model	[REDACTED]			CBR250R MC41 [REDACTED]
Summary of occurrence situation	[REDACTED]			Problem occurred intermittently within 10 min. after engine start. It occurred only when MC was decelerating and a clutch pulled in. The engine rev speeds when a clutch was pulled in were at the lowest of 3000rpm and the highest of 8000rpm.
QIC	[REDACTED]			M11THM 054-00 M12THM 009-00 M12THM 009-01 2HKO2012001-00
Occur. country	[REDACTED]			Japan USA Korea Whole world
No. of Claims/ No. of claims for Engine stop [no. of Units]	QIC	[REDACTED]		0 / 20 3 / 43 9 / 18 12 / 103
	Wty.	[REDACTED]		1 / 195 4 / 29 9 / 25 14 / 317
	TL	[REDACTED]		0 / 198 4 / 180 — 4 / 400
	CR	[REDACTED]		0 / 17 2 / 67 — 2 / 85
No. of Claims [No. of unit]	[REDACTED]			1 12 9※2 22
No. of sales (at the end of August)[no. of unit]	[REDACTED]			7,670 10,254 335 35,313
Ocurrence rate [%]	[REDACTED]			0.01 0.12 2.69 0.06
Planned sales Country	[REDACTED]			No planned sales country


※2: claims were alleged in winter, and no additional claim has happened after that.

4. Analysis Results

Actual Vehicle verification results (Reproductive test, in the range of temp. where a engine rev stop occurs.)

Reproductive test results

Temp. range of occur.




- Engine stop occurs during inertia run 2-3 seconds after clutch is pulled in with throttle fully closed from a high engine rev situation.
- Engine stop doesn't occur under the situation with clutch engaged. Even if the engine stop occurs, it is easy to restart engine.
- Engine rev decreases less than setting idol rev in warm-up process (oil temp is 25~65°C), and A/F becomes rich, and engine stall occurs.

4. Analysis Results

Comparison for A/F ratio lean control and Head comp tightening Torque

comparative data
PB Map at Eng rev 1000rpm



[Redacted]

CBR250R Tightening Torque changing (Right table)

Engine stall	Actual Unit	Not occur	—	Occur	—	Occur						
	New Unit	—	Not occur	—	Not occur	Not occur						
rpm at stall	Actual Unit	900r/min 11.1	—	980r/min 11.2	—	970r/min 11.2						
A/F	New Unit	—	1,050r/min 11.2	—	1,230r/min 11.8	1,160r/min 11.8						
leak amount as engine Assy	Actual Unit	236	—	434	—	1,700						
cm ³ /min at 20kPa)	New unit	—	79	—	580	610						
Tightening torque	For reference	40N·m	lower limit tolerance 48N·m	Set value 51N·m	Upper limit tolerance 54N·m	Outcome of Actual Unit 60.5N·m (Ave.)						
						<table border="1"> <tr> <td>L</td> <td>R</td> </tr> <tr> <td>EX 58.7</td> <td>61.1</td> </tr> <tr> <td>IN 69.3</td> <td>52.8</td> </tr> </table>	L	R	EX 58.7	61.1	IN 69.3	52.8
L	R											
EX 58.7	61.1											
IN 69.3	52.8											

It can not be compared numerically because of the difference of specifications (Fuel pressure, Bore diameter, Intake & Exhaust sys. [Redacted])


- CBR250R will not occur engine stall after the tightening torque of Actual unit is released to 40N·m.
- CBR250R will not occur engine stall after the engine head is replaced to new one.

Used parts such as nut and bolt can not reuse because aimed clamping axial power is not be gotten.


4. Analysis Results

CBR250R Verification results of clamping torque in factory line.


After clamping with oil pulse wrench (n=20units)




After QL clamping(n=20 units)



Unit	kgf·m	N·m
Max. std.	5.5	54
Cent. Std.	5.2	51
Min. std.	4.9	48



Ave. of clamping torque in line (N: 5 units)




Actual line verification shows that clamping torque data are all in standard.


4. Analysis Results

Correlation between air leak amount, head clamping axial power, and torque.

Valve leak amount / clamping axial power



Clamping torque / Axial power (comparison between development and mass product)



- The axial power which does not cause engine stall is under 38.6 kN.
- Compared to the axial power upper limit set in development, margins of axial power limit for leakage was small.
- Compared to the axial power set in development, MP clamping axial power has a big unevenness in the high axial power side.

4. Analysis Results

Verification results of clamping situation of MP line in TH factory


Clamping standard spec. of MP line is Oil pulse (impact) wrench : 51N·m, and QL wrench : 51N·m

Clamping by Oil pulse (impact) wrench was not long enough to be released. By unevenness of clamping time, axial power varies.


Because of unevenness of oil pulse wrench, Clamping stroke by QL wrench became Unstable. And it may cause some defective clamping such as overstroke.

QL clamping time is 0.5~3.3sec, and it is faster than that of development whose time was 5~10sec (corresponding to QL clamping), so coefficient of friction decreases, and unevenness spreads in the high axial power side. (refer to the diagraph of clamping torque/axial power of previous page)

Clamping time by impact wrench(51N·m) ~ Axial power



CL clamping of MP line in TH



Clamping of development process



- By the method of MP clamping (impact and QL) in TH, it may sometimes exceed the marginal axial power for leakage.
- Instability of clamping by QL wrench and overstroke, caused by unevenness of clamping time at the time of impact clamping.
- Decrease of coefficient of friction, caused by the clamping speed.

4. Analysis Results

Mechanism of Occurrence

For a work process by impact +QL clamping, the setting torque ($51 \pm 3\text{Nm}$) had no margin at the view point of axial power limit for leakage (38.6kN).

By QL clamping method set in TH, it may sometimes exceed the marginal axial power for leakage (38.6kN).

AND


Valve sheet deformed and valve leakage increased

In warm-up process, simultaneous operation of "throttle closed and clutch pulled in" from high load and high rev.

By valve leakage, engine rev falls below idling rev.

Combustion turns worse

Engine stall




CBR250R
Market incidence
0.06%(whole world)
Recreate test
incidence: 40%

5. Countermeasure Details

Market action proposal C/M contents

content	[REDACTED]	CBR250R
[REDACTED]		


	item	modification	effect	
(2) Engine Part replacem ent	1-①Cylinder Head Assy	New part, only head comp. can be reused with correction	Improve valve leakage caused by being over the target value of cylinder head clamping power	
	②Stud bolt	New part		
	③Cylinder gasket	↑		
	④Head gasket	↑		
	⑤Nut	↑		
	⑥Washer	↑		
	2- head clamp torque	45N·m		

• CBR250R: (2) Engine parts replacement
Countermeasure for both models will be the combinations mentioned above.


5. Countermeasure Details

Proposed market action, Confirmation of the measures effect

Before
C/M



After
C/M



No engine stall occurs by means of countermeasures for both [redacted] and CBR250R.

5. Countermeasure Details

前回報告変化なし

Proposed market action、 Confirmation of negative effect


content	[REDACTED]	CBR250R
---------	------------	---------

[REDACTED]		
------------	--	--

Engine part replacement	Only part modification. No performance affected.	←
-------------------------	--	---

No negative effect from modification was confirmed for both [REDACTED] and CBR250R


5. Countermeasure Details of clamping in TH



【Countermeasures】

Oil pulse wrench setting torque change: 51 → 33N·m
 Continue clamping until oil pulse wrench be released.
 QL setting torque change: 45 ± 3N·m

Impact (33N·m) clamp time ~ Axial power



By reducing setting torque of oil pulse wrench, clamping time before relief is shorten and axial power becomes stable.

Comparison of clamping torque with other models

Model name	CBR250R
Cooling method	Water cool
Displacement	250cc
Bore diameter	76.0
Dia. of stud axle	9.1
Dia. of screw	M10x1.25
Class	12.9
L limit of torque	42
U limit of torque	48

By setting change, axial torque comes in target range.
 Setting torque is equal to other models.
 But negative effect at axial power lower limit is to be verified and examined.
 (explained in next page)

5. Countermeasure Details

Market action (Service)

The method of clamping for head comp. in market (Service)

【countermeasures】

Clamping according to service manual instruction. Setting torque is $45\text{N}\cdot\text{m}$.

Service manual instruction (current)

Apply oil to screw thread, sitting face. Attach nut and tighten it, dividing into 2-3 times, at the opposite angle by designated torque.

Torque $51\text{N}\cdot\text{m}$ ($5.2\text{kgf}\cdot\text{m}$)



Service manual instruction (Countermeasure)

Apply oil to screw thread, sitting face. Attach nut and tighten it, dividing into 2-3 times, at the opposite angle by designated torque.

Torque $45\text{N}\cdot\text{m}$ ($4.6\text{kgf}\cdot\text{m}$)


Advisability for reuse of head comp. in market action (Service)

~ 1. Effectiveness verification for valve grinding

Seat contact state and seat surface width is heterogeneous. Effectiveness for air leakage is hardly provided.

~ 2. Effectiveness verification for seat cutter

According to service manual, grinding was done until the contact is confirmed. Uniform contact state was made and leakage as a comp. became smaller than $50\text{cm}^3/\text{min}$. Verification results with real vehicle test showed no engine stall. OK.



Service manual instruction:

Using Seat cutter (32° , 60°), correct sitting surface into the standard range. Valve sheet contact width: $0.9-1.1\text{mm}$. After that, perform valve grinding and verify contact state with red lead. Considering the status of contact, change valves.

- Clamping setting is changed to $45\text{N}\cdot\text{m}$. Stud bolt, washer, nut, and consumable part like gasket will be replaced with new one.
- Reuse of head comp. in market action is advisable with correction by sheet cutter.

5. Countermeasure Details

Verification results for negative effect
by change of head clamping torque.

【Countermeasures】

Setting torque change: $45 \pm 3 \text{N} \cdot \text{m}$

【Negative confirmation test results】

▪ Skid endurance simulating test

10000km endurance test was performed with clamping status of lower limit axial power. There were no torque down, no head gasket colonnade, and no bead crack. OK.

As a results of gasket make verification, there was no gasket colonnade, no bead crack, no abnormal waste, and so on. OK.

▪ Thermal durability

Thermal durability test with lower limit torque of $42 \text{N} \cdot \text{m}$ had shows no leak, no blur, no torque down, and so on. OK.

▪ Gasket contact pressure inspection

Verification results shows that boa bead part has more than 30 MPa and circumference bead part has more than 10 MPa. OK.

▪ In addition, there is no pending problem to become the negative for head clamping torque change. OK.

From the result mentioned above, the lower limit side axis power after the torque setting change can be guaranteed.

Promoting with the design change plan for MP on September 14th.

6. Proposal Detrails


Occurrence Prediction

CBR250R(Whole World)

■ Weibull method: User (N=17)

Data during 1 Year and 9 month on sale,

From register date to occurrence (30,777 units)



Passed years	Predictive incidence (%)	Occurrence no.
1	0.0659	20
2	0.0906	28
3	0.1092	34
4	0.1246	38
5	0.1381	42
6	0.1501	46
7	0.1611	50
8	0.1713	53
9	0.1809	56
10	0.1899	58

Predictive occurrence after 2 years is 28 units

6. Proposal Details

Proposal of Market Action, Definitive phenomenon

Market Action	Handle as Normal Warranty Claim for bot [REDACTED] and CBR250
C/M Detail	(1)Replacement of the specified Engine parts (only head comp can be reused after valve seat correction), and clamping by the designated torque of45N·m. (for [REDACTED] CBR250R)



『Reasons』

Customer Contention “Engine stall occurs when I close a throttle during slowdown with clutch off.”
 “Engine stall occurs when a clutch is pulled for a while.”, “It is unlikely to occur in in cold condition.”

Recurrence test results It occurs only in the condition from high rev with clutch pulled in warm-up process.
 The phenomenon occurs only when a limited condition and a rare operation are put together.

Definitive phenomenon

- Even if engine stall condition with clutch pulled was continued,,
 Change of slowdown feeling, rapid deceleration, and body behavior disturbance will not occur, and by pushing starter switch engine can be restarted.
- If a driver engaged clutch durinh engine stall,,
 Engine will be restarted by rear wheel traction. On this occasion no unpredictable body behavior will occur.
- ◆ Light device functions during engine stall. Detection from following car is possible.

In ordinary driving, no functional defect occurs.

Market incidence [REDACTED] CBR250R (Whole World) :0.06%

7. Schedule

Item	Div. in charge	Schedule						'13		
		Jun	Jul			Aug.		Sep	Oct	Sep
GQM promote	MQAD	26 ▼ Q-P	9 ▼ Q1-1st	16 ▼ Q1-2nd	31 ▼ Q-C1st	20 ▼ Q-C2nd	27 ▼ Q-C3rd	10 ▼ Q-C		
Recurrence test	MQAD	11 ▼	15 ▼							
Cause Analysis	HGA MQAD	Verification of correlation between clamping torque and axial power ▼			Clamping torque setting study HGA business trip to TH factory		C/M clamping method Apply to TH factory			
Countermeasure Study		▼			▼		▼			
Verification of Effectiveness/ Negative		▼			▼					
Occurrence prediction Definitive phenomenon Discussion for market action	Service MQAD		▼		▼					
CBR250 Study for toughness up	HGA		Clamping torque change (51→45N·m) · verification of negative factor			▼		14 ▼	MP Design Change	

END

PE14-032

HNDA

12-19-2014




Q8 REDACTED

GQM_REDACTED

JAPANESE


Q8-2 - 516th GQM

report_Japanese_REDACTED



QIS: TH2WE2011085








CBR250R MC41



QIC:M11THM 054-00

QIC Item Identification: M11THM 054-00 Date: 1/1/00

QIC





USA:425mile(684km)、韓国:546km

4.

		CBR250R (MC41 [REDACTED])		
		SPEC	L	R
Tp,Cl (mm)	IN	0.16±0.03		0.18
	EX	0.27±0.03		0.26
[REDACTED] °		IN	20 0 EX	21.5 3
		(8.60) 35 40 (8.30)	(8.45) 30.5 40 (8.14)	
[REDACTED]		10.7±0.2		10.63
COMP (kPa)		1300		1294
[REDACTED]		1400±100		1400
IDLE PB(kPa)/Gair(g/sec)		7 [REDACTED]		69.1/0.91
ENG OIL量		[REDACTED]		
[REDACTED]		[REDACTED]		
[REDACTED]		[REDACTED]		
[REDACTED]		[REDACTED]		

[REDACTED]

CBR250R (MC41





	[Redacted]	[Redacted]	[Redacted]
[Redacted]	[Redacted]	[Redacted]	[Redacted]
A/F	10.5	[Redacted]	13


4. [REDACTED]

ENTIRE PAGE CONTAINS BUSINESS CONFIDENTIAL INFORMATION

[REDACTED]










The main body of the page is completely obscured by a large black rectangular redaction. The redaction covers the entire content area, leaving only the header and footer information visible.



PE14-032

HNDA

12-19-2014



Q8 REDACTED

GQM_REDACTED

JAPANESE

Q8-3 - 518th GQM

report_Japanese_REDACTED





QIS: TH2WE2011085





< [REDACTED] > (2 [REDACTED])



[REDACTED]	[REDACTED]
<p>[REDACTED]</p> <p>[REDACTED]。</p>	<p>⇒P 3</p> <p>⇒P 8</p>



QIC



CBR250R MC41



USA		
-----	--	--




0.03%	2.7%	0.04%
-------	------	-------





USA:425mile(684), 882, :546

4.

		CBR250R (MC41 [REDACTED])																			
		SPEC	L	R																	
Tp,Cl (mm)	IN	0.16±0.03	0.18	0.18																	
	EX	0.27±0.03	0.26	0.26																	
[REDACTED]		<table border="1"> <tr> <td>IN</td> <td>20</td> <td>0</td> <td>EX</td> </tr> <tr> <td></td> <td>35</td> <td>40</td> <td></td> </tr> <tr> <td>(8.60)</td> <td></td> <td></td> <td>(8.30)</td> </tr> </table>	IN	20	0	EX		35	40		(8.60)			(8.30)	<table border="1"> <tr> <td>21.5</td> <td>3</td> </tr> <tr> <td>30.5</td> <td>40</td> </tr> <tr> <td>(8.45)</td> <td>(8.14)</td> </tr> </table>	21.5	3	30.5	40	(8.45)	(8.14)
IN	20	0	EX																		
	35	40																			
(8.60)			(8.30)																		
21.5	3																				
30.5	40																				
(8.45)	(8.14)																				
[REDACTED]		10.7±0.2	10.63																		
COMP (kPa)		1300	1294																		
IDLE [REDACTED]		1400±100	1400																		
IDLE PB(kPa)/Gair(g/sec)		72kpa [REDACTED] /0.90	69.1/0.91																		
ENG OIL量		[REDACTED]																			
[REDACTED]		[REDACTED]																			
[REDACTED]		[REDACTED]																			
[REDACTED]		[REDACTED]																			



4.



	[Redacted]	[Redacted]	[Redacted]
[Redacted]	[Redacted]	[Redacted]	[Redacted]
[Redacted]	[Redacted]	[Redacted]	[Redacted]

[Redacted]

[Redacted]

[Redacted]

[Redacted]

[Redacted]

4.

[REDACTED]

[REDACTED]

[REDACTED]






[REDACTED]


[REDACTED]

CBR							
kPa	c,3/min	kPa	c,3/min	kPa	c,3/min	kPa	c,3/min
11.78	254	10.52	206	/	/	7.13	74
20.01	436	19.99	395			10.89	129
50.03	1128	50.01	1025			20.03	237
CB							
kPa	c,3/min	kPa	c,3/min	kPa	c,3/min	kPa	c,3/min
10.51	4	10.99	24	7.39	90	7.94	175
20.86	9	21.02	53	10.26	114	10.86	231
50.24	21	50.04	139	20.11	236	20.09	434
CR							
kPa	c,3/min	kPa	c,3/min	kPa	c,3/min	kPa	c,3/min
/	/	/	/	/	/	6.94	237
						10.24	323
						20.38	566

値 : 50cm3/min(50kPa)

Eng_Assy. 50cm3/min(20kPa)






4.

[Redacted]


[Redacted]

[Redacted]



7. [REDACTED]

[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]	
[REDACTED]	[REDACTED]	26 ▼ [REDACTED]/Q1	9 ▽ Q2	16 ▽ Q[REDACTED]	
[REDACTED]	[REDACTED]	26 ▼ Q企	9 ▽ Q1-1[REDACTED]	[REDACTED] ▽ Q1-[REDACTED] 30 ▽ Q1~Q[REDACTED]	
[REDACTED]	[REDACTED]	11 15 ▼ ▼			
[REDACTED] [REDACTED] [REDACTED] [REDACTED]	HGA [REDACTED]	<p>CBR US [REDACTED]</p> <p>The diagram illustrates a network of relationships. At the top, 'CBR US' is connected to a series of entities. A dashed blue box encloses a central group of entities, with arrows indicating interactions between them. A large black redaction box covers a significant portion of the diagram, obscuring several entities and their connections. Arrows also point from the entities within the dashed box to other parts of the network.</p>			[REDACTED] [REDACTED] [REDACTED]
[REDACTED] [REDACTED] [REDACTED]	[REDACTED] [REDACTED]			▽ ▽ ▽	



PE14-032

HNDA

12-19-2014


Q8 REDACTED

GQM_REDACTED


JAPANESE

Q8-4 - 519th GQM

report_Japanese_REDACTED



QIC.NO : M11THM 054-00
M12THM 009-00
2HKO2012001-00



1 [REDACTED]

< [REDACTED])

[REDACTED]	[REDACTED]
1. [REDACTED] [REDACTED] [REDACTED]	[REDACTED]
[REDACTED] [REDACTED] [REDACTED]	[REDACTED]
[REDACTED] [REDACTED] [REDACTED] [REDACTED]	⇒ P 10


CBR250R QIC, Wty, TL, CR

[Redacted]	[Redacted]	[Redacted]
[Redacted]	[Redacted]	[Redacted]
[Redacted]	[Redacted]	[Redacted]
[Redacted]	[Redacted]	[Redacted]
[Redacted]	[Redacted]	[Redacted]
[Redacted]	[Redacted]	[Redacted]
[Redacted]	[Redacted]	[Redacted]
[Redacted]	[Redacted]	[Redacted]
[Redacted]	[Redacted]	[Redacted]
[Redacted]	102	56

[Redacted]

[Redacted]

[Redacted]



[Redacted]

[Redacted]

[Redacted]

[Redacted]

Date	YM	CR	TL	QIC	Model	Mile	Complaint
2012/5/21	2011	o			CBR250R	2000	[Redacted]
2012/7/6	2012	o			CBR250RA	?	[Redacted]
2012/4/30	2011		o		CBR250R	2,800	[Redacted]
2012/3/7	2011		o	M11THM054-00	CBR250R	450	[Redacted]
2012/4/19	2011		o		CBR250R	7785	[Redacted]
2012/5/22	2012		o		CBR250R	572	[Redacted]

Google™ Custom Search

Search

Total number of times topic has been viewed.

Total number of replies to this topic

NEW THREAD

1 of 15 1 2 3 11 > Last >

Threads in Forum : CBR250 Problems and Issues

Forum Tools

Search this Forum

Thread / Thread Starter	Rating	Last Post	Replies	Views
My CBR250's engine turns off when Downshifting!!! (1 2 3 ... Last Page) [Redacted]		Today 09:13 AM by cbrku	665	42,106
Unforced Stalling (1 2 3 ... Last Page) CBRNewbie [Redacted]		Today 12:59 PM by rrages	36	3,036
Cold Stall on first start...Help! (1 2 3) Mike323 [Redacted]		Yesterday 05:14 PM by TX_Dj	25	679
Engine shuts off on first start (1 2 3 ... Last Page) cbrlocal [Redacted]		07-08-2012 05:14 AM by Wynne G Oldman	45	1,988
stalling on cold start up (1 2) n [Redacted]		05-30-2012 02:34 PM by prittner	11	533
Engine stall on cold/first start r [Redacted]		05-26-2012 06:17 PM by cbrlocal	9	321
Engine snuts off when idling arter restart. (2012 CBR250R) R [Redacted]		05-04-2012 06:58 AM by Streetsville CBR Guy	9	496
Sometimes: engine stalls when downshifting to 1 while holding clutch (1 2 3 ... Last Page) p [Redacted]		04-09-2012 07:49 PM by jasinner	73	7,463

2、3

[REDACTED]	
[REDACTED]	
QIC	

CBR250R MC41 M [REDACTED]
[REDACTED]
[REDACTED]
[REDACTED]
M11THM 054-00 M12THM 009-00 2HKO2012001-00

[REDACTED]		
[REDACTED]		QIC
[REDACTED]		Wty.
[REDACTED]		TL
[REDACTED]		CR
[REDACTED]		
[REDACTED]		
[REDACTED]		

日本	USA	韓国	全世界
0 / 20	2 / 34	9 / 18	11 / 102
1 / 195	0 / 16	9 / 25	10 / 313
0 / 198	4 / 177	—	4 / 400
0 / 17	2 / 66	—	2 / 85
1	7	9	17
6,917	8,459	335	30,777
0.01	0.08	2.69	0.06

4. [REDACTED]

[REDACTED]

[REDACTED]

		CBR250R (MC41 [REDACTED])																									
		SPEC	L	R																							
Tp,Cl (mm)	IN	0.16±0.03	0.18	0.18																							
	EX	0.27±0.03	0.26	0.26																							
[REDACTED]		<table border="1"> <tr> <td>IN</td> <td>20</td> <td>0</td> <td>EX</td> </tr> <tr> <td></td> <td>35</td> <td>40</td> <td>(8.30)</td> </tr> <tr> <td>(8.60)</td> <td></td> <td></td> <td></td> </tr> </table>	IN	20	0	EX		35	40	(8.30)	(8.60)				<table border="1"> <tr> <td>IN</td> <td>21.5</td> <td>3</td> <td>EX</td> </tr> <tr> <td></td> <td>30.5</td> <td>40</td> <td>(8.14)</td> </tr> <tr> <td>(8.45)</td> <td></td> <td></td> <td></td> </tr> </table>	IN	21.5	3	EX		30.5	40	(8.14)	(8.45)			
IN	20	0	EX																								
	35	40	(8.30)																								
(8.60)																											
IN	21.5	3	EX																								
	30.5	40	(8.14)																								
(8.45)																											
[REDACTED]		10.7±0.2	10.63																								
COMP (kPa)		1300	1294																								
[REDACTED]		1400±100	1400																								
IDLE PB(kPa)/Gair(g/sec)		72kpa [REDACTED] 下 /0.90	69.1/0.91																								
ENG OIL量		[REDACTED]																									
[REDACTED]		[REDACTED]																									
[REDACTED]		[REDACTED]																									
[REDACTED]		[REDACTED]																									

[REDACTED]

4.

CBR250R (MC41

23~85°C

100km/h/7.000r/min

10°C



■

1,020r/min (A/F11.2)

■

(A/F~10.8


870r/min (A/F 10.8)

■

1,300r/min (A/F 11.5)

4.

CBR250R (MC41




	○	い ○	る ×		×
	900r/min	1,050r/min	980r/min	定)	970r/min
A/F	11.1	11.2	11.2		11.2
cm3/min (20kPa時)	236	79	434	1,564	1,700
	40N・m	48N・m	51N・m	35KN ⇒56N・m	60.5N・m
					EX 58.7 61.1 69.3 52.8

CBR250R

4.

FTA ()



CBR250R



-
-
-
-
-
-
-
-
-
-
-
-
-
-
-
-

A

4



CBR250R



5. [REDACTED]

[REDACTED]

[REDACTED]	[REDACTED]	CBR250R
ENG [REDACTED] [REDACTED] [REDACTED] [REDACTED]	[REDACTED]	[REDACTED]
ECU [REDACTED] [REDACTED]	[REDACTED]	[REDACTED]

[REDACTED]

内容	[Redacted]	CBR250R
[Redacted]	[Redacted]	
[Redacted]	[Redacted]	

7. [REDACTED]

日程		
6月	7月	8月
26 ▼ Q■/Q1	9 ▼ Q2	16 ▽ ■
26 ▼ ■	9 ▼ Q1-1■	16 ▽ Q1-■
31 ▽ Q1~Q■		
11 ▼ 15 ▼		
[REDACTED]		
▼	▽	
▼	▼	
▼	▼	
▼	▼	
	▽	
	▽	
	▽	



PE14-032

HNDA

12-19-2014


Q8 REDACTED

GQM_REDACTED

JAPANESE

Q8-5 - 520th GQM

report_Japanese_REDACTED



QIC.NO : M11THM 054-00
M12THM 009-00
2HKO2012001-00




Q1~Q

1. [Redacted]

[Redacted]

	[Redacted]	[Redacted]
1	[Redacted]	⇒P 9
2	[Redacted]	⇒P 7、14
3	[Redacted]	⇒7/20 ([Redacted])


2、3



CBR250R MC41



M11THM 054-00
M12THM 009-00
2HKO2012001-00



[Redacted]				
				QIC
				Wty.
				TL
				CR

[Redacted]	USA	[Redacted]	[Redacted]
0 / 20	2 / 34	9 / 18	11 / 102
1 / 195	0 / 16	9 / 25	10 / 313
0 / 198	4 / 177	—	4 / 400
0 / 17	2 / 66	—	2 / 85
1	7	9✖	17
6,917	8,459	335	30,777
0.01	0.08	2.69	0.06
[Redacted] °			



4.

		CBR250R (MC41)																
		SPEC	L	R														
Tp,Cl (mm)	IN	0.16±0.03	0.18	0.18														
	EX	0.27±0.03	0.26	0.26														
	<table border="1"> <tr> <td>IN</td> <td>20</td> <td>0</td> <td>EX</td> </tr> <tr> <td></td> <td>35</td> <td>40</td> <td>(8.30)</td> </tr> </table>	IN	20	0	EX		35	40	(8.30)	<table border="1"> <tr> <td>IN</td> <td>21.5</td> <td>3</td> <td>EX</td> </tr> <tr> <td></td> <td>30.5</td> <td>40</td> <td>(8.14)</td> </tr> </table>	IN	21.5	3	EX		30.5	40	(8.14)
IN	20	0	EX															
	35	40	(8.30)															
IN	21.5	3	EX															
	30.5	40	(8.14)															
	比	10.7±0.2	10.63															
	COMP (kPa)	1300	1294															
	IDLE ()	1400±100	1400															
	IDLE PB(kPa)/Gair(g/sec)		69.1/0.91															
	ENG OIL量																	

[Redacted]

CBR250R (MC41 [redacted])

23~85°C

100km/h / 7.000r/min

10°C



無し

1,020r/min (A/F 11.2)

する (A/F ~ 10.8 [redacted])


870r/min (A/F 10.8)

無し

1,300r/min (A/F 11.5)

4.




CBR250R (MC41



CBR250R

しない ○	—	する ×	—	する ×
—	しない ○	—	しない ○	しない ○
900r/min 11.1	—	980r/min 11.2	—	970r/min 11.2
—	1,050r/min 11.2	—	1,230r/min 11.8	1,160r/min 11.8
236	—	434	—	1,700
—	79	—	580	610
40N・m	48N・m	51N・m	54N・m	60.5N・m ()
				EX 58.7 61.1
				IN 69.3 52.8

4.



CAE [Redacted] 37.7kN

4.

[REDACTED]

[REDACTED]

[REDACTED]

CBR25

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]



内容

CBR250R

ENG

内容

(1)

内容

↑

↑

↑


↑


↑

(2)



51N・m

→48N・m





CBR250R



CBR250R

5.

[REDACTED]

[REDACTED]

[REDACTED]

CBR250R

[REDACTED]


[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED] CBR250R [REDACTED]

CBR250R



・M=0.4596
 [Redacted]

[Redacted]	[Redacted]	[Redacted]
1	0.0659	20
2	0.0906	28
3	0.1092	34
4	0.1246	38
5	0.1381	42
6	0.1501	46
7	0.1611	50
8	0.1713	53
9	0.1809	56
10	0.1899	58

・ CBR250R: [Redacted]

6. [REDACTED]

[REDACTED]

[REDACTED]

[REDACTED] CBR250 [REDACTED] [REDACTED]

[REDACTED]

(1) ENG [REDACTED] (C [REDACTED] BR250R)

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

CBR250R:0.06%)



PE14-032

HNDA

12-19-2014



Q8 REDACTED

GQM_REDACTED

JAPANESE

Q8-6 - 523th GQM

report_Japanese_REDACTED



1
2
3
4
5
6
7



QIC.NO : M11THM 054-00
M12THM 009-00
2HKO2012001-00

2012



1 [Redacted]

[Redacted]

	[Redacted]	[Redacted]
1	[Redacted]	[Redacted] P15
2	[Redacted]	[Redacted]
3	[Redacted]	⇒ P16

		CBR250R (MC41)			
		SPEC	L	R	
Tp,Cl (mm)	IN	0.16±0.03		0.18	
	EX	0.27±0.03		0.26	
		IN	20	0	EX
		(8.60)	35	40	(8.30)
		IN	21.5	3	EX
		(8.45)	30.5	40	(8.14)
		10.7±0.2		10.63	
COMP (kPa)		1300		1294	
IDLE		1400±100		1400	
IDLE PB(kPa)/Gair(g/sec)		72kpa以下 /0.90		69.1/0.91	
ENG OIL量					

CBR250R
CBR250R

CBR250R (MC41

23~85°C

100km/h / 7.000r/min

10°C




1,020r/min (A/F11.2)

870r/min (A/F 10.8)

1,300r/min (A/F 11.5)


CBR250R (MC41




CBR250R

		○	—	×	—	×						
		—	○	—	○	○						
		900r/min 11.1	—	980r/min 11.2	—	970r/min 11.2						
A/F		—	1,050r/min 11.2	—	1,230r/min 11.8	1,160r/min 11.8						
		236	—	434	—	1,700						
cm3/min (20kPa時)		—	79	—	580	610						
		40N·m	48N·m	51N·m	54N·m	60.5N·m						
						<table border="1"> <tr> <td>L</td> <td>R</td> </tr> <tr> <td>EX 58.7</td> <td>61.1</td> </tr> <tr> <td>IN 69.3</td> <td>52.8</td> </tr> </table>	L	R	EX 58.7	61.1	IN 69.3	52.8
L	R											
EX 58.7	61.1											
IN 69.3	52.8											



()






Q





	kgf·m	N·m
	5.5	54
	5.2	51
	4.9	48





CAE [redacted]
 [redacted]
 [redacted]
 CAE [redacted]

CBR250R < >





		CBR250R	
		L	R
EX		58.7	61.1
IN		69.3	52.8

[Redacted box]



[Redacted box]




内容

CBR250R





(2)
ENG [redacted]
[redacted]



▪ CBR250R: (2) ENG [redacted]

CBR250R




5.


CBR250R

ENG

CBR250R



CBR250R



• $M = 0.4596$
 [Redacted]

[Redacted]	[Redacted]	[Redacted]
1	0.0659	20
2	0.0906	28
3	0.1092	34
4	0.1246	38
5	0.1381	42
6	0.1501	46
7	0.1611	50
8	0.1713	53
9	0.1809	56
10	0.1899	58

[Redacted]
 • CBR250R [Redacted]

[REDACTED]

[REDACTED]



[REDACTED]

[REDACTED]

CBR250R
















[REDACTED]


[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[Redacted]	[Redacted]	[Redacted]					' 13		
		6 [Redacted]	7 [Redacted]	8 [Redacted]	9 [Redacted]	10 [Redacted]	9 [Redacted]		
GQ [Redacted]	[Redacted]	26 	9 	16 	31 	20 	27 		
[Redacted] ト	[Redacted]	11 	15 						
[Redacted]	HGA [Redacted]								
[Redacted]	[Redacted]								
[Redacted]	[Redacted]								
CBR250R [Redacted]	HGA [Redacted]					[Redacted]	[Redacted]		



PE14-032

HNDA

12-19-2014



Q8 REDACTED

GQM_REDACTED

JAPANESE

Q8-7 - 524th GQM

report_Japanese_REDACTED



QIC.NO : M11THM 054-00
M12THM 009-00
M12THM 009-01
2HKO2012001-00

2012 [redacted]
[redacted] 4回GQM
Q [redacted]

1. [Redacted]

[Redacted]

[Redacted]	[Redacted]
1	⇒P14
2	<p>Application Request, Supplement to Mfg., HS & HB</p> <p>[Redacted]</p>


		CBR250R (MC41)																									
		SPEC	L	R																							
Tp,Cl (mm)	IN	0.16±0.03	0.18	0.18																							
	EX	0.27±0.03	0.26	0.26																							
		<table border="1"> <tr> <td>IN</td> <td>20</td> <td>0</td> <td>EX</td> </tr> <tr> <td></td> <td>35</td> <td>40</td> <td>(8.30)</td> </tr> <tr> <td></td> <td>(8.60)</td> <td></td> <td></td> </tr> </table>	IN	20	0	EX		35	40	(8.30)		(8.60)			<table border="1"> <tr> <td>IN</td> <td>21.5</td> <td>3</td> <td>EX</td> </tr> <tr> <td></td> <td>30.5</td> <td>40</td> <td>(8.14)</td> </tr> <tr> <td></td> <td>(8.45)</td> <td></td> <td></td> </tr> </table>	IN	21.5	3	EX		30.5	40	(8.14)		(8.45)		
IN	20	0	EX																								
	35	40	(8.30)																								
	(8.60)																										
IN	21.5	3	EX																								
	30.5	40	(8.14)																								
	(8.45)																										
		10.7±0.2	10.63																								
	COMP (kPa)	1300	1294																								
	IDLE (r/min)	1400±100	1400																								
	IDLE PB(kPa)/Gair(g/sec)	72kpa以下 /0.90	69.1/0.91																								
	ENG OIL量																										

CBR250R (MC41

23~85°C

100km/h / 7.000r/min

10°C




1,020r/min (A/F11.2)

870r/min (A/F 10.8)

1,300r/min (A/F 11.5)

CBR250R (MC41











1,000r/min





CBR250R
 ()







○	—	×	—	×						
—	○	—	○	○						
900r/min 11.1	—	980r/min 11.2	—	970r/min 11.2						
—	1,050r/min 11.2	—	1,230r/min 11.8	1,160r/min 11.8						
236	—	434	—	1,700						
—	79	—	580	610						
40N·m	48N·m	51N·m	54N·m	60.5N·m ()						
				<table border="1"> <tr> <td>L</td> <td>R</td> </tr> <tr> <td>EX 58.7</td> <td>61.1</td> </tr> <tr> <td>IN 69.3</td> <td>52.8</td> </tr> </table>	L	R	EX 58.7	61.1	IN 69.3	52.8
L	R									
EX 58.7	61.1									
IN 69.3	52.8									




	kgf·m	N·m
	5.5	54
	5.2	51
	4.9	48








250R



5.



CBR250R




(2)





1

2



CBR250R



5.

[Redacted]



[Redacted]

[Redacted]


[Redacted]	[Redacted]	CBR250R
[Redacted]		<div data-bbox="1595 492 2040 578" style="border: 1px solid black; padding: 5px;">[Redacted]</div>
[Redacted] 換	[Redacted]	←

[Redacted] CBR250R [Redacted]


[Redacted]



[Redacted]



CBR250R




• $M = 0.4596$
 [Redacted]

[Redacted]	[Redacted]	[Redacted]
1	0.0659	20
2	0.0906	28
3	0.1092	34
4	0.1246	38
5	0.1381	42
6	0.1501	46
7	0.1611	50
8	0.1713	53
9	0.1809	56
10	0.1899	58

• CBR250R [Redacted]

6.



							'13
		6	7	8	9	10	9
[REDACTED]	[REDACTED]	26	9	16	31		
	[REDACTED]	[REDACTED]	Q [REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]
	[REDACTED]	[REDACTED]					
	HGA	[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]
	[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]
[REDACTED]	[REDACTED]						
[REDACTED]	[REDACTED]						
CBR250R	HGA						[REDACTED]

[REDACTED]

[REDACTED]



PE14-032

HNDA

12-19-2014



Q8 REDACTED

GQM_REDACTED

JAPANESE

Q8-8 - 525th GQM

report_Japanese_REDACTED



1
2
3
4
5
6
7



QIC.NO : M11THM 054-00
M12THM 009-00
M12THM 009-01
2HKO2012001-00

2012



1 [REDACTED]

< [REDACTED])

1	[REDACTED]	
1	[REDACTED]	o
2	[REDACTED]	
3	[REDACTED]	
4	[REDACTED]	
[REDACTED]	[REDACTED]	

CBR250R (MC41

23~85°C

100km/h / 7.000r/min

10°C




1,020r/min (A/F11.2)









870r/min (A/F 10.8)

1,300r/min (A/F 11.5)



CBR250R (MC41





○	—	×	—	×						
—	○	—	い	○						
900r/min 11.1	—	980r/min 11.2	—	970r/min 11.2						
—	1,050r/min 11.2	—	1,230r/min 11.8	1,160r/min 11.8						
236	—	434	—	1,700						
—	79	—	580	610						
40N·m	48N·m	51N·m	54N·m	60.5N·m						
				<table border="1"> <tbody> <tr> <td>L</td> <td>R</td> </tr> <tr> <td>EX 58.7</td> <td>61.1</td> </tr> <tr> <td>IN 69.3</td> <td>52.8</td> </tr> </tbody> </table>	L	R	EX 58.7	61.1	IN 69.3	52.8
L	R									
EX 58.7	61.1									
IN 69.3	52.8									







	kgf·m	N·m
[Redacted]	5.5	54
[Redacted]	5.2	51
[Redacted]	4.9	48









[Redacted text block]








AND



CBR250R



CBR250R






EN [redacted]


[redacted]



[redacted] CBR250R [redacted]



CBR250F
76.0
9.1
M10X1.25
12.9
42
48



5. [Redacted] [Redacted]



[Redacted]

[Redacted]


[Redacted].

[Redacted]

[Redacted]



OK.



1	0.0659	20
2	0.0906	28
3	0.1092	34
4	0.1246	38
5	0.1381	42
6	0.1501	46
7	0.1611	50
8	0.1713	53
9	0.1809	56
10	0.1899	58

