



U.S. Department
of Transportation

**National Highway
Traffic Safety
Administration**

Memorandum

Subject: Addition to File

Date: May 27, 2015

From: Evan Frings, Vehicle Integrity Division

Reply to
Attn of:

To: File RQ15-003

Thru: Scott Yon, Chief Vehicle Integrity Division

This memo documents a revision that was made to the opening resume of RQ15-003 to correct a clerical error. When the opening resume was originally released, it incorrectly stated that the number of fires reported by customers was 0. The actual number of fires reported is 8 and the opening resume was changed to reflect that specifically in the Failure Report Summary table. The original opening resume is attached for reference.



U.S. Department
of Transportation

**National Highway
Traffic Safety
Administration**

ODI RESUME

Investigation: RQ 15-003

Date Opened: 05/01/2015

Investigator: Evan Frings

Reviewer: Scott Yon

Approver: Otto Matheke

Subject: Headliner Fires

MANUFACTURER & PRODUCT INFORMATION

Manufacturer: Chrysler (FCA US LLC)

Products: 2011-2014 Jeep Grand Cherokee and Dodge Durango

Population: 661,888

Problem Description: A headliner fire may occur near either one of the vehicle's sun visors due to an electrical shorting condition in the vanity lamp wiring.

FAILURE REPORT SUMMARY

	ODI	Manufacturer	Total
Complaints:	8	TBD	TBD
Crashes/Fires:	0	TBD	TBD
Injury Incidents:	0	TBD	TBD
Number of Injuries:	0	TBD	TBD
Fatality Incidents:	0	TBD	TBD
Number of Fatalities:	0	TBD	TBD

ACTION / SUMMARY INFORMATION

Action: Open a Recall Query (RQ).

Summary:

On July 1st, 2014 Chrysler (FCA US LLC) issued safety recall 14V-391 to remedy a wiring-related fire hazard on the headliner of approximately 661,888 model year (MY) 2011-2014 Jeep Grand Cherokee and Dodge Durango vehicles manufactured between January 5, 2010 and December 11, 2013. The recall was in response to the Office of Defects Investigation (ODI) investigation EA14-001 during which data provided by Chrysler indicates that the fire is caused by an electrical short in the vanity lamp wiring for either one of the sun visors mounted on the vehicle. The sun visors are mounted to the roof of the vehicle through the headliner with three metal screws. EA14-001 determined that was possible for the sun visor wiring to be pierced by one of these screws, or otherwise electrically shorted either during initial vehicle assembly or later headliner area repairs which may cause an electrical short potentially resulting in fire. Most of the fires occurred while the vehicle was being driven.

The remedy Chrysler developed consists of a plastic guide way installed on each sun visor that routes the wiring away from the attachment screws preventing the wiring from being shorted. In order to install the guide way, the headliner must be lowered and the existing sun visor and headliner wiring is rerouted through the guide way and reinstalled. ODI has received 8 reports of fires occurring after the remedy was installed, with some occupants complaining of smoke sometimes followed by flames erupting in the headliner. No crashes or injuries were alleged in the post remedy fires.

A recall query has been opened to investigate the effectiveness of the remedy for recall 14V-391. The ODI reports cited above can be reviewed at <http://www-odi.nhtsa.dot.gov/owners/SearchSafetyIssues> under the following identification numbers: 10703058, 10692710, 10691520, 10684130, 10653417, 10711836, 10705802, and 10640524.

--