

U.S. Department of Transportation

National Highway Traffic Safety Administration

ODI RESUME

Investigation: PE 15-010

Date Opened: 03/24/2015

Investigator: Evan Frings

Approver: Frank Borris

Subject: Air Bag Clockspring Failure

Reviewer: Scott Yon

MANUFACTURER & PRODUCT INFORMATION

Manufacturer: Volkswagen Group of America, Inc.

Products: 2012 Volkswagen Passat and CC

Population: 30,000 (Estimated)

Problem Description: Failure of steering wheel clock spring/steering column control module (SCCM) potentially

resulting in improper function of the driver air bag.

FAILURE REPORT SUMMARY

TAILBRE RELIGITION OF THE PROPERTY OF THE PROP			
	ODI	Manufacturer	Total
Complaints:	9	TBD	TBD
Crashes/Fires:	0	TBD	TBD
Injury Incidents:	0	TBD	TBD
Number of Injuries:	0	TBD	TBD
Fatality Incidents:	0	TBD	TBD
Number of Fatalities:	0	TBD	TBD

ACTION / SUMMARY INFORMATION

Action: Open this Preliminary Evaluation.

Summary:

ODI has received a total of 9 reports from consumers alleging steering wheel clock spring/steering column control module (SCCM) failures in 2012 Volkswagen Passat and CC models. The SCCM is a module within the steering column that incorporates a spiral conductor (a ribbon cable) to electrically connect the steering wheel to the vehicle's electrical system while allowing for the turning of the steering wheel. Typical steering wheel mounted electrical components include the air bag as well as the horn and other electronic controls for such things as the radio. A failure of the SCCM results in a loss of connectivity of the steering wheel electrical devices to the rest of the vehicle, potentially affecting the performance of the driver side air bag, as well as the other steering wheel mounted components.

Consumer reports indicate that failures occur during normal driving conditions and are sometimes accompanied by an audible noise from the steering column. When the SCCM fails, an air bag warning light is illuminated on the dash of the vehicle. If a vehicle with a failed SCCM were to be involved in a crash of sufficient severity to require deployment, the driver air bag may not deploy properly.

NHTSA is opening this investigation to assess the scope, frequency, and consequence of the alleged defect.

The ODI reports cited above can be reviewed at www-odi.nhtsa.dot.gov/owners/SearchSafetyIssues under the following identification (ODI) numbers; 10691906, 10683944, 10682136, 10672715, 10670517, 10669312, 10628549, 10575783, 10552113.

Investigation: PE 15-010 Open Resume Page 1 of 1