

INFORMATION Redacted PURSUANT TO THE  
FREEDOM OF INFORMATION ACT (FOIA), 5 U.S.C. 552  
(B)(6)

# LD Spectra OCS Warranty Return Part Inspection Results

---

2015.10.07

Kia Quality Division  
Quality Assurance Team 2

# ■ OCS Warranty Return Part Inspection Summary & Results

## 1. Inspection Summary – To analyze the cause of Airbag Warning Light ON by inspecting OCS Warranty Return Parts

<b>What was inspected</b>	4 of KMA's recent (Sep. 2015) warranty return parts and 3 of VOQ parts – total 7 pieces
<b>Date / Location</b>	10/5 ~ 10/7/2015 / USA (KMA)
<b>Inspectors</b>	KMC Quality Assurance Team 2 (Manager, Min-Soo Kim), KMC Chassis Engineering Improvement Team (Sr. Engineer, Jae-Seung Song), KMC Electronics Improvement Team 2 (Asst. Manager, Wan-Hyun Baek)
<b>Inspection Method</b>	Visual Inspection on the damaged area of OCS Mat and Microscopic Inspection for detailed analysis on the damage patterns




## 2. Inspection Results

1. Shape/Form of damage: OCS circuit was damaged by repeated weight pressure on small affected areas or by sharp-edged objects
2. Damage Location: Each inspected part had different locations of damage

Damage by repeated weigh pressure on small area	Damage by sharp-edged objects	

# ■ Circuit Disconnection Location by Inspected Parts





Return Part #	VIN	# of Circuit Breakages
①	KNAFE222X95 [REDACTED] (47,373 mile)	2
②	KNAFE161085 [REDACTED] (74,562 mile)	2
③	KNAFE221295 [REDACTED] (96,452 mile)	3
④	KNAFE222695 [REDACTED] (82,239 mile)	3
⑤	KNAFE241295 [REDACTED] (54,300 mile)	1
⑥	KNAFE161485 [REDACTED] (76,687 mile)	1
⑦	KNAFE241995 [REDACTED] (50,000 mile)	1



# ※ Return Part Inspection Result Summary

NO	VIN	MY	Retail Date	Repair Date	Months in Service	Mileage	NHTSA VOQ#	Inspection Results
1	KNAFE222X95 [REDACTED]	2009	7/14/2009	7/30/2015	72.5	47,373	N/A	<ul style="list-style-type: none"> <li>Determined as repeated weight pressure focused on a certain area by small-size object(s) damaged the mat sensor circuit</li> </ul>
2	KNAFE161085 [REDACTED]	2008	9/2/2008	6/8/2015	81.2	74,562	N/A	
3	KNAFE221295 [REDACTED]	2009	4/27/2009	9/2/2015	76.2	95,452	N/A	<ul style="list-style-type: none"> <li>Determined as repeated weight pressure focused on a certain area by angular object(s) damaged the mat sensor circuit</li> </ul>
4	KNAFE222695 [REDACTED]	2009	3/16/2009	5/28/2015	74.4	82,239	10712140	<ul style="list-style-type: none"> <li>Determined as repeated weight pressure focused on a certain area by small-size object(s) damaged the mat sensor circuit</li> <li>Identified scratch mark by sharp &amp; pointy object(s) which possibly damaged the mat sensor circuit</li> </ul>
5	KNAFE241295 [REDACTED]	2009	12/19/2008	7/21/2015	79.1	54,300	N/A	<ul style="list-style-type: none"> <li>Determined as direct weight pressure by small-size object(s) cracked the mat sensor circuit</li> <li>Determined that damages started at crack are due to repeated weight pressure on the damaged area</li> </ul>
6	KNAFE161485 [REDACTED]	2008	3/24/2008	5/2/2015	85.3	76,687	10705387	<ul style="list-style-type: none"> <li>Determined as direct weight pressure focused on a certain area by small-size object(s) distorted and damaged the mat sensor circuit</li> </ul>
7	KNAFE241995 [REDACTED]	2009	4/22/2009	9/12/2015	76.7	50,000	10607838	<ul style="list-style-type: none"> <li>Determined as direct weight pressure focused on a certain area by angular object(s) damaged the mat sensor circuit</li> </ul>



※ Detailed Results of each Part Inspected

No.	Vehicle Info	Damage Location	Inspection Results
1	KNAFE222X95 (47,373 mile)		<ul style="list-style-type: none"> <li>• Determined as repeated weight pressure focused on a certain area by small-size object(s) damaged the mat sensor circuit                      - Inner-side was damaged first → expanded to outer-side</li> </ul>
2	KNAFE161085 (74,562 mile)		<ul style="list-style-type: none"> <li>• Determined as repeated weight pressure focused on a certain area by small-size object(s) damaged the mat sensor circuit                      - Inner-side was damaged first → expanded to outer-side</li> </ul>


※ Detailed Results of each Part Inspected

No.	Vehicle Info	Damage Location	Inspection Results
3	KNAFE221295 (96,452 mile)		<ul style="list-style-type: none"> <li>• Determined as repeated weight pressure focused on a certain area by angular object(s) damaged the mat sensor circuit                      - Inner-side was damaged first → expanded to outer-side</li> </ul>
4	KNAFE222695 (82,239 mile)		<ul style="list-style-type: none"> <li>• Determined as repeated weight pressure focused on a certain area by small-size object(s) damaged the mat sensor circuit                      - Inner-side was damaged first → expanded to outer-side</li> <li>• Identified scratch mark by sharp &amp; pointy object(s) which possibly damaged the mat sensor circuit</li> </ul>

※ Detailed Results of each Part Inspected

No.	Vehicle Info	Damage Location	Inspection Results
5	KNAFE24129 (54,300 mile)		<ul style="list-style-type: none"> <li>• Determined as direct weight pressure by small-size object(s) cracked the mat sensor circuit</li> <li>• Determined that damages started at crack are due to repeated weight pressure on the damaged area                             <ul style="list-style-type: none"> <li>- Inner-side was damaged first → expanded to outer-side</li> </ul> </li> </ul>
6	KNAFE161485 (76,687 mile)		<ul style="list-style-type: none"> <li>• Determined as direct weight pressure focused on a certain area by small-size object(s) distorted and damaged the mat sensor circuit                             <ul style="list-style-type: none"> <li>- V-shaped distortion observed around the damaged area</li> </ul> </li> </ul>

※ Detailed Results of each Part Inspected

No.	Vehicle Info	Damage Location	Inspection Results
7	KNAFE241995 (50,000 mile)		<ul style="list-style-type: none"> <li>Determined as direct weight pressure focused on a certain area by angular object(s) damaged the mat sensor circuit</li> <li>- Straight-line shaped damage</li> </ul>

**KOREAN  
DOCUMENT**

# LD Spectra OCS 고품분석 결과 보고

---

2015.10.07

기아 품질사업부  
품질보증2팀

# ■ OCS 고품 분석 개요 및 결과

## 1. 출장 조사 개요 - LD Spectra OCS 고품 분석하여 경고등 점등 원인 조사

분석 대상	KMA에서 최근 수거한 고품 (4개) 및 VOQ part (3개), 총 7개
일정 / 장소	'15.10/5 ~ 7 / 미국(KMA)
참석부문	품질보증2팀(김민수 과장), 사시설계개선팀(송재승 책임), 전자개선2팀(백완현 대리)
조사 방법	OCS MAT 파손부위 육안 검사 및 현미경 사용하여 세부 파손유형 분석



## 2. 고품 분석 결과

1. 파손 현상 : 국소 집중 하중 및 날카로운 물체에 의한 OCS 회로 파손
2. 발생위치 : 고품마다 파손 위치 상이

국소 집중하중에 의한 파손	날카로운 물체에 의한 파손	
		

고품별 단선 발생부위











고품 NO	VIN	회로 단선 (발생 개수)
①	KNAFE222X95 [REDACTED] (47,373 mile)	2
②	KNAFE161085 [REDACTED] (74,562 mile)	2
③	KNAFE221295 [REDACTED] (96,452 mile)	3
④	KNAFE222695 [REDACTED] (82,239 mile)	3
⑤	KNAFE241295 [REDACTED] (54,300 mile)	1
⑥	KNAFE161485 [REDACTED] (76,687 mile)	1
⑦	KNAFE241995 [REDACTED] (50,000 mile)	1

## ※ 고품 조사 결과 요약

NO	VIN	MY	판매일	수리일	주행기간 (개월)	주행거리 (mile)	NHTSA VOQ#	분석결과
1	KNAFE222X95 [REDACTED]	2009	'09.7/14	'15.7/30	72.5	47,373	없음	<ul style="list-style-type: none"> <li>• <u>면적이 좁은 물체가 특정 부위에 하중을 집중 시켜 매트 인장에 의한 파손</u> 판단됨</li> </ul>
2	KNAFE161085 [REDACTED]	2008	'08.9/2	'15.6/8	81.2	74,562	없음	
3	KNAFE221295 [REDACTED]	2009	'09.4/27	'15.9/2	76.2	95,452	없음	<ul style="list-style-type: none"> <li>• <u>각진 물체가 해당 부위에 하중을 집중 시켜 손상 및 인장에 의한 파손</u> 판단됨</li> </ul>
4	KNAFE222695 [REDACTED]	2009	'09.3/16	'15.5/28	74.4	82,239	10712140	<ul style="list-style-type: none"> <li>• <u>면적이 좁은 물체가 특정 부위에 하중이 집중되어 매트 인장에 의한 파손</u> 판단됨</li> <li>• <u>날카롭고 뾰족한 물체에 의한 굽힘 흔적</u>있으며 그로 인해 해당부 단선 발생 함</li> </ul>
5	KNAFE241295 [REDACTED]	2009	'08.12/19	15'.7/21	79.1	54,300	없음	<ul style="list-style-type: none"> <li>• <u>좁은 면적의 물체가 의해 직접적으로 하중을 받아 크랙발생</u></li> <li>• <u>크랙부위를 기점으로 반복적인 하중이 적용되어 파단된 것으로</u> 판단됨</li> </ul>
6	KNAFE161485 [REDACTED]	2008	'08.3/24	'15.5/2	85.3	76,687	10705387	<ul style="list-style-type: none"> <li>• <u>좁은 면적의 물체에 의해 직접적으로 하중을 받아, 뒤틀림에 의한 파손</u> 판단됨</li> </ul>
7	KNAFE241995 [REDACTED]	2009	'09.4/22	'15.9/12	76.7	50,000	10607838	<ul style="list-style-type: none"> <li>• <u>각진물체의 직접적인 하중 집중에 의해 손상</u> 판단됨</li> </ul>

※ 고품별 세부 분석 결과

No.	차량정보	고품 - 발생부위		분석내용
1	KNAFE222X95 (47,373 mile)		<div style="display: flex; justify-content: space-around;"> <div style="text-align: center;"> <p>매트 표면</p>  </div> <div style="text-align: center;"> <p>세부사진:반대면</p>  </div> </div> <div style="text-align: center; margin-top: 10px;"> <p>외력에 의한 파손흔적</p>  </div>	<ul style="list-style-type: none"> <li>면적이 좁은 물체가 특정 부위에 하중을 집중 시켜 매트 인장에 의한 파손 판단됨</li> <li>- 내측 최초 파손 → 외측으로 전이</li> </ul>
2	KNAFE161085 (74,562 mile)		<div style="text-align: center; margin-bottom: 10px;"> <p>외력에 의한 파손흔적</p>  </div> <div style="display: flex; justify-content: space-around;"> <div style="text-align: center;">  </div> <div style="text-align: center;">  </div> </div>	<ul style="list-style-type: none"> <li>면적이 좁은 물체가 특정 부위에 하중을 집중 시켜 매트 인장에 의한 파손 판단됨</li> <li>- 내측 최초 파손 → 외측으로 전이</li> </ul>

※ 고품별 세부 분석 결과

No.	차량정보	고품 - 발생부위	분석내용
3	KNAFE221295 (96,452 mile)		<ul style="list-style-type: none"> <li>• <u>각진 물체가 해당 부위에 하중을 집중 시켜 손상 및 인장에 의한 파손</u> 판단됨                      - 내측 최초 파손 → 외측으로 전이</li> </ul>
4	KNAFE222695 (82,239 mile)		<ul style="list-style-type: none"> <li>• <u>면적이 좁은 물체가 특정 부위에 하중이 집중되어 매트 인장에 의한 파손</u> 판단됨                      - 내측 최초 파손 → 외측으로 전이</li> </ul>
			<ul style="list-style-type: none"> <li>• <u>날카롭고 뾰족한 물체에 의한 굽힘 흔적 있으며</u> 그로인해 해당부 단선 발생 함</li> </ul>

※ 고품별 세부 분석 결과

No.	차량정보	고품 - 발생부위	분석내용
5	KNAFE241295 (54,300 mile)		<ul style="list-style-type: none"> <li>• 좁은 면적의 물체가 의해 직접적으로 하중을 받아 크랙발생</li> <li>• 크랙부위를 기점으로 반복적인 하중이 적용되어 파단된 것으로 판단됨                         <ul style="list-style-type: none"> <li>- 내측 최초 파손 → 외측으로 전이</li> </ul> </li> </ul>
6	KNAFE161485 (76,687 mile)		<ul style="list-style-type: none"> <li>• 좁은 면적의 물체에 의해 직접적으로 하중을 받아, 뒤틀림에 의한 파손 판단됨                         <ul style="list-style-type: none"> <li>- 꺾임시 발생하는 v형태의 파단모양</li> </ul> </li> </ul>

※ 고품별 세부 분석 결과

No.	차량정보	고품 - 발생부위	분석내용
7	KNAFE241995 (50,000 mile)	 <p>The image shows a red metal component with a grid-like pattern. A red box highlights a specific area, which is magnified in a central inset. This inset shows a crack in a metal surface. A further magnified view on the right shows the crack in detail, with a red dashed circle around it. A yellow box with a blue border contains the text '외력에 의한 파손흔적' (Damage mark due to external force).</p>	<ul style="list-style-type: none"> <li>• <u>각진물체의 직접적인 하중 집중에 의해 손상 판단됨</u>                      - 파단 현상이 일자현상</li> </ul>