



U.S. Department
of Transportation

**National Highway
Traffic Safety
Administration**

ODI RESUME

Investigation: PE 21-011
Date Opened: 05/13/2021
Investigator: Ryan Rahimpour
Approver: Stephen Ridella
Subject: Alternator Front Bearing Failure

Date Closed: 10/03/2022
Reviewer: Joshua Neff

MANUFACTURER & PRODUCT INFORMATION

Manufacturer: Volvo Bus Corporation, PREVOST CAR, INCORPORATED, Prevost Car (US) Inc.
Products: 2010-2023 Prevost H3, X3 and 2020 Volvo 9700
Population: 6,688

Problem Description: An alternator front bearing fails, elevating the temperature within the engine compartment, resulting in activation of the fire suppression system, which shuts down the bus.

FAILURE REPORT SUMMARY

	ODI	Manufacturer	Total
Complaints:	0	0	0
Crashes/Fires:	0	0	0
Injury Incidents:	0	0	0
Fatality Incidents:	0	0	0
Other*:	0	Confidential	Confidential
*Description of Other: EWR Data			

ACTION / SUMMARY INFORMATION

Action: This PE is closed. See safety recalls 22V-221 and 22V-222.

Summary:

NHTSA's Office of Defects Investigation (ODI) opened a Preliminary Evaluation after reviewing field reports concerning alternator front bearing failures that cause elevated temperatures within the engine compartment, resulting in the fire suppression system (FSS) activating, immediately shutting the engine down, and rendering the bus inoperable.

Analysis of the data provided by Prevost Car (US) Inc. showed high failure frequency and thermal events. An immediate shutdown of the bus can increase the risk of a crash or injury of bus occupants.

In response to this investigation, Prevost Car (US) Inc. and Volvo Bus Corporation decided to conduct recalls 22V-221 and 22V-222. By submitting Part 573 Defect Information Reports on April 6, 2022, Prevost Car (US) Inc. and Volvo Bus Corporation notified ODI of a safety defect in certain model year (MY) 2010-2023 Prevost H3-45; X3-45; X3-45 Com; H3-45 VIP; X3-45 VIP and 2020 Volvo 9700 vehicles; some of these buses may have experienced thermal events after failure of the alternator front bearing, because the alternator belt continues to turn the alternator after the bearing failure.

These recall actions address the safety concern that led to the opening of this investigation.

Therefore, with these recall actions, this investigation is closed. The recalls encompass all model and MY vehicles addressed by the investigation. However, the closing of this investigation does not constitute a finding by NHTSA that a safety-related defect does not exist in other model or MY vehicles outside of the recall scope. The agency reserves the right to take further action if warranted by the circumstances.

--