



Eaton Corporation
Vehicle Group-Materials CoE
19218 B Drive South
Marshall, Michigan 49068
269/781-0200

Materials and Basic Processes Report

MAT # 21279_07515
Prepared By E. Vincent
Work Done By D. Osborne
Date 13 Oct. 2021
Pages 1 of 5

Background:

Ford returned 1 intake valve (P/N 372237) fractured thru the 3rd keeper groove. The valve was in the intake cylinder #5 position from VIN# 2FMPK4AP5 [REDACTED] with 388miles. The valve was returned from the Capital Ford dealership. The intake valve date code is 21-C-1.

Objective:

1. Document tip contact, OD, and keeper groove.
2. Analyze fracture surface and document crack initiation site and fracture mode.
3. Perform Ford microhardness profile on a longitudinal tip section.
4. Document surface and core microstructure at the fracture.

Findings:

1. The valve tip fractured in the third keeper groove via fatigue initiating at the keeper groove surface and propagating unidirectionally across ~90% of the tip cross-section. The tip chamfer exhibits contact damage coincident with the crack initiation.
2. The valve tip exhibits a typical hardness profile for induction hardened EMS-322. The average tip hardness at the core is 55 HRC converted from HV0.5. The average hardness at the left and right keeper grooves is 57&56 HRC respectively converted from HV0.5.
3. The valve tip microstructure consists of tempered martensite at the surface and core consistent for hardened and tempered EMS-322. The keeper groove surface shows evidence of grinder burn at the fracture location.

PROPRIETARY RIGHTS

Eaton Corporation claims proprietary rights to the information in this document. This document is not to be reproduced, disclosed to a third party, or used in the manufacture of any product without the written permission of the Chief Engineer, Engineering Services and Material Development, of Eaton Corporation's Materials CoE.



Eaton Corporation
Vehicle Group-Materials CoE
19218 B Drive South
Marshall, Michigan 49068
269/781-0200

Materials and Basic Processes Report


MAT # 21279_07515
Prepared By E. Vincent
Work Done By D. Osborne
Date 13 Oct. 2021
Pages 2 of 5

a) Fracture Surface	b) Tip OD date code 21-C-1, arrows show orientation of chamfer damage and crack initiation
c) Keeper groove, typical contact	d) Tip contact, chamfer damage

Figure 1: Macro photographs of the intake valve tip fracture. The valve tip fractured in the third keeper groove via fatigue initiating at the keeper groove surface and propagating unidirectionally across ~90% of the tip cross-section. The tip chamfer exhibits contact damage coincident with the crack initiation.

PROPRIETARY RIGHTS

Eaton Corporation claims proprietary rights to the information in this document. This document is not to be reproduced, disclosed to a third party, or used in the manufacture of any product without the written permission of the Chief Engineer, Engineering Services and Material Development, of Eaton Corporation's Materials CoE.



PROPRIETARY RIGHTS

Eaton Corporation claims proprietary rights to the information in this document. This document is not to be reproduced, disclosed to a third party, or used in the manufacture of any product without the written permission of the Chief Engineer, Engineering Services and Material Development, of Eaton Corporation's Materials CoE.

Tip Hardness Profile




Figure 3: Tip hardness profile measured HV0.5 and converted to HRC. The valve tips exhibit a typical induction hardened profile.

Table 1: Microhardness measurements on the left and right keeper groove cross-sections measured HV0.5 and converted to HRC. The left and right keeper grooves exhibit typical hardness values.

		Left Side	Right Side
KG 1	56.5	55.5	
KG 2	55.6	56.3	
KG 3	57.7	56.3	

PROPRIETARY RIGHTS

Eaton Corporation claims proprietary rights to the information in this document. This document is not to be reproduced, disclosed to a third party, or used in the manufacture of any product without the written permission of the Chief Engineer, Engineering Services and Material Development, of Eaton Corporation's Materials CoE.



Eaton Corporation
Vehicle Group-Materials CoE
19218 B Drive South
Marshall, Michigan 49068
269/781-0200

Materials and Basic Processes Report

MAT # 21279_07515
Prepared By E. Vincent
Work Done By D. Osborne
Date 13 Oct. 2021
Pages 5 of 5




Figure 4: Etched micrographs on the longitudinal section thru the fractured valve tip. The valve tip microstructure consists of tempered martensite at the surface and core consistent for hardened and tempered EMS-322. The keeper groove surface shows evidence of grinder burn at the fracture location.

PROPRIETARY RIGHTS

Eaton Corporation claims proprietary rights to the information in this document. This document is not to be reproduced, disclosed to a third party, or used in the manufacture of any product without the written permission of the Chief Engineer, Engineering Services and Material Development, of Eaton Corporation's Materials CoE.