

THIS PAGE HAS BEEN SUPERSEDED OR DEACTIVATED



[REDACTED]

[REDACTED]

[REDACTED] **Update** [REDACTED]

This bulletin supersedes G0 [REDACTED] 4. Reason for update: Update the vehicle model years [REDACTED]

[REDACTED]

[REDACTED]
[REDACTED] Crown Victoria
[REDACTED]
[REDACTED]
[REDACTED]
[REDACTED]
[REDACTED]
[REDACTED]
[REDACTED]
[REDACTED]
[REDACTED]
[REDACTED]
[REDACTED]
[REDACTED]
[REDACTED]
[REDACTED]
[REDACTED] Motorhome Chassis / [REDACTED] Commercial Stripped Chassis
[REDACTED] Motorhome Chassis / [REDACTED] Commercial Stripped Chassis
[REDACTED]
[REDACTED]
[REDACTED]
[REDACTED]
[REDACTED] Fusion
[REDACTED]

2010-2019 Police Interceptor Sedan
2011-2020 Police Interceptor Utility
2019-2020 Ranger
2010-2019 Taurus
2008-2009 Taurus X
2014-2020 Transit
2008-2020 Transit Connect
Lincoln
2020 Aviator
2017-2020 Continental
2020 Corsair
2008 Mark LT
2015-2019 MKC
2009-2016 MKS
2010-2019 MKT
2008-2018 MKX
2008-2020 MKZ
2019-2020 Nautilus
2008-2020 Navigator
2008-2011 Town Car
Mercury
2008-2011 Grand Marquis / Marauder
2008-2011 Mariner
2008-2011 Milan
2008-2010 Mountaineer

Summary

This article supersedes GSB G0000184 to update the vehicle model years affected.

This bulletin is a guide to engine failure analysis and preventing repeat engine failure.

Service Information

Determining Root Cause

Understanding normal engine wear vs. actual engine damage can increase the accuracy of determining the root cause. If the true root cause of the engine failure is not identified with visual confirmation, an over repair or incomplete repair leading to repeat engine failure may result. Root cause determination and the extent of engine damage is necessary during engine assessment. Inspection areas include:

- Oil filter
- Oil pan
- Cylinder head and deck surfaces
- Camshaft bores, journals and lobes
- Crankshaft journals
- Cylinder walls and piston skirts
- Rod and main bearings

Engine Analysis

Metal in the Oil Pan, Filter and/or Screens – Acceptable Conditions

Some metal in the oil pan and filter is expected and considered normal (Figures 1-2).

Figure 1




||



Some metal [redacted] the oil filter are not a [redacted]
[redacted]



[REDACTED]
[REDACTED] Small specs of metal in the filter media is normal (Figure 4).
[REDACTED]



[REDACTED]

[REDACTED] paint is not a concern. Do not confuse with [REDACTED] bearing material.

metal in the Oil Pan, Filter and/or Screens – [REDACTED] Conditions

[REDACTED] chunks of metal in the pan and/or filter merit further root cause investigation (Figures 5-6).

[REDACTED]



11



Excessive amounts of metal in the oil filter and/or screens require further root cause investigation (Figures 7-8).

11






██████████
Camber, Valve, Journal and Lobe Inspection

██████████ Normal Wear: Polishing, discoloration, slight porosity or minor scoring (Figures 9-10).

██████████

#16, #17, #18, #19, #20, #21, #22, #23, #24, #25, #26, #27, #28, #29, #30, #31, #32, #33, #34, #35, #36, #37, #38, #39, #40, #41, #42, #43, #44, #45, #46, #47, #48, #49, #50, #51, #52, #53, #54, #55, #56, #57, #58, #59, #60, #61, #62, #63, #64, #65, #66, #67, #68, #69, #70, #71, #72, #73, #74, #75, #76, #77, #78, #79, #80, #81, #82, #83, #84, #85, #86, #87, #88, #89, #90, #91, #92, #93, #94, #95, #96, #97, #98, #99, #100



#014 #015 #016 #017 #018 #019 #020 #021 #022 #023 #024 #025 #026 #027 #028 #029 #030 #031 #032 #033 #034 #035 #036 #037 #038 #039 #040 #041 #042 #043 #044 #045 #046 #047 #048 #049 #050 #051 #052 #053 #054 #055 #056 #057 #058 #059 #060 #061 #062 #063 #064 #065 #066 #067 #068 #069 #070 #071 #072 #073 #074 #075 #076 #077 #078 #079 #080 #081 #082 #083 #084 #085 #086 #087 #088 #089 #090 #091 #092 #093 #094 #095 #096 #097 #098 #099 #100 #101 #102 #103 #104 #105 #106 #107 #108 #109 #110 #111 #112 #113 #114 #115 #116 #117 #118 #119 #120 #121 #122 #123 #124 #125 #126 #127 #128 #129 #130 #131 #132 #133 #134 #135 #136 #137 #138 #139 #140 #141 #142 #143 #144 #145 #146 #147 #148 #149 #150 #151 #152 #153 #154 #155 #156 #157 #158 #159 #160 #161 #162 #163 #164 #165 #166 #167 #168 #169 #170 #171 #172 #173 #174 #175 #176 #177 #178 #179 #180 #181 #182 #183 #184 #185 #186 #187 #188 #189 #190 #191 #192 #193 #194 #195 #196 #197 #198 #199 #200

[Redacted]

Cam-Bers - Dan

[Redacted] 11




11



#01a, #01b, #01c, #01d, #01e, #02a, #02b, #02c, #02d, #03a, #03b, #03c, #03d, #03e, #03f, #03g, #03h, #03i, #03j, #03k, #03L, #03m, #04a, #04b, #04c, #04d, #04e, #04f, #04g, #05a, #05b, #05c, #05d, #06a, #07a, #07b, #07c, #07d, #07e, #08a, #08b, #08c, #09, #10a, #10b, #11, #12, #13a, #13b, #13c, #13d, #13e, #14

██████████
██████████ Journals and Lobes - Normal Wear: Polishing, disco
██████████



11



1000122

1000122



[REDACTED]

Journals and Lobes – Damage: Material loss/transfer, deep scoring or bluing of the metal are all signs of damage (Figures 16-18).

[REDACTED]



11



Crankshaft and Bearing Inspection

Normal Wear: Polishing, discoloration, light scoring, light contact with red coating (Figures 19-22).

11





二

11





NOTE: Bearings are designed to manage some debris; therefore, some light scoring found on the bearing surface is not necessarily an indication of engine failure or root cause

metal transfer, erosion, material loss, coolant contamination, deep scoring, cracking, spun bearing (Figures 23-27).



II

11




11



11






[REDACTED]

[REDACTED] — Normal Wear: Discoloration, polishing, light scratches (Figures 28-29).

[REDACTED]



11



#01a, #01b, #01c, #01d, #01e, #02a, #02b, #02c, #02d, #03a, #03b, #03c, #03d, #03e, #03f, #03g, #03h, #03i, #03j, #03k, #03l, #03m, #04a, #04b, #04c, #04d, #04e, #04f, #04g, #05a, #05b, #05c, #05d, #06a, #07a, #07b, #07c, #07d, #07e, #08a, #08b, #08c, #09, #10a, #10b, #11, #12, #13a, #13b, #13c, #13d, #13e, #14

██████████ – Damage: Material loss, deep scoring, material transfer (Figures 30-32).

██████████



11



||



[REDACTED]

[REDACTED] and Block Surface Inspection

[REDACTED] and Block Surface – Normal Wear: Porosity outside sealing surfaces,

[REDACTED]

#01a, #01b, #01c, #01d, #01e, #02a, #02b, #02c, #02d, #03a, #03b, #03c, #03d, #03e, #03f, #03g, #03h, #03i, #03j, #03k, #03l, #03m, #04a, #04b, #04c, #04d, #04e, #04f, #04g, #05a, #05b, #05c, #05d, #06a, #07a, #07b, #07c, #07d, #07e, #08a, #08b, #08c, #09, #10a, #10b, #11, #12, #13a, #13b, #13c, #13d, #13e, #14




11



#01a, #01b, #01c, #01d, #01e, #02a, #02b, #02c, #02d, #03a, #03b, #03c, #03d, #03e, #03f, #03g, #03h, #03i, #03j, #03k, #03L, #03m, #04a, #04b, #04c, #04d, #04e, #04f, #04g, #05a, #05b, #05c, #05d, #06a, #07a, #07b, #07c, #07d, #07e, #08a, #08b, #08c, #09, #10a, #10b, #11, #12, #13a, #13b, #13c, #13d, #13e, #14

Head and Block Surface – Damage: Porosity on sealing surface




#01a, #01b, #01c, #01d, #01e, #02a, #02b, #02c, #02d, #03a, #03b, #03c, #03d, #03e, #03f, #03g, #03h, #03i, #03j, #03k, #03l, #03m, #04a, #04b, #04c, #04d, #04e, #04f, #04g, #05a, #05b, #05c, #05d, #06a, #07a, #07b, #07c, #07d, #07e, #08a, #08b, #08c, #09, #10a, #11, #12, #13a, #13b, #13c, #13d, #13e, #14





11



#01a, #01b, #01c, #01d, #01e, #02a, #02b, #02c, #02d, #03a, #03b, #03c, #03d, #03e, #03f, #03g, #03h, #03i, #03j, #03k, #03l, #03m, #04a, #04b, #04c, #04d, #04e, #04f, #04g, #05a, #05b, #05c, #05d, #06a, #07a, #07b, #07c, #07d, #07e, #08a, #08b, #08c, #09, #10a, #10b, #11, #12, #13a, #13b, #13c, #13d, #13e, #14

Cylinder Wall and Piston Skirt Inspection

Normal wear: Slight polishing and/or discoloration, vertical streaking, slight scoring, cross hatch present, light staining (Figures 38-40).

Abuse:

||






11

#01a, #01b, #01c, #01d, #01e, #02a, #02b, #02c, #02d, #03a, #03b, #03c, #03d, #03e, #03f, #03g, #03h, #03i, #03j, #03k, #03L, #03m, #04a, #04b, #04c, #04d, #04e, #04f, #04g, #05a, #05b, #05c, #05d, #06a, #07a, #07b, #07c, #07d, #07e, #08a, #08b, #08c, #09, #10a, #10b, #11, #12, #13a, #13b, #13c, #13d, #13e, #14

[REDACTED]

Cylinder Head [REDACTED] Deep gouging, impact marks, loss of


[REDACTED]



11



11



[REDACTED]

[REDACTED] Normal Wear: Light wear of the coating (Figures 44-45).

[REDACTED]



[REDACTED]

[REDACTED]



Skirt - scoring, severe wear




██████████

██████████



E336482

Figure 49



E336483

- Modifications (timing, CNG, incorrect spark plugs)
 - Overboost (supercharger/turbocharger)
 - PCM performance chip/programmer
- Lean conditions
 - Mass air flow (MAF) sensor failure
 - Damaged air intake

Effect: High cylinder pressure or spark knock

- Excessive combustion temperatures
- Excessive cylinder pressure
- Pre-ignition
- Excessive levels of detonation (low octane/poor fuel quality)

Damage: Piston and cylinder wall

- Spark plug electrode damage
- Hole in piston (pre-ignition)
- Piston ring land damage (detonation)

- Pitted piston face
- Cylinder wall scoring

Spark plug damage (porcelain fracture or melted electrode) is an indication of excess detonation (Figure 50)

Figure 50



Heat generated from friction can cause cylinder walls to crack. (upper ring land damage) (Figure 51)


Figure 51



E336485

Excess detonation causes excess cylinder pressure spikes leading to piston ring land fractures (second ring land is damaged). (Figure 52)

Figure 52



E336486

Cylinder Wall Damage (Figure 53)

Figure 53



Root Cause: Fuel/air mixture concerns

- Excess oil consumption
- Lean/rich conditions
- Cylinder misfire

Effect: Catalyst damage

- Catalyst material begins to deteriorate (turns to dust/sand)


- Catalyst material is pulled into the engine

Damage: Cylinder wall

- Cross hatch is polished away
- Vertical scoring
- Bearing damage may be present if catalyst material made it to the engine oil.

Check for catalyst debris by shaking out the converter onto a clean surface (Figure 54)

Figure 54



Catalyst material can collect on the sides of the piston damaging cylinder wall surfaces (Figure 55)

Figure 55



Valve Damage (Figures 56-57)

Figure 56



E336490

Figure 57



Root Cause: Lean condition

- Modification or damage to the air induction system

- MAF sensor damage/failure
- Lack of fuel to the cylinder

Effect: Excessive combustion chamber temperatures

- Misfire, lacks power
- Catalyst damage
- Running lean = hot cylinder

Damage: Valve and valve seat

- Valve tuliping
- Valve seat recession

(Figure 58)

Figure 58



E336492


If cylinder leakage is present past the valves:

- Check for valves held open by other valvetrain components
- Check for the valve stem sticking in the guide
- Inspect for debris between the valve and seat that could hold the valve open

Excessive lean conditions can cause valves to overheat and soften. Over time, the valve can stretch and deform against the seat causing the valve to “tulip” creating leakage and a misfire. Comparing total valve height of the suspect valve to a known good valve can help identify issues. A height difference in the suspect valve is an indication of valve tuliping. Valve tuliping is the effect, not the root cause of the concern.

Foreign Object Debris (Figure 59)

Figure 59



Root Cause: Combustion chamber damage

- Broken piston/rings
- Broken valves
- Dropped valve seats

Effect: Debris transfer


- Original intake manifold transferred to the new engine
- Intake manifolds cannot be cleaned in these instances and require replacement

Damage: Repeat engine failure

- Engine vacuum dislodges debris left in the manifold
- Debris will enter the combustion chamber and cause piston/cylinder damage

(Figure 60)

Figure 60



- Foreign object debris can cause metal transfer from the piston to the cylinder head
- This metal debris can also make it to the intake manifold
- The intake manifold must be replaced in these instances to prevent repeat damage

Bearing Damage (Figure 61)

Figure 61



E336640

Root Cause: PCV system concerns

- PCV system damaged
- Open breather tube in place of PCV valve
- Lack of oil maintenance

Effect: Oil consumption

- Oil is pulled through the engine and burned off

Damage: Bearing damage

- Bearing and journal damage from lack of lubrication
- An open breather tube fitting mistaken for a PCV valve could be transferred to the new engine leading to repeat bearing failure (Figure 62). During engine replacement, verify the PCV valve is operational and correct for the application.

Figure 62



E336642

NOTE: Remanufactured Modular 2V V8 and V10 engines do not come with a PCV valve installed. If there appears to be a valve/tube in place on a new Remanufactured 2V V8 or V10 engine, replace it.

Bent Connecting Rod (Figure 63)

Figure 63



E336643

Root Cause: Hydrolocking from liquid ingestion

- Leaking or stuck open fuel injector
- Water ingestion through the air inlet (wet, warped or damaged air filter)

Effect: Hydrolocking

- Liquid cannot be compressed and will prevent the piston from traveling to top dead center (TDC)

Damage: Connecting rod

- Connecting rod will bend or break
- May occur on more than one cylinder

(Figures 64-65)

Figures 64



Figure 65



E336645

- Since fluids cannot be compressed, the connecting rod typically suffers from a hydrolock event.