



May 8, 2007

SERVICE LETTER ML-425

NHTSA SAFETY RECALL CAMPAIGN # - 04V-218

IMPORTANT SAFETY RECALL CAMPAIGN INFORMATION!

Dear Dealer,

In a continuing effort to increase the completion rates of our safety recalls we have established a procedure to send follow-up notifications to the motorcycle owners of record who haven't had their motorcycles serviced in response to selected recalls. This communication and the attached sample Customer Letter relate to the following recall.

CODE 0114 XL's, DYNA's AND TOURING MODEL MOTORCYCLES BUILT BETWEEN JUNE 4, 2003 AND AUGUST 22, 2003 FOR DOMESTIC MODELS SEE CHART BELOW:


DYNA	XL	TOURING
FXD	XL 883	FLHT
FXDI	XL 883 Hugger	FLHTI
FXDL	XL 883C	FLHTC
FXDLI	XL 883R	FLHTCI
FXDWG	XL 1200	FLTRI
FXDWGI	XL 1200C	FLTR
FXDX	XL 1200R	FLHR
FXDXI	XL 1200S	FLHRI
FXDXT		FLHRCI
FXDP		FLHTPI
		FLHPI
		FLHPEI
		FLHTCSE
		FLHRSEI2
		FLHRS
		FLHRSI

This recall relates to the tail light bulb which could fall out of the socket, thereby rendering the tail light and the brake light inoperative. The recall was initiated in April 23, 2004. A sample of the follow-up letter, which we are sending to all registered owners of unserviced vehicles, is attached. Also attached is an updated list of Code 0114 vehicle VINs which our records show as still being unserviced. **Please refer to h-dnet.com on the Service Page, Safety Campaign and Product Campaign link, Safety Campaign and Open VIN lists link for an updated list of Code 0114 vehicle VINs which our records show as still being unserviced. Select the appropriate campaign number link (0114) to view any outstanding vehicles involved in this recall. Refer to Harley-Davidson Service Bulletin M-1153 dated May 27, 2004 for details on carrying out the requirements for this recall. Parts for the recall are currently available. Current shipment records indicate a number of kits are available in the field at the dealer level. Please check your inventory before placing any orders for parts. You may be required to provide a VIN for each recall kit ordered. Please refer to the related Service Bulletin for detailed instructions.**

If a VIN appears on the h-dnet.com list for a vehicle on which you have recently completed this recall, please disregard. **DO NOT** send in a duplicate service card. However, if a vehicle appears on the list that you know you have completed the recall on some time ago, please fill out a Dealer Service Card and attach a copy of your internal repair order to the card. We will use this information to update our records and issue you the appropriate amount of labor for performing the service. This information will be essential in reporting our completion rates to NHTSA, as required.

Your cooperation in this effort is appreciated.

Sincerely,



Sarah S. Ottallah
Manager, Warranty and Recall Administration
0114