

**DET-05-002** 

January 10, 2005

Mr. George H. Person Chief, Recall Management Division Office of Defects Investigation National Highway Traffic Safety Administration 400 Seventh Street, SW Washington, D.C. 20590

Subject:

2003 Isuzu Ascender Windshield Wiper System-

NVS-215lra 04V-061

Dear Mr. Person:

In response to your letter referenced above, Isuzu Manufacturing Services of America hereby replies that the quarterly reports for this campaign are the responsibility of General Motors Corporation, the manufacturer of the vehicle and the issuer of the Part 573 report (see Attachment 1).

Per your request, the 2004 third quarter campaign completion results for this campaign are shown in Attachment 2. In the future, quarterly campaign completion results will be submitted by General Motors Corporation.

If you have any questions or require additional information, please contact me at 734-582-9262 or Christine Ueno of my staff at 734-582-9260.

Sincerely,

Jeffery A. Marsee Chief Representative Emissions and Safety Isuzu Manufacturing Services of America, Inc

/cfu

Attachments

cc: Ms. Gay Kent, GM-Product Investigations

Ms. Kelly Schuler, NHTSA - Recall Mgt Division

February 2, 2004

04V-046 Oa®

S

Mr. K. N. Weinstein Associate Administrator for Safety Assurance National Highway Traffic Safety Administration 400 Seventh Street, S.W., Room 5321 Washinston, D.C. 20590

Dear Mr. Weinstein:

The following information is submitted pursuant to the requirements of 49 CFR 573.5 as it applies to a determination by General Motors of a safety defect involving certain 2002.05 model year Chevrolet Trailbiazer, GMC Envoy, Oldsmobile Brevada, and 2003 issue Ascentific models vehicles.

573.5(s)(1): Chevrolet, GMC, and Oldsmobile Divisions of General Motors Corporation and Isuzu Motors America, Inc.

573.8(a)(2)(3)(4); This Information is shown on the attached sheet.

578.6(a)(5); General Motors has decided to recall certain 2002 and 2003 model year Chevrolet Trailblazer, GMC Envoy, Oldemobile Bravada, and 2003 issuzu Ascender model vehicles. Some of these vehicles have windshield wiper systems that will not turn on, cease operation while in use, fall to turn off/on by themselves (moisture sensitive wiper system), or have continuous windshield washer pump operation because the presence of water within the wiper modules can either cause a short circuit or dan lead to the corresion of components within the module. Depending on the occurrence and weather situation, driver visibility could be reduced.

573.5(a)(6); in September of 2003 a Product Investigations Investigator was assigned to track alleged windshield wiper failures in 2002 and 2003 TrailBlazer, Envoy and Bravada vehicles after ODI resume PE03-042 was received from NHTSA.

The investigation revealed that during the early GMT 380 builds prior to the start of saleable vehicles at Morains assembly, the plant identified water ingestion in the windshield wiper module. GM Engineering determined the windshield wiper module cover was not seeing properly to the module housing due to voids in the butyl seal and cracks in the housing. There were also leaks in the connector due to a radius error. The windshield wiper module cover was rescaled to fix the radius of the connector. The original mating electrical connector was redesigned from a single-lip to a triple-lip seal. The graphed covers were caused by an interference with the circuit board terminals that were 1 mm too long. In addition, to avoid water being pulled into the module due to a negative pressure in the module, the windshield wiper module vent hole was added.

Engineering's test simulations showed that GM's required 100% online one-minute water test and the random eight minute off-line audit water test done at the Moraine assembly plant exceeded the pienum's capability to divert water away from the wiper covered circuit board. After the noted changes were made, water test failures at the plant were aliminated

In February 2002 the Moraine assembly plant observed a high number of windshield wiper motors being replaced. The wiper modules were inspected during the 100% warranty parts return process and evaluated by GM and the supplier (Valeo) to determine the root causes for this issue. By the end of February 2002, GM Engineering began a Red X study conducted to reduce warranty expense for Iront windshield wiper motors on the subject vehicles.



In November 2002 a new designed wiper module went into production for the GMT 360 Program that was initially pursued as a cost reduction project. In light of the Red X study findings, the new module was found to include a design feature that would also be directionally correct at reducing the potential for water intrusion.

On November 12, 2003 GM submitted a response to information request PE03-042 that was received by GM on September 29, 2003. In the response, GM indicated that the issue was still under investigation, and GM did not believe that the issue posed an unresechable risk to motor vehicle safety because there were only two reported minor presides and no injuries. On January 7, 2004 the NHTSA advised GM that PE03-042 would be upgraded to an EA.

On January 15, 2004 Product Investigations presented the leave to the PPE Director. The FPE Director reviewed the issue with the GMNA Senior Management Committee. GM continues to believe that there is no unreasonable risk to safety indicated with respect to this vehicle population. However, to acknowledge NHTSA's concern that windshield wipers are a safety system and to avoid prolonged confrontation over the issue, thereby promoting resolution of NHTSA's open investigation, on January 26, 2003 GM deckted to make owner letters containing statements required by 49 C.F.R. Part 577. The repairs will be made at no charge to the customer.

373.6(c)(8): This information will be included in the service procedure of the draft dealer bulletin.

Pursuant to 577.11(e), GM does not believe notification about reimbursement is required for this rocall. Involved vehicles are covered by the new vehicle warranty.

573.5(c)(B): Draft and final copies of the dealer bulletin and owner notification will be forwarded when available. General Motors plans to begin this safety recall in the third quarter of 2004.

Sincerely

say P. Kel Director

Product Investigations

2128 - 04005 Attachments

## VEHICLES POTENTIALLY AFFECTED BY MAKE, MODEL, AND MODEL YEAR PLIS INCLUSIVE DATES OF MANUFACTURE

MAKE	MODEL SERIES	MODEL YEAR	NUMBER INVOLVED	INCLUSI MANUFACTURI (FROM)	IVE ING DATES (TO)	DESCRIPTIVE INFO, TO PROPERLY IDENT, VEH,	EST. NO. W/CONDITION
Chevrolet Chevrolet	S/T S/T	2002 2003	277,126 101,366	10/00 4/02	8/02 11/02	TrailBlazer, TrailBlazer EXT	•
GMC GMC	s/T s/T	2002 2003	121,513 48,403	10/00 4/02	6/02 11/02	Envoy, Envoy XL. Envoy, Envoy XL.	ä =
Oldsmobile Oldsmobile	\$∕T 8∕T	2002 2003	28,709 3,788	10/00 4/02	6/02 11/02	Bravada Bravada	•
genistr.	8/T	2003	439	4/02	11/02	Agriencier	•
		Grand Total:	581,344				

2128/04005

<sup>\*</sup> All involved vehicles will be corrected.

	Par. (b)(1)	Par. (b)(2) Owner Notification				
CIPS#	NHTSA <u>Number</u>	Date <u>Began</u>	Date Completed			
SB04-04-S002	04V-061	7/15/2004	7/15/2004	Par. (b)(3) Total No. Vehicle Involved		438
				Par. (b)(4) Vehicles Inspected and Repaired Par. (b)(4) Veh. Inspec. Not Needing Repair		
				Par. (b)(5) Unreachable Vehicles	Exported	0
					Stolen	0
					Scrapped	0
					Pres. Owner Unknown	0
					Notification Undeliverable	0
					Unreachable	0