## **NISSAN**

#### NISSAN NORTH AMERICA, INC.

Corporate Office 18501 South Figueroa St. Gardena, California 90248-4500 Malling Address: P.O. Box 191 Gardena, California 90248-0191 Telephone: 310.532.3111

November 8, 2004

Mr. George Person
Chief, Recall Analysis Division
Office of Defects Investigation
Safety Assurance
National Highway Traffic Safety Administration
400 Seventh Street, S.W.
Washington, D.C. 20590

Ref: 04V-326

Dear Mr. Person:

The enclosed communication is being provided pursuant to 49 CFR Part 573.6(c)(9).

Technical Compliance Department

Encl.

Subject: 2004 Nissan Maxima SkyView Roof Panel Voluntary Safety Recall Campaign

Attention - Dealer Principals, Parts and Service Managers

\*\*\*\*\* Recall Campaign Bulletin \*\*\*\*\*

Recall Campaign Bulletin NTB04-100 has been revised to clarify the procedure to apply adhesive on the replacement glass. The revised bulletin (NTB04-100a) is immediately available via ASIST and also on NNAnet.com under My Documents in the Service/Campaign and Parts/Campaign folders. Please discard any copies of prior repair instructions related to this campaign.

\*\*\*\*\* Parts Availability \*\*\*\*\*

SkyView Roof Panels (P/N 79700-7Y005) continue to be available using the normal parts ordering process.

If you have any additional questions related to this campaign, please contact your Dealer Parts and Service Manager (DPSM).

Your continued support of the safety and customer satisfaction of Nissan Maxima owners is appreciated.

Nissan Parts and Service Operations 11/05/2004



# RECALL CAMPAIGN BULLETIN

Reference:

Date

NTB04-100a

November 5, 2004

## VOLUNTARY RECALL CAMPAIGN SKYVIEW ROOF GLASS

IMPORTANT: THIS BULLETIN HAS BEEN REVISED.

- Figure 10 (page 7) was revised to include a rubber seal on the glass.
  - Please use this bulletin (NTB04-100a) ONLY.
  - Discard all previous copies of NTB04-100.

CAMPAIGN I.D.# / NHTSA #: PU401 / 04V-326

**APPLIED VEHICLE:** 

2004 Maxima (A34)

**APPLIED VINS:** 

1N4BA41E\*4C800000 - 875558

NOTE: You MUST use Service Comm to confirm campaign eligibility.

#### INTRODUCTION

Nissan has determined that some 2004 model year Nissan Maxima vehicles may have a defect which relates to motor vehicle safety. There is a possibility that the tempered glass for the SkyView Roof may not have been cooled properly after the forming process, which could create excessive internal stress in the glass. This could eventually cause the glass to shatter into small pebble-like pieces and injure vehicle occupants. This issue does not affect Maxima vehicles equipped with the power glass sunroof. To prevent this condition from occurring, Nissan is conducting a Voluntary Safety Recall Campaign to inspect and replace, if required, the glass in the SkyView Roof.

## **IDENTIFICATION NUMBER**

Nissan has assigned identification number PU401 to this campaign. This number must appear on all communications and documentation of any nature dealing with this campaign.

## NUMBER OF VEHICLES POTENTIALLY AFFECTED

The number of vehicles potentially affected is approximately 32,100.

#### DEALER RESPONSIBILITY

It is the retailer's responsibility to check Service Comm for the campaign status on each vehicle falling within the range of this voluntary safety recall which for any reason enters the service department. This includes vehicles purchased from private parties or presented by transient (tourist) owners and vehicles in a dealer's inventory. Federal law requires that new vehicles in dealer inventory which are the subject of a safety recall must be corrected prior to sale. Failure to do so can result in civil penalties by the National Highway Traffic Safety Administration. While federal law applies only to new vehicles, Nissan strongly encourages dealers to correct any used vehicles in their inventory before they are retailed.

## SERVICE PROCEDURE

1. Confirm the Skyview Roof Glass needs to be replaced as follows:

## For Vehicles With A Production Date Of October 2003 Or Before:

Replace the Glass. Continue with step 2 of this procedure.

## For Vehicles With A Production Date Of November 2003 Or December 2003:

 Replace the Glass if the dots around the "CARLEX" name (located at the driver's side rear corner of the Glass) look like any one of the examples shown in Figure 1.
 In this case continue with step 2 of this procedure.




Figure 1

## **Remove Skyview Roof Glass**

CAUTION: Use suitable covers to protect upholstery, carpet, paint, etc. when performing this procedure.

- 2. Apply masking tape around the edges of the Skyview Roof Glass (see Figure 2).
  - This will help protect the body paint.
  - Use Scotch 3M Safe-Release Painters' Masking Tape #2090 (or equivalent).




Figure 2

3. Using a suitable windshield removal tool, <u>carefully</u> cut the adhesive around the Skyview Roof Glass (see Figure 3).

**CAUTION:** Be careful, don't scratch painted areas, and don't get the original adhesive on the headliner.

**NOTE**: The windshield removal tool shown below is available from Snap-On (#YA109A) and MAC (#PK160A).




Figure 3

IMPORTANT: Before removing the Glass, take note of the Nissan logo position on the glass. The new glass must be reinstalled with the logo in the same position (see Figure 4). Write "Logo" on the masking tape at the driver's side rear corner to help you remember the logo location.

4. Remove the Skyview Roof Glass.

# CAUTION: Use suitable eye and hand protection when performing the below procedure.

- 5. Destroy the original Glass as follows:
  - a. Put the **original** Glass into the box that the new Glass came in.
  - b. Completely tape up all seams on the box.
  - c. Hit the face of the box with a hammer until the Glass shatters.
  - d. Discard the box.





Figure 4

6. Use a Plastic Pry Tool (J-46534 or equivelant) to remove the Plastic Glass Clips from the vehicle body (see Figure 5).

## NOTE:


- The original Glass may have 4 or 8 Clips depending on when it was produced.
- The new replacement Glass only has 4 Clips.



7. Trim the original adhesive to be <u>nearly</u> flush with the vehicle body (see Figure 6).

## **CAUTION:**

- Do not scratch the paint.
- Leave a thin layer of old adhesive on the vehicle body to allow a good bonding surface for the new adhesive.



- 8. Clean the sealing areas on the body with isopropyl alcohol. Allow to dry.
- 9. Apply touch-up paint (if necessary) to areas that may have been scratched. Allow to dry.

10. Remove the four Rubber Spacers from the new Skyview Roof Glass (see Figure 7).




Figure 7

## NOTE:

- The Material Safety Data Sheets (MSDS) for the (Dow Automotive) Essex Adhesive and Primers listed below can be obtained from the Dow Automotive web site (http://www.dowautomotiveaftermarket.com).
- Be sure to read the MSDS and follow the manufactures directions when using these products.

## Apply Urethane Primer #U-401 ("Glass/Frit Prep #1)

- 11. Apply Urethane Primer to the new Skyview Roof Glass (see Figure 8).
  - Clean the entire Glass with Isopropyl Alcohol. Let it dry.
  - Use Essex Urethane Primer #U-401 ("Glass/Frit Prep #1") or equivalent. Follow the instructions supplied with the Primer.
  - Apply Primer to the black strip area around the edge of the glass (see Figure 8).
  - Allow the Primer to dry for 1 to 2 minutes.
  - Do NOT touch the Primer even after it dries.




Figure 8

## Apply Urethane Primer #U-402 ("Glass/Frit Primer #2") after the U-401 Primer Is dry

- 12. Apply this second Urethane Primer to the <u>new</u> Skyview Roof Glass (over the U-401 Primer). See Figure 9.
  - Use Essex Urethane Primer #U-402 ("Glass/Frit Primer #2") or equivalent.
     Follow the instructions supplied with the Primer.
  - Apply Primer around the Glass on top of the U-401 that you just applied (see Figure 9).
  - Allow the Primer to dry for about 6 minutes.
  - Do NOT touch the Primer even after it dries.




Figure 9

## Apply Urethane Adhesive #U-400HV ("Rapid Cure Auto Glass Urethane Adhesive")

- 13. Apply a bead of Urethane Adhesive to the <u>new Skyview Roof Glass over the Primer</u> coats (see Figure 10).
  - Use Essex Betaseal Urethane Adhesive #U-400HV ("Rapid Cure Auto Glass Urethane Adhesive") or equivalent. Follow the instructions supplied with the Adhesive.
  - Adhesive bead size should be 12 mm high and 7 mm wide.
  - Apply Adhesive around the Glass, on top of the U-402 that you just applied, so the adhesive bead runs along the inside edge of the rubber seal (see Figure 10).
  - Go past the start point to ensure overlap before ending the bead.
  - The Adhesive starts to set up quickly. You'll have to install the glass right away.
  - Do NOT touch the Adhesive.





Figure 10

## Install New Skyview Roof Glass

#### IMPORTANT:

- Make sure the "NISSAN" logo is positioned towards the driver's side rear of the vehicle, as shown in Figure 11.
- Do NOT touch the Adhesive while handling the Glass.
- 14. Install the new glass immediately after you apply the adhesive.
  - The directions supplied with your Urethane Adhesive will give you a recommended maximum allowable time between adhesive application and glass installation.
  - The "NISSAN" logo on the glass goes towards the driver's side rear of the vehicle (see Figure 11).
  - Make sure you line up the Clips on the Glass with the holes in the vehicle body. The Clips must "snap" into place.



- 15. Firmly press the glass down around the entire edge. Make sure the Clips "snap" into place.
- 16. Allow the Urethane Adhesive to cure.
  - Curing times will vary depending on temperature and humidity.
  - Follow directions supplied with the Urethane Adhesive for curing times.

## PARTS INFORMATION

DESCRIPTION	PART#	QUANTITY
Skyview Roof Glass	79700-7Y005	1

## Adhesive and Primers Required For Glass Installation:

## **NOTES:**

- The Essex products listed below are NOT available through the Direct Ship Chemical Care Products Program and are not available through the PDCs.
- Please obtain these products from a local supply source.
- To find out the local supply source nearest you, call 800-453-3779 between Monday through Thursday 8:00 AM to 5:00 PM Eastern time, and Friday 8:00 AM to 2:00 PM Eastern time.
- Do NOT include these products on the warranty claim, as they are considered shop supplies.

Essex Urethane Primer ("Glass/Frit Prep #1")	U-401	As needed
Essex Urethane Primer ("Glass/Frit Primer #2")	U-402	
Essex Betaseal Urethane Adhesive ("Rapid Cure Auto Glass Urethane Adhesive")	U-400HV	

## **CLAIMS INFORMATION**

# Submit a Campaign ("CM") line claim using the following claims coding information:

Campaign I.D.: PU401

DESCRIPTION	PFP	OP CODE	FRT
Inspect Skyview Roof Glass ONLY	PU401	PU4010	0.2 hr
Inspect and Replace Skyview Roof Glass	PU401	PU4011	1.9 hr

### **OWNER'S LETTER**

## Dear Nissan owner:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. Nissan has decided that a defect that relates to motor vehicle safety exists in some 2004 model year Nissan Maxima vehicles, equipped with the SkyView Roof.

## Reason for Recall

The tempered glass for the SkyView Roof may not have been cooled properly after the forming process, which could create excessive internal stress in the glass. This could eventually cause the glass to shatter into small pebble-like pieces and injure vehicle occupants. This issue does not affect Maxima vehicles equipped with the power glass sunroof.

## What Nissan Will Do

The glass in the SkyView Roof will be inspected and replaced if required.

#### What You Should Do

Contact your Nissan dealer at your earliest convenience in order to arrange an appointment to have your vehicle repaired. Please bring this notice with you when you keep your service appointment. Instructions have been sent to your Nissan dealer.

Until your vehicle is repaired, you may wish to keep the shade for the SkyView roof closed. If the glass should break, this will help reduce the chance that broken glass will unexpectedly fall inside the occupant compartment.

If the dealer fails, or is unable to make the necessary repairs free of charge, you may contact the National Consumer Affairs Office, Nissan North America, Inc. at P.O. Box 191, Gardena, California 90248-0191. The toll free number is 1-800-NISSAN1 (1-800-647-7261). You may also contact the Administrator of the National Highway Traffic Safety Administration, 400 Seventh Street SW, Washington, D.C. 20590 or call the toll free Safety Hotline at (888) 327-4236.

If you have paid to have a SkyView Roof replaced prior to this campaign, you may be eligible for reimbursement of the related expense. Contact Nissan Consumer Affairs at the number listed above for additional information on how to obtain a reimbursement.

Federal regulations require that any vehicle lesser receiving this recall notice must forward a copy of this notice to the lessee within ten days.

Thank you for your cooperation. We are indeed sorry for any inconvenience this may cause you.