



AFFECTED VEHICLES

MODELS: 2004 Endeavor,
2003-04 Outlander

04V-197

Date: January 2006

RE: FOLLOW-UP NOTIFICATION: SAFETY RECALL SR-04-004

Dear Mitsubishi Owner,

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. This is a follow-up to an earlier communication sent out to affected vehicle owners in May 2004.

Reason For Notice: Mitsubishi Motors North America, Inc. has decided that a defect which relates to motor vehicle safety exists in the Mitsubishi Genuine Accessory trailer hitch wiring harness (part number ACU03YHX02 or AEN04YHX02) that may have been installed by or purchased from your dealer. If the electrical current draw from the trailer lamp circuit becomes too high, the wiring harness may overheat and possibly result in a fire.

What you should do: If you have this trailer hitch wiring harness on your vehicle or you purchased a harness from a Mitsubishi dealer prior to July 2, 2004, you should contact your Authorized Mitsubishi Motors Dealer to schedule a repair date. If you are unsure if you have the affected harness installed on your vehicle, please contact your Mitsubishi dealer for assistance.

What your dealer will do: The dealer will remove the subject trailer hitch wiring harness and replace it with a new one, free of charge.

How long will it take? The time needed for the actual repair is approximately 30 minutes. The dealer may need your vehicle for a longer period of time due to service scheduling issues, but every effort will be made to minimize your inconvenience.

If you have any trouble having your vehicle repaired promptly and at no charge, please inform us by calling:

Mitsubishi Customer Relations Department **888-MITSU-2006 (888-648-7820)**

Hours: Monday – Saturday 7 a.m. to 5 p.m. (Pacific Standard Time)

If after contacting Mitsubishi Customer Relations, you still have a problem having this repair made promptly and without charge, write to the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street SW, Washington, D.C. 20590, or call the Vehicle Safety Hotline toll-free (1-888-327-4236); (TTY: 1-800-424-9153); or go to: <http://www.safercar.gov>.

If you have already encountered a problem regarding the above and have paid for the repair, you may send your original receipts and/or other adequate proof of payment to the following address for reimbursement:

Mitsubishi Customer Relations Department, P.O. Box 6400, Cypress, CA 90630-0064

Notice to Lessors: If you are a lessor of five or more leased vehicles as of the date of this letter, you have an obligation under federal law, (49 CFR Part 577), to provide the lessee of the above referenced vehicle with a copy of this letter by first class mail within ten days of receipt. Further, you must maintain a record, which identifies the lessee to whom you sent a copy of this letter, the date you sent it, and the vehicle identification number (VIN) of the subject vehicle.

We appreciate your prompt attention to this matter. If you have any questions, please contact your Mitsubishi Motors Dealer.

Sincerely,

Mitsubishi Motors North America, Inc.