

EXHIBIT "A"

[General Coach Letterhead]

SAFETY CAMPAIGN NOTICE

****SECOND NOTICE****

NHTSA Recall Number 04V-275
Driver's Seat Tether Strap Recall Campaign

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. This notice is a follow-up notice to an earlier communication sent to you in June 2004 by General Coach America, Inc. ("General Coach") regarding the driver's seat tether strap recall campaign referenced above.

Our records indicate that General Coach did not receive a response from you to the initial notice sent in connection with this recall campaign, **and in some cases, this is the third attempt to get this recall notice resolved.** General Coach urges you to follow the procedures set forth in this follow-up notice. By doing so, you will assist General Coach in its efforts to ensure that all of the buses subject to this recall campaign are repaired.

General Coach has decided that during the manufacturing process, the driver's seat tether straps were not installed on certain M1030, M1030L, M1035, and M1035L model buses built in 2002, 2003, and 2004. The absence of the driver's seat tether strap may result in the failure to properly secure the driver's seat in the event of a crash, which could in turn result in injury or death to the driver. This tether strap must be installed to meet the FMVSS-210 standards.

It has been determined that the vehicle(s) listed above did not have the required tether straps installed to the driver's seat. The straps must be installed as soon as possible to prevent injuries in the case of an accident. Attached is the Service Information Document #SID 2004_013 that describes the steps to add the tether straps. If you do not have the facilities to perform this repair at your location, an authorized General Coach service center will perform those repairs for you free of charge and will take approximately 0.75 hours to repair. If you need information on the nearest General Coach service center, please call the General Coach Service Center at (810) 724-6474 or toll free at (800) 842-0622.

If you experience difficulties with this procedure or are otherwise unable to comply with this notice, you may contact the Service Department at General Coach, (800) 842-0622. If General Coach is unable to provide assistance for you, you may contact the Administrator of NHTSA, 400 Seventh Street, SW, Washington, D.C. 20590 or toll free through the Vehicle Safety Hotline at 1-888-327-4236; or through NHTSA's teletypewriter number (TTY: 1-800-424-9153); or at its website <http://www.safercar.gov>.

You may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this recall. For more information contact General Coach at 1-800-842-0622.

Federal Regulations require any lessor receiving this letter to forward it on to the lessee within 10 days.

We apologize for any inconvenience this campaign may cause you. As always our first priority is the safety of the people using our products.

Sincerely,

Dick Cutcher
Service Manger
General Coach America, Inc.

G:\Thor\Gen Coach\Tether Strap Recall\Safety Campaign Notice-final-04V-275.doc
DAB-dja

EXHIBIT "B"

****SECOND NOTICE****

**GENERAL COACH AMERICA, INC.
DRIVER'S SEAT TETHER STRAP RECALL**

04V-275

Please complete the following information and mail this card immediately if your bus has been sold. If the bus is still in your possession, please return this card after the tether strap has been installed on your bus.

VIN Number _____

_____ The installation of the tether strap has been completed by:
Dealer/Service Center: _____
Date: _____

_____ I have sold the bus to:
Name: _____
Address: _____
City: _____