



Frank M. Ligon
Ford Motor Company
P.O. Box 1904
Dearborn, Michigan 48121



F0055468

0159



R. FILE

September 2005

330 TOWN CENTER DR STE 500
DEARBORN, MI 48126-2796

1995 F-150 Ford Truck

Vehicle ID #:

05S28

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Ford Motor Company has decided that a defect which relates to motor vehicle safety exists in certain 1994-1996 model year Bronco, 1994-2002 F-150/250 (Under 8500 GVW), 1997-2002 Expedition, 1998-2002 Navigator, and 2002 Blackwood vehicles equipped with speed control. We apologize for this situation and want to assure you that, with your assistance, we will correct this condition. Our commitment, together with Ford and Lincoln Mercury dealers, is to provide you with the highest level of service and support.

What is the issue?

On your vehicle, the underhood speed control deactivation switch may overheat, smoke, or burn, which could result in an underhood fire. This condition may occur either when the vehicle is parked or when it is being operated, even if the speed control is not in use.

What will Ford and your dealer do?

Parts to repair your vehicle will not be available until November 2005, and as a result, we are implementing a two-stage repair process. Until parts are available for the permanent repair, you should contact your dealer to make an appointment to disconnect the speed control deactivation switch, which is located under the hood of your vehicle. This procedure will temporarily disconnect the speed control system, which will prevent a speed control deactivation switch related fire. The speed control system will then be inoperative until the permanent repair is performed. We recognize this may be an inconvenience, but we believe this preventive action is in the best interest of our customers' safety.

When parts become available for the permanent repair in November 2005, you will be notified to contact your dealer to schedule an appointment to have a fused wiring harness installed and to reconnect the speed control system on your vehicle.


Ford Motor Company and your dealer will perform the above modification free of charge (parts and labor).

How long will it take?

Please call your dealer for an estimate of how much time will be required to perform this repair. Your dealer may be able to perform this repair while you wait; however, due to scheduling requirements, your dealer may need your vehicle for a longer period of time.

What are we asking you to do?

Please call your dealer without delay and request a service date to have the switch disconnected (Recall 05S28). Provide the dealer with the Vehicle Identification Number (VIN) of your vehicle. The VIN is printed near your name at the beginning of this letter.



Until you have the recall service performed, park your vehicle away from structures to prevent a potential underhood fire from spreading.

If you do not already have a servicing dealer, you can access <http://www.genuineservice.com> for dealer addresses, maps, and driving instructions.

Please note: Federal law requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

Have you previously paid for this repair?

If you paid to remedy the issue addressed in this notice, you may be eligible for a refund either through your dealer or directly from Ford Motor Company.

To verify eligibility and expedite reimbursement, give your paid original receipt to your dealer. Refund requests, including all required documentation, may also be mailed to Ford at P.O. Box 6251, Dearborn, Michigan 48121-6251. Refund requests mailed to Ford may take up to 60 days to process.

Detailed information regarding eligibility for Ford's reimbursement program and documentation requirements may be obtained by contacting the Ford Customer Relationship Center at 1-888-222-2751.

Owners who have previously paid for this repair are still eligible to have the recall described in this letter performed.

Have you changed your address or sold the vehicle?

If you have, please fill out the enclosed prepaid postcard and mail it to us so we can update our records. If you have sold the vehicle, the information you provide on the postcard will be used to notify the new owner about this recall.

Can we assist you further?

If you have difficulty getting your vehicle repaired promptly and without charge, please contact your dealership's Service Manager for assistance.

If you still have concerns, please contact our Customer Relationship Center and one of our representatives will be happy to assist you.

Call 1-888-222-2751.

For the hearing impaired call 1-800-232-5952 (TDD).

Office Hours: (Eastern Time Zone)


Monday – Friday: 8AM – 5PM

If you wish to contact us through the Internet, our address is: www.ownerconnection.com

If you are still having difficulty getting your vehicle repaired in a reasonable time or without charge, you may write the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street S. W., Washington, D. C. 20590 or call the toll free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153) or go to <http://www.safercar.gov>.

Thank you for your attention to this important matter.

Sincerely,



Frank M. Ligon
Director
Service Engineering Operations